Hydro Québec

# Heat pumps eligible for efficient heat pump measure in the LogisVert Efficient Homes Program

Start date: June 19, 2023

| | Efficient heat pumps | **Top-performing** efficient heat pumps |
|---|---|---|
| **Financial assistance** per 1000 BTU/h at -8°C | $50 | **SPECIAL OFFER! $120** |

Please Note that some models may Not be available in Québec. To find a model, you can use CTRL+F

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 212394313 | 1HVAC | ACIQ-30-HPB | ACIQ-30-ACL | | 22,600 | $2,712 |
| Yes | 210857353 | 1HVAC | ACIQ-60HPB | ACIQ-60AHB | | 42,000 | $5,040 |
| Yes | 210857354 | 1HVAC | ACIQ-18ZPL-HP230B | ACIQ-18AHB-HH-M | | 15,400 | $1,848 |
| Yes | 210857355 | 1HVAC | ACIQ-24ZPL-HP230B | ACIQ-24AHB-HH-M | | 16,900 | $2,028 |
| Yes | 208106640 | 1HVAC | ACIQ-48-HPB | ACIQ-48-AHB | | 36,000 | $4,320 |
| Yes | 208106638 | 1HVAC | ACIQ-24-HPB | ACIQ-24-AHB | | 19,200 | $2,304 |
| Yes | 210857310 | 1HVAC | ACIQ-18ZPL-HP230B | SCC-1218-HH-M | | 14,500 | $1,740 |
| Yes | 207825570 | 1HVAC | ACIQ-36Z-HH-M4B | Heat pump without ducts | | 33,000 | $3,960 |
| Yes | 210857363 | 1HVAC | ACIQ-55Z-HH-M5B | Heat pump with ducts | | 35,200 | $4,224 |
| Yes | 210857362 | 1HVAC | ACIQ-55Z-HH-M5B | Heat pump without ducts | | 34,400 | $4,128 |
| Yes | 207825564 | 1HVAC | ACIQ-18Z-HH-M2B | Heat pump without ducts | | 15,000 | $1,800 |
| Yes | 207825574 | 1HVAC | ACIQ-48Z-HH-M5B | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 207825573 | 1HVAC | ACIQ-48Z-HH-M5B | Heat pump without ducts | | 36,000 | $4,320 |
| Yes | 207825568 | 1HVAC | ACIQ-27Z-HH-M3B | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 207825567 | 1HVAC | ACIQ-27Z-HH-M3B | Heat pump without ducts | | 26,600 | $3,192 |
| Yes | 207825565 | 1HVAC | ACIQ-18Z-HH-M2B | Heat pump with ducts | | 16,000 | $1,920 |
| Yes | 210857306 | 1HVAC | ACIQ-60ZPL-HP230B | ACIQ-60FM-HH-MB | | 40,000 | $4,800 |
| Yes | 210857302 | 1HVAC | ACIQ-48ZPL-HP230B | ACIQ-48CD-HH-MB | | 39,500 | $4,740 |
| Yes | 210857300 | 1HVAC | ACIQ-48ZPL-HP230B | ACIQ-48CC-HH-MB | | 35,000 | $4,200 |
| Yes | 210857305 | 1HVAC | ACIQ-48ZPL-HP230B | ACIQ-48FM-HH-MB | | 35,000 | $4,200 |
| Yes | 210857299 | 1HVAC | ACIQ-36ZPL-HP230B | ACIQ-36CC-HH-MB | | 33,000 | $3,960 |
| Yes | 210857304 | 1HVAC | ACIQ-36ZPL-HP230B | ACIQ-36FM-HH-MB | | 32,000 | $3,840 |
| Yes | 207825522 | 1HVAC | ACIQ-24ZPL-HP230B | ACIQ-24CD-HH-MB | | 21,000 | $2,520 |
| Yes | 207825525 | 1HVAC | ACIQ-24ZPL-HP230B | ACIQ-24FM-HH-MB | | 19,000 | $2,280 |
| Yes | 207825521 | 1HVAC | ACIQ-18ZPL-HP230B | ACIQ-18CD-HH-MB | | 15,000 | $1,800 |
| Yes | 207825515 | 1HVAC | ACIQ-24ZPL-HP230B | ACIQ-24W-HH-MB | | 21,200 | $2,544 |
| Yes | 210857298 | 1HVAC | ACIQ-24ZPL-HP230B | ACIQ-24W-HH-MC | | 21,200 | $2,544 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 210857297 | 1HVAC | ACIQ-18ZPL-HP230B | ACIQ-18W-HH-MC | | 15,000 | $1,800 |
| Yes | 207825514 | 1HVAC | ACIQ-18ZPL-HP230B | ACIQ-18W-HH-MB | | 15,000 | $1,800 |
| Yes | 210857303 | 1HVAC | ACIQ-60ZPL-HP230B | ACIQ-60CD-HH-MB | | 40,000 | $4,800 |
| Yes | 207825571 | 1HVAC | ACIQ-36Z-HH-M4B | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 206315646 | 1HVAC | ACIQ-24-HP | ACIQ-24-AH | | 16,500 | $1,980 |
| Yes | 206315658 | 1HVAC | ACIQ-27Z-HH-M3 | Heat pump without ducts | | 18,000 | $2,160 |
| Yes | 207825575 | 1HVAC | ACIQ-48Z-HH-M5B | Combination heat pumps with or without ducts | | 29,000 | $3,480 |
| Yes | 207825572 | 1HVAC | ACIQ-36Z-HH-M4B | Combination heat pumps with or without ducts | | 23,000 | $2,760 |
| Yes | 206315660 | 1HVAC | ACIQ-48Z-HH-M5 | Heat pump without ducts | | 30,000 | $3,600 |
| Yes | 207827156 | AC PRO.COM | AOX430-17HFN1-MT0W | ATIU-18HWFN1-M | | 15,000 | $1,800 |
| Yes | 202132789 | ACD | UHD24KCH22S-O | UHD24KCH22S-I | | 15,500 | $1,860 |
| Yes | 202110485 | ACD | UHD18KCH25S-O | UHD18KCH25S-I | | 14,200 | $1,704 |
| Yes | 207497902 | ACD | FXD-ACD36 | AH236 | | 24,000 | $2,880 |
| Yes | 207497904 | ACD | FXD-ACD60 | AH260 | | 36,000 | $4,320 |
| Yes | 207497903 | ACD | FXD-ACD60 | AH248 | | 32,000 | $3,840 |
| Yes | 207497901 | ACD | FXD-ACD36 | AH224 | | 16,300 | $1,956 |
| Yes | 206428584 | ACD | MUD18KCH23S-O | Heat pump without ducts | | 17,000 | $2,040 |
| Yes | 206428585 | ACD | MUD24KCH23S-O | Heat pump without ducts | | 17,900 | $2,148 |
| Yes | 201863353 | ACD | OCD24KCH20S-O | OCD24KCH20S-I | | 14,600 | $1,752 |
| Yes | 201863352 | ACD | OCD18KCH20S-O | OCD18KCH20S-I | | 12,400 | $1,488 |
| Yes | 212394324 | ACIQ | ACIQ-30-HPB | ACIQ-30-ACL | | 22,600 | $2,712 |
| Yes | 210857356 | ACIQ | ACIQ-60HPB | ACIQ-60AHB | | 42,000 | $5,040 |
| Yes | 210857357 | ACIQ | ACIQ-18ZPL-HP230B | ACIQ-18AHB-HH-M | | 15,400 | $1,848 |
| Yes | 210857358 | ACIQ | ACIQ-24ZPL-HP230B | ACIQ-24AHB-HH-M | | 16,900 | $2,028 |
| Yes | 208106637 | ACIQ | ACIQ-48-HPB | ACIQ-48-AHB | | 36,000 | $4,320 |
| Yes | 208106635 | ACIQ | ACIQ-24-HPB | ACIQ-24-AHB | | 19,200 | $2,304 |
| Yes | 210857330 | ACIQ | ACIQ-18ZPL-HP230B | SCC-1218-HH-M | | 14,500 | $1,740 |
| Yes | 207825582 | ACIQ | ACIQ-36Z-HH-M4B | Heat pump without ducts | | 33,000 | $3,960 |
| Yes | 210857381 | ACIQ | ACIQ-55Z-HH-M5B | Heat pump with ducts | | 35,200 | $4,224 |
| Yes | 210857380 | ACIQ | ACIQ-55Z-HH-M5B | Heat pump without ducts | | 34,400 | $4,128 |
| Yes | 207825576 | ACIQ | ACIQ-18Z-HH-M2B | Heat pump without ducts | | 15,000 | $1,800 |
| Yes | 207825586 | ACIQ | ACIQ-48Z-HH-M5B | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 207825585 | ACIQ | ACIQ-48Z-HH-M5B | Heat pump without ducts | | 36,000 | $4,320 |
| Yes | 207825580 | ACIQ | ACIQ-27Z-HH-M3B | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 207825579 | ACIQ | ACIQ-27Z-HH-M3B | Heat pump without ducts | | 26,600 | $3,192 |
| Yes | 207825577 | ACIQ | ACIQ-18Z-HH-M2B | Heat pump with ducts | | 16,000 | $1,920 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 210857323 | ACIQ | ACIQ-60ZPL-HP230B | ACIQ-60CD-HH-MB | | 40,000 | $4,800 |
| Yes | 210857326 | ACIQ | ACIQ-60ZPL-HP230B | ACIQ-60FM-HH-MB | | 40,000 | $4,800 |
| Yes | 210857322 | ACIQ | ACIQ-48ZPL-HP230B | ACIQ-48CD-HH-MB | | 39,500 | $4,740 |
| Yes | 210857320 | ACIQ | ACIQ-48ZPL-HP230B | ACIQ-48CC-HH-MB | | 35,000 | $4,200 |
| Yes | 210857325 | ACIQ | ACIQ-48ZPL-HP230B | ACIQ-48FM-HH-MB | | 35,000 | $4,200 |
| Yes | 210857319 | ACIQ | ACIQ-36ZPL-HP230B | ACIQ-36CC-HH-MB | | 33,000 | $3,960 |
| Yes | 210857324 | ACIQ | ACIQ-36ZPL-HP230B | ACIQ-36FM-HH-MB | | 32,000 | $3,840 |
| Yes | 207825541 | ACIQ | ACIQ-24ZPL-HP230B | ACIQ-24CD-HH-MB | | 21,000 | $2,520 |
| Yes | 207825544 | ACIQ | ACIQ-24ZPL-HP230B | ACIQ-24FM-HH-MB | | 19,000 | $2,280 |
| Yes | 207825540 | ACIQ | ACIQ-18ZPL-HP230B | ACIQ-18CD-HH-MB | | 15,000 | $1,800 |
| Yes | 207825534 | ACIQ | ACIQ-24ZPL-HP230B | ACIQ-24W-HH-MB | | 21,200 | $2,544 |
| Yes | 210857318 | ACIQ | ACIQ-24ZPL-HP230B | ACIQ-24W-HH-MC | | 21,200 | $2,544 |
| Yes | 210857317 | ACIQ | ACIQ-18ZPL-HP230B | ACIQ-18W-HH-MC | | 15,000 | $1,800 |
| Yes | 207825533 | ACIQ | ACIQ-18ZPL-HP230B | ACIQ-18W-HH-MB | | 15,000 | $1,800 |
| Yes | 207825583 | ACIQ | ACIQ-36Z-HH-M4B | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 206315637 | ACIQ | ACIQ-24-HP | ACIQ-24-AH | | 16,500 | $1,980 |
| Yes | 206315654 | ACIQ | ACIQ-27Z-HH-M3 | Heat pump without ducts | | 18,000 | $2,160 |
| Yes | 207825587 | ACIQ | ACIQ-48Z-HH-M5B | Combination heat pumps with or without ducts | | 29,000 | $3,480 |
| Yes | 207825584 | ACIQ | ACIQ-36Z-HH-M4B | Combination heat pumps with or without ducts | | 23,000 | $2,760 |
| Yes | 206315656 | ACIQ | ACIQ-48Z-HH-M5 | Heat pump without ducts | | 30,000 | $3,600 |
| Yes | 212406532 | ADP | 4TXD2060A10NU** | H,TE88948+TD | | 30,200 | $3,624 |
| Yes | 212406531 | ADP | 4TXD2060A10NU** | H,TE86948+TD | | 30,200 | $3,624 |
| Yes | 212406530 | ADP | 4TXD2060A10NU** | H,TG52948+TD | | 30,200 | $3,624 |
| Yes | 212406529 | ADP | 4TXD2036A10NU** | H,TG34930+TD | | 15,800 | $1,896 |
| Yes | 212406528 | ADP | 4TXD2060A10NU** | H,TE88948+TD | | 30,200 | $3,624 |
| Yes | 212406527 | ADP | 4TXD2060A10NU** | H,TE86948+TD | | 30,200 | $3,624 |
| Yes | 212406526 | ADP | 4TXD2060A10NU** | H,TG52948+TD | | 30,200 | $3,624 |
| Yes | 212406525 | ADP | 4TXD2036A10NU** | H,TG34930+TD | | 15,800 | $1,896 |
| Yes | 212396770 | ADP | 4TXD2060A10NU** | H,TE88960+TD | | 35,200 | $4,224 |
| Yes | 212396769 | ADP | 4TXD2060A10NU** | H,TE86960+TD | | 35,200 | $4,224 |
| Yes | 212396768 | ADP | 4TXD2060A10NU** | H,TG52960+TD | | 35,200 | $4,224 |
| Yes | 212396767 | ADP | 4TXD2036A10NU** | H,TG34936+TD | | 22,000 | $2,640 |
| Yes | 212396766 | ADP | 4TXD2060A10NU** | H,TE88960+TD | | 35,200 | $4,224 |
| Yes | 212396765 | ADP | 4TXD2060A10NU** | H,TE86960+TD | | 35,200 | $4,224 |
| Yes | 212396764 | ADP | 4TXD2060A10NU** | H,TG52960+TD | | 35,200 | $4,224 |
| Yes | 212396763 | ADP | 4TXD2036A10NU** | H,TG34936+TD | | 22,000 | $2,640 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 212396762 | ADP | 4TXD2060A10NU** | BV**C9960 | | 30,200 | $3,624 |
| Yes | 212396761 | ADP | 4TXD2060A10NU** | BV**C9(1,2)60+TXV | | 30,200 | $3,624 |
| Yes | 212396760 | ADP | 4TXD2060A10NU** | BV**C9960 | | 30,200 | $3,624 |
| Yes | 212396759 | ADP | 4TXD2060A10NU** | BV**C9(1,2)60+TXV | | 30,200 | $3,624 |
| Yes | 212396575 | ADP | 4TXD2060A10NU** | F,PE*CC4960 | | 31,800 | $3,816 |
| Yes | 212396574 | ADP | 4TXD2060A10NU** | F,PE*CC9960 | | 36,400 | $4,368 |
| Yes | 212396573 | ADP | 4TXD2060A10NU** | F,PE*CC7948 | | 31,800 | $3,816 |
| Yes | 212396572 | ADP | 4TXD2060A10NU** | F,PE*UU1960 | | 36,400 | $4,368 |
| Yes | 212396571 | ADP | 4TXD2060A10NU** | F,PE*CC7960 | | 36,400 | $4,368 |
| Yes | 212396559 | ADP | 4TXD2060A10NU** | F,PE*CC4960 | | 31,800 | $3,816 |
| Yes | 212396558 | ADP | 4TXD2060A10NU** | F,PE*CC9960 | | 36,400 | $4,368 |
| Yes | 212396557 | ADP | 4TXD2060A10NU** | F,PE*CC7948 | | 31,800 | $3,816 |
| Yes | 212396556 | ADP | 4TXD2060A10NU** | F,PE*UU1960 | | 36,400 | $4,368 |
| Yes | 212396555 | ADP | 4TXD2060A10NU** | F,PE*CC7960 | | 36,400 | $4,368 |
| Yes | 212396570 | ADP | 4TXD2036A10NU** | F,PE*G34925 | | 15,000 | $1,800 |
| Yes | 212396569 | ADP | 4TXD2036A10NU** | F,PE*G34930 | | 15,000 | $1,800 |
| Yes | 212396568 | ADP | 4TXD2036A10NU** | F,PE*G34936 | | 24,200 | $2,904 |
| Yes | 212396567 | ADP | 4TXD2036A10NU** | F,PE*G33925 | | 15,000 | $1,800 |
| Yes | 212396566 | ADP | 4TXD2036A10NU** | F,PE*G33930 | | 15,000 | $1,800 |
| Yes | 212396565 | ADP | 4TXD2036A10NU** | F,PE*G33936 | | 24,200 | $2,904 |
| Yes | 212396564 | ADP | 4TXD2036A10NU** | F,PE*E32924 | | 15,000 | $1,800 |
| Yes | 212396563 | ADP | 4TXD2036A10NU** | F,PE*E32925 | | 15,000 | $1,800 |
| Yes | 212396562 | ADP | 4TXD2036A10NU** | F,PE*E32930 | | 15,000 | $1,800 |
| Yes | 212396561 | ADP | 4TXD2036A10NU** | F,PE*E32936 | | 24,200 | $2,904 |
| Yes | 212396560 | ADP | 4TXD2036A10NU** | F,PE*BB8937 | | 24,000 | $2,880 |
| Yes | 212396554 | ADP | 4TXD2036A10NU** | F,PE*G34925 | | 15,000 | $1,800 |
| Yes | 212396553 | ADP | 4TXD2036A10NU** | F,PE*G34930 | | 15,000 | $1,800 |
| Yes | 212396552 | ADP | 4TXD2036A10NU** | F,PE*G34936 | | 24,200 | $2,904 |
| Yes | 212396551 | ADP | 4TXD2036A10NU** | F,PE*G33925 | | 15,000 | $1,800 |
| Yes | 212396550 | ADP | 4TXD2036A10NU** | F,PE*G33930 | | 15,000 | $1,800 |
| Yes | 212396549 | ADP | 4TXD2036A10NU** | F,PE*G33936 | | 24,200 | $2,904 |
| Yes | 212396548 | ADP | 4TXD2036A10NU** | F,PE*E32924 | | 15,000 | $1,800 |
| Yes | 212396547 | ADP | 4TXD2036A10NU** | F,PE*E32925 | | 15,000 | $1,800 |
| Yes | 212396546 | ADP | 4TXD2036A10NU** | F,PE*E32930 | | 15,000 | $1,800 |
| Yes | 212396545 | ADP | 4TXD2036A10NU** | F,PE*E32936 | | 24,200 | $2,904 |
| Yes | 212396544 | ADP | 4TXD2036A10NU** | F,PE*BB8937 | | 24,000 | $2,880 |
| Yes | 211912012 | ADP | 38MURAQ24AB3* | CDP23H13P+TXV | 59SC2D080E17**16 | 18,400 | $2,208 |
| Yes | 211912009 | ADP | 38MURAQ24AB3* | CDP35H15P+TXV | 59SC2D080E17**16 | 18,400 | $2,208 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 211912005 | ADP | 38MURAQ24AB3* | CDP29H15P+TXV | 59SC2D080E17**16 | 18,400 | $2,208 |
| Yes | 211912000 | ADP | 38MURAQ24AB3* | CDP29H15P+TXV | 59SC2D060E17**14 | 18,400 | $2,208 |
| Yes | 211902846 | ADP | 38MURAQ24AB3* | CDP23A13P+TXV | 59SC2D080E17**16 | 18,400 | $2,208 |
| Yes | 211902845 | ADP | 38MURAQ24AB3* | CDP35A15P+TXV | 59SC2D080E17**16 | 18,400 | $2,208 |
| Yes | 211902844 | ADP | 38MURAQ24AB3* | CDP29A15P+TXV | 59SC2D080E17**16 | 18,400 | $2,208 |
| Yes | 211902843 | ADP | 38MURAQ24AB3* | CDP29A15P+TXV | 59SC2D060E17**14 | 18,400 | $2,208 |
| Yes | 211871788 | ADP | 38MURAQ24AB3* | H,PE31(1,2)24+TXV | 59SC2D080E17**16 | 18,400 | $2,208 |
| Yes | 211871783 | ADP | 38MURAQ24AB3* | H,PE31(1,2)24+TXV | 59SC2D060E17**14 | 18,400 | $2,208 |
| Yes | 211871493 | ADP | 38MURAQ24AB3* | H,PE30(1,2)24+TXV | 59SC2D080E17**16 | 18,400 | $2,208 |
| Yes | 211871492 | ADP | 38MURAQ24AB3* | H,PE32(1,2)36+TXV | 59SC2D080E17**16 | 18,400 | $2,208 |
| Yes | 211871491 | ADP | 38MURAQ24AB3* | H,PE31(1,2)30+TXV | 59SC2D080E17**16 | 18,400 | $2,208 |
| Yes | 211871490 | ADP | 38MURAQ24AB3* | H,PE31(1,2)30+TXV | 59SC2D060E17**14 | 18,400 | $2,208 |
| Yes | 212391625 | ADP | DLCURAH24ABK | H,GE22(1,2)24+TXV | *92ESN0801716A* | 18,400 | $2,208 |
| Yes | 212391624 | ADP | DLCURAH24ABK | H,GE22(1,2)24+TXV | *92ESN0601714A* | 18,400 | $2,208 |
| Yes | 212391594 | ADP | DLCURAH24ABK | H,GE30(1,2)24+TXV | *92ESN0801716A* | 18,400 | $2,208 |
| Yes | 212391593 | ADP | DLCURAH24ABK | H,GE32(1,2)36+TXV | *92ESN0801716A* | 18,400 | $2,208 |
| Yes | 212391592 | ADP | DLCURAH24ABK | H,GE31(1,2)30+TXV | *92ESN0801716A* | 18,400 | $2,208 |
| Yes | 212391591 | ADP | DLCURAH24ABK | H,GE31(1,2)24+TXV | *92ESN0801716A* | 18,400 | $2,208 |
| Yes | 212391590 | ADP | DLCURAH24ABK | H,GE31(1,2)30+TXV | *92ESN0601714A* | 18,400 | $2,208 |
| Yes | 212391589 | ADP | DLCURAH24ABK | H,GE31(1,2)24+TXV | *92ESN0601714A* | 18,400 | $2,208 |
| Yes | 211782039 | ADP | DLCURAH24ABK | H,GE22936 | *92ESN0801716A* | 18,400 | $2,208 |
| Yes | 211782038 | ADP | DLCURAH24ABK | H,GE22936 | *92ESN0601714A* | 18,400 | $2,208 |
| Yes | 211780577 | ADP | DLCURAH24ABK | H,GE30924 | *92ESN0801716A* | 18,400 | $2,208 |
| Yes | 211780576 | ADP | DLCURAH24ABK | H,GE32936 | *92ESN0801716A* | 18,400 | $2,208 |
| Yes | 211780575 | ADP | DLCURAH24ABK | H,GE31930 | *92ESN0801716A* | 18,400 | $2,208 |
| Yes | 211780574 | ADP | DLCURAH24ABK | H,GE31930 | *92ESN0601714A* | 18,400 | $2,208 |
| Yes | 211289597 | ADP | AC060BXUPCH | F,PE*CC7960 | | 54,000 | $6,480 |
| Yes | 211289596 | ADP | AC048BXUPCH | F,PE*CC3948 | | 46,000 | $5,520 |
| Yes | 211289595 | ADP | AC036BXUPCH | F,PE*CC3937 | | 40,500 | $4,860 |
| Yes | 211289594 | ADP | AC036BXUDCH | F,PE*CC3937 | | 36,000 | $4,320 |
| Yes | 211289593 | ADP | AC024BXUPCH | F,PE*BB9931 | | 31,200 | $3,744 |
| Yes | 208106809 | AirEase | 4DHP2S48M-1P | Heat pump without ducts | | 36,000 | $4,320 |
| Yes | 211709579 | AIREASE | 4SHP22LX124P-**A | BCE7E30M*4X | | 14,300 | $1,716 |
| Yes | 209852138 | AIRQUEST | DLCURAH48ABK | DLFUAAH48XAK | | 36,000 | $4,320 |
| Yes | 209852142 | AIRQUEST | DLCURAH36ABK | DLFUAAH36XAK | | 30,400 | $3,648 |
| Yes | 209852136 | AIRQUEST | DLCURAH24ABK | DLFUAAH24XAK | | 19,200 | $2,304 |
| Yes | 209852135 | AIRQUEST | DLCURAH18ABK | DLFUAAH18XAK | | 13,500 | $1,620 |
| Yes | 207643191 | AIRQUEST | DLCMHBH36DAK | Heat pump without ducts | | 22,000 | $2,640 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 207643188 | AIRQUEST | DLCMHBH48EAK | Heat pump without ducts | | 34,000 | $4,080 |
| Yes | 207643182 | AIRQUEST | DLCMHBH30DAK | Heat pump without ducts | | 18,500 | $2,220 |
| Yes | 207826613 | AIRQUEST | DLCSRBH18AAK | DLFSABH18XBK | | 12,000 | $1,440 |
| Yes | 207801577 | AIRQUEST | DLCSRBH18AAK | DLFSDAH24XAK | | 12,600 | $1,512 |
| Yes | 207643189 | AIRQUEST | DLCMHBH48EAK | Heat pump with ducts | | 28,000 | $3,360 |
| Yes | 207643183 | AIRQUEST | DLCMHBH30DAK | Heat pump with ducts | | 19,000 | $2,280 |
| Yes | 207643192 | AIRQUEST | DLCMHBH36DAK | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 207643184 | AIRQUEST | DLCMHBH30DAK | Combination heat pumps with or without ducts | | 18,700 | $2,244 |
| Yes | 207643193 | AIRQUEST | DLCMHBH36DAK | Combination heat pumps with or without ducts | | 22,400 | $2,688 |
| Yes | 207643190 | AIRQUEST | DLCMHBH48EAK | Combination heat pumps with or without ducts | | 31,000 | $3,720 |
| Yes | 206350488 | AIRQUEST | DLCSRBH18AAK | DLFSFAH18XAK | | 12,000 | $1,440 |
| Yes | 206350489 | AIRQUEST | DLCSRBH24AAK | DLFSCAH24XAK | | 14,500 | $1,740 |
| Yes | 206350491 | AIRQUEST | DLCSRBH24AAK | DLFSFAH24XAK | | 14,500 | $1,740 |
| Yes | 206188344 | AIRQUEST | DLCSRBH24AAK | DLFSAAH24XAK | | 16,500 | $1,980 |
| Yes | 206350487 | AIRQUEST | DLCSRBH18AAK | DLFSDAH18XAK | | 12,700 | $1,524 |
| Yes | 206350490 | AIRQUEST | DLCSRBH24AAK | DLFSDAH24XAK | | 14,500 | $1,740 |
| Yes | 205921381 | AIRQUEST | DLCSRAH24AAK | DLFSAAH24XAK | | 17,500 | $2,100 |
| Yes | 208106794 | Allied | 4DHP2S48M-1P | Heat pump without ducts | | 36,000 | $4,320 |
| Yes | 211644101 | Alsetria | MOX430-17HFN1-MT0W | MCBU-18HRFN1-MU2W | | 14,500 | $1,740 |
| Yes | 211644046 | Alsetria | MOD30-24HFN1-MU0W | MCD1-24HRFN1-MT0W(GA) | | 21,000 | $2,520 |
| Yes | 211644042 | Alsetria | MOE30U-48HFN1-M-[X](GA) | MTI-48HWFN1-M | | 39,500 | $4,740 |
| Yes | 211644048 | Alsetria | MOE30U-48HFN1-M-[X](GA) | MCD1-48HRFN1-M(GA) | | 35,000 | $4,200 |
| Yes | 211644047 | Alsetria | MOE30U-36HFN1-M(GA) | MCD1-36HRFN1-M(GA) | | 33,000 | $3,960 |
| Yes | 211644040 | Alsetria | MOD30-24HFN1-MU0W | MTIU-24HWFN1-M | | 21,000 | $2,520 |
| Yes | 211644039 | Alsetria | MOX430-17HFN1-MT0W | MTIU-18HWFN1-M | | 15,000 | $1,800 |
| Yes | 211644106 | Alsetria | MOX430-17HFN1-MT0W | MVC-18HWFN1-MW(GA) | | 15,400 | $1,848 |
| Yes | 211644107 | Alsetria | MOD30-24HFN1-MU0W | MVC-23HWFN1-M | | 16,900 | $2,028 |
| Yes | 208130395 | Alsetria | MOE30U-48HFN1-M-[X1] | MVC-48HWFN1-M | | 36,000 | $4,320 |
| Yes | 208130392 | Alsetria | MOD30-24HFN1-MW | MVC-24HWFN1-M | | 19,200 | $2,304 |
| Yes | 208130391 | Alsetria | MOX430U-18HFN1-M | MVC-18HWFN1-M | | 13,500 | $1,620 |
| Yes | 208121904 | Alsetria | MOD30-24HFN1-MU0W | MSEPD-24HRFN1-MU0W | | 21,200 | $2,544 |
| Yes | 208121903 | Alsetria | MOX430-17HFN1-MT0W | MSEPC-18HRFN1-MU0W | | 15,000 | $1,800 |
| Yes | 210798387 | AMANA | ASZS604210A* | AHVE60DP1400A* | | 25,600 | $3,072 |
| Yes | 210773180 | AMANA | ASZS604210A* | AHVE48DP1400A* | | 25,600 | $3,072 |
| Yes | 210798386 | AMANA | ASZS604210A* | AHVE42CP1400A* | | 25,600 | $3,072 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 210692583 | AMANA | ASZV903610A* | CSCF3642N6D*+TXV | A*VM971205DNB* | 21,600 | $2,592 |
| Yes | 210692582 | AMANA | ASZV903610A* | CSCF3642N6D*+TXV | A*VM971005CNB* | 21,600 | $2,592 |
| Yes | 210692581 | AMANA | ASZV903610A* | CSCF3642N6D*+TXV | A*VM970804CNB* | 21,600 | $2,592 |
| Yes | 210692580 | AMANA | ASZV903610A* | CSCF3642N6D*+TXV | A*VM970803BNB* | 21,600 | $2,592 |
| Yes | 210692579 | AMANA | ASZV903610A* | CSCF3642N6D*+TXV | A*VM970603BNB* | 21,600 | $2,592 |
| Yes | 210692578 | AMANA | ASZV903610A* | CSCF3642N6D*+TXV | A*VC961205DNB* | 21,600 | $2,592 |
| Yes | 210692577 | AMANA | ASZV903610A* | CSCF3642N6D*+TXV | A*VC961005CNB* | 21,600 | $2,592 |
| Yes | 210692576 | AMANA | ASZV903610A* | CSCF3642N6D*+TXV | A*VS960805CUA* | 21,600 | $2,592 |
| Yes | 210692575 | AMANA | ASZV903610A* | CSCF3642N6D*+TXV | A*VC960804CNB* | 21,600 | $2,592 |
| Yes | 210692574 | AMANA | ASZV903610A* | CSCF3642N6D*+TXV | A*VC960803BNB* | 21,600 | $2,592 |
| Yes | 210692573 | AMANA | ASZV903610A* | CSCF3642N6D*+TXV | A*VC960603BNB* | 21,600 | $2,592 |
| Yes | 210692572 | AMANA | ASZV903610A* | CSCF3642N6D*+TXV | A*VS960603BUA* | 21,600 | $2,592 |
| Yes | 210692571 | AMANA | ASZV903610A* | CSCF3642N6D*+TXV | A*VC960403BNB* | 21,600 | $2,592 |
| Yes | 210692564 | AMANA | ASZV903610A* | CSCF3642N6D*+MBVC1601**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210692563 | AMANA | ASZV903610A* | CSCF3642N6D*+MBVC1201**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210692562 | AMANA | ASZV903610A* | CHPF3743C6B*+TXV | A*VM971005CNB* | 21,600 | $2,592 |
| Yes | 210692561 | AMANA | ASZV903610A* | CHPF3743C6B*+TXV | A*VM970804CNB* | 21,600 | $2,592 |
| Yes | 210692560 | AMANA | ASZV903610A* | CHPF3743C6B*+TXV | A*VM970803BNB* | 21,600 | $2,592 |
| Yes | 210692559 | AMANA | ASZV903610A* | CHPF3743C6B*+TXV | A*VM970603BNB* | 21,600 | $2,592 |
| Yes | 210692558 | AMANA | ASZV903610A* | CHPF3743C6B*+TXV | A*VC961005CNB* | 21,600 | $2,592 |
| Yes | 210692557 | AMANA | ASZV903610A* | CHPF3743C6B*+TXV | A*VS960805CUA* | 21,600 | $2,592 |
| Yes | 210692556 | AMANA | ASZV903610A* | CHPF3743C6B*+TXV | A*VC960804CNB* | 21,600 | $2,592 |
| Yes | 210692555 | AMANA | ASZV903610A* | CHPF3743C6B*+TXV | A*VC960803BNB* | 21,600 | $2,592 |
| Yes | 210692554 | AMANA | ASZV903610A* | CHPF3743C6B*+TXV | A*VC960603BNB* | 21,600 | $2,592 |
| Yes | 210692553 | AMANA | ASZV903610A* | CHPF3743C6B*+TXV | A*VS960603BUA* | 21,600 | $2,592 |
| Yes | 210692552 | AMANA | ASZV903610A* | CHPF3743C6B*+TXV | A*VC960403BNB* | 21,600 | $2,592 |
| Yes | 210692545 | AMANA | ASZV903610A* | CHPF3743C6B*+MBVC1601**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210692544 | AMANA | ASZV903610A* | CHPF3743C6B*+MBVC1201**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210692543 | AMANA | ASZV903610A* | CHPF3642C6C*+TXV | A*VM971005CNB* | 21,600 | $2,592 |
| Yes | 210692542 | AMANA | ASZV903610A* | CHPF3642C6C*+TXV | A*VM970804CNB* | 21,600 | $2,592 |
| Yes | 210692541 | AMANA | ASZV903610A* | CHPF3642C6C*+TXV | A*VM970803BNB* | 21,600 | $2,592 |
| Yes | 210692540 | AMANA | ASZV903610A* | CHPF3642C6C*+TXV | A*VM970603BNB* | 21,600 | $2,592 |
| Yes | 210692539 | AMANA | ASZV903610A* | CHPF3642C6C*+TXV | A*VC961005CNB* | 21,600 | $2,592 |
| Yes | 210692538 | AMANA | ASZV903610A* | CHPF3642C6C*+TXV | A*VS960805CUA* | 21,600 | $2,592 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 210692537 | AMANA | ASZV903610A* | CHPF3642C6C*+TXV | A*VC960804CNB* | 21,600 | $2,592 |
| Yes | 210692536 | AMANA | ASZV903610A* | CHPF3642C6C*+TXV | A*VC960803BNB* | 21,600 | $2,592 |
| Yes | 210692535 | AMANA | ASZV903610A* | CHPF3642C6C*+TXV | A*VC960603BNB* | 21,600 | $2,592 |
| Yes | 210692534 | AMANA | ASZV903610A* | CHPF3642C6C*+TXV | A*VS960603BUA* | 21,600 | $2,592 |
| Yes | 210692533 | AMANA | ASZV903610A* | CHPF3642C6C*+TXV | A*VC960403BNB* | 21,600 | $2,592 |
| Yes | 210692526 | AMANA | ASZV903610A* | CHPF3642C6C*+MBVC1601**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210692525 | AMANA | ASZV903610A* | CHPF3642C6C*+MBVC1201**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210692524 | AMANA | ASZV903610A* | CA*F3743*6D*+TXV | A*VM971205DNB* | 21,600 | $2,592 |
| Yes | 210692523 | AMANA | ASZV903610A* | CA*F3743*6D*+TXV | A*VM971005CNB* | 21,600 | $2,592 |
| Yes | 210692522 | AMANA | ASZV903610A* | CA*F3743*6D*+TXV | A*VM970804CNB* | 21,600 | $2,592 |
| Yes | 210692521 | AMANA | ASZV903610A* | CA*F3743*6D*+TXV | A*VM970803BNB* | 21,600 | $2,592 |
| Yes | 210692520 | AMANA | ASZV903610A* | CA*F3743*6D*+TXV | A*VM970603BNB* | 21,600 | $2,592 |
| Yes | 210692519 | AMANA | ASZV903610A* | CA*F3743*6D*+TXV | A*VC961205DNB* | 21,600 | $2,592 |
| Yes | 210692518 | AMANA | ASZV903610A* | CA*F3743*6D*+TXV | A*VC961005CNB* | 21,600 | $2,592 |
| Yes | 210692517 | AMANA | ASZV903610A* | CA*F3743*6D*+TXV | A*VS960805CUA* | 21,600 | $2,592 |
| Yes | 210692516 | AMANA | ASZV903610A* | CA*F3743*6D*+TXV | A*VC960804CNB* | 21,600 | $2,592 |
| Yes | 210692515 | AMANA | ASZV903610A* | CA*F3743*6D*+TXV | A*VC960803BNB* | 21,600 | $2,592 |
| Yes | 210692514 | AMANA | ASZV903610A* | CA*F3743*6D*+TXV | A*VC960603BNB* | 21,600 | $2,592 |
| Yes | 210692513 | AMANA | ASZV903610A* | CA*F3743*6D*+TXV | A*VS960603BUA* | 21,600 | $2,592 |
| Yes | 210692512 | AMANA | ASZV903610A* | CA*F3743*6D*+TXV | A*VC960403BNB* | 21,600 | $2,592 |
| Yes | 210607578 | AMANA | ASZV903610A* | CA*F3743*6D*+MBVC1601**-1A*+TX | | 21,600 | $2,592 |
| Yes | 210692505 | AMANA | ASZV903610A* | CA*F3743*6D*+MBVC1201**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210692504 | AMANA | ASZV903610A* | CA*F3137*6A*+TXV | A*VM970803BNB* | 21,600 | $2,592 |
| Yes | 210692503 | AMANA | ASZV903610A* | CA*F3137*6A*+TXV | A*VM970603BNB* | 21,600 | $2,592 |
| Yes | 210692502 | AMANA | ASZV903610A* | CA*F3137*6A*+TXV | A*VC960803BNB* | 21,600 | $2,592 |
| Yes | 210692501 | AMANA | ASZV903610A* | CA*F3137*6A*+TXV | A*VC960603BNB* | 21,600 | $2,592 |
| Yes | 210692500 | AMANA | ASZV903610A* | CA*F3137*6A*+TXV | A*VS960603BUA* | 21,600 | $2,592 |
| Yes | 210692499 | AMANA | ASZV903610A* | CA*F3137*6A*+TXV | A*VC960403BNB* | 21,600 | $2,592 |
| Yes | 210692496 | AMANA | ASZV903610A* | CA*F3137*6A*+MBVC1201**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210609969 | AMANA | ASZV903610A* | AMVE48DP1400A* | | 21,400 | $2,568 |
| Yes | 210609968 | AMANA | ASZV903610A* | AMVE36CP1400A* | | 21,600 | $2,592 |
| Yes | 212361357 | AMERICAN STANDARD | 4TXD2036A10NU** | 4RXCB024AS3HC** | | 16,800 | $2,016 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204340535 | AMERICAN STANDARD | 4TXM2318A12NU** | Heat pump without ducts | N/A | 17,000 | $2,040 |
| Yes | 204340537 | AMERICAN STANDARD | 4TXM2324A13NU** | Heat pump without ducts | N/A | 17,900 | $2,148 |
| Yes | 9150126 | AMERICAN STANDARD | 4TXK3818A10NU** | 4MXW3818A10NU** | | 14,200 | $1,704 |
| Yes | 9150128 | AMERICAN STANDARD | 4TXK3824A10NU** | 4MXW3824A10NU** | | 15,500 | $1,860 |
| Yes | 207590311 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCC009DS3 | P0V0C000M50SA+RP | 35,600 | $4,272 |
| Yes | 204780193 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCC009DS3 | P0V0C000M50SA+RP | 35,600 | $4,272 |
| Yes | 204780109 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCC009DS3 | P0V0C000M50SA+RP | 35,600 | $4,272 |
| Yes | 204780172 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCD010DS3 | P0V0C000M50SA+RP | 35,200 | $4,224 |
| Yes | 207590358 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3 | P0V0C000M50SA+RP | 35,200 | $4,224 |
| Yes | 210435424 | AMERICAN STANDARD | 4TXM2142A15N0** | Heat pump without ducts | | 35,600 | $4,272 |
| Yes | 210435423 | AMERICAN STANDARD | 4TXM2136A14N0** | Heat pump without ducts | | 30,800 | $3,696 |
| Yes | 10153449 | AMERICAN STANDARD | 4A6V0060A1 | TEM8A0D48V41+TDR | | 49,500 | $5,940 |
| Yes | 10153473 | AMERICAN STANDARD | 4A6V8060A1 | TEM8A0D48V41+TDR | | 49,500 | $5,940 |
| Yes | 208141276 | AMERICAN STANDARD | 4TXD2036A10NU** | 4MXA2024A10NU** | N/A | 16,300 | $1,956 |
| Yes | 208141274 | AMERICAN STANDARD | 4TXD2060A10NU** | 4MXA2048A10NU** | N/A | 32,000 | $3,840 |
| Yes | 208141273 | AMERICAN STANDARD | 4TXD2036A10NU** | 4MXA2036A10NU** | N/A | 24,000 | $2,880 |
| Yes | 208141275 | AMERICAN STANDARD | 4TXD2060A10NU** | 4MXA2060A10NU** | N/A | 36,000 | $4,320 |
| Yes | 202703127 | AMERICAN STANDARD | 4TXK2324A10N0** | 4MXW2324A10N0** | N/A | 14,600 | $1,752 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 206223039 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSKH36A112AA | APEADA0361AA70A | | 25,400 | $3,048 |
| Yes | 204276768 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZH0241HA00NA | APEADA0241AA70A | | 18,000 | $2,160 |
| Yes | 204444398 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZH0361HA50NA | APEADA0361AA70A | | 27,000 | $3,240 |
| Yes | 209832999 | American Standard / Mitsubishi Electric | MUZ-FS18NA*** | NAXWPH18B112A* | | 12,800 | $1,536 |
| Yes | 209424916 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NTXMPH30A132C* | Heat pump without ducts | | 18,000 | $2,160 |
| Yes | 209424912 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NTXMPH24A132C* | Heat pump without ducts | | 14,000 | $1,680 |
| Yes | 209424908 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NTXMPH20A122C* | Heat pump without ducts | | 13,700 | $1,644 |
| Yes | 202392015 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMPH48A182AA | Combination heat pumps with or without ducts | | 41,500 | $4,980 |
| Yes | 202392011 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMPH42A152AA | Combination heat pumps with or without ducts | | 36,200 | $4,344 |
| Yes | 202373707 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMPH48A182AA | Heat pump without ducts | | 40,000 | $4,800 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 202354896 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMPH36A142AA | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 206908468 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMPH20A122A** | Heat pump without ducts | | 13,000 | $1,560 |
| Yes | 206374558 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSKH30A112AA | TPEADA0301AA70A | | 25,400 | $3,048 |
| Yes | 206328183 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSKH36A112AA | PEAD-A36AA7 | | 25,400 | $3,048 |
| Yes | 206908471 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMPH20A122A** | Combination heat pumps with or without ducts | | 13,300 | $1,596 |
| Yes | 202732311 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMPH20A122AA | NAXWPH09A112AANAXWPH09A112AA | | 13,000 | $1,560 |
| Yes | 204444986 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZH0421KA00NA | APVA0A0421AA70A | | 42,000 | $5,040 |
| Yes | 204281761 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZH0241HA00NA | APVA0A0241AA70A | | 17,500 | $2,100 |
| Yes | 204874294 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZH0361HA50NA | APVA0A0361AA70A | | 29,000 | $3,480 |
| Yes | 204276764 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZH0241HA00NA | APKA0A0241KA70A | | 17,200 | $2,064 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204276539 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZH0241HA00NA | APLA0A0241EA70A | | 17,300 | $2,076 |
| Yes | 204834288 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMPH36A142B* | Heat pump without ducts | | 30,000 | $3,600 |
| Yes | 204834261 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMPH48A182B* | Heat pump without ducts | | 38,000 | $4,560 |
| Yes | 204834289 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMPH36A142B* | Heat pump with ducts | | 34,000 | $4,080 |
| Yes | 204834290 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMPH42A152B* | Heat pump without ducts | | 32,000 | $3,840 |
| Yes | 204834260 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMPH42A152B* | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 204834262 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMPH48A182B* | Heat pump with ducts | | 38,000 | $4,560 |
| Yes | 204926524 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMPH42A152B* | Combination heat pumps with or without ducts | | 34,000 | $4,080 |
| Yes | 204926523 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMPH36A142B* | Combination heat pumps with or without ducts | | 32,000 | $3,840 |
| Yes | 204926526 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMPH48A182B* | Combination heat pumps with or without ducts | | 38,000 | $4,560 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204793330 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSKH15A112AA | NAXDKS15A112AA | | 12,200 | $1,464 |
| Yes | 202373705 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMPH42A152AA | Heat pump without ducts | | 35,800 | $4,296 |
| Yes | 202373678 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPF15A112AA | NAXFKS15A112AA | | 14,400 | $1,728 |
| Yes | 202354897 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMPH36A142AA | Heat pump without ducts | | 34,000 | $4,080 |
| Yes | 202354893 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMPH24A132AA | Heat pump without ducts | | 14,000 | $1,680 |
| Yes | 202373708 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMMX60A182AA | Heat pump without ducts | | 41,500 | $4,980 |
| Yes | 202373679 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPF18A112AA | NAXFKS18A112AA | | 12,800 | $1,536 |
| Yes | 202366328 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMPH36A142AA | Combination heat pumps with or without ducts | | 35,000 | $4,200 |
| Yes | 202392007 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMPH20A122AA | Combination heat pumps with or without ducts | | 13,700 | $1,644 |
| Yes | 202366326 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMPH24A132AA | Combination heat pumps with or without ducts | | 14,000 | $1,680 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 202373672 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMPH42A152AA | Heat pump with ducts | | 36,600 | $4,392 |
| Yes | 212400613 | AMERISTAR | E4HL5018A1000A | 4TXCB003DS3 | | 20,000 | $2,400 |
| Yes | 212394377 | AMERISTAR | E4HL5024A1000A | 4TXCB003DS3 | | 20,000 | $2,400 |
| Yes | 212394376 | AMERISTAR | E4HL5024A1000A | 4TXCB004DS3 | | 20,000 | $2,400 |
| Yes | 210488263 | AMERISTAR | M4THM1942A15N** | Heat pump without ducts | | 35,600 | $4,272 |
| Yes | 210488262 | AMERISTAR | M4THM1936A14N** | Heat pump without ducts | | 30,800 | $3,696 |
| Yes | 203162806 | AMERISTAR | M4THS1824A11N** | M4MHW1824A1N0** | | 14,600 | $1,752 |
| Yes | 209852039 | ARCOAIRE | DLCURAH48ABK | DLFUAAH48XAK | | 36,000 | $4,320 |
| Yes | 209852043 | ARCOAIRE | DLCURAH36ABK | DLFUAAH36XAK | | 30,400 | $3,648 |
| Yes | 209852037 | ARCOAIRE | DLCURAH24ABK | DLFUAAH24XAK | | 19,200 | $2,304 |
| Yes | 209852036 | ARCOAIRE | DLCURAH18ABK | DLFUAAH18XAK | | 13,500 | $1,620 |
| Yes | 207643002 | ARCOAIRE | DLCMHBH36DAK | Heat pump without ducts | | 22,000 | $2,640 |
| Yes | 207642999 | ARCOAIRE | DLCMHBH48EAK | Heat pump without ducts | | 34,000 | $4,080 |
| Yes | 207642993 | ARCOAIRE | DLCMHBH30DAK | Heat pump without ducts | | 18,500 | $2,220 |
| Yes | 207826595 | ARCOAIRE | DLCSRBH18AAK | DLFSABH18XBK | | 12,000 | $1,440 |
| Yes | 207801568 | ARCOAIRE | DLCSRBH18AAK | DLFSDAH24XAK | | 12,600 | $1,512 |
| Yes | 8177094 | ARCOAIRE | DLCAHB12K1A | DLFAHH12K1A | | 13,000 | $1,560 |
| Yes | 207643003 | ARCOAIRE | DLCMHBH36DAK | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 207642994 | ARCOAIRE | DLCMHBH30DAK | Heat pump with ducts | | 19,000 | $2,280 |
| Yes | 207642995 | ARCOAIRE | DLCMHBH30DAK | Combination heat pumps with or without ducts | | 18,700 | $2,244 |
| Yes | 207643000 | ARCOAIRE | DLCMHBH48EAK | Heat pump with ducts | | 28,000 | $3,360 |
| Yes | 207643004 | ARCOAIRE | DLCMHBH36DAK | Combination heat pumps with or without ducts | | 22,400 | $2,688 |
| Yes | 207643001 | ARCOAIRE | DLCMHBH48EAK | Combination heat pumps with or without ducts | | 31,000 | $3,720 |
| Yes | 206350392 | ARCOAIRE | DLCSRBH24AAK | DLFSFAH24XAK | | 14,500 | $1,740 |
| Yes | 206350389 | ARCOAIRE | DLCSRBH18AAK | DLFSFAH18XAK | | 12,000 | $1,440 |
| Yes | 206350390 | ARCOAIRE | DLCSRBH24AAK | DLFSCAH24XAK | | 14,500 | $1,740 |
| Yes | 206188288 | ARCOAIRE | DLCSRBH24AAK | DLFSAAH24XAK | | 16,500 | $1,980 |
| Yes | 206350388 | ARCOAIRE | DLCSRBH18AAK | DLFSDAH18XAK | | 12,700 | $1,524 |
| Yes | 206350391 | ARCOAIRE | DLCSRBH24AAK | DLFSDAH24XAK | | 14,500 | $1,740 |
| Yes | 205921372 | ARCOAIRE | DLCSRAH24AAK | DLFSAAH24XAK | | 17,500 | $2,100 |
| Yes | 201835540 | ARCOAIRE | DLCSRAH24AAK | DLFSCAH24XAK | | 16,200 | $1,944 |
| Yes | 202463643 | ARCOAIRE | DLCPRAH24AAK | DLFPHAH24XAK | | 15,450 | $1,854 |
| Yes | 201835538 | ARCOAIRE | DLCSRAH24AAK | DLFSDAH24XAK | | 17,400 | $2,088 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 201835518 | ARCOAIRE | DLCSRAH24AAK | DLFSHAH24XAK | | 15,000 | $1,800 |
| Yes | 201835544 | ARCOAIRE | DLCLRAH48AAK | DLFLFAH48XAK | | 35,000 | $4,200 |
| Yes | 201835539 | ARCOAIRE | DLCSRAH24AAK | DLFSFAH24XAK | | 17,200 | $2,064 |
| Yes | 201835537 | ARCOAIRE | DLCSRAH18AAK | DLFSCAH18XAK | | 12,000 | $1,440 |
| Yes | 208106824 | Armstrong Air | 4DHP2S48M-1P | Heat pump without ducts | | 36,000 | $4,320 |
| Yes | 211709429 | ARMSTRONG AIR | 4SHP22LX124P-**A | BCE7E30M*4X | | 14,300 | $1,716 |
| Yes | 208101262 | AURORA | AU-LXU24-2A-O | AU-LCU24-2A-I | | 16,700 | $2,004 |
| Yes | 208101264 | AURORA | AU-LXU36-2A-O | AU-LCU36-2A-I | | 24,000 | $2,880 |
| Yes | 208101261 | AURORA | AU-LXU18-2A-O | AU-LCU18-2A-I | | 13,000 | $1,560 |
| Yes | 208101259 | AURORA | AU-CX24HR-2A-O | AU-BS24HR-2A-I | | 17,000 | $2,040 |
| Yes | 207743716 | AURORA | AU-MU48-2A-U | AU-BS09HR-2A-I | | 31,000 | $3,720 |
| Yes | 208101265 | AURORA | AU-LXU48-2A-O | AU-LCU48-2A-I | | 32,000 | $3,840 |
| Yes | 208101263 | AURORA | AU-LXU30-2A-O | AU-LCU30-2A-I | | 19,400 | $2,328 |
| Yes | 205662517 | AZUR | AZ-36HPA | AH-36 | | 25,000 | $3,000 |
| Yes | 210025757 | BLUERIDGE | BMAH6016C | BMAH6016I | | 42,000 | $5,040 |
| Yes | 208101246 | BLUERIDGE | BMAH4816C | BMAH4816I | | 36,000 | $4,320 |
| Yes | 208101243 | BLUERIDGE | BMAH2420C | BMAH2420I | | 19,200 | $2,304 |
| Yes | 208101242 | BLUERIDGE | BMAH1820C | BMAH1820I | | 13,500 | $1,620 |
| Yes | 207641297 | BLUERIDGE | BMM36HHC | Heat pump without ducts | | 35,000 | $4,200 |
| Yes | 208650623 | BLUERIDGE | BMM55HHC | Heat pump with ducts | | 35,200 | $4,224 |
| Yes | 208650622 | BLUERIDGE | BMM55HHC | Heat pump without ducts | | 34,800 | $4,176 |
| Yes | 207641295 | BLUERIDGE | BMM27HHC | Heat pump without ducts | | 25,600 | $3,072 |
| Yes | 207641292 | BLUERIDGE | BMM18HHC | Heat pump with ducts | | 16,000 | $1,920 |
| Yes | 207641301 | BLUERIDGE | BMM48HHC | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 207641294 | BLUERIDGE | BMM27HHC | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 207641300 | BLUERIDGE | BMM48HHC | Heat pump without ducts | | 39,000 | $4,680 |
| Yes | 207641291 | BLUERIDGE | BMM18HHC | Heat pump without ducts | | 13,500 | $1,620 |
| Yes | 210191032 | BLUERIDGE | BMY60HHUC | BM60MFCC | | 40,000 | $4,800 |
| Yes | 209550310 | BLUERIDGE | BMY18HH22C | BMM18CC2 | | 14,500 | $1,740 |
| Yes | 208650627 | BLUERIDGE | BMY48HHUC | BM48MFCC | | 35,000 | $4,200 |
| Yes | 208650626 | BLUERIDGE | BMY36HHUC | BM36MFCC | | 32,000 | $3,840 |
| Yes | 207571393 | BLUERIDGE | BMY24HH22C | BM24MCD | | 21,000 | $2,520 |
| Yes | 207571394 | BLUERIDGE | BMY24HH22C | BM24MFCC | | 19,000 | $2,280 |
| Yes | 207571390 | BLUERIDGE | BMY18HH22C | BM18MCD | | 15,000 | $1,800 |
| Yes | 207339186 | BLUERIDGE | BMY24HH22C | BMY24HH22WM | | 21,200 | $2,544 |
| Yes | 207339185 | BLUERIDGE | BMY18HH22C | BMY18HH22WM | | 15,000 | $1,800 |
| Yes | 207641298 | BLUERIDGE | BMM36HHC | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 206905357 | BLUERIDGE | BMHH48M22C | Heat pump with ducts | | 28,000 | $3,360 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 202918821 | BLUERIDGE | BMHH27M18C | Heat pump without ducts | | 18,000 | $2,160 |
| Yes | 206905350 | BLUERIDGE | BMHH27M22C | Heat pump without ducts | | 18,000 | $2,160 |
| Yes | 207641299 | BLUERIDGE | BMM36HHC | Combination heat pumps with or without ducts | | 22,400 | $2,688 |
| Yes | 207641293 | BLUERIDGE | BMM18HHC | Combination heat pumps with or without ducts | | 15,200 | $1,824 |
| Yes | 208650624 | BLUERIDGE | BMM55HHC | Combination heat pumps with or without ducts | | 35,600 | $4,272 |
| Yes | 206905356 | BLUERIDGE | BMHH48M22C | Heat pump without ducts | | 30,000 | $3,600 |
| Yes | 207641302 | BLUERIDGE | BMM48HHC | Combination heat pumps with or without ducts | | 31,000 | $3,720 |
| Yes | 208130265 | BOREAL | ENVBR36HPJ1OA | ENVBR36HPJ1IB | | 24,000 | $2,880 |
| Yes | 208130264 | BOREAL | ENVBR36HPJ1OA | ENVBR24HPJ1IB | | 16,300 | $1,956 |
| Yes | 208130267 | BOREAL | ENVBR60HPJ1OA | ENVBR60HPJ1IB | | 36,000 | $4,320 |
| Yes | 208130266 | BOREAL | ENVBR60HPJ1OA | ENVBR48HPJ1IB | | 32,000 | $3,840 |
| Yes | 207759996 | BOSCH | BMS500-AAS018-1CSXHC | BMS500-AAU018-1AHWXC | | 15,000 | $1,800 |
| Yes | 207759997 | BOSCH | BMS500-AAS024-1CSXHC | BMS500-AAU024-1AHWXC | | 21,200 | $2,544 |
| Yes | 207760043 | BOSCH | BMS500-AAM048-1CSXHC | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 207760033 | BOSCH | BMS500-AAM018-1CSXHC | Heat pump without ducts | | 15,000 | $1,800 |
| Yes | 207760042 | BOSCH | BMS500-AAM048-1CSXHC | Heat pump without ducts | | 36,000 | $4,320 |
| Yes | 207760034 | BOSCH | BMS500-AAM018-1CSXHC | Heat pump with ducts | | 16,000 | $1,920 |
| Yes | 207760008 | BOSCH | BMS500-AAS024-1CSXHC | BMS500-AAU024-1AHDXB | | 21,000 | $2,520 |
| Yes | 207760018 | BOSCH | BMS500-AAS024-1CSXHC | BMS500-AAU024-1AHCXC | | 21,000 | $2,520 |
| Yes | 207760005 | BOSCH | BMS500-AAS018-1CSXHC | BMS500-AAU018-1AHDXB | | 15,000 | $1,800 |
| Yes | 203991183 | BOSCH | BMS500-AAM027-1CSXHB | Heat pump without ducts | | 18,000 | $2,160 |
| Yes | 204014470 | BOSCH | BMS500-AAS024-1CSXHB | BMS500-AAU024-1AHDXB | | 23,000 | $2,760 |
| Yes | 10333757 | BOSCH | BOVA-60HDN1-M18M | BVA-36WN1-M18B | | 24,000 | $2,880 |
| Yes | 208157119 | BOSCH | BMS500-AAS024-1CSXHC | BMS500-AAU024-1AHWXB | | 19,400 | $2,328 |
| Yes | 211277589 | Breeze33 | HSZ18H424ZMO | SCA18H424ZMI | | 14,500 | $1,740 |
| Yes | 211273236 | Breeze33 | BZ33-HYP18OUT2-G2-P | BZ33-OWCASS18-G2-P | | 14,500 | $1,740 |
| Yes | 211277593 | Breeze33 | HSZ24H424ZMO | CA24H424ZMI | | 21,000 | $2,520 |
| Yes | 211277594 | Breeze33 | HSZ24H424ZMO | D24H424ZMI | | 21,000 | $2,520 |
| Yes | 211277595 | Breeze33 | HSZ24H424ZMO | FC24H424ZMI | | 19,000 | $2,280 |
| Yes | 211277590 | Breeze33 | HSZ18H424ZMO | D18H424ZMI | | 15,000 | $1,800 |
| Yes | 211273238 | Breeze33 | BZ33-HYP48OUT2-G2-P | BZ33-MSAHU48-G2-P | | 38,000 | $4,560 |
| Yes | 211273237 | Breeze33 | BZ33-HYP36OUT2-G2-P | BZ33-MSAHU36-G2-P | | 28,600 | $3,432 |
| Yes | 211277597 | Breeze33 | HSZ18H424ZMO | AH18H424ZMI | | 15,400 | $1,848 |
| Yes | 208130311 | Breeze33 | BZ33-HYP18OUT2-G2-P | BZ33-MSAHU18-G2-P | | 15,400 | $1,848 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 208130312 | Breeze33 | BZ33-HYP24OUT2-G2-P | BZ33-MSAHU24-G2-P | | 16,900 | $2,028 |
| Yes | 211277596 | Breeze33 | HSZ24H424ZMO | AH24H424ZMI | | 16,900 | $2,028 |
| Yes | 207862098 | BREEZE33 | BZ33-HYP182Z2-G2-P | Heat pump without ducts | | 15,000 | $1,800 |
| Yes | 207862099 | BREEZE33 | BZ33-HYP182Z2-G2-P | Heat pump with ducts | | 16,000 | $1,920 |
| Yes | 207862108 | BREEZE33 | BZ33-HYP485Z2-G2-P | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 207862102 | BREEZE33 | BZ33-HYP273Z2-G2-P | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 207862107 | BREEZE33 | BZ33-HYP485Z2-G2-P | Heat pump without ducts | | 36,000 | $4,320 |
| Yes | 207862101 | BREEZE33 | BZ33-HYP273Z2-G2-P | Heat pump without ducts | | 26,600 | $3,192 |
| Yes | 207862078 | Breeze33 | BZ33-HYP24OUT2-G2-P | BZ33-CASS24-G2-P | | 21,000 | $2,520 |
| Yes | 207862084 | Breeze33 | BZ33-HYP24OUT2-G2-P | BZ33-IFMU24-G2-P | | 19,000 | $2,280 |
| Yes | 207862081 | Breeze33 | BZ33-HYP18OUT2-G2-P | BZ33-DIDU18-P | | 15,000 | $1,800 |
| Yes | 207862073 | Breeze33 | BZ33-HYP24OUT2-G2-P | BZ33-HYP24WALL2-G2-P | | 21,200 | $2,544 |
| Yes | 207862072 | Breeze33 | BZ33-HYP18OUT2-G2-P | BZ33-HYP18WALL2-G2-P | | 15,000 | $1,800 |
| Yes | 207862105 | BREEZE33 | BZ33-HYP364Z2-G2-P | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 207862109 | BREEZE33 | BZ33-HYP485Z2-G2-P | Combination heat pumps with or without ducts | | 29,000 | $3,480 |
| Yes | 207862106 | BREEZE33 | BZ33-HYP364Z2-G2-P | Combination heat pumps with or without ducts | | 23,000 | $2,760 |
| Yes | 210450263 | BRYANT | 38MURAQ36AB3* | CNPV*4821AL* | 926TB48080V17*** | 30,400 | $3,648 |
| Yes | 210450261 | BRYANT | 38MURAQ36AB3* | CNPV*4221AL* | 926TB48080V17*** | 30,600 | $3,672 |
| Yes | 210450259 | BRYANT | 38MURAQ36AB3* | CNPV*4217AL* | 926TB36060V14*** | 30,800 | $3,696 |
| Yes | 210450258 | BRYANT | 38MURAQ36AB3* | CNPV*4217AL* | 926TB48080V17*** | 30,400 | $3,648 |
| Yes | 210450251 | BRYANT | 38MURAQ36AB3* | CAP**4821AL* | 926TB48080V17*** | 30,000 | $3,600 |
| Yes | 210450249 | BRYANT | 38MURAQ36AB3* | CAP**4321AL* | 926TB48080V17*** | 30,400 | $3,648 |
| Yes | 210450247 | BRYANT | 38MURAQ36AB3* | CAP**3721AL* | 926TB48080V17*** | 30,400 | $3,648 |
| Yes | 210450245 | BRYANT | 38MURAQ36AB3* | CAP**3717AL* | 926TB36060V14*** | 30,600 | $3,672 |
| Yes | 210450244 | BRYANT | 38MURAQ36AB3* | CAP**3717AL* | 926TB48080V17*** | 30,600 | $3,672 |
| Yes | 210450242 | BRYANT | 38MURAQ36AB3* | CAP**3621AL* | 926TB48080V17*** | 30,600 | $3,672 |
| Yes | 210450239 | BRYANT | 38MURAQ36AB3* | CAP**3617AL* | 926TB48080V17*** | 30,600 | $3,672 |
| Yes | 210450223 | BRYANT | 38MURAQ30AB3* | CAP**4321AL* | 926TB48080V17*** | 20,600 | $2,472 |
| Yes | 208447891 | BRYANT | 38MURAQ48AB3 | 40MUAAQ48XA3 | | 36,000 | $4,320 |
| Yes | 208447892 | BRYANT | 38MURAQ36AB3 | 40MUAAQ36XA3 | | 30,400 | $3,648 |
| Yes | 208447896 | BRYANT | 38MURAQ24AB3 | 40MUAAQ24XA3 | | 19,200 | $2,304 |
| Yes | 208447894 | BRYANT | 38MURAQ18AB3 | 40MUAAQ18XA3 | | 13,500 | $1,620 |
| Yes | 207642912 | BRYANT | 38MGHBQ36DA3 | Heat pump without ducts | | 23,200 | $2,784 |
| Yes | 207642909 | BRYANT | 38MGHBQ48EA3 | Heat pump without ducts | | 30,000 | $3,600 |
| Yes | 207642903 | BRYANT | 38MGHBQ30DA3 | Heat pump without ducts | | 17,500 | $2,100 |
| Yes | 9854627 | BRYANT | 38MGRQ30D--3 | Heat pump without ducts | | 17,400 | $2,088 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 9118474 | BRYANT | 38MGRQ36D--3 | Heat pump without ducts | | 23,200 | $2,784 |
| Yes | 206790019 | BRYANT | 284ANV024*0**B* | FE4AN(B,F)005L+UI | | 23,800 | $2,856 |
| Yes | 207826664 | BRYANT | 38MARBQ18AA3 | 40MBABQ18XB3 | | 12,000 | $1,440 |
| Yes | 207801579 | BRYANT | 38MARBQ18AA3 | 40MBDQ24---3 | | 12,600 | $1,512 |
| Yes | 204430254 | BRYANT | 280ANV036*0**A* | CAP**3721AL*+UI | 987MB42080C17*** | 33,200 | $3,984 |
| Yes | 204430340 | BRYANT | 280ANV036*0**A* | CAP**4321AL*+UI | 987MB42080C17*** | 33,200 | $3,984 |
| Yes | 204431467 | BRYANT | 280ANV048*0**A* | CAP**6024AL*+UI | 986TC60080C21*** | 49,000 | $5,880 |
| Yes | 204430524 | BRYANT | 280ANV036*0**A* | CNPV*3617AL*+UI | 88*TA36070C14*** | 32,600 | $3,912 |
| Yes | 204430468 | BRYANT | 280ANV036*0**A* | CAP**6121AL*+UI | 987MB42060C17*** | 33,000 | $3,960 |
| Yes | 204431731 | BRYANT | 280ANV060*0**A* | CNPV*6024AL*+UI | 987MB66100C21*** | 56,000 | $6,720 |
| Yes | 204430338 | BRYANT | 280ANV036*0**A* | CAP**4321AL*+UI | 986TC42080C17*** | 33,200 | $3,984 |
| Yes | 204430157 | BRYANT | 280ANV036*0**A* | CNPV*3617AL*+UI | 987MB42080C17*** | 31,000 | $3,720 |
| Yes | 204430368 | BRYANT | 280ANV036*0**A* | CAP**4821AL*+UI | 987MB42080C17*** | 33,000 | $3,960 |
| Yes | 204431325 | BRYANT | 280ANV036*0**A* | CSPH*6012AL*+UI | 987MB42060C17*** | 33,000 | $3,960 |
| Yes | 204430233 | BRYANT | 280ANV036*0**A* | CAP**3717AL*+UI | 88*TA48070C17*** | 33,200 | $3,984 |
| Yes | 204430248 | BRYANT | 280ANV036*0**A* | CAP**3721AL*+UI | 986TC42060C17*** | 33,400 | $4,008 |
| Yes | 204430235 | BRYANT | 280ANV036*0**A* | CAP**3717AL*+UI | 88*TA36070C14*** | 33,400 | $4,008 |
| Yes | 204430365 | BRYANT | 280ANV036*0**A* | CAP**4821AL*+UI | 987MB42060C17*** | 33,200 | $3,984 |
| Yes | 204430731 | BRYANT | 280ANV036*0**A* | CNPV*4821AL*+UI | 987MB42060C17*** | 33,400 | $4,008 |
| Yes | 204431146 | BRYANT | 280ANV036*0**A* | CSPH*4212AL*+UI | 987MB42080C17*** | 33,200 | $3,984 |
| Yes | 204431264 | BRYANT | 280ANV036*0**A* | CSPH*4812AL*+UI | 987MB42080C17*** | 33,200 | $3,984 |
| Yes | 204430205 | BRYANT | 280ANV036*0**A* | CAP**3621AL*+UI | 986TC42060C17*** | 32,800 | $3,936 |
| Yes | 204431000 | BRYANT | 280ANV036*0**A* | CSPH*3612AL*+UI | 987MB42080C17*** | 33,400 | $4,008 |
| Yes | 204430588 | BRYANT | 280ANV036*0**A* | CNPV*4217AL*+UI | 987MB42080C17*** | 33,400 | $4,008 |
| Yes | 204430954 | BRYANT | 280ANV036*0**A* | CSPH*3612AL*+UI | 88*TA48070C17*** | 33,200 | $3,984 |
| Yes | 204430696 | BRYANT | 280ANV036*0**A* | CNPV*4221AL*+UI | 987MB60060C21*** | 33,000 | $3,960 |
| Yes | 204430182 | BRYANT | 280ANV036*0**A* | CAP**3617AL*+UI | 986TC42080C17*** | 32,800 | $3,936 |
| Yes | 204430535 | BRYANT | 280ANV036*0**A* | CNPV*3621AL*+UI | 986TC42080C17*** | 32,600 | $3,912 |
| Yes | 204430626 | BRYANT | 280ANV036*0**A* | CNPV*4221AL*+UI | 986TC42080C17*** | 33,200 | $3,984 |
| Yes | 204430617 | BRYANT | 280ANV036*0**A* | CNPV*4221AL*+UI | 986TC42060C17*** | 33,400 | $4,008 |
| Yes | 204430141 | BRYANT | 280ANV036*0**A* | CNPV*3621AL*+UI | 88*TA60090C21*** | 33,000 | $3,960 |
| Yes | 204430138 | BRYANT | 280ANV036*0**A* | CNPV*3617AL*+UI | 986TC42080C17*** | 33,600 | $4,032 |
| Yes | 204431608 | BRYANT | 280ANV048*0**A* | CSPH*6012AL*+UI | 987MB60080C21*** | 49,000 | $5,880 |
| Yes | 204431599 | BRYANT | 280ANV048*0**A* | CSPH*6012AL*+UI | 88*TA60070C21*** | 49,000 | $5,880 |
| Yes | 204431488 | BRYANT | 280ANV048*0**A* | CAP**6121AL*+UI | 986TC60080C21*** | 49,000 | $5,880 |
| Yes | 204431612 | BRYANT | 280ANV048*0**A* | CSPH*6012AL*+UI | 987MB66100C21*** | 49,000 | $5,880 |
| Yes | 204430200 | BRYANT | 280ANV036*0**A* | CAP**3621AL*+UI | 88*TA60070C21*** | 32,400 | $3,888 |
| Yes | 204431752 | BRYANT | 280ANV060*0**A* | CSPH*6012AL*+UI | 88*TA66135C24*** | 55,000 | $6,600 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204431722 | BRYANT | 280ANV060*0**A* | CNPV*6024AL*+UI | 88*TA66135C24*** | 55,500 | $6,660 |
| Yes | 204430164 | BRYANT | 280ANV036*0**A* | CNPV*4217AL*+UI | 987MB42060C17*** | 31,000 | $3,720 |
| Yes | 204430149 | BRYANT | 280ANV036*0**A* | CAP**4221AL*+UI | 987MB42080C17*** | 30,600 | $3,672 |
| Yes | 204431246 | BRYANT | 280ANV036*0**A* | CSPH*4812AL*+UI | 986TC42060C17*** | 33,200 | $3,984 |
| Yes | 204430724 | BRYANT | 280ANV036*0**A* | CNPV*4821AL*+UI | 986TC42060C17*** | 33,200 | $3,984 |
| Yes | 204431126 | BRYANT | 280ANV036*0**A* | CSPH*4212AL*+UI | 986TC42060C17*** | 33,400 | $4,008 |
| Yes | 204431079 | BRYANT | 280ANV036*0**A* | CSPH*3612AL*+UI | 987MB60060C21*** | 33,200 | $3,984 |
| Yes | 204430583 | BRYANT | 280ANV036*0**A* | CNPV*4217AL*+UI | 986TC42080C17*** | 33,400 | $4,008 |
| Yes | 204430208 | BRYANT | 280ANV036*0**A* | CAP**3621AL*+UI | 986TC42080C17*** | 32,600 | $3,912 |
| Yes | 204430592 | BRYANT | 280ANV036*0**A* | CNPV*4217AL*+UI | 88*TA36070C14*** | 33,200 | $3,984 |
| Yes | 204430993 | BRYANT | 280ANV036*0**A* | CSPH*3612AL*+UI | 986TC42080C17*** | 33,400 | $4,008 |
| Yes | 204430568 | BRYANT | 280ANV036*0**A* | CNPV*4217AL*+UI | 88*TA36045C17*** | 33,600 | $4,032 |
| Yes | 204430274 | BRYANT | 280ANV036*0**A* | CAP**4221AL*+UI | 986TC42060C17*** | 33,200 | $3,984 |
| Yes | 204430598 | BRYANT | 280ANV036*0**A* | CNPV*4221AL*+UI | 88*TA36045C17*** | 33,400 | $4,008 |
| Yes | 204430576 | BRYANT | 280ANV036*0**A* | CNPV*4217AL*+UI | 986TC42060C17*** | 33,600 | $4,032 |
| Yes | 204430986 | BRYANT | 280ANV036*0**A* | CSPH*3612AL*+UI | 986TC42060C17*** | 33,600 | $4,032 |
| Yes | 204431605 | BRYANT | 280ANV048*0**A* | CSPH*6012AL*+UI | 986TC66120C24*** | 48,500 | $5,820 |
| Yes | 204431444 | BRYANT | 280ANV048*0**A* | CAP**6024AL*+UI | 986TC66120C24*** | 48,500 | $5,820 |
| Yes | 204431432 | BRYANT | 280ANV048*0**A* | CAP**6024AL*+UI | 88*TA60070C21*** | 50,000 | $6,000 |
| Yes | 204431451 | BRYANT | 280ANV048*0**A* | CAP**6024AL*+UI | 987MB60080C21*** | 49,000 | $5,880 |
| Yes | 204431387 | BRYANT | 280ANV048*0**A* | CAP**4824AL*+UI | 986TC66120C24*** | 50,500 | $6,060 |
| Yes | 204431394 | BRYANT | 280ANV048*0**A* | CAP**4824AL*+UI | 987MB66100C21*** | 50,500 | $6,060 |
| Yes | 204431371 | BRYANT | 280ANV048*0**A* | CAP**4821AL*+UI | 987MB60080C21*** | 49,500 | $5,940 |
| Yes | 204431210 | BRYANT | 280ANV036*0**A* | CSPH*4812AL*+UI | 88*TA36045C17*** | 33,400 | $4,008 |
| Yes | 204431364 | BRYANT | 280ANV048*0**A* | CAP**4821AL*+UI | 88*TA60070C21*** | 50,500 | $6,060 |
| Yes | 204431390 | BRYANT | 280ANV048*0**A* | CAP**4824AL*+UI | 987MB60080C21*** | 50,500 | $6,060 |
| Yes | 204431384 | BRYANT | 280ANV048*0**A* | CAP**4824AL*+UI | 88*TA60070C21*** | 50,500 | $6,060 |
| Yes | 204430452 | BRYANT | 280ANV036*0**A* | CAP**6121AL*+UI | 88*TA36045C17*** | 33,000 | $3,960 |
| Yes | 204430360 | BRYANT | 280ANV036*0**A* | CAP**4821AL*+UI | 986TC42060C17*** | 33,200 | $3,984 |
| Yes | 204431616 | BRYANT | 280ANV048*0**A* | CSPH*6012AL*+UI | 987MB66120C24*** | 49,000 | $5,880 |
| Yes | 204430700 | BRYANT | 280ANV036*0**A* | CNPV*4821AL*+UI | 88*TA36045C17*** | 33,400 | $4,008 |
| Yes | 204431620 | BRYANT | 280ANV048*0**A* | CSPH*6012AL*+UI | 986TC60080C21*** | 49,000 | $5,880 |
| Yes | 204431623 | BRYANT | 280ANV048*0**A* | CSPH*6012AL*+UI | 986TC66100C21*** | 49,000 | $5,880 |
| Yes | 204431626 | BRYANT | 280ANV048*0**A* | CSPH*6012AL*+UI | 88*TA48090C17*** | 49,000 | $5,880 |
| Yes | 204431480 | BRYANT | 280ANV048*0**A* | CAP**6121AL*+UI | 88*TA60090C21*** | 48,500 | $5,820 |
| Yes | 204431492 | BRYANT | 280ANV048*0**A* | CAP**6121AL*+UI | 986TC66100C21*** | 48,500 | $5,820 |
| Yes | 204431513 | BRYANT | 280ANV048*0**A* | CAP**6124AL*+UI | 986TC66120C24*** | 48,500 | $5,820 |
| Yes | 204431499 | BRYANT | 280ANV048*0**A* | CAP**6121AL*+UI | 88*TA60110C21*** | 48,500 | $5,820 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204431485 | BRYANT | 280ANV048*0**A* | CAP**6121AL*+UI | 987MB66100C21*** | 48,500 | $5,820 |
| Yes | 204431439 | BRYANT | 280ANV048*0**A* | CAP**6024AL*+UI | 88*TA60090C21*** | 48,500 | $5,820 |
| Yes | 204431477 | BRYANT | 280ANV048*0**A* | CAP**6121AL*+UI | 88*TA60070C21*** | 49,000 | $5,880 |
| Yes | 204431496 | BRYANT | 280ANV048*0**A* | CAP**6121AL*+UI | 88*TA48090C17*** | 49,000 | $5,880 |
| Yes | 204431502 | BRYANT | 280ANV048*0**A* | CAP**6124AL*+UI | 88*TA60070C21*** | 49,000 | $5,880 |
| Yes | 204431423 | BRYANT | 280ANV048*0**A* | CAP**4824AL*+UI | 88*TA60110C21*** | 50,500 | $6,060 |
| Yes | 204431367 | BRYANT | 280ANV048*0**A* | CAP**4821AL*+UI | 88*TA60090C21*** | 50,500 | $6,060 |
| Yes | 204431458 | BRYANT | 280ANV048*0**A* | CAP**6024AL*+UI | 987MB66120C24*** | 49,000 | $5,880 |
| Yes | 204431416 | BRYANT | 280ANV048*0**A* | CAP**4824AL*+UI | 986TC66100C21*** | 50,500 | $6,060 |
| Yes | 204430349 | BRYANT | 280ANV036*0**A* | CAP**4821AL*+UI | 88*TA36045C17*** | 33,200 | $3,984 |
| Yes | 204430539 | BRYANT | 280ANV036*0**A* | CNPV*3621AL*+UI | 987MB42080C17*** | 32,600 | $3,912 |
| Yes | 204430515 | BRYANT | 280ANV036*0**A* | CNPV*3617AL*+UI | 88*TA48070C17*** | 32,600 | $3,912 |
| Yes | 204430529 | BRYANT | 280ANV036*0**A* | CNPV*3621AL*+UI | 88*TA48070C17*** | 32,400 | $3,888 |
| Yes | 204430564 | BRYANT | 280ANV036*0**A* | CNPV*3621AL*+UI | 987MB60060C21*** | 32,600 | $3,912 |
| Yes | 204430197 | BRYANT | 280ANV036*0**A* | CAP**3621AL*+UI | 88*TA48070C17*** | 32,400 | $3,888 |
| Yes | 204431529 | BRYANT | 280ANV048*0**A* | CAP**6124AL*+UI | 88*TA60110C21*** | 48,500 | $5,820 |
| Yes | 204431520 | BRYANT | 280ANV048*0**A* | CAP**6124AL*+UI | 987MB66100C21*** | 48,500 | $5,820 |
| Yes | 204431516 | BRYANT | 280ANV048*0**A* | CAP**6124AL*+UI | 987MB60080C21*** | 49,000 | $5,880 |
| Yes | 204431522 | BRYANT | 280ANV048*0**A* | CAP**6124AL*+UI | 986TC60080C21*** | 49,000 | $5,880 |
| Yes | 204430176 | BRYANT | 280ANV036*0**A* | CAP**3617AL*+UI | 88*TA48070C17*** | 32,600 | $3,912 |
| Yes | 204430266 | BRYANT | 280ANV036*0**A* | CAP**4221AL*+UI | 88*TA48070C17*** | 32,800 | $3,936 |
| Yes | 204430639 | BRYANT | 280ANV036*0**A* | CNPV*4221AL*+UI | 987MB42080C17*** | 33,200 | $3,984 |
| Yes | 204430543 | BRYANT | 280ANV036*0**A* | CNPV*3621AL*+UI | 987MB60080C21*** | 32,200 | $3,864 |
| Yes | 204430211 | BRYANT | 280ANV036*0**A* | CAP**3621AL*+UI | 987MB42080C17*** | 32,600 | $3,912 |
| Yes | 204430243 | BRYANT | 280ANV036*0**A* | CAP**3721AL*+UI | 88*TA60070C21*** | 32,800 | $3,936 |
| Yes | 204431305 | BRYANT | 280ANV036*0**A* | CSPH*6012AL*+UI | 88*TA48070C17*** | 32,600 | $3,912 |
| Yes | 204430259 | BRYANT | 280ANV036*0**A* | CAP**3721AL*+UI | 986TC60080C21*** | 32,800 | $3,936 |
| Yes | 204430376 | BRYANT | 280ANV036*0**A* | CAP**4821AL*+UI | 986TC60080C21*** | 32,600 | $3,912 |
| Yes | 204430256 | BRYANT | 280ANV036*0**A* | CAP**3721AL*+UI | 987MB60080C21*** | 32,800 | $3,936 |
| Yes | 204430471 | BRYANT | 280ANV036*0**A* | CAP**6121AL*+UI | 987MB42080C17*** | 32,800 | $3,936 |
| Yes | 204430346 | BRYANT | 280ANV036*0**A* | CAP**4321AL*+UI | 987MB60060C21*** | 33,000 | $3,960 |
| Yes | 204430335 | BRYANT | 280ANV036*0**A* | CAP**4321AL*+UI | 88*TA60070C21*** | 32,800 | $3,936 |
| Yes | 204430512 | BRYANT | 280ANV036*0**A* | CAP**6124AL*+UI | 987MB60060C21*** | 32,600 | $3,912 |
| Yes | 204430485 | BRYANT | 280ANV036*0**A* | CAP**6121AL*+UI | 987MB60060C21*** | 32,600 | $3,912 |
| Yes | 204430466 | BRYANT | 280ANV036*0**A* | CAP**6121AL*+UI | 986TC42080C17*** | 32,800 | $3,936 |
| Yes | 204430241 | BRYANT | 280ANV036*0**A* | CAP**3721AL*+UI | 88*TA48070C17*** | 33,000 | $3,960 |
| Yes | 204431293 | BRYANT | 280ANV036*0**A* | CSPH*4812AL*+UI | 88*TA48090C17*** | 32,600 | $3,912 |
| Yes | 204431328 | BRYANT | 280ANV036*0**A* | CSPH*6012AL*+UI | 987MB42080C17*** | 32,800 | $3,936 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204430352 | BRYANT | 280ANV036*0**A* | CAP**4821AL*+UI | 88*TA48070C17*** | 32,800 | $3,936 |
| Yes | 204431275 | BRYANT | 280ANV036*0**A* | CSPH*4812AL*+UI | 987MB66120C24*** | 32,800 | $3,936 |
| Yes | 204431279 | BRYANT | 280ANV036*0**A* | CSPH*4812AL*+UI | 986TC60080C21*** | 32,800 | $3,936 |
| Yes | 204430261 | BRYANT | 280ANV036*0**A* | CAP**3721AL*+UI | 987MB60060C21*** | 33,000 | $3,960 |
| Yes | 204431169 | BRYANT | 280ANV036*0**A* | CSPH*4212AL*+UI | 987MB66120C24*** | 32,800 | $3,936 |
| Yes | 204431174 | BRYANT | 280ANV036*0**A* | CSPH*4212AL*+UI | 986TC60080C21*** | 32,800 | $3,936 |
| Yes | 204430324 | BRYANT | 280ANV036*0**A* | CAP**4224AL*+UI | 986TC66100C21*** | 32,400 | $3,888 |
| Yes | 204430296 | BRYANT | 280ANV036*0**A* | CAP**4221AL*+UI | 88*TA60110C21*** | 32,600 | $3,912 |
| Yes | 204431180 | BRYANT | 280ANV036*0**A* | CSPH*4212AL*+UI | 986TC66100C21*** | 32,800 | $3,936 |
| Yes | 204431193 | BRYANT | 280ANV036*0**A* | CSPH*4212AL*+UI | 88*TA48090C17*** | 32,800 | $3,936 |
| Yes | 204431054 | BRYANT | 280ANV036*0**A* | CSPH*3612AL*+UI | 88*TA48090C17*** | 32,800 | $3,936 |
| Yes | 204430238 | BRYANT | 280ANV036*0**A* | CAP**3717AL*+UI | 88*TA48090C17*** | 33,000 | $3,960 |
| Yes | 204430463 | BRYANT | 280ANV036*0**A* | CAP**6121AL*+UI | 986TC42060C17*** | 33,000 | $3,960 |
| Yes | 204431215 | BRYANT | 280ANV036*0**A* | CSPH*4812AL*+UI | 88*TA48070C17*** | 33,000 | $3,960 |
| Yes | 204430970 | BRYANT | 280ANV036*0**A* | CSPH*3612AL*+UI | 88*TA60090C21*** | 32,800 | $3,936 |
| Yes | 204431069 | BRYANT | 280ANV036*0**A* | CSPH*3612AL*+UI | 88*TA60110C21*** | 32,800 | $3,936 |
| Yes | 204431098 | BRYANT | 280ANV036*0**A* | CSPH*4212AL*+UI | 88*TA48070C17*** | 33,000 | $3,960 |
| Yes | 204430272 | BRYANT | 280ANV036*0**A* | CAP**4221AL*+UI | 88*TA60090C21*** | 32,400 | $3,888 |
| Yes | 204430304 | BRYANT | 280ANV036*0**A* | CAP**4224AL*+UI | 88*TA60090C21*** | 32,400 | $3,888 |
| Yes | 204430327 | BRYANT | 280ANV036*0**A* | CAP**4224AL*+UI | 88*TA60110C21*** | 32,400 | $3,888 |
| Yes | 204431036 | BRYANT | 280ANV036*0**A* | CSPH*3612AL*+UI | 986TC66100C21*** | 32,800 | $3,936 |
| Yes | 204430532 | BRYANT | 280ANV036*0**A* | CNPV*3621AL*+UI | 88*TA60070C21*** | 32,400 | $3,888 |
| Yes | 204431025 | BRYANT | 280ANV036*0**A* | CSPH*3612AL*+UI | 986TC60080C21*** | 33,000 | $3,960 |
| Yes | 204431017 | BRYANT | 280ANV036*0**A* | CSPH*3612AL*+UI | 987MB66120C24*** | 33,000 | $3,960 |
| Yes | 204430293 | BRYANT | 280ANV036*0**A* | CAP**4221AL*+UI | 88*TA48090C17*** | 32,600 | $3,912 |
| Yes | 204431189 | BRYANT | 280ANV036*0**A* | CSPH*4212AL*+UI | 88*TA36070C14*** | 33,200 | $3,984 |
| Yes | 204430573 | BRYANT | 280ANV036*0**A* | CNPV*4217AL*+UI | 88*TA48070C17*** | 33,200 | $3,984 |
| Yes | 204431601 | BRYANT | 280ANV048*0**A* | CSPH*6012AL*+UI | 88*TA66135C24*** | 48,500 | $5,820 |
| Yes | 204431298 | BRYANT | 280ANV036*0**A* | CSPH*4812AL*+UI | 987MB60060C21*** | 33,000 | $3,960 |
| Yes | 204430214 | BRYANT | 280ANV036*0**A* | CAP**3621AL*+UI | 987MB60080C21*** | 32,200 | $3,864 |
| Yes | 204430547 | BRYANT | 280ANV036*0**A* | CNPV*3621AL*+UI | 987MB66100C21*** | 32,200 | $3,864 |
| Yes | 204430965 | BRYANT | 280ANV036*0**A* | CSPH*3612AL*+UI | 88*TA60070C21*** | 33,000 | $3,960 |
| Yes | 204431204 | BRYANT | 280ANV036*0**A* | CSPH*4212AL*+UI | 987MB60060C21*** | 33,200 | $3,984 |
| Yes | 204431002 | BRYANT | 280ANV036*0**A* | CSPH*3612AL*+UI | 987MB60080C21*** | 33,000 | $3,960 |
| Yes | 204431130 | BRYANT | 280ANV036*0**A* | CSPH*4212AL*+UI | 986TC42080C17*** | 33,200 | $3,984 |
| Yes | 204430604 | BRYANT | 280ANV036*0**A* | CNPV*4221AL*+UI | 88*TA60070C21*** | 32,800 | $3,936 |
| Yes | 204430329 | BRYANT | 280ANV036*0**A* | CAP**4224AL*+UI | 987MB60060C21*** | 32,800 | $3,936 |
| Yes | 204430230 | BRYANT | 280ANV036*0**A* | CAP**3621AL*+UI | 987MB60060C21*** | 32,600 | $3,912 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204431044 | BRYANT | 280ANV036*0**A* | CSPH*3612AL*+UI | 88*TA36070C14*** | 33,200 | $3,984 |
| Yes | 204430299 | BRYANT | 280ANV036*0**A* | CAP**4221AL*+UI | 987MB60060C21*** | 33,000 | $3,960 |
| Yes | 204431320 | BRYANT | 280ANV036*0**A* | CSPH*6012AL*+UI | 986TC42080C17*** | 32,800 | $3,936 |
| Yes | 204430332 | BRYANT | 280ANV036*0**A* | CAP**4321AL*+UI | 88*TA48070C17*** | 33,000 | $3,960 |
| Yes | 204431441 | BRYANT | 280ANV048*0**A* | CAP**6024AL*+UI | 88*TA66135C24*** | 48,500 | $5,820 |
| Yes | 204430269 | BRYANT | 280ANV036*0**A* | CAP**4221AL*+UI | 88*TA60070C21*** | 32,800 | $3,936 |
| Yes | 204431317 | BRYANT | 280ANV036*0**A* | CSPH*6012AL*+UI | 986TC42060C17*** | 33,000 | $3,960 |
| Yes | 204430166 | BRYANT | 280ANV036*0**A* | CNPV*4821AL*+UI | 987MB42080C17*** | 32,600 | $3,912 |
| Yes | 204431289 | BRYANT | 280ANV036*0**A* | CSPH*4812AL*+UI | 88*TA36070C14*** | 33,000 | $3,960 |
| Yes | 204430419 | BRYANT | 280ANV036*0**A* | CAP**4824AL*+UI | 987MB60060C21*** | 32,800 | $3,936 |
| Yes | 204430727 | BRYANT | 280ANV036*0**A* | CNPV*4821AL*+UI | 986TC42080C17*** | 33,200 | $3,984 |
| Yes | 204430302 | BRYANT | 280ANV036*0**A* | CAP**4224AL*+UI | 88*TA60070C21*** | 32,600 | $3,912 |
| Yes | 204430387 | BRYANT | 280ANV036*0**A* | CAP**4821AL*+UI | 987MB60060C21*** | 33,000 | $3,960 |
| Yes | 204431505 | BRYANT | 280ANV048*0**A* | CAP**6124AL*+UI | 88*TA60090C21*** | 48,500 | $5,820 |
| Yes | 204431250 | BRYANT | 280ANV036*0**A* | CSPH*4812AL*+UI | 986TC42080C17*** | 33,200 | $3,984 |
| Yes | 204430527 | BRYANT | 280ANV036*0**A* | CNPV*3617AL*+UI | 88*TA48090C17*** | 32,200 | $3,864 |
| Yes | 204431302 | BRYANT | 280ANV036*0**A* | CSPH*6012AL*+UI | 88*TA36045C17*** | 33,000 | $3,960 |
| Yes | 204430555 | BRYANT | 280ANV036*0**A* | CNPV*3621AL*+UI | 986TC66100C21*** | 32,200 | $3,864 |
| Yes | 204430390 | BRYANT | 280ANV036*0**A* | CAP**4824AL*+UI | 88*TA60070C21*** | 32,600 | $3,912 |
| Yes | 204430558 | BRYANT | 280ANV036*0**A* | CNPV*3621AL*+UI | 88*TA48090C17*** | 32,200 | $3,864 |
| Yes | 204430354 | BRYANT | 280ANV036*0**A* | CAP**4821AL*+UI | 88*TA60070C21*** | 32,600 | $3,912 |
| Yes | 204430362 | BRYANT | 280ANV036*0**A* | CAP**4821AL*+UI | 986TC42080C17*** | 33,000 | $3,960 |
| Yes | 204430318 | BRYANT | 280ANV036*0**A* | CAP**4224AL*+UI | 987MB66120C24*** | 32,600 | $3,912 |
| Yes | 204430291 | BRYANT | 280ANV036*0**A* | CAP**4221AL*+UI | 986TC66100C21*** | 32,600 | $3,912 |
| Yes | 204431509 | BRYANT | 280ANV048*0**A* | CAP**6124AL*+UI | 88*TA66135C24*** | 48,500 | $5,820 |
| Yes | 204430191 | BRYANT | 280ANV036*0**A* | CAP**3617AL*+UI | 88*TA48090C17*** | 32,400 | $3,888 |
| Yes | 204430561 | BRYANT | 280ANV036*0**A* | CNPV*3621AL*+UI | 88*TA60110C21*** | 32,200 | $3,864 |
| Yes | 204430227 | BRYANT | 280ANV036*0**A* | CAP**3621AL*+UI | 88*TA60110C21*** | 32,200 | $3,864 |
| Yes | 204430551 | BRYANT | 280ANV036*0**A* | CNPV*3621AL*+UI | 986TC60080C21*** | 32,200 | $3,864 |
| Yes | 204430202 | BRYANT | 280ANV036*0**A* | CAP**3621AL*+UI | 88*TA60090C21*** | 32,000 | $3,840 |
| Yes | 204430219 | BRYANT | 280ANV036*0**A* | CAP**3621AL*+UI | 986TC60080C21*** | 32,200 | $3,864 |
| Yes | 204430222 | BRYANT | 280ANV036*0**A* | CAP**3621AL*+UI | 986TC66100C21*** | 32,200 | $3,864 |
| Yes | 204430321 | BRYANT | 280ANV036*0**A* | CAP**4224AL*+UI | 986TC60080C21*** | 32,600 | $3,912 |
| Yes | 204430225 | BRYANT | 280ANV036*0**A* | CAP**3621AL*+UI | 88*TA48090C17*** | 32,200 | $3,864 |
| Yes | 204431345 | BRYANT | 280ANV036*0**A* | CSPH*6012AL*+UI | 986TC66100C21*** | 32,200 | $3,864 |
| Yes | 204430504 | BRYANT | 280ANV036*0**A* | CAP**6124AL*+UI | 987MB66120C24*** | 32,200 | $3,864 |
| Yes | 204430667 | BRYANT | 280ANV036*0**A* | CNPV*4221AL*+UI | 986TC60080C21*** | 32,600 | $3,912 |
| Yes | 204430080 | BRYANT | 280ANV024*0**A* | CSPH*2412AL*+UI | 986TC42060C17*** | 22,800 | $2,736 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204430685 | BRYANT | 280ANV036*0**A* | CNPV*4221AL*+UI | 88*TA48090C17*** | 32,600 | $3,912 |
| Yes | 204430287 | BRYANT | 280ANV036*0**A* | CAP**4221AL*+UI | 986TC60080C21*** | 32,600 | $3,912 |
| Yes | 204430602 | BRYANT | 280ANV036*0**A* | CNPV*4221AL*+UI | 88*TA48070C17*** | 32,800 | $3,936 |
| Yes | 204430676 | BRYANT | 280ANV036*0**A* | CNPV*4221AL*+UI | 986TC66100C21*** | 32,600 | $3,912 |
| Yes | 204431355 | BRYANT | 280ANV036*0**A* | CSPH*6012AL*+UI | 88*TA60110C21*** | 32,200 | $3,864 |
| Yes | 204430477 | BRYANT | 280ANV036*0**A* | CAP**6121AL*+UI | 987MB66100C21*** | 32,200 | $3,864 |
| Yes | 204430507 | BRYANT | 280ANV036*0**A* | CAP**6124AL*+UI | 986TC60080C21*** | 32,200 | $3,864 |
| Yes | 204430474 | BRYANT | 280ANV036*0**A* | CAP**6121AL*+UI | 987MB60080C21*** | 32,400 | $3,888 |
| Yes | 204430479 | BRYANT | 280ANV036*0**A* | CAP**6121AL*+UI | 986TC60080C21*** | 32,400 | $3,888 |
| Yes | 204430482 | BRYANT | 280ANV036*0**A* | CAP**6121AL*+UI | 986TC66100C21*** | 32,200 | $3,864 |
| Yes | 204430498 | BRYANT | 280ANV036*0**A* | CAP**6124AL*+UI | 987MB60080C21*** | 32,200 | $3,864 |
| Yes | 204430382 | BRYANT | 280ANV036*0**A* | CAP**4821AL*+UI | 88*TA48090C17*** | 32,600 | $3,912 |
| Yes | 204431337 | BRYANT | 280ANV036*0**A* | CSPH*6012AL*+UI | 987MB66120C24*** | 32,400 | $3,888 |
| Yes | 204431341 | BRYANT | 280ANV036*0**A* | CSPH*6012AL*+UI | 986TC60080C21*** | 32,400 | $3,888 |
| Yes | 204430446 | BRYANT | 280ANV036*0**A* | CAP**6024AL*+UI | 88*TA60110C21*** | 32,000 | $3,840 |
| Yes | 204430441 | BRYANT | 280ANV036*0**A* | CAP**6024AL*+UI | 986TC60080C21*** | 32,200 | $3,864 |
| Yes | 204430444 | BRYANT | 280ANV036*0**A* | CAP**6024AL*+UI | 986TC66100C21*** | 32,200 | $3,864 |
| Yes | 204430413 | BRYANT | 280ANV036*0**A* | CAP**4824AL*+UI | 986TC66100C21*** | 32,400 | $3,888 |
| Yes | 204430416 | BRYANT | 280ANV036*0**A* | CAP**4824AL*+UI | 88*TA60110C21*** | 32,400 | $3,888 |
| Yes | 204430438 | BRYANT | 280ANV036*0**A* | CAP**6024AL*+UI | 987MB66120C24*** | 32,200 | $3,864 |
| Yes | 204430393 | BRYANT | 280ANV036*0**A* | CAP**4824AL*+UI | 88*TA60090C21*** | 32,400 | $3,888 |
| Yes | 204430357 | BRYANT | 280ANV036*0**A* | CAP**4821AL*+UI | 88*TA60090C21*** | 32,400 | $3,888 |
| Yes | 204430407 | BRYANT | 280ANV036*0**A* | CAP**4824AL*+UI | 987MB66120C24*** | 32,600 | $3,912 |
| Yes | 204430457 | BRYANT | 280ANV036*0**A* | CAP**6121AL*+UI | 88*TA60070C21*** | 32,400 | $3,888 |
| Yes | 204430488 | BRYANT | 280ANV036*0**A* | CAP**6124AL*+UI | 88*TA60070C21*** | 32,400 | $3,888 |
| Yes | 204430379 | BRYANT | 280ANV036*0**A* | CAP**4821AL*+UI | 986TC66100C21*** | 32,600 | $3,912 |
| Yes | 204430384 | BRYANT | 280ANV036*0**A* | CAP**4821AL*+UI | 88*TA60110C21*** | 32,400 | $3,888 |
| Yes | 204430410 | BRYANT | 280ANV036*0**A* | CAP**4824AL*+UI | 986TC60080C21*** | 32,600 | $3,912 |
| Yes | 204431285 | BRYANT | 280ANV036*0**A* | CSPH*4812AL*+UI | 986TC66100C21*** | 32,600 | $3,912 |
| Yes | 204430455 | BRYANT | 280ANV036*0**A* | CAP**6121AL*+UI | 88*TA48070C17*** | 32,600 | $3,912 |
| Yes | 204431728 | BRYANT | 280ANV060*0**A* | CNPV*6024AL*+UI | 987MB60080C21*** | 54,500 | $6,540 |
| Yes | 204431650 | BRYANT | 280ANV060*0**A* | CAP**6024AL*+UI | 987MB66120C24*** | 53,500 | $6,420 |
| Yes | 204430146 | BRYANT | 280ANV036*0**A* | CAP**3621AL*+UI | 987MB42060C17*** | 31,000 | $3,720 |
| Yes | 204431765 | BRYANT | 280ANV060*0**A* | CSPH*6012AL*+UI | 987MB66120C24*** | 55,500 | $6,660 |
| Yes | 204431630 | BRYANT | 280ANV060*0**A* | CAP**6024AL*+UI | 88*TA60070C21*** | 54,000 | $6,480 |
| Yes | 204431758 | BRYANT | 280ANV060*0**A* | CSPH*6012AL*+UI | 987MB60080C21*** | 55,500 | $6,660 |
| Yes | 204431745 | BRYANT | 280ANV060*0**A* | CSPH*6012AL*+UI | 88*TA60070C21*** | 55,500 | $6,660 |
| Yes | 204431662 | BRYANT | 280ANV060*0**A* | CAP**6121AL*+UI | 88*TA60070C21*** | 54,000 | $6,480 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204431669 | BRYANT | 280ANV060*0**A* | CAP**6121AL*+UI | 987MB60080C21*** | 55,500 | $6,660 |
| Yes | 204431767 | BRYANT | 280ANV060*0**A* | CSPH*6012AL*+UI | 986TC60080C21*** | 55,500 | $6,660 |
| Yes | 204431725 | BRYANT | 280ANV060*0**A* | CNPV*6024AL*+UI | 986TC66120C24*** | 56,000 | $6,720 |
| Yes | 204431639 | BRYANT | 280ANV060*0**A* | CAP**6024AL*+UI | 986TC66120C24*** | 53,500 | $6,420 |
| Yes | 204431652 | BRYANT | 280ANV060*0**A* | CAP**6024AL*+UI | 986TC60080C21*** | 54,000 | $6,480 |
| Yes | 204431675 | BRYANT | 280ANV060*0**A* | CAP**6121AL*+UI | 986TC60080C21*** | 55,500 | $6,660 |
| Yes | 204431646 | BRYANT | 280ANV060*0**A* | CAP**6024AL*+UI | 987MB66100C21*** | 53,500 | $6,420 |
| Yes | 204431642 | BRYANT | 280ANV060*0**A* | CAP**6024AL*+UI | 987MB60080C21*** | 54,000 | $6,480 |
| Yes | 204430154 | BRYANT | 280ANV036*0**A* | CNPV*3617AL*+UI | 987MB42060C17*** | 31,400 | $3,768 |
| Yes | 204430518 | BRYANT | 280ANV036*0**A* | CNPV*3617AL*+UI | 986TC42060C17*** | 32,800 | $3,936 |
| Yes | 204431761 | BRYANT | 280ANV060*0**A* | CSPH*6012AL*+UI | 987MB66100C21*** | 55,000 | $6,600 |
| Yes | 204430179 | BRYANT | 280ANV036*0**A* | CAP**3617AL*+UI | 986TC42060C17*** | 33,000 | $3,960 |
| Yes | 204431137 | BRYANT | 280ANV036*0**A* | CSPH*4212AL*+UI | 987MB42060C17*** | 33,400 | $4,008 |
| Yes | 204431260 | BRYANT | 280ANV036*0**A* | CSPH*4812AL*+UI | 987MB42060C17*** | 33,400 | $4,008 |
| Yes | 204430998 | BRYANT | 280ANV036*0**A* | CSPH*3612AL*+UI | 987MB42060C17*** | 33,600 | $4,032 |
| Yes | 204431734 | BRYANT | 280ANV060*0**A* | CNPV*6024AL*+UI | 987MB66120C24*** | 54,500 | $6,540 |
| Yes | 204430161 | BRYANT | 280ANV036*0**A* | CNPV*3621AL*+UI | 987MB42060C17*** | 31,200 | $3,744 |
| Yes | 204430194 | BRYANT | 280ANV036*0**A* | CAP**3621AL*+UI | 88*TA36045C17*** | 32,800 | $3,936 |
| Yes | 204431716 | BRYANT | 280ANV060*0**A* | CNPV*6024AL*+UI | 88*TA60070C21*** | 56,000 | $6,720 |
| Yes | 204431633 | BRYANT | 280ANV060*0**A* | CAP**6024AL*+UI | 88*TA60090C21*** | 53,500 | $6,420 |
| Yes | 204430173 | BRYANT | 280ANV036*0**A* | CAP**3617AL*+UI | 88*TA36045C17*** | 33,000 | $3,960 |
| Yes | 204431736 | BRYANT | 280ANV060*0**A* | CNPV*6024AL*+UI | 986TC60080C21*** | 54,500 | $6,540 |
| Yes | 204430943 | BRYANT | 280ANV036*0**A* | CSPH*3612AL*+UI | 88*TA36045C17*** | 33,600 | $4,032 |
| Yes | 204431656 | BRYANT | 280ANV060*0**A* | CAP**6024AL*+UI | 986TC66100C21*** | 53,500 | $6,420 |
| Yes | 204431687 | BRYANT | 280ANV060*0**A* | CAP**6124AL*+UI | 88*TA60090C21*** | 55,000 | $6,600 |
| Yes | 204431659 | BRYANT | 280ANV060*0**A* | CAP**6024AL*+UI | 88*TA60110C21*** | 53,500 | $6,420 |
| Yes | 204431719 | BRYANT | 280ANV060*0**A* | CNPV*6024AL*+UI | 88*TA60090C21*** | 56,000 | $6,720 |
| Yes | 204431740 | BRYANT | 280ANV060*0**A* | CNPV*6024AL*+UI | 986TC66100C21*** | 56,000 | $6,720 |
| Yes | 204431743 | BRYANT | 280ANV060*0**A* | CNPV*6024AL*+UI | 88*TA60110C21*** | 56,000 | $6,720 |
| Yes | 204431088 | BRYANT | 280ANV036*0**A* | CSPH*4212AL*+UI | 88*TA36045C17*** | 33,400 | $4,008 |
| Yes | 204430264 | BRYANT | 280ANV036*0**A* | CAP**4221AL*+UI | 88*TA36045C17*** | 33,200 | $3,984 |
| Yes | 204431701 | BRYANT | 280ANV060*0**A* | CAP**6124AL*+UI | 987MB66100C21*** | 55,000 | $6,600 |
| Yes | 204431691 | BRYANT | 280ANV060*0**A* | CAP**6124AL*+UI | 88*TA66135C24*** | 55,000 | $6,600 |
| Yes | 204431713 | BRYANT | 280ANV060*0**A* | CAP**6124AL*+UI | 88*TA60110C21*** | 55,000 | $6,600 |
| Yes | 204431666 | BRYANT | 280ANV060*0**A* | CAP**6121AL*+UI | 88*TA60090C21*** | 55,000 | $6,600 |
| Yes | 204431694 | BRYANT | 280ANV060*0**A* | CAP**6124AL*+UI | 986TC66120C24*** | 55,000 | $6,600 |
| Yes | 204431678 | BRYANT | 280ANV060*0**A* | CAP**6121AL*+UI | 986TC66100C21*** | 55,000 | $6,600 |
| Yes | 204431710 | BRYANT | 280ANV060*0**A* | CAP**6124AL*+UI | 986TC66100C21*** | 55,000 | $6,600 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204431681 | BRYANT | 280ANV060*0**A* | CAP**6121AL*+UI | 88*TA60110C21*** | 55,000 | $6,600 |
| Yes | 204431671 | BRYANT | 280ANV060*0**A* | CAP**6121AL*+UI | 987MB66100C21*** | 55,000 | $6,600 |
| Yes | 204431697 | BRYANT | 280ANV060*0**A* | CAP**6124AL*+UI | 987MB60080C21*** | 54,000 | $6,480 |
| Yes | 204431704 | BRYANT | 280ANV060*0**A* | CAP**6124AL*+UI | 987MB66120C24*** | 55,000 | $6,600 |
| Yes | 204431708 | BRYANT | 280ANV060*0**A* | CAP**6124AL*+UI | 986TC60080C21*** | 54,000 | $6,480 |
| Yes | 204431684 | BRYANT | 280ANV060*0**A* | CAP**6124AL*+UI | 88*TA60070C21*** | 54,000 | $6,480 |
| Yes | 204431381 | BRYANT | 280ANV048*0**A* | CAP**4821AL*+UI | 88*TA60110C21*** | 50,500 | $6,060 |
| Yes | 204431401 | BRYANT | 280ANV048*0**A* | CAP**4824AL*+UI | 987MB66120C24*** | 50,500 | $6,060 |
| Yes | 204431749 | BRYANT | 280ANV060*0**A* | CSPH*6012AL*+UI | 88*TA60090C21*** | 55,000 | $6,600 |
| Yes | 204431771 | BRYANT | 280ANV060*0**A* | CSPH*6012AL*+UI | 986TC66100C21*** | 55,000 | $6,600 |
| Yes | 204431378 | BRYANT | 280ANV048*0**A* | CAP**4821AL*+UI | 88*TA48090C17*** | 50,500 | $6,060 |
| Yes | 204431774 | BRYANT | 280ANV060*0**A* | CSPH*6012AL*+UI | 88*TA60110C21*** | 55,000 | $6,600 |
| Yes | 204430185 | BRYANT | 280ANV036*0**A* | CAP**3617AL*+UI | 987MB42060C17*** | 33,000 | $3,960 |
| Yes | 204431374 | BRYANT | 280ANV048*0**A* | CAP**4821AL*+UI | 986TC60080C21*** | 49,500 | $5,940 |
| Yes | 204431472 | BRYANT | 280ANV048*0**A* | CAP**6024AL*+UI | 88*TA60110C21*** | 48,500 | $5,820 |
| Yes | 204431411 | BRYANT | 280ANV048*0**A* | CAP**4824AL*+UI | 986TC60080C21*** | 50,500 | $6,060 |
| Yes | 204430633 | BRYANT | 280ANV036*0**A* | CNPV*4221AL*+UI | 987MB42060C17*** | 33,400 | $4,008 |
| Yes | 204430279 | BRYANT | 280ANV036*0**A* | CAP**4221AL*+UI | 987MB42060C17*** | 33,200 | $3,984 |
| Yes | 204431637 | BRYANT | 280ANV060*0**A* | CAP**6024AL*+UI | 88*TA66135C24*** | 53,500 | $6,420 |
| Yes | 204430188 | BRYANT | 280ANV036*0**A* | CAP**3617AL*+UI | 987MB42080C17*** | 32,800 | $3,936 |
| Yes | 204431526 | BRYANT | 280ANV048*0**A* | CAP**6124AL*+UI | 986TC66100C21*** | 48,500 | $5,820 |
| Yes | 204431228 | BRYANT | 280ANV036*0**A* | CSPH*4812AL*+UI | 88*TA60090C21*** | 32,600 | $3,912 |
| Yes | 204431296 | BRYANT | 280ANV036*0**A* | CSPH*4812AL*+UI | 88*TA60110C21*** | 32,600 | $3,912 |
| Yes | 204430748 | BRYANT | 280ANV036*0**A* | CNPV*4821AL*+UI | 986TC66100C21*** | 32,600 | $3,912 |
| Yes | 204431111 | BRYANT | 280ANV036*0**A* | CSPH*4212AL*+UI | 88*TA60090C21*** | 32,600 | $3,912 |
| Yes | 204430809 | BRYANT | 280ANV036*0**A* | CNPV*4824AL*+UI | 986TC66100C21*** | 32,600 | $3,912 |
| Yes | 204430751 | BRYANT | 280ANV036*0**A* | CNPV*4821AL*+UI | 88*TA48090C17*** | 32,600 | $3,912 |
| Yes | 204430834 | BRYANT | 280ANV036*0**A* | CNPV*6024AL*+UI | 88*TA60070C21*** | 32,600 | $3,912 |
| Yes | 204431198 | BRYANT | 280ANV036*0**A* | CSPH*4212AL*+UI | 88*TA60110C21*** | 32,600 | $3,912 |
| Yes | 204430742 | BRYANT | 280ANV036*0**A* | CNPV*4821AL*+UI | 986TC60080C21*** | 32,800 | $3,936 |
| Yes | 204430704 | BRYANT | 280ANV036*0**A* | CNPV*4821AL*+UI | 88*TA48070C17*** | 33,000 | $3,960 |
| Yes | 204430798 | BRYANT | 280ANV036*0**A* | CNPV*4824AL*+UI | 987MB66120C24*** | 32,800 | $3,936 |
| Yes | 204430594 | BRYANT | 280ANV036*0**A* | CNPV*4217AL*+UI | 88*TA48090C17*** | 33,000 | $3,960 |
| Yes | 204430216 | BRYANT | 280ANV036*0**A* | CAP**3621AL*+UI | 987MB66100C21*** | 32,200 | $3,864 |
| Yes | 204430803 | BRYANT | 280ANV036*0**A* | CNPV*4824AL*+UI | 986TC60080C21*** | 32,800 | $3,936 |
| Yes | 204430931 | BRYANT | 280ANV036*0**A* | CNPV*6024AL*+UI | 987MB60060C21*** | 32,800 | $3,936 |
| Yes | 204430996 | BRYANT | 280ANV036*0**A* | CSPH*3612AL*+UI | 986TC66120C24*** | 32,800 | $3,936 |
| Yes | 204430977 | BRYANT | 280ANV036*0**A* | CSPH*3612AL*+UI | 88*TA66135C24*** | 32,800 | $3,936 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204431007 | BRYANT | 280ANV036*0**A* | CSPH*3612AL*+UI | 987MB66100C21*** | 32,800 | $3,936 |
| Yes | 204430661 | BRYANT | 280ANV036*0**A* | CNPV*4221AL*+UI | 987MB66100C21*** | 32,600 | $3,912 |
| Yes | 204430649 | BRYANT | 280ANV036*0**A* | CNPV*4221AL*+UI | 987MB60080C21*** | 32,600 | $3,912 |
| Yes | 204431360 | BRYANT | 280ANV036*0**A* | CSPH*6012AL*+UI | 987MB60060C21*** | 32,600 | $3,912 |
| Yes | 204431256 | BRYANT | 280ANV036*0**A* | CSPH*4812AL*+UI | 986TC66120C24*** | 32,600 | $3,912 |
| Yes | 204430449 | BRYANT | 280ANV036*0**A* | CAP**6024AL*+UI | 987MB60060C21*** | 32,600 | $3,912 |
| Yes | 204430738 | BRYANT | 280ANV036*0**A* | CNPV*4821AL*+UI | 987MB66100C21*** | 32,600 | $3,912 |
| Yes | 204431271 | BRYANT | 280ANV036*0**A* | CSPH*4812AL*+UI | 987MB66100C21*** | 32,600 | $3,912 |
| Yes | 204431351 | BRYANT | 280ANV036*0**A* | CSPH*6012AL*+UI | 88*TA36070C14*** | 32,600 | $3,912 |
| Yes | 204431119 | BRYANT | 280ANV036*0**A* | CSPH*4212AL*+UI | 88*TA66135C24*** | 32,600 | $3,912 |
| Yes | 204431220 | BRYANT | 280ANV036*0**A* | CSPH*4812AL*+UI | 88*TA60070C21*** | 32,800 | $3,936 |
| Yes | 204431268 | BRYANT | 280ANV036*0**A* | CSPH*4812AL*+UI | 987MB60080C21*** | 32,800 | $3,936 |
| Yes | 204430787 | BRYANT | 280ANV036*0**A* | CNPV*4824AL*+UI | 987MB60080C21*** | 32,800 | $3,936 |
| Yes | 204431151 | BRYANT | 280ANV036*0**A* | CSPH*4212AL*+UI | 987MB60080C21*** | 32,800 | $3,936 |
| Yes | 204430735 | BRYANT | 280ANV036*0**A* | CNPV*4821AL*+UI | 987MB60080C21*** | 32,800 | $3,936 |
| Yes | 204430791 | BRYANT | 280ANV036*0**A* | CNPV*4824AL*+UI | 987MB66100C21*** | 32,600 | $3,912 |
| Yes | 204431133 | BRYANT | 280ANV036*0**A* | CSPH*4212AL*+UI | 986TC66120C24*** | 32,600 | $3,912 |
| Yes | 204431107 | BRYANT | 280ANV036*0**A* | CSPH*4212AL*+UI | 88*TA60070C21*** | 32,800 | $3,936 |
| Yes | 204431158 | BRYANT | 280ANV036*0**A* | CSPH*4212AL*+UI | 987MB66100C21*** | 32,800 | $3,936 |
| Yes | 204430707 | BRYANT | 280ANV036*0**A* | CNPV*4821AL*+UI | 88*TA60070C21*** | 32,800 | $3,936 |
| Yes | 204430769 | BRYANT | 280ANV036*0**A* | CNPV*4824AL*+UI | 88*TA60070C21*** | 32,800 | $3,936 |
| Yes | 204430316 | BRYANT | 280ANV036*0**A* | CAP**4224AL*+UI | 987MB66100C21*** | 32,400 | $3,888 |
| Yes | 204430759 | BRYANT | 280ANV036*0**A* | CNPV*4821AL*+UI | 987MB60060C21*** | 33,000 | $3,960 |
| Yes | 204430828 | BRYANT | 280ANV036*0**A* | CNPV*4824AL*+UI | 987MB60060C21*** | 33,000 | $3,960 |
| Yes | 204430307 | BRYANT | 280ANV036*0**A* | CAP**4224AL*+UI | 88*TA66135C24*** | 32,400 | $3,888 |
| Yes | 204430399 | BRYANT | 280ANV036*0**A* | CAP**4824AL*+UI | 986TC66120C24*** | 32,400 | $3,888 |
| Yes | 204430310 | BRYANT | 280ANV036*0**A* | CAP**4224AL*+UI | 986TC66120C24*** | 32,400 | $3,888 |
| Yes | 204430285 | BRYANT | 280ANV036*0**A* | CAP**4221AL*+UI | 987MB66100C21*** | 32,600 | $3,912 |
| Yes | 204430313 | BRYANT | 280ANV036*0**A* | CAP**4224AL*+UI | 987MB60080C21*** | 32,600 | $3,912 |
| Yes | 204431308 | BRYANT | 280ANV036*0**A* | CSPH*6012AL*+UI | 88*TA60070C21*** | 32,400 | $3,888 |
| Yes | 204431756 | BRYANT | 280ANV060*0**A* | CSPH*6012AL*+UI | 986TC66120C24*** | 55,000 | $6,600 |
| Yes | 204430282 | BRYANT | 280ANV036*0**A* | CAP**4221AL*+UI | 987MB60080C21*** | 32,600 | $3,912 |
| Yes | 204430421 | BRYANT | 280ANV036*0**A* | CAP**6024AL*+UI | 88*TA60070C21*** | 32,200 | $3,864 |
| Yes | 204430432 | BRYANT | 280ANV036*0**A* | CAP**6024AL*+UI | 987MB60080C21*** | 32,200 | $3,864 |
| Yes | 204430435 | BRYANT | 280ANV036*0**A* | CAP**6024AL*+UI | 987MB66100C21*** | 32,200 | $3,864 |
| Yes | 204430405 | BRYANT | 280ANV036*0**A* | CAP**4824AL*+UI | 987MB66100C21*** | 32,400 | $3,888 |
| Yes | 204431331 | BRYANT | 280ANV036*0**A* | CSPH*6012AL*+UI | 987MB60080C21*** | 32,400 | $3,888 |
| Yes | 204430373 | BRYANT | 280ANV036*0**A* | CAP**4821AL*+UI | 987MB66100C21*** | 32,600 | $3,912 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204430371 | BRYANT | 280ANV036*0**A* | CAP**4821AL*+UI | 987MB60080C21*** | 32,600 | $3,912 |
| Yes | 204430402 | BRYANT | 280ANV036*0**A* | CAP**4824AL*+UI | 987MB60080C21*** | 32,600 | $3,912 |
| Yes | 204430501 | BRYANT | 280ANV036*0**A* | CAP**6124AL*+UI | 987MB66100C21*** | 32,200 | $3,864 |
| Yes | 204431312 | BRYANT | 280ANV036*0**A* | CSPH*6012AL*+UI | 88*TA60090C21*** | 32,200 | $3,864 |
| Yes | 204430693 | BRYANT | 280ANV036*0**A* | CNPV*4221AL*+UI | 88*TA60110C21*** | 32,600 | $3,912 |
| Yes | 204430491 | BRYANT | 280ANV036*0**A* | CAP**6124AL*+UI | 986TC66120C24*** | 32,200 | $3,864 |
| Yes | 204430246 | BRYANT | 280ANV036*0**A* | CAP**3721AL*+UI | 88*TA60090C21*** | 32,600 | $3,912 |
| Yes | 204430343 | BRYANT | 280ANV036*0**A* | CAP**4321AL*+UI | 987MB60080C21*** | 32,800 | $3,936 |
| Yes | 204430610 | BRYANT | 280ANV036*0**A* | CNPV*4221AL*+UI | 88*TA60090C21*** | 32,600 | $3,912 |
| Yes | 204429894 | BRYANT | 280ANV024*0**A* | CAP**3617AL*+UI | 987MB42080C17*** | 21,600 | $2,592 |
| Yes | 204430510 | BRYANT | 280ANV036*0**A* | CAP**6124AL*+UI | 986TC66100C21*** | 32,200 | $3,864 |
| Yes | 204430912 | BRYANT | 280ANV036*0**A* | CNPV*6024AL*+UI | 986TC66100C21*** | 32,400 | $3,888 |
| Yes | 204430460 | BRYANT | 280ANV036*0**A* | CAP**6121AL*+UI | 88*TA60090C21*** | 32,200 | $3,864 |
| Yes | 204430924 | BRYANT | 280ANV036*0**A* | CNPV*6024AL*+UI | 88*TA60110C21*** | 32,400 | $3,888 |
| Yes | 204430424 | BRYANT | 280ANV036*0**A* | CAP**6024AL*+UI | 88*TA60090C21*** | 32,000 | $3,840 |
| Yes | 204430896 | BRYANT | 280ANV036*0**A* | CNPV*6024AL*+UI | 987MB66120C24*** | 32,400 | $3,888 |
| Yes | 204430856 | BRYANT | 280ANV036*0**A* | CNPV*6024AL*+UI | 88*TA66135C24*** | 32,200 | $3,864 |
| Yes | 204430844 | BRYANT | 280ANV036*0**A* | CNPV*6024AL*+UI | 88*TA60090C21*** | 32,400 | $3,888 |
| Yes | 204430905 | BRYANT | 280ANV036*0**A* | CNPV*6024AL*+UI | 986TC60080C21*** | 32,400 | $3,888 |
| Yes | 204430095 | BRYANT | 280ANV024*0**A* | CSPH*3012AL*+UI | 88*TA60070C21*** | 23,000 | $2,760 |
| Yes | 204430754 | BRYANT | 280ANV036*0**A* | CNPV*4821AL*+UI | 88*TA60110C21*** | 32,600 | $3,912 |
| Yes | 204430714 | BRYANT | 280ANV036*0**A* | CNPV*4821AL*+UI | 88*TA60090C21*** | 32,600 | $3,912 |
| Yes | 204431236 | BRYANT | 280ANV036*0**A* | CSPH*4812AL*+UI | 88*TA66135C24*** | 32,600 | $3,912 |
| Yes | 204430774 | BRYANT | 280ANV036*0**A* | CNPV*4824AL*+UI | 88*TA60090C21*** | 32,600 | $3,912 |
| Yes | 204430818 | BRYANT | 280ANV036*0**A* | CNPV*4824AL*+UI | 88*TA60110C21*** | 32,600 | $3,912 |
| Yes | 204430892 | BRYANT | 280ANV036*0**A* | CNPV*6024AL*+UI | 987MB66100C21*** | 32,400 | $3,888 |
| Yes | 204430884 | BRYANT | 280ANV036*0**A* | CNPV*6024AL*+UI | 987MB60080C21*** | 32,400 | $3,888 |
| Yes | 204430874 | BRYANT | 280ANV036*0**A* | CNPV*6024AL*+UI | 986TC66120C24*** | 32,400 | $3,888 |
| Yes | 204430778 | BRYANT | 280ANV036*0**A* | CNPV*4824AL*+UI | 88*TA66135C24*** | 32,600 | $3,912 |
| Yes | 204431334 | BRYANT | 280ANV036*0**A* | CSPH*6012AL*+UI | 987MB66100C21*** | 32,200 | $3,864 |
| Yes | 204430781 | BRYANT | 280ANV036*0**A* | CNPV*4824AL*+UI | 986TC66120C24*** | 32,600 | $3,912 |
| Yes | 204430430 | BRYANT | 280ANV036*0**A* | CAP**6024AL*+UI | 986TC66120C24*** | 32,200 | $3,864 |
| Yes | 204431315 | BRYANT | 280ANV036*0**A* | CSPH*6012AL*+UI | 88*TA66135C24*** | 32,200 | $3,864 |
| Yes | 204431323 | BRYANT | 280ANV036*0**A* | CSPH*6012AL*+UI | 986TC66120C24*** | 32,200 | $3,864 |
| Yes | 204430427 | BRYANT | 280ANV036*0**A* | CAP**6024AL*+UI | 88*TA66135C24*** | 32,000 | $3,840 |
| Yes | 204430050 | BRYANT | 280ANV024*0**A* | CNPV*3621AL*+UI | 986TC42080C17*** | 21,400 | $2,568 |
| Yes | 204429916 | BRYANT | 280ANV024*0**A* | CAP**3621AL*+UI | 88*TA60070C21*** | 21,600 | $2,592 |
| Yes | 204429925 | BRYANT | 280ANV024*0**A* | CAP**3621AL*+UI | 986TC42060C17*** | 21,600 | $2,592 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204430396 | BRYANT | 280ANV036*0**A* | CAP**4824AL*+UI | 88*TA66135C24*** | 32,400 | $3,888 |
| Yes | 204429968 | BRYANT | 280ANV024*0**A* | CAP**4221AL*+UI | 88*TA60070C21*** | 22,200 | $2,664 |
| Yes | 204430025 | BRYANT | 280ANV024*0**A* | CNPV*3014AL*+UI | 88*TA36070C14*** | 21,400 | $2,568 |
| Yes | 204430097 | BRYANT | 280ANV024*0**A* | CSPH*3012AL*+UI | 88*TA60090C21*** | 23,000 | $2,760 |
| Yes | 204429878 | BRYANT | 280ANV024*0**A* | CAP**3617AL*+UI | 986TC42060C17*** | 21,600 | $2,592 |
| Yes | 204430075 | BRYANT | 280ANV024*0**A* | CNPV*4221AL*+UI | 987MB60060C21*** | 22,400 | $2,688 |
| Yes | 204430120 | BRYANT | 280ANV024*0**A* | CSPH*3012AL*+UI | 986TC66100C21*** | 23,000 | $2,760 |
| Yes | 204430112 | BRYANT | 280ANV024*0**A* | CSPH*3012AL*+UI | 987MB66100C21*** | 23,000 | $2,760 |
| Yes | 204430073 | BRYANT | 280ANV024*0**A* | CNPV*4221AL*+UI | 88*TA48090C17*** | 22,200 | $2,664 |
| Yes | 204430056 | BRYANT | 280ANV024*0**A* | CNPV*3621AL*+UI | 987MB66100C21*** | 24,200 | $2,904 |
| Yes | 204430103 | BRYANT | 280ANV024*0**A* | CSPH*3012AL*+UI | 986TC66120C24*** | 23,000 | $2,760 |
| Yes | 204430020 | BRYANT | 280ANV024*0**A* | CAP**4224AL*+UI | 986TC60080C21*** | 22,200 | $2,664 |
| Yes | 204429902 | BRYANT | 280ANV024*0**A* | CAP**3617AL*+UI | 88*TA48090C17*** | 21,600 | $2,592 |
| Yes | 204430065 | BRYANT | 280ANV024*0**A* | CNPV*4221AL*+UI | 986TC42080C17*** | 22,400 | $2,688 |
| Yes | 204430000 | BRYANT | 280ANV024*0**A* | CAP**4221AL*+UI | 88*TA60110C21*** | 22,000 | $2,640 |
| Yes | 204430008 | BRYANT | 280ANV024*0**A* | CAP**4224AL*+UI | 88*TA60090C21*** | 22,000 | $2,640 |
| Yes | 9893608 | BRYANT | 280ANV036000 | FE4AN(B,F)003L+UI | | 30,200 | $3,624 |
| Yes | 9893607 | BRYANT | 280ANV036000 | FE4ANF002L+UI | | 30,600 | $3,672 |
| Yes | 9893411 | BRYANT | 280ANV024*0**A* | FE4ANB006L+UI | | 24,800 | $2,976 |
| Yes | 9893462 | BRYANT | 280ANV024000 | FE4ANF002L+UI | | 25,200 | $3,024 |
| Yes | 9893463 | BRYANT | 280ANV024000 | FE4AN(B,F)003+UI | | 25,000 | $3,000 |
| Yes | 9893473 | BRYANT | 280ANV024*0**A* | CAP**3617AL*+UI & 98(6*B,7*A)42060V17*** | | 25,200 | $3,024 |
| Yes | 9893474 | BRYANT | 280ANV024*0**A* | CAP**3617AL*+UI & 98(6*B,7*A)42080V17*** | | 25,200 | $3,024 |
| Yes | 9893475 | BRYANT | 280ANV024*0**A* | CAP**3621AL*+UI & 98(6*B,7*A)42060V17*** | | 25,200 | $3,024 |
| Yes | 9893476 | BRYANT | 280ANV024*0**A* | CAP**3621AL*+UI & 98(6*B,7*A)42080V17*** | | 25,200 | $3,024 |
| Yes | 9893477 | BRYANT | 280ANV024*0**A* | CAP**4221AL*+UI & 98(6*B,7*A)42060V17*** | | 25,200 | $3,024 |
| Yes | 9893478 | BRYANT | 280ANV024*0**A* | CAP**4221AL*+UI & 98(6*B,7*A)42080V17*** | | 25,200 | $3,024 |
| Yes | 9893479 | BRYANT | 280ANV024*0**A* | CAP**4224AL*+UI & 98(6*B,7*A)66120V24*** | | 25,000 | $3,000 |
| Yes | 9893482 | BRYANT | 280ANV024*0**A* | CAP**4821AL*+UI & 98(6*B,7*A)42060V17*** | | 25,000 | $3,000 |
| Yes | 9893483 | BRYANT | 280ANV024*0**A* | CAP**4821AL*+UI & 98(6*B,7*A)42080V17*** | | 24,800 | $2,976 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 9893484 | BRYANT | 280ANV024*0**A* | CAP**4824AL*+UI & 98(6*B,7*A)66120V24*** | | 24,800 | $2,976 |
| Yes | 9893485 | BRYANT | 280ANV024*0**A* | CAP**6021AL*+UI & 98(6*B,7*A)42060V17*** | | 24,600 | $2,952 |
| Yes | 9893486 | BRYANT | 280ANV024*0**A* | CAP**6021AL*+UI & 98(6*B,7*A)42080V17*** | | 24,600 | $2,952 |
| Yes | 9893487 | BRYANT | 280ANV024*0**A* | CAP**6024AL*+UI & 98(6*B,7*A)66120V24*** | | 24,400 | $2,928 |
| Yes | 9893488 | BRYANT | 280ANV024*0**A* | CNPV*3617AL*+UI & 98(6*B,7*A)42060V17*** | | 25,400 | $3,048 |
| Yes | 9893489 | BRYANT | 280ANV024*0**A* | CNPV*3617AL*+UI & 98(6*B,7*A)42080V17*** | | 25,200 | $3,024 |
| Yes | 9893490 | BRYANT | 280ANV024*0**A* | CNPV*3621AL*+UI & 98(6*B,7*A)42060V17*** | | 25,400 | $3,048 |
| Yes | 9893491 | BRYANT | 280ANV024*0**A* | CNPV*3621AL*+UI & 98(6*B,7*A)42080V17*** | | 25,200 | $3,024 |
| Yes | 9893492 | BRYANT | 280ANV024*0**A* | CNPV*4217AL*+UI & 98(6*B,7*A)42060V17*** | | 25,200 | $3,024 |
| Yes | 9893493 | BRYANT | 280ANV024*0**A* | CNPV*4217AL*+UI & 98(6*B,7*A)42080V17*** | | 25,200 | $3,024 |
| Yes | 9893494 | BRYANT | 280ANV024*0**A* | CNPV*4221AL*+UI & 98(6*B,7*A)42060V17*** | | 25,200 | $3,024 |
| Yes | 9893495 | BRYANT | 280ANV024*0**A* | CNPV*4221AL*+UI & 98(6*B,7*A)42080V17*** | | 25,200 | $3,024 |
| Yes | 9893497 | BRYANT | 280ANV024*0**A* | CNPV*4821AL*+UI & 98(6*B,7*A)42080V17*** | | 25,000 | $3,000 |
| Yes | 9893498 | BRYANT | 280ANV024*0**A* | CNPV*4824AL*+UI & 98(6*B,7*A)66120V24*** | | 25,000 | $3,000 |
| Yes | 9893496 | BRYANT | 280ANV024*0**A* | CNPV*4821AL*+UI & 98(6*B,7*A)42060V17*** | | 25,000 | $3,000 |
| Yes | 9893499 | BRYANT | 280ANV024*0**A* | CNPV*6024AL*+UI & 98(6*B,7*A)66120V24*** | | 25,000 | $3,000 |
| Yes | 9893500 | BRYANT | 280ANV024*0**A* | CSPH*3612AL*+UI & 98(6*B,7*A)42060V17*** | | 25,200 | $3,024 |
| Yes | 9893501 | BRYANT | 280ANV024*0**A* | CSPH*3612AL*+UI & 98(6*B,7*A)42080V17*** | | 25,200 | $3,024 |
| Yes | 9893502 | BRYANT | 280ANV024*0**A* | CSPH*3612AL*+UI & 98(6*B,7*A)66120V24*** | | 25,000 | $3,000 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 9893503 | BRYANT | 280ANV024*0**A* | CSPH*4212AL*+UI & 98(6*B,7*A)42060V17*** | | 25,200 | $3,024 |
| Yes | 9893505 | BRYANT | 280ANV024*0**A* | CSPH*4212AL*+UI & 98(6*B,7*A)66120V24*** | | 25,000 | $3,000 |
| Yes | 9893504 | BRYANT | 280ANV024*0**A* | CSPH*4212AL*+UI & 98(6*B,7*A)42080V17*** | | 25,000 | $3,000 |
| Yes | 9893506 | BRYANT | 280ANV024*0**A* | CSPH*4812AL*+UI & 98(6*B,7*A)42060V17*** | | 25,000 | $3,000 |
| Yes | 9893507 | BRYANT | 280ANV024*0**A* | CSPH*4812AL*+UI & 98(6*B,7*A)42080V17*** | | 25,000 | $3,000 |
| Yes | 9893508 | BRYANT | 280ANV024*0**A* | CSPH*4812AL*+UI & 98(6*B,7*A)66120V24*** | | 25,000 | $3,000 |
| Yes | 9893509 | BRYANT | 280ANV024*0**A* | CSPH*6012AL*+UI & 98(6*B,7*A)42060V17*** | | 25,000 | $3,000 |
| Yes | 9893510 | BRYANT | 280ANV024*0**A* | CSPH*6012AL*+UI & 98(6*B,7*A)42080V17*** | | 25,000 | $3,000 |
| Yes | 9893511 | BRYANT | 280ANV024*0**A* | CSPH*6012AL*+UI & 98(6*B,7*A)66120V24*** | | 25,000 | $3,000 |
| Yes | 9893512 | BRYANT | 280ANV024*0**A* | CAP**3621AL*+UI & 98(6*B,7MA)60060V21*** | | 25,200 | $3,024 |
| Yes | 9893513 | BRYANT | 280ANV024*0**A* | CAP**3621AL*+UI & 98(6*B,7*A)60080V21*** | | 25,000 | $3,000 |
| Yes | 9893514 | BRYANT | 280ANV024*0**A* | CAP**3621AL*+UI & 98(6*B,7*A)66100V21*** | | 25,000 | $3,000 |
| Yes | 9893516 | BRYANT | 280ANV024*0**A* | CAP**4221AL*+UI & 98(6*B,7*A)60080V21*** | | 25,000 | $3,000 |
| Yes | 9893517 | BRYANT | 280ANV024*0**A* | CAP**4221AL*+UI & 98(6*B,7*A)66100V21*** | | 25,000 | $3,000 |
| Yes | 9893521 | BRYANT | 280ANV024*0**A* | CAP**4821AL*+UI & 98(6*B,7MA)60060V21*** | | 24,800 | $2,976 |
| Yes | 9893519 | BRYANT | 280ANV024*0**A* | CAP**4224AL*+UI & 98(6*B,7*A)60080V21*** | | 25,000 | $3,000 |
| Yes | 9893520 | BRYANT | 280ANV024*0**A* | CAP**4224AL*+UI & 98(6*B,7*A)66100V21*** | | 25,000 | $3,000 |
| Yes | 9893522 | BRYANT | 280ANV024*0**A* | CAP**4821AL*+UI & 98(6*B,7*A)60080V21*** | | 24,800 | $2,976 |
| Yes | 9893523 | BRYANT | 280ANV024*0**A* | CAP**4821AL*+UI & 98(6*B,7*A)66100V21*** | | 24,800 | $2,976 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 9893524 | BRYANT | 280ANV024*0**A* | CAP**4824AL*+UI & 98(6*B,7MA)60060V21*** | | 24,800 | $2,976 |
| Yes | 9893525 | BRYANT | 280ANV024*0**A* | CAP**4824AL*+UI & 98(6*B,7*A)60080V21*** | | 24,800 | $2,976 |
| Yes | 9893526 | BRYANT | 280ANV024*0**A* | CAP**4824AL*+UI & 98(6*B,7*A)66100V21*** | | 24,800 | $2,976 |
| Yes | 9893529 | BRYANT | 280ANV024*0**A* | CAP**6021AL*+UI & 98(6*B,7*A)66100V21*** | | 24,800 | $2,976 |
| Yes | 9893527 | BRYANT | 280ANV024*0**A* | CAP**6021AL*+UI & 98(6*B,7MA)60060V21*** | | 24,800 | $2,976 |
| Yes | 9893528 | BRYANT | 280ANV024*0**A* | CAP**6021AL*+UI & 98(6*B,7*A)60080V21*** | | 24,800 | $2,976 |
| Yes | 9893530 | BRYANT | 280ANV024*0**A* | CAP**6024AL*+UI & 98(6*B,7MA)60060V21*** | | 24,800 | $2,976 |
| Yes | 9893531 | BRYANT | 280ANV024*0**A* | CAP**6024AL*+UI & 98(6*B,7*A)60080V21*** | | 24,800 | $2,976 |
| Yes | 9893532 | BRYANT | 280ANV024*0**A* | CAP**6024AL*+UI & 98(6*B,7*A)66100V21*** | | 24,800 | $2,976 |
| Yes | 9893534 | BRYANT | 280ANV024*0**A* | CNPV*3621AL*+UI & 98(6*B,7*A)60080V21*** | | 25,200 | $3,024 |
| Yes | 9893533 | BRYANT | 280ANV024*0**A* | CNPV*3621AL*+UI & 98(6*B,7MA)60060V21*** | | 25,200 | $3,024 |
| Yes | 9893535 | BRYANT | 280ANV024*0**A* | CNPV*3621AL*+UI & 98(6*B,7*A)66100V21*** | | 25,200 | $3,024 |
| Yes | 9893536 | BRYANT | 280ANV024*0**A* | CNPV*4221AL*+UI & 98(6*B,7MA)60060V21*** | | 25,200 | $3,024 |
| Yes | 9893537 | BRYANT | 280ANV024*0**A* | CNPV*4221AL*+UI & 98(6*B,7*A)60080V21*** | | 25,200 | $3,024 |
| Yes | 9893539 | BRYANT | 280ANV024*0**A* | CNPV*4824AL*+UI & 98(6*B,7MA)60060V21*** | | 25,000 | $3,000 |
| Yes | 9893538 | BRYANT | 280ANV024*0**A* | CNPV*4221AL*+UI & 98(6*B,7*A)66100V21*** | | 25,000 | $3,000 |
| Yes | 9893540 | BRYANT | 280ANV024*0**A* | CNPV*4824AL*+UI & 98(6*B,7*A)60080V21*** | | 25,000 | $3,000 |
| Yes | 9893542 | BRYANT | 280ANV024*0**A* | CNPV*6024AL*+UI & 98(6*B,7MA)60060V21*** | | 25,000 | $3,000 |
| Yes | 9893541 | BRYANT | 280ANV024*0**A* | CNPV*4824AL*+UI & 98(6*B,7*A)66100V21*** | | 25,000 | $3,000 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 9893543 | BRYANT | 280ANV024*0**A* | CNPV*6024AL*+UI & 98(6*B,7*A)60080V21*** | | 25,000 | $3,000 |
| Yes | 9893544 | BRYANT | 280ANV024*0**A* | CNPV*6024AL*+UI & 98(6*B,7*A)66100V21*** | | 25,000 | $3,000 |
| Yes | 9893545 | BRYANT | 280ANV024*0**A* | CSPH*3612AL*+UI & 98(6*B,7MA)60060V21*** | | 25,200 | $3,024 |
| Yes | 9893546 | BRYANT | 280ANV024*0**A* | CSPH*3612AL*+UI & 98(6*B,7*A)60080V21*** | | 25,000 | $3,000 |
| Yes | 9893549 | BRYANT | 280ANV024*0**A* | CSPH*4212AL*+UI & 98(6*B,7*A)60080V21*** | | 25,000 | $3,000 |
| Yes | 9893548 | BRYANT | 280ANV024*0**A* | CSPH*4212AL*+UI & 98(6*B,7MA)60060V21*** | | 25,000 | $3,000 |
| Yes | 9893547 | BRYANT | 280ANV024*0**A* | CSPH*3612AL*+UI & 98(6*B,7*A)66100V21*** | | 25,000 | $3,000 |
| Yes | 9893550 | BRYANT | 280ANV024*0**A* | CSPH*4212AL*+UI & 98(6*B,7*A)66100V21*** | | 25,000 | $3,000 |
| Yes | 9893551 | BRYANT | 280ANV024*0**A* | CSPH*4812AL*+UI & 98(6*B,7MA)60060V21*** | | 25,000 | $3,000 |
| Yes | 9893552 | BRYANT | 280ANV024*0**A* | CSPH*4812AL*+UI & 98(6*B,7*A)60080V21*** | | 25,000 | $3,000 |
| Yes | 9893553 | BRYANT | 280ANV024*0**A* | CSPH*4812AL*+UI & 98(6*B,7*A)66100V21*** | | 24,800 | $2,976 |
| Yes | 9893554 | BRYANT | 280ANV024*0**A* | CSPH*6012AL*+UI & 98(6*B,7MA)60060V21*** | | 25,000 | $3,000 |
| Yes | 9893555 | BRYANT | 280ANV024*0**A* | CSPH*6012AL*+UI & 98(6*B,7*A)60080V21*** | | 25,000 | $3,000 |
| Yes | 9893556 | BRYANT | 280ANV036000 | FE4ANB006L+UI | | 31,600 | $3,792 |
| Yes | 9893621 | BRYANT | 280ANV036*0**A* | CAP**4224AL*+UI & 98(6*B,7*A)66120V24*** | | 30,200 | $3,624 |
| Yes | 9893614 | BRYANT | 280ANV036000 | FE4AN(B,F)005L+UI | | 31,600 | $3,792 |
| Yes | 9893626 | BRYANT | 280ANV036*0**A* | CAP**4824AL*+UI & 98(6*B,7*A)66120V24*** | | 32,000 | $3,840 |
| Yes | 9893625 | BRYANT | 280ANV036*0**A* | CAP**4821AL*+UI & 98(6*B,7*A)42080V17*** | | 32,600 | $3,912 |
| Yes | 9893628 | BRYANT | 280ANV036*0**A* | CAP**6021AL*+UI & 98(6*B,7*A)42080V17*** | | 32,000 | $3,840 |
| Yes | 9893629 | BRYANT | 280ANV036*0**A* | CAP**6024AL*+UI & 98(6*B,7*A)66120V24*** | | 31,600 | $3,792 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 9893639 | BRYANT | 280ANV036*0**A* | CNPV*4821AL*+UI & 98(6*B,7*A)42080V17*** | | 32,600 | $3,912 |
| Yes | 9893640 | BRYANT | 280ANV036*0**A* | CNPV*4824AL*+UI & 98(6*B,7*A)66120V24*** | | 32,200 | $3,864 |
| Yes | 9893641 | BRYANT | 280ANV036*0**A* | CNPV*6024AL*+UI & 98(6*B,7*A)66120V24*** | | 32,200 | $3,864 |
| Yes | 9893644 | BRYANT | 280ANV036*0**A* | CSPH*3612AL*+UI & 98(6*B,7*A)66120V24*** | | 30,400 | $3,648 |
| Yes | 9893646 | BRYANT | 280ANV036*0**A* | CSPH*4212AL*+UI & 98(6*B,7*A)42080V17*** | | 30,600 | $3,672 |
| Yes | 9893647 | BRYANT | 280ANV036*0**A* | CSPH*4212AL*+UI & 98(6*B,7*A)66120V24*** | | 30,200 | $3,624 |
| Yes | 9893649 | BRYANT | 280ANV036*0**A* | CSPH*4812AL*+UI & 98(6*B,7*A)42080V17*** | | 32,800 | $3,936 |
| Yes | 9893652 | BRYANT | 280ANV036*0**A* | CSPH*6012AL*+UI & 98(6*B,7*A)42080V17*** | | 32,400 | $3,888 |
| Yes | 9893651 | BRYANT | 280ANV036*0**A* | CSPH*6012AL*+UI & 98(6*B,7*A)42060V17*** | | 32,600 | $3,912 |
| Yes | 9893650 | BRYANT | 280ANV036*0**A* | CSPH*4812AL*+UI & 98(6*B,7*A)66120V24*** | | 32,200 | $3,864 |
| Yes | 9893653 | BRYANT | 280ANV036*0**A* | CSPH*6012AL*+UI & 98(6*B,7*A)66120V24*** | | 32,000 | $3,840 |
| Yes | 9893654 | BRYANT | 280ANV036*0**A* | CAP**3621AL*+UI & 98(6*B,7MA)60060V21*** | | 30,600 | $3,672 |
| Yes | 9893655 | BRYANT | 280ANV036*0**A* | CAP**3621AL*+UI & 98(6*B,7*A)60080V21*** | | 30,400 | $3,648 |
| Yes | 9893656 | BRYANT | 280ANV036*0**A* | CAP**3621AL*+UI & 98(6*B,7*A)66100V21*** | | 30,200 | $3,624 |
| Yes | 9893659 | BRYANT | 280ANV036*0**A* | CAP**4221AL*+UI & 98(6*B,7*A)66100V21*** | | 30,200 | $3,624 |
| Yes | 9893658 | BRYANT | 280ANV036*0**A* | CAP**4221AL*+UI & 98(6*B,7*A)60080V21*** | | 30,200 | $3,624 |
| Yes | 9893661 | BRYANT | 280ANV036*0**A* | CAP**4224AL*+UI & 98(6*B,7*A)60080V21*** | | 30,200 | $3,624 |
| Yes | 9893662 | BRYANT | 280ANV036*0**A* | CAP**4224AL*+UI & 98(6*B,7*A)66100V21*** | | 30,200 | $3,624 |
| Yes | 9893663 | BRYANT | 280ANV036*0**A* | CAP**4821AL*+UI & 98(6*B,7MA)60060V21*** | | 30,200 | $3,624 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 9893664 | BRYANT | 280ANV036*0**A* | CAP**4821AL*+UI & 98(6*B,7*A)60080V21*** | | 30,000 | $3,600 |
| Yes | 9893665 | BRYANT | 280ANV036*0**A* | CAP**4821AL*+UI & 98(6*B,7*A)66100V21*** | | 29,800 | $3,576 |
| Yes | 9893666 | BRYANT | 280ANV036*0**A* | CAP**4824AL*+UI & 98(6*B,7MA)60060V21*** | | 30,200 | $3,624 |
| Yes | 9893667 | BRYANT | 280ANV036*0**A* | CAP**4824AL*+UI & 98(6*B,7*A)60080V21*** | | 29,800 | $3,576 |
| Yes | 9893668 | BRYANT | 280ANV036*0**A* | CAP**4824AL*+UI & 98(6*B,7*A)66100V21*** | | 29,800 | $3,576 |
| Yes | 9893671 | BRYANT | 280ANV036*0**A* | CAP**6021AL*+UI & 98(6*B,7*A)66100V21*** | | 31,800 | $3,816 |
| Yes | 9893669 | BRYANT | 280ANV036*0**A* | CAP**6021AL*+UI & 98(6*B,7MA)60060V21*** | | 32,200 | $3,864 |
| Yes | 9893670 | BRYANT | 280ANV036*0**A* | CAP**6021AL*+UI & 98(6*B,7*A)60080V21*** | | 31,800 | $3,816 |
| Yes | 9893673 | BRYANT | 280ANV036*0**A* | CAP**6024AL*+UI & 98(6*B,7*A)60080V21*** | | 31,800 | $3,816 |
| Yes | 9893672 | BRYANT | 280ANV036*0**A* | CAP**6024AL*+UI & 98(6*B,7MA)60060V21*** | | 32,200 | $3,864 |
| Yes | 9893674 | BRYANT | 280ANV036*0**A* | CAP**6024AL*+UI & 98(6*B,7*A)66100V21*** | | 31,800 | $3,816 |
| Yes | 9893676 | BRYANT | 280ANV036*0**A* | CNPV*4221AL*+UI & 98(6*B,7*A)60080V21*** | | 30,400 | $3,648 |
| Yes | 9893678 | BRYANT | 280ANV036*0**A* | CNPV*4821AL*+UI & 98(6*B,7MA)60060V21*** | | 30,400 | $3,648 |
| Yes | 9893677 | BRYANT | 280ANV036*0**A* | CNPV*4221AL*+UI & 98(6*B,7*A)66100V21*** | | 30,200 | $3,624 |
| Yes | 9893679 | BRYANT | 280ANV036*0**A* | CNPV*4821AL*+UI & 98(6*B,7*A)60080V21*** | | 30,000 | $3,600 |
| Yes | 9893680 | BRYANT | 280ANV036*0**A* | CNPV*4821AL*+UI & 98(6*B,7*A)66100V21*** | | 30,000 | $3,600 |
| Yes | 9893681 | BRYANT | 280ANV036*0**A* | CNPV*4824AL*+UI & 98(6*B,7MA)60060V21*** | | 30,400 | $3,648 |
| Yes | 9893682 | BRYANT | 280ANV036*0**A* | CNPV*4824AL*+UI & 98(6*B,7*A)60080V21*** | | 30,000 | $3,600 |
| Yes | 9893685 | BRYANT | 280ANV036*0**A* | CNPV*6024AL*+UI & 98(6*B,7*A)60080V21*** | | 32,200 | $3,864 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 9893683 | BRYANT | 280ANV036*0**A* | CNPV*4824AL*+UI & 98(6*B,7*A)66100V21*** | | 30,000 | $3,600 |
| Yes | 9893684 | BRYANT | 280ANV036*0**A* | CNPV*6024AL*+UI & 98(6*B,7MA)60060V21*** | | 32,400 | $3,888 |
| Yes | 9893686 | BRYANT | 280ANV036*0**A* | CNPV*6024AL*+UI & 98(6*B,7*A)66100V21*** | | 32,000 | $3,840 |
| Yes | 9893688 | BRYANT | 280ANV036*0**A* | CSPH*3612AL*+UI & 98(6*B,7*A)60080V21*** | | 30,200 | $3,624 |
| Yes | 9893689 | BRYANT | 280ANV036*0**A* | CSPH*3612AL*+UI & 98(6*B,7*A)66100V21*** | | 30,200 | $3,624 |
| Yes | 9893690 | BRYANT | 280ANV036*0**A* | CSPH*4212AL*+UI & 98(6*B,7MA)60060V21*** | | 30,400 | $3,648 |
| Yes | 9893691 | BRYANT | 280ANV036*0**A* | CSPH*4212AL*+UI & 98(6*B,7*A)60080V21*** | | 30,200 | $3,624 |
| Yes | 9893694 | BRYANT | 280ANV036*0**A* | CSPH*4812AL*+UI & 98(6*B,7*A)60080V21*** | | 30,000 | $3,600 |
| Yes | 9893692 | BRYANT | 280ANV036*0**A* | CSPH*4212AL*+UI & 98(6*B,7*A)66100V21*** | | 30,000 | $3,600 |
| Yes | 9893693 | BRYANT | 280ANV036*0**A* | CSPH*4812AL*+UI & 98(6*B,7MA)60060V21*** | | 30,400 | $3,648 |
| Yes | 9893695 | BRYANT | 280ANV036*0**A* | CSPH*4812AL*+UI & 98(6*B,7*A)66100V21*** | | 30,000 | $3,600 |
| Yes | 9893696 | BRYANT | 280ANV036*0**A* | CSPH*6012AL*+UI & 98(6*B,7MA)60060V21*** | | 32,200 | $3,864 |
| Yes | 9893698 | BRYANT | 280ANV036*0**A* | CSPH*6012AL*+UI & 98(6*B,7*A)66100V21*** | | 32,000 | $3,840 |
| Yes | 9893697 | BRYANT | 280ANV036*0**A* | CSPH*6012AL*+UI & 98(6*B,7*A)60080V21*** | | 32,000 | $3,840 |
| Yes | 9893727 | BRYANT | 280ANV048000 | FE4AN(B,F)005L+UI | | 48,500 | $5,820 |
| Yes | 9893699 | BRYANT | 280ANV048000 | FE4ANB006L+UI | | 47,500 | $5,700 |
| Yes | 9893731 | BRYANT | 280ANV048*0**A* | CNPV*6024AL*+UI & 98(6*B,7*A)66120V24*** | | 49,000 | $5,880 |
| Yes | 9893742 | BRYANT | 280ANV048*0**A* | CAP**6021AL*+UI & 98(6*B,7*A)66100V21*** | | 48,000 | $5,760 |
| Yes | 9893745 | BRYANT | 280ANV048*0**A* | CAP**6024AL*+UI & 98(6*B,7*A)66100V21*** | | 48,000 | $5,760 |
| Yes | 9893748 | BRYANT | 280ANV048*0**A* | CNPV*4821AL*+UI & 98(6*B,7*A)66100V21*** | | 48,000 | $5,760 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 9893753 | BRYANT | 280ANV048*0**A* | CNPV*6024AL*+UI & 98(6*B,7*A)60080V21*** | | 49,000 | $5,880 |
| Yes | 9893754 | BRYANT | 280ANV048*0**A* | CNPV*6024AL*+UI & 98(6*B,7*A)66100V21*** | | 48,500 | $5,820 |
| Yes | 9893760 | BRYANT | 280ANV060000 | FE4ANB006L+UI | | 52,500 | $6,300 |
| Yes | 205274179 | BRYANT | 284ANV036*0**A* | CSPH*6012AL*+UI | 987MB42060C17*** | 33,800 | $4,056 |
| Yes | 205274176 | BRYANT | 284ANV036*0**A* | CSPH*6012AL*+UI | 986TC42060C17*** | 33,800 | $4,056 |
| Yes | 205274170 | BRYANT | 284ANV036*0**A* | CSPH*4812AL*+UI | 987MB60060C21*** | 34,000 | $4,080 |
| Yes | 205274171 | BRYANT | 284ANV036*0**A* | CSPH*6012AL*+UI | 88*TA36045C17*** | 33,800 | $4,056 |
| Yes | 205274161 | BRYANT | 284ANV036*0**A* | CSPH*4812AL*+UI | 987MB42080C17*** | 34,000 | $4,080 |
| Yes | 205274167 | BRYANT | 284ANV036*0**A* | CSPH*4812AL*+UI | 88*TA36070C14*** | 34,000 | $4,080 |
| Yes | 205274158 | BRYANT | 284ANV036*0**A* | CSPH*4812AL*+UI | 986TC42080C17*** | 34,200 | $4,104 |
| Yes | 205274160 | BRYANT | 284ANV036*0**A* | CSPH*4812AL*+UI | 987MB42060C17*** | 34,200 | $4,104 |
| Yes | 205274152 | BRYANT | 284ANV036*0**A* | CSPH*4812AL*+UI | 88*TA36045C17*** | 34,400 | $4,128 |
| Yes | 205274157 | BRYANT | 284ANV036*0**A* | CSPH*4812AL*+UI | 986TC42060C17*** | 34,200 | $4,104 |
| Yes | 205274148 | BRYANT | 284ANV036*0**A* | CSPH*4212AL*+UI | 88*TA36070C14*** | 34,000 | $4,080 |
| Yes | 205274151 | BRYANT | 284ANV036*0**A* | CSPH*4212AL*+UI | 987MB60060C21*** | 34,000 | $4,080 |
| Yes | 205274142 | BRYANT | 284ANV036*0**A* | CSPH*4212AL*+UI | 987MB42080C17*** | 34,200 | $4,104 |
| Yes | 205274138 | BRYANT | 284ANV036*0**A* | CSPH*4212AL*+UI | 986TC42060C17*** | 34,400 | $4,128 |
| Yes | 205274141 | BRYANT | 284ANV036*0**A* | CSPH*4212AL*+UI | 987MB42060C17*** | 34,200 | $4,104 |
| Yes | 205274139 | BRYANT | 284ANV036*0**A* | CSPH*4212AL*+UI | 986TC42080C17*** | 34,200 | $4,104 |
| Yes | 205274134 | BRYANT | 284ANV036*0**A* | CSPH*4212AL*+UI | 88*TA48070C17*** | 34,000 | $4,080 |
| Yes | 205274132 | BRYANT | 284ANV036*0**A* | CSPH*3612AL*+UI | 987MB60060C21*** | 34,200 | $4,104 |
| Yes | 205274129 | BRYANT | 284ANV036*0**A* | CSPH*3612AL*+UI | 88*TA36070C14*** | 34,200 | $4,104 |
| Yes | 205274120 | BRYANT | 284ANV036*0**A* | CSPH*3612AL*+UI | 986TC42080C17*** | 34,400 | $4,128 |
| Yes | 205274123 | BRYANT | 284ANV036*0**A* | CSPH*3612AL*+UI | 987MB42080C17*** | 34,200 | $4,104 |
| Yes | 205274133 | BRYANT | 284ANV036*0**A* | CSPH*4212AL*+UI | 88*TA36045C17*** | 34,400 | $4,128 |
| Yes | 205274119 | BRYANT | 284ANV036*0**A* | CSPH*3612AL*+UI | 986TC42060C17*** | 34,600 | $4,152 |
| Yes | 205274116 | BRYANT | 284ANV036*0**A* | CSPH*3612AL*+UI | 88*TA60070C21*** | 33,800 | $4,056 |
| Yes | 205274115 | BRYANT | 284ANV036*0**A* | CSPH*3612AL*+UI | 88*TA48070C17*** | 34,000 | $4,080 |
| Yes | 205274081 | BRYANT | 284ANV036*0**A* | CNPV*4821AL*+UI | 986TC42060C17*** | 34,400 | $4,128 |
| Yes | 205274083 | BRYANT | 284ANV036*0**A* | CNPV*4821AL*+UI | 987MB42060C17*** | 34,200 | $4,104 |
| Yes | 205274077 | BRYANT | 284ANV036*0**A* | CNPV*4821AL*+UI | 88*TA36045C17*** | 34,200 | $4,104 |
| Yes | 205274076 | BRYANT | 284ANV036*0**A* | CNPV*4221AL*+UI | 987MB60060C21*** | 34,400 | $4,128 |
| Yes | 205274069 | BRYANT | 284ANV036*0**A* | CNPV*4221AL*+UI | 987MB42080C17*** | 34,400 | $4,128 |
| Yes | 205274068 | BRYANT | 284ANV036*0**A* | CNPV*4221AL*+UI | 987MB42060C17*** | 34,600 | $4,152 |
| Yes | 205274066 | BRYANT | 284ANV036*0**A* | CNPV*4221AL*+UI | 986TC42060C17*** | 34,600 | $4,152 |
| Yes | 205274067 | BRYANT | 284ANV036*0**A* | CNPV*4221AL*+UI | 986TC42080C17*** | 34,600 | $4,152 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205274064 | BRYANT | 284ANV036*0**A* | CNPV*4221AL*+UI | 88*TA60070C21*** | 34,000 | $4,080 |
| Yes | 205274060 | BRYANT | 284ANV036*0**A* | CNPV*4217AL*+UI | 88*TA36070C14*** | 34,200 | $4,104 |
| Yes | 205274062 | BRYANT | 284ANV036*0**A* | CNPV*4221AL*+UI | 88*TA36045C17*** | 34,800 | $4,176 |
| Yes | 205274059 | BRYANT | 284ANV036*0**A* | CNPV*4217AL*+UI | 987MB42080C17*** | 34,200 | $4,104 |
| Yes | 205274063 | BRYANT | 284ANV036*0**A* | CNPV*4221AL*+UI | 88*TA48070C17*** | 34,200 | $4,104 |
| Yes | 205274057 | BRYANT | 284ANV036*0**A* | CNPV*4217AL*+UI | 986TC42080C17*** | 34,400 | $4,128 |
| Yes | 205274054 | BRYANT | 284ANV036*0**A* | CNPV*4217AL*+UI | 88*TA36045C17*** | 34,600 | $4,152 |
| Yes | 205274056 | BRYANT | 284ANV036*0**A* | CNPV*4217AL*+UI | 986TC42060C17*** | 34,600 | $4,152 |
| Yes | 205274058 | BRYANT | 284ANV036*0**A* | CNPV*4217AL*+UI | 987MB42060C17*** | 34,400 | $4,128 |
| Yes | 205274034 | BRYANT | 284ANV036*0**A* | CAP**6121AL*+UI | 987MB42060C17*** | 33,600 | $4,032 |
| Yes | 205274013 | BRYANT | 284ANV036*0**A* | CAP**4824AL*+UI | 986TC60080C21*** | 33,400 | $4,008 |
| Yes | 205274012 | BRYANT | 284ANV036*0**A* | CAP**4824AL*+UI | 987MB66120C24*** | 33,400 | $4,008 |
| Yes | 205274010 | BRYANT | 284ANV036*0**A* | CAP**4824AL*+UI | 987MB60080C21*** | 33,400 | $4,008 |
| Yes | 205274005 | BRYANT | 284ANV036*0**A* | CAP**4821AL*+UI | 987MB60060C21*** | 33,800 | $4,056 |
| Yes | 205273998 | BRYANT | 284ANV036*0**A* | CAP**4821AL*+UI | 987MB42080C17*** | 33,800 | $4,056 |
| Yes | 205273999 | BRYANT | 284ANV036*0**A* | CAP**4821AL*+UI | 987MB60080C21*** | 33,400 | $4,008 |
| Yes | 205273997 | BRYANT | 284ANV036*0**A* | CAP**4821AL*+UI | 987MB42060C17*** | 34,000 | $4,080 |
| Yes | 205273996 | BRYANT | 284ANV036*0**A* | CAP**4821AL*+UI | 986TC42080C17*** | 34,000 | $4,080 |
| Yes | 205273995 | BRYANT | 284ANV036*0**A* | CAP**4821AL*+UI | 986TC42060C17*** | 34,200 | $4,104 |
| Yes | 205273993 | BRYANT | 284ANV036*0**A* | CAP**4821AL*+UI | 88*TA60070C21*** | 33,600 | $4,032 |
| Yes | 205273991 | BRYANT | 284ANV036*0**A* | CAP**4821AL*+UI | 88*TA36045C17*** | 34,200 | $4,104 |
| Yes | 205273981 | BRYANT | 284ANV036*0**A* | CAP**4321AL*+UI | 986TC42060C17*** | 34,400 | $4,128 |
| Yes | 205273977 | BRYANT | 284ANV036*0**A* | CAP**4224AL*+UI | 987MB60060C21*** | 34,200 | $4,104 |
| Yes | 205273975 | BRYANT | 284ANV036*0**A* | CAP**4224AL*+UI | 986TC66100C21*** | 33,600 | $4,032 |
| Yes | 205273982 | BRYANT | 284ANV036*0**A* | CAP**4321AL*+UI | 986TC42080C17*** | 34,200 | $4,104 |
| Yes | 205273972 | BRYANT | 284ANV036*0**A* | CAP**4224AL*+UI | 987MB66100C21*** | 33,600 | $4,032 |
| Yes | 205273973 | BRYANT | 284ANV036*0**A* | CAP**4224AL*+UI | 987MB66120C24*** | 33,800 | $4,056 |
| Yes | 205273974 | BRYANT | 284ANV036*0**A* | CAP**4224AL*+UI | 986TC60080C21*** | 33,800 | $4,056 |
| Yes | 205273970 | BRYANT | 284ANV036*0**A* | CAP**4224AL*+UI | 986TC66120C24*** | 33,600 | $4,032 |
| Yes | 205273971 | BRYANT | 284ANV036*0**A* | CAP**4224AL*+UI | 987MB60080C21*** | 33,800 | $4,056 |
| Yes | 205273964 | BRYANT | 284ANV036*0**A* | CAP**4221AL*+UI | 88*TA48090C17*** | 33,800 | $4,056 |
| Yes | 205273966 | BRYANT | 284ANV036*0**A* | CAP**4221AL*+UI | 987MB60060C21*** | 34,200 | $4,104 |
| Yes | 205273961 | BRYANT | 284ANV036*0**A* | CAP**4221AL*+UI | 987MB66100C21*** | 33,800 | $4,056 |
| Yes | 205273962 | BRYANT | 284ANV036*0**A* | CAP**4221AL*+UI | 986TC60080C21*** | 33,800 | $4,056 |
| Yes | 205273963 | BRYANT | 284ANV036*0**A* | CAP**4221AL*+UI | 986TC66100C21*** | 33,800 | $4,056 |
| Yes | 205273959 | BRYANT | 284ANV036*0**A* | CAP**4221AL*+UI | 987MB42080C17*** | 34,400 | $4,128 |
| Yes | 205273957 | BRYANT | 284ANV036*0**A* | CAP**4221AL*+UI | 986TC42060C17*** | 34,600 | $4,152 |
| Yes | 205273960 | BRYANT | 284ANV036*0**A* | CAP**4221AL*+UI | 987MB60080C21*** | 33,800 | $4,056 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205273955 | BRYANT | 284ANV036*0**A* | CAP**4221AL*+UI | 88*TA60070C21*** | 34,000 | $4,080 |
| Yes | 205273944 | BRYANT | 284ANV036*0**A* | CAP**3721AL*+UI | 986TC42080C17*** | 34,200 | $4,104 |
| Yes | 205273954 | BRYANT | 284ANV036*0**A* | CAP**4221AL*+UI | 88*TA48070C17*** | 34,200 | $4,104 |
| Yes | 205273945 | BRYANT | 284ANV036*0**A* | CAP**3721AL*+UI | 987MB42080C17*** | 34,000 | $4,080 |
| Yes | 205273943 | BRYANT | 284ANV036*0**A* | CAP**3721AL*+UI | 986TC42060C17*** | 34,400 | $4,128 |
| Yes | 205273938 | BRYANT | 284ANV036*0**A* | CAP**3717AL*+UI | 88*TA36070C14*** | 34,000 | $4,080 |
| Yes | 205273937 | BRYANT | 284ANV036*0**A* | CAP**3717AL*+UI | 88*TA48070C17*** | 34,200 | $4,104 |
| Yes | 205274122 | BRYANT | 284ANV036*0**A* | CSPH*3612AL*+UI | 987MB42060C17*** | 34,400 | $4,128 |
| Yes | 205274114 | BRYANT | 284ANV036*0**A* | CSPH*3612AL*+UI | 88*TA36045C17*** | 34,600 | $4,152 |
| Yes | 205273967 | BRYANT | 284ANV036*0**A* | CAP**4224AL*+UI | 88*TA60070C21*** | 33,800 | $4,056 |
| Yes | 205273953 | BRYANT | 284ANV036*0**A* | CAP**4221AL*+UI | 88*TA36045C17*** | 34,600 | $4,152 |
| Yes | 205273958 | BRYANT | 284ANV036*0**A* | CAP**4221AL*+UI | 987MB42060C17*** | 34,600 | $4,152 |
| Yes | 205274145 | BRYANT | 284ANV036*0**A* | CSPH*4212AL*+UI | 987MB66120C24*** | 33,600 | $4,032 |
| Yes | 205274144 | BRYANT | 284ANV036*0**A* | CSPH*4212AL*+UI | 987MB66100C21*** | 33,400 | $4,008 |
| Yes | 205274143 | BRYANT | 284ANV036*0**A* | CSPH*4212AL*+UI | 987MB60080C21*** | 33,600 | $4,032 |
| Yes | 205274140 | BRYANT | 284ANV036*0**A* | CSPH*4212AL*+UI | 986TC66120C24*** | 33,400 | $4,008 |
| Yes | 205274137 | BRYANT | 284ANV036*0**A* | CSPH*4212AL*+UI | 88*TA66135C24*** | 33,400 | $4,008 |
| Yes | 205274136 | BRYANT | 284ANV036*0**A* | CSPH*4212AL*+UI | 88*TA60090C21*** | 33,400 | $4,008 |
| Yes | 205274131 | BRYANT | 284ANV036*0**A* | CSPH*3612AL*+UI | 88*TA60110C21*** | 33,600 | $4,032 |
| Yes | 205274130 | BRYANT | 284ANV036*0**A* | CSPH*3612AL*+UI | 88*TA48090C17*** | 33,800 | $4,056 |
| Yes | 205274135 | BRYANT | 284ANV036*0**A* | CSPH*4212AL*+UI | 88*TA60070C21*** | 33,600 | $4,032 |
| Yes | 205274118 | BRYANT | 284ANV036*0**A* | CSPH*3612AL*+UI | 88*TA66135C24*** | 33,400 | $4,008 |
| Yes | 205274121 | BRYANT | 284ANV036*0**A* | CSPH*3612AL*+UI | 986TC66120C24*** | 33,600 | $4,032 |
| Yes | 205274102 | BRYANT | 284ANV036*0**A* | CNPV*4824AL*+UI | 987MB60060C21*** | 34,000 | $4,080 |
| Yes | 205274117 | BRYANT | 284ANV036*0**A* | CSPH*3612AL*+UI | 88*TA60090C21*** | 33,600 | $4,032 |
| Yes | 205274082 | BRYANT | 284ANV036*0**A* | CNPV*4821AL*+UI | 986TC42080C17*** | 34,000 | $4,080 |
| Yes | 205274091 | BRYANT | 284ANV036*0**A* | CNPV*4821AL*+UI | 987MB60060C21*** | 34,000 | $4,080 |
| Yes | 205274084 | BRYANT | 284ANV036*0**A* | CNPV*4821AL*+UI | 987MB42080C17*** | 34,000 | $4,080 |
| Yes | 205274078 | BRYANT | 284ANV036*0**A* | CNPV*4821AL*+UI | 88*TA48070C17*** | 33,800 | $4,056 |
| Yes | 205274074 | BRYANT | 284ANV036*0**A* | CNPV*4221AL*+UI | 88*TA48090C17*** | 33,800 | $4,056 |
| Yes | 205274075 | BRYANT | 284ANV036*0**A* | CNPV*4221AL*+UI | 88*TA60110C21*** | 33,800 | $4,056 |
| Yes | 205274072 | BRYANT | 284ANV036*0**A* | CNPV*4221AL*+UI | 986TC60080C21*** | 34,000 | $4,080 |
| Yes | 205274065 | BRYANT | 284ANV036*0**A* | CNPV*4221AL*+UI | 88*TA60090C21*** | 33,800 | $4,056 |
| Yes | 205274073 | BRYANT | 284ANV036*0**A* | CNPV*4221AL*+UI | 986TC66100C21*** | 33,800 | $4,056 |
| Yes | 205274061 | BRYANT | 284ANV036*0**A* | CNPV*4217AL*+UI | 88*TA48090C17*** | 33,800 | $4,056 |
| Yes | 205274055 | BRYANT | 284ANV036*0**A* | CNPV*4217AL*+UI | 88*TA48070C17*** | 34,200 | $4,104 |
| Yes | 205274070 | BRYANT | 284ANV036*0**A* | CNPV*4221AL*+UI | 987MB60080C21*** | 34,000 | $4,080 |
| Yes | 205274053 | BRYANT | 284ANV036*0**A* | CAP**6124AL*+UI | 987MB60060C21*** | 33,600 | $4,032 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205274042 | BRYANT | 284ANV036*0**A* | CAP**6121AL*+UI | 987MB60060C21*** | 33,600 | $4,032 |
| Yes | 205274033 | BRYANT | 284ANV036*0**A* | CAP**6121AL*+UI | 986TC42080C17*** | 33,800 | $4,056 |
| Yes | 205274035 | BRYANT | 284ANV036*0**A* | CAP**6121AL*+UI | 987MB42080C17*** | 33,800 | $4,056 |
| Yes | 205274032 | BRYANT | 284ANV036*0**A* | CAP**6121AL*+UI | 986TC42060C17*** | 34,000 | $4,080 |
| Yes | 205274028 | BRYANT | 284ANV036*0**A* | CAP**6121AL*+UI | 88*TA36045C17*** | 33,800 | $4,056 |
| Yes | 205274027 | BRYANT | 284ANV036*0**A* | CAP**6024AL*+UI | 987MB60060C21*** | 33,400 | $4,008 |
| Yes | 205274017 | BRYANT | 284ANV036*0**A* | CAP**6024AL*+UI | 88*TA60070C21*** | 33,000 | $3,960 |
| Yes | 205274016 | BRYANT | 284ANV036*0**A* | CAP**4824AL*+UI | 987MB60060C21*** | 33,800 | $4,056 |
| Yes | 205274014 | BRYANT | 284ANV036*0**A* | CAP**4824AL*+UI | 986TC66100C21*** | 33,200 | $3,984 |
| Yes | 205274011 | BRYANT | 284ANV036*0**A* | CAP**4824AL*+UI | 987MB66100C21*** | 33,200 | $3,984 |
| Yes | 205274006 | BRYANT | 284ANV036*0**A* | CAP**4824AL*+UI | 88*TA60070C21*** | 33,400 | $4,008 |
| Yes | 205274009 | BRYANT | 284ANV036*0**A* | CAP**4824AL*+UI | 986TC66120C24*** | 33,200 | $3,984 |
| Yes | 205274004 | BRYANT | 284ANV036*0**A* | CAP**4821AL*+UI | 88*TA60110C21*** | 33,400 | $4,008 |
| Yes | 205274002 | BRYANT | 284ANV036*0**A* | CAP**4821AL*+UI | 986TC66100C21*** | 33,400 | $4,008 |
| Yes | 205274003 | BRYANT | 284ANV036*0**A* | CAP**4821AL*+UI | 88*TA48090C17*** | 33,400 | $4,008 |
| Yes | 205274001 | BRYANT | 284ANV036*0**A* | CAP**4821AL*+UI | 986TC60080C21*** | 33,400 | $4,008 |
| Yes | 205273994 | BRYANT | 284ANV036*0**A* | CAP**4821AL*+UI | 88*TA60090C21*** | 33,200 | $3,984 |
| Yes | 205274000 | BRYANT | 284ANV036*0**A* | CAP**4821AL*+UI | 987MB66100C21*** | 33,400 | $4,008 |
| Yes | 205273992 | BRYANT | 284ANV036*0**A* | CAP**4821AL*+UI | 88*TA48070C17*** | 33,800 | $4,056 |
| Yes | 205273990 | BRYANT | 284ANV036*0**A* | CAP**4321AL*+UI | 987MB60060C21*** | 34,000 | $4,080 |
| Yes | 205273986 | BRYANT | 284ANV036*0**A* | CAP**4321AL*+UI | 986TC60080C21*** | 33,600 | $4,032 |
| Yes | 205273979 | BRYANT | 284ANV036*0**A* | CAP**4321AL*+UI | 88*TA60070C21*** | 33,600 | $4,032 |
| Yes | 205273983 | BRYANT | 284ANV036*0**A* | CAP**4321AL*+UI | 987MB42080C17*** | 34,000 | $4,080 |
| Yes | 205273978 | BRYANT | 284ANV036*0**A* | CAP**4321AL*+UI | 88*TA48070C17*** | 33,800 | $4,056 |
| Yes | 205273984 | BRYANT | 284ANV036*0**A* | CAP**4321AL*+UI | 987MB60080C21*** | 33,600 | $4,032 |
| Yes | 205273976 | BRYANT | 284ANV036*0**A* | CAP**4224AL*+UI | 88*TA60110C21*** | 33,600 | $4,032 |
| Yes | 205273969 | BRYANT | 284ANV036*0**A* | CAP**4224AL*+UI | 88*TA66135C24*** | 33,600 | $4,032 |
| Yes | 205273968 | BRYANT | 284ANV036*0**A* | CAP**4224AL*+UI | 88*TA60090C21*** | 33,600 | $4,032 |
| Yes | 205273965 | BRYANT | 284ANV036*0**A* | CAP**4221AL*+UI | 88*TA60110C21*** | 33,800 | $4,056 |
| Yes | 205273952 | BRYANT | 284ANV036*0**A* | CAP**3721AL*+UI | 987MB60060C21*** | 34,000 | $4,080 |
| Yes | 205273956 | BRYANT | 284ANV036*0**A* | CAP**4221AL*+UI | 88*TA60090C21*** | 33,600 | $4,032 |
| Yes | 205273946 | BRYANT | 284ANV036*0**A* | CAP**3721AL*+UI | 987MB60080C21*** | 33,600 | $4,032 |
| Yes | 205273948 | BRYANT | 284ANV036*0**A* | CAP**3721AL*+UI | 986TC60080C21*** | 33,600 | $4,032 |
| Yes | 205273942 | BRYANT | 284ANV036*0**A* | CAP**3721AL*+UI | 88*TA60090C21*** | 33,400 | $4,008 |
| Yes | 205273940 | BRYANT | 284ANV036*0**A* | CAP**3721AL*+UI | 88*TA48070C17*** | 34,000 | $4,080 |
| Yes | 205273939 | BRYANT | 284ANV036*0**A* | CAP**3717AL*+UI | 88*TA48090C17*** | 33,800 | $4,056 |
| Yes | 205273941 | BRYANT | 284ANV036*0**A* | CAP**3721AL*+UI | 88*TA60070C21*** | 33,800 | $4,056 |
| Yes | 205274189 | BRYANT | 284ANV036*0**A* | CSPH*6012AL*+UI | 987MB60060C21*** | 33,400 | $4,008 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205274186 | BRYANT | 284ANV036*0**A* | CSPH*6012AL*+UI | 88*TA36070C14*** | 33,600 | $4,032 |
| Yes | 205274181 | BRYANT | 284ANV036*0**A* | CSPH*6012AL*+UI | 987MB60080C21*** | 33,000 | $3,960 |
| Yes | 205274184 | BRYANT | 284ANV036*0**A* | CSPH*6012AL*+UI | 986TC60080C21*** | 33,000 | $3,960 |
| Yes | 205274180 | BRYANT | 284ANV036*0**A* | CSPH*6012AL*+UI | 987MB42080C17*** | 33,600 | $4,032 |
| Yes | 205274177 | BRYANT | 284ANV036*0**A* | CSPH*6012AL*+UI | 986TC42080C17*** | 33,600 | $4,032 |
| Yes | 205274173 | BRYANT | 284ANV036*0**A* | CSPH*6012AL*+UI | 88*TA60070C21*** | 33,200 | $3,984 |
| Yes | 205274183 | BRYANT | 284ANV036*0**A* | CSPH*6012AL*+UI | 987MB66120C24*** | 33,000 | $3,960 |
| Yes | 205274172 | BRYANT | 284ANV036*0**A* | CSPH*6012AL*+UI | 88*TA48070C17*** | 33,400 | $4,008 |
| Yes | 205274169 | BRYANT | 284ANV036*0**A* | CSPH*4812AL*+UI | 88*TA60110C21*** | 33,400 | $4,008 |
| Yes | 205274168 | BRYANT | 284ANV036*0**A* | CSPH*4812AL*+UI | 88*TA48090C17*** | 33,400 | $4,008 |
| Yes | 205274166 | BRYANT | 284ANV036*0**A* | CSPH*4812AL*+UI | 986TC66100C21*** | 33,400 | $4,008 |
| Yes | 205274165 | BRYANT | 284ANV036*0**A* | CSPH*4812AL*+UI | 986TC60080C21*** | 33,600 | $4,032 |
| Yes | 205274163 | BRYANT | 284ANV036*0**A* | CSPH*4812AL*+UI | 987MB66100C21*** | 33,400 | $4,008 |
| Yes | 205274164 | BRYANT | 284ANV036*0**A* | CSPH*4812AL*+UI | 987MB66120C24*** | 33,600 | $4,032 |
| Yes | 205274162 | BRYANT | 284ANV036*0**A* | CSPH*4812AL*+UI | 987MB60080C21*** | 33,600 | $4,032 |
| Yes | 205274159 | BRYANT | 284ANV036*0**A* | CSPH*4812AL*+UI | 986TC66120C24*** | 33,400 | $4,008 |
| Yes | 205274155 | BRYANT | 284ANV036*0**A* | CSPH*4812AL*+UI | 88*TA60090C21*** | 33,400 | $4,008 |
| Yes | 205274156 | BRYANT | 284ANV036*0**A* | CSPH*4812AL*+UI | 88*TA66135C24*** | 33,200 | $3,984 |
| Yes | 205274154 | BRYANT | 284ANV036*0**A* | CSPH*4812AL*+UI | 88*TA60070C21*** | 33,600 | $4,032 |
| Yes | 205274153 | BRYANT | 284ANV036*0**A* | CSPH*4812AL*+UI | 88*TA48070C17*** | 33,800 | $4,056 |
| Yes | 205274149 | BRYANT | 284ANV036*0**A* | CSPH*4212AL*+UI | 88*TA48090C17*** | 33,600 | $4,032 |
| Yes | 205274150 | BRYANT | 284ANV036*0**A* | CSPH*4212AL*+UI | 88*TA60110C21*** | 33,400 | $4,008 |
| Yes | 205274146 | BRYANT | 284ANV036*0**A* | CSPH*4212AL*+UI | 986TC60080C21*** | 33,600 | $4,032 |
| Yes | 205274147 | BRYANT | 284ANV036*0**A* | CSPH*4212AL*+UI | 986TC66100C21*** | 33,400 | $4,008 |
| Yes | 205273951 | BRYANT | 284ANV036*0**A* | CAP**3721AL*+UI | 88*TA60110C21*** | 33,600 | $4,032 |
| Yes | 205273985 | BRYANT | 284ANV036*0**A* | CAP**4321AL*+UI | 987MB66100C21*** | 33,400 | $4,008 |
| Yes | 205273980 | BRYANT | 284ANV036*0**A* | CAP**4321AL*+UI | 88*TA60090C21*** | 33,400 | $4,008 |
| Yes | 205273987 | BRYANT | 284ANV036*0**A* | CAP**4321AL*+UI | 986TC66100C21*** | 33,400 | $4,008 |
| Yes | 205273949 | BRYANT | 284ANV036*0**A* | CAP**3721AL*+UI | 986TC66100C21*** | 33,600 | $4,032 |
| Yes | 205273950 | BRYANT | 284ANV036*0**A* | CAP**3721AL*+UI | 88*TA48090C17*** | 33,600 | $4,032 |
| Yes | 205273947 | BRYANT | 284ANV036*0**A* | CAP**3721AL*+UI | 987MB66100C21*** | 33,600 | $4,032 |
| Yes | 205273935 | BRYANT | 284ANV036*0**A* | FE4AN(B,F)003L+UI | | 33,000 | $3,960 |
| Yes | 205273825 | BRYANT | 284ANV024*0**A* | CSPH*6012AL*+UI | 987MB42060C17*** | 24,000 | $2,880 |
| Yes | 205273816 | BRYANT | 284ANV024*0**A* | CSPH*4812AL*+UI | 987MB42060C17*** | 24,400 | $2,928 |
| Yes | 205273818 | BRYANT | 284ANV024*0**A* | CSPH*4812AL*+UI | 987MB60060C21*** | 24,200 | $2,904 |
| Yes | 205273817 | BRYANT | 284ANV024*0**A* | CSPH*4812AL*+UI | 987MB42080C17*** | 24,200 | $2,904 |
| Yes | 205273807 | BRYANT | 284ANV024*0**A* | CSPH*4212AL*+UI | 987MB42060C17*** | 24,400 | $2,928 |
| Yes | 205273799 | BRYANT | 284ANV024*0**A* | CSPH*3612AL*+UI | 987MB42080C17*** | 24,400 | $2,928 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205273801 | BRYANT | 284ANV024*0**A* | CSPH*3612AL*+UI | 987MB60080C21*** | 24,200 | $2,904 |
| Yes | 205273800 | BRYANT | 284ANV024*0**A* | CSPH*3612AL*+UI | 987MB60060C21*** | 24,400 | $2,928 |
| Yes | 205273781 | BRYANT | 284ANV024*0**A* | CNPV*4821AL*+UI | 987MB42060C17*** | 24,400 | $2,928 |
| Yes | 205273776 | BRYANT | 284ANV024*0**A* | CNPV*4221AL*+UI | 987MB60060C21*** | 24,400 | $2,928 |
| Yes | 205273798 | BRYANT | 284ANV024*0**A* | CSPH*3612AL*+UI | 987MB42060C17*** | 24,400 | $2,928 |
| Yes | 205273775 | BRYANT | 284ANV024*0**A* | CNPV*4221AL*+UI | 987MB42080C17*** | 24,400 | $2,928 |
| Yes | 205273771 | BRYANT | 284ANV024*0**A* | CNPV*4217AL*+UI | 987MB42080C17*** | 24,400 | $2,928 |
| Yes | 205273765 | BRYANT | 284ANV024*0**A* | CNPV*3621AL*+UI | 987MB60060C21*** | 24,400 | $2,928 |
| Yes | 205273770 | BRYANT | 284ANV024*0**A* | CNPV*4217AL*+UI | 987MB42060C17*** | 24,400 | $2,928 |
| Yes | 205273774 | BRYANT | 284ANV024*0**A* | CNPV*4221AL*+UI | 987MB42060C17*** | 24,400 | $2,928 |
| Yes | 205273764 | BRYANT | 284ANV024*0**A* | CNPV*3621AL*+UI | 987MB42080C17*** | 24,400 | $2,928 |
| Yes | 205273763 | BRYANT | 284ANV024*0**A* | CNPV*3621AL*+UI | 987MB42060C17*** | 24,600 | $2,952 |
| Yes | 205273760 | BRYANT | 284ANV024*0**A* | CNPV*3617AL*+UI | 987MB42080C17*** | 24,400 | $2,928 |
| Yes | 205273759 | BRYANT | 284ANV024*0**A* | CNPV*3617AL*+UI | 987MB42060C17*** | 24,600 | $2,952 |
| Yes | 205273737 | BRYANT | 284ANV024*0**A* | CAP**4224AL*+UI | 987MB60060C21*** | 24,200 | $2,904 |
| Yes | 205273731 | BRYANT | 284ANV024*0**A* | CAP**4221AL*+UI | 987MB42080C17*** | 24,400 | $2,928 |
| Yes | 205273742 | BRYANT | 284ANV024*0**A* | CAP**4821AL*+UI | 987MB42060C17*** | 24,200 | $2,904 |
| Yes | 205273730 | BRYANT | 284ANV024*0**A* | CAP**4221AL*+UI | 987MB42060C17*** | 24,400 | $2,928 |
| Yes | 205273732 | BRYANT | 284ANV024*0**A* | CAP**4221AL*+UI | 987MB60060C21*** | 24,200 | $2,904 |
| Yes | 205273724 | BRYANT | 284ANV024*0**A* | CAP**3621AL*+UI | 987MB42080C17*** | 24,400 | $2,928 |
| Yes | 205273725 | BRYANT | 284ANV024*0**A* | CAP**3621AL*+UI | 987MB60060C21*** | 24,400 | $2,928 |
| Yes | 205273723 | BRYANT | 284ANV024*0**A* | CAP**3621AL*+UI | 987MB42060C17*** | 24,400 | $2,928 |
| Yes | 205273720 | BRYANT | 284ANV024*0**A* | CAP**3617AL*+UI | 987MB42080C17*** | 24,400 | $2,928 |
| Yes | 205273719 | BRYANT | 284ANV024*0**A* | CAP**3617AL*+UI | 987MB42060C17*** | 24,600 | $2,952 |
| Yes | 205274188 | BRYANT | 284ANV036*0**A* | CSPH*6012AL*+UI | 88*TA60110C21*** | 33,000 | $3,960 |
| Yes | 205274187 | BRYANT | 284ANV036*0**A* | CSPH*6012AL*+UI | 88*TA48090C17*** | 33,000 | $3,960 |
| Yes | 205274185 | BRYANT | 284ANV036*0**A* | CSPH*6012AL*+UI | 986TC66100C21*** | 33,000 | $3,960 |
| Yes | 205274178 | BRYANT | 284ANV036*0**A* | CSPH*6012AL*+UI | 986TC66120C24*** | 33,000 | $3,960 |
| Yes | 205274182 | BRYANT | 284ANV036*0**A* | CSPH*6012AL*+UI | 987MB66100C21*** | 33,000 | $3,960 |
| Yes | 205274174 | BRYANT | 284ANV036*0**A* | CSPH*6012AL*+UI | 88*TA60090C21*** | 32,800 | $3,936 |
| Yes | 205274175 | BRYANT | 284ANV036*0**A* | CSPH*6012AL*+UI | 88*TA66135C24*** | 32,800 | $3,936 |
| Yes | 205274113 | BRYANT | 284ANV036*0**A* | CNPV*6024AL*+UI | 987MB60060C21*** | 33,600 | $4,032 |
| Yes | 205274112 | BRYANT | 284ANV036*0**A* | CNPV*6024AL*+UI | 88*TA60110C21*** | 33,000 | $3,960 |
| Yes | 205274111 | BRYANT | 284ANV036*0**A* | CNPV*6024AL*+UI | 986TC66100C21*** | 33,000 | $3,960 |
| Yes | 205274110 | BRYANT | 284ANV036*0**A* | CNPV*6024AL*+UI | 986TC60080C21*** | 33,200 | $3,984 |
| Yes | 205274108 | BRYANT | 284ANV036*0**A* | CNPV*6024AL*+UI | 987MB66100C21*** | 33,000 | $3,960 |
| Yes | 205274106 | BRYANT | 284ANV036*0**A* | CNPV*6024AL*+UI | 986TC66120C24*** | 33,000 | $3,960 |
| Yes | 205274105 | BRYANT | 284ANV036*0**A* | CNPV*6024AL*+UI | 88*TA66135C24*** | 32,800 | $3,936 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205274107 | BRYANT | 284ANV036*0**A* | CNPV*6024AL*+UI | 987MB60080C21*** | 33,200 | $3,984 |
| Yes | 205274109 | BRYANT | 284ANV036*0**A* | CNPV*6024AL*+UI | 987MB66120C24*** | 33,200 | $3,984 |
| Yes | 205274104 | BRYANT | 284ANV036*0**A* | CNPV*6024AL*+UI | 88*TA60090C21*** | 33,000 | $3,960 |
| Yes | 205274103 | BRYANT | 284ANV036*0**A* | CNPV*6024AL*+UI | 88*TA60070C21*** | 33,200 | $3,984 |
| Yes | 205274100 | BRYANT | 284ANV036*0**A* | CNPV*4824AL*+UI | 986TC66100C21*** | 33,400 | $4,008 |
| Yes | 205274099 | BRYANT | 284ANV036*0**A* | CNPV*4824AL*+UI | 986TC60080C21*** | 33,600 | $4,032 |
| Yes | 205274098 | BRYANT | 284ANV036*0**A* | CNPV*4824AL*+UI | 987MB66120C24*** | 33,400 | $4,008 |
| Yes | 205274096 | BRYANT | 284ANV036*0**A* | CNPV*4824AL*+UI | 987MB60080C21*** | 33,600 | $4,032 |
| Yes | 205274101 | BRYANT | 284ANV036*0**A* | CNPV*4824AL*+UI | 88*TA60110C21*** | 33,400 | $4,008 |
| Yes | 205274097 | BRYANT | 284ANV036*0**A* | CNPV*4824AL*+UI | 987MB66100C21*** | 33,400 | $4,008 |
| Yes | 205274094 | BRYANT | 284ANV036*0**A* | CNPV*4824AL*+UI | 88*TA66135C24*** | 33,200 | $3,984 |
| Yes | 205274095 | BRYANT | 284ANV036*0**A* | CNPV*4824AL*+UI | 986TC66120C24*** | 33,400 | $4,008 |
| Yes | 205274093 | BRYANT | 284ANV036*0**A* | CNPV*4824AL*+UI | 88*TA60090C21*** | 33,400 | $4,008 |
| Yes | 205274092 | BRYANT | 284ANV036*0**A* | CNPV*4824AL*+UI | 88*TA60070C21*** | 33,600 | $4,032 |
| Yes | 205274089 | BRYANT | 284ANV036*0**A* | CNPV*4821AL*+UI | 88*TA48090C17*** | 33,400 | $4,008 |
| Yes | 205274090 | BRYANT | 284ANV036*0**A* | CNPV*4821AL*+UI | 88*TA60110C21*** | 33,400 | $4,008 |
| Yes | 205274087 | BRYANT | 284ANV036*0**A* | CNPV*4821AL*+UI | 986TC60080C21*** | 33,600 | $4,032 |
| Yes | 205274086 | BRYANT | 284ANV036*0**A* | CNPV*4821AL*+UI | 987MB66100C21*** | 33,400 | $4,008 |
| Yes | 205274085 | BRYANT | 284ANV036*0**A* | CNPV*4821AL*+UI | 987MB60080C21*** | 33,600 | $4,032 |
| Yes | 205274079 | BRYANT | 284ANV036*0**A* | CNPV*4821AL*+UI | 88*TA60070C21*** | 33,600 | $4,032 |
| Yes | 205274088 | BRYANT | 284ANV036*0**A* | CNPV*4821AL*+UI | 986TC66100C21*** | 33,400 | $4,008 |
| Yes | 205274080 | BRYANT | 284ANV036*0**A* | CNPV*4821AL*+UI | 88*TA60090C21*** | 33,400 | $4,008 |
| Yes | 205274071 | BRYANT | 284ANV036*0**A* | CNPV*4221AL*+UI | 987MB66100C21*** | 33,800 | $4,056 |
| Yes | 205274051 | BRYANT | 284ANV036*0**A* | CAP**6124AL*+UI | 986TC66100C21*** | 33,000 | $3,960 |
| Yes | 205274052 | BRYANT | 284ANV036*0**A* | CAP**6124AL*+UI | 88*TA60110C21*** | 33,000 | $3,960 |
| Yes | 205274050 | BRYANT | 284ANV036*0**A* | CAP**6124AL*+UI | 986TC60080C21*** | 33,200 | $3,984 |
| Yes | 205274048 | BRYANT | 284ANV036*0**A* | CAP**6124AL*+UI | 987MB66100C21*** | 33,000 | $3,960 |
| Yes | 205274046 | BRYANT | 284ANV036*0**A* | CAP**6124AL*+UI | 986TC66120C24*** | 33,000 | $3,960 |
| Yes | 205274049 | BRYANT | 284ANV036*0**A* | CAP**6124AL*+UI | 987MB66120C24*** | 33,000 | $3,960 |
| Yes | 205274047 | BRYANT | 284ANV036*0**A* | CAP**6124AL*+UI | 987MB60080C21*** | 33,200 | $3,984 |
| Yes | 205274045 | BRYANT | 284ANV036*0**A* | CAP**6124AL*+UI | 88*TA66135C24*** | 32,800 | $3,936 |
| Yes | 205274044 | BRYANT | 284ANV036*0**A* | CAP**6124AL*+UI | 88*TA60090C21*** | 33,000 | $3,960 |
| Yes | 205274039 | BRYANT | 284ANV036*0**A* | CAP**6121AL*+UI | 986TC66100C21*** | 33,000 | $3,960 |
| Yes | 205274040 | BRYANT | 284ANV036*0**A* | CAP**6121AL*+UI | 88*TA48090C17*** | 33,200 | $3,984 |
| Yes | 205274043 | BRYANT | 284ANV036*0**A* | CAP**6124AL*+UI | 88*TA60070C21*** | 33,200 | $3,984 |
| Yes | 205274041 | BRYANT | 284ANV036*0**A* | CAP**6121AL*+UI | 88*TA60110C21*** | 33,000 | $3,960 |
| Yes | 205274038 | BRYANT | 284ANV036*0**A* | CAP**6121AL*+UI | 986TC60080C21*** | 33,200 | $3,984 |
| Yes | 205274036 | BRYANT | 284ANV036*0**A* | CAP**6121AL*+UI | 987MB60080C21*** | 33,200 | $3,984 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205274037 | BRYANT | 284ANV036*0**A* | CAP**6121AL*+UI | 987MB66100C21*** | 33,000 | $3,960 |
| Yes | 205274030 | BRYANT | 284ANV036*0**A* | CAP**6121AL*+UI | 88*TA60070C21*** | 33,200 | $3,984 |
| Yes | 205274031 | BRYANT | 284ANV036*0**A* | CAP**6121AL*+UI | 88*TA60090C21*** | 33,000 | $3,960 |
| Yes | 205274029 | BRYANT | 284ANV036*0**A* | CAP**6121AL*+UI | 88*TA48070C17*** | 33,400 | $4,008 |
| Yes | 205274026 | BRYANT | 284ANV036*0**A* | CAP**6024AL*+UI | 88*TA60110C21*** | 32,800 | $3,936 |
| Yes | 205274025 | BRYANT | 284ANV036*0**A* | CAP**6024AL*+UI | 986TC66100C21*** | 32,800 | $3,936 |
| Yes | 205274024 | BRYANT | 284ANV036*0**A* | CAP**6024AL*+UI | 986TC60080C21*** | 33,000 | $3,960 |
| Yes | 205274023 | BRYANT | 284ANV036*0**A* | CAP**6024AL*+UI | 987MB66120C24*** | 33,000 | $3,960 |
| Yes | 205274022 | BRYANT | 284ANV036*0**A* | CAP**6024AL*+UI | 987MB66100C21*** | 32,800 | $3,936 |
| Yes | 205274021 | BRYANT | 284ANV036*0**A* | CAP**6024AL*+UI | 987MB60080C21*** | 33,000 | $3,960 |
| Yes | 205274020 | BRYANT | 284ANV036*0**A* | CAP**6024AL*+UI | 986TC66120C24*** | 32,800 | $3,936 |
| Yes | 205274019 | BRYANT | 284ANV036*0**A* | CAP**6024AL*+UI | 88*TA66135C24*** | 32,600 | $3,912 |
| Yes | 205274018 | BRYANT | 284ANV036*0**A* | CAP**6024AL*+UI | 88*TA60090C21*** | 32,800 | $3,936 |
| Yes | 205274015 | BRYANT | 284ANV036*0**A* | CAP**4824AL*+UI | 88*TA60110C21*** | 33,200 | $3,984 |
| Yes | 205274008 | BRYANT | 284ANV036*0**A* | CAP**4824AL*+UI | 88*TA66135C24*** | 33,000 | $3,960 |
| Yes | 205274007 | BRYANT | 284ANV036*0**A* | CAP**4824AL*+UI | 88*TA60090C21*** | 33,200 | $3,984 |
| Yes | 205273989 | BRYANT | 284ANV036*0**A* | CAP**4321AL*+UI | 88*TA60110C21*** | 33,400 | $4,008 |
| Yes | 205273988 | BRYANT | 284ANV036*0**A* | CAP**4321AL*+UI | 88*TA48090C17*** | 33,600 | $4,032 |
| Yes | 205273809 | BRYANT | 284ANV024*0**A* | CSPH*4212AL*+UI | 987MB60060C21*** | 24,200 | $2,904 |
| Yes | 205273808 | BRYANT | 284ANV024*0**A* | CSPH*4212AL*+UI | 987MB42080C17*** | 24,200 | $2,904 |
| Yes | 205273891 | BRYANT | 284ANV024*0**A* | CNPV*4821AL*+UI | 88*TA60090C21*** | 24,000 | $2,880 |
| Yes | 205273890 | BRYANT | 284ANV024*0**A* | CNPV*4821AL*+UI | 88*TA60070C21*** | 24,200 | $2,904 |
| Yes | 205273888 | BRYANT | 284ANV024*0**A* | CNPV*4821AL*+UI | 88*TA36045C17*** | 24,200 | $2,904 |
| Yes | 205273887 | BRYANT | 284ANV024*0**A* | CNPV*4221AL*+UI | 986TC42080C17*** | 24,400 | $2,928 |
| Yes | 205273886 | BRYANT | 284ANV024*0**A* | CNPV*4221AL*+UI | 986TC42060C17*** | 24,400 | $2,928 |
| Yes | 205273889 | BRYANT | 284ANV024*0**A* | CNPV*4821AL*+UI | 88*TA48070C17*** | 24,200 | $2,904 |
| Yes | 205273885 | BRYANT | 284ANV024*0**A* | CNPV*4221AL*+UI | 88*TA60090C21*** | 24,200 | $2,904 |
| Yes | 205273883 | BRYANT | 284ANV024*0**A* | CNPV*4221AL*+UI | 88*TA48070C17*** | 24,400 | $2,928 |
| Yes | 205273884 | BRYANT | 284ANV024*0**A* | CNPV*4221AL*+UI | 88*TA60070C21*** | 24,200 | $2,904 |
| Yes | 205273882 | BRYANT | 284ANV024*0**A* | CNPV*4221AL*+UI | 88*TA36045C17*** | 24,400 | $2,928 |
| Yes | 205273881 | BRYANT | 284ANV024*0**A* | CNPV*4217AL*+UI | 986TC42080C17*** | 24,400 | $2,928 |
| Yes | 205273880 | BRYANT | 284ANV024*0**A* | CNPV*4217AL*+UI | 986TC42060C17*** | 24,400 | $2,928 |
| Yes | 205273879 | BRYANT | 284ANV024*0**A* | CNPV*4217AL*+UI | 88*TA48070C17*** | 24,200 | $2,904 |
| Yes | 205273877 | BRYANT | 284ANV024*0**A* | CNPV*3621AL*+UI | 986TC42080C17*** | 24,400 | $2,928 |
| Yes | 205273876 | BRYANT | 284ANV024*0**A* | CNPV*3621AL*+UI | 986TC42060C17*** | 24,600 | $2,952 |
| Yes | 205273874 | BRYANT | 284ANV024*0**A* | CNPV*3621AL*+UI | 88*TA60070C21*** | 24,400 | $2,928 |
| Yes | 205273878 | BRYANT | 284ANV024*0**A* | CNPV*4217AL*+UI | 88*TA36045C17*** | 24,400 | $2,928 |
| Yes | 205273875 | BRYANT | 284ANV024*0**A* | CNPV*3621AL*+UI | 88*TA60090C21*** | 24,200 | $2,904 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205273872 | BRYANT | 284ANV024*0**A* | CNPV*3621AL*+UI | 88*TA36045C17*** | 24,600 | $2,952 |
| Yes | 205273873 | BRYANT | 284ANV024*0**A* | CNPV*3621AL*+UI | 88*TA48070C17*** | 24,400 | $2,928 |
| Yes | 205273871 | BRYANT | 284ANV024*0**A* | CNPV*3617AL*+UI | 986TC42080C17*** | 24,400 | $2,928 |
| Yes | 205273870 | BRYANT | 284ANV024*0**A* | CNPV*3617AL*+UI | 986TC42060C17*** | 24,600 | $2,952 |
| Yes | 205273869 | BRYANT | 284ANV024*0**A* | CNPV*3617AL*+UI | 88*TA48070C17*** | 24,400 | $2,928 |
| Yes | 205273868 | BRYANT | 284ANV024*0**A* | CNPV*3617AL*+UI | 88*TA36045C17*** | 24,600 | $2,952 |
| Yes | 205273867 | BRYANT | 284ANV024*0**A* | CAP**6024AL*+UI | 986TC66120C24*** | 23,600 | $2,832 |
| Yes | 205273866 | BRYANT | 284ANV024*0**A* | CAP**6024AL*+UI | 88*TA66135C24*** | 23,600 | $2,832 |
| Yes | 205273863 | BRYANT | 284ANV024*0**A* | CAP**4824AL*+UI | 986TC66120C24*** | 24,000 | $2,880 |
| Yes | 205273864 | BRYANT | 284ANV024*0**A* | CAP**6024AL*+UI | 88*TA60070C21*** | 23,600 | $2,832 |
| Yes | 205273865 | BRYANT | 284ANV024*0**A* | CAP**6024AL*+UI | 88*TA60090C21*** | 23,600 | $2,832 |
| Yes | 205273862 | BRYANT | 284ANV024*0**A* | CAP**4824AL*+UI | 88*TA66135C24*** | 23,800 | $2,856 |
| Yes | 205273861 | BRYANT | 284ANV024*0**A* | CAP**4824AL*+UI | 88*TA60090C21*** | 23,800 | $2,856 |
| Yes | 205273860 | BRYANT | 284ANV024*0**A* | CAP**4824AL*+UI | 88*TA60070C21*** | 24,000 | $2,880 |
| Yes | 205273859 | BRYANT | 284ANV024*0**A* | CAP**4821AL*+UI | 986TC42080C17*** | 24,000 | $2,880 |
| Yes | 205273858 | BRYANT | 284ANV024*0**A* | CAP**4821AL*+UI | 986TC42060C17*** | 24,200 | $2,904 |
| Yes | 205273857 | BRYANT | 284ANV024*0**A* | CAP**4821AL*+UI | 88*TA60090C21*** | 23,800 | $2,856 |
| Yes | 205273856 | BRYANT | 284ANV024*0**A* | CAP**4821AL*+UI | 88*TA60070C21*** | 24,000 | $2,880 |
| Yes | 205273855 | BRYANT | 284ANV024*0**A* | CAP**4821AL*+UI | 88*TA48070C17*** | 24,000 | $2,880 |
| Yes | 205273854 | BRYANT | 284ANV024*0**A* | CAP**4821AL*+UI | 88*TA36045C17*** | 24,200 | $2,904 |
| Yes | 205273852 | BRYANT | 284ANV024*0**A* | CAP**4224AL*+UI | 88*TA66135C24*** | 24,000 | $2,880 |
| Yes | 205273853 | BRYANT | 284ANV024*0**A* | CAP**4224AL*+UI | 986TC66120C24*** | 24,200 | $2,904 |
| Yes | 205273851 | BRYANT | 284ANV024*0**A* | CAP**4224AL*+UI | 88*TA60090C21*** | 24,200 | $2,904 |
| Yes | 205273850 | BRYANT | 284ANV024*0**A* | CAP**4224AL*+UI | 88*TA60070C21*** | 24,200 | $2,904 |
| Yes | 205273849 | BRYANT | 284ANV024*0**A* | CAP**4221AL*+UI | 986TC42080C17*** | 24,400 | $2,928 |
| Yes | 205273848 | BRYANT | 284ANV024*0**A* | CAP**4221AL*+UI | 986TC42060C17*** | 24,400 | $2,928 |
| Yes | 205273846 | BRYANT | 284ANV024*0**A* | CAP**4221AL*+UI | 88*TA60070C21*** | 24,200 | $2,904 |
| Yes | 205273847 | BRYANT | 284ANV024*0**A* | CAP**4221AL*+UI | 88*TA60090C21*** | 24,200 | $2,904 |
| Yes | 205273845 | BRYANT | 284ANV024*0**A* | CAP**4221AL*+UI | 88*TA48070C17*** | 24,200 | $2,904 |
| Yes | 205273844 | BRYANT | 284ANV024*0**A* | CAP**4221AL*+UI | 88*TA36045C17*** | 24,400 | $2,928 |
| Yes | 205273842 | BRYANT | 284ANV024*0**A* | CAP**3621AL*+UI | 986TC42060C17*** | 24,400 | $2,928 |
| Yes | 205273843 | BRYANT | 284ANV024*0**A* | CAP**3621AL*+UI | 986TC42080C17*** | 24,400 | $2,928 |
| Yes | 205273840 | BRYANT | 284ANV024*0**A* | CAP**3621AL*+UI | 88*TA60070C21*** | 24,200 | $2,904 |
| Yes | 205273841 | BRYANT | 284ANV024*0**A* | CAP**3621AL*+UI | 88*TA60090C21*** | 24,200 | $2,904 |
| Yes | 205273838 | BRYANT | 284ANV024*0**A* | CAP**3621AL*+UI | 88*TA36045C17*** | 24,400 | $2,928 |
| Yes | 205273839 | BRYANT | 284ANV024*0**A* | CAP**3621AL*+UI | 88*TA48070C17*** | 24,200 | $2,904 |
| Yes | 205273837 | BRYANT | 284ANV024*0**A* | CAP**3617AL*+UI | 986TC42080C17*** | 24,400 | $2,928 |
| Yes | 205273836 | BRYANT | 284ANV024*0**A* | CAP**3617AL*+UI | 986TC42060C17*** | 24,400 | $2,928 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205273835 | BRYANT | 284ANV024*0**A* | CAP**3617AL*+UI | 88*TA48070C17*** | 24,400 | $2,928 |
| Yes | 205273834 | BRYANT | 284ANV024*0**A* | CAP**3617AL*+UI | 88*TA36045C17*** | 24,400 | $2,928 |
| Yes | 205273832 | BRYANT | 284ANV024*0**A* | CSPH*6012AL*+UI | 88*TA48090C17*** | 23,800 | $2,856 |
| Yes | 205273833 | BRYANT | 284ANV024*0**A* | CSPH*6012AL*+UI | 88*TA60110C21*** | 23,800 | $2,856 |
| Yes | 205273831 | BRYANT | 284ANV024*0**A* | CSPH*6012AL*+UI | 88*TA36070C14*** | 23,800 | $2,856 |
| Yes | 205273827 | BRYANT | 284ANV024*0**A* | CSPH*6012AL*+UI | 987MB60060C21*** | 23,800 | $2,856 |
| Yes | 205273830 | BRYANT | 284ANV024*0**A* | CSPH*6012AL*+UI | 987MB66120C24*** | 23,800 | $2,856 |
| Yes | 205273829 | BRYANT | 284ANV024*0**A* | CSPH*6012AL*+UI | 987MB66100C21*** | 23,800 | $2,856 |
| Yes | 205273828 | BRYANT | 284ANV024*0**A* | CSPH*6012AL*+UI | 987MB60080C21*** | 23,800 | $2,856 |
| Yes | 205273824 | BRYANT | 284ANV024*0**A* | CSPH*4812AL*+UI | 88*TA60110C21*** | 24,000 | $2,880 |
| Yes | 205273826 | BRYANT | 284ANV024*0**A* | CSPH*6012AL*+UI | 987MB42080C17*** | 24,000 | $2,880 |
| Yes | 205273823 | BRYANT | 284ANV024*0**A* | CSPH*4812AL*+UI | 88*TA48090C17*** | 24,000 | $2,880 |
| Yes | 205273821 | BRYANT | 284ANV024*0**A* | CSPH*4812AL*+UI | 987MB66120C24*** | 24,000 | $2,880 |
| Yes | 205273822 | BRYANT | 284ANV024*0**A* | CSPH*4812AL*+UI | 88*TA36070C14*** | 24,200 | $2,904 |
| Yes | 205273820 | BRYANT | 284ANV024*0**A* | CSPH*4812AL*+UI | 987MB66100C21*** | 24,000 | $2,880 |
| Yes | 205273814 | BRYANT | 284ANV024*0**A* | CSPH*4212AL*+UI | 88*TA48090C17*** | 24,000 | $2,880 |
| Yes | 205273815 | BRYANT | 284ANV024*0**A* | CSPH*4212AL*+UI | 88*TA60110C21*** | 24,000 | $2,880 |
| Yes | 205273813 | BRYANT | 284ANV024*0**A* | CSPH*4212AL*+UI | 88*TA36070C14*** | 24,200 | $2,904 |
| Yes | 205273811 | BRYANT | 284ANV024*0**A* | CSPH*4212AL*+UI | 987MB66100C21*** | 24,000 | $2,880 |
| Yes | 205273819 | BRYANT | 284ANV024*0**A* | CSPH*4812AL*+UI | 987MB60080C21*** | 24,000 | $2,880 |
| Yes | 205273812 | BRYANT | 284ANV024*0**A* | CSPH*4212AL*+UI | 987MB66120C24*** | 24,200 | $2,904 |
| Yes | 205273810 | BRYANT | 284ANV024*0**A* | CSPH*4212AL*+UI | 987MB60080C21*** | 24,200 | $2,904 |
| Yes | 205273934 | BRYANT | 284ANV036*0**A* | FE4AN(B,F)005L+UI | | 32,800 | $3,936 |
| Yes | 205273936 | BRYANT | 284ANV036*0**A* | FE4ANB006L+UI | | 32,400 | $3,888 |
| Yes | 205273795 | BRYANT | 284ANV024*0**A* | CNPV*6024AL*+UI | 987MB66100C21*** | 23,800 | $2,856 |
| Yes | 205273796 | BRYANT | 284ANV024*0**A* | CNPV*6024AL*+UI | 987MB66120C24*** | 23,800 | $2,856 |
| Yes | 205273793 | BRYANT | 284ANV024*0**A* | CNPV*6024AL*+UI | 987MB60060C21*** | 24,000 | $2,880 |
| Yes | 205273794 | BRYANT | 284ANV024*0**A* | CNPV*6024AL*+UI | 987MB60080C21*** | 23,800 | $2,856 |
| Yes | 205273792 | BRYANT | 284ANV024*0**A* | CNPV*4824AL*+UI | 88*TA60110C21*** | 24,000 | $2,880 |
| Yes | 205273791 | BRYANT | 284ANV024*0**A* | CNPV*4824AL*+UI | 987MB66120C24*** | 24,000 | $2,880 |
| Yes | 205273790 | BRYANT | 284ANV024*0**A* | CNPV*4824AL*+UI | 987MB66100C21*** | 24,000 | $2,880 |
| Yes | 205273788 | BRYANT | 284ANV024*0**A* | CNPV*4824AL*+UI | 987MB60060C21*** | 24,200 | $2,904 |
| Yes | 205273787 | BRYANT | 284ANV024*0**A* | CNPV*4821AL*+UI | 88*TA60110C21*** | 24,000 | $2,880 |
| Yes | 205273789 | BRYANT | 284ANV024*0**A* | CNPV*4824AL*+UI | 987MB60080C21*** | 24,000 | $2,880 |
| Yes | 205273785 | BRYANT | 284ANV024*0**A* | CNPV*4821AL*+UI | 987MB66100C21*** | 24,000 | $2,880 |
| Yes | 205273784 | BRYANT | 284ANV024*0**A* | CNPV*4821AL*+UI | 987MB60080C21*** | 24,000 | $2,880 |
| Yes | 205273783 | BRYANT | 284ANV024*0**A* | CNPV*4821AL*+UI | 987MB60060C21*** | 24,200 | $2,904 |
| Yes | 205273786 | BRYANT | 284ANV024*0**A* | CNPV*4821AL*+UI | 88*TA48090C17*** | 24,000 | $2,880 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205273782 | BRYANT | 284ANV024*0**A* | CNPV*4821AL*+UI | 987MB42080C17*** | 24,200 | $2,904 |
| Yes | 205273780 | BRYANT | 284ANV024*0**A* | CNPV*4221AL*+UI | 88*TA60110C21*** | 24,200 | $2,904 |
| Yes | 205273779 | BRYANT | 284ANV024*0**A* | CNPV*4221AL*+UI | 88*TA48090C17*** | 24,200 | $2,904 |
| Yes | 205273778 | BRYANT | 284ANV024*0**A* | CNPV*4221AL*+UI | 987MB66100C21*** | 24,200 | $2,904 |
| Yes | 205273777 | BRYANT | 284ANV024*0**A* | CNPV*4221AL*+UI | 987MB60080C21*** | 24,200 | $2,904 |
| Yes | 205273773 | BRYANT | 284ANV024*0**A* | CNPV*4217AL*+UI | 88*TA48090C17*** | 24,200 | $2,904 |
| Yes | 205273772 | BRYANT | 284ANV024*0**A* | CNPV*4217AL*+UI | 88*TA36070C14*** | 24,200 | $2,904 |
| Yes | 205273769 | BRYANT | 284ANV024*0**A* | CNPV*3621AL*+UI | 88*TA60110C21*** | 24,200 | $2,904 |
| Yes | 205273768 | BRYANT | 284ANV024*0**A* | CNPV*3621AL*+UI | 88*TA48090C17*** | 24,200 | $2,904 |
| Yes | 205273767 | BRYANT | 284ANV024*0**A* | CNPV*3621AL*+UI | 987MB66100C21*** | 24,400 | $2,928 |
| Yes | 205273766 | BRYANT | 284ANV024*0**A* | CNPV*3621AL*+UI | 987MB60080C21*** | 24,400 | $2,928 |
| Yes | 205273762 | BRYANT | 284ANV024*0**A* | CNPV*3617AL*+UI | 88*TA48090C17*** | 24,200 | $2,904 |
| Yes | 205273761 | BRYANT | 284ANV024*0**A* | CNPV*3617AL*+UI | 88*TA36070C14*** | 24,400 | $2,928 |
| Yes | 205273757 | BRYANT | 284ANV024*0**A* | CAP**6024AL*+UI | 987MB66120C24*** | 23,600 | $2,832 |
| Yes | 205273756 | BRYANT | 284ANV024*0**A* | CAP**6024AL*+UI | 987MB66100C21*** | 23,600 | $2,832 |
| Yes | 205273754 | BRYANT | 284ANV024*0**A* | CAP**6024AL*+UI | 987MB60060C21*** | 23,800 | $2,856 |
| Yes | 205273755 | BRYANT | 284ANV024*0**A* | CAP**6024AL*+UI | 987MB60080C21*** | 23,600 | $2,832 |
| Yes | 205273758 | BRYANT | 284ANV024*0**A* | CAP**6024AL*+UI | 88*TA60110C21*** | 23,600 | $2,832 |
| Yes | 205273753 | BRYANT | 284ANV024*0**A* | CAP**4824AL*+UI | 88*TA60110C21*** | 23,800 | $2,856 |
| Yes | 205273752 | BRYANT | 284ANV024*0**A* | CAP**4824AL*+UI | 987MB66120C24*** | 24,000 | $2,880 |
| Yes | 205273751 | BRYANT | 284ANV024*0**A* | CAP**4824AL*+UI | 987MB66100C21*** | 23,800 | $2,856 |
| Yes | 205273750 | BRYANT | 284ANV024*0**A* | CAP**4824AL*+UI | 987MB60080C21*** | 24,000 | $2,880 |
| Yes | 205273749 | BRYANT | 284ANV024*0**A* | CAP**4824AL*+UI | 987MB60060C21*** | 24,000 | $2,880 |
| Yes | 205273748 | BRYANT | 284ANV024*0**A* | CAP**4821AL*+UI | 88*TA60110C21*** | 23,800 | $2,856 |
| Yes | 205273747 | BRYANT | 284ANV024*0**A* | CAP**4821AL*+UI | 88*TA48090C17*** | 23,800 | $2,856 |
| Yes | 205273746 | BRYANT | 284ANV024*0**A* | CAP**4821AL*+UI | 987MB66100C21*** | 24,000 | $2,880 |
| Yes | 205273745 | BRYANT | 284ANV024*0**A* | CAP**4821AL*+UI | 987MB60080C21*** | 24,000 | $2,880 |
| Yes | 205273744 | BRYANT | 284ANV024*0**A* | CAP**4821AL*+UI | 987MB60060C21*** | 24,000 | $2,880 |
| Yes | 205273741 | BRYANT | 284ANV024*0**A* | CAP**4224AL*+UI | 88*TA60110C21*** | 24,200 | $2,904 |
| Yes | 205273739 | BRYANT | 284ANV024*0**A* | CAP**4224AL*+UI | 987MB66100C21*** | 24,200 | $2,904 |
| Yes | 205273740 | BRYANT | 284ANV024*0**A* | CAP**4224AL*+UI | 987MB66120C24*** | 24,200 | $2,904 |
| Yes | 205273738 | BRYANT | 284ANV024*0**A* | CAP**4224AL*+UI | 987MB60080C21*** | 24,200 | $2,904 |
| Yes | 205273743 | BRYANT | 284ANV024*0**A* | CAP**4821AL*+UI | 987MB42080C17*** | 24,000 | $2,880 |
| Yes | 205273736 | BRYANT | 284ANV024*0**A* | CAP**4221AL*+UI | 88*TA60110C21*** | 24,200 | $2,904 |
| Yes | 205273735 | BRYANT | 284ANV024*0**A* | CAP**4221AL*+UI | 88*TA48090C17*** | 24,200 | $2,904 |
| Yes | 205273734 | BRYANT | 284ANV024*0**A* | CAP**4221AL*+UI | 987MB66100C21*** | 24,200 | $2,904 |
| Yes | 205273733 | BRYANT | 284ANV024*0**A* | CAP**4221AL*+UI | 987MB60080C21*** | 24,200 | $2,904 |
| Yes | 205273729 | BRYANT | 284ANV024*0**A* | CAP**3621AL*+UI | 88*TA60110C21*** | 24,200 | $2,904 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205273727 | BRYANT | 284ANV024*0**A* | CAP**3621AL*+UI | 987MB66100C21*** | 24,200 | $2,904 |
| Yes | 205273728 | BRYANT | 284ANV024*0**A* | CAP**3621AL*+UI | 88*TA48090C17*** | 24,200 | $2,904 |
| Yes | 205273722 | BRYANT | 284ANV024*0**A* | CAP**3617AL*+UI | 88*TA48090C17*** | 24,200 | $2,904 |
| Yes | 205273726 | BRYANT | 284ANV024*0**A* | CAP**3621AL*+UI | 987MB60080C21*** | 24,200 | $2,904 |
| Yes | 205273721 | BRYANT | 284ANV024*0**A* | CAP**3617AL*+UI | 88*TA36070C14*** | 24,400 | $2,928 |
| Yes | 205273716 | BRYANT | 284ANV024*0**A* | FE4ANF002L+UI | | 24,400 | $2,928 |
| Yes | 205273933 | BRYANT | 284ANV024*0**A* | CSPH*6012AL*+UI | 986TC66120C24*** | 23,800 | $2,856 |
| Yes | 205273932 | BRYANT | 284ANV024*0**A* | CSPH*6012AL*+UI | 986TC42080C17*** | 24,000 | $2,880 |
| Yes | 205273930 | BRYANT | 284ANV024*0**A* | CSPH*6012AL*+UI | 88*TA66135C24*** | 23,800 | $2,856 |
| Yes | 205273931 | BRYANT | 284ANV024*0**A* | CSPH*6012AL*+UI | 986TC42060C17*** | 24,000 | $2,880 |
| Yes | 205273928 | BRYANT | 284ANV024*0**A* | CSPH*6012AL*+UI | 88*TA60070C21*** | 23,800 | $2,856 |
| Yes | 205273929 | BRYANT | 284ANV024*0**A* | CSPH*6012AL*+UI | 88*TA60090C21*** | 23,800 | $2,856 |
| Yes | 205273926 | BRYANT | 284ANV024*0**A* | CSPH*6012AL*+UI | 88*TA36045C17*** | 24,000 | $2,880 |
| Yes | 205273927 | BRYANT | 284ANV024*0**A* | CSPH*6012AL*+UI | 88*TA48070C17*** | 23,800 | $2,856 |
| Yes | 205273924 | BRYANT | 284ANV024*0**A* | CSPH*4812AL*+UI | 986TC42080C17*** | 24,200 | $2,904 |
| Yes | 205273925 | BRYANT | 284ANV024*0**A* | CSPH*4812AL*+UI | 986TC66120C24*** | 24,000 | $2,880 |
| Yes | 205273922 | BRYANT | 284ANV024*0**A* | CSPH*4812AL*+UI | 88*TA66135C24*** | 24,000 | $2,880 |
| Yes | 205273921 | BRYANT | 284ANV024*0**A* | CSPH*4812AL*+UI | 88*TA60090C21*** | 24,000 | $2,880 |
| Yes | 205273920 | BRYANT | 284ANV024*0**A* | CSPH*4812AL*+UI | 88*TA60070C21*** | 24,200 | $2,904 |
| Yes | 205273919 | BRYANT | 284ANV024*0**A* | CSPH*4812AL*+UI | 88*TA48070C17*** | 24,200 | $2,904 |
| Yes | 205273917 | BRYANT | 284ANV024*0**A* | CSPH*4212AL*+UI | 986TC66120C24*** | 24,200 | $2,904 |
| Yes | 205273918 | BRYANT | 284ANV024*0**A* | CSPH*4812AL*+UI | 88*TA36045C17*** | 24,200 | $2,904 |
| Yes | 205273923 | BRYANT | 284ANV024*0**A* | CSPH*4812AL*+UI | 986TC42060C17*** | 24,200 | $2,904 |
| Yes | 205273916 | BRYANT | 284ANV024*0**A* | CSPH*4212AL*+UI | 986TC42080C17*** | 24,200 | $2,904 |
| Yes | 205273915 | BRYANT | 284ANV024*0**A* | CSPH*4212AL*+UI | 986TC42060C17*** | 24,400 | $2,928 |
| Yes | 205273913 | BRYANT | 284ANV024*0**A* | CSPH*4212AL*+UI | 88*TA60090C21*** | 24,000 | $2,880 |
| Yes | 205273914 | BRYANT | 284ANV024*0**A* | CSPH*4212AL*+UI | 88*TA66135C24*** | 24,000 | $2,880 |
| Yes | 205273911 | BRYANT | 284ANV024*0**A* | CSPH*4212AL*+UI | 88*TA48070C17*** | 24,200 | $2,904 |
| Yes | 205273912 | BRYANT | 284ANV024*0**A* | CSPH*4212AL*+UI | 88*TA60070C21*** | 24,200 | $2,904 |
| Yes | 205273909 | BRYANT | 284ANV024*0**A* | CSPH*3612AL*+UI | 986TC66120C24*** | 24,200 | $2,904 |
| Yes | 205273910 | BRYANT | 284ANV024*0**A* | CSPH*4212AL*+UI | 88*TA36045C17*** | 24,400 | $2,928 |
| Yes | 205273908 | BRYANT | 284ANV024*0**A* | CSPH*3612AL*+UI | 986TC42080C17*** | 24,400 | $2,928 |
| Yes | 205273906 | BRYANT | 284ANV024*0**A* | CSPH*3612AL*+UI | 88*TA66135C24*** | 24,200 | $2,904 |
| Yes | 205273905 | BRYANT | 284ANV024*0**A* | CSPH*3612AL*+UI | 88*TA60090C21*** | 24,200 | $2,904 |
| Yes | 205273907 | BRYANT | 284ANV024*0**A* | CSPH*3612AL*+UI | 986TC42060C17*** | 24,400 | $2,928 |
| Yes | 205273902 | BRYANT | 284ANV024*0**A* | CSPH*3612AL*+UI | 88*TA36045C17*** | 24,400 | $2,928 |
| Yes | 205273904 | BRYANT | 284ANV024*0**A* | CSPH*3612AL*+UI | 88*TA60070C21*** | 24,200 | $2,904 |
| Yes | 205273903 | BRYANT | 284ANV024*0**A* | CSPH*3612AL*+UI | 88*TA48070C17*** | 24,200 | $2,904 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205273901 | BRYANT | 284ANV024*0**A* | CNPV*6024AL*+UI | 986TC66120C24*** | 23,800 | $2,856 |
| Yes | 205273899 | BRYANT | 284ANV024*0**A* | CNPV*6024AL*+UI | 88*TA60090C21*** | 23,800 | $2,856 |
| Yes | 205273896 | BRYANT | 284ANV024*0**A* | CNPV*4824AL*+UI | 88*TA66135C24*** | 24,000 | $2,880 |
| Yes | 205273900 | BRYANT | 284ANV024*0**A* | CNPV*6024AL*+UI | 88*TA66135C24*** | 23,800 | $2,856 |
| Yes | 205273898 | BRYANT | 284ANV024*0**A* | CNPV*6024AL*+UI | 88*TA60070C21*** | 23,800 | $2,856 |
| Yes | 205273897 | BRYANT | 284ANV024*0**A* | CNPV*4824AL*+UI | 986TC66120C24*** | 24,000 | $2,880 |
| Yes | 205273895 | BRYANT | 284ANV024*0**A* | CNPV*4824AL*+UI | 88*TA60090C21*** | 24,000 | $2,880 |
| Yes | 205273894 | BRYANT | 284ANV024*0**A* | CNPV*4824AL*+UI | 88*TA60070C21*** | 24,200 | $2,904 |
| Yes | 205273893 | BRYANT | 284ANV024*0**A* | CNPV*4821AL*+UI | 986TC42080C17*** | 24,200 | $2,904 |
| Yes | 205273892 | BRYANT | 284ANV024*0**A* | CNPV*4821AL*+UI | 986TC42060C17*** | 24,200 | $2,904 |
| Yes | 205273806 | BRYANT | 284ANV024*0**A* | CSPH*3612AL*+UI | 88*TA60110C21*** | 24,200 | $2,904 |
| Yes | 205273805 | BRYANT | 284ANV024*0**A* | CSPH*3612AL*+UI | 88*TA48090C17*** | 24,200 | $2,904 |
| Yes | 205273803 | BRYANT | 284ANV024*0**A* | CSPH*3612AL*+UI | 987MB66120C24*** | 24,200 | $2,904 |
| Yes | 205273804 | BRYANT | 284ANV024*0**A* | CSPH*3612AL*+UI | 88*TA36070C14*** | 24,200 | $2,904 |
| Yes | 205273802 | BRYANT | 284ANV024*0**A* | CSPH*3612AL*+UI | 987MB66100C21*** | 24,200 | $2,904 |
| Yes | 205273797 | BRYANT | 284ANV024*0**A* | CNPV*6024AL*+UI | 88*TA60110C21*** | 23,800 | $2,856 |
| Yes | 205273718 | BRYANT | 284ANV024*0**A* | FE4AN(B,F)005L+UI | | 23,600 | $2,832 |
| Yes | 205273717 | BRYANT | 284ANV024*0**A* | FE4AN(B,F)003L+UI | | 24,200 | $2,904 |
| Yes | 204344197 | BRYANT | 38MAQB30R--3 | FV4CN(B,F)003 | | 20,200 | $2,424 |
| Yes | 204344196 | BRYANT | 38MAQB24R--3 | FV4CNF002 | | 14,000 | $1,680 |
| Yes | 203381000 | BRYANT | 38MAQB24R--3 | FM(C,U)4Z24**AL* | | 15,000 | $1,800 |
| Yes | 203380999 | BRYANT | 38MAQB18R--3 | FM(C,U)4Z18**AL* | | 12,600 | $1,512 |
| Yes | 9893660 | BRYANT | 280ANV036*0**A* | CAP**4224AL*+UI & 98(6*B,7MA)60060V21*** | | 30,400 | $3,648 |
| Yes | 9893657 | BRYANT | 280ANV036*0**A* | CAP**4221AL*+UI & 98(6*B,7MA)60060V21*** | | 30,600 | $3,672 |
| Yes | 9893515 | BRYANT | 280ANV024*0**A* | CAP**4221AL*+UI & 98(6*B,7MA)60060V21*** | | 25,200 | $3,024 |
| Yes | 9893518 | BRYANT | 280ANV024*0**A* | CAP**4224AL*+UI & 98(6*B,7MA)60060V21*** | | 25,200 | $3,024 |
| Yes | 205274124 | BRYANT | 284ANV036*0**A* | CSPH*3612AL*+UI | 987MB60080C21*** | 33,800 | $4,056 |
| Yes | 205274125 | BRYANT | 284ANV036*0**A* | CSPH*3612AL*+UI | 987MB66100C21*** | 33,600 | $4,032 |
| Yes | 205274126 | BRYANT | 284ANV036*0**A* | CSPH*3612AL*+UI | 987MB66120C24*** | 33,800 | $4,056 |
| Yes | 205274127 | BRYANT | 284ANV036*0**A* | CSPH*3612AL*+UI | 986TC60080C21*** | 33,800 | $4,056 |
| Yes | 205274128 | BRYANT | 284ANV036*0**A* | CSPH*3612AL*+UI | 986TC66100C21*** | 33,600 | $4,032 |
| Yes | 207642910 | BRYANT | 38MGHBQ48EA3 | Heat pump with ducts | | 28,000 | $3,360 |
| Yes | 207642914 | BRYANT | 38MGHBQ36DA3 | Combination heat pumps with or without ducts | | 23,000 | $2,760 |
| Yes | 207642904 | BRYANT | 38MGHBQ30DA3 | Heat pump with ducts | | 19,000 | $2,280 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 207642913 | BRYANT | 38MGHBQ36DA3 | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 207642905 | BRYANT | 38MGHBQ30DA3 | Combination heat pumps with or without ducts | | 18,200 | $2,184 |
| Yes | 207642911 | BRYANT | 38MGHBQ48EA3 | Combination heat pumps with or without ducts | | 29,000 | $3,480 |
| Yes | 206350344 | BRYANT | 38MARBQ18AA3 | 40MBDQ18--3 | | 12,700 | $1,524 |
| Yes | 206188260 | BRYANT | 38MARBQ24AA3 | 40MBAAQ24XA3 | | 16,500 | $1,980 |
| Yes | 206348145 | BRYANT | 38MARBQ24AA3 | 619AHBQ24XA3 | | 19,800 | $2,376 |
| Yes | 206350346 | BRYANT | 38MARBQ24AA3 | 40MBCQ24--3 | | 14,500 | $1,740 |
| Yes | 206350348 | BRYANT | 38MARBQ24AA3 | 40MBFQ24--3 | | 14,500 | $1,740 |
| Yes | 206350345 | BRYANT | 38MARBQ18AA3 | 40MBFQ18--3 | | 12,000 | $1,440 |
| Yes | 206350347 | BRYANT | 38MARBQ24AA3 | 40MBDQ24--3 | | 14,500 | $1,740 |
| Yes | 205921388 | BRYANT | 38MAQB24R--3 | 40MBAAQ24XA3 | | 17,500 | $2,100 |
| Yes | 205282606 | BRYANT | 38VMB036HDS3-1 | Combination heat pumps with or without ducts | | 25,000 | $3,000 |
| Yes | 205282609 | BRYANT | 38VMB048HDS3-1 | Combination heat pumps with or without ducts | | 34,000 | $4,080 |
| Yes | 202463637 | BRYANT | 38MPRAQ24AA3 | 619PHAQ24XA3 | | 15,450 | $1,854 |
| Yes | 201847030 | BRYANT | 38MBRQ48A--3 | 40MBFQ48---3 | | 35,000 | $4,200 |
| Yes | 201847028 | BRYANT | 38MAQB24R--3 | 40MBFQ24---3 | | 17,200 | $2,064 |
| Yes | 200059144 | BRYANT | 38MAQB24R--3 | 40MBDQ24---3 | | 17,300 | $2,076 |
| Yes | 202345973 | BRYANT | 38MGRQ36D--3 | Heat pump with ducts | | 24,600 | $2,952 |
| Yes | 204711113 | BRYANT | 38MGRQ30D--3 | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 204722813 | BRYANT | 38MGRQ36D--3 | Combination heat pumps with or without ducts | | 23,800 | $2,856 |
| Yes | 204722812 | BRYANT | 38MGRQ30D--3 | Combination heat pumps with or without ducts | | 20,200 | $2,424 |
| Yes | 205282608 | BRYANT | 38VMB048HDS3-1 | Heat pump with ducts | | 34,000 | $4,080 |
| Yes | 201863366 | BRYANT | 38VMA048HDS3-1 | Heat pump with ducts | | 34,000 | $4,080 |
| Yes | 205282605 | BRYANT | 38VMB036HDS3-1 | Heat pump with ducts | | 25,000 | $3,000 |
| Yes | 201863364 | BRYANT | 38VMA036HDS3-1 | Heat pump with ducts | | 25,000 | $3,000 |
| Yes | 207742379 | C&H | CH-HPR36M-230VO | Heat pump without ducts | | 33,000 | $3,960 |
| Yes | 208497429 | C&H | CH-HPR55M-230VO | Heat pump with ducts | | 35,200 | $4,224 |
| Yes | 208497428 | C&H | CH-HPR55M-230VO | Heat pump without ducts | | 34,400 | $4,128 |
| Yes | 207742373 | C&H | CH-HPR19M-230VO | Heat pump without ducts | | 15,000 | $1,800 |
| Yes | 207742382 | C&H | CH-HPR48M-230VO | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 207742381 | C&H | CH-HPR48M-230VO | Heat pump without ducts | | 36,000 | $4,320 |
| Yes | 207742377 | C&H | CH-HPR28M-230VO | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 207742376 | C&H | CH-HPR28M-230VO | Heat pump without ducts | | 26,600 | $3,192 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 207742374 | C&H | CH-HPR19M-230VO | Heat pump with ducts | | 16,000 | $1,920 |
| Yes | 210665995 | C&H | CH-HPR24-230VO | CH-B24MOLVWM-230VI | | 18,900 | $2,268 |
| Yes | 207742335 | C&H | CH-HPR24-230VO | CH-N24MSPHCT-230VI | | 21,000 | $2,520 |
| Yes | 207742350 | C&H | CH-NHPR48LCU-230VO | CH-48LCDTU/I | | 39,500 | $4,740 |
| Yes | 207742349 | C&H | CH-NHPR48LCU-230VO | CH-N48LCCT-230VI | | 35,000 | $4,200 |
| Yes | 207742351 | C&H | CH-NHPR48LCU-230VO | CH-48LCFC/I | | 35,000 | $4,200 |
| Yes | 207742346 | C&H | CH-NHPR36LCU-230VO | CH-N36LCCT-230VI | | 33,000 | $3,960 |
| Yes | 207742348 | C&H | CH-NHPR36LCU-230VO | CH-36LCFC/I | | 32,000 | $3,840 |
| Yes | 207740522 | C&H | CH-HPR24-230VO | CH-24MOLVWM-230VI | | 18,900 | $2,268 |
| Yes | 207742336 | C&H | CH-HPR24-230VO | CH-M24DTUI | | 21,000 | $2,520 |
| Yes | 207742337 | C&H | CH-HPR24-230VO | CH-24MSPHFC-230VI | | 19,000 | $2,280 |
| Yes | 207742333 | C&H | CH-HPR18-230VO | CH-M18DTUI | | 15,000 | $1,800 |
| Yes | 207740504 | C&H | CH-HPR24-230VO | CH-24MASTWM-230VI | | 21,200 | $2,544 |
| Yes | 207740503 | C&H | CH-HPR18-230VO | CH-18MASTWM-230VI | | 15,000 | $1,800 |
| Yes | 205263858 | C&H | CH-HYP24SPH230VO | CH-M24DTUI | | 17,200 | $2,064 |
| Yes | 205263857 | C&H | CH-24LCU/O | CH-M24DTUI | | 17,200 | $2,064 |
| Yes | 205263902 | C&H | CH-HYP28MSPH-230VO | Heat pump without ducts | | 18,000 | $2,160 |
| Yes | 201755335 | C&H | CH-24LCU/O | CH-24LCDTU/I | | 17,200 | $2,064 |
| Yes | 205047867 | C&H | CH-HYP28MSPH-230VO | Heat pump without ducts | | 18,000 | $2,160 |
| Yes | 10443490 | C&H | CH-24LCDTU/O | CH-24LCDTU/I | | 17,200 | $2,064 |
| Yes | 204098427 | C&H | CH-24DKT230VO | CH-24LCDTU/I | | 17,200 | $2,064 |
| Yes | 206597270 | C&H | CH-24LCU/O | CH-24AHU | | 17,500 | $2,100 |
| Yes | 206597269 | C&H | CH-HYP24SPH230VO | CH-24AHU | | 17,500 | $2,100 |
| Yes | 205263864 | C&H | CH-HYP48LCUO | CH-48LCDTU/I | | 33,000 | $3,960 |
| Yes | 205263863 | C&H | CH-HYP48LCUO | CH-48MSPHCT-230VI | | 35,000 | $4,200 |
| Yes | 205263860 | C&H | CH-HYP48LCUO | CH-48LCCT-230VI | | 35,000 | $4,200 |
| Yes | 205901586 | C&H | CH-HYP36LCUO | CH-36LCDTU/I | | 28,000 | $3,360 |
| Yes | 207742383 | C&H | CH-HPR48M-230VO | Combination heat pumps with or without ducts | | 29,000 | $3,480 |
| Yes | 207742380 | C&H | CH-HPR36M-230VO | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 207742384 | C&H | CH-HPR36M-230VO | Combination heat pumps with or without ducts | | 23,000 | $2,760 |
| Yes | 205313424 | C&H | CH-HYP48MSPH-230VO | Heat pump with ducts | | 28,000 | $3,360 |
| Yes | 208497430 | C&H | CH-HPR55M-230VO | Combination heat pumps with or without ducts | | 35,400 | $4,248 |
| Yes | 205313423 | C&H | CH-HYP48MSPH-230VO | Heat pump without ducts | | 30,000 | $3,600 |
| Yes | 208816951 | C&H | CH-HPR24-230VO | CH-D24MSPHWM-230VI | | 19,400 | $2,328 |
| Yes | 205263865 | C&H | CH-HYP48LCUO | CH-48LCFC/I | | 35,000 | $4,200 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205282615 | C&H | CH-HYP48LCUO | CH-48LCFCI | | 35,000 | $4,200 |
| Yes | 210342131 | CanAir | CDH2060C22 | CDH2060F21 | | 42,000 | $5,040 |
| Yes | 211644140 | CanAir | CDH2030C21 | MAC-36HWFN1-M | | 22,600 | $2,712 |
| Yes | 209550335 | CanAir | MOD30U-30HFN1-MR0(X) | MAC-36HWFN1-M | | 22,600 | $2,712 |
| Yes | 207706572 | CanAir | CDH2048C21 | CDH2048F21 | | 36,000 | $4,320 |
| Yes | 207706569 | CanAir | CDH2024C21 | CDH2024F21 | | 19,200 | $2,304 |
| Yes | 207706568 | CanAir | CDH2018C21 | CDH2018F21 | | 13,500 | $1,620 |
| Yes | 207862104 | CANAIR | BZ33-HYP364Z2-G2-P | Heat pump without ducts | | 33,000 | $3,960 |
| Yes | 207683272 | CANAIR | C28MC548H21 | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 207683271 | CANAIR | C28MC548H21 | Heat pump without ducts | | 36,000 | $4,320 |
| Yes | 207683259 | CanAir | C28SCH24H21 | C28SEH24H21 | | 21,200 | $2,544 |
| Yes | 207796645 | CanAir | C23SCH18H22 | C28SEH18H21 | | 15,000 | $1,800 |
| Yes | 207683258 | CanAir | C28SCH18H21 | C28SEH18H21 | | 15,000 | $1,800 |
| Yes | 207690472 | CANAIR | CDH2018C21 | CDH2018F21 | | 13,000 | $1,560 |
| Yes | 207690473 | CANAIR | CDH2024C21 | CDH2024F21 | | 16,700 | $2,004 |
| Yes | 207690475 | CANAIR | CDH2036C21 | CDH2036F21 | | 24,000 | $2,880 |
| Yes | 205816494 | CANAIR | C23SCH24H22 | C23SEH24H21 | | 19,400 | $2,328 |
| Yes | 207683273 | CANAIR | C28MC548H21 | Combination heat pumps with or without ducts | | 29,000 | $3,480 |
| Yes | 207690474 | CANAIR | CDH2030C21 | CDH2030F21 | | 19,400 | $2,328 |
| Yes | 207690476 | CANAIR | CDH2048C21 | CDH2048F21 | | 32,000 | $3,840 |
| Yes | 210450262 | CARRIER | 38MURAQ36AB3* | CNPV*4821AL* | GG96VTAA48080B | 30,400 | $3,648 |
| Yes | 210450203 | CARRIER | 38MURAQ36AB3* | CNPV*4821AL* | 59TP6B080V17**16 | 30,400 | $3,648 |
| Yes | 210450260 | CARRIER | 38MURAQ36AB3* | CNPV*4221AL* | GG96VTAA48080B | 30,600 | $3,672 |
| Yes | 210450202 | CARRIER | 38MURAQ36AB3* | CNPV*4221AL* | 59TP6B080V17**16 | 30,600 | $3,672 |
| Yes | 210450201 | CARRIER | 38MURAQ36AB3* | CNPV*4217AL* | 59TP6B060V14**12 | 30,800 | $3,696 |
| Yes | 210450257 | CARRIER | 38MURAQ36AB3* | CNPV*4217AL* | GG96VTAA48080B | 30,400 | $3,648 |
| Yes | 210450200 | CARRIER | 38MURAQ36AB3* | CNPV*4217AL* | 59TP6B080V17**16 | 30,400 | $3,648 |
| Yes | 210450250 | CARRIER | 38MURAQ36AB3* | CAP**4821AL* | GG96VTAA48080B | 30,000 | $3,600 |
| Yes | 210450196 | CARRIER | 38MURAQ36AB3* | CAP**4821AL* | 59TP6B080V17**16 | 30,000 | $3,600 |
| Yes | 210450248 | CARRIER | 38MURAQ36AB3* | CAP**4321AL* | GG96VTAA48080B | 30,400 | $3,648 |
| Yes | 210450195 | CARRIER | 38MURAQ36AB3* | CAP**4321AL* | 59TP6B080V17**16 | 30,400 | $3,648 |
| Yes | 210450246 | CARRIER | 38MURAQ36AB3* | CAP**3721AL* | GG96VTAA48080B | 30,400 | $3,648 |
| Yes | 210450194 | CARRIER | 38MURAQ36AB3* | CAP**3721AL* | 59TP6B080V17**16 | 30,400 | $3,648 |
| Yes | 210450193 | CARRIER | 38MURAQ36AB3* | CAP**3717AL* | 59TP6B060V14**12 | 30,600 | $3,672 |
| Yes | 210450243 | CARRIER | 38MURAQ36AB3* | CAP**3717AL* | GG96VTAA48080B | 30,600 | $3,672 |
| Yes | 210450192 | CARRIER | 38MURAQ36AB3* | CAP**3717AL* | 59TP6B080V17**16 | 30,600 | $3,672 |
| Yes | 210450241 | CARRIER | 38MURAQ36AB3* | CAP**3621AL* | GG96VTAA48080B | 30,600 | $3,672 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 210450191 | CARRIER | 38MURAQ36AB3* | CAP**3621AL* | 59TP6B080V17**16 | 30,600 | $3,672 |
| Yes | 210450238 | CARRIER | 38MURAQ36AB3* | CAP**3617AL* | GG96VTAA48080B | 30,600 | $3,672 |
| Yes | 210450189 | CARRIER | 38MURAQ36AB3* | CAP**3617AL* | 59TP6B080V17**16 | 30,600 | $3,672 |
| Yes | 210450222 | CARRIER | 38MURAQ30AB3* | CAP**4321AL* | GG96VTAA48080B | 20,600 | $2,472 |
| Yes | 210450179 | CARRIER | 38MURAQ30AB3* | CAP**4321AL* | 59TP6B080V17**16 | 20,600 | $2,472 |
| Yes | 208447882 | CARRIER | 38MURAQ48AB3 | 40MUAAQ48XA3 | | 36,000 | $4,320 |
| Yes | 208447883 | CARRIER | 38MURAQ36AB3 | 40MUAAQ36XA3 | | 30,400 | $3,648 |
| Yes | 208447887 | CARRIER | 38MURAQ24AB3 | 40MUAAQ24XA3 | | 19,200 | $2,304 |
| Yes | 208447885 | CARRIER | 38MURAQ18AB3 | 40MUAAQ18XA3 | | 13,500 | $1,620 |
| Yes | 207642891 | CARRIER | 38MGHBQ36DA3 | Heat pump without ducts | | 23,200 | $2,784 |
| Yes | 207642888 | CARRIER | 38MGHBQ48EA3 | Heat pump without ducts | | 30,000 | $3,600 |
| Yes | 207642882 | CARRIER | 38MGHBQ30DA3 | Heat pump without ducts | | 17,500 | $2,100 |
| Yes | 9854626 | CARRIER | 38MGRQ30D--3 | Heat pump without ducts | | 17,400 | $2,088 |
| Yes | 9118473 | CARRIER | 38MGRQ36D--3 | Heat pump without ducts | | 23,200 | $2,784 |
| Yes | 206788331 | CARRIER | 25VNA424A*031* | FE4AN(B,F)005L+UI | | 23,800 | $2,856 |
| Yes | 207826659 | CARRIER | 38MARBQ18AA3 | 40MBABQ18XB3 | | 12,000 | $1,440 |
| Yes | 207801578 | CARRIER | 38MARBQ18AA3 | 40MBDQ24---3 | | 12,600 | $1,512 |
| Yes | 204430189 | CARRIER | 25VNA036A*030* | CAP**3617AL*+UI | 58TN*A090C17**16 | 32,400 | $3,888 |
| Yes | 204430145 | CARRIER | 25VNA036A*030* | CAP**3621AL*+UI | 59MN7B060C17**14 | 31,000 | $3,720 |
| Yes | 204431726 | CARRIER | 25VNA060A*030* | CNPV*6024AL*+UI | 59MN7B080C21**20 | 54,500 | $6,540 |
| Yes | 204431757 | CARRIER | 25VNA060A*030* | CSPH*6012AL*+UI | 59MN7B080C21**20 | 55,500 | $6,660 |
| Yes | 204431660 | CARRIER | 25VNA060A*030* | CAP**6121AL*+UI | 58TN*A070C21**20 | 54,000 | $6,480 |
| Yes | 204431629 | CARRIER | 25VNA060A*030* | CAP**6024AL*+UI | 58TN*A070C21**20 | 54,000 | $6,480 |
| Yes | 204431763 | CARRIER | 25VNA060A*030* | CSPH*6012AL*+UI | 59MN7B120C24**22 | 55,500 | $6,660 |
| Yes | 204431651 | CARRIER | 25VNA060A*030* | CAP**6024AL*+UI | 59TN6B080C21**20 | 54,000 | $6,480 |
| Yes | 204431667 | CARRIER | 25VNA060A*030* | CAP**6121AL*+UI | 59MN7B080C21**20 | 55,500 | $6,660 |
| Yes | 204431673 | CARRIER | 25VNA060A*030* | CAP**6121AL*+UI | 59TN6B080C21**20 | 55,500 | $6,660 |
| Yes | 204431647 | CARRIER | 25VNA060A*030* | CAP**6024AL*+UI | 59MN7B120C24**22 | 53,500 | $6,420 |
| Yes | 204431766 | CARRIER | 25VNA060A*030* | CSPH*6012AL*+UI | 59TN6B080C21**20 | 55,500 | $6,660 |
| Yes | 204431638 | CARRIER | 25VNA060A*030* | CAP**6024AL*+UI | 59TN6B120C24**22 | 53,500 | $6,420 |
| Yes | 204431723 | CARRIER | 25VNA060A*030* | CNPV*6024AL*+UI | 59TN6B120C24**22 | 56,000 | $6,720 |
| Yes | 204431644 | CARRIER | 25VNA060A*030* | CAP**6024AL*+UI | 59MN7B100C21**22 | 53,500 | $6,420 |
| Yes | 204431744 | CARRIER | 25VNA060A*030* | CSPH*6012AL*+UI | 58TN*A070C21**20 | 55,500 | $6,660 |
| Yes | 204430997 | CARRIER | 25VNA036A*030* | CSPH*3612AL*+UI | 59MN7B060C17**14 | 33,600 | $4,032 |
| Yes | 204431258 | CARRIER | 25VNA036A*030* | CSPH*4812AL*+UI | 59MN7B060C17**14 | 33,400 | $4,008 |
| Yes | 204431641 | CARRIER | 25VNA060A*030* | CAP**6024AL*+UI | 59MN7B080C21**20 | 54,000 | $6,480 |
| Yes | 204430192 | CARRIER | 25VNA036A*030* | CAP**3621AL*+UI | 58TN*A045C17**12 | 32,800 | $3,936 |
| Yes | 204431136 | CARRIER | 25VNA036A*030* | CSPH*4212AL*+UI | 59MN7B060C17**14 | 33,400 | $4,008 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204431760 | CARRIER | 25VNA060A*030* | CSPH*6012AL*+UI | 59MN7B100C21**22 | 55,000 | $6,600 |
| Yes | 204430937 | CARRIER | 25VNA036A*030* | CSPH*3612AL*+UI | 58TN*A045C17**12 | 33,600 | $4,032 |
| Yes | 204431658 | CARRIER | 25VNA060A*030* | CAP**6024AL*+UI | 58TN*A110C21**20 | 53,500 | $6,420 |
| Yes | 204431083 | CARRIER | 25VNA036A*030* | CSPH*4212AL*+UI | 58TN*A045C17**12 | 33,400 | $4,008 |
| Yes | 204431735 | CARRIER | 25VNA060A*030* | CNPV*6024AL*+UI | 59TN6B080C21**20 | 54,500 | $6,540 |
| Yes | 204431714 | CARRIER | 25VNA060A*030* | CNPV*6024AL*+UI | 58TN*A070C21**20 | 56,000 | $6,720 |
| Yes | 204431733 | CARRIER | 25VNA060A*030* | CNPV*6024AL*+UI | 59MN7B120C24**22 | 54,500 | $6,540 |
| Yes | 204431632 | CARRIER | 25VNA060A*030* | CAP**6024AL*+UI | 58TN*A090C21**20 | 53,500 | $6,420 |
| Yes | 204431654 | CARRIER | 25VNA060A*030* | CAP**6024AL*+UI | 59TN6B100C21**22 | 53,500 | $6,420 |
| Yes | 204430262 | CARRIER | 25VNA036A*030* | CAP**4221AL*+UI | 58TN*A045C17**12 | 33,200 | $3,984 |
| Yes | 204431739 | CARRIER | 25VNA060A*030* | CNPV*6024AL*+UI | 59TN6B100C21**22 | 56,000 | $6,720 |
| Yes | 204431717 | CARRIER | 25VNA060A*030* | CNPV*6024AL*+UI | 58TN*A090C21**20 | 56,000 | $6,720 |
| Yes | 204431741 | CARRIER | 25VNA060A*030* | CNPV*6024AL*+UI | 58TN*A110C21**20 | 56,000 | $6,720 |
| Yes | 204431692 | CARRIER | 25VNA060A*030* | CAP**6124AL*+UI | 59TN6B120C24**22 | 55,000 | $6,600 |
| Yes | 204431686 | CARRIER | 25VNA060A*030* | CAP**6124AL*+UI | 58TN*A090C21**20 | 55,000 | $6,600 |
| Yes | 204431700 | CARRIER | 25VNA060A*030* | CAP**6124AL*+UI | 59MN7B100C21**22 | 55,000 | $6,600 |
| Yes | 204431689 | CARRIER | 25VNA060A*030* | CAP**6124AL*+UI | 58TN*A135C24**22 | 55,000 | $6,600 |
| Yes | 204431670 | CARRIER | 25VNA060A*030* | CAP**6121AL*+UI | 59MN7B100C21**22 | 55,000 | $6,600 |
| Yes | 204431676 | CARRIER | 25VNA060A*030* | CAP**6121AL*+UI | 59TN6B100C21**22 | 55,000 | $6,600 |
| Yes | 204431709 | CARRIER | 25VNA060A*030* | CAP**6124AL*+UI | 59TN6B100C21**22 | 55,000 | $6,600 |
| Yes | 204431711 | CARRIER | 25VNA060A*030* | CAP**6124AL*+UI | 58TN*A110C21**20 | 55,000 | $6,600 |
| Yes | 204431679 | CARRIER | 25VNA060A*030* | CAP**6121AL*+UI | 58TN*A110C21**20 | 55,000 | $6,600 |
| Yes | 204431663 | CARRIER | 25VNA060A*030* | CAP**6121AL*+UI | 58TN*A090C21**20 | 55,000 | $6,600 |
| Yes | 204431705 | CARRIER | 25VNA060A*030* | CAP**6124AL*+UI | 59TN6B080C21**20 | 54,000 | $6,480 |
| Yes | 204431772 | CARRIER | 25VNA060A*030* | CSPH*6012AL*+UI | 58TN*A110C21**20 | 55,000 | $6,600 |
| Yes | 204431769 | CARRIER | 25VNA060A*030* | CSPH*6012AL*+UI | 59TN6B100C21**22 | 55,000 | $6,600 |
| Yes | 204431696 | CARRIER | 25VNA060A*030* | CAP**6124AL*+UI | 59MN7B080C21**20 | 54,000 | $6,480 |
| Yes | 204430276 | CARRIER | 25VNA036A*030* | CAP**4221AL*+UI | 59MN7B060C17**14 | 33,200 | $3,984 |
| Yes | 204431703 | CARRIER | 25VNA060A*030* | CAP**6124AL*+UI | 59MN7B120C24**22 | 55,000 | $6,600 |
| Yes | 204430186 | CARRIER | 25VNA036A*030* | CAP**3617AL*+UI | 59MN7B080C17**14 | 32,800 | $3,936 |
| Yes | 204431748 | CARRIER | 25VNA060A*030* | CSPH*6012AL*+UI | 58TN*A090C21**20 | 55,000 | $6,600 |
| Yes | 204431683 | CARRIER | 25VNA060A*030* | CAP**6124AL*+UI | 58TN*A070C21**20 | 54,000 | $6,480 |
| Yes | 204430631 | CARRIER | 25VNA036A*030* | CNPV*4221AL*+UI | 59MN7B060C17**14 | 33,400 | $4,008 |
| Yes | 204430204 | CARRIER | 25VNA036A*030* | CAP**3621AL*+UI | 59TN6B060C17**14 | 32,800 | $3,936 |
| Yes | 204431463 | CARRIER | 25VNA048A*030* | CAP**6024AL*+UI | 59TN6B080C21**20 | 49,000 | $5,880 |
| Yes | 204430519 | CARRIER | 25VNA036A*030* | CNPV*3617AL*+UI | 58TN*A070C14**12 | 32,600 | $3,912 |
| Yes | 204431471 | CARRIER | 25VNA048A*030* | CAP**6024AL*+UI | 58TN*A110C21**20 | 48,500 | $5,820 |
| Yes | 204430156 | CARRIER | 25VNA036A*030* | CNPV*3617AL*+UI | 59MN7B080C17**14 | 31,000 | $3,720 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204431576 | CARRIER | 25VNA048A*030* | CSPH*4812AL*+UI | 59MN7B080C21**20 | 35,600 | $4,272 |
| Yes | 204431635 | CARRIER | 25VNA060A*030* | CAP**6024AL*+UI | 58TN*A135C24**22 | 53,500 | $6,420 |
| Yes | 204430181 | CARRIER | 25VNA036A*030* | CAP**3617AL*+UI | 59TN6B080C17**14 | 32,800 | $3,936 |
| Yes | 204430694 | CARRIER | 25VNA036A*030* | CNPV*4221AL*+UI | 59MN7B060C21**20 | 33,000 | $3,960 |
| Yes | 204430613 | CARRIER | 25VNA036A*030* | CNPV*4221AL*+UI | 59TN6B060C17**14 | 33,400 | $4,008 |
| Yes | 204431525 | CARRIER | 25VNA048A*030* | CAP**6124AL*+UI | 59TN6B100C21**22 | 48,500 | $5,820 |
| Yes | 204430621 | CARRIER | 25VNA036A*030* | CNPV*4221AL*+UI | 59TN6B080C17**14 | 33,200 | $3,984 |
| Yes | 204430729 | CARRIER | 25VNA036A*030* | CNPV*4821AL*+UI | 59MN7B060C17**14 | 33,400 | $4,008 |
| Yes | 204430948 | CARRIER | 25VNA036A*030* | CSPH*3612AL*+UI | 58TN*A070C17**16 | 33,200 | $3,984 |
| Yes | 204430585 | CARRIER | 25VNA036A*030* | CNPV*4217AL*+UI | 59MN7B080C17**14 | 33,400 | $4,008 |
| Yes | 204431138 | CARRIER | 25VNA036A*030* | CSPH*4212AL*+UI | 59MN7B080C17**14 | 33,200 | $3,984 |
| Yes | 204430999 | CARRIER | 25VNA036A*030* | CSPH*3612AL*+UI | 59MN7B080C17**14 | 33,400 | $4,008 |
| Yes | 204430364 | CARRIER | 25VNA036A*030* | CAP**4821AL*+UI | 59MN7B060C17**14 | 33,200 | $3,984 |
| Yes | 204430366 | CARRIER | 25VNA036A*030* | CAP**4821AL*+UI | 59MN7B080C17**14 | 33,000 | $3,960 |
| Yes | 204430234 | CARRIER | 25VNA036A*030* | CAP**3717AL*+UI | 58TN*A070C14**12 | 33,400 | $4,008 |
| Yes | 204431262 | CARRIER | 25VNA036A*030* | CSPH*4812AL*+UI | 59MN7B080C17**14 | 33,200 | $3,984 |
| Yes | 204430232 | CARRIER | 25VNA036A*030* | CAP**3717AL*+UI | 58TN*A070C17**16 | 33,200 | $3,984 |
| Yes | 204431324 | CARRIER | 25VNA036A*030* | CSPH*6012AL*+UI | 59MN7B060C17**14 | 33,000 | $3,960 |
| Yes | 204430247 | CARRIER | 25VNA036A*030* | CAP**3721AL*+UI | 59TN6B060C17**14 | 33,400 | $4,008 |
| Yes | 204430252 | CARRIER | 25VNA036A*030* | CAP**3721AL*+UI | 59MN7B080C17**14 | 33,200 | $3,984 |
| Yes | 204430467 | CARRIER | 25VNA036A*030* | CAP**6121AL*+UI | 59MN7B060C17**14 | 33,000 | $3,960 |
| Yes | 204430250 | CARRIER | 25VNA036A*030* | CAP**3721AL*+UI | 59TN6B080C17**14 | 33,200 | $3,984 |
| Yes | 204430336 | CARRIER | 25VNA036A*030* | CAP**4321AL*+UI | 59TN6B080C17**14 | 33,200 | $3,984 |
| Yes | 204430339 | CARRIER | 25VNA036A*030* | CAP**4321AL*+UI | 59MN7B080C17**14 | 33,200 | $3,984 |
| Yes | 204430596 | CARRIER | 25VNA036A*030* | CNPV*4221AL*+UI | 58TN*A045C17**12 | 33,400 | $4,008 |
| Yes | 204431730 | CARRIER | 25VNA060A*030* | CNPV*6024AL*+UI | 59MN7B100C21**22 | 56,000 | $6,720 |
| Yes | 204430273 | CARRIER | 25VNA036A*030* | CAP**4221AL*+UI | 59TN6B060C17**14 | 33,200 | $3,984 |
| Yes | 204431487 | CARRIER | 25VNA048A*030* | CAP**6121AL*+UI | 59TN6B080C21**20 | 49,000 | $5,880 |
| Yes | 204430207 | CARRIER | 25VNA036A*030* | CAP**3621AL*+UI | 59TN6B080C17**14 | 32,600 | $3,912 |
| Yes | 204430983 | CARRIER | 25VNA036A*030* | CSPH*3612AL*+UI | 59TN6B060C17**14 | 33,600 | $4,032 |
| Yes | 204431597 | CARRIER | 25VNA048A*030* | CSPH*6012AL*+UI | 58TN*A070C21**20 | 49,000 | $5,880 |
| Yes | 204431611 | CARRIER | 25VNA048A*030* | CSPH*6012AL*+UI | 59MN7B100C21**22 | 49,000 | $5,880 |
| Yes | 204431607 | CARRIER | 25VNA048A*030* | CSPH*6012AL*+UI | 59MN7B080C21**20 | 49,000 | $5,880 |
| Yes | 204430565 | CARRIER | 25VNA036A*030* | CNPV*4217AL*+UI | 58TN*A045C17**12 | 33,600 | $4,032 |
| Yes | 204430575 | CARRIER | 25VNA036A*030* | CNPV*4217AL*+UI | 59TN6B060C17**14 | 33,600 | $4,032 |
| Yes | 204430589 | CARRIER | 25VNA036A*030* | CNPV*4217AL*+UI | 58TN*A070C14**12 | 33,200 | $3,984 |
| Yes | 204430198 | CARRIER | 25VNA036A*030* | CAP**3621AL*+UI | 58TN*A070C21**20 | 32,400 | $3,888 |
| Yes | 204430579 | CARRIER | 25VNA036A*030* | CNPV*4217AL*+UI | 59TN6B080C17**14 | 33,400 | $4,008 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204430991 | CARRIER | 25VNA036A*030* | CSPH*3612AL*+UI | 59TN6B080C17**14 | 33,400 | $4,008 |
| Yes | 204431122 | CARRIER | 25VNA036A*030* | CSPH*4212AL*+UI | 59TN6B060C17**14 | 33,400 | $4,008 |
| Yes | 204431072 | CARRIER | 25VNA036A*030* | CSPH*3612AL*+UI | 59MN7B060C21**20 | 33,200 | $3,984 |
| Yes | 204431720 | CARRIER | 25VNA060A*030* | CNPV*6024AL*+UI | 58TN*A135C24**22 | 55,500 | $6,660 |
| Yes | 204430719 | CARRIER | 25VNA036A*030* | CNPV*4821AL*+UI | 59TN6B060C17**14 | 33,200 | $3,984 |
| Yes | 204430162 | CARRIER | 25VNA036A*030* | CNPV*4217AL*+UI | 59MN7B060C17**14 | 31,000 | $3,720 |
| Yes | 204430147 | CARRIER | 25VNA036A*030* | CAP**4221AL*+UI | 59MN7B080C17**14 | 30,600 | $3,672 |
| Yes | 204431447 | CARRIER | 25VNA048A*030* | CAP**6024AL*+UI | 59MN7B080C21**20 | 49,000 | $5,880 |
| Yes | 204431244 | CARRIER | 25VNA036A*030* | CSPH*4812AL*+UI | 59TN6B060C17**14 | 33,200 | $3,984 |
| Yes | 204431751 | CARRIER | 25VNA060A*030* | CSPH*6012AL*+UI | 58TN*A135C24**22 | 55,000 | $6,600 |
| Yes | 204431443 | CARRIER | 25VNA048A*030* | CAP**6024AL*+UI | 59TN6B120C24**22 | 48,500 | $5,820 |
| Yes | 204430699 | CARRIER | 25VNA036A*030* | CNPV*4821AL*+UI | 58TN*A045C17**12 | 33,400 | $4,008 |
| Yes | 204431427 | CARRIER | 25VNA048A*030* | CAP**6024AL*+UI | 58TN*A070C21**20 | 50,000 | $6,000 |
| Yes | 204431604 | CARRIER | 25VNA048A*030* | CSPH*6012AL*+UI | 59TN6B120C24**22 | 48,500 | $5,820 |
| Yes | 204430358 | CARRIER | 25VNA036A*030* | CAP**4821AL*+UI | 59TN6B060C17**14 | 33,200 | $3,984 |
| Yes | 204431207 | CARRIER | 25VNA036A*030* | CSPH*4812AL*+UI | 58TN*A045C17**12 | 33,400 | $4,008 |
| Yes | 204430450 | CARRIER | 25VNA036A*030* | CAP**6121AL*+UI | 58TN*A045C17**12 | 33,000 | $3,960 |
| Yes | 204430209 | CARRIER | 25VNA036A*030* | CAP**3621AL*+UI | 59MN7B080C17**14 | 32,600 | $3,912 |
| Yes | 204430538 | CARRIER | 25VNA036A*030* | CNPV*3621AL*+UI | 59MN7B080C17**14 | 32,600 | $3,912 |
| Yes | 204431454 | CARRIER | 25VNA048A*030* | CAP**6024AL*+UI | 59MN7B120C24**22 | 49,000 | $5,880 |
| Yes | 204430528 | CARRIER | 25VNA036A*030* | CNPV*3621AL*+UI | 58TN*A070C17**16 | 32,400 | $3,888 |
| Yes | 204430563 | CARRIER | 25VNA036A*030* | CNPV*3621AL*+UI | 59MN7B060C21**20 | 32,600 | $3,912 |
| Yes | 204430514 | CARRIER | 25VNA036A*030* | CNPV*3617AL*+UI | 58TN*A070C17**16 | 32,600 | $3,912 |
| Yes | 204431484 | CARRIER | 25VNA048A*030* | CAP**6121AL*+UI | 59MN7B100C21**22 | 48,500 | $5,820 |
| Yes | 204431614 | CARRIER | 25VNA048A*030* | CSPH*6012AL*+UI | 59MN7B120C24**22 | 49,000 | $5,880 |
| Yes | 204431617 | CARRIER | 25VNA048A*030* | CSPH*6012AL*+UI | 59TN6B080C21**20 | 49,000 | $5,880 |
| Yes | 204431625 | CARRIER | 25VNA048A*030* | CSPH*6012AL*+UI | 58TN*A090C17**16 | 49,000 | $5,880 |
| Yes | 204431493 | CARRIER | 25VNA048A*030* | CAP**6121AL*+UI | 58TN*A090C17**16 | 49,000 | $5,880 |
| Yes | 204431437 | CARRIER | 25VNA048A*030* | CAP**6024AL*+UI | 58TN*A090C21**20 | 48,500 | $5,820 |
| Yes | 204431476 | CARRIER | 25VNA048A*030* | CAP**6121AL*+UI | 58TN*A070C21**20 | 49,000 | $5,880 |
| Yes | 204430175 | CARRIER | 25VNA036A*030* | CAP**3617AL*+UI | 58TN*A070C17**16 | 32,600 | $3,912 |
| Yes | 204431515 | CARRIER | 25VNA048A*030* | CAP**6124AL*+UI | 59MN7B080C21**20 | 49,000 | $5,880 |
| Yes | 204431490 | CARRIER | 25VNA048A*030* | CAP**6121AL*+UI | 59TN6B100C21**22 | 48,500 | $5,820 |
| Yes | 204431478 | CARRIER | 25VNA048A*030* | CAP**6121AL*+UI | 58TN*A090C21**20 | 48,500 | $5,820 |
| Yes | 204431500 | CARRIER | 25VNA048A*030* | CAP**6124AL*+UI | 58TN*A070C21**20 | 49,000 | $5,880 |
| Yes | 204431497 | CARRIER | 25VNA048A*030* | CAP**6121AL*+UI | 58TN*A110C21**20 | 48,500 | $5,820 |
| Yes | 204431621 | CARRIER | 25VNA048A*030* | CSPH*6012AL*+UI | 59TN6B100C21**22 | 49,000 | $5,880 |
| Yes | 204431518 | CARRIER | 25VNA048A*030* | CAP**6124AL*+UI | 59MN7B100C21**22 | 48,500 | $5,820 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204431512 | CARRIER | 25VNA048A*030* | CAP**6124AL*+UI | 59TN6B120C24**22 | 48,500 | $5,820 |
| Yes | 204430347 | CARRIER | 25VNA036A*030* | CAP**4821AL*+UI | 58TN*A045C17**12 | 33,200 | $3,984 |
| Yes | 204430541 | CARRIER | 25VNA036A*030* | CNPV*3621AL*+UI | 59MN7B080C21**20 | 32,200 | $3,864 |
| Yes | 204431521 | CARRIER | 25VNA048A*030* | CAP**6124AL*+UI | 59TN6B080C21**20 | 49,000 | $5,880 |
| Yes | 204430195 | CARRIER | 25VNA036A*030* | CAP**3621AL*+UI | 58TN*A070C17**16 | 32,400 | $3,888 |
| Yes | 204430635 | CARRIER | 25VNA036A*030* | CNPV*4221AL*+UI | 59MN7B080C17**14 | 33,200 | $3,984 |
| Yes | 204431527 | CARRIER | 25VNA048A*030* | CAP**6124AL*+UI | 58TN*A110C21**20 | 48,500 | $5,820 |
| Yes | 204430265 | CARRIER | 25VNA036A*030* | CAP**4221AL*+UI | 58TN*A070C17**16 | 32,800 | $3,936 |
| Yes | 204430571 | CARRIER | 25VNA036A*030* | CNPV*4217AL*+UI | 58TN*A070C17**16 | 33,200 | $3,984 |
| Yes | 204430303 | CARRIER | 25VNA036A*030* | CAP**4224AL*+UI | 58TN*A090C21**20 | 32,400 | $3,888 |
| Yes | 204430270 | CARRIER | 25VNA036A*030* | CAP**4221AL*+UI | 58TN*A090C21**20 | 32,400 | $3,888 |
| Yes | 204430531 | CARRIER | 25VNA036A*030* | CNPV*3621AL*+UI | 58TN*A070C21**20 | 32,400 | $3,888 |
| Yes | 204430292 | CARRIER | 25VNA036A*030* | CAP**4221AL*+UI | 58TN*A090C17**16 | 32,600 | $3,912 |
| Yes | 204430295 | CARRIER | 25VNA036A*030* | CAP**4221AL*+UI | 58TN*A110C21**20 | 32,600 | $3,912 |
| Yes | 204430323 | CARRIER | 25VNA036A*030* | CAP**4224AL*+UI | 59TN6B100C21**22 | 32,400 | $3,888 |
| Yes | 204430325 | CARRIER | 25VNA036A*030* | CAP**4224AL*+UI | 58TN*A110C21**20 | 32,400 | $3,888 |
| Yes | 204431020 | CARRIER | 25VNA036A*030* | CSPH*3612AL*+UI | 59TN6B080C21**20 | 33,000 | $3,960 |
| Yes | 204431010 | CARRIER | 25VNA036A*030* | CSPH*3612AL*+UI | 59MN7B120C24**22 | 33,000 | $3,960 |
| Yes | 204431032 | CARRIER | 25VNA036A*030* | CSPH*3612AL*+UI | 59TN6B100C21**22 | 32,800 | $3,936 |
| Yes | 204431048 | CARRIER | 25VNA036A*030* | CSPH*3612AL*+UI | 58TN*A090C17**16 | 32,800 | $3,936 |
| Yes | 204430968 | CARRIER | 25VNA036A*030* | CSPH*3612AL*+UI | 58TN*A090C21**20 | 32,800 | $3,936 |
| Yes | 204431065 | CARRIER | 25VNA036A*030* | CSPH*3612AL*+UI | 58TN*A110C21**20 | 32,800 | $3,936 |
| Yes | 204431094 | CARRIER | 25VNA036A*030* | CSPH*4212AL*+UI | 58TN*A070C17**16 | 33,000 | $3,960 |
| Yes | 204430237 | CARRIER | 25VNA036A*030* | CAP**3717AL*+UI | 58TN*A090C17**16 | 33,000 | $3,960 |
| Yes | 204430350 | CARRIER | 25VNA036A*030* | CAP**4821AL*+UI | 58TN*A070C17**16 | 32,800 | $3,936 |
| Yes | 204430461 | CARRIER | 25VNA036A*030* | CAP**6121AL*+UI | 59TN6B060C17**14 | 33,000 | $3,960 |
| Yes | 204431164 | CARRIER | 25VNA036A*030* | CSPH*4212AL*+UI | 59MN7B120C24**22 | 32,800 | $3,936 |
| Yes | 204431213 | CARRIER | 25VNA036A*030* | CSPH*4812AL*+UI | 58TN*A070C17**16 | 33,000 | $3,960 |
| Yes | 204431191 | CARRIER | 25VNA036A*030* | CSPH*4212AL*+UI | 58TN*A090C17**16 | 32,800 | $3,936 |
| Yes | 204431178 | CARRIER | 25VNA036A*030* | CSPH*4212AL*+UI | 59TN6B100C21**22 | 32,800 | $3,936 |
| Yes | 204430470 | CARRIER | 25VNA036A*030* | CAP**6121AL*+UI | 59MN7B080C17**14 | 32,800 | $3,936 |
| Yes | 204431172 | CARRIER | 25VNA036A*030* | CSPH*4212AL*+UI | 59TN6B080C21**20 | 32,800 | $3,936 |
| Yes | 204430464 | CARRIER | 25VNA036A*030* | CAP**6121AL*+UI | 59TN6B080C17**14 | 32,800 | $3,936 |
| Yes | 204431274 | CARRIER | 25VNA036A*030* | CSPH*4812AL*+UI | 59MN7B120C24**22 | 32,800 | $3,936 |
| Yes | 204430484 | CARRIER | 25VNA036A*030* | CAP**6121AL*+UI | 59MN7B060C21**20 | 32,600 | $3,912 |
| Yes | 204431327 | CARRIER | 25VNA036A*030* | CSPH*6012AL*+UI | 59MN7B080C17**14 | 32,800 | $3,936 |
| Yes | 204431277 | CARRIER | 25VNA036A*030* | CSPH*4812AL*+UI | 59TN6B080C21**20 | 32,800 | $3,936 |
| Yes | 204430260 | CARRIER | 25VNA036A*030* | CAP**3721AL*+UI | 59MN7B060C21**20 | 33,000 | $3,960 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204430375 | CARRIER | 25VNA036A*030* | CAP**4821AL*+UI | 59TN6B080C21**20 | 32,600 | $3,912 |
| Yes | 204431290 | CARRIER | 25VNA036A*030* | CSPH*4812AL*+UI | 58TN*A090C17**16 | 32,600 | $3,912 |
| Yes | 204430511 | CARRIER | 25VNA036A*030* | CAP**6124AL*+UI | 59MN7B060C21**20 | 32,600 | $3,912 |
| Yes | 204430239 | CARRIER | 25VNA036A*030* | CAP**3721AL*+UI | 58TN*A070C17**16 | 33,000 | $3,960 |
| Yes | 204430255 | CARRIER | 25VNA036A*030* | CAP**3721AL*+UI | 59MN7B080C21**20 | 32,800 | $3,936 |
| Yes | 204430345 | CARRIER | 25VNA036A*030* | CAP**4321AL*+UI | 59MN7B060C21**20 | 33,000 | $3,960 |
| Yes | 204430242 | CARRIER | 25VNA036A*030* | CAP**3721AL*+UI | 58TN*A070C21**20 | 32,800 | $3,936 |
| Yes | 204431304 | CARRIER | 25VNA036A*030* | CSPH*6012AL*+UI | 58TN*A070C17**16 | 32,600 | $3,912 |
| Yes | 204430258 | CARRIER | 25VNA036A*030* | CAP**3721AL*+UI | 59TN6B080C21**20 | 32,800 | $3,936 |
| Yes | 204430333 | CARRIER | 25VNA036A*030* | CAP**4321AL*+UI | 58TN*A070C21**20 | 32,800 | $3,936 |
| Yes | 204430545 | CARRIER | 25VNA036A*030* | CNPV*3621AL*+UI | 59MN7B100C21**22 | 32,200 | $3,864 |
| Yes | 204431600 | CARRIER | 25VNA048A*030* | CSPH*6012AL*+UI | 58TN*A135C24**22 | 48,500 | $5,820 |
| Yes | 204430328 | CARRIER | 25VNA036A*030* | CAP**4224AL*+UI | 59MN7B060C21**20 | 32,800 | $3,936 |
| Yes | 204430297 | CARRIER | 25VNA036A*030* | CAP**4221AL*+UI | 59MN7B060C21**20 | 33,000 | $3,960 |
| Yes | 204430229 | CARRIER | 25VNA036A*030* | CAP**3621AL*+UI | 59MN7B060C21**20 | 32,600 | $3,912 |
| Yes | 204430603 | CARRIER | 25VNA036A*030* | CNPV*4221AL*+UI | 58TN*A070C21**20 | 32,800 | $3,936 |
| Yes | 204430212 | CARRIER | 25VNA036A*030* | CAP**3621AL*+UI | 59MN7B080C21**20 | 32,200 | $3,864 |
| Yes | 204430960 | CARRIER | 25VNA036A*030* | CSPH*3612AL*+UI | 58TN*A070C21**20 | 33,000 | $3,960 |
| Yes | 204431041 | CARRIER | 25VNA036A*030* | CSPH*3612AL*+UI | 58TN*A070C14**12 | 33,200 | $3,984 |
| Yes | 204431128 | CARRIER | 25VNA036A*030* | CSPH*4212AL*+UI | 59TN6B080C17**14 | 33,200 | $3,984 |
| Yes | 204431185 | CARRIER | 25VNA036A*030* | CSPH*4212AL*+UI | 58TN*A070C14**12 | 33,200 | $3,984 |
| Yes | 204431297 | CARRIER | 25VNA036A*030* | CSPH*4812AL*+UI | 59MN7B060C21**20 | 33,000 | $3,960 |
| Yes | 204431001 | CARRIER | 25VNA036A*030* | CSPH*3612AL*+UI | 59MN7B080C21**20 | 33,000 | $3,960 |
| Yes | 204431201 | CARRIER | 25VNA036A*030* | CSPH*4212AL*+UI | 59MN7B060C21**20 | 33,200 | $3,984 |
| Yes | 204431440 | CARRIER | 25VNA048A*030* | CAP**6024AL*+UI | 58TN*A135C24**22 | 48,500 | $5,820 |
| Yes | 204430300 | CARRIER | 25VNA036A*030* | CAP**4224AL*+UI | 58TN*A070C21**20 | 32,600 | $3,912 |
| Yes | 204430726 | CARRIER | 25VNA036A*030* | CNPV*4821AL*+UI | 59TN6B080C17**14 | 33,200 | $3,984 |
| Yes | 204430165 | CARRIER | 25VNA036A*030* | CNPV*4821AL*+UI | 59MN7B080C17**14 | 32,600 | $3,912 |
| Yes | 204430268 | CARRIER | 25VNA036A*030* | CAP**4221AL*+UI | 58TN*A070C21**20 | 32,800 | $3,936 |
| Yes | 204430386 | CARRIER | 25VNA036A*030* | CAP**4821AL*+UI | 59MN7B060C21**20 | 33,000 | $3,960 |
| Yes | 204431248 | CARRIER | 25VNA036A*030* | CSPH*4812AL*+UI | 59TN6B080C17**14 | 33,200 | $3,984 |
| Yes | 204431316 | CARRIER | 25VNA036A*030* | CSPH*6012AL*+UI | 59TN6B060C17**14 | 33,000 | $3,960 |
| Yes | 204430548 | CARRIER | 25VNA036A*030* | CNPV*3621AL*+UI | 59TN6B080C21**20 | 32,200 | $3,864 |
| Yes | 204431286 | CARRIER | 25VNA036A*030* | CSPH*4812AL*+UI | 58TN*A070C14**12 | 33,000 | $3,960 |
| Yes | 204431319 | CARRIER | 25VNA036A*030* | CSPH*6012AL*+UI | 59TN6B080C17**14 | 32,800 | $3,936 |
| Yes | 204430331 | CARRIER | 25VNA036A*030* | CAP**4321AL*+UI | 58TN*A070C17**16 | 33,000 | $3,960 |
| Yes | 204430526 | CARRIER | 25VNA036A*030* | CNPV*3617AL*+UI | 58TN*A090C17**16 | 32,200 | $3,864 |
| Yes | 204430552 | CARRIER | 25VNA036A*030* | CNPV*3621AL*+UI | 59TN6B100C21**22 | 32,200 | $3,864 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204430559 | CARRIER | 25VNA036A*030* | CNPV*3621AL*+UI | 58TN*A110C21**20 | 32,200 | $3,864 |
| Yes | 204430557 | CARRIER | 25VNA036A*030* | CNPV*3621AL*+UI | 58TN*A090C17**16 | 32,200 | $3,864 |
| Yes | 204430361 | CARRIER | 25VNA036A*030* | CAP**4821AL*+UI | 59TN6B080C17**14 | 33,000 | $3,960 |
| Yes | 204431300 | CARRIER | 25VNA036A*030* | CSPH*6012AL*+UI | 58TN*A045C17**12 | 33,000 | $3,960 |
| Yes | 204431504 | CARRIER | 25VNA048A*030* | CAP**6124AL*+UI | 58TN*A090C21**20 | 48,500 | $5,820 |
| Yes | 204430417 | CARRIER | 25VNA036A*030* | CAP**4824AL*+UI | 59MN7B060C21**20 | 32,800 | $3,936 |
| Yes | 204430353 | CARRIER | 25VNA036A*030* | CAP**4821AL*+UI | 58TN*A070C21**20 | 32,600 | $3,912 |
| Yes | 204430388 | CARRIER | 25VNA036A*030* | CAP**4824AL*+UI | 58TN*A070C21**20 | 32,600 | $3,912 |
| Yes | 204430223 | CARRIER | 25VNA036A*030* | CAP**3621AL*+UI | 58TN*A090C17**16 | 32,200 | $3,864 |
| Yes | 204430220 | CARRIER | 25VNA036A*030* | CAP**3621AL*+UI | 59TN6B100C21**22 | 32,200 | $3,864 |
| Yes | 204430218 | CARRIER | 25VNA036A*030* | CAP**3621AL*+UI | 59TN6B080C21**20 | 32,200 | $3,864 |
| Yes | 204431508 | CARRIER | 25VNA048A*030* | CAP**6124AL*+UI | 58TN*A135C24**22 | 48,500 | $5,820 |
| Yes | 204430286 | CARRIER | 25VNA036A*030* | CAP**4221AL*+UI | 59TN6B080C21**20 | 32,600 | $3,912 |
| Yes | 204430600 | CARRIER | 25VNA036A*030* | CNPV*4221AL*+UI | 58TN*A070C17**16 | 32,800 | $3,936 |
| Yes | 204430226 | CARRIER | 25VNA036A*030* | CAP**3621AL*+UI | 58TN*A110C21**20 | 32,200 | $3,864 |
| Yes | 204430201 | CARRIER | 25VNA036A*030* | CAP**3621AL*+UI | 58TN*A090C21**20 | 32,000 | $3,840 |
| Yes | 204430662 | CARRIER | 25VNA036A*030* | CNPV*4221AL*+UI | 59TN6B080C21**20 | 32,600 | $3,912 |
| Yes | 204430672 | CARRIER | 25VNA036A*030* | CNPV*4221AL*+UI | 59TN6B100C21**22 | 32,600 | $3,912 |
| Yes | 204430681 | CARRIER | 25VNA036A*030* | CNPV*4221AL*+UI | 58TN*A090C17**16 | 32,600 | $3,912 |
| Yes | 204430702 | CARRIER | 25VNA036A*030* | CNPV*4821AL*+UI | 58TN*A070C17**16 | 33,000 | $3,960 |
| Yes | 204430317 | CARRIER | 25VNA036A*030* | CAP**4224AL*+UI | 59MN7B120C24**22 | 32,600 | $3,912 |
| Yes | 204430289 | CARRIER | 25VNA036A*030* | CAP**4221AL*+UI | 59TN6B100C21**22 | 32,600 | $3,912 |
| Yes | 204431109 | CARRIER | 25VNA036A*030* | CSPH*4212AL*+UI | 58TN*A090C21**20 | 32,600 | $3,912 |
| Yes | 204430745 | CARRIER | 25VNA036A*030* | CNPV*4821AL*+UI | 59TN6B100C21**22 | 32,600 | $3,912 |
| Yes | 204430320 | CARRIER | 25VNA036A*030* | CAP**4224AL*+UI | 59TN6B080C21**20 | 32,600 | $3,912 |
| Yes | 204430593 | CARRIER | 25VNA036A*030* | CNPV*4217AL*+UI | 58TN*A090C17**16 | 33,000 | $3,960 |
| Yes | 204430749 | CARRIER | 25VNA036A*030* | CNPV*4821AL*+UI | 58TN*A090C17**16 | 32,600 | $3,912 |
| Yes | 204430807 | CARRIER | 25VNA036A*030* | CNPV*4824AL*+UI | 59TN6B100C21**22 | 32,600 | $3,912 |
| Yes | 204430741 | CARRIER | 25VNA036A*030* | CNPV*4821AL*+UI | 59TN6B080C21**20 | 32,800 | $3,936 |
| Yes | 204430801 | CARRIER | 25VNA036A*030* | CNPV*4824AL*+UI | 59TN6B080C21**20 | 32,800 | $3,936 |
| Yes | 204431195 | CARRIER | 25VNA036A*030* | CSPH*4212AL*+UI | 58TN*A110C21**20 | 32,600 | $3,912 |
| Yes | 204430831 | CARRIER | 25VNA036A*030* | CNPV*6024AL*+UI | 58TN*A070C21**20 | 32,600 | $3,912 |
| Yes | 204430355 | CARRIER | 25VNA036A*030* | CAP**4821AL*+UI | 58TN*A090C21**20 | 32,400 | $3,888 |
| Yes | 204430794 | CARRIER | 25VNA036A*030* | CNPV*4824AL*+UI | 59MN7B120C24**22 | 32,800 | $3,936 |
| Yes | 204430378 | CARRIER | 25VNA036A*030* | CAP**4821AL*+UI | 59TN6B100C21**22 | 32,600 | $3,912 |
| Yes | 204430383 | CARRIER | 25VNA036A*030* | CAP**4821AL*+UI | 58TN*A110C21**20 | 32,400 | $3,888 |
| Yes | 204431294 | CARRIER | 25VNA036A*030* | CSPH*4812AL*+UI | 58TN*A110C21**20 | 32,600 | $3,912 |
| Yes | 204430406 | CARRIER | 25VNA036A*030* | CAP**4824AL*+UI | 59MN7B120C24**22 | 32,600 | $3,912 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204430380 | CARRIER | 25VNA036A*030* | CAP**4821AL*+UI | 58TN*A090C17**16 | 32,600 | $3,912 |
| Yes | 204430409 | CARRIER | 25VNA036A*030* | CAP**4824AL*+UI | 59TN6B080C21**20 | 32,600 | $3,912 |
| Yes | 204430453 | CARRIER | 25VNA036A*030* | CAP**6121AL*+UI | 58TN*A070C17**16 | 32,600 | $3,912 |
| Yes | 204431283 | CARRIER | 25VNA036A*030* | CSPH*4812AL*+UI | 59TN6B100C21**22 | 32,600 | $3,912 |
| Yes | 204431224 | CARRIER | 25VNA036A*030* | CSPH*4812AL*+UI | 58TN*A090C21**20 | 32,600 | $3,912 |
| Yes | 204430414 | CARRIER | 25VNA036A*030* | CAP**4824AL*+UI | 58TN*A110C21**20 | 32,400 | $3,888 |
| Yes | 204430437 | CARRIER | 25VNA036A*030* | CAP**6024AL*+UI | 59MN7B120C24**22 | 32,200 | $3,864 |
| Yes | 204430412 | CARRIER | 25VNA036A*030* | CAP**4824AL*+UI | 59TN6B100C21**22 | 32,400 | $3,888 |
| Yes | 204430391 | CARRIER | 25VNA036A*030* | CAP**4824AL*+UI | 58TN*A090C21**20 | 32,400 | $3,888 |
| Yes | 204430439 | CARRIER | 25VNA036A*030* | CAP**6024AL*+UI | 59TN6B080C21**20 | 32,200 | $3,864 |
| Yes | 204430456 | CARRIER | 25VNA036A*030* | CAP**6121AL*+UI | 58TN*A070C21**20 | 32,400 | $3,888 |
| Yes | 204430442 | CARRIER | 25VNA036A*030* | CAP**6024AL*+UI | 59TN6B100C21**22 | 32,200 | $3,864 |
| Yes | 204430445 | CARRIER | 25VNA036A*030* | CAP**6024AL*+UI | 58TN*A110C21**20 | 32,000 | $3,840 |
| Yes | 204430487 | CARRIER | 25VNA036A*030* | CAP**6124AL*+UI | 58TN*A070C21**20 | 32,400 | $3,888 |
| Yes | 204430492 | CARRIER | 25VNA036A*030* | CAP**6124AL*+UI | 59MN7B080C21**20 | 32,200 | $3,864 |
| Yes | 204430472 | CARRIER | 25VNA036A*030* | CAP**6121AL*+UI | 59MN7B080C21**20 | 32,400 | $3,888 |
| Yes | 204430506 | CARRIER | 25VNA036A*030* | CAP**6124AL*+UI | 59TN6B080C21**20 | 32,200 | $3,864 |
| Yes | 204431340 | CARRIER | 25VNA036A*030* | CSPH*6012AL*+UI | 59TN6B080C21**20 | 32,400 | $3,888 |
| Yes | 204430475 | CARRIER | 25VNA036A*030* | CAP**6121AL*+UI | 59MN7B100C21**22 | 32,200 | $3,864 |
| Yes | 204430478 | CARRIER | 25VNA036A*030* | CAP**6121AL*+UI | 59TN6B080C21**20 | 32,400 | $3,888 |
| Yes | 204430481 | CARRIER | 25VNA036A*030* | CAP**6121AL*+UI | 59TN6B100C21**22 | 32,200 | $3,864 |
| Yes | 204430503 | CARRIER | 25VNA036A*030* | CAP**6124AL*+UI | 59MN7B120C24**22 | 32,200 | $3,864 |
| Yes | 204431352 | CARRIER | 25VNA036A*030* | CSPH*6012AL*+UI | 58TN*A110C21**20 | 32,200 | $3,864 |
| Yes | 204431336 | CARRIER | 25VNA036A*030* | CSPH*6012AL*+UI | 59MN7B120C24**22 | 32,400 | $3,888 |
| Yes | 204431343 | CARRIER | 25VNA036A*030* | CSPH*6012AL*+UI | 59TN6B100C21**22 | 32,200 | $3,864 |
| Yes | 204431005 | CARRIER | 25VNA036A*030* | CSPH*3612AL*+UI | 59MN7B100C21**22 | 32,800 | $3,936 |
| Yes | 204430644 | CARRIER | 25VNA036A*030* | CNPV*4221AL*+UI | 59MN7B080C21**20 | 32,600 | $3,912 |
| Yes | 204430927 | CARRIER | 25VNA036A*030* | CNPV*6024AL*+UI | 59MN7B060C21**20 | 32,800 | $3,936 |
| Yes | 204430215 | CARRIER | 25VNA036A*030* | CAP**3621AL*+UI | 59MN7B100C21**22 | 32,200 | $3,864 |
| Yes | 204430104 | CARRIER | 25VNA024A*030* | CSPH*3012AL*+UI | 59MN7B060C17**14 | 25,400 | $3,048 |
| Yes | 204430994 | CARRIER | 25VNA036A*030* | CSPH*3612AL*+UI | 59TN6B120C24**22 | 32,800 | $3,936 |
| Yes | 204430654 | CARRIER | 25VNA036A*030* | CNPV*4221AL*+UI | 59MN7B100C21**22 | 32,600 | $3,912 |
| Yes | 204430973 | CARRIER | 25VNA036A*030* | CSPH*3612AL*+UI | 58TN*A135C24**22 | 32,800 | $3,936 |
| Yes | 204430283 | CARRIER | 25VNA036A*030* | CAP**4221AL*+UI | 59MN7B100C21**22 | 32,600 | $3,912 |
| Yes | 204430309 | CARRIER | 25VNA036A*030* | CAP**4224AL*+UI | 59TN6B120C24**22 | 32,400 | $3,888 |
| Yes | 204430311 | CARRIER | 25VNA036A*030* | CAP**4224AL*+UI | 59MN7B080C21**20 | 32,600 | $3,912 |
| Yes | 204430757 | CARRIER | 25VNA036A*030* | CNPV*4821AL*+UI | 59MN7B060C21**20 | 33,000 | $3,960 |
| Yes | 204430280 | CARRIER | 25VNA036A*030* | CAP**4221AL*+UI | 59MN7B080C21**20 | 32,600 | $3,912 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204430314 | CARRIER | 25VNA036A*030* | CAP**4224AL*+UI | 59MN7B100C21**22 | 32,400 | $3,888 |
| Yes | 204430823 | CARRIER | 25VNA036A*030* | CNPV*4824AL*+UI | 59MN7B060C21**20 | 33,000 | $3,960 |
| Yes | 204430733 | CARRIER | 25VNA036A*030* | CNPV*4821AL*+UI | 59MN7B080C21**20 | 32,800 | $3,936 |
| Yes | 204431101 | CARRIER | 25VNA036A*030* | CSPH*4212AL*+UI | 58TN*A070C21**20 | 32,800 | $3,936 |
| Yes | 204430306 | CARRIER | 25VNA036A*030* | CAP**4224AL*+UI | 58TN*A135C24**22 | 32,400 | $3,888 |
| Yes | 204430789 | CARRIER | 25VNA036A*030* | CNPV*4824AL*+UI | 59MN7B100C21**22 | 32,600 | $3,912 |
| Yes | 204430763 | CARRIER | 25VNA036A*030* | CNPV*4824AL*+UI | 58TN*A070C21**20 | 32,800 | $3,936 |
| Yes | 204430706 | CARRIER | 25VNA036A*030* | CNPV*4821AL*+UI | 58TN*A070C21**20 | 32,800 | $3,936 |
| Yes | 204430737 | CARRIER | 25VNA036A*030* | CNPV*4821AL*+UI | 59MN7B100C21**22 | 32,600 | $3,912 |
| Yes | 204431154 | CARRIER | 25VNA036A*030* | CSPH*4212AL*+UI | 59MN7B100C21**22 | 32,800 | $3,936 |
| Yes | 204431132 | CARRIER | 25VNA036A*030* | CSPH*4212AL*+UI | 59TN6B120C24**22 | 32,600 | $3,912 |
| Yes | 204431218 | CARRIER | 25VNA036A*030* | CSPH*4812AL*+UI | 58TN*A070C21**20 | 32,800 | $3,936 |
| Yes | 204430784 | CARRIER | 25VNA036A*030* | CNPV*4824AL*+UI | 59MN7B080C21**20 | 32,800 | $3,936 |
| Yes | 204431253 | CARRIER | 25VNA036A*030* | CSPH*4812AL*+UI | 59TN6B120C24**22 | 32,600 | $3,912 |
| Yes | 204431148 | CARRIER | 25VNA036A*030* | CSPH*4212AL*+UI | 59MN7B080C21**20 | 32,800 | $3,936 |
| Yes | 204430448 | CARRIER | 25VNA036A*030* | CAP**6024AL*+UI | 59MN7B060C21**20 | 32,600 | $3,912 |
| Yes | 204431270 | CARRIER | 25VNA036A*030* | CSPH*4812AL*+UI | 59MN7B100C21**22 | 32,600 | $3,912 |
| Yes | 204431116 | CARRIER | 25VNA036A*030* | CSPH*4212AL*+UI | 58TN*A135C24**22 | 32,600 | $3,912 |
| Yes | 204431349 | CARRIER | 25VNA036A*030* | CSPH*6012AL*+UI | 58TN*A070C14**12 | 32,600 | $3,912 |
| Yes | 204431359 | CARRIER | 25VNA036A*030* | CSPH*6012AL*+UI | 59MN7B060C21**20 | 32,600 | $3,912 |
| Yes | 204430369 | CARRIER | 25VNA036A*030* | CAP**4821AL*+UI | 59MN7B080C21**20 | 32,600 | $3,912 |
| Yes | 204431266 | CARRIER | 25VNA036A*030* | CSPH*4812AL*+UI | 59MN7B080C21**20 | 32,800 | $3,936 |
| Yes | 204430372 | CARRIER | 25VNA036A*030* | CAP**4821AL*+UI | 59MN7B100C21**22 | 32,600 | $3,912 |
| Yes | 204430420 | CARRIER | 25VNA036A*030* | CAP**6024AL*+UI | 58TN*A070C21**20 | 32,200 | $3,864 |
| Yes | 204430398 | CARRIER | 25VNA036A*030* | CAP**4824AL*+UI | 59TN6B120C24**22 | 32,400 | $3,888 |
| Yes | 204430400 | CARRIER | 25VNA036A*030* | CAP**4824AL*+UI | 59MN7B080C21**20 | 32,600 | $3,912 |
| Yes | 204430431 | CARRIER | 25VNA036A*030* | CAP**6024AL*+UI | 59MN7B080C21**20 | 32,200 | $3,864 |
| Yes | 204430403 | CARRIER | 25VNA036A*030* | CAP**4824AL*+UI | 59MN7B100C21**22 | 32,400 | $3,888 |
| Yes | 204430434 | CARRIER | 25VNA036A*030* | CAP**6024AL*+UI | 59MN7B100C21**22 | 32,200 | $3,864 |
| Yes | 204431329 | CARRIER | 25VNA036A*030* | CSPH*6012AL*+UI | 59MN7B080C21**20 | 32,400 | $3,888 |
| Yes | 204431753 | CARRIER | 25VNA060A*030* | CSPH*6012AL*+UI | 59TN6B120C24**22 | 55,000 | $6,600 |
| Yes | 204430689 | CARRIER | 25VNA036A*030* | CNPV*4221AL*+UI | 58TN*A110C21**20 | 32,600 | $3,912 |
| Yes | 204431306 | CARRIER | 25VNA036A*030* | CSPH*6012AL*+UI | 58TN*A070C21**20 | 32,400 | $3,888 |
| Yes | 204431309 | CARRIER | 25VNA036A*030* | CSPH*6012AL*+UI | 58TN*A090C21**20 | 32,200 | $3,864 |
| Yes | 204430607 | CARRIER | 25VNA036A*030* | CNPV*4221AL*+UI | 58TN*A090C21**20 | 32,600 | $3,912 |
| Yes | 204430711 | CARRIER | 25VNA036A*030* | CNPV*4821AL*+UI | 58TN*A090C21**20 | 32,600 | $3,912 |
| Yes | 204430244 | CARRIER | 25VNA036A*030* | CAP**3721AL*+UI | 58TN*A090C21**20 | 32,600 | $3,912 |
| Yes | 204430813 | CARRIER | 25VNA036A*030* | CNPV*4824AL*+UI | 58TN*A110C21**20 | 32,600 | $3,912 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204430342 | CARRIER | 25VNA036A*030* | CAP**4321AL*+UI | 59MN7B080C21**20 | 32,800 | $3,936 |
| Yes | 204429905 | CARRIER | 25VNA024A*030* | CAP**3621AL*+UI | 58TN*A045C17**12 | 25,200 | $3,024 |
| Yes | 204430423 | CARRIER | 25VNA036A*030* | CAP**6024AL*+UI | 58TN*A090C21**20 | 32,000 | $3,840 |
| Yes | 204430895 | CARRIER | 25VNA036A*030* | CNPV*6024AL*+UI | 59MN7B120C24**22 | 32,400 | $3,888 |
| Yes | 204430753 | CARRIER | 25VNA036A*030* | CNPV*4821AL*+UI | 58TN*A110C21**20 | 32,600 | $3,912 |
| Yes | 204430838 | CARRIER | 25VNA036A*030* | CNPV*6024AL*+UI | 58TN*A090C21**20 | 32,400 | $3,888 |
| Yes | 204430772 | CARRIER | 25VNA036A*030* | CNPV*4824AL*+UI | 58TN*A090C21**20 | 32,600 | $3,912 |
| Yes | 204430888 | CARRIER | 25VNA036A*030* | CNPV*6024AL*+UI | 59MN7B100C21**22 | 32,400 | $3,888 |
| Yes | 204430909 | CARRIER | 25VNA036A*030* | CNPV*6024AL*+UI | 59TN6B100C21**22 | 32,400 | $3,888 |
| Yes | 204430900 | CARRIER | 25VNA036A*030* | CNPV*6024AL*+UI | 59TN6B080C21**20 | 32,400 | $3,888 |
| Yes | 204430918 | CARRIER | 25VNA036A*030* | CNPV*6024AL*+UI | 58TN*A110C21**20 | 32,400 | $3,888 |
| Yes | 204430775 | CARRIER | 25VNA036A*030* | CNPV*4824AL*+UI | 58TN*A135C24**22 | 32,600 | $3,912 |
| Yes | 204430459 | CARRIER | 25VNA036A*030* | CAP**6121AL*+UI | 58TN*A090C21**20 | 32,200 | $3,864 |
| Yes | 204430851 | CARRIER | 25VNA036A*030* | CNPV*6024AL*+UI | 58TN*A135C24**22 | 32,200 | $3,864 |
| Yes | 204430489 | CARRIER | 25VNA036A*030* | CAP**6124AL*+UI | 59TN6B120C24**22 | 32,200 | $3,864 |
| Yes | 204430500 | CARRIER | 25VNA036A*030* | CAP**6124AL*+UI | 59MN7B100C21**22 | 32,200 | $3,864 |
| Yes | 204430508 | CARRIER | 25VNA036A*030* | CAP**6124AL*+UI | 59TN6B100C21**22 | 32,200 | $3,864 |
| Yes | 204430076 | CARRIER | 25VNA024A*030* | CSPH*2412AL*+UI | 58TN*A090C21**20 | 25,200 | $3,024 |
| Yes | 204430081 | CARRIER | 25VNA024A*030* | CSPH*2412AL*+UI | 59MN7B100C21**22 | 25,200 | $3,024 |
| Yes | 204430395 | CARRIER | 25VNA036A*030* | CAP**4824AL*+UI | 58TN*A135C24**22 | 32,400 | $3,888 |
| Yes | 204429866 | CARRIER | 25VNA024A*030* | CAP**3617AL*+UI | 58TN*A045C17**12 | 25,200 | $3,024 |
| Yes | 204431232 | CARRIER | 25VNA036A*030* | CSPH*4812AL*+UI | 58TN*A135C24**22 | 32,600 | $3,912 |
| Yes | 204431313 | CARRIER | 25VNA036A*030* | CSPH*6012AL*+UI | 58TN*A135C24**22 | 32,200 | $3,864 |
| Yes | 204430779 | CARRIER | 25VNA036A*030* | CNPV*4824AL*+UI | 59TN6B120C24**22 | 32,600 | $3,912 |
| Yes | 204431321 | CARRIER | 25VNA036A*030* | CSPH*6012AL*+UI | 59TN6B120C24**22 | 32,200 | $3,864 |
| Yes | 204430879 | CARRIER | 25VNA036A*030* | CNPV*6024AL*+UI | 59MN7B080C21**20 | 32,400 | $3,888 |
| Yes | 204430864 | CARRIER | 25VNA036A*030* | CNPV*6024AL*+UI | 59TN6B120C24**22 | 32,400 | $3,888 |
| Yes | 204430426 | CARRIER | 25VNA036A*030* | CAP**6024AL*+UI | 58TN*A135C24**22 | 32,000 | $3,840 |
| Yes | 204430428 | CARRIER | 25VNA036A*030* | CAP**6024AL*+UI | 59TN6B120C24**22 | 32,200 | $3,864 |
| Yes | 204431332 | CARRIER | 25VNA036A*030* | CSPH*6012AL*+UI | 59MN7B100C21**22 | 32,200 | $3,864 |
| Yes | 204429965 | CARRIER | 25VNA024A*030* | CAP**4221AL*+UI | 58TN*A070C21**20 | 22,200 | $2,664 |
| Yes | 204430027 | CARRIER | 25VNA024A*030* | CNPV*3017AL*+UI | 59TN6B080C17**14 | 25,200 | $3,024 |
| Yes | 204430114 | CARRIER | 25VNA024A*030* | CSPH*3012AL*+UI | 59MN7B120C24**22 | 25,200 | $3,024 |
| Yes | 204429923 | CARRIER | 25VNA024A*030* | CAP**3621AL*+UI | 59TN6B060C17**14 | 21,600 | $2,592 |
| Yes | 204430099 | CARRIER | 25VNA024A*030* | CSPH*3012AL*+UI | 58TN*A135C24**22 | 25,200 | $3,024 |
| Yes | 204429880 | CARRIER | 25VNA024A*030* | CAP**3617AL*+UI | 59TN6B080C17**14 | 25,200 | $3,024 |
| Yes | 204430122 | CARRIER | 25VNA024A*030* | CSPH*3012AL*+UI | 58TN*A070C14**12 | 25,200 | $3,024 |
| Yes | 204429928 | CARRIER | 25VNA024A*030* | CAP**3621AL*+UI | 59TN6B080C17**14 | 25,200 | $3,024 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204633415 | CARRIER | 25VNA024A*030* | CNPV*3621AL*+UI | 59MN7B060C21**20 | 21,400 | $2,568 |
| Yes | 204430052 | CARRIER | 25VNA024A*030* | CNPV*3621AL*+UI | 59MN7B080C21**20 | 25,000 | $3,000 |
| Yes | 204430096 | CARRIER | 25VNA024A*030* | CSPH*3012AL*+UI | 58TN*A090C21**20 | 23,000 | $2,760 |
| Yes | 204430019 | CARRIER | 25VNA024A*030* | CAP**4224AL*+UI | 59TN6B080C21**20 | 22,200 | $2,664 |
| Yes | 204430074 | CARRIER | 25VNA024A*030* | CNPV*4221AL*+UI | 59MN7B060C21**20 | 22,400 | $2,688 |
| Yes | 204429998 | CARRIER | 25VNA024A*030* | CAP**4221AL*+UI | 58TN*A110C21**20 | 22,000 | $2,640 |
| Yes | 204430064 | CARRIER | 25VNA024A*030* | CNPV*4221AL*+UI | 59TN6B080C17**14 | 22,400 | $2,688 |
| Yes | 204430066 | CARRIER | 25VNA024A*030* | CNPV*4221AL*+UI | 59MN7B100C21**22 | 25,200 | $3,024 |
| Yes | 204429898 | CARRIER | 25VNA024A*030* | CAP**3617AL*+UI | 58TN*A090C17**16 | 21,600 | $2,592 |
| Yes | 204430006 | CARRIER | 25VNA024A*030* | CAP**4224AL*+UI | 58TN*A090C21**20 | 22,000 | $2,640 |
| Yes | 204430011 | CARRIER | 25VNA024A*030* | CAP**4224AL*+UI | 58TN*A135C24**22 | 25,000 | $3,000 |
| Yes | 9892659 | CARRIER | 25VNA036A*030* | FE4AN(B,F)003L+UI | | 30,200 | $3,624 |
| Yes | 9892658 | CARRIER | 25VNA036A*030* | FE4ANF002L+UI | | 30,600 | $3,672 |
| Yes | 9892461 | CARRIER | 25VNA024A*030* | FE4ANB006L+UI | | 24,800 | $2,976 |
| Yes | 9892512 | CARRIER | 25VNA024A*030* | FE4ANF002L + UI | | 25,200 | $3,024 |
| Yes | 9892513 | CARRIER | 25VNA024A*030* | FE4AN(B,F)003L+UI | | 25,000 | $3,000 |
| Yes | 9892523 | CARRIER | 25VNA024A*030* | CAP**3617AL*+UI & 59*N*A060V17**14 | | 25,200 | $3,024 |
| Yes | 9892524 | CARRIER | 25VNA024A*030* | CAP**3617AL*+UI & 59*N*A080V17**14 | | 25,200 | $3,024 |
| Yes | 9892525 | CARRIER | 25VNA024A*030* | CAP**3621AL*+UI & 59*N*A060V17**14 | | 25,200 | $3,024 |
| Yes | 9892526 | CARRIER | 25VNA024A*030* | CAP**3621AL*+UI & 59*N*A080V17**14 | | 25,200 | $3,024 |
| Yes | 9892528 | CARRIER | 25VNA024A*030* | CAP**4221AL*+UI & 59*N*A080V17**14 | | 25,200 | $3,024 |
| Yes | 9892527 | CARRIER | 25VNA024A*030* | CAP**4221AL*+UI & 59*N*A060V17**14 | | 25,200 | $3,024 |
| Yes | 9892529 | CARRIER | 25VNA024A*030* | CAP**4224AL*+UI & 59*N*A120V24**22 | | 25,000 | $3,000 |
| Yes | 9892532 | CARRIER | 25VNA024A*030* | CAP**4821AL*+UI & 59*N*A060V17**14 | | 25,000 | $3,000 |
| Yes | 9892533 | CARRIER | 25VNA024A*030* | CAP**4821AL*+UI & 59*N*A080V17**14 | | 24,800 | $2,976 |
| Yes | 9892535 | CARRIER | 25VNA024A*030* | CAP**6021AL*+UI & 59*N*A060V17**14 | | 24,600 | $2,952 |
| Yes | 9892534 | CARRIER | 25VNA024A*030* | CAP**4824AL*+UI & 59*N*A120V24**22 | | 24,800 | $2,976 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 9892536 | CARRIER | 25VNA024A*030* | CAP**6021AL*+UI & 59*N*A080V17**14 | | 24,600 | $2,952 |
| Yes | 9892537 | CARRIER | 25VNA024A*030* | CAP**6024AL*+UI & 59*N*A120V24**22 | | 24,400 | $2,928 |
| Yes | 9892538 | CARRIER | 25VNA024A*030* | CNPV*3617AL*+UI & 59*N*A060V17**14 | | 25,400 | $3,048 |
| Yes | 9892539 | CARRIER | 25VNA024A*030* | CNPV*3617AL*+UI & 59*N*A080V17**14 | | 25,200 | $3,024 |
| Yes | 9892540 | CARRIER | 25VNA024A*030* | CNPV*3621AL*+UI & 59*N*A060V17**14 | | 25,400 | $3,048 |
| Yes | 9892541 | CARRIER | 25VNA024A*030* | CNPV*3621AL*+UI & 59*N*A080V17**14 | | 25,200 | $3,024 |
| Yes | 9892542 | CARRIER | 25VNA024A*030* | CNPV*4217AL*+UI & 59*N*A060V17**14 | | 25,200 | $3,024 |
| Yes | 9892543 | CARRIER | 25VNA024A*030* | CNPV*4217AL*+UI & 59*N*A080V17**14 | | 25,200 | $3,024 |
| Yes | 9892544 | CARRIER | 25VNA024A*030* | CNPV*4221AL*+UI & 59*N*A060V17**14 | | 25,200 | $3,024 |
| Yes | 9892545 | CARRIER | 25VNA024A*030* | CNPV*4221AL*+UI & 59*N*A080V17**14 | | 25,200 | $3,024 |
| Yes | 9892546 | CARRIER | 25VNA024A*030* | CNPV*4821AL*+UI & 59*N*A060V17**14 | | 25,000 | $3,000 |
| Yes | 9892547 | CARRIER | 25VNA024A*030* | CNPV*4821AL*+UI & 59*N*A080V17**14 | | 25,000 | $3,000 |
| Yes | 9892548 | CARRIER | 25VNA024A*030* | CNPV*4824AL*+UI & 59*N*A120V24**22 | | 25,000 | $3,000 |
| Yes | 9892549 | CARRIER | 25VNA024A*030* | CNPV*6024AL*+UI & 59*N*A120V24**22 | | 25,000 | $3,000 |
| Yes | 9892550 | CARRIER | 25VNA024A*030* | CSPH*3612AL*+UI & 59*N*A060V17**14 | | 25,200 | $3,024 |
| Yes | 9892552 | CARRIER | 25VNA024A*030* | CSPH*3612AL*+UI & 59*N*A120V24**22 | | 25,000 | $3,000 |
| Yes | 9892553 | CARRIER | 25VNA024A*030* | CSPH*4212AL*+UI & 59*N*A060V17**14 | | 25,200 | $3,024 |
| Yes | 9892551 | CARRIER | 25VNA024A*030* | CSPH*3612AL*+UI & 59*N*A080V17**14 | | 25,200 | $3,024 |
| Yes | 9892554 | CARRIER | 25VNA024A*030* | CSPH*4212AL*+UI & 59*N*A080V17**14 | | 25,000 | $3,000 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 9892555 | CARRIER | 25VNA024A*030* | CSPH*4212AL*+UI & 59*N*A120V24**22 | | 25,000 | $3,000 |
| Yes | 9892556 | CARRIER | 25VNA024A*030* | CSPH*4812AL*+UI & 59*N*A060V17**14 | | 25,000 | $3,000 |
| Yes | 9892557 | CARRIER | 25VNA024A*030* | CSPH*4812AL*+UI & 59*N*A080V17**14 | | 25,000 | $3,000 |
| Yes | 9892558 | CARRIER | 25VNA024A*030* | CSPH*4812AL*+UI & 59*N*A120V24**22 | | 25,000 | $3,000 |
| Yes | 9892559 | CARRIER | 25VNA024A*030* | CSPH*6012AL*+UI & 59*N*A060V17**14 | | 25,000 | $3,000 |
| Yes | 9892560 | CARRIER | 25VNA024A*030* | CSPH*6012AL*+UI & 59*N*A080V17**14 | | 25,000 | $3,000 |
| Yes | 9892561 | CARRIER | 25VNA024A*030* | CSPH*6012AL*+UI & 59*N*A120V24**22 | | 25,000 | $3,000 |
| Yes | 9892562 | CARRIER | 25VNA024A*030* | CAP**3621AL*+UI & 59MN7A060V21**20 | | 25,200 | $3,024 |
| Yes | 9892563 | CARRIER | 25VNA024A*030* | CAP**3621AL*+UI & 59*N*A080V21**20 | | 25,000 | $3,000 |
| Yes | 9892564 | CARRIER | 25VNA024A*030* | CAP**3621AL*+UI & 59*N*A100V21**22 | | 25,000 | $3,000 |
| Yes | 9892566 | CARRIER | 25VNA024A*030* | CAP**4221AL*+UI & 59*N*A080V21**20 | | 25,000 | $3,000 |
| Yes | 9892567 | CARRIER | 25VNA024A*030* | CAP**4221AL*+UI & 59*N*A100V21**22 | | 25,000 | $3,000 |
| Yes | 9892569 | CARRIER | 25VNA024A*030* | CAP**4224AL*+UI & 59*N*A080V21**20 | | 25,000 | $3,000 |
| Yes | 9892570 | CARRIER | 25VNA024A*030* | CAP**4224AL*+UI & 59*N*A100V21**22 | | 25,000 | $3,000 |
| Yes | 9892572 | CARRIER | 25VNA024A*030* | CAP**4821AL*+UI & 59*N*A080V21**20 | | 24,800 | $2,976 |
| Yes | 9892571 | CARRIER | 25VNA024A*030* | CAP**4821AL*+UI & 59MN7A060V21**20 | | 24,800 | $2,976 |
| Yes | 9892573 | CARRIER | 25VNA024A*030* | CAP**4821AL*+UI & 59*N*A100V21**22 | | 24,800 | $2,976 |
| Yes | 9892574 | CARRIER | 25VNA024A*030* | CAP**4824AL*+UI & 59MN7A060V21**20 | | 24,800 | $2,976 |
| Yes | 9892575 | CARRIER | 25VNA024A*030* | CAP**4824AL*+UI & 59*N*A080V21**20 | | 24,800 | $2,976 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 9892576 | CARRIER | 25VNA024A*030* | CAP**4824AL*+UI & 59*N*A100V21**22 | | 24,800 | $2,976 |
| Yes | 9892578 | CARRIER | 25VNA024A*030* | CAP**6021AL*+UI & 59*N*A080V21**20 | | 24,800 | $2,976 |
| Yes | 9892577 | CARRIER | 25VNA024A*030* | CAP**6021AL*+UI & 59MN7A060V21**20 | | 24,800 | $2,976 |
| Yes | 9892579 | CARRIER | 25VNA024A*030* | CAP**6021AL*+UI & 59*N*A100V21**22 | | 24,800 | $2,976 |
| Yes | 9892580 | CARRIER | 25VNA024A*030* | CAP**6024AL*+UI & 59MN7A060V21**20 | | 24,800 | $2,976 |
| Yes | 9892581 | CARRIER | 25VNA024A*030* | CAP**6024AL*+UI & 59*N*A080V21**20 | | 24,800 | $2,976 |
| Yes | 9892582 | CARRIER | 25VNA024A*030* | CAP**6024AL*+UI & 59*N*A100V21**22 | | 24,800 | $2,976 |
| Yes | 9892584 | CARRIER | 25VNA024A*030* | CNPV*3621AL*+UI & 59*N*A080V21**20 | | 25,200 | $3,024 |
| Yes | 9892583 | CARRIER | 25VNA024A*030* | CNPV*3621AL*+UI & 59MN7A060V21**20 | | 25,200 | $3,024 |
| Yes | 9892585 | CARRIER | 25VNA024A*030* | CNPV*3621AL*+UI & 59*N*A100V21**22 | | 25,200 | $3,024 |
| Yes | 9892586 | CARRIER | 25VNA024A*030* | CNPV*4221AL*+UI & 59MN7A060V21**20 | | 25,200 | $3,024 |
| Yes | 9892587 | CARRIER | 25VNA024A*030* | CNPV*4221AL*+UI & 59*N*A080V21**20 | | 25,200 | $3,024 |
| Yes | 9892588 | CARRIER | 25VNA024A*030* | CNPV*4221AL*+UI & 59*N*A100V21**22 | | 25,000 | $3,000 |
| Yes | 9892589 | CARRIER | 25VNA024A*030* | CNPV*4824AL*+UI & 59MN7A060V21**20 | | 25,000 | $3,000 |
| Yes | 9892590 | CARRIER | 25VNA024A*030* | CNPV*4824AL*+UI & 59*N*A080V21**20 | | 25,000 | $3,000 |
| Yes | 9892591 | CARRIER | 25VNA024A*030* | CNPV*4824AL*+UI & 59*N*A100V21**22 | | 25,000 | $3,000 |
| Yes | 9892592 | CARRIER | 25VNA024A*030* | CNPV*6024AL*+UI & 59MN7A060V21**20 | | 25,000 | $3,000 |
| Yes | 9892593 | CARRIER | 25VNA024A*030* | CNPV*6024AL*+UI & 59*N*A080V21**20 | | 25,000 | $3,000 |
| Yes | 9892594 | CARRIER | 25VNA024A*030* | CNPV*6024AL*+UI & 59*N*A100V21**22 | | 25,000 | $3,000 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 9892596 | CARRIER | 25VNA024A*030* | CSPH*3612AL*+UI & 59*N*A080V21**20 | | 25,000 | $3,000 |
| Yes | 9892595 | CARRIER | 25VNA024A*030* | CSPH*3612AL*+UI & 59MN7A060V21**20 | | 25,200 | $3,024 |
| Yes | 9892597 | CARRIER | 25VNA024A*030* | CSPH*3612AL*+UI & 59*N*A100V21**22 | | 25,000 | $3,000 |
| Yes | 9892598 | CARRIER | 25VNA024A*030* | CSPH*4212AL*+UI & 59MN7A060V21**20 | | 25,000 | $3,000 |
| Yes | 9892599 | CARRIER | 25VNA024A*030* | CSPH*4212AL*+UI & 59*N*A080V21**20 | | 25,000 | $3,000 |
| Yes | 9892600 | CARRIER | 25VNA024A*030* | CSPH*4212AL*+UI & 59*N*A100V21**22 | | 25,000 | $3,000 |
| Yes | 9892601 | CARRIER | 25VNA024A*030* | CSPH*4812AL*+UI & 59MN7A060V21**20 | | 25,000 | $3,000 |
| Yes | 9892603 | CARRIER | 25VNA024A*030* | CSPH*4812AL*+UI & 59*N*A100V21**22 | | 24,800 | $2,976 |
| Yes | 9892602 | CARRIER | 25VNA024A*030* | CSPH*4812AL*+UI & 59*N*A080V21**20 | | 25,000 | $3,000 |
| Yes | 9892604 | CARRIER | 25VNA024A*030* | CSPH*6012AL*+UI & 59MN7A060V21**20 | | 25,000 | $3,000 |
| Yes | 9892605 | CARRIER | 25VNA024A*030* | CSPH*6012AL*+UI & 59*N*A080V21**20 | | 25,000 | $3,000 |
| Yes | 9892606 | CARRIER | 25VNA024A*030* | CSPH*6012AL*+UI & 59*N*A100V21**22 | | 25,000 | $3,000 |
| Yes | 9892607 | CARRIER | 25VNA036A*030* | FE4ANB006L+UI | | 31,600 | $3,792 |
| Yes | 9892665 | CARRIER | 25VNA036A*030* | FE4AN(B,F)005L+UI | | 31,600 | $3,792 |
| Yes | 9892672 | CARRIER | 25VNA036A*030* | CAP**4224AL*+UI & 59*N*A120V24**22 | | 30,200 | $3,624 |
| Yes | 9892676 | CARRIER | 25VNA036A*030* | CAP**4821AL*+UI & 59*N*A080V17**14 | | 32,600 | $3,912 |
| Yes | 9892677 | CARRIER | 25VNA036A*030* | CAP**4824AL*+UI & 59*N*A120V24**22 | | 32,000 | $3,840 |
| Yes | 9892679 | CARRIER | 25VNA036A*030* | CAP**6021AL*+UI & 59*N*A080V17**14 | | 32,000 | $3,840 |
| Yes | 9892680 | CARRIER | 25VNA036A*030* | CAP**6024AL*+UI & 59*N*A120V24**22 | | 31,600 | $3,792 |
| Yes | 9892691 | CARRIER | 25VNA036A*030* | CNPV*4824AL*+UI & 59*N*A120V24**22 | | 32,200 | $3,864 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 9892690 | CARRIER | 25VNA036A*030* | CNPV*4821AL*+UI & 59*N*A080V17**14 | | 32,600 | $3,912 |
| Yes | 9892692 | CARRIER | 25VNA036A*030* | CNPV*6024AL*+UI & 59*N*A120V24**22 | | 32,200 | $3,864 |
| Yes | 9892695 | CARRIER | 25VNA036A*030* | CSPH*3612AL*+UI & 59*N*A120V24**22 | | 30,400 | $3,648 |
| Yes | 9892697 | CARRIER | 25VNA036A*030* | CSPH*4212AL*+UI & 59*N*A080V17**14 | | 30,600 | $3,672 |
| Yes | 9892698 | CARRIER | 25VNA036A*030* | CSPH*4212AL*+UI & 59*N*A120V24**22 | | 30,200 | $3,624 |
| Yes | 9892700 | CARRIER | 25VNA036A*030* | CSPH*4812AL*+UI & 59*N*A080V17**14 | | 32,800 | $3,936 |
| Yes | 9892702 | CARRIER | 25VNA036A*030* | CSPH*6012AL*+UI & 59*N*A060V17**14 | | 32,600 | $3,912 |
| Yes | 9892701 | CARRIER | 25VNA036A*030* | CSPH*4812AL*+UI & 59*N*A120V24**22 | | 32,200 | $3,864 |
| Yes | 9892703 | CARRIER | 25VNA036A*030* | CSPH*6012AL*+UI & 59*N*A080V17**14 | | 32,400 | $3,888 |
| Yes | 9892704 | CARRIER | 25VNA036A*030* | CSPH*6012AL*+UI & 59*N*A120V24**22 | | 32,000 | $3,840 |
| Yes | 9892707 | CARRIER | 25VNA036A*030* | CAP**3621AL*+UI & 59*N*A100V21**22 | | 30,200 | $3,624 |
| Yes | 9892708 | CARRIER | 25VNA036A*030* | CAP**4221AL*+UI & 59MN7A060V21**20 | | 30,600 | $3,672 |
| Yes | 9892705 | CARRIER | 25VNA036A*030* | CAP**3621AL*+UI & 59MN7A060V21**20 | | 30,600 | $3,672 |
| Yes | 9892706 | CARRIER | 25VNA036A*030* | CAP**3621AL*+UI & 59*N*A080V21**20 | | 30,400 | $3,648 |
| Yes | 9892709 | CARRIER | 25VNA036A*030* | CAP**4221AL*+UI & 59*N*A080V21**20 | | 30,200 | $3,624 |
| Yes | 9892710 | CARRIER | 25VNA036A*030* | CAP**4221AL*+UI & 59*N*A100V21**22 | | 30,200 | $3,624 |
| Yes | 9892712 | CARRIER | 25VNA036A*030* | CAP**4224AL*+UI & 59*N*A080V21**20 | | 30,200 | $3,624 |
| Yes | 9892714 | CARRIER | 25VNA036A*030* | CAP**4821AL*+UI & 59MN7A060V21**20 | | 30,200 | $3,624 |
| Yes | 9892713 | CARRIER | 25VNA036A*030* | CAP**4224AL*+UI & 59*N*A100V21**22 | | 30,200 | $3,624 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 9892711 | CARRIER | 25VNA036A*030* | CAP**4224AL*+UI & 59MN7A060V21**20 | | 30,400 | $3,648 |
| Yes | 9892715 | CARRIER | 25VNA036A*030* | CAP**4821AL*+UI & 59*N*A080V21**20 | | 30,000 | $3,600 |
| Yes | 9892716 | CARRIER | 25VNA036A*030* | CAP**4821AL*+UI & 59*N*A100V21**22 | | 29,800 | $3,576 |
| Yes | 9892717 | CARRIER | 25VNA036A*030* | CAP**4824AL*+UI & 59MN7A060V21**20 | | 30,200 | $3,624 |
| Yes | 9892719 | CARRIER | 25VNA036A*030* | CAP**4824AL*+UI & 59*N*A100V21**22 | | 29,800 | $3,576 |
| Yes | 9892720 | CARRIER | 25VNA036A*030* | CAP**6021AL*+UI & 59MN7A060V21**20 | | 32,200 | $3,864 |
| Yes | 9892721 | CARRIER | 25VNA036A*030* | CAP**6021AL*+UI & 59*N*A080V21**20 | | 31,800 | $3,816 |
| Yes | 9892718 | CARRIER | 25VNA036A*030* | CAP**4824AL*+UI & 59*N*A080V21**20 | | 29,800 | $3,576 |
| Yes | 9892722 | CARRIER | 25VNA036A*030* | CAP**6021AL*+UI & 59*N*A100V21**22 | | 31,800 | $3,816 |
| Yes | 9892723 | CARRIER | 25VNA036A*030* | CAP**6024AL*+UI & 59MN7A060V21**20 | | 32,200 | $3,864 |
| Yes | 9892724 | CARRIER | 25VNA036A*030* | CAP**6024AL*+UI & 59*N*A080V21**20 | | 31,800 | $3,816 |
| Yes | 9892727 | CARRIER | 25VNA036A*030* | CNPV*4221AL*+UI & 59*N*A080V21**20 | | 30,400 | $3,648 |
| Yes | 9892725 | CARRIER | 25VNA036A*030* | CAP**6024AL*+UI & 59*N*A100V21**22 | | 31,800 | $3,816 |
| Yes | 9892728 | CARRIER | 25VNA036A*030* | CNPV*4221AL*+UI & 59*N*A100V21**22 | | 30,200 | $3,624 |
| Yes | 9892729 | CARRIER | 25VNA036A*030* | CNPV*4821AL*+UI & 59MN7A060V21**20 | | 30,400 | $3,648 |
| Yes | 9892730 | CARRIER | 25VNA036A*030* | CNPV*4821AL*+UI & 59*N*A080V21**20 | | 30,000 | $3,600 |
| Yes | 9892731 | CARRIER | 25VNA036A*030* | CNPV*4821AL*+UI & 59*N*A100V21**22 | | 30,000 | $3,600 |
| Yes | 9892732 | CARRIER | 25VNA036A*030* | CNPV*4824AL*+UI & 59MN7A060V21**20 | | 30,400 | $3,648 |
| Yes | 9892733 | CARRIER | 25VNA036A*030* | CNPV*4824AL*+UI & 59*N*A080V21**20 | | 30,000 | $3,600 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 9892735 | CARRIER | 25VNA036A*030* | CNPV*6024AL*+UI & 59MN7A060V21**20 | | 32,400 | $3,888 |
| Yes | 9892734 | CARRIER | 25VNA036A*030* | CNPV*4824AL*+UI & 59*N*A100V21**22 | | 30,000 | $3,600 |
| Yes | 9892736 | CARRIER | 25VNA036A*030* | CNPV*6024AL*+UI & 59*N*A080V21**20 | | 32,200 | $3,864 |
| Yes | 9892737 | CARRIER | 25VNA036A*030* | CNPV*6024AL*+UI & 59*N*A100V21**22 | | 32,000 | $3,840 |
| Yes | 9892739 | CARRIER | 25VNA036A*030* | CSPH*3612AL*+UI & 59*N*A080V21**20 | | 30,200 | $3,624 |
| Yes | 9892740 | CARRIER | 25VNA036A*030* | CSPH*3612AL*+UI & 59*N*A100V21**22 | | 30,200 | $3,624 |
| Yes | 9892741 | CARRIER | 25VNA036A*030* | CSPH*4212AL*+UI & 59MN7A060V21**20 | | 30,400 | $3,648 |
| Yes | 9892742 | CARRIER | 25VNA036A*030* | CSPH*4212AL*+UI & 59*N*A080V21**20 | | 30,200 | $3,624 |
| Yes | 9892743 | CARRIER | 25VNA036A*030* | CSPH*4212AL*+UI & 59*N*A100V21**22 | | 30,000 | $3,600 |
| Yes | 9892744 | CARRIER | 25VNA036A*030* | CSPH*4812AL*+UI & 59MN7A060V21**20 | | 30,400 | $3,648 |
| Yes | 9892745 | CARRIER | 25VNA036A*030* | CSPH*4812AL*+UI & 59*N*A080V21**20 | | 30,000 | $3,600 |
| Yes | 9892747 | CARRIER | 25VNA036A*030* | CSPH*6012AL*+UI & 59MN7A060V21**20 | | 32,200 | $3,864 |
| Yes | 9892746 | CARRIER | 25VNA036A*030* | CSPH*4812AL*+UI & 59*N*A100V21**22 | | 30,000 | $3,600 |
| Yes | 9892748 | CARRIER | 25VNA036A*030* | CSPH*6012AL*+UI & 59*N*A080V21**20 | | 32,000 | $3,840 |
| Yes | 9892749 | CARRIER | 25VNA036A*030* | CSPH*6012AL*+UI & 59*N*A100V21**22 | | 32,000 | $3,840 |
| Yes | 9892751 | CARRIER | 25VNA048A*030* | FE4ANB006L+UI | | 47,500 | $5,700 |
| Yes | 9892779 | CARRIER | 25VNA048A*030* | FE4AN(B,F)005L+UI | | 48,500 | $5,820 |
| Yes | 9892797 | CARRIER | 25VNA048A*030* | CAP**6024AL*+UI & 59*N*A100V21**22 | | 48,000 | $5,760 |
| Yes | 9892783 | CARRIER | 25VNA048A*030* | CNPV*6024AL*+UI & 59*N*A120V24**22 | | 49,000 | $5,880 |
| Yes | 9892794 | CARRIER | 25VNA048A*030* | CAP**6021AL*+UI & 59*N*A100V21**22 | | 48,000 | $5,760 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 9892800 | CARRIER | 25VNA048A*030* | CNPV*4821AL*+UI & 59*N*A100V21**22 | | 48,000 | $5,760 |
| Yes | 9892805 | CARRIER | 25VNA048A*030* | CNPV*6024AL*+UI & 59*N*A080V21**20 | | 49,000 | $5,880 |
| Yes | 9892806 | CARRIER | 25VNA048A*030* | CNPV*6024AL*+UI & 59*N*A100V21**22 | | 48,500 | $5,820 |
| Yes | 9892813 | CARRIER | 25VNA060A*030* | FE4ANB006L+UI | | 52,500 | $6,300 |
| Yes | 205272693 | CARRIER | 25VNA436A*030* | CSPH*3612AL*+UI | 59MN7B060C17**14 | 34,400 | $4,128 |
| Yes | 205272685 | CARRIER | 25VNA436A*030* | CSPH*3612AL*+UI | 58TN*A045C17**12 | 34,600 | $4,152 |
| Yes | 205272538 | CARRIER | 25VNA436A*030* | CAP**4224AL*+UI | 58TN*A070C21**20 | 33,800 | $4,056 |
| Yes | 205272529 | CARRIER | 25VNA436A*030* | CAP**4221AL*+UI | 59MN7B060C17**14 | 34,600 | $4,152 |
| Yes | 205272524 | CARRIER | 25VNA436A*030* | CAP**4221AL*+UI | 58TN*A045C17**12 | 34,600 | $4,152 |
| Yes | 205272741 | CARRIER | 25VNA436A*030* | CSPH*4812AL*+UI | 59MN7B060C21**20 | 34,000 | $4,080 |
| Yes | 205272742 | CARRIER | 25VNA436A*030* | CSPH*6012AL*+UI | 58TN*A045C17**12 | 33,800 | $4,056 |
| Yes | 205272738 | CARRIER | 25VNA436A*030* | CSPH*4812AL*+UI | 58TN*A070C14**12 | 34,000 | $4,080 |
| Yes | 205272732 | CARRIER | 25VNA436A*030* | CSPH*4812AL*+UI | 59MN7B080C17**14 | 34,000 | $4,080 |
| Yes | 205272731 | CARRIER | 25VNA436A*030* | CSPH*4812AL*+UI | 59MN7B060C17**14 | 34,200 | $4,104 |
| Yes | 205272729 | CARRIER | 25VNA436A*030* | CSPH*4812AL*+UI | 59TN6B080C17**14 | 34,200 | $4,104 |
| Yes | 205272728 | CARRIER | 25VNA436A*030* | CSPH*4812AL*+UI | 59TN6B060C17**14 | 34,200 | $4,104 |
| Yes | 205272723 | CARRIER | 25VNA436A*030* | CSPH*4812AL*+UI | 58TN*A045C17**12 | 34,400 | $4,128 |
| Yes | 205272719 | CARRIER | 25VNA436A*030* | CSPH*4212AL*+UI | 58TN*A070C14**12 | 34,000 | $4,080 |
| Yes | 205272722 | CARRIER | 25VNA436A*030* | CSPH*4212AL*+UI | 59MN7B060C21**20 | 34,000 | $4,080 |
| Yes | 205272713 | CARRIER | 25VNA436A*030* | CSPH*4212AL*+UI | 59MN7B080C17**14 | 34,200 | $4,104 |
| Yes | 205272712 | CARRIER | 25VNA436A*030* | CSPH*4212AL*+UI | 59MN7B060C17**14 | 34,200 | $4,104 |
| Yes | 205272710 | CARRIER | 25VNA436A*030* | CSPH*4212AL*+UI | 59TN6B080C17**14 | 34,200 | $4,104 |
| Yes | 205272705 | CARRIER | 25VNA436A*030* | CSPH*4212AL*+UI | 58TN*A070C17**16 | 34,000 | $4,080 |
| Yes | 205272709 | CARRIER | 25VNA436A*030* | CSPH*4212AL*+UI | 59TN6B060C17**14 | 34,400 | $4,128 |
| Yes | 205272704 | CARRIER | 25VNA436A*030* | CSPH*4212AL*+UI | 58TN*A045C17**12 | 34,400 | $4,128 |
| Yes | 205272703 | CARRIER | 25VNA436A*030* | CSPH*3612AL*+UI | 59MN7B060C21**20 | 34,200 | $4,104 |
| Yes | 205272694 | CARRIER | 25VNA436A*030* | CSPH*3612AL*+UI | 59MN7B080C17**14 | 34,200 | $4,104 |
| Yes | 205272700 | CARRIER | 25VNA436A*030* | CSPH*3612AL*+UI | 58TN*A070C14**12 | 34,200 | $4,104 |
| Yes | 205272690 | CARRIER | 25VNA436A*030* | CSPH*3612AL*+UI | 59TN6B060C17**14 | 34,600 | $4,152 |
| Yes | 205272691 | CARRIER | 25VNA436A*030* | CSPH*3612AL*+UI | 59TN6B080C17**14 | 34,400 | $4,128 |
| Yes | 205272687 | CARRIER | 25VNA436A*030* | CSPH*3612AL*+UI | 58TN*A070C21**20 | 33,800 | $4,056 |
| Yes | 205272686 | CARRIER | 25VNA436A*030* | CSPH*3612AL*+UI | 58TN*A070C17**16 | 34,000 | $4,080 |
| Yes | 205272654 | CARRIER | 25VNA436A*030* | CNPV*4821AL*+UI | 59MN7B060C17**14 | 34,200 | $4,104 |
| Yes | 205272652 | CARRIER | 25VNA436A*030* | CNPV*4821AL*+UI | 59TN6B060C17**14 | 34,400 | $4,128 |
| Yes | 205272648 | CARRIER | 25VNA436A*030* | CNPV*4821AL*+UI | 58TN*A045C17**12 | 34,200 | $4,104 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205272647 | CARRIER | 25VNA436A*030* | CNPV*4221AL*+UI | 59MN7B060C21**20 | 34,400 | $4,128 |
| Yes | 205272640 | CARRIER | 25VNA436A*030* | CNPV*4221AL*+UI | 59MN7B080C17**14 | 34,400 | $4,128 |
| Yes | 205272639 | CARRIER | 25VNA436A*030* | CNPV*4221AL*+UI | 59MN7B060C17**14 | 34,600 | $4,152 |
| Yes | 205272638 | CARRIER | 25VNA436A*030* | CNPV*4221AL*+UI | 59TN6B080C17**14 | 34,600 | $4,152 |
| Yes | 205272635 | CARRIER | 25VNA436A*030* | CNPV*4221AL*+UI | 58TN*A070C21**20 | 34,000 | $4,080 |
| Yes | 205272637 | CARRIER | 25VNA436A*030* | CNPV*4221AL*+UI | 59TN6B060C17**14 | 34,600 | $4,152 |
| Yes | 205272634 | CARRIER | 25VNA436A*030* | CNPV*4221AL*+UI | 58TN*A070C17**16 | 34,200 | $4,104 |
| Yes | 205272633 | CARRIER | 25VNA436A*030* | CNPV*4221AL*+UI | 58TN*A045C17**12 | 34,800 | $4,176 |
| Yes | 205272631 | CARRIER | 25VNA436A*030* | CNPV*4217AL*+UI | 58TN*A070C14**12 | 34,200 | $4,104 |
| Yes | 205272630 | CARRIER | 25VNA436A*030* | CNPV*4217AL*+UI | 59MN7B080C17**14 | 34,200 | $4,104 |
| Yes | 205272629 | CARRIER | 25VNA436A*030* | CNPV*4217AL*+UI | 59MN7B060C17**14 | 34,400 | $4,128 |
| Yes | 205272627 | CARRIER | 25VNA436A*030* | CNPV*4217AL*+UI | 59TN6B060C17**14 | 34,600 | $4,152 |
| Yes | 205272628 | CARRIER | 25VNA436A*030* | CNPV*4217AL*+UI | 59TN6B080C17**14 | 34,400 | $4,128 |
| Yes | 205272625 | CARRIER | 25VNA436A*030* | CNPV*4217AL*+UI | 58TN*A045C17**12 | 34,600 | $4,152 |
| Yes | 205272605 | CARRIER | 25VNA436A*030* | CAP**6121AL*+UI | 59MN7B060C17**14 | 33,600 | $4,032 |
| Yes | 205272584 | CARRIER | 25VNA436A*030* | CAP**4824AL*+UI | 59TN6B080C21**20 | 33,400 | $4,008 |
| Yes | 205272583 | CARRIER | 25VNA436A*030* | CAP**4824AL*+UI | 59MN7B120C24**22 | 33,400 | $4,008 |
| Yes | 205272576 | CARRIER | 25VNA436A*030* | CAP**4821AL*+UI | 59MN7B060C21**20 | 33,800 | $4,056 |
| Yes | 205272570 | CARRIER | 25VNA436A*030* | CAP**4821AL*+UI | 59MN7B080C21**20 | 33,400 | $4,008 |
| Yes | 205272581 | CARRIER | 25VNA436A*030* | CAP**4824AL*+UI | 59MN7B080C21**20 | 33,400 | $4,008 |
| Yes | 205272569 | CARRIER | 25VNA436A*030* | CAP**4821AL*+UI | 59MN7B080C17**14 | 33,800 | $4,056 |
| Yes | 205272566 | CARRIER | 25VNA436A*030* | CAP**4821AL*+UI | 59TN6B060C17**14 | 34,200 | $4,104 |
| Yes | 205272564 | CARRIER | 25VNA436A*030* | CAP**4821AL*+UI | 58TN*A070C21**20 | 33,600 | $4,032 |
| Yes | 205272568 | CARRIER | 25VNA436A*030* | CAP**4821AL*+UI | 59MN7B060C17**14 | 34,000 | $4,080 |
| Yes | 205272567 | CARRIER | 25VNA436A*030* | CAP**4821AL*+UI | 59TN6B080C17**14 | 34,000 | $4,080 |
| Yes | 205272562 | CARRIER | 25VNA436A*030* | CAP**4821AL*+UI | 58TN*A045C17**12 | 34,200 | $4,104 |
| Yes | 205272553 | CARRIER | 25VNA436A*030* | CAP**4321AL*+UI | 59TN6B080C17**14 | 34,200 | $4,104 |
| Yes | 205272552 | CARRIER | 25VNA436A*030* | CAP**4321AL*+UI | 59TN6B060C17**14 | 34,400 | $4,128 |
| Yes | 205272546 | CARRIER | 25VNA436A*030* | CAP**4224AL*+UI | 59TN6B100C21**22 | 33,600 | $4,032 |
| Yes | 205272548 | CARRIER | 25VNA436A*030* | CAP**4224AL*+UI | 59MN7B060C21**20 | 34,200 | $4,104 |
| Yes | 205272544 | CARRIER | 25VNA436A*030* | CAP**4224AL*+UI | 59MN7B120C24**22 | 33,800 | $4,056 |
| Yes | 205272542 | CARRIER | 25VNA436A*030* | CAP**4224AL*+UI | 59MN7B080C21**20 | 33,800 | $4,056 |
| Yes | 205272543 | CARRIER | 25VNA436A*030* | CAP**4224AL*+UI | 59MN7B100C21**22 | 33,600 | $4,032 |
| Yes | 205272545 | CARRIER | 25VNA436A*030* | CAP**4224AL*+UI | 59TN6B080C21**20 | 33,800 | $4,056 |
| Yes | 205272537 | CARRIER | 25VNA436A*030* | CAP**4221AL*+UI | 59MN7B060C21**20 | 34,200 | $4,104 |
| Yes | 205272535 | CARRIER | 25VNA436A*030* | CAP**4221AL*+UI | 58TN*A090C17**16 | 33,800 | $4,056 |
| Yes | 205272541 | CARRIER | 25VNA436A*030* | CAP**4224AL*+UI | 59TN6B120C24**22 | 33,600 | $4,032 |
| Yes | 205272534 | CARRIER | 25VNA436A*030* | CAP**4221AL*+UI | 59TN6B100C21**22 | 33,800 | $4,056 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205272532 | CARRIER | 25VNA436A*030* | CAP**4221AL*+UI | 59MN7B100C21**22 | 33,800 | $4,056 |
| Yes | 205272533 | CARRIER | 25VNA436A*030* | CAP**4221AL*+UI | 59TN6B080C21**20 | 33,800 | $4,056 |
| Yes | 205272531 | CARRIER | 25VNA436A*030* | CAP**4221AL*+UI | 59MN7B080C21**20 | 33,800 | $4,056 |
| Yes | 205272530 | CARRIER | 25VNA436A*030* | CAP**4221AL*+UI | 59MN7B080C17**14 | 34,400 | $4,128 |
| Yes | 205272528 | CARRIER | 25VNA436A*030* | CAP**4221AL*+UI | 59TN6B060C17**14 | 34,600 | $4,152 |
| Yes | 205272525 | CARRIER | 25VNA436A*030* | CAP**4221AL*+UI | 58TN*A070C17**16 | 34,200 | $4,104 |
| Yes | 205272516 | CARRIER | 25VNA436A*030* | CAP**3721AL*+UI | 59MN7B080C17**14 | 34,000 | $4,080 |
| Yes | 205272526 | CARRIER | 25VNA436A*030* | CAP**4221AL*+UI | 58TN*A070C21**20 | 34,000 | $4,080 |
| Yes | 205272514 | CARRIER | 25VNA436A*030* | CAP**3721AL*+UI | 59TN6B060C17**14 | 34,400 | $4,128 |
| Yes | 205272515 | CARRIER | 25VNA436A*030* | CAP**3721AL*+UI | 59TN6B080C17**14 | 34,200 | $4,104 |
| Yes | 205272509 | CARRIER | 25VNA436A*030* | CAP**3717AL*+UI | 58TN*A070C14**12 | 34,000 | $4,080 |
| Yes | 205272508 | CARRIER | 25VNA436A*030* | CAP**3717AL*+UI | 58TN*A070C17**16 | 34,200 | $4,104 |
| Yes | 205272750 | CARRIER | 25VNA436A*030* | CSPH*6012AL*+UI | 59MN7B060C17**14 | 33,800 | $4,056 |
| Yes | 205272747 | CARRIER | 25VNA436A*030* | CSPH*6012AL*+UI | 59TN6B060C17**14 | 33,800 | $4,056 |
| Yes | 205272626 | CARRIER | 25VNA436A*030* | CNPV*4217AL*+UI | 58TN*A070C17**16 | 34,200 | $4,104 |
| Yes | 205272632 | CARRIER | 25VNA436A*030* | CNPV*4217AL*+UI | 58TN*A090C17**16 | 33,800 | $4,056 |
| Yes | 205272624 | CARRIER | 25VNA436A*030* | CAP**6124AL*+UI | 59MN7B060C21**20 | 33,600 | $4,032 |
| Yes | 205272613 | CARRIER | 25VNA436A*030* | CAP**6121AL*+UI | 59MN7B060C21**20 | 33,600 | $4,032 |
| Yes | 205272606 | CARRIER | 25VNA436A*030* | CAP**6121AL*+UI | 59MN7B080C17**14 | 33,800 | $4,056 |
| Yes | 205272604 | CARRIER | 25VNA436A*030* | CAP**6121AL*+UI | 59TN6B080C17**14 | 33,800 | $4,056 |
| Yes | 205272603 | CARRIER | 25VNA436A*030* | CAP**6121AL*+UI | 59TN6B060C17**14 | 34,000 | $4,080 |
| Yes | 205272598 | CARRIER | 25VNA436A*030* | CAP**6024AL*+UI | 59MN7B060C21**20 | 33,400 | $4,008 |
| Yes | 205272588 | CARRIER | 25VNA436A*030* | CAP**6024AL*+UI | 58TN*A070C21**20 | 33,000 | $3,960 |
| Yes | 205272587 | CARRIER | 25VNA436A*030* | CAP**4824AL*+UI | 59MN7B060C21**20 | 33,800 | $4,056 |
| Yes | 205272599 | CARRIER | 25VNA436A*030* | CAP**6121AL*+UI | 58TN*A045C17**12 | 33,800 | $4,056 |
| Yes | 205272582 | CARRIER | 25VNA436A*030* | CAP**4824AL*+UI | 59MN7B100C21**22 | 33,200 | $3,984 |
| Yes | 205272585 | CARRIER | 25VNA436A*030* | CAP**4824AL*+UI | 59TN6B100C21**22 | 33,200 | $3,984 |
| Yes | 205272580 | CARRIER | 25VNA436A*030* | CAP**4824AL*+UI | 59TN6B120C24**22 | 33,200 | $3,984 |
| Yes | 205272577 | CARRIER | 25VNA436A*030* | CAP**4824AL*+UI | 58TN*A070C21**20 | 33,400 | $4,008 |
| Yes | 205272575 | CARRIER | 25VNA436A*030* | CAP**4821AL*+UI | 58TN*A110C21**20 | 33,400 | $4,008 |
| Yes | 205272574 | CARRIER | 25VNA436A*030* | CAP**4821AL*+UI | 58TN*A090C17**16 | 33,400 | $4,008 |
| Yes | 205272573 | CARRIER | 25VNA436A*030* | CAP**4821AL*+UI | 59TN6B100C21**22 | 33,400 | $4,008 |
| Yes | 205272571 | CARRIER | 25VNA436A*030* | CAP**4821AL*+UI | 59MN7B100C21**22 | 33,400 | $4,008 |
| Yes | 205272572 | CARRIER | 25VNA436A*030* | CAP**4821AL*+UI | 59TN6B080C21**20 | 33,400 | $4,008 |
| Yes | 205272563 | CARRIER | 25VNA436A*030* | CAP**4821AL*+UI | 58TN*A070C17**16 | 33,800 | $4,056 |
| Yes | 205272565 | CARRIER | 25VNA436A*030* | CAP**4821AL*+UI | 58TN*A090C21**20 | 33,200 | $3,984 |
| Yes | 205272561 | CARRIER | 25VNA436A*030* | CAP**4321AL*+UI | 59MN7B060C21**20 | 34,000 | $4,080 |
| Yes | 205272557 | CARRIER | 25VNA436A*030* | CAP**4321AL*+UI | 59TN6B080C21**20 | 33,600 | $4,032 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205272555 | CARRIER | 25VNA436A*030* | CAP**4321AL*+UI | 59MN7B080C21**20 | 33,600 | $4,032 |
| Yes | 205272554 | CARRIER | 25VNA436A*030* | CAP**4321AL*+UI | 59MN7B080C17**14 | 34,000 | $4,080 |
| Yes | 205272550 | CARRIER | 25VNA436A*030* | CAP**4321AL*+UI | 58TN*A070C21**20 | 33,600 | $4,032 |
| Yes | 205272547 | CARRIER | 25VNA436A*030* | CAP**4224AL*+UI | 58TN*A110C21**20 | 33,600 | $4,032 |
| Yes | 205272540 | CARRIER | 25VNA436A*030* | CAP**4224AL*+UI | 58TN*A135C24**22 | 33,600 | $4,032 |
| Yes | 205272549 | CARRIER | 25VNA436A*030* | CAP**4321AL*+UI | 58TN*A070C17**16 | 33,800 | $4,056 |
| Yes | 205272539 | CARRIER | 25VNA436A*030* | CAP**4224AL*+UI | 58TN*A090C21**20 | 33,600 | $4,032 |
| Yes | 205272536 | CARRIER | 25VNA436A*030* | CAP**4221AL*+UI | 58TN*A110C21**20 | 33,800 | $4,056 |
| Yes | 205272519 | CARRIER | 25VNA436A*030* | CAP**3721AL*+UI | 59TN6B080C21**20 | 33,600 | $4,032 |
| Yes | 205272527 | CARRIER | 25VNA436A*030* | CAP**4221AL*+UI | 58TN*A090C21**20 | 33,600 | $4,032 |
| Yes | 205272523 | CARRIER | 25VNA436A*030* | CAP**3721AL*+UI | 59MN7B060C21**20 | 34,000 | $4,080 |
| Yes | 205272513 | CARRIER | 25VNA436A*030* | CAP**3721AL*+UI | 58TN*A090C21**20 | 33,400 | $4,008 |
| Yes | 205272517 | CARRIER | 25VNA436A*030* | CAP**3721AL*+UI | 59MN7B080C21**20 | 33,600 | $4,032 |
| Yes | 205272512 | CARRIER | 25VNA436A*030* | CAP**3721AL*+UI | 58TN*A070C21**20 | 33,800 | $4,056 |
| Yes | 205272510 | CARRIER | 25VNA436A*030* | CAP**3717AL*+UI | 58TN*A090C17**16 | 33,800 | $4,056 |
| Yes | 205272511 | CARRIER | 25VNA436A*030* | CAP**3721AL*+UI | 58TN*A070C17**16 | 34,000 | $4,080 |
| Yes | 205272757 | CARRIER | 25VNA436A*030* | CSPH*6012AL*+UI | 58TN*A070C14**12 | 33,600 | $4,032 |
| Yes | 205272760 | CARRIER | 25VNA436A*030* | CSPH*6012AL*+UI | 59MN7B060C21**20 | 33,400 | $4,008 |
| Yes | 205272754 | CARRIER | 25VNA436A*030* | CSPH*6012AL*+UI | 59MN7B120C24**22 | 33,000 | $3,960 |
| Yes | 205272751 | CARRIER | 25VNA436A*030* | CSPH*6012AL*+UI | 59MN7B080C17**14 | 33,600 | $4,032 |
| Yes | 205272752 | CARRIER | 25VNA436A*030* | CSPH*6012AL*+UI | 59MN7B080C21**20 | 33,000 | $3,960 |
| Yes | 205272748 | CARRIER | 25VNA436A*030* | CSPH*6012AL*+UI | 59TN6B080C17**14 | 33,600 | $4,032 |
| Yes | 205272755 | CARRIER | 25VNA436A*030* | CSPH*6012AL*+UI | 59TN6B080C21**20 | 33,000 | $3,960 |
| Yes | 205272744 | CARRIER | 25VNA436A*030* | CSPH*6012AL*+UI | 58TN*A070C21**20 | 33,200 | $3,984 |
| Yes | 205272743 | CARRIER | 25VNA436A*030* | CSPH*6012AL*+UI | 58TN*A070C17**16 | 33,400 | $4,008 |
| Yes | 205272740 | CARRIER | 25VNA436A*030* | CSPH*4812AL*+UI | 58TN*A110C21**20 | 33,400 | $4,008 |
| Yes | 205272736 | CARRIER | 25VNA436A*030* | CSPH*4812AL*+UI | 59TN6B080C21**20 | 33,600 | $4,032 |
| Yes | 205272739 | CARRIER | 25VNA436A*030* | CSPH*4812AL*+UI | 58TN*A090C17**16 | 33,400 | $4,008 |
| Yes | 205272737 | CARRIER | 25VNA436A*030* | CSPH*4812AL*+UI | 59TN6B100C21**22 | 33,400 | $4,008 |
| Yes | 205272734 | CARRIER | 25VNA436A*030* | CSPH*4812AL*+UI | 59MN7B100C21**22 | 33,400 | $4,008 |
| Yes | 205272733 | CARRIER | 25VNA436A*030* | CSPH*4812AL*+UI | 59MN7B080C21**20 | 33,600 | $4,032 |
| Yes | 205272735 | CARRIER | 25VNA436A*030* | CSPH*4812AL*+UI | 59MN7B120C24**22 | 33,600 | $4,032 |
| Yes | 205272730 | CARRIER | 25VNA436A*030* | CSPH*4812AL*+UI | 59TN6B120C24**22 | 33,400 | $4,008 |
| Yes | 205272727 | CARRIER | 25VNA436A*030* | CSPH*4812AL*+UI | 58TN*A135C24**22 | 33,200 | $3,984 |
| Yes | 205272726 | CARRIER | 25VNA436A*030* | CSPH*4812AL*+UI | 58TN*A090C21**20 | 33,400 | $4,008 |
| Yes | 205272724 | CARRIER | 25VNA436A*030* | CSPH*4812AL*+UI | 58TN*A070C17**16 | 33,800 | $4,056 |
| Yes | 205272725 | CARRIER | 25VNA436A*030* | CSPH*4812AL*+UI | 58TN*A070C21**20 | 33,600 | $4,032 |
| Yes | 205272721 | CARRIER | 25VNA436A*030* | CSPH*4212AL*+UI | 58TN*A110C21**20 | 33,400 | $4,008 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205272718 | CARRIER | 25VNA436A*030* | CSPH*4212AL*+UI | 59TN6B100C21**22 | 33,400 | $4,008 |
| Yes | 205272720 | CARRIER | 25VNA436A*030* | CSPH*4212AL*+UI | 58TN*A090C17**16 | 33,600 | $4,032 |
| Yes | 205272717 | CARRIER | 25VNA436A*030* | CSPH*4212AL*+UI | 59TN6B080C21**20 | 33,600 | $4,032 |
| Yes | 205272716 | CARRIER | 25VNA436A*030* | CSPH*4212AL*+UI | 59MN7B120C24**22 | 33,600 | $4,032 |
| Yes | 205272715 | CARRIER | 25VNA436A*030* | CSPH*4212AL*+UI | 59MN7B100C21**22 | 33,400 | $4,008 |
| Yes | 205272714 | CARRIER | 25VNA436A*030* | CSPH*4212AL*+UI | 59MN7B080C21**20 | 33,600 | $4,032 |
| Yes | 205272711 | CARRIER | 25VNA436A*030* | CSPH*4212AL*+UI | 59TN6B120C24**22 | 33,400 | $4,008 |
| Yes | 205272708 | CARRIER | 25VNA436A*030* | CSPH*4212AL*+UI | 58TN*A135C24**22 | 33,400 | $4,008 |
| Yes | 205272702 | CARRIER | 25VNA436A*030* | CSPH*3612AL*+UI | 58TN*A110C21**20 | 33,600 | $4,032 |
| Yes | 205272707 | CARRIER | 25VNA436A*030* | CSPH*4212AL*+UI | 58TN*A090C21**20 | 33,400 | $4,008 |
| Yes | 205272701 | CARRIER | 25VNA436A*030* | CSPH*3612AL*+UI | 58TN*A090C17**16 | 33,800 | $4,056 |
| Yes | 205272706 | CARRIER | 25VNA436A*030* | CSPH*4212AL*+UI | 58TN*A070C21**20 | 33,600 | $4,032 |
| Yes | 205272692 | CARRIER | 25VNA436A*030* | CSPH*3612AL*+UI | 59TN6B120C24**22 | 33,600 | $4,032 |
| Yes | 205272688 | CARRIER | 25VNA436A*030* | CSPH*3612AL*+UI | 58TN*A090C21**20 | 33,600 | $4,032 |
| Yes | 205272689 | CARRIER | 25VNA436A*030* | CSPH*3612AL*+UI | 58TN*A135C24**22 | 33,400 | $4,008 |
| Yes | 205272673 | CARRIER | 25VNA436A*030* | CNPV*4824AL*+UI | 59MN7B060C21**20 | 34,000 | $4,080 |
| Yes | 205272662 | CARRIER | 25VNA436A*030* | CNPV*4821AL*+UI | 59MN7B060C21**20 | 34,000 | $4,080 |
| Yes | 205272655 | CARRIER | 25VNA436A*030* | CNPV*4821AL*+UI | 59MN7B080C17**14 | 34,000 | $4,080 |
| Yes | 205272653 | CARRIER | 25VNA436A*030* | CNPV*4821AL*+UI | 59TN6B080C17**14 | 34,000 | $4,080 |
| Yes | 205272649 | CARRIER | 25VNA436A*030* | CNPV*4821AL*+UI | 58TN*A070C17**16 | 33,800 | $4,056 |
| Yes | 205272645 | CARRIER | 25VNA436A*030* | CNPV*4221AL*+UI | 58TN*A090C17**16 | 33,800 | $4,056 |
| Yes | 205272643 | CARRIER | 25VNA436A*030* | CNPV*4221AL*+UI | 59TN6B080C21**20 | 34,000 | $4,080 |
| Yes | 205272644 | CARRIER | 25VNA436A*030* | CNPV*4221AL*+UI | 59TN6B100C21**22 | 33,800 | $4,056 |
| Yes | 205272646 | CARRIER | 25VNA436A*030* | CNPV*4221AL*+UI | 58TN*A110C21**20 | 33,800 | $4,056 |
| Yes | 205272641 | CARRIER | 25VNA436A*030* | CNPV*4221AL*+UI | 59MN7B080C21**20 | 34,000 | $4,080 |
| Yes | 205272636 | CARRIER | 25VNA436A*030* | CNPV*4221AL*+UI | 58TN*A090C21**20 | 33,800 | $4,056 |
| Yes | 205272679 | CARRIER | 25VNA436A*030* | CNPV*6024AL*+UI | 59MN7B100C21**22 | 33,000 | $3,960 |
| Yes | 205272678 | CARRIER | 25VNA436A*030* | CNPV*6024AL*+UI | 59MN7B080C21**20 | 33,200 | $3,984 |
| Yes | 205272677 | CARRIER | 25VNA436A*030* | CNPV*6024AL*+UI | 59TN6B120C24**22 | 33,000 | $3,960 |
| Yes | 205272676 | CARRIER | 25VNA436A*030* | CNPV*6024AL*+UI | 58TN*A135C24**22 | 32,800 | $3,936 |
| Yes | 205272675 | CARRIER | 25VNA436A*030* | CNPV*6024AL*+UI | 58TN*A090C21**20 | 33,000 | $3,960 |
| Yes | 205272674 | CARRIER | 25VNA436A*030* | CNPV*6024AL*+UI | 58TN*A070C21**20 | 33,200 | $3,984 |
| Yes | 205272672 | CARRIER | 25VNA436A*030* | CNPV*4824AL*+UI | 58TN*A110C21**20 | 33,400 | $4,008 |
| Yes | 205272670 | CARRIER | 25VNA436A*030* | CNPV*4824AL*+UI | 59TN6B080C21**20 | 33,600 | $4,032 |
| Yes | 205272669 | CARRIER | 25VNA436A*030* | CNPV*4824AL*+UI | 59MN7B120C24**22 | 33,400 | $4,008 |
| Yes | 205272671 | CARRIER | 25VNA436A*030* | CNPV*4824AL*+UI | 59TN6B100C21**22 | 33,400 | $4,008 |
| Yes | 205272667 | CARRIER | 25VNA436A*030* | CNPV*4824AL*+UI | 59MN7B080C21**20 | 33,600 | $4,032 |
| Yes | 205272666 | CARRIER | 25VNA436A*030* | CNPV*4824AL*+UI | 59TN6B120C24**22 | 33,400 | $4,008 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205272668 | CARRIER | 25VNA436A*030* | CNPV*4824AL*+UI | 59MN7B100C21**22 | 33,400 | $4,008 |
| Yes | 205272664 | CARRIER | 25VNA436A*030* | CNPV*4824AL*+UI | 58TN*A090C21**20 | 33,400 | $4,008 |
| Yes | 205272665 | CARRIER | 25VNA436A*030* | CNPV*4824AL*+UI | 58TN*A135C24**22 | 33,200 | $3,984 |
| Yes | 205272663 | CARRIER | 25VNA436A*030* | CNPV*4824AL*+UI | 58TN*A070C21**20 | 33,600 | $4,032 |
| Yes | 205272661 | CARRIER | 25VNA436A*030* | CNPV*4821AL*+UI | 58TN*A110C21**20 | 33,400 | $4,008 |
| Yes | 205272658 | CARRIER | 25VNA436A*030* | CNPV*4821AL*+UI | 59TN6B080C21**20 | 33,600 | $4,032 |
| Yes | 205272659 | CARRIER | 25VNA436A*030* | CNPV*4821AL*+UI | 59TN6B100C21**22 | 33,400 | $4,008 |
| Yes | 205272660 | CARRIER | 25VNA436A*030* | CNPV*4821AL*+UI | 58TN*A090C17**16 | 33,400 | $4,008 |
| Yes | 205272656 | CARRIER | 25VNA436A*030* | CNPV*4821AL*+UI | 59MN7B080C21**20 | 33,600 | $4,032 |
| Yes | 205272651 | CARRIER | 25VNA436A*030* | CNPV*4821AL*+UI | 58TN*A090C21**20 | 33,400 | $4,008 |
| Yes | 205272642 | CARRIER | 25VNA436A*030* | CNPV*4221AL*+UI | 59MN7B100C21**22 | 33,800 | $4,056 |
| Yes | 205272650 | CARRIER | 25VNA436A*030* | CNPV*4821AL*+UI | 58TN*A070C21**20 | 33,600 | $4,032 |
| Yes | 205272657 | CARRIER | 25VNA436A*030* | CNPV*4821AL*+UI | 59MN7B100C21**22 | 33,400 | $4,008 |
| Yes | 205272623 | CARRIER | 25VNA436A*030* | CAP**6124AL*+UI | 58TN*A110C21**20 | 33,000 | $3,960 |
| Yes | 205272622 | CARRIER | 25VNA436A*030* | CAP**6124AL*+UI | 59TN6B100C21**22 | 33,000 | $3,960 |
| Yes | 205272621 | CARRIER | 25VNA436A*030* | CAP**6124AL*+UI | 59TN6B080C21**20 | 33,200 | $3,984 |
| Yes | 205272618 | CARRIER | 25VNA436A*030* | CAP**6124AL*+UI | 59MN7B080C21**20 | 33,200 | $3,984 |
| Yes | 205272617 | CARRIER | 25VNA436A*030* | CAP**6124AL*+UI | 59TN6B120C24**22 | 33,000 | $3,960 |
| Yes | 205272620 | CARRIER | 25VNA436A*030* | CAP**6124AL*+UI | 59MN7B120C24**22 | 33,000 | $3,960 |
| Yes | 205272619 | CARRIER | 25VNA436A*030* | CAP**6124AL*+UI | 59MN7B100C21**22 | 33,000 | $3,960 |
| Yes | 205272616 | CARRIER | 25VNA436A*030* | CAP**6124AL*+UI | 58TN*A135C24**22 | 32,800 | $3,936 |
| Yes | 205272615 | CARRIER | 25VNA436A*030* | CAP**6124AL*+UI | 58TN*A090C21**20 | 33,000 | $3,960 |
| Yes | 205272614 | CARRIER | 25VNA436A*030* | CAP**6124AL*+UI | 58TN*A070C21**20 | 33,200 | $3,984 |
| Yes | 205272612 | CARRIER | 25VNA436A*030* | CAP**6121AL*+UI | 58TN*A110C21**20 | 33,000 | $3,960 |
| Yes | 205272611 | CARRIER | 25VNA436A*030* | CAP**6121AL*+UI | 58TN*A090C17**16 | 33,200 | $3,984 |
| Yes | 205272610 | CARRIER | 25VNA436A*030* | CAP**6121AL*+UI | 59TN6B100C21**22 | 33,000 | $3,960 |
| Yes | 205272609 | CARRIER | 25VNA436A*030* | CAP**6121AL*+UI | 59TN6B080C21**20 | 33,200 | $3,984 |
| Yes | 205272607 | CARRIER | 25VNA436A*030* | CAP**6121AL*+UI | 59MN7B080C21**20 | 33,200 | $3,984 |
| Yes | 205272608 | CARRIER | 25VNA436A*030* | CAP**6121AL*+UI | 59MN7B100C21**22 | 33,000 | $3,960 |
| Yes | 205272601 | CARRIER | 25VNA436A*030* | CAP**6121AL*+UI | 58TN*A070C21**20 | 33,200 | $3,984 |
| Yes | 205272600 | CARRIER | 25VNA436A*030* | CAP**6121AL*+UI | 58TN*A070C17**16 | 33,400 | $4,008 |
| Yes | 205272597 | CARRIER | 25VNA436A*030* | CAP**6024AL*+UI | 58TN*A110C21**20 | 32,800 | $3,936 |
| Yes | 205272602 | CARRIER | 25VNA436A*030* | CAP**6121AL*+UI | 58TN*A090C21**20 | 33,000 | $3,960 |
| Yes | 205272595 | CARRIER | 25VNA436A*030* | CAP**6024AL*+UI | 59TN6B080C21**20 | 33,000 | $3,960 |
| Yes | 205272596 | CARRIER | 25VNA436A*030* | CAP**6024AL*+UI | 59TN6B100C21**22 | 32,800 | $3,936 |
| Yes | 205272594 | CARRIER | 25VNA436A*030* | CAP**6024AL*+UI | 59MN7B120C24**22 | 33,000 | $3,960 |
| Yes | 205272591 | CARRIER | 25VNA436A*030* | CAP**6024AL*+UI | 59TN6B120C24**22 | 32,800 | $3,936 |
| Yes | 205272592 | CARRIER | 25VNA436A*030* | CAP**6024AL*+UI | 59MN7B080C21**20 | 33,000 | $3,960 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205272593 | CARRIER | 25VNA436A*030* | CAP**6024AL*+UI | 59MN7B100C21**22 | 32,800 | $3,936 |
| Yes | 205272590 | CARRIER | 25VNA436A*030* | CAP**6024AL*+UI | 58TN*A135C24**22 | 32,600 | $3,912 |
| Yes | 205272589 | CARRIER | 25VNA436A*030* | CAP**6024AL*+UI | 58TN*A090C21**20 | 32,800 | $3,936 |
| Yes | 205272586 | CARRIER | 25VNA436A*030* | CAP**4824AL*+UI | 58TN*A110C21**20 | 33,200 | $3,984 |
| Yes | 205272579 | CARRIER | 25VNA436A*030* | CAP**4824AL*+UI | 58TN*A135C24**22 | 33,000 | $3,960 |
| Yes | 205272558 | CARRIER | 25VNA436A*030* | CAP**4321AL*+UI | 59TN6B100C21**22 | 33,400 | $4,008 |
| Yes | 205272559 | CARRIER | 25VNA436A*030* | CAP**4321AL*+UI | 58TN*A090C17**16 | 33,600 | $4,032 |
| Yes | 205272578 | CARRIER | 25VNA436A*030* | CAP**4824AL*+UI | 58TN*A090C21**20 | 33,200 | $3,984 |
| Yes | 205272560 | CARRIER | 25VNA436A*030* | CAP**4321AL*+UI | 58TN*A110C21**20 | 33,400 | $4,008 |
| Yes | 205272556 | CARRIER | 25VNA436A*030* | CAP**4321AL*+UI | 59MN7B100C21**22 | 33,400 | $4,008 |
| Yes | 205272522 | CARRIER | 25VNA436A*030* | CAP**3721AL*+UI | 58TN*A110C21**20 | 33,600 | $4,032 |
| Yes | 205272521 | CARRIER | 25VNA436A*030* | CAP**3721AL*+UI | 58TN*A090C17**16 | 33,600 | $4,032 |
| Yes | 205272551 | CARRIER | 25VNA436A*030* | CAP**4321AL*+UI | 58TN*A090C21**20 | 33,400 | $4,008 |
| Yes | 205272520 | CARRIER | 25VNA436A*030* | CAP**3721AL*+UI | 59TN6B100C21**22 | 33,600 | $4,032 |
| Yes | 205272518 | CARRIER | 25VNA436A*030* | CAP**3721AL*+UI | 59MN7B100C21**22 | 33,600 | $4,032 |
| Yes | 205272506 | CARRIER | 25VNA436A*030* | FE4AN(B,F)003L+UI | | 33,000 | $3,960 |
| Yes | 205272396 | CARRIER | 25VNA424A*030* | CSPH*6012AL*+UI | 59MN7B060C17**14 | 24,000 | $2,880 |
| Yes | 205272389 | CARRIER | 25VNA424A*030* | CSPH*4812AL*+UI | 59MN7B060C21**20 | 24,200 | $2,904 |
| Yes | 205272388 | CARRIER | 25VNA424A*030* | CSPH*4812AL*+UI | 59MN7B080C17**14 | 24,200 | $2,904 |
| Yes | 205272378 | CARRIER | 25VNA424A*030* | CSPH*4212AL*+UI | 59MN7B060C17**14 | 24,400 | $2,928 |
| Yes | 205272372 | CARRIER | 25VNA424A*030* | CSPH*3612AL*+UI | 59MN7B080C21**20 | 24,200 | $2,904 |
| Yes | 205272387 | CARRIER | 25VNA424A*030* | CSPH*4812AL*+UI | 59MN7B060C17**14 | 24,400 | $2,928 |
| Yes | 205272380 | CARRIER | 25VNA424A*030* | CSPH*4212AL*+UI | 59MN7B060C21**20 | 24,200 | $2,904 |
| Yes | 205272371 | CARRIER | 25VNA424A*030* | CSPH*3612AL*+UI | 59MN7B060C21**20 | 24,400 | $2,928 |
| Yes | 205272379 | CARRIER | 25VNA424A*030* | CSPH*4212AL*+UI | 59MN7B080C17**14 | 24,200 | $2,904 |
| Yes | 205272370 | CARRIER | 25VNA424A*030* | CSPH*3612AL*+UI | 59MN7B080C17**14 | 24,400 | $2,928 |
| Yes | 205272369 | CARRIER | 25VNA424A*030* | CSPH*3612AL*+UI | 59MN7B060C17**14 | 24,400 | $2,928 |
| Yes | 205272352 | CARRIER | 25VNA424A*030* | CNPV*4821AL*+UI | 59MN7B060C17**14 | 24,400 | $2,928 |
| Yes | 205272346 | CARRIER | 25VNA424A*030* | CNPV*4221AL*+UI | 59MN7B080C17**14 | 24,400 | $2,928 |
| Yes | 205272347 | CARRIER | 25VNA424A*030* | CNPV*4221AL*+UI | 59MN7B060C21**20 | 24,400 | $2,928 |
| Yes | 205272345 | CARRIER | 25VNA424A*030* | CNPV*4221AL*+UI | 59MN7B060C17**14 | 24,400 | $2,928 |
| Yes | 205272342 | CARRIER | 25VNA424A*030* | CNPV*4217AL*+UI | 59MN7B080C17**14 | 24,400 | $2,928 |
| Yes | 205272341 | CARRIER | 25VNA424A*030* | CNPV*4217AL*+UI | 59MN7B060C17**14 | 24,400 | $2,928 |
| Yes | 205272336 | CARRIER | 25VNA424A*030* | CNPV*3621AL*+UI | 59MN7B060C21**20 | 24,400 | $2,928 |
| Yes | 205272334 | CARRIER | 25VNA424A*030* | CNPV*3621AL*+UI | 59MN7B060C17**14 | 24,600 | $2,952 |
| Yes | 205272331 | CARRIER | 25VNA424A*030* | CNPV*3617AL*+UI | 59MN7B080C17**14 | 24,400 | $2,928 |
| Yes | 205272335 | CARRIER | 25VNA424A*030* | CNPV*3621AL*+UI | 59MN7B080C17**14 | 24,400 | $2,928 |
| Yes | 205272330 | CARRIER | 25VNA424A*030* | CNPV*3617AL*+UI | 59MN7B060C17**14 | 24,600 | $2,952 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205272308 | CARRIER | 25VNA424A*030* | CAP**4224AL*+UI | 59MN7B060C21**20 | 24,200 | $2,904 |
| Yes | 205272313 | CARRIER | 25VNA424A*030* | CAP**4821AL*+UI | 59MN7B060C17**14 | 24,200 | $2,904 |
| Yes | 205272303 | CARRIER | 25VNA424A*030* | CAP**4221AL*+UI | 59MN7B060C21**20 | 24,200 | $2,904 |
| Yes | 205272302 | CARRIER | 25VNA424A*030* | CAP**4221AL*+UI | 59MN7B080C17**14 | 24,400 | $2,928 |
| Yes | 205272301 | CARRIER | 25VNA424A*030* | CAP**4221AL*+UI | 59MN7B060C17**14 | 24,400 | $2,928 |
| Yes | 205272296 | CARRIER | 25VNA424A*030* | CAP**3621AL*+UI | 59MN7B060C21**20 | 24,400 | $2,928 |
| Yes | 205272295 | CARRIER | 25VNA424A*030* | CAP**3621AL*+UI | 59MN7B080C17**14 | 24,400 | $2,928 |
| Yes | 205272294 | CARRIER | 25VNA424A*030* | CAP**3621AL*+UI | 59MN7B060C17**14 | 24,400 | $2,928 |
| Yes | 205272291 | CARRIER | 25VNA424A*030* | CAP**3617AL*+UI | 59MN7B080C17**14 | 24,400 | $2,928 |
| Yes | 205272290 | CARRIER | 25VNA424A*030* | CAP**3617AL*+UI | 59MN7B060C17**14 | 24,600 | $2,952 |
| Yes | 205272507 | CARRIER | 25VNA436A*030* | FE4ANB006L+UI | | 32,400 | $3,888 |
| Yes | 205272505 | CARRIER | 25VNA436A*030* | FE4AN(B,F)005L+UI | | 32,800 | $3,936 |
| Yes | 205272759 | CARRIER | 25VNA436A*030* | CSPH*6012AL*+UI | 58TN*A110C21**20 | 33,000 | $3,960 |
| Yes | 205272753 | CARRIER | 25VNA436A*030* | CSPH*6012AL*+UI | 59MN7B100C21**22 | 33,000 | $3,960 |
| Yes | 205272756 | CARRIER | 25VNA436A*030* | CSPH*6012AL*+UI | 59TN6B100C21**22 | 33,000 | $3,960 |
| Yes | 205272749 | CARRIER | 25VNA436A*030* | CSPH*6012AL*+UI | 59TN6B120C24**22 | 33,000 | $3,960 |
| Yes | 205272758 | CARRIER | 25VNA436A*030* | CSPH*6012AL*+UI | 58TN*A090C17**16 | 33,000 | $3,960 |
| Yes | 205272746 | CARRIER | 25VNA436A*030* | CSPH*6012AL*+UI | 58TN*A135C24**22 | 32,800 | $3,936 |
| Yes | 205272684 | CARRIER | 25VNA436A*030* | CNPV*6024AL*+UI | 59MN7B060C21**20 | 33,600 | $4,032 |
| Yes | 205272745 | CARRIER | 25VNA436A*030* | CSPH*6012AL*+UI | 58TN*A090C21**20 | 32,800 | $3,936 |
| Yes | 205272683 | CARRIER | 25VNA436A*030* | CNPV*6024AL*+UI | 58TN*A110C21**20 | 33,000 | $3,960 |
| Yes | 205272681 | CARRIER | 25VNA436A*030* | CNPV*6024AL*+UI | 59TN6B080C21**20 | 33,200 | $3,984 |
| Yes | 205272682 | CARRIER | 25VNA436A*030* | CNPV*6024AL*+UI | 59TN6B100C21**22 | 33,000 | $3,960 |
| Yes | 205272680 | CARRIER | 25VNA436A*030* | CNPV*6024AL*+UI | 59MN7B120C24**22 | 33,200 | $3,984 |
| Yes | 205272414 | CARRIER | 25VNA424A*030* | CAP**3621AL*+UI | 59TN6B080C17**14 | 24,400 | $2,928 |
| Yes | 205272413 | CARRIER | 25VNA424A*030* | CAP**3621AL*+UI | 59TN6B060C17**14 | 24,400 | $2,928 |
| Yes | 205272412 | CARRIER | 25VNA424A*030* | CAP**3621AL*+UI | 58TN*A090C21**20 | 24,200 | $2,904 |
| Yes | 205272411 | CARRIER | 25VNA424A*030* | CAP**3621AL*+UI | 58TN*A070C21**20 | 24,200 | $2,904 |
| Yes | 205272409 | CARRIER | 25VNA424A*030* | CAP**3621AL*+UI | 58TN*A045C17**12 | 24,400 | $2,928 |
| Yes | 205272410 | CARRIER | 25VNA424A*030* | CAP**3621AL*+UI | 58TN*A070C17**16 | 24,200 | $2,904 |
| Yes | 205272408 | CARRIER | 25VNA424A*030* | CAP**3617AL*+UI | 59TN6B080C17**14 | 24,400 | $2,928 |
| Yes | 205272407 | CARRIER | 25VNA424A*030* | CAP**3617AL*+UI | 59TN6B060C17**14 | 24,400 | $2,928 |
| Yes | 205272406 | CARRIER | 25VNA424A*030* | CAP**3617AL*+UI | 58TN*A070C17**16 | 24,400 | $2,928 |
| Yes | 205272404 | CARRIER | 25VNA424A*030* | CSPH*6012AL*+UI | 58TN*A110C21**20 | 23,800 | $2,856 |
| Yes | 205272402 | CARRIER | 25VNA424A*030* | CSPH*6012AL*+UI | 58TN*A070C14**12 | 23,800 | $2,856 |
| Yes | 205272403 | CARRIER | 25VNA424A*030* | CSPH*6012AL*+UI | 58TN*A090C17**16 | 23,800 | $2,856 |
| Yes | 205272405 | CARRIER | 25VNA424A*030* | CAP**3617AL*+UI | 58TN*A045C17**12 | 24,400 | $2,928 |
| Yes | 205272401 | CARRIER | 25VNA424A*030* | CSPH*6012AL*+UI | 59MN7B120C24**22 | 23,800 | $2,856 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205272400 | CARRIER | 25VNA424A*030* | CSPH*6012AL*+UI | 59MN7B100C21**22 | 23,800 | $2,856 |
| Yes | 205272399 | CARRIER | 25VNA424A*030* | CSPH*6012AL*+UI | 59MN7B080C21**20 | 23,800 | $2,856 |
| Yes | 205272398 | CARRIER | 25VNA424A*030* | CSPH*6012AL*+UI | 59MN7B060C21**20 | 23,800 | $2,856 |
| Yes | 205272397 | CARRIER | 25VNA424A*030* | CSPH*6012AL*+UI | 59MN7B080C17**14 | 24,000 | $2,880 |
| Yes | 205272395 | CARRIER | 25VNA424A*030* | CSPH*4812AL*+UI | 58TN*A110C21**20 | 24,000 | $2,880 |
| Yes | 205272393 | CARRIER | 25VNA424A*030* | CSPH*4812AL*+UI | 58TN*A070C14**12 | 24,200 | $2,904 |
| Yes | 205272394 | CARRIER | 25VNA424A*030* | CSPH*4812AL*+UI | 58TN*A090C17**16 | 24,000 | $2,880 |
| Yes | 205272392 | CARRIER | 25VNA424A*030* | CSPH*4812AL*+UI | 59MN7B120C24**22 | 24,000 | $2,880 |
| Yes | 205272391 | CARRIER | 25VNA424A*030* | CSPH*4812AL*+UI | 59MN7B100C21**22 | 24,000 | $2,880 |
| Yes | 205272390 | CARRIER | 25VNA424A*030* | CSPH*4812AL*+UI | 59MN7B080C21**20 | 24,000 | $2,880 |
| Yes | 205272386 | CARRIER | 25VNA424A*030* | CSPH*4212AL*+UI | 58TN*A110C21**20 | 24,000 | $2,880 |
| Yes | 205272384 | CARRIER | 25VNA424A*030* | CSPH*4212AL*+UI | 58TN*A070C14**12 | 24,200 | $2,904 |
| Yes | 205272383 | CARRIER | 25VNA424A*030* | CSPH*4212AL*+UI | 59MN7B120C24**22 | 24,200 | $2,904 |
| Yes | 205272385 | CARRIER | 25VNA424A*030* | CSPH*4212AL*+UI | 58TN*A090C17**16 | 24,000 | $2,880 |
| Yes | 205272382 | CARRIER | 25VNA424A*030* | CSPH*4212AL*+UI | 59MN7B100C21**22 | 24,000 | $2,880 |
| Yes | 205272381 | CARRIER | 25VNA424A*030* | CSPH*4212AL*+UI | 59MN7B080C21**20 | 24,200 | $2,904 |
| Yes | 205272376 | CARRIER | 25VNA424A*030* | CSPH*3612AL*+UI | 58TN*A090C17**16 | 24,200 | $2,904 |
| Yes | 205272375 | CARRIER | 25VNA424A*030* | CSPH*3612AL*+UI | 58TN*A070C14**12 | 24,200 | $2,904 |
| Yes | 205272374 | CARRIER | 25VNA424A*030* | CSPH*3612AL*+UI | 59MN7B120C24**22 | 24,200 | $2,904 |
| Yes | 205272377 | CARRIER | 25VNA424A*030* | CSPH*3612AL*+UI | 58TN*A110C21**20 | 24,200 | $2,904 |
| Yes | 205272368 | CARRIER | 25VNA424A*030* | CNPV*6024AL*+UI | 58TN*A110C21**20 | 23,800 | $2,856 |
| Yes | 205272367 | CARRIER | 25VNA424A*030* | CNPV*6024AL*+UI | 59MN7B120C24**22 | 23,800 | $2,856 |
| Yes | 205272366 | CARRIER | 25VNA424A*030* | CNPV*6024AL*+UI | 59MN7B100C21**22 | 23,800 | $2,856 |
| Yes | 205272373 | CARRIER | 25VNA424A*030* | CSPH*3612AL*+UI | 59MN7B100C21**22 | 24,200 | $2,904 |
| Yes | 205272365 | CARRIER | 25VNA424A*030* | CNPV*6024AL*+UI | 59MN7B080C21**20 | 23,800 | $2,856 |
| Yes | 205272364 | CARRIER | 25VNA424A*030* | CNPV*6024AL*+UI | 59MN7B060C21**20 | 24,000 | $2,880 |
| Yes | 205272363 | CARRIER | 25VNA424A*030* | CNPV*4824AL*+UI | 58TN*A110C21**20 | 24,000 | $2,880 |
| Yes | 205272362 | CARRIER | 25VNA424A*030* | CNPV*4824AL*+UI | 59MN7B120C24**22 | 24,000 | $2,880 |
| Yes | 205272361 | CARRIER | 25VNA424A*030* | CNPV*4824AL*+UI | 59MN7B100C21**22 | 24,000 | $2,880 |
| Yes | 205272360 | CARRIER | 25VNA424A*030* | CNPV*4824AL*+UI | 59MN7B080C21**20 | 24,000 | $2,880 |
| Yes | 205272359 | CARRIER | 25VNA424A*030* | CNPV*4824AL*+UI | 59MN7B060C21**20 | 24,200 | $2,904 |
| Yes | 205272357 | CARRIER | 25VNA424A*030* | CNPV*4821AL*+UI | 58TN*A090C17**16 | 24,000 | $2,880 |
| Yes | 205272356 | CARRIER | 25VNA424A*030* | CNPV*4821AL*+UI | 59MN7B100C21**22 | 24,000 | $2,880 |
| Yes | 205272355 | CARRIER | 25VNA424A*030* | CNPV*4821AL*+UI | 59MN7B080C21**20 | 24,000 | $2,880 |
| Yes | 205272358 | CARRIER | 25VNA424A*030* | CNPV*4821AL*+UI | 58TN*A110C21**20 | 24,000 | $2,880 |
| Yes | 205272354 | CARRIER | 25VNA424A*030* | CNPV*4821AL*+UI | 59MN7B060C21**20 | 24,200 | $2,904 |
| Yes | 205272353 | CARRIER | 25VNA424A*030* | CNPV*4821AL*+UI | 59MN7B080C17**14 | 24,200 | $2,904 |
| Yes | 205272351 | CARRIER | 25VNA424A*030* | CNPV*4221AL*+UI | 58TN*A110C21**20 | 24,200 | $2,904 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205272350 | CARRIER | 25VNA424A*030* | CNPV*4221AL*+UI | 58TN*A090C17**16 | 24,200 | $2,904 |
| Yes | 205272348 | CARRIER | 25VNA424A*030* | CNPV*4221AL*+UI | 59MN7B080C21**20 | 24,200 | $2,904 |
| Yes | 205272349 | CARRIER | 25VNA424A*030* | CNPV*4221AL*+UI | 59MN7B100C21**22 | 24,200 | $2,904 |
| Yes | 205272344 | CARRIER | 25VNA424A*030* | CNPV*4217AL*+UI | 58TN*A090C17**16 | 24,200 | $2,904 |
| Yes | 205272343 | CARRIER | 25VNA424A*030* | CNPV*4217AL*+UI | 58TN*A070C14**12 | 24,200 | $2,904 |
| Yes | 205272340 | CARRIER | 25VNA424A*030* | CNPV*3621AL*+UI | 58TN*A110C21**20 | 24,200 | $2,904 |
| Yes | 205272339 | CARRIER | 25VNA424A*030* | CNPV*3621AL*+UI | 58TN*A090C17**16 | 24,200 | $2,904 |
| Yes | 205272338 | CARRIER | 25VNA424A*030* | CNPV*3621AL*+UI | 59MN7B100C21**22 | 24,400 | $2,928 |
| Yes | 205272332 | CARRIER | 25VNA424A*030* | CNPV*3617AL*+UI | 58TN*A070C14**12 | 24,400 | $2,928 |
| Yes | 205272333 | CARRIER | 25VNA424A*030* | CNPV*3617AL*+UI | 58TN*A090C17**16 | 24,200 | $2,904 |
| Yes | 205272337 | CARRIER | 25VNA424A*030* | CNPV*3621AL*+UI | 59MN7B080C21**20 | 24,400 | $2,928 |
| Yes | 205272329 | CARRIER | 25VNA424A*030* | CAP**6024AL*+UI | 58TN*A110C21**20 | 23,600 | $2,832 |
| Yes | 205272328 | CARRIER | 25VNA424A*030* | CAP**6024AL*+UI | 59MN7B120C24**22 | 23,600 | $2,832 |
| Yes | 205272327 | CARRIER | 25VNA424A*030* | CAP**6024AL*+UI | 59MN7B100C21**22 | 23,600 | $2,832 |
| Yes | 205272326 | CARRIER | 25VNA424A*030* | CAP**6024AL*+UI | 59MN7B080C21**20 | 23,600 | $2,832 |
| Yes | 205272325 | CARRIER | 25VNA424A*030* | CAP**6024AL*+UI | 59MN7B060C21**20 | 23,800 | $2,856 |
| Yes | 205272323 | CARRIER | 25VNA424A*030* | CAP**4824AL*+UI | 59MN7B120C24**22 | 24,000 | $2,880 |
| Yes | 205272324 | CARRIER | 25VNA424A*030* | CAP**4824AL*+UI | 58TN*A110C21**20 | 23,800 | $2,856 |
| Yes | 205272322 | CARRIER | 25VNA424A*030* | CAP**4824AL*+UI | 59MN7B100C21**22 | 23,800 | $2,856 |
| Yes | 205272321 | CARRIER | 25VNA424A*030* | CAP**4824AL*+UI | 59MN7B080C21**20 | 24,000 | $2,880 |
| Yes | 205272320 | CARRIER | 25VNA424A*030* | CAP**4824AL*+UI | 59MN7B060C21**20 | 24,000 | $2,880 |
| Yes | 205272319 | CARRIER | 25VNA424A*030* | CAP**4821AL*+UI | 58TN*A110C21**20 | 23,800 | $2,856 |
| Yes | 205272318 | CARRIER | 25VNA424A*030* | CAP**4821AL*+UI | 58TN*A090C17**16 | 23,800 | $2,856 |
| Yes | 205272317 | CARRIER | 25VNA424A*030* | CAP**4821AL*+UI | 59MN7B100C21**22 | 24,000 | $2,880 |
| Yes | 205272316 | CARRIER | 25VNA424A*030* | CAP**4821AL*+UI | 59MN7B080C21**20 | 24,000 | $2,880 |
| Yes | 205272315 | CARRIER | 25VNA424A*030* | CAP**4821AL*+UI | 59MN7B060C21**20 | 24,000 | $2,880 |
| Yes | 205272312 | CARRIER | 25VNA424A*030* | CAP**4224AL*+UI | 58TN*A110C21**20 | 24,200 | $2,904 |
| Yes | 205272314 | CARRIER | 25VNA424A*030* | CAP**4821AL*+UI | 59MN7B080C17**14 | 24,000 | $2,880 |
| Yes | 205272311 | CARRIER | 25VNA424A*030* | CAP**4224AL*+UI | 59MN7B120C24**22 | 24,200 | $2,904 |
| Yes | 205272310 | CARRIER | 25VNA424A*030* | CAP**4224AL*+UI | 59MN7B100C21**22 | 24,200 | $2,904 |
| Yes | 205272309 | CARRIER | 25VNA424A*030* | CAP**4224AL*+UI | 59MN7B080C21**20 | 24,200 | $2,904 |
| Yes | 205272307 | CARRIER | 25VNA424A*030* | CAP**4221AL*+UI | 58TN*A110C21**20 | 24,200 | $2,904 |
| Yes | 205272306 | CARRIER | 25VNA424A*030* | CAP**4221AL*+UI | 58TN*A090C17**16 | 24,200 | $2,904 |
| Yes | 205272305 | CARRIER | 25VNA424A*030* | CAP**4221AL*+UI | 59MN7B100C21**22 | 24,200 | $2,904 |
| Yes | 205272304 | CARRIER | 25VNA424A*030* | CAP**4221AL*+UI | 59MN7B080C21**20 | 24,200 | $2,904 |
| Yes | 205272300 | CARRIER | 25VNA424A*030* | CAP**3621AL*+UI | 58TN*A110C21**20 | 24,200 | $2,904 |
| Yes | 205272299 | CARRIER | 25VNA424A*030* | CAP**3621AL*+UI | 58TN*A090C17**16 | 24,200 | $2,904 |
| Yes | 205272298 | CARRIER | 25VNA424A*030* | CAP**3621AL*+UI | 59MN7B100C21**22 | 24,200 | $2,904 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205272297 | CARRIER | 25VNA424A*030* | CAP**3621AL*+UI | 59MN7B080C21**20 | 24,200 | $2,904 |
| Yes | 205272293 | CARRIER | 25VNA424A*030* | CAP**3617AL*+UI | 58TN*A090C17**16 | 24,200 | $2,904 |
| Yes | 205272292 | CARRIER | 25VNA424A*030* | CAP**3617AL*+UI | 58TN*A070C14**12 | 24,400 | $2,928 |
| Yes | 205272287 | CARRIER | 25VNA424A*030* | FE4ANF002L+UI | | 24,400 | $2,928 |
| Yes | 205272289 | CARRIER | 25VNA424A*030* | FE4AN(B,F)005L+UI | | 23,600 | $2,832 |
| Yes | 205272288 | CARRIER | 25VNA424A*030* | FE4AN(B,F)003L+UI | | 24,200 | $2,904 |
| Yes | 205272504 | CARRIER | 25VNA424A*030* | CSPH*6012AL*+UI | 59TN6B120C24**22 | 23,800 | $2,856 |
| Yes | 205272503 | CARRIER | 25VNA424A*030* | CSPH*6012AL*+UI | 59TN6B080C17**14 | 24,000 | $2,880 |
| Yes | 205272502 | CARRIER | 25VNA424A*030* | CSPH*6012AL*+UI | 59TN6B060C17**14 | 24,000 | $2,880 |
| Yes | 205272501 | CARRIER | 25VNA424A*030* | CSPH*6012AL*+UI | 58TN*A135C24**22 | 23,800 | $2,856 |
| Yes | 205272500 | CARRIER | 25VNA424A*030* | CSPH*6012AL*+UI | 58TN*A090C21**20 | 23,800 | $2,856 |
| Yes | 205272498 | CARRIER | 25VNA424A*030* | CSPH*6012AL*+UI | 58TN*A070C17**16 | 23,800 | $2,856 |
| Yes | 205272499 | CARRIER | 25VNA424A*030* | CSPH*6012AL*+UI | 58TN*A070C21**20 | 23,800 | $2,856 |
| Yes | 205272497 | CARRIER | 25VNA424A*030* | CSPH*6012AL*+UI | 58TN*A045C17**12 | 24,000 | $2,880 |
| Yes | 205272496 | CARRIER | 25VNA424A*030* | CSPH*4812AL*+UI | 59TN6B120C24**22 | 24,000 | $2,880 |
| Yes | 205272495 | CARRIER | 25VNA424A*030* | CSPH*4812AL*+UI | 59TN6B080C17**14 | 24,200 | $2,904 |
| Yes | 205272494 | CARRIER | 25VNA424A*030* | CSPH*4812AL*+UI | 59TN6B060C17**14 | 24,200 | $2,904 |
| Yes | 205272493 | CARRIER | 25VNA424A*030* | CSPH*4812AL*+UI | 58TN*A135C24**22 | 24,000 | $2,880 |
| Yes | 205272492 | CARRIER | 25VNA424A*030* | CSPH*4812AL*+UI | 58TN*A090C21**20 | 24,000 | $2,880 |
| Yes | 205272490 | CARRIER | 25VNA424A*030* | CSPH*4812AL*+UI | 58TN*A070C17**16 | 24,200 | $2,904 |
| Yes | 205272489 | CARRIER | 25VNA424A*030* | CSPH*4812AL*+UI | 58TN*A045C17**12 | 24,200 | $2,904 |
| Yes | 205272487 | CARRIER | 25VNA424A*030* | CSPH*4212AL*+UI | 59TN6B080C17**14 | 24,200 | $2,904 |
| Yes | 205272488 | CARRIER | 25VNA424A*030* | CSPH*4212AL*+UI | 59TN6B120C24**22 | 24,200 | $2,904 |
| Yes | 205272491 | CARRIER | 25VNA424A*030* | CSPH*4812AL*+UI | 58TN*A070C21**20 | 24,200 | $2,904 |
| Yes | 205272486 | CARRIER | 25VNA424A*030* | CSPH*4212AL*+UI | 59TN6B060C17**14 | 24,400 | $2,928 |
| Yes | 205272484 | CARRIER | 25VNA424A*030* | CSPH*4212AL*+UI | 58TN*A090C21**20 | 24,000 | $2,880 |
| Yes | 205272485 | CARRIER | 25VNA424A*030* | CSPH*4212AL*+UI | 58TN*A135C24**22 | 24,000 | $2,880 |
| Yes | 205272482 | CARRIER | 25VNA424A*030* | CSPH*4212AL*+UI | 58TN*A070C17**16 | 24,200 | $2,904 |
| Yes | 205272483 | CARRIER | 25VNA424A*030* | CSPH*4212AL*+UI | 58TN*A070C21**20 | 24,200 | $2,904 |
| Yes | 205272481 | CARRIER | 25VNA424A*030* | CSPH*4212AL*+UI | 58TN*A045C17**12 | 24,400 | $2,928 |
| Yes | 205272480 | CARRIER | 25VNA424A*030* | CSPH*3612AL*+UI | 59TN6B120C24**22 | 24,200 | $2,904 |
| Yes | 205272479 | CARRIER | 25VNA424A*030* | CSPH*3612AL*+UI | 59TN6B080C17**14 | 24,400 | $2,928 |
| Yes | 205272477 | CARRIER | 25VNA424A*030* | CSPH*3612AL*+UI | 58TN*A135C24**22 | 24,200 | $2,904 |
| Yes | 205272478 | CARRIER | 25VNA424A*030* | CSPH*3612AL*+UI | 59TN6B060C17**14 | 24,400 | $2,928 |
| Yes | 205272476 | CARRIER | 25VNA424A*030* | CSPH*3612AL*+UI | 58TN*A090C21**20 | 24,200 | $2,904 |
| Yes | 205272475 | CARRIER | 25VNA424A*030* | CSPH*3612AL*+UI | 58TN*A070C21**20 | 24,200 | $2,904 |
| Yes | 205272473 | CARRIER | 25VNA424A*030* | CSPH*3612AL*+UI | 58TN*A045C17**12 | 24,400 | $2,928 |
| Yes | 205272474 | CARRIER | 25VNA424A*030* | CSPH*3612AL*+UI | 58TN*A070C17**16 | 24,200 | $2,904 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205272472 | CARRIER | 25VNA424A*030* | CNPV*6024AL*+UI | 59TN6B120C24**22 | 23,800 | $2,856 |
| Yes | 205272471 | CARRIER | 25VNA424A*030* | CNPV*6024AL*+UI | 58TN*A135C24**22 | 23,800 | $2,856 |
| Yes | 205272469 | CARRIER | 25VNA424A*030* | CNPV*6024AL*+UI | 58TN*A070C21**20 | 23,800 | $2,856 |
| Yes | 205272470 | CARRIER | 25VNA424A*030* | CNPV*6024AL*+UI | 58TN*A090C21**20 | 23,800 | $2,856 |
| Yes | 205272468 | CARRIER | 25VNA424A*030* | CNPV*4824AL*+UI | 59TN6B120C24**22 | 24,000 | $2,880 |
| Yes | 205272467 | CARRIER | 25VNA424A*030* | CNPV*4824AL*+UI | 58TN*A135C24**22 | 24,000 | $2,880 |
| Yes | 205272466 | CARRIER | 25VNA424A*030* | CNPV*4824AL*+UI | 58TN*A090C21**20 | 24,000 | $2,880 |
| Yes | 205272463 | CARRIER | 25VNA424A*030* | CNPV*4821AL*+UI | 59TN6B060C17**14 | 24,200 | $2,904 |
| Yes | 205272464 | CARRIER | 25VNA424A*030* | CNPV*4821AL*+UI | 59TN6B080C17**14 | 24,200 | $2,904 |
| Yes | 205272461 | CARRIER | 25VNA424A*030* | CNPV*4821AL*+UI | 58TN*A070C21**20 | 24,200 | $2,904 |
| Yes | 205272465 | CARRIER | 25VNA424A*030* | CNPV*4824AL*+UI | 58TN*A070C21**20 | 24,200 | $2,904 |
| Yes | 205272462 | CARRIER | 25VNA424A*030* | CNPV*4821AL*+UI | 58TN*A090C21**20 | 24,000 | $2,880 |
| Yes | 205272460 | CARRIER | 25VNA424A*030* | CNPV*4821AL*+UI | 58TN*A070C17**16 | 24,200 | $2,904 |
| Yes | 205272458 | CARRIER | 25VNA424A*030* | CNPV*4221AL*+UI | 59TN6B080C17**14 | 24,400 | $2,928 |
| Yes | 205272459 | CARRIER | 25VNA424A*030* | CNPV*4821AL*+UI | 58TN*A045C17**12 | 24,200 | $2,904 |
| Yes | 205272456 | CARRIER | 25VNA424A*030* | CNPV*4221AL*+UI | 58TN*A090C21**20 | 24,200 | $2,904 |
| Yes | 205272455 | CARRIER | 25VNA424A*030* | CNPV*4221AL*+UI | 58TN*A070C21**20 | 24,200 | $2,904 |
| Yes | 205272454 | CARRIER | 25VNA424A*030* | CNPV*4221AL*+UI | 58TN*A070C17**16 | 24,400 | $2,928 |
| Yes | 205272453 | CARRIER | 25VNA424A*030* | CNPV*4221AL*+UI | 58TN*A045C17**12 | 24,400 | $2,928 |
| Yes | 205272457 | CARRIER | 25VNA424A*030* | CNPV*4221AL*+UI | 59TN6B060C17**14 | 24,400 | $2,928 |
| Yes | 205272452 | CARRIER | 25VNA424A*030* | CNPV*4217AL*+UI | 59TN6B080C17**14 | 24,400 | $2,928 |
| Yes | 205272450 | CARRIER | 25VNA424A*030* | CNPV*4217AL*+UI | 58TN*A070C17**16 | 24,200 | $2,904 |
| Yes | 205272451 | CARRIER | 25VNA424A*030* | CNPV*4217AL*+UI | 59TN6B060C17**14 | 24,400 | $2,928 |
| Yes | 205272449 | CARRIER | 25VNA424A*030* | CNPV*4217AL*+UI | 58TN*A045C17**12 | 24,400 | $2,928 |
| Yes | 205272446 | CARRIER | 25VNA424A*030* | CNPV*3621AL*+UI | 58TN*A090C21**20 | 24,200 | $2,904 |
| Yes | 205272445 | CARRIER | 25VNA424A*030* | CNPV*3621AL*+UI | 58TN*A070C21**20 | 24,400 | $2,928 |
| Yes | 205272444 | CARRIER | 25VNA424A*030* | CNPV*3621AL*+UI | 58TN*A070C17**16 | 24,400 | $2,928 |
| Yes | 205272448 | CARRIER | 25VNA424A*030* | CNPV*3621AL*+UI | 59TN6B080C17**14 | 24,400 | $2,928 |
| Yes | 205272443 | CARRIER | 25VNA424A*030* | CNPV*3621AL*+UI | 58TN*A045C17**12 | 24,600 | $2,952 |
| Yes | 205272447 | CARRIER | 25VNA424A*030* | CNPV*3621AL*+UI | 59TN6B060C17**14 | 24,600 | $2,952 |
| Yes | 205272442 | CARRIER | 25VNA424A*030* | CNPV*3617AL*+UI | 59TN6B080C17**14 | 24,400 | $2,928 |
| Yes | 205272441 | CARRIER | 25VNA424A*030* | CNPV*3617AL*+UI | 59TN6B060C17**14 | 24,600 | $2,952 |
| Yes | 205272438 | CARRIER | 25VNA424A*030* | CAP**6024AL*+UI | 59TN6B120C24**22 | 23,600 | $2,832 |
| Yes | 205272439 | CARRIER | 25VNA424A*030* | CNPV*3617AL*+UI | 58TN*A045C17**12 | 24,600 | $2,952 |
| Yes | 205272435 | CARRIER | 25VNA424A*030* | CAP**6024AL*+UI | 58TN*A070C21**20 | 23,600 | $2,832 |
| Yes | 205272440 | CARRIER | 25VNA424A*030* | CNPV*3617AL*+UI | 58TN*A070C17**16 | 24,400 | $2,928 |
| Yes | 205272437 | CARRIER | 25VNA424A*030* | CAP**6024AL*+UI | 58TN*A135C24**22 | 23,600 | $2,832 |
| Yes | 205272434 | CARRIER | 25VNA424A*030* | CAP**4824AL*+UI | 59TN6B120C24**22 | 24,000 | $2,880 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205272436 | CARRIER | 25VNA424A*030* | CAP**6024AL*+UI | 58TN*A090C21**20 | 23,600 | $2,832 |
| Yes | 205272433 | CARRIER | 25VNA424A*030* | CAP**4824AL*+UI | 58TN*A135C24**22 | 23,800 | $2,856 |
| Yes | 205272432 | CARRIER | 25VNA424A*030* | CAP**4824AL*+UI | 58TN*A090C21**20 | 23,800 | $2,856 |
| Yes | 205272431 | CARRIER | 25VNA424A*030* | CAP**4824AL*+UI | 58TN*A070C21**20 | 24,000 | $2,880 |
| Yes | 205272429 | CARRIER | 25VNA424A*030* | CAP**4821AL*+UI | 59TN6B060C17**14 | 24,200 | $2,904 |
| Yes | 205272430 | CARRIER | 25VNA424A*030* | CAP**4821AL*+UI | 59TN6B080C17**14 | 24,000 | $2,880 |
| Yes | 205272427 | CARRIER | 25VNA424A*030* | CAP**4821AL*+UI | 58TN*A070C21**20 | 24,000 | $2,880 |
| Yes | 205272428 | CARRIER | 25VNA424A*030* | CAP**4821AL*+UI | 58TN*A090C21**20 | 23,800 | $2,856 |
| Yes | 205272426 | CARRIER | 25VNA424A*030* | CAP**4821AL*+UI | 58TN*A070C17**16 | 24,000 | $2,880 |
| Yes | 205272425 | CARRIER | 25VNA424A*030* | CAP**4821AL*+UI | 58TN*A045C17**12 | 24,200 | $2,904 |
| Yes | 205272424 | CARRIER | 25VNA424A*030* | CAP**4224AL*+UI | 59TN6B120C24**22 | 24,200 | $2,904 |
| Yes | 205272422 | CARRIER | 25VNA424A*030* | CAP**4224AL*+UI | 58TN*A090C21**20 | 24,200 | $2,904 |
| Yes | 205272423 | CARRIER | 25VNA424A*030* | CAP**4224AL*+UI | 58TN*A135C24**22 | 24,000 | $2,880 |
| Yes | 205272421 | CARRIER | 25VNA424A*030* | CAP**4224AL*+UI | 58TN*A070C21**20 | 24,200 | $2,904 |
| Yes | 205272420 | CARRIER | 25VNA424A*030* | CAP**4221AL*+UI | 59TN6B080C17**14 | 24,400 | $2,928 |
| Yes | 205272419 | CARRIER | 25VNA424A*030* | CAP**4221AL*+UI | 59TN6B060C17**14 | 24,400 | $2,928 |
| Yes | 205272417 | CARRIER | 25VNA424A*030* | CAP**4221AL*+UI | 58TN*A070C21**20 | 24,200 | $2,904 |
| Yes | 205272418 | CARRIER | 25VNA424A*030* | CAP**4221AL*+UI | 58TN*A090C21**20 | 24,200 | $2,904 |
| Yes | 205272416 | CARRIER | 25VNA424A*030* | CAP**4221AL*+UI | 58TN*A070C17**16 | 24,200 | $2,904 |
| Yes | 205272415 | CARRIER | 25VNA424A*030* | CAP**4221AL*+UI | 58TN*A045C17**12 | 24,400 | $2,928 |
| Yes | 204344192 | CARRIER | 38MAQB30R--3 | FV4CN(B,F)003 | | 20,200 | $2,424 |
| Yes | 204344191 | CARRIER | 38MAQB24R--3 | FV4CNF002 | | 14,000 | $1,680 |
| Yes | 203380994 | CARRIER | 38MAQB18R--3 | FM(C,U)4Z18**AL* | | 12,200 | $1,464 |
| Yes | 203380995 | CARRIER | 38MAQB24R--3 | FM(C,U)4Z24**AL* | | 15,000 | $1,800 |
| Yes | 9892568 | CARRIER | 25VNA024A*030* | CAP**4224AL*+UI & 59MN7A060V21**20 | | 25,200 | $3,024 |
| Yes | 9892565 | CARRIER | 25VNA024A*030* | CAP**4221AL*+UI & 59MN7A060V21**20 | | 25,200 | $3,024 |
| Yes | 204430057 | CARRIER | 25VNA024A*030* | CNPV*3621AL*+UI | 59TN6B080C21**20 | 25,000 | $3,000 |
| Yes | 205272695 | CARRIER | 25VNA436A*030* | CSPH*3612AL*+UI | 59MN7B080C21**20 | 33,800 | $4,056 |
| Yes | 205272696 | CARRIER | 25VNA436A*030* | CSPH*3612AL*+UI | 59MN7B100C21**22 | 33,600 | $4,032 |
| Yes | 205272697 | CARRIER | 25VNA436A*030* | CSPH*3612AL*+UI | 59MN7B120C24**22 | 33,800 | $4,056 |
| Yes | 205272698 | CARRIER | 25VNA436A*030* | CSPH*3612AL*+UI | 59TN6B080C21**20 | 33,800 | $4,056 |
| Yes | 205272699 | CARRIER | 25VNA436A*030* | CSPH*3612AL*+UI | 59TN6B100C21**22 | 33,600 | $4,032 |
| Yes | 207642889 | CARRIER | 38MGHBQ48EA3 | Heat pump with ducts | | 28,000 | $3,360 |
| Yes | 207642883 | CARRIER | 38MGHBQ30DA3 | Heat pump with ducts | | 19,000 | $2,280 |
| Yes | 207642892 | CARRIER | 38MGHBQ36DA3 | Heat pump with ducts | | 23,000 | $2,760 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 207642884 | CARRIER | 38MGHBQ30DA3 | Combination heat pumps with or without ducts | | 18,200 | $2,184 |
| Yes | 207642890 | CARRIER | 38MGHBQ48EA3 | Combination heat pumps with or without ducts | | 29,000 | $3,480 |
| Yes | 207642893 | CARRIER | 38MGHBQ36DA3 | Combination heat pumps with or without ducts | | 23,000 | $2,760 |
| Yes | 206788752 | CARRIER | 25VNA436A*031* | CSPH*3612AL*+UI | 59TN6B100C21**22 | 33,600 | $4,032 |
| Yes | 206788751 | CARRIER | 25VNA436A*031* | CSPH*3612AL*+UI | 59TN6B080C21**20 | 33,800 | $4,056 |
| Yes | 206788750 | CARRIER | 25VNA436A*031* | CSPH*3612AL*+UI | 59MN7B120C24**22 | 33,800 | $4,056 |
| Yes | 206788749 | CARRIER | 25VNA436A*031* | CSPH*3612AL*+UI | 59MN7B100C21**22 | 33,600 | $4,032 |
| Yes | 206788748 | CARRIER | 25VNA436A*031* | CSPH*3612AL*+UI | 59MN7B080C21**20 | 33,800 | $4,056 |
| Yes | 206788332 | CARRIER | 25VNA424A*031* | CAP**3617AL*+UI | 59MN7B060C17**14 | 24,600 | $2,952 |
| Yes | 206788333 | CARRIER | 25VNA424A*031* | CAP**3617AL*+UI | 59MN7B080C17**14 | 24,400 | $2,928 |
| Yes | 206788337 | CARRIER | 25VNA424A*031* | CAP**3621AL*+UI | 59MN7B080C17**14 | 24,400 | $2,928 |
| Yes | 206788343 | CARRIER | 25VNA424A*031* | CAP**4221AL*+UI | 59MN7B060C17**14 | 24,400 | $2,928 |
| Yes | 206788338 | CARRIER | 25VNA424A*031* | CAP**3621AL*+UI | 59MN7B060C21**20 | 24,400 | $2,928 |
| Yes | 206788344 | CARRIER | 25VNA424A*031* | CAP**4221AL*+UI | 59MN7B080C17**14 | 24,400 | $2,928 |
| Yes | 206788355 | CARRIER | 25VNA424A*031* | CAP**4821AL*+UI | 59MN7B060C17**14 | 24,200 | $2,904 |
| Yes | 206788372 | CARRIER | 25VNA424A*031* | CNPV*3617AL*+UI | 59MN7B060C17**14 | 24,600 | $2,952 |
| Yes | 206788384 | CARRIER | 25VNA424A*031* | CNPV*4217AL*+UI | 59MN7B080C17**14 | 24,400 | $2,928 |
| Yes | 206788376 | CARRIER | 25VNA424A*031* | CNPV*3621AL*+UI | 59MN7B060C17**14 | 24,600 | $2,952 |
| Yes | 206788388 | CARRIER | 25VNA424A*031* | CNPV*4221AL*+UI | 59MN7B080C17**14 | 24,400 | $2,928 |
| Yes | 206788389 | CARRIER | 25VNA424A*031* | CNPV*4221AL*+UI | 59MN7B060C21**20 | 24,400 | $2,928 |
| Yes | 206788394 | CARRIER | 25VNA424A*031* | CNPV*4821AL*+UI | 59MN7B060C17**14 | 24,400 | $2,928 |
| Yes | 206788413 | CARRIER | 25VNA424A*031* | CSPH*3612AL*+UI | 59MN7B060C21**20 | 24,400 | $2,928 |
| Yes | 206788412 | CARRIER | 25VNA424A*031* | CSPH*3612AL*+UI | 59MN7B080C17**14 | 24,400 | $2,928 |
| Yes | 206788420 | CARRIER | 25VNA424A*031* | CSPH*4212AL*+UI | 59MN7B060C17**14 | 24,400 | $2,928 |
| Yes | 206788414 | CARRIER | 25VNA424A*031* | CSPH*3612AL*+UI | 59MN7B080C21**20 | 24,200 | $2,904 |
| Yes | 206788429 | CARRIER | 25VNA424A*031* | CSPH*4812AL*+UI | 59MN7B060C17**14 | 24,400 | $2,928 |
| Yes | 206788430 | CARRIER | 25VNA424A*031* | CSPH*4812AL*+UI | 59MN7B080C17**14 | 24,200 | $2,904 |
| Yes | 206788438 | CARRIER | 25VNA424A*031* | CSPH*6012AL*+UI | 59MN7B060C17**14 | 24,000 | $2,880 |
| Yes | 206788431 | CARRIER | 25VNA424A*031* | CSPH*4812AL*+UI | 59MN7B060C21**20 | 24,200 | $2,904 |
| Yes | 206788334 | CARRIER | 25VNA424A*031* | CAP**3617AL*+UI | 58TN*A070C14**12 | 24,400 | $2,928 |
| Yes | 206788329 | CARRIER | 25VNA424A*031* | FE4ANF002L+UI | | 24,400 | $2,928 |
| Yes | 206788340 | CARRIER | 25VNA424A*031* | CAP**3621AL*+UI | 59MN7B100C21**22 | 24,200 | $2,904 |
| Yes | 206788341 | CARRIER | 25VNA424A*031* | CAP**3621AL*+UI | 58TN*A090C17**16 | 24,200 | $2,904 |
| Yes | 206788346 | CARRIER | 25VNA424A*031* | CAP**4221AL*+UI | 59MN7B080C21**20 | 24,200 | $2,904 |
| Yes | 206788335 | CARRIER | 25VNA424A*031* | CAP**3617AL*+UI | 58TN*A090C17**16 | 24,200 | $2,904 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 206788342 | CARRIER | 25VNA424A*031* | CAP**3621AL*+UI | 58TN*A110C21**20 | 24,200 | $2,904 |
| Yes | 206788347 | CARRIER | 25VNA424A*031* | CAP**4221AL*+UI | 59MN7B100C21**22 | 24,200 | $2,904 |
| Yes | 206788348 | CARRIER | 25VNA424A*031* | CAP**4221AL*+UI | 58TN*A090C17**16 | 24,200 | $2,904 |
| Yes | 206788349 | CARRIER | 25VNA424A*031* | CAP**4221AL*+UI | 58TN*A110C21**20 | 24,200 | $2,904 |
| Yes | 206788352 | CARRIER | 25VNA424A*031* | CAP**4224AL*+UI | 59MN7B100C21**22 | 24,200 | $2,904 |
| Yes | 206788365 | CARRIER | 25VNA424A*031* | CAP**4824AL*+UI | 59MN7B120C24**22 | 24,000 | $2,880 |
| Yes | 206788351 | CARRIER | 25VNA424A*031* | CAP**4224AL*+UI | 59MN7B080C21**20 | 24,200 | $2,904 |
| Yes | 206788353 | CARRIER | 25VNA424A*031* | CAP**4224AL*+UI | 59MN7B120C24**22 | 24,200 | $2,904 |
| Yes | 206788354 | CARRIER | 25VNA424A*031* | CAP**4224AL*+UI | 58TN*A110C21**20 | 24,200 | $2,904 |
| Yes | 206788358 | CARRIER | 25VNA424A*031* | CAP**4821AL*+UI | 59MN7B080C21**20 | 24,000 | $2,880 |
| Yes | 206788363 | CARRIER | 25VNA424A*031* | CAP**4824AL*+UI | 59MN7B080C21**20 | 24,000 | $2,880 |
| Yes | 206788359 | CARRIER | 25VNA424A*031* | CAP**4821AL*+UI | 59MN7B100C21**22 | 24,000 | $2,880 |
| Yes | 206788379 | CARRIER | 25VNA424A*031* | CNPV*3621AL*+UI | 59MN7B080C21**20 | 24,400 | $2,928 |
| Yes | 206788367 | CARRIER | 25VNA424A*031* | CAP**6024AL*+UI | 59MN7B060C21**20 | 23,800 | $2,856 |
| Yes | 206788368 | CARRIER | 25VNA424A*031* | CAP**6024AL*+UI | 59MN7B080C21**20 | 23,600 | $2,832 |
| Yes | 206788369 | CARRIER | 25VNA424A*031* | CAP**6024AL*+UI | 59MN7B100C21**22 | 23,600 | $2,832 |
| Yes | 206788370 | CARRIER | 25VNA424A*031* | CAP**6024AL*+UI | 59MN7B120C24**22 | 23,600 | $2,832 |
| Yes | 206788374 | CARRIER | 25VNA424A*031* | CNPV*3617AL*+UI | 58TN*A070C14**12 | 24,400 | $2,928 |
| Yes | 206788371 | CARRIER | 25VNA424A*031* | CAP**6024AL*+UI | 58TN*A110C21**20 | 23,600 | $2,832 |
| Yes | 206788380 | CARRIER | 25VNA424A*031* | CNPV*3621AL*+UI | 59MN7B100C21**22 | 24,400 | $2,928 |
| Yes | 206788392 | CARRIER | 25VNA424A*031* | CNPV*4221AL*+UI | 58TN*A090C17**16 | 24,200 | $2,904 |
| Yes | 206788386 | CARRIER | 25VNA424A*031* | CNPV*4217AL*+UI | 58TN*A090C17**16 | 24,200 | $2,904 |
| Yes | 206788396 | CARRIER | 25VNA424A*031* | CNPV*4821AL*+UI | 59MN7B060C21**20 | 24,200 | $2,904 |
| Yes | 206788393 | CARRIER | 25VNA424A*031* | CNPV*4221AL*+UI | 58TN*A110C21**20 | 24,200 | $2,904 |
| Yes | 206788395 | CARRIER | 25VNA424A*031* | CNPV*4821AL*+UI | 59MN7B080C17**14 | 24,200 | $2,904 |
| Yes | 206788400 | CARRIER | 25VNA424A*031* | CNPV*4821AL*+UI | 58TN*A110C21**20 | 24,000 | $2,880 |
| Yes | 206788401 | CARRIER | 25VNA424A*031* | CNPV*4824AL*+UI | 59MN7B060C21**20 | 24,200 | $2,904 |
| Yes | 206788405 | CARRIER | 25VNA424A*031* | CNPV*4824AL*+UI | 58TN*A110C21**20 | 24,000 | $2,880 |
| Yes | 206788406 | CARRIER | 25VNA424A*031* | CNPV*6024AL*+UI | 59MN7B060C21**20 | 24,000 | $2,880 |
| Yes | 206788410 | CARRIER | 25VNA424A*031* | CNPV*6024AL*+UI | 58TN*A110C21**20 | 23,800 | $2,856 |
| Yes | 206788425 | CARRIER | 25VNA424A*031* | CSPH*4212AL*+UI | 59MN7B120C24**22 | 24,200 | $2,904 |
| Yes | 206788408 | CARRIER | 25VNA424A*031* | CNPV*6024AL*+UI | 59MN7B100C21**22 | 23,800 | $2,856 |
| Yes | 206788415 | CARRIER | 25VNA424A*031* | CSPH*3612AL*+UI | 59MN7B100C21**22 | 24,200 | $2,904 |
| Yes | 206788416 | CARRIER | 25VNA424A*031* | CSPH*3612AL*+UI | 59MN7B120C24**22 | 24,200 | $2,904 |
| Yes | 206788418 | CARRIER | 25VNA424A*031* | CSPH*3612AL*+UI | 58TN*A090C17**16 | 24,200 | $2,904 |
| Yes | 206788423 | CARRIER | 25VNA424A*031* | CSPH*4212AL*+UI | 59MN7B080C21**20 | 24,200 | $2,904 |
| Yes | 206788419 | CARRIER | 25VNA424A*031* | CSPH*3612AL*+UI | 58TN*A110C21**20 | 24,200 | $2,904 |
| Yes | 206788426 | CARRIER | 25VNA424A*031* | CSPH*4212AL*+UI | 58TN*A070C14**12 | 24,200 | $2,904 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 206788439 | CARRIER | 25VNA424A*031* | CSPH*6012AL*+UI | 59MN7B080C17**14 | 24,000 | $2,880 |
| Yes | 206788441 | CARRIER | 25VNA424A*031* | CSPH*6012AL*+UI | 59MN7B080C21**20 | 23,800 | $2,856 |
| Yes | 206788435 | CARRIER | 25VNA424A*031* | CSPH*4812AL*+UI | 58TN*A070C14**12 | 24,200 | $2,904 |
| Yes | 206788445 | CARRIER | 25VNA424A*031* | CSPH*6012AL*+UI | 58TN*A090C17**16 | 23,800 | $2,856 |
| Yes | 206788442 | CARRIER | 25VNA424A*031* | CSPH*6012AL*+UI | 59MN7B100C21**22 | 23,800 | $2,856 |
| Yes | 206788443 | CARRIER | 25VNA424A*031* | CSPH*6012AL*+UI | 59MN7B120C24**22 | 23,800 | $2,856 |
| Yes | 206788454 | CARRIER | 25VNA424A*031* | CAP**3621AL*+UI | 58TN*A090C21**20 | 24,200 | $2,904 |
| Yes | 206788446 | CARRIER | 25VNA424A*031* | CSPH*6012AL*+UI | 58TN*A110C21**20 | 23,800 | $2,856 |
| Yes | 206788448 | CARRIER | 25VNA424A*031* | CAP**3617AL*+UI | 58TN*A070C17**16 | 24,400 | $2,928 |
| Yes | 206788456 | CARRIER | 25VNA424A*031* | CAP**3621AL*+UI | 59TN6B080C17**14 | 24,400 | $2,928 |
| Yes | 206788450 | CARRIER | 25VNA424A*031* | CAP**3617AL*+UI | 59TN6B080C17**14 | 24,400 | $2,928 |
| Yes | 206788455 | CARRIER | 25VNA424A*031* | CAP**3621AL*+UI | 59TN6B060C17**14 | 24,400 | $2,928 |
| Yes | 206788457 | CARRIER | 25VNA424A*031* | CAP**4221AL*+UI | 58TN*A045C17**12 | 24,400 | $2,928 |
| Yes | 206788459 | CARRIER | 25VNA424A*031* | CAP**4221AL*+UI | 58TN*A070C21**20 | 24,200 | $2,904 |
| Yes | 206788460 | CARRIER | 25VNA424A*031* | CAP**4221AL*+UI | 58TN*A090C21**20 | 24,200 | $2,904 |
| Yes | 206788461 | CARRIER | 25VNA424A*031* | CAP**4221AL*+UI | 59TN6B060C17**14 | 24,400 | $2,928 |
| Yes | 206788463 | CARRIER | 25VNA424A*031* | CAP**4224AL*+UI | 58TN*A070C21**20 | 24,200 | $2,904 |
| Yes | 206788462 | CARRIER | 25VNA424A*031* | CAP**4221AL*+UI | 59TN6B080C17**14 | 24,400 | $2,928 |
| Yes | 206788464 | CARRIER | 25VNA424A*031* | CAP**4224AL*+UI | 58TN*A090C21**20 | 24,200 | $2,904 |
| Yes | 206788466 | CARRIER | 25VNA424A*031* | CAP**4224AL*+UI | 59TN6B120C24**22 | 24,200 | $2,904 |
| Yes | 206788478 | CARRIER | 25VNA424A*031* | CAP**6024AL*+UI | 58TN*A090C21**20 | 23,600 | $2,832 |
| Yes | 206788467 | CARRIER | 25VNA424A*031* | CAP**4821AL*+UI | 58TN*A045C17**12 | 24,200 | $2,904 |
| Yes | 206788468 | CARRIER | 25VNA424A*031* | CAP**4821AL*+UI | 58TN*A070C17**16 | 24,000 | $2,880 |
| Yes | 206788469 | CARRIER | 25VNA424A*031* | CAP**4821AL*+UI | 58TN*A070C21**20 | 24,000 | $2,880 |
| Yes | 206788471 | CARRIER | 25VNA424A*031* | CAP**4821AL*+UI | 59TN6B060C17**14 | 24,200 | $2,904 |
| Yes | 206788473 | CARRIER | 25VNA424A*031* | CAP**4824AL*+UI | 58TN*A070C21**20 | 24,000 | $2,880 |
| Yes | 206788476 | CARRIER | 25VNA424A*031* | CAP**4824AL*+UI | 59TN6B120C24**22 | 24,000 | $2,880 |
| Yes | 206788480 | CARRIER | 25VNA424A*031* | CAP**6024AL*+UI | 59TN6B120C24**22 | 23,600 | $2,832 |
| Yes | 206788479 | CARRIER | 25VNA424A*031* | CAP**6024AL*+UI | 58TN*A135C24**22 | 23,600 | $2,832 |
| Yes | 206788481 | CARRIER | 25VNA424A*031* | CNPV*3617AL*+UI | 58TN*A045C17**12 | 24,600 | $2,952 |
| Yes | 206788482 | CARRIER | 25VNA424A*031* | CNPV*3617AL*+UI | 58TN*A070C17**16 | 24,400 | $2,928 |
| Yes | 206788483 | CARRIER | 25VNA424A*031* | CNPV*3617AL*+UI | 59TN6B060C17**14 | 24,600 | $2,952 |
| Yes | 206788486 | CARRIER | 25VNA424A*031* | CNPV*3621AL*+UI | 58TN*A070C17**16 | 24,400 | $2,928 |
| Yes | 206788487 | CARRIER | 25VNA424A*031* | CNPV*3621AL*+UI | 58TN*A070C21**20 | 24,400 | $2,928 |
| Yes | 206788498 | CARRIER | 25VNA424A*031* | CNPV*4221AL*+UI | 58TN*A090C21**20 | 24,200 | $2,904 |
| Yes | 206788489 | CARRIER | 25VNA424A*031* | CNPV*3621AL*+UI | 59TN6B060C17**14 | 24,600 | $2,952 |
| Yes | 206788485 | CARRIER | 25VNA424A*031* | CNPV*3621AL*+UI | 58TN*A045C17**12 | 24,600 | $2,952 |
| Yes | 206788491 | CARRIER | 25VNA424A*031* | CNPV*4217AL*+UI | 58TN*A045C17**12 | 24,400 | $2,928 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 206788507 | CARRIER | 25VNA424A*031* | CNPV*4824AL*+UI | 58TN*A070C21**20 | 24,200 | $2,904 |
| Yes | 206788494 | CARRIER | 25VNA424A*031* | CNPV*4217AL*+UI | 59TN6B080C17**14 | 24,400 | $2,928 |
| Yes | 206788493 | CARRIER | 25VNA424A*031* | CNPV*4217AL*+UI | 59TN6B060C17**14 | 24,400 | $2,928 |
| Yes | 206788496 | CARRIER | 25VNA424A*031* | CNPV*4221AL*+UI | 58TN*A070C17**16 | 24,400 | $2,928 |
| Yes | 206788500 | CARRIER | 25VNA424A*031* | CNPV*4221AL*+UI | 59TN6B080C17**14 | 24,400 | $2,928 |
| Yes | 206788502 | CARRIER | 25VNA424A*031* | CNPV*4821AL*+UI | 58TN*A070C17**16 | 24,200 | $2,904 |
| Yes | 206788503 | CARRIER | 25VNA424A*031* | CNPV*4821AL*+UI | 58TN*A070C21**20 | 24,200 | $2,904 |
| Yes | 206788509 | CARRIER | 25VNA424A*031* | CNPV*4824AL*+UI | 58TN*A135C24**22 | 24,000 | $2,880 |
| Yes | 206788504 | CARRIER | 25VNA424A*031* | CNPV*4821AL*+UI | 58TN*A090C21**20 | 24,000 | $2,880 |
| Yes | 206788508 | CARRIER | 25VNA424A*031* | CNPV*4824AL*+UI | 58TN*A090C21**20 | 24,000 | $2,880 |
| Yes | 206788515 | CARRIER | 25VNA424A*031* | CSPH*3612AL*+UI | 58TN*A045C17**12 | 24,400 | $2,928 |
| Yes | 206788519 | CARRIER | 25VNA424A*031* | CSPH*3612AL*+UI | 58TN*A135C24**22 | 24,200 | $2,904 |
| Yes | 206788513 | CARRIER | 25VNA424A*031* | CNPV*6024AL*+UI | 58TN*A135C24**22 | 23,800 | $2,856 |
| Yes | 206788512 | CARRIER | 25VNA424A*031* | CNPV*6024AL*+UI | 58TN*A090C21**20 | 23,800 | $2,856 |
| Yes | 206788518 | CARRIER | 25VNA424A*031* | CSPH*3612AL*+UI | 58TN*A090C21**20 | 24,200 | $2,904 |
| Yes | 206788520 | CARRIER | 25VNA424A*031* | CSPH*3612AL*+UI | 59TN6B060C17**14 | 24,400 | $2,928 |
| Yes | 206788522 | CARRIER | 25VNA424A*031* | CSPH*3612AL*+UI | 59TN6B120C24**22 | 24,200 | $2,904 |
| Yes | 206788521 | CARRIER | 25VNA424A*031* | CSPH*3612AL*+UI | 59TN6B080C17**14 | 24,400 | $2,928 |
| Yes | 206788523 | CARRIER | 25VNA424A*031* | CSPH*4212AL*+UI | 58TN*A045C17**12 | 24,400 | $2,928 |
| Yes | 206788524 | CARRIER | 25VNA424A*031* | CSPH*4212AL*+UI | 58TN*A070C17**16 | 24,200 | $2,904 |
| Yes | 206788525 | CARRIER | 25VNA424A*031* | CSPH*4212AL*+UI | 58TN*A070C21**20 | 24,200 | $2,904 |
| Yes | 206788528 | CARRIER | 25VNA424A*031* | CSPH*4212AL*+UI | 59TN6B060C17**14 | 24,400 | $2,928 |
| Yes | 206788532 | CARRIER | 25VNA424A*031* | CSPH*4812AL*+UI | 58TN*A070C17**16 | 24,200 | $2,904 |
| Yes | 206788530 | CARRIER | 25VNA424A*031* | CSPH*4212AL*+UI | 59TN6B120C24**22 | 24,200 | $2,904 |
| Yes | 206788533 | CARRIER | 25VNA424A*031* | CSPH*4812AL*+UI | 58TN*A070C21**20 | 24,200 | $2,904 |
| Yes | 206788535 | CARRIER | 25VNA424A*031* | CSPH*4812AL*+UI | 58TN*A135C24**22 | 24,000 | $2,880 |
| Yes | 206788542 | CARRIER | 25VNA424A*031* | CSPH*6012AL*+UI | 58TN*A090C21**20 | 23,800 | $2,856 |
| Yes | 206788539 | CARRIER | 25VNA424A*031* | CSPH*6012AL*+UI | 58TN*A045C17**12 | 24,000 | $2,880 |
| Yes | 206788544 | CARRIER | 25VNA424A*031* | CSPH*6012AL*+UI | 59TN6B060C17**14 | 24,000 | $2,880 |
| Yes | 206788330 | CARRIER | 25VNA424A*031* | FE4AN(B,F)003L+UI | | 24,200 | $2,904 |
| Yes | 206788545 | CARRIER | 25VNA424A*031* | CSPH*6012AL*+UI | 59TN6B080C17**14 | 24,000 | $2,880 |
| Yes | 206788543 | CARRIER | 25VNA424A*031* | CSPH*6012AL*+UI | 58TN*A135C24**22 | 23,800 | $2,856 |
| Yes | 206788576 | CARRIER | 25VNA436A*031* | FE4ANB006L+UI | | 32,400 | $3,888 |
| Yes | 206788546 | CARRIER | 25VNA424A*031* | CSPH*6012AL*+UI | 59TN6B120C24**22 | 23,800 | $2,856 |
| Yes | 206788655 | CARRIER | 25VNA436A*031* | CAP**6024AL*+UI | 59TN6B120C24**22 | 32,800 | $3,936 |
| Yes | 206788653 | CARRIER | 25VNA436A*031* | CAP**6024AL*+UI | 58TN*A090C21**20 | 32,800 | $3,936 |
| Yes | 206788654 | CARRIER | 25VNA436A*031* | CAP**6024AL*+UI | 58TN*A135C24**22 | 32,600 | $3,912 |
| Yes | 206788647 | CARRIER | 25VNA436A*031* | CAP**4824AL*+UI | 59MN7B120C24**22 | 33,400 | $4,008 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 206788661 | CARRIER | 25VNA436A*031* | CAP**6024AL*+UI | 58TN*A110C21**20 | 32,800 | $3,936 |
| Yes | 206788575 | CARRIER | 25VNA436A*031* | FE4AN(B,F)003L+UI | | 33,000 | $3,960 |
| Yes | 206788656 | CARRIER | 25VNA436A*031* | CAP**6024AL*+UI | 59MN7B080C21**20 | 33,000 | $3,960 |
| Yes | 206788660 | CARRIER | 25VNA436A*031* | CAP**6024AL*+UI | 59TN6B100C21**22 | 32,800 | $3,936 |
| Yes | 206788657 | CARRIER | 25VNA436A*031* | CAP**6024AL*+UI | 59MN7B100C21**22 | 32,800 | $3,936 |
| Yes | 206788658 | CARRIER | 25VNA436A*031* | CAP**6024AL*+UI | 59MN7B120C24**22 | 33,000 | $3,960 |
| Yes | 206788659 | CARRIER | 25VNA436A*031* | CAP**6024AL*+UI | 59TN6B080C21**20 | 33,000 | $3,960 |
| Yes | 206788678 | CARRIER | 25VNA436A*031* | CAP**6124AL*+UI | 58TN*A135C24**22 | 32,800 | $3,936 |
| Yes | 206788790 | CARRIER | 25VNA436A*031* | CSPH*6012AL*+UI | 58TN*A090C21**20 | 32,800 | $3,936 |
| Yes | 206788652 | CARRIER | 25VNA436A*031* | CAP**6024AL*+UI | 58TN*A070C21**20 | 33,000 | $3,960 |
| Yes | 206788796 | CARRIER | 25VNA436A*031* | CSPH*6012AL*+UI | 59MN7B080C21**20 | 33,000 | $3,960 |
| Yes | 206788791 | CARRIER | 25VNA436A*031* | CSPH*6012AL*+UI | 58TN*A135C24**22 | 32,800 | $3,936 |
| Yes | 206788798 | CARRIER | 25VNA436A*031* | CSPH*6012AL*+UI | 59MN7B120C24**22 | 33,000 | $3,960 |
| Yes | 206788799 | CARRIER | 25VNA436A*031* | CSPH*6012AL*+UI | 59TN6B080C21**20 | 33,000 | $3,960 |
| Yes | 206788677 | CARRIER | 25VNA436A*031* | CAP**6124AL*+UI | 58TN*A090C21**20 | 33,000 | $3,960 |
| Yes | 206788665 | CARRIER | 25VNA436A*031* | CAP**6121AL*+UI | 58TN*A090C21**20 | 33,000 | $3,960 |
| Yes | 206788679 | CARRIER | 25VNA436A*031* | CAP**6124AL*+UI | 59TN6B120C24**22 | 33,000 | $3,960 |
| Yes | 206788681 | CARRIER | 25VNA436A*031* | CAP**6124AL*+UI | 59MN7B100C21**22 | 33,000 | $3,960 |
| Yes | 206788684 | CARRIER | 25VNA436A*031* | CAP**6124AL*+UI | 59TN6B100C21**22 | 33,000 | $3,960 |
| Yes | 206788801 | CARRIER | 25VNA436A*031* | CSPH*6012AL*+UI | 58TN*A090C17**16 | 33,000 | $3,960 |
| Yes | 206788685 | CARRIER | 25VNA436A*031* | CAP**6124AL*+UI | 58TN*A110C21**20 | 33,000 | $3,960 |
| Yes | 206788794 | CARRIER | 25VNA436A*031* | CSPH*6012AL*+UI | 59TN6B120C24**22 | 33,000 | $3,960 |
| Yes | 206788731 | CARRIER | 25VNA436A*031* | CNPV*6024AL*+UI | 58TN*A135C24**22 | 32,800 | $3,936 |
| Yes | 206788800 | CARRIER | 25VNA436A*031* | CSPH*6012AL*+UI | 59TN6B100C21**22 | 33,000 | $3,960 |
| Yes | 206788797 | CARRIER | 25VNA436A*031* | CSPH*6012AL*+UI | 59MN7B100C21**22 | 33,000 | $3,960 |
| Yes | 206788802 | CARRIER | 25VNA436A*031* | CSPH*6012AL*+UI | 58TN*A110C21**20 | 33,000 | $3,960 |
| Yes | 206788672 | CARRIER | 25VNA436A*031* | CAP**6121AL*+UI | 59TN6B100C21**22 | 33,000 | $3,960 |
| Yes | 206788789 | CARRIER | 25VNA436A*031* | CSPH*6012AL*+UI | 58TN*A070C21**20 | 33,200 | $3,984 |
| Yes | 206788662 | CARRIER | 25VNA436A*031* | CAP**6024AL*+UI | 59MN7B060C21**20 | 33,400 | $4,008 |
| Yes | 206788670 | CARRIER | 25VNA436A*031* | CAP**6121AL*+UI | 59MN7B100C21**22 | 33,000 | $3,960 |
| Yes | 206788669 | CARRIER | 25VNA436A*031* | CAP**6121AL*+UI | 59MN7B080C21**20 | 33,200 | $3,984 |
| Yes | 206788680 | CARRIER | 25VNA436A*031* | CAP**6124AL*+UI | 59MN7B080C21**20 | 33,200 | $3,984 |
| Yes | 206788671 | CARRIER | 25VNA436A*031* | CAP**6121AL*+UI | 59TN6B080C21**20 | 33,200 | $3,984 |
| Yes | 206788673 | CARRIER | 25VNA436A*031* | CAP**6121AL*+UI | 58TN*A090C17**16 | 33,200 | $3,984 |
| Yes | 206788674 | CARRIER | 25VNA436A*031* | CAP**6121AL*+UI | 58TN*A110C21**20 | 33,000 | $3,960 |
| Yes | 206788683 | CARRIER | 25VNA436A*031* | CAP**6124AL*+UI | 59TN6B080C21**20 | 33,200 | $3,984 |
| Yes | 206788676 | CARRIER | 25VNA436A*031* | CAP**6124AL*+UI | 58TN*A070C21**20 | 33,200 | $3,984 |
| Yes | 206788682 | CARRIER | 25VNA436A*031* | CAP**6124AL*+UI | 59MN7B120C24**22 | 33,000 | $3,960 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 206788730 | CARRIER | 25VNA436A*031* | CNPV*6024AL*+UI | 58TN*A090C21**20 | 33,000 | $3,960 |
| Yes | 206788732 | CARRIER | 25VNA436A*031* | CNPV*6024AL*+UI | 59TN6B120C24**22 | 33,000 | $3,960 |
| Yes | 206788735 | CARRIER | 25VNA436A*031* | CNPV*6024AL*+UI | 59MN7B120C24**22 | 33,200 | $3,984 |
| Yes | 206788734 | CARRIER | 25VNA436A*031* | CNPV*6024AL*+UI | 59MN7B100C21**22 | 33,000 | $3,960 |
| Yes | 206788733 | CARRIER | 25VNA436A*031* | CNPV*6024AL*+UI | 59MN7B080C21**20 | 33,200 | $3,984 |
| Yes | 206788736 | CARRIER | 25VNA436A*031* | CNPV*6024AL*+UI | 59TN6B080C21**20 | 33,200 | $3,984 |
| Yes | 206788630 | CARRIER | 25VNA436A*031* | CAP**4821AL*+UI | 58TN*A090C21**20 | 33,200 | $3,984 |
| Yes | 206788737 | CARRIER | 25VNA436A*031* | CNPV*6024AL*+UI | 59TN6B100C21**22 | 33,000 | $3,960 |
| Yes | 206788738 | CARRIER | 25VNA436A*031* | CNPV*6024AL*+UI | 58TN*A110C21**20 | 33,000 | $3,960 |
| Yes | 206788645 | CARRIER | 25VNA436A*031* | CAP**4824AL*+UI | 59MN7B080C21**20 | 33,400 | $4,008 |
| Yes | 206788574 | CARRIER | 25VNA436A*031* | FE4AN(B,F)005L+UI | | 32,800 | $3,936 |
| Yes | 206788648 | CARRIER | 25VNA436A*031* | CAP**4824AL*+UI | 59TN6B080C21**20 | 33,400 | $4,008 |
| Yes | 206788885 | CARRIER | 25VNA436A*031* | CAP**6121AL*+UI | 59MN7B060C17**14 | 33,600 | $4,032 |
| Yes | 206788639 | CARRIER | 25VNA436A*031* | CAP**4821AL*+UI | 58TN*A110C21**20 | 33,400 | $4,008 |
| Yes | 206788644 | CARRIER | 25VNA436A*031* | CAP**4824AL*+UI | 59TN6B120C24**22 | 33,200 | $3,984 |
| Yes | 206788635 | CARRIER | 25VNA436A*031* | CAP**4821AL*+UI | 59MN7B100C21**22 | 33,400 | $4,008 |
| Yes | 206788638 | CARRIER | 25VNA436A*031* | CAP**4821AL*+UI | 58TN*A090C17**16 | 33,400 | $4,008 |
| Yes | 206788637 | CARRIER | 25VNA436A*031* | CAP**4821AL*+UI | 59TN6B100C21**22 | 33,400 | $4,008 |
| Yes | 206788803 | CARRIER | 25VNA436A*031* | CSPH*6012AL*+UI | 59MN7B060C21**20 | 33,400 | $4,008 |
| Yes | 206788646 | CARRIER | 25VNA436A*031* | CAP**4824AL*+UI | 59MN7B100C21**22 | 33,200 | $3,984 |
| Yes | 206788649 | CARRIER | 25VNA436A*031* | CAP**4824AL*+UI | 59TN6B100C21**22 | 33,200 | $3,984 |
| Yes | 206788875 | CARRIER | 25VNA436A*031* | CAP**6121AL*+UI | 58TN*A045C17**12 | 33,800 | $4,056 |
| Yes | 206788675 | CARRIER | 25VNA436A*031* | CAP**6121AL*+UI | 59MN7B060C21**20 | 33,600 | $4,032 |
| Yes | 206788686 | CARRIER | 25VNA436A*031* | CAP**6124AL*+UI | 59MN7B060C21**20 | 33,600 | $4,032 |
| Yes | 206788759 | CARRIER | 25VNA436A*031* | CSPH*4212AL*+UI | 58TN*A135C24**22 | 33,400 | $4,008 |
| Yes | 206788774 | CARRIER | 25VNA436A*031* | CSPH*4812AL*+UI | 58TN*A090C21**20 | 33,400 | $4,008 |
| Yes | 206788775 | CARRIER | 25VNA436A*031* | CSPH*4812AL*+UI | 58TN*A135C24**22 | 33,200 | $3,984 |
| Yes | 206788778 | CARRIER | 25VNA436A*031* | CSPH*4812AL*+UI | 59TN6B120C24**22 | 33,400 | $4,008 |
| Yes | 206788788 | CARRIER | 25VNA436A*031* | CSPH*6012AL*+UI | 58TN*A070C17**16 | 33,400 | $4,008 |
| Yes | 206788793 | CARRIER | 25VNA436A*031* | CSPH*6012AL*+UI | 59TN6B080C17**14 | 33,600 | $4,032 |
| Yes | 206788795 | CARRIER | 25VNA436A*031* | CSPH*6012AL*+UI | 59MN7B080C17**14 | 33,600 | $4,032 |
| Yes | 206788898 | CARRIER | 25VNA436A*031* | CSPH*6012AL*+UI | 58TN*A070C14**12 | 33,600 | $4,032 |
| Yes | 206788617 | CARRIER | 25VNA436A*031* | CAP**4321AL*+UI | 58TN*A090C21**20 | 33,400 | $4,008 |
| Yes | 206788622 | CARRIER | 25VNA436A*031* | CAP**4321AL*+UI | 59MN7B100C21**22 | 33,400 | $4,008 |
| Yes | 206788624 | CARRIER | 25VNA436A*031* | CAP**4321AL*+UI | 59TN6B100C21**22 | 33,400 | $4,008 |
| Yes | 206788642 | CARRIER | 25VNA436A*031* | CAP**4824AL*+UI | 58TN*A090C21**20 | 33,200 | $3,984 |
| Yes | 206788626 | CARRIER | 25VNA436A*031* | CAP**4321AL*+UI | 58TN*A110C21**20 | 33,400 | $4,008 |
| Yes | 206788643 | CARRIER | 25VNA436A*031* | CAP**4824AL*+UI | 58TN*A135C24**22 | 33,000 | $3,960 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 206788650 | CARRIER | 25VNA436A*031* | CAP**4824AL*+UI | 58TN*A110C21**20 | 33,200 | $3,984 |
| Yes | 206788663 | CARRIER | 25VNA436A*031* | CAP**6121AL*+UI | 58TN*A070C17**16 | 33,400 | $4,008 |
| Yes | 206788664 | CARRIER | 25VNA436A*031* | CAP**6121AL*+UI | 58TN*A070C21**20 | 33,200 | $3,984 |
| Yes | 206788629 | CARRIER | 25VNA436A*031* | CAP**4821AL*+UI | 58TN*A070C21**20 | 33,600 | $4,032 |
| Yes | 206788720 | CARRIER | 25VNA436A*031* | CNPV*4824AL*+UI | 58TN*A135C24**22 | 33,200 | $3,984 |
| Yes | 206788729 | CARRIER | 25VNA436A*031* | CNPV*6024AL*+UI | 58TN*A070C21**20 | 33,200 | $3,984 |
| Yes | 206788634 | CARRIER | 25VNA436A*031* | CAP**4821AL*+UI | 59MN7B080C21**20 | 33,400 | $4,008 |
| Yes | 206788882 | CARRIER | 25VNA436A*031* | CSPH*6012AL*+UI | 58TN*A045C17**12 | 33,800 | $4,056 |
| Yes | 206788792 | CARRIER | 25VNA436A*031* | CSPH*6012AL*+UI | 59TN6B060C17**14 | 33,800 | $4,056 |
| Yes | 206788585 | CARRIER | 25VNA436A*031* | CAP**3721AL*+UI | 59MN7B080C21**20 | 33,600 | $4,032 |
| Yes | 206788581 | CARRIER | 25VNA436A*031* | CAP**3721AL*+UI | 58TN*A090C21**20 | 33,400 | $4,008 |
| Yes | 206788892 | CARRIER | 25VNA436A*031* | CSPH*6012AL*+UI | 59MN7B060C17**14 | 33,800 | $4,056 |
| Yes | 206788587 | CARRIER | 25VNA436A*031* | CAP**3721AL*+UI | 59TN6B080C21**20 | 33,600 | $4,032 |
| Yes | 206788616 | CARRIER | 25VNA436A*031* | CAP**4321AL*+UI | 58TN*A070C21**20 | 33,600 | $4,032 |
| Yes | 206788621 | CARRIER | 25VNA436A*031* | CAP**4321AL*+UI | 59MN7B080C21**20 | 33,600 | $4,032 |
| Yes | 206788623 | CARRIER | 25VNA436A*031* | CAP**4321AL*+UI | 59TN6B080C21**20 | 33,600 | $4,032 |
| Yes | 206788636 | CARRIER | 25VNA436A*031* | CAP**4821AL*+UI | 59TN6B080C21**20 | 33,400 | $4,008 |
| Yes | 206788641 | CARRIER | 25VNA436A*031* | CAP**4824AL*+UI | 58TN*A070C21**20 | 33,400 | $4,008 |
| Yes | 206788667 | CARRIER | 25VNA436A*031* | CAP**6121AL*+UI | 59TN6B080C17**14 | 33,800 | $4,056 |
| Yes | 206788668 | CARRIER | 25VNA436A*031* | CAP**6121AL*+UI | 59MN7B080C17**14 | 33,800 | $4,056 |
| Yes | 206788743 | CARRIER | 25VNA436A*031* | CSPH*3612AL*+UI | 58TN*A135C24**22 | 33,400 | $4,008 |
| Yes | 206788758 | CARRIER | 25VNA436A*031* | CSPH*4212AL*+UI | 58TN*A090C21**20 | 33,400 | $4,008 |
| Yes | 206788762 | CARRIER | 25VNA436A*031* | CSPH*4212AL*+UI | 59TN6B120C24**22 | 33,400 | $4,008 |
| Yes | 206788765 | CARRIER | 25VNA436A*031* | CSPH*4212AL*+UI | 59MN7B100C21**22 | 33,400 | $4,008 |
| Yes | 206788768 | CARRIER | 25VNA436A*031* | CSPH*4212AL*+UI | 59TN6B100C21**22 | 33,400 | $4,008 |
| Yes | 206788770 | CARRIER | 25VNA436A*031* | CSPH*4212AL*+UI | 58TN*A110C21**20 | 33,400 | $4,008 |
| Yes | 206788780 | CARRIER | 25VNA436A*031* | CSPH*4812AL*+UI | 59MN7B080C21**20 | 33,600 | $4,032 |
| Yes | 206788781 | CARRIER | 25VNA436A*031* | CSPH*4812AL*+UI | 59MN7B100C21**22 | 33,400 | $4,008 |
| Yes | 206788782 | CARRIER | 25VNA436A*031* | CSPH*4812AL*+UI | 59MN7B120C24**22 | 33,600 | $4,032 |
| Yes | 206788783 | CARRIER | 25VNA436A*031* | CSPH*4812AL*+UI | 59TN6B080C21**20 | 33,600 | $4,032 |
| Yes | 206788784 | CARRIER | 25VNA436A*031* | CSPH*4812AL*+UI | 59TN6B100C21**22 | 33,400 | $4,008 |
| Yes | 206788786 | CARRIER | 25VNA436A*031* | CSPH*4812AL*+UI | 58TN*A110C21**20 | 33,400 | $4,008 |
| Yes | 206788785 | CARRIER | 25VNA436A*031* | CSPH*4812AL*+UI | 58TN*A090C17**16 | 33,400 | $4,008 |
| Yes | 206788586 | CARRIER | 25VNA436A*031* | CAP**3721AL*+UI | 59MN7B100C21**22 | 33,600 | $4,032 |
| Yes | 206788588 | CARRIER | 25VNA436A*031* | CAP**3721AL*+UI | 59TN6B100C21**22 | 33,600 | $4,032 |
| Yes | 206788707 | CARRIER | 25VNA436A*031* | CNPV*4821AL*+UI | 58TN*A090C21**20 | 33,400 | $4,008 |
| Yes | 206788625 | CARRIER | 25VNA436A*031* | CAP**4321AL*+UI | 58TN*A090C17**16 | 33,600 | $4,032 |
| Yes | 206788590 | CARRIER | 25VNA436A*031* | CAP**3721AL*+UI | 58TN*A110C21**20 | 33,600 | $4,032 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 206788589 | CARRIER | 25VNA436A*031* | CAP**3721AL*+UI | 58TN*A090C17**16 | 33,600 | $4,032 |
| Yes | 206788712 | CARRIER | 25VNA436A*031* | CNPV*4821AL*+UI | 59MN7B100C21**22 | 33,400 | $4,008 |
| Yes | 206788714 | CARRIER | 25VNA436A*031* | CNPV*4821AL*+UI | 59TN6B100C21**22 | 33,400 | $4,008 |
| Yes | 206788715 | CARRIER | 25VNA436A*031* | CNPV*4821AL*+UI | 58TN*A090C17**16 | 33,400 | $4,008 |
| Yes | 206788716 | CARRIER | 25VNA436A*031* | CNPV*4821AL*+UI | 58TN*A110C21**20 | 33,400 | $4,008 |
| Yes | 206788594 | CARRIER | 25VNA436A*031* | CAP**4221AL*+UI | 58TN*A090C21**20 | 33,600 | $4,032 |
| Yes | 206788719 | CARRIER | 25VNA436A*031* | CNPV*4824AL*+UI | 58TN*A090C21**20 | 33,400 | $4,008 |
| Yes | 206788721 | CARRIER | 25VNA436A*031* | CNPV*4824AL*+UI | 59TN6B120C24**22 | 33,400 | $4,008 |
| Yes | 206788724 | CARRIER | 25VNA436A*031* | CNPV*4824AL*+UI | 59MN7B120C24**22 | 33,400 | $4,008 |
| Yes | 206788726 | CARRIER | 25VNA436A*031* | CNPV*4824AL*+UI | 59TN6B100C21**22 | 33,400 | $4,008 |
| Yes | 206788723 | CARRIER | 25VNA436A*031* | CNPV*4824AL*+UI | 59MN7B100C21**22 | 33,400 | $4,008 |
| Yes | 206788727 | CARRIER | 25VNA436A*031* | CNPV*4824AL*+UI | 58TN*A110C21**20 | 33,400 | $4,008 |
| Yes | 206788632 | CARRIER | 25VNA436A*031* | CAP**4821AL*+UI | 59TN6B080C17**14 | 34,000 | $4,080 |
| Yes | 206788633 | CARRIER | 25VNA436A*031* | CAP**4821AL*+UI | 59MN7B080C17**14 | 33,800 | $4,056 |
| Yes | 206788739 | CARRIER | 25VNA436A*031* | CNPV*6024AL*+UI | 59MN7B060C21**20 | 33,600 | $4,032 |
| Yes | 206788666 | CARRIER | 25VNA436A*031* | CAP**6121AL*+UI | 59TN6B060C17**14 | 34,000 | $4,080 |
| Yes | 206788580 | CARRIER | 25VNA436A*031* | CAP**3721AL*+UI | 58TN*A070C21**20 | 33,800 | $4,056 |
| Yes | 206788620 | CARRIER | 25VNA436A*031* | CAP**4321AL*+UI | 59MN7B080C17**14 | 34,000 | $4,080 |
| Yes | 206788606 | CARRIER | 25VNA436A*031* | CAP**4224AL*+UI | 58TN*A135C24**22 | 33,600 | $4,032 |
| Yes | 206788628 | CARRIER | 25VNA436A*031* | CAP**4821AL*+UI | 58TN*A070C17**16 | 33,800 | $4,056 |
| Yes | 206788651 | CARRIER | 25VNA436A*031* | CAP**4824AL*+UI | 59MN7B060C21**20 | 33,800 | $4,056 |
| Yes | 206788746 | CARRIER | 25VNA436A*031* | CSPH*3612AL*+UI | 59TN6B120C24**22 | 33,600 | $4,032 |
| Yes | 206788742 | CARRIER | 25VNA436A*031* | CSPH*3612AL*+UI | 58TN*A090C21**20 | 33,600 | $4,032 |
| Yes | 206788766 | CARRIER | 25VNA436A*031* | CSPH*4212AL*+UI | 59MN7B120C24**22 | 33,600 | $4,032 |
| Yes | 206788757 | CARRIER | 25VNA436A*031* | CSPH*4212AL*+UI | 58TN*A070C21**20 | 33,600 | $4,032 |
| Yes | 206788754 | CARRIER | 25VNA436A*031* | CSPH*3612AL*+UI | 58TN*A110C21**20 | 33,600 | $4,032 |
| Yes | 206788764 | CARRIER | 25VNA436A*031* | CSPH*4212AL*+UI | 59MN7B080C21**20 | 33,600 | $4,032 |
| Yes | 206788767 | CARRIER | 25VNA436A*031* | CSPH*4212AL*+UI | 59TN6B080C21**20 | 33,600 | $4,032 |
| Yes | 206788706 | CARRIER | 25VNA436A*031* | CNPV*4821AL*+UI | 58TN*A070C21**20 | 33,600 | $4,032 |
| Yes | 206788769 | CARRIER | 25VNA436A*031* | CSPH*4212AL*+UI | 58TN*A090C17**16 | 33,600 | $4,032 |
| Yes | 206788773 | CARRIER | 25VNA436A*031* | CSPH*4812AL*+UI | 58TN*A070C21**20 | 33,600 | $4,032 |
| Yes | 206788711 | CARRIER | 25VNA436A*031* | CNPV*4821AL*+UI | 59MN7B080C21**20 | 33,600 | $4,032 |
| Yes | 206788713 | CARRIER | 25VNA436A*031* | CNPV*4821AL*+UI | 59TN6B080C21**20 | 33,600 | $4,032 |
| Yes | 206788718 | CARRIER | 25VNA436A*031* | CNPV*4824AL*+UI | 58TN*A070C21**20 | 33,600 | $4,032 |
| Yes | 206788600 | CARRIER | 25VNA436A*031* | CAP**4221AL*+UI | 59TN6B100C21**22 | 33,800 | $4,056 |
| Yes | 206788722 | CARRIER | 25VNA436A*031* | CNPV*4824AL*+UI | 59MN7B080C21**20 | 33,600 | $4,032 |
| Yes | 206788725 | CARRIER | 25VNA436A*031* | CNPV*4824AL*+UI | 59TN6B080C21**20 | 33,600 | $4,032 |
| Yes | 206788598 | CARRIER | 25VNA436A*031* | CAP**4221AL*+UI | 59MN7B100C21**22 | 33,800 | $4,056 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 206788609 | CARRIER | 25VNA436A*031* | CAP**4224AL*+UI | 59MN7B100C21**22 | 33,600 | $4,032 |
| Yes | 206788584 | CARRIER | 25VNA436A*031* | CAP**3721AL*+UI | 59MN7B080C17**14 | 34,000 | $4,080 |
| Yes | 206788607 | CARRIER | 25VNA436A*031* | CAP**4224AL*+UI | 59TN6B120C24**22 | 33,600 | $4,032 |
| Yes | 206788610 | CARRIER | 25VNA436A*031* | CAP**4224AL*+UI | 59MN7B120C24**22 | 33,800 | $4,056 |
| Yes | 206788612 | CARRIER | 25VNA436A*031* | CAP**4224AL*+UI | 59TN6B100C21**22 | 33,600 | $4,032 |
| Yes | 206788619 | CARRIER | 25VNA436A*031* | CAP**4321AL*+UI | 59TN6B080C17**14 | 34,200 | $4,104 |
| Yes | 206788884 | CARRIER | 25VNA436A*031* | CAP**4821AL*+UI | 59MN7B060C17**14 | 34,000 | $4,080 |
| Yes | 206788640 | CARRIER | 25VNA436A*031* | CAP**4821AL*+UI | 59MN7B060C21**20 | 33,800 | $4,056 |
| Yes | 206788741 | CARRIER | 25VNA436A*031* | CSPH*3612AL*+UI | 58TN*A070C21**20 | 33,800 | $4,056 |
| Yes | 206788756 | CARRIER | 25VNA436A*031* | CSPH*4212AL*+UI | 58TN*A070C17**16 | 34,000 | $4,080 |
| Yes | 206788897 | CARRIER | 25VNA436A*031* | CSPH*4812AL*+UI | 58TN*A070C14**12 | 34,000 | $4,080 |
| Yes | 206788787 | CARRIER | 25VNA436A*031* | CSPH*4812AL*+UI | 59MN7B060C21**20 | 34,000 | $4,080 |
| Yes | 206788578 | CARRIER | 25VNA436A*031* | CAP**3717AL*+UI | 58TN*A090C17**16 | 33,800 | $4,056 |
| Yes | 206788602 | CARRIER | 25VNA436A*031* | CAP**4221AL*+UI | 58TN*A110C21**20 | 33,800 | $4,056 |
| Yes | 206788605 | CARRIER | 25VNA436A*031* | CAP**4224AL*+UI | 58TN*A090C21**20 | 33,600 | $4,032 |
| Yes | 206788579 | CARRIER | 25VNA436A*031* | CAP**3721AL*+UI | 58TN*A070C17**16 | 34,000 | $4,080 |
| Yes | 206788613 | CARRIER | 25VNA436A*031* | CAP**4224AL*+UI | 58TN*A110C21**20 | 33,600 | $4,032 |
| Yes | 206788627 | CARRIER | 25VNA436A*031* | CAP**4321AL*+UI | 59MN7B060C21**20 | 34,000 | $4,080 |
| Yes | 206788615 | CARRIER | 25VNA436A*031* | CAP**4321AL*+UI | 58TN*A070C17**16 | 33,800 | $4,056 |
| Yes | 206788705 | CARRIER | 25VNA436A*031* | CNPV*4821AL*+UI | 58TN*A070C17**16 | 33,800 | $4,056 |
| Yes | 206788691 | CARRIER | 25VNA436A*031* | CNPV*4217AL*+UI | 58TN*A090C17**16 | 33,800 | $4,056 |
| Yes | 206788709 | CARRIER | 25VNA436A*031* | CNPV*4821AL*+UI | 59TN6B080C17**14 | 34,000 | $4,080 |
| Yes | 206788710 | CARRIER | 25VNA436A*031* | CNPV*4821AL*+UI | 59MN7B080C17**14 | 34,000 | $4,080 |
| Yes | 206788893 | CARRIER | 25VNA436A*031* | CAP**3717AL*+UI | 58TN*A070C14**12 | 34,000 | $4,080 |
| Yes | 206788604 | CARRIER | 25VNA436A*031* | CAP**4224AL*+UI | 58TN*A070C21**20 | 33,800 | $4,056 |
| Yes | 206788753 | CARRIER | 25VNA436A*031* | CSPH*3612AL*+UI | 58TN*A090C17**16 | 33,800 | $4,056 |
| Yes | 206788772 | CARRIER | 25VNA436A*031* | CSPH*4812AL*+UI | 58TN*A070C17**16 | 33,800 | $4,056 |
| Yes | 206788601 | CARRIER | 25VNA436A*031* | CAP**4221AL*+UI | 58TN*A090C17**16 | 33,800 | $4,056 |
| Yes | 206788582 | CARRIER | 25VNA436A*031* | CAP**3721AL*+UI | 59TN6B060C17**14 | 34,400 | $4,128 |
| Yes | 206788583 | CARRIER | 25VNA436A*031* | CAP**3721AL*+UI | 59TN6B080C17**14 | 34,200 | $4,104 |
| Yes | 206788611 | CARRIER | 25VNA436A*031* | CAP**4224AL*+UI | 59TN6B080C21**20 | 33,800 | $4,056 |
| Yes | 206788593 | CARRIER | 25VNA436A*031* | CAP**4221AL*+UI | 58TN*A070C21**20 | 34,000 | $4,080 |
| Yes | 206788597 | CARRIER | 25VNA436A*031* | CAP**4221AL*+UI | 59MN7B080C21**20 | 33,800 | $4,056 |
| Yes | 206788599 | CARRIER | 25VNA436A*031* | CAP**4221AL*+UI | 59TN6B080C21**20 | 33,800 | $4,056 |
| Yes | 206788608 | CARRIER | 25VNA436A*031* | CAP**4224AL*+UI | 59MN7B080C21**20 | 33,800 | $4,056 |
| Yes | 206788618 | CARRIER | 25VNA436A*031* | CAP**4321AL*+UI | 59TN6B060C17**14 | 34,400 | $4,128 |
| Yes | 206788690 | CARRIER | 25VNA436A*031* | CNPV*4217AL*+UI | 59MN7B080C17**14 | 34,200 | $4,104 |
| Yes | 206788740 | CARRIER | 25VNA436A*031* | CSPH*3612AL*+UI | 58TN*A070C17**16 | 34,000 | $4,080 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 206788896 | CARRIER | 25VNA436A*031* | CSPH*4212AL*+UI | 58TN*A070C14**12 | 34,000 | $4,080 |
| Yes | 206788771 | CARRIER | 25VNA436A*031* | CSPH*4212AL*+UI | 59MN7B060C21**20 | 34,000 | $4,080 |
| Yes | 206788891 | CARRIER | 25VNA436A*031* | CSPH*4812AL*+UI | 59MN7B060C17**14 | 34,200 | $4,104 |
| Yes | 206788777 | CARRIER | 25VNA436A*031* | CSPH*4812AL*+UI | 59TN6B080C17**14 | 34,200 | $4,104 |
| Yes | 206788779 | CARRIER | 25VNA436A*031* | CSPH*4812AL*+UI | 59MN7B080C17**14 | 34,000 | $4,080 |
| Yes | 206788694 | CARRIER | 25VNA436A*031* | CNPV*4221AL*+UI | 58TN*A090C21**20 | 33,800 | $4,056 |
| Yes | 206788591 | CARRIER | 25VNA436A*031* | CAP**3721AL*+UI | 59MN7B060C21**20 | 34,000 | $4,080 |
| Yes | 206788698 | CARRIER | 25VNA436A*031* | CNPV*4221AL*+UI | 59MN7B080C21**20 | 34,000 | $4,080 |
| Yes | 206788701 | CARRIER | 25VNA436A*031* | CNPV*4221AL*+UI | 59TN6B100C21**22 | 33,800 | $4,056 |
| Yes | 206788700 | CARRIER | 25VNA436A*031* | CNPV*4221AL*+UI | 59TN6B080C21**20 | 34,000 | $4,080 |
| Yes | 206788702 | CARRIER | 25VNA436A*031* | CNPV*4221AL*+UI | 58TN*A090C17**16 | 33,800 | $4,056 |
| Yes | 206788703 | CARRIER | 25VNA436A*031* | CNPV*4221AL*+UI | 58TN*A110C21**20 | 33,800 | $4,056 |
| Yes | 206788728 | CARRIER | 25VNA436A*031* | CNPV*4824AL*+UI | 59MN7B060C21**20 | 34,000 | $4,080 |
| Yes | 206788717 | CARRIER | 25VNA436A*031* | CNPV*4821AL*+UI | 59MN7B060C21**20 | 34,000 | $4,080 |
| Yes | 206788699 | CARRIER | 25VNA436A*031* | CNPV*4221AL*+UI | 59MN7B100C21**22 | 33,800 | $4,056 |
| Yes | 206788577 | CARRIER | 25VNA436A*031* | CAP**3717AL*+UI | 58TN*A070C17**16 | 34,200 | $4,104 |
| Yes | 206788592 | CARRIER | 25VNA436A*031* | CAP**4221AL*+UI | 58TN*A070C17**16 | 34,200 | $4,104 |
| Yes | 206788874 | CARRIER | 25VNA436A*031* | CAP**4821AL*+UI | 58TN*A045C17**12 | 34,200 | $4,104 |
| Yes | 206788689 | CARRIER | 25VNA436A*031* | CNPV*4217AL*+UI | 59TN6B080C17**14 | 34,400 | $4,128 |
| Yes | 206788894 | CARRIER | 25VNA436A*031* | CNPV*4217AL*+UI | 58TN*A070C14**12 | 34,200 | $4,104 |
| Yes | 206788693 | CARRIER | 25VNA436A*031* | CNPV*4221AL*+UI | 58TN*A070C21**20 | 34,000 | $4,080 |
| Yes | 206788878 | CARRIER | 25VNA436A*031* | CNPV*4821AL*+UI | 58TN*A045C17**12 | 34,200 | $4,104 |
| Yes | 206788895 | CARRIER | 25VNA436A*031* | CSPH*3612AL*+UI | 58TN*A070C14**12 | 34,200 | $4,104 |
| Yes | 206788755 | CARRIER | 25VNA436A*031* | CSPH*3612AL*+UI | 59MN7B060C21**20 | 34,200 | $4,104 |
| Yes | 206788761 | CARRIER | 25VNA436A*031* | CSPH*4212AL*+UI | 59TN6B080C17**14 | 34,200 | $4,104 |
| Yes | 206788890 | CARRIER | 25VNA436A*031* | CSPH*4212AL*+UI | 59MN7B060C17**14 | 34,200 | $4,104 |
| Yes | 206788881 | CARRIER | 25VNA436A*031* | CSPH*4812AL*+UI | 58TN*A045C17**12 | 34,400 | $4,128 |
| Yes | 206788763 | CARRIER | 25VNA436A*031* | CSPH*4212AL*+UI | 59MN7B080C17**14 | 34,200 | $4,104 |
| Yes | 206788776 | CARRIER | 25VNA436A*031* | CSPH*4812AL*+UI | 59TN6B060C17**14 | 34,200 | $4,104 |
| Yes | 206788889 | CARRIER | 25VNA436A*031* | CSPH*3612AL*+UI | 59MN7B060C17**14 | 34,400 | $4,128 |
| Yes | 206788687 | CARRIER | 25VNA436A*031* | CNPV*4217AL*+UI | 58TN*A070C17**16 | 34,200 | $4,104 |
| Yes | 206788603 | CARRIER | 25VNA436A*031* | CAP**4221AL*+UI | 59MN7B060C21**20 | 34,200 | $4,104 |
| Yes | 206788692 | CARRIER | 25VNA436A*031* | CNPV*4221AL*+UI | 58TN*A070C17**16 | 34,200 | $4,104 |
| Yes | 206788886 | CARRIER | 25VNA436A*031* | CNPV*4217AL*+UI | 59MN7B060C17**14 | 34,400 | $4,128 |
| Yes | 206788614 | CARRIER | 25VNA436A*031* | CAP**4224AL*+UI | 59MN7B060C21**20 | 34,200 | $4,104 |
| Yes | 206788745 | CARRIER | 25VNA436A*031* | CSPH*3612AL*+UI | 59TN6B080C17**14 | 34,400 | $4,128 |
| Yes | 206788760 | CARRIER | 25VNA436A*031* | CSPH*4212AL*+UI | 59TN6B060C17**14 | 34,400 | $4,128 |
| Yes | 206788747 | CARRIER | 25VNA436A*031* | CSPH*3612AL*+UI | 59MN7B080C17**14 | 34,200 | $4,104 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 206788880 | CARRIER | 25VNA436A*031* | CSPH*4212AL*+UI | 58TN*A045C17**12 | 34,400 | $4,128 |
| Yes | 206788873 | CARRIER | 25VNA436A*031* | CAP**4221AL*+UI | 58TN*A045C17**12 | 34,600 | $4,152 |
| Yes | 206788708 | CARRIER | 25VNA436A*031* | CNPV*4821AL*+UI | 59TN6B060C17**14 | 34,400 | $4,128 |
| Yes | 206788879 | CARRIER | 25VNA436A*031* | CSPH*3612AL*+UI | 58TN*A045C17**12 | 34,600 | $4,152 |
| Yes | 206788595 | CARRIER | 25VNA436A*031* | CAP**4221AL*+UI | 59TN6B060C17**14 | 34,600 | $4,152 |
| Yes | 206788596 | CARRIER | 25VNA436A*031* | CAP**4221AL*+UI | 59MN7B080C17**14 | 34,400 | $4,128 |
| Yes | 206788696 | CARRIER | 25VNA436A*031* | CNPV*4221AL*+UI | 59TN6B080C17**14 | 34,600 | $4,152 |
| Yes | 206788887 | CARRIER | 25VNA436A*031* | CNPV*4221AL*+UI | 59MN7B060C17**14 | 34,600 | $4,152 |
| Yes | 206788704 | CARRIER | 25VNA436A*031* | CNPV*4221AL*+UI | 59MN7B060C21**20 | 34,400 | $4,128 |
| Yes | 206788695 | CARRIER | 25VNA436A*031* | CNPV*4221AL*+UI | 59TN6B060C17**14 | 34,600 | $4,152 |
| Yes | 206788697 | CARRIER | 25VNA436A*031* | CNPV*4221AL*+UI | 59MN7B080C17**14 | 34,400 | $4,128 |
| Yes | 206788888 | CARRIER | 25VNA436A*031* | CNPV*4821AL*+UI | 59MN7B060C17**14 | 34,200 | $4,104 |
| Yes | 206788744 | CARRIER | 25VNA436A*031* | CSPH*3612AL*+UI | 59TN6B060C17**14 | 34,600 | $4,152 |
| Yes | 206788883 | CARRIER | 25VNA436A*031* | CAP**4221AL*+UI | 59MN7B060C17**14 | 34,600 | $4,152 |
| Yes | 206788688 | CARRIER | 25VNA436A*031* | CNPV*4217AL*+UI | 59TN6B060C17**14 | 34,600 | $4,152 |
| Yes | 206788876 | CARRIER | 25VNA436A*031* | CNPV*4217AL*+UI | 58TN*A045C17**12 | 34,600 | $4,152 |
| Yes | 206788877 | CARRIER | 25VNA436A*031* | CNPV*4221AL*+UI | 58TN*A045C17**12 | 32,400 | $3,888 |
| Yes | 206350333 | CARRIER | 38MARBQ18AA3 | 40MBDQ18--3 | | 12,700 | $1,524 |
| Yes | 206188253 | CARRIER | 38MARBQ24AA3 | 40MBAAQ24XA3 | | 16,500 | $1,980 |
| Yes | 206348138 | CARRIER | 38MARBQ24AA3 | 40MAHBQ24XA3 | | 19,800 | $2,376 |
| Yes | 206350337 | CARRIER | 38MARBQ24AA3 | 40MBFQ24--3 | | 14,500 | $1,740 |
| Yes | 206350335 | CARRIER | 38MARBQ24AA3 | 40MBCQ24--3 | | 14,500 | $1,740 |
| Yes | 206350334 | CARRIER | 38MARBQ18AA3 | 40MBFQ18--3 | | 12,000 | $1,440 |
| Yes | 205921384 | CARRIER | 38MAQB24R--3 | 40MBAAQ24XA3 | | 17,500 | $2,100 |
| Yes | 206350336 | CARRIER | 38MARBQ24AA3 | 40MBDQ24--3 | | 14,500 | $1,740 |
| Yes | 205282597 | CARRIER | 38VMB036HDS3-1 | Combination heat pumps with or without ducts | | 25,000 | $3,000 |
| Yes | 205282600 | CARRIER | 38VMB048HDS3-1 | Combination heat pumps with or without ducts | | 34,000 | $4,080 |
| Yes | 202463635 | CARRIER | 38MPRAQ24AA3 | 40MPHAQ24XA3 | | 15,450 | $1,854 |
| Yes | 201847017 | CARRIER | 38MBRQ48A--3 | 40MBFQ48---3 | | 35,000 | $4,200 |
| Yes | 201847015 | CARRIER | 38MAQB24R--3 | 40MBFQ24---3 | | 17,200 | $2,064 |
| Yes | 200059145 | CARRIER | 38MAQB24R--3 | 40MBDQ24---3 | | 17,300 | $2,076 |
| Yes | 202345968 | CARRIER | 38MGRQ36D--3 | Heat pump with ducts | | 24,600 | $2,952 |
| Yes | 204711112 | CARRIER | 38MGRQ30D--3 | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 204722798 | CARRIER | 38MGRQ36D--3 | Combination heat pumps with or without ducts | | 23,800 | $2,856 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204722797 | CARRIER | 38MGRQ30D--3 | Combination heat pumps with or without ducts | | 20,200 | $2,424 |
| Yes | 205282599 | CARRIER | 38VMB048HDS3-1 | Heat pump with ducts | | 34,000 | $4,080 |
| Yes | 201863360 | CARRIER | 38VMA048HDS3-1 | Heat pump with ducts | | 34,000 | $4,080 |
| Yes | 205282596 | CARRIER | 38VMB036HDS3-1 | Heat pump with ducts | | 25,000 | $3,000 |
| Yes | 201863358 | CARRIER | 38VMA036HDS3-1 | Heat pump with ducts | | 25,000 | $3,000 |
| Yes | 200059036 | CENTURY | A-VMH24SU-1 | B-VMH24SU-1 | | 15,400 | $1,848 |
| Yes | 201862959 | CENTURY | A-VMH36QU-1 | Heat pump without ducts | | 23,200 | $2,784 |
| Yes | 211207001 | CHAMPION HEATING AND COOLING | HL20B4821 | XAMC48HE3N1+CC | TPLC100C16MP13 | 41,500 | $4,980 |
| Yes | 211206996 | CHAMPION HEATING AND COOLING | HL20B4821 | XAMC48HE3N1+CC | TPLC080C16MP13 | 41,500 | $4,980 |
| Yes | 211206991 | CHAMPION HEATING AND COOLING | HL20B4821 | XAMC48HE3N1+CC | TMLV100C16MP12 | 41,500 | $4,980 |
| Yes | 211206986 | CHAMPION HEATING AND COOLING | HL20B4821 | XAMC48HE3N1+CC | TM8V080C16MP12 | 41,500 | $4,980 |
| Yes | 211206981 | CHAMPION HEATING AND COOLING | HL20B4821 | XAMC48HE3N1+CC | TM8V100C16MP12 | 41,500 | $4,980 |
| Yes | 211206973 | CHAMPION HEATING AND COOLING | HL20B4821 | XAMC48HE3N1+CC | TPLC120C20MP13 | 41,500 | $4,980 |
| Yes | 211206968 | CHAMPION HEATING AND COOLING | HL20B4821 | XAMC48HE3N1+CC | TPLC100C20MP13 | 41,500 | $4,980 |
| Yes | 211206963 | CHAMPION HEATING AND COOLING | HL20B4821 | XAMC48HE3N1+CC | TMLV120C20MP12 | 41,500 | $4,980 |
| Yes | 211206958 | CHAMPION HEATING AND COOLING | HL20B4821 | XAMC48HE3N1+CC | TM8V100C20MP12 | 41,500 | $4,980 |
| Yes | 211206953 | CHAMPION HEATING AND COOLING | HL20B4821 | XAMC48HE3N1+CC | TM8V120C20MP12 | 41,500 | $4,980 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 211206946 | CHAMPION HEATING AND COOLING | HL20B4821 | XAMC48HE3N1+CC | TP9C080C16MP13 | 41,500 | $4,980 |
| Yes | 211206941 | CHAMPION HEATING AND COOLING | HL20B4821 | XAMC48HE3N1+CC | TM9V080C16MP12 | 41,500 | $4,980 |
| Yes | 211206934 | CHAMPION HEATING AND COOLING | HL20B4821 | XAMC48HE3N1+CC | TP9C100C16MP13 | 41,500 | $4,980 |
| Yes | 211206929 | CHAMPION HEATING AND COOLING | HL20B4821 | XAMC48HE3N1+CC | TM9V100C16MP12 | 41,500 | $4,980 |
| Yes | 211206922 | CHAMPION HEATING AND COOLING | HL20B4821 | XAMC48HE3N1+CC | TP9C100C20MP13 | 41,500 | $4,980 |
| Yes | 211206917 | CHAMPION HEATING AND COOLING | HL20B4821 | XAMC48HE3N1+CC | TM9V100C20MP12 | 41,500 | $4,980 |
| Yes | 211206910 | CHAMPION HEATING AND COOLING | HL20B6021 | XAMC60HE4N1+CC | TP9C100C20MP13 | 47,000 | $5,640 |
| Yes | 211206905 | CHAMPION HEATING AND COOLING | HL20B6021 | XAMC60HE4N1+CC | TM9V100C20MP12 | 47,000 | $5,640 |
| Yes | 211206852 | CHAMPION HEATING AND COOLING | HL20B2421 | XAMB24DE1N1+CC | TPLC080B12MP13 | 23,000 | $2,760 |
| Yes | 211206847 | CHAMPION HEATING AND COOLING | HL20B2421 | XAMB24DE1N1+CC | TM8V080B12MP12 | 23,000 | $2,760 |
| Yes | 211206840 | CHAMPION HEATING AND COOLING | HL20B2421 | XAMB24DE1N1+CC | TP9C060B12MP13 | 23,200 | $2,784 |
| Yes | 211206835 | CHAMPION HEATING AND COOLING | HL20B2421 | XAMB24DE1N1+CC | TM9V060B12MP12 | 23,200 | $2,784 |
| Yes | 211010184 | CHAMPION HEATING AND COOLING | HL20B6021 | JHVVD60HE4C2N1+CC | | 46,500 | $5,580 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 10309105 | CHAMPION HEATING AND COOLING | HL20B4821 | AVV50DE321 | | 44,000 | $5,280 |
| Yes | 10309097 | CHAMPION HEATING AND COOLING | HL20B3621 | CM38CE2A1+MVC16CN21 | | 33,400 | $4,008 |
| Yes | 10309113 | CHAMPION HEATING AND COOLING | HL20B4821 | CM50CE3A1+MVC16CN21 | | 43,500 | $5,220 |
| Yes | 10309109 | CHAMPION HEATING AND COOLING | HL20B4821 | CM50DE3A1+MVC20DN21 | | 42,500 | $5,100 |
| Yes | 10525525 | CHAMPION HEATING AND COOLING | HL20B3621 | CM38CE2A1 | TP9C100C16MP13 | 31,600 | $3,792 |
| Yes | 10525521 | CHAMPION HEATING AND COOLING | HL20B3621 | CM38CE2A1 | TM9V100C16MP12 | 31,600 | $3,792 |
| Yes | 10525527 | CHAMPION HEATING AND COOLING | HL20B3621 | CM38CE2A1 | TPLC100C16MP13 | 33,400 | $4,008 |
| Yes | 10525529 | CHAMPION HEATING AND COOLING | HL20B4821 | CM50CE3A1 | TM8V080C16MP12 | 44,000 | $5,280 |
| Yes | 10525530 | CHAMPION HEATING AND COOLING | HL20B4821S | CM50CE3A1 | TM8V100C16MP12 | 44,000 | $5,280 |
| Yes | 10525528 | CHAMPION HEATING AND COOLING | HL20B4821 | AVV50CE321 | | 43,500 | $5,220 |
| Yes | 10525526 | CHAMPION HEATING AND COOLING | HL20B3621 | CM38CE2A1 | TPLC080C16MP13 | 33,400 | $4,008 |
| Yes | 10525531 | CHAMPION HEATING AND COOLING | HL20B4821 | CM50CE3A1 | TM8V100C20MP12 | 44,000 | $5,280 |
| Yes | 10525532 | CHAMPION HEATING AND COOLING | HL20B4821 | CM50CE3A1 | TM8V120C20MP12 | 44,000 | $5,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 10525535 | CHAMPION HEATING AND COOLING | HL20B4821 | CM50CE3A1 | TM9V100C20MP12 | 44,000 | $5,280 |
| Yes | 10525536 | CHAMPION HEATING AND COOLING | HL20B4821 | CM50CE3A1 | TMLV080C16MP12 | 44,000 | $5,280 |
| Yes | 10525538 | CHAMPION HEATING AND COOLING | HL20B4821 | CM50CE3A1 | TMLV100C20MP12 | 44,000 | $5,280 |
| Yes | 10525537 | CHAMPION HEATING AND COOLING | HL20B4821 | CM50CE3A1 | TMLV100C16MP12 | 44,000 | $5,280 |
| Yes | 10525539 | CHAMPION HEATING AND COOLING | HL20B4821 | CM50CE3A1 | TMLV120C20MP12 | 44,000 | $5,280 |
| Yes | 10525542 | CHAMPION HEATING AND COOLING | HL20B4821 | CM50CE3A1 | TP9C100C20MP13 | 44,000 | $5,280 |
| Yes | 10525543 | CHAMPION HEATING AND COOLING | HL20B4821 | CM50CE3A1 | TPLC080C16MP13 | 44,000 | $5,280 |
| Yes | 10525546 | CHAMPION HEATING AND COOLING | HL20B4821 | CM50CE3A1 | TPLC120C20MP13 | 44,000 | $5,280 |
| Yes | 10525545 | CHAMPION HEATING AND COOLING | HL20B4821 | CM50CE3A1 | TPLC100C20MP13 | 44,000 | $5,280 |
| Yes | 10525547 | CHAMPION HEATING AND COOLING | HL20B4821 | CM50DE3A1 | TM9V120D20MP12 | 44,000 | $5,280 |
| Yes | 10525544 | CHAMPION HEATING AND COOLING | HL20B4821 | CM50CE3A1 | TPLC100C16MP13 | 44,000 | $5,280 |
| Yes | 10525548 | CHAMPION HEATING AND COOLING | HL20B4821 | CM50DE3A1 | TP9C120D20MP13 | 44,000 | $5,280 |
| Yes | 201982916 | CHAMPION HEATING AND COOLING | HL20B3621 | AVV38CE221 | | 33,400 | $4,008 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 10309049 | CHAMPION HEATING AND COOLING | HL20B2421 | CM25BE1A1+MVC12BN21 | | 22,400 | $2,688 |
| Yes | 10525519 | CHAMPION HEATING AND COOLING | HL20B3621 | CM38CE2A1 | TM8V100C16MP12 | 33,400 | $4,008 |
| Yes | 10525518 | CHAMPION HEATING AND COOLING | HL20B3621 | CM38CE2A1 | TM8V080C16MP12 | 33,400 | $4,008 |
| Yes | 10525520 | CHAMPION HEATING AND COOLING | HL20B3621 | CM38CE2A1 | TM9V080C16MP12 | 31,800 | $3,816 |
| Yes | 10525522 | CHAMPION HEATING AND COOLING | HL20B3621 | CM38CE2A1 | TMLV080C16MP12 | 33,400 | $4,008 |
| Yes | 10525523 | CHAMPION HEATING AND COOLING | HL20B3621 | CM38CE2A1 | TMLV100C16MP12 | 33,400 | $4,008 |
| Yes | 10525524 | CHAMPION HEATING AND COOLING | HL20B3621 | CM38CE2A1 | TP9C080C16MP13 | 31,800 | $3,816 |
| Yes | 210278958 | Clearity | MOD30-24HFN1-MU0W | MSEPD-24HRFN1-MU0W | | 21,200 | $2,544 |
| Yes | 208141286 | Clearity | MOX430-17HFN1-MT0W | MSEPC-18HRFN1-MU0W | | 15,000 | $1,800 |
| Yes | 211719745 | COLEMAN | HC20B4821 | XAMC48HE3N1+CC | CPLC100C20MP13 | 41,500 | $4,980 |
| Yes | 211719744 | COLEMAN | HC20B2421 | XAMB24DE1N1+CC | CPLC080B12MP13 | 23,000 | $2,760 |
| Yes | 211207005 | COLEMAN | HC20B4821 | XAMC48HE3N1+CC | CPLC100C16MP13 | 41,500 | $4,980 |
| Yes | 211207003 | COLEMAN | HC20B4821 | XAMC48HE3N1+CC | CPLC080C16MP13 | 41,500 | $4,980 |
| Yes | 211206998 | COLEMAN | HC20B4821 | XAMC48HE3N1+CC | TPLC100C16MP13 | 41,500 | $4,980 |
| Yes | 211206993 | COLEMAN | HC20B4821 | XAMC48HE3N1+CC | TPLC080C16MP13 | 41,500 | $4,980 |
| Yes | 211206988 | COLEMAN | HC20B4821 | XAMC48HE3N1+CC | TMLV100C16MP12 | 41,500 | $4,980 |
| Yes | 211206983 | COLEMAN | HC20B4821 | XAMC48HE3N1+CC | TM8V080C16MP12 | 41,500 | $4,980 |
| Yes | 211206978 | COLEMAN | HC20B4821 | XAMC48HE3N1+CC | TM8V100C16MP12 | 41,500 | $4,980 |
| Yes | 211206976 | COLEMAN | HC20B4821 | XAMC48HE3N1+CC | CPLC120C20MP13 | 41,500 | $4,980 |
| Yes | 211206970 | COLEMAN | HC20B4821 | XAMC48HE3N1+CC | TPLC120C20MP13 | 41,500 | $4,980 |
| Yes | 211206965 | COLEMAN | HC20B4821 | XAMC48HE3N1+CC | TPLC100C20MP13 | 41,500 | $4,980 |
| Yes | 211206960 | COLEMAN | HC20B4821 | XAMC48HE3N1+CC | TMLV120C20MP12 | 41,500 | $4,980 |
| Yes | 211206955 | COLEMAN | HC20B4821 | XAMC48HE3N1+CC | TM8V100C20MP12 | 41,500 | $4,980 |
| Yes | 211206950 | COLEMAN | HC20B4821 | XAMC48HE3N1+CC | TM8V120C20MP12 | 41,500 | $4,980 |
| Yes | 211206948 | COLEMAN | HC20B4821 | XAMC48HE3N1+CC | CP9C080C16MP13 | 41,500 | $4,980 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 211206943 | COLEMAN | HC20B4821 | XAMC48HE3N1+CC | TP9C080C16MP13 | 41,500 | $4,980 |
| Yes | 211206938 | COLEMAN | HC20B4821 | XAMC48HE3N1+CC | TM9V080C16MP12 | 41,500 | $4,980 |
| Yes | 211206936 | COLEMAN | HC20B4821 | XAMC48HE3N1+CC | CP9C100C16MP13 | 41,500 | $4,980 |
| Yes | 211206931 | COLEMAN | HC20B4821 | XAMC48HE3N1+CC | TP9C100C16MP13 | 41,500 | $4,980 |
| Yes | 211206926 | COLEMAN | HC20B4821 | XAMC48HE3N1+CC | TM9V100C16MP12 | 41,500 | $4,980 |
| Yes | 211206924 | COLEMAN | HC20B4821 | XAMC48HE3N1+CC | CP9C100C20MP13 | 41,500 | $4,980 |
| Yes | 211206919 | COLEMAN | HC20B4821 | XAMC48HE3N1+CC | TP9C100C20MP13 | 41,500 | $4,980 |
| Yes | 211206914 | COLEMAN | HC20B4821 | XAMC48HE3N1+CC | TM9V100C20MP12 | 41,500 | $4,980 |
| Yes | 211206912 | COLEMAN | HC20B6021 | XAMC60HE4N1+CC | CP9C100C20MP13 | 47,000 | $5,640 |
| Yes | 211206907 | COLEMAN | HC20B6021 | XAMC60HE4N1+CC | TP9C100C20MP13 | 47,000 | $5,640 |
| Yes | 211206902 | COLEMAN | HC20B6021 | XAMC60HE4N1+CC | TM9V100C20MP12 | 47,000 | $5,640 |
| Yes | 211206849 | COLEMAN | HC20B2421 | XAMB24DE1N1+CC | TPLC080B12MP13 | 23,000 | $2,760 |
| Yes | 211206844 | COLEMAN | HC20B2421 | XAMB24DE1N1+CC | TM8V080B12MP12 | 23,000 | $2,760 |
| Yes | 211206842 | COLEMAN | HC20B2421 | XAMB24DE1N1+CC | CP9C060B12MP13 | 23,200 | $2,784 |
| Yes | 211206837 | COLEMAN | HC20B2421 | XAMB24DE1N1+CC | TP9C060B12MP13 | 23,200 | $2,784 |
| Yes | 211206832 | COLEMAN | HC20B2421 | XAMB24DE1N1+CC | TM9V060B12MP12 | 23,200 | $2,784 |
| Yes | 211010194 | COLEMAN | HC20B6021 | JHVVD60HE4C2N1+CC | | 46,500 | $5,580 |
| Yes | 10309046 | COLEMAN | HC20B2421 | CM25BE1A1+MVC12BN21 | | 22,400 | $2,688 |
| Yes | 10309102 | COLEMAN | HC20B4821 | AVV50DE321 | | 44,000 | $5,280 |
| Yes | 10309110 | COLEMAN | HC20B4821 | CM50CE3A1+MVC16CN21 | | 43,500 | $5,220 |
| Yes | 10309094 | COLEMAN | HC20B3621 | CM38CE2A1+MVC16CN21 | | 33,400 | $4,008 |
| Yes | 10309106 | COLEMAN | HC20B4821 | CM50DE3A1+MVC20DN21 | | 42,500 | $5,100 |
| Yes | 10525570 | COLEMAN | HC20B3621 | CM38CE2A1 | CP9C100C16MP13 | 31,600 | $3,792 |
| Yes | 10525569 | COLEMAN | HC20B3621 | CM38CE2A1 | CP9C080C16MP13 | 31,800 | $3,816 |
| Yes | 10525573 | COLEMAN | HC20B3621 | CM38CE2A1 | CPLC100C16MP13 | 33,400 | $4,008 |
| Yes | 10525571 | COLEMAN | HC20B3621 | CM38CE2A1 | CPLC080C16MP13 | 33,400 | $4,008 |
| Yes | 10525575 | COLEMAN | HC20B3621 | CM38CE2A1 | TM8V100C16MP12 | 33,400 | $4,008 |
| Yes | 10525576 | COLEMAN | HC20B3621 | CM38CE2A1 | TM9V080C16MP12 | 31,800 | $3,816 |
| Yes | 10525574 | COLEMAN | HC20B3621 | CM38CE2A1 | TM8V080C16MP12 | 33,400 | $4,008 |
| Yes | 10525577 | COLEMAN | HC20B3621 | CM38CE2A1 | TM9V100C16MP12 | 31,600 | $3,792 |
| Yes | 10525578 | COLEMAN | HC20B3621 | CM38CE2A1 | TMLV080C16MP12 | 33,400 | $4,008 |
| Yes | 10525582 | COLEMAN | HC20B3621 | CM38CE2A1 | TPLC080C16MP13 | 33,400 | $4,008 |
| Yes | 10525584 | COLEMAN | HC20B4821 | AVV50CE321 | | 43,500 | $5,220 |
| Yes | 10525587 | COLEMAN | HC20B4821 | CM50CE3A1 | CP9C100C20MP13 | 44,000 | $5,280 |
| Yes | 10525589 | COLEMAN | HC20B4821 | CM50CE3A1 | CPLC100C16MP13 | 44,000 | $5,280 |
| Yes | 10525590 | COLEMAN | HC20B4821 | CM50CE3A1 | CPLC100C20MP13 | 44,000 | $5,280 |
| Yes | 10525588 | COLEMAN | HC20B4821S | CM50CE3A1+CC&CPLC080C16MP13 | CPLC080C16MP13 | 44,000 | $5,280 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 10525592 | COLEMAN | HC20B4821 | CM50CE3A1 | TM8V080C16MP12 | 44,000 | $5,280 |
| Yes | 10525593 | COLEMAN | HC20B4821 | CM50CE3A1 | TM8V100C16MP12 | 44,000 | $5,280 |
| Yes | 10525594 | COLEMAN | HC20B4821 | CM50CE3A1 | TM8V100C20MP12 | 44,000 | $5,280 |
| Yes | 10525598 | COLEMAN | HC20B4821 | CM50CE3A1 | TM9V100C20MP12 | 44,000 | $5,280 |
| Yes | 10525595 | COLEMAN | HC20B4821 | CM50CE3A1 | TM8V120C20MP12 | 44,000 | $5,280 |
| Yes | 10525599 | COLEMAN | HC20B4821 | CM50CE3A1 | TMLV080C16MP12 | 44,000 | $5,280 |
| Yes | 10525601 | COLEMAN | HC20B4821 | CM50CE3A1 | TMLV100C20MP12 | 44,000 | $5,280 |
| Yes | 10525600 | COLEMAN | HC20B4821 | CM50CE3A1 | TMLV100C16MP12 | 44,000 | $5,280 |
| Yes | 10525605 | COLEMAN | HC20B4821 | CM50CE3A1 | TP9C100C20MP13 | 44,000 | $5,280 |
| Yes | 10525602 | COLEMAN | HC20B4821 | CM50CE3A1 | TMLV120C20MP12 | 44,000 | $5,280 |
| Yes | 10525606 | COLEMAN | HC20B4821 | CM50CE3A1 | TPLC080C16MP13 | 44,000 | $5,280 |
| Yes | 10525607 | COLEMAN | HC20B4821 | CM50CE3A1 | TPLC100C16MP13 | 44,000 | $5,280 |
| Yes | 10525608 | COLEMAN | HC20B4821 | CM50CE3A1 | TPLC100C20MP13 | 44,000 | $5,280 |
| Yes | 10525609 | COLEMAN | HC20B4821 | CM50CE3A1 | TPLC120C20MP13 | 44,000 | $5,280 |
| Yes | 10525612 | COLEMAN | HC20B4821 | CM50DE3A1 | TP9C120D20MP13 | 44,000 | $5,280 |
| Yes | 10525611 | COLEMAN | HC20B4821 | CM50DE3A1 | TM9V120D20MP12 | 44,000 | $5,280 |
| Yes | 201982919 | COLEMAN | HC20B3621 | AVV38CE221 | | 33,400 | $4,008 |
| Yes | 10525610 | COLEMAN | HC20B4821 | CM50DE3A1 | CP9C120D20MP13 | 44,000 | $5,280 |
| Yes | 10525579 | COLEMAN | HC20B3621 | CM38CE2A1 | TMLV100C16MP12 | 33,400 | $4,008 |
| Yes | 10525580 | COLEMAN | HC20B3621 | CM38CE2A1 | TP9C080C16MP13 | 31,800 | $3,816 |
| Yes | 10525583 | COLEMAN | HC20B3621 | CM38CE2A1 | TPLC100C16MP13 | 33,400 | $4,008 |
| Yes | 10525581 | COLEMAN | HC20B3621 | CM38CE2A1 | TP9C100C16MP13 | 31,600 | $3,792 |
| Yes | 10525591 | COLEMAN | HC20B4821 | CM50CE3A1 | CPLC120C20MP13 | 44,000 | $5,280 |
| Yes | 210568228 | COMFORT-AIRE | A-VCD60SA-1 | B-VCD60SA-1 | | 42,000 | $5,040 |
| Yes | 210568234 | COMFORT-AIRE | A-VCD30SA-1 | MCD30/36C1A | | 22,600 | $2,712 |
| Yes | 208136322 | COMFORT-AIRE | A-VMH18SV-1 | B-VMH18AV-1 | | 15,400 | $1,848 |
| Yes | 208136323 | COMFORT-AIRE | A-VMH24SV-1 | B-VMH24AV-1 | | 16,900 | $2,028 |
| Yes | 210568232 | COMFORT-AIRE | A-VCD48SA-1 | B-VCD48SA-1 | | 36,000 | $4,320 |
| Yes | 210568233 | COMFORT-AIRE | A-VCD24SA-1 | B-VCD24SA-1 | | 19,200 | $2,304 |
| Yes | 210568231 | COMFORT-AIRE | A-VCD18SA-1 | B-VCD18SA-1 | | 13,500 | $1,620 |
| Yes | 207657615 | COMFORT-AIRE | A-VMH36QV-1 | Heat pump without ducts | | 33,000 | $3,960 |
| Yes | 207657610 | COMFORT-AIRE | A-VMH18DV-1 | Heat pump without ducts | | 15,000 | $1,800 |
| Yes | 207657618 | COMFORT-AIRE | A-VMH48PV-1 | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 207657617 | COMFORT-AIRE | A-VMH48PV-1 | Heat pump without ducts | | 36,000 | $4,320 |
| Yes | 207657613 | COMFORT-AIRE | A-VMH28TV-1 | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 207657612 | COMFORT-AIRE | A-VMH28TV-1 | Heat pump without ducts | | 26,600 | $3,192 |
| Yes | 207657609 | COMFORT-AIRE | A-VMH18DV-1 | Heat pump with ducts | | 16,000 | $1,920 |
| Yes | 207657392 | COMFORT-AIRE | A-VMH24SV-1 | B-VMH24CV-1 | | 21,000 | $2,520 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 210568243 | COMFORT-AIRE | A-VMH24SV-1 | B-VMH24DU-1 | | 21,000 | $2,520 |
| Yes | 210568244 | COMFORT-AIRE | A-VMH24SV-1 | B-VMH24UU-1 | | 19,000 | $2,280 |
| Yes | 210568239 | COMFORT-AIRE | A-VMH18SV-1 | B-VMH18DU-1 | | 15,000 | $1,800 |
| Yes | 208141178 | COMFORT-AIRE | A-VMH24SU-1 | B-VMH24SV-1 | | 21,200 | $2,544 |
| Yes | 207657389 | COMFORT-AIRE | A-VMH24SV-1 | B-VMH24SV-1 | | 21,200 | $2,544 |
| Yes | 208141189 | COMFORT-AIRE | A-KMH24SU-1 | B-KMH24SV-1 | | 21,200 | $2,544 |
| Yes | 208141188 | COMFORT-AIRE | A-KMH18SU-1 | B-KMH18SV-1 | | 15,000 | $1,800 |
| Yes | 207657388 | COMFORT-AIRE | A-VMH18SV-1 | B-VMH18SV-1 | | 15,000 | $1,800 |
| Yes | 208141177 | COMFORT-AIRE | A-VMH18SU-1A | B-VMH18SV-1 | | 15,000 | $1,800 |
| Yes | 200059035 | COMFORT-AIRE | A-VMH24SU-1 | B-VMH24SU-1 | | 15,400 | $1,848 |
| Yes | 201810036 | COMFORT-AIRE | A-VMH36QU-1 | Heat pump without ducts | | 23,200 | $2,784 |
| Yes | 206221394 | COMFORT-AIRE | A-VMH24SU-1A | B-VMH24SU-1A | | 19,400 | $2,328 |
| Yes | 207657616 | COMFORT-AIRE | A-VMH36QV-1 | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 208141184 | COMFORT-AIRE | A-KMH24SV-1 | B-KMH24SU-1 | | 19,400 | $2,328 |
| Yes | 208141170 | COMFORT-AIRE | A-VMH24SV-1 | B-VMH24SU-1 | | 19,400 | $2,328 |
| Yes | 206913571 | COMFORT-AIRE | A-VMH24SU-1 | B-VMH24SU-1A | | 19,400 | $2,328 |
| Yes | 207657620 | COMFORT-AIRE | A-VMH36QV-1 | Combination heat pumps with or without ducts | | 23,000 | $2,760 |
| Yes | 207657619 | COMFORT-AIRE | A-VMH48PV-1 | Combination heat pumps with or without ducts | | 29,000 | $3,480 |
| Yes | 206913036 | COMFORT-AIRE | A-VMH24SU-1A | B-VMH24SU-1 | | 19,400 | $2,328 |
| Yes | 209852050 | COMFORTMAKER | DLCURAH48ABK | DLFUAAH48XAK | | 36,000 | $4,320 |
| Yes | 209852054 | COMFORTMAKER | DLCURAH36ABK | DLFUAAH36XAK | | 30,400 | $3,648 |
| Yes | 209852048 | COMFORTMAKER | DLCURAH24ABK | DLFUAAH24XAK | | 19,200 | $2,304 |
| Yes | 209852047 | COMFORTMAKER | DLCURAH18ABK | DLFUAAH18XAK | | 13,500 | $1,620 |
| Yes | 207643023 | COMFORTMAKER | DLCMHBH36DAK | Heat pump without ducts | | 22,000 | $2,640 |
| Yes | 207643020 | COMFORTMAKER | DLCMHBH48EAK | Heat pump without ducts | | 34,000 | $4,080 |
| Yes | 207643014 | COMFORTMAKER | DLCMHBH30DAK | Heat pump without ducts | | 18,500 | $2,220 |
| Yes | 207826597 | COMFORTMAKER | DLCSRBH18AAK | DLFSABH18XBK | | 12,000 | $1,440 |
| Yes | 207801569 | COMFORTMAKER | DLCSRBH18AAK | DLFSDAH24XAK | | 12,600 | $1,512 |
| Yes | 8177096 | COMFORTMAKER | DLCAHB12K1A | DLFAHH12K1A | | 13,000 | $1,560 |
| Yes | 207643015 | COMFORTMAKER | DLCMHBH30DAK | Heat pump with ducts | | 19,000 | $2,280 |
| Yes | 207643024 | COMFORTMAKER | DLCMHBH36DAK | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 207643021 | COMFORTMAKER | DLCMHBH48EAK | Heat pump with ducts | | 28,000 | $3,360 |
| Yes | 207643016 | COMFORTMAKER | DLCMHBH30DAK | Combination heat pumps with or without ducts | | 18,700 | $2,244 |
| Yes | 207643025 | COMFORTMAKER | DLCMHBH36DAK | Combination heat pumps with or without ducts | | 22,400 | $2,688 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 207643022 | COMFORTMAKER | DLCMHBH48EAK | Combination heat pumps with or without ducts | | 31,000 | $3,720 |
| Yes | 206350400 | COMFORTMAKER | DLCSRBH18AAK | DLFSFAH18XAK | | 12,000 | $1,440 |
| Yes | 206350403 | COMFORTMAKER | DLCSRBH24AAK | DLFSFAH24XAK | | 14,500 | $1,740 |
| Yes | 206350401 | COMFORTMAKER | DLCSRBH24AAK | DLFSCAH24XAK | | 14,500 | $1,740 |
| Yes | 206188295 | COMFORTMAKER | DLCSRBH24AAK | DLFSAAH24XAK | | 16,500 | $1,980 |
| Yes | 206350399 | COMFORTMAKER | DLCSRBH18AAK | DLFSDAH18XAK | | 12,700 | $1,524 |
| Yes | 206350402 | COMFORTMAKER | DLCSRBH24AAK | DLFSDAH24XAK | | 14,500 | $1,740 |
| Yes | 205921373 | COMFORTMAKER | DLCSRAH24AAK | DLFSAAH24XAK | | 17,500 | $2,100 |
| Yes | 201835589 | COMFORTMAKER | DLCSRAH24AAK | DLFSCAH24XAK | | 16,200 | $1,944 |
| Yes | 202463645 | COMFORTMAKER | DLCPRAH24AAK | DLFPHAH24XAK | | 15,450 | $1,854 |
| Yes | 201835587 | COMFORTMAKER | DLCSRAH24AAK | DLFSDAH24XAK | | 17,400 | $2,088 |
| Yes | 201835566 | COMFORTMAKER | DLCSRAH24AAK | DLFSHAH24XAK | | 15,000 | $1,800 |
| Yes | 201835593 | COMFORTMAKER | DLCLRAH48AAK | DLFLFAH48XAK | | 35,000 | $4,200 |
| Yes | 201835588 | COMFORTMAKER | DLCSRAH24AAK | DLFSFAH24XAK | | 17,200 | $2,064 |
| Yes | 201835586 | COMFORTMAKER | DLCSRAH18AAK | DLFSCAH18XAK | | 12,000 | $1,440 |
| Yes | 207658982 | COMFORTSTAR | CVH-36-4SH | Heat pump without ducts | | 33,000 | $3,960 |
| Yes | 207658976 | COMFORTSTAR | CVH-18-2SH | Heat pump without ducts | | 15,000 | $1,800 |
| Yes | 207658985 | COMFORTSTAR | CVH-48-5SH | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 207658984 | COMFORTSTAR | CVH-48-5SH | Heat pump without ducts | | 36,000 | $4,320 |
| Yes | 207658980 | COMFORTSTAR | CVH-27-3SH | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 207658979 | COMFORTSTAR | CVH-27-3SH | Heat pump without ducts | | 26,600 | $3,192 |
| Yes | 207658977 | COMFORTSTAR | CVH-18-2SH | Heat pump with ducts | | 16,000 | $1,920 |
| Yes | 207658952 | COMFORTSTAR | CHF24CD(O) | TIP-24 | | 21,000 | $2,520 |
| Yes | 207658942 | COMFORTSTAR | CHF48CD(O) | CPA-48C | | 39,500 | $4,740 |
| Yes | 207765966 | COMFORTSTAR | CHF48CD(O) | CPA-48DUB | | 39,500 | $4,740 |
| Yes | 207658954 | COMFORTSTAR | CHF48CD(O) | TIP-48 | | 35,000 | $4,200 |
| Yes | 207658963 | COMFORTSTAR | CHF48CD(O) | FPA-48DU | | 35,000 | $4,200 |
| Yes | 207658953 | COMFORTSTAR | CHF36CD(O) | TIP-36 | | 33,000 | $3,960 |
| Yes | 207658962 | COMFORTSTAR | CHF36CD(O) | FPA-36DU | | 32,000 | $3,840 |
| Yes | 207765972 | COMFORTSTAR | CHF24CD(O) | CPA-24B | | 21,000 | $2,520 |
| Yes | 207658940 | COMFORTSTAR | CHF24CD(O) | CPA-24C | | 21,000 | $2,520 |
| Yes | 207658961 | COMFORTSTAR | CHF24CD(O) | FPA-24 | | 19,000 | $2,280 |
| Yes | 207765971 | COMFORTSTAR | CHF18CD(O) | CPA-18B | | 15,000 | $1,800 |
| Yes | 207658939 | COMFORTSTAR | CHF18CD(O) | CPA-18C | | 15,000 | $1,800 |
| Yes | 207658929 | COMFORTSTAR | CHF24CD(O) | CHF24CD(I) | | 21,200 | $2,544 |
| Yes | 207658928 | COMFORTSTAR | CHF18CD(O) | CHF18CD(I) | | 15,000 | $1,800 |
| Yes | 202575869 | COMFORTSTAR | CXH024CD(O) | CPA-24B | | 17,200 | $2,064 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 202575872 | COMFORTSTAR | CM3-27-3ZX | Heat pump without ducts | | 18,000 | $2,160 |
| Yes | 207658986 | COMFORTSTAR | CVH-48-5SH | Combination heat pumps with or without ducts | | 29,000 | $3,480 |
| Yes | 207658987 | COMFORTSTAR | CVH-36-4SH | Combination heat pumps with or without ducts | | 23,000 | $2,760 |
| Yes | 207658983 | COMFORTSTAR | CVH-36-4SH | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 208106839 | CONCORD | 4DHP2S48M-1P | Heat pump without ducts | | 36,000 | $4,320 |
| Yes | 210605816 | CONFORTO | MHMZ436DA | Heat pump without ducts | | 33,000 | $3,960 |
| Yes | 210605810 | CONFORTO | MHMZ218DA | Heat pump without ducts | | 15,000 | $1,800 |
| Yes | 210605820 | CONFORTO | MHMZ548DA | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 210605819 | CONFORTO | MHMZ548DA | Heat pump without ducts | | 36,000 | $4,320 |
| Yes | 210605814 | CONFORTO | MHMZ327DA | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 210605813 | CONFORTO | MHMZ327DA | Heat pump without ducts | | 26,600 | $3,192 |
| Yes | 210605811 | CONFORTO | MHMZ218DA | Heat pump with ducts | | 16,000 | $1,920 |
| Yes | 210605809 | Conforto | MHSZ124DA | MHCAS24DA | | 21,000 | $2,520 |
| Yes | 210605805 | Conforto | MHSZ124DA | MHWAL24DA | | 21,200 | $2,544 |
| Yes | 210605804 | Conforto | MHSZ118DA | MHWAL18DA | | 15,000 | $1,800 |
| Yes | 212427856 | CONTINENTAL | WSEHV2436RA1-C | H,DE33(6,9)36 | WUV070T3AA | 15,000 | $1,800 |
| Yes | 212427855 | CONTINENTAL | WSEHV2436RA1-C | H,DE33(6,9)36 | WPV070T3AA | 15,000 | $1,800 |
| Yes | 211624979 | CONTINENTAL | WSEHV4860RA1-C | CPFX48A | | 31,400 | $3,768 |
| Yes | 211624978 | CONTINENTAL | WSEHV2436RA1-C | CPFX24A36A | | 24,000 | $2,880 |
| Yes | 211624977 | CONTINENTAL | WSEHV2436RA1-C | CPFX24A | | 16,000 | $1,920 |
| Yes | 212404700 | CONTINENTAL | WSEHV2436RA1-C | H,DE33(6,9)36 | WUV060T3AA | 15,000 | $1,800 |
| Yes | 212404699 | CONTINENTAL | WSEHV2436RA1-C | H,DE33(6,9)36 | WUV050T3AA | 15,000 | $1,800 |
| Yes | 212404698 | CONTINENTAL | WSEHV2436RA1-C | H,DE33(6,9)36 | WPV060T3AA | 15,000 | $1,800 |
| Yes | 212404697 | CONTINENTAL | WSEHV2436RA1-C | H,DE33(6,9)36 | WPV050T3AA | 15,000 | $1,800 |
| Yes | 209664495 | CONTINENTAL | CS18HV24A36 | H,DE32(6,9)36 | WPV035T2AA | 15,100 | $1,812 |
| Yes | 209664494 | CONTINENTAL | CS18HV24A36 | H,DE32(6,9)36 | WUV035T2AA | 15,100 | $1,812 |
| Yes | 209048801 | CONTINENTAL | CS18HV24A36 | H,DE33(6,9)36 | WUV070T3AA | 19,400 | $2,328 |
| Yes | 209048794 | CONTINENTAL | CS18HV24A36 | H,DE33(6,9)36 | WUV050T3AA | 19,400 | $2,328 |
| Yes | 209048793 | CONTINENTAL | CS18HV24A36 | H,DE33(6,9)36 | WPV070T3AA | 19,400 | $2,328 |
| Yes | 209048792 | CONTINENTAL | CS18HV24A36 | H,DE33(6,9)36 | WPV050T3AA | 19,400 | $2,328 |
| Yes | 207335558 | CONTINENTAL | CS18HV48A60 | CPFX48A | | 32,000 | $3,840 |
| Yes | 207335559 | CONTINENTAL | CS18HV48A60 | CPFX48A60A | | 36,000 | $4,320 |
| Yes | 207335557 | CONTINENTAL | CS18HV24A36 | CPFX24A36A | | 24,000 | $2,880 |
| Yes | 207335556 | CONTINENTAL | CS18HV24A36 | CPFX24A | | 16,300 | $1,956 |
| Yes | 207657622 | CONVECTAIR | 8422-C36-O | Heat pump without ducts | | 33,000 | $3,960 |
| Yes | 207590846 | CONVECTAIR | 8222-C18-O | Heat pump without ducts | | 15,000 | $1,800 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 207590853 | CONVECTAIR | 8522-C48-O | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 207590852 | CONVECTAIR | 8522-C48-O | Heat pump without ducts | | 36,000 | $4,320 |
| Yes | 207590850 | CONVECTAIR | 8322-C27-O | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 207590849 | CONVECTAIR | 8322-C27-O | Heat pump without ducts | | 26,600 | $3,192 |
| Yes | 207590847 | CONVECTAIR | 8222-C18-O | Heat pump with ducts | | 16,000 | $1,920 |
| Yes | 207709207 | Convectair | 8028-C24-O | 8028-C24-I | | 21,200 | $2,544 |
| Yes | 207709206 | Convectair | 8028-C18-O | 8028-C18-I | | 15,000 | $1,800 |
| Yes | 207657623 | CONVECTAIR | 8422-C36-O | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 206422439 | CONVECTAIR | 8240-O | 8240-I | | 19,400 | $2,328 |
| Yes | 207590854 | CONVECTAIR | 8522-C48-O | Combination heat pumps with or without ducts | | 29,000 | $3,480 |
| Yes | 207657624 | CONVECTAIR | 8422-C36-O | Combination heat pumps with or without ducts | | 23,000 | $2,760 |
| Yes | 211246029 | Cooper&Hunter | CH-NHPR60LCU-230VO | CH-60AHU | | 41,000 | $4,920 |
| Yes | 208141208 | Cooper&Hunter | CH-NHPR48LCU-230VO | CH-48AHU | | 38,000 | $4,560 |
| Yes | 208141207 | Cooper&Hunter | CH-NHPR36LCU-230VO | CH-36AHU | | 28,600 | $3,432 |
| Yes | 208141205 | Cooper&Hunter | CH-HPR18-230VO | CH-M18AHU | | 15,400 | $1,848 |
| Yes | 208101232 | Cooper&Hunter | CH-HPR24-230VO | CH-M24AHU | | 16,900 | $2,028 |
| Yes | 211246028 | COOPER&HUNTER | CH-NHPR60LCU-230VO | CH-60LCDTU/I | | 40,000 | $4,800 |
| Yes | 211246027 | COOPER&HUNTER | CH-NHPR60LCU-230VO | CH-60LCFC/I | | 40,000 | $4,800 |
| Yes | 210799634 | COOPER&HUNTER | CH-HPR36M-230VO | Heat pump without ducts | | 33,000 | $3,960 |
| Yes | 210799645 | COOPER&HUNTER | CH-HPR55M-230VO | Heat pump with ducts | | 35,200 | $4,224 |
| Yes | 210799644 | COOPER&HUNTER | CH-HPR55M-230VO | Heat pump without ducts | | 34,400 | $4,128 |
| Yes | 210799628 | COOPER&HUNTER | CH-HPR19M-230VO | Heat pump without ducts | | 15,000 | $1,800 |
| Yes | 210799637 | COOPER&HUNTER | CH-HPR48M-230VO | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 210799636 | COOPER&HUNTER | CH-HPR48M-230VO | Heat pump without ducts | | 36,000 | $4,320 |
| Yes | 210799632 | COOPER&HUNTER | CH-HPR28M-230VO | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 210799631 | COOPER&HUNTER | CH-HPR28M-230VO | Heat pump without ducts | | 26,600 | $3,192 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 210799629 | COOPER&HUNTER | CH-HPR19M-230VO | Heat pump with ducts | | 16,000 | $1,920 |
| Yes | 210857423 | Cooper&Hunter | CH-HPR18-230VO | CH-18MCT1W-230VI | | 14,500 | $1,740 |
| Yes | 210799599 | Cooper&Hunter | CH-HPR24-230VO | CH-N24MSPHCT-230VI | | 21,000 | $2,520 |
| Yes | 210799614 | Cooper&Hunter | CH-NHPR48LCU-230VO | CH-48LCDTU/I | | 39,500 | $4,740 |
| Yes | 210799613 | Cooper&Hunter | CH-NHPR48LCU-230VO | CH-N48LCCT-230VI | | 35,000 | $4,200 |
| Yes | 210799615 | Cooper&Hunter | CH-NHPR48LCU-230VO | CH-48LCFC/I | | 35,000 | $4,200 |
| Yes | 210799610 | Cooper&Hunter | CH-NHPR36LCU-230VO | CH-N36LCCT-230VI | | 33,000 | $3,960 |
| Yes | 210799612 | Cooper&Hunter | CH-NHPR36LCU-230VO | CH-36LCFC/I | | 32,000 | $3,840 |
| Yes | 210799694 | Cooper&Hunter | CH-HPR24-230VO | CH-B24MOLVWM-230VI | | 18,900 | $2,268 |
| Yes | 210799569 | Cooper&Hunter | CH-HPR24-230VO | CH-24MOLVWM-230VI | | 18,900 | $2,268 |
| Yes | 210799600 | Cooper&Hunter | CH-HPR24-230VO | CH-M24DTUI | | 21,000 | $2,520 |
| Yes | 210799601 | Cooper&Hunter | CH-HPR24-230VO | CH-24MSPHFC-230VI | | 19,000 | $2,280 |
| Yes | 210799597 | Cooper&Hunter | CH-HPR18-230VO | CH-M18DTUI | | 15,000 | $1,800 |
| Yes | 210799551 | Cooper&Hunter | CH-HPR24-230VO | CH-24MASTWM-230VI | | 21,200 | $2,544 |
| Yes | 210799550 | Cooper&Hunter | CH-HPR18-230VO | CH-18MASTWM-230VI | | 15,000 | $1,800 |
| Yes | 210191035 | CTMorley | MOU-A55VH-4 | MIU-A60V-4 | | 42,000 | $5,040 |
| Yes | 209865028 | CTMorley | MOU-A48VH-4 | MIU-A48V-4 | | 36,000 | $4,320 |
| Yes | 209865025 | CTMorley | MOU-A24VH-4 | MIU-A24V-4 | | 19,200 | $2,304 |
| Yes | 209865024 | CTMorley | MOU-A18VH-4 | MIU-A18V-4 | | 13,500 | $1,620 |
| Yes | 210288146 | CTMORLEY | MOU-4A36H-2 | Heat pump without ducts | | 35,000 | $4,200 |
| Yes | 209864940 | CTMORLEY | MOU-5A55H-2 | Heat pump with ducts | | 35,200 | $4,224 |
| Yes | 209864939 | CTMORLEY | MOU-5A55H-2 | Heat pump without ducts | | 34,800 | $4,176 |
| Yes | 210288143 | CTMORLEY | MOU-3A27H-2 | Heat pump without ducts | | 25,600 | $3,072 |
| Yes | 210288141 | CTMORLEY | MOU-2A18H-2 | Heat pump with ducts | | 16,000 | $1,920 |
| Yes | 210288150 | CTMORLEY | MOU-5A48H-2 | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 210288144 | CTMORLEY | MOU-3A27H-2 | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 210288149 | CTMORLEY | MOU-5A48H-2 | Heat pump without ducts | | 39,000 | $4,680 |
| Yes | 210288140 | CTMORLEY | MOU-2A18H-2 | Heat pump without ducts | | 13,500 | $1,620 |
| Yes | 210191034 | CTMorley | MOU-A55LH-2 | MIU-A60LF-2 | | 40,000 | $4,800 |
| Yes | 209864935 | CTMorley | MOU-A18H-2 | MIU-A18CO-2 | | 14,500 | $1,740 |
| Yes | 209843064 | CTMorley | MOU-A24H-2 | MIU-A24C-2 | | 21,000 | $2,520 |
| Yes | 209843079 | CTMorley | MOU-A48LH-2 | MIU-A48LD-2 | | 39,500 | $4,740 |
| Yes | 209843078 | CTMorley | MOU-A48LH-2 | MIU-A48LC-2 | | 35,000 | $4,200 |
| Yes | 209843080 | CTMorley | MOU-A48LH-2 | MIU-A48LF-2 | | 35,000 | $4,200 |
| Yes | 209843075 | CTMorley | MOU-A36LH-2 | MIU-A36LC-2 | | 33,000 | $3,960 |
| Yes | 209843077 | CTMorley | MOU-A36LH-2 | MIU-A36LF-2 | | 32,000 | $3,840 |
| Yes | 209694748 | CTMorley | MOU-A24H-2 | MIU-A24W-2 | | 18,900 | $2,268 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 209843065 | CTMorley | MOU-A24H-2 | MIU-A24D-2 | | 21,000 | $2,520 |
| Yes | 209843066 | CTMorley | MOU-A24H-2 | MIU-A24F-2 | | 19,000 | $2,280 |
| Yes | 209843062 | CTMorley | MOU-A18H-2 | MIU-A18D-2 | | 15,000 | $1,800 |
| Yes | 210191033 | CTMorley | MOU-A55LH-2 | MIU-A60LD-2 | | 40,000 | $4,800 |
| Yes | 209864941 | CTMORLEY | MOU-5A55H-2 | Combination heat pumps with or without ducts | | 35,600 | $4,272 |
| Yes | 211635181 | DAIKIN | RZQ36TBVJU* | FTQ36TAVJU*A* | | 28,400 | $3,408 |
| Yes | 211635180 | DAIKIN | RZQ30TBVJU* | FTQ30TAVJU*A* | | 24,000 | $2,880 |
| Yes | 211635176 | DAIKIN | RZQ18TBVJU* | FTQ18TAVJU*A* | | 13,600 | $1,632 |
| Yes | 211635175 | DAIKIN | RZQ48TBVJU* | FBQ48TBVJU | | 38,000 | $4,560 |
| Yes | 211635174 | DAIKIN | RZQ42TBVJU* | FBQ42TBVJU | | 32,400 | $3,888 |
| Yes | 211635173 | DAIKIN | RZQ36TBVJU* | FBQ36TBVJU | | 28,000 | $3,360 |
| Yes | 211635172 | DAIKIN | RZQ30TBVJU* | FBQ30TBVJU | | 24,000 | $2,880 |
| Yes | 211635170 | DAIKIN | RZQ18TBVJU* | FBQ18TBVJU | | 14,000 | $1,680 |
| Yes | 207158012 | DAIKIN | RXM24VVJU | FTXM24VVJU | | 16,000 | $1,920 |
| Yes | 207158011 | DAIKIN | RXM18VVJU | FTXM18VVJU | | 15,400 | $1,848 |
| Yes | 210791261 | DAIKIN | DZ6VSA6010A* | DV59FECD14A* | | 34,500 | $4,140 |
| Yes | 210791260 | DAIKIN | DZ6VSA4210A* | DV47FECD14A* | | 25,200 | $3,024 |
| Yes | 210791259 | DAIKIN | DZ6VSA3610A* | DV35FECC14A* | | 22,000 | $2,640 |
| Yes | 210791258 | DAIKIN | DZ6VSA3010A* | DV35FECC14A* | | 17,600 | $2,112 |
| Yes | 210435098 | DAIKIN | DZ6VSA4210A* | DV60FECD14A* | | 25,600 | $3,072 |
| Yes | 210435097 | DAIKIN | DZ6VSA4210A* | DV48FECD14A* | | 25,600 | $3,072 |
| Yes | 210435096 | DAIKIN | DZ6VSA4210A* | DV42FECC14A* | | 25,600 | $3,072 |
| Yes | 210435095 | DAIKIN | DZ6VSA4210A* | DFVE60DP1400A* | | 25,600 | $3,072 |
| Yes | 210435094 | DAIKIN | DZ6VSA4210A* | DFVE42CP1400A* | | 25,600 | $3,072 |
| Yes | 210435085 | DAIKIN | DZ6VSA4210A* | DFVE48DP1400A* | | 25,600 | $3,072 |
| Yes | 210692379 | DAIKIN | DZ9VCA3610A* | CSCF3642N6D*+TXV | D*97MC1205DNA* | 21,600 | $2,592 |
| Yes | 210692378 | DAIKIN | DZ9VCA3610A* | CSCF3642N6D*+TXV | D*97MC1005CNA* | 21,600 | $2,592 |
| Yes | 210692377 | DAIKIN | DZ9VCA3610A* | CSCF3642N6D*+TXV | D*97MC0804CNA* | 21,600 | $2,592 |
| Yes | 210692376 | DAIKIN | DZ9VCA3610A* | CSCF3642N6D*+TXV | D*97MC0803BNA* | 21,600 | $2,592 |
| Yes | 210692375 | DAIKIN | DZ9VCA3610A* | CSCF3642N6D*+TXV | D*97MC0603BNA* | 21,600 | $2,592 |
| Yes | 210692374 | DAIKIN | DZ9VCA3610A* | CSCF3642N6D*+TXV | D*96VC1205DNA* | 21,600 | $2,592 |
| Yes | 210692373 | DAIKIN | DZ9VCA3610A* | CSCF3642N6D*+TXV | D*96VC1005CNA* | 21,600 | $2,592 |
| Yes | 210692372 | DAIKIN | DZ9VCA3610A* | CSCF3642N6D*+TXV | D*96SC0805CUA* | 21,600 | $2,592 |
| Yes | 210692371 | DAIKIN | DZ9VCA3610A* | CSCF3642N6D*+TXV | D*96VC0804CNA* | 21,600 | $2,592 |
| Yes | 210692370 | DAIKIN | DZ9VCA3610A* | CSCF3642N6D*+TXV | D*96VC0803BNA* | 21,600 | $2,592 |
| Yes | 210692369 | DAIKIN | DZ9VCA3610A* | CSCF3642N6D*+TXV | D*96VC0603BNA* | 21,600 | $2,592 |
| Yes | 210692368 | DAIKIN | DZ9VCA3610A* | CSCF3642N6D*+TXV | D*96SC0603BUA* | 21,600 | $2,592 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 210692367 | DAIKIN | DZ9VCA3610A* | CSCF3642N6D*+TXV | D*96VC0403BNA* | 21,600 | $2,592 |
| Yes | 210692360 | DAIKIN | DZ9VCA3610A* | CSCF3642N6D*+MBVC1600**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210692359 | DAIKIN | DZ9VCA3610A* | CSCF3642N6D*+MBVC1200**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210692358 | DAIKIN | DZ9VCA3610A* | CHPF3743C6B*+TXV | D*97MC1005CNA* | 21,600 | $2,592 |
| Yes | 210692357 | DAIKIN | DZ9VCA3610A* | CHPF3743C6B*+TXV | D*97MC0804CNA* | 21,600 | $2,592 |
| Yes | 210692356 | DAIKIN | DZ9VCA3610A* | CHPF3743C6B*+TXV | D*97MC0803BNA* | 21,600 | $2,592 |
| Yes | 210692355 | DAIKIN | DZ9VCA3610A* | CHPF3743C6B*+TXV | D*97MC0603BNA* | 21,600 | $2,592 |
| Yes | 210692354 | DAIKIN | DZ9VCA3610A* | CHPF3743C6B*+TXV | D*96VC1005CNA* | 21,600 | $2,592 |
| Yes | 210692353 | DAIKIN | DZ9VCA3610A* | CHPF3743C6B*+TXV | D*96SC0805CUA* | 21,600 | $2,592 |
| Yes | 210692352 | DAIKIN | DZ9VCA3610A* | CHPF3743C6B*+TXV | D*96VC0804CNA* | 21,600 | $2,592 |
| Yes | 210692351 | DAIKIN | DZ9VCA3610A* | CHPF3743C6B*+TXV | D*96VC0803BNA* | 21,600 | $2,592 |
| Yes | 210692350 | DAIKIN | DZ9VCA3610A* | CHPF3743C6B*+TXV | D*96VC0603BNA* | 21,600 | $2,592 |
| Yes | 210692349 | DAIKIN | DZ9VCA3610A* | CHPF3743C6B*+TXV | D*96SC0603BUA* | 21,600 | $2,592 |
| Yes | 210692348 | DAIKIN | DZ9VCA3610A* | CHPF3743C6B*+TXV | D*96VC0403BNA* | 21,600 | $2,592 |
| Yes | 210692341 | DAIKIN | DZ9VCA3610A* | CHPF3743C6B*+MBVC1600**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210692340 | DAIKIN | DZ9VCA3610A* | CHPF3743C6B*+MBVC1200**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210692339 | DAIKIN | DZ9VCA3610A* | CHPF3642C6C*+TXV | D*97MC1005CNA* | 21,600 | $2,592 |
| Yes | 210692338 | DAIKIN | DZ9VCA3610A* | CHPF3642C6C*+TXV | D*97MC0804CNA* | 21,600 | $2,592 |
| Yes | 210692337 | DAIKIN | DZ9VCA3610A* | CHPF3642C6C*+TXV | D*97MC0803BNA* | 21,600 | $2,592 |
| Yes | 210692336 | DAIKIN | DZ9VCA3610A* | CHPF3642C6C*+TXV | D*97MC0603BNA* | 21,600 | $2,592 |
| Yes | 210692335 | DAIKIN | DZ9VCA3610A* | CHPF3642C6C*+TXV | D*96VC1005CNA* | 21,600 | $2,592 |
| Yes | 210692334 | DAIKIN | DZ9VCA3610A* | CHPF3642C6C*+TXV | D*96SC0805CUA* | 21,600 | $2,592 |
| Yes | 210692333 | DAIKIN | DZ9VCA3610A* | CHPF3642C6C*+TXV | D*96VC0804CNA* | 21,600 | $2,592 |
| Yes | 210692332 | DAIKIN | DZ9VCA3610A* | CHPF3642C6C*+TXV | D*96VC0803BNA* | 21,600 | $2,592 |
| Yes | 210692331 | DAIKIN | DZ9VCA3610A* | CHPF3642C6C*+TXV | D*96VC0603BNA* | 21,600 | $2,592 |
| Yes | 210692330 | DAIKIN | DZ9VCA3610A* | CHPF3642C6C*+TXV | D*96SC0603BUA* | 21,600 | $2,592 |
| Yes | 210692329 | DAIKIN | DZ9VCA3610A* | CHPF3642C6C*+TXV | D*96VC0403BNA* | 21,600 | $2,592 |
| Yes | 210692322 | DAIKIN | DZ9VCA3610A* | CHPF3642C6C*+MBVC1600**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210692321 | DAIKIN | DZ9VCA3610A* | CHPF3642C6C*+MBVC1200**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210692320 | DAIKIN | DZ9VCA3610A* | CA*F3743*6D*+TXV | D*97MC1205DNA* | 21,600 | $2,592 |
| Yes | 210692319 | DAIKIN | DZ9VCA3610A* | CA*F3743*6D*+TXV | D*97MC1005CNA* | 21,600 | $2,592 |
| Yes | 210692318 | DAIKIN | DZ9VCA3610A* | CA*F3743*6D*+TXV | D*97MC0804CNA* | 21,600 | $2,592 |
| Yes | 210692317 | DAIKIN | DZ9VCA3610A* | CA*F3743*6D*+TXV | D*97MC0803BNA* | 21,600 | $2,592 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 210692316 | DAIKIN | DZ9VCA3610A* | CA*F3743*6D*+TXV | D*97MC0603BNA* | 21,600 | $2,592 |
| Yes | 210692315 | DAIKIN | DZ9VCA3610A* | CA*F3743*6D*+TXV | D*96VC1205DNA* | 21,600 | $2,592 |
| Yes | 210692314 | DAIKIN | DZ9VCA3610A* | CA*F3743*6D*+TXV | D*96VC1005CNA* | 21,600 | $2,592 |
| Yes | 210692313 | DAIKIN | DZ9VCA3610A* | CA*F3743*6D*+TXV | D*96SC0805CUA* | 21,600 | $2,592 |
| Yes | 210692312 | DAIKIN | DZ9VCA3610A* | CA*F3743*6D*+TXV | D*96VC0804CNA* | 21,600 | $2,592 |
| Yes | 210692311 | DAIKIN | DZ9VCA3610A* | CA*F3743*6D*+TXV | D*96VC0803BNA* | 21,600 | $2,592 |
| Yes | 210692310 | DAIKIN | DZ9VCA3610A* | CA*F3743*6D*+TXV | D*96VC0603BNA* | 21,600 | $2,592 |
| Yes | 210692309 | DAIKIN | DZ9VCA3610A* | CA*F3743*6D*+TXV | D*96SC0603BUA* | 21,600 | $2,592 |
| Yes | 210692308 | DAIKIN | DZ9VCA3610A* | CA*F3743*6D*+TXV | D*96VC0403BNA* | 21,600 | $2,592 |
| Yes | 210607577 | DAIKIN | DZ9VCA3610A* | CA*F3743*6D*+MBVC1600**-1A*+TX | | 21,600 | $2,592 |
| Yes | 210692301 | DAIKIN | DZ9VCA3610A* | CA*F3743*6D*+MBVC1200**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210692300 | DAIKIN | DZ9VCA3610A* | CA*F3137*6A*+TXV | D*97MC0803BNA* | 21,600 | $2,592 |
| Yes | 210692299 | DAIKIN | DZ9VCA3610A* | CA*F3137*6A*+TXV | D*97MC0603BNA* | 21,600 | $2,592 |
| Yes | 210692298 | DAIKIN | DZ9VCA3610A* | CA*F3137*6A*+TXV | D*96VC0803BNA* | 21,600 | $2,592 |
| Yes | 210692297 | DAIKIN | DZ9VCA3610A* | CA*F3137*6A*+TXV | D*96VC0603BNA* | 21,600 | $2,592 |
| Yes | 210692296 | DAIKIN | DZ9VCA3610A* | CA*F3137*6A*+TXV | D*96SC0603BUA* | 21,600 | $2,592 |
| Yes | 210692295 | DAIKIN | DZ9VCA3610A* | CA*F3137*6A*+TXV | D*96VC0403BNA* | 21,600 | $2,592 |
| Yes | 210692292 | DAIKIN | DZ9VCA3610A* | CA*F3137*6A*+MBVC1200**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210609965 | DAIKIN | DZ9VCA3610A* | DMVE48DP1400A* | | 21,600 | $2,592 |
| Yes | 210609964 | DAIKIN | DZ9VCA3610A* | DMVE36CP1400A* | | 21,600 | $2,592 |
| Yes | 207599996 | DAIKIN | DZ17VSA421B* | DV47FECD14A* | | 25,200 | $3,024 |
| Yes | 207599995 | DAIKIN | DZ17VSA361B* | DV35FECC14A* | | 22,000 | $2,640 |
| Yes | 207599994 | DAIKIN | DZ17VSA301B* | DV35FECC14A* | | 17,600 | $2,112 |
| Yes | 205707003 | DAIKIN | RZQ36TAVJU* | FTQ36TAVJU*A* | | 29,000 | $3,480 |
| Yes | 205707002 | DAIKIN | RZQ24TAVJU* | FTQ24TAVJU*A* | | 19,400 | $2,328 |
| Yes | 205754949 | DAIKIN | RZQ30TAVJU* | FTQ30TAVJU*A* | | 24,000 | $2,880 |
| Yes | 205707008 | DAIKIN | RZQ24TAVJU* | FCQ24TAVJU | | 18,000 | $2,160 |
| Yes | 205707009 | DAIKIN | RZQ30TAVJU* | FCQ30TAVJU | | 22,800 | $2,736 |
| Yes | 205707005 | DAIKIN | RZQ24TAVJU* | FBQ24PVJU | | 18,800 | $2,256 |
| Yes | 205801306 | DAIKIN | RZQ18TAVJU* | FBQ18PVJU | | 13,200 | $1,584 |
| Yes | 205707006 | DAIKIN | RZQ30TAVJU* | FBQ30PVJU | | 23,400 | $2,808 |
| Yes | 205706994 | DAIKIN | RZQ36TAVJU* | FBQ36PVJU | | 27,400 | $3,288 |
| Yes | 207599997 | DAIKIN | DZ17VSA601B* | DV59FECD14A* | | 34,400 | $4,128 |
| Yes | 205663342 | DAIKIN | RXL18UMVJU* | FTX18UVJU | | 14,000 | $1,680 |
| Yes | 205663343 | DAIKIN | RXL18UMVJU* | FDMQ18RVJU | | 14,600 | $1,752 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205663345 | DAIKIN | RXL24UMVJU* | FDMQ24RVJU | | 16,000 | $1,920 |
| Yes | 205663344 | DAIKIN | RXL24UMVJU* | FTX24UVJU | | 15,800 | $1,896 |
| Yes | 209852061 | DAY & NIGHT | DLCURAH48ABK | DLFUAAH48XAK | | 36,000 | $4,320 |
| Yes | 209852065 | DAY & NIGHT | DLCURAH36ABK | DLFUAAH36XAK | | 30,400 | $3,648 |
| Yes | 209852059 | DAY & NIGHT | DLCURAH24ABK | DLFUAAH24XAK | | 19,200 | $2,304 |
| Yes | 209852058 | DAY & NIGHT | DLCURAH18ABK | DLFUAAH18XAK | | 13,500 | $1,620 |
| Yes | 207643044 | DAY & NIGHT | DLCMHBH36DAK | Heat pump without ducts | | 22,000 | $2,640 |
| Yes | 207643041 | DAY & NIGHT | DLCMHBH48EAK | Heat pump without ducts | | 34,000 | $4,080 |
| Yes | 207643035 | DAY & NIGHT | DLCMHBH30DAK | Heat pump without ducts | | 18,500 | $2,220 |
| Yes | 206350412 | DAY & NIGHT | DLCSRBH24AAK | DLFSCAH24XAK | | 14,500 | $1,740 |
| Yes | 207826599 | DAY & NIGHT | DLCSRBH18AAK | DLFSABH18XBK | | 12,000 | $1,440 |
| Yes | 207801570 | DAY & NIGHT | DLCSRBH18AAK | DLFSDAH24XAK | | 12,600 | $1,512 |
| Yes | 8177093 | DAY & NIGHT | DLCAHB12K1A | DLFAHH12K1A | | 13,000 | $1,560 |
| Yes | 207643036 | DAY & NIGHT | DLCMHBH30DAK | Heat pump with ducts | | 19,000 | $2,280 |
| Yes | 207643045 | DAY & NIGHT | DLCMHBH36DAK | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 207643042 | DAY & NIGHT | DLCMHBH48EAK | Heat pump with ducts | | 28,000 | $3,360 |
| Yes | 207643046 | DAY & NIGHT | DLCMHBH36DAK | Combination heat pumps with or without ducts | | 22,400 | $2,688 |
| Yes | 207643037 | DAY & NIGHT | DLCMHBH30DAK | Combination heat pumps with or without ducts | | 18,700 | $2,244 |
| Yes | 207643043 | DAY & NIGHT | DLCMHBH48EAK | Combination heat pumps with or without ducts | | 31,000 | $3,720 |
| Yes | 206350414 | DAY & NIGHT | DLCSRBH24AAK | DLFSFAH24XAK | | 14,500 | $1,740 |
| Yes | 206350411 | DAY & NIGHT | DLCSRBH18AAK | DLFSFAH18XAK | | 12,000 | $1,440 |
| Yes | 206350410 | DAY & NIGHT | DLCSRBH18AAK | DLFSDAH18XAK | | 12,700 | $1,524 |
| Yes | 206188302 | DAY & NIGHT | DLCSRBH24AAK | DLFSAAH24XAK | | 16,500 | $1,980 |
| Yes | 206350413 | DAY & NIGHT | DLCSRBH24AAK | DLFSDAH24XAK | | 14,500 | $1,740 |
| Yes | 205921374 | DAY & NIGHT | DLCSRAH24AAK | DLFSAAH24XAK | | 17,500 | $2,100 |
| Yes | 201835637 | DAY & NIGHT | DLCSRAH24AAK | DLFSCAH24XAK | | 16,200 | $1,944 |
| Yes | 202463647 | DAY & NIGHT | DLCPRAH24AAK | DLFPHAH24XAK | | 15,450 | $1,854 |
| Yes | 201835635 | DAY & NIGHT | DLCSRAH24AAK | DLFSDAH24XAK | | 17,400 | $2,088 |
| Yes | 201835614 | DAY & NIGHT | DLCSRAH24AAK | DLFSHAH24XAK | | 15,000 | $1,800 |
| Yes | 201835641 | DAY & NIGHT | DLCLRAH48AAK | DLFLFAH48XAK | | 35,000 | $4,200 |
| Yes | 201835636 | DAY & NIGHT | DLCSRAH24AAK | DLFSFAH24XAK | | 17,200 | $2,064 |
| Yes | 201835634 | DAY & NIGHT | DLCSRAH18AAK | DLFSCAH18XAK | | 12,000 | $1,440 |
| Yes | 210365428 | Dettson | MHD-24 | MHD-CC2.0-17.5-M | | 22,000 | $2,640 |
| Yes | 210365436 | Dettson | EVD-60-O | EVD-60-I | | 42,000 | $5,040 |
| Yes | 210365435 | Dettson | EVD-48-O | EVD-48-I | | 36,000 | $4,320 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 210365432 | Dettson | EVD-24-O | EVD-24-I | | 19,200 | $2,304 |
| Yes | 210365431 | Dettson | EVD-18-O | EVD-18-I | | 13,500 | $1,620 |
| Yes | 210857272 | DIAMONDAIR | D2024SHO2 | DF2024CI2 | | 21,000 | $2,520 |
| Yes | 210857268 | DIAMONDAIR | D2024SHO2 | DF2024HMSI2 | | 18,900 | $2,268 |
| Yes | 212388353 | DIRECT AIR | DIRM-30MAGICPRO20-OU | DIRM-36MAGICPRO20-COIL | | 22,600 | $2,712 |
| Yes | 210342132 | DIRECT AIR | DIRM-60MAGICPRO20-OU | DIRM-60MAGICPRO20-AH | | 42,000 | $5,040 |
| Yes | 207706567 | DIRECT AIR | DIRM-48MAGICPRO20-OU | DIRM-48MAGICPRO20-AH | | 36,000 | $4,320 |
| Yes | 207706564 | DIRECT AIR | DIRM-24MAGICPRO20-OU | DIRM-24MAGICPRO20-AH | | 19,200 | $2,304 |
| Yes | 207706563 | DIRECT AIR | DIRM-18MAGICPRO20-OU | DIRM-18MAGICPRO20-AH | | 13,500 | $1,620 |
| Yes | 207743791 | DIRECT AIR | DIRM-36HXPRO28-4Z | Heat pump without ducts | | 33,000 | $3,960 |
| Yes | 207743785 | DIRECT AIR | DIRM-18HXPRO28-2Z | Heat pump without ducts | | 15,000 | $1,800 |
| Yes | 207743795 | DIRECT AIR | DIRM-48HXPRO28-5Z | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 207743794 | DIRECT AIR | DIRM-48HXPRO28-5Z | Heat pump without ducts | | 36,000 | $4,320 |
| Yes | 207743789 | DIRECT AIR | DIRM-28HXPRO28-3Z | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 207743788 | DIRECT AIR | DIRM-28HXPRO28-3Z | Heat pump without ducts | | 26,600 | $3,192 |
| Yes | 207743786 | DIRECT AIR | DIRM-18HXPRO28-2Z | Heat pump with ducts | | 16,000 | $1,920 |
| Yes | 207743744 | DIRECT AIR | DIRM-24HXPRO28-1Z | DIRM-24HP-CA | | 21,000 | $2,520 |
| Yes | 207743760 | DIRECT AIR | DIRM-24HXPRO28-1Z | DIRM-24HP-DU | | 21,000 | $2,520 |
| Yes | 207743733 | DIRECT AIR | DIRM-24HXPRO28-1Z | DIRM-24HP-CF | | 19,000 | $2,280 |
| Yes | 206377760 | DIRECT AIR | MOX430-17HFN1-MT0W | MTIU-18HWFN1-M | | 15,000 | $1,800 |
| Yes | 207743758 | DIRECT AIR | DIRM-18HXPRO28-1Z | DIRM-18HP-DUV | | 15,000 | $1,800 |
| Yes | 207743757 | DIRECT AIR | DIRM-18HXPRO28-1Z | DIRM-18HP-DUH | | 15,000 | $1,800 |
| Yes | 207743727 | DIRECT AIR | DIRM-24HXPRO28-1Z | DIRM-24HP-WM | | 21,200 | $2,544 |
| Yes | 207743726 | DIRECT AIR | DIRM-18HXPRO28-1Z | DIRM-18HP-WM | | 15,000 | $1,800 |
| Yes | 203269783 | DIRECT AIR | M3OH-27HFN1-M | Heat pump without ducts | | 18,000 | $2,160 |
| Yes | 205920170 | DIRECT AIR | M5OG-48HFN1-M-[X] | Heat pump with ducts | | 28,000 | $3,360 |
| Yes | 207743792 | DIRECT AIR | DIRM-36HXPRO28-4Z | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 207743796 | DIRECT AIR | DIRM-48HXPRO28-5Z | Combination heat pumps with or without ducts | | 29,000 | $3,480 |
| Yes | 207743793 | DIRECT AIR | DIRM-36HXPRO28-4Z | Combination heat pumps with or without ducts | | 23,000 | $2,760 |
| Yes | 205920169 | DIRECT AIR | M5OG-48HFN1-M-[X] | Heat pump without ducts | | 30,000 | $3,600 |
| Yes | 212394335 | DIYCOOL | ACIQ-30-HPB | ACIQ-30-ACL | | 22,600 | $2,712 |
| Yes | 210857359 | DIYCOOL | ACIQ-60HPB | ACIQ-60AHB | | 42,000 | $5,040 |
| Yes | 210857360 | DIYCOOL | ACIQ-18ZPL-HP230B | ACIQ-18AHB-HH-M | | 15,400 | $1,848 |
| Yes | 210857361 | DIYCOOL | ACIQ-24ZPL-HP230B | ACIQ-24AHB-HH-M | | 16,900 | $2,028 |
| Yes | 208106634 | DIYCOOL | ACIQ-48-HPB | ACIQ-48-AHB | | 36,000 | $4,320 |
| Yes | 208106632 | DIYCOOL | ACIQ-24-HPB | ACIQ-24-AHB | | 19,200 | $2,304 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 210857350 | DIYCOOL | ACIQ-18ZPL-HP230B | SCC-1218-HH-M | | 14,500 | $1,740 |
| Yes | 207825594 | DIYCOOL | ACIQ-36Z-HH-M4B | Heat pump without ducts | | 33,000 | $3,960 |
| Yes | 210857399 | DIYCOOL | ACIQ-55Z-HH-M5B | Heat pump with ducts | | 35,200 | $4,224 |
| Yes | 210857398 | DIYCOOL | ACIQ-55Z-HH-M5B | Heat pump without ducts | | 34,400 | $4,128 |
| Yes | 207825588 | DIYCOOL | ACIQ-18Z-HH-M2B | Heat pump without ducts | | 15,000 | $1,800 |
| Yes | 207825598 | DIYCOOL | ACIQ-48Z-HH-M5B | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 207825597 | DIYCOOL | ACIQ-48Z-HH-M5B | Heat pump without ducts | | 36,000 | $4,320 |
| Yes | 207825592 | DIYCOOL | ACIQ-27Z-HH-M3B | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 207825591 | DIYCOOL | ACIQ-27Z-HH-M3B | Heat pump without ducts | | 26,600 | $3,192 |
| Yes | 207825589 | DIYCOOL | ACIQ-18Z-HH-M2B | Heat pump with ducts | | 16,000 | $1,920 |
| Yes | 210857346 | DIYCOOL | ACIQ-60ZPL-HP230B | ACIQ-60FM-HH-MB | | 40,000 | $4,800 |
| Yes | 210857342 | DIYCOOL | ACIQ-48ZPL-HP230B | ACIQ-48CD-HH-MB | | 39,500 | $4,740 |
| Yes | 210857340 | DIYCOOL | ACIQ-48ZPL-HP230B | ACIQ-48CC-HH-MB | | 35,000 | $4,200 |
| Yes | 210857345 | DIYCOOL | ACIQ-48ZPL-HP230B | ACIQ-48FM-HH-MB | | 35,000 | $4,200 |
| Yes | 210857339 | DIYCOOL | ACIQ-36ZPL-HP230B | ACIQ-36CC-HH-MB | | 33,000 | $3,960 |
| Yes | 210857344 | DIYCOOL | ACIQ-36ZPL-HP230B | ACIQ-36FM-HH-MB | | 32,000 | $3,840 |
| Yes | 207825560 | DIYCOOL | ACIQ-24ZPL-HP230B | ACIQ-24CD-HH-MB | | 21,000 | $2,520 |
| Yes | 207825563 | DIYCOOL | ACIQ-24ZPL-HP230B | ACIQ-24FM-HH-MB | | 19,000 | $2,280 |
| Yes | 207825559 | DIYCOOL | ACIQ-18ZPL-HP230B | ACIQ-18CD-HH-MB | | 15,000 | $1,800 |
| Yes | 207825553 | DIYCOOL | ACIQ-24ZPL-HP230B | ACIQ-24W-HH-MB | | 21,200 | $2,544 |
| Yes | 210857338 | DIYCOOL | ACIQ-24ZPL-HP230B | ACIQ-24W-HH-MC | | 21,200 | $2,544 |
| Yes | 210857337 | DIYCOOL | ACIQ-18ZPL-HP230B | ACIQ-18W-HH-MC | | 15,000 | $1,800 |
| Yes | 207825552 | DIYCOOL | ACIQ-18ZPL-HP230B | ACIQ-18W-HH-MB | | 15,000 | $1,800 |
| Yes | 210857343 | DIYCOOL | ACIQ-60ZPL-HP230B | ACIQ-60CD-HH-MB | | 40,000 | $4,800 |
| Yes | 207825595 | DIYCOOL | ACIQ-36Z-HH-M4B | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 206315628 | DIYCOOL | ACIQ-24-HP | ACIQ-24-AH | | 16,500 | $1,980 |
| Yes | 206315650 | DIYCOOL | ACIQ-27Z-HH-M3 | Heat pump without ducts | | 18,000 | $2,160 |
| Yes | 207825596 | DIYCOOL | ACIQ-36Z-HH-M4B | Combination heat pumps with or without ducts | | 23,000 | $2,760 |
| Yes | 207825599 | DIYCOOL | ACIQ-48Z-HH-M5B | Combination heat pumps with or without ducts | | 29,000 | $3,480 |
| Yes | 206315652 | DIYCOOL | ACIQ-48Z-HH-M5 | Heat pump without ducts | | 30,000 | $3,600 |
| Yes | 208106854 | DUCANE | 4DHP2S48M-1P | Heat pump without ducts | | 36,000 | $4,320 |
| Yes | 210568105 | DURASTAR | DRA1H18S1A | DRAL18F1A | | 14,500 | $1,740 |
| Yes | 210568225 | DURASTAR | DRA5H55M1A | Combination heat pumps with or without ducts | | 35,000 | $4,200 |
| Yes | 210568224 | DURASTAR | DRA5H55M1A | Heat pump with ducts | | 35,200 | $4,224 |
| Yes | 210568223 | DURASTAR | DRA5H55M1A | Heat pump without ducts | | 34,800 | $4,176 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 210568216 | DURASTAR | DRA3H28M1A | Combination heat pumps with or without ducts | | 26,200 | $3,144 |
| Yes | 210568214 | DURASTAR | DRA3H28M1A | Heat pump without ducts | | 25,600 | $3,072 |
| Yes | 210568213 | DURASTAR | DRA2H18M1A | Combination heat pumps with or without ducts | | 14,700 | $1,764 |
| Yes | 210568212 | DURASTAR | DRA2H18M1A | Heat pump with ducts | | 16,000 | $1,920 |
| Yes | 210568222 | DURASTAR | DRA5H48M1A | Combination heat pumps with or without ducts | | 37,400 | $4,488 |
| Yes | 210568221 | DURASTAR | DRA5H48M1A | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 210568219 | DURASTAR | DRA4H36M1A | Combination heat pumps with or without ducts | | 35,000 | $4,200 |
| Yes | 210568215 | DURASTAR | DRA3H28M1A | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 210568220 | DURASTAR | DRA5H48M1A | Heat pump without ducts | | 39,000 | $4,680 |
| Yes | 210568217 | DURASTAR | DRA4H36M1A | Heat pump without ducts | | 35,000 | $4,200 |
| Yes | 210568211 | DURASTAR | DRA2H18M1A | Heat pump without ducts | | 13,500 | $1,620 |
| Yes | 210568114 | DURASTAR | DRA1H24S1A | DRAC24F1B | | 21,000 | $2,520 |
| Yes | 210568101 | DURASTAR | DRA1H24S1A | DRAW24F1B | | 18,900 | $2,268 |
| Yes | 210568118 | DURASTAR | DRA1H24S1A | DRAD24F1A | | 21,000 | $2,520 |
| Yes | 210568120 | DURASTAR | DRA1H24S1A | DRAF24F1A | | 19,000 | $2,280 |
| Yes | 210568117 | DURASTAR | DRA1H18S1A | DRAD18F1A | | 15,000 | $1,800 |
| Yes | 211253520 | ECO AC | EHI-O60BAH | EHI-V60BA | | 42,000 | $5,040 |
| Yes | 211253519 | ECO AC | EHI-O48BAH | EHI-V48BA | | 36,000 | $4,320 |
| Yes | 211253516 | ECO AC | EHI-O24BAH | EHI-V24BA | | 19,200 | $2,304 |
| Yes | 211253515 | ECO AC | EHI-O18BAH | EHI-V18BA | | 13,500 | $1,620 |
| Yes | 210586157 | ECO AC | EMH-4O36BBH | Heat pump without ducts | | 35,000 | $4,200 |
| Yes | 210586154 | ECO AC | EMH-3O27BBH | Heat pump without ducts | | 25,600 | $3,072 |
| Yes | 210586152 | ECO AC | EMH-2O18BBH | Heat pump with ducts | | 16,000 | $1,920 |
| Yes | 210586155 | ECO AC | EMH-3O27BBH | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 210586151 | ECO AC | EMH-2O18BBH | Heat pump without ducts | | 13,500 | $1,620 |
| Yes | 209319644 | ECO AIR | M4OI-36HFN1-M | Heat pump without ducts | | 33,000 | $3,960 |
| Yes | 209319651 | ECO AIR | M5OA-55HFN1-M-[X] | Heat pump with ducts | | 35,200 | $4,224 |
| Yes | 209319650 | ECO AIR | M5OA-55HFN1-M-[X] | Heat pump without ducts | | 34,400 | $4,128 |
| Yes | 209319638 | ECO AIR | M2OI-18HFN1-M | Heat pump without ducts | | 15,000 | $1,800 |
| Yes | 209319648 | ECO AIR | M5OG-48HFN1-M-[X] | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 209319647 | ECO AIR | M5OG-48HFN1-M-[X] | Heat pump without ducts | | 36,000 | $4,320 |
| Yes | 209319642 | ECO AIR | M3OI-28HFN1-M | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 209319641 | ECO AIR | M3OI-28HFN1-M | Heat pump without ducts | | 26,600 | $3,192 |
| Yes | 209319639 | ECO AIR | M2OI-18HFN1-M | Heat pump with ducts | | 16,000 | $1,920 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 211644095 | ECO-AIR | MOX430-17HFN1-MT0W | MCBU-18HRFN1-MU2W | | 14,500 | $1,740 |
| Yes | 211644071 | ECO-AIR | MOD30-24HFN1-MU0W | MCD1-24HRFN1-MT0W(GA) | | 21,000 | $2,520 |
| Yes | 211644067 | ECO-AIR | MOE30U-48HFN1-M-[X](GA) | MTI-48HWFN1-M | | 39,500 | $4,740 |
| Yes | 211644073 | ECO-AIR | MOE30U-48HFN1-M-[X](GA) | MCD1-48HRFN1-M(GA) | | 35,000 | $4,200 |
| Yes | 211644072 | ECO-AIR | MOE30U-36HFN1-M(GA) | MCD1-36HRFN1-M(GA) | | 33,000 | $3,960 |
| Yes | 211644065 | ECO-AIR | MOD30-24HFN1-MU0W | MTIU-24HWFN1-M | | 21,000 | $2,520 |
| Yes | 211644064 | ECO-AIR | MOX430-17HFN1-MT0W | MTIU-18HWFN1-M | | 15,000 | $1,800 |
| Yes | 211644112 | ECO-AIR | MOX430-17HFN1-MT0W | MVC-18HWFN1-MW(GA) | | 15,400 | $1,848 |
| Yes | 211644113 | ECO-AIR | MOD30-24HFN1-MU0W | MVC-23HWFN1-M | | 16,900 | $2,028 |
| Yes | 208130406 | ECO-AIR | MOE30U-48HFN1-M-[X1] | MVC-48HWFN1-M | | 36,000 | $4,320 |
| Yes | 208130403 | ECO-AIR | MOD30-24HFN1-MW | MVC-24HWFN1-M | | 19,200 | $2,304 |
| Yes | 208130402 | ECO-AIR | MOX430U-18HFN1-M | MVC-18HWFN1-M | | 13,500 | $1,620 |
| Yes | 209270321 | ECO-AIR | MOD30U-30HFN1-MR0(X) | MAC-36HWFN1-M | | 22,600 | $2,712 |
| Yes | 208121867 | ECO-AIR | MOD30-24HFN1-MU0W | MSEPD-24HRFN1-MU0W | | 21,200 | $2,544 |
| Yes | 208121866 | ECO-AIR | MOX430-17HFN1-MT0W | MSEPC-18HRFN1-MU0W | | 15,000 | $1,800 |
| Yes | 209319649 | ECO-AIR | M5OG-48HFN1-M-[X] | Combination heat pumps with or without ducts | | 29,000 | $3,480 |
| Yes | 209319652 | ECO-AIR | M5OA-55HFN1-M-[X] | Combination heat pumps with or without ducts | | 35,400 | $4,248 |
| Yes | 209319646 | ECO-AIR | M4OI-36HFN1-M | Combination heat pumps with or without ducts | | 23,000 | $2,760 |
| Yes | 209319645 | ECO-AIR | M4OI-36HFN1-M | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 211594474 | Ecoer | ESCA16H-60 | EAHAEC-60 | | 42,000 | $5,040 |
| Yes | 207742466 | ELIOS | DEA36HOM25230X3 | Heat pump without ducts | | 33,000 | $3,960 |
| Yes | 208136314 | ELIOS | DEA55HOM25230X3 | Heat pump with ducts | | 35,200 | $4,224 |
| Yes | 208136313 | ELIOS | DEA55HOM25230X3 | Heat pump without ducts | | 34,400 | $4,128 |
| Yes | 207742460 | ELIOS | DEA18HOM25230X3 | Heat pump without ducts | | 15,000 | $1,800 |
| Yes | 207742470 | ELIOS | DEA48HOM25230X3 | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 207742469 | ELIOS | DEA48HOM25230X3 | Heat pump without ducts | | 36,000 | $4,320 |
| Yes | 207742464 | ELIOS | DEA27HOM25230X3 | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 207742463 | ELIOS | DEA27HOM25230X3 | Heat pump without ducts | | 26,600 | $3,192 |
| Yes | 207742461 | ELIOS | DEA18HOM25230X3 | Heat pump with ducts | | 16,000 | $1,920 |
| Yes | 207742442 | ELIOS | DEA24HOS28230E8 | DUA24HICU230X5 | | 21,000 | $2,520 |
| Yes | 207742457 | ELIOS | DEA48HOS28230E8 | DUA48HIDU230X5 | | 39,500 | $4,740 |
| Yes | 207742444 | ELIOS | DEA48HOS28230E8 | DUA48HICU230X5 | | 35,000 | $4,200 |
| Yes | 207742443 | ELIOS | DEA36HOS28230E8 | DUA36HICU230X5 | | 33,000 | $3,960 |
| Yes | 206401449 | ELIOS | DE24HOS25230E3A | DM24HIDU230X5 | | 21,000 | $2,520 |
| Yes | 207742455 | ELIOS | DEA24HOS28230E8 | DUA24HIDU230X5 | | 21,000 | $2,520 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 206401446 | ELIOS | DE18HOS25230E3A | DM18HIDU230X5 | | 15,000 | $1,800 |
| Yes | 207742454 | ELIOS | DEA18HOS28230E8 | DUA18HIDU230X5 | | 15,000 | $1,800 |
| Yes | 207742432 | ELIOS | DEA24HOS28230E8 | DEA24HIW25230E8 | | 21,200 | $2,544 |
| Yes | 207742431 | ELIOS | DEA18HOS28230E8 | DEA18HIW25230E8 | | 15,000 | $1,800 |
| Yes | 205300176 | ELIOS | DE24HOS25230E3 | DM24HIDU230X5 | | 17,200 | $2,064 |
| Yes | 204005781 | ELIOS | DE24HOS25230E3 | DE24HIDU230X5 | | 17,200 | $2,064 |
| Yes | 204005788 | ELIOS | DE27HOM25230X3 | Heat pump without ducts | | 18,000 | $2,160 |
| Yes | 207742467 | ELIOS | DEA36HOM25230X3 | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 206853242 | ELIOS | DE36HOS25230E3 | DM36HIDU230X5 | | 28,000 | $3,360 |
| Yes | 206853243 | ELIOS | DE48HOS25230E3 | DM48HIDU230X5 | | 33,000 | $3,960 |
| Yes | 206401448 | ELIOS | DE24HOS25230E3A | DE24HIW23230E3 | | 19,400 | $2,328 |
| Yes | 207645903 | ELIOS | DE48HOS25230E3 | DM48HICU230X5 | | 35,000 | $4,200 |
| Yes | 208119831 | ELIOS | DEA24HOS28230E8 | DE24HIW23230E3 | | 19,400 | $2,328 |
| Yes | 208136315 | ELIOS | DEA55HOM25230X3 | Combination heat pumps with or without ducts | | 35,400 | $4,248 |
| Yes | 207742471 | ELIOS | DEA48HOM25230X3 | Combination heat pumps with or without ducts | | 29,000 | $3,480 |
| Yes | 207742468 | ELIOS | DEA36HOM25230X3 | Combination heat pumps with or without ducts | | 23,000 | $2,760 |
| Yes | 207645902 | ELIOS | DE36HOS25230E3 | DM36HICU230X5 | | 25,400 | $3,048 |
| Yes | 10298959 | EMERSON QUIET KOOL | HP-20EACH24R2O | HP-20EACH24R2I | | 15,400 | $1,848 |
| Yes | 208121938 | EMI | MHMZ436DA | Heat pump without ducts | | 33,000 | $3,960 |
| Yes | 208121932 | EMI | MHMZ218DA | Heat pump without ducts | | 15,000 | $1,800 |
| Yes | 208121942 | EMI | MHMZ548DA | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 208121941 | EMI | MHMZ548DA | Heat pump without ducts | | 36,000 | $4,320 |
| Yes | 208121936 | EMI | MHMZ327DA | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 208121935 | EMI | MHMZ327DA | Heat pump without ducts | | 26,600 | $3,192 |
| Yes | 208121933 | EMI | MHMZ218DA | Heat pump with ducts | | 16,000 | $1,920 |
| Yes | 208121931 | EMI | MHSZ124DA | MHCAS24DA | | 21,000 | $2,520 |
| Yes | 208121927 | EMI | MHSZ124DA | MHWAL24DA | | 21,200 | $2,544 |
| Yes | 208121926 | EMI | MHSZ118DA | MHWAL18DA | | 15,000 | $1,800 |
| Yes | 203514062 | EMI | DHMZ327DA | Heat pump without ducts | | 18,000 | $2,160 |
| Yes | 208121939 | EMI | MHMZ436DA | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 208121943 | EMI | MHMZ548DA | Combination heat pumps with or without ducts | | 29,000 | $3,480 |
| Yes | 208121940 | EMI | MHMZ436DA | Combination heat pumps with or without ducts | | 23,000 | $2,760 |
| Yes | 208939392 | FORESTAIR | FAD36W/A-D(U) | FAD36AH2/A-D(U) | | 24,000 | $2,880 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 208939391 | FORESTAIR | FAD36W/A-D(U) | FAD24AH2/A-D(U) | | 16,300 | $1,956 |
| Yes | 208939395 | FORESTAIR | FAD60W/A-D(U) | FAD60AH2/A-D(U) | | 23,000 | $2,760 |
| Yes | 208939393 | FORESTAIR | FAD60W/A-D(U) | FAD48AH2/A-D(U) | | 21,000 | $2,520 |
| Yes | 206720377 | FORESTAIR | FGH-18ES/E-38-O | FGH-18ES/E-38-I | | 14,200 | $1,704 |
| Yes | 210693195 | FRANKLIN | ASZV903610A* | CSCF3642N6D*+TXV | G*VM971205DNB* | 21,600 | $2,592 |
| Yes | 210693194 | FRANKLIN | ASZV903610A* | CSCF3642N6D*+TXV | G*VM971005CNB* | 21,600 | $2,592 |
| Yes | 210693193 | FRANKLIN | ASZV903610A* | CSCF3642N6D*+TXV | G*VM970804CNB* | 21,600 | $2,592 |
| Yes | 210693192 | FRANKLIN | ASZV903610A* | CSCF3642N6D*+TXV | G*VM970803BNB* | 21,600 | $2,592 |
| Yes | 210693191 | FRANKLIN | ASZV903610A* | CSCF3642N6D*+TXV | G*VM970603BNB* | 21,600 | $2,592 |
| Yes | 210693190 | FRANKLIN | ASZV903610A* | CSCF3642N6D*+TXV | G*VC961205DNB* | 21,600 | $2,592 |
| Yes | 210693189 | FRANKLIN | ASZV903610A* | CSCF3642N6D*+TXV | G*VC961005CNB* | 21,600 | $2,592 |
| Yes | 210693188 | FRANKLIN | ASZV903610A* | CSCF3642N6D*+TXV | G*VS960805CUA* | 21,600 | $2,592 |
| Yes | 210693187 | FRANKLIN | ASZV903610A* | CSCF3642N6D*+TXV | G*VC960804CNB* | 21,600 | $2,592 |
| Yes | 210693186 | FRANKLIN | ASZV903610A* | CSCF3642N6D*+TXV | G*VC960803BNB* | 21,600 | $2,592 |
| Yes | 210693185 | FRANKLIN | ASZV903610A* | CSCF3642N6D*+TXV | G*VC960603BNB* | 21,600 | $2,592 |
| Yes | 210693184 | FRANKLIN | ASZV903610A* | CSCF3642N6D*+TXV | G*VS960603BUA* | 21,600 | $2,592 |
| Yes | 210693183 | FRANKLIN | ASZV903610A* | CSCF3642N6D*+TXV | G*VC960403BNB* | 21,600 | $2,592 |
| Yes | 210693176 | FRANKLIN | ASZV903610A* | CSCF3642N6D*+MBVC1601**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210693175 | FRANKLIN | ASZV903610A* | CSCF3642N6D*+MBVC1201**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210693174 | FRANKLIN | ASZV903610A* | CHPF3743C6B*+TXV | G*VM971005CNB* | 21,600 | $2,592 |
| Yes | 210693173 | FRANKLIN | ASZV903610A* | CHPF3743C6B*+TXV | G*VM970804CNB* | 21,600 | $2,592 |
| Yes | 210693172 | FRANKLIN | ASZV903610A* | CHPF3743C6B*+TXV | G*VM970803BNB* | 21,600 | $2,592 |
| Yes | 210693171 | FRANKLIN | ASZV903610A* | CHPF3743C6B*+TXV | G*VM970603BNB* | 21,600 | $2,592 |
| Yes | 210693170 | FRANKLIN | ASZV903610A* | CHPF3743C6B*+TXV | G*VC961005CNB* | 21,600 | $2,592 |
| Yes | 210693169 | FRANKLIN | ASZV903610A* | CHPF3743C6B*+TXV | G*VS960805CUA* | 21,600 | $2,592 |
| Yes | 210693168 | FRANKLIN | ASZV903610A* | CHPF3743C6B*+TXV | G*VC960804CNB* | 21,600 | $2,592 |
| Yes | 210693167 | FRANKLIN | ASZV903610A* | CHPF3743C6B*+TXV | G*VC960803BNB* | 21,600 | $2,592 |
| Yes | 210693166 | FRANKLIN | ASZV903610A* | CHPF3743C6B*+TXV | G*VC960603BNB* | 21,600 | $2,592 |
| Yes | 210693165 | FRANKLIN | ASZV903610A* | CHPF3743C6B*+TXV | G*VS960603BUA* | 21,600 | $2,592 |
| Yes | 210693164 | FRANKLIN | ASZV903610A* | CHPF3743C6B*+TXV | G*VC960403BNB* | 21,600 | $2,592 |
| Yes | 210693157 | FRANKLIN | ASZV903610A* | CHPF3743C6B*+MBVC1601**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210693156 | FRANKLIN | ASZV903610A* | CHPF3743C6B*+MBVC1201**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210693155 | FRANKLIN | ASZV903610A* | CHPF3642C6C*+TXV | G*VM971005CNB* | 21,600 | $2,592 |
| Yes | 210693154 | FRANKLIN | ASZV903610A* | CHPF3642C6C*+TXV | G*VM970804CNB* | 21,600 | $2,592 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 210693153 | FRANKLIN | ASZV903610A* | CHPF3642C6C*+TXV | G*VM970803BNB* | 21,600 | $2,592 |
| Yes | 210693152 | FRANKLIN | ASZV903610A* | CHPF3642C6C*+TXV | G*VM970603BNB* | 21,600 | $2,592 |
| Yes | 210693151 | FRANKLIN | ASZV903610A* | CHPF3642C6C*+TXV | G*VC961005CNB* | 21,600 | $2,592 |
| Yes | 210693150 | FRANKLIN | ASZV903610A* | CHPF3642C6C*+TXV | G*VS960805CUA* | 21,600 | $2,592 |
| Yes | 210693149 | FRANKLIN | ASZV903610A* | CHPF3642C6C*+TXV | G*VC960804CNB* | 21,600 | $2,592 |
| Yes | 210693148 | FRANKLIN | ASZV903610A* | CHPF3642C6C*+TXV | G*VC960803BNB* | 21,600 | $2,592 |
| Yes | 210693147 | FRANKLIN | ASZV903610A* | CHPF3642C6C*+TXV | G*VC960603BNB* | 21,600 | $2,592 |
| Yes | 210693146 | FRANKLIN | ASZV903610A* | CHPF3642C6C*+TXV | G*VS960603BUA* | 21,600 | $2,592 |
| Yes | 210693145 | FRANKLIN | ASZV903610A* | CHPF3642C6C*+TXV | G*VC960403BNB* | 21,600 | $2,592 |
| Yes | 210693138 | FRANKLIN | ASZV903610A* | CHPF3642C6C*+MBVC1601**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210693137 | FRANKLIN | ASZV903610A* | CHPF3642C6C*+MBVC1201**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210693136 | FRANKLIN | ASZV903610A* | CA*F3743*6D*+TXV | G*VM971205DNB* | 21,600 | $2,592 |
| Yes | 210693135 | FRANKLIN | ASZV903610A* | CA*F3743*6D*+TXV | G*VM971005CNB* | 21,600 | $2,592 |
| Yes | 210693134 | FRANKLIN | ASZV903610A* | CA*F3743*6D*+TXV | G*VM970804CNB* | 21,600 | $2,592 |
| Yes | 210693133 | FRANKLIN | ASZV903610A* | CA*F3743*6D*+TXV | G*VM970803BNB* | 21,600 | $2,592 |
| Yes | 210693132 | FRANKLIN | ASZV903610A* | CA*F3743*6D*+TXV | G*VM970603BNB* | 21,600 | $2,592 |
| Yes | 210693131 | FRANKLIN | ASZV903610A* | CA*F3743*6D*+TXV | G*VC961205DNB* | 21,600 | $2,592 |
| Yes | 210693130 | FRANKLIN | ASZV903610A* | CA*F3743*6D*+TXV | G*VC961005CNB* | 21,600 | $2,592 |
| Yes | 210693129 | FRANKLIN | ASZV903610A* | CA*F3743*6D*+TXV | G*VS960805CUA* | 21,600 | $2,592 |
| Yes | 210693128 | FRANKLIN | ASZV903610A* | CA*F3743*6D*+TXV | G*VC960804CNB* | 21,600 | $2,592 |
| Yes | 210693127 | FRANKLIN | ASZV903610A* | CA*F3743*6D*+TXV | G*VC960803BNB* | 21,600 | $2,592 |
| Yes | 210693126 | FRANKLIN | ASZV903610A* | CA*F3743*6D*+TXV | G*VC960603BNB* | 21,600 | $2,592 |
| Yes | 210693125 | FRANKLIN | ASZV903610A* | CA*F3743*6D*+TXV | G*VS960603BUA* | 21,600 | $2,592 |
| Yes | 210693124 | FRANKLIN | ASZV903610A* | CA*F3743*6D*+TXV | G*VC960403BNB* | 21,600 | $2,592 |
| Yes | 210607414 | FRANKLIN | ASZV903610A* | CA*F3743*6D*+MBVC1601**-1A*+TX | | 21,600 | $2,592 |
| Yes | 210693117 | FRANKLIN | ASZV903610A* | CA*F3743*6D*+MBVC1201**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210693116 | FRANKLIN | ASZV903610A* | CA*F3137*6A*+TXV | G*VM970803BNB* | 21,600 | $2,592 |
| Yes | 210693115 | FRANKLIN | ASZV903610A* | CA*F3137*6A*+TXV | G*VM970603BNB* | 21,600 | $2,592 |
| Yes | 210693114 | FRANKLIN | ASZV903610A* | CA*F3137*6A*+TXV | G*VC960803BNB* | 21,600 | $2,592 |
| Yes | 210693113 | FRANKLIN | ASZV903610A* | CA*F3137*6A*+TXV | G*VC960603BNB* | 21,600 | $2,592 |
| Yes | 210693112 | FRANKLIN | ASZV903610A* | CA*F3137*6A*+TXV | G*VS960603BUA* | 21,600 | $2,592 |
| Yes | 210693111 | FRANKLIN | ASZV903610A* | CA*F3137*6A*+TXV | G*VC960403BNB* | 21,600 | $2,592 |
| Yes | 210693108 | FRANKLIN | ASZV903610A* | CA*F3137*6A*+MBVC1201**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210609973 | FRANKLIN | ASZV903610A* | AMVE48DP1400A* | | 21,600 | $2,592 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 210609972 | FRANKLIN | ASZV903610A* | AMVE36CP1400A* | | 21,600 | $2,592 |
| Yes | 210692991 | FRANKLIN | GSZV903610A* | CSCF3642N6D*+TXV | G*VM971205DNB* | 21,600 | $2,592 |
| Yes | 210692990 | FRANKLIN | GSZV903610A* | CSCF3642N6D*+TXV | G*VM971005CNB* | 21,600 | $2,592 |
| Yes | 210692989 | FRANKLIN | GSZV903610A* | CSCF3642N6D*+TXV | G*VM970804CNB* | 21,600 | $2,592 |
| Yes | 210692988 | FRANKLIN | GSZV903610A* | CSCF3642N6D*+TXV | G*VM970803BNB* | 21,600 | $2,592 |
| Yes | 210692987 | FRANKLIN | GSZV903610A* | CSCF3642N6D*+TXV | G*VM970603BNB* | 21,600 | $2,592 |
| Yes | 210692986 | FRANKLIN | GSZV903610A* | CSCF3642N6D*+TXV | G*VC961205DNB* | 21,600 | $2,592 |
| Yes | 210692985 | FRANKLIN | GSZV903610A* | CSCF3642N6D*+TXV | G*VC961005CNB* | 21,600 | $2,592 |
| Yes | 210692984 | FRANKLIN | GSZV903610A* | CSCF3642N6D*+TXV | G*VS960805CUA* | 21,600 | $2,592 |
| Yes | 210692983 | FRANKLIN | GSZV903610A* | CSCF3642N6D*+TXV | G*VC960804CNB* | 21,600 | $2,592 |
| Yes | 210692982 | FRANKLIN | GSZV903610A* | CSCF3642N6D*+TXV | G*VC960803BNB* | 21,600 | $2,592 |
| Yes | 210692981 | FRANKLIN | GSZV903610A* | CSCF3642N6D*+TXV | G*VC960603BNB* | 21,600 | $2,592 |
| Yes | 210692980 | FRANKLIN | GSZV903610A* | CSCF3642N6D*+TXV | G*VS960603BUA* | 21,600 | $2,592 |
| Yes | 210692979 | FRANKLIN | GSZV903610A* | CSCF3642N6D*+TXV | G*VC960403BNB* | 21,600 | $2,592 |
| Yes | 210692972 | FRANKLIN | GSZV903610A* | CSCF3642N6D*+MBVC1601**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210692971 | FRANKLIN | GSZV903610A* | CSCF3642N6D*+MBVC1201**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210692970 | FRANKLIN | GSZV903610A* | CHPF3743C6B*+TXV | G*VM971005CNB* | 21,600 | $2,592 |
| Yes | 210692969 | FRANKLIN | GSZV903610A* | CHPF3743C6B*+TXV | G*VM970804CNB* | 21,600 | $2,592 |
| Yes | 210692968 | FRANKLIN | GSZV903610A* | CHPF3743C6B*+TXV | G*VM970803BNB* | 21,600 | $2,592 |
| Yes | 210692967 | FRANKLIN | GSZV903610A* | CHPF3743C6B*+TXV | G*VM970603BNB* | 21,600 | $2,592 |
| Yes | 210692966 | FRANKLIN | GSZV903610A* | CHPF3743C6B*+TXV | G*VC961005CNB* | 21,600 | $2,592 |
| Yes | 210692965 | FRANKLIN | GSZV903610A* | CHPF3743C6B*+TXV | G*VS960805CUA* | 21,600 | $2,592 |
| Yes | 210692964 | FRANKLIN | GSZV903610A* | CHPF3743C6B*+TXV | G*VC960804CNB* | 21,600 | $2,592 |
| Yes | 210692963 | FRANKLIN | GSZV903610A* | CHPF3743C6B*+TXV | G*VC960803BNB* | 21,600 | $2,592 |
| Yes | 210692962 | FRANKLIN | GSZV903610A* | CHPF3743C6B*+TXV | G*VC960603BNB* | 21,600 | $2,592 |
| Yes | 210692961 | FRANKLIN | GSZV903610A* | CHPF3743C6B*+TXV | G*VS960603BUA* | 21,600 | $2,592 |
| Yes | 210692960 | FRANKLIN | GSZV903610A* | CHPF3743C6B*+TXV | G*VC960403BNB* | 21,600 | $2,592 |
| Yes | 210692953 | FRANKLIN | GSZV903610A* | CHPF3743C6B*+MBVC1601**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210692952 | FRANKLIN | GSZV903610A* | CHPF3743C6B*+MBVC1201**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210692951 | FRANKLIN | GSZV903610A* | CHPF3642C6C*+TXV | G*VM971005CNB* | 21,600 | $2,592 |
| Yes | 210692950 | FRANKLIN | GSZV903610A* | CHPF3642C6C*+TXV | G*VM970804CNB* | 21,600 | $2,592 |
| Yes | 210692949 | FRANKLIN | GSZV903610A* | CHPF3642C6C*+TXV | G*VM970803BNB* | 21,600 | $2,592 |
| Yes | 210692948 | FRANKLIN | GSZV903610A* | CHPF3642C6C*+TXV | G*VM970603BNB* | 21,600 | $2,592 |
| Yes | 210692947 | FRANKLIN | GSZV903610A* | CHPF3642C6C*+TXV | G*VC961005CNB* | 21,600 | $2,592 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 210692946 | FRANKLIN | GSZV903610A* | CHPF3642C6C*+TXV | G*VS960805CUA* | 21,600 | $2,592 |
| Yes | 210692945 | FRANKLIN | GSZV903610A* | CHPF3642C6C*+TXV | G*VC960804CNB* | 21,600 | $2,592 |
| Yes | 210692944 | FRANKLIN | GSZV903610A* | CHPF3642C6C*+TXV | G*VC960803BNB* | 21,600 | $2,592 |
| Yes | 210692943 | FRANKLIN | GSZV903610A* | CHPF3642C6C*+TXV | G*VC960603BNB* | 21,600 | $2,592 |
| Yes | 210692942 | FRANKLIN | GSZV903610A* | CHPF3642C6C*+TXV | G*VS960603BUA* | 21,600 | $2,592 |
| Yes | 210692941 | FRANKLIN | GSZV903610A* | CHPF3642C6C*+TXV | G*VC960403BNB* | 21,600 | $2,592 |
| Yes | 210692934 | FRANKLIN | GSZV903610A* | CHPF3642C6C*+MBVC1601**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210692933 | FRANKLIN | GSZV903610A* | CHPF3642C6C*+MBVC1201**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210692932 | FRANKLIN | GSZV903610A* | CA*F3743*6D*+TXV | G*VM971205DNB* | 21,600 | $2,592 |
| Yes | 210692931 | FRANKLIN | GSZV903610A* | CA*F3743*6D*+TXV | G*VM971005CNB* | 21,600 | $2,592 |
| Yes | 210692930 | FRANKLIN | GSZV903610A* | CA*F3743*6D*+TXV | G*VM970804CNB* | 21,600 | $2,592 |
| Yes | 210692929 | FRANKLIN | GSZV903610A* | CA*F3743*6D*+TXV | G*VM970803BNB* | 21,600 | $2,592 |
| Yes | 210692928 | FRANKLIN | GSZV903610A* | CA*F3743*6D*+TXV | G*VM970603BNB* | 21,600 | $2,592 |
| Yes | 210692927 | FRANKLIN | GSZV903610A* | CA*F3743*6D*+TXV | G*VC961205DNB* | 21,600 | $2,592 |
| Yes | 210692926 | FRANKLIN | GSZV903610A* | CA*F3743*6D*+TXV | G*VC961005CNB* | 21,600 | $2,592 |
| Yes | 210692925 | FRANKLIN | GSZV903610A* | CA*F3743*6D*+TXV | G*VS960805CUA* | 21,600 | $2,592 |
| Yes | 210692924 | FRANKLIN | GSZV903610A* | CA*F3743*6D*+TXV | G*VC960804CNB* | 21,600 | $2,592 |
| Yes | 210692923 | FRANKLIN | GSZV903610A* | CA*F3743*6D*+TXV | G*VC960803BNB* | 21,600 | $2,592 |
| Yes | 210692922 | FRANKLIN | GSZV903610A* | CA*F3743*6D*+TXV | G*VC960603BNB* | 21,600 | $2,592 |
| Yes | 210692921 | FRANKLIN | GSZV903610A* | CA*F3743*6D*+TXV | G*VS960603BUA* | 21,600 | $2,592 |
| Yes | 210692920 | FRANKLIN | GSZV903610A* | CA*F3743*6D*+TXV | G*VC960403BNB* | 21,600 | $2,592 |
| Yes | 210607413 | FRANKLIN | GSZV903610A* | CA*F3743*6D*+MBVC1601**-1A*+TX | | 21,600 | $2,592 |
| Yes | 210692913 | FRANKLIN | GSZV903610A* | CA*F3743*6D*+MBVC1201**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210692912 | FRANKLIN | GSZV903610A* | CA*F3137*6A*+TXV | G*VM970803BNB* | 21,600 | $2,592 |
| Yes | 210692911 | FRANKLIN | GSZV903610A* | CA*F3137*6A*+TXV | G*VM970603BNB* | 21,600 | $2,592 |
| Yes | 210692910 | FRANKLIN | GSZV903610A* | CA*F3137*6A*+TXV | G*VC960803BNB* | 21,600 | $2,592 |
| Yes | 210692909 | FRANKLIN | GSZV903610A* | CA*F3137*6A*+TXV | G*VC960603BNB* | 21,600 | $2,592 |
| Yes | 210692908 | FRANKLIN | GSZV903610A* | CA*F3137*6A*+TXV | G*VS960603BUA* | 21,600 | $2,592 |
| Yes | 210692907 | FRANKLIN | GSZV903610A* | CA*F3137*6A*+TXV | G*VC960403BNB* | 21,600 | $2,592 |
| Yes | 210692904 | FRANKLIN | GSZV903610A* | CA*F3137*6A*+MBVC1201**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210609971 | FRANKLIN | GSZV903610A* | AMVE48DP1400A* | | 21,600 | $2,592 |
| Yes | 210609970 | FRANKLIN | GSZV903610A* | AMVE36CP1400A* | | 21,600 | $2,592 |
| Yes | 206764068 | FRANKLIN | MST183E23MHAA | Heat pump without ducts | | 15,000 | $1,800 |
| Yes | 206764069 | FRANKLIN | MST183E23MHAA | Heat pump with ducts | | 16,000 | $1,920 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 206900430 | FRANKLIN | MSH243E23MCAA | MST243E21ADAA | | 21,000 | $2,520 |
| Yes | 206900429 | FRANKLIN | MSH183E23MCAA | MST183E21ADAA | | 15,000 | $1,800 |
| Yes | 206764065 | FRANKLIN | MSH243E23MCAA | MSH243E23AXAA | | 19,400 | $2,328 |
| Yes | 206764071 | FRANKLIN | MST303E23MHAA | Heat pump without ducts | | 18,000 | $2,160 |
| Yes | 211207000 | FRASER-JOHNSTON | HL20B4821 | XAMC48HE3N1+CC | TPLC100C16MP13 | 41,500 | $4,980 |
| Yes | 211206995 | FRASER-JOHNSTON | HL20B4821 | XAMC48HE3N1+CC | TPLC080C16MP13 | 41,500 | $4,980 |
| Yes | 211206990 | FRASER-JOHNSTON | HL20B4821 | XAMC48HE3N1+CC | TMLV100C16MP12 | 41,500 | $4,980 |
| Yes | 211206985 | FRASER-JOHNSTON | HL20B4821 | XAMC48HE3N1+CC | TM8V080C16MP12 | 41,500 | $4,980 |
| Yes | 211206980 | FRASER-JOHNSTON | HL20B4821 | XAMC48HE3N1+CC | TM8V100C16MP12 | 41,500 | $4,980 |
| Yes | 211206972 | FRASER-JOHNSTON | HL20B4821 | XAMC48HE3N1+CC | TPLC120C20MP13 | 41,500 | $4,980 |
| Yes | 211206967 | FRASER-JOHNSTON | HL20B4821 | XAMC48HE3N1+CC | TPLC100C20MP13 | 41,500 | $4,980 |
| Yes | 211206962 | FRASER-JOHNSTON | HL20B4821 | XAMC48HE3N1+CC | TMLV120C20MP12 | 41,500 | $4,980 |
| Yes | 211206957 | FRASER-JOHNSTON | HL20B4821 | XAMC48HE3N1+CC | TM8V100C20MP12 | 41,500 | $4,980 |
| Yes | 211206952 | FRASER-JOHNSTON | HL20B4821 | XAMC48HE3N1+CC | TM8V120C20MP12 | 41,500 | $4,980 |
| Yes | 211206945 | FRASER-JOHNSTON | HL20B4821 | XAMC48HE3N1+CC | TP9C080C16MP13 | 41,500 | $4,980 |
| Yes | 211206940 | FRASER-JOHNSTON | HL20B4821 | XAMC48HE3N1+CC | TM9V080C16MP12 | 41,500 | $4,980 |
| Yes | 211206933 | FRASER-JOHNSTON | HL20B4821 | XAMC48HE3N1+CC | TP9C100C16MP13 | 41,500 | $4,980 |
| Yes | 211206928 | FRASER-JOHNSTON | HL20B4821 | XAMC48HE3N1+CC | TM9V100C16MP12 | 41,500 | $4,980 |
| Yes | 211206921 | FRASER-JOHNSTON | HL20B4821 | XAMC48HE3N1+CC | TP9C100C20MP13 | 41,500 | $4,980 |
| Yes | 211206916 | FRASER-JOHNSTON | HL20B4821 | XAMC48HE3N1+CC | TM9V100C20MP12 | 41,500 | $4,980 |
| Yes | 211206909 | FRASER-JOHNSTON | HL20B6021 | XAMC60HE4N1+CC | TP9C100C20MP13 | 47,000 | $5,640 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 211206904 | FRASER-JOHNSTON | HL20B6021 | XAMC60HE4N1+CC | TM9V100C20MP12 | 47,000 | $5,640 |
| Yes | 211206851 | FRASER-JOHNSTON | HL20B2421 | XAMB24DE1N1+CC | TPLC080B12MP13 | 23,000 | $2,760 |
| Yes | 211206846 | FRASER-JOHNSTON | HL20B2421 | XAMB24DE1N1+CC | TM8V080B12MP12 | 23,000 | $2,760 |
| Yes | 211206839 | FRASER-JOHNSTON | HL20B2421 | XAMB24DE1N1+CC | TP9C060B12MP13 | 23,200 | $2,784 |
| Yes | 211206834 | FRASER-JOHNSTON | HL20B2421 | XAMB24DE1N1+CC | TM9V060B12MP12 | 23,200 | $2,784 |
| Yes | 211010187 | FRASER-JOHNSTON | HL20B6021 | JHVVD60HE4C2N1+CC | | 46,500 | $5,580 |
| Yes | 10309048 | FRASER-JOHNSTON | HL20B2421 | CM25BE1A1+MVC12BN21 | | 22,400 | $2,688 |
| Yes | 10309104 | FRASER-JOHNSTON | HL20B4821 | AVV50DE321 | | 44,000 | $5,280 |
| Yes | 10309096 | FRASER-JOHNSTON | HL20B3621 | CM38CE2A1+MVC16CN21 | | 33,400 | $4,008 |
| Yes | 10309108 | FRASER-JOHNSTON | HL20B4821 | CM50DE3A1+MVC20DN21 | | 42,500 | $5,100 |
| Yes | 10309112 | FRASER-JOHNSTON | HL20B4821 | CM50CE3A1+MVC16CN21 | | 43,500 | $5,220 |
| Yes | 10525639 | FRASER-JOHNSTON | HL20B3621 | CM38CE2A1 | TMLV100C16MP12 | 33,400 | $4,008 |
| Yes | 10525637 | FRASER-JOHNSTON | HL20B3621 | CM38CE2A1 | TM9V100C16MP12 | 31,600 | $3,792 |
| Yes | 10525640 | FRASER-JOHNSTON | HL20B3621 | CM38CE2A1 | TP9C080C16MP13 | 31,800 | $3,816 |
| Yes | 10525641 | FRASER-JOHNSTON | HL20B3621 | CM38CE2A1 | TP9C100C16MP13 | 31,600 | $3,792 |
| Yes | 10525643 | FRASER-JOHNSTON | HL20B3621 | CM38CE2A1 | TPLC100C16MP13 | 33,400 | $4,008 |
| Yes | 10525642 | FRASER-JOHNSTON | HL20B3621 | CM38CE2A1 | TPLC080C16MP13 | 33,400 | $4,008 |
| Yes | 10525646 | FRASER-JOHNSTON | HL20B4821 | CM50CE3A1 | TM8V100C16MP12 | 44,000 | $5,280 |
| Yes | 10525645 | FRASER-JOHNSTON | HL20B4821 | CM50CE3A1 | TM8V080C16MP12 | 44,000 | $5,280 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 10525648 | FRASER-JOHNSTON | HL20B4821 | CM50CE3A1 | TM8V120C20MP12 | 44,000 | $5,280 |
| Yes | 10525651 | FRASER-JOHNSTON | HL20B4821 | CM50CE3A1 | TM9V100C20MP12 | 44,000 | $5,280 |
| Yes | 10525647 | FRASER-JOHNSTON | HL20B4821 | CM50CE3A1 | TM8V100C20MP12 | 44,000 | $5,280 |
| Yes | 10525652 | FRASER-JOHNSTON | HL20B4821 | CM50CE3A1 | TMLV080C16MP12 | 44,000 | $5,280 |
| Yes | 10525653 | FRASER-JOHNSTON | HL20B4821 | CM50CE3A1 | TMLV100C16MP12 | 44,000 | $5,280 |
| Yes | 10525654 | FRASER-JOHNSTON | HL20B4821 | CM50CE3A1 | TMLV100C20MP12 | 44,000 | $5,280 |
| Yes | 10525655 | FRASER-JOHNSTON | HL20B4821S | CM50CE3A1 | TMLV120C20MP12 | 44,000 | $5,280 |
| Yes | 10525660 | FRASER-JOHNSTON | HL20B4821 | CM50CE3A1 | TPLC100C16MP13 | 44,000 | $5,280 |
| Yes | 10525658 | FRASER-JOHNSTON | HL20B4821 | CM50CE3A1 | TP9C100C20MP13 | 44,000 | $5,280 |
| Yes | 10525659 | FRASER-JOHNSTON | HL20B4821 | CM50CE3A1 | TPLC080C16MP13 | 44,000 | $5,280 |
| Yes | 10525662 | FRASER-JOHNSTON | HL20B4821 | CM50CE3A1 | TPLC120C20MP13 | 44,000 | $5,280 |
| Yes | 10525663 | FRASER-JOHNSTON | HL20B4821 | CM50DE3A1 | TM9V120D20MP12 | 44,000 | $5,280 |
| Yes | 10525661 | FRASER-JOHNSTON | HL20B4821 | CM50CE3A1 | TPLC100C20MP13 | 44,000 | $5,280 |
| Yes | 201982917 | FRASER-JOHNSTON | HL20B3621 | AVV38CE221 | | 33,400 | $4,008 |
| Yes | 10525634 | FRASER-JOHNSTON | HL20B3621 | CM38CE2A1 | TM8V080C16MP12 | 33,400 | $4,008 |
| Yes | 10525635 | FRASER-JOHNSTON | HL20B3621 | CM38CE2A1 | TM8V100C16MP12 | 33,400 | $4,008 |
| Yes | 10525638 | FRASER-JOHNSTON | HL20B3621 | CM38CE2A1 | TMLV080C16MP12 | 33,400 | $4,008 |
| Yes | 10525636 | FRASER-JOHNSTON | HL20B3621 | CM38CE2A1 | TM9V080C16MP12 | 31,800 | $3,816 |
| Yes | 10525644 | FRASER-JOHNSTON | HL20B4821 | AVV50CE321 | | 43,500 | $5,220 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 10525664 | FRASER-JOHNSTON | HL20B4821 | CM50DE3A1 | TP9C120D20MP13 | 44,000 | $5,280 |
| Yes | 206319900 | FRIEDRICH | VRP24K******-* | VRP24K******-* | | 13,000 | $1,560 |
| Yes | 206319902 | FRIEDRICH | VRP24R******-* | VRP24R******-* | | 13,000 | $1,560 |
| Yes | 205123805 | FRIEDRICH | FPHFR24A3A | FPHFC24A3B | | 19,600 | $2,352 |
| Yes | 8912454 | FUJITSU | AOU30RLXEH | ASU30RLE | | 18,900 | $2,268 |
| Yes | 202208444 | FUJITSU | AOU24RGLX | AUU24RGLX | | 16,400 | $1,968 |
| Yes | 202534923 | FUJITSU | AOU18RGLX | ARU18RGLX | | 12,700 | $1,524 |
| Yes | 8033586 | FUJITSU | AOU24RLXFZH | Heat pump without ducts | | 15,400 | $1,848 |
| Yes | 8063924 | FUJITSU | AOU18RLXFZH | Combination heat pumps with or without ducts | | 14,200 | $1,704 |
| Yes | 8063925 | FUJITSU | AOU24RLXFZH | Combination heat pumps with or without ducts | | 15,400 | $1,848 |
| Yes | 8033742 | FUJITSU | AOU24RLXFZH | Heat pump with ducts | | 15,400 | $1,848 |
| Yes | 8033585 | FUJITSU | AOU18RLXFZH | Heat pump with ducts | | 14,200 | $1,704 |
| Yes | 5839958 | FUJITSU | AOU18RLFC | AUU18RLF | | 13,600 | $1,632 |
| Yes | 9962520 | FUJITSU | AOU48RLAVS | Heat pump without ducts | | 33,400 | $4,008 |
| Yes | 9962519 | FUJITSU | AOU48RLAVS | Heat pump with ducts | | 34,600 | $4,152 |
| Yes | 9962521 | FUJITSU | AOU48RLAVS | Combination heat pumps with or without ducts | | 34,000 | $4,080 |
| Yes | 8693477 | FUJITSU | AOU48RLAVM | Heat pump without ducts | | 33,000 | $3,960 |
| Yes | 207657376 | FUJITSU | AOUH30LUAH1 | AMUG30LMAS | | 21,600 | $2,592 |
| Yes | 207657377 | FUJITSU | AOUH36LMAH1 | AMUG36LMAS | | 25,600 | $3,072 |
| Yes | 206347281 | FUJITSU | AOU36RLAVS4 | Heat pump without ducts | | 26,600 | $3,192 |
| Yes | 206347277 | FUJITSU | AOU36RLAVM4 | Heat pump without ducts | | 25,800 | $3,096 |
| Yes | 206347275 | FUJITSU | AOU48RLAVM4 | Heat pump without ducts | | 33,000 | $3,960 |
| Yes | 206347273 | FUJITSU | AOU60RLAVM4 | Heat pump without ducts | | 41,500 | $4,980 |
| Yes | 9962523 | FUJITSU | AOU36RLAVS | Heat pump without ducts | | 26,600 | $3,192 |
| Yes | 8908615 | FUJITSU | AOU36RLXFZH | Heat pump without ducts | | 21,400 | $2,568 |
| Yes | 8693480 | FUJITSU | AOU36RLAVM | Heat pump without ducts | | 25,800 | $3,096 |
| Yes | 8693474 | FUJITSU | AOU60RLAVM | Heat pump without ducts | | 41,500 | $4,980 |
| Yes | 8033584 | FUJITSU | AOU18RLXFZH | Heat pump without ducts | | 14,200 | $1,704 |
| Yes | 207657378 | FUJITSU | AOUH48LMAH1 | AMUG48LMAS | | 34,400 | $4,128 |
| Yes | 206347276 | FUJITSU | AOU36RLAVM4 | Heat pump with ducts | | 26,400 | $3,168 |
| Yes | 206347272 | FUJITSU | AOU60RLAVM4 | Heat pump with ducts | | 41,500 | $4,980 |
| Yes | 206347274 | FUJITSU | AOU48RLAVM4 | Heat pump with ducts | | 34,000 | $4,080 |
| Yes | 206347300 | FUJITSU | AOU48RLAVM4 | Combination heat pumps with or without ducts | | 33,400 | $4,008 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 206347301 | FUJITSU | AOU36RLAVM4 | Combination heat pumps with or without ducts | | 26,000 | $3,120 |
| Yes | 206347299 | FUJITSU | AOU60RLAVM4 | Combination heat pumps with or without ducts | | 41,500 | $4,980 |
| Yes | 206347280 | FUJITSU | AOU36RLAVS4 | Heat pump with ducts | | 26,000 | $3,120 |
| Yes | 206347303 | FUJITSU | AOU36RLAVS4 | Combination heat pumps with or without ducts | | 26,200 | $3,144 |
| Yes | 206913027 | FUJITSU | AOUH18LMAS1 | ASUH18LMAS | | 13,600 | $1,632 |
| Yes | 207590837 | FUJITSU | AOUH36LPAS1 | ASUH36LPAS | | 22,400 | $2,688 |
| Yes | 207590836 | FUJITSU | AOUH30LPAS1 | ASUH30LPAS | | 19,400 | $2,328 |
| Yes | 206579745 | FUJITSU | AOUH18LUAS1 | ACUH18LUAS1 | | 14,400 | $1,728 |
| Yes | 8693478 | FUJITSU | AOU48RLAVM | Combination heat pumps with or without ducts | | 33,400 | $4,008 |
| Yes | 8693479 | FUJITSU | AOU36RLAVM | Heat pump with ducts | | 26,400 | $3,168 |
| Yes | 8693481 | FUJITSU | AOU36RLAVM | Combination heat pumps with or without ducts | | 26,000 | $3,120 |
| Yes | 8693476 | FUJITSU | AOU48RLAVM | Heat pump with ducts | | 34,000 | $4,080 |
| Yes | 9962524 | FUJITSU | AOU36RLAVS | Combination heat pumps with or without ducts | | 26,200 | $3,144 |
| Yes | 9962522 | FUJITSU | AOU36RLAVS | Heat pump with ducts | | 26,000 | $3,120 |
| Yes | 8693473 | FUJITSU | AOU60RLAVM | Heat pump with ducts | | 41,500 | $4,980 |
| Yes | 8693475 | FUJITSU | AOU60RLAVM | Combination heat pumps with or without ducts | | 41,500 | $4,980 |
| Yes | 7940753 | FUJITSU | AOU24RLB | ASU24RLB | | 15,300 | $1,836 |
| Yes | 8908616 | FUJITSU | AOU36RLXFZH | Heat pump with ducts | | 21,400 | $2,568 |
| Yes | 8912450 | FUJITSU | AOU36RLXFZH | Combination heat pumps with or without ducts | | 21,400 | $2,568 |
| Yes | 5839957 | FUJITSU | AOU18RLFC | ARU18RLF | | 13,600 | $1,632 |
| Yes | 202537550 | FUJITSU | AOU42RGLX | ARU42RGLX | | 29,600 | $3,552 |
| Yes | 202537548 | FUJITSU | AOU30RGLX | ARU30RGLX | | 19,600 | $2,352 |
| Yes | 8718495 | FUJITSU | AOU18RLXFW1 | ASU18RLF | | 14,600 | $1,752 |
| Yes | 8779045 | FUJITSU | AOU18RLXFWH | ASU18RLF | | 14,600 | $1,752 |
| Yes | 202195637 | FUJITSU | AOU36RGLX | AUU36RGLX | | 23,200 | $2,784 |
| Yes | 202195636 | FUJITSU | AOU30RGLX | AUU30RGLX | | 20,200 | $2,424 |
| Yes | 202195106 | FUJITSU | AOU18RGLX | AUU18RGLX | | 12,300 | $1,476 |
| Yes | 207590959 | GE APPLIANCES | AUH4860ZGDA* | TUY60ZPDA | | 36,000 | $4,320 |
| Yes | 207590958 | GE APPLIANCES | AUH4860ZGDA* | TUY48ZPDA | | 31,400 | $3,768 |
| Yes | 207590957 | GE APPLIANCES | AUH2436ZGDA* | TUY36ZPDA | | 24,000 | $2,880 |
| Yes | 207590956 | GE APPLIANCES | AUH2436ZGDA* | TUY24ZPDA | | 16,000 | $1,920 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 211744610 | GE Appliances | ASH3036UCDD** | USYL30UCDD** | | 22,000 | $2,640 |
| Yes | 211744609 | GE Appliances | ASH124UCDD** | ASYW24TRDF** | | 17,000 | $2,040 |
| Yes | 210154196 | GE APPLIANCES | ASH436NCDD** | Heat pump without ducts | | 23,600 | $2,832 |
| Yes | 210154194 | GE APPLIANCES | ASH324NCDD** | Heat pump with ducts | | 17,400 | $2,088 |
| Yes | 210154192 | GE APPLIANCES | ASH324NCDD** | Heat pump without ducts | | 17,000 | $2,040 |
| Yes | 210154190 | GE APPLIANCES | ASH220NCDD** | Heat pump with ducts | | 14,800 | $1,776 |
| Yes | 210154187 | GE APPLIANCES | ASH220NCDD** | Heat pump without ducts | | 14,000 | $1,680 |
| Yes | 206799411 | GE Appliances | AUH2436ZGDA* | UUY36ZGDAB* | | 24,000 | $2,880 |
| Yes | 206799410 | GE Appliances | AUH2436ZGDA* | UUY24ZGDAB* | | 16,000 | $1,920 |
| Yes | 206753163 | GE Appliances | AUH4860ZGDA* | UUY48ZGDAB* | | 31,400 | $3,768 |
| Yes | 206753162 | GE Appliances | AUH4860ZGDA* | UUY60ZGDAB* | | 36,000 | $4,320 |
| Yes | 203862746 | GE APPLIANCES | ASH324NCDWA | Heat pump without ducts | | 16,000 | $1,920 |
| Yes | 204035456 | GE APPLIANCES | ASH220NCDWA | Heat pump with ducts | | 14,000 | $1,680 |
| Yes | 206842137 | GE APPLIANCES | ASH118URDSE* | USYM18UCDSA* | | 15,000 | $1,800 |
| Yes | 204878533 | GE APPLIANCES | ASH436NCDW** | Heat pump without ducts | | 22,000 | $2,640 |
| Yes | 203862745 | GE APPLIANCES | ASH220NCDWA | Heat pump without ducts | | 14,000 | $1,680 |
| Yes | 206842134 | GE APPLIANCES | ASH118URDSE* | ASYW18URDWD* | | 15,300 | $1,836 |
| Yes | 205756419 | GE APPLIANCES | AUH2436ZGDA* | UUY36ZGDA** | | 24,400 | $2,928 |
| Yes | 205977487 | GE APPLIANCES | AUH4860ZGDA* | UUY60ZGDA** | | 37,200 | $4,464 |
| Yes | 205977486 | GE APPLIANCES | AUH4860ZGDA* | UUY48ZGDA** | | 32,800 | $3,936 |
| Yes | 205756418 | GE APPLIANCES | AUH2436ZGDA* | UUY24ZGDA** | | 16,300 | $1,956 |
| Yes | 205291990 | GE APPLIANCES | ASH118URDSD* | ASYW18URDWD* | | 15,300 | $1,836 |
| Yes | 210692787 | GOODMAN | GSZV903610A* | CSCF3642N6D*+TXV | G*VM971205DNB* | 21,600 | $2,592 |
| Yes | 210692786 | GOODMAN | GSZV903610A* | CSCF3642N6D*+TXV | G*VM971005CNB* | 21,600 | $2,592 |
| Yes | 210692785 | GOODMAN | GSZV903610A* | CSCF3642N6D*+TXV | G*VM970804CNB* | 21,600 | $2,592 |
| Yes | 210692784 | GOODMAN | GSZV903610A* | CSCF3642N6D*+TXV | G*VM970803BNB* | 21,600 | $2,592 |
| Yes | 210692783 | GOODMAN | GSZV903610A* | CSCF3642N6D*+TXV | G*VM970603BNB* | 21,600 | $2,592 |
| Yes | 210692782 | GOODMAN | GSZV903610A* | CSCF3642N6D*+TXV | G*VC961205DNB* | 21,600 | $2,592 |
| Yes | 210692781 | GOODMAN | GSZV903610A* | CSCF3642N6D*+TXV | G*VC961005CNB* | 21,600 | $2,592 |
| Yes | 210692780 | GOODMAN | GSZV903610A* | CSCF3642N6D*+TXV | G*VS960805CUA* | 21,600 | $2,592 |
| Yes | 210692779 | GOODMAN | GSZV903610A* | CSCF3642N6D*+TXV | G*VC960804CNB* | 21,600 | $2,592 |
| Yes | 210692778 | GOODMAN | GSZV903610A* | CSCF3642N6D*+TXV | G*VC960803BNB* | 21,600 | $2,592 |
| Yes | 210692777 | GOODMAN | GSZV903610A* | CSCF3642N6D*+TXV | G*VC960603BNB* | 21,600 | $2,592 |
| Yes | 210692776 | GOODMAN | GSZV903610A* | CSCF3642N6D*+TXV | G*VS960603BUA* | 21,600 | $2,592 |
| Yes | 210692775 | GOODMAN | GSZV903610A* | CSCF3642N6D*+TXV | G*VC960403BNB* | 21,600 | $2,592 |
| Yes | 210692768 | GOODMAN | GSZV903610A* | CSCF3642N6D*+MBVC1601**-1A*+TXV | | 21,600 | $2,592 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 210692767 | GOODMAN | GSZV903610A* | CSCF3642N6D*+MBVC1201**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210692766 | GOODMAN | GSZV903610A* | CHPF3743C6B*+TXV | G*VM971005CNB* | 21,600 | $2,592 |
| Yes | 210692765 | GOODMAN | GSZV903610A* | CHPF3743C6B*+TXV | G*VM970804CNB* | 21,600 | $2,592 |
| Yes | 210692764 | GOODMAN | GSZV903610A* | CHPF3743C6B*+TXV | G*VM970803BNB* | 21,600 | $2,592 |
| Yes | 210692763 | GOODMAN | GSZV903610A* | CHPF3743C6B*+TXV | G*VM970603BNB* | 21,600 | $2,592 |
| Yes | 210692762 | GOODMAN | GSZV903610A* | CHPF3743C6B*+TXV | G*VC961005CNB* | 21,600 | $2,592 |
| Yes | 210692761 | GOODMAN | GSZV903610A* | CHPF3743C6B*+TXV | G*VS960805CUA* | 21,600 | $2,592 |
| Yes | 210692760 | GOODMAN | GSZV903610A* | CHPF3743C6B*+TXV | G*VC960804CNB* | 21,600 | $2,592 |
| Yes | 210692759 | GOODMAN | GSZV903610A* | CHPF3743C6B*+TXV | G*VC960803BNB* | 21,600 | $2,592 |
| Yes | 210692758 | GOODMAN | GSZV903610A* | CHPF3743C6B*+TXV | G*VC960603BNB* | 21,600 | $2,592 |
| Yes | 210692757 | GOODMAN | GSZV903610A* | CHPF3743C6B*+TXV | G*VS960603BUA* | 21,600 | $2,592 |
| Yes | 210692756 | GOODMAN | GSZV903610A* | CHPF3743C6B*+TXV | G*VC960403BNB* | 21,600 | $2,592 |
| Yes | 210692749 | GOODMAN | GSZV903610A* | CHPF3743C6B*+MBVC1601**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210692748 | GOODMAN | GSZV903610A* | CHPF3743C6B*+MBVC1201**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210692747 | GOODMAN | GSZV903610A* | CHPF3642C6C*+TXV | G*VM971005CNB* | 21,600 | $2,592 |
| Yes | 210692746 | GOODMAN | GSZV903610A* | CHPF3642C6C*+TXV | G*VM970804CNB* | 21,600 | $2,592 |
| Yes | 210692745 | GOODMAN | GSZV903610A* | CHPF3642C6C*+TXV | G*VM970803BNB* | 21,600 | $2,592 |
| Yes | 210692744 | GOODMAN | GSZV903610A* | CHPF3642C6C*+TXV | G*VM970603BNB* | 21,600 | $2,592 |
| Yes | 210692743 | GOODMAN | GSZV903610A* | CHPF3642C6C*+TXV | G*VC961005CNB* | 21,600 | $2,592 |
| Yes | 210692742 | GOODMAN | GSZV903610A* | CHPF3642C6C*+TXV | G*VS960805CUA* | 21,600 | $2,592 |
| Yes | 210692741 | GOODMAN | GSZV903610A* | CHPF3642C6C*+TXV | G*VC960804CNB* | 21,600 | $2,592 |
| Yes | 210692740 | GOODMAN | GSZV903610A* | CHPF3642C6C*+TXV | G*VC960803BNB* | 21,600 | $2,592 |
| Yes | 210692739 | GOODMAN | GSZV903610A* | CHPF3642C6C*+TXV | G*VC960603BNB* | 21,600 | $2,592 |
| Yes | 210692738 | GOODMAN | GSZV903610A* | CHPF3642C6C*+TXV | G*VS960603BUA* | 21,600 | $2,592 |
| Yes | 210692737 | GOODMAN | GSZV903610A* | CHPF3642C6C*+TXV | G*VC960403BNB* | 21,600 | $2,592 |
| Yes | 210692730 | GOODMAN | GSZV903610A* | CHPF3642C6C*+MBVC1601**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210692729 | GOODMAN | GSZV903610A* | CHPF3642C6C*+MBVC1201**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210692728 | GOODMAN | GSZV903610A* | CA*F3743*6D*+TXV | G*VM971205DNB* | 21,600 | $2,592 |
| Yes | 210692727 | GOODMAN | GSZV903610A* | CA*F3743*6D*+TXV | G*VM971005CNB* | 21,600 | $2,592 |
| Yes | 210692726 | GOODMAN | GSZV903610A* | CA*F3743*6D*+TXV | G*VM970804CNB* | 21,600 | $2,592 |
| Yes | 210692725 | GOODMAN | GSZV903610A* | CA*F3743*6D*+TXV | G*VM970803BNB* | 21,600 | $2,592 |
| Yes | 210692724 | GOODMAN | GSZV903610A* | CA*F3743*6D*+TXV | G*VM970603BNB* | 21,600 | $2,592 |
| Yes | 210692723 | GOODMAN | GSZV903610A* | CA*F3743*6D*+TXV | G*VC961205DNB* | 21,600 | $2,592 |
| Yes | 210692722 | GOODMAN | GSZV903610A* | CA*F3743*6D*+TXV | G*VC961005CNB* | 21,600 | $2,592 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 210692721 | GOODMAN | GSZV903610A* | CA*F3743*6D*+TXV | G*VS960805CUA* | 21,600 | $2,592 |
| Yes | 210692720 | GOODMAN | GSZV903610A* | CA*F3743*6D*+TXV | G*VC960804CNB* | 21,600 | $2,592 |
| Yes | 210692719 | GOODMAN | GSZV903610A* | CA*F3743*6D*+TXV | G*VC960803BNB* | 21,600 | $2,592 |
| Yes | 210692718 | GOODMAN | GSZV903610A* | CA*F3743*6D*+TXV | G*VC960603BNB* | 21,600 | $2,592 |
| Yes | 210692717 | GOODMAN | GSZV903610A* | CA*F3743*6D*+TXV | G*VS960603BUA* | 21,600 | $2,592 |
| Yes | 210692716 | GOODMAN | GSZV903610A* | CA*F3743*6D*+TXV | G*VC960403BNB* | 21,600 | $2,592 |
| Yes | 210607412 | GOODMAN | GSZV903610A* | CA*F3743*6D*+MBVC1601**-1A*+TX | | 21,600 | $2,592 |
| Yes | 210692709 | GOODMAN | GSZV903610A* | CA*F3743*6D*+MBVC1201**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210692708 | GOODMAN | GSZV903610A* | CA*F3137*6A*+TXV | G*VM970803BNB* | 21,600 | $2,592 |
| Yes | 210692707 | GOODMAN | GSZV903610A* | CA*F3137*6A*+TXV | G*VM970603BNB* | 21,600 | $2,592 |
| Yes | 210692706 | GOODMAN | GSZV903610A* | CA*F3137*6A*+TXV | G*VC960803BNB* | 21,600 | $2,592 |
| Yes | 210692705 | GOODMAN | GSZV903610A* | CA*F3137*6A*+TXV | G*VC960603BNB* | 21,600 | $2,592 |
| Yes | 210692704 | GOODMAN | GSZV903610A* | CA*F3137*6A*+TXV | G*VS960603BUA* | 21,600 | $2,592 |
| Yes | 210692703 | GOODMAN | GSZV903610A* | CA*F3137*6A*+TXV | G*VC960403BNB* | 21,600 | $2,592 |
| Yes | 210692700 | GOODMAN | GSZV903610A* | CA*F3137*6A*+MBVC1201**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210609967 | GOODMAN | GSZV903610A* | AMVE48DP1400A* | | 21,600 | $2,592 |
| Yes | 210609966 | GOODMAN | GSZV903610A* | AMVE36CP1400A* | | 21,600 | $2,592 |
| Yes | 206900422 | GOODMAN | MSH243E23MCAA | MST243E21ADAA | | 21,000 | $2,520 |
| Yes | 206900421 | GOODMAN | MSH183E23MCAA | MST183E21ADAA | | 15,000 | $1,800 |
| Yes | 211717297 | GREE | FLEXX36HP230V1AO | FLEXX24C | | 16,800 | $2,016 |
| Yes | 211698448 | GREE | GMV-V36WL/C-T(U) | Heat pump without ducts | | 22,000 | $2,640 |
| Yes | 211698447 | GREE | GMV-V48WL/C-T(U) | Heat pump without ducts | | 30,000 | $3,600 |
| Yes | 211694660 | GREE | GMV-V60WL/C-T(U) | Heat pump without ducts | | 42,000 | $5,040 |
| Yes | 211644150 | GREE | GUD36W/A-D(U) | GCAT24*/NAA | | 16,800 | $2,016 |
| Yes | 208158334 | GREE | GWH24AGEXH-D3DNA1A/O | GFH(24)DB-D3DN***/I | | 14,900 | $1,788 |
| Yes | 211624987 | GREE | FLEXX60HP230V1AO | FLEXX48C | ML296UH090XV48C-* | 28,200 | $3,384 |
| Yes | 211624986 | GREE | FLEXX36HP230V1AO | FLEXX36C | ML296UH070XV36B-* | 22,000 | $2,640 |
| Yes | 211624985 | GREE | FLEXX36HP230V1AO | FLEXX24C | ML296UH070XV36B-* | 15,600 | $1,872 |
| Yes | 211177531 | GREE | GUD60W/A-D(U) | GCAT48*/NAA | ML296UH090XV48C-* | 28,200 | $3,384 |
| Yes | 211177529 | GREE | GUD36W/A-D(U) | GCAT36*/NAA | ML296UH070XV36B-* | 22,000 | $2,640 |
| Yes | 211177528 | GREE | GUD36W/A-D(U) | GCAT24*/NAA | ML296UH070XV36B-* | 15,600 | $1,872 |
| Yes | 210278981 | GREE | MULTI42HP230V1EO | Heat pump without ducts | | 35,600 | $4,272 |
| Yes | 210278979 | GREE | MULTI36HP230V1EO | Heat pump without ducts | | 30,800 | $3,696 |
| Yes | 208786088 | GREE | GWHD(42)ND3MO | Heat pump without ducts | | 35,600 | $4,272 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 208786087 | GREE | GWHD(36)ND3MO | Heat pump without ducts | | 30,800 | $3,696 |
| Yes | 207256443 | GREE | FLEXX60HP230V1AO | FLEXX48HP230V1BH | | 31,400 | $3,768 |
| Yes | 207256442 | GREE | FLEXX60HP230V1AO | FLEXX60HP230V1BH | | 36,000 | $4,320 |
| Yes | 207256441 | GREE | FLEXX36HP230V1AO | FLEXX36HP230V1BH | | 24,000 | $2,880 |
| Yes | 207256440 | GREE | FLEXX36HP230V1AO | FLEXX24HP230V1BH | | 16,000 | $1,920 |
| Yes | 206249119 | GREE | GUD60W/A-D(U) | GUD48AH2/A-D(U) | | 31,400 | $3,768 |
| Yes | 206249118 | GREE | GUD60W/A-D(U) | GUD60AH2/A-D(U) | | 36,000 | $4,320 |
| Yes | 206249117 | GREE | GUD36W/A-D(U) | GUD36AH2/A-D(U) | | 24,000 | $2,880 |
| Yes | 206249116 | GREE | GUD36W/A-D(U) | GUD24AH2/A-D(U) | | 16,000 | $1,920 |
| Yes | 203989086 | GREE | MULTIU24HP230V1DO | Heat pump without ducts | | 17,900 | $2,148 |
| Yes | 203989085 | GREE | MULTIU18HP230V1DO | Heat pump without ducts | | 17,000 | $2,040 |
| Yes | 202557961 | GREE | GWHD(24)ND3JO | Heat pump without ducts | | 17,900 | $2,148 |
| Yes | 202557960 | GREE | GWHD(18)ND3JO | Heat pump without ducts | | 17,000 | $2,040 |
| Yes | 10157571 | GREE | SAP24HP230V1AO | SAP24HP230V1AH | | 15,500 | $1,860 |
| Yes | 10157570 | GREE | SAP18HP230V1AO | SAP18HP230V1AH | | 14,200 | $1,704 |
| Yes | 9102074 | GREE | GWH18YE-D3DNA1A/O | GWH18QE-D3DN***/I | | 14,200 | $1,704 |
| Yes | 9102794 | GREE | GWH24YE-D3DNA1A/O | GWH24QE-D3DN***/I | | 15,500 | $1,860 |
| Yes | 9114294 | GREE | GWH18YE-D3DNA1A/O | GWH18AAE-D3DN***/I | | 14,200 | $1,704 |
| Yes | 9123256 | GREE | GWH24YE-D3DNA1A/O | GWH24AAE-D3DN***/I | | 15,500 | $1,860 |
| Yes | 210485366 | GREE | GWHD(42)ND3NO | Heat pump without ducts | | 35,600 | $4,272 |
| Yes | 210485365 | GREE | GWHD(36)ND3NO | Heat pump without ducts | | 30,800 | $3,696 |
| Yes | 8654211 | GREE | GMV-48WL/B-T(U) | Heat pump without ducts | | 38,000 | $4,560 |
| Yes | 202557965 | GREE | GWHD(18)ND3JO | Heat pump without ducts | | 17,000 | $2,040 |
| Yes | 203991158 | GREE | MULTIU48HP230V1BO | Heat pump without ducts | | 38,000 | $4,560 |
| Yes | 8654212 | GREE | GMV-48WL/B-T(U) | Combination heat pumps with or without ducts | | 38,000 | $4,560 |
| Yes | 8796414 | GREE | GMV-36WL/B-T(U) | Combination heat pumps with or without ducts | | 29,400 | $3,528 |
| Yes | 205984664 | GREE | FLEXX60HP230V1AO | FLEXX60HP230V1AH | | 38,000 | $4,560 |
| Yes | 205984663 | GREE | FLEXX36HP230V1AO | FLEXX36HP230V1AH | | 24,400 | $2,928 |
| Yes | 205993849 | GREE | FLEXX36HP230V1AO | FLEXX24HP230V1AH | | 16,300 | $1,956 |
| Yes | 205993850 | GREE | FLEXX60HP230V1AO | FLEXX48HP230V1AH | | 33,000 | $3,960 |
| Yes | 205724738 | GREE | GUD60W/A-D(U) | GUD60A/A-D(U) | | 37,200 | $4,464 |
| Yes | 205564529 | GREE | GUD36W/A-D(U) | GUD24A/A-D(U) | | 16,300 | $1,956 |
| Yes | 205747610 | GREE | GUD60W/A-D(U) | GUD48A/A-D(U) | | 32,800 | $3,936 |
| Yes | 10384787 | GREE | GWHD(48S)HD3DO | Heat pump without ducts | | 38,000 | $4,560 |
| Yes | 204043222 | GREE | GUD36W/A-D(U) | GUD36A/A-D(U) | | 24,400 | $2,928 |
| Yes | 10392955 | GREE | GWHD(48S)HD3DO | Heat pump with ducts | | 37,000 | $4,440 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 9342251 | GREE | GMV-HY36WLT/A-T(U) | Heat pump without ducts | | 30,000 | $3,600 |
| Yes | 9410050 | GREE | GMV-HY48WLT/A-T(U) | Unités sans conduits | | 35,000 | $4,200 |
| Yes | 8654208 | GREE | GMV-36WL/B-T(U) | Heat pump without ducts | | 29,400 | $3,528 |
| Yes | 9409574 | GREE | GMV-HY36WLT/A-T(U) | Heat pump with ducts | | 41,000 | $4,920 |
| Yes | 8654209 | GREE | GMV-36WL/B-T(U) | Heat pump with ducts | | 29,400 | $3,528 |
| Yes | 7607469 | GREE | GWH18UC-D3DNA4C/O | GWH18UC-D3DN***/I | | 12,717 | $1,526 |
| Yes | 7280525 | GREE | GUHD48ND3FO | GFH48D3FI | | 30,600 | $3,672 |
| Yes | 7280511 | GREE | GUHD42ND3FO | GFH42D3FI | | 24,800 | $2,976 |
| Yes | 8654210 | GREE | GMV-48WL/B-T(U) | Heat pump with ducts | | 38,000 | $4,560 |
| Yes | 9410052 | GREE | GMV-HY48WLT/A-T(U) | Heat pump with ducts | | 35,000 | $4,200 |
| Yes | 211744602 | Haier | 1U3036LP2HD** | USYL30UCDD** | | 22,000 | $2,640 |
| Yes | 211744601 | Haier | 1U24LP2HD** | AW24TL2HF** | | 17,000 | $2,040 |
| Yes | 210151026 | HAIER | 2U20EH2HD** | Heat pump with ducts | | 14,800 | $1,776 |
| Yes | 210082201 | HAIER | 4U36EH2HD** | Heat pump without ducts | | 23,600 | $2,832 |
| Yes | 210082199 | HAIER | 3U24EH2HD** | Heat pump with ducts | | 17,400 | $2,088 |
| Yes | 210082198 | HAIER | 3U24EH2HD** | Heat pump without ducts | | 17,000 | $2,040 |
| Yes | 210082195 | HAIER | 2U20EH2HD** | Heat pump without ducts | | 14,000 | $1,680 |
| Yes | 10225939 | HAIER | 1U48LP2VHA | AM48LP2VH* | | 26,600 | $3,192 |
| Yes | 202449650 | HAIER | 3U24EH2VHA | Heat pump without ducts | | 16,000 | $1,920 |
| Yes | 202449649 | HAIER | 2U20EH2VHA | Heat pump without ducts | | 14,000 | $1,680 |
| Yes | 206445820 | HAIER | 1U18EH2VHE* | AW18EH2VHD* | | 15,300 | $1,836 |
| Yes | 206608651 | HAIER | 1U18EH2VHE* | USYM18UCDSA* | | 15,000 | $1,800 |
| Yes | 205291903 | HAIER | 1U18EH2VHD* | AW18EH2VHD* | | 15,300 | $1,836 |
| Yes | 204878399 | HAIER | 4U36EH2VH** | Heat pump without ducts | | 22,000 | $2,640 |
| Yes | 207036468 | HAXXAIR | HVHD-36E2D2 | HAHD-36E2D2 | | 25,000 | $3,000 |
| Yes | 205726755 | HAXXAIR | HVHD-36E2D | HAHD-36E2D | | 25,000 | $3,000 |
| Yes | 209852072 | HEIL | DLCURAH48ABK | DLFUAAH48XAK | | 36,000 | $4,320 |
| Yes | 209852076 | HEIL | DLCURAH36ABK | DLFUAAH36XAK | | 30,400 | $3,648 |
| Yes | 209852070 | HEIL | DLCURAH24ABK | DLFUAAH24XAK | | 19,200 | $2,304 |
| Yes | 209852069 | HEIL | DLCURAH18ABK | DLFUAAH18XAK | | 13,500 | $1,620 |
| Yes | 207643065 | HEIL | DLCMHBH36DAK | Heat pump without ducts | | 22,000 | $2,640 |
| Yes | 207643062 | HEIL | DLCMHBH48EAK | Heat pump without ducts | | 34,000 | $4,080 |
| Yes | 207643056 | HEIL | DLCMHBH30DAK | Heat pump without ducts | | 18,500 | $2,220 |
| Yes | 207801571 | HEIL | DLCSRBH18AAK | DLFSDAH24XAK | | 12,600 | $1,512 |
| Yes | 207826601 | HEIL | DLCSRBH18AAK | DLFSABH18XBK | | 12,000 | $1,440 |
| Yes | 8177090 | HEIL | DLCAHB12K1A | DLFAHH12K1A | | 13,000 | $1,560 |
| Yes | 207643066 | HEIL | DLCMHBH36DAK | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 207643057 | HEIL | DLCMHBH30DAK | Heat pump with ducts | | 19,000 | $2,280 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 207643063 | HEIL | DLCMHBH48EAK | Heat pump with ducts | | 28,000 | $3,360 |
| Yes | 207643058 | HEIL | DLCMHBH30DAK | Combination heat pumps with or without ducts | | 18,700 | $2,244 |
| Yes | 207643067 | HEIL | DLCMHBH36DAK | Combination heat pumps with or without ducts | | 22,400 | $2,688 |
| Yes | 207643064 | HEIL | DLCMHBH48EAK | Combination heat pumps with or without ducts | | 31,000 | $3,720 |
| Yes | 206350425 | HEIL | DLCSRBH24AAK | DLFSFAH24XAK | | 14,500 | $1,740 |
| Yes | 206350422 | HEIL | DLCSRBH18AAK | DLFSFAH18XAK | | 12,000 | $1,440 |
| Yes | 206350423 | HEIL | DLCSRBH24AAK | DLFSCAH24XAK | | 14,500 | $1,740 |
| Yes | 206188309 | HEIL | DLCSRBH24AAK | DLFSAAH24XAK | | 16,500 | $1,980 |
| Yes | 206350421 | HEIL | DLCSRBH18AAK | DLFSDAH18XAK | | 12,700 | $1,524 |
| Yes | 206350424 | HEIL | DLCSRBH24AAK | DLFSDAH24XAK | | 14,500 | $1,740 |
| Yes | 205921375 | HEIL | DLCSRAH24AAK | DLFSAAH24XAK | | 17,500 | $2,100 |
| Yes | 201835722 | HEIL | DLCSRAH24AAK | DLFSCAH24XAK | | 16,200 | $1,944 |
| Yes | 202463649 | HEIL | DLCPRAH24AAK | DLFPHAH24XAK | | 15,450 | $1,854 |
| Yes | 201835718 | HEIL | DLCSRAH24AAK | DLFSDAH24XAK | | 17,400 | $2,088 |
| Yes | 201835676 | HEIL | DLCSRAH24AAK | DLFSHAH24XAK | | 15,000 | $1,800 |
| Yes | 201835730 | HEIL | DLCLRAH48AAK | DLFLFAH48XAK | | 35,000 | $4,200 |
| Yes | 201835720 | HEIL | DLCSRAH24AAK | DLFSFAH24XAK | | 17,200 | $2,064 |
| Yes | 201835716 | HEIL | DLCSRAH18AAK | DLFSCAH18XAK | | 12,000 | $1,440 |
| Yes | 203383847 | HISENSE | AST-24UW3SDB01 | AST-24UW3SDB**01 | | 14,500 | $1,740 |
| Yes | 204976869 | HISENSE | AUW-24U3SA | ADT-24UX3SLM | | 19,300 | $2,316 |
| Yes | 203994969 | HITACHI | HVAHP036B21S* | HIC4012B21S, HIC4012B21S, HIC4012B21S | | 23,800 | $2,856 |
| Yes | 203994975 | HITACHI | HVAHP036B21S* | HIDM018B21S, HIDM018B21S | | 23,800 | $2,856 |
| Yes | 203995169 | HITACHI | HVAHP036B21S* | NULL | | 23,800 | $2,856 |
| Yes | 206750858 | HITACHI | RAS-3.0PNNBDH1 | RPIM-3.0PNN1DH | | 19,200 | $2,304 |
| Yes | 206750860 | HITACHI | RAS-4.0PNNBDH1 | RPIM-4.0PNN1DH | | 26,000 | $3,120 |
| Yes | 206750859 | HITACHI | RAS-4.0PNNBDH1 | RCI-4.0PNN1DH | | 27,200 | $3,264 |
| Yes | 207200484 | HITACHI | RAC-PH18WHLAE | RAS-PH18PHLAE | | 13,300 | $1,596 |
| Yes | 207200483 | HITACHI | RAC-PH24WHLAE | RAS-PH24PHLAE | | 15,300 | $1,836 |
| Yes | 205261890 | ICP COMMERCIAL | 38VMA036HDS3-1 | Combination heat pumps with or without ducts | | 25,000 | $3,000 |
| Yes | 205261893 | ICP COMMERCIAL | 38VMA048HDS3-1 | Combination heat pumps with or without ducts | | 34,000 | $4,080 |
| Yes | 205261899 | ICP COMMERCIAL | 38VMB036HDS3-1 | Combination heat pumps with or without ducts | | 25,000 | $3,000 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205261902 | ICP COMMERCIAL | 38VMB048HDS3-1 | Combination heat pumps with or without ducts | | 34,000 | $4,080 |
| Yes | 205261892 | ICP COMMERCIAL | 38VMA048HDS3-1 | Heat pump with ducts | | 34,000 | $4,080 |
| Yes | 205261901 | ICP COMMERCIAL | 38VMB048HDS3-1 | Heat pump with ducts | | 34,000 | $4,080 |
| Yes | 205261898 | ICP COMMERCIAL | 38VMB036HDS3-1 | Heat pump with ducts | | 25,000 | $3,000 |
| Yes | 205261889 | ICP COMMERCIAL | 38VMA036HDS3-1 | Heat pump with ducts | | 25,000 | $3,000 |
| Yes | 210365430 | INNOVAIR | MHD-24 | MHD-CC2.0-17.5-M | | 22,000 | $2,640 |
| Yes | 210343159 | INNOVAIR | SHV60H2R20 | DEV60H2R19 | | 42,000 | $5,040 |
| Yes | 210343157 | INNOVAIR | SHV48H2R20 | DEV48H2R19 | | 36,000 | $4,320 |
| Yes | 210343158 | INNOVAIR | SHV24H2R20 | DEV24H2R19 | | 19,200 | $2,304 |
| Yes | 207821957 | INNOVAIR | VOM42H7R5P7 | Heat pump without ducts | | 24,000 | $2,880 |
| Yes | 206330209 | INNOVAIR | EIN18H2V32(O) | EIN18H2V32(I) | | 14,200 | $1,704 |
| Yes | 211207002 | JOHNSON CONTROLS | HL20B4821 | XAMC48HE3N1+CC | TPLC100C16MP13 | 41,500 | $4,980 |
| Yes | 211206997 | JOHNSON CONTROLS | HL20B4821 | XAMC48HE3N1+CC | TPLC080C16MP13 | 41,500 | $4,980 |
| Yes | 211206992 | JOHNSON CONTROLS | HL20B4821 | XAMC48HE3N1+CC | TMLV100C16MP12 | 41,500 | $4,980 |
| Yes | 211206987 | JOHNSON CONTROLS | HL20B4821 | XAMC48HE3N1+CC | TM8V080C16MP12 | 41,500 | $4,980 |
| Yes | 211206982 | JOHNSON CONTROLS | HL20B4821 | XAMC48HE3N1+CC | TM8V100C16MP12 | 41,500 | $4,980 |
| Yes | 211206974 | JOHNSON CONTROLS | HL20B4821 | XAMC48HE3N1+CC | TPLC120C20MP13 | 41,500 | $4,980 |
| Yes | 211206969 | JOHNSON CONTROLS | HL20B4821 | XAMC48HE3N1+CC | TPLC100C20MP13 | 41,500 | $4,980 |
| Yes | 211206964 | JOHNSON CONTROLS | HL20B4821 | XAMC48HE3N1+CC | TMLV120C20MP12 | 41,500 | $4,980 |
| Yes | 211206959 | JOHNSON CONTROLS | HL20B4821 | XAMC48HE3N1+CC | TM8V100C20MP12 | 41,500 | $4,980 |
| Yes | 211206954 | JOHNSON CONTROLS | HL20B4821 | XAMC48HE3N1+CC | TM8V120C20MP12 | 41,500 | $4,980 |
| Yes | 211206947 | JOHNSON CONTROLS | HL20B4821 | XAMC48HE3N1+CC | TP9C080C16MP13 | 41,500 | $4,980 |
| Yes | 211206942 | JOHNSON CONTROLS | HL20B4821 | XAMC48HE3N1+CC | TM9V080C16MP12 | 41,500 | $4,980 |
| Yes | 211206935 | JOHNSON CONTROLS | HL20B4821 | XAMC48HE3N1+CC | TP9C100C16MP13 | 41,500 | $4,980 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 211206930 | JOHNSON CONTROLS | HL20B4821 | XAMC48HE3N1+CC | TM9V100C16MP12 | 41,500 | $4,980 |
| Yes | 211206923 | JOHNSON CONTROLS | HL20B4821 | XAMC48HE3N1+CC | TP9C100C20MP13 | 41,500 | $4,980 |
| Yes | 211206918 | JOHNSON CONTROLS | HL20B4821 | XAMC48HE3N1+CC | TM9V100C20MP12 | 41,500 | $4,980 |
| Yes | 211206911 | JOHNSON CONTROLS | HL20B6021 | XAMC60HE4N1+CC | TP9C100C20MP13 | 47,000 | $5,640 |
| Yes | 211206906 | JOHNSON CONTROLS | HL20B6021 | XAMC60HE4N1+CC | TM9V100C20MP12 | 47,000 | $5,640 |
| Yes | 211206853 | JOHNSON CONTROLS | HL20B2421 | XAMB24DE1N1+CC | TPLC080B12MP13 | 23,000 | $2,760 |
| Yes | 211206848 | JOHNSON CONTROLS | HL20B2421 | XAMB24DE1N1+CC | TM8V080B12MP12 | 23,000 | $2,760 |
| Yes | 211206841 | JOHNSON CONTROLS | HL20B2421 | XAMB24DE1N1+CC | TP9C060B12MP13 | 23,200 | $2,784 |
| Yes | 211206836 | JOHNSON CONTROLS | HL20B2421 | XAMB24DE1N1+CC | TM9V060B12MP12 | 23,200 | $2,784 |
| Yes | 211010181 | JOHNSON CONTROLS | HL20B6021 | JHVVD60HE4C2N1+CC | | 46,500 | $5,580 |
| Yes | 207796643 | KARDA | 3KARDA24SZO | 3KARDA24UVC | | 21,000 | $2,520 |
| Yes | 207430431 | KARDA | 3KARDA24SZO | 3KARDA24UVW | | 18,900 | $2,268 |
| Yes | 207796644 | KARDA | 3KARDA24SZO | 3KARDA24UVD | | 21,000 | $2,520 |
| Yes | 206348123 | KARDA | 1KARDA24SZO20.5 | 2PAMSDH24 | | 21,000 | $2,520 |
| Yes | 206348122 | KARDA | 2KARDA18SZO20 | 2PAMSDH18 | | 15,000 | $1,800 |
| Yes | 207796642 | KARDA | 3KARDA18SZO | 3KARDA18UVD | | 15,000 | $1,800 |
| Yes | 201830348 | KARDA | 1PAMSHH24-SZO-20.5 | 1PAMSHH24-SZW-20.5 | | 15,400 | $1,848 |
| Yes | 205921401 | KARDA | 1PAMSHH24-SZO-20.5 | 2KARDA24UVD | | 17,200 | $2,064 |
| Yes | 209852083 | KEEPRITE | DLCURAH48ABK | DLFUAAH48XAK | | 36,000 | $4,320 |
| Yes | 209852087 | KEEPRITE | DLCURAH36ABK | DLFUAAH36XAK | | 30,400 | $3,648 |
| Yes | 209852081 | KEEPRITE | DLCURAH24ABK | DLFUAAH24XAK | | 19,200 | $2,304 |
| Yes | 209852080 | KEEPRITE | DLCURAH18ABK | DLFUAAH18XAK | | 13,500 | $1,620 |
| Yes | 207643086 | KEEPRITE | DLCMHBH36DAK | Heat pump without ducts | | 22,000 | $2,640 |
| Yes | 207643083 | KEEPRITE | DLCMHBH48EAK | Heat pump without ducts | | 34,000 | $4,080 |
| Yes | 207643077 | KEEPRITE | DLCMHBH30DAK | Heat pump without ducts | | 18,500 | $2,220 |
| Yes | 207826603 | KEEPRITE | DLCSRBH18AAK | DLFSABH18XBK | | 12,000 | $1,440 |
| Yes | 207801572 | KEEPRITE | DLCSRBH18AAK | DLFSDAH24XAK | | 12,600 | $1,512 |
| Yes | 8177091 | KEEPRITE | DLCAHB12K1A | DLFAHH12K1A | | 13,000 | $1,560 |
| Yes | 207643078 | KEEPRITE | DLCMHBH30DAK | Heat pump with ducts | | 19,000 | $2,280 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 207643087 | KEEPRITE | DLCMHBH36DAK | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 207643084 | KEEPRITE | DLCMHBH48EAK | Heat pump with ducts | | 28,000 | $3,360 |
| Yes | 207643085 | KEEPRITE | DLCMHBH48EAK | Combination heat pumps with or without ducts | | 31,000 | $3,720 |
| Yes | 207643079 | KEEPRITE | DLCMHBH30DAK | Combination heat pumps with or without ducts | | 18,700 | $2,244 |
| Yes | 207643088 | KEEPRITE | DLCMHBH36DAK | Combination heat pumps with or without ducts | | 22,400 | $2,688 |
| Yes | 206350434 | KEEPRITE | DLCSRBH24AAK | DLFSCAH24XAK | | 14,500 | $1,740 |
| Yes | 206350432 | KEEPRITE | DLCSRBH18AAK | DLFSDAH18XAK | | 12,700 | $1,524 |
| Yes | 206350436 | KEEPRITE | DLCSRBH24AAK | DLFSFAH24XAK | | 14,500 | $1,740 |
| Yes | 206350433 | KEEPRITE | DLCSRBH18AAK | DLFSFAH18XAK | | 12,000 | $1,440 |
| Yes | 206188316 | KEEPRITE | DLCSRBH24AAK | DLFSAAH24XAK | | 16,500 | $1,980 |
| Yes | 206350435 | KEEPRITE | DLCSRBH24AAK | DLFSDAH24XAK | | 14,500 | $1,740 |
| Yes | 205921376 | KEEPRITE | DLCSRAH24AAK | DLFSAAH24XAK | | 17,500 | $2,100 |
| Yes | 201835723 | KEEPRITE | DLCSRAH24AAK | DLFSCAH24XAK | | 16,200 | $1,944 |
| Yes | 202463651 | KEEPRITE | DLCPRAH24AAK | DLFPHAH24XAK | | 15,450 | $1,854 |
| Yes | 201835719 | KEEPRITE | DLCSRAH24AAK | DLFSDAH24XAK | | 17,400 | $2,088 |
| Yes | 201835677 | KEEPRITE | DLCSRAH24AAK | DLFSHAH24XAK | | 15,000 | $1,800 |
| Yes | 201835731 | KEEPRITE | DLCLRAH48AAK | DLFLFAH48XAK | | 35,000 | $4,200 |
| Yes | 201835721 | KEEPRITE | DLCSRAH24AAK | DLFSFAH24XAK | | 17,200 | $2,064 |
| Yes | 201835717 | KEEPRITE | DLCSRAH18AAK | DLFSCAH18XAK | | 12,000 | $1,440 |
| Yes | 207643107 | KENMORE | DLCMHBH36DAK | Heat pump without ducts | | 22,000 | $2,640 |
| Yes | 207643104 | KENMORE | DLCMHBH48EAK | Heat pump without ducts | | 34,000 | $4,080 |
| Yes | 207643098 | KENMORE | DLCMHBH30DAK | Heat pump without ducts | | 18,500 | $2,220 |
| Yes | 207826605 | KENMORE | DLCSRBH18AAK | DLFSABH18XBK | | 12,000 | $1,440 |
| Yes | 207801573 | KENMORE | DLCSRBH18AAK | DLFSDAH24XAK | | 12,600 | $1,512 |
| Yes | 8177095 | KENMORE | DLCAHB12K1A | DLFAHH12K1A | | 13,000 | $1,560 |
| Yes | 207643108 | KENMORE | DLCMHBH36DAK | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 207643099 | KENMORE | DLCMHBH30DAK | Heat pump with ducts | | 19,000 | $2,280 |
| Yes | 207643105 | KENMORE | DLCMHBH48EAK | Heat pump with ducts | | 28,000 | $3,360 |
| Yes | 207643109 | KENMORE | DLCMHBH36DAK | Combination heat pumps with or without ducts | | 22,400 | $2,688 |
| Yes | 207643106 | KENMORE | DLCMHBH48EAK | Combination heat pumps with or without ducts | | 31,000 | $3,720 |
| Yes | 207643100 | KENMORE | DLCMHBH30DAK | Combination heat pumps with or without ducts | | 18,700 | $2,244 |
| Yes | 206188323 | KENMORE | DLCSRBH24AAK | DLFSAAH24XAK | | 16,500 | $1,980 |
| Yes | 206350445 | KENMORE | DLCSRBH24AAK | DLFSCAH24XAK | | 14,500 | $1,740 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 206350447 | KENMORE | DLCSRBH24AAK | DLFSFAH24XAK | | 14,500 | $1,740 |
| Yes | 206350444 | KENMORE | DLCSRBH18AAK | DLFSFAH18XAK | | 12,000 | $1,440 |
| Yes | 206350443 | KENMORE | DLCSRBH18AAK | DLFSDAH18XAK | | 12,700 | $1,524 |
| Yes | 206350446 | KENMORE | DLCSRBH24AAK | DLFSDAH24XAK | | 14,500 | $1,740 |
| Yes | 205921377 | KENMORE | DLCSRAH24AAK | DLFSAAH24XAK | | 17,500 | $2,100 |
| Yes | 201835819 | KENMORE | DLCSRAH24AAK | DLFSCAH24XAK | | 16,200 | $1,944 |
| Yes | 202463653 | KENMORE | DLCPRAH24AAK | DLFPHAH24XAK | | 15,450 | $1,854 |
| Yes | 201835815 | KENMORE | DLCSRAH24AAK | DLFSDAH24XAK | | 17,400 | $2,088 |
| Yes | 201835772 | KENMORE | DLCSRAH24AAK | DLFSHAH24XAK | | 15,000 | $1,800 |
| Yes | 201835827 | KENMORE | DLCLRAH48AAK | DLFLFAH48XAK | | 35,000 | $4,200 |
| Yes | 201835817 | KENMORE | DLCSRAH24AAK | DLFSFAH24XAK | | 17,200 | $2,064 |
| Yes | 201835813 | KENMORE | DLCSRAH18AAK | DLFSCAH18XAK | | 12,000 | $1,440 |
| Yes | 210857424 | KERR | A-KCD60SA-1 | B-KCD60SA-1 | | 42,000 | $5,040 |
| Yes | 207657604 | KERR | A-KMH36QV-1 | Heat pump without ducts | | 33,000 | $3,960 |
| Yes | 207657599 | KERR | A-KMH18DV-1 | Heat pump without ducts | | 15,000 | $1,800 |
| Yes | 207657607 | KERR | A-KMH48PV-1 | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 207657606 | KERR | A-KMH48PV-1 | Heat pump without ducts | | 36,000 | $4,320 |
| Yes | 207657602 | KERR | A-KMH28TV-1 | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 207657601 | KERR | A-KMH28TV-1 | Heat pump without ducts | | 26,600 | $3,192 |
| Yes | 207657598 | KERR | A-KMH18DV-1 | Heat pump with ducts | | 16,000 | $1,920 |
| Yes | 210568248 | KERR | A-KMH24SV-1 | B-KMH24CV-1 | | 21,000 | $2,520 |
| Yes | 207657400 | KERR | A-KMH24SV-1 | C-VMH24CV-1 | | 21,000 | $2,520 |
| Yes | 210568247 | KERR | A-KMH24SV-1 | B-KMH24DU-1 | | 21,000 | $2,520 |
| Yes | 206347321 | KERR | A-KMH24SU-1A | B-KMH24DU-1 | | 21,000 | $2,520 |
| Yes | 206347323 | KERR | A-KMH24SU-1A | B-KMH24UU-1 | | 19,000 | $2,280 |
| Yes | 210568252 | KERR | A-KMH24SV-1 | B-KMH24UU-1 | | 19,000 | $2,280 |
| Yes | 206347320 | KERR | A-KMH18SU-1A | B-KMH18DU-1 | | 15,000 | $1,800 |
| Yes | 210568253 | KERR | A-KMH18SV-1 | B-KMH18DU-1 | | 15,000 | $1,800 |
| Yes | 208141201 | KERR | A-KMH24SU-1 | B-KMH24SV-1 | | 21,200 | $2,544 |
| Yes | 207657397 | KERR | A-KMH24SV-1 | B-KMH24SV-1 | | 21,200 | $2,544 |
| Yes | 207657396 | KERR | A-KMH18SV-1 | B-KMH18SV-1 | | 15,000 | $1,800 |
| Yes | 208141200 | KERR | A-KMH18SU-1 | B-KMH18SV-1 | | 15,000 | $1,800 |
| Yes | 201866480 | KERR | A-KMH28TU-1 | Heat pump without ducts | | 18,000 | $2,160 |
| Yes | 202111000 | KERR | A-KMH24SU-1 | B-KMH24DU-1 | | 17,200 | $2,064 |
| Yes | 207691816 | KERR | A-KCD36SA-1 | B-KCD36SA-1 | | 24,000 | $2,880 |
| Yes | 207691814 | KERR | A-KCD24SA-1 | B-KCD24SA-1 | | 16,700 | $2,004 |
| Yes | 207657605 | KERR | A-KMH36QV-1 | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 206221393 | KERR | A-KMH24SU-1A | B-KMH24SU-1A | | 19,400 | $2,328 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 208141196 | KERR | A-KMH24SV-1 | B-KMH24SU-1 | | 19,400 | $2,328 |
| Yes | 206913573 | KERR | A-KMH24SU-1 | B-KMH24SU-1A | | 19,400 | $2,328 |
| Yes | 207657608 | KERR | A-KMH48PV-1 | Combination heat pumps with or without ducts | | 29,000 | $3,480 |
| Yes | 207657621 | KERR | A-KMH36QV-1 | Combination heat pumps with or without ducts | | 23,000 | $2,760 |
| Yes | 206913038 | KERR | A-KMH24SU-1A | B-KMH24SU-1 | | 19,400 | $2,328 |
| Yes | 206061624 | KERR | A-VMH24SU-1A | B-VMH24SU-1A | | 19,400 | $2,328 |
| Yes | 207691815 | KERR | A-KCD30SA-1 | B-KCD30SA-1 | | 19,400 | $2,328 |
| Yes | 207691817 | KERR | A-KCD48SA-1 | B-KCD48SA-1 | | 32,000 | $3,840 |
| Yes | 212361361 | KINGHOME | KU36UHO | KCA24*I | | 16,800 | $2,016 |
| Yes | 211497156 | KINGHOME | KM42H5O | Heat pump without ducts | | 35,600 | $4,272 |
| Yes | 211497155 | KINGHOME | KM36H5O | Heat pump without ducts | | 30,800 | $3,696 |
| Yes | 206414279 | KINGHOME | KU60UHO | KU48UH2I | | 31,400 | $3,768 |
| Yes | 206414278 | KINGHOME | KU60UHO | KU60UH2I | | 36,000 | $4,320 |
| Yes | 206414277 | KINGHOME | KU36UHO | KU36UH2I | | 24,000 | $2,880 |
| Yes | 206414276 | KINGHOME | KU36UHO | KU24UH2I | | 16,000 | $1,920 |
| Yes | 204462623 | KINGHOME | KM24UH5O | Heat pump without ducts | | 17,900 | $2,148 |
| Yes | 204462622 | KINGHOME | KM18UH5O | Heat pump without ducts | | 17,000 | $2,040 |
| Yes | 203498481 | KINGHOME | KW24HQ3D6DO | KW24HQ3D6DI | | 15,500 | $1,860 |
| Yes | 203493071 | KINGHOME | KW18HQ3D6DO | KW18HQ3D6DI | | 14,200 | $1,704 |
| Yes | 211177533 | KINGHOME | KU36UHO | KCA36*I | ML296UH070XV36B-* | 22,000 | $2,640 |
| Yes | 211177534 | KINGHOME | KU60UHO | KCA48*I | ML296UH090XV48C-* | 28,200 | $3,384 |
| Yes | 211177532 | KINGHOME | KU36UHO | KCA24*I | ML296UH070XV36B-* | 15,600 | $1,872 |
| Yes | 204462790 | KINGHOME | KU21-ODU42-4 | KU21-CDU42-4 | | 28,600 | $3,432 |
| Yes | 205724739 | KINGHOME | KU60UHO | KU60UHI | | 38,000 | $4,560 |
| Yes | 205756438 | KINGHOME | KU36UHO | KU24UHI | | 16,300 | $1,956 |
| Yes | 206322337 | KINGHOME | KU60UHO | KU48UHI | | 32,800 | $3,936 |
| Yes | 204462632 | KINGHOME | KU21-OUD48-4 | KU21-CDU48-4S | | 33,000 | $3,960 |
| Yes | 204743192 | KINGHOME | KU36UHO | KU36UHI | | 24,400 | $2,928 |
| Yes | 204462626 | KINGHOME | KM48UH5O | Heat pump without ducts | | 38,000 | $4,560 |
| Yes | 10338836 | KINGHOME | KW18HUCA4DO | KW18HUCA4DI | | 12,700 | $1,524 |
| Yes | 10333040 | KINGHOME | KW18HQ2B8DO | KW18HQ2B8DI | | 12,400 | $1,488 |
| Yes | 10338140 | KINGHOME | KW24HQ2B8DO | KW24HQ2B8DI | | 14,600 | $1,752 |
| Yes | 10338155 | KINGHOME | KU21-ODU42-3 | KU21-CDU42-3 | | 24,800 | $2,976 |
| Yes | 10338151 | KINGHOME | KU21-ODU48-3 | KU21-CDU48-3 | | 30,600 | $3,672 |
| Yes | 205287677 | KINGHOME | KU21-ODU48-4 | KU21-CDU48-4S | | 33,000 | $3,960 |
| Yes | 212316044 | KLIMAIRE | KSIH024-H220-O-2 | KTIS24-H2 | | 21,000 | $2,520 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 209862156 | KLIMAIRE | KSIH024-H220-O-2 | KSIH024-H220-IW-2 | | 18,900 | $2,268 |
| Yes | 209862169 | KLIMAIRE | KSIH024-H220-O-2 | KDIP24-H2 | | 21,000 | $2,520 |
| Yes | 209862174 | KLIMAIRE | KSIH024-H220-O-2 | KUIR24-H2 | | 19,000 | $2,280 |
| Yes | 209862172 | KLIMAIRE | KSIH018-H220-O-2 | KDIP18-H2 | | 15,000 | $1,800 |
| Yes | 210191036 | KLIMAIRE | KOIF60H2-1S | KIDF60H2-1S | | 42,000 | $5,040 |
| Yes | 212316043 | KLIMAIRE | KOIF48H2-1S | KIDF48H2-1S | | 36,000 | $4,320 |
| Yes | 212316040 | KLIMAIRE | KOIF24H2-1S | KIDF24H2-1S | | 19,200 | $2,304 |
| Yes | 212331390 | LBG Products | LCUHB30DO | LCHB36DA | | 22,600 | $2,712 |
| Yes | 207641322 | LBG PRODUCTS | LMUHB36DO | Heat pump without ducts | | 35,000 | $4,200 |
| Yes | 207641320 | LBG Products | LMUHB27DO | Heat pump without ducts | | 25,600 | $3,072 |
| Yes | 207641317 | LBG Products | LMUHB18DO | Heat pump with ducts | | 16,000 | $1,920 |
| Yes | 207641326 | LBG Products | LMUHB48DO | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 207641325 | LBG Products | LMUHB48DO | Heat pump without ducts | | 39,000 | $4,680 |
| Yes | 207641316 | LBG Products | LMUHB18DO | Heat pump without ducts | | 13,500 | $1,620 |
| Yes | 208130834 | LBG Products | LBHB24DVWO | LMHB24DSI | | 21,000 | $2,520 |
| Yes | 208130842 | LBG Products | LUUHB48DO | LUHB48DFI | | 39,500 | $4,740 |
| Yes | 208130836 | LBG Products | LUUHB48DO | LUHB48DSI | | 35,000 | $4,200 |
| Yes | 208130847 | LBG Products | LUUHB48DO | LUHB48DZDI | | 35,000 | $4,200 |
| Yes | 208130835 | LBG Products | LUUHB36DO | LUHB36DSI | | 33,000 | $3,960 |
| Yes | 208130846 | LBG Products | LUUHB36DO | LUHB36DZDI | | 32,000 | $3,840 |
| Yes | 208130830 | LBG Products | LBHB24DVWO | LBHB24DUWI | | 18,900 | $2,268 |
| Yes | 208130840 | LBG Products | LBHB24DVWO | LMHB24DFI | | 21,000 | $2,520 |
| Yes | 208130845 | LBG Products | LBHB24DVWO | LMHB24DZDI | | 19,000 | $2,280 |
| Yes | 208130839 | LBG Products | LBHB18DVWO | LMHB18DFI | | 15,000 | $1,800 |
| Yes | 207629155 | LBG Products | LBHB18DYWO | LBHB18DYWI | | 21,200 | $2,544 |
| Yes | 207641323 | LBG PRODUCTS | LMUHB36DO | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 207641318 | LBG PRODUCTS | LMUHB18DO | Combination heat pumps with or without ducts | | 15,200 | $1,824 |
| Yes | 207641324 | LBG PRODUCTS | LMUHB36DO | Combination heat pumps with or without ducts | | 22,400 | $2,688 |
| Yes | 207641327 | LBG PRODUCTS | LMUHB48DO | Combination heat pumps with or without ducts | | 31,000 | $3,720 |
| Yes | 206726719 | LBG PRODUCTS | LCH24036DO | LCH36DGHNI | | 24,000 | $2,880 |
| Yes | 207699107 | LENNOX | MLB048S4M-2P | Heat pump without ducts | | 36,000 | $4,320 |
| Yes | 211034460 | LENNOX | MLB048S4S-2P | M33C048S4-*P | | 35,000 | $4,200 |
| Yes | 211034459 | LENNOX | MLB036S4S-2P | M33C036S4-*P | | 33,000 | $3,960 |
| Yes | 211034458 | LENNOX | MLB024S4S-1P | M33C024S4-*P | | 21,000 | $2,520 |
| Yes | 211034454 | LENNOX | MLB048S4S-2P | MCFA048S4-*P | | 35,000 | $4,200 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 211034452 | LENNOX | MLB024S4S-1P | MCFA024S4-*P | | 19,000 | $2,280 |
| Yes | 211034449 | LENNOX | MLB048S4S-2P | MMDB048S4-*P | | 39,500 | $4,740 |
| Yes | 211034448 | LENNOX | MLB036S4S-2P | MMDB036S4-*P | | 33,400 | $4,008 |
| Yes | 211034447 | LENNOX | MLB024S4S-1P | MMDB024S4-*P | | 21,000 | $2,520 |
| Yes | 211034446 | LENNOX | MLB018S4S-1P | MMDB018S4-*P | | 15,000 | $1,800 |
| Yes | 211034443 | LENNOX | MLB024S4S-1P | MWMC024S4-*P | | 21,200 | $2,544 |
| Yes | 211034442 | LENNOX | MLB018S4S-1P | MWMC018S4-*P | | 15,000 | $1,800 |
| Yes | 205782165 | LENNOX | MLB048S4S-1P | M33B048S4-2P | | 35,000 | $4,200 |
| Yes | 205782161 | LENNOX | MLB048S4S-1P | MMDB048S4-2P | | 39,500 | $4,740 |
| Yes | 207699108 | LENNOX | MLB048S4M-2P | MMDB009S4-2P | | 36,000 | $4,320 |
| Yes | 205782164 | LENNOX | MLB036S4S-1P | M33A036S4-2P | | 25,400 | $3,048 |
| Yes | 205782160 | LENNOX | MLB036S4S-1P | MMDB036S4-2P | | 34,000 | $4,080 |
| Yes | 207699104 | LENNOX | MLB036S4M-1P | Heat pump without ducts | | 33,000 | $3,960 |
| Yes | 207683523 | LENNOX | MLB024S4S-1P | MWMC024S4-1P | | 21,200 | $2,544 |
| Yes | 207683527 | LENNOX | MLB024S4S-1P | MMDB024S4-2P | | 21,000 | $2,520 |
| Yes | 207683530 | LENNOX | MLB024S4S-1P | MCFA024S4-2P | | 19,000 | $2,280 |
| Yes | 207683522 | LENNOX | MLB018S4S-1P | MWMC018S4-1P | | 15,000 | $1,800 |
| Yes | 207768728 | LENNOX | MLB018S4M-1P | Heat pump with ducts | | 16,000 | $1,920 |
| Yes | 207768727 | LENNOX | MLB018S4M-1P | Heat pump without ducts | | 15,000 | $1,800 |
| Yes | 201771989 | LENNOX | MLA036S4M-1P | Heat pump without ducts | | 16,800 | $2,016 |
| Yes | 10528572 | LENNOX | MLA024S4S-1P | MMDB024S4-2P | | 23,000 | $2,760 |
| Yes | 211694775 | LENNOX | EL22XPV-024-230A** | CBA27UHE-030-230*+TDR | | 14,300 | $1,716 |
| Yes | 211694663 | LENNOX | EL22XPV-024-230A** | CBA38MV-030-230*+TDR | | 14,300 | $1,716 |
| Yes | 207699100 | LENNOX | MLB048S4S-2P | M33C048S4-1P | | 35,000 | $4,200 |
| Yes | 207699098 | LENNOX | MLB048S4S-2P | MCFA048S4-2P | | 35,000 | $4,200 |
| Yes | 207699096 | LENNOX | MLB048S4S-2P | MMDB048S4-2P | | 33,000 | $3,960 |
| Yes | 207699099 | LENNOX | MLB036S4S-2P | M33C036S4-1P | | 25,000 | $3,000 |
| Yes | 207699095 | LENNOX | MLB036S4S-2P | MMDB036S4-2P | | 28,000 | $3,360 |
| Yes | 207699106 | LENNOX | MLB036S4M-1P | Combinaison d'unités avec et sans conduits | | 23,000 | $2,760 |
| Yes | 9920055 | LENNOX | MLA036S4M-1P | Heat pump without ducts | | 23,200 | $2,784 |
| Yes | 201771988 | LENNOX | MLA030S4M-1P | Heat pump without ducts | | 18,000 | $2,160 |
| Yes | 207436409 | LENNOX | SL25XPV-036-230A** | CHX35-48B-**-*+TDR | SL280UH080NV48B* | 31,000 | $3,720 |
| Yes | 207436574 | LENNOX | SL25XPV-048-230A** | CHX35-51/61C-**-*+TDR | SLP99UH110XV60C* | 46,000 | $5,520 |
| Yes | 207436572 | LENNOX | SL25XPV-048-230A** | CHX35-51/61C-**-*+TDR | SLP99UH090XV48C* | 46,000 | $5,520 |
| Yes | 207436573 | LENNOX | SL25XPV-048-230A** | CHX35-51/61C-**-*+TDR | SLP99UH090XV60C* | 46,000 | $5,520 |
| Yes | 207436563 | LENNOX | SL25XPV-048-230A** | CHX35-51/61C-**-*+TDR | EL296UH110XV60C* | 46,000 | $5,520 |
| Yes | 207436560 | LENNOX | SL25XPV-048-230A** | CHX35-51/61C-**-*+TDR | EL296UH090XV48C* | 46,000 | $5,520 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 207436561 | LENNOX | SL25XPV-048-230A** | CHX35-51/61C-**-*+TDR | EL296UH090XV60C* | 46,000 | $5,520 |
| Yes | 207436585 | LENNOX | SL25XPV-048-230A** | CR33-50/60+TDR+TXV | SLP99DF110XV60C* | 41,000 | $4,920 |
| Yes | 207436584 | LENNOX | SL25XPV-048-230A** | CR33-50/60+TDR+TXV | SLP99DF090XV60C* | 41,000 | $4,920 |
| Yes | 207436583 | LENNOX | SL25XPV-048-230A** | CR33-50/60+TDR+TXV | SLP99DF090XV48C* | 41,000 | $4,920 |
| Yes | 207436556 | LENNOX | SL25XPV-048-230A** | CH35-51C+TDR+TXV | SLP99UH110XV60C* | 46,000 | $5,520 |
| Yes | 207436579 | LENNOX | SL25XPV-048-230A** | CR33-50/60+TDR+TXV | EL296DF110XV60C* | 41,000 | $4,920 |
| Yes | 207436578 | LENNOX | SL25XPV-048-230A** | CR33-50/60+TDR+TXV | EL296DF090XV60C* | 41,000 | $4,920 |
| Yes | 207436555 | LENNOX | SL25XPV-048-230A** | CH35-51C+TDR+TXV | SLP99UH090XV60C* | 46,000 | $5,520 |
| Yes | 207436554 | LENNOX | SL25XPV-048-230A** | CH35-51C+TDR+TXV | SLP99UH090XV48C* | 46,000 | $5,520 |
| Yes | 207436543 | LENNOX | SL25XPV-048-230A** | CH35-51C+TDR+TXV | EL296UH090XV60C* | 46,000 | $5,520 |
| Yes | 207436545 | LENNOX | SL25XPV-048-230A** | CH35-51C+TDR+TXV | EL296UH110XV60C* | 46,000 | $5,520 |
| Yes | 207436577 | LENNOX | SL25XPV-048-230A** | CHX35-60D-**-*+TDR | SLP99UH135XV60D* | 42,000 | $5,040 |
| Yes | 207436576 | LENNOX | SL25XPV-048-230A** | CHX35-60D-**-*+TDR | SL280UH135V60D* | 42,000 | $5,040 |
| Yes | 207436575 | LENNOX | SL25XPV-048-230A** | CHX35-60D-**-*+TDR | EL296UH135XV60D* | 42,000 | $5,040 |
| Yes | 207436542 | LENNOX | SL25XPV-048-230A** | CH35-51C+TDR+TXV | EL296UH090XV48C* | 46,000 | $5,520 |
| Yes | 207436571 | LENNOX | SL25XPV-048-230A** | CHX35-51/61C-**-*+TDR | SL297UH080NV60C* | 46,000 | $5,520 |
| Yes | 207436570 | LENNOX | SL25XPV-048-230A** | CHX35-51/61C-**-*+TDR | SL297UH080NV48C* | 46,000 | $5,520 |
| Yes | 207436568 | LENNOX | SL25XPV-048-230A** | CHX35-51/61C-**-*+TDR | SL280UH110V60C* | 45,500 | $5,460 |
| Yes | 207436569 | LENNOX | SL25XPV-048-230A** | CHX35-51/61C-**-*+TDR | SL280UH110XV60C* | 45,500 | $5,460 |
| Yes | 207436567 | LENNOX | SL25XPV-048-230A** | CHX35-51/61C-**-*+TDR | SL280UH100NV60C* | 45,500 | $5,460 |
| Yes | 207436566 | LENNOX | SL25XPV-048-230A** | CHX35-51/61C-**-*+TDR | SL280UH090XV60C* | 45,500 | $5,460 |
| Yes | 207436565 | LENNOX | SL25XPV-048-230A** | CHX35-51/61C-**-*+TDR | SL280UH090V60C* | 45,500 | $5,460 |
| Yes | 207436564 | LENNOX | SL25XPV-048-230A** | CHX35-51/61C-**-*+TDR | SL280UH080NV60C* | 45,500 | $5,460 |
| Yes | 207436562 | LENNOX | SL25XPV-048-230A** | CHX35-51/61C-**-*+TDR | EL296UH110XV48C* | 46,000 | $5,520 |
| Yes | 207436413 | LENNOX | SL25XPV-036-230A** | CHX35-48B-**-*+TDR | SL297UH040NV36B* | 31,200 | $3,744 |
| Yes | 207436414 | LENNOX | SL25XPV-036-230A** | CHX35-48B-**-*+TDR | SL297UH060NV36B* | 31,400 | $3,768 |
| Yes | 207436412 | LENNOX | SL25XPV-036-230A** | CHX35-48B-**-*+TDR | SL280UH090XV48B* | 31,200 | $3,744 |
| Yes | 207436411 | LENNOX | SL25XPV-036-230A** | CHX35-48B-**-*+TDR | SL280UH090V48B* | 31,200 | $3,744 |
| Yes | 207436410 | LENNOX | SL25XPV-036-230A** | CHX35-48B-**-*+TDR | SL280UH090V36B* | 31,000 | $3,720 |
| Yes | 207436407 | LENNOX | SL25XPV-036-230A** | CHX35-48B-**-*+TDR | EL296UH045XV36B* | 31,400 | $3,768 |
| Yes | 207436408 | LENNOX | SL25XPV-036-230A** | CHX35-48B-**-*+TDR | EL296UH070XV36B* | 31,400 | $3,768 |
| Yes | 207436415 | LENNOX | SL25XPV-036-230A** | CHX35-48B-**-*+TDR | SLP99UH070XV36B* | 31,400 | $3,768 |
| Yes | 207436387 | LENNOX | SL25XPV-036-230A** | CHX35-42B-**-*+TDR | SL297UH040NV36B* | 30,600 | $3,672 |
| Yes | 207436388 | LENNOX | SL25XPV-036-230A** | CHX35-42B-**-*+TDR | SL297UH060NV36B* | 30,600 | $3,672 |
| Yes | 207436389 | LENNOX | SL25XPV-036-230A** | CHX35-42B-**-*+TDR | SLP99UH070XV36B* | 30,800 | $3,696 |
| Yes | 207436384 | LENNOX | SL25XPV-036-230A** | CHX35-42B-**-*+TDR | SL280UH090V36B* | 30,400 | $3,648 |
| Yes | 207436381 | LENNOX | SL25XPV-036-230A** | CHX35-42B-**-*+TDR | EL296UH045XV36B* | 30,800 | $3,696 |
| Yes | 207436386 | LENNOX | SL25XPV-036-230A** | CHX35-42B-**-*+TDR | SL280UH090XV48B* | 30,600 | $3,672 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 207436385 | LENNOX | SL25XPV-036-230A** | CHX35-42B-**-*+TDR | SL280UH090V48B* | 30,600 | $3,672 |
| Yes | 207436382 | LENNOX | SL25XPV-036-230A** | CHX35-42B-**-*+TDR | EL296UH070XV36B* | 30,800 | $3,696 |
| Yes | 207436383 | LENNOX | SL25XPV-036-230A** | CHX35-42B-**-*+TDR | SL280UH080NV48B* | 30,400 | $3,648 |
| Yes | 207436219 | LENNOX | SL25XPV-024-230A** | CHX35-42C-**-*+TDR | SLP99UH110XV60C* | 23,800 | $2,856 |
| Yes | 207436218 | LENNOX | SL25XPV-024-230A** | CHX35-42C-**-*+TDR | SLP99UH090XV60C* | 23,800 | $2,856 |
| Yes | 207436217 | LENNOX | SL25XPV-024-230A** | CHX35-42C-**-*+TDR | SLP99UH090XV48C* | 23,800 | $2,856 |
| Yes | 207436216 | LENNOX | SL25XPV-024-230A** | CHX35-42C-**-*+TDR | SLP99UH090XV36C* | 23,800 | $2,856 |
| Yes | 207436214 | LENNOX | SL25XPV-024-230A** | CHX35-42C-**-*+TDR | SL297UH080NV48C* | 23,800 | $2,856 |
| Yes | 207436215 | LENNOX | SL25XPV-024-230A** | CHX35-42C-**-*+TDR | SL297UH080NV60C* | 23,800 | $2,856 |
| Yes | 207436213 | LENNOX | SL25XPV-024-230A** | CHX35-42C-**-*+TDR | SL280UH110XV60C* | 23,800 | $2,856 |
| Yes | 207436212 | LENNOX | SL25XPV-024-230A** | CHX35-42C-**-*+TDR | SL280UH110V60C* | 23,800 | $2,856 |
| Yes | 207436208 | LENNOX | SL25XPV-024-230A** | CHX35-42C-**-*+TDR | SL280UH080NV60C* | 23,600 | $2,832 |
| Yes | 207436211 | LENNOX | SL25XPV-024-230A** | CHX35-42C-**-*+TDR | SL280UH100NV60C* | 23,800 | $2,856 |
| Yes | 207436209 | LENNOX | SL25XPV-024-230A** | CHX35-42C-**-*+TDR | SL280UH090V60C* | 23,800 | $2,856 |
| Yes | 207436210 | LENNOX | SL25XPV-024-230A** | CHX35-42C-**-*+TDR | SL280UH090XV60C* | 23,800 | $2,856 |
| Yes | 207436207 | LENNOX | SL25XPV-024-230A** | CHX35-42C-**-*+TDR | EL296UH110XV60C* | 23,800 | $2,856 |
| Yes | 207436204 | LENNOX | SL25XPV-024-230A** | CHX35-42C-**-*+TDR | EL296UH090XV48C* | 23,800 | $2,856 |
| Yes | 207436203 | LENNOX | SL25XPV-024-230A** | CHX35-42C-**-*+TDR | EL296UH090XV36C* | 23,800 | $2,856 |
| Yes | 207436206 | LENNOX | SL25XPV-024-230A** | CHX35-42C-**-*+TDR | EL296UH110XV48C* | 23,800 | $2,856 |
| Yes | 207436205 | LENNOX | SL25XPV-024-230A** | CHX35-42C-**-*+TDR | EL296UH090XV60C* | 23,800 | $2,856 |
| Yes | 207436202 | LENNOX | SL25XPV-024-230A** | CHX35-42B-**-*+TDR | SLP99UH070XV36B* | 23,600 | $2,832 |
| Yes | 207436201 | LENNOX | SL25XPV-024-230A** | CHX35-42B-**-*+TDR | SL297UH060NV36B* | 23,600 | $2,832 |
| Yes | 207436200 | LENNOX | SL25XPV-024-230A** | CHX35-42B-**-*+TDR | SL297UH040NV36B* | 23,400 | $2,808 |
| Yes | 207436195 | LENNOX | SL25XPV-024-230A** | CHX35-42B-**-*+TDR | EL296UH070XV36B* | 23,600 | $2,832 |
| Yes | 207436199 | LENNOX | SL25XPV-024-230A** | CHX35-42B-**-*+TDR | SL280UH090XV48B* | 23,600 | $2,832 |
| Yes | 207436197 | LENNOX | SL25XPV-024-230A** | CHX35-42B-**-*+TDR | SL280UH090V36B* | 23,400 | $2,808 |
| Yes | 207436198 | LENNOX | SL25XPV-024-230A** | CHX35-42B-**-*+TDR | SL280UH090V48B* | 23,600 | $2,832 |
| Yes | 207436194 | LENNOX | SL25XPV-024-230A** | CHX35-42B-**-*+TDR | EL296UH045XV36B* | 23,600 | $2,832 |
| Yes | 207436614 | LENNOX | SL25XPV-048-230A** | CX35-60C+TDR | SLP99UH090XV60C* | 42,500 | $5,100 |
| Yes | 207436615 | LENNOX | SL25XPV-048-230A** | CX35-60C+TDR | SLP99UH110XV60C* | 42,500 | $5,100 |
| Yes | 207436612 | LENNOX | SL25XPV-048-230A** | CX35-60C+TDR | SL297UH080NV60C* | 42,000 | $5,040 |
| Yes | 207436611 | LENNOX | SL25XPV-048-230A** | CX35-60C+TDR | SL297UH080NV48C* | 42,000 | $5,040 |
| Yes | 207436613 | LENNOX | SL25XPV-048-230A** | CX35-60C+TDR | SLP99UH090XV48C* | 42,500 | $5,100 |
| Yes | 207436610 | LENNOX | SL25XPV-048-230A** | CX35-60C+TDR | SL280UH110XV60C* | 42,000 | $5,040 |
| Yes | 207436609 | LENNOX | SL25XPV-048-230A** | CX35-60C+TDR | SL280UH110V60C* | 42,000 | $5,040 |
| Yes | 207436607 | LENNOX | SL25XPV-048-230A** | CX35-60C+TDR | SL280UH090XV60C* | 42,000 | $5,040 |
| Yes | 207436605 | LENNOX | SL25XPV-048-230A** | CX35-60C+TDR | SL280UH080NV60C* | 42,000 | $5,040 |
| Yes | 207436606 | LENNOX | SL25XPV-048-230A** | CX35-60C+TDR | SL280UH090V60C* | 42,000 | $5,040 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 207436604 | LENNOX | SL25XPV-048-230A** | CX35-60C+TDR | EL296UH110XV60C* | 42,500 | $5,100 |
| Yes | 207436196 | LENNOX | SL25XPV-024-230A** | CHX35-42B-**-*+TDR | SL280UH080NV48B* | 23,400 | $2,808 |
| Yes | 207436601 | LENNOX | SL25XPV-048-230A** | CX35-60C+TDR | EL296UH090XV48C* | 42,500 | $5,100 |
| Yes | 207436603 | LENNOX | SL25XPV-048-230A** | CX35-60C+TDR | EL296UH110XV48C* | 42,500 | $5,100 |
| Yes | 207436608 | LENNOX | SL25XPV-048-230A** | CX35-60C+TDR | SL280UH100NV60C* | 42,000 | $5,040 |
| Yes | 207436509 | LENNOX | SL25XPV-036-230A** | CX35-50/60C+TDR | SLP99UH090XV60C* | 30,600 | $3,672 |
| Yes | 207436510 | LENNOX | SL25XPV-036-230A** | CX35-50/60C+TDR | SLP99UH110XV60C* | 30,600 | $3,672 |
| Yes | 207436508 | LENNOX | SL25XPV-036-230A** | CX35-50/60C+TDR | SLP99UH090XV48C* | 30,600 | $3,672 |
| Yes | 207436507 | LENNOX | SL25XPV-036-230A** | CX35-50/60C+TDR | SLP99UH090XV36C* | 30,800 | $3,696 |
| Yes | 207436506 | LENNOX | SL25XPV-036-230A** | CX35-50/60C+TDR | SL297UH080NV60C* | 30,600 | $3,672 |
| Yes | 207436504 | LENNOX | SL25XPV-036-230A** | CX35-50/60C+TDR | SL280UH110XV60C* | 30,600 | $3,672 |
| Yes | 207436505 | LENNOX | SL25XPV-036-230A** | CX35-50/60C+TDR | SL297UH080NV48C* | 30,600 | $3,672 |
| Yes | 207436503 | LENNOX | SL25XPV-036-230A** | CX35-50/60C+TDR | SL280UH110V60C* | 30,600 | $3,672 |
| Yes | 207436502 | LENNOX | SL25XPV-036-230A** | CX35-50/60C+TDR | SL280UH100NV60C* | 30,400 | $3,648 |
| Yes | 207436501 | LENNOX | SL25XPV-036-230A** | CX35-50/60C+TDR | SL280UH090XV60C* | 30,600 | $3,672 |
| Yes | 207436602 | LENNOX | SL25XPV-048-230A** | CX35-60C+TDR | EL296UH090XV60C* | 42,500 | $5,100 |
| Yes | 207436500 | LENNOX | SL25XPV-036-230A** | CX35-50/60C+TDR | SL280UH090V60C* | 30,600 | $3,672 |
| Yes | 207436496 | LENNOX | SL25XPV-036-230A** | CX35-50/60C+TDR | EL296UH090XV60C* | 30,600 | $3,672 |
| Yes | 207436494 | LENNOX | SL25XPV-036-230A** | CX35-50/60C+TDR | EL296UH090XV36C* | 30,800 | $3,696 |
| Yes | 207436499 | LENNOX | SL25XPV-036-230A** | CX35-50/60C+TDR | SL280UH080NV60C* | 30,400 | $3,648 |
| Yes | 207436495 | LENNOX | SL25XPV-036-230A** | CX35-50/60C+TDR | EL296UH090XV48C* | 30,600 | $3,672 |
| Yes | 207436497 | LENNOX | SL25XPV-036-230A** | CX35-50/60C+TDR | EL296UH110XV48C* | 30,600 | $3,672 |
| Yes | 207436498 | LENNOX | SL25XPV-036-230A** | CX35-50/60C+TDR | EL296UH110XV60C* | 30,600 | $3,672 |
| Yes | 207436492 | LENNOX | SL25XPV-036-230A** | CX35-48C+TDR | SLP99UH090XV60C* | 33,200 | $3,984 |
| Yes | 207436493 | LENNOX | SL25XPV-036-230A** | CX35-48C+TDR | SLP99UH110XV60C* | 33,200 | $3,984 |
| Yes | 207436490 | LENNOX | SL25XPV-036-230A** | CX35-48C+TDR | SLP99UH090XV36C* | 33,200 | $3,984 |
| Yes | 207436488 | LENNOX | SL25XPV-036-230A** | CX35-48C+TDR | SL297UH080NV48C* | 33,000 | $3,960 |
| Yes | 207436489 | LENNOX | SL25XPV-036-230A** | CX35-48C+TDR | SL297UH080NV60C* | 33,200 | $3,984 |
| Yes | 207436491 | LENNOX | SL25XPV-036-230A** | CX35-48C+TDR | SLP99UH090XV48C* | 33,200 | $3,984 |
| Yes | 207436487 | LENNOX | SL25XPV-036-230A** | CX35-48C+TDR | SL280UH110XV60C* | 33,000 | $3,960 |
| Yes | 207436485 | LENNOX | SL25XPV-036-230A** | CX35-48C+TDR | SL280UH100NV60C* | 32,800 | $3,936 |
| Yes | 207436486 | LENNOX | SL25XPV-036-230A** | CX35-48C+TDR | SL280UH110V60C* | 33,000 | $3,960 |
| Yes | 207436483 | LENNOX | SL25XPV-036-230A** | CX35-48C+TDR | SL280UH090V60C* | 33,000 | $3,960 |
| Yes | 207436482 | LENNOX | SL25XPV-036-230A** | CX35-48C+TDR | SL280UH080NV60C* | 33,000 | $3,960 |
| Yes | 207436481 | LENNOX | SL25XPV-036-230A** | CX35-48C+TDR | EL296UH110XV60C* | 33,200 | $3,984 |
| Yes | 207436480 | LENNOX | SL25XPV-036-230A** | CX35-48C+TDR | EL296UH110XV48C* | 33,000 | $3,960 |
| Yes | 207436484 | LENNOX | SL25XPV-036-230A** | CX35-48C+TDR | SL280UH090XV60C* | 33,000 | $3,960 |
| Yes | 207436478 | LENNOX | SL25XPV-036-230A** | CX35-48C+TDR | EL296UH090XV48C* | 33,200 | $3,984 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 207436479 | LENNOX | SL25XPV-036-230A** | CX35-48C+TDR | EL296UH090XV60C* | 33,200 | $3,984 |
| Yes | 207436477 | LENNOX | SL25XPV-036-230A** | CX35-48C+TDR | EL296UH090XV36C* | 33,200 | $3,984 |
| Yes | 207436476 | LENNOX | SL25XPV-036-230A** | CX35-48B+TDR | SLP99UH070XV36B* | 33,400 | $4,008 |
| Yes | 207436475 | LENNOX | SL25XPV-036-230A** | CX35-48B+TDR | SL297UH060NV36B* | 33,400 | $4,008 |
| Yes | 207436474 | LENNOX | SL25XPV-036-230A** | CX35-48B+TDR | SL297UH040NV36B* | 33,400 | $4,008 |
| Yes | 207436473 | LENNOX | SL25XPV-036-230A** | CX35-48B+TDR | SL280UH090XV48B* | 33,200 | $3,984 |
| Yes | 207436470 | LENNOX | SL25XPV-036-230A** | CX35-48B+TDR | SL280UH080NV48B* | 33,000 | $3,960 |
| Yes | 207436471 | LENNOX | SL25XPV-036-230A** | CX35-48B+TDR | SL280UH090V36B* | 33,200 | $3,984 |
| Yes | 207436468 | LENNOX | SL25XPV-036-230A** | CX35-48B+TDR | EL296UH045XV36B* | 33,400 | $4,008 |
| Yes | 207436469 | LENNOX | SL25XPV-036-230A** | CX35-48B+TDR | EL296UH070XV36B* | 33,400 | $4,008 |
| Yes | 207436239 | LENNOX | SL25XPV-024-230A** | CX35-36B+TDR | SLP99UH070XV36B* | 24,200 | $2,904 |
| Yes | 207436238 | LENNOX | SL25XPV-024-230A** | CX35-36B+TDR | SL297UH060NV36B* | 24,200 | $2,904 |
| Yes | 207436237 | LENNOX | SL25XPV-024-230A** | CX35-36B+TDR | SL297UH040NV36B* | 24,200 | $2,904 |
| Yes | 207436234 | LENNOX | SL25XPV-024-230A** | CX35-36B+TDR | SL280UH090V36B* | 24,200 | $2,904 |
| Yes | 207436236 | LENNOX | SL25XPV-024-230A** | CX35-36B+TDR | SL280UH090XV48B* | 24,200 | $2,904 |
| Yes | 207436235 | LENNOX | SL25XPV-024-230A** | CX35-36B+TDR | SL280UH090V48B* | 24,200 | $2,904 |
| Yes | 207436230 | LENNOX | SL25XPV-024-230A** | CX35-36A+TDR | SL280UH070XV36A* | 24,200 | $2,904 |
| Yes | 207436232 | LENNOX | SL25XPV-024-230A** | CX35-36B+TDR | EL296UH070XV36B* | 24,200 | $2,904 |
| Yes | 207436231 | LENNOX | SL25XPV-024-230A** | CX35-36B+TDR | EL296UH045XV36B* | 24,200 | $2,904 |
| Yes | 207436229 | LENNOX | SL25XPV-024-230A** | CX35-36A+TDR | SL280UH060NV36A* | 24,200 | $2,904 |
| Yes | 207436472 | LENNOX | SL25XPV-036-230A** | CX35-48B+TDR | SL280UH090V48B* | 33,200 | $3,984 |
| Yes | 207436580 | LENNOX | SL25XPV-048-230A** | CR33-50/60+TDR+TXV | SL280DF080NV60C* | 41,000 | $4,920 |
| Yes | 207436582 | LENNOX | SL25XPV-048-230A** | CR33-50/60+TDR+TXV | SL280DF110V60C* | 41,000 | $4,920 |
| Yes | 207436559 | LENNOX | SL25XPV-048-230A** | CH35-60D+TDR+TXV | SLP99UH135XV60D* | 42,000 | $5,040 |
| Yes | 207436581 | LENNOX | SL25XPV-048-230A** | CR33-50/60+TDR+TXV | SL280DF090V60C* | 41,000 | $4,920 |
| Yes | 207436558 | LENNOX | SL25XPV-048-230A** | CH35-60D+TDR+TXV | SL280UH135V60D* | 42,000 | $5,040 |
| Yes | 207436233 | LENNOX | SL25XPV-024-230A** | CX35-36B+TDR | SL280UH080NV48B* | 24,200 | $2,904 |
| Yes | 207436553 | LENNOX | SL25XPV-048-230A** | CH35-51C+TDR+TXV | SL297UH080NV60C* | 46,000 | $5,520 |
| Yes | 207436557 | LENNOX | SL25XPV-048-230A** | CH35-60D+TDR+TXV | EL296UH135XV60D* | 42,000 | $5,040 |
| Yes | 207436550 | LENNOX | SL25XPV-048-230A** | CH35-51C+TDR+TXV | SL280UH110V60C* | 45,500 | $5,460 |
| Yes | 207436552 | LENNOX | SL25XPV-048-230A** | CH35-51C+TDR+TXV | SL297UH080NV48C* | 46,000 | $5,520 |
| Yes | 207436551 | LENNOX | SL25XPV-048-230A** | CH35-51C+TDR+TXV | SL280UH110XV60C* | 45,500 | $5,460 |
| Yes | 207436549 | LENNOX | SL25XPV-048-230A** | CH35-51C+TDR+TXV | SL280UH100NV60C* | 45,500 | $5,460 |
| Yes | 207436548 | LENNOX | SL25XPV-048-230A** | CH35-51C+TDR+TXV | SL280UH090XV60C* | 45,500 | $5,460 |
| Yes | 207436547 | LENNOX | SL25XPV-048-230A** | CH35-51C+TDR+TXV | SL280UH090V60C* | 45,500 | $5,460 |
| Yes | 207436540 | LENNOX | SL25XPV-048-230A** | C35-60C+TDR+TXV | SLP99UH110XV60C* | 42,500 | $5,100 |
| Yes | 207436546 | LENNOX | SL25XPV-048-230A** | CH35-51C+TDR+TXV | SL280UH080NV60C* | 45,500 | $5,460 |
| Yes | 207436544 | LENNOX | SL25XPV-048-230A** | CH35-51C+TDR+TXV | EL296UH110XV48C* | 46,000 | $5,520 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 207436541 | LENNOX | SL25XPV-048-230A** | CBA38MV-048-230*+TDR | | 45,500 | $5,460 |
| Yes | 207436539 | LENNOX | SL25XPV-048-230A** | C35-60C+TDR+TXV | SLP99UH090XV60C* | 42,500 | $5,100 |
| Yes | 207436537 | LENNOX | SL25XPV-048-230A** | C35-60C+TDR+TXV | SL297UH080NV60C* | 42,000 | $5,040 |
| Yes | 207436538 | LENNOX | SL25XPV-048-230A** | C35-60C+TDR+TXV | SLP99UH090XV48C* | 42,500 | $5,100 |
| Yes | 207436535 | LENNOX | SL25XPV-048-230A** | C35-60C+TDR+TXV | SL280UH110XV60C* | 42,000 | $5,040 |
| Yes | 207436534 | LENNOX | SL25XPV-048-230A** | C35-60C+TDR+TXV | SL280UH110V60C* | 42,000 | $5,040 |
| Yes | 207436533 | LENNOX | SL25XPV-048-230A** | C35-60C+TDR+TXV | SL280UH100NV60C* | 42,000 | $5,040 |
| Yes | 207436532 | LENNOX | SL25XPV-048-230A** | C35-60C+TDR+TXV | SL280UH090XV60C* | 42,000 | $5,040 |
| Yes | 207436531 | LENNOX | SL25XPV-048-230A** | C35-60C+TDR+TXV | SL280UH090V60C* | 42,000 | $5,040 |
| Yes | 207436528 | LENNOX | SL25XPV-048-230A** | C35-60C+TDR+TXV | EL296UH110XV48C* | 42,500 | $5,100 |
| Yes | 207436530 | LENNOX | SL25XPV-048-230A** | C35-60C+TDR+TXV | SL280UH080NV60C* | 42,000 | $5,040 |
| Yes | 207436529 | LENNOX | SL25XPV-048-230A** | C35-60C+TDR+TXV | EL296UH110XV60C* | 42,500 | $5,100 |
| Yes | 207436527 | LENNOX | SL25XPV-048-230A** | C35-60C+TDR+TXV | EL296UH090XV60C* | 42,500 | $5,100 |
| Yes | 207436526 | LENNOX | SL25XPV-048-230A** | C35-60C+TDR+TXV | EL296UH090XV48C* | 42,500 | $5,100 |
| Yes | 207436536 | LENNOX | SL25XPV-048-230A** | C35-60C+TDR+TXV | SL297UH080NV48C* | 42,000 | $5,040 |
| Yes | 207436444 | LENNOX | SL25XPV-036-230A** | CR33-48C*+TDR+TXV | SLP99DF090XV48C* | 34,000 | $4,080 |
| Yes | 207436445 | LENNOX | SL25XPV-036-230A** | CR33-48C*+TDR+TXV | SLP99DF090XV60C* | 34,000 | $4,080 |
| Yes | 207436443 | LENNOX | SL25XPV-036-230A** | CR33-48C*+TDR+TXV | SLP99DF090XV36C* | 34,000 | $4,080 |
| Yes | 207436442 | LENNOX | SL25XPV-036-230A** | CR33-48C*+TDR+TXV | SL280DF110V60C* | 33,800 | $4,056 |
| Yes | 207436446 | LENNOX | SL25XPV-036-230A** | CR33-48C*+TDR+TXV | SLP99DF110XV60C* | 34,000 | $4,080 |
| Yes | 207436440 | LENNOX | SL25XPV-036-230A** | CR33-48C*+TDR+TXV | SL280DF080NV60C* | 34,000 | $4,080 |
| Yes | 207436436 | LENNOX | SL25XPV-036-230A** | CR33-48B*+TDR+TXV | SL280DF090V48B* | 34,000 | $4,080 |
| Yes | 207436438 | LENNOX | SL25XPV-036-230A** | CR33-48C*+TDR+TXV | EL296DF090XV60C* | 34,000 | $4,080 |
| Yes | 207436441 | LENNOX | SL25XPV-036-230A** | CR33-48C*+TDR+TXV | SL280DF090V60C* | 34,000 | $4,080 |
| Yes | 207436439 | LENNOX | SL25XPV-036-230A** | CR33-48C*+TDR+TXV | EL296DF110XV60C* | 34,000 | $4,080 |
| Yes | 207436435 | LENNOX | SL25XPV-036-230A** | CR33-48B*+TDR+TXV | SL280DF060NV36B* | 34,200 | $4,104 |
| Yes | 207436361 | LENNOX | SL25XPV-036-230A** | CH35-48B+TDR+TXV | SL297UH040NV36B* | 31,200 | $3,744 |
| Yes | 207436362 | LENNOX | SL25XPV-036-230A** | CH35-48B+TDR+TXV | SL297UH060NV36B* | 31,400 | $3,768 |
| Yes | 207436363 | LENNOX | SL25XPV-036-230A** | CH35-48B+TDR+TXV | SLP99UH070XV36B* | 31,400 | $3,768 |
| Yes | 207436360 | LENNOX | SL25XPV-036-230A** | CH35-48B+TDR+TXV | SL280UH090XV48B* | 31,200 | $3,744 |
| Yes | 207436355 | LENNOX | SL25XPV-036-230A** | CH35-48B+TDR+TXV | EL296UH045XV36B* | 31,400 | $3,768 |
| Yes | 207436356 | LENNOX | SL25XPV-036-230A** | CH35-48B+TDR+TXV | EL296UH070XV36B* | 31,400 | $3,768 |
| Yes | 207436357 | LENNOX | SL25XPV-036-230A** | CH35-48B+TDR+TXV | SL280UH080NV48B* | 31,000 | $3,720 |
| Yes | 207436358 | LENNOX | SL25XPV-036-230A** | CH35-48B+TDR+TXV | SL280UH090V36B* | 31,000 | $3,720 |
| Yes | 207436337 | LENNOX | SL25XPV-036-230A** | CH35-42B+TDR+TXV | SLP99UH070XV36B* | 30,800 | $3,696 |
| Yes | 207436336 | LENNOX | SL25XPV-036-230A** | CH35-42B+TDR+TXV | SL297UH060NV36B* | 30,600 | $3,672 |
| Yes | 207436335 | LENNOX | SL25XPV-036-230A** | CH35-42B+TDR+TXV | SL297UH040NV36B* | 30,600 | $3,672 |
| Yes | 207436333 | LENNOX | SL25XPV-036-230A** | CH35-42B+TDR+TXV | SL280UH090V48B* | 30,600 | $3,672 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 207436331 | LENNOX | SL25XPV-036-230A** | CH35-42B+TDR+TXV | SL280UH080NV48B* | 30,400 | $3,648 |
| Yes | 207436334 | LENNOX | SL25XPV-036-230A** | CH35-42B+TDR+TXV | SL280UH090XV48B* | 30,600 | $3,672 |
| Yes | 207436330 | LENNOX | SL25XPV-036-230A** | CH35-42B+TDR+TXV | EL296UH070XV36B* | 30,800 | $3,696 |
| Yes | 207436332 | LENNOX | SL25XPV-036-230A** | CH35-42B+TDR+TXV | SL280UH090V36B* | 30,400 | $3,648 |
| Yes | 207436329 | LENNOX | SL25XPV-036-230A** | CH35-42B+TDR+TXV | EL296UH045XV36B* | 30,800 | $3,696 |
| Yes | 207436326 | LENNOX | SL25XPV-036-230A** | C35-50/60C+TDR+TXV | SLP99UH090XV60C* | 30,600 | $3,672 |
| Yes | 207436328 | LENNOX | SL25XPV-036-230A** | CBA38MV-036-230*+TDR | | 34,000 | $4,080 |
| Yes | 207436327 | LENNOX | SL25XPV-036-230A** | C35-50/60C+TDR+TXV | SLP99UH110XV60C* | 30,600 | $3,672 |
| Yes | 207436314 | LENNOX | SL25XPV-036-230A** | C35-50/60C+TDR+TXV | SLP99UH090XV48C* | 30,600 | $3,672 |
| Yes | 207436308 | LENNOX | SL25XPV-036-230A** | C35-50/60C+TDR+TXV | SLP99UH090XV36C* | 30,800 | $3,696 |
| Yes | 207436305 | LENNOX | SL25XPV-036-230A** | C35-50/60C+TDR+TXV | SL297UH080NV60C* | 30,600 | $3,672 |
| Yes | 207436302 | LENNOX | SL25XPV-036-230A** | C35-50/60C+TDR+TXV | SL297UH080NV48C* | 30,600 | $3,672 |
| Yes | 207436359 | LENNOX | SL25XPV-036-230A** | CH35-48B+TDR+TXV | SL280UH090V48B* | 31,200 | $3,744 |
| Yes | 207436300 | LENNOX | SL25XPV-036-230A** | C35-50/60C+TDR+TXV | SL280UH110XV60C* | 30,600 | $3,672 |
| Yes | 207436294 | LENNOX | SL25XPV-036-230A** | C35-50/60C+TDR+TXV | SL280UH090XV60C* | 30,600 | $3,672 |
| Yes | 207436295 | LENNOX | SL25XPV-036-230A** | C35-50/60C+TDR+TXV | SL280UH100NV60C* | 30,400 | $3,648 |
| Yes | 207436292 | LENNOX | SL25XPV-036-230A** | C35-50/60C+TDR+TXV | SL280UH080NV60C* | 30,400 | $3,648 |
| Yes | 207436293 | LENNOX | SL25XPV-036-230A** | C35-50/60C+TDR+TXV | SL280UH090V60C* | 30,600 | $3,672 |
| Yes | 207436291 | LENNOX | SL25XPV-036-230A** | C35-50/60C+TDR+TXV | EL296UH110XV60C* | 30,600 | $3,672 |
| Yes | 207436297 | LENNOX | SL25XPV-036-230A** | C35-50/60C+TDR+TXV | SL280UH110V60C* | 30,600 | $3,672 |
| Yes | 207436289 | LENNOX | SL25XPV-036-230A** | C35-50/60C+TDR+TXV | EL296UH090XV60C* | 30,600 | $3,672 |
| Yes | 207436290 | LENNOX | SL25XPV-036-230A** | C35-50/60C+TDR+TXV | EL296UH110XV48C* | 30,600 | $3,672 |
| Yes | 207436286 | LENNOX | SL25XPV-036-230A** | C35-48C+TDR+TXV | SLP99UH110XV60C* | 33,200 | $3,984 |
| Yes | 207436285 | LENNOX | SL25XPV-036-230A** | C35-48C+TDR+TXV | SLP99UH090XV60C* | 33,200 | $3,984 |
| Yes | 207436288 | LENNOX | SL25XPV-036-230A** | C35-50/60C+TDR+TXV | EL296UH090XV48C* | 30,600 | $3,672 |
| Yes | 207436284 | LENNOX | SL25XPV-036-230A** | C35-48C+TDR+TXV | SLP99UH090XV48C* | 33,200 | $3,984 |
| Yes | 207436283 | LENNOX | SL25XPV-036-230A** | C35-48C+TDR+TXV | SLP99UH090XV36C* | 33,200 | $3,984 |
| Yes | 207436281 | LENNOX | SL25XPV-036-230A** | C35-48C+TDR+TXV | SL297UH080NV48C* | 33,000 | $3,960 |
| Yes | 207436282 | LENNOX | SL25XPV-036-230A** | C35-48C+TDR+TXV | SL297UH080NV60C* | 33,200 | $3,984 |
| Yes | 207436280 | LENNOX | SL25XPV-036-230A** | C35-48C+TDR+TXV | SL280UH110XV60C* | 33,000 | $3,960 |
| Yes | 207436279 | LENNOX | SL25XPV-036-230A** | C35-48C+TDR+TXV | SL280UH110V60C* | 33,000 | $3,960 |
| Yes | 207436278 | LENNOX | SL25XPV-036-230A** | C35-48C+TDR+TXV | SL280UH100NV60C* | 32,800 | $3,936 |
| Yes | 207436287 | LENNOX | SL25XPV-036-230A** | C35-50/60C+TDR+TXV | EL296UH090XV36C* | 30,800 | $3,696 |
| Yes | 207436276 | LENNOX | SL25XPV-036-230A** | C35-48C+TDR+TXV | SL280UH090V60C* | 33,000 | $3,960 |
| Yes | 207436277 | LENNOX | SL25XPV-036-230A** | C35-48C+TDR+TXV | SL280UH090XV60C* | 33,000 | $3,960 |
| Yes | 207436275 | LENNOX | SL25XPV-036-230A** | C35-48C+TDR+TXV | SL280UH080NV60C* | 33,000 | $3,960 |
| Yes | 207436274 | LENNOX | SL25XPV-036-230A** | C35-48C+TDR+TXV | EL296UH110XV60C* | 33,200 | $3,984 |
| Yes | 207436273 | LENNOX | SL25XPV-036-230A** | C35-48C+TDR+TXV | EL296UH110XV48C* | 33,000 | $3,960 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 207436272 | LENNOX | SL25XPV-036-230A** | C35-48C+TDR+TXV | EL296UH090XV60C* | 33,200 | $3,984 |
| Yes | 207436270 | LENNOX | SL25XPV-036-230A** | C35-48C+TDR+TXV | EL296UH090XV36C* | 33,200 | $3,984 |
| Yes | 207436271 | LENNOX | SL25XPV-036-230A** | C35-48C+TDR+TXV | EL296UH090XV48C* | 33,200 | $3,984 |
| Yes | 207436268 | LENNOX | SL25XPV-036-230A** | C35-48B+TDR+TXV | SL297UH060NV36B* | 33,400 | $4,008 |
| Yes | 207436267 | LENNOX | SL25XPV-036-230A** | C35-48B+TDR+TXV | SL297UH040NV36B* | 33,400 | $4,008 |
| Yes | 207436266 | LENNOX | SL25XPV-036-230A** | C35-48B+TDR+TXV | SL280UH090XV48B* | 33,200 | $3,984 |
| Yes | 207436265 | LENNOX | SL25XPV-036-230A** | C35-48B+TDR+TXV | SL280UH090V48B* | 33,200 | $3,984 |
| Yes | 207436264 | LENNOX | SL25XPV-036-230A** | C35-48B+TDR+TXV | SL280UH090V36B* | 33,200 | $3,984 |
| Yes | 207436263 | LENNOX | SL25XPV-036-230A** | C35-48B+TDR+TXV | SL280UH080NV48B* | 33,000 | $3,960 |
| Yes | 207436262 | LENNOX | SL25XPV-036-230A** | C35-48B+TDR+TXV | EL296UH070XV36B* | 33,400 | $4,008 |
| Yes | 207436261 | LENNOX | SL25XPV-036-230A** | C35-48B+TDR+TXV | EL296UH045XV36B* | 33,400 | $4,008 |
| Yes | 207436193 | LENNOX | SL25XPV-024-230A** | CH35-42C+TDR+TXV | SLP99UH110XV60C* | 23,800 | $2,856 |
| Yes | 207436191 | LENNOX | SL25XPV-024-230A** | CH35-42C+TDR+TXV | SLP99UH090XV48C* | 23,800 | $2,856 |
| Yes | 207436190 | LENNOX | SL25XPV-024-230A** | CH35-42C+TDR+TXV | SLP99UH090XV36C* | 23,800 | $2,856 |
| Yes | 207436189 | LENNOX | SL25XPV-024-230A** | CH35-42C+TDR+TXV | SL297UH080NV60C* | 23,800 | $2,856 |
| Yes | 207436192 | LENNOX | SL25XPV-024-230A** | CH35-42C+TDR+TXV | SLP99UH090XV60C* | 23,800 | $2,856 |
| Yes | 207436269 | LENNOX | SL25XPV-036-230A** | C35-48B+TDR+TXV | SLP99UH070XV36B* | 33,400 | $4,008 |
| Yes | 207436188 | LENNOX | SL25XPV-024-230A** | CH35-42C+TDR+TXV | SL297UH080NV48C* | 23,800 | $2,856 |
| Yes | 207436186 | LENNOX | SL25XPV-024-230A** | CH35-42C+TDR+TXV | SL280UH110V60C* | 23,800 | $2,856 |
| Yes | 207436187 | LENNOX | SL25XPV-024-230A** | CH35-42C+TDR+TXV | SL280UH110XV60C* | 23,800 | $2,856 |
| Yes | 207436184 | LENNOX | SL25XPV-024-230A** | CH35-42C+TDR+TXV | SL280UH090XV60C* | 23,800 | $2,856 |
| Yes | 207436185 | LENNOX | SL25XPV-024-230A** | CH35-42C+TDR+TXV | SL280UH100NV60C* | 23,800 | $2,856 |
| Yes | 207436183 | LENNOX | SL25XPV-024-230A** | CH35-42C+TDR+TXV | SL280UH090V60C* | 23,800 | $2,856 |
| Yes | 207436182 | LENNOX | SL25XPV-024-230A** | CH35-42C+TDR+TXV | SL280UH080NV60C* | 23,600 | $2,832 |
| Yes | 207436181 | LENNOX | SL25XPV-024-230A** | CH35-42C+TDR+TXV | EL296UH110XV60C* | 23,800 | $2,856 |
| Yes | 207436176 | LENNOX | SL25XPV-024-230A** | CH35-42B+TDR+TXV | SLP99UH070XV36B* | 23,600 | $2,832 |
| Yes | 207436179 | LENNOX | SL25XPV-024-230A** | CH35-42C+TDR+TXV | EL296UH090XV60C* | 23,800 | $2,856 |
| Yes | 207436178 | LENNOX | SL25XPV-024-230A** | CH35-42C+TDR+TXV | EL296UH090XV48C* | 23,800 | $2,856 |
| Yes | 207436175 | LENNOX | SL25XPV-024-230A** | CH35-42B+TDR+TXV | SL297UH060NV36B* | 23,600 | $2,832 |
| Yes | 207436174 | LENNOX | SL25XPV-024-230A** | CH35-42B+TDR+TXV | SL297UH040NV36B* | 23,400 | $2,808 |
| Yes | 207436173 | LENNOX | SL25XPV-024-230A** | CH35-42B+TDR+TXV | SL280UH090XV48B* | 23,600 | $2,832 |
| Yes | 207436180 | LENNOX | SL25XPV-024-230A** | CH35-42C+TDR+TXV | EL296UH110XV48C* | 23,800 | $2,856 |
| Yes | 207436177 | LENNOX | SL25XPV-024-230A** | CH35-42C+TDR+TXV | EL296UH090XV36C* | 23,800 | $2,856 |
| Yes | 207436172 | LENNOX | SL25XPV-024-230A** | CH35-42B+TDR+TXV | SL280UH090V48B* | 23,600 | $2,832 |
| Yes | 207436169 | LENNOX | SL25XPV-024-230A** | CH35-42B+TDR+TXV | EL296UH070XV36B* | 23,600 | $2,832 |
| Yes | 207436171 | LENNOX | SL25XPV-024-230A** | CH35-42B+TDR+TXV | SL280UH090V36B* | 23,400 | $2,808 |
| Yes | 207436156 | LENNOX | SL25XPV-024-230A** | C35-36B+TDR+TXV | SLP99UH070XV36B* | 24,200 | $2,904 |
| Yes | 207436170 | LENNOX | SL25XPV-024-230A** | CH35-42B+TDR+TXV | SL280UH080NV48B* | 23,400 | $2,808 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 207436168 | LENNOX | SL25XPV-024-230A** | CH35-42B+TDR+TXV | EL296UH045XV36B* | 23,600 | $2,832 |
| Yes | 207436155 | LENNOX | SL25XPV-024-230A** | C35-36B+TDR+TXV | SL297UH060NV36B* | 24,200 | $2,904 |
| Yes | 207436154 | LENNOX | SL25XPV-024-230A** | C35-36B+TDR+TXV | SL297UH040NV36B* | 24,200 | $2,904 |
| Yes | 207436150 | LENNOX | SL25XPV-024-230A** | C35-36B+TDR+TXV | SL280UH080NV48B* | 24,200 | $2,904 |
| Yes | 207436149 | LENNOX | SL25XPV-024-230A** | C35-36B+TDR+TXV | EL296UH070XV36B* | 24,200 | $2,904 |
| Yes | 207436153 | LENNOX | SL25XPV-024-230A** | C35-36B+TDR+TXV | SL280UH090XV48B* | 24,200 | $2,904 |
| Yes | 207436152 | LENNOX | SL25XPV-024-230A** | C35-36B+TDR+TXV | SL280UH090V48B* | 24,200 | $2,904 |
| Yes | 207436151 | LENNOX | SL25XPV-024-230A** | C35-36B+TDR+TXV | SL280UH090V36B* | 24,200 | $2,904 |
| Yes | 207436148 | LENNOX | SL25XPV-024-230A** | C35-36B+TDR+TXV | EL296UH045XV36B* | 24,200 | $2,904 |
| Yes | 207436147 | LENNOX | SL25XPV-024-230A** | C35-36A+TDR+TXV | SL280UH070XV36A* | 24,200 | $2,904 |
| Yes | 207436166 | LENNOX | SL25XPV-024-230A** | CBA38MV-030-230*+TDR | | 25,200 | $3,024 |
| Yes | 207436146 | LENNOX | SL25XPV-024-230A** | C35-36A+TDR+TXV | SL280UH060NV36A* | 24,200 | $2,904 |
| Yes | 207436144 | LENNOX | SL25XPV-048-230A** | CBA38MV-060-230*+TDR | | 43,000 | $5,160 |
| Yes | 207436142 | LENNOX | SL25XPV-024-230A** | CBA38MV-042-230*+TDR | | 25,200 | $3,024 |
| Yes | 207436167 | LENNOX | SL25XPV-024-230A** | CBA38MV-036-230*+TDR | | 25,400 | $3,048 |
| Yes | 205747588 | LENNOX | MLB048S4M-1P | Heat pump without ducts | | 30,000 | $3,600 |
| Yes | 207699109 | LENNOX | MLB048S4M-2P | Combination heat pumps with or without ducts | | 29,000 | $3,480 |
| Yes | 207683526 | LENNOX | MLB018S4S-1P | MMDB018S4-2P | | 12,700 | $1,524 |
| Yes | 207683529 | LENNOX | MLB018S4S-1P | MCFB018S4-2P | | 12,000 | $1,440 |
| Yes | 207683534 | LENNOX | MLB024S4S-1P | M33C024S4-1P | | 15,000 | $1,800 |
| Yes | 205782163 | LENNOX | MLB048S4S-1P | MCFA048S4-2P | | 35,000 | $4,200 |
| Yes | 205747589 | LENNOX | MLB048S4M-1P | Heat pump with ducts | | 28,000 | $3,360 |
| Yes | 206717009 | LG | LMU480HHV | Heat pump with ducts | | 35,000 | $4,200 |
| Yes | 206717014 | LG | LMU480HHV | Combination heat pumps with or without ducts | | 35,000 | $4,200 |
| Yes | 206717002 | LG | LMU480HHV | Heat pump without ducts | | 35,000 | $4,200 |
| Yes | 206717012 | LG | LMU361HHV | Combination heat pumps with or without ducts | | 29,600 | $3,552 |
| Yes | 206717006 | LG | LMU361HHV | Heat pump with ducts | | 29,600 | $3,552 |
| Yes | 206717007 | LG | LMU361HHV | Heat pump without ducts | | 29,600 | $3,552 |
| Yes | 206717013 | LG | LMU421HHV | Combination heat pumps with or without ducts | | 31,600 | $3,792 |
| Yes | 206717008 | LG | LMU421HHV | Heat pump with ducts | | 31,600 | $3,792 |
| Yes | 206717001 | LG | LMU421HHV | Heat pump without ducts | | 31,600 | $3,792 |
| Yes | 205967236 | LG | ARUM048GSS5 | Heat pump with ducts | | 36,400 | $4,368 |
| Yes | 205967235 | LG | ARUM048GSS5 | Heat pump without ducts | | 38,500 | $4,620 |
| Yes | 10516997 | LG | LMU240HHV | Combination heat pumps with or without ducts | | 16,300 | $1,956 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205967235 | LG | ARUM048GSS5 | Heat pump without ducts | | 38,500 | $4,620 |
| Yes | 205967235 | LG | ARUM048GSS5 | Heat pump without ducts | | 38,500 | $4,620 |
| Yes | 205967235 | LG | ARUM048GSS5 | Heat pump without ducts | | 38,500 | $4,620 |
| Yes | 205967235 | LG | ARUM048GSS5 | Heat pump without ducts | | 38,500 | $4,620 |
| Yes | 208132537 | LG | LMU183HV | Combination heat pumps with or without ducts | | 13,600 | $1,632 |
| Yes | 208131884 | LG | LMU183HV | Heat pump without ducts | | 13,800 | $1,656 |
| Yes | 208131885 | LG | LMU183HV | Heat pump with ducts | | 13,400 | $1,608 |
| Yes | 206221543 | LG | LMU180HV | Heat pump without ducts | | 14,500 | $1,740 |
| Yes | 205967237 | LG | ARUM036GSS5 | Heat pump without ducts | | 26,000 | $3,120 |
| Yes | 205967235 | LG | ARUM048GSS5 | Heat pump without ducts | | 35,000 | $4,200 |
| Yes | 203161353 | LG | LUU249HV | LHN248HV | | 17,500 | $2,100 |
| Yes | 10445376 | LG | LMU300HHV | Heat pump without ducts | | 18,900 | $2,268 |
| Yes | 10445374 | LG | LMU240HHV | Heat pump without ducts | | 17,400 | $2,088 |
| Yes | 10445372 | LG | LMU180HHV | Heat pump without ducts | | 14,700 | $1,764 |
| Yes | 10443472 | LG | LMU360HHV | Heat pump without ducts | | 28,000 | $3,360 |
| Yes | 10443471 | LG | LMU420HHV | Heat pump without ducts | | 29,000 | $3,480 |
| Yes | 205967235 | LG | ARUM048GSS5 | Heat pump without ducts | | 35,000 | $4,200 |
| Yes | 205967239 | LG | ARUM048GSS5 | Combination heat pumps with or without ducts | | 35,400 | $4,248 |
| Yes | 205967240 | LG | ARUM036GSS5 | Combination heat pumps with or without ducts | | 27,000 | $3,240 |
| Yes | 205967238 | LG | ARUM036GSS5 | Heat pump with ducts | | 28,000 | $3,360 |
| Yes | 10444103 | LG | LMU420HHV | Combination heat pumps with or without ducts | | 29,000 | $3,480 |
| Yes | 205788777 | LG | LUU480HHV | LVN480HV | | 30,800 | $3,696 |
| Yes | 206221549 | LG | LMU180HV | Heat pump with ducts | | 13,000 | $1,560 |
| Yes | 206221550 | LG | LMU180HV | Combination heat pumps with or without ducts | | 13,700 | $1,644 |
| Yes | 203162003 | LG | LUU369HV | LVN361HV4 | | 23,800 | $2,856 |
| Yes | 205788771 | LG | LUU480HHV | LCN489HV | | 32,600 | $3,912 |
| Yes | 205788770 | LG | LUU420HHV | LHN428HV | | 28,400 | $3,408 |
| Yes | 205788766 | LG | LUU180HHV | LDN187HV4 | | 12,200 | $1,464 |
| Yes | 205788767 | LG | LUU240HHV | LHN248HV | | 18,200 | $2,184 |
| Yes | 205788776 | LG | LUU420HHV | LVN420HV | | 29,200 | $3,504 |
| Yes | 205788765 | LG | LUU420HHV | LCN429HV | | 29,200 | $3,504 |
| Yes | 205788772 | LG | LUU480HHV | LHN488HV | | 31,600 | $3,792 |
| Yes | 203161150 | LG | LUU249HV | LCN248HV | | 17,500 | $2,100 |
| Yes | 203161352 | LG | LUU249HV | LVN241HV4 | | 18,700 | $2,244 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 10445111 | LG | LMU360HHV | Combination heat pumps with or without ducts | | 27,500 | $3,300 |
| Yes | 10443475 | LG | LMU360HHV | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 10443474 | LG | LMU420HHV | Heat pump with ducts | | 29,000 | $3,480 |
| Yes | 9680934 | LG | LAU180HYV2 | LAN180HYV2 | | 13,500 | $1,620 |
| Yes | 10516996 | LG | LMU180HHV | Combination heat pumps with or without ducts | | 14,700 | $1,764 |
| Yes | 10525928 | LG | LMU300HHV | Combination heat pumps with or without ducts | | 18,300 | $2,196 |
| Yes | 10445375 | LG | LMU240HHV | Heat pump with ducts | | 15,200 | $1,824 |
| Yes | 10445377 | LG | LMU300HHV | Heat pump with ducts | | 17,700 | $2,124 |
| Yes | 203161351 | LG | LUU189HV | LVN181HV4 | | 13,000 | $1,560 |
| Yes | 203161354 | LG | LUU369HV | LHN368HV | | 24,000 | $2,880 |
| Yes | 10445373 | LG | LMU180HHV | Heat pump with ducts | | 14,700 | $1,764 |
| Yes | 204825183 | LG | LSU303HLV3 | LSN303HLV3 | | 19,700 | $2,364 |
| Yes | 204825184 | LG | LSU363HLV3 | LSN363HLV3 | | 21,400 | $2,568 |
| Yes | 210693399 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CSCF3642N6D*+TXV | G*VM971205DNB* | 21,600 | $2,592 |
| Yes | 210693398 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CSCF3642N6D*+TXV | G*VM971005CNB* | 21,600 | $2,592 |
| Yes | 210693397 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CSCF3642N6D*+TXV | G*VM970804CNB* | 21,600 | $2,592 |
| Yes | 210693396 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CSCF3642N6D*+TXV | G*VM970803BNB* | 21,600 | $2,592 |
| Yes | 210693395 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CSCF3642N6D*+TXV | G*VM970603BNB* | 21,600 | $2,592 |
| Yes | 210693394 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CSCF3642N6D*+TXV | G*VC961205DNB* | 21,600 | $2,592 |
| Yes | 210693393 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CSCF3642N6D*+TXV | G*VC961005CNB* | 21,600 | $2,592 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 210693392 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CSCF3642N6D*+TXV | G*VS960805CUA* | 21,600 | $2,592 |
| Yes | 210693391 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CSCF3642N6D*+TXV | G*VC960804CNB* | 21,600 | $2,592 |
| Yes | 210693390 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CSCF3642N6D*+TXV | G*VC960803BNB* | 21,600 | $2,592 |
| Yes | 210693389 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CSCF3642N6D*+TXV | G*VC960603BNB* | 21,600 | $2,592 |
| Yes | 210693388 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CSCF3642N6D*+TXV | G*VS960603BUA* | 21,600 | $2,592 |
| Yes | 210693387 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CSCF3642N6D*+TXV | G*VC960403BNB* | 21,600 | $2,592 |
| Yes | 210693380 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CSCF3642N6D*+MBVC1601**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210693379 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CSCF3642N6D*+MBVC1201**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210693378 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CHPF3743C6B*+TXV | G*VM971005CNB* | 21,600 | $2,592 |
| Yes | 210693377 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CHPF3743C6B*+TXV | G*VM970804CNB* | 21,600 | $2,592 |
| Yes | 210693376 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CHPF3743C6B*+TXV | G*VM970803BNB* | 21,600 | $2,592 |
| Yes | 210693375 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CHPF3743C6B*+TXV | G*VM970603BNB* | 21,600 | $2,592 |
| Yes | 210693374 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CHPF3743C6B*+TXV | G*VC961005CNB* | 21,600 | $2,592 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 210693373 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CHPF3743C6B*+TXV | G*VS960805CUA* | 21,600 | $2,592 |
| Yes | 210693372 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CHPF3743C6B*+TXV | G*VC960804CNB* | 21,600 | $2,592 |
| Yes | 210693371 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CHPF3743C6B*+TXV | G*VC960803BNB* | 21,600 | $2,592 |
| Yes | 210693370 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CHPF3743C6B*+TXV | G*VC960603BNB* | 21,600 | $2,592 |
| Yes | 210693369 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CHPF3743C6B*+TXV | G*VS960603BUA* | 21,600 | $2,592 |
| Yes | 210693368 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CHPF3743C6B*+TXV | G*VC960403BNB* | 21,600 | $2,592 |
| Yes | 210693361 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CHPF3743C6B*+MBVC1601**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210693360 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CHPF3743C6B*+MBVC1201**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210693359 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CHPF3642C6C*+TXV | G*VM971005CNB* | 21,600 | $2,592 |
| Yes | 210693358 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CHPF3642C6C*+TXV | G*VM970804CNB* | 21,600 | $2,592 |
| Yes | 210693357 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CHPF3642C6C*+TXV | G*VM970803BNB* | 21,600 | $2,592 |
| Yes | 210693356 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CHPF3642C6C*+TXV | G*VM970603BNB* | 21,600 | $2,592 |
| Yes | 210693355 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CHPF3642C6C*+TXV | G*VC961005CNB* | 21,600 | $2,592 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 210693354 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CHPF3642C6C*+TXV | G*VS960805CUA* | 21,600 | $2,592 |
| Yes | 210693353 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CHPF3642C6C*+TXV | G*VC960804CNB* | 21,600 | $2,592 |
| Yes | 210693352 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CHPF3642C6C*+TXV | G*VC960803BNB* | 21,600 | $2,592 |
| Yes | 210693351 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CHPF3642C6C*+TXV | G*VC960603BNB* | 21,600 | $2,592 |
| Yes | 210693350 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CHPF3642C6C*+TXV | G*VS960603BUA* | 21,600 | $2,592 |
| Yes | 210693349 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CHPF3642C6C*+TXV | G*VC960403BNB* | 21,600 | $2,592 |
| Yes | 210693342 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CHPF3642C6C*+MBVC1601**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210693341 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CHPF3642C6C*+MBVC1201**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210693340 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CA*F3743*6D*+TXV | G*VM971205DNB* | 21,600 | $2,592 |
| Yes | 210693339 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CA*F3743*6D*+TXV | G*VM971005CNB* | 21,600 | $2,592 |
| Yes | 210693338 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CA*F3743*6D*+TXV | G*VM970804CNB* | 21,600 | $2,592 |
| Yes | 210693337 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CA*F3743*6D*+TXV | G*VM970803BNB* | 21,600 | $2,592 |
| Yes | 210693336 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CA*F3743*6D*+TXV | G*VM970603BNB* | 21,600 | $2,592 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 210693335 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CA*F3743*6D*+TXV | G*VC961205DNB* | 21,600 | $2,592 |
| Yes | 210693334 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CA*F3743*6D*+TXV | G*VC961005CNB* | 21,600 | $2,592 |
| Yes | 210693333 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CA*F3743*6D*+TXV | G*VS960805CUA* | 21,600 | $2,592 |
| Yes | 210693332 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CA*F3743*6D*+TXV | G*VC960804CNB* | 21,600 | $2,592 |
| Yes | 210693331 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CA*F3743*6D*+TXV | G*VC960803BNB* | 21,600 | $2,592 |
| Yes | 210693330 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CA*F3743*6D*+TXV | G*VC960603BNB* | 21,600 | $2,592 |
| Yes | 210693329 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CA*F3743*6D*+TXV | G*VS960603BUA* | 21,600 | $2,592 |
| Yes | 210693328 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CA*F3743*6D*+TXV | G*VC960403BNB* | 21,600 | $2,592 |
| Yes | 210607415 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CA*F3743*6D*+MBVC1601**-1A*+TX | | 21,600 | $2,592 |
| Yes | 210693321 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CA*F3743*6D*+MBVC1201**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210693320 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CA*F3137*6A*+TXV | G*VM970803BNB* | 21,600 | $2,592 |
| Yes | 210693319 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CA*F3137*6A*+TXV | G*VM970603BNB* | 21,600 | $2,592 |
| Yes | 210693318 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CA*F3137*6A*+TXV | G*VC960803BNB* | 21,600 | $2,592 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 210693317 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CA*F3137*6A*+TXV | G*VC960603BNB* | 21,600 | $2,592 |
| Yes | 210693316 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CA*F3137*6A*+TXV | G*VS960603BUA* | 21,600 | $2,592 |
| Yes | 210693315 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CA*F3137*6A*+TXV | G*VC960403BNB* | 21,600 | $2,592 |
| Yes | 210693312 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | CA*F3137*6A*+MBVC1201**-1A*+TXV | | 21,600 | $2,592 |
| Yes | 210609975 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | AMVE48DP1400A* | | 21,600 | $2,592 |
| Yes | 210609974 | LIBERTY HEATING & AIR CONDITIONING | ASZV903610A* | AMVE36CP1400A* | | 21,600 | $2,592 |
| Yes | 211207006 | LUXAIRE | HL20B4821 | XAMC48HE3N1+CC | LPLC100C16MP13 | 41,500 | $4,980 |
| Yes | 211207004 | LUXAIRE | HL20B4821 | XAMC48HE3N1+CC | LPLC080C16MP13 | 41,500 | $4,980 |
| Yes | 211206999 | LUXAIRE | HL20B4821 | XAMC48HE3N1+CC | TPLC100C16MP13 | 41,500 | $4,980 |
| Yes | 211206994 | LUXAIRE | HL20B4821 | XAMC48HE3N1+CC | TPLC080C16MP13 | 41,500 | $4,980 |
| Yes | 211206989 | LUXAIRE | HL20B4821 | XAMC48HE3N1+CC | TMLV100C16MP12 | 41,500 | $4,980 |
| Yes | 211206984 | LUXAIRE | HL20B4821 | XAMC48HE3N1+CC | TM8V080C16MP12 | 41,500 | $4,980 |
| Yes | 211206979 | LUXAIRE | HL20B4821 | XAMC48HE3N1+CC | TM8V100C16MP12 | 41,500 | $4,980 |
| Yes | 211206977 | LUXAIRE | HL20B4821 | XAMC48HE3N1+CC | LPLC120C20MP13 | 41,500 | $4,980 |
| Yes | 211206975 | LUXAIRE | HL20B4821 | XAMC48HE3N1+CC | LPLC100C20MP13 | 41,500 | $4,980 |
| Yes | 211206971 | LUXAIRE | HL20B4821 | XAMC48HE3N1+CC | TPLC120C20MP13 | 41,500 | $4,980 |
| Yes | 211206966 | LUXAIRE | HL20B4821 | XAMC48HE3N1+CC | TPLC100C20MP13 | 41,500 | $4,980 |
| Yes | 211206961 | LUXAIRE | HL20B4821 | XAMC48HE3N1+CC | TMLV120C20MP12 | 41,500 | $4,980 |
| Yes | 211206956 | LUXAIRE | HL20B4821 | XAMC48HE3N1+CC | TM8V100C20MP12 | 41,500 | $4,980 |
| Yes | 211206951 | LUXAIRE | HL20B4821 | XAMC48HE3N1+CC | TM8V120C20MP12 | 41,500 | $4,980 |
| Yes | 211206949 | LUXAIRE | HL20B4821 | XAMC48HE3N1+CC | LP9C080C16MP13 | 41,500 | $4,980 |
| Yes | 211206944 | LUXAIRE | HL20B4821 | XAMC48HE3N1+CC | TP9C080C16MP13 | 41,500 | $4,980 |
| Yes | 211206939 | LUXAIRE | HL20B4821 | XAMC48HE3N1+CC | TM9V080C16MP12 | 41,500 | $4,980 |
| Yes | 211206937 | LUXAIRE | HL20B4821 | XAMC48HE3N1+CC | LP9C100C16MP13 | 41,500 | $4,980 |
| Yes | 211206932 | LUXAIRE | HL20B4821 | XAMC48HE3N1+CC | TP9C100C16MP13 | 41,500 | $4,980 |
| Yes | 211206927 | LUXAIRE | HL20B4821 | XAMC48HE3N1+CC | TM9V100C16MP12 | 41,500 | $4,980 |
| Yes | 211206925 | LUXAIRE | HL20B4821 | XAMC48HE3N1+CC | LP9C100C20MP13 | 41,500 | $4,980 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 211206920 | LUXAIRE | HL20B4821 | XAMC48HE3N1+CC | TP9C100C20MP13 | 41,500 | $4,980 |
| Yes | 211206915 | LUXAIRE | HL20B4821 | XAMC48HE3N1+CC | TM9V100C20MP12 | 41,500 | $4,980 |
| Yes | 211206913 | LUXAIRE | HL20B6021 | XAMC60HE4N1+CC | LP9C100C20MP13 | 47,000 | $5,640 |
| Yes | 211206908 | LUXAIRE | HL20B6021 | XAMC60HE4N1+CC | TP9C100C20MP13 | 47,000 | $5,640 |
| Yes | 211206903 | LUXAIRE | HL20B6021 | XAMC60HE4N1+CC | TM9V100C20MP12 | 47,000 | $5,640 |
| Yes | 211206854 | LUXAIRE | HL20B2421 | XAMB24DE1N1+CC | LPLC080B12MP13 | 23,000 | $2,760 |
| Yes | 211206850 | LUXAIRE | HL20B2421 | XAMB24DE1N1+CC | TPLC080B12MP13 | 23,000 | $2,760 |
| Yes | 211206845 | LUXAIRE | HL20B2421 | XAMB24DE1N1+CC | TM8V080B12MP12 | 23,000 | $2,760 |
| Yes | 211206843 | LUXAIRE | HL20B2421 | XAMB24DE1N1+CC | LP9C060B12MP13 | 23,200 | $2,784 |
| Yes | 211206838 | LUXAIRE | HL20B2421 | XAMB24DE1N1+CC | TP9C060B12MP13 | 23,200 | $2,784 |
| Yes | 211206833 | LUXAIRE | HL20B2421 | XAMB24DE1N1+CC | TM9V060B12MP12 | 23,200 | $2,784 |
| Yes | 211010191 | LUXAIRE | HL20B6021 | JHVVD60HE4C2N1+CC | | 46,500 | $5,580 |
| Yes | 10309047 | LUXAIRE | HL20B2421 | CM25BE1A1+MVC12BN21 | | 22,400 | $2,688 |
| Yes | 10309095 | LUXAIRE | HL20B3621 | CM38CE2A1+MVC16CN21 | | 33,400 | $4,008 |
| Yes | 10309103 | LUXAIRE | HL20B4821 | AVV50DE321 | | 44,000 | $5,280 |
| Yes | 10309111 | LUXAIRE | HL20B4821 | CM50CE3A1+MVC16CN21 | | 43,500 | $5,220 |
| Yes | 10309107 | LUXAIRE | HL20B4821 | CM50DE3A1+MVC20DN21 | | 42,500 | $5,100 |
| Yes | 10525685 | LUXAIRE | HL20B3621 | CM38CE2A1 | LP9C080C16MP13 | 31,800 | $3,816 |
| Yes | 10525686 | LUXAIRE | HL20B3621 | CM38CE2A1 | LP9C100C16MP13 | 31,600 | $3,792 |
| Yes | 10525687 | LUXAIRE | HL20B3621 | CM38CE2A1 | LPLC080C16MP13 | 33,400 | $4,008 |
| Yes | 10525688 | LUXAIRE | HL20B3621 | CM38CE2A1 | LPLC100C16MP13 | 33,400 | $4,008 |
| Yes | 10525691 | LUXAIRE | HL20B3621 | CM38CE2A1 | TM9V080C16MP12 | 31,800 | $3,816 |
| Yes | 10525690 | LUXAIRE | HL20B3621 | CM38CE2A1 | TM8V100C16MP12 | 33,400 | $4,008 |
| Yes | 10525692 | LUXAIRE | HL20B3621 | CM38CE2A1 | TM9V100C16MP12 | 31,600 | $3,792 |
| Yes | 10525694 | LUXAIRE | HL20B3621 | CM38CE2A1 | TMLV100C16MP12 | 33,400 | $4,008 |
| Yes | 10525693 | LUXAIRE | HL20B3621 | CM38CE2A1 | TMLV080C16MP12 | 33,400 | $4,008 |
| Yes | 10525695 | LUXAIRE | HL20B3621 | CM38CE2A1 | TP9C080C16MP13 | 31,800 | $3,816 |
| Yes | 10525696 | LUXAIRE | HL20B3621 | CM38CE2A1 | TP9C100C16MP13 | 31,600 | $3,792 |
| Yes | 10525698 | LUXAIRE | HL20B3621 | CM38CE2A1 | TPLC100C16MP13 | 33,400 | $4,008 |
| Yes | 10525697 | LUXAIRE | HL20B3621 | CM38CE2A1 | TPLC080C16MP13 | 33,400 | $4,008 |
| Yes | 10525702 | LUXAIRE | HL20B4821 | CM50CE3A1 | LP9C100C20MP13 | 44,000 | $5,280 |
| Yes | 10525703 | LUXAIRE | HL20B4821 | CM50CE3A1 | LPLC080C16MP13 | 44,000 | $5,280 |
| Yes | 10525704 | LUXAIRE | HL20B4821 | CM50CE3A1 | LPLC100C16MP13 | 44,000 | $5,280 |
| Yes | 10525705 | LUXAIRE | HL20B4821 | CM50CE3A1 | LPLC100C20MP13 | 44,000 | $5,280 |
| Yes | 10525707 | LUXAIRE | HL20B4821 | CM50CE3A1 | TM8V080C16MP12 | 44,000 | $5,280 |
| Yes | 10525709 | LUXAIRE | HL20B4821 | CM50CE3A1 | TM8V100C20MP12 | 44,000 | $5,280 |
| Yes | 10525706 | LUXAIRE | HL20B4821 | CM50CE3A1 | LPLC120C20MP13 | 44,000 | $5,280 |
| Yes | 10525714 | LUXAIRE | HL20B4821 | CM50CE3A1 | TMLV080C16MP12 | 44,000 | $5,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 10525713 | LUXAIRE | HL20B4821 | CM50CE3A1 | TM9V100C20MP12 | 44,000 | $5,280 |
| Yes | 10525717 | LUXAIRE | HL20B4821 | CM50CE3A1+CC | TMLV120C20MP12 | 44,000 | $5,280 |
| Yes | 10525716 | LUXAIRE | HL20B4821 | CM50CE3A1 | TMLV100C20MP12 | 44,000 | $5,280 |
| Yes | 10525720 | LUXAIRE | HL20B4821 | CM50CE3A1 | TP9C100C20MP13 | 44,000 | $5,280 |
| Yes | 10525721 | LUXAIRE | HL20B4821 | CM50CE3A1 | TPLC080C16MP13 | 44,000 | $5,280 |
| Yes | 10525722 | LUXAIRE | HL20B4821 | CM50CE3A1 | TPLC100C16MP13 | 44,000 | $5,280 |
| Yes | 10525723 | LUXAIRE | HL20B4821 | CM50CE3A1 | TPLC100C20MP13 | 44,000 | $5,280 |
| Yes | 10525726 | LUXAIRE | HL20B4821 | CM50DE3A1 | TM9V120D20MP12 | 44,000 | $5,280 |
| Yes | 10525725 | LUXAIRE | HL20B4821 | CM50DE3A1 | LP9C120D20MP13 | 44,000 | $5,280 |
| Yes | 10525727 | LUXAIRE | HL20B4821 | CM50DE3A1 | TP9C120D20MP13 | 44,000 | $5,280 |
| Yes | 201982918 | LUXAIRE | HL20B3621 | AVV38CE221 | | 33,400 | $4,008 |
| Yes | 10525699 | LUXAIRE | HL20B4821 | AVV50CE321 | | 43,500 | $5,220 |
| Yes | 10525689 | LUXAIRE | HL20B3621 | CM38CE2A1 | TM8V080C16MP12 | 33,400 | $4,008 |
| Yes | 10525708 | LUXAIRE | HL20B4821 | CM50CE3A1 | TM8V100C16MP12 | 44,000 | $5,280 |
| Yes | 10525710 | LUXAIRE | HL20B4821 | CM50CE3A1 | TM8V120C20MP12 | 44,000 | $5,280 |
| Yes | 10525715 | LUXAIRE | HL20B4821 | CM50CE3A1 | TMLV100C16MP12 | 44,000 | $5,280 |
| Yes | 10525724 | LUXAIRE | HL20B4821 | CM50CE3A1 | TPLC120C20MP13 | 44,000 | $5,280 |
| Yes | 212348362 | MAXI AIR | NE-T52-SUPAE18E | NE-T52-SUPAE18I | | 15,000 | $1,800 |
| Yes | 210426581 | MAXI AIR | MAXS-4260 | AHMS-6020 | | 42,000 | $5,040 |
| Yes | 206799639 | MAXI AIR CENTRAL | CLASS24CC | AHAN3615 | | 15,400 | $1,848 |
| Yes | 210372390 | MAXI AIR CENTRAL | CLASS30CC | AHAN3615 | | 16,800 | $2,016 |
| Yes | 204012250 | MAX-R | MAX-R(MZ)27K30 | Heat pump without ducts | | 18,000 | $2,160 |
| Yes | 207338196 | MAX-R | MAX-R24K35MZGR | Heat pump without ducts | | 17,900 | $2,148 |
| Yes | 207338179 | MAX-R | Max-R36k30CT-inv(out) | Max-R36k30CT-inv-(in) | | 24,400 | $2,928 |
| Yes | 207338195 | MAX-R | MAX-R18K35MZGR | Heat pump without ducts | | 17,000 | $2,040 |
| Yes | 207338182 | MAX-R | Max-R60k30CT-inv(out) | Max-R48k30CT-inv-(in) | | 32,800 | $3,936 |
| Yes | 205982980 | MAX-R | MAX-R18K35GR38(OUT) | MAX-R18K35GR38(IN) | | 14,200 | $1,704 |
| Yes | 207338181 | MAX-R | Max-R60k30CT-inv(out) | Max-R60k30CT-inv-(in) | | 37,200 | $4,464 |
| Yes | 207338180 | MAX-R | Max-R36k30CT-inv(out) | Max-R24k30CT-inv-(in) | | 16,300 | $1,956 |
| Yes | 208101911 | MDV | MOD30U-30HFN1-MR0(X) | MAC-36HWDN1-MN0 | | 22,600 | $2,712 |
| Yes | 209960477 | MDV | MOE30U-55HFN1-MQ3 | MVC-60HWFN1-MR0 | | 42,000 | $5,040 |
| Yes | 210191039 | MDV | MOE30U-48HFN1-M-[X] | MVC-48HWFN1-MQ3 | | 36,000 | $4,320 |
| Yes | 209960480 | MDV | MOD30U-30HFN1-MP0-Q1W | MVC-30HWFN1-MQ1W | | 21,000 | $2,520 |
| Yes | 210135403 | MDV | MOD30-24HFN1-MU0Q1W | MVC-23HWFN1-MQ1W | | 18,400 | $2,208 |
| Yes | 209960479 | MDV | MOX430-17HFN1-MT0Q1W | MVC-18HWFN1-MQ1W | | 15,000 | $1,800 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 209960476 | MDV | MOE30U-55HFN1-M | MVC-60HWFN1-M | | 42,000 | $5,040 |
| Yes | 207699011 | MDV | MOE30U-48HFN1-M-[X1] | MVC-48HWFN1-M | | 36,000 | $4,320 |
| Yes | 207699008 | MDV | MOD30-24HFN1-MW | MVC-24HWFN1-M | | 19,200 | $2,304 |
| Yes | 207699007 | MDV | MOX430U-18HFN1-M | MVC-18HWFN1-M | | 13,500 | $1,620 |
| Yes | 209960478 | MDV | MOE30U-55HFN1-M-[X](GA) | MVC-60HWFN1-M(GA) | | 41,000 | $4,920 |
| Yes | 208128249 | MDV | MOE30U-48HFN1-M-[X](GA) | MVC-48HWFN1-M(GA) | | 38,000 | $4,560 |
| Yes | 208128248 | MDV | MOE30U-36HFN1-M(GA) | MVC-36HWFN1-M(GA) | | 28,600 | $3,432 |
| Yes | 207802615 | MDV | MOD30-24HFN1-MU0W | MVC-23HWFN1-M | | 16,900 | $2,028 |
| Yes | 207803596 | MDV | MOX430-17HFN1-MT0W | MVC-18HWFN1-MW(GA) | | 15,400 | $1,848 |
| Yes | 210321397 | MDV | MOD30-24HFN1-MU0W | MAC-24HWDN1-MN0-N | | 22,000 | $2,640 |
| Yes | 202415590 | MDV | MOD30-22HFN1-MW5W | MSAB2F-22HRFN1-MW5W | | 15,400 | $1,848 |
| Yes | 10028966 | MDV | MOD30-24HFN1-MT0W* | MTIU-24HWFN1-M | | 17,200 | $2,064 |
| Yes | 201810023 | MDV | M3OH-27HFN1-M | CS11M-09HRFN1-MX0W(A) | | 18,000 | $2,160 |
| Yes | 205767337 | MDV | MOE30U-36HFN1-M-[X] | MTI-36HWFN1-M | | 28,000 | $3,360 |
| Yes | 205306855 | MDV | M5OG-48HFN1-M-[X] | MTIU-09HWFN1-M | | 28,000 | $3,360 |
| Yes | 204829821 | MDV | MOE30U-48HFN1-M-[X] | MTI-48HWFN1-M | | 33,000 | $3,960 |
| Yes | 204829817 | MDV | MOE30U-48HFN1-M-[X] | MCD-48HRFN1-M(D) | | 35,000 | $4,200 |
| Yes | 205782859 | MDV | MOD30-24HFN1-MT0W | MVB-24HWFN1-M | | 17,500 | $2,100 |
| Yes | 205823026 | MDV | MOE30U-32HFN1-M-[X] | MTI-32HWFN1-M | | 25,000 | $3,000 |
| Yes | 206143051 | MDV | MOD30-24HFN1-MU0W | MVB-24HWFN1-M | | 16,500 | $1,980 |
| Yes | 205993855 | MDV | MOD30-24HFN1-MU0W | MSEPD-24HRFN1-MU0W | | 19,800 | $2,376 |
| Yes | 206330136 | MDV | MOD30-24HFN1-MU0W | MTIU-24HWFN1-M | | 14,500 | $1,740 |
| Yes | 207338216 | MDV | MOE30U-48HFN1-M-[X](GA) | MCD1-48HRFN1-M(GA) | | 35,000 | $4,200 |
| Yes | 207338217 | MDV | MOE30U-48HFN1-M-[X](GA) | MTI-48HWFN1-M | | 33,000 | $3,960 |
| Yes | 207338215 | MDV | MOE30U-48HFN1-M-[X](GA) | MUE-48HRFN1-M(C) | | 35,000 | $4,200 |
| Yes | 207338214 | MDV | MOE30U-36HFN1-M(GA) | MTI-36HWFN1-M | | 28,000 | $3,360 |
| Yes | 206330134 | MDV | MOD30-24HFN1-MU0W | MUEU-24HRFN1-M(C) | | 14,500 | $1,740 |
| Yes | 206361863 | MDV | MOD30-24HFN1-MU0W | MSAG11D-23HRFN1-MU0W | | 17,000 | $2,040 |
| Yes | 207742580 | MDV | MOD30-24HFN1-MU0W | MVB-24HWFN1-M | | 16,500 | $1,980 |
| Yes | 207742579 | MDV | MOD30-24HFN1-MT0W | MVB-24HWFN1-M | | 17,500 | $2,100 |
| Yes | 207690464 | MDV | MOE31U-36HFN1-M | MVC-36HWFN1-M | | 24,000 | $2,880 |
| Yes | 207690461 | MDV | MOX430U-18HFN1-M | MVC-18HWFN1-M | | 13,000 | $1,560 |
| Yes | 207690462 | MDV | MOD30-24HFN1-MW | MVC-24HWFN1-M | | 16,700 | $2,004 |
| Yes | 206714985 | MDV | M5OG-48HFN1-M-[X]-20 | MTIU-09HWFN1-M | | 28,000 | $3,360 |
| Yes | 206714984 | MDV | M5OG-48HFN1-M-[X]-20 | MSEPB-09HRFN1-MY5W(GA) | | 30,000 | $3,600 |
| Yes | 206716986 | MDV | M2OI-18HFN1-M | MSEPB-09HRFN1-MY5W(GA) | | 12,000 | $1,440 |
| Yes | 205746255 | MDV | MOD30-24HFN1-MU0W | CS11M-23HRFN1-MT0W | | 19,400 | $2,328 |
| Yes | 207641229 | MDV | M4OI-36HFN1-M | MTIU-09HWFN1-M | | 23,000 | $2,760 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 208132543 | MDV | M5OA-55HFN1-M-[X]* | MSAG11B-09HRFN1-MX7W(GA) | | 35,200 | $4,224 |
| Yes | 208132552 | MDV | M5OA-55HFN1-M-[X] | 42 | | 35,400 | $4,248 |
| Yes | 208132544 | MDV | M5OA-55HFN1-M-[X]* | MTIU-09HWFN1-M | | 36,000 | $4,320 |
| Yes | 208132542 | MDV | M5OA-55HFN1-M-[X] | MTIU-09HWFN1-M | | 36,000 | $4,320 |
| Yes | 208132541 | MDV | M5OA-55HFN1-M-[X] | MSEPB-09HRFN1-MY5W(GA) | | 35,000 | $4,200 |
| Yes | 207641238 | MDV | M5OG-48HFN1-M-[X]-20* | MSAG11B-09HRFN1-MX7W(GA) | | 34,000 | $4,080 |
| Yes | 208132553 | MDV | M5OA-55HFN1-M-[X]* | 42 | | 35,600 | $4,272 |
| Yes | 207641250 | MDV | M5OG-48HFN1-M-[X]-20* | MTIU-09HWFN1-M | | 28,000 | $3,360 |
| Yes | 206716993 | MDV | M5OG-48HFN1-M-[X]-20 | 42 | | 29,000 | $3,480 |
| Yes | 207618262 | MDV | M5OG-42HFN1-M-[X] | 42 | | 29,000 | $3,480 |
| Yes | 207617659 | MDV | M5OG-42HFN1-M-[X] | MTIU-09HWFN1-M | | 28,000 | $3,360 |
| Yes | 207617657 | MDV | M5OG-42HFN1-M-[X] | MSEPB-09HRFN1-MY5W(GA) | | 30,000 | $3,600 |
| Yes | 207641249 | MDV | M4OI-36HFN1-M* | 42 | | 22,400 | $2,688 |
| Yes | 207641248 | MDV | M4OI-36HFN1-M* | MTIU-09HWFN1-M | | 23,000 | $2,760 |
| Yes | 207641237 | MDV | M4OI-36HFN1-M* | MSAG11B-09HRFN1-MX7W(GA) | | 22,000 | $2,640 |
| Yes | 207641231 | MDV | M4OI-36HFN1-M | 42 | | 23,000 | $2,760 |
| Yes | 207641228 | MDV | M4OI-36HFN1-M | MSEPB-09HRFN1-MY5W(GA) | | 23,200 | $2,784 |
| Yes | 207641257 | MDV | M2OI-18HFN1-M* | 42 | | 15,200 | $1,824 |
| Yes | 207641235 | MDV | M5OG-48HFN1-M* | MSAG11B-09HRFN1-MX7W(GA) | | 31,000 | $3,720 |
| Yes | 205306856 | MDV | M5OG-48HFN1-M-[X] | Heat pump without ducts | | 30,000 | $3,600 |
| Yes | 207641251 | MDV | M5OG-48HFN1-M-[X]-20* | Combination heat pumps with or without ducts | | 31,000 | $3,720 |
| Yes | 207690465 | MDV | MOE30U-48HFN1-M-[X1] | MVC-48HWFN1-M | | 32,000 | $3,840 |
| Yes | 207690463 | MDV | MOD30U-30HFN1-MR0(X) | MVC-30HWFN1-M | | 19,400 | $2,328 |
| Yes | 207338213 | MDV | MOE30U-36HFN1-M(GA) | MCD1-36HRFN1-M(GA) | | 25,000 | $3,000 |
| Yes | 207338219 | MDV | MOD30-24HFN1-MU0W | MCD1-24HRFN1-MT0W(GA) | | 15,000 | $1,800 |
| Yes | 206330129 | MDV | MOX430-17HFN1-MT0W | MTIU-18HWFN1-M | | 12,700 | $1,524 |
| Yes | 204829818 | MDV | MOE30U-48HFN1-M-[X] | MUE-48HRFN1-M(C) | | 35,000 | $4,200 |
| Yes | 205767336 | MDV | MOE30U-36HFN1-M-[X] | MCD-36HRFN1-M(C) | | 25,400 | $3,048 |
| Yes | 209852105 | MIDEA | DLCURAH48ABK | DLFUAAH48XAK | | 36,000 | $4,320 |
| Yes | 209852109 | MIDEA | DLCURAH36ABK | DLFUAAH36XAK | | 30,400 | $3,648 |
| Yes | 209852103 | MIDEA | DLCURAH24ABK | DLFUAAH24XAK | | 19,200 | $2,304 |
| Yes | 209852102 | MIDEA | DLCURAH18ABK | DLFUAAH18XAK | | 13,500 | $1,620 |
| Yes | 208447918 | MIDEA | 38MURAQ48AB3 | 40MUAAQ48XA3 | | 36,000 | $4,320 |
| Yes | 208447919 | MIDEA | 38MURAQ36AB3 | 40MUAAQ36XA3 | | 30,400 | $3,648 |
| Yes | 208447923 | MIDEA | 38MURAQ24AB3 | 40MUAAQ24XA3 | | 19,200 | $2,304 |
| Yes | 208447921 | MIDEA | 38MURAQ18AB3 | 40MUAAQ18XA3 | | 13,500 | $1,620 |
| Yes | 207643128 | MIDEA | DLCMHBH36DAK | Heat pump without ducts | | 22,000 | $2,640 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 207643125 | MIDEA | DLCMHBH48EAK | Heat pump without ducts | | 34,000 | $4,080 |
| Yes | 207643119 | MIDEA | DLCMHBH30DAK | Heat pump without ducts | | 18,500 | $2,220 |
| Yes | 207642975 | MIDEA | 38MGHBQ36DA3 | Heat pump without ducts | | 23,200 | $2,784 |
| Yes | 207642972 | MIDEA | 38MGHBQ48EA3 | Heat pump without ducts | | 30,000 | $3,600 |
| Yes | 207642966 | MIDEA | 38MGHBQ30DA3 | Heat pump without ducts | | 17,500 | $2,100 |
| Yes | 204722815 | MIDEA | 38MGRQ30D--3 | Heat pump without ducts | | 17,400 | $2,088 |
| Yes | 201847004 | MIDEA | 38MGRQ36D--3 | Heat pump without ducts | | 23,200 | $2,784 |
| Yes | 207826607 | MIDEA | DLCSRBH18AAK | DLFSABH18XBK | | 12,000 | $1,440 |
| Yes | 207801574 | MIDEA | DLCSRBH18AAK | DLFSDAH24XAK | | 12,600 | $1,512 |
| Yes | 207826679 | MIDEA | 38MARBQ18AA3 | 40MBABQ18XB3 | | 12,000 | $1,440 |
| Yes | 207801582 | MIDEA | 38MARBQ18AA3 | 40MBDQ24---3 | | 12,600 | $1,512 |
| Yes | 207643120 | MIDEA | DLCMHBH30DAK | Heat pump with ducts | | 19,000 | $2,280 |
| Yes | 207643126 | MIDEA | DLCMHBH48EAK | Heat pump with ducts | | 28,000 | $3,360 |
| Yes | 207643129 | MIDEA | DLCMHBH36DAK | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 207643121 | MIDEA | DLCMHBH30DAK | Combination heat pumps with or without ducts | | 18,700 | $2,244 |
| Yes | 207643127 | MIDEA | DLCMHBH48EAK | Combination heat pumps with or without ducts | | 31,000 | $3,720 |
| Yes | 207643130 | MIDEA | DLCMHBH36DAK | Combination heat pumps with or without ducts | | 22,400 | $2,688 |
| Yes | 207642967 | MIDEA | 38MGHBQ30DA3 | Heat pump with ducts | | 19,000 | $2,280 |
| Yes | 207642976 | MIDEA | 38MGHBQ36DA3 | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 207642973 | MIDEA | 38MGHBQ48EA3 | Heat pump with ducts | | 28,000 | $3,360 |
| Yes | 207642968 | MIDEA | 38MGHBQ30DA3 | Combination heat pumps with or without ducts | | 18,200 | $2,184 |
| Yes | 207642977 | MIDEA | 38MGHBQ36DA3 | Combination heat pumps with or without ducts | | 23,000 | $2,760 |
| Yes | 207642974 | MIDEA | 38MGHBQ48EA3 | Combination heat pumps with or without ducts | | 29,000 | $3,480 |
| Yes | 206188330 | MIDEA | DLCSRBH24AAK | DLFSAAH24XAK | | 16,500 | $1,980 |
| Yes | 206350458 | MIDEA | DLCSRBH24AAK | DLFSFAH24XAK | | 14,500 | $1,740 |
| Yes | 206350456 | MIDEA | DLCSRBH24AAK | DLFSCAH24XAK | | 14,500 | $1,740 |
| Yes | 206350455 | MIDEA | DLCSRBH18AAK | DLFSFAH18XAK | | 12,000 | $1,440 |
| Yes | 206350454 | MIDEA | DLCSRBH18AAK | DLFSDAH18XAK | | 12,700 | $1,524 |
| Yes | 206350377 | MIDEA | 38MARBQ18AA3 | 40MBDQ18--3 | | 12,700 | $1,524 |
| Yes | 206188281 | MIDEA | 38MARBQ24AA3 | 40MBAAQ24XA3 | | 16,500 | $1,980 |
| Yes | 206350379 | MIDEA | 38MARBQ24AA3 | 40MBCQ24--3 | | 14,500 | $1,740 |
| Yes | 206350321 | MIDEA | 38MARBQ24AA3 | DHMAHBQ24XA3 | | 19,800 | $2,376 |
| Yes | 206350381 | MIDEA | 38MARBQ24AA3 | 40MBFQ24--3 | | 14,500 | $1,740 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 206350378 | MIDEA | 38MARBQ18AA3 | 40MBFQ18--3 | | 12,000 | $1,440 |
| Yes | 206350457 | MIDEA | DLCSRBH24AAK | DLFSDAH24XAK | | 14,500 | $1,740 |
| Yes | 206350380 | MIDEA | 38MARBQ24AA3 | 40MBDQ24--3 | | 14,500 | $1,740 |
| Yes | 205962795 | MIDEA | 38MAQB24R--3 | 40MBAAQ24XA3 | | 17,500 | $2,100 |
| Yes | 205921378 | MIDEA | DLCSRAH24AAK | DLFSAAH24XAK | | 17,500 | $2,100 |
| Yes | 201796614 | MIDEA | DLCSRAH24AAK | DLFSCAH24XAK | | 16,200 | $1,944 |
| Yes | 202463655 | MIDEA | DLCPRAH24AAK | DLFPHAH24XAK | | 15,450 | $1,854 |
| Yes | 202463641 | MIDEA | 38MPRAQ24AA3 | DHMPHAQ24XA3 | | 15,450 | $1,854 |
| Yes | 201796612 | MIDEA | DLCSRAH24AAK | DLFSDAH24XAK | | 17,400 | $2,088 |
| Yes | 201756550 | MIDEA | DLCSRAH24AAK | DLFSHAH24XAK | | 15,000 | $1,800 |
| Yes | 201796618 | MIDEA | DLCLRAH48AAK | DLFLFAH48XAK | | 35,000 | $4,200 |
| Yes | 201847064 | MIDEA | 38MBRQ48A--3 | 40MBFQ48---3 | | 35,000 | $4,200 |
| Yes | 201847062 | MIDEA | 38MAQB24R--3 | 40MBFQ24---3 | | 17,200 | $2,064 |
| Yes | 201796613 | MIDEA | DLCSRAH24AAK | DLFSFAH24XAK | | 17,200 | $2,064 |
| Yes | 201796611 | MIDEA | DLCSRAH18AAK | DLFSCAH18XAK | | 12,000 | $1,440 |
| Yes | 201846998 | MIDEA | 38MAQB24R--3 | 40MBDQ24---3 | | 17,300 | $2,076 |
| Yes | 201847074 | MIDEA | 38MGRQ36D--3 | Heat pump with ducts | | 24,600 | $2,952 |
| Yes | 204711115 | MIDEA | 38MGRQ30D--3 | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 204722808 | MIDEA | 38MGRQ36D--3 | Combination heat pumps with or without ducts | | 23,800 | $2,856 |
| Yes | 204722807 | MIDEA | 38MGRQ30D--3 | Combination heat pumps with or without ducts | | 20,200 | $2,424 |
| Yes | 211257310 | MITS AIR | MOE30U-55HFN1-M | MVC-60HWFN1-M | | 42,000 | $5,040 |
| Yes | 211911385 | MITS AIR | MOD30U-30HFN1-MR0(X) | MAC-36HWFN1-M | | 22,600 | $2,712 |
| Yes | 211911382 | MITS AIR | MOD30U-30HFN1-MR0(X) | MAC-36HWDN1-MN0 | | 22,600 | $2,712 |
| Yes | 211257309 | MITS AIR | MOE30U-48HFN1-M-[X1] | MVC-48HWFN1-M | | 36,000 | $4,320 |
| Yes | 211257306 | MITS AIR | MOD30-24HFN1-MW | MVC-24HWFN1-M | | 19,200 | $2,304 |
| Yes | 211257305 | MITS AIR | MOX430U-18HFN1-M | MVC-18HWFN1-M | | 13,500 | $1,620 |
| Yes | 207702686 | MITSUBISHI ELECTRIC | PUZ-HA24NHA1 | PEAD-A24AA* | | 18,000 | $2,160 |
| Yes | 206223050 | MITSUBISHI ELECTRIC | PUZ-HA30NKA | PEAD-A30AA7 | | 21,000 | $2,520 |
| Yes | 207702691 | MITSUBISHI ELECTRIC | PUZ-HA36NKA | PEAD-A36AA* | | 24,800 | $2,976 |
| Yes | 211259282 | MITSUBISHI ELECTRIC | PUZ-HA42NKA1 | PVA-A42AA* | | 38,500 | $4,620 |
| Yes | 207702694 | MITSUBISHI ELECTRIC | PUZ-HA42NKA1 | PEAD-A42AA* | | 39,500 | $4,740 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 209836186 | MITSUBISHI ELECTRIC | MXZ-2C20NAHZ3*** | Heat pump without ducts | | 13,000 | $1,560 |
| Yes | 211259269 | MITSUBISHI ELECTRIC | PUZ-HA24NHA1 | PKA-A24KA* | | 17,200 | $2,064 |
| Yes | 211259270 | MITSUBISHI ELECTRIC | PUZ-HA24NHA1 | PCA-A24KA* | | 17,700 | $2,124 |
| Yes | 211259272 | MITSUBISHI ELECTRIC | PUZ-HA24NHA1 | PVA-A24AA* | | 17,500 | $2,100 |
| Yes | 211273264 | MITSUBISHI ELECTRIC | PUZ-HA24NHA1 | PLA-A24EA* | | 17,300 | $2,076 |
| Yes | 207702726 | MITSUBISHI ELECTRIC | SUZ-KA36NAHZ | PEAD-A36AA* | | 24,800 | $2,976 |
| Yes | 207702722 | MITSUBISHI ELECTRIC | SUZ-KA30NAHZ | PEAD-A30AA* | | 21,000 | $2,520 |
| Yes | 207702716 | MITSUBISHI ELECTRIC | SUZ-KA24NAHZ | PEAD-A24AA* | | 18,000 | $2,160 |
| Yes | 209832208 | Mitsubishi Electric | MUZ-FS18NAH*** | MSZ-FS18NA*** | | 12,800 | $1,536 |
| Yes | 209832207 | Mitsubishi Electric | MUZ-FS18NA*** | MSZ-FS18NA*** | | 12,800 | $1,536 |
| Yes | 211273652 | MITSUBISHI ELECTRIC | SUZ-KA30NAHZ | SVZ-KP30NA* | | 21,400 | $2,568 |
| Yes | 211259276 | MITSUBISHI ELECTRIC | PUZ-HA36NKA | PKA-A36KA* | | 25,400 | $3,048 |
| Yes | 211259279 | MITSUBISHI ELECTRIC | PUZ-HA36NKA | PVA-A36AA* | | 24,600 | $2,952 |
| Yes | 211259275 | MITSUBISHI ELECTRIC | PUZ-HA36NKA | PLA-A36EA* | | 24,200 | $2,904 |
| Yes | 211259278 | MITSUBISHI ELECTRIC | PUZ-HA36NKA | PCA-A36KA* | | 25,400 | $3,048 |
| Yes | 209424905 | MITSUBISHI ELECTRIC | MXZ-3C30NAHZ4*** | Heat pump without ducts | | 18,000 | $2,160 |
| Yes | 209424902 | MITSUBISHI ELECTRIC | MXZ-3C24NAHZ4*** | Heat pump without ducts | | 14,000 | $1,680 |
| Yes | 209424900 | MITSUBISHI ELECTRIC | MXZ-2C20NAHZ4*** | Heat pump without ducts | | 13,700 | $1,644 |
| Yes | 210819447 | MITSUBISHI ELECTRIC | MUFZ-KJ15NAHZ*** | MFZ-KJ15NA*** | | 12,000 | $1,440 |
| Yes | 210819448 | MITSUBISHI ELECTRIC | MUFZ-KJ18NAHZ*** | MFZ-KJ18NA*** | | 12,800 | $1,536 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 209949005 | MITSUBISHI ELECTRIC | MXZ-3C24NAHZ3 | Combination heat pumps with or without ducts | | 14,000 | $1,680 |
| Yes | 209836203 | MITSUBISHI ELECTRIC | MXZ-3C24NAHZ3 | Heat pump without ducts | | 14,000 | $1,680 |
| Yes | 209949006 | MITSUBISHI ELECTRIC | MXZ-3C30NAHZ3 | Combination heat pumps with or without ducts | | 17,200 | $2,064 |
| Yes | 209836204 | MITSUBISHI ELECTRIC | MXZ-3C30NAHZ3 | Heat pump without ducts | | 18,000 | $2,160 |
| Yes | 210435439 | MITSUBISHI ELECTRIC | PUZ-HA36NKA* | PAA-A36CA1 | | 28,400 | $3,408 |
| Yes | 209484153 | MITSUBISHI ELECTRIC | PUZ-HA36NKA* | PAA-A36BA1 | | 28,400 | $3,408 |
| Yes | 210435438 | MITSUBISHI ELECTRIC | PUZ-HA30NKA* | PAA-A30BA1 | | 23,200 | $2,784 |
| Yes | 210435437 | MITSUBISHI ELECTRIC | PUZ-HA30NKA* | PAA-A30AA1 | | 23,200 | $2,784 |
| Yes | 209447989 | MITSUBISHI ELECTRIC | PUZ-HA24NHA* | PAA-A24BA1 | | 16,600 | $1,992 |
| Yes | 209447988 | MITSUBISHI ELECTRIC | PUZ-HA24NHA* | PAA-A24AA1 | | 16,600 | $1,992 |
| Yes | 202732309 | MITSUBISHI ELECTRIC | MXZ-2C20NAHZ2 | MSZ-FH09NAMSZ-FH09NA | | 13,000 | $1,560 |
| Yes | 202412089 | MITSUBISHI ELECTRIC | PUMY-P60NKMU2 | Heat pump without ducts | | 41,500 | $4,980 |
| Yes | 202412088 | MITSUBISHI ELECTRIC | PUMY-HP48NKMU | Heat pump without ducts | | 39,000 | $4,680 |
| Yes | 202412085 | MITSUBISHI ELECTRIC | PUMY-HP36NKMU | Heat pump without ducts | | 33,000 | $3,960 |
| Yes | 201754904 | MITSUBISHI ELECTRIC | MXZ-3C24NAHZ2 | Heat pump without ducts | | 14,000 | $1,680 |
| Yes | 201754637 | MITSUBISHI ELECTRIC | MXZ-8C60NA-U* | Heat pump without ducts | | 41,500 | $4,980 |
| Yes | 201754926 | MITSUBISHI ELECTRIC | MXZ-5C42NAHZ | Heat pump without ducts | | 35,800 | $4,296 |
| Yes | 201754911 | MITSUBISHI ELECTRIC | MXZ-4C36NAHZ | Heat pump without ducts | | 34,000 | $4,080 |
| Yes | 201755020 | MITSUBISHI ELECTRIC | MXZ-4C36NAHZ | Combination heat pumps with or without ducts | | 35,000 | $4,200 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 201754635 | MITSUBISHI ELECTRIC | MXZ-8C48NAHZ | Heat pump without ducts | | 40,000 | $4,800 |
| Yes | 201754912 | MITSUBISHI ELECTRIC | MXZ-4C36NAHZ | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 201755022 | MITSUBISHI ELECTRIC | MXZ-5C42NAHZ | Combination heat pumps with or without ducts | | 36,200 | $4,344 |
| Yes | 201755024 | MITSUBISHI ELECTRIC | MXZ-8C48NAHZ | Combination heat pumps with or without ducts | | 41,500 | $4,980 |
| Yes | 204629352 | MITSUBISHI ELECTRIC | NAXSPF18A112A* | MFZ-KJ18NA*** | | 12,800 | $1,536 |
| Yes | 204629351 | MITSUBISHI ELECTRIC | NAXSPF15A112A* | MFZ-KJ15NA*** | | 12,000 | $1,440 |
| Yes | 204629264 | MITSUBISHI ELECTRIC | NTXSPF15A112A* | MFZ-KJ15NA*** | | 12,000 | $1,440 |
| Yes | 204629265 | MITSUBISHI ELECTRIC | NTXSPF18A112A* | MFZ-KJ18NA*** | | 12,800 | $1,536 |
| Yes | 206908469 | MITSUBISHI ELECTRIC | MXZ-2C20NAHZ2*** | Combination heat pumps with or without ducts | | 13,300 | $1,596 |
| Yes | 206908464 | MITSUBISHI ELECTRIC | MXZ-2C20NAHZ2*** | Heat pump without ducts | | 13,000 | $1,560 |
| Yes | 201754490 | MITSUBISHI ELECTRIC | PUZ-HA36NHA5 | PLA-A36BA* | | 28,000 | $3,360 |
| Yes | 201754640 | MITSUBISHI ELECTRIC | PUMY-P60NKMU1 | Heat pump without ducts | | 41,500 | $4,980 |
| Yes | 201754444 | MITSUBISHI ELECTRIC | PUMY-P36NKMU* | Heat pump with ducts | | 26,600 | $3,192 |
| Yes | 201755028 | MITSUBISHI ELECTRIC | PUMY-P60NKMU* | Combination heat pumps with or without ducts | | 41,500 | $4,980 |
| Yes | 204834295 | MITSUBISHI ELECTRIC | MXZ-8C60NA2 | Heat pump without ducts | | 41,500 | $4,980 |
| Yes | 207517153 | MITSUBISHI ELECTRIC | MXZ-SM36NAMHZ | Heat pump with ducts | | 32,000 | $3,840 |
| Yes | 207525855 | MITSUBISHI ELECTRIC | MXZ-SM36NAMHZ | Combination heat pumps with or without ducts | | 32,400 | $3,888 |
| Yes | 207517152 | MITSUBISHI ELECTRIC | MXZ-SM36NAMHZ | Heat pump without ducts | | 33,000 | $3,960 |
| Yes | 207517155 | MITSUBISHI ELECTRIC | MXZ-SM42NAMHZ | Heat pump with ducts | | 32,000 | $3,840 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 207525856 | MITSUBISHI ELECTRIC | MXZ-SM42NAMHZ | Combination heat pumps with or without ducts | | 32,000 | $3,840 |
| Yes | 207517154 | MITSUBISHI ELECTRIC | MXZ-SM42NAMHZ | Heat pump without ducts | | 32,000 | $3,840 |
| Yes | 207517159 | MITSUBISHI ELECTRIC | MXZ-SM48NAMHZ | Heat pump with ducts | | 42,000 | $5,040 |
| Yes | 207525858 | MITSUBISHI ELECTRIC | MXZ-SM48NAMHZ | Combination heat pumps with or without ducts | | 40,500 | $4,860 |
| Yes | 207517158 | MITSUBISHI ELECTRIC | MXZ-SM48NAMHZ | Heat pump without ducts | | 39,000 | $4,680 |
| Yes | 207525859 | MITSUBISHI ELECTRIC | MXZ-SM60NAM | Combination heat pumps with or without ducts | | 41,000 | $4,920 |
| Yes | 207517160 | MITSUBISHI ELECTRIC | MXZ-SM60NAM | Heat pump without ducts | | 41,500 | $4,980 |
| Yes | 207517161 | MITSUBISHI ELECTRIC | MXZ-SM60NAM | Heat pump with ducts | | 40,500 | $4,860 |
| Yes | 204834269 | MITSUBISHI ELECTRIC | MXZ-8C60NA2 | Heat pump with ducts | | 40,500 | $4,860 |
| Yes | 206223048 | MITSUBISHI ELECTRIC | PUZ-HA30NKA | PVA-A30AA7 | | 21,000 | $2,520 |
| Yes | 206328091 | MITSUBISHI ELECTRIC | SUZ-KA15NAHZ | NTXDKS15A112AA | | 12,200 | $1,464 |
| Yes | 206328112 | MITSUBISHI ELECTRIC | SUZ-KA15NAHZ | NAXDKS15A112AA | | 12,200 | $1,464 |
| Yes | 204629574 | MITSUBISHI ELECTRIC | MUFZ-KJ15NAHZ*** | NAXFKS15A112A* | | 12,000 | $1,440 |
| Yes | 204629179 | MITSUBISHI ELECTRIC | MUFZ-KJ15NAHZ*** | NTXFKS15A112A* | | 12,000 | $1,440 |
| Yes | 204629180 | MITSUBISHI ELECTRIC | MUFZ-KJ18NAHZ*** | NTXFKS18A112A* | | 12,800 | $1,536 |
| Yes | 204629575 | MITSUBISHI ELECTRIC | MUFZ-KJ18NAHZ*** | NAXFKS18A112A* | | 12,800 | $1,536 |
| Yes | 204834273 | MITSUBISHI ELECTRIC | PUMY-HP36NKMU1 | | | 32,000 | $3,840 |
| Yes | 204926535 | MITSUBISHI ELECTRIC | PUMY-HP36NKMU1 | Combination heat pumps with or without ducts | | 32,400 | $3,888 |
| Yes | 204834216 | MITSUBISHI ELECTRIC | PUMY-HP48NKMU1 | Heat pump with ducts | | 42,000 | $5,040 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204926537 | MITSUBISHI ELECTRIC | PUMY-HP48NKMU1 | Combination heat pumps with or without ducts | | 40,500 | $4,860 |
| Yes | 204834275 | MITSUBISHI ELECTRIC | PUMY-HP48NKMU1 | Heat pump without ducts | | 39,000 | $4,680 |
| Yes | 204834272 | MITSUBISHI ELECTRIC | PUMY-HP36NKMU1 | Heat pump without ducts | | 33,000 | $3,960 |
| Yes | 204276762 | MITSUBISHI ELECTRIC | PUZ-HA24NHA | PCA-A24KA7 | | 17,700 | $2,124 |
| Yes | 204281760 | MITSUBISHI ELECTRIC | PUZ-HA24NHA | PVA-A24AA7 | | 17,500 | $2,100 |
| Yes | 204276538 | MITSUBISHI ELECTRIC | PUZ-HA24NHA | PLA-A24EA7 | | 17,300 | $2,076 |
| Yes | 204834267 | MITSUBISHI ELECTRIC | MXZ-8C48NAHZ2 | Heat pump without ducts | | 38,000 | $4,560 |
| Yes | 204834292 | MITSUBISHI ELECTRIC | MXZ-4C36NAHZ2 | Heat pump without ducts | | 30,000 | $3,600 |
| Yes | 204834294 | MITSUBISHI ELECTRIC | MXZ-5C42NAHZ2 | Heat pump without ducts | | 32,000 | $3,840 |
| Yes | 204834293 | MITSUBISHI ELECTRIC | MXZ-4C36NAHZ2 | Heat pump with ducts | | 34,000 | $4,080 |
| Yes | 204834266 | MITSUBISHI ELECTRIC | MXZ-5C42NAHZ2 | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 204834268 | MITSUBISHI ELECTRIC | MXZ-8C48NAHZ2 | Heat pump with ducts | | 38,000 | $4,560 |
| Yes | 204926512 | MITSUBISHI ELECTRIC | MXZ-4C36NAHZ2 | Combination heat pumps with or without ducts | | 32,000 | $3,840 |
| Yes | 204926514 | MITSUBISHI ELECTRIC | MXZ-5C42NAHZ2 | Combination heat pumps with or without ducts | | 34,000 | $4,080 |
| Yes | 204926517 | MITSUBISHI ELECTRIC | MXZ-8C48NAHZ2 | Combination heat pumps with or without ducts | | 38,000 | $4,560 |
| Yes | 201754495 | MITSUBISHI ELECTRIC | PUZ-HA42NKA | PVA-A42AA* | | 42,000 | $5,040 |
| Yes | 202423535 | MITSUBISHI ELECTRIC | PUMY-HP48NKMU | Heat pump with ducts | | 42,000 | $5,040 |
| Yes | 202423533 | MITSUBISHI ELECTRIC | PUMY-HP36NKMU | Heat pump with ducts | | 32,000 | $3,840 |
| Yes | 202426336 | MITSUBISHI ELECTRIC | PUMY-HP48NKMU | Combination heat pumps with or without ducts | | 40,500 | $4,860 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204276767 | MITSUBISHI ELECTRIC | PUZ-HA24NHA | PEAD-A24AA7 | | 18,000 | $2,160 |
| Yes | 204276761 | MITSUBISHI ELECTRIC | PUZ-HA24NHA | PKA-A24KA7 | | 17,200 | $2,064 |
| Yes | 204627021 | MITSUBISHI ELECTRIC | SUZ-KA15NAHZ | SEZ-KD15NA4 | | 12,200 | $1,464 |
| Yes | 202426335 | MITSUBISHI ELECTRIC | PUMY-HP36NKMU | Combination heat pumps with or without ducts | | 45,898 | $5,508 |
| Yes | 201754321 | MITSUBISHI ELECTRIC | PUZ-HA36NHA5 | PLA-A36EA* | | 28,000 | $3,360 |
| Yes | 201754323 | MITSUBISHI ELECTRIC | PUZ-HA36NHA5 | PVA-A36AA* | | 25,000 | $3,000 |
| Yes | 201754322 | MITSUBISHI ELECTRIC | PUZ-HA36NHA5 | PEAD-A36AA* | | 27,000 | $3,240 |
| Yes | 201755016 | MITSUBISHI ELECTRIC | MXZ-3C24NAHZ2 | Combination heat pumps with or without ducts | | 14,000 | $1,680 |
| Yes | 201754441 | MITSUBISHI ELECTRIC | MXZ-5C42NAHZ | Heat pump with ducts | | 36,600 | $4,392 |
| Yes | 202426339 | MITSUBISHI ELECTRIC | PUMY-P60NKMU2 | Combination heat pumps with or without ducts | | 45,144 | $5,417 |
| Yes | 211306400 | Mitsutomo | HO-SZ18-AB-Q | HJ-UZ18-AB-Q | | 14,500 | $1,740 |
| Yes | 211306414 | Mitsutomo | HO-MP55-AB-Q | Heat pump with ducts | | 35,200 | $4,224 |
| Yes | 211306413 | Mitsutomo | HO-MP55-AB-Q | Heat pump without ducts | | 34,800 | $4,176 |
| Yes | 211306404 | Mitsutomo | HO-MT28-AB-Q | Heat pump without ducts | | 25,600 | $3,072 |
| Yes | 211306402 | Mitsutomo | HO-MD18-AB-Q | Heat pump with ducts | | 16,000 | $1,920 |
| Yes | 211306411 | Mitsutomo | HO-MP48-AB-Q | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 211306405 | Mitsutomo | HO-MT28-AB-Q | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 211306410 | Mitsutomo | HO-MP48-AB-Q | Heat pump without ducts | | 39,000 | $4,680 |
| Yes | 211306407 | Mitsutomo | HO-MQ36-AB-Q | Heat pump without ducts | | 35,000 | $4,200 |
| Yes | 211306401 | Mitsutomo | HO-MD18-AB-Q | Heat pump without ducts | | 13,500 | $1,620 |
| Yes | 211306396 | Mitsutomo | HO-SZ24-AB-Q | HW-SZ24-AB-Q | | 18,900 | $2,268 |
| Yes | 211306383 | Mitsutomo | UHO60-NB-Q | UHM60-DB-Q | | 42,000 | $5,040 |
| Yes | 211306382 | Mitsutomo | UHO48-NB-Q | UHM48-CB-Q | | 36,000 | $4,320 |
| Yes | 211306379 | Mitsutomo | UHO24-NB-Q | UHM24-BB-Q | | 19,200 | $2,304 |
| Yes | 211306378 | Mitsutomo | UHO18-NB-Q | UHM18-BB-Q | | 13,500 | $1,620 |
| Yes | 210586144 | MOOVAIR | DMA24HOS28230E8 | CUAC24HACU000X5 | | 22,000 | $2,640 |
| Yes | 210295923 | MOOVAIR | DMA60HOS20230E7 | FMA60HIAHUU230X7 | | 42,000 | $5,040 |
| Yes | 212361760 | MOOVAIR | DMA30HOS20230E7 | CUB36HAC20CWT7A | | 22,600 | $2,712 |
| Yes | 207706562 | MOOVAIR | DMA48HOS20230E7 | FMA48HIAHUU230X7 | | 36,000 | $4,320 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 207706559 | MOOVAIR | DMA24HOS20230E7 | FMA24HIAHUU230X7 | | 19,200 | $2,304 |
| Yes | 207706558 | MOOVAIR | DMA18HOS20230E7 | DMA18HOS20230E7 | | 13,500 | $1,620 |
| Yes | 207764688 | MOOVAIR | DMA18HOS20230E7 | FMA18HIAHUU230X7 | | 13,500 | $1,620 |
| Yes | 207742547 | MOOVAIR | DMA36HOM25230X3 | Heat pump without ducts | | 33,000 | $3,960 |
| Yes | 208136320 | MOOVAIR | DMA55HOM25230X3 | Heat pump with ducts | | 35,200 | $4,224 |
| Yes | 208136319 | MOOVAIR | DMA55HOM25230X3 | Heat pump without ducts | | 34,400 | $4,128 |
| Yes | 207742541 | MOOVAIR | DMA18HOM25230X3 | Heat pump without ducts | | 15,000 | $1,800 |
| Yes | 207742551 | MOOVAIR | DMA48HOM25230X3 | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 207742550 | MOOVAIR | DMA48HOM25230X3 | Heat pump without ducts | | 36,000 | $4,320 |
| Yes | 207742545 | MOOVAIR | DMA27HOM25230X3 | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 207742544 | MOOVAIR | DMA27HOM25230X3 | Heat pump without ducts | | 26,600 | $3,192 |
| Yes | 207742542 | MOOVAIR | DMA18HOM25230X3 | Heat pump with ducts | | 16,000 | $1,920 |
| Yes | 207742511 | MOOVAIR | DMA24HOS28230E8 | DUA24HICU230X5 | | 21,000 | $2,520 |
| Yes | 207742526 | MOOVAIR | DMA48HOS28230E8 | DUA48HIDU230X5 | | 39,500 | $4,740 |
| Yes | 207742513 | MOOVAIR | DMA48HOS28230E8 | DUA48HICU230X5 | | 35,000 | $4,200 |
| Yes | 207742512 | MOOVAIR | DMA36HOS28230E8 | DUA36HICU230X5 | | 33,000 | $3,960 |
| Yes | 207742524 | MOOVAIR | DMA24HOS28230E8 | DUA24HIDU230X5 | | 21,000 | $2,520 |
| Yes | 206401443 | MOOVAIR | DM24HOS25230E3A | DM24HIDU230X5 | | 21,000 | $2,520 |
| Yes | 206401440 | MOOVAIR | DM18HOS25230E3A | DM18HIDU230X5 | | 15,000 | $1,800 |
| Yes | 207742523 | MOOVAIR | DMA18HOS28230E8 | DUA18HIDU230X5 | | 15,000 | $1,800 |
| Yes | 207742498 | MOOVAIR | DMA24HOS28230E8 | DMA24HIW25230E8 | | 21,200 | $2,544 |
| Yes | 207742497 | MOOVAIR | DMA18HOS28230E8 | DMA18HIW25230E8 | | 15,000 | $1,800 |
| Yes | 210295922 | MOOVAIR | DMA24HOS28230E8 | FM24HIAHUU230X6 | | 16,500 | $1,980 |
| Yes | 205309414 | MOOVAIR | DM48HOM25230X3 | Heat pump with ducts | | 28,000 | $3,360 |
| Yes | 204005743 | MOOVAIR | DM24HOS25230E3 | DM24HIDU230X5 | | 17,200 | $2,064 |
| Yes | 204005772 | MOOVAIR | DM27HOM25230X3 | Heat pump without ducts | | 18,000 | $2,160 |
| Yes | 207742582 | MOOVAIR | DM24HOS25230E3A | FM24HIAHUU230X6 | | 16,500 | $1,980 |
| Yes | 207742581 | MOOVAIR | DM24HOS25230E3 | FM24HIAHUU230X6 | | 17,500 | $2,100 |
| Yes | 207742548 | MOOVAIR | DMA36HOM25230X3 | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 205921399 | MOOVAIR | DM24HOS25230E3 | FM24HIAHUU230X6 | | 17,500 | $2,100 |
| Yes | 207131748 | MOOVAIR | DM24HOS25230E3A | FM24HIAHUU230X6 | | 16,500 | $1,980 |
| Yes | 208119827 | MOOVAIR | DMA24HOS28230E8 | DM24HIW23230E3 | | 19,400 | $2,328 |
| Yes | 206853240 | MOOVAIR | DM36HOS25230E3 | DM36HIDU230X5 | | 28,000 | $3,360 |
| Yes | 206853241 | MOOVAIR | DM48HOS25230E3 | DM48HIDU230X5 | | 33,000 | $3,960 |
| Yes | 206401442 | MOOVAIR | DM24HOS25230E3A | DM24HIW23230E3 | | 19,400 | $2,328 |
| Yes | 207645901 | MOOVAIR | DM48HOS25230E3 | DM48HICU230X5 | | 35,000 | $4,200 |
| Yes | 208136321 | MOOVAIR | DMA55HOM25230X3 | Combination heat pumps with or without ducts | | 35,400 | $4,248 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 207742552 | MOOVAIR | DMA48HOM25230X3 | Combination heat pumps with or without ducts | | 29,000 | $3,480 |
| Yes | 207742549 | MOOVAIR | DMA36HOM25230X3 | Combination heat pumps with or without ducts | | 23,000 | $2,760 |
| Yes | 205309413 | MOOVAIR | DM48HOM25230X3 | Heat pump without ducts | | 30,000 | $3,600 |
| Yes | 207645900 | MOOVAIR | DM36HOS25230E3 | DM36HICU230X5 | | 25,400 | $3,048 |
| Yes | 210279123 | MRCOOL | CENTRAL-48-HP-C-230A00 | CENTRAL-48-HP-MUAH230A00 | | 36,000 | $4,320 |
| Yes | 210288098 | MRCOOL | DIYH-24-HP-C-230C25 | DIYH-24-HP-MUAH-230C25 | | 18,400 | $2,208 |
| Yes | 210288099 | MRCOOL | DIYH-30-HP-C-230C25 | DIYH-30-HP-MUAH-230C25 | | 21,000 | $2,520 |
| Yes | 210295926 | MRCOOL | DIYH-18-HP-C-230C25 | DIYH-18-HP-MUAH-230C25 | | 15,000 | $1,800 |
| Yes | 210279124 | MRCOOL | CENTRAL-60-HP-C-230A00 | CENTRAL-60-HP-MUAH230A00 | | 42,000 | $5,040 |
| Yes | 207339164 | MRCOOL | O-HH-24-HP-C-230A | O-24-HP-WMAH-230B | | 21,200 | $2,544 |
| Yes | 208552825 | MRCOOL | O-HH-24-HP-C-230B | O-24-HP-WMAH-230B | | 21,200 | $2,544 |
| Yes | 208552823 | MRCOOL | O-HH-18-HP-C-230B | O-18-HP-WMAH-230B | | 15,000 | $1,800 |
| Yes | 207339163 | MRCOOL | O-HH-18-HP-C-230A | O-18-HP-WMAH-230B | | 15,000 | $1,800 |
| Yes | 204469771 | MRCOOL | O-HH-24-HP-C-230 | DUCT-24HP-230 | | 17,200 | $2,064 |
| Yes | 212427854 | NAPOLEON | WSEHV2436RA1-N | H,DE33(6,9)36 | WUV070T3AA | 15,000 | $1,800 |
| Yes | 212427853 | NAPOLEON | WSEHV2436RA1-N | H,DE33(6,9)36 | WPV070T3AA | 15,000 | $1,800 |
| Yes | 211624975 | NAPOLEON | WSEHV4860RA1-N | NPFX48A | | 31,400 | $3,768 |
| Yes | 211624974 | NAPOLEON | WSEHV2436RA1-N | NPFX24A36A | | 24,000 | $2,880 |
| Yes | 211624973 | NAPOLEON | WSEHV2436RA1-N | NPFX24A | | 16,000 | $1,920 |
| Yes | 212404696 | NAPOLEON | WSEHV2436RA1-N | H,DE33(6,9)36 | WUV060T3AA | 15,000 | $1,800 |
| Yes | 212404695 | NAPOLEON | WSEHV2436RA1-N | H,DE33(6,9)36 | WUV050T3AA | 15,000 | $1,800 |
| Yes | 212404694 | NAPOLEON | WSEHV2436RA1-N | H,DE33(6,9)36 | WPV060T3AA | 15,000 | $1,800 |
| Yes | 212404693 | NAPOLEON | WSEHV2436RA1-N | H,DE33(6,9)36 | WPV050T3AA | 15,000 | $1,800 |
| Yes | 207683241 | NAPOLEON | NDHAM-36-O | Heat pump without ducts | | 35,000 | $4,200 |
| Yes | 207683238 | NAPOLEON | NDHAM-28-O | Heat pump without ducts | | 25,600 | $3,072 |
| Yes | 207683239 | NAPOLEON | NDHAM-28-O | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 207683236 | NAPOLEON | NDHAS26-24-O | NDHAS26-24-I | | 21,200 | $2,544 |
| Yes | 207683235 | NAPOLEON | NDHAS26-18-O | NDHAS26-18-I | | 15,000 | $1,800 |
| Yes | 206598613 | NAPOLEON | NH25-24H-O | NH25-24F-I | | 19,400 | $2,328 |
| Yes | 207683243 | NAPOLEON | NDHAM-36-O | Combination heat pumps with or without ducts | | 22,400 | $2,688 |
| Yes | 207683242 | NAPOLEON | NDHAM-36-O | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 206597272 | NAPOLEON | NH25-18H-O | NH25-24F-I | | 19,400 | $2,328 |
| Yes | 209664500 | NAPOLEON | NS18HV24A36 | H,DE32(6,9)36 | WPV035T2AA | 15,100 | $1,812 |
| Yes | 209664498 | NAPOLEON | NS18HV24A36 | H,DE32(6,9)36 | WUV035T2AA | 15,100 | $1,812 |
| Yes | 208157172 | NAPOLEON | NS18HV24A36 | H,DE33(6,9)36 | WUV070T3AA | 19,400 | $2,328 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 208157171 | NAPOLEON | NS18HV24A36 | H,DE33(6,9)36 | WUV050T3AA | 19,400 | $2,328 |
| Yes | 208157170 | NAPOLEON | NS18HV24A36 | H,DE33(6,9)36 | WPV070T3AA | 19,400 | $2,328 |
| Yes | 208143093 | NAPOLEON | NS18HV24A36 | H,DE33(6,9)36 | WPV050T3AA | 19,400 | $2,328 |
| Yes | 207335554 | NAPOLEON | NS18HV48A60 | NPFX48A | | 32,000 | $3,840 |
| Yes | 207335552 | NAPOLEON | NS18HV24A36 | NPFX24A | | 16,300 | $1,956 |
| Yes | 207335555 | NAPOLEON | NS18HV48A60 | NPFX48A60A | | 36,000 | $4,320 |
| Yes | 207335553 | NAPOLEON | NS18HV24A36 | NPFX24A36A | | 24,000 | $2,880 |
| Yes | 211709685 | NOVAIR | LEA24SZ35SK-O | 2LEA24UUSK-I | | 21,200 | $2,544 |
| Yes | 211709684 | NOVAIR | LEA18SZ35SK-O | 2LEA18UUSK-I | | 15,000 | $1,800 |
| Yes | 211253512 | NOVAIR | LEA60-EVOX-30-O | LEA60-EVOX-30-I | | 42,000 | $5,040 |
| Yes | 211253514 | NOVAIR | LEA48-EVOX-30-O | LEA48-EVOX-30-I | | 36,000 | $4,320 |
| Yes | 211253513 | NOVAIR | LEA24-EVOX-30-O | LEA24-EVOX-30-I | | 19,200 | $2,304 |
| Yes | 211253511 | NOVAIR | LEA18-EVOX-30-O | LEA18-EVOX-30-I | | 13,500 | $1,620 |
| Yes | 211133300 | NOVAIR | LEA36MZ-4P-35SK-O | Heat pump without ducts | | 35,000 | $4,200 |
| Yes | 209416881 | NOVAIR | LEA28MZ-3P-35SK-O | Heat pump without ducts | | 25,600 | $3,072 |
| Yes | 209416885 | NOVAIR | LEA20MZ-2P-35SK-O | Heat pump with ducts | | 16,000 | $1,920 |
| Yes | 209416882 | NOVAIR | LEA28MZ-3P-35SK-O | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 209416884 | NOVAIR | LEA20MZ-2P-35SK-O | Heat pump without ducts | | 13,500 | $1,620 |
| Yes | 209416880 | NOVAIR | LEA24SZ35SK-O | LEA24UUSK-I | | 18,900 | $2,268 |
| Yes | 209416886 | NOVAIR | LEA20MZ-2P-35SK-O | Combination heat pumps with or without ducts | | 15,200 | $1,824 |
| Yes | 205281392 | NOVAIR PLUS | 24EVONVO | 24EVDNVI | | 17,200 | $2,064 |
| Yes | 10221204 | PANASONIC | CU-4E24RBU-5 | Heat pump without ducts | | 35,700 | $4,284 |
| Yes | 10208229 | PANASONIC | CU-2E18SBU-5 | Heat pump without ducts | | 17,400 | $2,088 |
| Yes | 10221207 | PANASONIC | CU5E36QBU5 | Heat pump without ducts | | 28,000 | $3,360 |
| Yes | 205047855 | PANASONIC | CU-XE24WKUA | CS-XE24WKUAW | | 18,500 | $2,220 |
| Yes | 201900302 | PANASONIC | CU-XE15SKUA-1 | CS-XE15SKUA-1 | | 18,200 | $2,184 |
| Yes | 208447904 | PAYNE | 38MURAQ48AB3 | 40MUAAQ48XA3 | | 36,000 | $4,320 |
| Yes | 208447901 | PAYNE | 38MURAQ36AB3 | 40MUAAQ36XA3 | | 30,400 | $3,648 |
| Yes | 208447897 | PAYNE | 38MURAQ24AB3 | 40MUAAQ24XA3 | | 19,200 | $2,304 |
| Yes | 208447898 | PAYNE | 38MURAQ18AB3 | 40MUAAQ18XA3 | | 13,500 | $1,620 |
| Yes | 207642933 | PAYNE | 38MGHBQ36DA3 | Heat pump without ducts | | 23,200 | $2,784 |
| Yes | 207642930 | PAYNE | 38MGHBQ48EA3 | Heat pump without ducts | | 30,000 | $3,600 |
| Yes | 207642924 | PAYNE | 38MGHBQ30DA3 | Heat pump without ducts | | 17,500 | $2,100 |
| Yes | 204722816 | PAYNE | 38MGRQ30D--3 | Heat pump without ducts | | 17,400 | $2,088 |
| Yes | 201846984 | PAYNE | 38MGRQ36D--3 | Heat pump without ducts | | 23,200 | $2,784 |
| Yes | 207826669 | PAYNE | 38MARBQ18AA3 | 40MBABQ18XB3 | | 12,000 | $1,440 |
| Yes | 207801580 | PAYNE | 38MARBQ18AA3 | 40MBDQ24---3 | | 12,600 | $1,512 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204344202 | PAYNE | 38MAQB30R--3 | FV4CN(B,F)003 | | 20,200 | $2,424 |
| Yes | 204344201 | PAYNE | 38MAQB24R--3 | FV4CNF002 | | 14,000 | $1,680 |
| Yes | 203381006 | PAYNE | 38MAQB24R--3 | FM(C,U)4Z24**AL* | | 15,000 | $1,800 |
| Yes | 203381005 | PAYNE | 38MAQB18R--3 | FM(C,U)4Z18**AL* | | 12,600 | $1,512 |
| Yes | 207642934 | PAYNE | 38MGHBQ36DA3 | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 207642925 | PAYNE | 38MGHBQ30DA3 | Heat pump with ducts | | 19,000 | $2,280 |
| Yes | 207642931 | PAYNE | 38MGHBQ48EA3 | Heat pump with ducts | | 28,000 | $3,360 |
| Yes | 207642926 | PAYNE | 38MGHBQ30DA3 | Combination heat pumps with or without ducts | | 18,200 | $2,184 |
| Yes | 207642935 | PAYNE | 38MGHBQ36DA3 | Combination heat pumps with or without ducts | | 23,000 | $2,760 |
| Yes | 207642932 | PAYNE | 38MGHBQ48EA3 | Combination heat pumps with or without ducts | | 29,000 | $3,480 |
| Yes | 206350355 | PAYNE | 38MARBQ18AA3 | 40MBDQ18--3 | | 12,700 | $1,524 |
| Yes | 206188267 | PAYNE | 38MARBQ24AA3 | 40MBAAQ24XA3 | | 16,500 | $1,980 |
| Yes | 206350316 | PAYNE | 38MARBQ24AA3 | DHMAHBQ24XA3 | | 19,800 | $2,376 |
| Yes | 206350357 | PAYNE | 38MARBQ24AA3 | 40MBCQ24--3 | | 14,500 | $1,740 |
| Yes | 206350359 | PAYNE | 38MARBQ24AA3 | 40MBFQ24--3 | | 14,500 | $1,740 |
| Yes | 206350356 | PAYNE | 38MARBQ18AA3 | 40MBFQ18--3 | | 12,000 | $1,440 |
| Yes | 206350358 | PAYNE | 38MARBQ24AA3 | 40MBDQ24--3 | | 14,500 | $1,740 |
| Yes | 205921386 | PAYNE | 38MAQB24R--3 | 40MBAAQ24XA3 | | 17,500 | $2,100 |
| Yes | 202463639 | PAYNE | 38MPRAQ24AA3 | DHMPHAQ24XA3 | | 15,450 | $1,854 |
| Yes | 201847047 | PAYNE | 38MBRQ48A--3 | 40MBFQ48---3 | | 35,000 | $4,200 |
| Yes | 201847045 | PAYNE | 38MAQB24R--3 | 40MBFQ24---3 | | 17,200 | $2,064 |
| Yes | 201846978 | PAYNE | 38MAQB24R--3 | 40MBDQ24---3 | | 17,300 | $2,076 |
| Yes | 201847069 | PAYNE | 38MGRQ36D--3 | Heat pump with ducts | | 24,600 | $2,952 |
| Yes | 204711114 | PAYNE | 38MGRQ30D--3 | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 204722803 | PAYNE | 38MGRQ36D--3 | Combination heat pumps with or without ducts | | 23,800 | $2,856 |
| Yes | 204722802 | PAYNE | 38MGRQ30D--3 | Combination heat pumps with or without ducts | | 20,200 | $2,424 |
| Yes | 211253528 | PERFECTAIRE | 3PAHHSD60-SZO | 3PAHHSD60-AHU | | 42,000 | $5,040 |
| Yes | 211253527 | PERFECTAIRE | 3PAHHSD48-SZO | 3PAHHSD48-AHU | | 36,000 | $4,320 |
| Yes | 211253524 | PERFECTAIRE | 3PAHHSD24-SZO | 3PAHHSD24-AHU | | 19,200 | $2,304 |
| Yes | 211253523 | PERFECTAIRE | 3PAHHSD18-SZO | 3PAHHSD18-AHU | | 13,500 | $1,620 |
| Yes | 211253533 | PERFECTAIRE | 3PAMS55-HH-MZO5 | Heat pump with ducts | | 35,200 | $4,224 |
| Yes | 211253532 | PERFECTAIRE | 3PAMS55-HH-MZO5 | Heat pump without ducts | | 34,800 | $4,176 |
| Yes | 207657341 | PERFECTAIRE | 3PAMS36-HH-MZO4 | Heat pump without ducts | | 35,000 | $4,200 |
| Yes | 207657339 | PERFECTAIRE | 3PAMS27-HH-MZO3 | Heat pump without ducts | | 25,600 | $3,072 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 207657336 | PERFECTAIRE | 3PAMS18-HH-MZO2 | Heat pump with ducts | | 16,000 | $1,920 |
| Yes | 207657345 | PERFECTAIRE | 3PAMS48-HH-MZO5 | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 207657338 | PERFECTAIRE | 3PAMS27-HH-MZO3 | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 207657344 | PERFECTAIRE | 3PAMS48-HH-MZO5 | Heat pump without ducts | | 39,000 | $4,680 |
| Yes | 207657335 | PERFECTAIRE | 3PAMS18-HH-MZO2 | Heat pump without ducts | | 13,500 | $1,620 |
| Yes | 207796635 | PERFECTAIRE | 3PAMSHH24-SZO | 3PAMSCH24 | | 21,000 | $2,520 |
| Yes | 207614056 | PERFECTAIRE | 3PAMSHH24-SZO | 3PAMSHH24-UVW | | 18,900 | $2,268 |
| Yes | 207796636 | PERFECTAIRE | 3PAMSHH24-SZO | 3PAMSDH24 | | 21,000 | $2,520 |
| Yes | 207192291 | PERFECTAIRE | 1PAMSHH24-SZW-20.5 | 2PAMSDH24 | | 21,000 | $2,520 |
| Yes | 206348127 | PERFECTAIRE | 1KARDA24SZO20.5 | 2PAMSDH24 | | 21,000 | $2,520 |
| Yes | 206348126 | PERFECTAIRE | 2KARDA18SZO20 | 2PAMSDH18 | | 15,000 | $1,800 |
| Yes | 207796633 | PERFECTAIRE | 3PAMSHH18-SZO | 3PAMSDH18 | | 15,000 | $1,800 |
| Yes | 9856849 | PERFECTAIRE | 1PAMSHH24-SZO-20.5 | 1PAMSHH24-SZW-20.5 | | 15,400 | $1,848 |
| Yes | 205645142 | PERFECTAIRE | 2PAMS48-HH-MZO5 | Heat pump with ducts | | 28,000 | $3,360 |
| Yes | 205645135 | PERFECTAIRE | 2PAMS27-HH-MZO3 | Heat pump without ducts | | 18,000 | $2,160 |
| Yes | 207657342 | PERFECTAIRE | 3PAMS36-HH-MZO4 | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 207657337 | PERFECTAIRE | 3PAMS18-HH-MZO2 | Combination heat pumps with or without ducts | | 15,200 | $1,824 |
| Yes | 207657343 | PERFECTAIRE | 3PAMS36-HH-MZO4 | Combination heat pumps with or without ducts | | 22,400 | $2,688 |
| Yes | 205645141 | PERFECTAIRE | 2PAMS48-HH-MZO5 | Heat pump without ducts | | 30,000 | $3,600 |
| Yes | 207657346 | PERFECTAIRE | 3PAMS48-HH-MZO5 | Combination heat pumps with or without ducts | | 31,000 | $3,720 |
| Yes | 212394346 | PolarWave | ACIQ-30-HPB | ACIQ-30-ACL | | 22,600 | $2,712 |
| Yes | 212316114 | PolarWave | ACIQ-18ZPL-HP230B | SCC-1218-HH-M | | 14,500 | $1,740 |
| Yes | 212316107 | PolarWave | ACIQ-60ZPL-HP230B | ACIQ-60CD-HH-MB | | 40,000 | $4,800 |
| Yes | 212316110 | PolarWave | ACIQ-60ZPL-HP230B | ACIQ-60FM-HH-MB | | 40,000 | $4,800 |
| Yes | 212316119 | PolarWave | ACIQ-55Z-HH-M5B | Combination heat pumps with or without ducts | | 34,800 | $4,176 |
| Yes | 212316118 | PolarWave | ACIQ-55Z-HH-M5B | Heat pump with ducts | | 35,200 | $4,224 |
| Yes | 212316117 | PolarWave | ACIQ-55Z-HH-M5B | Heat pump without ducts | | 34,400 | $4,128 |
| Yes | 212316093 | PolarWave | ACIQ-36Z-HH-M4B | Combination heat pumps with or without ducts | | 34,000 | $4,080 |
| Yes | 212316091 | PolarWave | ACIQ-36Z-HH-M4B | Heat pump without ducts | | 33,000 | $3,960 |
| Yes | 212316106 | PolarWave | ACIQ-48ZPL-HP230B | ACIQ-48CD-HH-MB | | 39,500 | $4,740 |
| Yes | 212316104 | PolarWave | ACIQ-48ZPL-HP230B | ACIQ-48CC-HH-MB | | 35,000 | $4,200 |
| Yes | 212316109 | PolarWave | ACIQ-48ZPL-HP230B | ACIQ-48FM-HH-MB | | 35,000 | $4,200 |
| Yes | 212316103 | PolarWave | ACIQ-36ZPL-HP230B | ACIQ-36CC-HH-MB | | 33,000 | $3,960 |
| Yes | 212316108 | PolarWave | ACIQ-36ZPL-HP230B | ACIQ-36FM-HH-MB | | 32,000 | $3,840 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 212316096 | PolarWave | ACIQ-48Z-HH-M5B | Combination heat pumps with or without ducts | | 36,000 | $4,320 |
| Yes | 212316090 | PolarWave | ACIQ-27Z-HH-M3B | Combination heat pumps with or without ducts | | 26,800 | $3,216 |
| Yes | 212316087 | PolarWave | ACIQ-18Z-HH-M2B | Combination heat pumps with or without ducts | | 15,500 | $1,860 |
| Yes | 212316085 | PolarWave | ACIQ-18Z-HH-M2B | Heat pump without ducts | | 15,000 | $1,800 |
| Yes | 212316095 | PolarWave | ACIQ-48Z-HH-M5B | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 212316094 | PolarWave | ACIQ-48Z-HH-M5B | Heat pump without ducts | | 36,000 | $4,320 |
| Yes | 212316089 | PolarWave | ACIQ-27Z-HH-M3B | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 212316088 | PolarWave | ACIQ-27Z-HH-M3B | Heat pump without ducts | | 26,600 | $3,192 |
| Yes | 212316086 | PolarWave | ACIQ-18Z-HH-M2B | Heat pump with ducts | | 16,000 | $1,920 |
| Yes | 212316081 | PolarWave | ACIQ-24ZPL-HP230B | ACIQ-24CD-HH-MB | | 21,000 | $2,520 |
| Yes | 212316084 | PolarWave | ACIQ-24ZPL-HP230B | ACIQ-24FM-HH-MB | | 19,000 | $2,280 |
| Yes | 212316080 | PolarWave | ACIQ-18ZPL-HP230B | ACIQ-18CD-HH-MB | | 15,000 | $1,800 |
| Yes | 212316074 | PolarWave | ACIQ-24ZPL-HP230B | ACIQ-24W-HH-MB | | 21,200 | $2,544 |
| Yes | 212316102 | PolarWave | ACIQ-24ZPL-HP230B | ACIQ-24W-HH-MC | | 21,200 | $2,544 |
| Yes | 212316101 | PolarWave | ACIQ-18ZPL-HP230B | ACIQ-18W-HH-MC | | 15,000 | $1,800 |
| Yes | 212316073 | PolarWave | ACIQ-18ZPL-HP230B | ACIQ-18W-HH-MB | | 15,000 | $1,800 |
| Yes | 10595430 | RHEEM | ROMH36FXZHJ | Heat pump without ducts | | 21,400 | $2,568 |
| Yes | 10595424 | RHEEM | ROMH24FXZHJ | Heat pump without ducts | | 15,400 | $1,848 |
| Yes | 10595418 | RHEEM | ROMH18FXZHJ | Heat pump without ducts | | 14,200 | $1,704 |
| Yes | 10595420 | RHEEM | ROMH18FXZHJ | Heat pump with ducts | | 14,200 | $1,704 |
| Yes | 10595426 | RHEEM | ROMH24FXZHJ | Heat pump with ducts | | 15,400 | $1,848 |
| Yes | 10595432 | RHEEM | ROMH36FXZHJ | Heat pump with ducts | | 21,400 | $2,568 |
| Yes | 10595377 | RHEEM | ROSH18AHXHJ | RIWH18AVFJ | | 14,600 | $1,752 |
| Yes | 10595381 | RHEEM | ROSH30AHXHJ | RIWH30AVFJ | | 18,900 | $2,268 |
| Yes | 10595409 | RHEEM | ROSH18AFCJ | RICH18AVFJ | | 13,600 | $1,632 |
| Yes | 10061720 | RHEEM | ROSH18AXFWJ | RIWH18AVFJ | | 14,600 | $1,752 |
| Yes | 10595403 | RHEEM | ROSH18AFCJ | RIDH18AVFJ | | 13,600 | $1,632 |
| Yes | 10061706 | RHEEM | ROSH24ASJ | RIWH24ASJ | | 15,300 | $1,836 |
| Yes | 202245794 | RHEEM | ROSH36VGSN | RICH36AXCJ | | 23,200 | $2,784 |
| Yes | 202245032 | RHEEM | ROSH30VGSN | RICH30AXCJ | | 20,200 | $2,424 |
| Yes | 10595428 | RHEEM | ROMH24FXZHJ | Combination heat pumps with or without ducts | | 15,400 | $1,848 |
| Yes | 202244731 | RHEEM | ROSH24VGSN | RICH24AXCJ | | 16,400 | $1,968 |
| Yes | 202244046 | RHEEM | ROSH18VGSN | RICH18AXCJ | | 12,300 | $1,476 |
| Yes | 10595434 | RHEEM | ROMH36FXZHJ | Combination heat pumps with or without ducts | | 21,400 | $2,568 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 10595422 | RHEEM | ROMH18FXZHJ | Combination heat pumps with or without ducts | | 14,200 | $1,704 |
| Yes | 212400612 | RUNTRU | E4HL5018A1000A | 4TXCB003DS3 | | 20,000 | $2,400 |
| Yes | 212394369 | RUNTRU | E4HL5024A1000A | 4TXCB003DS3 | | 20,000 | $2,400 |
| Yes | 212394368 | RUNTRU | E4HL5024A1000A | 4TXCB004DS3 | | 20,000 | $2,400 |
| Yes | 210488278 | RUNTRU | M4THM1942A15N** | Heat pump without ducts | | 35,600 | $4,272 |
| Yes | 210488277 | RUNTRU | M4THM1936A14N** | Heat pump without ducts | | 30,800 | $3,696 |
| Yes | 205118701 | RUNTRU | M4THS1824A11N** | M4MHW1824A1N0** | | 14,600 | $1,752 |
| Yes | 206221523 | RUUD | ROMH24FXZHJ | Heat pump without ducts | | 15,400 | $1,848 |
| Yes | 206221522 | RUUD | ROMH18FXZHJ | Combination heat pumps with or without ducts | | 14,200 | $1,704 |
| Yes | 206221525 | RUUD | ROMH24FXZHJ | Combination heat pumps with or without ducts | | 15,400 | $1,848 |
| Yes | 206221539 | RUUD | ROSH24VGSN | RICH24AXCJ | | 16,400 | $1,968 |
| Yes | 206221519 | RUUD | ROSH18AFCJ | RICH18AVFJ | | 13,600 | $1,632 |
| Yes | 206221507 | RUUD | ROSH30AHXHJ | UIWH30AVFJ | | 18,900 | $2,268 |
| Yes | 206221524 | RUUD | ROMH24FXZHJ | Heat pump with ducts | | 15,400 | $1,848 |
| Yes | 206221521 | RUUD | ROMH18FXZHJ | Heat pump with ducts | | 14,200 | $1,704 |
| Yes | 206221526 | RUUD | ROMH36FXZHJ | Heat pump without ducts | | 21,400 | $2,568 |
| Yes | 206221520 | RUUD | ROMH18FXZHJ | Heat pump without ducts | | 14,200 | $1,704 |
| Yes | 206221527 | RUUD | ROMH36FXZHJ | Heat pump with ducts | | 21,400 | $2,568 |
| Yes | 206221505 | RUUD | ROSH18AHXHJ | UIWH18AVFJ | | 14,600 | $1,752 |
| Yes | 206221499 | RUUD | ROSH18AXFWJ | UIWH18AVFJ | | 14,600 | $1,752 |
| Yes | 206221492 | RUUD | ROSH24ASJ | UIWH24ASJ | | 15,300 | $1,836 |
| Yes | 206221516 | RUUD | ROSH18AFCJ | RIDH18AVFJ | | 13,600 | $1,632 |
| Yes | 206221541 | RUUD | ROSH36VGSN | RICH36AXCJ | | 23,200 | $2,784 |
| Yes | 206221540 | RUUD | ROSH30VGSN | RICH30AXCJ | | 20,200 | $2,424 |
| Yes | 206221538 | RUUD | ROSH18VGSN | RICH18AXCJ | | 12,300 | $1,476 |
| Yes | 206221528 | RUUD | ROMH36FXZHJ | Combination heat pumps with or without ducts | | 21,400 | $2,568 |
| Yes | 10147097 | SAMSUNG | AM060MXMDCH | Heat pump without ducts | | 43,000 | $5,160 |
| Yes | 10147096 | SAMSUNG | AM060MXMDCH | Heat pump with ducts | | 43,000 | $5,160 |
| Yes | 202083996 | SAMSUNG | AM060NXMDCR | Heat pump without ducts | | 43,000 | $5,160 |
| Yes | 202084065 | SAMSUNG | AM060NXMDCR | Heat pump with ducts | | 43,000 | $5,160 |
| Yes | 205230040 | SAMSUNG | AM053TXMDCH | Heat pump without ducts | | 36,400 | $4,368 |
| Yes | 205142812 | SAMSUNG | AM053TXMDCH | Heat pump with ducts | | 36,400 | $4,368 |
| Yes | 202083810 | SAMSUNG | AM053NXMDCR | Heat pump without ducts | | 36,400 | $4,368 |
| Yes | 202083811 | SAMSUNG | AM053NXMDCR | Heat pump with ducts | | 36,400 | $4,368 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 205142810 | SAMSUNG | AM048TXMDCH | Heat pump without ducts | | 31,600 | $3,792 |
| Yes | 205230039 | SAMSUNG | AM048TXMDCH | Heat pump with ducts | | 29,000 | $3,480 |
| Yes | 202057118 | SAMSUNG | AM048NXMDCR | Heat pump without ducts | | 31,600 | $3,792 |
| Yes | 202083773 | SAMSUNG | AM048NXMDCR | Heat pump with ducts | | 29,000 | $3,480 |
| Yes | 205142809 | SAMSUNG | AM036TXMDCH | Heat pump without ducts | | 25,000 | $3,000 |
| Yes | 205230038 | SAMSUNG | AM036TXMDCH | Heat pump with ducts | | 25,000 | $3,000 |
| Yes | 202098116 | SAMSUNG | AM036NXMDCR | Heat pump without ducts | | 25,000 | $3,000 |
| Yes | 202064264 | SAMSUNG | AM036NXMDCR | Heat pump with ducts | | 25,000 | $3,000 |
| Yes | 211133470 | SAMSUNG | AC060BXUPCH | BVRMC7960 | | 54,000 | $6,480 |
| Yes | 211133472 | SAMSUNG | AC048BXUPCH | BVRMC3948 | | 46,000 | $5,520 |
| Yes | 211133469 | SAMSUNG | AC036BXUPCH | BVRMC3937 | | 40,500 | $4,860 |
| Yes | 211133468 | SAMSUNG | AC036BXUDCH | BVRMC3937 | | 36,000 | $4,320 |
| Yes | 211133471 | SAMSUNG | AC024BXUPCH | BVRMB3925 | | 31,200 | $3,744 |
| Yes | 207698067 | SAMSUNG | AC036BXSCCH | AC036BNZDCH | | 37,000 | $4,440 |
| Yes | 207465458 | SAMSUNG | AC030BXADCH | AC030BNHDCH | | 33,000 | $3,960 |
| Yes | 207465436 | SAMSUNG | AC048BXADCH | AC048BN4DCH | | 46,000 | $5,520 |
| Yes | 207462391 | SAMSUNG | AC042BXADCH | AC042BN4DCH | | 46,000 | $5,520 |
| Yes | 207462390 | SAMSUNG | AC036BXADCH | AC036BN4DCH | | 37,000 | $4,440 |
| Yes | 207465461 | SAMSUNG | AC036BXADCH | AC036BN6DCH | | 33,600 | $4,032 |
| Yes | 207698066 | SAMSUNG | AC030BXSCCH | AC030BNZDCH | | 31,800 | $3,816 |
| Yes | 207698072 | SAMSUNG | AC036BXSCCH | AC036BNHDCH | | 38,500 | $4,620 |
| Yes | 207465448 | SAMSUNG | AC018BXADCH | AC018BNHDCH | | 25,600 | $3,072 |
| Yes | 207698071 | SAMSUNG | AC036BXSCCH | AC036BN4DCH | | 40,500 | $4,860 |
| Yes | 207698065 | SAMSUNG | AC030BXSCCH | AC030BN4DCH | | 37,000 | $4,440 |
| Yes | 207462388 | SAMSUNG | AC018BXADCH | AC018BN4DCH | | 27,600 | $3,312 |
| Yes | 207462389 | SAMSUNG | AC024BXADCH | AC024BN4DCH | | 31,200 | $3,744 |
| Yes | 210273924 | SAMSUNG | AC036BXUPCH | AV360CT | | 40,500 | $4,860 |
| Yes | 210299847 | SAMSUNG | AC048BXUPCH | AV480CT | | 46,000 | $5,520 |
| Yes | 210273925 | SAMSUNG | AC060BXUPCH | AV600CT | | 54,000 | $6,480 |
| Yes | 210273923 | SAMSUNG | AC036BXUDCH | AV360CT | | 36,000 | $4,320 |
| Yes | 210299846 | SAMSUNG | AC024BXUPCH | AV240BT | | 31,200 | $3,744 |
| Yes | 207698068 | SAMSUNG | AC030BXSCCH/AA | AC030KNZDCH/AA | | 18,800 | $2,256 |
| Yes | 207598068 | SAMSUNG | AC024BXADCH | AC024KNZDCH | | 16,300 | $1,956 |
| Yes | 207598067 | SAMSUNG | AC018BXADCH | AC018KNZDCH | | 12,000 | $1,440 |
| Yes | 207349920 | SAMSUNG | AJ036BXS4CH | Heat pump without ducts | | 19,500 | $2,340 |
| Yes | 207349919 | SAMSUNG | AJ030BXS4CH | Heat pump without ducts | | 14,500 | $1,740 |
| Yes | 207349918 | SAMSUNG | AJ024BXS4CH | Heat pump without ducts | | 14,600 | $1,752 |
| Yes | 207598069 | SAMSUNG | AC030BXADCH | AC030KNZDCH | | 21,400 | $2,568 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 207598071 | SAMSUNG | AC042BXADCH | AC042KNZDCH | | 28,000 | $3,360 |
| Yes | 207598070 | SAMSUNG | AC036BXADCH | AC036KNZDCH | | 25,800 | $3,096 |
| Yes | 207598072 | SAMSUNG | AC048BXADCH | AC048KNZDCH | | 32,200 | $3,864 |
| Yes | 207350834 | SAMSUNG | AJ036BXS4CH | Combination heat pumps with or without ducts | | 19,500 | $2,340 |
| Yes | 211126514 | SEA BREEZE+ | CSZ36H424ZMO | AH36H424ZMI | | 28,600 | $3,432 |
| Yes | 208128297 | SEA BREEZE+ | HMZ36H424ZMO | Heat pump without ducts | | 35,000 | $4,200 |
| Yes | 208816899 | SEA BREEZE+ | HMZ48H424ZMO | Heat pump with ducts | | 35,200 | $4,224 |
| Yes | 208816898 | SEA BREEZE+ | HMZ48H424ZMO | Heat pump without ducts | | 34,800 | $4,176 |
| Yes | 208128294 | SEA BREEZE+ | HMZ28H424ZMO | Heat pump without ducts | | 25,600 | $3,072 |
| Yes | 208816893 | SEA BREEZE+ | HMZ18H424ZMO | Heat pump with ducts | | 16,000 | $1,920 |
| Yes | 208128295 | SEA BREEZE+ | HMZ28H424ZMO | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 208816892 | SEA BREEZE+ | HMZ18H424ZMO | Heat pump without ducts | | 13,500 | $1,620 |
| Yes | 208816896 | SEA BREEZE+ | HMZ24H424ZMO | Heat pump with ducts | | 24,000 | $2,880 |
| Yes | 208816895 | SEA BREEZE+ | HMZ24H424ZMO | Heat pump without ducts | | 24,000 | $2,880 |
| Yes | 208128275 | SEA BREEZE+ | CSZ48H424ZMO | CA48H424ZMI | | 35,000 | $4,200 |
| Yes | 208128274 | SEA BREEZE+ | CSZ36H424ZMO | CA36H424ZMI | | 33,000 | $3,960 |
| Yes | 208816891 | SEA BREEZE+ | HSZ24H424ZMO | WM24H424ZMI | | 18,900 | $2,268 |
| Yes | 208128299 | SEA BREEZE+ | HMZ36H424ZMO | Combination heat pumps with or without ducts | | 22,400 | $2,688 |
| Yes | 208128298 | SEA BREEZE+ | HMZ36H424ZMO | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 208816900 | SEA BREEZE+ | HMZ48H424ZMO | Combination heat pumps with or without ducts | | 35,600 | $4,272 |
| Yes | 207641344 | SENVILLE | SENA/24HF/OQ | SENA/24HF/ICQ | | 21,000 | $2,520 |
| Yes | 207641348 | SENVILLE | SENA/24HF/OQ | SENA/24HF/ID | | 21,000 | $2,520 |
| Yes | 207641351 | SENVILLE | SENA/24HF/OQ | SENA/24HF/IF | | 19,000 | $2,280 |
| Yes | 207641347 | SENVILLE | SENA/18HF/OQ | SENA/18HF/ID | | 15,000 | $1,800 |
| Yes | 207571421 | SENVILLE | SENA/24HF/OQ | SENA/24HF/IQ | | 21,200 | $2,544 |
| Yes | 207657630 | SENVILLE | SENA/24HF/OQ | SENA/24HF/IQ | | 21,200 | $2,544 |
| Yes | 207657629 | SENVILLE | SENA/18HF/OQ | SENA/18HF/IQ | | 15,000 | $1,800 |
| Yes | 207571420 | SENVILLE | SENA/18HF/OQ | SENA/18HF/IQ | | 15,000 | $1,800 |
| Yes | 205921393 | SENVILLE | SENA/24HF/OZ | SENA/24HF/ID | | 17,200 | $2,064 |
| Yes | 208447943 | SLIMAIR | SHCD24VC2AG | SHMZ24VC2AG | | 18,900 | $2,268 |
| Yes | 209852127 | SMART COMFORT | DLCURAH48ABK | DLFUAAH48XAK | | 36,000 | $4,320 |
| Yes | 209852131 | SMART COMFORT | DLCURAH36ABK | DLFUAAH36XAK | | 30,400 | $3,648 |
| Yes | 209852125 | SMART COMFORT | DLCURAH24ABK | DLFUAAH24XAK | | 19,200 | $2,304 |
| Yes | 209852124 | SMART COMFORT | DLCURAH18ABK | DLFUAAH18XAK | | 13,500 | $1,620 |
| Yes | 207643170 | SMART COMFORT | DLCMHBH36DAK | Heat pump without ducts | | 22,000 | $2,640 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 207643167 | SMART COMFORT | DLCMHBH48EAK | Heat pump without ducts | | 34,000 | $4,080 |
| Yes | 207643161 | SMART COMFORT | DLCMHBH30DAK | Heat pump without ducts | | 18,500 | $2,220 |
| Yes | 207643162 | SMART COMFORT | DLCMHBH30DAK | Heat pump with ducts | | 19,000 | $2,280 |
| Yes | 207643171 | SMART COMFORT | DLCMHBH36DAK | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 207643168 | SMART COMFORT | DLCMHBH48EAK | Heat pump with ducts | | 28,000 | $3,360 |
| Yes | 207643172 | SMART COMFORT | DLCMHBH36DAK | Combination heat pumps with or without ducts | | 22,400 | $2,688 |
| Yes | 207643163 | SMART COMFORT | DLCMHBH30DAK | Combination heat pumps with or without ducts | | 18,700 | $2,244 |
| Yes | 207643169 | SMART COMFORT | DLCMHBH48EAK | Combination heat pumps with or without ducts | | 31,000 | $3,720 |
| Yes | 202119285 | SMART COMFORT | DLCSRAH24AAK | DLFSCAH24XAK | | 16,200 | $1,944 |
| Yes | 202463659 | SMART COMFORT | DLCPRAH24AAK | DLFPHAH24XAK | | 15,450 | $1,854 |
| Yes | 202119265 | SMART COMFORT | DLCSRAH24AAK | DLFSHAH24XAK | | 15,000 | $1,800 |
| Yes | 202119336 | SMART COMFORT | DLCLRAH48AAK | DLFLFAH48XAK | | 35,000 | $4,200 |
| Yes | 202119284 | SMART COMFORT | DLCSRAH24AAK | DLFSFAH24XAK | | 17,200 | $2,064 |
| Yes | 202119282 | SMART COMFORT | DLCSRAH18AAK | DLFSCAH18XAK | | 12,000 | $1,440 |
| Yes | 212394357 | STEALTH | ACIQ-30-HPB | ACIQ-30-ACL | | 22,600 | $2,712 |
| Yes | 212316200 | STEALTH | ACIQ-18ZPL-HP230B | SCC-1218-HH-M | | 14,500 | $1,740 |
| Yes | 212316193 | STEALTH | ACIQ-60ZPL-HP230B | ACIQ-60CD-HH-MB | | 40,000 | $4,800 |
| Yes | 212316196 | STEALTH | ACIQ-60ZPL-HP230B | ACIQ-60FM-HH-MB | | 40,000 | $4,800 |
| Yes | 212316205 | STEALTH | ACIQ-55Z-HH-M5B | Combination heat pumps with or without ducts | | 34,800 | $4,176 |
| Yes | 212316204 | STEALTH | ACIQ-55Z-HH-M5B | Heat pump with ducts | | 35,200 | $4,224 |
| Yes | 212316203 | STEALTH | ACIQ-55Z-HH-M5B | Heat pump without ducts | | 34,400 | $4,128 |
| Yes | 212316179 | STEALTH | ACIQ-36Z-HH-M4B | Combination heat pumps with or without ducts | | 34,000 | $4,080 |
| Yes | 212316177 | STEALTH | ACIQ-36Z-HH-M4B | Heat pump without ducts | | 33,000 | $3,960 |
| Yes | 212316192 | STEALTH | ACIQ-48ZPL-HP230B | ACIQ-48CD-HH-MB | | 39,500 | $4,740 |
| Yes | 212316190 | STEALTH | ACIQ-48ZPL-HP230B | ACIQ-48CC-HH-MB | | 35,000 | $4,200 |
| Yes | 212316195 | STEALTH | ACIQ-48ZPL-HP230B | ACIQ-48FM-HH-MB | | 35,000 | $4,200 |
| Yes | 212316189 | STEALTH | ACIQ-36ZPL-HP230B | ACIQ-36CC-HH-MB | | 33,000 | $3,960 |
| Yes | 212316194 | STEALTH | ACIQ-36ZPL-HP230B | ACIQ-36FM-HH-MB | | 32,000 | $3,840 |
| Yes | 212316182 | STEALTH | ACIQ-48Z-HH-M5B | Combination heat pumps with or without ducts | | 36,000 | $4,320 |
| Yes | 212316176 | STEALTH | ACIQ-27Z-HH-M3B | Combination heat pumps with or without ducts | | 26,800 | $3,216 |
| Yes | 212316173 | STEALTH | ACIQ-18Z-HH-M2B | Combination heat pumps with or without ducts | | 15,500 | $1,860 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 212316171 | STEALTH | ACIQ-18Z-HH-M2B | Heat pump without ducts | | 15,000 | $1,800 |
| Yes | 212316181 | STEALTH | ACIQ-48Z-HH-M5B | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 212316180 | STEALTH | ACIQ-48Z-HH-M5B | Heat pump without ducts | | 36,000 | $4,320 |
| Yes | 212316175 | STEALTH | ACIQ-27Z-HH-M3B | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 212316174 | STEALTH | ACIQ-27Z-HH-M3B | Heat pump without ducts | | 26,600 | $3,192 |
| Yes | 212316172 | STEALTH | ACIQ-18Z-HH-M2B | Heat pump with ducts | | 16,000 | $1,920 |
| Yes | 212316167 | STEALTH | ACIQ-24ZPL-HP230B | ACIQ-24CD-HH-MB | | 21,000 | $2,520 |
| Yes | 212316170 | STEALTH | ACIQ-24ZPL-HP230B | ACIQ-24FM-HH-MB | | 19,000 | $2,280 |
| Yes | 212316166 | STEALTH | ACIQ-18ZPL-HP230B | ACIQ-18CD-HH-MB | | 15,000 | $1,800 |
| Yes | 212316160 | STEALTH | ACIQ-24ZPL-HP230B | ACIQ-24W-HH-MB | | 21,200 | $2,544 |
| Yes | 212316188 | STEALTH | ACIQ-24ZPL-HP230B | ACIQ-24W-HH-MC | | 21,200 | $2,544 |
| Yes | 212316187 | STEALTH | ACIQ-18ZPL-HP230B | ACIQ-18W-HH-MC | | 15,000 | $1,800 |
| Yes | 212316159 | STEALTH | ACIQ-18ZPL-HP230B | ACIQ-18W-HH-MB | | 15,000 | $1,800 |
| Yes | 206799642 | SUPREME CENTRAL | SUPRM24CC | AHAN3615 | | 15,400 | $1,848 |
| Yes | 210372389 | SUPREME CENTRAL | SUPRM30CC | AHAN3615 | | 16,800 | $2,016 |
| Yes | 209852116 | TEMPSTAR | DLCURAH48ABK | DLFUAAH48XAK | | 36,000 | $4,320 |
| Yes | 209852120 | TEMPSTAR | DLCURAH36ABK | DLFUAAH36XAK | | 30,400 | $3,648 |
| Yes | 209852114 | TEMPSTAR | DLCURAH24ABK | DLFUAAH24XAK | | 19,200 | $2,304 |
| Yes | 209852113 | TEMPSTAR | DLCURAH18ABK | DLFUAAH18XAK | | 13,500 | $1,620 |
| Yes | 207643149 | TEMPSTAR | DLCMHBH36DAK | Heat pump without ducts | | 22,000 | $2,640 |
| Yes | 207643146 | TEMPSTAR | DLCMHBH48EAK | Heat pump without ducts | | 34,000 | $4,080 |
| Yes | 207643140 | TEMPSTAR | DLCMHBH30DAK | Heat pump without ducts | | 18,500 | $2,220 |
| Yes | 206350467 | TEMPSTAR | DLCSRBH24AAK | DLFSCAH24XAK | | 14,500 | $1,740 |
| Yes | 207826609 | TEMPSTAR | DLCSRBH18AAK | DLFSABH18XBK | | 12,000 | $1,440 |
| Yes | 207801575 | TEMPSTAR | DLCSRBH18AAK | DLFSDAH24XAK | | 12,600 | $1,512 |
| Yes | 8177092 | TEMPSTAR | DLCAHB12K1A | DLFAHH12K1A | | 13,000 | $1,560 |
| Yes | 207643141 | TEMPSTAR | DLCMHBH30DAK | Heat pump with ducts | | 19,000 | $2,280 |
| Yes | 207643150 | TEMPSTAR | DLCMHBH36DAK | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 207643147 | TEMPSTAR | DLCMHBH48EAK | Heat pump with ducts | | 28,000 | $3,360 |
| Yes | 207643142 | TEMPSTAR | DLCMHBH30DAK | Combination heat pumps with or without ducts | | 18,700 | $2,244 |
| Yes | 207643151 | TEMPSTAR | DLCMHBH36DAK | Combination heat pumps with or without ducts | | 22,400 | $2,688 |
| Yes | 207643148 | TEMPSTAR | DLCMHBH48EAK | Combination heat pumps with or without ducts | | 31,000 | $3,720 |
| Yes | 206350469 | TEMPSTAR | DLCSRBH24AAK | DLFSFAH24XAK | | 14,500 | $1,740 |
| Yes | 206350466 | TEMPSTAR | DLCSRBH18AAK | DLFSFAH18XAK | | 12,000 | $1,440 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 206188337 | TEMPSTAR | DLCSRBH24AAK | DLFSAAH24XAK | | 16,500 | $1,980 |
| Yes | 206350465 | TEMPSTAR | DLCSRBH18AAK | DLFSDAH18XAK | | 12,700 | $1,524 |
| Yes | 206350468 | TEMPSTAR | DLCSRBH24AAK | DLFSDAH24XAK | | 14,500 | $1,740 |
| Yes | 205921379 | TEMPSTAR | DLCSRAH24AAK | DLFSAAH24XAK | | 17,500 | $2,100 |
| Yes | 201835818 | TEMPSTAR | DLCSRAH24AAK | DLFSCAH24XAK | | 16,200 | $1,944 |
| Yes | 202463657 | TEMPSTAR | DLCPRAH24AAK | DLFPHAH24XAK | | 15,450 | $1,854 |
| Yes | 201835814 | TEMPSTAR | DLCSRAH24AAK | DLFSDAH24XAK | | 17,400 | $2,088 |
| Yes | 201835826 | TEMPSTAR | DLCLRAH48AAK | DLFLFAH48XAK | | 35,000 | $4,200 |
| Yes | 201835773 | TEMPSTAR | DLCSRAH24AAK | DLFSHAH24XAK | | 15,000 | $1,800 |
| Yes | 201835816 | TEMPSTAR | DLCSRAH24AAK | DLFSFAH24XAK | | 17,200 | $2,064 |
| Yes | 201835812 | TEMPSTAR | DLCSRAH18AAK | DLFSCAH18XAK | | 12,000 | $1,440 |
| Yes | 211126504 | THERMAL ZONE | TZPLV602PA | TZHVLE6024JA | | 42,000 | $5,040 |
| Yes | 211126512 | THERMAL ZONE | TZPLV482PA | TZHVLE4821JA | | 36,000 | $4,320 |
| Yes | 211126503 | THERMAL ZONE | TZPLV242PA | TZHVLE2417JA | | 19,200 | $2,304 |
| Yes | 211126509 | THERMAL ZONE | TZPLV182PA | TZHVLE1817JA | | 13,500 | $1,620 |
| Yes | 209549010 | THERMOCORE SYSTEMS | T5HH22S-H224-C | T5HH22S-H224-E | | 21,200 | $2,544 |
| Yes | 209549009 | THERMOCORE SYSTEMS | T5HH22S-H218-C | T5HH22S-H218-E | | 15,000 | $1,800 |
| Yes | 10052879 | TOSHIBA CARRIER | MCY-MAP0487HS-UL | Heat pump without ducts | | 32,000 | $3,840 |
| Yes | 10049878 | TOSHIBA CARRIER | MCY-MAP0367HS-UL | Heat pump with ducts | | 25,000 | $3,000 |
| Yes | 212394300 | TOSOT | TU60-48WADU | TCAT48H/NAA | ML296UH090XV48C-* | 28,200 | $3,384 |
| Yes | 212394299 | TOSOT | TU36-24WADU | TCAT36F/NAA | ML296UH070XV36B-* | 22,000 | $2,640 |
| Yes | 212394298 | TOSOT | TU36-24WADU | TCAT24F/NAA | ML296UH070XV36B-* | 15,600 | $1,872 |
| Yes | 212361365 | TOSOT | TU36-24WADU | TCAT24F/NAA | | 16,800 | $2,016 |
| Yes | 211727025 | TOSOT | TM42HMO | Heat pump without ducts | | 35,600 | $4,272 |
| Yes | 211727024 | TOSOT | TM36HMO | Heat pump without ducts | | 30,800 | $3,696 |
| Yes | 206414275 | TOSOT | TU60-48WADU | TUD48-24AH2ADU | | 31,400 | $3,768 |
| Yes | 206414274 | TOSOT | TU60-48WADU | TUD60-24AH2ADU | | 36,000 | $4,320 |
| Yes | 206414273 | TOSOT | TU36-24WADU | TUD36-24AH2ADU | | 24,000 | $2,880 |
| Yes | 206414272 | TOSOT | TU36-24WADU | TUD24-24AH2ADU | | 16,000 | $1,920 |
| Yes | 204344219 | TOSOT | TM24H5O | Heat pump without ducts | | 17,900 | $2,148 |
| Yes | 204344218 | TOSOT | TM18H5O | Heat pump without ducts | | 17,000 | $2,040 |
| Yes | 10062021 | TOSOT | TW24HQ3D6DO | TW24HQ3D6DI | | 15,500 | $1,860 |
| Yes | 204344218 | TOSOT | TM18H5O | Heat pump without ducts | | 17,000 | $2,040 |
| Yes | 204344218 | TOSOT | TM18H5O | Heat pump without ducts | | 17,000 | $2,040 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204344218 | TOSOT | TM18H5O | Heat pump without ducts | | 17,000 | $2,040 |
| Yes | 204344218 | TOSOT | TM18H5O | Heat pump without ducts | | 17,000 | $2,040 |
| Yes | 204344218 | TOSOT | TM18H5O | Heat pump without ducts | | 17,000 | $2,040 |
| Yes | 211164243 | TOSOT | TM42HX4O | Heat pump without ducts | | 35,600 | $4,272 |
| Yes | 211164242 | TOSOT | TM36HX4O | Heat pump without ducts | | 30,800 | $3,696 |
| Yes | 10062020 | TOSOT | TW18HQ3D6DO | TW18HQ3D6DI | | 14,200 | $1,704 |
| Yes | 204344218 | TOSOT | TM18H5O | Heat pump without ducts | | 17,000 | $2,040 |
| Yes | 205724741 | TOSOT | TU60-48WADU | TU60-48AADU | | 37,200 | $4,464 |
| Yes | 205724740 | TOSOT | TU60-24WADU | TU60-24AADU | | 38,000 | $4,560 |
| Yes | 205984662 | TOSOT | TU60-24WADU | TU48-24AADU | | 33,000 | $3,960 |
| Yes | 205756439 | TOSOT | TU36-24WADU | TU24-36AADU | | 16,300 | $1,956 |
| Yes | 204743191 | TOSOT | TU36-24WADU | TU36-24AADU | | 24,400 | $2,928 |
| Yes | 206322338 | TOSOT | TU60-48WADU | TU48-60AADU | | 32,800 | $3,936 |
| Yes | 204344218 | TOSOT | TM18H5O | Heat pump without ducts | | 17,000 | $2,040 |
| Yes | 9128593 | TOSOT | TMVRF-36KUH | Heat pump with ducts | | 29,400 | $3,528 |
| Yes | 9128596 | TOSOT | TMVRF-48KUH | Heat pump with ducts | | 38,000 | $4,560 |
| Yes | 212361353 | TRANE | 4TXD2036A10NU** | 4RXCB024AS3HC** | | 16,800 | $2,016 |
| Yes | 204340536 | TRANE | 4TXM2324A13NU** | Heat pump without ducts | N/A | 17,900 | $2,148 |
| Yes | 204340534 | TRANE | 4TXM2318A12NU** | Heat pump without ducts | N/A | 17,000 | $2,040 |
| Yes | 9150125 | TRANE | 4TXK3818A10NU** | 4MXW3818A10NU** | | 14,200 | $1,704 |
| Yes | 9150127 | TRANE | 4TXK3824A10NU** | 4MXW3824A10NU** | | 15,500 | $1,860 |
| Yes | 207526597 | TRANE | 4TWV0X48A1 | 4TXCC009DS3 | P0V0C000M50SA+RP | 35,600 | $4,272 |
| Yes | 204780384 | TRANE | 4TWV0048A1 | 4TXCC009DS3 | P0V0C000M50SA+RP | 35,600 | $4,272 |
| Yes | 204780482 | TRANE | 4TWV8049A1 | 4TXCC009DS3 | P0V0C000M50SA+RP | 35,600 | $4,272 |
| Yes | 204780447 | TRANE | 4TWV8048A1 | 4TXCD010DS3 | P0V0C000M50SA+RP | 35,200 | $4,224 |
| Yes | 207526644 | TRANE | 4TWV8X48A1 | 4TXCD010DS3 | P0V0C000M50SA+RP | 35,200 | $4,224 |
| Yes | 10153709 | TRANE | 4TWV0060A1 | TEM8A0D48V41+TDR | | 49,500 | $5,940 |
| Yes | 210435409 | TRANE | 4TXM2142A15N0** | Heat pump without ducts | | 35,600 | $4,272 |
| Yes | 210435408 | TRANE | 4TXM2136A14N0** | Heat pump without ducts | | 30,800 | $3,696 |
| Yes | 10153740 | TRANE | 4TWV8060A1 | TEM8A0D48V41+TDR | | 49,500 | $5,940 |
| Yes | 208141269 | TRANE | 4TXD2036A10NU** | 4MXA2024A10NU** | N/A | 16,300 | $1,956 |
| Yes | 208141272 | TRANE | 4TXD2060A10NU** | 4MXA2060A10NU** | N/A | 36,000 | $4,320 |
| Yes | 208141270 | TRANE | 4TXD2036A10NU** | 4MXA2036A10NU** | N/A | 24,000 | $2,880 |
| Yes | 208141271 | TRANE | 4TXD2060A10NU** | 4MXA2048A10NU** | N/A | 32,000 | $3,840 |
| Yes | 202703126 | TRANE | 4TXK2324A10N0** | 4MXW2324A10N0** | N/A | 14,600 | $1,752 |
| Yes | 211150932 | Trane / Mitsubishi Electric | TRUZH0361KA00NA | PAA-A36CA* | | 28,400 | $3,408 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 211150931 | Trane / Mitsubishi Electric | TRUZH0361KA00NA | PAA-A36BA* | | 28,400 | $3,408 |
| Yes | 211150930 | Trane / Mitsubishi Electric | TRUZH0301KA00NA | PAA-A30BA* | | 23,200 | $2,784 |
| Yes | 211150929 | Trane / Mitsubishi Electric | TRUZH0301KA00NA | PAA-A30AA* | | 23,200 | $2,784 |
| Yes | 211150928 | Trane / Mitsubishi Electric | TRUZH0241HA10NA | PAA-A24BA* | | 16,600 | $1,992 |
| Yes | 211150927 | Trane / Mitsubishi Electric | TRUZH0241HA10NA | PAA-A24AA* | | 16,600 | $1,992 |
| Yes | 209833003 | Trane / Mitsubishi Electric | NTXSPB18B112A* | MSZ-FS18NA*** | | 12,800 | $1,536 |
| Yes | 209833002 | Trane / Mitsubishi Electric | NTXSPH18B112A* | NAXWPH18B112A* | | 12,800 | $1,536 |
| Yes | 209833001 | Trane / Mitsubishi Electric | NTXSPH18B112A* | MSZ-FS18NA*** | | 12,800 | $1,536 |
| Yes | 209832262 | Trane / Mitsubishi Electric | NTXSPH18B112A* | NTXWPH18B112A* | | 12,800 | $1,536 |
| Yes | 209833000 | Trane / Mitsubishi Electric | MUZ-FS18NA*** | NTXWPH18B112A* | | 12,800 | $1,536 |
| Yes | 209424914 | TRANE / MITSUBISHI ELECTRIC | NTXMPH30A132C* | Heat pump without ducts | | 18,000 | $2,160 |
| Yes | 209424910 | TRANE / MITSUBISHI ELECTRIC | NTXMPH24A132C* | Heat pump without ducts | | 14,000 | $1,680 |
| Yes | 209424906 | TRANE / MITSUBISHI ELECTRIC | NTXMPH20A122C* | Heat pump without ducts | | 13,700 | $1,644 |
| Yes | 206223012 | TRANE / MITSUBISHI ELECTRIC | NTXSKH30A112AA | NTXAMT30A112AA | | 21,400 | $2,568 |
| Yes | 207342941 | TRANE / MITSUBISHI ELECTRIC | NTXMPH30A132** | Heat pump without ducts | | 18,000 | $2,160 |
| Yes | 207342939 | TRANE / MITSUBISHI ELECTRIC | NTXMPH24A132** | Heat pump without ducts | | 14,000 | $1,680 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 207342937 | TRANE / MITSUBISHI ELECTRIC | NTXMPH20A122** | Heat pump without ducts | | 13,700 | $1,644 |
| Yes | 204926529 | TRANE / MITSUBISHI ELECTRIC | NTXMMX60A182B* | Combination heat pumps with or without ducts | | 41,000 | $4,920 |
| Yes | 204834257 | TRANE / MITSUBISHI ELECTRIC | NTXMMX60A182B* | Heat pump with ducts | | 40,500 | $4,860 |
| Yes | 202354908 | TRANE / MITSUBISHI ELECTRIC | NTXMPH36A142AA | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 202392010 | TRANE / MITSUBISHI ELECTRIC | NTXMPH42A152AA | Combination heat pumps with or without ducts | | 36,200 | $4,344 |
| Yes | 202373747 | TRANE / MITSUBISHI ELECTRIC | NTXMPH48A182AA | Heat pump without ducts | | 40,000 | $4,800 |
| Yes | 202392014 | TRANE / MITSUBISHI ELECTRIC | NTXMPH48A182AA | Combination heat pumps with or without ducts | | 41,500 | $4,980 |
| Yes | 206908467 | TRANE / MITSUBISHI ELECTRIC | NTXMPH20A122A** | Heat pump without ducts | | 13,000 | $1,560 |
| Yes | 207348706 | TRANE / MITSUBISHI ELECTRIC | NTXMPH30A132** | Combination heat pumps with or without ducts | | 17,200 | $2,064 |
| Yes | 207348705 | TRANE / MITSUBISHI ELECTRIC | NTXMPH24A132** | Combination heat pumps with or without ducts | | 14,000 | $1,680 |
| Yes | 206223066 | TRANE / MITSUBISHI ELECTRIC | NTXSKH36A112AA | TPEADA0361AA70A | | 25,400 | $3,048 |
| Yes | 207518837 | TRANE / MITSUBISHI ELECTRIC | NTXMSH36A142A* | Heat pump with ducts | | 32,000 | $3,840 |
| Yes | 207525861 | TRANE / MITSUBISHI ELECTRIC | NTXMSH36A142A* | Combination heat pumps with or without ducts | | 32,400 | $3,888 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 207517163 | TRANE / MITSUBISHI ELECTRIC | NTXMSH36A142A* | Heat pump without ducts | | 33,000 | $3,960 |
| Yes | 207517165 | TRANE / MITSUBISHI ELECTRIC | NTXMSH42A152A* | Heat pump with ducts | | 32,000 | $3,840 |
| Yes | 207525862 | TRANE / MITSUBISHI ELECTRIC | NTXMSH42A152A* | Combination heat pumps with or without ducts | | 32,000 | $3,840 |
| Yes | 207517164 | TRANE / MITSUBISHI ELECTRIC | NTXMSH42A152A* | Heat pump without ducts | | 32,000 | $3,840 |
| Yes | 207525864 | TRANE / MITSUBISHI ELECTRIC | NTXMSH48A182A* | Combination heat pumps with or without ducts | | 40,500 | $4,860 |
| Yes | 207517167 | TRANE / MITSUBISHI ELECTRIC | NTXMSH48A182A* | Heat pump without ducts | | 39,000 | $4,680 |
| Yes | 207517168 | TRANE / MITSUBISHI ELECTRIC | NTXMSH48A182A* | Heat pump with ducts | | 42,000 | $5,040 |
| Yes | 207525865 | TRANE / MITSUBISHI ELECTRIC | NTXMSM60A182A* | Combination heat pumps with or without ducts | | 41,000 | $4,920 |
| Yes | 207517170 | TRANE / MITSUBISHI ELECTRIC | NTXMSM60A182A* | Heat pump with ducts | | 40,500 | $4,860 |
| Yes | 207517169 | TRANE / MITSUBISHI ELECTRIC | NTXMSM60A182A* | Heat pump without ducts | | 41,500 | $4,980 |
| Yes | 206908470 | TRANE / MITSUBISHI ELECTRIC | NTXMPH20A122A** | Combination heat pumps with or without ducts | | 13,300 | $1,596 |
| Yes | 204834287 | TRANE / MITSUBISHI ELECTRIC | NTXMMX60A182B* | Heat pump without ducts | | 41,500 | $4,980 |
| Yes | 202732310 | TRANE / MITSUBISHI ELECTRIC | NTXMPH20A122AA | NTXWPH09A112AANTXWPH09A112AA | | 13,000 | $1,560 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204444987 | TRANE / MITSUBISHI ELECTRIC | TRUZH0421KA00NA | TPVA0A0421AA70A | | 42,000 | $5,040 |
| Yes | 204834220 | TRANE / MITSUBISHI ELECTRIC | TUMYP0601AK43** | Heat pump with ducts | | 40,500 | $4,860 |
| Yes | 202850707 | TRANE / MITSUBISHI ELECTRIC | TUMYP0601AK42** | Heat pump with ducts | | 40,500 | $4,860 |
| Yes | 202850714 | TRANE / MITSUBISHI ELECTRIC | TUMYH0481AK40** | Heat pump with ducts | | 42,000 | $5,040 |
| Yes | 204281763 | TRANE / MITSUBISHI ELECTRIC | TRUZH0241HA00NA | TPVA0A0241AA70A | | 17,500 | $2,100 |
| Yes | 204834219 | TRANE / MITSUBISHI ELECTRIC | TUMYH0481AK41** | Heat pump with ducts | | 42,000 | $5,040 |
| Yes | 202850717 | TRANE / MITSUBISHI ELECTRIC | TUMYP0601AK42** | Combination heat pumps with or without ducts | | 45,144 | $5,417 |
| Yes | 202850719 | TRANE / MITSUBISHI ELECTRIC | TUMYH0481AK40** | Combination heat pumps with or without ducts | | 40,500 | $4,860 |
| Yes | 204926545 | TRANE / MITSUBISHI ELECTRIC | TUMYH0481AK41** | Combination heat pumps with or without ducts | | 40,500 | $4,860 |
| Yes | 204926550 | TRANE / MITSUBISHI ELECTRIC | TUMYP0601AK43** | Combination heat pumps with or without ducts | | 45,144 | $5,417 |
| Yes | 204444396 | TRANE / MITSUBISHI ELECTRIC | TRUZH0361HA50NA | TPEADA0361AA70A | | 27,000 | $3,240 |
| Yes | 204874302 | TRANE / MITSUBISHI ELECTRIC | TRUZH0361HA50NA | TPVA0A0361AA70A | | 29,000 | $3,480 |
| Yes | 202850708 | TRANE / MITSUBISHI ELECTRIC | TUMYH0361AK40** | | | 32,000 | $3,840 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204276766 | TRANE / MITSUBISHI ELECTRIC | TRUZH0241HA00NA | TPKA0A0241KA70A | | 17,200 | $2,064 |
| Yes | 204834280 | TRANE / MITSUBISHI ELECTRIC | TUMYH0361AK41** | Heat pump with ducts | | 32,000 | $3,840 |
| Yes | 202850713 | TRANE / MITSUBISHI ELECTRIC | TUMYH0481AK40** | Heat pump without ducts | | 39,000 | $4,680 |
| Yes | 204834283 | TRANE / MITSUBISHI ELECTRIC | TUMYP0601AK43** | Heat pump without ducts | | 41,500 | $4,980 |
| Yes | 202850711 | TRANE / MITSUBISHI ELECTRIC | TUMYP0601AK42** | Heat pump without ducts | | 41,500 | $4,980 |
| Yes | 204834282 | TRANE / MITSUBISHI ELECTRIC | TUMYH0481AK41** | Heat pump without ducts | | 39,000 | $4,680 |
| Yes | 204276540 | TRANE / MITSUBISHI ELECTRIC | TRUZH0241HA00NA | TPLA0A0241EA70A | | 17,300 | $2,076 |
| Yes | 202850712 | TRANE / MITSUBISHI ELECTRIC | TUMYH0361AK40** | Heat pump without ducts | | 33,000 | $3,960 |
| Yes | 204834279 | TRANE / MITSUBISHI ELECTRIC | TUMYH0361AK41** | Heat pump without ducts | | 33,000 | $3,960 |
| Yes | 204926544 | TRANE / MITSUBISHI ELECTRIC | TUMYH0361AK41** | Combination heat pumps with or without ducts | | 32,400 | $3,888 |
| Yes | 204834255 | TRANE / MITSUBISHI ELECTRIC | NTXMPH48A182B* | Heat pump without ducts | | 38,000 | $4,560 |
| Yes | 204834286 | TRANE / MITSUBISHI ELECTRIC | NTXMPH42A152B* | Heat pump without ducts | | 32,000 | $3,840 |
| Yes | 204834284 | TRANE / MITSUBISHI ELECTRIC | NTXMPH36A142B* | Heat pump without ducts | | 30,000 | $3,600 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 204834285 | TRANE / MITSUBISHI ELECTRIC | NTXMPH36A142B* | Heat pump with ducts | | 34,000 | $4,080 |
| Yes | 204834254 | TRANE / MITSUBISHI ELECTRIC | NTXMPH42A152B* | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 204926532 | TRANE / MITSUBISHI ELECTRIC | NTXMPH42A152B* | Combination heat pumps with or without ducts | | 34,000 | $4,080 |
| Yes | 204834256 | TRANE / MITSUBISHI ELECTRIC | NTXMPH48A182B* | Heat pump with ducts | | 38,000 | $4,560 |
| Yes | 204926530 | TRANE / MITSUBISHI ELECTRIC | NTXMPH36A142B* | Combination heat pumps with or without ducts | | 32,000 | $3,840 |
| Yes | 204926534 | TRANE / MITSUBISHI ELECTRIC | NTXMPH48A182B* | Combination heat pumps with or without ducts | | 38,000 | $4,560 |
| Yes | 204793347 | TRANE / MITSUBISHI ELECTRIC | NTXSKH15A112AA | NTXDKS15A112AA | | 12,200 | $1,464 |
| Yes | 202373718 | TRANE / MITSUBISHI ELECTRIC | NTXSPF15A112AA | NTXFKS15A112AA | | 14,400 | $1,728 |
| Yes | 202354909 | TRANE / MITSUBISHI ELECTRIC | NTXMPH36A142AA | Heat pump without ducts | | 34,000 | $4,080 |
| Yes | 202354905 | TRANE / MITSUBISHI ELECTRIC | NTXMPH24A132AA | Heat pump without ducts | | 14,000 | $1,680 |
| Yes | 202373745 | TRANE / MITSUBISHI ELECTRIC | NTXMPH42A152AA | Heat pump without ducts | | 35,800 | $4,296 |
| Yes | 202373748 | TRANE / MITSUBISHI ELECTRIC | NTXMMX60A182AA | Heat pump without ducts | | 41,500 | $4,980 |
| Yes | 202373719 | TRANE / MITSUBISHI ELECTRIC | NTXSPF18A112AA | NTXFKS18A112AA | | 12,800 | $1,536 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 202366334 | TRANE / MITSUBISHI ELECTRIC | NTXMPH36A142AA | Combination heat pumps with or without ducts | | 35,000 | $4,200 |
| Yes | 202392006 | TRANE / MITSUBISHI ELECTRIC | NTXMPH20A122AA | Combination heat pumps with or without ducts | | 13,700 | $1,644 |
| Yes | 202366332 | TRANE / MITSUBISHI ELECTRIC | NTXMPH24A132AA | Combination heat pumps with or without ducts | | 14,000 | $1,680 |
| Yes | 202373712 | TRANE / MITSUBISHI ELECTRIC | NTXMPH42A152AA | Heat pump with ducts | | 36,600 | $4,392 |
| Yes | 208284018 | TRUST AIR CONDITIONERS | AA48H/O44P | AH48H/I44P | | 36,000 | $4,320 |
| Yes | 208284015 | TRUST AIR CONDITIONERS | AA24H/O44P | AH24H/I44P | | 19,200 | $2,304 |
| Yes | 208284014 | TRUST AIR CONDITIONERS | AA18H/O44P | AH18H/I44P | | 13,500 | $1,620 |
| Yes | 208284491 | TRUST AIR CONDITIONERS | M4H36H/O4S4P | Heat pump without ducts | | 33,000 | $3,960 |
| Yes | 208284485 | TRUST AIR CONDITIONERS | M2H18H/O4S4P | Heat pump without ducts | | 15,000 | $1,800 |
| Yes | 208284495 | TRUST AIR CONDITIONERS | M5H48H/O4S4P | Heat pump with ducts | | 36,000 | $4,320 |
| Yes | 208284494 | TRUST AIR CONDITIONERS | M5H48H/O4S4P | Heat pump without ducts | | 36,000 | $4,320 |
| Yes | 208284489 | TRUST AIR CONDITIONERS | M3H27H/O4S4P | Heat pump with ducts | | 27,000 | $3,240 |
| Yes | 208284488 | TRUST AIR CONDITIONERS | M3H27H/O4S4P | Heat pump without ducts | | 26,600 | $3,192 |
| Yes | 208284486 | TRUST AIR CONDITIONERS | M2H18H/O4S4P | Heat pump with ducts | | 16,000 | $1,920 |
| Yes | 208280091 | TRUST AIR CONDITIONERS | AS24H/O4S41P | IUMC424H/I41P | | 21,000 | $2,520 |
| Yes | 208816925 | TRUST AIR CONDITIONERS | OAH24H/O4S4P | IUMC424H/I41P | | 21,000 | $2,520 |
| Yes | 208280127 | TRUST AIR CONDITIONERS | OAH48H/O4S41P | IUMDL48H/I43P | | 39,500 | $4,740 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 208280095 | TRUST AIR CONDITIONERS | OAH48H/O4S41P | IUMC448H/I41P | | 35,000 | $4,200 |
| Yes | 208280172 | TRUST AIR CONDITIONERS | OAH48H/O4S41P | IUMFC48H/I41P | | 35,000 | $4,200 |
| Yes | 208280093 | TRUST AIR CONDITIONERS | OAH36H/O4S41P | IUMC436H/I41P | | 33,000 | $3,960 |
| Yes | 208280169 | TRUST AIR CONDITIONERS | OAH36H/O4S41P | IUMFC36H/I41P | | 32,000 | $3,840 |
| Yes | 208816933 | TRUST AIR CONDITIONERS | OAH24H/O4S4P | IUMDL24H/I43P | | 21,000 | $2,520 |
| Yes | 208280123 | TRUST AIR CONDITIONERS | AS24H/O4S41P | IUMDL24H/I43P | | 21,000 | $2,520 |
| Yes | 208816939 | TRUST AIR CONDITIONERS | OAH24H/O4S4P | IUMFC24H/I41P | | 19,000 | $2,280 |
| Yes | 208280167 | TRUST AIR CONDITIONERS | AS24H/O4S41P | IUMFC24H/I41P | | 19,000 | $2,280 |
| Yes | 208280120 | TRUST AIR CONDITIONERS | AS18H/O4S41P | IUMDL18H/I43P | | 15,000 | $1,800 |
| Yes | 208816932 | TRUST AIR CONDITIONERS | OAH18H/O4S4P | IUMDL18H/I43P | | 15,000 | $1,800 |
| Yes | 208280067 | TRUST AIR CONDITIONERS | AS24H/O4S41P | IS24H/I4S41P | | 21,200 | $2,544 |
| Yes | 208816917 | TRUST AIR CONDITIONERS | OAH24H/O4S4P | IUMW124H/I41P | | 21,200 | $2,544 |
| Yes | 208816916 | TRUST AIR CONDITIONERS | OAH18H/O4S4P | IUMW118H/I41P | | 15,000 | $1,800 |
| Yes | 208280064 | TRUST AIR CONDITIONERS | AS18H/O4S41P | IS18H/I4S41P | | 15,000 | $1,800 |
| Yes | 208284496 | TRUST AIR CONDITIONERS | M5H48H/O4S4P | Combination heat pumps with or without ducts | | 29,000 | $3,480 |
| Yes | 208284492 | TRUST AIR CONDITIONERS | M4H36H/O4S4P | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 208284493 | TRUST AIR CONDITIONERS | M4H36H/O4S4P | Combination heat pumps with or without ducts | | 23,000 | $2,760 |
| Yes | 211174354 | WABBAN | BBM36HX4O | Heat pump without ducts | | 30,800 | $3,696 |
| Yes | 211174355 | WABBAN | BBM42HX4O | Heat pump without ducts | | 35,600 | $4,272 |
| Yes | 207196961 | WABBAN | BB36-24WADU | BBD24-24AH2ADU | | 16,000 | $1,920 |
| Yes | 207196958 | WABBAN | BB36-24WADU | BBD36-24AH2ADU | | 24,000 | $2,880 |
| Yes | 207196960 | WABBAN | BB60-48WADU | BBD60-24AH2ADU | | 36,000 | $4,320 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 207196959 | WABBAN | BB60-48WADU | BBD48-24AH2ADU | | 31,400 | $3,768 |
| Yes | 201903167 | WABBAN | BB18HQ2A3DO | BB18HQ2A3DI | | 12,400 | $1,488 |
| Yes | 201903168 | WABBAN | BB24HQ2A3DO | BB24HQ2A3DI | | 14,600 | $1,752 |
| Yes | 201903174 | WABBAN | BB18HQ3D6DO | BB18HQ3D6DI | | 14,200 | $1,704 |
| Yes | 201903175 | WABBAN | BB24HQ3D6DO | BB24HQ3D6DI | | 15,500 | $1,860 |
| Yes | 208447914 | WEATHERMAKER | 38MURAQ48AB3 | 40MUAAQ48XA3 | | 36,000 | $4,320 |
| Yes | 208447906 | WEATHERMAKER | 38MURAQ36AB3 | 40MUAAQ36XA3 | | 30,400 | $3,648 |
| Yes | 209911730 | WEATHERMAKER | 38MURAQ24AB3 | 40MUAAQ24XA3 | | 19,200 | $2,304 |
| Yes | 208447913 | WEATHERMAKER | 38MURAQ18AB3 | 40MUAAQ18XA3 | | 13,500 | $1,620 |
| Yes | 207642954 | WEATHERMAKER | 38MGHBQ36DA3 | Heat pump without ducts | | 23,200 | $2,784 |
| Yes | 207642951 | WEATHERMAKER | 38MGHBQ48EA3 | Heat pump without ducts | | 30,000 | $3,600 |
| Yes | 207642945 | WEATHERMAKER | 38MGHBQ30DA3 | Heat pump without ducts | | 17,500 | $2,100 |
| Yes | 207826674 | WEATHERMAKER | 38MARBQ18AA3 | 40MBABQ18XB3 | | 12,000 | $1,440 |
| Yes | 207801581 | WEATHERMAKER | 38MARBQ18AA3 | 40MBDQ24---3 | | 12,600 | $1,512 |
| Yes | 207642946 | WEATHERMAKER | 38MGHBQ30DA3 | Heat pump with ducts | | 19,000 | $2,280 |
| Yes | 207642952 | WEATHERMAKER | 38MGHBQ48EA3 | Heat pump with ducts | | 28,000 | $3,360 |
| Yes | 207642955 | WEATHERMAKER | 38MGHBQ36DA3 | Heat pump with ducts | | 23,000 | $2,760 |
| Yes | 207642947 | WEATHERMAKER | 38MGHBQ30DA3 | Combination heat pumps with or without ducts | | 18,200 | $2,184 |
| Yes | 207642953 | WEATHERMAKER | 38MGHBQ48EA3 | Combination heat pumps with or without ducts | | 29,000 | $3,480 |
| Yes | 207642956 | WEATHERMAKER | 38MGHBQ36DA3 | Combination heat pumps with or without ducts | | 23,000 | $2,760 |
| Yes | 206350366 | WEATHERMAKER | 38MARBQ18AA3 | 40MBDQ18--3 | | 12,700 | $1,524 |
| Yes | 206188274 | WEATHERMAKER | 38MARBQ24AA3 | 40MBAAQ24XA3 | | 16,500 | $1,980 |
| Yes | 206350326 | WEATHERMAKER | 38MARBQ24AA3 | DHMAHBQ24XA3 | | 19,800 | $2,376 |
| Yes | 206350368 | WEATHERMAKER | 38MARBQ24AA3 | 40MBCQ24--3 | | 14,500 | $1,740 |
| Yes | 206350370 | WEATHERMAKER | 38MARBQ24AA3 | 40MBFQ24--3 | | 14,500 | $1,740 |
| Yes | 206350367 | WEATHERMAKER | 38MARBQ18AA3 | 40MBFQ18--3 | | 12,000 | $1,440 |
| Yes | 206350369 | WEATHERMAKER | 38MARBQ24AA3 | 40MBDQ24--3 | | 14,500 | $1,740 |
| Yes | 205921382 | WEATHERMAKER | 38MAQB24R--3 | 40MBAAQ24XA3 | | 17,500 | $2,100 |
| Yes | 205417838 | WESTINGHOUSE | WHP24SZA21S | WHP24WMA21S | | 14,500 | $1,740 |
| Yes | 207237543 | WESTINGHOUSE | WHU24SZA21S | WHU24DHA21S | | 19,300 | $2,316 |
| Yes | 9038621 | WILLIS | WUHO24KW20S | WUHI24KHW | | 15,400 | $1,848 |
| Yes | 211207050 | YORK | YZV48B21 | XAMC48HE3N1+CC | YPLC100C16MP13 | 41,500 | $4,980 |
| Yes | 211207049 | YORK | YZV48B21 | XAMC48HE3N1+CC | YPLC080C16MP13 | 41,500 | $4,980 |
| Yes | 211207048 | YORK | YZV48B21 | XAMC48HE3N1+CC | TPLC100C16MP13 | 41,500 | $4,980 |
| Yes | 211207047 | YORK | YZV48B21 | XAMC48HE3N1+CC | TPLC080C16MP13 | 41,500 | $4,980 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 211207046 | YORK | YZV48B21 | XAMC48HE3N1+CC | TMLV100C16MP12 | 41,500 | $4,980 |
| Yes | 211207045 | YORK | YZV48B21 | XAMC48HE3N1+CC | TM8V080C16MP12 | 41,500 | $4,980 |
| Yes | 211207044 | YORK | YZV48B21 | XAMC48HE3N1+CC | TM8V100C16MP12 | 41,500 | $4,980 |
| Yes | 211207043 | YORK | YZV48B21 | XAMC48HE3N1+CC | YPLC120C20MP13 | 41,500 | $4,980 |
| Yes | 211207042 | YORK | YZV48B21 | XAMC48HE3N1+CC | YPLC100C20MP13 | 41,500 | $4,980 |
| Yes | 211207041 | YORK | YZV48B21 | XAMC48HE3N1+CC | TPLC120C20MP13 | 41,500 | $4,980 |
| Yes | 211207040 | YORK | YZV48B21 | XAMC48HE3N1+CC | TPLC100C20MP13 | 41,500 | $4,980 |
| Yes | 211207039 | YORK | YZV48B21 | XAMC48HE3N1+CC | TMLV120C20MP12 | 41,500 | $4,980 |
| Yes | 211207038 | YORK | YZV48B21 | XAMC48HE3N1+CC | TM8V100C20MP12 | 41,500 | $4,980 |
| Yes | 211207037 | YORK | YZV48B21 | XAMC48HE3N1+CC | TM8V120C20MP12 | 41,500 | $4,980 |
| Yes | 211207036 | YORK | YZV48B21 | XAMC48HE3N1+CC | YP9C080C16MP13 | 41,500 | $4,980 |
| Yes | 211207035 | YORK | YZV48B21 | XAMC48HE3N1+CC | TP9C080C16MP13 | 41,500 | $4,980 |
| Yes | 211207034 | YORK | YZV48B21 | XAMC48HE3N1+CC | TM9V080C16MP12 | 41,500 | $4,980 |
| Yes | 211207033 | YORK | YZV48B21 | XAMC48HE3N1+CC | YP9C100C16MP13 | 41,500 | $4,980 |
| Yes | 211207032 | YORK | YZV48B21 | XAMC48HE3N1+CC | TP9C100C16MP13 | 41,500 | $4,980 |
| Yes | 211207031 | YORK | YZV48B21 | XAMC48HE3N1+CC | TM9V100C16MP12 | 41,500 | $4,980 |
| Yes | 211207030 | YORK | YZV48B21 | XAMC48HE3N1+CC | YP9C100C20MP13 | 41,500 | $4,980 |
| Yes | 211207029 | YORK | YZV48B21 | XAMC48HE3N1+CC | TP9C100C20MP13 | 41,500 | $4,980 |
| Yes | 211207028 | YORK | YZV48B21 | XAMC48HE3N1+CC | TM9V100C20MP12 | 41,500 | $4,980 |
| Yes | 211207027 | YORK | YZV60B21 | XAMC60HE4N1+CC | YP9C100C20MP13 | 47,000 | $5,640 |
| Yes | 211207026 | YORK | YZV60B21 | XAMC60HE4N1+CC | TP9C100C20MP13 | 47,000 | $5,640 |
| Yes | 211207025 | YORK | YZV60B21 | XAMC60HE4N1+CC | TM9V100C20MP12 | 47,000 | $5,640 |
| Yes | 211207012 | YORK | YZV24B21 | XAMB24DE1N1+CC | YPLC080B12MP13 | 23,000 | $2,760 |
| Yes | 211207011 | YORK | YZV24B21 | XAMB24DE1N1+CC | TPLC080B12MP13 | 23,000 | $2,760 |
| Yes | 211207010 | YORK | YZV24B21 | XAMB24DE1N1+CC | TM8V080B12MP12 | 23,000 | $2,760 |
| Yes | 211207009 | YORK | YZV24B21 | XAMB24DE1N1+CC | YP9C060B12MP13 | 23,200 | $2,784 |
| Yes | 211207008 | YORK | YZV24B21 | XAMB24DE1N1+CC | TP9C060B12MP13 | 23,200 | $2,784 |
| Yes | 211207007 | YORK | YZV24B21 | XAMB24DE1N1+CC | TM9V060B12MP12 | 23,200 | $2,784 |
| Yes | 211010174 | YORK | YZV60B21 | JHVVD60HE4C2N1+CC |  | 46,500 | $5,580 |
| Yes | 211380186 | YORK | HMH72B341 | XAHD48FBCN1 | TL8E080C16UH11 | 25,400 | $3,048 |
| Yes | 211380183 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TL8E080C16UH11 | 25,400 | $3,048 |
| Yes | 211380198 | YORK | HMH72B341 | XAFD48FBCN1 | TL8E080C16UH11 | 25,600 | $3,072 |
| Yes | 211380195 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TL8E080C16UH11 | 25,600 | $3,072 |
| Yes | 211380206 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TL8E080C16UH11 | 26,000 | $3,120 |
| Yes | 211380203 | YORK | HMH72B341 | XAFC48FBCN1 | TL8E080C16UH11 | 26,000 | $3,120 |
| Yes | 211380200 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TL8E080C16UH11 | 26,000 | $3,120 |
| Yes | 211380192 | YORK | HMH72B341 | XAHC48FBCN1 | TL8E080C16UH11 | 25,600 | $3,072 |
| Yes | 211380189 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TL8E080C16UH11 | 25,600 | $3,072 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 211380181 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TL8E100C20UH11 | 25,400 | $3,048 |
| Yes | 211380178 | YORK | HMH72B341 | XAFC48FBCN1 | TL8E100C20UH11 | 25,400 | $3,048 |
| Yes | 211380175 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TL8E100C20UH11 | 25,400 | $3,048 |
| Yes | 211380172 | YORK | HMH72B341 | XAFD48FBCN1 | TL8E100C20UH11 | 25,400 | $3,048 |
| Yes | 211380169 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TL8E100C20UH11 | 25,400 | $3,048 |
| Yes | 211380211 | YORK | HMH72B341 | XAHC48FBCN1+JMET12CS2N1 | | 24,800 | $2,976 |
| Yes | 211380208 | YORK | HMH72B341 | XAHC48FXXN1+JMET12CS2N1+TXV | | 24,800 | $2,976 |
| Yes | 211380166 | YORK | HMH72B341 | XAHC48FBCN1 | TL8E100C20UH11 | 24,800 | $2,976 |
| Yes | 203994967 | YORK | YVAHP036B21S* | YIC4012B21S, YIC4012B21S, YIC4012B21S | | 23,800 | $2,856 |
| Yes | 203994973 | YORK | YVAHP036B21S* | YIDM018B21S, YIDM018B21S | | 23,800 | $2,856 |
| Yes | 203995167 | YORK | YVAHP036B21S* | NULL | | 23,800 | $2,856 |
| Yes | 10524902 | YORK | YZV36B21 | CM38CE2A1 | TMLV100C16MP12 | 33,400 | $4,008 |
| Yes | 10524904 | YORK | YZV36B21 | CM38CE2A1 | TP9C100C16MP13 | 31,600 | $3,792 |
| Yes | 10524907 | YORK | YZV36B21 | CM38CE2A1 | YP9C080C16MP13 | 31,800 | $3,816 |
| Yes | 10524905 | YORK | YZV36B21 | CM38CE2A1 | TPLC080C16MP13 | 33,400 | $4,008 |
| Yes | 10524903 | YORK | YZV36B21 | CM38CE2A1 | TP9C080C16MP13 | 31,800 | $3,816 |
| Yes | 10524898 | YORK | YZV36B21 | CM38CE2A1 | TM8V100C16MP12 | 33,400 | $4,008 |
| Yes | 10524901 | YORK | YZV36B21 | CM38CE2A1 | TMLV080C16MP12 | 33,400 | $4,008 |
| Yes | 10309023 | YORK | YZV48B21 | AVV50DE321 | | 44,000 | $5,280 |
| Yes | 10309025 | YORK | YZV48B21 | CM50DE3A1+MVC20DN21 | | 42,500 | $5,100 |
| Yes | 10309024 | YORK | YZV48B21 | CM50CE3A1+MVC16CN21 | | 43,500 | $5,220 |
| Yes | 10309022 | YORK | YZV48B21 | AVV50CE321 | | 43,500 | $5,220 |
| Yes | 10309007 | YORK | YZV36B21 | AVV38CE221 | | 33,400 | $4,008 |
| Yes | 10309021 | YORK | YZV36B21 | CM38CE2A1+MVC16CN21 | | 33,400 | $4,008 |
| Yes | 10309006 | YORK | YZV24B21 | CM25BE1A1+MVC12BN21 | | 22,400 | $2,688 |
| Yes | 10524906 | YORK | YZV36B21 | CM38CE2A1 | TPLC100C16MP13 | 33,400 | $4,008 |
| Yes | 10524908 | YORK | YZV36B21 | CM38CE2A1 | YP9C100C16MP13 | 31,600 | $3,792 |
| Yes | 10524909 | YORK | YZV36B21 | CM38CE2A1 | YPLC080C16MP13 | 33,400 | $4,008 |
| Yes | 10525204 | YORK | YZV48B21 | CM50CE3A1 | TM8V080C16MP12 | 44,000 | $5,280 |
| Yes | 10524910 | YORK | YZV36B21 | CM38CE2A1 | YPLC100C16MP13 | 33,400 | $4,008 |
| Yes | 10525206 | YORK | YZV48B21 | CM50CE3A1 | TM8V100C20MP12 | 44,000 | $5,280 |
| Yes | 10525207 | YORK | YZV48B21 | CM50CE3A1 | TM8V120C20MP12 | 44,000 | $5,280 |
| Yes | 10525210 | YORK | YZV48B21 | CM50CE3A1 | TM9V100C20MP12 | 44,000 | $5,280 |
| Yes | 10525211 | YORK | YZV48B21 | CM50CE3A1 | TMLV080C16MP12 | 44,000 | $5,280 |
| Yes | 10525213 | YORK | YZV48B21 | CM50CE3A1 | TMLV100C20MP12 | 44,000 | $5,280 |
| Yes | 10525212 | YORK | YZV48B21 | CM50CE3A1 | TMLV100C16MP12 | 44,000 | $5,280 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| Yes | 10525214 | YORK | YZV48B21 | CM50CE3A1 | TMLV120C20MP12 | 44,000 | $5,280 |
| Yes | 10525218 | YORK | YZV48B21 | CM50CE3A1 | TPLC080C16MP13 | 44,000 | $5,280 |
| Yes | 10525217 | YORK | YZV48B21 | CM50CE3A1 | TP9C100C20MP13 | 44,000 | $5,280 |
| Yes | 10525219 | YORK | YZV48B21 | CM50CE3A1 | TPLC100C16MP13 | 44,000 | $5,280 |
| Yes | 10525221 | YORK | YZV48B21 | CM50CE3A1 | TPLC120C20MP13 | 44,000 | $5,280 |
| Yes | 10525225 | YORK | YZV48B21 | CM50CE3A1 | YPLC080C16MP13 | 44,000 | $5,280 |
| Yes | 10525227 | YORK | YZV48B21 | CM50CE3A1 | YPLC100C20MP13 | 44,000 | $5,280 |
| Yes | 10525224 | YORK | YZV48B21 | CM50CE3A1 | YP9C100C20MP13 | 44,000 | $5,280 |
| Yes | 10525230 | YORK | YZV48B21 | CM50DE3A1 | TP9C120D20MP13 | 44,000 | $5,280 |
| Yes | 10525228 | YORK | YZV48B21 | CM50CE3A1 | YPLC120C20MP13 | 44,000 | $5,280 |
| Yes | 10525226 | YORK | YZV48B21 | CM50CE3A1 | YPLC100C16MP13 | 44,000 | $5,280 |
| Yes | 10525229 | YORK | YZV48B21 | CM50DE3A1 | TM9V120D20MP12 | 44,000 | $5,280 |
| Yes | 10525231 | YORK | YZV48B21 | CM50DE3A1 | YP9C120D20MP13 | 44,000 | $5,280 |
| Yes | 10524897 | YORK | YZV36B21 | CM38CE2A1 | TM8V080C16MP12 | 33,400 | $4,008 |
| Yes | 10524900 | YORK | YZV36B21 | CM38CE2A1 | TM9V100C16MP12 | 31,600 | $3,792 |
| Yes | 10524899 | YORK | YZV36B21 | CM38CE2A1 | TM9V080C16MP12 | 31,800 | $3,816 |
| Yes | 10525205 | YORK | YZV48B21 | CM50CE3A1 | TM8V100C16MP12 | 44,000 | $5,280 |
| Yes | 10525220 | YORK | YZV48B21 | CM50CE3A1 | TPLC100C20MP13 | 44,000 | $5,280 |
| Yes | 8578593 | YORK BY JOHNSON CONTROLS | DHZ18CSB21S | DHZ18NWB21S | | 12,700 | $1,524 |
| Yes | 8578481 | YORK BY JOHNSON CONTROLS | DHR48CSB21S | DHR48NDB48S | | 30,600 | $3,672 |
| Yes | 207911500 | ZENAIR TECHNOLOGIES | ZEN-PC48HP20S/O | ZEN-PC48HP20S/I | | 36,000 | $4,320 |
| Yes | 205306852 | ZEPHYR | ZE-36HPA | AH-36 | | 25,000 | $3,000 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 212394305 | 1HVAC | ACIQ-18-EHPB | ACIQ-18-ACL | | 13,000 | $650 |
| No | 212394315 | 1HVAC | ACIQ-48-HPB | ACIQ-48-ACL | | 32,000 | $1,600 |
| No | 212394314 | 1HVAC | ACIQ-36-HPB | ACIQ-36-ACL | | 33,000 | $1,650 |
| No | 212394309 | 1HVAC | ACIQ-48-EHPB | ACIQ-48-ACL | | 30,400 | $1,520 |
| No | 212394308 | 1HVAC | ACIQ-36-EHPB | ACIQ-36-ACL | | 19,800 | $990 |
| No | 212394312 | 1HVAC | ACIQ-24-HPB | ACIQ-24-ACL | | 21,000 | $1,050 |
| No | 212394311 | 1HVAC | ACIQ-18-HPB | ACIQ-18-ACL | | 14,700 | $735 |
| No | 212394310 | 1HVAC | ACIQ-60-EHPB | ACIQ-60-ACL | | 34,000 | $1,700 |
| No | 212394307 | 1HVAC | ACIQ-30-EHPB | ACIQ-30-ACL | | 22,000 | $1,100 |
| No | 212394306 | 1HVAC | ACIQ-24-EHPB | ACIQ-24-ACL | | 22,000 | $1,100 |
| No | 208106639 | 1HVAC | ACIQ-36-HPB | ACIQ-36-AHB | | 30,400 | $1,520 |
| No | 210857307 | 1HVAC | ACIQ-06ZPL-HP230B | SCC-0609-HH-M | | 5,700 | $285 |
| No | 210857309 | 1HVAC | ACIQ-12ZPL-HP230B | SCC-1218-HH-M | | 9,500 | $475 |
| No | 210857308 | 1HVAC | ACIQ-09ZPL-HP230B | SCC-0609-HH-M | | 9,800 | $490 |
| No | 210857377 | 1HVAC | ES-55Z-M5B | Heat pump without ducts | | 34,400 | $1,720 |
| No | 210857374 | 1HVAC | ES-48Z-M5B | Heat pump without ducts | | 34,000 | $1,700 |
| No | 210857371 | 1HVAC | ES-36Z-M4B | Heat pump without ducts | | 26,800 | $1,340 |
| No | 210857369 | 1HVAC | ES-27Z-M3B | Heat pump with ducts | | 22,000 | $1,100 |
| No | 210857366 | 1HVAC | ES-18Z-M2B | Heat pump with ducts | | 14,800 | $740 |
| No | 210857368 | 1HVAC | ES-27Z-M3B | Heat pump without ducts | | 21,000 | $1,050 |
| No | 210857365 | 1HVAC | ES-18Z-M2B | Heat pump without ducts | | 14,300 | $715 |
| No | 210857312 | 1HVAC | ACIQ-18ZPL-HP230B | ACIQ-18FM-HH-MC | | 14,700 | $735 |
| No | 210857311 | 1HVAC | ACIQ-12ZPL-HP230B | ACIQ-12FM-HH-MC | | 10,200 | $510 |
| No | 207825509 | 1HVAC | ACIQ-18Z-HP230B | ACIQ-18W-HP230B | | 11,500 | $575 |
| No | 207825507 | 1HVAC | ACIQ-09Z-HP115B | ACIQ-09W-HP115B | | 6,800 | $340 |
| No | 210857301 | 1HVAC | ACIQ-36ZPL-HP230B | ACIQ-36CD-HH-MB | | 34,000 | $1,700 |
| No | 210857294 | 1HVAC | ACIQ-06ZPL-HP230B | ACIQ-06W-HH-MC | | 8,500 | $425 |
| No | 207825511 | 1HVAC | ACIQ-36Z-HP230B | ACIQ-36W-HP230B | | 24,000 | $1,200 |
| No | 207825518 | 1HVAC | ACIQ-18ZPL-HP230B | ACIQ-18CC-HH-MB | | 15,600 | $780 |
| No | 207825524 | 1HVAC | ACIQ-18ZPL-HP230B | ACIQ-18FM-HH-MB | | 12,000 | $600 |
| No | 207825523 | 1HVAC | ACIQ-12ZPL-HP230B | ACIQ-12FM-HH-MB | | 9,600 | $480 |
| No | 207825520 | 1HVAC | ACIQ-12ZPL-HP230B | ACIQ-12CD-HH-MB | | 10,600 | $530 |
| No | 207825517 | 1HVAC | ACIQ-12ZPL-HP230B | ACIQ-12CC-HH-MB | | 9,900 | $495 |
| No | 207825519 | 1HVAC | ACIQ-09ZPL-HP230B | ACIQ-09CD-HH-MB | | 10,100 | $505 |
| No | 207825516 | 1HVAC | ACIQ-09ZPL-HP230B | ACIQ-09CC-HH-MB | | 9,000 | $450 |
| No | 207825513 | 1HVAC | ACIQ-12ZPL-HP230B | ACIQ-12W-HH-MB | | 10,000 | $500 |
| No | 210857296 | 1HVAC | ACIQ-12ZPL-HP230B | ACIQ-12W-HH-MC | | 10,000 | $500 |
| No | 210857295 | 1HVAC | ACIQ-09ZPL-HP230B | ACIQ-09W-HH-MC | | 9,500 | $475 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207825512 | 1HVAC | ACIQ-09ZPL-HP230B | ACIQ-09W-HH-MB | | 9,500 | $475 |
| No | 206315642 | 1HVAC | ACIQ-18Z-HP230 | ACIQ-18W-HP230 | | 11,000 | $550 |
| No | 206315640 | 1HVAC | ACIQ-09Z-HP115 | ACIQ-09W-HP115 | | 6,000 | $300 |
| No | 207825566 | 1HVAC | ACIQ-18Z-HH-M2B | Combination heat pumps with or without ducts | | 11,500 | $575 |
| No | 207825569 | 1HVAC | ACIQ-27Z-HH-M3B | Combination heat pumps with or without ducts | | 17,000 | $850 |
| No | 206315647 | 1HVAC | ACIQ-36-HP | ACIQ-36-AH | | 25,000 | $1,250 |
| No | 206315648 | 1HVAC | ACIQ-48-HP | ACIQ-48-AH | | 36,000 | $1,800 |
| No | 208106857 | AC BEST LA | MOE30U-60HFN1-MR0 | MVC-60HWFN1-M | | 37,000 | $1,850 |
| No | 210857479 | AC BEST LA | MOD30U-36HFN1-M(GA) | MFGD-36HRFN1-MQ6W | | 25,200 | $1,260 |
| No | 208073243 | AC BEST LA | M3OJ-27HFN1-M | Heat pump without ducts | | 20,000 | $1,000 |
| No | 208073245 | AC BEST LA | M3OJ-27HFN1-M | Heat pump with ducts | | 22,000 | $1,100 |
| No | 208073237 | AC BEST LA | M2OA-18HFN1-M | Heat pump with ducts | | 14,800 | $740 |
| No | 208073235 | AC BEST LA | M2OA-18HFN1-M | Heat pump without ducts | | 14,400 | $720 |
| No | 210857480 | AC BEST LA | MOX230-12HFN1-MV5W | MCBU-12HRFN1-MV0W | | 7,700 | $385 |
| No | 209864928 | AC BEST LA | AOD30U-36HFN1-MP0(GA) | ATI-36HWFN1-M | | 25,000 | $1,250 |
| No | 208073232 | AC BEST LA | MOX430-24HFN1-MR0W | MSAG11D-24HRFN1-MR0W | | 16,500 | $825 |
| No | 208073229 | AC BEST LA | MOX330-18HFN1-MS0W | MSAG11C-18HRDN1-MS0W | | 11,400 | $570 |
| No | 208073224 | AC BEST LA | MOX230-12HFN1-BS8W | MSAG11B-12HRFN1-BS0W | | 7,800 | $390 |
| No | 208073226 | AC BEST LA | MOX230-09HFN1-BS5W | MSAG11A-09HRFN1-BS5W | | 6,300 | $315 |
| No | 208073221 | AC BEST LA | MOE30U-60HFN1-MR0 | MVC-60HWFN1-M | | 33,800 | $1,690 |
| No | 208073247 | AC BEST LA | M3OJ-27HFN1-M | Combination heat pumps with or without ducts | | 16,100 | $805 |
| No | 208073239 | AC BEST LA | M2OA-18HFN1-M | Combination heat pumps with or without ducts | | 11,800 | $590 |
| No | 206905492 | AC PRO | 4HP18V36P | E*1P36A+H4TXV02 | 80G2UH070AE12L | 23,400 | $1,170 |
| No | 206905657 | AC PRO | 4HP18V36P | EAC4X36A | 80G2UH070AE12L | 22,800 | $1,140 |
| No | 206905565 | AC PRO | 4HP18V36P | EA(C,U)1P36A+H4TXV02 | 80G2UH070AE12L | 22,800 | $1,140 |
| No | 206905707 | AC PRO | 4HP18V36P | EAH1P30A+H4TXV01 | 80G2UH070AE12L | 15,800 | $790 |
| No | 206905636 | AC PRO | 4HP18V36P | EAC4X30A | 80G2UH070AE12L | 15,800 | $790 |
| No | 206905544 | AC PRO | 4HP18V36P | EA(C,U)1P30A+H4TXV01 | 80G2UH070AE12L | 15,800 | $790 |
| No | 206905523 | AC PRO | 4HP18V36P | EA(C,U)1P24A+H4TXV01 | 80G2UH070AE12L | 16,100 | $805 |
| No | 206905509 | AC PRO | 4HP18V36P | E*1P36C+H4TXV02 | 80G2UH110CE16 | 23,400 | $1,170 |
| No | 206905517 | AC PRO | 4HP18V36P | E*1P36C+H4TXV02 | EFV16CCA | 23,200 | $1,160 |
| No | 206905516 | AC PRO | 4HP18V36P | E*1P36C+H4TXV02 | 96G2UH090CV12 | 23,200 | $1,160 |
| No | 206905515 | AC PRO | 4HP18V36P | E*1P36C+H4TXV02 | 96G1UH090CE16 | 23,400 | $1,170 |
| No | 206905512 | AC PRO | 4HP18V36P | E*1P36C+H4TXV02 | 92G1UH110CE16 | 23,200 | $1,160 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206905511 | AC PRO | 4HP18V36P | E*1P36C+H4TXV02 | 92G1UH090CE16 | 23,200 | $1,160 |
| No | 206905510 | AC PRO | 4HP18V36P | E*1P36C+H4TXV02 | 92G1UH090CE12 | 23,400 | $1,170 |
| No | 206905508 | AC PRO | 4HP18V36P | E*1P36B+H4TXV02 | EFV12BCA | 23,400 | $1,170 |
| No | 206905507 | AC PRO | 4HP18V36P | E*1P36B+H4TXV02 | 96G2UH070BV12 | 23,400 | $1,170 |
| No | 206905506 | AC PRO | 4HP18V36P | E*1P36B+H4TXV02 | 96G2UH045BV12 | 23,600 | $1,180 |
| No | 206905505 | AC PRO | 4HP18V36P | E*1P36B+H4TXV02 | 96G1UH070BE12 | 23,200 | $1,160 |
| No | 206905503 | AC PRO | 4HP18V36P | E*1P36B+H4TXV02 | 92G1UH070BE12 | 23,400 | $1,170 |
| No | 206905502 | AC PRO | 4HP18V36P | E*1P36B+H4TXV02 | 92G1UH045BE12 | 23,400 | $1,170 |
| No | 206905501 | AC PRO | 4HP18V36P | E*1P36B+H4TXV02 | 92G1UH030BE12 | 23,400 | $1,170 |
| No | 206905498 | AC PRO | 4HP18V36P | E*1P36B+H4TXV02 | 80G2UH090BE16 | 23,400 | $1,170 |
| No | 206905497 | AC PRO | 4HP18V36P | E*1P36B+H4TXV02 | 80G2UH090BE12 | 23,400 | $1,170 |
| No | 206905496 | AC PRO | 4HP18V36P | E*1P36B+H4TXV02 | 80G1UH090BE16 | 23,200 | $1,160 |
| No | 206905495 | AC PRO | 4HP18V36P | E*1P36B+H4TXV02 | 80G1UH080BE16X | 23,600 | $1,180 |
| No | 206905494 | AC PRO | 4HP18V36P | E*1P36B+H4TXV02 | 80G1UH070BE12 | 23,200 | $1,160 |
| No | 206905491 | AC PRO | 4HP18V36P | E*1P36A+H4TXV02 | 80G2UH070AE12 | 23,400 | $1,170 |
| No | 206905490 | AC PRO | 4HP18V36P | E*1P36A+H4TXV02 | 80G1UH070AE12 | 23,200 | $1,160 |
| No | 206905489 | AC PRO | 4HP18V36P | E*1P36A+H4TXV02 | 80G1UH060AE12X | 23,200 | $1,160 |
| No | 206905488 | AC PRO | 4HP18V36P | E*1P36A+H4TXV02 | 80G1UH045AE12 | 23,200 | $1,160 |
| No | 206905832 | AC PRO | 4HP18V36P | ED1P30/36C+H4TXV02 | 96G1DF090CE16 | 22,200 | $1,110 |
| No | 206905830 | AC PRO | 4HP18V36P | ED1P30/36C+H4TXV02 | 92G1DF090CE16 | 22,200 | $1,110 |
| No | 206905829 | AC PRO | 4HP18V36P | ED1P30/36B+H4TXV02 | 96G2DF070BV16 | 22,600 | $1,130 |
| No | 206905827 | AC PRO | 4HP18V36P | ED1P30/36B+H4TXV02 | 96G1DF070BE16 | 22,400 | $1,120 |
| No | 206905826 | AC PRO | 4HP18V36P | ED1P30/36B+H4TXV02 | 96G1DF045BE12 | 22,000 | $1,100 |
| No | 206905823 | AC PRO | 4HP18V36P | ED1P30/36B+H4TXV02 | 92G1DF070BE12 | 22,400 | $1,120 |
| No | 206905822 | AC PRO | 4HP18V36P | ED1P30/36B+H4TXV02 | 92G1DF045BE12 | 22,400 | $1,120 |
| No | 206905820 | AC PRO | 4HP18V36P | ED1P30/36B+H4TXV02 | 80G1DF090BE16 | 22,200 | $1,110 |
| No | 206905819 | AC PRO | 4HP18V36P | ED1P30/36B+H4TXV02 | 80G1DF070BE12 | 22,000 | $1,100 |
| No | 206905817 | AC PRO | 4HP18V36P | ED1P30/36A+H4TXV02 | 80G1DF070AE12 | 22,200 | $1,110 |
| No | 206905754 | AC PRO | 4HP18V36P | EAH1P48B+H4TXV02 | EFV12BCA | 22,000 | $1,100 |
| No | 206905753 | AC PRO | 4HP18V36P | EAH1P48B+H4TXV02 | 96G2UH070BV12 | 22,400 | $1,120 |
| No | 206905752 | AC PRO | 4HP18V36P | EAH1P48B+H4TXV02 | 96G2UH045BV12 | 22,400 | $1,120 |
| No | 206905751 | AC PRO | 4HP18V36P | EAH1P48B+H4TXV02 | 96G1UH070BE12 | 22,000 | $1,100 |
| No | 206905749 | AC PRO | 4HP18V36P | EAH1P48B+H4TXV02 | 92G1UH070BE12 | 22,200 | $1,110 |
| No | 206905748 | AC PRO | 4HP18V36P | EAH1P48B+H4TXV02 | 92G1UH045BE12 | 22,400 | $1,120 |
| No | 206905747 | AC PRO | 4HP18V36P | EAH1P48B+H4TXV02 | 92G1UH030BE12 | 22,200 | $1,110 |
| No | 206905746 | AC PRO | 4HP18V36P | EAH1P48B+H4TXV02 | 80G2UH090BV16* | 22,400 | $1,120 |
| No | 206905744 | AC PRO | 4HP18V36P | EAH1P48B+H4TXV02 | 80G2UH090BE16 | 22,200 | $1,110 |
| No | 206905743 | AC PRO | 4HP18V36P | EAH1P48B+H4TXV02 | 80G2UH090BE12 | 22,400 | $1,120 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206905742 | AC PRO | 4HP18V36P | EAH1P48B+H4TXV02 | 80G1UH090BE16 | 22,000 | $1,100 |
| No | 206905741 | AC PRO | 4HP18V36P | EAH1P48B+H4TXV02 | 80G1UH070BE12 | 22,000 | $1,100 |
| No | 206905740 | AC PRO | 4HP18V36P | EAH1P36B+H4TXV02 | EFV12BCA | 22,200 | $1,110 |
| No | 206905739 | AC PRO | 4HP18V36P | EAH1P36B+H4TXV02 | 96G2UH070BV12 | 22,200 | $1,110 |
| No | 206905738 | AC PRO | 4HP18V36P | EAH1P36B+H4TXV02 | 96G2UH045BV12 | 22,400 | $1,120 |
| No | 206905737 | AC PRO | 4HP18V36P | EAH1P36B+H4TXV02 | 96G1UH070BE12 | 21,800 | $1,090 |
| No | 206905733 | AC PRO | 4HP18V36P | EAH1P36B+H4TXV02 | 92G1UH070BE12 | 22,200 | $1,110 |
| No | 206905732 | AC PRO | 4HP18V36P | EAH1P36B+H4TXV02 | 92G1UH045BE12 | 22,200 | $1,110 |
| No | 206905731 | AC PRO | 4HP18V36P | EAH1P36B+H4TXV02 | 92G1UH030BE12 | 22,200 | $1,110 |
| No | 206905730 | AC PRO | 4HP18V36P | EAH1P36B+H4TXV02 | 80G2UH090BV16* | 22,000 | $1,100 |
| No | 206905728 | AC PRO | 4HP18V36P | EAH1P36B+H4TXV02 | 80G2UH090BE16 | 22,200 | $1,110 |
| No | 206905727 | AC PRO | 4HP18V36P | EAH1P36B+H4TXV02 | 80G2UH090BE12 | 22,200 | $1,110 |
| No | 206905726 | AC PRO | 4HP18V36P | EAH1P36B+H4TXV02 | 80G1UH090BE16 | 22,000 | $1,100 |
| No | 206905725 | AC PRO | 4HP18V36P | EAH1P36B+H4TXV02 | 80G1UH080BE16X | 22,200 | $1,110 |
| No | 206905724 | AC PRO | 4HP18V36P | EAH1P36B+H4TXV02 | 80G1UH070BE12 | 22,000 | $1,100 |
| No | 206905701 | AC PRO | 4HP18V36P | EAC4X48C | EFV16CCA | 21,600 | $1,080 |
| No | 206905700 | AC PRO | 4HP18V36P | EAC4X48C | 96G2UH090CV12 | 21,600 | $1,080 |
| No | 206905699 | AC PRO | 4HP18V36P | EAC4X48C | 96G1UH090CE16 | 21,600 | $1,080 |
| No | 206905698 | AC PRO | 4HP18V36P | EAC4X48C | 95G1UH090CE16 | 21,600 | $1,080 |
| No | 206905696 | AC PRO | 4HP18V36P | EAC4X48C | 92G1UH110CE16 | 21,400 | $1,070 |
| No | 206905695 | AC PRO | 4HP18V36P | EAC4X48C | 92G1UH090CE16 | 21,600 | $1,080 |
| No | 206905694 | AC PRO | 4HP18V36P | EAC4X48C | 92G1UH090CE12 | 21,800 | $1,090 |
| No | 206905693 | AC PRO | 4HP18V36P | EAC4X48C | 80G2UH110CE16 | 21,600 | $1,080 |
| No | 206905692 | AC PRO | 4HP18V36P | EAC4X48B | EFV12BCA | 21,600 | $1,080 |
| No | 206905691 | AC PRO | 4HP18V36P | EAC4X48B | 96G2UH070BV12 | 21,800 | $1,090 |
| No | 206905690 | AC PRO | 4HP18V36P | EAC4X48B | 96G2UH045BV12 | 21,800 | $1,090 |
| No | 206905689 | AC PRO | 4HP18V36P | EAC4X48B | 96G1UH070BE12 | 21,400 | $1,070 |
| No | 206905688 | AC PRO | 4HP18V36P | EAC4X48B | 96G1UH045BE12 | 21,400 | $1,070 |
| No | 206905685 | AC PRO | 4HP18V36P | EAC4X48B | 92G1UH070BE12 | 21,600 | $1,080 |
| No | 206905684 | AC PRO | 4HP18V36P | EAC4X48B | 92G1UH045BE12 | 21,800 | $1,090 |
| No | 206905683 | AC PRO | 4HP18V36P | EAC4X48B | 92G1UH030BE12 | 21,600 | $1,080 |
| No | 206905682 | AC PRO | 4HP18V36P | EAC4X48B | 80G2UH090BV16* | 21,600 | $1,080 |
| No | 206905680 | AC PRO | 4HP18V36P | EAC4X48B | 80G2UH090BE16 | 21,600 | $1,080 |
| No | 206905679 | AC PRO | 4HP18V36P | EAC4X48B | 80G2UH090BE12 | 21,800 | $1,090 |
| No | 206905678 | AC PRO | 4HP18V36P | EAC4X48B | 80G1UH090BE16 | 21,600 | $1,080 |
| No | 206905677 | AC PRO | 4HP18V36P | EAC4X48B | 80G1UH080BE16X | 21,800 | $1,090 |
| No | 206905676 | AC PRO | 4HP18V36P | EAC4X48B | 80G1UH070BE12 | 21,600 | $1,080 |
| No | 206905608 | AC PRO | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 96G2UH090CV12 | 21,600 | $1,080 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206905607 | AC PRO | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 96G1UH090CE16 | 21,600 | $1,080 |
| No | 206905606 | AC PRO | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 95G1UH090CE16 | 21,600 | $1,080 |
| No | 206905604 | AC PRO | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 92G1UH110CE16 | 21,400 | $1,070 |
| No | 206905603 | AC PRO | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 92G1UH090CE16 | 21,600 | $1,080 |
| No | 206905602 | AC PRO | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 92G1UH090CE12 | 21,800 | $1,090 |
| No | 206905601 | AC PRO | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 80G2UH110CE16 | 21,600 | $1,080 |
| No | 206905600 | AC PRO | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | EFV12BCA | 21,800 | $1,090 |
| No | 206905599 | AC PRO | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 96G2UH070BV12 | 21,800 | $1,090 |
| No | 206905598 | AC PRO | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 96G2UH045BV12 | 21,800 | $1,090 |
| No | 206905597 | AC PRO | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 96G1UH070BE12 | 21,400 | $1,070 |
| No | 206905596 | AC PRO | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 96G1UH045BE12 | 21,400 | $1,070 |
| No | 206905593 | AC PRO | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 92G1UH070BE12 | 21,600 | $1,080 |
| No | 206905592 | AC PRO | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 92G1UH045BE12 | 21,800 | $1,090 |
| No | 206905591 | AC PRO | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 92G1UH030BE12 | 21,600 | $1,080 |
| No | 206905590 | AC PRO | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 80G2UH090BV16* | 21,600 | $1,080 |
| No | 206905588 | AC PRO | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 80G2UH090BE16 | 21,600 | $1,080 |
| No | 206905587 | AC PRO | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 80G2UH090BE12 | 21,800 | $1,090 |
| No | 206905586 | AC PRO | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 80G1UH090BE16 | 21,600 | $1,080 |
| No | 206905585 | AC PRO | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 80G1UH080BE16X | 21,800 | $1,090 |
| No | 206905675 | AC PRO | 4HP18V36P | EAC4X36B | EFV12BCA | 22,800 | $1,140 |
| No | 206905674 | AC PRO | 4HP18V36P | EAC4X36B | 96G2UH070BV12 | 22,800 | $1,140 |
| No | 206905673 | AC PRO | 4HP18V36P | EAC4X36B | 96G2UH045BV12 | 23,000 | $1,150 |
| No | 206905672 | AC PRO | 4HP18V36P | EAC4X36B | 96G1UH070BE12 | 22,400 | $1,120 |
| No | 206905668 | AC PRO | 4HP18V36P | EAC4X36B | 92G1UH070BE12 | 22,800 | $1,140 |
| No | 206905667 | AC PRO | 4HP18V36P | EAC4X36B | 92G1UH045BE12 | 22,800 | $1,140 |
| No | 206905666 | AC PRO | 4HP18V36P | EAC4X36B | 92G1UH030BE12 | 22,600 | $1,130 |
| No | 206905663 | AC PRO | 4HP18V36P | EAC4X36B | 80G2UH090BE16 | 22,800 | $1,140 |
| No | 206905662 | AC PRO | 4HP18V36P | EAC4X36B | 80G2UH090BE12 | 22,800 | $1,140 |
| No | 206905661 | AC PRO | 4HP18V36P | EAC4X36B | 80G1UH090BE16 | 22,600 | $1,130 |
| No | 206905660 | AC PRO | 4HP18V36P | EAC4X36B | 80G1UH080BE16X | 22,800 | $1,140 |
| No | 206905659 | AC PRO | 4HP18V36P | EAC4X36B | 80G1UH070BE12 | 22,600 | $1,130 |
| No | 206905656 | AC PRO | 4HP18V36P | EAC4X36A | 80G2UH070AE12 | 22,800 | $1,140 |
| No | 206905655 | AC PRO | 4HP18V36P | EAC4X36A | 80G1UH070AE12 | 22,600 | $1,130 |
| No | 206905654 | AC PRO | 4HP18V36P | EAC4X36A | 80G1UH060AE12X | 22,400 | $1,120 |
| No | 206905653 | AC PRO | 4HP18V36P | EAC4X36A | 80G1UH045AE12 | 22,400 | $1,120 |
| No | 206905583 | AC PRO | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | EFV12BCA | 22,000 | $1,100 |
| No | 206905582 | AC PRO | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 96G2UH070BV12 | 22,800 | $1,140 |
| No | 206905581 | AC PRO | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 96G2UH045BV12 | 23,000 | $1,150 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206905576 | AC PRO | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 92G1UH070BE12 | 22,800 | $1,140 |
| No | 206905575 | AC PRO | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 92G1UH045BE12 | 22,800 | $1,140 |
| No | 206905574 | AC PRO | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 92G1UH030BE12 | 22,600 | $1,130 |
| No | 206905571 | AC PRO | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 80G2UH090BE16 | 22,800 | $1,140 |
| No | 206905570 | AC PRO | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 80G2UH090BE12 | 22,800 | $1,140 |
| No | 206905569 | AC PRO | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 80G1UH090BE16 | 22,600 | $1,130 |
| No | 206905568 | AC PRO | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 80G1UH080BE16X | 22,800 | $1,140 |
| No | 206905567 | AC PRO | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 80G1UH070BE12 | 22,600 | $1,130 |
| No | 206905564 | AC PRO | 4HP18V36P | EA(C,U)1P36A+H4TXV02 | 80G2UH070AE12 | 22,800 | $1,140 |
| No | 206905563 | AC PRO | 4HP18V36P | EA(C,U)1P36A+H4TXV02 | 80G1UH070AE12 | 22,600 | $1,130 |
| No | 206905562 | AC PRO | 4HP18V36P | EA(C,U)1P36A+H4TXV02 | 80G1UH060AE12X | 22,400 | $1,120 |
| No | 206905561 | AC PRO | 4HP18V36P | EA(C,U)1P36A+H4TXV02 | 80G1UH045AE12 | 22,400 | $1,120 |
| No | 206905465 | AC PRO | 4HP18V36P | BCE7E36M | | 23,400 | $1,170 |
| No | 206905453 | AC PRO | 4HP18V36P | BCE5C36M*4X | | 22,400 | $1,120 |
| No | 206905452 | AC PRO | 4HP18V36P | BCE5C36M*1P+H4TXV02 | | 22,400 | $1,120 |
| No | 206905457 | AC PRO | 4HP18V36P | BCE5E42M | | 22,200 | $1,110 |
| No | 206905456 | AC PRO | 4HP18V36P | BCE5E36M | | 22,600 | $1,130 |
| No | 206905461 | AC PRO | 4HP18V36P | BCE5V42M | | 22,200 | $1,110 |
| No | 206905466 | AC PRO | 4HP18V36P | BCE7E42M | | 22,000 | $1,100 |
| No | 206905445 | AC PRO | 4HP18V36P | BCE5V36M | | 22,000 | $1,100 |
| No | 206905485 | AC PRO | 4HP18V36P | E*1P23B+H4TXV01 | 96G2UH070BV12 | 15,100 | $755 |
| No | 206905484 | AC PRO | 4HP18V36P | E*1P23B+H4TXV01 | 96G2UH045BV12 | 15,100 | $755 |
| No | 206905487 | AC PRO | 4HP18V36P | E*1P23B+H4TXV01 | EFV12BCA | 15,200 | $760 |
| No | 206905486 | AC PRO | 4HP18V36P | E*1P23B+H4TXV01 | EFV08BCA | 15,300 | $765 |
| No | 206905478 | AC PRO | 4HP18V36P | E*1P23B+H4TXV01 | 92G1UH070BE12 | 15,300 | $765 |
| No | 206905477 | AC PRO | 4HP18V36P | E*1P23B+H4TXV01 | 92G1UH045BE12 | 15,400 | $770 |
| No | 206905476 | AC PRO | 4HP18V36P | E*1P23B+H4TXV01 | 92G1UH030BE12 | 15,300 | $765 |
| No | 206905475 | AC PRO | 4HP18V36P | E*1P23B+H4TXV01 | 80G2UH090BE12 | 15,300 | $765 |
| No | 206905474 | AC PRO | 4HP18V36P | E*1P23B+H4TXV01 | 80G1UH070BE12 | 15,000 | $750 |
| No | 206905471 | AC PRO | 4HP18V36P | E*1P23A+H4TXV01 | 80G2UH070AE12 | 15,400 | $770 |
| No | 206905470 | AC PRO | 4HP18V36P | E*1P23A+H4TXV01 | 80G2UH045AE12 | 14,900 | $745 |
| No | 206905469 | AC PRO | 4HP18V36P | E*1P23A+H4TXV01 | 80G1UH060AE12X | 15,300 | $765 |
| No | 206905468 | AC PRO | 4HP18V36P | E*1P23A+H4TXV01 | 80G1UH045AE12 | 15,200 | $760 |
| No | 206905467 | AC PRO | 4HP18V36P | E*1P23A+H4TXV01 | 80G1UH040AE12X | 15,300 | $765 |
| No | 206905723 | AC PRO | 4HP18V36P | EAH1P30B+H4TXV01 | EFV12BCA | 15,600 | $780 |
| No | 206905722 | AC PRO | 4HP18V36P | EAH1P30B+H4TXV01 | EFV08BCA | 15,700 | $785 |
| No | 206905721 | AC PRO | 4HP18V36P | EAH1P30B+H4TXV01 | 96G2UH070BV12 | 15,500 | $775 |
| No | 206905720 | AC PRO | 4HP18V36P | EAH1P30B+H4TXV01 | 96G2UH045BV12 | 15,600 | $780 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206905719 | AC PRO | 4HP18V36P | EAH1P30B+H4TXV01 | 96G1UH070BE12 | 15,900 | $795 |
| No | 206905717 | AC PRO | 4HP18V36P | EAH1P30B+H4TXV01 | 96G1UH030BE08 | 15,800 | $790 |
| No | 206905713 | AC PRO | 4HP18V36P | EAH1P30B+H4TXV01 | 92G1UH070BE12 | 15,800 | $790 |
| No | 206905712 | AC PRO | 4HP18V36P | EAH1P30B+H4TXV01 | 92G1UH045BE12 | 15,900 | $795 |
| No | 206905711 | AC PRO | 4HP18V36P | EAH1P30B+H4TXV01 | 92G1UH030BE12 | 15,800 | $790 |
| No | 206905710 | AC PRO | 4HP18V36P | EAH1P30B+H4TXV01 | 80G2UH090BE12 | 15,800 | $790 |
| No | 206905709 | AC PRO | 4HP18V36P | EAH1P30B+H4TXV01 | 80G1UH070BE12 | 15,500 | $775 |
| No | 206905706 | AC PRO | 4HP18V36P | EAH1P30A+H4TXV01 | 80G2UH070AE12 | 15,800 | $790 |
| No | 206905705 | AC PRO | 4HP18V36P | EAH1P30A+H4TXV01 | 80G2UH045AE12 | 15,400 | $770 |
| No | 206905704 | AC PRO | 4HP18V36P | EAH1P30A+H4TXV01 | 80G1UH060AE12X | 15,700 | $785 |
| No | 206905703 | AC PRO | 4HP18V36P | EAH1P30A+H4TXV01 | 80G1UH045AE12 | 15,700 | $785 |
| No | 206905702 | AC PRO | 4HP18V36P | EAH1P30A+H4TXV01 | 80G1UH040AE12X | 15,700 | $785 |
| No | 206905650 | AC PRO | 4HP18V36P | EAC4X30B | 96G2UH070BV12 | 15,500 | $775 |
| No | 206905649 | AC PRO | 4HP18V36P | EAC4X30B | 96G2UH045BV12 | 15,600 | $780 |
| No | 206905652 | AC PRO | 4HP18V36P | EAC4X30B | EFV12BCA | 15,600 | $780 |
| No | 206905651 | AC PRO | 4HP18V36P | EAC4X30B | EFV08BCA | 15,900 | $795 |
| No | 206905648 | AC PRO | 4HP18V36P | EAC4X30B | 96G1UH070BE12 | 15,900 | $795 |
| No | 206905646 | AC PRO | 4HP18V36P | EAC4X30B | 96G1UH030BE08 | 15,800 | $790 |
| No | 206905642 | AC PRO | 4HP18V36P | EAC4X30B | 92G1UH070BE12 | 15,800 | $790 |
| No | 206905641 | AC PRO | 4HP18V36P | EAC4X30B | 92G1UH045BE12 | 15,900 | $795 |
| No | 206905640 | AC PRO | 4HP18V36P | EAC4X30B | 92G1UH030BE12 | 15,800 | $790 |
| No | 206905639 | AC PRO | 4HP18V36P | EAC4X30B | 80G2UH090BE12 | 15,800 | $790 |
| No | 206905638 | AC PRO | 4HP18V36P | EAC4X30B | 80G1UH070BE12 | 15,600 | $780 |
| No | 206905635 | AC PRO | 4HP18V36P | EAC4X30A | 80G2UH070AE12 | 15,800 | $790 |
| No | 206905634 | AC PRO | 4HP18V36P | EAC4X30A | 80G2UH045AE12 | 15,800 | $790 |
| No | 206905633 | AC PRO | 4HP18V36P | EAC4X30A | 80G1UH060AE12X | 15,800 | $790 |
| No | 206905632 | AC PRO | 4HP18V36P | EAC4X30A | 80G1UH045AE12 | 15,700 | $785 |
| No | 206905631 | AC PRO | 4HP18V36P | EAC4X30A | 80G1UH040AE12X | 15,800 | $790 |
| No | 206905558 | AC PRO | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 96G2UH070BV12 | 15,500 | $775 |
| No | 206905557 | AC PRO | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 96G2UH045BV12 | 15,600 | $780 |
| No | 206905560 | AC PRO | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | EFV12BCA | 15,600 | $780 |
| No | 206905559 | AC PRO | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | EFV08BCA | 15,900 | $795 |
| No | 206905556 | AC PRO | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 96G1UH070BE12 | 15,900 | $795 |
| No | 206905554 | AC PRO | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 96G1UH030BE08 | 15,800 | $790 |
| No | 206905550 | AC PRO | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 92G1UH070BE12 | 15,800 | $790 |
| No | 206905549 | AC PRO | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 92G1UH045BE12 | 15,900 | $795 |
| No | 206905548 | AC PRO | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 92G1UH030BE12 | 15,800 | $790 |
| No | 206905547 | AC PRO | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 80G2UH090BE12 | 15,800 | $790 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206905546 | AC PRO | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 80G1UH070BE12 | 15,600 | $780 |
| No | 206905543 | AC PRO | 4HP18V36P | EA(C,U)1P30A+H4TXV01 | 80G2UH070AE12 | 15,800 | $790 |
| No | 206905542 | AC PRO | 4HP18V36P | EA(C,U)1P30A+H4TXV01 | 80G2UH045AE12 | 15,800 | $790 |
| No | 206905541 | AC PRO | 4HP18V36P | EA(C,U)1P30A+H4TXV01 | 80G1UH060AE12X | 15,800 | $790 |
| No | 206905540 | AC PRO | 4HP18V36P | EA(C,U)1P30A+H4TXV01 | 80G1UH045AE12 | 15,700 | $785 |
| No | 206905539 | AC PRO | 4HP18V36P | EA(C,U)1P30A+H4TXV01 | 80G1UH040AE12X | 15,800 | $790 |
| No | 206905628 | AC PRO | 4HP18V36P | EAC4X24B | 96G2UH070BV12 | 15,900 | $795 |
| No | 206905627 | AC PRO | 4HP18V36P | EAC4X24B | 96G2UH045BV12 | 16,000 | $800 |
| No | 206905630 | AC PRO | 4HP18V36P | EAC4X24B | EFV12BCA | 16,000 | $800 |
| No | 206905621 | AC PRO | 4HP18V36P | EAC4X24B | 92G1UH070BE12 | 16,200 | $810 |
| No | 206905620 | AC PRO | 4HP18V36P | EAC4X24B | 92G1UH045BE12 | 16,200 | $810 |
| No | 206905618 | AC PRO | 4HP18V36P | EAC4X24B | 80G2UH090BE12 | 16,100 | $805 |
| No | 206905617 | AC PRO | 4HP18V36P | EAC4X24B | 80G1UH070BE12 | 15,900 | $795 |
| No | 206905614 | AC PRO | 4HP18V36P | EAC4X24A | 80G2UH070AE12 | 16,100 | $805 |
| No | 206905612 | AC PRO | 4HP18V36P | EAC4X24A | 80G1UH060AE12X | 16,100 | $805 |
| No | 206905610 | AC PRO | 4HP18V36P | EAC4X24A | 80G1UH040AE12X | 16,100 | $805 |
| No | 206905535 | AC PRO | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 96G2UH045BV12 | 16,000 | $800 |
| No | 206905536 | AC PRO | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 96G2UH070BV12 | 15,900 | $795 |
| No | 206905538 | AC PRO | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | EFV12BCA | 16,000 | $800 |
| No | 206905537 | AC PRO | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | EFV08BCA | 16,300 | $815 |
| No | 206905529 | AC PRO | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 92G1UH070BE12 | 16,200 | $810 |
| No | 206905528 | AC PRO | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 92G1UH045BE12 | 16,200 | $810 |
| No | 206905526 | AC PRO | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 80G2UH090BE12 | 16,100 | $805 |
| No | 206905525 | AC PRO | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 80G1UH070BE12 | 15,900 | $795 |
| No | 206905522 | AC PRO | 4HP18V36P | EA(C,U)1P24A+H4TXV01 | 80G2UH070AE12 | 16,100 | $805 |
| No | 206905520 | AC PRO | 4HP18V36P | EA(C,U)1P24A+H4TXV01 | 80G1UH060AE12X | 16,100 | $805 |
| No | 206905518 | AC PRO | 4HP18V36P | EA(C,U)1P24A+H4TXV01 | 80G1UH040AE12X | 16,100 | $805 |
| No | 206905464 | AC PRO | 4HP18V36P | BCE7E30M | | 16,200 | $810 |
| No | 206905463 | AC PRO | 4HP18V36P | BCE7E24M | | 15,800 | $790 |
| No | 206905462 | AC PRO | 4HP18V36P | BCE7E18M | | 15,400 | $770 |
| No | 206905460 | AC PRO | 4HP18V36P | BCE5V30M | | 15,900 | $795 |
| No | 206905458 | AC PRO | 4HP18V36P | BCE5V18M | | 15,900 | $795 |
| No | 206905455 | AC PRO | 4HP18V36P | BCE5E30M | | 15,900 | $795 |
| No | 206905454 | AC PRO | 4HP18V36P | BCE5E24M | | 15,000 | $750 |
| No | 206905451 | AC PRO | 4HP18V36P | BCE5C24M*4X | | 16,100 | $805 |
| No | 206905450 | AC PRO | 4HP18V36P | BCE5C24M*1P+H4TXV01 | | 16,100 | $805 |
| No | 206905449 | AC PRO | 4HP18V36P | BCE5C18M*4X | | 15,400 | $770 |
| No | 206905448 | AC PRO | 4HP18V36P | BCE5C18M*1P+H4TXV01 | | 15,400 | $770 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206905459 | AC PRO | 4HP18V36P | BCE5V24M | | 16,100 | $805 |
| No | 206906623 | AC PRO | 4HP18V60P | E*1P50C+H4TXV03 | 96G2UH110CV20 | 39,000 | $1,950 |
| No | 206906622 | AC PRO | 4HP18V60P | E*1P50C+H4TXV03 | 96G2UH090CV20 | 39,500 | $1,975 |
| No | 206906621 | AC PRO | 4HP18V60P | E*1P50C+H4TXV03 | 96G1UH110CE20 | 39,000 | $1,950 |
| No | 206906618 | AC PRO | 4HP18V60P | E*1P50C+H4TXV03 | 92G1UH110CE20 | 39,000 | $1,950 |
| No | 206906617 | AC PRO | 4HP18V60P | E*1P50C+H4TXV03 | 80G2UH110CV20 | 39,000 | $1,950 |
| No | 206906616 | AC PRO | 4HP18V60P | E*1P50C+H4TXV03 | 80G2UH110CE20L | 39,500 | $1,975 |
| No | 206906615 | AC PRO | 4HP18V60P | E*1P50C+H4TXV03 | 80G2UH110CE20 | 39,500 | $1,975 |
| No | 206906614 | AC PRO | 4HP18V60P | E*1P50C+H4TXV03 | 80G1UH110CE20 | 39,500 | $1,975 |
| No | 206906613 | AC PRO | 4HP18V60P | E*1P50C+H4TXV03 | 80G1UH100CE20X | 39,500 | $1,975 |
| No | 206906612 | AC PRO | 4HP18V60P | E*1P50C+H4TXV03 | 80G1UH090CE20 | 39,500 | $1,975 |
| No | 206906793 | AC PRO | 4HP18V60P | ED1P60D+H4TXV03 | EFV20DCA | 38,000 | $1,900 |
| No | 206906748 | AC PRO | 4HP18V60P | EAC4X60D | EFV20DCA | 40,000 | $2,000 |
| No | 206906747 | AC PRO | 4HP18V60P | EAC4X60D | 96G2UH135DV20 | 40,000 | $2,000 |
| No | 206906746 | AC PRO | 4HP18V60P | EAC4X60D | 80G1UH135DE20 | 40,000 | $2,000 |
| No | 206906742 | AC PRO | 4HP18V60P | EAC4X60C | 96G1UH110CE20 | 37,800 | $1,890 |
| No | 206906735 | AC PRO | 4HP18V60P | EAC4X60C | 80G1UH110CE20 | 38,000 | $1,900 |
| No | 206906734 | AC PRO | 4HP18V60P | EAC4X60C | 80G1UH100CE20X | 38,000 | $1,900 |
| No | 206906733 | AC PRO | 4HP18V60P | EAC4X60C | 80G1UH090CE20 | 38,000 | $1,900 |
| No | 206906686 | AC PRO | 4HP18V60P | EA(C,U)1P60D+H4TXV03 | EFV20DCA | 40,000 | $2,000 |
| No | 206906680 | AC PRO | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 96G1UH110CE20 | 37,800 | $1,890 |
| No | 206906673 | AC PRO | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 80G1UH110CE20 | 38,000 | $1,900 |
| No | 206906672 | AC PRO | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 80G1UH100CE20X | 38,000 | $1,900 |
| No | 206906671 | AC PRO | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 80G1UH090CE20 | 38,000 | $1,900 |
| No | 206906788 | AC PRO | 4HP18V60P | ED1P50/60C+H4TXV02 | EFV16CCA | 30,400 | $1,520 |
| No | 206906720 | AC PRO | 4HP18V60P | EAC4X49C | EFV16CCA | 30,600 | $1,530 |
| No | 206906709 | AC PRO | 4HP18V60P | EAC4X49C | 80G2UH110CE16 | 30,200 | $1,510 |
| No | 206906658 | AC PRO | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | EFV16CCA | 30,600 | $1,530 |
| No | 206906647 | AC PRO | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | 80G2UH110CE16 | 30,200 | $1,510 |
| No | 206906737 | AC PRO | 4HP18V60P | EAC4X60C | 80G2UH110CE20L | 38,000 | $1,900 |
| No | 206906675 | AC PRO | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 80G2UH110CE20L | 38,000 | $1,900 |
| No | 206906754 | AC PRO | 4HP18V60P | EAH1P48C+H4TXV02 | 80G2UH110CE20L | 31,000 | $1,550 |
| No | 206906789 | AC PRO | 4HP18V60P | ED1P60D+H4TXV03 | 80G1DF110CE20 | 38,000 | $1,900 |
| No | 206906792 | AC PRO | 4HP18V60P | ED1P60D+H4TXV03 | 96G2DF110CV20 | 38,500 | $1,925 |
| No | 206906791 | AC PRO | 4HP18V60P | ED1P60D+H4TXV03 | 96G2DF090CV20 | 38,500 | $1,925 |
| No | 206906766 | AC PRO | 4HP18V60P | EAH1P51C+H4TXV03 | 80G1UH090CE20 | 36,800 | $1,840 |
| No | 206906685 | AC PRO | 4HP18V60P | EA(C,U)1P60D+H4TXV03 | 96G2UH135DV20 | 39,000 | $1,950 |
| No | 206906684 | AC PRO | 4HP18V60P | EA(C,U)1P60D+H4TXV03 | 80G1UH135DE20 | 39,000 | $1,950 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206906744 | AC PRO | 4HP18V60P | EAC4X60C | 96G2UH110CV20 | 38,000 | $1,900 |
| No | 206906743 | AC PRO | 4HP18V60P | EAC4X60C | 96G2UH090CV20 | 38,000 | $1,900 |
| No | 206906739 | AC PRO | 4HP18V60P | EAC4X60C | 92G1UH110CE20 | 37,800 | $1,890 |
| No | 206906738 | AC PRO | 4HP18V60P | EAC4X60C | 80G2UH110CV20 | 38,000 | $1,900 |
| No | 206906736 | AC PRO | 4HP18V60P | EAC4X60C | 80G2UH110CE20 | 38,000 | $1,900 |
| No | 206906682 | AC PRO | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 96G2UH110CV20 | 38,000 | $1,900 |
| No | 206906681 | AC PRO | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 96G2UH090CV20 | 38,000 | $1,900 |
| No | 206906677 | AC PRO | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 92G1UH110CE20 | 37,800 | $1,890 |
| No | 206906676 | AC PRO | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 80G2UH110CV20 | 38,000 | $1,900 |
| No | 206906674 | AC PRO | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 80G2UH110CE20 | 38,000 | $1,900 |
| No | 206906603 | AC PRO | 4HP18V60P | BCE5V60M | | 38,500 | $1,925 |
| No | 206906719 | AC PRO | 4HP18V60P | EAC4X49C | 96G2UH110CV20 | 30,600 | $1,530 |
| No | 206906718 | AC PRO | 4HP18V60P | EAC4X49C | 96G2UH090CV20 | 30,800 | $1,540 |
| No | 206906713 | AC PRO | 4HP18V60P | EAC4X49C | 92G1UH110CE20 | 30,400 | $1,520 |
| No | 206906710 | AC PRO | 4HP18V60P | EAC4X49C | 80G2UH110CV20 | 30,400 | $1,520 |
| No | 206906708 | AC PRO | 4HP18V60P | EAC4X49C | 80G1UH110CE20 | 30,400 | $1,520 |
| No | 206906707 | AC PRO | 4HP18V60P | EAC4X49C | 80G1UH100CE20X | 30,600 | $1,530 |
| No | 206906657 | AC PRO | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | 96G2UH110CV20 | 30,600 | $1,530 |
| No | 206906656 | AC PRO | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | 96G2UH090CV20 | 30,800 | $1,540 |
| No | 206906651 | AC PRO | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | 92G1UH110CE20 | 30,400 | $1,520 |
| No | 206906648 | AC PRO | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | 80G2UH110CV20 | 30,400 | $1,520 |
| No | 206906646 | AC PRO | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | 80G1UH110CE20 | 30,400 | $1,520 |
| No | 206906645 | AC PRO | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | 80G1UH100CE20X | 30,600 | $1,530 |
| No | 206906755 | AC PRO | 4HP18V60P | EAH1P48C+H4TXV02 | 80G2UH110CV20 | 31,000 | $1,550 |
| No | 206906764 | AC PRO | 4HP18V60P | EAH1P48C+H4TXV02 | 96G2UH110CV20 | 31,200 | $1,560 |
| No | 206906763 | AC PRO | 4HP18V60P | EAH1P48C+H4TXV02 | 96G2UH090CV20 | 31,400 | $1,570 |
| No | 206906758 | AC PRO | 4HP18V60P | EAH1P48C+H4TXV02 | 92G1UH110CE20 | 30,800 | $1,540 |
| No | 206906753 | AC PRO | 4HP18V60P | EAH1P48C+H4TXV02 | 80G2UH110CE20 | 31,000 | $1,550 |
| No | 206906751 | AC PRO | 4HP18V60P | EAH1P48C+H4TXV02 | 80G1UH110CE20 | 30,800 | $1,540 |
| No | 206906749 | AC PRO | 4HP18V60P | EAH1P48C+H4TXV02 | 80G1UH090CE20 | 30,800 | $1,540 |
| No | 206906611 | AC PRO | 4HP18V60P | BCE7E48M | | 32,200 | $1,610 |
| No | 206906608 | AC PRO | 4HP18V60P | BCE5E48M | | 31,600 | $1,580 |
| No | 206906607 | AC PRO | 4HP18V60P | BCE5C48M*4X | | 31,600 | $1,580 |
| No | 206906606 | AC PRO | 4HP18V60P | BCE5C48M*1P+H4TXV02 | | 31,600 | $1,580 |
| No | 206906610 | AC PRO | 4HP18V60P | BCE5V48M | | 31,400 | $1,570 |
| No | 206905821 | AC PRO | 4HP18V36P | ED1P30/36B+H4TXV02 | 80G2DF090BE16 | 22,200 | $1,110 |
| No | 206905584 | AC PRO | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 80G1UH070BE12 | 21,600 | $1,080 |
| No | 206905665 | AC PRO | 4HP18V36P | EAC4X36B | 80G2UH090BV16* | 22,800 | $1,140 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206905573 | AC PRO | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 80G2UH090BV16* | 22,800 | $1,140 |
| No | 206905815 | AC PRO | 4HP18V36P | ED1P24B+H4TXV01 | EFV12BCA | 15,500 | $775 |
| No | 206905814 | AC PRO | 4HP18V36P | ED1P24B+H4TXV01 | EFV08BCA | 15,700 | $785 |
| No | 206905813 | AC PRO | 4HP18V36P | ED1P24B+H4TXV01 | 96G2DF070BV16 | 15,800 | $790 |
| No | 206905718 | AC PRO | 4HP18V36P | EAH1P30B+H4TXV01 | 96G1UH045BE12 | 15,900 | $795 |
| No | 206905708 | AC PRO | 4HP18V36P | EAH1P30A+H4TXV01 | 80G2UH070AV12* | 15,600 | $780 |
| No | 206905644 | AC PRO | 4HP18V36P | EAC4X30B | 95G1UH045BE12 | 15,800 | $790 |
| No | 206905637 | AC PRO | 4HP18V36P | EAC4X30A | 80G2UH070AV12* | 15,600 | $780 |
| No | 206905555 | AC PRO | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 96G1UH045BE12 | 15,900 | $795 |
| No | 206905545 | AC PRO | 4HP18V36P | EA(C,U)1P30A+H4TXV01 | 80G2UH070AV12* | 15,600 | $780 |
| No | 206905626 | AC PRO | 4HP18V36P | EAC4X24B | 96G1UH070BE12 | 16,300 | $815 |
| No | 206905625 | AC PRO | 4HP18V36P | EAC4X24B | 96G1UH045BE12 | 16,300 | $815 |
| No | 206905624 | AC PRO | 4HP18V36P | EAC4X24B | 96G1UH030BE08 | 15,800 | $790 |
| No | 206905619 | AC PRO | 4HP18V36P | EAC4X24B | 92G1UH030BE12 | 15,700 | $785 |
| No | 206905616 | AC PRO | 4HP18V36P | EAC4X24A | 80G2UH070AV12* | 16,000 | $800 |
| No | 206905534 | AC PRO | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 96G1UH070BE12 | 16,300 | $815 |
| No | 206905533 | AC PRO | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 96G1UH045BE12 | 16,300 | $815 |
| No | 206905532 | AC PRO | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 96G1UH030BE08 | 15,800 | $790 |
| No | 206905524 | AC PRO | 4HP18V36P | EA(C,U)1P24A+H4TXV01 | 80G2UH070AV12* | 16,000 | $800 |
| No | 206905483 | AC PRO | 4HP18V36P | E*1P23B+H4TXV01 | 96G1UH070BE12 | 15,400 | $770 |
| No | 206905482 | AC PRO | 4HP18V36P | E*1P23B+H4TXV01 | 96G1UH045BE12 | 15,400 | $770 |
| No | 206905481 | AC PRO | 4HP18V36P | E*1P23B+H4TXV01 | 96G1UH030BE08 | 14,900 | $745 |
| No | 206905473 | AC PRO | 4HP18V36P | E*1P23A+H4TXV01 | 80G2UH070AV12* | 15,200 | $760 |
| No | 206905499 | AC PRO | 4HP18V36P | E*1P36B+H4TXV02 | 80G2UH090BE16L | 23,400 | $1,170 |
| No | 206905745 | AC PRO | 4HP18V36P | EAH1P48B+H4TXV02 | 80G2UH090BE16L | 22,200 | $1,110 |
| No | 206905729 | AC PRO | 4HP18V36P | EAH1P36B+H4TXV02 | 80G2UH090BE16L | 22,200 | $1,110 |
| No | 206905681 | AC PRO | 4HP18V36P | EAC4X48B | 80G2UH090BE16L | 21,600 | $1,080 |
| No | 206905589 | AC PRO | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 80G2UH090BE16L | 21,600 | $1,080 |
| No | 206905664 | AC PRO | 4HP18V36P | EAC4X36B | 80G2UH090BE16L | 22,800 | $1,140 |
| No | 206905572 | AC PRO | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 80G2UH090BE16L | 22,800 | $1,140 |
| No | 212219665 | AC PRO.COM | AOD30U-36HFN1-MP0(GA) | ACD1-36HRFN1-M(GA) | | 23,000 | $1,150 |
| No | 212219666 | AC PRO.COM | AOD30U-36HFN1-MP0(GA) | AUE-36HRFN1-M(C) | | 23,000 | $1,150 |
| No | 211001954 | AC PRO.COM | AOD30U-36HFN1-M(GA) | AVCU-36HWFN1-M(GA) | | 27,000 | $1,350 |
| No | 209748112 | AC PRO.COM | AOE30U-60HFN1-MR0 | AVC-60HWFN1-M | | 37,000 | $1,850 |
| No | 209748111 | AC PRO.COM | AOE30U-48HFN1-MR0 | AVC-48HWFN1-M | | 37,000 | $1,850 |
| No | 209748110 | AC PRO.COM | AOD30U-36HFN1-MR0 | AVC-36HWFN1-M | | 20,400 | $1,020 |
| No | 209748109 | AC PRO.COM | AOX430-24HFN1-MR0 | AVC-24HWFN1-M | | 21,000 | $1,050 |
| No | 208650715 | AC PRO.COM | AOX330-18HFN1-MR0 | AVC-18HWFN1-M | | 12,000 | $600 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211001953 | AC PRO.COM | AOD30U-30HFN1-M(GA) | AVC-30HWFN1-M(GA) | | 20,400 | $1,020 |
| No | 211001952 | AC PRO.COM | AOD32-24HFN1-MT0W | AVC-23HWFN1-M | | 17,000 | $850 |
| No | 211001951 | AC PRO.COM | AOX430-18HFN1-MT8W | AVC-18HWFN1-MW(GA) | | 13,200 | $660 |
| No | 210343320 | AC PRO.COM | A5OA-55HFN1-M | Heat pump without ducts | | 36,400 | $1,820 |
| No | 207827136 | AC PRO.COM | A5OG-48HFN1-M | Heat pump without ducts | | 34,000 | $1,700 |
| No | 207827128 | AC PRO.COM | A4OG-36HFN1-M | Heat pump without ducts | | 26,800 | $1,340 |
| No | 211001949 | AC PRO.COM | AOX230-12HFN1-MV5W | ACBU-12HRFN1-MV0W | | 7,700 | $385 |
| No | 211001948 | AC PRO.COM | AOX230-09HFN1-MW5W | ACBU-09HRFN1-MW0W | | 8,000 | $400 |
| No | 211001950 | AC PRO.COM | AOX430-18HFN1-MT8W | ACBU-18HRFN1-MU2W | | 12,200 | $610 |
| No | 207827126 | AC PRO.COM | A3OJ-27HFN1-M | Heat pump with ducts | | 22,000 | $1,100 |
| No | 207827125 | AC PRO.COM | A2OA-18HFN1-M | Heat pump with ducts | | 14,800 | $740 |
| No | 207827135 | AC PRO.COM | A3OJ-27HFN1-M | Heat pump without ducts | | 21,000 | $1,050 |
| No | 207827133 | AC PRO.COM | A2OA-18HFN1-M | Heat pump without ducts | | 14,300 | $715 |
| No | 209748105 | AC PRO.COM | AOX430-18HFN1-MT8W | ATIU-18HWFN1-M | | 12,600 | $630 |
| No | 209748101 | AC PRO.COM | AOX430-18HFN1-MT8W | ACCA3U-18HRFN1-M(C) | | 12,000 | $600 |
| No | 209748107 | AC PRO.COM | AOX430-18HFN1-MT8W | AUEU-18HRFN1-M(C) | | 12,800 | $640 |
| No | 209843057 | AC PRO.COM | AOX430-18HFN1-MT8W | ASEPC-18HRFN1-MU0W | | 14,900 | $745 |
| No | 209748102 | AC PRO.COM | AOD32-24HFN1-MT0W | ACD1-24HRFN1-MT0W | | 19,000 | $950 |
| No | 210265863 | AC PRO.COM | AOD30U-36HFN1-MP0(GA) | ATI-36HWFN1-M | | 25,000 | $1,250 |
| No | 209748106 | AC PRO.COM | AOX230-12HFN1-MV5W | AFAU-12HRFN1-M(C) | | 9,000 | $450 |
| No | 209748104 | AC PRO.COM | AOX230-12HFN1-MV5W | ATIU-12HWFN1-M | | 9,300 | $465 |
| No | 209748103 | AC PRO.COM | AOX230-09HFN1-MW5W | ATIU-09HWFN1-M | | 7,700 | $385 |
| No | 209748108 | AC PRO.COM | AOD32-24HFN1-MT0W | AUEU-24HRFN1-M(C) | | 16,000 | $800 |
| No | 209748100 | AC PRO.COM | AOX230-12HFN1-MV5W | ACCA3U-12HRFN1-M(C) | | 8,900 | $445 |
| No | 209748099 | AC PRO.COM | AOX230-09HFN1-MW5W | ACCA3U-09HRFN1-M | | 7,500 | $375 |
| No | 207827153 | AC PRO.COM | AOX430-17HFN1-MT0W | ACCA3U-18HRFN1-M | | 12,000 | $600 |
| No | 207827147 | AC PRO.COM | AOX430-18HFN1-MU0W | ASEPC-18HRFN1-MU0W | | 14,900 | $745 |
| No | 207827141 | AC PRO.COM | AOX330-18HFN1-MS0W | ASABD-18HRFN1-MS1W | | 11,500 | $575 |
| No | 207827139 | AC PRO.COM | AOX230-09HFN1-MT0W | ASABA-09HRFN1-MU5W | | 6,900 | $345 |
| No | 207827137 | AC PRO.COM | AOX230-09HFN1-BS5W | ASABA-09HRFN1-BT5W | | 6,800 | $340 |
| No | 207827144 | AC PRO.COM | AOD31-36HFN1-MP0W | ASABF-36HRFNX-MQ0W | | 24,000 | $1,200 |
| No | 207827148 | AC PRO.COM | AOD32-24HFN1-MT0W | ASEPD-24HRFN1-MU0W | | 16,200 | $810 |
| No | 207827146 | AC PRO.COM | AOX230-12HFN1-MV5W | ASEPB-12HRFN1-MW5W(GA) | | 9,000 | $450 |
| No | 207827145 | AC PRO.COM | AOX230-09HFN1-MW5W | ASEPB-09HRFN1-MY5W(GA) | | 8,500 | $425 |
| No | 207827157 | AC PRO.COM | AOD32-24HFN1-MT0W | ATIU-24HWFN1-M | | 20,000 | $1,000 |
| No | 207827158 | AC PRO.COM | AOX330-12HFN1-MW5W | AFAU-12HRFN1-M(C) | | 9,600 | $480 |
| No | 207827155 | AC PRO.COM | AOX330-12HFN1-MW5W | ATIU-12HWFN1-M | | 10,600 | $530 |
| No | 207827152 | AC PRO.COM | AOX330-12HFN1-MW5W | ACCA3U-12HRFN1-M | | 9,900 | $495 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207827151 | AC PRO.COM | AOX330-09HFN1-MY5W | ACCA3U-09HRFN1-M | | 9,000 | $450 |
| No | 207827154 | AC PRO.COM | AOX330-09HFN1-MY5W | ATIU-09HWFN1-M | | 7,700 | $385 |
| No | 210343322 | AC PRO.COM | A5OA-55HFN1-M | Combination heat pumps with or without ducts | | 35,600 | $1,780 |
| No | 210343321 | AC PRO.COM | A5OA-55HFN1-M | Heat pump with ducts | | 35,000 | $1,750 |
| No | 205921395 | AC PRO.COM | AOBA30-09HFN1-MT0W | AS11M-09HRFN1-MXOW(A) | | 5,800 | $290 |
| No | 205921396 | AC PRO.COM | AOB30-12HFN1-MT0W | AS11M-12HRFN1-MU5W | | 7,700 | $385 |
| No | 205355555 | AC PRO.COM | AOCA31-18HFN1-MT0W | ATIU-18HWFN1-M | | 12,000 | $600 |
| No | 205355570 | AC PRO.COM | AOBA30-09HFN1-BS0W | ASABA-09HRFN1-BS0W | | 6,000 | $300 |
| No | 205355574 | AC PRO.COM | AOB30-18HFN1-MS0W | ASABD-18HRFN1-MS0W | | 11,000 | $550 |
| No | 205921398 | AC PRO.COM | AOD31-24HFN1-MT0W | AS11M-23HRFN1-MTOW | | 15,300 | $765 |
| No | 205355553 | AC PRO.COM | AOBA30-09HFN1-MT0W | ATIU-09HWFN1-M | | 6,800 | $340 |
| No | 205921397 | AC PRO.COM | AOCA31-18HFN1-MT0W | AS11M-18HRFN1-MTOW | | 11,400 | $570 |
| No | 205355559 | AC PRO.COM | AOBA30-09HFN1-MT0W | ACCA3U-09HRFN1-M | | 5,800 | $290 |
| No | 205355561 | AC PRO.COM | AOCA31-18HFN1-MT0W | ACCA3U-18HRFN1-M | | 12,000 | $600 |
| No | 205355556 | AC PRO.COM | AOD31-24HFN1-MT0W | ATIU-24HWFN1-M | | 16,000 | $800 |
| No | 205355558 | AC PRO.COM | AOE30U-48HFN1-M | ATI-48HWFN1-M | | 33,400 | $1,670 |
| No | 205355557 | AC PRO.COM | AOD30U-36HFN1-M | ATI-36HWFN1-M | | 27,600 | $1,380 |
| No | 205355562 | AC PRO.COM | AOD31-24HFN1-MT0W | ACDU-24HRFN1-M | | 15,800 | $790 |
| No | 205355564 | AC PRO.COM | AOE30U-48HFN1-M | ACDU-48HRFN1-M | | 35,000 | $1,750 |
| No | 205355563 | AC PRO.COM | AOD30U-36HFN1-M | ACDU-36HRFN1-M | | 25,200 | $1,260 |
| No | 205355566 | AC PRO.COM | AOCA31-18HFN1-MT0W | AUEU-18HRFN1-M(C) | | 12,000 | $600 |
| No | 205355567 | AC PRO.COM | AOD31-24HFN1-MT0W | AUEU-24HRFN1-M(C) | | 15,000 | $750 |
| No | 205355565 | AC PRO.COM | AOB30-12HFN1-MT0W | AFAU-12HRFN1-M(C) | | 7,200 | $360 |
| No | 205355560 | AC PRO.COM | AOB30-12HFN1-MT0W | ACCA3U-12HRFN1-M | | 7,500 | $375 |
| No | 205355569 | AC PRO.COM | AOE30U-48HFN1-M | AUE-48HRFN1-M(C) | | 35,000 | $1,750 |
| No | 205816501 | AC PRO.COM | A4OF-36HFN1-M | Heat pump without ducts | | 24,600 | $1,230 |
| No | 205816495 | AC PRO.COM | A2OF-18HFN1-M | Heat pump without ducts | | 12,000 | $600 |
| No | 207691810 | AC PRO.COM | AOX430-24HFN1-MR0 | AVC-24HWFN1-M | | 17,000 | $850 |
| No | 207691812 | AC PRO.COM | AOE30U-48HFN1-MR0 | AVC-48HWFN1-M | | 33,000 | $1,650 |
| No | 207691811 | AC PRO.COM | AOD30U-36HFN1-MR0 | AVC-36HWFN1-M | | 18,400 | $920 |
| No | 207691813 | AC PRO.COM | AOE30U-60HFN1-MR0 | AVC-60HWFN1-M | | 33,800 | $1,690 |
| No | 207827131 | AC PRO.COM | A5OG-48HFN1-M | Heat pump with ducts | | 30,400 | $1,520 |
| No | 207827132 | AC PRO.COM | A5OG-48HFN1-M | Combination heat pumps with or without ducts | | 30,000 | $1,500 |
| No | 207827134 | AC PRO.COM | A2OA-18HFN1-M | Combination heat pumps with or without ducts | | 11,400 | $570 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207827127 | AC PRO.COM | A3OJ-27HFN1-M | Combination heat pumps with or without ducts | | 16,000 | $800 |
| No | 208650714 | AC PRO.COM | AOD30U-30HFN1-MR0 | AVC-30HWFN1-M | | 19,000 | $950 |
| No | 205355578 | AC PRO.COM | AOE30U-48HFN1-MP0 | AVB-48HWFN1-M | | 36,000 | $1,800 |
| No | 205355577 | AC PRO.COM | AOD30U-36HFN1-MP0 | AVB-36HWFN1-M | | 25,000 | $1,250 |
| No | 202110497 | ACD | MPD24KCH21S-O | Heat pump without ducts | | 16,600 | $830 |
| No | 202110500 | ACD | MPD30KCH21S-O | Heat pump without ducts | | 18,000 | $900 |
| No | 202110494 | ACD | MPD18KCH22S-O | Heat pump without ducts | | 12,800 | $640 |
| No | 201863350 | ACD | OCD09KCH23S-O | OCD09KCH23S-I | | 7,300 | $365 |
| No | 202110506 | ACD | MPD42KCH21S-O | Heat pump without ducts | | 29,000 | $1,450 |
| No | 206703383 | ACD | OCD15KCH20S-O | OCD15KCH20S-I | | 10,300 | $515 |
| No | 201863351 | ACD | OCD12KCH22S-O | OCD12KCH22S-I | | 7,700 | $385 |
| No | 206428586 | ACD | MUD36KCH23S-O | Heat pump without ducts | | 29,000 | $1,450 |
| No | 206428587 | ACD | MUD42KCH23S-O | Heat pump without ducts | | 30,000 | $1,500 |
| No | 202110484 | ACD | UHD12KCH31S-O | UHD12KCH31S-I | | 8,300 | $415 |
| No | 202409832 | ACD | UHD09KCH38SB-O | UHD09KCH38SB-I | | 7,300 | $365 |
| No | 202110503 | ACD | MPD36KCH21S-O | Heat pump without ducts | | 20,000 | $1,000 |
| No | 202110483 | ACD | UHD09KCH38S-O | UHD09KCH38S-I | | 5,600 | $280 |
| No | 212394316 | ACIQ | ACIQ-18-EHPB | ACIQ-18-ACL | | 13,000 | $650 |
| No | 212394326 | ACIQ | ACIQ-48-HPB | ACIQ-48-ACL | | 32,000 | $1,600 |
| No | 212394325 | ACIQ | ACIQ-36-HPB | ACIQ-36-ACL | | 33,000 | $1,650 |
| No | 212394320 | ACIQ | ACIQ-48-EHPB | ACIQ-48-ACL | | 30,400 | $1,520 |
| No | 212394319 | ACIQ | ACIQ-36-EHPB | ACIQ-36-ACL | | 19,800 | $990 |
| No | 212394323 | ACIQ | ACIQ-24-HPB | ACIQ-24-ACL | | 21,000 | $1,050 |
| No | 212394322 | ACIQ | ACIQ-18-HPB | ACIQ-18-ACL | | 14,700 | $735 |
| No | 212394321 | ACIQ | ACIQ-60-EHPB | ACIQ-60-ACL | | 34,000 | $1,700 |
| No | 212394318 | ACIQ | ACIQ-30-EHPB | ACIQ-30-ACL | | 22,000 | $1,100 |
| No | 212394317 | ACIQ | ACIQ-24-EHPB | ACIQ-24-ACL | | 22,000 | $1,100 |
| No | 208106636 | ACIQ | ACIQ-36-HPB | ACIQ-36-AHB | | 30,400 | $1,520 |
| No | 210857327 | ACIQ | ACIQ-06ZPL-HP230B | SCC-0609-HH-M | | 5,700 | $285 |
| No | 210857329 | ACIQ | ACIQ-12ZPL-HP230B | SCC-1218-HH-M | | 9,500 | $475 |
| No | 210857328 | ACIQ | ACIQ-09ZPL-HP230B | SCC-0609-HH-M | | 9,800 | $490 |
| No | 210857395 | ACIQ | ES-55Z-M5B | Heat pump without ducts | | 34,400 | $1,720 |
| No | 210857392 | ACIQ | ES-48Z-M5B | Heat pump without ducts | | 34,000 | $1,700 |
| No | 210857389 | ACIQ | ES-36Z-M4B | Heat pump without ducts | | 26,800 | $1,340 |
| No | 210857387 | ACIQ | ES-27Z-M3B | Heat pump with ducts | | 22,000 | $1,100 |
| No | 210857384 | ACIQ | ES-18Z-M2B | Heat pump with ducts | | 14,800 | $740 |
| No | 210857386 | ACIQ | ES-27Z-M3B | Heat pump without ducts | | 21,000 | $1,050 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210857383 | ACIQ | ES-18Z-M2B | Heat pump without ducts | | 14,300 | $715 |
| No | 210857332 | ACIQ | ACIQ-18ZPL-HP230B | ACIQ-18FM-HH-MC | | 14,700 | $735 |
| No | 210857331 | ACIQ | ACIQ-12ZPL-HP230B | ACIQ-12FM-HH-MC | | 10,200 | $510 |
| No | 207825528 | ACIQ | ACIQ-18Z-HP230B | ACIQ-18W-HP230B | | 11,500 | $575 |
| No | 207825526 | ACIQ | ACIQ-09Z-HP115B | ACIQ-09W-HP115B | | 6,800 | $340 |
| No | 210857321 | ACIQ | ACIQ-36ZPL-HP230B | ACIQ-36CD-HH-MB | | 34,000 | $1,700 |
| No | 210857314 | ACIQ | ACIQ-06ZPL-HP230B | ACIQ-06W-HH-MC | | 8,500 | $425 |
| No | 207825530 | ACIQ | ACIQ-36Z-HP230B | ACIQ-36W-HP230B | | 24,000 | $1,200 |
| No | 207825537 | ACIQ | ACIQ-18ZPL-HP230B | ACIQ-18CC-HH-MB | | 15,600 | $780 |
| No | 207825543 | ACIQ | ACIQ-18ZPL-HP230B | ACIQ-18FM-HH-MB | | 12,000 | $600 |
| No | 207825542 | ACIQ | ACIQ-12ZPL-HP230B | ACIQ-12FM-HH-MB | | 9,600 | $480 |
| No | 207825539 | ACIQ | ACIQ-12ZPL-HP230B | ACIQ-12CD-HH-MB | | 10,600 | $530 |
| No | 207825536 | ACIQ | ACIQ-12ZPL-HP230B | ACIQ-12CC-HH-MB | | 9,900 | $495 |
| No | 207825538 | ACIQ | ACIQ-09ZPL-HP230B | ACIQ-09CD-HH-MB | | 10,100 | $505 |
| No | 207825535 | ACIQ | ACIQ-09ZPL-HP230B | ACIQ-09CC-HH-MB | | 9,000 | $450 |
| No | 207825532 | ACIQ | ACIQ-12ZPL-HP230B | ACIQ-12W-HH-MB | | 10,000 | $500 |
| No | 210857316 | ACIQ | ACIQ-12ZPL-HP230B | ACIQ-12W-HH-MC | | 10,000 | $500 |
| No | 210857315 | ACIQ | ACIQ-09ZPL-HP230B | ACIQ-09W-HH-MC | | 9,500 | $475 |
| No | 207825531 | ACIQ | ACIQ-09ZPL-HP230B | ACIQ-09W-HH-MB | | 9,500 | $475 |
| No | 206315633 | ACIQ | ACIQ-18Z-HP230 | ACIQ-18W-HP230 | | 11,000 | $550 |
| No | 206315631 | ACIQ | ACIQ-09Z-HP115 | ACIQ-09W-HP115 | | 6,000 | $300 |
| No | 207825578 | ACIQ | ACIQ-18Z-HH-M2B | Combination heat pumps with or without ducts | | 11,500 | $575 |
| No | 207825581 | ACIQ | ACIQ-27Z-HH-M3B | Combination heat pumps with or without ducts | | 17,000 | $850 |
| No | 206315639 | ACIQ | ACIQ-48-HP | ACIQ-48-AH | | 36,000 | $1,800 |
| No | 206315638 | ACIQ | ACIQ-36-HP | ACIQ-36-AH | | 25,000 | $1,250 |
| No | 212361492 | ADP | BOVA-60HDN1-M20G | HE48960 | BGH96M120D5B | 34,600 | $1,730 |
| No | 212361491 | ADP | BOVA-60HDN1-M20G | HE37960 | BGH96M120D5B | 34,600 | $1,730 |
| No | 212361490 | ADP | BOVA-60HDN1-M20G | HE36960 | BGH96M120D5B | 34,600 | $1,730 |
| No | 212361489 | ADP | BOVA-60HDN1-M20G | HE35948 | BGH96M120D5B | 34,600 | $1,730 |
| No | 212361488 | ADP | BOVA-60HDN1-M20G | HE48960 | BGH96M120D5A | 34,600 | $1,730 |
| No | 212361487 | ADP | BOVA-60HDN1-M20G | HE37960 | BGH96M120D5A | 34,600 | $1,730 |
| No | 212361486 | ADP | BOVA-60HDN1-M20G | HE36960 | BGH96M120D5A | 34,600 | $1,730 |
| No | 212361485 | ADP | BOVA-60HDN1-M20G | HE35948 | BGH96M120D5A | 34,600 | $1,730 |
| No | 212361484 | ADP | BOVA-60HDN1-M20G | HE48960 | BGH96M100D5B | 34,600 | $1,730 |
| No | 212361483 | ADP | BOVA-60HDN1-M20G | HE37960 | BGH96M100D5B | 34,600 | $1,730 |
| No | 212361482 | ADP | BOVA-60HDN1-M20G | HE36960 | BGH96M100D5B | 34,600 | $1,730 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 212361481 | ADP | BOVA-60HDN1-M20G | HE35948 | BGH96M100D5B | 34,600 | $1,730 |
| No | 212361480 | ADP | BOVA-60HDN1-M20G | HE48960 | BGH96M100D5A | 34,600 | $1,730 |
| No | 212361479 | ADP | BOVA-60HDN1-M20G | HE37960 | BGH96M100D5A | 34,600 | $1,730 |
| No | 212361478 | ADP | BOVA-60HDN1-M20G | HE36960 | BGH96M100D5A | 34,600 | $1,730 |
| No | 212361477 | ADP | BOVA-60HDN1-M20G | HE35948 | BGH96M100D5A | 34,600 | $1,730 |
| No | 212361476 | ADP | BOVA-60HDN1-M20G | HE48960 | BGH96M100C5B | 34,600 | $1,730 |
| No | 212361475 | ADP | BOVA-60HDN1-M20G | HE37960 | BGH96M100C5B | 34,600 | $1,730 |
| No | 212361474 | ADP | BOVA-60HDN1-M20G | HE36960 | BGH96M100C5B | 34,600 | $1,730 |
| No | 212361473 | ADP | BOVA-60HDN1-M20G | HE35948 | BGH96M100C5B | 34,600 | $1,730 |
| No | 212361472 | ADP | BOVA-60HDN1-M20G | HE48960 | BGH96M100C5A | 34,600 | $1,730 |
| No | 212361471 | ADP | BOVA-60HDN1-M20G | HE37960 | BGH96M100C5A | 34,600 | $1,730 |
| No | 212361470 | ADP | BOVA-60HDN1-M20G | HE36960 | BGH96M100C5A | 34,600 | $1,730 |
| No | 212361469 | ADP | BOVA-60HDN1-M20G | HE35948 | BGH96M100C5A | 34,600 | $1,730 |
| No | 212361468 | ADP | BOVA-60HDN1-M20G | HE48960 | BGH96M080C4B | 34,000 | $1,700 |
| No | 212361467 | ADP | BOVA-60HDN1-M20G | HE37960 | BGH96M080C4B | 34,000 | $1,700 |
| No | 212361466 | ADP | BOVA-60HDN1-M20G | HE36960 | BGH96M080C4B | 34,000 | $1,700 |
| No | 212361465 | ADP | BOVA-60HDN1-M20G | HE35948 | BGH96M080C4B | 34,000 | $1,700 |
| No | 212361464 | ADP | BOVA-60HDN1-M20G | HE48960 | BGH96M080C4A | 34,000 | $1,700 |
| No | 212361463 | ADP | BOVA-60HDN1-M20G | HE37960 | BGH96M080C4A | 34,000 | $1,700 |
| No | 212361462 | ADP | BOVA-60HDN1-M20G | HE36960 | BGH96M080C4A | 34,000 | $1,700 |
| No | 212361461 | ADP | BOVA-60HDN1-M20G | HE35948 | BGH96M080C4A | 34,000 | $1,700 |
| No | 212361460 | ADP | BOVA-60HDN1-M20G | HE48960 | BGH96M080B3B | 34,000 | $1,700 |
| No | 212361459 | ADP | BOVA-60HDN1-M20G | HE37960 | BGH96M080B3B | 34,000 | $1,700 |
| No | 212361458 | ADP | BOVA-60HDN1-M20G | HE36960 | BGH96M080B3B | 34,000 | $1,700 |
| No | 212361457 | ADP | BOVA-60HDN1-M20G | HE35948 | BGH96M080B3B | 34,000 | $1,700 |
| No | 212361456 | ADP | BOVA-60HDN1-M20G | HE48960 | BGH96M080B3A | 34,000 | $1,700 |
| No | 212361455 | ADP | BOVA-60HDN1-M20G | HE37960 | BGH96M080B3A | 34,000 | $1,700 |
| No | 212361454 | ADP | BOVA-60HDN1-M20G | HE36960 | BGH96M080B3A | 34,000 | $1,700 |
| No | 212361453 | ADP | BOVA-60HDN1-M20G | HE35948 | BGH96M080B3A | 34,000 | $1,700 |
| No | 212361452 | ADP | BOVA-36HDN1-M20G | HE33936 | BGH96M080B3B | 19,000 | $950 |
| No | 212361451 | ADP | BOVA-36HDN1-M20G | HE32936 | BGH96M080B3B | 19,000 | $950 |
| No | 212361450 | ADP | BOVA-36HDN1-M20G | HE31930 | BGH96M080B3B | 19,000 | $950 |
| No | 212361449 | ADP | BOVA-36HDN1-M20G | HE33936 | BGH96M080B3A | 19,000 | $950 |
| No | 212361448 | ADP | BOVA-36HDN1-M20G | HE32936 | BGH96M080B3A | 19,000 | $950 |
| No | 212361447 | ADP | BOVA-36HDN1-M20G | HE31930 | BGH96M080B3A | 19,000 | $950 |
| No | 212361446 | ADP | BOVA-36HDN1-M20G | HE33936 | BGH96M060B3B | 19,000 | $950 |
| No | 212361445 | ADP | BOVA-36HDN1-M20G | HE32936 | BGH96M060B3B | 19,000 | $950 |
| No | 212361444 | ADP | BOVA-36HDN1-M20G | HE31930 | BGH96M060B3B | 19,000 | $950 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 212361443 | ADP | BOVA-36HDN1-M20G | HE33936 | BGH96M060B3A | 19,000 | $950 |
| No | 212361442 | ADP | BOVA-36HDN1-M20G | HE32936 | BGH96M060B3A | 19,000 | $950 |
| No | 212361441 | ADP | BOVA-36HDN1-M20G | HE31930 | BGH96M060B3A | 19,000 | $950 |
| No | 212407346 | ADP | HMH72B601 | F,PE*CC4960 | | 35,400 | $1,770 |
| No | 212407345 | ADP | HMH72B481 | F,PE*CC4960 | | 28,800 | $1,440 |
| No | 212407344 | ADP | HMH72B481 | F,PE*CC3948 | | 28,800 | $1,440 |
| No | 211708560 | ADP | HMH72B361 | F,PE*E34936 | | 23,000 | $1,150 |
| No | 212407348 | ADP | HMH72B361 | F,PE*E32936 | | 23,600 | $1,180 |
| No | 212407347 | ADP | HMH72B361 | F,PE*CC3937 | | 23,600 | $1,180 |
| No | 212407343 | ADP | HMH72B341 | F,PE*E34936 | | 24,400 | $1,220 |
| No | 212407342 | ADP | HMH72B341 | F,PE*E32936 | | 23,600 | $1,180 |
| No | 212407341 | ADP | HMH72B241 | F,PE*E31930 | | 14,000 | $700 |
| No | 212400331 | ADP | 4HP18V36P | H,A,DE32936 | 96G1UH070BE12 | 20,800 | $1,040 |
| No | 211001337 | ADP | 4SHP18LX136P | H,A,DE35936 | A96UH2E045B12 | 14,900 | $745 |
| No | 211001324 | ADP | 4SHP18LX136P | H,A,DE35936 | A96UH1E070B12 | 14,900 | $745 |
| No | 211001272 | ADP | 4SHP18LX136P | H,A,DE35936 | A93UH1E070B12 | 14,000 | $700 |
| No | 211001266 | ADP | 4SHP18LX136P | H,A,DE33936 | A93UH1E070B12 | 14,300 | $715 |
| No | 211001262 | ADP | 4SHP18LX136P | H,A,DE35936 | A93UH1E045B12 | 14,000 | $700 |
| No | 211001256 | ADP | 4SHP18LX136P | H,A,DE33936 | A93UH1E045B12 | 13,800 | $690 |
| No | 211912050 | ADP | 38MURAQ24AA3* | CDP23H13P+TXV | 59SC5B080E21**20 | 19,400 | $970 |
| No | 211912047 | ADP | 38MURAQ24AA3* | CDP35H15P+TXV | 59SC5B080E21**20 | 19,400 | $970 |
| No | 211912042 | ADP | 38MURAQ24AA3* | CDP29H15P+TXV | 59SC5B080E21**20 | 19,400 | $970 |
| No | 211912038 | ADP | 38MURAQ24AA3* | CDP35H15P+TXV | 59SC5B060E17**14 | 19,600 | $980 |
| No | 211912035 | ADP | 38MURAQ24AA3* | CDP29H15P+TXV | 59SC5B060E17**14 | 19,600 | $980 |
| No | 211912031 | ADP | 38MURAQ24AA3* | CDP35H15P+TXV | 59SC2D100E21**20 | 19,600 | $980 |
| No | 211912027 | ADP | 38MURAQ24AA3* | CDP29H15P+TXV | 59SC2D100E21**20 | 19,600 | $980 |
| No | 211912023 | ADP | 38MURAQ24AA3* | CDP35H15P+TXV | 59SC2D080E21**20 | 19,600 | $980 |
| No | 211912019 | ADP | 38MURAQ24AA3* | CDP29H15P+TXV | 59SC2D080E21**20 | 19,600 | $980 |
| No | 211912016 | ADP | 38MURAQ24AA3* | CDP23H13P+TXV | 59SC2D060E14**12 | 19,600 | $980 |
| No | 211902856 | ADP | 38MURAQ24AA3* | CDP23A13P+TXV | 59SC5B080E21**20 | 19,400 | $970 |
| No | 211902855 | ADP | 38MURAQ24AA3* | CDP35A15P+TXV | 59SC5B080E21**20 | 19,400 | $970 |
| No | 211902854 | ADP | 38MURAQ24AA3* | CDP29A15P+TXV | 59SC5B080E21**20 | 19,400 | $970 |
| No | 211902853 | ADP | 38MURAQ24AA3* | CDP35A15P+TXV | 59SC5B060E17**14 | 19,600 | $980 |
| No | 211902852 | ADP | 38MURAQ24AA3* | CDP29A15P+TXV | 59SC5B060E17**14 | 19,600 | $980 |
| No | 211902851 | ADP | 38MURAQ24AA3* | CDP35A15P+TXV | 59SC2D100E21**20 | 19,600 | $980 |
| No | 211902850 | ADP | 38MURAQ24AA3* | CDP29A15P+TXV | 59SC2D100E21**20 | 19,600 | $980 |
| No | 211902849 | ADP | 38MURAQ24AA3* | CDP35A15P+TXV | 59SC2D080E21**20 | 19,600 | $980 |
| No | 211902848 | ADP | 38MURAQ24AA3* | CDP29A15P+TXV | 59SC2D080E21**20 | 19,600 | $980 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211902847 | ADP | 38MURAQ24AA3* | CDP23A13P+TXV | 59SC2D060E14**12 | 19,600 | $980 |
| No | 211871818 | ADP | 38MURAQ24AA3* | H,PE31(1,2)24+TXV | 59SC5B080E21**20 | 19,400 | $970 |
| No | 211871808 | ADP | 38MURAQ24AA3* | H,PE31(1,2)24+TXV | 59SC5B060E17**14 | 19,600 | $980 |
| No | 211871800 | ADP | 38MURAQ24AA3* | H,PE31(1,2)24+TXV | 59SC2D100E21**20 | 19,600 | $980 |
| No | 211871794 | ADP | 38MURAQ24AA3* | H,PE31(1,2)24+TXV | 59SC2D080E21**20 | 19,600 | $980 |
| No | 211871512 | ADP | 38MURAQ24AA3* | H,PE30(1,2)24+TXV | 59SC5B080E21**20 | 19,400 | $970 |
| No | 211871511 | ADP | 38MURAQ24AA3* | H,PE33(1,2)36+TXV | 59SC5B080E21**20 | 19,400 | $970 |
| No | 211871510 | ADP | 38MURAQ24AA3* | H,PE32(1,2)36+TXV | 59SC5B080E21**20 | 19,400 | $970 |
| No | 211871509 | ADP | 38MURAQ24AA3* | H,PE31(1,2)30+TXV | 59SC5B080E21**20 | 19,400 | $970 |
| No | 211871503 | ADP | 38MURAQ24AA3* | H,PE33(1,2)36+TXV | 59SC5B060E17**14 | 19,600 | $980 |
| No | 211871502 | ADP | 38MURAQ24AA3* | H,PE32(1,2)36+TXV | 59SC5B060E17**14 | 19,600 | $980 |
| No | 211871501 | ADP | 38MURAQ24AA3* | H,PE31(1,2)30+TXV | 59SC5B060E17**14 | 19,600 | $980 |
| No | 211871500 | ADP | 38MURAQ24AA3* | H,PE33(1,2)36+TXV | 59SC2D100E21**20 | 19,600 | $980 |
| No | 211871499 | ADP | 38MURAQ24AA3* | H,PE32(1,2)36+TXV | 59SC2D100E21**20 | 19,600 | $980 |
| No | 211871498 | ADP | 38MURAQ24AA3* | H,PE31(1,2)30+TXV | 59SC2D100E21**20 | 19,600 | $980 |
| No | 211871497 | ADP | 38MURAQ24AA3* | H,PE33(1,2)36+TXV | 59SC2D080E21**20 | 19,600 | $980 |
| No | 211871496 | ADP | 38MURAQ24AA3* | H,PE32(1,2)36+TXV | 59SC2D080E21**20 | 19,600 | $980 |
| No | 211871495 | ADP | 38MURAQ24AA3* | H,PE31(1,2)30+TXV | 59SC2D080E21**20 | 19,600 | $980 |
| No | 211871494 | ADP | 38MURAQ24AA3* | H,PE30(1,2)24+TXV | 59SC2D060E14**12 | 19,600 | $980 |
| No | 212391612 | ADP | DLCURAH24AAK | H,GE30(1,2)24+TXV | *95ESN0802120A* | 19,400 | $970 |
| No | 212391611 | ADP | DLCURAH24AAK | H,GE33(1,2)36+TXV | *95ESN0802120A* | 19,400 | $970 |
| No | 212391610 | ADP | DLCURAH24AAK | H,GE32(1,2)36+TXV | *95ESN0802120A* | 19,400 | $970 |
| No | 212391609 | ADP | DLCURAH24AAK | H,GE31(1,2)30+TXV | *95ESN0802120A* | 19,400 | $970 |
| No | 212391608 | ADP | DLCURAH24AAK | H,GE31(1,2)24+TXV | *95ESN0802120A* | 19,400 | $970 |
| No | 212391607 | ADP | DLCURAH24AAK | H,GE33(1,2)36+TXV | *95ESN0601714A* | 19,600 | $980 |
| No | 212391606 | ADP | DLCURAH24AAK | H,GE32(1,2)36+TXV | *95ESN0601714A* | 19,600 | $980 |
| No | 212391605 | ADP | DLCURAH24AAK | H,GE31(1,2)30+TXV | *95ESN0601714A* | 19,600 | $980 |
| No | 212391604 | ADP | DLCURAH24AAK | H,GE31(1,2)24+TXV | *95ESN0601714A* | 19,600 | $980 |
| No | 212391603 | ADP | DLCURAH24AAK | H,GE33(1,2)36+TXV | *92ESN1002120A* | 19,600 | $980 |
| No | 212391602 | ADP | DLCURAH24AAK | H,GE32(1,2)36+TXV | *92ESN1002120A* | 19,600 | $980 |
| No | 212391601 | ADP | DLCURAH24AAK | H,GE31(1,2)30+TXV | *92ESN1002120A* | 19,600 | $980 |
| No | 212391600 | ADP | DLCURAH24AAK | H,GE31(1,2)24+TXV | *92ESN1002120A* | 19,600 | $980 |
| No | 212391599 | ADP | DLCURAH24AAK | H,GE33(1,2)36+TXV | *92ESN0802120A* | 19,600 | $980 |
| No | 212391598 | ADP | DLCURAH24AAK | H,GE32(1,2)36+TXV | *92ESN0802120A* | 19,600 | $980 |
| No | 212391597 | ADP | DLCURAH24AAK | H,GE31(1,2)30+TXV | *92ESN0802120A* | 19,600 | $980 |
| No | 212391596 | ADP | DLCURAH24AAK | H,GE31(1,2)24+TXV | *92ESN0802120A* | 19,600 | $980 |
| No | 212391595 | ADP | DLCURAH24AAK | H,GE30(1,2)24+TXV | *92ESN0601412A* | 19,600 | $980 |
| No | 211780606 | ADP | DLCURAH24AAK | H,GE30924 | *95ESN0802120A* | 19,400 | $970 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211780605 | ADP | DLCURAH24AAK | H,GE35936 | *95ESN0802120A* | 19,400 | $970 |
| No | 211780604 | ADP | DLCURAH24AAK | H,GE34936 | *95ESN0802120A* | 19,400 | $970 |
| No | 211780603 | ADP | DLCURAH24AAK | H,GE33936 | *95ESN0802120A* | 19,400 | $970 |
| No | 211780602 | ADP | DLCURAH24AAK | H,GE32936 | *95ESN0802120A* | 19,400 | $970 |
| No | 211780601 | ADP | DLCURAH24AAK | H,GE31930 | *95ESN0802120A* | 19,400 | $970 |
| No | 211780593 | ADP | DLCURAH24AAK | H,GE35936 | *95ESN0601714A* | 19,600 | $980 |
| No | 211780592 | ADP | DLCURAH24AAK | H,GE34936 | *95ESN0601714A* | 19,600 | $980 |
| No | 211780591 | ADP | DLCURAH24AAK | H,GE33936 | *95ESN0601714A* | 19,600 | $980 |
| No | 211780590 | ADP | DLCURAH24AAK | H,GE32936 | *95ESN0601714A* | 19,600 | $980 |
| No | 211780589 | ADP | DLCURAH24AAK | H,GE31930 | *95ESN0601714A* | 19,600 | $980 |
| No | 211780588 | ADP | DLCURAH24AAK | H,GE35936 | *92ESN1002120A* | 19,600 | $980 |
| No | 211780587 | ADP | DLCURAH24AAK | H,GE34936 | *92ESN1002120A* | 19,600 | $980 |
| No | 211780586 | ADP | DLCURAH24AAK | H,GE33936 | *92ESN1002120A* | 19,600 | $980 |
| No | 211780585 | ADP | DLCURAH24AAK | H,GE32936 | *92ESN1002120A* | 19,600 | $980 |
| No | 211780584 | ADP | DLCURAH24AAK | H,GE31930 | *92ESN1002120A* | 19,600 | $980 |
| No | 211780583 | ADP | DLCURAH24AAK | H,GE35936 | *92ESN0802120A* | 19,600 | $980 |
| No | 211780582 | ADP | DLCURAH24AAK | H,GE34936 | *92ESN0802120A* | 19,600 | $980 |
| No | 211780581 | ADP | DLCURAH24AAK | H,GE33936 | *92ESN0802120A* | 19,600 | $980 |
| No | 211780580 | ADP | DLCURAH24AAK | H,GE32936 | *92ESN0802120A* | 19,600 | $980 |
| No | 211780579 | ADP | DLCURAH24AAK | H,GE31930 | *92ESN0802120A* | 19,600 | $980 |
| No | 211780578 | ADP | DLCURAH24AAK | H,GE30924 | *92ESN0601412A* | 19,600 | $980 |
| No | 208674957 | AIC TECHNOLOGIES | NAKS-MULTI AC-27K-208-230 | Heat pump with ducts | | 22,000 | $1,100 |
| No | 208674955 | AIC TECHNOLOGIES | NAKS-MULTI AC-18K-208-230 | Heat pump with ducts | | 14,800 | $740 |
| No | 208674967 | AIC TECHNOLOGIES | NAKS-SPLIT AC-18K-ODU-208-230 | NAKS-SPLIT AC-18K-IDU-208-230 | | 14,100 | $705 |
| No | 208674965 | AIC TECHNOLOGIES | NAKS-SPLIT AC-9K-ODU-208-230 | NAKS-SPLIT AC-9K-IDU-208-230 | | 8,100 | $405 |
| No | 208674963 | AIC TECHNOLOGIES | NAKS-SPLIT AC-9K-ODU-115 | NAKS-SPLIT AC-9K-IDU-115 | | 5,900 | $295 |
| No | 208674968 | AIC TECHNOLOGIES | NAKS-SPLIT AC-24K-ODU-208-230 | NAKS-SPLIT AC-24K-IDU-208-230 | | 17,400 | $870 |
| No | 208674966 | AIC TECHNOLOGIES | NAKS-SPLIT AC-12K-ODU-208-230 | NAKS-SPLIT AC-12K-IDU-208-230 | | 10,000 | $500 |
| No | 208674964 | AIC TECHNOLOGIES | NAKS-SPLIT AC-12K-ODU-115 | NAKS-SPLIT AC-12K-IDU-115 | | 8,900 | $445 |
| No | 208674962 | AIC TECHNOLOGIES | NAKS-MULTI AC-48K-208-230 | Combination heat pumps with or without ducts | | 30,600 | $1,530 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208674961 | AIC TECHNOLOGIES | NAKS-MULTI AC-48K-208-230 | Heat pump with ducts | | 30,400 | $1,520 |
| No | 208674958 | AIC TECHNOLOGIES | NAKS-MULTI AC-27K-208-230 | Combination heat pumps with or without ducts | | 16,100 | $805 |
| No | 208674956 | AIC TECHNOLOGIES | NAKS-MULTI AC-18K-208-230 | Combination heat pumps with or without ducts | | 11,800 | $590 |
| No | 208674970 | AIC TECHNOLOGIES | NAKS-SPLIT AC-36K-ODU-208-230 | NAKS-SPLIT AC-36K-IDU-208-230 | | 20,000 | $1,000 |
| No | 209948204 | AIRDACH | ACSH2421VM2-D | AIWH2400VM2-D | | 18,000 | $900 |
| No | 210474677 | AIRDACH | AMSH3600VM1-D | Heat pump without ducts | | 26,400 | $1,320 |
| No | 210474674 | AIRDACH | AMSH2700VM1-D | Heat pump without ducts | | 20,000 | $1,000 |
| No | 210474675 | AIRDACH | AMSH2700VM1-D | Heat pump with ducts | | 22,000 | $1,100 |
| No | 210474672 | AIRDACH | AMSH1800VM1-D | Heat pump with ducts | | 14,800 | $740 |
| No | 210474680 | AIRDACH | AMSH4800VM1-D | Heat pump without ducts | | 36,000 | $1,800 |
| No | 210474671 | AIRDACH | AMSH1800VM1-D | Heat pump without ducts | | 14,400 | $720 |
| No | 210476737 | AIRDACH | ACSH1823VM2-D | AICH1800VM1-D | | 12,000 | $600 |
| No | 209948209 | AIRDACH | ACSH1222VM2-D | AIWH1200VM2-D | | 8,200 | $410 |
| No | 209948205 | AIRDACH | ACSH0924VM2-D | AIWH0900VM2-D | | 8,300 | $415 |
| No | 209948207 | AIRDACH | ACSH1823VM2-D | AIWH1800VM2-D | | 14,000 | $700 |
| No | 209948208 | AIRDACH | ACSH0920VM2-A | AIWH0900VM2-A | | 6,800 | $340 |
| No | 209948203 | AIRDACH | ACSH3618VM2-D | AIWH3600VM2-D | | 24,000 | $1,200 |
| No | 210476736 | AIRDACH | ACSH1222VM2-D | AICH1200VM1-D | | 8,900 | $445 |
| No | 211034488 | AirEase | 4DHV2S12S-1L | DWH212S4-*L | | 7,800 | $390 |
| No | 211034487 | AirEase | 4DHV2S09S-1L | DWH209S4-*L | | 6,300 | $315 |
| No | 211034467 | AirEase | 4DHP2S12S-1L | DWM212S4-*L | | 8,400 | $420 |
| No | 211034492 | AirEase | 4DHV2S24S-1P | DWH224S4-*P | | 16,500 | $825 |
| No | 211034491 | AirEase | 4DHV2S18S-1P | DWH218S4-*P | | 11,400 | $570 |
| No | 211034490 | AirEase | 4DHV2S12S-1P | DWH212S4-*P | | 7,000 | $350 |
| No | 211034489 | AirEase | 4DHV2S09S-1P | DWH209S4-*P | | 6,000 | $300 |
| No | 211034486 | AirEase | 4DHP2S48S-1P | D33C248S4-*P | | 30,000 | $1,500 |
| No | 211034485 | AirEase | 4DHP2S36S-1P | D33C236S4-*P | | 23,000 | $1,150 |
| No | 211034484 | AirEase | 4DHP2S24S-1P | D33C224S4-*P | | 19,000 | $950 |
| No | 211034483 | AirEase | 4DHP2S18S-1P | D22C118S4-*P | | 12,000 | $600 |
| No | 211034482 | AirEase | 4DHP2S12S-1P | D22C112S4-*P | | 8,900 | $445 |
| No | 211034481 | AirEase | 4DHPS209S-1P | D22C109S4-*P | | 7,500 | $375 |
| No | 211034480 | AirEase | 4DHP2S48S-1P | DMD248S4-*P | | 34,000 | $1,700 |
| No | 211034479 | AirEase | 4DHP2S36S-1P | DMD236S4-*P | | 25,000 | $1,250 |
| No | 211034478 | AirEase | 4DHP2S24S-1P | DMD224S4-*P | | 20,000 | $1,000 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211034477 | AirEase | 4DHP2S18S-1P | DMD218S4-*P | | 12,600 | $630 |
| No | 211034476 | AirEase | 4DHP2S12S-1P | DMD212S4-*P | | 9,300 | $465 |
| No | 211034475 | AirEase | 4DHPS209S-1P | DMD209S4-*P | | 7,700 | $385 |
| No | 211034472 | AirEase | 4DHP2S30S-1P | DWM230S4-*P | | 19,000 | $950 |
| No | 211034471 | AirEase | 4DHP2S24S-1P | DWM224S4-*P | | 16,200 | $810 |
| No | 211034470 | AirEase | 4DHP2S18S-1P | DWM218S4-*P | | 14,900 | $745 |
| No | 211034469 | AirEase | 4DHP2S12S-1P | DWM212S4-*P | | 9,000 | $450 |
| No | 211034468 | AirEase | 4DHPS209S-1P | DWM209S4-*P | | 8,500 | $425 |
| No | 208106734 | AIREASE | 4DHV2S24S-1P | DWH224S4-1P | | 16,500 | $825 |
| No | 208106733 | AIREASE | 4DHV2S18S-1P | DWH218S4-1P | | 11,400 | $570 |
| No | 208106732 | AIREASE | 4DHV2S12S-1P | DWH212S4-1P | | 7,000 | $350 |
| No | 208106730 | AIREASE | 4DHV2S12S-1L | DWH212S4-1L | | 7,800 | $390 |
| No | 208106731 | AIREASE | 4DHV2S09S-1P | DWH209S4-1P | | 6,000 | $300 |
| No | 208106729 | AIREASE | 4DHV2S09S-1L | DWH209S4-1L | | 6,300 | $315 |
| No | 208106725 | AIREASE | 4DHPS209S-1P | DWM209S4-1P | | 8,500 | $425 |
| No | 208106717 | AIREASE | 4DHPS209S-1P | DMD209S4-1P | | 7,700 | $385 |
| No | 208106716 | AIREASE | 4DHPS209S-1P | D22C109S4-1P | | 7,500 | $375 |
| No | 208106806 | AIREASE | 4DHP2S36M-1P | Heat pump without ducts | | 26,800 | $1,340 |
| No | 208106803 | AIREASE | 4DHP2S30M-1P | Heat pump without ducts | | 21,000 | $1,050 |
| No | 208106804 | AIREASE | 4DHP2S30M-1P | Heat pump with ducts | | 22,000 | $1,100 |
| No | 208106683 | AIREASE | 4DHP2S24S-1P | DWM224S4-1P | | 16,200 | $810 |
| No | 208106801 | AIREASE | 4DHP2S24M-1P | Heat pump with ducts | | 21,600 | $1,080 |
| No | 208106800 | AIREASE | 4DHP2S24M-1P | Heat pump without ducts | | 20,400 | $1,020 |
| No | 208106688 | AIREASE | 4DHP2S18S-1P | DMD218S4-1P | | 12,600 | $630 |
| No | 208106682 | AIREASE | 4DHP2S18S-1P | DWM218S4-1P | | 14,900 | $745 |
| No | 208106798 | AIREASE | 4DHP2S18M-1P | Heat pump with ducts | | 14,800 | $740 |
| No | 208106797 | AIREASE | 4DHP2S18M-1P | Heat pump without ducts | | 14,300 | $715 |
| No | 208106681 | AIREASE | 4DHP2S12S-1P | DWM212S4-1P | | 9,000 | $450 |
| No | 208106687 | AIREASE | 4DHP2S12S-1P | DMD212S4-1P | | 9,300 | $465 |
| No | 208106724 | AIREASE | 4DHP2S12S-1L | DWM212S4-1L | | 8,400 | $420 |
| No | 211729604 | AIREASE | 4SHP22LX124P-**A | BCE5E30M | | 14,500 | $725 |
| No | 211729603 | AIREASE | 4SHP22LX124P-**A | BCE5E24M | | 15,000 | $750 |
| No | 211708569 | AIREASE | 4SHP22LX136P-**A | BCE5E42M | | 22,200 | $1,110 |
| No | 211708568 | AIREASE | 4SHP22LX136P-**A | BCE5E36M | | 21,800 | $1,090 |
| No | 211708566 | AIREASE | 4SHP22LX136P-**A | BCE7S36M*4X | | 22,800 | $1,140 |
| No | 211699898 | AIREASE | 4SHP22LX148P-**A | BCE7S60M*4X | | 27,200 | $1,360 |
| No | 211727078 | AIREASE | 4SHP22LX160P-**A | BCE5E60M | | 36,800 | $1,840 |
| No | 211727076 | AIREASE | 4SHP22LX160P-**A | BCE7S60M*4X | | 37,000 | $1,850 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210822152 | AIREASE | 4SHP18LX160P | BCE7E48M*4X | | 32,200 | $1,610 |
| No | 210822245 | AIREASE | 4SHP18LX160P | EAC4X49C+TDR | A97USMV110C20 | 30,800 | $1,540 |
| No | 210822243 | AIREASE | 4SHP18LX160P | EAC4X49C+TDR | A97USMV090C20 | 30,800 | $1,540 |
| No | 210822242 | AIREASE | 4SHP18LX160P | EAC4X49C+TDR | A97USMV090C16 | 30,800 | $1,540 |
| No | 210822241 | AIREASE | 4SHP18LX160P | EAC4X49C+TDR | A97US2V080C20X | 30,600 | $1,530 |
| No | 210822239 | AIREASE | 4SHP18LX160P | EAC4X49C+TDR | A97US2V080C16X | 30,600 | $1,530 |
| No | 210822229 | AIREASE | 4SHP18LX160P | EAC4X49C+TDR | A80US2V110C20L | 30,600 | $1,530 |
| No | 210822226 | AIREASE | 4SHP18LX160P | EAC4X49C+TDR | A80US2V100C20X | 30,200 | $1,510 |
| No | 210822225 | AIREASE | 4SHP18LX160P | EAC4X49C+TDR | A80US2V080C20X | 30,400 | $1,520 |
| No | 210822237 | AIREASE | 4SHP18LX160P | EAC4X49C+TDR | A96US2V110C16 | 30,600 | $1,530 |
| No | 210822235 | AIREASE | 4SHP18LX160P | EAC4X49C+TDR | A96US2V090C16 | 30,800 | $1,540 |
| No | 210822238 | AIREASE | 4SHP18LX160P | EAC4X49C+TDR | A96US2V110C20 | 30,800 | $1,540 |
| No | 210822232 | AIREASE | 4SHP18LX160P | EAC4X49C+TDR | A96UH2E110C20 | 30,600 | $1,530 |
| No | 210822236 | AIREASE | 4SHP18LX160P | EAC4X49C+TDR | A96US2V090C20 | 30,800 | $1,540 |
| No | 210822231 | AIREASE | 4SHP18LX160P | EAC4X49C+TDR | A96UH1E110C20 | 30,600 | $1,530 |
| No | 210822230 | AIREASE | 4SHP18LX160P | EAC4X49C+TDR | A93UH1E110C20 | 30,400 | $1,520 |
| No | 210822228 | AIREASE | 4SHP18LX160P | EAC4X49C+TDR | A80US2V110C20 | 30,600 | $1,530 |
| No | 210822224 | AIREASE | 4SHP18LX160P | EAC4X49C+TDR | A80UH2E110C20 | 30,400 | $1,520 |
| No | 210822223 | AIREASE | 4SHP18LX160P | EAC4X49C+TDR | A80UH1E110C20 | 30,400 | $1,520 |
| No | 210822222 | AIREASE | 4SHP18LX160P | EAC4X49C+TDR | A80UH1E100C20X | 30,600 | $1,530 |
| No | 210822221 | AIREASE | 4SHP18LX160P | EAC4X49C+TDR | A80UH1E090C20 | 30,200 | $1,510 |
| No | 210822210 | AIREASE | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A97USMV110C20 | 30,800 | $1,540 |
| No | 210822209 | AIREASE | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A97USMV090C20 | 30,800 | $1,540 |
| No | 210822208 | AIREASE | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A97USMV090C16 | 30,800 | $1,540 |
| No | 210822207 | AIREASE | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A97US2V080C20X | 30,600 | $1,530 |
| No | 210822205 | AIREASE | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A97US2V080C16X | 30,600 | $1,530 |
| No | 210822189 | AIREASE | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A80US2V110C20L | 30,600 | $1,530 |
| No | 210822185 | AIREASE | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A80US2V100C20X | 30,200 | $1,510 |
| No | 210822183 | AIREASE | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A80US2V080C20X | 30,400 | $1,520 |
| No | 210822200 | AIREASE | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A96US2V110C16 | 30,600 | $1,530 |
| No | 210822195 | AIREASE | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A96US2V090C16 | 30,800 | $1,540 |
| No | 210822203 | AIREASE | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A96US2V110C20 | 30,800 | $1,540 |
| No | 210822194 | AIREASE | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A96UH2E110C20 | 30,600 | $1,530 |
| No | 210822198 | AIREASE | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A96US2V090C20 | 30,800 | $1,540 |
| No | 210822192 | AIREASE | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A96UH1E110C20 | 30,600 | $1,530 |
| No | 210822191 | AIREASE | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A93UH1E110C20 | 30,400 | $1,520 |
| No | 210822187 | AIREASE | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A80US2V110C20 | 30,600 | $1,530 |
| No | 210822182 | AIREASE | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A80UH2E110C20 | 30,400 | $1,520 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210822180 | AIREASE | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A80UH1E110C20 | 30,400 | $1,520 |
| No | 210822178 | AIREASE | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A80UH1E100C20X | 30,600 | $1,530 |
| No | 210822176 | AIREASE | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A80UH1E090C20 | 30,200 | $1,510 |
| No | 210822273 | AIREASE | 4SHP18LX160P | EAH1P48C+TDR+TXV | A97USMV110C20 | 31,400 | $1,570 |
| No | 210822272 | AIREASE | 4SHP18LX160P | EAH1P48C+TDR+TXV | A97USMV090C20 | 31,400 | $1,570 |
| No | 210822271 | AIREASE | 4SHP18LX160P | EAH1P48C+TDR+TXV | A97USMV090C16 | 31,400 | $1,570 |
| No | 210822268 | AIREASE | 4SHP18LX160P | EAH1P48C+TDR+TXV | A97US2V080C20X | 31,200 | $1,560 |
| No | 210822267 | AIREASE | 4SHP18LX160P | EAH1P48C+TDR+TXV | A97US2V080C16X | 31,200 | $1,560 |
| No | 210822257 | AIREASE | 4SHP18LX160P | EAH1P48C+TDR+TXV | A80US2V110C20L | 31,200 | $1,560 |
| No | 210822265 | AIREASE | 4SHP18LX160P | EAH1P48C+TDR+TXV | A96US2V110C16 | 31,400 | $1,570 |
| No | 210822262 | AIREASE | 4SHP18LX160P | EAH1P48C+TDR+TXV | A96US2V090C16 | 31,400 | $1,570 |
| No | 210822266 | AIREASE | 4SHP18LX160P | EAH1P48C+TDR+TXV | A96US2V110C20 | 31,400 | $1,570 |
| No | 210822263 | AIREASE | 4SHP18LX160P | EAH1P48C+TDR+TXV | A96US2V090C20 | 31,400 | $1,570 |
| No | 210822255 | AIREASE | 4SHP18LX160P | EAH1P48C+TDR+TXV | A80US2V110C20 | 31,200 | $1,560 |
| No | 210822254 | AIREASE | 4SHP18LX160P | EAH1P48C+TDR+TXV | A80UH2E110C20 | 31,000 | $1,550 |
| No | 210822149 | AIREASE | 4SHP18LX160P | BCE5V48M | | 31,400 | $1,570 |
| No | 210822147 | AIREASE | 4SHP18LX160P | BCE5E48M*4X | | 31,600 | $1,580 |
| No | 210822144 | AIREASE | 4SHP18LX160P | BCE5C48M*4X | | 31,600 | $1,580 |
| No | 210822140 | AIREASE | 4SHP18LX160P | BCE5C48M*1P+TXV | | 31,600 | $1,580 |
| No | 210822154 | AIREASE | 4SHP18LX160P | BCE7S48 | | 32,800 | $1,640 |
| No | 210821444 | AIREASE | 4SHP18LX160P | ED1P60D+TDR+TXV | A97DSMV110C20 | 38,500 | $1,925 |
| No | 210821442 | AIREASE | 4SHP18LX160P | ED1P60D+TDR+TXV | A97DSMV090C20 | 38,500 | $1,925 |
| No | 210821434 | AIREASE | 4SHP18LX160P | ED1P60D+TDR+TXV | A80DF1E110C20 | 38,000 | $1,900 |
| No | 210821439 | AIREASE | 4SHP18LX160P | ED1P60D+TDR+TXV | A96DS2V110C20 | 38,500 | $1,925 |
| No | 210821437 | AIREASE | 4SHP18LX160P | ED1P60D+TDR+TXV | A96DS2V090C20 | 38,500 | $1,925 |
| No | 210821404 | AIREASE | 4SHP18LX160P | EAC4X60D+TDR | EFV20DCA | 39,000 | $1,950 |
| No | 210821402 | AIREASE | 4SHP18LX160P | EAC4X60D+TDR | A97USMV135D20 | 39,000 | $1,950 |
| No | 210821399 | AIREASE | 4SHP18LX160P | EAC4X60D+TDR | A96US2V135D20 | 39,000 | $1,950 |
| No | 210821398 | AIREASE | 4SHP18LX160P | EAC4X60D+TDR | A80US2V135D20* | 39,000 | $1,950 |
| No | 210821397 | AIREASE | 4SHP18LX160P | EAC4X60D+TDR | A80UH1E135D20 | 39,000 | $1,950 |
| No | 210821372 | AIREASE | 4SHP18LX160P | EA(C;U)1P60D+TDR+TXV | EFV20DCA | 39,000 | $1,950 |
| No | 210821370 | AIREASE | 4SHP18LX160P | EA(C;U)1P60D+TDR+TXV | A97USMV135D20 | 39,000 | $1,950 |
| No | 210821369 | AIREASE | 4SHP18LX160P | EA(C;U)1P60D+TDR+TXV | A96US2V135D20 | 39,000 | $1,950 |
| No | 210821367 | AIREASE | 4SHP18LX160P | EA(C;U)1P60D+TDR+TXV | A80US2V135D20* | 39,000 | $1,950 |
| No | 210821365 | AIREASE | 4SHP18LX160P | EA(C;U)1P60D+TDR+TXV | A80UH1E135D20 | 39,000 | $1,950 |
| No | 210821395 | AIREASE | 4SHP18LX160P | EAC4X60C+TDR | A97USMV110C20 | 38,000 | $1,900 |
| No | 210821391 | AIREASE | 4SHP18LX160P | EAC4X60C+TDR | A97USMV090C20 | 38,000 | $1,900 |
| No | 210821389 | AIREASE | 4SHP18LX160P | EAC4X60C+TDR | A97US2V080C20X | 38,000 | $1,900 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210821388 | AIREASE | 4SHP18LX160P | EAC4X60C+TDR | A96US2V110C20 | 38,000 | $1,900 |
| No | 210821387 | AIREASE | 4SHP18LX160P | EAC4X60C+TDR | A96US2V090C20 | 38,000 | $1,900 |
| No | 210821385 | AIREASE | 4SHP18LX160P | EAC4X60C+TDR | A96UH2E110C20 | 37,800 | $1,890 |
| No | 210821384 | AIREASE | 4SHP18LX160P | EAC4X60C+TDR | A93UH1E110C20 | 37,800 | $1,890 |
| No | 210821382 | AIREASE | 4SHP18LX160P | EAC4X60C+TDR | A80US2V110C20L | 38,000 | $1,900 |
| No | 210821380 | AIREASE | 4SHP18LX160P | EAC4X60C+TDR | A80US2V110C20* | 38,000 | $1,900 |
| No | 210821378 | AIREASE | 4SHP18LX160P | EAC4X60C+TDR | A80US2V100C20X | 37,600 | $1,880 |
| No | 210821377 | AIREASE | 4SHP18LX160P | EAC4X60C+TDR | A80US2V090C20* | 37,800 | $1,890 |
| No | 210821374 | AIREASE | 4SHP18LX160P | EAC4X60C+TDR | A80US2V080C20X | 37,600 | $1,880 |
| No | 210821373 | AIREASE | 4SHP18LX160P | EAC4X60C+TDR | A80UH2E110C20 | 38,000 | $1,900 |
| No | 210821363 | AIREASE | 4SHP18LX160P | EA(C;U)1P60C+TDR+TXV | A97USMV110C20 | 38,000 | $1,900 |
| No | 210821361 | AIREASE | 4SHP18LX160P | EA(C;U)1P60C+TDR+TXV | A97USMV090C20 | 38,000 | $1,900 |
| No | 210821359 | AIREASE | 4SHP18LX160P | EA(C;U)1P60C+TDR+TXV | A97US2V080C20X | 38,000 | $1,900 |
| No | 210821357 | AIREASE | 4SHP18LX160P | EA(C;U)1P60C+TDR+TXV | A96US2V110C20 | 38,000 | $1,900 |
| No | 210821355 | AIREASE | 4SHP18LX160P | EA(C;U)1P60C+TDR+TXV | A96US2V090C20 | 38,000 | $1,900 |
| No | 210821353 | AIREASE | 4SHP18LX160P | EA(C;U)1P60C+TDR+TXV | A96UH2E110C20 | 37,800 | $1,890 |
| No | 210821351 | AIREASE | 4SHP18LX160P | EA(C;U)1P60C+TDR+TXV | A93UH1E110C20 | 37,800 | $1,890 |
| No | 210821349 | AIREASE | 4SHP18LX160P | EA(C;U)1P60C+TDR+TXV | A80US2V110C20L | 38,000 | $1,900 |
| No | 210821348 | AIREASE | 4SHP18LX160P | EA(C;U)1P60C+TDR+TXV | A80US2V110C20* | 38,000 | $1,900 |
| No | 210821346 | AIREASE | 4SHP18LX160P | EA(C;U)1P60C+TDR+TXV | A80US2V100C20X | 37,600 | $1,880 |
| No | 210821344 | AIREASE | 4SHP18LX160P | EA(C;U)1P60C+TDR+TXV | A80US2V090C20* | 37,800 | $1,890 |
| No | 210821343 | AIREASE | 4SHP18LX160P | EA(C;U)1P60C+TDR+TXV | A80US2V080C20X | 37,600 | $1,880 |
| No | 210821341 | AIREASE | 4SHP18LX160P | EA(C;U)1P60C+TDR+TXV | A80UH2E110C20 | 38,000 | $1,900 |
| No | 210821337 | AIREASE | 4SHP18LX160P | BCE5V60M | | 38,500 | $1,925 |
| No | 210821339 | AIREASE | 4SHP18LX160P | BCE7E60M - TXV | | 38,000 | $1,900 |
| No | 210821329 | AIREASE | 4SHP18LX160P | BCE7S60 - TXV | | 38,500 | $1,925 |
| No | 210822107 | AIREASE | 4SHP18LX136P | ED1P24B+TDR+TXV | A93DF1E070B12 | 15,600 | $780 |
| No | 210821910 | AIREASE | 4SHP18LX136P | E*1P23B+TDR+TXV | A96US2V045B12 | 15,100 | $755 |
| No | 210821914 | AIREASE | 4SHP18LX136P | E*1P23B+TDR+TXV | A97US2V060B12X | 15,100 | $755 |
| No | 210821913 | AIREASE | 4SHP18LX136P | E*1P23B+TDR+TXV | A97US2V040B12X | 15,100 | $755 |
| No | 210821911 | AIREASE | 4SHP18LX136P | E*1P23B+TDR+TXV | A96US2V070B12 | 15,000 | $750 |
| No | 210821917 | AIREASE | 4SHP18LX136P | E*1P23B+TDR+TXV | EFV12BCA | 15,200 | $760 |
| No | 210821916 | AIREASE | 4SHP18LX136P | E*1P23B+TDR+TXV | EFV08BCA | 15,300 | $765 |
| No | 210821908 | AIREASE | 4SHP18LX136P | E*1P23B+TDR+TXV | A96UH2E070B12 | 15,400 | $770 |
| No | 210821907 | AIREASE | 4SHP18LX136P | E*1P23B+TDR+TXV | A96UH2E045B12 | 15,400 | $770 |
| No | 210821905 | AIREASE | 4SHP18LX136P | E*1P23B+TDR+TXV | A93UH1E070B12 | 15,300 | $765 |
| No | 210821903 | AIREASE | 4SHP18LX136P | E*1P23B+TDR+TXV | A93UH1E045B12 | 15,400 | $770 |
| No | 210821901 | AIREASE | 4SHP18LX136P | E*1P23B+TDR+TXV | A93UH1E030B12 | 15,300 | $765 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210821899 | AIREASE | 4SHP18LX136P | E*1P23B+TDR+TXV | A80UH2E090B12 | 15,300 | $765 |
| No | 210821898 | AIREASE | 4SHP18LX136P | E*1P23B+TDR+TXV | A80UH1E070B12 | 15,000 | $750 |
| No | 210821896 | AIREASE | 4SHP18LX136P | E*1P23A+TDR+TXV | A80US2V060A12X | 15,000 | $750 |
| No | 210821893 | AIREASE | 4SHP18LX136P | E*1P23A+TDR+TXV | A80UH2E070A12 | 15,400 | $770 |
| No | 210821891 | AIREASE | 4SHP18LX136P | E*1P23A+TDR+TXV | A80UH2E045A12 | 14,900 | $745 |
| No | 210821890 | AIREASE | 4SHP18LX136P | E*1P23A+TDR+TXV | A80UH1E070A12 | 15,100 | $755 |
| No | 210821888 | AIREASE | 4SHP18LX136P | E*1P23A+TDR+TXV | A80UH1E060A12X | 15,300 | $765 |
| No | 210821887 | AIREASE | 4SHP18LX136P | E*1P23A+TDR+TXV | A80UH1E045A12 | 15,200 | $760 |
| No | 210821886 | AIREASE | 4SHP18LX136P | E*1P23A+TDR+TXV | A80UH1E040A12X | 15,300 | $765 |
| No | 210822104 | AIREASE | 4SHP18LX136P | EAH1P30B+TDR+TXV | EFV12BCA | 15,600 | $780 |
| No | 210822103 | AIREASE | 4SHP18LX136P | EAH1P30B+TDR+TXV | EFV08BCA | 15,700 | $785 |
| No | 210822101 | AIREASE | 4SHP18LX136P | EAH1P30B+TDR+TXV | A97US2V060B12X | 15,600 | $780 |
| No | 210822100 | AIREASE | 4SHP18LX136P | EAH1P30B+TDR+TXV | A97US2V040B12X | 15,600 | $780 |
| No | 210822098 | AIREASE | 4SHP18LX136P | EAH1P30B+TDR+TXV | A96US2V070B12 | 15,500 | $775 |
| No | 210822096 | AIREASE | 4SHP18LX136P | EAH1P30B+TDR+TXV | A96UH2E070B12 | 15,900 | $795 |
| No | 210822097 | AIREASE | 4SHP18LX136P | EAH1P30B+TDR+TXV | A96US2V045B12 | 15,600 | $780 |
| No | 210822095 | AIREASE | 4SHP18LX136P | EAH1P30B+TDR+TXV | A96UH2E045B12 | 15,900 | $795 |
| No | 210822093 | AIREASE | 4SHP18LX136P | EAH1P30B+TDR+TXV | A96UH1E070B12 | 15,900 | $795 |
| No | 210822092 | AIREASE | 4SHP18LX136P | EAH1P30B+TDR+TXV | A96UH1E030B12 | 15,800 | $790 |
| No | 210822090 | AIREASE | 4SHP18LX136P | EAH1P30B+TDR+TXV | A93UH1E070B12 | 15,800 | $790 |
| No | 210822089 | AIREASE | 4SHP18LX136P | EAH1P30B+TDR+TXV | A93UH1E045B12 | 15,900 | $795 |
| No | 210822087 | AIREASE | 4SHP18LX136P | EAH1P30B+TDR+TXV | A93UH1E030B12 | 15,800 | $790 |
| No | 210822086 | AIREASE | 4SHP18LX136P | EAH1P30B+TDR+TXV | A80UH2E090B12 | 15,800 | $790 |
| No | 210822085 | AIREASE | 4SHP18LX136P | EAH1P30B+TDR+TXV | A80UH1E070B12 | 15,500 | $775 |
| No | 210822081 | AIREASE | 4SHP18LX136P | EAH1P30A+TDR+TXV | A80UH2E070A12 | 15,800 | $790 |
| No | 210822080 | AIREASE | 4SHP18LX136P | EAH1P30A+TDR+TXV | A80UH2E045A12 | 15,400 | $770 |
| No | 210822078 | AIREASE | 4SHP18LX136P | EAH1P30A+TDR+TXV | A80UH1E070A12 | 15,500 | $775 |
| No | 210822073 | AIREASE | 4SHP18LX136P | EAH1P30A+TDR+TXV | A80UH1E060A12X | 15,700 | $785 |
| No | 210822071 | AIREASE | 4SHP18LX136P | EAH1P30A+TDR+TXV | A80UH1E045A12 | 15,700 | $785 |
| No | 210822069 | AIREASE | 4SHP18LX136P | EAH1P30A+TDR+TXV | A80UH1E040A12X | 15,700 | $785 |
| No | 210822068 | AIREASE | 4SHP18LX136P | EAC4X30B+TDR | EFV12BCA | 15,600 | $780 |
| No | 210822067 | AIREASE | 4SHP18LX136P | EAC4X30B+TDR | EFV08BCA | 15,900 | $795 |
| No | 210822065 | AIREASE | 4SHP18LX136P | EAC4X30B+TDR | A97US2V060B12X | 15,500 | $775 |
| No | 210822063 | AIREASE | 4SHP18LX136P | EAC4X30B+TDR | A97US2V040B12X | 15,500 | $775 |
| No | 210822062 | AIREASE | 4SHP18LX136P | EAC4X30B+TDR | A96US2V070B12 | 15,500 | $775 |
| No | 210822058 | AIREASE | 4SHP18LX136P | EAC4X30B+TDR | A96UH2E070B12 | 15,900 | $795 |
| No | 210822061 | AIREASE | 4SHP18LX136P | EAC4X30B+TDR | A96US2V045B12 | 15,600 | $780 |
| No | 210822056 | AIREASE | 4SHP18LX136P | EAC4X30B+TDR | A96UH2E045B12 | 15,900 | $795 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210822054 | AIREASE | 4SHP18LX136P | EAC4X30B+TDR | A96UH1E070B12 | 15,900 | $795 |
| No | 210822051 | AIREASE | 4SHP18LX136P | EAC4X30B+TDR | A93UH1E070B12 | 15,800 | $790 |
| No | 210822049 | AIREASE | 4SHP18LX136P | EAC4X30B+TDR | A93UH1E045B12 | 15,900 | $795 |
| No | 210822045 | AIREASE | 4SHP18LX136P | EAC4X30B+TDR | A80UH2E090B12 | 15,800 | $790 |
| No | 210822043 | AIREASE | 4SHP18LX136P | EAC4X30B+TDR | A80UH1E070B12 | 15,600 | $780 |
| No | 210822041 | AIREASE | 4SHP18LX136P | EAC4X30A+TDR | A80US2V060A12X | 15,400 | $770 |
| No | 210822040 | AIREASE | 4SHP18LX136P | EAC4X30A+TDR | A80UH2E070A12 | 15,800 | $790 |
| No | 210822037 | AIREASE | 4SHP18LX136P | EAC4X30A+TDR | A80UH2E045A12 | 15,800 | $790 |
| No | 210822036 | AIREASE | 4SHP18LX136P | EAC4X30A+TDR | A80UH1E070A12 | 15,600 | $780 |
| No | 210822034 | AIREASE | 4SHP18LX136P | EAC4X30A+TDR | A80UH1E060A12X | 15,800 | $790 |
| No | 210822032 | AIREASE | 4SHP18LX136P | EAC4X30A+TDR | A80UH1E045A12 | 15,700 | $785 |
| No | 210822031 | AIREASE | 4SHP18LX136P | EAC4X30A+TDR | A80UH1E040A12X | 15,800 | $790 |
| No | 210821996 | AIREASE | 4SHP18LX136P | EA(C;U)1P30B+TDR+TXV | EFV12BCA | 15,600 | $780 |
| No | 210821994 | AIREASE | 4SHP18LX136P | EA(C;U)1P30B+TDR+TXV | EFV08BCA | 15,900 | $795 |
| No | 210821993 | AIREASE | 4SHP18LX136P | EA(C;U)1P30B+TDR+TXV | A97US2V060B12X | 15,500 | $775 |
| No | 210821991 | AIREASE | 4SHP18LX136P | EA(C;U)1P30B+TDR+TXV | A97US2V040B12X | 15,500 | $775 |
| No | 210821989 | AIREASE | 4SHP18LX136P | EA(C;U)1P30B+TDR+TXV | A96US2V070B12 | 15,500 | $775 |
| No | 210821986 | AIREASE | 4SHP18LX136P | EA(C;U)1P30B+TDR+TXV | A96UH2E070B12 | 15,900 | $795 |
| No | 210821988 | AIREASE | 4SHP18LX136P | EA(C;U)1P30B+TDR+TXV | A96US2V045B12 | 15,600 | $780 |
| No | 210821983 | AIREASE | 4SHP18LX136P | EA(C;U)1P30B+TDR+TXV | A96UH2E045B12 | 15,900 | $795 |
| No | 210821982 | AIREASE | 4SHP18LX136P | EA(C;U)1P30B+TDR+TXV | A96UH1E070B12 | 15,900 | $795 |
| No | 210821979 | AIREASE | 4SHP18LX136P | EA(C;U)1P30B+TDR+TXV | A93UH1E070B12 | 15,800 | $790 |
| No | 210821977 | AIREASE | 4SHP18LX136P | EA(C;U)1P30B+TDR+TXV | A93UH1E045B12 | 15,900 | $795 |
| No | 210821974 | AIREASE | 4SHP18LX136P | EA(C;U)1P30B+TDR+TXV | A80UH2E090B12 | 15,800 | $790 |
| No | 210821972 | AIREASE | 4SHP18LX136P | EA(C;U)1P30B+TDR+TXV | A80UH1E070B12 | 15,600 | $780 |
| No | 210821970 | AIREASE | 4SHP18LX136P | EA(C;U)1P30A+TDR+TXV | A80US2V060A12X | 15,400 | $770 |
| No | 210821969 | AIREASE | 4SHP18LX136P | EA(C;U)1P30A+TDR+TXV | A80UH2E070A12 | 15,800 | $790 |
| No | 210821967 | AIREASE | 4SHP18LX136P | EA(C;U)1P30A+TDR+TXV | A80UH2E045A12 | 15,800 | $790 |
| No | 210821966 | AIREASE | 4SHP18LX136P | EA(C;U)1P30A+TDR+TXV | A80UH1E070A12 | 15,600 | $780 |
| No | 210821963 | AIREASE | 4SHP18LX136P | EA(C;U)1P30A+TDR+TXV | A80UH1E060A12X | 15,800 | $790 |
| No | 210821960 | AIREASE | 4SHP18LX136P | EA(C;U)1P30A+TDR+TXV | A80UH1E045A12 | 15,700 | $785 |
| No | 210821958 | AIREASE | 4SHP18LX136P | EA(C;U)1P30A+TDR+TXV | A80UH1E040A12X | 15,800 | $790 |
| No | 210821885 | AIREASE | 4SHP18LX136P | BCE7S30M*4X | | 16,000 | $800 |
| No | 210821881 | AIREASE | 4SHP18LX136P | BCE7E30M*4X | | 16,200 | $810 |
| No | 210821878 | AIREASE | 4SHP18LX136P | BCE7E18M*4X | | 15,400 | $770 |
| No | 210821877 | AIREASE | 4SHP18LX136P | BCE5V30M*4X | | 15,900 | $795 |
| No | 210821876 | AIREASE | 4SHP18LX136P | BCE5V24M*4X | | 16,100 | $805 |
| No | 210821875 | AIREASE | 4SHP18LX136P | BCE5V18M*4X | | 15,900 | $795 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210821874 | AIREASE | 4SHP18LX136P | BCE5E30M*4X | | 15,900 | $795 |
| No | 210821872 | AIREASE | 4SHP18LX136P | BCE5C24M*4X | | 16,100 | $805 |
| No | 210821870 | AIREASE | 4SHP18LX136P | BCE5C24M*1P+TXV | | 16,100 | $805 |
| No | 210821869 | AIREASE | 4SHP18LX136P | BCE5C18M*4X | | 15,400 | $770 |
| No | 210821868 | AIREASE | 4SHP18LX136P | BCE5C18M*1P+TXV | | 15,400 | $770 |
| No | 210821883 | AIREASE | 4SHP18LX136P | BCE7S24M*4X | | 15,200 | $760 |
| No | 210821460 | AIREASE | 4SHP18LX136P | BCE7E36M*4X | | 23,400 | $1,170 |
| No | 210821528 | AIREASE | 4SHP18LX136P | E*1P36C+TDR+TXV | EFV16CCA | 23,200 | $1,160 |
| No | 210821527 | AIREASE | 4SHP18LX136P | E*1P36C+TDR+TXV | A97USMV090C16 | 23,600 | $1,180 |
| No | 210821525 | AIREASE | 4SHP18LX136P | E*1P36C+TDR+TXV | A97USMV090C12 | 23,600 | $1,180 |
| No | 210821523 | AIREASE | 4SHP18LX136P | E*1P36C+TDR+TXV | A97US2V080C16X | 23,400 | $1,170 |
| No | 210821522 | AIREASE | 4SHP18LX136P | E*1P36C+TDR+TXV | A96US2V110C16 | 23,600 | $1,180 |
| No | 210821518 | AIREASE | 4SHP18LX136P | E*1P36C+TDR+TXV | A96US2V090C16 | 23,600 | $1,180 |
| No | 210821517 | AIREASE | 4SHP18LX136P | E*1P36C+TDR+TXV | A96US2V090C12 | 23,600 | $1,180 |
| No | 210821516 | AIREASE | 4SHP18LX136P | E*1P36C+TDR+TXV | A96UH2E090C16 | 23,400 | $1,170 |
| No | 210821514 | AIREASE | 4SHP18LX136P | E*1P36C+TDR+TXV | A96UH1E090C16 | 23,400 | $1,170 |
| No | 210821513 | AIREASE | 4SHP18LX136P | E*1P36C+TDR+TXV | A93UH1E110C16 | 23,200 | $1,160 |
| No | 210821511 | AIREASE | 4SHP18LX136P | E*1P36C+TDR+TXV | A93UH1E090C16 | 23,200 | $1,160 |
| No | 210821510 | AIREASE | 4SHP18LX136P | E*1P36C+TDR+TXV | A93UH1E090C12 | 23,400 | $1,170 |
| No | 210821508 | AIREASE | 4SHP18LX136P | E*1P36C+TDR+TXV | A80UH2E110C16 | 23,400 | $1,170 |
| No | 210821506 | AIREASE | 4SHP18LX136P | E*1P36B+TDR+TXV | EFV12BCA | 23,400 | $1,170 |
| No | 210821505 | AIREASE | 4SHP18LX136P | E*1P36B+TDR+TXV | A97US2V060B12X | 23,800 | $1,190 |
| No | 210821504 | AIREASE | 4SHP18LX136P | E*1P36B+TDR+TXV | A97US2V040B12X | 23,800 | $1,190 |
| No | 210821486 | AIREASE | 4SHP18LX136P | E*1P36B+TDR+TXV | A80US2V090B16L | 23,600 | $1,180 |
| No | 210821484 | AIREASE | 4SHP18LX136P | E*1P36B+TDR+TXV | A80US2V080B16X | 23,400 | $1,170 |
| No | 210821502 | AIREASE | 4SHP18LX136P | E*1P36B+TDR+TXV | A96US2V070B12 | 23,800 | $1,190 |
| No | 210821498 | AIREASE | 4SHP18LX136P | E*1P36B+TDR+TXV | A96UH2E070B12 | 23,200 | $1,160 |
| No | 210821500 | AIREASE | 4SHP18LX136P | E*1P36B+TDR+TXV | A96US2V045B12 | 23,800 | $1,190 |
| No | 210821496 | AIREASE | 4SHP18LX136P | E*1P36B+TDR+TXV | A96UH2E045B12 | 23,200 | $1,160 |
| No | 210821495 | AIREASE | 4SHP18LX136P | E*1P36B+TDR+TXV | A96UH1E070B12 | 23,200 | $1,160 |
| No | 210821494 | AIREASE | 4SHP18LX136P | E*1P36B+TDR+TXV | A96UH1E030B12 | 23,200 | $1,160 |
| No | 210821492 | AIREASE | 4SHP18LX136P | E*1P36B+TDR+TXV | A95UH1E070B12 | 23,000 | $1,150 |
| No | 210821490 | AIREASE | 4SHP18LX136P | E*1P36B+TDR+TXV | A93UH1E070B12 | 23,400 | $1,170 |
| No | 210821489 | AIREASE | 4SHP18LX136P | E*1P36B+TDR+TXV | A93UH1E045B12 | 23,400 | $1,170 |
| No | 210821487 | AIREASE | 4SHP18LX136P | E*1P36B+TDR+TXV | A93UH1E030B12 | 23,400 | $1,170 |
| No | 210821482 | AIREASE | 4SHP18LX136P | E*1P36B+TDR+TXV | A80UH2E090B16 | 23,400 | $1,170 |
| No | 210821481 | AIREASE | 4SHP18LX136P | E*1P36B+TDR+TXV | A80UH2E090B12 | 23,400 | $1,170 |
| No | 210821480 | AIREASE | 4SHP18LX136P | E*1P36B+TDR+TXV | A80UH1E090B16 | 23,200 | $1,160 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210821478 | AIREASE | 4SHP18LX136P | E*1P36B+TDR+TXV | A80UH1E080B16X | 23,600 | $1,180 |
| No | 210821477 | AIREASE | 4SHP18LX136P | E*1P36B+TDR+TXV | A80UH1E070B12 | 23,200 | $1,160 |
| No | 210821474 | AIREASE | 4SHP18LX136P | E*1P36A+TDR+TXV | A80US2V060A12X | 23,600 | $1,180 |
| No | 210821476 | AIREASE | 4SHP18LX136P | E*1P36A+TDR+TXV | A80US2V070A12L | 23,800 | $1,190 |
| No | 210821473 | AIREASE | 4SHP18LX136P | E*1P36A+TDR+TXV | A80UH2E070A12 | 23,400 | $1,170 |
| No | 210821472 | AIREASE | 4SHP18LX136P | E*1P36A+TDR+TXV | A80UH2E045A12 | 23,400 | $1,170 |
| No | 210821470 | AIREASE | 4SHP18LX136P | E*1P36A+TDR+TXV | A80UH1E070A12 | 23,200 | $1,160 |
| No | 210821468 | AIREASE | 4SHP18LX136P | E*1P36A+TDR+TXV | A80UH1E060A12X | 23,200 | $1,160 |
| No | 210821467 | AIREASE | 4SHP18LX136P | E*1P36A+TDR+TXV | A80UH1E045A12 | 23,200 | $1,160 |
| No | 210821465 | AIREASE | 4SHP18LX136P | E*1P36A+TDR+TXV | A80UH1E040A12X | 23,200 | $1,160 |
| No | 210821838 | AIREASE | 4SHP18LX136P | ED1P30/36B+TDR+TXV | A80DS2V090B16 | 22,600 | $1,130 |
| No | 210821800 | AIREASE | 4SHP18LX136P | EAH1P36B+TDR+TXV | EFV12BCA | 22,600 | $1,130 |
| No | 210821797 | AIREASE | 4SHP18LX136P | EAH1P36B+TDR+TXV | A97US2V060B12X | 23,000 | $1,150 |
| No | 210821795 | AIREASE | 4SHP18LX136P | EAH1P36B+TDR+TXV | A97US2V040B12X | 22,800 | $1,140 |
| No | 210821768 | AIREASE | 4SHP18LX136P | EAH1P36B+TDR+TXV | A80US2V090B16L | 22,800 | $1,140 |
| No | 210821765 | AIREASE | 4SHP18LX136P | EAH1P36B+TDR+TXV | A80US2V080B16X | 22,600 | $1,130 |
| No | 210821792 | AIREASE | 4SHP18LX136P | EAH1P36B+TDR+TXV | A96US2V070B12 | 22,800 | $1,140 |
| No | 210821786 | AIREASE | 4SHP18LX136P | EAH1P36B+TDR+TXV | A96UH2E070B12 | 22,400 | $1,120 |
| No | 210821789 | AIREASE | 4SHP18LX136P | EAH1P36B+TDR+TXV | A96US2V045B12 | 23,000 | $1,150 |
| No | 210821783 | AIREASE | 4SHP18LX136P | EAH1P36B+TDR+TXV | A96UH2E045B12 | 22,400 | $1,120 |
| No | 210821780 | AIREASE | 4SHP18LX136P | EAH1P36B+TDR+TXV | A96UH1E070B12 | 22,200 | $1,110 |
| No | 210821779 | AIREASE | 4SHP18LX136P | EAH1P36B+TDR+TXV | A96UH1E030B12 | 22,400 | $1,120 |
| No | 210821776 | AIREASE | 4SHP18LX136P | EAH1P36B+TDR+TXV | A95UH1E070B12 | 22,200 | $1,110 |
| No | 210821775 | AIREASE | 4SHP18LX136P | EAH1P36B+TDR+TXV | A93UH1E070B12 | 22,600 | $1,130 |
| No | 210821772 | AIREASE | 4SHP18LX136P | EAH1P36B+TDR+TXV | A93UH1E045B12 | 22,600 | $1,130 |
| No | 210821771 | AIREASE | 4SHP18LX136P | EAH1P36B+TDR+TXV | A93UH1E030B12 | 22,600 | $1,130 |
| No | 210821766 | AIREASE | 4SHP18LX136P | EAH1P36B+TDR+TXV | A80US2V090B16 | 22,800 | $1,140 |
| No | 210821763 | AIREASE | 4SHP18LX136P | EAH1P36B+TDR+TXV | A80UH2E090B16 | 22,600 | $1,130 |
| No | 210821760 | AIREASE | 4SHP18LX136P | EAH1P36B+TDR+TXV | A80UH2E090B12 | 22,600 | $1,130 |
| No | 210821756 | AIREASE | 4SHP18LX136P | EAH1P36B+TDR+TXV | A80UH1E090B16 | 22,400 | $1,120 |
| No | 210821754 | AIREASE | 4SHP18LX136P | EAH1P36B+TDR+TXV | A80UH1E080B16X | 22,600 | $1,130 |
| No | 210821752 | AIREASE | 4SHP18LX136P | EAH1P36B+TDR+TXV | A80UH1E070B12 | 22,400 | $1,120 |
| No | 210821750 | AIREASE | 4SHP18LX136P | EAC4X48C+TDR | EFV16CCA | 22,600 | $1,130 |
| No | 210821749 | AIREASE | 4SHP18LX136P | EAC4X48C+TDR | A97USMV090C16 | 22,800 | $1,140 |
| No | 210821747 | AIREASE | 4SHP18LX136P | EAC4X48C+TDR | A97USMV090C12 | 22,800 | $1,140 |
| No | 210821746 | AIREASE | 4SHP18LX136P | EAC4X48C+TDR | A97US2V080C16X | 22,800 | $1,140 |
| No | 210821744 | AIREASE | 4SHP18LX136P | EAC4X48C+TDR | A96US2V110C16 | 22,800 | $1,140 |
| No | 210821743 | AIREASE | 4SHP18LX136P | EAC4X48C+TDR | A96US2V090C16 | 22,800 | $1,140 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210821742 | AIREASE | 4SHP18LX136P | EAC4X48C+TDR | A96US2V090C12 | 22,800 | $1,140 |
| No | 210821740 | AIREASE | 4SHP18LX136P | EAC4X48C+TDR | A96UH2E090C16 | 22,800 | $1,140 |
| No | 210821738 | AIREASE | 4SHP18LX136P | EAC4X48C+TDR | A96UH1E090C16 | 22,600 | $1,130 |
| No | 210821737 | AIREASE | 4SHP18LX136P | EAC4X48C+TDR | A95UH1E090C16 | 22,600 | $1,130 |
| No | 210821735 | AIREASE | 4SHP18LX136P | EAC4X48C+TDR | A93UH1E110C16 | 22,400 | $1,120 |
| No | 210821734 | AIREASE | 4SHP18LX136P | EAC4X48C+TDR | A93UH1E090C16 | 22,600 | $1,130 |
| No | 210821732 | AIREASE | 4SHP18LX136P | EAC4X48C+TDR | A93UH1E090C12 | 22,800 | $1,140 |
| No | 210821731 | AIREASE | 4SHP18LX136P | EAC4X48C+TDR | A80UH2E110C16 | 22,600 | $1,130 |
| No | 210821729 | AIREASE | 4SHP18LX136P | EAC4X48B+TDR | EFV12BCA | 22,600 | $1,130 |
| No | 210821728 | AIREASE | 4SHP18LX136P | EAC4X48B+TDR | A97USMV070B12 | 23,000 | $1,150 |
| No | 210821727 | AIREASE | 4SHP18LX136P | EAC4X48B+TDR | A97US2V060B12X | 23,000 | $1,150 |
| No | 210821726 | AIREASE | 4SHP18LX136P | EAC4X48B+TDR | A97US2V040B12X | 23,000 | $1,150 |
| No | 210821702 | AIREASE | 4SHP18LX136P | EAC4X48B+TDR | A80US2V090B16L | 22,800 | $1,140 |
| No | 210821699 | AIREASE | 4SHP18LX136P | EAC4X48B+TDR | A80US2V080B16X | 22,800 | $1,140 |
| No | 210821724 | AIREASE | 4SHP18LX136P | EAC4X48B+TDR | A96US2V070B12 | 23,000 | $1,150 |
| No | 210821719 | AIREASE | 4SHP18LX136P | EAC4X48B+TDR | A96UH2E070B12 | 22,600 | $1,130 |
| No | 210821722 | AIREASE | 4SHP18LX136P | EAC4X48B+TDR | A96US2V045B12 | 23,000 | $1,150 |
| No | 210821717 | AIREASE | 4SHP18LX136P | EAC4X48B+TDR | A96UH2E045B12 | 22,600 | $1,130 |
| No | 210821715 | AIREASE | 4SHP18LX136P | EAC4X48B+TDR | A96UH1E070B12 | 22,400 | $1,120 |
| No | 210821712 | AIREASE | 4SHP18LX136P | EAC4X48B+TDR | A96UH1E045B12 | 22,400 | $1,120 |
| No | 210821708 | AIREASE | 4SHP18LX136P | EAC4X48B+TDR | A95UH1E070B12 | 22,200 | $1,110 |
| No | 210821706 | AIREASE | 4SHP18LX136P | EAC4X48B+TDR | A93UH1E070B12 | 22,600 | $1,130 |
| No | 210821705 | AIREASE | 4SHP18LX136P | EAC4X48B+TDR | A93UH1E045B12 | 22,800 | $1,140 |
| No | 210821703 | AIREASE | 4SHP18LX136P | EAC4X48B+TDR | A93UH1E030B12 | 22,600 | $1,130 |
| No | 210821701 | AIREASE | 4SHP18LX136P | EAC4X48B+TDR | A80US2V090B16 | 22,800 | $1,140 |
| No | 210821698 | AIREASE | 4SHP18LX136P | EAC4X48B+TDR | A80UH2E090B16 | 22,600 | $1,130 |
| No | 210821694 | AIREASE | 4SHP18LX136P | EAC4X48B+TDR | A80UH2E090B12 | 22,800 | $1,140 |
| No | 210821693 | AIREASE | 4SHP18LX136P | EAC4X48B+TDR | A80UH1E090B16 | 22,600 | $1,130 |
| No | 210821690 | AIREASE | 4SHP18LX136P | EAC4X48B+TDR | A80UH1E070B12 | 22,600 | $1,130 |
| No | 210821629 | AIREASE | 4SHP18LX136P | EA(C;U)1P48C+TDR+TXV | A97USMV090C16 | 22,800 | $1,140 |
| No | 210821626 | AIREASE | 4SHP18LX136P | EA(C;U)1P48C+TDR+TXV | A97USMV090C12 | 22,800 | $1,140 |
| No | 210821625 | AIREASE | 4SHP18LX136P | EA(C;U)1P48C+TDR+TXV | A97US2V080C16X | 22,800 | $1,140 |
| No | 210821624 | AIREASE | 4SHP18LX136P | EA(C;U)1P48C+TDR+TXV | A96US2V110C16 | 22,800 | $1,140 |
| No | 210821622 | AIREASE | 4SHP18LX136P | EA(C;U)1P48C+TDR+TXV | A96US2V090C16 | 22,800 | $1,140 |
| No | 210821620 | AIREASE | 4SHP18LX136P | EA(C;U)1P48C+TDR+TXV | A96US2V090C12 | 22,800 | $1,140 |
| No | 210821618 | AIREASE | 4SHP18LX136P | EA(C;U)1P48C+TDR+TXV | A96UH2E090C16 | 22,800 | $1,140 |
| No | 210821616 | AIREASE | 4SHP18LX136P | EA(C;U)1P48C+TDR+TXV | A96UH1E090C16 | 22,600 | $1,130 |
| No | 210821613 | AIREASE | 4SHP18LX136P | EA(C;U)1P48C+TDR+TXV | A95UH1E090C16 | 22,600 | $1,130 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210821611 | AIREASE | 4SHP18LX136P | EA(C;U)1P48C+TDR+TXV | A93UH1E110C16 | 22,400 | $1,120 |
| No | 210821610 | AIREASE | 4SHP18LX136P | EA(C;U)1P48C+TDR+TXV | A93UH1E090C16 | 22,600 | $1,130 |
| No | 210821609 | AIREASE | 4SHP18LX136P | EA(C;U)1P48C+TDR+TXV | A93UH1E090C12 | 22,800 | $1,140 |
| No | 210821607 | AIREASE | 4SHP18LX136P | EA(C;U)1P48C+TDR+TXV | A80UH2E110C16 | 22,600 | $1,130 |
| No | 210821606 | AIREASE | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | EFV12BCA | 22,800 | $1,140 |
| No | 210821604 | AIREASE | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A97US2V060B12X | 23,000 | $1,150 |
| No | 210821582 | AIREASE | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A80US2V090B16L | 22,800 | $1,140 |
| No | 210821580 | AIREASE | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A80US2V080B16X | 22,800 | $1,140 |
| No | 210821601 | AIREASE | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A96US2V070B12 | 23,000 | $1,150 |
| No | 210821597 | AIREASE | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A96UH2E070B12 | 22,600 | $1,130 |
| No | 210821598 | AIREASE | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A96US2V045B12 | 23,000 | $1,150 |
| No | 210821596 | AIREASE | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A96UH2E045B12 | 22,600 | $1,130 |
| No | 210821593 | AIREASE | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A96UH1E070B12 | 22,400 | $1,120 |
| No | 210821592 | AIREASE | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A96UH1E045B12 | 22,400 | $1,120 |
| No | 210821589 | AIREASE | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A95UH1E070B12 | 22,200 | $1,110 |
| No | 210821587 | AIREASE | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A93UH1E070B12 | 22,600 | $1,130 |
| No | 210821585 | AIREASE | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A93UH1E045B12 | 22,800 | $1,140 |
| No | 210821584 | AIREASE | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A93UH1E030B12 | 22,600 | $1,130 |
| No | 210821581 | AIREASE | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A80US2V090B16 | 22,800 | $1,140 |
| No | 210821579 | AIREASE | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A80UH2E090B16 | 22,600 | $1,130 |
| No | 210821576 | AIREASE | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A80UH2E090B12 | 22,800 | $1,140 |
| No | 210821574 | AIREASE | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A80UH1E090B16 | 22,600 | $1,130 |
| No | 210821570 | AIREASE | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A80UH1E070B12 | 22,600 | $1,130 |
| No | 210821686 | AIREASE | 4SHP18LX136P | EAC4X36B+TDR | A97USMV070B12 | 23,200 | $1,160 |
| No | 210821684 | AIREASE | 4SHP18LX136P | EAC4X36B+TDR | A97US2V060B12X | 23,200 | $1,160 |
| No | 210821680 | AIREASE | 4SHP18LX136P | EAC4X36B+TDR | A97US2V040B12X | 23,200 | $1,160 |
| No | 210821656 | AIREASE | 4SHP18LX136P | EAC4X36B+TDR | A80US2V090B16L | 23,000 | $1,150 |
| No | 210821654 | AIREASE | 4SHP18LX136P | EAC4X36B+TDR | A80US2V080B16X | 23,000 | $1,150 |
| No | 210821678 | AIREASE | 4SHP18LX136P | EAC4X36B+TDR | A96US2V070B12 | 23,200 | $1,160 |
| No | 210821676 | AIREASE | 4SHP18LX136P | EAC4X36B+TDR | A96US2V045B12 | 23,400 | $1,170 |
| No | 210821645 | AIREASE | 4SHP18LX136P | EAC4X36B+TDR | A80UH1E070B12 | 22,600 | $1,130 |
| No | 210821641 | AIREASE | 4SHP18LX136P | EAC4X36A+TDR | A80US2V060A12X | 23,000 | $1,150 |
| No | 210821644 | AIREASE | 4SHP18LX136P | EAC4X36A+TDR | A80US2V070A12L | 23,200 | $1,160 |
| No | 210821637 | AIREASE | 4SHP18LX136P | EAC4X36A+TDR | A80UH2E045A12 | 22,800 | $1,140 |
| No | 210821635 | AIREASE | 4SHP18LX136P | EAC4X36A+TDR | A80UH1E070A12 | 22,600 | $1,130 |
| No | 210821548 | AIREASE | 4SHP18LX136P | EA(C;U)1P36B+TDR+TXV | A80US2V080B16X | 23,000 | $1,150 |
| No | 210821567 | AIREASE | 4SHP18LX136P | EA(C;U)1P36B+TDR+TXV | A97US2V060B12X | 23,200 | $1,160 |
| No | 210821564 | AIREASE | 4SHP18LX136P | EA(C;U)1P36B+TDR+TXV | A97US2V040B12X | 23,200 | $1,160 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210821550 | AIREASE | 4SHP18LX136P | EA(C;U)1P36B+TDR+TXV | A80US2V090B16L | 23,000 | $1,150 |
| No | 210821561 | AIREASE | 4SHP18LX136P | EA(C;U)1P36B+TDR+TXV | A96US2V070B12 | 23,200 | $1,160 |
| No | 210821560 | AIREASE | 4SHP18LX136P | EA(C;U)1P36B+TDR+TXV | A96US2V045B12 | 23,400 | $1,170 |
| No | 210821540 | AIREASE | 4SHP18LX136P | EA(C;U)1P36B+TDR+TXV | A80UH1E070B12 | 22,600 | $1,130 |
| No | 210821539 | AIREASE | 4SHP18LX136P | EA(C;U)1P36A+TDR+TXV | A80US2V070A12L | 23,200 | $1,160 |
| No | 210821538 | AIREASE | 4SHP18LX136P | EA(C;U)1P36A+TDR+TXV | A80US2V060A12X | 23,000 | $1,150 |
| No | 210821536 | AIREASE | 4SHP18LX136P | EA(C;U)1P36A+TDR+TXV | A80UH2E045A12 | 22,800 | $1,140 |
| No | 210821535 | AIREASE | 4SHP18LX136P | EA(C;U)1P36A+TDR+TXV | A80UH1E070A12 | 22,600 | $1,130 |
| No | 210821864 | AIREASE | 4SHP18LX136P | BCE5C36M*4X | | 22,400 | $1,120 |
| No | 210821452 | AIREASE | 4SHP18LX136P | BCE5C36M*1P+TXV | | 22,400 | $1,120 |
| No | 210821455 | AIREASE | 4SHP18LX136P | BCE5E42M*4X | | 22,000 | $1,100 |
| No | 210821453 | AIREASE | 4SHP18LX136P | BCE5E36M*4X | | 22,200 | $1,110 |
| No | 210821457 | AIREASE | 4SHP18LX136P | BCE5V36M*4X | | 22,000 | $1,100 |
| No | 210821458 | AIREASE | 4SHP18LX136P | BCE5V42M*4X | | 22,200 | $1,110 |
| No | 210821462 | AIREASE | 4SHP18LX136P | BCE7S42M*4X | | 22,400 | $1,120 |
| No | 210821450 | AIREASE | 4SHP18LX136P | BCE7S36 | | 22,600 | $1,130 |
| No | 211528683 | AIREASE | 4SHP22LX136P-**A | ED1P48B+TDR+TXV | A97DSMV070B12 | 21,800 | $1,090 |
| No | 211528682 | AIREASE | 4SHP22LX136P-**A | ED1P48B+TDR+TXV | A80DS2V090B16 | 21,800 | $1,090 |
| No | 211528681 | AIREASE | 4SHP22LX136P-**A | ED1P48B+TDR+TXV | A96DF1E070B16 | 21,800 | $1,090 |
| No | 211528680 | AIREASE | 4SHP22LX136P-**A | ED1P48B+TDR+TXV | A96DF1E045B12 | 21,600 | $1,080 |
| No | 211528679 | AIREASE | 4SHP22LX136P-**A | ED1P48B+TDR+TXV | A93DF1E070B12 | 21,600 | $1,080 |
| No | 211528678 | AIREASE | 4SHP22LX136P-**A | ED1P48B+TDR+TXV | A93DF1E045B12 | 21,800 | $1,090 |
| No | 211528677 | AIREASE | 4SHP22LX136P-**A | ED1P48B+TDR+TXV | A80DF1E090B16 | 21,400 | $1,070 |
| No | 211528676 | AIREASE | 4SHP22LX136P-**A | ED1P48B+TDR+TXV | A80DF1E070B12 | 21,600 | $1,080 |
| No | 211528675 | AIREASE | 4SHP22LX136P-**A | ED1P48B+TDR+TXV | A96DS2V070B16 | 22,000 | $1,100 |
| No | 211528674 | AIREASE | 4SHP22LX136P-**A | ED1P48B+TDR+TXV | A96DF2E070B16 | 21,800 | $1,090 |
| No | 211528673 | AIREASE | 4SHP22LX136P-**A | ED1P48B+TDR+TXV | A96DS2V045B12 | 22,000 | $1,100 |
| No | 211804162 | AIREASE | 4SHP22LX136P-**A | EAC4X48C+TDR | A97USMV110C20 | 22,400 | $1,120 |
| No | 211804160 | AIREASE | 4SHP22LX136P-**A | EAC4X48C+TDR | A97USMV090C16 | 22,400 | $1,120 |
| No | 211804159 | AIREASE | 4SHP22LX136P-**A | EAC4X48C+TDR | A97USMV090C12 | 22,400 | $1,120 |
| No | 211804157 | AIREASE | 4SHP22LX136P-**A | EAC4X48C+TDR | A97US2V080C16X | 22,400 | $1,120 |
| No | 211804153 | AIREASE | 4SHP22LX136P-**A | EAC4X48C+TDR | A96US2V110C16 | 22,400 | $1,120 |
| No | 211804150 | AIREASE | 4SHP22LX136P-**A | EAC4X48C+TDR | A96US2V090C16 | 22,400 | $1,120 |
| No | 211804149 | AIREASE | 4SHP22LX136P-**A | EAC4X48C+TDR | A96US2V090C12 | 22,400 | $1,120 |
| No | 211804147 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48C+TDR+TXV | A97USMV110C20 | 22,400 | $1,120 |
| No | 211804145 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48C+TDR+TXV | A97USMV090C16 | 22,400 | $1,120 |
| No | 211804144 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48C+TDR+TXV | A97USMV090C12 | 22,400 | $1,120 |
| No | 211804142 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48C+TDR+TXV | A97US2V080C16X | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211804138 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48C+TDR+TXV | A96US2V110C16 | 22,400 | $1,120 |
| No | 211804135 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48C+TDR+TXV | A96US2V090C16 | 22,400 | $1,120 |
| No | 211804134 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48C+TDR+TXV | A96US2V090C12 | 22,400 | $1,120 |
| No | 211709595 | AIREASE | 4SHP22LX124P-**A | ED1P24B+TDR+TXV | A97DSMV070B12 | 15,000 | $750 |
| No | 211709594 | AIREASE | 4SHP22LX124P-**A | ED1P24B+TDR+TXV | A80DS2V090B16 | 15,100 | $755 |
| No | 211709593 | AIREASE | 4SHP22LX124P-**A | ED1P24B+TDR+TXV | A96DF1E070B16 | 15,000 | $750 |
| No | 211709592 | AIREASE | 4SHP22LX124P-**A | ED1P24B+TDR+TXV | A96DF1E045B12 | 15,000 | $750 |
| No | 211709591 | AIREASE | 4SHP22LX124P-**A | ED1P24B+TDR+TXV | A93DF1E070B12 | 14,900 | $745 |
| No | 211709590 | AIREASE | 4SHP22LX124P-**A | ED1P24B+TDR+TXV | A93DF1E045B12 | 14,900 | $745 |
| No | 211709589 | AIREASE | 4SHP22LX124P-**A | ED1P24B+TDR+TXV | A80DF1E090B16 | 15,100 | $755 |
| No | 211709588 | AIREASE | 4SHP22LX124P-**A | ED1P24B+TDR+TXV | A80DF1E070B12 | 15,000 | $750 |
| No | 211709587 | AIREASE | 4SHP22LX124P-**A | ED1P24B+TDR+TXV | A96DS2V070B16 | 15,200 | $760 |
| No | 211709586 | AIREASE | 4SHP22LX124P-**A | ED1P24B+TDR+TXV | A96DF2E070B16 | 14,900 | $745 |
| No | 211709585 | AIREASE | 4SHP22LX124P-**A | ED1P24B+TDR+TXV | A96DS2V045B12 | 15,000 | $750 |
| No | 211709584 | AIREASE | 4SHP22LX124P-**A | ED1P24B+TDR+TXV | A96DF2E045B12 | 14,900 | $745 |
| No | 211709583 | AIREASE | 4SHP22LX124P-**A | ED1P24A+TDR+TXV | A80DS2V070A12 | 15,000 | $750 |
| No | 211709582 | AIREASE | 4SHP22LX124P-**A | ED1P24A+TDR+TXV | A80DF1E070A12 | 14,900 | $745 |
| No | 211709581 | AIREASE | 4SHP22LX124P-**A | ED1P24A+TDR+TXV | A80DF1E045A12 | 14,900 | $745 |
| No | 211709626 | AIREASE | 4SHP22LX124P-**A | EAC4X24B+TDR | A97USMV070B12 | 14,700 | $735 |
| No | 211709625 | AIREASE | 4SHP22LX124P-**A | EAC4X24B+TDR | A97US2V060B12X | 14,700 | $735 |
| No | 211709624 | AIREASE | 4SHP22LX124P-**A | EAC4X24B+TDR | A97US2V040B12X | 14,700 | $735 |
| No | 211709623 | AIREASE | 4SHP22LX124P-**A | EAC4X24B+TDR | A80US2V090B16L | 14,600 | $730 |
| No | 211709622 | AIREASE | 4SHP22LX124P-**A | EAC4X24B+TDR | A80US2V090B16 | 14,600 | $730 |
| No | 211709621 | AIREASE | 4SHP22LX124P-**A | EAC4X24B+TDR | A80US2V090B12 | 14,600 | $730 |
| No | 211709620 | AIREASE | 4SHP22LX124P-**A | EAC4X24B+TDR | A80US2V080B16X | 14,800 | $740 |
| No | 211709619 | AIREASE | 4SHP22LX124P-**A | EAC4X24B+TDR | A96UH1E070B12 | 14,800 | $740 |
| No | 211709618 | AIREASE | 4SHP22LX124P-**A | EAC4X24B+TDR | A96UH1E045B12 | 14,800 | $740 |
| No | 211709617 | AIREASE | 4SHP22LX124P-**A | EAC4X24B+TDR | A96UH1E030B12 | 14,800 | $740 |
| No | 211709616 | AIREASE | 4SHP22LX124P-**A | EAC4X24B+TDR | A93UH1E070B12 | 14,700 | $735 |
| No | 211709615 | AIREASE | 4SHP22LX124P-**A | EAC4X24B+TDR | A93UH1E045B12 | 14,800 | $740 |
| No | 211709614 | AIREASE | 4SHP22LX124P-**A | EAC4X24B+TDR | A93UH1E030B12 | 14,800 | $740 |
| No | 211709613 | AIREASE | 4SHP22LX124P-**A | EAC4X24B+TDR | A80UH1E090B16 | 14,800 | $740 |
| No | 211709612 | AIREASE | 4SHP22LX124P-**A | EAC4X24B+TDR | A80UH1E070B12 | 14,500 | $725 |
| No | 211709611 | AIREASE | 4SHP22LX124P-**A | EAC4X24B+TDR | A96US2V070B12 | 14,700 | $735 |
| No | 211709610 | AIREASE | 4SHP22LX124P-**A | EAC4X24B+TDR | A96UH2E070B12 | 14,800 | $740 |
| No | 211709609 | AIREASE | 4SHP22LX124P-**A | EAC4X24B+TDR | A96US2V045B12 | 14,800 | $740 |
| No | 211709608 | AIREASE | 4SHP22LX124P-**A | EAC4X24B+TDR | A96UH2E045B12 | 14,800 | $740 |
| No | 211709607 | AIREASE | 4SHP22LX124P-**A | EAC4X24B+TDR | A80UH2E090B16 | 14,800 | $740 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211709606 | AIREASE | 4SHP22LX124P-**A | EAC4X24B+TDR | A80UH2E090B12 | 14,700 | $735 |
| No | 211709605 | AIREASE | 4SHP22LX124P-**A | EAC4X24B+TDR | A80UH1E080B16X | 15,000 | $750 |
| No | 211709540 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A97USMV070B12 | 14,700 | $735 |
| No | 211709539 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A97US2V060B12X | 14,700 | $735 |
| No | 211709538 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A97US2V040B12X | 14,700 | $735 |
| No | 211709537 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A80US2V090B16L | 14,600 | $730 |
| No | 211709536 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A80US2V090B16 | 14,600 | $730 |
| No | 211709535 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A80US2V090B12 | 14,600 | $730 |
| No | 211709534 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A80US2V080B16X | 14,800 | $740 |
| No | 211709533 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A96UH1E070B12 | 14,800 | $740 |
| No | 211709532 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A96UH1E045B12 | 14,800 | $740 |
| No | 211709531 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A96UH1E030B12 | 14,800 | $740 |
| No | 211709530 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A93UH1E070B12 | 14,700 | $735 |
| No | 211709529 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A93UH1E045B12 | 14,800 | $740 |
| No | 211709528 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A93UH1E030B12 | 14,800 | $740 |
| No | 211709527 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A80UH1E090B16 | 14,800 | $740 |
| No | 211709526 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A80UH1E070B12 | 14,500 | $725 |
| No | 211709525 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A96US2V070B12 | 14,700 | $735 |
| No | 211709524 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A96UH2E070B12 | 14,800 | $740 |
| No | 211709523 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A96US2V045B12 | 14,800 | $740 |
| No | 211709522 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A96UH2E045B12 | 14,800 | $740 |
| No | 211709521 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A80UH2E090B16 | 14,800 | $740 |
| No | 211709520 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A80UH2E090B12 | 14,700 | $735 |
| No | 211709519 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A80UH1E080B16X | 15,000 | $750 |
| No | 211709604 | AIREASE | 4SHP22LX124P-**A | EAC4X24A+TDR | A80US2V070A12L | 14,700 | $735 |
| No | 211709603 | AIREASE | 4SHP22LX124P-**A | EAC4X24A+TDR | A80US2V070A12 | 14,700 | $735 |
| No | 211709602 | AIREASE | 4SHP22LX124P-**A | EAC4X24A+TDR | A80US2V060A12X | 14,700 | $735 |
| No | 211709601 | AIREASE | 4SHP22LX124P-**A | EAC4X24A+TDR | A80UH1E070A12 | 14,500 | $725 |
| No | 211709600 | AIREASE | 4SHP22LX124P-**A | EAC4X24A+TDR | A80UH1E045A12 | 14,200 | $710 |
| No | 211709599 | AIREASE | 4SHP22LX124P-**A | EAC4X24A+TDR | A80UH2E070A12 | 14,700 | $735 |
| No | 211709598 | AIREASE | 4SHP22LX124P-**A | EAC4X24A+TDR | A80UH2E045A12 | 14,300 | $715 |
| No | 211709597 | AIREASE | 4SHP22LX124P-**A | EAC4X24A+TDR | A80UH1E060A12X | 14,700 | $735 |
| No | 211709596 | AIREASE | 4SHP22LX124P-**A | EAC4X24A+TDR | A80UH1E040A12X | 14,700 | $735 |
| No | 211709518 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24A+TDR+TXV | A80US2V070A12L | 14,700 | $735 |
| No | 211709517 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24A+TDR+TXV | A80US2V070A12 | 14,700 | $735 |
| No | 211709516 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24A+TDR+TXV | A80US2V060A12X | 14,700 | $735 |
| No | 211709515 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24A+TDR+TXV | A80UH1E070A12 | 14,500 | $725 |
| No | 211709514 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24A+TDR+TXV | A80UH1E045A12 | 14,200 | $710 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211709513 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24A+TDR+TXV | A80UH2E070A12 | 14,700 | $735 |
| No | 211709512 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24A+TDR+TXV | A80UH2E045A12 | 14,300 | $715 |
| No | 211709511 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24A+TDR+TXV | A80UH1E060A12X | 14,700 | $735 |
| No | 211709510 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P24A+TDR+TXV | A80UH1E040A12X | 14,700 | $735 |
| No | 211709648 | AIREASE | 4SHP22LX124P-**A | EAC4X30B+TDR | A97DSMV070B12 | 14,200 | $710 |
| No | 211709649 | AIREASE | 4SHP22LX124P-**A | EAC4X30B+TDR | A97USMV070B12 | 14,200 | $710 |
| No | 211709647 | AIREASE | 4SHP22LX124P-**A | EAC4X30B+TDR | A97US2V060B12X | 14,200 | $710 |
| No | 211709646 | AIREASE | 4SHP22LX124P-**A | EAC4X30B+TDR | A97US2V040B12X | 14,200 | $710 |
| No | 211709645 | AIREASE | 4SHP22LX124P-**A | EAC4X30B+TDR | A80US2V090B16L | 14,100 | $705 |
| No | 211709644 | AIREASE | 4SHP22LX124P-**A | EAC4X30B+TDR | A80US2V090B16 | 14,100 | $705 |
| No | 211709643 | AIREASE | 4SHP22LX124P-**A | EAC4X30B+TDR | A80US2V090B12 | 14,100 | $705 |
| No | 211709642 | AIREASE | 4SHP22LX124P-**A | EAC4X30B+TDR | A80US2V080B16X | 14,300 | $715 |
| No | 211709641 | AIREASE | 4SHP22LX124P-**A | EAC4X30B+TDR | A96UH1E070B12 | 14,400 | $720 |
| No | 211709640 | AIREASE | 4SHP22LX124P-**A | EAC4X30B+TDR | A96UH1E045B12 | 14,400 | $720 |
| No | 211709639 | AIREASE | 4SHP22LX124P-**A | EAC4X30B+TDR | A96UH1E030B12 | 13,900 | $695 |
| No | 211709638 | AIREASE | 4SHP22LX124P-**A | EAC4X30B+TDR | A93UH1E070B12 | 14,200 | $710 |
| No | 211709637 | AIREASE | 4SHP22LX124P-**A | EAC4X30B+TDR | A93UH1E045B12 | 14,300 | $715 |
| No | 211709636 | AIREASE | 4SHP22LX124P-**A | EAC4X30B+TDR | A93UH1E030B12 | 13,800 | $690 |
| No | 211709635 | AIREASE | 4SHP22LX124P-**A | EAC4X30B+TDR | A80UH1E090B16 | 14,400 | $720 |
| No | 211709634 | AIREASE | 4SHP22LX124P-**A | EAC4X30B+TDR | A80UH1E070B12 | 14,000 | $700 |
| No | 211709633 | AIREASE | 4SHP22LX124P-**A | EAC4X30B+TDR | A96US2V070B12 | 14,200 | $710 |
| No | 211709632 | AIREASE | 4SHP22LX124P-**A | EAC4X30B+TDR | A96UH2E070B12 | 14,300 | $715 |
| No | 211709631 | AIREASE | 4SHP22LX124P-**A | EAC4X30B+TDR | A96US2V045B12 | 14,300 | $715 |
| No | 211709630 | AIREASE | 4SHP22LX124P-**A | EAC4X30B+TDR | A96UH2E045B12 | 14,300 | $715 |
| No | 211709629 | AIREASE | 4SHP22LX124P-**A | EAC4X30B+TDR | A80UH2E090B16 | 14,400 | $720 |
| No | 211709628 | AIREASE | 4SHP22LX124P-**A | EAC4X30B+TDR | A80UH2E090B12 | 14,300 | $715 |
| No | 211709627 | AIREASE | 4SHP22LX124P-**A | EAC4X30B+TDR | A80UH1E080B16X | 14,500 | $725 |
| No | 211709571 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A97DSMV070B12 | 14,200 | $710 |
| No | 211709572 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A97USMV070B12 | 14,200 | $710 |
| No | 211709570 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A97US2V060B12X | 14,200 | $710 |
| No | 211709569 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A97US2V040B12X | 14,200 | $710 |
| No | 211709568 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A80US2V090B16L | 14,100 | $705 |
| No | 211709567 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A80US2V090B16 | 14,100 | $705 |
| No | 211709566 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A80US2V090B12 | 14,100 | $705 |
| No | 211709565 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A80US2V080B16X | 14,300 | $715 |
| No | 211709564 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A96UH1E070B12 | 14,400 | $720 |
| No | 211709563 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A96UH1E045B12 | 14,400 | $720 |
| No | 211709562 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A96UH1E030B12 | 13,900 | $695 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211709561 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A93UH1E070B12 | 14,200 | $710 |
| No | 211709560 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A93UH1E045B12 | 14,300 | $715 |
| No | 211709559 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A93UH1E030B12 | 13,800 | $690 |
| No | 211709558 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A80UH1E090B16 | 14,400 | $720 |
| No | 211709557 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A80UH1E070B12 | 14,000 | $700 |
| No | 211709556 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A96US2V070B12 | 14,200 | $710 |
| No | 211709555 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A96UH2E070B12 | 14,300 | $715 |
| No | 211709554 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A96US2V045B12 | 14,300 | $715 |
| No | 211709553 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A96UH2E045B12 | 14,300 | $715 |
| No | 211709552 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A80UH2E090B16 | 14,400 | $720 |
| No | 211709551 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A80UH2E090B12 | 14,300 | $715 |
| No | 211709550 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A80UH1E080B16X | 14,500 | $725 |
| No | 211709658 | AIREASE | 4SHP22LX124P-**A | EAC4X30A+TDR | A80US2V070A12L | 14,200 | $710 |
| No | 211709657 | AIREASE | 4SHP22LX124P-**A | EAC4X30A+TDR | A80US2V070A12 | 14,200 | $710 |
| No | 211709656 | AIREASE | 4SHP22LX124P-**A | EAC4X30A+TDR | A80US2V060A12X | 14,200 | $710 |
| No | 211709655 | AIREASE | 4SHP22LX124P-**A | EAC4X30A+TDR | A80UH1E070A12 | 14,000 | $700 |
| No | 211709654 | AIREASE | 4SHP22LX124P-**A | EAC4X30A+TDR | A80UH1E045A12 | 14,200 | $710 |
| No | 211709653 | AIREASE | 4SHP22LX124P-**A | EAC4X30A+TDR | A80UH2E070A12 | 14,300 | $715 |
| No | 211709652 | AIREASE | 4SHP22LX124P-**A | EAC4X30A+TDR | A80UH2E045A12 | 13,900 | $695 |
| No | 211709651 | AIREASE | 4SHP22LX124P-**A | EAC4X30A+TDR | A80UH1E060A12X | 14,200 | $710 |
| No | 211709650 | AIREASE | 4SHP22LX124P-**A | EAC4X30A+TDR | A80UH1E040A12X | 14,200 | $710 |
| No | 211709549 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30A+TDR+TXV | A80US2V070A12L | 14,200 | $710 |
| No | 211709548 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30A+TDR+TXV | A80US2V070A12 | 14,200 | $710 |
| No | 211709547 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30A+TDR+TXV | A80US2V060A12X | 14,200 | $710 |
| No | 211709546 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30A+TDR+TXV | A80UH1E070A12 | 14,000 | $700 |
| No | 211709545 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30A+TDR+TXV | A80UH1E045A12 | 14,200 | $710 |
| No | 211709544 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30A+TDR+TXV | A80UH2E070A12 | 14,300 | $715 |
| No | 211709543 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30A+TDR+TXV | A80UH2E045A12 | 13,900 | $695 |
| No | 211709542 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30A+TDR+TXV | A80UH1E060A12X | 14,200 | $710 |
| No | 211709541 | AIREASE | 4SHP22LX124P-**A | EA(C;U)1P30A+TDR+TXV | A80UH1E040A12X | 14,200 | $710 |
| No | 211709574 | AIREASE | 4SHP22LX124P-**A | BCE5C30M*4X | | 14,900 | $745 |
| No | 211709576 | AIREASE | 4SHP22LX124P-**A | BCE5V30M*4X | | 14,500 | $725 |
| No | 211709573 | AIREASE | 4SHP22LX124P-**A | BCE5C24M*4X | | 14,700 | $735 |
| No | 211709575 | AIREASE | 4SHP22LX124P-**A | BCE5V24M*4X | | 14,900 | $745 |
| No | 211709577 | AIREASE | 4SHP22LX124P-**A | BCE7E18M*4X | | 14,100 | $705 |
| No | 211709578 | AIREASE | 4SHP22LX124P-**A | BCE7E24M*4X | | 14,500 | $725 |
| No | 211709580 | AIREASE | 4SHP22LX124P-**A | BCE7S24M*4X | | 14,400 | $720 |
| No | 211804206 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A97USMV110C20 | 38,000 | $1,900 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211804284 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A97USMV090C20 | 38,000 | $1,900 |
| No | 211804283 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A97USMV090C16 | 38,500 | $1,925 |
| No | 211804205 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A80US2V110C20L | 37,800 | $1,890 |
| No | 211804204 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A80US2V110C20 | 37,800 | $1,890 |
| No | 211804202 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A80US2V090C20 | 37,800 | $1,890 |
| No | 211804200 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A96US2V110C20 | 38,000 | $1,900 |
| No | 211804276 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A96US2V090C20 | 38,000 | $1,900 |
| No | 211804275 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A96US2V090C16 | 38,500 | $1,925 |
| No | 211804282 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A97US2V080C20X | 38,000 | $1,900 |
| No | 211804203 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A80US2V100C20X | 38,000 | $1,900 |
| No | 211804201 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A80US2V080C20X | 38,000 | $1,900 |
| No | 211804281 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A96UH1E110C20 | 38,000 | $1,900 |
| No | 211804280 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A93UH1E110C20 | 38,000 | $1,900 |
| No | 211804279 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A80UH1E110C20 | 38,500 | $1,925 |
| No | 211804278 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A80UH1E090C20 | 38,500 | $1,925 |
| No | 211804277 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A96UH2E110C20 | 38,000 | $1,900 |
| No | 211804199 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A80UH2E110C20 | 37,600 | $1,880 |
| No | 211804274 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A80UH1E100C20X | 38,500 | $1,925 |
| No | 211804198 | AIREASE | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A97USMV110C20 | 38,000 | $1,900 |
| No | 211804273 | AIREASE | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A97USMV090C20 | 38,000 | $1,900 |
| No | 211804272 | AIREASE | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A97USMV090C16 | 38,500 | $1,925 |
| No | 211804197 | AIREASE | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A80US2V110C20L | 37,800 | $1,890 |
| No | 211804196 | AIREASE | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A80US2V110C20 | 37,800 | $1,890 |
| No | 211804194 | AIREASE | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A80US2V090C20 | 37,800 | $1,890 |
| No | 211804192 | AIREASE | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A96US2V110C20 | 38,000 | $1,900 |
| No | 211804265 | AIREASE | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A96US2V090C20 | 38,000 | $1,900 |
| No | 211804264 | AIREASE | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A96US2V090C16 | 38,500 | $1,925 |
| No | 211804271 | AIREASE | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A97US2V080C20X | 38,000 | $1,900 |
| No | 211804195 | AIREASE | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A80US2V100C20X | 38,000 | $1,900 |
| No | 211804193 | AIREASE | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A80US2V080C20X | 38,000 | $1,900 |
| No | 211804270 | AIREASE | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A96UH1E110C20 | 38,000 | $1,900 |
| No | 211804269 | AIREASE | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A93UH1E110C20 | 38,000 | $1,900 |
| No | 211804268 | AIREASE | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A80UH1E110C20 | 38,500 | $1,925 |
| No | 211804267 | AIREASE | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A80UH1E090C20 | 38,500 | $1,925 |
| No | 211804266 | AIREASE | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A96UH2E110C20 | 38,000 | $1,900 |
| No | 211804191 | AIREASE | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A80UH2E110C20 | 37,600 | $1,880 |
| No | 211804263 | AIREASE | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A80UH1E100C20X | 38,500 | $1,925 |
| No | 211529016 | AIREASE | 4SHP22LX160P-**A | EAC4X60C+TDR | A97USMV110C20 | 37,400 | $1,870 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211530262 | AIREASE | 4SHP22LX160P-**A | EAC4X60C+TDR | A97USMV090C20 | 37,600 | $1,880 |
| No | 211530261 | AIREASE | 4SHP22LX160P-**A | EAC4X60C+TDR | A97USMV090C16 | 37,800 | $1,890 |
| No | 211530260 | AIREASE | 4SHP22LX160P-**A | EAC4X60C+TDR | A97US2V080C20X | 37,600 | $1,880 |
| No | 211529015 | AIREASE | 4SHP22LX160P-**A | EAC4X60C+TDR | A80US2V110C20L | 37,400 | $1,870 |
| No | 211529014 | AIREASE | 4SHP22LX160P-**A | EAC4X60C+TDR | A80US2V110C20 | 37,400 | $1,870 |
| No | 211529013 | AIREASE | 4SHP22LX160P-**A | EAC4X60C+TDR | A80US2V100C20X | 37,400 | $1,870 |
| No | 211529012 | AIREASE | 4SHP22LX160P-**A | EAC4X60C+TDR | A80US2V090C20 | 37,400 | $1,870 |
| No | 211529011 | AIREASE | 4SHP22LX160P-**A | EAC4X60C+TDR | A80US2V080C20X | 37,400 | $1,870 |
| No | 211530259 | AIREASE | 4SHP22LX160P-**A | EAC4X60C+TDR | A96UH1E110C20 | 37,800 | $1,890 |
| No | 211530258 | AIREASE | 4SHP22LX160P-**A | EAC4X60C+TDR | A93UH1E110C20 | 37,800 | $1,890 |
| No | 211530257 | AIREASE | 4SHP22LX160P-**A | EAC4X60C+TDR | A80UH1E110C20 | 37,800 | $1,890 |
| No | 211529010 | AIREASE | 4SHP22LX160P-**A | EAC4X60C+TDR | A80UH1E090C20 | 37,000 | $1,850 |
| No | 211529009 | AIREASE | 4SHP22LX160P-**A | EAC4X60C+TDR | A96US2V110C20 | 37,400 | $1,870 |
| No | 211530256 | AIREASE | 4SHP22LX160P-**A | EAC4X60C+TDR | A96US2V110C16 | 37,800 | $1,890 |
| No | 211530255 | AIREASE | 4SHP22LX160P-**A | EAC4X60C+TDR | A96UH2E110C20 | 37,800 | $1,890 |
| No | 211530254 | AIREASE | 4SHP22LX160P-**A | EAC4X60C+TDR | A96US2V090C20 | 37,600 | $1,880 |
| No | 211530253 | AIREASE | 4SHP22LX160P-**A | EAC4X60C+TDR | A96US2V090C16 | 37,800 | $1,890 |
| No | 211529008 | AIREASE | 4SHP22LX160P-**A | EAC4X60C+TDR | A80UH2E110C20 | 37,200 | $1,860 |
| No | 211530252 | AIREASE | 4SHP22LX160P-**A | EAC4X60C+TDR | A80UH1E100C20X | 38,000 | $1,900 |
| No | 211528991 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A97USMV110C20 | 37,400 | $1,870 |
| No | 211530244 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A97USMV090C20 | 37,600 | $1,880 |
| No | 211530243 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A97USMV090C16 | 37,800 | $1,890 |
| No | 211530242 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A97US2V080C20X | 37,600 | $1,880 |
| No | 211528990 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A80US2V110C20L | 37,400 | $1,870 |
| No | 211528989 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A80US2V110C20 | 37,400 | $1,870 |
| No | 211528988 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A80US2V100C20X | 37,400 | $1,870 |
| No | 211528987 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A80US2V090C20 | 37,400 | $1,870 |
| No | 211528986 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A80US2V080C20X | 37,400 | $1,870 |
| No | 211530241 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A96UH1E110C20 | 37,800 | $1,890 |
| No | 211530240 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A93UH1E110C20 | 37,800 | $1,890 |
| No | 211530239 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A80UH1E110C20 | 37,800 | $1,890 |
| No | 211528985 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A80UH1E090C20 | 37,000 | $1,850 |
| No | 211528984 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A96US2V110C20 | 37,400 | $1,870 |
| No | 211530238 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A96US2V110C16 | 37,800 | $1,890 |
| No | 211530237 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A96UH2E110C20 | 37,800 | $1,890 |
| No | 211530236 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A96US2V090C20 | 37,600 | $1,880 |
| No | 211530235 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A96US2V090C16 | 37,800 | $1,890 |
| No | 211528983 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A80UH2E110C20 | 37,200 | $1,860 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211530234 | AIREASE | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A80UH1E100C20X | 38,000 | $1,900 |
| No | 211529020 | AIREASE | 4SHP22LX160P-**A | EAC4X60D+TDR | A97USMV135D20 | 37,600 | $1,880 |
| No | 211529019 | AIREASE | 4SHP22LX160P-**A | EAC4X60D+TDR | A80US2V135D20 | 37,400 | $1,870 |
| No | 211529018 | AIREASE | 4SHP22LX160P-**A | EAC4X60D+TDR | A96UH1E135D20 | 37,800 | $1,890 |
| No | 211530263 | AIREASE | 4SHP22LX160P-**A | EAC4X60D+TDR | A80UH1E135D20 | 37,800 | $1,890 |
| No | 211529017 | AIREASE | 4SHP22LX160P-**A | EAC4X60D+TDR | A96US2V135D20 | 37,600 | $1,880 |
| No | 211530251 | AIREASE | 4SHP22LX160P-**A | EAH1P60D+TDR+TXV | A97USMV135D20 | 36,400 | $1,820 |
| No | 211530250 | AIREASE | 4SHP22LX160P-**A | EAH1P60D+TDR+TXV | A80US2V135D20 | 36,200 | $1,810 |
| No | 211530249 | AIREASE | 4SHP22LX160P-**A | EAH1P60D+TDR+TXV | A96UH1E135D20 | 36,600 | $1,830 |
| No | 211530248 | AIREASE | 4SHP22LX160P-**A | EAH1P60D+TDR+TXV | A80UH1E135D20 | 36,800 | $1,840 |
| No | 211530247 | AIREASE | 4SHP22LX160P-**A | EAH1P60D+TDR+TXV | A96US2V135D20 | 36,200 | $1,810 |
| No | 211528997 | AIREASE | 4SHP22LX160P-**A | ED1P50/60C+TDR+TXV | A80DS2V110C20 | 38,000 | $1,900 |
| No | 211528999 | AIREASE | 4SHP22LX160P-**A | ED1P50/60C+TDR+TXV | A97DSMV110C20 | 38,500 | $1,925 |
| No | 211528998 | AIREASE | 4SHP22LX160P-**A | ED1P50/60C+TDR+TXV | A97DSMV090C20 | 38,500 | $1,925 |
| No | 211528996 | AIREASE | 4SHP22LX160P-**A | ED1P50/60C+TDR+TXV | A96DF1E110C20 | 38,500 | $1,925 |
| No | 211528995 | AIREASE | 4SHP22LX160P-**A | ED1P50/60C+TDR+TXV | A80DF1E110C20 | 37,600 | $1,880 |
| No | 211528994 | AIREASE | 4SHP22LX160P-**A | ED1P50/60C+TDR+TXV | A96DS2V110C20 | 38,500 | $1,925 |
| No | 211528993 | AIREASE | 4SHP22LX160P-**A | ED1P50/60C+TDR+TXV | A96DF2E110C20 | 38,000 | $1,900 |
| No | 211528992 | AIREASE | 4SHP22LX160P-**A | ED1P50/60C+TDR+TXV | A96DS2V090C20 | 38,500 | $1,925 |
| No | 211529005 | AIREASE | 4SHP22LX160P-**A | ED1P60D+TDR+TXV | A80DS2V110C20 | 38,000 | $1,900 |
| No | 211529007 | AIREASE | 4SHP22LX160P-**A | ED1P60D+TDR+TXV | A97DSMV110C20 | 38,500 | $1,925 |
| No | 211529006 | AIREASE | 4SHP22LX160P-**A | ED1P60D+TDR+TXV | A97DSMV090C20 | 38,500 | $1,925 |
| No | 211529004 | AIREASE | 4SHP22LX160P-**A | ED1P60D+TDR+TXV | A96DF1E110C20 | 38,500 | $1,925 |
| No | 211529003 | AIREASE | 4SHP22LX160P-**A | ED1P60D+TDR+TXV | A80DF1E110C20 | 37,600 | $1,880 |
| No | 211529002 | AIREASE | 4SHP22LX160P-**A | ED1P60D+TDR+TXV | A96DS2V110C20 | 38,500 | $1,925 |
| No | 211529001 | AIREASE | 4SHP22LX160P-**A | ED1P60D+TDR+TXV | A96DF2E110C20 | 38,000 | $1,900 |
| No | 211529000 | AIREASE | 4SHP22LX160P-**A | ED1P60D+TDR+TXV | A96DS2V090C20 | 38,500 | $1,925 |
| No | 211530245 | AIREASE | 4SHP22LX160P-**A | BCE5C60M*4X | | 36,800 | $1,840 |
| No | 211530246 | AIREASE | 4SHP22LX160P-**A | BCE5V60M*4X | | 37,200 | $1,860 |
| No | 211529021 | AIREASE | 4SHP22LX160P-**A | BCE7E60M*4X | | 37,000 | $1,850 |
| No | 211528647 | AIREASE | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A97US2V080C16X | 22,600 | $1,130 |
| No | 211528646 | AIREASE | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A80US2V110C20L | 22,400 | $1,120 |
| No | 211528645 | AIREASE | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A80US2V110C20 | 22,400 | $1,120 |
| No | 211528644 | AIREASE | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A80US2V100C20X | 22,400 | $1,120 |
| No | 211528643 | AIREASE | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A80US2V090C20 | 22,400 | $1,120 |
| No | 211528642 | AIREASE | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A80US2V080C20X | 22,400 | $1,120 |
| No | 211528641 | AIREASE | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A96UH1E110C20 | 22,600 | $1,130 |
| No | 211528640 | AIREASE | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A96UH1E090C16 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211528639 | AIREASE | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A93UH1E110C20 | 22,400 | $1,120 |
| No | 211528638 | AIREASE | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A93UH1E110C16 | 22,200 | $1,110 |
| No | 211528637 | AIREASE | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A93UH1E090C16 | 22,400 | $1,120 |
| No | 211528636 | AIREASE | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A93UH1E090C12 | 22,400 | $1,120 |
| No | 211528635 | AIREASE | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A80UH1E110C20 | 22,200 | $1,110 |
| No | 211528634 | AIREASE | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A80UH1E090C20 | 22,200 | $1,110 |
| No | 211528633 | AIREASE | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A96US2V110C20 | 22,400 | $1,120 |
| No | 211528632 | AIREASE | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A96US2V110C16 | 22,600 | $1,130 |
| No | 211528631 | AIREASE | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A96UH2E110C20 | 22,600 | $1,130 |
| No | 211528630 | AIREASE | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A96US2V090C20 | 22,600 | $1,130 |
| No | 211528629 | AIREASE | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A96US2V090C16 | 22,600 | $1,130 |
| No | 211528628 | AIREASE | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A96US2V090C12 | 22,600 | $1,130 |
| No | 211528627 | AIREASE | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A96UH2E090C16 | 22,200 | $1,110 |
| No | 211528626 | AIREASE | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A80UH2E110C20 | 22,600 | $1,130 |
| No | 211528625 | AIREASE | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A80UH2E110C16 | 22,000 | $1,100 |
| No | 211528624 | AIREASE | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A80UH1E100C20X | 22,400 | $1,120 |
| No | 211528763 | AIREASE | 4SHP22LX136P-**A | EAC4X48B+TDR | A97USMV070B12 | 22,600 | $1,130 |
| No | 211528762 | AIREASE | 4SHP22LX136P-**A | EAC4X48B+TDR | A97US2V060B12X | 22,600 | $1,130 |
| No | 211528761 | AIREASE | 4SHP22LX136P-**A | EAC4X48B+TDR | A97US2V040B12X | 22,600 | $1,130 |
| No | 211528760 | AIREASE | 4SHP22LX136P-**A | EAC4X48B+TDR | A80US2V090B16L | 22,400 | $1,120 |
| No | 211528759 | AIREASE | 4SHP22LX136P-**A | EAC4X48B+TDR | A80US2V090B16 | 22,400 | $1,120 |
| No | 211528758 | AIREASE | 4SHP22LX136P-**A | EAC4X48B+TDR | A80US2V090B12 | 22,400 | $1,120 |
| No | 211528757 | AIREASE | 4SHP22LX136P-**A | EAC4X48B+TDR | A80US2V080B16X | 22,600 | $1,130 |
| No | 211528756 | AIREASE | 4SHP22LX136P-**A | EAC4X48B+TDR | A96UH1E070B12 | 22,200 | $1,110 |
| No | 211528755 | AIREASE | 4SHP22LX136P-**A | EAC4X48B+TDR | A96UH1E045B12 | 21,800 | $1,090 |
| No | 211528754 | AIREASE | 4SHP22LX136P-**A | EAC4X48B+TDR | A96UH1E030B12 | 22,200 | $1,110 |
| No | 211528753 | AIREASE | 4SHP22LX136P-**A | EAC4X48B+TDR | A93UH1E070B12 | 22,200 | $1,110 |
| No | 211528752 | AIREASE | 4SHP22LX136P-**A | EAC4X48B+TDR | A93UH1E045B12 | 22,400 | $1,120 |
| No | 211528751 | AIREASE | 4SHP22LX136P-**A | EAC4X48B+TDR | A93UH1E030B12 | 22,400 | $1,120 |
| No | 211528750 | AIREASE | 4SHP22LX136P-**A | EAC4X48B+TDR | A80UH1E090B16 | 22,200 | $1,110 |
| No | 211528749 | AIREASE | 4SHP22LX136P-**A | EAC4X48B+TDR | A80UH1E070B12 | 22,200 | $1,110 |
| No | 211528748 | AIREASE | 4SHP22LX136P-**A | EAC4X48B+TDR | A96US2V070B12 | 22,600 | $1,130 |
| No | 211528747 | AIREASE | 4SHP22LX136P-**A | EAC4X48B+TDR | A96UH2E070B12 | 22,200 | $1,110 |
| No | 211528746 | AIREASE | 4SHP22LX136P-**A | EAC4X48B+TDR | A96US2V045B12 | 22,600 | $1,130 |
| No | 211528745 | AIREASE | 4SHP22LX136P-**A | EAC4X48B+TDR | A96UH2E045B12 | 22,400 | $1,120 |
| No | 211528744 | AIREASE | 4SHP22LX136P-**A | EAC4X48B+TDR | A80UH2E090B16 | 22,000 | $1,100 |
| No | 211528743 | AIREASE | 4SHP22LX136P-**A | EAC4X48B+TDR | A80UH2E090B12 | 22,000 | $1,100 |
| No | 211528742 | AIREASE | 4SHP22LX136P-**A | EAC4X48B+TDR | A80UH1E080B16X | 22,600 | $1,130 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211528567 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A97USMV070B12 | 22,600 | $1,130 |
| No | 211528566 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A97US2V060B12X | 22,600 | $1,130 |
| No | 211528565 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A97US2V040B12X | 22,600 | $1,130 |
| No | 211528564 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A80US2V090B16L | 22,400 | $1,120 |
| No | 211528563 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A80US2V090B16 | 22,400 | $1,120 |
| No | 211528562 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A80US2V090B12 | 22,400 | $1,120 |
| No | 211528561 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A80US2V080B16X | 22,600 | $1,130 |
| No | 211528560 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A96UH1E070B12 | 22,200 | $1,110 |
| No | 211528559 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A96UH1E045B12 | 21,800 | $1,090 |
| No | 211528558 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A96UH1E030B12 | 22,200 | $1,110 |
| No | 211528557 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A93UH1E070B12 | 22,200 | $1,110 |
| No | 211528556 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A93UH1E045B12 | 22,400 | $1,120 |
| No | 211528555 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A93UH1E030B12 | 22,400 | $1,120 |
| No | 211528554 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A80UH1E090B16 | 22,200 | $1,110 |
| No | 211528553 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A80UH1E070B12 | 22,200 | $1,110 |
| No | 211528552 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A96US2V070B12 | 22,600 | $1,130 |
| No | 211528551 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A96UH2E070B12 | 22,200 | $1,110 |
| No | 211528550 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A96US2V045B12 | 22,600 | $1,130 |
| No | 211528549 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A96UH2E045B12 | 22,400 | $1,120 |
| No | 211528548 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A80UH2E090B16 | 22,000 | $1,100 |
| No | 211528547 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A80UH2E090B12 | 22,000 | $1,100 |
| No | 211528546 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A80UH1E080B16X | 22,600 | $1,130 |
| No | 211530163 | AIREASE | 4SHP22LX136P-**A | EAH1P30A+TDR+TXV | A80US2V070A12L | 23,200 | $1,160 |
| No | 211530162 | AIREASE | 4SHP22LX136P-**A | EAH1P30A+TDR+TXV | A80US2V070A12 | 23,200 | $1,160 |
| No | 211528575 | AIREASE | 4SHP22LX136P-**A | EAH1P30A+TDR+TXV | A80UH1E070A12 | 22,600 | $1,130 |
| No | 211528574 | AIREASE | 4SHP22LX136P-**A | EAH1P30A+TDR+TXV | A80UH1E045A12 | 22,600 | $1,130 |
| No | 211530161 | AIREASE | 4SHP22LX136P-**A | EAH1P30A+TDR+TXV | A80UH2E070A12 | 23,000 | $1,150 |
| No | 211528573 | AIREASE | 4SHP22LX136P-**A | EAH1P30A+TDR+TXV | A80UH2E045A12 | 23,000 | $1,150 |
| No | 211530160 | AIREASE | 4SHP22LX136P-**A | EAH1P30A+TDR+TXV | A80UH1E060A12X | 22,600 | $1,130 |
| No | 211530159 | AIREASE | 4SHP22LX136P-**A | EAH1P30A+TDR+TXV | A80UH1E040A12X | 22,600 | $1,130 |
| No | 211528672 | AIREASE | 4SHP22LX136P-**A | ED1P30/36C+TDR+TXV | A97DSMV090C16 | 23,400 | $1,170 |
| No | 211528671 | AIREASE | 4SHP22LX136P-**A | ED1P30/36C+TDR+TXV | A96DF1E110C20 | 23,000 | $1,150 |
| No | 211528670 | AIREASE | 4SHP22LX136P-**A | ED1P30/36C+TDR+TXV | A96DF1E090C16 | 22,800 | $1,140 |
| No | 211528669 | AIREASE | 4SHP22LX136P-**A | ED1P30/36C+TDR+TXV | A93DF1E090C16 | 22,800 | $1,140 |
| No | 211528668 | AIREASE | 4SHP22LX136P-**A | ED1P30/36C+TDR+TXV | A80DF1E110C20 | 22,800 | $1,140 |
| No | 211528667 | AIREASE | 4SHP22LX136P-**A | ED1P30/36C+TDR+TXV | A96DF2E110C20 | 23,000 | $1,150 |
| No | 211528666 | AIREASE | 4SHP22LX136P-**A | ED1P30/36C+TDR+TXV | A96DF2E090C16 | 22,800 | $1,140 |
| No | 211528665 | AIREASE | 4SHP22LX136P-**A | ED1P30/36B+TDR+TXV | A97DSMV070B12 | 23,200 | $1,160 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211528664 | AIREASE | 4SHP22LX136P-**A | ED1P30/36B+TDR+TXV | A80DS2V090B16 | 23,200 | $1,160 |
| No | 211528663 | AIREASE | 4SHP22LX136P-**A | ED1P30/36B+TDR+TXV | A96DF1E070B16 | 23,200 | $1,160 |
| No | 211528662 | AIREASE | 4SHP22LX136P-**A | ED1P30/36B+TDR+TXV | A96DF1E045B12 | 22,800 | $1,140 |
| No | 211528661 | AIREASE | 4SHP22LX136P-**A | ED1P30/36B+TDR+TXV | A93DF1E070B12 | 23,000 | $1,150 |
| No | 211528660 | AIREASE | 4SHP22LX136P-**A | ED1P30/36B+TDR+TXV | A93DF1E045B12 | 23,000 | $1,150 |
| No | 211528659 | AIREASE | 4SHP22LX136P-**A | ED1P30/36B+TDR+TXV | A80DF1E090B16 | 22,800 | $1,140 |
| No | 211528658 | AIREASE | 4SHP22LX136P-**A | ED1P30/36B+TDR+TXV | A80DF1E070B12 | 22,600 | $1,130 |
| No | 211528657 | AIREASE | 4SHP22LX136P-**A | ED1P30/36B+TDR+TXV | A96DS2V070B16 | 23,400 | $1,170 |
| No | 211528656 | AIREASE | 4SHP22LX136P-**A | ED1P30/36B+TDR+TXV | A96DF2E070B16 | 23,000 | $1,150 |
| No | 211528655 | AIREASE | 4SHP22LX136P-**A | ED1P30/36B+TDR+TXV | A96DS2V045B12 | 23,400 | $1,170 |
| No | 211528654 | AIREASE | 4SHP22LX136P-**A | ED1P30/36A+TDR+TXV | A80DS2V070A12 | 23,400 | $1,170 |
| No | 211528653 | AIREASE | 4SHP22LX136P-**A | ED1P30/36A+TDR+TXV | A80DF1E070A12 | 22,800 | $1,140 |
| No | 211528741 | AIREASE | 4SHP22LX136P-**A | EAC4X36B+TDR | A97USMV070B12 | 22,000 | $1,100 |
| No | 211528740 | AIREASE | 4SHP22LX136P-**A | EAC4X36B+TDR | A97US2V060B12X | 22,200 | $1,110 |
| No | 211528739 | AIREASE | 4SHP22LX136P-**A | EAC4X36B+TDR | A97US2V040B12X | 22,000 | $1,100 |
| No | 211528738 | AIREASE | 4SHP22LX136P-**A | EAC4X36B+TDR | A80US2V090B16L | 22,000 | $1,100 |
| No | 211528737 | AIREASE | 4SHP22LX136P-**A | EAC4X36B+TDR | A80US2V090B16 | 22,000 | $1,100 |
| No | 211528736 | AIREASE | 4SHP22LX136P-**A | EAC4X36B+TDR | A80US2V090B12 | 22,000 | $1,100 |
| No | 211528735 | AIREASE | 4SHP22LX136P-**A | EAC4X36B+TDR | A80US2V080B16X | 22,000 | $1,100 |
| No | 211528734 | AIREASE | 4SHP22LX136P-**A | EAC4X36B+TDR | A96UH1E070B12 | 21,600 | $1,080 |
| No | 211528733 | AIREASE | 4SHP22LX136P-**A | EAC4X36B+TDR | A96UH1E030B12 | 21,600 | $1,080 |
| No | 211528732 | AIREASE | 4SHP22LX136P-**A | EAC4X36B+TDR | A93UH1E070B12 | 21,800 | $1,090 |
| No | 211528731 | AIREASE | 4SHP22LX136P-**A | EAC4X36B+TDR | A93UH1E045B12 | 21,800 | $1,090 |
| No | 211528730 | AIREASE | 4SHP22LX136P-**A | EAC4X36B+TDR | A93UH1E030B12 | 21,800 | $1,090 |
| No | 211528729 | AIREASE | 4SHP22LX136P-**A | EAC4X36B+TDR | A80UH1E090B16 | 21,600 | $1,080 |
| No | 211528728 | AIREASE | 4SHP22LX136P-**A | EAC4X36B+TDR | A80UH1E070B12 | 21,600 | $1,080 |
| No | 211528727 | AIREASE | 4SHP22LX136P-**A | EAC4X36B+TDR | A96US2V070B12 | 22,000 | $1,100 |
| No | 211528726 | AIREASE | 4SHP22LX136P-**A | EAC4X36B+TDR | A96UH2E070B12 | 21,600 | $1,080 |
| No | 211528725 | AIREASE | 4SHP22LX136P-**A | EAC4X36B+TDR | A96US2V045B12 | 22,200 | $1,110 |
| No | 211528724 | AIREASE | 4SHP22LX136P-**A | EAC4X36B+TDR | A96UH2E045B12 | 21,800 | $1,090 |
| No | 211528723 | AIREASE | 4SHP22LX136P-**A | EAC4X36B+TDR | A80UH2E090B16 | 21,400 | $1,070 |
| No | 211528722 | AIREASE | 4SHP22LX136P-**A | EAC4X36B+TDR | A80UH2E090B12 | 21,800 | $1,090 |
| No | 211528721 | AIREASE | 4SHP22LX136P-**A | EAC4X36B+TDR | A80UH1E080B16X | 22,000 | $1,100 |
| No | 211528545 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A97USMV070B12 | 22,000 | $1,100 |
| No | 211528544 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A97US2V060B12X | 22,200 | $1,110 |
| No | 211528543 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A97US2V040B12X | 22,000 | $1,100 |
| No | 211528542 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A80US2V090B16L | 22,000 | $1,100 |
| No | 211528541 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A80US2V090B16 | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211528540 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A80US2V090B12 | 22,000 | $1,100 |
| No | 211528539 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A80US2V080B16X | 22,000 | $1,100 |
| No | 211528538 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A96UH1E070B12 | 21,600 | $1,080 |
| No | 211528537 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A96UH1E030B12 | 21,600 | $1,080 |
| No | 211528536 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A93UH1E070B12 | 21,800 | $1,090 |
| No | 211528535 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A93UH1E045B12 | 21,800 | $1,090 |
| No | 211528534 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A93UH1E030B12 | 21,800 | $1,090 |
| No | 211528533 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A80UH1E090B16 | 21,600 | $1,080 |
| No | 211528532 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A80UH1E070B12 | 21,600 | $1,080 |
| No | 211528531 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A96US2V070B12 | 22,000 | $1,100 |
| No | 211528530 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A96UH2E070B12 | 21,600 | $1,080 |
| No | 211528529 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A96US2V045B12 | 22,200 | $1,110 |
| No | 211528528 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A96UH2E045B12 | 21,800 | $1,090 |
| No | 211528527 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A80UH2E090B16 | 21,400 | $1,070 |
| No | 211528526 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A80UH2E090B12 | 21,800 | $1,090 |
| No | 211528525 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A80UH1E080B16X | 22,000 | $1,100 |
| No | 211528720 | AIREASE | 4SHP22LX136P-**A | EAC4X36A+TDR | A80US2V070A12L | 22,200 | $1,110 |
| No | 211528719 | AIREASE | 4SHP22LX136P-**A | EAC4X36A+TDR | A80US2V070A12 | 22,200 | $1,110 |
| No | 211528718 | AIREASE | 4SHP22LX136P-**A | EAC4X36A+TDR | A80UH1E070A12 | 21,600 | $1,080 |
| No | 211528717 | AIREASE | 4SHP22LX136P-**A | EAC4X36A+TDR | A80UH1E045A12 | 21,600 | $1,080 |
| No | 211528716 | AIREASE | 4SHP22LX136P-**A | EAC4X36A+TDR | A80UH2E070A12 | 21,800 | $1,090 |
| No | 211528715 | AIREASE | 4SHP22LX136P-**A | EAC4X36A+TDR | A80UH2E045A12 | 21,800 | $1,090 |
| No | 211528714 | AIREASE | 4SHP22LX136P-**A | EAC4X36A+TDR | A80UH1E060A12X | 21,600 | $1,080 |
| No | 211528713 | AIREASE | 4SHP22LX136P-**A | EAC4X36A+TDR | A80UH1E040A12X | 21,600 | $1,080 |
| No | 211528524 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36A+TDR+TXV | A80US2V070A12L | 22,200 | $1,110 |
| No | 211528523 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36A+TDR+TXV | A80US2V070A12 | 22,200 | $1,110 |
| No | 211528522 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36A+TDR+TXV | A80UH1E070A12 | 21,600 | $1,080 |
| No | 211528521 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36A+TDR+TXV | A80UH1E045A12 | 21,600 | $1,080 |
| No | 211528520 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36A+TDR+TXV | A80UH2E070A12 | 21,800 | $1,090 |
| No | 211528519 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36A+TDR+TXV | A80UH2E045A12 | 21,800 | $1,090 |
| No | 211528518 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36A+TDR+TXV | A80UH1E060A12X | 21,600 | $1,080 |
| No | 211528517 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P36A+TDR+TXV | A80UH1E040A12X | 21,600 | $1,080 |
| No | 211528623 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A97USMV110C20 | 22,800 | $1,140 |
| No | 211528622 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A97USMV090C20 | 22,800 | $1,140 |
| No | 211528621 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A97USMV090C16 | 23,000 | $1,150 |
| No | 211528620 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A97USMV090C12 | 23,000 | $1,150 |
| No | 211528619 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A97US2V080C20X | 23,000 | $1,150 |
| No | 211528618 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A97US2V080C16X | 22,800 | $1,140 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211528617 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A80US2V110C20L | 22,800 | $1,140 |
| No | 211528616 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A80US2V110C20 | 22,800 | $1,140 |
| No | 211528615 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A80US2V100C20X | 22,800 | $1,140 |
| No | 211528614 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A80US2V090C20 | 22,800 | $1,140 |
| No | 211528613 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A80US2V080C20X | 22,800 | $1,140 |
| No | 211528612 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A96UH1E110C20 | 22,800 | $1,140 |
| No | 211528611 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A96UH1E090C16 | 22,800 | $1,140 |
| No | 211528610 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A93UH1E110C20 | 22,800 | $1,140 |
| No | 211528609 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A93UH1E110C16 | 22,600 | $1,130 |
| No | 211528608 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A93UH1E090C16 | 22,600 | $1,130 |
| No | 211528607 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A93UH1E090C12 | 22,800 | $1,140 |
| No | 211528606 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A80UH1E110C20 | 22,600 | $1,130 |
| No | 211528605 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A80UH1E090C20 | 22,600 | $1,130 |
| No | 211528604 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A96US2V110C20 | 22,800 | $1,140 |
| No | 211528603 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A96US2V110C16 | 23,000 | $1,150 |
| No | 211528602 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A96UH2E110C20 | 22,800 | $1,140 |
| No | 211528601 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A96US2V090C20 | 22,800 | $1,140 |
| No | 211528600 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A96US2V090C16 | 23,000 | $1,150 |
| No | 211528599 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A96US2V090C12 | 23,000 | $1,150 |
| No | 211528598 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A96UH2E090C16 | 22,600 | $1,130 |
| No | 211528597 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A80UH2E110C20 | 22,800 | $1,140 |
| No | 211528596 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A80UH2E110C16 | 22,400 | $1,120 |
| No | 211528595 | AIREASE | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A80UH1E100C20X | 22,800 | $1,140 |
| No | 211528594 | AIREASE | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A97USMV070B12 | 23,000 | $1,150 |
| No | 211528593 | AIREASE | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A97US2V060B12X | 23,000 | $1,150 |
| No | 211528592 | AIREASE | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A97US2V040B12X | 23,000 | $1,150 |
| No | 211528591 | AIREASE | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A80US2V090B16L | 22,600 | $1,130 |
| No | 211528590 | AIREASE | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A80US2V090B16 | 22,600 | $1,130 |
| No | 211528589 | AIREASE | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A80US2V090B12 | 22,800 | $1,140 |
| No | 211528588 | AIREASE | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A80US2V080B16X | 22,800 | $1,140 |
| No | 211528587 | AIREASE | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A96UH1E070B12 | 22,400 | $1,120 |
| No | 211528586 | AIREASE | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A96UH1E030B12 | 22,400 | $1,120 |
| No | 211528585 | AIREASE | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A93UH1E070B12 | 22,600 | $1,130 |
| No | 211528584 | AIREASE | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A93UH1E045B12 | 22,600 | $1,130 |
| No | 211530165 | AIREASE | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A93UH1E030B12 | 22,600 | $1,130 |
| No | 211528583 | AIREASE | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A80UH1E090B16 | 22,200 | $1,110 |
| No | 211528582 | AIREASE | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A80UH1E070B12 | 22,400 | $1,120 |
| No | 211528581 | AIREASE | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A96US2V070B12 | 23,000 | $1,150 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211528580 | AIREASE | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A96UH2E070B12 | 22,400 | $1,120 |
| No | 211530164 | AIREASE | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A96US2V045B12 | 23,000 | $1,150 |
| No | 211528579 | AIREASE | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A96UH2E045B12 | 22,600 | $1,130 |
| No | 211528578 | AIREASE | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A80UH2E090B16 | 22,600 | $1,130 |
| No | 211528577 | AIREASE | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A80UH2E090B12 | 22,600 | $1,130 |
| No | 211528576 | AIREASE | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A80UH1E080B16X | 22,800 | $1,140 |
| No | 211528712 | AIREASE | 4SHP22LX136P-**A | EAC4X30B+TDR | A97USMV070B12 | 22,000 | $1,100 |
| No | 211528711 | AIREASE | 4SHP22LX136P-**A | EAC4X30B+TDR | A97US2V060B12X | 22,200 | $1,110 |
| No | 211528710 | AIREASE | 4SHP22LX136P-**A | EAC4X30B+TDR | A97US2V040B12X | 22,000 | $1,100 |
| No | 211528709 | AIREASE | 4SHP22LX136P-**A | EAC4X30B+TDR | A80US2V090B16L | 21,800 | $1,090 |
| No | 211528708 | AIREASE | 4SHP22LX136P-**A | EAC4X30B+TDR | A80US2V090B16 | 21,800 | $1,090 |
| No | 211528707 | AIREASE | 4SHP22LX136P-**A | EAC4X30B+TDR | A80US2V090B12 | 21,800 | $1,090 |
| No | 211528706 | AIREASE | 4SHP22LX136P-**A | EAC4X30B+TDR | A80US2V080B16X | 22,000 | $1,100 |
| No | 211528705 | AIREASE | 4SHP22LX136P-**A | EAC4X30B+TDR | A96UH1E070B12 | 21,600 | $1,080 |
| No | 211528704 | AIREASE | 4SHP22LX136P-**A | EAC4X30B+TDR | A96UH1E030B12 | 21,800 | $1,090 |
| No | 211528703 | AIREASE | 4SHP22LX136P-**A | EAC4X30B+TDR | A93UH1E070B12 | 21,800 | $1,090 |
| No | 211528702 | AIREASE | 4SHP22LX136P-**A | EAC4X30B+TDR | A93UH1E045B12 | 21,800 | $1,090 |
| No | 211528701 | AIREASE | 4SHP22LX136P-**A | EAC4X30B+TDR | A93UH1E030B12 | 21,800 | $1,090 |
| No | 211528700 | AIREASE | 4SHP22LX136P-**A | EAC4X30B+TDR | A80UH1E090B16 | 21,600 | $1,080 |
| No | 211528699 | AIREASE | 4SHP22LX136P-**A | EAC4X30B+TDR | A80UH1E070B12 | 21,600 | $1,080 |
| No | 211528698 | AIREASE | 4SHP22LX136P-**A | EAC4X30B+TDR | A96US2V070B12 | 22,000 | $1,100 |
| No | 211528697 | AIREASE | 4SHP22LX136P-**A | EAC4X30B+TDR | A96UH2E070B12 | 21,600 | $1,080 |
| No | 211528696 | AIREASE | 4SHP22LX136P-**A | EAC4X30B+TDR | A96US2V045B12 | 22,200 | $1,110 |
| No | 211528695 | AIREASE | 4SHP22LX136P-**A | EAC4X30B+TDR | A96UH2E045B12 | 21,600 | $1,080 |
| No | 211528694 | AIREASE | 4SHP22LX136P-**A | EAC4X30B+TDR | A80UH2E090B16 | 21,600 | $1,080 |
| No | 211528693 | AIREASE | 4SHP22LX136P-**A | EAC4X30B+TDR | A80UH2E090B12 | 21,800 | $1,090 |
| No | 211528692 | AIREASE | 4SHP22LX136P-**A | EAC4X30B+TDR | A80UH1E080B16X | 21,600 | $1,080 |
| No | 211528516 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A97USMV070B12 | 22,000 | $1,100 |
| No | 211528515 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A97US2V060B12X | 22,200 | $1,110 |
| No | 211528514 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A97US2V040B12X | 22,000 | $1,100 |
| No | 211528513 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A80US2V090B16L | 21,800 | $1,090 |
| No | 211528512 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A80US2V090B16 | 21,800 | $1,090 |
| No | 211528511 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A80US2V090B12 | 21,800 | $1,090 |
| No | 211528510 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A80US2V080B16X | 22,000 | $1,100 |
| No | 211528509 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A96UH1E070B12 | 21,600 | $1,080 |
| No | 211528508 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A96UH1E030B12 | 21,800 | $1,090 |
| No | 211528507 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A93UH1E070B12 | 21,800 | $1,090 |
| No | 211528506 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A93UH1E045B12 | 21,800 | $1,090 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211528505 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A93UH1E030B12 | 21,800 | $1,090 |
| No | 211528504 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A80UH1E090B16 | 21,600 | $1,080 |
| No | 211528503 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A80UH1E070B12 | 21,600 | $1,080 |
| No | 211528502 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A96US2V070B12 | 22,000 | $1,100 |
| No | 211528501 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A96UH2E070B12 | 21,600 | $1,080 |
| No | 211528500 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A96US2V045B12 | 22,200 | $1,110 |
| No | 211528499 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A96UH2E045B12 | 21,600 | $1,080 |
| No | 211528498 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A80UH2E090B16 | 21,600 | $1,080 |
| No | 211528497 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A80UH2E090B12 | 21,800 | $1,090 |
| No | 211528496 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A80UH1E080B16X | 21,600 | $1,080 |
| No | 211528691 | AIREASE | 4SHP22LX136P-**A | EAC4X30A+TDR | A80US2V070A12L | 22,000 | $1,100 |
| No | 211528690 | AIREASE | 4SHP22LX136P-**A | EAC4X30A+TDR | A80US2V070A12 | 22,000 | $1,100 |
| No | 211528689 | AIREASE | 4SHP22LX136P-**A | EAC4X30A+TDR | A80UH1E070A12 | 21,600 | $1,080 |
| No | 211528688 | AIREASE | 4SHP22LX136P-**A | EAC4X30A+TDR | A80UH1E045A12 | 21,400 | $1,070 |
| No | 211528687 | AIREASE | 4SHP22LX136P-**A | EAC4X30A+TDR | A80UH2E070A12 | 21,800 | $1,090 |
| No | 211528686 | AIREASE | 4SHP22LX136P-**A | EAC4X30A+TDR | A80UH2E045A12 | 21,800 | $1,090 |
| No | 211528685 | AIREASE | 4SHP22LX136P-**A | EAC4X30A+TDR | A80UH1E060A12X | 21,600 | $1,080 |
| No | 211528684 | AIREASE | 4SHP22LX136P-**A | EAC4X30A+TDR | A80UH1E040A12X | 21,600 | $1,080 |
| No | 211528495 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30A+TDR+TXV | A80US2V070A12L | 22,000 | $1,100 |
| No | 211528494 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30A+TDR+TXV | A80US2V070A12 | 22,000 | $1,100 |
| No | 211528493 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30A+TDR+TXV | A80UH1E070A12 | 21,600 | $1,080 |
| No | 211528492 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30A+TDR+TXV | A80UH1E045A12 | 21,400 | $1,070 |
| No | 211528491 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30A+TDR+TXV | A80UH2E070A12 | 21,800 | $1,090 |
| No | 211528490 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30A+TDR+TXV | A80UH2E045A12 | 21,800 | $1,090 |
| No | 211528489 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30A+TDR+TXV | A80UH1E060A12X | 21,600 | $1,080 |
| No | 211528488 | AIREASE | 4SHP22LX136P-**A | EA(C;U)1P30A+TDR+TXV | A80UH1E040A12X | 21,600 | $1,080 |
| No | 211528569 | AIREASE | 4SHP22LX136P-**A | BCE5V42M*4X | | 22,200 | $1,110 |
| No | 211528568 | AIREASE | 4SHP22LX136P-**A | BCE5V36M*4X | | 22,200 | $1,110 |
| No | 211528571 | AIREASE | 4SHP22LX136P-**A | BCE7E42M*4X | | 22,200 | $1,110 |
| No | 211528572 | AIREASE | 4SHP22LX136P-**A | BCE7S42M*4X | | 22,800 | $1,140 |
| No | 211528570 | AIREASE | 4SHP22LX136P-**A | BCE7E36M*4X | | 23,000 | $1,150 |
| No | 211528943 | AIREASE | 4SHP22LX148P-**A | EAC4X60C+TDR | A97USMV110C20 | 28,800 | $1,440 |
| No | 211528942 | AIREASE | 4SHP22LX148P-**A | EAC4X60C+TDR | A97USMV090C20 | 28,800 | $1,440 |
| No | 211528941 | AIREASE | 4SHP22LX148P-**A | EAC4X60C+TDR | A97USMV090C16 | 29,000 | $1,450 |
| No | 211528940 | AIREASE | 4SHP22LX148P-**A | EAC4X60C+TDR | A97US2V080C20X | 29,000 | $1,450 |
| No | 211528939 | AIREASE | 4SHP22LX148P-**A | EAC4X60C+TDR | A97US2V080C16X | 29,000 | $1,450 |
| No | 211528938 | AIREASE | 4SHP22LX148P-**A | EAC4X60C+TDR | A80US2V110C20L | 28,600 | $1,430 |
| No | 211528937 | AIREASE | 4SHP22LX148P-**A | EAC4X60C+TDR | A80US2V110C20 | 28,600 | $1,430 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211528936 | AIREASE | 4SHP22LX148P-**A | EAC4X60C+TDR | A80US2V100C20X | 28,800 | $1,440 |
| No | 211528935 | AIREASE | 4SHP22LX148P-**A | EAC4X60C+TDR | A80US2V090C20 | 28,400 | $1,420 |
| No | 211528934 | AIREASE | 4SHP22LX148P-**A | EAC4X60C+TDR | A80US2V080C20X | 28,800 | $1,440 |
| No | 211528933 | AIREASE | 4SHP22LX148P-**A | EAC4X60C+TDR | A96UH1E110C20 | 28,800 | $1,440 |
| No | 211528932 | AIREASE | 4SHP22LX148P-**A | EAC4X60C+TDR | A93UH1E110C20 | 28,600 | $1,430 |
| No | 211528931 | AIREASE | 4SHP22LX148P-**A | EAC4X60C+TDR | A80UH1E110C20 | 28,600 | $1,430 |
| No | 211528930 | AIREASE | 4SHP22LX148P-**A | EAC4X60C+TDR | A80UH1E090C20 | 28,600 | $1,430 |
| No | 211528929 | AIREASE | 4SHP22LX148P-**A | EAC4X60C+TDR | A96US2V110C20 | 28,800 | $1,440 |
| No | 211528928 | AIREASE | 4SHP22LX148P-**A | EAC4X60C+TDR | A96US2V110C16 | 29,000 | $1,450 |
| No | 211528927 | AIREASE | 4SHP22LX148P-**A | EAC4X60C+TDR | A96UH2E110C20 | 28,800 | $1,440 |
| No | 211528926 | AIREASE | 4SHP22LX148P-**A | EAC4X60C+TDR | A96US2V090C20 | 29,000 | $1,450 |
| No | 211528925 | AIREASE | 4SHP22LX148P-**A | EAC4X60C+TDR | A96US2V090C16 | 29,000 | $1,450 |
| No | 211528924 | AIREASE | 4SHP22LX148P-**A | EAC4X60C+TDR | A80UH2E110C20 | 28,800 | $1,440 |
| No | 211528923 | AIREASE | 4SHP22LX148P-**A | EAC4X60C+TDR | A80UH2E110C16 | 28,400 | $1,420 |
| No | 211528922 | AIREASE | 4SHP22LX148P-**A | EAC4X60C+TDR | A80UH1E100C20X | 28,800 | $1,440 |
| No | 211528875 | AIREASE | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A97USMV110C20 | 28,800 | $1,440 |
| No | 211528874 | AIREASE | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A97USMV090C20 | 28,800 | $1,440 |
| No | 211528873 | AIREASE | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A97USMV090C16 | 29,000 | $1,450 |
| No | 211528872 | AIREASE | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A97US2V080C20X | 29,000 | $1,450 |
| No | 211528871 | AIREASE | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A97US2V080C16X | 29,000 | $1,450 |
| No | 211528870 | AIREASE | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A80US2V110C20L | 28,600 | $1,430 |
| No | 211528869 | AIREASE | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A80US2V110C20 | 28,600 | $1,430 |
| No | 211528868 | AIREASE | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A80US2V100C20X | 28,800 | $1,440 |
| No | 211528867 | AIREASE | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A80US2V090C20 | 28,400 | $1,420 |
| No | 211528866 | AIREASE | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A80US2V080C20X | 28,800 | $1,440 |
| No | 211528865 | AIREASE | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A96UH1E110C20 | 28,800 | $1,440 |
| No | 211528864 | AIREASE | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A93UH1E110C20 | 28,600 | $1,430 |
| No | 211528863 | AIREASE | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A80UH1E110C20 | 28,600 | $1,430 |
| No | 211528862 | AIREASE | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A80UH1E090C20 | 28,600 | $1,430 |
| No | 211528861 | AIREASE | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A96US2V110C20 | 28,800 | $1,440 |
| No | 211528860 | AIREASE | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A96US2V110C16 | 29,000 | $1,450 |
| No | 211528859 | AIREASE | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A96UH2E110C20 | 28,800 | $1,440 |
| No | 211528858 | AIREASE | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A96US2V090C20 | 29,000 | $1,450 |
| No | 211528857 | AIREASE | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A96US2V090C16 | 29,000 | $1,450 |
| No | 211528856 | AIREASE | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A80UH2E110C20 | 28,800 | $1,440 |
| No | 211528855 | AIREASE | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A80UH2E110C16 | 28,400 | $1,420 |
| No | 211528854 | AIREASE | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A80UH1E100C20X | 28,800 | $1,440 |
| No | 211528921 | AIREASE | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A97USMV110C20 | 28,200 | $1,410 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211528920 | AIREASE | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A97USMV090C20 | 28,200 | $1,410 |
| No | 211528919 | AIREASE | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A97USMV090C16 | 28,400 | $1,420 |
| No | 211528918 | AIREASE | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A97US2V080C20X | 28,400 | $1,420 |
| No | 211528917 | AIREASE | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A97US2V080C16X | 28,400 | $1,420 |
| No | 211528916 | AIREASE | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A80US2V110C20L | 28,200 | $1,410 |
| No | 211528915 | AIREASE | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A80US2V110C20 | 28,200 | $1,410 |
| No | 211528914 | AIREASE | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A80US2V100C20X | 28,200 | $1,410 |
| No | 211528913 | AIREASE | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A80US2V090C20 | 27,800 | $1,390 |
| No | 211528912 | AIREASE | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A80US2V080C20X | 28,200 | $1,410 |
| No | 211528911 | AIREASE | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A96UH1E110C20 | 28,200 | $1,410 |
| No | 211528910 | AIREASE | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A93UH1E110C20 | 28,000 | $1,400 |
| No | 211528909 | AIREASE | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A80UH1E110C20 | 28,000 | $1,400 |
| No | 211528908 | AIREASE | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A80UH1E090C20 | 28,000 | $1,400 |
| No | 211528907 | AIREASE | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A96US2V110C20 | 28,200 | $1,410 |
| No | 211528906 | AIREASE | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A96US2V110C16 | 28,400 | $1,420 |
| No | 211528905 | AIREASE | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A96UH2E110C20 | 28,200 | $1,410 |
| No | 211528904 | AIREASE | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A96US2V090C20 | 28,400 | $1,420 |
| No | 211528903 | AIREASE | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A96US2V090C16 | 28,400 | $1,420 |
| No | 211528902 | AIREASE | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A80UH2E110C20 | 28,000 | $1,400 |
| No | 211528901 | AIREASE | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A80UH2E110C16 | 27,800 | $1,390 |
| No | 211528900 | AIREASE | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A80UH1E100C20X | 28,200 | $1,410 |
| No | 211528899 | AIREASE | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A97USMV110C20 | 28,400 | $1,420 |
| No | 211528898 | AIREASE | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A97USMV090C20 | 28,400 | $1,420 |
| No | 211528897 | AIREASE | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A97USMV090C16 | 28,600 | $1,430 |
| No | 211528896 | AIREASE | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A97US2V080C20X | 28,400 | $1,420 |
| No | 211528895 | AIREASE | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A97US2V080C16X | 28,400 | $1,420 |
| No | 211528894 | AIREASE | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A80US2V110C20L | 28,200 | $1,410 |
| No | 211528893 | AIREASE | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A80US2V110C20 | 28,200 | $1,410 |
| No | 211528892 | AIREASE | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A80US2V100C20X | 28,400 | $1,420 |
| No | 211528891 | AIREASE | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A80US2V090C20 | 28,000 | $1,400 |
| No | 211528890 | AIREASE | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A80US2V080C20X | 28,200 | $1,410 |
| No | 211528889 | AIREASE | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A96UH1E110C20 | 28,200 | $1,410 |
| No | 211528888 | AIREASE | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A93UH1E110C20 | 28,000 | $1,400 |
| No | 211530194 | AIREASE | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A93UH1E110C16 | 27,800 | $1,390 |
| No | 211530193 | AIREASE | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A93UH1E090C16 | 28,000 | $1,400 |
| No | 211528887 | AIREASE | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A80UH1E110C20 | 28,000 | $1,400 |
| No | 211528886 | AIREASE | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A80UH1E090C20 | 28,000 | $1,400 |
| No | 211528885 | AIREASE | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A96US2V110C20 | 28,400 | $1,420 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211528884 | AIREASE | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A96US2V110C16 | 28,600 | $1,430 |
| No | 211528883 | AIREASE | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A96UH2E110C20 | 28,200 | $1,410 |
| No | 211528882 | AIREASE | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A96US2V090C20 | 28,400 | $1,420 |
| No | 211528881 | AIREASE | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A96US2V090C16 | 28,600 | $1,430 |
| No | 211528880 | AIREASE | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A80UH2E110C20 | 28,200 | $1,410 |
| No | 211528879 | AIREASE | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A80UH2E110C16 | 27,800 | $1,390 |
| No | 211530192 | AIREASE | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A80UH1E100C20X | 28,400 | $1,420 |
| No | 211530186 | AIREASE | 4SHP22LX148P-**A | BCE5C60M*4X | | 28,200 | $1,410 |
| No | 211530188 | AIREASE | 4SHP22LX148P-**A | BCE5V60M*4X | | 28,000 | $1,400 |
| No | 211530187 | AIREASE | 4SHP22LX148P-**A | BCE5V48M*4X | | 28,600 | $1,430 |
| No | 211528876 | AIREASE | 4SHP22LX148P-**A | BCE7E48M*4X | | 27,800 | $1,390 |
| No | 211528878 | AIREASE | 4SHP22LX148P-**A | BCE7S48M*4X | | 28,400 | $1,420 |
| No | 211528877 | AIREASE | 4SHP22LX148P-**A | BCE7E60M*4X | | 27,000 | $1,350 |
| No | 208106805 | AIREASE | 4DHP2S30M-1P | Combination heat pumps with or without ducts | | 16,000 | $800 |
| No | 208106802 | AIREASE | 4DHP2S24M-1P | Combination heat pumps with or without ducts | | 16,700 | $835 |
| No | 208106799 | AIREASE | 4DHP2S18M-1P | Combination heat pumps with or without ducts | | 11,400 | $570 |
| No | 202483115 | AIREASE | 4SHP20LX160P | ED1P50/60C+H4TXV02 | A97DSMV110C20 | 36,400 | $1,820 |
| No | 202483116 | AIREASE | 4SHP20LX160P | ED1P50/60C+H4TXV02 | A96DS2V110C20 | 36,400 | $1,820 |
| No | 202483118 | AIREASE | 4SHP20LX160P | ED1P50/60C+H4TXV02 | A96DS2V090C20 | 36,400 | $1,820 |
| No | 201846654 | AIREASE | 4SHP20LX160P | EAH1P60D+H4TXV03 | A97USMV135D20 | 36,600 | $1,830 |
| No | 201846653 | AIREASE | 4SHP20LX160P | EAH1P60D+H4TXV03 | A96US2V135D20 | 36,600 | $1,830 |
| No | 201848023 | AIREASE | 4SHP20LX124P | EAC4X30B | A97USMV070B12 | 13,000 | $650 |
| No | 10077413 | AIREASE | 4SHP20LX124P | EC4X36B | A96US2V045B12 | 13,000 | $650 |
| No | 10077414 | AIREASE | 4SHP20LX124P | EC4X36B | A96US2V070B12 | 13,000 | $650 |
| No | 201846651 | AIREASE | 4SHP20LX148P | EAH1P60D+H4TXV03 | A97USMV135D20 | 29,200 | $1,460 |
| No | 202760848 | AIREASE | 4SHP20LX124P | BCE7S30M | | 14,000 | $700 |
| No | 201848019 | AIREASE | 4SHP20LX124P | EA(C,U)1P30B+H4TXV01 | A97USMV070B12 | 13,000 | $650 |
| No | 201848018 | AIREASE | 4SHP20LX124P | EA(C,U)1P30B+H4TXV01 | A96US2V070B12 | 13,000 | $650 |
| No | 201848017 | AIREASE | 4SHP20LX124P | EA(C,U)1P30B+H4TXV01 | A96US2V045B12 | 13,000 | $650 |
| No | 202760852 | AIREASE | 4SHP20LX148P | BCE7S60M | | 26,400 | $1,320 |
| No | 201846649 | AIREASE | 4SHP20LX136P | EAH1P48C+H4TXV02 | A96US2V090C12 | 21,600 | $1,080 |
| No | 202760850 | AIREASE | 4SHP20LX136P | BCE7S42M | | 21,400 | $1,070 |
| No | 10616052 | AIREASE | 4SHP20LX124P | ED1P48B+H4TXV02 | A97DSMV070B12 | 14,700 | $735 |
| No | 10616050 | AIREASE | 4SHP20LX124P | ED1P48B+H4TXV02 | A96DS2V045B12 | 14,700 | $735 |
| No | 201846632 | AIREASE | 4SHP20LX124P | EAH1P30B+H4TXV01 | A96US2V045B12 | 14,400 | $720 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201846633 | AIREASE | 4SHP20LX124P | EAH1P30B+H4TXV01 | A96US2V070B12 | 14,400 | $720 |
| No | 202483119 | AIREASE | 4SHP20LX160P | ED1P50/60C+H4TXV02 | A97DSMV090C20 | 36,400 | $1,820 |
| No | 201846634 | AIREASE | 4SHP20LX124P | EAH1P30B+H4TXV01 | A97USMV070B12 | 14,400 | $720 |
| No | 202760846 | AIREASE | 4SHP20LX124P | BCE7S24M | | 13,600 | $680 |
| No | 202760854 | AIREASE | 4SHP20LX160P | BCE7S60M | | 36,200 | $1,810 |
| No | 208106689 | AIREASE | 4DHP2S24S-1P | DMD224S4-1P | | 13,500 | $675 |
| No | 208106762 | AIREASE | 4DHP2S36S-1P | D33C236S4-1P | | 23,000 | $1,150 |
| No | 208106764 | AIREASE | 4DHP2S36S-1P | DMD236S4-2P | | 27,000 | $1,350 |
| No | 208106763 | AIREASE | 4DHP2S48S-1P | D33C248S4-1P | | 28,000 | $1,400 |
| No | 208106765 | AIREASE | 4DHP2S48S-1P | DMD248S4-2P | | 29,000 | $1,450 |
| No | 208106686 | AIREASE | 4DHP2S24S-1P | D33C224S4-1P | | 15,600 | $780 |
| No | 208106685 | AIREASE | 4DHP2S18S-1P | D22C118S4-1P | | 12,000 | $600 |
| No | 207691842 | AIRGREAN | AG-MO36IR410AH | Heat pump without ducts | | 26,400 | $1,320 |
| No | 207691836 | AIRGREAN | AG-MO30IR410AH | Heat pump without ducts | | 20,000 | $1,000 |
| No | 207691837 | AIRGREAN | AG-MO30IR410AH | Heat pump with ducts | | 22,000 | $1,100 |
| No | 207691846 | AIRGREAN | AG-MO18IR410AH | Heat pump with ducts | | 14,800 | $740 |
| No | 207691839 | AIRGREAN | AG-MO48IR410AH | Heat pump without ducts | | 36,000 | $1,800 |
| No | 207691845 | AIRGREAN | AG-MO18IR410AH | Heat pump without ducts | | 14,400 | $720 |
| No | 208119678 | AIRLUX | AM4M36O/2022 | Heat pump without ducts | | 26,400 | $1,320 |
| No | 208119675 | AIRLUX | AM3M27O/2022 | Heat pump without ducts | | 20,000 | $1,000 |
| No | 208119676 | AIRLUX | AM3M27O/2022 | Heat pump with ducts | | 22,000 | $1,100 |
| No | 208119673 | AIRLUX | AM2M18O/2022 | Heat pump with ducts | | 14,800 | $740 |
| No | 208119672 | AIRLUX | AM2M18O/2022 | Heat pump without ducts | | 14,400 | $720 |
| No | 208119664 | Airlux | ASZ24O/2022 | AMM24I/2022 | | 18,000 | $900 |
| No | 208119667 | Airlux | ASZ18O/2022 | AMD18I | | 12,600 | $630 |
| No | 208119662 | Airlux | ASZ12O/2022 | AMM12I/2022 | | 8,200 | $410 |
| No | 208119661 | Airlux | ASZ09O/2022 | AMM09I/2022 | | 8,300 | $415 |
| No | 208119670 | Airlux | ASZ09O115/2022 | ASZ09I115/2022 | | 6,000 | $300 |
| No | 208119663 | Airlux | ASZ18O/2022 | AMM18I/2022 | | 14,000 | $700 |
| No | 208119671 | Airlux | ASZ12O115/2022 | ASZ12I115/2022 | | 8,400 | $420 |
| No | 209049224 | Airlux | ASZ48O/2022 | AMD48I | | 34,000 | $1,700 |
| No | 208119669 | Airlux | ASZ36O/2022 | AMD36I | | 25,000 | $1,250 |
| No | 208119668 | Airlux | ASZ24O/2022 | AMD24I | | 20,000 | $1,000 |
| No | 208119666 | Airlux | ASZ12O/2022 | AMD12I | | 9,300 | $465 |
| No | 208119665 | Airlux | ASZ09O/2022 | AMD09I | | 7,700 | $385 |
| No | 208119677 | AIRLUX | AM3M27O/2022 | Combination heat pumps with or without ducts | | 16,100 | $805 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208119674 | AIRLUX | AM2M18O/2022 | Combination heat pumps with or without ducts | | 11,800 | $590 |
| No | 203401044 | AIRLUX | ASZ18O | AMD18I | | 12,000 | $600 |
| No | 203401050 | AIRLUX | ASZ36O | AMD36I | | 27,600 | $1,380 |
| No | 203401043 | AIRLUX | ASZ24O | AMD24I | | 16,000 | $800 |
| No | 203401047 | AIRLUX | ASZ18O | AMM18I | | 10,400 | $520 |
| No | 203401048 | AIRLUX | ASZ09O | AMM09I | | 6,400 | $320 |
| No | 210819429 | AIRQUEST | DLCSRBH30AAK | DLFSABH30XBK | | 20,400 | $1,020 |
| No | 209852137 | AIRQUEST | DLCURAH60AAK | DLFUAAH60XAK | | 37,000 | $1,850 |
| No | 209852134 | AIRQUEST | DLCURAH48AAK | DLFUAAH48XAK | | 37,000 | $1,850 |
| No | 209852141 | AIRQUEST | DLCURAH36AAK | DLFUAAH36XAK | | 20,400 | $1,020 |
| No | 209852143 | AIRQUEST | DLCURAH30ABK | DLFUAAH30XAK | | 21,000 | $1,050 |
| No | 209852140 | AIRQUEST | DLCURAH30AAK | DLFUAAH30XAK | | 20,000 | $1,000 |
| No | 209852133 | AIRQUEST | DLCURAH24AAK | DLFUAAH24XAK | | 21,000 | $1,050 |
| No | 209852139 | AIRQUEST | DLCURAH18AAK | DLFUAAH18XAK | | 12,000 | $600 |
| No | 207643194 | AIRQUEST | DLCMRBH48EAK | Heat pump without ducts | | 31,000 | $1,550 |
| No | 207826642 | AIRQUEST | DLCLRCH58AAK | DLFLABH60XAK | | 34,000 | $1,700 |
| No | 207826641 | AIRQUEST | DLCLRCH48AAK | DLFLABH48XAK | | 37,400 | $1,870 |
| No | 208104327 | AIRQUEST | DLCSRBH36ABK | DLFSABH36XBK | | 25,600 | $1,280 |
| No | 207826643 | AIRQUEST | DLCLRCH36AAK | DLFLABH36XAK | | 25,600 | $1,280 |
| No | 207826612 | AIRQUEST | DLCSRBH24AAK | DLFSABH24XBK | | 16,200 | $810 |
| No | 208104328 | AIRQUEST | DLCSRBH30AAK11 | DLFSABH30XBK | | 19,200 | $960 |
| No | 206188341 | AIRQUEST | DLCLRBH48AAK | DLFLFAH48XAK | | 29,000 | $1,450 |
| No | 206188338 | AIRQUEST | DLCLRBH36AAK | DLFLFAH36XAK | | 22,000 | $1,100 |
| No | 206188339 | AIRQUEST | DLCLRBH36AAK | DLFLCAH36XAK | | 22,000 | $1,100 |
| No | 206188342 | AIRQUEST | DLCLRBH48AAK | DLFLCAH48XAK | | 29,000 | $1,450 |
| No | 206188343 | AIRQUEST | DLCLRBH48AAK | DLFLDAH48XAK | | 29,000 | $1,450 |
| No | 207202530 | AIRQUEST | DLCSRBH18AAK | EA*4X19L17A* | *80ES(N,L)0701412A* | 13,900 | $695 |
| No | 207202527 | AIRQUEST | DLCSRBH18AAK | EA*4X19L17A* | *80ES(N,L)0451712A* | 13,900 | $695 |
| No | 207202531 | AIRQUEST | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0701412A* | 14,600 | $730 |
| No | 207202529 | AIRQUEST | DLCSRBH18AAK | EA*4X25L17A* | *80ES(N,L)0451712A* | 13,800 | $690 |
| No | 207202528 | AIRQUEST | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0451712A* | 14,600 | $730 |
| No | 207202532 | AIRQUEST | DLCSRBH18AAK | EA*4X25L17A* | *80ES(N,L)0701412A* | 13,800 | $690 |
| No | 207202533 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X18L14** | *80ES(N,L)0701412A* | 14,700 | $735 |
| No | 207202534 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X24L14** | *80ES(N,L)0701412A* | 14,600 | $730 |
| No | 207202536 | AIRQUEST | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0701712A* | 14,700 | $735 |
| No | 207202535 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ES(N,L)0701412A* | 14,600 | $730 |
| No | 207202541 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ESU0401712A* | 14,500 | $725 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207202537 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ES(N,L)0701712A* | 14,700 | $735 |
| No | 207202539 | AIRQUEST | DLCSRBH18AAK | EA*4X24L17A* | *80ESU0401712A* | 14,500 | $725 |
| No | 207202546 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X18L14** | *92ESN0401410A* | 14,600 | $730 |
| No | 207202538 | AIRQUEST | DLCSRBH18AAK | EA*4X19L17A* | *80ESU0401712A* | 13,700 | $685 |
| No | 207202540 | AIRQUEST | DLCSRBH18AAK | EA*4X25L17A* | *80ESU0401712A* | 13,600 | $680 |
| No | 207202545 | AIRQUEST | DLCSRBH18AAK | EA*4X25L17A* | *92ESN0401410A* | 13,700 | $685 |
| No | 207202542 | AIRQUEST | DLCSRBH18AAK | EA*4X19L17A* | *92ESN0401410A* | 13,800 | $690 |
| No | 207202543 | AIRQUEST | DLCSRBH18AAK | EA*4X24L14A* | *92ESN0401410A* | 14,500 | $725 |
| No | 207202544 | AIRQUEST | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0401410A* | 14,500 | $725 |
| No | 207202547 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X24L14** | *92ESN0401410A* | 14,500 | $725 |
| No | 207202548 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0401410A* | 14,500 | $725 |
| No | 207202550 | AIRQUEST | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0401712A* | 14,600 | $730 |
| No | 207202549 | AIRQUEST | DLCSRBH18AAK | EA*4X19L17A* | *92ESN0401712A* | 13,900 | $695 |
| No | 207202551 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0401712A* | 14,600 | $730 |
| No | 207202552 | AIRQUEST | DLCSRBH18AAK | EA*4X19L17A* | *92ESN0601412A* | 14,000 | $700 |
| No | 207202554 | AIRQUEST | DLCSRBH18AAK | EA*4X25L17A* | *92ESN0601412A* | 13,800 | $690 |
| No | 207202553 | AIRQUEST | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0601412A* | 14,600 | $730 |
| No | 207202555 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X18L14** | *92ESN0601412A* | 14,700 | $735 |
| No | 207202556 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X24L14** | *92ESN0601412A* | 14,600 | $730 |
| No | 207202557 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0601412A* | 14,600 | $730 |
| No | 207202558 | AIRQUEST | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0801716A* | 14,700 | $735 |
| No | 207202559 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0801716A* | 14,700 | $735 |
| No | 207202560 | AIRQUEST | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0261410A* | 14,100 | $705 |
| No | 207202562 | AIRQUEST | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0261410A* | 13,900 | $695 |
| No | 207202561 | AIRQUEST | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0261410A* | 14,700 | $735 |
| No | 207202563 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X18L14** | *95ESN0261410A* | 14,800 | $740 |
| No | 207202564 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X24L14** | *95ESN0261410A* | 14,700 | $735 |
| No | 207202565 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0261410A* | 14,700 | $735 |
| No | 207202566 | AIRQUEST | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0401410A* | 13,900 | $695 |
| No | 207202568 | AIRQUEST | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0401410A* | 14,600 | $730 |
| No | 207202567 | AIRQUEST | DLCSRBH18AAK | EA*4X24L14A* | *95ESN0401410A* | 14,600 | $730 |
| No | 207202569 | AIRQUEST | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0401410A* | 13,800 | $690 |
| No | 207202572 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0401410A* | 14,600 | $730 |
| No | 207202573 | AIRQUEST | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0401712A* | 13,800 | $690 |
| No | 207202574 | AIRQUEST | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0401712A* | 14,600 | $730 |
| No | 207202570 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X18L14** | *95ESN0401410A* | 14,700 | $735 |
| No | 207202571 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X24L14** | *95ESN0401410A* | 14,600 | $730 |
| No | 207202585 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESU0401712A* | 14,600 | $730 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207202581 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0601714A* | 14,700 | $735 |
| No | 207202586 | AIRQUEST | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0401410A* | 13,900 | $695 |
| No | 207202584 | AIRQUEST | DLCSRBH18AAK | EA*4X25L17A* | *95ESU0401712A* | 13,800 | $690 |
| No | 207202583 | AIRQUEST | DLCSRBH18AAK | EA*4X24L17A* | *95ESU0401712A* | 14,600 | $730 |
| No | 207202582 | AIRQUEST | DLCSRBH18AAK | EA*4X19L17A* | *95ESU0401712A* | 13,800 | $690 |
| No | 207202576 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0401712A* | 14,600 | $730 |
| No | 207202578 | AIRQUEST | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0601412A* | 14,900 | $745 |
| No | 207202580 | AIRQUEST | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0601714A* | 14,000 | $700 |
| No | 207202579 | AIRQUEST | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0601714A* | 14,100 | $705 |
| No | 207202575 | AIRQUEST | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0401712A* | 13,700 | $685 |
| No | 207202577 | AIRQUEST | DLCSRBH18AAK | EA*4X24L14A* | *95ESN0601412A* | 14,900 | $745 |
| No | 207098930 | AIRQUEST | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *92ESN0801716A* | 15,400 | $770 |
| No | 207098929 | AIRQUEST | DLCSRBH24AAK | EA*4X36L17A* | *92ESN0801716A* | 15,400 | $770 |
| No | 207098931 | AIRQUEST | DLCSRBH24AAK | EA*4X30L17A* | *92ESN0801716A* | 15,400 | $770 |
| No | 207098933 | AIRQUEST | DLCSRBH24AAK | EA*4X24L14A* | *95ESN0261410A* | 15,800 | $790 |
| No | 207098934 | AIRQUEST | DLCSRBH24AAK | EA*4X30L14A* | *95ESN0261410A* | 15,500 | $775 |
| No | 207098935 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X30L14** | *95ESN0261410A* | 15,500 | $775 |
| No | 207099006 | AIRQUEST | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0401410A* | 15,300 | $765 |
| No | 207098943 | AIRQUEST | DLCSRBH24AAK | EA*4X36L17A* | *95ESN0401712A* | 15,500 | $775 |
| No | 207098942 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESN0401712A* | 15,600 | $780 |
| No | 207098945 | AIRQUEST | DLCSRBH24AAK | EA*4X30L17A* | *95ESN0401712A* | 15,600 | $780 |
| No | 207098998 | AIRQUEST | DLCSRBH24AAK | EA*4X25L17A* | *95ESN0401712A* | 15,200 | $760 |
| No | 207099002 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X36L21** | *95ESN0401712A* | 15,600 | $780 |
| No | 207098944 | AIRQUEST | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESN0401712A* | 15,600 | $780 |
| No | 207099000 | AIRQUEST | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0401712A* | 15,300 | $765 |
| No | 207098999 | AIRQUEST | DLCSRBH24AAK | EA*4X36L21A* | *95ESN0401712A* | 15,500 | $775 |
| No | 207099001 | AIRQUEST | DLCSRBH24AAK | EA*4X37L21A* | *95ESN0401712A* | 15,200 | $760 |
| No | 207098947 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X24L14** | *95ESN0601412A* | 15,600 | $780 |
| No | 207098949 | AIRQUEST | DLCSRBH24AAK | EA*4X30L14A* | *95ESN0601412A* | 15,600 | $780 |
| No | 207098948 | AIRQUEST | DLCSRBH24AAK | EA*4X24L14A* | *95ESN0601412A* | 15,800 | $790 |
| No | 207098950 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X30L14** | *95ESN0601412A* | 15,500 | $775 |
| No | 207098990 | AIRQUEST | DLCSRBH24AAK | EA*4X24L17A* | *95ESN0601412A* | 15,800 | $790 |
| No | 207098993 | AIRQUEST | DLCSRBH24AAK | EA*4X30L17A* | *95ESN0601412A* | 15,600 | $780 |
| No | 207098991 | AIRQUEST | DLCSRBH24AAK | EA*4X25L17A* | *95ESN0601412A* | 15,200 | $760 |
| No | 207098994 | AIRQUEST | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0601412A* | 15,300 | $765 |
| No | 207098992 | AIRQUEST | DLCSRBH24AAK | EA*4X36L17A* | *95ESN0601412A* | 15,500 | $775 |
| No | 207098995 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X24L17** | *95ESN0601412A* | 15,600 | $780 |
| No | 207098953 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESN0601714A* | 15,500 | $775 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207098996 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESN0601412A* | 15,500 | $775 |
| No | 207098997 | AIRQUEST | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESN0601412A* | 15,500 | $775 |
| No | 207098952 | AIRQUEST | DLCSRBH24AAK | EA*4X24L17A* | *95ESN0601714A* | 15,800 | $790 |
| No | 207098951 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X24L17** | *95ESN0601714A* | 15,600 | $780 |
| No | 207098986 | AIRQUEST | DLCSRBH24AAK | EA*4X36L21A* | *95ESN0601714A* | 15,400 | $770 |
| No | 207098954 | AIRQUEST | DLCSRBH24AAK | EA*4X36L17A* | *95ESN0601714A* | 15,400 | $770 |
| No | 207098955 | AIRQUEST | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESN0601714A* | 15,500 | $775 |
| No | 207098985 | AIRQUEST | DLCSRBH24AAK | EA*4X25L17A* | *95ESN0601714A* | 15,200 | $760 |
| No | 207098956 | AIRQUEST | DLCSRBH24AAK | EA*4X30L17A* | *95ESN0601714A* | 15,500 | $775 |
| No | 207098908 | AIRQUEST | DLCSRBH24AAK | EA*4X36L17A* | *95ESU0401712A* | 15,400 | $770 |
| No | 207098988 | AIRQUEST | DLCSRBH24AAK | EA*4X37L21A* | *95ESN0601714A* | 15,100 | $755 |
| No | 207098987 | AIRQUEST | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0601714A* | 15,200 | $760 |
| No | 207098906 | AIRQUEST | DLCSRBH24AAK | EA*4X24L17A* | *95ESU0401712A* | 15,700 | $785 |
| No | 207098989 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X36L21** | *95ESN0601714A* | 15,500 | $775 |
| No | 207098905 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X24L17** | *95ESU0401712A* | 15,600 | $780 |
| No | 207098907 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESU0401712A* | 15,500 | $775 |
| No | 207098909 | AIRQUEST | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESU0401712A* | 15,500 | $775 |
| No | 207098960 | AIRQUEST | DLCSRBH24AAK | EA*4X30L14A* | *96VTN0401410A* | 15,600 | $780 |
| No | 207098910 | AIRQUEST | DLCSRBH24AAK | EA*4X30L17A* | *95ESU0401712A* | 15,500 | $775 |
| No | 207098961 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X30L14** | *96VTN0401410A* | 15,600 | $780 |
| No | 207098972 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X30L14** | *96VTN0601412A* | 15,600 | $780 |
| No | 207098971 | AIRQUEST | DLCSRBH24AAK | EA*4X30L14A* | *96VTN0601412A* | 15,600 | $780 |
| No | 207098965 | AIRQUEST | DLCSRBH24AAK | EA*4X36L17A* | *96VTN0401712A* | 15,500 | $775 |
| No | 207098974 | AIRQUEST | DLCSRBH24AAK | EA*4X24L17A* | *96VTN0601714A* | 15,800 | $790 |
| No | 207098973 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X24L17** | *96VTN0601714A* | 15,600 | $780 |
| No | 207098981 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X30L17** | *96VTN0801716A* | 15,500 | $775 |
| No | 207098975 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X30L17** | *96VTN0601714A* | 15,500 | $775 |
| No | 207098977 | AIRQUEST | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *96VTN0601714A* | 15,500 | $775 |
| No | 207098978 | AIRQUEST | DLCSRBH24AAK | EA*4X30L17A* | *96VTN0601714A* | 15,500 | $775 |
| No | 207098976 | AIRQUEST | DLCSRBH24AAK | EA*4X36L17A* | *96VTN0601714A* | 15,400 | $770 |
| No | 207098980 | AIRQUEST | DLCSRBH24AAK | EA*4X24L17A* | *96VTN0801716A* | 15,700 | $785 |
| No | 207098979 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X24L17** | *96VTN0801716A* | 15,600 | $780 |
| No | 207098982 | AIRQUEST | DLCSRBH24AAK | EA*4X36L17A* | *96VTN0801716A* | 15,400 | $770 |
| No | 207202522 | AIRQUEST | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207202523 | AIRQUEST | DLCSRBH18AAK | EA*4X25L17A* | *80ES(N,L)0451412A* | 13,800 | $690 |
| No | 207202525 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X24L14** | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207202524 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X18L14** | *80ES(N,L)0451412A* | 14,700 | $735 |
| No | 207202526 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ES(N,L)0451412A* | 14,600 | $730 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207202589 | AIRQUEST | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0401410A* | 13,900 | $695 |
| No | 207202587 | AIRQUEST | DLCSRBH18AAK | EA*4X24L14A* | *96VTN0401410A* | 14,700 | $735 |
| No | 207202588 | AIRQUEST | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0401410A* | 14,700 | $735 |
| No | 207202590 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X18L14** | *96VTN0401410A* | 14,800 | $740 |
| No | 207202592 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X24L17** | *96VTN0401410A* | 14,700 | $735 |
| No | 207202591 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X24L14** | *96VTN0401410A* | 14,700 | $735 |
| No | 207202593 | AIRQUEST | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0401712A* | 13,900 | $695 |
| No | 207202600 | AIRQUEST | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0601412A* | 13,800 | $690 |
| No | 207202594 | AIRQUEST | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0401712A* | 14,600 | $730 |
| No | 207202595 | AIRQUEST | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0401712A* | 13,800 | $690 |
| No | 207202596 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X24L17** | *96VTN0401712A* | 14,600 | $730 |
| No | 207202597 | AIRQUEST | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0601412A* | 13,800 | $690 |
| No | 207202598 | AIRQUEST | DLCSRBH18AAK | EA*4X24L14A* | *96VTN0601412A* | 14,600 | $730 |
| No | 207202599 | AIRQUEST | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0601412A* | 14,600 | $730 |
| No | 207202601 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X18L14** | *96VTN0601412A* | 14,700 | $735 |
| No | 207202602 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X24L14** | *96VTN0601412A* | 14,600 | $730 |
| No | 207202604 | AIRQUEST | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0601714A* | 14,100 | $705 |
| No | 207202603 | AIRQUEST | DLCSRBH18AAK | EN(A,D)4X24L17** | *96VTN0601412A* | 14,600 | $730 |
| No | 207202605 | AIRQUEST | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0601714A* | 14,700 | $735 |
| No | 207202606 | AIRQUEST | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0601714A* | 13,900 | $695 |
| No | 207202607 | AIRQUEST | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0801716A* | 13,800 | $690 |
| No | 207202515 | AIRQUEST | DLCSRBH18AAK | FMA4X18**AL* | | 15,000 | $750 |
| No | 207202516 | AIRQUEST | DLCSRBH18AAK | FM(C,U)4Z18**AL* | | 15,000 | $750 |
| No | 207202171 | AIRQUEST | DLCSRBH18AAK | FVM4X24***L | | 13,400 | $670 |
| No | 207202517 | AIRQUEST | DLCSRBH18AAK | FXM4X18**AL | | 14,500 | $725 |
| No | 207098881 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X24L14** | *80ES(N,L)0451412A* | 15,600 | $780 |
| No | 207098882 | AIRQUEST | DLCSRBH24AAK | EA*4X24L14A* | *80ES(N,L)0451412A* | 15,700 | $785 |
| No | 207098884 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X30L14** | *80ES(N,L)0451412A* | 15,500 | $775 |
| No | 207098883 | AIRQUEST | DLCSRBH24AAK | EA*4X30L14A* | *80ES(N,L)0451412A* | 15,500 | $775 |
| No | 207098892 | AIRQUEST | DLCSRBH24AAK | EA*4X36L17A* | *80ES(N,L)0701712A* | 15,400 | $770 |
| No | 207098885 | AIRQUEST | DLCSRBH24AAK | EA*4X36L17A* | *80ES(N,L)0451712A* | 15,500 | $775 |
| No | 207098886 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X24L14** | *80ES(N,L)0701412A* | 15,600 | $780 |
| No | 207098889 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X30L14** | *80ES(N,L)0701412A* | 15,500 | $775 |
| No | 207098887 | AIRQUEST | DLCSRBH24AAK | EA*4X24L14A* | *80ES(N,L)0701412A* | 15,700 | $785 |
| No | 207098888 | AIRQUEST | DLCSRBH24AAK | EA*4X30L14A* | *80ES(N,L)0701412A* | 15,500 | $775 |
| No | 207098894 | AIRQUEST | DLCSRBH24AAK | EA*4X30L17A* | *80ES(N,L)0701712A* | 15,500 | $775 |
| No | 207098891 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X30L17** | *80ES(N,L)0701712A* | 15,400 | $770 |
| No | 207098890 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X24L17** | *80ES(N,L)0701712A* | 15,600 | $780 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207098899 | AIRQUEST | DLCSRBH24AAK | EA*4X30L17A* | *80ESU0401712A* | 15,400 | $770 |
| No | 207098893 | AIRQUEST | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *80ES(N,L)0701712A* | 15,400 | $770 |
| No | 207098896 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X30L17** | *80ESU0401712A* | 15,400 | $770 |
| No | 207098904 | AIRQUEST | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *80ESU0601716A | 15,500 | $775 |
| No | 207098897 | AIRQUEST | DLCSRBH24AAK | EA*4X36L17A* | *80ESU0401712A* | 15,300 | $765 |
| No | 207098895 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X24L17** | *80ESU0401712A* | 15,500 | $775 |
| No | 207098898 | AIRQUEST | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *80ESU0401712A* | 15,400 | $770 |
| No | 207098900 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X24L17** | *80ESU0601716A | 15,600 | $780 |
| No | 207098902 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X30L17** | *80ESU0601716A | 15,500 | $775 |
| No | 207098901 | AIRQUEST | DLCSRBH24AAK | EA*4X24L17A* | *80ESU0601716A | 15,700 | $785 |
| No | 207098903 | AIRQUEST | DLCSRBH24AAK | EA*4X36L17A* | *80ESU0601716A | 15,400 | $770 |
| No | 207098922 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X24L14** | *92ESN0601714A* | 15,500 | $775 |
| No | 207098917 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X24L14** | *92ESN0601412A* | 15,600 | $780 |
| No | 207098918 | AIRQUEST | DLCSRBH24AAK | EA*4X24L14A* | *92ESN0601412A* | 15,700 | $785 |
| No | 207098920 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X30L14** | *92ESN0601412A* | 15,500 | $775 |
| No | 207098928 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X30L17** | *92ESN0801716A* | 15,400 | $770 |
| No | 207098919 | AIRQUEST | DLCSRBH24AAK | EA*4X30L14A* | *92ESN0601412A* | 15,500 | $775 |
| No | 207098923 | AIRQUEST | DLCSRBH24AAK | EA*4X24L14A* | *92ESN0601714A* | 15,700 | $785 |
| No | 207098924 | AIRQUEST | DLCSRBH24AAK | EA*4X30L14A* | *92ESN0601714A* | 15,500 | $775 |
| No | 207098927 | AIRQUEST | DLCSRBH24AAK | EA*4X24L17A* | *92ESN0801716A* | 15,700 | $785 |
| No | 207098926 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X24L17** | *92ESN0801716A* | 15,500 | $775 |
| No | 207098925 | AIRQUEST | DLCSRBH24AAK | EN(A,D)4X30L14** | *92ESN0601714A* | 15,400 | $770 |
| No | 207098983 | AIRQUEST | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *96VTN0801716A* | 15,500 | $775 |
| No | 207098876 | AIRQUEST | DLCSRBH24AAK | FXM4X24**AL | | 15,500 | $775 |
| No | 207098984 | AIRQUEST | DLCSRBH24AAK | EA*4X30L17A* | *96VTN0801716A* | 15,500 | $775 |
| No | 207098878 | AIRQUEST | DLCSRBH24AAK | FMA4X24**AL* | | 16,000 | $800 |
| No | 207098879 | AIRQUEST | DLCSRBH24AAK | FM(C,U)4Z24**AL* | | 16,100 | $805 |
| No | 207198938 | AIRQUEST | DLCSRBH30AAK | EA*4X30L14A* | *80ES(N,L)0451412A* | 19,200 | $960 |
| No | 207198939 | AIRQUEST | DLCSRBH30AAK | EN(A,D)4X30L14** | *80ES(N,L)0451412A* | 19,200 | $960 |
| No | 207198941 | AIRQUEST | DLCSRBH30AAK | EN(A,D)4X30L17** | *80ES(N,L)0451712A* | 19,100 | $955 |
| No | 207198940 | AIRQUEST | DLCSRBH30AAK | EA*4X30L17A* | *80ES(N,L)0451712A* | 19,100 | $955 |
| No | 207198942 | AIRQUEST | DLCSRBH30AAK | EA*4X30L14A* | *80ES(N,L)0701412A* | 19,100 | $955 |
| No | 207198943 | AIRQUEST | DLCSRBH30AAK | EN(A,D)4X30L14** | *80ES(N,L)0701412A* | 19,100 | $955 |
| No | 207198944 | AIRQUEST | DLCSRBH30AAK | EA*4X30L17A* | *80ES(N,L)0701716A* | 19,300 | $965 |
| No | 207198945 | AIRQUEST | DLCSRBH30AAK | EN(A,D)4X30L17** | *80ES(N,L)0701716A* | 19,300 | $965 |
| No | 207198946 | AIRQUEST | DLCSRBH30AAK | EA*4X36L21A* | *80ES(N,L)0702116A* | 19,000 | $950 |
| No | 207198948 | AIRQUEST | DLCSRBH30AAK | EN(A,D)4X36L21** | *80ES(N,L)0902116A* | 19,300 | $965 |
| No | 207198947 | AIRQUEST | DLCSRBH30AAK | EN(A,D)4X36L21** | *80ES(N,L)0702116A* | 19,100 | $955 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207198949 | AIRQUEST | DLCSRBH30AAK | EA*4X30L17A* | *80ESU0401712A* | 19,000 | $950 |
| No | 207198950 | AIRQUEST | DLCSRBH30AAK | EN(A,D)4X30L17** | *80ESU0401712A* | 19,000 | $950 |
| No | 207198952 | AIRQUEST | DLCSRBH30AAK | EN(A,D)4X30L14** | *92ESN0601412A* | 19,200 | $960 |
| No | 207198951 | AIRQUEST | DLCSRBH30AAK | EA*4X30L14A* | *92ESN0601412A* | 19,200 | $960 |
| No | 207198953 | AIRQUEST | DLCSRBH30AAK | EA*4X30L17A* | *92ESN0601714A* | 19,100 | $955 |
| No | 207198954 | AIRQUEST | DLCSRBH30AAK | EN(A,D)4X30L17** | *92ESN0601714A* | 19,100 | $955 |
| No | 207198955 | AIRQUEST | DLCSRBH30AAK | EA*4X30L17A* | *92ESN0801716A* | 19,100 | $955 |
| No | 207198974 | AIRQUEST | DLCSRBH30AAK | END4X42L17** | *95ESN0401410A* | 19,200 | $960 |
| No | 207198973 | AIRQUEST | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0401410A* | 19,100 | $955 |
| No | 207198956 | AIRQUEST | DLCSRBH30AAK | EN(A,D)4X30L17** | *92ESN0801716A* | 19,100 | $955 |
| No | 207198976 | AIRQUEST | DLCSRBH30AAK | EA*4X36L21A* | *95ESN0401712A* | 19,300 | $965 |
| No | 207198975 | AIRQUEST | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0401712A* | 19,300 | $965 |
| No | 207198979 | AIRQUEST | DLCSRBH30AAK | EA*4X42L21A* | *95ESN0401712A* | 19,200 | $960 |
| No | 207198981 | AIRQUEST | DLCSRBH30AAK | END4X42L17** | *95ESN0401712A* | 19,100 | $955 |
| No | 207198977 | AIRQUEST | DLCSRBH30AAK | EA*4X36L17A* | *95ESN0401712A* | 19,300 | $965 |
| No | 207198978 | AIRQUEST | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0401712A* | 19,000 | $950 |
| No | 207198980 | AIRQUEST | DLCSRBH30AAK | EA*4X43L21A* | *95ESN0401712A* | 18,700 | $935 |
| No | 207198984 | AIRQUEST | DLCSRBH30AAK | EA*4X36L17A* | *95ESN0601412A* | 19,200 | $960 |
| No | 207198985 | AIRQUEST | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0601412A* | 19,000 | $950 |
| No | 207198982 | AIRQUEST | DLCSRBH30AAK | EA*4X30L14A* | *95ESN0601412A* | 19,300 | $965 |
| No | 207198983 | AIRQUEST | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0601412A* | 19,300 | $965 |
| No | 207198986 | AIRQUEST | DLCSRBH30AAK | EN(A,D)4X30L14** | *95ESN0601412A* | 19,300 | $965 |
| No | 207198987 | AIRQUEST | DLCSRBH30AAK | EN(A,D,W)4X36L17** | *95ESN0601412A* | 19,300 | $965 |
| No | 207198988 | AIRQUEST | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESN0601412A* | 19,300 | $965 |
| No | 207198989 | AIRQUEST | DLCSRBH30AAK | END4X42L17** | *95ESN0601412A* | 19,100 | $955 |
| No | 207198990 | AIRQUEST | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0601714A* | 19,300 | $965 |
| No | 207198992 | AIRQUEST | DLCSRBH30AAK | EA*4X36L21A* | *95ESN0601714A* | 19,200 | $960 |
| No | 207198991 | AIRQUEST | DLCSRBH30AAK | EA*4X36L17A* | *95ESN0601714A* | 19,200 | $960 |
| No | 207198993 | AIRQUEST | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0601714A* | 19,000 | $950 |
| No | 207198994 | AIRQUEST | DLCSRBH30AAK | EA*4X42L21A* | *95ESN0601714A* | 19,100 | $955 |
| No | 207198995 | AIRQUEST | DLCSRBH30AAK | EA*4X37L21A* | *95ESN0601714A* | 18,700 | $935 |
| No | 207198996 | AIRQUEST | DLCSRBH30AAK | EA*4X43L21A* | *95ESN0601714A* | 18,700 | $935 |
| No | 207198997 | AIRQUEST | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESN0601714A* | 19,200 | $960 |
| No | 207198998 | AIRQUEST | DLCSRBH30AAK | EN(A,D)4X36L21** | *95ESN0601714A* | 19,200 | $960 |
| No | 207198999 | AIRQUEST | DLCSRBH30AAK | EN(A,D,W)4X36L17** | *95ESN0601714A* | 19,200 | $960 |
| No | 207199000 | AIRQUEST | DLCSRBH30AAK | END4X42L17** | *95ESN0601714A* | 19,000 | $950 |
| No | 207199001 | AIRQUEST | DLCSRBH30AAK | EN(A,D,W)4X42L21** | *95ESN0601714A* | 19,100 | $955 |
| No | 207198957 | AIRQUEST | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0801716A* | 19,300 | $965 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207198959 | AIRQUEST | DLCSRBH30AAK | EA*4X36L21A* | *95ESN0802120A* | 19,100 | $955 |
| No | 207198958 | AIRQUEST | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESN0801716A* | 19,300 | $965 |
| No | 207198962 | AIRQUEST | DLCSRBH30AAK | EA*4X30L17A* | *96VTN0401712A* | 19,300 | $965 |
| No | 207198960 | AIRQUEST | DLCSRBH30AAK | EA*4X30L17A* | *95ESU0401712A* | 19,000 | $950 |
| No | 207198961 | AIRQUEST | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESU0401712A* | 19,000 | $950 |
| No | 207198963 | AIRQUEST | DLCSRBH30AAK | EN(A,D)4X30L14** | *96VTN0601412A* | 19,300 | $965 |
| No | 207198964 | AIRQUEST | DLCSRBH30AAK | EA*4X30L17A* | *96VTN0601714A* | 19,100 | $955 |
| No | 207198965 | AIRQUEST | DLCSRBH30AAK | EN(A,D)4X30L17** | *96VTN0601714A* | 19,100 | $955 |
| No | 207198966 | AIRQUEST | DLCSRBH30AAK | EA*4X30L17A* | *96VTN0801716A* | 19,100 | $955 |
| No | 207198967 | AIRQUEST | DLCSRBH30AAK | EN(A,D)4X30L17** | *96VTN0801716A* | 19,100 | $955 |
| No | 207198968 | AIRQUEST | DLCSRBH30AAK | EA*4X36L21A* | *96VTN0802120A* | 18,800 | $940 |
| No | 207198970 | AIRQUEST | DLCSRBH30AAK | EA*4X36L21A* | *96VTN1002120A* | 18,800 | $940 |
| No | 207198969 | AIRQUEST | DLCSRBH30AAK | EN(A,D)4X36L21** | *96VTN0802120A* | 19,000 | $950 |
| No | 207198925 | AIRQUEST | DLCSRBH30AAK | FVM4X36***L | | 19,200 | $960 |
| No | 207200377 | AIRQUEST | DLCSRBH30AAK | EN(A,D)4X36L21** | *96VTN1002120A* | 20,800 | $1,040 |
| No | 207198936 | AIRQUEST | DLCSRBH30AAK | FXM4X30**AL | | 18,800 | $940 |
| No | 207198935 | AIRQUEST | DLCSRBH30AAK | FMA4X30**AL* | | 19,400 | $970 |
| No | 207198937 | AIRQUEST | DLCSRBH30AAK | FM(C,U)4Z30**AL* | | 19,200 | $960 |
| No | 207198933 | AIRQUEST | DLCSRBH30AAK | FEM4P30**AL | | 19,100 | $955 |
| No | 207198934 | AIRQUEST | DLCSRBH30AAK | FEM4X30**BL | | 19,100 | $955 |
| No | 207202521 | AIRQUEST | DLCSRBH18AAK | EA*4X24L14A* | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207202518 | AIRQUEST | DLCSRBH18AAK | FEM4P18**AL | | 14,700 | $735 |
| No | 207202519 | AIRQUEST | DLCSRBH18AAK | FEM4X18**BL | | 14,700 | $735 |
| No | 207202520 | AIRQUEST | DLCSRBH18AAK | EA*4X19L17A* | *80ES(N,L)0451412A* | 13,800 | $690 |
| No | 206188340 | AIRQUEST | DLCLRBH36AAK | DLFLDAH36XAK | | 27,000 | $1,350 |
| No | 207643180 | AIRQUEST | DLCMHBH24CAK | Heat pump with ducts | | 18,500 | $925 |
| No | 207643181 | AIRQUEST | DLCMHBH24CAK | Combination heat pumps with or without ducts | | 15,900 | $795 |
| No | 207643195 | AIRQUEST | DLCMRBH48EAK | Heat pump with ducts | | 30,400 | $1,520 |
| No | 207643177 | AIRQUEST | DLCMRBH18BAK | Heat pump with ducts | | 11,800 | $590 |
| No | 207643196 | AIRQUEST | DLCMRBH48EAK | Combination heat pumps with or without ducts | | 30,600 | $1,530 |
| No | 207643178 | AIRQUEST | DLCMRBH18BAK | Combination heat pumps with or without ducts | | 11,800 | $590 |
| No | 207643179 | AIRQUEST | DLCMHBH24CAK | Heat pump without ducts | | 13,300 | $665 |
| No | 207643186 | AIRQUEST | DLCMRBH36DAK | Heat pump without ducts | | 24,000 | $1,200 |
| No | 207643176 | AIRQUEST | DLCMRBH18BAK | Heat pump without ducts | | 11,800 | $590 |
| No | 206350481 | AIRQUEST | DLCSRBH09AAK | DLFSCAH09XAK | | 6,100 | $305 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206350482 | AIRQUEST | DLCSRBH09AAK | DLFSDAH09XAK | | 6,400 | $320 |
| No | 206396158 | AIRQUEST | DLCSRBH12AAK | DLFSHAH12XAK | | 7,500 | $375 |
| No | 206361915 | AIRQUEST | DLCSRBH12AAK | DLFSHBH12XAK | | 7,300 | $365 |
| No | 206350484 | AIRQUEST | DLCSRBH12AAK | DLFSDAH12XAK | | 8,300 | $415 |
| No | 206396159 | AIRQUEST | DLCSRAH12AAK | DLFSHBH12XAK | | 7,500 | $375 |
| No | 206396162 | AIRQUEST | DLCSRAH24AAK | DLFSHBH24XAK | | 15,000 | $750 |
| No | 206396163 | AIRQUEST | DLCSRBH24AAK | DLFSHAH24XAK | | 15,000 | $750 |
| No | 206361917 | AIRQUEST | DLCSRBH24AAK | DLFSHBH24XAK | | 17,000 | $850 |
| No | 206361913 | AIRQUEST | DLCSRBH12AAJ | DLFSHBH12XAJ | | 8,200 | $410 |
| No | 206361916 | AIRQUEST | DLCSRBH18AAK | DLFSHBH18XAK | | 11,100 | $555 |
| No | 206361914 | AIRQUEST | DLCSRBH09AAK | DLFSHBH09XAK | | 7,400 | $370 |
| No | 206350483 | AIRQUEST | DLCSRBH12AAK | DLFSCAH12XAK | | 7,900 | $395 |
| No | 206350485 | AIRQUEST | DLCSRBH12AAK | DLFSFAH12XAK | | 8,400 | $420 |
| No | 205767367 | AIRQUEST | DLCLRBH36AAK | DLFLAAH36XAK | | 25,000 | $1,250 |
| No | 205767368 | AIRQUEST | DLCLRBH48AAK | DLFLAAH48XAK | | 36,000 | $1,800 |
| No | 203966592 | AIRQUEST | DLCLRAH36AAK | DLFLFAH36XAK | | 25,400 | $1,270 |
| No | 203966588 | AIRQUEST | DLCLRAH36AAK | DLFLCAH36XAK | | 25,200 | $1,260 |
| No | 203966599 | AIRQUEST | DLCLRAH36AAK | DLFLDAH36XAK | | 27,600 | $1,380 |
| No | 211034514 | Allied | 4DHV2S12S-1L | DWH212S4-*L | | 7,800 | $390 |
| No | 211034513 | Allied | 4DHV2S09S-1L | DWH209S4-*L | | 6,300 | $315 |
| No | 211034493 | Allied | 4DHP2S12S-1L | DWM212S4-*L | | 8,400 | $420 |
| No | 211034518 | Allied | 4DHV2S24S-1P | DWH224S4-*P | | 16,500 | $825 |
| No | 211034517 | Allied | 4DHV2S18S-1P | DWH218S4-*P | | 11,400 | $570 |
| No | 211034516 | Allied | 4DHV2S12S-1P | DWH212S4-*P | | 7,000 | $350 |
| No | 211034515 | Allied | 4DHV2S09S-1P | DWH209S4-*P | | 6,000 | $300 |
| No | 211034512 | Allied | 4DHP2S48S-1P | D33C248S4-*P | | 30,000 | $1,500 |
| No | 211034511 | Allied | 4DHP2S36S-1P | D33C236S4-*P | | 23,000 | $1,150 |
| No | 211034510 | Allied | 4DHP2S24S-1P | D33C224S4-*P | | 19,000 | $950 |
| No | 211034509 | Allied | 4DHP2S18S-1P | D22C118S4-*P | | 12,000 | $600 |
| No | 211034508 | Allied | 4DHP2S12S-1P | D22C112S4-*P | | 8,900 | $445 |
| No | 211034507 | Allied | 4DHPS209S-1P | D22C109S4-*P | | 7,500 | $375 |
| No | 211034506 | Allied | 4DHP2S48S-1P | DMD248S4-*P | | 34,000 | $1,700 |
| No | 211034505 | Allied | 4DHP2S36S-1P | DMD236S4-*P | | 25,000 | $1,250 |
| No | 211034504 | Allied | 4DHP2S24S-1P | DMD224S4-*P | | 20,000 | $1,000 |
| No | 211034503 | Allied | 4DHP2S18S-1P | DMD218S4-*P | | 12,600 | $630 |
| No | 211034502 | Allied | 4DHP2S12S-1P | DMD212S4-*P | | 9,300 | $465 |
| No | 211034501 | Allied | 4DHPS209S-1P | DMD209S4-*P | | 7,700 | $385 |
| No | 211034498 | Allied | 4DHP2S30S-1P | DWM230S4-*P | | 19,000 | $950 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211034497 | Allied | 4DHP2S24S-1P | DWM224S4-*P | | 16,200 | $810 |
| No | 211034496 | Allied | 4DHP2S18S-1P | DWM218S4-*P | | 14,900 | $745 |
| No | 211034495 | Allied | 4DHP2S12S-1P | DWM212S4-*P | | 9,000 | $450 |
| No | 211034494 | Allied | 4DHPS209S-1P | DWM209S4-*P | | 8,500 | $425 |
| No | 208106712 | ALLIED | 4DHV2S24S-1P | DWH224S4-1P | | 16,500 | $825 |
| No | 208106711 | ALLIED | 4DHV2S18S-1P | DWH218S4-1P | | 11,400 | $570 |
| No | 208106710 | ALLIED | 4DHV2S12S-1P | DWH212S4-1P | | 7,000 | $350 |
| No | 208106708 | ALLIED | 4DHV2S12S-1L | DWH212S4-1L | | 7,800 | $390 |
| No | 208106709 | ALLIED | 4DHV2S09S-1P | DWH209S4-1P | | 6,000 | $300 |
| No | 208106707 | ALLIED | 4DHV2S09S-1L | DWH209S4-1L | | 6,300 | $315 |
| No | 208106703 | ALLIED | 4DHPS209S-1P | DWM209S4-1P | | 8,500 | $425 |
| No | 208106706 | ALLIED | 4DHPS209S-1P | DMD209S4-1P | | 7,700 | $385 |
| No | 208106705 | ALLIED | 4DHPS209S-1P | D22C109S4-1P | | 7,500 | $375 |
| No | 208106791 | ALLIED | 4DHP2S36M-1P | Heat pump without ducts | | 26,800 | $1,340 |
| No | 208106788 | ALLIED | 4DHP2S30M-1P | Heat pump without ducts | | 21,000 | $1,050 |
| No | 208106789 | ALLIED | 4DHP2S30M-1P | Heat pump with ducts | | 22,000 | $1,100 |
| No | 208106655 | ALLIED | 4DHP2S24S-1P | DWM224S4-1P | | 16,200 | $810 |
| No | 208106786 | ALLIED | 4DHP2S24M-1P | Heat pump with ducts | | 21,600 | $1,080 |
| No | 208106785 | ALLIED | 4DHP2S24M-1P | Heat pump without ducts | | 20,400 | $1,020 |
| No | 208106661 | ALLIED | 4DHP2S18S-1P | DMD218S4-1P | | 12,600 | $630 |
| No | 208106654 | ALLIED | 4DHP2S18S-1P | DWM218S4-1P | | 14,900 | $745 |
| No | 208106783 | ALLIED | 4DHP2S18M-1P | Heat pump with ducts | | 14,800 | $740 |
| No | 208106782 | ALLIED | 4DHP2S18M-1P | Heat pump without ducts | | 14,300 | $715 |
| No | 208106653 | ALLIED | 4DHP2S12S-1P | DWM212S4-1P | | 9,000 | $450 |
| No | 208106660 | ALLIED | 4DHP2S12S-1P | DMD212S4-1P | | 9,300 | $465 |
| No | 208106657 | ALLIED | 4DHP2S12S-1P | D22C112S4-1P | | 8,900 | $445 |
| No | 208127266 | ALLIED | 4DHP2S12S-1L | DWM212S4-1L | | 8,400 | $420 |
| No | 206906811 | ALLIED | 4HP18V60P | E*1P50C+H4TXV03 | 96G2UH110CV20 | 39,000 | $1,950 |
| No | 206906810 | ALLIED | 4HP18V60P | E*1P50C+H4TXV03 | 96G2UH090CV20 | 39,500 | $1,975 |
| No | 206906809 | ALLIED | 4HP18V60P | E*1P50C+H4TXV03 | 96G1UH110CE20 | 39,000 | $1,950 |
| No | 206906806 | ALLIED | 4HP18V60P | E*1P50C+H4TXV03 | 92G1UH110CE20 | 39,000 | $1,950 |
| No | 206906805 | ALLIED | 4HP18V60P | E*1P50C+H4TXV03 | 80G2UH110CV20 | 39,000 | $1,950 |
| No | 206906804 | ALLIED | 4HP18V60P | E*1P50C+H4TXV03 | 80G2UH110CE20L | 39,500 | $1,975 |
| No | 206906803 | ALLIED | 4HP18V60P | E*1P50C+H4TXV03 | 80G2UH110CE20 | 39,500 | $1,975 |
| No | 206906802 | ALLIED | 4HP18V60P | E*1P50C+H4TXV03 | 80G1UH110CE20 | 39,500 | $1,975 |
| No | 206906801 | ALLIED | 4HP18V60P | E*1P50C+H4TXV03 | 80G1UH100CE20X | 39,500 | $1,975 |
| No | 206906800 | ALLIED | 4HP18V60P | E*1P50C+H4TXV03 | 80G1UH090CE20 | 39,500 | $1,975 |
| No | 206906981 | ALLIED | 4HP18V60P | ED1P60D+H4TXV03 | EFV20DCA | 38,000 | $1,900 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206906936 | ALLIED | 4HP18V60P | EAC4X60D | EFV20DCA | 40,000 | $2,000 |
| No | 206906935 | ALLIED | 4HP18V60P | EAC4X60D | 96G2UH135DV20 | 40,000 | $2,000 |
| No | 206906934 | ALLIED | 4HP18V60P | EAC4X60D | 80G1UH135DE20 | 40,000 | $2,000 |
| No | 206906930 | ALLIED | 4HP18V60P | EAC4X60C | 96G1UH110CE20 | 37,800 | $1,890 |
| No | 206906923 | ALLIED | 4HP18V60P | EAC4X60C | 80G1UH110CE20 | 38,000 | $1,900 |
| No | 206906922 | ALLIED | 4HP18V60P | EAC4X60C | 80G1UH100CE20X | 38,000 | $1,900 |
| No | 206906921 | ALLIED | 4HP18V60P | EAC4X60C | 80G1UH090CE20 | 38,000 | $1,900 |
| No | 206906874 | ALLIED | 4HP18V60P | EA(C,U)1P60D+H4TXV03 | EFV20DCA | 40,000 | $2,000 |
| No | 206906868 | ALLIED | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 96G1UH110CE20 | 37,800 | $1,890 |
| No | 206906861 | ALLIED | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 80G1UH110CE20 | 38,000 | $1,900 |
| No | 206906860 | ALLIED | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 80G1UH100CE20X | 38,000 | $1,900 |
| No | 206906859 | ALLIED | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 80G1UH090CE20 | 38,000 | $1,900 |
| No | 206906976 | ALLIED | 4HP18V60P | ED1P50/60C+H4TXV02 | EFV16CCA | 30,400 | $1,520 |
| No | 206906908 | ALLIED | 4HP18V60P | EAC4X49C | EFV16CCA | 30,600 | $1,530 |
| No | 206906897 | ALLIED | 4HP18V60P | EAC4X49C | 80G2UH110CE16 | 30,200 | $1,510 |
| No | 206906846 | ALLIED | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | EFV16CCA | 30,600 | $1,530 |
| No | 206906835 | ALLIED | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | 80G2UH110CE16 | 30,200 | $1,510 |
| No | 206906925 | ALLIED | 4HP18V60P | EAC4X60C | 80G2UH110CE20L | 38,000 | $1,900 |
| No | 206906863 | ALLIED | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 80G2UH110CE20L | 38,000 | $1,900 |
| No | 206906942 | ALLIED | 4HP18V60P | EAH1P48C+H4TXV02 | 80G2UH110CE20L | 31,000 | $1,550 |
| No | 206906977 | ALLIED | 4HP18V60P | ED1P60D+H4TXV03 | 80G1DF110CE20 | 38,000 | $1,900 |
| No | 206906980 | ALLIED | 4HP18V60P | ED1P60D+H4TXV03 | 96G2DF110CV20 | 38,500 | $1,925 |
| No | 206906979 | ALLIED | 4HP18V60P | ED1P60D+H4TXV03 | 96G2DF090CV20 | 38,500 | $1,925 |
| No | 206906954 | ALLIED | 4HP18V60P | EAH1P51C+H4TXV03 | 80G1UH090CE20 | 36,800 | $1,840 |
| No | 206906873 | ALLIED | 4HP18V60P | EA(C,U)1P60D+H4TXV03 | 96G2UH135DV20 | 39,000 | $1,950 |
| No | 206906872 | ALLIED | 4HP18V60P | EA(C,U)1P60D+H4TXV03 | 80G1UH135DE20 | 39,000 | $1,950 |
| No | 206906932 | ALLIED | 4HP18V60P | EAC4X60C | 96G2UH110CV20 | 38,000 | $1,900 |
| No | 206906931 | ALLIED | 4HP18V60P | EAC4X60C | 96G2UH090CV20 | 38,000 | $1,900 |
| No | 206906927 | ALLIED | 4HP18V60P | EAC4X60C | 92G1UH110CE20 | 37,800 | $1,890 |
| No | 206906926 | ALLIED | 4HP18V60P | EAC4X60C | 80G2UH110CV20 | 38,000 | $1,900 |
| No | 206906924 | ALLIED | 4HP18V60P | EAC4X60C | 80G2UH110CE20 | 38,000 | $1,900 |
| No | 206906870 | ALLIED | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 96G2UH110CV20 | 38,000 | $1,900 |
| No | 206906869 | ALLIED | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 96G2UH090CV20 | 38,000 | $1,900 |
| No | 206906865 | ALLIED | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 92G1UH110CE20 | 37,800 | $1,890 |
| No | 206906864 | ALLIED | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 80G2UH110CV20 | 38,000 | $1,900 |
| No | 206906862 | ALLIED | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 80G2UH110CE20 | 38,000 | $1,900 |
| No | 206906604 | ALLIED | 4HP18V60P | BCE5V60M | | 38,500 | $1,925 |
| No | 206906907 | ALLIED | 4HP18V60P | EAC4X49C | 96G2UH110CV20 | 30,600 | $1,530 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206906906 | ALLIED | 4HP18V60P | EAC4X49C | 96G2UH090CV20 | 30,800 | $1,540 |
| No | 206906901 | ALLIED | 4HP18V60P | EAC4X49C | 92G1UH110CE20 | 30,400 | $1,520 |
| No | 206906898 | ALLIED | 4HP18V60P | EAC4X49C | 80G2UH110CV20 | 30,400 | $1,520 |
| No | 206906896 | ALLIED | 4HP18V60P | EAC4X49C | 80G1UH110CE20 | 30,400 | $1,520 |
| No | 206906895 | ALLIED | 4HP18V60P | EAC4X49C | 80G1UH100CE20X | 30,600 | $1,530 |
| No | 206906845 | ALLIED | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | 96G2UH110CV20 | 30,600 | $1,530 |
| No | 206906844 | ALLIED | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | 96G2UH090CV20 | 30,800 | $1,540 |
| No | 206906839 | ALLIED | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | 92G1UH110CE20 | 30,400 | $1,520 |
| No | 206906836 | ALLIED | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | 80G2UH110CV20 | 30,400 | $1,520 |
| No | 206906834 | ALLIED | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | 80G1UH110CE20 | 30,400 | $1,520 |
| No | 206906833 | ALLIED | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | 80G1UH100CE20X | 30,600 | $1,530 |
| No | 206906943 | ALLIED | 4HP18V60P | EAH1P48C+H4TXV02 | 80G2UH110CV20 | 31,000 | $1,550 |
| No | 206906952 | ALLIED | 4HP18V60P | EAH1P48C+H4TXV02 | 96G2UH110CV20 | 31,200 | $1,560 |
| No | 206906951 | ALLIED | 4HP18V60P | EAH1P48C+H4TXV02 | 96G2UH090CV20 | 31,400 | $1,570 |
| No | 206906946 | ALLIED | 4HP18V60P | EAH1P48C+H4TXV02 | 92G1UH110CE20 | 30,800 | $1,540 |
| No | 206906941 | ALLIED | 4HP18V60P | EAH1P48C+H4TXV02 | 80G2UH110CE20 | 31,000 | $1,550 |
| No | 206906939 | ALLIED | 4HP18V60P | EAH1P48C+H4TXV02 | 80G1UH110CE20 | 30,800 | $1,540 |
| No | 206906937 | ALLIED | 4HP18V60P | EAH1P48C+H4TXV02 | 80G1UH090CE20 | 30,800 | $1,540 |
| No | 206906799 | ALLIED | 4HP18V60P | BCE7E48M | | 32,200 | $1,610 |
| No | 206906796 | ALLIED | 4HP18V60P | BCE5E48M | | 31,600 | $1,580 |
| No | 206906795 | ALLIED | 4HP18V60P | BCE5C48M*4X | | 31,600 | $1,580 |
| No | 206906794 | ALLIED | 4HP18V60P | BCE5C48M*1P+H4TXV02 | | 31,600 | $1,580 |
| No | 206906798 | ALLIED | 4HP18V60P | BCE5V48M | | 31,400 | $1,570 |
| No | 206906206 | ALLIED | 4HP18V36P | ED1P30/36B+H4TXV02 | 80G2DF090BE16 | 22,200 | $1,110 |
| No | 206905969 | ALLIED | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 80G1UH070BE12 | 21,600 | $1,080 |
| No | 206906050 | ALLIED | 4HP18V36P | EAC4X36B | 80G2UH090BV16* | 22,800 | $1,140 |
| No | 206905958 | ALLIED | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 80G2UH090BV16* | 22,800 | $1,140 |
| No | 206906200 | ALLIED | 4HP18V36P | ED1P24B+H4TXV01 | EFV12BCA | 15,500 | $775 |
| No | 206906199 | ALLIED | 4HP18V36P | ED1P24B+H4TXV01 | EFV08BCA | 15,700 | $785 |
| No | 206906198 | ALLIED | 4HP18V36P | ED1P24B+H4TXV01 | 96G2DF070BV16 | 15,800 | $790 |
| No | 206906103 | ALLIED | 4HP18V36P | EAH1P30B+H4TXV01 | 96G1UH045BE12 | 15,900 | $795 |
| No | 206906093 | ALLIED | 4HP18V36P | EAH1P30A+H4TXV01 | 80G2UH070AV12* | 15,600 | $780 |
| No | 206906029 | ALLIED | 4HP18V36P | EAC4X30B | 95G1UH045BE12 | 15,800 | $790 |
| No | 206906022 | ALLIED | 4HP18V36P | EAC4X30A | 80G2UH070AV12* | 15,600 | $780 |
| No | 206905940 | ALLIED | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 96G1UH045BE12 | 15,900 | $795 |
| No | 206905930 | ALLIED | 4HP18V36P | EA(C,U)1P30A+H4TXV01 | 80G2UH070AV12* | 15,600 | $780 |
| No | 206906011 | ALLIED | 4HP18V36P | EAC4X24B | 96G1UH070BE12 | 16,300 | $815 |
| No | 206906010 | ALLIED | 4HP18V36P | EAC4X24B | 96G1UH045BE12 | 16,300 | $815 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206906009 | ALLIED | 4HP18V36P | EAC4X24B | 96G1UH030BE08 | 15,800 | $790 |
| No | 206906004 | ALLIED | 4HP18V36P | EAC4X24B | 92G1UH030BE12 | 15,700 | $785 |
| No | 206906001 | ALLIED | 4HP18V36P | EAC4X24A | 80G2UH070AV12* | 16,000 | $800 |
| No | 206905919 | ALLIED | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 96G1UH070BE12 | 16,300 | $815 |
| No | 206905918 | ALLIED | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 96G1UH045BE12 | 16,300 | $815 |
| No | 206905917 | ALLIED | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 96G1UH030BE08 | 15,800 | $790 |
| No | 206905909 | ALLIED | 4HP18V36P | EA(C,U)1P24A+H4TXV01 | 80G2UH070AV12* | 16,000 | $800 |
| No | 206905868 | ALLIED | 4HP18V36P | E*1P23B+H4TXV01 | 96G1UH070BE12 | 15,400 | $770 |
| No | 206905867 | ALLIED | 4HP18V36P | E*1P23B+H4TXV01 | 96G1UH045BE12 | 15,400 | $770 |
| No | 206905866 | ALLIED | 4HP18V36P | E*1P23B+H4TXV01 | 96G1UH030BE08 | 14,900 | $745 |
| No | 206905858 | ALLIED | 4HP18V36P | E*1P23A+H4TXV01 | 80G2UH070AV12* | 15,200 | $760 |
| No | 206905884 | ALLIED | 4HP18V36P | E*1P36B+H4TXV02 | 80G2UH090BE16L | 23,400 | $1,170 |
| No | 206906130 | ALLIED | 4HP18V36P | EAH1P48B+H4TXV02 | 80G2UH090BE16L | 22,200 | $1,110 |
| No | 206906114 | ALLIED | 4HP18V36P | EAH1P36B+H4TXV02 | 80G2UH090BE16L | 22,200 | $1,110 |
| No | 206906066 | ALLIED | 4HP18V36P | EAC4X48B | 80G2UH090BE16L | 21,600 | $1,080 |
| No | 206905974 | ALLIED | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 80G2UH090BE16L | 21,600 | $1,080 |
| No | 206906049 | ALLIED | 4HP18V36P | EAC4X36B | 80G2UH090BE16L | 22,800 | $1,140 |
| No | 206905957 | ALLIED | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 80G2UH090BE16L | 22,800 | $1,140 |
| No | 206905877 | ALLIED | 4HP18V36P | E*1P36A+H4TXV02 | 80G2UH070AE12L | 23,400 | $1,170 |
| No | 206906042 | ALLIED | 4HP18V36P | EAC4X36A | 80G2UH070AE12L | 22,800 | $1,140 |
| No | 206905950 | ALLIED | 4HP18V36P | EA(C,U)1P36A+H4TXV02 | 80G2UH070AE12L | 22,800 | $1,140 |
| No | 206906092 | ALLIED | 4HP18V36P | EAH1P30A+H4TXV01 | 80G2UH070AE12L | 15,800 | $790 |
| No | 206906021 | ALLIED | 4HP18V36P | EAC4X30A | 80G2UH070AE12L | 15,800 | $790 |
| No | 206905929 | ALLIED | 4HP18V36P | EA(C,U)1P30A+H4TXV01 | 80G2UH070AE12L | 15,800 | $790 |
| No | 206905908 | ALLIED | 4HP18V36P | EA(C,U)1P24A+H4TXV01 | 80G2UH070AE12L | 16,100 | $805 |
| No | 206905894 | ALLIED | 4HP18V36P | E*1P36C+H4TXV02 | 80G2UH110CE16 | 23,400 | $1,170 |
| No | 206905902 | ALLIED | 4HP18V36P | E*1P36C+H4TXV02 | EFV16CCA | 23,200 | $1,160 |
| No | 206905901 | ALLIED | 4HP18V36P | E*1P36C+H4TXV02 | 96G2UH090CV12 | 23,200 | $1,160 |
| No | 206905900 | ALLIED | 4HP18V36P | E*1P36C+H4TXV02 | 96G1UH090CE16 | 23,400 | $1,170 |
| No | 206905897 | ALLIED | 4HP18V36P | E*1P36C+H4TXV02 | 92G1UH110CE16 | 23,200 | $1,160 |
| No | 206905896 | ALLIED | 4HP18V36P | E*1P36C+H4TXV02 | 92G1UH090CE16 | 23,200 | $1,160 |
| No | 206905895 | ALLIED | 4HP18V36P | E*1P36C+H4TXV02 | 92G1UH090CE12 | 23,400 | $1,170 |
| No | 206905893 | ALLIED | 4HP18V36P | E*1P36B+H4TXV02 | EFV12BCA | 23,400 | $1,170 |
| No | 206905892 | ALLIED | 4HP18V36P | E*1P36B+H4TXV02 | 96G2UH070BV12 | 23,400 | $1,170 |
| No | 206905891 | ALLIED | 4HP18V36P | E*1P36B+H4TXV02 | 96G2UH045BV12 | 23,600 | $1,180 |
| No | 206905890 | ALLIED | 4HP18V36P | E*1P36B+H4TXV02 | 96G1UH070BE12 | 23,200 | $1,160 |
| No | 206905888 | ALLIED | 4HP18V36P | E*1P36B+H4TXV02 | 92G1UH070BE12 | 23,400 | $1,170 |
| No | 206905887 | ALLIED | 4HP18V36P | E*1P36B+H4TXV02 | 92G1UH045BE12 | 23,400 | $1,170 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206905886 | ALLIED | 4HP18V36P | E*1P36B+H4TXV02 | 92G1UH030BE12 | 23,400 | $1,170 |
| No | 206905883 | ALLIED | 4HP18V36P | E*1P36B+H4TXV02 | 80G2UH090BE16 | 23,400 | $1,170 |
| No | 206905882 | ALLIED | 4HP18V36P | E*1P36B+H4TXV02 | 80G2UH090BE12 | 23,400 | $1,170 |
| No | 206905881 | ALLIED | 4HP18V36P | E*1P36B+H4TXV02 | 80G1UH090BE16 | 23,200 | $1,160 |
| No | 206905880 | ALLIED | 4HP18V36P | E*1P36B+H4TXV02 | 80G1UH080BE16X | 23,600 | $1,180 |
| No | 206905879 | ALLIED | 4HP18V36P | E*1P36B+H4TXV02 | 80G1UH070BE12 | 23,200 | $1,160 |
| No | 206905876 | ALLIED | 4HP18V36P | E*1P36A+H4TXV02 | 80G2UH070AE12 | 23,400 | $1,170 |
| No | 206905875 | ALLIED | 4HP18V36P | E*1P36A+H4TXV02 | 80G1UH070AE12 | 23,200 | $1,160 |
| No | 206905874 | ALLIED | 4HP18V36P | E*1P36A+H4TXV02 | 80G1UH060AE12X | 23,200 | $1,160 |
| No | 206905873 | ALLIED | 4HP18V36P | E*1P36A+H4TXV02 | 80G1UH045AE12 | 23,200 | $1,160 |
| No | 206906217 | ALLIED | 4HP18V36P | ED1P30/36C+H4TXV02 | 96G1DF090CE16 | 22,200 | $1,110 |
| No | 206906215 | ALLIED | 4HP18V36P | ED1P30/36C+H4TXV02 | 92G1DF090CE16 | 22,200 | $1,110 |
| No | 206906214 | ALLIED | 4HP18V36P | ED1P30/36B+H4TXV02 | 96G2DF070BV16 | 22,600 | $1,130 |
| No | 206906212 | ALLIED | 4HP18V36P | ED1P30/36B+H4TXV02 | 96G1DF070BE16 | 22,400 | $1,120 |
| No | 206906211 | ALLIED | 4HP18V36P | ED1P30/36B+H4TXV02 | 96G1DF045BE12 | 22,000 | $1,100 |
| No | 206906208 | ALLIED | 4HP18V36P | ED1P30/36B+H4TXV02 | 92G1DF070BE12 | 22,400 | $1,120 |
| No | 206906207 | ALLIED | 4HP18V36P | ED1P30/36B+H4TXV02 | 92G1DF045BE12 | 22,400 | $1,120 |
| No | 206906205 | ALLIED | 4HP18V36P | ED1P30/36B+H4TXV02 | 80G1DF090BE16 | 22,200 | $1,110 |
| No | 206906204 | ALLIED | 4HP18V36P | ED1P30/36B+H4TXV02 | 80G1DF070BE12 | 22,000 | $1,100 |
| No | 206906202 | ALLIED | 4HP18V36P | ED1P30/36A+H4TXV02 | 80G1DF070AE12 | 22,200 | $1,110 |
| No | 206906139 | ALLIED | 4HP18V36P | EAH1P48B+H4TXV02 | EFV12BCA | 22,000 | $1,100 |
| No | 206906138 | ALLIED | 4HP18V36P | EAH1P48B+H4TXV02 | 96G2UH070BV12 | 22,400 | $1,120 |
| No | 206906137 | ALLIED | 4HP18V36P | EAH1P48B+H4TXV02 | 96G2UH045BV12 | 22,400 | $1,120 |
| No | 206906136 | ALLIED | 4HP18V36P | EAH1P48B+H4TXV02 | 96G1UH070BE12 | 22,000 | $1,100 |
| No | 206906134 | ALLIED | 4HP18V36P | EAH1P48B+H4TXV02 | 92G1UH070BE12 | 22,200 | $1,110 |
| No | 206906133 | ALLIED | 4HP18V36P | EAH1P48B+H4TXV02 | 92G1UH045BE12 | 22,400 | $1,120 |
| No | 206906132 | ALLIED | 4HP18V36P | EAH1P48B+H4TXV02 | 92G1UH030BE12 | 22,200 | $1,110 |
| No | 206906131 | ALLIED | 4HP18V36P | EAH1P48B+H4TXV02 | 80G2UH090BV16* | 22,400 | $1,120 |
| No | 206906129 | ALLIED | 4HP18V36P | EAH1P48B+H4TXV02 | 80G2UH090BE16 | 22,200 | $1,110 |
| No | 206906128 | ALLIED | 4HP18V36P | EAH1P48B+H4TXV02 | 80G2UH090BE12 | 22,400 | $1,120 |
| No | 206906127 | ALLIED | 4HP18V36P | EAH1P48B+H4TXV02 | 80G1UH090BE16 | 22,000 | $1,100 |
| No | 206906126 | ALLIED | 4HP18V36P | EAH1P48B+H4TXV02 | 80G1UH070BE12 | 22,000 | $1,100 |
| No | 206906125 | ALLIED | 4HP18V36P | EAH1P36B+H4TXV02 | EFV12BCA | 22,200 | $1,110 |
| No | 206906124 | ALLIED | 4HP18V36P | EAH1P36B+H4TXV02 | 96G2UH070BV12 | 22,200 | $1,110 |
| No | 206906123 | ALLIED | 4HP18V36P | EAH1P36B+H4TXV02 | 96G2UH045BV12 | 22,400 | $1,120 |
| No | 206906122 | ALLIED | 4HP18V36P | EAH1P36B+H4TXV02 | 96G1UH070BE12 | 21,800 | $1,090 |
| No | 206906118 | ALLIED | 4HP18V36P | EAH1P36B+H4TXV02 | 92G1UH070BE12 | 22,200 | $1,110 |
| No | 206906117 | ALLIED | 4HP18V36P | EAH1P36B+H4TXV02 | 92G1UH045BE12 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206906116 | ALLIED | 4HP18V36P | EAH1P36B+H4TXV02 | 92G1UH030BE12 | 22,200 | $1,110 |
| No | 206906115 | ALLIED | 4HP18V36P | EAH1P36B+H4TXV02 | 80G2UH090BV16* | 22,000 | $1,100 |
| No | 206906113 | ALLIED | 4HP18V36P | EAH1P36B+H4TXV02 | 80G2UH090BE16 | 22,200 | $1,110 |
| No | 206906112 | ALLIED | 4HP18V36P | EAH1P36B+H4TXV02 | 80G2UH090BE12 | 22,200 | $1,110 |
| No | 206906111 | ALLIED | 4HP18V36P | EAH1P36B+H4TXV02 | 80G1UH090BE16 | 22,000 | $1,100 |
| No | 206906110 | ALLIED | 4HP18V36P | EAH1P36B+H4TXV02 | 80G1UH080BE16X | 22,200 | $1,110 |
| No | 206906109 | ALLIED | 4HP18V36P | EAH1P36B+H4TXV02 | 80G1UH070BE12 | 22,000 | $1,100 |
| No | 206906086 | ALLIED | 4HP18V36P | EAC4X48C | EFV16CCA | 21,600 | $1,080 |
| No | 206906085 | ALLIED | 4HP18V36P | EAC4X48C | 96G2UH090CV12 | 21,600 | $1,080 |
| No | 206906084 | ALLIED | 4HP18V36P | EAC4X48C | 96G1UH090CE16 | 21,600 | $1,080 |
| No | 206906083 | ALLIED | 4HP18V36P | EAC4X48C | 95G1UH090CE16 | 21,600 | $1,080 |
| No | 206906081 | ALLIED | 4HP18V36P | EAC4X48C | 92G1UH110CE16 | 21,400 | $1,070 |
| No | 206906080 | ALLIED | 4HP18V36P | EAC4X48C | 92G1UH090CE16 | 21,600 | $1,080 |
| No | 206906079 | ALLIED | 4HP18V36P | EAC4X48C | 92G1UH090CE12 | 21,800 | $1,090 |
| No | 206906078 | ALLIED | 4HP18V36P | EAC4X48C | 80G2UH110CE16 | 21,600 | $1,080 |
| No | 206906077 | ALLIED | 4HP18V36P | EAC4X48B | EFV12BCA | 21,600 | $1,080 |
| No | 206906076 | ALLIED | 4HP18V36P | EAC4X48B | 96G2UH070BV12 | 21,800 | $1,090 |
| No | 206906075 | ALLIED | 4HP18V36P | EAC4X48B | 96G2UH045BV12 | 21,800 | $1,090 |
| No | 206906074 | ALLIED | 4HP18V36P | EAC4X48B | 96G1UH070BE12 | 21,400 | $1,070 |
| No | 206906073 | ALLIED | 4HP18V36P | EAC4X48B | 96G1UH045BE12 | 21,400 | $1,070 |
| No | 206906070 | ALLIED | 4HP18V36P | EAC4X48B | 92G1UH070BE12 | 21,600 | $1,080 |
| No | 206906069 | ALLIED | 4HP18V36P | EAC4X48B | 92G1UH045BE12 | 21,800 | $1,090 |
| No | 206906068 | ALLIED | 4HP18V36P | EAC4X48B | 92G1UH030BE12 | 21,600 | $1,080 |
| No | 206906067 | ALLIED | 4HP18V36P | EAC4X48B | 80G2UH090BV16* | 21,600 | $1,080 |
| No | 206906065 | ALLIED | 4HP18V36P | EAC4X48B | 80G2UH090BE16 | 21,600 | $1,080 |
| No | 206906064 | ALLIED | 4HP18V36P | EAC4X48B | 80G2UH090BE12 | 21,800 | $1,090 |
| No | 206906063 | ALLIED | 4HP18V36P | EAC4X48B | 80G1UH090BE16 | 21,600 | $1,080 |
| No | 206906062 | ALLIED | 4HP18V36P | EAC4X48B | 80G1UH080BE16X | 21,800 | $1,090 |
| No | 206906061 | ALLIED | 4HP18V36P | EAC4X48B | 80G1UH070BE12 | 21,600 | $1,080 |
| No | 206905993 | ALLIED | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 96G2UH090CV12 | 21,600 | $1,080 |
| No | 206905992 | ALLIED | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 96G1UH090CE16 | 21,600 | $1,080 |
| No | 206905991 | ALLIED | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 95G1UH090CE16 | 21,600 | $1,080 |
| No | 206905989 | ALLIED | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 92G1UH110CE16 | 21,400 | $1,070 |
| No | 206905988 | ALLIED | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 92G1UH090CE16 | 21,600 | $1,080 |
| No | 206905987 | ALLIED | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 92G1UH090CE12 | 21,800 | $1,090 |
| No | 206905986 | ALLIED | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 80G2UH110CE16 | 21,600 | $1,080 |
| No | 206905985 | ALLIED | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | EFV12BCA | 21,800 | $1,090 |
| No | 206905984 | ALLIED | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 96G2UH070BV12 | 21,800 | $1,090 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206905983 | ALLIED | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 96G2UH045BV12 | 21,800 | $1,090 |
| No | 206905982 | ALLIED | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 96G1UH070BE12 | 21,400 | $1,070 |
| No | 206905981 | ALLIED | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 96G1UH045BE12 | 21,400 | $1,070 |
| No | 206905978 | ALLIED | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 92G1UH070BE12 | 21,600 | $1,080 |
| No | 206905977 | ALLIED | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 92G1UH045BE12 | 21,800 | $1,090 |
| No | 206905976 | ALLIED | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 92G1UH030BE12 | 21,600 | $1,080 |
| No | 206905975 | ALLIED | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 80G2UH090BV16* | 21,600 | $1,080 |
| No | 206905973 | ALLIED | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 80G2UH090BE16 | 21,600 | $1,080 |
| No | 206905972 | ALLIED | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 80G2UH090BE12 | 21,800 | $1,090 |
| No | 206905971 | ALLIED | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 80G1UH090BE16 | 21,600 | $1,080 |
| No | 206905970 | ALLIED | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 80G1UH080BE16X | 21,800 | $1,090 |
| No | 206906060 | ALLIED | 4HP18V36P | EAC4X36B | EFV12BCA | 22,800 | $1,140 |
| No | 206906059 | ALLIED | 4HP18V36P | EAC4X36B | 96G2UH070BV12 | 22,800 | $1,140 |
| No | 206906058 | ALLIED | 4HP18V36P | EAC4X36B | 96G2UH045BV12 | 23,000 | $1,150 |
| No | 206906057 | ALLIED | 4HP18V36P | EAC4X36B | 96G1UH070BE12 | 22,400 | $1,120 |
| No | 206906053 | ALLIED | 4HP18V36P | EAC4X36B | 92G1UH070BE12 | 22,800 | $1,140 |
| No | 206906052 | ALLIED | 4HP18V36P | EAC4X36B | 92G1UH045BE12 | 22,800 | $1,140 |
| No | 206906051 | ALLIED | 4HP18V36P | EAC4X36B | 92G1UH030BE12 | 22,600 | $1,130 |
| No | 206906048 | ALLIED | 4HP18V36P | EAC4X36B | 80G2UH090BE16 | 22,800 | $1,140 |
| No | 206906047 | ALLIED | 4HP18V36P | EAC4X36B | 80G2UH090BE12 | 22,800 | $1,140 |
| No | 206906046 | ALLIED | 4HP18V36P | EAC4X36B | 80G1UH090BE16 | 22,600 | $1,130 |
| No | 206906045 | ALLIED | 4HP18V36P | EAC4X36B | 80G1UH080BE16X | 22,800 | $1,140 |
| No | 206906044 | ALLIED | 4HP18V36P | EAC4X36B | 80G1UH070BE12 | 22,600 | $1,130 |
| No | 206906041 | ALLIED | 4HP18V36P | EAC4X36A | 80G2UH070AE12 | 22,800 | $1,140 |
| No | 206906040 | ALLIED | 4HP18V36P | EAC4X36A | 80G1UH070AE12 | 22,600 | $1,130 |
| No | 206906039 | ALLIED | 4HP18V36P | EAC4X36A | 80G1UH060AE12X | 22,400 | $1,120 |
| No | 206906038 | ALLIED | 4HP18V36P | EAC4X36A | 80G1UH045AE12 | 22,400 | $1,120 |
| No | 206905968 | ALLIED | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | EFV12BCA | 22,000 | $1,100 |
| No | 206905967 | ALLIED | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 96G2UH070BV12 | 22,800 | $1,140 |
| No | 206905966 | ALLIED | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 96G2UH045BV12 | 23,000 | $1,150 |
| No | 206905961 | ALLIED | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 92G1UH070BE12 | 22,800 | $1,140 |
| No | 206905960 | ALLIED | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 92G1UH045BE12 | 22,800 | $1,140 |
| No | 206905959 | ALLIED | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 92G1UH030BE12 | 22,600 | $1,130 |
| No | 206905956 | ALLIED | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 80G2UH090BE16 | 22,800 | $1,140 |
| No | 206905955 | ALLIED | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 80G2UH090BE12 | 22,800 | $1,140 |
| No | 206905954 | ALLIED | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 80G1UH090BE16 | 22,600 | $1,130 |
| No | 206905953 | ALLIED | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 80G1UH080BE16X | 22,800 | $1,140 |
| No | 206905952 | ALLIED | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 80G1UH070BE12 | 22,600 | $1,130 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206905949 | ALLIED | 4HP18V36P | EA(C,U)1P36A+H4TXV02 | 80G2UH070AE12 | 22,800 | $1,140 |
| No | 206905948 | ALLIED | 4HP18V36P | EA(C,U)1P36A+H4TXV02 | 80G1UH070AE12 | 22,600 | $1,130 |
| No | 206905947 | ALLIED | 4HP18V36P | EA(C,U)1P36A+H4TXV02 | 80G1UH060AE12X | 22,400 | $1,120 |
| No | 206905946 | ALLIED | 4HP18V36P | EA(C,U)1P36A+H4TXV02 | 80G1UH045AE12 | 22,400 | $1,120 |
| No | 206905850 | ALLIED | 4HP18V36P | BCE7E36M | | 23,400 | $1,170 |
| No | 206905838 | ALLIED | 4HP18V36P | BCE5C36M*4X | | 22,400 | $1,120 |
| No | 206905837 | ALLIED | 4HP18V36P | BCE5C36M*1P+H4TXV02 | | 22,400 | $1,120 |
| No | 206905842 | ALLIED | 4HP18V36P | BCE5E42M | | 22,200 | $1,110 |
| No | 206905841 | ALLIED | 4HP18V36P | BCE5E36M | | 22,600 | $1,130 |
| No | 206905846 | ALLIED | 4HP18V36P | BCE5V42M | | 22,200 | $1,110 |
| No | 206905851 | ALLIED | 4HP18V36P | BCE7E42M | | 22,000 | $1,100 |
| No | 206905446 | ALLIED | 4HP18V36P | BCE5V36M | | 22,000 | $1,100 |
| No | 206905870 | ALLIED | 4HP18V36P | E*1P23B+H4TXV01 | 96G2UH070BV12 | 15,100 | $755 |
| No | 206905869 | ALLIED | 4HP18V36P | E*1P23B+H4TXV01 | 96G2UH045BV12 | 15,100 | $755 |
| No | 206905872 | ALLIED | 4HP18V36P | E*1P23B+H4TXV01 | EFV12BCA | 15,200 | $760 |
| No | 206905871 | ALLIED | 4HP18V36P | E*1P23B+H4TXV01 | EFV08BCA | 15,300 | $765 |
| No | 206905863 | ALLIED | 4HP18V36P | E*1P23B+H4TXV01 | 92G1UH070BE12 | 15,300 | $765 |
| No | 206905862 | ALLIED | 4HP18V36P | E*1P23B+H4TXV01 | 92G1UH045BE12 | 15,400 | $770 |
| No | 206905861 | ALLIED | 4HP18V36P | E*1P23B+H4TXV01 | 92G1UH030BE12 | 15,300 | $765 |
| No | 206905860 | ALLIED | 4HP18V36P | E*1P23B+H4TXV01 | 80G2UH090BE12 | 15,300 | $765 |
| No | 206905859 | ALLIED | 4HP18V36P | E*1P23B+H4TXV01 | 80G1UH070BE12 | 15,000 | $750 |
| No | 206905856 | ALLIED | 4HP18V36P | E*1P23A+H4TXV01 | 80G2UH070AE12 | 15,400 | $770 |
| No | 206905855 | ALLIED | 4HP18V36P | E*1P23A+H4TXV01 | 80G2UH045AE12 | 14,900 | $745 |
| No | 206905854 | ALLIED | 4HP18V36P | E*1P23A+H4TXV01 | 80G1UH060AE12X | 15,300 | $765 |
| No | 206905853 | ALLIED | 4HP18V36P | E*1P23A+H4TXV01 | 80G1UH045AE12 | 15,200 | $760 |
| No | 206905852 | ALLIED | 4HP18V36P | E*1P23A+H4TXV01 | 80G1UH040AE12X | 15,300 | $765 |
| No | 206906108 | ALLIED | 4HP18V36P | EAH1P30B+H4TXV01 | EFV12BCA | 15,600 | $780 |
| No | 206906107 | ALLIED | 4HP18V36P | EAH1P30B+H4TXV01 | EFV08BCA | 15,700 | $785 |
| No | 206906106 | ALLIED | 4HP18V36P | EAH1P30B+H4TXV01 | 96G2UH070BV12 | 15,500 | $775 |
| No | 206906105 | ALLIED | 4HP18V36P | EAH1P30B+H4TXV01 | 96G2UH045BV12 | 15,600 | $780 |
| No | 206906104 | ALLIED | 4HP18V36P | EAH1P30B+H4TXV01 | 96G1UH070BE12 | 15,900 | $795 |
| No | 206906102 | ALLIED | 4HP18V36P | EAH1P30B+H4TXV01 | 96G1UH030BE08 | 15,800 | $790 |
| No | 206906098 | ALLIED | 4HP18V36P | EAH1P30B+H4TXV01 | 92G1UH070BE12 | 15,800 | $790 |
| No | 206906097 | ALLIED | 4HP18V36P | EAH1P30B+H4TXV01 | 92G1UH045BE12 | 15,900 | $795 |
| No | 206906096 | ALLIED | 4HP18V36P | EAH1P30B+H4TXV01 | 92G1UH030BE12 | 15,800 | $790 |
| No | 206906095 | ALLIED | 4HP18V36P | EAH1P30B+H4TXV01 | 80G2UH090BE12 | 15,800 | $790 |
| No | 206906094 | ALLIED | 4HP18V36P | EAH1P30B+H4TXV01 | 80G1UH070BE12 | 15,500 | $775 |
| No | 206906091 | ALLIED | 4HP18V36P | EAH1P30A+H4TXV01 | 80G2UH070AE12 | 15,800 | $790 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206906090 | ALLIED | 4HP18V36P | EAH1P30A+H4TXV01 | 80G2UH045AE12 | 15,400 | $770 |
| No | 206906089 | ALLIED | 4HP18V36P | EAH1P30A+H4TXV01 | 80G1UH060AE12X | 15,700 | $785 |
| No | 206906088 | ALLIED | 4HP18V36P | EAH1P30A+H4TXV01 | 80G1UH045AE12 | 15,700 | $785 |
| No | 206906087 | ALLIED | 4HP18V36P | EAH1P30A+H4TXV01 | 80G1UH040AE12X | 15,700 | $785 |
| No | 206906035 | ALLIED | 4HP18V36P | EAC4X30B | 96G2UH070BV12 | 15,500 | $775 |
| No | 206906034 | ALLIED | 4HP18V36P | EAC4X30B | 96G2UH045BV12 | 15,600 | $780 |
| No | 206906037 | ALLIED | 4HP18V36P | EAC4X30B | EFV12BCA | 15,600 | $780 |
| No | 206906036 | ALLIED | 4HP18V36P | EAC4X30B | EFV08BCA | 15,900 | $795 |
| No | 206906033 | ALLIED | 4HP18V36P | EAC4X30B | 96G1UH070BE12 | 15,900 | $795 |
| No | 206906031 | ALLIED | 4HP18V36P | EAC4X30B | 96G1UH030BE08 | 15,800 | $790 |
| No | 206906027 | ALLIED | 4HP18V36P | EAC4X30B | 92G1UH070BE12 | 15,800 | $790 |
| No | 206906026 | ALLIED | 4HP18V36P | EAC4X30B | 92G1UH045BE12 | 15,900 | $795 |
| No | 206906025 | ALLIED | 4HP18V36P | EAC4X30B | 92G1UH030BE12 | 15,800 | $790 |
| No | 206906024 | ALLIED | 4HP18V36P | EAC4X30B | 80G2UH090BE12 | 15,800 | $790 |
| No | 206906023 | ALLIED | 4HP18V36P | EAC4X30B | 80G1UH070BE12 | 15,600 | $780 |
| No | 206906020 | ALLIED | 4HP18V36P | EAC4X30A | 80G2UH070AE12 | 15,800 | $790 |
| No | 206906019 | ALLIED | 4HP18V36P | EAC4X30A | 80G2UH045AE12 | 15,800 | $790 |
| No | 206906018 | ALLIED | 4HP18V36P | EAC4X30A | 80G1UH060AE12X | 15,800 | $790 |
| No | 206906017 | ALLIED | 4HP18V36P | EAC4X30A | 80G1UH045AE12 | 15,700 | $785 |
| No | 206906016 | ALLIED | 4HP18V36P | EAC4X30A | 80G1UH040AE12X | 15,800 | $790 |
| No | 206905943 | ALLIED | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 96G2UH070BV12 | 15,500 | $775 |
| No | 206905942 | ALLIED | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 96G2UH045BV12 | 15,600 | $780 |
| No | 206905945 | ALLIED | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | EFV12BCA | 15,600 | $780 |
| No | 206905944 | ALLIED | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | EFV08BCA | 15,900 | $795 |
| No | 206905941 | ALLIED | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 96G1UH070BE12 | 15,900 | $795 |
| No | 206905939 | ALLIED | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 96G1UH030BE08 | 15,800 | $790 |
| No | 206905935 | ALLIED | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 92G1UH070BE12 | 15,800 | $790 |
| No | 206905934 | ALLIED | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 92G1UH045BE12 | 15,900 | $795 |
| No | 206905933 | ALLIED | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 92G1UH030BE12 | 15,800 | $790 |
| No | 206905932 | ALLIED | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 80G2UH090BE12 | 15,800 | $790 |
| No | 206905931 | ALLIED | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 80G1UH070BE12 | 15,600 | $780 |
| No | 206905928 | ALLIED | 4HP18V36P | EA(C,U)1P30A+H4TXV01 | 80G2UH070AE12 | 15,800 | $790 |
| No | 206905927 | ALLIED | 4HP18V36P | EA(C,U)1P30A+H4TXV01 | 80G2UH045AE12 | 15,800 | $790 |
| No | 206905926 | ALLIED | 4HP18V36P | EA(C,U)1P30A+H4TXV01 | 80G1UH060AE12X | 15,800 | $790 |
| No | 206905925 | ALLIED | 4HP18V36P | EA(C,U)1P30A+H4TXV01 | 80G1UH045AE12 | 15,700 | $785 |
| No | 206905924 | ALLIED | 4HP18V36P | EA(C,U)1P30A+H4TXV01 | 80G1UH040AE12X | 15,800 | $790 |
| No | 206906013 | ALLIED | 4HP18V36P | EAC4X24B | 96G2UH070BV12 | 15,900 | $795 |
| No | 206906012 | ALLIED | 4HP18V36P | EAC4X24B | 96G2UH045BV12 | 16,000 | $800 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206906015 | ALLIED | 4HP18V36P | EAC4X24B | EFV12BCA | 16,000 | $800 |
| No | 206906006 | ALLIED | 4HP18V36P | EAC4X24B | 92G1UH070BE12 | 16,200 | $810 |
| No | 206906005 | ALLIED | 4HP18V36P | EAC4X24B | 92G1UH045BE12 | 16,200 | $810 |
| No | 206906003 | ALLIED | 4HP18V36P | EAC4X24B | 80G2UH090BE12 | 16,100 | $805 |
| No | 206906002 | ALLIED | 4HP18V36P | EAC4X24B | 80G1UH070BE12 | 15,900 | $795 |
| No | 206905999 | ALLIED | 4HP18V36P | EAC4X24A | 80G2UH070AE12 | 16,100 | $805 |
| No | 206905997 | ALLIED | 4HP18V36P | EAC4X24A | 80G1UH060AE12X | 16,100 | $805 |
| No | 206905995 | ALLIED | 4HP18V36P | EAC4X24A | 80G1UH040AE12X | 16,100 | $805 |
| No | 206905920 | ALLIED | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 96G2UH045BV12 | 16,000 | $800 |
| No | 206905921 | ALLIED | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 96G2UH070BV12 | 15,900 | $795 |
| No | 206905923 | ALLIED | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | EFV12BCA | 16,000 | $800 |
| No | 206905922 | ALLIED | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | EFV08BCA | 16,300 | $815 |
| No | 206905914 | ALLIED | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 92G1UH070BE12 | 16,200 | $810 |
| No | 206905913 | ALLIED | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 92G1UH045BE12 | 16,200 | $810 |
| No | 206905911 | ALLIED | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 80G2UH090BE12 | 16,100 | $805 |
| No | 206905910 | ALLIED | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 80G1UH070BE12 | 15,900 | $795 |
| No | 206905907 | ALLIED | 4HP18V36P | EA(C,U)1P24A+H4TXV01 | 80G2UH070AE12 | 16,100 | $805 |
| No | 206905905 | ALLIED | 4HP18V36P | EA(C,U)1P24A+H4TXV01 | 80G1UH060AE12X | 16,100 | $805 |
| No | 206905903 | ALLIED | 4HP18V36P | EA(C,U)1P24A+H4TXV01 | 80G1UH040AE12X | 16,100 | $805 |
| No | 206905849 | ALLIED | 4HP18V36P | BCE7E30M | | 16,200 | $810 |
| No | 206905848 | ALLIED | 4HP18V36P | BCE7E24M | | 15,800 | $790 |
| No | 206905847 | ALLIED | 4HP18V36P | BCE7E18M | | 15,400 | $770 |
| No | 206905845 | ALLIED | 4HP18V36P | BCE5V30M | | 15,900 | $795 |
| No | 206905843 | ALLIED | 4HP18V36P | BCE5V18M | | 15,900 | $795 |
| No | 206905840 | ALLIED | 4HP18V36P | BCE5E30M | | 15,900 | $795 |
| No | 206905839 | ALLIED | 4HP18V36P | BCE5E24M | | 15,000 | $750 |
| No | 206905836 | ALLIED | 4HP18V36P | BCE5C24M*4X | | 16,100 | $805 |
| No | 206905835 | ALLIED | 4HP18V36P | BCE5C24M*1P+H4TXV01 | | 16,100 | $805 |
| No | 206905834 | ALLIED | 4HP18V36P | BCE5C18M*4X | | 15,400 | $770 |
| No | 206905833 | ALLIED | 4HP18V36P | BCE5C18M*1P+H4TXV01 | | 15,400 | $770 |
| No | 206905844 | ALLIED | 4HP18V36P | BCE5V24M | | 16,100 | $805 |
| No | 208106790 | ALLIED | 4DHP2S30M-1P | Combination heat pumps with or without ducts | | 16,000 | $800 |
| No | 208106787 | ALLIED | 4DHP2S24M-1P | Combination heat pumps with or without ducts | | 16,700 | $835 |
| No | 208106784 | ALLIED | 4DHP2S18M-1P | Combination heat pumps with or without ducts | | 11,400 | $570 |
| No | 206906812 | ALLIED | 4HP18V60P | E*1P50C+H4TXV03 | EFV16CCA | 39,500 | $1,975 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206906190 | ALLIED | 4HP18V36P | EC4X36C | EFV16CCA | 22,600 | $1,130 |
| No | 206906189 | ALLIED | 4HP18V36P | EC4X36C | 96G2UH090CV12 | 22,800 | $1,140 |
| No | 206906188 | ALLIED | 4HP18V36P | EC4X36C | 96G1UH090CE16 | 22,800 | $1,140 |
| No | 206906187 | ALLIED | 4HP18V36P | EC4X36C | 95G1UH090CE16 | 23,000 | $1,150 |
| No | 206906186 | ALLIED | 4HP18V36P | EC4X36C | 95G1UH080CE16X | 22,800 | $1,140 |
| No | 206906185 | ALLIED | 4HP18V36P | EC4X36C | 92G1UH110CE16 | 22,800 | $1,140 |
| No | 206906182 | ALLIED | 4HP18V36P | EC4X36C | 80G2UH110CE16 | 22,800 | $1,140 |
| No | 206906184 | ALLIED | 4HP18V36P | EC4X36C | 92G1UH090CE16 | 22,600 | $1,130 |
| No | 206906181 | ALLIED | 4HP18V36P | EC4X36B | EFV12BCA | 22,800 | $1,140 |
| No | 206906183 | ALLIED | 4HP18V36P | EC4X36C | 92G1UH090CE12 | 23,000 | $1,150 |
| No | 206906179 | ALLIED | 4HP18V36P | EC4X36B | 96G2UH045BV12 | 23,000 | $1,150 |
| No | 206906180 | ALLIED | 4HP18V36P | EC4X36B | 96G2UH070BV12 | 23,000 | $1,150 |
| No | 206906177 | ALLIED | 4HP18V36P | EC4X36B | 96G1UH045BE12 | 23,200 | $1,160 |
| No | 206906176 | ALLIED | 4HP18V36P | EC4X36B | 92G1UH070BE12 | 23,200 | $1,160 |
| No | 206906175 | ALLIED | 4HP18V36P | EC4X36B | 92G1UH045BE12 | 23,200 | $1,160 |
| No | 206906178 | ALLIED | 4HP18V36P | EC4X36B | 96G1UH070BE12 | 23,200 | $1,160 |
| No | 206906173 | ALLIED | 4HP18V36P | EC4X36B | 80G2UH090BV16* | 22,800 | $1,140 |
| No | 206906174 | ALLIED | 4HP18V36P | EC4X36B | 92G1UH030BE12 | 23,200 | $1,160 |
| No | 206906172 | ALLIED | 4HP18V36P | EC4X36B | 80G2UH090BE16L | 22,800 | $1,140 |
| No | 206906170 | ALLIED | 4HP18V36P | EC4X36B | 80G2UH090BE12 | 22,800 | $1,140 |
| No | 206906169 | ALLIED | 4HP18V36P | EC4X36B | 80G1UH090BE16 | 22,800 | $1,140 |
| No | 206906171 | ALLIED | 4HP18V36P | EC4X36B | 80G2UH090BE16 | 22,800 | $1,140 |
| No | 206906167 | ALLIED | 4HP18V36P | EC4X36B | 80G1UH070BE12 | 23,000 | $1,150 |
| No | 206906168 | ALLIED | 4HP18V36P | EC4X36B | 80G1UH080BE16X | 22,800 | $1,140 |
| No | 206906166 | ALLIED | 4HP18V36P | EC4X36A | 80G2UH070AV12* | 23,000 | $1,150 |
| No | 206906165 | ALLIED | 4HP18V36P | EC4X36A | 80G2UH070AE12L | 22,800 | $1,140 |
| No | 206906163 | ALLIED | 4HP18V36P | EC4X36A | 80G1UH070AE12 | 23,000 | $1,150 |
| No | 206906162 | ALLIED | 4HP18V36P | EC4X36A | 80G1UH060AE12X | 22,800 | $1,140 |
| No | 206906161 | ALLIED | 4HP18V36P | EC4X36A | 80G1UH045AE12 | 23,000 | $1,150 |
| No | 206906164 | ALLIED | 4HP18V36P | EC4X36A | 80G2UH070AE12 | 22,800 | $1,140 |
| No | 206906082 | ALLIED | 4HP18V36P | EAC4X48C | 95G1UH080CE16X | 22,000 | $1,100 |
| No | 206906071 | ALLIED | 4HP18V36P | EAC4X48B | 95G1UH040BE12X | 22,000 | $1,100 |
| No | 206906072 | ALLIED | 4HP18V36P | EAC4X48B | 95G1UH060BE12X | 22,000 | $1,100 |
| No | 206905878 | ALLIED | 4HP18V36P | E*1P36A+H4TXV02 | 80G2UH070AV12* | 23,000 | $1,150 |
| No | 206906135 | ALLIED | 4HP18V36P | EAH1P48B+H4TXV02 | 96G1UH045BE12 | 22,000 | $1,100 |
| No | 206905994 | ALLIED | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | EFV16CCA | 22,000 | $1,100 |
| No | 206905990 | ALLIED | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 95G1UH080CE16X | 22,200 | $1,110 |
| No | 206905979 | ALLIED | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 95G1UH040BE12X | 22,200 | $1,110 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206905980 | ALLIED | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 95G1UH060BE12X | 22,200 | $1,110 |
| No | 206905963 | ALLIED | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 95G1UH060BE12X | 22,000 | $1,100 |
| No | 206905962 | ALLIED | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 95G1UH040BE12X | 22,000 | $1,100 |
| No | 206905965 | ALLIED | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 96G1UH070BE12 | 22,600 | $1,130 |
| No | 206905964 | ALLIED | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 96G1UH045BE12 | 22,600 | $1,130 |
| No | 206906032 | ALLIED | 4HP18V36P | EAC4X30B | 96G1UH045BE12 | 15,400 | $770 |
| No | 206906140 | ALLIED | 4HP18V36P | EC4X23A | 80G1UH040AE12X | 14,900 | $745 |
| No | 206906028 | ALLIED | 4HP18V36P | EAC4X30B | 95G1UH040BE12X | 15,500 | $775 |
| No | 206906030 | ALLIED | 4HP18V36P | EAC4X30B | 95G1UH070BE12 | 15,400 | $770 |
| No | 206906000 | ALLIED | 4HP18V36P | EAC4X24A | 80G2UH070AE12L | 15,200 | $760 |
| No | 206905998 | ALLIED | 4HP18V36P | EAC4X24A | 80G2UH045AE12 | 15,300 | $765 |
| No | 206906101 | ALLIED | 4HP18V36P | EAH1P30B+H4TXV01 | 95G1UH070BE12 | 15,400 | $770 |
| No | 206906099 | ALLIED | 4HP18V36P | EAH1P30B+H4TXV01 | 95G1UH040BE12X | 15,400 | $770 |
| No | 206906100 | ALLIED | 4HP18V36P | EAH1P30B+H4TXV01 | 95G1UH045BE12 | 15,300 | $765 |
| No | 206906197 | ALLIED | 4HP18V36P | ED1P24B+H4TXV01 | 96G2DF045BV12 | 15,100 | $755 |
| No | 206906196 | ALLIED | 4HP18V36P | ED1P24B+H4TXV01 | 96G1DF070BE16 | 15,000 | $750 |
| No | 206906193 | ALLIED | 4HP18V36P | ED1P24B+H4TXV01 | 80G1DF070BE12 | 15,000 | $750 |
| No | 206906194 | ALLIED | 4HP18V36P | ED1P24B+H4TXV01 | 95G1DF045BE12 | 15,000 | $750 |
| No | 206906192 | ALLIED | 4HP18V36P | ED1P24A+H4TXV01 | 80G2DF070AE12 | 15,100 | $755 |
| No | 206906191 | ALLIED | 4HP18V36P | ED1P24A+H4TXV01 | 80G1DF045AE12 | 15,200 | $760 |
| No | 206906056 | ALLIED | 4HP18V36P | EAC4X36B | 96G1UH045BE12 | 22,600 | $1,130 |
| No | 206906055 | ALLIED | 4HP18V36P | EAC4X36B | 95G1UH060BE12X | 22,000 | $1,100 |
| No | 206906054 | ALLIED | 4HP18V36P | EAC4X36B | 95G1UH040BE12X | 22,000 | $1,100 |
| No | 206906043 | ALLIED | 4HP18V36P | EAC4X36A | 80G2UH070AV12* | 22,200 | $1,110 |
| No | 206906216 | ALLIED | 4HP18V36P | ED1P30/36C+H4TXV02 | 95G1DF090CE16 | 22,000 | $1,100 |
| No | 206906210 | ALLIED | 4HP18V36P | ED1P30/36B+H4TXV02 | 95G1DF070BE16 | 22,000 | $1,100 |
| No | 206906209 | ALLIED | 4HP18V36P | ED1P30/36B+H4TXV02 | 95G1DF045BE12 | 22,400 | $1,120 |
| No | 206906213 | ALLIED | 4HP18V36P | ED1P30/36B+H4TXV02 | 96G2DF045BV12 | 22,200 | $1,110 |
| No | 206906203 | ALLIED | 4HP18V36P | ED1P30/36A+H4TXV02 | 80G2DF070AE12 | 22,000 | $1,100 |
| No | 206906201 | ALLIED | 4HP18V36P | ED1P30/36A+H4TXV02 | 80G1DF045AE12 | 22,200 | $1,110 |
| No | 206905899 | ALLIED | 4HP18V36P | E*1P36C+H4TXV02 | 95G1UH090CE16 | 23,000 | $1,150 |
| No | 206905898 | ALLIED | 4HP18V36P | E*1P36C+H4TXV02 | 95G1UH080CE16X | 22,800 | $1,140 |
| No | 206905889 | ALLIED | 4HP18V36P | E*1P36B+H4TXV02 | 96G1UH045BE12 | 23,200 | $1,160 |
| No | 206905885 | ALLIED | 4HP18V36P | E*1P36B+H4TXV02 | 80G2UH090BV16* | 22,800 | $1,140 |
| No | 206905865 | ALLIED | 4HP18V36P | E*1P23B+H4TXV01 | 95G1UH070BE12 | 14,900 | $745 |
| No | 206905864 | ALLIED | 4HP18V36P | E*1P23B+H4TXV01 | 95G1UH045BE12 | 14,800 | $740 |
| No | 206905857 | ALLIED | 4HP18V36P | E*1P23A+H4TXV01 | 80G2UH070AE12L | 14,900 | $745 |
| No | 206905938 | ALLIED | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 95G1UH070BE12 | 15,400 | $770 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206905936 | ALLIED | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 95G1UH040BE12X | 15,500 | $775 |
| No | 206905937 | ALLIED | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 95G1UH045BE12 | 15,400 | $770 |
| No | 206905912 | ALLIED | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 92G1UH030BE12 | 15,300 | $765 |
| No | 206905906 | ALLIED | 4HP18V36P | EA(C,U)1P24A+H4TXV01 | 80G2UH045AE12 | 15,300 | $765 |
| No | 206905951 | ALLIED | 4HP18V36P | EA(C,U)1P36A+H4TXV02 | 80G2UH070AV12* | 22,200 | $1,110 |
| No | 206906159 | ALLIED | 4HP18V36P | EC4X23B | EFV08BCA | 15,100 | $755 |
| No | 206906160 | ALLIED | 4HP18V36P | EC4X23B | EFV12BCA | 14,900 | $745 |
| No | 206906014 | ALLIED | 4HP18V36P | EAC4X24B | EFV08BCA | 15,400 | $770 |
| No | 206906158 | ALLIED | 4HP18V36P | EC4X23B | 96G2UH070BV12 | 14,800 | $740 |
| No | 206906155 | ALLIED | 4HP18V36P | EC4X23B | 96G1UH045BE12 | 14,900 | $745 |
| No | 206906156 | ALLIED | 4HP18V36P | EC4X23B | 96G1UH070BE12 | 14,800 | $740 |
| No | 206906154 | ALLIED | 4HP18V36P | EC4X23B | 96G1UH030BE08 | 14,900 | $745 |
| No | 206906153 | ALLIED | 4HP18V36P | EC4X23B | 95G1UH070BE12 | 14,900 | $745 |
| No | 206906152 | ALLIED | 4HP18V36P | EC4X23B | 95G1UH045BE12 | 14,800 | $740 |
| No | 206906157 | ALLIED | 4HP18V36P | EC4X23B | 96G2UH045BV12 | 14,900 | $745 |
| No | 206906150 | ALLIED | 4HP18V36P | EC4X23B | 92G1UH045BE12 | 14,800 | $740 |
| No | 206906148 | ALLIED | 4HP18V36P | EC4X23B | 80G2UH090BE12 | 14,900 | $745 |
| No | 206906149 | ALLIED | 4HP18V36P | EC4X23B | 92G1UH030BE12 | 15,000 | $750 |
| No | 206906147 | ALLIED | 4HP18V36P | EC4X23B | 80G1UH070BE12 | 14,800 | $740 |
| No | 206906151 | ALLIED | 4HP18V36P | EC4X23B | 92G1UH070BE12 | 14,900 | $745 |
| No | 206906145 | ALLIED | 4HP18V36P | EC4X23A | 80G2UH070AE12L | 14,900 | $745 |
| No | 206906146 | ALLIED | 4HP18V36P | EC4X23A | 80G2UH070AV12* | 14,900 | $745 |
| No | 206906144 | ALLIED | 4HP18V36P | EC4X23A | 80G2UH070AE12 | 14,900 | $745 |
| No | 206906141 | ALLIED | 4HP18V36P | EC4X23A | 80G1UH045AE12 | 15,000 | $750 |
| No | 206906142 | ALLIED | 4HP18V36P | EC4X23A | 80G1UH060AE12X | 14,900 | $745 |
| No | 206906143 | ALLIED | 4HP18V36P | EC4X23A | 80G2UH045AE12 | 15,000 | $750 |
| No | 206906808 | ALLIED | 4HP18V60P | E*1P50C+H4TXV03 | 95G1UH110CE20 | 40,000 | $2,000 |
| No | 206906807 | ALLIED | 4HP18V60P | E*1P50C+H4TXV03 | 95G1UH100CE20X | 40,000 | $2,000 |
| No | 206906978 | ALLIED | 4HP18V60P | ED1P60D+H4TXV03 | 95G1DF110CE20 | 37,400 | $1,870 |
| No | 206906968 | ALLIED | 4HP18V60P | EAH1P60D+H4TXV03 | EFV20DCA | 36,600 | $1,830 |
| No | 206906933 | ALLIED | 4HP18V60P | EAC4X60C | EFV16CCA | 37,400 | $1,870 |
| No | 206906929 | ALLIED | 4HP18V60P | EAC4X60C | 95G1UH110CE20 | 37,200 | $1,860 |
| No | 206906928 | ALLIED | 4HP18V60P | EAC4X60C | 95G1UH100CE20X | 38,000 | $1,900 |
| No | 206906871 | ALLIED | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | EFV16CCA | 37,400 | $1,870 |
| No | 206906867 | ALLIED | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 95G1UH110CE20 | 37,200 | $1,860 |
| No | 206906866 | ALLIED | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 95G1UH100CE20X | 38,000 | $1,900 |
| No | 206906797 | ALLIED | 4HP18V60P | BCE5E60M | | 37,800 | $1,890 |
| No | 206906975 | ALLIED | 4HP18V60P | ED1P50/60C+H4TXV02 | 96G2DF110CV20 | 30,800 | $1,540 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206906974 | ALLIED | 4HP18V60P | ED1P50/60C+H4TXV02 | 96G2DF090CV20 | 30,800 | $1,540 |
| No | 206906972 | ALLIED | 4HP18V60P | ED1P50/60C+H4TXV02 | 95G1DF110CE20 | 30,400 | $1,520 |
| No | 206906973 | ALLIED | 4HP18V60P | ED1P50/60C+H4TXV02 | 96G1DF090CE16 | 30,800 | $1,540 |
| No | 206906971 | ALLIED | 4HP18V60P | ED1P50/60C+H4TXV02 | 95G1DF090CE16 | 30,600 | $1,530 |
| No | 206906970 | ALLIED | 4HP18V60P | ED1P50/60C+H4TXV02 | 92G1DF090CE16 | 30,600 | $1,530 |
| No | 206906969 | ALLIED | 4HP18V60P | ED1P50/60C+H4TXV02 | 80G1DF110CE20 | 30,400 | $1,520 |
| No | 208106662 | ALLIED | 4DHP2S24S-1P | DMD224S4-1P | | 13,500 | $675 |
| No | 208106757 | ALLIED | 4DHP2S36S-1P | D33C236S4-1P | | 23,000 | $1,150 |
| No | 208106758 | ALLIED | 4DHP2S48S-1P | D33C248S4-1P | | 28,000 | $1,400 |
| No | 208106759 | ALLIED | 4DHP2S36S-1P | DMD236S4-2P | | 27,000 | $1,350 |
| No | 208106760 | ALLIED | 4DHP2S48S-1P | DMD248S4-2P | | 29,000 | $1,450 |
| No | 208106659 | ALLIED | 4DHP2S24S-1P | D33C224S4-1P | | 15,600 | $780 |
| No | 208106658 | ALLIED | 4DHP2S18S-1P | D22C118S4-1P | | 12,000 | $600 |
| No | 211644098 | Alsetria | MOX230-09HFN1-MW5W | MCBU-06HRFN1-MV0W | | 5,700 | $285 |
| No | 211644100 | Alsetria | MOX330-12HFN1-MW5W | MCBU-12HRFN1-MV0W | | 9,500 | $475 |
| No | 211644099 | Alsetria | MOX330-09HFN1-MY5W | MCBU-09HRFN1-MW0W | | 9,800 | $490 |
| No | 211644097 | Alsetria | MOX430-18HFN1-MU0W | MFA2U-16HRFN1-MV0W | | 13,400 | $670 |
| No | 211644096 | Alsetria | MOX230-12HFN1-MV5W | MFA2U-12HRFN1-MW5W | | 9,200 | $460 |
| No | 211644030 | Alsetria | MOE30U-60HFN1-M(GA)(X) | MHG-60HWFN1-MW | | 34,400 | $1,720 |
| No | 211644026 | Alsetria | MOX430-18HFN1-MU0W | MTIU-18HWFN1-M | | 12,600 | $630 |
| No | 211644033 | Alsetria | MOX430-18HFN1-MU0W | CCA3U-18HRFN1-M(C) | | 12,000 | $600 |
| No | 211644034 | Alsetria | MOD33-24HFN1-MT0W | MCD1-24HRFN1-MT0W(GA) | | 19,000 | $950 |
| No | 211644041 | Alsetria | MOE30U-36HFN1-M(GA) | MTI-36HWFN1-M | | 34,000 | $1,700 |
| No | 211644029 | Alsetria | MOE30U-48HFN1-MP0(GA) | MTI-48HWFN1-M | | 34,000 | $1,700 |
| No | 211644036 | Alsetria | MOE30U-48HFN1-MP0(GA) | MCD1-48HRFN1-M(GA) | | 30,000 | $1,500 |
| No | 211644028 | Alsetria | MOD30U-36HFN1-MP0(GA) | MTI-36HWFN1-M | | 25,000 | $1,250 |
| No | 211644035 | Alsetria | MOD30U-36HFN1-MP0(GA) | MCD1-36HRFN1-M(GA) | | 23,000 | $1,150 |
| No | 211644027 | Alsetria | MOD33-24HFN1-MT0W | MTIU-24HWFN1-M | | 20,000 | $1,000 |
| No | 211644045 | Alsetria | MOX430-17HFN1-MT0W | CCA3U-18HRFN1-M(C) | | 15,600 | $780 |
| No | 211644038 | Alsetria | MOX330-12HFN1-MW5W | MTIU-12HWFN1-M | | 10,600 | $530 |
| No | 211644044 | Alsetria | MOX330-12HFN1-MW5W | CCA3U-12HRFN1-M(C) | | 9,900 | $495 |
| No | 211644025 | Alsetria | MOX230-12HFN1-MV5W | MTIU-12HWFN1-M | | 9,300 | $465 |
| No | 211644037 | Alsetria | MOX330-09HFN1-MY5W | MTIU-09HWFN1-M | | 10,100 | $505 |
| No | 211644043 | Alsetria | MOX330-09HFN1-MY5W | CCA3U-09HRFN1-M(C) | | 9,000 | $450 |
| No | 211644024 | Alsetria | MOX230-09HFN1-MW5W | MTIU-09HWFN1-M | | 7,700 | $385 |
| No | 211644032 | Alsetria | MOX230-12HFN1-MV5W | CCA3U-12HRFN1-M(C) | | 8,900 | $445 |
| No | 211644031 | Alsetria | MOX230-09HFN1-MW5W | CCA3U-09HRFN1-M(C) | | 7,500 | $375 |
| No | 211644105 | Alsetria | MOD30U-36HFN1-M(GA) | MVCU-36HWFN1-M(GA) | | 27,000 | $1,350 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208130390 | Alsetria | MOE30U-60HFN1-MR0 | MVC-60HWFN1-M | | 37,000 | $1,850 |
| No | 208130389 | Alsetria | MOE30U-48HFN1-MR0 | MVC-48HWFN1-M | | 37,000 | $1,850 |
| No | 208130388 | Alsetria | MOD30U-36HFN1-MR0 | MVC-36HWFN1-M | | 20,400 | $1,020 |
| No | 208130386 | Alsetria | MOX430U-24HFN1-MR0 | MVC-24HWFN1-M | | 21,000 | $1,050 |
| No | 208130385 | Alsetria | MOX330U-18HFN1-MR0 | MVC-18HWFN1-M | | 12,000 | $600 |
| No | 211644104 | Alsetria | MOD30U-30HFN1-M(GA) | MVC-30HWFN1-M(GA) | | 20,400 | $1,020 |
| No | 211644103 | Alsetria | MOD33-24HFN1-MT0W | MVC-23HWFN1-M | | 17,000 | $850 |
| No | 211644102 | Alsetria | MOX430-18HFN1-MU0W | MVC-18HWFN1-MW(GA) | | 13,200 | $660 |
| No | 208130394 | Alsetria | MOE31U-36HFN1-M | MVC-36HWFN1-M | | 30,400 | $1,520 |
| No | 208130393 | Alsetria | MOD30U-30HFN1-MR0(X) | MVC-30HWFN1-M | | 21,000 | $1,050 |
| No | 208121914 | ALSETRIA | M5OG-48HFN1-M | Heat pump without ducts | | 34,000 | $1,700 |
| No | 208121911 | ALSETRIA | M4OG-36HFN1-M | Heat pump without ducts | | 26,800 | $1,340 |
| No | 208121909 | ALSETRIA | M3OJ-27HFN1-M | Heat pump with ducts | | 22,000 | $1,100 |
| No | 208121906 | ALSETRIA | M2OA-18HFN1-M | Heat pump with ducts | | 14,800 | $740 |
| No | 208121908 | ALSETRIA | M3OJ-27HFN1-M | Heat pump without ducts | | 21,000 | $1,050 |
| No | 208121905 | ALSETRIA | M2OA-18HFN1-M | Heat pump without ducts | | 14,300 | $715 |
| No | 208121886 | Alsetria | MOD30U-30HFN1-M(GA) | MSAGF-30HRFN1-MT0W | | 20,000 | $1,000 |
| No | 208121894 | Alsetria | MOD31-23HFN1-MT2Q1W | MSABE-23HRFN1-MT2Q1W | | 17,900 | $895 |
| No | 208121893 | Alsetria | MOX430-18HFN1-MT2Q1W | MSABE-18HRFN1-MT2Q1W | | 13,800 | $690 |
| No | 208121892 | Alsetria | MOX230-12HFN1-BV0Q1W | MSABB-12HRFN1-BV0Q1W | | 7,500 | $375 |
| No | 208121900 | Alsetria | MOX230-09HFN1-MW5W | MSEPB-06HRFN1-MY5W | | 8,500 | $425 |
| No | 208121899 | Alsetria | MOD33-24HFN1-MT0W | MSEPD-24HRFN1-MU0W | | 16,200 | $810 |
| No | 208121897 | Alsetria | MOX230-12HFN1-MV5W | MSEPB-12HRFN1-MW5W(GA) | | 9,000 | $450 |
| No | 208121896 | Alsetria | MOX230-09HFN1-MW5W | MSEPB-09HRFN1-MY5W(GA) | | 8,500 | $425 |
| No | 208121885 | Alsetria | MOX430-24HFN1-MR0W | MSAG11D-24HRFN1-MR0W | | 16,500 | $825 |
| No | 208121884 | Alsetria | MOX330-18HFN1-MS0W | MSAG11C-18HRDN1-MS0W | | 11,400 | $570 |
| No | 208121883 | Alsetria | MOX230-12HFN1-MS8W | MSAG11B-12HRFN1-MS0W | | 7,000 | $350 |
| No | 208121882 | Alsetria | MOX230-09HFN1-MT0W | MSAG11A-09HRFN1-MT0W | | 6,000 | $300 |
| No | 208121881 | Alsetria | MOX230-12HFN1-BS8W | MSAG11B-12HRFN1-BS0W | | 7,800 | $390 |
| No | 208121880 | Alsetria | MOX230-09HFN1-BS5W | MSAG11A-09HRFN1-BS5W | | 6,300 | $315 |
| No | 208121902 | Alsetria | MOX330-12HFN1-MW5W | MSEPB-12HRFN1-MW5W(GA) | | 10,000 | $500 |
| No | 208121901 | Alsetria | MOX330-09HFN1-MY5W | MSEPB-09HRFN1-MY5W(GA) | | 9,500 | $475 |
| No | 208121916 | ALSETRIA | M5OG-48HFN1-M | Combination heat pumps with or without ducts | | 30,000 | $1,500 |
| No | 208121915 | ALSETRIA | M5OG-48HFN1-M | Heat pump with ducts | | 30,400 | $1,520 |
| No | 208121910 | ALSETRIA | M3OJ-27HFN1-M | Combination heat pumps with or without ducts | | 16,000 | $800 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208121907 | ALSETRIA | M2OA-18HFN1-M | Combination heat pumps with or without ducts | | 11,400 | $570 |
| No | 208130387 | ALSETRIA | MOD30U-30HFN1-MR0 | MVC-30HWFN1-M | | 19,000 | $950 |
| No | 208121895 | ALSETRIA | MOD30-36HFN1-MR0Q1W | MSABF-36HRFN1-MR0Q1W | | 21,000 | $1,050 |
| No | 208121887 | ALSETRIA | MOD31-36HFN1-MP0W | MSAGF-36HRFNX-MR0W | | 20,000 | $1,000 |
| No | 208121898 | ALSETRIA | MOX430-18HFN1-MT8W | MSEPC-18HRFN1-MU0W | | 12,700 | $635 |
| No | 210773183 | AMANA | ASZS606010A* | AHVE60DP1400A* | | 34,800 | $1,740 |
| No | 210798388 | AMANA | ASZS604810A* | AHVE60DP1400A* | | 29,800 | $1,490 |
| No | 210773182 | AMANA | ASZS604810A* | AHVE48DP1400A* | | 29,800 | $1,490 |
| No | 210854822 | AMANA | ASZS603610A* | CA*EA3026*4A*+MBVC2000**-1A* | | 22,400 | $1,120 |
| No | 210854821 | AMANA | ASZS603610A* | CA*EA3026*4A*+MBVC1600**-1A* | | 22,400 | $1,120 |
| No | 210854820 | AMANA | ASZS603610A* | CA*EA3026*4A*+MBVC1200**-1A* | | 22,400 | $1,120 |
| No | 210798518 | AMANA | ASZS603610A* | CA*EA3026*4A* | A*VS960805CUA* | 22,400 | $1,120 |
| No | 210798507 | AMANA | ASZS603610A* | CA*EA3026*4A* | A*VS960603BUA* | 22,400 | $1,120 |
| No | 210798527 | AMANA | ASZS603610A* | CA*EA3026*4A* | A*VM971205DNB* | 22,400 | $1,120 |
| No | 210798522 | AMANA | ASZS603610A* | CA*EA3026*4A* | A*VM971005CNB* | 22,400 | $1,120 |
| No | 210798521 | AMANA | ASZS603610A* | CA*EA3026*4A* | A*VM970804CNB* | 22,400 | $1,120 |
| No | 210798512 | AMANA | ASZS603610A* | CA*EA3026*4A* | A*VM970803BNB* | 22,400 | $1,120 |
| No | 210798511 | AMANA | ASZS603610A* | CA*EA3026*4A* | A*VM970603BNB* | 22,400 | $1,120 |
| No | 210798526 | AMANA | ASZS603610A* | CA*EA3026*4A* | A*VC961205DNB* | 22,400 | $1,120 |
| No | 210798525 | AMANA | ASZS603610A* | CA*EA3026*4A* | A*VC961005DNB* | 22,400 | $1,120 |
| No | 210798520 | AMANA | ASZS603610A* | CA*EA3026*4A* | A*VC961005CNB* | 22,400 | $1,120 |
| No | 210798519 | AMANA | ASZS603610A* | CA*EA3026*4A* | A*VC960804CNB* | 22,400 | $1,120 |
| No | 210798510 | AMANA | ASZS603610A* | CA*EA3026*4A* | A*VC960803BNB* | 22,400 | $1,120 |
| No | 210798509 | AMANA | ASZS603610A* | CA*EA3026*4A* | A*VC960603BNB* | 22,400 | $1,120 |
| No | 210798508 | AMANA | ASZS603610A* | CA*EA3026*4A* | A*VC960403BNB* | 22,400 | $1,120 |
| No | 210798385 | AMANA | ASZS603610A* | AHVE42CP1400A* | | 22,400 | $1,120 |
| No | 210773178 | AMANA | ASZS603610A* | AHVE36CP1400A* | | 22,400 | $1,120 |
| No | 210854819 | AMANA | ASZS603010A* | CA*EA3026*4A*+MBVC1600**-1A* | | 18,000 | $900 |
| No | 210854818 | AMANA | ASZS603010A* | CA*EA3026*4A*+MBVC1200**-1A* | | 18,000 | $900 |
| No | 210798497 | AMANA | ASZS603010A* | CA*EA3026*4A* | A*VS960805CUA* | 18,000 | $900 |
| No | 210798486 | AMANA | ASZS603010A* | CA*EA3026*4A* | A*VS960603BUA* | 18,000 | $900 |
| No | 210798501 | AMANA | ASZS603010A* | CA*EA3026*4A* | A*VM971005CNB* | 18,000 | $900 |
| No | 210798500 | AMANA | ASZS603010A* | CA*EA3026*4A* | A*VM970804CNB* | 18,000 | $900 |
| No | 210798491 | AMANA | ASZS603010A* | CA*EA3026*4A* | A*VM970803BNB* | 18,000 | $900 |
| No | 210798490 | AMANA | ASZS603010A* | CA*EA3026*4A* | A*VM970603BNB* | 18,000 | $900 |
| No | 210798499 | AMANA | ASZS603010A* | CA*EA3026*4A* | A*VC961005CNB* | 18,000 | $900 |
| No | 210798498 | AMANA | ASZS603010A* | CA*EA3026*4A* | A*VC960804CNB* | 18,000 | $900 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210798489 | AMANA | ASZS603010A* | CA*EA3026*4A* | A*VC960803BNB* | 18,000 | $900 |
| No | 210798488 | AMANA | ASZS603010A* | CA*EA3026*4A* | A*VC960603BNB* | 18,000 | $900 |
| No | 210798487 | AMANA | ASZS603010A* | CA*EA3026*4A* | A*VC960403BNB* | 18,000 | $900 |
| No | 210854817 | AMANA | ASZS603010A* | CA*EA2422*4A*+MBVC1600**-1A* | | 18,000 | $900 |
| No | 210854816 | AMANA | ASZS603010A* | CA*EA2422*4A*+MBVC1200**-1A* | | 18,000 | $900 |
| No | 210798476 | AMANA | ASZS603010A* | CA*EA2422*4A* | A*VS960805CUA* | 18,000 | $900 |
| No | 210798465 | AMANA | ASZS603010A* | CA*EA2422*4A* | A*VS960603BUA* | 18,000 | $900 |
| No | 210798480 | AMANA | ASZS603010A* | CA*EA2422*4A* | A*VM971005CNB* | 18,000 | $900 |
| No | 210798479 | AMANA | ASZS603010A* | CA*EA2422*4A* | A*VM970804CNB* | 18,000 | $900 |
| No | 210798470 | AMANA | ASZS603010A* | CA*EA2422*4A* | A*VM970803BNB* | 18,000 | $900 |
| No | 210798469 | AMANA | ASZS603010A* | CA*EA2422*4A* | A*VM970603BNB* | 18,000 | $900 |
| No | 210798478 | AMANA | ASZS603010A* | CA*EA2422*4A* | A*VC961005CNB* | 18,000 | $900 |
| No | 210798477 | AMANA | ASZS603010A* | CA*EA2422*4A* | A*VC960804CNB* | 18,000 | $900 |
| No | 210798468 | AMANA | ASZS603010A* | CA*EA2422*4A* | A*VC960803BNB* | 18,000 | $900 |
| No | 210798467 | AMANA | ASZS603010A* | CA*EA2422*4A* | A*VC960603BNB* | 18,000 | $900 |
| No | 210798466 | AMANA | ASZS603010A* | CA*EA2422*4A* | A*VC960403BNB* | 18,000 | $900 |
| No | 210773176 | AMANA | ASZS603010A* | AHVE36CP1400A* | | 18,000 | $900 |
| No | 210854815 | AMANA | ASZS602410A* | CA*EA2422*4A*+MBVC1600**-1A* | | 14,600 | $730 |
| No | 210854814 | AMANA | ASZS602410A* | CA*EA2422*4A*+MBVC1200**-1A* | | 14,600 | $730 |
| No | 210798457 | AMANA | ASZS602410A* | CA*EA2422*4A* | A*VS960805CUA* | 14,600 | $730 |
| No | 210798447 | AMANA | ASZS602410A* | CA*EA2422*4A* | A*VS960603BUA* | 14,600 | $730 |
| No | 210798459 | AMANA | ASZS602410A* | CA*EA2422*4A* | A*VM970804CNB* | 14,600 | $730 |
| No | 210798452 | AMANA | ASZS602410A* | CA*EA2422*4A* | A*VM970803BNB* | 14,600 | $730 |
| No | 210798451 | AMANA | ASZS602410A* | CA*EA2422*4A* | A*VM970603BNB* | 14,600 | $730 |
| No | 210798458 | AMANA | ASZS602410A* | CA*EA2422*4A* | A*VC960804CNB* | 14,600 | $730 |
| No | 210798450 | AMANA | ASZS602410A* | CA*EA2422*4A* | A*VC960803BNB* | 14,600 | $730 |
| No | 210798449 | AMANA | ASZS602410A* | CA*EA2422*4A* | A*VC960603BNB* | 14,600 | $730 |
| No | 210798448 | AMANA | ASZS602410A* | CA*EA2422*4A* | A*VC960403BNB* | 14,600 | $730 |
| No | 210854813 | AMANA | ASZS602410A* | CA*EA1818*4A*+MBVC1600**-1A* | | 14,600 | $730 |
| No | 210854812 | AMANA | ASZS602410A* | CA*EA1818*4A*+MBVC1200**-1A* | | 14,600 | $730 |
| No | 210798439 | AMANA | ASZS602410A* | CA*EA1818*4A* | A*VS960805CUA* | 14,600 | $730 |
| No | 210798429 | AMANA | ASZS602410A* | CA*EA1818*4A* | A*VS960603BUA* | 14,600 | $730 |
| No | 210798441 | AMANA | ASZS602410A* | CA*EA1818*4A* | A*VM970804CNB* | 14,600 | $730 |
| No | 210798434 | AMANA | ASZS602410A* | CA*EA1818*4A* | A*VM970803BNB* | 14,600 | $730 |
| No | 210798433 | AMANA | ASZS602410A* | CA*EA1818*4A* | A*VM970603BNB* | 14,600 | $730 |
| No | 210798440 | AMANA | ASZS602410A* | CA*EA1818*4A* | A*VC960804CNB* | 14,600 | $730 |
| No | 210798432 | AMANA | ASZS602410A* | CA*EA1818*4A* | A*VC960803BNB* | 14,600 | $730 |
| No | 210798431 | AMANA | ASZS602410A* | CA*EA1818*4A* | A*VC960603BNB* | 14,600 | $730 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210798430 | AMANA | ASZS602410A* | CA*EA1818*4A* | A*VC960403BNB* | 14,600 | $730 |
| No | 210773174 | AMANA | ASZS602410A* | AHVE24BP1400A* | | 14,600 | $730 |
| No | 210854810 | AMANA | ASZS601810A* | CA*EA2422*4A*+MBVC1600**-1A* | | 10,800 | $540 |
| No | 210854809 | AMANA | ASZS601810A* | CA*EA2422*4A*+MBVC1200**-1A* | | 10,800 | $540 |
| No | 210798421 | AMANA | ASZS601810A* | CA*EA2422*4A* | A*VS960805CUA* | 10,800 | $540 |
| No | 210798411 | AMANA | ASZS601810A* | CA*EA2422*4A* | A*VS960603BUA* | 10,800 | $540 |
| No | 210798423 | AMANA | ASZS601810A* | CA*EA2422*4A* | A*VM970804CNB* | 10,800 | $540 |
| No | 210798416 | AMANA | ASZS601810A* | CA*EA2422*4A* | A*VM970803BNB* | 10,800 | $540 |
| No | 210798415 | AMANA | ASZS601810A* | CA*EA2422*4A* | A*VM970603BNB* | 10,800 | $540 |
| No | 210798422 | AMANA | ASZS601810A* | CA*EA2422*4A* | A*VC960804CNB* | 10,800 | $540 |
| No | 210798414 | AMANA | ASZS601810A* | CA*EA2422*4A* | A*VC960803BNB* | 10,800 | $540 |
| No | 210798413 | AMANA | ASZS601810A* | CA*EA2422*4A* | A*VC960603BNB* | 10,800 | $540 |
| No | 210798412 | AMANA | ASZS601810A* | CA*EA2422*4A* | A*VC960403BNB* | 10,800 | $540 |
| No | 210854808 | AMANA | ASZS601810A* | CA*EA1818*4A*+MBVC1600**-1A* | | 10,800 | $540 |
| No | 210854807 | AMANA | ASZS601810A* | CA*EA1818*4A*+MBVC1200**-1A* | | 10,800 | $540 |
| No | 210798403 | AMANA | ASZS601810A* | CA*EA1818*4A* | A*VS960805CUA* | 10,800 | $540 |
| No | 210798393 | AMANA | ASZS601810A* | CA*EA1818*4A* | A*VS960603BUA* | 10,800 | $540 |
| No | 210798405 | AMANA | ASZS601810A* | CA*EA1818*4A* | A*VM970804CNB* | 10,800 | $540 |
| No | 210798398 | AMANA | ASZS601810A* | CA*EA1818*4A* | A*VM970803BNB* | 10,800 | $540 |
| No | 210798397 | AMANA | ASZS601810A* | CA*EA1818*4A* | A*VM970603BNB* | 10,800 | $540 |
| No | 210798404 | AMANA | ASZS601810A* | CA*EA1818*4A* | A*VC960804CNB* | 10,800 | $540 |
| No | 210798396 | AMANA | ASZS601810A* | CA*EA1818*4A* | A*VC960803BNB* | 10,800 | $540 |
| No | 210798395 | AMANA | ASZS601810A* | CA*EA1818*4A* | A*VC960603BNB* | 10,800 | $540 |
| No | 210798394 | AMANA | ASZS601810A* | CA*EA1818*4A* | A*VC960403BNB* | 10,800 | $540 |
| No | 210773171 | AMANA | ASZS601810A* | AHVE24BP1400A* | | 10,800 | $540 |
| No | 210692659 | AMANA | ASZV906010A* | CSCF4860N6D*+TXV | A*VM971205DNB* | 32,400 | $1,620 |
| No | 210692658 | AMANA | ASZV906010A* | CSCF4860N6D*+TXV | A*VM971005CNB* | 32,400 | $1,620 |
| No | 210692657 | AMANA | ASZV906010A* | CSCF4860N6D*+TXV | A*VC961205DNB* | 32,400 | $1,620 |
| No | 210692656 | AMANA | ASZV906010A* | CSCF4860N6D*+TXV | A*VC961005CNB* | 32,400 | $1,620 |
| No | 210692655 | AMANA | ASZV906010A* | CSCF4860N6D*+TXV | A*VS960805CUA* | 32,400 | $1,620 |
| No | 210692651 | AMANA | ASZV906010A* | CHPF4860D6D*+TXV | A*VM971205DNB* | 32,400 | $1,620 |
| No | 210692650 | AMANA | ASZV906010A* | CHPF4860D6D*+TXV | A*VM971005CNB* | 32,400 | $1,620 |
| No | 210692649 | AMANA | ASZV906010A* | CHPF4860D6D*+TXV | A*VC961205DNB* | 32,400 | $1,620 |
| No | 210692648 | AMANA | ASZV906010A* | CHPF4860D6D*+TXV | A*VC961005CNB* | 32,400 | $1,620 |
| No | 210692647 | AMANA | ASZV906010A* | CHPF4860D6D*+TXV | A*VS960805CUA* | 32,400 | $1,620 |
| No | 210692643 | AMANA | ASZV906010A* | CHPF4860D6D*+MBVC2001**-1A*+TXV | | 32,400 | $1,620 |
| No | 210692642 | AMANA | ASZV906010A* | CA*F4961*6D*+TXV | A*VM971205DNB* | 33,400 | $1,670 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210692641 | AMANA | ASZV906010A* | CA*F4961*6D*+TXV | A*VM971005CNB* | 33,400 | $1,670 |
| No | 210692640 | AMANA | ASZV906010A* | CA*F4961*6D*+TXV | A*VC961205DNB* | 33,400 | $1,670 |
| No | 210692639 | AMANA | ASZV906010A* | CA*F4961*6D*+TXV | A*VC961005CNB* | 33,400 | $1,670 |
| No | 210692638 | AMANA | ASZV906010A* | CA*F4961*6D*+TXV | A*VS960805CUA* | 33,400 | $1,670 |
| No | 210607423 | AMANA | ASZV906010A* | CA*F4961*6D*+MBVC2001**-1A*+TX | | 34,000 | $1,700 |
| No | 210609990 | AMANA | ASZV906010A* | AMVE60DP1400A* | | 33,400 | $1,670 |
| No | 210692634 | AMANA | ASZV904810A* | CSCF4860N6D*+TXV | A*VM971205DNB* | 27,000 | $1,350 |
| No | 210692633 | AMANA | ASZV904810A* | CSCF4860N6D*+TXV | A*VM971005CNB* | 27,000 | $1,350 |
| No | 210692632 | AMANA | ASZV904810A* | CSCF4860N6D*+TXV | A*VM970804CNB* | 27,000 | $1,350 |
| No | 210692631 | AMANA | ASZV904810A* | CSCF4860N6D*+TXV | A*VC961205DNB* | 27,000 | $1,350 |
| No | 210692630 | AMANA | ASZV904810A* | CSCF4860N6D*+TXV | A*VC961005CNB* | 27,000 | $1,350 |
| No | 210692629 | AMANA | ASZV904810A* | CSCF4860N6D*+TXV | A*VS960805CUA* | 27,000 | $1,350 |
| No | 210692628 | AMANA | ASZV904810A* | CSCF4860N6D*+TXV | A*VC960804CNB* | 27,000 | $1,350 |
| No | 210692622 | AMANA | ASZV904810A* | CSCF4860N6D*+MBVC2001**-1A*+TXV | | 27,000 | $1,350 |
| No | 210692621 | AMANA | ASZV904810A* | CSCF4860N6D*+MBVC1601**-1A*+TXV | | 27,000 | $1,350 |
| No | 210692620 | AMANA | ASZV904810A* | CHPF4860D6D*+TXV | A*VM971205DNB* | 27,000 | $1,350 |
| No | 210692619 | AMANA | ASZV904810A* | CHPF4860D6D*+TXV | A*VM971005CNB* | 27,000 | $1,350 |
| No | 210692618 | AMANA | ASZV904810A* | CHPF4860D6D*+TXV | A*VM970804CNB* | 27,000 | $1,350 |
| No | 210692617 | AMANA | ASZV904810A* | CHPF4860D6D*+TXV | A*VC961205DNB* | 27,000 | $1,350 |
| No | 210692616 | AMANA | ASZV904810A* | CHPF4860D6D*+TXV | A*VC961005CNB* | 27,000 | $1,350 |
| No | 210692615 | AMANA | ASZV904810A* | CHPF4860D6D*+TXV | A*VC960804CNB* | 27,000 | $1,350 |
| No | 210692611 | AMANA | ASZV904810A* | CHPF4860D6D*+MBVC2001**-1A*+TXV | | 27,000 | $1,350 |
| No | 210692610 | AMANA | ASZV904810A* | CHPF4860D6D*+MBVC1601**-1A*+TXV | | 27,000 | $1,350 |
| No | 210692609 | AMANA | ASZV904810A* | CA*F4961*6D*+TXV | A*VM971205DNB* | 27,000 | $1,350 |
| No | 210692608 | AMANA | ASZV904810A* | CA*F4961*6D*+TXV | A*VM971005CNB* | 27,000 | $1,350 |
| No | 210692607 | AMANA | ASZV904810A* | CA*F4961*6D*+TXV | A*VM970804CNB* | 27,000 | $1,350 |
| No | 210692606 | AMANA | ASZV904810A* | CA*F4961*6D*+TXV | A*VC961205DNB* | 27,000 | $1,350 |
| No | 210692605 | AMANA | ASZV904810A* | CA*F4961*6D*+TXV | A*VC961005CNB* | 27,000 | $1,350 |
| No | 210692604 | AMANA | ASZV904810A* | CA*F4961*6D*+TXV | A*VS960805CUA* | 27,000 | $1,350 |
| No | 210692603 | AMANA | ASZV904810A* | CA*F4961*6D*+TXV | A*VC960804CNB* | 27,000 | $1,350 |
| No | 210607580 | AMANA | ASZV904810A* | CA*F4961*6D*+MBVC2001**-1A*+TX | | 27,000 | $1,350 |
| No | 210692597 | AMANA | ASZV904810A* | CA*F4961*6D*+MBVC1601**-1A*+TXV | | 27,000 | $1,350 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210692596 | AMANA | ASZV904810A* | CA*F4860*6D*+TXV | A*VM971205DNB* | 27,000 | $1,350 |
| No | 210692595 | AMANA | ASZV904810A* | CA*F4860*6D*+TXV | A*VM971005CNB* | 27,000 | $1,350 |
| No | 210692594 | AMANA | ASZV904810A* | CA*F4860*6D*+TXV | A*VM970804CNB* | 27,000 | $1,350 |
| No | 210692593 | AMANA | ASZV904810A* | CA*F4860*6D*+TXV | A*VC961205DNB* | 27,000 | $1,350 |
| No | 210692592 | AMANA | ASZV904810A* | CA*F4860*6D*+TXV | A*VC961005CNB* | 27,000 | $1,350 |
| No | 210692591 | AMANA | ASZV904810A* | CA*F4860*6D*+TXV | A*VS960805CUA* | 27,000 | $1,350 |
| No | 210692590 | AMANA | ASZV904810A* | CA*F4860*6D*+TXV | A*VC960804CNB* | 27,000 | $1,350 |
| No | 210692585 | AMANA | ASZV904810A* | CA*F4860*6D*+MBVC2001**-1A*+TXV | | 27,000 | $1,350 |
| No | 210692584 | AMANA | ASZV904810A* | CA*F4860*6D*+MBVC1601**-1A*+TXV | | 27,000 | $1,350 |
| No | 210609981 | AMANA | ASZV904810A* | AMVE60DP1400A* | | 27,000 | $1,350 |
| No | 210609980 | AMANA | ASZV904810A* | AMVE48DP1400A* | | 27,000 | $1,350 |
| No | 210692495 | AMANA | ASZV902410A* | CSCF3642N6D*+TXV | A*VM970804CNB* | 14,200 | $710 |
| No | 210692494 | AMANA | ASZV902410A* | CSCF3642N6D*+TXV | A*VM970803BNB* | 14,200 | $710 |
| No | 210692493 | AMANA | ASZV902410A* | CSCF3642N6D*+TXV | A*VM970603BNB* | 14,200 | $710 |
| No | 210692492 | AMANA | ASZV902410A* | CSCF3642N6D*+TXV | A*VC960804CNB* | 14,200 | $710 |
| No | 210692491 | AMANA | ASZV902410A* | CSCF3642N6D*+TXV | A*VC960803BNB* | 14,200 | $710 |
| No | 210692490 | AMANA | ASZV902410A* | CSCF3642N6D*+TXV | A*VC960603BNB* | 14,200 | $710 |
| No | 210692489 | AMANA | ASZV902410A* | CSCF3642N6D*+TXV | A*VS960603BUA* | 14,200 | $710 |
| No | 210692488 | AMANA | ASZV902410A* | CSCF3642N6D*+TXV | A*VC960403BNB* | 14,200 | $710 |
| No | 210692485 | AMANA | ASZV902410A* | CSCF3642N6D*+MBVC1201**-1A*+TXV | | 14,200 | $710 |
| No | 210692484 | AMANA | ASZV902410A* | CHPF3642C6C*+MBVC1201**-1A*+TXV | | 14,100 | $705 |
| No | 210692483 | AMANA | ASZV902410A* | CHPF3636B6C*+TXV | A*VM970803BNB* | 14,200 | $710 |
| No | 210692482 | AMANA | ASZV902410A* | CHPF3636B6C*+TXV | A*VM970603BNB* | 14,200 | $710 |
| No | 210692481 | AMANA | ASZV902410A* | CHPF3636B6C*+TXV | A*VC960803BNB* | 14,200 | $710 |
| No | 210692480 | AMANA | ASZV902410A* | CHPF3636B6C*+TXV | A*VC960603BNB* | 14,200 | $710 |
| No | 210692479 | AMANA | ASZV902410A* | CHPF3636B6C*+TXV | A*VS960603BUA* | 14,200 | $710 |
| No | 210692478 | AMANA | ASZV902410A* | CHPF3636B6C*+TXV | A*VC960403BNB* | 14,200 | $710 |
| No | 210692475 | AMANA | ASZV902410A* | CHPF3636B6C*+MBVC1201**-1A*+TXV | | 14,200 | $710 |
| No | 210692474 | AMANA | ASZV902410A* | CA*F3743*6D*+TXV | A*VM970804CNB* | 14,500 | $725 |
| No | 210692473 | AMANA | ASZV902410A* | CA*F3743*6D*+TXV | A*VM970803BNB* | 14,500 | $725 |
| No | 210692472 | AMANA | ASZV902410A* | CA*F3743*6D*+TXV | A*VM970603BNB* | 14,500 | $725 |
| No | 210692471 | AMANA | ASZV902410A* | CA*F3743*6D*+TXV | A*VC960804CNB* | 14,500 | $725 |
| No | 210692470 | AMANA | ASZV902410A* | CA*F3743*6D*+TXV | A*VC960803BNB* | 14,500 | $725 |
| No | 210692469 | AMANA | ASZV902410A* | CA*F3743*6D*+TXV | A*VC960603BNB* | 14,600 | $730 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210692468 | AMANA | ASZV902410A* | CA*F3743*6D*+TXV | A*VS960603BUA* | 14,600 | $730 |
| No | 210692467 | AMANA | ASZV902410A* | CA*F3743*6D*+TXV | A*VC960403BNB* | 14,500 | $725 |
| No | 210692464 | AMANA | ASZV902410A* | CA*F3743*6D*+MBVC1201**-1A*+TXV | | 14,500 | $725 |
| No | 210692463 | AMANA | ASZV902410A* | CA*F3137*6A*+TXV | A*VM970803BNB* | 13,800 | $690 |
| No | 210692462 | AMANA | ASZV902410A* | CA*F3137*6A*+TXV | A*VM970603BNB* | 13,800 | $690 |
| No | 210692461 | AMANA | ASZV902410A* | CA*F3137*6A*+TXV | A*VC960803BNB* | 13,800 | $690 |
| No | 210692460 | AMANA | ASZV902410A* | CA*F3137*6A*+TXV | A*VC960603BNB* | 13,800 | $690 |
| No | 210692459 | AMANA | ASZV902410A* | CA*F3137*6A*+TXV | A*VS960603BUA* | 13,800 | $690 |
| No | 210692458 | AMANA | ASZV902410A* | CA*F3137*6A*+TXV | A*VC960403BNB* | 13,800 | $690 |
| No | 210607572 | AMANA | ASZV902410A* | CA*F3137*6A*+MBVC1201**-1A*+TX | | 14,000 | $700 |
| No | 210610034 | AMANA | ASZV902410A* | AMVE24BP1400A* | | 14,800 | $740 |
| No | 206144696 | AMANA | AVZC200241A* | CA*F3743*6D*+TXV | A*VC800604B*A* | 13,000 | $650 |
| No | 202680615 | AMANA | AVZC200241A* | CA*F3743*6D*+TXV | A*VM970603BNB* | 13,000 | $650 |
| No | 206144698 | AMANA | AVZC200241A* | CA*F3743*6D*+TXV | A*VC960603BNB* | 13,000 | $650 |
| No | 202680616 | AMANA | AVZC200241A* | CA*F3743*6D*+TXV | A*VM970803BNB* | 13,000 | $650 |
| No | 206144699 | AMANA | AVZC200241A* | CA*F3743*6D*+TXV | A*VC960803BNB* | 13,000 | $650 |
| No | 206144697 | AMANA | AVZC200241A* | CA*F3743*6D*+TXV | A*VC960403BNB* | 13,000 | $650 |
| No | 206144700 | AMANA | AVZC200241A* | CA*F3743*6D*+TXV | A*VC960804CNB* | 13,000 | $650 |
| No | 205651531 | AMANA | AVZC200241A* | CHPF3636B6C*+TXV | A*VS800604BUA* | 13,000 | $650 |
| No | 202603314 | AMANA | AVZC200241A* | CA*F3743*6D*+TXV | A*VM970804CNB* | 13,000 | $650 |
| No | 206144701 | AMANA | AVZC200241A* | CHPF3636B6C*+TXV | A*VC800604B*A* | 13,000 | $650 |
| No | 205651529 | AMANA | AVZC200241A* | CA*F3743*6D*+TXV | A*VS800604BUA* | 13,000 | $650 |
| No | 205651539 | AMANA | AVZC200241A* | CA*F3743*6D*+TXV | A*VS960603BUA* | 13,000 | $650 |
| No | 206144702 | AMANA | AVZC200241A* | CHPF3636B6C*+TXV | A*VC960403BNB* | 13,000 | $650 |
| No | 206144704 | AMANA | AVZC200241A* | CHPF3636B6C*+TXV | A*VC960803BNB* | 13,000 | $650 |
| No | 206144703 | AMANA | AVZC200241A* | CHPF3636B6C*+TXV | A*VC960603BNB* | 13,000 | $650 |
| No | 202680618 | AMANA | AVZC200241A* | CHPF3636B6C*+TXV | A*VM970803BNB* | 13,000 | $650 |
| No | 202680617 | AMANA | AVZC200241A* | CHPF3636B6C*+TXV | A*VM970603BNB* | 13,000 | $650 |
| No | 205651541 | AMANA | AVZC200241A* | CHPF3636B6C*+TXV | A*VS960603BUA* | 13,000 | $650 |
| No | 206144706 | AMANA | AVZC200241A* | CSCF3642N6D*+TXV | A*VC960403BNB* | 13,000 | $650 |
| No | 206144709 | AMANA | AVZC200241A* | CSCF3642N6D*+TXV | A*VC960804CNB* | 13,000 | $650 |
| No | 206144708 | AMANA | AVZC200241A* | CSCF3642N6D*+TXV | A*VC960803BNB* | 13,000 | $650 |
| No | 206144705 | AMANA | AVZC200241A* | CSCF3642N6D*+TXV | A*VC800604B*A* | 13,000 | $650 |
| No | 206144707 | AMANA | AVZC200241A* | CSCF3642N6D*+TXV | A*VC960603BNB* | 13,000 | $650 |
| No | 206144710 | AMANA | AVZC200241A* | CSCF3642N6D*+TXV | A*VM970603BNB* | 13,000 | $650 |
| No | 206144711 | AMANA | AVZC200241A* | CSCF3642N6D*+TXV | A*VM970803BNB* | 13,000 | $650 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 9993625 | AMANA | AVZC200361A* | AVPEC59D14A* | | 18,900 | $945 |
| No | 205651533 | AMANA | AVZC200241A* | CSCF3642N6D*+TXV | A*VS800604BUA* | 13,000 | $650 |
| No | 206144837 | AMANA | AVZC200361A* | CA*F3137*6A*+TXV | A*VC800604B*A* | 18,200 | $910 |
| No | 205651543 | AMANA | AVZC200241A* | CSCF3642N6D*+TXV | A*VS960603BUA* | 13,000 | $650 |
| No | 9993624 | AMANA | AVZC200361A* | AVPEC37C14A* | | 18,900 | $945 |
| No | 206144712 | AMANA | AVZC200241A* | CSCF3642N6D*+TXV | A*VM970804CNB* | 13,000 | $650 |
| No | 202680620 | AMANA | AVZC200361A* | CA*F3137*6A*+TXV | A*VM970803BNB* | 18,200 | $910 |
| No | 206144839 | AMANA | AVZC200361A* | CA*F3137*6A*+TXV | A*VC960603BNB* | 18,200 | $910 |
| No | 205651545 | AMANA | AVZC200361A* | CA*F3137*6A*+TXV | A*VS800604BUA* | 18,200 | $910 |
| No | 206144838 | AMANA | AVZC200361A* | CA*F3137*6A*+TXV | A*VC960403BNB* | 18,200 | $910 |
| No | 202680619 | AMANA | AVZC200361A* | CA*F3137*6A*+TXV | A*VM970603BNB* | 18,200 | $910 |
| No | 206144840 | AMANA | AVZC200361A* | CA*F3137*6A*+TXV | A*VC960803BNB* | 18,200 | $910 |
| No | 206144841 | AMANA | AVZC200361A* | CA*F3642*6D*+TXV | A*VC800604B*A* | 18,200 | $910 |
| No | 205651551 | AMANA | AVZC200361A* | CA*F3137*6A*+TXV | A*VS960603BUA* | 18,200 | $910 |
| No | 206144846 | AMANA | AVZC200361A* | CA*F3642*6D*+TXV | A*VC960803BNB* | 18,000 | $900 |
| No | 206144845 | AMANA | AVZC200361A* | CA*F3642*6D*+TXV | A*VC960603BNB* | 18,000 | $900 |
| No | 206144844 | AMANA | AVZC200361A* | CA*F3642*6D*+TXV | A*VC960403BNB* | 18,000 | $900 |
| No | 206144847 | AMANA | AVZC200361A* | CA*F3642*6D*+TXV | A*VC960804CNB* | 18,200 | $910 |
| No | 206144843 | AMANA | AVZC200361A* | CA*F3642*6D*+TXV | A*VC801005C*A* | 18,000 | $900 |
| No | 206144842 | AMANA | AVZC200361A* | CA*F3642*6D*+TXV | A*VC800805C*A* | 18,000 | $900 |
| No | 205651869 | AMANA | AVZC200361A* | CA*F3642*6D*+TXV | A*VS800805CUA* | 18,000 | $900 |
| No | 202680623 | AMANA | AVZC200361A* | CA*F3642*6D*+TXV | A*VM970603BNB* | 18,000 | $900 |
| No | 202603316 | AMANA | AVZC200361A* | CA*F3642*6D*+TXV | A*VM970804CNB* | 18,200 | $910 |
| No | 206144849 | AMANA | AVZC200361A* | CA*F3642*6D*+TXV | A*VC961205DNB* | 18,000 | $900 |
| No | 202680624 | AMANA | AVZC200361A* | CA*F3642*6D*+TXV | A*VM970803BNB* | 18,000 | $900 |
| No | 206144848 | AMANA | AVZC200361A* | CA*F3642*6D*+TXV | A*VC961005CNB* | 18,000 | $900 |
| No | 202680621 | AMANA | AVZC200361A* | CA*F3642*6D*+TXV | A*VM971005CNB* | 18,000 | $900 |
| No | 205651879 | AMANA | AVZC200361A* | CA*F3642*6D*+TXV | A*VS960805CUA* | 18,000 | $900 |
| No | 205651875 | AMANA | AVZC200361A* | CA*F3642*6D*+TXV | A*VS960603BUA* | 18,000 | $900 |
| No | 205651883 | AMANA | AVZC200361A* | CA*F3642*6D*+TXV | A*VS800604BUA* | 18,200 | $910 |
| No | 202680622 | AMANA | AVZC200361A* | CA*F3642*6D*+TXV | A*VM971205DNB* | 18,000 | $900 |
| No | 206144853 | AMANA | AVZC200361A* | CA*F3743*6D*+TXV | A*VC960403BNB* | 18,200 | $910 |
| No | 206144851 | AMANA | AVZC200361A* | CA*F3743*6D*+TXV | A*VC800805C*A* | 18,200 | $910 |
| No | 206144850 | AMANA | AVZC200361A* | CA*F3743*6D*+TXV | A*VC800604B*A* | 18,000 | $900 |
| No | 206144854 | AMANA | AVZC200361A* | CA*F3743*6D*+TXV | A*VC960603BNB* | 18,200 | $910 |
| No | 206144856 | AMANA | AVZC200361A* | CA*F3743*6D*+TXV | A*VC960804CNB* | 18,000 | $900 |
| No | 206144852 | AMANA | AVZC200361A* | CA*F3743*6D*+TXV | A*VC801005C*A* | 18,200 | $910 |
| No | 202680625 | AMANA | AVZC200361A* | CA*F3743*6D*+TXV | A*VM970603BNB* | 18,200 | $910 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202680626 | AMANA | AVZC200361A* | CA*F3743*6D*+TXV | A*VM970803BNB* | 18,200 | $910 |
| No | 206144858 | AMANA | AVZC200361A* | CA*F3743*6D*+TXV | A*VC961205DNB* | 18,200 | $910 |
| No | 206144857 | AMANA | AVZC200361A* | CA*F3743*6D*+TXV | A*VC961005CNB* | 18,200 | $910 |
| No | 206144855 | AMANA | AVZC200361A* | CA*F3743*6D*+TXV | A*VC960803BNB* | 18,200 | $910 |
| No | 206144859 | AMANA | AVZC200361A* | CHPF3642C6C*+TXV | A*VC800604B*A* | 18,000 | $900 |
| No | 202680627 | AMANA | AVZC200361A* | CA*F3743*6D*+TXV | A*VM971005CNB* | 18,200 | $910 |
| No | 202603317 | AMANA | AVZC200361A* | CA*F3743*6D*+TXV | A*VM970804CNB* | 18,000 | $900 |
| No | 202680628 | AMANA | AVZC200361A* | CA*F3743*6D*+TXV | A*VM971205DNB* | 18,200 | $910 |
| No | 205651547 | AMANA | AVZC200361A* | CA*F3743*6D*+TXV | A*VS800604BUA* | 18,000 | $900 |
| No | 205651871 | AMANA | AVZC200361A* | CA*F3743*6D*+TXV | A*VS800805CUA* | 18,200 | $910 |
| No | 205651553 | AMANA | AVZC200361A* | CA*F3743*6D*+TXV | A*VS960603BUA* | 18,200 | $910 |
| No | 206144860 | AMANA | AVZC200361A* | CHPF3642C6C*+TXV | A*VC800805C*A* | 18,000 | $900 |
| No | 205651559 | AMANA | AVZC200361A* | CA*F3743*6D*+TXV | A*VS960805CUA* | 18,200 | $910 |
| No | 206144862 | AMANA | AVZC200361A* | CHPF3642C6C*+TXV | A*VC960403BNB* | 18,000 | $900 |
| No | 206144861 | AMANA | AVZC200361A* | CHPF3642C6C*+TXV | A*VC801005C*A* | 18,000 | $900 |
| No | 206144863 | AMANA | AVZC200361A* | CHPF3642C6C*+TXV | A*VC960603BNB* | 18,000 | $900 |
| No | 206144866 | AMANA | AVZC200361A* | CHPF3642C6C*+TXV | A*VC961005CNB* | 18,000 | $900 |
| No | 202680631 | AMANA | AVZC200361A* | CHPF3642C6C*+TXV | A*VM970603BNB* | 18,000 | $900 |
| No | 206144865 | AMANA | AVZC200361A* | CHPF3642C6C*+TXV | A*VC960804CNB* | 18,000 | $900 |
| No | 202680630 | AMANA | AVZC200361A* | CHPF3642C6C*+TXV | A*VM970803BNB* | 18,000 | $900 |
| No | 206144864 | AMANA | AVZC200361A* | CHPF3642C6C*+TXV | A*VC960803BNB* | 18,000 | $900 |
| No | 202603318 | AMANA | AVZC200361A* | CHPF3642C6C*+TXV | A*VM970804CNB* | 18,000 | $900 |
| No | 202680629 | AMANA | AVZC200361A* | CHPF3642C6C*+TXV | A*VM971005CNB* | 18,000 | $900 |
| No | 205651561 | AMANA | AVZC200361A* | CHPF3642C6C*+TXV | A*VS960805CUA* | 18,000 | $900 |
| No | 205651549 | AMANA | AVZC200361A* | CHPF3642C6C*+TXV | A*VS800805CUA* | 18,000 | $900 |
| No | 205651563 | AMANA | AVZC200361A* | CHPF3642C6C*+TXV | A*VS800604BUA* | 18,000 | $900 |
| No | 202680633 | AMANA | AVZC200361A* | CHPF3743C6B*+TXV | A*VM970803BNB* | 18,200 | $910 |
| No | 206144867 | AMANA | AVZC200361A* | CHPF3743C6B*+TXV | A*VC800604B*A* | 18,200 | $910 |
| No | 205651555 | AMANA | AVZC200361A* | CHPF3642C6C*+TXV | A*VS960603BUA* | 18,000 | $900 |
| No | 206144868 | AMANA | AVZC200361A* | CHPF3743C6B*+TXV | A*VC800805C*A* | 18,200 | $910 |
| No | 206144870 | AMANA | AVZC200361A* | CHPF3743C6B*+TXV | A*VC960403BNB* | 18,200 | $910 |
| No | 206144869 | AMANA | AVZC200361A* | CHPF3743C6B*+TXV | A*VC801005C*A* | 18,200 | $910 |
| No | 206144871 | AMANA | AVZC200361A* | CHPF3743C6B*+TXV | A*VC960603BNB* | 18,200 | $910 |
| No | 206144872 | AMANA | AVZC200361A* | CHPF3743C6B*+TXV | A*VC960803BNB* | 18,200 | $910 |
| No | 206144873 | AMANA | AVZC200361A* | CHPF3743C6B*+TXV | A*VC960804CNB* | 18,200 | $910 |
| No | 206144874 | AMANA | AVZC200361A* | CHPF3743C6B*+TXV | A*VC961005CNB* | 18,200 | $910 |
| No | 202680632 | AMANA | AVZC200361A* | CHPF3743C6B*+TXV | A*VM970603BNB* | 18,200 | $910 |
| No | 202680634 | AMANA | AVZC200361A* | CHPF3743C6B*+TXV | A*VM971005CNB* | 18,200 | $910 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202603319 | AMANA | AVZC200361A* | CHPF3743C6B*+TXV | A*VM970804CNB* | 18,200 | $910 |
| No | 205651565 | AMANA | AVZC200361A* | CHPF3743C6B*+TXV | A*VS800604BUA* | 18,200 | $910 |
| No | 205651567 | AMANA | AVZC200361A* | CHPF3743C6B*+TXV | A*VS800805CUA* | 18,200 | $910 |
| No | 206144877 | AMANA | AVZC200361A* | CSCF3642N6D*+TXV | A*VC801005C*A* | 18,200 | $910 |
| No | 206144875 | AMANA | AVZC200361A* | CSCF3642N6D*+TXV | A*VC800604B*A* | 18,200 | $910 |
| No | 205651569 | AMANA | AVZC200361A* | CHPF3743C6B*+TXV | A*VS960805CUA* | 18,200 | $910 |
| No | 205651557 | AMANA | AVZC200361A* | CHPF3743C6B*+TXV | A*VS960603BUA* | 18,200 | $910 |
| No | 206144876 | AMANA | AVZC200361A* | CSCF3642N6D*+TXV | A*VC800805C*A* | 18,200 | $910 |
| No | 206144879 | AMANA | AVZC200361A* | CSCF3642N6D*+TXV | A*VC960603BNB* | 18,200 | $910 |
| No | 206144881 | AMANA | AVZC200361A* | CSCF3642N6D*+TXV | A*VC960804CNB* | 18,200 | $910 |
| No | 206144880 | AMANA | AVZC200361A* | CSCF3642N6D*+TXV | A*VC960803BNB* | 18,200 | $910 |
| No | 206144878 | AMANA | AVZC200361A* | CSCF3642N6D*+TXV | A*VC960403BNB* | 18,200 | $910 |
| No | 206144882 | AMANA | AVZC200361A* | CSCF3642N6D*+TXV | A*VC961005CNB* | 18,200 | $910 |
| No | 206144883 | AMANA | AVZC200361A* | CSCF3642N6D*+TXV | A*VC961205DNB* | 18,200 | $910 |
| No | 202680635 | AMANA | AVZC200361A* | CSCF3642N6D*+TXV | A*VM971205DNB* | 18,200 | $910 |
| No | 202603320 | AMANA | AVZC200361A* | CSCF3642N6D*+TXV | A*VM970804CNB* | 18,200 | $910 |
| No | 202680638 | AMANA | AVZC200361A* | CSCF3642N6D*+TXV | A*VM970603BNB* | 18,200 | $910 |
| No | 202680636 | AMANA | AVZC200361A* | CSCF3642N6D*+TXV | A*VM971005CNB* | 18,200 | $910 |
| No | 202680637 | AMANA | AVZC200361A* | CSCF3642N6D*+TXV | A*VM970803BNB* | 18,200 | $910 |
| No | 205651885 | AMANA | AVZC200361A* | CSCF3642N6D*+TXV | A*VS800604BUA* | 18,200 | $910 |
| No | 205651873 | AMANA | AVZC200361A* | CSCF3642N6D*+TXV | A*VS800805CUA* | 18,200 | $910 |
| No | 205651877 | AMANA | AVZC200361A* | CSCF3642N6D*+TXV | A*VS960603BUA* | 18,200 | $910 |
| No | 202327352 | AMANA | AVZC200481A* | AVPEC59D14A* | | 27,000 | $1,350 |
| No | 206145125 | AMANA | AVZC200481A* | CA*F4860*6D*+TXV | A*VC800604B*A* | 27,400 | $1,370 |
| No | 205651881 | AMANA | AVZC200361A* | CSCF3642N6D*+TXV | A*VS960805CUA* | 18,200 | $910 |
| No | 206145126 | AMANA | AVZC200481A* | CA*F4860*6D*+TXV | A*VC800805C*A* | 27,400 | $1,370 |
| No | 206145127 | AMANA | AVZC200481A* | CA*F4860*6D*+TXV | A*VC801005C*A* | 27,400 | $1,370 |
| No | 206145128 | AMANA | AVZC200481A* | CA*F4860*6D*+TXV | A*VC960804CNB* | 27,400 | $1,370 |
| No | 206145131 | AMANA | AVZC200481A* | CA*F4961*6D*+TXV | A*VC800604B*A* | 28,000 | $1,400 |
| No | 206145129 | AMANA | AVZC200481A* | CA*F4860*6D*+TXV | A*VC961005CNB* | 27,400 | $1,370 |
| No | 206145132 | AMANA | AVZC200481A* | CA*F4961*6D*+TXV | A*VC800805C*A* | 27,600 | $1,380 |
| No | 202680640 | AMANA | AVZC200481A* | CA*F4860*6D*+TXV | A*VM971205DNB* | 27,400 | $1,370 |
| No | 202680639 | AMANA | AVZC200481A* | CA*F4860*6D*+TXV | A*VM971005CNB* | 27,400 | $1,370 |
| No | 206145130 | AMANA | AVZC200481A* | CA*F4860*6D*+TXV | A*VC961205DNB* | 27,400 | $1,370 |
| No | 202603321 | AMANA | AVZC200481A* | CA*F4860*6D*+TXV | A*VM970804CNB* | 27,400 | $1,370 |
| No | 205651575 | AMANA | AVZC200481A* | CA*F4860*6D*+TXV | A*VS800805CUA* | 27,400 | $1,370 |
| No | 205651583 | AMANA | AVZC200481A* | CA*F4860*6D*+TXV | A*VS960805CUA* | 27,400 | $1,370 |
| No | 206145133 | AMANA | AVZC200481A* | CA*F4961*6D*+TXV | A*VC801005C*A* | 27,800 | $1,390 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206145134 | AMANA | AVZC200481A* | CA*F4961*6D*+TXV | A*VC960804CNB* | 27,600 | $1,380 |
| No | 206145135 | AMANA | AVZC200481A* | CA*F4961*6D*+TXV | A*VC961005CNB* | 27,800 | $1,390 |
| No | 202603322 | AMANA | AVZC200481A* | CA*F4961*6D*+TXV | A*VM970804CNB* | 27,800 | $1,390 |
| No | 202680642 | AMANA | AVZC200481A* | CA*F4961*6D*+TXV | A*VM971205DNB* | 27,800 | $1,390 |
| No | 205651571 | AMANA | AVZC200481A* | CA*F4961*6D*+TXV | A*VS800604BUA* | 28,000 | $1,400 |
| No | 206145136 | AMANA | AVZC200481A* | CA*F4961*6D*+TXV | A*VC961205DNB* | 27,800 | $1,390 |
| No | 202680641 | AMANA | AVZC200481A* | CA*F4961*6D*+TXV | A*VM971005CNB* | 27,800 | $1,390 |
| No | 206145137 | AMANA | AVZC200481A* | CHPF4860D6D*+TXV | A*VC800805C*A* | 27,600 | $1,380 |
| No | 205651585 | AMANA | AVZC200481A* | CA*F4961*6D*+TXV | A*VS960805CUA* | 27,600 | $1,380 |
| No | 205651577 | AMANA | AVZC200481A* | CA*F4961*6D*+TXV | A*VS800805CUA* | 27,200 | $1,360 |
| No | 206145139 | AMANA | AVZC200481A* | CHPF4860D6D*+TXV | A*VC960804CNB* | 27,800 | $1,390 |
| No | 206145140 | AMANA | AVZC200481A* | CHPF4860D6D*+TXV | A*VC961005CNB* | 27,800 | $1,390 |
| No | 206145138 | AMANA | AVZC200481A* | CHPF4860D6D*+TXV | A*VC801005C*A* | 27,600 | $1,380 |
| No | 206145141 | AMANA | AVZC200481A* | CHPF4860D6D*+TXV | A*VC961205DNB* | 27,800 | $1,390 |
| No | 202680643 | AMANA | AVZC200481A* | CHPF4860D6D*+TXV | A*VM971005CNB* | 27,800 | $1,390 |
| No | 202603323 | AMANA | AVZC200481A* | CHPF4860D6D*+TXV | A*VM970804CNB* | 28,000 | $1,400 |
| No | 205651579 | AMANA | AVZC200481A* | CHPF4860D6D*+TXV | A*VS800805CUA* | 27,200 | $1,360 |
| No | 206145142 | AMANA | AVZC200481A* | CSCF4860N6D*+TXV | A*VC800604B*A* | 27,400 | $1,370 |
| No | 202680644 | AMANA | AVZC200481A* | CHPF4860D6D*+TXV | A*VM971205DNB* | 27,800 | $1,390 |
| No | 206145145 | AMANA | AVZC200481A* | CSCF4860N6D*+TXV | A*VC960804CNB* | 27,400 | $1,370 |
| No | 205651587 | AMANA | AVZC200481A* | CSCF4860N6D*+TXV | A*VS960805CUA* | 27,400 | $1,370 |
| No | 206145144 | AMANA | AVZC200481A* | CSCF4860N6D*+TXV | A*VC801005C*A* | 27,400 | $1,370 |
| No | 206145147 | AMANA | AVZC200481A* | CSCF4860N6D*+TXV | A*VC961205DNB* | 27,400 | $1,370 |
| No | 206145143 | AMANA | AVZC200481A* | CSCF4860N6D*+TXV | A*VC800805C*A* | 27,400 | $1,370 |
| No | 206145146 | AMANA | AVZC200481A* | CSCF4860N6D*+TXV | A*VC961005CNB* | 27,400 | $1,370 |
| No | 202603324 | AMANA | AVZC200481A* | CSCF4860N6D*+TXV | A*VM970804CNB* | 27,400 | $1,370 |
| No | 205651581 | AMANA | AVZC200481A* | CSCF4860N6D*+TXV | A*VS800805CUA* | 27,400 | $1,370 |
| No | 202680645 | AMANA | AVZC200481A* | CSCF4860N6D*+TXV | A*VM971005CNB* | 27,400 | $1,370 |
| No | 202680646 | AMANA | AVZC200481A* | CSCF4860N6D*+TXV | A*VM971205DNB* | 27,400 | $1,370 |
| No | 205651573 | AMANA | AVZC200481A* | CSCF4860N6D*+TXV | A*VS800604BUA* | 27,400 | $1,370 |
| No | 205976135 | AMANA | AVZC200601B* | CA*F4961*6D*+MBVC2000**-1A*+TXV | | 32,000 | $1,600 |
| No | 205976141 | AMANA | AVZC200601B* | CA*F4961*6D*+TXV | A*VC800805C*A* | 32,000 | $1,600 |
| No | 205976166 | AMANA | AVZC200601B* | AVPEC61D14A* | | 32,600 | $1,630 |
| No | 205976167 | AMANA | AVZC200601B* | CA*F4961*6D*+MBVC2001**-1A*+TXV | | 32,000 | $1,600 |
| No | 205976142 | AMANA | AVZC200601B* | CA*F4961*6D*+TXV | A*VC801005C*A* | 32,000 | $1,600 |
| No | 205976143 | AMANA | AVZC200601B* | CA*F4961*6D*+TXV | A*VC961005CNB* | 32,000 | $1,600 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205976144 | AMANA | AVZC200601B* | CA*F4961*6D*+TXV | A*VC961205DNB* | 32,000 | $1,600 |
| No | 205976145 | AMANA | AVZC200601B* | CA*F4961*6D*+TXV | A*VM971005CNB* | 32,000 | $1,600 |
| No | 205976147 | AMANA | AVZC200601B* | CA*F4961*6D*+TXV | A*VS800805CUA* | 32,000 | $1,600 |
| No | 205976146 | AMANA | AVZC200601B* | CA*F4961*6D*+TXV | A*VM971205DNB* | 32,000 | $1,600 |
| No | 205976148 | AMANA | AVZC200601B* | CA*F4961*6D*+TXV | A*VS960805CUA* | 32,000 | $1,600 |
| No | 205976155 | AMANA | AVZC200601B* | CHPF4860D6D*+MBVC2000**-1A*+TXV | | 32,000 | $1,600 |
| No | 205976149 | AMANA | AVZC200601B* | CHPF4860D6D*+TXV | A*VC800805C*A* | 32,000 | $1,600 |
| No | 205976150 | AMANA | AVZC200601B* | CHPF4860D6D*+TXV | A*VC801005C*A* | 32,000 | $1,600 |
| No | 205976152 | AMANA | AVZC200601B* | CHPF4860D6D*+TXV | A*VC961205DNB* | 32,000 | $1,600 |
| No | 205976151 | AMANA | AVZC200601B* | CHPF4860D6D*+TXV | A*VC961005CNB* | 32,000 | $1,600 |
| No | 205976153 | AMANA | AVZC200601B* | CHPF4860D6D*+TXV | A*VM971005CNB* | 32,000 | $1,600 |
| No | 205976168 | AMANA | AVZC200601B* | CHPF4860D6D*+MBVC2001**-1A*+TXV | | 32,000 | $1,600 |
| No | 205976161 | AMANA | AVZC200601B* | CSCF4860N6D*+TXV | A*VC961205DNB* | 32,000 | $1,600 |
| No | 205976154 | AMANA | AVZC200601B* | CHPF4860D6D*+TXV | A*VM971205DNB* | 32,000 | $1,600 |
| No | 205976159 | AMANA | AVZC200601B* | CSCF4860N6D*+TXV | A*VC801005C*A* | 32,000 | $1,600 |
| No | 205976158 | AMANA | AVZC200601B* | CSCF4860N6D*+TXV | A*VC800805C*A* | 32,000 | $1,600 |
| No | 205976156 | AMANA | AVZC200601B* | CHPF4860D6D*+TXV | A*VS800805CUA* | 32,000 | $1,600 |
| No | 205976157 | AMANA | AVZC200601B* | CHPF4860D6D*+TXV | A*VS960805CUA* | 32,000 | $1,600 |
| No | 205976160 | AMANA | AVZC200601B* | CSCF4860N6D*+TXV | A*VC961005CNB* | 32,000 | $1,600 |
| No | 8657940 | AMANA | AVZC200241A* | CA*F3137*6A*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205976164 | AMANA | AVZC200601B* | CSCF4860N6D*+TXV | A*VS800805CUA* | 32,000 | $1,600 |
| No | 205976162 | AMANA | AVZC200601B* | CSCF4860N6D*+TXV | A*VM971005CNB* | 32,000 | $1,600 |
| No | 205976163 | AMANA | AVZC200601B* | CSCF4860N6D*+TXV | A*VM971205DNB* | 32,000 | $1,600 |
| No | 205976165 | AMANA | AVZC200601B* | CSCF4860N6D*+TXV | A*VS960805CUA* | 32,000 | $1,600 |
| No | 8669093 | AMANA | AVZC200241A* | CA*F3636*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 8669585 | AMANA | AVZC200361A* | CHPF3642C6C*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 8669274 | AMANA | AVZC200241A* | CA*F3743*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 8669302 | AMANA | AVZC200361A* | CA*F3137*6A*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 8669301 | AMANA | AVZC200361A* | CA*F3137*6A*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 8669283 | AMANA | AVZC200241A* | CHPF3636B6C*+MBVC1200**-1A*+TXV | | 13,000 | $650 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 8669641 | AMANA | AVZC200481A* | CA*F4860*6D*+MBVC1600**-1A*+TXV | | 33,400 | $1,670 |
| No | 8669309 | AMANA | AVZC200361A* | CA*F3642*6D*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 8669310 | AMANA | AVZC200361A* | CA*F3642*6D*+MBVC1600**-1A*+TXV | | 18,000 | $900 |
| No | 8669654 | AMANA | AVZC200481A* | CA*F4961*6D*+MBVC1600**-1A*+TXV | | 34,000 | $1,700 |
| No | 8669331 | AMANA | AVZC200361A* | CA*F3743*6D*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 8669586 | AMANA | AVZC200361A* | CHPF3642C6C*+MBVC1600**-1A*+TXV | | 18,000 | $900 |
| No | 202132779 | AMANA | AVZC200241A* | CHPF3642C6C*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 8669601 | AMANA | AVZC200361A* | CHPF3743C6B*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 10324705 | AMANA | AVZC200361A* | CA*F3743*6D*+MBVC1600**-1A*+TX | | 18,200 | $910 |
| No | 206144682 | AMANA | AVZC200241A* | CA*F3137*6A*+TXV | A*VC800604B*A* | 13,000 | $650 |
| No | 9993623 | AMANA | AVZC200241A* | AVPEC25B14A* | | 13,600 | $680 |
| No | 206144684 | AMANA | AVZC200241A* | CA*F3137*6A*+TXV | A*VC960603BNB* | 13,000 | $650 |
| No | 206144685 | AMANA | AVZC200241A* | CA*F3137*6A*+TXV | A*VC960803BNB* | 13,000 | $650 |
| No | 206144683 | AMANA | AVZC200241A* | CA*F3137*6A*+TXV | A*VC960403BNB* | 13,000 | $650 |
| No | 202680609 | AMANA | AVZC200241A* | CA*F3137*6A*+TXV | A*VM970603BNB* | 13,000 | $650 |
| No | 202680610 | AMANA | AVZC200241A* | CA*F3137*6A*+TXV | A*VM970803BNB* | 13,000 | $650 |
| No | 205651535 | AMANA | AVZC200241A* | CA*F3137*6A*+TXV | A*VS960603BUA* | 13,000 | $650 |
| No | 205651525 | AMANA | AVZC200241A* | CA*F3137*6A*+TXV | A*VS800604BUA* | 13,000 | $650 |
| No | 206144690 | AMANA | AVZC200241A* | CA*F3636*6D*+TXV | A*VC960804CNB* | 13,000 | $650 |
| No | 206144689 | AMANA | AVZC200241A* | CA*F3636*6D*+TXV | A*VC960803BNB* | 13,000 | $650 |
| No | 206144687 | AMANA | AVZC200241A* | CA*F3636*6D*+TXV | A*VC960403BNB* | 13,000 | $650 |
| No | 206144686 | AMANA | AVZC200241A* | CA*F3636*6D*+TXV | A*VC800604B*A* | 13,000 | $650 |
| No | 206144688 | AMANA | AVZC200241A* | CA*F3636*6D*+TXV | A*VC960603BNB* | 13,000 | $650 |
| No | 202680611 | AMANA | AVZC200241A* | CA*F3636*6D*+TXV | A*VM970603BNB* | 13,000 | $650 |
| No | 202603312 | AMANA | AVZC200241A* | CA*F3636*6D*+TXV | A*VM970804CNB* | 13,000 | $650 |
| No | 205651537 | AMANA | AVZC200241A* | CA*F3636*6D*+TXV | A*VS960603BUA* | 13,000 | $650 |
| No | 205651527 | AMANA | AVZC200241A* | CA*F3636*6D*+TXV | A*VS800604BUA* | 13,000 | $650 |
| No | 202680612 | AMANA | AVZC200241A* | CA*F3636*6D*+TXV | A*VM970803BNB* | 13,000 | $650 |
| No | 206144691 | AMANA | AVZC200241A* | CA*F3642*6D*+TXV | A*VC800604B*A* | 13,000 | $650 |
| No | 206144692 | AMANA | AVZC200241A* | CA*F3642*6D*+TXV | A*VC960403BNB* | 13,000 | $650 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202680613 | AMANA | AVZC200241A* | CA*F3642*6D*+TXV | A*VM970603BNB* | 13,000 | $650 |
| No | 206144693 | AMANA | AVZC200241A* | CA*F3642*6D*+TXV | A*VC960603BNB* | 13,000 | $650 |
| No | 202680614 | AMANA | AVZC200241A* | CA*F3642*6D*+TXV | A*VM970803BNB* | 13,000 | $650 |
| No | 206144695 | AMANA | AVZC200241A* | CA*F3642*6D*+TXV | A*VC960804CNB* | 13,000 | $650 |
| No | 202603313 | AMANA | AVZC200241A* | CA*F3642*6D*+TXV | A*VM970804CNB* | 13,000 | $650 |
| No | 206144694 | AMANA | AVZC200241A* | CA*F3642*6D*+TXV | A*VC960803BNB* | 13,000 | $650 |
| No | 8669618 | AMANA | AVZC200361A* | CSCF3642N6D*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 8669602 | AMANA | AVZC200361A* | CHPF3743C6B*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 8669617 | AMANA | AVZC200361A* | CSCF3642N6D*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 8669686 | AMANA | AVZC200481A* | CHPF4860D6D*+MBVC1600**-1A*+TXV | | 34,000 | $1,700 |
| No | 8669931 | AMANA | AVZC200481A* | CSCF4860N6D*+MBVC1600**-1A*+TXV | | 33,400 | $1,670 |
| No | 8669642 | AMANA | AVZC200481A* | CA*F4860*6D*+MBVC2000**-1A*+TXV | | 33,400 | $1,670 |
| No | 8669687 | AMANA | AVZC200481A* | CHPF4860D6D*+MBVC2000**-1A*+TXV | | 34,000 | $1,700 |
| No | 205358207 | AMANA | AVZC200361A* | CHPF3642C6C*+MBVC1601**-1A*+TXV | | 18,000 | $900 |
| No | 8670115 | AMANA | AVZC200481A* | CSCF4860N6D*+MBVC2000**-1A*+TXV | | 33,400 | $1,670 |
| No | 9993626 | AMANA | AVZC200481A* | AVPEC61D14A* | | 28,600 | $1,430 |
| No | 205358193 | AMANA | AVZC200241A* | CA*F3137*6A*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205358194 | AMANA | AVZC200241A* | CA*F3636*6D*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205358195 | AMANA | AVZC200241A* | CA*F3743*6D*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205358197 | AMANA | AVZC200241A* | CA*F3642*6D*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205358199 | AMANA | AVZC200361A* | CA*F3137*6A*+MBVC1201**-1A*+TXV | | 18,000 | $900 |
| No | 205358198 | AMANA | AVZC200241A* | CHPF3642C6C*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205358196 | AMANA | AVZC200241A* | CHPF3636B6C*+MBVC1201**-1A*+TXV | | 13,000 | $650 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205358200 | AMANA | AVZC200361A* | CA*F3642*6D*+MBVC1201**-1A*+TXV | | 18,000 | $900 |
| No | 205358202 | AMANA | AVZC200361A* | CHPF3642C6C*+MBVC1201**-1A*+TXV | | 18,000 | $900 |
| No | 205358204 | AMANA | AVZC200361A* | CSCF3642N6D*+MBVC1201**-1A*+TXV | | 18,200 | $910 |
| No | 205358201 | AMANA | AVZC200361A* | CA*F3743*6D*+MBVC1201**-1A*+TXV | | 18,200 | $910 |
| No | 205358203 | AMANA | AVZC200361A* | CHPF3743C6B*+MBVC1201**-1A*+TXV | | 18,200 | $910 |
| No | 205358205 | AMANA | AVZC200361A* | CA*F3137*6A*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205358211 | AMANA | AVZC200481A* | CA*F4860*6D*+MBVC1601**-1A*+TXV | | 26,600 | $1,330 |
| No | 205358206 | AMANA | AVZC200361A* | CA*F3642*6D*+MBVC1601**-1A*+TXV | | 18,000 | $900 |
| No | 205358208 | AMANA | AVZC200361A* | CHPF3743C6B*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205358209 | AMANA | AVZC200361A* | CSCF3642N6D*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205358210 | AMANA | AVZC200361A* | CA*F3743*6D*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205358216 | AMANA | AVZC200481A* | CHPF4860D6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205358213 | AMANA | AVZC200481A* | CHPF4860D6D*+MBVC1601**-1A*+TXV | | 26,600 | $1,330 |
| No | 205358215 | AMANA | AVZC200481A* | CA*F4860*6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205358217 | AMANA | AVZC200481A* | CSCF4860N6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205358212 | AMANA | AVZC200481A* | CA*F4961*6D*+MBVC1601**-1A*+TXV | | 26,800 | $1,340 |
| No | 205358214 | AMANA | AVZC200481A* | CSCF4860N6D*+MBVC1601**-1A*+TXV | | 26,600 | $1,330 |
| No | 205358218 | AMANA | AVZC200481A* | CA*F4961*6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 10324707 | AMANA | AVZC200601A* | CA*F4961*6D*+MBVC2000**-1A*+TX | | 34,000 | $1,700 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10324704 | AMANA | AVZC200241A* | CA*F3642*6D*+MBVC1200**-1A*+TX | | 15,200 | $760 |
| No | 10324706 | AMANA | AVZC200481A* | CA*F4961*6D*+MBVC2000**-1A*+TX | | 34,000 | $1,700 |
| No | 205965779 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3642*6D*+TXV | G*VS960603BUA* | 18,000 | $900 |
| No | 205965778 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3642*6D*+TXV | G*VS800805CUA* | 18,000 | $900 |
| No | 205965780 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3642*6D*+TXV | G*VS960805CUA* | 18,000 | $900 |
| No | 205965783 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3743*6D*+TXV | G*VM971205DNB* | 18,200 | $910 |
| No | 205965781 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3743*6D*+TXV | G*VM970603BNB* | 18,200 | $910 |
| No | 205965782 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3743*6D*+TXV | G*VM970803BNB* | 18,200 | $910 |
| No | 205965784 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3743*6D*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 205965785 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3743*6D*+TXV | G*VS800604BUA* | 18,000 | $900 |
| No | 205965787 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3743*6D*+TXV | G*VS960603BUA* | 18,200 | $910 |
| No | 205965786 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3743*6D*+TXV | G*VS800805CUA* | 18,200 | $910 |
| No | 205965789 | AMANA DISTINCTIONS | GVZC200361A* | CHPF3642C6C*+TXV | G*VM970603BNB* | 18,000 | $900 |
| No | 205965788 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3743*6D*+TXV | G*VS960805CUA* | 18,200 | $910 |
| No | 205965790 | AMANA DISTINCTIONS | GVZC200361A* | CHPF3642C6C*+TXV | G*VM970803BNB* | 18,000 | $900 |
| No | 205965791 | AMANA DISTINCTIONS | GVZC200361A* | CHPF3642C6C*+TXV | G*VM970804CNB* | 18,000 | $900 |
| No | 205965798 | AMANA DISTINCTIONS | GVZC200361A* | CHPF3642C6C*+TXV | G*VS960805CUA* | 18,000 | $900 |
| No | 205965792 | AMANA DISTINCTIONS | GVZC200361A* | CHPF3642C6C*+TXV | G*VM971005CNB* | 18,000 | $900 |
| No | 205965803 | AMANA DISTINCTIONS | GVZC200361A* | CHPF3743C6B*+MBVC1200**-1A*+TXV | | 18,200 | $910 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205965794 | AMANA DISTINCTIONS | GVZC200361A* | CHPF3642C6C*+MBVC1600**-1A*+TXV | | 18,000 | $900 |
| No | 205965795 | AMANA DISTINCTIONS | GVZC200361A* | CHPF3642C6C*+TXV | G*VS800604BUA* | 18,000 | $900 |
| No | 205965793 | AMANA DISTINCTIONS | GVZC200361A* | CHPF3642C6C*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 205965796 | AMANA DISTINCTIONS | GVZC200361A* | CHPF3642C6C*+TXV | G*VS800805CUA* | 18,000 | $900 |
| No | 205965797 | AMANA DISTINCTIONS | GVZC200361A* | CHPF3642C6C*+TXV | G*VS960603BUA* | 18,000 | $900 |
| No | 205965800 | AMANA DISTINCTIONS | GVZC200361A* | CHPF3743C6B*+TXV | G*VM970803BNB* | 18,200 | $910 |
| No | 205965799 | AMANA DISTINCTIONS | GVZC200361A* | CHPF3743C6B*+TXV | G*VM970603BNB* | 18,200 | $910 |
| No | 205965815 | AMANA DISTINCTIONS | GVZC200361A* | CSCF3642N6D*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 205965801 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3743*6D*+TXV | G*VM970804CNB* | 18,000 | $900 |
| No | 205965802 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3743*6D*+TXV | G*VM971005CNB* | 18,200 | $910 |
| No | 205965811 | AMANA DISTINCTIONS | GVZC200361A* | CSCF3642N6D*+TXV | G*VM970804CNB* | 18,200 | $910 |
| No | 205965804 | AMANA DISTINCTIONS | GVZC200361A* | CHPF3743C6B*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 205965805 | AMANA DISTINCTIONS | GVZC200361A* | CHPF3743C6B*+TXV | G*VS800604BUA* | 18,200 | $910 |
| No | 205965806 | AMANA DISTINCTIONS | GVZC200361A* | CHPF3743C6B*+TXV | G*VS800805CUA* | 18,200 | $910 |
| No | 205965808 | AMANA DISTINCTIONS | GVZC200361A* | CHPF3743C6B*+TXV | G*VS960805CUA* | 18,200 | $910 |
| No | 205965807 | AMANA DISTINCTIONS | GVZC200361A* | CHPF3743C6B*+TXV | G*VS960603BUA* | 18,200 | $910 |
| No | 205965810 | AMANA DISTINCTIONS | GVZC200361A* | CSCF3642N6D*+TXV | G*VM970803BNB* | 18,200 | $910 |
| No | 205965809 | AMANA DISTINCTIONS | GVZC200361A* | CSCF3642N6D*+TXV | G*VM970603BNB* | 18,200 | $910 |
| No | 205965812 | AMANA DISTINCTIONS | GVZC200361A* | CSCF3642N6D*+TXV | G*VM971005CNB* | 18,200 | $910 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205965813 | AMANA DISTINCTIONS | GVZC200361A* | CSCF3642N6D*+TXV | G*VM971205DNB* | 18,200 | $910 |
| No | 205965814 | AMANA DISTINCTIONS | GVZC200361A* | CSCF3642N6D*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 205965818 | AMANA DISTINCTIONS | GVZC200361A* | CSCF3642N6D*+TXV | G*VS960603BUA* | 18,200 | $910 |
| No | 205965817 | AMANA DISTINCTIONS | GVZC200361A* | CSCF3642N6D*+TXV | G*VS800805CUA* | 18,200 | $910 |
| No | 205965819 | AMANA DISTINCTIONS | GVZC200361A* | CSCF3642N6D*+TXV | G*VS960805CUA* | 18,200 | $910 |
| No | 205965816 | AMANA DISTINCTIONS | GVZC200361A* | CSCF3642N6D*+TXV | G*VS800604BUA* | 18,200 | $910 |
| No | 205965828 | AMANA DISTINCTIONS | GVZC200361A* | CHPF3642C6C*+MBVC1201**-1A*+TXV | | 18,000 | $900 |
| No | 205965835 | AMANA DISTINCTIONS | GVZC200481A* | CA*F4860*6D*+TXV | G*VM971005CNB* | 27,400 | $1,370 |
| No | 205965820 | AMANA DISTINCTIONS | GVZC200361A* | AVPEC37C14A* | | 18,900 | $945 |
| No | 205965821 | AMANA DISTINCTIONS | GVZC200361A* | AVPEC59D14A* | | 18,900 | $945 |
| No | 205965824 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3642*6D*+MBVC1201**-1A*+TXV | | 18,000 | $900 |
| No | 205965822 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3137*6A*+MBVC1201**-1A*+TXV | | 18,000 | $900 |
| No | 205965823 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3137*6A*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205965825 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3642*6D*+MBVC1601**-1A*+TXV | | 18,000 | $900 |
| No | 205965737 | AMANA DISTINCTIONS | GVZC200241A* | CA*F3636*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205965726 | AMANA DISTINCTIONS | GVZC200241A* | CA*F3642*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205965728 | AMANA DISTINCTIONS | GVZC200481A* | CA*F4961*6D*+MBVC2000**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965727 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3743*6D*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 205965729 | AMANA DISTINCTIONS | GVZC200241A* | CA*F3137*6A*+TXV | G*VM970603BNB* | 13,000 | $650 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205965730 | AMANA DISTINCTIONS | GVZC200241A* | CA*F3137*6A*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205965731 | AMANA DISTINCTIONS | GVZC200241A* | CA*F3137*6A*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205965732 | AMANA DISTINCTIONS | GVZC200241A* | CA*F3137*6A*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205965734 | AMANA DISTINCTIONS | GVZC200241A* | CA*F3636*6D*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205965733 | AMANA DISTINCTIONS | GVZC200241A* | CA*F3137*6A*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205965736 | AMANA DISTINCTIONS | GVZC200241A* | CA*F3636*6D*+TXV | G*VM970804CNB* | 13,000 | $650 |
| No | 205965735 | AMANA DISTINCTIONS | GVZC200241A* | CA*F3636*6D*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205965738 | AMANA DISTINCTIONS | GVZC200241A* | CA*F3636*6D*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205965739 | AMANA DISTINCTIONS | GVZC200241A* | CA*F3636*6D*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205965740 | AMANA DISTINCTIONS | GVZC200241A* | CA*F3642*6D*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205965759 | AMANA DISTINCTIONS | GVZC200241A* | CA*F3636*6D*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205965742 | AMANA DISTINCTIONS | GVZC200241A* | CA*F3642*6D*+TXV | G*VM970804CNB* | 13,000 | $650 |
| No | 205965743 | AMANA DISTINCTIONS | GVZC200241A* | CA*F3743*6D*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205965751 | AMANA DISTINCTIONS | GVZC200241A* | CHPF3636B6C*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205965741 | AMANA DISTINCTIONS | GVZC200241A* | CA*F3642*6D*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205965744 | AMANA DISTINCTIONS | GVZC200241A* | CA*F3743*6D*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205965747 | AMANA DISTINCTIONS | GVZC200241A* | CA*F3743*6D*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205965746 | AMANA DISTINCTIONS | GVZC200241A* | CA*F3743*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205965748 | AMANA DISTINCTIONS | GVZC200241A* | CA*F3743*6D*+TXV | G*VS960603BUA* | 13,000 | $650 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205965745 | AMANA DISTINCTIONS | GVZC200241A* | CA*F3743*6D*+TXV | G*VM970804CNB* | 13,000 | $650 |
| No | 205965749 | AMANA DISTINCTIONS | GVZC200241A* | CHPF3636B6C*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205965750 | AMANA DISTINCTIONS | GVZC200241A* | CHPF3636B6C*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205965753 | AMANA DISTINCTIONS | GVZC200241A* | CHPF3636B6C*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205965752 | AMANA DISTINCTIONS | GVZC200241A* | CHPF3636B6C*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205965754 | AMANA DISTINCTIONS | GVZC200241A* | CHPF3642C6C*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205965757 | AMANA DISTINCTIONS | GVZC200241A* | AVPEC25B14A* | | 13,600 | $680 |
| No | 205965758 | AMANA DISTINCTIONS | GVZC200241A* | CA*F3137*6A*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205965756 | AMANA DISTINCTIONS | GVZC200241A* | CSCF3642N6D*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205965755 | AMANA DISTINCTIONS | GVZC200241A* | CSCF3642N6D*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205965761 | AMANA DISTINCTIONS | GVZC200241A* | CA*F3743*6D*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205965760 | AMANA DISTINCTIONS | GVZC200241A* | CA*F3642*6D*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205965762 | AMANA DISTINCTIONS | GVZC200241A* | CHPF3636B6C*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205965763 | AMANA DISTINCTIONS | GVZC200241A* | CHPF3642C6C*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205965764 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3137*6A*+TXV | G*VM970603BNB* | 18,200 | $910 |
| No | 205965765 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3137*6A*+TXV | G*VM970803BNB* | 18,200 | $910 |
| No | 205965769 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3137*6A*+TXV | G*VS960603BUA* | 18,200 | $910 |
| No | 205965768 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3137*6A*+TXV | G*VS800604BUA* | 18,200 | $910 |
| No | 205965767 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3137*6A*+MBVC1600**-1A*+TXV | | 18,200 | $910 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205965766 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3137*6A*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 205965771 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3642*6D*+TXV | G*VM970803BNB* | 18,000 | $900 |
| No | 205965770 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3642*6D*+TXV | G*VM970603BNB* | 18,000 | $900 |
| No | 205965777 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3642*6D*+TXV | G*VS800604BUA* | 18,200 | $910 |
| No | 205965773 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3642*6D*+TXV | G*VM971005CNB* | 18,000 | $900 |
| No | 205965772 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3642*6D*+TXV | G*VM970804CNB* | 18,200 | $910 |
| No | 205965776 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3642*6D*+MBVC1600**-1A*+TXV | | 18,000 | $900 |
| No | 205965774 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3642*6D*+TXV | G*VM971205DNB* | 18,000 | $900 |
| No | 205965775 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3642*6D*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 205965826 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3743*6D*+MBVC1201**-1A*+TXV | | 18,200 | $910 |
| No | 205965827 | AMANA DISTINCTIONS | GVZC200361A* | CA*F3743*6D*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205965829 | AMANA DISTINCTIONS | GVZC200361A* | CHPF3642C6C*+MBVC1601**-1A*+TXV | | 18,000 | $900 |
| No | 205965830 | AMANA DISTINCTIONS | GVZC200361A* | CHPF3743C6B*+MBVC1201**-1A*+TXV | | 18,200 | $910 |
| No | 205965831 | AMANA DISTINCTIONS | GVZC200361A* | CHPF3743C6B*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205965834 | AMANA DISTINCTIONS | GVZC200481A* | CA*F4860*6D*+TXV | G*VM970804CNB* | 27,400 | $1,370 |
| No | 205965833 | AMANA DISTINCTIONS | GVZC200361A* | CSCF3642N6D*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205965832 | AMANA DISTINCTIONS | GVZC200361A* | CSCF3642N6D*+MBVC1201**-1A*+TXV | | 18,200 | $910 |
| No | 205965844 | AMANA DISTINCTIONS | GVZC200481A* | CHPF4860D6D*+MBVC1600**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965836 | AMANA DISTINCTIONS | GVZC200481A* | CA*F4860*6D*+TXV | G*VM971205DNB* | 27,400 | $1,370 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205965837 | AMANA DISTINCTIONS | GVZC200481A* | CA*F4860*6D*+MBVC1600**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965842 | AMANA DISTINCTIONS | GVZC200481A* | CHPF4860D6D*+TXV | G*VM971005CNB* | 27,800 | $1,390 |
| No | 205965838 | AMANA DISTINCTIONS | GVZC200481A* | CA*F4860*6D*+MBVC2000**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965839 | AMANA DISTINCTIONS | GVZC200481A* | CA*F4860*6D*+TXV | G*VS800805CUA* | 27,400 | $1,370 |
| No | 205965841 | AMANA DISTINCTIONS | GVZC200481A* | CHPF4860D6D*+TXV | G*VM970804CNB* | 28,000 | $1,400 |
| No | 205965840 | AMANA DISTINCTIONS | GVZC200481A* | CA*F4860*6D*+TXV | G*VS960805CUA* | 27,400 | $1,370 |
| No | 205965843 | AMANA DISTINCTIONS | GVZC200481A* | CHPF4860D6D*+TXV | G*VM971205DNB* | 27,800 | $1,390 |
| No | 205965845 | AMANA DISTINCTIONS | GVZC200481A* | CHPF4860D6D*+TXV | G*VS800805CUA* | 27,200 | $1,360 |
| No | 205965846 | AMANA DISTINCTIONS | GVZC200481A* | CSCF4860N6D*+TXV | G*VM970804CNB* | 27,400 | $1,370 |
| No | 205965847 | AMANA DISTINCTIONS | GVZC200481A* | CSCF4860N6D*+TXV | G*VM971005CNB* | 27,400 | $1,370 |
| No | 205965848 | AMANA DISTINCTIONS | GVZC200481A* | CSCF4860N6D*+TXV | G*VM971205DNB* | 27,400 | $1,370 |
| No | 205965850 | AMANA DISTINCTIONS | GVZC200481A* | CSCF4860N6D*+MBVC2000**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965852 | AMANA DISTINCTIONS | GVZC200481A* | CSCF4860N6D*+TXV | G*VS800805CUA* | 27,400 | $1,370 |
| No | 205965851 | AMANA DISTINCTIONS | GVZC200481A* | CSCF4860N6D*+TXV | G*VS800604BUA* | 27,400 | $1,370 |
| No | 205965849 | AMANA DISTINCTIONS | GVZC200481A* | CSCF4860N6D*+MBVC1600**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965854 | AMANA DISTINCTIONS | GVZC200481A* | AVPEC59D14A* | | 27,000 | $1,350 |
| No | 205965853 | AMANA DISTINCTIONS | GVZC200481A* | CSCF4860N6D*+TXV | G*VS960805CUA* | 27,400 | $1,370 |
| No | 205965859 | AMANA DISTINCTIONS | GVZC200481A* | CSCF4860N6D*+MBVC1601**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965855 | AMANA DISTINCTIONS | GVZC200481A* | CA*F4860*6D*+MBVC1601**-1A*+TXV | | 26,600 | $1,330 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205965856 | AMANA DISTINCTIONS | GVZC200481A* | CA*F4860*6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965857 | AMANA DISTINCTIONS | GVZC200481A* | CHPF4860D6D*+MBVC1601**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965860 | AMANA DISTINCTIONS | GVZC200481A* | CSCF4860N6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965858 | AMANA DISTINCTIONS | GVZC200481A* | CHPF4860D6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965863 | AMANA DISTINCTIONS | GVZC200481A* | CA*F4961*6D*+TXV | G*VM971205DNB* | 27,800 | $1,390 |
| No | 205965864 | AMANA DISTINCTIONS | GVZC200481A* | CA*F4961*6D*+MBVC1600**-1A*+TXV | | 26,800 | $1,340 |
| No | 205965861 | AMANA DISTINCTIONS | GVZC200481A* | CA*F4961*6D*+TXV | G*VM970804CNB* | 27,800 | $1,390 |
| No | 205965862 | AMANA DISTINCTIONS | GVZC200481A* | CA*F4961*6D*+TXV | G*VM971005CNB* | 27,800 | $1,390 |
| No | 205965865 | AMANA DISTINCTIONS | GVZC200481A* | CA*F4961*6D*+TXV | G*VS800604BUA* | 28,000 | $1,400 |
| No | 205965866 | AMANA DISTINCTIONS | GVZC200481A* | CA*F4961*6D*+TXV | G*VS800805CUA* | 27,200 | $1,360 |
| No | 205965867 | AMANA DISTINCTIONS | GVZC200481A* | CA*F4961*6D*+TXV | G*VS960805CUA* | 27,600 | $1,380 |
| No | 205965870 | AMANA DISTINCTIONS | GVZC200481A* | CA*F4961*6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965868 | AMANA DISTINCTIONS | GVZC200481A* | CHPF4860D6D*+MBVC2000**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965869 | AMANA DISTINCTIONS | GVZC200481A* | CA*F4961*6D*+MBVC1601**-1A*+TXV | | 26,800 | $1,340 |
| No | 212391576 | American Standard | 4A6V7X60A1 | 4TXCD010DS3 | S8V2D120M5PDA | 49,500 | $2,475 |
| No | 212391575 | American Standard | 4A6V7X60A1 | 4TXCD010DS3 | S8V2D120M5PCA | 49,500 | $2,475 |
| No | 212391572 | American Standard | 4A6V7X60A1 | 4PX*DU60BS3 | S8V2D120M5PDA | 49,500 | $2,475 |
| No | 212391571 | American Standard | 4A6V7X60A1 | 4PX*DU60BS3 | S8V2D120M5PCA | 49,500 | $2,475 |
| No | 212391552 | American Standard | 4A6V7X48A1 | 4TXCD010DS3 | S8V2D120M5PDA | 37,000 | $1,850 |
| No | 212391553 | American Standard | 4A6V7X48A1 | 4TXCD010DS3 | S8V2D120M5PCA | 37,000 | $1,850 |
| No | 212391551 | American Standard | 4A6V7X48A1 | 4TXCD008DS3 | S8V2D120M5PDA | 37,600 | $1,880 |
| No | 212391550 | American Standard | 4A6V7X48A1 | 4TXCD008DS3 | S8V2D120M5PCA | 37,600 | $1,880 |
| No | 212391546 | American Standard | 4A6V7X48A1 | 4TXCC009DS3 | S8V2C100M5PDA | 37,200 | $1,860 |
| No | 212391549 | American Standard | 4A6V7X48A1 | 4TXCC009DS3 | S8V2C100M5PCA | 37,200 | $1,860 |
| No | 212391547 | American Standard | 4A6V7X48A1 | 4TXCC009DS3 | S8V2C080M5PDA | 37,000 | $1,850 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 212391548 | American Standard | 4A6V7X48A1 | 4TXCC009DS3 | S8V2C080M5PCA | 37,000 | $1,850 |
| No | 212391540 | American Standard | 4A6V7X48A1 | 4TXCC007DS3 | S8V2C100M5PDA | 37,600 | $1,880 |
| No | 212391544 | American Standard | 4A6V7X48A1 | 4TXCC007DS3 | S8V2C100M5PCA | 37,600 | $1,880 |
| No | 212391542 | American Standard | 4A6V7X48A1 | 4TXCC007DS3 | S8V2C080M5PDA | 37,400 | $1,870 |
| No | 212391545 | American Standard | 4A6V7X48A1 | 4TXCC007DS3 | S8V2C080M5PCA | 37,400 | $1,870 |
| No | 212391536 | American Standard | 4A6V7X48A1 | 4TXCC005DS3 | S8V2C100M5PDA | 37,600 | $1,880 |
| No | 212391538 | American Standard | 4A6V7X48A1 | 4TXCC005DS3 | S8V2C100M5PCA | 37,600 | $1,880 |
| No | 212391524 | American Standard | 4A6V7X48A1 | 4TXCB006DS3 | S8V2B080M4PDA | 37,400 | $1,870 |
| No | 212391530 | American Standard | 4A6V7X48A1 | 4TXCB006DS3 | S8V2B080M4PCA | 37,400 | $1,870 |
| No | 212391528 | American Standard | 4A6V7X48A1 | 4TXCB006DS3 | S8V2B060M4PDA | 37,400 | $1,870 |
| No | 212391526 | American Standard | 4A6V7X48A1 | 4TXCB006DS3 | S8V2B060M4PCA | 37,400 | $1,870 |
| No | 212391522 | American Standard | 4A6V7X48A1 | 4PX*DU60BS3 | S8V2D120M5PDA | 37,000 | $1,850 |
| No | 212391521 | American Standard | 4A6V7X48A1 | 4PX*DU60BS3 | S8V2D120M5PCA | 37,000 | $1,850 |
| No | 212391519 | American Standard | 4A6V7X48A1 | 4PX*DU48BS3 | S8V2D120M5PDA | 37,600 | $1,880 |
| No | 212391520 | American Standard | 4A6V7X48A1 | 4PX*DU48BS3 | S8V2D120M5PCA | 37,600 | $1,880 |
| No | 212391516 | American Standard | 4A6V7X48A1 | 4PX*DD60BS3 | S8V2D120M5PDA | 37,000 | $1,850 |
| No | 212391518 | American Standard | 4A6V7X48A1 | 4PX*DD60BS3 | S8V2D120M5PCA | 37,000 | $1,850 |
| No | 212391513 | American Standard | 4A6V7X48A1 | 4PX*CU60BS3 | S8V2C100M5PDA | 37,200 | $1,860 |
| No | 212391512 | American Standard | 4A6V7X48A1 | 4PX*CU60BS3 | S8V2C100M5PCA | 37,200 | $1,860 |
| No | 212391511 | American Standard | 4A6V7X48A1 | 4PX*CU60BS3 | S8V2C080M5PDA | 37,000 | $1,850 |
| No | 212391514 | American Standard | 4A6V7X48A1 | 4PX*CU60BS3 | S8V2C080M5PCA | 37,000 | $1,850 |
| No | 212391504 | American Standard | 4A6V7X48A1 | 4PX*CU48BS3 | S8V2C100M5PDA | 37,600 | $1,880 |
| No | 212391508 | American Standard | 4A6V7X48A1 | 4PX*CU48BS3 | S8V2C100M5PCA | 37,600 | $1,880 |
| No | 212391506 | American Standard | 4A6V7X48A1 | 4PX*CU48BS3 | S8V2C080M5PDA | 37,400 | $1,870 |
| No | 212391510 | American Standard | 4A6V7X48A1 | 4PX*CU48BS3 | S8V2C080M5PCA | 37,400 | $1,870 |
| No | 212391502 | American Standard | 4A6V7X48A1 | 4PX*CU42BS3 | S8V2C100M5PDA | 38,000 | $1,900 |
| No | 212391496 | American Standard | 4A6V7X48A1 | 4PX*CU42BS3 | S8V2C100M5PCA | 38,000 | $1,900 |
| No | 212391494 | American Standard | 4A6V7X48A1 | 4PX*CD60BS3 | S8V2C100M5PDA | 37,200 | $1,860 |
| No | 212391492 | American Standard | 4A6V7X48A1 | 4PX*CD60BS3 | S8V2C100M5PCA | 37,200 | $1,860 |
| No | 212391493 | American Standard | 4A6V7X48A1 | 4PX*CD60BS3 | S8V2C080M5PDA | 37,000 | $1,850 |
| No | 212391491 | American Standard | 4A6V7X48A1 | 4PX*CD60BS3 | S8V2C080M5PCA | 37,000 | $1,850 |
| No | 212391480 | American Standard | 4A6V7X48A1 | 4PX*BU48BS3 | S8V2B080M4PDA | 37,400 | $1,870 |
| No | 212391482 | American Standard | 4A6V7X48A1 | 4PX*BU48BS3 | S8V2B080M4PCA | 37,400 | $1,870 |
| No | 212391478 | American Standard | 4A6V7X48A1 | 4PX*BU48BS3 | S8V2B060M4PDA | 37,400 | $1,870 |
| No | 212391476 | American Standard | 4A6V7X48A1 | 4PX*BU48BS3 | S8V2B060M4PCA | 37,400 | $1,870 |
| No | 212391465 | American Standard | 4A6V7X36A1 | 4TXCC005DS3 | S8V2C100M5PDA | 26,400 | $1,320 |
| No | 212391466 | American Standard | 4A6V7X36A1 | 4TXCC005DS3 | S8V2C100M5PCA | 26,400 | $1,320 |
| No | 212391463 | American Standard | 4A6V7X36A1 | 4TXCB006DS3 | S8V2B080M4PDA | 26,600 | $1,330 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 212391461 | American Standard | 4A6V7X36A1 | 4TXCB006DS3 | S8V2B080M4PCA | 26,600 | $1,330 |
| No | 212391460 | American Standard | 4A6V7X36A1 | 4TXCB006DS3 | S8V2B060M4PDA | 26,600 | $1,330 |
| No | 212391459 | American Standard | 4A6V7X36A1 | 4TXCB006DS3 | S8V2B060M4PCA | 26,600 | $1,330 |
| No | 212391458 | American Standard | 4A6V7X36A1 | 4TXCB006DS3 | S8V2A040M3PDA | 25,200 | $1,260 |
| No | 212391462 | American Standard | 4A6V7X36A1 | 4TXCB006DS3 | S8V2A040M3PCA | 25,200 | $1,260 |
| No | 212391449 | American Standard | 4A6V7X36A1 | 4TXCB004DS3 | S8V2B080M4PDA | 26,400 | $1,320 |
| No | 212391451 | American Standard | 4A6V7X36A1 | 4TXCB004DS3 | S8V2B080M4PCA | 26,400 | $1,320 |
| No | 212391447 | American Standard | 4A6V7X36A1 | 4TXCB004DS3 | S8V2B060M4PDA | 26,200 | $1,310 |
| No | 212391457 | American Standard | 4A6V7X36A1 | 4TXCB004DS3 | S8V2B060M4PCA | 26,200 | $1,310 |
| No | 212391453 | American Standard | 4A6V7X36A1 | 4TXCB004DS3 | S8V2A040M3PDA | 25,000 | $1,250 |
| No | 212391455 | American Standard | 4A6V7X36A1 | 4TXCB004DS3 | S8V2A040M3PCA | 25,000 | $1,250 |
| No | 212391444 | American Standard | 4A6V7X36A1 | 4PX*CU48BS3 | S8V2C100M5PDA | 26,400 | $1,320 |
| No | 212391443 | American Standard | 4A6V7X36A1 | 4PX*CU48BS3 | S8V2C100M5PCA | 26,400 | $1,320 |
| No | 212391442 | American Standard | 4A6V7X36A1 | 4PX*CU48BS3 | S8V2C080M5PDA | 26,200 | $1,310 |
| No | 212391445 | American Standard | 4A6V7X36A1 | 4PX*CU48BS3 | S8V2C080M5PCA | 26,200 | $1,310 |
| No | 212391438 | American Standard | 4A6V7X36A1 | 4PX*CU42BS3 | S8V2C100M5PDA | 26,600 | $1,330 |
| No | 212391441 | American Standard | 4A6V7X36A1 | 4PX*CU42BS3 | S8V2C100M5PCA | 26,600 | $1,330 |
| No | 212391440 | American Standard | 4A6V7X36A1 | 4PX*CU42BS3 | S8V2C080M5PDA | 26,400 | $1,320 |
| No | 212391439 | American Standard | 4A6V7X36A1 | 4PX*CU42BS3 | S8V2C080M5PCA | 26,400 | $1,320 |
| No | 212391434 | American Standard | 4A6V7X36A1 | 4PX*CU36BS3 | S8V2C100M5PDA | 26,200 | $1,310 |
| No | 212391436 | American Standard | 4A6V7X36A1 | 4PX*CU36BS3 | S8V2C100M5PCA | 26,200 | $1,310 |
| No | 212391435 | American Standard | 4A6V7X36A1 | 4PX*CU36BS3 | S8V2C080M5PDA | 25,800 | $1,290 |
| No | 212391437 | American Standard | 4A6V7X36A1 | 4PX*CU36BS3 | S8V2C080M5PCA | 25,800 | $1,290 |
| No | 212391419 | American Standard | 4A6V7X36A1 | 4PX*BU42BS3 | S8V2B080M4PDA | 26,800 | $1,340 |
| No | 212391416 | American Standard | 4A6V7X36A1 | 4PX*BU42BS3 | S8V2B080M4PCA | 26,800 | $1,340 |
| No | 212391417 | American Standard | 4A6V7X36A1 | 4PX*BU42BS3 | S8V2B060M4PDA | 26,800 | $1,340 |
| No | 212391418 | American Standard | 4A6V7X36A1 | 4PX*BU42BS3 | S8V2B060M4PCA | 26,800 | $1,340 |
| No | 212391415 | American Standard | 4A6V7X36A1 | 4PX*BU36BS3 | S8V2B080M4PDA | 26,200 | $1,310 |
| No | 212391405 | American Standard | 4A6V7X36A1 | 4PX*BU36BS3 | S8V2B080M4PCA | 26,200 | $1,310 |
| No | 212391407 | American Standard | 4A6V7X36A1 | 4PX*BU36BS3 | S8V2B060M4PDA | 26,400 | $1,320 |
| No | 212391409 | American Standard | 4A6V7X36A1 | 4PX*BU36BS3 | S8V2B060M4PCA | 26,400 | $1,320 |
| No | 212391411 | American Standard | 4A6V7X36A1 | 4PX*BU36BS3 | S8V2A040M3PDA | 25,000 | $1,250 |
| No | 212391413 | American Standard | 4A6V7X36A1 | 4PX*BU36BS3 | S8V2A040M3PCA | 25,000 | $1,250 |
| No | 212391382 | American Standard | 4A6V7X24A1 | 4PX*BU36BS3 | S8V2A040M3PDA | 16,300 | $815 |
| No | 212391383 | American Standard | 4A6V7X24A1 | 4PX*BU36BS3 | S8V2A040M3PCA | 16,300 | $815 |
| No | 210636946 | AMERICAN STANDARD | 4A6V8X60A1 | TEM8B0C60V51+TDR | N/A | 48,500 | $2,425 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207590077 | AMERICAN STANDARD | 4A6V8X60A1 | TEM8A0D60V51+TDR | N/A | 48,000 | $2,400 |
| No | 210636944 | AMERICAN STANDARD | 4A6V8X60A1 | TEM8A0D48V41+TDR | N/A | 48,500 | $2,425 |
| No | 210636942 | AMERICAN STANDARD | 4A6V8X60A1 | TEM8A0C48V41+TDR | N/A | 48,500 | $2,425 |
| No | 211081504 | AMERICAN STANDARD | 4A6V8X60A1 | 4TXCD010DS3 | S8V2D120M5PDA | 49,500 | $2,475 |
| No | 210692143 | AMERICAN STANDARD | 4A6V8X60A1 | 4TXCD010DS3 | S8V2D120M5PCA | 49,500 | $2,475 |
| No | 211081501 | AMERICAN STANDARD | 4A6V8X60A1 | 4PX*DU60BS3 | S8V2D120M5PDA | 49,500 | $2,475 |
| No | 210692139 | AMERICAN STANDARD | 4A6V8X60A1 | 4PX*DU60BS3 | S8V2D120M5PCA | 49,500 | $2,475 |
| No | 210636941 | AMERICAN STANDARD | 4A6V8X48A1 | TEM8B0C60V51+TDR | N/A | 36,600 | $1,830 |
| No | 207590075 | AMERICAN STANDARD | 4A6V8X48A1 | TEM8A0D60V51+TDR | N/A | 36,400 | $1,820 |
| No | 207590074 | AMERICAN STANDARD | 4A6V8X48A1 | TEM8A0D48V41+TDR | N/A | 37,000 | $1,850 |
| No | 207590072 | AMERICAN STANDARD | 4A6V8X48A1 | TEM8A0C48V41+TDR | N/A | 36,600 | $1,830 |
| No | 207590071 | AMERICAN STANDARD | 4A6V8X48A1 | TEM8A0C42V41+TDR | N/A | 36,600 | $1,830 |
| No | 210929585 | AMERICAN STANDARD | 4A6V8X48A1 | TAMXB0C60V51 | N/A | 35,800 | $1,790 |
| No | 210929584 | AMERICAN STANDARD | 4A6V8X48A1 | TAMXB0C48V41 | N/A | 35,600 | $1,780 |
| No | 207690057 | AMERICAN STANDARD | 4A6V8X48A1 | TAMXA0C60V51 | N/A | 35,800 | $1,790 |
| No | 207590049 | AMERICAN STANDARD | 4A6V8X48A1 | TAM9A0C60V51 | N/A | 35,800 | $1,790 |
| No | 207590048 | AMERICAN STANDARD | 4A6V8X48A1 | TAM9A0C48V41 | N/A | 35,600 | $1,780 |
| No | 207805716 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3+P0V0D000M50SC+RP | N/A | 36,400 | $1,820 |
| No | 207805715 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3+P0V0C000M50SC+RP | N/A | 35,400 | $1,770 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207590208 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3 | S9V2D120U5VSA+RP | 36,800 | $1,840 |
| No | 210653223 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3 | S9V2D120U5PSB+RP | 36,800 | $1,840 |
| No | 207599980 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3 | S9V2C100U5PSB+RP | 35,800 | $1,790 |
| No | 207590209 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3 | S9V2C100U4VSA+RP | 35,800 | $1,790 |
| No | 210653222 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3 | S9V2C100U4PSB+RP | 35,800 | $1,790 |
| No | 210653221 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3 | S9V2C080U5PSB+RP | 35,800 | $1,790 |
| No | 211081497 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3 | S8V2D120M5PDA | 37,000 | $1,850 |
| No | 210692136 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3 | S8V2D120M5PCA | 37,000 | $1,850 |
| No | 211081496 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3 | S8V2C100M5PDA | 36,000 | $1,800 |
| No | 210692135 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3 | S8V2C100M5PCA | 36,000 | $1,800 |
| No | 211089210 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3 | S8V2C080M5PDA | 35,800 | $1,790 |
| No | 210692251 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3 | S8V2C080M5PCA | 35,800 | $1,790 |
| No | 207590618 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3 | L8V1C100U5VSA+RP | 35,600 | $1,780 |
| No | 207590814 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3 | *UHMD120ACV5 | 36,600 | $1,830 |
| No | 211597795 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3 | *UD2D120B9V5+RP | 36,800 | $1,840 |
| No | 207590811 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3 | *UD2D120ACV5 | 37,000 | $1,850 |
| No | 210641282 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3 | *UD2D120A9V5+RP | 37,000 | $1,850 |
| No | 210641281 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3 | *UD2C100B9V5+RP | 35,800 | $1,790 |
| No | 211289097 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3 | *UD2C100ACV5 | 36,200 | $1,810 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210641278 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3 | *UD2C100A9V5+RP | 35,600 | $1,780 |
| No | 210641280 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3 | *UD2C080B9V4+RP | 35,600 | $1,780 |
| No | 211597796 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3 | *UD2C080ACV4 | 35,600 | $1,780 |
| No | 210641279 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3 | *UD2C080A9V4+RP | 36,000 | $1,800 |
| No | 207805713 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3+P0V0D000M50SC+RP | N/A | 37,000 | $1,850 |
| No | 207805714 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3+P0V0C000M50SC+RP | N/A | 36,000 | $1,800 |
| No | 210653217 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | S9V2D120U5VSA+RP | 37,200 | $1,860 |
| No | 210653218 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | S9V2D120U5PSB+RP | 37,200 | $1,860 |
| No | 207599977 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | S9V2D120D5PSB+RP | 36,200 | $1,810 |
| No | 210653219 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | S9V2C100U5PSB+RP | 36,200 | $1,810 |
| No | 210653220 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | S9V2C100U4VSA+RP | 36,200 | $1,810 |
| No | 210653216 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | S9V2C100U4PSB+RP | 36,200 | $1,810 |
| No | 210653213 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | S9V2C080U5PSB+RP | 36,200 | $1,810 |
| No | 211081495 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | S8V2D120M5PDA | 37,600 | $1,880 |
| No | 210692134 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | S8V2D120M5PCA | 37,600 | $1,880 |
| No | 211089208 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | S8V2C100M5PDA | 36,400 | $1,820 |
| No | 210692249 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | S8V2C100M5PCA | 36,400 | $1,820 |
| No | 211089209 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | S8V2C080M5PDA | 36,200 | $1,810 |
| No | 210692250 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | S8V2C080M5PCA | 36,200 | $1,810 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210653214 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | L8V1C100U5VSA+RP | 36,200 | $1,810 |
| No | 210653215 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | *UHMD120ACV5 | 37,000 | $1,850 |
| No | 211597794 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | *UD2D120B9V5+RP | 37,200 | $1,860 |
| No | 211289096 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | *UD2D120ACV5 | 37,400 | $1,870 |
| No | 210641276 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | *UD2D120A9V5+RP | 37,400 | $1,870 |
| No | 210641277 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | *UD2C100B9V5+RP | 36,200 | $1,810 |
| No | 211289095 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | *UD2C100ACV5 | 36,600 | $1,830 |
| No | 210641274 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | *UD2C080B9V4+RP | 36,200 | $1,810 |
| No | 211598192 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | *UD2C080ACV4 | 36,000 | $1,800 |
| No | 210641275 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | *UD2C080A9V4+RP | 36,400 | $1,820 |
| No | 207805712 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC009DS3+P0V0C000M50SC+RP | N/A | 36,600 | $1,830 |
| No | 210653211 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC009DS3 | S9V2C100U5PSB+RP | 37,000 | $1,850 |
| No | 207590206 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC009DS3 | S9V2C100U4VSA+RP | 37,000 | $1,850 |
| No | 210653209 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC009DS3 | S9V2C100U4PSB+RP | 37,000 | $1,850 |
| No | 210653210 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC009DS3 | S9V2C080U5PSB+RP | 37,000 | $1,850 |
| No | 211081494 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC009DS3 | S8V2C100M5PDA | 37,200 | $1,860 |
| No | 210692133 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC009DS3 | S8V2C100M5PCA | 37,200 | $1,860 |
| No | 211081493 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC009DS3 | S8V2C080M5PDA | 37,000 | $1,850 |
| No | 210692132 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC009DS3 | S8V2C080M5PCA | 37,000 | $1,850 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210653212 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC009DS3 | L8V1C100U5VSA+RP | 36,800 | $1,840 |
| No | 210641272 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC009DS3 | *UD2C100B9V5+RP | 37,000 | $1,850 |
| No | 207590809 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC009DS3 | *UD2C100ACV5 | 37,400 | $1,870 |
| No | 210641271 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC009DS3 | *UD2C100A9V5+RP | 36,800 | $1,840 |
| No | 210641269 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC009DS3 | *UD2C080B9V4+RP | 36,800 | $1,840 |
| No | 207590806 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC009DS3 | *UD2C080ACV4 | 36,600 | $1,830 |
| No | 210641270 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC009DS3 | *UD2C080A9V4+RP | 37,200 | $1,860 |
| No | 207805711 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC007DS3+P0V0C000M50SC+RP | N/A | 37,200 | $1,860 |
| No | 210653207 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC007DS3 | S9V2C100U5PSB+RP | 37,400 | $1,870 |
| No | 207590203 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC007DS3 | S9V2C100U4VSA+RP | 37,400 | $1,870 |
| No | 207599975 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC007DS3 | S9V2C100U4PSB+RP | 37,400 | $1,870 |
| No | 210653909 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC007DS3 | S9V2C100D5PSB+RP | 36,400 | $1,820 |
| No | 210653908 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC007DS3 | S9V2C100D4VSA+RP | 36,400 | $1,820 |
| No | 207599976 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC007DS3 | S9V2C100D4PSB+RP | 36,400 | $1,820 |
| No | 210653208 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC007DS3 | S9V2C080U5PSB+RP | 37,400 | $1,870 |
| No | 211081492 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC007DS3 | S8V2C100M5PDA | 37,600 | $1,880 |
| No | 210692131 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC007DS3 | S8V2C100M5PCA | 37,600 | $1,880 |
| No | 211081491 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC007DS3 | S8V2C080M5PDA | 37,400 | $1,870 |
| No | 210692130 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC007DS3 | S8V2C080M5PCA | 37,400 | $1,870 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207590617 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC007DS3 | L8V1C100U5VSA+RP | 37,400 | $1,870 |
| No | 210641265 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC007DS3 | *UD2C100B9V5+RP | 37,400 | $1,870 |
| No | 207590803 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC007DS3 | *UD2C100ACV5 | 37,800 | $1,890 |
| No | 210641266 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC007DS3 | *UD2C100A9V5+RP | 37,200 | $1,860 |
| No | 210641267 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC007DS3 | *UD2C080B9V4+RP | 37,000 | $1,850 |
| No | 207590805 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC007DS3 | *UD2C080ACV4 | 37,200 | $1,860 |
| No | 210641268 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC007DS3 | *UD2C080A9V4+RP | 37,600 | $1,880 |
| No | 210653910 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC007DS3 | *DHMC100ACV4 | 36,200 | $1,810 |
| No | 207805710 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC005DS3+P0V0C000M50SC+RP | N/A | 37,000 | $1,850 |
| No | 210653202 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC005DS3 | S9V2C100U5PSB+RP | 37,000 | $1,850 |
| No | 210653206 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC005DS3 | S9V2C100U4VSA+RP | 37,400 | $1,870 |
| No | 210653205 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC005DS3 | S9V2C100U4PSB+RP | 37,000 | $1,850 |
| No | 210653204 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC005DS3 | S9V2C080U5PSB+RP | 37,000 | $1,850 |
| No | 211089207 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC005DS3 | S8V2C100M5PDA | 37,200 | $1,860 |
| No | 210692248 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC005DS3 | S8V2C100M5PCA | 37,200 | $1,860 |
| No | 210653203 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC005DS3 | L8V1C100U5VSA+RP | 37,200 | $1,860 |
| No | 211598191 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC005DS3 | *UD2C080ACV4 | 37,000 | $1,850 |
| No | 210653200 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCB006DS3 | S9V2B080U4VSA+RP | 37,800 | $1,890 |
| No | 207599972 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCB006DS3 | S9V2B080U4PSB+RP | 37,800 | $1,890 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210653907 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCB006DS3 | S9V2B080D4VSA+RP | 36,600 | $1,830 |
| No | 207599974 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCB006DS3 | S9V2B080D4PSB+RP | 36,600 | $1,830 |
| No | 211081489 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCB006DS3 | S8V2B080M4PDA | 37,400 | $1,870 |
| No | 210692128 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCB006DS3 | S8V2B080M4PCA | 37,400 | $1,870 |
| No | 211081490 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCB006DS3 | S8V2B060M4PDA | 37,400 | $1,870 |
| No | 210692129 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCB006DS3 | S8V2B060M4PCA | 37,400 | $1,870 |
| No | 210653201 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCB006DS3 | L8V1B080U4VSA+RP | 37,400 | $1,870 |
| No | 207805708 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3+P0V0D000M50SC+RP | N/A | 36,400 | $1,820 |
| No | 207805709 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3+P0V0C000M50SC+RP | N/A | 35,400 | $1,770 |
| No | 207590201 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | S9V2D120U5VSA+RP | 36,800 | $1,840 |
| No | 210653199 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | S9V2D120U5PSB+RP | 36,800 | $1,840 |
| No | 207599971 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | S9V2C100U5PSB+RP | 35,800 | $1,790 |
| No | 207590202 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | S9V2C100U4VSA+RP | 35,800 | $1,790 |
| No | 210653198 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | S9V2C100U4PSB+RP | 35,800 | $1,790 |
| No | 210653197 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | S9V2C080U5PSB+RP | 35,800 | $1,790 |
| No | 211081487 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | S8V2D120M5PDA | 37,000 | $1,850 |
| No | 210692127 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | S8V2D120M5PCA | 37,000 | $1,850 |
| No | 211081488 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | S8V2C100M5PDA | 36,000 | $1,800 |
| No | 210692126 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | S8V2C100M5PCA | 36,000 | $1,800 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211089205 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | S8V2C080M5PDA | 35,800 | $1,790 |
| No | 210692246 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | S8V2C080M5PCA | 35,800 | $1,790 |
| No | 207590616 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | L8V1C100U5VSA+RP | 35,600 | $1,780 |
| No | 207590785 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | *UHMD120ACV5 | 36,600 | $1,830 |
| No | 211597793 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | *UD2D120B9V5+RP | 36,800 | $1,840 |
| No | 207590784 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | *UD2D120ACV5 | 37,000 | $1,850 |
| No | 210641261 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | *UD2D120A9V5+RP | 37,000 | $1,850 |
| No | 210641263 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | *UD2C100B9V5+RP | 35,800 | $1,790 |
| No | 211289094 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | *UD2C100ACV5 | 36,200 | $1,810 |
| No | 210641264 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | *UD2C100A9V5+RP | 35,600 | $1,780 |
| No | 210641262 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | *UD2C080B9V4+RP | 35,600 | $1,780 |
| No | 211597792 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | *UD2C080ACV4 | 35,600 | $1,780 |
| No | 210641260 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | *UD2C080A9V4+RP | 36,000 | $1,800 |
| No | 207805707 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3+P0V0D000M50SC+RP | N/A | 37,000 | $1,850 |
| No | 207805706 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3+P0V0C000M50SC+RP | N/A | 36,000 | $1,800 |
| No | 210653191 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3 | S9V2D120U5VSA+RP | 37,200 | $1,860 |
| No | 210653192 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3 | S9V2D120U5PSB+RP | 37,200 | $1,860 |
| No | 207590238 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3 | S9V2D120D5PSB+RP | 36,200 | $1,810 |
| No | 210653193 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3 | S9V2C100U5PSB+RP | 36,200 | $1,810 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210653194 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3 | S9V2C100U4VSA+RP | 36,200 | $1,810 |
| No | 210653195 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3 | S9V2C100U4PSB+RP | 36,200 | $1,810 |
| No | 210653196 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3 | S9V2C080U5PSB+RP | 36,200 | $1,810 |
| No | 211081486 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3 | S8V2D120M5PDA | 37,600 | $1,880 |
| No | 210692125 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3 | S8V2D120M5PCA | 37,600 | $1,880 |
| No | 211089203 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3 | S8V2C100M5PDA | 36,400 | $1,820 |
| No | 210692245 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3 | S8V2C100M5PCA | 36,400 | $1,820 |
| No | 211089204 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3 | S8V2C080M5PDA | 36,200 | $1,810 |
| No | 210692244 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3 | S8V2C080M5PCA | 36,200 | $1,810 |
| No | 210653190 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3 | L8V1C100U5VSA+RP | 36,200 | $1,810 |
| No | 210653189 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3 | *UHMD120ACV5 | 37,000 | $1,850 |
| No | 211597791 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3 | *UD2D120B9V5+RP | 37,200 | $1,860 |
| No | 211289093 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3 | *UD2D120ACV5 | 37,400 | $1,870 |
| No | 210641256 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3 | *UD2D120A9V5+RP | 37,400 | $1,870 |
| No | 210641259 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3 | *UD2C100B9V5+RP | 36,200 | $1,810 |
| No | 211289092 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3 | *UD2C100ACV5 | 36,600 | $1,830 |
| No | 210641258 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3 | *UD2C080B9V4+RP | 36,200 | $1,810 |
| No | 211598190 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3 | *UD2C080ACV4 | 36,000 | $1,800 |
| No | 210641257 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3 | *UD2C080A9V4+RP | 36,400 | $1,820 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207805702 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD60BS3+P0V0D000M50SC+RP | N/A | 36,400 | $1,820 |
| No | 207805703 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD60BS3+P0V0C000M50SC+RP | N/A | 35,400 | $1,770 |
| No | 211597790 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD60BS3+HORIZ-RT | *UD2D120B9V5+RP | 36,200 | $1,810 |
| No | 211289091 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD60BS3+HORIZ-RT | *UD2D120ACV5 | 37,000 | $1,850 |
| No | 210641254 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD60BS3+HORIZ-RT | *UD2D120A9V5+RP | 36,200 | $1,810 |
| No | 211289090 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD60BS3+HORIZ-RT | *UD2C100ACV5 | 36,200 | $1,810 |
| No | 211597789 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD60BS3+HORIZ-RT | *UD2C080ACV4 | 35,400 | $1,770 |
| No | 210653188 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD60BS3 | S9V2D120D5PSB+RP | 36,800 | $1,840 |
| No | 210653187 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD60BS3 | S9V2C100D5PSB+RP | 35,800 | $1,790 |
| No | 207590200 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD60BS3 | S9V2C100D4VSA+RP | 35,600 | $1,780 |
| No | 211081484 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD60BS3 | S8V2D120M5PDA | 37,000 | $1,850 |
| No | 210692124 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD60BS3 | S8V2D120M5PCA | 37,000 | $1,850 |
| No | 211081485 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD60BS3 | S8V2C100M5PDA | 36,000 | $1,800 |
| No | 210692123 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD60BS3 | S8V2C100M5PCA | 36,000 | $1,800 |
| No | 207590827 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD60BS3 | *DHMC100ACV4 | 35,600 | $1,780 |
| No | 207590825 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD60BS3 | *DD2D120ACV5 | 36,400 | $1,820 |
| No | 210641248 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD60BS3 | *DD2D120A9V5+RP | 36,600 | $1,830 |
| No | 207805697 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU60BS3+P0V0C000M50SC+RP | N/A | 36,600 | $1,830 |
| No | 210653185 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU60BS3 | S9V2C100U5PSB+RP | 37,000 | $1,850 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207590197 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU60BS3 | S9V2C100U4VSA+RP | 37,000 | $1,850 |
| No | 210653183 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU60BS3 | S9V2C100U4PSB+RP | 37,000 | $1,850 |
| No | 210653184 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU60BS3 | S9V2C080U5PSB+RP | 37,000 | $1,850 |
| No | 211081483 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU60BS3 | S8V2C100M5PDA | 37,200 | $1,860 |
| No | 210692122 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU60BS3 | S8V2C100M5PCA | 37,200 | $1,860 |
| No | 211081482 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU60BS3 | S8V2C080M5PDA | 37,000 | $1,850 |
| No | 210692121 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU60BS3 | S8V2C080M5PCA | 37,000 | $1,850 |
| No | 207590615 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU60BS3 | L8V1C100U5VSA+RP | 36,800 | $1,840 |
| No | 210641245 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU60BS3 | *UD2C100B9V5+RP | 37,000 | $1,850 |
| No | 207590780 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU60BS3 | *UD2C100ACV5 | 37,400 | $1,870 |
| No | 210641247 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU60BS3 | *UD2C100A9V5+RP | 36,800 | $1,840 |
| No | 210641244 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU60BS3 | *UD2C080B9V4+RP | 36,800 | $1,840 |
| No | 207590781 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU60BS3 | *UD2C080ACV4 | 36,600 | $1,830 |
| No | 210641246 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU60BS3 | *UD2C080A9V4+RP | 37,200 | $1,860 |
| No | 207805696 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU48BS3+P0V0C000M50SC+RP | N/A | 37,200 | $1,860 |
| No | 210653181 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU48BS3 | S9V2C100U5PSB+RP | 37,400 | $1,870 |
| No | 207590195 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU48BS3 | S9V2C100U4VSA+RP | 37,400 | $1,870 |
| No | 207599970 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU48BS3 | S9V2C100U4PSB+RP | 37,400 | $1,870 |
| No | 207590236 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU48BS3 | S9V2C100D5PSB+RP | 36,400 | $1,820 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210653906 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU48BS3 | S9V2C100D4VSA+RP | 36,400 | $1,820 |
| No | 207590235 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU48BS3 | S9V2C100D4PSB+RP | 36,400 | $1,820 |
| No | 210653182 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU48BS3 | S9V2C080U5PSB+RP | 37,400 | $1,870 |
| No | 211081481 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU48BS3 | S8V2C100M5PDA | 37,600 | $1,880 |
| No | 210692119 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU48BS3 | S8V2C100M5PCA | 37,600 | $1,880 |
| No | 211081480 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU48BS3 | S8V2C080M5PDA | 37,400 | $1,870 |
| No | 210692120 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU48BS3 | S8V2C080M5PCA | 37,400 | $1,870 |
| No | 207590614 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU48BS3 | L8V1C100U5VSA+RP | 37,400 | $1,870 |
| No | 210641240 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU48BS3 | *UD2C100B9V5+RP | 37,400 | $1,870 |
| No | 207590776 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU48BS3 | *UD2C100ACV5 | 37,800 | $1,890 |
| No | 210641242 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU48BS3 | *UD2C100A9V5+RP | 37,200 | $1,860 |
| No | 210641241 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU48BS3 | *UD2C080B9V4+RP | 37,000 | $1,850 |
| No | 207590778 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU48BS3 | *UD2C080ACV4 | 37,200 | $1,860 |
| No | 210641243 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU48BS3 | *UD2C080A9V4+RP | 37,600 | $1,880 |
| No | 210653905 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU48BS3 | *DHMC100ACV4 | 36,200 | $1,810 |
| No | 207805695 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU42BS3+P0V0C000M50SC+RP | N/A | 37,400 | $1,870 |
| No | 210653176 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU42BS3 | S9V2C100U5PSB+RP | 37,800 | $1,890 |
| No | 210653177 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU42BS3 | S9V2C100U4VSA+RP | 37,600 | $1,880 |
| No | 210653178 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU42BS3 | S9V2C100U4PSB+RP | 37,600 | $1,880 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210653180 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU42BS3 | S9V2C080U5PSB+RP | 37,800 | $1,890 |
| No | 211081479 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU42BS3 | S8V2C100M5PDA | 38,000 | $1,900 |
| No | 210692118 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU42BS3 | S8V2C100M5PCA | 38,000 | $1,900 |
| No | 210653179 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU42BS3 | L8V1C100U5VSA+RP | 37,600 | $1,880 |
| No | 210641237 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU42BS3 | *UD2C100B9V5+RP | 37,800 | $1,890 |
| No | 211597788 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU42BS3 | *UD2C100ACV5 | 37,800 | $1,890 |
| No | 210641238 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU42BS3 | *UD2C080B9V4+RP | 37,200 | $1,860 |
| No | 211597787 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU42BS3 | *UD2C080ACV4 | 37,400 | $1,870 |
| No | 210641235 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU42BS3 | *UD2C080A9V4+RP | 38,000 | $1,900 |
| No | 207805693 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CD60BS3+P0V0C000M50SC+RP | N/A | 36,600 | $1,830 |
| No | 211289089 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CD60BS3+HORIZ-RT | *UD2C100ACV5 | 37,200 | $1,860 |
| No | 210641233 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CD60BS3+HORIZ-RT | *UD2C080B9V4+RP | 36,600 | $1,830 |
| No | 211597786 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CD60BS3+HORIZ-RT | *UD2C080ACV4 | 36,600 | $1,830 |
| No | 209449884 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CD60BS3 | S9V2C100D5PSB+RP | 37,000 | $1,850 |
| No | 207590194 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CD60BS3 | S9V2C100D4VSA+RP | 36,800 | $1,840 |
| No | 211081477 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CD60BS3 | S8V2C100M5PDA | 37,200 | $1,860 |
| No | 210692116 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CD60BS3 | S8V2C100M5PCA | 37,200 | $1,860 |
| No | 211081476 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CD60BS3 | S8V2C080M5PDA | 37,000 | $1,850 |
| No | 210692115 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CD60BS3 | S8V2C080M5PCA | 37,000 | $1,850 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207590775 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CD60BS3 | *DHMC100ACV4 | 36,800 | $1,840 |
| No | 210641230 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CD60BS3 | *DD2C100A9V5+RP | 36,800 | $1,840 |
| No | 210653165 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*BU48BS3 | S9V2B080U4VSA+RP | 37,800 | $1,890 |
| No | 207599968 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*BU48BS3 | S9V2B080U4PSB+RP | 37,800 | $1,890 |
| No | 210653904 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*BU48BS3 | S9V2B080D4VSA+RP | 36,600 | $1,830 |
| No | 207590264 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*BU48BS3 | S9V2B080D4PSB+RP | 36,600 | $1,830 |
| No | 211081475 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*BU48BS3 | S8V2B080M4PDA | 37,400 | $1,870 |
| No | 210692113 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*BU48BS3 | S8V2B080M4PCA | 37,400 | $1,870 |
| No | 211081474 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*BU48BS3 | S8V2B060M4PDA | 37,400 | $1,870 |
| No | 210692114 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*BU48BS3 | S8V2B060M4PCA | 37,400 | $1,870 |
| No | 210653166 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*BU48BS3 | L8V1B080U4VSA+RP | 37,400 | $1,870 |
| No | 207590068 | AMERICAN STANDARD | 4A6V8X36A1 | TEM8A0C42V41+TDR | N/A | 26,200 | $1,310 |
| No | 207590067 | AMERICAN STANDARD | 4A6V8X36A1 | TEM8A0C36V31+TDR | N/A | 26,200 | $1,310 |
| No | 207590066 | AMERICAN STANDARD | 4A6V8X36A1 | TEM8A0B30V31+TDR | N/A | 26,600 | $1,330 |
| No | 210929582 | AMERICAN STANDARD | 4A6V8X36A1 | TAMXB0C36V31 | N/A | 25,800 | $1,290 |
| No | 210929581 | AMERICAN STANDARD | 4A6V8X36A1 | TAMXB0B30V31 | N/A | 26,200 | $1,310 |
| No | 207690061 | AMERICAN STANDARD | 4A6V8X36A1 | TAMXA0B30V31 | N/A | 26,200 | $1,310 |
| No | 207590046 | AMERICAN STANDARD | 4A6V8X36A1 | TAM9A0C36V31 | N/A | 25,800 | $1,290 |
| No | 207590834 | AMERICAN STANDARD | 4A6V8X36A1 | TAM9A0B30V31 | N/A | 26,200 | $1,310 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207590190 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCC005DS3 | S9V2C100U4VSA+RP | 25,800 | $1,290 |
| No | 210653159 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCC005DS3 | S9V2C100U4PSB+RP | 25,800 | $1,290 |
| No | 210653160 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCC005DS3 | S9V2C100D4VSA+RP | 25,400 | $1,270 |
| No | 210653162 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCC005DS3 | S9V2C100D4PSB+RP | 25,400 | $1,270 |
| No | 211081473 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCC005DS3 | S8V2C100M5PDA | 26,200 | $1,310 |
| No | 210692112 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCC005DS3 | S8V2C100M5PCA | 26,200 | $1,310 |
| No | 210641223 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCC005DS3 | *UD2C100B9V5+RP | 25,800 | $1,290 |
| No | 207590799 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCC005DS3 | *UD2C100ACV5 | 26,400 | $1,320 |
| No | 210641222 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCC005DS3 | *UD2C100A9V5+RP | 26,200 | $1,310 |
| No | 210641221 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCC005DS3 | *UD2C080B9V4+RP | 25,800 | $1,290 |
| No | 207590797 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCC005DS3 | *UD2C080ACV4 | 26,000 | $1,300 |
| No | 210641220 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCC005DS3 | *UD2C080A9V4+RP | 25,800 | $1,290 |
| No | 210653161 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCC005DS3 | *DHMC100ACV4 | 25,600 | $1,280 |
| No | 211597785 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCC005DS3 | *DD2C100ACV5 | 25,600 | $1,280 |
| No | 210641224 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCC005DS3 | *DD2C100A9V5+RP | 25,200 | $1,260 |
| No | 211081470 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB006DS3 | S8V2B080M4PDA | 26,600 | $1,330 |
| No | 210692110 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB006DS3 | S8V2B080M4PCA | 26,600 | $1,330 |
| No | 211081469 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB006DS3 | S8V2B060M4PDA | 26,600 | $1,330 |
| No | 210692109 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB006DS3 | S8V2B060M4PCA | 26,600 | $1,330 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211081471 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB006DS3 | S8V2A040M3PDA | 25,200 | $1,260 |
| No | 210692108 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB006DS3 | S8V2A040M3PCA | 25,200 | $1,260 |
| No | 210653158 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB006DS3 | L8V1B080U4VSA+RP | 26,600 | $1,330 |
| No | 210653157 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB006DS3 | L8V1A060U3VSA+RP | 25,400 | $1,270 |
| No | 210653156 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB006DS3 | L8V1A040U3VSA+RP | 25,400 | $1,270 |
| No | 209459222 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB006DS3 | *UD2B080ACV3 | 26,000 | $1,300 |
| No | 211597784 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB006DS3 | *UD2B060ACV3 | 26,200 | $1,310 |
| No | 210641218 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB006DS3 | *UD2B060A9V3+RP | 26,000 | $1,300 |
| No | 207590389 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | S9V2B080U4VSA+RP | 25,800 | $1,290 |
| No | 210653148 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | S9V2B080U4PSB+RP | 26,000 | $1,300 |
| No | 210653154 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | S9V2B080D4PSB+RP | 25,600 | $1,280 |
| No | 207590184 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | S9V2B060U3VSA+RP | 26,000 | $1,300 |
| No | 210653147 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | S9V2B060U3PSB+RP | 26,000 | $1,300 |
| No | 207590185 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | S9V2B040U3VSA+RP | 26,000 | $1,300 |
| No | 210653146 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | S9V2B040U3PSB+RP | 26,000 | $1,300 |
| No | 210653150 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | S9V2B040D3PSB+RP | 25,600 | $1,280 |
| No | 211081468 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | S8V2B080M4PDA | 26,400 | $1,320 |
| No | 210692106 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | S8V2B080M4PCA | 26,400 | $1,320 |
| No | 211081467 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | S8V2B060M4PDA | 26,200 | $1,310 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210692105 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | S8V2B060M4PCA | 26,200 | $1,310 |
| No | 211081466 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | S8V2A040M3PDA | 25,000 | $1,250 |
| No | 210692107 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | S8V2A040M3PCA | 25,000 | $1,250 |
| No | 210653145 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | L8V1B080U4VSA+RP | 26,400 | $1,320 |
| No | 210653144 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | L8V1A060U3VSA+RP | 25,000 | $1,250 |
| No | 210653143 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | L8V1A040U3VSA+RP | 24,800 | $1,240 |
| No | 207590791 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | *UHMB080ACV3 | 25,800 | $1,290 |
| No | 207590792 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | *UHMB060ACV3 | 26,000 | $1,300 |
| No | 207590790 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | *UD2B080ACV3 | 25,600 | $1,280 |
| No | 207590793 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | *UD2B060ACV3 | 25,800 | $1,290 |
| No | 210653149 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | *DHMB080ACV3 | 25,400 | $1,270 |
| No | 211597783 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | *DD2B080ACV3 | 25,600 | $1,280 |
| No | 211597782 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | *DD2B060ACV3 | 25,800 | $1,290 |
| No | 210641217 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | *DD2B060A9V3+RP | 25,600 | $1,280 |
| No | 210641214 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*DU48BS3 | *DD2D120A9V5+RP | 25,200 | $1,260 |
| No | 207590183 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU48BS3 | S9V2C100U4VSA+RP | 26,000 | $1,300 |
| No | 210653141 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU48BS3 | S9V2C100U4PSB+RP | 26,000 | $1,300 |
| No | 210653140 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU48BS3 | S9V2C100D4VSA+RP | 25,400 | $1,270 |
| No | 207590234 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU48BS3 | S9V2C100D4PSB+RP | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211081465 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU48BS3 | S8V2C100M5PDA | 26,400 | $1,320 |
| No | 210692103 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU48BS3 | S8V2C100M5PCA | 26,400 | $1,320 |
| No | 211081464 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU48BS3 | S8V2C080M5PDA | 26,200 | $1,310 |
| No | 210692104 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU48BS3 | S8V2C080M5PCA | 26,200 | $1,310 |
| No | 210641212 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU48BS3 | *UD2C100B9V5+RP | 26,000 | $1,300 |
| No | 207590771 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU48BS3 | *UD2C100ACV5 | 26,400 | $1,320 |
| No | 210641211 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU48BS3 | *UD2C100A9V5+RP | 26,200 | $1,310 |
| No | 210641210 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU48BS3 | *UD2C080B9V4+RP | 26,000 | $1,300 |
| No | 207590768 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU48BS3 | *UD2C080ACV4 | 26,000 | $1,300 |
| No | 210641209 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU48BS3 | *UD2C080A9V4+RP | 26,000 | $1,300 |
| No | 210653142 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU48BS3 | *DHMC100ACV4 | 25,800 | $1,290 |
| No | 207590233 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU48BS3 | *DD2C100ACV5 | 25,400 | $1,270 |
| No | 210641213 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU48BS3 | *DD2C100A9V5+RP | 25,400 | $1,270 |
| No | 210653138 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU42BS3 | S9V2C100U4VSA+RP | 26,200 | $1,310 |
| No | 210653137 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU42BS3 | S9V2C100U4PSB+RP | 26,200 | $1,310 |
| No | 210653139 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU42BS3 | S9V2C100D4VSA+RP | 25,600 | $1,280 |
| No | 210653136 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU42BS3 | S9V2C100D4PSB+RP | 25,600 | $1,280 |
| No | 211081463 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU42BS3 | S8V2C100M5PDA | 26,600 | $1,330 |
| No | 210692102 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU42BS3 | S8V2C100M5PCA | 26,600 | $1,330 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211081462 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU42BS3 | S8V2C080M5PDA | 26,400 | $1,320 |
| No | 210692101 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU42BS3 | S8V2C080M5PCA | 26,400 | $1,320 |
| No | 210641207 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU42BS3 | *UD2C100B9V5+RP | 26,200 | $1,310 |
| No | 211289088 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU42BS3 | *UD2C100ACV5 | 26,600 | $1,330 |
| No | 210641206 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU42BS3 | *UD2C100A9V5+RP | 26,400 | $1,320 |
| No | 210641205 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU42BS3 | *UD2C080B9V4+RP | 26,200 | $1,310 |
| No | 211597781 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU42BS3 | *UD2C080ACV4 | 26,200 | $1,310 |
| No | 210641204 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU42BS3 | *UD2C080A9V4+RP | 26,200 | $1,310 |
| No | 207590268 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU42BS3 | *DHMC100ACV4 | 25,800 | $1,290 |
| No | 207590267 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU42BS3 | *DD2C100ACV5 | 25,600 | $1,280 |
| No | 210641208 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU42BS3 | *DD2C100A9V5+RP | 25,400 | $1,270 |
| No | 207590182 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU36BS3 | S9V2C100U4VSA+RP | 25,800 | $1,290 |
| No | 210653135 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU36BS3 | S9V2C100U4PSB+RP | 25,600 | $1,280 |
| No | 211081461 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU36BS3 | S8V2C100M5PDA | 26,200 | $1,310 |
| No | 210692099 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU36BS3 | S8V2C100M5PCA | 26,200 | $1,310 |
| No | 211081460 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU36BS3 | S8V2C080M5PDA | 25,800 | $1,290 |
| No | 210692100 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU36BS3 | S8V2C080M5PCA | 25,800 | $1,290 |
| No | 210641203 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU36BS3 | *UD2C100B9V5+RP | 25,600 | $1,280 |
| No | 207590767 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU36BS3 | *UD2C100ACV5 | 26,000 | $1,300 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210641202 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU36BS3 | *UD2C100A9V5+RP | 26,000 | $1,300 |
| No | 210641201 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU36BS3 | *UD2C080B9V4+RP | 25,800 | $1,290 |
| No | 207590766 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU36BS3 | *UD2C080ACV4 | 25,600 | $1,280 |
| No | 210641200 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU36BS3 | *UD2C080A9V4+RP | 25,800 | $1,290 |
| No | 207590262 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CD42BS3 | S9V2C100D4PSB+RP | 25,600 | $1,280 |
| No | 207590263 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CD42BS3 | *DD2C100ACV5 | 25,600 | $1,280 |
| No | 207590180 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CD36BS3 | S9V2C100D4VSA+RP | 26,400 | $1,320 |
| No | 210653129 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU48BS3 | S9V2B080D4VSA+RP | 25,600 | $1,280 |
| No | 207590229 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU48BS3 | S9V2B080D4PSB+RP | 25,600 | $1,280 |
| No | 210653130 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU48BS3 | S9V2B080D3VSA+RP | 25,400 | $1,270 |
| No | 207590230 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU48BS3 | S9V2B080D3PSB+RP | 25,400 | $1,270 |
| No | 207590231 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU48BS3 | S9V2B060D3PSB+RP | 25,600 | $1,280 |
| No | 210653128 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU48BS3 | S9V2B040D3PSB+RP | 25,800 | $1,290 |
| No | 210653131 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU48BS3 | *DHMB080ACV3 | 25,400 | $1,270 |
| No | 207590227 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU48BS3 | *DD2B080ACV3 | 25,600 | $1,280 |
| No | 210641188 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU48BS3 | *DD2B080A9V3+RP | 25,400 | $1,270 |
| No | 211597778 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU48BS3 | *DD2B060ACV3 | 26,000 | $1,300 |
| No | 210641189 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU48BS3 | *DD2B060A9V3+RP | 25,200 | $1,260 |
| No | 210653124 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU42BS3 | S9V2B080U4VSA+RP | 26,400 | $1,320 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207590484 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU42BS3 | S9V2B080U4PSB+RP | 26,400 | $1,320 |
| No | 210653122 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU42BS3 | S9V2B060U3VSA+RP | 26,400 | $1,320 |
| No | 210653121 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU42BS3 | S9V2B060U3PSB+RP | 26,400 | $1,320 |
| No | 210653120 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU42BS3 | S9V2B040U3VSA+RP | 26,400 | $1,320 |
| No | 210653119 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU42BS3 | S9V2B040U3PSB+RP | 26,400 | $1,320 |
| No | 211081455 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU42BS3 | S8V2B080M4PDA | 26,800 | $1,340 |
| No | 210692094 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU42BS3 | S8V2B080M4PCA | 26,800 | $1,340 |
| No | 211081454 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU42BS3 | S8V2B060M4PDA | 26,800 | $1,340 |
| No | 210692093 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU42BS3 | S8V2B060M4PCA | 26,800 | $1,340 |
| No | 210653123 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU42BS3 | L8V1B080U4VSA+RP | 26,800 | $1,340 |
| No | 210653127 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU42BS3 | L8V1A060U3VSA+RP | 25,600 | $1,280 |
| No | 210653125 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU42BS3 | *UHMB080ACV3 | 26,400 | $1,320 |
| No | 210653118 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU42BS3 | *UHMB060ACV3 | 26,400 | $1,320 |
| No | 211597777 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU42BS3 | *UD2B080ACV3 | 26,400 | $1,320 |
| No | 211597776 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU42BS3 | *UD2B060ACV3 | 26,400 | $1,320 |
| No | 210641187 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU42BS3 | *UD2B060A9V3+RP | 26,400 | $1,320 |
| No | 210653112 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | S9V2B080U4VSA+RP | 26,000 | $1,300 |
| No | 210653109 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | S9V2B080U4PSB+RP | 26,000 | $1,300 |
| No | 207590226 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | S9V2B080D3PSB+RP | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207590176 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | S9V2B060U3VSA+RP | 26,000 | $1,300 |
| No | 210653110 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | S9V2B060U3PSB+RP | 26,000 | $1,300 |
| No | 207590225 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | S9V2B060D3PSB+RP | 25,400 | $1,270 |
| No | 207590174 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | S9V2B040U3VSA+RP | 26,000 | $1,300 |
| No | 210653111 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | S9V2B040U3PSB+RP | 26,000 | $1,300 |
| No | 207590261 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | S9V2B040D3PSB+RP | 25,600 | $1,280 |
| No | 211081452 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | S8V2B080M4PDA | 26,400 | $1,320 |
| No | 210692091 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | S8V2B080M4PCA | 26,400 | $1,320 |
| No | 211081451 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | S8V2B060M4PDA | 26,400 | $1,320 |
| No | 210692089 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | S8V2B060M4PCA | 26,400 | $1,320 |
| No | 211081450 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | S8V2A040M3PDA | 25,000 | $1,250 |
| No | 210692090 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | S8V2A040M3PCA | 25,000 | $1,250 |
| No | 210653108 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | L8V1B080U4VSA+RP | 26,400 | $1,320 |
| No | 210653113 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | L8V1A060U3VSA+RP | 25,000 | $1,250 |
| No | 207590752 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | *UHMB080ACV3 | 26,000 | $1,300 |
| No | 207590755 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | *UHMB060ACV3 | 26,000 | $1,300 |
| No | 207590754 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | *UD2B080ACV3 | 25,800 | $1,290 |
| No | 207590753 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | *UD2B060ACV3 | 25,800 | $1,290 |
| No | 210653107 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | *DHMB080ACV3 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211597775 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | *DD2B080ACV3 | 25,400 | $1,270 |
| No | 210641183 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | *DD2B080A9V3+RP | 25,600 | $1,280 |
| No | 211597774 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | *DD2B060ACV3 | 25,800 | $1,290 |
| No | 210641182 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | *DD2B060A9V3+RP | 25,600 | $1,280 |
| No | 207590259 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BD42BS3 | S9V2B080D4PSB+RP | 26,000 | $1,300 |
| No | 207590260 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BD42BS3 | S9V2B080D3PSB+RP | 25,800 | $1,290 |
| No | 207590258 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BD42BS3 | S9V2B060D3PSB+RP | 25,800 | $1,290 |
| No | 207590256 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BD42BS3 | S9V2B040D3PSB+RP | 26,000 | $1,300 |
| No | 207590257 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BD42BS3 | *DD2B080ACV3 | 25,800 | $1,290 |
| No | 207590610 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BD42BS3 | *DD2B060ACV3 | 26,000 | $1,300 |
| No | 211597770 | AMERICAN STANDARD | 4A6V8X24A1 | TEM8A0B24V21+TDR | N/A | 17,600 | $880 |
| No | 211015541 | AMERICAN STANDARD | 4A6V8X24A1 | TAMXB0B30V31 | N/A | 17,100 | $855 |
| No | 207590045 | AMERICAN STANDARD | 4A6V8X24A1 | TAM9A0B30V31 | N/A | 17,100 | $855 |
| No | 207590735 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXFH024CZ3 | *DHMB080ACV3 | 16,800 | $840 |
| No | 207590731 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXFH024CZ3 | *DHMB060BCV3 | 16,800 | $840 |
| No | 207590730 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXFH024CZ3 | *DD2B060ACV3 | 16,800 | $840 |
| No | 211092944 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXCB004DS3 | S8V2B080M4PDA | 17,100 | $855 |
| No | 211092914 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXCB004DS3 | S8V2B080M4PCA | 17,100 | $855 |
| No | 211081444 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXCB004DS3 | S8V2B060M4PDA | 17,100 | $855 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210692083 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXCB004DS3 | S8V2B060M4PCA | 17,100 | $855 |
| No | 211092945 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXCB004DS3 | S8V2A040M3PDA | 16,300 | $815 |
| No | 211092915 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXCB004DS3 | S8V2A040M3PCA | 16,300 | $815 |
| No | 210653102 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXCB004DS3 | L8V1B080U4VSA+RP | 17,000 | $850 |
| No | 210653101 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXCB004DS3 | L8V1A040U3VSA+RP | 16,600 | $830 |
| No | 211597769 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXCB004DS3 | *UHMB080ACV3 | 16,800 | $840 |
| No | 210641175 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXCB004DS3 | *UD2B080A9V3+RP | 16,900 | $845 |
| No | 210641174 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXCB004DS3 | *UD2B060A9V3+RP | 17,000 | $850 |
| No | 210653098 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXCB003DS3 | S9V2B040U3VSA+RP | 17,900 | $895 |
| No | 210653097 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXCB003DS3 | S9V2B040U3PSB+RP | 17,900 | $895 |
| No | 211081443 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXCB003DS3 | S8V2B080M4PDA | 18,000 | $900 |
| No | 210692081 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXCB003DS3 | S8V2B080M4PCA | 18,000 | $900 |
| No | 211081442 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXCB003DS3 | S8V2B060M4PDA | 17,900 | $895 |
| No | 210692080 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXCB003DS3 | S8V2B060M4PCA | 17,900 | $895 |
| No | 210653093 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXCB003DS3 | *UHMB080ACV3 | 17,700 | $885 |
| No | 210653088 | AMERICAN STANDARD | 4A6V8X24A1 | 4PX*BU36BS3 | S9V2B080D3PSB+RP | 16,700 | $835 |
| No | 211597767 | AMERICAN STANDARD | 4A6V8X24A1 | 4PX*BU36BS3 | S9V2B060U3PSB+RP | 16,900 | $845 |
| No | 207590106 | AMERICAN STANDARD | 4A6V8X24A1 | 4PX*BU36BS3 | S9V2B040U3PSB+RP | 17,000 | $850 |
| No | 211092943 | AMERICAN STANDARD | 4A6V8X24A1 | 4PX*BU36BS3 | S8V2B080M4PDA | 17,100 | $855 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211092912 | AMERICAN STANDARD | 4A6V8X24A1 | 4PX*BU36BS3 | S8V2B080M4PCA | 17,100 | $855 |
| No | 211092941 | AMERICAN STANDARD | 4A6V8X24A1 | 4PX*BU36BS3 | S8V2A040M3PDA | 16,300 | $815 |
| No | 211092913 | AMERICAN STANDARD | 4A6V8X24A1 | 4PX*BU36BS3 | S8V2A040M3PCA | 16,300 | $815 |
| No | 210653089 | AMERICAN STANDARD | 4A6V8X24A1 | 4PX*BU36BS3 | L8V1B080U4VSA+RP | 17,000 | $850 |
| No | 210653087 | AMERICAN STANDARD | 4A6V8X24A1 | 4PX*BU36BS3 | L8V1A060U3VSA+RP | 16,500 | $825 |
| No | 207590745 | AMERICAN STANDARD | 4A6V8X24A1 | 4PX*BU36BS3 | *UHMB080ACV3 | 16,800 | $840 |
| No | 210641171 | AMERICAN STANDARD | 4A6V8X24A1 | 4PX*BU36BS3 | *UD2B080A9V3+RP | 16,900 | $845 |
| No | 210641172 | AMERICAN STANDARD | 4A6V8X24A1 | 4PX*BU36BS3 | *UD2B060A9V3+RP | 17,000 | $850 |
| No | 207820993 | AMERICAN STANDARD | 4A6V0X60A1 | TEM8B0C60V51+TDR | N/A | 48,500 | $2,425 |
| No | 207590064 | AMERICAN STANDARD | 4A6V0X60A1 | TEM8A0D60V51+TDR | N/A | 48,000 | $2,400 |
| No | 207590063 | AMERICAN STANDARD | 4A6V0X60A1 | TEM8A0D48V41+TDR | N/A | 48,500 | $2,425 |
| No | 207709026 | AMERICAN STANDARD | 4A6V0X60A1 | TEM8A0C48V41+TDR | N/A | 48,500 | $2,425 |
| No | 211081440 | AMERICAN STANDARD | 4A6V0X60A1 | 4TXCD010DS3 | S8V2D120M5PDA | 49,500 | $2,475 |
| No | 210692079 | AMERICAN STANDARD | 4A6V0X60A1 | 4TXCD010DS3 | S8V2D120M5PCA | 49,500 | $2,475 |
| No | 211081436 | AMERICAN STANDARD | 4A6V0X60A1 | 4PX*DU60BS3 | S8V2D120M5PDA | 49,500 | $2,475 |
| No | 210692076 | AMERICAN STANDARD | 4A6V0X60A1 | 4PX*DU60BS3 | S8V2D120M5PCA | 49,500 | $2,475 |
| No | 207820991 | AMERICAN STANDARD | 4A6V0X48A1 | TEM8B0C60V51+TDR | N/A | 36,000 | $1,800 |
| No | 207590061 | AMERICAN STANDARD | 4A6V0X48A1 | TEM8A0D60V51+TDR | N/A | 35,800 | $1,790 |
| No | 207590060 | AMERICAN STANDARD | 4A6V0X48A1 | TEM8A0D48V41+TDR | N/A | 36,200 | $1,810 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207590058 | AMERICAN STANDARD | 4A6V0X48A1 | TEM8A0C48V41+TDR | N/A | 36,000 | $1,800 |
| No | 207590057 | AMERICAN STANDARD | 4A6V0X48A1 | TEM8A0C42V41+TDR | N/A | 36,000 | $1,800 |
| No | 210929579 | AMERICAN STANDARD | 4A6V0X48A1 | TAMXB0C60V51 | N/A | 35,200 | $1,760 |
| No | 210929578 | AMERICAN STANDARD | 4A6V0X48A1 | TAMXB0C48V41 | N/A | 35,200 | $1,760 |
| No | 207690051 | AMERICAN STANDARD | 4A6V0X48A1 | TAMXA0C60V51 | N/A | 35,200 | $1,760 |
| No | 207590043 | AMERICAN STANDARD | 4A6V0X48A1 | TAM9A0C60V51 | N/A | 35,200 | $1,760 |
| No | 207590042 | AMERICAN STANDARD | 4A6V0X48A1 | TAM9A0C48V41 | N/A | 35,200 | $1,760 |
| No | 207590271 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXFH064AZ3 | *UD2C080ACV4 | 35,800 | $1,790 |
| No | 207805669 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCD010DS3+P0V0D000M50SC+RP | N/A | 35,800 | $1,790 |
| No | 207805668 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCD010DS3+P0V0C000M50SC+RP | N/A | 34,800 | $1,740 |
| No | 207590159 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCD010DS3 | S9V2D120U5VSA+RP | 36,200 | $1,810 |
| No | 208185421 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCD010DS3 | S9V2D120U5PSB+RP | 36,200 | $1,810 |
| No | 210653895 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCD010DS3 | S9V2D120D5PSB+RP | 35,000 | $1,750 |
| No | 207590160 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCD010DS3 | S9V2C100U4VSA+RP | 35,200 | $1,760 |
| No | 211089196 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCD010DS3 | S8V2D120M5PDA | 36,400 | $1,820 |
| No | 210692237 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCD010DS3 | S8V2D120M5PCA | 36,400 | $1,820 |
| No | 207590690 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCD010DS3 | *UHMD120ACV5 | 35,800 | $1,790 |
| No | 211597765 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCD010DS3 | *UD2D120B9V5+RP | 36,200 | $1,810 |
| No | 207590706 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCD010DS3 | *UD2D120ACV5 | 36,400 | $1,820 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210641153 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCD010DS3 | *UD2D120A9V5+RP | 36,200 | $1,810 |
| No | 207805666 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCD008DS3+P0V0D000M50SC+RP | N/A | 36,200 | $1,810 |
| No | 210653061 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCD008DS3 | S9V2D120U5VSA+RP | 36,600 | $1,830 |
| No | 210653068 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCD008DS3 | S9V2D120U5PSB+RP | 36,600 | $1,830 |
| No | 211081432 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCD008DS3 | S8V2D120M5PDA | 36,800 | $1,840 |
| No | 210692071 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCD008DS3 | S8V2D120M5PCA | 36,800 | $1,840 |
| No | 207805665 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCC009DS3+P0V0C000M50SC+RP | N/A | 36,000 | $1,800 |
| No | 207782228 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCC009DS3 | S9V2C100U5PSB+RP | 36,400 | $1,820 |
| No | 207590157 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCC009DS3 | S9V2C100U4VSA+RP | 36,200 | $1,810 |
| No | 208185436 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCC009DS3 | S9V2C100U4PSB+RP | 36,200 | $1,810 |
| No | 210653893 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCC009DS3 | S9V2C100D5PSB+RP | 35,200 | $1,760 |
| No | 210653892 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCC009DS3 | S9V2C100D4VSA+RP | 35,200 | $1,760 |
| No | 210653891 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCC009DS3 | S9V2C100D4PSB+RP | 35,200 | $1,760 |
| No | 210653060 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCC009DS3 | S9V2C080U5PSB+RP | 36,400 | $1,820 |
| No | 211089192 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCC009DS3 | S8V2C100M5PDA | 36,600 | $1,830 |
| No | 210692234 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCC009DS3 | S8V2C100M5PCA | 36,600 | $1,830 |
| No | 208554519 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCC009DS3 | L8V1C100U5VSA+RP | 36,200 | $1,810 |
| No | 210641143 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCC009DS3 | *UD2C100B9V5+RP | 36,400 | $1,820 |
| No | 207590704 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCC009DS3 | *UD2C100ACV5 | 36,600 | $1,830 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210641142 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCC009DS3 | *UD2C080B9V4+RP | 36,000 | $1,800 |
| No | 207590686 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCC009DS3 | *UD2C080ACV4 | 36,000 | $1,800 |
| No | 210641141 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCC009DS3 | *UD2C080A9V4+RP | 36,600 | $1,830 |
| No | 207590705 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCC009DS3 | *DHMC100ACV4 | 35,000 | $1,750 |
| No | 207805664 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCC007DS3+P0V0C000M50SC+RP | N/A | 36,400 | $1,820 |
| No | 207590102 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCC007DS3 | S9V2C100D5PSB+RP | 36,000 | $1,800 |
| No | 207805661 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DU60BS3+P0V0D000M50SC+RP | N/A | 35,800 | $1,790 |
| No | 207805662 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DU60BS3+P0V0C000M50SC+RP | N/A | 34,800 | $1,740 |
| No | 207590154 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DU60BS3 | S9V2D120U5VSA+RP | 36,200 | $1,810 |
| No | 210653051 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DU60BS3 | S9V2D120U5PSB+RP | 36,200 | $1,810 |
| No | 207590153 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DU60BS3 | S9V2C100U4VSA+RP | 35,200 | $1,760 |
| No | 211089189 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DU60BS3 | S8V2D120M5PDA | 36,400 | $1,820 |
| No | 210692230 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DU60BS3 | S8V2D120M5PCA | 36,400 | $1,820 |
| No | 207590671 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DU60BS3 | *UHMD120ACV5 | 35,800 | $1,790 |
| No | 211597762 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DU60BS3 | *UD2D120B9V5+RP | 36,200 | $1,810 |
| No | 207590703 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DU60BS3 | *UD2D120ACV5 | 36,400 | $1,820 |
| No | 210641132 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DU60BS3 | *UD2D120A9V5+RP | 36,200 | $1,810 |
| No | 207805659 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DU48BS3+P0V0D000M50SC+RP | N/A | 36,200 | $1,810 |
| No | 210653047 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DU48BS3 | S9V2D120U5VSA+RP | 36,600 | $1,830 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210653046 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DU48BS3 | S9V2D120U5PSB+RP | 36,600 | $1,830 |
| No | 207590223 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DU48BS3 | S9V2D120D5PSB+RP | 35,800 | $1,790 |
| No | 211081425 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DU48BS3 | S8V2D120M5PDA | 36,800 | $1,840 |
| No | 210692064 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DU48BS3 | S8V2D120M5PCA | 36,800 | $1,840 |
| No | 207805656 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DD60BS3+P0V0D000M50SC+RP | N/A | 35,800 | $1,790 |
| No | 207590152 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DD60BS3 | S9V2C100D4VSA+RP | 35,000 | $1,750 |
| No | 211089185 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DD60BS3 | S8V2D120M5PDA | 36,400 | $1,820 |
| No | 210692227 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DD60BS3 | S8V2D120M5PCA | 36,400 | $1,820 |
| No | 207590710 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DD60BS3 | *DD2D120ACV5 | 35,800 | $1,790 |
| No | 210641121 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DD60BS3 | *DD2D120A9V5+RP | 36,600 | $1,830 |
| No | 207805654 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CU60BS3+P0V0C000M50SC+RP | N/A | 36,000 | $1,800 |
| No | 207782225 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CU60BS3 | S9V2C100U5PSB+RP | 36,400 | $1,820 |
| No | 207590150 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CU60BS3 | S9V2C100U4VSA+RP | 36,200 | $1,810 |
| No | 210653037 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CU60BS3 | S9V2C100U4PSB+RP | 36,200 | $1,810 |
| No | 210653035 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CU60BS3 | S9V2C080U5PSB+RP | 36,400 | $1,820 |
| No | 211089183 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CU60BS3 | S8V2C100M5PDA | 36,600 | $1,830 |
| No | 210692225 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CU60BS3 | S8V2C100M5PCA | 36,600 | $1,830 |
| No | 210653036 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CU60BS3 | L8V1C100U5VSA+RP | 36,200 | $1,810 |
| No | 210641119 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CU60BS3 | *UD2C100B9V5+RP | 36,400 | $1,820 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207590702 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CU60BS3 | *UD2C100ACV5 | 36,600 | $1,830 |
| No | 210641118 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CU60BS3 | *UD2C080B9V4+RP | 36,000 | $1,800 |
| No | 207590669 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CU60BS3 | *UD2C080ACV4 | 36,000 | $1,800 |
| No | 207805653 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CU48BS3+P0V0C000M50SC+RP | N/A | 36,400 | $1,820 |
| No | 207590221 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CU48BS3 | S9V2C100D5PSB+RP | 36,000 | $1,800 |
| No | 207590220 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CU48BS3 | S9V2C100D4PSB+RP | 36,000 | $1,800 |
| No | 207590147 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CD60BS3 | S9V2C100D4VSA+RP | 36,200 | $1,810 |
| No | 207590054 | AMERICAN STANDARD | 4A6V0X36A1 | TEM8A0C42V41+TDR | N/A | 26,400 | $1,320 |
| No | 207590053 | AMERICAN STANDARD | 4A6V0X36A1 | TEM8A0C36V31+TDR | N/A | 26,400 | $1,320 |
| No | 207590052 | AMERICAN STANDARD | 4A6V0X36A1 | TEM8A0B30V31+TDR | N/A | 27,000 | $1,350 |
| No | 210929576 | AMERICAN STANDARD | 4A6V0X36A1 | TAMXB0C36V31 | N/A | 26,000 | $1,300 |
| No | 210929575 | AMERICAN STANDARD | 4A6V0X36A1 | TAMXB0B30V31 | N/A | 26,400 | $1,320 |
| No | 207690059 | AMERICAN STANDARD | 4A6V0X36A1 | TAMXA0B30V31 | N/A | 26,400 | $1,320 |
| No | 207590040 | AMERICAN STANDARD | 4A6V0X36A1 | TAM9A0C36V31 | N/A | 26,000 | $1,300 |
| No | 207590718 | AMERICAN STANDARD | 4A6V0X36A1 | TAM9A0B30V31 | N/A | 26,400 | $1,320 |
| No | 207590145 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCC005DS3 | S9V2C100U4VSA+RP | 26,000 | $1,300 |
| No | 208185434 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCC005DS3 | S9V2C100U4PSB+RP | 25,800 | $1,290 |
| No | 207590144 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCC005DS3 | S9V2C100D4VSA+RP | 25,400 | $1,270 |
| No | 210653015 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCC005DS3 | S9V2C100D4PSB+RP | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211081417 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCC005DS3 | S8V2C100M5PDA | 26,600 | $1,330 |
| No | 210692055 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCC005DS3 | S8V2C100M5PCA | 26,600 | $1,330 |
| No | 210641094 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCC005DS3 | *UD2C100B9V5+RP | 25,800 | $1,290 |
| No | 207590683 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCC005DS3 | *UD2C100ACV5 | 26,800 | $1,340 |
| No | 210641095 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCC005DS3 | *UD2C100A9V5+RP | 26,000 | $1,300 |
| No | 210641096 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCC005DS3 | *UD2C080B9V4+RP | 26,000 | $1,300 |
| No | 207590682 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCC005DS3 | *UD2C080ACV4 | 26,000 | $1,300 |
| No | 210641093 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCC005DS3 | *UD2C080A9V4+RP | 26,000 | $1,300 |
| No | 210653016 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCC005DS3 | *DHMC100ACV4 | 25,800 | $1,290 |
| No | 211597755 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCC005DS3 | *DD2C100ACV5 | 25,400 | $1,270 |
| No | 209326025 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCB004DS3 | S9V2B080U4VSA+RP | 26,000 | $1,300 |
| No | 208185432 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCB004DS3 | S9V2B080U4PSB+RP | 26,000 | $1,300 |
| No | 207590138 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCB004DS3 | S9V2B060U3VSA+RP | 26,000 | $1,300 |
| No | 208185430 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCB004DS3 | S9V2B060U3PSB+RP | 26,000 | $1,300 |
| No | 207590137 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCB004DS3 | S9V2B040U3VSA+RP | 26,200 | $1,310 |
| No | 208185431 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCB004DS3 | S9V2B040U3PSB+RP | 26,200 | $1,310 |
| No | 211081413 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCB004DS3 | S8V2B080M4PDA | 26,600 | $1,330 |
| No | 210692054 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCB004DS3 | S8V2B080M4PCA | 26,600 | $1,330 |
| No | 211081414 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCB004DS3 | S8V2B060M4PDA | 26,800 | $1,340 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210692053 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCB004DS3 | S8V2B060M4PCA | 26,800 | $1,340 |
| No | 207590676 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCB004DS3 | *UHMB080ACV3 | 26,400 | $1,320 |
| No | 207590677 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCB004DS3 | *UHMB060ACV3 | 26,000 | $1,300 |
| No | 207590678 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCB004DS3 | *UD2B080ACV3 | 25,600 | $1,280 |
| No | 207590679 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCB004DS3 | *UD2B060ACV3 | 25,800 | $1,290 |
| No | 211597754 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCB004DS3 | *DD2B080ACV3 | 25,600 | $1,280 |
| No | 211597753 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCB004DS3 | *DD2B060ACV3 | 26,000 | $1,300 |
| No | 210641087 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*DU48BS3 | *DD2D120A9V5+RP | 25,600 | $1,280 |
| No | 207590136 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU48BS3 | S9V2C100U4VSA+RP | 26,200 | $1,310 |
| No | 207590099 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU48BS3 | S9V2C100U4PSB+RP | 26,200 | $1,310 |
| No | 210653006 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU48BS3 | S9V2C100D4VSA+RP | 25,600 | $1,280 |
| No | 207590254 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU48BS3 | S9V2C100D4PSB+RP | 25,600 | $1,280 |
| No | 211081411 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU48BS3 | S8V2C100M5PDA | 26,800 | $1,340 |
| No | 210692050 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU48BS3 | S8V2C100M5PCA | 26,800 | $1,340 |
| No | 211081412 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU48BS3 | S8V2C080M5PDA | 26,600 | $1,330 |
| No | 210692051 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU48BS3 | S8V2C080M5PCA | 26,600 | $1,330 |
| No | 210641082 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU48BS3 | *UD2C100B9V5+RP | 26,200 | $1,310 |
| No | 207590662 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU48BS3 | *UD2C100ACV5 | 26,800 | $1,340 |
| No | 210641083 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU48BS3 | *UD2C100A9V5+RP | 26,400 | $1,320 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210641084 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU48BS3 | *UD2C080B9V4+RP | 26,200 | $1,310 |
| No | 207590661 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU48BS3 | *UD2C080ACV4 | 26,400 | $1,320 |
| No | 210641085 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU48BS3 | *UD2C080A9V4+RP | 26,200 | $1,310 |
| No | 210653005 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU48BS3 | *DHMC100ACV4 | 26,000 | $1,300 |
| No | 211597752 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU48BS3 | *DD2C100ACV5 | 25,400 | $1,270 |
| No | 210641086 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU48BS3 | *DD2C100A9V5+RP | 25,400 | $1,270 |
| No | 210653002 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU42BS3 | S9V2C100U4VSA+RP | 26,400 | $1,320 |
| No | 210653001 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU42BS3 | S9V2C100U4PSB+RP | 26,400 | $1,320 |
| No | 211081410 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU42BS3 | S8V2C100M5PDA | 27,000 | $1,350 |
| No | 210692048 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU42BS3 | S8V2C100M5PCA | 27,000 | $1,350 |
| No | 211081409 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU42BS3 | S8V2C080M5PDA | 26,800 | $1,340 |
| No | 210692049 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU42BS3 | S8V2C080M5PCA | 26,800 | $1,340 |
| No | 210641081 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU42BS3 | *UD2C100B9V5+RP | 26,400 | $1,320 |
| No | 211289072 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU42BS3 | *UD2C100ACV5 | 27,000 | $1,350 |
| No | 210641079 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU42BS3 | *UD2C100A9V5+RP | 26,600 | $1,330 |
| No | 210641080 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU42BS3 | *UD2C080B9V4+RP | 26,400 | $1,320 |
| No | 211597751 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU42BS3 | *UD2C080ACV4 | 26,600 | $1,330 |
| No | 210641077 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU42BS3 | *UD2C080A9V4+RP | 26,400 | $1,320 |
| No | 207590266 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU42BS3 | *DHMC100ACV4 | 26,200 | $1,310 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207590265 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU42BS3 | *DD2C100ACV5 | 25,600 | $1,280 |
| No | 210641078 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU42BS3 | *DD2C100A9V5+RP | 26,000 | $1,300 |
| No | 207590135 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU36BS3 | S9V2C100U4VSA+RP | 25,800 | $1,290 |
| No | 210653000 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU36BS3 | S9V2C100U4PSB+RP | 25,800 | $1,290 |
| No | 211081407 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU36BS3 | S8V2C100M5PDA | 26,400 | $1,320 |
| No | 210692046 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU36BS3 | S8V2C100M5PCA | 26,400 | $1,320 |
| No | 211081408 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU36BS3 | S8V2C080M5PDA | 26,400 | $1,320 |
| No | 210692047 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU36BS3 | S8V2C080M5PCA | 26,400 | $1,320 |
| No | 210641073 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU36BS3 | *UD2C100B9V5+RP | 25,800 | $1,290 |
| No | 207590658 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU36BS3 | *UD2C100ACV5 | 26,400 | $1,320 |
| No | 210641074 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU36BS3 | *UD2C100A9V5+RP | 26,000 | $1,300 |
| No | 210641076 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU36BS3 | *UD2C080B9V4+RP | 25,800 | $1,290 |
| No | 207590660 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU36BS3 | *UD2C080ACV4 | 26,000 | $1,300 |
| No | 210641075 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU36BS3 | *UD2C080A9V4+RP | 26,000 | $1,300 |
| No | 207590252 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CD42BS3 | S9V2C100D4PSB+RP | 25,800 | $1,290 |
| No | 207590133 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CD36BS3 | S9V2C100D4VSA+RP | 26,600 | $1,330 |
| No | 207590097 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CD36BS3 | S9V2C100D4PSB+RP | 26,600 | $1,330 |
| No | 210652997 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU48BS3 | S9V2B080D4VSA+RP | 25,600 | $1,280 |
| No | 207590249 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU48BS3 | S9V2B080D4PSB+RP | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210652995 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU48BS3 | S9V2B080D3VSA+RP | 25,600 | $1,280 |
| No | 207590250 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU48BS3 | S9V2B080D3PSB+RP | 25,600 | $1,280 |
| No | 207590251 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU48BS3 | S9V2B060D3PSB+RP | 25,600 | $1,280 |
| No | 207590248 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU48BS3 | S9V2B040D3PSB+RP | 25,800 | $1,290 |
| No | 210652996 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU48BS3 | *DHMB080ACV3 | 25,400 | $1,270 |
| No | 207590247 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU48BS3 | *DD2B080ACV3 | 26,000 | $1,300 |
| No | 210641061 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU48BS3 | *DD2B080A9V3+RP | 25,400 | $1,270 |
| No | 211597748 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU48BS3 | *DD2B060ACV3 | 26,400 | $1,320 |
| No | 210641062 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU48BS3 | *DD2B060A9V3+RP | 25,800 | $1,290 |
| No | 210652986 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU42BS3 | S9V2B080U4VSA+RP | 26,600 | $1,330 |
| No | 210652987 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU42BS3 | S9V2B080U4PSB+RP | 26,600 | $1,330 |
| No | 210652988 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU42BS3 | S9V2B060U3VSA+RP | 26,600 | $1,330 |
| No | 210652989 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU42BS3 | S9V2B060U3PSB+RP | 26,600 | $1,330 |
| No | 210652990 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU42BS3 | S9V2B040U3VSA+RP | 26,600 | $1,330 |
| No | 210652991 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU42BS3 | S9V2B040U3PSB+RP | 26,600 | $1,330 |
| No | 211081400 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU42BS3 | S8V2B080M4PDA | 27,400 | $1,370 |
| No | 210692041 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU42BS3 | S8V2B080M4PCA | 27,400 | $1,370 |
| No | 211081401 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU42BS3 | S8V2B060M4PDA | 27,200 | $1,360 |
| No | 210692039 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU42BS3 | S8V2B060M4PCA | 27,200 | $1,360 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210652992 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU42BS3 | L8V1B080U4VSA+RP | 27,200 | $1,360 |
| No | 210652985 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU42BS3 | *UHMB080ACV3 | 26,800 | $1,340 |
| No | 210652984 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU42BS3 | *UHMB060ACV3 | 26,600 | $1,330 |
| No | 211597747 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU42BS3 | *UD2B080ACV3 | 26,400 | $1,320 |
| No | 211597746 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU42BS3 | *UD2B060ACV3 | 26,600 | $1,330 |
| No | 210641059 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU42BS3 | *UD2B060A9V3+RP | 26,600 | $1,330 |
| No | 207590621 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU36BS3 | S9V2B080U4VSA+RP | 26,000 | $1,300 |
| No | 210610549 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU36BS3 | S9V2B080U4PSB+RP | 26,000 | $1,300 |
| No | 207590127 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU36BS3 | S9V2B060U3VSA+RP | 26,000 | $1,300 |
| No | 210652977 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU36BS3 | S9V2B060U3PSB+RP | 26,000 | $1,300 |
| No | 207590129 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU36BS3 | S9V2B040U3VSA+RP | 26,200 | $1,310 |
| No | 210652976 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU36BS3 | S9V2B040U3PSB+RP | 26,200 | $1,310 |
| No | 211081397 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU36BS3 | S8V2B080M4PDA | 26,800 | $1,340 |
| No | 210692038 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU36BS3 | S8V2B080M4PCA | 26,800 | $1,340 |
| No | 211081398 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU36BS3 | S8V2B060M4PDA | 26,800 | $1,340 |
| No | 210692037 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU36BS3 | S8V2B060M4PCA | 26,800 | $1,340 |
| No | 207590648 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU36BS3 | *UHMB080ACV3 | 26,400 | $1,320 |
| No | 207590651 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU36BS3 | *UHMB060ACV3 | 26,200 | $1,310 |
| No | 207590649 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU36BS3 | *UD2B080ACV3 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207590650 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU36BS3 | *UD2B060ACV3 | 25,600 | $1,280 |
| No | 211597744 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU36BS3 | *DD2B080ACV3 | 25,600 | $1,280 |
| No | 211597745 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU36BS3 | *DD2B060ACV3 | 26,000 | $1,300 |
| No | 207590246 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BD42BS3 | S9V2B080D4PSB+RP | 25,800 | $1,290 |
| No | 207590245 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BD42BS3 | S9V2B080D3PSB+RP | 25,800 | $1,290 |
| No | 207590244 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BD42BS3 | S9V2B060D3PSB+RP | 25,800 | $1,290 |
| No | 207590242 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BD42BS3 | S9V2B040D3PSB+RP | 26,000 | $1,300 |
| No | 207590243 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BD42BS3 | *DD2B080ACV3 | 26,000 | $1,300 |
| No | 207590087 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BD36BS3 | S9V2B080D4PSB+RP | 26,800 | $1,340 |
| No | 207590051 | AMERICAN STANDARD | 4A6V0X24A1 | TEM8A0B30V31+TDR | N/A | 17,600 | $880 |
| No | 210636934 | AMERICAN STANDARD | 4A6V0X24A1 | TEM8A0B24V21+TDR | N/A | 17,600 | $880 |
| No | 210929574 | AMERICAN STANDARD | 4A6V0X24A1 | TAMXB0B30V31 | N/A | 17,100 | $855 |
| No | 207590039 | AMERICAN STANDARD | 4A6V0X24A1 | TAM9A0B30V31 | N/A | 17,100 | $855 |
| No | 207590632 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXFH024CZ3 | *DHMB080ACV3 | 16,800 | $840 |
| No | 207590629 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXFH024CZ3 | *DHMB060BCV3 | 16,800 | $840 |
| No | 207590628 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXFH024CZ3 | *DD2B060ACV3 | 16,800 | $840 |
| No | 211089176 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXCB004DS3 | S8V2B080M4PDA | 17,200 | $860 |
| No | 210692217 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXCB004DS3 | S8V2B080M4PCA | 17,200 | $860 |
| No | 211081391 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXCB004DS3 | S8V2A040M3PDA | 16,400 | $820 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210692030 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXCB004DS3 | S8V2A040M3PCA | 16,400 | $820 |
| No | 210652969 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXCB004DS3 | L8V1A060U3VSA+RP | 16,500 | $825 |
| No | 210652968 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXCB004DS3 | L8V1A040U3VSA+RP | 16,600 | $830 |
| No | 210288156 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXCB004DS3 | *UHMB060ACV3 | 16,800 | $840 |
| No | 210641046 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXCB004DS3 | *UD2B080A9V3+RP | 16,900 | $845 |
| No | 210641047 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXCB004DS3 | *UD2B060A9V3+RP | 16,700 | $835 |
| No | 210652959 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXCB003DS3 | S9V2B040U3VSA+RP | 17,900 | $895 |
| No | 210652962 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXCB003DS3 | S9V2B040U3PSB+RP | 17,900 | $895 |
| No | 211081388 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXCB003DS3 | S8V2B080M4PDA | 18,000 | $900 |
| No | 210692027 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXCB003DS3 | S8V2B080M4PCA | 18,000 | $900 |
| No | 211081389 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXCB003DS3 | S8V2B060M4PDA | 17,900 | $895 |
| No | 210692029 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXCB003DS3 | S8V2B060M4PCA | 17,900 | $895 |
| No | 210652966 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXCB003DS3 | *UHMB080ACV3 | 17,700 | $885 |
| No | 207590119 | AMERICAN STANDARD | 4A6V0X24A1 | 4PX*BU36BS3 | S9V2B060U3VSA+RP | 16,900 | $845 |
| No | 207590118 | AMERICAN STANDARD | 4A6V0X24A1 | 4PX*BU36BS3 | S9V2B040U3VSA+RP | 17,000 | $850 |
| No | 207590082 | AMERICAN STANDARD | 4A6V0X24A1 | 4PX*BU36BS3 | S9V2B040U3PSB+RP | 17,000 | $850 |
| No | 211089174 | AMERICAN STANDARD | 4A6V0X24A1 | 4PX*BU36BS3 | S8V2B080M4PDA | 17,100 | $855 |
| No | 210692215 | AMERICAN STANDARD | 4A6V0X24A1 | 4PX*BU36BS3 | S8V2B080M4PCA | 17,100 | $855 |
| No | 211089175 | AMERICAN STANDARD | 4A6V0X24A1 | 4PX*BU36BS3 | S8V2B060M4PDA | 17,100 | $855 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210692216 | AMERICAN STANDARD | 4A6V0X24A1 | 4PX*BU36BS3 | S8V2B060M4PCA | 17,100 | $855 |
| No | 211081387 | AMERICAN STANDARD | 4A6V0X24A1 | 4PX*BU36BS3 | S8V2A040M3PDA | 16,400 | $820 |
| No | 210692026 | AMERICAN STANDARD | 4A6V0X24A1 | 4PX*BU36BS3 | S8V2A040M3PCA | 16,400 | $820 |
| No | 210652958 | AMERICAN STANDARD | 4A6V0X24A1 | 4PX*BU36BS3 | L8V1B080U4VSA+RP | 17,000 | $850 |
| No | 210652957 | AMERICAN STANDARD | 4A6V0X24A1 | 4PX*BU36BS3 | L8V1A060U3VSA+RP | 16,500 | $825 |
| No | 207590641 | AMERICAN STANDARD | 4A6V0X24A1 | 4PX*BU36BS3 | *UHMB060ACV3 | 16,800 | $840 |
| No | 210641044 | AMERICAN STANDARD | 4A6V0X24A1 | 4PX*BU36BS3 | *UD2B080A9V3+RP | 16,900 | $845 |
| No | 210641043 | AMERICAN STANDARD | 4A6V0X24A1 | 4PX*BU36BS3 | *UD2B060A9V3+RP | 17,000 | $850 |
| No | 211455294 | AMERICAN STANDARD | 4A6V0024A1 | TEM8A0B24V21+TDR | N/A | 17,600 | $880 |
| No | 207820973 | AMERICAN STANDARD | 4A6L9060A1 | TEM8B0C60V51+TDR | N/A | 37,800 | $1,890 |
| No | 201922848 | AMERICAN STANDARD | 4A6L9060A1 | TEM8A0D60V51+TDR | N/A | 38,000 | $1,900 |
| No | 201922847 | AMERICAN STANDARD | 4A6L9060A1 | TEM8A0D48V41+TDR | N/A | 38,500 | $1,925 |
| No | 207709012 | AMERICAN STANDARD | 4A6L9060A1 | TEM8A0C48V41+TDR | N/A | 38,000 | $1,900 |
| No | 201923686 | AMERICAN STANDARD | 4A6L9060A1 | TAM9A0C60V51 | N/A | 38,000 | $1,900 |
| No | 207805244 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3+P0V0D000M50SC+RP | N/A | 38,000 | $1,900 |
| No | 207805245 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3+P0V0C000M50SC+RP | N/A | 37,000 | $1,850 |
| No | 210652956 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | S9V2D120U5VSA+RP | 38,500 | $1,925 |
| No | 201922829 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | S9V2D120U5PSB+RP | 38,500 | $1,925 |
| No | 201922828 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | S9V2C100U5PSB+RP | 37,400 | $1,870 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211306998 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | S9V2C100D5PSB+RP | 36,400 | $1,820 |
| No | 201922827 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | S9V2C080U5PSB+RP | 37,600 | $1,880 |
| No | 211081386 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | S8V2D120M5PDA | 38,500 | $1,925 |
| No | 210692025 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | S8V2D120M5PCA | 38,500 | $1,925 |
| No | 211081384 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | S8V2C100M5PDA | 37,400 | $1,870 |
| No | 210692023 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | S8V2C100M5PCA | 37,400 | $1,870 |
| No | 211081385 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | S8V2C080M5PDA | 37,400 | $1,870 |
| No | 210692024 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | S8V2C080M5PCA | 37,400 | $1,870 |
| No | 207352653 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | L8V1C100U5VSA+RP | 37,400 | $1,870 |
| No | 201922826 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | *UHMD120ACV5 | 38,000 | $1,900 |
| No | 211597421 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | *UD2D120B9V5+RP | 38,500 | $1,925 |
| No | 201922823 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | *UD2D120ACV5 | 39,000 | $1,950 |
| No | 210649671 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | *UD2D120A9V5+RP | 38,000 | $1,900 |
| No | 210649670 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | *UD2C100B9V5+RP | 36,800 | $1,840 |
| No | 201922822 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | *UD2C100ACV5 | 37,000 | $1,850 |
| No | 210649669 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | *UD2C100A9V5+RP | 37,400 | $1,870 |
| No | 211306997 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | *DD2C100A9V5+RP | 35,400 | $1,770 |
| No | 207805242 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3+P0V0D000M50SC+RP | N/A | 38,500 | $1,925 |
| No | 207805243 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3+P0V0C000M50SC+RP | N/A | 37,400 | $1,870 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210652953 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3 | S9V2D120U5VSA+RP | 39,000 | $1,950 |
| No | 201922814 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3 | S9V2D120U5PSB+RP | 39,000 | $1,950 |
| No | 210652954 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3 | S9V2D120D5PSB+RP | 38,000 | $1,900 |
| No | 201922818 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3 | S9V2C100U5PSB+RP | 37,800 | $1,890 |
| No | 210652955 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3 | S9V2C100D5PSB+RP | 37,000 | $1,850 |
| No | 201922819 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3 | S9V2C080U5PSB+RP | 38,000 | $1,900 |
| No | 211081382 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3 | S8V2D120M5PDA | 39,000 | $1,950 |
| No | 210692021 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3 | S8V2D120M5PCA | 39,000 | $1,950 |
| No | 211081383 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3 | S8V2C100M5PDA | 38,000 | $1,900 |
| No | 210692022 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3 | S8V2C100M5PCA | 38,000 | $1,900 |
| No | 211081381 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3 | S8V2C080M5PDA | 38,000 | $1,900 |
| No | 210692020 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3 | S8V2C080M5PCA | 38,000 | $1,900 |
| No | 210652952 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3 | L8V1C100U5VSA+RP | 37,800 | $1,890 |
| No | 201922813 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3 | *UHMD120ACV5 | 38,500 | $1,925 |
| No | 207805241 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC009DS3+P0V0C000M50SC+RP | N/A | 38,000 | $1,900 |
| No | 201922801 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC009DS3 | S9V2C100U5PSB+RP | 38,500 | $1,925 |
| No | 201922807 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC009DS3 | S9V2C080U5PSB+RP | 38,500 | $1,925 |
| No | 211081380 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC009DS3 | S8V2C100M5PDA | 38,500 | $1,925 |
| No | 210692019 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC009DS3 | S8V2C100M5PCA | 38,500 | $1,925 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211081379 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC009DS3 | S8V2C080M5PDA | 38,500 | $1,925 |
| No | 210692018 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC009DS3 | S8V2C080M5PCA | 38,500 | $1,925 |
| No | 207352652 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC009DS3 | L8V1C100U5VSA+RP | 38,500 | $1,925 |
| No | 201922805 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC009DS3 | *UD2C100ACV5 | 38,000 | $1,900 |
| No | 211306996 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC009DS3 | *DD2C100A9V5+RP | 36,600 | $1,830 |
| No | 207805240 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC007DS3+P0V0C000M50SC+RP | N/A | 38,500 | $1,925 |
| No | 201922797 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC007DS3 | S9V2C100U5PSB+RP | 39,000 | $1,950 |
| No | 210652951 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC007DS3 | S9V2C100D5PSB+RP | 38,000 | $1,900 |
| No | 201922793 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC007DS3 | S9V2C080U5PSB+RP | 39,000 | $1,950 |
| No | 211081378 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC007DS3 | S8V2C100M5PDA | 39,000 | $1,950 |
| No | 210692017 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC007DS3 | S8V2C100M5PCA | 39,000 | $1,950 |
| No | 211081377 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC007DS3 | S8V2C080M5PDA | 39,000 | $1,950 |
| No | 210692016 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC007DS3 | S8V2C080M5PCA | 39,000 | $1,950 |
| No | 210652950 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC007DS3 | L8V1C100U5VSA+RP | 39,000 | $1,950 |
| No | 207805239 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3+P0V0D000M50SC+RP | N/A | 38,000 | $1,900 |
| No | 207805238 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3+P0V0C000M50SC+RP | N/A | 37,000 | $1,850 |
| No | 210652949 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3 | S9V2D120U5VSA+RP | 38,500 | $1,925 |
| No | 201922791 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3 | S9V2D120U5PSB+RP | 38,500 | $1,925 |
| No | 201922790 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3 | S9V2C100U5PSB+RP | 37,400 | $1,870 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922789 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3 | S9V2C080U5PSB+RP | 37,600 | $1,880 |
| No | 211081376 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3 | S8V2D120M5PDA | 38,500 | $1,925 |
| No | 210692015 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3 | S8V2D120M5PCA | 38,500 | $1,925 |
| No | 211081375 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3 | S8V2C100M5PDA | 37,600 | $1,880 |
| No | 210692014 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3 | S8V2C100M5PCA | 37,600 | $1,880 |
| No | 211081374 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3 | S8V2C080M5PDA | 37,400 | $1,870 |
| No | 210692013 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3 | S8V2C080M5PCA | 37,400 | $1,870 |
| No | 207352651 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3 | L8V1C100U5VSA+RP | 37,400 | $1,870 |
| No | 201922792 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3 | *UHMD120ACV5 | 38,000 | $1,900 |
| No | 211597420 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3 | *UD2D120B9V5+RP | 38,000 | $1,900 |
| No | 201922785 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3 | *UD2D120ACV5 | 38,500 | $1,925 |
| No | 210649668 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3 | *UD2D120A9V5+RP | 37,600 | $1,880 |
| No | 210649667 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3 | *UD2C100B9V5+RP | 36,400 | $1,820 |
| No | 201922784 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3 | *UD2C100ACV5 | 37,000 | $1,850 |
| No | 210649666 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3 | *UD2C100A9V5+RP | 36,800 | $1,840 |
| No | 211306995 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3 | *DD2C100A9V5+RP | 35,800 | $1,790 |
| No | 210652947 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU48BS3 | S9V2D120D5PSB+RP | 38,000 | $1,900 |
| No | 210652948 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU48BS3 | S9V2C100D5PSB+RP | 36,800 | $1,840 |
| No | 210652946 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU48BS3 | *DD2D120ACV5 | 38,500 | $1,925 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211306994 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU48BS3 | *DD2C100ACV5 | 37,200 | $1,860 |
| No | 207805234 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3+P0V0D000M50SC+RP | N/A | 38,000 | $1,900 |
| No | 207805235 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3+P0V0C000M50SC+RP | N/A | 37,000 | $1,850 |
| No | 210649665 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3+HORIZ-RT | *UD2C100A9V5+RP | 36,800 | $1,840 |
| No | 203978698 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3 | S9V2D120D5PSB+RP | 38,500 | $1,925 |
| No | 203864457 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3 | S9V2C100D5PSB+RP | 37,200 | $1,860 |
| No | 211081373 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3 | S8V2D120M5PDA | 38,500 | $1,925 |
| No | 210692012 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3 | S8V2D120M5PCA | 38,500 | $1,925 |
| No | 211081372 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3 | S8V2C100M5PDA | 37,600 | $1,880 |
| No | 210692011 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3 | S8V2C100M5PCA | 37,600 | $1,880 |
| No | 211081371 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3 | S8V2C080M5PDA | 37,400 | $1,870 |
| No | 210692010 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3 | S8V2C080M5PCA | 37,400 | $1,870 |
| No | 210649664 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3 | *DD2D120A9V5+RP | 37,400 | $1,870 |
| No | 210649663 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3 | *DD2C100A9V5+RP | 36,200 | $1,810 |
| No | 207805233 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU60BS3+P0V0C000M50SC+RP | N/A | 38,000 | $1,900 |
| No | 201922757 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU60BS3 | S9V2C100U5PSB+RP | 38,500 | $1,925 |
| No | 201922756 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU60BS3 | S9V2C080U5PSB+RP | 38,500 | $1,925 |
| No | 211081370 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU60BS3 | S8V2C100M5PDA | 38,500 | $1,925 |
| No | 210692009 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU60BS3 | S8V2C100M5PCA | 38,500 | $1,925 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211081369 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU60BS3 | S8V2C080M5PDA | 38,500 | $1,925 |
| No | 210692008 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU60BS3 | S8V2C080M5PCA | 38,500 | $1,925 |
| No | 207352650 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU60BS3 | L8V1C100U5VSA+RP | 38,500 | $1,925 |
| No | 201922759 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU60BS3 | *UD2C100ACV5 | 38,000 | $1,900 |
| No | 211306993 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU60BS3 | *DD2C100A9V5+RP | 37,000 | $1,850 |
| No | 211286027 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU48BS3+P0V0C000M50SC+RP | N/A | 38,500 | $1,925 |
| No | 201922750 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU48BS3 | S9V2C100U5PSB+RP | 39,000 | $1,950 |
| No | 210652944 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU48BS3 | S9V2C100D5PSB+RP | 38,500 | $1,925 |
| No | 201922751 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU48BS3 | S9V2C080U5PSB+RP | 39,000 | $1,950 |
| No | 211081368 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU48BS3 | S8V2C100M5PDA | 39,000 | $1,950 |
| No | 210692007 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU48BS3 | S8V2C100M5PCA | 39,000 | $1,950 |
| No | 211081367 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU48BS3 | S8V2C080M5PDA | 39,000 | $1,950 |
| No | 210692006 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU48BS3 | S8V2C080M5PCA | 39,000 | $1,950 |
| No | 210652943 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU48BS3 | L8V1C100U5VSA+RP | 39,000 | $1,950 |
| No | 210652945 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU48BS3 | *DD2C100ACV5 | 38,000 | $1,900 |
| No | 207805231 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CD60BS3+P0V0C000M50SC+RP | N/A | 38,000 | $1,900 |
| No | 201922740 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CD60BS3 | S9V2C100D5PSB+RP | 38,500 | $1,925 |
| No | 211081366 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CD60BS3 | S8V2C100M5PDA | 38,500 | $1,925 |
| No | 210692005 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CD60BS3 | S8V2C100M5PCA | 38,500 | $1,925 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211081365 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CD60BS3 | S8V2C080M5PDA | 38,500 | $1,925 |
| No | 210692004 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CD60BS3 | S8V2C080M5PCA | 38,500 | $1,925 |
| No | 207820971 | AMERICAN STANDARD | 4A6L9048A1 | TEM8B0C60V51+TDR | N/A | 31,200 | $1,560 |
| No | 207335059 | AMERICAN STANDARD | 4A6L9048A1 | TEM8A0D60V51+TDR | N/A | 32,000 | $1,600 |
| No | 201922738 | AMERICAN STANDARD | 4A6L9048A1 | TEM8A0D48V41+TDR | N/A | 32,200 | $1,610 |
| No | 201922736 | AMERICAN STANDARD | 4A6L9048A1 | TEM8A0C48V41+TDR | N/A | 31,400 | $1,570 |
| No | 207804060 | AMERICAN STANDARD | 4A6L9048A1 | TEM8A0C42V41+TDR | N/A | 32,000 | $1,600 |
| No | 201922735 | AMERICAN STANDARD | 4A6L9048A1 | TAM9A0C60V51 | N/A | 31,600 | $1,580 |
| No | 201923684 | AMERICAN STANDARD | 4A6L9048A1 | TAM9A0C48V41 | N/A | 31,600 | $1,580 |
| No | 201922734 | AMERICAN STANDARD | 4A6L9048A1 | TAM9A0C42V41 | N/A | 31,600 | $1,580 |
| No | 206392943 | AMERICAN STANDARD | 4A6L9048A1 | 4TXFH064AZ3 | *UD2C080ACV4 | 31,600 | $1,580 |
| No | 207805230 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3+P0V0D000M50SC+RP | N/A | 31,400 | $1,570 |
| No | 207805229 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3+P0V0C000M50SC+RP | N/A | 30,600 | $1,530 |
| No | 210652941 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | S9V2D120U5VSA+RP | 31,800 | $1,590 |
| No | 201922718 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | S9V2D120U5PSB+RP | 31,800 | $1,590 |
| No | 201922713 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | S9V2D120D5PSB+RP | 30,800 | $1,540 |
| No | 201922719 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | S9V2C100U5PSB+RP | 31,000 | $1,550 |
| No | 210652942 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | S9V2C100U4VSA+RP | 30,800 | $1,540 |
| No | 201922720 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | S9V2C100U4PSB+RP | 30,800 | $1,540 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922706 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | S9V2C100D5PSB+RP | 30,000 | $1,500 |
| No | 210653877 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | S9V2C100D4VSA+RP | 29,800 | $1,490 |
| No | 201922707 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | S9V2C100D4PSB+RP | 29,800 | $1,490 |
| No | 201922721 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | S9V2C080U5PSB+RP | 30,800 | $1,540 |
| No | 211081363 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | S8V2D120M5PDA | 31,800 | $1,590 |
| No | 210692002 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | S8V2D120M5PCA | 31,800 | $1,590 |
| No | 211089034 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | S8V2C100M5PDA | 31,000 | $1,550 |
| No | 210692214 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | S8V2C100M5PCA | 31,000 | $1,550 |
| No | 211081364 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | S8V2C080M5PDA | 30,800 | $1,540 |
| No | 210692003 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | S8V2C080M5PCA | 30,800 | $1,540 |
| No | 207352648 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | L8V1C100U5VSA+RP | 30,800 | $1,540 |
| No | 201922722 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | *UHMD120ACV5 | 31,600 | $1,580 |
| No | 201922723 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | *UHMC100ACV4 | 30,800 | $1,540 |
| No | 201922724 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | *UD2D140ACV5 | 31,800 | $1,590 |
| No | 201922727 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | *UD2D120ACV5 | 31,800 | $1,590 |
| No | 201922729 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | *UD2C100ACV5 | 31,200 | $1,560 |
| No | 201922714 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | *UD2C080ACV4 | 30,800 | $1,540 |
| No | 201922708 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | *DHMD120BCV5 | 31,000 | $1,550 |
| No | 201922709 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | *DHMC100ACV4 | 30,200 | $1,510 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922710 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | *DD2D120ACV5 | 30,800 | $1,540 |
| No | 201922711 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | *DD2C100ACV5 | 30,000 | $1,500 |
| No | 207805228 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3+P0V0D000M50SC+RP | N/A | 32,000 | $1,600 |
| No | 207805227 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3+P0V0C000M50SC+RP | N/A | 31,000 | $1,550 |
| No | 210652939 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | S9V2D120U5VSA+RP | 32,200 | $1,610 |
| No | 201922700 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | S9V2D120U5PSB+RP | 32,200 | $1,610 |
| No | 201922690 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | S9V2D120D5PSB+RP | 31,400 | $1,570 |
| No | 201922701 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | S9V2C100U5PSB+RP | 31,400 | $1,570 |
| No | 210652940 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | S9V2C100U4VSA+RP | 31,200 | $1,560 |
| No | 201922702 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | S9V2C100U4PSB+RP | 31,200 | $1,560 |
| No | 201922691 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | S9V2C100D5PSB+RP | 30,600 | $1,530 |
| No | 210653876 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | S9V2C100D4VSA+RP | 30,400 | $1,520 |
| No | 201922692 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | S9V2C100D4PSB+RP | 30,400 | $1,520 |
| No | 201922703 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | S9V2C080U5PSB+RP | 31,400 | $1,570 |
| No | 211081362 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | S8V2D120M5PDA | 32,200 | $1,610 |
| No | 210692001 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | S8V2D120M5PCA | 32,200 | $1,610 |
| No | 211089032 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | S8V2C100M5PDA | 31,400 | $1,570 |
| No | 210692212 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | S8V2C100M5PCA | 31,400 | $1,570 |
| No | 211089033 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | S8V2C080M5PDA | 31,200 | $1,560 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210692213 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | S8V2C080M5PCA | 31,200 | $1,560 |
| No | 207352647 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | L8V1C100U5VSA+RP | 31,200 | $1,560 |
| No | 201922678 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | *UHMD120ACV5 | 32,200 | $1,610 |
| No | 201922679 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | *UHMC100ACV4 | 31,200 | $1,560 |
| No | 201922680 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | *UD2D140ACV5 | 32,200 | $1,610 |
| No | 201922683 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | *UD2D120ACV5 | 32,200 | $1,610 |
| No | 201922686 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | *UD2C100ACV5 | 31,400 | $1,570 |
| No | 201922687 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | *UD2C080ACV4 | 31,200 | $1,560 |
| No | 201922693 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | *DHMD120BCV5 | 31,600 | $1,580 |
| No | 201922694 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | *DHMC100ACV4 | 30,600 | $1,530 |
| No | 201922695 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | *DD2D120ACV5 | 31,400 | $1,570 |
| No | 201922697 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | *DD2C100ACV5 | 30,600 | $1,530 |
| No | 207805226 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC009DS3+P0V0C000M50SC+RP | N/A | 31,600 | $1,580 |
| No | 201922673 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC009DS3 | S9V2C100U5PSB+RP | 32,000 | $1,600 |
| No | 210652937 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC009DS3 | S9V2C100U4VSA+RP | 31,800 | $1,590 |
| No | 201922672 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC009DS3 | S9V2C100U4PSB+RP | 31,800 | $1,590 |
| No | 201922666 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC009DS3 | S9V2C100D5PSB+RP | 31,000 | $1,550 |
| No | 210652938 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC009DS3 | S9V2C100D4VSA+RP | 30,800 | $1,540 |
| No | 201922665 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC009DS3 | S9V2C100D4PSB+RP | 30,800 | $1,540 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922671 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC009DS3 | S9V2C080U5PSB+RP | 31,800 | $1,590 |
| No | 211081361 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC009DS3 | S8V2C100M5PDA | 32,000 | $1,600 |
| No | 210692000 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC009DS3 | S8V2C100M5PCA | 32,000 | $1,600 |
| No | 211081360 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC009DS3 | S8V2C080M5PDA | 31,800 | $1,590 |
| No | 210691999 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC009DS3 | S8V2C080M5PCA | 31,800 | $1,590 |
| No | 207352646 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC009DS3 | L8V1C100U5VSA+RP | 31,800 | $1,590 |
| No | 201922669 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC009DS3 | *UHMC100ACV4 | 31,800 | $1,590 |
| No | 201922667 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC009DS3 | *UD2C100ACV5 | 32,200 | $1,610 |
| No | 201922675 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC009DS3 | *UD2C080ACV4 | 31,800 | $1,590 |
| No | 201922664 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC009DS3 | *DHMC100ACV4 | 31,000 | $1,550 |
| No | 201922663 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC009DS3 | *DD2C100ACV5 | 30,800 | $1,540 |
| No | 207805225 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC007DS3+P0V0C000M50SC+RP | N/A | 31,800 | $1,590 |
| No | 201922654 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC007DS3 | S9V2C100U5PSB+RP | 32,400 | $1,620 |
| No | 210652936 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC007DS3 | S9V2C100U4VSA+RP | 32,000 | $1,600 |
| No | 201922655 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC007DS3 | S9V2C100U4PSB+RP | 32,200 | $1,610 |
| No | 201922650 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC007DS3 | S9V2C100D5PSB+RP | 31,600 | $1,580 |
| No | 210652935 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC007DS3 | S9V2C100D4VSA+RP | 31,400 | $1,570 |
| No | 201922649 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC007DS3 | S9V2C100D4PSB+RP | 31,400 | $1,570 |
| No | 201922653 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC007DS3 | S9V2C080U5PSB+RP | 32,400 | $1,620 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211081359 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC007DS3 | S8V2C100M5PDA | 32,200 | $1,610 |
| No | 210691998 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC007DS3 | S8V2C100M5PCA | 32,200 | $1,610 |
| No | 211081358 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC007DS3 | S8V2C080M5PDA | 32,200 | $1,610 |
| No | 210691997 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC007DS3 | S8V2C080M5PCA | 32,200 | $1,610 |
| No | 207352645 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC007DS3 | L8V1C100U5VSA+RP | 32,000 | $1,600 |
| No | 201922660 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC007DS3 | *UHMC100ACV4 | 32,200 | $1,610 |
| No | 201922657 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC007DS3 | *UD2C100ACV5 | 32,200 | $1,610 |
| No | 201922651 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC007DS3 | *UD2C080ACV4 | 32,200 | $1,610 |
| No | 201922648 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC007DS3 | *DHMC100ACV4 | 32,000 | $1,600 |
| No | 201922659 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC007DS3 | *DD2C100ACV5 | 31,400 | $1,570 |
| No | 210652934 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC005DS3 | S9V2C100U4VSA+RP | 32,600 | $1,630 |
| No | 210652933 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC005DS3 | S9V2C100U4PSB+RP | 32,600 | $1,630 |
| No | 210652932 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC005DS3 | S9V2C080U5PSB+RP | 32,800 | $1,640 |
| No | 211081357 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC005DS3 | S8V2C080M5PDA | 32,600 | $1,630 |
| No | 210691996 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC005DS3 | S8V2C080M5PCA | 32,600 | $1,630 |
| No | 201922647 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC005DS3 | *UHMC100ACV4 | 32,600 | $1,630 |
| No | 201922645 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC005DS3 | *UD2C100ACV5 | 32,600 | $1,630 |
| No | 201922646 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC005DS3 | *UD2C080ACV4 | 32,600 | $1,630 |
| No | 208185440 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCB006DS3+P0V0B000M40SC+RP | N/A | 31,600 | $1,580 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210652930 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCB006DS3 | S9V2B080U4VSA+RP | 32,600 | $1,630 |
| No | 201922642 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCB006DS3 | S9V2B080U4PSB+RP | 32,600 | $1,630 |
| No | 210652931 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCB006DS3 | S9V2B080D4VSA+RP | 31,600 | $1,580 |
| No | 201922644 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCB006DS3 | S9V2B080D4PSB+RP | 31,600 | $1,580 |
| No | 201922643 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCB006DS3 | S9V2B060U4PSB+RP | 32,600 | $1,630 |
| No | 211081355 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCB006DS3 | S8V2B080M4PDA | 32,600 | $1,630 |
| No | 210691995 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCB006DS3 | S8V2B080M4PCA | 32,600 | $1,630 |
| No | 211081356 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCB006DS3 | S8V2B060M4PDA | 32,600 | $1,630 |
| No | 210691994 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCB006DS3 | S8V2B060M4PCA | 32,600 | $1,630 |
| No | 210652929 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCB006DS3 | L8V1B080U4VSA+RP | 32,600 | $1,630 |
| No | 207805223 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3+P0V0D000M50SC+RP | N/A | 31,400 | $1,570 |
| No | 207805222 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3+P0V0C000M50SC+RP | N/A | 30,600 | $1,530 |
| No | 210652925 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | S9V2D120U5VSA+RP | 31,600 | $1,580 |
| No | 201922640 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | S9V2D120U5PSB+RP | 31,800 | $1,590 |
| No | 210652928 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | S9V2D120D5PSB+RP | 30,800 | $1,540 |
| No | 201922639 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | S9V2C100U5PSB+RP | 31,000 | $1,550 |
| No | 210652924 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | S9V2C100U4VSA+RP | 30,800 | $1,540 |
| No | 201922638 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | S9V2C100U4PSB+RP | 30,800 | $1,540 |
| No | 210653875 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | S9V2C100D5PSB+RP | 30,000 | $1,500 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210653874 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | S9V2C100D4VSA+RP | 29,800 | $1,490 |
| No | 210653873 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | S9V2C100D4PSB+RP | 29,800 | $1,490 |
| No | 201922625 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | S9V2C080U5PSB+RP | 31,000 | $1,550 |
| No | 211081353 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | S8V2D120M5PDA | 31,800 | $1,590 |
| No | 210691993 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | S8V2D120M5PCA | 31,800 | $1,590 |
| No | 211089031 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | S8V2C100M5PDA | 30,800 | $1,540 |
| No | 210692211 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | S8V2C100M5PCA | 30,800 | $1,540 |
| No | 211081354 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | S8V2C080M5PDA | 30,800 | $1,540 |
| No | 210691992 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | S8V2C080M5PCA | 30,800 | $1,540 |
| No | 207352644 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | L8V1C100U5VSA+RP | 30,800 | $1,540 |
| No | 201922641 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | *UHMD120ACV5 | 31,600 | $1,580 |
| No | 201922627 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | *UHMC100ACV4 | 30,800 | $1,540 |
| No | 201922628 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | *UD2D140ACV5 | 31,800 | $1,590 |
| No | 201922631 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | *UD2D120ACV5 | 31,800 | $1,590 |
| No | 201922633 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | *UD2C100ACV5 | 31,200 | $1,560 |
| No | 201922636 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | *UD2C080ACV4 | 30,800 | $1,540 |
| No | 210652927 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | *DHMD120BCV5 | 31,000 | $1,550 |
| No | 210653872 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | *DHMC100ACV4 | 30,000 | $1,500 |
| No | 210652926 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | *DD2D120ACV5 | 30,600 | $1,530 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210649662 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | *DD2D120A9V5+RP | 30,600 | $1,530 |
| No | 210653871 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | *DD2C100ACV5 | 30,000 | $1,500 |
| No | 207805221 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3+P0V0D000M50SC+RP | N/A | 31,800 | $1,590 |
| No | 207805220 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3+P0V0C000M50SC+RP | N/A | 31,200 | $1,560 |
| No | 210652922 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | S9V2D120U5VSA+RP | 32,200 | $1,610 |
| No | 201922624 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | S9V2D120U5PSB+RP | 32,200 | $1,610 |
| No | 210652919 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | S9V2D120D5PSB+RP | 31,600 | $1,580 |
| No | 201922623 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | S9V2C100U5PSB+RP | 31,200 | $1,560 |
| No | 210652923 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | S9V2C100U4VSA+RP | 31,400 | $1,570 |
| No | 201922622 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | S9V2C100U4PSB+RP | 31,200 | $1,560 |
| No | 210653870 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | S9V2C100D5PSB+RP | 30,600 | $1,530 |
| No | 210653869 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | S9V2C100D4VSA+RP | 30,400 | $1,520 |
| No | 210653866 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | S9V2C100D4PSB+RP | 30,400 | $1,520 |
| No | 201922609 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | S9V2C080U5PSB+RP | 31,400 | $1,570 |
| No | 211081352 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | S8V2D120M5PDA | 32,400 | $1,620 |
| No | 210691991 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | S8V2D120M5PCA | 32,400 | $1,620 |
| No | 211089029 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | S8V2C100M5PDA | 31,400 | $1,570 |
| No | 210692210 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | S8V2C100M5PCA | 31,400 | $1,570 |
| No | 211089030 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | S8V2C080M5PDA | 31,200 | $1,560 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210692209 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | S8V2C080M5PCA | 31,200 | $1,560 |
| No | 207352643 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | L8V1C100U5VSA+RP | 31,200 | $1,560 |
| No | 201922608 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | *UHMD120ACV5 | 32,200 | $1,610 |
| No | 201922621 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | *UHMC100ACV4 | 31,200 | $1,560 |
| No | 201922610 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | *UD2D140ACV5 | 32,200 | $1,610 |
| No | 201922613 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | *UD2D120ACV5 | 32,200 | $1,610 |
| No | 201922616 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | *UD2C100ACV5 | 31,400 | $1,570 |
| No | 201922617 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | *UD2C080ACV4 | 31,200 | $1,560 |
| No | 210652920 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | *DHMD120BCV5 | 31,600 | $1,580 |
| No | 210653867 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | *DHMC100ACV4 | 30,800 | $1,540 |
| No | 210652921 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | *DD2D120ACV5 | 31,600 | $1,580 |
| No | 210649661 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | *DD2D120A9V5+RP | 31,200 | $1,560 |
| No | 210653868 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | *DD2C100ACV5 | 30,600 | $1,530 |
| No | 207805216 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3+P0V0D000M50SC+RP | N/A | 31,400 | $1,570 |
| No | 207805217 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3+P0V0C000M50SC+RP | N/A | 30,600 | $1,530 |
| No | 201922605 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3+HORIZ-RT | *UD2D140ACV5 | 31,800 | $1,590 |
| No | 201922593 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3+HORIZ-RT | *UD2D120ACV5 | 32,000 | $1,600 |
| No | 201922596 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3+HORIZ-RT | *UD2C100ACV5 | 31,200 | $1,560 |
| No | 201922599 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3+HORIZ-RT | *UD2C080ACV4 | 30,800 | $1,540 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922588 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3 | S9V2D120D5PSB+RP | 31,800 | $1,590 |
| No | 201922591 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3 | S9V2C100D5PSB+RP | 31,000 | $1,550 |
| No | 210652918 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3 | S9V2C100D4VSA+RP | 30,800 | $1,540 |
| No | 201922584 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3 | S9V2C100D4PSB+RP | 30,800 | $1,540 |
| No | 211081351 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3 | S8V2D120M5PDA | 31,800 | $1,590 |
| No | 210691990 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3 | S8V2D120M5PCA | 31,800 | $1,590 |
| No | 211089028 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3 | S8V2C100M5PDA | 31,000 | $1,550 |
| No | 210692208 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3 | S8V2C100M5PCA | 31,000 | $1,550 |
| No | 211081350 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3 | S8V2C080M5PDA | 30,800 | $1,540 |
| No | 210691989 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3 | S8V2C080M5PCA | 30,800 | $1,540 |
| No | 201922590 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3 | *DHMD120BCV5 | 32,000 | $1,600 |
| No | 201922589 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3 | *DHMC100ACV4 | 31,000 | $1,550 |
| No | 201922592 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3 | *DD2D120ACV5 | 31,800 | $1,590 |
| No | 201922586 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3 | *DD2C100ACV5 | 31,000 | $1,550 |
| No | 207805211 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU60BS3+P0V0C000M50SC+RP | N/A | 31,600 | $1,580 |
| No | 201922557 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU60BS3 | S9V2C100U5PSB+RP | 32,000 | $1,600 |
| No | 210652913 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU60BS3 | S9V2C100U4VSA+RP | 31,800 | $1,590 |
| No | 201922560 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU60BS3 | S9V2C100U4PSB+RP | 31,800 | $1,590 |
| No | 210652916 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU60BS3 | S9V2C100D5PSB+RP | 31,000 | $1,550 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210652917 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU60BS3 | S9V2C100D4VSA+RP | 30,800 | $1,540 |
| No | 202544296 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU60BS3 | S9V2C100D4PSB+RP | 30,800 | $1,540 |
| No | 201922554 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU60BS3 | S9V2C080U5PSB+RP | 31,800 | $1,590 |
| No | 211081348 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU60BS3 | S8V2C100M5PDA | 32,000 | $1,600 |
| No | 210691988 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU60BS3 | S8V2C100M5PCA | 32,000 | $1,600 |
| No | 211081349 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU60BS3 | S8V2C080M5PDA | 31,800 | $1,590 |
| No | 210691987 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU60BS3 | S8V2C080M5PCA | 31,800 | $1,590 |
| No | 207352642 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU60BS3 | L8V1C100U5VSA+RP | 31,800 | $1,590 |
| No | 201922552 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU60BS3 | *UHMC100ACV4 | 31,800 | $1,590 |
| No | 201922558 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU60BS3 | *UD2C100ACV5 | 32,200 | $1,610 |
| No | 201922559 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU60BS3 | *UD2C080ACV4 | 31,800 | $1,590 |
| No | 210652915 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU60BS3 | *DHMC100ACV4 | 31,000 | $1,550 |
| No | 210652914 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU60BS3 | *DD2C100ACV5 | 30,800 | $1,540 |
| No | 210649660 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU60BS3 | *DD2C100A9V5+RP | 30,800 | $1,540 |
| No | 207805210 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU48BS3+P0V0C000M50SC+RP | N/A | 32,000 | $1,600 |
| No | 201922550 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU48BS3 | S9V2C100U5PSB+RP | 32,400 | $1,620 |
| No | 210652908 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU48BS3 | S9V2C100U4VSA+RP | 32,200 | $1,610 |
| No | 201922549 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU48BS3 | S9V2C100U4PSB+RP | 32,200 | $1,610 |
| No | 210652912 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU48BS3 | S9V2C100D5PSB+RP | 31,600 | $1,580 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210652911 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU48BS3 | S9V2C100D4VSA+RP | 31,400 | $1,570 |
| No | 210652910 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU48BS3 | S9V2C100D4PSB+RP | 31,400 | $1,570 |
| No | 201922542 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU48BS3 | S9V2C080U5PSB+RP | 32,400 | $1,620 |
| No | 211081346 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU48BS3 | S8V2C100M5PDA | 32,200 | $1,610 |
| No | 210691986 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU48BS3 | S8V2C100M5PCA | 32,200 | $1,610 |
| No | 211081347 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU48BS3 | S8V2C080M5PDA | 32,200 | $1,610 |
| No | 210691985 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU48BS3 | S8V2C080M5PCA | 32,200 | $1,610 |
| No | 207352641 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU48BS3 | L8V1C100U5VSA+RP | 32,200 | $1,610 |
| No | 201922541 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU48BS3 | *UHMC100ACV4 | 32,200 | $1,610 |
| No | 201922547 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU48BS3 | *UD2C100ACV5 | 32,400 | $1,620 |
| No | 201922544 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU48BS3 | *UD2C080ACV4 | 32,200 | $1,610 |
| No | 210652909 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU48BS3 | *DHMC100ACV4 | 31,600 | $1,580 |
| No | 207259420 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU48BS3 | *DD2C100ACV5 | 31,400 | $1,570 |
| No | 210649659 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU48BS3 | *DD2C100A9V5+RP | 31,000 | $1,550 |
| No | 207805209 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU42BS3+P0V0C000M50SC+RP | N/A | 32,400 | $1,620 |
| No | 201922538 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU42BS3 | S9V2C100U5PSB+RP | 32,600 | $1,630 |
| No | 210652904 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU42BS3 | S9V2C100U4VSA+RP | 32,600 | $1,630 |
| No | 201922537 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU42BS3 | S9V2C100U4PSB+RP | 32,400 | $1,620 |
| No | 210652907 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU42BS3 | S9V2C100D5PSB+RP | 31,800 | $1,590 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210652906 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU42BS3 | S9V2C100D4VSA+RP | 31,800 | $1,590 |
| No | 210652905 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU42BS3 | S9V2C100D4PSB+RP | 32,000 | $1,600 |
| No | 201922536 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU42BS3 | S9V2C080U5PSB+RP | 32,600 | $1,630 |
| No | 211081344 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU42BS3 | S8V2C100M5PDA | 32,600 | $1,630 |
| No | 210691984 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU42BS3 | S8V2C100M5PCA | 32,600 | $1,630 |
| No | 211081345 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU42BS3 | S8V2C080M5PDA | 32,600 | $1,630 |
| No | 210691983 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU42BS3 | S8V2C080M5PCA | 32,600 | $1,630 |
| No | 207352640 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU42BS3 | L8V1C100U5VSA+RP | 32,400 | $1,620 |
| No | 201922540 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU42BS3 | *UHMC100ACV4 | 32,400 | $1,620 |
| No | 201922533 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU42BS3 | *UD2C100ACV5 | 32,600 | $1,630 |
| No | 201922535 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU42BS3 | *UD2C080ACV4 | 32,400 | $1,620 |
| No | 202586183 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU42BS3 | *DHMC100ACV4 | 32,200 | $1,610 |
| No | 202586182 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU42BS3 | *DD2C100ACV5 | 32,000 | $1,600 |
| No | 210649658 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU42BS3 | *DD2C100A9V5+RP | 31,600 | $1,580 |
| No | 207805207 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD60BS3+P0V0C000M50SC+RP | N/A | 31,400 | $1,570 |
| No | 201922522 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD60BS3+HORIZ-RT | *UD2C100ACV5 | 32,200 | $1,610 |
| No | 201922525 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD60BS3+HORIZ-RT | *UD2C080ACV4 | 31,800 | $1,590 |
| No | 201922514 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD60BS3 | S9V2C100D5PSB+RP | 31,800 | $1,590 |
| No | 210652903 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD60BS3 | S9V2C100D4VSA+RP | 31,800 | $1,590 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922515 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD60BS3 | S9V2C100D4PSB+RP | 31,800 | $1,590 |
| No | 211081342 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD60BS3 | S8V2C100M5PDA | 31,800 | $1,590 |
| No | 210691981 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD60BS3 | S8V2C100M5PCA | 31,800 | $1,590 |
| No | 211081343 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD60BS3 | S8V2C080M5PDA | 31,800 | $1,590 |
| No | 210691982 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD60BS3 | S8V2C080M5PCA | 31,800 | $1,590 |
| No | 201922517 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD60BS3 | *DHMC100ACV4 | 31,800 | $1,590 |
| No | 201922518 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD60BS3 | *DD2C100ACV5 | 31,800 | $1,590 |
| No | 211289109 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*BU48BS3+P0V0B000M40SC+RP | N/A | 31,400 | $1,570 |
| No | 210652902 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*BU48BS3 | S9V2B080U4VSA+RP | 32,600 | $1,630 |
| No | 201922501 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*BU48BS3 | S9V2B080U4PSB+RP | 32,600 | $1,630 |
| No | 210652901 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*BU48BS3 | S9V2B080D4VSA+RP | 31,600 | $1,580 |
| No | 207786386 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*BU48BS3 | S9V2B080D4PSB+RP | 31,600 | $1,580 |
| No | 201922500 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*BU48BS3 | S9V2B060U4PSB+RP | 32,600 | $1,630 |
| No | 211081340 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*BU48BS3 | S8V2B080M4PDA | 32,600 | $1,630 |
| No | 210691980 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*BU48BS3 | S8V2B080M4PCA | 32,600 | $1,630 |
| No | 211081341 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*BU48BS3 | S8V2B060M4PDA | 32,400 | $1,620 |
| No | 210691979 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*BU48BS3 | S8V2B060M4PCA | 32,400 | $1,620 |
| No | 210652900 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*BU48BS3 | L8V1B080U4VSA+RP | 32,600 | $1,630 |
| No | 210653865 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*BU42BS3 | S9V2B080D4VSA+RP | 32,000 | $1,600 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210653864 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*BU42BS3 | S9V2B080D4PSB+RP | 32,000 | $1,600 |
| No | 210636931 | AMERICAN STANDARD | 4A6L9036A1 | TEM8A0D60V51+TDR | N/A | 23,400 | $1,170 |
| No | 201922496 | AMERICAN STANDARD | 4A6L9036A1 | TEM8A0D48V41+TDR | N/A | 23,600 | $1,180 |
| No | 201922495 | AMERICAN STANDARD | 4A6L9036A1 | TEM8A0C48V41+TDR | N/A | 23,000 | $1,150 |
| No | 201922494 | AMERICAN STANDARD | 4A6L9036A1 | TEM8A0C42V41+TDR | N/A | 23,400 | $1,170 |
| No | 201922493 | AMERICAN STANDARD | 4A6L9036A1 | TEM8A0C36V31+TDR | N/A | 23,200 | $1,160 |
| No | 202538581 | AMERICAN STANDARD | 4A6L9036A1 | TEM8A0B30V31+TDR | N/A | 24,200 | $1,210 |
| No | 208443276 | AMERICAN STANDARD | 4A6L9036A1 | TAM9A0C48V41 | N/A | 23,000 | $1,150 |
| No | 201922492 | AMERICAN STANDARD | 4A6L9036A1 | TAM9A0C42V41 | N/A | 22,800 | $1,140 |
| No | 201922491 | AMERICAN STANDARD | 4A6L9036A1 | TAM9A0B30V31 | N/A | 24,000 | $1,200 |
| No | 201922484 | AMERICAN STANDARD | 4A6L9036A1 | 4TXFH036CZ3 | *UD2C100ACV5 | 23,400 | $1,170 |
| No | 201922480 | AMERICAN STANDARD | 4A6L9036A1 | 4TXFH036CZ3 | *UD2C080ACV4 | 23,200 | $1,160 |
| No | 201922482 | AMERICAN STANDARD | 4A6L9036A1 | 4TXFH036CZ3 | *UD2B080ACV3 | 23,600 | $1,180 |
| No | 201922483 | AMERICAN STANDARD | 4A6L9036A1 | 4TXFH036CZ3 | *UD2B060ACV3 | 23,600 | $1,180 |
| No | 206216701 | AMERICAN STANDARD | 4A6L9036A1 | 4TXFH036CZ3 | *DHMB060BCV3 | 23,600 | $1,180 |
| No | 211081339 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCD010DS3 | S8V2D120M5PDA | 23,200 | $1,160 |
| No | 210691978 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCD010DS3 | S8V2D120M5PCA | 23,200 | $1,160 |
| No | 210649657 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCD010DS3 | *UD2D120A9V5+RP | 23,400 | $1,170 |
| No | 211081338 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCD008DS3 | S8V2D120M5PDA | 23,600 | $1,180 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210691977 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCD008DS3 | S8V2D120M5PCA | 23,600 | $1,180 |
| No | 210649655 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCD008DS3 | *UD2D120A9V5+RP | 23,600 | $1,180 |
| No | 210649656 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCD008DS3 | *DD2D120A9V5+RP | 22,600 | $1,130 |
| No | 209559373 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC009DS3 | S9V2C100U4VSA+RP | 23,000 | $1,150 |
| No | 210652899 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC009DS3 | S9V2C100U4PSB+RP | 22,800 | $1,140 |
| No | 211081337 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC009DS3 | S8V2C100M5PDA | 23,400 | $1,170 |
| No | 210691976 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC009DS3 | S8V2C100M5PCA | 23,400 | $1,170 |
| No | 211081336 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC009DS3 | S8V2C080M5PDA | 23,200 | $1,160 |
| No | 210691975 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC009DS3 | S8V2C080M5PCA | 23,200 | $1,160 |
| No | 210652898 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC009DS3 | L8V1C100U5VSA+RP | 23,200 | $1,160 |
| No | 201922466 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC009DS3 | *UHMC100ACV4 | 23,200 | $1,160 |
| No | 210649654 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC009DS3 | *UD2C100B9V5+RP | 23,200 | $1,160 |
| No | 201922465 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC009DS3 | *UD2C100ACV5 | 23,400 | $1,170 |
| No | 210649653 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC009DS3 | *UD2C100A9V5+RP | 23,200 | $1,160 |
| No | 210649652 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC009DS3 | *UD2C080B9V4+RP | 23,200 | $1,160 |
| No | 201922464 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC009DS3 | *UD2C080ACV4 | 23,200 | $1,160 |
| No | 210649651 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC009DS3 | *UD2C080A9V4+RP | 23,600 | $1,180 |
| No | 210652895 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC007DS3 | S9V2C100U4VSA+RP | 23,400 | $1,170 |
| No | 201922460 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC007DS3 | S9V2C100U4PSB+RP | 23,000 | $1,150 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210652897 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC007DS3 | S9V2C100D4VSA+RP | 22,800 | $1,140 |
| No | 210652896 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC007DS3 | S9V2C100D4PSB+RP | 22,800 | $1,140 |
| No | 211081335 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC007DS3 | S8V2C100M5PDA | 23,400 | $1,170 |
| No | 210691974 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC007DS3 | S8V2C100M5PCA | 23,400 | $1,170 |
| No | 211081334 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC007DS3 | S8V2C080M5PDA | 23,400 | $1,170 |
| No | 210691973 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC007DS3 | S8V2C080M5PCA | 23,400 | $1,170 |
| No | 210652894 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC007DS3 | L8V1C100U5VSA+RP | 23,200 | $1,160 |
| No | 201922452 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC007DS3 | *UHMC100ACV4 | 23,200 | $1,160 |
| No | 210649649 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC007DS3 | *UD2C100B9V5+RP | 23,200 | $1,160 |
| No | 201922453 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC007DS3 | *UD2C100ACV5 | 23,600 | $1,180 |
| No | 210649646 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC007DS3 | *UD2C100A9V5+RP | 23,600 | $1,180 |
| No | 210649647 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC007DS3 | *UD2C080B9V4+RP | 23,000 | $1,150 |
| No | 201922454 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC007DS3 | *UD2C080ACV4 | 23,400 | $1,170 |
| No | 210649648 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC007DS3 | *UD2C080A9V4+RP | 23,400 | $1,170 |
| No | 201922462 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC007DS3 | *DHMC100ACV4 | 23,000 | $1,150 |
| No | 201922461 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC007DS3 | *DD2C100ACV5 | 23,000 | $1,150 |
| No | 210649650 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC007DS3 | *DD2C100A9V5+RP | 22,400 | $1,120 |
| No | 210652892 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | S9V2C100U4VSA+RP | 23,400 | $1,170 |
| No | 201922450 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | S9V2C100U4PSB+RP | 23,400 | $1,170 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210652891 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | S9V2C100D4VSA+RP | 23,000 | $1,150 |
| No | 210652893 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | S9V2C100D4PSB+RP | 23,000 | $1,150 |
| No | 211081333 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | S8V2C100M5PDA | 23,800 | $1,190 |
| No | 210691972 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | S8V2C100M5PCA | 23,800 | $1,190 |
| No | 211081332 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | S8V2C080M5PDA | 23,600 | $1,180 |
| No | 210691971 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | S8V2C080M5PCA | 23,600 | $1,180 |
| No | 210652890 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | L8V1C100U5VSA+RP | 23,800 | $1,190 |
| No | 201922441 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | *UHMC100ACV4 | 23,600 | $1,180 |
| No | 210649644 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | *UD2C100B9V5+RP | 23,600 | $1,180 |
| No | 201922440 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | *UD2C100ACV5 | 23,600 | $1,180 |
| No | 210649641 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | *UD2C100A9V5+RP | 23,600 | $1,180 |
| No | 210649642 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | *UD2C080B9V4+RP | 23,600 | $1,180 |
| No | 201922439 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | *UD2C080ACV4 | 23,600 | $1,180 |
| No | 210649643 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | *UD2C080A9V4+RP | 23,200 | $1,160 |
| No | 201922443 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | *DHMC100ACV4 | 23,400 | $1,170 |
| No | 201922444 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | *DD2C100ACV5 | 23,400 | $1,170 |
| No | 210649645 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | *DD2C100A9V5+RP | 23,000 | $1,150 |
| No | 207805203 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3+P0V0B000M40SC+RP | N/A | 22,400 | $1,120 |
| No | 207805202 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3+P0V0A000M30SC+RP | N/A | 22,000 | $1,100 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204433498 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | S9V2B080U4VSA+RP | 23,400 | $1,170 |
| No | 210652883 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | S9V2B080U4PSB+RP | 23,400 | $1,170 |
| No | 208106939 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | S9V2B080D4VSA+RP | 23,000 | $1,150 |
| No | 210652879 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | S9V2B080D4PSB+RP | 23,000 | $1,150 |
| No | 207062443 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | S9V2B080D3VSA+RP | 23,000 | $1,150 |
| No | 210652880 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | S9V2B080D3PSB+RP | 23,000 | $1,150 |
| No | 203334082 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | S9V2B060U4PSB+RP | 23,600 | $1,180 |
| No | 210652884 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | S9V2B060U3VSA+RP | 23,600 | $1,180 |
| No | 205805507 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | S9V2B060U3PSB+RP | 23,600 | $1,180 |
| No | 210652881 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | S9V2B060D3PSB+RP | 23,000 | $1,150 |
| No | 210652885 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | S9V2B040U3VSA+RP | 23,600 | $1,180 |
| No | 205807174 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | S9V2B040U3PSB+RP | 23,200 | $1,160 |
| No | 210652882 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | S9V2B040D3PSB+RP | 23,200 | $1,160 |
| No | 211081330 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | S8V2B080M4PDA | 23,800 | $1,190 |
| No | 210691970 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | S8V2B080M4PCA | 23,800 | $1,190 |
| No | 211081331 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | S8V2B060M4PDA | 23,600 | $1,180 |
| No | 210691969 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | S8V2B060M4PCA | 23,600 | $1,180 |
| No | 211081329 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | S8V2A040M3PDA | 22,800 | $1,140 |
| No | 210691968 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | S8V2A040M3PCA | 22,800 | $1,140 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210652886 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | L8V1B080U4VSA+RP | 23,600 | $1,180 |
| No | 210652887 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | L8V1A060U3VSA+RP | 22,800 | $1,140 |
| No | 210652888 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | L8V1A040U3VSA+RP | 22,800 | $1,140 |
| No | 206392933 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | *UHMB080ACV3 | 23,400 | $1,170 |
| No | 210652889 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | *UHMB060ACV3 | 23,800 | $1,190 |
| No | 205070222 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | *UD2B080ACV3 | 23,800 | $1,190 |
| No | 210649640 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | *UD2B080A9V3+RP | 23,200 | $1,160 |
| No | 207062437 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | *UD2B060ACV3 | 23,800 | $1,190 |
| No | 210649639 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | *UD2B060A9V3+RP | 23,400 | $1,170 |
| No | 201922437 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | *DHMB080ACV3 | 23,000 | $1,150 |
| No | 201922434 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | *DHMB060BCV3 | 23,200 | $1,160 |
| No | 201922435 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | *DD2B080ACV3 | 23,000 | $1,150 |
| No | 210649638 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | *DD2B080A9V3+RP | 22,800 | $1,140 |
| No | 201922436 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | *DD2B060ACV3 | 23,400 | $1,170 |
| No | 210649637 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | *DD2B060A9V3+RP | 23,000 | $1,150 |
| No | 207805201 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3+P0V0B000M40SC+RP | N/A | 22,800 | $1,140 |
| No | 207805200 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3+P0V0A000M30SC+RP | N/A | 22,200 | $1,110 |
| No | 204433495 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | S9V2B080U4VSA+RP | 23,600 | $1,180 |
| No | 210652878 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | S9V2B080U4PSB+RP | 23,600 | $1,180 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208106938 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | S9V2B080D4VSA+RP | 23,000 | $1,150 |
| No | 204013232 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | S9V2B080D4PSB+RP | 23,200 | $1,160 |
| No | 210652874 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | S9V2B080D3VSA+RP | 23,200 | $1,160 |
| No | 201922430 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | S9V2B080D3PSB+RP | 23,200 | $1,160 |
| No | 207782124 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | S9V2B060U4PSB+RP | 23,600 | $1,180 |
| No | 207063277 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | S9V2B060U3VSA+RP | 23,600 | $1,180 |
| No | 205805505 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | S9V2B060U3PSB+RP | 23,600 | $1,180 |
| No | 202382481 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | S9V2B060D3PSB+RP | 23,200 | $1,160 |
| No | 207062441 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | S9V2B040U3VSA+RP | 23,800 | $1,190 |
| No | 205807176 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | S9V2B040U3PSB+RP | 23,600 | $1,180 |
| No | 210652873 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | S9V2B040D3PSB+RP | 23,200 | $1,160 |
| No | 211081328 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | S8V2B080M4PDA | 24,000 | $1,200 |
| No | 210691966 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | S8V2B080M4PCA | 24,000 | $1,200 |
| No | 211081327 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | S8V2B060M4PDA | 23,800 | $1,190 |
| No | 210691967 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | S8V2B060M4PCA | 23,800 | $1,190 |
| No | 211081326 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | S8V2A040M3PDA | 23,000 | $1,150 |
| No | 210691965 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | S8V2A040M3PCA | 23,000 | $1,150 |
| No | 210652877 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | L8V1B080U4VSA+RP | 24,000 | $1,200 |
| No | 210652876 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | L8V1A060U3VSA+RP | 22,800 | $1,140 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210652875 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | L8V1A040U3VSA+RP | 23,000 | $1,150 |
| No | 206392935 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | *UHMB080ACV3 | 23,600 | $1,180 |
| No | 204431311 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | *UHMB060ACV3 | 23,800 | $1,190 |
| No | 205070221 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | *UD2B080ACV3 | 23,800 | $1,190 |
| No | 210649634 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | *UD2B080A9V3+RP | 23,400 | $1,170 |
| No | 201922431 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | *UD2B060ACV3 | 24,000 | $1,200 |
| No | 210649635 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | *UD2B060A9V3+RP | 23,600 | $1,180 |
| No | 201922429 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | *DHMB080ACV3 | 23,200 | $1,160 |
| No | 201922428 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | *DHMB060BCV3 | 23,400 | $1,170 |
| No | 201922432 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | *DD2B080ACV3 | 23,200 | $1,160 |
| No | 210649636 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | *DD2B080A9V3+RP | 23,000 | $1,150 |
| No | 201922433 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | *DD2B060ACV3 | 23,400 | $1,170 |
| No | 210649633 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | *DD2B060A9V3+RP | 23,200 | $1,160 |
| No | 211081325 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*DU60BS3 | S8V2D120M5PDA | 23,200 | $1,160 |
| No | 210691964 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*DU60BS3 | S8V2D120M5PCA | 23,200 | $1,160 |
| No | 210649632 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*DU60BS3 | *UD2D120A9V5+RP | 23,400 | $1,170 |
| No | 211081324 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*DU48BS3 | S8V2D120M5PDA | 23,600 | $1,180 |
| No | 210691963 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*DU48BS3 | S8V2D120M5PCA | 23,600 | $1,180 |
| No | 210649630 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*DU48BS3 | *UD2D120A9V5+RP | 23,600 | $1,180 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210649631 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*DU48BS3 | *DD2D120A9V5+RP | 22,600 | $1,130 |
| No | 210649629 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*DD60BS3+HORIZ-RT | *UD2D120A9V5+RP | 23,400 | $1,170 |
| No | 211081323 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*DD60BS3 | S8V2D120M5PDA | 23,400 | $1,170 |
| No | 210691962 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*DD60BS3 | S8V2D120M5PCA | 23,400 | $1,170 |
| No | 210649628 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*DD60BS3 | *DD2D120A9V5+RP | 23,200 | $1,160 |
| No | 210652872 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU60BS3 | S9V2C100U4VSA+RP | 23,000 | $1,150 |
| No | 210652871 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU60BS3 | S9V2C100U4PSB+RP | 23,000 | $1,150 |
| No | 211081322 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU60BS3 | S8V2C100M5PDA | 23,200 | $1,160 |
| No | 210691961 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU60BS3 | S8V2C100M5PCA | 23,200 | $1,160 |
| No | 211081321 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU60BS3 | S8V2C080M5PDA | 23,200 | $1,160 |
| No | 210691960 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU60BS3 | S8V2C080M5PCA | 23,200 | $1,160 |
| No | 210652870 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU60BS3 | L8V1C100U5VSA+RP | 23,200 | $1,160 |
| No | 210649627 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU60BS3 | *UD2C100B9V5+RP | 23,200 | $1,160 |
| No | 201922407 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU60BS3 | *UD2C100ACV5 | 23,200 | $1,160 |
| No | 210649626 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU60BS3 | *UD2C100A9V5+RP | 23,200 | $1,160 |
| No | 210649625 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU60BS3 | *UD2C080B9V4+RP | 23,200 | $1,160 |
| No | 201922409 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU60BS3 | *UD2C080ACV4 | 23,200 | $1,160 |
| No | 210649624 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU60BS3 | *UD2C080A9V4+RP | 23,600 | $1,180 |
| No | 210652869 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU48BS3 | S9V2C100U4VSA+RP | 23,400 | $1,170 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922405 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU48BS3 | S9V2C100U4PSB+RP | 23,200 | $1,160 |
| No | 210652864 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU48BS3 | S9V2C100D4VSA+RP | 22,800 | $1,140 |
| No | 210652865 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU48BS3 | S9V2C100D4PSB+RP | 22,800 | $1,140 |
| No | 211081320 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU48BS3 | S8V2C100M5PDA | 23,600 | $1,180 |
| No | 210691959 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU48BS3 | S8V2C100M5PCA | 23,600 | $1,180 |
| No | 211081319 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU48BS3 | S8V2C080M5PDA | 23,400 | $1,170 |
| No | 210691958 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU48BS3 | S8V2C080M5PCA | 23,400 | $1,170 |
| No | 210652866 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU48BS3 | L8V1C100U5VSA+RP | 23,400 | $1,170 |
| No | 201922400 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU48BS3 | *UHMC100ACV4 | 23,400 | $1,170 |
| No | 210649622 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU48BS3 | *UD2C100B9V5+RP | 23,400 | $1,170 |
| No | 201922406 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU48BS3 | *UD2C100ACV5 | 23,600 | $1,180 |
| No | 210649619 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU48BS3 | *UD2C100A9V5+RP | 23,600 | $1,180 |
| No | 210649620 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU48BS3 | *UD2C080B9V4+RP | 23,400 | $1,170 |
| No | 201922398 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU48BS3 | *UD2C080ACV4 | 23,400 | $1,170 |
| No | 210649621 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU48BS3 | *UD2C080A9V4+RP | 23,400 | $1,170 |
| No | 210652868 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU48BS3 | *DHMC100ACV4 | 23,000 | $1,150 |
| No | 210652867 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU48BS3 | *DD2C100ACV5 | 23,000 | $1,150 |
| No | 210649623 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU48BS3 | *DD2C100A9V5+RP | 22,800 | $1,140 |
| No | 210652863 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU42BS3 | S9V2C100U4VSA+RP | 23,600 | $1,180 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922386 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU42BS3 | S9V2C100U4PSB+RP | 23,400 | $1,170 |
| No | 210652861 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU42BS3 | S9V2C100D4VSA+RP | 22,800 | $1,140 |
| No | 210652860 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU42BS3 | S9V2C100D4PSB+RP | 22,800 | $1,140 |
| No | 211081318 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU42BS3 | S8V2C100M5PDA | 23,800 | $1,190 |
| No | 210691957 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU42BS3 | S8V2C100M5PCA | 23,800 | $1,190 |
| No | 211081317 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU42BS3 | S8V2C080M5PDA | 23,600 | $1,180 |
| No | 210691956 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU42BS3 | S8V2C080M5PCA | 23,600 | $1,180 |
| No | 210652862 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU42BS3 | L8V1C100U5VSA+RP | 23,600 | $1,180 |
| No | 201922392 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU42BS3 | *UHMC100ACV4 | 23,400 | $1,170 |
| No | 210649617 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU42BS3 | *UD2C100B9V5+RP | 23,600 | $1,180 |
| No | 201922393 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU42BS3 | *UD2C100ACV5 | 23,800 | $1,190 |
| No | 210649616 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU42BS3 | *UD2C100A9V5+RP | 23,400 | $1,170 |
| No | 210649615 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU42BS3 | *UD2C080B9V4+RP | 23,600 | $1,180 |
| No | 201922394 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU42BS3 | *UD2C080ACV4 | 23,400 | $1,170 |
| No | 210649614 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU42BS3 | *UD2C080A9V4+RP | 23,600 | $1,180 |
| No | 202586181 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU42BS3 | *DHMC100ACV4 | 23,200 | $1,160 |
| No | 202586180 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU42BS3 | *DD2C100ACV5 | 23,000 | $1,150 |
| No | 210649618 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU42BS3 | *DD2C100A9V5+RP | 22,800 | $1,140 |
| No | 210652858 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | S9V2C100U4VSA+RP | 23,200 | $1,160 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922374 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | S9V2C100U4PSB+RP | 23,400 | $1,170 |
| No | 210652854 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | S9V2C100D4VSA+RP | 23,200 | $1,160 |
| No | 210652855 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | S9V2C100D4PSB+RP | 23,000 | $1,150 |
| No | 211081316 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | S8V2C100M5PDA | 23,800 | $1,190 |
| No | 210691955 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | S8V2C100M5PCA | 23,800 | $1,190 |
| No | 211081315 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | S8V2C080M5PDA | 23,600 | $1,180 |
| No | 210691954 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | S8V2C080M5PCA | 23,600 | $1,180 |
| No | 210652859 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | L8V1C100U5VSA+RP | 23,400 | $1,170 |
| No | 201922380 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | *UHMC100ACV4 | 23,400 | $1,170 |
| No | 210649612 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | *UD2C100B9V5+RP | 23,600 | $1,180 |
| No | 201922381 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | *UD2C100ACV5 | 23,600 | $1,180 |
| No | 210649609 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | *UD2C100A9V5+RP | 23,600 | $1,180 |
| No | 210649610 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | *UD2C080B9V4+RP | 23,600 | $1,180 |
| No | 201922382 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | *UD2C080ACV4 | 23,600 | $1,180 |
| No | 210649611 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | *UD2C080A9V4+RP | 23,200 | $1,160 |
| No | 210652856 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | *DHMC100ACV4 | 23,600 | $1,180 |
| No | 210652857 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | *DD2C100ACV5 | 23,400 | $1,170 |
| No | 210649613 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | *DD2C100A9V5+RP | 23,000 | $1,150 |
| No | 210649606 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD60BS3+HORIZ-RT | *UD2C100B9V5+RP | 23,000 | $1,150 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922371 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD60BS3+HORIZ-RT | *UD2C100ACV5 | 23,000 | $1,150 |
| No | 210649607 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD60BS3+HORIZ-RT | *UD2C100A9V5+RP | 23,200 | $1,160 |
| No | 210649608 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD60BS3+HORIZ-RT | *UD2C080B9V4+RP | 22,800 | $1,140 |
| No | 201922372 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD60BS3+HORIZ-RT | *UD2C080ACV4 | 23,200 | $1,160 |
| No | 210649605 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD60BS3+HORIZ-RT | *UD2C080A9V4+RP | 23,200 | $1,160 |
| No | 210652853 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD60BS3 | S9V2C100D4VSA+RP | 22,800 | $1,140 |
| No | 210652852 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD60BS3 | S9V2C100D4PSB+RP | 23,000 | $1,150 |
| No | 211081314 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD60BS3 | S8V2C100M5PDA | 23,200 | $1,160 |
| No | 210691953 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD60BS3 | S8V2C100M5PCA | 23,200 | $1,160 |
| No | 211081313 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD60BS3 | S8V2C080M5PDA | 23,000 | $1,150 |
| No | 210691952 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD60BS3 | S8V2C080M5PCA | 23,000 | $1,150 |
| No | 201922369 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD60BS3 | *DHMC100ACV4 | 23,200 | $1,160 |
| No | 201922370 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD60BS3 | *DD2C100ACV5 | 23,000 | $1,150 |
| No | 210649604 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD60BS3 | *DD2C100A9V5+RP | 23,000 | $1,150 |
| No | 210649603 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD42BS3+HORIZ-RT | *UD2C100B9V5+RP | 23,400 | $1,170 |
| No | 210652851 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD42BS3+HORIZ-RT | *UD2C100ACV5 | 23,600 | $1,180 |
| No | 210649602 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD42BS3+HORIZ-RT | *UD2C100A9V5+RP | 23,600 | $1,180 |
| No | 210649601 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD42BS3+HORIZ-RT | *UD2C080B9V4+RP | 23,400 | $1,170 |
| No | 210652850 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD42BS3+HORIZ-RT | *UD2C080ACV4 | 23,600 | $1,180 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210649600 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD42BS3+HORIZ-RT | *UD2C080A9V4+RP | 23,600 | $1,180 |
| No | 210652849 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD42BS3 | S9V2C100D4VSA+RP | 23,400 | $1,170 |
| No | 201922348 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD42BS3 | S9V2C100D4PSB+RP | 23,400 | $1,170 |
| No | 211081312 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD42BS3 | S8V2C100M5PDA | 23,600 | $1,180 |
| No | 210691951 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD42BS3 | S8V2C100M5PCA | 23,600 | $1,180 |
| No | 211081311 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD42BS3 | S8V2C080M5PDA | 23,600 | $1,180 |
| No | 210691950 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD42BS3 | S8V2C080M5PCA | 23,600 | $1,180 |
| No | 201922345 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD42BS3 | *DHMC100ACV4 | 23,600 | $1,180 |
| No | 201922346 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD42BS3 | *DD2C100ACV5 | 23,600 | $1,180 |
| No | 210649599 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD42BS3 | *DD2C100A9V5+RP | 23,400 | $1,170 |
| No | 210649598 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD36BS3+HORIZ-RT | *UD2C100B9V5+RP | 23,800 | $1,190 |
| No | 201922340 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD36BS3+HORIZ-RT | *UD2C100ACV5 | 23,800 | $1,190 |
| No | 210649597 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD36BS3+HORIZ-RT | *UD2C100A9V5+RP | 23,600 | $1,180 |
| No | 210649595 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD36BS3+HORIZ-RT | *UD2C080B9V4+RP | 23,800 | $1,190 |
| No | 201922339 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD36BS3+HORIZ-RT | *UD2C080ACV4 | 23,800 | $1,190 |
| No | 210649596 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD36BS3+HORIZ-RT | *UD2C080A9V4+RP | 23,800 | $1,190 |
| No | 201922336 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD36BS3 | S9V2C100D4PSB+RP | 23,600 | $1,180 |
| No | 211081310 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD36BS3 | S8V2C100M5PDA | 24,000 | $1,200 |
| No | 210691949 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD36BS3 | S8V2C100M5PCA | 24,000 | $1,200 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211081309 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD36BS3 | S8V2C080M5PDA | 23,800 | $1,190 |
| No | 210691948 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD36BS3 | S8V2C080M5PCA | 23,800 | $1,190 |
| No | 210652848 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD36BS3 | *DHMC100ACV4 | 24,000 | $1,200 |
| No | 210652847 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD36BS3 | *DD2C100ACV5 | 24,000 | $1,200 |
| No | 210649594 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD36BS3 | *DD2C100A9V5+RP | 23,200 | $1,160 |
| No | 207805199 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3+P0V0B000M40SC+RP | N/A | 22,600 | $1,130 |
| No | 207805198 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3+P0V0A000M30SC+RP | N/A | 22,000 | $1,100 |
| No | 210652830 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | S9V2B080U4VSA+RP | 23,400 | $1,170 |
| No | 210652846 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | S9V2B080U4PSB+RP | 23,400 | $1,170 |
| No | 208106936 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | S9V2B080D4VSA+RP | 22,800 | $1,140 |
| No | 210652836 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | S9V2B080D4PSB+RP | 23,000 | $1,150 |
| No | 210652835 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | S9V2B080D3VSA+RP | 23,000 | $1,150 |
| No | 210652834 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | S9V2B080D3PSB+RP | 23,000 | $1,150 |
| No | 210652828 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | S9V2B060U4PSB+RP | 23,600 | $1,180 |
| No | 210652837 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | S9V2B060U3VSA+RP | 23,600 | $1,180 |
| No | 210652838 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | S9V2B060U3PSB+RP | 23,600 | $1,180 |
| No | 210652833 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | S9V2B060D3PSB+RP | 23,000 | $1,150 |
| No | 210652839 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | S9V2B040U3VSA+RP | 23,600 | $1,180 |
| No | 210652840 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | S9V2B040U3PSB+RP | 23,600 | $1,180 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210652832 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | S9V2B040D3PSB+RP | 23,000 | $1,150 |
| No | 211081307 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | S8V2B080M4PDA | 23,800 | $1,190 |
| No | 210691947 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | S8V2B080M4PCA | 23,800 | $1,190 |
| No | 211081308 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | S8V2B060M4PDA | 23,800 | $1,190 |
| No | 210691946 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | S8V2B060M4PCA | 23,800 | $1,190 |
| No | 211081306 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | S8V2A040M3PDA | 22,800 | $1,140 |
| No | 210691945 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | S8V2A040M3PCA | 22,800 | $1,140 |
| No | 210652841 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | L8V1B080U4VSA+RP | 23,800 | $1,190 |
| No | 210652842 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | L8V1A060U3VSA+RP | 22,800 | $1,140 |
| No | 210652843 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | L8V1A040U3VSA+RP | 22,800 | $1,140 |
| No | 210652844 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | *UHMB080ACV3 | 23,600 | $1,180 |
| No | 210652845 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | *UHMB060ACV3 | 23,800 | $1,190 |
| No | 205070219 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | *UD2B080ACV3 | 23,600 | $1,180 |
| No | 210649590 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | *UD2B080A9V3+RP | 23,200 | $1,160 |
| No | 210652829 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | *UD2B060ACV3 | 23,800 | $1,190 |
| No | 210649591 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | *UD2B060A9V3+RP | 23,400 | $1,170 |
| No | 202544294 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | *DHMB080ACV3 | 23,000 | $1,150 |
| No | 202544295 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | *DHMB060BCV3 | 23,200 | $1,160 |
| No | 210652831 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | *DD2B080ACV3 | 23,000 | $1,150 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210649593 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | *DD2B080A9V3+RP | 22,800 | $1,140 |
| No | 206214527 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | *DD2B060ACV3 | 23,200 | $1,160 |
| No | 210649592 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | *DD2B060A9V3+RP | 23,000 | $1,150 |
| No | 207805197 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3+P0V0B000M40SC+RP | N/A | 23,000 | $1,150 |
| No | 207805196 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3+P0V0A000M30SC+RP | N/A | 22,200 | $1,110 |
| No | 210652807 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | S9V2B080U4VSA+RP | 23,600 | $1,180 |
| No | 210652818 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | S9V2B080U4PSB+RP | 23,600 | $1,180 |
| No | 210652817 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | S9V2B080D4VSA+RP | 23,000 | $1,150 |
| No | 210652816 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | S9V2B080D4PSB+RP | 23,000 | $1,150 |
| No | 210652815 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | S9V2B080D3VSA+RP | 23,000 | $1,150 |
| No | 210652814 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | S9V2B080D3PSB+RP | 23,000 | $1,150 |
| No | 210652805 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | S9V2B060U4PSB+RP | 23,800 | $1,190 |
| No | 210652806 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | S9V2B060U3VSA+RP | 23,600 | $1,180 |
| No | 210652819 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | S9V2B060U3PSB+RP | 23,600 | $1,180 |
| No | 210652813 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | S9V2B060D3PSB+RP | 23,000 | $1,150 |
| No | 210652820 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | S9V2B040U3VSA+RP | 23,800 | $1,190 |
| No | 210652821 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | S9V2B040U3PSB+RP | 23,800 | $1,190 |
| No | 210652812 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | S9V2B040D3PSB+RP | 23,200 | $1,160 |
| No | 211081305 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | S8V2B080M4PDA | 24,000 | $1,200 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210691944 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | S8V2B080M4PCA | 24,000 | $1,200 |
| No | 211081304 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | S8V2B060M4PDA | 24,000 | $1,200 |
| No | 210691943 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | S8V2B060M4PCA | 24,000 | $1,200 |
| No | 211081303 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | S8V2A040M3PDA | 23,000 | $1,150 |
| No | 210691942 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | S8V2A040M3PCA | 23,000 | $1,150 |
| No | 210652822 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | L8V1B080U4VSA+RP | 23,800 | $1,190 |
| No | 210652823 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | L8V1A060U3VSA+RP | 23,000 | $1,150 |
| No | 210652824 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | L8V1A040U3VSA+RP | 23,000 | $1,150 |
| No | 210652825 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | *UHMB080ACV3 | 23,800 | $1,190 |
| No | 210652826 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | *UHMB060ACV3 | 23,800 | $1,190 |
| No | 205070217 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | *UD2B080ACV3 | 23,800 | $1,190 |
| No | 210649587 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | *UD2B080A9V3+RP | 23,600 | $1,180 |
| No | 210652827 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | *UD2B060ACV3 | 24,000 | $1,200 |
| No | 210649588 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | *UD2B060A9V3+RP | 23,600 | $1,180 |
| No | 210652811 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | *DHMB080ACV3 | 23,200 | $1,160 |
| No | 210652810 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | *DHMB060BCV3 | 23,000 | $1,150 |
| No | 210652809 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | *DD2B080ACV3 | 23,200 | $1,160 |
| No | 210649589 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | *DD2B080A9V3+RP | 22,800 | $1,140 |
| No | 210652808 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | *DD2B060ACV3 | 23,400 | $1,170 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210649586 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | *DD2B060A9V3+RP | 23,200 | $1,160 |
| No | 207805195 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3+P0V0B000M40SC+RP | N/A | 22,800 | $1,140 |
| No | 207805194 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3+P0V0A000M30SC+RP | N/A | 22,200 | $1,110 |
| No | 210652790 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | S9V2B080U4VSA+RP | 23,600 | $1,180 |
| No | 204013231 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | S9V2B080U4PSB+RP | 23,400 | $1,170 |
| No | 208106935 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | S9V2B080D4VSA+RP | 22,800 | $1,140 |
| No | 210652799 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | S9V2B080D4PSB+RP | 23,200 | $1,160 |
| No | 210652798 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | S9V2B080D3VSA+RP | 23,200 | $1,160 |
| No | 210652797 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | S9V2B080D3PSB+RP | 23,200 | $1,160 |
| No | 206901673 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | S9V2B060U4PSB+RP | 23,600 | $1,180 |
| No | 210652804 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | S9V2B060U3VSA+RP | 23,600 | $1,180 |
| No | 210652803 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | S9V2B060U3PSB+RP | 23,600 | $1,180 |
| No | 210652796 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | S9V2B060D3PSB+RP | 23,200 | $1,160 |
| No | 210652802 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | S9V2B040U3VSA+RP | 23,800 | $1,190 |
| No | 203297106 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | S9V2B040U3PSB+RP | 23,800 | $1,190 |
| No | 210652795 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | S9V2B040D3PSB+RP | 23,200 | $1,160 |
| No | 211081302 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | S8V2B080M4PDA | 24,000 | $1,200 |
| No | 210691941 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | S8V2B080M4PCA | 24,000 | $1,200 |
| No | 211081301 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | S8V2B060M4PDA | 24,000 | $1,200 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210691940 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | S8V2B060M4PCA | 24,000 | $1,200 |
| No | 211081300 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | S8V2A040M3PDA | 22,800 | $1,140 |
| No | 210691939 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | S8V2A040M3PCA | 22,800 | $1,140 |
| No | 210652801 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | L8V1B080U4VSA+RP | 24,000 | $1,200 |
| No | 210652800 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | L8V1A060U3VSA+RP | 23,000 | $1,150 |
| No | 210652792 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | L8V1A040U3VSA+RP | 22,800 | $1,140 |
| No | 208121976 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | *UHMB080ACV3 | 23,800 | $1,190 |
| No | 207335058 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | *UHMB060ACV3 | 23,800 | $1,190 |
| No | 205070215 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | *UD2B080ACV3 | 23,800 | $1,190 |
| No | 207783931 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | *UD2B080A9V3+RP | 23,200 | $1,160 |
| No | 201922334 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | *UD2B060ACV3 | 24,000 | $1,200 |
| No | 210649583 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | *UD2B060A9V3+RP | 23,600 | $1,180 |
| No | 206315459 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | *DHMB080ACV3 | 23,200 | $1,160 |
| No | 210652794 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | *DHMB060BCV3 | 23,400 | $1,170 |
| No | 210652793 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | *DD2B080ACV3 | 23,200 | $1,160 |
| No | 210649585 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | *DD2B080A9V3+RP | 23,000 | $1,150 |
| No | 210652791 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | *DD2B060ACV3 | 23,400 | $1,170 |
| No | 210649584 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | *DD2B060A9V3+RP | 23,200 | $1,160 |
| No | 211289068 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU30BS3 | *UD2B060ACV3 | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211289069 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU30BS3 | *DD2B060ACV3 | 24,200 | $1,210 |
| No | 207805189 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3+P0V0B000M40SC+RP | N/A | 22,800 | $1,140 |
| No | 207805188 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3+P0V0A000M30SC+RP | N/A | 22,200 | $1,110 |
| No | 210652787 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3+HORIZ-RT | *UD2B080ACV3 | 23,800 | $1,190 |
| No | 210649582 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3+HORIZ-RT | *UD2B080A9V3+RP | 23,400 | $1,170 |
| No | 210652786 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3+HORIZ-RT | *UD2B060ACV3 | 23,800 | $1,190 |
| No | 210649581 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3+HORIZ-RT | *UD2B060A9V3+RP | 23,600 | $1,180 |
| No | 208106933 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3 | S9V2B080D4VSA+RP | 23,600 | $1,180 |
| No | 210652779 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3 | S9V2B080D4PSB+RP | 23,600 | $1,180 |
| No | 210652780 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3 | S9V2B080D3VSA+RP | 23,600 | $1,180 |
| No | 210652781 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3 | S9V2B080D3PSB+RP | 23,600 | $1,180 |
| No | 210652782 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3 | S9V2B060D3PSB+RP | 23,600 | $1,180 |
| No | 210652785 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3 | S9V2B040D3PSB+RP | 23,800 | $1,190 |
| No | 211081299 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3 | S8V2B080M4PDA | 24,000 | $1,200 |
| No | 210691938 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3 | S8V2B080M4PCA | 24,000 | $1,200 |
| No | 211081298 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3 | S8V2B060M4PDA | 24,000 | $1,200 |
| No | 210691937 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3 | S8V2B060M4PCA | 24,000 | $1,200 |
| No | 211081297 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3 | S8V2A040M3PDA | 23,000 | $1,150 |
| No | 210691936 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3 | S8V2A040M3PCA | 23,000 | $1,150 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210652784 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3 | *DHMB080ACV3 | 23,600 | $1,180 |
| No | 210652783 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3 | *DHMB060BCV3 | 23,800 | $1,190 |
| No | 201922329 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3 | *DD2B080ACV3 | 23,600 | $1,180 |
| No | 210649580 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3 | *DD2B080A9V3+RP | 23,400 | $1,170 |
| No | 201922331 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3 | *DD2B060ACV3 | 24,000 | $1,200 |
| No | 210649579 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3 | *DD2B060A9V3+RP | 23,400 | $1,170 |
| No | 207805186 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3+P0V0B000M40SC+RP | N/A | 23,000 | $1,150 |
| No | 207805185 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3+P0V0A000M30SC+RP | N/A | 22,600 | $1,130 |
| No | 201922313 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3+HORIZ-RT | *UD2B080ACV3 | 24,000 | $1,200 |
| No | 210649578 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3+HORIZ-RT | *UD2B080A9V3+RP | 24,000 | $1,200 |
| No | 201922312 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3+HORIZ-RT | *UD2B060ACV3 | 24,200 | $1,210 |
| No | 210649577 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3+HORIZ-RT | *UD2B060A9V3+RP | 23,800 | $1,190 |
| No | 208106932 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3 | S9V2B080D4VSA+RP | 23,600 | $1,180 |
| No | 201922308 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3 | S9V2B080D4PSB+RP | 23,800 | $1,190 |
| No | 210652778 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3 | S9V2B080D3VSA+RP | 23,800 | $1,190 |
| No | 201922304 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3 | S9V2B080D3PSB+RP | 23,800 | $1,190 |
| No | 201922303 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3 | S9V2B060D3PSB+RP | 23,800 | $1,190 |
| No | 201922301 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3 | S9V2B040D3PSB+RP | 24,000 | $1,200 |
| No | 211081295 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3 | S8V2B080M4PDA | 24,200 | $1,210 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210691935 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3 | S8V2B080M4PCA | 24,200 | $1,210 |
| No | 211081294 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3 | S8V2B060M4PDA | 24,000 | $1,200 |
| No | 210691934 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3 | S8V2B060M4PCA | 24,000 | $1,200 |
| No | 211081296 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3 | S8V2A040M3PDA | 23,000 | $1,150 |
| No | 210691933 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3 | S8V2A040M3PCA | 23,000 | $1,150 |
| No | 201922302 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3 | *DHMB080ACV3 | 24,000 | $1,200 |
| No | 201922309 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3 | *DHMB060BCV3 | 24,000 | $1,200 |
| No | 201922306 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3 | *DD2B080ACV3 | 23,800 | $1,190 |
| No | 210649575 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3 | *DD2B080A9V3+RP | 23,600 | $1,180 |
| No | 201922307 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3 | *DD2B060ACV3 | 24,200 | $1,210 |
| No | 210649576 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3 | *DD2B060A9V3+RP | 23,600 | $1,180 |
| No | 201922925 | AMERICAN STANDARD | 4A6L9024A1 | TEM8A0B30V31+TDR | N/A | 14,200 | $710 |
| No | 201923080 | AMERICAN STANDARD | 4A6L9024A1 | TEM8A0B24V21+TDR | N/A | 14,100 | $705 |
| No | 201922924 | AMERICAN STANDARD | 4A6L9024A1 | TAM9A0C36V31 | N/A | 13,600 | $680 |
| No | 201978189 | AMERICAN STANDARD | 4A6L9024A1 | TAM9A0A24V21 | N/A | 14,100 | $705 |
| No | 207805184 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3+P0V0A000M30SC+RP | N/A | 13,300 | $665 |
| No | 210652774 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | S9V2B080D3VSA+RP | 13,800 | $690 |
| No | 201922893 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | S9V2B080D3PSB+RP | 13,800 | $690 |
| No | 207782114 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | S9V2B060U4PSB+RP | 14,200 | $710 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206909921 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | S9V2B060U3VSA+RP | 14,300 | $715 |
| No | 201923051 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | S9V2B060U3PSB+RP | 14,200 | $710 |
| No | 201923052 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | S9V2B060D3PSB+RP | 13,800 | $690 |
| No | 207062439 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | S9V2B040U3VSA+RP | 14,300 | $715 |
| No | 201923050 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | S9V2B040U3PSB+RP | 14,300 | $715 |
| No | 201922890 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | S9V2B040D3PSB+RP | 13,900 | $695 |
| No | 211089027 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | S8V2B080M4PDA | 14,400 | $720 |
| No | 210692207 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | S8V2B080M4PCA | 14,400 | $720 |
| No | 211081293 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | S8V2B060M4PDA | 14,400 | $720 |
| No | 210691932 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | S8V2B060M4PCA | 14,400 | $720 |
| No | 211089026 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | S8V2A040M3PDA | 13,700 | $685 |
| No | 210692206 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | S8V2A040M3PCA | 13,700 | $685 |
| No | 210652777 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | L8V1B080U4VSA+RP | 14,300 | $715 |
| No | 210652776 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | L8V1A060U3VSA+RP | 13,800 | $690 |
| No | 210652775 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | L8V1A040U3VSA+RP | 14,000 | $700 |
| No | 201922297 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | *UHMB080ACV3 | 14,100 | $705 |
| No | 201922296 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | *UHMB060ACV3 | 14,200 | $710 |
| No | 210649572 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | *UD2B080A9V3+RP | 14,000 | $700 |
| No | 210649571 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | *UD2B060A9V3+RP | 14,000 | $700 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922891 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | *DHMB080ACV3 | 13,900 | $695 |
| No | 201922888 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | *DHMB060BCV3 | 13,900 | $695 |
| No | 210649574 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | *DD2B080A9V3+RP | 13,300 | $665 |
| No | 201922887 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | *DD2B060ACV3 | 14,000 | $700 |
| No | 210649573 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | *DD2B060A9V3+RP | 13,500 | $675 |
| No | 211081292 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCA002DS3 | S8V2A040M3PDA | 14,500 | $725 |
| No | 210691931 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCA002DS3 | S8V2A040M3PCA | 14,500 | $725 |
| No | 210652773 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCA002DS3 | L8V1A060U3VSA+RP | 14,700 | $735 |
| No | 210652772 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU42BS3 | S9V2B060U4PSB+RP | 13,800 | $690 |
| No | 210652771 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU42BS3 | S9V2B060U3VSA+RP | 13,700 | $685 |
| No | 201922873 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU42BS3 | S9V2B060U3PSB+RP | 13,700 | $685 |
| No | 201923042 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU42BS3 | S9V2B040U3PSB+RP | 13,800 | $690 |
| No | 211089025 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU42BS3 | S8V2A040M3PDA | 13,400 | $670 |
| No | 210692205 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU42BS3 | S8V2A040M3PCA | 13,400 | $670 |
| No | 210649570 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU42BS3 | *UD2B080A9V3+RP | 13,500 | $675 |
| No | 210649569 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU42BS3 | *UD2B060A9V3+RP | 13,600 | $680 |
| No | 207805182 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3+P0V0A000M30SC+RP | N/A | 13,300 | $665 |
| No | 210652761 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | S9V2B080D3VSA+RP | 13,800 | $690 |
| No | 210652764 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | S9V2B080D3PSB+RP | 13,800 | $690 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207782113 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | S9V2B060U4PSB+RP | 14,000 | $700 |
| No | 210652766 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | S9V2B060U3VSA+RP | 14,200 | $710 |
| No | 201923036 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | S9V2B060U3PSB+RP | 14,200 | $710 |
| No | 210652763 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | S9V2B060D3PSB+RP | 13,800 | $690 |
| No | 210652770 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | S9V2B040U3VSA+RP | 14,300 | $715 |
| No | 201923035 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | S9V2B040U3PSB+RP | 14,100 | $705 |
| No | 210652762 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | S9V2B040D3PSB+RP | 13,900 | $695 |
| No | 211089023 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | S8V2B080M4PDA | 14,300 | $715 |
| No | 210692204 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | S8V2B080M4PCA | 14,300 | $715 |
| No | 211081291 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | S8V2B060M4PDA | 14,400 | $720 |
| No | 210691930 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | S8V2B060M4PCA | 14,400 | $720 |
| No | 211089024 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | S8V2A040M3PDA | 13,800 | $690 |
| No | 210692203 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | S8V2A040M3PCA | 13,800 | $690 |
| No | 210652769 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | L8V1B080U4VSA+RP | 14,200 | $710 |
| No | 210652768 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | L8V1A060U3VSA+RP | 13,900 | $695 |
| No | 210652767 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | L8V1A040U3VSA+RP | 14,000 | $700 |
| No | 201922293 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | *UHMB080ACV3 | 14,100 | $705 |
| No | 201922292 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | *UHMB060ACV3 | 14,000 | $700 |
| No | 210649566 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | *UD2B080A9V3+RP | 14,000 | $700 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210649565 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | *UD2B060A9V3+RP | 14,000 | $700 |
| No | 210652765 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | *DHMB060BCV3 | 13,900 | $695 |
| No | 210649568 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | *DD2B080A9V3+RP | 13,300 | $665 |
| No | 210649567 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | *DD2B060A9V3+RP | 13,500 | $675 |
| No | 210652758 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU24BS3 | S9V2B080D3VSA+RP | 14,300 | $715 |
| No | 207782112 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU24BS3 | S9V2B060U4PSB+RP | 14,300 | $715 |
| No | 210652760 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU24BS3 | S9V2B060U3VSA+RP | 14,300 | $715 |
| No | 201923033 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU24BS3 | S9V2B060U3PSB+RP | 14,300 | $715 |
| No | 210652757 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU24BS3 | S9V2B060D3PSB+RP | 14,300 | $715 |
| No | 210652759 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU24BS3 | S9V2B040U3VSA+RP | 14,400 | $720 |
| No | 201923034 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU24BS3 | S9V2B040U3PSB+RP | 14,400 | $720 |
| No | 210652756 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU24BS3 | S9V2B040D3PSB+RP | 14,400 | $720 |
| No | 211089022 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU24BS3 | S8V2A040M3PDA | 13,900 | $695 |
| No | 210692202 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU24BS3 | S8V2A040M3PCA | 13,900 | $695 |
| No | 210652752 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU24BS3 | L8V1B080U4VSA+RP | 14,400 | $720 |
| No | 210652753 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU24BS3 | L8V1A060U3VSA+RP | 14,100 | $705 |
| No | 210652754 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU24BS3 | L8V1A040U3VSA+RP | 14,100 | $705 |
| No | 201922284 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU24BS3 | *UHMB080ACV3 | 14,200 | $710 |
| No | 201922285 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU24BS3 | *UHMB060ACV3 | 14,300 | $715 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210649561 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU24BS3 | *UD2B080A9V3+RP | 14,300 | $715 |
| No | 210649562 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU24BS3 | *UD2B060A9V3+RP | 14,300 | $715 |
| No | 210652755 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU24BS3 | *DHMB080ACV3 | 14,400 | $720 |
| No | 210649564 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU24BS3 | *DD2B080A9V3+RP | 14,300 | $715 |
| No | 210649563 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU24BS3 | *DD2B060A9V3+RP | 14,200 | $710 |
| No | 210649560 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD36BS3+HORIZ-RT | *UD2B080A9V3+RP | 13,400 | $670 |
| No | 210649559 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD36BS3+HORIZ-RT | *UD2B060A9V3+RP | 13,700 | $685 |
| No | 210652751 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD36BS3 | S9V2B080D3VSA+RP | 13,700 | $685 |
| No | 201923013 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD36BS3 | S9V2B080D3PSB+RP | 13,700 | $685 |
| No | 201923012 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD36BS3 | S9V2B060D3PSB+RP | 13,600 | $680 |
| No | 211089021 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD36BS3 | S8V2B060M4PDA | 13,900 | $695 |
| No | 210692201 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD36BS3 | S8V2B060M4PCA | 13,900 | $695 |
| No | 211081290 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD36BS3 | S8V2A040M3PDA | 13,300 | $665 |
| No | 210691929 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD36BS3 | S8V2A040M3PCA | 13,300 | $665 |
| No | 201922277 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD36BS3 | *DHMB060BCV3 | 13,700 | $685 |
| No | 210649558 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD36BS3 | *DD2B080A9V3+RP | 13,400 | $670 |
| No | 210649557 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD36BS3 | *DD2B060A9V3+RP | 13,400 | $670 |
| No | 207805180 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD30BS3+P0V0A000M30SC+RP | N/A | 13,300 | $665 |
| No | 210649556 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD30BS3+HORIZ-RT | *UD2B080A9V3+RP | 14,000 | $700 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210649555 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD30BS3+HORIZ-RT | *UD2B060A9V3+RP | 14,000 | $700 |
| No | 210652750 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD30BS3 | S9V2B080D3VSA+RP | 14,200 | $710 |
| No | 201922851 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD30BS3 | S9V2B080D3PSB+RP | 14,000 | $700 |
| No | 201922852 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD30BS3 | S9V2B060D3PSB+RP | 14,100 | $705 |
| No | 201922853 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD30BS3 | S9V2B040D3PSB+RP | 14,200 | $710 |
| No | 211089018 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD30BS3 | S8V2B080M4PDA | 14,400 | $720 |
| No | 210692200 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD30BS3 | S8V2B080M4PCA | 14,400 | $720 |
| No | 211089020 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD30BS3 | S8V2B060M4PDA | 14,400 | $720 |
| No | 210692199 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD30BS3 | S8V2B060M4PCA | 14,400 | $720 |
| No | 211089019 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD30BS3 | S8V2A040M3PDA | 13,800 | $690 |
| No | 210692198 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD30BS3 | S8V2A040M3PCA | 13,800 | $690 |
| No | 201922275 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD30BS3 | *DHMB080ACV3 | 14,300 | $715 |
| No | 201922274 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD30BS3 | *DHMB060BCV3 | 14,200 | $710 |
| No | 210649553 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD30BS3 | *DD2B080A9V3+RP | 13,800 | $690 |
| No | 210649554 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD30BS3 | *DD2B060A9V3+RP | 13,900 | $695 |
| No | 211081289 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*AU24BS3 | S8V2A040M3PDA | 14,500 | $725 |
| No | 210691928 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*AU24BS3 | S8V2A040M3PCA | 14,500 | $725 |
| No | 210652749 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*AU24BS3 | L8V1A060U3VSA+RP | 14,700 | $735 |
| No | 210652748 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*AU24BS3 | L8V1A040U3VSA+RP | 14,700 | $735 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 212361360 | AMERICAN STANDARD | 4TXD2060A10NU** | 4RXCD060AS3HC** | | 35,200 | $1,760 |
| No | 212361359 | AMERICAN STANDARD | 4TXD2060A10NU** | 4RXCD048AS3HC** | | 31,200 | $1,560 |
| No | 212361358 | AMERICAN STANDARD | 4TXD2036A10NU** | 4RXCB036AS3HC** | | 22,000 | $1,100 |
| No | 207629144 | AMERICAN STANDARD | 4TXK2509A10N0** | 4MXW2509A10N0** | N/A | 7,300 | $365 |
| No | 204340355 | AMERICAN STANDARD | 4TXK3809B10NU** | 4MXW3809B10NU** | | 5,600 | $280 |
| No | 8761170 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCC007DS3 | *UD2B100ACV3 | 26,800 | $1,340 |
| No | 8761160 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB006DS3 | *UHMB080ACV3 | 26,600 | $1,330 |
| No | 10153460 | AMERICAN STANDARD | 4A6V8037A1 | TEM8A0C48V41+TDR | | 25,200 | $1,260 |
| No | 10511010 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BD48BS3 | S9V2B080D3PSB+RP | 26,800 | $1,340 |
| No | 20180110 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BD48BS3 | S9V2B080D3VSA+RP | 26,800 | $1,340 |
| No | 202541564 | AMERICAN STANDARD | 4TXK2309A10N0** | 4MXW2309A10N0** | | 6,800 | $340 |
| No | 8935199 | AMERICAN STANDARD | 4A6V0024A1 | 4TXCB004DS3 | *UD2B060ACV3 | 16,800 | $840 |
| No | 201922923 | AMERICAN STANDARD | 4A6L9024A1 | 4TXFH036CZ3 | *UD2B100ACV3 | 13,300 | $665 |
| No | 201923039 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU42BS3 | *UD2B100ACV3 | 13,800 | $690 |
| No | 201923674 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU48BS3 | *UD2B100ACV3 | 13,700 | $685 |
| No | 201923676 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB006DS3 | *UD2B100ACV3 | 13,700 | $685 |
| No | 20192307 | AMERICAN STANDARD | 4A6L9024A1 | 4TXFH024CZ3 | *UD2B100ACV3 | 13,500 | $675 |
| No | 20192287 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU42BS3 | *UHMB080ACV3 | 14,000 | $700 |
| No | 201922866 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU36BS3 | *UD2B100ACV3 | 13,400 | $670 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922895 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB004DS3 | *UD2B100ACV3 | 13,400 | $670 |
| No | 20192288 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*CD60BS3 | *DHMC100ACV4 | 13,800 | $690 |
| No | 20192285 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD24BS3+HORIZ-RT | *DD2B080ACV3 | 14,300 | $715 |
| No | 20249226 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU36BS3 | S9V2B040D3PSB+RP | 25,600 | $1,280 |
| No | 20192249 | AMERICAN STANDARD | 4A6L9036A1 | 4TXFH036CZ3 | *UHMD120ACV5 | 23,200 | $1,160 |
| No | 7599436 | AMERICAN STANDARD | 4A6V0036A1 | *AM8C0C48V41 | | 25,400 | $1,270 |
| No | 9150124 | AMERICAN STANDARD | 4TXK3812A10NU** | 4MXW3812A10NU** | | 8,100 | $405 |
| No | 10093468 | AMERICAN STANDARD | 4A6V8060A1 | TAM9A0C60V51 | | 48,000 | $2,400 |
| No | 7151530 | AMERICAN STANDARD | 4TXK2709A10N0AA | 4MXW2709A10N0AA | | 5,800 | $290 |
| No | 6796562 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCC007CC3 | *UD2C080ACV4 | 25,800 | $1,290 |
| No | 7125570 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB004CC3 | *UHMB060ACV3 | 26,000 | $1,300 |
| No | 6796559 | AMERICAN STANDARD | 4A6V8037A1 | *AM8C0B30V21 | | 26,200 | $1,310 |
| No | 6796524 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCC007CC3 | *UD2C080ACV4 | 25,800 | $1,290 |
| No | 6796560 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB004CC3 | *UD2B080ACV3 | 25,800 | $1,290 |
| No | 6796526 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCC007CC3 | *UD2C100ACV5 | 25,600 | $1,280 |
| No | 6750455 | AMERICAN STANDARD | 4A6V8024A1 | *AM8C0B30V21 | | 16,800 | $840 |
| No | 6750232 | AMERICAN STANDARD | 4A6V8036A1 | *AM8C0C36V31 | | 25,200 | $1,260 |
| No | 6992577 | AMERICAN STANDARD | 4A6V0036A1 | *AM8C0B30V21 | | 26,200 | $1,310 |
| No | 6749789 | AMERICAN STANDARD | 4A6V0024A1 | *AM8C0B30V21 | | 16,800 | $840 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 8759204 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU36BS3 | *UD2B080ACV3 | 26,000 | $1,300 |
| No | 8759186 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CU48BS3 | *UD2B100ACV3 | 26,800 | $1,340 |
| No | 8759185 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CU36BS3 | *UD2B100ACV3 | 26,200 | $1,310 |
| No | 8759123 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BD48BS3 | *DD2B080ACV3 | 27,200 | $1,360 |
| No | 202492252 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*CD42BS3 | *DD2C100ACV5 | 25,800 | $1,290 |
| No | 20249225 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU48BS3 | S9V2B060D3PSB+RP | 25,400 | $1,270 |
| No | 20236609 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU48BS3 | S9V2B080D3PSB+RP | 25,600 | $1,280 |
| No | 20192304 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU42BS3 | *UD2B080ACV3 | 13,800 | $690 |
| No | 20192303 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD48BS3 | *DHMB080ACV3 | 14,100 | $705 |
| No | 20192302 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD42BS3 | *DD2B060ACV3 | 13,200 | $660 |
| No | 201923015 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD36BS3+HORIZ-RT | *UD2B100ACV3 | 13,800 | $690 |
| No | 20192286 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD42BS3 | *DHMB060BCV3 | 13,300 | $665 |
| No | 20192264 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | S9V2D120U5PSB+RP | 31,800 | $1,590 |
| No | 20192258 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD48BS3+HORIZ-RT | S9V2C100U5PSB+RP | 31,800 | $1,590 |
| No | 20192257 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD48BS3+HORIZ-RT | S9V2C080U5PSB+RP | 31,800 | $1,590 |
| No | 20192256 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU60BS3 | S9V2C100U4PSB+RP | 32,000 | $1,600 |
| No | 20192255 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU48BS3 | S9V2C100U5PSB+RP | 32,200 | $1,610 |
| No | 20192252 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD60BS3+HORIZ-RT | S9V2C080U5PSB+RP | 31,800 | $1,590 |
| No | 20192242 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*DU48BS3 | *UD2D120ACV5 | 23,400 | $1,170 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 20192241 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*DD48BS3 | *DD2D120ACV5 | 23,600 | $1,180 |
| No | 201922397 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU48BS3 | *UD2B100ACV3 | 23,600 | $1,180 |
| No | 20192239 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU42BS3 | *UD2B100ACV3 | 23,600 | $1,180 |
| No | 201922383 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | *UD2B100ACV3 | 23,000 | $1,150 |
| No | 20192238 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | *UHMC100ACV4 | 23,000 | $1,150 |
| No | 20192237 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD60BS3 | *DD2C100ACV5 | 23,000 | $1,150 |
| No | 20192236 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD48BS3 | S9V2B060U3PSB+RP | 23,800 | $1,190 |
| No | 20192235 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD42BS3 | S9V2B080D3PSB+RP | 23,000 | $1,150 |
| No | 20192234 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD36BS3+HORIZ-RT | *UD2C100ACV5 | 23,600 | $1,180 |
| No | 201922314 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3+HORIZ-RT | *UD2B100ACV3 | 23,400 | $1,170 |
| No | 20192231 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3+HORIZ-RT | *DD2B060ACV3 | 23,600 | $1,180 |
| No | 20192229 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | *UD2B080ACV3 | 14,000 | $700 |
| No | 201922291 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | *UD2B100ACV3 | 14,100 | $705 |
| No | 201922286 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU24BS3 | *UD2B100ACV3 | 14,100 | $705 |
| No | 20192228 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD48BS3 | *DD2B060ACV3 | 13,800 | $690 |
| No | 201922281 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD48BS3+HORIZ-RT | *UD2B100ACV3 | 13,800 | $690 |
| No | 201922278 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD42BS3+HORIZ-RT | *UD2B100ACV3 | 13,200 | $660 |
| No | 20192227 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD24BS3 | *DHMB060BCV3 | 14,100 | $705 |
| No | 207590820 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXCB003DS3 | *UD2B060ACV3 | 17,600 | $880 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 20180115 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*CD36BS3 | S9V2C100D4VSA+RP | 26,600 | $1,330 |
| No | 20180095 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU36BS3 | S9V2B080U3VSA+RP | 26,000 | $1,300 |
| No | 201800595 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BD48BS3 | S9V2B080D3VSA+RP | 26,800 | $1,340 |
| No | 10511009 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BD48BS3 | S9V2B080D4PSB+RP | 26,800 | $1,340 |
| No | 10511008 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BD48BS3 | S9V2B040D3PSB+RP | 26,800 | $1,340 |
| No | 10510874 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BD48BS3 | S9V2B080D3PSB+RP | 26,800 | $1,340 |
| No | 10510871 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BD48BS3 | S9V2B040D3PSB+RP | 26,800 | $1,340 |
| No | 10510872 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BD48BS3 | S9V2B080D4PSB+RP | 26,800 | $1,340 |
| No | 8761179 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB004DS3 | *UD2B080ACV3 | 26,000 | $1,300 |
| No | 8761155 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB004DS3 | *UHMB060ACV3 | 26,600 | $1,330 |
| No | 8761151 | AMERICAN STANDARD | 4A6V8024A1 | 4TXCB004DS3 | *DD2B060ACV3 | 16,500 | $825 |
| No | 8761135 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCC007DS3 | *UD2C080ACV4 | 26,600 | $1,330 |
| No | 8761123 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB004DS3 | *UD2B080ACV3 | 26,000 | $1,300 |
| No | 8761117 | AMERICAN STANDARD | 4A6V0024A1 | 4TXCB004DS3 | *UHMB060ACV3 | 16,900 | $845 |
| No | 6796547 | AMERICAN STANDARD | 4A6V8024A1 | 4TXFH024CZ3 | *DD2B060ACV3 | 16,600 | $830 |
| No | 6796545 | AMERICAN STANDARD | 4A6V8024A1 | 4TXFH024CZ3 | *UD2B060ACV3 | 16,200 | $810 |
| No | 20192308 | AMERICAN STANDARD | 4A6L9024A1 | TEM8A0B24V21+TDR | N/A | 13,400 | $670 |
| No | 20192306 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB006DS3 | S9V2B080D3PSB+RP | 13,300 | $665 |
| No | 20192305 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | S9V2B040U3PSB+RP | 14,100 | $705 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 20192292 | AMERICAN STANDARD | 4A6L9024A1 | 4TXFH036CZ3 | *UHMB060ACV3 | 13,300 | $665 |
| No | 20192291 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB006DS3 | *UHMB060ACV3 | 13,800 | $690 |
| No | 20192289 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | S9V2B040D3PSB+RP | 13,700 | $685 |
| No | 20192272 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | S9V2C100U4PSB+RP | 31,000 | $1,550 |
| No | 20192269 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | S9V2D120D5PSB+RP | 31,200 | $1,560 |
| No | 20192265 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC007DS3 | S9V2C100D5PSB+RP | 31,000 | $1,550 |
| No | 201922481 | AMERICAN STANDARD | 4A6L9036A1 | 4TXFH036CZ3 | *UD2B100ACV3 | 22,600 | $1,130 |
| No | 20192248 | AMERICAN STANDARD | 4A6L9036A1 | 4TXFH036CZ3 | *UD2C080ACV4 | 22,400 | $1,120 |
| No | 20192247 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCD008DS3 | *UD2D140ACV5 | 23,400 | $1,170 |
| No | 20192246 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC007DS3 | S9V2C100U4PSB+RP | 23,400 | $1,170 |
| No | 201922455 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC007DS3 | *UD2B100ACV3 | 23,600 | $1,180 |
| No | 20192245 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | S9V2C100U4PSB+RP | 22,800 | $1,140 |
| No | 20192244 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | *UD2C100ACV5 | 22,800 | $1,140 |
| No | 201922438 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | *UD2B100ACV3 | 23,000 | $1,150 |
| No | 20192243 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | S9V2B080D3PSB+RP | 22,600 | $1,130 |
| No | 201922295 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | *UD2B100ACV3 | 14,100 | $705 |
| No | 20180121 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB006DS3 | S9V2B040U3VSA+RP | 26,400 | $1,320 |
| No | 20180106 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB006DS3 | S9V2B060U3VSA+RP | 26,400 | $1,320 |
| No | 20180091 | AMERICAN STANDARD | 4A6V8024A1 | 4TXCB004DS3 | S9V2B080U3VSA+RP | 16,800 | $840 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 20180071 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB006DS3 | S9V2B080U3VSA+RP | 26,600 | $1,330 |
| No | 20180069 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB004DS3 | S9V2B080D3VSA+RP | 25,400 | $1,270 |
| No | 20180067 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB004DS3 | S9V2B040U3VSA+RP | 26,200 | $1,310 |
| No | 10510999 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCC005DS3 | S9V2C100D4PSB+RP | 25,400 | $1,270 |
| No | 10153461 | AMERICAN STANDARD | 4A6V8037A1 | TEM8A0D48V41+TDR | N/A | 25,800 | $1,290 |
| No | 8761192 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCC007DS3 | *UD2C080ACV4 | 26,600 | $1,330 |
| No | 8761191 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCC007DS3 | *UD2C100ACV5 | 26,600 | $1,330 |
| No | 8761171 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCC007DS3 | *UD2C080ACV4 | 26,400 | $1,320 |
| No | 8759192 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CU60BS3 | *UD2B100ACV3 | 26,400 | $1,320 |
| No | 7125581 | AMERICAN STANDARD | 4A6V8037A1 | 4TXFH036CZ3 | *DHMB060BCV3 | 25,800 | $1,290 |
| No | 6796565 | AMERICAN STANDARD | 4A6V8037A1 | 4TXFH036CZ3 | *UD2C080ACV4 | 25,600 | $1,280 |
| No | 9060512 | AMERICAN STANDARD | 4TXM2230A15N0** | Heat pump without ducts | | 27,000 | $1,350 |
| No | 9060511 | AMERICAN STANDARD | 4TXM2224A14N0** | Heat pump without ducts | | 18,000 | $900 |
| No | 9060515 | AMERICAN STANDARD | 4TXM2236A15N0** | Heat pump without ducts | | 25,000 | $1,250 |
| No | 9060509 | AMERICAN STANDARD | 4TXM2218A12N0** | Heat pump without ducts | | 12,800 | $640 |
| No | 9060510 | AMERICAN STANDARD | 4TXM2221A13N0** | Heat pump without ducts | | 16,800 | $840 |
| No | 9060516 | AMERICAN STANDARD | 4TXM2242A15N0** | Heat pump without ducts | | 29,000 | $1,450 |
| No | 8854987 | AMERICAN STANDARD | 4A6V8024A1 | 4TXCB003DS3 | *UD2B060ACV3 | 17,600 | $880 |
| No | 207590218 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXCB003DS3 | *UD2B060ACV3 | 17,500 | $875 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202325438 | AMERICAN STANDARD | 4A6V0024A1 | 4TXCB003DS3 | *UD2B060ACV3 | 17,500 | $875 |
| No | 207590657 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CD48BS3 | *DHMC100ACV4 | 27,600 | $1,380 |
| No | 8759139 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*CD48BS3 | *DHMC100ACV4 | 27,600 | $1,380 |
| No | 201922883 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*CU42BS3 | *UD2C080ACV4 | 13,800 | $690 |
| No | 201922914 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCC007DS3 | *UD2C080ACV4 | 13,600 | $680 |
| No | 201922886 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*CU48BS3 | *UD2C080ACV4 | 13,600 | $680 |
| No | 201923029 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD48BS3 | S9V2B040D3PSB+RP | 13,900 | $695 |
| No | 201923032 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD48BS3+HORIZ-RT | S9V2B040U3PSB+RP | 13,900 | $695 |
| No | 201922884 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*CU42BS3 | *UHMC100ACV4 | 13,900 | $695 |
| No | 201922885 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*CU48BS3 | *UHMC100ACV4 | 13,700 | $685 |
| No | 201923062 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB006DS3 | S9V2B060U3PSB+RP | 13,500 | $675 |
| No | 201923043 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU48BS3 | S9V2B060U3PSB+RP | 13,500 | $675 |
| No | 201923041 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU42BS3 | *UD2B060ACV3 | 13,800 | $690 |
| No | 201923031 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD48BS3+HORIZ-RT | S9V2B060U3PSB+RP | 13,800 | $690 |
| No | 201923040 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU42BS3 | *UD2B080ACV3 | 13,800 | $690 |
| No | 201922913 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCC007DS3 | *UHMC100ACV4 | 13,700 | $685 |
| No | 201923028 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD48BS3 | S9V2B060D3PSB+RP | 13,800 | $690 |
| No | 201923046 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU48BS3 | *UD2B080ACV3 | 13,600 | $680 |
| No | 201923058 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB006DS3 | *UD2B080ACV3 | 13,600 | $680 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201923066 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCC009DS3 | *UD2C080ACV4 | 13,400 | $670 |
| No | 201923049 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*CU60BS3 | *UD2C080ACV4 | 13,400 | $670 |
| No | 201922926 | AMERICAN STANDARD | 4A6L9024A1 | TEM8A0C36V31+TDR | | 13,300 | $665 |
| No | 201922872 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU42BS3 | S9V2B080U3PSB+RP | 13,700 | $685 |
| No | 201923014 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD36BS3+HORIZ-RT | *UD2B060ACV3 | 13,900 | $695 |
| No | 201923044 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU48BS3 | S9V2B040U3PSB+RP | 13,600 | $680 |
| No | 201923063 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB006DS3 | S9V2B040U3PSB+RP | 13,600 | $680 |
| No | 201922280 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD48BS3 | *DD2B060ACV3 | 13,800 | $690 |
| No | 201922908 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB006DS3 | S9V2B080U3PSB+RP | 13,500 | $675 |
| No | 201922903 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB006DS3 | S9V2B040D3PSB+RP | 13,400 | $670 |
| No | 201922878 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*CD36BS3+HORIZ-RT | *UD2C080ACV4 | 13,700 | $685 |
| No | 201922874 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU48BS3 | S9V2B080U3PSB+RP | 13,500 | $675 |
| No | 201922283 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD48BS3+HORIZ-RT | *UD2B060ACV3 | 13,800 | $690 |
| No | 201923065 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCC009DS3 | *UHMC100ACV4 | 13,500 | $675 |
| No | 201923048 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*CU60BS3 | *UHMC100ACV4 | 13,500 | $675 |
| No | 201922906 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB006DS3 | *DD2B080ACV3 | 13,500 | $675 |
| No | 201922862 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD48BS3+HORIZ-RT | S9V2B080U3PSB+RP | 13,800 | $690 |
| No | 201922279 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD48BS3 | *DHMB060BCV3 | 13,900 | $695 |
| No | 201922889 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | S9V2B080U3PSB+RP | 14,100 | $705 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922864 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | S9V2B080U3PSB+RP | 14,100 | $705 |
| No | 201922299 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | *UD2B060ACV3 | 14,100 | $705 |
| No | 201922289 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | *UD2B060ACV3 | 14,100 | $705 |
| No | 201922471 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCD008DS3 | *UD2D120ACV5 | 23,400 | $1,170 |
| No | 201922420 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*DU48BS3 | *UD2D120ACV5 | 23,400 | $1,170 |
| No | 201922861 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD48BS3 | S9V2B080D3PSB+RP | 13,800 | $690 |
| No | 201922857 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD36BS3+HORIZ-RT | *UD2B080ACV3 | 13,800 | $690 |
| No | 201922870 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU42BS3 | *UHMB080ACV3 | 14,000 | $700 |
| No | 201923073 | AMERICAN STANDARD | 4A6L9024A1 | 4TXFH024CZ3 | *UD2C080ACV4 | 13,400 | $670 |
| No | 201923059 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB006DS3 | *UD2B060ACV3 | 13,600 | $680 |
| No | 201923011 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD36BS3 | *DD2B080ACV3 | 13,800 | $690 |
| No | 201922919 | AMERICAN STANDARD | 4A6L9024A1 | 4TXFH024CZ3 | S9V2B040U3PSB+RP | 13,400 | $670 |
| No | 201923045 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU48BS3 | *UD2B060ACV3 | 13,600 | $680 |
| No | 201922474 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCD010DS3 | *UD2D120ACV5 | 23,000 | $1,150 |
| No | 201922918 | AMERICAN STANDARD | 4A6L9024A1 | 4TXFH024CZ3 | S9V2B060U3PSB+RP | 13,400 | $670 |
| No | 201922421 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*DU60BS3 | *UD2D120ACV5 | 23,000 | $1,150 |
| No | 201923047 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*CD60BS3+HORIZ-RT | *UD2C080ACV4 | 13,400 | $670 |
| No | 201922911 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCC005DS3 | *UD2C080ACV4 | 13,300 | $665 |
| No | 201922882 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*CU36BS3 | *UD2C080ACV4 | 13,300 | $665 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201923017 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD36BS3+HORIZ-RT | S9V2B080U3PSB+RP | 13,700 | $685 |
| No | 201923016 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD36BS3+HORIZ-RT | S9V2B060U3PSB+RP | 13,700 | $685 |
| No | 201922875 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU48BS3 | *UHMB060ACV3 | 13,800 | $690 |
| No | 201922858 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD36BS3+HORIZ-RT | S9V2B040U3PSB+RP | 13,800 | $690 |
| No | 201922910 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB006DS3 | *UHMB060ACV3 | 13,800 | $690 |
| No | 201922856 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD36BS3 | S9V2B040D3PSB+RP | 13,800 | $690 |
| No | 201922282 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD48BS3+HORIZ-RT | *UD2B080ACV3 | 13,700 | $685 |
| No | 201922298 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | *UD2B080ACV3 | 14,000 | $700 |
| No | 201922290 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | *UD2B080ACV3 | 14,000 | $700 |
| No | 207590056 | AMERICAN STANDARD | 4A6V0X36A1 | TEM8A0D48V41+TDR | | 25,800 | $1,290 |
| No | 10153442 | AMERICAN STANDARD | 4A6V0036A1 | TEM8A0D48V41+TDR | | 25,800 | $1,290 |
| No | 207590169 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXCB004DS3 | S9V2B040U3VSA+RP | 16,800 | $840 |
| No | 207590166 | AMERICAN STANDARD | 4A6V8X24A1 | 4PX*BU36BS3 | S9V2B040U3VSA+RP | 16,800 | $840 |
| No | 207590123 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXCB004DS3 | S9V2B040U3VSA+RP | 16,800 | $840 |
| No | 207590109 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXCB004DS3 | S9V2B040U3PSB+RP | 16,800 | $840 |
| No | 207590086 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXCB004DS3 | S9V2B040U3PSB+RP | 16,800 | $840 |
| No | 201800879 | AMERICAN STANDARD | 4A6V8024A1 | 4PX*BU36BS3 | S9V2B040U3VSA+RP | 16,800 | $840 |
| No | 201800898 | AMERICAN STANDARD | 4A6V8024A1 | 4TXCB004DS3 | S9V2B040U3VSA+RP | 16,800 | $840 |
| No | 10510955 | AMERICAN STANDARD | 4A6V8024A1 | 4TXCB004DS3 | S9V2B040U3PSB+RP | 16,800 | $840 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201800553 | AMERICAN STANDARD | 4A6V0024A1 | 4TXCB004DS3 | S9V2B040U3VSA+RP | 16,800 | $840 |
| No | 201800511 | AMERICAN STANDARD | 4A6V0024A1 | 4PX*BU36BS3 | S9V2B040U3VSA+RP | 16,800 | $840 |
| No | 10510949 | AMERICAN STANDARD | 4A6V8024A1 | 4PX*BU36BS3 | S9V2B040U3PSB+RP | 16,800 | $840 |
| No | 10510866 | AMERICAN STANDARD | 4A6V0024A1 | 4TXCB004DS3 | S9V2B040U3PSB+RP | 16,800 | $840 |
| No | 10510858 | AMERICAN STANDARD | 4A6V0024A1 | 4PX*BU36BS3 | S9V2B040U3PSB+RP | 16,800 | $840 |
| No | 207590070 | AMERICAN STANDARD | 4A6V8X36A1 | TEM8A0D48V41+TDR | | 25,800 | $1,290 |
| No | 10153456 | AMERICAN STANDARD | 4A6V8036A1 | TEM8A0D48V41+TDR | | 25,800 | $1,290 |
| No | 10093446 | AMERICAN STANDARD | 4A6V0024A1 | TAM9A0B30V31 | | 16,800 | $840 |
| No | 207590122 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXCB004DS3 | S9V2B080U3VSA+RP | 16,800 | $840 |
| No | 207590171 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXCB004DS3 | S9V2B080U3VSA+RP | 16,800 | $840 |
| No | 207590168 | AMERICAN STANDARD | 4A6V8X24A1 | 4PX*BU36BS3 | S9V2B080U3VSA+RP | 16,800 | $840 |
| No | 207590120 | AMERICAN STANDARD | 4A6V0X24A1 | 4PX*BU36BS3 | S9V2B080U3VSA+RP | 16,800 | $840 |
| No | 207590108 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXCB004DS3 | S9V2B080U3PSB+RP | 16,800 | $840 |
| No | 207590107 | AMERICAN STANDARD | 4A6V8X24A1 | 4PX*BU36BS3 | S9V2B080U3PSB+RP | 16,800 | $840 |
| No | 207590084 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXCB004DS3 | S9V2B080U3PSB+RP | 16,800 | $840 |
| No | 207590083 | AMERICAN STANDARD | 4A6V0X24A1 | 4PX*BU36BS3 | S9V2B080U3PSB+RP | 16,800 | $840 |
| No | 201800910 | AMERICAN STANDARD | 4A6V8024A1 | 4TXCB004DS3 | S9V2B080U3VSA+RP | 16,800 | $840 |
| No | 201800891 | AMERICAN STANDARD | 4A6V8024A1 | 4PX*BU36BS3 | S9V2B080U3VSA+RP | 16,800 | $840 |
| No | 201800544 | AMERICAN STANDARD | 4A6V0024A1 | 4TXCB004DS3 | S9V2B080U3VSA+RP | 16,800 | $840 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10510952 | AMERICAN STANDARD | 4A6V8024A1 | 4TXCB004DS3 | S9V2B080U3PSB+RP | 16,800 | $840 |
| No | 10510951 | AMERICAN STANDARD | 4A6V8024A1 | 4PX*BU36BS3 | S9V2B080U3PSB+RP | 16,800 | $840 |
| No | 10510862 | AMERICAN STANDARD | 4A6V0024A1 | 4TXCB004DS3 | S9V2B080U3PSB+RP | 16,800 | $840 |
| No | 10510859 | AMERICAN STANDARD | 4A6V0024A1 | 4PX*BU36BS3 | S9V2B080U3PSB+RP | 16,800 | $840 |
| No | 10153455 | AMERICAN STANDARD | 4A6V8036A1 | TEM8A0C48V41+TDR | | 25,400 | $1,270 |
| No | 207590069 | AMERICAN STANDARD | 4A6V8X36A1 | TEM8A0C48V41+TDR | | 25,400 | $1,270 |
| No | 201800526 | AMERICAN STANDARD | 4A6V0024A1 | 4PX*BU36BS3 | S9V2B080U3VSA+RP | 16,800 | $840 |
| No | 6796520 | AMERICAN STANDARD | 4A6V0024A1 | 4TXFH024CZ3 | *DD2B060ACV3 | 16,600 | $830 |
| No | 10093456 | AMERICAN STANDARD | 4A6V8036A1 | TAM9A0B30V31 | | 26,600 | $1,330 |
| No | 201922376 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | S9V2B080U3PSB+RP | 23,000 | $1,150 |
| No | 201922871 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU42BS3 | *UHMB060ACV3 | 14,000 | $700 |
| No | 201922470 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCD008DS3 | *UD2D140ACV5 | 23,400 | $1,170 |
| No | 201922418 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*DU48BS3 | *UD2D140ACV5 | 23,400 | $1,170 |
| No | 201922855 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD36BS3 | *DD2B060ACV3 | 13,800 | $690 |
| No | 201922477 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCD010DS3 | *UD2D140ACV5 | 23,000 | $1,150 |
| No | 201923061 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB006DS3 | S9V2B060D3PSB+RP | 13,300 | $665 |
| No | 201923069 | AMERICAN STANDARD | 4A6L9024A1 | 4TXFH024CZ3 | S9V2B080U3PSB+RP | 13,400 | $670 |
| No | 201922423 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*DU60BS3 | *UD2D140ACV5 | 23,000 | $1,150 |
| No | 201923072 | AMERICAN STANDARD | 4A6L9024A1 | 4TXFH024CZ3 | *UD2B060ACV3 | 13,400 | $670 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206910602 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD48BS3+HORIZ-RT | S9V2B060U4PSBC+RP | 13,300 | $665 |
| No | 201922907 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB006DS3 | *DD2B060ACV3 | 13,300 | $665 |
| No | 201922894 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB004DS3 | *UD2B060ACV3 | 13,400 | $670 |
| No | 201922865 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU36BS3 | *UD2B060ACV3 | 13,400 | $670 |
| No | 201923067 | AMERICAN STANDARD | 4A6L9024A1 | 4TXFH024CZ3 | *UHMC100ACV4 | 13,500 | $675 |
| No | 201922385 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU42BS3 | S9V2B080U4PSB+RP | 23,800 | $1,190 |
| No | 201922459 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC007DS3 | S9V2B080U4PSB+RP | 23,600 | $1,180 |
| No | 201922457 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC007DS3 | S9V2B040U3PSB+RP | 23,600 | $1,180 |
| No | 201922404 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU48BS3 | S9V2B080U4PSB+RP | 23,600 | $1,180 |
| No | 201922869 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU36BS3 | S9V2B080U3PSB+RP | 13,300 | $665 |
| No | 201922901 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB004DS3 | S9V2B080U3PSB+RP | 13,300 | $665 |
| No | 201922399 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU48BS3 | S9V2B040U3PSB+RP | 23,600 | $1,180 |
| No | 201922909 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB006DS3 | *UHMB080ACV3 | 13,800 | $690 |
| No | 201922922 | AMERICAN STANDARD | 4A6L9024A1 | 4TXFH036CZ3 | *UD2C080ACV4 | 13,200 | $660 |
| No | 201922921 | AMERICAN STANDARD | 4A6L9024A1 | 4TXFH036CZ3 | *UD2B080ACV3 | 13,300 | $665 |
| No | 201922391 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU42BS3 | S9V2B040U3PSB+RP | 23,800 | $1,190 |
| No | 201922463 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC007DS3 | S9V2B060U4PSB+RP | 23,400 | $1,170 |
| No | 201922402 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU48BS3 | S9V2B060U4PSB+RP | 23,400 | $1,170 |
| No | 201922479 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCD010DS3+HORIZ-LT | *DD2D120ACV5 | 22,800 | $1,140 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922401 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU48BS3 | S9V2B060U3PSB+RP | 23,600 | $1,180 |
| No | 201922451 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC007DS3 | S9V2B060U3PSB+RP | 23,600 | $1,180 |
| No | 201922876 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU48BS3 | *UHMB080ACV3 | 13,800 | $690 |
| No | 206918580 | AMERICAN STANDARD | 4A6L9036A1 | TEM6A0D48H41+TDR+RP | | 22,200 | $1,110 |
| No | 201923077 | AMERICAN STANDARD | 4A6L9024A1 | 4TXFH036CZ3 | S9V2B060U3PSB+RP | 13,200 | $660 |
| No | 201922395 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU42BS3 | S9V2B060U3PSB+RP | 23,600 | $1,180 |
| No | 201922905 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB006DS3 | *DHMB060BCV3 | 13,400 | $670 |
| No | 201923075 | AMERICAN STANDARD | 4A6L9024A1 | 4TXFH036CZ3 | S9V2B040U3PSB+RP | 13,200 | $660 |
| No | 201922892 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | *DD2B080ACV3 | 13,800 | $690 |
| No | 206910618 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC007DS3 | S9V2C100U5PSBC+RP | 22,800 | $1,140 |
| No | 201923060 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB006DS3 | S9V2B080D3PSB+RP | 13,300 | $665 |
| No | 201922458 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC007DS3 | S9V2B080U3PSB+RP | 23,400 | $1,170 |
| No | 206910615 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU48BS3 | S9V2C100U5PSBC+RP | 22,800 | $1,140 |
| No | 201922403 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU48BS3 | S9V2B080U3PSB+RP | 23,400 | $1,170 |
| No | 206910614 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU42BS3 | S9V2C100U5PSBC+RP | 23,000 | $1,150 |
| No | 201922389 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU42BS3 | S9V2B060U4PSB+RP | 23,600 | $1,180 |
| No | 201922416 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*DD60BS3+HORIZ-RT | *UD2D120ACV5 | 23,000 | $1,150 |
| No | 201923076 | AMERICAN STANDARD | 4A6L9024A1 | 4TXFH036CZ3 | S9V2B080U3PSB+RP | 13,200 | $660 |
| No | 201923071 | AMERICAN STANDARD | 4A6L9024A1 | 4TXFH024CZ3 | *UD2B080ACV3 | 13,400 | $670 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201923053 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB004DS3 | *UD2B080ACV3 | 13,300 | $665 |
| No | 201923037 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU36BS3 | *UD2B080ACV3 | 13,300 | $665 |
| No | 201922912 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCC005DS3 | *UHMC100ACV4 | 13,400 | $670 |
| No | 201922881 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*CU36BS3 | *UHMC100ACV4 | 13,400 | $670 |
| No | 201922276 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD30BS3 | *DD2B060ACV3 | 14,100 | $705 |
| No | 201922388 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU42BS3 | S9V2B080U3PSB+RP | 23,600 | $1,180 |
| No | 201922414 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*DD60BS3 | *DHMD120BCV5 | 23,000 | $1,150 |
| No | 201922902 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB004DS3 | S9V2B060U3PSB+RP | 13,200 | $660 |
| No | 201922417 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*DD60BS3+HORIZ-RT | *UD2D140ACV5 | 23,200 | $1,160 |
| No | 206910605 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | S9V2B060U4PSBC+RP | 13,600 | $680 |
| No | 201923030 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD48BS3 | *DHMB080ACV3 | 14,100 | $705 |
| No | 206910604 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | S9V2B060U4PSBC+RP | 13,600 | $680 |
| No | 201922868 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU36BS3 | S9V2B060U3PSB+RP | 13,200 | $660 |
| No | 201922478 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCD010DS3 | *DD2D120ACV5 | 22,400 | $1,120 |
| No | 201922475 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCD010DS3 | *UHMD120ACV5 | 23,400 | $1,170 |
| No | 201922422 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*DU60BS3 | *UHMD120ACV5 | 23,400 | $1,170 |
| No | 201922408 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU60BS3 | *UHMC100ACV4 | 23,000 | $1,150 |
| No | 201922456 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC007DS3 | *UD2B080ACV3 | 23,400 | $1,170 |
| No | 201922396 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU48BS3 | *UD2B080ACV3 | 23,400 | $1,170 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201923079 | AMERICAN STANDARD | 4A6L9024A1 | 4TXFH036CZ3 | *UHMC100ACV4 | 13,300 | $665 |
| No | 201922896 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB004DS3 | *DD2B060ACV3 | 13,200 | $660 |
| No | 201922473 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCD008DS3 | *DD2D120ACV5 | 22,600 | $1,130 |
| No | 201923681 | AMERICAN STANDARD | 4A6L9036A1 | TAM9A0C36V31 | | 22,800 | $1,140 |
| No | 201922900 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB004DS3 | S9V2B040U3PSB+RP | 13,300 | $665 |
| No | 201922867 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU36BS3 | S9V2B040U3PSB+RP | 13,300 | $665 |
| No | 204780005 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | P0V0B000M40SA+RP | 23,000 | $1,150 |
| No | 204780011 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | P0V0B000M40SA+RP | 23,000 | $1,150 |
| No | 201922904 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB006DS3 | *DHMB080ACV3 | 13,700 | $685 |
| No | 201923078 | AMERICAN STANDARD | 4A6L9024A1 | 4TXFH036CZ3 | *UD2B060ACV3 | 13,200 | $660 |
| No | 201922472 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCD008DS3 | *DHMD120BCV5 | 23,000 | $1,150 |
| No | 201922358 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD48BS3 | S9V2C100D4PSB+RP | 23,800 | $1,190 |
| No | 204433497 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | S9V2B080U3VSA+RP | 23,200 | $1,160 |
| No | 201923068 | AMERICAN STANDARD | 4A6L9024A1 | 4TXFH024CZ3 | *UHMB080ACV3 | 13,600 | $680 |
| No | 201923056 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB004DS3 | S9V2B060D3PSB+RP | 13,100 | $655 |
| No | 206908445 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | S9V2B060U3PSA+RP | 13,600 | $680 |
| No | 201922415 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*DD60BS3 | *DD2D120ACV5 | 22,800 | $1,140 |
| No | 201922476 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCD010DS3 | *DHMD120BCV5 | 22,200 | $1,110 |
| No | 206918578 | AMERICAN STANDARD | 4A6L9036A1 | TEM6A0C36H31+TDR+RP | | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201923054 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB004DS3 | *DD2B080ACV3 | 13,100 | $655 |
| No | 201922854 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD36BS3 | *DHMB080ACV3 | 14,000 | $700 |
| No | 201923025 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD42BS3+HORIZ-RT | *UD2B080ACV3 | 13,300 | $665 |
| No | 201923024 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD42BS3+HORIZ-RT | *UD2B060ACV3 | 13,300 | $665 |
| No | 201922387 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU42BS3 | *UD2B080ACV3 | 23,600 | $1,180 |
| No | 205962511 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | P0V0B000M40SB+RP | 22,400 | $1,120 |
| No | 201923019 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD42BS3 | *DD2B080ACV3 | 13,300 | $665 |
| No | 205962507 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | P0V0B000M40SB+RP | 22,400 | $1,120 |
| No | 201923021 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD42BS3 | S9V2B060D3PSB+RP | 13,200 | $660 |
| No | 204780003 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | P0V0B000M40SA+RP | 23,200 | $1,160 |
| No | 201923023 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD42BS3+HORIZ-RT | S9V2B060U3PSB+RP | 13,200 | $660 |
| No | 201922899 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB004DS3 | S9V2B080D3PSB+RP | 13,100 | $655 |
| No | 201922898 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB004DS3 | S9V2B040D3PSB+RP | 13,100 | $655 |
| No | 201922469 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCD008DS3 | *UHMD120ACV5 | 23,400 | $1,170 |
| No | 201922413 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*DD48BS3+HORIZ-RT | *UD2D120ACV5 | 23,600 | $1,180 |
| No | 201922410 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*DD48BS3 | *DD2D120ACV5 | 23,600 | $1,180 |
| No | 201922917 | AMERICAN STANDARD | 4A6L9024A1 | 4TXFH024CZ3 | *UHMB060ACV3 | 13,500 | $675 |
| No | 201922915 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCC007DS3 | *DHMC100ACV4 | 13,800 | $690 |
| No | 206918579 | AMERICAN STANDARD | 4A6L9036A1 | TEM6A0C42H41+TDR+RP | | 22,400 | $1,120 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922419 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*DU48BS3 | *UHMD120ACV5 | 23,400 | $1,170 |
| No | 206910613 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | S9V2C100U5PSBC+RP | 22,800 | $1,140 |
| No | 201922485 | AMERICAN STANDARD | 4A6L9036A1 | 4TXFH036CZ3 | *UD2D120ACV5 | 22,600 | $1,130 |
| No | 201923026 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD42BS3+HORIZ-RT | S9V2B040U3PSB+RP | 13,200 | $660 |
| No | 201923022 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD42BS3 | S9V2B080D3PSB+RP | 13,100 | $655 |
| No | 206910601 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD36BS3+HORIZ-RT | S9V2B060U4PSBC+RP | 13,200 | $660 |
| No | 201923027 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD42BS3+HORIZ-RT | S9V2B080U3PSB+RP | 13,100 | $655 |
| No | 201923018 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD42BS3 | S9V2B040D3PSB+RP | 13,200 | $660 |
| No | 201922363 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD48BS3+HORIZ-RT | S9V2C100U4PSB+RP | 23,600 | $1,180 |
| No | 201923074 | AMERICAN STANDARD | 4A6L9024A1 | 4TXFH036CZ3 | *UHMB080ACV3 | 13,400 | $670 |
| No | 206852870 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | S9V2B060U3VSAB+RP | 23,000 | $1,150 |
| No | 201922366 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD48BS3+HORIZ-RT | *UD2C100ACV5 | 23,600 | $1,180 |
| No | 201922490 | AMERICAN STANDARD | 4A6L9036A1 | 4TXFH036CZ3 | *UHMD120ACV5 | 23,200 | $1,160 |
| No | 201922880 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*CD60BS3 | *DHMC100ACV4 | 13,800 | $690 |
| No | 201923020 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD42BS3 | *DD2B060ACV3 | 13,200 | $660 |
| No | 201922360 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD48BS3 | S9V2B060U3PSB+RP | 23,800 | $1,190 |
| No | 201922375 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | S9V2B080U4PSB+RP | 23,000 | $1,150 |
| No | 201922364 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD48BS3+HORIZ-RT | S9V2B040U3PSB+RP | 23,800 | $1,190 |
| No | 201922877 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*CD36BS3 | *DHMC100ACV4 | 14,100 | $705 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922449 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | S9V2B080U4PSB+RP | 23,000 | $1,150 |
| No | 201922357 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD48BS3 | S9V2B040D3PSB+RP | 23,800 | $1,190 |
| No | 201922411 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*DD48BS3 | *DHMD120BCV5 | 23,600 | $1,180 |
| No | 201922468 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC009DS3 | *DD2C100ACV5 | 22,000 | $1,100 |
| No | 201922442 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | S9V2B060U3PSB+RP | 23,000 | $1,150 |
| No | 201922379 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | S9V2B060U3PSB+RP | 23,000 | $1,150 |
| No | 201922486 | AMERICAN STANDARD | 4A6L9036A1 | 4TXFH036CZ3 | *UD2D140ACV5 | 22,600 | $1,130 |
| No | 201922412 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*DD48BS3+HORIZ-RT | *UD2D140ACV5 | 23,600 | $1,180 |
| No | 201922378 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | S9V2B040U3PSB+RP | 23,000 | $1,150 |
| No | 201922445 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | S9V2B040U3PSB+RP | 23,000 | $1,150 |
| No | 201922362 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD48BS3+HORIZ-RT | S9V2B080U4PSB+RP | 23,800 | $1,190 |
| No | 201922356 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD48BS3 | S9V2B080D3PSB+RP | 23,800 | $1,190 |
| No | 201922359 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD48BS3 | S9V2B080D4PSB+RP | 23,800 | $1,190 |
| No | 201922361 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD48BS3+HORIZ-RT | S9V2B080U3PSB+RP | 23,800 | $1,190 |
| No | 201922332 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD48BS3 | S9V2B080D3PSB+RP | 23,800 | $1,190 |
| No | 202919212 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | S9V2B080U3PSB+RP | 23,000 | $1,150 |
| No | 201922447 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | S9V2B060U4PSB+RP | 22,800 | $1,140 |
| No | 201922365 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD48BS3+HORIZ-RT | *UD2C080ACV4 | 23,600 | $1,180 |
| No | 201922377 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | S9V2B060U4PSB+RP | 22,800 | $1,140 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922448 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | S9V2B080U3PSB+RP | 23,000 | $1,150 |
| No | 201922920 | AMERICAN STANDARD | 4A6L9024A1 | 4TXFH036CZ3 | *UHMB060ACV3 | 13,300 | $665 |
| No | 205962505 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | P0V0B000M40SB+RP | 22,600 | $1,130 |
| No | 204780013 | AMERICAN STANDARD | 4A6L9036A1 | 4TXFH036CZ3 | P0V0B000M40SA+RP | 22,200 | $1,110 |
| No | 201922860 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD42BS3 | *DHMB060BCV3 | 13,300 | $665 |
| No | 201922489 | AMERICAN STANDARD | 4A6L9036A1 | 4TXFH036CZ3 | *UHMC100ACV4 | 22,600 | $1,130 |
| No | 201922353 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD48BS3 | *DD2C100ACV5 | 23,600 | $1,180 |
| No | 201922305 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3 | S9V2C100D4PSB+RP | 23,600 | $1,180 |
| No | 201922300 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB004DS3 | *UHMB060ACV3 | 13,400 | $670 |
| No | 201922294 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU36BS3 | *UHMB060ACV3 | 13,400 | $670 |
| No | 201922367 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD48BS3+HORIZ-RT | *UD2B060ACV3 | 23,800 | $1,190 |
| No | 201922311 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3+HORIZ-RT | S9V2C100U4PSB+RP | 23,600 | $1,180 |
| No | 201922355 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD48BS3 | *DD2B060ACV3 | 23,600 | $1,180 |
| No | 206910611 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD48BS3 | S9V2C100D5PSBC+RP | 23,000 | $1,150 |
| No | 201923057 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB004DS3 | *UHMB080ACV3 | 13,500 | $675 |
| No | 201923038 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU36BS3 | *UHMB080ACV3 | 13,500 | $675 |
| No | 201923055 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB004DS3 | *DHMB060BCV3 | 13,100 | $655 |
| No | 206910612 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD48BS3+HORIZ-RT | S9V2C100U5PSBC+RP | 23,000 | $1,150 |
| No | 206910610 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD42BS3 | S9V2C100D5PSBC+RP | 22,400 | $1,120 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204779983 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | P0V0A000M30SA+RP | 13,300 | $665 |
| No | 204780012 | AMERICAN STANDARD | 4A6L9036A1 | 4TXFH036CZ3 | P0V0A000M30SA+RP | 22,200 | $1,110 |
| No | 201922446 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | *UD2B080ACV3 | 23,000 | $1,150 |
| No | 201922384 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | *UD2B080ACV3 | 23,000 | $1,150 |
| No | 204013230 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD48BS3 | S9V2B080D4PSB+RP | 23,600 | $1,180 |
| No | 206910617 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | S9V2C100U5PSBC+RP | 22,200 | $1,110 |
| No | 204779980 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD48BS3 | P0V0A000M30SA+RP | 13,000 | $650 |
| No | 204779981 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD48BS3+HORIZ-RT | P0V0A000M30SA+RP | 13,000 | $650 |
| No | 201922337 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD36BS3+HORIZ-RT | S9V2B040U3PSB+RP | 23,600 | $1,180 |
| No | 201922488 | AMERICAN STANDARD | 4A6L9036A1 | 4TXFH036CZ3 | *UHMB080ACV3 | 23,200 | $1,160 |
| No | 204779985 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | P0V0A000M30SA+RP | 13,300 | $665 |
| No | 204779995 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD48BS3 | P0V0B000M40SA+RP | 23,400 | $1,170 |
| No | 204779997 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD48BS3+HORIZ-RT | P0V0B000M40SA+RP | 23,400 | $1,170 |
| No | 201922849 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD24BS3 | *DD2B080ACV3 | 14,300 | $715 |
| No | 201922850 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD24BS3+HORIZ-RT | *DD2B080ACV3 | 14,300 | $715 |
| No | 201922347 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD42BS3 | *DD2B060ACV3 | 23,000 | $1,150 |
| No | 201922341 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD36BS3+HORIZ-RT | S9V2B060U3PSB+RP | 23,600 | $1,180 |
| No | 201922350 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD42BS3 | S9V2B080D3PSB+RP | 23,000 | $1,150 |
| No | 204433493 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | S9V2B080U3VSA+RP | 22,800 | $1,140 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204780002 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | P0V0A000M30SA+RP | 22,600 | $1,130 |
| No | 205962489 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD48BS3 | P0V0A000M30SB+RP | 12,700 | $635 |
| No | 201922344 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD36BS3+HORIZ-RT | S9V2C100U4PSB+RP | 23,400 | $1,170 |
| No | 204780001 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | P0V0B000M40SA+RP | 22,400 | $1,120 |
| No | 206910607 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | S9V2B060U4PSBC+RP | 22,400 | $1,120 |
| No | 201922342 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD36BS3+HORIZ-RT | S9V2B080U3PSB+RP | 23,600 | $1,180 |
| No | 201923679 | AMERICAN STANDARD | 4A6L9024A1 | TAM9A0B30V31 | | 13,000 | $650 |
| No | 201922897 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB004DS3 | *DHMB080ACV3 | 13,400 | $670 |
| No | 201922487 | AMERICAN STANDARD | 4A6L9036A1 | 4TXFH036CZ3 | *UHMB060ACV3 | 23,200 | $1,160 |
| No | 204780010 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | P0V0A000M30SA+RP | 22,400 | $1,120 |
| No | 201923064 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCC005DS3 | *DHMC100ACV4 | 13,600 | $680 |
| No | 204780000 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | P0V0A000M30SA+RP | 22,000 | $1,100 |
| No | 201922863 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU24BS3 | S9V2B080U3PSB+RP | 14,000 | $700 |
| No | 201922335 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD36BS3 | S9V2B080D4PSB+RP | 23,600 | $1,180 |
| No | 201922343 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD36BS3+HORIZ-RT | S9V2B080U4PSB+RP | 23,600 | $1,180 |
| No | 201922316 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3+HORIZ-RT | S9V2B060U3PSB+RP | 23,600 | $1,180 |
| No | 201922315 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3+HORIZ-RT | S9V2B040U3PSB+RP | 23,600 | $1,180 |
| No | 206910616 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | S9V2B060U4PSBC+RP | 22,200 | $1,110 |
| No | 205962510 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB006DS3 | P0V0A000M30SB+RP | 21,800 | $1,090 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922859 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD42BS3 | *DHMB080ACV3 | 13,500 | $675 |
| No | 204780009 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | P0V0B000M40SA+RP | 22,400 | $1,120 |
| No | 205962506 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU48BS3 | P0V0A000M30SB+RP | 21,800 | $1,090 |
| No | 201923007 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD24BS3 | S9V2B080D3PSB+RP | 14,200 | $710 |
| No | 205962501 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD48BS3+HORIZ-RT | P0V0B000M40SB+RP | 22,800 | $1,140 |
| No | 205962500 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD48BS3 | P0V0B000M40SB+RP | 22,800 | $1,140 |
| No | 201922349 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD42BS3 | S9V2B080D4PSB+RP | 23,000 | $1,150 |
| No | 201922352 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD42BS3 | S9V2B040D3PSB+RP | 22,800 | $1,140 |
| No | 206852868 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | S9V2B060U3VSAB+RP | 22,600 | $1,130 |
| No | 201922317 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3+HORIZ-RT | S9V2B080U3PSB+RP | 23,600 | $1,180 |
| No | 201922354 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD48BS3 | *DHMC100ACV4 | 24,400 | $1,220 |
| No | 201922287 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU24BS3 | *UD2B080ACV3 | 14,000 | $700 |
| No | 201922288 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU24BS3 | *UD2B060ACV3 | 14,000 | $700 |
| No | 201922323 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3+HORIZ-RT | S9V2B080U4PSB+RP | 23,600 | $1,180 |
| No | 201922351 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD42BS3 | S9V2B060D3PSB+RP | 22,800 | $1,140 |
| No | 201922310 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3+HORIZ-RT | *DD2B060ACV3 | 23,600 | $1,180 |
| No | 201922338 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD36BS3+HORIZ-RT | *UD2B060ACV3 | 23,600 | $1,180 |
| No | 204779979 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD30BS3 | P0V0A000M30SA+RP | 13,300 | $665 |
| No | 205962490 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU30BS3 | P0V0A000M30SB+RP | 13,000 | $650 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205962492 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCB003DS3 | P0V0A000M30SB+RP | 13,000 | $650 |
| No | 201922916 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCC009DS3 | *DHMC100ACV4 | 13,200 | $660 |
| No | 201923006 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD24BS3 | S9V2B040D3PSB+RP | 14,200 | $710 |
| No | 201923005 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD24BS3 | S9V2B060D3PSB+RP | 14,200 | $710 |
| No | 205962504 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU42BS3 | P0V0A000M30SB+RP | 22,000 | $1,100 |
| No | 205962488 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD30BS3 | P0V0A000M30SB+RP | 13,100 | $655 |
| No | 205962509 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | P0V0B000M40SB+RP | 21,600 | $1,080 |
| No | 204779993 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3+HORIZ-RT | P0V0B000M40SA+RP | 22,800 | $1,140 |
| No | 205962503 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | P0V0B000M40SB+RP | 21,600 | $1,080 |
| No | 204779991 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3 | P0V0B000M40SA+RP | 22,800 | $1,140 |
| No | 201922879 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*CD42BS3 | *DHMC100ACV4 | 13,600 | $680 |
| No | 206214517 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | *DD2B080ACV3 | 22,000 | $1,100 |
| No | 206910609 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD36BS3+HORIZ-RT | S9V2C100U5PSBC+RP | 23,000 | $1,150 |
| No | 206910608 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CD36BS3 | S9V2C100D5PSBC+RP | 23,000 | $1,150 |
| No | 206910603 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU24BS3 | S9V2B060U4PSBC+RP | 13,500 | $675 |
| No | 204779989 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3+HORIZ-RT | P0V0B000M40SA+RP | 23,200 | $1,160 |
| No | 204779986 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3 | P0V0B000M40SA+RP | 23,200 | $1,160 |
| No | 204780008 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | P0V0A000M30SA+RP | 22,000 | $1,100 |
| No | 204779996 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD48BS3+HORIZ-RT | P0V0A000M30SA+RP | 22,600 | $1,130 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204779994 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD48BS3 | P0V0A000M30SA+RP | 22,600 | $1,130 |
| No | 205962497 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3 | P0V0B000M40SB+RP | 21,800 | $1,090 |
| No | 205962502 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU36BS3 | P0V0A000M30SB+RP | 21,200 | $1,060 |
| No | 205962508 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB004DS3 | P0V0A000M30SB+RP | 21,200 | $1,060 |
| No | 206214519 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCC005DS3 | *DD2B060ACV3 | 21,600 | $1,080 |
| No | 205962498 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3+HORIZ-RT | P0V0B000M40SB+RP | 21,800 | $1,090 |
| No | 205962499 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD48BS3 | P0V0A000M30SB+RP | 22,200 | $1,110 |
| No | 206912615 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD48BS3 | P0V0A000M30SC+RP | 22,200 | $1,110 |
| No | 204779992 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3+HORIZ-RT | P0V0A000M30SA+RP | 22,000 | $1,100 |
| No | 204779990 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3 | P0V0A000M30SA+RP | 22,000 | $1,100 |
| No | 206918616 | AMERICAN STANDARD | 4A6L9036A1 | TEM6A0B30H21+TDR+RP | | 22,200 | $1,110 |
| No | 201922272 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD24BS3+HORIZ-RT | *DHMB080ACV3 | 14,300 | $715 |
| No | 201922271 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD24BS3 | *DHMB080ACV3 | 14,300 | $715 |
| No | 201922273 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD24BS3+HORIZ-RT | *DHMB060BCV3 | 14,100 | $705 |
| No | 201922270 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD24BS3 | *DHMB060BCV3 | 14,100 | $705 |
| No | 205962486 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*AU24BS3 | P0V0A000M30SB+RP | 13,400 | $670 |
| No | 206910606 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3+HORIZ-RT | S9V2B060U4PSBC+RP | 23,000 | $1,150 |
| No | 204779988 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3+HORIZ-RT | P0V0A000M30SA+RP | 22,600 | $1,130 |
| No | 204779984 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCA002DS3 | P0V0A000M30SA+RP | 13,600 | $680 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205962495 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3+HORIZ-RT | P0V0B000M40SB+RP | 22,800 | $1,140 |
| No | 205962494 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3 | P0V0B000M40SB+RP | 22,800 | $1,140 |
| No | 204779987 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3 | P0V0A000M30SA+RP | 22,400 | $1,120 |
| No | 205962496 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3 | P0V0A000M30SB+RP | 21,400 | $1,070 |
| No | 206912612 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD42BS3 | P0V0A000M30SC+RP | 21,400 | $1,070 |
| No | 204779975 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*AD24BS3 | P0V0A000M30SA+RP | 13,800 | $690 |
| No | 204779982 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BU24BS3 | P0V0A000M30SA+RP | 13,200 | $660 |
| No | 201922373 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU30BS3 | *UHMC100ACV4 | 24,200 | $1,210 |
| No | 206315457 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*CU36BS3 | *DHMB080ACV3 | 22,000 | $1,100 |
| No | 201922427 | AMERICAN STANDARD | 4A6L9036A1 | 4TXCB003DS3 | *UHMB080ACV3 | 24,400 | $1,220 |
| No | 201922333 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BU30BS3 | *UHMB080ACV3 | 24,400 | $1,220 |
| No | 205962485 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*AD24BS3 | P0V0A000M30SB+RP | 13,500 | $675 |
| No | 205962491 | AMERICAN STANDARD | 4A6L9024A1 | 4TXCA002DS3 | P0V0A000M30SB+RP | 13,600 | $680 |
| No | 205962493 | AMERICAN STANDARD | 4A6L9036A1 | 4PX*BD36BS3 | P0V0A000M30SB+RP | 22,200 | $1,110 |
| No | 204779978 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD24BS3+HORIZ-RT | P0V0A000M30SA+RP | 13,300 | $665 |
| No | 204779977 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD24BS3 | P0V0A000M30SA+RP | 13,300 | $665 |
| No | 205962487 | AMERICAN STANDARD | 4A6L9024A1 | 4PX*BD24BS3 | P0V0A000M30SB+RP | 13,100 | $655 |
| No | 207590788 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXCB004DS3 | *DHMB060BCV3 | 16,500 | $825 |
| No | 207590674 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXCB004DS3 | *DHMB060BCV3 | 16,500 | $825 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 8761149 | AMERICAN STANDARD | 4A6V8024A1 | 4TXCB004DS3 | *DHMB060BCV3 | 16,500 | $825 |
| No | 8761119 | AMERICAN STANDARD | 4A6V0024A1 | 4TXCB004DS3 | *DHMB060BCV3 | 16,500 | $825 |
| No | 10093455 | AMERICAN STANDARD | 4A6V8024A1 | TAM9A0C36V31 | | 16,700 | $835 |
| No | 10153453 | AMERICAN STANDARD | 4A6V8036A1 | TEM8A0C36V31+TDR | | 25,600 | $1,280 |
| No | 10153439 | AMERICAN STANDARD | 4A6V0036A1 | TEM8A0C36V31+TDR | | 25,600 | $1,280 |
| No | 207590170 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXCB004DS3 | S9V2B060U3VSA+RP | 16,700 | $835 |
| No | 207590167 | AMERICAN STANDARD | 4A6V8X24A1 | 4PX*BU36BS3 | S9V2B060U3VSA+RP | 16,700 | $835 |
| No | 207590121 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXCB004DS3 | S9V2B060U3VSA+RP | 16,700 | $835 |
| No | 207590085 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXCB004DS3 | S9V2B060U3PSB+RP | 16,700 | $835 |
| No | 201800904 | AMERICAN STANDARD | 4A6V8024A1 | 4TXCB004DS3 | S9V2B060U3VSA+RP | 16,700 | $835 |
| No | 201800885 | AMERICAN STANDARD | 4A6V8024A1 | 4PX*BU36BS3 | S9V2B060U3VSA+RP | 16,700 | $835 |
| No | 10510957 | AMERICAN STANDARD | 4A6V8024A1 | 4TXCB004DS3 | S9V2B060U3PSB+RP | 16,700 | $835 |
| No | 10510863 | AMERICAN STANDARD | 4A6V0024A1 | 4TXCB004DS3 | S9V2B060U3PSB+RP | 16,700 | $835 |
| No | 10510950 | AMERICAN STANDARD | 4A6V8024A1 | 4PX*BU36BS3 | S9V2B060U3PSB+RP | 16,700 | $835 |
| No | 201800535 | AMERICAN STANDARD | 4A6V0024A1 | 4TXCB004DS3 | S9V2B060U3VSA+RP | 16,700 | $835 |
| No | 10510860 | AMERICAN STANDARD | 4A6V0024A1 | 4PX*BU36BS3 | S9V2B060U3PSB+RP | 16,700 | $835 |
| No | 207590055 | AMERICAN STANDARD | 4A6V0X36A1 | TEM8A0C48V41+TDR | | 25,200 | $1,260 |
| No | 201800519 | AMERICAN STANDARD | 4A6V0024A1 | 4PX*BU36BS3 | S9V2B060U3VSA+RP | 16,700 | $835 |
| No | 10153441 | AMERICAN STANDARD | 4A6V0036A1 | TEM8A0C48V41+TDR | | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10510888 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*CU48BS3 | S9V2C100U4PSB+RP | 26,400 | $1,320 |
| No | 10510905 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCC007DS3 | S9V2C100U4PSB+RP | 26,400 | $1,320 |
| No | 207590146 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCC007DS3 | S9V2C100U4VSA+RP | 26,400 | $1,320 |
| No | 201803249 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCC007DS3 | S9V2C100U4VSA+RP | 26,400 | $1,320 |
| No | 201801171 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*CU48BS3 | S9V2C100U4VSA+RP | 26,400 | $1,320 |
| No | 10511041 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCC007DS3 | S9V2C100U4PSB+RP | 26,400 | $1,320 |
| No | 10511024 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*CU48BS3 | S9V2C100U4PSB+RP | 26,400 | $1,320 |
| No | 201800662 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*CU48BS3 | S9V2C100U4VSA+RP | 26,400 | $1,320 |
| No | 201800732 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCC007DS3 | S9V2C100U4VSA+RP | 26,400 | $1,320 |
| No | 204780115 | AMERICAN STANDARD | 4A6V8024A1 | 4TXFH024CZ3 | P0V0A000M30SA+RP | 16,600 | $830 |
| No | 207590317 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXFH024CZ3 | P0V0A000M30SA+RP | 16,600 | $830 |
| No | 10153436 | AMERICAN STANDARD | 4A6V0024A1 | TEM8A0B30V31+TDR | | 17,000 | $850 |
| No | 207590502 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU48BS3 | S9V2C100U5PSBC+RP | 25,600 | $1,280 |
| No | 206910636 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CU48BS3 | S9V2C100U5PSBC+RP | 25,600 | $1,280 |
| No | 10510956 | AMERICAN STANDARD | 4A6V8024A1 | 4TXCB004DS3 | S9V2B040D3PSB+RP | 16,700 | $835 |
| No | 202366094 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CU48BS3 | S9V2C100D4PSB+RP | 25,600 | $1,280 |
| No | 207590274 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXFH024CZ3 | P0V0A000M30SA+RP | 16,600 | $830 |
| No | 204780072 | AMERICAN STANDARD | 4A6V0024A1 | 4TXFH024CZ3 | P0V0A000M30SA+RP | 16,600 | $830 |
| No | 207590219 | AMERICAN STANDARD | 4A6V0X24A1 | 4PX*BU36BS3 | *DHMB060BCV3 | 16,800 | $840 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202366079 | AMERICAN STANDARD | 4A6V0024A1 | 4PX*BU36BS3 | *DHMB060BCV3 | 16,800 | $840 |
| No | 10510861 | AMERICAN STANDARD | 4A6V0024A1 | 4TXCB004DS3 | S9V2B040D3PSB+RP | 16,700 | $835 |
| No | 9122736 | AMERICAN STANDARD | 4A6V0024A1 | 4PX*BU42BS3 | *UHMB060ACV3 | 17,300 | $865 |
| No | 207590717 | AMERICAN STANDARD | 4A6V0X24A1 | 4PX*BU42BS3 | *UHMB060ACV3 | 17,300 | $865 |
| No | 10093459 | AMERICAN STANDARD | 4A6V8037A1 | TAM9A0B30V31 | | 26,200 | $1,310 |
| No | 207590701 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXFH036CZ3 | *DD2B060ACV3 | 26,400 | $1,320 |
| No | 10093447 | AMERICAN STANDARD | 4A6V0036A1 | TAM9A0B30V31 | | 26,200 | $1,310 |
| No | 207590188 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB006DS3 | S9V2B080U3VSA+RP | 26,600 | $1,330 |
| No | 8938521 | AMERICAN STANDARD | 4A6V0036A1 | 4TXFH036CZ3 | *DD2B060ACV3 | 26,400 | $1,320 |
| No | 207590179 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU48BS3 | S9V2B080U3VSA+RP | 26,600 | $1,330 |
| No | 207590114 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB006DS3 | S9V2B080U3PSB+RP | 26,600 | $1,330 |
| No | 207590111 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU48BS3 | S9V2B080U3PSB+RP | 26,600 | $1,330 |
| No | 201800981 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU48BS3 | S9V2B080U3VSA+RP | 26,600 | $1,330 |
| No | 201801066 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB006DS3 | S9V2B080U3VSA+RP | 26,600 | $1,330 |
| No | 10510996 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB006DS3 | S9V2B080U3PSB+RP | 26,600 | $1,330 |
| No | 8761152 | AMERICAN STANDARD | 4A6V8024A1 | 4TXCB004DS3 | *UHMB080ACV3 | 16,900 | $845 |
| No | 8761150 | AMERICAN STANDARD | 4A6V8024A1 | 4TXCB004DS3 | *UHMB060ACV3 | 16,900 | $845 |
| No | 8761118 | AMERICAN STANDARD | 4A6V0024A1 | 4TXCB004DS3 | *UHMB080ACV3 | 16,900 | $845 |
| No | 207590789 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXCB004DS3 | *UHMB060ACV3 | 16,900 | $845 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10510972 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU48BS3 | S9V2B060U4PSB+RP | 26,400 | $1,320 |
| No | 10510994 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB006DS3 | S9V2B060U4PSB+RP | 26,400 | $1,320 |
| No | 10153458 | AMERICAN STANDARD | 4A6V8037A1 | TEM8A0C36V31+TDR | | 25,600 | $1,280 |
| No | 10510973 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU48BS3 | S9V2B080U3PSB+RP | 26,600 | $1,330 |
| No | 207590192 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCD008DS3 | S9V2C100D4VSA+RP | 25,200 | $1,260 |
| No | 207590116 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCD008DS3 | S9V2C100D4PSB+RP | 25,200 | $1,260 |
| No | 201801087 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCD008DS3 | S9V2C100D4VSA+RP | 25,200 | $1,260 |
| No | 207590191 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCC007DS3 | S9V2C100U4VSA+RP | 26,200 | $1,310 |
| No | 10511002 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCD008DS3 | S9V2C100D4PSB+RP | 25,200 | $1,260 |
| No | 201801083 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCC007DS3 | S9V2C100U4VSA+RP | 26,200 | $1,310 |
| No | 201801015 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CU48BS3 | S9V2C100U4VSA+RP | 26,200 | $1,310 |
| No | 10510979 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CU48BS3 | S9V2C100U4PSB+RP | 26,200 | $1,310 |
| No | 10511000 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCC007DS3 | S9V2C100U4PSB+RP | 26,200 | $1,310 |
| No | 207590769 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU48BS3 | *UHMC100ACV4 | 26,600 | $1,330 |
| No | 8759189 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CU48BS3 | *UHMC100ACV4 | 26,600 | $1,330 |
| No | 207590105 | AMERICAN STANDARD | 4A6V8X24A1 | 4PX*BD36BS3 | S9V2B040D3PSB+RP | 17,300 | $865 |
| No | 207590104 | AMERICAN STANDARD | 4A6V8X24A1 | 4PX*BD36BS3 | S9V2B080D3PSB+RP | 17,300 | $865 |
| No | 10510948 | AMERICAN STANDARD | 4A6V8024A1 | 4PX*BD36BS3 | S9V2B040D3PSB+RP | 17,300 | $865 |
| No | 10510947 | AMERICAN STANDARD | 4A6V8024A1 | 4PX*BD36BS3 | S9V2B080D3PSB+RP | 17,300 | $865 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207590165 | AMERICAN STANDARD | 4A6V8X24A1 | 4PX*BD36BS3 | S9V2B080D3VSA+RP | 17,300 | $865 |
| No | 207590117 | AMERICAN STANDARD | 4A6V0X24A1 | 4PX*BD36BS3 | S9V2B080D3VSA+RP | 17,300 | $865 |
| No | 207590080 | AMERICAN STANDARD | 4A6V0X24A1 | 4PX*BD36BS3 | S9V2B080D3PSB+RP | 17,300 | $865 |
| No | 201800503 | AMERICAN STANDARD | 4A6V0024A1 | 4PX*BD36BS3 | S9V2B080D3VSA+RP | 17,300 | $865 |
| No | 201800873 | AMERICAN STANDARD | 4A6V8024A1 | 4PX*BD36BS3 | S9V2B080D3VSA+RP | 17,300 | $865 |
| No | 10510856 | AMERICAN STANDARD | 4A6V0024A1 | 4PX*BD36BS3 | S9V2B080D3PSB+RP | 17,300 | $865 |
| No | 207590079 | AMERICAN STANDARD | 4A6V0X24A1 | 4PX*BD36BS3 | S9V2B040D3PSB+RP | 17,300 | $865 |
| No | 10510855 | AMERICAN STANDARD | 4A6V0024A1 | 4PX*BD36BS3 | S9V2B040D3PSB+RP | 17,300 | $865 |
| No | 6796548 | AMERICAN STANDARD | 4A6V8024A1 | 4TXFH024CZ3 | *DHMB060BCV3 | 16,700 | $835 |
| No | 207590490 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU48BS3 | S9V2C100U5PSBC+RP | 25,600 | $1,280 |
| No | 206910639 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*CU48BS3 | S9V2C100U5PSBC+RP | 25,600 | $1,280 |
| No | 206910624 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*CU48BS3 | S9V2C100U5PSBC+RP | 25,600 | $1,280 |
| No | 10510953 | AMERICAN STANDARD | 4A6V8024A1 | 4TXCB004DS3 | S9V2B060D3PSB+RP | 16,500 | $825 |
| No | 10510865 | AMERICAN STANDARD | 4A6V0024A1 | 4TXCB004DS3 | S9V2B060D3PSB+RP | 16,500 | $825 |
| No | 207590130 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU48BS3 | S9V2B080U3VSA+RP | 26,600 | $1,330 |
| No | 207590143 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCB006DS3 | S9V2B080U3VSA+RP | 26,600 | $1,330 |
| No | 207590101 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCB006DS3 | S9V2B080U3PSB+RP | 26,600 | $1,330 |
| No | 207590096 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU48BS3 | S9V2B080U3PSB+RP | 26,600 | $1,330 |
| No | 201803243 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB006DS3 | S9V2B080U3VSA+RP | 26,600 | $1,330 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201801126 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU48BS3 | S9V2B080U3VSA+RP | 26,600 | $1,330 |
| No | 201800622 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU48BS3 | S9V2B080U3VSA+RP | 26,600 | $1,330 |
| No | 201800710 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB006DS3 | S9V2B080U3VSA+RP | 26,600 | $1,330 |
| No | 10511036 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB006DS3 | S9V2B080U3PSB+RP | 26,600 | $1,330 |
| No | 10511020 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU48BS3 | S9V2B080U3PSB+RP | 26,600 | $1,330 |
| No | 10510882 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU48BS3 | S9V2B080U3PSB+RP | 26,600 | $1,330 |
| No | 10510898 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB006DS3 | S9V2B080U3PSB+RP | 26,600 | $1,330 |
| No | 207590759 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU48BS3 | *UHMB060ACV3 | 26,400 | $1,320 |
| No | 8759176 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU48BS3 | *UHMB060ACV3 | 26,400 | $1,320 |
| No | 8759188 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CU48BS3 | *UD2C080ACV4 | 26,400 | $1,320 |
| No | 207590698 | AMERICAN STANDARD | 4A6V0X24A1 | 4PX*BD36BS3 | *DHMB060BCV3 | 17,400 | $870 |
| No | 8935198 | AMERICAN STANDARD | 4A6V0024A1 | 4PX*BD36BS3 | *DHMB060BCV3 | 17,400 | $870 |
| No | 207590189 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB006DS3 | S9V2B040U3VSA+RP | 26,400 | $1,320 |
| No | 207590178 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU48BS3 | S9V2B040U3VSA+RP | 26,400 | $1,320 |
| No | 201800972 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU48BS3 | S9V2B040U3VSA+RP | 26,400 | $1,320 |
| No | 201801072 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB006DS3 | S9V2B040U3VSA+RP | 26,400 | $1,320 |
| No | 10510992 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB006DS3 | S9V2B040U3PSB+RP | 26,400 | $1,320 |
| No | 10510990 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB006DS3 | S9V2B080U4PSB+RP | 26,400 | $1,320 |
| No | 10510975 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU48BS3 | S9V2B040U3PSB+RP | 26,400 | $1,320 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10510974 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU48BS3 | S9V2B080U4PSB+RP | 26,400 | $1,320 |
| No | 10511034 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB006DS3 | S9V2B080U4PSB+RP | 26,600 | $1,330 |
| No | 10510883 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU48BS3 | S9V2B080U4PSB+RP | 26,600 | $1,330 |
| No | 10511017 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU48BS3 | S9V2B080U4PSB+RP | 26,600 | $1,330 |
| No | 202366093 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CU48BS3 | *DD2C100ACV5 | 25,800 | $1,290 |
| No | 10510902 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB006DS3 | S9V2B080U4PSB+RP | 26,600 | $1,330 |
| No | 10510900 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB006DS3 | S9V2B060U4PSB+RP | 26,400 | $1,320 |
| No | 10511018 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU48BS3 | S9V2B060U4PSB+RP | 26,400 | $1,320 |
| No | 10510884 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU48BS3 | S9V2B060U4PSB+RP | 26,400 | $1,320 |
| No | 10511037 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB006DS3 | S9V2B060U4PSB+RP | 26,400 | $1,320 |
| No | 207590187 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB006DS3 | S9V2B060U3VSA+RP | 26,400 | $1,320 |
| No | 207590177 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU48BS3 | S9V2B060U3VSA+RP | 26,400 | $1,320 |
| No | 201800965 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU48BS3 | S9V2B060U3VSA+RP | 26,400 | $1,320 |
| No | 10510971 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU48BS3 | S9V2B060U3PSB+RP | 26,400 | $1,320 |
| No | 201801060 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB006DS3 | S9V2B060U3VSA+RP | 26,400 | $1,320 |
| No | 8759144 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*CU48BS3 | *UD2C080ACV4 | 26,600 | $1,330 |
| No | 207590594 | AMERICAN STANDARD | 4A6V0X36A1 | TEM6A0C36H31+TDR+RP | | 25,000 | $1,250 |
| No | 10510991 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB006DS3 | S9V2B060U3PSB+RP | 26,400 | $1,320 |
| No | 8759218 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*CU48BS3 | *UD2C080ACV4 | 26,600 | $1,330 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206918594 | AMERICAN STANDARD | 4A6V8037A1 | TEM6A0C36H31+TDR+RP | | 25,000 | $1,250 |
| No | 206918586 | AMERICAN STANDARD | 4A6V0036A1 | TEM6A0C36H31+TDR+RP | | 25,000 | $1,250 |
| No | 8759132 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU48BS3 | *UD2B080ACV3 | 26,800 | $1,340 |
| No | 207590103 | AMERICAN STANDARD | 4A6V8X24A1 | 4PX*BD36BS3 | S9V2B060D3PSB+RP | 17,200 | $860 |
| No | 207590081 | AMERICAN STANDARD | 4A6V0X24A1 | 4PX*BD36BS3 | S9V2B060D3PSB+RP | 17,200 | $860 |
| No | 10510946 | AMERICAN STANDARD | 4A6V8024A1 | 4PX*BD36BS3 | S9V2B060D3PSB+RP | 17,200 | $860 |
| No | 10510857 | AMERICAN STANDARD | 4A6V0024A1 | 4PX*BD36BS3 | S9V2B060D3PSB+RP | 17,200 | $860 |
| No | 207590726 | AMERICAN STANDARD | 4A6V8X36A1 | TAMXA0B30V3PA | | 26,000 | $1,300 |
| No | 8759146 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*CU48BS3 | *UHMC100ACV4 | 26,800 | $1,340 |
| No | 201800917 | AMERICAN STANDARD | 4A6V8024A1 | 4TXCB004DS3 | S9V2B080D3VSA+RP | 16,500 | $825 |
| No | 207590172 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXCB004DS3 | S9V2B080D3VSA+RP | 16,500 | $825 |
| No | 8759191 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CU48BS3 | *UD2C100ACV5 | 26,200 | $1,310 |
| No | 207590124 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXCB004DS3 | S9V2B080D3VSA+RP | 16,500 | $825 |
| No | 207590663 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU48BS3 | *UHMC100ACV4 | 26,800 | $1,340 |
| No | 201800565 | AMERICAN STANDARD | 4A6V0024A1 | 4TXCB004DS3 | S9V2B080D3VSA+RP | 16,500 | $825 |
| No | 10510954 | AMERICAN STANDARD | 4A6V8024A1 | 4TXCB004DS3 | S9V2B080D3PSB+RP | 16,500 | $825 |
| No | 8761133 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCC007DS3 | *UD2C100ACV5 | 26,200 | $1,310 |
| No | 10510864 | AMERICAN STANDARD | 4A6V0024A1 | 4TXCB004DS3 | S9V2B080D3PSB+RP | 16,500 | $825 |
| No | 207590600 | AMERICAN STANDARD | 4A6V8X36A1 | TEM6A0C36H31+TDR+RP | | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207590289 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCB004DS3 | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 204780087 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB004DS3 | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 207590757 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU48BS3 | *UD2B080ACV3 | 26,600 | $1,330 |
| No | 206918592 | AMERICAN STANDARD | 4A6V8036A1 | TEM6A0C36H31+TDR+RP | | 24,800 | $1,240 |
| No | 8759174 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU48BS3 | *UD2B080ACV3 | 26,600 | $1,330 |
| No | 207590609 | AMERICAN STANDARD | 4A6V8X24A1 | TEM6A0B30H21+TDR+RP | | 16,600 | $830 |
| No | 206918620 | AMERICAN STANDARD | 4A6V8024A1 | TEM6A0B30H21+TDR+RP | | 16,600 | $830 |
| No | 8761173 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCC007DS3 | *UD2C100ACV5 | 25,800 | $1,290 |
| No | 207590142 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCB006DS3 | S9V2B040U3VSA+RP | 26,400 | $1,320 |
| No | 201801210 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB006DS3 | S9V2B040U3VSA+RP | 26,400 | $1,320 |
| No | 201801137 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU48BS3 | S9V2B040U3VSA+RP | 26,400 | $1,320 |
| No | 207590141 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCB006DS3 | S9V2B060U3VSA+RP | 26,400 | $1,320 |
| No | 201801222 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB006DS3 | S9V2B060U3VSA+RP | 26,400 | $1,320 |
| No | 207590131 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU48BS3 | S9V2B060U3VSA+RP | 26,400 | $1,320 |
| No | 201800696 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB006DS3 | S9V2B060U3VSA+RP | 26,400 | $1,320 |
| No | 201801132 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU48BS3 | S9V2B060U3VSA+RP | 26,400 | $1,320 |
| No | 201800702 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB006DS3 | S9V2B040U3VSA+RP | 26,400 | $1,320 |
| No | 201800628 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU48BS3 | S9V2B060U3VSA+RP | 26,400 | $1,320 |
| No | 201800635 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU48BS3 | S9V2B040U3VSA+RP | 26,400 | $1,320 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207590132 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU48BS3 | S9V2B040U3VSA+RP | 26,400 | $1,320 |
| No | 10511035 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB006DS3 | S9V2B040U3PSB+RP | 26,400 | $1,320 |
| No | 10511038 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB006DS3 | S9V2B060U3PSB+RP | 26,400 | $1,320 |
| No | 10511019 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU48BS3 | S9V2B060U3PSB+RP | 26,400 | $1,320 |
| No | 10511016 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU48BS3 | S9V2B040U3PSB+RP | 26,400 | $1,320 |
| No | 10510901 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB006DS3 | S9V2B060U3PSB+RP | 26,400 | $1,320 |
| No | 10510899 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB006DS3 | S9V2B040U3PSB+RP | 26,400 | $1,320 |
| No | 10510881 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU48BS3 | S9V2B040U3PSB+RP | 26,400 | $1,320 |
| No | 10510880 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU48BS3 | S9V2B060U3PSB+RP | 26,400 | $1,320 |
| No | 10510878 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU36BS3 | S9V2B060U3PSB+RP | 26,200 | $1,310 |
| No | 201801121 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU36BS3 | S9V2B080U3VSA+RP | 26,000 | $1,300 |
| No | 10511013 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU36BS3 | S9V2B080U3PSB+RP | 26,000 | $1,300 |
| No | 10510879 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU36BS3 | S9V2B040U3PSB+RP | 26,200 | $1,310 |
| No | 207590606 | AMERICAN STANDARD | 4A6V0X24A1 | TEM6A0B24H21+TDR+RP | | 16,600 | $830 |
| No | 206918617 | AMERICAN STANDARD | 4A6V0024A1 | TEM6A0B24H21+TDR+RP | | 16,600 | $830 |
| No | 207590744 | AMERICAN STANDARD | 4A6V8X24A1 | 4PX*BU36BS3 | *UHMB060ACV3 | 16,900 | $845 |
| No | 207590640 | AMERICAN STANDARD | 4A6V0X24A1 | 4PX*BU36BS3 | *UHMB080ACV3 | 16,900 | $845 |
| No | 8759162 | AMERICAN STANDARD | 4A6V8024A1 | 4PX*BU36BS3 | *UHMB080ACV3 | 16,900 | $845 |
| No | 8759118 | AMERICAN STANDARD | 4A6V0024A1 | 4PX*BU36BS3 | *UHMB060ACV3 | 16,900 | $845 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 8759161 | AMERICAN STANDARD | 4A6V8024A1 | 4PX*BU36BS3 | *UHMB060ACV3 | 16,900 | $845 |
| No | 8759117 | AMERICAN STANDARD | 4A6V0024A1 | 4PX*BU36BS3 | *UHMB080ACV3 | 16,900 | $845 |
| No | 207590598 | AMERICAN STANDARD | 4A6V0X48A1 | TEM6A0D60H51+TDR+RP | | 35,000 | $1,750 |
| No | 206918601 | AMERICAN STANDARD | 4A6V8049A1 | TEM6A0D60H51+TDR+RP | | 35,000 | $1,750 |
| No | 206918590 | AMERICAN STANDARD | 4A6V0048A1 | TEM6A0D60H51+TDR+RP | | 35,000 | $1,750 |
| No | 207590770 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU48BS3 | *UHMB080ACV3 | 26,800 | $1,340 |
| No | 207590065 | AMERICAN STANDARD | 4A6V8X24A1 | TEM8A0B30V31+TDR | | 16,700 | $835 |
| No | 10510993 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB006DS3 | S9V2B080D4PSB+RP | 25,400 | $1,270 |
| No | 8759190 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CU48BS3 | *UHMB080ACV3 | 26,800 | $1,340 |
| No | 10153451 | AMERICAN STANDARD | 4A6V8024A1 | TEM8A0B30V31+TDR | | 16,700 | $835 |
| No | 10511001 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCC007DS3 | S9V2C100D4PSB+RP | 25,000 | $1,250 |
| No | 10510903 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCC005DS3 | S9V2C100U4PSB+RP | 26,000 | $1,300 |
| No | 10510887 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*CU36BS3 | S9V2C100U4PSB+RP | 26,000 | $1,300 |
| No | 201801165 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*CU36BS3 | S9V2C100U4VSA+RP | 26,000 | $1,300 |
| No | 201803245 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCC005DS3 | S9V2C100U4VSA+RP | 26,000 | $1,300 |
| No | 201800723 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCC005DS3 | S9V2C100U4VSA+RP | 26,000 | $1,300 |
| No | 201800654 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*CU36BS3 | S9V2C100U4VSA+RP | 26,000 | $1,300 |
| No | 10511040 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCC005DS3 | S9V2C100U4PSB+RP | 26,000 | $1,300 |
| No | 10511023 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*CU36BS3 | S9V2C100U4PSB+RP | 26,000 | $1,300 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 8759220 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*CU48BS3 | *UHMC100ACV4 | 26,800 | $1,340 |
| No | 10510877 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU36BS3 | S9V2B060U4PSB+RP | 26,000 | $1,300 |
| No | 201801008 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CU36BS3 | S9V2C100U4VSA+RP | 26,000 | $1,300 |
| No | 10510978 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CU36BS3 | S9V2C100U4PSB+RP | 26,000 | $1,300 |
| No | 10510998 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCC005DS3 | S9V2C100U4PSB+RP | 26,000 | $1,300 |
| No | 207590285 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU42BS3 | P0V0B000M40SA+RP | 26,200 | $1,310 |
| No | 204780143 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU42BS3 | P0V0B000M40SA+RP | 26,200 | $1,310 |
| No | 204780083 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU42BS3 | P0V0B000M40SA+RP | 26,200 | $1,310 |
| No | 201801077 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCC005DS3 | S9V2C100U4VSA+RP | 26,000 | $1,300 |
| No | 8759133 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU48BS3 | *UD2B060ACV3 | 26,800 | $1,340 |
| No | 207590652 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU48BS3 | *UD2B060ACV3 | 26,800 | $1,340 |
| No | 10510997 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB006DS3 | S9V2B080D3PSB+RP | 25,400 | $1,270 |
| No | 207590115 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB006DS3 | S9V2B080D3PSB+RP | 25,400 | $1,270 |
| No | 207590232 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU36BS3 | S9V2C100D4PSB+RP | 25,400 | $1,270 |
| No | 8759209 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU48BS3 | *UHMB080ACV3 | 27,000 | $1,350 |
| No | 8759135 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU48BS3 | *UHMB080ACV3 | 27,000 | $1,350 |
| No | 202366092 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CU36BS3 | S9V2C100D4PSB+RP | 25,400 | $1,270 |
| No | 207590631 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXFH036CZ3 | *UD2C080ACV4 | 25,600 | $1,280 |
| No | 6796528 | AMERICAN STANDARD | 4A6V0036A1 | 4TXFH036CZ3 | *UD2C080ACV4 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207590654 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU48BS3 | *UHMB080ACV3 | 27,000 | $1,350 |
| No | 202366090 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU48BS3 | S9V2B080D3PSB+RP | 25,600 | $1,280 |
| No | 10153454 | AMERICAN STANDARD | 4A6V8036A1 | TEM8A0C42V41+TDR | | 25,600 | $1,280 |
| No | 207590329 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU42BS3 | P0V0B000M40SA+RP | 26,000 | $1,300 |
| No | 204780127 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU42BS3 | P0V0B000M40SA+RP | 26,000 | $1,300 |
| No | 207590503 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCC005DS3 | S9V2C100U5PSBC+RP | 25,400 | $1,270 |
| No | 207590501 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU36BS3 | S9V2C100U5PSBC+RP | 25,400 | $1,270 |
| No | 207590758 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU48BS3 | *UD2B060ACV3 | 26,600 | $1,330 |
| No | 206910635 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CU36BS3 | S9V2C100U5PSBC+RP | 25,400 | $1,270 |
| No | 207590756 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU48BS3 | *UHMB080ACV3 | 26,600 | $1,330 |
| No | 8759175 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU48BS3 | *UD2B060ACV3 | 26,600 | $1,330 |
| No | 8759173 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU48BS3 | *UHMB080ACV3 | 26,600 | $1,330 |
| No | 206910637 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCC005DS3 | S9V2C100U5PSBC+RP | 25,400 | $1,270 |
| No | 202492269 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*CU48BS3 | S9V2C100D4PSB+RP | 25,200 | $1,260 |
| No | 202492253 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*CU48BS3 | S9V2C100D4PSB+RP | 25,200 | $1,260 |
| No | 207590833 | AMERICAN STANDARD | 4A6V8X24A1 | 4PX*BU42BS3 | *UHMB060ACV3 | 17,000 | $850 |
| No | 9122737 | AMERICAN STANDARD | 4A6V8024A1 | 4PX*BU42BS3 | *UHMB060ACV3 | 17,000 | $850 |
| No | 8759145 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*CU48BS3 | *UD2C100ACV5 | 26,600 | $1,330 |
| No | 8761163 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB006DS3 | *UD2B080ACV3 | 26,200 | $1,310 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 8761190 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCC007DS3 | *UHMC100ACV4 | 26,200 | $1,310 |
| No | 8761134 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCC007DS3 | *UHMC100ACV4 | 26,200 | $1,310 |
| No | 201800678 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB004DS3 | S9V2B060U3VSA+RP | 26,200 | $1,310 |
| No | 201801177 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB004DS3 | S9V2B060U3VSA+RP | 26,200 | $1,310 |
| No | 10510895 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB004DS3 | S9V2B060U3PSB+RP | 26,200 | $1,310 |
| No | 201801106 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU36BS3 | S9V2B060U3VSA+RP | 26,200 | $1,310 |
| No | 10511032 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB004DS3 | S9V2B060U3PSB+RP | 26,200 | $1,310 |
| No | 201800601 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU36BS3 | S9V2B060U3VSA+RP | 26,200 | $1,310 |
| No | 207590699 | AMERICAN STANDARD | 4A6V0X24A1 | 4PX*BD36BS3+HORIZ-RT | *UD2B060ACV3 | 17,200 | $860 |
| No | 10511011 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU36BS3 | S9V2B060U3PSB+RP | 26,200 | $1,310 |
| No | 10510875 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU36BS3 | S9V2B080U4PSB+RP | 26,000 | $1,300 |
| No | 202366089 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU48BS3 | S9V2B080D4PSB+RP | 25,600 | $1,280 |
| No | 8938514 | AMERICAN STANDARD | 4A6V0024A1 | 4PX*BD36BS3+HORIZ-RT | *UD2B060ACV3 | 17,200 | $860 |
| No | 8761164 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB006DS3 | *UD2B060ACV3 | 26,200 | $1,310 |
| No | 207590326 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 204780124 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU36BS3 | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 7125574 | AMERICAN STANDARD | 4A6V8024A1 | 4TXFH024CZ3 | *DHMB080ACV3 | 16,700 | $835 |
| No | 10510995 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB006DS3 | S9V2B040D3PSB+RP | 25,200 | $1,260 |
| No | 10510989 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB006DS3 | S9V2B060D3PSB+RP | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201800615 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU36BS3 | S9V2B040U3VSA+RP | 26,200 | $1,310 |
| No | 201800670 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB004DS3 | S9V2B040U3VSA+RP | 26,200 | $1,310 |
| No | 201801113 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU36BS3 | S9V2B040U3VSA+RP | 26,200 | $1,310 |
| No | 201801183 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB004DS3 | S9V2B040U3VSA+RP | 26,200 | $1,310 |
| No | 10511033 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB004DS3 | S9V2B040U3PSB+RP | 26,200 | $1,310 |
| No | 10510889 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB004DS3 | S9V2B040U3PSB+RP | 26,200 | $1,310 |
| No | 8761183 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB006DS3 | *UD2B080ACV3 | 26,400 | $1,320 |
| No | 8761175 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCC007DS3 | *UHMC100ACV4 | 25,800 | $1,290 |
| No | 10511015 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU36BS3 | S9V2B040U3PSB+RP | 26,200 | $1,310 |
| No | 8761127 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB006DS3 | *UD2B080ACV3 | 26,400 | $1,320 |
| No | 8759205 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU48BS3 | *UD2B080ACV3 | 26,400 | $1,320 |
| No | 201801037 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB004DS3 | S9V2B040U3VSA+RP | 26,200 | $1,310 |
| No | 201800938 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU36BS3 | S9V2B040U3VSA+RP | 26,200 | $1,310 |
| No | 10510982 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB004DS3 | S9V2B040U3PSB+RP | 26,200 | $1,310 |
| No | 10510967 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU36BS3 | S9V2B040U3PSB+RP | 26,200 | $1,310 |
| No | 204780113 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCD010DS3 | P0V0C000M50SA+RP | 34,400 | $1,720 |
| No | 207590315 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCD010DS3 | P0V0C000M50SA+RP | 34,400 | $1,720 |
| No | 8761120 | AMERICAN STANDARD | 4A6V0024A1 | 4TXCB004DS3 | *DD2B060ACV3 | 16,500 | $825 |
| No | 207590675 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXCB004DS3 | *DD2B060ACV3 | 16,500 | $825 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10153440 | AMERICAN STANDARD | 4A6V0036A1 | TEM8A0C42V41+TDR | | 25,200 | $1,260 |
| No | 207590312 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCD008DS3 | P0V0D000M50SA+RP | 35,800 | $1,790 |
| No | 204780110 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCD008DS3 | P0V0D000M50SA+RP | 35,800 | $1,790 |
| No | 10510891 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB004DS3 | S9V2B060U4PSB+RP | 26,000 | $1,300 |
| No | 10511031 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB004DS3 | S9V2B060U4PSB+RP | 26,000 | $1,300 |
| No | 207590095 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU36BS3 | S9V2B080U3PSB+RP | 26,000 | $1,300 |
| No | 10510980 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB004DS3 | S9V2B060U4PSB+RP | 26,000 | $1,300 |
| No | 10510969 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU36BS3 | S9V2B060U4PSB+RP | 26,000 | $1,300 |
| No | 10510876 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU36BS3 | S9V2B080U3PSB+RP | 26,000 | $1,300 |
| No | 207590736 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXFH036CZ3 | *DHMB060BCV3 | 25,600 | $1,280 |
| No | 7125576 | AMERICAN STANDARD | 4A6V8036A1 | 4TXFH036CZ3 | *DHMB060BCV3 | 25,600 | $1,280 |
| No | 10511012 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU36BS3 | S9V2B060U4PSB+RP | 26,000 | $1,300 |
| No | 202366091 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU48BS3 | S9V2B060D3PSB+RP | 25,400 | $1,270 |
| No | 10510966 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU36BS3 | S9V2B080U4PSB+RP | 26,200 | $1,310 |
| No | 10510988 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB004DS3 | S9V2B080U4PSB+RP | 26,200 | $1,310 |
| No | 6796521 | AMERICAN STANDARD | 4A6V0024A1 | 4TXFH024CZ3 | *DHMB060BCV3 | 16,400 | $820 |
| No | 8759142 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*CU36BS3 | *UD2C080ACV4 | 26,400 | $1,320 |
| No | 204780195 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCD008DS3 | P0V0D000M50SA+RP | 35,800 | $1,790 |
| No | 8759183 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CU36BS3 | *UD2C080ACV4 | 26,200 | $1,310 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10510968 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU36BS3 | S9V2B060U3PSB+RP | 26,200 | $1,310 |
| No | 201800957 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU36BS3 | S9V2B060U3VSA+RP | 26,200 | $1,310 |
| No | 201801022 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB004DS3 | S9V2B060U3VSA+RP | 26,200 | $1,310 |
| No | 10510981 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB004DS3 | S9V2B060U3PSB+RP | 26,200 | $1,310 |
| No | 202492260 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU36BS3 | S9V2B040D3PSB+RP | 25,600 | $1,280 |
| No | 202366087 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU48BS3 | *DD2B080ACV3 | 25,600 | $1,280 |
| No | 206918593 | AMERICAN STANDARD | 4A6V8036A1 | TEM6A0C42H41+TDR+RP | | 25,000 | $1,250 |
| No | 207590181 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CD48BS3 | S9V2C100D4VSA+RP | 26,600 | $1,330 |
| No | 207590601 | AMERICAN STANDARD | 4A6V8X36A1 | TEM6A0C42H41+TDR+RP | | 25,000 | $1,250 |
| No | 201801002 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CD48BS3 | S9V2C100D4VSA+RP | 26,600 | $1,330 |
| No | 207590112 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CD48BS3 | S9V2C100D4PSB+RP | 26,600 | $1,330 |
| No | 8759181 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CU36BS3 | *UHMC100ACV4 | 26,200 | $1,310 |
| No | 10510977 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CD48BS3 | S9V2C100D4PSB+RP | 26,600 | $1,330 |
| No | 207590764 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU36BS3 | *UHMC100ACV4 | 26,200 | $1,310 |
| No | 207590595 | AMERICAN STANDARD | 4A6V0X36A1 | TEM6A0C42H41+TDR+RP | | 25,000 | $1,250 |
| No | 8759140 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*CU36BS3 | *UD2C100ACV5 | 26,400 | $1,320 |
| No | 206918587 | AMERICAN STANDARD | 4A6V0036A1 | TEM6A0C42H41+TDR+RP | | 25,000 | $1,250 |
| No | 206918595 | AMERICAN STANDARD | 4A6V8037A1 | TEM6A0C42H41+TDR+RP | | 25,000 | $1,250 |
| No | 207590488 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU36BS3 | S9V2C100U5PSBC+RP | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207590492 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCC005DS3 | S9V2C100U5PSBC+RP | 25,200 | $1,260 |
| No | 206910640 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCC005DS3 | S9V2C100U5PSBC+RP | 25,200 | $1,260 |
| No | 206910638 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*CU36BS3 | S9V2C100U5PSBC+RP | 25,200 | $1,260 |
| No | 206910626 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCC005DS3 | S9V2C100U5PSBC+RP | 25,200 | $1,260 |
| No | 206910622 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*CU36BS3 | S9V2C100U5PSBC+RP | 25,200 | $1,260 |
| No | 204780147 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB004DS3 | P0V0B000M40SA+RP | 25,400 | $1,270 |
| No | 207590489 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU48BS3 | S9V2C100D5PSBC+RP | 24,800 | $1,240 |
| No | 206910623 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*CU48BS3 | S9V2C100D5PSBC+RP | 24,800 | $1,240 |
| No | 8761165 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCC005DS3 | *UD2C080ACV4 | 26,200 | $1,310 |
| No | 202492247 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU48BS3 | S9V2B040D3PSB+RP | 25,000 | $1,250 |
| No | 207590333 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 204780131 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB004DS3 | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 206753732 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU42BS3 | S9V2B080U4PSB+RP | 26,000 | $1,300 |
| No | 202586185 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*CU42BS3 | *DHMC100ACV4 | 26,800 | $1,340 |
| No | 207590801 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCC005DS3 | *UHMC100ACV4 | 26,200 | $1,310 |
| No | 8761169 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCC005DS3 | *UHMC100ACV4 | 26,200 | $1,310 |
| No | 202492263 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU48BS3 | S9V2B060D3PSB+RP | 25,400 | $1,270 |
| No | 202492250 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU48BS3 | S9V2B060D3PSB+RP | 25,400 | $1,270 |
| No | 8761187 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCC005DS3 | *UD2C080ACV4 | 26,400 | $1,320 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 8761130 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCC005DS3 | *UD2C080ACV4 | 26,400 | $1,320 |
| No | 8759216 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*CU36BS3 | *UD2C080ACV4 | 26,400 | $1,320 |
| No | 10153459 | AMERICAN STANDARD | 4A6V8037A1 | TEM8A0C42V41+TDR | | 25,200 | $1,260 |
| No | 8759184 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CU36BS3 | *UD2C100ACV5 | 26,000 | $1,300 |
| No | 8761167 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCC005DS3 | *UD2C100ACV5 | 26,000 | $1,300 |
| No | 207590298 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CU48BS3 | P0V0C000M50SA+RP | 36,000 | $1,800 |
| No | 204780180 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*CU48BS3 | P0V0C000M50SA+RP | 36,000 | $1,800 |
| No | 204780108 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCC007DS3 | P0V0C000M50SA+RP | 36,000 | $1,800 |
| No | 204780096 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*CU48BS3 | P0V0C000M50SA+RP | 36,000 | $1,800 |
| No | 207590283 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU36BS3 | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 204780081 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU36BS3 | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 204780140 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU36BS3 | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 207590310 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCC007DS3 | P0V0C000M50SA+RP | 36,000 | $1,800 |
| No | 202366088 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU48BS3 | *DHMB060BCV3 | 25,800 | $1,290 |
| No | 207590228 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU48BS3 | *DHMB060BCV3 | 25,800 | $1,290 |
| No | 201801197 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB004DS3 | S9V2B080U3VSA+RP | 26,000 | $1,300 |
| No | 207590128 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU36BS3 | S9V2B080U3VSA+RP | 26,000 | $1,300 |
| No | 207590100 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCB004DS3 | S9V2B080U3PSB+RP | 26,000 | $1,300 |
| No | 201800685 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB004DS3 | S9V2B080U3VSA+RP | 26,000 | $1,300 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207590139 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCB004DS3 | S9V2B080U3VSA+RP | 26,000 | $1,300 |
| No | 201800607 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU36BS3 | S9V2B080U3VSA+RP | 26,000 | $1,300 |
| No | 10510892 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB004DS3 | S9V2B080U3PSB+RP | 26,000 | $1,300 |
| No | 10511030 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB004DS3 | S9V2B080U3PSB+RP | 26,000 | $1,300 |
| No | 207590186 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | S9V2B080U3VSA+RP | 26,000 | $1,300 |
| No | 207590113 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | S9V2B080U3PSB+RP | 26,000 | $1,300 |
| No | 207590175 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | S9V2B080U3VSA+RP | 26,000 | $1,300 |
| No | 201801051 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB004DS3 | S9V2B080U3VSA+RP | 26,000 | $1,300 |
| No | 207590110 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | S9V2B080U3PSB+RP | 26,000 | $1,300 |
| No | 201800950 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU36BS3 | S9V2B080U3VSA+RP | 26,000 | $1,300 |
| No | 10510983 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB004DS3 | S9V2B080U3PSB+RP | 26,000 | $1,300 |
| No | 10511014 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU36BS3 | S9V2B080U4PSB+RP | 26,000 | $1,300 |
| No | 10511029 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB004DS3 | S9V2B080U4PSB+RP | 26,000 | $1,300 |
| No | 202366085 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU36BS3 | S9V2B060D3PSB+RP | 25,400 | $1,270 |
| No | 10510970 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU36BS3 | S9V2B080U3PSB+RP | 26,000 | $1,300 |
| No | 207590659 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CU36BS3 | *UHMC100ACV4 | 26,200 | $1,310 |
| No | 207590681 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCC005DS3 | *UHMC100ACV4 | 26,200 | $1,310 |
| No | 8761129 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCC005DS3 | *UHMC100ACV4 | 26,200 | $1,310 |
| No | 8759214 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*CU36BS3 | *UD2C100ACV5 | 26,400 | $1,320 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10510893 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB004DS3 | S9V2B080U4PSB+RP | 26,000 | $1,300 |
| No | 8759141 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*CU36BS3 | *UHMC100ACV4 | 26,200 | $1,310 |
| No | 8759171 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU36BS3 | *UD2B080ACV3 | 26,400 | $1,320 |
| No | 8761189 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCC005DS3 | *UHMC100ACV4 | 26,200 | $1,310 |
| No | 210435422 | AMERICAN STANDARD | 4TXM2130A14N0** | Heat pump without ducts | | 27,200 | $1,360 |
| No | 210435421 | AMERICAN STANDARD | 4TXM2124A13N0** | Heat pump without ducts | | 23,600 | $1,180 |
| No | 210435420 | AMERICAN STANDARD | 4TXM2118A12N0** | Heat pump without ducts | | 14,700 | $735 |
| No | 8759215 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*CU36BS3 | *UHMC100ACV4 | 26,200 | $1,310 |
| No | 202492265 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU48BS3 | *DD2B080ACV3 | 25,800 | $1,290 |
| No | 202492246 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU48BS3 | *DD2B080ACV3 | 25,800 | $1,290 |
| No | 202366086 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU36BS3 | S9V2B080D3PSB+RP | 25,400 | $1,270 |
| No | 202492249 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU48BS3 | S9V2B080D3PSB+RP | 25,200 | $1,260 |
| No | 205262065 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB004DS3 | S9V2B080U4VSA+RP | 25,600 | $1,280 |
| No | 202492266 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU48BS3 | S9V2B080D3PSB+RP | 25,200 | $1,260 |
| No | 207590330 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU48BS3 | P0V0B000M40SA+RP | 25,000 | $1,250 |
| No | 204780128 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU48BS3 | P0V0B000M40SA+RP | 25,000 | $1,250 |
| No | 8759127 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU36BS3 | *UHMB080ACV3 | 26,600 | $1,330 |
| No | 202492267 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU48BS3 | S9V2B080D4PSB+RP | 25,200 | $1,260 |
| No | 6796529 | AMERICAN STANDARD | 4A6V0036A1 | 4TXFH036CZ3 | *UD2B080ACV3 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202492248 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU48BS3 | S9V2B080D4PSB+RP | 25,200 | $1,260 |
| No | 8761186 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCC005DS3 | *UD2C100ACV5 | 26,400 | $1,320 |
| No | 207590720 | AMERICAN STANDARD | 4A6V8X24A1 | TAMXA0B30V3PA | | 15,800 | $790 |
| No | 6796566 | AMERICAN STANDARD | 4A6V8037A1 | 4TXFH036CZ3 | *UD2B080ACV3 | 25,600 | $1,280 |
| No | 207590762 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CD48BS3 | *DD2C100ACV5 | 26,800 | $1,340 |
| No | 8759179 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CD48BS3 | *DD2C100ACV5 | 26,800 | $1,340 |
| No | 207590734 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXFH036CZ3 | *UD2C080ACV4 | 25,200 | $1,260 |
| No | 6796558 | AMERICAN STANDARD | 4A6V8036A1 | 4TXFH036CZ3 | *UD2C080ACV4 | 25,200 | $1,260 |
| No | 8761182 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB006DS3 | *UHMB060ACV3 | 26,600 | $1,330 |
| No | 8761125 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB006DS3 | *UHMB060ACV3 | 26,600 | $1,330 |
| No | 207590093 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BD48BS3 | S9V2B060D3PSB+RP | 27,000 | $1,350 |
| No | 10511007 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BD48BS3 | S9V2B060D3PSB+RP | 27,000 | $1,350 |
| No | 10510873 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BD48BS3 | S9V2B060D3PSB+RP | 27,000 | $1,350 |
| No | 207590479 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU48BS3 | S9V2B080U4PSA+RP | 25,000 | $1,250 |
| No | 206118999 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CU48BS3 | S9V2B080U4PSA+RP | 25,000 | $1,250 |
| No | 10510962 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BD48BS3 | S9V2B060D3PSB+RP | 26,800 | $1,340 |
| No | 10510965 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BD48BS3 | S9V2B040D3PSB+RP | 26,800 | $1,340 |
| No | 204780085 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU48BS3 | P0V0B000M40SA+RP | 25,000 | $1,250 |
| No | 204780145 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU48BS3 | P0V0B000M40SA+RP | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 8761131 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCC005DS3 | *UD2C100ACV5 | 26,400 | $1,320 |
| No | 206910625 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCC005DS3 | S9V2C100D5PSBC+RP | 25,000 | $1,250 |
| No | 207590491 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCC005DS3 | S9V2C100D5PSBC+RP | 25,000 | $1,250 |
| No | 8761154 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB004DS3 | *UHMB080ACV3 | 26,400 | $1,320 |
| No | 8759170 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU36BS3 | *UD2B060ACV3 | 26,400 | $1,320 |
| No | 207590173 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BD48BS3 | S9V2B080D3VSA+RP | 26,800 | $1,340 |
| No | 201800923 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BD48BS3 | S9V2B080D3VSA+RP | 26,800 | $1,340 |
| No | 10510963 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BD48BS3 | S9V2B080D3PSB+RP | 26,800 | $1,340 |
| No | 8759169 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU36BS3 | *UHMB080ACV3 | 26,400 | $1,320 |
| No | 207590634 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXFH036CZ3 | *DHMB060BCV3 | 25,800 | $1,290 |
| No | 207590485 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU36BS3 | S9V2B060U4PSBC+RP | 25,400 | $1,270 |
| No | 206910634 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU36BS3 | S9V2B060U4PSBC+RP | 25,400 | $1,270 |
| No | 207590500 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | S9V2B060U4PSBC+RP | 25,400 | $1,270 |
| No | 7125572 | AMERICAN STANDARD | 4A6V0036A1 | 4TXFH036CZ3 | *DHMB060BCV3 | 25,800 | $1,290 |
| No | 207590626 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXFH024CZ3 | *UD2B060ACV3 | 16,300 | $815 |
| No | 205962621 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU42BS3 | P0V0B000M40SB+RP | 25,400 | $1,270 |
| No | 207590436 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU42BS3 | P0V0B000M40SB+RP | 25,400 | $1,270 |
| No | 206910619 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU36BS3 | S9V2B060U4PSBC+RP | 25,400 | $1,270 |
| No | 207590630 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXFH036CZ3 | *UHMB080ACV3 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 6796527 | AMERICAN STANDARD | 4A6V0036A1 | 4TXFH036CZ3 | *UHMB080ACV3 | 25,600 | $1,280 |
| No | 10510964 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BD48BS3 | S9V2B080D4PSB+RP | 26,800 | $1,340 |
| No | 207590656 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CD48BS3 | *DD2C100ACV5 | 27,000 | $1,350 |
| No | 8759138 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*CD48BS3 | *DD2C100ACV5 | 27,000 | $1,350 |
| No | 6796518 | AMERICAN STANDARD | 4A6V0024A1 | 4TXFH024CZ3 | *UD2B060ACV3 | 16,300 | $815 |
| No | 8761178 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB004DS3 | *UD2B060ACV3 | 26,200 | $1,310 |
| No | 8761124 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB004DS3 | *UD2B060ACV3 | 26,200 | $1,310 |
| No | 8759203 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU36BS3 | *UD2B060ACV3 | 26,200 | $1,310 |
| No | 10093458 | AMERICAN STANDARD | 4A6V8036A1 | TAM9A0C42V41 | | 25,400 | $1,270 |
| No | 207590047 | AMERICAN STANDARD | 4A6V8X36A1 | TAM9A0C42V41 | | 25,400 | $1,270 |
| No | 207590487 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CD42BS3 | S9V2C100D5PSBC+RP | 25,200 | $1,260 |
| No | 207590287 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU48BS3 | P0V0B000M40SA+RP | 25,200 | $1,260 |
| No | 206910621 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*CD42BS3 | S9V2C100D5PSBC+RP | 25,200 | $1,260 |
| No | 8761121 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB004DS3 | *UHMB080ACV3 | 26,600 | $1,330 |
| No | 8761181 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB004DS3 | *UHMB080ACV3 | 26,600 | $1,330 |
| No | 8759201 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU36BS3 | *UHMB080ACV3 | 26,600 | $1,330 |
| No | 6796567 | AMERICAN STANDARD | 4A6V8037A1 | 4TXFH036CZ3 | *UHMB080ACV3 | 25,600 | $1,280 |
| No | 8761153 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB004DS3 | *UD2B080ACV3 | 26,400 | $1,320 |
| No | 10510922 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCC007DS3 | S9V2C100D5PSB+RP | 35,200 | $1,760 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202492264 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU48BS3 | S9V2B040D3PSB+RP | 25,000 | $1,250 |
| No | 10093448 | AMERICAN STANDARD | 4A6V0036A1 | TAM9A0C36V31 | | 25,200 | $1,260 |
| No | 10093460 | AMERICAN STANDARD | 4A6V8037A1 | TAM9A0C36V31 | | 25,200 | $1,260 |
| No | 204780129 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU48BS3 | P0V0A000M30SA+RP | 24,200 | $1,210 |
| No | 204780144 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU48BS3 | P0V0A000M30SA+RP | 24,400 | $1,220 |
| No | 207590288 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU48BS3 | P0V0A000M30SA+RP | 24,400 | $1,220 |
| No | 204780086 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU48BS3 | P0V0A000M30SA+RP | 24,400 | $1,220 |
| No | 207590331 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU48BS3 | P0V0A000M30SA+RP | 24,200 | $1,210 |
| No | 202492268 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*CD42BS3 | S9V2C100D4PSB+RP | 25,400 | $1,270 |
| No | 202492251 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*CD42BS3 | S9V2C100D4PSB+RP | 25,400 | $1,270 |
| No | 202586186 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CU42BS3 | *DD2C100ACV5 | 25,200 | $1,260 |
| No | 8759129 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU36BS3 | *UD2B060ACV3 | 26,200 | $1,310 |
| No | 202492261 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CD42BS3 | S9V2C100D4PSB+RP | 25,400 | $1,270 |
| No | 8759172 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU36BS3 | *UHMB060ACV3 | 26,600 | $1,330 |
| No | 8761172 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCC007DS3 | *UHMB080ACV3 | 25,400 | $1,270 |
| No | 8761162 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB006DS3 | *UHMB060ACV3 | 26,000 | $1,300 |
| No | 207590765 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CU36BS3 | *UHMB080ACV3 | 26,200 | $1,310 |
| No | 204780084 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU42BS3 | P0V0A000M30SA+RP | 25,400 | $1,270 |
| No | 204780142 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU42BS3 | P0V0A000M30SA+RP | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 8761168 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCC005DS3 | *UHMB080ACV3 | 26,200 | $1,310 |
| No | 207590286 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU42BS3 | P0V0A000M30SA+RP | 25,400 | $1,270 |
| No | 8759182 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CU36BS3 | *UHMB080ACV3 | 26,200 | $1,310 |
| No | 201800993 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CD36BS3 | S9V2C100D4VSA+RP | 26,600 | $1,330 |
| No | 10510976 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CD36BS3 | S9V2C100D4PSB+RP | 26,600 | $1,330 |
| No | 207590800 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCC005DS3 | *UHMB080ACV3 | 26,200 | $1,310 |
| No | 8761156 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB004DS3 | *UD2B060ACV3 | 26,400 | $1,320 |
| No | 207590723 | AMERICAN STANDARD | 4A6V8X48A1 | TAMXA0C48V4PA | | 34,800 | $1,740 |
| No | 205962631 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU42BS3 | P0V0B000M40SB+RP | 25,400 | $1,270 |
| No | 207590290 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCB004DS3 | P0V0A000M30SA+RP | 24,800 | $1,240 |
| No | 204780088 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB004DS3 | P0V0A000M30SA+RP | 24,800 | $1,240 |
| No | 205962580 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU42BS3 | P0V0B000M40SB+RP | 25,400 | $1,270 |
| No | 207590395 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU42BS3 | P0V0B000M40SB+RP | 25,400 | $1,270 |
| No | 207590749 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BD48BS3 | *DD2B080ACV3 | 27,000 | $1,350 |
| No | 8759166 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BD48BS3 | *DD2B080ACV3 | 27,000 | $1,350 |
| No | 202492262 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CD42BS3 | *DD2C100ACV5 | 25,600 | $1,280 |
| No | 8759128 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU36BS3 | *UD2B080ACV3 | 26,000 | $1,300 |
| No | 8761122 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB004DS3 | *UHMB060ACV3 | 26,200 | $1,310 |
| No | 8761180 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB004DS3 | *UHMB060ACV3 | 26,200 | $1,310 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 8759202 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU36BS3 | *UHMB060ACV3 | 26,200 | $1,310 |
| No | 207590653 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU48BS3 | *UHMB060ACV3 | 26,400 | $1,320 |
| No | 8759208 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU48BS3 | *UHMB060ACV3 | 26,400 | $1,320 |
| No | 8759134 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU48BS3 | *UHMB060ACV3 | 26,400 | $1,320 |
| No | 10511116 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCC007DS3 | S9V2C100U5PSB+RP | 36,600 | $1,830 |
| No | 10511097 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*CU48BS3 | S9V2C100U5PSB+RP | 36,600 | $1,830 |
| No | 202492257 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BD42BS3 | S9V2B060D3PSB+RP | 25,800 | $1,290 |
| No | 207590281 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BD42BS3+HORIZ-RT | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 204780138 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BD42BS3+HORIZ-RT | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 204780079 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BD42BS3+HORIZ-RT | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 204780136 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BD42BS3 | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 202492241 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BD42BS3 | S9V2B040D3PSB+RP | 25,600 | $1,280 |
| No | 207590722 | AMERICAN STANDARD | 4A6V8X36A1 | TAMXA0C42V4PA | | 25,000 | $1,250 |
| No | 207590633 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXFH036CZ3 | *UHMB060ACV3 | 25,600 | $1,280 |
| No | 7125571 | AMERICAN STANDARD | 4A6V0036A1 | 4TXFH036CZ3 | *UHMB060ACV3 | 25,600 | $1,280 |
| No | 7125580 | AMERICAN STANDARD | 4A6V8037A1 | 4TXFH036CZ3 | *UHMB060ACV3 | 25,600 | $1,280 |
| No | 205962583 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB004DS3 | P0V0B000M40SB+RP | 24,600 | $1,230 |
| No | 205962633 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB004DS3 | P0V0B000M40SB+RP | 24,600 | $1,230 |
| No | 207590398 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCB004DS3 | P0V0B000M40SB+RP | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10510985 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB004DS3 | S9V2B080D3PSB+RP | 25,600 | $1,280 |
| No | 207590394 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU36BS3 | P0V0B000M40SB+RP | 24,800 | $1,240 |
| No | 205962629 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU36BS3 | P0V0B000M40SB+RP | 24,800 | $1,240 |
| No | 205962579 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU36BS3 | P0V0B000M40SB+RP | 24,800 | $1,240 |
| No | 10153438 | AMERICAN STANDARD | 4A6V0036A1 | TEM8A0B30V31+TDR | | 26,200 | $1,310 |
| No | 204780141 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU36BS3 | P0V0A000M30SA+RP | 24,800 | $1,240 |
| No | 8759136 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*CD36BS3 | *DD2C100ACV5 | 27,200 | $1,360 |
| No | 207590325 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BD42BS3+HORIZ-RT | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 207590322 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BD42BS3 | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 207590655 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*CD36BS3 | *DD2C100ACV5 | 27,200 | $1,360 |
| No | 204780120 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BD42BS3 | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 204780123 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BD42BS3+HORIZ-RT | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 202492255 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BD42BS3 | S9V2B040D3PSB+RP | 25,600 | $1,280 |
| No | 207590798 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCC005DS3 | *UD2B100ACV3 | 26,200 | $1,310 |
| No | 207590062 | AMERICAN STANDARD | 4A6V0X60A1 | TEM8A0C60V51+TDR | | 50,000 | $2,500 |
| No | 8761166 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCC005DS3 | *UD2B100ACV3 | 26,200 | $1,310 |
| No | 10153448 | AMERICAN STANDARD | 4A6V0060A1 | TEM8A0C60V51+TDR | | 50,000 | $2,500 |
| No | 202586190 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*CU42BS3 | *DD2C100ACV5 | 25,400 | $1,270 |
| No | 202586184 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*CU42BS3 | *DD2C100ACV5 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202492244 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BD42BS3 | S9V2B080D3PSB+RP | 25,600 | $1,280 |
| No | 202492245 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BD42BS3 | S9V2B080D4PSB+RP | 25,600 | $1,280 |
| No | 202492259 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BD42BS3 | S9V2B080D3PSB+RP | 25,600 | $1,280 |
| No | 10093457 | AMERICAN STANDARD | 4A6V8036A1 | TAM9A0C36V31 | | 25,200 | $1,260 |
| No | 8759212 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*CD48BS3 | *DD2C100ACV5 | 26,400 | $1,320 |
| No | 207590733 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXFH036CZ3 | *UD2B080ACV3 | 25,400 | $1,270 |
| No | 10153450 | AMERICAN STANDARD | 4A6V0060A1 | TEM8A0D60V51+TDR | | 49,500 | $2,475 |
| No | 207177309 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BD42BS3 | *DD2B060ACV3 | 25,800 | $1,290 |
| No | 6796557 | AMERICAN STANDARD | 4A6V8036A1 | 4TXFH036CZ3 | *UD2B080ACV3 | 25,400 | $1,270 |
| No | 10524438 | AMERICAN STANDARD | 4A6V8024A1 | 4TXCB003DS3 | *UHMB060ACV3 | 18,000 | $900 |
| No | 10511039 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCC005DS3 | S9V2C100D4PSB+RP | 25,600 | $1,280 |
| No | 10510904 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCC005DS3 | S9V2C100D4PSB+RP | 25,600 | $1,280 |
| No | 10524437 | AMERICAN STANDARD | 4A6V8024A1 | 4PX*BU30BS3 | *UHMB060ACV3 | 18,000 | $900 |
| No | 205962624 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB004DS3 | P0V0B000M40SB+RP | 24,600 | $1,230 |
| No | 207590439 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | P0V0B000M40SB+RP | 24,600 | $1,230 |
| No | 201803247 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCC005DS3 | S9V2C100D4VSA+RP | 25,600 | $1,280 |
| No | 207590435 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | P0V0B000M40SB+RP | 24,800 | $1,240 |
| No | 201800717 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCC005DS3 | S9V2C100D4VSA+RP | 25,600 | $1,280 |
| No | 205962620 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU36BS3 | P0V0B000M40SB+RP | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202492242 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BD42BS3 | *DD2B080ACV3 | 26,000 | $1,300 |
| No | 202586187 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CU42BS3 | *DHMC100ACV4 | 25,800 | $1,290 |
| No | 202492256 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BD42BS3 | *DD2B080ACV3 | 25,800 | $1,290 |
| No | 10153472 | AMERICAN STANDARD | 4A6V8060A1 | TEM8A0C60V51+TDR | | 49,000 | $2,450 |
| No | 10153474 | AMERICAN STANDARD | 4A6V8060A1 | TEM8A0D60V51+TDR | | 48,500 | $2,425 |
| No | 207590076 | AMERICAN STANDARD | 4A6V8X60A1 | TEM8A0C60V51+TDR | | 49,000 | $2,450 |
| No | 207590279 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BD42BS3 | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 10093461 | AMERICAN STANDARD | 4A6V8037A1 | TAM9A0C42V41 | | 25,000 | $1,250 |
| No | 204780077 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BD42BS3 | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 202492243 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BD42BS3 | S9V2B060D3PSB+RP | 25,600 | $1,280 |
| No | 202492258 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BD42BS3 | S9V2B080D4PSB+RP | 25,600 | $1,280 |
| No | 10511021 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*CD36BS3 | S9V2C100D4PSB+RP | 26,600 | $1,330 |
| No | 201800641 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*CD36BS3 | S9V2C100D4VSA+RP | 26,600 | $1,330 |
| No | 201801150 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*CD36BS3 | S9V2C100D4VSA+RP | 26,600 | $1,330 |
| No | 10510885 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*CD36BS3 | S9V2C100D4PSB+RP | 26,600 | $1,330 |
| No | 8759210 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*CD36BS3 | *DD2C100ACV5 | 27,200 | $1,360 |
| No | 207590041 | AMERICAN STANDARD | 4A6V0X36A1 | TAM9A0C42V41 | | 24,800 | $1,240 |
| No | 10093449 | AMERICAN STANDARD | 4A6V0036A1 | TAM9A0C42V41 | | 24,800 | $1,240 |
| No | 207590284 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU36BS3 | P0V0A000M30SA+RP | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207590327 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU36BS3 | P0V0A000M30SA+RP | 24,800 | $1,240 |
| No | 204780082 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU36BS3 | P0V0A000M30SA+RP | 24,800 | $1,240 |
| No | 204780125 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU36BS3 | P0V0A000M30SA+RP | 24,800 | $1,240 |
| No | 207590332 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXCB004DS3 | P0V0A000M30SA+RP | 24,800 | $1,240 |
| No | 204780130 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB004DS3 | P0V0A000M30SA+RP | 24,800 | $1,240 |
| No | 207590387 | AMERICAN STANDARD | 4A6V8X60A1 | 4TXCD010DS3 | P0V0D000M50SA+RP | 49,000 | $2,450 |
| No | 207590370 | AMERICAN STANDARD | 4A6V0X60A1 | 4TXCD010DS3 | P0V0D000M50SA+RP | 49,000 | $2,450 |
| No | 207590381 | AMERICAN STANDARD | 4A6V8X60A1 | 4PX*DU60BS3 | P0V0D000M50SA+RP | 49,000 | $2,450 |
| No | 204836804 | AMERICAN STANDARD | 4A6V8060A1 | 4TXCD010DS3 | P0V0D000M50SA+RP | 49,000 | $2,450 |
| No | 204836793 | AMERICAN STANDARD | 4A6V8060A1 | 4PX*DU60BS3 | P0V0D000M50SA+RP | 49,000 | $2,450 |
| No | 207590365 | AMERICAN STANDARD | 4A6V0X60A1 | 4PX*DU60BS3 | P0V0D000M50SA+RP | 49,000 | $2,450 |
| No | 204836771 | AMERICAN STANDARD | 4A6V0060A1 | 4TXCD010DS3 | P0V0D000M50SA+RP | 49,000 | $2,450 |
| No | 204836762 | AMERICAN STANDARD | 4A6V0060A1 | 4PX*DU60BS3 | P0V0D000M50SA+RP | 49,000 | $2,450 |
| No | 10511028 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB004DS3 | S9V2B040D3PSB+RP | 25,400 | $1,270 |
| No | 10510894 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB004DS3 | S9V2B040D3PSB+RP | 25,400 | $1,270 |
| No | 10510987 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB004DS3 | S9V2B040D3PSB+RP | 25,400 | $1,270 |
| No | 207590270 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCB004DS3 | *DHMB060BCV3 | 25,400 | $1,270 |
| No | 204780146 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB004DS3 | P0V0A000M30SA+RP | 24,800 | $1,240 |
| No | 202636142 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB004DS3 | *DHMB060BCV3 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 8759130 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU36BS3 | *UHMB060ACV3 | 26,200 | $1,310 |
| No | 207590761 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*CD36BS3 | *DD2C100ACV5 | 26,800 | $1,340 |
| No | 10153457 | AMERICAN STANDARD | 4A6V8037A1 | TEM8A0B30V31+TDR | | 26,000 | $1,300 |
| No | 8759178 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*CD36BS3 | *DD2C100ACV5 | 26,800 | $1,340 |
| No | 8759167 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BD48BS3 | *DHMB080ACV3 | 27,200 | $1,360 |
| No | 207590750 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BD48BS3 | *DHMB080ACV3 | 27,200 | $1,360 |
| No | 10510986 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB004DS3 | S9V2B060D3PSB+RP | 25,400 | $1,270 |
| No | 10510984 | AMERICAN STANDARD | 4A6V8036A1 | 4TXCB004DS3 | S9V2B080D4PSB+RP | 25,400 | $1,270 |
| No | 10511025 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB004DS3 | S9V2B080D4PSB+RP | 25,400 | $1,270 |
| No | 10510897 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB004DS3 | S9V2B080D4PSB+RP | 25,400 | $1,270 |
| No | 205962630 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BU42BS3 | P0V0A000M30SB+RP | 24,800 | $1,240 |
| No | 207590396 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU42BS3 | P0V0A000M30SB+RP | 24,800 | $1,240 |
| No | 205962581 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU42BS3 | P0V0A000M30SB+RP | 24,800 | $1,240 |
| No | 10511006 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BD36BS3 | S9V2B080D4PSB+RP | 26,800 | $1,340 |
| No | 10510867 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BD36BS3 | S9V2B080D4PSB+RP | 26,800 | $1,340 |
| No | 202586189 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BD42BS3 | *DHMB060BCV3 | 26,000 | $1,300 |
| No | 207590732 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXFH036CZ3 | *UHMB080ACV3 | 25,200 | $1,260 |
| No | 6796556 | AMERICAN STANDARD | 4A6V8036A1 | 4TXFH036CZ3 | *UHMB080ACV3 | 25,200 | $1,260 |
| No | 202586188 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BD42BS3 | *DD2B080ACV3 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207590273 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXCB003DS3 | P0V0A000M30SA+RP | 17,100 | $855 |
| No | 206912697 | AMERICAN STANDARD | 4A6V0036A1 | 4PX*BU42BS3 | P0V0A000M30SC+RP | 24,800 | $1,240 |
| No | 207590510 | AMERICAN STANDARD | 4A6V0X36A1 | 4PX*BU42BS3 | P0V0A000M30SC+RP | 24,800 | $1,240 |
| No | 207590316 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXCB003DS3 | P0V0A000M30SA+RP | 17,100 | $855 |
| No | 204780071 | AMERICAN STANDARD | 4A6V0024A1 | 4TXCB003DS3 | P0V0A000M30SA+RP | 17,100 | $855 |
| No | 204780114 | AMERICAN STANDARD | 4A6V8024A1 | 4TXCB003DS3 | P0V0A000M30SA+RP | 17,100 | $855 |
| No | 10510940 | AMERICAN STANDARD | 4A6V0060A1 | 4TXCD010DS3 | S9V2C080U5PSB+RP | 50,500 | $2,525 |
| No | 10510932 | AMERICAN STANDARD | 4A6V0060A1 | 4PX*DU60BS3 | S9V2C080U5PSB+RP | 50,500 | $2,525 |
| No | 8759198 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*BD48BS3 | *DD2B080ACV3 | 26,600 | $1,330 |
| No | 207590737 | AMERICAN STANDARD | 4A6V8X36A1 | 4TXFH036CZ3 | *UHMB060ACV3 | 25,400 | $1,270 |
| No | 7125577 | AMERICAN STANDARD | 4A6V8036A1 | 4TXFH036CZ3 | *UHMB060ACV3 | 25,400 | $1,270 |
| No | 207590729 | AMERICAN STANDARD | 4A6V8X24A1 | 4TXFH024CZ3 | *UHMB060ACV3 | 16,400 | $820 |
| No | 207590627 | AMERICAN STANDARD | 4A6V0X24A1 | 4TXFH024CZ3 | *UHMB060ACV3 | 16,400 | $820 |
| No | 8938531 | AMERICAN STANDARD | 4A6V8037A1 | 4PX*CD48BS3 | *DHMC100ACV4 | 27,200 | $1,360 |
| No | 6796519 | AMERICAN STANDARD | 4A6V0024A1 | 4TXFH024CZ3 | *UHMB060ACV3 | 16,400 | $820 |
| No | 6796546 | AMERICAN STANDARD | 4A6V8024A1 | 4TXFH024CZ3 | *UHMB060ACV3 | 16,400 | $820 |
| No | 207590213 | AMERICAN STANDARD | 4A6V8X60A1 | 4TXCD010DS3 | S9V2D120U5VSA+RP | 50,000 | $2,500 |
| No | 207590211 | AMERICAN STANDARD | 4A6V8X60A1 | 4PX*DU60BS3 | S9V2D120U5VSA+RP | 50,000 | $2,500 |
| No | 207590162 | AMERICAN STANDARD | 4A6V0X60A1 | 4PX*DU60BS3 | S9V2D120U5VSA+RP | 50,000 | $2,500 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201803319 | AMERICAN STANDARD | 4A6V8060A1 | 4TXCD010DS3 | S9V2D120U5VSA+RP | 50,000 | $2,500 |
| No | 207590164 | AMERICAN STANDARD | 4A6V0X60A1 | 4TXCD010DS3 | S9V2D120U5VSA+RP | 50,000 | $2,500 |
| No | 201803315 | AMERICAN STANDARD | 4A6V8060A1 | 4PX*DU60BS3 | S9V2D120U5VSA+RP | 50,000 | $2,500 |
| No | 201800865 | AMERICAN STANDARD | 4A6V0060A1 | 4TXCD010DS3 | S9V2D120U5VSA+RP | 50,000 | $2,500 |
| No | 201800853 | AMERICAN STANDARD | 4A6V0060A1 | 4PX*DU60BS3 | S9V2D120U5VSA+RP | 50,000 | $2,500 |
| No | 10511149 | AMERICAN STANDARD | 4A6V8060A1 | 4TXCD010DS3 | S9V2D120U5PSB+RP | 50,000 | $2,500 |
| No | 10510943 | AMERICAN STANDARD | 4A6V0060A1 | 4TXCD010DS3 | S9V2D120U5PSB+RP | 50,000 | $2,500 |
| No | 10511141 | AMERICAN STANDARD | 4A6V8060A1 | 4PX*DU60BS3 | S9V2D120U5PSB+RP | 50,000 | $2,500 |
| No | 10510933 | AMERICAN STANDARD | 4A6V0060A1 | 4PX*DU60BS3 | S9V2D120U5PSB+RP | 50,000 | $2,500 |
| No | 207590721 | AMERICAN STANDARD | 4A6V8X36A1 | TAMXA0C36V3PA | | 24,800 | $1,240 |
| No | 10510961 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BD36BS3 | S9V2B080D3PSB+RP | 26,600 | $1,330 |
| No | 201801204 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB004DS3 | S9V2B080D3VSA+RP | 25,400 | $1,270 |
| No | 10511027 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB004DS3 | S9V2B080D3PSB+RP | 25,400 | $1,270 |
| No | 10511026 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCB004DS3 | S9V2B060D3PSB+RP | 25,400 | $1,270 |
| No | 10510896 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB004DS3 | S9V2B080D3PSB+RP | 25,400 | $1,270 |
| No | 10510890 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB004DS3 | S9V2B060D3PSB+RP | 25,400 | $1,270 |
| No | 207590140 | AMERICAN STANDARD | 4A6V0X36A1 | 4TXCB004DS3 | S9V2B080D3VSA+RP | 25,400 | $1,270 |
| No | 201800690 | AMERICAN STANDARD | 4A6V0036A1 | 4TXCB004DS3 | S9V2B080D3VSA+RP | 25,400 | $1,270 |
| No | 207590437 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU42BS3 | P0V0A000M30SB+RP | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205962622 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU42BS3 | P0V0A000M30SB+RP | 24,600 | $1,230 |
| No | 207590551 | AMERICAN STANDARD | 4A6V8X36A1 | 4PX*BU42BS3 | P0V0A000M30SC+RP | 24,600 | $1,230 |
| No | 206912738 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BU42BS3 | P0V0A000M30SC+RP | 24,600 | $1,230 |
| No | 10510960 | AMERICAN STANDARD | 4A6V8036A1 | 4PX*BD36BS3 | S9V2B080D4PSB+RP | 26,600 | $1,330 |
| No | 10511139 | AMERICAN STANDARD | 4A6V8060A1 | 4PX*CU60BS3 | S9V2C080U5PSB+RP | 50,500 | $2,525 |
| No | 10511146 | AMERICAN STANDARD | 4A6V8060A1 | 4TXCC009DS3 | S9V2C080U5PSB+RP | 50,500 | $2,525 |
| No | 10510937 | AMERICAN STANDARD | 4A6V0060A1 | 4TXCC009DS3 | S9V2C080U5PSB+RP | 50,500 | $2,525 |
| No | 10510930 | AMERICAN STANDARD | 4A6V0060A1 | 4PX*CU60BS3 | S9V2C080U5PSB+RP | 50,500 | $2,525 |
| No | 7151532 | AMERICAN STANDARD | 4TXK2712A10NAA | 4MXW2712A10N0AA | | 8,000 | $400 |
| No | 207629148 | AMERICAN STANDARD | 4TXK2536A10N0** | 4MXW2536A10N0** | | 22,600 | $1,130 |
| No | 10093463 | AMERICAN STANDARD | 4A6V8048A1 | TAM9A0C48V41 | | 34,400 | $1,720 |
| No | 207629150 | AMERICAN STANDARD | 4TXK2512A10N0** | 4MXW2512A10N0** | N/A | 7,700 | $385 |
| No | 207642982 | AMERICAN STANDARD | 4TXK2518A10N0** | 4MXW2518A10N0** | N/A | 11,400 | $570 |
| No | 207629152 | AMERICAN STANDARD | 4TXK2524A10N0** | 4MXW2524A10N0** | N/A | 15,500 | $775 |
| No | 202366082 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*CU60BS3 | *DD2C100ACV5 | 35,200 | $1,760 |
| No | 10511093 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*CD60BS3 | S9V2C100D5PSB+RP | 36,400 | $1,820 |
| No | 204780105 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*DU60BS3 | P0V0C000M50SA+RP | 34,400 | $1,720 |
| No | 8759243 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*CU60BS3 | *UHMC100ACV4 | 36,000 | $1,800 |
| No | 8761212 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCC009DS3 | *UHMC100ACV4 | 36,000 | $1,800 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204780151 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CD42BS3 | P0V0C000M50SA+RP | 36,200 | $1,810 |
| No | 207590337 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CD42BS3 | P0V0C000M50SA+RP | 36,200 | $1,810 |
| No | 205962595 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*DU48BS3 | P0V0C000M50SB+RP | 34,800 | $1,740 |
| No | 205962678 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCD008DS3 | P0V0C000M50SB+RP | 34,800 | $1,740 |
| No | 8759153 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*CU60BS3 | *UD2C080ACV4 | 35,800 | $1,790 |
| No | 207590410 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DU48BS3 | P0V0C000M50SB+RP | 34,800 | $1,740 |
| No | 204506102 | AMERICAN STANDARD | 4A6V0048A1 | 4TXFH064AZ3 | *UHMC100ACV4 | 35,800 | $1,790 |
| No | 207590272 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXFH064AZ3 | *UHMC100ACV4 | 35,800 | $1,790 |
| No | 207590255 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*BU48BS3 | S9V2B080D4PSB+RP | 36,400 | $1,820 |
| No | 202492254 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*BU48BS3 | S9V2B080D4PSB+RP | 36,400 | $1,820 |
| No | 8938533 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCD010DS3 | *DHMC100ACV4 | 35,600 | $1,780 |
| No | 207590823 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3 | *DHMC100ACV4 | 35,600 | $1,780 |
| No | 207590297 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CU42BS3 | P0V0C000M50SA+RP | 36,200 | $1,810 |
| No | 204780095 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*CU42BS3 | P0V0C000M50SA+RP | 36,200 | $1,810 |
| No | 204780179 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*CU42BS3 | P0V0C000M50SA+RP | 36,200 | $1,810 |
| No | 8761140 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCC009DS3 | *UHMC100ACV4 | 36,000 | $1,800 |
| No | 205962636 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CD48BS3+HORIZ-RT | P0V0C000M50SB+RP | 37,200 | $1,860 |
| No | 207590688 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCC009DS3 | *UHMC100ACV4 | 36,000 | $1,800 |
| No | 202366081 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*CU48BS3 | S9V2C100D5PSB+RP | 35,400 | $1,770 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204836773 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CD48BS3 | P0V0C000M50SA+RP | 37,200 | $1,860 |
| No | 204836774 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CD48BS3+HORIZ-RT | P0V0C000M50SA+RP | 37,200 | $1,860 |
| No | 205962635 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CD48BS3 | P0V0C000M50SB+RP | 37,200 | $1,860 |
| No | 207590371 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CD48BS3 | P0V0C000M50SA+RP | 37,200 | $1,860 |
| No | 207590372 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CD48BS3+HORIZ-RT | P0V0C000M50SA+RP | 37,200 | $1,860 |
| No | 207590442 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CD48BS3+HORIZ-RT | P0V0C000M50SB+RP | 37,200 | $1,860 |
| No | 207590441 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CD48BS3 | P0V0C000M50SB+RP | 37,200 | $1,860 |
| No | 10511107 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*DU48BS3 | S9V2B080U4PSB+RP | 36,800 | $1,840 |
| No | 10511127 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCD008DS3 | S9V2B080U4PSB+RP | 36,800 | $1,840 |
| No | 10510917 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCB006DS3 | S9V2B080D4PSB+RP | 35,400 | $1,770 |
| No | 10511114 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCB006DS3 | S9V2B080D4PSB+RP | 35,400 | $1,770 |
| No | 207590670 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DU60BS3 | *UHMC100ACV4 | 35,800 | $1,790 |
| No | 206910630 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*DU60BS3 | S9V2C100U5PSBC+RP | 34,200 | $1,710 |
| No | 8759154 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*DU60BS3 | *UHMC100ACV4 | 35,800 | $1,790 |
| No | 8759156 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*DU60BS3 | *UHMD120ACV5 | 36,400 | $1,820 |
| No | 206910627 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*CD60BS3 | S9V2C100D5PSBC+RP | 35,600 | $1,780 |
| No | 207590493 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CD60BS3 | S9V2C100D5PSBC+RP | 35,600 | $1,780 |
| No | 207590496 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DU60BS3 | S9V2C100U5PSBC+RP | 34,200 | $1,710 |
| No | 9119386 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DD60BS3 | *DD2C100ACV5 | 36,400 | $1,820 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207590828 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD60BS3 | *DD2C100ACV5 | 36,400 | $1,820 |
| No | 206910633 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCD010DS3 | S9V2C100U5PSBC+RP | 34,200 | $1,710 |
| No | 207590499 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCD010DS3 | S9V2C100U5PSBC+RP | 34,200 | $1,710 |
| No | 10510907 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*BU48BS3 | S9V2B080U4PSB+RP | 37,200 | $1,860 |
| No | 10510916 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCB006DS3 | S9V2B080U4PSB+RP | 37,200 | $1,860 |
| No | 10511091 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*BU48BS3 | S9V2B080U4PSB+RP | 37,200 | $1,860 |
| No | 10511112 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCB006DS3 | S9V2B080U4PSB+RP | 37,200 | $1,860 |
| No | 10153462 | AMERICAN STANDARD | 4A6V8048A1 | TEM8A0C42V41+TDR | | 36,000 | $1,800 |
| No | 10153463 | AMERICAN STANDARD | 4A6V8048A1 | TEM8A0C48V41+TDR | | 34,200 | $1,710 |
| No | 8759152 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*CU60BS3 | *UHMC100ACV4 | 36,000 | $1,800 |
| No | 207590668 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CU60BS3 | *UHMC100ACV4 | 36,000 | $1,800 |
| No | 10093462 | AMERICAN STANDARD | 4A6V8048A1 | TAM9A0C42V41 | | 36,200 | $1,810 |
| No | 9119384 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DD60BS3 | *DHMD120BCV5 | 36,400 | $1,820 |
| No | 10511105 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*DD60BS3 | S9V2C100D5PSB+RP | 35,000 | $1,750 |
| No | 207590826 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD60BS3 | *DHMD120BCV5 | 36,400 | $1,820 |
| No | 207590835 | AMERICAN STANDARD | 4A6V8X48A1 | TAM9A0C42V41 | | 36,200 | $1,810 |
| No | 201800781 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*DD60BS3 | S9V2C100D4VSA+RP | 35,000 | $1,750 |
| No | 204340749 | AMERICAN STANDARD | 4A6V0048A1 | 4TXFH064AZ3 | *UD2C080ACV4 | 36,200 | $1,810 |
| No | 206910628 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*CU48BS3 | S9V2C100U5PSBC+RP | 35,800 | $1,790 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206910631 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCC007DS3 | S9V2C100U5PSBC+RP | 35,800 | $1,790 |
| No | 207590494 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CU48BS3 | S9V2C100U5PSBC+RP | 35,800 | $1,790 |
| No | 207590497 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCC007DS3 | S9V2C100U5PSBC+RP | 35,800 | $1,790 |
| No | 10511104 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*DD60BS3 | S9V2C100D4PSB+RP | 35,000 | $1,750 |
| No | 201803294 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*DD60BS3 | S9V2C100D4VSA+RP | 35,000 | $1,750 |
| No | 10511042 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*BD48BS3 | S9V2B080D4PSB+RP | 39,000 | $1,950 |
| No | 205962585 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*CD60BS3 | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 10511106 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*DU48BS3 | S9V2B060U4PSB+RP | 36,800 | $1,840 |
| No | 205962586 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*CD60BS3+HORIZ-RT | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 10511129 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCD008DS3 | S9V2B060U4PSB+RP | 36,800 | $1,840 |
| No | 205962662 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*CD60BS3 | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 205962663 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*CD60BS3+HORIZ-RT | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 207590400 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CD60BS3 | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 207590401 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CD60BS3+HORIZ-RT | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 205962647 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DD60BS3 | P0V0C000M50SB+RP | 34,600 | $1,730 |
| No | 207590453 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD60BS3 | P0V0C000M50SB+RP | 34,600 | $1,730 |
| No | 205962649 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DD60BS3+HORIZ-RT | P0V0C000M50SB+RP | 34,600 | $1,730 |
| No | 207590455 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD60BS3+HORIZ-RT | P0V0C000M50SB+RP | 34,600 | $1,730 |
| No | 207590450 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD48BS3+HORIZ-RT | P0V0D000M50SB+RP | 37,000 | $1,850 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205962642 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DD48BS3 | P0V0D000M50SB+RP | 37,000 | $1,850 |
| No | 205962644 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DD48BS3+HORIZ-RT | P0V0D000M50SB+RP | 37,000 | $1,850 |
| No | 207590448 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD48BS3 | P0V0D000M50SB+RP | 37,000 | $1,850 |
| No | 207590224 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DU60BS3 | *DD2D120ACV5 | 34,600 | $1,730 |
| No | 202366084 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*DU60BS3 | *DD2D120ACV5 | 34,600 | $1,730 |
| No | 207590602 | AMERICAN STANDARD | 4A6V8X48A1 | TEM6A0C42H41+TDR+RP | | 35,600 | $1,780 |
| No | 206918596 | AMERICAN STANDARD | 4A6V8048A1 | TEM6A0C42H41+TDR+RP | | 35,600 | $1,780 |
| No | 202366080 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*CU48BS3 | S9V2C100D4PSB+RP | 36,000 | $1,800 |
| No | 202366083 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*DU48BS3 | S9V2D120D5PSB+RP | 35,600 | $1,780 |
| No | 10510908 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*CD60BS3 | S9V2C100D4PSB+RP | 36,400 | $1,820 |
| No | 8761145 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCD010DS3 | *DD2D120ACV5 | 34,400 | $1,720 |
| No | 207590693 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCD010DS3 | *DD2D120ACV5 | 34,400 | $1,720 |
| No | 201800739 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*CD60BS3 | S9V2C100D4VSA+RP | 36,400 | $1,820 |
| No | 201803285 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*CD60BS3 | S9V2C100D4VSA+RP | 36,400 | $1,820 |
| No | 10511094 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*CD60BS3 | S9V2C100D4PSB+RP | 36,400 | $1,820 |
| No | 10511058 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DD48BS3 | S9V2D120D5PSB+RP | 38,000 | $1,900 |
| No | 10511046 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CD48BS3 | S9V2C100D4PSB+RP | 38,500 | $1,925 |
| No | 207590193 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CD48BS3 | S9V2C100D4VSA+RP | 38,500 | $1,925 |
| No | 201803251 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CD48BS3 | S9V2C100D4VSA+RP | 38,500 | $1,925 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207590375 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD48BS3+HORIZ-RT | P0V0D000M50SA+RP | 37,200 | $1,860 |
| No | 204836779 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DD48BS3 | P0V0D000M50SA+RP | 37,200 | $1,860 |
| No | 204836780 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DD48BS3+HORIZ-RT | P0V0D000M50SA+RP | 37,200 | $1,860 |
| No | 207590374 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD48BS3 | P0V0D000M50SA+RP | 37,200 | $1,860 |
| No | 205962591 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*DD60BS3 | P0V0D000M50SB+RP | 35,000 | $1,750 |
| No | 205962599 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCC007DS3 | P0V0C000M50SB+RP | 35,800 | $1,790 |
| No | 205962670 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*DD60BS3+HORIZ-RT | P0V0D000M50SB+RP | 35,000 | $1,750 |
| No | 205962667 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*DD60BS3 | P0V0D000M50SB+RP | 35,000 | $1,750 |
| No | 207590406 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DD60BS3 | P0V0D000M50SB+RP | 35,000 | $1,750 |
| No | 204780149 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*BU42BS3 | P0V0B000M40SA+RP | 35,000 | $1,750 |
| No | 205962588 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*CU48BS3 | P0V0C000M50SB+RP | 35,800 | $1,790 |
| No | 205962665 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*CU48BS3 | P0V0C000M50SB+RP | 35,800 | $1,790 |
| No | 207590335 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*BU42BS3 | P0V0B000M40SA+RP | 35,000 | $1,750 |
| No | 207590403 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CU48BS3 | P0V0C000M50SB+RP | 35,800 | $1,790 |
| No | 205962676 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCC007DS3 | P0V0C000M50SB+RP | 35,800 | $1,790 |
| No | 207590414 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCC007DS3 | P0V0C000M50SB+RP | 35,800 | $1,790 |
| No | 10510909 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*CU48BS3 | S9V2C080U5PSB+RP | 36,600 | $1,830 |
| No | 10510920 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCC007DS3 | S9V2C080U5PSB+RP | 36,600 | $1,830 |
| No | 10511119 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCC007DS3 | S9V2C080U5PSB+RP | 36,600 | $1,830 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204780177 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*CD60BS3 | P0V0C000M50SA+RP | 35,600 | $1,780 |
| No | 10511095 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*CU48BS3 | S9V2C080U5PSB+RP | 36,600 | $1,830 |
| No | 204780093 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*CD60BS3 | P0V0C000M50SA+RP | 35,600 | $1,780 |
| No | 204780094 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*CD60BS3+HORIZ-RT | P0V0C000M50SA+RP | 35,600 | $1,780 |
| No | 204780178 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*CD60BS3+HORIZ-RT | P0V0C000M50SA+RP | 35,600 | $1,780 |
| No | 207590295 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CD60BS3 | P0V0C000M50SA+RP | 35,600 | $1,780 |
| No | 207590296 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CD60BS3+HORIZ-RT | P0V0C000M50SA+RP | 35,600 | $1,780 |
| No | 204780157 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DD60BS3 | P0V0C000M50SA+RP | 34,800 | $1,740 |
| No | 204780160 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DD60BS3+HORIZ-RT | P0V0C000M50SA+RP | 34,800 | $1,740 |
| No | 207590346 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD60BS3+HORIZ-RT | P0V0C000M50SA+RP | 34,800 | $1,740 |
| No | 207590343 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD60BS3 | P0V0C000M50SA+RP | 34,800 | $1,740 |
| No | 10511060 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DD60BS3 | S9V2C100D4PSB+RP | 35,600 | $1,780 |
| No | 201803265 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DD60BS3 | S9V2C100D4VSA+RP | 35,600 | $1,780 |
| No | 10510924 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCD008DS3 | S9V2D120D5PSB+RP | 35,000 | $1,750 |
| No | 207590777 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU48BS3 | *UHMC100ACV4 | 37,200 | $1,860 |
| No | 8759227 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU48BS3 | *UHMC100ACV4 | 37,200 | $1,860 |
| No | 10511118 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCC007DS3 | S9V2C100D4PSB+RP | 35,200 | $1,760 |
| No | 10510919 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCC007DS3 | S9V2C100D4PSB+RP | 35,200 | $1,760 |
| No | 10511130 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCD008DS3 | S9V2D120D5PSB+RP | 35,000 | $1,750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204780192 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCC007DS3 | P0V0C000M50SA+RP | 36,000 | $1,800 |
| No | 204780098 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*DD60BS3 | P0V0D000M50SA+RP | 35,200 | $1,760 |
| No | 204780185 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*DD60BS3+HORIZ-RT | P0V0D000M50SA+RP | 35,200 | $1,760 |
| No | 204780182 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*DD60BS3 | P0V0D000M50SA+RP | 35,200 | $1,760 |
| No | 207590300 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DD60BS3 | P0V0D000M50SA+RP | 35,200 | $1,760 |
| No | 10511115 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCC007DS3 | S9V2D120U5PSB+RP | 36,800 | $1,840 |
| No | 10511098 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*CU48BS3 | S9V2D120U5PSB+RP | 36,800 | $1,840 |
| No | 10511128 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCD008DS3 | S9V2C100D4PSB+RP | 35,200 | $1,760 |
| No | 201800755 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*CU48BS3 | S9V2D120U5VSA+RP | 36,800 | $1,840 |
| No | 201800803 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCC007DS3 | S9V2D120U5VSA+RP | 36,800 | $1,840 |
| No | 207590149 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CU48BS3 | S9V2D120U5VSA+RP | 36,800 | $1,840 |
| No | 201803289 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*CU48BS3 | S9V2D120U5VSA+RP | 36,800 | $1,840 |
| No | 201803302 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCC007DS3 | S9V2D120U5VSA+RP | 36,800 | $1,840 |
| No | 207590155 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCC007DS3 | S9V2D120U5VSA+RP | 36,800 | $1,840 |
| No | 10511045 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CD48BS3 | S9V2C100D5PSB+RP | 38,500 | $1,925 |
| No | 8759225 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU48BS3 | *UD2C100ACV5 | 37,200 | $1,860 |
| No | 8759231 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU60BS3 | *UD2C080ACV4 | 36,400 | $1,820 |
| No | 204780166 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC005DS3 | P0V0C000M50SA+RP | 36,000 | $1,800 |
| No | 205962654 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC005DS3 | P0V0C000M50SB+RP | 36,000 | $1,800 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207590352 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC005DS3 | P0V0C000M50SA+RP | 36,000 | $1,800 |
| No | 207590460 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC005DS3 | P0V0C000M50SB+RP | 36,000 | $1,800 |
| No | 10511120 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCC007DS3 | S9V2C100D5PSB+RP | 35,200 | $1,760 |
| No | 205962679 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCD008DS3 | P0V0D000M50SB+RP | 35,800 | $1,790 |
| No | 204780103 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*DU48BS3 | P0V0D000M50SA+RP | 35,800 | $1,790 |
| No | 205962601 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCD008DS3 | P0V0D000M50SB+RP | 35,800 | $1,790 |
| No | 205962594 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*DU48BS3 | P0V0D000M50SB+RP | 35,800 | $1,790 |
| No | 205962671 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*DU48BS3 | P0V0D000M50SB+RP | 35,800 | $1,790 |
| No | 207590305 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DU48BS3 | P0V0D000M50SA+RP | 35,800 | $1,790 |
| No | 207590409 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DU48BS3 | P0V0D000M50SB+RP | 35,800 | $1,790 |
| No | 207590416 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCD008DS3 | P0V0D000M50SB+RP | 35,800 | $1,790 |
| No | 204780152 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CD60BS3 | P0V0C000M50SA+RP | 35,800 | $1,790 |
| No | 204780153 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CD60BS3+HORIZ-RT | P0V0C000M50SA+RP | 35,800 | $1,790 |
| No | 205962638 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CD60BS3+HORIZ-RT | P0V0C000M50SB+RP | 35,800 | $1,790 |
| No | 205962637 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CD60BS3 | P0V0C000M50SB+RP | 35,800 | $1,790 |
| No | 207590338 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CD60BS3 | P0V0C000M50SA+RP | 35,800 | $1,790 |
| No | 207590339 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CD60BS3+HORIZ-RT | P0V0C000M50SA+RP | 35,800 | $1,790 |
| No | 207590443 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CD60BS3 | P0V0C000M50SB+RP | 35,800 | $1,790 |
| No | 207590444 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CD60BS3+HORIZ-RT | P0V0C000M50SB+RP | 35,800 | $1,790 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207590774 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CD60BS3 | *DD2C100ACV5 | 36,800 | $1,840 |
| No | 8759223 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CD60BS3 | *DD2C100ACV5 | 36,800 | $1,840 |
| No | 10511121 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCC007DS3 | S9V2D120D5PSB+RP | 35,200 | $1,760 |
| No | 8759233 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU60BS3 | *UHMC100ACV4 | 36,600 | $1,830 |
| No | 207590782 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU60BS3 | *UHMC100ACV4 | 36,600 | $1,830 |
| No | 8761194 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC007DS3 | *UD2C100ACV5 | 37,200 | $1,860 |
| No | 205962658 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCD008DS3 | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 205962650 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DU48BS3 | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 204780100 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*DD60BS3+HORIZ-RT | P0V0D000M50SA+RP | 35,400 | $1,770 |
| No | 205962593 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*DD60BS3+HORIZ-RT | P0V0D000M50SB+RP | 35,400 | $1,770 |
| No | 207590408 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DD60BS3+HORIZ-RT | P0V0D000M50SB+RP | 35,400 | $1,770 |
| No | 207590302 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DD60BS3+HORIZ-RT | P0V0D000M50SA+RP | 35,400 | $1,770 |
| No | 207590464 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 207590456 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3 | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 9119383 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DD60BS3 | *DD2D120ACV5 | 36,800 | $1,840 |
| No | 8761196 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC007DS3 | *UHMC100ACV4 | 37,200 | $1,860 |
| No | 207590804 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC007DS3 | *UHMC100ACV4 | 37,200 | $1,860 |
| No | 10511126 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCD008DS3 | S9V2C100D5PSB+RP | 35,200 | $1,760 |
| No | 202492270 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*BU48BS3 | S9V2B080D4PSB+RP | 36,800 | $1,840 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206910629 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*CU60BS3 | S9V2C100U5PSBC+RP | 35,600 | $1,780 |
| No | 207590495 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CU60BS3 | S9V2C100U5PSBC+RP | 35,600 | $1,780 |
| No | 207590498 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCC009DS3 | S9V2C100U5PSBC+RP | 35,600 | $1,780 |
| No | 206910632 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCC009DS3 | S9V2C100U5PSBC+RP | 35,600 | $1,780 |
| No | 204780150 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*BU48BS3 | P0V0B000M40SA+RP | 37,000 | $1,850 |
| No | 207590336 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*BU48BS3 | P0V0B000M40SA+RP | 37,000 | $1,850 |
| No | 10511067 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCB006DS3 | S9V2B080U4PSB+RP | 37,800 | $1,890 |
| No | 10511043 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*BU48BS3 | S9V2B080U4PSB+RP | 37,800 | $1,890 |
| No | 8759234 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU60BS3 | *UD2D120ACV5 | 36,600 | $1,830 |
| No | 207590783 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU60BS3 | *UD2D120ACV5 | 36,600 | $1,830 |
| No | 8761197 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC007DS3 | *UD2C080ACV4 | 37,600 | $1,880 |
| No | 8759228 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU48BS3 | *UD2C080ACV4 | 37,600 | $1,880 |
| No | 10510912 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*DD60BS3 | S9V2D120D5PSB+RP | 36,200 | $1,810 |
| No | 10511103 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*DD60BS3 | S9V2D120D5PSB+RP | 36,200 | $1,810 |
| No | 8759229 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU48BS3 | *UD2D120ACV5 | 37,600 | $1,880 |
| No | 8759230 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU60BS3 | *UD2C100ACV5 | 36,600 | $1,830 |
| No | 207590779 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU48BS3 | *UD2D120ACV5 | 37,600 | $1,880 |
| No | 10511069 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCB006DS3 | S9V2B080D4PSB+RP | 36,000 | $1,800 |
| No | 8761199 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC009DS3 | *UD2C080ACV4 | 36,400 | $1,820 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205962600 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCC009DS3 | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 205962589 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*CU60BS3 | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 205962677 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCC009DS3 | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 207590415 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCC009DS3 | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 205962666 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*CU60BS3 | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 207590404 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CU60BS3 | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 8759236 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DU60BS3 | *UHMD120ACV5 | 37,200 | $1,860 |
| No | 8233511 | AMERICAN STANDARD | 4A6V8048A1 | 4TXFH064AZ3 | *UHMD120ACV5 | 37,600 | $1,880 |
| No | 207590739 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXFH064AZ3 | *UHMD120ACV5 | 37,600 | $1,880 |
| No | 205962639 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU42BS3 | P0V0C000M50SB+RP | 36,800 | $1,840 |
| No | 8761208 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCD010DS3 | *UHMD120ACV5 | 37,200 | $1,860 |
| No | 207590445 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU42BS3 | P0V0C000M50SB+RP | 36,800 | $1,840 |
| No | 207590808 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC009DS3 | *UHMC100ACV4 | 36,600 | $1,830 |
| No | 8761201 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC009DS3 | *UHMC100ACV4 | 36,600 | $1,830 |
| No | 10511062 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DD60BS3 | S9V2C100D5PSB+RP | 36,000 | $1,800 |
| No | 8233510 | AMERICAN STANDARD | 4A6V8048A1 | 4TXFH064AZ3 | *UHMC100ACV4 | 37,000 | $1,850 |
| No | 207590738 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXFH064AZ3 | *UHMC100ACV4 | 37,000 | $1,850 |
| No | 10511109 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*DU60BS3 | S9V2C100U4PSB+RP | 36,400 | $1,820 |
| No | 10510914 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*DU60BS3 | S9V2C100U4PSB+RP | 36,400 | $1,820 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10510927 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCD010DS3 | S9V2C100U4PSB+RP | 36,400 | $1,820 |
| No | 201800788 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*DU60BS3 | S9V2C100U4VSA+RP | 36,400 | $1,820 |
| No | 10511132 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCD010DS3 | S9V2C100U4PSB+RP | 36,400 | $1,820 |
| No | 201800839 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCD010DS3 | S9V2C100U4VSA+RP | 36,400 | $1,820 |
| No | 201803297 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*DU60BS3 | S9V2C100U4VSA+RP | 36,400 | $1,820 |
| No | 201803308 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCD010DS3 | S9V2C100U4VSA+RP | 36,400 | $1,820 |
| No | 10511068 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCB006DS3 | S9V2B060U4PSB+RP | 37,800 | $1,890 |
| No | 202366095 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU48BS3 | S9V2C100D4PSB+RP | 36,200 | $1,810 |
| No | 10511044 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*BU48BS3 | S9V2B060U4PSB+RP | 37,800 | $1,890 |
| No | 207599969 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*BU48BS3 | S9V2B060U4PSB+RP | 37,800 | $1,890 |
| No | 207599973 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCB006DS3 | S9V2B060U4PSB+RP | 37,800 | $1,890 |
| No | 205962653 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DU60BS3 | P0V0C000M50SB+RP | 35,000 | $1,750 |
| No | 205962659 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCD010DS3 | P0V0C000M50SB+RP | 35,000 | $1,750 |
| No | 207590465 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3 | P0V0C000M50SB+RP | 35,000 | $1,750 |
| No | 207590459 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | P0V0C000M50SB+RP | 35,000 | $1,750 |
| No | 10093452 | AMERICAN STANDARD | 4A6V0048A1 | TAM9A0C60V51 | | 35,600 | $1,780 |
| No | 202366098 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DU48BS3 | S9V2D120D5PSB+RP | 36,000 | $1,800 |
| No | 10093467 | AMERICAN STANDARD | 4A6V8049A1 | TAM9A0C60V51 | | 35,600 | $1,780 |
| No | 207590724 | AMERICAN STANDARD | 4A6V8X48A1 | TAMXA0C60V5PA | | 35,200 | $1,760 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10511099 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*CU60BS3 | S9V2C080U5PSB+RP | 36,400 | $1,820 |
| No | 10511123 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCC009DS3 | S9V2D120U5PSB+RP | 36,400 | $1,820 |
| No | 10511102 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*CU60BS3 | S9V2D120U5PSB+RP | 36,400 | $1,820 |
| No | 10511124 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCC009DS3 | S9V2C080U5PSB+RP | 36,400 | $1,820 |
| No | 201800775 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*CU60BS3 | S9V2D120U5VSA+RP | 36,400 | $1,820 |
| No | 201800826 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCC009DS3 | S9V2D120U5VSA+RP | 36,400 | $1,820 |
| No | 201803293 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*CU60BS3 | S9V2D120U5VSA+RP | 36,400 | $1,820 |
| No | 201803306 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCC009DS3 | S9V2D120U5VSA+RP | 36,400 | $1,820 |
| No | 207590151 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CU60BS3 | S9V2D120U5VSA+RP | 36,400 | $1,820 |
| No | 207590158 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCC009DS3 | S9V2D120U5VSA+RP | 36,400 | $1,820 |
| No | 204780161 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DU48BS3 | P0V0C000M50SA+RP | 35,600 | $1,780 |
| No | 204780169 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCD008DS3 | P0V0C000M50SA+RP | 35,600 | $1,780 |
| No | 207590347 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3 | P0V0C000M50SA+RP | 35,600 | $1,780 |
| No | 207590355 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | P0V0C000M50SA+RP | 35,600 | $1,780 |
| No | 205962656 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC009DS3 | P0V0C000M50SB+RP | 35,600 | $1,780 |
| No | 202366099 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DU60BS3 | *DD2D120ACV5 | 35,200 | $1,760 |
| No | 207590239 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | *DD2D120ACV5 | 35,200 | $1,760 |
| No | 10511083 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCD008DS3 | S9V2C100D5PSB+RP | 35,200 | $1,760 |
| No | 207599979 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | S9V2C100D5PSB+RP | 35,200 | $1,760 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205962641 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU60BS3 | P0V0C000M50SB+RP | 35,600 | $1,780 |
| No | 207590447 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU60BS3 | P0V0C000M50SB+RP | 35,600 | $1,780 |
| No | 207590462 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC009DS3 | P0V0C000M50SB+RP | 35,600 | $1,780 |
| No | 10511100 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*CU60BS3 | S9V2C100U4PSB+RP | 36,600 | $1,830 |
| No | 10511122 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCC009DS3 | S9V2C100U4PSB+RP | 36,600 | $1,830 |
| No | 201800766 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*CU60BS3 | S9V2C100U4VSA+RP | 36,600 | $1,830 |
| No | 201803291 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*CU60BS3 | S9V2C100U4VSA+RP | 36,600 | $1,830 |
| No | 201800818 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCC009DS3 | S9V2C100U4VSA+RP | 36,600 | $1,830 |
| No | 201803305 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCC009DS3 | S9V2C100U4VSA+RP | 36,600 | $1,830 |
| No | 8761202 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC009DS3 | *UD2C100ACV5 | 36,600 | $1,830 |
| No | 204780154 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU42BS3 | P0V0C000M50SA+RP | 37,000 | $1,850 |
| No | 207590340 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU42BS3 | P0V0C000M50SA+RP | 37,000 | $1,850 |
| No | 204780097 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*CU60BS3 | P0V0C000M50SA+RP | 35,600 | $1,780 |
| No | 204780181 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*CU60BS3 | P0V0C000M50SA+RP | 35,600 | $1,780 |
| No | 207590299 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*CU60BS3 | P0V0C000M50SA+RP | 35,600 | $1,780 |
| No | 204780186 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*DU48BS3 | P0V0D000M50SA+RP | 35,800 | $1,790 |
| No | 10510915 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*DU60BS3 | S9V2C080U5PSB+RP | 36,400 | $1,820 |
| No | 10510925 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCD010DS3 | S9V2C080U5PSB+RP | 36,400 | $1,820 |
| No | 202366100 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DU60BS3 | *DHMD120BCV5 | 35,600 | $1,780 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10511134 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCD010DS3 | S9V2C080U5PSB+RP | 36,400 | $1,820 |
| No | 207590240 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | *DHMD120BCV5 | 35,600 | $1,780 |
| No | 202366096 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU48BS3 | S9V2C100D5PSB+RP | 36,200 | $1,810 |
| No | 10511108 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*DU60BS3 | S9V2C080U5PSB+RP | 36,400 | $1,820 |
| No | 8759235 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DU60BS3 | *UD2D120ACV5 | 37,000 | $1,850 |
| No | 8761205 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCD010DS3 | *UD2D120ACV5 | 37,000 | $1,850 |
| No | 10511110 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*DU60BS3 | S9V2C100U5PSB+RP | 36,400 | $1,820 |
| No | 10511133 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCD010DS3 | S9V2C100U5PSB+RP | 36,400 | $1,820 |
| No | 10511048 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CD60BS3 | S9V2C100D4PSB+RP | 37,400 | $1,870 |
| No | 201803253 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CD60BS3 | S9V2C100D4VSA+RP | 37,400 | $1,870 |
| No | 10511075 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC007DS3 | S9V2C100D4PSB+RP | 35,800 | $1,790 |
| No | 205962655 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC007DS3 | P0V0C000M50SB+RP | 36,600 | $1,830 |
| No | 205962640 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU48BS3 | P0V0C000M50SB+RP | 36,600 | $1,830 |
| No | 207590446 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU48BS3 | P0V0C000M50SB+RP | 36,600 | $1,830 |
| No | 207590461 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC007DS3 | P0V0C000M50SB+RP | 36,600 | $1,830 |
| No | 10511050 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU48BS3 | S9V2C100U4PSB+RP | 37,600 | $1,880 |
| No | 201803270 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC007DS3 | S9V2C100U4VSA+RP | 37,600 | $1,880 |
| No | 10511073 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC007DS3 | S9V2C100U4PSB+RP | 37,600 | $1,880 |
| No | 201803255 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU48BS3 | S9V2C100U4VSA+RP | 37,600 | $1,880 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10510913 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*DU60BS3 | S9V2D120U5PSB+RP | 36,400 | $1,820 |
| No | 10510926 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCD010DS3 | S9V2D120U5PSB+RP | 36,400 | $1,820 |
| No | 10511111 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*DU60BS3 | S9V2D120U5PSB+RP | 36,400 | $1,820 |
| No | 10511131 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCD010DS3 | S9V2D120U5PSB+RP | 36,400 | $1,820 |
| No | 201800796 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*DU60BS3 | S9V2D120U5VSA+RP | 36,400 | $1,820 |
| No | 201800832 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCD010DS3 | S9V2D120U5VSA+RP | 36,400 | $1,820 |
| No | 201803311 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCD010DS3 | S9V2D120U5VSA+RP | 36,400 | $1,820 |
| No | 201803299 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*DU60BS3 | S9V2D120U5VSA+RP | 36,400 | $1,820 |
| No | 204780158 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DD60BS3 | P0V0D000M50SA+RP | 36,000 | $1,800 |
| No | 204780159 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DD60BS3+HORIZ-RT | P0V0D000M50SA+RP | 36,000 | $1,800 |
| No | 205962646 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DD60BS3 | P0V0D000M50SB+RP | 36,000 | $1,800 |
| No | 207590344 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD60BS3 | P0V0D000M50SA+RP | 36,000 | $1,800 |
| No | 205962648 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DD60BS3+HORIZ-RT | P0V0D000M50SB+RP | 36,000 | $1,800 |
| No | 207590345 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD60BS3+HORIZ-RT | P0V0D000M50SA+RP | 36,000 | $1,800 |
| No | 207590452 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD60BS3 | P0V0D000M50SB+RP | 36,000 | $1,800 |
| No | 207590454 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DD60BS3+HORIZ-RT | P0V0D000M50SB+RP | 36,000 | $1,800 |
| No | 10511047 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CD60BS3 | S9V2C100D5PSB+RP | 37,200 | $1,860 |
| No | 207590349 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | P0V0C000M50SA+RP | 35,200 | $1,760 |
| No | 204780163 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DU60BS3 | P0V0C000M50SA+RP | 35,200 | $1,760 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10511101 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*CU60BS3 | S9V2C100U5PSB+RP | 36,600 | $1,830 |
| No | 10511081 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCD008DS3 | S9V2D120D5PSB+RP | 35,600 | $1,780 |
| No | 204780156 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU60BS3 | P0V0C000M50SA+RP | 35,800 | $1,790 |
| No | 10511125 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCC009DS3 | S9V2C100U5PSB+RP | 36,600 | $1,830 |
| No | 207590342 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU60BS3 | P0V0C000M50SA+RP | 35,800 | $1,790 |
| No | 204780168 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC009DS3 | P0V0C000M50SA+RP | 35,800 | $1,790 |
| No | 207590354 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC009DS3 | P0V0C000M50SA+RP | 35,800 | $1,790 |
| No | 207599978 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | S9V2C100D4PSB+RP | 35,800 | $1,790 |
| No | 10511082 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCD008DS3 | S9V2C100D4PSB+RP | 35,800 | $1,790 |
| No | 201803279 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCD008DS3 | S9V2C100D4VSA+RP | 35,800 | $1,790 |
| No | 207590207 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | S9V2C100D4VSA+RP | 35,800 | $1,790 |
| No | 204780112 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCD010DS3 | P0V0D000M50SA+RP | 35,600 | $1,780 |
| No | 204780104 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*DU60BS3 | P0V0D000M50SA+RP | 35,600 | $1,780 |
| No | 204780188 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*DU60BS3 | P0V0D000M50SA+RP | 35,600 | $1,780 |
| No | 205962596 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*DU60BS3 | P0V0D000M50SB+RP | 35,600 | $1,780 |
| No | 205962604 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCD010DS3 | P0V0D000M50SB+RP | 35,600 | $1,780 |
| No | 204780197 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCD010DS3 | P0V0D000M50SA+RP | 35,600 | $1,780 |
| No | 205962681 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCD010DS3 | P0V0D000M50SB+RP | 35,600 | $1,780 |
| No | 205962673 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*DU60BS3 | P0V0D000M50SB+RP | 35,600 | $1,780 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207590306 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DU60BS3 | P0V0D000M50SA+RP | 35,600 | $1,780 |
| No | 207590411 | AMERICAN STANDARD | 4A6V0X48A1 | 4PX*DU60BS3 | P0V0D000M50SB+RP | 35,600 | $1,780 |
| No | 207590314 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCD010DS3 | P0V0D000M50SA+RP | 35,600 | $1,780 |
| No | 207590419 | AMERICAN STANDARD | 4A6V0X48A1 | 4TXCD010DS3 | P0V0D000M50SB+RP | 35,600 | $1,780 |
| No | 207590059 | AMERICAN STANDARD | 4A6V0X48A1 | TEM8A0C60V51+TDR | | 36,200 | $1,810 |
| No | 10511071 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC007DS3 | S9V2D120D5PSB+RP | 35,800 | $1,790 |
| No | 10153445 | AMERICAN STANDARD | 4A6V0048A1 | TEM8A0C60V51+TDR | | 36,200 | $1,810 |
| No | 10153469 | AMERICAN STANDARD | 4A6V8049A1 | TEM8A0C60V51+TDR | | 36,200 | $1,810 |
| No | 202366097 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU60BS3 | *DD2C100ACV5 | 35,800 | $1,790 |
| No | 207590237 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU60BS3 | *DD2C100ACV5 | 35,800 | $1,790 |
| No | 10511076 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC007DS3 | S9V2C100D5PSB+RP | 35,800 | $1,790 |
| No | 10510911 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*CU60BS3 | S9V2C100U4PSB+RP | 36,600 | $1,830 |
| No | 10510923 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCC009DS3 | S9V2C100U4PSB+RP | 36,600 | $1,830 |
| No | 206918589 | AMERICAN STANDARD | 4A6V0048A1 | TEM6A0D48H41+TDR+RP | | 35,200 | $1,760 |
| No | 207590597 | AMERICAN STANDARD | 4A6V0X48A1 | TEM6A0D48H41+TDR+RP | | 35,200 | $1,760 |
| No | 206918600 | AMERICAN STANDARD | 4A6V8049A1 | TEM6A0D48H41+TDR+RP | | 35,200 | $1,760 |
| No | 205962657 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCD008DS3 | P0V0D000M50SB+RP | 36,600 | $1,830 |
| No | 204780170 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCD008DS3 | P0V0D000M50SA+RP | 36,600 | $1,830 |
| No | 205962651 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DU48BS3 | P0V0D000M50SB+RP | 36,600 | $1,830 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10511049 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU48BS3 | S9V2C100U5PSB+RP | 37,800 | $1,890 |
| No | 10511070 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC007DS3 | S9V2C100U5PSB+RP | 37,800 | $1,890 |
| No | 207590463 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | P0V0D000M50SB+RP | 36,600 | $1,830 |
| No | 207590356 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD008DS3 | P0V0D000M50SA+RP | 36,600 | $1,830 |
| No | 207590457 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3 | P0V0D000M50SB+RP | 36,600 | $1,830 |
| No | 10511064 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DU60BS3 | S9V2C100U5PSB+RP | 36,600 | $1,830 |
| No | 10511087 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCD010DS3 | S9V2C100U5PSB+RP | 36,600 | $1,830 |
| No | 10511061 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DD60BS3 | S9V2D120D5PSB+RP | 37,000 | $1,850 |
| No | 10511072 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC007DS3 | S9V2C080U5PSB+RP | 37,800 | $1,890 |
| No | 10511051 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU48BS3 | S9V2D120U5PSB+RP | 37,800 | $1,890 |
| No | 201803257 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU48BS3 | S9V2D120U5VSA+RP | 37,800 | $1,890 |
| No | 10511052 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU48BS3 | S9V2C080U5PSB+RP | 37,800 | $1,890 |
| No | 10511074 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC007DS3 | S9V2D120U5PSB+RP | 37,800 | $1,890 |
| No | 201803273 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC007DS3 | S9V2D120U5VSA+RP | 37,800 | $1,890 |
| No | 207590196 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU48BS3 | S9V2D120U5VSA+RP | 37,800 | $1,890 |
| No | 207590204 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC007DS3 | S9V2D120U5VSA+RP | 37,800 | $1,890 |
| No | 10093464 | AMERICAN STANDARD | 4A6V8048A1 | TAM9A0C60V51 | | 36,200 | $1,810 |
| No | 10153447 | AMERICAN STANDARD | 4A6V0048A1 | TEM8A0D60V51+TDR | | 35,800 | $1,790 |
| No | 10153471 | AMERICAN STANDARD | 4A6V8049A1 | TEM8A0D60V51+TDR | | 35,800 | $1,790 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207590351 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCB006DS3 | P0V0B000M40SA+RP | 37,000 | $1,850 |
| No | 204780165 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCB006DS3 | P0V0B000M40SA+RP | 37,000 | $1,850 |
| No | 206918598 | AMERICAN STANDARD | 4A6V8048A1 | TEM6A0D60H51+TDR+RP | | 35,400 | $1,770 |
| No | 207590604 | AMERICAN STANDARD | 4A6V8X48A1 | TEM6A0D60H51+TDR+RP | | 35,400 | $1,770 |
| No | 205962652 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DU60BS3 | P0V0D000M50SB+RP | 36,000 | $1,800 |
| No | 207590458 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | P0V0D000M50SB+RP | 36,000 | $1,800 |
| No | 205962660 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCD010DS3 | P0V0D000M50SB+RP | 36,000 | $1,800 |
| No | 207590466 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3 | P0V0D000M50SB+RP | 36,000 | $1,800 |
| No | 201803277 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC009DS3 | S9V2C100U4VSA+RP | 37,400 | $1,870 |
| No | 10511077 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC009DS3 | S9V2C100U4PSB+RP | 37,400 | $1,870 |
| No | 10511055 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU60BS3 | S9V2C100U4PSB+RP | 37,400 | $1,870 |
| No | 201803259 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU60BS3 | S9V2C100U4VSA+RP | 37,400 | $1,870 |
| No | 10153468 | AMERICAN STANDARD | 4A6V8049A1 | TEM8A0C48V41+TDR | | 35,600 | $1,780 |
| No | 10511054 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU60BS3 | S9V2C080U5PSB+RP | 37,200 | $1,860 |
| No | 10153444 | AMERICAN STANDARD | 4A6V0048A1 | TEM8A0C48V41+TDR | | 35,600 | $1,780 |
| No | 10511078 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC009DS3 | S9V2C080U5PSB+RP | 37,200 | $1,860 |
| No | 10153464 | AMERICAN STANDARD | 4A6V8048A1 | TEM8A0C60V51+TDR | | 36,800 | $1,840 |
| No | 207590073 | AMERICAN STANDARD | 4A6V8X48A1 | TEM8A0C60V51+TDR | | 36,800 | $1,840 |
| No | 201803269 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DU60BS3 | S9V2C100U4VSA+RP | 37,200 | $1,860 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10511065 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DU60BS3 | S9V2C100U4PSB+RP | 37,200 | $1,860 |
| No | 10511085 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCD010DS3 | S9V2C100U4PSB+RP | 37,200 | $1,860 |
| No | 201803283 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCD010DS3 | S9V2C100U4VSA+RP | 37,200 | $1,860 |
| No | 10511053 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU60BS3 | S9V2D120U5PSB+RP | 37,200 | $1,860 |
| No | 10153446 | AMERICAN STANDARD | 4A6V0048A1 | TEM8A0D48V41+TDR | | 36,200 | $1,810 |
| No | 10153470 | AMERICAN STANDARD | 4A6V8049A1 | TEM8A0D48V41+TDR | | 36,200 | $1,810 |
| No | 10511079 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC009DS3 | S9V2D120U5PSB+RP | 37,200 | $1,860 |
| No | 201803275 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC009DS3 | S9V2D120U5VSA+RP | 37,200 | $1,860 |
| No | 201803261 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU60BS3 | S9V2D120U5VSA+RP | 37,200 | $1,860 |
| No | 207590198 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU60BS3 | S9V2D120U5VSA+RP | 37,200 | $1,860 |
| No | 207590205 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC009DS3 | S9V2D120U5VSA+RP | 37,200 | $1,860 |
| No | 204780164 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DU60BS3 | P0V0D000M50SA+RP | 36,200 | $1,810 |
| No | 204780171 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCD010DS3 | P0V0D000M50SA+RP | 36,200 | $1,810 |
| No | 207590603 | AMERICAN STANDARD | 4A6V8X48A1 | TEM6A0D48H41+TDR+RP | | 35,800 | $1,790 |
| No | 207590350 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU60BS3 | P0V0D000M50SA+RP | 36,200 | $1,810 |
| No | 207590357 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCD010DS3 | P0V0D000M50SA+RP | 36,200 | $1,810 |
| No | 206918597 | AMERICAN STANDARD | 4A6V8048A1 | TEM6A0D48H41+TDR+RP | | 35,800 | $1,790 |
| No | 10511056 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU60BS3 | S9V2C100U5PSB+RP | 37,400 | $1,870 |
| No | 10511080 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC009DS3 | S9V2C100U5PSB+RP | 37,400 | $1,870 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10511066 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DU60BS3 | S9V2C080U5PSB+RP | 37,200 | $1,860 |
| No | 10511086 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCD010DS3 | S9V2D120U5PSB+RP | 37,200 | $1,860 |
| No | 10511084 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCD010DS3 | S9V2C080U5PSB+RP | 37,200 | $1,860 |
| No | 201803267 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DU60BS3 | S9V2D120U5VSA+RP | 37,200 | $1,860 |
| No | 201803281 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCD010DS3 | S9V2D120U5VSA+RP | 37,200 | $1,860 |
| No | 10153466 | AMERICAN STANDARD | 4A6V8048A1 | TEM8A0D60V51+TDR | | 36,400 | $1,820 |
| No | 204780155 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*CU48BS3 | P0V0C000M50SA+RP | 36,800 | $1,840 |
| No | 204780167 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC007DS3 | P0V0C000M50SA+RP | 36,800 | $1,840 |
| No | 207590341 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*CU48BS3 | P0V0C000M50SA+RP | 36,800 | $1,840 |
| No | 207590353 | AMERICAN STANDARD | 4A6V8X48A1 | 4TXCC007DS3 | P0V0C000M50SA+RP | 36,800 | $1,840 |
| No | 204780162 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DU48BS3 | P0V0D000M50SA+RP | 36,600 | $1,830 |
| No | 10153465 | AMERICAN STANDARD | 4A6V8048A1 | TEM8A0D48V41+TDR | | 36,600 | $1,830 |
| No | 207590348 | AMERICAN STANDARD | 4A6V8X48A1 | 4PX*DU48BS3 | P0V0D000M50SA+RP | 36,600 | $1,830 |
| No | 10511063 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*DU60BS3 | S9V2D120U5PSB+RP | 37,200 | $1,860 |
| No | 201922564 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD48BS3 | *DHMC100ACV4 | 32,400 | $1,620 |
| No | 201922834 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | *DHMC100ACV4 | 36,200 | $1,810 |
| No | 201922760 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3 | *DHMC100ACV4 | 37,400 | $1,870 |
| No | 201922568 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD48BS3 | *DD2C100ACV5 | 32,000 | $1,600 |
| No | 201922798 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC007DS3 | *DHMC100ACV4 | 37,800 | $1,890 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922830 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | *DD2C100ACV5 | 36,600 | $1,830 |
| No | 201922573 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD48BS3+HORIZ-RT | *UD2C100ACV5 | 32,000 | $1,600 |
| No | 201922802 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC009DS3 | *DHMC100ACV4 | 37,200 | $1,860 |
| No | 201922571 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD48BS3+HORIZ-RT | *UD2C080ACV4 | 32,000 | $1,600 |
| No | 201922739 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CD60BS3 | *DHMC100ACV4 | 38,500 | $1,925 |
| No | 201922815 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3 | *DD2C100ACV5 | 35,800 | $1,790 |
| No | 206197341 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD48BS3 | S9V2B080D4PSB+RP | 31,400 | $1,570 |
| No | 201922503 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD48BS3 | *DHMC100ACV4 | 33,800 | $1,690 |
| No | 201922570 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD48BS3+HORIZ-RT | S9V2C080U5PSB+RP | 31,800 | $1,590 |
| No | 201922563 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD48BS3 | S9V2C100D4PSB+RP | 32,000 | $1,600 |
| No | 201922581 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD48BS3+HORIZ-RT | S9V2C100U4PSB+RP | 32,000 | $1,600 |
| No | 201922561 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD48BS3 | S9V2C100D5PSB+RP | 31,800 | $1,590 |
| No | 201922580 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD48BS3+HORIZ-RT | S9V2C100U5PSB+RP | 31,800 | $1,590 |
| No | 201922497 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*BD48BS3 | S9V2B080D4PSB+RP | 33,200 | $1,660 |
| No | 201922498 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*BD48BS3+HORIZ-RT | S9V2B080U4PSB+RP | 33,200 | $1,660 |
| No | 204780014 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*BD42BS3 | P0V0B000M40SA+RP | 31,000 | $1,550 |
| No | 201922837 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3+HORIZ-LT | *DD2C100ACV5 | 37,600 | $1,880 |
| No | 201922499 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*BD48BS3+HORIZ-RT | S9V2B060U4PSB+RP | 33,200 | $1,660 |
| No | 201922603 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3+HORIZ-RT | S9V2C100U4PSB+RP | 30,600 | $1,530 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922762 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3 | *DHMD120BCV5 | 38,500 | $1,925 |
| No | 201922562 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD48BS3 | *DHMD120BCV5 | 33,000 | $1,650 |
| No | 201922530 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU36BS3 | *UD2C080ACV4 | 31,600 | $1,580 |
| No | 204836728 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU48BS3 | P0V0C000M50SA+RP | 34,800 | $1,740 |
| No | 201922799 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC007DS3 | *DD2C100ACV5 | 37,200 | $1,860 |
| No | 201922771 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3+HORIZ-RT | *UD2C100ACV5 | 37,400 | $1,870 |
| No | 201922764 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3+HORIZ-RT | *UD2D140ACV5 | 39,000 | $1,950 |
| No | 201922509 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD48BS3+HORIZ-RT | *UD2C100ACV5 | 33,000 | $1,650 |
| No | 201922604 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3+HORIZ-RT | S9V2C080U5PSB+RP | 30,600 | $1,530 |
| No | 201922770 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3+HORIZ-RT | *UD2C080ACV4 | 37,200 | $1,860 |
| No | 201922502 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD48BS3 | S9V2C100D4PSB+RP | 33,000 | $1,650 |
| No | 201922602 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3+HORIZ-RT | S9V2C100U5PSB+RP | 30,600 | $1,530 |
| No | 201922529 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU36BS3 | *UHMC100ACV4 | 31,800 | $1,590 |
| No | 201922816 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3 | *DD2D120ACV5 | 36,600 | $1,830 |
| No | 201922512 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD48BS3+HORIZ-RT | S9V2C100U4PSB+RP | 33,000 | $1,650 |
| No | 201922528 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU36BS3 | *UD2C100ACV5 | 32,000 | $1,600 |
| No | 201922582 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD48BS3+HORIZ-RT | *UD2D140ACV5 | 33,200 | $1,660 |
| No | 201922511 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD48BS3+HORIZ-RT | *UD2C080ACV4 | 33,200 | $1,660 |
| No | 201922504 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD48BS3 | *DD2C100ACV5 | 33,200 | $1,660 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922786 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3 | *UD2D140ACV5 | 39,000 | $1,950 |
| No | 201922824 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | *UD2D140ACV5 | 39,000 | $1,950 |
| No | 201922576 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD48BS3+HORIZ-RT | *UD2D120ACV5 | 33,000 | $1,650 |
| No | 204780015 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*BD48BS3 | P0V0B000M40SA+RP | 32,600 | $1,630 |
| No | 204780016 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*BD48BS3+HORIZ-RT | P0V0B000M40SA+RP | 32,600 | $1,630 |
| No | 201922763 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3 | *DD2C100ACV5 | 37,000 | $1,850 |
| No | 201922565 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD48BS3 | *DD2D120ACV5 | 33,000 | $1,650 |
| No | 204780027 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD48BS3 | P0V0C000M50SA+RP | 31,000 | $1,550 |
| No | 201922567 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD48BS3 | S9V2D120D5PSB+RP | 32,800 | $1,640 |
| No | 204780030 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD48BS3+HORIZ-RT | P0V0C000M50SA+RP | 31,000 | $1,550 |
| No | 205962520 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD48BS3 | P0V0C000M50SB+RP | 31,000 | $1,550 |
| No | 205962522 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD48BS3+HORIZ-RT | P0V0C000M50SB+RP | 31,000 | $1,550 |
| No | 201922579 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD48BS3+HORIZ-RT | S9V2D120U5PSB+RP | 32,800 | $1,640 |
| No | 201922731 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3+HORIZ-LT | *DD2C100ACV5 | 31,000 | $1,550 |
| No | 201922767 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3+HORIZ-RT | *UD2D120ACV5 | 39,000 | $1,950 |
| No | 201922741 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CD60BS3 | *DD2C100ACV5 | 38,000 | $1,900 |
| No | 201922507 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD48BS3+HORIZ-RT | S9V2C080U5PSB+RP | 33,000 | $1,650 |
| No | 206325972 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU48BS3 | S9V2B080U4PSA+RP | 30,800 | $1,540 |
| No | 201922746 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CD60BS3+HORIZ-RT | *UD2C100ACV5 | 38,500 | $1,925 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204780019 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD42BS3 | P0V0C000M50SA+RP | 30,800 | $1,540 |
| No | 205962512 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD42BS3 | P0V0C000M50SB+RP | 30,800 | $1,540 |
| No | 205962543 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3 | P0V0C000M50SB+RP | 35,800 | $1,790 |
| No | 201922820 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3 | *DHMD120BCV5 | 37,000 | $1,850 |
| No | 201922747 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CD60BS3+HORIZ-RT | S9V2C080U5PSB+RP | 38,000 | $1,900 |
| No | 201922505 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD48BS3 | S9V2C100D5PSB+RP | 33,000 | $1,650 |
| No | 201922513 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD48BS3+HORIZ-RT | S9V2C100U5PSB+RP | 33,000 | $1,650 |
| No | 201922772 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3+HORIZ-RT | S9V2C080U5PSB+RP | 36,600 | $1,830 |
| No | 201922773 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3+HORIZ-RT | S9V2C100U5PSB+RP | 36,800 | $1,840 |
| No | 201922825 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | *UHMC100ACV4 | 37,000 | $1,850 |
| No | 201922803 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC009DS3 | *DD2C100ACV5 | 36,400 | $1,820 |
| No | 201922788 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3 | *UD2C080ACV4 | 37,200 | $1,860 |
| No | 201922787 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3 | *UHMC100ACV4 | 37,000 | $1,850 |
| No | 201922821 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | *UD2C080ACV4 | 37,200 | $1,860 |
| No | 204780017 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*BU42BS3 | P0V0B000M40SA+RP | 30,000 | $1,500 |
| No | 201922748 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CD60BS3+HORIZ-RT | *UD2C080ACV4 | 38,500 | $1,925 |
| No | 201922524 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD60BS3+HORIZ-RT | S9V2C100U4PSB+RP | 32,000 | $1,600 |
| No | 201922520 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD60BS3+HORIZ-RT | S9V2C080U5PSB+RP | 31,800 | $1,590 |
| No | 205962527 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3+HORIZ-RT | P0V0C000M50SB+RP | 29,800 | $1,490 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205962525 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3 | P0V0C000M50SB+RP | 29,800 | $1,490 |
| No | 204836717 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU48BS3 | P0V0C000M50SA+RP | 36,000 | $1,800 |
| No | 201922521 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD60BS3+HORIZ-RT | S9V2C100U5PSB+RP | 31,800 | $1,590 |
| No | 206918581 | AMERICAN STANDARD | 4A6L9048A1 | TEM6A0C42H41+TDR+RP | | 30,400 | $1,520 |
| No | 204836721 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3 | P0V0C000M50SA+RP | 36,000 | $1,800 |
| No | 201922833 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | *DHMD120BCV5 | 36,400 | $1,820 |
| No | 201922601 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3+HORIZ-RT | S9V2D120U5PSB+RP | 31,600 | $1,580 |
| No | 201922761 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3 | *DD2D120ACV5 | 38,000 | $1,900 |
| No | 205962545 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3+HORIZ-RT | P0V0C000M50SB+RP | 35,600 | $1,780 |
| No | 201922800 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC009DS3 | S9V2C100D5PSB+RP | 36,800 | $1,840 |
| No | 204836725 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3+HORIZ-RT | P0V0C000M50SA+RP | 35,600 | $1,780 |
| No | 204780036 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | P0V0C000M50SA+RP | 30,200 | $1,510 |
| No | 204780043 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | P0V0C000M50SA+RP | 30,200 | $1,510 |
| No | 205962535 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | P0V0C000M50SB+RP | 30,200 | $1,510 |
| No | 205962528 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | P0V0C000M50SB+RP | 30,200 | $1,510 |
| No | 205962513 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD48BS3 | P0V0C000M50SB+RP | 32,000 | $1,600 |
| No | 205962546 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3 | P0V0C000M50SB+RP | 35,800 | $1,790 |
| No | 201922832 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | *DD2D120ACV5 | 36,600 | $1,830 |
| No | 205962514 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD48BS3+HORIZ-RT | P0V0C000M50SB+RP | 32,000 | $1,600 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205962553 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | P0V0C000M50SB+RP | 35,800 | $1,790 |
| No | 204780040 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC005DS3 | P0V0C000M50SA+RP | 30,800 | $1,540 |
| No | 201922745 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CD60BS3+HORIZ-RT | S9V2C100U5PSB+RP | 38,000 | $1,900 |
| No | 205962532 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC005DS3 | P0V0C000M50SB+RP | 30,800 | $1,540 |
| No | 201922780 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU48BS3 | *UHMC100ACV4 | 37,400 | $1,870 |
| No | 201922812 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3 | *UHMC100ACV4 | 37,400 | $1,870 |
| No | 204780031 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3 | P0V0C000M50SA+RP | 30,000 | $1,500 |
| No | 205962539 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CD60BS3 | P0V0C000M50SB+RP | 37,000 | $1,850 |
| No | 204780033 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3+HORIZ-RT | P0V0C000M50SA+RP | 30,000 | $1,500 |
| No | 205962540 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CD60BS3+HORIZ-RT | P0V0C000M50SB+RP | 37,000 | $1,850 |
| No | 201922776 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU48BS3 | *UD2C080ACV4 | 37,200 | $1,860 |
| No | 201922817 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3 | *UD2C080ACV4 | 37,200 | $1,860 |
| No | 204780039 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCB006DS3 | P0V0B000M40SA+RP | 31,400 | $1,570 |
| No | 204836730 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU48BS3 | P0V0D000M50SA+RP | 36,000 | $1,800 |
| No | 201922755 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU60BS3 | *UHMC100ACV4 | 38,000 | $1,900 |
| No | 201922808 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC009DS3 | *UHMC100ACV4 | 38,000 | $1,900 |
| No | 205962521 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD48BS3 | P0V0D000M50SB+RP | 31,800 | $1,590 |
| No | 205962523 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD48BS3+HORIZ-RT | P0V0D000M50SB+RP | 31,800 | $1,590 |
| No | 201922779 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU48BS3 | *UD2D140ACV5 | 39,000 | $1,950 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204780018 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*BU48BS3 | P0V0B000M40SA+RP | 32,000 | $1,600 |
| No | 201922811 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3 | *UD2D140ACV5 | 39,000 | $1,950 |
| No | 204836734 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3 | P0V0C000M50SA+RP | 36,000 | $1,800 |
| No | 204836744 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | P0V0C000M50SA+RP | 36,000 | $1,800 |
| No | 204780021 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD48BS3+HORIZ-RT | P0V0C000M50SA+RP | 32,200 | $1,610 |
| No | 204780020 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD48BS3 | P0V0C000M50SA+RP | 32,200 | $1,610 |
| No | 204836715 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CD60BS3+HORIZ-RT | P0V0C000M50SA+RP | 37,200 | $1,860 |
| No | 201923082 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC009DS3 | *UD2C080ACV4 | 38,500 | $1,925 |
| No | 204836713 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CD60BS3 | P0V0C000M50SA+RP | 37,200 | $1,860 |
| No | 201923081 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU60BS3 | *UD2C080ACV4 | 38,500 | $1,925 |
| No | 201922783 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU48BS3 | S9V2C100U5PSB+RP | 37,000 | $1,850 |
| No | 204780029 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD48BS3+HORIZ-RT | P0V0D000M50SA+RP | 32,000 | $1,600 |
| No | 204780028 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD48BS3 | P0V0D000M50SA+RP | 32,000 | $1,600 |
| No | 205962530 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | P0V0C000M50SB+RP | 30,000 | $1,500 |
| No | 205962537 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | P0V0C000M50SB+RP | 30,000 | $1,500 |
| No | 205962551 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3 | P0V0C000M50SB+RP | 36,200 | $1,810 |
| No | 201922752 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU48BS3 | *UHMC100ACV4 | 38,500 | $1,925 |
| No | 201922733 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3+HORIZ-LT | *DD2D120ACV5 | 32,000 | $1,600 |
| No | 201922794 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC007DS3 | *UHMC100ACV4 | 38,500 | $1,925 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922775 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU48BS3 | S9V2C080U5PSB+RP | 37,000 | $1,850 |
| No | 204780022 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD60BS3 | P0V0C000M50SA+RP | 31,000 | $1,550 |
| No | 204780023 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD60BS3+HORIZ-RT | P0V0C000M50SA+RP | 31,000 | $1,550 |
| No | 205962515 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD60BS3 | P0V0C000M50SB+RP | 31,000 | $1,550 |
| No | 205962516 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CD60BS3+HORIZ-RT | P0V0C000M50SB+RP | 31,000 | $1,550 |
| No | 201922769 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3+HORIZ-RT | S9V2D120U5PSB+RP | 37,600 | $1,880 |
| No | 201922846 | AMERICAN STANDARD | 4A6L9060A1 | TEM8A0C60V51+TDR | | 38,500 | $1,925 |
| No | 201922777 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU48BS3 | *UD2C100ACV5 | 37,200 | $1,860 |
| No | 201922809 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3 | *UD2C100ACV5 | 37,200 | $1,860 |
| No | 205962517 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU42BS3 | P0V0C000M50SB+RP | 31,600 | $1,580 |
| No | 205962524 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3 | P0V0D000M50SB+RP | 30,600 | $1,530 |
| No | 205962526 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3+HORIZ-RT | P0V0D000M50SB+RP | 30,600 | $1,530 |
| No | 204836740 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3 | P0V0C000M50SA+RP | 36,400 | $1,820 |
| No | 205962549 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC009DS3 | P0V0C000M50SB+RP | 37,000 | $1,850 |
| No | 205962541 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU60BS3 | P0V0C000M50SB+RP | 37,000 | $1,850 |
| No | 201922781 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU48BS3 | *UHMD120ACV5 | 39,000 | $1,950 |
| No | 201922753 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU48BS3 | *UD2C080ACV4 | 38,500 | $1,925 |
| No | 204780046 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | P0V0C000M50SA+RP | 30,200 | $1,510 |
| No | 204780037 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | P0V0C000M50SA+RP | 30,200 | $1,510 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922796 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC007DS3 | *UD2C080ACV4 | 38,500 | $1,925 |
| No | 206918584 | AMERICAN STANDARD | 4A6L9060A1 | TEM6A0D48H41+TDR+RP | | 36,800 | $1,840 |
| No | 204780034 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3+HORIZ-RT | P0V0D000M50SA+RP | 30,800 | $1,540 |
| No | 204780032 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3 | P0V0D000M50SA+RP | 30,800 | $1,540 |
| No | 205962533 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC007DS3 | P0V0C000M50SB+RP | 31,400 | $1,570 |
| No | 205962518 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU48BS3 | P0V0C000M50SB+RP | 31,400 | $1,570 |
| No | 204780024 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU42BS3 | P0V0C000M50SA+RP | 31,800 | $1,590 |
| No | 204836723 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3 | P0V0D000M50SA+RP | 36,600 | $1,830 |
| No | 204836727 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3+HORIZ-RT | P0V0D000M50SA+RP | 36,600 | $1,830 |
| No | 205962542 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3 | P0V0D000M50SB+RP | 36,600 | $1,830 |
| No | 205962544 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3+HORIZ-RT | P0V0D000M50SB+RP | 36,600 | $1,830 |
| No | 204836739 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC009DS3 | P0V0C000M50SA+RP | 37,200 | $1,860 |
| No | 204836719 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU60BS3 | P0V0C000M50SA+RP | 37,200 | $1,860 |
| No | 204836732 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3 | P0V0D000M50SA+RP | 37,000 | $1,850 |
| No | 204836746 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | P0V0D000M50SA+RP | 37,000 | $1,850 |
| No | 205962547 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3 | P0V0D000M50SB+RP | 37,000 | $1,850 |
| No | 205962552 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | P0V0D000M50SB+RP | 37,000 | $1,850 |
| No | 206918583 | AMERICAN STANDARD | 4A6L9048A1 | TEM6A0D60H51+TDR+RP | | 30,200 | $1,510 |
| No | 204836736 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC007DS3 | P0V0C000M50SA+RP | 37,400 | $1,870 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205962548 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC007DS3 | P0V0C000M50SB+RP | 37,400 | $1,870 |
| No | 204780025 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU48BS3 | P0V0C000M50SA+RP | 31,600 | $1,580 |
| No | 204780041 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC007DS3 | P0V0C000M50SA+RP | 31,600 | $1,580 |
| No | 204780042 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC009DS3 | P0V0C000M50SA+RP | 31,000 | $1,550 |
| No | 205962534 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC009DS3 | P0V0C000M50SB+RP | 31,000 | $1,550 |
| No | 204780026 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU60BS3 | P0V0C000M50SA+RP | 31,000 | $1,550 |
| No | 201922835 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3+HORIZ-LT | *DD2D120ACV5 | 37,400 | $1,870 |
| No | 205962519 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU60BS3 | P0V0C000M50SB+RP | 31,000 | $1,550 |
| No | 201922810 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3 | *UD2D120ACV5 | 38,500 | $1,925 |
| No | 201922778 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU48BS3 | *UD2D120ACV5 | 38,500 | $1,925 |
| No | 201922795 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCC007DS3 | *UD2C100ACV5 | 38,500 | $1,925 |
| No | 204780044 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | P0V0D000M50SA+RP | 31,400 | $1,570 |
| No | 201922749 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU48BS3 | *UD2C100ACV5 | 38,500 | $1,925 |
| No | 205962529 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | P0V0D000M50SB+RP | 31,400 | $1,570 |
| No | 204780035 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | P0V0D000M50SA+RP | 31,400 | $1,570 |
| No | 205962536 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | P0V0D000M50SB+RP | 31,400 | $1,570 |
| No | 201922782 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU48BS3 | S9V2D120U5PSB+RP | 38,000 | $1,900 |
| No | 206918582 | AMERICAN STANDARD | 4A6L9048A1 | TEM6A0D48H41+TDR+RP | | 30,600 | $1,530 |
| No | 204780045 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | P0V0D000M50SA+RP | 31,000 | $1,550 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205962538 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | P0V0D000M50SB+RP | 31,000 | $1,550 |
| No | 205962531 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | P0V0D000M50SB+RP | 31,000 | $1,550 |
| No | 204780038 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU60BS3 | P0V0D000M50SA+RP | 31,000 | $1,550 |
| No | 204836742 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3 | P0V0D000M50SA+RP | 37,200 | $1,860 |
| No | 205962550 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3 | P0V0D000M50SB+RP | 37,200 | $1,860 |
| No | 201922737 | AMERICAN STANDARD | 4A6L9048A1 | TEM8A0C60V51+TDR | | 31,400 | $1,570 |
| No | 8761198 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC009DS3 | *UD2D120ACV5 | 36,600 | $1,830 |
| No | 10510921 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCC007DS3 | S9V2C100U4PSB+RP | 37,000 | $1,850 |
| No | 10511117 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCC007DS3 | S9V2C100U4PSB+RP | 37,000 | $1,850 |
| No | 201800811 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCC007DS3 | S9V2C100U4VSA+RP | 37,000 | $1,850 |
| No | 20180327 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC007DS3 | S9V2C100U4VSA+RP | 37,600 | $1,880 |
| No | 201803301 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCC007DS3 | S9V2C100U4VSA+RP | 37,000 | $1,850 |
| No | 20192266 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCC007DS3 | *UHMC100ACV4 | 32,400 | $1,620 |
| No | 20192268 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD008DS3 | *UD2D140ACV5 | 32,400 | $1,620 |
| No | 20192271 | AMERICAN STANDARD | 4A6L9048A1 | 4TXCD010DS3 | *DD2D120ACV5 | 31,200 | $1,560 |
| No | 20192281 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3 | *UD2D120ACV5 | 38,500 | $1,925 |
| No | 20192282 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD008DS3 | *DHMD120BCV5 | 37,000 | $1,850 |
| No | 20192283 | AMERICAN STANDARD | 4A6L9060A1 | 4TXCD010DS3 | *DD2C100ACV5 | 36,600 | $1,830 |
| No | 8761138 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCC009DS3 | *UD2C080ACV4 | 35,800 | $1,790 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 8761142 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCD010DS3 | *UHMD120ACV5 | 36,400 | $1,820 |
| No | 8761143 | AMERICAN STANDARD | 4A6V0048A1 | 4TXCD010DS3 | *UHMC100ACV4 | 35,800 | $1,790 |
| No | 8761193 | AMERICAN STANDARD | 4A6V8048A1 | 4TXCC007DS3 | *UD2D120ACV5 | 37,600 | $1,880 |
| No | 8761214 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCC009DS3 | *UD2C080ACV4 | 35,800 | $1,790 |
| No | 8761221 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCD010DS3 | *UHMC100ACV4 | 35,800 | $1,790 |
| No | 8761222 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCD010DS3 | *UHMD120ACV5 | 36,400 | $1,820 |
| No | 10511096 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*CU48BS3 | S9V2C100U4PSB+RP | 37,000 | $1,850 |
| No | 201800747 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*CU48BS3 | S9V2C100U4VSA+RP | 37,000 | $1,850 |
| No | 201803287 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*CU48BS3 | S9V2C100U4VSA+RP | 37,000 | $1,850 |
| No | 20192253 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU36BS3 | *UD2C080ACV4 | 31,600 | $1,580 |
| No | 20192254 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*CU42BS3 | *UHMC100ACV4 | 32,600 | $1,630 |
| No | 20192259 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DD60BS3 | *DHMD120BCV5 | 31,800 | $1,590 |
| No | 20192261 | AMERICAN STANDARD | 4A6L9048A1 | 4PX*DU48BS3 | *UD2D140ACV5 | 32,400 | $1,620 |
| No | 20192274 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CD60BS3 | S9V2C100D5PSB+RP | 38,000 | $1,900 |
| No | 20192275 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*CU48BS3 | S9V2C100U5PSB+RP | 38,500 | $1,925 |
| No | 20192276 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3 | *DHMC100ACV4 | 37,400 | $1,870 |
| No | 20192277 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DD60BS3+HORIZ-RT | *UD2C080ACV4 | 37,200 | $1,860 |
| No | 20192278 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU48BS3 | *UHMC100ACV4 | 37,400 | $1,870 |
| No | 20192279 | AMERICAN STANDARD | 4A6L9060A1 | 4PX*DU60BS3 | S9V2C100U5PSB+RP | 36,800 | $1,840 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 20249227 | AMERICAN STANDARD | 4A6V8048A1 | 4PX*BU48BS3 | S9V2B080D4PSB+RP | 36,800 | $1,840 |
| No | 8759242 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*CU60BS3 | *UD2C080ACV4 | 35,800 | $1,790 |
| No | 8759247 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*DU60BS3 | *UHMC100ACV4 | 35,800 | $1,790 |
| No | 8759248 | AMERICAN STANDARD | 4A6V8049A1 | 4PX*DU60BS3 | *UHMD120ACV5 | 36,400 | $1,820 |
| No | 6749791 | AMERICAN STANDARD | 4A6V0048A1 | *AM8C0C48V41 | | 34,000 | $1,700 |
| No | 6750233 | AMERICAN STANDARD | 4A6V8048A1 | *AM8C0C48V41 | | 34,400 | $1,720 |
| No | 6750457 | AMERICAN STANDARD | 4A6V8049A1 | *AM8C0C48V41 | | 34,000 | $1,700 |
| No | 6796563 | AMERICAN STANDARD | 4A6V8037A1 | 4TXCC007CC3 | *UD2C100ACV5 | 25,600 | $1,280 |
| No | 7161151 | AMERICAN STANDARD | 4A6V0048A1 | *AM8C0C60V51 | | 34,200 | $1,710 |
| No | 10093451 | AMERICAN STANDARD | 4A6V0048A1 | TAM9A0C48V41 | | 34,000 | $1,700 |
| No | 20236608 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*CU48BS3 | S9V2C100D4PSB+RP | 36,000 | $1,800 |
| No | 8761217 | AMERICAN STANDARD | 4A6V8049A1 | 4TXCD010DS3 | *DD2D120ACV5 | 34,400 | $1,720 |
| No | 202703125 | AMERICAN STANDARD | 4TXK2318A10N0** | 4MXW2318A10N0** | N/A | 12,400 | $620 |
| No | 202703123 | AMERICAN STANDARD | 4TXK2312A10N0** | 4MXW2312A10N0** | N/A | 7,100 | $355 |
| No | 10510910 | AMERICAN STANDARD | 4A6V0048A1 | 4PX*CU48BS3 | S9V2C100U4PSB+RP | 37,000 | $1,850 |
| No | 207705504 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | MUZ-GS24NAHZ*** | NAXWST24B112** | | 13,300 | $665 |
| No | 207705501 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | MUZ-GS15NAHZ*** | NAXWST15B112** | | 8,700 | $435 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207705500 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | MUZ-GS12NAHZ*** | NAXWST12B112** | | 7,600 | $380 |
| No | 207705499 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | MUZ-GS09NAHZ*** | NAXWST09B112** | | 5,700 | $285 |
| No | 204795633 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0301HA70N* | APEADA0301AA70A | | 18,500 | $925 |
| No | 204795632 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0301HA70B* | APEADA0301AA70A | | 18,500 | $925 |
| No | 204795637 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0421KA70N* | APEADA0421AA70A | | 30,600 | $1,530 |
| No | 204795636 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0421KA70B* | APEADA0421AA70A | | 30,600 | $1,530 |
| No | 204795630 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0241HA70B* | APEADA0241AA70A | | 14,800 | $740 |
| No | 204795631 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0241HA70N* | APEADA0241AA70A | | 14,800 | $740 |
| No | 204795634 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0361KA70B* | APEADA0361AA70A | | 20,800 | $1,040 |
| No | 204795635 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0361KA70N* | APEADA0361AA70A | | 20,800 | $1,040 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204793332 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSKH15A112AA | APEADA0151AA70A | | 11,700 | $585 |
| No | 204793327 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSKH12A112AA | APEADA0121AA70A | | 9,000 | $450 |
| No | 207705491 | American Standard / Mitsubishi Electric | MUZ-GS24NA*** | NAXWST24B112** | | 17,600 | $880 |
| No | 207705490 | American Standard / Mitsubishi Electric | MUZ-GS18NA*** | NAXWST18B112** | | 13,300 | $665 |
| No | 207705488 | American Standard / Mitsubishi Electric | MUZ-GS15NA*** | NAXWST15B112** | | 12,100 | $605 |
| No | 207705487 | American Standard / Mitsubishi Electric | MUZ-GS12NA*** | NAXWST12B112** | | 9,000 | $450 |
| No | 207705485 | American Standard / Mitsubishi Electric | MUZ-GS09NA*** | NAXWST09B112** | | 6,500 | $325 |
| No | 209832994 | American Standard / Mitsubishi Electric | MUZ-FS15NA*** | NAXWPH15B112A* | | 10,000 | $500 |
| No | 209832989 | American Standard / Mitsubishi Electric | MUZ-FS12NA*** | NAXWPH12B112A* | | 8,400 | $420 |
| No | 209832984 | American Standard / Mitsubishi Electric | MUZ-FS09NA*** | NAXWPH09B112A* | | 5,900 | $295 |
| No | 209832979 | American Standard / Mitsubishi Electric | MUZ-FS06NA*** | NAXWPH06B112A* | | 5,900 | $295 |
| No | 209319660 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NTXMMX36A142C* | Heat pump without ducts | | 22,400 | $1,120 |
| No | 209319657 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NTXMMX30A132C* | Heat pump without ducts | | 18,600 | $930 |
| No | 209319655 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NTXMMX24A132C* | Heat pump without ducts | | 14,300 | $715 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 209424925 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NTXMMX20A122C* | Heat pump without ducts | | 13,500 | $675 |
| No | 206908466 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMPH20A122A** | Heat pump with ducts | | 13,700 | $685 |
| No | 202354889 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMMX30A132A* | Heat pump without ducts | | 16,000 | $800 |
| No | 202354891 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMMX36A142A* | Heat pump without ducts | | 22,200 | $1,110 |
| No | 206401423 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPH18A112A* | NAXWPH18B112AA | | 13,700 | $685 |
| No | 206425203 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPB15B112A* | NAXWPH15A112AA | | 11,000 | $550 |
| No | 206425190 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPH09B112A* | NAXWPH09A112AA | | 6,700 | $335 |
| No | 206425188 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPB18B112A* | NAXWPH18A112AA | | 13,700 | $685 |
| No | 206425192 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPH15B112A* | NAXWPH15A112AA | | 11,000 | $550 |
| No | 206425189 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPH06B112A* | NAXWPH06A112AA | | 5,900 | $295 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206425191 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPH12B112A* | NAXWPH12A112AA | | 8,100 | $405 |
| No | 206425201 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPB09B112A* | NAXWPH09A112AA | | 6,700 | $335 |
| No | 206425193 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPH18B112A* | NAXWPH18A112AA | | 13,700 | $685 |
| No | 206425202 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPB12B112A* | NAXWPH12A112AA | | 8,100 | $405 |
| No | 206425187 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPB06B112A* | NAXWPH06A112AA | | 5,900 | $295 |
| No | 206401418 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPH06A112A* | NAXWPH06B112AA | | 5,900 | $295 |
| No | 206401419 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPB06A112A* | NAXWPH06B112AA | | 5,900 | $295 |
| No | 206401405 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPB09A112A* | NAXWPH09B112AA | | 6,700 | $335 |
| No | 206401420 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPH09A112A* | NAXWPH09B112AA | | 6,700 | $335 |
| No | 206401422 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPH15A112A* | NAXWPH15B112AA | | 11,000 | $550 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206401421 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPH12A112A* | NAXWPH12B112AA | | 8,100 | $405 |
| No | 206401406 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPB12A112A* | NAXWPH12B112AA | | 8,100 | $405 |
| No | 206401407 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPB15A112A* | NAXWPH15B112AA | | 11,000 | $550 |
| No | 206401424 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPB18A112A* | NAXWPH18B112AA | | 13,700 | $685 |
| No | 204795658 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0361KA70B* | APVA0A0361AA70A | | 24,000 | $1,200 |
| No | 204795659 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0361KA70N* | APVA0A0361AA70A | | 24,000 | $1,200 |
| No | 204795640 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0181KA70B* | APKA0A0181HA70A | | 11,300 | $565 |
| No | 204795641 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0181KA70N* | APKA0A0181HA70A | | 11,300 | $565 |
| No | 204795656 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0301HA70B* | APVA0A0301AA70A | | 18,000 | $900 |
| No | 204795657 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0301HA70N* | APVA0A0301AA70A | | 18,000 | $900 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204795661 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0421KA70N* | APVA0A0421AA70A | | 28,400 | $1,420 |
| No | 204795660 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0421KA70B* | APVA0A0421AA70A | | 28,400 | $1,420 |
| No | 204795626 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0421KA70B* | APCA0A0421KA70A | | 31,800 | $1,590 |
| No | 204795627 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0421KA70N* | APCA0A0421KA70A | | 31,800 | $1,590 |
| No | 204795652 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0181KA70B* | APVA0A0181AA70A | | 12,000 | $600 |
| No | 204795624 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0361KA70B* | APCA0A0361KA70A | | 21,000 | $1,050 |
| No | 204795625 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0361KA70N* | APCA0A0361KA70A | | 21,000 | $1,050 |
| No | 204795653 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0181KA70N* | APVA0A0181AA70A | | 12,000 | $600 |
| No | 204795648 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0301HA70B* | APLA0A0301EA70A | | 18,100 | $905 |
| No | 204795649 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0301HA70N* | APLA0A0301EA70A | | 18,100 | $905 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204795638 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0121KA70B* | APKA0A0121HA70A | | 9,200 | $460 |
| No | 204795639 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0121KA70N* | APKA0A0121HA70A | | 9,200 | $460 |
| No | 204795620 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0241HA70B* | APCA0A0241KA70A | | 15,400 | $770 |
| No | 204795621 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0241HA70N* | APCA0A0241KA70A | | 15,400 | $770 |
| No | 204795642 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0241HA70B* | APKA0A0241KA70A | | 15,700 | $785 |
| No | 204795643 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0241HA70N* | APKA0A0241KA70A | | 15,700 | $785 |
| No | 204795654 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0241HA70B* | APVA0A0241AA70A | | 15,000 | $750 |
| No | 204795655 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0241HA70N* | APVA0A0241AA70A | | 15,000 | $750 |
| No | 204813310 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0121KA70N* | APVA0A0121AA70A | | 9,900 | $495 |
| No | 204813304 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0361KA70B* | APLA0A0361EA70A | | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204813306 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0361KA70N* | APLA0A0361EA70A | | 22,000 | $1,100 |
| No | 204813308 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0121KA70B* | APVA0A0121AA70A | | 9,900 | $495 |
| No | 204813297 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0181KA70B* | APLA0A0181EA70A | | 11,000 | $550 |
| No | 204813299 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0181KA70N* | APLA0A0181EA70A | | 11,000 | $550 |
| No | 204813293 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0121KA70B* | APLA0A0121EA70A | | 10,100 | $505 |
| No | 204813295 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | ASUZA0121KA70N* | APLA0A0121EA70A | | 10,100 | $505 |
| No | 204834258 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMMX48A182B* | Heat pump without ducts | | 33,000 | $1,650 |
| No | 204834259 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMMX48A182B* | Heat pump with ducts | | 33,000 | $1,650 |
| No | 204926520 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMMX48A182B* | Combination heat pumps with or without ducts | | 33,000 | $1,650 |
| No | 204793325 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSKH12A112AA | NAXDKS12A112AA | | 9,000 | $450 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204793326 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSKH12A112AA | NAXCKS12A112AA | | 8,300 | $415 |
| No | 204793336 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSKH18A112AA | NAXAMT18A112AA | | 14,300 | $715 |
| No | 204793333 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSKH18A112AA | NAXDKS18A112AA | | 14,200 | $710 |
| No | 202354895 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMPH30A132AA | Heat pump without ducts | | 18,000 | $900 |
| No | 202373683 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPB06A112AA | NAXWPH06A112AA | | 5,900 | $295 |
| No | 202373702 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMMX20A122AA | Heat pump without ducts | | 12,500 | $625 |
| No | 202392238 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSKS18A112AA | NAXCKS18A112AA | | 12,900 | $645 |
| No | 202392234 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSKS18A112AA | NAXUKS18A112AA | | 13,100 | $655 |
| No | 202392232 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSKS18A112AA | NAXDKS18A112AA | | 13,900 | $695 |
| No | 202392226 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSKS15A112AA | NAXDKS15A112AA | | 11,700 | $585 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202392222 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSKS12A112AA | NAXCKS12A112AA | | 8,900 | $445 |
| No | 202392218 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSKS12A112AA | NAXDKS12A112AA | | 10,000 | $500 |
| No | 202392220 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSKS12A112AA | NAXUKS12A112AA | | 9,900 | $495 |
| No | 202392214 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSKS09A112AA | NAXCKS09A112AA | | 6,900 | $345 |
| No | 202392208 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSKS09A112AA | NAXDKS09A112AA | | 7,600 | $380 |
| No | 202392210 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSKS09A112AA | NAXUKS09A112AA | | 7,700 | $385 |
| No | 202373696 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSST24A112AA | NAXWST24A112AA | | 16,000 | $800 |
| No | 202373689 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPB15A112AA | NAXWPH15A112AA | | 11,070 | $554 |
| No | 202373687 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPB12A112AA | NAXWPH12A112AA | | 8,100 | $405 |
| No | 202373685 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPB09A112AA | NAXWPH09A112AA | | 6,700 | $335 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202373688 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPH15A112AA | NAXWPH15A112AA | | 11,000 | $550 |
| No | 202373692 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSST09A112AA | NAXWST09A112AA | | 6,700 | $335 |
| No | 202373690 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPH18A112AA | NAXWPH18A112AA | | 13,700 | $685 |
| No | 202373695 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSST18A112AA | NAXWST18A112AA | | 13,800 | $690 |
| No | 202373691 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPB18A112AA | NAXWPH18A112AA | | 12,480 | $624 |
| No | 202373694 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSST15A112AA | NAXWST15A112AA | | 12,200 | $610 |
| No | 202373686 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPH12A112AA | NAXWPH12A112AA | | 8,000 | $400 |
| No | 202373693 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSST12A112AA | NAXWST12A112AA | | 9,200 | $460 |
| No | 202373682 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPH06A112AA | NAXWPH06A112AA | | 5,900 | $295 |
| No | 202373677 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPF12A112AA | NAXFKS12A112AA | | 8,800 | $440 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202373684 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPH09A112AA | NAXWPH09A112AA | | 6,700 | $335 |
| No | 202354890 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMMX36A142AA | Heat pump with ducts | | 20,200 | $1,010 |
| No | 202373698 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSMT12A112AA | NAXWMT12A112AA | | 7,600 | $380 |
| No | 202373701 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSMT24A112AA | NAXWMT24A112AA | | 18,500 | $925 |
| No | 202366323 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMMX24A132AA | Combination heat pumps with or without ducts | | 14,000 | $700 |
| No | 202392005 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMMX20A122AA | Combination heat pumps with or without ducts | | 13,000 | $650 |
| No | 202354886 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMMX24A132AA | Heat pump with ducts | | 14,000 | $700 |
| No | 202373670 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMPH20A122AA | Heat pump with ducts | | 13,700 | $685 |
| No | 202373669 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMMX20A122AA | Heat pump with ducts | | 12,500 | $625 |
| No | 202354892 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMPH24A132AA | Heat pump with ducts | | 14,000 | $700 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202354888 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMMX30A132AA | Heat pump with ducts | | 15,100 | $755 |
| No | 202366325 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMMX36A142AA | Combination heat pumps with or without ducts | | 21,200 | $1,060 |
| No | 202366324 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMMX30A132AA | Combination heat pumps with or without ducts | | 15,550 | $778 |
| No | 202373699 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSMT15A112AA | NAXWMT15A112AA | | 11,500 | $575 |
| No | 202373697 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSMT09A112AA | NAXWMT09A112AA | | 6,700 | $335 |
| No | 202373700 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSMT18A112AA | NAXWMT18A112AA | | 11,500 | $575 |
| No | 202373706 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMMX48A182AA | Heat pump without ducts | | 33,000 | $1,650 |
| No | 202392230 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSKS15A112AA | NAXCKS15A112AA | | 11,900 | $595 |
| No | 202392013 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXMMX48A182AA | Combination heat pumps with or without ducts | | 34,000 | $1,700 |
| No | 202373676 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSPF09A112AA | NAXFKS09A112AA | | 7,500 | $375 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202392228 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSKS15A112AA | PEAD-A15AA | | 11,300 | $565 |
| No | 202392224 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSKS12A112AA | NAXAMT12A112AA | | 9,900 | $495 |
| No | 202392212 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSKS09A112AA | PEAD-A09AA7 | | 7,600 | $380 |
| No | 202392216 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSKS12A112AA | PEAD-A12AA | | 9,900 | $495 |
| No | 202392240 | AMERICAN STANDARD / MITSUBISHI ELECTRIC | NAXSKS18A112AA | NAXAMT18A112AA | | 14,000 | $700 |
| No | 212394379 | AMERISTAR | E4HL5042A1000A | 4TXCC009DS3 | | 30,000 | $1,500 |
| No | 212394375 | AMERISTAR | E4HL5030A1000A | 4TXCB003DS3 | | 19,100 | $955 |
| No | 212394374 | AMERISTAR | E4HL5036A1000A | 4TXCB006DS3 | | 20,000 | $1,000 |
| No | 212394373 | AMERISTAR | E4HL5036A1000A | 4TXCB004DS3 | | 19,100 | $955 |
| No | 207642983 | AMERISTAR | M4THS2309A11N** | M4MHW2309A1N0** | | 7,300 | $365 |
| No | 10596841 | AMERISTAR | M4TLS1824A11N** | M4MLW1824A1N0** | | 16,000 | $800 |
| No | 203162809 | AMERISTAR | M4THS1809A11N** | M4MHW1809A1N0** | | 6,800 | $340 |
| No | 210488261 | AMERISTAR | M4THM1930A14N** | Heat pump without ducts | | 27,200 | $1,360 |
| No | 210488260 | AMERISTAR | M4THM1924A13N** | Heat pump without ducts | | 23,600 | $1,180 |
| No | 210488259 | AMERISTAR | M4THM1918A12N** | Heat pump without ducts | | 14,700 | $735 |
| No | 207642985 | AMERISTAR | M4THS2312A11N** | M4MHW2312A1N0** | | 7,700 | $385 |
| No | 208120592 | AMERISTAR | M4THS2318A11N** | M4MHW2318A1N0** | N/A | 11,400 | $570 |
| No | 208120590 | AMERISTAR | M4THS2324A11N** | M4MHW2324A1N0** | N/A | 15,500 | $775 |
| No | 10596838 | AMERISTAR | M4TLS1809A11N** | M4MLW1809A1N0** | | 5,800 | $290 |
| No | 203162808 | AMERISTAR | M4THS1812A11N** | M4MHW1812A1N0** | | 7,100 | $355 |
| No | 203162807 | AMERISTAR | M4THS1818A11N** | M4MHW1818A1N0** | | 12,400 | $620 |
| No | 209157101 | ApooDr | AM4OG-36HFN1 | Heat pump without ducts | | 26,400 | $1,320 |
| No | 209157098 | ApooDr | AM3OJ-27HFN1 | Heat pump without ducts | | 20,000 | $1,000 |
| No | 209157099 | ApooDr | AM3OJ-27HFN1 | Heat pump with ducts | | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 209157096 | ApooDr | AM2OA-18HFN1 | Heat pump with ducts | | 14,800 | $740 |
| No | 209157104 | ApooDr | AM5OG-48HFN1 | Heat pump without ducts | | 36,000 | $1,800 |
| No | 209157095 | ApooDr | AM2OA-18HFN1 | Heat pump without ducts | | 14,400 | $720 |
| No | 209157090 | ApooDr | AGN24-09H220V1B | AGN24-09H220V1A | | 8,100 | $405 |
| No | 209157089 | ApooDr | AGN24-09H1B | AGN24-09H1A | | 5,900 | $295 |
| No | 209157088 | ApooDr | AAG21-36H1B | AAG21-36H1A | | 24,000 | $1,200 |
| No | 209157086 | ApooDr | AAG21-24H1B | AAG21-24H1A | | 16,500 | $825 |
| No | 209157085 | ApooDr | AAG21-18H1B | AAG21-18H1A | | 11,400 | $570 |
| No | 209157084 | ApooDr | AAG21-12H220V1B | AAG21-12H220V1A | | 7,000 | $350 |
| No | 209157083 | ApooDr | AAG21-09H220V1B | AAG21-09H220V1A | | 6,000 | $300 |
| No | 209157082 | ApooDr | AAG21-12H1B | AAG21-12H1A | | 7,800 | $390 |
| No | 209157081 | ApooDr | AAG21-09H1B | AAG21-09H1A | | 6,300 | $315 |
| No | 209157094 | ApooDr | AGN24-24H1B | AGN24-24H1A | | 17,400 | $870 |
| No | 209157092 | ApooDr | AGN24-12H220V1B | AGN24-12H220V1A | | 10,000 | $500 |
| No | 209157091 | ApooDr | AGN24-12H1B | AGN24-12H1A | | 8,900 | $445 |
| No | 209157093 | ApooDr | AGN24-18H1B | AGN24-18H1A | | 14,100 | $705 |
| No | 209270312 | ApooDr | AHU19-60HN1-MR | AHU19-60HN1-M | | 37,000 | $1,850 |
| No | 209270311 | ApooDr | AHU19-48HN1-MR | AHU19-48HN1-M | | 37,000 | $1,850 |
| No | 209270310 | ApooDr | AHU19-36HN1-MR | AHU19-36HN1-M | | 20,400 | $1,020 |
| No | 209270308 | ApooDr | AHU19-24HN1-MR | AHU19-24HN1-M | | 21,000 | $1,050 |
| No | 209270307 | ApooDr | AHU19-18HN1-MR | AHU19-18HN1-M | | 12,000 | $600 |
| No | 210819420 | ARCOAIRE | DLCSRBH30AAK | DLFSABH30XBK | | 20,400 | $1,020 |
| No | 209852038 | ARCOAIRE | DLCURAH60AAK | DLFUAAH60XAK | | 37,000 | $1,850 |
| No | 209852035 | ARCOAIRE | DLCURAH48AAK | DLFUAAH48XAK | | 37,000 | $1,850 |
| No | 209852042 | ARCOAIRE | DLCURAH36AAK | DLFUAAH36XAK | | 20,400 | $1,020 |
| No | 209852044 | ARCOAIRE | DLCURAH30ABK | DLFUAAH30XAK | | 21,000 | $1,050 |
| No | 209852041 | ARCOAIRE | DLCURAH30AAK | DLFUAAH30XAK | | 20,000 | $1,000 |
| No | 209852034 | ARCOAIRE | DLCURAH24AAK | DLFUAAH24XAK | | 21,000 | $1,050 |
| No | 209852040 | ARCOAIRE | DLCURAH18AAK | DLFUAAH18XAK | | 12,000 | $600 |
| No | 207643005 | ARCOAIRE | DLCMRBH48EAK | Heat pump without ducts | | 31,000 | $1,550 |
| No | 201835525 | ARCOAIRE | DLCMRAH27CAK | Heat pump without ducts | | 17,800 | $890 |
| No | 208104309 | ARCOAIRE | DLCSRBH36ABK | DLFSABH36XBK | | 25,600 | $1,280 |
| No | 207826616 | ARCOAIRE | DLCLRCH36AAK | DLFLABH36XAK | | 25,600 | $1,280 |
| No | 207826615 | ARCOAIRE | DLCLRCH58AAK | DLFLABH60XAK | | 34,000 | $1,700 |
| No | 207826614 | ARCOAIRE | DLCLRCH48AAK | DLFLABH48XAK | | 37,400 | $1,870 |
| No | 207826594 | ARCOAIRE | DLCSRBH24AAK | DLFSABH24XBK | | 16,200 | $810 |
| No | 208104310 | ARCOAIRE | DLCSRBH30AAK11 | DLFSABH30XBK | | 19,200 | $960 |
| No | 206188282 | ARCOAIRE | DLCLRBH36AAK | DLFLFAH36XAK | | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206188285 | ARCOAIRE | DLCLRBH48AAK | DLFLFAH48XAK | | 29,000 | $1,450 |
| No | 206188283 | ARCOAIRE | DLCLRBH36AAK | DLFLCAH36XAK | | 22,000 | $1,100 |
| No | 206188286 | ARCOAIRE | DLCLRBH48AAK | DLFLCAH48XAK | | 29,000 | $1,450 |
| No | 206188287 | ARCOAIRE | DLCLRBH48AAK | DLFLDAH48XAK | | 29,000 | $1,450 |
| No | 207202611 | ARCOAIRE | DLCSRBH18AAK | FEM4P18**AL | | 14,700 | $735 |
| No | 207202612 | ARCOAIRE | DLCSRBH18AAK | FEM4X18**BL | | 14,700 | $735 |
| No | 207202613 | ARCOAIRE | DLCSRBH18AAK | EA*4X19L17A* | *80ES(N,L)0451412A* | 13,800 | $690 |
| No | 207202614 | ARCOAIRE | DLCSRBH18AAK | EA*4X24L14A* | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207202615 | ARCOAIRE | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207202620 | ARCOAIRE | DLCSRBH18AAK | EA*4X19L17A* | *80ES(N,L)0451712A* | 13,900 | $695 |
| No | 207202616 | ARCOAIRE | DLCSRBH18AAK | EA*4X25L17A* | *80ES(N,L)0451412A* | 13,800 | $690 |
| No | 207202617 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X18L14** | *80ES(N,L)0451412A* | 14,700 | $735 |
| No | 207202618 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X24L14** | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207202619 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207202621 | ARCOAIRE | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0451712A* | 14,600 | $730 |
| No | 207202622 | ARCOAIRE | DLCSRBH18AAK | EA*4X25L17A* | *80ES(N,L)0451712A* | 13,800 | $690 |
| No | 207202625 | ARCOAIRE | DLCSRBH18AAK | EA*4X25L17A* | *80ES(N,L)0701412A* | 13,800 | $690 |
| No | 207202623 | ARCOAIRE | DLCSRBH18AAK | EA*4X19L17A* | *80ES(N,L)0701412A* | 13,900 | $695 |
| No | 207202624 | ARCOAIRE | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0701412A* | 14,600 | $730 |
| No | 207202626 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X18L14** | *80ES(N,L)0701412A* | 14,700 | $735 |
| No | 207202627 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X24L14** | *80ES(N,L)0701412A* | 14,600 | $730 |
| No | 207202629 | ARCOAIRE | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0701712A* | 14,700 | $735 |
| No | 207202628 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ES(N,L)0701412A* | 14,600 | $730 |
| No | 207202631 | ARCOAIRE | DLCSRBH18AAK | EA*4X19L17A* | *80ESU0401712A* | 13,700 | $685 |
| No | 207202630 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ES(N,L)0701712A* | 14,700 | $735 |
| No | 207202632 | ARCOAIRE | DLCSRBH18AAK | EA*4X24L17A* | *80ESU0401712A* | 14,500 | $725 |
| No | 207202633 | ARCOAIRE | DLCSRBH18AAK | EA*4X25L17A* | *80ESU0401712A* | 13,600 | $680 |
| No | 207202635 | ARCOAIRE | DLCSRBH18AAK | EA*4X19L17A* | *92ESN0401410A* | 13,800 | $690 |
| No | 207202634 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ESU0401712A* | 14,500 | $725 |
| No | 207202644 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0401712A* | 14,600 | $730 |
| No | 207202636 | ARCOAIRE | DLCSRBH18AAK | EA*4X24L14A* | *92ESN0401410A* | 14,500 | $725 |
| No | 207202637 | ARCOAIRE | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0401410A* | 14,500 | $725 |
| No | 207202643 | ARCOAIRE | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0401712A* | 14,600 | $730 |
| No | 207202638 | ARCOAIRE | DLCSRBH18AAK | EA*4X25L17A* | *92ESN0401410A* | 13,700 | $685 |
| No | 207202640 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X24L14** | *92ESN0401410A* | 14,500 | $725 |
| No | 207202642 | ARCOAIRE | DLCSRBH18AAK | EA*4X19L17A* | *92ESN0401712A* | 13,900 | $695 |
| No | 207202639 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X18L14** | *92ESN0401410A* | 14,600 | $730 |
| No | 207202641 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0401410A* | 14,500 | $725 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207202645 | ARCOAIRE | DLCSRBH18AAK | EA*4X19L17A* | *92ESN0601412A* | 14,000 | $700 |
| No | 207202646 | ARCOAIRE | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0601412A* | 14,600 | $730 |
| No | 207202648 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X18L14** | *92ESN0601412A* | 14,700 | $735 |
| No | 207202649 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X24L14** | *92ESN0601412A* | 14,600 | $730 |
| No | 207202647 | ARCOAIRE | DLCSRBH18AAK | EA*4X25L17A* | *92ESN0601412A* | 13,800 | $690 |
| No | 207202650 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0601412A* | 14,600 | $730 |
| No | 207202651 | ARCOAIRE | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0801716A* | 14,700 | $735 |
| No | 207202652 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0801716A* | 14,700 | $735 |
| No | 207202653 | ARCOAIRE | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0261410A* | 14,100 | $705 |
| No | 207202654 | ARCOAIRE | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0261410A* | 14,700 | $735 |
| No | 207202655 | ARCOAIRE | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0261410A* | 13,900 | $695 |
| No | 207202656 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X18L14** | *95ESN0261410A* | 14,800 | $740 |
| No | 207202657 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X24L14** | *95ESN0261410A* | 14,700 | $735 |
| No | 207202658 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0261410A* | 14,700 | $735 |
| No | 207202659 | ARCOAIRE | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0401410A* | 13,900 | $695 |
| No | 207202660 | ARCOAIRE | DLCSRBH18AAK | EA*4X24L14A* | *95ESN0401410A* | 14,600 | $730 |
| No | 207202662 | ARCOAIRE | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0401410A* | 13,800 | $690 |
| No | 207202661 | ARCOAIRE | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0401410A* | 14,600 | $730 |
| No | 207202663 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X18L14** | *95ESN0401410A* | 14,700 | $735 |
| No | 207202669 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0401712A* | 14,600 | $730 |
| No | 207202665 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0401410A* | 14,600 | $730 |
| No | 207202664 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X24L14** | *95ESN0401410A* | 14,600 | $730 |
| No | 207202666 | ARCOAIRE | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0401712A* | 13,800 | $690 |
| No | 207202667 | ARCOAIRE | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0401712A* | 14,600 | $730 |
| No | 207202668 | ARCOAIRE | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0401712A* | 13,700 | $685 |
| No | 207202673 | ARCOAIRE | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0601714A* | 14,000 | $700 |
| No | 207202670 | ARCOAIRE | DLCSRBH18AAK | EA*4X24L14A* | *95ESN0601412A* | 14,900 | $745 |
| No | 207202674 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0601714A* | 14,700 | $735 |
| No | 207202672 | ARCOAIRE | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0601714A* | 14,100 | $705 |
| No | 207202671 | ARCOAIRE | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0601412A* | 14,900 | $745 |
| No | 207202675 | ARCOAIRE | DLCSRBH18AAK | EA*4X19L17A* | *95ESU0401712A* | 13,800 | $690 |
| No | 207202678 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESU0401712A* | 14,600 | $730 |
| No | 207202676 | ARCOAIRE | DLCSRBH18AAK | EA*4X24L17A* | *95ESU0401712A* | 14,600 | $730 |
| No | 207202680 | ARCOAIRE | DLCSRBH18AAK | EA*4X24L14A* | *96VTN0401410A* | 14,700 | $735 |
| No | 207202677 | ARCOAIRE | DLCSRBH18AAK | EA*4X25L17A* | *95ESU0401712A* | 13,800 | $690 |
| No | 207202679 | ARCOAIRE | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0401410A* | 13,900 | $695 |
| No | 207202681 | ARCOAIRE | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0401410A* | 14,700 | $735 |
| No | 207202682 | ARCOAIRE | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0401410A* | 13,900 | $695 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207202687 | ARCOAIRE | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0401712A* | 14,600 | $730 |
| No | 207202683 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X18L14** | *96VTN0401410A* | 14,800 | $740 |
| No | 207202684 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X24L14** | *96VTN0401410A* | 14,700 | $735 |
| No | 207202685 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X24L17** | *96VTN0401410A* | 14,700 | $735 |
| No | 207202686 | ARCOAIRE | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0401712A* | 13,900 | $695 |
| No | 207202690 | ARCOAIRE | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0601412A* | 13,800 | $690 |
| No | 207202689 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X24L17** | *96VTN0401712A* | 14,600 | $730 |
| No | 207202688 | ARCOAIRE | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0401712A* | 13,800 | $690 |
| No | 207202692 | ARCOAIRE | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0601412A* | 14,600 | $730 |
| No | 207202691 | ARCOAIRE | DLCSRBH18AAK | EA*4X24L14A* | *96VTN0601412A* | 14,600 | $730 |
| No | 207202694 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X18L14** | *96VTN0601412A* | 14,700 | $735 |
| No | 207202693 | ARCOAIRE | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0601412A* | 13,800 | $690 |
| No | 207202700 | ARCOAIRE | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0801716A* | 13,800 | $690 |
| No | 207202697 | ARCOAIRE | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0601714A* | 14,100 | $705 |
| No | 207202695 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X24L14** | *96VTN0601412A* | 14,600 | $730 |
| No | 207202696 | ARCOAIRE | DLCSRBH18AAK | EN(A,D)4X24L17** | *96VTN0601412A* | 14,600 | $730 |
| No | 207202698 | ARCOAIRE | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0601714A* | 14,700 | $735 |
| No | 207202699 | ARCOAIRE | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0601714A* | 13,900 | $695 |
| No | 207202609 | ARCOAIRE | DLCSRBH18AAK | FM(C,U)4Z18**AL* | | 15,000 | $750 |
| No | 207202608 | ARCOAIRE | DLCSRBH18AAK | FMA4X18**AL* | | 15,000 | $750 |
| No | 207202172 | ARCOAIRE | DLCSRBH18AAK | FVM4X24***L | | 13,400 | $670 |
| No | 207202610 | ARCOAIRE | DLCSRBH18AAK | FXM4X18**AL | | 14,500 | $725 |
| No | 207099020 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X24L14** | *80ES(N,L)0701412A* | 15,600 | $780 |
| No | 207099015 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X24L14** | *80ES(N,L)0451412A* | 15,600 | $780 |
| No | 207099018 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X30L14** | *80ES(N,L)0451412A* | 15,500 | $775 |
| No | 207099017 | ARCOAIRE | DLCSRBH24AAK | EA*4X30L14A* | *80ES(N,L)0451412A* | 15,500 | $775 |
| No | 207099016 | ARCOAIRE | DLCSRBH24AAK | EA*4X24L14A* | *80ES(N,L)0451412A* | 15,700 | $785 |
| No | 207099019 | ARCOAIRE | DLCSRBH24AAK | EA*4X36L17A* | *80ES(N,L)0451712A* | 15,500 | $775 |
| No | 207099023 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X30L14** | *80ES(N,L)0701412A* | 15,500 | $775 |
| No | 207099022 | ARCOAIRE | DLCSRBH24AAK | EA*4X30L14A* | *80ES(N,L)0701412A* | 15,500 | $775 |
| No | 207099021 | ARCOAIRE | DLCSRBH24AAK | EA*4X24L14A* | *80ES(N,L)0701412A* | 15,700 | $785 |
| No | 207099024 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X24L17** | *80ES(N,L)0701712A* | 15,600 | $780 |
| No | 207099026 | ARCOAIRE | DLCSRBH24AAK | EA*4X36L17A* | *80ES(N,L)0701712A* | 15,400 | $770 |
| No | 207099025 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X30L17** | *80ES(N,L)0701712A* | 15,400 | $770 |
| No | 207099027 | ARCOAIRE | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *80ES(N,L)0701712A* | 15,400 | $770 |
| No | 207099028 | ARCOAIRE | DLCSRBH24AAK | EA*4X30L17A* | *80ES(N,L)0701712A* | 15,500 | $775 |
| No | 207099030 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X30L17** | *80ESU0401712A* | 15,400 | $770 |
| No | 207099029 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X24L17** | *80ESU0401712A* | 15,500 | $775 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207099031 | ARCOAIRE | DLCSRBH24AAK | EA*4X36L17A* | *80ESU0401712A* | 15,300 | $765 |
| No | 207099032 | ARCOAIRE | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *80ESU0401712A* | 15,400 | $770 |
| No | 207099033 | ARCOAIRE | DLCSRBH24AAK | EA*4X30L17A* | *80ESU0401712A* | 15,400 | $770 |
| No | 207099034 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X24L17** | *80ESU0601716A | 15,600 | $780 |
| No | 207099035 | ARCOAIRE | DLCSRBH24AAK | EA*4X24L17A* | *80ESU0601716A | 15,700 | $785 |
| No | 207099051 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X24L14** | *92ESN0601412A* | 15,600 | $780 |
| No | 207099053 | ARCOAIRE | DLCSRBH24AAK | EA*4X30L14A* | *92ESN0601412A* | 15,500 | $775 |
| No | 207099037 | ARCOAIRE | DLCSRBH24AAK | EA*4X36L17A* | *80ESU0601716A | 15,400 | $770 |
| No | 207099038 | ARCOAIRE | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *80ESU0601716A | 15,500 | $775 |
| No | 207099036 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X30L17** | *80ESU0601716A | 15,500 | $775 |
| No | 207099056 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X24L14** | *92ESN0601714A* | 15,500 | $775 |
| No | 207099052 | ARCOAIRE | DLCSRBH24AAK | EA*4X24L14A* | *92ESN0601412A* | 15,700 | $785 |
| No | 207099060 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X24L17** | *92ESN0801716A* | 15,500 | $775 |
| No | 207099054 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X30L14** | *92ESN0601412A* | 15,500 | $775 |
| No | 207099057 | ARCOAIRE | DLCSRBH24AAK | EA*4X24L14A* | *92ESN0601714A* | 15,700 | $785 |
| No | 207099058 | ARCOAIRE | DLCSRBH24AAK | EA*4X30L14A* | *92ESN0601714A* | 15,500 | $775 |
| No | 207099059 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X30L14** | *92ESN0601714A* | 15,400 | $770 |
| No | 207099061 | ARCOAIRE | DLCSRBH24AAK | EA*4X24L17A* | *92ESN0801716A* | 15,700 | $785 |
| No | 207099062 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X30L17** | *92ESN0801716A* | 15,400 | $770 |
| No | 207099064 | ARCOAIRE | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *92ESN0801716A* | 15,400 | $770 |
| No | 207099063 | ARCOAIRE | DLCSRBH24AAK | EA*4X36L17A* | *92ESN0801716A* | 15,400 | $770 |
| No | 207099065 | ARCOAIRE | DLCSRBH24AAK | EA*4X30L17A* | *92ESN0801716A* | 15,400 | $770 |
| No | 207099068 | ARCOAIRE | DLCSRBH24AAK | EA*4X30L14A* | *95ESN0261410A* | 15,500 | $775 |
| No | 207099067 | ARCOAIRE | DLCSRBH24AAK | EA*4X24L14A* | *95ESN0261410A* | 15,800 | $790 |
| No | 207099069 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X30L14** | *95ESN0261410A* | 15,500 | $775 |
| No | 207099147 | ARCOAIRE | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0401410A* | 15,300 | $765 |
| No | 207099076 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESN0401712A* | 15,600 | $780 |
| No | 207099077 | ARCOAIRE | DLCSRBH24AAK | EA*4X36L17A* | *95ESN0401712A* | 15,500 | $775 |
| No | 207099079 | ARCOAIRE | DLCSRBH24AAK | EA*4X30L17A* | *95ESN0401712A* | 15,600 | $780 |
| No | 207099078 | ARCOAIRE | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESN0401712A* | 15,600 | $780 |
| No | 207099135 | ARCOAIRE | DLCSRBH24AAK | EA*4X25L17A* | *95ESN0401712A* | 15,200 | $760 |
| No | 207099136 | ARCOAIRE | DLCSRBH24AAK | EA*4X36L21A* | *95ESN0401712A* | 15,500 | $775 |
| No | 207099138 | ARCOAIRE | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0401712A* | 15,300 | $765 |
| No | 207099139 | ARCOAIRE | DLCSRBH24AAK | EA*4X37L21A* | *95ESN0401712A* | 15,200 | $760 |
| No | 207099141 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X36L21** | *95ESN0401712A* | 15,600 | $780 |
| No | 207099082 | ARCOAIRE | DLCSRBH24AAK | EA*4X24L14A* | *95ESN0601412A* | 15,800 | $790 |
| No | 207099083 | ARCOAIRE | DLCSRBH24AAK | EA*4X30L14A* | *95ESN0601412A* | 15,600 | $780 |
| No | 207099081 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X24L14** | *95ESN0601412A* | 15,600 | $780 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207099084 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X30L14** | *95ESN0601412A* | 15,500 | $775 |
| No | 207099124 | ARCOAIRE | DLCSRBH24AAK | EA*4X24L17A* | *95ESN0601412A* | 15,800 | $790 |
| No | 207099125 | ARCOAIRE | DLCSRBH24AAK | EA*4X25L17A* | *95ESN0601412A* | 15,200 | $760 |
| No | 207099127 | ARCOAIRE | DLCSRBH24AAK | EA*4X36L17A* | *95ESN0601412A* | 15,500 | $775 |
| No | 207099129 | ARCOAIRE | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0601412A* | 15,300 | $765 |
| No | 207099128 | ARCOAIRE | DLCSRBH24AAK | EA*4X30L17A* | *95ESN0601412A* | 15,600 | $780 |
| No | 207099087 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESN0601714A* | 15,500 | $775 |
| No | 207099133 | ARCOAIRE | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESN0601412A* | 15,500 | $775 |
| No | 207099132 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESN0601412A* | 15,500 | $775 |
| No | 207099130 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X24L17** | *95ESN0601412A* | 15,600 | $780 |
| No | 207099085 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X24L17** | *95ESN0601714A* | 15,600 | $780 |
| No | 207099086 | ARCOAIRE | DLCSRBH24AAK | EA*4X24L17A* | *95ESN0601714A* | 15,800 | $790 |
| No | 207099120 | ARCOAIRE | DLCSRBH24AAK | EA*4X36L21A* | *95ESN0601714A* | 15,400 | $770 |
| No | 207099089 | ARCOAIRE | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESN0601714A* | 15,500 | $775 |
| No | 207099119 | ARCOAIRE | DLCSRBH24AAK | EA*4X25L17A* | *95ESN0601714A* | 15,200 | $760 |
| No | 207099121 | ARCOAIRE | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0601714A* | 15,200 | $760 |
| No | 207099088 | ARCOAIRE | DLCSRBH24AAK | EA*4X36L17A* | *95ESN0601714A* | 15,400 | $770 |
| No | 207099090 | ARCOAIRE | DLCSRBH24AAK | EA*4X30L17A* | *95ESN0601714A* | 15,500 | $775 |
| No | 207099123 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X36L21** | *95ESN0601714A* | 15,500 | $775 |
| No | 207099122 | ARCOAIRE | DLCSRBH24AAK | EA*4X37L21A* | *95ESN0601714A* | 15,100 | $755 |
| No | 207099039 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X24L17** | *95ESU0401712A* | 15,600 | $780 |
| No | 207099040 | ARCOAIRE | DLCSRBH24AAK | EA*4X24L17A* | *95ESU0401712A* | 15,700 | $785 |
| No | 207099042 | ARCOAIRE | DLCSRBH24AAK | EA*4X36L17A* | *95ESU0401712A* | 15,400 | $770 |
| No | 207099041 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESU0401712A* | 15,500 | $775 |
| No | 207099043 | ARCOAIRE | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESU0401712A* | 15,500 | $775 |
| No | 207099044 | ARCOAIRE | DLCSRBH24AAK | EA*4X30L17A* | *95ESU0401712A* | 15,500 | $775 |
| No | 207099095 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X30L14** | *96VTN0401410A* | 15,600 | $780 |
| No | 207099094 | ARCOAIRE | DLCSRBH24AAK | EA*4X30L14A* | *96VTN0401410A* | 15,600 | $780 |
| No | 207099099 | ARCOAIRE | DLCSRBH24AAK | EA*4X36L17A* | *96VTN0401712A* | 15,500 | $775 |
| No | 207099105 | ARCOAIRE | DLCSRBH24AAK | EA*4X30L14A* | *96VTN0601412A* | 15,600 | $780 |
| No | 207099106 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X30L14** | *96VTN0601412A* | 15,600 | $780 |
| No | 207099107 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X24L17** | *96VTN0601714A* | 15,600 | $780 |
| No | 207099109 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X30L17** | *96VTN0601714A* | 15,500 | $775 |
| No | 207099108 | ARCOAIRE | DLCSRBH24AAK | EA*4X24L17A* | *96VTN0601714A* | 15,800 | $790 |
| No | 207099110 | ARCOAIRE | DLCSRBH24AAK | EA*4X36L17A* | *96VTN0601714A* | 15,400 | $770 |
| No | 207099112 | ARCOAIRE | DLCSRBH24AAK | EA*4X30L17A* | *96VTN0601714A* | 15,500 | $775 |
| No | 207099111 | ARCOAIRE | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *96VTN0601714A* | 15,500 | $775 |
| No | 207099113 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X24L17** | *96VTN0801716A* | 15,600 | $780 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207099115 | ARCOAIRE | DLCSRBH24AAK | EN(A,D)4X30L17** | *96VTN0801716A* | 15,500 | $775 |
| No | 207099114 | ARCOAIRE | DLCSRBH24AAK | EA*4X24L17A* | *96VTN0801716A* | 15,700 | $785 |
| No | 207099116 | ARCOAIRE | DLCSRBH24AAK | EA*4X36L17A* | *96VTN0801716A* | 15,400 | $770 |
| No | 207199007 | ARCOAIRE | DLCSRBH30AAK | EA*4X30L14A* | *80ES(N,L)0451412A* | 19,200 | $960 |
| No | 207099118 | ARCOAIRE | DLCSRBH24AAK | EA*4X30L17A* | *96VTN0801716A* | 15,500 | $775 |
| No | 207099117 | ARCOAIRE | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *96VTN0801716A* | 15,500 | $775 |
| No | 207099012 | ARCOAIRE | DLCSRBH24AAK | FMA4X24**AL* | | 16,000 | $800 |
| No | 207099010 | ARCOAIRE | DLCSRBH24AAK | FXM4X24**AL | | 15,500 | $775 |
| No | 207099013 | ARCOAIRE | DLCSRBH24AAK | FM(C,U)4Z24**AL* | | 16,100 | $805 |
| No | 207199009 | ARCOAIRE | DLCSRBH30AAK | EA*4X30L17A* | *80ES(N,L)0451712A* | 19,100 | $955 |
| No | 207199008 | ARCOAIRE | DLCSRBH30AAK | EN(A,D)4X30L14** | *80ES(N,L)0451412A* | 19,200 | $960 |
| No | 207199010 | ARCOAIRE | DLCSRBH30AAK | EN(A,D)4X30L17** | *80ES(N,L)0451712A* | 19,100 | $955 |
| No | 207199011 | ARCOAIRE | DLCSRBH30AAK | EA*4X30L14A* | *80ES(N,L)0701412A* | 19,100 | $955 |
| No | 207199012 | ARCOAIRE | DLCSRBH30AAK | EN(A,D)4X30L14** | *80ES(N,L)0701412A* | 19,100 | $955 |
| No | 207199015 | ARCOAIRE | DLCSRBH30AAK | EA*4X36L21A* | *80ES(N,L)0702116A* | 19,000 | $950 |
| No | 207199013 | ARCOAIRE | DLCSRBH30AAK | EA*4X30L17A* | *80ES(N,L)0701716A* | 19,300 | $965 |
| No | 207199014 | ARCOAIRE | DLCSRBH30AAK | EN(A,D)4X30L17** | *80ES(N,L)0701716A* | 19,300 | $965 |
| No | 207199018 | ARCOAIRE | DLCSRBH30AAK | EA*4X30L17A* | *80ESU0401712A* | 19,000 | $950 |
| No | 207199022 | ARCOAIRE | DLCSRBH30AAK | EA*4X30L17A* | *92ESN0601714A* | 19,100 | $955 |
| No | 207199016 | ARCOAIRE | DLCSRBH30AAK | EN(A,D)4X36L21** | *80ES(N,L)0702116A* | 19,100 | $955 |
| No | 207199017 | ARCOAIRE | DLCSRBH30AAK | EN(A,D)4X36L21** | *80ES(N,L)0902116A* | 19,300 | $965 |
| No | 207199020 | ARCOAIRE | DLCSRBH30AAK | EA*4X30L14A* | *92ESN0601412A* | 19,200 | $960 |
| No | 207199019 | ARCOAIRE | DLCSRBH30AAK | EN(A,D)4X30L17** | *80ESU0401712A* | 19,000 | $950 |
| No | 207199021 | ARCOAIRE | DLCSRBH30AAK | EN(A,D)4X30L14** | *92ESN0601412A* | 19,200 | $960 |
| No | 207199023 | ARCOAIRE | DLCSRBH30AAK | EN(A,D)4X30L17** | *92ESN0601714A* | 19,100 | $955 |
| No | 207199024 | ARCOAIRE | DLCSRBH30AAK | EA*4X30L17A* | *92ESN0801716A* | 19,100 | $955 |
| No | 207199025 | ARCOAIRE | DLCSRBH30AAK | EN(A,D)4X30L17** | *92ESN0801716A* | 19,100 | $955 |
| No | 207199042 | ARCOAIRE | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0401410A* | 19,100 | $955 |
| No | 207199046 | ARCOAIRE | DLCSRBH30AAK | END4X42L17** | *95ESN0401410A* | 19,200 | $960 |
| No | 207199050 | ARCOAIRE | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0401712A* | 19,300 | $965 |
| No | 207199052 | ARCOAIRE | DLCSRBH30AAK | EA*4X36L17A* | *95ESN0401712A* | 19,300 | $965 |
| No | 207199051 | ARCOAIRE | DLCSRBH30AAK | EA*4X36L21A* | *95ESN0401712A* | 19,300 | $965 |
| No | 207199057 | ARCOAIRE | DLCSRBH30AAK | EA*4X30L14A* | *95ESN0601412A* | 19,300 | $965 |
| No | 207199054 | ARCOAIRE | DLCSRBH30AAK | EA*4X42L21A* | *95ESN0401712A* | 19,200 | $960 |
| No | 207199053 | ARCOAIRE | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0401712A* | 19,000 | $950 |
| No | 207199056 | ARCOAIRE | DLCSRBH30AAK | END4X42L17** | *95ESN0401712A* | 19,100 | $955 |
| No | 207199058 | ARCOAIRE | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0601412A* | 19,300 | $965 |
| No | 207199055 | ARCOAIRE | DLCSRBH30AAK | EA*4X43L21A* | *95ESN0401712A* | 18,700 | $935 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207199059 | ARCOAIRE | DLCSRBH30AAK | EA*4X36L17A* | *95ESN0601412A* | 19,200 | $960 |
| No | 207199060 | ARCOAIRE | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0601412A* | 19,000 | $950 |
| No | 207199062 | ARCOAIRE | DLCSRBH30AAK | EN(A,D)4X30L14** | *95ESN0601412A* | 19,300 | $965 |
| No | 207199063 | ARCOAIRE | DLCSRBH30AAK | EN(A,D,W)4X36L17** | *95ESN0601412A* | 19,300 | $965 |
| No | 207199064 | ARCOAIRE | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESN0601412A* | 19,300 | $965 |
| No | 207199065 | ARCOAIRE | DLCSRBH30AAK | END4X42L17** | *95ESN0601412A* | 19,100 | $955 |
| No | 207199067 | ARCOAIRE | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0601714A* | 19,300 | $965 |
| No | 207199068 | ARCOAIRE | DLCSRBH30AAK | EA*4X36L17A* | *95ESN0601714A* | 19,200 | $960 |
| No | 207199070 | ARCOAIRE | DLCSRBH30AAK | EA*4X36L21A* | *95ESN0601714A* | 19,200 | $960 |
| No | 207199072 | ARCOAIRE | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0601714A* | 19,000 | $950 |
| No | 207199073 | ARCOAIRE | DLCSRBH30AAK | EA*4X42L21A* | *95ESN0601714A* | 19,100 | $955 |
| No | 207199077 | ARCOAIRE | DLCSRBH30AAK | EA*4X43L21A* | *95ESN0601714A* | 18,700 | $935 |
| No | 207199075 | ARCOAIRE | DLCSRBH30AAK | EA*4X37L21A* | *95ESN0601714A* | 18,700 | $935 |
| No | 207199079 | ARCOAIRE | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESN0601714A* | 19,200 | $960 |
| No | 207199081 | ARCOAIRE | DLCSRBH30AAK | EN(A,D)4X36L21** | *95ESN0601714A* | 19,200 | $960 |
| No | 207199027 | ARCOAIRE | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESN0801716A* | 19,300 | $965 |
| No | 207199083 | ARCOAIRE | DLCSRBH30AAK | END4X42L17** | *95ESN0601714A* | 19,000 | $950 |
| No | 207199084 | ARCOAIRE | DLCSRBH30AAK | EN(A,D,W)4X42L21** | *95ESN0601714A* | 19,100 | $955 |
| No | 207199082 | ARCOAIRE | DLCSRBH30AAK | EN(A,D,W)4X36L17** | *95ESN0601714A* | 19,200 | $960 |
| No | 207199026 | ARCOAIRE | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0801716A* | 19,300 | $965 |
| No | 207199028 | ARCOAIRE | DLCSRBH30AAK | EA*4X36L21A* | *95ESN0802120A* | 19,100 | $955 |
| No | 207199029 | ARCOAIRE | DLCSRBH30AAK | EA*4X30L17A* | *95ESU0401712A* | 19,000 | $950 |
| No | 207199034 | ARCOAIRE | DLCSRBH30AAK | EN(A,D)4X30L17** | *96VTN0601714A* | 19,100 | $955 |
| No | 207199031 | ARCOAIRE | DLCSRBH30AAK | EA*4X30L17A* | *96VTN0401712A* | 19,300 | $965 |
| No | 207199030 | ARCOAIRE | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESU0401712A* | 19,000 | $950 |
| No | 207199032 | ARCOAIRE | DLCSRBH30AAK | EN(A,D)4X30L14** | *96VTN0601412A* | 19,300 | $965 |
| No | 207199033 | ARCOAIRE | DLCSRBH30AAK | EA*4X30L17A* | *96VTN0601714A* | 19,100 | $955 |
| No | 207199035 | ARCOAIRE | DLCSRBH30AAK | EA*4X30L17A* | *96VTN0801716A* | 19,100 | $955 |
| No | 207199036 | ARCOAIRE | DLCSRBH30AAK | EN(A,D)4X30L17** | *96VTN0801716A* | 19,100 | $955 |
| No | 207199037 | ARCOAIRE | DLCSRBH30AAK | EA*4X36L21A* | *96VTN0802120A* | 18,800 | $940 |
| No | 207199038 | ARCOAIRE | DLCSRBH30AAK | EN(A,D)4X36L21** | *96VTN0802120A* | 19,000 | $950 |
| No | 207199039 | ARCOAIRE | DLCSRBH30AAK | EA*4X36L21A* | *96VTN1002120A* | 18,800 | $940 |
| No | 207198926 | ARCOAIRE | DLCSRBH30AAK | FVM4X36***L | | 19,200 | $960 |
| No | 207200385 | ARCOAIRE | DLCSRBH30AAK | EN(A,D)4X36L21** | *96VTN1002120A* | 20,800 | $1,040 |
| No | 207199004 | ARCOAIRE | DLCSRBH30AAK | FMA4X30**AL* | | 19,400 | $970 |
| No | 207199006 | ARCOAIRE | DLCSRBH30AAK | FM(C,U)4Z30**AL* | | 19,200 | $960 |
| No | 207199005 | ARCOAIRE | DLCSRBH30AAK | FXM4X30**AL | | 18,800 | $940 |
| No | 207199002 | ARCOAIRE | DLCSRBH30AAK | FEM4P30**AL | | 19,100 | $955 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207199003 | ARCOAIRE | DLCSRBH30AAK | FEM4X30**BL | | 19,100 | $955 |
| No | 206188284 | ARCOAIRE | DLCLRBH36AAK | DLFLDAH36XAK | | 27,000 | $1,350 |
| No | 207642991 | ARCOAIRE | DLCMHBH24CAK | Heat pump with ducts | | 18,500 | $925 |
| No | 207643006 | ARCOAIRE | DLCMRBH48EAK | Heat pump with ducts | | 30,400 | $1,520 |
| No | 207642988 | ARCOAIRE | DLCMRBH18BAK | Heat pump with ducts | | 11,800 | $590 |
| No | 207642992 | ARCOAIRE | DLCMHBH24CAK | Combination heat pumps with or without ducts | | 15,900 | $795 |
| No | 207642989 | ARCOAIRE | DLCMRBH18BAK | Combination heat pumps with or without ducts | | 11,800 | $590 |
| No | 207643007 | ARCOAIRE | DLCMRBH48EAK | Combination heat pumps with or without ducts | | 30,600 | $1,530 |
| No | 207642990 | ARCOAIRE | DLCMHBH24CAK | Heat pump without ducts | | 13,300 | $665 |
| No | 207642987 | ARCOAIRE | DLCMRBH18BAK | Heat pump without ducts | | 11,800 | $590 |
| No | 207642997 | ARCOAIRE | DLCMRBH36DAK | Heat pump without ducts | | 24,000 | $1,200 |
| No | 206350383 | ARCOAIRE | DLCSRBH09AAK | DLFSDAH09XAK | | 6,400 | $320 |
| No | 206350382 | ARCOAIRE | DLCSRBH09AAK | DLFSCAH09XAK | | 6,100 | $305 |
| No | 206396068 | ARCOAIRE | DLCSRBH12AAK | DLFSHAH12XAK | | 7,500 | $375 |
| No | 206361870 | ARCOAIRE | DLCSRBH12AAK | DLFSHBH12XAK | | 7,300 | $365 |
| No | 206350385 | ARCOAIRE | DLCSRBH12AAK | DLFSDAH12XAK | | 8,300 | $415 |
| No | 206396069 | ARCOAIRE | DLCSRAH12AAK | DLFSHBH12XAK | | 7,500 | $375 |
| No | 206396072 | ARCOAIRE | DLCSRAH24AAK | DLFSHBH24XAK | | 15,000 | $750 |
| No | 206396073 | ARCOAIRE | DLCSRBH24AAK | DLFSHAH24XAK | | 15,000 | $750 |
| No | 206361872 | ARCOAIRE | DLCSRBH24AAK | DLFSHBH24XAK | | 17,000 | $850 |
| No | 206361868 | ARCOAIRE | DLCSRBH12AAJ | DLFSHBH12XAJ | | 8,200 | $410 |
| No | 206361871 | ARCOAIRE | DLCSRBH18AAK | DLFSHBH18XAK | | 11,100 | $555 |
| No | 206361869 | ARCOAIRE | DLCSRBH09AAK | DLFSHBH09XAK | | 7,400 | $370 |
| No | 206350384 | ARCOAIRE | DLCSRBH12AAK | DLFSCAH12XAK | | 7,900 | $395 |
| No | 206350386 | ARCOAIRE | DLCSRBH12AAK | DLFSFAH12XAK | | 8,400 | $420 |
| No | 205767340 | ARCOAIRE | DLCLRBH36AAK | DLFLAAH36XAK | | 25,000 | $1,250 |
| No | 205767341 | ARCOAIRE | DLCLRBH48AAK | DLFLAAH48XAK | | 36,000 | $1,800 |
| No | 201835520 | ARCOAIRE | DLCSRAH36AAK | DLFSHAH36XAK | | 20,600 | $1,030 |
| No | 202463642 | ARCOAIRE | DLCPRAH18AAK | DLFPHAH18XAK | | 12,300 | $615 |
| No | 201835550 | ARCOAIRE | DLCMRAH48EAK | Heat pump without ducts | | 30,400 | $1,520 |
| No | 201835526 | ARCOAIRE | DLCMRAH36DAK | Heat pump without ducts | | 23,600 | $1,180 |
| No | 201835514 | ARCOAIRE | DLCSRAH12AAJ | DLFSHAH12XAJ | | 7,100 | $355 |
| No | 201835507 | ARCOAIRE | DLCPRAH12AAK | DLFPHAH12XAK | | 6,800 | $340 |
| No | 201835506 | ARCOAIRE | DLCPRAH09AAK | DLFPHAH09XAK | | 7,200 | $360 |
| No | 201835515 | ARCOAIRE | DLCSRAH09AAK | DLFSHAH09XAK | | 7,500 | $375 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201835523 | ARCOAIRE | DLCLRAH58AAK | DLFLDAH58XAK | | 37,600 | $1,880 |
| No | 201835517 | ARCOAIRE | DLCSRAH18AAK | DLFSHAH18XAK | | 11,900 | $595 |
| No | 201835516 | ARCOAIRE | DLCSRAH12AAK | DLFSHAH12XAK | | 7,600 | $380 |
| No | 201835545 | ARCOAIRE | DLCLRAH48AAK | DLFLCAH48XAK | | 35,000 | $1,750 |
| No | 201835546 | ARCOAIRE | DLCLRAH58AAK | DLFLFAH58XAK | | 39,000 | $1,950 |
| No | 201835522 | ARCOAIRE | DLCLRAH48AAK | DLFLDAH48XAK | | 33,400 | $1,670 |
| No | 201835521 | ARCOAIRE | DLCLRAH36AAK | DLFLDAH36XAK | | 27,600 | $1,380 |
| No | 201835535 | ARCOAIRE | DLCSRAH12AAK | DLFSDAH12XAK | | 8,100 | $405 |
| No | 201835534 | ARCOAIRE | DLCSRAH12AAK | DLFSFAH12XAK | | 9,600 | $480 |
| No | 201835542 | ARCOAIRE | DLCLRAH36AAK | DLFLCAH36XAK | | 25,200 | $1,260 |
| No | 201835532 | ARCOAIRE | DLCSRAH09AAK | DLFSCAH09XAK | | 6,700 | $335 |
| No | 201835536 | ARCOAIRE | DLCSRAH18AAK | DLFSFAH18XAK | | 12,900 | $645 |
| No | 201835533 | ARCOAIRE | DLCSRAH12AAK | DLFSCAH12XAK | | 8,200 | $410 |
| No | 201835541 | ARCOAIRE | DLCLRAH36AAK | DLFLFAH36XAK | | 25,400 | $1,270 |
| No | 201835531 | ARCOAIRE | DLCSRAH09AAK | DLFSDAH09XAK | | 6,800 | $340 |
| No | 207821945 | ARCTIC KING | MOD33-24HFN1-MT0W | MSAG11D-23HRFN1-MU0W | | 17,400 | $870 |
| No | 208106745 | ARM STRONG AIR | 4DHV2S24S-1P | DWH224S4-1P | | 16,500 | $825 |
| No | 208106744 | ARM STRONG AIR | 4DHV2S18S-1P | DWH218S4-1P | | 11,400 | $570 |
| No | 208106743 | ARM STRONG AIR | 4DHV2S12S-1P | DWH212S4-1P | | 7,000 | $350 |
| No | 208106741 | ARM STRONG AIR | 4DHV2S12S-1L | DWH212S4-1L | | 7,800 | $390 |
| No | 208106742 | ARM STRONG AIR | 4DHV2S09S-1P | DWH209S4-1P | | 6,000 | $300 |
| No | 208106740 | ARM STRONG AIR | 4DHV2S09S-1L | DWH209S4-1L | | 6,300 | $315 |
| No | 211034540 | Armstrong Air | 4DHV2S12S-1L | DWH212S4-*L | | 7,800 | $390 |
| No | 211034539 | Armstrong Air | 4DHV2S09S-1L | DWH209S4-*L | | 6,300 | $315 |
| No | 211034519 | Armstrong Air | 4DHP2S12S-1L | DWM212S4-*L | | 8,400 | $420 |
| No | 211034544 | Armstrong Air | 4DHV2S24S-1P | DWH224S4-*P | | 16,500 | $825 |
| No | 211034543 | Armstrong Air | 4DHV2S18S-1P | DWH218S4-*P | | 11,400 | $570 |
| No | 211034542 | Armstrong Air | 4DHV2S12S-1P | DWH212S4-*P | | 7,000 | $350 |
| No | 211034541 | Armstrong Air | 4DHV2S09S-1P | DWH209S4-*P | | 6,000 | $300 |
| No | 211034538 | Armstrong Air | 4DHP2S48S-1P | D33C248S4-*P | | 30,000 | $1,500 |
| No | 211034537 | Armstrong Air | 4DHP2S36S-1P | D33C236S4-*P | | 23,000 | $1,150 |
| No | 211034536 | Armstrong Air | 4DHP2S24S-1P | D33C224S4-*P | | 19,000 | $950 |
| No | 211034535 | Armstrong Air | 4DHP2S18S-1P | D22C118S4-*P | | 12,000 | $600 |
| No | 211034534 | Armstrong Air | 4DHP2S12S-1P | D22C112S4-*P | | 8,900 | $445 |
| No | 211034533 | Armstrong Air | 4DHPS209S-1P | D22C109S4-*P | | 7,500 | $375 |
| No | 211034532 | Armstrong Air | 4DHP2S48S-1P | DMD248S4-*P | | 34,000 | $1,700 |
| No | 211034531 | Armstrong Air | 4DHP2S36S-1P | DMD236S4-*P | | 25,000 | $1,250 |
| No | 211034530 | Armstrong Air | 4DHP2S24S-1P | DMD224S4-*P | | 20,000 | $1,000 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211034529 | Armstrong Air | 4DHP2S18S-1P | DMD218S4-*P | | 12,600 | $630 |
| No | 211034528 | Armstrong Air | 4DHP2S12S-1P | DMD212S4-*P | | 9,300 | $465 |
| No | 211034527 | Armstrong Air | 4DHPS209S-1P | DMD209S4-*P | | 7,700 | $385 |
| No | 211034524 | Armstrong Air | 4DHP2S30S-1P | DWM230S4-*P | | 19,000 | $950 |
| No | 211034523 | Armstrong Air | 4DHP2S24S-1P | DWM224S4-*P | | 16,200 | $810 |
| No | 211034522 | Armstrong Air | 4DHP2S18S-1P | DWM218S4-*P | | 14,900 | $745 |
| No | 211034521 | Armstrong Air | 4DHP2S12S-1P | DWM212S4-*P | | 9,000 | $450 |
| No | 211034520 | Armstrong Air | 4DHPS209S-1P | DWM209S4-*P | | 8,500 | $425 |
| No | 208106739 | ARMSTRONG AIR | 4DHPS209S-1P | DMD209S4-1P | | 7,700 | $385 |
| No | 208106738 | ARMSTRONG AIR | 4DHPS209S-1P | D22C109S4-1P | | 7,500 | $375 |
| No | 208106736 | ARMSTRONG AIR | 4DHPS209S-1P | DWM209S4-1P | | 8,500 | $425 |
| No | 208106821 | ARMSTRONG AIR | 4DHP2S36M-1P | Heat pump without ducts | | 26,800 | $1,340 |
| No | 208106818 | ARMSTRONG AIR | 4DHP2S30M-1P | Heat pump without ducts | | 21,000 | $1,050 |
| No | 208106819 | ARMSTRONG AIR | 4DHP2S30M-1P | Ducted Indoor Units | | 22,000 | $1,100 |
| No | 208106674 | ARMSTRONG AIR | 4DHP2S24S-1P | DWM224S4-1P | | 16,200 | $810 |
| No | 208106815 | ARMSTRONG AIR | 4DHP2S24M-1P | Non-Ducted Indoor Units | | 20,400 | $1,020 |
| No | 208106816 | ARMSTRONG AIR | 4DHP2S24M-1P | Ducted Indoor Units | | 21,600 | $1,080 |
| No | 208106679 | ARMSTRONG AIR | 4DHP2S18S-1P | DMD218S4-1P | | 12,600 | $630 |
| No | 208106673 | ARMSTRONG AIR | 4DHP2S18S-1P | DWM218S4-1P | | 14,900 | $745 |
| No | 208106813 | ARMSTRONG AIR | 4DHP2S18M-1P | Heat pump with ducts | | 14,800 | $740 |
| No | 208106812 | ARMSTRONG AIR | 4DHP2S18M-1P | Heat pump without ducts | | 14,300 | $715 |
| No | 208106672 | ARMSTRONG AIR | 4DHP2S12S-1P | DWM212S4-1P | | 9,000 | $450 |
| No | 208106675 | ARMSTRONG AIR | 4DHP2S12S-1P | D22C112S4-1P | | 8,900 | $445 |
| No | 208106678 | ARMSTRONG AIR | 4DHP2S12S-1P | DMD212S4-1P | | 9,300 | $465 |
| No | 208106735 | ARMSTRONG AIR | 4DHP2S12S-1L | DWM212S4-1L | | 8,400 | $420 |
| No | 211954933 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30B+TDR+TXV | A97USMV070B12 | 14,300 | $715 |
| No | 211954931 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30B+TDR+TXV | A97US2V060B12X | 14,400 | $720 |
| No | 211954929 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30B+TDR+TXV | A97US2V040B12X | 14,400 | $720 |
| No | 211954927 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30B+TDR+TXV | A80US2V090B16L | 14,300 | $715 |
| No | 211954925 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30B+TDR+TXV | A80US2V090B16 | 14,300 | $715 |
| No | 211954924 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30B+TDR+TXV | A80US2V090B12 | 14,300 | $715 |
| No | 211954922 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30B+TDR+TXV | A80US2V080B16X | 14,400 | $720 |
| No | 211954920 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30B+TDR+TXV | A96UH1E070B12 | 14,500 | $725 |
| No | 211954918 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30B+TDR+TXV | A96UH1E045B12 | 14,500 | $725 |
| No | 211954916 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30B+TDR+TXV | A96UH1E030B12 | 14,500 | $725 |
| No | 211954914 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30B+TDR+TXV | A93UH1E070B12 | 14,400 | $720 |
| No | 211954912 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30B+TDR+TXV | A93UH1E045B12 | 14,500 | $725 |
| No | 211954910 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30B+TDR+TXV | A93UH1E030B12 | 14,500 | $725 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211954909 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30B+TDR+TXV | A80UH1E090B16 | 14,500 | $725 |
| No | 211954907 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30B+TDR+TXV | A80UH1E070B12 | 14,200 | $710 |
| No | 211954905 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30B+TDR+TXV | A96US2V070B12 | 14,400 | $720 |
| No | 211954903 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30B+TDR+TXV | A96UH2E070B12 | 14,500 | $725 |
| No | 211954901 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30B+TDR+TXV | A96US2V045B12 | 14,400 | $720 |
| No | 211954899 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30B+TDR+TXV | A96UH2E045B12 | 14,500 | $725 |
| No | 211954897 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30B+TDR+TXV | A80UH2E090B16 | 14,500 | $725 |
| No | 211954896 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30B+TDR+TXV | A80UH2E090B12 | 14,400 | $720 |
| No | 211954894 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30B+TDR+TXV | A80UH1E080B16X | 14,700 | $735 |
| No | 211954892 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30A+TDR+TXV | A80US2V070A12L | 14,300 | $715 |
| No | 211954890 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30A+TDR+TXV | A80US2V070A12 | 14,300 | $715 |
| No | 211954888 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30A+TDR+TXV | A80US2V060A12X | 14,300 | $715 |
| No | 211954886 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30A+TDR+TXV | A80UH1E070A12 | 14,000 | $700 |
| No | 211954885 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30A+TDR+TXV | A80UH1E045A12 | 14,300 | $715 |
| No | 211954883 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30A+TDR+TXV | A80UH2E070A12 | 14,300 | $715 |
| No | 211954881 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30A+TDR+TXV | A80UH2E045A12 | 13,900 | $695 |
| No | 211954879 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30A+TDR+TXV | A80UH1E060A12X | 14,200 | $710 |
| No | 211954877 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAH1P30A+TDR+TXV | A80UH1E040A12X | 14,200 | $710 |
| No | 211729606 | ARMSTRONG AIR | 4SHP22LX124P-**A | BCE5E30M | | 14,500 | $725 |
| No | 211729605 | ARMSTRONG AIR | 4SHP22LX124P-**A | BCE5E24M | | 15,000 | $750 |
| No | 211708571 | ARMSTRONG AIR | 4SHP22LX136P-**A | BCE5E42M | | 22,200 | $1,110 |
| No | 211708570 | ARMSTRONG AIR | 4SHP22LX136P-**A | BCE5E36M | | 21,800 | $1,090 |
| No | 211708567 | ARMSTRONG AIR | 4SHP22LX136P-**A | BCE7S36M*4X | | 22,800 | $1,140 |
| No | 211699899 | ARMSTRONG AIR | 4SHP22LX148P-**A | BCE7S60M*4X | | 27,200 | $1,360 |
| No | 211727079 | ARMSTRONG AIR | 4SHP22LX160P-**A | BCE5E60M | | 36,800 | $1,840 |
| No | 211727077 | ARMSTRONG AIR | 4SHP22LX160P-**A | BCE7S60M*4X | | 37,000 | $1,850 |
| No | 211528407 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P48B+TDR+TXV | A97DSMV070B12 | 21,800 | $1,090 |
| No | 211528406 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P48B+TDR+TXV | A80DS2V090B16 | 21,800 | $1,090 |
| No | 211528405 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P48B+TDR+TXV | A96DF1E070B16 | 21,800 | $1,090 |
| No | 211528404 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P48B+TDR+TXV | A96DF1E045B12 | 21,600 | $1,080 |
| No | 211528403 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P48B+TDR+TXV | A93DF1E070B12 | 21,600 | $1,080 |
| No | 211528402 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P48B+TDR+TXV | A93DF1E045B12 | 21,800 | $1,090 |
| No | 211528401 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P48B+TDR+TXV | A80DF1E090B16 | 21,400 | $1,070 |
| No | 211528400 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P48B+TDR+TXV | A80DF1E070B12 | 21,600 | $1,080 |
| No | 211528399 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P48B+TDR+TXV | A96DS2V070B16 | 22,000 | $1,100 |
| No | 211528398 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P48B+TDR+TXV | A96DF2E070B16 | 21,800 | $1,090 |
| No | 211528397 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P48B+TDR+TXV | A96DS2V045B12 | 22,000 | $1,100 |
| No | 211804088 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48C+TDR | A97USMV110C20 | 22,400 | $1,120 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211804086 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48C+TDR | A97USMV090C16 | 22,400 | $1,120 |
| No | 211804085 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48C+TDR | A97USMV090C12 | 22,400 | $1,120 |
| No | 211804083 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48C+TDR | A97US2V080C16X | 22,400 | $1,120 |
| No | 211804079 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48C+TDR | A96US2V110C16 | 22,400 | $1,120 |
| No | 211804076 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48C+TDR | A96US2V090C16 | 22,400 | $1,120 |
| No | 211804075 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48C+TDR | A96US2V090C12 | 22,400 | $1,120 |
| No | 211804073 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48C+TDR+TXV | A97USMV110C20 | 22,400 | $1,120 |
| No | 211804071 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48C+TDR+TXV | A97USMV090C16 | 22,400 | $1,120 |
| No | 211804070 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48C+TDR+TXV | A97USMV090C12 | 22,400 | $1,120 |
| No | 211804068 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48C+TDR+TXV | A97US2V080C16X | 22,400 | $1,120 |
| No | 211804064 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48C+TDR+TXV | A96US2V110C16 | 22,400 | $1,120 |
| No | 211804061 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48C+TDR+TXV | A96US2V090C16 | 22,400 | $1,120 |
| No | 211804060 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48C+TDR+TXV | A96US2V090C12 | 22,400 | $1,120 |
| No | 211709445 | ARMSTRONG AIR | 4SHP22LX124P-**A | ED1P24B+TDR+TXV | A97DSMV070B12 | 15,000 | $750 |
| No | 211709444 | ARMSTRONG AIR | 4SHP22LX124P-**A | ED1P24B+TDR+TXV | A80DS2V090B16 | 15,100 | $755 |
| No | 211709443 | ARMSTRONG AIR | 4SHP22LX124P-**A | ED1P24B+TDR+TXV | A96DF1E070B16 | 15,000 | $750 |
| No | 211709442 | ARMSTRONG AIR | 4SHP22LX124P-**A | ED1P24B+TDR+TXV | A96DF1E045B12 | 15,000 | $750 |
| No | 211709441 | ARMSTRONG AIR | 4SHP22LX124P-**A | ED1P24B+TDR+TXV | A93DF1E070B12 | 14,900 | $745 |
| No | 211709440 | ARMSTRONG AIR | 4SHP22LX124P-**A | ED1P24B+TDR+TXV | A93DF1E045B12 | 14,900 | $745 |
| No | 211709439 | ARMSTRONG AIR | 4SHP22LX124P-**A | ED1P24B+TDR+TXV | A80DF1E090B16 | 15,100 | $755 |
| No | 211709438 | ARMSTRONG AIR | 4SHP22LX124P-**A | ED1P24B+TDR+TXV | A80DF1E070B12 | 15,000 | $750 |
| No | 211709437 | ARMSTRONG AIR | 4SHP22LX124P-**A | ED1P24B+TDR+TXV | A96DS2V070B16 | 15,200 | $760 |
| No | 211709436 | ARMSTRONG AIR | 4SHP22LX124P-**A | ED1P24B+TDR+TXV | A96DF2E070B16 | 14,900 | $745 |
| No | 211709435 | ARMSTRONG AIR | 4SHP22LX124P-**A | ED1P24B+TDR+TXV | A96DS2V045B12 | 15,000 | $750 |
| No | 211709434 | ARMSTRONG AIR | 4SHP22LX124P-**A | ED1P24B+TDR+TXV | A96DF2E045B12 | 14,900 | $745 |
| No | 211709433 | ARMSTRONG AIR | 4SHP22LX124P-**A | ED1P24A+TDR+TXV | A80DS2V070A12 | 15,000 | $750 |
| No | 211709432 | ARMSTRONG AIR | 4SHP22LX124P-**A | ED1P24A+TDR+TXV | A80DF1E070A12 | 14,900 | $745 |
| No | 211709431 | ARMSTRONG AIR | 4SHP22LX124P-**A | ED1P24A+TDR+TXV | A80DF1E045A12 | 14,900 | $745 |
| No | 211709476 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24B+TDR | A97USMV070B12 | 14,700 | $735 |
| No | 211709475 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24B+TDR | A97US2V060B12X | 14,700 | $735 |
| No | 211709474 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24B+TDR | A97US2V040B12X | 14,700 | $735 |
| No | 211709473 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24B+TDR | A80US2V090B16L | 14,600 | $730 |
| No | 211709472 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24B+TDR | A80US2V090B16 | 14,600 | $730 |
| No | 211709471 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24B+TDR | A80US2V090B12 | 14,600 | $730 |
| No | 211709470 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24B+TDR | A80US2V080B16X | 14,800 | $740 |
| No | 211709469 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24B+TDR | A96UH1E070B12 | 14,800 | $740 |
| No | 211709468 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24B+TDR | A96UH1E045B12 | 14,800 | $740 |
| No | 211709467 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24B+TDR | A96UH1E030B12 | 14,800 | $740 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211709466 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24B+TDR | A93UH1E070B12 | 14,700 | $735 |
| No | 211709465 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24B+TDR | A93UH1E045B12 | 14,800 | $740 |
| No | 211709464 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24B+TDR | A93UH1E030B12 | 14,800 | $740 |
| No | 211709463 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24B+TDR | A80UH1E090B16 | 14,800 | $740 |
| No | 211709462 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24B+TDR | A80UH1E070B12 | 14,500 | $725 |
| No | 211709461 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24B+TDR | A96US2V070B12 | 14,700 | $735 |
| No | 211709460 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24B+TDR | A96UH2E070B12 | 14,800 | $740 |
| No | 211709459 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24B+TDR | A96US2V045B12 | 14,800 | $740 |
| No | 211709458 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24B+TDR | A96UH2E045B12 | 14,800 | $740 |
| No | 211709457 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24B+TDR | A80UH2E090B16 | 14,800 | $740 |
| No | 211709456 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24B+TDR | A80UH2E090B12 | 14,700 | $735 |
| No | 211709455 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24B+TDR | A80UH1E080B16X | 15,000 | $750 |
| No | 211709390 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A97USMV070B12 | 14,700 | $735 |
| No | 211709389 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A97US2V060B12X | 14,700 | $735 |
| No | 211709388 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A97US2V040B12X | 14,700 | $735 |
| No | 211709387 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A80US2V090B16L | 14,600 | $730 |
| No | 211709386 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A80US2V090B16 | 14,600 | $730 |
| No | 211709385 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A80US2V090B12 | 14,600 | $730 |
| No | 211709384 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A80US2V080B16X | 14,800 | $740 |
| No | 211709383 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A96UH1E070B12 | 14,800 | $740 |
| No | 211709382 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A96UH1E045B12 | 14,800 | $740 |
| No | 211709381 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A96UH1E030B12 | 14,800 | $740 |
| No | 211709380 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A93UH1E070B12 | 14,700 | $735 |
| No | 211709379 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A93UH1E045B12 | 14,800 | $740 |
| No | 211709378 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A93UH1E030B12 | 14,800 | $740 |
| No | 211709377 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A80UH1E090B16 | 14,800 | $740 |
| No | 211709376 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A80UH1E070B12 | 14,500 | $725 |
| No | 211709375 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A96US2V070B12 | 14,700 | $735 |
| No | 211709374 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A96UH2E070B12 | 14,800 | $740 |
| No | 211709373 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A96US2V045B12 | 14,800 | $740 |
| No | 211709372 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A96UH2E045B12 | 14,800 | $740 |
| No | 211709371 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A80UH2E090B16 | 14,800 | $740 |
| No | 211709370 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A80UH2E090B12 | 14,700 | $735 |
| No | 211709369 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24B+TDR+TXV | A80UH1E080B16X | 15,000 | $750 |
| No | 211709454 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24A+TDR | A80US2V070A12L | 14,700 | $735 |
| No | 211709453 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24A+TDR | A80US2V070A12 | 14,700 | $735 |
| No | 211709452 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24A+TDR | A80US2V060A12X | 14,700 | $735 |
| No | 211709451 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24A+TDR | A80UH1E070A12 | 14,500 | $725 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211709450 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24A+TDR | A80UH1E045A12 | 14,200 | $710 |
| No | 211709449 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24A+TDR | A80UH2E070A12 | 14,700 | $735 |
| No | 211709448 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24A+TDR | A80UH2E045A12 | 14,300 | $715 |
| No | 211709447 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24A+TDR | A80UH1E060A12X | 14,700 | $735 |
| No | 211709446 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X24A+TDR | A80UH1E040A12X | 14,700 | $735 |
| No | 211709368 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24A+TDR+TXV | A80US2V070A12L | 14,700 | $735 |
| No | 211709367 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24A+TDR+TXV | A80US2V070A12 | 14,700 | $735 |
| No | 211709366 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24A+TDR+TXV | A80US2V060A12X | 14,700 | $735 |
| No | 211709365 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24A+TDR+TXV | A80UH1E070A12 | 14,500 | $725 |
| No | 211709364 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24A+TDR+TXV | A80UH1E045A12 | 14,200 | $710 |
| No | 211709363 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24A+TDR+TXV | A80UH2E070A12 | 14,700 | $735 |
| No | 211709362 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24A+TDR+TXV | A80UH2E045A12 | 14,300 | $715 |
| No | 211709361 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24A+TDR+TXV | A80UH1E060A12X | 14,700 | $735 |
| No | 211709360 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P24A+TDR+TXV | A80UH1E040A12X | 14,700 | $735 |
| No | 211709498 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30B+TDR | A97DSMV070B12 | 14,200 | $710 |
| No | 211709499 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30B+TDR | A97USMV070B12 | 14,200 | $710 |
| No | 211709497 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30B+TDR | A97US2V060B12X | 14,200 | $710 |
| No | 211709496 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30B+TDR | A97US2V040B12X | 14,200 | $710 |
| No | 211709495 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30B+TDR | A80US2V090B16L | 14,100 | $705 |
| No | 211709494 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30B+TDR | A80US2V090B16 | 14,100 | $705 |
| No | 211709493 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30B+TDR | A80US2V090B12 | 14,100 | $705 |
| No | 211709492 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30B+TDR | A80US2V080B16X | 14,300 | $715 |
| No | 211709491 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30B+TDR | A96UH1E070B12 | 14,400 | $720 |
| No | 211709490 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30B+TDR | A96UH1E045B12 | 14,400 | $720 |
| No | 211709489 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30B+TDR | A96UH1E030B12 | 13,900 | $695 |
| No | 211709488 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30B+TDR | A93UH1E070B12 | 14,200 | $710 |
| No | 211709487 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30B+TDR | A93UH1E045B12 | 14,300 | $715 |
| No | 211709486 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30B+TDR | A93UH1E030B12 | 13,800 | $690 |
| No | 211709485 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30B+TDR | A80UH1E090B16 | 14,400 | $720 |
| No | 211709484 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30B+TDR | A80UH1E070B12 | 14,000 | $700 |
| No | 211709483 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30B+TDR | A96US2V070B12 | 14,200 | $710 |
| No | 211709482 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30B+TDR | A96UH2E070B12 | 14,300 | $715 |
| No | 211709481 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30B+TDR | A96US2V045B12 | 14,300 | $715 |
| No | 211709480 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30B+TDR | A96UH2E045B12 | 14,300 | $715 |
| No | 211709479 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30B+TDR | A80UH2E090B16 | 14,400 | $720 |
| No | 211709478 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30B+TDR | A80UH2E090B12 | 14,300 | $715 |
| No | 211709477 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30B+TDR | A80UH1E080B16X | 14,500 | $725 |
| No | 211709421 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A97DSMV070B12 | 14,200 | $710 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211709422 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A97USMV070B12 | 14,200 | $710 |
| No | 211709420 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A97US2V060B12X | 14,200 | $710 |
| No | 211709419 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A97US2V040B12X | 14,200 | $710 |
| No | 211709418 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A80US2V090B16L | 14,100 | $705 |
| No | 211709417 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A80US2V090B16 | 14,100 | $705 |
| No | 211709416 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A80US2V090B12 | 14,100 | $705 |
| No | 211709415 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A80US2V080B16X | 14,300 | $715 |
| No | 211709414 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A96UH1E070B12 | 14,400 | $720 |
| No | 211709413 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A96UH1E045B12 | 14,400 | $720 |
| No | 211709412 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A96UH1E030B12 | 13,900 | $695 |
| No | 211709411 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A93UH1E070B12 | 14,200 | $710 |
| No | 211709410 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A93UH1E045B12 | 14,300 | $715 |
| No | 211709409 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A93UH1E030B12 | 13,800 | $690 |
| No | 211709408 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A80UH1E090B16 | 14,400 | $720 |
| No | 211709407 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A80UH1E070B12 | 14,000 | $700 |
| No | 211709406 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A96US2V070B12 | 14,200 | $710 |
| No | 211709405 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A96UH2E070B12 | 14,300 | $715 |
| No | 211709404 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A96US2V045B12 | 14,300 | $715 |
| No | 211709403 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A96UH2E045B12 | 14,300 | $715 |
| No | 211709402 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A80UH2E090B16 | 14,400 | $720 |
| No | 211709401 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A80UH2E090B12 | 14,300 | $715 |
| No | 211709400 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30B+TDR+TXV | A80UH1E080B16X | 14,500 | $725 |
| No | 211709508 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30A+TDR | A80US2V070A12L | 14,200 | $710 |
| No | 211709507 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30A+TDR | A80US2V070A12 | 14,200 | $710 |
| No | 211709506 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30A+TDR | A80US2V060A12X | 14,200 | $710 |
| No | 211709505 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30A+TDR | A80UH1E070A12 | 14,000 | $700 |
| No | 211709504 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30A+TDR | A80UH1E045A12 | 14,200 | $710 |
| No | 211709503 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30A+TDR | A80UH2E070A12 | 14,300 | $715 |
| No | 211709502 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30A+TDR | A80UH2E045A12 | 13,900 | $695 |
| No | 211709501 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30A+TDR | A80UH1E060A12X | 14,200 | $710 |
| No | 211709500 | ARMSTRONG AIR | 4SHP22LX124P-**A | EAC4X30A+TDR | A80UH1E040A12X | 14,200 | $710 |
| No | 211709399 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30A+TDR+TXV | A80US2V070A12L | 14,200 | $710 |
| No | 211709398 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30A+TDR+TXV | A80US2V070A12 | 14,200 | $710 |
| No | 211709397 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30A+TDR+TXV | A80US2V060A12X | 14,200 | $710 |
| No | 211709396 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30A+TDR+TXV | A80UH1E070A12 | 14,000 | $700 |
| No | 211709395 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30A+TDR+TXV | A80UH1E045A12 | 14,200 | $710 |
| No | 211709394 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30A+TDR+TXV | A80UH2E070A12 | 14,300 | $715 |
| No | 211709393 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30A+TDR+TXV | A80UH2E045A12 | 13,900 | $695 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211709392 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30A+TDR+TXV | A80UH1E060A12X | 14,200 | $710 |
| No | 211709391 | ARMSTRONG AIR | 4SHP22LX124P-**A | EA(C;U)1P30A+TDR+TXV | A80UH1E040A12X | 14,200 | $710 |
| No | 211709424 | ARMSTRONG AIR | 4SHP22LX124P-**A | BCE5C30M*4X | | 14,900 | $745 |
| No | 211709426 | ARMSTRONG AIR | 4SHP22LX124P-**A | BCE5V30M*4X | | 14,500 | $725 |
| No | 211709423 | ARMSTRONG AIR | 4SHP22LX124P-**A | BCE5C24M*4X | | 14,700 | $735 |
| No | 211709425 | ARMSTRONG AIR | 4SHP22LX124P-**A | BCE5V24M*4X | | 14,900 | $745 |
| No | 211709427 | ARMSTRONG AIR | 4SHP22LX124P-**A | BCE7E18M*4X | | 14,100 | $705 |
| No | 211709428 | ARMSTRONG AIR | 4SHP22LX124P-**A | BCE7E24M*4X | | 14,500 | $725 |
| No | 211709430 | ARMSTRONG AIR | 4SHP22LX124P-**A | BCE7S24M*4X | | 14,400 | $720 |
| No | 211804132 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A97USMV110C20 | 38,000 | $1,900 |
| No | 211804245 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A97USMV090C20 | 38,000 | $1,900 |
| No | 211804244 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A97USMV090C16 | 38,500 | $1,925 |
| No | 211804131 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A80US2V110C20L | 37,800 | $1,890 |
| No | 211804130 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A80US2V110C20 | 37,800 | $1,890 |
| No | 211804128 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A80US2V090C20 | 37,800 | $1,890 |
| No | 211804126 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A96US2V110C20 | 38,000 | $1,900 |
| No | 211804237 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A96US2V090C20 | 38,000 | $1,900 |
| No | 211804236 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A96US2V090C16 | 38,500 | $1,925 |
| No | 211804243 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A97US2V080C20X | 38,000 | $1,900 |
| No | 211804129 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A80US2V100C20X | 38,000 | $1,900 |
| No | 211804127 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A80US2V080C20X | 38,000 | $1,900 |
| No | 211804242 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A96UH1E110C20 | 38,000 | $1,900 |
| No | 211804241 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A93UH1E110C20 | 38,000 | $1,900 |
| No | 211804240 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A80UH1E110C20 | 38,500 | $1,925 |
| No | 211804239 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A80UH1E090C20 | 38,500 | $1,925 |
| No | 211804238 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A96UH2E110C20 | 38,000 | $1,900 |
| No | 211804125 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A80UH2E110C20 | 37,600 | $1,880 |
| No | 211804235 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P50/60C+TDR+TXV | A80UH1E100C20X | 38,500 | $1,925 |
| No | 211804124 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A97USMV110C20 | 38,000 | $1,900 |
| No | 211804234 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A97USMV090C20 | 38,000 | $1,900 |
| No | 211804233 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A97USMV090C16 | 38,500 | $1,925 |
| No | 211804123 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A80US2V110C20L | 37,800 | $1,890 |
| No | 211804122 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A80US2V110C20 | 37,800 | $1,890 |
| No | 211804120 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A80US2V090C20 | 37,800 | $1,890 |
| No | 211804118 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A96US2V110C20 | 38,000 | $1,900 |
| No | 211804226 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A96US2V090C20 | 38,000 | $1,900 |
| No | 211804225 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A96US2V090C16 | 38,500 | $1,925 |
| No | 211804232 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A97US2V080C20X | 38,000 | $1,900 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211804121 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A80US2V100C20X | 38,000 | $1,900 |
| No | 211804119 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A80US2V080C20X | 38,000 | $1,900 |
| No | 211804231 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A96UH1E110C20 | 38,000 | $1,900 |
| No | 211804230 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A93UH1E110C20 | 38,000 | $1,900 |
| No | 211804229 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A80UH1E110C20 | 38,500 | $1,925 |
| No | 211804228 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A80UH1E090C20 | 38,500 | $1,925 |
| No | 211804227 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A96UH2E110C20 | 38,000 | $1,900 |
| No | 211804117 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A80UH2E110C20 | 37,600 | $1,880 |
| No | 211804224 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X50/60C+TDR | A80UH1E100C20X | 38,500 | $1,925 |
| No | 211528977 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X60C+TDR | A97USMV110C20 | 37,400 | $1,870 |
| No | 211530232 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X60C+TDR | A97USMV090C20 | 37,600 | $1,880 |
| No | 211530231 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X60C+TDR | A97USMV090C16 | 37,800 | $1,890 |
| No | 211530230 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X60C+TDR | A97US2V080C20X | 37,600 | $1,880 |
| No | 211528976 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X60C+TDR | A80US2V110C20L | 37,400 | $1,870 |
| No | 211528975 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X60C+TDR | A80US2V110C20 | 37,400 | $1,870 |
| No | 211528974 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X60C+TDR | A80US2V100C20X | 37,400 | $1,870 |
| No | 211528973 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X60C+TDR | A80US2V090C20 | 37,400 | $1,870 |
| No | 211528972 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X60C+TDR | A80US2V080C20X | 37,400 | $1,870 |
| No | 211530229 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X60C+TDR | A96UH1E110C20 | 37,800 | $1,890 |
| No | 211530228 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X60C+TDR | A93UH1E110C20 | 37,800 | $1,890 |
| No | 211530227 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X60C+TDR | A80UH1E110C20 | 37,800 | $1,890 |
| No | 211528971 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X60C+TDR | A80UH1E090C20 | 37,000 | $1,850 |
| No | 211528970 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X60C+TDR | A96US2V110C20 | 37,400 | $1,870 |
| No | 211530226 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X60C+TDR | A96US2V110C16 | 37,800 | $1,890 |
| No | 211530225 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X60C+TDR | A96UH2E110C20 | 37,800 | $1,890 |
| No | 211530224 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X60C+TDR | A96US2V090C20 | 37,600 | $1,880 |
| No | 211530223 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X60C+TDR | A96US2V090C16 | 37,800 | $1,890 |
| No | 211528969 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X60C+TDR | A80UH2E110C20 | 37,200 | $1,860 |
| No | 211530222 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X60C+TDR | A80UH1E100C20X | 38,000 | $1,900 |
| No | 211528952 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A97USMV110C20 | 37,400 | $1,870 |
| No | 211530214 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A97USMV090C20 | 37,600 | $1,880 |
| No | 211530213 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A97USMV090C16 | 37,800 | $1,890 |
| No | 211530212 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A97US2V080C20X | 37,600 | $1,880 |
| No | 211528951 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A80US2V110C20L | 37,400 | $1,870 |
| No | 211528950 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A80US2V110C20 | 37,400 | $1,870 |
| No | 211528949 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A80US2V100C20X | 37,400 | $1,870 |
| No | 211528948 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A80US2V090C20 | 37,400 | $1,870 |
| No | 211528947 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A80US2V080C20X | 37,400 | $1,870 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211530211 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A96UH1E110C20 | 37,800 | $1,890 |
| No | 211530210 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A93UH1E110C20 | 37,800 | $1,890 |
| No | 211530209 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A80UH1E110C20 | 37,800 | $1,890 |
| No | 211528946 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A80UH1E090C20 | 37,000 | $1,850 |
| No | 211528945 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A96US2V110C20 | 37,400 | $1,870 |
| No | 211530208 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A96US2V110C16 | 37,800 | $1,890 |
| No | 211530207 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A96UH2E110C20 | 37,800 | $1,890 |
| No | 211530206 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A96US2V090C20 | 37,600 | $1,880 |
| No | 211530205 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A96US2V090C16 | 37,800 | $1,890 |
| No | 211528944 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A80UH2E110C20 | 37,200 | $1,860 |
| No | 211530204 | ARMSTRONG AIR | 4SHP22LX160P-**A | EA(C;U)1P60C+TDR+TXV | A80UH1E100C20X | 38,000 | $1,900 |
| No | 211528981 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X60D+TDR | A97USMV135D20 | 37,600 | $1,880 |
| No | 211528980 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X60D+TDR | A80US2V135D20 | 37,400 | $1,870 |
| No | 211528979 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X60D+TDR | A96UH1E135D20 | 37,800 | $1,890 |
| No | 211530233 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X60D+TDR | A80UH1E135D20 | 37,800 | $1,890 |
| No | 211528978 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAC4X60D+TDR | A96US2V135D20 | 37,600 | $1,880 |
| No | 211530221 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAH1P60D+TDR+TXV | A97USMV135D20 | 36,400 | $1,820 |
| No | 211530220 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAH1P60D+TDR+TXV | A80US2V135D20 | 36,200 | $1,810 |
| No | 211530219 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAH1P60D+TDR+TXV | A96UH1E135D20 | 36,600 | $1,830 |
| No | 211530218 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAH1P60D+TDR+TXV | A80UH1E135D20 | 36,800 | $1,840 |
| No | 211530217 | ARMSTRONG AIR | 4SHP22LX160P-**A | EAH1P60D+TDR+TXV | A96US2V135D20 | 36,200 | $1,810 |
| No | 211528958 | ARMSTRONG AIR | 4SHP22LX160P-**A | ED1P50/60C+TDR+TXV | A80DS2V110C20 | 38,000 | $1,900 |
| No | 211528960 | ARMSTRONG AIR | 4SHP22LX160P-**A | ED1P50/60C+TDR+TXV | A97DSMV110C20 | 38,500 | $1,925 |
| No | 211528959 | ARMSTRONG AIR | 4SHP22LX160P-**A | ED1P50/60C+TDR+TXV | A97DSMV090C20 | 38,500 | $1,925 |
| No | 211528957 | ARMSTRONG AIR | 4SHP22LX160P-**A | ED1P50/60C+TDR+TXV | A96DF1E110C20 | 38,500 | $1,925 |
| No | 211528956 | ARMSTRONG AIR | 4SHP22LX160P-**A | ED1P50/60C+TDR+TXV | A80DF1E110C20 | 37,600 | $1,880 |
| No | 211528955 | ARMSTRONG AIR | 4SHP22LX160P-**A | ED1P50/60C+TDR+TXV | A96DS2V110C20 | 38,500 | $1,925 |
| No | 211528954 | ARMSTRONG AIR | 4SHP22LX160P-**A | ED1P50/60C+TDR+TXV | A96DF2E110C20 | 38,000 | $1,900 |
| No | 211528953 | ARMSTRONG AIR | 4SHP22LX160P-**A | ED1P50/60C+TDR+TXV | A96DS2V090C20 | 38,500 | $1,925 |
| No | 211528966 | ARMSTRONG AIR | 4SHP22LX160P-**A | ED1P60D+TDR+TXV | A80DS2V110C20 | 38,000 | $1,900 |
| No | 211528968 | ARMSTRONG AIR | 4SHP22LX160P-**A | ED1P60D+TDR+TXV | A97DSMV110C20 | 38,500 | $1,925 |
| No | 211528967 | ARMSTRONG AIR | 4SHP22LX160P-**A | ED1P60D+TDR+TXV | A97DSMV090C20 | 38,500 | $1,925 |
| No | 211528965 | ARMSTRONG AIR | 4SHP22LX160P-**A | ED1P60D+TDR+TXV | A96DF1E110C20 | 38,500 | $1,925 |
| No | 211528964 | ARMSTRONG AIR | 4SHP22LX160P-**A | ED1P60D+TDR+TXV | A80DF1E110C20 | 37,600 | $1,880 |
| No | 211528963 | ARMSTRONG AIR | 4SHP22LX160P-**A | ED1P60D+TDR+TXV | A96DS2V110C20 | 38,500 | $1,925 |
| No | 211528962 | ARMSTRONG AIR | 4SHP22LX160P-**A | ED1P60D+TDR+TXV | A96DF2E110C20 | 38,000 | $1,900 |
| No | 211528961 | ARMSTRONG AIR | 4SHP22LX160P-**A | ED1P60D+TDR+TXV | A96DS2V090C20 | 38,500 | $1,925 |
| No | 211530215 | ARMSTRONG AIR | 4SHP22LX160P-**A | BCE5C60M*4X | | 36,800 | $1,840 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211530216 | ARMSTRONG AIR | 4SHP22LX160P-**A | BCE5V60M*4X | | 37,200 | $1,860 |
| No | 211528982 | ARMSTRONG AIR | 4SHP22LX160P-**A | BCE7E60M*4X | | 37,000 | $1,850 |
| No | 211528371 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A97US2V080C16X | 22,600 | $1,130 |
| No | 211528370 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A80US2V110C20L | 22,400 | $1,120 |
| No | 211528369 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A80US2V110C20 | 22,400 | $1,120 |
| No | 211528368 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A80US2V100C20X | 22,400 | $1,120 |
| No | 211528367 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A80US2V090C20 | 22,400 | $1,120 |
| No | 211528366 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A80US2V080C20X | 22,400 | $1,120 |
| No | 211528365 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A96UH1E110C20 | 22,600 | $1,130 |
| No | 211528364 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A96UH1E090C16 | 22,400 | $1,120 |
| No | 211528363 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A93UH1E110C20 | 22,400 | $1,120 |
| No | 211528362 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A93UH1E110C16 | 22,200 | $1,110 |
| No | 211528361 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A93UH1E090C16 | 22,400 | $1,120 |
| No | 211528360 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A93UH1E090C12 | 22,400 | $1,120 |
| No | 211528359 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A80UH1E110C20 | 22,200 | $1,110 |
| No | 211528358 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A80UH1E090C20 | 22,200 | $1,110 |
| No | 211528357 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A96US2V110C20 | 22,400 | $1,120 |
| No | 211528356 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A96US2V110C16 | 22,600 | $1,130 |
| No | 211528355 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A96UH2E110C20 | 22,600 | $1,130 |
| No | 211528354 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A96US2V090C20 | 22,600 | $1,130 |
| No | 211528353 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A96US2V090C16 | 22,600 | $1,130 |
| No | 211528352 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A96US2V090C12 | 22,600 | $1,130 |
| No | 211528351 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A96UH2E090C16 | 22,200 | $1,110 |
| No | 211528350 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A80UH2E110C20 | 22,600 | $1,130 |
| No | 211528349 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A80UH2E110C16 | 22,000 | $1,100 |
| No | 211528348 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P42C+TDR+TXV | A80UH1E100C20X | 22,400 | $1,120 |
| No | 211528487 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48B+TDR | A97USMV070B12 | 22,600 | $1,130 |
| No | 211528486 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48B+TDR | A97US2V060B12X | 22,600 | $1,130 |
| No | 211528485 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48B+TDR | A97US2V040B12X | 22,600 | $1,130 |
| No | 211528484 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48B+TDR | A80US2V090B16L | 22,400 | $1,120 |
| No | 211528483 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48B+TDR | A80US2V090B16 | 22,400 | $1,120 |
| No | 211528482 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48B+TDR | A80US2V090B12 | 22,400 | $1,120 |
| No | 211528481 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48B+TDR | A80US2V080B16X | 22,600 | $1,130 |
| No | 211528480 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48B+TDR | A96UH1E070B12 | 22,200 | $1,110 |
| No | 211528479 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48B+TDR | A96UH1E045B12 | 21,800 | $1,090 |
| No | 211528478 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48B+TDR | A96UH1E030B12 | 22,200 | $1,110 |
| No | 211528477 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48B+TDR | A93UH1E070B12 | 22,200 | $1,110 |
| No | 211528476 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48B+TDR | A93UH1E045B12 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211528475 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48B+TDR | A93UH1E030B12 | 22,400 | $1,120 |
| No | 211528474 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48B+TDR | A80UH1E090B16 | 22,200 | $1,110 |
| No | 211528473 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48B+TDR | A80UH1E070B12 | 22,200 | $1,110 |
| No | 211528472 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48B+TDR | A96US2V070B12 | 22,600 | $1,130 |
| No | 211528471 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48B+TDR | A96UH2E070B12 | 22,200 | $1,110 |
| No | 211528470 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48B+TDR | A96US2V045B12 | 22,600 | $1,130 |
| No | 211528469 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48B+TDR | A96UH2E045B12 | 22,400 | $1,120 |
| No | 211528468 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48B+TDR | A80UH2E090B16 | 22,000 | $1,100 |
| No | 211528467 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48B+TDR | A80UH2E090B12 | 22,000 | $1,100 |
| No | 211528466 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X48B+TDR | A80UH1E080B16X | 22,600 | $1,130 |
| No | 211528291 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A97USMV070B12 | 22,600 | $1,130 |
| No | 211528290 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A97US2V060B12X | 22,600 | $1,130 |
| No | 211528289 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A97US2V040B12X | 22,600 | $1,130 |
| No | 211528288 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A80US2V090B16L | 22,400 | $1,120 |
| No | 211528287 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A80US2V090B16 | 22,400 | $1,120 |
| No | 211528286 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A80US2V090B12 | 22,400 | $1,120 |
| No | 211528285 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A80US2V080B16X | 22,600 | $1,130 |
| No | 211528284 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A96UH1E070B12 | 22,200 | $1,110 |
| No | 211528283 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A96UH1E045B12 | 21,800 | $1,090 |
| No | 211528282 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A96UH1E030B12 | 22,200 | $1,110 |
| No | 211528281 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A93UH1E070B12 | 22,200 | $1,110 |
| No | 211528280 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A93UH1E045B12 | 22,400 | $1,120 |
| No | 211528279 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A93UH1E030B12 | 22,400 | $1,120 |
| No | 211528278 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A80UH1E090B16 | 22,200 | $1,110 |
| No | 211528277 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A80UH1E070B12 | 22,200 | $1,110 |
| No | 211528276 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A96US2V070B12 | 22,600 | $1,130 |
| No | 211528275 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A96UH2E070B12 | 22,200 | $1,110 |
| No | 211528274 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A96US2V045B12 | 22,600 | $1,130 |
| No | 211528273 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A96UH2E045B12 | 22,400 | $1,120 |
| No | 211528272 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A80UH2E090B16 | 22,000 | $1,100 |
| No | 211528271 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A80UH2E090B12 | 22,000 | $1,100 |
| No | 211528270 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P48B+TDR+TXV | A80UH1E080B16X | 22,600 | $1,130 |
| No | 211530156 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30A+TDR+TXV | A80US2V070A12L | 23,200 | $1,160 |
| No | 211530155 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30A+TDR+TXV | A80US2V070A12 | 23,200 | $1,160 |
| No | 211528299 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30A+TDR+TXV | A80UH1E070A12 | 22,600 | $1,130 |
| No | 211528298 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30A+TDR+TXV | A80UH1E045A12 | 22,600 | $1,130 |
| No | 211530154 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30A+TDR+TXV | A80UH2E070A12 | 23,000 | $1,150 |
| No | 211528297 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30A+TDR+TXV | A80UH2E045A12 | 23,000 | $1,150 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211530153 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30A+TDR+TXV | A80UH1E060A12X | 22,600 | $1,130 |
| No | 211530152 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30A+TDR+TXV | A80UH1E040A12X | 22,600 | $1,130 |
| No | 211528396 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P30/36C+TDR+TXV | A97DSMV090C16 | 23,400 | $1,170 |
| No | 211528395 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P30/36C+TDR+TXV | A96DF1E110C20 | 23,000 | $1,150 |
| No | 211528394 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P30/36C+TDR+TXV | A96DF1E090C16 | 22,800 | $1,140 |
| No | 211528393 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P30/36C+TDR+TXV | A93DF1E090C16 | 22,800 | $1,140 |
| No | 211528392 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P30/36C+TDR+TXV | A80DF1E110C20 | 22,800 | $1,140 |
| No | 211528391 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P30/36C+TDR+TXV | A96DF2E110C20 | 23,000 | $1,150 |
| No | 211528390 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P30/36C+TDR+TXV | A96DF2E090C16 | 22,800 | $1,140 |
| No | 211528389 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P30/36B+TDR+TXV | A97DSMV070B12 | 23,200 | $1,160 |
| No | 211528388 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P30/36B+TDR+TXV | A80DS2V090B16 | 23,200 | $1,160 |
| No | 211528387 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P30/36B+TDR+TXV | A96DF1E070B16 | 23,200 | $1,160 |
| No | 211528386 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P30/36B+TDR+TXV | A96DF1E045B12 | 22,800 | $1,140 |
| No | 211528385 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P30/36B+TDR+TXV | A93DF1E070B12 | 23,000 | $1,150 |
| No | 211528384 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P30/36B+TDR+TXV | A93DF1E045B12 | 23,000 | $1,150 |
| No | 211528383 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P30/36B+TDR+TXV | A80DF1E090B16 | 22,800 | $1,140 |
| No | 211528382 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P30/36B+TDR+TXV | A80DF1E070B12 | 22,600 | $1,130 |
| No | 211528381 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P30/36B+TDR+TXV | A96DS2V070B16 | 23,400 | $1,170 |
| No | 211528380 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P30/36B+TDR+TXV | A96DF2E070B16 | 23,000 | $1,150 |
| No | 211528379 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P30/36B+TDR+TXV | A96DS2V045B12 | 23,400 | $1,170 |
| No | 211528378 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P30/36A+TDR+TXV | A80DS2V070A12 | 23,400 | $1,170 |
| No | 211528377 | ARMSTRONG AIR | 4SHP22LX136P-**A | ED1P30/36A+TDR+TXV | A80DF1E070A12 | 22,800 | $1,140 |
| No | 211528465 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36B+TDR | A97USMV070B12 | 22,000 | $1,100 |
| No | 211528464 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36B+TDR | A97US2V060B12X | 22,200 | $1,110 |
| No | 211528463 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36B+TDR | A97US2V040B12X | 22,000 | $1,100 |
| No | 211528462 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36B+TDR | A80US2V090B16L | 22,000 | $1,100 |
| No | 211528461 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36B+TDR | A80US2V090B16 | 22,000 | $1,100 |
| No | 211528460 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36B+TDR | A80US2V090B12 | 22,000 | $1,100 |
| No | 211528459 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36B+TDR | A80US2V080B16X | 22,000 | $1,100 |
| No | 211528458 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36B+TDR | A96UH1E070B12 | 21,600 | $1,080 |
| No | 211528457 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36B+TDR | A96UH1E030B12 | 21,600 | $1,080 |
| No | 211528456 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36B+TDR | A93UH1E070B12 | 21,800 | $1,090 |
| No | 211528455 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36B+TDR | A93UH1E045B12 | 21,800 | $1,090 |
| No | 211528454 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36B+TDR | A93UH1E030B12 | 21,800 | $1,090 |
| No | 211528453 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36B+TDR | A80UH1E090B16 | 21,600 | $1,080 |
| No | 211528452 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36B+TDR | A80UH1E070B12 | 21,600 | $1,080 |
| No | 211528451 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36B+TDR | A96US2V070B12 | 22,000 | $1,100 |
| No | 211528450 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36B+TDR | A96UH2E070B12 | 21,600 | $1,080 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211528449 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36B+TDR | A96US2V045B12 | 22,200 | $1,110 |
| No | 211528448 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36B+TDR | A96UH2E045B12 | 21,800 | $1,090 |
| No | 211528447 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36B+TDR | A80UH2E090B16 | 21,400 | $1,070 |
| No | 211528446 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36B+TDR | A80UH2E090B12 | 21,800 | $1,090 |
| No | 211528445 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36B+TDR | A80UH1E080B16X | 22,000 | $1,100 |
| No | 211528269 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A97USMV070B12 | 22,000 | $1,100 |
| No | 211528268 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A97US2V060B12X | 22,200 | $1,110 |
| No | 211528267 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A97US2V040B12X | 22,000 | $1,100 |
| No | 211528266 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A80US2V090B16L | 22,000 | $1,100 |
| No | 211528265 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A80US2V090B16 | 22,000 | $1,100 |
| No | 211528264 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A80US2V090B12 | 22,000 | $1,100 |
| No | 211528263 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A80US2V080B16X | 22,000 | $1,100 |
| No | 211528262 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A96UH1E070B12 | 21,600 | $1,080 |
| No | 211528261 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A96UH1E030B12 | 21,600 | $1,080 |
| No | 211528260 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A93UH1E070B12 | 21,800 | $1,090 |
| No | 211528259 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A93UH1E045B12 | 21,800 | $1,090 |
| No | 211528258 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A93UH1E030B12 | 21,800 | $1,090 |
| No | 211528257 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A80UH1E090B16 | 21,600 | $1,080 |
| No | 211528256 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A80UH1E070B12 | 21,600 | $1,080 |
| No | 211528255 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A96US2V070B12 | 22,000 | $1,100 |
| No | 211528254 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A96UH2E070B12 | 21,600 | $1,080 |
| No | 211528253 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A96US2V045B12 | 22,200 | $1,110 |
| No | 211528252 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A96UH2E045B12 | 21,800 | $1,090 |
| No | 211528251 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A80UH2E090B16 | 21,400 | $1,070 |
| No | 211528250 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A80UH2E090B12 | 21,800 | $1,090 |
| No | 211528249 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36B+TDR+TXV | A80UH1E080B16X | 22,000 | $1,100 |
| No | 211528444 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36A+TDR | A80US2V070A12L | 22,200 | $1,110 |
| No | 211528443 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36A+TDR | A80US2V070A12 | 22,200 | $1,110 |
| No | 211528442 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36A+TDR | A80UH1E070A12 | 21,600 | $1,080 |
| No | 211528441 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36A+TDR | A80UH1E045A12 | 21,600 | $1,080 |
| No | 211528440 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36A+TDR | A80UH2E070A12 | 21,800 | $1,090 |
| No | 211528439 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36A+TDR | A80UH2E045A12 | 21,800 | $1,090 |
| No | 211528438 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36A+TDR | A80UH1E060A12X | 21,600 | $1,080 |
| No | 211528437 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X36A+TDR | A80UH1E040A12X | 21,600 | $1,080 |
| No | 211528248 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36A+TDR+TXV | A80US2V070A12L | 22,200 | $1,110 |
| No | 211528247 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36A+TDR+TXV | A80US2V070A12 | 22,200 | $1,110 |
| No | 211528246 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36A+TDR+TXV | A80UH1E070A12 | 21,600 | $1,080 |
| No | 211528245 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36A+TDR+TXV | A80UH1E045A12 | 21,600 | $1,080 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211528244 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36A+TDR+TXV | A80UH2E070A12 | 21,800 | $1,090 |
| No | 211528243 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36A+TDR+TXV | A80UH2E045A12 | 21,800 | $1,090 |
| No | 211528242 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36A+TDR+TXV | A80UH1E060A12X | 21,600 | $1,080 |
| No | 211528241 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P36A+TDR+TXV | A80UH1E040A12X | 21,600 | $1,080 |
| No | 211528347 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A97USMV110C20 | 22,800 | $1,140 |
| No | 211528346 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A97USMV090C20 | 22,800 | $1,140 |
| No | 211528345 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A97USMV090C16 | 23,000 | $1,150 |
| No | 211528344 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A97USMV090C12 | 23,000 | $1,150 |
| No | 211528343 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A97US2V080C20X | 23,000 | $1,150 |
| No | 211528342 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A97US2V080C16X | 22,800 | $1,140 |
| No | 211528341 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A80US2V110C20L | 22,800 | $1,140 |
| No | 211528340 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A80US2V110C20 | 22,800 | $1,140 |
| No | 211528339 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A80US2V100C20X | 22,800 | $1,140 |
| No | 211528338 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A80US2V090C20 | 22,800 | $1,140 |
| No | 211528337 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A80US2V080C20X | 22,800 | $1,140 |
| No | 211528336 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A96UH1E110C20 | 22,800 | $1,140 |
| No | 211528335 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A96UH1E090C16 | 22,800 | $1,140 |
| No | 211528334 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A93UH1E110C20 | 22,800 | $1,140 |
| No | 211528333 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A93UH1E110C16 | 22,600 | $1,130 |
| No | 211528332 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A93UH1E090C16 | 22,600 | $1,130 |
| No | 211528331 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A93UH1E090C12 | 22,800 | $1,140 |
| No | 211528330 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A80UH1E110C20 | 22,600 | $1,130 |
| No | 211528329 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A80UH1E090C20 | 22,600 | $1,130 |
| No | 211528328 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A96US2V110C20 | 22,800 | $1,140 |
| No | 211528327 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A96US2V110C16 | 23,000 | $1,150 |
| No | 211528326 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A96UH2E110C20 | 22,800 | $1,140 |
| No | 211528325 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A96US2V090C20 | 22,800 | $1,140 |
| No | 211528324 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A96US2V090C16 | 23,000 | $1,150 |
| No | 211528323 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A96US2V090C12 | 23,000 | $1,150 |
| No | 211528322 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A96UH2E090C16 | 22,600 | $1,130 |
| No | 211528321 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A80UH2E110C20 | 22,800 | $1,140 |
| No | 211528320 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A80UH2E110C16 | 22,400 | $1,120 |
| No | 211528319 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P36C+TDR+TXV | A80UH1E100C20X | 22,800 | $1,140 |
| No | 211528318 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A97USMV070B12 | 23,000 | $1,150 |
| No | 211528317 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A97US2V060B12X | 23,000 | $1,150 |
| No | 211528316 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A97US2V040B12X | 23,000 | $1,150 |
| No | 211528315 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A80US2V090B16L | 22,600 | $1,130 |
| No | 211528314 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A80US2V090B16 | 22,600 | $1,130 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211528313 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A80US2V090B12 | 22,800 | $1,140 |
| No | 211528312 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A80US2V080B16X | 22,800 | $1,140 |
| No | 211528311 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A96UH1E070B12 | 22,400 | $1,120 |
| No | 211528310 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A96UH1E030B12 | 22,400 | $1,120 |
| No | 211528309 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A93UH1E070B12 | 22,600 | $1,130 |
| No | 211528308 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A93UH1E045B12 | 22,600 | $1,130 |
| No | 211530158 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A93UH1E030B12 | 22,600 | $1,130 |
| No | 211528307 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A80UH1E090B16 | 22,200 | $1,110 |
| No | 211528306 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A80UH1E070B12 | 22,400 | $1,120 |
| No | 211528305 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A96US2V070B12 | 23,000 | $1,150 |
| No | 211528304 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A96UH2E070B12 | 22,400 | $1,120 |
| No | 211530157 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A96US2V045B12 | 23,000 | $1,150 |
| No | 211528303 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A96UH2E045B12 | 22,600 | $1,130 |
| No | 211528302 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A80UH2E090B16 | 22,600 | $1,130 |
| No | 211528301 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A80UH2E090B12 | 22,600 | $1,130 |
| No | 211528300 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAH1P30B+TDR+TXV | A80UH1E080B16X | 22,800 | $1,140 |
| No | 211528436 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30B+TDR | A97USMV070B12 | 22,000 | $1,100 |
| No | 211528435 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30B+TDR | A97US2V060B12X | 22,200 | $1,110 |
| No | 211528434 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30B+TDR | A97US2V040B12X | 22,000 | $1,100 |
| No | 211528433 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30B+TDR | A80US2V090B16L | 21,800 | $1,090 |
| No | 211528432 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30B+TDR | A80US2V090B16 | 21,800 | $1,090 |
| No | 211528431 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30B+TDR | A80US2V090B12 | 21,800 | $1,090 |
| No | 211528430 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30B+TDR | A80US2V080B16X | 22,000 | $1,100 |
| No | 211528429 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30B+TDR | A96UH1E070B12 | 21,600 | $1,080 |
| No | 211528428 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30B+TDR | A96UH1E030B12 | 21,800 | $1,090 |
| No | 211528427 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30B+TDR | A93UH1E070B12 | 21,800 | $1,090 |
| No | 211528426 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30B+TDR | A93UH1E045B12 | 21,800 | $1,090 |
| No | 211528425 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30B+TDR | A93UH1E030B12 | 21,800 | $1,090 |
| No | 211528424 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30B+TDR | A80UH1E090B16 | 21,600 | $1,080 |
| No | 211528423 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30B+TDR | A80UH1E070B12 | 21,600 | $1,080 |
| No | 211528422 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30B+TDR | A96US2V070B12 | 22,000 | $1,100 |
| No | 211528421 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30B+TDR | A96UH2E070B12 | 21,600 | $1,080 |
| No | 211528420 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30B+TDR | A96US2V045B12 | 22,200 | $1,110 |
| No | 211528419 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30B+TDR | A96UH2E045B12 | 21,600 | $1,080 |
| No | 211528418 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30B+TDR | A80UH2E090B16 | 21,600 | $1,080 |
| No | 211528417 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30B+TDR | A80UH2E090B12 | 21,800 | $1,090 |
| No | 211528416 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30B+TDR | A80UH1E080B16X | 21,600 | $1,080 |
| No | 211528240 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A97USMV070B12 | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211528239 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A97US2V060B12X | 22,200 | $1,110 |
| No | 211528238 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A97US2V040B12X | 22,000 | $1,100 |
| No | 211528237 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A80US2V090B16L | 21,800 | $1,090 |
| No | 211528236 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A80US2V090B16 | 21,800 | $1,090 |
| No | 211528235 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A80US2V090B12 | 21,800 | $1,090 |
| No | 211528234 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A80US2V080B16X | 22,000 | $1,100 |
| No | 211528233 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A96UH1E070B12 | 21,600 | $1,080 |
| No | 211528232 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A96UH1E030B12 | 21,800 | $1,090 |
| No | 211528231 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A93UH1E070B12 | 21,800 | $1,090 |
| No | 211528230 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A93UH1E045B12 | 21,800 | $1,090 |
| No | 211528229 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A93UH1E030B12 | 21,800 | $1,090 |
| No | 211528228 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A80UH1E090B16 | 21,600 | $1,080 |
| No | 211528227 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A80UH1E070B12 | 21,600 | $1,080 |
| No | 211528226 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A96US2V070B12 | 22,000 | $1,100 |
| No | 211528225 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A96UH2E070B12 | 21,600 | $1,080 |
| No | 211528224 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A96US2V045B12 | 22,200 | $1,110 |
| No | 211528223 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A96UH2E045B12 | 21,600 | $1,080 |
| No | 211528222 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A80UH2E090B16 | 21,600 | $1,080 |
| No | 211528221 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A80UH2E090B12 | 21,800 | $1,090 |
| No | 211528220 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30B+TDR+TXV | A80UH1E080B16X | 21,600 | $1,080 |
| No | 211528415 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30A+TDR | A80US2V070A12L | 22,000 | $1,100 |
| No | 211528414 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30A+TDR | A80US2V070A12 | 22,000 | $1,100 |
| No | 211528413 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30A+TDR | A80UH1E070A12 | 21,600 | $1,080 |
| No | 211528412 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30A+TDR | A80UH1E045A12 | 21,400 | $1,070 |
| No | 211528411 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30A+TDR | A80UH2E070A12 | 21,800 | $1,090 |
| No | 211528410 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30A+TDR | A80UH2E045A12 | 21,800 | $1,090 |
| No | 211528409 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30A+TDR | A80UH1E060A12X | 21,600 | $1,080 |
| No | 211528408 | ARMSTRONG AIR | 4SHP22LX136P-**A | EAC4X30A+TDR | A80UH1E040A12X | 21,600 | $1,080 |
| No | 211528219 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30A+TDR+TXV | A80US2V070A12L | 22,000 | $1,100 |
| No | 211528218 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30A+TDR+TXV | A80US2V070A12 | 22,000 | $1,100 |
| No | 211528217 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30A+TDR+TXV | A80UH1E070A12 | 21,600 | $1,080 |
| No | 211528216 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30A+TDR+TXV | A80UH1E045A12 | 21,400 | $1,070 |
| No | 211528215 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30A+TDR+TXV | A80UH2E070A12 | 21,800 | $1,090 |
| No | 211528214 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30A+TDR+TXV | A80UH2E045A12 | 21,800 | $1,090 |
| No | 211528213 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30A+TDR+TXV | A80UH1E060A12X | 21,600 | $1,080 |
| No | 211528212 | ARMSTRONG AIR | 4SHP22LX136P-**A | EA(C;U)1P30A+TDR+TXV | A80UH1E040A12X | 21,600 | $1,080 |
| No | 211528293 | ARMSTRONG AIR | 4SHP22LX136P-**A | BCE5V42M*4X | | 22,200 | $1,110 |
| No | 211528292 | ARMSTRONG AIR | 4SHP22LX136P-**A | BCE5V36M*4X | | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211528295 | ARMSTRONG AIR | 4SHP22LX136P-**A | BCE7E42M*4X | | 22,200 | $1,110 |
| No | 211528296 | ARMSTRONG AIR | 4SHP22LX136P-**A | BCE7S42M*4X | | 22,800 | $1,140 |
| No | 211528294 | ARMSTRONG AIR | 4SHP22LX136P-**A | BCE7E36M*4X | | 23,000 | $1,150 |
| No | 211528853 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAC4X60C+TDR | A97USMV110C20 | 28,800 | $1,440 |
| No | 211528852 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAC4X60C+TDR | A97USMV090C20 | 28,800 | $1,440 |
| No | 211528851 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAC4X60C+TDR | A97USMV090C16 | 29,000 | $1,450 |
| No | 211528850 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAC4X60C+TDR | A97US2V080C20X | 29,000 | $1,450 |
| No | 211528849 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAC4X60C+TDR | A97US2V080C16X | 29,000 | $1,450 |
| No | 211528848 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAC4X60C+TDR | A80US2V110C20L | 28,600 | $1,430 |
| No | 211528847 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAC4X60C+TDR | A80US2V110C20 | 28,600 | $1,430 |
| No | 211528846 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAC4X60C+TDR | A80US2V100C20X | 28,800 | $1,440 |
| No | 211528845 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAC4X60C+TDR | A80US2V090C20 | 28,400 | $1,420 |
| No | 211528844 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAC4X60C+TDR | A80US2V080C20X | 28,800 | $1,440 |
| No | 211528843 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAC4X60C+TDR | A96UH1E110C20 | 28,800 | $1,440 |
| No | 211528842 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAC4X60C+TDR | A93UH1E110C20 | 28,600 | $1,430 |
| No | 211528841 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAC4X60C+TDR | A80UH1E110C20 | 28,600 | $1,430 |
| No | 211528840 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAC4X60C+TDR | A80UH1E090C20 | 28,600 | $1,430 |
| No | 211528839 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAC4X60C+TDR | A96US2V110C20 | 28,800 | $1,440 |
| No | 211528838 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAC4X60C+TDR | A96US2V110C16 | 29,000 | $1,450 |
| No | 211528837 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAC4X60C+TDR | A96UH2E110C20 | 28,800 | $1,440 |
| No | 211528836 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAC4X60C+TDR | A96US2V090C20 | 29,000 | $1,450 |
| No | 211528835 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAC4X60C+TDR | A96US2V090C16 | 29,000 | $1,450 |
| No | 211528834 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAC4X60C+TDR | A80UH2E110C20 | 28,800 | $1,440 |
| No | 211528833 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAC4X60C+TDR | A80UH2E110C16 | 28,400 | $1,420 |
| No | 211528832 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAC4X60C+TDR | A80UH1E100C20X | 28,800 | $1,440 |
| No | 211528785 | ARMSTRONG AIR | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A97USMV110C20 | 28,800 | $1,440 |
| No | 211528784 | ARMSTRONG AIR | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A97USMV090C20 | 28,800 | $1,440 |
| No | 211528783 | ARMSTRONG AIR | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A97USMV090C16 | 29,000 | $1,450 |
| No | 211528782 | ARMSTRONG AIR | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A97US2V080C20X | 29,000 | $1,450 |
| No | 211528781 | ARMSTRONG AIR | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A97US2V080C16X | 29,000 | $1,450 |
| No | 211528780 | ARMSTRONG AIR | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A80US2V110C20L | 28,600 | $1,430 |
| No | 211528779 | ARMSTRONG AIR | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A80US2V110C20 | 28,600 | $1,430 |
| No | 211528778 | ARMSTRONG AIR | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A80US2V100C20X | 28,800 | $1,440 |
| No | 211528777 | ARMSTRONG AIR | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A80US2V090C20 | 28,400 | $1,420 |
| No | 211528776 | ARMSTRONG AIR | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A80US2V080C20X | 28,800 | $1,440 |
| No | 211528775 | ARMSTRONG AIR | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A96UH1E110C20 | 28,800 | $1,440 |
| No | 211528774 | ARMSTRONG AIR | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A93UH1E110C20 | 28,600 | $1,430 |
| No | 211528773 | ARMSTRONG AIR | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A80UH1E110C20 | 28,600 | $1,430 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211528772 | ARMSTRONG AIR | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A80UH1E090C20 | 28,600 | $1,430 |
| No | 211528771 | ARMSTRONG AIR | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A96US2V110C20 | 28,800 | $1,440 |
| No | 211528770 | ARMSTRONG AIR | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A96US2V110C16 | 29,000 | $1,450 |
| No | 211528769 | ARMSTRONG AIR | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A96UH2E110C20 | 28,800 | $1,440 |
| No | 211528768 | ARMSTRONG AIR | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A96US2V090C20 | 29,000 | $1,450 |
| No | 211528767 | ARMSTRONG AIR | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A96US2V090C16 | 29,000 | $1,450 |
| No | 211528766 | ARMSTRONG AIR | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A80UH2E110C20 | 28,800 | $1,440 |
| No | 211528765 | ARMSTRONG AIR | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A80UH2E110C16 | 28,400 | $1,420 |
| No | 211528764 | ARMSTRONG AIR | 4SHP22LX148P-**A | EA(C;U)1P60C+TDR+TXV | A80UH1E100C20X | 28,800 | $1,440 |
| No | 211528831 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A97USMV110C20 | 28,200 | $1,410 |
| No | 211528830 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A97USMV090C20 | 28,200 | $1,410 |
| No | 211528829 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A97USMV090C16 | 28,400 | $1,420 |
| No | 211528828 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A97US2V080C20X | 28,400 | $1,420 |
| No | 211528827 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A97US2V080C16X | 28,400 | $1,420 |
| No | 211528826 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A80US2V110C20L | 28,200 | $1,410 |
| No | 211528825 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A80US2V110C20 | 28,200 | $1,410 |
| No | 211528824 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A80US2V100C20X | 28,200 | $1,410 |
| No | 211528823 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A80US2V090C20 | 27,800 | $1,390 |
| No | 211528822 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A80US2V080C20X | 28,200 | $1,410 |
| No | 211528821 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A96UH1E110C20 | 28,200 | $1,410 |
| No | 211528820 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A93UH1E110C20 | 28,000 | $1,400 |
| No | 211528819 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A80UH1E110C20 | 28,000 | $1,400 |
| No | 211528818 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A80UH1E090C20 | 28,000 | $1,400 |
| No | 211528817 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A96US2V110C20 | 28,200 | $1,410 |
| No | 211528816 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A96US2V110C16 | 28,400 | $1,420 |
| No | 211528815 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A96UH2E110C20 | 28,200 | $1,410 |
| No | 211528814 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A96US2V090C20 | 28,400 | $1,420 |
| No | 211528813 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A96US2V090C16 | 28,400 | $1,420 |
| No | 211528812 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A80UH2E110C20 | 28,000 | $1,400 |
| No | 211528811 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A80UH2E110C16 | 27,800 | $1,390 |
| No | 211528810 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P51C+TDR+TXV | A80UH1E100C20X | 28,200 | $1,410 |
| No | 211528809 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A97USMV110C20 | 28,400 | $1,420 |
| No | 211528808 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A97USMV090C20 | 28,400 | $1,420 |
| No | 211528807 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A97USMV090C16 | 28,600 | $1,430 |
| No | 211528806 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A97US2V080C20X | 28,400 | $1,420 |
| No | 211528805 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A97US2V080C16X | 28,400 | $1,420 |
| No | 211528804 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A80US2V110C20L | 28,200 | $1,410 |
| No | 211528803 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A80US2V110C20 | 28,200 | $1,410 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211528802 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A80US2V100C20X | 28,400 | $1,420 |
| No | 211528801 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A80US2V090C20 | 28,000 | $1,400 |
| No | 211528800 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A80US2V080C20X | 28,200 | $1,410 |
| No | 211528799 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A96UH1E110C20 | 28,200 | $1,410 |
| No | 211528798 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A93UH1E110C20 | 28,000 | $1,400 |
| No | 211530175 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A93UH1E110C16 | 27,800 | $1,390 |
| No | 211530174 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A93UH1E090C16 | 28,000 | $1,400 |
| No | 211528797 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A80UH1E110C20 | 28,000 | $1,400 |
| No | 211528796 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A80UH1E090C20 | 28,000 | $1,400 |
| No | 211528795 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A96US2V110C20 | 28,400 | $1,420 |
| No | 211528794 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A96US2V110C16 | 28,600 | $1,430 |
| No | 211528793 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A96UH2E110C20 | 28,200 | $1,410 |
| No | 211528792 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A96US2V090C20 | 28,400 | $1,420 |
| No | 211528791 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A96US2V090C16 | 28,600 | $1,430 |
| No | 211528790 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A80UH2E110C20 | 28,200 | $1,410 |
| No | 211528789 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A80UH2E110C16 | 27,800 | $1,390 |
| No | 211530173 | ARMSTRONG AIR | 4SHP22LX148P-**A | EAH1P48C+TDR+TXV | A80UH1E100C20X | 28,400 | $1,420 |
| No | 211530167 | ARMSTRONG AIR | 4SHP22LX148P-**A | BCE5C60M*4X | | 28,200 | $1,410 |
| No | 211530169 | ARMSTRONG AIR | 4SHP22LX148P-**A | BCE5V60M*4X | | 28,000 | $1,400 |
| No | 211530168 | ARMSTRONG AIR | 4SHP22LX148P-**A | BCE5V48M*4X | | 28,600 | $1,430 |
| No | 211528786 | ARMSTRONG AIR | 4SHP22LX148P-**A | BCE7E48M*4X | | 27,800 | $1,390 |
| No | 211528788 | ARMSTRONG AIR | 4SHP22LX148P-**A | BCE7S48M*4X | | 28,400 | $1,420 |
| No | 211528787 | ARMSTRONG AIR | 4SHP22LX148P-**A | BCE7E60M*4X | | 27,000 | $1,350 |
| No | 210727715 | ARMSTRONG AIR | 4SHP18LX160P | BCE7E48M*4X | | 32,200 | $1,610 |
| No | 210727772 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X49C+TDR | A97USMV110C20 | 30,800 | $1,540 |
| No | 210727771 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X49C+TDR | A97USMV090C20 | 30,800 | $1,540 |
| No | 210727770 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X49C+TDR | A97USMV090C16 | 30,800 | $1,540 |
| No | 210727769 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X49C+TDR | A97US2V080C20X | 30,600 | $1,530 |
| No | 210727768 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X49C+TDR | A97US2V080C16X | 30,600 | $1,530 |
| No | 210727760 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X49C+TDR | A80US2V110C20L | 30,600 | $1,530 |
| No | 210727758 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X49C+TDR | A80US2V100C20X | 30,200 | $1,510 |
| No | 210727757 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X49C+TDR | A80US2V080C20X | 30,400 | $1,520 |
| No | 210727766 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X49C+TDR | A96US2V110C16 | 30,600 | $1,530 |
| No | 210727764 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X49C+TDR | A96US2V090C16 | 30,800 | $1,540 |
| No | 210727767 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X49C+TDR | A96US2V110C20 | 30,800 | $1,540 |
| No | 210727763 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X49C+TDR | A96UH2E110C20 | 30,600 | $1,530 |
| No | 210727765 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X49C+TDR | A96US2V090C20 | 30,800 | $1,540 |
| No | 210727762 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X49C+TDR | A96UH1E110C20 | 30,600 | $1,530 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210727761 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X49C+TDR | A93UH1E110C20 | 30,400 | $1,520 |
| No | 210727759 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X49C+TDR | A80US2V110C20 | 30,600 | $1,530 |
| No | 210727756 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X49C+TDR | A80UH2E110C20 | 30,400 | $1,520 |
| No | 210727755 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X49C+TDR | A80UH1E110C20 | 30,400 | $1,520 |
| No | 210727754 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X49C+TDR | A80UH1E100C20X | 30,600 | $1,530 |
| No | 210727753 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X49C+TDR | A80UH1E090C20 | 30,200 | $1,510 |
| No | 210727744 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A97USMV110C20 | 30,800 | $1,540 |
| No | 210727743 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A97USMV090C20 | 30,800 | $1,540 |
| No | 210727742 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A97USMV090C16 | 30,800 | $1,540 |
| No | 210727741 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A97US2V080C20X | 30,600 | $1,530 |
| No | 210727740 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A97US2V080C16X | 30,600 | $1,530 |
| No | 210727732 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A80US2V110C20L | 30,600 | $1,530 |
| No | 210727730 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A80US2V100C20X | 30,200 | $1,510 |
| No | 210727729 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A80US2V080C20X | 30,400 | $1,520 |
| No | 210727738 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A96US2V110C16 | 30,600 | $1,530 |
| No | 210727736 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A96US2V090C16 | 30,800 | $1,540 |
| No | 210727739 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A96US2V110C20 | 30,800 | $1,540 |
| No | 210727735 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A96UH2E110C20 | 30,600 | $1,530 |
| No | 210727737 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A96US2V090C20 | 30,800 | $1,540 |
| No | 210727734 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A96UH1E110C20 | 30,600 | $1,530 |
| No | 210727733 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A93UH1E110C20 | 30,400 | $1,520 |
| No | 210727731 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A80US2V110C20 | 30,600 | $1,530 |
| No | 210727728 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A80UH2E110C20 | 30,400 | $1,520 |
| No | 210727727 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A80UH1E110C20 | 30,400 | $1,520 |
| No | 210727726 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A80UH1E100C20X | 30,600 | $1,530 |
| No | 210727725 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P49C+TDR+TXV | A80UH1E090C20 | 30,200 | $1,510 |
| No | 210727792 | ARMSTRONG AIR | 4SHP18LX160P | EAH1P48C+TDR+TXV | A97USMV110C20 | 31,400 | $1,570 |
| No | 210727791 | ARMSTRONG AIR | 4SHP18LX160P | EAH1P48C+TDR+TXV | A97USMV090C20 | 31,400 | $1,570 |
| No | 210727790 | ARMSTRONG AIR | 4SHP18LX160P | EAH1P48C+TDR+TXV | A97USMV090C16 | 31,400 | $1,570 |
| No | 210727789 | ARMSTRONG AIR | 4SHP18LX160P | EAH1P48C+TDR+TXV | A97US2V080C20X | 31,200 | $1,560 |
| No | 210727788 | ARMSTRONG AIR | 4SHP18LX160P | EAH1P48C+TDR+TXV | A97US2V080C16X | 31,200 | $1,560 |
| No | 210727780 | ARMSTRONG AIR | 4SHP18LX160P | EAH1P48C+TDR+TXV | A80US2V110C20L | 31,200 | $1,560 |
| No | 210727786 | ARMSTRONG AIR | 4SHP18LX160P | EAH1P48C+TDR+TXV | A96US2V110C16 | 31,400 | $1,570 |
| No | 210727784 | ARMSTRONG AIR | 4SHP18LX160P | EAH1P48C+TDR+TXV | A96US2V090C16 | 31,400 | $1,570 |
| No | 210727787 | ARMSTRONG AIR | 4SHP18LX160P | EAH1P48C+TDR+TXV | A96US2V110C20 | 31,400 | $1,570 |
| No | 210727785 | ARMSTRONG AIR | 4SHP18LX160P | EAH1P48C+TDR+TXV | A96US2V090C20 | 31,400 | $1,570 |
| No | 210727779 | ARMSTRONG AIR | 4SHP18LX160P | EAH1P48C+TDR+TXV | A80US2V110C20 | 31,200 | $1,560 |
| No | 210727778 | ARMSTRONG AIR | 4SHP18LX160P | EAH1P48C+TDR+TXV | A80UH2E110C20 | 31,000 | $1,550 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210727714 | ARMSTRONG AIR | 4SHP18LX160P | BCE5V48M | | 31,400 | $1,570 |
| No | 210727713 | ARMSTRONG AIR | 4SHP18LX160P | BCE5E48M*4X | | 31,600 | $1,580 |
| No | 210727712 | ARMSTRONG AIR | 4SHP18LX160P | BCE5C48M*4X | | 31,600 | $1,580 |
| No | 210727711 | ARMSTRONG AIR | 4SHP18LX160P | BCE5C48M*1P+TXV | | 31,600 | $1,580 |
| No | 210727716 | ARMSTRONG AIR | 4SHP18LX160P | BCE7S48 | | 32,800 | $1,640 |
| No | 210727570 | ARMSTRONG AIR | 4SHP18LX160P | ED1P60D+TDR+TXV | A97DSMV110C20 | 38,500 | $1,925 |
| No | 210727569 | ARMSTRONG AIR | 4SHP18LX160P | ED1P60D+TDR+TXV | A97DSMV090C20 | 38,500 | $1,925 |
| No | 210727565 | ARMSTRONG AIR | 4SHP18LX160P | ED1P60D+TDR+TXV | A80DF1E110C20 | 38,000 | $1,900 |
| No | 210727568 | ARMSTRONG AIR | 4SHP18LX160P | ED1P60D+TDR+TXV | A96DS2V110C20 | 38,500 | $1,925 |
| No | 210727567 | ARMSTRONG AIR | 4SHP18LX160P | ED1P60D+TDR+TXV | A96DS2V090C20 | 38,500 | $1,925 |
| No | 210727547 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X60D+TDR | EFV20DCA | 39,000 | $1,950 |
| No | 210727546 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X60D+TDR | A97USMV135D20 | 39,000 | $1,950 |
| No | 210727545 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X60D+TDR | A96US2V135D20 | 39,000 | $1,950 |
| No | 210727544 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X60D+TDR | A80US2V135D20* | 39,000 | $1,950 |
| No | 210727543 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X60D+TDR | A80UH1E135D20 | 39,000 | $1,950 |
| No | 210727529 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P60D+TDR+TXV | EFV20DCA | 39,000 | $1,950 |
| No | 210727528 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P60D+TDR+TXV | A97USMV135D20 | 39,000 | $1,950 |
| No | 210727527 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P60D+TDR+TXV | A96US2V135D20 | 39,000 | $1,950 |
| No | 210727526 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P60D+TDR+TXV | A80US2V135D20* | 39,000 | $1,950 |
| No | 210727525 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P60D+TDR+TXV | A80UH1E135D20 | 39,000 | $1,950 |
| No | 210727542 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X60C+TDR | A97USMV110C20 | 38,000 | $1,900 |
| No | 210727541 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X60C+TDR | A97USMV090C20 | 38,000 | $1,900 |
| No | 210727540 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X60C+TDR | A97US2V080C20X | 38,000 | $1,900 |
| No | 210727539 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X60C+TDR | A96US2V110C20 | 38,000 | $1,900 |
| No | 210727538 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X60C+TDR | A96US2V090C20 | 38,000 | $1,900 |
| No | 210727537 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X60C+TDR | A96UH2E110C20 | 37,800 | $1,890 |
| No | 210727536 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X60C+TDR | A93UH1E110C20 | 37,800 | $1,890 |
| No | 210727535 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X60C+TDR | A80US2V110C20L | 38,000 | $1,900 |
| No | 210727534 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X60C+TDR | A80US2V110C20* | 38,000 | $1,900 |
| No | 210727533 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X60C+TDR | A80US2V100C20X | 37,600 | $1,880 |
| No | 210727532 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X60C+TDR | A80US2V090C20* | 37,800 | $1,890 |
| No | 210727531 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X60C+TDR | A80US2V080C20X | 37,600 | $1,880 |
| No | 210727530 | ARMSTRONG AIR | 4SHP18LX160P | EAC4X60C+TDR | A80UH2E110C20 | 38,000 | $1,900 |
| No | 210727524 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P60C+TDR+TXV | A97USMV110C20 | 38,000 | $1,900 |
| No | 210727523 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P60C+TDR+TXV | A97USMV090C20 | 38,000 | $1,900 |
| No | 210727522 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P60C+TDR+TXV | A97US2V080C20X | 38,000 | $1,900 |
| No | 210727521 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P60C+TDR+TXV | A96US2V110C20 | 38,000 | $1,900 |
| No | 210727520 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P60C+TDR+TXV | A96US2V090C20 | 38,000 | $1,900 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210727519 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P60C+TDR+TXV | A96UH2E110C20 | 37,800 | $1,890 |
| No | 210727518 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P60C+TDR+TXV | A93UH1E110C20 | 37,800 | $1,890 |
| No | 210727517 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P60C+TDR+TXV | A80US2V110C20L | 38,000 | $1,900 |
| No | 210727516 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P60C+TDR+TXV | A80US2V110C20* | 38,000 | $1,900 |
| No | 210727515 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P60C+TDR+TXV | A80US2V100C20X | 37,600 | $1,880 |
| No | 210727514 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P60C+TDR+TXV | A80US2V090C20* | 37,800 | $1,890 |
| No | 210727513 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P60C+TDR+TXV | A80US2V080C20X | 37,600 | $1,880 |
| No | 210727512 | ARMSTRONG AIR | 4SHP18LX160P | EA(C;U)1P60C+TDR+TXV | A80UH2E110C20 | 38,000 | $1,900 |
| No | 210727510 | ARMSTRONG AIR | 4SHP18LX160P | BCE5V60M | | 38,500 | $1,925 |
| No | 210727511 | ARMSTRONG AIR | 4SHP18LX160P | BCE7E60M - TXV | | 38,000 | $1,900 |
| No | 210727506 | ARMSTRONG AIR | 4SHP18LX160P | BCE7S60 - TXV | | 38,500 | $1,925 |
| No | 210740456 | ARMSTRONG AIR | 4SHP18LX136P | ED1P24B+TDR+TXV | A93DF1E070B12 | 15,600 | $780 |
| No | 210740009 | ARMSTRONG AIR | 4SHP18LX136P | E*1P23B+TDR+TXV | A96US2V045B12 | 15,100 | $755 |
| No | 210740021 | ARMSTRONG AIR | 4SHP18LX136P | E*1P23B+TDR+TXV | A97US2V060B12X | 15,100 | $755 |
| No | 210740017 | ARMSTRONG AIR | 4SHP18LX136P | E*1P23B+TDR+TXV | A97US2V040B12X | 15,100 | $755 |
| No | 210740013 | ARMSTRONG AIR | 4SHP18LX136P | E*1P23B+TDR+TXV | A96US2V070B12 | 15,000 | $750 |
| No | 210740030 | ARMSTRONG AIR | 4SHP18LX136P | E*1P23B+TDR+TXV | EFV12BCA | 15,200 | $760 |
| No | 210740026 | ARMSTRONG AIR | 4SHP18LX136P | E*1P23B+TDR+TXV | EFV08BCA | 15,300 | $765 |
| No | 210740005 | ARMSTRONG AIR | 4SHP18LX136P | E*1P23B+TDR+TXV | A96UH2E070B12 | 15,400 | $770 |
| No | 210740000 | ARMSTRONG AIR | 4SHP18LX136P | E*1P23B+TDR+TXV | A96UH2E045B12 | 15,400 | $770 |
| No | 210739996 | ARMSTRONG AIR | 4SHP18LX136P | E*1P23B+TDR+TXV | A93UH1E070B12 | 15,300 | $765 |
| No | 210739992 | ARMSTRONG AIR | 4SHP18LX136P | E*1P23B+TDR+TXV | A93UH1E045B12 | 15,400 | $770 |
| No | 210739989 | ARMSTRONG AIR | 4SHP18LX136P | E*1P23B+TDR+TXV | A93UH1E030B12 | 15,300 | $765 |
| No | 210739987 | ARMSTRONG AIR | 4SHP18LX136P | E*1P23B+TDR+TXV | A80UH2E090B12 | 15,300 | $765 |
| No | 210739983 | ARMSTRONG AIR | 4SHP18LX136P | E*1P23B+TDR+TXV | A80UH1E070B12 | 15,000 | $750 |
| No | 210739978 | ARMSTRONG AIR | 4SHP18LX136P | E*1P23A+TDR+TXV | A80US2V060A12X | 15,000 | $750 |
| No | 210739974 | ARMSTRONG AIR | 4SHP18LX136P | E*1P23A+TDR+TXV | A80UH2E070A12 | 15,400 | $770 |
| No | 210739970 | ARMSTRONG AIR | 4SHP18LX136P | E*1P23A+TDR+TXV | A80UH2E045A12 | 14,900 | $745 |
| No | 210739966 | ARMSTRONG AIR | 4SHP18LX136P | E*1P23A+TDR+TXV | A80UH1E070A12 | 15,100 | $755 |
| No | 210739963 | ARMSTRONG AIR | 4SHP18LX136P | E*1P23A+TDR+TXV | A80UH1E060A12X | 15,300 | $765 |
| No | 210739959 | ARMSTRONG AIR | 4SHP18LX136P | E*1P23A+TDR+TXV | A80UH1E045A12 | 15,200 | $760 |
| No | 210739955 | ARMSTRONG AIR | 4SHP18LX136P | E*1P23A+TDR+TXV | A80UH1E040A12X | 15,300 | $765 |
| No | 210740452 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P30B+TDR+TXV | EFV12BCA | 15,300 | $765 |
| No | 210740448 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P30B+TDR+TXV | EFV08BCA | 15,500 | $775 |
| No | 210740443 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P30B+TDR+TXV | A97US2V060B12X | 15,300 | $765 |
| No | 210740439 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P30B+TDR+TXV | A97US2V040B12X | 15,300 | $765 |
| No | 210740435 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P30B+TDR+TXV | A96US2V070B12 | 15,300 | $765 |
| No | 210740427 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P30B+TDR+TXV | A96UH2E070B12 | 15,700 | $785 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210740431 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P30B+TDR+TXV | A96US2V045B12 | 15,300 | $765 |
| No | 210740423 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P30B+TDR+TXV | A96UH2E045B12 | 15,700 | $785 |
| No | 210740419 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P30B+TDR+TXV | A96UH1E070B12 | 15,700 | $785 |
| No | 210740415 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P30B+TDR+TXV | A96UH1E030B12 | 15,500 | $775 |
| No | 210740411 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P30B+TDR+TXV | A93UH1E070B12 | 15,600 | $780 |
| No | 210740407 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P30B+TDR+TXV | A93UH1E045B12 | 15,600 | $780 |
| No | 210740403 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P30B+TDR+TXV | A93UH1E030B12 | 15,600 | $780 |
| No | 210740399 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P30B+TDR+TXV | A80UH2E090B12 | 15,500 | $775 |
| No | 210740395 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P30B+TDR+TXV | A80UH1E070B12 | 15,300 | $765 |
| No | 210740391 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P30A+TDR+TXV | A80UH2E070A12 | 15,800 | $790 |
| No | 210740387 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P30A+TDR+TXV | A80UH2E045A12 | 15,300 | $765 |
| No | 210740383 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P30A+TDR+TXV | A80UH1E070A12 | 15,500 | $775 |
| No | 210740379 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P30A+TDR+TXV | A80UH1E060A12X | 15,700 | $785 |
| No | 210740375 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P30A+TDR+TXV | A80UH1E045A12 | 15,700 | $785 |
| No | 210740372 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P30A+TDR+TXV | A80UH1E040A12X | 15,700 | $785 |
| No | 210740368 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X30B+TDR | EFV12BCA | 15,700 | $785 |
| No | 210740364 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X30B+TDR | EFV08BCA | 16,000 | $800 |
| No | 210740360 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X30B+TDR | A97US2V060B12X | 15,600 | $780 |
| No | 210740357 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X30B+TDR | A97US2V040B12X | 15,600 | $780 |
| No | 210740353 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X30B+TDR | A96US2V070B12 | 15,600 | $780 |
| No | 210740344 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X30B+TDR | A96UH2E070B12 | 15,900 | $795 |
| No | 210740348 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X30B+TDR | A96US2V045B12 | 15,600 | $780 |
| No | 210740339 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X30B+TDR | A96UH2E045B12 | 15,900 | $795 |
| No | 210740335 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X30B+TDR | A96UH1E070B12 | 16,000 | $800 |
| No | 210740328 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X30B+TDR | A93UH1E070B12 | 15,800 | $790 |
| No | 210740324 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X30B+TDR | A93UH1E045B12 | 15,900 | $795 |
| No | 210740315 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X30B+TDR | A80UH2E090B12 | 15,900 | $795 |
| No | 210740311 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X30B+TDR | A80UH1E070B12 | 15,700 | $785 |
| No | 210740307 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X30A+TDR | A80US2V060A12X | 15,500 | $775 |
| No | 210740302 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X30A+TDR | A80UH2E070A12 | 15,900 | $795 |
| No | 210740298 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X30A+TDR | A80UH2E045A12 | 15,900 | $795 |
| No | 210740294 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X30A+TDR | A80UH1E070A12 | 15,600 | $780 |
| No | 210740289 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X30A+TDR | A80UH1E060A12X | 15,800 | $790 |
| No | 210740285 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X30A+TDR | A80UH1E045A12 | 15,800 | $790 |
| No | 210740281 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X30A+TDR | A80UH1E040A12X | 15,800 | $790 |
| No | 210740199 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P30B+TDR+TXV | EFV12BCA | 15,700 | $785 |
| No | 210740196 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P30B+TDR+TXV | EFV08BCA | 16,000 | $800 |
| No | 210740192 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P30B+TDR+TXV | A97US2V060B12X | 15,600 | $780 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210740188 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P30B+TDR+TXV | A97US2V040B12X | 15,600 | $780 |
| No | 210740184 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P30B+TDR+TXV | A96US2V070B12 | 15,600 | $780 |
| No | 210740176 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P30B+TDR+TXV | A96UH2E070B12 | 15,900 | $795 |
| No | 210740180 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P30B+TDR+TXV | A96US2V045B12 | 15,600 | $780 |
| No | 210740171 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P30B+TDR+TXV | A96UH2E045B12 | 15,900 | $795 |
| No | 210740167 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P30B+TDR+TXV | A96UH1E070B12 | 16,000 | $800 |
| No | 210740158 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P30B+TDR+TXV | A93UH1E070B12 | 15,800 | $790 |
| No | 210740154 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P30B+TDR+TXV | A93UH1E045B12 | 15,900 | $795 |
| No | 210740149 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P30B+TDR+TXV | A80UH2E090B12 | 15,900 | $795 |
| No | 210740147 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P30B+TDR+TXV | A80UH1E070B12 | 15,700 | $785 |
| No | 210740142 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P30A+TDR+TXV | A80US2V060A12X | 15,500 | $775 |
| No | 210740138 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P30A+TDR+TXV | A80UH2E070A12 | 15,900 | $795 |
| No | 210740134 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P30A+TDR+TXV | A80UH2E045A12 | 15,900 | $795 |
| No | 210740129 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P30A+TDR+TXV | A80UH1E070A12 | 15,600 | $780 |
| No | 210740125 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P30A+TDR+TXV | A80UH1E060A12X | 15,800 | $790 |
| No | 210740121 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P30A+TDR+TXV | A80UH1E045A12 | 15,800 | $790 |
| No | 210740116 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P30A+TDR+TXV | A80UH1E040A12X | 15,800 | $790 |
| No | 210739951 | ARMSTRONG AIR | 4SHP18LX136P | BCE7S30M*4X | | 16,000 | $800 |
| No | 210739943 | ARMSTRONG AIR | 4SHP18LX136P | BCE7E30M*4X | | 16,200 | $810 |
| No | 210739939 | ARMSTRONG AIR | 4SHP18LX136P | BCE7E18M*4X | | 15,300 | $765 |
| No | 210739935 | ARMSTRONG AIR | 4SHP18LX136P | BCE5V30M*4X | | 15,900 | $795 |
| No | 210739932 | ARMSTRONG AIR | 4SHP18LX136P | BCE5V24M*4X | | 16,200 | $810 |
| No | 210739928 | ARMSTRONG AIR | 4SHP18LX136P | BCE5V18M*4X | | 15,900 | $795 |
| No | 210739926 | ARMSTRONG AIR | 4SHP18LX136P | BCE5E30M*4X | | 15,900 | $795 |
| No | 210739920 | ARMSTRONG AIR | 4SHP18LX136P | BCE5C24M*4X | | 16,100 | $805 |
| No | 210739916 | ARMSTRONG AIR | 4SHP18LX136P | BCE5C24M*1P+TXV | | 16,100 | $805 |
| No | 210739914 | ARMSTRONG AIR | 4SHP18LX136P | BCE5C18M*4X | | 15,400 | $770 |
| No | 210739913 | ARMSTRONG AIR | 4SHP18LX136P | BCE5C18M*1P+TXV | | 15,400 | $770 |
| No | 210739947 | ARMSTRONG AIR | 4SHP18LX136P | BCE7S24M*4X | | 15,200 | $760 |
| No | 210737956 | ARMSTRONG AIR | 4SHP18LX136P | BCE7E36M*4X | | 23,600 | $1,180 |
| No | 210738128 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36C+TDR+TXV | EFV16CCA | 23,600 | $1,180 |
| No | 210738124 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36C+TDR+TXV | A97USMV090C16 | 23,800 | $1,190 |
| No | 210738120 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36C+TDR+TXV | A97USMV090C12 | 23,800 | $1,190 |
| No | 210738116 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36C+TDR+TXV | A97US2V080C16X | 23,800 | $1,190 |
| No | 210738112 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36C+TDR+TXV | A96US2V110C16 | 23,800 | $1,190 |
| No | 210738107 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36C+TDR+TXV | A96US2V090C16 | 23,800 | $1,190 |
| No | 210738106 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36C+TDR+TXV | A96US2V090C12 | 23,800 | $1,190 |
| No | 210738104 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36C+TDR+TXV | A96UH2E090C16 | 23,800 | $1,190 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210738101 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36C+TDR+TXV | A96UH1E090C16 | 23,600 | $1,180 |
| No | 210738097 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36C+TDR+TXV | A93UH1E110C16 | 23,400 | $1,170 |
| No | 210738093 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36C+TDR+TXV | A93UH1E090C16 | 23,600 | $1,180 |
| No | 210738089 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36C+TDR+TXV | A93UH1E090C12 | 23,800 | $1,190 |
| No | 210738084 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36C+TDR+TXV | A80UH2E110C16 | 23,600 | $1,180 |
| No | 210738080 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36B+TDR+TXV | EFV12BCA | 23,600 | $1,180 |
| No | 210738076 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36B+TDR+TXV | A97US2V060B12X | 24,000 | $1,200 |
| No | 210738072 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36B+TDR+TXV | A97US2V040B12X | 24,000 | $1,200 |
| No | 210738028 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36B+TDR+TXV | A80US2V090B16L | 23,800 | $1,190 |
| No | 210738024 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36B+TDR+TXV | A80US2V080B16X | 23,800 | $1,190 |
| No | 210738067 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36B+TDR+TXV | A96US2V070B12 | 24,000 | $1,200 |
| No | 210738058 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36B+TDR+TXV | A96UH2E070B12 | 23,600 | $1,180 |
| No | 210738063 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36B+TDR+TXV | A96US2V045B12 | 24,200 | $1,210 |
| No | 210738054 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36B+TDR+TXV | A96UH2E045B12 | 23,600 | $1,180 |
| No | 210738050 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36B+TDR+TXV | A96UH1E070B12 | 23,400 | $1,170 |
| No | 210738047 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36B+TDR+TXV | A96UH1E030B12 | 23,400 | $1,170 |
| No | 210738043 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36B+TDR+TXV | A95UH1E070B12 | 23,200 | $1,160 |
| No | 210738040 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36B+TDR+TXV | A93UH1E070B12 | 23,600 | $1,180 |
| No | 210738036 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36B+TDR+TXV | A93UH1E045B12 | 23,800 | $1,190 |
| No | 210738032 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36B+TDR+TXV | A93UH1E030B12 | 23,600 | $1,180 |
| No | 210738019 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36B+TDR+TXV | A80UH2E090B16 | 23,600 | $1,180 |
| No | 210738015 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36B+TDR+TXV | A80UH2E090B12 | 23,800 | $1,190 |
| No | 210738011 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36B+TDR+TXV | A80UH1E090B16 | 23,600 | $1,180 |
| No | 210738007 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36B+TDR+TXV | A80UH1E080B16X | 23,800 | $1,190 |
| No | 210738002 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36B+TDR+TXV | A80UH1E070B12 | 23,600 | $1,180 |
| No | 210737994 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36A+TDR+TXV | A80US2V060A12X | 23,800 | $1,190 |
| No | 210737998 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36A+TDR+TXV | A80US2V070A12L | 24,000 | $1,200 |
| No | 210737989 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36A+TDR+TXV | A80UH2E070A12 | 23,800 | $1,190 |
| No | 210737985 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36A+TDR+TXV | A80UH2E045A12 | 23,800 | $1,190 |
| No | 210737980 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36A+TDR+TXV | A80UH1E070A12 | 23,400 | $1,170 |
| No | 210737976 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36A+TDR+TXV | A80UH1E060A12X | 23,400 | $1,170 |
| No | 210737972 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36A+TDR+TXV | A80UH1E045A12 | 23,400 | $1,170 |
| No | 210737968 | ARMSTRONG AIR | 4SHP18LX136P | E*1P36A+TDR+TXV | A80UH1E040A12X | 23,400 | $1,170 |
| No | 210738752 | ARMSTRONG AIR | 4SHP18LX136P | ED1P30/36B+TDR+TXV | A80DS2V090B16 | 21,000 | $1,050 |
| No | 210738691 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P36B+TDR+TXV | EFV12BCA | 22,400 | $1,120 |
| No | 210738687 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P36B+TDR+TXV | A97US2V060B12X | 22,600 | $1,130 |
| No | 210738683 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P36B+TDR+TXV | A97US2V040B12X | 22,600 | $1,130 |
| No | 210738644 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P36B+TDR+TXV | A80US2V090B16L | 22,600 | $1,130 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210738635 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P36B+TDR+TXV | A80US2V080B16X | 22,400 | $1,120 |
| No | 210738679 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P36B+TDR+TXV | A96US2V070B12 | 22,600 | $1,130 |
| No | 210738671 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P36B+TDR+TXV | A96UH2E070B12 | 22,200 | $1,110 |
| No | 210738675 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P36B+TDR+TXV | A96US2V045B12 | 22,800 | $1,140 |
| No | 210738669 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P36B+TDR+TXV | A96UH2E045B12 | 22,200 | $1,110 |
| No | 210738668 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P36B+TDR+TXV | A96UH1E070B12 | 22,000 | $1,100 |
| No | 210738665 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P36B+TDR+TXV | A96UH1E030B12 | 22,000 | $1,100 |
| No | 210738661 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P36B+TDR+TXV | A95UH1E070B12 | 22,000 | $1,100 |
| No | 210738657 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P36B+TDR+TXV | A93UH1E070B12 | 22,200 | $1,110 |
| No | 210738653 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P36B+TDR+TXV | A93UH1E045B12 | 22,400 | $1,120 |
| No | 210738648 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P36B+TDR+TXV | A93UH1E030B12 | 22,400 | $1,120 |
| No | 210738640 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P36B+TDR+TXV | A80US2V090B16 | 22,600 | $1,130 |
| No | 210738631 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P36B+TDR+TXV | A80UH2E090B16 | 22,200 | $1,110 |
| No | 210738627 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P36B+TDR+TXV | A80UH2E090B12 | 22,400 | $1,120 |
| No | 210738623 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P36B+TDR+TXV | A80UH1E090B16 | 22,200 | $1,110 |
| No | 210738619 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P36B+TDR+TXV | A80UH1E080B16X | 22,400 | $1,120 |
| No | 210738614 | ARMSTRONG AIR | 4SHP18LX136P | EAH1P36B+TDR+TXV | A80UH1E070B12 | 22,200 | $1,110 |
| No | 210738610 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48C+TDR | EFV16CCA | 22,200 | $1,110 |
| No | 210738606 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48C+TDR | A97USMV090C16 | 22,400 | $1,120 |
| No | 210738602 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48C+TDR | A97USMV090C12 | 22,400 | $1,120 |
| No | 210738598 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48C+TDR | A97US2V080C16X | 22,400 | $1,120 |
| No | 210738594 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48C+TDR | A96US2V110C16 | 22,400 | $1,120 |
| No | 210738591 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48C+TDR | A96US2V090C16 | 22,400 | $1,120 |
| No | 210738587 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48C+TDR | A96US2V090C12 | 22,400 | $1,120 |
| No | 210738585 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48C+TDR | A96UH2E090C16 | 22,400 | $1,120 |
| No | 210738581 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48C+TDR | A96UH1E090C16 | 22,200 | $1,110 |
| No | 210738576 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48C+TDR | A95UH1E090C16 | 22,200 | $1,110 |
| No | 210738572 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48C+TDR | A93UH1E110C16 | 22,000 | $1,100 |
| No | 210738568 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48C+TDR | A93UH1E090C16 | 22,200 | $1,110 |
| No | 210738563 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48C+TDR | A93UH1E090C12 | 22,400 | $1,120 |
| No | 210738559 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48C+TDR | A80UH2E110C16 | 22,200 | $1,110 |
| No | 210738555 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48B+TDR | EFV12BCA | 22,200 | $1,110 |
| No | 210738550 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48B+TDR | A97USMV070B12 | 22,600 | $1,130 |
| No | 210738546 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48B+TDR | A97US2V060B12X | 22,600 | $1,130 |
| No | 210738541 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48B+TDR | A97US2V040B12X | 22,600 | $1,130 |
| No | 210738503 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48B+TDR | A80US2V090B16L | 22,400 | $1,120 |
| No | 210738496 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48B+TDR | A80US2V080B16X | 22,400 | $1,120 |
| No | 210738537 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48B+TDR | A96US2V070B12 | 22,600 | $1,130 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210738528 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48B+TDR | A96UH2E070B12 | 22,200 | $1,110 |
| No | 210738532 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48B+TDR | A96US2V045B12 | 22,600 | $1,130 |
| No | 210738524 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48B+TDR | A96UH2E045B12 | 22,200 | $1,110 |
| No | 210738521 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48B+TDR | A96UH1E070B12 | 22,000 | $1,100 |
| No | 210738520 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48B+TDR | A96UH1E045B12 | 22,000 | $1,100 |
| No | 210738517 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48B+TDR | A95UH1E070B12 | 21,800 | $1,090 |
| No | 210738514 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48B+TDR | A93UH1E070B12 | 22,200 | $1,110 |
| No | 210738510 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48B+TDR | A93UH1E045B12 | 22,400 | $1,120 |
| No | 210738506 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48B+TDR | A93UH1E030B12 | 22,200 | $1,110 |
| No | 210738500 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48B+TDR | A80US2V090B16 | 22,400 | $1,120 |
| No | 210738492 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48B+TDR | A80UH2E090B16 | 22,200 | $1,110 |
| No | 210738487 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48B+TDR | A80UH2E090B12 | 22,400 | $1,120 |
| No | 210738483 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48B+TDR | A80UH1E090B16 | 22,200 | $1,110 |
| No | 210738475 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X48B+TDR | A80UH1E070B12 | 22,200 | $1,110 |
| No | 210738351 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48C+TDR+TXV | A97USMV090C16 | 22,400 | $1,120 |
| No | 210738346 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48C+TDR+TXV | A97USMV090C12 | 22,400 | $1,120 |
| No | 210738342 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48C+TDR+TXV | A97US2V080C16X | 22,400 | $1,120 |
| No | 210738337 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48C+TDR+TXV | A96US2V110C16 | 22,400 | $1,120 |
| No | 210738333 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48C+TDR+TXV | A96US2V090C16 | 22,400 | $1,120 |
| No | 210738329 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48C+TDR+TXV | A96US2V090C12 | 22,400 | $1,120 |
| No | 210738324 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48C+TDR+TXV | A96UH2E090C16 | 22,400 | $1,120 |
| No | 210738320 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48C+TDR+TXV | A96UH1E090C16 | 22,200 | $1,110 |
| No | 210738316 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48C+TDR+TXV | A95UH1E090C16 | 22,200 | $1,110 |
| No | 210738315 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48C+TDR+TXV | A93UH1E110C16 | 22,000 | $1,100 |
| No | 210738313 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48C+TDR+TXV | A93UH1E090C16 | 22,200 | $1,110 |
| No | 210738309 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48C+TDR+TXV | A93UH1E090C12 | 22,400 | $1,120 |
| No | 210738304 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48C+TDR+TXV | A80UH2E110C16 | 22,200 | $1,110 |
| No | 210738300 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | EFV12BCA | 22,400 | $1,120 |
| No | 210738296 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A97US2V060B12X | 22,600 | $1,130 |
| No | 210738240 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A80US2V090B16L | 22,400 | $1,120 |
| No | 210738231 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A80US2V080B16X | 22,400 | $1,120 |
| No | 210738287 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A96US2V070B12 | 22,600 | $1,130 |
| No | 210738278 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A96UH2E070B12 | 22,200 | $1,110 |
| No | 210738283 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A96US2V045B12 | 22,600 | $1,130 |
| No | 210738274 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A96UH2E045B12 | 22,200 | $1,110 |
| No | 210738270 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A96UH1E070B12 | 22,000 | $1,100 |
| No | 210738265 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A96UH1E045B12 | 22,000 | $1,100 |
| No | 210738257 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A95UH1E070B12 | 21,800 | $1,090 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210738252 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A93UH1E070B12 | 22,200 | $1,110 |
| No | 210738248 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A93UH1E045B12 | 22,400 | $1,120 |
| No | 210738244 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A93UH1E030B12 | 22,200 | $1,110 |
| No | 210738235 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A80US2V090B16 | 22,400 | $1,120 |
| No | 210738227 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A80UH2E090B16 | 22,200 | $1,110 |
| No | 210738222 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A80UH2E090B12 | 22,400 | $1,120 |
| No | 210738221 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A80UH1E090B16 | 22,200 | $1,110 |
| No | 210738217 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P48B+TDR+TXV | A80UH1E070B12 | 22,200 | $1,110 |
| No | 210738468 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X36B+TDR | A97USMV070B12 | 23,400 | $1,170 |
| No | 210738467 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X36B+TDR | A97US2V060B12X | 23,400 | $1,170 |
| No | 210738463 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X36B+TDR | A97US2V040B12X | 23,400 | $1,170 |
| No | 210738415 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X36B+TDR | A80US2V090B16L | 23,400 | $1,170 |
| No | 210738411 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X36B+TDR | A80US2V080B16X | 23,200 | $1,160 |
| No | 210738459 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X36B+TDR | A96US2V070B12 | 23,400 | $1,170 |
| No | 210738455 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X36B+TDR | A96US2V045B12 | 23,600 | $1,180 |
| No | 210738390 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X36B+TDR | A80UH1E070B12 | 22,800 | $1,140 |
| No | 210738381 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X36A+TDR | A80US2V060A12X | 23,200 | $1,160 |
| No | 210738386 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X36A+TDR | A80US2V070A12L | 23,400 | $1,170 |
| No | 210738373 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X36A+TDR | A80UH2E045A12 | 23,000 | $1,150 |
| No | 210738368 | ARMSTRONG AIR | 4SHP18LX136P | EAC4X36A+TDR | A80UH1E070A12 | 22,800 | $1,140 |
| No | 210738169 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P36B+TDR+TXV | A80US2V080B16X | 23,200 | $1,160 |
| No | 210738211 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P36B+TDR+TXV | A97US2V060B12X | 23,400 | $1,170 |
| No | 210738207 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P36B+TDR+TXV | A97US2V040B12X | 23,400 | $1,170 |
| No | 210738173 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P36B+TDR+TXV | A80US2V090B16L | 23,400 | $1,170 |
| No | 210738203 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P36B+TDR+TXV | A96US2V070B12 | 23,400 | $1,170 |
| No | 210738199 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P36B+TDR+TXV | A96US2V045B12 | 23,600 | $1,180 |
| No | 210738154 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P36B+TDR+TXV | A80UH1E070B12 | 22,800 | $1,140 |
| No | 210738150 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P36A+TDR+TXV | A80US2V070A12L | 23,400 | $1,170 |
| No | 210738146 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P36A+TDR+TXV | A80US2V060A12X | 23,200 | $1,160 |
| No | 210738141 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P36A+TDR+TXV | A80UH2E045A12 | 23,000 | $1,150 |
| No | 210738140 | ARMSTRONG AIR | 4SHP18LX136P | EA(C;U)1P36A+TDR+TXV | A80UH1E070A12 | 22,800 | $1,140 |
| No | 210739644 | ARMSTRONG AIR | 4SHP18LX136P | BCE5C36M*4X | | 20,800 | $1,040 |
| No | 210737936 | ARMSTRONG AIR | 4SHP18LX136P | BCE5C36M*1P+TXV | | 20,800 | $1,040 |
| No | 210737945 | ARMSTRONG AIR | 4SHP18LX136P | BCE5E42M*4X | | 22,200 | $1,110 |
| No | 210737940 | ARMSTRONG AIR | 4SHP18LX136P | BCE5E36M*4X | | 22,600 | $1,130 |
| No | 210737949 | ARMSTRONG AIR | 4SHP18LX136P | BCE5V36M*4X | | 22,200 | $1,110 |
| No | 210737952 | ARMSTRONG AIR | 4SHP18LX136P | BCE5V42M*4X | | 22,200 | $1,110 |
| No | 210737964 | ARMSTRONG AIR | 4SHP18LX136P | BCE7S42M*4X | | 23,000 | $1,150 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210737934 | ARMSTRONG AIR | 4SHP18LX136P | BCE7S36 | | 22,600 | $1,130 |
| No | 208106820 | ARMSTRONG AIR | 4DHP2S30M-1P | Combination heat pumps with or without ducts | | 16,000 | $800 |
| No | 208106817 | ARMSTRONG AIR | 4DHP2S24M-1P | Combination heat pumps with or without ducts | | 16,700 | $835 |
| No | 208106814 | ARMSTRONG AIR | 4DHP2S18M-1P | Combination heat pumps with or without ducts | | 11,400 | $570 |
| No | 202483113 | ARMSTRONG AIR | 4SHP20LX160P | ED1P50/60C+H4TXV02 | A97DSMV090C20 | 36,400 | $1,820 |
| No | 202483114 | ARMSTRONG AIR | 4SHP20LX160P | ED1P50/60C+H4TXV02 | A97DSMV110C20 | 36,400 | $1,820 |
| No | 202483111 | ARMSTRONG AIR | 4SHP20LX160P | ED1P50/60C+H4TXV02 | A96DS2V110C20 | 36,400 | $1,820 |
| No | 201846643 | ARMSTRONG AIR | 4SHP20LX160P | EAH1P60D+H4TXV03 | A96US2V135D20 | 36,600 | $1,830 |
| No | 201846644 | ARMSTRONG AIR | 4SHP20LX160P | EAH1P60D+H4TXV03 | A97USMV135D20 | 36,600 | $1,830 |
| No | 201848001 | ARMSTRONG AIR | 4SHP20LX124P | EAC4X30B | A97USMV070B12 | 13,000 | $650 |
| No | 201846641 | ARMSTRONG AIR | 4SHP20LX148P | EAH1P60D+H4TXV03 | A97USMV135D20 | 29,200 | $1,460 |
| No | 10075489 | ARMSTRONG AIR | 4SHP20LX124P | EC4X36B | A96US2V045B12 | 13,000 | $650 |
| No | 10075490 | ARMSTRONG AIR | 4SHP20LX124P | EC4X36B | A96US2V070B12 | 13,000 | $650 |
| No | 201847997 | ARMSTRONG AIR | 4SHP20LX124P | EA(C,U)1P30B+H4TXV01 | A97USMV070B12 | 13,000 | $650 |
| No | 201847996 | ARMSTRONG AIR | 4SHP20LX124P | EA(C,U)1P30B+H4TXV01 | A96US2V070B12 | 13,000 | $650 |
| No | 201847995 | ARMSTRONG AIR | 4SHP20LX124P | EA(C,U)1P30B+H4TXV01 | A96US2V045B12 | 13,000 | $650 |
| No | 10581281 | ARMSTRONG AIR | 4SHP20LX124P | ED1P48B+H4TXV02 | A97DSMV070B12 | 14,700 | $735 |
| No | 202760844 | ARMSTRONG AIR | 4SHP20LX160P | BCE7S60M | | 36,200 | $1,810 |
| No | 202760842 | ARMSTRONG AIR | 4SHP20LX148P | BCE7S60M | | 26,400 | $1,320 |
| No | 202760839 | ARMSTRONG AIR | 4SHP20LX136P | BCE7S42M | | 21,400 | $1,070 |
| No | 201846639 | ARMSTRONG AIR | 4SHP20LX136P | EAH1P48C+H4TXV02 | A96US2V090C12 | 21,600 | $1,080 |
| No | 10581280 | ARMSTRONG AIR | 4SHP20LX124P | ED1P48B+H4TXV02 | A96DS2V045B12 | 14,700 | $735 |
| No | 201846630 | ARMSTRONG AIR | 4SHP20LX124P | EAH1P30B+H4TXV01 | A97USMV070B12 | 14,400 | $720 |
| No | 201846629 | ARMSTRONG AIR | 4SHP20LX124P | EAH1P30B+H4TXV01 | A96US2V070B12 | 14,400 | $720 |
| No | 202483110 | ARMSTRONG AIR | 4SHP20LX160P | ED1P50/60C+H4TXV02 | A96DS2V090C20 | 36,400 | $1,820 |
| No | 201846628 | ARMSTRONG AIR | 4SHP20LX124P | EAH1P30B+H4TXV01 | A96US2V045B12 | 14,400 | $720 |
| No | 202760837 | ARMSTRONG AIR | 4SHP20LX124P | BCE7S30M | | 14,000 | $700 |
| No | 202760835 | ARMSTRONG AIR | 4SHP20LX124P | BCE7S24M | | 13,600 | $680 |
| No | 208106680 | ARMSTRONG AIR | 4DHP2S24S-1P | DMD224S4-1P | | 13,500 | $675 |
| No | 208106767 | ARMSTRONG AIR | 4DHP2S36S-1P | D33C236S4-1P | | 23,000 | $1,150 |
| No | 208106769 | ARMSTRONG AIR | 4DHP2S36S-1P | DMD236S4-2P | | 27,000 | $1,350 |
| No | 208106768 | ARMSTRONG AIR | 4DHP2S48S-1P | D33C248S4-1P | | 28,000 | $1,400 |
| No | 208106770 | ARMSTRONG AIR | 4DHP2S48S-1P | DMD248S4-2P | | 29,000 | $1,450 |
| No | 208106677 | ARMSTRONG AIR | 4DHP2S24S-1P | D33C224S4-1P | | 15,600 | $780 |
| No | 208106676 | ARMSTRONG AIR | 4DHP2S18S-1P | D22C118S4-1P | | 12,000 | $600 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208101258 | AURORA | AU-CX18HR-2A-O | AU-BS18HR-2A-I | | 11,100 | $555 |
| No | 208101260 | AURORA | AU-LCU60-2A-O | AU-LCU60-2A-I | | 33,800 | $1,690 |
| No | 208101257 | AURORA | AU-CX12HR-2A-O | AU-BS12HR-2A-I | | 7,300 | $365 |
| No | 208101256 | AURORA | AU-CX09HR-2A-O | AU-BS09HR-2A-I | | 7,400 | $370 |
| No | 207743717 | AURORA | AU-MU48-2A-U | AU-LCF09-2A-I | | 30,400 | $1,520 |
| No | 207743711 | AURORA | AU-MU27-2A-U | AU-LCF09-2A-I | | 16,000 | $800 |
| No | 207743713 | AURORA | AU-MU36-2A-U | AU-BS09HR-2A-I | | 24,000 | $1,200 |
| No | 207743710 | AURORA | AU-MU27-2A-U | AU-BS09HR-2A-I | | 16,200 | $810 |
| No | 207743707 | AURORA | AU-MU18-2A-U | AU-BS09HR-2A-I | | 11,800 | $590 |
| No | 207339172 | AURORA | AU-A36HR-2B-O | AU-A36HR-2B-I | | 24,000 | $1,200 |
| No | 207339168 | AURORA | AU-A12HR-2B-O | AU-A12HR-2B-I | | 7,000 | $350 |
| No | 207339170 | AURORA | AU-A24HR-2B-O | AU-A24HR-2B-I | | 14,800 | $740 |
| No | 207339169 | AURORA | AU-A18HR-2B-O | AU-A18HR-2B-I | | 11,400 | $570 |
| No | 207339167 | AURORA | AU-A09HR-2B-O | AU-A09HR-2B-I | | 6,000 | $300 |
| No | 207339166 | AURORA | AU-A12HR-1B-O | AU-A12HR-1B-I | | 7,000 | $350 |
| No | 207339165 | AURORA | AU-A09HR-1B-O | AU-A09HR-1B-I | | 6,000 | $300 |
| No | 205788778 | AURORA | AU-A09HR-1A-O | AU-A09HR-1A-I | | 6,000 | $300 |
| No | 205788782 | AURORA | AU-A18HR-2A-O | AU-A18HR-2A-I | | 11,000 | $550 |
| No | 205417847 | AZUR | AZ-18CA22EXT | AZ-18CA22INT | | 11,600 | $580 |
| No | 205417845 | AZUR | AZ-12CA22EXT | AZ-12CA22INT | | 7,500 | $375 |
| No | 207036537 | AZUR | AZ-60HPB | AH-60B | | 40,000 | $2,000 |
| No | 207036533 | AZUR | AZ-48HPB | AH-48B | | 31,000 | $1,550 |
| No | 207036530 | AZUR | AZ-36HPB | AH-36B | | 24,000 | $1,200 |
| No | 207036527 | AZUR | AZ-24HPB | AH-24B | | 15,000 | $750 |
| No | 206346136 | AZUR | AZ-24M322SCO | Heat pump without ducts | | 15,400 | $770 |
| No | 206347268 | AZUR | AZ-36M422SCO | Heat pump without ducts | | 23,200 | $1,160 |
| No | 206346140 | AZUR | AZ-42M522SCO | Heat pump without ducts | | 24,000 | $1,200 |
| No | 205662516 | AZUR | AZ-24HPA | AH-24 | | 15,300 | $765 |
| No | 205663369 | AZUR | AZ-60HPA | AH-60 | | 32,400 | $1,620 |
| No | 205417843 | AZUR | AZ-09DA17EXT | AZ-09DA17INT | | 5,000 | $250 |
| No | 205417846 | AZUR | AZ-18CA17EXT | AZ-18CA17INT | | 11,600 | $580 |
| No | 208101245 | BLUERIDGE | BMAH3618C | BMAH3618I | | 30,400 | $1,520 |
| No | 208101244 | BLUERIDGE | BMAH3018C | BMAH3018I | | 21,000 | $1,050 |
| No | 208650619 | BLUERIDGE | BMM55C | Heat pump without ducts | | 36,400 | $1,820 |
| No | 207641286 | BLUERIDGE | BMM36C | Heat pump without ducts | | 26,400 | $1,320 |
| No | 207641288 | BLUERIDGE | BMM48C | Heat pump without ducts | | 36,000 | $1,800 |
| No | 207641283 | BLUERIDGE | BMM27C | Heat pump without ducts | | 20,000 | $1,000 |
| No | 207641282 | BLUERIDGE | BMM27C | Heat pump with ducts | | 22,000 | $1,100 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207641280 | BLUERIDGE | BMM18C | Heat pump with ducts | | 14,800 | $740 |
| No | 207641279 | BLUERIDGE | BMM18C | Heat pump without ducts | | 14,400 | $720 |
| No | 209550307 | BLUERIDGE | BMY6HH27C | BMM6CC2 | | 5,700 | $285 |
| No | 209550309 | BLUERIDGE | BMY12HH26C | BMM12CC2 | | 9,500 | $475 |
| No | 209550308 | BLUERIDGE | BMY9HH28C | BMM9CC2 | | 9,800 | $490 |
| No | 209550312 | BLUERIDGE | BMY18HH22C | BMM16LW | | 14,700 | $735 |
| No | 209550311 | BLUERIDGE | BMY12HH26C | BMM12LW | | 10,200 | $510 |
| No | 209948201 | BLUERIDGE | BMY60UC2 | BM60MFCC | | 35,000 | $1,750 |
| No | 209948202 | BLUERIDGE | BMY3021C | BMY3020WM | | 20,000 | $1,000 |
| No | 208650625 | BLUERIDGE | BMY36HHUC | BM36MCD | | 34,000 | $1,700 |
| No | 207339181 | BLUERIDGE | BMY24DIY21C | BMY24DIY21WM | | 17,900 | $895 |
| No | 207339180 | BLUERIDGE | BMY18DIY22C | BMY18DIY22WM | | 13,800 | $690 |
| No | 207339179 | BLUERIDGE | BMY12DIY22C | BMY12DIY22WM | | 7,500 | $375 |
| No | 207571385 | BLUERIDGE | BMY48UC | BM48MFCC | | 29,000 | $1,450 |
| No | 207571383 | BLUERIDGE | BMY36UC | BM36MCD | | 25,000 | $1,250 |
| No | 207571384 | BLUERIDGE | BMY36UC | BM36MFCC | | 23,000 | $1,150 |
| No | 207826692 | BLUERIDGE | BMY6HH27C | BMY6HH27WM | | 8,500 | $425 |
| No | 207339176 | BLUERIDGE | BMY2419C | BMY2419WM | | 16,500 | $825 |
| No | 207339175 | BLUERIDGE | BMY1820C | BMY1820WM | | 11,400 | $570 |
| No | 207339174 | BLUERIDGE | BMY1221C | BMY1221WM | | 7,000 | $350 |
| No | 207339173 | BLUERIDGE | BMY922C | BMY922WM | | 6,000 | $300 |
| No | 207826691 | BLUERIDGE | BMX1220C | BMX1220WM | | 7,800 | $390 |
| No | 207826690 | BLUERIDGE | BMX922C | BMX922WM | | 6,300 | $315 |
| No | 207571391 | BLUERIDGE | BMY18HH22C | BM18MCC | | 15,600 | $780 |
| No | 207571392 | BLUERIDGE | BMY18HH22C | BM18MFCC | | 12,000 | $600 |
| No | 207571389 | BLUERIDGE | BMY12HH26C | BM12M22CNS | | 9,600 | $480 |
| No | 207571387 | BLUERIDGE | BMY12HH26C | BM12MCD | | 10,600 | $530 |
| No | 207571388 | BLUERIDGE | BMY12HH26C | BM12MCC | | 9,900 | $495 |
| No | 207571386 | BLUERIDGE | BMY9HH28C | BM09MCC | | 9,000 | $450 |
| No | 207339184 | BLUERIDGE | BMY12HH26C | BMY12HH26WM | | 10,000 | $500 |
| No | 207339183 | BLUERIDGE | BMY9HH28C | BMY9HH28WM | | 9,500 | $475 |
| No | 207641289 | BLUERIDGE | BMM48C | Heat pump with ducts | | 30,400 | $1,520 |
| No | 207339182 | BLUERIDGE | BMY36DIY18C | BMY36DIY18WM | | 21,000 | $1,050 |
| No | 207339178 | BLUERIDGE | BMY3618C | BMY3618WM | | 20,000 | $1,000 |
| No | 202918822 | BLUERIDGE | BMHH36M17C | Heat pump without ducts | | 23,200 | $1,160 |
| No | 202897338 | BLUERIDGE | BM18Y19C | BM18Y19WM | | 11,000 | $550 |
| No | 202918812 | BLUERIDGE | BMHH36M17C | Heat pump with ducts | | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207641290 | BLUERIDGE | BMM48C | Combination heat pumps with or without ducts | | 30,600 | $1,530 |
| No | 207641284 | BLUERIDGE | BMM27C | Combination heat pumps with or without ducts | | 16,100 | $805 |
| No | 207641281 | BLUERIDGE | BMM18C | Combination heat pumps with or without ducts | | 11,800 | $590 |
| No | 207641296 | BLUERIDGE | BMM27HHC | Combination heat pumps with or without ducts | | 16,900 | $845 |
| No | 208650621 | BLUERIDGE | BMM55C | Combination heat pumps with or without ducts | | 35,600 | $1,780 |
| No | 208650620 | BLUERIDGE | BMM55C | Heat pump with ducts | | 35,000 | $1,750 |
| No | 207641303 | BLUERIDGE | BMY60UC | BM60MFCC | | 35,000 | $1,750 |
| No | 10277686 | BOREAL | EQX18HPJ1OB | EQX18HPJ1IB | | 12,400 | $620 |
| No | 10277687 | BOREAL | EQX24HPJ1OB | EQX24HPJ1IB | | 14,600 | $730 |
| No | 10277685 | BOREAL | EQX12HPJ1OB | EQX12HPJ1IB | | 7,100 | $355 |
| No | 10277684 | BOREAL | EQX09HPJ1OB | EQX09HPJ1IB | | 6,800 | $340 |
| No | 207759993 | BOSCH | BMS500-AAS009-1CSXRC | BMS500-AAU006-1AHWXC | | 8,500 | $425 |
| No | 207760014 | BOSCH | BMS500-AAS012-1CSXHC | BMS500-AAU012-1AHCXB | | 9,900 | $495 |
| No | 207759995 | BOSCH | BMS500-AAS012-1CSXHC | BMS500-AAU012-1AHWXC | | 10,000 | $500 |
| No | 207759990 | BOSCH | BMS500-AAS012-1CSXRC | BMS500-AAU012-1AHWXC | | 9,000 | $450 |
| No | 207760045 | BOSCH | BMS500-AAS012-1CSXRC | BMS500-AAU012-1AHCXB | | 8,900 | $445 |
| No | 207760037 | BOSCH | BMS500-AAM027-1CSXHC | Heat pump with ducts | | 27,000 | $1,350 |
| No | 207760025 | BOSCH | BMS500-AAM027-1CSXRC | Heat pump with ducts | | 22,000 | $1,100 |
| No | 207760012 | BOSCH | BMS500-AAS009-1CSXRC | BMS500-AAU009-1AHCXB | | 7,500 | $375 |
| No | 207759991 | BOSCH | BMS500-AAS018-1CSXRC | BMS500-AAU018-1AHWXC | | 14,900 | $745 |
| No | 207760004 | BOSCH | BMS500-AAS018-1CSXRC | BMS500-AAU018-1AHDXB | | 12,600 | $630 |
| No | 207760027 | BOSCH | BMS500-AAM036-1CSXRC | Heat pump without ducts | | 26,800 | $1,340 |
| No | 207760036 | BOSCH | BMS500-AAM027-1CSXHC | Heat pump without ducts | | 26,600 | $1,330 |
| No | 207760024 | BOSCH | BMS500-AAM027-1CSXRC | Heat pump without ducts | | 21,000 | $1,050 |
| No | 207760022 | BOSCH | BMS500-AAM018-1CSXRC | Heat pump with ducts | | 14,800 | $740 |
| No | 207760021 | BOSCH | BMS500-AAM018-1CSXRC | Heat pump without ducts | | 14,300 | $715 |
| No | 207759992 | BOSCH | BMS500-AAS024-1CSXRC | BMS500-AAU024-1AHWXC | | 16,200 | $810 |
| No | 207759989 | BOSCH | BMS500-AAS009-1CSXRC | BMS500-AAU009-1AHWXC | | 8,500 | $425 |
| No | 207760003 | BOSCH | BMS500-AAS012-1CSXHC | BMS500-AAU012-1AHDXB | | 10,600 | $530 |
| No | 207760001 | BOSCH | BMS500-AAS009-1CSXHC | BMS500-AAU009-1AHDXB | | 10,100 | $505 |
| No | 207759998 | BOSCH | BMS500-AAS030-1CSXRC | BMS500-AAU030-1AHWXC | | 19,000 | $950 |
| No | 207760002 | BOSCH | BMS500-AAS012-1CSXRC | BMS500-AAU012-1AHDXB | | 9,300 | $465 |
| No | 207760000 | BOSCH | BMS500-AAS009-1CSXRC | BMS500-AAU009-1AHDXB | | 7,700 | $385 |
| No | 211635160 | BOSCH | BOVA-36HDN1-M15G | BMAC4248CNTF | BGH96M100C5B | 23,000 | $1,150 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211635159 | BOSCH | BOVA-36HDN1-M15G | BMAC4248BNTF | BGH96M080B3B | 23,000 | $1,150 |
| No | 207454652 | BOSCH | BOVB-36HDN1-M18M | BMA*3036ANTD | BGH96M060B3B | 23,000 | $1,150 |
| No | 207454653 | BOSCH | BOVB-36HDN1-M18M | BMA*3036ANTD | BGH96M080B3B | 23,000 | $1,150 |
| No | 207454654 | BOSCH | BOVB-36HDN1-M18M | BMA*3036BNTD | BGH96M060B3B | 23,000 | $1,150 |
| No | 207454655 | BOSCH | BOVB-36HDN1-M18M | BMA*3036BNTD | BGH96M080B3B | 23,000 | $1,150 |
| No | 207454656 | BOSCH | BOVB-36HDN1-M18M | BMA*3036CNTD | BGH96M080C4B | 23,000 | $1,150 |
| No | 207454657 | BOSCH | BOVB-36HDN1-M18M | BMA*3036CNTD | BGH96M100C5B | 23,000 | $1,150 |
| No | 207454658 | BOSCH | BOVB-36HDN1-M18M | BMA*2430ANTD | BGH96M060B3B | 21,600 | $1,080 |
| No | 207454659 | BOSCH | BOVB-36HDN1-M18M | BMA*2430ANTD | BGH96M080B3B | 21,600 | $1,080 |
| No | 207454660 | BOSCH | BOVB-36HDN1-M18M | BMA*2430BNTD | BGH96M060B3B | 21,600 | $1,080 |
| No | 207454661 | BOSCH | BOVB-36HDN1-M18M | BMA*2430BNTD | BGH96M080B3B | 21,600 | $1,080 |
| No | 207454662 | BOSCH | BOVB-60HDN1-M18M | BMA*4248BNTF | BGH96M080B3B | 33,000 | $1,650 |
| No | 207454663 | BOSCH | BOVB-60HDN1-M18M | BMA*4248CNTF | BGH96M080C4B | 33,000 | $1,650 |
| No | 207454664 | BOSCH | BOVB-60HDN1-M18M | BMA*4248CNTF | BGH96M100C5B | 34,000 | $1,700 |
| No | 207454665 | BOSCH | BOVB-60HDN1-M18M | BMA*4248DNTF | BGH96M100D5B | 34,200 | $1,710 |
| No | 207454666 | BOSCH | BOVB-60HDN1-M18M | BMA*4248DNTF | BGH96M120D5B | 34,200 | $1,710 |
| No | 207454667 | BOSCH | BOVB-60HDN1-M18M | BMA*4860CNTF | BGH96M100C5B | 37,200 | $1,860 |
| No | 207454668 | BOSCH | BOVB-60HDN1-M18M | BMA*4860DNTF | BGH96M100D5B | 37,400 | $1,870 |
| No | 207454669 | BOSCH | BOVB-60HDN1-M18M | BMA*4860DNTF | BGH96M120D5B | 37,400 | $1,870 |
| No | 207658575 | BOSCH | BOVB-60HDN1-M20G | BMA*4860DNTF | BGH96M120D5B | 38,500 | $1,925 |
| No | 207658574 | BOSCH | BOVB-60HDN1-M20G | BMA*4860DNTF | BGH96M100D5B | 38,500 | $1,925 |
| No | 207658573 | BOSCH | BOVB-60HDN1-M20G | BMA*4248DNTF | BGH96M120D5B | 35,600 | $1,780 |
| No | 207658571 | BOSCH | BOVB-60HDN1-M20G | BMA*4248CNTF | BGH96M100C5B | 35,600 | $1,780 |
| No | 207658570 | BOSCH | BOVB-36HDN1-M20G | BMA*4248CNTF | BGH96M100C5B | 25,600 | $1,280 |
| No | 207658572 | BOSCH | BOVB-60HDN1-M20G | BMA*4248DNTF | BGH96M100D5B | 35,600 | $1,780 |
| No | 207658569 | BOSCH | BOVB-36HDN1-M20G | BMA*4248BNTF | BGH96M080B3B | 26,000 | $1,300 |
| No | 207658568 | BOSCH | BOVB-36HDN1-M20G | BMA*2430BNTD | BGH96M080B3B | 20,000 | $1,000 |
| No | 207658565 | BOSCH | BOVB-60HDN1-M20G | BMA*4860CNTF | BGH96M100C5B | 37,000 | $1,850 |
| No | 207658567 | BOSCH | BOVB-36HDN1-M20G | BMA*2430BNTD | BGH96M060B3B | 20,000 | $1,000 |
| No | 207658566 | BOSCH | BOVB-36HDN1-M20G | BMA*2430ANTD | BGH96M080B3B | 19,600 | $980 |
| No | 207658564 | BOSCH | BOVB-60HDN1-M20G | BMA*4248CNTF | BGH96M080C4B | 35,000 | $1,750 |
| No | 207658562 | BOSCH | BOVB-36HDN1-M20G | BMA*3036CNTD | BGH96M100C5B | 25,000 | $1,250 |
| No | 207658561 | BOSCH | BOVB-36HDN1-M20G | BMA*3036CNTD | BGH96M080C4B | 25,000 | $1,250 |
| No | 207658542 | BOSCH | BOVB-36HDN1-M20G | BMA*3036BNTD | BGH96M080B3B | 25,000 | $1,250 |
| No | 207658541 | BOSCH | BOVB-36HDN1-M20G | BMA*3036BNTD | BGH96M060B3B | 25,000 | $1,250 |
| No | 207658540 | BOSCH | BOVB-36HDN1-M20G | BMA*3036ANTD | BGH96M080B3B | 25,000 | $1,250 |
| No | 207658539 | BOSCH | BOVB-36HDN1-M20G | BMA*3036ANTD | BGH96M060B3B | 25,000 | $1,250 |
| No | 207658538 | BOSCH | BOVB-36HDN1-M20G | BMA*2430ANTD | BGH96M060B3B | 19,600 | $980 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207658525 | BOSCH | BOVB-60HDN1-M20G | BVA-60WN1-M20 | | 43,500 | $2,175 |
| No | 207658524 | BOSCH | BOVB-36HDN1-M20G | BVA-36WN1-M20 | | 28,000 | $1,400 |
| No | 207658523 | BOSCH | BOVB-60HDN1-M20G | BVA-48WN1-M20 | | 40,000 | $2,000 |
| No | 207658522 | BOSCH | BOVB-36HDN1-M20G | BVA-24WN1-M20 | | 22,400 | $1,120 |
| No | 207658535 | BOSCH | BOVB-60HDN1-M20G | BMA*4860DNTF | | 39,000 | $1,950 |
| No | 207658534 | BOSCH | BOVB-60HDN1-M20G | BMA*4860CNTF | | 38,000 | $1,900 |
| No | 207658532 | BOSCH | BOVB-60HDN1-M20G | BMA*4248CNTF | | 33,000 | $1,650 |
| No | 207658533 | BOSCH | BOVB-60HDN1-M20G | BMA*4248DNTF | | 33,200 | $1,660 |
| No | 207658531 | BOSCH | BOVB-60HDN1-M20G | BMA*4248BNTF | | 33,000 | $1,650 |
| No | 207658530 | BOSCH | BOVB-36HDN1-M20G | BMA*3036CNTD | | 23,000 | $1,150 |
| No | 207658529 | BOSCH | BOVB-36HDN1-M20G | BMA*3036BNTD | | 23,000 | $1,150 |
| No | 207658527 | BOSCH | BOVB-36HDN1-M20G | BMA*2430BNTD | | 18,000 | $900 |
| No | 207658526 | BOSCH | BOVB-36HDN1-M20G | BMA*2430ANTD | | 18,000 | $900 |
| No | 207658528 | BOSCH | BOVB-36HDN1-M20G | BMA*3036ANTD | | 22,000 | $1,100 |
| No | 207454651 | BOSCH | BOVA-60HDN1-M20G | BMA*4860DNTF | BGH96M120D5B | 38,500 | $1,925 |
| No | 207454650 | BOSCH | BOVA-60HDN1-M20G | BMA*4860DNTF | BGH96M100D5B | 38,500 | $1,925 |
| No | 207454649 | BOSCH | BOVA-60HDN1-M20G | BMA*4248DNTF | BGH96M120D5B | 35,600 | $1,780 |
| No | 207454647 | BOSCH | BOVA-60HDN1-M20G | BMA*4248CNTF | BGH96M100C5B | 35,600 | $1,780 |
| No | 207454646 | BOSCH | BOVA-36HDN1-M20G | BMA*4248CNTF | BGH96M100C5B | 25,600 | $1,280 |
| No | 207454648 | BOSCH | BOVA-60HDN1-M20G | BMA*4248DNTF | BGH96M100D5B | 35,600 | $1,780 |
| No | 207454645 | BOSCH | BOVA-36HDN1-M20G | BMA*4248BNTF | BGH96M080B3B | 26,000 | $1,300 |
| No | 207454644 | BOSCH | BOVA-36HDN1-M20G | BMA*2430BNTD | BGH96M080B3B | 20,000 | $1,000 |
| No | 207454641 | BOSCH | BOVA-60HDN1-M20G | BMA*4860CNTF | BGH96M100C5B | 37,000 | $1,850 |
| No | 207454643 | BOSCH | BOVA-36HDN1-M20G | BMA*2430BNTD | BGH96M060B3B | 20,000 | $1,000 |
| No | 207454642 | BOSCH | BOVA-36HDN1-M20G | BMA*2430ANTD | BGH96M080B3B | 19,600 | $980 |
| No | 207454640 | BOSCH | BOVA-60HDN1-M20G | BMA*4248CNTF | BGH96M080C4B | 35,000 | $1,750 |
| No | 207454638 | BOSCH | BOVA-36HDN1-M20G | BMA*3036CNTD | BGH96M100C5B | 25,000 | $1,250 |
| No | 207454637 | BOSCH | BOVA-36HDN1-M20G | BMA*3036CNTD | BGH96M080C4B | 25,000 | $1,250 |
| No | 207454636 | BOSCH | BOVA-36HDN1-M20G | BMA*3036BNTD | BGH96M080B3B | 25,000 | $1,250 |
| No | 207454635 | BOSCH | BOVA-36HDN1-M20G | BMA*3036BNTD | BGH96M060B3B | 25,000 | $1,250 |
| No | 207454634 | BOSCH | BOVA-36HDN1-M20G | BMA*3036ANTD | BGH96M080B3B | 25,000 | $1,250 |
| No | 207454633 | BOSCH | BOVA-36HDN1-M20G | BMA*3036ANTD | BGH96M060B3B | 25,000 | $1,250 |
| No | 207454632 | BOSCH | BOVA-36HDN1-M20G | BMA*2430ANTD | BGH96M060B3B | 19,600 | $980 |
| No | 208128219 | BOSCH | BOVA-24HDN1-M15G | BVA-24WN1-M15 | | 20,000 | $1,000 |
| No | 208128225 | BOSCH | BOVA-36HDN1-M15G | BVA-24WN1-M15 | | 20,500 | $1,025 |
| No | 208128226 | BOSCH | BOVA-36HDN1-M15G | BVA-36WN1-M15 | | 25,000 | $1,250 |
| No | 208128243 | BOSCH | BOVA-60HDN1-M15G | BVA-48WN1-M15 | | 38,000 | $1,900 |
| No | 208128244 | BOSCH | BOVA-60HDN1-M15G | BVA-60WN1-M15 | | 40,500 | $2,025 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208128218 | BOSCH | BOVA-24HDN1-M15G | BVA-24WN1-M20 | | 19,500 | $975 |
| No | 208128227 | BOSCH | BOVA-36HDN1-M15G | BVA-24WN1-M20 | | 21,000 | $1,050 |
| No | 208128224 | BOSCH | BOVA-36HDN1-M15G | BVA-36WN1-M20 | | 24,500 | $1,225 |
| No | 208128246 | BOSCH | BOVA-60HDN1-M15G | BVA-48WN1-M20 | | 38,000 | $1,900 |
| No | 208128234 | BOSCH | BOVA-60HDN1-M15G | BVA-60WN1-M20 | | 40,000 | $2,000 |
| No | 208546461 | BOSCH | BOVA-24HDN1-M15G | BMAC2430ANTD | BGH96M060B3B | 17,600 | $880 |
| No | 208546462 | BOSCH | BOVA-24HDN1-M15G | BMAC2430ANTD | BGH96M080B3B | 17,600 | $880 |
| No | 208546463 | BOSCH | BOVA-24HDN1-M15G | BMAC2430BNTD | BGH96M060B3B | 17,600 | $880 |
| No | 208546464 | BOSCH | BOVA-24HDN1-M15G | BMAC2430BNTD | BGH96M080B3B | 17,600 | $880 |
| No | 208546476 | BOSCH | BOVA-60HDN1-M15G | BMAC4860CNTF | BGH96M100C5B | 38,000 | $1,900 |
| No | 208546477 | BOSCH | BOVA-60HDN1-M15G | BMAC4860DNTF | BGH96M100D5B | 38,000 | $1,900 |
| No | 208546478 | BOSCH | BOVA-60HDN1-M15G | BMAC4860DNTF | BGH96M120D5B | 38,000 | $1,900 |
| No | 207760016 | BOSCH | BMS500-AAS018-1CSXHC | BMS500-AAU018-1AHCXB | | 15,600 | $780 |
| No | 207760013 | BOSCH | BMS500-AAS009-1CSXHC | BMS500-AAU009-1AHCXB | | 9,000 | $450 |
| No | 207760015 | BOSCH | BMS500-AAS018-1CSXRC | BMS500-AAU018-1AHCXB | | 12,000 | $600 |
| No | 207760006 | BOSCH | BMS500-AAS024-1CSXRC | BMS500-AAU024-1AHDXB | | 20,000 | $1,000 |
| No | 207760017 | BOSCH | BMS500-AAS024-1CSXRC | BMS500-AAU024-1AHCXC | | 19,000 | $950 |
| No | 207760010 | BOSCH | BMS500-AAS048-1CSXLC | BMS500-AAU048-1AHDXB | | 34,000 | $1,700 |
| No | 207760020 | BOSCH | BMS500-AAS048-1CSXLC | BMS500-AAU048-1AHCXC | | 30,000 | $1,500 |
| No | 203991165 | BOSCH | BMS500-AAS060-1CSXLB | BMS500-AAU060-1AHDXB | | 34,400 | $1,720 |
| No | 203991178 | BOSCH | BMS500-AAM048-1CSXRA | Heat pump without ducts | | 28,400 | $1,420 |
| No | 203991172 | BOSCH | BMS500-AAM018-1CSXRA | Heat pump without ducts | | 11,800 | $590 |
| No | 203991186 | BOSCH | BMS500-AAM036-1CSXHB | Heat pump without ducts | | 16,800 | $840 |
| No | 203991174 | BOSCH | BMS500-AAM027-1CSXRA | Heat pump without ducts | | 17,200 | $860 |
| No | 203991164 | BOSCH | BMS500-AAS048-1CSXLB | BMS500-AAU048-1AHDXB | | 34,000 | $1,700 |
| No | 203991161 | BOSCH | BMS500-AAS018-1CSXRA | BMS500-AAU018-1AHDXB | | 11,600 | $580 |
| No | 203991163 | BOSCH | BMS500-AAS036-1CSXLB | BMS500-AAU036-1AHDXB | | 25,000 | $1,250 |
| No | 204014468 | BOSCH | BMS500-AAS012-1CSXHB | BMS500-AAU012-1AHDXB | | 10,600 | $530 |
| No | 203991162 | BOSCH | BMS500-AAS024-1CSXRA | BMS500-AAU024-1AHDXB | | 18,000 | $900 |
| No | 203991159 | BOSCH | BMS500-AAS009-1CSXRA | BMS500-AAU009-1AHDXB | | 8,000 | $400 |
| No | 204014467 | BOSCH | BMS500-AAS009-1CSXHB | BMS500-AAU009-1AHDXB | | 10,100 | $505 |
| No | 203991147 | BOSCH | BMS500-AAS012-0CSXRB | BMS500-AAS012-0AHWXB | | 7,600 | $380 |
| No | 203991168 | BOSCH | BMS500-AAS018-1CSXRA | BMS500-AAU018-1AHCXB | | 12,000 | $600 |
| No | 203991170 | BOSCH | BMS500-AAS036-1CSXLB | BMS500-AAU036-1AHCXB | | 24,000 | $1,200 |
| No | 204014465 | BOSCH | BMS500-AAS012-1CSXHB | BMS500-AAU012-1AHCXB | | 8,700 | $435 |
| No | 203991148 | BOSCH | BMS500-AAS009-1CSXRA | BMS500-AAU009-1AHWXB | | 5,800 | $290 |
| No | 203991152 | BOSCH | BMS500-AAS009-1CSXHB | BMS500-AAU009-1AHWXB | | 6,900 | $345 |
| No | 203991171 | BOSCH | BMS500-AAS048-1CSXLB | BMS500-AAU048-1AHCXB | | 35,000 | $1,750 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203991149 | BOSCH | BMS500-AAS012-1CSXRA | BMS500-AAU012-1AHWXB | | 7,700 | $385 |
| No | 203991153 | BOSCH | BMS500-AAS012-1CSXHB | BMS500-AAU012-1AHWXB | | 7,800 | $390 |
| No | 203991151 | BOSCH | BMS500-AAS024-1CSXRA | BMS500-AAU024-1AHWXB | | 15,300 | $765 |
| No | 203377012 | BOSCH | BOVA-36HDN1-M20G | BMA*3036ANTD | | 22,000 | $1,100 |
| No | 203377010 | BOSCH | BOVA-36HDN1-M20G | BMA*2430ANTD | | 18,000 | $900 |
| No | 203377011 | BOSCH | BOVA-36HDN1-M20G | BMA*2430BNTD | | 18,000 | $900 |
| No | 203377013 | BOSCH | BOVA-36HDN1-M20G | BMA*3036BNTD | | 23,000 | $1,150 |
| No | 203377014 | BOSCH | BOVA-36HDN1-M20G | BMA*3036CNTD | | 23,000 | $1,150 |
| No | 203377015 | BOSCH | BOVA-60HDN1-M20G | BMA*4248BNTF | | 33,000 | $1,650 |
| No | 203377017 | BOSCH | BOVA-60HDN1-M20G | BMA*4248DNTF | | 33,200 | $1,660 |
| No | 203377016 | BOSCH | BOVA-60HDN1-M20G | BMA*4248CNTF | | 33,000 | $1,650 |
| No | 203377018 | BOSCH | BOVA-60HDN1-M20G | BMA*4860CNTF | | 38,000 | $1,900 |
| No | 203377019 | BOSCH | BOVA-60HDN1-M20G | BMA*4860DNTF | | 39,000 | $1,950 |
| No | 202868494 | BOSCH | BOVA-36HDN1-M20G | BVA-24WN1-M20 | | 22,400 | $1,120 |
| No | 202868495 | BOSCH | BOVA-60HDN1-M20G | BVA-48WN1-M20 | | 40,000 | $2,000 |
| No | 202868496 | BOSCH | BOVA-36HDN1-M20G | BVA-36WN1-M20 | | 28,000 | $1,400 |
| No | 202868497 | BOSCH | BOVA-60HDN1-M20G | BVA-60WN1-M20 | | 43,500 | $2,175 |
| No | 203024976 | BOSCH | BOVA-36HDN1-M20G | BMA*2430ANTD | BGH96M060B3A | 19,600 | $980 |
| No | 203024978 | BOSCH | BOVA-36HDN1-M20G | BMA*3036ANTD | BGH96M060B3A | 25,000 | $1,250 |
| No | 203024981 | BOSCH | BOVA-36HDN1-M20G | BMA*3036ANTD | BGH96M080B3A | 25,000 | $1,250 |
| No | 203024984 | BOSCH | BOVA-36HDN1-M20G | BMA*3036BNTD | BGH96M060B3A | 25,000 | $1,250 |
| No | 203024986 | BOSCH | BOVA-36HDN1-M20G | BMA*3036BNTD | BGH96M080B3A | 25,000 | $1,250 |
| No | 203024989 | BOSCH | BOVA-36HDN1-M20G | BMA*3036CNTD | BGH96M080C4A | 25,000 | $1,250 |
| No | 203024992 | BOSCH | BOVA-36HDN1-M20G | BMA*3036CNTD | BGH96M100C5A | 25,000 | $1,250 |
| No | 203024998 | BOSCH | BOVA-60HDN1-M20G | BMA*4248CNTF | BGH96M080C4A | 35,000 | $1,750 |
| No | 203025005 | BOSCH | BOVA-36HDN1-M20G | BMA*2430ANTD | BGH96M080B3A | 19,600 | $980 |
| No | 203025008 | BOSCH | BOVA-36HDN1-M20G | BMA*2430BNTD | BGH96M060B3A | 20,000 | $1,000 |
| No | 203025001 | BOSCH | BOVA-60HDN1-M20G | BMA*4860CNTF | BGH96M100C5A | 37,000 | $1,850 |
| No | 203025011 | BOSCH | BOVA-36HDN1-M20G | BMA*2430BNTD | BGH96M080B3A | 20,000 | $1,000 |
| No | 203025014 | BOSCH | BOVA-36HDN1-M20G | BMA*4248BNTF | BGH96M080B3A | 26,000 | $1,300 |
| No | 203025023 | BOSCH | BOVA-60HDN1-M20G | BMA*4248DNTF | BGH96M100D5A | 35,600 | $1,780 |
| No | 203025017 | BOSCH | BOVA-36HDN1-M20G | BMA*4248CNTF | BGH96M100C5A | 25,600 | $1,280 |
| No | 203025020 | BOSCH | BOVA-60HDN1-M20G | BMA*4248CNTF | BGH96M100C5A | 35,600 | $1,780 |
| No | 203025026 | BOSCH | BOVA-60HDN1-M20G | BMA*4248DNTF | BGH96M120D5A | 35,600 | $1,780 |
| No | 203025029 | BOSCH | BOVA-60HDN1-M20G | BMA*4860DNTF | BGH96M100D5A | 38,500 | $1,925 |
| No | 203025032 | BOSCH | BOVA-60HDN1-M20G | BMA*4860DNTF | BGH96M120D5A | 38,500 | $1,925 |
| No | 205921394 | BOSCH | BMS500-AAS012-1CSXXA | BMS500-AAU012-1AHWXB | | 7,700 | $385 |
| No | 206395998 | BOSCH | BOVB-60HDN1-M18M | BVA-60WN1-M15 | | 40,500 | $2,025 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206395997 | BOSCH | BOVB-60HDN1-M18M | BVA-48WN1-M15 | | 38,000 | $1,900 |
| No | 206396004 | BOSCH | BOVB-60HDN1-M18M | BMA*4248CNTF | | 33,000 | $1,650 |
| No | 206396002 | BOSCH | BOVB-60HDN1-M18M | BMA*4248BNTF | | 32,800 | $1,640 |
| No | 206396003 | BOSCH | BOVB-60HDN1-M18M | BMA*4860CNTF | | 37,000 | $1,850 |
| No | 206396005 | BOSCH | BOVB-60HDN1-M18M | BMA*4248DNTF | | 33,000 | $1,650 |
| No | 206396006 | BOSCH | BOVB-60HDN1-M18M | BMA*4860DNTF | | 37,400 | $1,870 |
| No | 206395994 | BOSCH | BOVB-60HDN1-M18M | BMA*4860CNTF | BGH96M100C5A | 37,200 | $1,860 |
| No | 206396000 | BOSCH | BOVB-60HDN1-M18M | BVA-60WN1-M20 | | 40,500 | $2,025 |
| No | 206395999 | BOSCH | BOVB-60HDN1-M18M | BVA-48WN1-M20 | | 38,000 | $1,900 |
| No | 206395995 | BOSCH | BOVB-60HDN1-M18M | BMA*4860DNTF | BGH96M100D5A | 37,400 | $1,870 |
| No | 206395991 | BOSCH | BOVB-60HDN1-M18M | BMA*4248CNTF | BGH96M100C5A | 34,000 | $1,700 |
| No | 206395993 | BOSCH | BOVB-60HDN1-M18M | BMA*4248DNTF | BGH96M120D5A | 34,200 | $1,710 |
| No | 206395990 | BOSCH | BOVB-60HDN1-M18M | BMA*4248CNTF | BGH96M080C4A | 33,000 | $1,650 |
| No | 206395989 | BOSCH | BOVB-60HDN1-M18M | BMA*4248BNTF | BGH96M080B3A | 33,000 | $1,650 |
| No | 206395987 | BOSCH | BOVB-36HDN1-M18M | BMA*2430BNTD | BGH96M080B3A | 17,200 | $860 |
| No | 206395986 | BOSCH | BOVB-36HDN1-M18M | BMA*2430BNTD | BGH96M060B3A | 17,200 | $860 |
| No | 206395992 | BOSCH | BOVB-60HDN1-M18M | BMA*4248DNTF | BGH96M100D5A | 34,200 | $1,710 |
| No | 206395985 | BOSCH | BOVB-36HDN1-M18M | BMA*2430ANTD | BGH96M080B3A | 17,200 | $860 |
| No | 206395984 | BOSCH | BOVB-36HDN1-M18M | BMA*2430ANTD | BGH96M060B3A | 17,200 | $860 |
| No | 206395976 | BOSCH | BOVB-36HDN1-M18M | BVA-36WN1-M20 | | 25,000 | $1,250 |
| No | 206395973 | BOSCH | BOVB-36HDN1-M18M | BVA-24WN1-M15 | | 21,200 | $1,060 |
| No | 206395974 | BOSCH | BOVB-36HDN1-M18M | BVA-36WN1-M15 | | 25,000 | $1,250 |
| No | 206395975 | BOSCH | BOVB-36HDN1-M18M | BVA-24WN1-M20 | | 21,000 | $1,050 |
| No | 206395972 | BOSCH | BOVB-36HDN1-M18M | BMA*3036CNTD | BGH96M100C5A | 23,000 | $1,150 |
| No | 206395969 | BOSCH | BOVB-36HDN1-M18M | BMA*3036BNTD | BGH96M060B3A | 23,000 | $1,150 |
| No | 206395971 | BOSCH | BOVB-36HDN1-M18M | BMA*3036CNTD | BGH96M080C4A | 23,000 | $1,150 |
| No | 206395970 | BOSCH | BOVB-36HDN1-M18M | BMA*3036BNTD | BGH96M080B3A | 23,000 | $1,150 |
| No | 206395968 | BOSCH | BOVB-36HDN1-M18M | BMA*3036ANTD | BGH96M080B3A | 22,600 | $1,130 |
| No | 206395967 | BOSCH | BOVB-36HDN1-M18M | BMA*3036ANTD | BGH96M060B3A | 22,600 | $1,130 |
| No | 206395996 | BOSCH | BOVB-60HDN1-M18M | BMA*4860DNTF | BGH96M120D5A | 37,400 | $1,870 |
| No | 206396001 | BOSCH | BOVB-60HDN1-M18M | BVA-36WN1-M20 | | 25,000 | $1,250 |
| No | 9966844 | BOSCH | BMS500-AAS024-1CSXXA | BMS500-AAU024-1AHXXA | | 16,000 | $800 |
| No | 9966839 | BOSCH | BMS500-AAS012-0CSXXA | BMS500-AAU012-0AHXXA | | 7,500 | $375 |
| No | 9966838 | BOSCH | BMS500-AAS009-1CSXXA | BMS500-AAU009-1AHXXA | | 6,300 | $315 |
| No | 9966843 | BOSCH | BMS500-AAS018-1CSXXA | BMS500-AAU018-1AHXXA | | 11,100 | $555 |
| No | 9966837 | BOSCH | BMS500-AAS009-0CSXXA | BMS500-AAU009-0AHXXA | | 5,800 | $290 |
| No | 208650710 | BOSCH | BMS500-AAS009-1CSXRC | BMS500-AAU009-1AHWXB | | 6,100 | $305 |
| No | 208650711 | BOSCH | BMS500-AAS012-1CSXRC | BMS500-AAU012-1AHWXB | | 8,000 | $400 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208650712 | BOSCH | BMS500-AAS018-1CSXRC | BMS500-AAU018-1AHWXB | | 12,700 | $635 |
| No | 208650713 | BOSCH | BMS500-AAS024-1CSXRC | BMS500-AAU024-1AHWXB | | 14,200 | $710 |
| No | 207759994 | BOSCH | BMS500-AAS009-1CSXHC | BMS500-AAU009-1AHWXC | | 7,500 | $375 |
| No | 208157116 | BOSCH | BMS500-AAS009-1CSXHC | BMS500-AAU009-1AHWXB | | 7,100 | $355 |
| No | 208157117 | BOSCH | BMS500-AAS012-1CSXHC | BMS500-AAU012-1AHWXB | | 7,500 | $375 |
| No | 208157118 | BOSCH | BMS500-AAS018-1CSXHC | BMS500-AAU018-1AHWXB | | 10,900 | $545 |
| No | 207759999 | BOSCH | BMS500-AAS036-1CSXRC | BMS500-AAU036-1AHWXC | | 22,400 | $1,120 |
| No | 206395966 | BOSCH | BOVB-36HDN1-M18M | BVA-36WN1-M18B | | 25,000 | $1,250 |
| No | 206395964 | BOSCH | BOVB-36HDN1-M18M | BVA-24WN1-M18 | | 21,600 | $1,080 |
| No | 206395977 | BOSCH | BOVB-36HDN1-M18M | BMA*2430ANTD | | 17,200 | $860 |
| No | 206395978 | BOSCH | BOVB-36HDN1-M18M | BMA*2430BNTD | | 17,200 | $860 |
| No | 206395982 | BOSCH | BOVB-36HDN1-M18M | BMA*4248BNTF | | 23,000 | $1,150 |
| No | 206395983 | BOSCH | BOVB-36HDN1-M18M | BMA*4248CNTF | | 23,000 | $1,150 |
| No | 206395965 | BOSCH | BOVB-60HDN1-M18M | BVA-48WN1-M18 | | 38,000 | $1,900 |
| No | 206395988 | BOSCH | BOVB-60HDN1-M18M | BVA-60WN1-M18 | | 40,000 | $2,000 |
| No | 206396007 | BOSCH | BOVB-60HDN1-M18M | BVA-36WN1-M18B | | 24,000 | $1,200 |
| No | 206331368 | BOSCH | BOVA-36HDN1-M18M | BVA-24WN1-M15 | | 21,200 | $1,060 |
| No | 206331370 | BOSCH | BOVA-60HDN1-M18M | BVA-48WN1-M15 | | 38,000 | $1,900 |
| No | 206331369 | BOSCH | BOVA-36HDN1-M18M | BVA-36WN1-M15 | | 25,000 | $1,250 |
| No | 206331371 | BOSCH | BOVA-60HDN1-M18M | BVA-60WN1-M15 | | 40,500 | $2,025 |
| No | 202534085 | BOSCH | BOVA-36HDN1-M18M | BMA*2430ANTD | BGH96M060B3A | 17,200 | $860 |
| No | 202534086 | BOSCH | BOVA-36HDN1-M18M | BMA*2430ANTD | BGH96M080B3A | 17,200 | $860 |
| No | 202534087 | BOSCH | BOVA-36HDN1-M18M | BMA*2430BNTD | BGH96M060B3A | 17,200 | $860 |
| No | 202534088 | BOSCH | BOVA-36HDN1-M18M | BMA*2430BNTD | BGH96M080B3A | 17,200 | $860 |
| No | 202534100 | BOSCH | BOVA-60HDN1-M18M | BMA*4860CNTF | BGH96M100C5A | 37,000 | $1,850 |
| No | 202534102 | BOSCH | BOVA-60HDN1-M18M | BMA*4860DNTF | BGH96M120D5A | 38,000 | $1,900 |
| No | 202534101 | BOSCH | BOVA-60HDN1-M18M | BMA*4860DNTF | BGH96M100D5A | 38,000 | $1,900 |
| No | 202534099 | BOSCH | BOVA-60HDN1-M18M | BMA*4248DNTF | BGH96M120D5A | 32,000 | $1,600 |
| No | 202534098 | BOSCH | BOVA-60HDN1-M18M | BMA*4248DNTF | BGH96M100D5A | 32,000 | $1,600 |
| No | 202534097 | BOSCH | BOVA-60HDN1-M18M | BMA*4248CNTF | BGH96M100C5A | 31,400 | $1,570 |
| No | 202534096 | BOSCH | BOVA-60HDN1-M18M | BMA*4248CNTF | BGH96M080C4A | 31,000 | $1,550 |
| No | 202534095 | BOSCH | BOVA-60HDN1-M18M | BMA*4248BNTF | BGH96M080B3A | 31,000 | $1,550 |
| No | 202534094 | BOSCH | BOVA-36HDN1-M18M | BMA*3036CNTD | BGH96M100C5A | 23,000 | $1,150 |
| No | 202534093 | BOSCH | BOVA-36HDN1-M18M | BMA*3036CNTD | BGH96M080C4A | 23,000 | $1,150 |
| No | 202534092 | BOSCH | BOVA-36HDN1-M18M | BMA*3036BNTD | BGH96M080B3A | 23,000 | $1,150 |
| No | 202534091 | BOSCH | BOVA-36HDN1-M18M | BMA*3036BNTD | BGH96M060B3A | 23,000 | $1,150 |
| No | 202534090 | BOSCH | BOVA-36HDN1-M18M | BMA*3036ANTD | BGH96M080B3A | 22,600 | $1,130 |
| No | 202534089 | BOSCH | BOVA-36HDN1-M18M | BMA*3036ANTD | BGH96M060B3A | 22,600 | $1,130 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202337988 | BOSCH | BOVA-60HDN1-M18M | BMA*4248DNTF | BGS80M120D5A | 31,000 | $1,550 |
| No | 202337987 | BOSCH | BOVA-60HDN1-M18M | BMA*4860DNTF | BGS80M120D5A | 36,000 | $1,800 |
| No | 202337986 | BOSCH | BOVA-60HDN1-M18M | BMA*4860CNTF | BGS80M100C5A | 35,000 | $1,750 |
| No | 202337985 | BOSCH | BOVA-60HDN1-M18M | BMA*4248CNTF | BGS80M100C5A | 31,000 | $1,550 |
| No | 202337984 | BOSCH | BOVA-60HDN1-M18M | BMA*4248BNTF | BGS80M080B4A | 30,000 | $1,500 |
| No | 8860512 | BOSCH | BOVA-36HDN1-M18M | BVA-36WN1-M18B | | 24,000 | $1,200 |
| No | 8860511 | BOSCH | BOVA-60HDN1-M18M | BVA-60WN1-M18 | | 40,000 | $2,000 |
| No | 8860510 | BOSCH | BOVA-60HDN1-M18M | BVA-48WN1-M18 | | 35,000 | $1,750 |
| No | 8860508 | BOSCH | BOVA-36HDN1-M18M | BVA-24WN1-M18 | | 19,000 | $950 |
| No | 10021152 | BOSCH | BOVA-60HDN1-M18M | BMA*4860DNTF | | 39,000 | $1,950 |
| No | 10021151 | BOSCH | BOVA-60HDN1-M18M | BMA*4860CNTF | | 32,000 | $1,600 |
| No | 10021149 | BOSCH | BOVA-60HDN1-M18M | BMA*4248CNTF | | 32,000 | $1,600 |
| No | 10021148 | BOSCH | BOVA-60HDN1-M18M | BMA*4248BNTF | | 31,000 | $1,550 |
| No | 10021144 | BOSCH | BOVA-36HDN1-M18M | BMA*2430BNTD | | 17,200 | $860 |
| No | 10021150 | BOSCH | BOVA-60HDN1-M18M | BMA*4248DNTF | | 32,000 | $1,600 |
| No | 10021143 | BOSCH | BOVA-36HDN1-M18M | BMA*2430ANTD | | 17,200 | $860 |
| No | 204427507 | BOSCH | BOVA-36HDN1-M18M | BMA*4248CNTF | | 23,000 | $1,150 |
| No | 204396671 | BOSCH | BOVA-36HDN1-M18M | BMA*4248BNTF | | 23,000 | $1,150 |
| No | 203991167 | BOSCH | BMS500-AAS012-1CSXRA | BMS500-AAU012-1AHCXB | | 7,500 | $375 |
| No | 203991169 | BOSCH | BMS500-AAS024-1CSXRA | BMS500-AAU024-1AHCXB | | 15,800 | $790 |
| No | 203991166 | BOSCH | BMS500-AAS009-1CSXRA | BMS500-AAU009-1AHCXB | | 5,800 | $290 |
| No | 203991150 | BOSCH | BMS500-AAS018-1CSXRA | BMS500-AAU018-1AHWXB | | 11,400 | $570 |
| No | 203991187 | BOSCH | BMS500-AAM036-1CSXHB | Heat pump with ducts | | 24,600 | $1,230 |
| No | 203991176 | BOSCH | BMS500-AAM036-1CSXRA | Heat pump without ducts | | 24,600 | $1,230 |
| No | 211273235 | Breeze33 | BZ33-HYP12OUT2-G2-P | BZ33-OWCASS12-G2-P | | 9,500 | $475 |
| No | 211277585 | Breeze33 | HSZ12H424ZMO | SCA12H424ZMI | | 9,500 | $475 |
| No | 211277582 | Breeze33 | HSZ9H424ZMO | SCA9H424ZMI | | 9,800 | $490 |
| No | 211277591 | Breeze33 | HSZ18H424ZMO | C18H424ZMI | | 14,700 | $735 |
| No | 211277587 | Breeze33 | HSZ12H424ZMO | C12H424ZMI | | 10,200 | $510 |
| No | 211277588 | Breeze33 | HSZ18H424ZMO | CA18H424ZMI | | 15,600 | $780 |
| No | 211277592 | Breeze33 | HSZ18H424ZMO | FC18H424ZMI | | 12,000 | $600 |
| No | 211277586 | Breeze33 | HSZ12H424ZMO | D12H424ZMI | | 10,600 | $530 |
| No | 211277584 | Breeze33 | HSZ12H424ZMO | CA12H424ZMI | | 9,900 | $495 |
| No | 211277583 | Breeze33 | HSZ9H424ZMO | D9H424ZMI | | 10,100 | $505 |
| No | 207862095 | BREEZE33 | BZ33-HP485Z2-G2-P | Heat pump without ducts | | 34,000 | $1,700 |
| No | 207862092 | BREEZE33 | BZ33-HP364Z2-G2-P | Heat pump without ducts | | 26,800 | $1,340 |
| No | 211257122 | Breeze33 | BZ33-HYP09OUT2-G2-P | BZ33-OWCASS09-G2-P | | 9,800 | $490 |
| No | 207862086 | BREEZE33 | BZ33-HP182Z2-G2-P | Heat pump without ducts | | 14,300 | $715 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207862090 | BREEZE33 | BZ33-HP273Z2-G2-P | Heat pump with ducts | | 22,000 | $1,100 |
| No | 207862087 | BREEZE33 | BZ33-HP182Z2-G2-P | Heat pump with ducts | | 14,800 | $740 |
| No | 207862089 | BREEZE33 | BZ33-HP273Z2-G2-P | Heat pump without ducts | | 21,000 | $1,050 |
| No | 207862065 | Breeze33 | BZ33-HP18OUT2-G2-C | BZ33-HP18WALL2-G2-C | | 11,500 | $575 |
| No | 207862063 | Breeze33 | BZ33-HP09OUT1-G2-C | BZ33-HP09WALL1-G2-C | | 6,800 | $340 |
| No | 207862069 | Breeze33 | BZ33-HYP06OUT2-G2-P | BZ33-HYP06WALL2-G2-P | | 8,500 | $425 |
| No | 207862068 | Breeze33 | BZ33-HP36OUT2-G2-C | BZ33-HP36WALL2-G2-C | | 24,000 | $1,200 |
| No | 207862085 | Breeze33 | BZ33-HYP18OUT2-G2-P | BZ33-CASS18-P | | 15,600 | $780 |
| No | 207862083 | Breeze33 | BZ33-HYP18OUT2-G2-P | BZ33-IFMU18-P | | 12,000 | $600 |
| No | 207862082 | Breeze33 | BZ33-HYP12OUT2-G2-P | BZ33-ICM12-G2-P | | 9,600 | $480 |
| No | 207862080 | Breeze33 | BZ33-HYP12OUT2-G2-P | BZ33-DIDU12-P | | 10,600 | $530 |
| No | 207862077 | Breeze33 | BZ33-HYP12OUT2-G2-P | BZ33-CASS12-P | | 9,900 | $495 |
| No | 207862079 | Breeze33 | BZ33-HYP09OUT2-G2-P | BZ33-DIDU9-P | | 10,100 | $505 |
| No | 207862076 | Breeze33 | BZ33-HYP09OUT2-G2-P | BZ33-CASS09-P | | 9,000 | $450 |
| No | 207862071 | Breeze33 | BZ33-HYP12OUT2-G2-P | BZ33-HYP12WALL2-G2-P | | 10,000 | $500 |
| No | 207862070 | Breeze33 | BZ33-HYP09OUT2-G2-P | BZ33-HYP09WALL2-G2-P | | 9,500 | $475 |
| No | 207862100 | BREEZE33 | BZ33-HYP182Z2-G2-P | Combination heat pumps with or without ducts | | 11,500 | $575 |
| No | 207862096 | BREEZE33 | BZ33-HP485Z2-G2-P | Heat pump with ducts | | 30,400 | $1,520 |
| No | 207862097 | BREEZE33 | BZ33-HP485Z2-G2-P | Combination heat pumps with or without ducts | | 30,000 | $1,500 |
| No | 207862091 | BREEZE33 | BZ33-HP273Z2-G2-P | Combination heat pumps with or without ducts | | 16,000 | $800 |
| No | 207862088 | BREEZE33 | BZ33-HP182Z2-G2-P | Combination heat pumps with or without ducts | | 11,400 | $570 |
| No | 207862103 | BREEZE33 | BZ33-HYP273Z2-G2-P | Combination heat pumps with or without ducts | | 17,000 | $850 |
| No | 210819416 | BRYANT | 38MARBQ30AA3 | 40MBABQ30XB3 | | 20,400 | $1,020 |
| No | 210450240 | BRYANT | 38MURAQ36AB3* | CAP**3617AL* | 926TB36060V14*** | 31,200 | $1,560 |
| No | 210450219 | BRYANT | 38MURAQ30AB3* | CAP**3721AL* | 926TB48080V17*** | 20,600 | $1,030 |
| No | 208447895 | BRYANT | 38MURAQ60AA3 | 40MUAAQ60XA3 | | 37,000 | $1,850 |
| No | 208447888 | BRYANT | 38MURAQ48AA3 | 40MUAAQ48XA3 | | 37,000 | $1,850 |
| No | 208447889 | BRYANT | 38MURAQ36AA3 | 40MUAAQ36XA3 | | 20,400 | $1,020 |
| No | 208447893 | BRYANT | 38MURAQ30AB3 | 40MUAAQ30XA3 | | 21,000 | $1,050 |
| No | 209852145 | BRYANT | 38MURAQ30AA3 | 40MUAAQ30XA3 | | 20,000 | $1,000 |
| No | 208447890 | BRYANT | 38MURAQ24AA3 | 40MUAAQ24XA3 | | 21,000 | $1,050 |
| No | 209911728 | BRYANT | 38MURAQ18AA3 | 40MUAAQ18XA3 | | 12,000 | $600 |
| No | 207642915 | BRYANT | 38MGRBQ48EA3 | Heat pump without ducts | | 29,600 | $1,480 |
| No | 204711107 | BRYANT | 38MGRQ24C--3 | Heat pump without ducts | | 17,200 | $860 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 9854623 | BRYANT | 38MGRQ24C--3 | Heat pump without ducts | | 13,600 | $680 |
| No | 9118478 | BRYANT | 38MGRQ48E--3 | Heat pump without ducts | | 29,600 | $1,480 |
| No | 9118462 | BRYANT | 38MGRQ18B--3 | Heat pump without ducts | | 12,000 | $600 |
| No | 206790588 | BRYANT | 284ANV048*0**B* | FE4AN(B,F)005L+UI | | 42,500 | $2,125 |
| No | 207826667 | BRYANT | 38MBRCQ48AA3 | 40MBABQ48XA3 | | 37,400 | $1,870 |
| No | 208104302 | BRYANT | 38MARBQ36AB3 | 40MBABQ36XB3 | | 25,600 | $1,280 |
| No | 207826666 | BRYANT | 38MBRCQ36AA3 | 40MBABQ36XA3 | | 25,600 | $1,280 |
| No | 207826668 | BRYANT | 38MBRCQ58AA3 | 40MBABQ60XA3 | | 34,000 | $1,700 |
| No | 207826665 | BRYANT | 38MARBQ24AA3 | 40MBABQ24XB3 | | 16,200 | $810 |
| No | 208104301 | BRYANT | 38MARBQ30AA311 | 40MBABQ30XB3 | | 19,200 | $960 |
| No | 204431572 | BRYANT | 280ANV048*0**A* | CSPH*4812AL*+UI | 88*TA66135C24*** | 50,500 | $2,525 |
| No | 204431581 | BRYANT | 280ANV048*0**A* | CSPH*4812AL*+UI | 987MB66100C21*** | 50,500 | $2,525 |
| No | 204431575 | BRYANT | 280ANV048*0**A* | CSPH*4812AL*+UI | 986TC66120C24*** | 50,500 | $2,525 |
| No | 204431553 | BRYANT | 280ANV048*0**A* | CNPV*6024AL*+UI | 987MB66120C24*** | 49,500 | $2,475 |
| No | 204431547 | BRYANT | 280ANV048*0**A* | CNPV*6024AL*+UI | 987MB66100C21*** | 49,000 | $2,450 |
| No | 204431543 | BRYANT | 280ANV048*0**A* | CNPV*6024AL*+UI | 986TC66120C24*** | 49,000 | $2,450 |
| No | 204431535 | BRYANT | 280ANV048*0**A* | CNPV*6024AL*+UI | 88*TA60090C21*** | 49,000 | $2,450 |
| No | 204431561 | BRYANT | 280ANV048*0**A* | CNPV*6024AL*+UI | 986TC66100C21*** | 49,000 | $2,450 |
| No | 204431564 | BRYANT | 280ANV048*0**A* | CNPV*6024AL*+UI | 88*TA60110C21*** | 49,000 | $2,450 |
| No | 204430143 | BRYANT | 280ANV036*0**A* | CNPV*3621AL*+UI | 986TC42060C17*** | 26,800 | $1,340 |
| No | 204431585 | BRYANT | 280ANV048*0**A* | CSPH*4812AL*+UI | 987MB66120C24*** | 51,000 | $2,550 |
| No | 204431588 | BRYANT | 280ANV048*0**A* | CSPH*4812AL*+UI | 986TC60080C21*** | 51,000 | $2,550 |
| No | 204431568 | BRYANT | 280ANV048*0**A* | CSPH*4812AL*+UI | 88*TA60090C21*** | 50,500 | $2,525 |
| No | 204431592 | BRYANT | 280ANV048*0**A* | CSPH*4812AL*+UI | 986TC66100C21*** | 50,500 | $2,525 |
| No | 204431596 | BRYANT | 280ANV048*0**A* | CSPH*4812AL*+UI | 88*TA48090C17*** | 51,000 | $2,550 |
| No | 204431539 | BRYANT | 280ANV048*0**A* | CNPV*6024AL*+UI | 88*TA66135C24*** | 49,000 | $2,450 |
| No | 204429963 | BRYANT | 280ANV024*0**A* | CAP**4221AL*+UI | 88*TA48070C17*** | 22,200 | $1,110 |
| No | 204429985 | BRYANT | 280ANV024*0**A* | CAP**4221AL*+UI | 986TC60080C21*** | 22,200 | $1,110 |
| No | 204429991 | BRYANT | 280ANV024*0**A* | CAP**4221AL*+UI | 986TC66100C21*** | 22,200 | $1,110 |
| No | 204429996 | BRYANT | 280ANV024*0**A* | CAP**4221AL*+UI | 88*TA48090C17*** | 22,000 | $1,100 |
| No | 204430015 | BRYANT | 280ANV024*0**A* | CAP**4224AL*+UI | 987MB60080C21*** | 22,200 | $1,110 |
| No | 204430017 | BRYANT | 280ANV024*0**A* | CAP**4224AL*+UI | 987MB66120C24*** | 22,200 | $1,110 |
| No | 204429981 | BRYANT | 280ANV024*0**A* | CAP**4221AL*+UI | 987MB66100C21*** | 22,200 | $1,110 |
| No | 205274212 | BRYANT | 284ANV048*0**A* | CSPH*4812AL*+UI | 88*TA60090C21*** | 43,000 | $2,150 |
| No | 205274198 | BRYANT | 284ANV048*0**A* | CAP**4824AL*+UI | 987MB66120C24*** | 43,000 | $2,150 |
| No | 205274194 | BRYANT | 284ANV048*0**A* | CAP**4821AL*+UI | 986TC66100C21*** | 43,000 | $2,150 |
| No | 205274195 | BRYANT | 284ANV048*0**A* | CAP**4821AL*+UI | 88*TA60110C21*** | 43,000 | $2,150 |
| No | 205274193 | BRYANT | 284ANV048*0**A* | CAP**4821AL*+UI | 987MB66100C21*** | 43,000 | $2,150 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205274192 | BRYANT | 284ANV048*0**A* | CAP**4821AL*+UI | 88*TA60090C21*** | 43,000 | $2,150 |
| No | 205274238 | BRYANT | 284ANV060*0**A* | CAP**6024AL*+UI | 987MB60060C21*** | 52,000 | $2,600 |
| No | 205274251 | BRYANT | 284ANV060*0**A* | CAP**6124AL*+UI | 987MB60060C21*** | 52,000 | $2,600 |
| No | 205274244 | BRYANT | 284ANV060*0**A* | CAP**6121AL*+UI | 987MB60060C21*** | 51,500 | $2,575 |
| No | 205274262 | BRYANT | 284ANV060*0**A* | CNPV*6124AL*+UI | 987MB60060C21*** | 51,500 | $2,575 |
| No | 205274248 | BRYANT | 284ANV060*0**A* | CAP**6124AL*+UI | 986TC60080C21*** | 51,000 | $2,550 |
| No | 205274245 | BRYANT | 284ANV060*0**A* | CAP**6124AL*+UI | 987MB60080C21*** | 51,000 | $2,550 |
| No | 205274247 | BRYANT | 284ANV060*0**A* | CAP**6124AL*+UI | 987MB66120C24*** | 50,500 | $2,525 |
| No | 205274242 | BRYANT | 284ANV060*0**A* | CAP**6121AL*+UI | 986TC66100C21*** | 50,500 | $2,525 |
| No | 205274241 | BRYANT | 284ANV060*0**A* | CAP**6121AL*+UI | 986TC60080C21*** | 51,000 | $2,550 |
| No | 205274240 | BRYANT | 284ANV060*0**A* | CAP**6121AL*+UI | 987MB66100C21*** | 50,500 | $2,525 |
| No | 205274239 | BRYANT | 284ANV060*0**A* | CAP**6121AL*+UI | 987MB60080C21*** | 51,000 | $2,550 |
| No | 205274237 | BRYANT | 284ANV060*0**A* | CAP**6024AL*+UI | 88*TA60110C21*** | 50,500 | $2,525 |
| No | 205274236 | BRYANT | 284ANV060*0**A* | CAP**6024AL*+UI | 986TC66100C21*** | 50,500 | $2,525 |
| No | 205274235 | BRYANT | 284ANV060*0**A* | CAP**6024AL*+UI | 986TC60080C21*** | 51,000 | $2,550 |
| No | 205274234 | BRYANT | 284ANV060*0**A* | CAP**6024AL*+UI | 987MB66120C24*** | 50,500 | $2,525 |
| No | 205274233 | BRYANT | 284ANV060*0**A* | CAP**6024AL*+UI | 987MB66100C21*** | 50,500 | $2,525 |
| No | 205274232 | BRYANT | 284ANV060*0**A* | CAP**6024AL*+UI | 987MB60080C21*** | 51,000 | $2,550 |
| No | 205274229 | BRYANT | 284ANV048*0**A* | CSPH*6012AL*+UI | 88*TA48090C17*** | 43,000 | $2,150 |
| No | 205274227 | BRYANT | 284ANV048*0**A* | CSPH*6012AL*+UI | 986TC60080C21*** | 43,000 | $2,150 |
| No | 205274224 | BRYANT | 284ANV048*0**A* | CSPH*6012AL*+UI | 987MB60080C21*** | 43,000 | $2,150 |
| No | 205274220 | BRYANT | 284ANV048*0**A* | CSPH*6012AL*+UI | 88*TA60070C21*** | 43,000 | $2,150 |
| No | 205274219 | BRYANT | 284ANV048*0**A* | CSPH*4812AL*+UI | 88*TA60110C21*** | 43,000 | $2,150 |
| No | 205274218 | BRYANT | 284ANV048*0**A* | CSPH*4812AL*+UI | 88*TA48090C17*** | 43,500 | $2,175 |
| No | 205274217 | BRYANT | 284ANV048*0**A* | CSPH*4812AL*+UI | 986TC66100C21*** | 43,000 | $2,150 |
| No | 205274216 | BRYANT | 284ANV048*0**A* | CSPH*4812AL*+UI | 987MB66120C24*** | 43,500 | $2,175 |
| No | 205274214 | BRYANT | 284ANV048*0**A* | CSPH*4812AL*+UI | 986TC66120C24*** | 43,000 | $2,150 |
| No | 205274215 | BRYANT | 284ANV048*0**A* | CSPH*4812AL*+UI | 987MB66100C21*** | 43,000 | $2,150 |
| No | 205274260 | BRYANT | 284ANV060*0**A* | CNPV*6124AL*+UI | 986TC66100C21*** | 50,000 | $2,500 |
| No | 205274259 | BRYANT | 284ANV060*0**A* | CNPV*6124AL*+UI | 986TC60080C21*** | 50,500 | $2,525 |
| No | 205274258 | BRYANT | 284ANV060*0**A* | CNPV*6124AL*+UI | 987MB66120C24*** | 50,500 | $2,525 |
| No | 205274261 | BRYANT | 284ANV060*0**A* | CNPV*6124AL*+UI | 88*TA60110C21*** | 50,000 | $2,500 |
| No | 205274257 | BRYANT | 284ANV060*0**A* | CNPV*6124AL*+UI | 987MB66100C21*** | 50,000 | $2,500 |
| No | 205274256 | BRYANT | 284ANV060*0**A* | CNPV*6124AL*+UI | 987MB60080C21*** | 50,500 | $2,525 |
| No | 205274255 | BRYANT | 284ANV060*0**A* | CNPV*6124AL*+UI | 986TC66120C24*** | 50,500 | $2,525 |
| No | 205274252 | BRYANT | 284ANV060*0**A* | CNPV*6124AL*+UI | 88*TA60070C21*** | 51,000 | $2,550 |
| No | 205274250 | BRYANT | 284ANV060*0**A* | CAP**6124AL*+UI | 88*TA60110C21*** | 50,500 | $2,525 |
| No | 205274249 | BRYANT | 284ANV060*0**A* | CAP**6124AL*+UI | 986TC66100C21*** | 50,500 | $2,525 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205274246 | BRYANT | 284ANV060*0**A* | CAP**6124AL*+UI | 987MB66100C21*** | 50,500 | $2,525 |
| No | 205274243 | BRYANT | 284ANV060*0**A* | CAP**6121AL*+UI | 88*TA60110C21*** | 50,500 | $2,525 |
| No | 205274230 | BRYANT | 284ANV048*0**A* | CSPH*6012AL*+UI | 88*TA60110C21*** | 43,000 | $2,150 |
| No | 205274228 | BRYANT | 284ANV048*0**A* | CSPH*6012AL*+UI | 986TC66100C21*** | 43,000 | $2,150 |
| No | 205274226 | BRYANT | 284ANV048*0**A* | CSPH*6012AL*+UI | 987MB66120C24*** | 43,000 | $2,150 |
| No | 205274225 | BRYANT | 284ANV048*0**A* | CSPH*6012AL*+UI | 987MB66100C21*** | 43,000 | $2,150 |
| No | 205274221 | BRYANT | 284ANV048*0**A* | CSPH*6012AL*+UI | 88*TA60090C21*** | 42,500 | $2,125 |
| No | 205274222 | BRYANT | 284ANV048*0**A* | CSPH*6012AL*+UI | 88*TA66135C24*** | 42,500 | $2,125 |
| No | 205274213 | BRYANT | 284ANV048*0**A* | CSPH*4812AL*+UI | 88*TA66135C24*** | 43,000 | $2,150 |
| No | 205274223 | BRYANT | 284ANV048*0**A* | CSPH*6012AL*+UI | 986TC66120C24*** | 43,000 | $2,150 |
| No | 205274211 | BRYANT | 284ANV048*0**A* | CNPV*6024AL*+UI | 987MB66120C24*** | 43,000 | $2,150 |
| No | 205274210 | BRYANT | 284ANV048*0**A* | CNPV*6024AL*+UI | 986TC66120C24*** | 43,000 | $2,150 |
| No | 205274208 | BRYANT | 284ANV048*0**A* | CAP**6124AL*+UI | 987MB66120C24*** | 43,000 | $2,150 |
| No | 205274209 | BRYANT | 284ANV048*0**A* | CNPV*6024AL*+UI | 88*TA66135C24*** | 42,500 | $2,125 |
| No | 205274207 | BRYANT | 284ANV048*0**A* | CAP**6124AL*+UI | 986TC66120C24*** | 43,000 | $2,150 |
| No | 205274205 | BRYANT | 284ANV048*0**A* | CAP**6121AL*+UI | 88*TA60110C21*** | 43,000 | $2,150 |
| No | 205274204 | BRYANT | 284ANV048*0**A* | CAP**6121AL*+UI | 986TC66100C21*** | 43,000 | $2,150 |
| No | 205274206 | BRYANT | 284ANV048*0**A* | CAP**6124AL*+UI | 88*TA66135C24*** | 42,500 | $2,125 |
| No | 205274202 | BRYANT | 284ANV048*0**A* | CAP**6121AL*+UI | 88*TA60090C21*** | 43,000 | $2,150 |
| No | 205274203 | BRYANT | 284ANV048*0**A* | CAP**6121AL*+UI | 987MB66100C21*** | 43,000 | $2,150 |
| No | 205274200 | BRYANT | 284ANV048*0**A* | CAP**6024AL*+UI | 986TC66120C24*** | 42,500 | $2,125 |
| No | 205274201 | BRYANT | 284ANV048*0**A* | CAP**6024AL*+UI | 987MB66120C24*** | 43,000 | $2,150 |
| No | 205274199 | BRYANT | 284ANV048*0**A* | CAP**6024AL*+UI | 88*TA66135C24*** | 42,500 | $2,125 |
| No | 205274197 | BRYANT | 284ANV048*0**A* | CAP**4824AL*+UI | 986TC66120C24*** | 43,000 | $2,150 |
| No | 205274196 | BRYANT | 284ANV048*0**A* | CAP**4824AL*+UI | 88*TA66135C24*** | 43,000 | $2,150 |
| No | 205274254 | BRYANT | 284ANV060*0**A* | CNPV*6124AL*+UI | 88*TA66135C24*** | 50,000 | $2,500 |
| No | 205274253 | BRYANT | 284ANV060*0**A* | CNPV*6124AL*+UI | 88*TA60090C21*** | 50,500 | $2,525 |
| No | 205274191 | BRYANT | 284ANV048*0**A* | FE4AN(B,F)005L+UI | | 42,500 | $2,125 |
| No | 205274231 | BRYANT | 284ANV060*0**A* | FE4ANB006L+UI | | 49,500 | $2,475 |
| No | 205274190 | BRYANT | 284ANV048*0**A* | FE4ANB006L+UI | | 42,500 | $2,125 |
| No | 203380986 | BRYANT | 38MAQB30R--3 | FMA4X30**AL* | | 21,200 | $1,060 |
| No | 204344194 | BRYANT | 38MAQB12R--3 | FV4CNF002 | | 6,400 | $320 |
| No | 204344195 | BRYANT | 38MAQB18R--3 | FV4CNF002 | | 11,000 | $550 |
| No | 203380984 | BRYANT | 38MAQB18R--3 | FMA4X18**AL* | | 10,800 | $540 |
| No | 203381002 | BRYANT | 38MAQB36R--3 | FM(C,U)4Z36**AL* | | 19,000 | $950 |
| No | 203380983 | BRYANT | 38MAQB12R--3 | FMA4X18**AL* | | 7,600 | $380 |
| No | 203381001 | BRYANT | 38MAQB30R--3 | FM(C,U)4Z30**AL* | | 20,200 | $1,010 |
| No | 207098589 | BRYANT | 38MARBQ24AA3 | FMA4X24**AL* | | 16,000 | $800 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207098587 | BRYANT | 38MARBQ24AA3 | FX4DNF025L | | 15,500 | $775 |
| No | 207098590 | BRYANT | 38MARBQ24AA3 | FM(C,U)4Z24**AL* | | 16,100 | $805 |
| No | 207098631 | BRYANT | 38MARBQ24AA3 | CAP**3017AL* | 935SA36040E17*** | 15,500 | $775 |
| No | 207098627 | BRYANT | 38MARBQ24AA3 | CAP**2417AL* | 935SA36040E17*** | 15,700 | $785 |
| No | 207098629 | BRYANT | 38MARBQ24AA3 | CAP**3617AL* | 935SA36040E17*** | 15,400 | $770 |
| No | 207098626 | BRYANT | 38MARBQ24AA3 | CNPV*2417AL* | 935SA36040E17*** | 15,600 | $780 |
| No | 207098630 | BRYANT | 38MARBQ24AA3 | CNPV*3617AL* | 935SA36040E17*** | 15,500 | $775 |
| No | 207098628 | BRYANT | 38MARBQ24AA3 | CNPV*3017AL* | 935SA36040E17*** | 15,500 | $775 |
| No | 207098705 | BRYANT | 38MARBQ24AA3 | CAP**3017AL* | 926TB48080V17*** | 15,500 | $775 |
| No | 207098704 | BRYANT | 38MARBQ24AA3 | CNPV*3617AL* | 926TB48080V17*** | 15,500 | $775 |
| No | 207098701 | BRYANT | 38MARBQ24AA3 | CAP**2417AL* | 926TB48080V17*** | 15,700 | $785 |
| No | 207098702 | BRYANT | 38MARBQ24AA3 | CNPV*3017AL* | 926TB48080V17*** | 15,500 | $775 |
| No | 207098703 | BRYANT | 38MARBQ24AA3 | CAP**3617AL* | 926TB48080V17*** | 15,400 | $770 |
| No | 207098698 | BRYANT | 38MARBQ24AA3 | CNPV*3617AL* | 926TB42060V17*** | 15,500 | $775 |
| No | 207098700 | BRYANT | 38MARBQ24AA3 | CNPV*2417AL* | 926TB48080V17*** | 15,600 | $780 |
| No | 207098697 | BRYANT | 38MARBQ24AA3 | CAP**3617AL* | 926TB42060V17*** | 15,400 | $770 |
| No | 207098695 | BRYANT | 38MARBQ24AA3 | CAP**2417AL* | 926TB42060V17*** | 15,800 | $790 |
| No | 207098693 | BRYANT | 38MARBQ24AA3 | CNPV*3014AL* | 926TB36060V14*** | 15,600 | $780 |
| No | 207098696 | BRYANT | 38MARBQ24AA3 | CNPV*3017AL* | 926TB42060V17*** | 15,500 | $775 |
| No | 207098694 | BRYANT | 38MARBQ24AA3 | CNPV*2417AL* | 926TB42060V17*** | 15,600 | $780 |
| No | 207098692 | BRYANT | 38MARBQ24AA3 | CAP**3014AL* | 926TB36060V14*** | 15,600 | $780 |
| No | 207098686 | BRYANT | 38MARBQ24AA3 | CAP**3617AL* | 926TB36040V17*** | 15,500 | $775 |
| No | 207098682 | BRYANT | 38MARBQ24AA3 | CNPV*3014AL* | 926TB30040V14*** | 15,600 | $780 |
| No | 207098707 | BRYANT | 38MARBQ24AA3 | CAP**3621AL* | 915SB42060E17*** | 15,400 | $770 |
| No | 207098681 | BRYANT | 38MARBQ24AA3 | CAP**3014AL* | 926TB30040V14*** | 15,600 | $780 |
| No | 207098708 | BRYANT | 38MARBQ24AA3 | CAP**3717AL* | 915SB42060E17*** | 15,200 | $760 |
| No | 207098673 | BRYANT | 38MARBQ24AA3 | CAP**2417AL* | 915SB42060E17*** | 15,800 | $790 |
| No | 207098710 | BRYANT | 38MARBQ24AA3 | CNPV*3621AL* | 915SB42060E17*** | 15,500 | $775 |
| No | 207098677 | BRYANT | 38MARBQ24AA3 | CAP**3017AL* | 915SB42060E17*** | 15,500 | $775 |
| No | 207098672 | BRYANT | 38MARBQ24AA3 | CNPV*2417AL* | 915SB42060E17*** | 15,600 | $780 |
| No | 207098675 | BRYANT | 38MARBQ24AA3 | CAP**3617AL* | 915SB42060E17*** | 15,400 | $770 |
| No | 207098709 | BRYANT | 38MARBQ24AA3 | CAP**3721AL* | 915SB42060E17*** | 15,100 | $755 |
| No | 207098699 | BRYANT | 38MARBQ24AA3 | CAP**3017AL* | 926TB42060V17*** | 15,500 | $775 |
| No | 207098706 | BRYANT | 38MARBQ24AA3 | CAP**2517AL* | 915SB42060E17*** | 15,200 | $760 |
| No | 207098676 | BRYANT | 38MARBQ24AA3 | CNPV*3617AL* | 915SB42060E17*** | 15,500 | $775 |
| No | 207098718 | BRYANT | 38MARBQ24AA3 | CNPV*3617AL* | 915SB36060E14*** | 15,500 | $775 |
| No | 207098674 | BRYANT | 38MARBQ24AA3 | CNPV*3017AL* | 915SB42060E17*** | 15,500 | $775 |
| No | 207098717 | BRYANT | 38MARBQ24AA3 | CNPV*3017AL* | 915SB36060E14*** | 15,500 | $775 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207098714 | BRYANT | 38MARBQ24AA3 | CAP**3017AL* | 915SB36060E14*** | 15,600 | $780 |
| No | 207098715 | BRYANT | 38MARBQ24AA3 | CAP**3717AL* | 915SB36060E14*** | 15,300 | $765 |
| No | 207098716 | BRYANT | 38MARBQ24AA3 | CNPV*2417AL* | 915SB36060E14*** | 15,600 | $780 |
| No | 207098712 | BRYANT | 38MARBQ24AA3 | CAP**2517AL* | 915SB36060E14*** | 15,200 | $760 |
| No | 207098713 | BRYANT | 38MARBQ24AA3 | CAP**3617AL* | 915SB36060E14*** | 15,500 | $775 |
| No | 207098711 | BRYANT | 38MARBQ24AA3 | CAP**2417AL* | 915SB36060E14*** | 15,800 | $790 |
| No | 207098671 | BRYANT | 38MARBQ24AA3 | CNPV*3014AL* | 915SB36060E14*** | 15,500 | $775 |
| No | 207098670 | BRYANT | 38MARBQ24AA3 | CAP**3014AL* | 915SB36060E14*** | 15,600 | $780 |
| No | 207098669 | BRYANT | 38MARBQ24AA3 | CAP**2414AL* | 915SB36060E14*** | 15,800 | $790 |
| No | 207098668 | BRYANT | 38MARBQ24AA3 | CNPV*2414AL* | 915SB36060E14*** | 15,600 | $780 |
| No | 207098722 | BRYANT | 38MARBQ24AA3 | CAP**3721AL* | 915SB36040E17*** | 15,200 | $760 |
| No | 207098723 | BRYANT | 38MARBQ24AA3 | CNPV*3621AL* | 915SB36040E17*** | 15,600 | $780 |
| No | 207098721 | BRYANT | 38MARBQ24AA3 | CAP**3717AL* | 915SB36040E17*** | 15,300 | $765 |
| No | 207098719 | BRYANT | 38MARBQ24AA3 | CAP**2517AL* | 915SB36040E17*** | 15,200 | $760 |
| No | 207098664 | BRYANT | 38MARBQ24AA3 | CAP**3617AL* | 915SB36040E17*** | 15,500 | $775 |
| No | 207098666 | BRYANT | 38MARBQ24AA3 | CAP**3017AL* | 915SB36040E17*** | 15,600 | $780 |
| No | 207098663 | BRYANT | 38MARBQ24AA3 | CNPV*3017AL* | 915SB36040E17*** | 15,600 | $780 |
| No | 207098665 | BRYANT | 38MARBQ24AA3 | CNPV*3617AL* | 915SB36040E17*** | 15,600 | $780 |
| No | 207098727 | BRYANT | 38MARBQ24AA3 | CAP**3717AL* | 915SB30040E14*** | 15,300 | $765 |
| No | 207098648 | BRYANT | 38MARBQ24AA3 | CAP**2417AL* | 912SD48080E17*** | 15,700 | $785 |
| No | 207098656 | BRYANT | 38MARBQ24AA3 | CNPV*3014AL* | 915SB30026E14*** | 15,500 | $775 |
| No | 207098654 | BRYANT | 38MARBQ24AA3 | CAP**2414AL* | 915SB30026E14*** | 15,800 | $790 |
| No | 207098655 | BRYANT | 38MARBQ24AA3 | CAP**3014AL* | 915SB30026E14*** | 15,500 | $775 |
| No | 207098651 | BRYANT | 38MARBQ24AA3 | CNPV*3617AL* | 912SD48080E17*** | 15,400 | $770 |
| No | 207098652 | BRYANT | 38MARBQ24AA3 | CAP**3017AL* | 912SD48080E17*** | 15,400 | $770 |
| No | 207098649 | BRYANT | 38MARBQ24AA3 | CNPV*3017AL* | 912SD48080E17*** | 15,400 | $770 |
| No | 207098647 | BRYANT | 38MARBQ24AA3 | CNPV*2417AL* | 912SD48080E17*** | 15,500 | $775 |
| No | 207098645 | BRYANT | 38MARBQ24AA3 | CAP**3014AL* | 912SD42060E17*** | 15,500 | $775 |
| No | 207098644 | BRYANT | 38MARBQ24AA3 | CAP**2414AL* | 912SD42060E17*** | 15,700 | $785 |
| No | 207098720 | BRYANT | 38MARBQ24AA3 | CAP**3621AL* | 915SB36040E17*** | 15,500 | $775 |
| No | 207098650 | BRYANT | 38MARBQ24AA3 | CAP**3617AL* | 912SD48080E17*** | 15,400 | $770 |
| No | 207098646 | BRYANT | 38MARBQ24AA3 | CNPV*3014AL* | 912SD42060E17*** | 15,400 | $770 |
| No | 207098640 | BRYANT | 38MARBQ24AA3 | CAP**3014AL* | 912SD36060E14*** | 15,500 | $775 |
| No | 207098641 | BRYANT | 38MARBQ24AA3 | CNPV*3014AL* | 912SD36060E14*** | 15,500 | $775 |
| No | 207098639 | BRYANT | 38MARBQ24AA3 | CAP**2414AL* | 912SD36060E14*** | 15,700 | $785 |
| No | 207098612 | BRYANT | 38MARBQ24AA3 | CAP**2417AL* | 83*SA48060E17*** | 15,700 | $785 |
| No | 207098643 | BRYANT | 38MARBQ24AA3 | CNPV*2414AL* | 912SD42060E17*** | 15,500 | $775 |
| No | 207098638 | BRYANT | 38MARBQ24AA3 | CNPV*2414AL* | 912SD36060E14*** | 15,600 | $780 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207098615 | BRYANT | 38MARBQ24AA3 | CNPV*3617AL* | 83*SA48060E17*** | 15,500 | $775 |
| No | 207098613 | BRYANT | 38MARBQ24AA3 | CNPV*3017AL* | 83*SA48060E17*** | 15,500 | $775 |
| No | 207098614 | BRYANT | 38MARBQ24AA3 | CAP**3617AL* | 83*SA48060E17*** | 15,400 | $770 |
| No | 207098606 | BRYANT | 38MARBQ24AA3 | CNPV*2417AL* | 83*SA36040E17*** | 15,500 | $775 |
| No | 207098611 | BRYANT | 38MARBQ24AA3 | CNPV*2417AL* | 83*SA48060E17*** | 15,600 | $780 |
| No | 207098607 | BRYANT | 38MARBQ24AA3 | CNPV*3017AL* | 83*SA36040E17*** | 15,400 | $770 |
| No | 207098608 | BRYANT | 38MARBQ24AA3 | CAP**3617AL* | 83*SA36040E17*** | 15,300 | $765 |
| No | 207098621 | BRYANT | 38MARBQ24AA3 | CAP**2417AL* | 82*TA48070V17*** | 15,700 | $785 |
| No | 207098625 | BRYANT | 38MARBQ24AA3 | CAP**3017AL* | 82*TA48070V17*** | 15,500 | $775 |
| No | 207098620 | BRYANT | 38MARBQ24AA3 | CNPV*2417AL* | 82*TA48070V17*** | 15,600 | $780 |
| No | 207098618 | BRYANT | 38MARBQ24AA3 | CAP**3014AL* | 82*TA36045V14*** | 15,500 | $775 |
| No | 207098624 | BRYANT | 38MARBQ24AA3 | CNPV*3617AL* | 82*TA48070V17*** | 15,400 | $770 |
| No | 207098622 | BRYANT | 38MARBQ24AA3 | CNPV*3017AL* | 82*TA48070V17*** | 15,400 | $770 |
| No | 207098619 | BRYANT | 38MARBQ24AA3 | CNPV*3014AL* | 82*TA36045V14*** | 15,500 | $775 |
| No | 207098617 | BRYANT | 38MARBQ24AA3 | CAP**2414AL* | 82*TA36045V14*** | 15,700 | $785 |
| No | 207098616 | BRYANT | 38MARBQ24AA3 | CNPV*2414AL* | 82*TA36045V14*** | 15,600 | $780 |
| No | 207098609 | BRYANT | 38MARBQ24AA3 | CNPV*3617AL* | 83*SA36040E17*** | 15,400 | $770 |
| No | 207098605 | BRYANT | 38MARBQ24AA3 | CAP**3017AL* | 8(0,1)*SA36070E17*** | 15,500 | $775 |
| No | 207098601 | BRYANT | 38MARBQ24AA3 | CNPV*2417AL* | 8(0,1)*SA36070E17*** | 15,600 | $780 |
| No | 207098610 | BRYANT | 38MARBQ24AA3 | CAP**3017AL* | 83*SA36040E17*** | 15,400 | $770 |
| No | 207098604 | BRYANT | 38MARBQ24AA3 | CNPV*3617AL* | 8(0,1)*SA36070E17*** | 15,400 | $770 |
| No | 207098603 | BRYANT | 38MARBQ24AA3 | CAP**3617AL* | 8(0,1)*SA36070E17*** | 15,400 | $770 |
| No | 207098599 | BRYANT | 38MARBQ24AA3 | CAP**3014AL* | 8(0,1)*SA36070E14*** | 15,500 | $775 |
| No | 207098602 | BRYANT | 38MARBQ24AA3 | CNPV*3017AL* | 8(0,1)*SA36070E17*** | 15,400 | $770 |
| No | 207098598 | BRYANT | 38MARBQ24AA3 | CAP**2414AL* | 8(0,1)*SA36070E14*** | 15,700 | $785 |
| No | 207098597 | BRYANT | 38MARBQ24AA3 | CNPV*2414AL* | 8(0,1)*SA36070E14*** | 15,600 | $780 |
| No | 207098600 | BRYANT | 38MARBQ24AA3 | CNPV*3014AL* | 8(0,1)*SA36070E14*** | 15,500 | $775 |
| No | 207098623 | BRYANT | 38MARBQ24AA3 | CAP**3617AL* | 82*TA48070V17*** | 15,400 | $770 |
| No | 207098596 | BRYANT | 38MARBQ24AA3 | CAP**3617AL* | 8(0,1)*SA36045E17*** | 15,500 | $775 |
| No | 207098593 | BRYANT | 38MARBQ24AA3 | CAP**2414AL* | 8(0,1)*SA36045E14*** | 15,700 | $785 |
| No | 207098594 | BRYANT | 38MARBQ24AA3 | CAP**3014AL* | 8(0,1)*SA36045E14*** | 15,500 | $775 |
| No | 207098592 | BRYANT | 38MARBQ24AA3 | CNPV*2414AL* | 8(0,1)*SA36045E14*** | 15,600 | $780 |
| No | 207098595 | BRYANT | 38MARBQ24AA3 | CNPV*3014AL* | 8(0,1)*SA36045E14*** | 15,500 | $775 |
| No | 207202168 | BRYANT | 38MARBQ18AA3 | FV4CNF002L | | 13,400 | $670 |
| No | 207202295 | BRYANT | 38MARBQ18AA3 | FB4CNP018L | | 14,700 | $735 |
| No | 207202291 | BRYANT | 38MARBQ18AA3 | FMA4X18**AL* | | 15,000 | $750 |
| No | 207202378 | BRYANT | 38MARBQ18AA3 | CAP**2417AL* | 935SA36040E17*** | 14,600 | $730 |
| No | 207202293 | BRYANT | 38MARBQ18AA3 | PF4MNB019L | | 14,500 | $725 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207202292 | BRYANT | 38MARBQ18AA3 | FM(C,U)4Z18**AL* | | 15,000 | $750 |
| No | 207202380 | BRYANT | 38MARBQ18AA3 | CNPV*2417AL* | 935SA36040E17*** | 14,600 | $730 |
| No | 207202294 | BRYANT | 38MARBQ18AA3 | FB4CNF018L | | 14,700 | $735 |
| No | 207202379 | BRYANT | 38MARBQ18AA3 | CAP**2517AL* | 935SA36040E17*** | 13,800 | $690 |
| No | 207202377 | BRYANT | 38MARBQ18AA3 | CAP**1917AL* | 935SA36040E17*** | 13,800 | $690 |
| No | 207202400 | BRYANT | 38MARBQ18AA3 | CAP**2417AL* | 926TB42060V17*** | 14,700 | $735 |
| No | 207202402 | BRYANT | 38MARBQ18AA3 | CAP**2517AL* | 926TB48080V17*** | 13,800 | $690 |
| No | 207202399 | BRYANT | 38MARBQ18AA3 | CAP**1917AL* | 926TB42060V17*** | 14,100 | $705 |
| No | 207202401 | BRYANT | 38MARBQ18AA3 | CAP**2517AL* | 926TB42060V17*** | 13,900 | $695 |
| No | 207202396 | BRYANT | 38MARBQ18AA3 | CNPV*1814AL* | 926TB36060V14*** | 14,700 | $735 |
| No | 207202397 | BRYANT | 38MARBQ18AA3 | CNPV*2414AL* | 926TB36060V14*** | 14,600 | $730 |
| No | 207202392 | BRYANT | 38MARBQ18AA3 | CAP**1917AL* | 926TB36060V14*** | 13,800 | $690 |
| No | 207202394 | BRYANT | 38MARBQ18AA3 | CAP**2417AL* | 926TB36060V14*** | 14,600 | $730 |
| No | 207202393 | BRYANT | 38MARBQ18AA3 | CAP**2414AL* | 926TB36060V14*** | 14,600 | $730 |
| No | 207202395 | BRYANT | 38MARBQ18AA3 | CAP**2517AL* | 926TB36060V14*** | 13,800 | $690 |
| No | 207202391 | BRYANT | 38MARBQ18AA3 | CNPV*2417AL* | 926TB36040V17*** | 14,600 | $730 |
| No | 207202389 | BRYANT | 38MARBQ18AA3 | CAP**2417AL* | 926TB36040V17*** | 14,600 | $730 |
| No | 207202390 | BRYANT | 38MARBQ18AA3 | CAP**2517AL* | 926TB36040V17*** | 13,800 | $690 |
| No | 207202388 | BRYANT | 38MARBQ18AA3 | CAP**1917AL* | 926TB36040V17*** | 13,900 | $695 |
| No | 207202385 | BRYANT | 38MARBQ18AA3 | CNPV*1814AL* | 926TB30040V14*** | 14,800 | $740 |
| No | 207202382 | BRYANT | 38MARBQ18AA3 | CAP**2414AL* | 926TB30040V14*** | 14,700 | $735 |
| No | 207202398 | BRYANT | 38MARBQ18AA3 | CNPV*2417AL* | 926TB36060V14*** | 14,600 | $730 |
| No | 207202386 | BRYANT | 38MARBQ18AA3 | CNPV*2414AL* | 926TB30040V14*** | 14,700 | $735 |
| No | 207202384 | BRYANT | 38MARBQ18AA3 | CAP**2517AL* | 926TB30040V14*** | 13,900 | $695 |
| No | 207202376 | BRYANT | 38MARBQ18AA3 | CNPV*2417AL* | 915SB42060E17*** | 14,700 | $735 |
| No | 207202383 | BRYANT | 38MARBQ18AA3 | CAP**2417AL* | 926TB30040V14*** | 14,700 | $735 |
| No | 207202381 | BRYANT | 38MARBQ18AA3 | CAP**1917AL* | 926TB30040V14*** | 13,900 | $695 |
| No | 207202387 | BRYANT | 38MARBQ18AA3 | CNPV*2417AL* | 926TB30040V14*** | 14,700 | $735 |
| No | 207202375 | BRYANT | 38MARBQ18AA3 | CAP**2517AL* | 915SB42060E17*** | 14,000 | $700 |
| No | 207202374 | BRYANT | 38MARBQ18AA3 | CAP**1917AL* | 915SB42060E17*** | 14,100 | $705 |
| No | 207202369 | BRYANT | 38MARBQ18AA3 | CAP**2417AL* | 915SB36040E17*** | 14,600 | $730 |
| No | 207202373 | BRYANT | 38MARBQ18AA3 | CAP**2417AL* | 915SB36060E14*** | 14,900 | $745 |
| No | 207202371 | BRYANT | 38MARBQ18AA3 | CNPV*2417AL* | 915SB36040E17*** | 14,600 | $730 |
| No | 207202368 | BRYANT | 38MARBQ18AA3 | CAP**1917AL* | 915SB36040E17*** | 13,800 | $690 |
| No | 207202365 | BRYANT | 38MARBQ18AA3 | CNPV*1814AL* | 915SB30040E14*** | 14,700 | $735 |
| No | 207202370 | BRYANT | 38MARBQ18AA3 | CAP**2517AL* | 915SB36040E17*** | 13,700 | $685 |
| No | 207202367 | BRYANT | 38MARBQ18AA3 | CNPV*2417AL* | 915SB30040E14*** | 14,600 | $730 |
| No | 207202366 | BRYANT | 38MARBQ18AA3 | CNPV*2414AL* | 915SB30040E14*** | 14,600 | $730 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207202363 | BRYANT | 38MARBQ18AA3 | CAP**2417AL* | 915SB30040E14*** | 14,600 | $730 |
| No | 207202362 | BRYANT | 38MARBQ18AA3 | CAP**2414AL* | 915SB30040E14*** | 14,600 | $730 |
| No | 207202361 | BRYANT | 38MARBQ18AA3 | CAP**1917AL* | 915SB30040E14*** | 13,900 | $695 |
| No | 207202358 | BRYANT | 38MARBQ18AA3 | CNPV*1814AL* | 915SB30026E14*** | 14,800 | $740 |
| No | 207202360 | BRYANT | 38MARBQ18AA3 | CNPV*2417AL* | 915SB30026E14*** | 14,700 | $735 |
| No | 207202359 | BRYANT | 38MARBQ18AA3 | CNPV*2414AL* | 915SB30026E14*** | 14,700 | $735 |
| No | 207202357 | BRYANT | 38MARBQ18AA3 | CAP**2517AL* | 915SB30026E14*** | 13,900 | $695 |
| No | 207202356 | BRYANT | 38MARBQ18AA3 | CAP**2417AL* | 915SB30026E14*** | 14,700 | $735 |
| No | 207202354 | BRYANT | 38MARBQ18AA3 | CNPV*2417AL* | 912SD48080E17*** | 14,700 | $735 |
| No | 207202355 | BRYANT | 38MARBQ18AA3 | CAP**1917AL* | 915SB30026E14*** | 14,100 | $705 |
| No | 207202372 | BRYANT | 38MARBQ18AA3 | CAP**2414AL* | 915SB36060E14*** | 14,900 | $745 |
| No | 207202353 | BRYANT | 38MARBQ18AA3 | CAP**2417AL* | 912SD48080E17*** | 14,700 | $735 |
| No | 207202350 | BRYANT | 38MARBQ18AA3 | CNPV*1814AL* | 912SD36060E14*** | 14,700 | $735 |
| No | 207202352 | BRYANT | 38MARBQ18AA3 | CNPV*2417AL* | 912SD36060E14*** | 14,600 | $730 |
| No | 207202351 | BRYANT | 38MARBQ18AA3 | CNPV*2414AL* | 912SD36060E14*** | 14,600 | $730 |
| No | 207202349 | BRYANT | 38MARBQ18AA3 | CAP**2517AL* | 912SD36060E14*** | 13,800 | $690 |
| No | 207202348 | BRYANT | 38MARBQ18AA3 | CAP**2417AL* | 912SD36060E14*** | 14,600 | $730 |
| No | 207202347 | BRYANT | 38MARBQ18AA3 | CAP**1917AL* | 912SD36060E14*** | 14,000 | $700 |
| No | 207202346 | BRYANT | 38MARBQ18AA3 | CNPV*2417AL* | 912SD36040E17*** | 14,600 | $730 |
| No | 207202345 | BRYANT | 38MARBQ18AA3 | CAP**2417AL* | 912SD36040E17*** | 14,600 | $730 |
| No | 207202344 | BRYANT | 38MARBQ18AA3 | CAP**1917AL* | 912SD36040E17*** | 13,900 | $695 |
| No | 207202341 | BRYANT | 38MARBQ18AA3 | CNPV*1814AL* | 912SD30040E14*** | 14,600 | $730 |
| No | 207202343 | BRYANT | 38MARBQ18AA3 | CNPV*2417AL* | 912SD30040E14*** | 14,500 | $725 |
| No | 207202364 | BRYANT | 38MARBQ18AA3 | CAP**2517AL* | 915SB30040E14*** | 13,800 | $690 |
| No | 207202342 | BRYANT | 38MARBQ18AA3 | CNPV*2414AL* | 912SD30040E14*** | 14,500 | $725 |
| No | 207202340 | BRYANT | 38MARBQ18AA3 | CAP**2517AL* | 912SD30040E14*** | 13,700 | $685 |
| No | 207202338 | BRYANT | 38MARBQ18AA3 | CAP**2414AL* | 912SD30040E14*** | 14,500 | $725 |
| No | 207202339 | BRYANT | 38MARBQ18AA3 | CAP**2417AL* | 912SD30040E14*** | 14,500 | $725 |
| No | 207202317 | BRYANT | 38MARBQ18AA3 | CNPV*2417AL* | 83*SA36040E17*** | 14,500 | $725 |
| No | 207202337 | BRYANT | 38MARBQ18AA3 | CAP**1917AL* | 912SD30040E14*** | 13,800 | $690 |
| No | 207202314 | BRYANT | 38MARBQ18AA3 | CAP**1917AL* | 83*SA36040E17*** | 13,700 | $685 |
| No | 207202315 | BRYANT | 38MARBQ18AA3 | CAP**2417AL* | 83*SA36040E17*** | 14,500 | $725 |
| No | 207202316 | BRYANT | 38MARBQ18AA3 | CAP**2517AL* | 83*SA36040E17*** | 13,600 | $680 |
| No | 207202334 | BRYANT | 38MARBQ18AA3 | CAP**1917AL* | 82*TA48090V17*** | 13,900 | $695 |
| No | 207202336 | BRYANT | 38MARBQ18AA3 | CAP**2517AL* | 82*TA48090V17*** | 13,800 | $690 |
| No | 207202335 | BRYANT | 38MARBQ18AA3 | CAP**2417AL* | 82*TA48090V17*** | 14,600 | $730 |
| No | 207202333 | BRYANT | 38MARBQ18AA3 | CAP**2517AL* | 82*TA48070V17*** | 13,800 | $690 |
| No | 207202332 | BRYANT | 38MARBQ18AA3 | CAP**2417AL* | 82*TA48070V17*** | 14,600 | $730 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207202331 | BRYANT | 38MARBQ18AA3 | CAP**1917AL* | 82*TA48070V17*** | 13,900 | $695 |
| No | 207202330 | BRYANT | 38MARBQ18AA3 | CNPV*2417AL* | 82*TA36070V14*** | 14,600 | $730 |
| No | 207202329 | BRYANT | 38MARBQ18AA3 | CNPV*2414AL* | 82*TA36070V14*** | 14,600 | $730 |
| No | 207202328 | BRYANT | 38MARBQ18AA3 | CNPV*1814AL* | 82*TA36070V14*** | 14,700 | $735 |
| No | 207202325 | BRYANT | 38MARBQ18AA3 | CAP**2414AL* | 82*TA36070V14*** | 14,500 | $725 |
| No | 207202326 | BRYANT | 38MARBQ18AA3 | CAP**2417AL* | 82*TA36070V14*** | 14,600 | $730 |
| No | 207202319 | BRYANT | 38MARBQ18AA3 | CAP**2414AL* | 82*TA36045V14*** | 14,600 | $730 |
| No | 207202323 | BRYANT | 38MARBQ18AA3 | CNPV*2417AL* | 82*TA36045V14*** | 14,600 | $730 |
| No | 207202324 | BRYANT | 38MARBQ18AA3 | CAP**1917AL* | 82*TA36070V14*** | 13,900 | $695 |
| No | 207202320 | BRYANT | 38MARBQ18AA3 | CAP**2417AL* | 82*TA36045V14*** | 14,600 | $730 |
| No | 207202322 | BRYANT | 38MARBQ18AA3 | CNPV*2414AL* | 82*TA36045V14*** | 14,600 | $730 |
| No | 207202327 | BRYANT | 38MARBQ18AA3 | CAP**2517AL* | 82*TA36070V14*** | 13,700 | $685 |
| No | 207202318 | BRYANT | 38MARBQ18AA3 | CAP**1917AL* | 82*TA36045V14*** | 13,900 | $695 |
| No | 207202321 | BRYANT | 38MARBQ18AA3 | CAP**2517AL* | 82*TA36045V14*** | 13,800 | $690 |
| No | 207202313 | BRYANT | 38MARBQ18AA3 | CNPV*2417AL* | 8(0,1)*SA36070E17*** | 14,700 | $735 |
| No | 207202312 | BRYANT | 38MARBQ18AA3 | CAP**2417AL* | 8(0,1)*SA36070E17*** | 14,700 | $735 |
| No | 207202309 | BRYANT | 38MARBQ18AA3 | CNPV*1814AL* | 8(0,1)*SA36070E14*** | 14,700 | $735 |
| No | 207202307 | BRYANT | 38MARBQ18AA3 | CAP**2417AL* | 8(0,1)*SA36070E14*** | 14,600 | $730 |
| No | 207202311 | BRYANT | 38MARBQ18AA3 | CNPV*2417AL* | 8(0,1)*SA36070E14*** | 14,600 | $730 |
| No | 207202306 | BRYANT | 38MARBQ18AA3 | CAP**1917AL* | 8(0,1)*SA36070E14*** | 13,900 | $695 |
| No | 207202308 | BRYANT | 38MARBQ18AA3 | CAP**2517AL* | 8(0,1)*SA36070E14*** | 13,800 | $690 |
| No | 207202304 | BRYANT | 38MARBQ18AA3 | CAP**2417AL* | 8(0,1)*SA36045E17*** | 14,600 | $730 |
| No | 207202305 | BRYANT | 38MARBQ18AA3 | CAP**2517AL* | 8(0,1)*SA36045E17*** | 13,800 | $690 |
| No | 207202303 | BRYANT | 38MARBQ18AA3 | CAP**1917AL* | 8(0,1)*SA36045E17*** | 13,900 | $695 |
| No | 207202302 | BRYANT | 38MARBQ18AA3 | CNPV*2417AL* | 8(0,1)*SA36045E14*** | 14,600 | $730 |
| No | 207202300 | BRYANT | 38MARBQ18AA3 | CNPV*1814AL* | 8(0,1)*SA36045E14*** | 14,700 | $735 |
| No | 207202298 | BRYANT | 38MARBQ18AA3 | CAP**2417AL* | 8(0,1)*SA36045E14*** | 14,600 | $730 |
| No | 207202301 | BRYANT | 38MARBQ18AA3 | CNPV*2414AL* | 8(0,1)*SA36045E14*** | 14,600 | $730 |
| No | 207202297 | BRYANT | 38MARBQ18AA3 | CAP**2414AL* | 8(0,1)*SA36045E14*** | 14,600 | $730 |
| No | 207202296 | BRYANT | 38MARBQ18AA3 | CAP**1917AL* | 8(0,1)*SA36045E14*** | 13,800 | $690 |
| No | 207202299 | BRYANT | 38MARBQ18AA3 | CAP**2517AL* | 8(0,1)*SA36045E14*** | 13,800 | $690 |
| No | 207202310 | BRYANT | 38MARBQ18AA3 | CNPV*2414AL* | 8(0,1)*SA36070E14*** | 14,600 | $730 |
| No | 207642901 | BRYANT | 38MGHBQ24CA3 | Heat pump with ducts | | 18,500 | $925 |
| No | 207642898 | BRYANT | 38MGRBQ18BA3 | Heat pump with ducts | | 11,800 | $590 |
| No | 207642916 | BRYANT | 38MGRBQ48EA3 | Heat pump with ducts | | 30,400 | $1,520 |
| No | 207642902 | BRYANT | 38MGHBQ24CA3 | Combination heat pumps with or without ducts | | 16,700 | $835 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207642917 | BRYANT | 38MGRBQ48EA3 | Combination heat pumps with or without ducts | | 30,000 | $1,500 |
| No | 207642899 | BRYANT | 38MGRBQ18BA3 | Combination heat pumps with or without ducts | | 11,400 | $570 |
| No | 207642900 | BRYANT | 38MGHBQ24CA3 | Heat pump without ducts | | 15,000 | $750 |
| No | 207642897 | BRYANT | 38MGRBQ18BA3 | Heat pump without ducts | | 11,000 | $550 |
| No | 207642906 | BRYANT | 38MGRBQ36DA3 | Heat pump without ducts | | 23,400 | $1,170 |
| No | 206400648 | BRYANT | 38MARBQ09AA3 | 619PEQ009BBMA | | 7,500 | $375 |
| No | 201846964 | BRYANT | 38MAQB12R--3 | 40MBDQ12---3 | | 8,500 | $425 |
| No | 206350339 | BRYANT | 38MARBQ09AA3 | 40MBDQ09--3 | | 6,400 | $320 |
| No | 206348143 | BRYANT | 38MARBQ12AA3 | 619AHBQ12XA3 | | 7,500 | $375 |
| No | 206348144 | BRYANT | 38MARBQ18AA3 | 619AHBQ18XA3 | | 10,800 | $540 |
| No | 206350338 | BRYANT | 38MARBQ09AA3 | 40MBCQ09--3 | | 6,100 | $305 |
| No | 206900149 | BRYANT | 38MARBQ30AA3 | CNPV*3017AL* | 8(0,1)*SA36045E17*** | 19,100 | $955 |
| No | 207198867 | BRYANT | 38MARBQ30AA3 | CAP**3014AL* | 8(0,1)*SA36045E14*** | 19,200 | $960 |
| No | 206900147 | BRYANT | 38MARBQ30AA3 | CNPV*3014AL* | 8(0,1)*SA36045E14*** | 19,200 | $960 |
| No | 206900150 | BRYANT | 38MARBQ30AA3 | CAP**3014AL* | 8(0,1)*SA36070E14*** | 19,100 | $955 |
| No | 206900148 | BRYANT | 38MARBQ30AA3 | CAP**3017AL* | 8(0,1)*SA36045E17*** | 19,100 | $955 |
| No | 206900156 | BRYANT | 38MARBQ30AA3 | CNPV*3621AL* | 8(0,1)*SA48090E21*** | 19,300 | $965 |
| No | 206900154 | BRYANT | 38MARBQ30AA3 | CAP**3621AL* | 8(0,1)*SA48070E21*** | 19,000 | $950 |
| No | 206900153 | BRYANT | 38MARBQ30AA3 | CNPV*3017AL* | 8(0,1)*SA48070E17*** | 19,300 | $965 |
| No | 206900151 | BRYANT | 38MARBQ30AA3 | CNPV*3014AL* | 8(0,1)*SA36070E14*** | 19,100 | $955 |
| No | 206900152 | BRYANT | 38MARBQ30AA3 | CAP**3017AL* | 8(0,1)*SA48070E17*** | 19,300 | $965 |
| No | 206900155 | BRYANT | 38MARBQ30AA3 | CNPV*3621AL* | 8(0,1)*SA48070E21*** | 19,100 | $955 |
| No | 206900157 | BRYANT | 38MARBQ30AA3 | CAP**3017AL* | 83*SA36040E17*** | 19,000 | $950 |
| No | 206900159 | BRYANT | 38MARBQ30AA3 | CAP**3014AL* | 82*TA36045V14*** | 19,100 | $955 |
| No | 206900160 | BRYANT | 38MARBQ30AA3 | CNPV*3014AL* | 82*TA36045V14*** | 19,100 | $955 |
| No | 206900158 | BRYANT | 38MARBQ30AA3 | CNPV*3017AL* | 83*SA36040E17*** | 19,000 | $950 |
| No | 206900163 | BRYANT | 38MARBQ30AA3 | CAP**3014AL* | 912SD36060E14*** | 19,200 | $960 |
| No | 206900166 | BRYANT | 38MARBQ30AA3 | CNPV*3017AL* | 912SD42060E17*** | 19,100 | $955 |
| No | 206900164 | BRYANT | 38MARBQ30AA3 | CNPV*3014AL* | 912SD36060E14*** | 19,200 | $960 |
| No | 206900165 | BRYANT | 38MARBQ30AA3 | CAP**3017AL* | 912SD42060E17*** | 19,100 | $955 |
| No | 206900168 | BRYANT | 38MARBQ30AA3 | CNPV*3017AL* | 912SD48080E17*** | 19,100 | $955 |
| No | 206900167 | BRYANT | 38MARBQ30AA3 | CAP**3017AL* | 912SD48080E17*** | 19,100 | $955 |
| No | 207198870 | BRYANT | 38MARBQ30AA3 | CNPV*4217AL* | 915SB30040E14*** | 19,200 | $960 |
| No | 207198873 | BRYANT | 38MARBQ30AA3 | CAP**3717AL* | 915SB36040E17*** | 19,000 | $950 |
| No | 207198869 | BRYANT | 38MARBQ30AA3 | CAP**3717AL* | 915SB30040E14*** | 19,100 | $955 |
| No | 207198875 | BRYANT | 38MARBQ30AA3 | CAP**4321AL* | 915SB36040E17*** | 18,700 | $935 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207198876 | BRYANT | 38MARBQ30AA3 | CNPV*4217AL* | 915SB36040E17*** | 19,100 | $955 |
| No | 206900175 | BRYANT | 38MARBQ30AA3 | CAP**3017AL* | 915SB42060E17*** | 19,300 | $965 |
| No | 207198872 | BRYANT | 38MARBQ30AA3 | CAP**3617AL* | 915SB36040E17*** | 19,300 | $965 |
| No | 207198874 | BRYANT | 38MARBQ30AA3 | CAP**4221AL* | 915SB36040E17*** | 19,200 | $960 |
| No | 206900174 | BRYANT | 38MARBQ30AA3 | CNPV*3014AL* | 915SB36060E14*** | 19,300 | $965 |
| No | 207198871 | BRYANT | 38MARBQ30AA3 | CAP**3621AL* | 915SB36040E17*** | 19,300 | $965 |
| No | 206900171 | BRYANT | 38MARBQ30AA3 | CAP**3017AL* | 915SB36040E17*** | 19,300 | $965 |
| No | 207198878 | BRYANT | 38MARBQ30AA3 | CAP**3617AL* | 915SB36060E14*** | 19,200 | $960 |
| No | 207198880 | BRYANT | 38MARBQ30AA3 | CNPV*3617AL* | 915SB36060E14*** | 19,300 | $965 |
| No | 207198879 | BRYANT | 38MARBQ30AA3 | CAP**3717AL* | 915SB36060E14*** | 19,000 | $950 |
| No | 207198889 | BRYANT | 38MARBQ30AA3 | CNPV*3621AL* | 915SB42060E17*** | 19,200 | $960 |
| No | 207198881 | BRYANT | 38MARBQ30AA3 | CNPV*3017AL* | 915SB36060E14*** | 19,300 | $965 |
| No | 207198882 | BRYANT | 38MARBQ30AA3 | CNPV*4217AL* | 915SB36060E14*** | 19,100 | $955 |
| No | 206900173 | BRYANT | 38MARBQ30AA3 | CAP**3014AL* | 915SB36060E14*** | 19,300 | $965 |
| No | 207198877 | BRYANT | 38MARBQ30AA3 | CAP**3017AL* | 915SB36060E14*** | 19,300 | $965 |
| No | 206900191 | BRYANT | 38MARBQ30AA3 | CAP**3017AL* | 926TB48080V17*** | 19,100 | $955 |
| No | 207198891 | BRYANT | 38MARBQ30AA3 | CNPV*4217AL* | 915SB42060E17*** | 19,000 | $950 |
| No | 207198883 | BRYANT | 38MARBQ30AA3 | CAP**3617AL* | 915SB42060E17*** | 19,200 | $960 |
| No | 207198884 | BRYANT | 38MARBQ30AA3 | CAP**3621AL* | 915SB42060E17*** | 19,200 | $960 |
| No | 206900176 | BRYANT | 38MARBQ30AA3 | CNPV*3017AL* | 915SB42060E17*** | 19,200 | $960 |
| No | 207198885 | BRYANT | 38MARBQ30AA3 | CAP**3717AL* | 915SB42060E17*** | 19,000 | $950 |
| No | 207198888 | BRYANT | 38MARBQ30AA3 | CAP**4321AL* | 915SB42060E17*** | 18,700 | $935 |
| No | 207198886 | BRYANT | 38MARBQ30AA3 | CAP**4221AL* | 915SB42060E17*** | 19,100 | $955 |
| No | 207198887 | BRYANT | 38MARBQ30AA3 | CAP**3721AL* | 915SB42060E17*** | 18,700 | $935 |
| No | 207198890 | BRYANT | 38MARBQ30AA3 | CNPV*3617AL* | 915SB42060E17*** | 19,200 | $960 |
| No | 206900178 | BRYANT | 38MARBQ30AA3 | CNPV*3017AL* | 915SB48080E17*** | 19,300 | $965 |
| No | 207198892 | BRYANT | 38MARBQ30AA3 | CNPV*4221AL* | 915SB42060E17*** | 19,100 | $955 |
| No | 206900177 | BRYANT | 38MARBQ30AA3 | CAP**3017AL* | 915SB48080E17*** | 19,300 | $965 |
| No | 206900179 | BRYANT | 38MARBQ30AA3 | CAP**3621AL* | 915SB60080E21*** | 19,100 | $955 |
| No | 206900185 | BRYANT | 38MARBQ30AA3 | CAP**3017AL* | 926TB36040V17*** | 19,300 | $965 |
| No | 206900188 | BRYANT | 38MARBQ30AA3 | CNPV*3014AL* | 926TB36060V14*** | 19,300 | $965 |
| No | 206900189 | BRYANT | 38MARBQ30AA3 | CAP**3017AL* | 926TB42060V17*** | 19,100 | $955 |
| No | 206900192 | BRYANT | 38MARBQ30AA3 | CNPV*3017AL* | 926TB48080V17*** | 19,100 | $955 |
| No | 206900190 | BRYANT | 38MARBQ30AA3 | CNPV*3017AL* | 926TB42060V17*** | 19,100 | $955 |
| No | 206900196 | BRYANT | 38MARBQ30AA3 | CNPV*3621AL* | 926TB60100V21*** | 20,800 | $1,040 |
| No | 206900181 | BRYANT | 38MARBQ30AA3 | CAP**3017AL* | 935SA36040E17*** | 19,000 | $950 |
| No | 206900193 | BRYANT | 38MARBQ30AA3 | CAP**3621AL* | 926TB60080V21*** | 18,800 | $940 |
| No | 206900195 | BRYANT | 38MARBQ30AA3 | CAP**3621AL* | 926TB60100V21*** | 18,800 | $940 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206900194 | BRYANT | 38MARBQ30AA3 | CNPV*3621AL* | 926TB60080V21*** | 19,000 | $950 |
| No | 206900182 | BRYANT | 38MARBQ30AA3 | CNPV*3017AL* | 935SA36040E17*** | 19,000 | $950 |
| No | 206900197 | BRYANT | 38MARBQ30AA3 | FB4CNF030L | | 19,100 | $955 |
| No | 206905406 | BRYANT | 38MARBQ30AA3 | FV4CN(B,F)003L | | 19,200 | $960 |
| No | 207198866 | BRYANT | 38MARBQ30AA3 | FM(C,U)4Z30**AL* | | 19,200 | $960 |
| No | 206900199 | BRYANT | 38MARBQ30AA3 | FX4DNF031L | | 18,800 | $940 |
| No | 207198865 | BRYANT | 38MARBQ30AA3 | FB4CNP030L | | 19,100 | $955 |
| No | 206900198 | BRYANT | 38MARBQ30AA3 | FMA4X30**AL* | | 19,400 | $970 |
| No | 206188259 | BRYANT | 38MBRBQ48AA3 | 40MBDQ48---3 | | 29,000 | $1,450 |
| No | 206188256 | BRYANT | 38MBRBQ36AA3 | 40MBDQ36---3 | | 27,000 | $1,350 |
| No | 206350341 | BRYANT | 38MARBQ12AA3 | 40MBDQ12--3 | | 8,300 | $415 |
| No | 205788727 | BRYANT | 38MBRBQ48AA3 | 40MBAAQ48XA3 | | 36,000 | $1,800 |
| No | 205788726 | BRYANT | 38MBRBQ36AA3 | 40MBAAQ36XA3 | | 25,000 | $1,250 |
| No | 206400650 | BRYANT | 38MARBQ18AA3 | 619PEQ018BBMA | | 10,800 | $540 |
| No | 206396040 | BRYANT | 38MAQB24R--3 | 619AHBQ24XA3 | | 18,800 | $940 |
| No | 206396038 | BRYANT | 38MAQB12R--3 | 619AHBQ12XA3 | | 7,500 | $375 |
| No | 206396039 | BRYANT | 38MAQB18R--3 | 619AHBQ18XA3 | | 11,000 | $550 |
| No | 206396037 | BRYANT | 38MAQB09R--3 | 619AHBQ09XA3 | | 7,000 | $350 |
| No | 206400651 | BRYANT | 38MARBQ24AA3 | 619PEQ024BBMA | | 19,800 | $990 |
| No | 206348141 | BRYANT | 38MARBQ12AA1 | 619AHBQ12XA1 | | 7,400 | $370 |
| No | 206400649 | BRYANT | 38MARBQ12AA3 | 619PEQ012BBMA | | 7,500 | $375 |
| No | 206348142 | BRYANT | 38MARBQ09AA3 | 619AHBQ09XA3 | | 7,500 | $375 |
| No | 206188258 | BRYANT | 38MBRBQ48AA3 | 40MBCQ48---3 | | 29,000 | $1,450 |
| No | 206350340 | BRYANT | 38MARBQ12AA3 | 40MBCQ12--3 | | 7,900 | $395 |
| No | 206188255 | BRYANT | 38MBRBQ36AA3 | 40MBCQ36---3 | | 22,000 | $1,100 |
| No | 206188254 | BRYANT | 38MBRBQ36AA3 | 40MBFQ36---3 | | 22,000 | $1,100 |
| No | 206188257 | BRYANT | 38MBRBQ48AA3 | 40MBFQ48---3 | | 29,000 | $1,450 |
| No | 206350342 | BRYANT | 38MARBQ12AA3 | 40MBFQ12--3 | | 8,400 | $420 |
| No | 8738645 | BRYANT | 38MAQB12R--3 | 619PEQ012BBMA | | 7,800 | $390 |
| No | 201863368 | BRYANT | 38VMA060HDS3-1 | Heat pump with ducts | | 42,000 | $2,100 |
| No | 205282611 | BRYANT | 38VMB060HDS3-1 | Heat pump with ducts | | 42,000 | $2,100 |
| No | 201863367 | BRYANT | 38VMA060HDS3-1 | Heat pump without ducts | | 42,000 | $2,100 |
| No | 205282610 | BRYANT | 38VMB060HDS3-1 | Heat pump without ducts | | 42,000 | $2,100 |
| No | 205282612 | BRYANT | 38VMB060HDS3-1 | Combination heat pumps with or without ducts | | 42,000 | $2,100 |
| No | 202463636 | BRYANT | 38MPRAQ18AA3 | 619PHAQ18XA3 | | 12,300 | $615 |
| No | 201753409 | BRYANT | 38MPRAQ09AA3 | 619PHAQ09XA3 | | 7,200 | $360 |
| No | 201753412 | BRYANT | 38MPRAQ12AA3 | 619PHAQ12XA3 | | 6,800 | $340 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 200059158 | BRYANT | 38MAQB18R--3 | 40MBCQ18---3 | | 12,000 | $600 |
| No | 8738646 | BRYANT | 38MAQB09R--3 | 619PEQ009BBMA | | 6,900 | $345 |
| No | 8738643 | BRYANT | 38MAQB24R--3 | 619PEQ024BBMA | | 15,400 | $770 |
| No | 201847027 | BRYANT | 38MBRQ58A--3 | 40MBDQ58---3 | | 37,600 | $1,880 |
| No | 201847026 | BRYANT | 38MBRQ48A--3 | 40MBCQ48---3 | | 35,000 | $1,750 |
| No | 200059148 | BRYANT | 38MBRQ48A--3 | 40MBDQ48---3 | | 33,400 | $1,670 |
| No | 201847031 | BRYANT | 38MBRQ58A--3 | 40MBFQ58---3 | | 39,000 | $1,950 |
| No | 8738647 | BRYANT | 38MAQB12R--1 | 619PAQ012BBMA | | 7,600 | $380 |
| No | 200059154 | BRYANT | 38MAQB12R--3 | 40MBCQ12---3 | | 8,700 | $435 |
| No | 201847024 | BRYANT | 38MAQB24R--3 | 40MBCQ24---3 | | 16,200 | $810 |
| No | 200059156 | BRYANT | 38MAQB12R--3 | 40MBFQ12---3 | | 9,600 | $480 |
| No | 8738644 | BRYANT | 38MAQB18R--3 | 619PEQ018BBMA | | 10,800 | $540 |
| No | 201846965 | BRYANT | 38MAQB18R--3 | 40MBFQ18---3 | | 13,400 | $670 |
| No | 200059150 | BRYANT | 38MAQB09R--3 | 40MBCQ09---3 | | 6,700 | $335 |
| No | 200059146 | BRYANT | 38MBRQ36A--3 | 40MBDQ36---3 | | 27,600 | $1,380 |
| No | 201847025 | BRYANT | 38MBRQ36A--3 | 40MBCQ36---3 | | 25,200 | $1,260 |
| No | 201847029 | BRYANT | 38MBRQ36A--3 | 40MBFQ36---3 | | 25,400 | $1,270 |
| No | 201846963 | BRYANT | 38MAQB09R--3 | 40MBDQ09---3 | | 7,200 | $360 |
| No | 200059142 | BRYANT | 38MAQB18R--3 | 40MBDQ18---3 | | 13,400 | $670 |
| No | 202345974 | BRYANT | 38MGRQ48E--3 | Heat pump with ducts | | 34,000 | $1,700 |
| No | 204707614 | BRYANT | 38MGRQ24C--3 | Heat pump with ducts | | 17,600 | $880 |
| No | 202345970 | BRYANT | 38MGRQ18B--3 | Heat pump with ducts | | 11,500 | $575 |
| No | 204722814 | BRYANT | 38MGRQ48E--3 | Combination heat pumps with or without ducts | | 31,800 | $1,590 |
| No | 204722811 | BRYANT | 38MGRQ24C--3 | Combination heat pumps with or without ducts | | 17,400 | $870 |
| No | 204722810 | BRYANT | 38MGRQ18B--3 | Combination heat pumps with or without ducts | | 11,700 | $585 |
| No | 208102133 | Bryant | 38MARBQ30AA311 | 619AHBQ30XA3 | | 19,000 | $950 |
| No | 206348146 | Bryant | 38MARBQ30AA3 | 619AHBQ30XA3 | | 19,000 | $950 |
| No | 208497425 | C&H | CH-55MES-230VO | Heat pump without ducts | | 34,400 | $1,720 |
| No | 207742370 | C&H | CH-48MES-230VO | Heat pump without ducts | | 34,000 | $1,700 |
| No | 207742367 | C&H | CH-36MES-230VO | Heat pump without ducts | | 26,800 | $1,340 |
| No | 207742365 | C&H | CH-28MES-230VO | Heat pump with ducts | | 22,000 | $1,100 |
| No | 207742362 | C&H | CH-18MES-230VO | Heat pump with ducts | | 14,800 | $740 |
| No | 207742364 | C&H | CH-28MES-230VO | Heat pump without ducts | | 21,000 | $1,050 |
| No | 207742361 | C&H | CH-18MES-230VO | Heat pump without ducts | | 14,300 | $715 |
| No | 210665996 | C&H | CH-ES06-115VO | CH-06OLVWM-115VI | | 5,900 | $295 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210434544 | C&H | CH-06OLVWM-115VO | CH-06OLVWM-115VI | | 5,900 | $295 |
| No | 210434545 | C&H | CH-NY06MIA-115VO | CH-NY06MIA-115VI | | 6,800 | $340 |
| No | 209937054 | C&H | CH-HPR18-230VO | CH-16MMC-230VI | | 14,700 | $735 |
| No | 209937053 | C&H | CH-ES18-230VO | CH-16MMC-230VI | | 13,400 | $670 |
| No | 209937051 | C&H | CH-ES12-230VO | CH-12MMC-230VI | | 9,200 | $460 |
| No | 209937052 | C&H | CH-HPR12-230VO | CH-12MMC-230VI | | 10,200 | $510 |
| No | 209937049 | C&H | CH-ES18-230VO | CH-18MASTWM-230VI | | 14,900 | $745 |
| No | 210665990 | C&H | CH-ES18-230VO | CH-B18MOLVWM-230VI | | 14,100 | $705 |
| No | 210665988 | C&H | CH-ES09-230VO | CH-B09MOLVWM-230VI | | 8,100 | $405 |
| No | 210665987 | C&H | CH-HPR06F9-230VO | CH-B06MOLVWM-230VI | | 7,500 | $375 |
| No | 210665985 | C&H | CH-ES09-115VO | CH-B09OLVWM-115VI | | 5,900 | $295 |
| No | 209937048 | C&H | CH-ES24-230VO | CH-24MASTWM-230VI | | 16,200 | $810 |
| No | 209937050 | C&H | CH-ES12-230VO | CH-12MASTWM-230VI | | 9,000 | $450 |
| No | 209937047 | C&H | CH-ES09-230VO | CH-09MASTWM-230VI | | 8,500 | $425 |
| No | 210665991 | C&H | CH-ES24-230VO | CH-B24MOLVWM-230VI | | 17,400 | $870 |
| No | 210665989 | C&H | CH-ES12-230VO | CH-B12MOLVWM-230VI | | 10,000 | $500 |
| No | 210665986 | C&H | CH-ES12-115VO | CH-B12OLVWM-115VI | | 8,900 | $445 |
| No | 210665994 | C&H | CH-HPR18-230VO | CH-B18MOLVWM-230VI | | 11,100 | $555 |
| No | 210665993 | C&H | CH-HPR12-230VO | CH-B12MOLVWM-230VI | | 10,300 | $515 |
| No | 210665992 | C&H | CH-HPR09-230VO | CH-B09MOLVWM-230VI | | 9,300 | $465 |
| No | 207742344 | C&H | CH-N60LCU-230VO | CH-60LCDTU/I | | 34,400 | $1,720 |
| No | 207742345 | C&H | CH-N60LCU-230VO | CH-60LCFC/I | | 35,000 | $1,750 |
| No | 207742322 | C&H | CH-ES18-230VO | CH-M18DTUI | | 12,600 | $630 |
| No | 207742321 | C&H | CH-ES18-230VO | CH-18MSPHCT-230VI | | 12,000 | $600 |
| No | 207742323 | C&H | CH-ES18-230VO | CH-18MSPHFC-230VI | | 12,800 | $640 |
| No | 207740514 | C&H | CH-ES18-230VO | CH-18MOLVWM-230VI | | 14,100 | $705 |
| No | 207740527 | C&H | CH-NY18MIA-230VO | CH-NY18MIA-230VI | | 11,500 | $575 |
| No | 207740525 | C&H | CH-NY09MIA-230VO | CH-NY09MIA-230VI | | 6,900 | $345 |
| No | 207740523 | C&H | CH-NY09MIA-115VO | CH-NY09MIA-115VI | | 6,800 | $340 |
| No | 207742324 | C&H | CH-ES24-230VO | CH-N24MSPHCT-230VI | | 19,000 | $950 |
| No | 207742347 | C&H | CH-NHPR36LCU-230VO | CH-36LCDTU/I | | 34,000 | $1,700 |
| No | 207742342 | C&H | CH-N48LCU-230VO | CH-48LCDTU/I | | 34,000 | $1,700 |
| No | 207742341 | C&H | CH-N48LCU-230VO | CH-N48LCCT-230VI | | 30,000 | $1,500 |
| No | 207742343 | C&H | CH-N48LCU-230VO | CH-48LCFC/I | | 29,000 | $1,450 |
| No | 207742339 | C&H | CH-N36LCU-230VO | CH-36LCDTU/I | | 25,000 | $1,250 |
| No | 207742338 | C&H | CH-N36LCU-230VO | CH-N36LCCT-230VI | | 23,000 | $1,150 |
| No | 207742340 | C&H | CH-N36LCU-230VO | CH-36LCFC/I | | 23,000 | $1,150 |
| No | 207740512 | C&H | CH-ES09-230VO | CH-09MOLVWM-230VI | | 8,100 | $405 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207740518 | C&H | CH-HPR06F9-230VO | CH-06MOLVWM-230VI | | 7,500 | $375 |
| No | 207740500 | C&H | CH-HPR06F9-230VO | CH-06MASTWM-230VI | | 8,500 | $425 |
| No | 207765977 | C&H | CH-ES09-115VO | CH-09OLVWM-115VI | | 5,900 | $295 |
| No | 207740530 | C&H | CH-EL36-230VO | CH-36ELSPHWM-230VI | | 24,000 | $1,200 |
| No | 207740511 | C&H | CH-NY24MIA-230VO | CH-24MOLV-230VI | | 16,500 | $825 |
| No | 207740510 | C&H | CH-NY18MIA-230VO | CH-18MOLV-230VI | | 11,400 | $570 |
| No | 207740509 | C&H | CH-NY12MIA-230VO | CH-12MOLV-230VI | | 7,000 | $350 |
| No | 207740532 | C&H | CH-NY09MIA-230VO | CH-09MOLV-230VI | | 6,000 | $300 |
| No | 207740508 | C&H | CH-NY12MIA-115VO | CH-12OLV-115VI | | 7,800 | $390 |
| No | 207740507 | C&H | CH-NY09MIA-115VO | CH-09OLV-115VI | | 6,300 | $315 |
| No | 207740515 | C&H | CH-ES24-230VO | CH-24MOLVWM-230VI | | 17,400 | $870 |
| No | 207740513 | C&H | CH-ES12-230VO | CH-12MOLVWM-230VI | | 10,000 | $500 |
| No | 207740531 | C&H | CH-ES12-115VO | CH-12OLVWM-115VI | | 8,900 | $445 |
| No | 207740521 | C&H | CH-HPR18-230VO | CH-18MOLVWM-230VI | | 11,100 | $555 |
| No | 207740520 | C&H | CH-HPR12-230VO | CH-12MOLVWM-230VI | | 10,300 | $515 |
| No | 207740519 | C&H | CH-HPR09-230VO | CH-09MOLVWM-230VI | | 9,300 | $465 |
| No | 207742325 | C&H | CH-ES24-230VO | CH-M24DTUI | | 20,000 | $1,000 |
| No | 207742332 | C&H | CH-HPR18-230VO | CH-18MSPHCT-230VI | | 15,600 | $780 |
| No | 207742334 | C&H | CH-HPR18-230VO | CH-18MSPHFC-230VI | | 12,000 | $600 |
| No | 207742331 | C&H | CH-HPR12-230VO | CH-12MSPHMC-230VI | | 9,600 | $480 |
| No | 207742330 | C&H | CH-HPR12-230VO | CH-M12DTUI | | 10,600 | $530 |
| No | 207742329 | C&H | CH-HPR12-230VO | CH-12MSPHCT-230VI | | 9,900 | $495 |
| No | 207742320 | C&H | CH-ES12-230VO | CH-12MSPHMC-230VI | | 9,000 | $450 |
| No | 207742319 | C&H | CH-ES12-230VO | CH-M12DTUI | | 9,300 | $465 |
| No | 207742328 | C&H | CH-HPR09-230VO | CH-M09DTUI | | 10,100 | $505 |
| No | 207742327 | C&H | CH-HPR09-230VO | CH-09MSPHCT-230VI | | 9,000 | $450 |
| No | 207742317 | C&H | CH-ES09-230VO | CH-M09DTUI | | 7,700 | $385 |
| No | 207742326 | C&H | CH-ES24-230VO | CH-24MSPHFC-230VI | | 16,000 | $800 |
| No | 207742318 | C&H | CH-ES12-230VO | CH-12MSPHCT-230VI | | 8,900 | $445 |
| No | 207742316 | C&H | CH-ES09-230VO | CH-09MSPHCT-230VI | | 7,500 | $375 |
| No | 207740502 | C&H | CH-HPR12-230VO | CH-12MASTWM-230VI | | 10,000 | $500 |
| No | 207740501 | C&H | CH-HPR09-230VO | CH-09MASTWM-230VI | | 9,500 | $475 |
| No | 205263867 | C&H | CH-12SPH-115VO | CH-12SPHWM-115VI | | 7,100 | $355 |
| No | 205263866 | C&H | CH-SR09SPH-115VO | CH-SR09SPHWM-115VI | | 7,100 | $355 |
| No | 205263873 | C&H | CH-HYP09SPH230VO | CH-D09MSPHWM-230VI | | 6,900 | $345 |
| No | 205263869 | C&H | CH-18SPH-230VO | CH-18MSPHWM-230VI | | 10,400 | $520 |
| No | 205263874 | C&H | CH-HYP12SPH230VO | CH-D12MSPHWM-230VI | | 7,800 | $390 |
| No | 205263862 | C&H | CH-36LCU/O | CH-36LCCT-230VI | | 25,200 | $1,260 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205263861 | C&H | CH-48LCU/O | CH-48LCCT-230VI | | 35,000 | $1,750 |
| No | 205282616 | C&H | CH-48LCU/O | CH-48LCFCI | | 35,000 | $1,750 |
| No | 205282617 | C&H | CH48MSPH230VO | Heat pump without ducts | | 29,600 | $1,480 |
| No | 205263877 | C&H | CH-09SPH-230VO | CH-D09MSPHWM-230VI | | 5,800 | $290 |
| No | 205263878 | C&H | CH-12SPH-230VO | CH-D12MSPHWM-230VI | | 7,700 | $385 |
| No | 205263889 | C&H | CH36MSPH230VO | Heat pump without ducts | | 24,600 | $1,230 |
| No | 205263880 | C&H | CH-24SPH-230VO | CH-D24MSPHWM-230VI | | 15,300 | $765 |
| No | 205263879 | C&H | CH-18SPH-230VO | CH-D18MSPHWM-230VI | | 11,400 | $570 |
| No | 205287344 | C&H | CH-60LCU/O | CH-60LCFC/I | | 39,000 | $1,950 |
| No | 205282614 | C&H | CH-60LCU/O | CH-60LCFCI | | 39,000 | $1,950 |
| No | 205263851 | C&H | CH-HYP09SPH230VO | CH-M09DTUI | | 7,200 | $360 |
| No | 205263852 | C&H | CH-09SPH-230VO | CH-M09DTUI | | 6,800 | $340 |
| No | 205263853 | C&H | CH-HYP12SPH230VO | CH-M12DTUI | | 8,500 | $425 |
| No | 205263859 | C&H | CH-24SPH-230VO | CH-M24DTUI | | 16,000 | $800 |
| No | 205263856 | C&H | CH-18SPH-230VO | CH-M18DTUI | | 12,000 | $600 |
| No | 202081019 | C&H | CH-09DKT230VO | CH-09DKT230VI | | 6,900 | $345 |
| No | 204098412 | C&H | CH-09SPH-230VO | CH-09MSPHCT-230VI | | 5,800 | $290 |
| No | 205047857 | C&H | CH-09SPH-230VO | CH-09DKT230VI | | 5,800 | $290 |
| No | 205047866 | C&H | CH-HYP36MSPH-230VO | Heat pump with ducts | | 24,600 | $1,230 |
| No | 204098417 | C&H | CH-12DKT230VO | CH-12MSPHCT-230VI | | 8,700 | $435 |
| No | 204098415 | C&H | CH-24SPH-230VO | CH-24MSPHCT-230VI | | 15,800 | $790 |
| No | 203748693 | C&H | CH-09MIA115VO | CH-09MIA115VI | | 6,000 | $300 |
| No | 204098433 | C&H | CH-24SPH-230VO | CH-24MSPHFC-230VI | | 15,000 | $750 |
| No | 9119324 | C&H | CH-09SPH-230VO | CH-09SPH-230VI | | 6,400 | $320 |
| No | 9119326 | C&H | CH-18SPH-230VO | CH-18SPH-230VI | | 10,400 | $520 |
| No | 204098423 | C&H | CH-24SPH-230VO | CH-24LCDTU/I | | 16,000 | $800 |
| No | 202534925 | C&H | CH-48LCU/O | CH-48MSPHCT-230VI | | 35,000 | $1,750 |
| No | 9119323 | C&H | CH-12SPH-115VO | CH-12SPH-115VI | | 7,100 | $355 |
| No | 203456306 | C&H | CH-SR09SPH-115VO | CH-SR09SPH-115VI | | 5,800 | $290 |
| No | 202081220 | C&H | CH-12DKT230VO | CH-12DKT230VI | | 7,800 | $390 |
| No | 204098413 | C&H | CH-12SPH-230VO | CH-12MSPHCT-230VI | | 7,500 | $375 |
| No | 204098429 | C&H | CH-12SPH-230VO | CH-12MSPHMC-230VI | | 7,200 | $360 |
| No | 202534924 | C&H | CH-36LCU/O | CH-36MSPHCT-230VI | | 25,200 | $1,260 |
| No | 204098414 | C&H | CH-18SPH-230VO | CH-18MSPHCT-230VI | | 12,000 | $600 |
| No | 204098432 | C&H | CH-18SPH-230VO | CH-18MSPHFC-230VI | | 12,000 | $600 |
| No | 205047859 | C&H | CH-48LCU/O | CH-48LCFC/I | | 35,000 | $1,750 |
| No | 205047858 | C&H | CH-60LCU/O | CH-60LCFC/I | | 39,000 | $1,950 |
| No | 205047864 | C&H | CH-HYP36MSPH-230VO | Heat pump without ducts | | 23,200 | $1,160 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10443492 | C&H | CH-48LCDTU/O | CH-48LCDTU/I | | 33,400 | $1,670 |
| No | 201755337 | C&H | CH-48LCU/O | CH-48LCDTU/I | | 33,400 | $1,670 |
| No | 205104725 | C&H | CH-12SPH-230VO | CH-12DKT230VI | | 7,700 | $385 |
| No | 205104726 | C&H | CH-18SPH-230VO | CH-18DKT230VI | | 11,400 | $570 |
| No | 205104727 | C&H | CH-24SPH-230VO | CH-24DKT230VI | | 15,300 | $765 |
| No | 204098425 | C&H | CH-12DKT230VO | CH-12LCDTU/I | | 8,500 | $425 |
| No | 202832586 | C&H | CH28MSPH230VO | Heat pump without ducts | | 17,200 | $860 |
| No | 205104722 | C&H | CH18MSPH230VO | Heat pump without ducts | | 12,000 | $600 |
| No | 205104723 | C&H | CH36MSPH230VO | Heat pump without ducts | | 24,600 | $1,230 |
| No | 204098420 | C&H | CH-09SPH-230VO | CH-09LCDTU/I | | 6,800 | $340 |
| No | 205104724 | C&H | CH48MSPH230VO | Heat pump without ducts | | 29,600 | $1,480 |
| No | 204098424 | C&H | CH-09DKT230VO | CH-09LCDTU/I | | 7,200 | $360 |
| No | 201755336 | C&H | CH-36LCU/O | CH-36LCDTU/I | | 27,600 | $1,380 |
| No | 201755338 | C&H | CH-60LCU/O | CH-60LCDTU/I | | 37,600 | $1,880 |
| No | 204098422 | C&H | CH-18SPH-230VO | CH-18LCDTU/I | | 12,000 | $600 |
| No | 201992972 | C&H | CH-09LCU/O | CH-09LCDTU/I | | 6,800 | $340 |
| No | 205741612 | C&H | CH-09SPH-230VO | CH-09MSPHWM-230VI | | 6,400 | $320 |
| No | 205756420 | C&H | CH-NG09MIA115VO | CH-NG09MIA115VI | | 6,000 | $300 |
| No | 201992974 | C&H | CH-18LCU/O | CH-18LCDTU/I | | 12,000 | $600 |
| No | 205756424 | C&H | CH-NG18MIA230VO | CH-NG18MIA230VI | | 11,000 | $550 |
| No | 10507898 | C&H | CH-60LCDTU/O | CH-60LCDTU/I | | 37,600 | $1,880 |
| No | 10443491 | C&H | CH-36LCDTU/O | CH-36LCDTU/I | | 27,600 | $1,380 |
| No | 207742375 | C&H | CH-HPR19M-230VO | Combination heat pumps with or without ducts | | 11,500 | $575 |
| No | 207742372 | C&H | CH-48MES-230VO | Combination heat pumps with or without ducts | | 30,000 | $1,500 |
| No | 207742371 | C&H | CH-48MES-230VO | Heat pump with ducts | | 30,400 | $1,520 |
| No | 207742366 | C&H | CH-28MES-230VO | Combination heat pumps with or without ducts | | 16,000 | $800 |
| No | 207742363 | C&H | CH-18MES-230VO | Combination heat pumps with or without ducts | | 11,400 | $570 |
| No | 207740517 | C&H | CH-EL36-230VO | CH-36ELVWM-230VI | | 20,000 | $1,000 |
| No | 207742378 | C&H | CH-HPR28M-230VO | Combination heat pumps with or without ducts | | 17,000 | $850 |
| No | 208497427 | C&H | CH-55MES-230VO | Combination heat pumps with or without ducts | | 34,600 | $1,730 |
| No | 208497426 | C&H | CH-55MES-230VO | Heat pump with ducts | | 35,000 | $1,750 |
| No | 208816949 | C&H | CH-HPR12-230VO | CH-D12MSPHWM-230VI | | 7,600 | $380 |
| No | 208816948 | C&H | CH-HPR09-230VO | CH-D09MSPHWM-230VI | | 7,100 | $355 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208816950 | C&H | CH-HPR18-230VO | CH-D18MSPHWM-230VI | | 10,900 | $545 |
| No | 206597268 | C&H | CH-NH48LCUO | CH-48AHU | | 36,000 | $1,800 |
| No | 206597267 | C&H | CH-NH36LCUO | CH-36AHU | | 25,000 | $1,250 |
| No | 209550331 | CanAir | MOE30U-48HFN1-MR0 | MAC-48HWFN1-M | | 30,400 | $1,520 |
| No | 209550327 | CanAir | MOX330-18HFN1-MR0 | MAC-24HWDN1-MN0 | | 13,000 | $650 |
| No | 211644137 | CanAir | CDH2048C21 | MAC-48HWFN1-M | | 32,000 | $1,600 |
| No | 209550337 | CanAir | MOE30U-48HFN1-M-[X1] | MAC-48HWFN1-M | | 32,000 | $1,600 |
| No | 209550336 | CanAir | MOE31U-36HFN1-M | MAC-36HWFN1-M | | 33,000 | $1,650 |
| No | 211644138 | CanAir | CDH2036C21 | MAC-36HWFN1-M | | 33,000 | $1,650 |
| No | 209550330 | CanAir | MOD30U-36HFN1-MR0 | MAC-36HWFN1-M | | 19,800 | $990 |
| No | 209550334 | CanAir | MOD30-24HFN1-MW | MAC-24HWDN1-MN0 | | 21,000 | $1,050 |
| No | 211644139 | CanAir | CDH2024C21 | MAC-24HWDN1-MN0 | | 21,000 | $1,050 |
| No | 211644141 | CanAir | CDH2018C21 | MAC-24HWDN1-MN0 | | 14,700 | $735 |
| No | 209550333 | CanAir | MOX430U-18HFN1-M | MAC-24HWDN1-MN0 | | 14,700 | $735 |
| No | 209550332 | CanAir | MOE30U-60HFN1-MR0 | MAC-60HWDN1-MN0 | | 34,000 | $1,700 |
| No | 209550329 | CanAir | MOD30U-30HFN1-MR0 | MAC-36HWFN1-M | | 22,000 | $1,100 |
| No | 209550328 | CanAir | MOX430-24HFN1-MR0 | MAC-24HWDN1-MN0 | | 22,000 | $1,100 |
| No | 208101228 | CanAir | CDH2060C21 | CDH2060F21 | | 37,000 | $1,850 |
| No | 207706571 | CanAir | CDH2036C21 | CDH2036F21 | | 30,400 | $1,520 |
| No | 207706570 | CanAir | CDH2030C21 | CDH2030F21 | | 21,000 | $1,050 |
| No | 211253521 | CANAIR | C25SCH12H21 | C28SEH12H21 | | 9,000 | $450 |
| No | 211253522 | CANAIR | C25SCH09H21 | C28SEH09H21 | | 8,500 | $425 |
| No | 207683268 | CANAIR | C28MC436H21 | Heat pump without ducts | | 26,800 | $1,340 |
| No | 207683266 | CANAIR | C28MC324H21 | Heat pump with ducts | | 21,600 | $1,080 |
| No | 207683265 | CANAIR | C28MC324H21 | Heat pump without ducts | | 20,400 | $1,020 |
| No | 207683263 | CANAIR | C28MC218H21 | Heat pump with ducts | | 14,800 | $740 |
| No | 207683262 | CANAIR | C28MC218H21 | Heat pump without ducts | | 14,300 | $715 |
| No | 207683253 | CanAir | C22SCH18H21 | C22SEH18H21 | | 11,500 | $575 |
| No | 207683251 | CanAir | C22SCH09H21 | C22SEH09H21 | | 6,900 | $345 |
| No | 207683249 | CanAir | C22SCH09H11 | C22SEH09H11 | | 6,800 | $340 |
| No | 207683255 | CanAir | C28SCH06H21 | C28SEH06H21 | | 8,500 | $425 |
| No | 207683257 | CanAir | C28SCH12H21 | C28SEH12H21 | | 10,000 | $500 |
| No | 207683256 | CanAir | C28SCH09H21 | C28SEH09H21 | | 9,500 | $475 |
| No | 205306867 | CANAIR | C23MC218H21 | Heat pump without ducts | | 12,000 | $600 |
| No | 205306868 | CANAIR | C23MC327H21 | Heat pump without ducts | | 17,200 | $860 |
| No | 203913326 | CANAIR | C19SCH09H11 | C19SEH09H11 | | 6,000 | $300 |
| No | 205306870 | CANAIR | C23MC548H21 | Heat pump without ducts | | 29,600 | $1,480 |
| No | 203913330 | CANAIR | C19SCH18H21 | C19SEH18H21 | | 11,000 | $550 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205306861 | CANAIR | C23SCH09H21 | C23SEH09H21 | | 6,900 | $345 |
| No | 205306862 | CANAIR | C23SCH12H21 | C23SEH12H21 | | 7,800 | $390 |
| No | 205816493 | CANAIR | C23SCH18H22 | C23SEH18H21 | | 10,900 | $545 |
| No | 207690477 | CANAIR | CDH2060C21 | CDH2060F21 | | 33,800 | $1,690 |
| No | 207683267 | CANAIR | C28MC324H21 | Combination heat pumps with or without ducts | | 16,700 | $835 |
| No | 207683264 | CANAIR | C28MC218H21 | Combination heat pumps with or without ducts | | 11,400 | $570 |
| No | 210819415 | CARRIER | 38MARBQ30AA3 | 40MBABQ30XB3 | | 20,400 | $1,020 |
| No | 208102137 | CARRIER | 38MARBQ30AA311 | 40MAHBQ30XA3 | | 19,000 | $950 |
| No | 206348139 | CARRIER | 38MARBQ30AA3 | 40MAHBQ30XA3 | | 19,000 | $950 |
| No | 210450190 | CARRIER | 38MURAQ36AB3* | CAP**3617AL* | 59TP6B060V14**12 | 31,200 | $1,560 |
| No | 210450218 | CARRIER | 38MURAQ30AB3* | CAP**3721AL* | GG96VTAA48080B | 20,600 | $1,030 |
| No | 210450177 | CARRIER | 38MURAQ30AB3* | CAP**3721AL* | 59TP6B080V17**16 | 20,600 | $1,030 |
| No | 208447886 | CARRIER | 38MURAQ60AA3 | 40MUAAQ60XA3 | | 37,000 | $1,850 |
| No | 208447879 | CARRIER | 38MURAQ48AA3 | 40MUAAQ48XA3 | | 37,000 | $1,850 |
| No | 208447880 | CARRIER | 38MURAQ36AA3 | 40MUAAQ36XA3 | | 20,400 | $1,020 |
| No | 208447884 | CARRIER | 38MURAQ30AB3 | 40MUAAQ30XA3 | | 21,000 | $1,050 |
| No | 209852144 | CARRIER | 38MURAQ30AA3 | 40MUAAQ30XA3 | | 20,000 | $1,000 |
| No | 208447881 | CARRIER | 38MURAQ24AA3 | 40MUAAQ24XA3 | | 21,000 | $1,050 |
| No | 209911727 | CARRIER | 38MURAQ18AA3 | 40MUAAQ18XA3 | | 12,000 | $600 |
| No | 207642894 | CARRIER | 38MGRBQ48EA3 | Heat pump without ducts | | 29,600 | $1,480 |
| No | 204711106 | CARRIER | 38MGRQ24C--3 | Heat pump without ducts | | 17,200 | $860 |
| No | 9854622 | CARRIER | 38MGRQ24C--3 | Heat pump without ducts | | 13,600 | $680 |
| No | 9118477 | CARRIER | 38MGRQ48E--3 | Heat pump without ducts | | 29,600 | $1,480 |
| No | 9118461 | CARRIER | 38MGRQ18B--3 | Heat pump without ducts | | 12,000 | $600 |
| No | 207202185 | CARRIER | 38MARBQ18AA3 | CAP**2414AL* | 58S(B,C)*A045E14**12 | 14,600 | $730 |
| No | 207202190 | CARRIER | 38MARBQ18AA3 | CNPV*2417AL* | 58S(B,C)*A045E14**12 | 14,600 | $730 |
| No | 206788900 | CARRIER | 25VNA448A*031* | FE4AN(B,F)005L+UI | | 42,500 | $2,125 |
| No | 207826663 | CARRIER | 38MBRCQ58AA3 | 40MBABQ60XA3 | | 34,000 | $1,700 |
| No | 207826661 | CARRIER | 38MBRCQ36AA3 | 40MBABQ36XA3 | | 25,600 | $1,280 |
| No | 207826662 | CARRIER | 38MBRCQ48AA3 | 40MBABQ48XA3 | | 37,400 | $1,870 |
| No | 208104300 | CARRIER | 38MARBQ36AB3 | 40MBABQ36XB3 | | 25,600 | $1,280 |
| No | 207202192 | CARRIER | 38MARBQ18AA3 | CAP**2417AL* | 58S(B,C)*A045E17**12 | 14,600 | $730 |
| No | 207202218 | CARRIER | 38MARBQ18AA3 | CNPV*2417AL* | 58TP*A070V14**12 | 14,600 | $730 |
| No | 207202186 | CARRIER | 38MARBQ18AA3 | CAP**2417AL* | 58S(B,C)*A045E14**12 | 14,600 | $730 |
| No | 207202189 | CARRIER | 38MARBQ18AA3 | CNPV*2414AL* | 58S(B,C)*A045E14**12 | 14,600 | $730 |
| No | 207202188 | CARRIER | 38MARBQ18AA3 | CNPV*1814AL* | 58S(B,C)*A045E14**12 | 14,700 | $735 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207202187 | CARRIER | 38MARBQ18AA3 | CAP**2517AL* | 58S(B,C)*A045E14**12 | 13,800 | $690 |
| No | 207202191 | CARRIER | 38MARBQ18AA3 | CAP**1917AL* | 58S(B,C)*A045E17**12 | 13,900 | $695 |
| No | 207202184 | CARRIER | 38MARBQ18AA3 | CAP**1917AL* | 58S(B,C)*A045E14**12 | 13,800 | $690 |
| No | 207202199 | CARRIER | 38MARBQ18AA3 | CNPV*2417AL* | 58S(B,C)*A070E14**12 | 14,600 | $730 |
| No | 207202198 | CARRIER | 38MARBQ18AA3 | CNPV*2414AL* | 58S(B,C)*A070E14**12 | 14,600 | $730 |
| No | 207202193 | CARRIER | 38MARBQ18AA3 | CAP**2517AL* | 58S(B,C)*A045E17**12 | 13,800 | $690 |
| No | 207202195 | CARRIER | 38MARBQ18AA3 | CAP**2417AL* | 58S(B,C)*A070E14**12 | 14,600 | $730 |
| No | 207202197 | CARRIER | 38MARBQ18AA3 | CNPV*1814AL* | 58S(B,C)*A070E14**12 | 14,700 | $735 |
| No | 207202194 | CARRIER | 38MARBQ18AA3 | CAP**1917AL* | 58S(B,C)*A070E14**12 | 13,900 | $695 |
| No | 207202201 | CARRIER | 38MARBQ18AA3 | CNPV*2417AL* | 58S(B,C)*A070E17**12 | 14,700 | $735 |
| No | 207202196 | CARRIER | 38MARBQ18AA3 | CAP**2517AL* | 58S(B,C)*A070E14**12 | 13,800 | $690 |
| No | 207202203 | CARRIER | 38MARBQ18AA3 | CAP**2417AL* | 58SU*A040E17**12 | 14,500 | $725 |
| No | 207202205 | CARRIER | 38MARBQ18AA3 | CNPV*2417AL* | 58SU*A040E17**12 | 14,500 | $725 |
| No | 207202202 | CARRIER | 38MARBQ18AA3 | CAP**1917AL* | 58SU*A040E17**12 | 13,700 | $685 |
| No | 207202200 | CARRIER | 38MARBQ18AA3 | CAP**2417AL* | 58S(B,C)*A070E17**12 | 14,700 | $735 |
| No | 207202217 | CARRIER | 38MARBQ18AA3 | CNPV*2414AL* | 58TP*A070V14**12 | 14,600 | $730 |
| No | 207202204 | CARRIER | 38MARBQ18AA3 | CAP**2517AL* | 58SU*A040E17**12 | 13,600 | $680 |
| No | 207202211 | CARRIER | 38MARBQ18AA3 | CNPV*2417AL* | 58TP*A045V14**12 | 14,600 | $730 |
| No | 207202208 | CARRIER | 38MARBQ18AA3 | CAP**2417AL* | 58TP*A045V14**12 | 14,600 | $730 |
| No | 207202207 | CARRIER | 38MARBQ18AA3 | CAP**2414AL* | 58TP*A045V14**12 | 14,600 | $730 |
| No | 207202210 | CARRIER | 38MARBQ18AA3 | CNPV*2414AL* | 58TP*A045V14**12 | 14,600 | $730 |
| No | 207202216 | CARRIER | 38MARBQ18AA3 | CNPV*1814AL* | 58TP*A070V14**12 | 14,700 | $735 |
| No | 207202206 | CARRIER | 38MARBQ18AA3 | CAP**1917AL* | 58TP*A045V14**12 | 13,900 | $695 |
| No | 207202214 | CARRIER | 38MARBQ18AA3 | CAP**2417AL* | 58TP*A070V14**12 | 14,600 | $730 |
| No | 207202221 | CARRIER | 38MARBQ18AA3 | CAP**2517AL* | 58TP*A070V17**16 | 13,800 | $690 |
| No | 207202209 | CARRIER | 38MARBQ18AA3 | CAP**2517AL* | 58TP*A045V14**12 | 13,800 | $690 |
| No | 207202212 | CARRIER | 38MARBQ18AA3 | CAP**1917AL* | 58TP*A070V14**12 | 13,900 | $695 |
| No | 207202219 | CARRIER | 38MARBQ18AA3 | CAP**1917AL* | 58TP*A070V17**16 | 13,900 | $695 |
| No | 207202233 | CARRIER | 38MARBQ18AA3 | CAP**2417AL* | 59SC2D040E17**12 | 14,600 | $730 |
| No | 207202220 | CARRIER | 38MARBQ18AA3 | CAP**2417AL* | 58TP*A070V17**16 | 14,600 | $730 |
| No | 207202213 | CARRIER | 38MARBQ18AA3 | CAP**2414AL* | 58TP*A070V14**12 | 14,500 | $725 |
| No | 207202215 | CARRIER | 38MARBQ18AA3 | CAP**2517AL* | 58TP*A070V14**12 | 13,700 | $685 |
| No | 207202223 | CARRIER | 38MARBQ18AA3 | CAP**2417AL* | 58TP*A090V17**16 | 14,600 | $730 |
| No | 207202230 | CARRIER | 38MARBQ18AA3 | CNPV*2414AL* | 59SC2D040E14**10 | 14,500 | $725 |
| No | 207202227 | CARRIER | 38MARBQ18AA3 | CAP**2417AL* | 59SC2D040E14**10 | 14,500 | $725 |
| No | 207202231 | CARRIER | 38MARBQ18AA3 | CNPV*2417AL* | 59SC2D040E14**10 | 14,500 | $725 |
| No | 207202224 | CARRIER | 38MARBQ18AA3 | CAP**2517AL* | 58TP*A090V17**16 | 13,800 | $690 |
| No | 207202226 | CARRIER | 38MARBQ18AA3 | CAP**2414AL* | 59SC2D040E14**10 | 14,500 | $725 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207202222 | CARRIER | 38MARBQ18AA3 | CAP**1917AL* | 58TP*A090V17**16 | 13,900 | $695 |
| No | 207202225 | CARRIER | 38MARBQ18AA3 | CAP**1917AL* | 59SC2D040E14**10 | 13,800 | $690 |
| No | 207202229 | CARRIER | 38MARBQ18AA3 | CNPV*1814AL* | 59SC2D040E14**10 | 14,600 | $730 |
| No | 207202239 | CARRIER | 38MARBQ18AA3 | CNPV*2414AL* | 59SC2D060E14**12 | 14,600 | $730 |
| No | 207202234 | CARRIER | 38MARBQ18AA3 | CNPV*2417AL* | 59SC2D040E17**12 | 14,600 | $730 |
| No | 207202249 | CARRIER | 38MARBQ18AA3 | CAP**1917AL* | 59SC5B040E14**10 | 13,900 | $695 |
| No | 207202232 | CARRIER | 38MARBQ18AA3 | CAP**1917AL* | 59SC2D040E17**12 | 13,900 | $695 |
| No | 207202228 | CARRIER | 38MARBQ18AA3 | CAP**2517AL* | 59SC2D040E14**10 | 13,700 | $685 |
| No | 207202236 | CARRIER | 38MARBQ18AA3 | CAP**2417AL* | 59SC2D060E14**12 | 14,600 | $730 |
| No | 207202238 | CARRIER | 38MARBQ18AA3 | CNPV*1814AL* | 59SC2D060E14**12 | 14,700 | $735 |
| No | 207202235 | CARRIER | 38MARBQ18AA3 | CAP**1917AL* | 59SC2D060E14**12 | 14,000 | $700 |
| No | 207202237 | CARRIER | 38MARBQ18AA3 | CAP**2517AL* | 59SC2D060E14**12 | 13,800 | $690 |
| No | 207202241 | CARRIER | 38MARBQ18AA3 | CAP**2417AL* | 59SC2D080E17**16 | 14,700 | $735 |
| No | 207202240 | CARRIER | 38MARBQ18AA3 | CNPV*2417AL* | 59SC2D060E14**12 | 14,600 | $730 |
| No | 207202242 | CARRIER | 38MARBQ18AA3 | CNPV*2417AL* | 59SC2D080E17**16 | 14,700 | $735 |
| No | 207202244 | CARRIER | 38MARBQ18AA3 | CAP**2417AL* | 59SC5B026E14**10 | 14,700 | $735 |
| No | 207202248 | CARRIER | 38MARBQ18AA3 | CNPV*2417AL* | 59SC5B026E14**10 | 14,700 | $735 |
| No | 207202243 | CARRIER | 38MARBQ18AA3 | CAP**1917AL* | 59SC5B026E14**10 | 14,100 | $705 |
| No | 207202246 | CARRIER | 38MARBQ18AA3 | CNPV*1814AL* | 59SC5B026E14**10 | 14,800 | $740 |
| No | 207202245 | CARRIER | 38MARBQ18AA3 | CAP**2517AL* | 59SC5B026E14**10 | 13,900 | $695 |
| No | 207202247 | CARRIER | 38MARBQ18AA3 | CNPV*2414AL* | 59SC5B026E14**10 | 14,700 | $735 |
| No | 207202255 | CARRIER | 38MARBQ18AA3 | CNPV*2417AL* | 59SC5B040E14**10 | 14,600 | $730 |
| No | 207202258 | CARRIER | 38MARBQ18AA3 | CAP**2517AL* | 59SC5B040E17**12 | 13,700 | $685 |
| No | 207202251 | CARRIER | 38MARBQ18AA3 | CAP**2417AL* | 59SC5B040E14**10 | 14,600 | $730 |
| No | 207202250 | CARRIER | 38MARBQ18AA3 | CAP**2414AL* | 59SC5B040E14**10 | 14,600 | $730 |
| No | 207202254 | CARRIER | 38MARBQ18AA3 | CNPV*2414AL* | 59SC5B040E14**10 | 14,600 | $730 |
| No | 207202279 | CARRIER | 38MARBQ18AA3 | CNPV*2417AL* | 59TP6B040V17**12 | 14,600 | $730 |
| No | 207202259 | CARRIER | 38MARBQ18AA3 | CNPV*2417AL* | 59SC5B040E17**12 | 14,600 | $730 |
| No | 207202257 | CARRIER | 38MARBQ18AA3 | CAP**2417AL* | 59SC5B040E17**12 | 14,600 | $730 |
| No | 207202253 | CARRIER | 38MARBQ18AA3 | CNPV*1814AL* | 59SC5B040E14**10 | 14,700 | $735 |
| No | 207202252 | CARRIER | 38MARBQ18AA3 | CAP**2517AL* | 59SC5B040E14**10 | 13,800 | $690 |
| No | 207202263 | CARRIER | 38MARBQ18AA3 | CAP**2517AL* | 59SC5B060E17**14 | 14,000 | $700 |
| No | 207202256 | CARRIER | 38MARBQ18AA3 | CAP**1917AL* | 59SC5B040E17**12 | 13,800 | $690 |
| No | 207202260 | CARRIER | 38MARBQ18AA3 | CAP**2414AL* | 59SC5B060E14**12 | 14,900 | $745 |
| No | 207202268 | CARRIER | 38MARBQ18AA3 | CNPV*2417AL* | 59SU5A040E17**12 | 14,600 | $730 |
| No | 207202262 | CARRIER | 38MARBQ18AA3 | CAP**1917AL* | 59SC5B060E17**14 | 14,100 | $705 |
| No | 207202261 | CARRIER | 38MARBQ18AA3 | CAP**2417AL* | 59SC5B060E14**12 | 14,900 | $745 |
| No | 207202264 | CARRIER | 38MARBQ18AA3 | CNPV*2417AL* | 59SC5B060E17**14 | 14,700 | $735 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207202266 | CARRIER | 38MARBQ18AA3 | CAP**2417AL* | 59SU5A040E17**12 | 14,600 | $730 |
| No | 207202267 | CARRIER | 38MARBQ18AA3 | CAP**2517AL* | 59SU5A040E17**12 | 13,800 | $690 |
| No | 207202271 | CARRIER | 38MARBQ18AA3 | CAP**2417AL* | 59TP6B040V14**10 | 14,700 | $735 |
| No | 207202265 | CARRIER | 38MARBQ18AA3 | CAP**1917AL* | 59SU5A040E17**12 | 13,800 | $690 |
| No | 207202274 | CARRIER | 38MARBQ18AA3 | CNPV*2414AL* | 59TP6B040V14**10 | 14,700 | $735 |
| No | 207202272 | CARRIER | 38MARBQ18AA3 | CAP**2517AL* | 59TP6B040V14**10 | 13,900 | $695 |
| No | 207202278 | CARRIER | 38MARBQ18AA3 | CAP**2517AL* | 59TP6B040V17**12 | 13,800 | $690 |
| No | 207202275 | CARRIER | 38MARBQ18AA3 | CNPV*2417AL* | 59TP6B040V14**10 | 14,700 | $735 |
| No | 207202273 | CARRIER | 38MARBQ18AA3 | CNPV*1814AL* | 59TP6B040V14**10 | 14,800 | $740 |
| No | 207202269 | CARRIER | 38MARBQ18AA3 | CAP**1917AL* | 59TP6B040V14**10 | 13,900 | $695 |
| No | 207202276 | CARRIER | 38MARBQ18AA3 | CAP**1917AL* | 59TP6B040V17**12 | 13,900 | $695 |
| No | 207202285 | CARRIER | 38MARBQ18AA3 | CNPV*2414AL* | 59TP6B060V14**12 | 14,600 | $730 |
| No | 207202182 | CARRIER | 38MARBQ18AA3 | FB4CNF018L | | 14,700 | $735 |
| No | 207202289 | CARRIER | 38MARBQ18AA3 | CAP**2517AL* | 59TP6B060V17**14 | 13,900 | $695 |
| No | 207202286 | CARRIER | 38MARBQ18AA3 | CNPV*2417AL* | 59TP6B060V14**12 | 14,600 | $730 |
| No | 207202287 | CARRIER | 38MARBQ18AA3 | CAP**1917AL* | 59TP6B060V17**14 | 14,100 | $705 |
| No | 207202282 | CARRIER | 38MARBQ18AA3 | CAP**2417AL* | 59TP6B060V14**12 | 14,600 | $730 |
| No | 207202281 | CARRIER | 38MARBQ18AA3 | CAP**2414AL* | 59TP6B060V14**12 | 14,600 | $730 |
| No | 207202283 | CARRIER | 38MARBQ18AA3 | CAP**2517AL* | 59TP6B060V14**12 | 13,800 | $690 |
| No | 207202284 | CARRIER | 38MARBQ18AA3 | CNPV*1814AL* | 59TP6B060V14**12 | 14,700 | $735 |
| No | 207202280 | CARRIER | 38MARBQ18AA3 | CAP**1917AL* | 59TP6B060V14**12 | 13,800 | $690 |
| No | 207202170 | CARRIER | 38MARBQ18AA3 | FV4CNF002L | | 13,400 | $670 |
| No | 207202290 | CARRIER | 38MARBQ18AA3 | CAP**2517AL* | 59TP6B080V17**16 | 13,800 | $690 |
| No | 207202270 | CARRIER | 38MARBQ18AA3 | CAP**2414AL* | 59TP6B040V14**10 | 14,700 | $735 |
| No | 207202181 | CARRIER | 38MARBQ18AA3 | FX4DNF019L | | 14,500 | $725 |
| No | 207202183 | CARRIER | 38MARBQ18AA3 | FB4CNP018L | | 14,700 | $735 |
| No | 207202277 | CARRIER | 38MARBQ18AA3 | CAP**2417AL* | 59TP6B040V17**12 | 14,600 | $730 |
| No | 207202179 | CARRIER | 38MARBQ18AA3 | FMA4X18**AL* | | 15,000 | $750 |
| No | 207202180 | CARRIER | 38MARBQ18AA3 | FM(C,U)4Z18**AL* | | 15,000 | $750 |
| No | 207202288 | CARRIER | 38MARBQ18AA3 | CAP**2417AL* | 59TP6B060V17**14 | 14,700 | $735 |
| No | 207826660 | CARRIER | 38MARBQ24AA3 | 40MBABQ24XB3 | | 16,200 | $810 |
| No | 208104299 | CARRIER | 38MARBQ30AA311 | 40MBABQ30XB3 | | 19,200 | $960 |
| No | 204430516 | CARRIER | 25VNA036A*030* | CNPV*3617AL*+UI | 59TN6B060C17**14 | 32,800 | $1,640 |
| No | 204430153 | CARRIER | 25VNA036A*030* | CNPV*3617AL*+UI | 59MN7B060C17**14 | 31,400 | $1,570 |
| No | 204430178 | CARRIER | 25VNA036A*030* | CAP**3617AL*+UI | 59TN6B060C17**14 | 33,000 | $1,650 |
| No | 204430159 | CARRIER | 25VNA036A*030* | CNPV*3621AL*+UI | 59MN7B060C17**14 | 31,200 | $1,560 |
| No | 204430172 | CARRIER | 25VNA036A*030* | CAP**3617AL*+UI | 58TN*A045C17**12 | 33,000 | $1,650 |
| No | 204431584 | CARRIER | 25VNA048A*030* | CSPH*4812AL*+UI | 59MN7B120C24**22 | 51,000 | $2,550 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204431587 | CARRIER | 25VNA048A*030* | CSPH*4812AL*+UI | 59TN6B080C21**20 | 51,000 | $2,550 |
| No | 204431408 | CARRIER | 25VNA048A*030* | CAP**4824AL*+UI | 59TN6B080C21**20 | 50,500 | $2,525 |
| No | 204431376 | CARRIER | 25VNA048A*030* | CAP**4821AL*+UI | 58TN*A090C17**16 | 50,500 | $2,525 |
| No | 204431397 | CARRIER | 25VNA048A*030* | CAP**4824AL*+UI | 59MN7B120C24**22 | 50,500 | $2,525 |
| No | 204431379 | CARRIER | 25VNA048A*030* | CAP**4821AL*+UI | 58TN*A110C21**20 | 50,500 | $2,525 |
| No | 204431566 | CARRIER | 25VNA048A*030* | CSPH*4812AL*+UI | 58TN*A090C21**20 | 50,500 | $2,525 |
| No | 204431589 | CARRIER | 25VNA048A*030* | CSPH*4812AL*+UI | 59TN6B100C21**22 | 50,500 | $2,525 |
| No | 204431593 | CARRIER | 25VNA048A*030* | CSPH*4812AL*+UI | 58TN*A090C17**16 | 51,000 | $2,550 |
| No | 204430534 | CARRIER | 25VNA036A*030* | CNPV*3621AL*+UI | 59TN6B080C17**14 | 32,600 | $1,630 |
| No | 204430184 | CARRIER | 25VNA036A*030* | CAP**3617AL*+UI | 59MN7B060C17**14 | 33,000 | $1,650 |
| No | 204430140 | CARRIER | 25VNA036A*030* | CNPV*3621AL*+UI | 58TN*A090C21**20 | 33,000 | $1,650 |
| No | 204431580 | CARRIER | 25VNA048A*030* | CSPH*4812AL*+UI | 59MN7B100C21**22 | 50,500 | $2,525 |
| No | 204431573 | CARRIER | 25VNA048A*030* | CSPH*4812AL*+UI | 59TN6B120C24**22 | 50,500 | $2,525 |
| No | 204431569 | CARRIER | 25VNA048A*030* | CSPH*4812AL*+UI | 58TN*A135C24**22 | 50,500 | $2,525 |
| No | 204431363 | CARRIER | 25VNA048A*030* | CAP**4821AL*+UI | 58TN*A070C21**20 | 50,500 | $2,525 |
| No | 204431382 | CARRIER | 25VNA048A*030* | CAP**4824AL*+UI | 58TN*A070C21**20 | 50,500 | $2,525 |
| No | 204431413 | CARRIER | 25VNA048A*030* | CAP**4824AL*+UI | 59TN6B100C21**22 | 50,500 | $2,525 |
| No | 204431550 | CARRIER | 25VNA048A*030* | CNPV*6024AL*+UI | 59MN7B120C24**22 | 49,500 | $2,475 |
| No | 204431388 | CARRIER | 25VNA048A*030* | CAP**4824AL*+UI | 59MN7B080C21**20 | 50,500 | $2,525 |
| No | 204431391 | CARRIER | 25VNA048A*030* | CAP**4824AL*+UI | 59MN7B100C21**22 | 50,500 | $2,525 |
| No | 204431420 | CARRIER | 25VNA048A*030* | CAP**4824AL*+UI | 58TN*A110C21**20 | 50,500 | $2,525 |
| No | 204431386 | CARRIER | 25VNA048A*030* | CAP**4824AL*+UI | 59TN6B120C24**22 | 50,500 | $2,525 |
| No | 204431365 | CARRIER | 25VNA048A*030* | CAP**4821AL*+UI | 58TN*A090C21**20 | 50,500 | $2,525 |
| No | 204431545 | CARRIER | 25VNA048A*030* | CNPV*6024AL*+UI | 59MN7B100C21**22 | 49,000 | $2,450 |
| No | 204431542 | CARRIER | 25VNA048A*030* | CNPV*6024AL*+UI | 59TN6B120C24**22 | 49,000 | $2,450 |
| No | 204431534 | CARRIER | 25VNA048A*030* | CNPV*6024AL*+UI | 58TN*A090C21**20 | 49,000 | $2,450 |
| No | 204431559 | CARRIER | 25VNA048A*030* | CNPV*6024AL*+UI | 59TN6B100C21**22 | 49,000 | $2,450 |
| No | 204431563 | CARRIER | 25VNA048A*030* | CNPV*6024AL*+UI | 58TN*A110C21**20 | 49,000 | $2,450 |
| No | 204431538 | CARRIER | 25VNA048A*030* | CNPV*6024AL*+UI | 58TN*A135C24**22 | 49,000 | $2,450 |
| No | 204429969 | CARRIER | 25VNA024A*030* | CAP**4221AL*+UI | 59MN7B060C17**14 | 25,200 | $1,260 |
| No | 204430024 | CARRIER | 25VNA024A*030* | CNPV*3014AL*+UI | 58TN*A070C14**12 | 21,400 | $1,070 |
| No | 204429856 | CARRIER | 25VNA024A*030* | CAP**3014AL*+UI | 58TN*A070C14**12 | 21,200 | $1,060 |
| No | 204430016 | CARRIER | 25VNA024A*030* | CAP**4224AL*+UI | 59MN7B120C24**22 | 22,200 | $1,110 |
| No | 204430003 | CARRIER | 25VNA024A*030* | CAP**4221AL*+UI | 59MN7B060C21**20 | 22,200 | $1,110 |
| No | 204429994 | CARRIER | 25VNA024A*030* | CAP**4221AL*+UI | 58TN*A090C17**16 | 22,000 | $1,100 |
| No | 204429983 | CARRIER | 25VNA024A*030* | CAP**4221AL*+UI | 59TN6B080C21**20 | 22,200 | $1,110 |
| No | 205272782 | CARRIER | 25VNA448A*030* | CNPV*6024AL*+UI | 59MN7B120C24**22 | 43,000 | $2,150 |
| No | 205272822 | CARRIER | 25VNA460A*030* | CAP**6124AL*+UI | 59MN7B060C21**20 | 52,000 | $2,600 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205272815 | CARRIER | 25VNA460A*030* | CAP**6121AL*+UI | 59MN7B060C21**20 | 51,500 | $2,575 |
| No | 205272809 | CARRIER | 25VNA460A*030* | CAP**6024AL*+UI | 59MN7B060C21**20 | 52,000 | $2,600 |
| No | 205272833 | CARRIER | 25VNA460A*030* | CNPV*6124AL*+UI | 59MN7B060C21**20 | 51,500 | $2,575 |
| No | 205272819 | CARRIER | 25VNA460A*030* | CAP**6124AL*+UI | 59TN6B080C21**20 | 51,000 | $2,550 |
| No | 205272818 | CARRIER | 25VNA460A*030* | CAP**6124AL*+UI | 59MN7B120C24**22 | 50,500 | $2,525 |
| No | 205272813 | CARRIER | 25VNA460A*030* | CAP**6121AL*+UI | 59TN6B100C21**22 | 50,500 | $2,525 |
| No | 205272816 | CARRIER | 25VNA460A*030* | CAP**6124AL*+UI | 59MN7B080C21**20 | 51,000 | $2,550 |
| No | 205272812 | CARRIER | 25VNA460A*030* | CAP**6121AL*+UI | 59TN6B080C21**20 | 51,000 | $2,550 |
| No | 205272811 | CARRIER | 25VNA460A*030* | CAP**6121AL*+UI | 59MN7B100C21**22 | 50,500 | $2,525 |
| No | 205272810 | CARRIER | 25VNA460A*030* | CAP**6121AL*+UI | 59MN7B080C21**20 | 51,000 | $2,550 |
| No | 205272808 | CARRIER | 25VNA460A*030* | CAP**6024AL*+UI | 58TN*A110C21**20 | 50,500 | $2,525 |
| No | 205272807 | CARRIER | 25VNA460A*030* | CAP**6024AL*+UI | 59TN6B100C21**22 | 50,500 | $2,525 |
| No | 205272803 | CARRIER | 25VNA460A*030* | CAP**6024AL*+UI | 59MN7B080C21**20 | 51,000 | $2,550 |
| No | 205272804 | CARRIER | 25VNA460A*030* | CAP**6024AL*+UI | 59MN7B100C21**22 | 50,500 | $2,525 |
| No | 205272806 | CARRIER | 25VNA460A*030* | CAP**6024AL*+UI | 59TN6B080C21**20 | 51,000 | $2,550 |
| No | 205272805 | CARRIER | 25VNA460A*030* | CAP**6024AL*+UI | 59MN7B120C24**22 | 50,500 | $2,525 |
| No | 205272800 | CARRIER | 25VNA448A*030* | CSPH*6012AL*+UI | 58TN*A090C17**16 | 43,000 | $2,150 |
| No | 205272798 | CARRIER | 25VNA448A*030* | CSPH*6012AL*+UI | 59TN6B080C21**20 | 43,000 | $2,150 |
| No | 205272795 | CARRIER | 25VNA448A*030* | CSPH*6012AL*+UI | 59MN7B080C21**20 | 43,000 | $2,150 |
| No | 205272791 | CARRIER | 25VNA448A*030* | CSPH*6012AL*+UI | 58TN*A070C21**20 | 43,000 | $2,150 |
| No | 205272790 | CARRIER | 25VNA448A*030* | CSPH*4812AL*+UI | 58TN*A110C21**20 | 43,000 | $2,150 |
| No | 205272789 | CARRIER | 25VNA448A*030* | CSPH*4812AL*+UI | 58TN*A090C17**16 | 43,500 | $2,175 |
| No | 205272788 | CARRIER | 25VNA448A*030* | CSPH*4812AL*+UI | 59TN6B100C21**22 | 43,000 | $2,150 |
| No | 205272787 | CARRIER | 25VNA448A*030* | CSPH*4812AL*+UI | 59MN7B120C24**22 | 43,500 | $2,175 |
| No | 205272786 | CARRIER | 25VNA448A*030* | CSPH*4812AL*+UI | 59MN7B100C21**22 | 43,000 | $2,150 |
| No | 205272785 | CARRIER | 25VNA448A*030* | CSPH*4812AL*+UI | 59TN6B120C24**22 | 43,000 | $2,150 |
| No | 205272783 | CARRIER | 25VNA448A*030* | CSPH*4812AL*+UI | 58TN*A090C21**20 | 43,000 | $2,150 |
| No | 205272769 | CARRIER | 25VNA448A*030* | CAP**4824AL*+UI | 59MN7B120C24**22 | 43,000 | $2,150 |
| No | 205272766 | CARRIER | 25VNA448A*030* | CAP**4821AL*+UI | 58TN*A110C21**20 | 43,000 | $2,150 |
| No | 205272765 | CARRIER | 25VNA448A*030* | CAP**4821AL*+UI | 59TN6B100C21**22 | 43,000 | $2,150 |
| No | 205272764 | CARRIER | 25VNA448A*030* | CAP**4821AL*+UI | 59MN7B100C21**22 | 43,000 | $2,150 |
| No | 205272763 | CARRIER | 25VNA448A*030* | CAP**4821AL*+UI | 58TN*A090C21**20 | 43,000 | $2,150 |
| No | 205272830 | CARRIER | 25VNA460A*030* | CNPV*6124AL*+UI | 59TN6B080C21**20 | 50,500 | $2,525 |
| No | 205272832 | CARRIER | 25VNA460A*030* | CNPV*6124AL*+UI | 58TN*A110C21**20 | 50,000 | $2,500 |
| No | 205272829 | CARRIER | 25VNA460A*030* | CNPV*6124AL*+UI | 59MN7B120C24**22 | 50,500 | $2,525 |
| No | 205272831 | CARRIER | 25VNA460A*030* | CNPV*6124AL*+UI | 59TN6B100C21**22 | 50,000 | $2,500 |
| No | 205272827 | CARRIER | 25VNA460A*030* | CNPV*6124AL*+UI | 59MN7B080C21**20 | 50,500 | $2,525 |
| No | 205272828 | CARRIER | 25VNA460A*030* | CNPV*6124AL*+UI | 59MN7B100C21**22 | 50,000 | $2,500 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205272826 | CARRIER | 25VNA460A*030* | CNPV*6124AL*+UI | 59TN6B120C24**22 | 50,500 | $2,525 |
| No | 205272823 | CARRIER | 25VNA460A*030* | CNPV*6124AL*+UI | 58TN*A070C21**20 | 51,000 | $2,550 |
| No | 205272821 | CARRIER | 25VNA460A*030* | CAP**6124AL*+UI | 58TN*A110C21**20 | 50,500 | $2,525 |
| No | 205272814 | CARRIER | 25VNA460A*030* | CAP**6121AL*+UI | 58TN*A110C21**20 | 50,500 | $2,525 |
| No | 205272820 | CARRIER | 25VNA460A*030* | CAP**6124AL*+UI | 59TN6B100C21**22 | 50,500 | $2,525 |
| No | 205272817 | CARRIER | 25VNA460A*030* | CAP**6124AL*+UI | 59MN7B100C21**22 | 50,500 | $2,525 |
| No | 205272801 | CARRIER | 25VNA448A*030* | CSPH*6012AL*+UI | 58TN*A110C21**20 | 43,000 | $2,150 |
| No | 205272799 | CARRIER | 25VNA448A*030* | CSPH*6012AL*+UI | 59TN6B100C21**22 | 43,000 | $2,150 |
| No | 205272797 | CARRIER | 25VNA448A*030* | CSPH*6012AL*+UI | 59MN7B120C24**22 | 43,000 | $2,150 |
| No | 205272796 | CARRIER | 25VNA448A*030* | CSPH*6012AL*+UI | 59MN7B100C21**22 | 43,000 | $2,150 |
| No | 205272793 | CARRIER | 25VNA448A*030* | CSPH*6012AL*+UI | 58TN*A135C24**22 | 42,500 | $2,125 |
| No | 205272794 | CARRIER | 25VNA448A*030* | CSPH*6012AL*+UI | 59TN6B120C24**22 | 43,000 | $2,150 |
| No | 205272792 | CARRIER | 25VNA448A*030* | CSPH*6012AL*+UI | 58TN*A090C21**20 | 42,500 | $2,125 |
| No | 205272781 | CARRIER | 25VNA448A*030* | CNPV*6024AL*+UI | 59TN6B120C24**22 | 43,000 | $2,150 |
| No | 205272780 | CARRIER | 25VNA448A*030* | CNPV*6024AL*+UI | 58TN*A135C24**22 | 42,500 | $2,125 |
| No | 205272778 | CARRIER | 25VNA448A*030* | CAP**6124AL*+UI | 59TN6B120C24**22 | 43,000 | $2,150 |
| No | 205272777 | CARRIER | 25VNA448A*030* | CAP**6124AL*+UI | 58TN*A135C24**22 | 42,500 | $2,125 |
| No | 205272775 | CARRIER | 25VNA448A*030* | CAP**6121AL*+UI | 59TN6B100C21**22 | 43,000 | $2,150 |
| No | 205272776 | CARRIER | 25VNA448A*030* | CAP**6121AL*+UI | 58TN*A110C21**20 | 43,000 | $2,150 |
| No | 205272779 | CARRIER | 25VNA448A*030* | CAP**6124AL*+UI | 59MN7B120C24**22 | 43,000 | $2,150 |
| No | 205272784 | CARRIER | 25VNA448A*030* | CSPH*4812AL*+UI | 58TN*A135C24**22 | 43,000 | $2,150 |
| No | 205272774 | CARRIER | 25VNA448A*030* | CAP**6121AL*+UI | 59MN7B100C21**22 | 43,000 | $2,150 |
| No | 205272771 | CARRIER | 25VNA448A*030* | CAP**6024AL*+UI | 59TN6B120C24**22 | 42,500 | $2,125 |
| No | 205272772 | CARRIER | 25VNA448A*030* | CAP**6024AL*+UI | 59MN7B120C24**22 | 43,000 | $2,150 |
| No | 205272773 | CARRIER | 25VNA448A*030* | CAP**6121AL*+UI | 58TN*A090C21**20 | 43,000 | $2,150 |
| No | 205272770 | CARRIER | 25VNA448A*030* | CAP**6024AL*+UI | 58TN*A135C24**22 | 42,500 | $2,125 |
| No | 205272768 | CARRIER | 25VNA448A*030* | CAP**4824AL*+UI | 59TN6B120C24**22 | 43,000 | $2,150 |
| No | 205272767 | CARRIER | 25VNA448A*030* | CAP**4824AL*+UI | 58TN*A135C24**22 | 43,000 | $2,150 |
| No | 205272761 | CARRIER | 25VNA448A*030* | FE4ANB006L+UI | | 42,500 | $2,125 |
| No | 205272825 | CARRIER | 25VNA460A*030* | CNPV*6124AL*+UI | 58TN*A135C24**22 | 50,000 | $2,500 |
| No | 205272824 | CARRIER | 25VNA460A*030* | CNPV*6124AL*+UI | 58TN*A090C21**20 | 50,500 | $2,525 |
| No | 205272802 | CARRIER | 25VNA460A*030* | FE4ANB006L+UI | | 49,500 | $2,475 |
| No | 205272762 | CARRIER | 25VNA448A*030* | FE4AN(B,F)005L+UI | | 42,500 | $2,125 |
| No | 204344190 | CARRIER | 38MAQB18R--3 | FV4CNF002 | | 11,000 | $550 |
| No | 204344189 | CARRIER | 38MAQB12R--3 | FV4CNF002 | | 6,400 | $320 |
| No | 203380981 | CARRIER | 38MAQB30R--3 | FMA4X30**AL* | | 21,200 | $1,060 |
| No | 203380979 | CARRIER | 38MAQB18R--3 | FMA4X18**AL* | | 10,800 | $540 |
| No | 203380978 | CARRIER | 38MAQB12R--3 | FMA4X18**AL* | | 7,600 | $380 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203380997 | CARRIER | 38MAQB36R--3 | FM(C,U)4Z36**AL* | | 19,000 | $950 |
| No | 203380996 | CARRIER | 38MAQB30R--3 | FM(C,U)4Z30**AL* | | 20,200 | $1,010 |
| No | 207098560 | CARRIER | 38MARBQ24AA3 | CAP**3017AL* | 59TP6B080V17**16 | 15,500 | $775 |
| No | 207098559 | CARRIER | 38MARBQ24AA3 | CNPV*3617AL* | 59TP6B080V17**16 | 15,500 | $775 |
| No | 207098445 | CARRIER | 38MARBQ24AA3 | FM(C,U)4Z24**AL* | | 16,100 | $805 |
| No | 207098549 | CARRIER | 38MARBQ24AA3 | CNPV*2417AL* | 59TP6B060V17**14 | 15,600 | $780 |
| No | 207098557 | CARRIER | 38MARBQ24AA3 | CNPV*3017AL* | 59TP6B080V17**16 | 15,500 | $775 |
| No | 207098555 | CARRIER | 38MARBQ24AA3 | CNPV*2417AL* | 59TP6B080V17**16 | 15,600 | $780 |
| No | 207098554 | CARRIER | 38MARBQ24AA3 | CAP**3017AL* | 59TP6B060V17**14 | 15,500 | $775 |
| No | 207098553 | CARRIER | 38MARBQ24AA3 | CNPV*3617AL* | 59TP6B060V17**14 | 15,500 | $775 |
| No | 207098548 | CARRIER | 38MARBQ24AA3 | CNPV*3014AL* | 59TP6B060V14**12 | 15,600 | $780 |
| No | 207098552 | CARRIER | 38MARBQ24AA3 | CAP**3617AL* | 59TP6B060V17**14 | 15,400 | $770 |
| No | 207098541 | CARRIER | 38MARBQ24AA3 | CAP**3617AL* | 59TP6B040V17**12 | 15,500 | $775 |
| No | 207098537 | CARRIER | 38MARBQ24AA3 | CNPV*3014AL* | 59TP6B040V14**10 | 15,600 | $780 |
| No | 207098536 | CARRIER | 38MARBQ24AA3 | CAP**3014AL* | 59TP6B040V14**10 | 15,600 | $780 |
| No | 207098486 | CARRIER | 38MARBQ24AA3 | CAP**3017AL* | 59SU5A040E17**12 | 15,500 | $775 |
| No | 207098484 | CARRIER | 38MARBQ24AA3 | CAP**3617AL* | 59SU5A040E17**12 | 15,400 | $770 |
| No | 207098558 | CARRIER | 38MARBQ24AA3 | CAP**3617AL* | 59TP6B080V17**16 | 15,400 | $770 |
| No | 207098482 | CARRIER | 38MARBQ24AA3 | CAP**2417AL* | 59SU5A040E17**12 | 15,700 | $785 |
| No | 207098481 | CARRIER | 38MARBQ24AA3 | CNPV*2417AL* | 59SU5A040E17**12 | 15,600 | $780 |
| No | 207098483 | CARRIER | 38MARBQ24AA3 | CNPV*3017AL* | 59SU5A040E17**12 | 15,500 | $775 |
| No | 207098485 | CARRIER | 38MARBQ24AA3 | CNPV*3617AL* | 59SU5A040E17**12 | 15,500 | $775 |
| No | 207098563 | CARRIER | 38MARBQ24AA3 | CAP**3717AL* | 59SC5B060E17**14 | 15,200 | $760 |
| No | 207098527 | CARRIER | 38MARBQ24AA3 | CNPV*2417AL* | 59SC5B060E17**14 | 15,600 | $780 |
| No | 207098562 | CARRIER | 38MARBQ24AA3 | CAP**3621AL* | 59SC5B060E17**14 | 15,400 | $770 |
| No | 207098530 | CARRIER | 38MARBQ24AA3 | CAP**3617AL* | 59SC5B060E17**14 | 15,400 | $770 |
| No | 207098532 | CARRIER | 38MARBQ24AA3 | CAP**3017AL* | 59SC5B060E17**14 | 15,500 | $775 |
| No | 207098528 | CARRIER | 38MARBQ24AA3 | CAP**2417AL* | 59SC5B060E17**14 | 15,800 | $790 |
| No | 207098565 | CARRIER | 38MARBQ24AA3 | CNPV*3621AL* | 59SC5B060E17**14 | 15,500 | $775 |
| No | 207098561 | CARRIER | 38MARBQ24AA3 | CAP**2517AL* | 59SC5B060E17**14 | 15,200 | $760 |
| No | 207098564 | CARRIER | 38MARBQ24AA3 | CAP**3721AL* | 59SC5B060E17**14 | 15,100 | $755 |
| No | 207098531 | CARRIER | 38MARBQ24AA3 | CNPV*3617AL* | 59SC5B060E17**14 | 15,500 | $775 |
| No | 207098551 | CARRIER | 38MARBQ24AA3 | CNPV*3017AL* | 59TP6B060V17**14 | 15,500 | $775 |
| No | 207098547 | CARRIER | 38MARBQ24AA3 | CAP**3014AL* | 59TP6B060V14**12 | 15,600 | $780 |
| No | 207098571 | CARRIER | 38MARBQ24AA3 | CNPV*2417AL* | 59SC5B060E14**12 | 15,600 | $780 |
| No | 207098529 | CARRIER | 38MARBQ24AA3 | CNPV*3017AL* | 59SC5B060E17**14 | 15,500 | $775 |
| No | 207098572 | CARRIER | 38MARBQ24AA3 | CNPV*3017AL* | 59SC5B060E14**12 | 15,500 | $775 |
| No | 207098573 | CARRIER | 38MARBQ24AA3 | CNPV*3617AL* | 59SC5B060E14**12 | 15,500 | $775 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207098570 | CARRIER | 38MARBQ24AA3 | CAP**3717AL* | 59SC5B060E14**12 | 15,300 | $765 |
| No | 207098569 | CARRIER | 38MARBQ24AA3 | CAP**3017AL* | 59SC5B060E14**12 | 15,600 | $780 |
| No | 207098567 | CARRIER | 38MARBQ24AA3 | CAP**2517AL* | 59SC5B060E14**12 | 15,200 | $760 |
| No | 207098568 | CARRIER | 38MARBQ24AA3 | CAP**3617AL* | 59SC5B060E14**12 | 15,500 | $775 |
| No | 207098526 | CARRIER | 38MARBQ24AA3 | CNPV*3014AL* | 59SC5B060E14**12 | 15,500 | $775 |
| No | 207098524 | CARRIER | 38MARBQ24AA3 | CAP**2414AL* | 59SC5B060E14**12 | 15,800 | $790 |
| No | 207098525 | CARRIER | 38MARBQ24AA3 | CAP**3014AL* | 59SC5B060E14**12 | 15,600 | $780 |
| No | 207098578 | CARRIER | 38MARBQ24AA3 | CNPV*3621AL* | 59SC5B040E17**12 | 15,600 | $780 |
| No | 207098577 | CARRIER | 38MARBQ24AA3 | CAP**3721AL* | 59SC5B040E17**12 | 15,200 | $760 |
| No | 207098575 | CARRIER | 38MARBQ24AA3 | CAP**3621AL* | 59SC5B040E17**12 | 15,500 | $775 |
| No | 207098576 | CARRIER | 38MARBQ24AA3 | CAP**3717AL* | 59SC5B040E17**12 | 15,300 | $765 |
| No | 207098521 | CARRIER | 38MARBQ24AA3 | CAP**3017AL* | 59SC5B040E17**12 | 15,600 | $780 |
| No | 207098574 | CARRIER | 38MARBQ24AA3 | CAP**2517AL* | 59SC5B040E17**12 | 15,200 | $760 |
| No | 207098520 | CARRIER | 38MARBQ24AA3 | CNPV*3617AL* | 59SC5B040E17**12 | 15,600 | $780 |
| No | 207098582 | CARRIER | 38MARBQ24AA3 | CAP**3717AL* | 59SC5B040E14**10 | 15,300 | $765 |
| No | 207098519 | CARRIER | 38MARBQ24AA3 | CAP**3617AL* | 59SC5B040E17**12 | 15,500 | $775 |
| No | 207098518 | CARRIER | 38MARBQ24AA3 | CNPV*3017AL* | 59SC5B040E17**12 | 15,600 | $780 |
| No | 207098523 | CARRIER | 38MARBQ24AA3 | CNPV*2414AL* | 59SC5B060E14**12 | 15,600 | $780 |
| No | 207098566 | CARRIER | 38MARBQ24AA3 | CAP**2417AL* | 59SC5B060E14**12 | 15,800 | $790 |
| No | 207098509 | CARRIER | 38MARBQ24AA3 | CAP**2414AL* | 59SC5B026E14**10 | 15,800 | $790 |
| No | 207098511 | CARRIER | 38MARBQ24AA3 | CNPV*3014AL* | 59SC5B026E14**10 | 15,500 | $775 |
| No | 207098502 | CARRIER | 38MARBQ24AA3 | CNPV*2417AL* | 59SC2D080E17**16 | 15,500 | $775 |
| No | 207098507 | CARRIER | 38MARBQ24AA3 | CAP**3017AL* | 59SC2D080E17**16 | 15,400 | $770 |
| No | 207098510 | CARRIER | 38MARBQ24AA3 | CAP**3014AL* | 59SC5B026E14**10 | 15,500 | $775 |
| No | 207098503 | CARRIER | 38MARBQ24AA3 | CAP**2417AL* | 59SC2D080E17**16 | 15,700 | $785 |
| No | 207098506 | CARRIER | 38MARBQ24AA3 | CNPV*3617AL* | 59SC2D080E17**16 | 15,400 | $770 |
| No | 207098501 | CARRIER | 38MARBQ24AA3 | CNPV*3014AL* | 59SC2D060E17**14 | 15,400 | $770 |
| No | 207098505 | CARRIER | 38MARBQ24AA3 | CAP**3617AL* | 59SC2D080E17**16 | 15,400 | $770 |
| No | 207098498 | CARRIER | 38MARBQ24AA3 | CNPV*2414AL* | 59SC2D060E17**14 | 15,500 | $775 |
| No | 207098504 | CARRIER | 38MARBQ24AA3 | CNPV*3017AL* | 59SC2D080E17**16 | 15,400 | $770 |
| No | 207098500 | CARRIER | 38MARBQ24AA3 | CAP**3014AL* | 59SC2D060E17**14 | 15,500 | $775 |
| No | 207098499 | CARRIER | 38MARBQ24AA3 | CAP**2414AL* | 59SC2D060E17**14 | 15,700 | $785 |
| No | 207098494 | CARRIER | 38MARBQ24AA3 | CAP**2414AL* | 59SC2D060E14**12 | 15,700 | $785 |
| No | 207098495 | CARRIER | 38MARBQ24AA3 | CAP**3014AL* | 59SC2D060E14**12 | 15,500 | $775 |
| No | 207098493 | CARRIER | 38MARBQ24AA3 | CNPV*2414AL* | 59SC2D060E14**12 | 15,600 | $780 |
| No | 207098496 | CARRIER | 38MARBQ24AA3 | CNPV*3014AL* | 59SC2D060E14**12 | 15,500 | $775 |
| No | 207098479 | CARRIER | 38MARBQ24AA3 | CNPV*3617AL* | 58TP*A070V17**16 | 15,400 | $770 |
| No | 207098476 | CARRIER | 38MARBQ24AA3 | CAP**2417AL* | 58TP*A070V17**16 | 15,700 | $785 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207098473 | CARRIER | 38MARBQ24AA3 | CAP**3014AL* | 58TP*A045V14**12 | 15,500 | $775 |
| No | 207098478 | CARRIER | 38MARBQ24AA3 | CAP**3617AL* | 58TP*A070V17**16 | 15,400 | $770 |
| No | 207098480 | CARRIER | 38MARBQ24AA3 | CAP**3017AL* | 58TP*A070V17**16 | 15,500 | $775 |
| No | 207098475 | CARRIER | 38MARBQ24AA3 | CNPV*2417AL* | 58TP*A070V17**16 | 15,600 | $780 |
| No | 207098477 | CARRIER | 38MARBQ24AA3 | CNPV*3017AL* | 58TP*A070V17**16 | 15,400 | $770 |
| No | 207098472 | CARRIER | 38MARBQ24AA3 | CAP**2414AL* | 58TP*A045V14**12 | 15,700 | $785 |
| No | 207098469 | CARRIER | 38MARBQ24AA3 | CAP**3617AL* | 58SU*A060E17**16 | 15,400 | $770 |
| No | 207098467 | CARRIER | 38MARBQ24AA3 | CAP**2417AL* | 58SU*A060E17**16 | 15,700 | $785 |
| No | 207098470 | CARRIER | 38MARBQ24AA3 | CNPV*3617AL* | 58SU*A060E17**16 | 15,500 | $775 |
| No | 207098468 | CARRIER | 38MARBQ24AA3 | CNPV*3017AL* | 58SU*A060E17**16 | 15,500 | $775 |
| No | 207098465 | CARRIER | 38MARBQ24AA3 | CAP**3017AL* | 58SU*A040E17**12 | 15,400 | $770 |
| No | 207098461 | CARRIER | 38MARBQ24AA3 | CNPV*2417AL* | 58SU*A040E17**12 | 15,500 | $775 |
| No | 207098463 | CARRIER | 38MARBQ24AA3 | CAP**3617AL* | 58SU*A040E17**12 | 15,300 | $765 |
| No | 207098464 | CARRIER | 38MARBQ24AA3 | CNPV*3617AL* | 58SU*A040E17**12 | 15,400 | $770 |
| No | 207098462 | CARRIER | 38MARBQ24AA3 | CNPV*3017AL* | 58SU*A040E17**12 | 15,400 | $770 |
| No | 207098456 | CARRIER | 38MARBQ24AA3 | CNPV*2417AL* | 58S(B,C)*A070E17**12 | 15,600 | $780 |
| No | 207098459 | CARRIER | 38MARBQ24AA3 | CNPV*3617AL* | 58S(B,C)*A070E17**12 | 15,400 | $770 |
| No | 207098466 | CARRIER | 38MARBQ24AA3 | CNPV*2417AL* | 58SU*A060E17**16 | 15,600 | $780 |
| No | 207098457 | CARRIER | 38MARBQ24AA3 | CNPV*3017AL* | 58S(B,C)*A070E17**12 | 15,400 | $770 |
| No | 207098474 | CARRIER | 38MARBQ24AA3 | CNPV*3014AL* | 58TP*A045V14**12 | 15,500 | $775 |
| No | 207098471 | CARRIER | 38MARBQ24AA3 | CNPV*2414AL* | 58TP*A045V14**12 | 15,600 | $780 |
| No | 207098460 | CARRIER | 38MARBQ24AA3 | CAP**3017AL* | 58S(B,C)*A070E17**12 | 15,500 | $775 |
| No | 207098454 | CARRIER | 38MARBQ24AA3 | CAP**3014AL* | 58S(B,C)*A070E14**12 | 15,500 | $775 |
| No | 207098452 | CARRIER | 38MARBQ24AA3 | CNPV*2414AL* | 58S(B,C)*A070E14**12 | 15,600 | $780 |
| No | 207098455 | CARRIER | 38MARBQ24AA3 | CNPV*3014AL* | 58S(B,C)*A070E14**12 | 15,500 | $775 |
| No | 207098449 | CARRIER | 38MARBQ24AA3 | CAP**3014AL* | 58S(B,C)*A045E14**12 | 15,500 | $775 |
| No | 207098453 | CARRIER | 38MARBQ24AA3 | CAP**2414AL* | 58S(B,C)*A070E14**12 | 15,700 | $785 |
| No | 207098451 | CARRIER | 38MARBQ24AA3 | CAP**3617AL* | 58S(B,C)*A045E17**12 | 15,500 | $775 |
| No | 207098550 | CARRIER | 38MARBQ24AA3 | CAP**2417AL* | 59TP6B060V17**14 | 15,800 | $790 |
| No | 207098448 | CARRIER | 38MARBQ24AA3 | CAP**2414AL* | 58S(B,C)*A045E14**12 | 15,700 | $785 |
| No | 207098447 | CARRIER | 38MARBQ24AA3 | CNPV*2414AL* | 58S(B,C)*A045E14**12 | 15,600 | $780 |
| No | 207098450 | CARRIER | 38MARBQ24AA3 | CNPV*3014AL* | 58S(B,C)*A045E14**12 | 15,500 | $775 |
| No | 207098556 | CARRIER | 38MARBQ24AA3 | CAP**2417AL* | 59TP6B080V17**16 | 15,700 | $785 |
| No | 207098444 | CARRIER | 38MARBQ24AA3 | FMA4X24**AL* | | 16,000 | $800 |
| No | 207098458 | CARRIER | 38MARBQ24AA3 | CAP**3617AL* | 58S(B,C)*A070E17**12 | 15,400 | $770 |
| No | 207098442 | CARRIER | 38MARBQ24AA3 | FX4DNF025L | | 15,500 | $775 |
| No | 207642880 | CARRIER | 38MGHBQ24CA3 | Heat pump with ducts | | 18,500 | $925 |
| No | 207642877 | CARRIER | 38MGRBQ18BA3 | Heat pump with ducts | | 11,800 | $590 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207642881 | CARRIER | 38MGHBQ24CA3 | Combination heat pumps with or without ducts | | 16,700 | $835 |
| No | 207642895 | CARRIER | 38MGRBQ48EA3 | Heat pump with ducts | | 30,400 | $1,520 |
| No | 207642879 | CARRIER | 38MGHBQ24CA3 | Heat pump without ducts | | 15,000 | $750 |
| No | 207642896 | CARRIER | 38MGRBQ48EA3 | Combination heat pumps with or without ducts | | 30,000 | $1,500 |
| No | 207642878 | CARRIER | 38MGRBQ18BA3 | Combination heat pumps with or without ducts | | 11,400 | $570 |
| No | 207642876 | CARRIER | 38MGRBQ18BA3 | Heat pump without ducts | | 11,000 | $550 |
| No | 207642885 | CARRIER | 38MGRBQ36DA3 | Heat pump without ducts | | 23,400 | $1,170 |
| No | 206400642 | CARRIER | 38MARBQ09AA3 | 40MAQB09B--3 | | 7,500 | $375 |
| No | 201846961 | CARRIER | 38MAQB12R--3 | 40MBDQ12---3 | | 8,500 | $425 |
| No | 206788899 | CARRIER | 25VNA448A*031* | FE4ANB006L+UI | | 42,500 | $2,125 |
| No | 206788928 | CARRIER | 25VNA448A*031* | CAP**4821AL*+UI | 59TN6B100C21**22 | 43,000 | $2,150 |
| No | 206788914 | CARRIER | 25VNA448A*031* | CAP**4821AL*+UI | 59MN7B100C21**22 | 43,000 | $2,150 |
| No | 206788904 | CARRIER | 25VNA448A*031* | CAP**6024AL*+UI | 58TN*A135C24**22 | 42,500 | $2,125 |
| No | 206788902 | CARRIER | 25VNA448A*031* | CAP**4821AL*+UI | 58TN*A110C21**20 | 43,000 | $2,150 |
| No | 206788916 | CARRIER | 25VNA448A*031* | CAP**4824AL*+UI | 59MN7B120C24**22 | 43,000 | $2,150 |
| No | 206788909 | CARRIER | 25VNA448A*031* | CSPH*6012AL*+UI | 58TN*A070C21**20 | 43,000 | $2,150 |
| No | 206788925 | CARRIER | 25VNA448A*031* | CSPH*6012AL*+UI | 59MN7B080C21**20 | 43,000 | $2,150 |
| No | 206788940 | CARRIER | 25VNA448A*031* | CSPH*6012AL*+UI | 59TN6B080C21**20 | 43,000 | $2,150 |
| No | 206788912 | CARRIER | 25VNA448A*031* | CSPH*6012AL*+UI | 58TN*A090C17**16 | 43,000 | $2,150 |
| No | 206788903 | CARRIER | 25VNA448A*031* | CAP**4824AL*+UI | 58TN*A135C24**22 | 43,000 | $2,150 |
| No | 206788929 | CARRIER | 25VNA448A*031* | CAP**4824AL*+UI | 59TN6B120C24**22 | 43,000 | $2,150 |
| No | 206788918 | CARRIER | 25VNA448A*031* | CAP**6024AL*+UI | 59MN7B120C24**22 | 43,000 | $2,150 |
| No | 206788931 | CARRIER | 25VNA448A*031* | CAP**6024AL*+UI | 59TN6B120C24**22 | 42,500 | $2,125 |
| No | 206788919 | CARRIER | 25VNA448A*031* | CAP**6121AL*+UI | 59MN7B100C21**22 | 43,000 | $2,150 |
| No | 206788905 | CARRIER | 25VNA448A*031* | CAP**6121AL*+UI | 58TN*A090C21**20 | 43,000 | $2,150 |
| No | 206788906 | CARRIER | 25VNA448A*031* | CAP**6121AL*+UI | 58TN*A110C21**20 | 43,000 | $2,150 |
| No | 206788933 | CARRIER | 25VNA448A*031* | CAP**6121AL*+UI | 59TN6B100C21**22 | 43,000 | $2,150 |
| No | 206788907 | CARRIER | 25VNA448A*031* | CAP**6124AL*+UI | 58TN*A135C24**22 | 42,500 | $2,125 |
| No | 206788934 | CARRIER | 25VNA448A*031* | CAP**6124AL*+UI | 59TN6B120C24**22 | 43,000 | $2,150 |
| No | 206788921 | CARRIER | 25VNA448A*031* | CAP**6124AL*+UI | 59MN7B120C24**22 | 43,000 | $2,150 |
| No | 206788908 | CARRIER | 25VNA448A*031* | CNPV*6024AL*+UI | 58TN*A135C24**22 | 42,500 | $2,125 |
| No | 206788936 | CARRIER | 25VNA448A*031* | CNPV*6024AL*+UI | 59TN6B120C24**22 | 43,000 | $2,150 |
| No | 206788924 | CARRIER | 25VNA448A*031* | CNPV*6024AL*+UI | 59MN7B120C24**22 | 43,000 | $2,150 |
| No | 206788910 | CARRIER | 25VNA448A*031* | CSPH*6012AL*+UI | 58TN*A090C21**20 | 42,500 | $2,125 |
| No | 206788911 | CARRIER | 25VNA448A*031* | CSPH*6012AL*+UI | 58TN*A135C24**22 | 42,500 | $2,125 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206788978 | CARRIER | 25VNA460A*031* | CAP**6121AL*+UI | 59MN7B080C21**20 | 51,000 | $2,550 |
| No | 206788939 | CARRIER | 25VNA448A*031* | CSPH*6012AL*+UI | 59TN6B120C24**22 | 43,000 | $2,150 |
| No | 206788926 | CARRIER | 25VNA448A*031* | CSPH*6012AL*+UI | 59MN7B100C21**22 | 43,000 | $2,150 |
| No | 206788913 | CARRIER | 25VNA448A*031* | CSPH*6012AL*+UI | 58TN*A110C21**20 | 43,000 | $2,150 |
| No | 206788927 | CARRIER | 25VNA448A*031* | CSPH*6012AL*+UI | 59MN7B120C24**22 | 43,000 | $2,150 |
| No | 206788983 | CARRIER | 25VNA460A*031* | CAP**6121AL*+UI | 59MN7B060C21**20 | 51,500 | $2,575 |
| No | 206788973 | CARRIER | 25VNA460A*031* | CAP**6024AL*+UI | 59MN7B120C24**22 | 50,500 | $2,525 |
| No | 206788979 | CARRIER | 25VNA460A*031* | CAP**6121AL*+UI | 59MN7B100C21**22 | 50,500 | $2,525 |
| No | 206788980 | CARRIER | 25VNA460A*031* | CAP**6121AL*+UI | 59TN6B080C21**20 | 51,000 | $2,550 |
| No | 206788981 | CARRIER | 25VNA460A*031* | CAP**6121AL*+UI | 59TN6B100C21**22 | 50,500 | $2,525 |
| No | 206788986 | CARRIER | 25VNA460A*031* | CAP**6124AL*+UI | 59MN7B120C24**22 | 50,500 | $2,525 |
| No | 206788982 | CARRIER | 25VNA460A*031* | CAP**6121AL*+UI | 58TN*A110C21**20 | 50,500 | $2,525 |
| No | 206788988 | CARRIER | 25VNA460A*031* | CAP**6124AL*+UI | 59TN6B100C21**22 | 50,500 | $2,525 |
| No | 206788995 | CARRIER | 25VNA460A*031* | CNPV*6124AL*+UI | 59MN7B080C21**20 | 50,500 | $2,525 |
| No | 206788996 | CARRIER | 25VNA460A*031* | CNPV*6124AL*+UI | 59MN7B100C21**22 | 50,000 | $2,500 |
| No | 206788999 | CARRIER | 25VNA460A*031* | CNPV*6124AL*+UI | 59TN6B100C21**22 | 50,000 | $2,500 |
| No | 206788998 | CARRIER | 25VNA460A*031* | CNPV*6124AL*+UI | 59TN6B080C21**20 | 50,500 | $2,525 |
| No | 206788970 | CARRIER | 25VNA460A*031* | FE4ANB006L+UI | | 49,500 | $2,475 |
| No | 206789000 | CARRIER | 25VNA460A*031* | CNPV*6124AL*+UI | 58TN*A110C21**20 | 50,000 | $2,500 |
| No | 206789001 | CARRIER | 25VNA460A*031* | CNPV*6124AL*+UI | 59MN7B060C21**20 | 51,500 | $2,575 |
| No | 206350328 | CARRIER | 38MARBQ09AA3 | 40MBDQ09--3 | | 6,400 | $320 |
| No | 206348136 | CARRIER | 38MARBQ12AA3 | 40MAHBQ12XA3 | | 7,500 | $375 |
| No | 206348137 | CARRIER | 38MARBQ18AA3 | 40MAHBQ18XA3 | | 10,800 | $540 |
| No | 206350327 | CARRIER | 38MARBQ09AA3 | 40MBCQ09--3 | | 6,100 | $305 |
| No | 207198839 | CARRIER | 38MARBQ30AA3 | CAP**3014AL* | 58S(B,C)*A045E14**12 | 19,200 | $960 |
| No | 206900096 | CARRIER | 38MARBQ30AA3 | CNPV*3017AL* | 58S(B,C)*A045E17**12 | 19,100 | $955 |
| No | 206900095 | CARRIER | 38MARBQ30AA3 | CAP**3017AL* | 58S(B,C)*A045E17**12 | 19,100 | $955 |
| No | 206900097 | CARRIER | 38MARBQ30AA3 | CAP**3014AL* | 58S(B,C)*A070E14**12 | 19,100 | $955 |
| No | 206900102 | CARRIER | 38MARBQ30AA3 | CNPV*3621AL* | 58S(B,C)*A070E21**16 | 19,100 | $955 |
| No | 206900103 | CARRIER | 38MARBQ30AA3 | CNPV*3621AL* | 58S(B,C)*A090E21**16 | 19,300 | $965 |
| No | 206900101 | CARRIER | 38MARBQ30AA3 | CAP**3621AL* | 58S(B,C)*A070E21**16 | 19,000 | $950 |
| No | 206900098 | CARRIER | 38MARBQ30AA3 | CNPV*3014AL* | 58S(B,C)*A070E14**12 | 19,100 | $955 |
| No | 206900099 | CARRIER | 38MARBQ30AA3 | CAP**3017AL* | 58S(B,C)*A070E17**16 | 19,300 | $965 |
| No | 206900100 | CARRIER | 38MARBQ30AA3 | CNPV*3017AL* | 58S(B,C)*A070E17**16 | 19,300 | $965 |
| No | 206900104 | CARRIER | 38MARBQ30AA3 | CAP**3017AL* | 58SU*A040E17**12 | 19,000 | $950 |
| No | 206900111 | CARRIER | 38MARBQ30AA3 | CNPV*3014AL* | 59SC2D060E14**12 | 19,200 | $960 |
| No | 206900107 | CARRIER | 38MARBQ30AA3 | CNPV*3014AL* | 58TP*A045V14**12 | 19,100 | $955 |
| No | 206900105 | CARRIER | 38MARBQ30AA3 | CNPV*3017AL* | 58SU*A040E17**12 | 19,000 | $950 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206900106 | CARRIER | 38MARBQ30AA3 | CAP**3014AL* | 58TP*A045V14**12 | 19,100 | $955 |
| No | 206900121 | CARRIER | 38MARBQ30AA3 | CNPV*3014AL* | 59SC5B060E14**12 | 19,300 | $965 |
| No | 206900110 | CARRIER | 38MARBQ30AA3 | CAP**3014AL* | 59SC2D060E14**12 | 19,200 | $960 |
| No | 206900112 | CARRIER | 38MARBQ30AA3 | CAP**3017AL* | 59SC2D060E17**14 | 19,100 | $955 |
| No | 206900113 | CARRIER | 38MARBQ30AA3 | CNPV*3017AL* | 59SC2D060E17**14 | 19,100 | $955 |
| No | 207198852 | CARRIER | 38MARBQ30AA3 | CNPV*3617AL* | 59SC5B060E14**12 | 19,300 | $965 |
| No | 206900115 | CARRIER | 38MARBQ30AA3 | CNPV*3017AL* | 59SC2D080E17**16 | 19,100 | $955 |
| No | 207198842 | CARRIER | 38MARBQ30AA3 | CNPV*4217AL* | 59SC5B040E14**10 | 19,200 | $960 |
| No | 206900114 | CARRIER | 38MARBQ30AA3 | CAP**3017AL* | 59SC2D080E17**16 | 19,100 | $955 |
| No | 207198841 | CARRIER | 38MARBQ30AA3 | CAP**3717AL* | 59SC5B040E14**10 | 19,100 | $955 |
| No | 207198847 | CARRIER | 38MARBQ30AA3 | CAP**4321AL* | 59SC5B040E17**12 | 18,700 | $935 |
| No | 207198848 | CARRIER | 38MARBQ30AA3 | CNPV*4217AL* | 59SC5B040E17**12 | 19,100 | $955 |
| No | 207198845 | CARRIER | 38MARBQ30AA3 | CAP**3717AL* | 59SC5B040E17**12 | 19,000 | $950 |
| No | 207198843 | CARRIER | 38MARBQ30AA3 | CAP**3621AL* | 59SC5B040E17**12 | 19,300 | $965 |
| No | 207198844 | CARRIER | 38MARBQ30AA3 | CAP**3617AL* | 59SC5B040E17**12 | 19,300 | $965 |
| No | 207198846 | CARRIER | 38MARBQ30AA3 | CAP**4221AL* | 59SC5B040E17**12 | 19,200 | $960 |
| No | 206900118 | CARRIER | 38MARBQ30AA3 | CAP**3017AL* | 59SC5B040E17**12 | 19,300 | $965 |
| No | 207198851 | CARRIER | 38MARBQ30AA3 | CAP**3717AL* | 59SC5B060E14**12 | 19,000 | $950 |
| No | 207198850 | CARRIER | 38MARBQ30AA3 | CAP**3617AL* | 59SC5B060E14**12 | 19,200 | $960 |
| No | 207198854 | CARRIER | 38MARBQ30AA3 | CNPV*4217AL* | 59SC5B060E14**12 | 19,100 | $955 |
| No | 206900120 | CARRIER | 38MARBQ30AA3 | CAP**3014AL* | 59SC5B060E14**12 | 19,300 | $965 |
| No | 207198849 | CARRIER | 38MARBQ30AA3 | CAP**3017AL* | 59SC5B060E14**12 | 19,300 | $965 |
| No | 207198853 | CARRIER | 38MARBQ30AA3 | CNPV*3017AL* | 59SC5B060E14**12 | 19,300 | $965 |
| No | 206900135 | CARRIER | 38MARBQ30AA3 | CNPV*3014AL* | 59TP6B060V14**12 | 19,300 | $965 |
| No | 207198857 | CARRIER | 38MARBQ30AA3 | CAP**3717AL* | 59SC5B060E17**14 | 19,000 | $950 |
| No | 207198859 | CARRIER | 38MARBQ30AA3 | CAP**3721AL* | 59SC5B060E17**14 | 18,700 | $935 |
| No | 207198860 | CARRIER | 38MARBQ30AA3 | CAP**4321AL* | 59SC5B060E17**14 | 18,700 | $935 |
| No | 206900122 | CARRIER | 38MARBQ30AA3 | CAP**3017AL* | 59SC5B060E17**14 | 19,300 | $965 |
| No | 207198863 | CARRIER | 38MARBQ30AA3 | CNPV*4217AL* | 59SC5B060E17**14 | 19,000 | $950 |
| No | 207198855 | CARRIER | 38MARBQ30AA3 | CAP**3617AL* | 59SC5B060E17**14 | 19,200 | $960 |
| No | 207198856 | CARRIER | 38MARBQ30AA3 | CAP**3621AL* | 59SC5B060E17**14 | 19,200 | $960 |
| No | 207198858 | CARRIER | 38MARBQ30AA3 | CAP**4221AL* | 59SC5B060E17**14 | 19,100 | $955 |
| No | 207198864 | CARRIER | 38MARBQ30AA3 | CNPV*4221AL* | 59SC5B060E17**14 | 19,100 | $955 |
| No | 207198861 | CARRIER | 38MARBQ30AA3 | CNPV*3621AL* | 59SC5B060E17**14 | 19,200 | $960 |
| No | 206900123 | CARRIER | 38MARBQ30AA3 | CNPV*3017AL* | 59SC5B060E17**14 | 19,200 | $960 |
| No | 206900124 | CARRIER | 38MARBQ30AA3 | CAP**3017AL* | 59SC5B080E17**16 | 19,300 | $965 |
| No | 207198862 | CARRIER | 38MARBQ30AA3 | CNPV*3617AL* | 59SC5B060E17**14 | 19,200 | $960 |
| No | 206900126 | CARRIER | 38MARBQ30AA3 | CAP**3621AL* | 59SC5B080E21**20 | 19,100 | $955 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206900125 | CARRIER | 38MARBQ30AA3 | CNPV*3017AL* | 59SC5B080E17**16 | 19,300 | $965 |
| No | 206900128 | CARRIER | 38MARBQ30AA3 | CAP**3017AL* | 59SU5A040E17**12 | 19,000 | $950 |
| No | 206900132 | CARRIER | 38MARBQ30AA3 | CAP**3017AL* | 59TP6B040V17**12 | 19,300 | $965 |
| No | 206900129 | CARRIER | 38MARBQ30AA3 | CNPV*3017AL* | 59SU5A040E17**12 | 19,000 | $950 |
| No | 206900138 | CARRIER | 38MARBQ30AA3 | CAP**3017AL* | 59TP6B080V17**16 | 19,100 | $955 |
| No | 206900137 | CARRIER | 38MARBQ30AA3 | CNPV*3017AL* | 59TP6B060V17**14 | 19,100 | $955 |
| No | 206900139 | CARRIER | 38MARBQ30AA3 | CNPV*3017AL* | 59TP6B080V17**16 | 19,100 | $955 |
| No | 206900136 | CARRIER | 38MARBQ30AA3 | CAP**3017AL* | 59TP6B060V17**14 | 19,100 | $955 |
| No | 206900141 | CARRIER | 38MARBQ30AA3 | CNPV*3621AL* | 59TP6B080V21**20 | 19,000 | $950 |
| No | 206900140 | CARRIER | 38MARBQ30AA3 | CAP**3621AL* | 59TP6B080V21**20 | 18,800 | $940 |
| No | 207198837 | CARRIER | 38MARBQ30AA3 | FB4CNP030L | | 19,100 | $955 |
| No | 206900143 | CARRIER | 38MARBQ30AA3 | CNPV*3621AL* | 59TP6B100V21**20 | 20,800 | $1,040 |
| No | 206900142 | CARRIER | 38MARBQ30AA3 | CAP**3621AL* | 59TP6B100V21**20 | 18,800 | $940 |
| No | 206900146 | CARRIER | 38MARBQ30AA3 | FX4DNF031L | | 18,800 | $940 |
| No | 206900144 | CARRIER | 38MARBQ30AA3 | FB4CNF030L | | 19,100 | $955 |
| No | 207198838 | CARRIER | 38MARBQ30AA3 | FM(C,U)4Z30**AL* | | 19,200 | $960 |
| No | 206905408 | CARRIER | 38MARBQ30AA3 | FV4CN(B,F)003L | | 19,200 | $960 |
| No | 206900145 | CARRIER | 38MARBQ30AA3 | FMA4X30**AL* | | 19,400 | $970 |
| No | 205788722 | CARRIER | 38MBRBQ36AA3 | 40MBAAQ36XA3 | | 25,000 | $1,250 |
| No | 206188249 | CARRIER | 38MBRBQ36AA3 | 40MBDQ36---3 | | 27,000 | $1,350 |
| No | 206188252 | CARRIER | 38MBRBQ48AA3 | 40MBDQ48---3 | | 29,000 | $1,450 |
| No | 206350330 | CARRIER | 38MARBQ12AA3 | 40MBDQ12--3 | | 8,300 | $415 |
| No | 205788723 | CARRIER | 38MBRBQ48AA3 | 40MBAAQ48XA3 | | 36,000 | $1,800 |
| No | 206396031 | CARRIER | 38MAQB12R--3 | 40MAHBQ12XA3 | | 7,500 | $375 |
| No | 206396033 | CARRIER | 38MAQB24R--3 | 40MAHBQ24XA3 | | 18,800 | $940 |
| No | 206400644 | CARRIER | 38MARBQ18AA3 | 40MAQB18B--3 | | 10,800 | $540 |
| No | 206396032 | CARRIER | 38MAQB18R--3 | 40MAHBQ18XA3 | | 11,000 | $550 |
| No | 206400645 | CARRIER | 38MARBQ24AA3 | 40MAQB24B--3 | | 19,800 | $990 |
| No | 206396030 | CARRIER | 38MAQB09R--3 | 40MAHBQ09XA3 | | 7,000 | $350 |
| No | 206348134 | CARRIER | 38MARBQ12AA1 | 40MAHBQ12XA1 | | 7,400 | $370 |
| No | 206400643 | CARRIER | 38MARBQ12AA3 | 40MAQB12B--3 | | 7,500 | $375 |
| No | 206348135 | CARRIER | 38MARBQ09AA3 | 40MAHBQ09XA3 | | 7,500 | $375 |
| No | 206188251 | CARRIER | 38MBRBQ48AA3 | 40MBCQ48---3 | | 29,000 | $1,450 |
| No | 206188248 | CARRIER | 38MBRBQ36AA3 | 40MBCQ36---3 | | 22,000 | $1,100 |
| No | 206350329 | CARRIER | 38MARBQ12AA3 | 40MBCQ12--3 | | 7,900 | $395 |
| No | 206188247 | CARRIER | 38MBRBQ36AA3 | 40MBFQ36---3 | | 22,000 | $1,100 |
| No | 206188250 | CARRIER | 38MBRBQ48AA3 | 40MBFQ48---3 | | 29,000 | $1,450 |
| No | 206350331 | CARRIER | 38MARBQ12AA3 | 40MBFQ12--3 | | 8,400 | $420 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 8738636 | CARRIER | 38MAQB12R--3 | 40MAQB12B--3 | | 7,800 | $390 |
| No | 201863362 | CARRIER | 38VMA060HDS3-1 | Heat pump with ducts | | 42,000 | $2,100 |
| No | 205282602 | CARRIER | 38VMB060HDS3-1 | Heat pump with ducts | | 42,000 | $2,100 |
| No | 205282601 | CARRIER | 38VMB060HDS3-1 | Heat pump without ducts | | 42,000 | $2,100 |
| No | 201863361 | CARRIER | 38VMA060HDS3-1 | Heat pump without ducts | | 42,000 | $2,100 |
| No | 205282603 | CARRIER | 38VMB060HDS3-1 | Combination heat pumps with or without ducts | | 42,000 | $2,100 |
| No | 202463634 | CARRIER | 38MPRAQ18AA3 | 40MPHAQ18XA3 | | 12,300 | $615 |
| No | 201753408 | CARRIER | 38MPRAQ09AA3 | 40MPHAQ09XA3 | | 7,200 | $360 |
| No | 201753411 | CARRIER | 38MPRAQ12AA3 | 40MPHAQ12XA3 | | 6,800 | $340 |
| No | 200059159 | CARRIER | 38MAQB18R--3 | 40MBCQ18---3 | | 12,000 | $600 |
| No | 8738638 | CARRIER | 38MAQB24R--3 | 40MAQB24B--3 | | 15,400 | $770 |
| No | 8738635 | CARRIER | 38MAQB09R--3 | 40MAQB09B--3 | | 6,900 | $345 |
| No | 201847014 | CARRIER | 38MBRQ58A--3 | 40MBDQ58---3 | | 37,600 | $1,880 |
| No | 201847013 | CARRIER | 38MBRQ48A--3 | 40MBCQ48---3 | | 35,000 | $1,750 |
| No | 200059149 | CARRIER | 38MBRQ48A--3 | 40MBDQ48---3 | | 33,400 | $1,670 |
| No | 201847018 | CARRIER | 38MBRQ58A--3 | 40MBFQ58---3 | | 39,000 | $1,950 |
| No | 8738634 | CARRIER | 38MAQB12R--1 | 40MAQB12B--1 | | 7,600 | $380 |
| No | 200059155 | CARRIER | 38MAQB12R--3 | 40MBCQ12---3 | | 8,700 | $435 |
| No | 201847011 | CARRIER | 38MAQB24R--3 | 40MBCQ24---3 | | 16,200 | $810 |
| No | 200059157 | CARRIER | 38MAQB12R--3 | 40MBFQ12---3 | | 9,600 | $480 |
| No | 8738637 | CARRIER | 38MAQB18R--3 | 40MAQB18B--3 | | 10,800 | $540 |
| No | 201846962 | CARRIER | 38MAQB18R--3 | 40MBFQ18---3 | | 13,400 | $670 |
| No | 200059151 | CARRIER | 38MAQB09R--3 | 40MBCQ09---3 | | 6,700 | $335 |
| No | 200059147 | CARRIER | 38MBRQ36A--3 | 40MBDQ36---3 | | 27,600 | $1,380 |
| No | 201847012 | CARRIER | 38MBRQ36A--3 | 40MBCQ36---3 | | 25,200 | $1,260 |
| No | 201847016 | CARRIER | 38MBRQ36A--3 | 40MBFQ36---3 | | 25,400 | $1,270 |
| No | 201846960 | CARRIER | 38MAQB09R--3 | 40MBDQ09---3 | | 7,200 | $360 |
| No | 200059143 | CARRIER | 38MAQB18R--3 | 40MBDQ18---3 | | 13,400 | $670 |
| No | 202345969 | CARRIER | 38MGRQ48E--3 | Heat pump with ducts | | 34,000 | $1,700 |
| No | 204707613 | CARRIER | 38MGRQ24C--3 | Heat pump with ducts | | 17,600 | $880 |
| No | 202345965 | CARRIER | 38MGRQ18B--3 | Heat pump with ducts | | 11,500 | $575 |
| No | 204722799 | CARRIER | 38MGRQ48E--3 | Combination heat pumps with or without ducts | | 31,800 | $1,590 |
| No | 204722796 | CARRIER | 38MGRQ24C--3 | Combination heat pumps with or without ducts | | 17,400 | $870 |
| No | 204722795 | CARRIER | 38MGRQ18B--3 | Combination heat pumps with or without ducts | | 11,700 | $585 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 200059086 | CENTURY | A-VFH24TB-1 | Heat pump without ducts | | 16,600 | $830 |
| No | 200059084 | CENTURY | A-VFH18DB-1 | Heat pump without ducts | | 12,800 | $640 |
| No | 200059088 | CENTURY | A-VFH30QB-1 | Heat pump without ducts | | 18,000 | $900 |
| No | 200059090 | CENTURY | A-VFH36QB-1 | Heat pump without ducts | | 20,000 | $1,000 |
| No | 200059092 | CENTURY | A-VFH42PB-1 | Heat pump without ducts | | 29,000 | $1,450 |
| No | 207071468 | CENTURY | HRG1860S1P | E*1P50C+H4TXV03 | GUH96T110C5M | 39,500 | $1,975 |
| No | 207071456 | CENTURY | HRG1860S1P | E*1P50C+H4TXV03 | GUH80C090C5M | 40,000 | $2,000 |
| No | 207071460 | CENTURY | HRG1860S1P | E*1P50C+H4TXV03 | GUH92C110C5M | 40,000 | $2,000 |
| No | 207071464 | CENTURY | HRG1860S1P | E*1P50C+H4TXV03 | GUH96C110C5M | 40,500 | $2,025 |
| No | 207071466 | CENTURY | HRG1860S1P | E*1P50C+H4TXV03 | GUH96T090C5M | 40,000 | $2,000 |
| No | 207071462 | CENTURY | HRG1860S1P | E*1P50C+H4TXV03 | GUH95C110C5M | 40,000 | $2,000 |
| No | 207071538 | CENTURY | HRG1860S1P | ED1P60D+H4TXV03 | GDD95C110C5M | 37,400 | $1,870 |
| No | 207071518 | CENTURY | HRG1860S1P | EAC4X60D | GUH96T135D5M | 39,500 | $1,975 |
| No | 207071516 | CENTURY | HRG1860S1P | EAC4X60D | GUH80C135D5M | 39,500 | $1,975 |
| No | 207071486 | CENTURY | HRG1860S1P | EA(C,U)1P60D+H4TXV03 | GUH96T135D5M | 39,500 | $1,975 |
| No | 207071514 | CENTURY | HRG1860S1P | EAC4X60C | GUH96T110C5M | 37,600 | $1,880 |
| No | 207071484 | CENTURY | HRG1860S1P | EA(C,U)1P60D+H4TXV03 | GUH80C135D5M | 39,500 | $1,975 |
| No | 207071512 | CENTURY | HRG1860S1P | EAC4X60C | GUH96T090C5M | 37,800 | $1,890 |
| No | 207071510 | CENTURY | HRG1860S1P | EAC4X60C | GUH96C110C5M | 37,400 | $1,870 |
| No | 207071504 | CENTURY | HRG1860S1P | EAC4X60C | GUH80C110C5M | 37,200 | $1,860 |
| No | 207071506 | CENTURY | HRG1860S1P | EAC4X60C | GUH92C110C5M | 38,000 | $1,900 |
| No | 207071502 | CENTURY | HRG1860S1P | EAC4X60C | GUH80C090C5M | 37,200 | $1,860 |
| No | 207071508 | CENTURY | HRG1860S1P | EAC4X60C | GUH95C110C5M | 37,200 | $1,860 |
| No | 207071482 | CENTURY | HRG1860S1P | EA(C,U)1P60C+H4TXV03 | GUH96T110C5M | 37,600 | $1,880 |
| No | 207071480 | CENTURY | HRG1860S1P | EA(C,U)1P60C+H4TXV03 | GUH96T090C5M | 37,800 | $1,890 |
| No | 207071478 | CENTURY | HRG1860S1P | EA(C,U)1P60C+H4TXV03 | GUH96C110C5M | 37,400 | $1,870 |
| No | 207071474 | CENTURY | HRG1860S1P | EA(C,U)1P60C+H4TXV03 | GUH92C110C5M | 38,000 | $1,900 |
| No | 207071472 | CENTURY | HRG1860S1P | EA(C,U)1P60C+H4TXV03 | GUH80C110C5M | 37,200 | $1,860 |
| No | 207071470 | CENTURY | HRG1860S1P | EA(C,U)1P60C+H4TXV03 | GUH80C090C5M | 37,200 | $1,860 |
| No | 207071476 | CENTURY | HRG1860S1P | EA(C,U)1P60C+H4TXV03 | GUH95C110C5M | 37,200 | $1,860 |
| No | 207071454 | CENTURY | HRG1860S1P | HMG60X1P | | 37,800 | $1,890 |
| No | 207071452 | CENTURY | HRG1860S1P | HCG60V1P | | 37,400 | $1,870 |
| No | 207071656 | CENTURY | HRG1860S1P | ED1P50/60C+H4TXV02 | GDD95C090C4M | 30,600 | $1,530 |
| No | 207071658 | CENTURY | HRG1860S1P | ED1P50/60C+H4TXV02 | GDD95C110C5M | 30,400 | $1,520 |
| No | 207071558 | CENTURY | HRG1860S1P | HCG48V1P | | 30,800 | $1,540 |
| No | 207071556 | CENTURY | HRG1860S1P | HMG48X1P | | 30,800 | $1,540 |
| No | 207071660 | CENTURY | HRG1860S1P | ED1P50/60C+H4TXV02 | GDD96C090C4M | 30,800 | $1,540 |
| No | 207071027 | CENTURY | HRG1836S1P | HMG36F1P+H4TXV01 | | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207071654 | CENTURY | HRG1860S1P | ED1P50/60C+H4TXV02 | GDD92C090C4M | 30,600 | $1,530 |
| No | 207071652 | CENTURY | HRG1860S1P | ED1P50/60C+H4TXV02 | GDD80C110C5M | 30,400 | $1,520 |
| No | 207071223 | CENTURY | HRG1836S1P | EC4X36C | GUH96C090C4M | 22,800 | $1,140 |
| No | 207071221 | CENTURY | HRG1836S1P | EC4X36C | GUH95C090C4M | 23,000 | $1,150 |
| No | 207071225 | CENTURY | HRG1836S1P | EC4X36C | GUH96T090C3M | 22,800 | $1,140 |
| No | 207071215 | CENTURY | HRG1836S1P | EC4X36C | GUH92C090C3M | 23,000 | $1,150 |
| No | 207071213 | CENTURY | HRG1836S1P | EC4X36B | GUH96T070B3M | 23,000 | $1,150 |
| No | 207071219 | CENTURY | HRG1836S1P | EC4X36C | GUH92C110C4M | 22,800 | $1,140 |
| No | 207071211 | CENTURY | HRG1836S1P | EC4X36B | GUH96T045B3M | 23,000 | $1,150 |
| No | 207071217 | CENTURY | HRG1836S1P | EC4X36C | GUH92C090C4M | 22,600 | $1,130 |
| No | 207071209 | CENTURY | HRG1836S1P | EC4X36B | GUH96C070B3M | 23,200 | $1,160 |
| No | 207071205 | CENTURY | HRG1836S1P | EC4X36B | GUH92C070B3M | 23,200 | $1,160 |
| No | 207071207 | CENTURY | HRG1836S1P | EC4X36B | GUH96C045B3M | 23,200 | $1,160 |
| No | 207071201 | CENTURY | HRG1836S1P | EC4X36B | GUH80C090B4M | 22,800 | $1,140 |
| No | 207071199 | CENTURY | HRG1836S1P | EC4X36B | GUH80C070B3M | 23,000 | $1,150 |
| No | 207071197 | CENTURY | HRG1836S1P | EC4X36A | GUH80C070A3M | 23,000 | $1,150 |
| No | 207071195 | CENTURY | HRG1836S1P | EC4X36A | GUH80C045A3M | 23,000 | $1,150 |
| No | 207071203 | CENTURY | HRG1836S1P | EC4X36B | GUH92C045B3M | 23,200 | $1,160 |
| No | 207071161 | CENTURY | HRG1836S1P | EAC4X48C | GUH96T090C3M | 22,000 | $1,100 |
| No | 207071157 | CENTURY | HRG1836S1P | EAC4X48C | GUH95C090C4M | 22,000 | $1,100 |
| No | 207071159 | CENTURY | HRG1836S1P | EAC4X48C | GUH96C090C4M | 22,000 | $1,100 |
| No | 207071153 | CENTURY | HRG1836S1P | EAC4X48C | GUH92C090C4M | 22,000 | $1,100 |
| No | 207071155 | CENTURY | HRG1836S1P | EAC4X48C | GUH92C110C4M | 22,000 | $1,100 |
| No | 207071151 | CENTURY | HRG1836S1P | EAC4X48C | GUH92C090C3M | 22,000 | $1,100 |
| No | 207071147 | CENTURY | HRG1836S1P | EAC4X48B | GUH96T045B3M | 22,400 | $1,120 |
| No | 207071149 | CENTURY | HRG1836S1P | EAC4X48B | GUH96T070B3M | 22,200 | $1,110 |
| No | 207071145 | CENTURY | HRG1836S1P | EAC4X48B | GUH96C070B3M | 22,600 | $1,130 |
| No | 207071143 | CENTURY | HRG1836S1P | EAC4X48B | GUH96C045B3M | 22,600 | $1,130 |
| No | 207071141 | CENTURY | HRG1836S1P | EAC4X48B | GUH92C070B3M | 22,400 | $1,120 |
| No | 207071139 | CENTURY | HRG1836S1P | EAC4X48B | GUH92C045B3M | 22,400 | $1,120 |
| No | 207071137 | CENTURY | HRG1836S1P | EAC4X48B | GUH80C090B4M | 22,200 | $1,110 |
| No | 207071135 | CENTURY | HRG1836S1P | EAC4X48B | GUH80C070B3M | 22,200 | $1,110 |
| No | 207071133 | CENTURY | HRG1836S1P | EAC4X36B | GUH96T070B3M | 22,400 | $1,120 |
| No | 207071131 | CENTURY | HRG1836S1P | EAC4X36B | GUH96T045B3M | 22,400 | $1,120 |
| No | 207071129 | CENTURY | HRG1836S1P | EAC4X36B | GUH96C070B3M | 22,600 | $1,130 |
| No | 207071121 | CENTURY | HRG1836S1P | EAC4X36B | GUH96C045B3M | 22,600 | $1,130 |
| No | 207071127 | CENTURY | HRG1836S1P | EAC4X36B | GUH92C070B3M | 22,400 | $1,120 |
| No | 207071125 | CENTURY | HRG1836S1P | EAC4X36B | GUH92C045B3M | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207071123 | CENTURY | HRG1836S1P | EAC4X36B | GUH80C090B4M | 22,000 | $1,100 |
| No | 207071119 | CENTURY | HRG1836S1P | EAC4X36B | GUH80C070B3M | 22,200 | $1,110 |
| No | 207071117 | CENTURY | HRG1836S1P | EAC4X36A | GUH80C070A3M | 22,400 | $1,120 |
| No | 207071249 | CENTURY | HRG1836S1P | ED1P30/36C+H4TXV02 | GDD96C090C4M | 22,000 | $1,100 |
| No | 207071115 | CENTURY | HRG1836S1P | EAC4X36A | GUH80C045A3M | 22,200 | $1,110 |
| No | 207071245 | CENTURY | HRG1836S1P | ED1P30/36C+H4TXV02 | GDD92C090C4M | 22,000 | $1,100 |
| No | 207071243 | CENTURY | HRG1836S1P | ED1P30/36B+H4TXV02 | GDD96C070B3M | 22,000 | $1,100 |
| No | 207071241 | CENTURY | HRG1836S1P | ED1P30/36B+H4TXV02 | GDD96C045B3M | 22,400 | $1,120 |
| No | 207071237 | CENTURY | HRG1836S1P | ED1P30/36B+H4TXV02 | GDD95C045B3M | 22,400 | $1,120 |
| No | 207071239 | CENTURY | HRG1836S1P | ED1P30/36B+H4TXV02 | GDD95C070B4M | 22,000 | $1,100 |
| No | 207071247 | CENTURY | HRG1836S1P | ED1P30/36C+H4TXV02 | GDD95C090C4M | 22,000 | $1,100 |
| No | 207071235 | CENTURY | HRG1836S1P | ED1P30/36B+H4TXV02 | GDD92C070B3M | 22,400 | $1,120 |
| No | 207071233 | CENTURY | HRG1836S1P | ED1P30/36B+H4TXV02 | GDD92C045B3M | 22,400 | $1,120 |
| No | 207071227 | CENTURY | HRG1836S1P | ED1P30/36A+H4TXV02 | GDD80C045A3M | 22,200 | $1,110 |
| No | 207071229 | CENTURY | HRG1836S1P | ED1P30/36B+H4TXV02 | GDD80C070B3M | 22,200 | $1,110 |
| No | 207071231 | CENTURY | HRG1836S1P | ED1P30/36B+H4TXV02 | GDD80C090B4M | 22,000 | $1,100 |
| No | 207071063 | CENTURY | HRG1836S1P | E*1P36C+H4TXV02 | GUH96C090C4M | 22,800 | $1,140 |
| No | 207071061 | CENTURY | HRG1836S1P | E*1P36C+H4TXV02 | GUH95C090C4M | 23,000 | $1,150 |
| No | 207071053 | CENTURY | HRG1836S1P | E*1P36B+H4TXV02 | GUH96T070B3M | 23,000 | $1,150 |
| No | 207071057 | CENTURY | HRG1836S1P | E*1P36C+H4TXV02 | GUH92C090C4M | 22,600 | $1,130 |
| No | 207071065 | CENTURY | HRG1836S1P | E*1P36C+H4TXV02 | GUH96T090C3M | 22,800 | $1,140 |
| No | 207071055 | CENTURY | HRG1836S1P | E*1P36C+H4TXV02 | GUH92C090C3M | 23,000 | $1,150 |
| No | 207071051 | CENTURY | HRG1836S1P | E*1P36B+H4TXV02 | GUH96T045B3M | 23,000 | $1,150 |
| No | 207071059 | CENTURY | HRG1836S1P | E*1P36C+H4TXV02 | GUH92C110C4M | 22,800 | $1,140 |
| No | 207071349 | CENTURY | HRG1836S1P | EAC4X30B | GUH92C045B3M | 15,400 | $770 |
| No | 207071351 | CENTURY | HRG1836S1P | EAC4X30B | GUH92C070B3M | 15,400 | $770 |
| No | 207071357 | CENTURY | HRG1836S1P | EAC4X30B | GUH96C045B3M | 15,400 | $770 |
| No | 207071355 | CENTURY | HRG1836S1P | EAC4X30B | GUH95C070B3M | 15,400 | $770 |
| No | 207071353 | CENTURY | HRG1836S1P | EAC4X30B | GUH95C045B3M | 15,400 | $770 |
| No | 207071341 | CENTURY | HRG1836S1P | EAC4X30A | GUH80C045A3M | 15,500 | $775 |
| No | 207071347 | CENTURY | HRG1836S1P | EAC4X30B | GUH80C070B3M | 15,400 | $770 |
| No | 207071325 | CENTURY | HRG1836S1P | EAC4X24B | GUH96T070B3M | 15,200 | $760 |
| No | 207071323 | CENTURY | HRG1836S1P | EAC4X24B | GUH96T045B3M | 15,200 | $760 |
| No | 207071331 | CENTURY | HRG1836S1P | EAC4X24B | GUH92C070B3M | 15,200 | $760 |
| No | 207071329 | CENTURY | HRG1836S1P | EAC4X24B | GUH92C045B3M | 15,200 | $760 |
| No | 207071365 | CENTURY | HRG1836S1P | EAH1P30B+H4TXV01 | GUH96T070B3M | 15,300 | $765 |
| No | 207071363 | CENTURY | HRG1836S1P | EAH1P30B+H4TXV01 | GUH96T045B3M | 15,300 | $765 |
| No | 207071377 | CENTURY | HRG1836S1P | EAH1P30B+H4TXV01 | GUH96C045B3M | 15,300 | $765 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207071375 | CENTURY | HRG1836S1P | EAH1P30B+H4TXV01 | GUH95C070B3M | 15,400 | $770 |
| No | 207071369 | CENTURY | HRG1836S1P | EAH1P30B+H4TXV01 | GUH92C045B3M | 15,300 | $765 |
| No | 207071373 | CENTURY | HRG1836S1P | EAH1P30B+H4TXV01 | GUH95C045B3M | 15,300 | $765 |
| No | 207071367 | CENTURY | HRG1836S1P | EAH1P30B+H4TXV01 | GUH80C070B3M | 15,300 | $765 |
| No | 207071361 | CENTURY | HRG1836S1P | EAH1P30A+H4TXV01 | GUH80C045A3M | 15,200 | $760 |
| No | 207071371 | CENTURY | HRG1836S1P | EAH1P30B+H4TXV01 | GUH92C070B3M | 15,300 | $765 |
| No | 207071403 | CENTURY | HRG1836S1P | ED1P24B+H4TXV01 | GDD80C070B3M | 15,000 | $750 |
| No | 207071409 | CENTURY | HRG1836S1P | ED1P24B+H4TXV01 | GDD96C070B3M | 15,000 | $750 |
| No | 207071379 | CENTURY | HRG1836S1P | EAH1P30B+H4TXV01 | GUH96C070B3M | 15,300 | $765 |
| No | 207071405 | CENTURY | HRG1836S1P | ED1P24B+H4TXV01 | GDD95C045B3M | 15,000 | $750 |
| No | 207071401 | CENTURY | HRG1836S1P | ED1P24A+H4TXV01 | GDD80C045A3M | 15,200 | $760 |
| No | 207071265 | CENTURY | HRG1836S1P | E*1P23B+H4TXV01 | GUH96T070B3M | 14,800 | $740 |
| No | 207071279 | CENTURY | HRG1836S1P | E*1P23B+H4TXV01 | GUH96C070B3M | 14,800 | $740 |
| No | 207071277 | CENTURY | HRG1836S1P | E*1P23B+H4TXV01 | GUH96C045B3M | 14,900 | $745 |
| No | 207071273 | CENTURY | HRG1836S1P | E*1P23B+H4TXV01 | GUH95C045B3M | 14,800 | $740 |
| No | 207071271 | CENTURY | HRG1836S1P | E*1P23B+H4TXV01 | GUH92C070B3M | 14,900 | $745 |
| No | 207071267 | CENTURY | HRG1836S1P | E*1P23B+H4TXV01 | GUH80C070B3M | 14,800 | $740 |
| No | 207071263 | CENTURY | HRG1836S1P | E*1P23B+H4TXV01 | GUH96T045B3M | 14,900 | $745 |
| No | 207071261 | CENTURY | HRG1836S1P | E*1P23A+H4TXV01 | GUH80C045A3M | 15,000 | $750 |
| No | 207071305 | CENTURY | HRG1836S1P | EA(C,U)1P30B+H4TXV01 | GUH96T070B3M | 15,400 | $770 |
| No | 207071275 | CENTURY | HRG1836S1P | E*1P23B+H4TXV01 | GUH95C070B3M | 14,900 | $745 |
| No | 207071303 | CENTURY | HRG1836S1P | EA(C,U)1P30B+H4TXV01 | GUH96T045B3M | 15,400 | $770 |
| No | 207071319 | CENTURY | HRG1836S1P | EA(C,U)1P30B+H4TXV01 | GUH96C070B3M | 15,400 | $770 |
| No | 207071315 | CENTURY | HRG1836S1P | EA(C,U)1P30B+H4TXV01 | GUH95C070B3M | 15,400 | $770 |
| No | 207071317 | CENTURY | HRG1836S1P | EA(C,U)1P30B+H4TXV01 | GUH96C045B3M | 15,400 | $770 |
| No | 207071311 | CENTURY | HRG1836S1P | EA(C,U)1P30B+H4TXV01 | GUH92C070B3M | 15,400 | $770 |
| No | 207071313 | CENTURY | HRG1836S1P | EA(C,U)1P30B+H4TXV01 | GUH95C045B3M | 15,400 | $770 |
| No | 207071309 | CENTURY | HRG1836S1P | EA(C,U)1P30B+H4TXV01 | GUH92C045B3M | 15,400 | $770 |
| No | 207071307 | CENTURY | HRG1836S1P | EA(C,U)1P30B+H4TXV01 | GUH80C070B3M | 15,400 | $770 |
| No | 207071301 | CENTURY | HRG1836S1P | EA(C,U)1P30A+H4TXV01 | GUH80C045A3M | 15,500 | $775 |
| No | 207071285 | CENTURY | HRG1836S1P | EA(C,U)1P24B+H4TXV01 | GUH96T070B3M | 15,200 | $760 |
| No | 207071283 | CENTURY | HRG1836S1P | EA(C,U)1P24B+H4TXV01 | GUH96T045B3M | 15,200 | $760 |
| No | 207071291 | CENTURY | HRG1836S1P | EA(C,U)1P24B+H4TXV01 | GUH92C070B3M | 15,200 | $760 |
| No | 207071289 | CENTURY | HRG1836S1P | EA(C,U)1P24B+H4TXV01 | GUH92C045B3M | 15,200 | $760 |
| No | 207071253 | CENTURY | HRG1836S1P | HMG24X1P | | 15,600 | $780 |
| No | 207071255 | CENTURY | HRG1836S1P | HMG30X1P | | 15,600 | $780 |
| No | 207071047 | CENTURY | HRG1836S1P | E*1P36B+H4TXV02 | GUH96C045B3M | 23,200 | $1,160 |
| No | 207071049 | CENTURY | HRG1836S1P | E*1P36B+H4TXV02 | GUH96C070B3M | 23,200 | $1,160 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207071043 | CENTURY | HRG1836S1P | E*1P36B+H4TXV02 | GUH92C045B3M | 23,200 | $1,160 |
| No | 207071045 | CENTURY | HRG1836S1P | E*1P36B+H4TXV02 | GUH92C070B3M | 23,200 | $1,160 |
| No | 207071039 | CENTURY | HRG1836S1P | E*1P36B+H4TXV02 | GUH80C070B3M | 23,000 | $1,150 |
| No | 207071041 | CENTURY | HRG1836S1P | E*1P36B+H4TXV02 | GUH80C090B4M | 22,800 | $1,140 |
| No | 207071035 | CENTURY | HRG1836S1P | E*1P36A+H4TXV02 | GUH80C045A3M | 23,000 | $1,150 |
| No | 207071037 | CENTURY | HRG1836S1P | E*1P36A+H4TXV02 | GUH80C070A3M | 23,000 | $1,150 |
| No | 207071193 | CENTURY | HRG1836S1P | EAH1P48B+H4TXV02 | GUH96T070B3M | 21,800 | $1,090 |
| No | 207071191 | CENTURY | HRG1836S1P | EAH1P48B+H4TXV02 | GUH96T045B3M | 22,000 | $1,100 |
| No | 207071187 | CENTURY | HRG1836S1P | EAH1P48B+H4TXV02 | GUH96C045B3M | 22,000 | $1,100 |
| No | 207071189 | CENTURY | HRG1836S1P | EAH1P48B+H4TXV02 | GUH96C070B3M | 22,000 | $1,100 |
| No | 207071185 | CENTURY | HRG1836S1P | EAH1P48B+H4TXV02 | GUH92C070B3M | 22,000 | $1,100 |
| No | 207071183 | CENTURY | HRG1836S1P | EAH1P48B+H4TXV02 | GUH92C045B3M | 22,000 | $1,100 |
| No | 207071181 | CENTURY | HRG1836S1P | EAH1P48B+H4TXV02 | GUH80C090B4M | 21,800 | $1,090 |
| No | 207071179 | CENTURY | HRG1836S1P | EAH1P48B+H4TXV02 | GUH80C070B3M | 21,800 | $1,090 |
| No | 207071111 | CENTURY | HRG1836S1P | EA(C,U)1P48C+H4TXV02 | GUH96C090C4M | 22,200 | $1,110 |
| No | 207071113 | CENTURY | HRG1836S1P | EA(C,U)1P48C+H4TXV02 | GUH96T090C3M | 22,200 | $1,110 |
| No | 207071109 | CENTURY | HRG1836S1P | EA(C,U)1P48C+H4TXV02 | GUH95C090C4M | 22,200 | $1,110 |
| No | 207071105 | CENTURY | HRG1836S1P | EA(C,U)1P48C+H4TXV02 | GUH92C090C4M | 22,200 | $1,110 |
| No | 207071107 | CENTURY | HRG1836S1P | EA(C,U)1P48C+H4TXV02 | GUH92C110C4M | 22,200 | $1,110 |
| No | 207071097 | CENTURY | HRG1836S1P | EA(C,U)1P48B+H4TXV02 | GUH96C070B3M | 22,800 | $1,140 |
| No | 207071099 | CENTURY | HRG1836S1P | EA(C,U)1P48B+H4TXV02 | GUH96T045B3M | 22,600 | $1,130 |
| No | 207071101 | CENTURY | HRG1836S1P | EA(C,U)1P48B+H4TXV02 | GUH96T070B3M | 22,400 | $1,120 |
| No | 207071103 | CENTURY | HRG1836S1P | EA(C,U)1P48C+H4TXV02 | GUH92C090C3M | 22,200 | $1,110 |
| No | 207071091 | CENTURY | HRG1836S1P | EA(C,U)1P48B+H4TXV02 | GUH92C045B3M | 22,600 | $1,130 |
| No | 207071095 | CENTURY | HRG1836S1P | EA(C,U)1P48B+H4TXV02 | GUH96C045B3M | 22,800 | $1,140 |
| No | 207071087 | CENTURY | HRG1836S1P | EA(C,U)1P48B+H4TXV02 | GUH80C070B3M | 22,400 | $1,120 |
| No | 207071089 | CENTURY | HRG1836S1P | EA(C,U)1P48B+H4TXV02 | GUH80C090B4M | 22,400 | $1,120 |
| No | 207071085 | CENTURY | HRG1836S1P | EA(C,U)1P36B+H4TXV02 | GUH96T070B3M | 22,400 | $1,120 |
| No | 207071083 | CENTURY | HRG1836S1P | EA(C,U)1P36B+H4TXV02 | GUH96T045B3M | 22,400 | $1,120 |
| No | 207071081 | CENTURY | HRG1836S1P | EA(C,U)1P36B+H4TXV02 | GUH96C070B3M | 22,600 | $1,130 |
| No | 207071073 | CENTURY | HRG1836S1P | EA(C,U)1P36B+H4TXV02 | GUH96C045B3M | 22,600 | $1,130 |
| No | 207071093 | CENTURY | HRG1836S1P | EA(C,U)1P48B+H4TXV02 | GUH92C070B3M | 22,600 | $1,130 |
| No | 207071079 | CENTURY | HRG1836S1P | EA(C,U)1P36B+H4TXV02 | GUH92C070B3M | 22,400 | $1,120 |
| No | 207071077 | CENTURY | HRG1836S1P | EA(C,U)1P36B+H4TXV02 | GUH92C045B3M | 22,400 | $1,120 |
| No | 207071075 | CENTURY | HRG1836S1P | EA(C,U)1P36B+H4TXV02 | GUH80C090B4M | 22,000 | $1,100 |
| No | 207071071 | CENTURY | HRG1836S1P | EA(C,U)1P36B+H4TXV02 | GUH80C070B3M | 22,200 | $1,110 |
| No | 207071069 | CENTURY | HRG1836S1P | EA(C,U)1P36A+H4TXV02 | GUH80C070A3M | 22,400 | $1,120 |
| No | 207071067 | CENTURY | HRG1836S1P | EA(C,U)1P36A+H4TXV02 | GUH80C045A3M | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207071033 | CENTURY | HRG1836S1P | HCG42V1P | | 21,600 | $1,080 |
| No | 207071029 | CENTURY | HRG1836S1P | HMG36X1P | | 21,800 | $1,090 |
| No | 207071025 | CENTURY | HRG1836S1P | HCG36V1P | | 21,400 | $1,070 |
| No | 207071257 | CENTURY | HRG1836S1P | HCG24V1P | | 15,900 | $795 |
| No | 207071251 | CENTURY | HRG1836S1P | HMG24F1P+H4TXV01 | | 16,200 | $810 |
| No | 207071031 | CENTURY | HRG1836S1P | HMG42X1P | | 21,800 | $1,090 |
| No | 207071259 | CENTURY | HRG1836S1P | HCG30V1P | | 15,600 | $780 |
| No | 207071385 | CENTURY | HRG1836S1P | EC4X23B | GUH96T070B3M | 14,800 | $740 |
| No | 207071383 | CENTURY | HRG1836S1P | EC4X23B | GUH96T045B3M | 14,900 | $745 |
| No | 207071399 | CENTURY | HRG1836S1P | EC4X23B | GUH96C070B3M | 14,800 | $740 |
| No | 207071393 | CENTURY | HRG1836S1P | EC4X23B | GUH95C045B3M | 14,800 | $740 |
| No | 207071395 | CENTURY | HRG1836S1P | EC4X23B | GUH95C070B3M | 14,900 | $745 |
| No | 207071391 | CENTURY | HRG1836S1P | EC4X23B | GUH92C070B3M | 14,900 | $745 |
| No | 207071389 | CENTURY | HRG1836S1P | EC4X23B | GUH92C045B3M | 14,800 | $740 |
| No | 207071387 | CENTURY | HRG1836S1P | EC4X23B | GUH80C070B3M | 14,800 | $740 |
| No | 207071345 | CENTURY | HRG1836S1P | EAC4X30B | GUH96T070B3M | 15,400 | $770 |
| No | 207071359 | CENTURY | HRG1836S1P | EAC4X30B | GUH96C070B3M | 15,400 | $770 |
| No | 207071397 | CENTURY | HRG1836S1P | EC4X23B | GUH96C045B3M | 14,900 | $745 |
| No | 207071343 | CENTURY | HRG1836S1P | EAC4X30B | GUH96T045B3M | 15,400 | $770 |
| No | 207071381 | CENTURY | HRG1836S1P | EC4X23A | GUH80C045A3M | 15,000 | $750 |
| No | 200059040 | CENTURY | B-VMH12SU-1 | A-VMH12SU-1 | | 7,800 | $390 |
| No | 200059042 | CENTURY | A-VMH09SU-1 | B-VMH09SU-1 | | 6,900 | $345 |
| No | 201862958 | CENTURY | A-VMH28TU-1 | Heat pump without ducts | | 18,000 | $900 |
| No | 202195115 | CENTURY | A-VMH48PU-1 | Heat pump without ducts | | 29,600 | $1,480 |
| No | 211238539 | CHAMPION HEATING AND COOLING | HMH72B341 | JHETC36DBCS2N1 | | 24,600 | $1,230 |
| No | 211662226 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+JMET12BS2N1+TXV | | 24,800 | $1,240 |
| No | 211662221 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+JMET12BS2N1+TXV | | 24,800 | $1,240 |
| No | 211662216 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB30CXXN1+JMET12BS2N1+TXV | | 23,800 | $1,190 |
| No | 211662211 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+JMVT12BC2N1+TXV | | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211662206 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+JMVT12BC2N1+TXV | | 24,600 | $1,230 |
| No | 211662201 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB30CXXN1+JMVT12BC2N1+TXV | | 24,200 | $1,210 |
| No | 211662196 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+TXV | TMLE040A12MP11 | 24,400 | $1,220 |
| No | 211662191 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+TXV | TM8E040A12MP11 | 24,400 | $1,220 |
| No | 211662186 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+TXV | TMLE040A12MP11 | 24,400 | $1,220 |
| No | 211662181 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+TXV | TM8E040A12MP11 | 24,400 | $1,220 |
| No | 211662176 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB30CXXN1+TXV | TMLE040A12MP11 | 23,800 | $1,190 |
| No | 211662171 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB30CXXN1+TXV | TM8E040A12MP11 | 23,800 | $1,190 |
| No | 211662166 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+TXV | TL8E060A12UH11 | 24,400 | $1,220 |
| No | 211662161 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+TXV | TL8E060A12UH11 | 24,400 | $1,220 |
| No | 211662156 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB30CXXN1+TXV | TL8E060A12UH11 | 24,000 | $1,200 |
| No | 211662151 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TL8E080C16UH11 | 25,200 | $1,260 |
| No | 211662146 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TL8E080C16UH11 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211662141 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TL8E100C20UH11 | 24,400 | $1,220 |
| No | 211662136 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TL8E100C20UH11 | 24,000 | $1,200 |
| No | 211662131 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 211662126 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 211662121 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 211662116 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB30CXXN1+TXV | TL9E060B12UH11 | 23,600 | $1,180 |
| No | 211662111 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 211662106 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TL9E080C16UH11 | 24,800 | $1,240 |
| No | 211662101 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TL9E080C16UH11 | 24,400 | $1,220 |
| No | 211662096 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TL9E100C20UH11 | 24,600 | $1,230 |
| No | 211662091 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TL9E100C20UH11 | 24,000 | $1,200 |
| No | 211662086 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+TXV | TMLE060A12MP11 | 24,400 | $1,220 |
| No | 211662081 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+TXV | TM8E060A12MP11 | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211662076 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+TXV | TMLE060A12MP11 | 24,400 | $1,220 |
| No | 211662071 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+TXV | TM8E060A12MP11 | 24,400 | $1,220 |
| No | 211662066 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB30CXXN1+TXV | TMLE060A12MP11 | 24,000 | $1,200 |
| No | 211662061 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB30CXXN1+TXV | TM8E060A12MP11 | 24,000 | $1,200 |
| No | 211662056 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 211662051 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 211662046 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 211662041 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 211662036 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 211662031 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 211662026 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB30CXXN1+TXV | TMLE080B12MP11 | 24,400 | $1,220 |
| No | 211662021 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB30CXXN1+TXV | TM8E080B12MP11 | 24,400 | $1,220 |
| No | 211662016 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TMLE080B12MP11 | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211662011 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TM8E080B12MP11 | 24,400 | $1,220 |
| No | 211662006 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TMLE080C16MP11 | 24,200 | $1,210 |
| No | 211662001 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TM8E080C16MP11 | 24,200 | $1,210 |
| No | 211661996 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TMLE080C16MP11 | 23,800 | $1,190 |
| No | 211661991 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TM8E080C16MP11 | 23,800 | $1,190 |
| No | 211661986 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+TXV | TMLE100B12MP11 | 24,400 | $1,220 |
| No | 211661981 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+TXV | TM8E100B12MP11 | 24,400 | $1,220 |
| No | 211661976 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+TXV | TMLE100B12MP11 | 24,400 | $1,220 |
| No | 211661971 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+TXV | TM8E100B12MP11 | 24,400 | $1,220 |
| No | 211661966 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TMLE100B12MP11 | 24,400 | $1,220 |
| No | 211661961 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TM8E100B12MP11 | 24,400 | $1,220 |
| No | 211661956 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB30CXXN1+TXV | TMLE100B12MP11 | 24,000 | $1,200 |
| No | 211661951 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB30CXXN1+TXV | TM8E100B12MP11 | 24,000 | $1,200 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661946 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TMLE100B12MP11 | 24,000 | $1,200 |
| No | 211661941 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TM8E100B12MP11 | 24,000 | $1,200 |
| No | 211661936 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TMLE100C16MP11 | 24,200 | $1,210 |
| No | 211661931 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TM8E100C16MP11 | 24,200 | $1,210 |
| No | 211661926 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TMLE100C16MP11 | 23,800 | $1,190 |
| No | 211661921 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TM8E100C16MP11 | 23,800 | $1,190 |
| No | 211661916 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TMLE120C16MP11 | 24,200 | $1,210 |
| No | 211661911 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TM8E120C16MP11 | 24,200 | $1,210 |
| No | 211661906 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TMLE120C16MP11 | 23,800 | $1,190 |
| No | 211661901 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TM8E120C16MP11 | 23,800 | $1,190 |
| No | 211661896 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFA30DXXN1+TXV | TPLC060A12MP13 | 25,800 | $1,290 |
| No | 211661891 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFA30DXXN1+TXV | TMLV060A12MP12 | 25,800 | $1,290 |
| No | 211661886 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFA30DXXN1+TXV | TM8V060A12MP12 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661881 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+TXV | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 211661876 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+TXV | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 211661871 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+TXV | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 211661866 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+TXV | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 211661861 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+TXV | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 211661856 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+TXV | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 211661851 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB30CXXN1+TXV | TPLC060A12MP13 | 24,200 | $1,210 |
| No | 211661846 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB30CXXN1+TXV | TMLV060A12MP12 | 24,200 | $1,210 |
| No | 211661841 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB30CXXN1+TXV | TM8V060A12MP12 | 24,200 | $1,210 |
| No | 211661835 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 211661830 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 211661824 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 211661819 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661813 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TPLC080B12MP13 | 24,800 | $1,240 |
| No | 211661808 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TM8V080B12MP12 | 24,800 | $1,240 |
| No | 211661802 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB30CXXN1+TXV | TPLC080B12MP13 | 24,000 | $1,200 |
| No | 211661797 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB30CXXN1+TXV | TM8V080B12MP12 | 24,000 | $1,200 |
| No | 211661791 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TPLC080B12MP13 | 24,200 | $1,210 |
| No | 211661786 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TM8V080B12MP12 | 24,200 | $1,210 |
| No | 211661777 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TPLC100C16MP13 | 25,000 | $1,250 |
| No | 211661772 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TPLC080C16MP13 | 25,000 | $1,250 |
| No | 211661767 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TMLV100C16MP12 | 25,000 | $1,250 |
| No | 211661762 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TM8V080C16MP12 | 25,000 | $1,250 |
| No | 211661757 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TM8V100C16MP12 | 25,000 | $1,250 |
| No | 211661748 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 211661743 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TPLC080C16MP13 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661738 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TMLV100C16MP12 | 24,600 | $1,230 |
| No | 211661728 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 211661723 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+TXV | TM8Y060A12MP11 | 24,200 | $1,210 |
| No | 211661718 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+TXV | TM8Y060A12MP11 | 24,200 | $1,210 |
| No | 211661713 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB30CXXN1+TXV | TM8Y060A12MP11 | 23,800 | $1,190 |
| No | 211661708 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+TXV | TM8Y080B12MP11 | 24,200 | $1,210 |
| No | 211661703 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+TXV | TM8Y080B12MP11 | 24,200 | $1,210 |
| No | 211661698 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TM8Y080B12MP11 | 24,200 | $1,210 |
| No | 211661693 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB30CXXN1+TXV | TM8Y080B12MP11 | 23,800 | $1,190 |
| No | 211661688 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TM8Y080B12MP11 | 23,800 | $1,190 |
| No | 211661683 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TM8Y080C16MP11 | 25,200 | $1,260 |
| No | 211661678 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TM8Y100C16MP11 | 25,200 | $1,260 |
| No | 211661673 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TM8Y080C16MP11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661668 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TM8Y100C16MP11 | 24,600 | $1,230 |
| No | 211661663 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TM8Y100C20MP11 | 24,800 | $1,240 |
| No | 211661658 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TM8Y120C20MP11 | 24,800 | $1,240 |
| No | 211661653 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TM8Y100C20MP11 | 24,400 | $1,220 |
| No | 211661648 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TM8Y120C20MP11 | 24,400 | $1,220 |
| No | 211661643 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+TXV | TM9E040A10MP12 | 24,200 | $1,210 |
| No | 211661638 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+TXV | TM9E040A10MP12 | 24,200 | $1,210 |
| No | 211661633 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+TXV | TM9E060A10MP12 | 24,400 | $1,220 |
| No | 211661628 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+TXV | TM9E060A10MP12 | 24,400 | $1,220 |
| No | 211661623 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB30CXXN1+TXV | TM9E060A10MP12 | 24,000 | $1,200 |
| No | 211661618 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 211661613 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 211661608 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661603 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB30CXXN1+TXV | TM9E060B12MP12 | 24,200 | $1,210 |
| No | 211661598 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 211661593 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 211661588 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 211661583 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 211661578 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB30CXXN1+TXV | TM9E080B12MP12 | 24,400 | $1,220 |
| No | 211661573 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TM9E080B12MP12 | 24,400 | $1,220 |
| No | 211661568 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TM9E080C16MP12 | 25,200 | $1,260 |
| No | 211661563 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TM9E080C16MP12 | 24,800 | $1,240 |
| No | 211661558 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TM9E100C16MP12 | 24,400 | $1,220 |
| No | 211661553 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TM9E100C16MP12 | 23,800 | $1,190 |
| No | 211661548 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+TXV | TM9V040A10MP12 | 24,400 | $1,220 |
| No | 211661543 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+TXV | TM9V040A10MP12 | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661531 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+TXV | TP9C060B12MP13 | 24,600 | $1,230 |
| No | 211661526 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+TXV | TM9V060B12MP12 | 24,600 | $1,230 |
| No | 211661519 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+TXV | TP9C060B12MP13 | 24,600 | $1,230 |
| No | 211661514 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+TXV | TM9V060B12MP12 | 24,600 | $1,230 |
| No | 211661506 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TP9C060B12MP13 | 24,600 | $1,230 |
| No | 211661498 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TM9V060B12MP12 | 24,600 | $1,230 |
| No | 211661491 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB30CXXN1+TXV | TP9C060B12MP13 | 24,000 | $1,200 |
| No | 211661486 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB30CXXN1+TXV | TM9V060B12MP12 | 24,000 | $1,200 |
| No | 211661479 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TP9C060B12MP13 | 24,200 | $1,210 |
| No | 211661474 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TM9V060B12MP12 | 24,200 | $1,210 |
| No | 211661467 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+TXV | TP9C080B12MP13 | 24,800 | $1,240 |
| No | 211661462 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+TXV | TM9V080B12MP12 | 24,800 | $1,240 |
| No | 211661455 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+TXV | TP9C080B12MP13 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661450 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+TXV | TM9V080B12MP12 | 24,800 | $1,240 |
| No | 211661443 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 211661438 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 211661431 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB30CXXN1+TXV | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 211661426 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB30CXXN1+TXV | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 211661419 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 211661414 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 211661407 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TP9C080C16MP13 | 25,200 | $1,260 |
| No | 211661402 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TM9V080C16MP12 | 25,200 | $1,260 |
| No | 211661395 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TP9C080C16MP13 | 24,800 | $1,240 |
| No | 211661390 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TM9V080C16MP12 | 24,800 | $1,240 |
| No | 211661383 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211661378 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TM9V100C16MP12 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661371 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TP9C100C16MP13 | 24,600 | $1,230 |
| No | 211661366 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TM9V100C16MP12 | 24,600 | $1,230 |
| No | 211661359 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TP9C100C20MP13 | 25,000 | $1,250 |
| No | 211661354 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TM9V100C20MP12 | 25,000 | $1,250 |
| No | 211661347 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TP9C100C20MP13 | 24,600 | $1,230 |
| No | 211661342 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TM9V100C20MP12 | 24,600 | $1,230 |
| No | 211661337 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+TXV | TM9Y060B12MP11 | 24,800 | $1,240 |
| No | 211661332 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+TXV | TM9Y060B12MP11 | 24,800 | $1,240 |
| No | 211661327 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TM9Y060B12MP11 | 24,800 | $1,240 |
| No | 211661322 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB30CXXN1+TXV | TM9Y060B12MP11 | 24,200 | $1,210 |
| No | 211661317 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TM9Y060B12MP11 | 24,200 | $1,210 |
| No | 211661312 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB30CXXN1+TXV | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211661307 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB30CXXN1+TXV | TM9Y080B12MP11 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661302 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211661297 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB30CXXN1+TXV | TM9Y080B12MP11 | 24,400 | $1,220 |
| No | 211661292 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TM9Y080B12MP11 | 24,400 | $1,220 |
| No | 211661287 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TM9Y080C16MP11 | 24,800 | $1,240 |
| No | 211661282 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TM9Y080C16MP11 | 24,400 | $1,220 |
| No | 211661277 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC30CXXN1+TXV | TM9Y100C16MP11 | 24,800 | $1,240 |
| No | 211661272 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC30CXXN1+TXV | TM9Y100C16MP11 | 24,400 | $1,220 |
| No | 211661267 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CBAN1 | TM9E040A10MP12 | 15,000 | $750 |
| No | 211661262 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CXXN1+TXV | TM9E040A10MP12 | 15,000 | $750 |
| No | 211661257 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB30CXXN1+TXV | TM9E060A10MP12 | 15,000 | $750 |
| No | 211661252 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CBAN1 | TM9E060A10MP12 | 15,000 | $750 |
| No | 211661247 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CXXN1+TXV | TM9E060A10MP12 | 15,000 | $750 |
| No | 211661242 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CBAN1 | TM9E060A10MP12 | 14,900 | $745 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661237 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CXXN1+TXV | TM9E060A10MP12 | 14,900 | $745 |
| No | 211661232 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB30CXXN1+TXV | TM9E060B12MP12 | 15,400 | $770 |
| No | 211661227 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CBAN1 | TM9E060B12MP12 | 15,400 | $770 |
| No | 211661222 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CXXN1+TXV | TM9E060B12MP12 | 15,400 | $770 |
| No | 211661217 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TM9E060B12MP12 | 15,400 | $770 |
| No | 211661212 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TM9E060B12MP12 | 15,400 | $770 |
| No | 211661207 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CBAN1 | TM9E060B12MP12 | 15,100 | $755 |
| No | 211661202 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CXXN1+TXV | TM9E060B12MP12 | 15,100 | $755 |
| No | 211661197 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TM9E060B12MP12 | 15,100 | $755 |
| No | 211661191 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TM9E060B12MP12 | 15,100 | $755 |
| No | 211661181 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB30CXXN1+TXV | TM9E080B12MP12 | 15,700 | $785 |
| No | 211661171 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CBAN1 | TM9E080B12MP12 | 15,700 | $785 |
| No | 211661162 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CXXN1+TXV | TM9E080B12MP12 | 15,700 | $785 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661157 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TM9E080B12MP12 | 15,700 | $785 |
| No | 211661152 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TM9E080B12MP12 | 15,700 | $785 |
| No | 211661147 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CBAN1 | TM9E080B12MP12 | 14,900 | $745 |
| No | 211661142 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CXXN1+TXV | TM9E080B12MP12 | 14,900 | $745 |
| No | 211661137 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TM9E080B12MP12 | 14,900 | $745 |
| No | 211661132 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TM9E080B12MP12 | 14,900 | $745 |
| No | 211661127 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TM9E080C16MP12 | 14,900 | $745 |
| No | 211661122 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TM9E080C16MP12 | 14,900 | $745 |
| No | 211661117 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TM9E080C16MP12 | 14,600 | $730 |
| No | 211661112 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TM9E080C16MP12 | 14,600 | $730 |
| No | 211661107 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TM9E100C16MP12 | 15,000 | $750 |
| No | 211661102 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TM9E100C16MP12 | 15,000 | $750 |
| No | 211661097 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TM9E100C16MP12 | 14,700 | $735 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661092 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TM9E100C16MP12 | 14,700 | $735 |
| No | 211661087 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB30CXXN1+TXV | TM9V040A10MP12 | 15,400 | $770 |
| No | 211661082 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CBAN1 | TM9V040A10MP12 | 15,400 | $770 |
| No | 211661077 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CXXN1+TXV | TM9V040A10MP12 | 15,400 | $770 |
| No | 211661072 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CBAN1 | TM9V040A10MP12 | 15,100 | $755 |
| No | 211661067 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CXXN1+TXV | TM9V040A10MP12 | 15,100 | $755 |
| No | 211661058 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB30CXXN1+TXV | TP9C060B12MP13 | 15,100 | $755 |
| No | 211661053 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CBAN1 | TP9C060B12MP13 | 15,100 | $755 |
| No | 211661048 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB30CXXN1+TXV | TM9V060B12MP12 | 15,100 | $755 |
| No | 211661043 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CBAN1 | TM9V060B12MP12 | 15,100 | $755 |
| No | 211661036 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CXXN1+TXV | TP9C060B12MP13 | 15,100 | $755 |
| No | 211661031 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CXXN1+TXV | TM9V060B12MP12 | 15,100 | $755 |
| No | 211661024 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TP9C060B12MP13 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661019 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TM9V060B12MP12 | 15,100 | $755 |
| No | 211661012 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TP9C060B12MP13 | 15,100 | $755 |
| No | 211661007 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TM9V060B12MP12 | 15,100 | $755 |
| No | 211661000 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CBAN1 | TP9C060B12MP13 | 15,100 | $755 |
| No | 211660995 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CBAN1 | TM9V060B12MP12 | 15,100 | $755 |
| No | 211660988 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CXXN1+TXV | TP9C060B12MP13 | 15,100 | $755 |
| No | 211660983 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CXXN1+TXV | TM9V060B12MP12 | 15,100 | $755 |
| No | 211660976 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TP9C060B12MP13 | 15,000 | $750 |
| No | 211660971 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TM9V060B12MP12 | 15,000 | $750 |
| No | 211660964 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TP9C060B12MP13 | 15,000 | $750 |
| No | 211660959 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TM9V060B12MP12 | 15,000 | $750 |
| No | 211660950 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB30CXXN1+TXV | TP9C080B12MP13 | 15,300 | $765 |
| No | 211660945 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CBAN1 | TP9C080B12MP13 | 15,300 | $765 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660940 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB30CXXN1+TXV | TM9V080B12MP12 | 15,300 | $765 |
| No | 211660935 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CBAN1 | TM9V080B12MP12 | 15,300 | $765 |
| No | 211660928 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CXXN1+TXV | TP9C080B12MP13 | 15,300 | $765 |
| No | 211660923 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CXXN1+TXV | TM9V080B12MP12 | 15,300 | $765 |
| No | 211660916 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TP9C080B12MP13 | 15,300 | $765 |
| No | 211660911 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TM9V080B12MP12 | 15,300 | $765 |
| No | 211660904 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TP9C080B12MP13 | 15,300 | $765 |
| No | 211660899 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TM9V080B12MP12 | 15,300 | $765 |
| No | 211660892 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CBAN1 | TP9C080B12MP13 | 14,800 | $740 |
| No | 211660887 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CBAN1 | TM9V080B12MP12 | 14,800 | $740 |
| No | 211660880 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CXXN1+TXV | TP9C080B12MP13 | 14,800 | $740 |
| No | 211660875 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CXXN1+TXV | TM9V080B12MP12 | 14,800 | $740 |
| No | 211660868 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TP9C080B12MP13 | 15,000 | $750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660863 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TM9V080B12MP12 | 15,000 | $750 |
| No | 211660856 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 211660851 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 211660821 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB30CXXN1+TXV | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211660816 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CBAN1 | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211660811 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CXXN1+TXV | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211660806 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211660801 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211660796 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CBAN1 | TM9Y060B12MP11 | 15,100 | $755 |
| No | 211660791 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CXXN1+TXV | TM9Y060B12MP11 | 15,100 | $755 |
| No | 211660786 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TM9Y060B12MP11 | 14,800 | $740 |
| No | 211660781 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TM9Y060B12MP11 | 14,800 | $740 |
| No | 211660776 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB30CXXN1+TXV | TM9Y080B12MP11 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660771 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CBAN1 | TM9Y080B12MP11 | 15,100 | $755 |
| No | 211660766 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CXXN1+TXV | TM9Y080B12MP11 | 15,100 | $755 |
| No | 211660761 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TM9Y080B12MP11 | 15,100 | $755 |
| No | 211660756 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TM9Y080B12MP11 | 15,100 | $755 |
| No | 211660751 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CBAN1 | TM9Y080B12MP11 | 14,900 | $745 |
| No | 211660746 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CXXN1+TXV | TM9Y080B12MP11 | 14,900 | $745 |
| No | 211660741 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TM9Y080B12MP11 | 14,900 | $745 |
| No | 211660736 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TM9Y080B12MP11 | 14,900 | $745 |
| No | 211660731 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TM9Y080C16MP11 | 15,200 | $760 |
| No | 211660726 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TM9Y080C16MP11 | 15,200 | $760 |
| No | 211660721 | CHAMPION HEATING AND COOLING | HMH72B241 | JHETB24CBAS2N1 | | 15,000 | $750 |
| No | 211660716 | CHAMPION HEATING AND COOLING | HMH72B241 | JHVTB24CBAC2N1 | | 15,000 | $750 |
| No | 211660711 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB30CXXN1+JMET12BS2N1+TXV | | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660706 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CBAN1+JMET12BS2N1 | | 15,100 | $755 |
| No | 211660701 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CXXN1+JMET12BS2N1+TXV | | 15,100 | $755 |
| No | 211660696 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CBAN1+JMET12BS2N1 | | 14,800 | $740 |
| No | 211660691 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CXXN1+JMET12BS2N1+TXV | | 14,800 | $740 |
| No | 211660686 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB30CXXN1+JMVT12BC2N1+TXV | | 14,900 | $745 |
| No | 211660681 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CBAN1+JMVT12BC2N1 | | 14,900 | $745 |
| No | 211660676 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CXXN1+JMVT12BC2N1+TXV | | 14,900 | $745 |
| No | 211660671 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CBAN1+JMVT12BC2N1 | | 14,900 | $745 |
| No | 211660666 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CXXN1+JMVT12BC2N1+TXV | | 14,900 | $745 |
| No | 211660661 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB30CXXN1+TXV | TL8E060A12UH11 | 15,000 | $750 |
| No | 211660656 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CBAN1 | TL8E060A12UH11 | 15,000 | $750 |
| No | 211660651 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CXXN1+TXV | TL8E060A12UH11 | 15,000 | $750 |
| No | 211660646 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CBAN1 | TL8E060A12UH11 | 14,700 | $735 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660641 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CXXN1+TXV | TL8E060A12UH11 | 14,700 | $735 |
| No | 211660636 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TL8E080C16UH11 | 15,600 | $780 |
| No | 211660631 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TL8E080C16UH11 | 15,600 | $780 |
| No | 211660626 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TM9Y080C16MP11 | 14,900 | $745 |
| No | 211660621 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TM9Y080C16MP11 | 14,900 | $745 |
| No | 211660616 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TM9Y100C16MP11 | 15,200 | $760 |
| No | 211660611 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TM9Y100C16MP11 | 15,200 | $760 |
| No | 211660606 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TM9Y100C16MP11 | 14,800 | $740 |
| No | 211660601 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TM9Y100C16MP11 | 14,800 | $740 |
| No | 211660596 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TL8E080C16UH11 | 15,300 | $765 |
| No | 211660591 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TL8E080C16UH11 | 15,300 | $765 |
| No | 211660586 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB30CXXN1+TXV | TL9E060B12UH11 | 15,100 | $755 |
| No | 211660581 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CBAN1 | TL9E060B12UH11 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660576 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CXXN1+TXV | TL9E060B12UH11 | 15,100 | $755 |
| No | 211660571 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TL9E060B12UH11 | 15,100 | $755 |
| No | 211660566 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TL9E060B12UH11 | 15,100 | $755 |
| No | 211660561 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CBAN1 | TL9E060B12UH11 | 14,800 | $740 |
| No | 211660556 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CXXN1+TXV | TL9E060B12UH11 | 14,800 | $740 |
| No | 211660551 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TL9E060B12UH11 | 14,800 | $740 |
| No | 211660546 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TL9E060B12UH11 | 14,800 | $740 |
| No | 211660541 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TL9E080C16UH11 | 15,700 | $785 |
| No | 211660536 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TL9E080C16UH11 | 15,700 | $785 |
| No | 211660531 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TL9E080C16UH11 | 15,300 | $765 |
| No | 211660526 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TL9E080C16UH11 | 15,300 | $765 |
| No | 211660521 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB30CXXN1+TXV | TMLE040A12MP11 | 15,000 | $750 |
| No | 211660516 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CBAN1 | TMLE040A12MP11 | 15,000 | $750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660511 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB30CXXN1+TXV | TM8E040A12MP11 | 15,000 | $750 |
| No | 211660506 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CBAN1 | TM8E040A12MP11 | 15,000 | $750 |
| No | 211660501 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CXXN1+TXV | TMLE040A12MP11 | 15,000 | $750 |
| No | 211660496 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CXXN1+TXV | TM8E040A12MP11 | 15,000 | $750 |
| No | 211660491 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CBAN1 | TMLE040A12MP11 | 14,700 | $735 |
| No | 211660486 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CBAN1 | TM8E040A12MP11 | 14,700 | $735 |
| No | 211660481 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CXXN1+TXV | TMLE040A12MP11 | 14,700 | $735 |
| No | 211660476 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CXXN1+TXV | TM8E040A12MP11 | 14,700 | $735 |
| No | 211660471 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB30CXXN1+TXV | TMLE060A12MP11 | 15,000 | $750 |
| No | 211660466 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CBAN1 | TMLE060A12MP11 | 15,000 | $750 |
| No | 211660461 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB30CXXN1+TXV | TM8E060A12MP11 | 15,000 | $750 |
| No | 211660456 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CBAN1 | TM8E060A12MP11 | 15,000 | $750 |
| No | 211660451 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CXXN1+TXV | TMLE060A12MP11 | 15,000 | $750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660446 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CXXN1+TXV | TM8E060A12MP11 | 15,000 | $750 |
| No | 211660441 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CBAN1 | TMLE060A12MP11 | 14,700 | $735 |
| No | 211660436 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CBAN1 | TM8E060A12MP11 | 14,700 | $735 |
| No | 211660431 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CXXN1+TXV | TMLE060A12MP11 | 14,700 | $735 |
| No | 211660426 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CXXN1+TXV | TM8E060A12MP11 | 14,700 | $735 |
| No | 211660421 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB30CXXN1+TXV | TMLE080B12MP11 | 15,100 | $755 |
| No | 211660416 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CBAN1 | TMLE080B12MP11 | 15,100 | $755 |
| No | 211660411 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB30CXXN1+TXV | TM8E080B12MP11 | 15,100 | $755 |
| No | 211660406 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CBAN1 | TM8E080B12MP11 | 15,100 | $755 |
| No | 211660401 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CXXN1+TXV | TMLE080B12MP11 | 15,100 | $755 |
| No | 211660396 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CXXN1+TXV | TM8E080B12MP11 | 15,100 | $755 |
| No | 211660391 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TMLE080B12MP11 | 15,100 | $755 |
| No | 211660386 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TM8E080B12MP11 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660381 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TMLE080B12MP11 | 15,100 | $755 |
| No | 211660376 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TM8E080B12MP11 | 15,100 | $755 |
| No | 211660371 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CBAN1 | TMLE080B12MP11 | 14,800 | $740 |
| No | 211660366 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CBAN1 | TM8E080B12MP11 | 14,800 | $740 |
| No | 211660361 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CXXN1+TXV | TMLE080B12MP11 | 14,800 | $740 |
| No | 211660356 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CXXN1+TXV | TM8E080B12MP11 | 14,800 | $740 |
| No | 211660351 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TMLE080B12MP11 | 14,800 | $740 |
| No | 211660346 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TM8E080B12MP11 | 14,800 | $740 |
| No | 211660341 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TMLE080B12MP11 | 14,800 | $740 |
| No | 211660336 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TM8E080B12MP11 | 14,800 | $740 |
| No | 211660331 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TMLE080C16MP11 | 15,500 | $775 |
| No | 211660326 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TM8E080C16MP11 | 15,500 | $775 |
| No | 211660321 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TMLE080C16MP11 | 15,500 | $775 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660316 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TM8E080C16MP11 | 15,500 | $775 |
| No | 211660311 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TMLE080C16MP11 | 14,700 | $735 |
| No | 211660306 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TM8E080C16MP11 | 14,700 | $735 |
| No | 211660301 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TMLE080C16MP11 | 14,700 | $735 |
| No | 211660296 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TM8E080C16MP11 | 14,700 | $735 |
| No | 211660291 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB30CXXN1+TXV | TMLE100B12MP11 | 15,100 | $755 |
| No | 211660286 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CBAN1 | TMLE100B12MP11 | 15,100 | $755 |
| No | 211660281 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB30CXXN1+TXV | TM8E100B12MP11 | 15,100 | $755 |
| No | 211660276 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CBAN1 | TM8E100B12MP11 | 15,100 | $755 |
| No | 211660271 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CXXN1+TXV | TMLE100B12MP11 | 15,100 | $755 |
| No | 211660266 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CXXN1+TXV | TM8E100B12MP11 | 15,100 | $755 |
| No | 211660261 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TMLE100B12MP11 | 14,800 | $740 |
| No | 211660256 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TM8E100B12MP11 | 14,800 | $740 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660251 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TMLE100B12MP11 | 14,800 | $740 |
| No | 211660246 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660241 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CBAN1 | TMLE100B12MP11 | 14,800 | $740 |
| No | 211660236 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CBAN1 | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660231 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CXXN1+TXV | TMLE100B12MP11 | 14,800 | $740 |
| No | 211660226 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CXXN1+TXV | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660221 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TMLE100B12MP11 | 14,800 | $740 |
| No | 211660216 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660211 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TMLE100B12MP11 | 14,800 | $740 |
| No | 211660206 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660201 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TMLE100C16MP11 | 15,000 | $750 |
| No | 211660196 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TM8E100C16MP11 | 15,000 | $750 |
| No | 211660191 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TMLE100C16MP11 | 15,000 | $750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660186 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TM8E100C16MP11 | 15,000 | $750 |
| No | 211660181 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TMLE100C16MP11 | 14,700 | $735 |
| No | 211660176 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TM8E100C16MP11 | 14,700 | $735 |
| No | 211660171 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TMLE100C16MP11 | 14,700 | $735 |
| No | 211660166 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TM8E100C16MP11 | 14,700 | $735 |
| No | 211660161 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TMLE120C16MP11 | 15,000 | $750 |
| No | 211660156 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TM8E120C16MP11 | 15,000 | $750 |
| No | 211660151 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TMLE120C16MP11 | 15,000 | $750 |
| No | 211660146 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TM8E120C16MP11 | 15,000 | $750 |
| No | 211660141 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TMLE120C16MP11 | 15,300 | $765 |
| No | 211660136 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TM8E120C16MP11 | 15,300 | $765 |
| No | 211660131 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TMLE120C16MP11 | 15,300 | $765 |
| No | 211660126 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TM8E120C16MP11 | 15,300 | $765 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660119 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB30CXXN1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 211660114 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CBAN1 | TPLC080B12MP13 | 15,100 | $755 |
| No | 211660109 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB30CXXN1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 211660104 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CBAN1 | TM8V080B12MP12 | 15,100 | $755 |
| No | 211660098 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CXXN1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 211660093 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CXXN1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 211660087 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TPLC080B12MP13 | 15,100 | $755 |
| No | 211660082 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TM8V080B12MP12 | 15,100 | $755 |
| No | 211660076 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 211660071 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 211660065 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CBAN1 | TPLC080B12MP13 | 14,900 | $745 |
| No | 211660060 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CBAN1 | TM8V080B12MP12 | 14,900 | $745 |
| No | 211660054 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CXXN1+TXV | TPLC080B12MP13 | 14,900 | $745 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660049 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CXXN1+TXV | TM8V080B12MP12 | 14,900 | $745 |
| No | 211660043 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TPLC080B12MP13 | 14,800 | $740 |
| No | 211660038 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TM8V080B12MP12 | 14,800 | $740 |
| No | 211660032 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TPLC080B12MP13 | 14,800 | $740 |
| No | 211660027 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TM8V080B12MP12 | 14,800 | $740 |
| No | 211660022 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB30CXXN1+TXV | TM8Y060A12MP11 | 15,300 | $765 |
| No | 211660017 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CBAN1 | TM8Y060A12MP11 | 15,300 | $765 |
| No | 211660012 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CXXN1+TXV | TM8Y060A12MP11 | 15,300 | $765 |
| No | 211660007 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CBAN1 | TM8Y060A12MP11 | 15,000 | $750 |
| No | 211660002 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CXXN1+TXV | TM8Y060A12MP11 | 15,000 | $750 |
| No | 211659997 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB30CXXN1+TXV | TM8Y080B12MP11 | 15,300 | $765 |
| No | 211659992 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CBAN1 | TM8Y080B12MP11 | 15,300 | $765 |
| No | 211659987 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CXXN1+TXV | TM8Y080B12MP11 | 15,300 | $765 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211659982 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TM8Y080B12MP11 | 15,300 | $765 |
| No | 211659977 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TM8Y080B12MP11 | 15,300 | $765 |
| No | 211659972 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CBAN1 | TM8Y080B12MP11 | 15,000 | $750 |
| No | 211659967 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CXXN1+TXV | TM8Y080B12MP11 | 15,000 | $750 |
| No | 211659962 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TM8Y080B12MP11 | 15,100 | $755 |
| No | 211659957 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TM8Y080B12MP11 | 15,100 | $755 |
| No | 211659947 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CBAN1 | TM8Y100C16MP11 | 15,100 | $755 |
| No | 211659937 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC30CXXN1+TXV | TM8Y100C16MP11 | 15,100 | $755 |
| No | 211659932 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TM8Y080C16MP11 | 14,800 | $740 |
| No | 211659927 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CBAN1 | TM8Y100C16MP11 | 14,800 | $740 |
| No | 211659922 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TM8Y080C16MP11 | 14,800 | $740 |
| No | 211659917 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC30CXXN1+TXV | TM8Y100C16MP11 | 14,800 | $740 |
| No | 211659912 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB30CXXN1+TXV | TM9E026A08MP12 | 15,400 | $770 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211659907 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CBAN1 | TM9E026A08MP12 | 15,400 | $770 |
| No | 211659902 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB30CXXN1+TXV | TM9E026A08MP12 | 15,400 | $770 |
| No | 211659897 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CBAN1 | TM9E026A08MP12 | 15,100 | $755 |
| No | 211659892 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB30CXXN1+TXV | TM9E026A08MP12 | 15,100 | $755 |
| No | 207417132 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFA30DXXN1+TXV | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 207417128 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFA30DXXN1+TXV | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 207417035 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFA30DXXN1+TXV | TM8Y060A12MP11 | 25,000 | $1,250 |
| No | 207416617 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFA30DXXN1+TXV | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 207416593 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFA30DXXN1+TXV | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 207416589 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFA30DXXN1+TXV | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211398896 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211398882 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211398868 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TMLE080C16MP11 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211398856 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211398841 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TMLE080C16MP11 | 24,800 | $1,240 |
| No | 211398826 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TM8E080C16MP11 | 24,800 | $1,240 |
| No | 211398811 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TMLE080C16MP11 | 24,800 | $1,240 |
| No | 211398798 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TM8E080C16MP11 | 24,800 | $1,240 |
| No | 211398790 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TMLE080C16MP11 | 24,800 | $1,240 |
| No | 211398776 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TM8E080C16MP11 | 24,800 | $1,240 |
| No | 211398763 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TMLE080C16MP11 | 24,800 | $1,240 |
| No | 211398748 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TM8E080C16MP11 | 24,800 | $1,240 |
| No | 211398734 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211398719 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211398704 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211398689 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TM8E100B12MP11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211398674 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211398659 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211398644 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 211398634 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 211398622 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 211398607 | CHAMPION HEATING AND COOLING | HMH72B341 | 0 | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 211398592 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211398577 | CHAMPION HEATING AND COOLING | HMH72B341 | 0 | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211398562 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211398547 | CHAMPION HEATING AND COOLING | HMH72B341 | 0 | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211398532 | CHAMPION HEATING AND COOLING | HMH72B341 | 0 | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211398517 | CHAMPION HEATING AND COOLING | HMH72B341 | 0 | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211398502 | CHAMPION HEATING AND COOLING | HMH72B341 | 0 | TMLE100C16MP11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211398488 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211398477 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211398469 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211398454 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211398439 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211398424 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211398409 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211398394 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211398380 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211398365 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211398353 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211398338 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TMLE120C16MP11 | 25,400 | $1,270 |
| No | 211398326 | CHAMPION HEATING AND COOLING | HMH72B341 | 0 | TMLE120C16MP11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211398315 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TM8E120C16MP11 | 25,400 | $1,270 |
| No | 211398300 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TM8E120C16MP11 | 25,400 | $1,270 |
| No | 211398288 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TMLE120C16MP11 | 25,400 | $1,270 |
| No | 211398273 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TM8E120C16MP11 | 25,400 | $1,270 |
| No | 211398258 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TMLE120C16MP11 | 25,200 | $1,260 |
| No | 211398243 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TM8E120C16MP11 | 25,200 | $1,260 |
| No | 211398228 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TMLE120C16MP11 | 25,200 | $1,260 |
| No | 211398213 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TM8E120C16MP11 | 25,200 | $1,260 |
| No | 211398197 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211398182 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211398167 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211398157 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211398144 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TMLE120C16MP11 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211398129 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211398114 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211398099 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211398086 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TPLC080B12MP13 | 25,800 | $1,290 |
| No | 211398074 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TPLC080B12MP13 | 25,800 | $1,290 |
| No | 211398059 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TM8V080B12MP12 | 25,800 | $1,290 |
| No | 211398044 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TM8V080B12MP12 | 25,800 | $1,290 |
| No | 211398026 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TPLC080B12MP13 | 25,800 | $1,290 |
| No | 211398011 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TM8V080B12MP12 | 25,800 | $1,290 |
| No | 211397993 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TPLC080B12MP13 | 25,200 | $1,260 |
| No | 211397978 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TM8V080B12MP12 | 25,200 | $1,260 |
| No | 211397960 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TPLC080B12MP13 | 25,200 | $1,260 |
| No | 211397945 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TM8V080B12MP12 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211397906 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397891 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397877 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397865 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397850 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211397835 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211397798 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211397783 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211397756 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397741 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397726 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211397702 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211397675 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TPLC100C16MP13 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211397660 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397645 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211397615 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211397588 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397573 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397558 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211397528 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211397501 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TPLC100C16MP13 | 25,400 | $1,270 |
| No | 211397486 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TPLC080C16MP13 | 25,400 | $1,270 |
| No | 211397471 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TMLV100C16MP12 | 25,400 | $1,270 |
| No | 211397448 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TM8V100C16MP12 | 25,400 | $1,270 |
| No | 211397427 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TPLC100C16MP13 | 25,400 | $1,270 |
| No | 211397412 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TPLC080C16MP13 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211397397 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TMLV100C16MP12 | 25,400 | $1,270 |
| No | 211397374 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TM8V100C16MP12 | 25,400 | $1,270 |
| No | 211397347 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TPLC100C16MP13 | 25,200 | $1,260 |
| No | 211397331 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TPLC080C16MP13 | 25,200 | $1,260 |
| No | 211397317 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TMLV100C16MP12 | 25,200 | $1,260 |
| No | 211397305 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TM8V080C16MP12 | 25,200 | $1,260 |
| No | 211397290 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TM8V100C16MP12 | 25,200 | $1,260 |
| No | 211397267 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TPLC100C16MP13 | 25,200 | $1,260 |
| No | 211397252 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TPLC080C16MP13 | 25,200 | $1,260 |
| No | 211397237 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TMLV100C16MP12 | 25,200 | $1,260 |
| No | 211397222 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TM8V080C16MP12 | 25,200 | $1,260 |
| No | 211397206 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TM8V100C16MP12 | 25,200 | $1,260 |
| No | 211397182 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TPLC120C20MP13 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211397168 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TPLC100C20MP13 | 25,200 | $1,260 |
| No | 211397161 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TMLV120C20MP12 | 25,200 | $1,260 |
| No | 211397146 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TM8V100C20MP12 | 25,200 | $1,260 |
| No | 211397131 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TM8V120C20MP12 | 25,200 | $1,260 |
| No | 211397110 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TPLC120C20MP13 | 25,200 | $1,260 |
| No | 211397096 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TPLC100C20MP13 | 25,200 | $1,260 |
| No | 211397080 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TMLV120C20MP12 | 25,200 | $1,260 |
| No | 211397065 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TM8V100C20MP12 | 25,200 | $1,260 |
| No | 211397050 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TM8V120C20MP12 | 25,200 | $1,260 |
| No | 211397035 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211397020 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211397005 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211396990 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TM8Y080B12MP11 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211396980 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211396966 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TM8Y080C16MP11 | 25,800 | $1,290 |
| No | 211396951 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TM8Y080C16MP11 | 25,800 | $1,290 |
| No | 211396936 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211396922 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211396912 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TM8Y080C16MP11 | 25,800 | $1,290 |
| No | 211396897 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211396882 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TM8Y080C16MP11 | 25,800 | $1,290 |
| No | 211396867 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211396852 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TM8Y080C16MP11 | 25,800 | $1,290 |
| No | 211396837 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211396822 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TM8Y080C16MP11 | 25,400 | $1,270 |
| No | 211396807 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TM8Y100C16MP11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211396799 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TM8Y080C16MP11 | 25,400 | $1,270 |
| No | 211396784 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211396769 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TM8Y080C16MP11 | 25,400 | $1,270 |
| No | 211396754 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211396739 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TM8Y080C16MP11 | 25,400 | $1,270 |
| No | 211396725 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211396710 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TM8Y100C20MP11 | 25,600 | $1,280 |
| No | 211396694 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TM8Y100C20MP11 | 25,600 | $1,280 |
| No | 211396683 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TM8Y120C20MP11 | 25,600 | $1,280 |
| No | 211396668 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TM8Y120C20MP11 | 25,600 | $1,280 |
| No | 211396653 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TM8Y100C20MP11 | 25,600 | $1,280 |
| No | 211396637 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TM8Y120C20MP11 | 25,600 | $1,280 |
| No | 211396625 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TM8Y100C20MP11 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211396614 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TM8Y120C20MP11 | 25,600 | $1,280 |
| No | 211396599 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TM8Y100C20MP11 | 25,600 | $1,280 |
| No | 211396586 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TM8Y120C20MP11 | 25,600 | $1,280 |
| No | 211396571 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TM8Y100C20MP11 | 25,200 | $1,260 |
| No | 211396556 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211396540 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TM8Y100C20MP11 | 25,200 | $1,260 |
| No | 211396523 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211396500 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TM8Y100C20MP11 | 25,200 | $1,260 |
| No | 211396479 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211396454 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TM8Y100C20MP11 | 25,200 | $1,260 |
| No | 211396432 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211396410 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211396385 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TM9E060B12MP12 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211396362 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211396342 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211396317 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211396295 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TM9E080B12MP12 | 25,600 | $1,280 |
| No | 211396275 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TM9E080B12MP12 | 25,600 | $1,280 |
| No | 211396253 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TM9E080B12MP12 | 25,600 | $1,280 |
| No | 211396230 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211396210 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211396190 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TM9E080C16MP12 | 26,000 | $1,300 |
| No | 211396171 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TM9E080C16MP12 | 26,000 | $1,300 |
| No | 211396152 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TM9E080C16MP12 | 26,000 | $1,300 |
| No | 211396134 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TM9E080C16MP12 | 26,000 | $1,300 |
| No | 211396119 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TM9E080C16MP12 | 26,000 | $1,300 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211396105 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211396089 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211396074 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211396059 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211396044 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211396031 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211396017 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211396003 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211395987 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211395973 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211395960 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211395946 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211395933 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TM9E100C16MP12 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211395909 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211395897 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211395885 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211395868 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211395839 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211395815 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211395793 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TP9C060B12MP13 | 25,200 | $1,260 |
| No | 211395771 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TM9V060B12MP12 | 25,200 | $1,260 |
| No | 211395743 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TP9C060B12MP13 | 25,200 | $1,260 |
| No | 211395722 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TM9V060B12MP12 | 25,200 | $1,260 |
| No | 211395683 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TP9C080B12MP13 | 25,600 | $1,280 |
| No | 211395662 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TP9C080B12MP13 | 25,600 | $1,280 |
| No | 211395636 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TM9V080B12MP12 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211395617 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TM9V080B12MP12 | 25,600 | $1,280 |
| No | 211395586 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TP9C080B12MP13 | 25,600 | $1,280 |
| No | 211395562 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TM9V080B12MP12 | 25,600 | $1,280 |
| No | 211395530 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TP9C080B12MP13 | 25,200 | $1,260 |
| No | 211395505 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TM9V080B12MP12 | 25,200 | $1,260 |
| No | 211395479 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TP9C080B12MP13 | 25,200 | $1,260 |
| No | 211395460 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TM9V080B12MP12 | 25,200 | $1,260 |
| No | 211395414 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395395 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395371 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211395354 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211395326 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395301 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TM9V080C16MP12 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211395265 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395241 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211395211 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395185 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211395151 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TP9C080C16MP13 | 24,800 | $1,240 |
| No | 211395128 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TM9V080C16MP12 | 24,800 | $1,240 |
| No | 211395096 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TP9C080C16MP13 | 24,800 | $1,240 |
| No | 211395079 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TM9V080C16MP12 | 24,800 | $1,240 |
| No | 211395048 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TP9C080C16MP13 | 25,000 | $1,250 |
| No | 211395037 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TM9V080C16MP12 | 25,000 | $1,250 |
| No | 211395019 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TP9C080C16MP13 | 25,000 | $1,250 |
| No | 211395005 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TM9V080C16MP12 | 25,000 | $1,250 |
| No | 211394979 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TP9C100C16MP13 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211394964 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394949 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211394936 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211394917 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394903 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211394884 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394871 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211394850 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394836 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211394815 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211394800 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TM9V100C16MP12 | 24,800 | $1,240 |
| No | 211394779 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211394765 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TM9V100C16MP12 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211394744 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211394729 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TM9V100C16MP12 | 24,800 | $1,240 |
| No | 211394712 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211394698 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TM9V100C16MP12 | 24,800 | $1,240 |
| No | 211394671 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TP9C100C20MP13 | 25,800 | $1,290 |
| No | 211394656 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TP9C100C20MP13 | 25,800 | $1,290 |
| No | 211394644 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TM9V100C20MP12 | 25,800 | $1,290 |
| No | 211394629 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TM9V100C20MP12 | 25,800 | $1,290 |
| No | 211394612 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TP9C100C20MP13 | 25,800 | $1,290 |
| No | 211394597 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TM9V100C20MP12 | 25,800 | $1,290 |
| No | 211394576 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TP9C100C20MP13 | 25,600 | $1,280 |
| No | 211394561 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TM9V100C20MP12 | 25,600 | $1,280 |
| No | 211394542 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TP9C100C20MP13 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211394529 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TM9V100C20MP12 | 25,600 | $1,280 |
| No | 211394512 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TP9C100C20MP13 | 25,000 | $1,250 |
| No | 211394500 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TM9V100C20MP12 | 25,000 | $1,250 |
| No | 211394480 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TP9C100C20MP13 | 25,000 | $1,250 |
| No | 211394467 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TM9V100C20MP12 | 25,000 | $1,250 |
| No | 211394446 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TP9C100C20MP13 | 25,200 | $1,260 |
| No | 211394431 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TM9V100C20MP12 | 25,200 | $1,260 |
| No | 211394413 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TP9C100C20MP13 | 25,200 | $1,260 |
| No | 211394400 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TM9V100C20MP12 | 25,200 | $1,260 |
| No | 211394379 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TP9C120D20MP13 | 25,400 | $1,270 |
| No | 211394364 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TM9V120D20MP12 | 25,400 | $1,270 |
| No | 211394347 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TP9C120D20MP13 | 25,400 | $1,270 |
| No | 211394334 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TM9V120D20MP12 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211394315 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TP9C120D20MP13 | 24,800 | $1,240 |
| No | 211394302 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TM9V120D20MP12 | 24,800 | $1,240 |
| No | 211394282 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TP9C120D20MP13 | 24,800 | $1,240 |
| No | 211394267 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TM9V120D20MP12 | 24,800 | $1,240 |
| No | 211394252 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TM9Y060B12MP11 | 25,800 | $1,290 |
| No | 211394237 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TM9Y060B12MP11 | 25,800 | $1,290 |
| No | 211394225 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TM9Y060B12MP11 | 25,800 | $1,290 |
| No | 211394210 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TM9Y060B12MP11 | 25,400 | $1,270 |
| No | 211394197 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TM9Y060B12MP11 | 25,400 | $1,270 |
| No | 211394182 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211394167 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211394156 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211394141 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TM9Y080B12MP11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211394126 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TM9Y080B12MP11 | 25,400 | $1,270 |
| No | 211394113 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TM9Y080C16MP11 | 25,800 | $1,290 |
| No | 211394098 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TM9Y080C16MP11 | 25,800 | $1,290 |
| No | 211394085 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TM9Y080C16MP11 | 25,800 | $1,290 |
| No | 211394070 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TM9Y080C16MP11 | 25,400 | $1,270 |
| No | 211394055 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TM9Y080C16MP11 | 25,400 | $1,270 |
| No | 211394040 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TM9Y080C16MP11 | 25,200 | $1,260 |
| No | 211394025 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TM9Y080C16MP11 | 25,200 | $1,260 |
| No | 211394010 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TM9Y080C16MP11 | 25,000 | $1,250 |
| No | 211393995 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TM9Y080C16MP11 | 25,000 | $1,250 |
| No | 211393980 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TM9Y100C16MP11 | 25,800 | $1,290 |
| No | 211393965 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TM9Y100C16MP11 | 25,800 | $1,290 |
| No | 211393950 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TM9Y100C16MP11 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211393935 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TM9Y100C16MP11 | 25,400 | $1,270 |
| No | 211393920 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TM9Y100C16MP11 | 25,400 | $1,270 |
| No | 211393905 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TM9Y100C16MP11 | 25,200 | $1,260 |
| No | 211393890 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TM9Y100C16MP11 | 25,200 | $1,260 |
| No | 211393875 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TM9Y100C16MP11 | 25,200 | $1,260 |
| No | 211393860 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TM9Y100C16MP11 | 25,200 | $1,260 |
| No | 211393845 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TM9Y120D20MP11 | 25,400 | $1,270 |
| No | 211393830 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TM9Y120D20MP11 | 25,400 | $1,270 |
| No | 211393815 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TM9Y120D20MP11 | 25,000 | $1,250 |
| No | 211393800 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TM9Y120D20MP11 | 25,000 | $1,250 |
| No | 211393785 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFA30DXXN1+TXV | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 211393770 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFA30DXXN1+TXV | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 211393756 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFA30DXXN1+TXV | TM8E040A12MP11 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211393741 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFA30DXXN1+TXV | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 211393726 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFA30DXXN1+TXV | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 211393711 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFA30DXXN1+TXV | TPLC060A12MP13 | 25,800 | $1,290 |
| No | 211393696 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFA30DXXN1+TXV | TMLV060A12MP12 | 25,800 | $1,290 |
| No | 211393680 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFA30DXXN1+TXV | TM8V060A12MP12 | 25,800 | $1,290 |
| No | 211393666 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFA30DXXN1+TXV | TM8Y060A12MP11 | 25,200 | $1,260 |
| No | 211393638 | CHAMPION HEATING AND COOLING | HMH72B341 | JHETB36DBCS2N1 | | 25,400 | $1,270 |
| No | 211393624 | CHAMPION HEATING AND COOLING | HMH72B341 | JHVTB36DBCC2N1 | | 25,200 | $1,260 |
| No | 211393610 | CHAMPION HEATING AND COOLING | HMH72B341 | JHVTC36DBCC2N1 | | 25,400 | $1,270 |
| No | 211393597 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB30CXXN1+TXV | TL8E060A12UH11 | 26,200 | $1,310 |
| No | 211393583 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB30CXXN1+TXV | TL8E060A12UH11 | 26,200 | $1,310 |
| No | 211393568 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB36DXXN1+TXV | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 211393553 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DBCN1 | TL8E060A12UH11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211393538 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DXXN1+TXV | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 211393524 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB30CXXN1+TXV | TL8E060A12UH11 | 25,800 | $1,290 |
| No | 211393509 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DBCN1 | TL8E060A12UH11 | 25,000 | $1,250 |
| No | 211393494 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DXXN1+TXV | TL8E060A12UH11 | 25,000 | $1,250 |
| No | 211393479 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TL8E080C16UH11 | 26,600 | $1,330 |
| No | 211393464 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211393449 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211393434 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TL8E080C16UH11 | 26,000 | $1,300 |
| No | 211393420 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TL8E080C16UH11 | 25,800 | $1,290 |
| No | 211393405 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TL8E080C16UH11 | 25,800 | $1,290 |
| No | 211393390 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TL8E100C20UH11 | 26,400 | $1,320 |
| No | 211393375 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211393360 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TL8E100C20UH11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211393348 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TL8E100C20UH11 | 25,800 | $1,290 |
| No | 211393328 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TL8E100C20UH11 | 25,600 | $1,280 |
| No | 211393313 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TL8E100C20UH11 | 25,600 | $1,280 |
| No | 211393299 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB30CXXN1+TXV | TL9E060B12UH11 | 26,400 | $1,320 |
| No | 211393284 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB30CXXN1+TXV | TL9E060B12UH11 | 26,400 | $1,320 |
| No | 211393269 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB36DXXN1+TXV | TL9E060B12UH11 | 25,000 | $1,250 |
| No | 211393254 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DBCN1 | TL9E060B12UH11 | 25,000 | $1,250 |
| No | 211393246 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DXXN1+TXV | TL9E060B12UH11 | 25,000 | $1,250 |
| No | 211393231 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TL9E060B12UH11 | 26,400 | $1,320 |
| No | 211393216 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TL9E060B12UH11 | 25,600 | $1,280 |
| No | 211393201 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TL9E060B12UH11 | 25,600 | $1,280 |
| No | 211393186 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB30CXXN1+TXV | TL9E060B12UH11 | 25,200 | $1,260 |
| No | 211393175 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TL9E060B12UH11 | 26,000 | $1,300 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211393160 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TL9E060B12UH11 | 24,400 | $1,220 |
| No | 211393145 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TL9E060B12UH11 | 24,400 | $1,220 |
| No | 211393130 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TL9E080C16UH11 | 26,200 | $1,310 |
| No | 211393115 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TL9E080C16UH11 | 25,800 | $1,290 |
| No | 211393100 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TL9E080C16UH11 | 25,800 | $1,290 |
| No | 211393085 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TL9E080C16UH11 | 26,400 | $1,320 |
| No | 211393074 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TL9E080C16UH11 | 25,400 | $1,270 |
| No | 211393066 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TL9E080C16UH11 | 25,400 | $1,270 |
| No | 211393051 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TL9E100C20UH11 | 26,400 | $1,320 |
| No | 211393037 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TL9E100C20UH11 | 26,200 | $1,310 |
| No | 211393022 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TL9E100C20UH11 | 26,200 | $1,310 |
| No | 211393006 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TL9E100C20UH11 | 26,000 | $1,300 |
| No | 211392991 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TL9E100C20UH11 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211392976 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TL9E100C20UH11 | 25,600 | $1,280 |
| No | 211392962 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB30CXXN1+TXV | TMLE040A12MP11 | 26,200 | $1,310 |
| No | 211392947 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB30CXXN1+TXV | TM8E040A12MP11 | 26,200 | $1,310 |
| No | 211392932 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB30CXXN1+TXV | TMLE040A12MP11 | 26,200 | $1,310 |
| No | 211392917 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB30CXXN1+TXV | TM8E040A12MP11 | 26,200 | $1,310 |
| No | 211392902 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB36DXXN1+TXV | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 211392888 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DBCN1 | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 211392881 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB36DXXN1+TXV | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211392866 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DBCN1 | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211392851 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DXXN1+TXV | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 211392836 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DXXN1+TXV | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211392821 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB30CXXN1+TXV | TMLE040A12MP11 | 25,600 | $1,280 |
| No | 211392806 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB30CXXN1+TXV | TM8E040A12MP11 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211392791 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DBCN1 | TMLE040A12MP11 | 24,800 | $1,240 |
| No | 211392776 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DBCN1 | TM8E040A12MP11 | 24,800 | $1,240 |
| No | 211392761 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DXXN1+TXV | TMLE040A12MP11 | 24,800 | $1,240 |
| No | 211392746 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DXXN1+TXV | TM8E040A12MP11 | 24,800 | $1,240 |
| No | 211392731 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB30CXXN1+TXV | TMLE060A12MP11 | 26,200 | $1,310 |
| No | 211392716 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB30CXXN1+TXV | TM8E060A12MP11 | 26,200 | $1,310 |
| No | 211392701 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB30CXXN1+TXV | TMLE060A12MP11 | 26,200 | $1,310 |
| No | 211392695 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB30CXXN1+TXV | TM8E060A12MP11 | 26,200 | $1,310 |
| No | 211392684 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB36DXXN1+TXV | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 211392669 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DBCN1 | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 211392655 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB36DXXN1+TXV | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 211392640 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DBCN1 | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 211392625 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DXXN1+TXV | TMLE060A12MP11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211392610 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DXXN1+TXV | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 211392595 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB30CXXN1+TXV | TMLE060A12MP11 | 25,800 | $1,290 |
| No | 211392580 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB30CXXN1+TXV | TM8E060A12MP11 | 25,800 | $1,290 |
| No | 211392565 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DBCN1 | TMLE060A12MP11 | 25,000 | $1,250 |
| No | 211392554 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DBCN1 | TM8E060A12MP11 | 25,000 | $1,250 |
| No | 211392539 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DXXN1+TXV | TMLE060A12MP11 | 25,000 | $1,250 |
| No | 211392524 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DXXN1+TXV | TM8E060A12MP11 | 25,000 | $1,250 |
| No | 211392513 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB30CXXN1+TXV | TMLE080B12MP11 | 26,800 | $1,340 |
| No | 211392498 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB30CXXN1+TXV | TM8E080B12MP11 | 26,800 | $1,340 |
| No | 211392483 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB30CXXN1+TXV | TMLE080B12MP11 | 26,800 | $1,340 |
| No | 211392468 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB30CXXN1+TXV | TM8E080B12MP11 | 26,800 | $1,340 |
| No | 211392453 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB36DXXN1+TXV | TMLE080B12MP11 | 25,800 | $1,290 |
| No | 211392442 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DBCN1 | TMLE080B12MP11 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211392427 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB36DXXN1+TXV | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211392414 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DBCN1 | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211392403 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DXXN1+TXV | TMLE080B12MP11 | 25,800 | $1,290 |
| No | 211392388 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DXXN1+TXV | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211392373 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TMLE080B12MP11 | 26,800 | $1,340 |
| No | 211392358 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TM8E080B12MP11 | 26,800 | $1,340 |
| No | 211392343 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TMLE080B12MP11 | 25,800 | $1,290 |
| No | 211392328 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211392313 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TMLE080B12MP11 | 25,800 | $1,290 |
| No | 211392301 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211392286 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB30CXXN1+TXV | TMLE080B12MP11 | 26,200 | $1,310 |
| No | 211392276 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB30CXXN1+TXV | TM8E080B12MP11 | 26,200 | $1,310 |
| No | 211392268 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DBCN1 | TMLE080B12MP11 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211392253 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DBCN1 | TM8E080B12MP11 | 25,000 | $1,250 |
| No | 211392238 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DXXN1+TXV | TMLE080B12MP11 | 25,000 | $1,250 |
| No | 211392223 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DXXN1+TXV | TM8E080B12MP11 | 25,000 | $1,250 |
| No | 211392208 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TMLE080B12MP11 | 26,400 | $1,320 |
| No | 211392196 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TM8E080B12MP11 | 26,400 | $1,320 |
| No | 211392187 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TMLE080B12MP11 | 25,000 | $1,250 |
| No | 211392171 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TM8E080B12MP11 | 25,000 | $1,250 |
| No | 211392156 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TMLE080B12MP11 | 25,000 | $1,250 |
| No | 211392141 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TM8E080B12MP11 | 25,000 | $1,250 |
| No | 211392126 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TMLE080C16MP11 | 26,000 | $1,300 |
| No | 211392111 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TM8E080C16MP11 | 26,000 | $1,300 |
| No | 211392096 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211392081 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TM8E080C16MP11 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211392066 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211392058 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211392047 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TMLE080C16MP11 | 25,600 | $1,280 |
| No | 211392032 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TM8E080C16MP11 | 25,600 | $1,280 |
| No | 211392017 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TMLE080C16MP11 | 24,600 | $1,230 |
| No | 211392002 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TM8E080C16MP11 | 24,600 | $1,230 |
| No | 211391987 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TMLE080C16MP11 | 24,600 | $1,230 |
| No | 211391972 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TM8E080C16MP11 | 24,600 | $1,230 |
| No | 211391957 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB30CXXN1+TXV | TMLE100B12MP11 | 26,200 | $1,310 |
| No | 211391942 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB30CXXN1+TXV | TM8E100B12MP11 | 26,200 | $1,310 |
| No | 211391927 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB30CXXN1+TXV | TMLE100B12MP11 | 26,200 | $1,310 |
| No | 211391912 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB30CXXN1+TXV | TM8E100B12MP11 | 26,200 | $1,310 |
| No | 211391897 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB36DXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211391882 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DBCN1 | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211391867 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB36DXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211391852 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DBCN1 | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211391838 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211391824 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211391809 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TMLE100B12MP11 | 26,200 | $1,310 |
| No | 211391794 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TM8E100B12MP11 | 26,200 | $1,310 |
| No | 211391783 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211391768 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211391753 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211391742 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211391728 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB30CXXN1+TXV | TMLE100B12MP11 | 25,800 | $1,290 |
| No | 211391713 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB30CXXN1+TXV | TM8E100B12MP11 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211391701 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DBCN1 | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 211391696 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DBCN1 | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 211391681 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DXXN1+TXV | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 211391666 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DXXN1+TXV | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 211391651 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TMLE100B12MP11 | 25,600 | $1,280 |
| No | 211391636 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TM8E100B12MP11 | 25,600 | $1,280 |
| No | 211391627 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TMLE100B12MP11 | 24,800 | $1,240 |
| No | 211391614 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TM8E100B12MP11 | 24,800 | $1,240 |
| No | 211391599 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TMLE100B12MP11 | 24,800 | $1,240 |
| No | 211391584 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TM8E100B12MP11 | 24,800 | $1,240 |
| No | 211391569 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TMLE100C16MP11 | 26,000 | $1,300 |
| No | 211391554 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TM8E100C16MP11 | 26,000 | $1,300 |
| No | 211391539 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TMLE100C16MP11 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211391524 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TM8E100C16MP11 | 25,200 | $1,260 |
| No | 211391509 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TMLE100C16MP11 | 25,200 | $1,260 |
| No | 211391494 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TM8E100C16MP11 | 25,200 | $1,260 |
| No | 211391479 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TMLE100C16MP11 | 25,600 | $1,280 |
| No | 211391464 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TM8E100C16MP11 | 25,600 | $1,280 |
| No | 211391449 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211391434 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211391419 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211391404 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211391389 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TMLE120C16MP11 | 26,200 | $1,310 |
| No | 211391374 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TM8E120C16MP11 | 26,200 | $1,310 |
| No | 211391359 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TMLE120C16MP11 | 25,200 | $1,260 |
| No | 211391344 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TM8E120C16MP11 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211391329 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TMLE120C16MP11 | 25,200 | $1,260 |
| No | 211391314 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TM8E120C16MP11 | 25,200 | $1,260 |
| No | 211391299 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TMLE120C16MP11 | 25,600 | $1,280 |
| No | 211391285 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TM8E120C16MP11 | 25,600 | $1,280 |
| No | 211391270 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211391255 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211391241 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211391226 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211391211 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB30CXXN1+TXV | TPLC060A12MP13 | 26,000 | $1,300 |
| No | 211391196 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB30CXXN1+TXV | TMLV060A12MP12 | 26,000 | $1,300 |
| No | 211391181 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB30CXXN1+TXV | TM8V060A12MP12 | 26,000 | $1,300 |
| No | 211391166 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB30CXXN1+TXV | TPLC060A12MP13 | 26,000 | $1,300 |
| No | 211391152 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB30CXXN1+TXV | TMLV060A12MP12 | 26,000 | $1,300 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211391137 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB30CXXN1+TXV | TM8V060A12MP12 | 26,000 | $1,300 |
| No | 211391122 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB36DXXN1+TXV | TPLC060A12MP13 | 25,600 | $1,280 |
| No | 211391107 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DBCN1 | TPLC060A12MP13 | 25,600 | $1,280 |
| No | 211391092 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB36DXXN1+TXV | TMLV060A12MP12 | 25,600 | $1,280 |
| No | 211391077 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DBCN1 | TMLV060A12MP12 | 25,600 | $1,280 |
| No | 211391062 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB36DXXN1+TXV | TM8V060A12MP12 | 25,600 | $1,280 |
| No | 211391047 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DBCN1 | TM8V060A12MP12 | 25,600 | $1,280 |
| No | 211391032 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DXXN1+TXV | TPLC060A12MP13 | 25,600 | $1,280 |
| No | 211391017 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DXXN1+TXV | TMLV060A12MP12 | 25,600 | $1,280 |
| No | 211391002 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DXXN1+TXV | TM8V060A12MP12 | 25,600 | $1,280 |
| No | 211390987 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB30CXXN1+TXV | TPLC060A12MP13 | 25,600 | $1,280 |
| No | 211390972 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB30CXXN1+TXV | TMLV060A12MP12 | 25,600 | $1,280 |
| No | 211390957 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB30CXXN1+TXV | TM8V060A12MP12 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211390943 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DBCN1 | TPLC060A12MP13 | 25,200 | $1,260 |
| No | 211390928 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DBCN1 | TMLV060A12MP12 | 25,200 | $1,260 |
| No | 211390913 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DBCN1 | TM8V060A12MP12 | 25,200 | $1,260 |
| No | 211390898 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DXXN1+TXV | TPLC060A12MP13 | 25,200 | $1,260 |
| No | 211390883 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DXXN1+TXV | TMLV060A12MP12 | 25,200 | $1,260 |
| No | 211390869 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DXXN1+TXV | TM8V060A12MP12 | 25,200 | $1,260 |
| No | 211390851 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB30CXXN1+TXV | TPLC080B12MP13 | 26,400 | $1,320 |
| No | 211390836 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB30CXXN1+TXV | TM8V080B12MP12 | 26,400 | $1,320 |
| No | 211390818 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB30CXXN1+TXV | TPLC080B12MP13 | 26,400 | $1,320 |
| No | 211390803 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB30CXXN1+TXV | TM8V080B12MP12 | 26,400 | $1,320 |
| No | 211390783 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB36DXXN1+TXV | TPLC080B12MP13 | 25,400 | $1,270 |
| No | 211390768 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DBCN1 | TPLC080B12MP13 | 25,400 | $1,270 |
| No | 211390753 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB36DXXN1+TXV | TM8V080B12MP12 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211390738 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DBCN1 | TM8V080B12MP12 | 25,400 | $1,270 |
| No | 211390720 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DXXN1+TXV | TPLC080B12MP13 | 25,400 | $1,270 |
| No | 211390705 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DXXN1+TXV | TM8V080B12MP12 | 25,400 | $1,270 |
| No | 211390687 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TPLC080B12MP13 | 26,400 | $1,320 |
| No | 211390672 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TM8V080B12MP12 | 26,400 | $1,320 |
| No | 211390654 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TPLC080B12MP13 | 25,600 | $1,280 |
| No | 211390640 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TM8V080B12MP12 | 25,600 | $1,280 |
| No | 211390622 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TPLC080B12MP13 | 25,600 | $1,280 |
| No | 211390607 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TM8V080B12MP12 | 25,600 | $1,280 |
| No | 211390589 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB30CXXN1+TXV | TPLC080B12MP13 | 25,600 | $1,280 |
| No | 211390574 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB30CXXN1+TXV | TM8V080B12MP12 | 25,600 | $1,280 |
| No | 211390556 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DBCN1 | TPLC080B12MP13 | 25,000 | $1,250 |
| No | 211390541 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DBCN1 | TM8V080B12MP12 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211390523 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DXXN1+TXV | TPLC080B12MP13 | 25,000 | $1,250 |
| No | 211390508 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DXXN1+TXV | TM8V080B12MP12 | 25,000 | $1,250 |
| No | 211390491 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TPLC080B12MP13 | 26,000 | $1,300 |
| No | 211390476 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TM8V080B12MP12 | 26,000 | $1,300 |
| No | 211390458 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TPLC080B12MP13 | 24,800 | $1,240 |
| No | 211390443 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TM8V080B12MP12 | 24,800 | $1,240 |
| No | 211390425 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TPLC080B12MP13 | 24,800 | $1,240 |
| No | 211390410 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TM8V080B12MP12 | 24,800 | $1,240 |
| No | 211390384 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TPLC100C16MP13 | 26,400 | $1,320 |
| No | 211390369 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TPLC080C16MP13 | 26,400 | $1,320 |
| No | 211390354 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TMLV100C16MP12 | 26,400 | $1,320 |
| No | 211390340 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TM8V080C16MP12 | 26,400 | $1,320 |
| No | 211390326 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TM8V100C16MP12 | 26,400 | $1,320 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211390301 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TPLC100C16MP13 | 25,400 | $1,270 |
| No | 211390287 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TPLC080C16MP13 | 25,400 | $1,270 |
| No | 211390274 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TMLV100C16MP12 | 25,400 | $1,270 |
| No | 211390260 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TM8V080C16MP12 | 25,400 | $1,270 |
| No | 211390245 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TM8V100C16MP12 | 25,400 | $1,270 |
| No | 211390219 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TPLC100C16MP13 | 25,400 | $1,270 |
| No | 211390205 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TPLC080C16MP13 | 25,400 | $1,270 |
| No | 211390191 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TMLV100C16MP12 | 25,400 | $1,270 |
| No | 211390177 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TM8V080C16MP12 | 25,400 | $1,270 |
| No | 211390163 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TM8V100C16MP12 | 25,400 | $1,270 |
| No | 211390139 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TPLC100C16MP13 | 25,600 | $1,280 |
| No | 211390125 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TPLC080C16MP13 | 25,600 | $1,280 |
| No | 211390111 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TMLV100C16MP12 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211390082 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TM8V100C16MP12 | 25,600 | $1,280 |
| No | 211390055 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TPLC100C16MP13 | 25,600 | $1,280 |
| No | 211390042 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TPLC080C16MP13 | 25,600 | $1,280 |
| No | 211390028 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TMLV100C16MP12 | 25,600 | $1,280 |
| No | 211390000 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TM8V100C16MP12 | 25,600 | $1,280 |
| No | 211389975 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TPLC100C16MP13 | 25,600 | $1,280 |
| No | 211389961 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TPLC080C16MP13 | 25,600 | $1,280 |
| No | 211389946 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TMLV100C16MP12 | 25,600 | $1,280 |
| No | 211389917 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TM8V100C16MP12 | 25,600 | $1,280 |
| No | 211389902 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB30CXXN1+TXV | TM8Y060A12MP11 | 25,800 | $1,290 |
| No | 211389889 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB30CXXN1+TXV | TM8Y060A12MP11 | 25,800 | $1,290 |
| No | 211389881 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB36DXXN1+TXV | TM8Y060A12MP11 | 25,200 | $1,260 |
| No | 211389867 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DBCN1 | TM8Y060A12MP11 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211389854 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DXXN1+TXV | TM8Y060A12MP11 | 25,200 | $1,260 |
| No | 211389839 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB30CXXN1+TXV | TM8Y060A12MP11 | 25,400 | $1,270 |
| No | 211389824 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DBCN1 | TM8Y060A12MP11 | 24,600 | $1,230 |
| No | 211389810 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DXXN1+TXV | TM8Y060A12MP11 | 24,600 | $1,230 |
| No | 211389795 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB30CXXN1+TXV | TM8Y080B12MP11 | 26,000 | $1,300 |
| No | 211389780 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB30CXXN1+TXV | TM8Y080B12MP11 | 26,000 | $1,300 |
| No | 211389765 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB36DXXN1+TXV | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211389750 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DBCN1 | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211389735 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DXXN1+TXV | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211389725 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TM8Y080B12MP11 | 26,000 | $1,300 |
| No | 211389713 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211389699 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211389684 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB30CXXN1+TXV | TM8Y080B12MP11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211389669 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DBCN1 | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211389654 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DXXN1+TXV | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211389639 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211389625 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211389610 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211389580 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TM8Y100C16MP11 | 26,400 | $1,320 |
| No | 211389561 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211389532 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211389517 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TM8Y080C16MP11 | 26,600 | $1,330 |
| No | 211389503 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TM8Y100C16MP11 | 26,600 | $1,330 |
| No | 211389488 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TM8Y080C16MP11 | 25,600 | $1,280 |
| No | 211389473 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TM8Y100C16MP11 | 25,600 | $1,280 |
| No | 211389458 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TM8Y080C16MP11 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211389446 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TM8Y100C16MP11 | 25,600 | $1,280 |
| No | 211389417 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TM8Y120C20MP11 | 27,000 | $1,350 |
| No | 211389394 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211389369 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211389354 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TM8Y100C20MP11 | 26,400 | $1,320 |
| No | 211389339 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TM8Y120C20MP11 | 26,400 | $1,320 |
| No | 211389324 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TM8Y100C20MP11 | 25,400 | $1,270 |
| No | 211389310 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TM8Y120C20MP11 | 25,400 | $1,270 |
| No | 211389295 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TM8Y100C20MP11 | 25,400 | $1,270 |
| No | 211389280 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TM8Y120C20MP11 | 25,400 | $1,270 |
| No | 211389266 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB30CXXN1+TXV | TM9E040A10MP12 | 25,800 | $1,290 |
| No | 211389251 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB30CXXN1+TXV | TM9E040A10MP12 | 25,800 | $1,290 |
| No | 211389243 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB30CXXN1+TXV | TM9E060A10MP12 | 26,200 | $1,310 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211389229 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB30CXXN1+TXV | TM9E060A10MP12 | 26,200 | $1,310 |
| No | 211389214 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB36DXXN1+TXV | TM9E060A10MP12 | 25,400 | $1,270 |
| No | 211389199 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DBCN1 | TM9E060A10MP12 | 25,400 | $1,270 |
| No | 211389184 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DXXN1+TXV | TM9E060A10MP12 | 25,400 | $1,270 |
| No | 211389174 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB30CXXN1+TXV | TM9E060A10MP12 | 25,800 | $1,290 |
| No | 211389165 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DBCN1 | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 211389151 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DXXN1+TXV | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 211389136 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB30CXXN1+TXV | TM9E060B12MP12 | 26,400 | $1,320 |
| No | 211389121 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB30CXXN1+TXV | TM9E060B12MP12 | 26,400 | $1,320 |
| No | 211389106 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB36DXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211389091 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DBCN1 | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211389076 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211389062 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TM9E060B12MP12 | 26,400 | $1,320 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211389047 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211389032 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211389017 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB30CXXN1+TXV | TM9E060B12MP12 | 26,000 | $1,300 |
| No | 211389003 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DBCN1 | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211388988 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DXXN1+TXV | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211388973 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TM9E060B12MP12 | 26,200 | $1,310 |
| No | 211388961 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211388947 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211388932 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB30CXXN1+TXV | TM9E080B12MP12 | 26,800 | $1,340 |
| No | 211388917 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB30CXXN1+TXV | TM9E080B12MP12 | 26,800 | $1,340 |
| No | 211388902 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB36DXXN1+TXV | TM9E080B12MP12 | 25,400 | $1,270 |
| No | 211388890 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DBCN1 | TM9E080B12MP12 | 25,400 | $1,270 |
| No | 211388880 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DXXN1+TXV | TM9E080B12MP12 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211388865 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TM9E080B12MP12 | 26,400 | $1,320 |
| No | 211388850 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TM9E080B12MP12 | 25,800 | $1,290 |
| No | 211388835 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TM9E080B12MP12 | 25,800 | $1,290 |
| No | 211388820 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB30CXXN1+TXV | TM9E080B12MP12 | 25,800 | $1,290 |
| No | 211388805 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DBCN1 | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211388796 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DXXN1+TXV | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211388782 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TM9E080B12MP12 | 26,200 | $1,310 |
| No | 211388768 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211388753 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211388738 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TM9E080C16MP12 | 26,200 | $1,310 |
| No | 211388723 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TM9E080C16MP12 | 25,200 | $1,260 |
| No | 211388709 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TM9E080C16MP12 | 25,200 | $1,260 |
| No | 211388694 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TM9E080C16MP12 | 26,800 | $1,340 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211388679 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211388664 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211388649 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TM9E100C16MP12 | 26,200 | $1,310 |
| No | 211388634 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TM9E100C16MP12 | 25,200 | $1,260 |
| No | 211388619 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TM9E100C16MP12 | 25,200 | $1,260 |
| No | 211388605 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TM9E100C16MP12 | 25,600 | $1,280 |
| No | 211388590 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211388575 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211388562 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TM9E100C20MP12 | 25,000 | $1,250 |
| No | 211388552 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TM9E100C20MP12 | 25,000 | $1,250 |
| No | 211388546 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB30CXXN1+TXV | TM9V040A10MP12 | 25,800 | $1,290 |
| No | 211388537 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB30CXXN1+TXV | TM9V040A10MP12 | 25,800 | $1,290 |
| No | 211388522 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB36DXXN1+TXV | TM9V040A10MP12 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211388512 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DBCN1 | TM9V040A10MP12 | 25,200 | $1,260 |
| No | 211388504 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DXXN1+TXV | TM9V040A10MP12 | 25,200 | $1,260 |
| No | 211388490 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB30CXXN1+TXV | TM9V040A10MP12 | 25,200 | $1,260 |
| No | 211388476 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DBCN1 | TM9V040A10MP12 | 24,800 | $1,240 |
| No | 211388463 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DXXN1+TXV | TM9V040A10MP12 | 24,800 | $1,240 |
| No | 211388447 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB30CXXN1+TXV | TP9C060B12MP13 | 26,400 | $1,320 |
| No | 211388437 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB30CXXN1+TXV | TM9V060B12MP12 | 26,400 | $1,320 |
| No | 211388418 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB30CXXN1+TXV | TP9C060B12MP13 | 26,400 | $1,320 |
| No | 211388403 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB30CXXN1+TXV | TM9V060B12MP12 | 26,400 | $1,320 |
| No | 211388378 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB36DXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388369 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DBCN1 | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388355 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB36DXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388340 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DBCN1 | TM9V060B12MP12 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211388323 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388309 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388289 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TP9C060B12MP13 | 26,400 | $1,320 |
| No | 211388275 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TM9V060B12MP12 | 26,400 | $1,320 |
| No | 211388255 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388241 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388227 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388222 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388203 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB30CXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388190 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB30CXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388174 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DBCN1 | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 211388160 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DBCN1 | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 211388140 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DXXN1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211388126 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DXXN1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 211388106 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TP9C060B12MP13 | 26,000 | $1,300 |
| No | 211388092 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TM9V060B12MP12 | 26,000 | $1,300 |
| No | 211388074 | CHAMPION HEATING AND COOLING | HMH72B341 | 0 | TP9C060B12MP13 | 25,200 | $1,260 |
| No | 211388060 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TM9V060B12MP12 | 25,200 | $1,260 |
| No | 211388042 | CHAMPION HEATING AND COOLING | HMH72B341 | 0 | TP9C060B12MP13 | 25,200 | $1,260 |
| No | 211388030 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TM9V060B12MP12 | 25,200 | $1,260 |
| No | 211388018 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB30CXXN1+TXV | TP9C080B12MP13 | 26,600 | $1,330 |
| No | 211388007 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB30CXXN1+TXV | TM9V080B12MP12 | 26,600 | $1,330 |
| No | 211387987 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB30CXXN1+TXV | TP9C080B12MP13 | 26,600 | $1,330 |
| No | 211387973 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB30CXXN1+TXV | TM9V080B12MP12 | 26,600 | $1,330 |
| No | 211387956 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB36DXXN1+TXV | TP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387942 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DBCN1 | TP9C080B12MP13 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211387927 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB36DXXN1+TXV | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211387916 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DBCN1 | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211387895 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DXXN1+TXV | TP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387880 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DXXN1+TXV | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211387859 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TP9C080B12MP13 | 26,600 | $1,330 |
| No | 211387846 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TM9V080B12MP12 | 26,600 | $1,330 |
| No | 211387835 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387826 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211387814 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387805 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211387793 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB30CXXN1+TXV | TP9C080B12MP13 | 26,200 | $1,310 |
| No | 211387785 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB30CXXN1+TXV | TM9V080B12MP12 | 26,200 | $1,310 |
| No | 211387773 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DBCN1 | TP9C080B12MP13 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211387764 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DBCN1 | TM9V080B12MP12 | 25,200 | $1,260 |
| No | 211387753 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DXXN1+TXV | TP9C080B12MP13 | 25,200 | $1,260 |
| No | 211387745 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DXXN1+TXV | TM9V080B12MP12 | 25,200 | $1,260 |
| No | 211387733 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TP9C080B12MP13 | 26,200 | $1,310 |
| No | 211387725 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TM9V080B12MP12 | 26,200 | $1,310 |
| No | 211387713 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 211387705 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 211387693 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 211387685 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 211387673 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TP9C080C16MP13 | 26,200 | $1,310 |
| No | 211387664 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TM9V080C16MP12 | 26,200 | $1,310 |
| No | 211387653 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211387646 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TM9V080C16MP12 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211387636 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211387627 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211387615 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TP9C080C16MP13 | 25,800 | $1,290 |
| No | 211387608 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TM9V080C16MP12 | 25,800 | $1,290 |
| No | 211387596 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TP9C080C16MP13 | 25,000 | $1,250 |
| No | 211387588 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TM9V080C16MP12 | 25,000 | $1,250 |
| No | 211387575 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TP9C080C16MP13 | 25,000 | $1,250 |
| No | 211387567 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TM9V080C16MP12 | 25,000 | $1,250 |
| No | 211387556 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TP9C100C16MP13 | 26,400 | $1,320 |
| No | 211387548 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TM9V100C16MP12 | 26,400 | $1,320 |
| No | 211387541 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211387532 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211387517 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TP9C100C16MP13 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211387504 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211387486 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TP9C100C16MP13 | 25,800 | $1,290 |
| No | 211387474 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TM9V100C16MP12 | 25,800 | $1,290 |
| No | 211387454 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TP9C100C16MP13 | 25,000 | $1,250 |
| No | 211387440 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TM9V100C16MP12 | 25,000 | $1,250 |
| No | 211387423 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TP9C100C16MP13 | 25,000 | $1,250 |
| No | 211387408 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TM9V100C16MP12 | 25,000 | $1,250 |
| No | 211387389 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TP9C100C20MP13 | 27,000 | $1,350 |
| No | 211387375 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TM9V100C20MP12 | 27,000 | $1,350 |
| No | 211387356 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TP9C100C20MP13 | 26,000 | $1,300 |
| No | 211387340 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TM9V100C20MP12 | 26,000 | $1,300 |
| No | 211387318 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TP9C100C20MP13 | 26,000 | $1,300 |
| No | 211387304 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TM9V100C20MP12 | 26,000 | $1,300 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211387285 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TP9C100C20MP13 | 26,600 | $1,330 |
| No | 211387270 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TM9V100C20MP12 | 26,600 | $1,330 |
| No | 211387257 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB30CXXN1+TXV | TM9Y060B12MP11 | 26,600 | $1,330 |
| No | 211387243 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB30CXXN1+TXV | TM9Y060B12MP11 | 26,600 | $1,330 |
| No | 211387228 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB36DXXN1+TXV | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211387214 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DBCN1 | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211387200 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DXXN1+TXV | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211387185 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TM9Y060B12MP11 | 26,600 | $1,330 |
| No | 211387172 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211386478 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TL8E080C16UH11 | 25,400 | $1,270 |
| No | 211386466 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211386452 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211386438 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TL8E100C20UH11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211386424 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211386411 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211386400 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TL8E100C20UH11 | 24,800 | $1,240 |
| No | 211386387 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TL8E100C20UH11 | 24,800 | $1,240 |
| No | 211386375 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TL8E100C20UH11 | 24,800 | $1,240 |
| No | 211386363 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TL8E100C20UH11 | 24,800 | $1,240 |
| No | 211386352 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TL9E060B12UH11 | 25,800 | $1,290 |
| No | 211386339 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TL9E060B12UH11 | 25,800 | $1,290 |
| No | 211386328 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TL9E060B12UH11 | 25,800 | $1,290 |
| No | 211386316 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TL9E060B12UH11 | 25,200 | $1,260 |
| No | 211386302 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TL9E060B12UH11 | 25,200 | $1,260 |
| No | 211386288 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TL9E080C16UH11 | 25,800 | $1,290 |
| No | 211386274 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TL9E080C16UH11 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211386259 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TL9E080C16UH11 | 25,800 | $1,290 |
| No | 211386247 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TL9E080C16UH11 | 25,600 | $1,280 |
| No | 211386235 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TL9E080C16UH11 | 25,600 | $1,280 |
| No | 211386222 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TL9E080C16UH11 | 25,200 | $1,260 |
| No | 211386209 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TL9E080C16UH11 | 25,200 | $1,260 |
| No | 211386202 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TL9E080C16UH11 | 25,200 | $1,260 |
| No | 211386191 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TL9E080C16UH11 | 25,200 | $1,260 |
| No | 211386174 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211386159 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211386145 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211386128 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211386114 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211386100 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TL9E100C20UH11 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211386086 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TL9E100C20UH11 | 25,000 | $1,250 |
| No | 211386071 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TL9E100C20UH11 | 25,000 | $1,250 |
| No | 211386056 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FXXN1+TXV | TL9E100C20UH11 | 25,000 | $1,250 |
| No | 211386044 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TMLE080B12MP11 | 25,600 | $1,280 |
| No | 211386029 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TMLE080B12MP11 | 25,600 | $1,280 |
| No | 211386014 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TM8E080B12MP11 | 25,600 | $1,280 |
| No | 211385999 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TM8E080B12MP11 | 25,600 | $1,280 |
| No | 211385985 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TMLE080B12MP11 | 25,600 | $1,280 |
| No | 211385973 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TM8E080B12MP11 | 25,600 | $1,280 |
| No | 211385959 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TMLE080B12MP11 | 25,400 | $1,270 |
| No | 211385946 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TM8E080B12MP11 | 25,400 | $1,270 |
| No | 211385932 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TMLE080B12MP11 | 25,400 | $1,270 |
| No | 211385920 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TM8E080B12MP11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211385906 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211385890 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211385873 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211385858 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211385845 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211385833 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211387158 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211387143 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB30CXXN1+TXV | TM9Y060B12MP11 | 26,000 | $1,300 |
| No | 211387130 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DBCN1 | TM9Y060B12MP11 | 25,000 | $1,250 |
| No | 211387116 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DXXN1+TXV | TM9Y060B12MP11 | 25,000 | $1,250 |
| No | 211387102 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TM9Y060B12MP11 | 26,000 | $1,300 |
| No | 211387091 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TM9Y060B12MP11 | 25,200 | $1,260 |
| No | 211387078 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TM9Y060B12MP11 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211387065 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB30CXXN1+TXV | TM9Y080B12MP11 | 26,800 | $1,340 |
| No | 211387052 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB30CXXN1+TXV | TM9Y080B12MP11 | 26,800 | $1,340 |
| No | 211387038 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUB36DXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211387023 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DBCN1 | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211387009 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFB36DXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211386996 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TM9Y080B12MP11 | 26,800 | $1,340 |
| No | 211386981 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211386967 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211386952 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB30CXXN1+TXV | TM9Y080B12MP11 | 26,200 | $1,310 |
| No | 211386939 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DBCN1 | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211386925 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHB36DXXN1+TXV | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211386911 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TM9Y080B12MP11 | 26,200 | $1,310 |
| No | 211386896 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TM9Y080B12MP11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211386882 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TM9Y080B12MP11 | 25,400 | $1,270 |
| No | 211386869 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TM9Y080C16MP11 | 26,800 | $1,340 |
| No | 211386856 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TM9Y080C16MP11 | 25,800 | $1,290 |
| No | 211386841 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TM9Y080C16MP11 | 25,800 | $1,290 |
| No | 211386828 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TM9Y080C16MP11 | 26,200 | $1,310 |
| No | 211386814 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TM9Y080C16MP11 | 25,400 | $1,270 |
| No | 211386799 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TM9Y080C16MP11 | 25,400 | $1,270 |
| No | 211386782 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC30CXXN1+TXV | TM9Y100C16MP11 | 26,000 | $1,300 |
| No | 211386768 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DBCN1 | TM9Y100C16MP11 | 25,800 | $1,290 |
| No | 211386755 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC36DXXN1+TXV | TM9Y100C16MP11 | 25,800 | $1,290 |
| No | 211386742 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC30CXXN1+TXV | TM9Y100C16MP11 | 25,600 | $1,280 |
| No | 211386728 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TM9Y100C16MP11 | 25,400 | $1,270 |
| No | 211386716 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TM9Y100C16MP11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211386703 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DBCN1 | TM9Y100C20MP11 | 25,600 | $1,280 |
| No | 211386689 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC36DXXN1+TXV | TM9Y100C20MP11 | 25,600 | $1,280 |
| No | 211386674 | CHAMPION HEATING AND COOLING | HMH72B341 | JHETC42FBCS2N1 | | 25,200 | $1,260 |
| No | 211386660 | CHAMPION HEATING AND COOLING | HMH72B341 | JHVTC42FBCC2N1 | | 25,000 | $1,250 |
| No | 211386648 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+JMET12CS2N1+TXV | | 25,400 | $1,270 |
| No | 211386635 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1+JMET12CS2N1 | | 25,400 | $1,270 |
| No | 211386623 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+JMET12CS2N1+TXV | | 25,400 | $1,270 |
| No | 211386610 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1+JMET12CS2N1 | | 24,800 | $1,240 |
| No | 211386595 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+JMET12CS2N1+TXV | | 24,800 | $1,240 |
| No | 211386582 | CHAMPION HEATING AND COOLING | HMH72B341 | XAUC48FXXN1+TXV | TL8E080C16UH11 | 26,000 | $1,300 |
| No | 211386572 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FBCN1 | TL8E080C16UH11 | 26,000 | $1,300 |
| No | 211386559 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFC48FXXN1+TXV | TL8E080C16UH11 | 26,000 | $1,300 |
| No | 211386547 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FBCN1 | TL8E080C16UH11 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211386535 | CHAMPION HEATING AND COOLING | HMH72B341 | XAFD48FXXN1+TXV | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211386522 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FBCN1 | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211386507 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHC48FXXN1+TXV | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211386492 | CHAMPION HEATING AND COOLING | HMH72B341 | XAHD48FBCN1 | TL8E080C16UH11 | 25,400 | $1,270 |
| No | 208502150 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB36DXXN1+JMET08BS2N1+TXV | | 13,900 | $695 |
| No | 208503266 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB36DXXN1+JMET08BS2N1+TXV | | 14,200 | $710 |
| No | 208614039 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB36DBAN1+JMET08BS2N1 | | 14,200 | $710 |
| No | 208503248 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB36DXXN1+JMET08BS2N1+TXV | | 14,200 | $710 |
| No | 208502628 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB36DXXN1+JMET12BS2N1+TXV | | 14,200 | $710 |
| No | 208614034 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB36DBAN1+JMET12BS2N1 | | 14,200 | $710 |
| No | 208502620 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB36DXXN1+JMET12BS2N1+TXV | | 14,200 | $710 |
| No | 207434664 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC36DXXN1+MVC12CN21+TXV | | 14,300 | $715 |
| No | 207417444 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC36DXXN1+TXV | TM8Y080B12MP11 | 14,300 | $715 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208213899 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC36DXXN1+TXV | TP9C060B12MP13 | 14,300 | $715 |
| No | 208213894 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC36DXXN1+TXV | TM9V060B12MP12 | 14,300 | $715 |
| No | 208501678 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB36DXXN1+JMVT12BC2N1+TXV | | 13,900 | $695 |
| No | 207434660 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB36DXXN1+ME08BN21+TXV | | 14,100 | $705 |
| No | 207434659 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB36DXXN1+ME08BN21+TXV | | 14,100 | $705 |
| No | 207417477 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB36DXXN1+TXV | TL8E060A12UH11 | 14,400 | $720 |
| No | 207417473 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB36DXXN1+TXV | TL8E060A12UH11 | 14,400 | $720 |
| No | 207416657 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFA30DXXN1+TXV | TM9E060A10MP12 | 14,600 | $730 |
| No | 208213897 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB36DXXN1+TXV | TP9C080B12MP13 | 14,200 | $710 |
| No | 208213892 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB36DXXN1+TXV | TM9V080B12MP12 | 14,200 | $710 |
| No | 207434661 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB36DXXN1+MVC12BN21+TXV | | 14,300 | $715 |
| No | 207434663 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB36DXXN1+MVC12BN21+TXV | | 14,300 | $715 |
| No | 207417192 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFA30DXXN1+TXV | TMLE040A12MP11 | 14,400 | $720 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417188 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFA30DXXN1+TXV | TM8E040A12MP11 | 14,400 | $720 |
| No | 207417460 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB36DXXN1+TXV | TM8Y060A12MP11 | 14,200 | $710 |
| No | 207417456 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB36DXXN1+TXV | TM8Y060A12MP11 | 14,200 | $710 |
| No | 207417438 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB36DXXN1+TXV | TP9C060B12MP13 | 14,600 | $730 |
| No | 207417434 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB36DXXN1+TXV | TM9V060B12MP12 | 14,600 | $730 |
| No | 207417428 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB36DXXN1+TXV | TP9C060B12MP13 | 14,600 | $730 |
| No | 207417424 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB36DXXN1+TXV | TM9V060B12MP12 | 14,600 | $730 |
| No | 207416621 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC36DXXN1+TXV | TM9Y060B12MP11 | 14,500 | $725 |
| No | 208614033 | CHAMPION HEATING AND COOLING | HMH72B241 | JHETB30DBAS2N1 | | 14,600 | $730 |
| No | 208501700 | CHAMPION HEATING AND COOLING | HMH72B241 | JHETB30DXXS2N1+TXV | | 14,600 | $730 |
| No | 208502143 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB36DXXN1+JMET12BS2N1+TXV | | 13,900 | $695 |
| No | 208400369 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB36DXXN1+ME08BN21+TXV | | 14,200 | $710 |
| No | 207417200 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB36DXXN1+TXV | TL9E060B12UH11 | 14,500 | $725 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417196 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB36DXXN1+TXV | TL9E060B12UH11 | 14,500 | $725 |
| No | 208213890 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC36DXXN1+TXV | TPLC080B12MP13 | 14,100 | $705 |
| No | 208213882 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC36DXXN1+TXV | TM8V080B12MP12 | 14,100 | $705 |
| No | 207417164 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB36DXXN1+TXV | TM9E060A10MP12 | 14,600 | $730 |
| No | 207417160 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB36DXXN1+TXV | TM9E060A10MP12 | 14,600 | $730 |
| No | 208213896 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC36DXXN1+TXV | TP9C080B12MP13 | 14,100 | $705 |
| No | 208213891 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC36DXXN1+TXV | TM9V080B12MP12 | 14,100 | $705 |
| No | 208614035 | CHAMPION HEATING AND COOLING | HMH72B241 | JHETB36DBAS2N1 | | 14,300 | $715 |
| No | 208502157 | CHAMPION HEATING AND COOLING | HMH72B241 | JHETB36DXXS2N1+TXV | | 14,300 | $715 |
| No | 208501693 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB36DXXN1+JMVT12BC2N1+TXV | | 14,000 | $700 |
| No | 208614032 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB36DBAN1+JMVT12BC2N1 | | 14,000 | $700 |
| No | 208501686 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB36DXXN1+JMVT12BC2N1+TXV | | 14,000 | $700 |
| No | 207416859 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC36DXXN1+TXV | TMLE100B12MP11 | 14,300 | $715 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207416855 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC36DXXN1+TXV | TM8E100B12MP11 | 14,300 | $715 |
| No | 208614036 | CHAMPION HEATING AND COOLING | HMH72B241 | JHETC36DBAS2N1 | | 14,200 | $710 |
| No | 208500502 | CHAMPION HEATING AND COOLING | HMH72B241 | JHETC36DXXS2N1+TXV | | 14,200 | $710 |
| No | 208400367 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC36DXXN1+MVC12CN21+TXV | | 14,000 | $700 |
| No | 208213878 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC36DXXN1+TXV | TMLE100B12MP11 | 14,000 | $700 |
| No | 208213880 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC36DXXN1+TXV | TM8E100B12MP11 | 14,000 | $700 |
| No | 208213901 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHC36DXXN1+TXV | TM8Y080B12MP11 | 14,000 | $700 |
| No | 207417408 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB36DXXN1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 207417404 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB36DXXN1+TXV | TM9V080B12MP12 | 14,400 | $720 |
| No | 207417398 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB36DXXN1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 207417394 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB36DXXN1+TXV | TM9V080B12MP12 | 14,400 | $720 |
| No | 207434662 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC36DXXN1+ME12CN21+TXV | | 14,200 | $710 |
| No | 207416669 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC36DXXN1+TXV | TL9E060B12UH11 | 14,500 | $725 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417184 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFA30DXXN1+TXV | TM8Y060A12MP11 | 14,700 | $735 |
| No | 207416649 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB36DXXN1+TXV | TM9V040A10MP12 | 14,800 | $740 |
| No | 207416645 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB36DXXN1+TXV | TM9V040A10MP12 | 14,800 | $740 |
| No | 207416629 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB36DXXN1+TXV | TM9Y060B12MP11 | 14,500 | $725 |
| No | 207416625 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB36DXXN1+TXV | TM9Y060B12MP11 | 14,500 | $725 |
| No | 207416673 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFA30DXXN1+TXV | TL8E060A12UH11 | 14,400 | $720 |
| No | 207416850 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB36DXXN1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 207416846 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB36DXXN1+TXV | TM8V080B12MP12 | 14,400 | $720 |
| No | 207416841 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB36DXXN1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 207416837 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB36DXXN1+TXV | TM8V080B12MP12 | 14,400 | $720 |
| No | 207417176 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB36DXXN1+TXV | TM9E026A08MP12 | 14,800 | $740 |
| No | 207417172 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB36DXXN1+TXV | TM9E026A08MP12 | 14,800 | $740 |
| No | 207416831 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC36DXXN1+TXV | TP9C080B12MP13 | 14,400 | $720 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207416827 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC36DXXN1+TXV | TM9V080B12MP12 | 14,400 | $720 |
| No | 208614037 | CHAMPION HEATING AND COOLING | HMH72B241 | JHVTB36DBAC2N1 | | 14,000 | $700 |
| No | 208504353 | CHAMPION HEATING AND COOLING | HMH72B241 | JHVTB36DXXC2N1+TXV | | 14,000 | $700 |
| No | 208614038 | CHAMPION HEATING AND COOLING | HMH72B241 | JHVTC36DBAC2N1 | | 14,100 | $705 |
| No | 208503290 | CHAMPION HEATING AND COOLING | HMH72B241 | JHVTC36DXXC2N1+TXV | | 14,100 | $705 |
| No | 207417468 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC36DXXN1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 207417464 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC36DXXN1+TXV | TM8V080B12MP12 | 14,400 | $720 |
| No | 208400368 | CHAMPION HEATING AND COOLING | HMH72B241 | XAHB36DXXN1+MVC12BN21+TXV | | 14,100 | $705 |
| No | 207416875 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB36DXXN1+TXV | TMLE040A12MP11 | 14,500 | $725 |
| No | 207416871 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB36DXXN1+TXV | TM8E040A12MP11 | 14,500 | $725 |
| No | 207416867 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB36DXXN1+TXV | TMLE040A12MP11 | 14,500 | $725 |
| No | 207416863 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB36DXXN1+TXV | TM8E040A12MP11 | 14,500 | $725 |
| No | 207417452 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB36DXXN1+TXV | TM8Y080B12MP11 | 14,300 | $715 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417448 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB36DXXN1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207417418 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC36DXXN1+TXV | TP9C060B12MP13 | 14,600 | $730 |
| No | 207417414 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFC36DXXN1+TXV | TM9V060B12MP12 | 14,600 | $730 |
| No | 207417390 | CHAMPION HEATING AND COOLING | HMH72B241 | XAUB36DXXN1+TXV | TM9Y080B12MP11 | 14,600 | $730 |
| No | 207417386 | CHAMPION HEATING AND COOLING | HMH72B241 | XAFB36DXXN1+TXV | TM9Y080B12MP11 | 14,600 | $730 |
| No | 208614071 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DBCN1+JMET16CS2N1 | | 24,200 | $1,210 |
| No | 208500514 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+JMET16CS2N1+TXV | | 24,200 | $1,210 |
| No | 208503346 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+JMET12CS2N1+TXV | | 24,200 | $1,210 |
| No | 208614066 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DBCN1+JMET12CS2N1 | | 24,800 | $1,240 |
| No | 208502635 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+JMET12CS2N1+TXV | | 24,800 | $1,240 |
| No | 208503327 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB36DXXN1+JMVT12BC2N1+TXV | | 24,200 | $1,210 |
| No | 208400389 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB36DXXN1+ME12BN21+TXV | | 24,400 | $1,220 |
| No | 208400393 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+MVC12CN21+TXV | | 24,200 | $1,210 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207416605 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 207416601 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 208214143 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB36DXXN1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 208214186 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB36DXXN1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 207417108 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TMLE080C16MP11 | 25,000 | $1,250 |
| No | 207417104 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TM8E080C16MP11 | 25,000 | $1,250 |
| No | 207417100 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TMLE120C16MP11 | 25,000 | $1,250 |
| No | 207417096 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TM8E120C16MP11 | 25,000 | $1,250 |
| No | 208214207 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB36DXXN1+TXV | TM8Y080B12MP11 | 24,400 | $1,220 |
| No | 207417011 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TM8Y120C20MP11 | 24,600 | $1,230 |
| No | 208214166 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TM9E060B12MP12 | 24,200 | $1,210 |
| No | 208214169 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TM9E100C16MP12 | 24,600 | $1,230 |
| No | 207416977 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+TXV | TP9C080B12MP13 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207416973 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+TXV | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 207416967 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+TXV | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 207416963 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+TXV | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 207416429 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TP9C100C20MP13 | 25,200 | $1,260 |
| No | 207416425 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TM9V100C20MP12 | 25,200 | $1,260 |
| No | 208214215 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB36DXXN1+TXV | TM9Y080B12MP11 | 24,400 | $1,220 |
| No | 208502172 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+JMVT12BC2N1+TXV | | 24,600 | $1,230 |
| No | 208614068 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DBCN1+JMVT12BC2N1 | | 24,600 | $1,230 |
| No | 208502164 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+JMVT12BC2N1+TXV | | 24,600 | $1,230 |
| No | 207434695 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+ME12BN21+TXV | | 24,800 | $1,240 |
| No | 207434696 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+ME12BN21+TXV | | 24,800 | $1,240 |
| No | 207434693 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+MVC12CN21+TXV | | 24,600 | $1,230 |
| No | 208214178 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TL8E080C16UH11 | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417148 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+TXV | TMLE040A12MP11 | 25,000 | $1,250 |
| No | 207417144 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+TXV | TM8E040A12MP11 | 25,000 | $1,250 |
| No | 207417140 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+TXV | TMLE040A12MP11 | 25,000 | $1,250 |
| No | 207417136 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+TXV | TM8E040A12MP11 | 25,000 | $1,250 |
| No | 208501100 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+JMVT16CC2N1+TXV | | 24,000 | $1,200 |
| No | 208400390 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+ME12CN21+TXV | | 24,400 | $1,220 |
| No | 208400388 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+MVC16CN21+TXV | | 24,400 | $1,220 |
| No | 208214171 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB36DXXN1+TXV | TL9E060B12UH11 | 24,000 | $1,200 |
| No | 207416585 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+TXV | TMLE060A12MP11 | 25,200 | $1,260 |
| No | 207416581 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+TXV | TM8E060A12MP11 | 25,200 | $1,260 |
| No | 207416577 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+TXV | TMLE060A12MP11 | 25,200 | $1,260 |
| No | 207416573 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+TXV | TM8E060A12MP11 | 25,200 | $1,260 |
| No | 207416561 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+TXV | TMLE100B12MP11 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207416557 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+TXV | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 207416553 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+TXV | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 207416549 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+TXV | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 207417092 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+TXV | TPLC060A12MP13 | 25,400 | $1,270 |
| No | 207417088 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+TXV | TMLV060A12MP12 | 25,400 | $1,270 |
| No | 207417084 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+TXV | TM8V060A12MP12 | 25,400 | $1,270 |
| No | 207417080 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+TXV | TPLC060A12MP13 | 25,400 | $1,270 |
| No | 207417076 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+TXV | TMLV060A12MP12 | 25,400 | $1,270 |
| No | 207417072 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+TXV | TM8V060A12MP12 | 25,400 | $1,270 |
| No | 208214191 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 208214190 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TPLC080C16MP13 | 24,600 | $1,230 |
| No | 208214157 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TMLV100C16MP12 | 24,600 | $1,230 |
| No | 208214154 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TM8V080C16MP12 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208214156 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 207416499 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFA30DXXN1+TXV | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 208214138 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 208214181 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TM8E080B12MP11 | 24,600 | $1,230 |
| No | 208214130 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TMLE100C16MP11 | 24,600 | $1,230 |
| No | 208214146 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TM8E100C16MP11 | 24,600 | $1,230 |
| No | 207416511 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TM8Y080B12MP11 | 25,000 | $1,250 |
| No | 208214164 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB36DXXN1+TXV | TM9E060B12MP12 | 24,200 | $1,210 |
| No | 207416463 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TM9E100C16MP12 | 25,000 | $1,250 |
| No | 208214200 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 208214193 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 208214206 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TP9C100C16MP13 | 24,600 | $1,230 |
| No | 208214198 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TM9V100C16MP12 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207416931 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TM9Y080B12MP11 | 25,000 | $1,250 |
| No | 207416467 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TM9E080B12MP12 | 25,200 | $1,260 |
| No | 207416459 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+TXV | TM9V040A10MP12 | 24,600 | $1,230 |
| No | 207416455 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+TXV | TM9V040A10MP12 | 24,600 | $1,230 |
| No | 208214204 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB36DXXN1+TXV | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 208214196 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB36DXXN1+TXV | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 207416939 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+TXV | TM9Y060B12MP11 | 25,000 | $1,250 |
| No | 207416935 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+TXV | TM9Y060B12MP11 | 25,000 | $1,250 |
| No | 207416927 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TM9Y080C16MP11 | 25,000 | $1,250 |
| No | 208614067 | CHAMPION HEATING AND COOLING | HMH72B361 | JHETB36DBCS2N1 | | 25,000 | $1,250 |
| No | 208502186 | CHAMPION HEATING AND COOLING | HMH72B361 | JHETB36DXXS2N1+TXV | | 25,000 | $1,250 |
| No | 207434692 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+ME16CN21+TXV | | 25,000 | $1,250 |
| No | 208214173 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TL9E060B12UH11 | 24,000 | $1,200 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208214136 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB36DXXN1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 208214185 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB36DXXN1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 207416545 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 207416541 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 207416528 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+TXV | TPLC080B12MP13 | 25,000 | $1,250 |
| No | 207416524 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+TXV | TM8V080B12MP12 | 25,000 | $1,250 |
| No | 207416519 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+TXV | TPLC080B12MP13 | 25,000 | $1,250 |
| No | 207416515 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+TXV | TM8V080B12MP12 | 25,000 | $1,250 |
| No | 207416495 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+TXV | TM9E060A10MP12 | 25,200 | $1,260 |
| No | 207416491 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+TXV | TM9E060A10MP12 | 25,200 | $1,260 |
| No | 208614069 | CHAMPION HEATING AND COOLING | HMH72B361 | JHETC36DBCS2N1 | | 24,000 | $1,200 |
| No | 208500525 | CHAMPION HEATING AND COOLING | HMH72B361 | JHETC36DXXS2N1+TXV | | 24,000 | $1,200 |
| No | 207434690 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+MVC12BN21+TXV | | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207434689 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+MVC12BN21+TXV | | 24,800 | $1,240 |
| No | 208214176 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB36DXXN1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 208214174 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TL9E080C16UH11 | 24,600 | $1,230 |
| No | 207416569 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TMLE080B12MP11 | 25,200 | $1,260 |
| No | 207416565 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TM8E080B12MP11 | 25,200 | $1,260 |
| No | 208214163 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB36DXXN1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 208214192 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB36DXXN1+TXV | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 208214203 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 208214195 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 207416421 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TM9Y060B12MP11 | 25,000 | $1,250 |
| No | 208214219 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TM9Y080C16MP11 | 24,600 | $1,230 |
| No | 208214131 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 208214148 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208214189 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB36DXXN1+TXV | TPLC080B12MP13 | 24,200 | $1,210 |
| No | 208214153 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB36DXXN1+TXV | TM8V080B12MP12 | 24,200 | $1,210 |
| No | 208214209 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB36DXXN1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 208214213 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TM8Y080C16MP11 | 24,000 | $1,200 |
| No | 208214211 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TM8Y100C16MP11 | 24,000 | $1,200 |
| No | 207416487 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 207416483 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 208614064 | CHAMPION HEATING AND COOLING | HMH72B361 | JHVTC36DBCC2N1 | | 24,400 | $1,220 |
| No | 208501707 | CHAMPION HEATING AND COOLING | HMH72B361 | JHVTC36DXXC2N1+TXV | | 24,400 | $1,220 |
| No | 208400391 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+ME16CN21+TXV | | 24,600 | $1,230 |
| No | 207416613 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+TXV | TL8E060A12UH11 | 25,000 | $1,250 |
| No | 207416609 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+TXV | TL8E060A12UH11 | 25,000 | $1,250 |
| No | 207416597 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TL9E080C16UH11 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417124 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+TXV | TMLE080B12MP11 | 25,200 | $1,260 |
| No | 207417120 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+TXV | TM8E080B12MP11 | 25,200 | $1,260 |
| No | 207417116 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+TXV | TMLE080B12MP11 | 25,200 | $1,260 |
| No | 207417112 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+TXV | TM8E080B12MP11 | 25,200 | $1,260 |
| No | 208614070 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DBCN1+JMVT16CC2N1 | | 24,400 | $1,220 |
| No | 208501108 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+JMVT16CC2N1+TXV | | 24,400 | $1,220 |
| No | 207434691 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+ME12CN21+TXV | | 24,800 | $1,240 |
| No | 207434694 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+MVC16CN21+TXV | | 24,800 | $1,240 |
| No | 207417152 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 207417007 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TM9E080C16MP12 | 25,000 | $1,250 |
| No | 207416449 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TP9C060B12MP13 | 24,800 | $1,240 |
| No | 207416445 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TM9V060B12MP12 | 24,800 | $1,240 |
| No | 208214202 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TP9C080C16MP13 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208214197 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TM9V080C16MP12 | 24,600 | $1,230 |
| No | 208214216 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TM9Y060B12MP11 | 24,400 | $1,220 |
| No | 208214218 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TM9Y100C16MP11 | 24,600 | $1,230 |
| No | 208214133 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB36DXXN1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 208214149 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB36DXXN1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 207417067 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TPLC080B12MP13 | 25,000 | $1,250 |
| No | 207417063 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TM8V080B12MP12 | 25,000 | $1,250 |
| No | 207417031 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+TXV | TM8Y060A12MP11 | 24,800 | $1,240 |
| No | 207417027 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+TXV | TM8Y060A12MP11 | 24,800 | $1,240 |
| No | 207416507 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TM8Y080C16MP11 | 24,600 | $1,230 |
| No | 207417015 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TM8Y100C16MP11 | 24,600 | $1,230 |
| No | 208214159 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB36DXXN1+TXV | TM9E060A10MP12 | 24,200 | $1,210 |
| No | 208214135 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TMLE080C16MP11 | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208214179 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TM8E080C16MP11 | 24,400 | $1,220 |
| No | 208214128 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TMLE120C16MP11 | 24,600 | $1,230 |
| No | 208214144 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TM8E120C16MP11 | 24,600 | $1,230 |
| No | 207417055 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TPLC100C16MP13 | 25,200 | $1,260 |
| No | 207417051 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TPLC080C16MP13 | 25,200 | $1,260 |
| No | 207417047 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TMLV100C16MP12 | 25,200 | $1,260 |
| No | 207417043 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TM8V080C16MP12 | 25,200 | $1,260 |
| No | 207417039 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TM8V100C16MP12 | 25,200 | $1,260 |
| No | 208214208 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TM8Y080B12MP11 | 24,400 | $1,220 |
| No | 208214212 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TM8Y100C20MP11 | 24,200 | $1,210 |
| No | 208214210 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TM8Y120C20MP11 | 24,200 | $1,210 |
| No | 208502179 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+JMET16CS2N1+TXV | | 24,400 | $1,220 |
| No | 208614065 | CHAMPION HEATING AND COOLING | HMH72B361 | JHVTB36DBCC2N1 | | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208502643 | CHAMPION HEATING AND COOLING | HMH72B361 | JHVTB36DXXC2N1+TXV | | 25,200 | $1,260 |
| No | 208400392 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB36DXXN1+MVC12BN21+TXV | | 24,400 | $1,220 |
| No | 207417156 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TL8E080C16UH11 | 25,000 | $1,250 |
| No | 208214161 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 207416997 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 207416993 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 207416987 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 207416983 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 207416957 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TP9C080C16MP13 | 25,000 | $1,250 |
| No | 207416953 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TM9V080C16MP12 | 25,000 | $1,250 |
| No | 208214217 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB36DXXN1+TXV | TM9Y060B12MP11 | 23,800 | $1,190 |
| No | 207416923 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TM9Y100C16MP11 | 25,000 | $1,250 |
| No | 207416475 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+TXV | TM9E080B12MP12 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207416471 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+TXV | TM9E080B12MP12 | 25,200 | $1,260 |
| No | 207417003 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFA30DXXN1+TXV | TM9V040A10MP12 | 24,400 | $1,220 |
| No | 207416439 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 207416435 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 208214205 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TP9C100C20MP13 | 25,000 | $1,250 |
| No | 208214199 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TM9V100C20MP12 | 25,000 | $1,250 |
| No | 208214214 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TM9Y080B12MP11 | 24,400 | $1,220 |
| No | 208214141 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB36DXXN1+TXV | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 208214183 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB36DXXN1+TXV | TM8E080B12MP11 | 24,600 | $1,230 |
| No | 207416537 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TMLE100C16MP11 | 25,000 | $1,250 |
| No | 207416533 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TM8E100C16MP11 | 25,000 | $1,250 |
| No | 208214188 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 208214151 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417023 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+TXV | TM8Y080B12MP11 | 25,000 | $1,250 |
| No | 207417019 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+TXV | TM8Y080B12MP11 | 25,000 | $1,250 |
| No | 207416503 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TM8Y100C20MP11 | 24,600 | $1,230 |
| No | 207416479 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 208214167 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHC36DXXN1+TXV | TM9E080C16MP12 | 24,600 | $1,230 |
| No | 208214201 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB36DXXN1+TXV | TP9C060B12MP13 | 24,600 | $1,230 |
| No | 208214194 | CHAMPION HEATING AND COOLING | HMH72B361 | XAHB36DXXN1+TXV | TM9V060B12MP12 | 24,600 | $1,230 |
| No | 207416947 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TP9C100C16MP13 | 25,000 | $1,250 |
| No | 207416943 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFC36DXXN1+TXV | TM9V100C16MP12 | 25,000 | $1,250 |
| No | 207416417 | CHAMPION HEATING AND COOLING | HMH72B361 | XAUB36DXXN1+TXV | TM9Y080B12MP11 | 25,000 | $1,250 |
| No | 207416413 | CHAMPION HEATING AND COOLING | HMH72B361 | XAFB36DXXN1+TXV | TM9Y080B12MP11 | 25,000 | $1,250 |
| No | 208214576 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+TXV | TL8E100C20UH11 | 35,800 | $1,790 |
| No | 208214562 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+TXV | TMLE100C16MP11 | 36,000 | $1,800 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208214568 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+TXV | TM8E100C16MP11 | 36,000 | $1,800 |
| No | 208214574 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+TXV | TM9E080C20MP12 | 36,600 | $1,830 |
| No | 208214581 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+TXV | TP9C100C20MP13 | 36,200 | $1,810 |
| No | 208214578 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+TXV | TM9V100C20MP12 | 36,200 | $1,810 |
| No | 208502192 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+JMET18DS2N1+TXV | | 35,800 | $1,790 |
| No | 208400424 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+MVC20DN21+TXV | | 36,800 | $1,840 |
| No | 208614100 | CHAMPION HEATING AND COOLING | HMH72B601 | JHETD60JBCS2N1 | | 36,400 | $1,820 |
| No | 208501717 | CHAMPION HEATING AND COOLING | HMH72B601 | JHETD60JXXS2N1+TXV | | 36,400 | $1,820 |
| No | 207434727 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+ME20DN21+TXV | | 37,200 | $1,860 |
| No | 208214564 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+TXV | TMLE080C16MP11 | 36,000 | $1,800 |
| No | 208214575 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+TXV | TM8E080C16MP11 | 36,000 | $1,800 |
| No | 208214561 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+TXV | TMLE120C16MP11 | 36,000 | $1,800 |
| No | 208214566 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+TXV | TM8E120C16MP11 | 36,000 | $1,800 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208214571 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+TXV | TM9E120D20MP12 | 36,000 | $1,800 |
| No | 208214588 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+TXV | TM9Y100C20MP11 | 35,800 | $1,790 |
| No | 207416787 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TMLE100C20MP11 | 36,200 | $1,810 |
| No | 207416783 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TM8E100C20MP11 | 36,200 | $1,810 |
| No | 207416775 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TM8Y100C16MP11 | 36,600 | $1,830 |
| No | 207417347 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TM9E100C20MP12 | 37,000 | $1,850 |
| No | 207417317 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TP9C120D20MP13 | 37,400 | $1,870 |
| No | 207417313 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TM9V120D20MP12 | 37,400 | $1,870 |
| No | 208614103 | CHAMPION HEATING AND COOLING | HMH72B601 | JHVTD60JBCC2N1 | | 36,200 | $1,810 |
| No | 208501122 | CHAMPION HEATING AND COOLING | HMH72B601 | JHVTD60JXXC2N1+TXV | | 36,200 | $1,810 |
| No | 208400425 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+ME20DN21+TXV | | 36,600 | $1,830 |
| No | 208614102 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JBCN1+JMVT20DC2N1 | | 36,000 | $1,800 |
| No | 208500537 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+JMVT20DC2N1+TXV | | 36,000 | $1,800 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207416823 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TL8E080C16UH11 | 36,600 | $1,830 |
| No | 207416803 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TMLE080C20MP11 | 36,400 | $1,820 |
| No | 207416799 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TM8E080C20MP11 | 36,400 | $1,820 |
| No | 207417337 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TP9C100C16MP13 | 36,800 | $1,840 |
| No | 207417333 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TM9V100C16MP12 | 36,800 | $1,840 |
| No | 208214570 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+TXV | TL9E100C20UH11 | 36,000 | $1,800 |
| No | 208214563 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+TXV | TMLE100C20MP11 | 35,600 | $1,780 |
| No | 208214567 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+TXV | TM8E100C20MP11 | 35,600 | $1,780 |
| No | 208214586 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+TXV | TM8Y080C16MP11 | 35,800 | $1,790 |
| No | 208214584 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+TXV | TM8Y100C16MP11 | 35,800 | $1,790 |
| No | 208214573 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+TXV | TM9E100C20MP12 | 36,400 | $1,820 |
| No | 208214580 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+TXV | TP9C120D20MP13 | 36,200 | $1,810 |
| No | 208214579 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+TXV | TM9V120D20MP12 | 36,200 | $1,810 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207416819 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TL8E100C20UH11 | 36,600 | $1,830 |
| No | 207417351 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TM9E080C20MP12 | 37,200 | $1,860 |
| No | 208614101 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JBCN1+JMET18DS2N1 | | 36,400 | $1,820 |
| No | 208500548 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+JMET18DS2N1+TXV | | 36,400 | $1,820 |
| No | 207416815 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TL9E100C20UH11 | 36,600 | $1,830 |
| No | 207416779 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TM8Y080C16MP11 | 36,600 | $1,830 |
| No | 207417327 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TP9C100C20MP13 | 36,800 | $1,840 |
| No | 207417323 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TM9V100C20MP12 | 36,800 | $1,840 |
| No | 207434728 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+MVC20DN21+TXV | | 37,200 | $1,860 |
| No | 208501115 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+JMVT20DC2N1+TXV | | 35,400 | $1,770 |
| No | 207416795 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TMLE100C16MP11 | 36,800 | $1,840 |
| No | 207416791 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TM8E100C16MP11 | 36,800 | $1,840 |
| No | 207416767 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TM8Y120C20MP11 | 36,400 | $1,820 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417305 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TM9Y120D20MP11 | 36,600 | $1,830 |
| No | 208214572 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+TXV | TL8E080C16UH11 | 36,000 | $1,800 |
| No | 207416811 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TMLE080C16MP11 | 36,800 | $1,840 |
| No | 207416807 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TM8E080C16MP11 | 36,800 | $1,840 |
| No | 207417382 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TMLE120C16MP11 | 36,600 | $1,830 |
| No | 207417378 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TM8E120C16MP11 | 36,600 | $1,830 |
| No | 207416771 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TM8Y100C20MP11 | 36,400 | $1,820 |
| No | 207417343 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TM9E120D20MP12 | 37,200 | $1,860 |
| No | 207417309 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TM9Y100C20MP11 | 36,600 | $1,830 |
| No | 208214565 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+TXV | TMLE080C20MP11 | 35,600 | $1,780 |
| No | 208214569 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+TXV | TM8E080C20MP11 | 35,600 | $1,780 |
| No | 207417371 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TPLC120C20MP13 | 37,400 | $1,870 |
| No | 207417367 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TPLC100C20MP13 | 37,400 | $1,870 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417363 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TMLV120C20MP12 | 37,400 | $1,870 |
| No | 207417359 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TM8V100C20MP12 | 37,400 | $1,870 |
| No | 207417355 | CHAMPION HEATING AND COOLING | HMH72B601 | XAFD60JXXN1+TXV | TM8V120C20MP12 | 37,400 | $1,870 |
| No | 208214585 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+TXV | TM8Y100C20MP11 | 35,600 | $1,780 |
| No | 208214583 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+TXV | TM8Y120C20MP11 | 35,600 | $1,780 |
| No | 208214582 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+TXV | TP9C100C16MP13 | 36,200 | $1,810 |
| No | 208214577 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+TXV | TM9V100C16MP12 | 36,200 | $1,810 |
| No | 208214587 | CHAMPION HEATING AND COOLING | HMH72B601 | XAHD60JXXN1+TXV | TM9Y120D20MP11 | 35,800 | $1,790 |
| No | 207434718 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+ME12CN21+TXV | | 29,200 | $1,460 |
| No | 208400415 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHC60HXXN1+MVC12CN21+TXV | | 28,600 | $1,430 |
| No | 208400412 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHC60HXXN1+ME12CN21+TXV | | 28,600 | $1,430 |
| No | 207434720 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+MVC12CN21+TXV | | 28,800 | $1,440 |
| No | 207416763 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TL8E100C20UH11 | 29,800 | $1,490 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208614085 | CHAMPION HEATING AND COOLING | HMH72B481 | JHETD48GBCS2N1 | | 29,600 | $1,480 |
| No | 208501092 | CHAMPION HEATING AND COOLING | HMH72B481 | JHETC60HXXS2N1+TXV | | 29,600 | $1,480 |
| No | 207434719 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+ME14DN21+TXV | | 30,000 | $1,500 |
| No | 207417301 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TL8E080C16UH11 | 29,200 | $1,460 |
| No | 207417534 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TMLE080C16MP11 | 30,200 | $1,510 |
| No | 207417530 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TM8E080C16MP11 | 30,200 | $1,510 |
| No | 207416731 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TPLC100C16MP13 | 29,600 | $1,480 |
| No | 207416727 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TPLC080C16MP13 | 29,600 | $1,480 |
| No | 207416723 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TMLV100C16MP12 | 29,600 | $1,480 |
| No | 207416715 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TM8V100C16MP12 | 29,600 | $1,480 |
| No | 207416893 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TP9C100C20MP13 | 31,000 | $1,550 |
| No | 207416889 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TM9V100C20MP12 | 31,000 | $1,550 |
| No | 207417208 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TM9Y100C16MP11 | 30,200 | $1,510 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207416903 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TM8Y100C20MP11 | 29,800 | $1,490 |
| No | 207416899 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TM8Y120C20MP11 | 29,800 | $1,490 |
| No | 208400413 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHD60JXXN1+ME14DN21+TXV | | 28,800 | $1,440 |
| No | 207416911 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TL8E080C16UH11 | 30,200 | $1,510 |
| No | 208214416 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHD60JXXN1+TXV | TMLE080C16MP11 | 29,600 | $1,480 |
| No | 208214435 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHD60JXXN1+TXV | TM8E080C16MP11 | 29,600 | $1,480 |
| No | 207416915 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TM9Y100C16MP11 | 30,000 | $1,500 |
| No | 207417507 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TPLC120C20MP13 | 29,800 | $1,490 |
| No | 207417503 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TPLC100C20MP13 | 29,800 | $1,490 |
| No | 207417499 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TMLV120C20MP12 | 29,800 | $1,490 |
| No | 207417491 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TM8V120C20MP12 | 29,800 | $1,490 |
| No | 208614086 | CHAMPION HEATING AND COOLING | HMH72B481 | JHVTD60JBCC2N1 | | 29,800 | $1,490 |
| No | 208503463 | CHAMPION HEATING AND COOLING | HMH72B481 | JHVTD60JXXC2N1+TXV | | 29,800 | $1,490 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207416759 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TMLE080C16MP11 | 30,000 | $1,500 |
| No | 207416755 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TM8E080C16MP11 | 30,000 | $1,500 |
| No | 207416719 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TM8V080C16MP12 | 29,600 | $1,480 |
| No | 208214443 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHD60JXXN1+TXV | TPLC120C20MP13 | 28,800 | $1,440 |
| No | 208214440 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHD60JXXN1+TXV | TPLC100C20MP13 | 28,800 | $1,440 |
| No | 208214422 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHD60JXXN1+TXV | TMLV120C20MP12 | 28,800 | $1,440 |
| No | 208214430 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHD60JXXN1+TXV | TM8V120C20MP12 | 28,800 | $1,440 |
| No | 208214453 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHD60JXXN1+TXV | TP9C100C16MP13 | 30,400 | $1,520 |
| No | 208214447 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHD60JXXN1+TXV | TM9V100C16MP12 | 30,400 | $1,520 |
| No | 207417204 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TM9Y120D20MP11 | 30,600 | $1,530 |
| No | 208214414 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHD60JXXN1+TXV | TMLE120C16MP11 | 29,600 | $1,480 |
| No | 208214418 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHD60JXXN1+TXV | TM8E120C16MP11 | 29,600 | $1,480 |
| No | 207417262 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TPLC120C20MP13 | 29,200 | $1,460 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417258 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TPLC100C20MP13 | 29,200 | $1,460 |
| No | 207417254 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TMLV120C20MP12 | 29,200 | $1,460 |
| No | 207417246 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TM8V120C20MP12 | 29,200 | $1,460 |
| No | 207416695 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TP9C100C16MP13 | 30,800 | $1,540 |
| No | 207416691 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TM9V100C16MP12 | 30,800 | $1,540 |
| No | 207416677 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TM9Y080C16MP11 | 30,200 | $1,510 |
| No | 208400414 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHC60HXXN1+MVC16CN21+TXV | | 29,200 | $1,460 |
| No | 208614084 | CHAMPION HEATING AND COOLING | HMH72B481 | JHVTD42FBCC2N1 | | 29,800 | $1,490 |
| No | 208501159 | CHAMPION HEATING AND COOLING | HMH72B481 | JHVTC60HXXC2N1+TXV | | 29,800 | $1,490 |
| No | 207417293 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TL9E080C16UH11 | 29,600 | $1,480 |
| No | 208214427 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHD60JXXN1+TXV | TM8V100C20MP12 | 29,200 | $1,460 |
| No | 208214458 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHD60JXXN1+TXV | TM8Y080C16MP11 | 29,600 | $1,480 |
| No | 208214463 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHD60JXXN1+TXV | TM8Y100C16MP11 | 29,600 | $1,480 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207416705 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TP9C080C16MP13 | 30,600 | $1,530 |
| No | 207416701 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TM9V080C16MP12 | 30,600 | $1,530 |
| No | 208214457 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHD60JXXN1+TXV | TP9C120D20MP13 | 30,400 | $1,520 |
| No | 208214448 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHD60JXXN1+TXV | TM9V120D20MP12 | 30,400 | $1,520 |
| No | 207417485 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TP9C100C16MP13 | 31,000 | $1,550 |
| No | 207417481 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TM9V100C16MP12 | 31,000 | $1,550 |
| No | 207434715 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+ME16CN21+TXV | | 30,400 | $1,520 |
| No | 208214432 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHD60JXXN1+TXV | TL8E080C16UH11 | 29,600 | $1,480 |
| No | 207416751 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TMLE100C16MP11 | 30,000 | $1,500 |
| No | 207416747 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TM8E100C16MP11 | 30,000 | $1,500 |
| No | 207417285 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TPLC100C16MP13 | 29,400 | $1,470 |
| No | 207417281 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TPLC080C16MP13 | 29,400 | $1,470 |
| No | 207417277 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TMLV100C16MP12 | 29,400 | $1,470 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417273 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TM8V080C16MP12 | 29,400 | $1,470 |
| No | 207417269 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TM8V100C16MP12 | 29,400 | $1,470 |
| No | 207417226 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TM8Y100C20MP11 | 29,600 | $1,480 |
| No | 207417222 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TM8Y120C20MP11 | 29,600 | $1,480 |
| No | 207416685 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TP9C100C20MP13 | 31,000 | $1,550 |
| No | 207416681 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TM9V100C20MP12 | 31,000 | $1,550 |
| No | 208214470 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHD60JXXN1+TXV | TM9Y120D20MP11 | 30,000 | $1,500 |
| No | 207417526 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TMLE100C16MP11 | 30,200 | $1,510 |
| No | 207417522 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TM8E100C16MP11 | 30,200 | $1,510 |
| No | 207434716 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+MVC14DN21+TXV | | 29,800 | $1,490 |
| No | 207416907 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TL8E100C20UH11 | 30,000 | $1,500 |
| No | 207434717 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+MVC16CN21+TXV | | 29,800 | $1,490 |
| No | 207417518 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TMLE120C16MP11 | 30,200 | $1,510 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417514 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TM8E120C16MP11 | 30,200 | $1,510 |
| No | 208614087 | CHAMPION HEATING AND COOLING | HMH72B481 | JHETD60JBCS2N1 | | 30,000 | $1,500 |
| No | 208503494 | CHAMPION HEATING AND COOLING | HMH72B481 | JHETD60JXXS2N1+TXV | | 30,000 | $1,500 |
| No | 208400417 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHD60JXXN1+MVC14DN21+TXV | | 29,400 | $1,470 |
| No | 208214437 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHD60JXXN1+TXV | TL8E100C20UH11 | 29,400 | $1,470 |
| No | 208214415 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHD60JXXN1+TXV | TMLE100C16MP11 | 29,600 | $1,480 |
| No | 208214419 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHD60JXXN1+TXV | TM8E100C16MP11 | 29,600 | $1,480 |
| No | 207417250 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TM8V100C20MP12 | 29,600 | $1,480 |
| No | 207417242 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TM8Y080C16MP11 | 29,800 | $1,490 |
| No | 207417238 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TM8Y100C16MP11 | 29,800 | $1,490 |
| No | 208214460 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHD60JXXN1+TXV | TM8Y100C20MP11 | 29,200 | $1,460 |
| No | 208214465 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHD60JXXN1+TXV | TM8Y120C20MP11 | 29,200 | $1,460 |
| No | 208214454 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHD60JXXN1+TXV | TP9C100C20MP13 | 30,400 | $1,520 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208214449 | CHAMPION HEATING AND COOLING | HMH72B481 | XAHD60JXXN1+TXV | TM9V100C20MP12 | 30,400 | $1,520 |
| No | 207416743 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TMLE120C16MP11 | 30,000 | $1,500 |
| No | 207416739 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TM8E120C16MP11 | 30,000 | $1,500 |
| No | 207417495 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TM8V100C20MP12 | 29,800 | $1,490 |
| No | 207417234 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TM8Y080C16MP11 | 30,200 | $1,510 |
| No | 207417230 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TM8Y100C16MP11 | 30,200 | $1,510 |
| No | 207417216 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TP9C080C16MP13 | 30,600 | $1,530 |
| No | 207417212 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFC60HXXN1+TXV | TM9V080C16MP12 | 30,600 | $1,530 |
| No | 207416883 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TP9C120D20MP13 | 30,800 | $1,540 |
| No | 207416879 | CHAMPION HEATING AND COOLING | HMH72B481 | XAFD60JXXN1+TXV | TM9V120D20MP12 | 30,800 | $1,540 |
| No | 10309053 | CHAMPION HEATING AND COOLING | HL20B6021 | CM61DE4A1+MVC20DN21 | | 45,500 | $2,275 |
| No | 10525510 | CHAMPION HEATING AND COOLING | HL20B2421 | CM25BE1A1 | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 10525512 | CHAMPION HEATING AND COOLING | HL20B2421 | CM25BE1A1 | TM9V080B12MP12 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10525511 | CHAMPION HEATING AND COOLING | HL20B2421 | CM25BE1A1 | TM9V060B12MP12 | 21,200 | $1,060 |
| No | 10525513 | CHAMPION HEATING AND COOLING | HL20B2421 | CM25BE1A1 | TMLV080B12MP12 | 22,400 | $1,120 |
| No | 10525517 | CHAMPION HEATING AND COOLING | HL20B2421 | CM25BE1A1 | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 10525514 | CHAMPION HEATING AND COOLING | HL20B2421 | CM25BE1A1 | TP9C060B12MP13 | 21,200 | $1,060 |
| No | 10525515 | CHAMPION HEATING AND COOLING | HL20B2421 | CM25BE1A1 | TP9C080B12MP13 | 22,400 | $1,120 |
| No | 10525534 | CHAMPION HEATING AND COOLING | HL20B4821 | CM50CE3A1 | TM9V100C16MP12 | 44,000 | $2,200 |
| No | 10525541 | CHAMPION HEATING AND COOLING | HL20B4821 | CM50CE3A1 | TP9C100C16MP13 | 44,000 | $2,200 |
| No | 201982915 | CHAMPION HEATING AND COOLING | HL20B2421 | AVV25BE121 | | 22,400 | $1,120 |
| No | 201982951 | CHAMPION HEATING AND COOLING | HL20B6021 | AVV61DE421 | | 46,000 | $2,300 |
| No | 201982925 | CHAMPION HEATING AND COOLING | HL20B3621S | CM37BE2A1+CC | TM9V060B12MP12 | 31,600 | $1,580 |
| No | 201982930 | CHAMPION HEATING AND COOLING | HL20B3621S | CM37BE2A1+CC | TM9V080B12MP12 | 31,000 | $1,550 |
| No | 201982933 | CHAMPION HEATING AND COOLING | HL20B3621S | CM37BE2A1+CC | TP9C060B12MP13 | 31,600 | $1,580 |
| No | 201982938 | CHAMPION HEATING AND COOLING | HL20B3621S | CM37BE2A1+CC | TP9C080B12MP13 | 31,000 | $1,550 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201982945 | CHAMPION HEATING AND COOLING | HL20B3621S | CM37BE2A1+MVC12BN21+CC | | 30,800 | $1,540 |
| No | 10309057 | CHAMPION HEATING AND COOLING | HL20B6021S | AVV61CE421+CC | | 46,000 | $2,300 |
| No | 10525549 | CHAMPION HEATING AND COOLING | HL20B6021S | CM61CE4A1+CC | TM8V100C20MP12 | 46,000 | $2,300 |
| No | 10525550 | CHAMPION HEATING AND COOLING | HL20B6021S | CM61CE4A1+CC | TM8V120C20MP12 | 46,000 | $2,300 |
| No | 10525551 | CHAMPION HEATING AND COOLING | HL20B6021S | CM61CE4A1+CC | TM9V100C20MP12 | 46,500 | $2,325 |
| No | 10525552 | CHAMPION HEATING AND COOLING | HL20B6021S | CM61CE4A1+CC | TMLV100C20MP12 | 46,000 | $2,300 |
| No | 10525553 | CHAMPION HEATING AND COOLING | HL20B6021S | CM61CE4A1+CC | TMLV120C20MP12 | 46,000 | $2,300 |
| No | 10525554 | CHAMPION HEATING AND COOLING | HL20B6021S | CM61CE4A1+CC | TP9C100C20MP13 | 46,500 | $2,325 |
| No | 10525555 | CHAMPION HEATING AND COOLING | HL20B6021S | CM61CE4A1+CC | TPLC100C20MP13 | 46,000 | $2,300 |
| No | 10525556 | CHAMPION HEATING AND COOLING | HL20B6021S | CM61CE4A1+CC | TPLC120C20MP13 | 46,000 | $2,300 |
| No | 10525558 | CHAMPION HEATING AND COOLING | HL20B6021S | CM61DE4A1+CC | TP9C120D20MP13 | 46,000 | $2,300 |
| No | 201982921 | CHAMPION HEATING AND COOLING | HL20B3621S | AVV37BE221+CC | | 31,000 | $1,550 |
| No | 10525557 | CHAMPION HEATING AND COOLING | HL20B6021S | CM61DE4A1+CC | TM9V120D20MP12 | 46,000 | $2,300 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205537305 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36BXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203430832 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203430827 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205538527 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205538519 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36BXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205538511 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203087049 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203087066 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205538493 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205538485 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205544337 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36BXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 203088193 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BBCA1 | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205544331 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203088174 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BBCA1 | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205544319 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205544310 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 203088139 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205544300 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205544291 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205544283 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42BXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205544274 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TL9E080C16UH11 | 22,400 | $1,120 |
| No | 205544264 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TL9E080C16UH11 | 22,400 | $1,120 |
| No | 205544251 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 203087842 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 203087824 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205544238 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205544225 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 203087787 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205544196 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205544186 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205544165 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36AXA1+TXV | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 205544158 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36AXA1+TXV | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 205544154 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36AXA1+TXV | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 205544176 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205544150 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36AXA1+TXV | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 206781240 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36BXA1+TXV | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 203430992 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BBCA1 | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 206781244 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BXA1+TXV | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 203430987 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BBCA1 | TMLE060A12MP11 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781236 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36BXA1+TXV | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 203087619 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BBCA1 | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 206781232 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BXA1+TXV | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 203087600 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BBCA1 | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 206781228 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BXA1+TXV | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 206781224 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BXA1+TXV | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 205544146 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42BXA1+TXV | TMLE060A12MP11 | 22,800 | $1,140 |
| No | 205544142 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42BXA1+TXV | TM8E060A12MP11 | 22,800 | $1,140 |
| No | 206781220 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36BXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 203430965 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BBCA1 | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 206781216 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 203430959 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BBCA1 | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 206781212 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36BXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203087522 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BBCA1 | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 206781208 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 203087503 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BBCA1 | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 206781196 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 206781192 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 206781188 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203430893 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 206781204 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 206781200 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 203087277 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 206781184 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 206781176 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 206781180 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205544138 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203430882 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205544215 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203430876 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205544205 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 203087240 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205544134 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 203087221 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205544120 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 206781172 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205544107 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 206781168 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 206781164 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781160 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205544095 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203430860 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205544130 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205544088 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 203430854 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203087159 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205544077 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 203087141 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205544067 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205544057 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 206781156 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203430793 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781152 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203430788 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 206781148 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203086935 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 206781144 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203086917 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 206781140 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 206781136 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205544045 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203430777 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205544034 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203430771 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205544023 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203086878 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205544009 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203086860 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205543965 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205543952 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205543934 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 203430760 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205543980 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205543996 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 203086818 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205543913 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205543897 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205543878 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205543887 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203430749 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205543867 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 203430744 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205543855 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203086774 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205543845 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203086755 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205543822 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205543812 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 206781128 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206781124 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781120 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781116 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781112 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206781132 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 203430667 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 203430661 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206781108 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 203098236 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781104 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781100 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 203098228 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781096 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 203430650 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206781092 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781088 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 203098212 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781084 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781080 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781076 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 205543794 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36AXA1+TXV | TPLC060A12MP13 | 22,400 | $1,120 |
| No | 205543782 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36AXA1+TXV | TMLV060A12MP12 | 22,400 | $1,120 |
| No | 206781072 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 205543774 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36AXA1+TXV | TM8V060A12MP12 | 22,400 | $1,120 |
| No | 205543759 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36AXA1+TXV | TPLC060A12MP13 | 22,400 | $1,120 |
| No | 205543745 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36AXA1+TXV | TMLV060A12MP12 | 22,400 | $1,120 |
| No | 205543734 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36AXA1+TXV | TM8V060A12MP12 | 22,400 | $1,120 |
| No | 205543724 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36AXA1+TXV | TM9E060A10MP12 | 22,600 | $1,130 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205543713 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36AXA1+TXV | TM9E060A10MP12 | 22,600 | $1,130 |
| No | 206781068 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42BXA1+TXV | TM9E060B12MP12 | 22,200 | $1,110 |
| No | 205543703 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 203097866 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205543834 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 203097858 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205543693 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 206781064 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 203097842 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 206781060 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 203097834 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 206781056 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205543682 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36BXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203097818 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205543673 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097810 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205543662 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097715 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 205543624 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 205543608 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 205543650 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 206781052 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 203097699 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 206781048 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 203097691 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 206781044 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205543596 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 205543589 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 206781040 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 206781036 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 203097659 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 206781032 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 203097667 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 203097555 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205543572 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205543582 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205543563 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 206781028 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42BXA1+TXV | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 203097458 | CHAMPION HEATING AND COOLING | TH16B3622 | AE36CX21+TXV | | 22,600 | $1,130 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205543551 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+ME14DN21+TXV | | 22,000 | $1,100 |
| No | 205543544 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+ME14DN21+TXV | | 22,000 | $1,100 |
| No | 205543517 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205543536 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205543497 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TM9Y080C16MP11 | 22,600 | $1,130 |
| No | 203096964 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TM9Y080C16MP11 | 22,600 | $1,130 |
| No | 205543637 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TM9Y080C16MP11 | 22,600 | $1,130 |
| No | 203096948 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TM9Y080C16MP11 | 22,600 | $1,130 |
| No | 205543469 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TM9Y080C16MP11 | 22,600 | $1,130 |
| No | 203096916 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205543422 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205543394 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205543438 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205543380 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TM9Y120D20MP11 | 22,400 | $1,120 |
| No | 205543363 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TM9Y120D20MP11 | 22,400 | $1,120 |
| No | 205543329 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205543320 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205543311 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205543288 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205543276 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205543249 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205543236 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205543223 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205543199 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205543189 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203096750 | CHAMPION HEATING AND COOLING | TH16B3622 | AVC48CX21+TXV | | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205543171 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+ME14DN21+TXV | | 22,000 | $1,100 |
| No | 205543161 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+ME14DN21+TXV | | 22,000 | $1,100 |
| No | 203096703 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1+ME14DN21 | | 22,000 | $1,100 |
| No | 203096670 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1+MVC16CN21 | | 22,000 | $1,100 |
| No | 205543153 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+MVC16CN21+TXV | | 22,000 | $1,100 |
| No | 205543145 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+MVC16CN21+TXV | | 22,000 | $1,100 |
| No | 203096654 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1+MVC16CN21 | | 21,800 | $1,090 |
| No | 205543136 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+MVC16CN21+TXV | | 21,800 | $1,090 |
| No | 203096646 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1+MVC16CN21 | | 21,800 | $1,090 |
| No | 205543128 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+MVC16CN21+TXV | | 21,800 | $1,090 |
| No | 205543109 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36BXA1+TXV | TPLC060A12MP13 | 22,200 | $1,110 |
| No | 203096543 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BBCA1 | TPLC060A12MP13 | 22,200 | $1,110 |
| No | 205543091 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BXA1+TXV | TPLC060A12MP13 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203096514 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BBCA1 | TPLC060A12MP13 | 22,200 | $1,110 |
| No | 205543081 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36BXA1+TXV | TMLV060A12MP12 | 22,200 | $1,110 |
| No | 203096535 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BBCA1 | TMLV060A12MP12 | 22,200 | $1,110 |
| No | 205543072 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BXA1+TXV | TMLV060A12MP12 | 22,200 | $1,110 |
| No | 203096506 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BBCA1 | TMLV060A12MP12 | 22,200 | $1,110 |
| No | 205543061 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36BXA1+TXV | TM8V060A12MP12 | 22,200 | $1,110 |
| No | 203096527 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BBCA1 | TM8V060A12MP12 | 22,200 | $1,110 |
| No | 205543045 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BXA1+TXV | TM8V060A12MP12 | 22,200 | $1,110 |
| No | 203096498 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BBCA1 | TM8V060A12MP12 | 22,200 | $1,110 |
| No | 205543004 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BXA1+TXV | TPLC060A12MP13 | 22,200 | $1,110 |
| No | 205542994 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BXA1+TXV | TMLV060A12MP12 | 22,200 | $1,110 |
| No | 205542982 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BXA1+TXV | TM8V060A12MP12 | 22,200 | $1,110 |
| No | 203096155 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BBCA1 | TP9C060B12MP13 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781016 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BXA1+TXV | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 206781020 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36BXA1+TXV | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 203096135 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BBCA1 | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 206781012 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36BXA1+TXV | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 203096147 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BBCA1 | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 206781008 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BXA1+TXV | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 203096127 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BBCA1 | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 206781002 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BXA1+TXV | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 206780998 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BXA1+TXV | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 205542966 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42BXA1+TXV | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 205542956 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42BXA1+TXV | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 203095801 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 205543032 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205543020 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 203095793 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 205542945 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 205542930 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 205542910 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 205542900 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 203095765 | CHAMPION HEATING AND COOLING | TH16B3622 | AVC36BX21+TXV | | 22,200 | $1,110 |
| No | 203095757 | CHAMPION HEATING AND COOLING | TH16B3622 | AVC36CX21+TXV | | 22,200 | $1,110 |
| No | 203095742 | CHAMPION HEATING AND COOLING | TH16B3622 | AVC48DX21+TXV | | 22,200 | $1,110 |
| No | 205542867 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203095335 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205542858 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203095278 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205542849 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 203095327 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205542841 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 203095271 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205542832 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203095318 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205542822 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203095263 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205542790 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205542775 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203095247 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203095302 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205542762 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203095294 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205542752 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203095239 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205542731 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205542721 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205542706 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205542675 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205542660 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 206780986 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203095000 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 206780982 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203094943 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 206780978 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203094991 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 206780974 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 206780970 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203094983 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203094936 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 206780966 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203094927 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 206780962 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203094967 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 206780958 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203094912 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 206780954 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203094959 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780950 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203094904 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 206780938 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 206780934 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 206780930 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 206780926 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 206780922 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 206780916 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TPLC120C20MP13 | 22,200 | $1,110 |
| No | 203093765 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TPLC120C20MP13 | 22,200 | $1,110 |
| No | 206780912 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TPLC120C20MP13 | 22,200 | $1,110 |
| No | 203093708 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TPLC120C20MP13 | 22,200 | $1,110 |
| No | 206780908 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TPLC100C20MP13 | 22,200 | $1,110 |
| No | 203093757 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TPLC100C20MP13 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780904 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TPLC100C20MP13 | 22,200 | $1,110 |
| No | 203093700 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TPLC100C20MP13 | 22,200 | $1,110 |
| No | 206780900 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TMLV120C20MP12 | 22,200 | $1,110 |
| No | 203093749 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TMLV120C20MP12 | 22,200 | $1,110 |
| No | 203093692 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TMLV120C20MP12 | 22,200 | $1,110 |
| No | 206780896 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TMLV120C20MP12 | 22,200 | $1,110 |
| No | 206780892 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TM8V100C20MP12 | 22,200 | $1,110 |
| No | 203093733 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TM8V100C20MP12 | 22,200 | $1,110 |
| No | 203093676 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TM8V100C20MP12 | 22,200 | $1,110 |
| No | 206780888 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TM8V100C20MP12 | 22,200 | $1,110 |
| No | 203093725 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TM8V120C20MP12 | 22,200 | $1,110 |
| No | 206780884 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TM8V120C20MP12 | 22,200 | $1,110 |
| No | 206780880 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TM8V120C20MP12 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203093668 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TM8V120C20MP12 | 22,200 | $1,110 |
| No | 206780873 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TPLC120C20MP13 | 22,200 | $1,110 |
| No | 206780869 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TPLC100C20MP13 | 22,200 | $1,110 |
| No | 206780865 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TMLV120C20MP12 | 22,200 | $1,110 |
| No | 206780861 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TM8V100C20MP12 | 22,200 | $1,110 |
| No | 206780857 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TM8V120C20MP12 | 22,200 | $1,110 |
| No | 203093374 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205542614 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205542597 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 203093355 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205542581 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205542571 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 203093336 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TMLV120C20MP12 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205542555 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 203093300 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205542538 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205542501 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205542488 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205542304 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 203093282 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205542291 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205542251 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205542265 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205542242 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205542219 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205542215 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205542206 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36AXA1+TXV | TM8Y060A12MP11 | 22,200 | $1,110 |
| No | 205542169 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36AXA1+TXV | TM8Y060A12MP11 | 22,200 | $1,110 |
| No | 205542135 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 203092903 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205542480 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205542469 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203092885 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205542458 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205542116 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205542109 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205542061 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 203092231 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205542318 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203092125 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205542051 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203092212 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205542040 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203092108 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205541950 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205541940 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203091914 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205541884 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205541873 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 203091896 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205541862 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205541850 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205541679 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205541667 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 206780849 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36BXA1+TXV | TM9Y080B12MP11 | 22,200 | $1,110 |
| No | 203808681 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BBCA1 | TM9Y080B12MP11 | 22,200 | $1,110 |
| No | 206780853 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BXA1+TXV | TM9Y080B12MP11 | 22,200 | $1,110 |
| No | 203808675 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BBCA1 | TM9Y080B12MP11 | 22,200 | $1,110 |
| No | 206780845 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BXA1+TXV | TM9Y080B12MP11 | 22,200 | $1,110 |
| No | 205541610 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205541598 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205541587 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205541575 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205541763 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205541744 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205541725 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 206780839 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36BXA1+TXV | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 203091040 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BBCA1 | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 206780805 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BXA1+TXV | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 206780801 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36BXA1+TXV | TM9V080B12MP12 | 22,200 | $1,110 |
| No | 203090994 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BBCA1 | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 203091022 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BBCA1 | TM9V080B12MP12 | 22,200 | $1,110 |
| No | 206780797 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BXA1+TXV | TM9V080B12MP12 | 22,200 | $1,110 |
| No | 203090975 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BBCA1 | TM9V080B12MP12 | 22,200 | $1,110 |
| No | 206780791 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BXA1+TXV | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 206780787 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BXA1+TXV | TM9V080B12MP12 | 22,200 | $1,110 |
| No | 205541548 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TP9C100C16MP13 | 22,000 | $1,100 |
| No | 203090630 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TP9C100C16MP13 | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205541535 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TP9C100C16MP13 | 22,000 | $1,100 |
| No | 205541524 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TM9V100C16MP12 | 22,000 | $1,100 |
| No | 203090614 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TM9V100C16MP12 | 22,000 | $1,100 |
| No | 205541513 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TM9V100C16MP12 | 22,000 | $1,100 |
| No | 205541484 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TM9V100C16MP12 | 22,000 | $1,100 |
| No | 205541495 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TP9C100C16MP13 | 22,000 | $1,100 |
| No | 205541458 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 203090404 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205541447 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 203090360 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205541435 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 203090387 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205541423 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203090341 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205541407 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205541395 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205541365 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205541348 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205541338 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205541377 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205541324 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541312 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205541291 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541281 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205541259 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 203089082 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205541248 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 203089035 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541237 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203089063 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205541226 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203089017 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205541210 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541199 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203088852 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541173 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541160 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 203088832 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205541134 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205541120 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205541102 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541086 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205144648 | CHAMPION HEATING AND COOLING | TH16B3622 | AE42CBC21 | | 22,400 | $1,120 |
| No | 203088411 | CHAMPION HEATING AND COOLING | TH16B3622 | AE42CX21+TXV | | 22,400 | $1,120 |
| No | 205537141 | CHAMPION HEATING AND COOLING | TH16B2421 | CU24AXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |
| No | 205537133 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24ABAA1 | TL8E060A12UH11 | 15,200 | $760 |
| No | 205537124 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24AXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |
| No | 205537118 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24ABAA1 | TL8E060A12UH11 | 15,200 | $760 |
| No | 205537110 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24AXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |
| No | 206782446 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 206782442 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 206782438 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782434 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 206782430 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 205085349 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60CXA2+TXV | TL8E080C16UH11 | 27,800 | $1,390 |
| No | 205085343 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60CXA2+TXV | TL8E080C16UH11 | 27,800 | $1,390 |
| No | 205085336 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60CXA2+TXV | TL8E080C16UH11 | 27,800 | $1,390 |
| No | 206782474 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TL8E080C16UH11 | 29,600 | $1,480 |
| No | 206782470 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TL8E080C16UH11 | 29,600 | $1,480 |
| No | 205085314 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60CXA2+TXV | TL8E100C20UH11 | 27,600 | $1,380 |
| No | 205085308 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60CXA2+TXV | TL8E100C20UH11 | 27,600 | $1,380 |
| No | 205085302 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60CXA2+TXV | TL8E100C20UH11 | 27,600 | $1,380 |
| No | 205085290 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60DXA2+TXV | TL8E100C20UH11 | 27,800 | $1,390 |
| No | 205085296 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60DXA2+TXV | TL8E100C20UH11 | 27,800 | $1,390 |
| No | 205085283 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60DXA2+TXV | TL8E100C20UH11 | 27,800 | $1,390 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205537103 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205537093 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205537084 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205537075 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205537057 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TL9E080C16UH11 | 29,600 | $1,480 |
| No | 205085247 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60CXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205537068 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TL9E080C16UH11 | 29,600 | $1,480 |
| No | 205085241 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60CXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205085236 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60CXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205085231 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60DXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205085225 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60DXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205085219 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60DXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205085148 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60CXA2+TXV | TMLE080C20MP11 | 27,400 | $1,370 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205085142 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60CXA2+TXV | TMLE080C20MP11 | 27,400 | $1,370 |
| No | 205085136 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60CXA2+TXV | TM8E080C20MP11 | 27,400 | $1,370 |
| No | 205085131 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60CXA2+TXV | TM8E080C20MP11 | 27,400 | $1,370 |
| No | 205085125 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60CXA2+TXV | TMLE080C20MP11 | 27,400 | $1,370 |
| No | 205085120 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60CXA2+TXV | TM8E080C20MP11 | 27,400 | $1,370 |
| No | 205085115 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60DXA2+TXV | TMLE080C20MP11 | 27,600 | $1,380 |
| No | 205085109 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60DXA2+TXV | TMLE080C20MP11 | 27,600 | $1,380 |
| No | 205085104 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60DXA2+TXV | TM8E080C20MP11 | 27,600 | $1,380 |
| No | 205085099 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60DXA2+TXV | TM8E080C20MP11 | 27,600 | $1,380 |
| No | 205085093 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60DXA2+TXV | TMLE080C20MP11 | 27,600 | $1,380 |
| No | 205085088 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60DXA2+TXV | TM8E080C20MP11 | 27,600 | $1,380 |
| No | 206782426 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 203431141 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TMLE120C16MP11 | 28,000 | $1,400 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782422 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 203431130 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 206782418 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 203431135 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 206782414 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 203431124 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 206782410 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 206782406 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 205084916 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60DXA2+TXV | TMLE120C16MP11 | 27,800 | $1,390 |
| No | 205084911 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60DXA2+TXV | TMLE120C16MP11 | 27,800 | $1,390 |
| No | 205084905 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60DXA2+TXV | TM8E120C16MP11 | 27,800 | $1,390 |
| No | 205084900 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60DXA2+TXV | TM8E120C16MP11 | 27,800 | $1,390 |
| No | 205084895 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60DXA2+TXV | TMLE120C16MP11 | 27,800 | $1,390 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205084889 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60DXA2+TXV | TM8E120C16MP11 | 27,800 | $1,390 |
| No | 206782402 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TMLE120C16MP11 | 30,400 | $1,520 |
| No | 206782398 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TM8E120C16MP11 | 30,400 | $1,520 |
| No | 206782394 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TMLE120C16MP11 | 30,400 | $1,520 |
| No | 206782390 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TM8E120C16MP11 | 30,400 | $1,520 |
| No | 205084815 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60DXA2+TXV | TMLE130D20MP11 | 27,800 | $1,390 |
| No | 205084810 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60DXA2+TXV | TMLE130D20MP11 | 27,800 | $1,390 |
| No | 205084798 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60DXA2+TXV | TM8E130D20MP11 | 27,800 | $1,390 |
| No | 205084804 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60DXA2+TXV | TM8E130D20MP11 | 27,800 | $1,390 |
| No | 205084792 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60DXA2+TXV | TMLE130D20MP11 | 27,800 | $1,390 |
| No | 205084787 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60DXA2+TXV | TM8E130D20MP11 | 27,800 | $1,390 |
| No | 205536891 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TM9E080B12MP12 | 28,600 | $1,430 |
| No | 205536882 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TM9E080B12MP12 | 28,600 | $1,430 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205536865 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TM9E080B12MP12 | 28,600 | $1,430 |
| No | 205536858 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TM9E080B12MP12 | 28,600 | $1,430 |
| No | 205536873 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TM9E080B12MP12 | 28,600 | $1,430 |
| No | 206782386 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 206782382 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 206782378 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 206782374 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 206782370 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 205536846 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TM9E080C16MP12 | 28,800 | $1,440 |
| No | 205536836 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TM9E080C16MP12 | 28,800 | $1,440 |
| No | 205536821 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205536814 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205536829 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205536805 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205536796 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205084676 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60DXA2+TXV | TM9E100C20MP12 | 27,400 | $1,370 |
| No | 205084672 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60DXA2+TXV | TM9E100C20MP12 | 27,400 | $1,370 |
| No | 205084668 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60DXA2+TXV | TM9E100C20MP12 | 27,400 | $1,370 |
| No | 205084663 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60DXA2+TXV | TM9E120D20MP12 | 27,800 | $1,390 |
| No | 205084659 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60DXA2+TXV | TM9E120D20MP12 | 27,800 | $1,390 |
| No | 205084655 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60DXA2+TXV | TM9E120D20MP12 | 27,800 | $1,390 |
| No | 206783057 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TL8E080C16UH11 | 33,000 | $1,650 |
| No | 206783053 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TL8E080C16UH11 | 33,000 | $1,650 |
| No | 205536787 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TL9E080C16UH11 | 32,600 | $1,630 |
| No | 205536778 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TL9E080C16UH11 | 32,600 | $1,630 |
| No | 206783045 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TMLE080C16MP11 | 33,000 | $1,650 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206783041 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TM8E080C16MP11 | 33,000 | $1,650 |
| No | 206783037 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TMLE080C16MP11 | 33,000 | $1,650 |
| No | 206783033 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TM8E080C16MP11 | 33,000 | $1,650 |
| No | 206783029 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TMLE100C16MP11 | 33,000 | $1,650 |
| No | 206783025 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TM8E100C16MP11 | 33,000 | $1,650 |
| No | 206783021 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TMLE100C16MP11 | 33,000 | $1,650 |
| No | 206783013 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TMLE100C20MP11 | 32,600 | $1,630 |
| No | 206783017 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TM8E100C16MP11 | 33,000 | $1,650 |
| No | 206783009 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TM8E100C20MP11 | 32,600 | $1,630 |
| No | 206783005 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TMLE100C20MP11 | 32,600 | $1,630 |
| No | 206783001 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TM8E100C20MP11 | 32,600 | $1,630 |
| No | 206782981 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TMLE120C20MP11 | 32,600 | $1,630 |
| No | 206782977 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TM8E120C20MP11 | 32,600 | $1,630 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782973 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TMLE120C20MP11 | 32,600 | $1,630 |
| No | 206782969 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TM8E120C20MP11 | 32,600 | $1,630 |
| No | 205536769 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TMLE130D20MP11 | 32,800 | $1,640 |
| No | 205536760 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TM8E130D20MP11 | 32,800 | $1,640 |
| No | 205536752 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TMLE130D20MP11 | 32,800 | $1,640 |
| No | 205536743 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TM8E130D20MP11 | 32,800 | $1,640 |
| No | 206779796 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BBAA1+MVC12BN21 | | 14,900 | $745 |
| No | 206779792 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BXA1+MVC12BN21+TXV | | 14,900 | $745 |
| No | 202101791 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BBAA1+MVC12BN21 | | 14,900 | $745 |
| No | 206779788 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BXA1+MVC12BN21+TXV | | 14,900 | $745 |
| No | 206780122 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BBAA1+MVC12BN21 | | 15,300 | $765 |
| No | 206780114 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BBAA1+MVC12BN21 | | 15,300 | $765 |
| No | 206780118 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BXA1+MVC12BN21+TXV | | 15,300 | $765 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780110 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BXA1+MVC12BN21+TXV | | 15,300 | $765 |
| No | 206779804 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30CXA1+MVC16CN21+TXV | | 14,800 | $740 |
| No | 206779800 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30CXA1+MVC16CN21+TXV | | 14,800 | $740 |
| No | 206780090 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36CXA1+MVC16CN21+TXV | | 15,300 | $765 |
| No | 206780086 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36CXA1+MVC16CN21+TXV | | 15,300 | $765 |
| No | 206779756 | CHAMPION HEATING AND COOLING | TH16B2421 | CU24AXA1+TXV | TPLC060A12MP13 | 15,000 | $750 |
| No | 206779752 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24ABAA1 | TPLC060A12MP13 | 15,000 | $750 |
| No | 206779748 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24AXA1+TXV | TPLC060A12MP13 | 15,000 | $750 |
| No | 202102010 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24ABAA1 | TPLC060A12MP13 | 15,000 | $750 |
| No | 206779768 | CHAMPION HEATING AND COOLING | TH16B2421 | CU24AXA1+TXV | TMLV060A12MP12 | 15,000 | $750 |
| No | 206779764 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24ABAA1 | TMLV060A12MP12 | 15,000 | $750 |
| No | 206779760 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24AXA1+TXV | TMLV060A12MP12 | 15,000 | $750 |
| No | 202102006 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24ABAA1 | TMLV060A12MP12 | 15,000 | $750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206779744 | CHAMPION HEATING AND COOLING | TH16B2421 | CU24AXA1+TXV | TM8V060A12MP12 | 15,000 | $750 |
| No | 206779740 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24ABAA1 | TM8V060A12MP12 | 15,000 | $750 |
| No | 206779736 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24AXA1+TXV | TM8V060A12MP12 | 15,000 | $750 |
| No | 202102004 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24ABAA1 | TM8V060A12MP12 | 15,000 | $750 |
| No | 206779732 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24AXA1+TXV | TPLC060A12MP13 | 15,000 | $750 |
| No | 206779728 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24AXA1+TXV | TMLV060A12MP12 | 15,000 | $750 |
| No | 206779724 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24AXA1+TXV | TM8V060A12MP12 | 15,000 | $750 |
| No | 206780644 | CHAMPION HEATING AND COOLING | TH16B2421 | CU30BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780640 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BBAA1 | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780636 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780632 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BBAA1 | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780628 | CHAMPION HEATING AND COOLING | TH16B2421 | CU30BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780624 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BBAA1 | TM8V080B12MP12 | 15,000 | $750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780620 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780616 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BBAA1 | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780611 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780607 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780170 | CHAMPION HEATING AND COOLING | TH16B2421 | CU24BXA1+TXV | TM9Y060B12MP11 | 14,900 | $745 |
| No | 206780166 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BBAA1 | TM9Y060B12MP11 | 14,900 | $745 |
| No | 206780162 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BXA1+TXV | TM9Y060B12MP11 | 14,900 | $745 |
| No | 202143776 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BBAA1 | TM9Y060B12MP11 | 14,900 | $745 |
| No | 206780178 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BXA1+TXV | TM9Y060B12MP11 | 14,900 | $745 |
| No | 206780158 | CHAMPION HEATING AND COOLING | TH16B2421 | CU24AXA1+TXV | TM9V040A10MP12 | 15,200 | $760 |
| No | 206780154 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24ABAA1 | TM9V040A10MP12 | 15,200 | $760 |
| No | 206780150 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24AXA1+TXV | TM9V040A10MP12 | 15,200 | $760 |
| No | 202143768 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24ABAA1 | TM9V040A10MP12 | 15,200 | $760 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780174 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24AXA1+TXV | TM9V040A10MP12 | 15,200 | $760 |
| No | 206779984 | CHAMPION HEATING AND COOLING | TH16B2421 | CU36BXA1+TXV | TP9C060B12MP13 | 14,900 | $745 |
| No | 206779980 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BBAA1 | TP9C060B12MP13 | 14,900 | $745 |
| No | 206779976 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BXA1+TXV | TP9C060B12MP13 | 14,900 | $745 |
| No | 206779972 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BBAA1 | TP9C060B12MP13 | 14,900 | $745 |
| No | 206779968 | CHAMPION HEATING AND COOLING | TH16B2421 | CU36BXA1+TXV | TM9V060B12MP12 | 14,900 | $745 |
| No | 206779956 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BBAA1 | TM9V060B12MP12 | 14,900 | $745 |
| No | 206782622 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TP9C100C20MP13 | 33,000 | $1,650 |
| No | 206779960 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BXA1+TXV | TM9V060B12MP12 | 14,900 | $745 |
| No | 206779964 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BBAA1 | TM9V060B12MP12 | 14,900 | $745 |
| No | 206779950 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BXA1+TXV | TP9C060B12MP13 | 14,900 | $745 |
| No | 206779946 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BXA1+TXV | TM9V060B12MP12 | 14,900 | $745 |
| No | 206782618 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TM9V100C20MP12 | 33,000 | $1,650 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782612 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TP9C100C20MP13 | 33,000 | $1,650 |
| No | 206782608 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TM9V100C20MP12 | 33,000 | $1,650 |
| No | 205539555 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TP9C120D20MP13 | 32,600 | $1,630 |
| No | 205539550 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TM9V120D20MP12 | 32,600 | $1,630 |
| No | 205539538 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TP9C120D20MP13 | 32,600 | $1,630 |
| No | 205539529 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TM9V120D20MP12 | 32,600 | $1,630 |
| No | 9036784 | CHAMPION HEATING AND COOLING | TH16B4821 | AVC48CX21+TXV | | 27,600 | $1,380 |
| No | 206781532 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1+MVC16CN21 | | 28,000 | $1,400 |
| No | 206781528 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+MVC16CN21+TXV | | 28,000 | $1,400 |
| No | 202100055 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1+MVC16CN21 | | 28,000 | $1,400 |
| No | 206781774 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+MVC16CN21+TXV | | 28,000 | $1,400 |
| No | 206782363 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TPLC080B12MP13 | 28,200 | $1,410 |
| No | 206782359 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TPLC080B12MP13 | 28,200 | $1,410 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782355 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TPLC080B12MP13 | 28,200 | $1,410 |
| No | 202100736 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TPLC080B12MP13 | 28,200 | $1,410 |
| No | 206782351 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TM8V080B12MP12 | 28,200 | $1,410 |
| No | 206782347 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TM8V080B12MP12 | 28,200 | $1,410 |
| No | 206782343 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TM8V080B12MP12 | 28,200 | $1,410 |
| No | 202100657 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TM8V080B12MP12 | 28,200 | $1,410 |
| No | 206782338 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TPLC080B12MP13 | 28,200 | $1,410 |
| No | 206782334 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TM8V080B12MP12 | 28,200 | $1,410 |
| No | 206782318 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782310 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782314 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 202100744 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782306 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782302 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782298 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 202100739 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782294 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782290 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782286 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 202100704 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782282 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782278 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782274 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 202100658 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782270 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782266 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TM8V100C16MP12 | 28,000 | $1,400 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782262 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 202100665 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782168 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782164 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782160 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782152 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782156 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782136 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782132 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782128 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782124 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782120 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782116 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782112 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782108 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782104 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782100 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782096 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782092 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782088 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782084 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782080 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782072 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782068 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782064 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782060 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782056 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782043 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TPLC120C20MP13 | 28,200 | $1,410 |
| No | 206782039 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TPLC120C20MP13 | 28,200 | $1,410 |
| No | 206782035 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TPLC120C20MP13 | 28,200 | $1,410 |
| No | 206782031 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TPLC100C20MP13 | 28,200 | $1,410 |
| No | 206782027 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TPLC100C20MP13 | 28,200 | $1,410 |
| No | 206782023 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TPLC100C20MP13 | 28,200 | $1,410 |
| No | 206782019 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TMLV120C20MP12 | 28,200 | $1,410 |
| No | 206782015 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TMLV120C20MP12 | 28,200 | $1,410 |
| No | 206782011 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TMLV120C20MP12 | 28,200 | $1,410 |
| No | 206782007 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TM8V100C20MP12 | 28,200 | $1,410 |
| No | 206782003 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TM8V100C20MP12 | 28,200 | $1,410 |
| No | 206781999 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TM8V100C20MP12 | 28,200 | $1,410 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781991 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TM8V120C20MP12 | 28,200 | $1,410 |
| No | 206781995 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TM8V120C20MP12 | 28,200 | $1,410 |
| No | 206781987 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TM8V120C20MP12 | 28,200 | $1,410 |
| No | 206781972 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TMLV120C20MP12 | 28,200 | $1,410 |
| No | 206781980 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TPLC120C20MP13 | 28,200 | $1,410 |
| No | 206781976 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TPLC100C20MP13 | 28,200 | $1,410 |
| No | 206781968 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TM8V100C20MP12 | 28,200 | $1,410 |
| No | 206781964 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TM8V120C20MP12 | 28,200 | $1,410 |
| No | 206781957 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TPLC120C20MP13 | 28,600 | $1,430 |
| No | 206781953 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TPLC100C20MP13 | 28,600 | $1,430 |
| No | 206781949 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TMLV120C20MP12 | 28,600 | $1,430 |
| No | 206781945 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TM8V100C20MP12 | 28,600 | $1,430 |
| No | 206781941 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TM8V120C20MP12 | 28,600 | $1,430 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781934 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TPLC120C20MP13 | 28,600 | $1,430 |
| No | 206781930 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TPLC100C20MP13 | 28,600 | $1,430 |
| No | 206781926 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TMLV120C20MP12 | 28,600 | $1,430 |
| No | 206781922 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TM8V100C20MP12 | 28,600 | $1,430 |
| No | 206781918 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TM8V120C20MP12 | 28,600 | $1,430 |
| No | 206781342 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TP9C060B12MP13 | 28,400 | $1,420 |
| No | 206781338 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TP9C060B12MP13 | 28,400 | $1,420 |
| No | 206781334 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TP9C060B12MP13 | 28,400 | $1,420 |
| No | 206781330 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TM9V060B12MP12 | 28,400 | $1,420 |
| No | 202100715 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TP9C060B12MP13 | 28,400 | $1,420 |
| No | 206781326 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TM9V060B12MP12 | 28,400 | $1,420 |
| No | 206781322 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TM9V060B12MP12 | 28,400 | $1,420 |
| No | 202100674 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TM9V060B12MP12 | 28,400 | $1,420 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781312 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TP9C060B12MP13 | 28,400 | $1,420 |
| No | 206781308 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TM9V060B12MP12 | 28,400 | $1,420 |
| No | 206782248 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TP9C080B12MP13 | 28,200 | $1,410 |
| No | 206782244 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TP9C080B12MP13 | 28,200 | $1,410 |
| No | 206782240 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TP9C080B12MP13 | 28,200 | $1,410 |
| No | 202100720 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TP9C080B12MP13 | 28,200 | $1,410 |
| No | 206782236 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TM9V080B12MP12 | 28,200 | $1,410 |
| No | 206782232 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TM9V080B12MP12 | 28,200 | $1,410 |
| No | 206782228 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TM9V080B12MP12 | 28,200 | $1,410 |
| No | 202100680 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TM9V080B12MP12 | 28,200 | $1,410 |
| No | 206782210 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TP9C080B12MP13 | 28,200 | $1,410 |
| No | 206782206 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TM9V080B12MP12 | 28,200 | $1,410 |
| No | 206782224 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782216 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206782220 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 202100723 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206782196 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206782192 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206782188 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 202100683 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206781884 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781880 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206781870 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781866 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781862 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781858 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TM9V080C16MP12 | 28,200 | $1,410 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781854 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206781850 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206781844 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781840 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206781834 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TP9C080C16MP13 | 29,800 | $1,490 |
| No | 206781830 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TM9V080C16MP12 | 29,800 | $1,490 |
| No | 206781824 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TP9C080C16MP13 | 29,800 | $1,490 |
| No | 206781820 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TM9V080C16MP12 | 29,800 | $1,490 |
| No | 206782184 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206782180 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206782176 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 202100729 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781810 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781806 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206781802 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 202100688 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206781756 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781752 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206781742 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781738 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781734 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781730 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206781726 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206781722 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206781716 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781712 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782508 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TP9C100C20MP13 | 28,200 | $1,410 |
| No | 206782504 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TP9C100C20MP13 | 28,200 | $1,410 |
| No | 206782500 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TP9C100C20MP13 | 28,200 | $1,410 |
| No | 206782496 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TM9V100C20MP12 | 28,200 | $1,410 |
| No | 206782492 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TM9V100C20MP12 | 28,200 | $1,410 |
| No | 206782488 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TM9V100C20MP12 | 28,200 | $1,410 |
| No | 206782482 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TP9C100C20MP13 | 28,200 | $1,410 |
| No | 206782478 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TM9V100C20MP12 | 28,200 | $1,410 |
| No | 206782464 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TP9C120D20MP13 | 29,400 | $1,470 |
| No | 206782460 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TM9V120D20MP12 | 29,400 | $1,470 |
| No | 206782454 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TP9C120D20MP13 | 29,400 | $1,470 |
| No | 206782450 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TM9V120D20MP12 | 29,400 | $1,470 |
| No | 205536125 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TP9C120D20MP13 | 28,400 | $1,420 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205536117 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TP9C120D20MP13 | 28,400 | $1,420 |
| No | 205536109 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TP9C120D20MP13 | 28,400 | $1,420 |
| No | 205536099 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TM9V120D20MP12 | 28,400 | $1,420 |
| No | 205536092 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TM9V120D20MP12 | 28,400 | $1,420 |
| No | 205536083 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TM9V120D20MP12 | 28,400 | $1,420 |
| No | 205536070 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TP9C120D20MP13 | 28,400 | $1,420 |
| No | 205536061 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TM9V120D20MP12 | 28,400 | $1,420 |
| No | 206780290 | CHAMPION HEATING AND COOLING | TH16B2421 | CU24BXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |
| No | 206780286 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BBAA1 | TL8E060A12UH11 | 15,200 | $760 |
| No | 206780282 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |
| No | 206780278 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BBAA1 | TL8E060A12UH11 | 15,200 | $760 |
| No | 206780274 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |
| No | 205541015 | CHAMPION HEATING AND COOLING | TH16B2421 | CU36BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205541004 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BBAA1 | TL8E060A12UH11 | 15,100 | $755 |
| No | 205540992 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205540980 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BBAA1 | TL8E060A12UH11 | 15,100 | $755 |
| No | 205540966 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205540954 | CHAMPION HEATING AND COOLING | TH16B2421 | CU24BXA1+TXV | TL9E060B12UH11 | 15,300 | $765 |
| No | 205540939 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BBAA1 | TL9E060B12UH11 | 15,300 | $765 |
| No | 205540915 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BBAA1 | TL9E060B12UH11 | 15,300 | $765 |
| No | 205540903 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BXA1+TXV | TL9E060B12UH11 | 15,300 | $765 |
| No | 205540928 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BXA1+TXV | TL9E060B12UH11 | 15,300 | $765 |
| No | 206780270 | CHAMPION HEATING AND COOLING | TH16B2421 | CU36CXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 206780266 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36CXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 206780262 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36CXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205540890 | CHAMPION HEATING AND COOLING | TH16B2421 | CU30BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203429770 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BBAA1 | TMLE040A12MP11 | 15,100 | $755 |
| No | 205541147 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 203429759 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BBAA1 | TMLE040A12MP11 | 15,100 | $755 |
| No | 205540879 | CHAMPION HEATING AND COOLING | TH16B2421 | CU30BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 203429764 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BBAA1 | TM8E040A12MP11 | 15,100 | $755 |
| No | 205540869 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 203429754 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BBAA1 | TM8E040A12MP11 | 15,100 | $755 |
| No | 205540856 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 205540845 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 206780238 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36AXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 206780234 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36AXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 206780230 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36AXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 206780226 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36AXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780222 | CHAMPION HEATING AND COOLING | TH16B2421 | CU36BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 206780218 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 203429715 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BBAA1 | TMLE040A12MP11 | 15,100 | $755 |
| No | 203429726 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BBAA1 | TMLE040A12MP11 | 15,100 | $755 |
| No | 206780214 | CHAMPION HEATING AND COOLING | TH16B2421 | CU36BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 203429721 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BBAA1 | TM8E040A12MP11 | 15,100 | $755 |
| No | 206780210 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 203429710 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BBAA1 | TM8E040A12MP11 | 15,100 | $755 |
| No | 206780206 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 206780202 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 205550183 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30CXA1+TXV | TMLE100B12MP11 | 15,200 | $760 |
| No | 205550179 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30CXA1+TXV | TM8E100B12MP11 | 15,200 | $760 |
| No | 205550175 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30CXA1+TXV | TMLE100B12MP11 | 15,200 | $760 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205550171 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30CXA1+TXV | TM8E100B12MP11 | 15,200 | $760 |
| No | 206373350 | CHAMPION HEATING AND COOLING | TH16B2421 | CU24AXA1+TXV | TM9E026A08MP12 | 15,000 | $750 |
| No | 206373351 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24ABAA1 | TM9E026A08MP12 | 15,000 | $750 |
| No | 206373352 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24AXA1+TXV | TM9E026A08MP12 | 15,000 | $750 |
| No | 206373353 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24ABAA1 | TM9E026A08MP12 | 15,000 | $750 |
| No | 206373354 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24AXA1+TXV | TM9E026A08MP12 | 15,000 | $750 |
| No | 206373355 | CHAMPION HEATING AND COOLING | TH16B2421 | CU30BXA1+TXV | TM9E026A08MP12 | 15,400 | $770 |
| No | 206373356 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BBAA1 | TM9E026A08MP12 | 15,400 | $770 |
| No | 206373357 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BXA1+TXV | TM9E026A08MP12 | 15,400 | $770 |
| No | 206373358 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BBAA1 | TM9E026A08MP12 | 15,400 | $770 |
| No | 206373359 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BXA1+TXV | TM9E026A08MP12 | 15,400 | $770 |
| No | 206780198 | CHAMPION HEATING AND COOLING | TH16B2421 | CU24AXA1+TXV | TM9E040A10MP12 | 15,300 | $765 |
| No | 206780194 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24ABAA1 | TM9E040A10MP12 | 15,300 | $765 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780190 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24AXA1+TXV | TM9E040A10MP12 | 15,300 | $765 |
| No | 206780186 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24ABAA1 | TM9E040A10MP12 | 15,300 | $765 |
| No | 206780182 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24AXA1+TXV | TM9E040A10MP12 | 15,300 | $765 |
| No | 205074500 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30AXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205074493 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30AXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205074259 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30ABAA1 | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540834 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36AXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540821 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36AXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540810 | CHAMPION HEATING AND COOLING | TH16B2421 | CU36BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540796 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BBAA1 | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540784 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540775 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BBAA1 | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540761 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205540751 | CHAMPION HEATING AND COOLING | TH16B2421 | CU24BXA1+TXV | TM9E060A10MP12 | 15,300 | $765 |
| No | 205540735 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BBAA1 | TM9E060A10MP12 | 15,300 | $765 |
| No | 205540720 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BXA1+TXV | TM9E060A10MP12 | 15,300 | $765 |
| No | 205540707 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BBAA1 | TM9E060A10MP12 | 15,300 | $765 |
| No | 205540694 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BXA1+TXV | TM9E060A10MP12 | 15,300 | $765 |
| No | 205074488 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30AXA1+TXV | TM9E060A10MP12 | 15,200 | $760 |
| No | 205074247 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30ABAA1 | TM9E060A10MP12 | 15,200 | $760 |
| No | 205074482 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30AXA1+TXV | TM9E060A10MP12 | 15,200 | $760 |
| No | 205540489 | CHAMPION HEATING AND COOLING | TH16B2421 | CU36BXA1+TXV | TM9E060A10MP12 | 15,200 | $760 |
| No | 205540474 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BBAA1 | TM9E060A10MP12 | 15,200 | $760 |
| No | 205540459 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BXA1+TXV | TM9E060A10MP12 | 15,200 | $760 |
| No | 205540445 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BBAA1 | TM9E060A10MP12 | 15,200 | $760 |
| No | 205540430 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BXA1+TXV | TM9E060A10MP12 | 15,200 | $760 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202763641 | CHAMPION HEATING AND COOLING | TH16B4821 | AVC60CX22+TXV | | 28,200 | $1,410 |
| No | 202143940 | CHAMPION HEATING AND COOLING | TH16B4821 | AE48DBC21 | | 28,200 | $1,410 |
| No | 202143944 | CHAMPION HEATING AND COOLING | TH16B4821 | AE48DX21+TXV | | 28,200 | $1,410 |
| No | 206781252 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+ME14DN21+TXV | | 29,000 | $1,450 |
| No | 206781248 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+ME14DN21+TXV | | 29,000 | $1,450 |
| No | 205540172 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205540159 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205540142 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205540644 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 202143988 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205540618 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205540606 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205540594 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205540546 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 206782574 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TM9Y080C16MP11 | 29,800 | $1,490 |
| No | 206782570 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TM9Y080C16MP11 | 29,800 | $1,490 |
| No | 9060460 | CHAMPION HEATING AND COOLING | TH16B2421 | AE30BX21+TXV | | 14,800 | $740 |
| No | 206838954 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BBAA1+ME08BN21 | | 15,100 | $755 |
| No | 206838950 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BXA1+ME08BN21+TXV | | 15,100 | $755 |
| No | 206838946 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BBAA1+ME08BN21 | | 15,100 | $755 |
| No | 206838942 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BXA1+ME08BN21+TXV | | 15,100 | $755 |
| No | 205536240 | CHAMPION HEATING AND COOLING | TH16B2421 | CU36BXA1+TXV | TM9Y060B12MP11 | 14,800 | $740 |
| No | 205536228 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BBAA1 | TM9Y060B12MP11 | 14,800 | $740 |
| No | 205536217 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BXA1+TXV | TM9Y060B12MP11 | 14,800 | $740 |
| No | 205536208 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BBAA1 | TM9Y060B12MP11 | 14,800 | $740 |
| No | 205536157 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BXA1+TXV | TM9Y060B12MP11 | 14,800 | $740 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 9060461 | CHAMPION HEATING AND COOLING | TH16B2421 | AVC24BX21+TXV | | 14,800 | $740 |
| No | 9060464 | CHAMPION HEATING AND COOLING | TH16B2421 | AVC36CX21+TXV | | 14,600 | $730 |
| No | 9036087 | CHAMPION HEATING AND COOLING | TH16B6021 | AVC60DX21+TXV | | 32,000 | $1,600 |
| No | 205539836 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TP9C080C16MP13 | 32,600 | $1,630 |
| No | 205539825 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TM9V080C16MP12 | 32,600 | $1,630 |
| No | 205539810 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TP9C080C16MP13 | 32,600 | $1,630 |
| No | 205539800 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TM9V080C16MP12 | 32,600 | $1,630 |
| No | 9036787 | CHAMPION HEATING AND COOLING | TH16B4821 | AVC60DX21+TXV | | 29,400 | $1,470 |
| No | 205550167 | CHAMPION HEATING AND COOLING | TH16B2421 | CU36BXA1+TXV | TMLE100B12MP11 | 15,000 | $750 |
| No | 203429584 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BBAA1 | TMLE100B12MP11 | 15,000 | $750 |
| No | 205550163 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BXA1+TXV | TMLE100B12MP11 | 15,000 | $750 |
| No | 203429573 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BBAA1 | TMLE100B12MP11 | 15,000 | $750 |
| No | 203429578 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BBAA1 | TM8E100B12MP11 | 15,000 | $750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205550155 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BXA1+TXV | TM8E100B12MP11 | 15,000 | $750 |
| No | 203429567 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BBAA1 | TM8E100B12MP11 | 15,000 | $750 |
| No | 205550159 | CHAMPION HEATING AND COOLING | TH16B2421 | CU36BXA1+TXV | TM8E100B12MP11 | 15,000 | $750 |
| No | 205550147 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BXA1+TXV | TMLE100B12MP11 | 15,000 | $750 |
| No | 205550143 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BXA1+TXV | TM8E100B12MP11 | 15,000 | $750 |
| No | 203064286 | CHAMPION HEATING AND COOLING | TH16B3622 | AE36BX21+TXV | | 22,200 | $1,110 |
| No | 205548018 | CHAMPION HEATING AND COOLING | TH16B2421 | CU30BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205548014 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BBAA1 | TL8E060A12UH11 | 15,100 | $755 |
| No | 205548010 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205548006 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BBAA1 | TL8E060A12UH11 | 15,100 | $755 |
| No | 205548002 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205547998 | CHAMPION HEATING AND COOLING | TH16B2421 | CU30BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547994 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BBAA1 | TL9E060B12UH11 | 15,200 | $760 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205547990 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547986 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BBAA1 | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547982 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547978 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30CXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547974 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30CXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547970 | CHAMPION HEATING AND COOLING | TH16B2421 | CU36BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547966 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BBAA1 | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547962 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547958 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BBAA1 | TL9E060B12UH11 | 15,200 | $760 |
| No | 206780258 | CHAMPION HEATING AND COOLING | TH16B2421 | CU24AXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |
| No | 203429847 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24ABAA1 | TMLE040A12MP11 | 15,200 | $760 |
| No | 205547954 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 206780466 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24AXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203429858 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24ABAA1 | TMLE040A12MP11 | 15,200 | $760 |
| No | 206780254 | CHAMPION HEATING AND COOLING | TH16B2421 | CU24AXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 203429841 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24ABAA1 | TM8E040A12MP11 | 15,200 | $760 |
| No | 206780250 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24AXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 203429852 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24ABAA1 | TM8E040A12MP11 | 15,200 | $760 |
| No | 206780246 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24AXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |
| No | 206780242 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24AXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 205547950 | CHAMPION HEATING AND COOLING | TH16B2421 | CU24BXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |
| No | 203429814 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BBAA1 | TMLE040A12MP11 | 15,200 | $760 |
| No | 205548244 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |
| No | 203429825 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BBAA1 | TMLE040A12MP11 | 15,200 | $760 |
| No | 205548240 | CHAMPION HEATING AND COOLING | TH16B2421 | CU24BXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 203429808 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BBAA1 | TM8E040A12MP11 | 15,200 | $760 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205548236 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 203429819 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BBAA1 | TM8E040A12MP11 | 15,200 | $760 |
| No | 205548204 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |
| No | 205548200 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 205074520 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30AXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 203429792 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30ABAA1 | TMLE040A12MP11 | 15,100 | $755 |
| No | 205074272 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30AXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 203429786 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30ABAA1 | TM8E040A12MP11 | 15,100 | $755 |
| No | 205074267 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30AXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 205074507 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30AXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 203429682 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BBAA1 | TMLE080B12MP11 | 15,200 | $760 |
| No | 205546114 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BXA1+TXV | TMLE080B12MP11 | 15,200 | $760 |
| No | 205546118 | CHAMPION HEATING AND COOLING | TH16B2421 | CU24BXA1+TXV | TMLE080B12MP11 | 15,200 | $760 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203429693 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BBAA1 | TMLE080B12MP11 | 15,200 | $760 |
| No | 205546110 | CHAMPION HEATING AND COOLING | TH16B2421 | CU24BXA1+TXV | TM8E080B12MP11 | 15,200 | $760 |
| No | 203429677 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BBAA1 | TM8E080B12MP11 | 15,200 | $760 |
| No | 205546106 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BXA1+TXV | TM8E080B12MP11 | 15,200 | $760 |
| No | 203429688 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BBAA1 | TM8E080B12MP11 | 15,200 | $760 |
| No | 205546098 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BXA1+TXV | TMLE080B12MP11 | 15,200 | $760 |
| No | 205546094 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BXA1+TXV | TM8E080B12MP11 | 15,200 | $760 |
| No | 205546090 | CHAMPION HEATING AND COOLING | TH16B2421 | CU24BXA1+TXV | TMLE100B12MP11 | 15,100 | $755 |
| No | 203429649 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BBAA1 | TMLE100B12MP11 | 15,100 | $755 |
| No | 205546102 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BXA1+TXV | TMLE100B12MP11 | 15,100 | $755 |
| No | 203429660 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BBAA1 | TMLE100B12MP11 | 15,100 | $755 |
| No | 205544364 | CHAMPION HEATING AND COOLING | TH16B2421 | CU24BXA1+TXV | TM8E100B12MP11 | 15,100 | $755 |
| No | 203429644 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BBAA1 | TM8E100B12MP11 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205544357 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BXA1+TXV | TM8E100B12MP11 | 15,100 | $755 |
| No | 203429655 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BBAA1 | TM8E100B12MP11 | 15,100 | $755 |
| No | 205544351 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BXA1+TXV | TMLE100B12MP11 | 15,100 | $755 |
| No | 205544344 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BXA1+TXV | TM8E100B12MP11 | 15,100 | $755 |
| No | 205550203 | CHAMPION HEATING AND COOLING | TH16B2421 | CU30BXA1+TXV | TMLE100B12MP11 | 15,200 | $760 |
| No | 203429627 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BBAA1 | TMLE100B12MP11 | 15,200 | $760 |
| No | 205550227 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BXA1+TXV | TMLE100B12MP11 | 15,200 | $760 |
| No | 203429616 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BBAA1 | TMLE100B12MP11 | 15,200 | $760 |
| No | 205550199 | CHAMPION HEATING AND COOLING | TH16B2421 | CU30BXA1+TXV | TM8E100B12MP11 | 15,200 | $760 |
| No | 203429622 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BBAA1 | TM8E100B12MP11 | 15,200 | $760 |
| No | 205550195 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BXA1+TXV | TM8E100B12MP11 | 15,200 | $760 |
| No | 203429611 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BBAA1 | TM8E100B12MP11 | 15,200 | $760 |
| No | 205550191 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BXA1+TXV | TMLE100B12MP11 | 15,200 | $760 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205550187 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BXA1+TXV | TM8E100B12MP11 | 15,200 | $760 |
| No | 206373360 | CHAMPION HEATING AND COOLING | TH16B2421 | CU24BXA1+TXV | TM9E026A08MP12 | 15,600 | $780 |
| No | 206373361 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BBAA1 | TM9E026A08MP12 | 15,600 | $780 |
| No | 206373363 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BBAA1 | TM9E026A08MP12 | 15,600 | $780 |
| No | 206373362 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BXA1+TXV | TM9E026A08MP12 | 15,600 | $780 |
| No | 206373364 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BXA1+TXV | TM9E026A08MP12 | 15,600 | $780 |
| No | 206373365 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30AXA1+TXV | TM9E026A08MP12 | 14,800 | $740 |
| No | 206373366 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30ABAA1 | TM9E026A08MP12 | 14,800 | $740 |
| No | 206373368 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36AXA1+TXV | TM9E026A08MP12 | 14,900 | $745 |
| No | 206373367 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30AXA1+TXV | TM9E026A08MP12 | 14,800 | $740 |
| No | 206373369 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36AXA1+TXV | TM9E026A08MP12 | 14,900 | $745 |
| No | 206373370 | CHAMPION HEATING AND COOLING | TH16B2421 | CU36BXA1+TXV | TM9E026A08MP12 | 14,900 | $745 |
| No | 206373371 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BBAA1 | TM9E026A08MP12 | 14,900 | $745 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206373372 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BXA1+TXV | TM9E026A08MP12 | 14,900 | $745 |
| No | 206373373 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BBAA1 | TM9E026A08MP12 | 14,900 | $745 |
| No | 206373374 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BXA1+TXV | TM9E026A08MP12 | 14,900 | $745 |
| No | 205548196 | CHAMPION HEATING AND COOLING | TH16B2421 | CU24BXA1+TXV | TM9E040A10MP12 | 15,400 | $770 |
| No | 205548192 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BBAA1 | TM9E040A10MP12 | 15,400 | $770 |
| No | 205548188 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BXA1+TXV | TM9E040A10MP12 | 15,400 | $770 |
| No | 205548184 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BBAA1 | TM9E040A10MP12 | 15,400 | $770 |
| No | 205548180 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BXA1+TXV | TM9E040A10MP12 | 15,400 | $770 |
| No | 205548176 | CHAMPION HEATING AND COOLING | TH16B2421 | CU30BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205548172 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BBAA1 | TM9E040A10MP12 | 15,200 | $760 |
| No | 205548168 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205548164 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BBAA1 | TM9E040A10MP12 | 15,200 | $760 |
| No | 205548160 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205548156 | CHAMPION HEATING AND COOLING | TH16B2421 | CU24AXA1+TXV | TM9E060A10MP12 | 15,400 | $770 |
| No | 205548152 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24ABAA1 | TM9E060A10MP12 | 15,400 | $770 |
| No | 205548148 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24AXA1+TXV | TM9E060A10MP12 | 15,400 | $770 |
| No | 205548144 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24ABAA1 | TM9E060A10MP12 | 15,400 | $770 |
| No | 205548140 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24AXA1+TXV | TM9E060A10MP12 | 15,400 | $770 |
| No | 205548136 | CHAMPION HEATING AND COOLING | TH16B2421 | CU30BXA1+TXV | TM9E060A10MP12 | 15,100 | $755 |
| No | 205548132 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BBAA1 | TM9E060A10MP12 | 15,100 | $755 |
| No | 205548128 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BXA1+TXV | TM9E060A10MP12 | 15,100 | $755 |
| No | 205548124 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BBAA1 | TM9E060A10MP12 | 15,100 | $755 |
| No | 205548120 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BXA1+TXV | TM9E060A10MP12 | 15,100 | $755 |
| No | 205548116 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36AXA1+TXV | TM9E060A10MP12 | 15,100 | $755 |
| No | 205548112 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36AXA1+TXV | TM9E060A10MP12 | 15,100 | $755 |
| No | 206779784 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BBAA1+ME08BN21 | | 15,000 | $750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206779780 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BXA1+ME08BN21+TXV | | 15,000 | $750 |
| No | 206779776 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BBAA1+ME08BN21 | | 15,000 | $750 |
| No | 206779772 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BXA1+ME08BN21+TXV | | 15,000 | $750 |
| No | 9060462 | CHAMPION HEATING AND COOLING | TH16B2421 | AVC30BX21+TXV | | 15,100 | $755 |
| No | 9060463 | CHAMPION HEATING AND COOLING | TH16B2421 | AVC36BX21+TXV | | 15,000 | $750 |
| No | 205547850 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+MVC20DN21+TXV | | 32,600 | $1,630 |
| No | 205547846 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+MVC20DN21+TXV | | 32,600 | $1,630 |
| No | 205547838 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TPLC120C20MP13 | 32,400 | $1,620 |
| No | 205547834 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TPLC100C20MP13 | 32,400 | $1,620 |
| No | 205547830 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TMLV120C20MP12 | 32,400 | $1,620 |
| No | 205547822 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TM8V100C20MP12 | 32,400 | $1,620 |
| No | 205547818 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TM8V120C20MP12 | 32,400 | $1,620 |
| No | 205547810 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TPLC120C20MP13 | 32,400 | $1,620 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205547806 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TPLC100C20MP13 | 32,400 | $1,620 |
| No | 205547802 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TMLV120C20MP12 | 32,400 | $1,620 |
| No | 205547794 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TM8V100C20MP12 | 32,400 | $1,620 |
| No | 205547790 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TM8V120C20MP12 | 32,400 | $1,620 |
| No | 203431218 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205547628 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205547624 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 203431212 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 205547574 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 205547570 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 205547566 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205547562 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 9854435 | CHAMPION HEATING AND COOLING | TH16B2421 | AE24BBA21 | | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 9854440 | CHAMPION HEATING AND COOLING | TH16B4821 | AE48CBC21 | | 28,400 | $1,420 |
| No | 9006273 | CHAMPION HEATING AND COOLING | TH16B2421 | AE24BX21+TXV | | 15,100 | $755 |
| No | 9006283 | CHAMPION HEATING AND COOLING | TH16B4821 | AE48CX21+TXV | | 28,400 | $1,420 |
| No | 205550139 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36AXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 205550135 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36AXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 205550131 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36BXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 203088290 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BBCA1 | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 205550151 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 203088270 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BBCA1 | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 205550127 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 205550123 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42BXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 205550119 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 203088066 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TL9E060B12UH11 | 22,600 | $1,130 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205550115 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 203088045 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205550111 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205550107 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TL9E060B12UH11 | 22,400 | $1,120 |
| No | 203088006 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TL9E060B12UH11 | 22,400 | $1,120 |
| No | 205550103 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TL9E060B12UH11 | 22,400 | $1,120 |
| No | 203087988 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TL9E060B12UH11 | 22,400 | $1,120 |
| No | 205550099 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TL9E060B12UH11 | 22,400 | $1,120 |
| No | 205550095 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TL9E080C16UH11 | 22,600 | $1,130 |
| No | 203087951 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TL9E080C16UH11 | 22,600 | $1,130 |
| No | 205550091 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TL9E080C16UH11 | 22,600 | $1,130 |
| No | 205550087 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TL9E080C16UH11 | 22,600 | $1,130 |
| No | 205550083 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TL9E080C16UH11 | 22,800 | $1,140 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203087915 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TL9E080C16UH11 | 22,800 | $1,140 |
| No | 205550079 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TL9E080C16UH11 | 22,800 | $1,140 |
| No | 203087893 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TL9E080C16UH11 | 22,800 | $1,140 |
| No | 205550071 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TL9E080C16UH11 | 22,800 | $1,140 |
| No | 205550067 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36AXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205550063 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36AXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205550059 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36AXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205550055 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36AXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205550051 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36BXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 203431025 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BBCA1 | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 203431020 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BBCA1 | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205550047 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36BXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205550075 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203087733 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BBCA1 | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205550043 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 203087712 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BBCA1 | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205550039 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205550035 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205550031 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42BXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205550027 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42BXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205550020 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 203430948 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205550016 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205550012 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 203087468 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205550004 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549996 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205550000 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205549992 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42BXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205549988 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42BXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205549984 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 203430926 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205550008 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 203430921 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205549980 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 203087391 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205549976 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 203087372 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205549972 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549968 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 206780767 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TMLE080B12MP11 | 22,200 | $1,110 |
| No | 203430910 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TMLE080B12MP11 | 22,200 | $1,110 |
| No | 206780763 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TMLE080B12MP11 | 22,200 | $1,110 |
| No | 203430904 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TMLE080B12MP11 | 22,200 | $1,110 |
| No | 206780759 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TM8E080B12MP11 | 22,200 | $1,110 |
| No | 203087337 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TM8E080B12MP11 | 22,200 | $1,110 |
| No | 206780755 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TM8E080B12MP11 | 22,200 | $1,110 |
| No | 206780751 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TMLE080B12MP11 | 22,200 | $1,110 |
| No | 206780747 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TM8E080B12MP11 | 22,200 | $1,110 |
| No | 203087318 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TM8E080B12MP11 | 22,200 | $1,110 |
| No | 203430843 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205549964 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549960 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203087103 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205549956 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205549952 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205549948 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205549944 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205549940 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205549936 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203430816 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205549932 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203087014 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205549916 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205549912 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549908 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205549904 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42BXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205549900 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42BXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205549896 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549892 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205549888 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549880 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549884 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203430728 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549928 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 203430722 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549924 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203086702 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549920 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203086682 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205549876 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549872 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203430711 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549868 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549864 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 203086643 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205549860 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205549856 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205549844 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 205549848 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205549852 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203430700 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 205549840 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 205549836 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 203086605 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 205549826 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 205549822 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 205549818 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206780739 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 203430689 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 203430683 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206780735 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206780743 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 203098268 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780731 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 203098261 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206780727 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206780723 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 205549830 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36BXA1+TXV | TPLC080B12MP13 | 22,800 | $1,140 |
| No | 203098051 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BBCA1 | TPLC080B12MP13 | 22,800 | $1,140 |
| No | 205549812 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BXA1+TXV | TPLC080B12MP13 | 22,800 | $1,140 |
| No | 203098023 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BBCA1 | TPLC080B12MP13 | 22,800 | $1,140 |
| No | 205549800 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36BXA1+TXV | TM8V080B12MP12 | 22,800 | $1,140 |
| No | 203098035 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BBCA1 | TM8V080B12MP12 | 22,800 | $1,140 |
| No | 205549796 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BXA1+TXV | TM8V080B12MP12 | 22,800 | $1,140 |
| No | 203098007 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BBCA1 | TM8V080B12MP12 | 22,800 | $1,140 |
| No | 205549786 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BXA1+TXV | TPLC080B12MP13 | 22,800 | $1,140 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549778 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BXA1+TXV | TM8V080B12MP12 | 22,800 | $1,140 |
| No | 203097963 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BBCA1 | TM9E060A10MP12 | 23,000 | $1,150 |
| No | 205549792 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BXA1+TXV | TM9E060A10MP12 | 23,000 | $1,150 |
| No | 205549774 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36BXA1+TXV | TM9E060A10MP12 | 23,000 | $1,150 |
| No | 203097955 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BBCA1 | TM9E060A10MP12 | 23,000 | $1,150 |
| No | 205549770 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BXA1+TXV | TM9E060A10MP12 | 23,000 | $1,150 |
| No | 205549766 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42BXA1+TXV | TM9E060A10MP12 | 22,600 | $1,130 |
| No | 205549762 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36BXA1+TXV | TM9E060B12MP12 | 22,400 | $1,120 |
| No | 203097923 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BBCA1 | TM9E060B12MP12 | 22,400 | $1,120 |
| No | 205549758 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BXA1+TXV | TM9E060B12MP12 | 22,400 | $1,120 |
| No | 203097915 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BBCA1 | TM9E060B12MP12 | 22,400 | $1,120 |
| No | 205549750 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 203097899 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TM9E060B12MP12 | 22,600 | $1,130 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549754 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BXA1+TXV | TM9E060B12MP12 | 22,400 | $1,120 |
| No | 205549746 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205549742 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205549738 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097794 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549734 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549730 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549726 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42BXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549722 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097762 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549718 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097754 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549714 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549710 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097739 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549706 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097731 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097643 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 205549702 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 206780719 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 206780715 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 206780711 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 205549698 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 203097627 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205549694 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205549690 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549686 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 203097610 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 205549682 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 203097602 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 205549674 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 205549670 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205549666 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205549662 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 203097578 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 203097571 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 205549678 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 205549658 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 203097506 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BBCA1 | TM9Y060B12MP11 | 22,600 | $1,130 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549650 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BXA1+TXV | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 205549654 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36BXA1+TXV | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 203097490 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BBCA1 | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 205549638 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BXA1+TXV | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 205549630 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42BXA1+TXV | TM8Y080B12MP11 | 22,200 | $1,110 |
| No | 205549618 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TM8Y100C20MP11 | 22,400 | $1,120 |
| No | 203097394 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TM8Y100C20MP11 | 22,400 | $1,120 |
| No | 205549614 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TM8Y100C20MP11 | 22,400 | $1,120 |
| No | 205549610 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TM8Y120C20MP11 | 22,400 | $1,120 |
| No | 203097386 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TM8Y120C20MP11 | 22,400 | $1,120 |
| No | 205549606 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TM8Y120C20MP11 | 22,400 | $1,120 |
| No | 205549558 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TM8Y100C20MP11 | 22,400 | $1,120 |
| No | 205549554 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TM8Y120C20MP11 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549534 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TM8Y100C20MP11 | 23,200 | $1,160 |
| No | 203097298 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TM8Y100C20MP11 | 23,200 | $1,160 |
| No | 205549574 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TM8Y100C20MP11 | 23,200 | $1,160 |
| No | 203097250 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TM8Y100C20MP11 | 23,200 | $1,160 |
| No | 205549570 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TM8Y120C20MP11 | 23,200 | $1,160 |
| No | 203097290 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TM8Y120C20MP11 | 23,200 | $1,160 |
| No | 205549566 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TM8Y120C20MP11 | 23,200 | $1,160 |
| No | 203097242 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TM8Y120C20MP11 | 23,200 | $1,160 |
| No | 205549498 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TM8Y100C20MP11 | 23,200 | $1,160 |
| No | 203097155 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TM8Y100C20MP11 | 22,200 | $1,110 |
| No | 205549494 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TM8Y120C20MP11 | 23,200 | $1,160 |
| No | 205549474 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TM8Y100C20MP11 | 22,200 | $1,110 |
| No | 205549470 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TM8Y100C20MP11 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203097147 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TM8Y120C20MP11 | 22,200 | $1,110 |
| No | 205549466 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TM8Y120C20MP11 | 22,200 | $1,110 |
| No | 205549418 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TM8Y100C20MP11 | 22,200 | $1,110 |
| No | 205549462 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TM8Y120C20MP11 | 22,200 | $1,110 |
| No | 205549414 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TM8Y120C20MP11 | 22,200 | $1,110 |
| No | 205549394 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 203097059 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205549434 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205549386 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205549378 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 203097028 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205549374 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 203097011 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TM9Y080C16MP11 | 22,800 | $1,140 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549358 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205549350 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42BXA1+MVC12BN21+TXV | | 22,000 | $1,100 |
| No | 203096742 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BBCA1+ME12BN21 | | 22,200 | $1,110 |
| No | 205549362 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BXA1+ME12BN21+TXV | | 22,200 | $1,110 |
| No | 203096735 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BBCA1+ME12BN21 | | 22,200 | $1,110 |
| No | 205549346 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BXA1+ME12BN21+TXV | | 22,200 | $1,110 |
| No | 205549342 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42BXA1+ME12BN21+TXV | | 22,200 | $1,110 |
| No | 203096686 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1+MVC14DN21 | | 21,800 | $1,090 |
| No | 205549338 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+MVC14DN21+TXV | | 21,800 | $1,090 |
| No | 205549334 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+MVC14DN21+TXV | | 21,800 | $1,090 |
| No | 205549326 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 203096402 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 205549322 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549310 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 203096387 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205549300 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205549294 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 205549286 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205549304 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 203096262 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 205549280 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 203096235 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 205549268 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 203096247 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205549264 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 203096219 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TM8V080B12MP12 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549252 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 205549244 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205549258 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 203096024 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549234 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 203096016 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205549238 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549224 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205549218 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549214 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205549228 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 203095961 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549208 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203095941 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549202 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 203095953 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205549198 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 203095933 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205549188 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205549192 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 203095876 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 205549182 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 203095856 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 205549172 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 205549176 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 203095868 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TM9V080C16MP12 | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549168 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 203095848 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 205549162 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 205549158 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 203095749 | CHAMPION HEATING AND COOLING | TH16B3622 | AVC42CX21+TXV | | 22,600 | $1,130 |
| No | 205549144 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203095614 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205549140 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205549136 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 203095606 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549132 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549128 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203095598 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549124 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205549112 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203095582 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205549108 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205549104 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203095574 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205549100 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205549092 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205549088 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549084 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205549076 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205549072 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203094721 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549060 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205549056 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203094713 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549052 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549048 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 203094705 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205549044 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205549040 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203094689 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205549028 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205549024 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203094681 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205549006 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549002 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205548994 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205548990 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205548986 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205548978 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205548974 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205549018 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 203094494 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205549014 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205549010 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 203094486 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548968 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548964 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203094479 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548960 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548948 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 203094463 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548944 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548940 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 203094455 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548936 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548924 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548928 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548920 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548912 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548908 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205548896 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 203094213 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548892 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 203094158 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548888 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 203094205 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548884 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 203094150 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548880 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 203094197 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548876 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 203094141 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548864 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203094182 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548855 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 203094125 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548845 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 203094173 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548837 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 203094117 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548812 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548808 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548804 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548796 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548792 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548784 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205548780 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548776 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548768 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548764 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548752 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548748 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548756 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548740 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548736 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548732 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36BXA1+TXV | TM8Y080B12MP11 | 22,000 | $1,100 |
| No | 203093071 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BBCA1 | TM8Y080B12MP11 | 22,000 | $1,100 |
| No | 205548828 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36BXA1+TXV | TM8Y080B12MP11 | 22,000 | $1,100 |
| No | 203093017 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BBCA1 | TM8Y080B12MP11 | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205548720 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36BXA1+TXV | TM8Y080B12MP11 | 22,000 | $1,100 |
| No | 205548708 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 203092686 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205548704 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 203092571 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205548700 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203092667 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205548696 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203092551 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205548656 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205548652 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205548632 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205548628 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205548608 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205548604 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205548584 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42BXA1+TXV | TM9Y080B12MP11 | 22,000 | $1,100 |
| No | 205548576 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205548572 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205548568 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205548556 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205548548 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548544 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548540 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548536 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548528 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548520 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TM9Y100C16MP11 | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205548516 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548512 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548490 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548388 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42BXA1+TXV | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 205548384 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42BXA1+TXV | TM9V080B12MP12 | 22,200 | $1,110 |
| No | 205548502 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 203090047 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548414 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 203090001 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 203090029 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CBCA1 | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205548378 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 203089982 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CBCA1 | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205548410 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205548372 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548368 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 203089863 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548358 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548354 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 203089844 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205548350 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205548346 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205548340 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548336 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205548328 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 203089674 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548324 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205548320 | CHAMPION HEATING AND COOLING | TH16B3622 | CU36CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203089656 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205548316 | CHAMPION HEATING AND COOLING | TH16B3622 | CM36CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205548310 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548306 | CHAMPION HEATING AND COOLING | TH16B3622 | CF36CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205548300 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 203089447 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548292 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 203089404 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548288 | CHAMPION HEATING AND COOLING | TH16B3622 | CU42CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203089429 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205548284 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203089385 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205548278 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548274 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 206780705 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 206780701 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+TXV | TM9V120D20MP12 | 22,000 | $1,100 |
| No | 206780695 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 206780691 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+TXV | TM9V120D20MP12 | 22,000 | $1,100 |
| No | 203088570 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 205548270 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 205548266 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 205548262 | CHAMPION HEATING AND COOLING | TH16B3622 | CU48DXA1+TXV | TM9V120D20MP12 | 22,000 | $1,100 |
| No | 203088553 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1 | TM9V120D20MP12 | 22,000 | $1,100 |
| No | 205548258 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+TXV | TM9V120D20MP12 | 22,000 | $1,100 |
| No | 205548252 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TP9C120D20MP13 | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203088489 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DBCA1+MVC20DN21 | | 22,000 | $1,100 |
| No | 205548248 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+TXV | TM9V120D20MP12 | 22,000 | $1,100 |
| No | 205548100 | CHAMPION HEATING AND COOLING | TH16B3622 | CM48DXA1+MVC20DN21+TXV | | 22,000 | $1,100 |
| No | 205548096 | CHAMPION HEATING AND COOLING | TH16B3622 | CF48DXA1+MVC20DN21+TXV | | 22,000 | $1,100 |
| No | 205548092 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+MVC20DN21+TXV | | 22,000 | $1,100 |
| No | 205548088 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+MVC20DN21+TXV | | 22,000 | $1,100 |
| No | 205548084 | CHAMPION HEATING AND COOLING | TH16B3622 | CM42DXA1+MVC14DN21+TXV | | 22,200 | $1,110 |
| No | 205548080 | CHAMPION HEATING AND COOLING | TH16B3622 | CF42DXA1+MVC14DN21+TXV | | 22,200 | $1,110 |
| No | 205074561 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30AXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205074309 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30ABAA1 | TL8E060A12UH11 | 15,100 | $755 |
| No | 205546770 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36AXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205074554 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30AXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205546766 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36AXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205546762 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 205546758 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 205546754 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 205546750 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 205546718 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TL8E100C20UH11 | 28,200 | $1,410 |
| No | 205546714 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TL8E100C20UH11 | 28,200 | $1,410 |
| No | 205546706 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TL8E100C20UH11 | 28,200 | $1,410 |
| No | 205546710 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TL8E100C20UH11 | 28,200 | $1,410 |
| No | 205546702 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TL8E100C20UH11 | 28,200 | $1,410 |
| No | 205546698 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TL8E100C20UH11 | 28,600 | $1,430 |
| No | 205546694 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TL8E100C20UH11 | 28,600 | $1,430 |
| No | 205546690 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TL8E100C20UH11 | 28,600 | $1,430 |
| No | 205546682 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TL8E100C20UH11 | 29,400 | $1,470 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205546686 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TL8E100C20UH11 | 28,600 | $1,430 |
| No | 205546678 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TL8E100C20UH11 | 29,400 | $1,470 |
| No | 205546674 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205546670 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205546666 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205546662 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205546658 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205546654 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TL9E100C20UH11 | 28,400 | $1,420 |
| No | 205546650 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TL9E100C20UH11 | 28,400 | $1,420 |
| No | 205546646 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TL9E100C20UH11 | 28,400 | $1,420 |
| No | 205546642 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TL9E100C20UH11 | 28,400 | $1,420 |
| No | 205546638 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TL9E100C20UH11 | 28,400 | $1,420 |
| No | 205546634 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TL9E100C20UH11 | 28,600 | $1,430 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205546630 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TL9E100C20UH11 | 28,600 | $1,430 |
| No | 205546626 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TL9E100C20UH11 | 28,600 | $1,430 |
| No | 205546622 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TL9E100C20UH11 | 28,600 | $1,430 |
| No | 205546618 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TL9E100C20UH11 | 30,400 | $1,520 |
| No | 205546614 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TL9E100C20UH11 | 30,400 | $1,520 |
| No | 205546610 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TMLE080B12MP11 | 28,000 | $1,400 |
| No | 203431431 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TMLE080B12MP11 | 28,000 | $1,400 |
| No | 203431420 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TMLE080B12MP11 | 28,000 | $1,400 |
| No | 205546746 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TMLE080B12MP11 | 28,000 | $1,400 |
| No | 205546742 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TM8E080B12MP11 | 28,000 | $1,400 |
| No | 203431426 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TM8E080B12MP11 | 28,000 | $1,400 |
| No | 205546738 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TM8E080B12MP11 | 28,000 | $1,400 |
| No | 203431415 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TM8E080B12MP11 | 28,000 | $1,400 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205546730 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TMLE080B12MP11 | 28,000 | $1,400 |
| No | 205546726 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TM8E080B12MP11 | 28,000 | $1,400 |
| No | 205546722 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TMLE080C16MP11 | 28,600 | $1,430 |
| No | 203431387 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TMLE080C16MP11 | 28,600 | $1,430 |
| No | 205546734 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TMLE080C16MP11 | 28,600 | $1,430 |
| No | 203431376 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TMLE080C16MP11 | 28,600 | $1,430 |
| No | 205546606 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TM8E080C16MP11 | 28,600 | $1,430 |
| No | 203431382 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TM8E080C16MP11 | 28,600 | $1,430 |
| No | 205546602 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TM8E080C16MP11 | 28,600 | $1,430 |
| No | 203431371 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TM8E080C16MP11 | 28,600 | $1,430 |
| No | 205546598 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TMLE080C16MP11 | 28,600 | $1,430 |
| No | 205546594 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TM8E080C16MP11 | 28,600 | $1,430 |
| No | 203431354 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TMLE080C16MP11 | 27,800 | $1,390 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205546590 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 205546586 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 203431349 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205546582 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205546578 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205546570 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205546574 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 205085184 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60DXA2+TXV | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 205085178 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60DXA2+TXV | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 205085172 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60DXA2+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205085167 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60DXA2+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205085163 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60DXA2+TXV | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 205085154 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60DXA2+TXV | TM8E080C16MP11 | 27,800 | $1,390 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205546558 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TMLE080C16MP11 | 30,600 | $1,530 |
| No | 205546553 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TM8E080C16MP11 | 30,600 | $1,530 |
| No | 205546548 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TMLE080C16MP11 | 30,600 | $1,530 |
| No | 205546544 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TM8E080C16MP11 | 30,600 | $1,530 |
| No | 205546539 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TMLE100B12MP11 | 27,800 | $1,390 |
| No | 203431289 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TMLE100B12MP11 | 27,800 | $1,390 |
| No | 205546566 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TMLE100B12MP11 | 27,800 | $1,390 |
| No | 203431278 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TMLE100B12MP11 | 27,800 | $1,390 |
| No | 205546562 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TM8E100B12MP11 | 27,800 | $1,390 |
| No | 203431283 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TM8E100B12MP11 | 27,800 | $1,390 |
| No | 205546534 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TM8E100B12MP11 | 27,800 | $1,390 |
| No | 203431272 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TM8E100B12MP11 | 27,800 | $1,390 |
| No | 205546530 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TMLE100B12MP11 | 27,800 | $1,390 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205546525 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TM8E100B12MP11 | 27,800 | $1,390 |
| No | 205546521 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 203431250 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205546516 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 203431239 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205546511 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 203431245 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 205546506 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 203431234 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 205546502 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 206781501 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TMLE100C16MP11 | 30,600 | $1,530 |
| No | 205546497 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 206781497 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TM8E100C16MP11 | 30,600 | $1,530 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781493 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TMLE100C16MP11 | 30,600 | $1,530 |
| No | 206781489 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TM8E100C16MP11 | 30,600 | $1,530 |
| No | 205084985 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60CXA2+TXV | TMLE100C20MP11 | 27,200 | $1,360 |
| No | 205084980 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60CXA2+TXV | TMLE100C20MP11 | 27,200 | $1,360 |
| No | 205084975 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60CXA2+TXV | TM8E100C20MP11 | 27,200 | $1,360 |
| No | 205084969 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60CXA2+TXV | TM8E100C20MP11 | 27,200 | $1,360 |
| No | 205084963 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60CXA2+TXV | TMLE100C20MP11 | 27,200 | $1,360 |
| No | 205084958 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60CXA2+TXV | TM8E100C20MP11 | 27,200 | $1,360 |
| No | 205084952 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60DXA2+TXV | TMLE100C20MP11 | 27,400 | $1,370 |
| No | 205084946 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60DXA2+TXV | TMLE100C20MP11 | 27,400 | $1,370 |
| No | 205084940 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60DXA2+TXV | TM8E100C20MP11 | 27,400 | $1,370 |
| No | 205084928 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60DXA2+TXV | TMLE100C20MP11 | 27,400 | $1,370 |
| No | 205084934 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60DXA2+TXV | TM8E100C20MP11 | 27,400 | $1,370 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205084923 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60DXA2+TXV | TM8E100C20MP11 | 27,400 | $1,370 |
| No | 203431108 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 205546492 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 205546488 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 203431102 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 205546483 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 205546478 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 205546473 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 205546468 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 205084883 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60CXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205084878 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60CXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205084874 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60CXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 205084868 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60CXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205084862 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60CXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205084857 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60CXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 205084851 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60DXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205084845 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60DXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205084840 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60DXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 205084833 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60DXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 205084827 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60DXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205084820 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60DXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 205546438 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 205546433 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 205546429 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 205546424 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 205084745 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60CXA2+TXV | TM9E080C20MP12 | 27,200 | $1,360 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205084739 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60CXA2+TXV | TM9E080C20MP12 | 27,200 | $1,360 |
| No | 205084733 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60CXA2+TXV | TM9E080C20MP12 | 27,200 | $1,360 |
| No | 205084728 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60DXA2+TXV | TM9E080C20MP12 | 27,600 | $1,380 |
| No | 205084722 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60DXA2+TXV | TM9E080C20MP12 | 27,600 | $1,380 |
| No | 205084716 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60DXA2+TXV | TM9E080C20MP12 | 27,600 | $1,380 |
| No | 205546457 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1 | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205546452 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48DXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205546448 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205546443 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205084710 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60DXA2+TXV | TM9E100C16MP12 | 28,000 | $1,400 |
| No | 205084704 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60DXA2+TXV | TM9E100C16MP12 | 28,000 | $1,400 |
| No | 205084698 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60DXA2+TXV | TM9E100C16MP12 | 28,000 | $1,400 |
| No | 205546464 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TM9E100C16MP12 | 28,800 | $1,440 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205546459 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TM9E100C16MP12 | 28,800 | $1,440 |
| No | 205084693 | CHAMPION HEATING AND COOLING | TH16B4821 | CU60CXA2+TXV | TM9E100C20MP12 | 27,200 | $1,360 |
| No | 205084687 | CHAMPION HEATING AND COOLING | TH16B4821 | CM60CXA2+TXV | TM9E100C20MP12 | 27,200 | $1,360 |
| No | 205084681 | CHAMPION HEATING AND COOLING | TH16B4821 | CF60CXA2+TXV | TM9E100C20MP12 | 27,200 | $1,360 |
| No | 205546318 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TL8E100C20UH11 | 32,800 | $1,640 |
| No | 205546314 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TL8E100C20UH11 | 32,800 | $1,640 |
| No | 205546310 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TL9E100C20UH11 | 32,800 | $1,640 |
| No | 205546306 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TL9E100C20UH11 | 32,800 | $1,640 |
| No | 205546302 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TMLE080C20MP11 | 32,600 | $1,630 |
| No | 205546298 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TM8E080C20MP11 | 32,600 | $1,630 |
| No | 205546294 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TMLE080C20MP11 | 32,600 | $1,630 |
| No | 205546290 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TM8E080C20MP11 | 32,600 | $1,630 |
| No | 206782997 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TMLE120C16MP11 | 32,800 | $1,640 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782993 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TM8E120C16MP11 | 32,800 | $1,640 |
| No | 206782989 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TMLE120C16MP11 | 32,800 | $1,640 |
| No | 206782985 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TM8E120C16MP11 | 32,800 | $1,640 |
| No | 205546286 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TM9E080C20MP12 | 32,600 | $1,630 |
| No | 205546282 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TM9E080C20MP12 | 32,600 | $1,630 |
| No | 205546278 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TM9E100C20MP12 | 32,600 | $1,630 |
| No | 205546274 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TM9E100C20MP12 | 32,600 | $1,630 |
| No | 205546270 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TM9E120D20MP12 | 33,200 | $1,660 |
| No | 205546266 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TM9E120D20MP12 | 33,200 | $1,660 |
| No | 206838938 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36AXA1+TXV | TPLC060A12MP13 | 15,000 | $750 |
| No | 206838934 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36AXA1+TXV | TMLV060A12MP12 | 15,000 | $750 |
| No | 206838930 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36AXA1+TXV | TM8V060A12MP12 | 15,000 | $750 |
| No | 206838926 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36AXA1+TXV | TPLC060A12MP13 | 15,000 | $750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206838922 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36AXA1+TXV | TMLV060A12MP12 | 15,000 | $750 |
| No | 206838918 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36AXA1+TXV | TM8V060A12MP12 | 15,000 | $750 |
| No | 206779717 | CHAMPION HEATING AND COOLING | TH16B2421 | CU24BXA1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 206779713 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BBAA1 | TPLC080B12MP13 | 15,100 | $755 |
| No | 206779709 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BXA1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 202102055 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BBAA1 | TPLC080B12MP13 | 15,100 | $755 |
| No | 206780687 | CHAMPION HEATING AND COOLING | TH16B2421 | CU24BXA1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 206780683 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BBAA1 | TM8V080B12MP12 | 15,100 | $755 |
| No | 206780679 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BXA1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 202102039 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BBAA1 | TM8V080B12MP12 | 15,100 | $755 |
| No | 206780656 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BXA1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 206780652 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BXA1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 206780599 | CHAMPION HEATING AND COOLING | TH16B2421 | CU36BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780595 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BBAA1 | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780591 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780587 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BBAA1 | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780583 | CHAMPION HEATING AND COOLING | TH16B2421 | CU36BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780579 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BBAA1 | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780575 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780571 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BBAA1 | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780566 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780562 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780550 | CHAMPION HEATING AND COOLING | TH16B2421 | CU36CXA1+TXV | TPLC100C16MP13 | 15,100 | $755 |
| No | 206780546 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36CXA1+TXV | TPLC100C16MP13 | 15,100 | $755 |
| No | 206780542 | CHAMPION HEATING AND COOLING | TH16B2421 | CU36CXA1+TXV | TPLC080C16MP13 | 15,100 | $755 |
| No | 206780538 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36CXA1+TXV | TPLC080C16MP13 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780534 | CHAMPION HEATING AND COOLING | TH16B2421 | CU36CXA1+TXV | TMLV100C16MP12 | 15,100 | $755 |
| No | 206780530 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36CXA1+TXV | TMLV100C16MP12 | 15,100 | $755 |
| No | 206780526 | CHAMPION HEATING AND COOLING | TH16B2421 | CU36CXA1+TXV | TM8V080C16MP12 | 15,100 | $755 |
| No | 206780522 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36CXA1+TXV | TM8V080C16MP12 | 15,100 | $755 |
| No | 206780518 | CHAMPION HEATING AND COOLING | TH16B2421 | CU36CXA1+TXV | TM8V100C16MP12 | 15,100 | $755 |
| No | 206780514 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36CXA1+TXV | TM8V100C16MP12 | 15,100 | $755 |
| No | 206780506 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36CXA1+TXV | TPLC100C16MP13 | 15,100 | $755 |
| No | 206780502 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36CXA1+TXV | TPLC080C16MP13 | 15,100 | $755 |
| No | 206780498 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36CXA1+TXV | TMLV100C16MP12 | 15,100 | $755 |
| No | 206780494 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36CXA1+TXV | TM8V080C16MP12 | 15,100 | $755 |
| No | 206780490 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36CXA1+TXV | TM8V100C16MP12 | 15,100 | $755 |
| No | 205545604 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BBAA1 | TM9Y060B12MP11 | 15,300 | $765 |
| No | 205545612 | CHAMPION HEATING AND COOLING | TH16B2421 | CU30BXA1+TXV | TM9Y060B12MP11 | 15,300 | $765 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205545595 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BXA1+TXV | TM9Y060B12MP11 | 15,300 | $765 |
| No | 205545588 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BBAA1 | TM9Y060B12MP11 | 15,300 | $765 |
| No | 205545544 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BXA1+TXV | TM9Y060B12MP11 | 15,300 | $765 |
| No | 205074547 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30AXA1+TXV | TM9V040A10MP12 | 15,100 | $755 |
| No | 202143780 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30ABAA1 | TM9V040A10MP12 | 15,100 | $755 |
| No | 205074541 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30AXA1+TXV | TM9V040A10MP12 | 15,100 | $755 |
| No | 205546399 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36AXA1+TXV | TM9V040A10MP12 | 15,000 | $750 |
| No | 205546394 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36AXA1+TXV | TM9V040A10MP12 | 15,000 | $750 |
| No | 206780146 | CHAMPION HEATING AND COOLING | TH16B2421 | CU24BXA1+TXV | TP9C060B12MP13 | 15,200 | $760 |
| No | 206780142 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BBAA1 | TP9C060B12MP13 | 15,200 | $760 |
| No | 206780138 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BXA1+TXV | TP9C060B12MP13 | 15,200 | $760 |
| No | 202101777 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BBAA1 | TP9C060B12MP13 | 15,200 | $760 |
| No | 206780134 | CHAMPION HEATING AND COOLING | TH16B2421 | CU24BXA1+TXV | TM9V060B12MP12 | 15,200 | $760 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780130 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BBAA1 | TM9V060B12MP12 | 15,200 | $760 |
| No | 206780126 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BXA1+TXV | TM9V060B12MP12 | 15,200 | $760 |
| No | 202101773 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BBAA1 | TM9V060B12MP12 | 15,200 | $760 |
| No | 206780050 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BXA1+TXV | TP9C060B12MP13 | 15,200 | $760 |
| No | 206780046 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BXA1+TXV | TM9V060B12MP12 | 15,200 | $760 |
| No | 206780034 | CHAMPION HEATING AND COOLING | TH16B2421 | CU30BXA1+TXV | TP9C060B12MP13 | 15,400 | $770 |
| No | 206780026 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BXA1+TXV | TP9C060B12MP13 | 15,400 | $770 |
| No | 206780022 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BBAA1 | TP9C060B12MP13 | 15,400 | $770 |
| No | 206780030 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BBAA1 | TP9C060B12MP13 | 15,400 | $770 |
| No | 206780018 | CHAMPION HEATING AND COOLING | TH16B2421 | CU30BXA1+TXV | TM9V060B12MP12 | 15,400 | $770 |
| No | 206780014 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BBAA1 | TM9V060B12MP12 | 15,400 | $770 |
| No | 206780010 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BXA1+TXV | TM9V060B12MP12 | 15,400 | $770 |
| No | 206780006 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BBAA1 | TM9V060B12MP12 | 15,400 | $770 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206779996 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BXA1+TXV | TM9V060B12MP12 | 15,400 | $770 |
| No | 206780000 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BXA1+TXV | TP9C060B12MP13 | 15,400 | $770 |
| No | 206780669 | CHAMPION HEATING AND COOLING | TH16B2421 | CU24BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780665 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BBAA1 | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780661 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 202102051 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BBAA1 | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780478 | CHAMPION HEATING AND COOLING | TH16B2421 | CU24BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780474 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BBAA1 | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780470 | CHAMPION HEATING AND COOLING | TH16B2421 | CM24BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 202102042 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BBAA1 | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780398 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BBAA1 | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780378 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780394 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780382 | CHAMPION HEATING AND COOLING | TH16B2421 | CM30BBAA1 | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780402 | CHAMPION HEATING AND COOLING | TH16B2421 | CU30BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780390 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BBAA1 | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780418 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780386 | CHAMPION HEATING AND COOLING | TH16B2421 | CU30BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780414 | CHAMPION HEATING AND COOLING | TH16B2421 | CF24BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780374 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BBAA1 | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780368 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780364 | CHAMPION HEATING AND COOLING | TH16B2421 | CF30BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780352 | CHAMPION HEATING AND COOLING | TH16B2421 | CU36BXA1+TXV | TP9C080B12MP13 | 15,100 | $755 |
| No | 206780344 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BXA1+TXV | TP9C080B12MP13 | 15,100 | $755 |
| No | 206780340 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BBAA1 | TP9C080B12MP13 | 15,100 | $755 |
| No | 206780348 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BBAA1 | TP9C080B12MP13 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780336 | CHAMPION HEATING AND COOLING | TH16B2421 | CU36BXA1+TXV | TM9V080B12MP12 | 15,100 | $755 |
| No | 206780332 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BBAA1 | TM9V080B12MP12 | 15,100 | $755 |
| No | 206780328 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36BXA1+TXV | TM9V080B12MP12 | 15,100 | $755 |
| No | 206780324 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BBAA1 | TM9V080B12MP12 | 15,100 | $755 |
| No | 206780318 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BXA1+TXV | TP9C080B12MP13 | 15,100 | $755 |
| No | 206780314 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36BXA1+TXV | TM9V080B12MP12 | 15,100 | $755 |
| No | 206779938 | CHAMPION HEATING AND COOLING | TH16B2421 | CU36CXA1+TXV | TP9C080C16MP13 | 15,100 | $755 |
| No | 206779934 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36CXA1+TXV | TP9C080C16MP13 | 15,100 | $755 |
| No | 206779930 | CHAMPION HEATING AND COOLING | TH16B2421 | CU36CXA1+TXV | TM9V080C16MP12 | 15,100 | $755 |
| No | 206779926 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36CXA1+TXV | TM9V080C16MP12 | 15,100 | $755 |
| No | 206779920 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36CXA1+TXV | TP9C080C16MP13 | 15,100 | $755 |
| No | 206779916 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36CXA1+TXV | TM9V080C16MP12 | 15,100 | $755 |
| No | 206780458 | CHAMPION HEATING AND COOLING | TH16B2421 | CU36CXA1+TXV | TP9C100C16MP13 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780454 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36CXA1+TXV | TP9C100C16MP13 | 15,100 | $755 |
| No | 206780450 | CHAMPION HEATING AND COOLING | TH16B2421 | CU36CXA1+TXV | TM9V100C16MP12 | 15,100 | $755 |
| No | 206780446 | CHAMPION HEATING AND COOLING | TH16B2421 | CM36CXA1+TXV | TM9V100C16MP12 | 15,100 | $755 |
| No | 206780440 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36CXA1+TXV | TP9C100C16MP13 | 15,100 | $755 |
| No | 206780436 | CHAMPION HEATING AND COOLING | TH16B2421 | CF36CXA1+TXV | TM9V100C16MP12 | 15,100 | $755 |
| No | 206782642 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TP9C100C16MP13 | 32,600 | $1,630 |
| No | 206782638 | CHAMPION HEATING AND COOLING | TH16B6021 | CM64DXA1+TXV | TM9V100C16MP12 | 32,600 | $1,630 |
| No | 206782632 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TP9C100C16MP13 | 32,600 | $1,630 |
| No | 206781770 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1+MVC14DN21 | | 28,000 | $1,400 |
| No | 206781766 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+MVC14DN21+TXV | | 28,000 | $1,400 |
| No | 206782628 | CHAMPION HEATING AND COOLING | TH16B6021 | CF64DXA1+TXV | TM9V100C16MP12 | 32,600 | $1,630 |
| No | 206781762 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+MVC14DN21+TXV | | 28,000 | $1,400 |
| No | 206781544 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DBCA1+MVC20DN21 | | 27,800 | $1,390 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781540 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48DXA1+MVC20DN21+TXV | | 27,800 | $1,390 |
| No | 206781536 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48DXA1+MVC20DN21+TXV | | 27,800 | $1,390 |
| No | 206781260 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+MVC20DN21+TXV | | 29,800 | $1,490 |
| No | 9036785 | CHAMPION HEATING AND COOLING | TH16B4821 | AVC48DX21+TXV | | 28,200 | $1,410 |
| No | 206781256 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+MVC20DN21+TXV | | 29,800 | $1,490 |
| No | 206781421 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TPLC100C16MP13 | 29,000 | $1,450 |
| No | 206781417 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TPLC080C16MP13 | 29,000 | $1,450 |
| No | 206781413 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TMLV100C16MP12 | 29,000 | $1,450 |
| No | 206781409 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TM8V080C16MP12 | 29,000 | $1,450 |
| No | 206781405 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TM8V100C16MP12 | 29,000 | $1,450 |
| No | 206781397 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TPLC100C16MP13 | 29,000 | $1,450 |
| No | 206781393 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TPLC080C16MP13 | 29,000 | $1,450 |
| No | 206781389 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TMLV100C16MP12 | 29,000 | $1,450 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781385 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TM8V080C16MP12 | 29,000 | $1,450 |
| No | 206781381 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TM8V100C16MP12 | 29,000 | $1,450 |
| No | 206781485 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TPLC120C20MP13 | 28,000 | $1,400 |
| No | 206781481 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TPLC120C20MP13 | 28,000 | $1,400 |
| No | 206781477 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TPLC120C20MP13 | 28,000 | $1,400 |
| No | 206781473 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TPLC100C20MP13 | 28,000 | $1,400 |
| No | 202100752 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TPLC120C20MP13 | 28,000 | $1,400 |
| No | 206781469 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TPLC100C20MP13 | 28,000 | $1,400 |
| No | 206781465 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TPLC100C20MP13 | 28,000 | $1,400 |
| No | 202100747 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TPLC100C20MP13 | 28,000 | $1,400 |
| No | 206781461 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TMLV120C20MP12 | 28,000 | $1,400 |
| No | 206781457 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TMLV120C20MP12 | 28,000 | $1,400 |
| No | 202100713 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TMLV120C20MP12 | 28,000 | $1,400 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781437 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TM8V100C20MP12 | 28,000 | $1,400 |
| No | 206781453 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TMLV120C20MP12 | 28,000 | $1,400 |
| No | 206781433 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TM8V100C20MP12 | 28,000 | $1,400 |
| No | 206781429 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TM8V100C20MP12 | 28,000 | $1,400 |
| No | 202100666 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TM8V100C20MP12 | 28,000 | $1,400 |
| No | 206781449 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TM8V120C20MP12 | 28,000 | $1,400 |
| No | 206781445 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TM8V120C20MP12 | 28,000 | $1,400 |
| No | 206781441 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TM8V120C20MP12 | 28,000 | $1,400 |
| No | 202100673 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TM8V120C20MP12 | 28,000 | $1,400 |
| No | 206781368 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TPLC120C20MP13 | 28,000 | $1,400 |
| No | 206781364 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TPLC100C20MP13 | 28,000 | $1,400 |
| No | 206781360 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TMLV120C20MP12 | 28,000 | $1,400 |
| No | 206781356 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TM8V100C20MP12 | 28,000 | $1,400 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781352 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TM8V120C20MP12 | 28,000 | $1,400 |
| No | 206781706 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TP9C100C16MP13 | 29,200 | $1,460 |
| No | 206781702 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TM9V100C16MP12 | 29,200 | $1,460 |
| No | 206781696 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TP9C100C16MP13 | 29,200 | $1,460 |
| No | 206781692 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TM9V100C16MP12 | 29,200 | $1,460 |
| No | 206782544 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TP9C100C20MP13 | 28,400 | $1,420 |
| No | 206782540 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TP9C100C20MP13 | 28,400 | $1,420 |
| No | 206782548 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TP9C100C20MP13 | 28,400 | $1,420 |
| No | 202100730 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TP9C100C20MP13 | 28,400 | $1,420 |
| No | 206782536 | CHAMPION HEATING AND COOLING | TH16B4821 | CU48CXA1+TXV | TM9V100C20MP12 | 28,400 | $1,420 |
| No | 206782528 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CXA1+TXV | TM9V100C20MP12 | 28,400 | $1,420 |
| No | 206782532 | CHAMPION HEATING AND COOLING | TH16B4821 | CM48CBCA1 | TM9V100C20MP12 | 28,400 | $1,420 |
| No | 202100693 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CBCA1 | TM9V100C20MP12 | 28,400 | $1,420 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782522 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TP9C100C20MP13 | 28,400 | $1,420 |
| No | 206782518 | CHAMPION HEATING AND COOLING | TH16B4821 | CF48CXA1+TXV | TM9V100C20MP12 | 28,400 | $1,420 |
| No | 206781522 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TP9C100C20MP13 | 29,000 | $1,450 |
| No | 206781518 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TM9V100C20MP12 | 29,000 | $1,450 |
| No | 206781512 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TP9C100C20MP13 | 29,000 | $1,450 |
| No | 206781508 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TM9V100C20MP12 | 29,000 | $1,450 |
| No | 205545160 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TM8Y080C16MP11 | 29,400 | $1,470 |
| No | 205545153 | CHAMPION HEATING AND COOLING | TH16B4821 | CM64DXA1+TXV | TM8Y100C16MP11 | 29,400 | $1,470 |
| No | 205545110 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TM8Y080C16MP11 | 29,400 | $1,470 |
| No | 205545104 | CHAMPION HEATING AND COOLING | TH16B4821 | CF64DXA1+TXV | TM8Y100C16MP11 | 29,400 | $1,470 |
| No | 206921726 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36BXA1+TXV | TM9E040A10MP12 | 14,500 | $725 |
| No | 206921730 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36BBAA1 | TM9E040A10MP12 | 14,500 | $725 |
| No | 206921734 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36BXA1+TXV | TM9E040A10MP12 | 14,500 | $725 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921738 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36BBAA1 | TM9E040A10MP12 | 14,500 | $725 |
| No | 206921742 | CHAMPION HEATING AND COOLING | HMH72B241 | CU36BXA1+TXV | TM9E040A10MP12 | 14,500 | $725 |
| No | 207335191 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36AXA1+TXV | TM8Y060A12MP11 | 14,200 | $710 |
| No | 207335190 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36AXA1+TXV | TM8Y060A12MP11 | 14,200 | $710 |
| No | 207335194 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36BXA1+TXV | TM8Y060A12MP11 | 14,300 | $715 |
| No | 207335196 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36BBAA1 | TM8Y060A12MP11 | 14,300 | $715 |
| No | 207335195 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36BXA1+TXV | TM8Y060A12MP11 | 14,300 | $715 |
| No | 207335193 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36BBAA1 | TM8Y060A12MP11 | 14,300 | $715 |
| No | 207335192 | CHAMPION HEATING AND COOLING | HMH72B241 | CU36BXA1+TXV | TM8Y060A12MP11 | 14,300 | $715 |
| No | 207175990 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36CXA1+TXV | TM9Y060B12MP11 | 14,500 | $725 |
| No | 207175994 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36CXA1+TXV | TM9Y060B12MP11 | 14,500 | $725 |
| No | 206921618 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36CXA1+TXV | TM9V060B12MP12 | 14,500 | $725 |
| No | 206921622 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36CXA1+TXV | TP9C060B12MP13 | 14,500 | $725 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921628 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36CXA1+TXV | TM9V060B12MP12 | 14,500 | $725 |
| No | 206921636 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36CXA1+TXV | TP9C060B12MP13 | 14,500 | $725 |
| No | 207335203 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36CXA1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207335202 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36CXA1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207335201 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36BXA1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207335200 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36BBAA1 | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207335199 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36BXA1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207335198 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36BBAA1 | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207335197 | CHAMPION HEATING AND COOLING | HMH72B241 | CU36BXA1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 206921568 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36BXA1+TXV | TM9V080B12MP12 | 14,400 | $720 |
| No | 206921572 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36BXA1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 206921578 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36BBAA1 | TM9V080B12MP12 | 14,400 | $720 |
| No | 206921582 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36BXA1+TXV | TM9V080B12MP12 | 14,400 | $720 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921586 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36BBAA1 | TM9V080B12MP12 | 14,400 | $720 |
| No | 206921598 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36BXA1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 206921590 | CHAMPION HEATING AND COOLING | HMH72B241 | CU36BXA1+TXV | TM9V080B12MP12 | 14,400 | $720 |
| No | 206921594 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36BBAA1 | TP9C080B12MP13 | 14,400 | $720 |
| No | 206921602 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36BBAA1 | TP9C080B12MP13 | 14,400 | $720 |
| No | 206921606 | CHAMPION HEATING AND COOLING | HMH72B241 | CU36BXA1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 207251150 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TM9E100C16MP12 | 31,000 | $1,550 |
| No | 207251152 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TM9E100C16MP12 | 31,000 | $1,550 |
| No | 206971551 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TM9V080C16MP12 | 30,800 | $1,540 |
| No | 206971541 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TM9V080C16MP12 | 30,800 | $1,540 |
| No | 206971545 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TP9C080C16MP13 | 30,800 | $1,540 |
| No | 206971555 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TP9C080C16MP13 | 30,800 | $1,540 |
| No | 207176158 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TM9Y100C16MP11 | 30,200 | $1,510 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207176162 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TM9Y100C16MP11 | 30,200 | $1,510 |
| No | 206921538 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36CXA1+TXV | TM9V080B12MP12 | 14,300 | $715 |
| No | 206921542 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36CXA1+TXV | TP9C080B12MP13 | 14,300 | $715 |
| No | 206921548 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36CXA1+TXV | TM9V080B12MP12 | 14,300 | $715 |
| No | 206921556 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36CXA1+TXV | TP9C080B12MP13 | 14,300 | $715 |
| No | 207251154 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TM9E080C16MP12 | 31,200 | $1,560 |
| No | 207251156 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TM9E080C16MP12 | 31,200 | $1,560 |
| No | 206971671 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TL9E080C16UH11 | 29,600 | $1,480 |
| No | 206971675 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TL9E080C16UH11 | 29,600 | $1,480 |
| No | 206921782 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36CXA1+TXV | TM8V100C16MP12 | 14,300 | $715 |
| No | 206921786 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36CXA1+TXV | TM8V080C16MP12 | 14,300 | $715 |
| No | 206921790 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36CXA1+TXV | TMLV100C16MP12 | 14,300 | $715 |
| No | 206921794 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36CXA1+TXV | TPLC080C16MP13 | 14,300 | $715 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921798 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36CXA1+TXV | TPLC100C16MP13 | 14,300 | $715 |
| No | 206921806 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36CXA1+TXV | TM8V100C16MP12 | 14,300 | $715 |
| No | 206921814 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36CXA1+TXV | TM8V080C16MP12 | 14,300 | $715 |
| No | 206921822 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36CXA1+TXV | TMLV100C16MP12 | 14,300 | $715 |
| No | 206921830 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36CXA1+TXV | TPLC080C16MP13 | 14,300 | $715 |
| No | 207176166 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TM9Y080C16MP11 | 30,200 | $1,510 |
| No | 207176170 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TM9Y080C16MP11 | 30,200 | $1,510 |
| No | 206921838 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36CXA1+TXV | TPLC100C16MP13 | 14,300 | $715 |
| No | 207335304 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TM8Y080C16MP11 | 30,200 | $1,510 |
| No | 206971711 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TM8E100C16MP11 | 30,200 | $1,510 |
| No | 207335303 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TM8Y080C16MP11 | 30,200 | $1,510 |
| No | 206971703 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TM8E100C16MP11 | 30,200 | $1,510 |
| No | 206971707 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TMLE100C16MP11 | 30,200 | $1,510 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206971715 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TMLE100C16MP11 | 30,200 | $1,510 |
| No | 206971719 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TL8E080C16UH11 | 30,200 | $1,510 |
| No | 206971723 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TL8E080C16UH11 | 30,200 | $1,510 |
| No | 206971481 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TM9V100C16MP12 | 30,800 | $1,540 |
| No | 206971485 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TP9C100C16MP13 | 30,800 | $1,540 |
| No | 206971491 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TM9V100C16MP12 | 30,800 | $1,540 |
| No | 206971495 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TP9C100C16MP13 | 30,800 | $1,540 |
| No | 206971521 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TM9V100C20MP12 | 31,000 | $1,550 |
| No | 206971525 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TP9C100C20MP13 | 31,000 | $1,550 |
| No | 206971531 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TM9V100C20MP12 | 31,000 | $1,550 |
| No | 206971535 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TP9C100C20MP13 | 31,000 | $1,550 |
| No | 206971687 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TM8E120C16MP11 | 30,200 | $1,510 |
| No | 206971691 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TMLE120C16MP11 | 30,200 | $1,510 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206971695 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TM8E120C16MP11 | 30,200 | $1,510 |
| No | 206971699 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TMLE120C16MP11 | 30,200 | $1,510 |
| No | 206971655 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TM8E080C16MP11 | 30,200 | $1,510 |
| No | 206971659 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TMLE080C16MP11 | 30,200 | $1,510 |
| No | 206971663 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TM8E080C16MP11 | 30,200 | $1,510 |
| No | 206971667 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TMLE080C16MP11 | 30,200 | $1,510 |
| No | 206971607 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TM8V100C16MP12 | 29,600 | $1,480 |
| No | 206971611 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TM8V080C16MP12 | 29,600 | $1,480 |
| No | 206971615 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TMLV100C16MP12 | 29,600 | $1,480 |
| No | 206971619 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TPLC080C16MP13 | 29,600 | $1,480 |
| No | 206971623 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TPLC100C16MP13 | 29,600 | $1,480 |
| No | 206971631 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TM8V100C16MP12 | 29,600 | $1,480 |
| No | 206971635 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TM8V080C16MP12 | 29,600 | $1,480 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206971639 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TMLV100C16MP12 | 29,600 | $1,480 |
| No | 206971643 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TPLC080C16MP13 | 29,600 | $1,480 |
| No | 206971647 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TPLC100C16MP13 | 29,600 | $1,480 |
| No | 207176150 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TM9Y120D20MP11 | 30,600 | $1,530 |
| No | 207176154 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TM9Y120D20MP11 | 30,600 | $1,530 |
| No | 207335302 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TM8Y120C20MP11 | 29,800 | $1,490 |
| No | 207335299 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TM8Y100C20MP11 | 29,800 | $1,490 |
| No | 207335301 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TM8Y120C20MP11 | 29,800 | $1,490 |
| No | 207335300 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TM8Y100C20MP11 | 29,800 | $1,490 |
| No | 206971561 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TM8V120C20MP12 | 29,800 | $1,490 |
| No | 206971565 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TM8V100C20MP12 | 29,800 | $1,490 |
| No | 206971569 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TMLV120C20MP12 | 29,800 | $1,490 |
| No | 206971573 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TPLC100C20MP13 | 29,800 | $1,490 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206971577 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TPLC120C20MP13 | 29,800 | $1,490 |
| No | 206971584 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TM8V120C20MP12 | 29,800 | $1,490 |
| No | 206971588 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TM8V100C20MP12 | 29,800 | $1,490 |
| No | 206971592 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TMLV120C20MP12 | 29,800 | $1,490 |
| No | 206971596 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TPLC100C20MP13 | 29,800 | $1,490 |
| No | 206971505 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TP9C120D20MP13 | 30,800 | $1,540 |
| No | 206971600 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TPLC120C20MP13 | 29,800 | $1,490 |
| No | 206971501 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TM9V120D20MP12 | 30,800 | $1,540 |
| No | 206971511 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TM9V120D20MP12 | 30,800 | $1,540 |
| No | 206971683 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TL8E100C20UH11 | 30,000 | $1,500 |
| No | 206971515 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+TXV | TP9C120D20MP13 | 30,800 | $1,540 |
| No | 206971679 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+TXV | TL8E100C20UH11 | 30,000 | $1,500 |
| No | 206922360 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922364 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 206922370 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 206922530 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1 | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206922534 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206922538 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1 | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206922542 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36BXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206922834 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 206922838 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 206922843 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1 | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 206922847 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 206922851 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1 | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 206922855 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36BXA1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 206922859 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1 | TPLC080B12MP13 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922863 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 206922867 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1 | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 206922871 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36BXA1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 206922879 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+TXV | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 206922883 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+TXV | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 206922887 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+TXV | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 206922891 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1 | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 206922895 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+TXV | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 206922899 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1 | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 206922911 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+TXV | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 206922903 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36BXA1+TXV | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 206922907 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1 | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 206922916 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1 | TMLV060A12MP12 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922920 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36BXA1+TXV | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 206922924 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1 | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 206922928 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+TXV | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 206923405 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36AXA1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206922932 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1 | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 206922936 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36BXA1+TXV | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 206923409 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36AXA1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206923165 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 206923169 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 206923173 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1 | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 206923177 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 206923181 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1 | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 206923185 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36BXA1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206923189 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1 | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 206923193 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 206923197 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1 | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 206923201 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36BXA1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 206923205 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206923209 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206923213 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1 | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206923217 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206923221 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1 | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206923225 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36BXA1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206923229 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1 | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206923233 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206923237 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1 | TMLE060A12MP11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206923241 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36BXA1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206923385 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206923389 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1 | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206923393 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206923397 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1 | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206923401 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36BXA1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206922320 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1 | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 206922310 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+TXV | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 206922314 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+TXV | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922324 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+TXV | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 206922328 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1 | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 206922332 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36BXA1+TXV | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 206922336 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1 | TP9C080B12MP13 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922340 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+TXV | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922344 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1 | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922348 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36BXA1+TXV | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922510 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206922514 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206922518 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 207176078 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 207176086 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 207176082 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1 | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 207176090 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1 | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 207176094 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36BXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 206923028 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923032 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206923036 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923040 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923048 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923052 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 207176046 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TM9Y080C16MP11 | 24,600 | $1,230 |
| No | 207176114 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207176050 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TM9Y080C16MP11 | 24,600 | $1,230 |
| No | 207176054 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TM9Y080C16MP11 | 24,600 | $1,230 |
| No | 207176118 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1 | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207176122 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207176126 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1 | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207176130 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36BXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207335263 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207335265 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1 | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 207335268 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36BXA1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 207335264 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 207335269 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1 | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 206922562 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+TXV | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 206922566 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1 | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 206922570 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+TXV | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 206922574 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1 | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 206922578 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36BXA1+TXV | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 206922798 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TM8V080B12MP12 | 24,400 | $1,220 |
| No | 206922807 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TM8V080B12MP12 | 24,400 | $1,220 |
| No | 206922802 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TPLC080B12MP13 | 24,400 | $1,220 |
| No | 206922811 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TM8V080B12MP12 | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922819 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TPLC080B12MP13 | 24,400 | $1,220 |
| No | 206922823 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TPLC080B12MP13 | 24,400 | $1,220 |
| No | 206923060 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923064 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923072 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923068 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1 | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923076 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1 | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923081 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36BXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923085 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1 | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923089 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923093 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1 | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923097 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36BXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923133 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TM8E080B12MP11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206923137 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 206923141 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TM8E080B12MP11 | 24,600 | $1,230 |
| No | 206923145 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TM8E080B12MP11 | 24,600 | $1,230 |
| No | 206923157 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 206923153 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 206971315 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TM9V080C16MP12 | 38,000 | $1,900 |
| No | 206971319 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TP9C080C16MP13 | 38,000 | $1,900 |
| No | 206971325 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TM9V080C16MP12 | 38,000 | $1,900 |
| No | 206971329 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TP9C080C16MP13 | 38,000 | $1,900 |
| No | 207335266 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36AXA1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 207335267 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36AXA1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 206922450 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+TXV | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 206922454 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1 | TM9V040A10MP12 | 24,200 | $1,210 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922458 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+TXV | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 206922462 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1 | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 206922466 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36BXA1+TXV | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 206922602 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36AXA1+TXV | TM9E060A10MP12 | 24,200 | $1,210 |
| No | 206922606 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36AXA1+TXV | TM9E060A10MP12 | 24,200 | $1,210 |
| No | 206923301 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36AXA1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206923305 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36AXA1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 206923309 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36AXA1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206923313 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36AXA1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 207176098 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207176102 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207176106 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207335274 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+TXV | TM8Y080B12MP11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207335273 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1 | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 207335272 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+TXV | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 207335271 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1 | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 207335270 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36BXA1+TXV | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 207176062 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 207176066 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 207176070 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 206922230 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TM9V080C16MP12 | 24,400 | $1,220 |
| No | 206922234 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TP9C080C16MP13 | 24,400 | $1,220 |
| No | 206922240 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TM9V080C16MP12 | 24,400 | $1,220 |
| No | 206922244 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TM9V080C16MP12 | 24,400 | $1,220 |
| No | 206922252 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TP9C080C16MP13 | 24,400 | $1,220 |
| No | 206922494 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TM9E080C16MP12 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922256 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TP9C080C16MP13 | 24,400 | $1,220 |
| No | 206922498 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TM9E080C16MP12 | 24,600 | $1,230 |
| No | 206922502 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TM9E080C16MP12 | 24,600 | $1,230 |
| No | 206923317 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TL9E080C16UH11 | 24,600 | $1,230 |
| No | 206923321 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TL9E080C16UH11 | 24,600 | $1,230 |
| No | 206923325 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TL9E080C16UH11 | 24,600 | $1,230 |
| No | 206922400 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+TXV | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 206922404 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+TXV | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922410 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1 | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 206922414 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+TXV | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 206922418 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1 | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 206922422 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36BXA1+TXV | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 206922430 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+TXV | TP9C060B12MP13 | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922426 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1 | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922434 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1 | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922438 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36BXA1+TXV | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922702 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 206922706 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TM8V080C16MP12 | 24,600 | $1,230 |
| No | 206922710 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TMLV100C16MP12 | 24,600 | $1,230 |
| No | 206922714 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TPLC080C16MP13 | 24,600 | $1,230 |
| No | 206922718 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 206922726 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 206922730 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 206922738 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TM8V080C16MP12 | 24,600 | $1,230 |
| No | 206922742 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TM8V080C16MP12 | 24,600 | $1,230 |
| No | 206922750 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TMLV100C16MP12 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922754 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TMLV100C16MP12 | 24,600 | $1,230 |
| No | 206922762 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TPLC080C16MP13 | 24,600 | $1,230 |
| No | 206922766 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TPLC080C16MP13 | 24,600 | $1,230 |
| No | 206922774 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 206922778 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 206923261 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206923265 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 206923269 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1 | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206923273 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206923277 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1 | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206923289 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 206923281 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36BXA1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206923285 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1 | TMLE040A12MP11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206923293 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1 | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 206923297 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36BXA1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 206923349 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+TXV | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 206923353 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1 | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 206923357 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+TXV | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 206923361 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1 | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 206922614 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TM8V100C20MP12 | 24,600 | $1,230 |
| No | 206923365 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36BXA1+TXV | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 206922610 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TM8V120C20MP12 | 24,600 | $1,230 |
| No | 206922618 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TMLV120C20MP12 | 24,600 | $1,230 |
| No | 206922622 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TPLC100C20MP13 | 24,600 | $1,230 |
| No | 206922626 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TPLC120C20MP13 | 24,600 | $1,230 |
| No | 206922633 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TM8V120C20MP12 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922637 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TM8V120C20MP12 | 24,600 | $1,230 |
| No | 206922645 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TM8V100C20MP12 | 24,600 | $1,230 |
| No | 206922649 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TM8V100C20MP12 | 24,600 | $1,230 |
| No | 206922657 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TMLV120C20MP12 | 24,600 | $1,230 |
| No | 206922661 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TMLV120C20MP12 | 24,600 | $1,230 |
| No | 206922669 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TPLC100C20MP13 | 24,600 | $1,230 |
| No | 206922673 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TPLC100C20MP13 | 24,600 | $1,230 |
| No | 206922681 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TPLC120C20MP13 | 24,600 | $1,230 |
| No | 206922685 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TPLC120C20MP13 | 24,600 | $1,230 |
| No | 206922478 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TM9E100C16MP12 | 24,600 | $1,230 |
| No | 206922482 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TM9E100C16MP12 | 24,600 | $1,230 |
| No | 207335326 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TM8Y080C16MP11 | 38,000 | $1,900 |
| No | 206922486 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TM9E100C16MP12 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207335325 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TM8Y080C16MP11 | 38,000 | $1,900 |
| No | 206971407 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TL8E080C16UH11 | 38,000 | $1,900 |
| No | 207335277 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 206971411 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TL8E080C16UH11 | 38,000 | $1,900 |
| No | 207335275 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 207335276 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 206922270 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 206922274 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 206922280 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 206922284 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 206922292 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 206922296 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 206922150 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TM9V100C20MP12 | 24,400 | $1,220 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922154 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TP9C100C20MP13 | 24,400 | $1,220 |
| No | 206922164 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TM9V100C20MP12 | 24,400 | $1,220 |
| No | 206922160 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TM9V100C20MP12 | 24,400 | $1,220 |
| No | 206922172 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TP9C100C20MP13 | 24,400 | $1,220 |
| No | 206922176 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TP9C100C20MP13 | 24,400 | $1,220 |
| No | 206922964 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TM8E120C16MP11 | 24,600 | $1,230 |
| No | 206922968 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TMLE120C16MP11 | 24,600 | $1,230 |
| No | 206922972 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TM8E120C16MP11 | 24,600 | $1,230 |
| No | 206922976 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TM8E120C16MP11 | 24,600 | $1,230 |
| No | 206922984 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TMLE120C16MP11 | 24,600 | $1,230 |
| No | 206922988 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TMLE120C16MP11 | 24,600 | $1,230 |
| No | 206923008 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TM8E100C16MP11 | 24,600 | $1,230 |
| No | 206922996 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TM8E100C16MP11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206923000 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TMLE100C16MP11 | 24,600 | $1,230 |
| No | 206923004 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TM8E100C16MP11 | 24,600 | $1,230 |
| No | 206923016 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TMLE100C16MP11 | 24,600 | $1,230 |
| No | 206923020 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TMLE100C16MP11 | 24,600 | $1,230 |
| No | 206971211 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TM9V100C20MP12 | 38,000 | $1,900 |
| No | 206971215 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TP9C100C20MP13 | 38,000 | $1,900 |
| No | 206971221 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TM9V100C20MP12 | 38,000 | $1,900 |
| No | 206971225 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TP9C100C20MP13 | 38,000 | $1,900 |
| No | 206971311 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TMLE100C16MP11 | 38,000 | $1,900 |
| No | 206971299 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TM8E100C16MP11 | 38,000 | $1,900 |
| No | 206971303 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TMLE100C16MP11 | 38,000 | $1,900 |
| No | 206971307 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TM8E100C16MP11 | 38,000 | $1,900 |
| No | 206971375 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TM8E080C16MP11 | 38,000 | $1,900 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206971379 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TMLE080C16MP11 | 38,000 | $1,900 |
| No | 206971383 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TM8E080C16MP11 | 38,000 | $1,900 |
| No | 206971387 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TMLE080C16MP11 | 38,000 | $1,900 |
| No | 206922470 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36AXA1+TXV | TM9V040A10MP12 | 24,000 | $1,200 |
| No | 206922474 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36AXA1+TXV | TM9V040A10MP12 | 24,000 | $1,200 |
| No | 206922940 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36AXA1+TXV | TM8V060A12MP12 | 24,200 | $1,210 |
| No | 206922944 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36AXA1+TXV | TMLV060A12MP12 | 24,200 | $1,210 |
| No | 206922948 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36AXA1+TXV | TPLC060A12MP13 | 24,200 | $1,210 |
| No | 206922952 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36AXA1+TXV | TM8V060A12MP12 | 24,200 | $1,210 |
| No | 206922956 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36AXA1+TXV | TMLV060A12MP12 | 24,200 | $1,210 |
| No | 206922960 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36AXA1+TXV | TPLC060A12MP13 | 24,200 | $1,210 |
| No | 206922190 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TM9V100C16MP12 | 24,400 | $1,220 |
| No | 206922194 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TP9C100C16MP13 | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922200 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TM9V100C16MP12 | 24,400 | $1,220 |
| No | 206922204 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TM9V100C16MP12 | 24,400 | $1,220 |
| No | 206922212 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TP9C100C16MP13 | 24,400 | $1,220 |
| No | 206922216 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TP9C100C16MP13 | 24,400 | $1,220 |
| No | 206971267 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TM8E120C16MP11 | 38,000 | $1,900 |
| No | 206971279 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TMLE120C16MP11 | 38,000 | $1,900 |
| No | 206971271 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TMLE120C16MP11 | 38,000 | $1,900 |
| No | 206971275 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TM8E120C16MP11 | 38,000 | $1,900 |
| No | 207176134 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TM9Y120D20MP11 | 38,000 | $1,900 |
| No | 207176138 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TM9Y120D20MP11 | 38,000 | $1,900 |
| No | 206923101 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TM8E080C16MP11 | 24,400 | $1,220 |
| No | 206923105 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TMLE080C16MP11 | 24,400 | $1,220 |
| No | 206923109 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TM8E080C16MP11 | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206923113 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TM8E080C16MP11 | 24,400 | $1,220 |
| No | 206923121 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TMLE080C16MP11 | 24,400 | $1,220 |
| No | 206923125 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TMLE080C16MP11 | 24,400 | $1,220 |
| No | 206971231 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TM9V100C16MP12 | 38,000 | $1,900 |
| No | 206971235 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TP9C100C16MP13 | 38,000 | $1,900 |
| No | 206971241 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TM9V100C16MP12 | 38,000 | $1,900 |
| No | 206971245 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TP9C100C16MP13 | 38,000 | $1,900 |
| No | 206971335 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TM9E120D20MP12 | 38,500 | $1,925 |
| No | 206971339 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TM9E120D20MP12 | 38,500 | $1,925 |
| No | 206971415 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TM8V120C20MP12 | 39,000 | $1,950 |
| No | 206971419 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TM8V100C20MP12 | 39,000 | $1,950 |
| No | 206971423 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TMLV120C20MP12 | 39,000 | $1,950 |
| No | 206971427 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TPLC100C20MP13 | 39,000 | $1,950 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206971431 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TPLC120C20MP13 | 39,000 | $1,950 |
| No | 206971438 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TM8V120C20MP12 | 39,000 | $1,950 |
| No | 206971442 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TM8V100C20MP12 | 39,000 | $1,950 |
| No | 206971446 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TMLV120C20MP12 | 39,000 | $1,950 |
| No | 206971450 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TPLC100C20MP13 | 39,000 | $1,950 |
| No | 206971454 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TPLC120C20MP13 | 39,000 | $1,950 |
| No | 207176142 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TM9Y100C20MP11 | 38,000 | $1,900 |
| No | 207176146 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TM9Y100C20MP11 | 38,000 | $1,900 |
| No | 206971283 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TM8E100C20MP11 | 38,500 | $1,925 |
| No | 206971287 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TMLE100C20MP11 | 38,500 | $1,925 |
| No | 206971291 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TM8E100C20MP11 | 38,500 | $1,925 |
| No | 206971295 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TMLE100C20MP11 | 38,500 | $1,925 |
| No | 207176030 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TM9Y100C16MP11 | 24,200 | $1,210 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207176034 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TM9Y100C16MP11 | 24,200 | $1,210 |
| No | 207176038 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TM9Y100C16MP11 | 24,200 | $1,210 |
| No | 206971391 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TL9E100C20UH11 | 38,000 | $1,900 |
| No | 206971395 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TL9E100C20UH11 | 38,000 | $1,900 |
| No | 206971343 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TM9E100C20MP12 | 38,500 | $1,925 |
| No | 206971347 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TM9E100C20MP12 | 38,500 | $1,925 |
| No | 206971399 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TL8E100C20UH11 | 38,000 | $1,900 |
| No | 206971403 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TL8E100C20UH11 | 38,000 | $1,900 |
| No | 206971351 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TM9E080C20MP12 | 38,500 | $1,925 |
| No | 206971355 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TM9E080C20MP12 | 38,500 | $1,925 |
| No | 206971191 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TM9V120D20MP12 | 39,000 | $1,950 |
| No | 206971195 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TP9C120D20MP13 | 39,000 | $1,950 |
| No | 206971201 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TM9V120D20MP12 | 39,000 | $1,950 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206971205 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TP9C120D20MP13 | 39,000 | $1,950 |
| No | 207335327 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TM8Y100C20MP11 | 37,800 | $1,890 |
| No | 207335324 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TM8Y120C20MP11 | 37,800 | $1,890 |
| No | 207335323 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TM8Y120C20MP11 | 37,800 | $1,890 |
| No | 207335328 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TM8Y100C20MP11 | 37,800 | $1,890 |
| No | 206971251 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TM8E120C20MP11 | 37,600 | $1,880 |
| No | 206971255 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TMLE120C20MP11 | 37,600 | $1,880 |
| No | 206971259 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TM8E120C20MP11 | 37,600 | $1,880 |
| No | 206971263 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TMLE120C20MP11 | 37,600 | $1,880 |
| No | 207335280 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TM8Y080C16MP11 | 24,200 | $1,210 |
| No | 206923373 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TL8E080C16UH11 | 24,000 | $1,200 |
| No | 207335279 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TM8Y080C16MP11 | 24,200 | $1,210 |
| No | 207335278 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TM8Y080C16MP11 | 24,200 | $1,210 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206923369 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TL8E080C16UH11 | 24,000 | $1,200 |
| No | 206923377 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TL8E080C16UH11 | 24,000 | $1,200 |
| No | 206971359 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TM8E080C20MP11 | 37,800 | $1,890 |
| No | 206971363 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+TXV | TMLE080C20MP11 | 37,800 | $1,890 |
| No | 206922382 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 206971367 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TM8E080C20MP11 | 37,800 | $1,890 |
| No | 206971371 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+TXV | TMLE080C20MP11 | 37,800 | $1,890 |
| No | 206922374 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 206922386 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 206922546 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 206922550 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 206922554 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 206923333 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+TXV | TL9E060B12UH11 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206923337 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+TXV | TL9E060B12UH11 | 24,800 | $1,240 |
| No | 206923341 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1 | TL9E060B12UH11 | 24,800 | $1,240 |
| No | 206922582 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+TXV | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 206922586 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1 | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 206922590 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+TXV | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 206922594 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1 | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 206922598 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36BXA1+TXV | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 206923245 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36AXA1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206923249 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36AXA1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206923253 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36AXA1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206923257 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36AXA1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206922526 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 207176110 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206923509 | CHAMPION HEATING AND COOLING | HMH72B361 | AE36BX21+TXV | | 24,400 | $1,220 |
| No | 206971743 | CHAMPION HEATING AND COOLING | HMH72B481 | AVC60DX21+TXV | | 30,600 | $1,530 |
| No | 206971747 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+ME14DN21+TXV | | 30,000 | $1,500 |
| No | 206971751 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+ME14DN21+TXV | | 30,000 | $1,500 |
| No | 207175998 | CHAMPION HEATING AND COOLING | HMH72B241 | CU36CXA1+TXV | TM9Y060B12MP11 | 14,500 | $725 |
| No | 207176022 | CHAMPION HEATING AND COOLING | HMH72B241 | AE36BX21+TXV | | 14,300 | $715 |
| No | 207176026 | CHAMPION HEATING AND COOLING | HMH72B241 | AE36BBA21 | | 14,300 | $715 |
| No | 207176042 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TM9Y100C16MP11 | 24,200 | $1,210 |
| No | 207176058 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TM9Y080C16MP11 | 24,600 | $1,230 |
| No | 207176074 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 206922248 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TM9V080C16MP12 | 24,400 | $1,220 |
| No | 206922260 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TP9C080C16MP13 | 24,400 | $1,220 |
| No | 206922288 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TM9V080B12MP12 | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922300 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 206922378 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 206922390 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 206922506 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TM9E080C16MP12 | 24,600 | $1,230 |
| No | 206923345 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TL9E060B12UH11 | 24,800 | $1,240 |
| No | 206923381 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TL8E080C16UH11 | 24,000 | $1,200 |
| No | 206923413 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+MVC16CN21+TXV | | 24,200 | $1,210 |
| No | 206923417 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+MVC16CN21+TXV | | 24,200 | $1,210 |
| No | 206923421 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1+MVC16CN21 | | 24,200 | $1,210 |
| No | 206923425 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+MVC12CN21+TXV | | 24,000 | $1,200 |
| No | 206923429 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+MVC12CN21+TXV | | 24,000 | $1,200 |
| No | 206923433 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1+MVC12CN21 | | 24,000 | $1,200 |
| No | 206921632 | CHAMPION HEATING AND COOLING | HMH72B241 | CU36CXA1+TXV | TM9V060B12MP12 | 14,500 | $725 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921640 | CHAMPION HEATING AND COOLING | HMH72B241 | CU36CXA1+TXV | TP9C060B12MP13 | 14,500 | $725 |
| No | 206922130 | CHAMPION HEATING AND COOLING | HMH72B241 | AVC36BX21+TXV | | 14,300 | $715 |
| No | 206922641 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TM8V120C20MP12 | 24,600 | $1,230 |
| No | 206922653 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TM8V100C20MP12 | 24,600 | $1,230 |
| No | 206922665 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TMLV120C20MP12 | 24,600 | $1,230 |
| No | 206922677 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TPLC100C20MP13 | 24,600 | $1,230 |
| No | 206922689 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TPLC120C20MP13 | 24,600 | $1,230 |
| No | 206922734 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 206922746 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TM8V080C16MP12 | 24,600 | $1,230 |
| No | 206922758 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TMLV100C16MP12 | 24,600 | $1,230 |
| No | 206922770 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TPLC080C16MP13 | 24,600 | $1,230 |
| No | 206922782 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 206922980 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TM8E120C16MP11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922992 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TMLE120C16MP11 | 24,600 | $1,230 |
| No | 206923012 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TM8E100C16MP11 | 24,600 | $1,230 |
| No | 206923024 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TMLE100C16MP11 | 24,600 | $1,230 |
| No | 206923044 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923056 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923117 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TM8E080C16MP11 | 24,400 | $1,220 |
| No | 206923129 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TMLE080C16MP11 | 24,400 | $1,220 |
| No | 206923161 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 206923149 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TM8E080B12MP11 | 24,600 | $1,230 |
| No | 206923477 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+ME12BN21+TXV | | 24,400 | $1,220 |
| No | 206923481 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1+ME12BN21 | | 24,400 | $1,220 |
| No | 206923485 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+ME12BN21+TXV | | 24,400 | $1,220 |
| No | 206923489 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1+ME12BN21 | | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206923493 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+ME08BN21+TXV | | 23,600 | $1,180 |
| No | 206924357 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1+ME08BN21 | | 23,600 | $1,180 |
| No | 206923497 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+ME08BN21+TXV | | 23,600 | $1,180 |
| No | 206924361 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1+ME08BN21 | | 23,600 | $1,180 |
| No | 206923501 | CHAMPION HEATING AND COOLING | HMH72B361 | AVC36CX21+TXV | | 24,200 | $1,210 |
| No | 206923505 | CHAMPION HEATING AND COOLING | HMH72B361 | AVC36BX21+TXV | | 24,600 | $1,230 |
| No | 206921810 | CHAMPION HEATING AND COOLING | HMH72B241 | CU36CXA1+TXV | TM8V100C16MP12 | 14,300 | $715 |
| No | 206921818 | CHAMPION HEATING AND COOLING | HMH72B241 | CU36CXA1+TXV | TM8V080C16MP12 | 14,300 | $715 |
| No | 206921826 | CHAMPION HEATING AND COOLING | HMH72B241 | CU36CXA1+TXV | TMLV100C16MP12 | 14,300 | $715 |
| No | 206921834 | CHAMPION HEATING AND COOLING | HMH72B241 | CU36CXA1+TXV | TPLC080C16MP13 | 14,300 | $715 |
| No | 206921842 | CHAMPION HEATING AND COOLING | HMH72B241 | CU36CXA1+TXV | TPLC100C16MP13 | 14,300 | $715 |
| No | 206922110 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36CXA1+ME12CN21+TXV | | 14,200 | $710 |
| No | 206922114 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36CXA1+ME12CN21+TXV | | 14,200 | $710 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922168 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TM9V100C20MP12 | 24,400 | $1,220 |
| No | 206922180 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TP9C100C20MP13 | 24,400 | $1,220 |
| No | 206922208 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TM9V100C16MP12 | 24,400 | $1,220 |
| No | 206922220 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TP9C100C16MP13 | 24,400 | $1,220 |
| No | 206922490 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TM9E100C16MP12 | 24,600 | $1,230 |
| No | 206922522 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206922558 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 206923329 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TL9E080C16UH11 | 24,600 | $1,230 |
| No | 206923437 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BXA1+MVC12BN21+TXV | | 24,400 | $1,220 |
| No | 206923441 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36BBCA1+MVC12BN21 | | 24,400 | $1,220 |
| No | 206923445 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BXA1+MVC12BN21+TXV | | 24,400 | $1,220 |
| No | 206923449 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36BBCA1+MVC12BN21 | | 24,400 | $1,220 |
| No | 206921552 | CHAMPION HEATING AND COOLING | HMH72B241 | CU36CXA1+TXV | TM9V080B12MP12 | 14,300 | $715 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921560 | CHAMPION HEATING AND COOLING | HMH72B241 | CU36CXA1+TXV | TP9C080B12MP13 | 14,300 | $715 |
| No | 206922126 | CHAMPION HEATING AND COOLING | HMH72B241 | AVC36CX21+TXV | | 14,200 | $710 |
| No | 206922815 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TM8V080B12MP12 | 24,400 | $1,220 |
| No | 206922827 | CHAMPION HEATING AND COOLING | HMH72B361 | CU36CXA1+TXV | TPLC080B12MP13 | 24,400 | $1,220 |
| No | 206923453 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+ME16CN21+TXV | | 23,800 | $1,190 |
| No | 206923457 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+ME16CN21+TXV | | 23,800 | $1,190 |
| No | 206923461 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1+ME16CN21 | | 23,800 | $1,190 |
| No | 206923465 | CHAMPION HEATING AND COOLING | HMH72B361 | CF36CXA1+ME12CN21+TXV | | 24,200 | $1,210 |
| No | 206923469 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CXA1+ME12CN21+TXV | | 24,200 | $1,210 |
| No | 206923473 | CHAMPION HEATING AND COOLING | HMH72B361 | CM36CBCA1+ME12CN21 | | 24,200 | $1,210 |
| No | 206922086 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36CXA1+MVC12CN21+TXV | | 14,200 | $710 |
| No | 206922090 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36CXA1+MVC12CN21+TXV | | 14,200 | $710 |
| No | 206922094 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36BXA1+MVC12BN21+TXV | | 14,300 | $715 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922098 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36BBAA1+MVC12BN21 | | 14,300 | $715 |
| No | 206922102 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36BXA1+MVC12BN21+TXV | | 14,300 | $715 |
| No | 206922106 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36BBAA1+MVC12BN21 | | 14,300 | $715 |
| No | 206922134 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36BXA1+ME08BN21+TXV | | 14,100 | $705 |
| No | 206922138 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36BBAA1+ME08BN21 | | 14,100 | $705 |
| No | 206922142 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36BXA1+ME08BN21+TXV | | 14,100 | $705 |
| No | 206922146 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36BBAA1+ME08BN21 | | 14,100 | $705 |
| No | 206971731 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+MVC20DN21+TXV | | 30,200 | $1,510 |
| No | 206971727 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+MVC20DN21+TXV | | 30,200 | $1,510 |
| No | 206971461 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+MVC20DN21+TXV | | 39,000 | $1,950 |
| No | 206971465 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+MVC20DN21+TXV | | 39,000 | $1,950 |
| No | 206971469 | CHAMPION HEATING AND COOLING | HMH72B601 | CF64DXA1+ME20DN21+TXV | | 39,000 | $1,950 |
| No | 206971473 | CHAMPION HEATING AND COOLING | HMH72B601 | CM64DXA1+ME20DN21+TXV | | 39,000 | $1,950 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206971477 | CHAMPION HEATING AND COOLING | HMH72B601 | AVC60DX21+TXV | | 39,000 | $1,950 |
| No | 206921986 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36AXA1+TXV | TM8V060A12MP12 | 14,100 | $705 |
| No | 206921990 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36AXA1+TXV | TMLV060A12MP12 | 14,100 | $705 |
| No | 206921994 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36AXA1+TXV | TPLC060A12MP13 | 14,100 | $705 |
| No | 206921998 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36AXA1+TXV | TM8V060A12MP12 | 14,100 | $705 |
| No | 206922002 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36AXA1+TXV | TMLV060A12MP12 | 14,100 | $705 |
| No | 206922006 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36AXA1+TXV | TPLC060A12MP13 | 14,100 | $705 |
| No | 206921881 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36BXA1+TXV | TM8V080B12MP12 | 14,400 | $720 |
| No | 206921885 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36BXA1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 206921894 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36BXA1+TXV | TM8V080B12MP12 | 14,400 | $720 |
| No | 206921890 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36BBAA1 | TM8V080B12MP12 | 14,400 | $720 |
| No | 206921898 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36BBAA1 | TM8V080B12MP12 | 14,400 | $720 |
| No | 206921902 | CHAMPION HEATING AND COOLING | HMH72B241 | CU36BXA1+TXV | TM8V080B12MP12 | 14,400 | $720 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921906 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36BBAA1 | TPLC080B12MP13 | 14,400 | $720 |
| No | 206921910 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36BXA1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 206921914 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36BBAA1 | TPLC080B12MP13 | 14,400 | $720 |
| No | 206921918 | CHAMPION HEATING AND COOLING | HMH72B241 | CU36BXA1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 206922058 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36BXA1+TXV | TL8E060A12UH11 | 14,500 | $725 |
| No | 206922062 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36BBAA1 | TL8E060A12UH11 | 14,500 | $725 |
| No | 206922066 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36BXA1+TXV | TL8E060A12UH11 | 14,500 | $725 |
| No | 206922070 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36BBAA1 | TL8E060A12UH11 | 14,500 | $725 |
| No | 206922074 | CHAMPION HEATING AND COOLING | HMH72B241 | CU36BXA1+TXV | TL8E060A12UH11 | 14,500 | $725 |
| No | 206922078 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36AXA1+TXV | TL8E060A12UH11 | 14,400 | $720 |
| No | 206922082 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36AXA1+TXV | TL8E060A12UH11 | 14,400 | $720 |
| No | 206921854 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36CXA1+TXV | TM8V080B12MP12 | 14,300 | $715 |
| No | 206921858 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36CXA1+TXV | TPLC080B12MP13 | 14,300 | $715 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921863 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36CXA1+TXV | TM8V080B12MP12 | 14,300 | $715 |
| No | 206921867 | CHAMPION HEATING AND COOLING | HMH72B241 | CU36CXA1+TXV | TM8V080B12MP12 | 14,300 | $715 |
| No | 206921871 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36CXA1+TXV | TPLC080B12MP13 | 14,300 | $715 |
| No | 206921875 | CHAMPION HEATING AND COOLING | HMH72B241 | CU36CXA1+TXV | TPLC080B12MP13 | 14,300 | $715 |
| No | 206921926 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36BXA1+TXV | TM8V060A12MP12 | 14,000 | $700 |
| No | 206921930 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36BXA1+TXV | TMLV060A12MP12 | 14,000 | $700 |
| No | 206921934 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36BXA1+TXV | TPLC060A12MP13 | 14,000 | $700 |
| No | 206921938 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36BBAA1 | TM8V060A12MP12 | 14,000 | $700 |
| No | 206921942 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36BXA1+TXV | TM8V060A12MP12 | 14,000 | $700 |
| No | 206921946 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36BBAA1 | TM8V060A12MP12 | 14,000 | $700 |
| No | 206921950 | CHAMPION HEATING AND COOLING | HMH72B241 | CU36BXA1+TXV | TM8V060A12MP12 | 14,000 | $700 |
| No | 206921958 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36BXA1+TXV | TMLV060A12MP12 | 14,000 | $700 |
| No | 206921954 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36BBAA1 | TMLV060A12MP12 | 14,000 | $700 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921962 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36BBAA1 | TMLV060A12MP12 | 14,000 | $700 |
| No | 206921966 | CHAMPION HEATING AND COOLING | HMH72B241 | CU36BXA1+TXV | TMLV060A12MP12 | 14,000 | $700 |
| No | 206921970 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36BBAA1 | TPLC060A12MP13 | 14,000 | $700 |
| No | 206921974 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36BXA1+TXV | TPLC060A12MP13 | 14,000 | $700 |
| No | 206921978 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36BBAA1 | TPLC060A12MP13 | 14,000 | $700 |
| No | 206921982 | CHAMPION HEATING AND COOLING | HMH72B241 | CU36BXA1+TXV | TPLC060A12MP13 | 14,000 | $700 |
| No | 206922010 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36AXA1+TXV | TM8E040A12MP11 | 14,400 | $720 |
| No | 206922038 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36BXA1+TXV | TL9E060B12UH11 | 14,500 | $725 |
| No | 206922014 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36AXA1+TXV | TMLE040A12MP11 | 14,400 | $720 |
| No | 206922018 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36AXA1+TXV | TM8E040A12MP11 | 14,400 | $720 |
| No | 206922022 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36AXA1+TXV | TMLE040A12MP11 | 14,400 | $720 |
| No | 206922042 | CHAMPION HEATING AND COOLING | HMH72B241 | CF36BBAA1 | TL9E060B12UH11 | 14,500 | $725 |
| No | 206922046 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36BXA1+TXV | TL9E060B12UH11 | 14,500 | $725 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922050 | CHAMPION HEATING AND COOLING | HMH72B241 | CM36BBAA1 | TL9E060B12UH11 | 14,500 | $725 |
| No | 206922054 | CHAMPION HEATING AND COOLING | HMH72B241 | CU36BXA1+TXV | TL9E060B12UH11 | 14,500 | $725 |
| No | 206971735 | CHAMPION HEATING AND COOLING | HMH72B481 | CF64DXA1+MVC14DN21+TXV | | 29,200 | $1,460 |
| No | 206971739 | CHAMPION HEATING AND COOLING | HMH72B481 | CM64DXA1+MVC14DN21+TXV | | 29,200 | $1,460 |
| No | 206787285 | CHAMPION HEATING AND COOLING | HMH72B241 | AE36CX21+TXV | | 14,000 | $700 |
| No | 206787286 | CHAMPION HEATING AND COOLING | HMH72B361 | AE36CX21+TXV | | 24,000 | $1,200 |
| No | 206787287 | CHAMPION HEATING AND COOLING | HMH72B481 | AE60DX21+TXV | | 30,200 | $1,510 |
| No | 206787288 | CHAMPION HEATING AND COOLING | HMH72B601 | AE60DX21+TXV | | 36,800 | $1,840 |
| No | 207659297 | CIAC | CG43VX036PH3N1H | CH43VX036-H3N1H | | 24,000 | $1,200 |
| No | 209843039 | CLASSIC | MMRSHC36AS4 | Heat pump without ducts | | 26,400 | $1,320 |
| No | 209843036 | CLASSIC | MMRSHC27AS3 | Heat pump without ducts | | 20,000 | $1,000 |
| No | 209843037 | CLASSIC | MMRSHC27AS3 | Heat pump with ducts | | 22,000 | $1,100 |
| No | 209843034 | CLASSIC | MMRSHC18AS2 | Heat pump with ducts | | 14,800 | $740 |
| No | 209843042 | CLASSIC | MMRSHC48AS5 | Heat pump without ducts | | 36,000 | $1,800 |
| No | 209843033 | CLASSIC | MMRSHC18AS2 | Heat pump without ducts | | 14,400 | $720 |
| No | 209843002 | CLASSIC | MRSVHC18AS | MFCHC18S | | 12,600 | $630 |
| No | 209842997 | CLASSIC | MRSVHC18AS | MC4VHC18S | | 12,000 | $600 |
| No | 209843007 | CLASSIC | MC4VHC18S | MUVHC18S | | 12,800 | $640 |
| No | 209842998 | CLASSIC | MRSVHC24AS | MC4VHC24S | | 19,000 | $950 |
| No | 209843005 | CLASSIC | MRSVHC48AS | MFCHC48S | | 34,000 | $1,700 |
| No | 209843000 | CLASSIC | MRSVHC48AS | MC4VHC48S | | 30,000 | $1,500 |
| No | 209843010 | CLASSIC | MRSVHC48AS | MUVHC48S | | 29,000 | $1,450 |
| No | 209843004 | CLASSIC | MRSVHC36AS | MFCHC36S | | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 209842999 | CLASSIC | MRSVHC36AS | MC4VHC36S | | 23,000 | $1,150 |
| No | 209843009 | CLASSIC | MRSVHC36AS | MUVHC36S | | 23,000 | $1,150 |
| No | 209843003 | CLASSIC | MRSVHC24AS | MFCHC24S | | 20,000 | $1,000 |
| No | 209843001 | CLASSIC | MRSVHC12AS | MFCHC12S | | 9,300 | $465 |
| No | 209843008 | CLASSIC | MRSVHC24AS | MUVHC24S | | 16,000 | $800 |
| No | 209842996 | CLASSIC | MRSVHC12AS | MC4VHC12S | | 8,900 | $445 |
| No | 210568095 | Clearity | MOX330-12HFN1-MW5W | MSEPB-12HRFN1-MW5W(GA) | | 10,000 | $500 |
| No | 211257104 | CLIMA SMART | MCH12-CS-S23-O | MCH12-CS-S23-I | | 7,100 | $355 |
| No | 211257106 | CLIMA SMART | MCH24-CS-S23-O | MCH24-CS-S23-I | | 13,900 | $695 |
| No | 211257105 | CLIMA SMART | MCH18-CS-S23-O | MCH18-CS-S23-I | | 10,000 | $500 |
| No | 211126489 | COAST AIR | A-CAD24-1A | B-CAD24-1A | | 17,900 | $895 |
| No | 211126491 | COAST AIR | A-CAD18-1A | B-CAD18-1A | | 13,800 | $690 |
| No | 211126487 | COAST AIR | A-CAD09-0A | B-CAD09-0A | | 7,500 | $375 |
| No | 211126490 | COAST AIR | A-CAD12-0A | B-CAD12-0A | | 7,500 | $375 |
| No | 211238543 | COLEMAN | HMH72B341 | JHETC36DBCS2N1 | | 24,600 | $1,230 |
| No | 211719794 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | CPLC060A12MP13 | 25,000 | $1,250 |
| No | 211719792 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | CPLC060A12MP13 | 25,000 | $1,250 |
| No | 211719774 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | CPLC080B12MP13 | 24,000 | $1,200 |
| No | 211719773 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | CPLC080B12MP13 | 15,100 | $755 |
| No | 211719772 | COLEMAN | HMH72B241 | XAHB30CBAN1 | CPLC080B12MP13 | 14,900 | $745 |
| No | 211719771 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | CPLC080B12MP13 | 14,900 | $745 |
| No | 211719770 | COLEMAN | HMH72B241 | XAFC30CBAN1 | CPLC080B12MP13 | 15,100 | $755 |
| No | 211719769 | COLEMAN | HMH72B241 | XAFB30CBAN1 | CPLC080B12MP13 | 15,100 | $755 |
| No | 211719768 | COLEMAN | HMH72B241 | XAFB30CXXN1+TXV | CPLC080B12MP13 | 15,100 | $755 |
| No | 211719767 | COLEMAN | HMH72B241 | XAUB30CXXN1+TXV | CPLC080B12MP13 | 15,100 | $755 |
| No | 211719766 | COLEMAN | HMH72B241 | XAHC30CBAN1 | CPLC080B12MP13 | 14,800 | $740 |
| No | 211719765 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | CPLC080B12MP13 | 14,800 | $740 |
| No | 211719755 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | CPLC060A12MP13 | 24,200 | $1,210 |
| No | 211719753 | COLEMAN | HMH72B361 | XAFA30DXXN1+TXV | CPLC060A12MP13 | 25,800 | $1,290 |
| No | 211719752 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | CPLC080B12MP13 | 24,600 | $1,230 |
| No | 211719751 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | CPLC080B12MP13 | 24,600 | $1,230 |
| No | 211719750 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | CPLC080B12MP13 | 24,800 | $1,240 |
| No | 211719737 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | CPLC080B12MP13 | 24,200 | $1,210 |
| No | 211662223 | COLEMAN | HMH72B361 | XAUB30CXXN1+JMET12BS2N1+TXV | | 24,800 | $1,240 |
| No | 211662218 | COLEMAN | HMH72B361 | XAFB30CXXN1+JMET12BS2N1+TXV | | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211662213 | COLEMAN | HMH72B361 | XAHB30CXXN1+JMET12BS2N1+TXV | | 23,800 | $1,190 |
| No | 211662208 | COLEMAN | HMH72B361 | XAUB30CXXN1+JMVT12BC2N1+TXV | | 24,600 | $1,230 |
| No | 211662203 | COLEMAN | HMH72B361 | XAFB30CXXN1+JMVT12BC2N1+TXV | | 24,600 | $1,230 |
| No | 211662198 | COLEMAN | HMH72B361 | XAHB30CXXN1+JMVT12BC2N1+TXV | | 24,200 | $1,210 |
| No | 211662193 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | TMLE040A12MP11 | 24,400 | $1,220 |
| No | 211662188 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | TM8E040A12MP11 | 24,400 | $1,220 |
| No | 211662183 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | TMLE040A12MP11 | 24,400 | $1,220 |
| No | 211662178 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | TM8E040A12MP11 | 24,400 | $1,220 |
| No | 211662173 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | TMLE040A12MP11 | 23,800 | $1,190 |
| No | 211662168 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | TM8E040A12MP11 | 23,800 | $1,190 |
| No | 211662163 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | TL8E060A12UH11 | 24,400 | $1,220 |
| No | 211662158 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | TL8E060A12UH11 | 24,400 | $1,220 |
| No | 211662153 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | TL8E060A12UH11 | 24,000 | $1,200 |
| No | 211662148 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TL8E080C16UH11 | 25,200 | $1,260 |
| No | 211662143 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TL8E080C16UH11 | 24,800 | $1,240 |
| No | 211662138 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TL8E100C20UH11 | 24,400 | $1,220 |
| No | 211662133 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TL8E100C20UH11 | 24,000 | $1,200 |
| No | 211662128 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 211662123 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 211662118 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 211662113 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | TL9E060B12UH11 | 23,600 | $1,180 |
| No | 211662108 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 211662103 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TL9E080C16UH11 | 24,800 | $1,240 |
| No | 211662098 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TL9E080C16UH11 | 24,400 | $1,220 |
| No | 211662093 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TL9E100C20UH11 | 24,600 | $1,230 |
| No | 211662088 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TL9E100C20UH11 | 24,000 | $1,200 |
| No | 211662083 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | TMLE060A12MP11 | 24,400 | $1,220 |
| No | 211662078 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | TM8E060A12MP11 | 24,400 | $1,220 |
| No | 211662073 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | TMLE060A12MP11 | 24,400 | $1,220 |
| No | 211662068 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | TM8E060A12MP11 | 24,400 | $1,220 |
| No | 211662063 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | TMLE060A12MP11 | 24,000 | $1,200 |
| No | 211662058 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | TM8E060A12MP11 | 24,000 | $1,200 |
| No | 211662053 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 211662048 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211662043 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 211662038 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 211662033 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 211662028 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 211662023 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | TMLE080B12MP11 | 24,400 | $1,220 |
| No | 211662018 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | TM8E080B12MP11 | 24,400 | $1,220 |
| No | 211662013 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TMLE080B12MP11 | 24,400 | $1,220 |
| No | 211662008 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TM8E080B12MP11 | 24,400 | $1,220 |
| No | 211662003 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TMLE080C16MP11 | 24,200 | $1,210 |
| No | 211661998 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TM8E080C16MP11 | 24,200 | $1,210 |
| No | 211661993 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TMLE080C16MP11 | 23,800 | $1,190 |
| No | 211661988 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TM8E080C16MP11 | 23,800 | $1,190 |
| No | 211661983 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | TMLE100B12MP11 | 24,400 | $1,220 |
| No | 211661978 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | TM8E100B12MP11 | 24,400 | $1,220 |
| No | 211661973 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | TMLE100B12MP11 | 24,400 | $1,220 |
| No | 211661968 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | TM8E100B12MP11 | 24,400 | $1,220 |
| No | 211661963 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TMLE100B12MP11 | 24,400 | $1,220 |
| No | 211661958 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TM8E100B12MP11 | 24,400 | $1,220 |
| No | 211661953 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | TMLE100B12MP11 | 24,000 | $1,200 |
| No | 211661948 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | TM8E100B12MP11 | 24,000 | $1,200 |
| No | 211661943 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TMLE100B12MP11 | 24,000 | $1,200 |
| No | 211661938 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TM8E100B12MP11 | 24,000 | $1,200 |
| No | 211661933 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TMLE100C16MP11 | 24,200 | $1,210 |
| No | 211661928 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TM8E100C16MP11 | 24,200 | $1,210 |
| No | 211661923 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TMLE100C16MP11 | 23,800 | $1,190 |
| No | 211661918 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TM8E100C16MP11 | 23,800 | $1,190 |
| No | 211661913 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TMLE120C16MP11 | 24,200 | $1,210 |
| No | 211661908 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TM8E120C16MP11 | 24,200 | $1,210 |
| No | 211661903 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TMLE120C16MP11 | 23,800 | $1,190 |
| No | 211661898 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TM8E120C16MP11 | 23,800 | $1,190 |
| No | 211661893 | COLEMAN | HMH72B361 | XAFA30DXXN1+TXV | TPLC060A12MP13 | 25,800 | $1,290 |
| No | 211661888 | COLEMAN | HMH72B361 | XAFA30DXXN1+TXV | TMLV060A12MP12 | 25,800 | $1,290 |
| No | 211661883 | COLEMAN | HMH72B361 | XAFA30DXXN1+TXV | TM8V060A12MP12 | 25,800 | $1,290 |
| No | 211661878 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 211661873 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 211661868 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 211661863 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 211661858 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | TMLV060A12MP12 | 25,000 | $1,250 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661853 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 211661848 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | TPLC060A12MP13 | 24,200 | $1,210 |
| No | 211661843 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | TMLV060A12MP12 | 24,200 | $1,210 |
| No | 211661838 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | TM8V060A12MP12 | 24,200 | $1,210 |
| No | 211661832 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 211661827 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 211661821 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 211661816 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 211661810 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TPLC080B12MP13 | 24,800 | $1,240 |
| No | 211661805 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TM8V080B12MP12 | 24,800 | $1,240 |
| No | 211661799 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | TPLC080B12MP13 | 24,000 | $1,200 |
| No | 211661794 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | TM8V080B12MP12 | 24,000 | $1,200 |
| No | 211661788 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TPLC080B12MP13 | 24,200 | $1,210 |
| No | 211661783 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TM8V080B12MP12 | 24,200 | $1,210 |
| No | 211661781 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | CPLC100C16MP13 | 25,000 | $1,250 |
| No | 211661779 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | CPLC080C16MP13 | 25,000 | $1,250 |
| No | 211661774 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TPLC100C16MP13 | 25,000 | $1,250 |
| No | 211661769 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TPLC080C16MP13 | 25,000 | $1,250 |
| No | 211661764 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TMLV100C16MP12 | 25,000 | $1,250 |
| No | 211661759 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TM8V080C16MP12 | 25,000 | $1,250 |
| No | 211661754 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TM8V100C16MP12 | 25,000 | $1,250 |
| No | 211661752 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | CPLC100C16MP13 | 24,600 | $1,230 |
| No | 211661750 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | CPLC080C16MP13 | 24,600 | $1,230 |
| No | 211661745 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 211661740 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TPLC080C16MP13 | 24,600 | $1,230 |
| No | 211661735 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TMLV100C16MP12 | 24,600 | $1,230 |
| No | 211661725 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 211661720 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | TM8Y060A12MP11 | 24,200 | $1,210 |
| No | 211661715 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | TM8Y060A12MP11 | 24,200 | $1,210 |
| No | 211661710 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | TM8Y060A12MP11 | 23,800 | $1,190 |
| No | 211661705 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | TM8Y080B12MP11 | 24,200 | $1,210 |
| No | 211661700 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | TM8Y080B12MP11 | 24,200 | $1,210 |
| No | 211661695 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TM8Y080B12MP11 | 24,200 | $1,210 |
| No | 211661690 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | TM8Y080B12MP11 | 23,800 | $1,190 |
| No | 211661685 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TM8Y080B12MP11 | 23,800 | $1,190 |
| No | 211661680 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TM8Y080C16MP11 | 25,200 | $1,260 |
| No | 211661675 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TM8Y100C16MP11 | 25,200 | $1,260 |
| No | 211661670 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TM8Y080C16MP11 | 24,600 | $1,230 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661665 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TM8Y100C16MP11 | 24,600 | $1,230 |
| No | 211661660 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TM8Y100C20MP11 | 24,800 | $1,240 |
| No | 211661655 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TM8Y120C20MP11 | 24,800 | $1,240 |
| No | 211661650 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TM8Y100C20MP11 | 24,400 | $1,220 |
| No | 211661645 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TM8Y120C20MP11 | 24,400 | $1,220 |
| No | 211661640 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | TM9E040A10MP12 | 24,200 | $1,210 |
| No | 211661635 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | TM9E040A10MP12 | 24,200 | $1,210 |
| No | 211661630 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | TM9E060A10MP12 | 24,400 | $1,220 |
| No | 211661625 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | TM9E060A10MP12 | 24,400 | $1,220 |
| No | 211661620 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | TM9E060A10MP12 | 24,000 | $1,200 |
| No | 211661615 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 211661610 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 211661605 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 211661600 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | TM9E060B12MP12 | 24,200 | $1,210 |
| No | 211661595 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 211661590 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 211661585 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 211661580 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 211661575 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | TM9E080B12MP12 | 24,400 | $1,220 |
| No | 211661570 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TM9E080B12MP12 | 24,400 | $1,220 |
| No | 211661565 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TM9E080C16MP12 | 25,200 | $1,260 |
| No | 211661560 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TM9E080C16MP12 | 24,800 | $1,240 |
| No | 211661555 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TM9E100C16MP12 | 24,400 | $1,220 |
| No | 211661550 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TM9E100C16MP12 | 23,800 | $1,190 |
| No | 211661545 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | TM9V040A10MP12 | 24,400 | $1,220 |
| No | 211661540 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | TM9V040A10MP12 | 24,400 | $1,220 |
| No | 211661533 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | CP9C060B12MP13 | 24,600 | $1,230 |
| No | 211661528 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | TP9C060B12MP13 | 24,600 | $1,230 |
| No | 211661523 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | TM9V060B12MP12 | 24,600 | $1,230 |
| No | 211661521 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | CP9C060B12MP13 | 24,600 | $1,230 |
| No | 211661516 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | TP9C060B12MP13 | 24,600 | $1,230 |
| No | 211661511 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | TM9V060B12MP12 | 24,600 | $1,230 |
| No | 211661509 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | CP9C060B12MP13 | 24,600 | $1,230 |
| No | 211661500 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TP9C060B12MP13 | 24,600 | $1,230 |
| No | 211661495 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TM9V060B12MP12 | 24,600 | $1,230 |
| No | 211661493 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | CP9C060B12MP13 | 24,000 | $1,200 |
| No | 211661488 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | TP9C060B12MP13 | 24,000 | $1,200 |
| No | 211661483 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | TM9V060B12MP12 | 24,000 | $1,200 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661481 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | CP9C060B12MP13 | 24,200 | $1,210 |
| No | 211661476 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TP9C060B12MP13 | 24,200 | $1,210 |
| No | 211661471 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TM9V060B12MP12 | 24,200 | $1,210 |
| No | 211661469 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | CP9C080B12MP13 | 24,800 | $1,240 |
| No | 211661464 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | TP9C080B12MP13 | 24,800 | $1,240 |
| No | 211661459 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | TM9V080B12MP12 | 24,800 | $1,240 |
| No | 211661457 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | CP9C080B12MP13 | 24,800 | $1,240 |
| No | 211661452 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | TP9C080B12MP13 | 24,800 | $1,240 |
| No | 211661447 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | TM9V080B12MP12 | 24,800 | $1,240 |
| No | 211661445 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | CP9C080B12MP13 | 25,000 | $1,250 |
| No | 211661440 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 211661435 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 211661433 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | CP9C080B12MP13 | 24,400 | $1,220 |
| No | 211661428 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 211661423 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 211661421 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | CP9C080B12MP13 | 24,600 | $1,230 |
| No | 211661416 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 211661411 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 211661409 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | CP9C080C16MP13 | 25,200 | $1,260 |
| No | 211661404 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TP9C080C16MP13 | 25,200 | $1,260 |
| No | 211661399 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TM9V080C16MP12 | 25,200 | $1,260 |
| No | 211661397 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | CP9C080C16MP13 | 24,800 | $1,240 |
| No | 211661392 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TP9C080C16MP13 | 24,800 | $1,240 |
| No | 211661387 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TM9V080C16MP12 | 24,800 | $1,240 |
| No | 211661385 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | CP9C100C16MP13 | 24,800 | $1,240 |
| No | 211661380 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211661375 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TM9V100C16MP12 | 24,800 | $1,240 |
| No | 211661373 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | CP9C100C16MP13 | 24,600 | $1,230 |
| No | 211661368 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TP9C100C16MP13 | 24,600 | $1,230 |
| No | 211661363 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TM9V100C16MP12 | 24,600 | $1,230 |
| No | 211661361 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | CP9C100C20MP13 | 25,000 | $1,250 |
| No | 211661356 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TP9C100C20MP13 | 25,000 | $1,250 |
| No | 211661351 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TM9V100C20MP12 | 25,000 | $1,250 |
| No | 211661349 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | CP9C100C20MP13 | 24,600 | $1,230 |
| No | 211661344 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TP9C100C20MP13 | 24,600 | $1,230 |
| No | 211661339 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TM9V100C20MP12 | 24,600 | $1,230 |
| No | 211661334 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | TM9Y060B12MP11 | 24,800 | $1,240 |
| No | 211661329 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | TM9Y060B12MP11 | 24,800 | $1,240 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661324 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TM9Y060B12MP11 | 24,800 | $1,240 |
| No | 211661319 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | TM9Y060B12MP11 | 24,200 | $1,210 |
| No | 211661314 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TM9Y060B12MP11 | 24,200 | $1,210 |
| No | 211661309 | COLEMAN | HMH72B361 | XAUB30CXXN1+TXV | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211661304 | COLEMAN | HMH72B361 | XAFB30CXXN1+TXV | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211661299 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211661294 | COLEMAN | HMH72B361 | XAHB30CXXN1+TXV | TM9Y080B12MP11 | 24,400 | $1,220 |
| No | 211661289 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TM9Y080B12MP11 | 24,400 | $1,220 |
| No | 211661284 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TM9Y080C16MP11 | 24,800 | $1,240 |
| No | 211661279 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TM9Y080C16MP11 | 24,400 | $1,220 |
| No | 211661274 | COLEMAN | HMH72B361 | XAFC30CXXN1+TXV | TM9Y100C16MP11 | 24,800 | $1,240 |
| No | 211661269 | COLEMAN | HMH72B361 | XAHC30CXXN1+TXV | TM9Y100C16MP11 | 24,400 | $1,220 |
| No | 211661264 | COLEMAN | HMH72B241 | XAHB30CBAN1 | TM9E040A10MP12 | 15,000 | $750 |
| No | 211661259 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | TM9E040A10MP12 | 15,000 | $750 |
| No | 211661254 | COLEMAN | HMH72B241 | XAUB30CXXN1+TXV | TM9E060A10MP12 | 15,000 | $750 |
| No | 211661249 | COLEMAN | HMH72B241 | XAFB30CBAN1 | TM9E060A10MP12 | 15,000 | $750 |
| No | 211661244 | COLEMAN | HMH72B241 | XAFB30CXXN1+TXV | TM9E060A10MP12 | 15,000 | $750 |
| No | 211661239 | COLEMAN | HMH72B241 | XAHB30CBAN1 | TM9E060A10MP12 | 14,900 | $745 |
| No | 211661234 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | TM9E060A10MP12 | 14,900 | $745 |
| No | 211661229 | COLEMAN | HMH72B241 | XAUB30CXXN1+TXV | TM9E060B12MP12 | 15,400 | $770 |
| No | 211661224 | COLEMAN | HMH72B241 | XAFB30CBAN1 | TM9E060B12MP12 | 15,400 | $770 |
| No | 211661219 | COLEMAN | HMH72B241 | XAFB30CXXN1+TXV | TM9E060B12MP12 | 15,400 | $770 |
| No | 211661214 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TM9E060B12MP12 | 15,400 | $770 |
| No | 211661209 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TM9E060B12MP12 | 15,400 | $770 |
| No | 211661204 | COLEMAN | HMH72B241 | XAHB30CBAN1 | TM9E060B12MP12 | 15,100 | $755 |
| No | 211661199 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | TM9E060B12MP12 | 15,100 | $755 |
| No | 211661194 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TM9E060B12MP12 | 15,100 | $755 |
| No | 211661185 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TM9E060B12MP12 | 15,100 | $755 |
| No | 211661175 | COLEMAN | HMH72B241 | XAUB30CXXN1+TXV | TM9E080B12MP12 | 15,700 | $785 |
| No | 211661165 | COLEMAN | HMH72B241 | XAFB30CBAN1 | TM9E080B12MP12 | 15,700 | $785 |
| No | 211661159 | COLEMAN | HMH72B241 | XAFB30CXXN1+TXV | TM9E080B12MP12 | 15,700 | $785 |
| No | 211661154 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TM9E080B12MP12 | 15,700 | $785 |
| No | 211661149 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TM9E080B12MP12 | 15,700 | $785 |
| No | 211661144 | COLEMAN | HMH72B241 | XAHB30CBAN1 | TM9E080B12MP12 | 14,900 | $745 |
| No | 211661139 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | TM9E080B12MP12 | 14,900 | $745 |
| No | 211661134 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TM9E080B12MP12 | 14,900 | $745 |
| No | 211661129 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TM9E080B12MP12 | 14,900 | $745 |
| No | 211661124 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TM9E080C16MP12 | 14,900 | $745 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661119 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TM9E080C16MP12 | 14,900 | $745 |
| No | 211661114 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TM9E080C16MP12 | 14,600 | $730 |
| No | 211661109 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TM9E080C16MP12 | 14,600 | $730 |
| No | 211661104 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TM9E100C16MP12 | 15,000 | $750 |
| No | 211661099 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TM9E100C16MP12 | 15,000 | $750 |
| No | 211661094 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TM9E100C16MP12 | 14,700 | $735 |
| No | 211661089 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TM9E100C16MP12 | 14,700 | $735 |
| No | 211661084 | COLEMAN | HMH72B241 | XAUB30CXXN1+TXV | TM9V040A10MP12 | 15,400 | $770 |
| No | 211661079 | COLEMAN | HMH72B241 | XAFB30CBAN1 | TM9V040A10MP12 | 15,400 | $770 |
| No | 211661074 | COLEMAN | HMH72B241 | XAFB30CXXN1+TXV | TM9V040A10MP12 | 15,400 | $770 |
| No | 211661069 | COLEMAN | HMH72B241 | XAHB30CBAN1 | TM9V040A10MP12 | 15,100 | $755 |
| No | 211661064 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | TM9V040A10MP12 | 15,100 | $755 |
| No | 211661062 | COLEMAN | HMH72B241 | XAUB30CXXN1+TXV | CP9C060B12MP13 | 15,100 | $755 |
| No | 211661060 | COLEMAN | HMH72B241 | XAFB30CBAN1 | CP9C060B12MP13 | 15,100 | $755 |
| No | 211661055 | COLEMAN | HMH72B241 | XAUB30CXXN1+TXV | TP9C060B12MP13 | 15,100 | $755 |
| No | 211661050 | COLEMAN | HMH72B241 | XAFB30CBAN1 | TP9C060B12MP13 | 15,100 | $755 |
| No | 211661045 | COLEMAN | HMH72B241 | XAUB30CXXN1+TXV | TM9V060B12MP12 | 15,100 | $755 |
| No | 211661040 | COLEMAN | HMH72B241 | XAFB30CBAN1 | TM9V060B12MP12 | 15,100 | $755 |
| No | 211661038 | COLEMAN | HMH72B241 | XAFB30CXXN1+TXV | CP9C060B12MP13 | 15,100 | $755 |
| No | 211661033 | COLEMAN | HMH72B241 | XAFB30CXXN1+TXV | TP9C060B12MP13 | 15,100 | $755 |
| No | 211661028 | COLEMAN | HMH72B241 | XAFB30CXXN1+TXV | TM9V060B12MP12 | 15,100 | $755 |
| No | 211661026 | COLEMAN | HMH72B241 | XAFC30CBAN1 | CP9C060B12MP13 | 15,100 | $755 |
| No | 211661021 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TP9C060B12MP13 | 15,100 | $755 |
| No | 211661016 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TM9V060B12MP12 | 15,100 | $755 |
| No | 211661014 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | CP9C060B12MP13 | 15,100 | $755 |
| No | 211661009 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TP9C060B12MP13 | 15,100 | $755 |
| No | 211661004 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TM9V060B12MP12 | 15,100 | $755 |
| No | 211661002 | COLEMAN | HMH72B241 | XAHB30CBAN1 | CP9C060B12MP13 | 15,100 | $755 |
| No | 211660997 | COLEMAN | HMH72B241 | XAHB30CBAN1 | TP9C060B12MP13 | 15,100 | $755 |
| No | 211660992 | COLEMAN | HMH72B241 | XAHB30CBAN1 | TM9V060B12MP12 | 15,100 | $755 |
| No | 211660990 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | CP9C060B12MP13 | 15,100 | $755 |
| No | 211660985 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | TP9C060B12MP13 | 15,100 | $755 |
| No | 211660980 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | TM9V060B12MP12 | 15,100 | $755 |
| No | 211660978 | COLEMAN | HMH72B241 | XAHC30CBAN1 | CP9C060B12MP13 | 15,000 | $750 |
| No | 211660973 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TP9C060B12MP13 | 15,000 | $750 |
| No | 211660968 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TM9V060B12MP12 | 15,000 | $750 |
| No | 211660966 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | CP9C060B12MP13 | 15,000 | $750 |
| No | 211660961 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TP9C060B12MP13 | 15,000 | $750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660956 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TM9V060B12MP12 | 15,000 | $750 |
| No | 211660954 | COLEMAN | HMH72B241 | XAUB30CXXN1+TXV | CP9C080B12MP13 | 15,300 | $765 |
| No | 211660952 | COLEMAN | HMH72B241 | XAFB30CBAN1 | CP9C080B12MP13 | 15,300 | $765 |
| No | 211660947 | COLEMAN | HMH72B241 | XAUB30CXXN1+TXV | TP9C080B12MP13 | 15,300 | $765 |
| No | 211660942 | COLEMAN | HMH72B241 | XAFB30CBAN1 | TP9C080B12MP13 | 15,300 | $765 |
| No | 211660937 | COLEMAN | HMH72B241 | XAUB30CXXN1+TXV | TM9V080B12MP12 | 15,300 | $765 |
| No | 211660932 | COLEMAN | HMH72B241 | XAFB30CBAN1 | TM9V080B12MP12 | 15,300 | $765 |
| No | 211660930 | COLEMAN | HMH72B241 | XAFB30CXXN1+TXV | CP9C080B12MP13 | 15,300 | $765 |
| No | 211660925 | COLEMAN | HMH72B241 | XAFB30CXXN1+TXV | TP9C080B12MP13 | 15,300 | $765 |
| No | 211660920 | COLEMAN | HMH72B241 | XAFB30CXXN1+TXV | TM9V080B12MP12 | 15,300 | $765 |
| No | 211660918 | COLEMAN | HMH72B241 | XAFC30CBAN1 | CP9C080B12MP13 | 15,300 | $765 |
| No | 211660913 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TP9C080B12MP13 | 15,300 | $765 |
| No | 211660908 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TM9V080B12MP12 | 15,300 | $765 |
| No | 211660906 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | CP9C080B12MP13 | 15,300 | $765 |
| No | 211660901 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TP9C080B12MP13 | 15,300 | $765 |
| No | 211660896 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TM9V080B12MP12 | 15,300 | $765 |
| No | 211660894 | COLEMAN | HMH72B241 | XAHB30CBAN1 | CP9C080B12MP13 | 14,800 | $740 |
| No | 211660889 | COLEMAN | HMH72B241 | XAHB30CBAN1 | TP9C080B12MP13 | 14,800 | $740 |
| No | 211660884 | COLEMAN | HMH72B241 | XAHB30CBAN1 | TM9V080B12MP12 | 14,800 | $740 |
| No | 211660882 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | CP9C080B12MP13 | 14,800 | $740 |
| No | 211660877 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | TP9C080B12MP13 | 14,800 | $740 |
| No | 211660872 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | TM9V080B12MP12 | 14,800 | $740 |
| No | 211660870 | COLEMAN | HMH72B241 | XAHC30CBAN1 | CP9C080B12MP13 | 15,000 | $750 |
| No | 211660865 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TP9C080B12MP13 | 15,000 | $750 |
| No | 211660860 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TM9V080B12MP12 | 15,000 | $750 |
| No | 211660858 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | CP9C080B12MP13 | 15,000 | $750 |
| No | 211660853 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 211660848 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 211660818 | COLEMAN | HMH72B241 | XAUB30CXXN1+TXV | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211660813 | COLEMAN | HMH72B241 | XAFB30CBAN1 | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211660808 | COLEMAN | HMH72B241 | XAFB30CXXN1+TXV | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211660803 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211660798 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211660793 | COLEMAN | HMH72B241 | XAHB30CBAN1 | TM9Y060B12MP11 | 15,100 | $755 |
| No | 211660788 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | TM9Y060B12MP11 | 15,100 | $755 |
| No | 211660783 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TM9Y060B12MP11 | 14,800 | $740 |
| No | 211660778 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TM9Y060B12MP11 | 14,800 | $740 |
| No | 211660773 | COLEMAN | HMH72B241 | XAUB30CXXN1+TXV | TM9Y080B12MP11 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660768 | COLEMAN | HMH72B241 | XAFB30CBAN1 | TM9Y080B12MP11 | 15,100 | $755 |
| No | 211660763 | COLEMAN | HMH72B241 | XAFB30CXXN1+TXV | TM9Y080B12MP11 | 15,100 | $755 |
| No | 211660758 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TM9Y080B12MP11 | 15,100 | $755 |
| No | 211660753 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TM9Y080B12MP11 | 15,100 | $755 |
| No | 211660748 | COLEMAN | HMH72B241 | XAHB30CBAN1 | TM9Y080B12MP11 | 14,900 | $745 |
| No | 211660743 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | TM9Y080B12MP11 | 14,900 | $745 |
| No | 211660738 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TM9Y080B12MP11 | 14,900 | $745 |
| No | 211660733 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TM9Y080B12MP11 | 14,900 | $745 |
| No | 211660728 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TM9Y080C16MP11 | 15,200 | $760 |
| No | 211660723 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TM9Y080C16MP11 | 15,200 | $760 |
| No | 211660718 | COLEMAN | HMH72B241 | JHETB24CBAS2N1 | | 15,000 | $750 |
| No | 211660713 | COLEMAN | HMH72B241 | JHVTB24CBAC2N1 | | 15,000 | $750 |
| No | 211660708 | COLEMAN | HMH72B241 | XAUB30CXXN1+JMET12BS2N1+TXV | | 15,100 | $755 |
| No | 211660703 | COLEMAN | HMH72B241 | XAFB30CBAN1+JMET12BS2N1 | | 15,100 | $755 |
| No | 211660698 | COLEMAN | HMH72B241 | XAFB30CXXN1+JMET12BS2N1+TXV | | 15,100 | $755 |
| No | 211660693 | COLEMAN | HMH72B241 | XAHB30CBAN1+JMET12BS2N1 | | 14,800 | $740 |
| No | 211660688 | COLEMAN | HMH72B241 | XAHB30CXXN1+JMET12BS2N1+TXV | | 14,800 | $740 |
| No | 211660683 | COLEMAN | HMH72B241 | XAUB30CXXN1+JMVT12BC2N1+TXV | | 14,900 | $745 |
| No | 211660678 | COLEMAN | HMH72B241 | XAFB30CBAN1+JMVT12BC2N1 | | 14,900 | $745 |
| No | 211660673 | COLEMAN | HMH72B241 | XAFB30CXXN1+JMVT12BC2N1+TXV | | 14,900 | $745 |
| No | 211660668 | COLEMAN | HMH72B241 | XAHB30CBAN1+JMVT12BC2N1 | | 14,900 | $745 |
| No | 211660663 | COLEMAN | HMH72B241 | XAHB30CXXN1+JMVT12BC2N1+TXV | | 14,900 | $745 |
| No | 211660658 | COLEMAN | HMH72B241 | XAUB30CXXN1+TXV | TL8E060A12UH11 | 15,000 | $750 |
| No | 211660653 | COLEMAN | HMH72B241 | XAFB30CBAN1 | TL8E060A12UH11 | 15,000 | $750 |
| No | 211660648 | COLEMAN | HMH72B241 | XAFB30CXXN1+TXV | TL8E060A12UH11 | 15,000 | $750 |
| No | 211660643 | COLEMAN | HMH72B241 | XAHB30CBAN1 | TL8E060A12UH11 | 14,700 | $735 |
| No | 211660638 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | TL8E060A12UH11 | 14,700 | $735 |
| No | 211660633 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TL8E080C16UH11 | 15,600 | $780 |
| No | 211660628 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TL8E080C16UH11 | 15,600 | $780 |
| No | 211660623 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TM9Y080C16MP11 | 14,900 | $745 |
| No | 211660618 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TM9Y080C16MP11 | 14,900 | $745 |
| No | 211660613 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TM9Y100C16MP11 | 15,200 | $760 |
| No | 211660608 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TM9Y100C16MP11 | 15,200 | $760 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660603 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TM9Y100C16MP11 | 14,800 | $740 |
| No | 211660598 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TM9Y100C16MP11 | 14,800 | $740 |
| No | 211660593 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TL8E080C16UH11 | 15,300 | $765 |
| No | 211660588 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TL8E080C16UH11 | 15,300 | $765 |
| No | 211660583 | COLEMAN | HMH72B241 | XAUB30CXXN1+TXV | TL9E060B12UH11 | 15,100 | $755 |
| No | 211660578 | COLEMAN | HMH72B241 | XAFB30CBAN1 | TL9E060B12UH11 | 15,100 | $755 |
| No | 211660573 | COLEMAN | HMH72B241 | XAFB30CXXN1+TXV | TL9E060B12UH11 | 15,100 | $755 |
| No | 211660568 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TL9E060B12UH11 | 15,100 | $755 |
| No | 211660563 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TL9E060B12UH11 | 15,100 | $755 |
| No | 211660558 | COLEMAN | HMH72B241 | XAHB30CBAN1 | TL9E060B12UH11 | 14,800 | $740 |
| No | 211660553 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | TL9E060B12UH11 | 14,800 | $740 |
| No | 211660548 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TL9E060B12UH11 | 14,800 | $740 |
| No | 211660543 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TL9E060B12UH11 | 14,800 | $740 |
| No | 211660538 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TL9E080C16UH11 | 15,700 | $785 |
| No | 211660533 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TL9E080C16UH11 | 15,700 | $785 |
| No | 211660528 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TL9E080C16UH11 | 15,300 | $765 |
| No | 211660523 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TL9E080C16UH11 | 15,300 | $765 |
| No | 211660518 | COLEMAN | HMH72B241 | XAUB30CXXN1+TXV | TMLE040A12MP11 | 15,000 | $750 |
| No | 211660513 | COLEMAN | HMH72B241 | XAFB30CBAN1 | TMLE040A12MP11 | 15,000 | $750 |
| No | 211660508 | COLEMAN | HMH72B241 | XAUB30CXXN1+TXV | TM8E040A12MP11 | 15,000 | $750 |
| No | 211660503 | COLEMAN | HMH72B241 | XAFB30CBAN1 | TM8E040A12MP11 | 15,000 | $750 |
| No | 211660498 | COLEMAN | HMH72B241 | XAFB30CXXN1+TXV | TMLE040A12MP11 | 15,000 | $750 |
| No | 211660493 | COLEMAN | HMH72B241 | XAFB30CXXN1+TXV | TM8E040A12MP11 | 15,000 | $750 |
| No | 211660488 | COLEMAN | HMH72B241 | XAHB30CBAN1 | TMLE040A12MP11 | 14,700 | $735 |
| No | 211660483 | COLEMAN | HMH72B241 | XAHB30CBAN1 | TM8E040A12MP11 | 14,700 | $735 |
| No | 211660478 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | TMLE040A12MP11 | 14,700 | $735 |
| No | 211660473 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | TM8E040A12MP11 | 14,700 | $735 |
| No | 211660468 | COLEMAN | HMH72B241 | XAUB30CXXN1+TXV | TMLE060A12MP11 | 15,000 | $750 |
| No | 211660463 | COLEMAN | HMH72B241 | XAFB30CBAN1 | TMLE060A12MP11 | 15,000 | $750 |
| No | 211660458 | COLEMAN | HMH72B241 | XAUB30CXXN1+TXV | TM8E060A12MP11 | 15,000 | $750 |
| No | 211660453 | COLEMAN | HMH72B241 | XAFB30CBAN1 | TM8E060A12MP11 | 15,000 | $750 |
| No | 211660448 | COLEMAN | HMH72B241 | XAFB30CXXN1+TXV | TMLE060A12MP11 | 15,000 | $750 |
| No | 211660443 | COLEMAN | HMH72B241 | XAFB30CXXN1+TXV | TM8E060A12MP11 | 15,000 | $750 |
| No | 211660438 | COLEMAN | HMH72B241 | XAHB30CBAN1 | TMLE060A12MP11 | 14,700 | $735 |
| No | 211660433 | COLEMAN | HMH72B241 | XAHB30CBAN1 | TM8E060A12MP11 | 14,700 | $735 |
| No | 211660428 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | TMLE060A12MP11 | 14,700 | $735 |
| No | 211660423 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | TM8E060A12MP11 | 14,700 | $735 |
| No | 211660418 | COLEMAN | HMH72B241 | XAUB30CXXN1+TXV | TMLE080B12MP11 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660413 | COLEMAN | HMH72B241 | XAFB30CBAN1 | TMLE080B12MP11 | 15,100 | $755 |
| No | 211660408 | COLEMAN | HMH72B241 | XAUB30CXXN1+TXV | TM8E080B12MP11 | 15,100 | $755 |
| No | 211660403 | COLEMAN | HMH72B241 | XAFB30CBAN1 | TM8E080B12MP11 | 15,100 | $755 |
| No | 211660398 | COLEMAN | HMH72B241 | XAFB30CXXN1+TXV | TMLE080B12MP11 | 15,100 | $755 |
| No | 211660393 | COLEMAN | HMH72B241 | XAFB30CXXN1+TXV | TM8E080B12MP11 | 15,100 | $755 |
| No | 211660388 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TMLE080B12MP11 | 15,100 | $755 |
| No | 211660383 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TM8E080B12MP11 | 15,100 | $755 |
| No | 211660378 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TMLE080B12MP11 | 15,100 | $755 |
| No | 211660373 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TM8E080B12MP11 | 15,100 | $755 |
| No | 211660368 | COLEMAN | HMH72B241 | XAHB30CBAN1 | TMLE080B12MP11 | 14,800 | $740 |
| No | 211660363 | COLEMAN | HMH72B241 | XAHB30CBAN1 | TM8E080B12MP11 | 14,800 | $740 |
| No | 211660358 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | TMLE080B12MP11 | 14,800 | $740 |
| No | 211660353 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | TM8E080B12MP11 | 14,800 | $740 |
| No | 211660348 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TMLE080B12MP11 | 14,800 | $740 |
| No | 211660343 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TM8E080B12MP11 | 14,800 | $740 |
| No | 211660338 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TMLE080B12MP11 | 14,800 | $740 |
| No | 211660333 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TM8E080B12MP11 | 14,800 | $740 |
| No | 211660328 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TMLE080C16MP11 | 15,500 | $775 |
| No | 211660323 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TM8E080C16MP11 | 15,500 | $775 |
| No | 211660318 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TMLE080C16MP11 | 15,500 | $775 |
| No | 211660313 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TM8E080C16MP11 | 15,500 | $775 |
| No | 211660308 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TMLE080C16MP11 | 14,700 | $735 |
| No | 211660303 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TM8E080C16MP11 | 14,700 | $735 |
| No | 211660298 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TMLE080C16MP11 | 14,700 | $735 |
| No | 211660293 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TM8E080C16MP11 | 14,700 | $735 |
| No | 211660288 | COLEMAN | HMH72B241 | XAUB30CXXN1+TXV | TMLE100B12MP11 | 15,100 | $755 |
| No | 211660283 | COLEMAN | HMH72B241 | XAFB30CBAN1 | TMLE100B12MP11 | 15,100 | $755 |
| No | 211660278 | COLEMAN | HMH72B241 | XAUB30CXXN1+TXV | TM8E100B12MP11 | 15,100 | $755 |
| No | 211660273 | COLEMAN | HMH72B241 | XAFB30CBAN1 | TM8E100B12MP11 | 15,100 | $755 |
| No | 211660268 | COLEMAN | HMH72B241 | XAFB30CXXN1+TXV | TMLE100B12MP11 | 15,100 | $755 |
| No | 211660263 | COLEMAN | HMH72B241 | XAFB30CXXN1+TXV | TM8E100B12MP11 | 15,100 | $755 |
| No | 211660258 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TMLE100B12MP11 | 14,800 | $740 |
| No | 211660253 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660248 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TMLE100B12MP11 | 14,800 | $740 |
| No | 211660243 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660238 | COLEMAN | HMH72B241 | XAHB30CBAN1 | TMLE100B12MP11 | 14,800 | $740 |
| No | 211660233 | COLEMAN | HMH72B241 | XAHB30CBAN1 | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660228 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | TMLE100B12MP11 | 14,800 | $740 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660223 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660218 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TMLE100B12MP11 | 14,800 | $740 |
| No | 211660213 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660208 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TMLE100B12MP11 | 14,800 | $740 |
| No | 211660203 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660198 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TMLE100C16MP11 | 15,000 | $750 |
| No | 211660193 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TM8E100C16MP11 | 15,000 | $750 |
| No | 211660188 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TMLE100C16MP11 | 15,000 | $750 |
| No | 211660183 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TM8E100C16MP11 | 15,000 | $750 |
| No | 211660178 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TMLE100C16MP11 | 14,700 | $735 |
| No | 211660173 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TM8E100C16MP11 | 14,700 | $735 |
| No | 211660168 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TMLE100C16MP11 | 14,700 | $735 |
| No | 211660163 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TM8E100C16MP11 | 14,700 | $735 |
| No | 211660158 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TMLE120C16MP11 | 15,000 | $750 |
| No | 211660153 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TM8E120C16MP11 | 15,000 | $750 |
| No | 211660148 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TMLE120C16MP11 | 15,000 | $750 |
| No | 211660143 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TM8E120C16MP11 | 15,000 | $750 |
| No | 211660138 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TMLE120C16MP11 | 15,300 | $765 |
| No | 211660133 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TM8E120C16MP11 | 15,300 | $765 |
| No | 211660128 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TMLE120C16MP11 | 15,300 | $765 |
| No | 211660123 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TM8E120C16MP11 | 15,300 | $765 |
| No | 211660116 | COLEMAN | HMH72B241 | XAUB30CXXN1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 211660111 | COLEMAN | HMH72B241 | XAFB30CBAN1 | TPLC080B12MP13 | 15,100 | $755 |
| No | 211660106 | COLEMAN | HMH72B241 | XAUB30CXXN1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 211660101 | COLEMAN | HMH72B241 | XAFB30CBAN1 | TM8V080B12MP12 | 15,100 | $755 |
| No | 211660095 | COLEMAN | HMH72B241 | XAFB30CXXN1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 211660090 | COLEMAN | HMH72B241 | XAFB30CXXN1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 211660084 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TPLC080B12MP13 | 15,100 | $755 |
| No | 211660079 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TM8V080B12MP12 | 15,100 | $755 |
| No | 211660073 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 211660068 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 211660062 | COLEMAN | HMH72B241 | XAHB30CBAN1 | TPLC080B12MP13 | 14,900 | $745 |
| No | 211660057 | COLEMAN | HMH72B241 | XAHB30CBAN1 | TM8V080B12MP12 | 14,900 | $745 |
| No | 211660051 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | TPLC080B12MP13 | 14,900 | $745 |
| No | 211660046 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | TM8V080B12MP12 | 14,900 | $745 |
| No | 211660040 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TPLC080B12MP13 | 14,800 | $740 |
| No | 211660035 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TM8V080B12MP12 | 14,800 | $740 |
| No | 211660029 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TPLC080B12MP13 | 14,800 | $740 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660024 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TM8V080B12MP12 | 14,800 | $740 |
| No | 211660019 | COLEMAN | HMH72B241 | XAUB30CXXN1+TXV | TM8Y060A12MP11 | 15,300 | $765 |
| No | 211660014 | COLEMAN | HMH72B241 | XAFB30CBAN1 | TM8Y060A12MP11 | 15,300 | $765 |
| No | 211660009 | COLEMAN | HMH72B241 | XAFB30CXXN1+TXV | TM8Y060A12MP11 | 15,300 | $765 |
| No | 211660004 | COLEMAN | HMH72B241 | XAHB30CBAN1 | TM8Y060A12MP11 | 15,000 | $750 |
| No | 211659999 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | TM8Y060A12MP11 | 15,000 | $750 |
| No | 211659994 | COLEMAN | HMH72B241 | XAUB30CXXN1+TXV | TM8Y080B12MP11 | 15,300 | $765 |
| No | 211659989 | COLEMAN | HMH72B241 | XAFB30CBAN1 | TM8Y080B12MP11 | 15,300 | $765 |
| No | 211659984 | COLEMAN | HMH72B241 | XAFB30CXXN1+TXV | TM8Y080B12MP11 | 15,300 | $765 |
| No | 211659979 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TM8Y080B12MP11 | 15,300 | $765 |
| No | 211659974 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TM8Y080B12MP11 | 15,300 | $765 |
| No | 211659969 | COLEMAN | HMH72B241 | XAHB30CBAN1 | TM8Y080B12MP11 | 15,000 | $750 |
| No | 211659964 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | TM8Y080B12MP11 | 15,000 | $750 |
| No | 211659959 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TM8Y080B12MP11 | 15,100 | $755 |
| No | 211659954 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TM8Y080B12MP11 | 15,100 | $755 |
| No | 211659944 | COLEMAN | HMH72B241 | XAFC30CBAN1 | TM8Y100C16MP11 | 15,100 | $755 |
| No | 211659934 | COLEMAN | HMH72B241 | XAFC30CXXN1+TXV | TM8Y100C16MP11 | 15,100 | $755 |
| No | 211659929 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TM8Y080C16MP11 | 14,800 | $740 |
| No | 211659924 | COLEMAN | HMH72B241 | XAHC30CBAN1 | TM8Y100C16MP11 | 14,800 | $740 |
| No | 211659919 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TM8Y080C16MP11 | 14,800 | $740 |
| No | 211659914 | COLEMAN | HMH72B241 | XAHC30CXXN1+TXV | TM8Y100C16MP11 | 14,800 | $740 |
| No | 211659909 | COLEMAN | HMH72B241 | XAUB30CXXN1+TXV | TM9E026A08MP12 | 15,400 | $770 |
| No | 211659904 | COLEMAN | HMH72B241 | XAFB30CBAN1 | TM9E026A08MP12 | 15,400 | $770 |
| No | 211659899 | COLEMAN | HMH72B241 | XAFB30CXXN1+TXV | TM9E026A08MP12 | 15,400 | $770 |
| No | 211659894 | COLEMAN | HMH72B241 | XAHB30CBAN1 | TM9E026A08MP12 | 15,100 | $755 |
| No | 211659889 | COLEMAN | HMH72B241 | XAHB30CXXN1+TXV | TM9E026A08MP12 | 15,100 | $755 |
| No | 207417129 | COLEMAN | HMH72B361 | XAFA30DXXN1+TXV | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 207417125 | COLEMAN | HMH72B361 | XAFA30DXXN1+TXV | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 207417032 | COLEMAN | HMH72B361 | XAFA30DXXN1+TXV | TM8Y060A12MP11 | 25,000 | $1,250 |
| No | 207416614 | COLEMAN | HMH72B361 | XAFA30DXXN1+TXV | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 207416590 | COLEMAN | HMH72B361 | XAFA30DXXN1+TXV | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 207416586 | COLEMAN | HMH72B361 | XAFA30DXXN1+TXV | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211719802 | COLEMAN | HMH72B341 | XAFC48FBCN1 | CPLC080B12MP13 | 25,800 | $1,290 |
| No | 211719801 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | CPLC080B12MP13 | 25,800 | $1,290 |
| No | 211719800 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | CPLC080B12MP13 | 25,800 | $1,290 |
| No | 211719798 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | CPLC060A12MP13 | 26,000 | $1,300 |
| No | 211719796 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | CPLC060A12MP13 | 26,000 | $1,300 |
| No | 211719791 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | CPLC080B12MP13 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211719790 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | CPLC080B12MP13 | 26,400 | $1,320 |
| No | 211719788 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | CPLC060A12MP13 | 25,600 | $1,280 |
| No | 211719787 | COLEMAN | HMH72B341 | XAHC48FBCN1 | CPLC080B12MP13 | 25,200 | $1,260 |
| No | 211719785 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | CPLC060A12MP13 | 25,600 | $1,280 |
| No | 211719783 | COLEMAN | HMH72B341 | XAFB36DBCN1 | CPLC060A12MP13 | 25,600 | $1,280 |
| No | 211719782 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | CPLC080B12MP13 | 26,400 | $1,320 |
| No | 211719781 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | CPLC080B12MP13 | 26,400 | $1,320 |
| No | 211719780 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | CPLC080B12MP13 | 25,600 | $1,280 |
| No | 211719747 | COLEMAN | HMH72B341 | XAHC36DBCN1 | CPLC080B12MP13 | 24,800 | $1,240 |
| No | 211719746 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | CPLC080B12MP13 | 24,800 | $1,240 |
| No | 211719723 | COLEMAN | HMH72B341 | XAHB36DBCN1 | CPLC060A12MP13 | 25,200 | $1,260 |
| No | 211719721 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | CPLC060A12MP13 | 25,200 | $1,260 |
| No | 211719719 | COLEMAN | HMH72B341 | XAFA30DXXN1+TXV | CPLC060A12MP13 | 25,800 | $1,290 |
| No | 211719717 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | CPLC060A12MP13 | 25,600 | $1,280 |
| No | 211719716 | COLEMAN | HMH72B341 | XAFB36DBCN1 | CPLC080B12MP13 | 25,400 | $1,270 |
| No | 211719715 | COLEMAN | HMH72B341 | XAHC48FBCN1 | CPLC100C20MP13 | 25,200 | $1,260 |
| No | 211719714 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | CPLC100C20MP13 | 25,200 | $1,260 |
| No | 211719713 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | CPLC080B12MP13 | 25,400 | $1,270 |
| No | 211719712 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | CPLC080B12MP13 | 25,400 | $1,270 |
| No | 211719711 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | CPLC080B12MP13 | 25,600 | $1,280 |
| No | 211719710 | COLEMAN | HMH72B341 | XAHB36DBCN1 | CPLC080B12MP13 | 25,000 | $1,250 |
| No | 211719709 | COLEMAN | HMH72B341 | XAFC36DBCN1 | CPLC080B12MP13 | 25,600 | $1,280 |
| No | 211719708 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | CPLC080B12MP13 | 25,000 | $1,250 |
| No | 211719707 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | CPLC080B12MP13 | 26,000 | $1,300 |
| No | 211398888 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211398874 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211398861 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211398847 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211398832 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TMLE080C16MP11 | 24,800 | $1,240 |
| No | 211398817 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TM8E080C16MP11 | 24,800 | $1,240 |
| No | 211398802 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TMLE080C16MP11 | 24,800 | $1,240 |
| No | 211398795 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TM8E080C16MP11 | 24,800 | $1,240 |
| No | 211398782 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TMLE080C16MP11 | 24,800 | $1,240 |
| No | 211398768 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TM8E080C16MP11 | 24,800 | $1,240 |
| No | 211398754 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TMLE080C16MP11 | 24,800 | $1,240 |
| No | 211398739 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TM8E080C16MP11 | 24,800 | $1,240 |
| No | 211398725 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211398710 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TMLE100B12MP11 | 25,400 | $1,270 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211398695 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211398680 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211398665 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211398650 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211398636 | COLEMAN | HMH72B341 | 0 | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 211398628 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 211398613 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 211398598 | COLEMAN | HMH72B341 | 0 | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 211398583 | COLEMAN | HMH72B341 | 0 | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211398568 | COLEMAN | HMH72B341 | 0 | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211398553 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211398538 | COLEMAN | HMH72B341 | 0 | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211398523 | COLEMAN | HMH72B341 | 0 | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211398508 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211398494 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211398479 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211398474 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211398460 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211398445 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211398430 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211398415 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211398400 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211398386 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211398371 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211398357 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211398344 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211398329 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TMLE120C16MP11 | 25,400 | $1,270 |
| No | 211398321 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TMLE120C16MP11 | 25,400 | $1,270 |
| No | 211398306 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TM8E120C16MP11 | 25,400 | $1,270 |
| No | 211398291 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TM8E120C16MP11 | 25,400 | $1,270 |
| No | 211398279 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TMLE120C16MP11 | 25,400 | $1,270 |
| No | 211398264 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TM8E120C16MP11 | 25,400 | $1,270 |
| No | 211398249 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TMLE120C16MP11 | 25,200 | $1,260 |
| No | 211398234 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TM8E120C16MP11 | 25,200 | $1,260 |
| No | 211398219 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TMLE120C16MP11 | 25,200 | $1,260 |
| No | 211398204 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TM8E120C16MP11 | 25,200 | $1,260 |
| No | 211398188 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211398173 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TM8E120C16MP11 | 24,800 | $1,240 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211398159 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211398150 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211398135 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211398120 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211398105 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211398090 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211398080 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TPLC080B12MP13 | 25,800 | $1,290 |
| No | 211398065 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TPLC080B12MP13 | 25,800 | $1,290 |
| No | 211398050 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TM8V080B12MP12 | 25,800 | $1,290 |
| No | 211398035 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TM8V080B12MP12 | 25,800 | $1,290 |
| No | 211398017 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TPLC080B12MP13 | 25,800 | $1,290 |
| No | 211398002 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TM8V080B12MP12 | 25,800 | $1,290 |
| No | 211397984 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TPLC080B12MP13 | 25,200 | $1,260 |
| No | 211397969 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TM8V080B12MP12 | 25,200 | $1,260 |
| No | 211397951 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TPLC080B12MP13 | 25,200 | $1,260 |
| No | 211397936 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TM8V080B12MP12 | 25,200 | $1,260 |
| No | 211397930 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | CPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397924 | COLEMAN | HMH72B341 | XAFC48FBCN1 | CPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397918 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | CPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397912 | COLEMAN | HMH72B341 | XAFC48FBCN1 | CPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397897 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397882 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397871 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397856 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397841 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211397826 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211397789 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211397774 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211397768 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | CPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397762 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | CPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397747 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397732 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397717 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211397694 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211397688 | COLEMAN | HMH72B341 | XAFD48FBCN1 | CPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397681 | COLEMAN | HMH72B341 | XAFD48FBCN1 | CPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397666 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397651 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TPLC080C16MP13 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211397636 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211397606 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211397600 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | CPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397594 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | CPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397579 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397564 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397549 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211397519 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211397513 | COLEMAN | HMH72B341 | XAHC48FBCN1 | CPLC100C16MP13 | 25,400 | $1,270 |
| No | 211397507 | COLEMAN | HMH72B341 | XAHC48FBCN1 | CPLC080C16MP13 | 25,400 | $1,270 |
| No | 211397492 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TPLC100C16MP13 | 25,400 | $1,270 |
| No | 211397477 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TPLC080C16MP13 | 25,400 | $1,270 |
| No | 211397468 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TMLV100C16MP12 | 25,400 | $1,270 |
| No | 211397439 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TM8V100C16MP12 | 25,400 | $1,270 |
| No | 211397437 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | CPLC100C16MP13 | 25,400 | $1,270 |
| No | 211397433 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | CPLC080C16MP13 | 25,400 | $1,270 |
| No | 211397418 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TPLC100C16MP13 | 25,400 | $1,270 |
| No | 211397403 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TPLC080C16MP13 | 25,400 | $1,270 |
| No | 211397388 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TMLV100C16MP12 | 25,400 | $1,270 |
| No | 211397365 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TM8V100C16MP12 | 25,400 | $1,270 |
| No | 211397359 | COLEMAN | HMH72B341 | XAHD48FBCN1 | CPLC100C16MP13 | 25,200 | $1,260 |
| No | 211397353 | COLEMAN | HMH72B341 | XAHD48FBCN1 | CPLC080C16MP13 | 25,200 | $1,260 |
| No | 211397338 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TPLC100C16MP13 | 25,200 | $1,260 |
| No | 211397323 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TPLC080C16MP13 | 25,200 | $1,260 |
| No | 211397310 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TMLV100C16MP12 | 25,200 | $1,260 |
| No | 211397296 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TM8V080C16MP12 | 25,200 | $1,260 |
| No | 211397281 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TM8V100C16MP12 | 25,200 | $1,260 |
| No | 211397275 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | CPLC100C16MP13 | 25,200 | $1,260 |
| No | 211397273 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | CPLC080C16MP13 | 25,200 | $1,260 |
| No | 211397258 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TPLC100C16MP13 | 25,200 | $1,260 |
| No | 211397243 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TPLC080C16MP13 | 25,200 | $1,260 |
| No | 211397228 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TMLV100C16MP12 | 25,200 | $1,260 |
| No | 211397212 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TM8V080C16MP12 | 25,200 | $1,260 |
| No | 211397198 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TM8V100C16MP12 | 25,200 | $1,260 |
| No | 211397192 | COLEMAN | HMH72B341 | XAHC48FBCN1 | CPLC120C20MP13 | 25,200 | $1,260 |
| No | 211397173 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TPLC120C20MP13 | 25,200 | $1,260 |
| No | 211397165 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TPLC100C20MP13 | 25,200 | $1,260 |
| No | 211397152 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TMLV120C20MP12 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211397137 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TM8V100C20MP12 | 25,200 | $1,260 |
| No | 211397126 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TM8V120C20MP12 | 25,200 | $1,260 |
| No | 211397119 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | CPLC120C20MP13 | 25,200 | $1,260 |
| No | 211397101 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TPLC120C20MP13 | 25,200 | $1,260 |
| No | 211397086 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TPLC100C20MP13 | 25,200 | $1,260 |
| No | 211397071 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TMLV120C20MP12 | 25,200 | $1,260 |
| No | 211397056 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TM8V100C20MP12 | 25,200 | $1,260 |
| No | 211397041 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TM8V120C20MP12 | 25,200 | $1,260 |
| No | 211397026 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211397011 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211396996 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211396982 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211396972 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211396957 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TM8Y080C16MP11 | 25,800 | $1,290 |
| No | 211396942 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TM8Y080C16MP11 | 25,800 | $1,290 |
| No | 211396927 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211396918 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211396903 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TM8Y080C16MP11 | 25,800 | $1,290 |
| No | 211396888 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211396873 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TM8Y080C16MP11 | 25,800 | $1,290 |
| No | 211396858 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211396843 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TM8Y080C16MP11 | 25,800 | $1,290 |
| No | 211396828 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211396813 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TM8Y080C16MP11 | 25,400 | $1,270 |
| No | 211396801 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211396790 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TM8Y080C16MP11 | 25,400 | $1,270 |
| No | 211396775 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211396760 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TM8Y080C16MP11 | 25,400 | $1,270 |
| No | 211396745 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211396730 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TM8Y080C16MP11 | 25,400 | $1,270 |
| No | 211396715 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211396701 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TM8Y100C20MP11 | 25,600 | $1,280 |
| No | 211396685 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TM8Y100C20MP11 | 25,600 | $1,280 |
| No | 211396674 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TM8Y120C20MP11 | 25,600 | $1,280 |
| No | 211396659 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TM8Y120C20MP11 | 25,600 | $1,280 |
| No | 211396643 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TM8Y100C20MP11 | 25,600 | $1,280 |
| No | 211396628 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TM8Y120C20MP11 | 25,600 | $1,280 |
| No | 211396620 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TM8Y100C20MP11 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211396604 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TM8Y120C20MP11 | 25,600 | $1,280 |
| No | 211396592 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TM8Y100C20MP11 | 25,600 | $1,280 |
| No | 211396577 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TM8Y120C20MP11 | 25,600 | $1,280 |
| No | 211396562 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TM8Y100C20MP11 | 25,200 | $1,260 |
| No | 211396548 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211396533 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TM8Y100C20MP11 | 25,200 | $1,260 |
| No | 211396511 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211396487 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TM8Y100C20MP11 | 25,200 | $1,260 |
| No | 211396464 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211396439 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TM8Y100C20MP11 | 25,200 | $1,260 |
| No | 211396419 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211396395 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211396372 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211396350 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211396328 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211396304 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211396282 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TM9E080B12MP12 | 25,600 | $1,280 |
| No | 211396261 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TM9E080B12MP12 | 25,600 | $1,280 |
| No | 211396238 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TM9E080B12MP12 | 25,600 | $1,280 |
| No | 211396217 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211396197 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211396177 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TM9E080C16MP12 | 26,000 | $1,300 |
| No | 211396162 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TM9E080C16MP12 | 26,000 | $1,300 |
| No | 211396139 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TM9E080C16MP12 | 26,000 | $1,300 |
| No | 211396126 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TM9E080C16MP12 | 26,000 | $1,300 |
| No | 211396111 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TM9E080C16MP12 | 26,000 | $1,300 |
| No | 211396095 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211396080 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211396065 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211396051 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211396036 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211396024 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211396009 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211395993 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211395979 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211395965 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211395951 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211395939 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TM9E100C16MP12 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211395924 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211395918 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | CP9C060B12MP13 | 25,600 | $1,280 |
| No | 211395914 | COLEMAN | HMH72B341 | XAFC48FBCN1 | CP9C060B12MP13 | 25,600 | $1,280 |
| No | 211395902 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211395891 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211395876 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211395858 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211395849 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | CP9C060B12MP13 | 25,600 | $1,280 |
| No | 211395825 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211395804 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211395798 | COLEMAN | HMH72B341 | XAHC48FBCN1 | CP9C060B12MP13 | 25,200 | $1,260 |
| No | 211395781 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TP9C060B12MP13 | 25,200 | $1,260 |
| No | 211395761 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TM9V060B12MP12 | 25,200 | $1,260 |
| No | 211395752 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | CP9C060B12MP13 | 25,200 | $1,260 |
| No | 211395731 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TP9C060B12MP13 | 25,200 | $1,260 |
| No | 211395711 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TM9V060B12MP12 | 25,200 | $1,260 |
| No | 211395701 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | CP9C080B12MP13 | 25,600 | $1,280 |
| No | 211395690 | COLEMAN | HMH72B341 | XAFC48FBCN1 | CP9C080B12MP13 | 25,600 | $1,280 |
| No | 211395670 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TP9C080B12MP13 | 25,600 | $1,280 |
| No | 211395646 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TP9C080B12MP13 | 25,600 | $1,280 |
| No | 211395626 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TM9V080B12MP12 | 25,600 | $1,280 |
| No | 211395602 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TM9V080B12MP12 | 25,600 | $1,280 |
| No | 211395595 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | CP9C080B12MP13 | 25,600 | $1,280 |
| No | 211395571 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TP9C080B12MP13 | 25,600 | $1,280 |
| No | 211395549 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TM9V080B12MP12 | 25,600 | $1,280 |
| No | 211395539 | COLEMAN | HMH72B341 | XAHC48FBCN1 | CP9C080B12MP13 | 25,200 | $1,260 |
| No | 211395514 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TP9C080B12MP13 | 25,200 | $1,260 |
| No | 211395496 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TM9V080B12MP12 | 25,200 | $1,260 |
| No | 211395488 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | CP9C080B12MP13 | 25,200 | $1,260 |
| No | 211395468 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TP9C080B12MP13 | 25,200 | $1,260 |
| No | 211395445 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TM9V080B12MP12 | 25,200 | $1,260 |
| No | 211395435 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | CP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395424 | COLEMAN | HMH72B341 | XAFC48FBCN1 | CP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395402 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395381 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395362 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211395343 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211395334 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | CP9C080C16MP13 | 25,400 | $1,270 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211395311 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395285 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211395275 | COLEMAN | HMH72B341 | XAFD48FBCN1 | CP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395250 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395229 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211395219 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | CP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395195 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395170 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211395161 | COLEMAN | HMH72B341 | XAHC48FBCN1 | CP9C080C16MP13 | 24,800 | $1,240 |
| No | 211395138 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TP9C080C16MP13 | 24,800 | $1,240 |
| No | 211395113 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TM9V080C16MP12 | 24,800 | $1,240 |
| No | 211395106 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | CP9C080C16MP13 | 24,800 | $1,240 |
| No | 211395085 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TP9C080C16MP13 | 24,800 | $1,240 |
| No | 211395065 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TM9V080C16MP12 | 24,800 | $1,240 |
| No | 211395055 | COLEMAN | HMH72B341 | XAHD48FBCN1 | CP9C080C16MP13 | 25,000 | $1,250 |
| No | 211395042 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TP9C080C16MP13 | 25,000 | $1,250 |
| No | 211395030 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TM9V080C16MP12 | 25,000 | $1,250 |
| No | 211395024 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | CP9C080C16MP13 | 25,000 | $1,250 |
| No | 211395010 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TP9C080C16MP13 | 25,000 | $1,250 |
| No | 211394996 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TM9V080C16MP12 | 25,000 | $1,250 |
| No | 211394991 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | CP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394985 | COLEMAN | HMH72B341 | XAFC48FBCN1 | CP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394970 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394955 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394941 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211394929 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211394923 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | CP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394909 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394895 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211394890 | COLEMAN | HMH72B341 | XAFD48FBCN1 | CP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394876 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394862 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211394856 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | CP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394841 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394827 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211394821 | COLEMAN | HMH72B341 | XAHC48FBCN1 | CP9C100C16MP13 | 24,800 | $1,240 |
| No | 211394806 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211394791 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TM9V100C16MP12 | 24,800 | $1,240 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211394785 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | CP9C100C16MP13 | 24,800 | $1,240 |
| No | 211394770 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211394756 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TM9V100C16MP12 | 24,800 | $1,240 |
| No | 211394750 | COLEMAN | HMH72B341 | XAHD48FBCN1 | CP9C100C16MP13 | 24,800 | $1,240 |
| No | 211394735 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211394721 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TM9V100C16MP12 | 24,800 | $1,240 |
| No | 211394716 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | CP9C100C16MP13 | 24,800 | $1,240 |
| No | 211394703 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211394689 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TM9V100C16MP12 | 24,800 | $1,240 |
| No | 211394683 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | CP9C100C20MP13 | 25,800 | $1,290 |
| No | 211394677 | COLEMAN | HMH72B341 | XAFC48FBCN1 | CP9C100C20MP13 | 25,800 | $1,290 |
| No | 211394662 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TP9C100C20MP13 | 25,800 | $1,290 |
| No | 211394650 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TP9C100C20MP13 | 25,800 | $1,290 |
| No | 211394635 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TM9V100C20MP12 | 25,800 | $1,290 |
| No | 211394624 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TM9V100C20MP12 | 25,800 | $1,290 |
| No | 211394618 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | CP9C100C20MP13 | 25,800 | $1,290 |
| No | 211394603 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TP9C100C20MP13 | 25,800 | $1,290 |
| No | 211394588 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TM9V100C20MP12 | 25,800 | $1,290 |
| No | 211394582 | COLEMAN | HMH72B341 | XAFD48FBCN1 | CP9C100C20MP13 | 25,600 | $1,280 |
| No | 211394567 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TP9C100C20MP13 | 25,600 | $1,280 |
| No | 211394554 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TM9V100C20MP12 | 25,600 | $1,280 |
| No | 211394548 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | CP9C100C20MP13 | 25,600 | $1,280 |
| No | 211394534 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TP9C100C20MP13 | 25,600 | $1,280 |
| No | 211394523 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TM9V100C20MP12 | 25,600 | $1,280 |
| No | 211394517 | COLEMAN | HMH72B341 | XAHC48FBCN1 | CP9C100C20MP13 | 25,000 | $1,250 |
| No | 211394504 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TP9C100C20MP13 | 25,000 | $1,250 |
| No | 211394492 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TM9V100C20MP12 | 25,000 | $1,250 |
| No | 211394486 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | CP9C100C20MP13 | 25,000 | $1,250 |
| No | 211394473 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TP9C100C20MP13 | 25,000 | $1,250 |
| No | 211394458 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TM9V100C20MP12 | 25,000 | $1,250 |
| No | 211394452 | COLEMAN | HMH72B341 | XAHD48FBCN1 | CP9C100C20MP13 | 25,200 | $1,260 |
| No | 211394437 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TP9C100C20MP13 | 25,200 | $1,260 |
| No | 211394422 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TM9V100C20MP12 | 25,200 | $1,260 |
| No | 211394416 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | CP9C100C20MP13 | 25,200 | $1,260 |
| No | 211394404 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TP9C100C20MP13 | 25,200 | $1,260 |
| No | 211394391 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TM9V100C20MP12 | 25,200 | $1,260 |
| No | 211394385 | COLEMAN | HMH72B341 | XAFD48FBCN1 | CP9C120D20MP13 | 25,400 | $1,270 |
| No | 211394370 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TP9C120D20MP13 | 25,400 | $1,270 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211394360 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TM9V120D20MP12 | 25,400 | $1,270 |
| No | 211394353 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | CP9C120D20MP13 | 25,400 | $1,270 |
| No | 211394339 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TP9C120D20MP13 | 25,400 | $1,270 |
| No | 211394325 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TM9V120D20MP12 | 25,400 | $1,270 |
| No | 211394320 | COLEMAN | HMH72B341 | XAHD48FBCN1 | CP9C120D20MP13 | 24,800 | $1,240 |
| No | 211394308 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TP9C120D20MP13 | 24,800 | $1,240 |
| No | 211394294 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TM9V120D20MP12 | 24,800 | $1,240 |
| No | 211394288 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | CP9C120D20MP13 | 24,800 | $1,240 |
| No | 211394273 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TP9C120D20MP13 | 24,800 | $1,240 |
| No | 211394258 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TM9V120D20MP12 | 24,800 | $1,240 |
| No | 211394243 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TM9Y060B12MP11 | 25,800 | $1,290 |
| No | 211394231 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TM9Y060B12MP11 | 25,800 | $1,290 |
| No | 211394216 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TM9Y060B12MP11 | 25,800 | $1,290 |
| No | 211394203 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TM9Y060B12MP11 | 25,400 | $1,270 |
| No | 211394188 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TM9Y060B12MP11 | 25,400 | $1,270 |
| No | 211394173 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211394160 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211394147 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211394132 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TM9Y080B12MP11 | 25,400 | $1,270 |
| No | 211394119 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TM9Y080B12MP11 | 25,400 | $1,270 |
| No | 211394104 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TM9Y080C16MP11 | 25,800 | $1,290 |
| No | 211394091 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TM9Y080C16MP11 | 25,800 | $1,290 |
| No | 211394076 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TM9Y080C16MP11 | 25,800 | $1,290 |
| No | 211394061 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TM9Y080C16MP11 | 25,400 | $1,270 |
| No | 211394046 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TM9Y080C16MP11 | 25,400 | $1,270 |
| No | 211394031 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TM9Y080C16MP11 | 25,200 | $1,260 |
| No | 211394016 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TM9Y080C16MP11 | 25,200 | $1,260 |
| No | 211394001 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TM9Y080C16MP11 | 25,000 | $1,250 |
| No | 211393986 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TM9Y080C16MP11 | 25,000 | $1,250 |
| No | 211393971 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TM9Y100C16MP11 | 25,800 | $1,290 |
| No | 211393956 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TM9Y100C16MP11 | 25,800 | $1,290 |
| No | 211393941 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TM9Y100C16MP11 | 25,800 | $1,290 |
| No | 211393926 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TM9Y100C16MP11 | 25,400 | $1,270 |
| No | 211393911 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TM9Y100C16MP11 | 25,400 | $1,270 |
| No | 211393896 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TM9Y100C16MP11 | 25,200 | $1,260 |
| No | 211393881 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TM9Y100C16MP11 | 25,200 | $1,260 |
| No | 211393866 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TM9Y100C16MP11 | 25,200 | $1,260 |
| No | 211393851 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TM9Y100C16MP11 | 25,200 | $1,260 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211393836 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TM9Y120D20MP11 | 25,400 | $1,270 |
| No | 211393821 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TM9Y120D20MP11 | 25,400 | $1,270 |
| No | 211393806 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TM9Y120D20MP11 | 25,000 | $1,250 |
| No | 211393791 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TM9Y120D20MP11 | 25,000 | $1,250 |
| No | 211393776 | COLEMAN | HMH72B341 | XAFA30DXXN1+TXV | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 211393761 | COLEMAN | HMH72B341 | XAFA30DXXN1+TXV | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 211393747 | COLEMAN | HMH72B341 | XAFA30DXXN1+TXV | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211393732 | COLEMAN | HMH72B341 | XAFA30DXXN1+TXV | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 211393717 | COLEMAN | HMH72B341 | XAFA30DXXN1+TXV | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 211393702 | COLEMAN | HMH72B341 | XAFA30DXXN1+TXV | TPLC060A12MP13 | 25,800 | $1,290 |
| No | 211393686 | COLEMAN | HMH72B341 | XAFA30DXXN1+TXV | TMLV060A12MP12 | 25,800 | $1,290 |
| No | 211393672 | COLEMAN | HMH72B341 | XAFA30DXXN1+TXV | TM8V060A12MP12 | 25,800 | $1,290 |
| No | 211393657 | COLEMAN | HMH72B341 | XAFA30DXXN1+TXV | TM8Y060A12MP11 | 25,200 | $1,260 |
| No | 211393629 | COLEMAN | HMH72B341 | JHETB36DBCS2N1 | | 25,400 | $1,270 |
| No | 211393616 | COLEMAN | HMH72B341 | JHVTB36DBCC2N1 | | 25,200 | $1,260 |
| No | 211393602 | COLEMAN | HMH72B341 | JHVTC36DBCC2N1 | | 25,400 | $1,270 |
| No | 211393588 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | TL8E060A12UH11 | 26,200 | $1,310 |
| No | 211393574 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | TL8E060A12UH11 | 26,200 | $1,310 |
| No | 211393559 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 211393544 | COLEMAN | HMH72B341 | XAFB36DBCN1 | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 211393529 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 211393515 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | TL8E060A12UH11 | 25,800 | $1,290 |
| No | 211393499 | COLEMAN | HMH72B341 | XAHB36DBCN1 | TL8E060A12UH11 | 25,000 | $1,250 |
| No | 211393485 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | TL8E060A12UH11 | 25,000 | $1,250 |
| No | 211393470 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TL8E080C16UH11 | 26,600 | $1,330 |
| No | 211393455 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211393440 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211393426 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TL8E080C16UH11 | 26,000 | $1,300 |
| No | 211393411 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TL8E080C16UH11 | 25,800 | $1,290 |
| No | 211393396 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TL8E080C16UH11 | 25,800 | $1,290 |
| No | 211393381 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TL8E100C20UH11 | 26,400 | $1,320 |
| No | 211393366 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211393352 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211393334 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TL8E100C20UH11 | 25,800 | $1,290 |
| No | 211393319 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TL8E100C20UH11 | 25,600 | $1,280 |
| No | 211393304 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TL8E100C20UH11 | 25,600 | $1,280 |
| No | 211393290 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | TL9E060B12UH11 | 26,400 | $1,320 |
| No | 211393275 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | TL9E060B12UH11 | 26,400 | $1,320 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211393260 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | TL9E060B12UH11 | 25,000 | $1,250 |
| No | 211393249 | COLEMAN | HMH72B341 | XAFB36DBCN1 | TL9E060B12UH11 | 25,000 | $1,250 |
| No | 211393237 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | TL9E060B12UH11 | 25,000 | $1,250 |
| No | 211393222 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TL9E060B12UH11 | 26,400 | $1,320 |
| No | 211393207 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TL9E060B12UH11 | 25,600 | $1,280 |
| No | 211393192 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TL9E060B12UH11 | 25,600 | $1,280 |
| No | 211393177 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | TL9E060B12UH11 | 25,200 | $1,260 |
| No | 211393166 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TL9E060B12UH11 | 26,000 | $1,300 |
| No | 211393151 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TL9E060B12UH11 | 24,400 | $1,220 |
| No | 211393136 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TL9E060B12UH11 | 24,400 | $1,220 |
| No | 211393121 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TL9E080C16UH11 | 26,200 | $1,310 |
| No | 211393106 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TL9E080C16UH11 | 25,800 | $1,290 |
| No | 211393091 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TL9E080C16UH11 | 25,800 | $1,290 |
| No | 211393076 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TL9E080C16UH11 | 26,400 | $1,320 |
| No | 211393071 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TL9E080C16UH11 | 25,400 | $1,270 |
| No | 211393057 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TL9E080C16UH11 | 25,400 | $1,270 |
| No | 211393042 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TL9E100C20UH11 | 26,400 | $1,320 |
| No | 211393028 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TL9E100C20UH11 | 26,200 | $1,310 |
| No | 211393012 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TL9E100C20UH11 | 26,200 | $1,310 |
| No | 211392997 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TL9E100C20UH11 | 26,000 | $1,300 |
| No | 211392982 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TL9E100C20UH11 | 25,600 | $1,280 |
| No | 211392967 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TL9E100C20UH11 | 25,600 | $1,280 |
| No | 211392953 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | TMLE040A12MP11 | 26,200 | $1,310 |
| No | 211392938 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | TM8E040A12MP11 | 26,200 | $1,310 |
| No | 211392923 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | TMLE040A12MP11 | 26,200 | $1,310 |
| No | 211392908 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | TM8E040A12MP11 | 26,200 | $1,310 |
| No | 211392894 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 211392884 | COLEMAN | HMH72B341 | XAFB36DBCN1 | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 211392872 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211392857 | COLEMAN | HMH72B341 | XAFB36DBCN1 | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211392842 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 211392827 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211392812 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | TMLE040A12MP11 | 25,600 | $1,280 |
| No | 211392797 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | TM8E040A12MP11 | 25,600 | $1,280 |
| No | 211392782 | COLEMAN | HMH72B341 | XAHB36DBCN1 | TMLE040A12MP11 | 24,800 | $1,240 |
| No | 211392767 | COLEMAN | HMH72B341 | XAHB36DBCN1 | TM8E040A12MP11 | 24,800 | $1,240 |
| No | 211392752 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | TMLE040A12MP11 | 24,800 | $1,240 |
| No | 211392737 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | TM8E040A12MP11 | 24,800 | $1,240 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211392722 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | TMLE060A12MP11 | 26,200 | $1,310 |
| No | 211392707 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | TM8E060A12MP11 | 26,200 | $1,310 |
| No | 211392697 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | TMLE060A12MP11 | 26,200 | $1,310 |
| No | 211392690 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | TM8E060A12MP11 | 26,200 | $1,310 |
| No | 211392675 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 211392660 | COLEMAN | HMH72B341 | XAFB36DBCN1 | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 211392646 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 211392631 | COLEMAN | HMH72B341 | XAFB36DBCN1 | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 211392616 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 211392601 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 211392586 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | TMLE060A12MP11 | 25,800 | $1,290 |
| No | 211392571 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | TM8E060A12MP11 | 25,800 | $1,290 |
| No | 211392557 | COLEMAN | HMH72B341 | XAHB36DBCN1 | TMLE060A12MP11 | 25,000 | $1,250 |
| No | 211392545 | COLEMAN | HMH72B341 | XAHB36DBCN1 | TM8E060A12MP11 | 25,000 | $1,250 |
| No | 211392530 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | TMLE060A12MP11 | 25,000 | $1,250 |
| No | 211392519 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | TM8E060A12MP11 | 25,000 | $1,250 |
| No | 211392504 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | TMLE080B12MP11 | 26,800 | $1,340 |
| No | 211392489 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | TM8E080B12MP11 | 26,800 | $1,340 |
| No | 211392474 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | TMLE080B12MP11 | 26,800 | $1,340 |
| No | 211392459 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | TM8E080B12MP11 | 26,800 | $1,340 |
| No | 211392448 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | TMLE080B12MP11 | 25,800 | $1,290 |
| No | 211392433 | COLEMAN | HMH72B341 | XAFB36DBCN1 | TMLE080B12MP11 | 25,800 | $1,290 |
| No | 211392418 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211392408 | COLEMAN | HMH72B341 | XAFB36DBCN1 | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211392394 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | TMLE080B12MP11 | 25,800 | $1,290 |
| No | 211392379 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211392364 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TMLE080B12MP11 | 26,800 | $1,340 |
| No | 211392349 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TM8E080B12MP11 | 26,800 | $1,340 |
| No | 211392334 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TMLE080B12MP11 | 25,800 | $1,290 |
| No | 211392319 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211392308 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TMLE080B12MP11 | 25,800 | $1,290 |
| No | 211392292 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211392278 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | TMLE080B12MP11 | 26,200 | $1,310 |
| No | 211392273 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | TM8E080B12MP11 | 26,200 | $1,310 |
| No | 211392259 | COLEMAN | HMH72B341 | XAHB36DBCN1 | TMLE080B12MP11 | 25,000 | $1,250 |
| No | 211392244 | COLEMAN | HMH72B341 | XAHB36DBCN1 | TM8E080B12MP11 | 25,000 | $1,250 |
| No | 211392229 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | TMLE080B12MP11 | 25,000 | $1,250 |
| No | 211392214 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | TM8E080B12MP11 | 25,000 | $1,250 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211392199 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TMLE080B12MP11 | 26,400 | $1,320 |
| No | 211392193 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TM8E080B12MP11 | 26,400 | $1,320 |
| No | 211392178 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TMLE080B12MP11 | 25,000 | $1,250 |
| No | 211392162 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TM8E080B12MP11 | 25,000 | $1,250 |
| No | 211392147 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TMLE080B12MP11 | 25,000 | $1,250 |
| No | 211392132 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TM8E080B12MP11 | 25,000 | $1,250 |
| No | 211392117 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TMLE080C16MP11 | 26,000 | $1,300 |
| No | 211392102 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TM8E080C16MP11 | 26,000 | $1,300 |
| No | 211392087 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211392072 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211392060 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211392053 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211392038 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TMLE080C16MP11 | 25,600 | $1,280 |
| No | 211392023 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TM8E080C16MP11 | 25,600 | $1,280 |
| No | 211392009 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TMLE080C16MP11 | 24,600 | $1,230 |
| No | 211391993 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TM8E080C16MP11 | 24,600 | $1,230 |
| No | 211391978 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TMLE080C16MP11 | 24,600 | $1,230 |
| No | 211391963 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TM8E080C16MP11 | 24,600 | $1,230 |
| No | 211391948 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | TMLE100B12MP11 | 26,200 | $1,310 |
| No | 211391933 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | TM8E100B12MP11 | 26,200 | $1,310 |
| No | 211391918 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | TMLE100B12MP11 | 26,200 | $1,310 |
| No | 211391903 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | TM8E100B12MP11 | 26,200 | $1,310 |
| No | 211391888 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211391873 | COLEMAN | HMH72B341 | XAFB36DBCN1 | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211391858 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211391844 | COLEMAN | HMH72B341 | XAFB36DBCN1 | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211391829 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211391815 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211391800 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TMLE100B12MP11 | 26,200 | $1,310 |
| No | 211391785 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TM8E100B12MP11 | 26,200 | $1,310 |
| No | 211391774 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211391759 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211391745 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211391734 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211391719 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | TMLE100B12MP11 | 25,800 | $1,290 |
| No | 211391704 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | TM8E100B12MP11 | 25,800 | $1,290 |
| No | 211391698 | COLEMAN | HMH72B341 | XAHB36DBCN1 | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 211391687 | COLEMAN | HMH72B341 | XAHB36DBCN1 | TM8E100B12MP11 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211391672 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 211391657 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 211391642 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TMLE100B12MP11 | 25,600 | $1,280 |
| No | 211391629 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TM8E100B12MP11 | 25,600 | $1,280 |
| No | 211391620 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TMLE100B12MP11 | 24,800 | $1,240 |
| No | 211391605 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TM8E100B12MP11 | 24,800 | $1,240 |
| No | 211391590 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TMLE100B12MP11 | 24,800 | $1,240 |
| No | 211391575 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TM8E100B12MP11 | 24,800 | $1,240 |
| No | 211391560 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TMLE100C16MP11 | 26,000 | $1,300 |
| No | 211391545 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TM8E100C16MP11 | 26,000 | $1,300 |
| No | 211391530 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TMLE100C16MP11 | 25,200 | $1,260 |
| No | 211391515 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TM8E100C16MP11 | 25,200 | $1,260 |
| No | 211391500 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TMLE100C16MP11 | 25,200 | $1,260 |
| No | 211391485 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TM8E100C16MP11 | 25,200 | $1,260 |
| No | 211391470 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TMLE100C16MP11 | 25,600 | $1,280 |
| No | 211391455 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TM8E100C16MP11 | 25,600 | $1,280 |
| No | 211391441 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211391425 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211391410 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211391395 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211391380 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TMLE120C16MP11 | 26,200 | $1,310 |
| No | 211391365 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TM8E120C16MP11 | 26,200 | $1,310 |
| No | 211391350 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TMLE120C16MP11 | 25,200 | $1,260 |
| No | 211391335 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TM8E120C16MP11 | 25,200 | $1,260 |
| No | 211391320 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TMLE120C16MP11 | 25,200 | $1,260 |
| No | 211391305 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TM8E120C16MP11 | 25,200 | $1,260 |
| No | 211391291 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TMLE120C16MP11 | 25,600 | $1,280 |
| No | 211391276 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TM8E120C16MP11 | 25,600 | $1,280 |
| No | 211391261 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211391246 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211391232 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211391217 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211391202 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | TPLC060A12MP13 | 26,000 | $1,300 |
| No | 211391187 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | TMLV060A12MP12 | 26,000 | $1,300 |
| No | 211391172 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | TM8V060A12MP12 | 26,000 | $1,300 |
| No | 211391157 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | TPLC060A12MP13 | 26,000 | $1,300 |
| No | 211391143 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | TMLV060A12MP12 | 26,000 | $1,300 |
| No | 211391128 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | TM8V060A12MP12 | 26,000 | $1,300 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211391113 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | TPLC060A12MP13 | 25,600 | $1,280 |
| No | 211391098 | COLEMAN | HMH72B341 | XAFB36DBCN1 | TPLC060A12MP13 | 25,600 | $1,280 |
| No | 211391083 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | TMLV060A12MP12 | 25,600 | $1,280 |
| No | 211391068 | COLEMAN | HMH72B341 | XAFB36DBCN1 | TMLV060A12MP12 | 25,600 | $1,280 |
| No | 211391053 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | TM8V060A12MP12 | 25,600 | $1,280 |
| No | 211391038 | COLEMAN | HMH72B341 | XAFB36DBCN1 | TM8V060A12MP12 | 25,600 | $1,280 |
| No | 211391023 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | TPLC060A12MP13 | 25,600 | $1,280 |
| No | 211391008 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | TMLV060A12MP12 | 25,600 | $1,280 |
| No | 211390993 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | TM8V060A12MP12 | 25,600 | $1,280 |
| No | 211390978 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | TPLC060A12MP13 | 25,600 | $1,280 |
| No | 211390963 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | TMLV060A12MP12 | 25,600 | $1,280 |
| No | 211390948 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | TM8V060A12MP12 | 25,600 | $1,280 |
| No | 211390934 | COLEMAN | HMH72B341 | XAHB36DBCN1 | TPLC060A12MP13 | 25,200 | $1,260 |
| No | 211390919 | COLEMAN | HMH72B341 | XAHB36DBCN1 | TMLV060A12MP12 | 25,200 | $1,260 |
| No | 211390904 | COLEMAN | HMH72B341 | XAHB36DBCN1 | TM8V060A12MP12 | 25,200 | $1,260 |
| No | 211390889 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | TPLC060A12MP13 | 25,200 | $1,260 |
| No | 211390875 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | TMLV060A12MP12 | 25,200 | $1,260 |
| No | 211390860 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | TM8V060A12MP12 | 25,200 | $1,260 |
| No | 211390842 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | TPLC080B12MP13 | 26,400 | $1,320 |
| No | 211390827 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | TM8V080B12MP12 | 26,400 | $1,320 |
| No | 211390809 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | TPLC080B12MP13 | 26,400 | $1,320 |
| No | 211390794 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | TM8V080B12MP12 | 26,400 | $1,320 |
| No | 211390774 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | TPLC080B12MP13 | 25,400 | $1,270 |
| No | 211390759 | COLEMAN | HMH72B341 | XAFB36DBCN1 | TPLC080B12MP13 | 25,400 | $1,270 |
| No | 211390744 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | TM8V080B12MP12 | 25,400 | $1,270 |
| No | 211390729 | COLEMAN | HMH72B341 | XAFB36DBCN1 | TM8V080B12MP12 | 25,400 | $1,270 |
| No | 211390711 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | TPLC080B12MP13 | 25,400 | $1,270 |
| No | 211390696 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | TM8V080B12MP12 | 25,400 | $1,270 |
| No | 211390678 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TPLC080B12MP13 | 26,400 | $1,320 |
| No | 211390663 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TM8V080B12MP12 | 26,400 | $1,320 |
| No | 211390645 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TPLC080B12MP13 | 25,600 | $1,280 |
| No | 211390631 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TM8V080B12MP12 | 25,600 | $1,280 |
| No | 211390613 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TPLC080B12MP13 | 25,600 | $1,280 |
| No | 211390598 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TM8V080B12MP12 | 25,600 | $1,280 |
| No | 211390580 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | TPLC080B12MP13 | 25,600 | $1,280 |
| No | 211390565 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | TM8V080B12MP12 | 25,600 | $1,280 |
| No | 211390547 | COLEMAN | HMH72B341 | XAHB36DBCN1 | TPLC080B12MP13 | 25,000 | $1,250 |
| No | 211390532 | COLEMAN | HMH72B341 | XAHB36DBCN1 | TM8V080B12MP12 | 25,000 | $1,250 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211390514 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | TPLC080B12MP13 | 25,000 | $1,250 |
| No | 211390499 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | TM8V080B12MP12 | 25,000 | $1,250 |
| No | 211390482 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TPLC080B12MP13 | 26,000 | $1,300 |
| No | 211390467 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TM8V080B12MP12 | 26,000 | $1,300 |
| No | 211390449 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TPLC080B12MP13 | 24,800 | $1,240 |
| No | 211390434 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TM8V080B12MP12 | 24,800 | $1,240 |
| No | 211390416 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TPLC080B12MP13 | 24,800 | $1,240 |
| No | 211390402 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TM8V080B12MP12 | 24,800 | $1,240 |
| No | 211390396 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | CPLC100C16MP13 | 26,400 | $1,320 |
| No | 211390390 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | CPLC080C16MP13 | 26,400 | $1,320 |
| No | 211390375 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TPLC100C16MP13 | 26,400 | $1,320 |
| No | 211390360 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TPLC080C16MP13 | 26,400 | $1,320 |
| No | 211390345 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TMLV100C16MP12 | 26,400 | $1,320 |
| No | 211390332 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TM8V080C16MP12 | 26,400 | $1,320 |
| No | 211390318 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TM8V100C16MP12 | 26,400 | $1,320 |
| No | 211390312 | COLEMAN | HMH72B341 | XAFC36DBCN1 | CPLC100C16MP13 | 25,400 | $1,270 |
| No | 211390307 | COLEMAN | HMH72B341 | XAFC36DBCN1 | CPLC080C16MP13 | 25,400 | $1,270 |
| No | 211390293 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TPLC100C16MP13 | 25,400 | $1,270 |
| No | 211390279 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TPLC080C16MP13 | 25,400 | $1,270 |
| No | 211390265 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TMLV100C16MP12 | 25,400 | $1,270 |
| No | 211390251 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TM8V080C16MP12 | 25,400 | $1,270 |
| No | 211390237 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TM8V100C16MP12 | 25,400 | $1,270 |
| No | 211390231 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | CPLC100C16MP13 | 25,400 | $1,270 |
| No | 211390225 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | CPLC080C16MP13 | 25,400 | $1,270 |
| No | 211390210 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TPLC100C16MP13 | 25,400 | $1,270 |
| No | 211390196 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TPLC080C16MP13 | 25,400 | $1,270 |
| No | 211390183 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TMLV100C16MP12 | 25,400 | $1,270 |
| No | 211390169 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TM8V080C16MP12 | 25,400 | $1,270 |
| No | 211390155 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TM8V100C16MP12 | 25,400 | $1,270 |
| No | 211390150 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | CPLC100C16MP13 | 25,600 | $1,280 |
| No | 211390145 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | CPLC080C16MP13 | 25,600 | $1,280 |
| No | 211390131 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TPLC100C16MP13 | 25,600 | $1,280 |
| No | 211390117 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TPLC080C16MP13 | 25,600 | $1,280 |
| No | 211390103 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TMLV100C16MP12 | 25,600 | $1,280 |
| No | 211390073 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TM8V100C16MP12 | 25,600 | $1,280 |
| No | 211390067 | COLEMAN | HMH72B341 | XAHC36DBCN1 | CPLC100C16MP13 | 25,600 | $1,280 |
| No | 211390061 | COLEMAN | HMH72B341 | XAHC36DBCN1 | CPLC080C16MP13 | 25,600 | $1,280 |
| No | 211390048 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TPLC100C16MP13 | 25,600 | $1,280 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211390034 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TPLC080C16MP13 | 25,600 | $1,280 |
| No | 211390019 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TMLV100C16MP12 | 25,600 | $1,280 |
| No | 211389992 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TM8V100C16MP12 | 25,600 | $1,280 |
| No | 211389987 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | CPLC100C16MP13 | 25,600 | $1,280 |
| No | 211389981 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | CPLC080C16MP13 | 25,600 | $1,280 |
| No | 211389967 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TPLC100C16MP13 | 25,600 | $1,280 |
| No | 211389953 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TPLC080C16MP13 | 25,600 | $1,280 |
| No | 211389938 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TMLV100C16MP12 | 25,600 | $1,280 |
| No | 211389908 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TM8V100C16MP12 | 25,600 | $1,280 |
| No | 211389893 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | TM8Y060A12MP11 | 25,800 | $1,290 |
| No | 211389886 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | TM8Y060A12MP11 | 25,800 | $1,290 |
| No | 211389873 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | TM8Y060A12MP11 | 25,200 | $1,260 |
| No | 211389859 | COLEMAN | HMH72B341 | XAFB36DBCN1 | TM8Y060A12MP11 | 25,200 | $1,260 |
| No | 211389845 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | TM8Y060A12MP11 | 25,200 | $1,260 |
| No | 211389830 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | TM8Y060A12MP11 | 25,400 | $1,270 |
| No | 211389816 | COLEMAN | HMH72B341 | XAHB36DBCN1 | TM8Y060A12MP11 | 24,600 | $1,230 |
| No | 211389801 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | TM8Y060A12MP11 | 24,600 | $1,230 |
| No | 211389786 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | TM8Y080B12MP11 | 26,000 | $1,300 |
| No | 211389771 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | TM8Y080B12MP11 | 26,000 | $1,300 |
| No | 211389756 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211389741 | COLEMAN | HMH72B341 | XAFB36DBCN1 | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211389727 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211389719 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TM8Y080B12MP11 | 26,000 | $1,300 |
| No | 211389705 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211389690 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211389675 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211389660 | COLEMAN | HMH72B341 | XAHB36DBCN1 | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211389645 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211389631 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211389616 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211389601 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211389571 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TM8Y100C16MP11 | 26,400 | $1,320 |
| No | 211389553 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211389523 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211389509 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TM8Y080C16MP11 | 26,600 | $1,330 |
| No | 211389494 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TM8Y100C16MP11 | 26,600 | $1,330 |
| No | 211389479 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TM8Y080C16MP11 | 25,600 | $1,280 |
| No | 211389464 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TM8Y100C16MP11 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211389449 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TM8Y080C16MP11 | 25,600 | $1,280 |
| No | 211389438 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TM8Y100C16MP11 | 25,600 | $1,280 |
| No | 211389414 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TM8Y120C20MP11 | 27,000 | $1,350 |
| No | 211389385 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211389360 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211389345 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TM8Y100C20MP11 | 26,400 | $1,320 |
| No | 211389330 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TM8Y120C20MP11 | 26,400 | $1,320 |
| No | 211389315 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TM8Y100C20MP11 | 25,400 | $1,270 |
| No | 211389301 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TM8Y120C20MP11 | 25,400 | $1,270 |
| No | 211389286 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TM8Y100C20MP11 | 25,400 | $1,270 |
| No | 211389271 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TM8Y120C20MP11 | 25,400 | $1,270 |
| No | 211389257 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | TM9E040A10MP12 | 25,800 | $1,290 |
| No | 211389245 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | TM9E040A10MP12 | 25,800 | $1,290 |
| No | 211389235 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | TM9E060A10MP12 | 26,200 | $1,310 |
| No | 211389220 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | TM9E060A10MP12 | 26,200 | $1,310 |
| No | 211389205 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | TM9E060A10MP12 | 25,400 | $1,270 |
| No | 211389190 | COLEMAN | HMH72B341 | XAFB36DBCN1 | TM9E060A10MP12 | 25,400 | $1,270 |
| No | 211389176 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | TM9E060A10MP12 | 25,400 | $1,270 |
| No | 211389171 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | TM9E060A10MP12 | 25,800 | $1,290 |
| No | 211389157 | COLEMAN | HMH72B341 | XAHB36DBCN1 | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 211389142 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 211389127 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | TM9E060B12MP12 | 26,400 | $1,320 |
| No | 211389112 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | TM9E060B12MP12 | 26,400 | $1,320 |
| No | 211389097 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211389082 | COLEMAN | HMH72B341 | XAFB36DBCN1 | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211389068 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211389053 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TM9E060B12MP12 | 26,400 | $1,320 |
| No | 211389038 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211389023 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211389008 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | TM9E060B12MP12 | 26,000 | $1,300 |
| No | 211388994 | COLEMAN | HMH72B341 | XAHB36DBCN1 | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211388979 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211388964 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TM9E060B12MP12 | 26,200 | $1,310 |
| No | 211388953 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211388938 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211388923 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | TM9E080B12MP12 | 26,800 | $1,340 |
| No | 211388908 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | TM9E080B12MP12 | 26,800 | $1,340 |
| No | 211388893 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | TM9E080B12MP12 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211388886 | COLEMAN | HMH72B341 | XAFB36DBCN1 | TM9E080B12MP12 | 25,400 | $1,270 |
| No | 211388871 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | TM9E080B12MP12 | 25,400 | $1,270 |
| No | 211388856 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TM9E080B12MP12 | 26,400 | $1,320 |
| No | 211388841 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TM9E080B12MP12 | 25,800 | $1,290 |
| No | 211388826 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TM9E080B12MP12 | 25,800 | $1,290 |
| No | 211388811 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | TM9E080B12MP12 | 25,800 | $1,290 |
| No | 211388798 | COLEMAN | HMH72B341 | XAHB36DBCN1 | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211388788 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211388774 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TM9E080B12MP12 | 26,200 | $1,310 |
| No | 211388759 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211388744 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211388729 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TM9E080C16MP12 | 26,200 | $1,310 |
| No | 211388714 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TM9E080C16MP12 | 25,200 | $1,260 |
| No | 211388700 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TM9E080C16MP12 | 25,200 | $1,260 |
| No | 211388685 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TM9E080C16MP12 | 26,800 | $1,340 |
| No | 211388670 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211388655 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211388640 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TM9E100C16MP12 | 26,200 | $1,310 |
| No | 211388625 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TM9E100C16MP12 | 25,200 | $1,260 |
| No | 211388611 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TM9E100C16MP12 | 25,200 | $1,260 |
| No | 211388596 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TM9E100C16MP12 | 25,600 | $1,280 |
| No | 211388581 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211388566 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211388556 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TM9E100C20MP12 | 25,000 | $1,250 |
| No | 211388548 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TM9E100C20MP12 | 25,000 | $1,250 |
| No | 211388543 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | TM9V040A10MP12 | 25,800 | $1,290 |
| No | 211388528 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | TM9V040A10MP12 | 25,800 | $1,290 |
| No | 211388514 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | TM9V040A10MP12 | 25,200 | $1,260 |
| No | 211388509 | COLEMAN | HMH72B341 | XAFB36DBCN1 | TM9V040A10MP12 | 25,200 | $1,260 |
| No | 211388495 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | TM9V040A10MP12 | 25,200 | $1,260 |
| No | 211388481 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | TM9V040A10MP12 | 25,200 | $1,260 |
| No | 211388468 | COLEMAN | HMH72B341 | XAHB36DBCN1 | TM9V040A10MP12 | 24,800 | $1,240 |
| No | 211388457 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | TM9V040A10MP12 | 24,800 | $1,240 |
| No | 211388451 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | CP9C060B12MP13 | 26,400 | $1,320 |
| No | 211388444 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | TP9C060B12MP13 | 26,400 | $1,320 |
| No | 211388429 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | TM9V060B12MP12 | 26,400 | $1,320 |
| No | 211388423 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | CP9C060B12MP13 | 26,400 | $1,320 |
| No | 211388409 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | TP9C060B12MP13 | 26,400 | $1,320 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211388394 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | TM9V060B12MP12 | 26,400 | $1,320 |
| No | 211388390 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | CP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388384 | COLEMAN | HMH72B341 | XAFB36DBCN1 | CP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388375 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388360 | COLEMAN | HMH72B341 | XAFB36DBCN1 | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388344 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388335 | COLEMAN | HMH72B341 | XAFB36DBCN1 | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388328 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | CP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388315 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388300 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388295 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | CP9C060B12MP13 | 26,400 | $1,320 |
| No | 211388280 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TP9C060B12MP13 | 26,400 | $1,320 |
| No | 211388266 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TM9V060B12MP12 | 26,400 | $1,320 |
| No | 211388261 | COLEMAN | HMH72B341 | XAFC36DBCN1 | CP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388247 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388233 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388229 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | CP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388224 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388215 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388209 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | CP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388195 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388185 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388180 | COLEMAN | HMH72B341 | XAHB36DBCN1 | CP9C060B12MP13 | 25,000 | $1,250 |
| No | 211388166 | COLEMAN | HMH72B341 | XAHB36DBCN1 | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 211388151 | COLEMAN | HMH72B341 | XAHB36DBCN1 | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 211388146 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | CP9C060B12MP13 | 25,000 | $1,250 |
| No | 211388132 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 211388117 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 211388111 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | CP9C060B12MP13 | 26,000 | $1,300 |
| No | 211388098 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TP9C060B12MP13 | 26,000 | $1,300 |
| No | 211388085 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TM9V060B12MP12 | 26,000 | $1,300 |
| No | 211388080 | COLEMAN | HMH72B341 | XAHC36DBCN1 | CP9C060B12MP13 | 25,200 | $1,260 |
| No | 211388066 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TP9C060B12MP13 | 25,200 | $1,260 |
| No | 211388052 | COLEMAN | HMH72B341 | 0 | TM9V060B12MP12 | 25,200 | $1,260 |
| No | 211388047 | COLEMAN | HMH72B341 | 0 | CP9C060B12MP13 | 25,200 | $1,260 |
| No | 211388032 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TP9C060B12MP13 | 25,200 | $1,260 |
| No | 211388027 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TM9V060B12MP12 | 25,200 | $1,260 |
| No | 211388022 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | CP9C080B12MP13 | 26,600 | $1,330 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211388012 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | TP9C080B12MP13 | 26,600 | $1,330 |
| No | 211387997 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | TM9V080B12MP12 | 26,600 | $1,330 |
| No | 211387993 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | CP9C080B12MP13 | 26,600 | $1,330 |
| No | 211387979 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | TP9C080B12MP13 | 26,600 | $1,330 |
| No | 211387965 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | TM9V080B12MP12 | 26,600 | $1,330 |
| No | 211387963 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | CP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387961 | COLEMAN | HMH72B341 | XAFB36DBCN1 | CP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387947 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | TP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387932 | COLEMAN | HMH72B341 | XAFB36DBCN1 | TP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387921 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211387906 | COLEMAN | HMH72B341 | XAFB36DBCN1 | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211387901 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | CP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387886 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | TP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387871 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211387865 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | CP9C080B12MP13 | 26,600 | $1,330 |
| No | 211387852 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TP9C080B12MP13 | 26,600 | $1,330 |
| No | 211387839 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TM9V080B12MP12 | 26,600 | $1,330 |
| No | 211387837 | COLEMAN | HMH72B341 | XAFC36DBCN1 | CP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387831 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387821 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211387817 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | CP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387809 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387800 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211387796 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | CP9C080B12MP13 | 26,200 | $1,310 |
| No | 211387788 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | TP9C080B12MP13 | 26,200 | $1,310 |
| No | 211387780 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | TM9V080B12MP12 | 26,200 | $1,310 |
| No | 211387777 | COLEMAN | HMH72B341 | XAHB36DBCN1 | CP9C080B12MP13 | 25,200 | $1,260 |
| No | 211387768 | COLEMAN | HMH72B341 | XAHB36DBCN1 | TP9C080B12MP13 | 25,200 | $1,260 |
| No | 211387760 | COLEMAN | HMH72B341 | XAHB36DBCN1 | TM9V080B12MP12 | 25,200 | $1,260 |
| No | 211387756 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | CP9C080B12MP13 | 25,200 | $1,260 |
| No | 211387748 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | TP9C080B12MP13 | 25,200 | $1,260 |
| No | 211387740 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | TM9V080B12MP12 | 25,200 | $1,260 |
| No | 211387736 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | CP9C080B12MP13 | 26,200 | $1,310 |
| No | 211387728 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TP9C080B12MP13 | 26,200 | $1,310 |
| No | 211387720 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TM9V080B12MP12 | 26,200 | $1,310 |
| No | 211387716 | COLEMAN | HMH72B341 | XAHC36DBCN1 | CP9C080B12MP13 | 25,000 | $1,250 |
| No | 211387708 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 211387700 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TM9V080B12MP12 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211387696 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | CP9C080B12MP13 | 25,000 | $1,250 |
| No | 211387688 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 211387680 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 211387676 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | CP9C080C16MP13 | 26,200 | $1,310 |
| No | 211387668 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TP9C080C16MP13 | 26,200 | $1,310 |
| No | 211387659 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TM9V080C16MP12 | 26,200 | $1,310 |
| No | 211387656 | COLEMAN | HMH72B341 | XAFC36DBCN1 | CP9C080C16MP13 | 25,400 | $1,270 |
| No | 211387648 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211387642 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211387639 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | CP9C080C16MP13 | 25,400 | $1,270 |
| No | 211387631 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211387622 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211387618 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | CP9C080C16MP13 | 25,800 | $1,290 |
| No | 211387610 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TP9C080C16MP13 | 25,800 | $1,290 |
| No | 211387603 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TM9V080C16MP12 | 25,800 | $1,290 |
| No | 211387600 | COLEMAN | HMH72B341 | XAHC36DBCN1 | CP9C080C16MP13 | 25,000 | $1,250 |
| No | 211387591 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TP9C080C16MP13 | 25,000 | $1,250 |
| No | 211387583 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TM9V080C16MP12 | 25,000 | $1,250 |
| No | 211387579 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | CP9C080C16MP13 | 25,000 | $1,250 |
| No | 211387570 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TP9C080C16MP13 | 25,000 | $1,250 |
| No | 211387562 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TM9V080C16MP12 | 25,000 | $1,250 |
| No | 211387559 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | CP9C100C16MP13 | 26,400 | $1,320 |
| No | 211387551 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TP9C100C16MP13 | 26,400 | $1,320 |
| No | 211387545 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TM9V100C16MP12 | 26,400 | $1,320 |
| No | 211387543 | COLEMAN | HMH72B341 | XAFC36DBCN1 | CP9C100C16MP13 | 25,400 | $1,270 |
| No | 211387536 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211387528 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211387522 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | CP9C100C16MP13 | 25,400 | $1,270 |
| No | 211387509 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211387496 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211387490 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | CP9C100C16MP13 | 25,800 | $1,290 |
| No | 211387478 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TP9C100C16MP13 | 25,800 | $1,290 |
| No | 211387465 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TM9V100C16MP12 | 25,800 | $1,290 |
| No | 211387459 | COLEMAN | HMH72B341 | XAHC36DBCN1 | CP9C100C16MP13 | 25,000 | $1,250 |
| No | 211387446 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TP9C100C16MP13 | 25,000 | $1,250 |
| No | 211387434 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TM9V100C16MP12 | 25,000 | $1,250 |
| No | 211387429 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | CP9C100C16MP13 | 25,000 | $1,250 |
| No | 211387413 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TP9C100C16MP13 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211387401 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TM9V100C16MP12 | 25,000 | $1,250 |
| No | 211387396 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | CP9C100C20MP13 | 27,000 | $1,350 |
| No | 211387380 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TP9C100C20MP13 | 27,000 | $1,350 |
| No | 211387367 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TM9V100C20MP12 | 27,000 | $1,350 |
| No | 211387361 | COLEMAN | HMH72B341 | XAFC36DBCN1 | CP9C100C20MP13 | 26,000 | $1,300 |
| No | 211387346 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TP9C100C20MP13 | 26,000 | $1,300 |
| No | 211387330 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TM9V100C20MP12 | 26,000 | $1,300 |
| No | 211387323 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | CP9C100C20MP13 | 26,000 | $1,300 |
| No | 211387310 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TP9C100C20MP13 | 26,000 | $1,300 |
| No | 211387296 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TM9V100C20MP12 | 26,000 | $1,300 |
| No | 211387290 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | CP9C100C20MP13 | 26,600 | $1,330 |
| No | 211387276 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TP9C100C20MP13 | 26,600 | $1,330 |
| No | 211387263 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TM9V100C20MP12 | 26,600 | $1,330 |
| No | 211387248 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | TM9Y060B12MP11 | 26,600 | $1,330 |
| No | 211387234 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | TM9Y060B12MP11 | 26,600 | $1,330 |
| No | 211387219 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211387205 | COLEMAN | HMH72B341 | XAFB36DBCN1 | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211387191 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211387178 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TM9Y060B12MP11 | 26,600 | $1,330 |
| No | 211387165 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211386471 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TL8E080C16UH11 | 25,400 | $1,270 |
| No | 211386458 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211386444 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211386429 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211386416 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211386405 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211386392 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TL8E100C20UH11 | 24,800 | $1,240 |
| No | 211386380 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TL8E100C20UH11 | 24,800 | $1,240 |
| No | 211386368 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TL8E100C20UH11 | 24,800 | $1,240 |
| No | 211386356 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TL8E100C20UH11 | 24,800 | $1,240 |
| No | 211386344 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TL9E060B12UH11 | 25,800 | $1,290 |
| No | 211386332 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TL9E060B12UH11 | 25,800 | $1,290 |
| No | 211386321 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TL9E060B12UH11 | 25,800 | $1,290 |
| No | 211386308 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TL9E060B12UH11 | 25,200 | $1,260 |
| No | 211386293 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TL9E060B12UH11 | 25,200 | $1,260 |
| No | 211386280 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TL9E080C16UH11 | 25,800 | $1,290 |
| No | 211386265 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TL9E080C16UH11 | 25,800 | $1,290 |
| No | 211386252 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TL9E080C16UH11 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211386240 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TL9E080C16UH11 | 25,600 | $1,280 |
| No | 211386227 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TL9E080C16UH11 | 25,600 | $1,280 |
| No | 211386214 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TL9E080C16UH11 | 25,200 | $1,260 |
| No | 211386204 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TL9E080C16UH11 | 25,200 | $1,260 |
| No | 211386196 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TL9E080C16UH11 | 25,200 | $1,260 |
| No | 211386179 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TL9E080C16UH11 | 25,200 | $1,260 |
| No | 211386165 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211386151 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211386134 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211386119 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211386105 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211386091 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TL9E100C20UH11 | 25,000 | $1,250 |
| No | 211386077 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TL9E100C20UH11 | 25,000 | $1,250 |
| No | 211386063 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TL9E100C20UH11 | 25,000 | $1,250 |
| No | 211386048 | COLEMAN | HMH72B341 | XAHD48FXXN1+TXV | TL9E100C20UH11 | 25,000 | $1,250 |
| No | 211386034 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TMLE080B12MP11 | 25,600 | $1,280 |
| No | 211386020 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TMLE080B12MP11 | 25,600 | $1,280 |
| No | 211386005 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TM8E080B12MP11 | 25,600 | $1,280 |
| No | 211385990 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TM8E080B12MP11 | 25,600 | $1,280 |
| No | 211385978 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TMLE080B12MP11 | 25,600 | $1,280 |
| No | 211385965 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TM8E080B12MP11 | 25,600 | $1,280 |
| No | 211385951 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TMLE080B12MP11 | 25,400 | $1,270 |
| No | 211385938 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TM8E080B12MP11 | 25,400 | $1,270 |
| No | 211385924 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TMLE080B12MP11 | 25,400 | $1,270 |
| No | 211385912 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TM8E080B12MP11 | 25,400 | $1,270 |
| No | 211385897 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211385881 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211385865 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211385851 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211385837 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211385828 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211387148 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211387135 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | TM9Y060B12MP11 | 26,000 | $1,300 |
| No | 211387121 | COLEMAN | HMH72B341 | XAHB36DBCN1 | TM9Y060B12MP11 | 25,000 | $1,250 |
| No | 211387108 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | TM9Y060B12MP11 | 25,000 | $1,250 |
| No | 211387095 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TM9Y060B12MP11 | 26,000 | $1,300 |
| No | 211387083 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TM9Y060B12MP11 | 25,200 | $1,260 |
| No | 211387070 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TM9Y060B12MP11 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211387057 | COLEMAN | HMH72B341 | XAUB30CXXN1+TXV | TM9Y080B12MP11 | 26,800 | $1,340 |
| No | 211387044 | COLEMAN | HMH72B341 | XAFB30CXXN1+TXV | TM9Y080B12MP11 | 26,800 | $1,340 |
| No | 211387029 | COLEMAN | HMH72B341 | XAUB36DXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211387015 | COLEMAN | HMH72B341 | XAFB36DBCN1 | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211387001 | COLEMAN | HMH72B341 | XAFB36DXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211386987 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TM9Y080B12MP11 | 26,800 | $1,340 |
| No | 211386972 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211386957 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211386944 | COLEMAN | HMH72B341 | XAHB30CXXN1+TXV | TM9Y080B12MP11 | 26,200 | $1,310 |
| No | 211386932 | COLEMAN | HMH72B341 | XAHB36DBCN1 | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211386916 | COLEMAN | HMH72B341 | XAHB36DXXN1+TXV | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211386902 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TM9Y080B12MP11 | 26,200 | $1,310 |
| No | 211386887 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TM9Y080B12MP11 | 25,400 | $1,270 |
| No | 211386874 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TM9Y080B12MP11 | 25,400 | $1,270 |
| No | 211386861 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TM9Y080C16MP11 | 26,800 | $1,340 |
| No | 211386849 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TM9Y080C16MP11 | 25,800 | $1,290 |
| No | 211386833 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TM9Y080C16MP11 | 25,800 | $1,290 |
| No | 211386819 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TM9Y080C16MP11 | 26,200 | $1,310 |
| No | 211386805 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TM9Y080C16MP11 | 25,400 | $1,270 |
| No | 211386789 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TM9Y080C16MP11 | 25,400 | $1,270 |
| No | 211386774 | COLEMAN | HMH72B341 | XAFC30CXXN1+TXV | TM9Y100C16MP11 | 26,000 | $1,300 |
| No | 211386759 | COLEMAN | HMH72B341 | XAFC36DBCN1 | TM9Y100C16MP11 | 25,800 | $1,290 |
| No | 211386746 | COLEMAN | HMH72B341 | XAFC36DXXN1+TXV | TM9Y100C16MP11 | 25,800 | $1,290 |
| No | 211386733 | COLEMAN | HMH72B341 | XAHC30CXXN1+TXV | TM9Y100C16MP11 | 25,600 | $1,280 |
| No | 211386721 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TM9Y100C16MP11 | 25,400 | $1,270 |
| No | 211386708 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TM9Y100C16MP11 | 25,400 | $1,270 |
| No | 211386694 | COLEMAN | HMH72B341 | XAHC36DBCN1 | TM9Y100C20MP11 | 25,600 | $1,280 |
| No | 211386680 | COLEMAN | HMH72B341 | XAHC36DXXN1+TXV | TM9Y100C20MP11 | 25,600 | $1,280 |
| No | 211386666 | COLEMAN | HMH72B341 | JHETC42FBCS2N1 | | 25,200 | $1,260 |
| No | 211386653 | COLEMAN | HMH72B341 | JHVTC42FBCC2N1 | | 25,000 | $1,250 |
| No | 211386641 | COLEMAN | HMH72B341 | XAUC48FXXN1+JMET12CS2N1+TXV | | 25,400 | $1,270 |
| No | 211386627 | COLEMAN | HMH72B341 | XAFC48FBCN1+JMET12CS2N1 | | 25,400 | $1,270 |
| No | 211386615 | COLEMAN | HMH72B341 | XAFC48FXXN1+JMET12CS2N1+TXV | | 25,400 | $1,270 |
| No | 211386601 | COLEMAN | HMH72B341 | XAHC48FBCN1+JMET12CS2N1 | | 24,800 | $1,240 |
| No | 211386587 | COLEMAN | HMH72B341 | XAHC48FXXN1+JMET12CS2N1+TXV | | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211386577 | COLEMAN | HMH72B341 | XAUC48FXXN1+TXV | TL8E080C16UH11 | 26,000 | $1,300 |
| No | 211386565 | COLEMAN | HMH72B341 | XAFC48FBCN1 | TL8E080C16UH11 | 26,000 | $1,300 |
| No | 211386552 | COLEMAN | HMH72B341 | XAFC48FXXN1+TXV | TL8E080C16UH11 | 26,000 | $1,300 |
| No | 211386540 | COLEMAN | HMH72B341 | XAFD48FBCN1 | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211386528 | COLEMAN | HMH72B341 | XAFD48FXXN1+TXV | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211386513 | COLEMAN | HMH72B341 | XAHC48FBCN1 | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211386498 | COLEMAN | HMH72B341 | XAHC48FXXN1+TXV | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211386484 | COLEMAN | HMH72B341 | XAHD48FBCN1 | TL8E080C16UH11 | 25,400 | $1,270 |
| No | 208502144 | COLEMAN | HMH72B241 | XAHB36DXXN1+JMET08BS2N1+TXV | | 13,900 | $695 |
| No | 208503254 | COLEMAN | HMH72B241 | XAUB36DXXN1+JMET08BS2N1+TXV | | 14,200 | $710 |
| No | 208614008 | COLEMAN | HMH72B241 | XAFB36DBAN1+JMET08BS2N1 | | 14,200 | $710 |
| No | 208503242 | COLEMAN | HMH72B241 | XAFB36DXXN1+JMET08BS2N1+TXV | | 14,200 | $710 |
| No | 208502622 | COLEMAN | HMH72B241 | XAUB36DXXN1+JMET12BS2N1+TXV | | 14,200 | $710 |
| No | 208614013 | COLEMAN | HMH72B241 | XAFB36DBAN1+JMET12BS2N1 | | 14,200 | $710 |
| No | 208502615 | COLEMAN | HMH72B241 | XAFB36DXXN1+JMET12BS2N1+TXV | | 14,200 | $710 |
| No | 207434641 | COLEMAN | HMH72B241 | XAFC36DXXN1+MVC12CN21+TXV | | 14,300 | $715 |
| No | 207417441 | COLEMAN | HMH72B241 | XAFC36DXXN1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 208213786 | COLEMAN | HMH72B241 | XAHC36DXXN1+TXV | CP9C060B12MP13 | 14,300 | $715 |
| No | 208213792 | COLEMAN | HMH72B241 | XAHC36DXXN1+TXV | TP9C060B12MP13 | 14,300 | $715 |
| No | 208213800 | COLEMAN | HMH72B241 | XAHC36DXXN1+TXV | TM9V060B12MP12 | 14,300 | $715 |
| No | 208501673 | COLEMAN | HMH72B241 | XAHB36DXXN1+JMVT12BC2N1+TXV | | 13,900 | $695 |
| No | 207434645 | COLEMAN | HMH72B241 | XAUB36DXXN1+ME08BN21+TXV | | 14,100 | $705 |
| No | 207434646 | COLEMAN | HMH72B241 | XAFB36DXXN1+ME08BN21+TXV | | 14,100 | $705 |
| No | 207417474 | COLEMAN | HMH72B241 | XAUB36DXXN1+TXV | TL8E060A12UH11 | 14,400 | $720 |
| No | 207417470 | COLEMAN | HMH72B241 | XAFB36DXXN1+TXV | TL8E060A12UH11 | 14,400 | $720 |
| No | 207416654 | COLEMAN | HMH72B241 | XAFA30DXXN1+TXV | TM9E060A10MP12 | 14,600 | $730 |
| No | 208213784 | COLEMAN | HMH72B241 | XAHB36DXXN1+TXV | CP9C080B12MP13 | 14,200 | $710 |
| No | 208213794 | COLEMAN | HMH72B241 | XAHB36DXXN1+TXV | TP9C080B12MP13 | 14,200 | $710 |
| No | 208213801 | COLEMAN | HMH72B241 | XAHB36DXXN1+TXV | TM9V080B12MP12 | 14,200 | $710 |
| No | 207434644 | COLEMAN | HMH72B241 | XAUB36DXXN1+MVC12BN21+TXV | | 14,300 | $715 |
| No | 207434642 | COLEMAN | HMH72B241 | XAFB36DXXN1+MVC12BN21+TXV | | 14,300 | $715 |
| No | 207417189 | COLEMAN | HMH72B241 | XAFA30DXXN1+TXV | TMLE040A12MP11 | 14,400 | $720 |
| No | 207417185 | COLEMAN | HMH72B241 | XAFA30DXXN1+TXV | TM8E040A12MP11 | 14,400 | $720 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417457 | COLEMAN | HMH72B241 | XAUB36DXXN1+TXV | TM8Y060A12MP11 | 14,200 | $710 |
| No | 207417453 | COLEMAN | HMH72B241 | XAFB36DXXN1+TXV | TM8Y060A12MP11 | 14,200 | $710 |
| No | 207417439 | COLEMAN | HMH72B241 | XAUB36DXXN1+TXV | CP9C060B12MP13 | 14,600 | $730 |
| No | 207417435 | COLEMAN | HMH72B241 | XAUB36DXXN1+TXV | TP9C060B12MP13 | 14,600 | $730 |
| No | 207417431 | COLEMAN | HMH72B241 | XAUB36DXXN1+TXV | TM9V060B12MP12 | 14,600 | $730 |
| No | 207417429 | COLEMAN | HMH72B241 | XAFB36DXXN1+TXV | CP9C060B12MP13 | 14,600 | $730 |
| No | 207417425 | COLEMAN | HMH72B241 | XAFB36DXXN1+TXV | TP9C060B12MP13 | 14,600 | $730 |
| No | 207417421 | COLEMAN | HMH72B241 | XAFB36DXXN1+TXV | TM9V060B12MP12 | 14,600 | $730 |
| No | 207416618 | COLEMAN | HMH72B241 | XAFC36DXXN1+TXV | TM9Y060B12MP11 | 14,500 | $725 |
| No | 208614014 | COLEMAN | HMH72B241 | JHETB30DBAS2N1 | | 14,600 | $730 |
| No | 208501694 | COLEMAN | HMH72B241 | JHETB30DXXS2N1+TXV | | 14,600 | $730 |
| No | 208502138 | COLEMAN | HMH72B241 | XAHB36DXXN1+JMET12BS2N1+TXV | | 13,900 | $695 |
| No | 208400358 | COLEMAN | HMH72B241 | XAHB36DXXN1+ME08BN21+TXV | | 14,200 | $710 |
| No | 207417197 | COLEMAN | HMH72B241 | XAUB36DXXN1+TXV | TL9E060B12UH11 | 14,500 | $725 |
| No | 207417193 | COLEMAN | HMH72B241 | XAFB36DXXN1+TXV | TL9E060B12UH11 | 14,500 | $725 |
| No | 208213790 | COLEMAN | HMH72B241 | XAHC36DXXN1+TXV | TPLC080B12MP13 | 14,100 | $705 |
| No | 208213796 | COLEMAN | HMH72B241 | XAHC36DXXN1+TXV | TM8V080B12MP12 | 14,100 | $705 |
| No | 207417161 | COLEMAN | HMH72B241 | XAUB36DXXN1+TXV | TM9E060A10MP12 | 14,600 | $730 |
| No | 207417157 | COLEMAN | HMH72B241 | XAFB36DXXN1+TXV | TM9E060A10MP12 | 14,600 | $730 |
| No | 208213785 | COLEMAN | HMH72B241 | XAHC36DXXN1+TXV | CP9C080B12MP13 | 14,100 | $705 |
| No | 208213795 | COLEMAN | HMH72B241 | XAHC36DXXN1+TXV | TP9C080B12MP13 | 14,100 | $705 |
| No | 208213802 | COLEMAN | HMH72B241 | XAHC36DXXN1+TXV | TM9V080B12MP12 | 14,100 | $705 |
| No | 208614012 | COLEMAN | HMH72B241 | JHETB36DBAS2N1 | | 14,300 | $715 |
| No | 208502151 | COLEMAN | HMH72B241 | JHETB36DXXS2N1+TXV | | 14,300 | $715 |
| No | 208501687 | COLEMAN | HMH72B241 | XAUB36DXXN1+JMVT12BC2N1+TXV | | 14,000 | $700 |
| No | 208614015 | COLEMAN | HMH72B241 | XAFB36DBAN1+JMVT12BC2N1 | | 14,000 | $700 |
| No | 208501680 | COLEMAN | HMH72B241 | XAFB36DXXN1+JMVT12BC2N1+TXV | | 14,000 | $700 |
| No | 207416856 | COLEMAN | HMH72B241 | XAFC36DXXN1+TXV | TMLE100B12MP11 | 14,300 | $715 |
| No | 207416852 | COLEMAN | HMH72B241 | XAFC36DXXN1+TXV | TM8E100B12MP11 | 14,300 | $715 |
| No | 208614011 | COLEMAN | HMH72B241 | JHETC36DBAS2N1 | | 14,200 | $710 |
| No | 208504355 | COLEMAN | HMH72B241 | JHETC36DXXS2N1+TXV | | 14,200 | $710 |
| No | 208400360 | COLEMAN | HMH72B241 | XAHC36DXXN1+MVC12CN21+TXV | | 14,000 | $700 |
| No | 208213811 | COLEMAN | HMH72B241 | XAHC36DXXN1+TXV | TMLE100B12MP11 | 14,000 | $700 |
| No | 208213809 | COLEMAN | HMH72B241 | XAHC36DXXN1+TXV | TM8E100B12MP11 | 14,000 | $700 |
| No | 208213788 | COLEMAN | HMH72B241 | XAHC36DXXN1+TXV | TM8Y080B12MP11 | 14,000 | $700 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417409 | COLEMAN | HMH72B241 | XAUB36DXXN1+TXV | CP9C080B12MP13 | 14,400 | $720 |
| No | 207417405 | COLEMAN | HMH72B241 | XAUB36DXXN1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 207417401 | COLEMAN | HMH72B241 | XAUB36DXXN1+TXV | TM9V080B12MP12 | 14,400 | $720 |
| No | 207417399 | COLEMAN | HMH72B241 | XAFB36DXXN1+TXV | CP9C080B12MP13 | 14,400 | $720 |
| No | 207417395 | COLEMAN | HMH72B241 | XAFB36DXXN1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 207417391 | COLEMAN | HMH72B241 | XAFB36DXXN1+TXV | TM9V080B12MP12 | 14,400 | $720 |
| No | 207434643 | COLEMAN | HMH72B241 | XAFC36DXXN1+ME12CN21+TXV | | 14,200 | $710 |
| No | 207416666 | COLEMAN | HMH72B241 | XAFC36DXXN1+TXV | TL9E060B12UH11 | 14,500 | $725 |
| No | 207417181 | COLEMAN | HMH72B241 | XAFA30DXXN1+TXV | TM8Y060A12MP11 | 14,700 | $735 |
| No | 207416646 | COLEMAN | HMH72B241 | XAUB36DXXN1+TXV | TM9V040A10MP12 | 14,800 | $740 |
| No | 207416642 | COLEMAN | HMH72B241 | XAFB36DXXN1+TXV | TM9V040A10MP12 | 14,800 | $740 |
| No | 207416626 | COLEMAN | HMH72B241 | XAUB36DXXN1+TXV | TM9Y060B12MP11 | 14,500 | $725 |
| No | 207416622 | COLEMAN | HMH72B241 | XAFB36DXXN1+TXV | TM9Y060B12MP11 | 14,500 | $725 |
| No | 207416670 | COLEMAN | HMH72B241 | XAFA30DXXN1+TXV | TL8E060A12UH11 | 14,400 | $720 |
| No | 207416847 | COLEMAN | HMH72B241 | XAUB36DXXN1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 207416843 | COLEMAN | HMH72B241 | XAUB36DXXN1+TXV | TM8V080B12MP12 | 14,400 | $720 |
| No | 207416838 | COLEMAN | HMH72B241 | XAFB36DXXN1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 207416834 | COLEMAN | HMH72B241 | XAFB36DXXN1+TXV | TM8V080B12MP12 | 14,400 | $720 |
| No | 207417173 | COLEMAN | HMH72B241 | XAUB36DXXN1+TXV | TM9E026A08MP12 | 14,800 | $740 |
| No | 207417169 | COLEMAN | HMH72B241 | XAFB36DXXN1+TXV | TM9E026A08MP12 | 14,800 | $740 |
| No | 207416832 | COLEMAN | HMH72B241 | XAFC36DXXN1+TXV | CP9C080B12MP13 | 14,400 | $720 |
| No | 207416828 | COLEMAN | HMH72B241 | XAFC36DXXN1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 207416824 | COLEMAN | HMH72B241 | XAFC36DXXN1+TXV | TM9V080B12MP12 | 14,400 | $720 |
| No | 208614010 | COLEMAN | HMH72B241 | JHVTB36DBAC2N1 | | 14,000 | $700 |
| No | 208504346 | COLEMAN | HMH72B241 | JHVTB36DXXC2N1+TXV | | 14,000 | $700 |
| No | 208614009 | COLEMAN | HMH72B241 | JHVTC36DBAC2N1 | | 14,100 | $705 |
| No | 208503271 | COLEMAN | HMH72B241 | JHVTC36DXXC2N1+TXV | | 14,100 | $705 |
| No | 207417465 | COLEMAN | HMH72B241 | XAFC36DXXN1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 207417461 | COLEMAN | HMH72B241 | XAFC36DXXN1+TXV | TM8V080B12MP12 | 14,400 | $720 |
| No | 208400359 | COLEMAN | HMH72B241 | XAHB36DXXN1+MVC12BN21+TXV | | 14,100 | $705 |
| No | 207416872 | COLEMAN | HMH72B241 | XAUB36DXXN1+TXV | TMLE040A12MP11 | 14,500 | $725 |
| No | 207416868 | COLEMAN | HMH72B241 | XAUB36DXXN1+TXV | TM8E040A12MP11 | 14,500 | $725 |
| No | 207416864 | COLEMAN | HMH72B241 | XAFB36DXXN1+TXV | TMLE040A12MP11 | 14,500 | $725 |
| No | 207416860 | COLEMAN | HMH72B241 | XAFB36DXXN1+TXV | TM8E040A12MP11 | 14,500 | $725 |
| No | 207417449 | COLEMAN | HMH72B241 | XAUB36DXXN1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207417445 | COLEMAN | HMH72B241 | XAFB36DXXN1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207417419 | COLEMAN | HMH72B241 | XAFC36DXXN1+TXV | CP9C060B12MP13 | 14,600 | $730 |
| No | 207417415 | COLEMAN | HMH72B241 | XAFC36DXXN1+TXV | TP9C060B12MP13 | 14,600 | $730 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417411 | COLEMAN | HMH72B241 | XAFC36DXXN1+TXV | TM9V060B12MP12 | 14,600 | $730 |
| No | 207417387 | COLEMAN | HMH72B241 | XAUB36DXXN1+TXV | TM9Y080B12MP11 | 14,600 | $730 |
| No | 207417383 | COLEMAN | HMH72B241 | XAFB36DXXN1+TXV | TM9Y080B12MP11 | 14,600 | $730 |
| No | 208614040 | COLEMAN | HMH72B361 | XAFC36DBCN1+JMET16CS2N1 | | 24,200 | $1,210 |
| No | 208500505 | COLEMAN | HMH72B361 | XAFC36DXXN1+JMET16CS2N1+TXV | | 24,200 | $1,210 |
| No | 208503336 | COLEMAN | HMH72B361 | XAHC36DXXN1+JMET12CS2N1+TXV | | 24,200 | $1,210 |
| No | 208614045 | COLEMAN | HMH72B361 | XAFC36DBCN1+JMET12CS2N1 | | 24,800 | $1,240 |
| No | 208502630 | COLEMAN | HMH72B361 | XAFC36DXXN1+JMET12CS2N1+TXV | | 24,800 | $1,240 |
| No | 208503295 | COLEMAN | HMH72B361 | XAHB36DXXN1+JMVT12BC2N1+TXV | | 24,200 | $1,210 |
| No | 208400374 | COLEMAN | HMH72B361 | XAHB36DXXN1+ME12BN21+TXV | | 24,400 | $1,220 |
| No | 208400370 | COLEMAN | HMH72B361 | XAHC36DXXN1+MVC12CN21+TXV | | 24,200 | $1,210 |
| No | 207416602 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 207416598 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 208213974 | COLEMAN | HMH72B361 | XAHB36DXXN1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 208213952 | COLEMAN | HMH72B361 | XAHB36DXXN1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 207417105 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TMLE080C16MP11 | 25,000 | $1,250 |
| No | 207417101 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TM8E080C16MP11 | 25,000 | $1,250 |
| No | 207417097 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TMLE120C16MP11 | 25,000 | $1,250 |
| No | 207417093 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TM8E120C16MP11 | 25,000 | $1,250 |
| No | 208213915 | COLEMAN | HMH72B361 | XAHB36DXXN1+TXV | TM8Y080B12MP11 | 24,400 | $1,220 |
| No | 207417008 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TM8Y120C20MP11 | 24,600 | $1,230 |
| No | 208213957 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TM9E060B12MP12 | 24,200 | $1,210 |
| No | 208213965 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TM9E100C16MP12 | 24,600 | $1,230 |
| No | 207416978 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | CP9C080B12MP13 | 25,000 | $1,250 |
| No | 207416974 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 207416970 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 207416968 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | CP9C080B12MP13 | 25,000 | $1,250 |
| No | 207416964 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 207416960 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 207416430 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | CP9C100C20MP13 | 25,200 | $1,260 |
| No | 207416426 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TP9C100C20MP13 | 25,200 | $1,260 |
| No | 207416422 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TM9V100C20MP12 | 25,200 | $1,260 |
| No | 208213909 | COLEMAN | HMH72B361 | XAHB36DXXN1+TXV | TM9Y080B12MP11 | 24,400 | $1,220 |
| No | 208502166 | COLEMAN | HMH72B361 | XAUB36DXXN1+JMVT12BC2N1+TXV | | 24,600 | $1,230 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208614043 | COLEMAN | HMH72B361 | XAFB36DBCN1+JMVT12BC2N1 | | 24,600 | $1,230 |
| No | 208502159 | COLEMAN | HMH72B361 | XAFB36DXXN1+JMVT12BC2N1+TXV | | 24,600 | $1,230 |
| No | 207434666 | COLEMAN | HMH72B361 | XAUB36DXXN1+ME12BN21+TXV | | 24,800 | $1,240 |
| No | 207434665 | COLEMAN | HMH72B361 | XAFB36DXXN1+ME12BN21+TXV | | 24,800 | $1,240 |
| No | 207434668 | COLEMAN | HMH72B361 | XAFC36DXXN1+MVC12CN21+TXV | | 24,600 | $1,230 |
| No | 208213960 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TL8E080C16UH11 | 24,400 | $1,220 |
| No | 207417145 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | TMLE040A12MP11 | 25,000 | $1,250 |
| No | 207417141 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | TM8E040A12MP11 | 25,000 | $1,250 |
| No | 207417137 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | TMLE040A12MP11 | 25,000 | $1,250 |
| No | 207417133 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | TM8E040A12MP11 | 25,000 | $1,250 |
| No | 208501094 | COLEMAN | HMH72B361 | XAHC36DXXN1+JMVT16CC2N1+TXV | | 24,000 | $1,200 |
| No | 208400373 | COLEMAN | HMH72B361 | XAHC36DXXN1+ME12CN21+TXV | | 24,400 | $1,220 |
| No | 208400375 | COLEMAN | HMH72B361 | XAHC36DXXN1+MVC16CN21+TXV | | 24,400 | $1,220 |
| No | 208213964 | COLEMAN | HMH72B361 | XAHB36DXXN1+TXV | TL9E060B12UH11 | 24,000 | $1,200 |
| No | 207416582 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | TMLE060A12MP11 | 25,200 | $1,260 |
| No | 207416578 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | TM8E060A12MP11 | 25,200 | $1,260 |
| No | 207416574 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | TMLE060A12MP11 | 25,200 | $1,260 |
| No | 207416570 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | TM8E060A12MP11 | 25,200 | $1,260 |
| No | 207416558 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 207416554 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 207416550 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 207416546 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 207417089 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | TPLC060A12MP13 | 25,400 | $1,270 |
| No | 207417085 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | TMLV060A12MP12 | 25,400 | $1,270 |
| No | 207417081 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | TM8V060A12MP12 | 25,400 | $1,270 |
| No | 207417077 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | TPLC060A12MP13 | 25,400 | $1,270 |
| No | 207417073 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | TMLV060A12MP12 | 25,400 | $1,270 |
| No | 207417069 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | TM8V060A12MP12 | 25,400 | $1,270 |
| No | 208213931 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | CPLC100C16MP13 | 24,600 | $1,230 |
| No | 208213930 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | CPLC080C16MP13 | 24,600 | $1,230 |
| No | 208213926 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 208213929 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TPLC080C16MP13 | 24,600 | $1,230 |
| No | 208213959 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TMLV100C16MP12 | 24,600 | $1,230 |
| No | 208213941 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TM8V080C16MP12 | 24,600 | $1,230 |
| No | 208213942 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 207416496 | COLEMAN | HMH72B361 | XAFA30DXXN1+TXV | TM9E060A10MP12 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208213977 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 208213955 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TM8E080B12MP11 | 24,600 | $1,230 |
| No | 208213978 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TMLE100C16MP11 | 24,600 | $1,230 |
| No | 208213971 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TM8E100C16MP11 | 24,600 | $1,230 |
| No | 207416508 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TM8Y080B12MP11 | 25,000 | $1,250 |
| No | 208213958 | COLEMAN | HMH72B361 | XAHB36DXXN1+TXV | TM9E060B12MP12 | 24,200 | $1,210 |
| No | 207416460 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TM9E100C16MP12 | 25,000 | $1,250 |
| No | 208213922 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | CP9C060B12MP13 | 24,400 | $1,220 |
| No | 208213938 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 208213943 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 208213924 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | CP9C100C16MP13 | 24,600 | $1,230 |
| No | 208213932 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TP9C100C16MP13 | 24,600 | $1,230 |
| No | 208213949 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TM9V100C16MP12 | 24,600 | $1,230 |
| No | 207416928 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TM9Y080B12MP11 | 25,000 | $1,250 |
| No | 207416464 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TM9E080B12MP12 | 25,200 | $1,260 |
| No | 207416456 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | TM9V040A10MP12 | 24,600 | $1,230 |
| No | 207416452 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | TM9V040A10MP12 | 24,600 | $1,230 |
| No | 208213919 | COLEMAN | HMH72B361 | XAHB36DXXN1+TXV | CP9C080B12MP13 | 24,400 | $1,220 |
| No | 208213934 | COLEMAN | HMH72B361 | XAHB36DXXN1+TXV | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 208213946 | COLEMAN | HMH72B361 | XAHB36DXXN1+TXV | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 207416936 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | TM9Y060B12MP11 | 25,000 | $1,250 |
| No | 207416932 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | TM9Y060B12MP11 | 25,000 | $1,250 |
| No | 207416924 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TM9Y080C16MP11 | 25,000 | $1,250 |
| No | 208614044 | COLEMAN | HMH72B361 | JHETB36DBCS2N1 | | 25,000 | $1,250 |
| No | 208502180 | COLEMAN | HMH72B361 | JHETB36DXXS2N1+TXV | | 25,000 | $1,250 |
| No | 207434669 | COLEMAN | HMH72B361 | XAFC36DXXN1+ME16CN21+TXV | | 25,000 | $1,250 |
| No | 208213963 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TL9E060B12UH11 | 24,000 | $1,200 |
| No | 208213973 | COLEMAN | HMH72B361 | XAHB36DXXN1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 208213951 | COLEMAN | HMH72B361 | XAHB36DXXN1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 207416542 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 207416538 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 207416525 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | TPLC080B12MP13 | 25,000 | $1,250 |
| No | 207416521 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | TM8V080B12MP12 | 25,000 | $1,250 |
| No | 207416516 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | TPLC080B12MP13 | 25,000 | $1,250 |
| No | 207416512 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | TM8V080B12MP12 | 25,000 | $1,250 |
| No | 207416492 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | TM9E060A10MP12 | 25,200 | $1,260 |
| No | 207416488 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | TM9E060A10MP12 | 25,200 | $1,260 |
| No | 208614042 | COLEMAN | HMH72B361 | JHETC36DBCS2N1 | | 24,000 | $1,200 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208500517 | COLEMAN | HMH72B361 | JHETC36DXXS2N1+TXV | | 24,000 | $1,200 |
| No | 207434671 | COLEMAN | HMH72B361 | XAUB36DXXN1+MVC12BN21+TXV | | 24,800 | $1,240 |
| No | 207434672 | COLEMAN | HMH72B361 | XAFB36DXXN1+MVC12BN21+TXV | | 24,800 | $1,240 |
| No | 208213961 | COLEMAN | HMH72B361 | XAHB36DXXN1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 208213962 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TL9E080C16UH11 | 24,600 | $1,230 |
| No | 207416566 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TMLE080B12MP11 | 25,200 | $1,260 |
| No | 207416562 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TM8E080B12MP11 | 25,200 | $1,260 |
| No | 208213967 | COLEMAN | HMH72B361 | XAHB36DXXN1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 208213947 | COLEMAN | HMH72B361 | XAHB36DXXN1+TXV | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 208213920 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | CP9C080B12MP13 | 24,600 | $1,230 |
| No | 208213935 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 208213945 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 207416418 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TM9Y060B12MP11 | 25,000 | $1,250 |
| No | 208213908 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TM9Y080C16MP11 | 24,600 | $1,230 |
| No | 208213980 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 208213970 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 208213927 | COLEMAN | HMH72B361 | XAHB36DXXN1+TXV | TPLC080B12MP13 | 24,200 | $1,210 |
| No | 208213939 | COLEMAN | HMH72B361 | XAHB36DXXN1+TXV | TM8V080B12MP12 | 24,200 | $1,210 |
| No | 208213917 | COLEMAN | HMH72B361 | XAHB36DXXN1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 208213918 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TM8Y080C16MP11 | 24,000 | $1,200 |
| No | 208213913 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TM8Y100C16MP11 | 24,000 | $1,200 |
| No | 207416484 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 207416480 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 208614047 | COLEMAN | HMH72B361 | JHVTC36DBCC2N1 | | 24,400 | $1,220 |
| No | 208501702 | COLEMAN | HMH72B361 | JHVTC36DXXC2N1+TXV | | 24,400 | $1,220 |
| No | 208400372 | COLEMAN | HMH72B361 | XAHC36DXXN1+ME16CN21+TXV | | 24,600 | $1,230 |
| No | 207416610 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | TL8E060A12UH11 | 25,000 | $1,250 |
| No | 207416606 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | TL8E060A12UH11 | 25,000 | $1,250 |
| No | 207416594 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TL9E080C16UH11 | 25,000 | $1,250 |
| No | 207417121 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | TMLE080B12MP11 | 25,200 | $1,260 |
| No | 207417117 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | TM8E080B12MP11 | 25,200 | $1,260 |
| No | 207417113 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | TMLE080B12MP11 | 25,200 | $1,260 |
| No | 207417109 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | TM8E080B12MP11 | 25,200 | $1,260 |
| No | 208614041 | COLEMAN | HMH72B361 | XAFC36DBCN1+JMVT16CC2N1 | | 24,400 | $1,220 |
| No | 208501102 | COLEMAN | HMH72B361 | XAFC36DXXN1+JMVT16CC2N1+TXV | | 24,400 | $1,220 |
| No | 207434670 | COLEMAN | HMH72B361 | XAFC36DXXN1+ME12CN21+TXV | | 24,800 | $1,240 |
| No | 207434667 | COLEMAN | HMH72B361 | XAFC36DXXN1+MVC16CN21+TXV | | 24,800 | $1,240 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417149 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 207417004 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TM9E080C16MP12 | 25,000 | $1,250 |
| No | 207416450 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | CP9C060B12MP13 | 24,800 | $1,240 |
| No | 207416446 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TP9C060B12MP13 | 24,800 | $1,240 |
| No | 207416442 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TM9V060B12MP12 | 24,800 | $1,240 |
| No | 208213925 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | CP9C080C16MP13 | 24,600 | $1,230 |
| No | 208213936 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TP9C080C16MP13 | 24,600 | $1,230 |
| No | 208213948 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TM9V080C16MP12 | 24,600 | $1,230 |
| No | 208213911 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TM9Y060B12MP11 | 24,400 | $1,220 |
| No | 208213906 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TM9Y100C16MP11 | 24,600 | $1,230 |
| No | 208213979 | COLEMAN | HMH72B361 | XAHB36DXXN1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 208213969 | COLEMAN | HMH72B361 | XAHB36DXXN1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 207417064 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TPLC080B12MP13 | 25,000 | $1,250 |
| No | 207417060 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TM8V080B12MP12 | 25,000 | $1,250 |
| No | 207417028 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | TM8Y060A12MP11 | 24,800 | $1,240 |
| No | 207417024 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | TM8Y060A12MP11 | 24,800 | $1,240 |
| No | 207416504 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TM8Y080C16MP11 | 24,600 | $1,230 |
| No | 207417012 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TM8Y100C16MP11 | 24,600 | $1,230 |
| No | 208213956 | COLEMAN | HMH72B361 | XAHB36DXXN1+TXV | TM9E060A10MP12 | 24,200 | $1,210 |
| No | 208213975 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TMLE080C16MP11 | 24,400 | $1,220 |
| No | 208213953 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TM8E080C16MP11 | 24,400 | $1,220 |
| No | 208213981 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TMLE120C16MP11 | 24,600 | $1,230 |
| No | 208213972 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TM8E120C16MP11 | 24,600 | $1,230 |
| No | 207417058 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | CPLC100C16MP13 | 25,200 | $1,260 |
| No | 207417056 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | CPLC080C16MP13 | 25,200 | $1,260 |
| No | 207417052 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TPLC100C16MP13 | 25,200 | $1,260 |
| No | 207417048 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TPLC080C16MP13 | 25,200 | $1,260 |
| No | 207417044 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TMLV100C16MP12 | 25,200 | $1,260 |
| No | 207417040 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TM8V080C16MP12 | 25,200 | $1,260 |
| No | 207417036 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TM8V100C16MP12 | 25,200 | $1,260 |
| No | 208213916 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TM8Y080B12MP11 | 24,400 | $1,220 |
| No | 208213914 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TM8Y100C20MP11 | 24,200 | $1,210 |
| No | 208213912 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TM8Y120C20MP11 | 24,200 | $1,210 |
| No | 208502173 | COLEMAN | HMH72B361 | XAHC36DXXN1+JMET16CS2N1+TXV | | 24,400 | $1,220 |
| No | 208614046 | COLEMAN | HMH72B361 | JHVTB36DBCC2N1 | | 25,200 | $1,260 |
| No | 208502637 | COLEMAN | HMH72B361 | JHVTB36DXXC2N1+TXV | | 25,200 | $1,260 |
| No | 208400371 | COLEMAN | HMH72B361 | XAHB36DXXN1+MVC12BN21+TXV | | 24,400 | $1,220 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417153 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TL8E080C16UH11 | 25,000 | $1,250 |
| No | 208213966 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 207416998 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | CP9C060B12MP13 | 25,000 | $1,250 |
| No | 207416994 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 207416990 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 207416988 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | CP9C060B12MP13 | 25,000 | $1,250 |
| No | 207416984 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 207416980 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 207416958 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | CP9C080C16MP13 | 25,000 | $1,250 |
| No | 207416954 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TP9C080C16MP13 | 25,000 | $1,250 |
| No | 207416950 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TM9V080C16MP12 | 25,000 | $1,250 |
| No | 208213910 | COLEMAN | HMH72B361 | XAHB36DXXN1+TXV | TM9Y060B12MP11 | 23,800 | $1,190 |
| No | 207416920 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TM9Y100C16MP11 | 25,000 | $1,250 |
| No | 207416472 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | TM9E080B12MP12 | 25,200 | $1,260 |
| No | 207416468 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | TM9E080B12MP12 | 25,200 | $1,260 |
| No | 207417000 | COLEMAN | HMH72B361 | XAFA30DXXN1+TXV | TM9V040A10MP12 | 24,400 | $1,220 |
| No | 207416440 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | CP9C080B12MP13 | 25,000 | $1,250 |
| No | 207416436 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 207416432 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 208213923 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | CP9C100C20MP13 | 25,000 | $1,250 |
| No | 208213933 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TP9C100C20MP13 | 25,000 | $1,250 |
| No | 208213950 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TM9V100C20MP12 | 25,000 | $1,250 |
| No | 208213907 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TM9Y080B12MP11 | 24,400 | $1,220 |
| No | 208213976 | COLEMAN | HMH72B361 | XAHB36DXXN1+TXV | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 208213954 | COLEMAN | HMH72B361 | XAHB36DXXN1+TXV | TM8E080B12MP11 | 24,600 | $1,230 |
| No | 207416534 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TMLE100C16MP11 | 25,000 | $1,250 |
| No | 207416530 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TM8E100C16MP11 | 25,000 | $1,250 |
| No | 208213928 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 208213940 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 207417020 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | TM8Y080B12MP11 | 25,000 | $1,250 |
| No | 207417016 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | TM8Y080B12MP11 | 25,000 | $1,250 |
| No | 207416500 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TM8Y100C20MP11 | 24,600 | $1,230 |
| No | 207416476 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 208213968 | COLEMAN | HMH72B361 | XAHC36DXXN1+TXV | TM9E080C16MP12 | 24,600 | $1,230 |
| No | 208213921 | COLEMAN | HMH72B361 | XAHB36DXXN1+TXV | CP9C060B12MP13 | 24,600 | $1,230 |
| No | 208213937 | COLEMAN | HMH72B361 | XAHB36DXXN1+TXV | TP9C060B12MP13 | 24,600 | $1,230 |
| No | 208213944 | COLEMAN | HMH72B361 | XAHB36DXXN1+TXV | TM9V060B12MP12 | 24,600 | $1,230 |
| No | 207416948 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | CP9C100C16MP13 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207416944 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TP9C100C16MP13 | 25,000 | $1,250 |
| No | 207416940 | COLEMAN | HMH72B361 | XAFC36DXXN1+TXV | TM9V100C16MP12 | 25,000 | $1,250 |
| No | 207416414 | COLEMAN | HMH72B361 | XAUB36DXXN1+TXV | TM9Y080B12MP11 | 25,000 | $1,250 |
| No | 207416410 | COLEMAN | HMH72B361 | XAFB36DXXN1+TXV | TM9Y080B12MP11 | 25,000 | $1,250 |
| No | 208214491 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | TL8E100C20UH11 | 35,800 | $1,790 |
| No | 208214498 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | TMLE100C16MP11 | 36,000 | $1,800 |
| No | 208214495 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | TM8E100C16MP11 | 36,000 | $1,800 |
| No | 208214490 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | TM9E080C20MP12 | 36,600 | $1,830 |
| No | 208214477 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | CP9C100C20MP13 | 36,200 | $1,810 |
| No | 208214480 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | TP9C100C20MP13 | 36,200 | $1,810 |
| No | 208214484 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | TM9V100C20MP12 | 36,200 | $1,810 |
| No | 208502187 | COLEMAN | HMH72B601 | XAHD60JXXN1+JMET18DS2N1+TXV | | 35,800 | $1,790 |
| No | 208400419 | COLEMAN | HMH72B601 | XAHD60JXXN1+MVC20DN21+TXV | | 36,800 | $1,840 |
| No | 208614091 | COLEMAN | HMH72B601 | JHETD60JBCS2N1 | | 36,400 | $1,820 |
| No | 208501709 | COLEMAN | HMH72B601 | JHETD60JXXS2N1+TXV | | 36,400 | $1,820 |
| No | 207434722 | COLEMAN | HMH72B601 | XAFD60JXXN1+ME20DN21+TXV | | 37,200 | $1,860 |
| No | 208214499 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | TMLE080C16MP11 | 36,000 | $1,800 |
| No | 208214487 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | TM8E080C16MP11 | 36,000 | $1,800 |
| No | 208214501 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | TMLE120C16MP11 | 36,000 | $1,800 |
| No | 208214496 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | TM8E120C16MP11 | 36,000 | $1,800 |
| No | 208214489 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | TM9E120D20MP12 | 36,000 | $1,800 |
| No | 208214471 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | TM9Y100C20MP11 | 35,800 | $1,790 |
| No | 207416784 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TMLE100C20MP11 | 36,200 | $1,810 |
| No | 207416780 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TM8E100C20MP11 | 36,200 | $1,810 |
| No | 207416772 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TM8Y100C16MP11 | 36,600 | $1,830 |
| No | 207417344 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TM9E100C20MP12 | 37,000 | $1,850 |
| No | 207417318 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | CP9C120D20MP13 | 37,400 | $1,870 |
| No | 207417314 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TP9C120D20MP13 | 37,400 | $1,870 |
| No | 207417310 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TM9V120D20MP12 | 37,400 | $1,870 |
| No | 208614088 | COLEMAN | HMH72B601 | JHVTD60JBCC2N1 | | 36,200 | $1,810 |
| No | 208501117 | COLEMAN | HMH72B601 | JHVTD60JXXC2N1+TXV | | 36,200 | $1,810 |
| No | 208400418 | COLEMAN | HMH72B601 | XAHD60JXXN1+ME20DN21+TXV | | 36,600 | $1,830 |
| No | 208614089 | COLEMAN | HMH72B601 | XAFD60JBCN1+JMVT20DC2N1 | | 36,000 | $1,800 |
| No | 208500529 | COLEMAN | HMH72B601 | XAFD60JXXN1+JMVT20DC2N1+TXV | | 36,000 | $1,800 |
| No | 207416820 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TL8E080C16UH11 | 36,600 | $1,830 |
| No | 207416800 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TMLE080C20MP11 | 36,400 | $1,820 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207416796 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TM8E080C20MP11 | 36,400 | $1,820 |
| No | 207417338 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | CP9C100C16MP13 | 36,800 | $1,840 |
| No | 207417334 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TP9C100C16MP13 | 36,800 | $1,840 |
| No | 207417330 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TM9V100C16MP12 | 36,800 | $1,840 |
| No | 208214493 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | TL9E100C20UH11 | 36,000 | $1,800 |
| No | 208214500 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | TMLE100C20MP11 | 35,600 | $1,780 |
| No | 208214494 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | TM8E100C20MP11 | 35,600 | $1,780 |
| No | 208214476 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | TM8Y080C16MP11 | 35,800 | $1,790 |
| No | 208214474 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | TM8Y100C16MP11 | 35,800 | $1,790 |
| No | 208214488 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | TM9E100C20MP12 | 36,400 | $1,820 |
| No | 208214479 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | CP9C120D20MP13 | 36,200 | $1,810 |
| No | 208214482 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | TP9C120D20MP13 | 36,200 | $1,810 |
| No | 208214485 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | TM9V120D20MP12 | 36,200 | $1,810 |
| No | 207416816 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TL8E100C20UH11 | 36,600 | $1,830 |
| No | 207417348 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TM9E080C20MP12 | 37,200 | $1,860 |
| No | 208614090 | COLEMAN | HMH72B601 | XAFD60JBCN1+JMET18DS2N1 | | 36,400 | $1,820 |
| No | 208500540 | COLEMAN | HMH72B601 | XAFD60JXXN1+JMET18DS2N1+TXV | | 36,400 | $1,820 |
| No | 207416812 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TL9E100C20UH11 | 36,600 | $1,830 |
| No | 207416776 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TM8Y080C16MP11 | 36,600 | $1,830 |
| No | 207417328 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | CP9C100C20MP13 | 36,800 | $1,840 |
| No | 207417324 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TP9C100C20MP13 | 36,800 | $1,840 |
| No | 207417320 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TM9V100C20MP12 | 36,800 | $1,840 |
| No | 207434721 | COLEMAN | HMH72B601 | XAFD60JXXN1+MVC20DN21+TXV | | 37,200 | $1,860 |
| No | 208501110 | COLEMAN | HMH72B601 | XAHD60JXXN1+JMVT20DC2N1+TXV | | 35,400 | $1,770 |
| No | 207416792 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TMLE100C16MP11 | 36,800 | $1,840 |
| No | 207416788 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TM8E100C16MP11 | 36,800 | $1,840 |
| No | 207416764 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TM8Y120C20MP11 | 36,400 | $1,820 |
| No | 207417302 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TM9Y120D20MP11 | 36,600 | $1,830 |
| No | 208214492 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | TL8E080C16UH11 | 36,000 | $1,800 |
| No | 207416808 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TMLE080C16MP11 | 36,800 | $1,840 |
| No | 207416804 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TM8E080C16MP11 | 36,800 | $1,840 |
| No | 207417379 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TMLE120C16MP11 | 36,600 | $1,830 |
| No | 207417375 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TM8E120C16MP11 | 36,600 | $1,830 |
| No | 207416768 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TM8Y100C20MP11 | 36,400 | $1,820 |
| No | 207417340 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TM9E120D20MP12 | 37,200 | $1,860 |
| No | 207417306 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TM9Y100C20MP11 | 36,600 | $1,830 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208214497 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | TMLE080C20MP11 | 35,600 | $1,780 |
| No | 208214486 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | TM8E080C20MP11 | 35,600 | $1,780 |
| No | 207417373 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | CPLC120C20MP13 | 37,400 | $1,870 |
| No | 207417368 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TPLC120C20MP13 | 37,400 | $1,870 |
| No | 207417364 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TPLC100C20MP13 | 37,400 | $1,870 |
| No | 207417360 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TMLV120C20MP12 | 37,400 | $1,870 |
| No | 207417356 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TM8V100C20MP12 | 37,400 | $1,870 |
| No | 207417352 | COLEMAN | HMH72B601 | XAFD60JXXN1+TXV | TM8V120C20MP12 | 37,400 | $1,870 |
| No | 208214475 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | TM8Y100C20MP11 | 35,600 | $1,780 |
| No | 208214473 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | TM8Y120C20MP11 | 35,600 | $1,780 |
| No | 208214478 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | CP9C100C16MP13 | 36,200 | $1,810 |
| No | 208214481 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | TP9C100C16MP13 | 36,200 | $1,810 |
| No | 208214483 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | TM9V100C16MP12 | 36,200 | $1,810 |
| No | 208214472 | COLEMAN | HMH72B601 | XAHD60JXXN1+TXV | TM9Y120D20MP11 | 35,800 | $1,790 |
| No | 207434699 | COLEMAN | HMH72B481 | XAFC60HXXN1+ME12CN21+TXV | | 29,200 | $1,460 |
| No | 208400396 | COLEMAN | HMH72B481 | XAHC60HXXN1+MVC12CN21+TXV | | 28,600 | $1,430 |
| No | 208400399 | COLEMAN | HMH72B481 | XAHC60HXXN1+ME12CN21+TXV | | 28,600 | $1,430 |
| No | 207434697 | COLEMAN | HMH72B481 | XAFC60HXXN1+MVC12CN21+TXV | | 28,800 | $1,440 |
| No | 207416760 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TL8E100C20UH11 | 29,800 | $1,490 |
| No | 208614074 | COLEMAN | HMH72B481 | JHETD48GBCS2N1 | | 29,600 | $1,480 |
| No | 208501086 | COLEMAN | HMH72B481 | JHETC60HXXS2N1+TXV | | 29,600 | $1,480 |
| No | 207434698 | COLEMAN | HMH72B481 | XAFD60JXXN1+ME14DN21+TXV | | 30,000 | $1,500 |
| No | 207417298 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TL8E080C16UH11 | 29,200 | $1,460 |
| No | 207417531 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TMLE080C16MP11 | 30,200 | $1,510 |
| No | 207417527 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TM8E080C16MP11 | 30,200 | $1,510 |
| No | 207416734 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | CPLC100C16MP13 | 29,600 | $1,480 |
| No | 207416732 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | CPLC080C16MP13 | 29,600 | $1,480 |
| No | 207416728 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TPLC100C16MP13 | 29,600 | $1,480 |
| No | 207416724 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TPLC080C16MP13 | 29,600 | $1,480 |
| No | 207416720 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TMLV100C16MP12 | 29,600 | $1,480 |
| No | 207416712 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TM8V100C16MP12 | 29,600 | $1,480 |
| No | 207416894 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | CP9C100C20MP13 | 31,000 | $1,550 |
| No | 207416890 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TP9C100C20MP13 | 31,000 | $1,550 |
| No | 207416886 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TM9V100C20MP12 | 31,000 | $1,550 |
| No | 207417205 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TM9Y100C16MP11 | 30,200 | $1,510 |
| No | 207416900 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TM8Y100C20MP11 | 29,800 | $1,490 |
| No | 207416896 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TM8Y120C20MP11 | 29,800 | $1,490 |
| No | 208400398 | COLEMAN | HMH72B481 | XAHD60JXXN1+ME14DN21+TXV | | 28,800 | $1,440 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207416908 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TL8E080C16UH11 | 30,200 | $1,510 |
| No | 208214284 | COLEMAN | HMH72B481 | XAHD60JXXN1+TXV | TMLE080C16MP11 | 29,600 | $1,480 |
| No | 208214271 | COLEMAN | HMH72B481 | XAHD60JXXN1+TXV | TM8E080C16MP11 | 29,600 | $1,480 |
| No | 207416912 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TM9Y100C16MP11 | 30,000 | $1,500 |
| No | 207417509 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | CPLC120C20MP13 | 29,800 | $1,490 |
| No | 207417504 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TPLC120C20MP13 | 29,800 | $1,490 |
| No | 207417500 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TPLC100C20MP13 | 29,800 | $1,490 |
| No | 207417496 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TMLV120C20MP12 | 29,800 | $1,490 |
| No | 207417488 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TM8V120C20MP12 | 29,800 | $1,490 |
| No | 208614073 | COLEMAN | HMH72B481 | JHVTD60JBCC2N1 | | 29,800 | $1,490 |
| No | 208503452 | COLEMAN | HMH72B481 | JHVTD60JXXC2N1+TXV | | 29,800 | $1,490 |
| No | 207416756 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TMLE080C16MP11 | 30,000 | $1,500 |
| No | 207416752 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TM8E080C16MP11 | 30,000 | $1,500 |
| No | 207416716 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TM8V080C16MP12 | 29,600 | $1,480 |
| No | 208214247 | COLEMAN | HMH72B481 | XAHD60JXXN1+TXV | CPLC120C20MP13 | 28,800 | $1,440 |
| No | 208214244 | COLEMAN | HMH72B481 | XAHD60JXXN1+TXV | TPLC120C20MP13 | 28,800 | $1,440 |
| No | 208214242 | COLEMAN | HMH72B481 | XAHD60JXXN1+TXV | TPLC100C20MP13 | 28,800 | $1,440 |
| No | 208214272 | COLEMAN | HMH72B481 | XAHD60JXXN1+TXV | TMLV120C20MP12 | 28,800 | $1,440 |
| No | 208214263 | COLEMAN | HMH72B481 | XAHD60JXXN1+TXV | TM8V120C20MP12 | 28,800 | $1,440 |
| No | 208214235 | COLEMAN | HMH72B481 | XAHD60JXXN1+TXV | CP9C100C16MP13 | 30,400 | $1,520 |
| No | 208214253 | COLEMAN | HMH72B481 | XAHD60JXXN1+TXV | TP9C100C16MP13 | 30,400 | $1,520 |
| No | 208214269 | COLEMAN | HMH72B481 | XAHD60JXXN1+TXV | TM9V100C16MP12 | 30,400 | $1,520 |
| No | 207417201 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TM9Y120D20MP11 | 30,600 | $1,530 |
| No | 208214286 | COLEMAN | HMH72B481 | XAHD60JXXN1+TXV | TMLE120C16MP11 | 29,600 | $1,480 |
| No | 208214282 | COLEMAN | HMH72B481 | XAHD60JXXN1+TXV | TM8E120C16MP11 | 29,600 | $1,480 |
| No | 207417264 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | CPLC120C20MP13 | 29,200 | $1,460 |
| No | 207417259 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TPLC120C20MP13 | 29,200 | $1,460 |
| No | 207417255 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TPLC100C20MP13 | 29,200 | $1,460 |
| No | 207417251 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TMLV120C20MP12 | 29,200 | $1,460 |
| No | 207417243 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TM8V120C20MP12 | 29,200 | $1,460 |
| No | 207416696 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | CP9C100C16MP13 | 30,800 | $1,540 |
| No | 207416692 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TP9C100C16MP13 | 30,800 | $1,540 |
| No | 207416688 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TM9V100C16MP12 | 30,800 | $1,540 |
| No | 207416674 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TM9Y080C16MP11 | 30,200 | $1,510 |
| No | 208400397 | COLEMAN | HMH72B481 | XAHC60HXXN1+MVC16CN21+TXV | | 29,200 | $1,460 |
| No | 208614075 | COLEMAN | HMH72B481 | JHVTD42FBCC2N1 | | 29,800 | $1,490 |
| No | 208501153 | COLEMAN | HMH72B481 | JHVTC60HXXC2N1+TXV | | 29,800 | $1,490 |
| No | 207417290 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TL9E080C16UH11 | 29,600 | $1,480 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208214260 | COLEMAN | HMH72B481 | XAHD60JXXN1+TXV | TM8V100C20MP12 | 29,200 | $1,460 |
| No | 208214231 | COLEMAN | HMH72B481 | XAHD60JXXN1+TXV | TM8Y080C16MP11 | 29,600 | $1,480 |
| No | 208214230 | COLEMAN | HMH72B481 | XAHD60JXXN1+TXV | TM8Y100C16MP11 | 29,600 | $1,480 |
| No | 207416706 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | CP9C080C16MP13 | 30,600 | $1,530 |
| No | 207416702 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TP9C080C16MP13 | 30,600 | $1,530 |
| No | 207416698 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TM9V080C16MP12 | 30,600 | $1,530 |
| No | 208214245 | COLEMAN | HMH72B481 | XAHD60JXXN1+TXV | CP9C120D20MP13 | 30,400 | $1,520 |
| No | 208214251 | COLEMAN | HMH72B481 | XAHD60JXXN1+TXV | TP9C120D20MP13 | 30,400 | $1,520 |
| No | 208214265 | COLEMAN | HMH72B481 | XAHD60JXXN1+TXV | TM9V120D20MP12 | 30,400 | $1,520 |
| No | 207417486 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | CP9C100C16MP13 | 31,000 | $1,550 |
| No | 207417482 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TP9C100C16MP13 | 31,000 | $1,550 |
| No | 207417478 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TM9V100C16MP12 | 31,000 | $1,550 |
| No | 207434702 | COLEMAN | HMH72B481 | XAFC60HXXN1+ME16CN21+TXV | | 30,400 | $1,520 |
| No | 208214275 | COLEMAN | HMH72B481 | XAHD60JXXN1+TXV | TL8E080C16UH11 | 29,600 | $1,480 |
| No | 207416748 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TMLE100C16MP11 | 30,000 | $1,500 |
| No | 207416744 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TM8E100C16MP11 | 30,000 | $1,500 |
| No | 207417288 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | CPLC100C16MP13 | 29,400 | $1,470 |
| No | 207417286 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | CPLC080C16MP13 | 29,400 | $1,470 |
| No | 207417282 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TPLC100C16MP13 | 29,400 | $1,470 |
| No | 207417278 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TPLC080C16MP13 | 29,400 | $1,470 |
| No | 207417274 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TMLV100C16MP12 | 29,400 | $1,470 |
| No | 207417270 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TM8V080C16MP12 | 29,400 | $1,470 |
| No | 207417266 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TM8V100C16MP12 | 29,400 | $1,470 |
| No | 207417223 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TM8Y100C20MP11 | 29,600 | $1,480 |
| No | 207417219 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TM8Y120C20MP11 | 29,600 | $1,480 |
| No | 207416686 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | CP9C100C20MP13 | 31,000 | $1,550 |
| No | 207416682 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TP9C100C20MP13 | 31,000 | $1,550 |
| No | 207416678 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TM9V100C20MP12 | 31,000 | $1,550 |
| No | 208214220 | COLEMAN | HMH72B481 | XAHD60JXXN1+TXV | TM9Y120D20MP11 | 30,000 | $1,500 |
| No | 207417523 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TMLE100C16MP11 | 30,200 | $1,510 |
| No | 207417519 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TM8E100C16MP11 | 30,200 | $1,510 |
| No | 207434701 | COLEMAN | HMH72B481 | XAFD60JXXN1+MVC14DN21+TXV | | 29,800 | $1,490 |
| No | 207416904 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TL8E100C20UH11 | 30,000 | $1,500 |
| No | 207434700 | COLEMAN | HMH72B481 | XAFC60HXXN1+MVC16CN21+TXV | | 29,800 | $1,490 |
| No | 207417515 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TMLE120C16MP11 | 30,200 | $1,510 |
| No | 207417511 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TM8E120C16MP11 | 30,200 | $1,510 |
| No | 208614072 | COLEMAN | HMH72B481 | JHETD60JBCS2N1 | | 30,000 | $1,500 |
| No | 208503467 | COLEMAN | HMH72B481 | JHETD60JXXS2N1+TXV | | 30,000 | $1,500 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208400394 | COLEMAN | HMH72B481 | XAHD60JXXN1+MVC14DN21+TXV | | 29,400 | $1,470 |
| No | 208214277 | COLEMAN | HMH72B481 | XAHD60JXXN1+TXV | TL8E100C20UH11 | 29,400 | $1,470 |
| No | 208214285 | COLEMAN | HMH72B481 | XAHD60JXXN1+TXV | TMLE100C16MP11 | 29,600 | $1,480 |
| No | 208214281 | COLEMAN | HMH72B481 | XAHD60JXXN1+TXV | TM8E100C16MP11 | 29,600 | $1,480 |
| No | 207417247 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TM8V100C20MP12 | 29,600 | $1,480 |
| No | 207417239 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TM8Y080C16MP11 | 29,800 | $1,490 |
| No | 207417235 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TM8Y100C16MP11 | 29,800 | $1,490 |
| No | 208214227 | COLEMAN | HMH72B481 | XAHD60JXXN1+TXV | TM8Y100C20MP11 | 29,200 | $1,460 |
| No | 208214226 | COLEMAN | HMH72B481 | XAHD60JXXN1+TXV | TM8Y120C20MP11 | 29,200 | $1,460 |
| No | 208214236 | COLEMAN | HMH72B481 | XAHD60JXXN1+TXV | CP9C100C20MP13 | 30,400 | $1,520 |
| No | 208214254 | COLEMAN | HMH72B481 | XAHD60JXXN1+TXV | TP9C100C20MP13 | 30,400 | $1,520 |
| No | 208214264 | COLEMAN | HMH72B481 | XAHD60JXXN1+TXV | TM9V100C20MP12 | 30,400 | $1,520 |
| No | 207416740 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TMLE120C16MP11 | 30,000 | $1,500 |
| No | 207416736 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TM8E120C16MP11 | 30,000 | $1,500 |
| No | 207417492 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TM8V100C20MP12 | 29,800 | $1,490 |
| No | 207417231 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TM8Y080C16MP11 | 30,200 | $1,510 |
| No | 207417227 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TM8Y100C16MP11 | 30,200 | $1,510 |
| No | 207417217 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | CP9C080C16MP13 | 30,600 | $1,530 |
| No | 207417213 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TP9C080C16MP13 | 30,600 | $1,530 |
| No | 207417209 | COLEMAN | HMH72B481 | XAFC60HXXN1+TXV | TM9V080C16MP12 | 30,600 | $1,530 |
| No | 207416884 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | CP9C120D20MP13 | 30,800 | $1,540 |
| No | 207416880 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TP9C120D20MP13 | 30,800 | $1,540 |
| No | 207416876 | COLEMAN | HMH72B481 | XAFD60JXXN1+TXV | TM9V120D20MP12 | 30,800 | $1,540 |
| No | 9006285 | COLEMAN | CH16B6021 | AE60DX21+TXV | | 33,200 | $1,660 |
| No | 10309054 | COLEMAN | HC20B6021 | AVV61DE421 | | 46,000 | $2,300 |
| No | 10309050 | COLEMAN | HC20B6021 | CM61DE4A1+MVC20DN21 | | 45,500 | $2,275 |
| No | 10525561 | COLEMAN | HC20B2421 | CM25BE1A1 | CPLC080B12MP13 | 22,400 | $1,120 |
| No | 10525559 | COLEMAN | HC20B2421 | CM25BE1A1 | CP9C060B12MP13 | 21,200 | $1,060 |
| No | 10525560 | COLEMAN | HC20B2421 | CM25BE1A1 | CP9C080B12MP13 | 22,400 | $1,120 |
| No | 10525563 | COLEMAN | HC20B2421 | CM25BE1A1 | TM9V060B12MP12 | 21,200 | $1,060 |
| No | 10525565 | COLEMAN | HC20B2421 | CM25BE1A1 | TMLV080B12MP12 | 22,400 | $1,120 |
| No | 10525564 | COLEMAN | HC20B2421 | CM25BE1A1 | TM9V080B12MP12 | 22,400 | $1,120 |
| No | 10525567 | COLEMAN | HC20B2421 | CM25BE1A1 | TP9C080B12MP13 | 22,400 | $1,120 |
| No | 10525566 | COLEMAN | HC20B2421 | CM25BE1A1 | TP9C060B12MP13 | 21,200 | $1,060 |
| No | 10525597 | COLEMAN | HC20B4821 | CM50CE3A1 | TM9V100C16MP12 | 44,000 | $2,200 |
| No | 10525604 | COLEMAN | HC20B4821 | CM50CE3A1 | TP9C100C16MP13 | 44,000 | $2,200 |
| No | 201982912 | COLEMAN | HC20B2421 | AVV25BE121 | | 22,400 | $1,120 |
| No | 10525568 | COLEMAN | HC20B2421 | CM25BE1A1 | TPLC080B12MP13 | 22,400 | $1,120 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10525586 | COLEMAN | HC20B4821 | CM50CE3A1 | CP9C100C16MP13 | 44,000 | $2,200 |
| No | 10525562 | COLEMAN | HC20B2421S | CM25BE1A1+CC | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 10525613 | COLEMAN | HC20B6021S | CM61CE4A1+CC | CP9C100C20MP13 | 46,500 | $2,325 |
| No | 201982926 | COLEMAN | HC20B3621S | CM37BE2A1+CC | TM9V060B12MP12 | 31,600 | $1,580 |
| No | 201982929 | COLEMAN | HC20B3621S | CM37BE2A1+CC | TM9V080B12MP12 | 31,000 | $1,550 |
| No | 201982934 | COLEMAN | HC20B3621S | CM37BE2A1+CC | TP9C060B12MP13 | 31,600 | $1,580 |
| No | 201982940 | COLEMAN | HC20B3621S | CM37BE2A1+CC | CP9C060B12MP13 | 31,600 | $1,580 |
| No | 201982937 | COLEMAN | HC20B3621S | CM37BE2A1+CC | TP9C080B12MP13 | 31,000 | $1,550 |
| No | 201982943 | COLEMAN | HC20B3621S | CM37BE2A1+CC | CP9C080B12MP13 | 31,000 | $1,550 |
| No | 201982946 | COLEMAN | HC20B3621S | CM37BE2A1+MVC12BN21+CC | | 30,800 | $1,540 |
| No | 10525614 | COLEMAN | HC20B6021S | CM61CE4A1+CC | CPLC100C20MP13 | 46,000 | $2,300 |
| No | 10525615 | COLEMAN | HC20B6021S | CM61CE4A1+CC | CPLC120C20MP13 | 46,000 | $2,300 |
| No | 10525616 | COLEMAN | HC20B6021S | CM61CE4A1+CC | TM8V100C20MP12 | 46,000 | $2,300 |
| No | 10525617 | COLEMAN | HC20B6021S | CM61CE4A1+CC | TM8V120C20MP12 | 46,000 | $2,300 |
| No | 10525618 | COLEMAN | HC20B6021S | CM61CE4A1+CC | TM9V100C20MP12 | 46,500 | $2,325 |
| No | 10525619 | COLEMAN | HC20B6021S | CM61CE4A1+CC | TMLV100C20MP12 | 46,000 | $2,300 |
| No | 10525620 | COLEMAN | HC20B6021S | CM61CE4A1+CC | TMLV120C20MP12 | 46,000 | $2,300 |
| No | 10525621 | COLEMAN | HC20B6021S | CM61CE4A1+CC | TP9C100C20MP13 | 46,500 | $2,325 |
| No | 10525622 | COLEMAN | HC20B6021S | CM61CE4A1+CC | TPLC100C20MP13 | 46,000 | $2,300 |
| No | 10525623 | COLEMAN | HC20B6021S | CM61CE4A1+CC | TPLC120C20MP13 | 46,000 | $2,300 |
| No | 10525624 | COLEMAN | HC20B6021S | CM61DE4A1+CC | CP9C120D20MP13 | 46,000 | $2,300 |
| No | 10525625 | COLEMAN | HC20B6021S | CM61DE4A1+CC | TM9V120D20MP12 | 46,000 | $2,300 |
| No | 10525626 | COLEMAN | HC20B6021S | CM61DE4A1+CC | TP9C120D20MP13 | 46,000 | $2,300 |
| No | 201982948 | COLEMAN | HC20B6021S | AVV61DE421+CC | | 46,000 | $2,300 |
| No | 201982920 | COLEMAN | HC20B3621S | AVV37BE221+CC | | 31,000 | $1,550 |
| No | 205537298 | COLEMAN | CH16B3622 | CU36BXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203430828 | COLEMAN | CH16B3622 | CM36BBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205538521 | COLEMAN | CH16B3622 | CM36BXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203430822 | COLEMAN | CH16B3622 | CF36BBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205538513 | COLEMAN | CH16B3622 | CU36BXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203087053 | COLEMAN | CH16B3622 | CM36BBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205538504 | COLEMAN | CH16B3622 | CM36BXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203087035 | COLEMAN | CH16B3622 | CF36BBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205538487 | COLEMAN | CH16B3622 | CF36BXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205538477 | COLEMAN | CH16B3622 | CF36BXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205544332 | COLEMAN | CH16B3622 | CU36BXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 203088179 | COLEMAN | CH16B3622 | CM36BBCA1 | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205544321 | COLEMAN | CH16B3622 | CM36BXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203088162 | COLEMAN | CH16B3622 | CF36BBCA1 | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205544312 | COLEMAN | CH16B3622 | CF36BXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205544302 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 203088124 | COLEMAN | CH16B3622 | CM36CBCA1 | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205544294 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205544285 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205544276 | COLEMAN | CH16B3622 | CF42BXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205544267 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TL9E080C16UH11 | 22,400 | $1,120 |
| No | 205544254 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TL9E080C16UH11 | 22,400 | $1,120 |
| No | 205544242 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 203087829 | COLEMAN | CH16B3622 | CM48CBCA1 | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205544227 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 203087810 | COLEMAN | CH16B3622 | CF48CBCA1 | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205544217 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 203087775 | COLEMAN | CH16B3622 | CM48DBCA1 | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205544189 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205544178 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205544169 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205544159 | COLEMAN | CH16B3622 | CM36AXA1+TXV | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 205544155 | COLEMAN | CH16B3622 | CM36AXA1+TXV | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 205544151 | COLEMAN | CH16B3622 | CF36AXA1+TXV | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 205544147 | COLEMAN | CH16B3622 | CF36AXA1+TXV | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 206781237 | COLEMAN | CH16B3622 | CU36BXA1+TXV | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 203430988 | COLEMAN | CH16B3622 | CM36BBCA1 | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 206781241 | COLEMAN | CH16B3622 | CM36BXA1+TXV | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 203430982 | COLEMAN | CH16B3622 | CF36BBCA1 | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 206781233 | COLEMAN | CH16B3622 | CU36BXA1+TXV | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 203087605 | COLEMAN | CH16B3622 | CM36BBCA1 | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 206781229 | COLEMAN | CH16B3622 | CM36BXA1+TXV | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 203087584 | COLEMAN | CH16B3622 | CF36BBCA1 | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 206781225 | COLEMAN | CH16B3622 | CF36BXA1+TXV | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 206781221 | COLEMAN | CH16B3622 | CF36BXA1+TXV | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 205544143 | COLEMAN | CH16B3622 | CF42BXA1+TXV | TMLE060A12MP11 | 22,800 | $1,140 |
| No | 205544139 | COLEMAN | CH16B3622 | CF42BXA1+TXV | TM8E060A12MP11 | 22,800 | $1,140 |
| No | 206781217 | COLEMAN | CH16B3622 | CU36BXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 203430961 | COLEMAN | CH16B3622 | CM36BBCA1 | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 206781213 | COLEMAN | CH16B3622 | CM36BXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 203430955 | COLEMAN | CH16B3622 | CF36BBCA1 | TMLE080B12MP11 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781209 | COLEMAN | CH16B3622 | CU36BXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 203087507 | COLEMAN | CH16B3622 | CM36BBCA1 | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 206781205 | COLEMAN | CH16B3622 | CM36BXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 206781193 | COLEMAN | CH16B3622 | CF36BXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 206781189 | COLEMAN | CH16B3622 | CF36BXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 206781185 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203087491 | COLEMAN | CH16B3622 | CF36BBCA1 | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 203430889 | COLEMAN | CH16B3622 | CM36CBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 206781201 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 206781197 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 203087265 | COLEMAN | CH16B3622 | CM36CBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 206781181 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 206781177 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 206781173 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205544135 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203430878 | COLEMAN | CH16B3622 | CM42CBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205544208 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203430872 | COLEMAN | CH16B3622 | CF42CBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205544198 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 203087227 | COLEMAN | CH16B3622 | CM42CBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205544131 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 203087206 | COLEMAN | CH16B3622 | CF42CBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205544111 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205544097 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 206781169 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 206781165 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 206781161 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205544090 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203430856 | COLEMAN | CH16B3622 | CM48CBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 206781157 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205544123 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203430850 | COLEMAN | CH16B3622 | CF48CBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205544079 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 203087145 | COLEMAN | CH16B3622 | CM48CBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 203087127 | COLEMAN | CH16B3622 | CF48CBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205544070 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205544059 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205544048 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781153 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203430789 | COLEMAN | CH16B3622 | CM42CBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 206781149 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203430784 | COLEMAN | CH16B3622 | CF42CBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 206781145 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203086920 | COLEMAN | CH16B3622 | CM42CBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 206781141 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203086904 | COLEMAN | CH16B3622 | CF42CBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 206781137 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 206781133 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205544037 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203430773 | COLEMAN | CH16B3622 | CM48CBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205544026 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203430767 | COLEMAN | CH16B3622 | CF48CBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205544012 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203086865 | COLEMAN | CH16B3622 | CM48CBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205543999 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203086846 | COLEMAN | CH16B3622 | CF48CBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205543956 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205543938 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203430756 | COLEMAN | CH16B3622 | CM36CBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205543916 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205543984 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205543968 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203086803 | COLEMAN | CH16B3622 | CM36CBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205543902 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205543889 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205543880 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205543869 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 203430745 | COLEMAN | CH16B3622 | CM42CBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205543860 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 203430740 | COLEMAN | CH16B3622 | CF42CBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205543849 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203086760 | COLEMAN | CH16B3622 | CM42CBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205543836 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203086741 | COLEMAN | CH16B3622 | CF42CBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205543815 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205543803 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781125 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206781121 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781117 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206781113 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781109 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 203430663 | COLEMAN | CH16B3622 | CM48CBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206781129 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 203430657 | COLEMAN | CH16B3622 | CF48CBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206781105 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 203098230 | COLEMAN | CH16B3622 | CM48CBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781101 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 203098222 | COLEMAN | CH16B3622 | CF48CBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781097 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206781093 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 203430646 | COLEMAN | CH16B3622 | CM48DBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206781089 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206781085 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 203098206 | COLEMAN | CH16B3622 | CM48DBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781081 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781077 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781073 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206781069 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 205543785 | COLEMAN | CH16B3622 | CM36AXA1+TXV | TPLC060A12MP13 | 22,400 | $1,120 |
| No | 205543776 | COLEMAN | CH16B3622 | CM36AXA1+TXV | TMLV060A12MP12 | 22,400 | $1,120 |
| No | 205543768 | COLEMAN | CH16B3622 | CM36AXA1+TXV | TM8V060A12MP12 | 22,400 | $1,120 |
| No | 205543748 | COLEMAN | CH16B3622 | CF36AXA1+TXV | TPLC060A12MP13 | 22,400 | $1,120 |
| No | 205543737 | COLEMAN | CH16B3622 | CF36AXA1+TXV | TMLV060A12MP12 | 22,400 | $1,120 |
| No | 205543727 | COLEMAN | CH16B3622 | CF36AXA1+TXV | TM8V060A12MP12 | 22,400 | $1,120 |
| No | 205543715 | COLEMAN | CH16B3622 | CM36AXA1+TXV | TM9E060A10MP12 | 22,600 | $1,130 |
| No | 205543706 | COLEMAN | CH16B3622 | CF36AXA1+TXV | TM9E060A10MP12 | 22,600 | $1,130 |
| No | 205543695 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 206781065 | COLEMAN | CH16B3622 | CF42BXA1+TXV | TM9E060B12MP12 | 22,200 | $1,110 |
| No | 203097860 | COLEMAN | CH16B3622 | CM42CBCA1 | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205543825 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 203097852 | COLEMAN | CH16B3622 | CF42CBCA1 | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205543685 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 206781061 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 203097836 | COLEMAN | CH16B3622 | CM48CBCA1 | TM9E060B12MP12 | 22,600 | $1,130 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781057 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 203097828 | COLEMAN | CH16B3622 | CF48CBCA1 | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 206781053 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205543675 | COLEMAN | CH16B3622 | CU36BXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097812 | COLEMAN | CH16B3622 | CM36BBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205543667 | COLEMAN | CH16B3622 | CM36BXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205543653 | COLEMAN | CH16B3622 | CF36BXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097709 | COLEMAN | CH16B3622 | CM36CBCA1 | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 203097804 | COLEMAN | CH16B3622 | CF36BBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205543641 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 205543611 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 205543599 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 206781049 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 203097693 | COLEMAN | CH16B3622 | CM42CBCA1 | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 203097685 | COLEMAN | CH16B3622 | CF42CBCA1 | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 206781045 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 206781041 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 205543591 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 205543583 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 206781037 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 203097661 | COLEMAN | CH16B3622 | CM48CBCA1 | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 206781033 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 203097653 | COLEMAN | CH16B3622 | CF48CBCA1 | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 206781029 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 203097548 | COLEMAN | CH16B3622 | CM48DBCA1 | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205543575 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205543564 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205543554 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 206781025 | COLEMAN | CH16B3622 | CF42BXA1+TXV | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 203097452 | COLEMAN | CH16B3622 | AE36CX21+TXV | | 22,600 | $1,130 |
| No | 205543546 | COLEMAN | CH16B3622 | CM42DXA1+ME14DN21+TXV | | 22,000 | $1,100 |
| No | 205543538 | COLEMAN | CH16B3622 | CF42DXA1+ME14DN21+TXV | | 22,000 | $1,100 |
| No | 205543529 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205543489 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TM9Y080C16MP11 | 22,600 | $1,130 |
| No | 203096958 | COLEMAN | CH16B3622 | CM48CBCA1 | TM9Y080C16MP11 | 22,600 | $1,130 |
| No | 205543509 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205543628 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TM9Y080C16MP11 | 22,600 | $1,130 |
| No | 203096942 | COLEMAN | CH16B3622 | CF48CBCA1 | TM9Y080C16MP11 | 22,600 | $1,130 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205543459 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TM9Y080C16MP11 | 22,600 | $1,130 |
| No | 203096910 | COLEMAN | CH16B3622 | CM48DBCA1 | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205543425 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205543415 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205543388 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205543374 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TM9Y120D20MP11 | 22,400 | $1,120 |
| No | 205543357 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TM9Y120D20MP11 | 22,400 | $1,120 |
| No | 205543338 | COLEMAN | CH16B3622 | CM42DXA1+TXV | CPLC100C16MP13 | 22,200 | $1,110 |
| No | 205543332 | COLEMAN | CH16B3622 | CM42DXA1+TXV | CPLC080C16MP13 | 22,200 | $1,110 |
| No | 205543321 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205543314 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205543302 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205543279 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205543265 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205543259 | COLEMAN | CH16B3622 | CF42DXA1+TXV | CPLC100C16MP13 | 22,200 | $1,110 |
| No | 205543253 | COLEMAN | CH16B3622 | CF42DXA1+TXV | CPLC080C16MP13 | 22,200 | $1,110 |
| No | 205543240 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205543226 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205543213 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205543191 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205543180 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203096744 | COLEMAN | CH16B3622 | AVC48CX21+TXV | | 22,400 | $1,120 |
| No | 203096696 | COLEMAN | CH16B3622 | CM48DBCA1+ME14DN21 | | 22,000 | $1,100 |
| No | 205543155 | COLEMAN | CH16B3622 | CF48DXA1+ME14DN21+TXV | | 22,000 | $1,100 |
| No | 205543163 | COLEMAN | CH16B3622 | CM48DXA1+ME14DN21+TXV | | 22,000 | $1,100 |
| No | 203096664 | COLEMAN | CH16B3622 | CM36CBCA1+MVC16CN21 | | 22,000 | $1,100 |
| No | 205543148 | COLEMAN | CH16B3622 | CM36CXA1+MVC16CN21+TXV | | 22,000 | $1,100 |
| No | 205543138 | COLEMAN | CH16B3622 | CF36CXA1+MVC16CN21+TXV | | 22,000 | $1,100 |
| No | 203096648 | COLEMAN | CH16B3622 | CM42CBCA1+MVC16CN21 | | 21,800 | $1,090 |
| No | 205543130 | COLEMAN | CH16B3622 | CM42CXA1+MVC16CN21+TXV | | 21,800 | $1,090 |
| No | 203096640 | COLEMAN | CH16B3622 | CF42CBCA1+MVC16CN21 | | 21,800 | $1,090 |
| No | 205543119 | COLEMAN | CH16B3622 | CF42CXA1+MVC16CN21+TXV | | 21,800 | $1,090 |
| No | 205543103 | COLEMAN | CH16B3622 | CU36BXA1+TXV | TPLC060A12MP13 | 22,200 | $1,110 |
| No | 203096537 | COLEMAN | CH16B3622 | CM36BBCA1 | TPLC060A12MP13 | 22,200 | $1,110 |
| No | 205543084 | COLEMAN | CH16B3622 | CM36BXA1+TXV | TPLC060A12MP13 | 22,200 | $1,110 |
| No | 203096509 | COLEMAN | CH16B3622 | CF36BBCA1 | TPLC060A12MP13 | 22,200 | $1,110 |
| No | 205543074 | COLEMAN | CH16B3622 | CU36BXA1+TXV | TMLV060A12MP12 | 22,200 | $1,110 |
| No | 203096529 | COLEMAN | CH16B3622 | CM36BBCA1 | TMLV060A12MP12 | 22,200 | $1,110 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205543063 | COLEMAN | CH16B3622 | CM36BXA1+TXV | TMLV060A12MP12 | 22,200 | $1,110 |
| No | 203096500 | COLEMAN | CH16B3622 | CF36BBCA1 | TMLV060A12MP12 | 22,200 | $1,110 |
| No | 205543048 | COLEMAN | CH16B3622 | CU36BXA1+TXV | TM8V060A12MP12 | 22,200 | $1,110 |
| No | 203096520 | COLEMAN | CH16B3622 | CM36BBCA1 | TM8V060A12MP12 | 22,200 | $1,110 |
| No | 205543035 | COLEMAN | CH16B3622 | CM36BXA1+TXV | TM8V060A12MP12 | 22,200 | $1,110 |
| No | 203096492 | COLEMAN | CH16B3622 | CF36BBCA1 | TM8V060A12MP12 | 22,200 | $1,110 |
| No | 205542996 | COLEMAN | CH16B3622 | CF36BXA1+TXV | TPLC060A12MP13 | 22,200 | $1,110 |
| No | 205542973 | COLEMAN | CH16B3622 | CF36BXA1+TXV | TM8V060A12MP12 | 22,200 | $1,110 |
| No | 205542985 | COLEMAN | CH16B3622 | CF36BXA1+TXV | TMLV060A12MP12 | 22,200 | $1,110 |
| No | 206781023 | COLEMAN | CH16B3622 | CU36BXA1+TXV | CP9C060B12MP13 | 22,400 | $1,120 |
| No | 206781021 | COLEMAN | CH16B3622 | CM36BXA1+TXV | CP9C060B12MP13 | 22,400 | $1,120 |
| No | 203096137 | COLEMAN | CH16B3622 | CF36BBCA1 | CP9C060B12MP13 | 22,400 | $1,120 |
| No | 203096157 | COLEMAN | CH16B3622 | CM36BBCA1 | CP9C060B12MP13 | 22,400 | $1,120 |
| No | 206781017 | COLEMAN | CH16B3622 | CU36BXA1+TXV | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 203096149 | COLEMAN | CH16B3622 | CM36BBCA1 | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 206781013 | COLEMAN | CH16B3622 | CM36BXA1+TXV | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 206781009 | COLEMAN | CH16B3622 | CU36BXA1+TXV | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 203096141 | COLEMAN | CH16B3622 | CM36BBCA1 | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 203096129 | COLEMAN | CH16B3622 | CF36BBCA1 | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 206781005 | COLEMAN | CH16B3622 | CM36BXA1+TXV | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 203096122 | COLEMAN | CH16B3622 | CF36BBCA1 | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 206781003 | COLEMAN | CH16B3622 | CF36BXA1+TXV | CP9C060B12MP13 | 22,400 | $1,120 |
| No | 206780999 | COLEMAN | CH16B3622 | CF36BXA1+TXV | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 206780995 | COLEMAN | CH16B3622 | CF36BXA1+TXV | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 205542968 | COLEMAN | CH16B3622 | CF42BXA1+TXV | CP9C060B12MP13 | 22,400 | $1,120 |
| No | 205542958 | COLEMAN | CH16B3622 | CF42BXA1+TXV | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 205542948 | COLEMAN | CH16B3622 | CF42BXA1+TXV | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 203095803 | COLEMAN | CH16B3622 | CM48DBCA1 | CP9C080C16MP13 | 22,000 | $1,100 |
| No | 205543098 | COLEMAN | CH16B3622 | CU48DXA1+TXV | CP9C080C16MP13 | 22,000 | $1,100 |
| No | 203095795 | COLEMAN | CH16B3622 | CM48DBCA1 | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 205543093 | COLEMAN | CH16B3622 | CM48DXA1+TXV | CP9C080C16MP13 | 22,000 | $1,100 |
| No | 205543022 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 205543011 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 203095787 | COLEMAN | CH16B3622 | CM48DBCA1 | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 205542936 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 205542913 | COLEMAN | CH16B3622 | CF48DXA1+TXV | CP9C080C16MP13 | 22,000 | $1,100 |
| No | 205542921 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 205542902 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205542891 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 203095759 | COLEMAN | CH16B3622 | AVC36BX21+TXV | | 22,200 | $1,110 |
| No | 203095751 | COLEMAN | CH16B3622 | AVC36CX21+TXV | | 22,200 | $1,110 |
| No | 203095736 | COLEMAN | CH16B3622 | AVC48DX21+TXV | | 22,200 | $1,110 |
| No | 205542884 | COLEMAN | CH16B3622 | CU42CXA1+TXV | CPLC100C16MP13 | 22,200 | $1,110 |
| No | 203095341 | COLEMAN | CH16B3622 | CM42CBCA1 | CPLC100C16MP13 | 22,200 | $1,110 |
| No | 205542879 | COLEMAN | CH16B3622 | CM42CXA1+TXV | CPLC100C16MP13 | 22,200 | $1,110 |
| No | 203095284 | COLEMAN | CH16B3622 | CF42CBCA1 | CPLC100C16MP13 | 22,200 | $1,110 |
| No | 205542875 | COLEMAN | CH16B3622 | CU42CXA1+TXV | CPLC080C16MP13 | 22,200 | $1,110 |
| No | 203095337 | COLEMAN | CH16B3622 | CM42CBCA1 | CPLC080C16MP13 | 22,200 | $1,110 |
| No | 205542869 | COLEMAN | CH16B3622 | CM42CXA1+TXV | CPLC080C16MP13 | 22,200 | $1,110 |
| No | 203095280 | COLEMAN | CH16B3622 | CF42CBCA1 | CPLC080C16MP13 | 22,200 | $1,110 |
| No | 205542861 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203095329 | COLEMAN | CH16B3622 | CM42CBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205542852 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203095273 | COLEMAN | CH16B3622 | CF42CBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205542844 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 203095320 | COLEMAN | CH16B3622 | CM42CBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205542834 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 203095265 | COLEMAN | CH16B3622 | CF42CBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205542824 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203095312 | COLEMAN | CH16B3622 | CM42CBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205542814 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203095257 | COLEMAN | CH16B3622 | CF42CBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205542779 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203095296 | COLEMAN | CH16B3622 | CM42CBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205542764 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203095241 | COLEMAN | CH16B3622 | CF42CBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205542754 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203095288 | COLEMAN | CH16B3622 | CM42CBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205542743 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203095233 | COLEMAN | CH16B3622 | CF42CBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205542739 | COLEMAN | CH16B3622 | CF42CXA1+TXV | CPLC100C16MP13 | 22,200 | $1,110 |
| No | 205542734 | COLEMAN | CH16B3622 | CF42CXA1+TXV | CPLC080C16MP13 | 22,200 | $1,110 |
| No | 205542724 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205542709 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205542693 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205542665 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205542651 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 206780993 | COLEMAN | CH16B3622 | CU48CXA1+TXV | CPLC100C16MP13 | 22,200 | $1,110 |
| No | 203095006 | COLEMAN | CH16B3622 | CM48CBCA1 | CPLC100C16MP13 | 22,200 | $1,110 |
| No | 206780991 | COLEMAN | CH16B3622 | CM48CXA1+TXV | CPLC100C16MP13 | 22,200 | $1,110 |
| No | 203094949 | COLEMAN | CH16B3622 | CF48CBCA1 | CPLC100C16MP13 | 22,200 | $1,110 |
| No | 203095002 | COLEMAN | CH16B3622 | CM48CBCA1 | CPLC080C16MP13 | 22,200 | $1,110 |
| No | 206780989 | COLEMAN | CH16B3622 | CU48CXA1+TXV | CPLC080C16MP13 | 22,200 | $1,110 |
| No | 203094945 | COLEMAN | CH16B3622 | CF48CBCA1 | CPLC080C16MP13 | 22,200 | $1,110 |
| No | 206780983 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 206780987 | COLEMAN | CH16B3622 | CM48CXA1+TXV | CPLC080C16MP13 | 22,200 | $1,110 |
| No | 203094993 | COLEMAN | CH16B3622 | CM48CBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 206780979 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203094938 | COLEMAN | CH16B3622 | CF48CBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 206780975 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 203094985 | COLEMAN | CH16B3622 | CM48CBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 206780971 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 203094930 | COLEMAN | CH16B3622 | CF48CBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 206780967 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203094977 | COLEMAN | CH16B3622 | CM48CBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 206780963 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203094921 | COLEMAN | CH16B3622 | CF48CBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 206780959 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203094961 | COLEMAN | CH16B3622 | CM48CBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 206780955 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203094906 | COLEMAN | CH16B3622 | CF48CBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 206780951 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203094953 | COLEMAN | CH16B3622 | CM48CBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203094898 | COLEMAN | CH16B3622 | CF48CBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 206780941 | COLEMAN | CH16B3622 | CF48CXA1+TXV | CPLC100C16MP13 | 22,200 | $1,110 |
| No | 206780939 | COLEMAN | CH16B3622 | CF48CXA1+TXV | CPLC080C16MP13 | 22,200 | $1,110 |
| No | 206780947 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 206780935 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 206780931 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 206780927 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 206780919 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 206780917 | COLEMAN | CH16B3622 | CU48CXA1+TXV | CPLC120C20MP13 | 22,200 | $1,110 |
| No | 203093771 | COLEMAN | CH16B3622 | CM48CBCA1 | CPLC120C20MP13 | 22,200 | $1,110 |
| No | 206780923 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780945 | COLEMAN | CH16B3622 | CM48CXA1+TXV | CPLC120C20MP13 | 22,200 | $1,110 |
| No | 203093714 | COLEMAN | CH16B3622 | CF48CBCA1 | CPLC120C20MP13 | 22,200 | $1,110 |
| No | 206780913 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TPLC120C20MP13 | 22,200 | $1,110 |
| No | 203093759 | COLEMAN | CH16B3622 | CM48CBCA1 | TPLC120C20MP13 | 22,200 | $1,110 |
| No | 206780909 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TPLC120C20MP13 | 22,200 | $1,110 |
| No | 203093703 | COLEMAN | CH16B3622 | CF48CBCA1 | TPLC120C20MP13 | 22,200 | $1,110 |
| No | 206780905 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TPLC100C20MP13 | 22,200 | $1,110 |
| No | 203093751 | COLEMAN | CH16B3622 | CM48CBCA1 | TPLC100C20MP13 | 22,200 | $1,110 |
| No | 206780901 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TPLC100C20MP13 | 22,200 | $1,110 |
| No | 203093694 | COLEMAN | CH16B3622 | CF48CBCA1 | TPLC100C20MP13 | 22,200 | $1,110 |
| No | 206780897 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TMLV120C20MP12 | 22,200 | $1,110 |
| No | 203093743 | COLEMAN | CH16B3622 | CM48CBCA1 | TMLV120C20MP12 | 22,200 | $1,110 |
| No | 206780893 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TMLV120C20MP12 | 22,200 | $1,110 |
| No | 203093686 | COLEMAN | CH16B3622 | CF48CBCA1 | TMLV120C20MP12 | 22,200 | $1,110 |
| No | 206780889 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TM8V100C20MP12 | 22,200 | $1,110 |
| No | 203093727 | COLEMAN | CH16B3622 | CM48CBCA1 | TM8V100C20MP12 | 22,200 | $1,110 |
| No | 206780885 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TM8V100C20MP12 | 22,200 | $1,110 |
| No | 203093670 | COLEMAN | CH16B3622 | CF48CBCA1 | TM8V100C20MP12 | 22,200 | $1,110 |
| No | 206780881 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TM8V120C20MP12 | 22,200 | $1,110 |
| No | 203093718 | COLEMAN | CH16B3622 | CM48CBCA1 | TM8V120C20MP12 | 22,200 | $1,110 |
| No | 206780877 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TM8V120C20MP12 | 22,200 | $1,110 |
| No | 203093662 | COLEMAN | CH16B3622 | CF48CBCA1 | TM8V120C20MP12 | 22,200 | $1,110 |
| No | 206780875 | COLEMAN | CH16B3622 | CF48CXA1+TXV | CPLC120C20MP13 | 22,200 | $1,110 |
| No | 206780870 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TPLC120C20MP13 | 22,200 | $1,110 |
| No | 206780862 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TMLV120C20MP12 | 22,200 | $1,110 |
| No | 206780858 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TM8V100C20MP12 | 22,200 | $1,110 |
| No | 206780866 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TPLC100C20MP13 | 22,200 | $1,110 |
| No | 203093386 | COLEMAN | CH16B3622 | CM48DBCA1 | CPLC120C20MP13 | 22,400 | $1,120 |
| No | 206780854 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TM8V120C20MP12 | 22,200 | $1,110 |
| No | 205542641 | COLEMAN | CH16B3622 | CU48DXA1+TXV | CPLC120C20MP13 | 22,400 | $1,120 |
| No | 205542635 | COLEMAN | CH16B3622 | CM48DXA1+TXV | CPLC120C20MP13 | 22,400 | $1,120 |
| No | 203093360 | COLEMAN | CH16B3622 | CM48DBCA1 | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205542601 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205542585 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 203093341 | COLEMAN | CH16B3622 | CM48DBCA1 | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205542574 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205542558 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 203093322 | COLEMAN | CH16B3622 | CM48DBCA1 | TMLV120C20MP12 | 22,400 | $1,120 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205542541 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205542528 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 203093286 | COLEMAN | CH16B3622 | CM48DBCA1 | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205542493 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205542483 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 203093269 | COLEMAN | CH16B3622 | CM48DBCA1 | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205542294 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205542282 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205542275 | COLEMAN | CH16B3622 | CF48DXA1+TXV | CPLC120C20MP13 | 22,400 | $1,120 |
| No | 205542254 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205542245 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205542232 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205542216 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205542209 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205542196 | COLEMAN | CH16B3622 | CM36AXA1+TXV | TM8Y060A12MP11 | 22,200 | $1,110 |
| No | 205542127 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205542160 | COLEMAN | CH16B3622 | CF36AXA1+TXV | TM8Y060A12MP11 | 22,200 | $1,110 |
| No | 203092888 | COLEMAN | CH16B3622 | CM36CBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205542472 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205542461 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203092872 | COLEMAN | CH16B3622 | CM36CBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205542449 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205542111 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205542103 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205542053 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 203092217 | COLEMAN | CH16B3622 | CM48CBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205542307 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 203092112 | COLEMAN | CH16B3622 | CF48CBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205542042 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203092199 | COLEMAN | CH16B3622 | CM48CBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205542032 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203092093 | COLEMAN | CH16B3622 | CF48CBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205541943 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205541932 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203091902 | COLEMAN | CH16B3622 | CM48DBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205541876 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205541864 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 203091883 | COLEMAN | CH16B3622 | CM48DBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205541854 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205541670 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205541842 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205541661 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 206780846 | COLEMAN | CH16B3622 | CU36BXA1+TXV | TM9Y080B12MP11 | 22,200 | $1,110 |
| No | 203808677 | COLEMAN | CH16B3622 | CM36BBCA1 | TM9Y080B12MP11 | 22,200 | $1,110 |
| No | 206780850 | COLEMAN | CH16B3622 | CM36BXA1+TXV | TM9Y080B12MP11 | 22,200 | $1,110 |
| No | 203808671 | COLEMAN | CH16B3622 | CF36BBCA1 | TM9Y080B12MP11 | 22,200 | $1,110 |
| No | 206780842 | COLEMAN | CH16B3622 | CF36BXA1+TXV | TM9Y080B12MP11 | 22,200 | $1,110 |
| No | 205541601 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205541590 | COLEMAN | CH16B3622 | CM42CBCA1 | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205541579 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205541567 | COLEMAN | CH16B3622 | CF42CBCA1 | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205541755 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205541737 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205541717 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 206780806 | COLEMAN | CH16B3622 | CU36BXA1+TXV | CP9C080B12MP13 | 22,200 | $1,110 |
| No | 203091045 | COLEMAN | CH16B3622 | CM36BBCA1 | CP9C080B12MP13 | 22,200 | $1,110 |
| No | 206780840 | COLEMAN | CH16B3622 | CM36BXA1+TXV | CP9C080B12MP13 | 22,200 | $1,110 |
| No | 203090999 | COLEMAN | CH16B3622 | CF36BBCA1 | CP9C080B12MP13 | 22,200 | $1,110 |
| No | 206780836 | COLEMAN | CH16B3622 | CU36BXA1+TXV | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 203091026 | COLEMAN | CH16B3622 | CM36BBCA1 | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 206780802 | COLEMAN | CH16B3622 | CM36BXA1+TXV | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 203090978 | COLEMAN | CH16B3622 | CF36BBCA1 | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 206780798 | COLEMAN | CH16B3622 | CU36BXA1+TXV | TM9V080B12MP12 | 22,200 | $1,110 |
| No | 203091008 | COLEMAN | CH16B3622 | CM36BBCA1 | TM9V080B12MP12 | 22,200 | $1,110 |
| No | 206780794 | COLEMAN | CH16B3622 | CM36BXA1+TXV | TM9V080B12MP12 | 22,200 | $1,110 |
| No | 203090964 | COLEMAN | CH16B3622 | CF36BBCA1 | TM9V080B12MP12 | 22,200 | $1,110 |
| No | 206780792 | COLEMAN | CH16B3622 | CF36BXA1+TXV | CP9C080B12MP13 | 22,200 | $1,110 |
| No | 206780788 | COLEMAN | CH16B3622 | CF36BXA1+TXV | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 206780784 | COLEMAN | CH16B3622 | CF36BXA1+TXV | TM9V080B12MP12 | 22,200 | $1,110 |
| No | 205541702 | COLEMAN | CH16B3622 | CU36CXA1+TXV | CP9C100C16MP13 | 22,000 | $1,100 |
| No | 203090637 | COLEMAN | CH16B3622 | CM36CBCA1 | CP9C100C16MP13 | 22,000 | $1,100 |
| No | 205541550 | COLEMAN | CH16B3622 | CM36CXA1+TXV | CP9C100C16MP13 | 22,000 | $1,100 |
| No | 205541538 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TP9C100C16MP13 | 22,000 | $1,100 |
| No | 203090616 | COLEMAN | CH16B3622 | CM36CBCA1 | TP9C100C16MP13 | 22,000 | $1,100 |
| No | 205541527 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TP9C100C16MP13 | 22,000 | $1,100 |
| No | 205541516 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TM9V100C16MP12 | 22,000 | $1,100 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203090600 | COLEMAN | CH16B3622 | CM36CBCA1 | TM9V100C16MP12 | 22,000 | $1,100 |
| No | 205541504 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TM9V100C16MP12 | 22,000 | $1,100 |
| No | 205541497 | COLEMAN | CH16B3622 | CF36CXA1+TXV | CP9C100C16MP13 | 22,000 | $1,100 |
| No | 205541486 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TP9C100C16MP13 | 22,000 | $1,100 |
| No | 205541474 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TM9V100C16MP12 | 22,000 | $1,100 |
| No | 205541468 | COLEMAN | CH16B3622 | CU42CXA1+TXV | CP9C100C16MP13 | 21,800 | $1,090 |
| No | 203090408 | COLEMAN | CH16B3622 | CM42CBCA1 | CP9C100C16MP13 | 21,800 | $1,090 |
| No | 205541463 | COLEMAN | CH16B3622 | CM42CXA1+TXV | CP9C100C16MP13 | 21,800 | $1,090 |
| No | 203090365 | COLEMAN | CH16B3622 | CF42CBCA1 | CP9C100C16MP13 | 21,800 | $1,090 |
| No | 205541450 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 203090391 | COLEMAN | CH16B3622 | CM42CBCA1 | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205541438 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 203090346 | COLEMAN | CH16B3622 | CF42CBCA1 | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205541426 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 203090374 | COLEMAN | CH16B3622 | CM42CBCA1 | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205541415 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205541409 | COLEMAN | CH16B3622 | CF42CXA1+TXV | CP9C100C16MP13 | 21,800 | $1,090 |
| No | 203090328 | COLEMAN | CH16B3622 | CF42CBCA1 | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205541397 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205541386 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205541380 | COLEMAN | CH16B3622 | CM42DXA1+TXV | CP9C100C16MP13 | 21,800 | $1,090 |
| No | 205541368 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205541357 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205541351 | COLEMAN | CH16B3622 | CF42DXA1+TXV | CP9C100C16MP13 | 21,800 | $1,090 |
| No | 205541340 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205541330 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205541325 | COLEMAN | CH16B3622 | CM42DXA1+TXV | CP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541316 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541301 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205541293 | COLEMAN | CH16B3622 | CF42DXA1+TXV | CP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541283 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541271 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205541267 | COLEMAN | CH16B3622 | CU48CXA1+TXV | CP9C100C20MP13 | 22,400 | $1,120 |
| No | 203089087 | COLEMAN | CH16B3622 | CM48CBCA1 | CP9C100C20MP13 | 22,400 | $1,120 |
| No | 203089040 | COLEMAN | CH16B3622 | CF48CBCA1 | CP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541262 | COLEMAN | CH16B3622 | CM48CXA1+TXV | CP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541251 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 203089068 | COLEMAN | CH16B3622 | CM48CBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205541240 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 203089021 | COLEMAN | CH16B3622 | CF48CBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541229 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203089050 | COLEMAN | CH16B3622 | CM48CBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205541218 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203089004 | COLEMAN | CH16B3622 | CF48CBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205541213 | COLEMAN | CH16B3622 | CF48CXA1+TXV | CP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541202 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541191 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203088857 | COLEMAN | CH16B3622 | CM48DBCA1 | CP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541184 | COLEMAN | CH16B3622 | CU48DXA1+TXV | CP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541176 | COLEMAN | CH16B3622 | CM48DXA1+TXV | CP9C100C20MP13 | 22,400 | $1,120 |
| No | 203088838 | COLEMAN | CH16B3622 | CM48DBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541163 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541150 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 203088819 | COLEMAN | CH16B3622 | CM48DBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205541124 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205541111 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205541105 | COLEMAN | CH16B3622 | CF48DXA1+TXV | CP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541089 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541075 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205144699 | COLEMAN | CH16B3622 | AE42CBC21 | | 22,400 | $1,120 |
| No | 203088397 | COLEMAN | CH16B3622 | AE42CX21+TXV | | 22,400 | $1,120 |
| No | 205537134 | COLEMAN | CH16B2421 | CU24AXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |
| No | 205537126 | COLEMAN | CH16B2421 | CM24ABAA1 | TL8E060A12UH11 | 15,200 | $760 |
| No | 205537120 | COLEMAN | CH16B2421 | CM24AXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |
| No | 205537112 | COLEMAN | CH16B2421 | CF24ABAA1 | TL8E060A12UH11 | 15,200 | $760 |
| No | 205537105 | COLEMAN | CH16B2421 | CF24AXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |
| No | 206782443 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 206782435 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 206782439 | COLEMAN | CH16B4821 | CM48CBCA1 | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 206782431 | COLEMAN | CH16B4821 | CF48CBCA1 | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 206782427 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 205085344 | COLEMAN | CH16B4821 | CU60CXA2+TXV | TL8E080C16UH11 | 27,800 | $1,390 |
| No | 205085338 | COLEMAN | CH16B4821 | CM60CXA2+TXV | TL8E080C16UH11 | 27,800 | $1,390 |
| No | 205085332 | COLEMAN | CH16B4821 | CF60CXA2+TXV | TL8E080C16UH11 | 27,800 | $1,390 |
| No | 206782467 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TL8E080C16UH11 | 29,600 | $1,480 |
| No | 206782471 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TL8E080C16UH11 | 29,600 | $1,480 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205085310 | COLEMAN | CH16B4821 | CU60CXA2+TXV | TL8E100C20UH11 | 27,600 | $1,380 |
| No | 205085304 | COLEMAN | CH16B4821 | CM60CXA2+TXV | TL8E100C20UH11 | 27,600 | $1,380 |
| No | 205085298 | COLEMAN | CH16B4821 | CF60CXA2+TXV | TL8E100C20UH11 | 27,600 | $1,380 |
| No | 205085291 | COLEMAN | CH16B4821 | CU60DXA2+TXV | TL8E100C20UH11 | 27,800 | $1,390 |
| No | 205085285 | COLEMAN | CH16B4821 | CM60DXA2+TXV | TL8E100C20UH11 | 27,800 | $1,390 |
| No | 205085279 | COLEMAN | CH16B4821 | CF60DXA2+TXV | TL8E100C20UH11 | 27,800 | $1,390 |
| No | 205537096 | COLEMAN | CH16B4821 | CM48DBCA1 | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205537087 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205537078 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205537069 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205537059 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TL9E080C16UH11 | 29,600 | $1,480 |
| No | 205537052 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TL9E080C16UH11 | 29,600 | $1,480 |
| No | 205085243 | COLEMAN | CH16B4821 | CU60CXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205085237 | COLEMAN | CH16B4821 | CM60CXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205085232 | COLEMAN | CH16B4821 | CF60CXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205085226 | COLEMAN | CH16B4821 | CU60DXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205085221 | COLEMAN | CH16B4821 | CM60DXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205085215 | COLEMAN | CH16B4821 | CF60DXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205085144 | COLEMAN | CH16B4821 | CU60CXA2+TXV | TMLE080C20MP11 | 27,400 | $1,370 |
| No | 205085138 | COLEMAN | CH16B4821 | CM60CXA2+TXV | TMLE080C20MP11 | 27,400 | $1,370 |
| No | 205085132 | COLEMAN | CH16B4821 | CU60CXA2+TXV | TM8E080C20MP11 | 27,400 | $1,370 |
| No | 205085126 | COLEMAN | CH16B4821 | CM60CXA2+TXV | TM8E080C20MP11 | 27,400 | $1,370 |
| No | 205085122 | COLEMAN | CH16B4821 | CF60CXA2+TXV | TMLE080C20MP11 | 27,400 | $1,370 |
| No | 205085116 | COLEMAN | CH16B4821 | CF60CXA2+TXV | TM8E080C20MP11 | 27,400 | $1,370 |
| No | 205085111 | COLEMAN | CH16B4821 | CU60DXA2+TXV | TMLE080C20MP11 | 27,600 | $1,380 |
| No | 205085106 | COLEMAN | CH16B4821 | CM60DXA2+TXV | TMLE080C20MP11 | 27,600 | $1,380 |
| No | 205085100 | COLEMAN | CH16B4821 | CU60DXA2+TXV | TM8E080C20MP11 | 27,600 | $1,380 |
| No | 205085095 | COLEMAN | CH16B4821 | CM60DXA2+TXV | TM8E080C20MP11 | 27,600 | $1,380 |
| No | 205085089 | COLEMAN | CH16B4821 | CF60DXA2+TXV | TMLE080C20MP11 | 27,600 | $1,380 |
| No | 205085083 | COLEMAN | CH16B4821 | CF60DXA2+TXV | TM8E080C20MP11 | 27,600 | $1,380 |
| No | 206782423 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 203431137 | COLEMAN | CH16B4821 | CM48CBCA1 | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 206782419 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 203431126 | COLEMAN | CH16B4821 | CF48CBCA1 | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 206782415 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 203431131 | COLEMAN | CH16B4821 | CM48CBCA1 | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 206782411 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 203431120 | COLEMAN | CH16B4821 | CF48CBCA1 | TM8E120C16MP11 | 28,000 | $1,400 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782403 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 205084912 | COLEMAN | CH16B4821 | CU60DXA2+TXV | TMLE120C16MP11 | 27,800 | $1,390 |
| No | 206782407 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 205084906 | COLEMAN | CH16B4821 | CM60DXA2+TXV | TMLE120C16MP11 | 27,800 | $1,390 |
| No | 205084901 | COLEMAN | CH16B4821 | CU60DXA2+TXV | TM8E120C16MP11 | 27,800 | $1,390 |
| No | 205084896 | COLEMAN | CH16B4821 | CM60DXA2+TXV | TM8E120C16MP11 | 27,800 | $1,390 |
| No | 205084885 | COLEMAN | CH16B4821 | CF60DXA2+TXV | TM8E120C16MP11 | 27,800 | $1,390 |
| No | 206782399 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TMLE120C16MP11 | 30,400 | $1,520 |
| No | 205084890 | COLEMAN | CH16B4821 | CF60DXA2+TXV | TMLE120C16MP11 | 27,800 | $1,390 |
| No | 206782395 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TM8E120C16MP11 | 30,400 | $1,520 |
| No | 206782391 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TMLE120C16MP11 | 30,400 | $1,520 |
| No | 206782387 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TM8E120C16MP11 | 30,400 | $1,520 |
| No | 205084811 | COLEMAN | CH16B4821 | CU60DXA2+TXV | TMLE130D20MP11 | 27,800 | $1,390 |
| No | 205084805 | COLEMAN | CH16B4821 | CM60DXA2+TXV | TMLE130D20MP11 | 27,800 | $1,390 |
| No | 205084793 | COLEMAN | CH16B4821 | CM60DXA2+TXV | TM8E130D20MP11 | 27,800 | $1,390 |
| No | 205084800 | COLEMAN | CH16B4821 | CU60DXA2+TXV | TM8E130D20MP11 | 27,800 | $1,390 |
| No | 205084788 | COLEMAN | CH16B4821 | CF60DXA2+TXV | TMLE130D20MP11 | 27,800 | $1,390 |
| No | 205084782 | COLEMAN | CH16B4821 | CF60DXA2+TXV | TM8E130D20MP11 | 27,800 | $1,390 |
| No | 205536884 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TM9E080B12MP12 | 28,600 | $1,430 |
| No | 205536875 | COLEMAN | CH16B4821 | CM48CBCA1 | TM9E080B12MP12 | 28,600 | $1,430 |
| No | 205536867 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TM9E080B12MP12 | 28,600 | $1,430 |
| No | 205536859 | COLEMAN | CH16B4821 | CF48CBCA1 | TM9E080B12MP12 | 28,600 | $1,430 |
| No | 205536849 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TM9E080B12MP12 | 28,600 | $1,430 |
| No | 206782383 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 206782379 | COLEMAN | CH16B4821 | CM48CBCA1 | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 206782375 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 206782371 | COLEMAN | CH16B4821 | CF48CBCA1 | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 206782367 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 205536838 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TM9E080C16MP12 | 28,800 | $1,440 |
| No | 205536831 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TM9E080C16MP12 | 28,800 | $1,440 |
| No | 205536822 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205536815 | COLEMAN | CH16B4821 | CM48CBCA1 | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205536807 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205536798 | COLEMAN | CH16B4821 | CF48CBCA1 | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205536790 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205084673 | COLEMAN | CH16B4821 | CU60DXA2+TXV | TM9E100C20MP12 | 27,400 | $1,370 |
| No | 205084669 | COLEMAN | CH16B4821 | CM60DXA2+TXV | TM9E100C20MP12 | 27,400 | $1,370 |
| No | 205084664 | COLEMAN | CH16B4821 | CF60DXA2+TXV | TM9E100C20MP12 | 27,400 | $1,370 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205084660 | COLEMAN | CH16B4821 | CU60DXA2+TXV | TM9E120D20MP12 | 27,800 | $1,390 |
| No | 205084656 | COLEMAN | CH16B4821 | CM60DXA2+TXV | TM9E120D20MP12 | 27,800 | $1,390 |
| No | 205084651 | COLEMAN | CH16B4821 | CF60DXA2+TXV | TM9E120D20MP12 | 27,800 | $1,390 |
| No | 206783054 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TL8E080C16UH11 | 33,000 | $1,650 |
| No | 206783050 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TL8E080C16UH11 | 33,000 | $1,650 |
| No | 205536780 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TL9E080C16UH11 | 32,600 | $1,630 |
| No | 205536771 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TL9E080C16UH11 | 32,600 | $1,630 |
| No | 206783042 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TMLE080C16MP11 | 33,000 | $1,650 |
| No | 206783038 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TM8E080C16MP11 | 33,000 | $1,650 |
| No | 206783034 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TMLE080C16MP11 | 33,000 | $1,650 |
| No | 206783030 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TM8E080C16MP11 | 33,000 | $1,650 |
| No | 206783026 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TMLE100C16MP11 | 33,000 | $1,650 |
| No | 206783022 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TM8E100C16MP11 | 33,000 | $1,650 |
| No | 206783018 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TMLE100C16MP11 | 33,000 | $1,650 |
| No | 206783014 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TM8E100C16MP11 | 33,000 | $1,650 |
| No | 206783010 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TMLE100C20MP11 | 32,600 | $1,630 |
| No | 206783006 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TM8E100C20MP11 | 32,600 | $1,630 |
| No | 206783002 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TMLE100C20MP11 | 32,600 | $1,630 |
| No | 206782998 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TM8E100C20MP11 | 32,600 | $1,630 |
| No | 206782978 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TMLE120C20MP11 | 32,600 | $1,630 |
| No | 206782974 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TM8E120C20MP11 | 32,600 | $1,630 |
| No | 206782970 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TMLE120C20MP11 | 32,600 | $1,630 |
| No | 206782966 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TM8E120C20MP11 | 32,600 | $1,630 |
| No | 205536762 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TMLE130D20MP11 | 32,800 | $1,640 |
| No | 205536754 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TM8E130D20MP11 | 32,800 | $1,640 |
| No | 205536745 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TMLE130D20MP11 | 32,800 | $1,640 |
| No | 205536737 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TM8E130D20MP11 | 32,800 | $1,640 |
| No | 206779793 | COLEMAN | CH16B2421 | CM24BBAA1+MVC12BN21 | | 14,900 | $745 |
| No | 206779789 | COLEMAN | CH16B2421 | CM24BXA1+MVC12BN21+TXV | | 14,900 | $745 |
| No | 202101788 | COLEMAN | CH16B2421 | CF24BBAA1+MVC12BN21 | | 14,900 | $745 |
| No | 206779785 | COLEMAN | CH16B2421 | CF24BXA1+MVC12BN21+TXV | | 14,900 | $745 |
| No | 206780119 | COLEMAN | CH16B2421 | CM30BBAA1+MVC12BN21 | | 15,300 | $765 |
| No | 206780115 | COLEMAN | CH16B2421 | CM30BXA1+MVC12BN21+TXV | | 15,300 | $765 |
| No | 206780107 | COLEMAN | CH16B2421 | CF30BXA1+MVC12BN21+TXV | | 15,300 | $765 |
| No | 206780111 | COLEMAN | CH16B2421 | CF30BBAA1+MVC12BN21 | | 15,300 | $765 |
| No | 206779801 | COLEMAN | CH16B2421 | CM30CXA1+MVC16CN21+TXV | | 14,800 | $740 |
| No | 206779797 | COLEMAN | CH16B2421 | CF30CXA1+MVC16CN21+TXV | | 14,800 | $740 |
| No | 206780087 | COLEMAN | CH16B2421 | CM36CXA1+MVC16CN21+TXV | | 15,300 | $765 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780083 | COLEMAN | CH16B2421 | CF36CXA1+MVC16CN21+TXV | | 15,300 | $765 |
| No | 206779753 | COLEMAN | CH16B2421 | CU24AXA1+TXV | TPLC060A12MP13 | 15,000 | $750 |
| No | 206779749 | COLEMAN | CH16B2421 | CM24ABAA1 | TPLC060A12MP13 | 15,000 | $750 |
| No | 206779745 | COLEMAN | CH16B2421 | CM24AXA1+TXV | TPLC060A12MP13 | 15,000 | $750 |
| No | 202102011 | COLEMAN | CH16B2421 | CF24ABAA1 | TPLC060A12MP13 | 15,000 | $750 |
| No | 206779765 | COLEMAN | CH16B2421 | CU24AXA1+TXV | TMLV060A12MP12 | 15,000 | $750 |
| No | 206779761 | COLEMAN | CH16B2421 | CM24ABAA1 | TMLV060A12MP12 | 15,000 | $750 |
| No | 206779757 | COLEMAN | CH16B2421 | CM24AXA1+TXV | TMLV060A12MP12 | 15,000 | $750 |
| No | 202102009 | COLEMAN | CH16B2421 | CF24ABAA1 | TMLV060A12MP12 | 15,000 | $750 |
| No | 206779741 | COLEMAN | CH16B2421 | CU24AXA1+TXV | TM8V060A12MP12 | 15,000 | $750 |
| No | 206779737 | COLEMAN | CH16B2421 | CM24ABAA1 | TM8V060A12MP12 | 15,000 | $750 |
| No | 202102003 | COLEMAN | CH16B2421 | CF24ABAA1 | TM8V060A12MP12 | 15,000 | $750 |
| No | 206779733 | COLEMAN | CH16B2421 | CM24AXA1+TXV | TM8V060A12MP12 | 15,000 | $750 |
| No | 206779725 | COLEMAN | CH16B2421 | CF24AXA1+TXV | TMLV060A12MP12 | 15,000 | $750 |
| No | 206779729 | COLEMAN | CH16B2421 | CF24AXA1+TXV | TPLC060A12MP13 | 15,000 | $750 |
| No | 206779721 | COLEMAN | CH16B2421 | CF24AXA1+TXV | TM8V060A12MP12 | 15,000 | $750 |
| No | 206780641 | COLEMAN | CH16B2421 | CU30BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780637 | COLEMAN | CH16B2421 | CM30BBAA1 | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780633 | COLEMAN | CH16B2421 | CM30BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780629 | COLEMAN | CH16B2421 | CF30BBAA1 | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780625 | COLEMAN | CH16B2421 | CU30BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780621 | COLEMAN | CH16B2421 | CM30BBAA1 | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780617 | COLEMAN | CH16B2421 | CM30BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780613 | COLEMAN | CH16B2421 | CF30BBAA1 | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780604 | COLEMAN | CH16B2421 | CF30BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780608 | COLEMAN | CH16B2421 | CF30BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780167 | COLEMAN | CH16B2421 | CU24BXA1+TXV | TM9Y060B12MP11 | 14,900 | $745 |
| No | 206780159 | COLEMAN | CH16B2421 | CM24BXA1+TXV | TM9Y060B12MP11 | 14,900 | $745 |
| No | 206780163 | COLEMAN | CH16B2421 | CM24BBAA1 | TM9Y060B12MP11 | 14,900 | $745 |
| No | 202143773 | COLEMAN | CH16B2421 | CF24BBAA1 | TM9Y060B12MP11 | 14,900 | $745 |
| No | 206780175 | COLEMAN | CH16B2421 | CF24BXA1+TXV | TM9Y060B12MP11 | 14,900 | $745 |
| No | 206780155 | COLEMAN | CH16B2421 | CU24AXA1+TXV | TM9V040A10MP12 | 15,200 | $760 |
| No | 206780151 | COLEMAN | CH16B2421 | CM24ABAA1 | TM9V040A10MP12 | 15,200 | $760 |
| No | 206780147 | COLEMAN | CH16B2421 | CM24AXA1+TXV | TM9V040A10MP12 | 15,200 | $760 |
| No | 202143765 | COLEMAN | CH16B2421 | CF24ABAA1 | TM9V040A10MP12 | 15,200 | $760 |
| No | 206780171 | COLEMAN | CH16B2421 | CF24AXA1+TXV | TM9V040A10MP12 | 15,200 | $760 |
| No | 206779991 | COLEMAN | CH16B2421 | CU36BXA1+TXV | CP9C060B12MP13 | 14,900 | $745 |
| No | 206779989 | COLEMAN | CH16B2421 | CM36BBAA1 | CP9C060B12MP13 | 14,900 | $745 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206779987 | COLEMAN | CH16B2421 | CM36BXA1+TXV | CP9C060B12MP13 | 14,900 | $745 |
| No | 206779985 | COLEMAN | CH16B2421 | CF36BBAA1 | CP9C060B12MP13 | 14,900 | $745 |
| No | 206779981 | COLEMAN | CH16B2421 | CU36BXA1+TXV | TP9C060B12MP13 | 14,900 | $745 |
| No | 206779977 | COLEMAN | CH16B2421 | CM36BBAA1 | TP9C060B12MP13 | 14,900 | $745 |
| No | 206779973 | COLEMAN | CH16B2421 | CM36BXA1+TXV | TP9C060B12MP13 | 14,900 | $745 |
| No | 206779957 | COLEMAN | CH16B2421 | CM36BXA1+TXV | TM9V060B12MP12 | 14,900 | $745 |
| No | 206779969 | COLEMAN | CH16B2421 | CF36BBAA1 | TP9C060B12MP13 | 14,900 | $745 |
| No | 206779961 | COLEMAN | CH16B2421 | CM36BBAA1 | TM9V060B12MP12 | 14,900 | $745 |
| No | 206779947 | COLEMAN | CH16B2421 | CF36BXA1+TXV | TP9C060B12MP13 | 14,900 | $745 |
| No | 206779953 | COLEMAN | CH16B2421 | CF36BBAA1 | TM9V060B12MP12 | 14,900 | $745 |
| No | 206779965 | COLEMAN | CH16B2421 | CU36BXA1+TXV | TM9V060B12MP12 | 14,900 | $745 |
| No | 206782619 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TP9C100C20MP13 | 33,000 | $1,650 |
| No | 206779943 | COLEMAN | CH16B2421 | CF36BXA1+TXV | TM9V060B12MP12 | 14,900 | $745 |
| No | 206782623 | COLEMAN | CH16B6021 | CM64DXA1+TXV | CP9C100C20MP13 | 33,000 | $1,650 |
| No | 206779951 | COLEMAN | CH16B2421 | CF36BXA1+TXV | CP9C060B12MP13 | 14,900 | $745 |
| No | 206782613 | COLEMAN | CH16B6021 | CF64DXA1+TXV | CP9C100C20MP13 | 33,000 | $1,650 |
| No | 206782615 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TM9V100C20MP12 | 33,000 | $1,650 |
| No | 206782609 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TP9C100C20MP13 | 33,000 | $1,650 |
| No | 206782605 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TM9V100C20MP12 | 33,000 | $1,650 |
| No | 205539557 | COLEMAN | CH16B6021 | CM64DXA1+TXV | CP9C120D20MP13 | 32,600 | $1,630 |
| No | 205539551 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TP9C120D20MP13 | 32,600 | $1,630 |
| No | 205539544 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TM9V120D20MP12 | 32,600 | $1,630 |
| No | 205539540 | COLEMAN | CH16B6021 | CF64DXA1+TXV | CP9C120D20MP13 | 32,600 | $1,630 |
| No | 205539531 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TP9C120D20MP13 | 32,600 | $1,630 |
| No | 205539523 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TM9V120D20MP12 | 32,600 | $1,630 |
| No | 9036115 | COLEMAN | CH16B4821 | AVC48CX21+TXV | | 27,600 | $1,380 |
| No | 206781529 | COLEMAN | CH16B4821 | CM48CBCA1+MVC16CN21 | | 28,000 | $1,400 |
| No | 206781525 | COLEMAN | CH16B4821 | CM48CXA1+MVC16CN21+TXV | | 28,000 | $1,400 |
| No | 202100052 | COLEMAN | CH16B4821 | CF48CBCA1+MVC16CN21 | | 28,000 | $1,400 |
| No | 206781771 | COLEMAN | CH16B4821 | CF48CXA1+MVC16CN21+TXV | | 28,000 | $1,400 |
| No | 206782360 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TPLC080B12MP13 | 28,200 | $1,410 |
| No | 206782356 | COLEMAN | CH16B4821 | CM48CBCA1 | TPLC080B12MP13 | 28,200 | $1,410 |
| No | 206782352 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TPLC080B12MP13 | 28,200 | $1,410 |
| No | 202100734 | COLEMAN | CH16B4821 | CF48CBCA1 | TPLC080B12MP13 | 28,200 | $1,410 |
| No | 206782348 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TM8V080B12MP12 | 28,200 | $1,410 |
| No | 206782340 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TM8V080B12MP12 | 28,200 | $1,410 |
| No | 202100654 | COLEMAN | CH16B4821 | CF48CBCA1 | TM8V080B12MP12 | 28,200 | $1,410 |
| No | 206782344 | COLEMAN | CH16B4821 | CM48CBCA1 | TM8V080B12MP12 | 28,200 | $1,410 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782335 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TPLC080B12MP13 | 28,200 | $1,410 |
| No | 206782331 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TM8V080B12MP12 | 28,200 | $1,410 |
| No | 206782329 | COLEMAN | CH16B4821 | CU48CXA1+TXV | CPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782327 | COLEMAN | CH16B4821 | CM48CBCA1 | CPLC100C16MP13 | 28,000 | $1,400 |
| No | 202100768 | COLEMAN | CH16B4821 | CF48CBCA1 | CPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782325 | COLEMAN | CH16B4821 | CM48CXA1+TXV | CPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782323 | COLEMAN | CH16B4821 | CU48CXA1+TXV | CPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782319 | COLEMAN | CH16B4821 | CM48CXA1+TXV | CPLC080C16MP13 | 28,000 | $1,400 |
| No | 202100767 | COLEMAN | CH16B4821 | CF48CBCA1 | CPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782321 | COLEMAN | CH16B4821 | CM48CBCA1 | CPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782311 | COLEMAN | CH16B4821 | CM48CBCA1 | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782315 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782307 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 202100742 | COLEMAN | CH16B4821 | CF48CBCA1 | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782303 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782299 | COLEMAN | CH16B4821 | CM48CBCA1 | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782295 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 202100741 | COLEMAN | CH16B4821 | CF48CBCA1 | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782291 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782287 | COLEMAN | CH16B4821 | CM48CBCA1 | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782283 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 202100702 | COLEMAN | CH16B4821 | CF48CBCA1 | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782279 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782275 | COLEMAN | CH16B4821 | CM48CBCA1 | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782271 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 202100661 | COLEMAN | CH16B4821 | CF48CBCA1 | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782267 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782263 | COLEMAN | CH16B4821 | CM48CBCA1 | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782259 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 202100662 | COLEMAN | CH16B4821 | CF48CBCA1 | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782171 | COLEMAN | CH16B4821 | CF48CXA1+TXV | CPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782169 | COLEMAN | CH16B4821 | CF48CXA1+TXV | CPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782165 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782161 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782157 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782153 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782149 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782147 | COLEMAN | CH16B4821 | CM48DBCA1 | CPLC100C16MP13 | 28,000 | $1,400 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782145 | COLEMAN | CH16B4821 | CU48DXA1+TXV | CPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782143 | COLEMAN | CH16B4821 | CM48DXA1+TXV | CPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782141 | COLEMAN | CH16B4821 | CM48DBCA1 | CPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782137 | COLEMAN | CH16B4821 | CM48DXA1+TXV | CPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782139 | COLEMAN | CH16B4821 | CU48DXA1+TXV | CPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782133 | COLEMAN | CH16B4821 | CM48DBCA1 | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782129 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782125 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782121 | COLEMAN | CH16B4821 | CM48DBCA1 | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782117 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782113 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782109 | COLEMAN | CH16B4821 | CM48DBCA1 | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782105 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782101 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782097 | COLEMAN | CH16B4821 | CM48DBCA1 | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782093 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782089 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782085 | COLEMAN | CH16B4821 | CM48DBCA1 | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782081 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782077 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782075 | COLEMAN | CH16B4821 | CF48DXA1+TXV | CPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782069 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782073 | COLEMAN | CH16B4821 | CF48DXA1+TXV | CPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782065 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782061 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782057 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782053 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782051 | COLEMAN | CH16B4821 | CM48DBCA1 | CPLC120C20MP13 | 28,200 | $1,410 |
| No | 206782049 | COLEMAN | CH16B4821 | CU48DXA1+TXV | CPLC120C20MP13 | 28,200 | $1,410 |
| No | 206782047 | COLEMAN | CH16B4821 | CM48DXA1+TXV | CPLC120C20MP13 | 28,200 | $1,410 |
| No | 206782040 | COLEMAN | CH16B4821 | CM48DBCA1 | TPLC120C20MP13 | 28,200 | $1,410 |
| No | 206782036 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TPLC120C20MP13 | 28,200 | $1,410 |
| No | 206782032 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TPLC120C20MP13 | 28,200 | $1,410 |
| No | 206782028 | COLEMAN | CH16B4821 | CM48DBCA1 | TPLC100C20MP13 | 28,200 | $1,410 |
| No | 206782024 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TPLC100C20MP13 | 28,200 | $1,410 |
| No | 206782020 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TPLC100C20MP13 | 28,200 | $1,410 |
| No | 206782016 | COLEMAN | CH16B4821 | CM48DBCA1 | TMLV120C20MP12 | 28,200 | $1,410 |
| No | 206782012 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TMLV120C20MP12 | 28,200 | $1,410 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782008 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TMLV120C20MP12 | 28,200 | $1,410 |
| No | 206782004 | COLEMAN | CH16B4821 | CM48DBCA1 | TM8V100C20MP12 | 28,200 | $1,410 |
| No | 206782000 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TM8V100C20MP12 | 28,200 | $1,410 |
| No | 206781996 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TM8V100C20MP12 | 28,200 | $1,410 |
| No | 206781992 | COLEMAN | CH16B4821 | CM48DBCA1 | TM8V120C20MP12 | 28,200 | $1,410 |
| No | 206781988 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TM8V120C20MP12 | 28,200 | $1,410 |
| No | 206781984 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TM8V120C20MP12 | 28,200 | $1,410 |
| No | 206781982 | COLEMAN | CH16B4821 | CF48DXA1+TXV | CPLC120C20MP13 | 28,200 | $1,410 |
| No | 206781973 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TPLC100C20MP13 | 28,200 | $1,410 |
| No | 206781977 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TPLC120C20MP13 | 28,200 | $1,410 |
| No | 206781969 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TMLV120C20MP12 | 28,200 | $1,410 |
| No | 206781965 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TM8V100C20MP12 | 28,200 | $1,410 |
| No | 206781961 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TM8V120C20MP12 | 28,200 | $1,410 |
| No | 206781959 | COLEMAN | CH16B4821 | CM64DXA1+TXV | CPLC120C20MP13 | 28,600 | $1,430 |
| No | 206781954 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TPLC120C20MP13 | 28,600 | $1,430 |
| No | 206781950 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TPLC100C20MP13 | 28,600 | $1,430 |
| No | 206781946 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TMLV120C20MP12 | 28,600 | $1,430 |
| No | 206781942 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TM8V100C20MP12 | 28,600 | $1,430 |
| No | 206781938 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TM8V120C20MP12 | 28,600 | $1,430 |
| No | 206781936 | COLEMAN | CH16B4821 | CF64DXA1+TXV | CPLC120C20MP13 | 28,600 | $1,430 |
| No | 206781931 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TPLC120C20MP13 | 28,600 | $1,430 |
| No | 206781927 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TPLC100C20MP13 | 28,600 | $1,430 |
| No | 206781923 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TMLV120C20MP12 | 28,600 | $1,430 |
| No | 206781919 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TM8V100C20MP12 | 28,600 | $1,430 |
| No | 206781915 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TM8V120C20MP12 | 28,600 | $1,430 |
| No | 206781347 | COLEMAN | CH16B4821 | CU48CXA1+TXV | CP9C060B12MP13 | 28,400 | $1,420 |
| No | 206781345 | COLEMAN | CH16B4821 | CM48CBCA1 | CP9C060B12MP13 | 28,400 | $1,420 |
| No | 206781343 | COLEMAN | CH16B4821 | CM48CXA1+TXV | CP9C060B12MP13 | 28,400 | $1,420 |
| No | 202100755 | COLEMAN | CH16B4821 | CF48CBCA1 | CP9C060B12MP13 | 28,400 | $1,420 |
| No | 206781339 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TP9C060B12MP13 | 28,400 | $1,420 |
| No | 206781335 | COLEMAN | CH16B4821 | CM48CBCA1 | TP9C060B12MP13 | 28,400 | $1,420 |
| No | 202100714 | COLEMAN | CH16B4821 | CF48CBCA1 | TP9C060B12MP13 | 28,400 | $1,420 |
| No | 206781331 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TP9C060B12MP13 | 28,400 | $1,420 |
| No | 206781327 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TM9V060B12MP12 | 28,400 | $1,420 |
| No | 206781323 | COLEMAN | CH16B4821 | CM48CBCA1 | TM9V060B12MP12 | 28,400 | $1,420 |
| No | 206781319 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TM9V060B12MP12 | 28,400 | $1,420 |
| No | 202100677 | COLEMAN | CH16B4821 | CF48CBCA1 | TM9V060B12MP12 | 28,400 | $1,420 |
| No | 206781313 | COLEMAN | CH16B4821 | CF48CXA1+TXV | CP9C060B12MP13 | 28,400 | $1,420 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781309 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TP9C060B12MP13 | 28,400 | $1,420 |
| No | 206781305 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TM9V060B12MP12 | 28,400 | $1,420 |
| No | 206782253 | COLEMAN | CH16B4821 | CU48CXA1+TXV | CP9C080B12MP13 | 28,200 | $1,410 |
| No | 206782251 | COLEMAN | CH16B4821 | CM48CBCA1 | CP9C080B12MP13 | 28,200 | $1,410 |
| No | 206782249 | COLEMAN | CH16B4821 | CM48CXA1+TXV | CP9C080B12MP13 | 28,200 | $1,410 |
| No | 202100756 | COLEMAN | CH16B4821 | CF48CBCA1 | CP9C080B12MP13 | 28,200 | $1,410 |
| No | 206782245 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TP9C080B12MP13 | 28,200 | $1,410 |
| No | 206782241 | COLEMAN | CH16B4821 | CM48CBCA1 | TP9C080B12MP13 | 28,200 | $1,410 |
| No | 206782237 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TP9C080B12MP13 | 28,200 | $1,410 |
| No | 202100721 | COLEMAN | CH16B4821 | CF48CBCA1 | TP9C080B12MP13 | 28,200 | $1,410 |
| No | 206782233 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TM9V080B12MP12 | 28,200 | $1,410 |
| No | 206782225 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TM9V080B12MP12 | 28,200 | $1,410 |
| No | 206782229 | COLEMAN | CH16B4821 | CM48CBCA1 | TM9V080B12MP12 | 28,200 | $1,410 |
| No | 206782211 | COLEMAN | CH16B4821 | CF48CXA1+TXV | CP9C080B12MP13 | 28,200 | $1,410 |
| No | 202100678 | COLEMAN | CH16B4821 | CF48CBCA1 | TM9V080B12MP12 | 28,200 | $1,410 |
| No | 206782207 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TP9C080B12MP13 | 28,200 | $1,410 |
| No | 206782203 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TM9V080B12MP12 | 28,200 | $1,410 |
| No | 206782201 | COLEMAN | CH16B4821 | CU48CXA1+TXV | CP9C080C16MP13 | 28,200 | $1,410 |
| No | 206782199 | COLEMAN | CH16B4821 | CM48CBCA1 | CP9C080C16MP13 | 28,200 | $1,410 |
| No | 206782197 | COLEMAN | CH16B4821 | CM48CXA1+TXV | CP9C080C16MP13 | 28,200 | $1,410 |
| No | 202100759 | COLEMAN | CH16B4821 | CF48CBCA1 | CP9C080C16MP13 | 28,200 | $1,410 |
| No | 206782217 | COLEMAN | CH16B4821 | CM48CBCA1 | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206782221 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206782213 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 202100722 | COLEMAN | CH16B4821 | CF48CBCA1 | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206782193 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206782189 | COLEMAN | CH16B4821 | CM48CBCA1 | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206782185 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 202100684 | COLEMAN | CH16B4821 | CF48CBCA1 | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206781885 | COLEMAN | CH16B4821 | CF48CXA1+TXV | CP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781881 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781877 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206781875 | COLEMAN | CH16B4821 | CM48DBCA1 | CP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781873 | COLEMAN | CH16B4821 | CU48DXA1+TXV | CP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781871 | COLEMAN | CH16B4821 | CM48DXA1+TXV | CP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781867 | COLEMAN | CH16B4821 | CM48DBCA1 | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781863 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781859 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781855 | COLEMAN | CH16B4821 | CM48DBCA1 | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206781851 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206781847 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206781845 | COLEMAN | CH16B4821 | CF48DXA1+TXV | CP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781841 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781837 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206781835 | COLEMAN | CH16B4821 | CM64DXA1+TXV | CP9C080C16MP13 | 29,800 | $1,490 |
| No | 206781831 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TP9C080C16MP13 | 29,800 | $1,490 |
| No | 206781827 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TM9V080C16MP12 | 29,800 | $1,490 |
| No | 206781825 | COLEMAN | CH16B4821 | CF64DXA1+TXV | CP9C080C16MP13 | 29,800 | $1,490 |
| No | 206781821 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TP9C080C16MP13 | 29,800 | $1,490 |
| No | 206781817 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TM9V080C16MP12 | 29,800 | $1,490 |
| No | 206781815 | COLEMAN | CH16B4821 | CU48CXA1+TXV | CP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781813 | COLEMAN | CH16B4821 | CM48CBCA1 | CP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781811 | COLEMAN | CH16B4821 | CM48CXA1+TXV | CP9C100C16MP13 | 28,000 | $1,400 |
| No | 202100760 | COLEMAN | CH16B4821 | CF48CBCA1 | CP9C100C16MP13 | 28,000 | $1,400 |
| No | 206782181 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206782177 | COLEMAN | CH16B4821 | CM48CBCA1 | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206782173 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 202100727 | COLEMAN | CH16B4821 | CF48CBCA1 | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781807 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206781803 | COLEMAN | CH16B4821 | CM48CBCA1 | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206781799 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 202100687 | COLEMAN | CH16B4821 | CF48CBCA1 | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206781753 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781757 | COLEMAN | CH16B4821 | CF48CXA1+TXV | CP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781747 | COLEMAN | CH16B4821 | CM48DBCA1 | CP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781749 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206781745 | COLEMAN | CH16B4821 | CU48DXA1+TXV | CP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781743 | COLEMAN | CH16B4821 | CM48DXA1+TXV | CP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781739 | COLEMAN | CH16B4821 | CM48DBCA1 | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781735 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781731 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781727 | COLEMAN | CH16B4821 | CM48DBCA1 | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206781723 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206781719 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206781717 | COLEMAN | CH16B4821 | CF48DXA1+TXV | CP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781713 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781709 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206782513 | COLEMAN | CH16B4821 | CM48DBCA1 | CP9C100C20MP13 | 28,200 | $1,410 |
| No | 206782511 | COLEMAN | CH16B4821 | CU48DXA1+TXV | CP9C100C20MP13 | 28,200 | $1,410 |
| No | 206782509 | COLEMAN | CH16B4821 | CM48DXA1+TXV | CP9C100C20MP13 | 28,200 | $1,410 |
| No | 206782505 | COLEMAN | CH16B4821 | CM48DBCA1 | TP9C100C20MP13 | 28,200 | $1,410 |
| No | 206782501 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TP9C100C20MP13 | 28,200 | $1,410 |
| No | 206782497 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TP9C100C20MP13 | 28,200 | $1,410 |
| No | 206782493 | COLEMAN | CH16B4821 | CM48DBCA1 | TM9V100C20MP12 | 28,200 | $1,410 |
| No | 206782489 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TM9V100C20MP12 | 28,200 | $1,410 |
| No | 206782485 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TM9V100C20MP12 | 28,200 | $1,410 |
| No | 206782483 | COLEMAN | CH16B4821 | CF48DXA1+TXV | CP9C100C20MP13 | 28,200 | $1,410 |
| No | 206782479 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TP9C100C20MP13 | 28,200 | $1,410 |
| No | 206782475 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TM9V100C20MP12 | 28,200 | $1,410 |
| No | 206782465 | COLEMAN | CH16B4821 | CM64DXA1+TXV | CP9C120D20MP13 | 29,400 | $1,470 |
| No | 206782461 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TP9C120D20MP13 | 29,400 | $1,470 |
| No | 206782457 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TM9V120D20MP12 | 29,400 | $1,470 |
| No | 206782451 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TP9C120D20MP13 | 29,400 | $1,470 |
| No | 206782455 | COLEMAN | CH16B4821 | CF64DXA1+TXV | CP9C120D20MP13 | 29,400 | $1,470 |
| No | 206782447 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TM9V120D20MP12 | 29,400 | $1,470 |
| No | 205536134 | COLEMAN | CH16B4821 | CM48DBCA1 | CP9C120D20MP13 | 28,400 | $1,420 |
| No | 205536130 | COLEMAN | CH16B4821 | CU48DXA1+TXV | CP9C120D20MP13 | 28,400 | $1,420 |
| No | 205536127 | COLEMAN | CH16B4821 | CM48DXA1+TXV | CP9C120D20MP13 | 28,400 | $1,420 |
| No | 205536119 | COLEMAN | CH16B4821 | CM48DBCA1 | TP9C120D20MP13 | 28,400 | $1,420 |
| No | 205536111 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TP9C120D20MP13 | 28,400 | $1,420 |
| No | 205536101 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TP9C120D20MP13 | 28,400 | $1,420 |
| No | 205536094 | COLEMAN | CH16B4821 | CM48DBCA1 | TM9V120D20MP12 | 28,400 | $1,420 |
| No | 205536086 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TM9V120D20MP12 | 28,400 | $1,420 |
| No | 205536077 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TM9V120D20MP12 | 28,400 | $1,420 |
| No | 205536072 | COLEMAN | CH16B4821 | CF48DXA1+TXV | CP9C120D20MP13 | 28,400 | $1,420 |
| No | 205536063 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TP9C120D20MP13 | 28,400 | $1,420 |
| No | 205536057 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TM9V120D20MP12 | 28,400 | $1,420 |
| No | 206780287 | COLEMAN | CH16B2421 | CU24BXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |
| No | 206780283 | COLEMAN | CH16B2421 | CM24BBAA1 | TL8E060A12UH11 | 15,200 | $760 |
| No | 206780279 | COLEMAN | CH16B2421 | CM24BXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |
| No | 206780275 | COLEMAN | CH16B2421 | CF24BBAA1 | TL8E060A12UH11 | 15,200 | $760 |
| No | 206780271 | COLEMAN | CH16B2421 | CF24BXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |
| No | 205540995 | COLEMAN | CH16B2421 | CM36BBAA1 | TL8E060A12UH11 | 15,100 | $755 |
| No | 205541007 | COLEMAN | CH16B2421 | CU36BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205540982 | COLEMAN | CH16B2421 | CM36BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205540969 | COLEMAN | CH16B2421 | CF36BBAA1 | TL8E060A12UH11 | 15,100 | $755 |
| No | 205540957 | COLEMAN | CH16B2421 | CF36BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205540942 | COLEMAN | CH16B2421 | CU24BXA1+TXV | TL9E060B12UH11 | 15,300 | $765 |
| No | 205540931 | COLEMAN | CH16B2421 | CM24BBAA1 | TL9E060B12UH11 | 15,300 | $765 |
| No | 205540918 | COLEMAN | CH16B2421 | CM24BXA1+TXV | TL9E060B12UH11 | 15,300 | $765 |
| No | 205540906 | COLEMAN | CH16B2421 | CF24BBAA1 | TL9E060B12UH11 | 15,300 | $765 |
| No | 205540892 | COLEMAN | CH16B2421 | CF24BXA1+TXV | TL9E060B12UH11 | 15,300 | $765 |
| No | 206780267 | COLEMAN | CH16B2421 | CU36CXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 206780263 | COLEMAN | CH16B2421 | CM36CXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 206780259 | COLEMAN | CH16B2421 | CF36CXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205540882 | COLEMAN | CH16B2421 | CU30BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 203429766 | COLEMAN | CH16B2421 | CM30BBAA1 | TMLE040A12MP11 | 15,100 | $755 |
| No | 205541137 | COLEMAN | CH16B2421 | CM30BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 203429755 | COLEMAN | CH16B2421 | CF30BBAA1 | TMLE040A12MP11 | 15,100 | $755 |
| No | 205540872 | COLEMAN | CH16B2421 | CU30BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 203429760 | COLEMAN | CH16B2421 | CM30BBAA1 | TM8E040A12MP11 | 15,100 | $755 |
| No | 205540859 | COLEMAN | CH16B2421 | CM30BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 203429750 | COLEMAN | CH16B2421 | CF30BBAA1 | TM8E040A12MP11 | 15,100 | $755 |
| No | 205540848 | COLEMAN | CH16B2421 | CF30BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 205540836 | COLEMAN | CH16B2421 | CF30BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 206780235 | COLEMAN | CH16B2421 | CM36AXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 206780231 | COLEMAN | CH16B2421 | CM36AXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 206780227 | COLEMAN | CH16B2421 | CF36AXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 206780223 | COLEMAN | CH16B2421 | CF36AXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 206780219 | COLEMAN | CH16B2421 | CU36BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 203429722 | COLEMAN | CH16B2421 | CM36BBAA1 | TMLE040A12MP11 | 15,100 | $755 |
| No | 206780215 | COLEMAN | CH16B2421 | CM36BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 203429711 | COLEMAN | CH16B2421 | CF36BBAA1 | TMLE040A12MP11 | 15,100 | $755 |
| No | 206780211 | COLEMAN | CH16B2421 | CU36BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 203429716 | COLEMAN | CH16B2421 | CM36BBAA1 | TM8E040A12MP11 | 15,100 | $755 |
| No | 206780207 | COLEMAN | CH16B2421 | CM36BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 203429706 | COLEMAN | CH16B2421 | CF36BBAA1 | TM8E040A12MP11 | 15,100 | $755 |
| No | 206780203 | COLEMAN | CH16B2421 | CF36BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 206780199 | COLEMAN | CH16B2421 | CF36BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 205550180 | COLEMAN | CH16B2421 | CM30CXA1+TXV | TMLE100B12MP11 | 15,200 | $760 |
| No | 205550176 | COLEMAN | CH16B2421 | CM30CXA1+TXV | TM8E100B12MP11 | 15,200 | $760 |
| No | 205550172 | COLEMAN | CH16B2421 | CF30CXA1+TXV | TMLE100B12MP11 | 15,200 | $760 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205550168 | COLEMAN | CH16B2421 | CF30CXA1+TXV | TM8E100B12MP11 | 15,200 | $760 |
| No | 206373299 | COLEMAN | CH16B2421 | CU24AXA1+TXV | TM9E026A08MP12 | 15,000 | $750 |
| No | 206373298 | COLEMAN | CH16B2421 | CM24ABAA1 | TM9E026A08MP12 | 15,000 | $750 |
| No | 206373297 | COLEMAN | CH16B2421 | CM24AXA1+TXV | TM9E026A08MP12 | 15,000 | $750 |
| No | 206373296 | COLEMAN | CH16B2421 | CF24ABAA1 | TM9E026A08MP12 | 15,000 | $750 |
| No | 206373294 | COLEMAN | CH16B2421 | CU30BXA1+TXV | TM9E026A08MP12 | 15,400 | $770 |
| No | 206373295 | COLEMAN | CH16B2421 | CF24AXA1+TXV | TM9E026A08MP12 | 15,000 | $750 |
| No | 206373292 | COLEMAN | CH16B2421 | CM30BXA1+TXV | TM9E026A08MP12 | 15,400 | $770 |
| No | 206373291 | COLEMAN | CH16B2421 | CF30BBAA1 | TM9E026A08MP12 | 15,400 | $770 |
| No | 206373293 | COLEMAN | CH16B2421 | CM30BBAA1 | TM9E026A08MP12 | 15,400 | $770 |
| No | 206373290 | COLEMAN | CH16B2421 | CF30BXA1+TXV | TM9E026A08MP12 | 15,400 | $770 |
| No | 206780195 | COLEMAN | CH16B2421 | CU24AXA1+TXV | TM9E040A10MP12 | 15,300 | $765 |
| No | 206780191 | COLEMAN | CH16B2421 | CM24ABAA1 | TM9E040A10MP12 | 15,300 | $765 |
| No | 206780187 | COLEMAN | CH16B2421 | CM24AXA1+TXV | TM9E040A10MP12 | 15,300 | $765 |
| No | 206780183 | COLEMAN | CH16B2421 | CF24ABAA1 | TM9E040A10MP12 | 15,300 | $765 |
| No | 206780179 | COLEMAN | CH16B2421 | CF24AXA1+TXV | TM9E040A10MP12 | 15,300 | $765 |
| No | 205074495 | COLEMAN | CH16B2421 | CM30AXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205074254 | COLEMAN | CH16B2421 | CF30ABAA1 | TM9E040A10MP12 | 15,200 | $760 |
| No | 205074490 | COLEMAN | CH16B2421 | CF30AXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540824 | COLEMAN | CH16B2421 | CM36AXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540812 | COLEMAN | CH16B2421 | CF36AXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540798 | COLEMAN | CH16B2421 | CU36BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540786 | COLEMAN | CH16B2421 | CM36BBAA1 | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540777 | COLEMAN | CH16B2421 | CM36BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540764 | COLEMAN | CH16B2421 | CF36BBAA1 | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540754 | COLEMAN | CH16B2421 | CF36BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540722 | COLEMAN | CH16B2421 | CM24BBAA1 | TM9E060A10MP12 | 15,300 | $765 |
| No | 205540739 | COLEMAN | CH16B2421 | CU24BXA1+TXV | TM9E060A10MP12 | 15,300 | $765 |
| No | 205540697 | COLEMAN | CH16B2421 | CF24BBAA1 | TM9E060A10MP12 | 15,300 | $765 |
| No | 205540710 | COLEMAN | CH16B2421 | CM24BXA1+TXV | TM9E060A10MP12 | 15,300 | $765 |
| No | 205074483 | COLEMAN | CH16B2421 | CM30AXA1+TXV | TM9E060A10MP12 | 15,200 | $760 |
| No | 205540683 | COLEMAN | CH16B2421 | CF24BXA1+TXV | TM9E060A10MP12 | 15,300 | $765 |
| No | 205074242 | COLEMAN | CH16B2421 | CF30ABAA1 | TM9E060A10MP12 | 15,200 | $760 |
| No | 205074476 | COLEMAN | CH16B2421 | CF30AXA1+TXV | TM9E060A10MP12 | 15,200 | $760 |
| No | 205540477 | COLEMAN | CH16B2421 | CU36BXA1+TXV | TM9E060A10MP12 | 15,200 | $760 |
| No | 205540461 | COLEMAN | CH16B2421 | CM36BBAA1 | TM9E060A10MP12 | 15,200 | $760 |
| No | 205540449 | COLEMAN | CH16B2421 | CM36BXA1+TXV | TM9E060A10MP12 | 15,200 | $760 |
| No | 205540433 | COLEMAN | CH16B2421 | CF36BBAA1 | TM9E060A10MP12 | 15,200 | $760 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205540418 | COLEMAN | CH16B2421 | CF36BXA1+TXV | TM9E060A10MP12 | 15,200 | $760 |
| No | 202763638 | COLEMAN | CH16B4821 | AVC60CX22+TXV | | 28,200 | $1,410 |
| No | 202143937 | COLEMAN | CH16B4821 | AE48DBC21 | | 28,200 | $1,410 |
| No | 202143941 | COLEMAN | CH16B4821 | AE48DX21+TXV | | 28,200 | $1,410 |
| No | 206781249 | COLEMAN | CH16B4821 | CM64DXA1+ME14DN21+TXV | | 29,000 | $1,450 |
| No | 206781245 | COLEMAN | CH16B4821 | CF64DXA1+ME14DN21+TXV | | 29,000 | $1,450 |
| No | 205540162 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205540147 | COLEMAN | CH16B4821 | CM48CBCA1 | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205540130 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205540634 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 202143985 | COLEMAN | CH16B4821 | CF48CBCA1 | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205540609 | COLEMAN | CH16B4821 | CM48DBCA1 | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205540596 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205540586 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205540537 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 206782571 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TM9Y080C16MP11 | 29,800 | $1,490 |
| No | 206782567 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TM9Y080C16MP11 | 29,800 | $1,490 |
| No | 9060430 | COLEMAN | CH16B2421 | AE30BX21+TXV | | 14,800 | $740 |
| No | 206838951 | COLEMAN | CH16B2421 | CM30BBAA1+ME08BN21 | | 15,100 | $755 |
| No | 206838947 | COLEMAN | CH16B2421 | CM30BXA1+ME08BN21+TXV | | 15,100 | $755 |
| No | 206838943 | COLEMAN | CH16B2421 | CF30BBAA1+ME08BN21 | | 15,100 | $755 |
| No | 206838939 | COLEMAN | CH16B2421 | CF30BXA1+ME08BN21+TXV | | 15,100 | $755 |
| No | 205536232 | COLEMAN | CH16B2421 | CU36BXA1+TXV | TM9Y060B12MP11 | 14,800 | $740 |
| No | 205536220 | COLEMAN | CH16B2421 | CM36BBAA1 | TM9Y060B12MP11 | 14,800 | $740 |
| No | 205536210 | COLEMAN | CH16B2421 | CM36BXA1+TXV | TM9Y060B12MP11 | 14,800 | $740 |
| No | 205536199 | COLEMAN | CH16B2421 | CF36BBAA1 | TM9Y060B12MP11 | 14,800 | $740 |
| No | 205536148 | COLEMAN | CH16B2421 | CF36BXA1+TXV | TM9Y060B12MP11 | 14,800 | $740 |
| No | 9060431 | COLEMAN | CH16B2421 | AVC24BX21+TXV | | 14,800 | $740 |
| No | 9060434 | COLEMAN | CH16B2421 | AVC36CX21+TXV | | 14,600 | $730 |
| No | 9036009 | COLEMAN | CH16B6021 | AVC60DX21+TXV | | 32,000 | $1,600 |
| No | 205539839 | COLEMAN | CH16B6021 | CM64DXA1+TXV | CP9C080C16MP13 | 32,600 | $1,630 |
| No | 205539828 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TP9C080C16MP13 | 32,600 | $1,630 |
| No | 205539817 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TM9V080C16MP12 | 32,600 | $1,630 |
| No | 205539812 | COLEMAN | CH16B6021 | CF64DXA1+TXV | CP9C080C16MP13 | 32,600 | $1,630 |
| No | 205539801 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TP9C080C16MP13 | 32,600 | $1,630 |
| No | 205539792 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TM9V080C16MP12 | 32,600 | $1,630 |
| No | 9036118 | COLEMAN | CH16B4821 | AVC60DX21+TXV | | 29,400 | $1,470 |
| No | 203429580 | COLEMAN | CH16B2421 | CM36BBAA1 | TMLE100B12MP11 | 15,000 | $750 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205550164 | COLEMAN | CH16B2421 | CU36BXA1+TXV | TMLE100B12MP11 | 15,000 | $750 |
| No | 203429569 | COLEMAN | CH16B2421 | CF36BBAA1 | TMLE100B12MP11 | 15,000 | $750 |
| No | 205550160 | COLEMAN | CH16B2421 | CM36BXA1+TXV | TMLE100B12MP11 | 15,000 | $750 |
| No | 205550156 | COLEMAN | CH16B2421 | CU36BXA1+TXV | TM8E100B12MP11 | 15,000 | $750 |
| No | 203429574 | COLEMAN | CH16B2421 | CM36BBAA1 | TM8E100B12MP11 | 15,000 | $750 |
| No | 205550152 | COLEMAN | CH16B2421 | CM36BXA1+TXV | TM8E100B12MP11 | 15,000 | $750 |
| No | 203429563 | COLEMAN | CH16B2421 | CF36BBAA1 | TM8E100B12MP11 | 15,000 | $750 |
| No | 205550144 | COLEMAN | CH16B2421 | CF36BXA1+TXV | TMLE100B12MP11 | 15,000 | $750 |
| No | 205550140 | COLEMAN | CH16B2421 | CF36BXA1+TXV | TM8E100B12MP11 | 15,000 | $750 |
| No | 203064261 | COLEMAN | CH16B3622 | AE36BX21+TXV | | 22,200 | $1,110 |
| No | 205548015 | COLEMAN | CH16B2421 | CU30BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205548011 | COLEMAN | CH16B2421 | CM30BBAA1 | TL8E060A12UH11 | 15,100 | $755 |
| No | 205548007 | COLEMAN | CH16B2421 | CM30BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205548003 | COLEMAN | CH16B2421 | CF30BBAA1 | TL8E060A12UH11 | 15,100 | $755 |
| No | 205547999 | COLEMAN | CH16B2421 | CF30BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205547995 | COLEMAN | CH16B2421 | CU30BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547991 | COLEMAN | CH16B2421 | CM30BBAA1 | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547987 | COLEMAN | CH16B2421 | CM30BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547983 | COLEMAN | CH16B2421 | CF30BBAA1 | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547979 | COLEMAN | CH16B2421 | CF30BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547975 | COLEMAN | CH16B2421 | CM30CXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547971 | COLEMAN | CH16B2421 | CF30CXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547963 | COLEMAN | CH16B2421 | CM36BBAA1 | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547959 | COLEMAN | CH16B2421 | CM36BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547967 | COLEMAN | CH16B2421 | CU36BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547955 | COLEMAN | CH16B2421 | CF36BBAA1 | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547951 | COLEMAN | CH16B2421 | CF36BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 206780255 | COLEMAN | CH16B2421 | CU24AXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |
| No | 203429842 | COLEMAN | CH16B2421 | CM24ABAA1 | TMLE040A12MP11 | 15,200 | $760 |
| No | 206780463 | COLEMAN | CH16B2421 | CM24AXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |
| No | 203429853 | COLEMAN | CH16B2421 | CF24ABAA1 | TMLE040A12MP11 | 15,200 | $760 |
| No | 206780251 | COLEMAN | CH16B2421 | CU24AXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 206780247 | COLEMAN | CH16B2421 | CM24AXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 203429837 | COLEMAN | CH16B2421 | CM24ABAA1 | TM8E040A12MP11 | 15,200 | $760 |
| No | 203429848 | COLEMAN | CH16B2421 | CF24ABAA1 | TM8E040A12MP11 | 15,200 | $760 |
| No | 206780243 | COLEMAN | CH16B2421 | CF24AXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |
| No | 205547947 | COLEMAN | CH16B2421 | CU24BXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |
| No | 206780239 | COLEMAN | CH16B2421 | CF24AXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203429810 | COLEMAN | CH16B2421 | CM24BBAA1 | TMLE040A12MP11 | 15,200 | $760 |
| No | 205548241 | COLEMAN | CH16B2421 | CM24BXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |
| No | 203429821 | COLEMAN | CH16B2421 | CF24BBAA1 | TMLE040A12MP11 | 15,200 | $760 |
| No | 205548237 | COLEMAN | CH16B2421 | CU24BXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 205548233 | COLEMAN | CH16B2421 | CM24BXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 203429804 | COLEMAN | CH16B2421 | CM24BBAA1 | TM8E040A12MP11 | 15,200 | $760 |
| No | 203429815 | COLEMAN | CH16B2421 | CF24BBAA1 | TM8E040A12MP11 | 15,200 | $760 |
| No | 205548201 | COLEMAN | CH16B2421 | CF24BXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |
| No | 205074515 | COLEMAN | CH16B2421 | CM30AXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 203429788 | COLEMAN | CH16B2421 | CF30ABAA1 | TMLE040A12MP11 | 15,100 | $755 |
| No | 205548197 | COLEMAN | CH16B2421 | CF24BXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 205074268 | COLEMAN | CH16B2421 | CM30AXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 203429782 | COLEMAN | CH16B2421 | CF30ABAA1 | TM8E040A12MP11 | 15,100 | $755 |
| No | 205074264 | COLEMAN | CH16B2421 | CF30AXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 205074502 | COLEMAN | CH16B2421 | CF30AXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 205546115 | COLEMAN | CH16B2421 | CU24BXA1+TXV | TMLE080B12MP11 | 15,200 | $760 |
| No | 203429678 | COLEMAN | CH16B2421 | CM24BBAA1 | TMLE080B12MP11 | 15,200 | $760 |
| No | 205546111 | COLEMAN | CH16B2421 | CM24BXA1+TXV | TMLE080B12MP11 | 15,200 | $760 |
| No | 203429689 | COLEMAN | CH16B2421 | CF24BBAA1 | TMLE080B12MP11 | 15,200 | $760 |
| No | 205546107 | COLEMAN | CH16B2421 | CU24BXA1+TXV | TM8E080B12MP11 | 15,200 | $760 |
| No | 203429673 | COLEMAN | CH16B2421 | CM24BBAA1 | TM8E080B12MP11 | 15,200 | $760 |
| No | 203429684 | COLEMAN | CH16B2421 | CF24BBAA1 | TM8E080B12MP11 | 15,200 | $760 |
| No | 205546103 | COLEMAN | CH16B2421 | CM24BXA1+TXV | TM8E080B12MP11 | 15,200 | $760 |
| No | 205546095 | COLEMAN | CH16B2421 | CF24BXA1+TXV | TMLE080B12MP11 | 15,200 | $760 |
| No | 205546091 | COLEMAN | CH16B2421 | CF24BXA1+TXV | TM8E080B12MP11 | 15,200 | $760 |
| No | 205546087 | COLEMAN | CH16B2421 | CU24BXA1+TXV | TMLE100B12MP11 | 15,100 | $755 |
| No | 203429645 | COLEMAN | CH16B2421 | CM24BBAA1 | TMLE100B12MP11 | 15,100 | $755 |
| No | 205546099 | COLEMAN | CH16B2421 | CM24BXA1+TXV | TMLE100B12MP11 | 15,100 | $755 |
| No | 203429656 | COLEMAN | CH16B2421 | CF24BBAA1 | TMLE100B12MP11 | 15,100 | $755 |
| No | 205544358 | COLEMAN | CH16B2421 | CU24BXA1+TXV | TM8E100B12MP11 | 15,100 | $755 |
| No | 203429640 | COLEMAN | CH16B2421 | CM24BBAA1 | TM8E100B12MP11 | 15,100 | $755 |
| No | 205544352 | COLEMAN | CH16B2421 | CM24BXA1+TXV | TM8E100B12MP11 | 15,100 | $755 |
| No | 203429651 | COLEMAN | CH16B2421 | CF24BBAA1 | TM8E100B12MP11 | 15,100 | $755 |
| No | 205544345 | COLEMAN | CH16B2421 | CF24BXA1+TXV | TMLE100B12MP11 | 15,100 | $755 |
| No | 205544338 | COLEMAN | CH16B2421 | CF24BXA1+TXV | TM8E100B12MP11 | 15,100 | $755 |
| No | 205550200 | COLEMAN | CH16B2421 | CU30BXA1+TXV | TMLE100B12MP11 | 15,200 | $760 |
| No | 203429623 | COLEMAN | CH16B2421 | CM30BBAA1 | TMLE100B12MP11 | 15,200 | $760 |
| No | 205550220 | COLEMAN | CH16B2421 | CM30BXA1+TXV | TMLE100B12MP11 | 15,200 | $760 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203429612 | COLEMAN | CH16B2421 | CF30BBAA1 | TMLE100B12MP11 | 15,200 | $760 |
| No | 205550196 | COLEMAN | CH16B2421 | CU30BXA1+TXV | TM8E100B12MP11 | 15,200 | $760 |
| No | 203429618 | COLEMAN | CH16B2421 | CM30BBAA1 | TM8E100B12MP11 | 15,200 | $760 |
| No | 205550192 | COLEMAN | CH16B2421 | CM30BXA1+TXV | TM8E100B12MP11 | 15,200 | $760 |
| No | 203429607 | COLEMAN | CH16B2421 | CF30BBAA1 | TM8E100B12MP11 | 15,200 | $760 |
| No | 205550188 | COLEMAN | CH16B2421 | CF30BXA1+TXV | TMLE100B12MP11 | 15,200 | $760 |
| No | 205550184 | COLEMAN | CH16B2421 | CF30BXA1+TXV | TM8E100B12MP11 | 15,200 | $760 |
| No | 206373289 | COLEMAN | CH16B2421 | CU24BXA1+TXV | TM9E026A08MP12 | 15,600 | $780 |
| No | 206373288 | COLEMAN | CH16B2421 | CM24BBAA1 | TM9E026A08MP12 | 15,600 | $780 |
| No | 206373287 | COLEMAN | CH16B2421 | CM24BXA1+TXV | TM9E026A08MP12 | 15,600 | $780 |
| No | 206373286 | COLEMAN | CH16B2421 | CF24BBAA1 | TM9E026A08MP12 | 15,600 | $780 |
| No | 206373285 | COLEMAN | CH16B2421 | CF24BXA1+TXV | TM9E026A08MP12 | 15,600 | $780 |
| No | 206373284 | COLEMAN | CH16B2421 | CM30AXA1+TXV | TM9E026A08MP12 | 14,800 | $740 |
| No | 206373283 | COLEMAN | CH16B2421 | CF30ABAA1 | TM9E026A08MP12 | 14,800 | $740 |
| No | 206373282 | COLEMAN | CH16B2421 | CF30AXA1+TXV | TM9E026A08MP12 | 14,800 | $740 |
| No | 206373281 | COLEMAN | CH16B2421 | CM36AXA1+TXV | TM9E026A08MP12 | 14,900 | $745 |
| No | 206373280 | COLEMAN | CH16B2421 | CF36AXA1+TXV | TM9E026A08MP12 | 14,900 | $745 |
| No | 206373279 | COLEMAN | CH16B2421 | CU36BXA1+TXV | TM9E026A08MP12 | 14,900 | $745 |
| No | 206373278 | COLEMAN | CH16B2421 | CM36BBAA1 | TM9E026A08MP12 | 14,900 | $745 |
| No | 206373277 | COLEMAN | CH16B2421 | CM36BXA1+TXV | TM9E026A08MP12 | 14,900 | $745 |
| No | 206373276 | COLEMAN | CH16B2421 | CF36BBAA1 | TM9E026A08MP12 | 14,900 | $745 |
| No | 206373275 | COLEMAN | CH16B2421 | CF36BXA1+TXV | TM9E026A08MP12 | 14,900 | $745 |
| No | 205548193 | COLEMAN | CH16B2421 | CU24BXA1+TXV | TM9E040A10MP12 | 15,400 | $770 |
| No | 205548189 | COLEMAN | CH16B2421 | CM24BBAA1 | TM9E040A10MP12 | 15,400 | $770 |
| No | 205548185 | COLEMAN | CH16B2421 | CM24BXA1+TXV | TM9E040A10MP12 | 15,400 | $770 |
| No | 205548181 | COLEMAN | CH16B2421 | CF24BBAA1 | TM9E040A10MP12 | 15,400 | $770 |
| No | 205548173 | COLEMAN | CH16B2421 | CU30BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205548177 | COLEMAN | CH16B2421 | CF24BXA1+TXV | TM9E040A10MP12 | 15,400 | $770 |
| No | 205548169 | COLEMAN | CH16B2421 | CM30BBAA1 | TM9E040A10MP12 | 15,200 | $760 |
| No | 205548161 | COLEMAN | CH16B2421 | CF30BBAA1 | TM9E040A10MP12 | 15,200 | $760 |
| No | 205548157 | COLEMAN | CH16B2421 | CF30BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205548165 | COLEMAN | CH16B2421 | CM30BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205548153 | COLEMAN | CH16B2421 | CU24AXA1+TXV | TM9E060A10MP12 | 15,400 | $770 |
| No | 205548149 | COLEMAN | CH16B2421 | CM24ABAA1 | TM9E060A10MP12 | 15,400 | $770 |
| No | 205548145 | COLEMAN | CH16B2421 | CM24AXA1+TXV | TM9E060A10MP12 | 15,400 | $770 |
| No | 205548141 | COLEMAN | CH16B2421 | CF24ABAA1 | TM9E060A10MP12 | 15,400 | $770 |
| No | 205548133 | COLEMAN | CH16B2421 | CU30BXA1+TXV | TM9E060A10MP12 | 15,100 | $755 |
| No | 205548137 | COLEMAN | CH16B2421 | CF24AXA1+TXV | TM9E060A10MP12 | 15,400 | $770 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205548129 | COLEMAN | CH16B2421 | CM30BBAA1 | TM9E060A10MP12 | 15,100 | $755 |
| No | 205548125 | COLEMAN | CH16B2421 | CM30BXA1+TXV | TM9E060A10MP12 | 15,100 | $755 |
| No | 205548121 | COLEMAN | CH16B2421 | CF30BBAA1 | TM9E060A10MP12 | 15,100 | $755 |
| No | 205548117 | COLEMAN | CH16B2421 | CF30BXA1+TXV | TM9E060A10MP12 | 15,100 | $755 |
| No | 205548113 | COLEMAN | CH16B2421 | CM36AXA1+TXV | TM9E060A10MP12 | 15,100 | $755 |
| No | 205548109 | COLEMAN | CH16B2421 | CF36AXA1+TXV | TM9E060A10MP12 | 15,100 | $755 |
| No | 206779781 | COLEMAN | CH16B2421 | CM36BBAA1+ME08BN21 | | 15,000 | $750 |
| No | 206779777 | COLEMAN | CH16B2421 | CM36BXA1+ME08BN21+TXV | | 15,000 | $750 |
| No | 206779773 | COLEMAN | CH16B2421 | CF36BBAA1+ME08BN21 | | 15,000 | $750 |
| No | 206779769 | COLEMAN | CH16B2421 | CF36BXA1+ME08BN21+TXV | | 15,000 | $750 |
| No | 9060432 | COLEMAN | CH16B2421 | AVC30BX21+TXV | | 15,100 | $755 |
| No | 9060433 | COLEMAN | CH16B2421 | AVC36BX21+TXV | | 15,000 | $750 |
| No | 205547847 | COLEMAN | CH16B6021 | CM64DXA1+MVC20DN21+TXV | | 32,600 | $1,630 |
| No | 205547843 | COLEMAN | CH16B6021 | CF64DXA1+MVC20DN21+TXV | | 32,600 | $1,630 |
| No | 205547841 | COLEMAN | CH16B6021 | CM64DXA1+TXV | CPLC120C20MP13 | 32,400 | $1,620 |
| No | 205547835 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TPLC120C20MP13 | 32,400 | $1,620 |
| No | 205547831 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TPLC100C20MP13 | 32,400 | $1,620 |
| No | 205547827 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TMLV120C20MP12 | 32,400 | $1,620 |
| No | 205547819 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TM8V100C20MP12 | 32,400 | $1,620 |
| No | 205547813 | COLEMAN | CH16B6021 | CF64DXA1+TXV | CPLC120C20MP13 | 32,400 | $1,620 |
| No | 205547815 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TM8V120C20MP12 | 32,400 | $1,620 |
| No | 205547807 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TPLC120C20MP13 | 32,400 | $1,620 |
| No | 205547803 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TPLC100C20MP13 | 32,400 | $1,620 |
| No | 205547799 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TMLV120C20MP12 | 32,400 | $1,620 |
| No | 205547791 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TM8V100C20MP12 | 32,400 | $1,620 |
| No | 205547787 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TM8V120C20MP12 | 32,400 | $1,620 |
| No | 203431213 | COLEMAN | CH16B4821 | CM48DBCA1 | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205547625 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205547621 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 203431208 | COLEMAN | CH16B4821 | CM48DBCA1 | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 205547571 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 205547567 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 205547563 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205547559 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 9854441 | COLEMAN | CH16B4821 | AE48CBC21 | | 28,400 | $1,420 |
| No | 9006280 | COLEMAN | CH16B4821 | AE48CX21+TXV | | 28,400 | $1,420 |
| No | 9854436 | COLEMAN | CH16B2421 | AE24BBA21 | | 15,100 | $755 |
| No | 9006270 | COLEMAN | CH16B2421 | AE24BX21+TXV | | 15,100 | $755 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205550136 | COLEMAN | CH16B3622 | CM36AXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 205550132 | COLEMAN | CH16B3622 | CF36AXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 203088274 | COLEMAN | CH16B3622 | CM36BBCA1 | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 205550128 | COLEMAN | CH16B3622 | CU36BXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 205550148 | COLEMAN | CH16B3622 | CM36BXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 203088256 | COLEMAN | CH16B3622 | CF36BBCA1 | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 205550124 | COLEMAN | CH16B3622 | CF36BXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 205550116 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205550120 | COLEMAN | CH16B3622 | CF42BXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 203088050 | COLEMAN | CH16B3622 | CM42CBCA1 | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205550112 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 203088030 | COLEMAN | CH16B3622 | CF42CBCA1 | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205550108 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205550104 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TL9E060B12UH11 | 22,400 | $1,120 |
| No | 203087992 | COLEMAN | CH16B3622 | CM48CBCA1 | TL9E060B12UH11 | 22,400 | $1,120 |
| No | 205550100 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TL9E060B12UH11 | 22,400 | $1,120 |
| No | 203087974 | COLEMAN | CH16B3622 | CF48CBCA1 | TL9E060B12UH11 | 22,400 | $1,120 |
| No | 205550096 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TL9E060B12UH11 | 22,400 | $1,120 |
| No | 205550092 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TL9E080C16UH11 | 22,600 | $1,130 |
| No | 203087938 | COLEMAN | CH16B3622 | CM36CBCA1 | TL9E080C16UH11 | 22,600 | $1,130 |
| No | 205550088 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TL9E080C16UH11 | 22,600 | $1,130 |
| No | 205550084 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TL9E080C16UH11 | 22,600 | $1,130 |
| No | 205550080 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TL9E080C16UH11 | 22,800 | $1,140 |
| No | 203087899 | COLEMAN | CH16B3622 | CM42CBCA1 | TL9E080C16UH11 | 22,800 | $1,140 |
| No | 205550076 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TL9E080C16UH11 | 22,800 | $1,140 |
| No | 203087880 | COLEMAN | CH16B3622 | CF42CBCA1 | TL9E080C16UH11 | 22,800 | $1,140 |
| No | 205550064 | COLEMAN | CH16B3622 | CM36AXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205550060 | COLEMAN | CH16B3622 | CM36AXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205550068 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TL9E080C16UH11 | 22,800 | $1,140 |
| No | 205550056 | COLEMAN | CH16B3622 | CF36AXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205550052 | COLEMAN | CH16B3622 | CF36AXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 203431021 | COLEMAN | CH16B3622 | CM36BBCA1 | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205550048 | COLEMAN | CH16B3622 | CU36BXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205550072 | COLEMAN | CH16B3622 | CM36BXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 203431015 | COLEMAN | CH16B3622 | CF36BBCA1 | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205550044 | COLEMAN | CH16B3622 | CU36BXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 203087717 | COLEMAN | CH16B3622 | CM36BBCA1 | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205550040 | COLEMAN | CH16B3622 | CM36BXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203087700 | COLEMAN | CH16B3622 | CF36BBCA1 | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205550036 | COLEMAN | CH16B3622 | CF36BXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205550032 | COLEMAN | CH16B3622 | CF36BXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205550028 | COLEMAN | CH16B3622 | CF42BXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205550021 | COLEMAN | CH16B3622 | CF42BXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205550017 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 203430944 | COLEMAN | CH16B3622 | CM36CBCA1 | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205550013 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205550009 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 203087452 | COLEMAN | CH16B3622 | CM36CBCA1 | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205550001 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205549997 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205549993 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205549985 | COLEMAN | CH16B3622 | CF42BXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205549989 | COLEMAN | CH16B3622 | CF42BXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205549981 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 203430922 | COLEMAN | CH16B3622 | CM42CBCA1 | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205550005 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 203430916 | COLEMAN | CH16B3622 | CF42CBCA1 | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205549977 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 203087377 | COLEMAN | CH16B3622 | CM42CBCA1 | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205549973 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 203087361 | COLEMAN | CH16B3622 | CF42CBCA1 | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205549969 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205549965 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 206780764 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TMLE080B12MP11 | 22,200 | $1,110 |
| No | 203430905 | COLEMAN | CH16B3622 | CM48CBCA1 | TMLE080B12MP11 | 22,200 | $1,110 |
| No | 206780760 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TMLE080B12MP11 | 22,200 | $1,110 |
| No | 203430900 | COLEMAN | CH16B3622 | CF48CBCA1 | TMLE080B12MP11 | 22,200 | $1,110 |
| No | 203087323 | COLEMAN | CH16B3622 | CM48CBCA1 | TM8E080B12MP11 | 22,200 | $1,110 |
| No | 206780756 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TM8E080B12MP11 | 22,200 | $1,110 |
| No | 206780752 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TM8E080B12MP11 | 22,200 | $1,110 |
| No | 203087300 | COLEMAN | CH16B3622 | CF48CBCA1 | TM8E080B12MP11 | 22,200 | $1,110 |
| No | 206780748 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TMLE080B12MP11 | 22,200 | $1,110 |
| No | 206780744 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TM8E080B12MP11 | 22,200 | $1,110 |
| No | 205549961 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203430839 | COLEMAN | CH16B3622 | CM48DBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205549957 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203087090 | COLEMAN | CH16B3622 | CM48DBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205549953 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205549949 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205549945 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205549941 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205549937 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203430811 | COLEMAN | CH16B3622 | CM36CBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205549933 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205549929 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203087002 | COLEMAN | CH16B3622 | CM36CBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205549909 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205549913 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205549905 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205549901 | COLEMAN | CH16B3622 | CF42BXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205549897 | COLEMAN | CH16B3622 | CF42BXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205549889 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205549893 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549885 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549881 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205549877 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 203430723 | COLEMAN | CH16B3622 | CM48CBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549925 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 203430718 | COLEMAN | CH16B3622 | CF48CBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549921 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203086688 | COLEMAN | CH16B3622 | CM48CBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205549917 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203086667 | COLEMAN | CH16B3622 | CF48CBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205549873 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549869 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203430707 | COLEMAN | CH16B3622 | CM48DBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549865 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 203086629 | COLEMAN | CH16B3622 | CM48DBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205549861 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549857 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205549853 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205549849 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549845 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205549841 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203430696 | COLEMAN | CH16B3622 | CM36CBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 205549837 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 205549833 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 203098278 | COLEMAN | CH16B3622 | CM36CBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 205549823 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 205549819 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 205549815 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 203430685 | COLEMAN | CH16B3622 | CM42CBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206780736 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206780740 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 203430679 | COLEMAN | CH16B3622 | CF42CBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206780732 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 203098262 | COLEMAN | CH16B3622 | CM42CBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 203098254 | COLEMAN | CH16B3622 | CF42CBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206780728 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206780724 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206780720 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 205549827 | COLEMAN | CH16B3622 | CU36BXA1+TXV | TPLC080B12MP13 | 22,800 | $1,140 |
| No | 203098045 | COLEMAN | CH16B3622 | CM36BBCA1 | TPLC080B12MP13 | 22,800 | $1,140 |
| No | 203098017 | COLEMAN | CH16B3622 | CF36BBCA1 | TPLC080B12MP13 | 22,800 | $1,140 |
| No | 205549809 | COLEMAN | CH16B3622 | CM36BXA1+TXV | TPLC080B12MP13 | 22,800 | $1,140 |
| No | 205549797 | COLEMAN | CH16B3622 | CU36BXA1+TXV | TM8V080B12MP12 | 22,800 | $1,140 |
| No | 203098029 | COLEMAN | CH16B3622 | CM36BBCA1 | TM8V080B12MP12 | 22,800 | $1,140 |
| No | 205549793 | COLEMAN | CH16B3622 | CM36BXA1+TXV | TM8V080B12MP12 | 22,800 | $1,140 |
| No | 203098001 | COLEMAN | CH16B3622 | CF36BBCA1 | TM8V080B12MP12 | 22,800 | $1,140 |
| No | 205549783 | COLEMAN | CH16B3622 | CF36BXA1+TXV | TPLC080B12MP13 | 22,800 | $1,140 |
| No | 205549775 | COLEMAN | CH16B3622 | CF36BXA1+TXV | TM8V080B12MP12 | 22,800 | $1,140 |
| No | 205549771 | COLEMAN | CH16B3622 | CU36BXA1+TXV | TM9E060A10MP12 | 23,000 | $1,150 |
| No | 205549789 | COLEMAN | CH16B3622 | CM36BXA1+TXV | TM9E060A10MP12 | 23,000 | $1,150 |
| No | 203097957 | COLEMAN | CH16B3622 | CM36BBCA1 | TM9E060A10MP12 | 23,000 | $1,150 |
| No | 203097949 | COLEMAN | CH16B3622 | CF36BBCA1 | TM9E060A10MP12 | 23,000 | $1,150 |
| No | 205549767 | COLEMAN | CH16B3622 | CF36BXA1+TXV | TM9E060A10MP12 | 23,000 | $1,150 |
| No | 205549763 | COLEMAN | CH16B3622 | CF42BXA1+TXV | TM9E060A10MP12 | 22,600 | $1,130 |
| No | 205549759 | COLEMAN | CH16B3622 | CU36BXA1+TXV | TM9E060B12MP12 | 22,400 | $1,120 |
| No | 203097916 | COLEMAN | CH16B3622 | CM36BBCA1 | TM9E060B12MP12 | 22,400 | $1,120 |
| No | 205549755 | COLEMAN | CH16B3622 | CM36BXA1+TXV | TM9E060B12MP12 | 22,400 | $1,120 |
| No | 205549747 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 203097909 | COLEMAN | CH16B3622 | CF36BBCA1 | TM9E060B12MP12 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549751 | COLEMAN | CH16B3622 | CF36BXA1+TXV | TM9E060B12MP12 | 22,400 | $1,120 |
| No | 203097892 | COLEMAN | CH16B3622 | CM36CBCA1 | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205549743 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205549739 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205549735 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097788 | COLEMAN | CH16B3622 | CM36CBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549731 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549727 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549723 | COLEMAN | CH16B3622 | CF42BXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549719 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097756 | COLEMAN | CH16B3622 | CM42CBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549715 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097748 | COLEMAN | CH16B3622 | CF42CBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549711 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549707 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097733 | COLEMAN | CH16B3622 | CM48CBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549703 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097725 | COLEMAN | CH16B3622 | CF48CBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549699 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097637 | COLEMAN | CH16B3622 | CM48DBCA1 | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 206780716 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 206780712 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 206780708 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 205549695 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 203097621 | COLEMAN | CH16B3622 | CM36CBCA1 | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205549691 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205549687 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205549683 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 203097604 | COLEMAN | CH16B3622 | CM42CBCA1 | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 205549679 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 203097596 | COLEMAN | CH16B3622 | CF42CBCA1 | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 205549671 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 205549667 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205549663 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205549659 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 203097573 | COLEMAN | CH16B3622 | CM48CBCA1 | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 205549675 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 203097564 | COLEMAN | CH16B3622 | CF48CBCA1 | TM9E100C16MP12 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549655 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 205549651 | COLEMAN | CH16B3622 | CU36BXA1+TXV | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 203097500 | COLEMAN | CH16B3622 | CM36BBCA1 | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 205549647 | COLEMAN | CH16B3622 | CM36BXA1+TXV | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 203097483 | COLEMAN | CH16B3622 | CF36BBCA1 | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 205549635 | COLEMAN | CH16B3622 | CF36BXA1+TXV | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 205549627 | COLEMAN | CH16B3622 | CF42BXA1+TXV | TM8Y080B12MP11 | 22,200 | $1,110 |
| No | 205549615 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TM8Y100C20MP11 | 22,400 | $1,120 |
| No | 203097388 | COLEMAN | CH16B3622 | CM36CBCA1 | TM8Y100C20MP11 | 22,400 | $1,120 |
| No | 205549611 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TM8Y100C20MP11 | 22,400 | $1,120 |
| No | 205549607 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TM8Y120C20MP11 | 22,400 | $1,120 |
| No | 203097380 | COLEMAN | CH16B3622 | CM36CBCA1 | TM8Y120C20MP11 | 22,400 | $1,120 |
| No | 205549603 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TM8Y120C20MP11 | 22,400 | $1,120 |
| No | 205549555 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TM8Y100C20MP11 | 22,400 | $1,120 |
| No | 205549551 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TM8Y120C20MP11 | 22,400 | $1,120 |
| No | 205549531 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TM8Y100C20MP11 | 23,200 | $1,160 |
| No | 203097292 | COLEMAN | CH16B3622 | CM42CBCA1 | TM8Y100C20MP11 | 23,200 | $1,160 |
| No | 205549571 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TM8Y100C20MP11 | 23,200 | $1,160 |
| No | 203097244 | COLEMAN | CH16B3622 | CF42CBCA1 | TM8Y100C20MP11 | 23,200 | $1,160 |
| No | 205549567 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TM8Y120C20MP11 | 23,200 | $1,160 |
| No | 203097284 | COLEMAN | CH16B3622 | CM42CBCA1 | TM8Y120C20MP11 | 23,200 | $1,160 |
| No | 205549563 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TM8Y120C20MP11 | 23,200 | $1,160 |
| No | 203097236 | COLEMAN | CH16B3622 | CF42CBCA1 | TM8Y120C20MP11 | 23,200 | $1,160 |
| No | 205549491 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TM8Y120C20MP11 | 23,200 | $1,160 |
| No | 205549495 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TM8Y100C20MP11 | 23,200 | $1,160 |
| No | 203097149 | COLEMAN | CH16B3622 | CM48DBCA1 | TM8Y100C20MP11 | 22,200 | $1,110 |
| No | 205549471 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TM8Y100C20MP11 | 22,200 | $1,110 |
| No | 205549467 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TM8Y100C20MP11 | 22,200 | $1,110 |
| No | 203097141 | COLEMAN | CH16B3622 | CM48DBCA1 | TM8Y120C20MP11 | 22,200 | $1,110 |
| No | 205549463 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TM8Y120C20MP11 | 22,200 | $1,110 |
| No | 205549459 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TM8Y120C20MP11 | 22,200 | $1,110 |
| No | 205549411 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TM8Y120C20MP11 | 22,200 | $1,110 |
| No | 205549415 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TM8Y100C20MP11 | 22,200 | $1,110 |
| No | 205549391 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 203097053 | COLEMAN | CH16B3622 | CM36CBCA1 | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205549431 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205549375 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 203097021 | COLEMAN | CH16B3622 | CM42CBCA1 | TM9Y080C16MP11 | 22,800 | $1,140 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549383 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205549371 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205549355 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 203097006 | COLEMAN | CH16B3622 | CF42CBCA1 | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205549347 | COLEMAN | CH16B3622 | CF42BXA1+MVC12BN21+TXV | | 22,000 | $1,100 |
| No | 203096737 | COLEMAN | CH16B3622 | CM36BBCA1+ME12BN21 | | 22,200 | $1,110 |
| No | 205549359 | COLEMAN | CH16B3622 | CM36BXA1+ME12BN21+TXV | | 22,200 | $1,110 |
| No | 203096729 | COLEMAN | CH16B3622 | CF36BBCA1+ME12BN21 | | 22,200 | $1,110 |
| No | 205549343 | COLEMAN | CH16B3622 | CF36BXA1+ME12BN21+TXV | | 22,200 | $1,110 |
| No | 205549339 | COLEMAN | CH16B3622 | CF42BXA1+ME12BN21+TXV | | 22,200 | $1,110 |
| No | 203096680 | COLEMAN | CH16B3622 | CM48DBCA1+MVC14DN21 | | 21,800 | $1,090 |
| No | 205549335 | COLEMAN | CH16B3622 | CM48DXA1+MVC14DN21+TXV | | 21,800 | $1,090 |
| No | 205549331 | COLEMAN | CH16B3622 | CF48DXA1+MVC14DN21+TXV | | 21,800 | $1,090 |
| No | 205549323 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 203096396 | COLEMAN | CH16B3622 | CM36CBCA1 | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 205549319 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 205549307 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 203096381 | COLEMAN | CH16B3622 | CM36CBCA1 | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205549297 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205549291 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 205549283 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205549301 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 203096256 | COLEMAN | CH16B3622 | CM42CBCA1 | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 205549277 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 205549265 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 203096229 | COLEMAN | CH16B3622 | CF42CBCA1 | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 203096241 | COLEMAN | CH16B3622 | CM42CBCA1 | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205549261 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 203096213 | COLEMAN | CH16B3622 | CF42CBCA1 | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205549249 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 205549241 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205549239 | COLEMAN | CH16B3622 | CU36CXA1+TXV | CP9C080C16MP13 | 22,200 | $1,110 |
| No | 203096026 | COLEMAN | CH16B3622 | CM36CBCA1 | CP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549259 | COLEMAN | CH16B3622 | CM36CXA1+TXV | CP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549255 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 203096018 | COLEMAN | CH16B3622 | CM36CBCA1 | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549235 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549231 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203096011 | COLEMAN | CH16B3622 | CM36CBCA1 | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205549219 | COLEMAN | CH16B3622 | CF36CXA1+TXV | CP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549221 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205549215 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549211 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205549209 | COLEMAN | CH16B3622 | CU42CXA1+TXV | CP9C080C16MP13 | 22,200 | $1,110 |
| No | 203095963 | COLEMAN | CH16B3622 | CM42CBCA1 | CP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549229 | COLEMAN | CH16B3622 | CM42CXA1+TXV | CP9C080C16MP13 | 22,200 | $1,110 |
| No | 203095943 | COLEMAN | CH16B3622 | CF42CBCA1 | CP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549225 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 203095955 | COLEMAN | CH16B3622 | CM42CBCA1 | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549205 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 203095935 | COLEMAN | CH16B3622 | CF42CBCA1 | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549199 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 203095947 | COLEMAN | CH16B3622 | CM42CBCA1 | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205549195 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205549193 | COLEMAN | CH16B3622 | CF42CXA1+TXV | CP9C080C16MP13 | 22,200 | $1,110 |
| No | 203095927 | COLEMAN | CH16B3622 | CF42CBCA1 | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205549185 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205549183 | COLEMAN | CH16B3622 | CU48CXA1+TXV | CP9C080C16MP13 | 22,000 | $1,100 |
| No | 205549189 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 203095878 | COLEMAN | CH16B3622 | CM48CBCA1 | CP9C080C16MP13 | 22,000 | $1,100 |
| No | 205549203 | COLEMAN | CH16B3622 | CM48CXA1+TXV | CP9C080C16MP13 | 22,000 | $1,100 |
| No | 203095858 | COLEMAN | CH16B3622 | CF48CBCA1 | CP9C080C16MP13 | 22,000 | $1,100 |
| No | 205549179 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 203095870 | COLEMAN | CH16B3622 | CM48CBCA1 | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 205549173 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 203095850 | COLEMAN | CH16B3622 | CF48CBCA1 | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 205549169 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 203095862 | COLEMAN | CH16B3622 | CM48CBCA1 | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 205549165 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 203095842 | COLEMAN | CH16B3622 | CF48CBCA1 | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 205549163 | COLEMAN | CH16B3622 | CF48CXA1+TXV | CP9C080C16MP13 | 22,000 | $1,100 |
| No | 205549159 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 205549155 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 203095744 | COLEMAN | CH16B3622 | AVC42CX21+TXV | | 22,600 | $1,130 |
| No | 203095620 | COLEMAN | CH16B3622 | CM36CBCA1 | CPLC100C16MP13 | 22,200 | $1,110 |
| No | 205549177 | COLEMAN | CH16B3622 | CU36CXA1+TXV | CPLC100C16MP13 | 22,200 | $1,110 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549153 | COLEMAN | CH16B3622 | CM36CXA1+TXV | CPLC100C16MP13 | 22,200 | $1,110 |
| No | 205549151 | COLEMAN | CH16B3622 | CU36CXA1+TXV | CPLC080C16MP13 | 22,200 | $1,110 |
| No | 203095616 | COLEMAN | CH16B3622 | CM36CBCA1 | CPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549145 | COLEMAN | CH16B3622 | CM36CXA1+TXV | CPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549141 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203095608 | COLEMAN | CH16B3622 | CM36CBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205549137 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205549133 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 203095600 | COLEMAN | CH16B3622 | CM36CBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549129 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549125 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203095592 | COLEMAN | CH16B3622 | CM36CBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205549121 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205549109 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203095576 | COLEMAN | CH16B3622 | CM36CBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205549105 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205549101 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203095568 | COLEMAN | CH16B3622 | CM36CBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205549097 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205549095 | COLEMAN | CH16B3622 | CF36CXA1+TXV | CPLC100C16MP13 | 22,200 | $1,110 |
| No | 205549093 | COLEMAN | CH16B3622 | CF36CXA1+TXV | CPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549089 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205549085 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549081 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205549073 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205549069 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205549149 | COLEMAN | CH16B3622 | CU48DXA1+TXV | CPLC100C16MP13 | 22,200 | $1,110 |
| No | 203094727 | COLEMAN | CH16B3622 | CM48DBCA1 | CPLC100C16MP13 | 22,200 | $1,110 |
| No | 205549147 | COLEMAN | CH16B3622 | CM48DXA1+TXV | CPLC100C16MP13 | 22,200 | $1,110 |
| No | 203094723 | COLEMAN | CH16B3622 | CM48DBCA1 | CPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549067 | COLEMAN | CH16B3622 | CU48DXA1+TXV | CPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549065 | COLEMAN | CH16B3622 | CM48DXA1+TXV | CPLC080C16MP13 | 22,200 | $1,110 |
| No | 203094715 | COLEMAN | CH16B3622 | CM48DBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205549057 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205549053 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203094707 | COLEMAN | CH16B3622 | CM48DBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549049 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549045 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203094699 | COLEMAN | CH16B3622 | CM48DBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205549037 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205549041 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203094683 | COLEMAN | CH16B3622 | CM48DBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205549025 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205549021 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203094675 | COLEMAN | CH16B3622 | CM48DBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205548999 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205548997 | COLEMAN | CH16B3622 | CF48DXA1+TXV | CPLC100C16MP13 | 22,200 | $1,110 |
| No | 205548995 | COLEMAN | CH16B3622 | CF48DXA1+TXV | CPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549003 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205548991 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205548987 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205548983 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205548975 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205548971 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205548969 | COLEMAN | CH16B3622 | CU36CXA1+TXV | CPLC120C20MP13 | 22,400 | $1,120 |
| No | 203094500 | COLEMAN | CH16B3622 | CM36CBCA1 | CPLC120C20MP13 | 22,400 | $1,120 |
| No | 205549063 | COLEMAN | CH16B3622 | CM36CXA1+TXV | CPLC120C20MP13 | 22,400 | $1,120 |
| No | 205549015 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 203094488 | COLEMAN | CH16B3622 | CM36CBCA1 | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205549011 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205549007 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 203094480 | COLEMAN | CH16B3622 | CM36CBCA1 | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548965 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548961 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 203094473 | COLEMAN | CH16B3622 | CM36CBCA1 | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548957 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548945 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 203094457 | COLEMAN | CH16B3622 | CM36CBCA1 | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548941 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548937 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 203094449 | COLEMAN | CH16B3622 | CM36CBCA1 | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548933 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548931 | COLEMAN | CH16B3622 | CF36CXA1+TXV | CPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548925 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548921 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548917 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205548909 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548905 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548903 | COLEMAN | CH16B3622 | CU42CXA1+TXV | CPLC120C20MP13 | 22,400 | $1,120 |
| No | 203094219 | COLEMAN | CH16B3622 | CM42CBCA1 | CPLC120C20MP13 | 22,400 | $1,120 |
| No | 203094164 | COLEMAN | CH16B3622 | CF42CBCA1 | CPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548901 | COLEMAN | CH16B3622 | CM42CXA1+TXV | CPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548893 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 203094207 | COLEMAN | CH16B3622 | CM42CBCA1 | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548889 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 203094152 | COLEMAN | CH16B3622 | CF42CBCA1 | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548885 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548881 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 203094200 | COLEMAN | CH16B3622 | CM42CBCA1 | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 203094143 | COLEMAN | CH16B3622 | CF42CBCA1 | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548877 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 203094191 | COLEMAN | CH16B3622 | CM42CBCA1 | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548873 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 203094135 | COLEMAN | CH16B3622 | CF42CBCA1 | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548857 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 203094175 | COLEMAN | CH16B3622 | CM42CBCA1 | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548847 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548839 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 203094167 | COLEMAN | CH16B3622 | CM42CBCA1 | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 203094119 | COLEMAN | CH16B3622 | CF42CBCA1 | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548829 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 203094112 | COLEMAN | CH16B3622 | CF42CBCA1 | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548815 | COLEMAN | CH16B3622 | CF42CXA1+TXV | CPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548809 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548805 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548801 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548793 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548789 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548787 | COLEMAN | CH16B3622 | CM42DXA1+TXV | CPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548781 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548777 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548773 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548765 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548761 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205548759 | COLEMAN | CH16B3622 | CF42DXA1+TXV | CPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548753 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548749 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548745 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548737 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548733 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548729 | COLEMAN | CH16B3622 | CU36BXA1+TXV | TM8Y080B12MP11 | 22,000 | $1,100 |
| No | 203093057 | COLEMAN | CH16B3622 | CM36BBCA1 | TM8Y080B12MP11 | 22,000 | $1,100 |
| No | 205548825 | COLEMAN | CH16B3622 | CM36BXA1+TXV | TM8Y080B12MP11 | 22,000 | $1,100 |
| No | 203093004 | COLEMAN | CH16B3622 | CF36BBCA1 | TM8Y080B12MP11 | 22,000 | $1,100 |
| No | 205548717 | COLEMAN | CH16B3622 | CF36BXA1+TXV | TM8Y080B12MP11 | 22,000 | $1,100 |
| No | 203092671 | COLEMAN | CH16B3622 | CM42CBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205548705 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205548701 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 203092555 | COLEMAN | CH16B3622 | CF42CBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205548697 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203092653 | COLEMAN | CH16B3622 | CM42CBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205548693 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203092537 | COLEMAN | CH16B3622 | CF42CBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205548653 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205548649 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205548629 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205548625 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205548605 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205548581 | COLEMAN | CH16B3622 | CF42BXA1+TXV | TM9Y080B12MP11 | 22,000 | $1,100 |
| No | 205548601 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205548573 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205548569 | COLEMAN | CH16B3622 | CM36CBCA1 | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205548565 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205548553 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205548545 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548541 | COLEMAN | CH16B3622 | CM48CBCA1 | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548537 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548533 | COLEMAN | CH16B3622 | CF48CBCA1 | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548525 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548517 | COLEMAN | CH16B3622 | CM48DBCA1 | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548513 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548509 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205548389 | COLEMAN | CH16B3622 | CF42BXA1+TXV | CP9C080B12MP13 | 22,200 | $1,110 |
| No | 205548487 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548385 | COLEMAN | CH16B3622 | CF42BXA1+TXV | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 205548381 | COLEMAN | CH16B3622 | CF42BXA1+TXV | TM9V080B12MP12 | 22,200 | $1,110 |
| No | 205548379 | COLEMAN | CH16B3622 | CU48CXA1+TXV | CP9C100C16MP13 | 21,800 | $1,090 |
| No | 203090052 | COLEMAN | CH16B3622 | CM48CBCA1 | CP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548503 | COLEMAN | CH16B3622 | CM48CXA1+TXV | CP9C100C16MP13 | 21,800 | $1,090 |
| No | 203090005 | COLEMAN | CH16B3622 | CF48CBCA1 | CP9C100C16MP13 | 21,800 | $1,090 |
| No | 203090033 | COLEMAN | CH16B3622 | CM48CBCA1 | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548499 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548411 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 203089987 | COLEMAN | CH16B3622 | CF48CBCA1 | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548407 | COLEMAN | CH16B3622 | CU48CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 203090014 | COLEMAN | CH16B3622 | CM48CBCA1 | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205548375 | COLEMAN | CH16B3622 | CM48CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 203089971 | COLEMAN | CH16B3622 | CF48CBCA1 | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205548373 | COLEMAN | CH16B3622 | CF48CXA1+TXV | CP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548369 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548365 | COLEMAN | CH16B3622 | CF48CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 203089867 | COLEMAN | CH16B3622 | CM48DBCA1 | CP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548363 | COLEMAN | CH16B3622 | CU48DXA1+TXV | CP9C100C16MP13 | 21,800 | $1,090 |
| No | 203089850 | COLEMAN | CH16B3622 | CM48DBCA1 | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548355 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548361 | COLEMAN | CH16B3622 | CM48DXA1+TXV | CP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548351 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 203089832 | COLEMAN | CH16B3622 | CM48DBCA1 | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205548347 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205548343 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205548341 | COLEMAN | CH16B3622 | CF48DXA1+TXV | CP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548337 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548333 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205548331 | COLEMAN | CH16B3622 | CU36CXA1+TXV | CP9C100C20MP13 | 22,400 | $1,120 |
| No | 203089681 | COLEMAN | CH16B3622 | CM36CBCA1 | CP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548329 | COLEMAN | CH16B3622 | CM36CXA1+TXV | CP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548325 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 203089661 | COLEMAN | CH16B3622 | CM36CBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548321 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548317 | COLEMAN | CH16B3622 | CU36CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203089644 | COLEMAN | CH16B3622 | CM36CBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205548313 | COLEMAN | CH16B3622 | CM36CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205548311 | COLEMAN | CH16B3622 | CF36CXA1+TXV | CP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548307 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548301 | COLEMAN | CH16B3622 | CU42CXA1+TXV | CP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548303 | COLEMAN | CH16B3622 | CF36CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203089451 | COLEMAN | CH16B3622 | CM42CBCA1 | CP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548359 | COLEMAN | CH16B3622 | CM42CXA1+TXV | CP9C100C20MP13 | 22,400 | $1,120 |
| No | 203089408 | COLEMAN | CH16B3622 | CF42CBCA1 | CP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548297 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 203089434 | COLEMAN | CH16B3622 | CM42CBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548289 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 203089390 | COLEMAN | CH16B3622 | CF42CBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548285 | COLEMAN | CH16B3622 | CU42CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203089416 | COLEMAN | CH16B3622 | CM42CBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203089372 | COLEMAN | CH16B3622 | CF42CBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205548281 | COLEMAN | CH16B3622 | CM42CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205548279 | COLEMAN | CH16B3622 | CF42CXA1+TXV | CP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548275 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548271 | COLEMAN | CH16B3622 | CF42CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 206780706 | COLEMAN | CH16B3622 | CM42DXA1+TXV | CP9C120D20MP13 | 22,000 | $1,100 |
| No | 206780702 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 206780698 | COLEMAN | CH16B3622 | CM42DXA1+TXV | TM9V120D20MP12 | 22,000 | $1,100 |
| No | 206780692 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 206780688 | COLEMAN | CH16B3622 | CF42DXA1+TXV | TM9V120D20MP12 | 22,000 | $1,100 |
| No | 206780696 | COLEMAN | CH16B3622 | CF42DXA1+TXV | CP9C120D20MP13 | 22,000 | $1,100 |
| No | 203088574 | COLEMAN | CH16B3622 | CM48DBCA1 | CP9C120D20MP13 | 22,000 | $1,100 |
| No | 205548295 | COLEMAN | CH16B3622 | CU48DXA1+TXV | CP9C120D20MP13 | 22,000 | $1,100 |
| No | 205548293 | COLEMAN | CH16B3622 | CM48DXA1+TXV | CP9C120D20MP13 | 22,000 | $1,100 |
| No | 203088559 | COLEMAN | CH16B3622 | CM48DBCA1 | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 205548267 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 205548263 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 203088540 | COLEMAN | CH16B3622 | CM48DBCA1 | TM9V120D20MP12 | 22,000 | $1,100 |
| No | 205548259 | COLEMAN | CH16B3622 | CU48DXA1+TXV | TM9V120D20MP12 | 22,000 | $1,100 |
| No | 205548255 | COLEMAN | CH16B3622 | CM48DXA1+TXV | TM9V120D20MP12 | 22,000 | $1,100 |
| No | 205548253 | COLEMAN | CH16B3622 | CF48DXA1+TXV | CP9C120D20MP13 | 22,000 | $1,100 |
| No | 205548249 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 205548245 | COLEMAN | CH16B3622 | CF48DXA1+TXV | TM9V120D20MP12 | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203088475 | COLEMAN | CH16B3622 | CM48DBCA1+MVC20DN21 | | 22,000 | $1,100 |
| No | 205548097 | COLEMAN | CH16B3622 | CM48DXA1+MVC20DN21+TXV | | 22,000 | $1,100 |
| No | 205548093 | COLEMAN | CH16B3622 | CF48DXA1+MVC20DN21+TXV | | 22,000 | $1,100 |
| No | 205548089 | COLEMAN | CH16B3622 | CM42DXA1+MVC20DN21+TXV | | 22,000 | $1,100 |
| No | 205548085 | COLEMAN | CH16B3622 | CF42DXA1+MVC20DN21+TXV | | 22,000 | $1,100 |
| No | 205548081 | COLEMAN | CH16B3622 | CM42DXA1+MVC14DN21+TXV | | 22,200 | $1,110 |
| No | 205548077 | COLEMAN | CH16B3622 | CF42DXA1+MVC14DN21+TXV | | 22,200 | $1,110 |
| No | 205074556 | COLEMAN | CH16B2421 | CM30AXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205074304 | COLEMAN | CH16B2421 | CF30ABAA1 | TL8E060A12UH11 | 15,100 | $755 |
| No | 205074549 | COLEMAN | CH16B2421 | CF30AXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205546767 | COLEMAN | CH16B2421 | CM36AXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205546763 | COLEMAN | CH16B2421 | CF36AXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205546759 | COLEMAN | CH16B4821 | CM48DBCA1 | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 205546755 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 205546751 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 205546747 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 205546715 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TL8E100C20UH11 | 28,200 | $1,410 |
| No | 205546711 | COLEMAN | CH16B4821 | CM48CBCA1 | TL8E100C20UH11 | 28,200 | $1,410 |
| No | 205546703 | COLEMAN | CH16B4821 | CF48CBCA1 | TL8E100C20UH11 | 28,200 | $1,410 |
| No | 205546707 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TL8E100C20UH11 | 28,200 | $1,410 |
| No | 205546699 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TL8E100C20UH11 | 28,200 | $1,410 |
| No | 205546695 | COLEMAN | CH16B4821 | CM48DBCA1 | TL8E100C20UH11 | 28,600 | $1,430 |
| No | 205546691 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TL8E100C20UH11 | 28,600 | $1,430 |
| No | 205546687 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TL8E100C20UH11 | 28,600 | $1,430 |
| No | 205546683 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TL8E100C20UH11 | 28,600 | $1,430 |
| No | 205546679 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TL8E100C20UH11 | 29,400 | $1,470 |
| No | 205546675 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TL8E100C20UH11 | 29,400 | $1,470 |
| No | 205546671 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205546667 | COLEMAN | CH16B4821 | CM48CBCA1 | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205546663 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205546659 | COLEMAN | CH16B4821 | CF48CBCA1 | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205546655 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205546651 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TL9E100C20UH11 | 28,400 | $1,420 |
| No | 205546647 | COLEMAN | CH16B4821 | CM48CBCA1 | TL9E100C20UH11 | 28,400 | $1,420 |
| No | 205546643 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TL9E100C20UH11 | 28,400 | $1,420 |
| No | 205546639 | COLEMAN | CH16B4821 | CF48CBCA1 | TL9E100C20UH11 | 28,400 | $1,420 |
| No | 205546635 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TL9E100C20UH11 | 28,400 | $1,420 |
| No | 205546631 | COLEMAN | CH16B4821 | CM48DBCA1 | TL9E100C20UH11 | 28,600 | $1,430 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205546627 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TL9E100C20UH11 | 28,600 | $1,430 |
| No | 205546623 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TL9E100C20UH11 | 28,600 | $1,430 |
| No | 205546619 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TL9E100C20UH11 | 28,600 | $1,430 |
| No | 205546615 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TL9E100C20UH11 | 30,400 | $1,520 |
| No | 205546611 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TL9E100C20UH11 | 30,400 | $1,520 |
| No | 205546607 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TMLE080B12MP11 | 28,000 | $1,400 |
| No | 203431427 | COLEMAN | CH16B4821 | CM48CBCA1 | TMLE080B12MP11 | 28,000 | $1,400 |
| No | 203431416 | COLEMAN | CH16B4821 | CF48CBCA1 | TMLE080B12MP11 | 28,000 | $1,400 |
| No | 205546743 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TMLE080B12MP11 | 28,000 | $1,400 |
| No | 205546739 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TM8E080B12MP11 | 28,000 | $1,400 |
| No | 203431422 | COLEMAN | CH16B4821 | CM48CBCA1 | TM8E080B12MP11 | 28,000 | $1,400 |
| No | 205546735 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TM8E080B12MP11 | 28,000 | $1,400 |
| No | 203431411 | COLEMAN | CH16B4821 | CF48CBCA1 | TM8E080B12MP11 | 28,000 | $1,400 |
| No | 205546727 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TMLE080B12MP11 | 28,000 | $1,400 |
| No | 205546723 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TM8E080B12MP11 | 28,000 | $1,400 |
| No | 205546719 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TMLE080C16MP11 | 28,600 | $1,430 |
| No | 203431383 | COLEMAN | CH16B4821 | CM48CBCA1 | TMLE080C16MP11 | 28,600 | $1,430 |
| No | 205546731 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TMLE080C16MP11 | 28,600 | $1,430 |
| No | 203431372 | COLEMAN | CH16B4821 | CF48CBCA1 | TMLE080C16MP11 | 28,600 | $1,430 |
| No | 205546603 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TM8E080C16MP11 | 28,600 | $1,430 |
| No | 203431378 | COLEMAN | CH16B4821 | CM48CBCA1 | TM8E080C16MP11 | 28,600 | $1,430 |
| No | 205546599 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TM8E080C16MP11 | 28,600 | $1,430 |
| No | 203431367 | COLEMAN | CH16B4821 | CF48CBCA1 | TM8E080C16MP11 | 28,600 | $1,430 |
| No | 205546595 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TMLE080C16MP11 | 28,600 | $1,430 |
| No | 205546591 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TM8E080C16MP11 | 28,600 | $1,430 |
| No | 203431350 | COLEMAN | CH16B4821 | CM48DBCA1 | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 205546583 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 205546587 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 203431345 | COLEMAN | CH16B4821 | CM48DBCA1 | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205546579 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205546575 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205546571 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 205546567 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205085174 | COLEMAN | CH16B4821 | CM60DXA2+TXV | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 205085168 | COLEMAN | CH16B4821 | CU60DXA2+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205085179 | COLEMAN | CH16B4821 | CU60DXA2+TXV | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 205085164 | COLEMAN | CH16B4821 | CM60DXA2+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205085160 | COLEMAN | CH16B4821 | CF60DXA2+TXV | TMLE080C16MP11 | 27,800 | $1,390 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205085150 | COLEMAN | CH16B4821 | CF60DXA2+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205546554 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TMLE080C16MP11 | 30,600 | $1,530 |
| No | 205546549 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TM8E080C16MP11 | 30,600 | $1,530 |
| No | 205546545 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TMLE080C16MP11 | 30,600 | $1,530 |
| No | 205546540 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TM8E080C16MP11 | 30,600 | $1,530 |
| No | 205546536 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TMLE100B12MP11 | 27,800 | $1,390 |
| No | 205546563 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TMLE100B12MP11 | 27,800 | $1,390 |
| No | 203431285 | COLEMAN | CH16B4821 | CM48CBCA1 | TMLE100B12MP11 | 27,800 | $1,390 |
| No | 205546559 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TM8E100B12MP11 | 27,800 | $1,390 |
| No | 203431274 | COLEMAN | CH16B4821 | CF48CBCA1 | TMLE100B12MP11 | 27,800 | $1,390 |
| No | 203431279 | COLEMAN | CH16B4821 | CM48CBCA1 | TM8E100B12MP11 | 27,800 | $1,390 |
| No | 205546531 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TM8E100B12MP11 | 27,800 | $1,390 |
| No | 203431268 | COLEMAN | CH16B4821 | CF48CBCA1 | TM8E100B12MP11 | 27,800 | $1,390 |
| No | 205546526 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TMLE100B12MP11 | 27,800 | $1,390 |
| No | 205546522 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TM8E100B12MP11 | 27,800 | $1,390 |
| No | 205546517 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 203431246 | COLEMAN | CH16B4821 | CM48CBCA1 | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205546512 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 203431235 | COLEMAN | CH16B4821 | CF48CBCA1 | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205546508 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 203431241 | COLEMAN | CH16B4821 | CM48CBCA1 | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 205546503 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 203431230 | COLEMAN | CH16B4821 | CF48CBCA1 | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 205546498 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205546494 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 206781498 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TMLE100C16MP11 | 30,600 | $1,530 |
| No | 206781494 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TM8E100C16MP11 | 30,600 | $1,530 |
| No | 206781490 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TMLE100C16MP11 | 30,600 | $1,530 |
| No | 206781486 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TM8E100C16MP11 | 30,600 | $1,530 |
| No | 205084981 | COLEMAN | CH16B4821 | CU60CXA2+TXV | TMLE100C20MP11 | 27,200 | $1,360 |
| No | 205084976 | COLEMAN | CH16B4821 | CM60CXA2+TXV | TMLE100C20MP11 | 27,200 | $1,360 |
| No | 205084971 | COLEMAN | CH16B4821 | CU60CXA2+TXV | TM8E100C20MP11 | 27,200 | $1,360 |
| No | 205084965 | COLEMAN | CH16B4821 | CM60CXA2+TXV | TM8E100C20MP11 | 27,200 | $1,360 |
| No | 205084959 | COLEMAN | CH16B4821 | CF60CXA2+TXV | TMLE100C20MP11 | 27,200 | $1,360 |
| No | 205084953 | COLEMAN | CH16B4821 | CF60CXA2+TXV | TM8E100C20MP11 | 27,200 | $1,360 |
| No | 205084947 | COLEMAN | CH16B4821 | CU60DXA2+TXV | TMLE100C20MP11 | 27,400 | $1,370 |
| No | 205084941 | COLEMAN | CH16B4821 | CM60DXA2+TXV | TMLE100C20MP11 | 27,400 | $1,370 |
| No | 205084935 | COLEMAN | CH16B4821 | CU60DXA2+TXV | TM8E100C20MP11 | 27,400 | $1,370 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205084930 | COLEMAN | CH16B4821 | CM60DXA2+TXV | TM8E100C20MP11 | 27,400 | $1,370 |
| No | 205084924 | COLEMAN | CH16B4821 | CF60DXA2+TXV | TMLE100C20MP11 | 27,400 | $1,370 |
| No | 205084918 | COLEMAN | CH16B4821 | CF60DXA2+TXV | TM8E100C20MP11 | 27,400 | $1,370 |
| No | 205546489 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 205546484 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 203431103 | COLEMAN | CH16B4821 | CM48DBCA1 | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 203431098 | COLEMAN | CH16B4821 | CM48DBCA1 | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 205546479 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 205546474 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 205546469 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 205546465 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 205084879 | COLEMAN | CH16B4821 | CU60CXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205084875 | COLEMAN | CH16B4821 | CM60CXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205084870 | COLEMAN | CH16B4821 | CU60CXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 205084864 | COLEMAN | CH16B4821 | CM60CXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 205084859 | COLEMAN | CH16B4821 | CF60CXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205084853 | COLEMAN | CH16B4821 | CF60CXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 205084847 | COLEMAN | CH16B4821 | CU60DXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205084841 | COLEMAN | CH16B4821 | CM60DXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205084835 | COLEMAN | CH16B4821 | CU60DXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 205084828 | COLEMAN | CH16B4821 | CM60DXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 205084822 | COLEMAN | CH16B4821 | CF60DXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205084816 | COLEMAN | CH16B4821 | CF60DXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 205546435 | COLEMAN | CH16B4821 | CM48DBCA1 | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 205546426 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 205546430 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 205546421 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 205084740 | COLEMAN | CH16B4821 | CU60CXA2+TXV | TM9E080C20MP12 | 27,200 | $1,360 |
| No | 205084735 | COLEMAN | CH16B4821 | CM60CXA2+TXV | TM9E080C20MP12 | 27,200 | $1,360 |
| No | 205084723 | COLEMAN | CH16B4821 | CU60DXA2+TXV | TM9E080C20MP12 | 27,600 | $1,380 |
| No | 205084729 | COLEMAN | CH16B4821 | CF60CXA2+TXV | TM9E080C20MP12 | 27,200 | $1,360 |
| No | 205084718 | COLEMAN | CH16B4821 | CM60DXA2+TXV | TM9E080C20MP12 | 27,600 | $1,380 |
| No | 205084712 | COLEMAN | CH16B4821 | CF60DXA2+TXV | TM9E080C20MP12 | 27,600 | $1,380 |
| No | 205546453 | COLEMAN | CH16B4821 | CM48DBCA1 | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205546449 | COLEMAN | CH16B4821 | CU48DXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205546444 | COLEMAN | CH16B4821 | CM48DXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205546439 | COLEMAN | CH16B4821 | CF48DXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205084705 | COLEMAN | CH16B4821 | CU60DXA2+TXV | TM9E100C16MP12 | 28,000 | $1,400 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205084700 | COLEMAN | CH16B4821 | CM60DXA2+TXV | TM9E100C16MP12 | 28,000 | $1,400 |
| No | 205084694 | COLEMAN | CH16B4821 | CF60DXA2+TXV | TM9E100C16MP12 | 28,000 | $1,400 |
| No | 205546460 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TM9E100C16MP12 | 28,800 | $1,440 |
| No | 205546319 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TM9E100C16MP12 | 28,800 | $1,440 |
| No | 205084689 | COLEMAN | CH16B4821 | CU60CXA2+TXV | TM9E100C20MP12 | 27,200 | $1,360 |
| No | 205084682 | COLEMAN | CH16B4821 | CM60CXA2+TXV | TM9E100C20MP12 | 27,200 | $1,360 |
| No | 205084677 | COLEMAN | CH16B4821 | CF60CXA2+TXV | TM9E100C20MP12 | 27,200 | $1,360 |
| No | 205546315 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TL8E100C20UH11 | 32,800 | $1,640 |
| No | 205546311 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TL8E100C20UH11 | 32,800 | $1,640 |
| No | 205546307 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TL9E100C20UH11 | 32,800 | $1,640 |
| No | 205546303 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TL9E100C20UH11 | 32,800 | $1,640 |
| No | 205546299 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TMLE080C20MP11 | 32,600 | $1,630 |
| No | 205546295 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TM8E080C20MP11 | 32,600 | $1,630 |
| No | 205546287 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TM8E080C20MP11 | 32,600 | $1,630 |
| No | 205546291 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TMLE080C20MP11 | 32,600 | $1,630 |
| No | 206782986 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TMLE120C16MP11 | 32,800 | $1,640 |
| No | 206782994 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TMLE120C16MP11 | 32,800 | $1,640 |
| No | 206782990 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TM8E120C16MP11 | 32,800 | $1,640 |
| No | 206782982 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TM8E120C16MP11 | 32,800 | $1,640 |
| No | 205546283 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TM9E080C20MP12 | 32,600 | $1,630 |
| No | 205546279 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TM9E080C20MP12 | 32,600 | $1,630 |
| No | 205546275 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TM9E100C20MP12 | 32,600 | $1,630 |
| No | 205546271 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TM9E100C20MP12 | 32,600 | $1,630 |
| No | 205546267 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TM9E120D20MP12 | 33,200 | $1,660 |
| No | 205546263 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TM9E120D20MP12 | 33,200 | $1,660 |
| No | 206838935 | COLEMAN | CH16B2421 | CM36AXA1+TXV | TPLC060A12MP13 | 15,000 | $750 |
| No | 206838931 | COLEMAN | CH16B2421 | CM36AXA1+TXV | TMLV060A12MP12 | 15,000 | $750 |
| No | 206838927 | COLEMAN | CH16B2421 | CM36AXA1+TXV | TM8V060A12MP12 | 15,000 | $750 |
| No | 206838923 | COLEMAN | CH16B2421 | CF36AXA1+TXV | TPLC060A12MP13 | 15,000 | $750 |
| No | 206838919 | COLEMAN | CH16B2421 | CF36AXA1+TXV | TMLV060A12MP12 | 15,000 | $750 |
| No | 206838915 | COLEMAN | CH16B2421 | CF36AXA1+TXV | TM8V060A12MP12 | 15,000 | $750 |
| No | 206779714 | COLEMAN | CH16B2421 | CU24BXA1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 206779710 | COLEMAN | CH16B2421 | CM24BBAA1 | TPLC080B12MP13 | 15,100 | $755 |
| No | 206779706 | COLEMAN | CH16B2421 | CM24BXA1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 202102052 | COLEMAN | CH16B2421 | CF24BBAA1 | TPLC080B12MP13 | 15,100 | $755 |
| No | 206780684 | COLEMAN | CH16B2421 | CU24BXA1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 206780680 | COLEMAN | CH16B2421 | CM24BBAA1 | TM8V080B12MP12 | 15,100 | $755 |
| No | 206780676 | COLEMAN | CH16B2421 | CM24BXA1+TXV | TM8V080B12MP12 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202102037 | COLEMAN | CH16B2421 | CF24BBAA1 | TM8V080B12MP12 | 15,100 | $755 |
| No | 206780653 | COLEMAN | CH16B2421 | CF24BXA1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 206780649 | COLEMAN | CH16B2421 | CF24BXA1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 206780592 | COLEMAN | CH16B2421 | CM36BBAA1 | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780588 | COLEMAN | CH16B2421 | CM36BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780596 | COLEMAN | CH16B2421 | CU36BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780584 | COLEMAN | CH16B2421 | CF36BBAA1 | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780580 | COLEMAN | CH16B2421 | CU36BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780576 | COLEMAN | CH16B2421 | CM36BBAA1 | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780572 | COLEMAN | CH16B2421 | CM36BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780568 | COLEMAN | CH16B2421 | CF36BBAA1 | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780563 | COLEMAN | CH16B2421 | CF36BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780559 | COLEMAN | CH16B2421 | CF36BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780557 | COLEMAN | CH16B2421 | CU36CXA1+TXV | CPLC100C16MP13 | 15,100 | $755 |
| No | 206780555 | COLEMAN | CH16B2421 | CM36CXA1+TXV | CPLC100C16MP13 | 15,100 | $755 |
| No | 206780553 | COLEMAN | CH16B2421 | CU36CXA1+TXV | CPLC080C16MP13 | 15,100 | $755 |
| No | 206780551 | COLEMAN | CH16B2421 | CM36CXA1+TXV | CPLC080C16MP13 | 15,100 | $755 |
| No | 206780547 | COLEMAN | CH16B2421 | CU36CXA1+TXV | TPLC100C16MP13 | 15,100 | $755 |
| No | 206780543 | COLEMAN | CH16B2421 | CM36CXA1+TXV | TPLC100C16MP13 | 15,100 | $755 |
| No | 206780539 | COLEMAN | CH16B2421 | CU36CXA1+TXV | TPLC080C16MP13 | 15,100 | $755 |
| No | 206780535 | COLEMAN | CH16B2421 | CM36CXA1+TXV | TPLC080C16MP13 | 15,100 | $755 |
| No | 206780531 | COLEMAN | CH16B2421 | CU36CXA1+TXV | TMLV100C16MP12 | 15,100 | $755 |
| No | 206780527 | COLEMAN | CH16B2421 | CM36CXA1+TXV | TMLV100C16MP12 | 15,100 | $755 |
| No | 206780523 | COLEMAN | CH16B2421 | CU36CXA1+TXV | TM8V080C16MP12 | 15,100 | $755 |
| No | 206780519 | COLEMAN | CH16B2421 | CM36CXA1+TXV | TM8V080C16MP12 | 15,100 | $755 |
| No | 206780515 | COLEMAN | CH16B2421 | CU36CXA1+TXV | TM8V100C16MP12 | 15,100 | $755 |
| No | 206780511 | COLEMAN | CH16B2421 | CM36CXA1+TXV | TM8V100C16MP12 | 15,100 | $755 |
| No | 206780509 | COLEMAN | CH16B2421 | CF36CXA1+TXV | CPLC100C16MP13 | 15,100 | $755 |
| No | 206780507 | COLEMAN | CH16B2421 | CF36CXA1+TXV | CPLC080C16MP13 | 15,100 | $755 |
| No | 206780503 | COLEMAN | CH16B2421 | CF36CXA1+TXV | TPLC100C16MP13 | 15,100 | $755 |
| No | 206780495 | COLEMAN | CH16B2421 | CF36CXA1+TXV | TMLV100C16MP12 | 15,100 | $755 |
| No | 206780499 | COLEMAN | CH16B2421 | CF36CXA1+TXV | TPLC080C16MP13 | 15,100 | $755 |
| No | 206780487 | COLEMAN | CH16B2421 | CF36CXA1+TXV | TM8V100C16MP12 | 15,100 | $755 |
| No | 205545606 | COLEMAN | CH16B2421 | CU30BXA1+TXV | TM9Y060B12MP11 | 15,300 | $765 |
| No | 206780491 | COLEMAN | CH16B2421 | CF36CXA1+TXV | TM8V080C16MP12 | 15,100 | $755 |
| No | 205545597 | COLEMAN | CH16B2421 | CM30BBAA1 | TM9Y060B12MP11 | 15,300 | $765 |
| No | 205545590 | COLEMAN | CH16B2421 | CM30BXA1+TXV | TM9Y060B12MP11 | 15,300 | $765 |
| No | 205545582 | COLEMAN | CH16B2421 | CF30BBAA1 | TM9Y060B12MP11 | 15,300 | $765 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205545537 | COLEMAN | CH16B2421 | CF30BXA1+TXV | TM9Y060B12MP11 | 15,300 | $765 |
| No | 205074542 | COLEMAN | CH16B2421 | CM30AXA1+TXV | TM9V040A10MP12 | 15,100 | $755 |
| No | 202143777 | COLEMAN | CH16B2421 | CF30ABAA1 | TM9V040A10MP12 | 15,100 | $755 |
| No | 205074537 | COLEMAN | CH16B2421 | CF30AXA1+TXV | TM9V040A10MP12 | 15,100 | $755 |
| No | 205546395 | COLEMAN | CH16B2421 | CM36AXA1+TXV | TM9V040A10MP12 | 15,000 | $750 |
| No | 205546391 | COLEMAN | CH16B2421 | CF36AXA1+TXV | TM9V040A10MP12 | 15,000 | $750 |
| No | 206780079 | COLEMAN | CH16B2421 | CM24BBAA1 | CP9C060B12MP13 | 15,200 | $760 |
| No | 206780081 | COLEMAN | CH16B2421 | CU24BXA1+TXV | CP9C060B12MP13 | 15,200 | $760 |
| No | 206780077 | COLEMAN | CH16B2421 | CM24BXA1+TXV | CP9C060B12MP13 | 15,200 | $760 |
| No | 202101779 | COLEMAN | CH16B2421 | CF24BBAA1 | CP9C060B12MP13 | 15,200 | $760 |
| No | 206780143 | COLEMAN | CH16B2421 | CU24BXA1+TXV | TP9C060B12MP13 | 15,200 | $760 |
| No | 206780135 | COLEMAN | CH16B2421 | CM24BXA1+TXV | TP9C060B12MP13 | 15,200 | $760 |
| No | 202101774 | COLEMAN | CH16B2421 | CF24BBAA1 | TP9C060B12MP13 | 15,200 | $760 |
| No | 206780139 | COLEMAN | CH16B2421 | CM24BBAA1 | TP9C060B12MP13 | 15,200 | $760 |
| No | 206780131 | COLEMAN | CH16B2421 | CU24BXA1+TXV | TM9V060B12MP12 | 15,200 | $760 |
| No | 206780127 | COLEMAN | CH16B2421 | CM24BBAA1 | TM9V060B12MP12 | 15,200 | $760 |
| No | 206780123 | COLEMAN | CH16B2421 | CM24BXA1+TXV | TM9V060B12MP12 | 15,200 | $760 |
| No | 202101770 | COLEMAN | CH16B2421 | CF24BBAA1 | TM9V060B12MP12 | 15,200 | $760 |
| No | 206780051 | COLEMAN | CH16B2421 | CF24BXA1+TXV | CP9C060B12MP13 | 15,200 | $760 |
| No | 206780047 | COLEMAN | CH16B2421 | CF24BXA1+TXV | TP9C060B12MP13 | 15,200 | $760 |
| No | 206780043 | COLEMAN | CH16B2421 | CF24BXA1+TXV | TM9V060B12MP12 | 15,200 | $760 |
| No | 206780041 | COLEMAN | CH16B2421 | CU30BXA1+TXV | CP9C060B12MP13 | 15,400 | $770 |
| No | 206780039 | COLEMAN | CH16B2421 | CM30BBAA1 | CP9C060B12MP13 | 15,400 | $770 |
| No | 206780037 | COLEMAN | CH16B2421 | CM30BXA1+TXV | CP9C060B12MP13 | 15,400 | $770 |
| No | 206780031 | COLEMAN | CH16B2421 | CU30BXA1+TXV | TP9C060B12MP13 | 15,400 | $770 |
| No | 206780027 | COLEMAN | CH16B2421 | CM30BBAA1 | TP9C060B12MP13 | 15,400 | $770 |
| No | 206780023 | COLEMAN | CH16B2421 | CM30BXA1+TXV | TP9C060B12MP13 | 15,400 | $770 |
| No | 206780035 | COLEMAN | CH16B2421 | CF30BBAA1 | CP9C060B12MP13 | 15,400 | $770 |
| No | 206780019 | COLEMAN | CH16B2421 | CF30BBAA1 | TP9C060B12MP13 | 15,400 | $770 |
| No | 206780015 | COLEMAN | CH16B2421 | CU30BXA1+TXV | TM9V060B12MP12 | 15,400 | $770 |
| No | 206780011 | COLEMAN | CH16B2421 | CM30BBAA1 | TM9V060B12MP12 | 15,400 | $770 |
| No | 206780007 | COLEMAN | CH16B2421 | CM30BXA1+TXV | TM9V060B12MP12 | 15,400 | $770 |
| No | 206780003 | COLEMAN | CH16B2421 | CF30BBAA1 | TM9V060B12MP12 | 15,400 | $770 |
| No | 206780001 | COLEMAN | CH16B2421 | CF30BXA1+TXV | CP9C060B12MP13 | 15,400 | $770 |
| No | 206779993 | COLEMAN | CH16B2421 | CF30BXA1+TXV | TM9V060B12MP12 | 15,400 | $770 |
| No | 206779997 | COLEMAN | CH16B2421 | CF30BXA1+TXV | TP9C060B12MP13 | 15,400 | $770 |
| No | 206780674 | COLEMAN | CH16B2421 | CU24BXA1+TXV | CP9C080B12MP13 | 15,000 | $750 |
| No | 206780672 | COLEMAN | CH16B2421 | CM24BBAA1 | CP9C080B12MP13 | 15,000 | $750 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780670 | COLEMAN | CH16B2421 | CM24BXA1+TXV | CP9C080B12MP13 | 15,000 | $750 |
| No | 202102057 | COLEMAN | CH16B2421 | CF24BBAA1 | CP9C080B12MP13 | 15,000 | $750 |
| No | 206780666 | COLEMAN | CH16B2421 | CU24BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780662 | COLEMAN | CH16B2421 | CM24BBAA1 | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780658 | COLEMAN | CH16B2421 | CM24BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 202102048 | COLEMAN | CH16B2421 | CF24BBAA1 | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780467 | COLEMAN | CH16B2421 | CM24BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780475 | COLEMAN | CH16B2421 | CU24BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780471 | COLEMAN | CH16B2421 | CM24BBAA1 | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780419 | COLEMAN | CH16B2421 | CF24BXA1+TXV | CP9C080B12MP13 | 15,000 | $750 |
| No | 206780391 | COLEMAN | CH16B2421 | CM30BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780407 | COLEMAN | CH16B2421 | CM30BBAA1 | CP9C080B12MP13 | 15,000 | $750 |
| No | 206780415 | COLEMAN | CH16B2421 | CF24BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780395 | COLEMAN | CH16B2421 | CM30BBAA1 | TP9C080B12MP13 | 15,000 | $750 |
| No | 202102043 | COLEMAN | CH16B2421 | CF24BBAA1 | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780383 | COLEMAN | CH16B2421 | CU30BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780379 | COLEMAN | CH16B2421 | CM30BBAA1 | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780411 | COLEMAN | CH16B2421 | CF24BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780403 | COLEMAN | CH16B2421 | CF30BBAA1 | CP9C080B12MP13 | 15,000 | $750 |
| No | 206780387 | COLEMAN | CH16B2421 | CF30BBAA1 | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780409 | COLEMAN | CH16B2421 | CU30BXA1+TXV | CP9C080B12MP13 | 15,000 | $750 |
| No | 206780399 | COLEMAN | CH16B2421 | CU30BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780405 | COLEMAN | CH16B2421 | CM30BXA1+TXV | CP9C080B12MP13 | 15,000 | $750 |
| No | 206780375 | COLEMAN | CH16B2421 | CM30BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780371 | COLEMAN | CH16B2421 | CF30BBAA1 | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780369 | COLEMAN | CH16B2421 | CF30BXA1+TXV | CP9C080B12MP13 | 15,000 | $750 |
| No | 206780361 | COLEMAN | CH16B2421 | CF30BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780359 | COLEMAN | CH16B2421 | CU36BXA1+TXV | CP9C080B12MP13 | 15,100 | $755 |
| No | 206780357 | COLEMAN | CH16B2421 | CM36BBAA1 | CP9C080B12MP13 | 15,100 | $755 |
| No | 206780365 | COLEMAN | CH16B2421 | CF30BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780355 | COLEMAN | CH16B2421 | CM36BXA1+TXV | CP9C080B12MP13 | 15,100 | $755 |
| No | 206780353 | COLEMAN | CH16B2421 | CF36BBAA1 | CP9C080B12MP13 | 15,100 | $755 |
| No | 206780349 | COLEMAN | CH16B2421 | CU36BXA1+TXV | TP9C080B12MP13 | 15,100 | $755 |
| No | 206780341 | COLEMAN | CH16B2421 | CM36BXA1+TXV | TP9C080B12MP13 | 15,100 | $755 |
| No | 206780337 | COLEMAN | CH16B2421 | CF36BBAA1 | TP9C080B12MP13 | 15,100 | $755 |
| No | 206780345 | COLEMAN | CH16B2421 | CM36BBAA1 | TP9C080B12MP13 | 15,100 | $755 |
| No | 206780333 | COLEMAN | CH16B2421 | CU36BXA1+TXV | TM9V080B12MP12 | 15,100 | $755 |
| No | 206780329 | COLEMAN | CH16B2421 | CM36BBAA1 | TM9V080B12MP12 | 15,100 | $755 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780325 | COLEMAN | CH16B2421 | CM36BXA1+TXV | TM9V080B12MP12 | 15,100 | $755 |
| No | 206780321 | COLEMAN | CH16B2421 | CF36BBAA1 | TM9V080B12MP12 | 15,100 | $755 |
| No | 206780319 | COLEMAN | CH16B2421 | CF36BXA1+TXV | CP9C080B12MP13 | 15,100 | $755 |
| No | 206780315 | COLEMAN | CH16B2421 | CF36BXA1+TXV | TP9C080B12MP13 | 15,100 | $755 |
| No | 206780311 | COLEMAN | CH16B2421 | CF36BXA1+TXV | TM9V080B12MP12 | 15,100 | $755 |
| No | 206779941 | COLEMAN | CH16B2421 | CU36CXA1+TXV | CP9C080C16MP13 | 15,100 | $755 |
| No | 206779939 | COLEMAN | CH16B2421 | CM36CXA1+TXV | CP9C080C16MP13 | 15,100 | $755 |
| No | 206779935 | COLEMAN | CH16B2421 | CU36CXA1+TXV | TP9C080C16MP13 | 15,100 | $755 |
| No | 206779931 | COLEMAN | CH16B2421 | CM36CXA1+TXV | TP9C080C16MP13 | 15,100 | $755 |
| No | 206779927 | COLEMAN | CH16B2421 | CU36CXA1+TXV | TM9V080C16MP12 | 15,100 | $755 |
| No | 206779923 | COLEMAN | CH16B2421 | CM36CXA1+TXV | TM9V080C16MP12 | 15,100 | $755 |
| No | 206779921 | COLEMAN | CH16B2421 | CF36CXA1+TXV | CP9C080C16MP13 | 15,100 | $755 |
| No | 206779917 | COLEMAN | CH16B2421 | CF36CXA1+TXV | TP9C080C16MP13 | 15,100 | $755 |
| No | 206779913 | COLEMAN | CH16B2421 | CF36CXA1+TXV | TM9V080C16MP12 | 15,100 | $755 |
| No | 206780461 | COLEMAN | CH16B2421 | CU36CXA1+TXV | CP9C100C16MP13 | 15,100 | $755 |
| No | 206780455 | COLEMAN | CH16B2421 | CU36CXA1+TXV | TP9C100C16MP13 | 15,100 | $755 |
| No | 206780451 | COLEMAN | CH16B2421 | CM36CXA1+TXV | TP9C100C16MP13 | 15,100 | $755 |
| No | 206780459 | COLEMAN | CH16B2421 | CM36CXA1+TXV | CP9C100C16MP13 | 15,100 | $755 |
| No | 206780443 | COLEMAN | CH16B2421 | CM36CXA1+TXV | TM9V100C16MP12 | 15,100 | $755 |
| No | 206780441 | COLEMAN | CH16B2421 | CF36CXA1+TXV | CP9C100C16MP13 | 15,100 | $755 |
| No | 206780447 | COLEMAN | CH16B2421 | CU36CXA1+TXV | TM9V100C16MP12 | 15,100 | $755 |
| No | 206780437 | COLEMAN | CH16B2421 | CF36CXA1+TXV | TP9C100C16MP13 | 15,100 | $755 |
| No | 206780433 | COLEMAN | CH16B2421 | CF36CXA1+TXV | TM9V100C16MP12 | 15,100 | $755 |
| No | 206782643 | COLEMAN | CH16B6021 | CM64DXA1+TXV | CP9C100C16MP13 | 32,600 | $1,630 |
| No | 206782639 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TP9C100C16MP13 | 32,600 | $1,630 |
| No | 206782635 | COLEMAN | CH16B6021 | CM64DXA1+TXV | TM9V100C16MP12 | 32,600 | $1,630 |
| No | 206782633 | COLEMAN | CH16B6021 | CF64DXA1+TXV | CP9C100C16MP13 | 32,600 | $1,630 |
| No | 206782629 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TP9C100C16MP13 | 32,600 | $1,630 |
| No | 206782625 | COLEMAN | CH16B6021 | CF64DXA1+TXV | TM9V100C16MP12 | 32,600 | $1,630 |
| No | 206781767 | COLEMAN | CH16B4821 | CM48DBCA1+MVC14DN21 | | 28,000 | $1,400 |
| No | 206781763 | COLEMAN | CH16B4821 | CM48DXA1+MVC14DN21+TXV | | 28,000 | $1,400 |
| No | 206781759 | COLEMAN | CH16B4821 | CF48DXA1+MVC14DN21+TXV | | 28,000 | $1,400 |
| No | 206781541 | COLEMAN | CH16B4821 | CM48DBCA1+MVC20DN21 | | 27,800 | $1,390 |
| No | 206781537 | COLEMAN | CH16B4821 | CM48DXA1+MVC20DN21+TXV | | 27,800 | $1,390 |
| No | 206781533 | COLEMAN | CH16B4821 | CF48DXA1+MVC20DN21+TXV | | 27,800 | $1,390 |
| No | 206781257 | COLEMAN | CH16B4821 | CM64DXA1+MVC20DN21+TXV | | 29,800 | $1,490 |
| No | 206781253 | COLEMAN | CH16B4821 | CF64DXA1+MVC20DN21+TXV | | 29,800 | $1,490 |
| No | 9036116 | COLEMAN | CH16B4821 | AVC48DX21+TXV | | 28,200 | $1,410 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781424 | COLEMAN | CH16B4821 | CM64DXA1+TXV | CPLC100C16MP13 | 29,000 | $1,450 |
| No | 206781422 | COLEMAN | CH16B4821 | CM64DXA1+TXV | CPLC080C16MP13 | 29,000 | $1,450 |
| No | 206781418 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TPLC100C16MP13 | 29,000 | $1,450 |
| No | 206781414 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TPLC080C16MP13 | 29,000 | $1,450 |
| No | 206781410 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TMLV100C16MP12 | 29,000 | $1,450 |
| No | 206781406 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TM8V080C16MP12 | 29,000 | $1,450 |
| No | 206781402 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TM8V100C16MP12 | 29,000 | $1,450 |
| No | 206781400 | COLEMAN | CH16B4821 | CF64DXA1+TXV | CPLC100C16MP13 | 29,000 | $1,450 |
| No | 206781398 | COLEMAN | CH16B4821 | CF64DXA1+TXV | CPLC080C16MP13 | 29,000 | $1,450 |
| No | 206781394 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TPLC100C16MP13 | 29,000 | $1,450 |
| No | 206781390 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TPLC080C16MP13 | 29,000 | $1,450 |
| No | 206781386 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TMLV100C16MP12 | 29,000 | $1,450 |
| No | 206781382 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TM8V080C16MP12 | 29,000 | $1,450 |
| No | 206781376 | COLEMAN | CH16B4821 | CU48CXA1+TXV | CPLC120C20MP13 | 28,000 | $1,400 |
| No | 206781374 | COLEMAN | CH16B4821 | CM48CBCA1 | CPLC120C20MP13 | 28,000 | $1,400 |
| No | 206781378 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TM8V100C16MP12 | 29,000 | $1,450 |
| No | 206781372 | COLEMAN | CH16B4821 | CM48CXA1+TXV | CPLC120C20MP13 | 28,000 | $1,400 |
| No | 202100772 | COLEMAN | CH16B4821 | CF48CBCA1 | CPLC120C20MP13 | 28,000 | $1,400 |
| No | 206781482 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TPLC120C20MP13 | 28,000 | $1,400 |
| No | 206781478 | COLEMAN | CH16B4821 | CM48CBCA1 | TPLC120C20MP13 | 28,000 | $1,400 |
| No | 206781474 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TPLC120C20MP13 | 28,000 | $1,400 |
| No | 202100750 | COLEMAN | CH16B4821 | CF48CBCA1 | TPLC120C20MP13 | 28,000 | $1,400 |
| No | 206781470 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TPLC100C20MP13 | 28,000 | $1,400 |
| No | 206781466 | COLEMAN | CH16B4821 | CM48CBCA1 | TPLC100C20MP13 | 28,000 | $1,400 |
| No | 206781462 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TPLC100C20MP13 | 28,000 | $1,400 |
| No | 202100749 | COLEMAN | CH16B4821 | CF48CBCA1 | TPLC100C20MP13 | 28,000 | $1,400 |
| No | 206781458 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TMLV120C20MP12 | 28,000 | $1,400 |
| No | 206781454 | COLEMAN | CH16B4821 | CM48CBCA1 | TMLV120C20MP12 | 28,000 | $1,400 |
| No | 206781450 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TMLV120C20MP12 | 28,000 | $1,400 |
| No | 202100710 | COLEMAN | CH16B4821 | CF48CBCA1 | TMLV120C20MP12 | 28,000 | $1,400 |
| No | 206781434 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TM8V100C20MP12 | 28,000 | $1,400 |
| No | 206781430 | COLEMAN | CH16B4821 | CM48CBCA1 | TM8V100C20MP12 | 28,000 | $1,400 |
| No | 206781426 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TM8V100C20MP12 | 28,000 | $1,400 |
| No | 202100669 | COLEMAN | CH16B4821 | CF48CBCA1 | TM8V100C20MP12 | 28,000 | $1,400 |
| No | 206781446 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TM8V120C20MP12 | 28,000 | $1,400 |
| No | 206781442 | COLEMAN | CH16B4821 | CM48CBCA1 | TM8V120C20MP12 | 28,000 | $1,400 |
| No | 202100670 | COLEMAN | CH16B4821 | CF48CBCA1 | TM8V120C20MP12 | 28,000 | $1,400 |
| No | 206781438 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TM8V120C20MP12 | 28,000 | $1,400 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781370 | COLEMAN | CH16B4821 | CF48CXA1+TXV | CPLC120C20MP13 | 28,000 | $1,400 |
| No | 206781365 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TPLC120C20MP13 | 28,000 | $1,400 |
| No | 206781361 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TPLC100C20MP13 | 28,000 | $1,400 |
| No | 206781357 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TMLV120C20MP12 | 28,000 | $1,400 |
| No | 206781353 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TM8V100C20MP12 | 28,000 | $1,400 |
| No | 206781349 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TM8V120C20MP12 | 28,000 | $1,400 |
| No | 206781707 | COLEMAN | CH16B4821 | CM64DXA1+TXV | CP9C100C16MP13 | 29,200 | $1,460 |
| No | 206781703 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TP9C100C16MP13 | 29,200 | $1,460 |
| No | 206781699 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TM9V100C16MP12 | 29,200 | $1,460 |
| No | 206781697 | COLEMAN | CH16B4821 | CF64DXA1+TXV | CP9C100C16MP13 | 29,200 | $1,460 |
| No | 206781693 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TP9C100C16MP13 | 29,200 | $1,460 |
| No | 206781689 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TM9V100C16MP12 | 29,200 | $1,460 |
| No | 206782553 | COLEMAN | CH16B4821 | CU48CXA1+TXV | CP9C100C20MP13 | 28,400 | $1,420 |
| No | 206782551 | COLEMAN | CH16B4821 | CM48CBCA1 | CP9C100C20MP13 | 28,400 | $1,420 |
| No | 202100763 | COLEMAN | CH16B4821 | CF48CBCA1 | CP9C100C20MP13 | 28,400 | $1,420 |
| No | 206782549 | COLEMAN | CH16B4821 | CM48CXA1+TXV | CP9C100C20MP13 | 28,400 | $1,420 |
| No | 206782545 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TP9C100C20MP13 | 28,400 | $1,420 |
| No | 206782541 | COLEMAN | CH16B4821 | CM48CBCA1 | TP9C100C20MP13 | 28,400 | $1,420 |
| No | 206782537 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TP9C100C20MP13 | 28,400 | $1,420 |
| No | 206782533 | COLEMAN | CH16B4821 | CU48CXA1+TXV | TM9V100C20MP12 | 28,400 | $1,420 |
| No | 202100732 | COLEMAN | CH16B4821 | CF48CBCA1 | TP9C100C20MP13 | 28,400 | $1,420 |
| No | 206782529 | COLEMAN | CH16B4821 | CM48CBCA1 | TM9V100C20MP12 | 28,400 | $1,420 |
| No | 206782525 | COLEMAN | CH16B4821 | CM48CXA1+TXV | TM9V100C20MP12 | 28,400 | $1,420 |
| No | 202100691 | COLEMAN | CH16B4821 | CF48CBCA1 | TM9V100C20MP12 | 28,400 | $1,420 |
| No | 206782523 | COLEMAN | CH16B4821 | CF48CXA1+TXV | CP9C100C20MP13 | 28,400 | $1,420 |
| No | 206782515 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TM9V100C20MP12 | 28,400 | $1,420 |
| No | 206781523 | COLEMAN | CH16B4821 | CM64DXA1+TXV | CP9C100C20MP13 | 29,000 | $1,450 |
| No | 206782519 | COLEMAN | CH16B4821 | CF48CXA1+TXV | TP9C100C20MP13 | 28,400 | $1,420 |
| No | 206781519 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TP9C100C20MP13 | 29,000 | $1,450 |
| No | 206781515 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TM9V100C20MP12 | 29,000 | $1,450 |
| No | 206781513 | COLEMAN | CH16B4821 | CF64DXA1+TXV | CP9C100C20MP13 | 29,000 | $1,450 |
| No | 206781509 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TP9C100C20MP13 | 29,000 | $1,450 |
| No | 206781505 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TM9V100C20MP12 | 29,000 | $1,450 |
| No | 205545155 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TM8Y080C16MP11 | 29,400 | $1,470 |
| No | 205545148 | COLEMAN | CH16B4821 | CM64DXA1+TXV | TM8Y100C16MP11 | 29,400 | $1,470 |
| No | 205545106 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TM8Y080C16MP11 | 29,400 | $1,470 |
| No | 205545099 | COLEMAN | CH16B4821 | CF64DXA1+TXV | TM8Y100C16MP11 | 29,400 | $1,470 |
| No | 206921731 | COLEMAN | HMH72B241 | CM36BXA1+TXV | TM9E040A10MP12 | 14,500 | $725 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921723 | COLEMAN | HMH72B241 | CF36BXA1+TXV | TM9E040A10MP12 | 14,500 | $725 |
| No | 206921727 | COLEMAN | HMH72B241 | CF36BBAA1 | TM9E040A10MP12 | 14,500 | $725 |
| No | 206921735 | COLEMAN | HMH72B241 | CM36BBAA1 | TM9E040A10MP12 | 14,500 | $725 |
| No | 206921739 | COLEMAN | HMH72B241 | CU36BXA1+TXV | TM9E040A10MP12 | 14,500 | $725 |
| No | 207335148 | COLEMAN | HMH72B241 | CF36BXA1+TXV | TM8Y060A12MP11 | 14,300 | $715 |
| No | 207335153 | COLEMAN | HMH72B241 | CF36AXA1+TXV | TM8Y060A12MP11 | 14,200 | $710 |
| No | 207335154 | COLEMAN | HMH72B241 | CM36AXA1+TXV | TM8Y060A12MP11 | 14,200 | $710 |
| No | 207335149 | COLEMAN | HMH72B241 | CF36BBAA1 | TM8Y060A12MP11 | 14,300 | $715 |
| No | 207335150 | COLEMAN | HMH72B241 | CM36BXA1+TXV | TM8Y060A12MP11 | 14,300 | $715 |
| No | 207335151 | COLEMAN | HMH72B241 | CM36BBAA1 | TM8Y060A12MP11 | 14,300 | $715 |
| No | 207335152 | COLEMAN | HMH72B241 | CU36BXA1+TXV | TM8Y060A12MP11 | 14,300 | $715 |
| No | 207175987 | COLEMAN | HMH72B241 | CF36CXA1+TXV | TM9Y060B12MP11 | 14,500 | $725 |
| No | 207175991 | COLEMAN | HMH72B241 | CM36CXA1+TXV | TM9Y060B12MP11 | 14,500 | $725 |
| No | 206921615 | COLEMAN | HMH72B241 | CF36CXA1+TXV | TM9V060B12MP12 | 14,500 | $725 |
| No | 206921619 | COLEMAN | HMH72B241 | CF36CXA1+TXV | TP9C060B12MP13 | 14,500 | $725 |
| No | 206921623 | COLEMAN | HMH72B241 | CF36CXA1+TXV | CP9C060B12MP13 | 14,500 | $725 |
| No | 206921625 | COLEMAN | HMH72B241 | CM36CXA1+TXV | TM9V060B12MP12 | 14,500 | $725 |
| No | 206921633 | COLEMAN | HMH72B241 | CM36CXA1+TXV | TP9C060B12MP13 | 14,500 | $725 |
| No | 206921641 | COLEMAN | HMH72B241 | CM36CXA1+TXV | CP9C060B12MP13 | 14,500 | $725 |
| No | 207335160 | COLEMAN | HMH72B241 | CF36CXA1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207335159 | COLEMAN | HMH72B241 | CM36BBAA1 | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207335161 | COLEMAN | HMH72B241 | CM36CXA1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207335156 | COLEMAN | HMH72B241 | CF36BXA1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207335157 | COLEMAN | HMH72B241 | CF36BBAA1 | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207335155 | COLEMAN | HMH72B241 | CU36BXA1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207335158 | COLEMAN | HMH72B241 | CM36BXA1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 206921565 | COLEMAN | HMH72B241 | CF36BXA1+TXV | TM9V080B12MP12 | 14,400 | $720 |
| No | 206921569 | COLEMAN | HMH72B241 | CF36BXA1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 206921573 | COLEMAN | HMH72B241 | CF36BXA1+TXV | CP9C080B12MP13 | 14,400 | $720 |
| No | 206921575 | COLEMAN | HMH72B241 | CF36BBAA1 | TM9V080B12MP12 | 14,400 | $720 |
| No | 206921579 | COLEMAN | HMH72B241 | CM36BXA1+TXV | TM9V080B12MP12 | 14,400 | $720 |
| No | 206921583 | COLEMAN | HMH72B241 | CM36BBAA1 | TM9V080B12MP12 | 14,400 | $720 |
| No | 206921587 | COLEMAN | HMH72B241 | CU36BXA1+TXV | TM9V080B12MP12 | 14,400 | $720 |
| No | 206921591 | COLEMAN | HMH72B241 | CF36BBAA1 | TP9C080B12MP13 | 14,400 | $720 |
| No | 206921595 | COLEMAN | HMH72B241 | CM36BXA1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 206921599 | COLEMAN | HMH72B241 | CM36BBAA1 | TP9C080B12MP13 | 14,400 | $720 |
| No | 206921603 | COLEMAN | HMH72B241 | CU36BXA1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 206921607 | COLEMAN | HMH72B241 | CF36BBAA1 | CP9C080B12MP13 | 14,400 | $720 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921609 | COLEMAN | HMH72B241 | CM36BXA1+TXV | CP9C080B12MP13 | 14,400 | $720 |
| No | 206921611 | COLEMAN | HMH72B241 | CM36BBAA1 | CP9C080B12MP13 | 14,400 | $720 |
| No | 207251157 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TM9E100C16MP12 | 31,000 | $1,550 |
| No | 206921613 | COLEMAN | HMH72B241 | CU36BXA1+TXV | CP9C080B12MP13 | 14,400 | $720 |
| No | 207251159 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TM9E100C16MP12 | 31,000 | $1,550 |
| No | 206971542 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TP9C080C16MP13 | 30,800 | $1,540 |
| No | 206971538 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TM9V080C16MP12 | 30,800 | $1,540 |
| No | 206971546 | COLEMAN | HMH72B481 | CF64DXA1+TXV | CP9C080C16MP13 | 30,800 | $1,540 |
| No | 206971548 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TM9V080C16MP12 | 30,800 | $1,540 |
| No | 206971552 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TP9C080C16MP13 | 30,800 | $1,540 |
| No | 206971556 | COLEMAN | HMH72B481 | CM64DXA1+TXV | CP9C080C16MP13 | 30,800 | $1,540 |
| No | 207176155 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TM9Y100C16MP11 | 30,200 | $1,510 |
| No | 207176159 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TM9Y100C16MP11 | 30,200 | $1,510 |
| No | 206921535 | COLEMAN | HMH72B241 | CF36CXA1+TXV | TM9V080B12MP12 | 14,300 | $715 |
| No | 206921539 | COLEMAN | HMH72B241 | CF36CXA1+TXV | TP9C080B12MP13 | 14,300 | $715 |
| No | 206921543 | COLEMAN | HMH72B241 | CF36CXA1+TXV | CP9C080B12MP13 | 14,300 | $715 |
| No | 206921545 | COLEMAN | HMH72B241 | CM36CXA1+TXV | TM9V080B12MP12 | 14,300 | $715 |
| No | 206921553 | COLEMAN | HMH72B241 | CM36CXA1+TXV | TP9C080B12MP13 | 14,300 | $715 |
| No | 206921561 | COLEMAN | HMH72B241 | CM36CXA1+TXV | CP9C080B12MP13 | 14,300 | $715 |
| No | 207251161 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TM9E080C16MP12 | 31,200 | $1,560 |
| No | 206971668 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TL9E080C16UH11 | 29,600 | $1,480 |
| No | 207251163 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TM9E080C16MP12 | 31,200 | $1,560 |
| No | 206971672 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TL9E080C16UH11 | 29,600 | $1,480 |
| No | 206921779 | COLEMAN | HMH72B241 | CF36CXA1+TXV | TM8V100C16MP12 | 14,300 | $715 |
| No | 206921795 | COLEMAN | HMH72B241 | CF36CXA1+TXV | TPLC100C16MP13 | 14,300 | $715 |
| No | 206921783 | COLEMAN | HMH72B241 | CF36CXA1+TXV | TM8V080C16MP12 | 14,300 | $715 |
| No | 206921799 | COLEMAN | HMH72B241 | CF36CXA1+TXV | CPLC080C16MP13 | 14,300 | $715 |
| No | 206921787 | COLEMAN | HMH72B241 | CF36CXA1+TXV | TMLV100C16MP12 | 14,300 | $715 |
| No | 206921791 | COLEMAN | HMH72B241 | CF36CXA1+TXV | TPLC080C16MP13 | 14,300 | $715 |
| No | 206921801 | COLEMAN | HMH72B241 | CF36CXA1+TXV | CPLC100C16MP13 | 14,300 | $715 |
| No | 206921803 | COLEMAN | HMH72B241 | CM36CXA1+TXV | TM8V100C16MP12 | 14,300 | $715 |
| No | 206921811 | COLEMAN | HMH72B241 | CM36CXA1+TXV | TM8V080C16MP12 | 14,300 | $715 |
| No | 206921819 | COLEMAN | HMH72B241 | CM36CXA1+TXV | TMLV100C16MP12 | 14,300 | $715 |
| No | 206921827 | COLEMAN | HMH72B241 | CM36CXA1+TXV | TPLC080C16MP13 | 14,300 | $715 |
| No | 206921835 | COLEMAN | HMH72B241 | CM36CXA1+TXV | TPLC100C16MP13 | 14,300 | $715 |
| No | 206921843 | COLEMAN | HMH72B241 | CM36CXA1+TXV | CPLC080C16MP13 | 14,300 | $715 |
| No | 206921847 | COLEMAN | HMH72B241 | CM36CXA1+TXV | CPLC100C16MP13 | 14,300 | $715 |
| No | 207176163 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TM9Y080C16MP11 | 30,200 | $1,510 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207176167 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TM9Y080C16MP11 | 30,200 | $1,510 |
| No | 207335281 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TM8Y080C16MP11 | 30,200 | $1,510 |
| No | 206971704 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TMLE100C16MP11 | 30,200 | $1,510 |
| No | 207335282 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TM8Y080C16MP11 | 30,200 | $1,510 |
| No | 206971700 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TM8E100C16MP11 | 30,200 | $1,510 |
| No | 206971708 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TM8E100C16MP11 | 30,200 | $1,510 |
| No | 206971720 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TL8E080C16UH11 | 30,200 | $1,510 |
| No | 206971712 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TMLE100C16MP11 | 30,200 | $1,510 |
| No | 206971716 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TL8E080C16UH11 | 30,200 | $1,510 |
| No | 206971478 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TM9V100C16MP12 | 30,800 | $1,540 |
| No | 206971482 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TP9C100C16MP13 | 30,800 | $1,540 |
| No | 206971486 | COLEMAN | HMH72B481 | CF64DXA1+TXV | CP9C100C16MP13 | 30,800 | $1,540 |
| No | 206971488 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TM9V100C16MP12 | 30,800 | $1,540 |
| No | 206971492 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TP9C100C16MP13 | 30,800 | $1,540 |
| No | 206971496 | COLEMAN | HMH72B481 | CM64DXA1+TXV | CP9C100C16MP13 | 30,800 | $1,540 |
| No | 206971518 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TM9V100C20MP12 | 31,000 | $1,550 |
| No | 206971522 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TP9C100C20MP13 | 31,000 | $1,550 |
| No | 206971526 | COLEMAN | HMH72B481 | CF64DXA1+TXV | CP9C100C20MP13 | 31,000 | $1,550 |
| No | 206971528 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TM9V100C20MP12 | 31,000 | $1,550 |
| No | 206971532 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TP9C100C20MP13 | 31,000 | $1,550 |
| No | 206971536 | COLEMAN | HMH72B481 | CM64DXA1+TXV | CP9C100C20MP13 | 31,000 | $1,550 |
| No | 206971684 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TM8E120C16MP11 | 30,200 | $1,510 |
| No | 206971688 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TMLE120C16MP11 | 30,200 | $1,510 |
| No | 206971692 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TM8E120C16MP11 | 30,200 | $1,510 |
| No | 206971696 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TMLE120C16MP11 | 30,200 | $1,510 |
| No | 206971652 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TM8E080C16MP11 | 30,200 | $1,510 |
| No | 206971656 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TMLE080C16MP11 | 30,200 | $1,510 |
| No | 206971660 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TM8E080C16MP11 | 30,200 | $1,510 |
| No | 206971664 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TMLE080C16MP11 | 30,200 | $1,510 |
| No | 206971604 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TM8V100C16MP12 | 29,600 | $1,480 |
| No | 206971608 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TM8V080C16MP12 | 29,600 | $1,480 |
| No | 206971612 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TMLV100C16MP12 | 29,600 | $1,480 |
| No | 206971616 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TPLC080C16MP13 | 29,600 | $1,480 |
| No | 206971620 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TPLC100C16MP13 | 29,600 | $1,480 |
| No | 206971632 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TM8V080C16MP12 | 29,600 | $1,480 |
| No | 206971624 | COLEMAN | HMH72B481 | CF64DXA1+TXV | CPLC080C16MP13 | 29,600 | $1,480 |
| No | 206971626 | COLEMAN | HMH72B481 | CF64DXA1+TXV | CPLC100C16MP13 | 29,600 | $1,480 |
| No | 206971628 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TM8V100C16MP12 | 29,600 | $1,480 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206971636 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TMLV100C16MP12 | 29,600 | $1,480 |
| No | 206971640 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TPLC080C16MP13 | 29,600 | $1,480 |
| No | 206971644 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TPLC100C16MP13 | 29,600 | $1,480 |
| No | 206971648 | COLEMAN | HMH72B481 | CM64DXA1+TXV | CPLC080C16MP13 | 29,600 | $1,480 |
| No | 206971650 | COLEMAN | HMH72B481 | CM64DXA1+TXV | CPLC100C16MP13 | 29,600 | $1,480 |
| No | 207176147 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TM9Y120D20MP11 | 30,600 | $1,530 |
| No | 207176151 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TM9Y120D20MP11 | 30,600 | $1,530 |
| No | 207335284 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TM8Y120C20MP11 | 29,800 | $1,490 |
| No | 206971558 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TM8V120C20MP12 | 29,800 | $1,490 |
| No | 207335285 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TM8Y100C20MP11 | 29,800 | $1,490 |
| No | 207335283 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TM8Y120C20MP11 | 29,800 | $1,490 |
| No | 207335286 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TM8Y100C20MP11 | 29,800 | $1,490 |
| No | 206971562 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TM8V100C20MP12 | 29,800 | $1,490 |
| No | 206971574 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TPLC120C20MP13 | 29,800 | $1,490 |
| No | 206971566 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TMLV120C20MP12 | 29,800 | $1,490 |
| No | 206971570 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TPLC100C20MP13 | 29,800 | $1,490 |
| No | 206971579 | COLEMAN | HMH72B481 | CF64DXA1+TXV | CPLC120C20MP13 | 29,800 | $1,490 |
| No | 206971581 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TM8V120C20MP12 | 29,800 | $1,490 |
| No | 206971585 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TM8V100C20MP12 | 29,800 | $1,490 |
| No | 206971589 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TMLV120C20MP12 | 29,800 | $1,490 |
| No | 206971593 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TPLC100C20MP13 | 29,800 | $1,490 |
| No | 206971502 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TP9C120D20MP13 | 30,800 | $1,540 |
| No | 206971597 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TPLC120C20MP13 | 29,800 | $1,490 |
| No | 206971602 | COLEMAN | HMH72B481 | CM64DXA1+TXV | CPLC120C20MP13 | 29,800 | $1,490 |
| No | 206971498 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TM9V120D20MP12 | 30,800 | $1,540 |
| No | 206971506 | COLEMAN | HMH72B481 | CF64DXA1+TXV | CP9C120D20MP13 | 30,800 | $1,540 |
| No | 206971508 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TM9V120D20MP12 | 30,800 | $1,540 |
| No | 206971512 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TP9C120D20MP13 | 30,800 | $1,540 |
| No | 206971516 | COLEMAN | HMH72B481 | CM64DXA1+TXV | CP9C120D20MP13 | 30,800 | $1,540 |
| No | 206971676 | COLEMAN | HMH72B481 | CF64DXA1+TXV | TL8E100C20UH11 | 30,000 | $1,500 |
| No | 206971680 | COLEMAN | HMH72B481 | CM64DXA1+TXV | TL8E100C20UH11 | 30,000 | $1,500 |
| No | 206922357 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 206922361 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 206922365 | COLEMAN | HMH72B361 | CF36CXA1+TXV | CP9C060B12MP13 | 25,000 | $1,250 |
| No | 206922367 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 206922371 | COLEMAN | HMH72B361 | CM36CBCA1 | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 206922527 | COLEMAN | HMH72B361 | CF36BBCA1 | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206922531 | COLEMAN | HMH72B361 | CM36BXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922535 | COLEMAN | HMH72B361 | CM36BBCA1 | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206922539 | COLEMAN | HMH72B361 | CU36BXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206922831 | COLEMAN | HMH72B361 | CF36BXA1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 206922835 | COLEMAN | HMH72B361 | CF36BXA1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 206922840 | COLEMAN | HMH72B361 | CF36BBCA1 | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 206922844 | COLEMAN | HMH72B361 | CM36BXA1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 206922848 | COLEMAN | HMH72B361 | CM36BBCA1 | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 206922856 | COLEMAN | HMH72B361 | CF36BBCA1 | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 206922852 | COLEMAN | HMH72B361 | CU36BXA1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 206922860 | COLEMAN | HMH72B361 | CM36BXA1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 206922864 | COLEMAN | HMH72B361 | CM36BBCA1 | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 206922868 | COLEMAN | HMH72B361 | CU36BXA1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 206922888 | COLEMAN | HMH72B361 | CF36BBCA1 | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 206922876 | COLEMAN | HMH72B361 | CF36BXA1+TXV | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 206922880 | COLEMAN | HMH72B361 | CF36BXA1+TXV | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 206922884 | COLEMAN | HMH72B361 | CF36BXA1+TXV | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 206922892 | COLEMAN | HMH72B361 | CM36BXA1+TXV | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 206922896 | COLEMAN | HMH72B361 | CM36BBCA1 | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 206922900 | COLEMAN | HMH72B361 | CU36BXA1+TXV | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 206922912 | COLEMAN | HMH72B361 | CM36BBCA1 | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 206922904 | COLEMAN | HMH72B361 | CF36BBCA1 | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 206922908 | COLEMAN | HMH72B361 | CM36BXA1+TXV | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 206922917 | COLEMAN | HMH72B361 | CU36BXA1+TXV | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 206922921 | COLEMAN | HMH72B361 | CF36BBCA1 | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 206922925 | COLEMAN | HMH72B361 | CM36BXA1+TXV | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 206922929 | COLEMAN | HMH72B361 | CM36BBCA1 | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 206922933 | COLEMAN | HMH72B361 | CU36BXA1+TXV | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 206923402 | COLEMAN | HMH72B361 | CF36AXA1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206923406 | COLEMAN | HMH72B361 | CM36AXA1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206923162 | COLEMAN | HMH72B361 | CF36BXA1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 206923166 | COLEMAN | HMH72B361 | CF36BXA1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 206923170 | COLEMAN | HMH72B361 | CF36BBCA1 | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 206923174 | COLEMAN | HMH72B361 | CM36BXA1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 206923178 | COLEMAN | HMH72B361 | CM36BBCA1 | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 206923182 | COLEMAN | HMH72B361 | CU36BXA1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 206923186 | COLEMAN | HMH72B361 | CF36BBCA1 | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 206923190 | COLEMAN | HMH72B361 | CM36BXA1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 206923194 | COLEMAN | HMH72B361 | CM36BBCA1 | TMLE080B12MP11 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206923198 | COLEMAN | HMH72B361 | CU36BXA1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 206923202 | COLEMAN | HMH72B361 | CF36BXA1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206923206 | COLEMAN | HMH72B361 | CF36BXA1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206923210 | COLEMAN | HMH72B361 | CF36BBCA1 | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206923214 | COLEMAN | HMH72B361 | CM36BXA1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206923218 | COLEMAN | HMH72B361 | CM36BBCA1 | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206923222 | COLEMAN | HMH72B361 | CU36BXA1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206923226 | COLEMAN | HMH72B361 | CF36BBCA1 | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206923230 | COLEMAN | HMH72B361 | CM36BXA1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206923234 | COLEMAN | HMH72B361 | CM36BBCA1 | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206923238 | COLEMAN | HMH72B361 | CU36BXA1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206923382 | COLEMAN | HMH72B361 | CF36BXA1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206923386 | COLEMAN | HMH72B361 | CF36BBCA1 | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206923390 | COLEMAN | HMH72B361 | CM36BXA1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206923394 | COLEMAN | HMH72B361 | CM36BBCA1 | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206923398 | COLEMAN | HMH72B361 | CU36BXA1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206922307 | COLEMAN | HMH72B361 | CF36BXA1+TXV | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 206922325 | COLEMAN | HMH72B361 | CM36BBCA1 | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 206922311 | COLEMAN | HMH72B361 | CF36BXA1+TXV | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922315 | COLEMAN | HMH72B361 | CF36BXA1+TXV | CP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922317 | COLEMAN | HMH72B361 | CF36BBCA1 | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 206922321 | COLEMAN | HMH72B361 | CM36BXA1+TXV | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 206922329 | COLEMAN | HMH72B361 | CU36BXA1+TXV | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 206922333 | COLEMAN | HMH72B361 | CF36BBCA1 | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922337 | COLEMAN | HMH72B361 | CM36BXA1+TXV | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922341 | COLEMAN | HMH72B361 | CM36BBCA1 | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922345 | COLEMAN | HMH72B361 | CU36BXA1+TXV | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922349 | COLEMAN | HMH72B361 | CF36BBCA1 | CP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922351 | COLEMAN | HMH72B361 | CM36BXA1+TXV | CP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922353 | COLEMAN | HMH72B361 | CM36BBCA1 | CP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922355 | COLEMAN | HMH72B361 | CU36BXA1+TXV | CP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922507 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206922511 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 207176075 | COLEMAN | HMH72B361 | CF36BXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 206922515 | COLEMAN | HMH72B361 | CM36CBCA1 | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 207176079 | COLEMAN | HMH72B361 | CF36BBCA1 | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 207176083 | COLEMAN | HMH72B361 | CM36BXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 207176087 | COLEMAN | HMH72B361 | CM36BBCA1 | TM9Y080B12MP11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207176091 | COLEMAN | HMH72B361 | CU36BXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 206923025 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923029 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923033 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923037 | COLEMAN | HMH72B361 | CM36CBCA1 | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923045 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923049 | COLEMAN | HMH72B361 | CM36CBCA1 | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 207176043 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TM9Y080C16MP11 | 24,600 | $1,230 |
| No | 207176047 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TM9Y080C16MP11 | 24,600 | $1,230 |
| No | 207176051 | COLEMAN | HMH72B361 | CM36CBCA1 | TM9Y080C16MP11 | 24,600 | $1,230 |
| No | 207176111 | COLEMAN | HMH72B361 | CF36BXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207176115 | COLEMAN | HMH72B361 | CF36BBCA1 | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207176119 | COLEMAN | HMH72B361 | CM36BXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207176123 | COLEMAN | HMH72B361 | CM36BBCA1 | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207176127 | COLEMAN | HMH72B361 | CU36BXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207335207 | COLEMAN | HMH72B361 | CF36BXA1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 207335208 | COLEMAN | HMH72B361 | CF36BBCA1 | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 207335209 | COLEMAN | HMH72B361 | CM36BXA1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 206922559 | COLEMAN | HMH72B361 | CF36BXA1+TXV | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 207335210 | COLEMAN | HMH72B361 | CM36BBCA1 | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 207335211 | COLEMAN | HMH72B361 | CU36BXA1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 206922563 | COLEMAN | HMH72B361 | CF36BBCA1 | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 206922567 | COLEMAN | HMH72B361 | CM36BXA1+TXV | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 206922571 | COLEMAN | HMH72B361 | CM36BBCA1 | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 206922575 | COLEMAN | HMH72B361 | CU36BXA1+TXV | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 206922795 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TM8V080B12MP12 | 24,400 | $1,220 |
| No | 206922799 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TPLC080B12MP13 | 24,400 | $1,220 |
| No | 206922804 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TM8V080B12MP12 | 24,400 | $1,220 |
| No | 206922816 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TPLC080B12MP13 | 24,400 | $1,220 |
| No | 206922808 | COLEMAN | HMH72B361 | CM36CBCA1 | TM8V080B12MP12 | 24,400 | $1,220 |
| No | 206922820 | COLEMAN | HMH72B361 | CM36CBCA1 | TPLC080B12MP13 | 24,400 | $1,220 |
| No | 206923057 | COLEMAN | HMH72B361 | CF36BXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923061 | COLEMAN | HMH72B361 | CF36BXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923065 | COLEMAN | HMH72B361 | CF36BBCA1 | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923069 | COLEMAN | HMH72B361 | CM36BXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923073 | COLEMAN | HMH72B361 | CM36BBCA1 | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923077 | COLEMAN | HMH72B361 | CU36BXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923082 | COLEMAN | HMH72B361 | CF36BBCA1 | TMLE100B12MP11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206923086 | COLEMAN | HMH72B361 | CM36BXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923090 | COLEMAN | HMH72B361 | CM36BBCA1 | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923094 | COLEMAN | HMH72B361 | CU36BXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923130 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TM8E080B12MP11 | 24,600 | $1,230 |
| No | 206923134 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 206923142 | COLEMAN | HMH72B361 | CM36CBCA1 | TM8E080B12MP11 | 24,600 | $1,230 |
| No | 206923138 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TM8E080B12MP11 | 24,600 | $1,230 |
| No | 206923150 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 206923154 | COLEMAN | HMH72B361 | CM36CBCA1 | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 206971312 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TM9V080C16MP12 | 38,000 | $1,900 |
| No | 206971316 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TP9C080C16MP13 | 38,000 | $1,900 |
| No | 206971320 | COLEMAN | HMH72B601 | CF64DXA1+TXV | CP9C080C16MP13 | 38,000 | $1,900 |
| No | 206971322 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TM9V080C16MP12 | 38,000 | $1,900 |
| No | 206971326 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TP9C080C16MP13 | 38,000 | $1,900 |
| No | 206971330 | COLEMAN | HMH72B601 | CM64DXA1+TXV | CP9C080C16MP13 | 38,000 | $1,900 |
| No | 207335213 | COLEMAN | HMH72B361 | CF36AXA1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 207335212 | COLEMAN | HMH72B361 | CM36AXA1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 206922447 | COLEMAN | HMH72B361 | CF36BXA1+TXV | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 206922451 | COLEMAN | HMH72B361 | CF36BBCA1 | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 206922455 | COLEMAN | HMH72B361 | CM36BXA1+TXV | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 206922459 | COLEMAN | HMH72B361 | CM36BBCA1 | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 206922463 | COLEMAN | HMH72B361 | CU36BXA1+TXV | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 206922599 | COLEMAN | HMH72B361 | CF36AXA1+TXV | TM9E060A10MP12 | 24,200 | $1,210 |
| No | 206922603 | COLEMAN | HMH72B361 | CM36AXA1+TXV | TM9E060A10MP12 | 24,200 | $1,210 |
| No | 206923298 | COLEMAN | HMH72B361 | CF36AXA1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206923302 | COLEMAN | HMH72B361 | CF36AXA1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 206923306 | COLEMAN | HMH72B361 | CM36AXA1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206923310 | COLEMAN | HMH72B361 | CM36AXA1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 207176095 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207176099 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207176103 | COLEMAN | HMH72B361 | CM36CBCA1 | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207335215 | COLEMAN | HMH72B361 | CF36BXA1+TXV | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 207335216 | COLEMAN | HMH72B361 | CF36BBCA1 | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 207335217 | COLEMAN | HMH72B361 | CM36BXA1+TXV | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 207335218 | COLEMAN | HMH72B361 | CM36BBCA1 | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 207335214 | COLEMAN | HMH72B361 | CU36BXA1+TXV | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 207176059 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 207176063 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207176067 | COLEMAN | HMH72B361 | CM36CBCA1 | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 206922227 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TM9V080C16MP12 | 24,400 | $1,220 |
| No | 206922231 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TP9C080C16MP13 | 24,400 | $1,220 |
| No | 206922249 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TP9C080C16MP13 | 24,400 | $1,220 |
| No | 206922235 | COLEMAN | HMH72B361 | CF36CXA1+TXV | CP9C080C16MP13 | 24,400 | $1,220 |
| No | 206922237 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TM9V080C16MP12 | 24,400 | $1,220 |
| No | 206922241 | COLEMAN | HMH72B361 | CM36CBCA1 | TM9V080C16MP12 | 24,400 | $1,220 |
| No | 206922253 | COLEMAN | HMH72B361 | CM36CBCA1 | TP9C080C16MP13 | 24,400 | $1,220 |
| No | 206922261 | COLEMAN | HMH72B361 | CM36CXA1+TXV | CP9C080C16MP13 | 24,400 | $1,220 |
| No | 206922263 | COLEMAN | HMH72B361 | CM36CBCA1 | CP9C080C16MP13 | 24,400 | $1,220 |
| No | 206922491 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TM9E080C16MP12 | 24,600 | $1,230 |
| No | 206922499 | COLEMAN | HMH72B361 | CM36CBCA1 | TM9E080C16MP12 | 24,600 | $1,230 |
| No | 206922495 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TM9E080C16MP12 | 24,600 | $1,230 |
| No | 206923314 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TL9E080C16UH11 | 24,600 | $1,230 |
| No | 206923318 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TL9E080C16UH11 | 24,600 | $1,230 |
| No | 206923322 | COLEMAN | HMH72B361 | CM36CBCA1 | TL9E080C16UH11 | 24,600 | $1,230 |
| No | 206922397 | COLEMAN | HMH72B361 | CF36BXA1+TXV | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 206922401 | COLEMAN | HMH72B361 | CF36BXA1+TXV | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922405 | COLEMAN | HMH72B361 | CF36BXA1+TXV | CP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922407 | COLEMAN | HMH72B361 | CF36BBCA1 | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 206922411 | COLEMAN | HMH72B361 | CM36BXA1+TXV | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 206922415 | COLEMAN | HMH72B361 | CM36BBCA1 | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 206922419 | COLEMAN | HMH72B361 | CU36BXA1+TXV | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 206922423 | COLEMAN | HMH72B361 | CF36BBCA1 | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922427 | COLEMAN | HMH72B361 | CM36BXA1+TXV | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922431 | COLEMAN | HMH72B361 | CM36BBCA1 | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922443 | COLEMAN | HMH72B361 | CM36BBCA1 | CP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922435 | COLEMAN | HMH72B361 | CU36BXA1+TXV | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922439 | COLEMAN | HMH72B361 | CF36BBCA1 | CP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922441 | COLEMAN | HMH72B361 | CM36BXA1+TXV | CP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922445 | COLEMAN | HMH72B361 | CU36BXA1+TXV | CP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922699 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 206922703 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TM8V080C16MP12 | 24,600 | $1,230 |
| No | 206922707 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TMLV100C16MP12 | 24,600 | $1,230 |
| No | 206922711 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TPLC080C16MP13 | 24,600 | $1,230 |
| No | 206922715 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 206922721 | COLEMAN | HMH72B361 | CF36CXA1+TXV | CPLC100C16MP13 | 24,600 | $1,230 |
| No | 206922719 | COLEMAN | HMH72B361 | CF36CXA1+TXV | CPLC080C16MP13 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922723 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 206922727 | COLEMAN | HMH72B361 | CM36CBCA1 | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 206922735 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TM8V080C16MP12 | 24,600 | $1,230 |
| No | 206922739 | COLEMAN | HMH72B361 | CM36CBCA1 | TM8V080C16MP12 | 24,600 | $1,230 |
| No | 206922747 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TMLV100C16MP12 | 24,600 | $1,230 |
| No | 206922751 | COLEMAN | HMH72B361 | CM36CBCA1 | TMLV100C16MP12 | 24,600 | $1,230 |
| No | 206922759 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TPLC080C16MP13 | 24,600 | $1,230 |
| No | 206922763 | COLEMAN | HMH72B361 | CM36CBCA1 | TPLC080C16MP13 | 24,600 | $1,230 |
| No | 206922783 | COLEMAN | HMH72B361 | CM36CXA1+TXV | CPLC080C16MP13 | 24,600 | $1,230 |
| No | 206922771 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 206922775 | COLEMAN | HMH72B361 | CM36CBCA1 | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 206922785 | COLEMAN | HMH72B361 | CM36CBCA1 | CPLC080C16MP13 | 24,600 | $1,230 |
| No | 206922789 | COLEMAN | HMH72B361 | CM36CXA1+TXV | CPLC100C16MP13 | 24,600 | $1,230 |
| No | 206923270 | COLEMAN | HMH72B361 | CM36BXA1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206923258 | COLEMAN | HMH72B361 | CF36BXA1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206922791 | COLEMAN | HMH72B361 | CM36CBCA1 | CPLC100C16MP13 | 24,600 | $1,230 |
| No | 206923262 | COLEMAN | HMH72B361 | CF36BXA1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 206923266 | COLEMAN | HMH72B361 | CF36BBCA1 | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206923274 | COLEMAN | HMH72B361 | CM36BBCA1 | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206923278 | COLEMAN | HMH72B361 | CU36BXA1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206923282 | COLEMAN | HMH72B361 | CF36BBCA1 | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 206923286 | COLEMAN | HMH72B361 | CM36BXA1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 206923290 | COLEMAN | HMH72B361 | CM36BBCA1 | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 206923294 | COLEMAN | HMH72B361 | CU36BXA1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 206923346 | COLEMAN | HMH72B361 | CF36BXA1+TXV | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 206923350 | COLEMAN | HMH72B361 | CF36BBCA1 | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 206923354 | COLEMAN | HMH72B361 | CM36BXA1+TXV | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 206923358 | COLEMAN | HMH72B361 | CM36BBCA1 | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 206923362 | COLEMAN | HMH72B361 | CU36BXA1+TXV | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 206922607 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TM8V120C20MP12 | 24,600 | $1,230 |
| No | 206922611 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TM8V100C20MP12 | 24,600 | $1,230 |
| No | 206922615 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TMLV120C20MP12 | 24,600 | $1,230 |
| No | 206922619 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TPLC100C20MP13 | 24,600 | $1,230 |
| No | 206922623 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TPLC120C20MP13 | 24,600 | $1,230 |
| No | 206922628 | COLEMAN | HMH72B361 | CF36CXA1+TXV | CPLC120C20MP13 | 24,600 | $1,230 |
| No | 206922630 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TM8V120C20MP12 | 24,600 | $1,230 |
| No | 206922634 | COLEMAN | HMH72B361 | CM36CBCA1 | TM8V120C20MP12 | 24,600 | $1,230 |
| No | 206922642 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TM8V100C20MP12 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922654 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TMLV120C20MP12 | 24,600 | $1,230 |
| No | 206922646 | COLEMAN | HMH72B361 | CM36CBCA1 | TM8V100C20MP12 | 24,600 | $1,230 |
| No | 206922658 | COLEMAN | HMH72B361 | CM36CBCA1 | TMLV120C20MP12 | 24,600 | $1,230 |
| No | 206922666 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TPLC100C20MP13 | 24,600 | $1,230 |
| No | 206922670 | COLEMAN | HMH72B361 | CM36CBCA1 | TPLC100C20MP13 | 24,600 | $1,230 |
| No | 206922678 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TPLC120C20MP13 | 24,600 | $1,230 |
| No | 206922682 | COLEMAN | HMH72B361 | CM36CBCA1 | TPLC120C20MP13 | 24,600 | $1,230 |
| No | 206922693 | COLEMAN | HMH72B361 | CM36CXA1+TXV | CPLC120C20MP13 | 24,600 | $1,230 |
| No | 206922695 | COLEMAN | HMH72B361 | CM36CBCA1 | CPLC120C20MP13 | 24,600 | $1,230 |
| No | 206922475 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TM9E100C16MP12 | 24,600 | $1,230 |
| No | 206922483 | COLEMAN | HMH72B361 | CM36CBCA1 | TM9E100C16MP12 | 24,600 | $1,230 |
| No | 206922479 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TM9E100C16MP12 | 24,600 | $1,230 |
| No | 207335310 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TM8Y080C16MP11 | 38,000 | $1,900 |
| No | 207335309 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TM8Y080C16MP11 | 38,000 | $1,900 |
| No | 206971404 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TL8E080C16UH11 | 38,000 | $1,900 |
| No | 207335220 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 206971408 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TL8E080C16UH11 | 38,000 | $1,900 |
| No | 207335219 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 206922267 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 207335221 | COLEMAN | HMH72B361 | CM36CBCA1 | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 206922271 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 206922275 | COLEMAN | HMH72B361 | CF36CXA1+TXV | CP9C080B12MP13 | 24,400 | $1,220 |
| No | 206922277 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 206922281 | COLEMAN | HMH72B361 | CM36CBCA1 | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 206922289 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 206922293 | COLEMAN | HMH72B361 | CM36CBCA1 | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 206922301 | COLEMAN | HMH72B361 | CM36CXA1+TXV | CP9C080B12MP13 | 24,400 | $1,220 |
| No | 206922303 | COLEMAN | HMH72B361 | CM36CBCA1 | CP9C080B12MP13 | 24,400 | $1,220 |
| No | 206922147 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TM9V100C20MP12 | 24,400 | $1,220 |
| No | 206922151 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TP9C100C20MP13 | 24,400 | $1,220 |
| No | 206922155 | COLEMAN | HMH72B361 | CF36CXA1+TXV | CP9C100C20MP13 | 24,400 | $1,220 |
| No | 206922157 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TM9V100C20MP12 | 24,400 | $1,220 |
| No | 206922161 | COLEMAN | HMH72B361 | CM36CBCA1 | TM9V100C20MP12 | 24,400 | $1,220 |
| No | 206922169 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TP9C100C20MP13 | 24,400 | $1,220 |
| No | 206922173 | COLEMAN | HMH72B361 | CM36CBCA1 | TP9C100C20MP13 | 24,400 | $1,220 |
| No | 206922181 | COLEMAN | HMH72B361 | CM36CXA1+TXV | CP9C100C20MP13 | 24,400 | $1,220 |
| No | 206922183 | COLEMAN | HMH72B361 | CM36CBCA1 | CP9C100C20MP13 | 24,400 | $1,220 |
| No | 206922961 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TM8E120C16MP11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922965 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TMLE120C16MP11 | 24,600 | $1,230 |
| No | 206922969 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TM8E120C16MP11 | 24,600 | $1,230 |
| No | 206922973 | COLEMAN | HMH72B361 | CM36CBCA1 | TM8E120C16MP11 | 24,600 | $1,230 |
| No | 206922981 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TMLE120C16MP11 | 24,600 | $1,230 |
| No | 206922985 | COLEMAN | HMH72B361 | CM36CBCA1 | TMLE120C16MP11 | 24,600 | $1,230 |
| No | 206923005 | COLEMAN | HMH72B361 | CM36CBCA1 | TM8E100C16MP11 | 24,600 | $1,230 |
| No | 206922993 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TM8E100C16MP11 | 24,600 | $1,230 |
| No | 206922997 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TMLE100C16MP11 | 24,600 | $1,230 |
| No | 206923001 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TM8E100C16MP11 | 24,600 | $1,230 |
| No | 206923013 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TMLE100C16MP11 | 24,600 | $1,230 |
| No | 206923017 | COLEMAN | HMH72B361 | CM36CBCA1 | TMLE100C16MP11 | 24,600 | $1,230 |
| No | 206971208 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TM9V100C20MP12 | 38,000 | $1,900 |
| No | 206971212 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TP9C100C20MP13 | 38,000 | $1,900 |
| No | 206971216 | COLEMAN | HMH72B601 | CF64DXA1+TXV | CP9C100C20MP13 | 38,000 | $1,900 |
| No | 206971218 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TM9V100C20MP12 | 38,000 | $1,900 |
| No | 206971222 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TP9C100C20MP13 | 38,000 | $1,900 |
| No | 206971304 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TM8E100C16MP11 | 38,000 | $1,900 |
| No | 206971226 | COLEMAN | HMH72B601 | CM64DXA1+TXV | CP9C100C20MP13 | 38,000 | $1,900 |
| No | 206971296 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TM8E100C16MP11 | 38,000 | $1,900 |
| No | 206971300 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TMLE100C16MP11 | 38,000 | $1,900 |
| No | 206971308 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TMLE100C16MP11 | 38,000 | $1,900 |
| No | 206971372 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TM8E080C16MP11 | 38,000 | $1,900 |
| No | 206971376 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TMLE080C16MP11 | 38,000 | $1,900 |
| No | 206971380 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TM8E080C16MP11 | 38,000 | $1,900 |
| No | 206971384 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TMLE080C16MP11 | 38,000 | $1,900 |
| No | 206922467 | COLEMAN | HMH72B361 | CF36AXA1+TXV | TM9V040A10MP12 | 24,000 | $1,200 |
| No | 206922471 | COLEMAN | HMH72B361 | CM36AXA1+TXV | TM9V040A10MP12 | 24,000 | $1,200 |
| No | 206922937 | COLEMAN | HMH72B361 | CF36AXA1+TXV | TM8V060A12MP12 | 24,200 | $1,210 |
| No | 206922941 | COLEMAN | HMH72B361 | CF36AXA1+TXV | TMLV060A12MP12 | 24,200 | $1,210 |
| No | 206922945 | COLEMAN | HMH72B361 | CF36AXA1+TXV | TPLC060A12MP13 | 24,200 | $1,210 |
| No | 206922949 | COLEMAN | HMH72B361 | CM36AXA1+TXV | TM8V060A12MP12 | 24,200 | $1,210 |
| No | 206922953 | COLEMAN | HMH72B361 | CM36AXA1+TXV | TMLV060A12MP12 | 24,200 | $1,210 |
| No | 206922957 | COLEMAN | HMH72B361 | CM36AXA1+TXV | TPLC060A12MP13 | 24,200 | $1,210 |
| No | 206922197 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TM9V100C16MP12 | 24,400 | $1,220 |
| No | 206922187 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TM9V100C16MP12 | 24,400 | $1,220 |
| No | 206922191 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TP9C100C16MP13 | 24,400 | $1,220 |
| No | 206922195 | COLEMAN | HMH72B361 | CF36CXA1+TXV | CP9C100C16MP13 | 24,400 | $1,220 |
| No | 206922209 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TP9C100C16MP13 | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922201 | COLEMAN | HMH72B361 | CM36CBCA1 | TM9V100C16MP12 | 24,400 | $1,220 |
| No | 206922213 | COLEMAN | HMH72B361 | CM36CBCA1 | TP9C100C16MP13 | 24,400 | $1,220 |
| No | 206922221 | COLEMAN | HMH72B361 | CM36CXA1+TXV | CP9C100C16MP13 | 24,400 | $1,220 |
| No | 206922223 | COLEMAN | HMH72B361 | CM36CBCA1 | CP9C100C16MP13 | 24,400 | $1,220 |
| No | 206971264 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TM8E120C16MP11 | 38,000 | $1,900 |
| No | 206971268 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TMLE120C16MP11 | 38,000 | $1,900 |
| No | 206971272 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TM8E120C16MP11 | 38,000 | $1,900 |
| No | 206971276 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TMLE120C16MP11 | 38,000 | $1,900 |
| No | 207176131 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TM9Y120D20MP11 | 38,000 | $1,900 |
| No | 207176135 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TM9Y120D20MP11 | 38,000 | $1,900 |
| No | 206923098 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TM8E080C16MP11 | 24,400 | $1,220 |
| No | 206923102 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TMLE080C16MP11 | 24,400 | $1,220 |
| No | 206923106 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TM8E080C16MP11 | 24,400 | $1,220 |
| No | 206923110 | COLEMAN | HMH72B361 | CM36CBCA1 | TM8E080C16MP11 | 24,400 | $1,220 |
| No | 206923118 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TMLE080C16MP11 | 24,400 | $1,220 |
| No | 206971228 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TM9V100C16MP12 | 38,000 | $1,900 |
| No | 206923122 | COLEMAN | HMH72B361 | CM36CBCA1 | TMLE080C16MP11 | 24,400 | $1,220 |
| No | 206971232 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TP9C100C16MP13 | 38,000 | $1,900 |
| No | 206971236 | COLEMAN | HMH72B601 | CF64DXA1+TXV | CP9C100C16MP13 | 38,000 | $1,900 |
| No | 206971238 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TM9V100C16MP12 | 38,000 | $1,900 |
| No | 206971242 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TP9C100C16MP13 | 38,000 | $1,900 |
| No | 206971246 | COLEMAN | HMH72B601 | CM64DXA1+TXV | CP9C100C16MP13 | 38,000 | $1,900 |
| No | 206971332 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TM9E120D20MP12 | 38,500 | $1,925 |
| No | 206971336 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TM9E120D20MP12 | 38,500 | $1,925 |
| No | 206971416 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TM8V100C20MP12 | 39,000 | $1,950 |
| No | 206971424 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TPLC100C20MP13 | 39,000 | $1,950 |
| No | 206971412 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TM8V120C20MP12 | 39,000 | $1,950 |
| No | 206971420 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TMLV120C20MP12 | 39,000 | $1,950 |
| No | 206971428 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TPLC120C20MP13 | 39,000 | $1,950 |
| No | 206971443 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TMLV120C20MP12 | 39,000 | $1,950 |
| No | 206971433 | COLEMAN | HMH72B601 | CF64DXA1+TXV | CPLC120C20MP13 | 39,000 | $1,950 |
| No | 206971435 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TM8V120C20MP12 | 39,000 | $1,950 |
| No | 206971439 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TM8V100C20MP12 | 39,000 | $1,950 |
| No | 206971456 | COLEMAN | HMH72B601 | CM64DXA1+TXV | CPLC120C20MP13 | 39,000 | $1,950 |
| No | 206971447 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TPLC100C20MP13 | 39,000 | $1,950 |
| No | 206971451 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TPLC120C20MP13 | 39,000 | $1,950 |
| No | 207176139 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TM9Y100C20MP11 | 38,000 | $1,900 |
| No | 207176143 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TM9Y100C20MP11 | 38,000 | $1,900 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206971280 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TM8E100C20MP11 | 38,500 | $1,925 |
| No | 206971284 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TMLE100C20MP11 | 38,500 | $1,925 |
| No | 206971288 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TM8E100C20MP11 | 38,500 | $1,925 |
| No | 206971292 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TMLE100C20MP11 | 38,500 | $1,925 |
| No | 207176027 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TM9Y100C16MP11 | 24,200 | $1,210 |
| No | 207176031 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TM9Y100C16MP11 | 24,200 | $1,210 |
| No | 207176035 | COLEMAN | HMH72B361 | CM36CBCA1 | TM9Y100C16MP11 | 24,200 | $1,210 |
| No | 206971388 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TL9E100C20UH11 | 38,000 | $1,900 |
| No | 206971392 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TL9E100C20UH11 | 38,000 | $1,900 |
| No | 206971340 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TM9E100C20MP12 | 38,500 | $1,925 |
| No | 206971344 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TM9E100C20MP12 | 38,500 | $1,925 |
| No | 206971396 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TL8E100C20UH11 | 38,000 | $1,900 |
| No | 206971400 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TL8E100C20UH11 | 38,000 | $1,900 |
| No | 206971348 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TM9E080C20MP12 | 38,500 | $1,925 |
| No | 206971196 | COLEMAN | HMH72B601 | CF64DXA1+TXV | CP9C120D20MP13 | 39,000 | $1,950 |
| No | 206971352 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TM9E080C20MP12 | 38,500 | $1,925 |
| No | 206971188 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TM9V120D20MP12 | 39,000 | $1,950 |
| No | 206971192 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TP9C120D20MP13 | 39,000 | $1,950 |
| No | 206971198 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TM9V120D20MP12 | 39,000 | $1,950 |
| No | 206971202 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TP9C120D20MP13 | 39,000 | $1,950 |
| No | 207335308 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TM8Y120C20MP11 | 37,800 | $1,890 |
| No | 206971206 | COLEMAN | HMH72B601 | CM64DXA1+TXV | CP9C120D20MP13 | 39,000 | $1,950 |
| No | 207335305 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TM8Y100C20MP11 | 37,800 | $1,890 |
| No | 207335307 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TM8Y120C20MP11 | 37,800 | $1,890 |
| No | 207335306 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TM8Y100C20MP11 | 37,800 | $1,890 |
| No | 206971248 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TM8E120C20MP11 | 37,600 | $1,880 |
| No | 206971252 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TMLE120C20MP11 | 37,600 | $1,880 |
| No | 206971256 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TM8E120C20MP11 | 37,600 | $1,880 |
| No | 206971260 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TMLE120C20MP11 | 37,600 | $1,880 |
| No | 207335204 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TM8Y080C16MP11 | 24,200 | $1,210 |
| No | 207335205 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TM8Y080C16MP11 | 24,200 | $1,210 |
| No | 207335206 | COLEMAN | HMH72B361 | CM36CBCA1 | TM8Y080C16MP11 | 24,200 | $1,210 |
| No | 206923366 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TL8E080C16UH11 | 24,000 | $1,200 |
| No | 206923370 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TL8E080C16UH11 | 24,000 | $1,200 |
| No | 206923374 | COLEMAN | HMH72B361 | CM36CBCA1 | TL8E080C16UH11 | 24,000 | $1,200 |
| No | 206971364 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TM8E080C20MP11 | 37,800 | $1,890 |
| No | 206971356 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TM8E080C20MP11 | 37,800 | $1,890 |
| No | 206971360 | COLEMAN | HMH72B601 | CF64DXA1+TXV | TMLE080C20MP11 | 37,800 | $1,890 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206971368 | COLEMAN | HMH72B601 | CM64DXA1+TXV | TMLE080C20MP11 | 37,800 | $1,890 |
| No | 206922379 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 206922383 | COLEMAN | HMH72B361 | CM36CBCA1 | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 206922393 | COLEMAN | HMH72B361 | CM36CBCA1 | CP9C060B12MP13 | 25,000 | $1,250 |
| No | 206922391 | COLEMAN | HMH72B361 | CM36CXA1+TXV | CP9C060B12MP13 | 25,000 | $1,250 |
| No | 206922543 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 206922547 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 206922551 | COLEMAN | HMH72B361 | CM36CBCA1 | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 206923330 | COLEMAN | HMH72B361 | CF36CXA1+TXV | TL9E060B12UH11 | 24,800 | $1,240 |
| No | 206923334 | COLEMAN | HMH72B361 | CM36CXA1+TXV | TL9E060B12UH11 | 24,800 | $1,240 |
| No | 206923338 | COLEMAN | HMH72B361 | CM36CBCA1 | TL9E060B12UH11 | 24,800 | $1,240 |
| No | 206922579 | COLEMAN | HMH72B361 | CF36BXA1+TXV | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 206922583 | COLEMAN | HMH72B361 | CF36BBCA1 | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 206922587 | COLEMAN | HMH72B361 | CM36BXA1+TXV | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 206922591 | COLEMAN | HMH72B361 | CM36BBCA1 | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 206922595 | COLEMAN | HMH72B361 | CU36BXA1+TXV | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 206923242 | COLEMAN | HMH72B361 | CF36AXA1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206923246 | COLEMAN | HMH72B361 | CF36AXA1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206923250 | COLEMAN | HMH72B361 | CM36AXA1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206923254 | COLEMAN | HMH72B361 | CM36AXA1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206922523 | COLEMAN | HMH72B361 | CF36BXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 207176107 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 206923506 | COLEMAN | HMH72B361 | AE36BX21+TXV | | 24,400 | $1,220 |
| No | 206971740 | COLEMAN | HMH72B481 | AVC60DX21+TXV | | 30,600 | $1,530 |
| No | 206971744 | COLEMAN | HMH72B481 | CF64DXA1+ME14DN21+TXV | | 30,000 | $1,500 |
| No | 206971748 | COLEMAN | HMH72B481 | CM64DXA1+ME14DN21+TXV | | 30,000 | $1,500 |
| No | 207175995 | COLEMAN | HMH72B241 | CU36CXA1+TXV | TM9Y060B12MP11 | 14,500 | $725 |
| No | 207176019 | COLEMAN | HMH72B241 | AE36BX21+TXV | | 14,300 | $715 |
| No | 207176023 | COLEMAN | HMH72B241 | AE36BBA21 | | 14,300 | $715 |
| No | 207176039 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TM9Y100C16MP11 | 24,200 | $1,210 |
| No | 207176055 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TM9Y080C16MP11 | 24,600 | $1,230 |
| No | 207176071 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 206922245 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TM9V080C16MP12 | 24,400 | $1,220 |
| No | 206922257 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TP9C080C16MP13 | 24,400 | $1,220 |
| No | 206922265 | COLEMAN | HMH72B361 | CU36CXA1+TXV | CP9C080C16MP13 | 24,400 | $1,220 |
| No | 206922285 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 206922297 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 206922305 | COLEMAN | HMH72B361 | CU36CXA1+TXV | CP9C080B12MP13 | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922375 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 206922387 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 206922395 | COLEMAN | HMH72B361 | CU36CXA1+TXV | CP9C060B12MP13 | 25,000 | $1,250 |
| No | 206922503 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TM9E080C16MP12 | 24,600 | $1,230 |
| No | 206923342 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TL9E060B12UH11 | 24,800 | $1,240 |
| No | 206923378 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TL8E080C16UH11 | 24,000 | $1,200 |
| No | 206923410 | COLEMAN | HMH72B361 | CF36CXA1+MVC16CN21+TXV | | 24,200 | $1,210 |
| No | 206923414 | COLEMAN | HMH72B361 | CM36CXA1+MVC16CN21+TXV | | 24,200 | $1,210 |
| No | 206923418 | COLEMAN | HMH72B361 | CM36CBCA1+MVC16CN21 | | 24,200 | $1,210 |
| No | 206923422 | COLEMAN | HMH72B361 | CF36CXA1+MVC12CN21+TXV | | 24,000 | $1,200 |
| No | 206923426 | COLEMAN | HMH72B361 | CM36CXA1+MVC12CN21+TXV | | 24,000 | $1,200 |
| No | 206923430 | COLEMAN | HMH72B361 | CM36CBCA1+MVC12CN21 | | 24,000 | $1,200 |
| No | 206921629 | COLEMAN | HMH72B241 | CU36CXA1+TXV | TM9V060B12MP12 | 14,500 | $725 |
| No | 206921637 | COLEMAN | HMH72B241 | CU36CXA1+TXV | TP9C060B12MP13 | 14,500 | $725 |
| No | 206921643 | COLEMAN | HMH72B241 | CU36CXA1+TXV | CP9C060B12MP13 | 14,500 | $725 |
| No | 206922127 | COLEMAN | HMH72B241 | AVC36BX21+TXV | | 14,300 | $715 |
| No | 206922638 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TM8V120C20MP12 | 24,600 | $1,230 |
| No | 206922650 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TM8V100C20MP12 | 24,600 | $1,230 |
| No | 206922662 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TMLV120C20MP12 | 24,600 | $1,230 |
| No | 206922674 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TPLC100C20MP13 | 24,600 | $1,230 |
| No | 206922686 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TPLC120C20MP13 | 24,600 | $1,230 |
| No | 206922697 | COLEMAN | HMH72B361 | CU36CXA1+TXV | CPLC120C20MP13 | 24,600 | $1,230 |
| No | 206922731 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 206922743 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TM8V080C16MP12 | 24,600 | $1,230 |
| No | 206922755 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TMLV100C16MP12 | 24,600 | $1,230 |
| No | 206922767 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TPLC080C16MP13 | 24,600 | $1,230 |
| No | 206922779 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 206922787 | COLEMAN | HMH72B361 | CU36CXA1+TXV | CPLC080C16MP13 | 24,600 | $1,230 |
| No | 206922793 | COLEMAN | HMH72B361 | CU36CXA1+TXV | CPLC100C16MP13 | 24,600 | $1,230 |
| No | 206922977 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TM8E120C16MP11 | 24,600 | $1,230 |
| No | 206922989 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TMLE120C16MP11 | 24,600 | $1,230 |
| No | 206923009 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TM8E100C16MP11 | 24,600 | $1,230 |
| No | 206923021 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TMLE100C16MP11 | 24,600 | $1,230 |
| No | 206923041 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923053 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923114 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TM8E080C16MP11 | 24,400 | $1,220 |
| No | 206923126 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TMLE080C16MP11 | 24,400 | $1,220 |
| No | 206923146 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TM8E080B12MP11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206923158 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 206923474 | COLEMAN | HMH72B361 | CF36BXA1+ME12BN21+TXV | | 24,400 | $1,220 |
| No | 206923478 | COLEMAN | HMH72B361 | CF36BBCA1+ME12BN21 | | 24,400 | $1,220 |
| No | 206923482 | COLEMAN | HMH72B361 | CM36BXA1+ME12BN21+TXV | | 24,400 | $1,220 |
| No | 206923486 | COLEMAN | HMH72B361 | CM36BBCA1+ME12BN21 | | 24,400 | $1,220 |
| No | 206923490 | COLEMAN | HMH72B361 | CF36BXA1+ME08BN21+TXV | | 23,600 | $1,180 |
| No | 206923494 | COLEMAN | HMH72B361 | CM36BXA1+ME08BN21+TXV | | 23,600 | $1,180 |
| No | 206924363 | COLEMAN | HMH72B361 | CF36BBCA1+ME08BN21 | | 23,600 | $1,180 |
| No | 206924367 | COLEMAN | HMH72B361 | CM36BBCA1+ME08BN21 | | 23,600 | $1,180 |
| No | 206923498 | COLEMAN | HMH72B361 | AVC36CX21+TXV | | 24,200 | $1,210 |
| No | 206923502 | COLEMAN | HMH72B361 | AVC36BX21+TXV | | 24,600 | $1,230 |
| No | 206921815 | COLEMAN | HMH72B241 | CU36CXA1+TXV | TM8V080C16MP12 | 14,300 | $715 |
| No | 206921807 | COLEMAN | HMH72B241 | CU36CXA1+TXV | TM8V100C16MP12 | 14,300 | $715 |
| No | 206921823 | COLEMAN | HMH72B241 | CU36CXA1+TXV | TMLV100C16MP12 | 14,300 | $715 |
| No | 206921831 | COLEMAN | HMH72B241 | CU36CXA1+TXV | TPLC080C16MP13 | 14,300 | $715 |
| No | 206921839 | COLEMAN | HMH72B241 | CU36CXA1+TXV | TPLC100C16MP13 | 14,300 | $715 |
| No | 206921845 | COLEMAN | HMH72B241 | CU36CXA1+TXV | CPLC080C16MP13 | 14,300 | $715 |
| No | 206922111 | COLEMAN | HMH72B241 | CM36CXA1+ME12CN21+TXV | | 14,200 | $710 |
| No | 206921849 | COLEMAN | HMH72B241 | CU36CXA1+TXV | CPLC100C16MP13 | 14,300 | $715 |
| No | 206922107 | COLEMAN | HMH72B241 | CF36CXA1+ME12CN21+TXV | | 14,200 | $710 |
| No | 206922165 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TM9V100C20MP12 | 24,400 | $1,220 |
| No | 206922177 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TP9C100C20MP13 | 24,400 | $1,220 |
| No | 206922185 | COLEMAN | HMH72B361 | CU36CXA1+TXV | CP9C100C20MP13 | 24,400 | $1,220 |
| No | 206922205 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TM9V100C16MP12 | 24,400 | $1,220 |
| No | 206922217 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TP9C100C16MP13 | 24,400 | $1,220 |
| No | 206922225 | COLEMAN | HMH72B361 | CU36CXA1+TXV | CP9C100C16MP13 | 24,400 | $1,220 |
| No | 206922487 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TM9E100C16MP12 | 24,600 | $1,230 |
| No | 206922519 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206922555 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 206923326 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TL9E080C16UH11 | 24,600 | $1,230 |
| No | 206923434 | COLEMAN | HMH72B361 | CF36BXA1+MVC12BN21+TXV | | 24,400 | $1,220 |
| No | 206923438 | COLEMAN | HMH72B361 | CF36BBCA1+MVC12BN21 | | 24,400 | $1,220 |
| No | 206923442 | COLEMAN | HMH72B361 | CM36BXA1+MVC12BN21+TXV | | 24,400 | $1,220 |
| No | 206923446 | COLEMAN | HMH72B361 | CM36BBCA1+MVC12BN21 | | 24,400 | $1,220 |
| No | 206921549 | COLEMAN | HMH72B241 | CU36CXA1+TXV | TM9V080B12MP12 | 14,300 | $715 |
| No | 206921557 | COLEMAN | HMH72B241 | CU36CXA1+TXV | TP9C080B12MP13 | 14,300 | $715 |
| No | 206921563 | COLEMAN | HMH72B241 | CU36CXA1+TXV | CP9C080B12MP13 | 14,300 | $715 |
| No | 206922123 | COLEMAN | HMH72B241 | AVC36CX21+TXV | | 14,200 | $710 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922812 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TM8V080B12MP12 | 24,400 | $1,220 |
| No | 206922824 | COLEMAN | HMH72B361 | CU36CXA1+TXV | TPLC080B12MP13 | 24,400 | $1,220 |
| No | 206923450 | COLEMAN | HMH72B361 | CF36CXA1+ME16CN21+TXV | | 23,800 | $1,190 |
| No | 206923454 | COLEMAN | HMH72B361 | CM36CXA1+ME16CN21+TXV | | 23,800 | $1,190 |
| No | 206923462 | COLEMAN | HMH72B361 | CF36CXA1+ME12CN21+TXV | | 24,200 | $1,210 |
| No | 206923458 | COLEMAN | HMH72B361 | CM36CBCA1+ME16CN21 | | 23,800 | $1,190 |
| No | 206923466 | COLEMAN | HMH72B361 | CM36CXA1+ME12CN21+TXV | | 24,200 | $1,210 |
| No | 206923470 | COLEMAN | HMH72B361 | CM36CBCA1+ME12CN21 | | 24,200 | $1,210 |
| No | 206922083 | COLEMAN | HMH72B241 | CF36CXA1+MVC12CN21+TXV | | 14,200 | $710 |
| No | 206922087 | COLEMAN | HMH72B241 | CM36CXA1+MVC12CN21+TXV | | 14,200 | $710 |
| No | 206922091 | COLEMAN | HMH72B241 | CF36BXA1+MVC12BN21+TXV | | 14,300 | $715 |
| No | 206922095 | COLEMAN | HMH72B241 | CF36BBAA1+MVC12BN21 | | 14,300 | $715 |
| No | 206922099 | COLEMAN | HMH72B241 | CM36BXA1+MVC12BN21+TXV | | 14,300 | $715 |
| No | 206922103 | COLEMAN | HMH72B241 | CM36BBAA1+MVC12BN21 | | 14,300 | $715 |
| No | 206922131 | COLEMAN | HMH72B241 | CF36BXA1+ME08BN21+TXV | | 14,100 | $705 |
| No | 206922135 | COLEMAN | HMH72B241 | CF36BBAA1+ME08BN21 | | 14,100 | $705 |
| No | 206922139 | COLEMAN | HMH72B241 | CM36BXA1+ME08BN21+TXV | | 14,100 | $705 |
| No | 206922143 | COLEMAN | HMH72B241 | CM36BBAA1+ME08BN21 | | 14,100 | $705 |
| No | 206971724 | COLEMAN | HMH72B481 | CF64DXA1+MVC20DN21+TXV | | 30,200 | $1,510 |
| No | 206971728 | COLEMAN | HMH72B481 | CM64DXA1+MVC20DN21+TXV | | 30,200 | $1,510 |
| No | 206971458 | COLEMAN | HMH72B601 | CF64DXA1+MVC20DN21+TXV | | 39,000 | $1,950 |
| No | 206971462 | COLEMAN | HMH72B601 | CM64DXA1+MVC20DN21+TXV | | 39,000 | $1,950 |
| No | 206971466 | COLEMAN | HMH72B601 | CF64DXA1+ME20DN21+TXV | | 39,000 | $1,950 |
| No | 206971470 | COLEMAN | HMH72B601 | CM64DXA1+ME20DN21+TXV | | 39,000 | $1,950 |
| No | 206971474 | COLEMAN | HMH72B601 | AVC60DX21+TXV | | 39,000 | $1,950 |
| No | 206921983 | COLEMAN | HMH72B241 | CF36AXA1+TXV | TM8V060A12MP12 | 14,100 | $705 |
| No | 206921987 | COLEMAN | HMH72B241 | CF36AXA1+TXV | TMLV060A12MP12 | 14,100 | $705 |
| No | 206921991 | COLEMAN | HMH72B241 | CF36AXA1+TXV | TPLC060A12MP13 | 14,100 | $705 |
| No | 206922003 | COLEMAN | HMH72B241 | CM36AXA1+TXV | TPLC060A12MP13 | 14,100 | $705 |
| No | 206921995 | COLEMAN | HMH72B241 | CM36AXA1+TXV | TM8V060A12MP12 | 14,100 | $705 |
| No | 206921999 | COLEMAN | HMH72B241 | CM36AXA1+TXV | TMLV060A12MP12 | 14,100 | $705 |
| No | 206921878 | COLEMAN | HMH72B241 | CF36BXA1+TXV | TM8V080B12MP12 | 14,400 | $720 |
| No | 206921882 | COLEMAN | HMH72B241 | CF36BXA1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 206921887 | COLEMAN | HMH72B241 | CF36BBAA1 | TM8V080B12MP12 | 14,400 | $720 |
| No | 206921891 | COLEMAN | HMH72B241 | CM36BXA1+TXV | TM8V080B12MP12 | 14,400 | $720 |
| No | 206921895 | COLEMAN | HMH72B241 | CM36BBAA1 | TM8V080B12MP12 | 14,400 | $720 |
| No | 206921899 | COLEMAN | HMH72B241 | CU36BXA1+TXV | TM8V080B12MP12 | 14,400 | $720 |
| No | 206921903 | COLEMAN | HMH72B241 | CF36BBAA1 | TPLC080B12MP13 | 14,400 | $720 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921907 | COLEMAN | HMH72B241 | CM36BXA1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 206921911 | COLEMAN | HMH72B241 | CM36BBAA1 | TPLC080B12MP13 | 14,400 | $720 |
| No | 206921915 | COLEMAN | HMH72B241 | CU36BXA1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 206922055 | COLEMAN | HMH72B241 | CF36BXA1+TXV | TL8E060A12UH11 | 14,500 | $725 |
| No | 206922059 | COLEMAN | HMH72B241 | CF36BBAA1 | TL8E060A12UH11 | 14,500 | $725 |
| No | 206922071 | COLEMAN | HMH72B241 | CU36BXA1+TXV | TL8E060A12UH11 | 14,500 | $725 |
| No | 206922063 | COLEMAN | HMH72B241 | CM36BXA1+TXV | TL8E060A12UH11 | 14,500 | $725 |
| No | 206922067 | COLEMAN | HMH72B241 | CM36BBAA1 | TL8E060A12UH11 | 14,500 | $725 |
| No | 206922075 | COLEMAN | HMH72B241 | CF36AXA1+TXV | TL8E060A12UH11 | 14,400 | $720 |
| No | 206922079 | COLEMAN | HMH72B241 | CM36AXA1+TXV | TL8E060A12UH11 | 14,400 | $720 |
| No | 206921851 | COLEMAN | HMH72B241 | CF36CXA1+TXV | TM8V080B12MP12 | 14,300 | $715 |
| No | 206921855 | COLEMAN | HMH72B241 | CF36CXA1+TXV | TPLC080B12MP13 | 14,300 | $715 |
| No | 206921860 | COLEMAN | HMH72B241 | CM36CXA1+TXV | TM8V080B12MP12 | 14,300 | $715 |
| No | 206921864 | COLEMAN | HMH72B241 | CU36CXA1+TXV | TM8V080B12MP12 | 14,300 | $715 |
| No | 206921923 | COLEMAN | HMH72B241 | CF36BXA1+TXV | TM8V060A12MP12 | 14,000 | $700 |
| No | 206921868 | COLEMAN | HMH72B241 | CM36CXA1+TXV | TPLC080B12MP13 | 14,300 | $715 |
| No | 206921872 | COLEMAN | HMH72B241 | CU36CXA1+TXV | TPLC080B12MP13 | 14,300 | $715 |
| No | 206921927 | COLEMAN | HMH72B241 | CF36BXA1+TXV | TMLV060A12MP12 | 14,000 | $700 |
| No | 206921931 | COLEMAN | HMH72B241 | CF36BXA1+TXV | TPLC060A12MP13 | 14,000 | $700 |
| No | 206921935 | COLEMAN | HMH72B241 | CF36BBAA1 | TM8V060A12MP12 | 14,000 | $700 |
| No | 206921939 | COLEMAN | HMH72B241 | CM36BXA1+TXV | TM8V060A12MP12 | 14,000 | $700 |
| No | 206921943 | COLEMAN | HMH72B241 | CM36BBAA1 | TM8V060A12MP12 | 14,000 | $700 |
| No | 206921947 | COLEMAN | HMH72B241 | CU36BXA1+TXV | TM8V060A12MP12 | 14,000 | $700 |
| No | 206921951 | COLEMAN | HMH72B241 | CF36BBAA1 | TMLV060A12MP12 | 14,000 | $700 |
| No | 206921955 | COLEMAN | HMH72B241 | CM36BXA1+TXV | TMLV060A12MP12 | 14,000 | $700 |
| No | 206921959 | COLEMAN | HMH72B241 | CM36BBAA1 | TMLV060A12MP12 | 14,000 | $700 |
| No | 206921971 | COLEMAN | HMH72B241 | CM36BXA1+TXV | TPLC060A12MP13 | 14,000 | $700 |
| No | 206921963 | COLEMAN | HMH72B241 | CU36BXA1+TXV | TMLV060A12MP12 | 14,000 | $700 |
| No | 206921975 | COLEMAN | HMH72B241 | CM36BBAA1 | TPLC060A12MP13 | 14,000 | $700 |
| No | 206921967 | COLEMAN | HMH72B241 | CF36BBAA1 | TPLC060A12MP13 | 14,000 | $700 |
| No | 206921979 | COLEMAN | HMH72B241 | CU36BXA1+TXV | TPLC060A12MP13 | 14,000 | $700 |
| No | 206922007 | COLEMAN | HMH72B241 | CF36AXA1+TXV | TM8E040A12MP11 | 14,400 | $720 |
| No | 206922011 | COLEMAN | HMH72B241 | CF36AXA1+TXV | TMLE040A12MP11 | 14,400 | $720 |
| No | 206922015 | COLEMAN | HMH72B241 | CM36AXA1+TXV | TM8E040A12MP11 | 14,400 | $720 |
| No | 206922019 | COLEMAN | HMH72B241 | CM36AXA1+TXV | TMLE040A12MP11 | 14,400 | $720 |
| No | 206922035 | COLEMAN | HMH72B241 | CF36BXA1+TXV | TL9E060B12UH11 | 14,500 | $725 |
| No | 206922039 | COLEMAN | HMH72B241 | CF36BBAA1 | TL9E060B12UH11 | 14,500 | $725 |
| No | 206922043 | COLEMAN | HMH72B241 | CM36BXA1+TXV | TL9E060B12UH11 | 14,500 | $725 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922047 | COLEMAN | HMH72B241 | CM36BBAA1 | TL9E060B12UH11 | 14,500 | $725 |
| No | 206922051 | COLEMAN | HMH72B241 | CU36BXA1+TXV | TL9E060B12UH11 | 14,500 | $725 |
| No | 206971732 | COLEMAN | HMH72B481 | CF64DXA1+MVC14DN21+TXV | | 29,200 | $1,460 |
| No | 206971736 | COLEMAN | HMH72B481 | CM64DXA1+MVC14DN21+TXV | | 29,200 | $1,460 |
| No | 206787289 | COLEMAN | HMH72B241 | AE36CX21+TXV | | 14,000 | $700 |
| No | 206787290 | COLEMAN | HMH72B361 | AE36CX21+TXV | | 24,000 | $1,200 |
| No | 206787291 | COLEMAN | HMH72B481 | AE60DX21+TXV | | 30,200 | $1,510 |
| No | 206787292 | COLEMAN | HMH72B601 | AE60DX21+TXV | | 36,800 | $1,840 |
| No | 210568235 | COMFORT-AIRE | A-VCD48SA-1 | MCD48C1A | | 32,000 | $1,600 |
| No | 210568236 | COMFORT-AIRE | A-VCD36SA-1 | MCD30/36C1A | | 33,000 | $1,650 |
| No | 210568229 | COMFORT-AIRE | A-VCD24SA-1 | MCD18/24B1A | | 21,000 | $1,050 |
| No | 210568230 | COMFORT-AIRE | A-VCD18SA-1 | MCD18/24B1A | | 14,700 | $735 |
| No | 210568227 | COMFORT-AIRE | A-VCD36SA-1 | B-VCD36SA-1 | | 30,400 | $1,520 |
| No | 210568226 | COMFORT-AIRE | A-VCD30SA-1 | B-VCD30SA-1 | | 21,000 | $1,050 |
| No | 200059085 | COMFORT-AIRE | A-VFH24TB-1 | Heat pump without ducts | | 16,600 | $830 |
| No | 207691822 | COMFORT-AIRE | A-DVH18SH-1 | B-DVH18SH-1 | | 11,500 | $575 |
| No | 207691820 | COMFORT-AIRE | A-DVH09SH-1 | B-DVH09SH-1 | | 6,900 | $345 |
| No | 207691818 | COMFORT-AIRE | A-DVH09SH-0 | B-DVH09SH-0 | | 6,800 | $340 |
| No | 207657385 | COMFORT-AIRE | A-VMH06SV-1 | B-VMH06SV-1 | | 8,500 | $425 |
| No | 210568238 | COMFORT-AIRE | A-VMH18SV-1 | B-VMH18CU-1 | | 15,600 | $780 |
| No | 210568237 | COMFORT-AIRE | A-VMH18SV-1 | B-VMH18UU-1 | | 12,000 | $600 |
| No | 210568242 | COMFORT-AIRE | A-VMH12SV-1 | B-VMH12FU-1 | | 9,600 | $480 |
| No | 210568246 | COMFORT-AIRE | A-VMH12SV-1 | B-VMH12DU-1 | | 10,600 | $530 |
| No | 210568240 | COMFORT-AIRE | A-VMH12SV-1 | B-VMH12CU-1 | | 9,900 | $495 |
| No | 210568245 | COMFORT-AIRE | A-VMH09SV-1 | B-VMH09DU-1 | | 10,100 | $505 |
| No | 210568241 | COMFORT-AIRE | A-VMH09SV-1 | B-VMH09CU-1 | | 9,000 | $450 |
| No | 207657387 | COMFORT-AIRE | A-VMH12SV-1 | B-VMH12SV-1 | | 10,000 | $500 |
| No | 207657386 | COMFORT-AIRE | A-VMH09SV-1 | B-VMH09SV-1 | | 9,500 | $475 |
| No | 200059091 | COMFORT-AIRE | A-VFH42PB-1 | Heat pump without ducts | | 29,000 | $1,450 |
| No | 200059087 | COMFORT-AIRE | A-VFH30QB-1 | Heat pump without ducts | | 18,000 | $900 |
| No | 200059089 | COMFORT-AIRE | A-VFH36QB-1 | Heat pump without ducts | | 20,000 | $1,000 |
| No | 200059083 | COMFORT-AIRE | A-VFH18DB-1 | Heat pump without ducts | | 12,800 | $640 |
| No | 207071146 | COMFORT-AIRE | HRG1836S1P | EAC4X48B | GUH96C070B3M | 22,600 | $1,130 |
| No | 207071148 | COMFORT-AIRE | HRG1836S1P | EAC4X48B | GUH96T045B3M | 22,400 | $1,120 |
| No | 207071156 | COMFORT-AIRE | HRG1836S1P | EAC4X48C | GUH92C110C4M | 22,000 | $1,100 |
| No | 207071152 | COMFORT-AIRE | HRG1836S1P | EAC4X48C | GUH92C090C3M | 22,000 | $1,100 |
| No | 207071150 | COMFORT-AIRE | HRG1836S1P | EAC4X48B | GUH96T070B3M | 22,200 | $1,110 |
| No | 207071154 | COMFORT-AIRE | HRG1836S1P | EAC4X48C | GUH92C090C4M | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207071160 | COMFORT-AIRE | HRG1836S1P | EAC4X48C | GUH96C090C4M | 22,000 | $1,100 |
| No | 207071162 | COMFORT-AIRE | HRG1836S1P | EAC4X48C | GUH96T090C3M | 22,000 | $1,100 |
| No | 207071158 | COMFORT-AIRE | HRG1836S1P | EAC4X48C | GUH95C090C4M | 22,000 | $1,100 |
| No | 207071202 | COMFORT-AIRE | HRG1836S1P | EC4X36B | GUH80C090B4M | 22,800 | $1,140 |
| No | 207071200 | COMFORT-AIRE | HRG1836S1P | EC4X36B | GUH80C070B3M | 23,000 | $1,150 |
| No | 207071196 | COMFORT-AIRE | HRG1836S1P | EC4X36A | GUH80C045A3M | 23,000 | $1,150 |
| No | 207071198 | COMFORT-AIRE | HRG1836S1P | EC4X36A | GUH80C070A3M | 23,000 | $1,150 |
| No | 207071208 | COMFORT-AIRE | HRG1836S1P | EC4X36B | GUH96C045B3M | 23,200 | $1,160 |
| No | 207071210 | COMFORT-AIRE | HRG1836S1P | EC4X36B | GUH96C070B3M | 23,200 | $1,160 |
| No | 207071214 | COMFORT-AIRE | HRG1836S1P | EC4X36B | GUH96T070B3M | 23,000 | $1,150 |
| No | 207071206 | COMFORT-AIRE | HRG1836S1P | EC4X36B | GUH92C070B3M | 23,200 | $1,160 |
| No | 207071216 | COMFORT-AIRE | HRG1836S1P | EC4X36C | GUH92C090C3M | 23,000 | $1,150 |
| No | 207071204 | COMFORT-AIRE | HRG1836S1P | EC4X36B | GUH92C045B3M | 23,200 | $1,160 |
| No | 207071218 | COMFORT-AIRE | HRG1836S1P | EC4X36C | GUH92C090C4M | 22,600 | $1,130 |
| No | 207071559 | COMFORT-AIRE | HRG1860S1P | HCG48V1P | | 30,800 | $1,540 |
| No | 207071212 | COMFORT-AIRE | HRG1836S1P | EC4X36B | GUH96T045B3M | 23,000 | $1,150 |
| No | 207071224 | COMFORT-AIRE | HRG1836S1P | EC4X36C | GUH96C090C4M | 22,800 | $1,140 |
| No | 207071220 | COMFORT-AIRE | HRG1836S1P | EC4X36C | GUH92C110C4M | 22,800 | $1,140 |
| No | 207071028 | COMFORT-AIRE | HRG1836S1P | HMG36F1P+H4TXV01 | | 22,200 | $1,110 |
| No | 207071557 | COMFORT-AIRE | HRG1860S1P | HMG48X1P | | 30,800 | $1,540 |
| No | 207071222 | COMFORT-AIRE | HRG1836S1P | EC4X36C | GUH95C090C4M | 23,000 | $1,150 |
| No | 207071226 | COMFORT-AIRE | HRG1836S1P | EC4X36C | GUH96T090C3M | 22,800 | $1,140 |
| No | 207071659 | COMFORT-AIRE | HRG1860S1P | ED1P50/60C+H4TXV02 | GDD95C110C5M | 30,400 | $1,520 |
| No | 207071653 | COMFORT-AIRE | HRG1860S1P | ED1P50/60C+H4TXV02 | GDD80C110C5M | 30,400 | $1,520 |
| No | 207071455 | COMFORT-AIRE | HRG1860S1P | HMG60X1P | | 37,800 | $1,890 |
| No | 207071655 | COMFORT-AIRE | HRG1860S1P | ED1P50/60C+H4TXV02 | GDD92C090C4M | 30,600 | $1,530 |
| No | 207071661 | COMFORT-AIRE | HRG1860S1P | ED1P50/60C+H4TXV02 | GDD96C090C4M | 30,800 | $1,540 |
| No | 207071453 | COMFORT-AIRE | HRG1860S1P | HCG60V1P | | 37,400 | $1,870 |
| No | 207071473 | COMFORT-AIRE | HRG1860S1P | EA(C,U)1P60C+H4TXV03 | GUH80C110C5M | 37,200 | $1,860 |
| No | 207071475 | COMFORT-AIRE | HRG1860S1P | EA(C,U)1P60C+H4TXV03 | GUH92C110C5M | 38,000 | $1,900 |
| No | 207071471 | COMFORT-AIRE | HRG1860S1P | EA(C,U)1P60C+H4TXV03 | GUH80C090C5M | 37,200 | $1,860 |
| No | 207071477 | COMFORT-AIRE | HRG1860S1P | EA(C,U)1P60C+H4TXV03 | GUH95C110C5M | 37,200 | $1,860 |
| No | 207071657 | COMFORT-AIRE | HRG1860S1P | ED1P50/60C+H4TXV02 | GDD95C090C4M | 30,600 | $1,530 |
| No | 207071479 | COMFORT-AIRE | HRG1860S1P | EA(C,U)1P60C+H4TXV03 | GUH96C110C5M | 37,400 | $1,870 |
| No | 207071481 | COMFORT-AIRE | HRG1860S1P | EA(C,U)1P60C+H4TXV03 | GUH96T090C5M | 37,800 | $1,890 |
| No | 207071503 | COMFORT-AIRE | HRG1860S1P | EAC4X60C | GUH80C090C5M | 37,200 | $1,860 |
| No | 207071505 | COMFORT-AIRE | HRG1860S1P | EAC4X60C | GUH80C110C5M | 37,200 | $1,860 |
| No | 207071483 | COMFORT-AIRE | HRG1860S1P | EA(C,U)1P60C+H4TXV03 | GUH96T110C5M | 37,600 | $1,880 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207071507 | COMFORT-AIRE | HRG1860S1P | EAC4X60C | GUH92C110C5M | 38,000 | $1,900 |
| No | 207071509 | COMFORT-AIRE | HRG1860S1P | EAC4X60C | GUH95C110C5M | 37,200 | $1,860 |
| No | 207071511 | COMFORT-AIRE | HRG1860S1P | EAC4X60C | GUH96C110C5M | 37,400 | $1,870 |
| No | 207071513 | COMFORT-AIRE | HRG1860S1P | EAC4X60C | GUH96T090C5M | 37,800 | $1,890 |
| No | 207071515 | COMFORT-AIRE | HRG1860S1P | EAC4X60C | GUH96T110C5M | 37,600 | $1,880 |
| No | 207071487 | COMFORT-AIRE | HRG1860S1P | EA(C,U)1P60D+H4TXV03 | GUH96T135D5M | 39,500 | $1,975 |
| No | 207071485 | COMFORT-AIRE | HRG1860S1P | EA(C,U)1P60D+H4TXV03 | GUH80C135D5M | 39,500 | $1,975 |
| No | 207071517 | COMFORT-AIRE | HRG1860S1P | EAC4X60D | GUH80C135D5M | 39,500 | $1,975 |
| No | 207071519 | COMFORT-AIRE | HRG1860S1P | EAC4X60D | GUH96T135D5M | 39,500 | $1,975 |
| No | 207071457 | COMFORT-AIRE | HRG1860S1P | E*1P50C+H4TXV03 | GUH80C090C5M | 40,000 | $2,000 |
| No | 207071463 | COMFORT-AIRE | HRG1860S1P | E*1P50C+H4TXV03 | GUH95C110C5M | 40,000 | $2,000 |
| No | 207071539 | COMFORT-AIRE | HRG1860S1P | ED1P60D+H4TXV03 | GDD95C110C5M | 37,400 | $1,870 |
| No | 207071461 | COMFORT-AIRE | HRG1860S1P | E*1P50C+H4TXV03 | GUH92C110C5M | 40,000 | $2,000 |
| No | 207071465 | COMFORT-AIRE | HRG1860S1P | E*1P50C+H4TXV03 | GUH96C110C5M | 40,500 | $2,025 |
| No | 207071467 | COMFORT-AIRE | HRG1860S1P | E*1P50C+H4TXV03 | GUH96T090C5M | 40,000 | $2,000 |
| No | 207071469 | COMFORT-AIRE | HRG1860S1P | E*1P50C+H4TXV03 | GUH96T110C5M | 39,500 | $1,975 |
| No | 207071142 | COMFORT-AIRE | HRG1836S1P | EAC4X48B | GUH92C070B3M | 22,400 | $1,120 |
| No | 207071136 | COMFORT-AIRE | HRG1836S1P | EAC4X48B | GUH80C070B3M | 22,200 | $1,110 |
| No | 207071144 | COMFORT-AIRE | HRG1836S1P | EAC4X48B | GUH96C045B3M | 22,600 | $1,130 |
| No | 207071134 | COMFORT-AIRE | HRG1836S1P | EAC4X36B | GUH96T070B3M | 22,400 | $1,120 |
| No | 207071140 | COMFORT-AIRE | HRG1836S1P | EAC4X48B | GUH92C045B3M | 22,400 | $1,120 |
| No | 207071138 | COMFORT-AIRE | HRG1836S1P | EAC4X48B | GUH80C090B4M | 22,200 | $1,110 |
| No | 207071132 | COMFORT-AIRE | HRG1836S1P | EAC4X36B | GUH96T045B3M | 22,400 | $1,120 |
| No | 207071130 | COMFORT-AIRE | HRG1836S1P | EAC4X36B | GUH96C070B3M | 22,600 | $1,130 |
| No | 207071122 | COMFORT-AIRE | HRG1836S1P | EAC4X36B | GUH96C045B3M | 22,600 | $1,130 |
| No | 207071124 | COMFORT-AIRE | HRG1836S1P | EAC4X36B | GUH80C090B4M | 22,000 | $1,100 |
| No | 207071128 | COMFORT-AIRE | HRG1836S1P | EAC4X36B | GUH92C070B3M | 22,400 | $1,120 |
| No | 207071126 | COMFORT-AIRE | HRG1836S1P | EAC4X36B | GUH92C045B3M | 22,400 | $1,120 |
| No | 207071120 | COMFORT-AIRE | HRG1836S1P | EAC4X36B | GUH80C070B3M | 22,200 | $1,110 |
| No | 207071118 | COMFORT-AIRE | HRG1836S1P | EAC4X36A | GUH80C070A3M | 22,400 | $1,120 |
| No | 207071250 | COMFORT-AIRE | HRG1836S1P | ED1P30/36C+H4TXV02 | GDD96C090C4M | 22,000 | $1,100 |
| No | 207071248 | COMFORT-AIRE | HRG1836S1P | ED1P30/36C+H4TXV02 | GDD95C090C4M | 22,000 | $1,100 |
| No | 207071116 | COMFORT-AIRE | HRG1836S1P | EAC4X36A | GUH80C045A3M | 22,200 | $1,110 |
| No | 207071244 | COMFORT-AIRE | HRG1836S1P | ED1P30/36B+H4TXV02 | GDD96C070B3M | 22,000 | $1,100 |
| No | 207071246 | COMFORT-AIRE | HRG1836S1P | ED1P30/36C+H4TXV02 | GDD92C090C4M | 22,000 | $1,100 |
| No | 207071240 | COMFORT-AIRE | HRG1836S1P | ED1P30/36B+H4TXV02 | GDD95C070B4M | 22,000 | $1,100 |
| No | 207071242 | COMFORT-AIRE | HRG1836S1P | ED1P30/36B+H4TXV02 | GDD96C045B3M | 22,400 | $1,120 |
| No | 207071238 | COMFORT-AIRE | HRG1836S1P | ED1P30/36B+H4TXV02 | GDD95C045B3M | 22,400 | $1,120 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207071234 | COMFORT-AIRE | HRG1836S1P | ED1P30/36B+H4TXV02 | GDD92C045B3M | 22,400 | $1,120 |
| No | 207071236 | COMFORT-AIRE | HRG1836S1P | ED1P30/36B+H4TXV02 | GDD92C070B3M | 22,400 | $1,120 |
| No | 207071232 | COMFORT-AIRE | HRG1836S1P | ED1P30/36B+H4TXV02 | GDD80C090B4M | 22,000 | $1,100 |
| No | 207071228 | COMFORT-AIRE | HRG1836S1P | ED1P30/36A+H4TXV02 | GDD80C045A3M | 22,200 | $1,110 |
| No | 207071230 | COMFORT-AIRE | HRG1836S1P | ED1P30/36B+H4TXV02 | GDD80C070B3M | 22,200 | $1,110 |
| No | 207071066 | COMFORT-AIRE | HRG1836S1P | E*1P36C+H4TXV02 | GUH96T090C3M | 22,800 | $1,140 |
| No | 207071062 | COMFORT-AIRE | HRG1836S1P | E*1P36C+H4TXV02 | GUH95C090C4M | 23,000 | $1,150 |
| No | 207071064 | COMFORT-AIRE | HRG1836S1P | E*1P36C+H4TXV02 | GUH96C090C4M | 22,800 | $1,140 |
| No | 207071060 | COMFORT-AIRE | HRG1836S1P | E*1P36C+H4TXV02 | GUH92C110C4M | 22,800 | $1,140 |
| No | 207071058 | COMFORT-AIRE | HRG1836S1P | E*1P36C+H4TXV02 | GUH92C090C4M | 22,600 | $1,130 |
| No | 207071056 | COMFORT-AIRE | HRG1836S1P | E*1P36C+H4TXV02 | GUH92C090C3M | 23,000 | $1,150 |
| No | 207071054 | COMFORT-AIRE | HRG1836S1P | E*1P36B+H4TXV02 | GUH96T070B3M | 23,000 | $1,150 |
| No | 207071050 | COMFORT-AIRE | HRG1836S1P | E*1P36B+H4TXV02 | GUH96C070B3M | 23,200 | $1,160 |
| No | 207071052 | COMFORT-AIRE | HRG1836S1P | E*1P36B+H4TXV02 | GUH96T045B3M | 23,000 | $1,150 |
| No | 207071048 | COMFORT-AIRE | HRG1836S1P | E*1P36B+H4TXV02 | GUH96C045B3M | 23,200 | $1,160 |
| No | 207071046 | COMFORT-AIRE | HRG1836S1P | E*1P36B+H4TXV02 | GUH92C070B3M | 23,200 | $1,160 |
| No | 207071044 | COMFORT-AIRE | HRG1836S1P | E*1P36B+H4TXV02 | GUH92C045B3M | 23,200 | $1,160 |
| No | 207071040 | COMFORT-AIRE | HRG1836S1P | E*1P36B+H4TXV02 | GUH80C070B3M | 23,000 | $1,150 |
| No | 207071042 | COMFORT-AIRE | HRG1836S1P | E*1P36B+H4TXV02 | GUH80C090B4M | 22,800 | $1,140 |
| No | 207071194 | COMFORT-AIRE | HRG1836S1P | EAH1P48B+H4TXV02 | GUH96T070B3M | 21,800 | $1,090 |
| No | 207071190 | COMFORT-AIRE | HRG1836S1P | EAH1P48B+H4TXV02 | GUH96C070B3M | 22,000 | $1,100 |
| No | 207071188 | COMFORT-AIRE | HRG1836S1P | EAH1P48B+H4TXV02 | GUH96C045B3M | 22,000 | $1,100 |
| No | 207071192 | COMFORT-AIRE | HRG1836S1P | EAH1P48B+H4TXV02 | GUH96T045B3M | 22,000 | $1,100 |
| No | 207071038 | COMFORT-AIRE | HRG1836S1P | E*1P36A+H4TXV02 | GUH80C070A3M | 23,000 | $1,150 |
| No | 207071036 | COMFORT-AIRE | HRG1836S1P | E*1P36A+H4TXV02 | GUH80C045A3M | 23,000 | $1,150 |
| No | 207071186 | COMFORT-AIRE | HRG1836S1P | EAH1P48B+H4TXV02 | GUH92C070B3M | 22,000 | $1,100 |
| No | 207071184 | COMFORT-AIRE | HRG1836S1P | EAH1P48B+H4TXV02 | GUH92C045B3M | 22,000 | $1,100 |
| No | 207071114 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P48C+H4TXV02 | GUH96T090C3M | 22,200 | $1,110 |
| No | 207071182 | COMFORT-AIRE | HRG1836S1P | EAH1P48B+H4TXV02 | GUH80C090B4M | 21,800 | $1,090 |
| No | 207071180 | COMFORT-AIRE | HRG1836S1P | EAH1P48B+H4TXV02 | GUH80C070B3M | 21,800 | $1,090 |
| No | 207071110 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P48C+H4TXV02 | GUH95C090C4M | 22,200 | $1,110 |
| No | 207071108 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P48C+H4TXV02 | GUH92C110C4M | 22,200 | $1,110 |
| No | 207071106 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P48C+H4TXV02 | GUH92C090C4M | 22,200 | $1,110 |
| No | 207071102 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P48B+H4TXV02 | GUH96T070B3M | 22,400 | $1,120 |
| No | 207071112 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P48C+H4TXV02 | GUH96C090C4M | 22,200 | $1,110 |
| No | 207071104 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P48C+H4TXV02 | GUH92C090C3M | 22,200 | $1,110 |
| No | 207071100 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P48B+H4TXV02 | GUH96T045B3M | 22,600 | $1,130 |
| No | 207071098 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P48B+H4TXV02 | GUH96C070B3M | 22,800 | $1,140 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207071086 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P36B+H4TXV02 | GUH96T070B3M | 22,400 | $1,120 |
| No | 207071096 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P48B+H4TXV02 | GUH96C045B3M | 22,800 | $1,140 |
| No | 207071092 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P48B+H4TXV02 | GUH92C045B3M | 22,600 | $1,130 |
| No | 207071094 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P48B+H4TXV02 | GUH92C070B3M | 22,600 | $1,130 |
| No | 207071090 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P48B+H4TXV02 | GUH80C090B4M | 22,400 | $1,120 |
| No | 207071088 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P48B+H4TXV02 | GUH80C070B3M | 22,400 | $1,120 |
| No | 207071082 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P36B+H4TXV02 | GUH96C070B3M | 22,600 | $1,130 |
| No | 207071084 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P36B+H4TXV02 | GUH96T045B3M | 22,400 | $1,120 |
| No | 207071074 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P36B+H4TXV02 | GUH96C045B3M | 22,600 | $1,130 |
| No | 207071080 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P36B+H4TXV02 | GUH92C070B3M | 22,400 | $1,120 |
| No | 207071078 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P36B+H4TXV02 | GUH92C045B3M | 22,400 | $1,120 |
| No | 207071072 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P36B+H4TXV02 | GUH80C070B3M | 22,200 | $1,110 |
| No | 207071034 | COMFORT-AIRE | HRG1836S1P | HCG42V1P | | 21,600 | $1,080 |
| No | 207071076 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P36B+H4TXV02 | GUH80C090B4M | 22,000 | $1,100 |
| No | 207071070 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P36A+H4TXV02 | GUH80C070A3M | 22,400 | $1,120 |
| No | 207071032 | COMFORT-AIRE | HRG1836S1P | HMG42X1P | | 21,800 | $1,090 |
| No | 207071026 | COMFORT-AIRE | HRG1836S1P | HCG36V1P | | 21,400 | $1,070 |
| No | 207071252 | COMFORT-AIRE | HRG1836S1P | HMG24F1P+H4TXV01 | | 16,200 | $810 |
| No | 207071030 | COMFORT-AIRE | HRG1836S1P | HMG36X1P | | 21,800 | $1,090 |
| No | 207071258 | COMFORT-AIRE | HRG1836S1P | HCG24V1P | | 15,900 | $795 |
| No | 207071068 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P36A+H4TXV02 | GUH80C045A3M | 22,200 | $1,110 |
| No | 207071386 | COMFORT-AIRE | HRG1836S1P | EC4X23B | GUH96T070B3M | 14,800 | $740 |
| No | 207071260 | COMFORT-AIRE | HRG1836S1P | HCG30V1P | | 15,600 | $780 |
| No | 207071384 | COMFORT-AIRE | HRG1836S1P | EC4X23B | GUH96T045B3M | 14,900 | $745 |
| No | 207071396 | COMFORT-AIRE | HRG1836S1P | EC4X23B | GUH95C070B3M | 14,900 | $745 |
| No | 207071398 | COMFORT-AIRE | HRG1836S1P | EC4X23B | GUH96C045B3M | 14,900 | $745 |
| No | 207071394 | COMFORT-AIRE | HRG1836S1P | EC4X23B | GUH95C045B3M | 14,800 | $740 |
| No | 207071390 | COMFORT-AIRE | HRG1836S1P | EC4X23B | GUH92C045B3M | 14,800 | $740 |
| No | 207071400 | COMFORT-AIRE | HRG1836S1P | EC4X23B | GUH96C070B3M | 14,800 | $740 |
| No | 207071388 | COMFORT-AIRE | HRG1836S1P | EC4X23B | GUH80C070B3M | 14,800 | $740 |
| No | 207071382 | COMFORT-AIRE | HRG1836S1P | EC4X23A | GUH80C045A3M | 15,000 | $750 |
| No | 207071344 | COMFORT-AIRE | HRG1836S1P | EAC4X30B | GUH96T045B3M | 15,400 | $770 |
| No | 207071360 | COMFORT-AIRE | HRG1836S1P | EAC4X30B | GUH96C070B3M | 15,400 | $770 |
| No | 207071392 | COMFORT-AIRE | HRG1836S1P | EC4X23B | GUH92C070B3M | 14,900 | $745 |
| No | 207071346 | COMFORT-AIRE | HRG1836S1P | EAC4X30B | GUH96T070B3M | 15,400 | $770 |
| No | 207071358 | COMFORT-AIRE | HRG1836S1P | EAC4X30B | GUH96C045B3M | 15,400 | $770 |
| No | 207071354 | COMFORT-AIRE | HRG1836S1P | EAC4X30B | GUH95C045B3M | 15,400 | $770 |
| No | 207071356 | COMFORT-AIRE | HRG1836S1P | EAC4X30B | GUH95C070B3M | 15,400 | $770 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207071352 | COMFORT-AIRE | HRG1836S1P | EAC4X30B | GUH92C070B3M | 15,400 | $770 |
| No | 207071350 | COMFORT-AIRE | HRG1836S1P | EAC4X30B | GUH92C045B3M | 15,400 | $770 |
| No | 207071348 | COMFORT-AIRE | HRG1836S1P | EAC4X30B | GUH80C070B3M | 15,400 | $770 |
| No | 207071342 | COMFORT-AIRE | HRG1836S1P | EAC4X30A | GUH80C045A3M | 15,500 | $775 |
| No | 207071326 | COMFORT-AIRE | HRG1836S1P | EAC4X24B | GUH96T070B3M | 15,200 | $760 |
| No | 207071330 | COMFORT-AIRE | HRG1836S1P | EAC4X24B | GUH92C045B3M | 15,200 | $760 |
| No | 207071332 | COMFORT-AIRE | HRG1836S1P | EAC4X24B | GUH92C070B3M | 15,200 | $760 |
| No | 207071378 | COMFORT-AIRE | HRG1836S1P | EAH1P30B+H4TXV01 | GUH96C045B3M | 15,300 | $765 |
| No | 207071366 | COMFORT-AIRE | HRG1836S1P | EAH1P30B+H4TXV01 | GUH96T070B3M | 15,300 | $765 |
| No | 207071324 | COMFORT-AIRE | HRG1836S1P | EAC4X24B | GUH96T045B3M | 15,200 | $760 |
| No | 207071376 | COMFORT-AIRE | HRG1836S1P | EAH1P30B+H4TXV01 | GUH95C070B3M | 15,400 | $770 |
| No | 207071364 | COMFORT-AIRE | HRG1836S1P | EAH1P30B+H4TXV01 | GUH96T045B3M | 15,300 | $765 |
| No | 207071374 | COMFORT-AIRE | HRG1836S1P | EAH1P30B+H4TXV01 | GUH95C045B3M | 15,300 | $765 |
| No | 207071370 | COMFORT-AIRE | HRG1836S1P | EAH1P30B+H4TXV01 | GUH92C045B3M | 15,300 | $765 |
| No | 207071372 | COMFORT-AIRE | HRG1836S1P | EAH1P30B+H4TXV01 | GUH92C070B3M | 15,300 | $765 |
| No | 207071368 | COMFORT-AIRE | HRG1836S1P | EAH1P30B+H4TXV01 | GUH80C070B3M | 15,300 | $765 |
| No | 207071362 | COMFORT-AIRE | HRG1836S1P | EAH1P30A+H4TXV01 | GUH80C045A3M | 15,200 | $760 |
| No | 207071380 | COMFORT-AIRE | HRG1836S1P | EAH1P30B+H4TXV01 | GUH96C070B3M | 15,300 | $765 |
| No | 207071410 | COMFORT-AIRE | HRG1836S1P | ED1P24B+H4TXV01 | GDD96C070B3M | 15,000 | $750 |
| No | 207071406 | COMFORT-AIRE | HRG1836S1P | ED1P24B+H4TXV01 | GDD95C045B3M | 15,000 | $750 |
| No | 207071404 | COMFORT-AIRE | HRG1836S1P | ED1P24B+H4TXV01 | GDD80C070B3M | 15,000 | $750 |
| No | 207071402 | COMFORT-AIRE | HRG1836S1P | ED1P24A+H4TXV01 | GDD80C045A3M | 15,200 | $760 |
| No | 207071266 | COMFORT-AIRE | HRG1836S1P | E*1P23B+H4TXV01 | GUH96T070B3M | 14,800 | $740 |
| No | 207071280 | COMFORT-AIRE | HRG1836S1P | E*1P23B+H4TXV01 | GUH96C070B3M | 14,800 | $740 |
| No | 207071264 | COMFORT-AIRE | HRG1836S1P | E*1P23B+H4TXV01 | GUH96T045B3M | 14,900 | $745 |
| No | 207071276 | COMFORT-AIRE | HRG1836S1P | E*1P23B+H4TXV01 | GUH95C070B3M | 14,900 | $745 |
| No | 207071278 | COMFORT-AIRE | HRG1836S1P | E*1P23B+H4TXV01 | GUH96C045B3M | 14,900 | $745 |
| No | 207071274 | COMFORT-AIRE | HRG1836S1P | E*1P23B+H4TXV01 | GUH95C045B3M | 14,800 | $740 |
| No | 207071268 | COMFORT-AIRE | HRG1836S1P | E*1P23B+H4TXV01 | GUH80C070B3M | 14,800 | $740 |
| No | 207071306 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P30B+H4TXV01 | GUH96T070B3M | 15,400 | $770 |
| No | 207071262 | COMFORT-AIRE | HRG1836S1P | E*1P23A+H4TXV01 | GUH80C045A3M | 15,000 | $750 |
| No | 207071304 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P30B+H4TXV01 | GUH96T045B3M | 15,400 | $770 |
| No | 207071318 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P30B+H4TXV01 | GUH96C045B3M | 15,400 | $770 |
| No | 207071320 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P30B+H4TXV01 | GUH96C070B3M | 15,400 | $770 |
| No | 207071316 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P30B+H4TXV01 | GUH95C070B3M | 15,400 | $770 |
| No | 207071314 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P30B+H4TXV01 | GUH95C045B3M | 15,400 | $770 |
| No | 207071312 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P30B+H4TXV01 | GUH92C070B3M | 15,400 | $770 |
| No | 207071310 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P30B+H4TXV01 | GUH92C045B3M | 15,400 | $770 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207071272 | COMFORT-AIRE | HRG1836S1P | E*1P23B+H4TXV01 | GUH92C070B3M | 14,900 | $745 |
| No | 207071302 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P30A+H4TXV01 | GUH80C045A3M | 15,500 | $775 |
| No | 207071308 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P30B+H4TXV01 | GUH80C070B3M | 15,400 | $770 |
| No | 207071286 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P24B+H4TXV01 | GUH96T070B3M | 15,200 | $760 |
| No | 207071284 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P24B+H4TXV01 | GUH96T045B3M | 15,200 | $760 |
| No | 207071290 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P24B+H4TXV01 | GUH92C045B3M | 15,200 | $760 |
| No | 207071256 | COMFORT-AIRE | HRG1836S1P | HMG30X1P | | 15,600 | $780 |
| No | 207071254 | COMFORT-AIRE | HRG1836S1P | HMG24X1P | | 15,600 | $780 |
| No | 207071292 | COMFORT-AIRE | HRG1836S1P | EA(C,U)1P24B+H4TXV01 | GUH92C070B3M | 15,200 | $760 |
| No | 200059039 | COMFORT-AIRE | B-VMH12SU-1 | A-VMH12SU-1 | | 7,800 | $390 |
| No | 200059041 | COMFORT-AIRE | A-VMH09SU-1 | B-VMH09SU-1 | | 6,900 | $345 |
| No | 201810035 | COMFORT-AIRE | A-VMH28TU-1 | Heat pump without ducts | | 18,000 | $900 |
| No | 202195114 | COMFORT-AIRE | A-VMH48PU-1 | Heat pump without ducts | | 29,600 | $1,480 |
| No | 205287684 | COMFORT-AIRE | A-DVH09SG-0 | B-DVH09SG-0 | | 6,000 | $300 |
| No | 201810033 | COMFORT-AIRE | A-VMH36QU-1 | Heat pump with ducts | | 24,600 | $1,230 |
| No | 205047889 | COMFORT-AIRE | A-DVH18SG-1 | B-DVH18SG-1 | | 11,000 | $550 |
| No | 205123795 | COMFORT-AIRE | A-VMH12SU-1 | B-VMH12SU-1C | | 7,800 | $390 |
| No | 205123794 | COMFORT-AIRE | A-VMH09SU-1 | B-VMH09SU-1C | | 6,900 | $345 |
| No | 205123797 | COMFORT-AIRE | A-VMH12SU-1 | B-VMH12CU-1 | | 8,700 | $435 |
| No | 205747696 | COMFORT-AIRE | A-VMH18SU-1B | B-VMH18SU-1B | | 10,900 | $545 |
| No | 208141174 | COMFORT-AIRE | A-VMH12SV-1 | B-VMH12SU-1C | | 7,600 | $380 |
| No | 208141181 | COMFORT-AIRE | A-KMH09SV-1 | B-KMH09SU-1 | | 7,100 | $355 |
| No | 208141173 | COMFORT-AIRE | A-VMH09SV-1 | B-VMH09SU-1C | | 7,100 | $355 |
| No | 208141182 | COMFORT-AIRE | A-KMH12SV-1 | B-KMH12SU-1 | | 7,600 | $380 |
| No | 208141169 | COMFORT-AIRE | A-VMH18SV-1 | B-VMH18SU-1A | | 10,900 | $545 |
| No | 208141183 | COMFORT-AIRE | A-KMH18SV-1 | B-KMH18SU-1 | | 10,900 | $545 |
| No | 206913570 | COMFORT-AIRE | A-VMH18SU-1A | B-VMH18SU-1B | | 10,900 | $545 |
| No | 207657611 | COMFORT-AIRE | A-VMH18DV-1 | Combination heat pumps with or without ducts | | 11,500 | $575 |
| No | 208141168 | COMFORT-AIRE | A-VMH12SV-1 | B-VMH12SU-1 | | 7,600 | $380 |
| No | 208141167 | COMFORT-AIRE | A-VMH09SV-1 | B-VMH09SU-1 | | 7,100 | $355 |
| No | 206913035 | COMFORT-AIRE | A-VMH18SU-1B | B-VMH18SU-1A | | 10,900 | $545 |
| No | 205288546 | COMFORT-AIRE | A-VMH12SU-1 | B-VMH12SU-1C | | 7,800 | $390 |
| No | 205288547 | COMFORT-AIRE | A-VMH09SU-1 | B-VMH09SU-1C | | 6,900 | $345 |
| No | 207657614 | COMFORT-AIRE | A-VMH28TV-1 | Combination heat pumps with or without ducts | | 17,000 | $850 |
| No | 210819421 | COMFORTMAKER | DLCSRBH30AAK | DLFSABH30XBK | | 20,400 | $1,020 |
| No | 209852049 | COMFORTMAKER | DLCURAH60AAK | DLFUAAH60XAK | | 37,000 | $1,850 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 209852046 | COMFORTMAKER | DLCURAH48AAK | DLFUAAH48XAK | | 37,000 | $1,850 |
| No | 209852053 | COMFORTMAKER | DLCURAH36AAK | DLFUAAH36XAK | | 20,400 | $1,020 |
| No | 209852055 | COMFORTMAKER | DLCURAH30ABK | DLFUAAH30XAK | | 21,000 | $1,050 |
| No | 209852052 | COMFORTMAKER | DLCURAH30AAK | DLFUAAH30XAK | | 20,000 | $1,000 |
| No | 209852045 | COMFORTMAKER | DLCURAH24AAK | DLFUAAH24XAK | | 21,000 | $1,050 |
| No | 209852051 | COMFORTMAKER | DLCURAH18AAK | DLFUAAH18XAK | | 12,000 | $600 |
| No | 207643026 | COMFORTMAKER | DLCMRBH48EAK | Heat pump without ducts | | 31,000 | $1,550 |
| No | 201835573 | COMFORTMAKER | DLCMRAH27CAK | Heat pump without ducts | | 17,800 | $890 |
| No | 207826619 | COMFORTMAKER | DLCLRCH36AAK | DLFLABH36XAK | | 25,600 | $1,280 |
| No | 208104311 | COMFORTMAKER | DLCSRBH36ABK | DLFSABH36XBK | | 25,600 | $1,280 |
| No | 207826617 | COMFORTMAKER | DLCLRCH48AAK | DLFLABH48XAK | | 37,400 | $1,870 |
| No | 207826618 | COMFORTMAKER | DLCLRCH58AAK | DLFLABH60XAK | | 34,000 | $1,700 |
| No | 207826596 | COMFORTMAKER | DLCSRBH24AAK | DLFSABH24XBK | | 16,200 | $810 |
| No | 208104312 | COMFORTMAKER | DLCSRBH30AAK11 | DLFSABH30XBK | | 19,200 | $960 |
| No | 207202704 | COMFORTMAKER | DLCSRBH18AAK | FEM4P18**AL | | 14,700 | $735 |
| No | 207202705 | COMFORTMAKER | DLCSRBH18AAK | FEM4X18**BL | | 14,700 | $735 |
| No | 207202707 | COMFORTMAKER | DLCSRBH18AAK | EA*4X24L14A* | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207202706 | COMFORTMAKER | DLCSRBH18AAK | EA*4X19L17A* | *80ES(N,L)0451412A* | 13,800 | $690 |
| No | 207202712 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207202708 | COMFORTMAKER | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207202710 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X18L14** | *80ES(N,L)0451412A* | 14,700 | $735 |
| No | 207202709 | COMFORTMAKER | DLCSRBH18AAK | EA*4X25L17A* | *80ES(N,L)0451412A* | 13,800 | $690 |
| No | 207202711 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X24L14** | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207202713 | COMFORTMAKER | DLCSRBH18AAK | EA*4X19L17A* | *80ES(N,L)0451712A* | 13,900 | $695 |
| No | 207202714 | COMFORTMAKER | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0451712A* | 14,600 | $730 |
| No | 207202715 | COMFORTMAKER | DLCSRBH18AAK | EA*4X25L17A* | *80ES(N,L)0451712A* | 13,800 | $690 |
| No | 207202718 | COMFORTMAKER | DLCSRBH18AAK | EA*4X25L17A* | *80ES(N,L)0701412A* | 13,800 | $690 |
| No | 207202717 | COMFORTMAKER | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0701412A* | 14,600 | $730 |
| No | 207202716 | COMFORTMAKER | DLCSRBH18AAK | EA*4X19L17A* | *80ES(N,L)0701412A* | 13,900 | $695 |
| No | 207202719 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X18L14** | *80ES(N,L)0701412A* | 14,700 | $735 |
| No | 207202723 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ES(N,L)0701712A* | 14,700 | $735 |
| No | 207202720 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X24L14** | *80ES(N,L)0701412A* | 14,600 | $730 |
| No | 207202721 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ES(N,L)0701412A* | 14,600 | $730 |
| No | 207202722 | COMFORTMAKER | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0701712A* | 14,700 | $735 |
| No | 207202725 | COMFORTMAKER | DLCSRBH18AAK | EA*4X24L17A* | *80ESU0401712A* | 14,500 | $725 |
| No | 207202724 | COMFORTMAKER | DLCSRBH18AAK | EA*4X19L17A* | *80ESU0401712A* | 13,700 | $685 |
| No | 207202726 | COMFORTMAKER | DLCSRBH18AAK | EA*4X25L17A* | *80ESU0401712A* | 13,600 | $680 |
| No | 207202727 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ESU0401712A* | 14,500 | $725 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207202728 | COMFORTMAKER | DLCSRBH18AAK | EA*4X19L17A* | *92ESN0401410A* | 13,800 | $690 |
| No | 207202729 | COMFORTMAKER | DLCSRBH18AAK | EA*4X24L14A* | *92ESN0401410A* | 14,500 | $725 |
| No | 207202730 | COMFORTMAKER | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0401410A* | 14,500 | $725 |
| No | 207202732 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X18L14** | *92ESN0401410A* | 14,600 | $730 |
| No | 207202736 | COMFORTMAKER | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0401712A* | 14,600 | $730 |
| No | 207202731 | COMFORTMAKER | DLCSRBH18AAK | EA*4X25L17A* | *92ESN0401410A* | 13,700 | $685 |
| No | 207202734 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0401410A* | 14,500 | $725 |
| No | 207202733 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X24L14** | *92ESN0401410A* | 14,500 | $725 |
| No | 207202739 | COMFORTMAKER | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0601412A* | 14,600 | $730 |
| No | 207202735 | COMFORTMAKER | DLCSRBH18AAK | EA*4X19L17A* | *92ESN0401712A* | 13,900 | $695 |
| No | 207202737 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0401712A* | 14,600 | $730 |
| No | 207202740 | COMFORTMAKER | DLCSRBH18AAK | EA*4X25L17A* | *92ESN0601412A* | 13,800 | $690 |
| No | 207202738 | COMFORTMAKER | DLCSRBH18AAK | EA*4X19L17A* | *92ESN0601412A* | 14,000 | $700 |
| No | 207202744 | COMFORTMAKER | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0801716A* | 14,700 | $735 |
| No | 207202741 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X18L14** | *92ESN0601412A* | 14,700 | $735 |
| No | 207202748 | COMFORTMAKER | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0261410A* | 13,900 | $695 |
| No | 207202743 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0601412A* | 14,600 | $730 |
| No | 207202742 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X24L14** | *92ESN0601412A* | 14,600 | $730 |
| No | 207202745 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0801716A* | 14,700 | $735 |
| No | 207202747 | COMFORTMAKER | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0261410A* | 14,700 | $735 |
| No | 207202746 | COMFORTMAKER | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0261410A* | 14,100 | $705 |
| No | 207202754 | COMFORTMAKER | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0401410A* | 14,600 | $730 |
| No | 207202749 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X18L14** | *95ESN0261410A* | 14,800 | $740 |
| No | 207202750 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X24L14** | *95ESN0261410A* | 14,700 | $735 |
| No | 207202751 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0261410A* | 14,700 | $735 |
| No | 207202752 | COMFORTMAKER | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0401410A* | 13,900 | $695 |
| No | 207202753 | COMFORTMAKER | DLCSRBH18AAK | EA*4X24L14A* | *95ESN0401410A* | 14,600 | $730 |
| No | 207202755 | COMFORTMAKER | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0401410A* | 13,800 | $690 |
| No | 207202756 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X18L14** | *95ESN0401410A* | 14,700 | $735 |
| No | 207202758 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0401410A* | 14,600 | $730 |
| No | 207202759 | COMFORTMAKER | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0401712A* | 13,800 | $690 |
| No | 207202757 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X24L14** | *95ESN0401410A* | 14,600 | $730 |
| No | 207202765 | COMFORTMAKER | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0601714A* | 14,100 | $705 |
| No | 207202760 | COMFORTMAKER | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0401712A* | 14,600 | $730 |
| No | 207202761 | COMFORTMAKER | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0401712A* | 13,700 | $685 |
| No | 207202763 | COMFORTMAKER | DLCSRBH18AAK | EA*4X24L14A* | *95ESN0601412A* | 14,900 | $745 |
| No | 207202764 | COMFORTMAKER | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0601412A* | 14,900 | $745 |
| No | 207202767 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0601714A* | 14,700 | $735 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207202762 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0401712A* | 14,600 | $730 |
| No | 207202766 | COMFORTMAKER | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0601714A* | 14,000 | $700 |
| No | 207202775 | COMFORTMAKER | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0401410A* | 13,900 | $695 |
| No | 207202770 | COMFORTMAKER | DLCSRBH18AAK | EA*4X25L17A* | *95ESU0401712A* | 13,800 | $690 |
| No | 207202768 | COMFORTMAKER | DLCSRBH18AAK | EA*4X19L17A* | *95ESU0401712A* | 13,800 | $690 |
| No | 207202769 | COMFORTMAKER | DLCSRBH18AAK | EA*4X24L17A* | *95ESU0401712A* | 14,600 | $730 |
| No | 207202771 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESU0401712A* | 14,600 | $730 |
| No | 207202772 | COMFORTMAKER | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0401410A* | 13,900 | $695 |
| No | 207202773 | COMFORTMAKER | DLCSRBH18AAK | EA*4X24L14A* | *96VTN0401410A* | 14,700 | $735 |
| No | 207202774 | COMFORTMAKER | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0401410A* | 14,700 | $735 |
| No | 207202776 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X18L14** | *96VTN0401410A* | 14,800 | $740 |
| No | 207202778 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X24L17** | *96VTN0401410A* | 14,700 | $735 |
| No | 207202777 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X24L14** | *96VTN0401410A* | 14,700 | $735 |
| No | 207202779 | COMFORTMAKER | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0401712A* | 13,900 | $695 |
| No | 207202780 | COMFORTMAKER | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0401712A* | 14,600 | $730 |
| No | 207202781 | COMFORTMAKER | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0401712A* | 13,800 | $690 |
| No | 207202782 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X24L17** | *96VTN0401712A* | 14,600 | $730 |
| No | 207202784 | COMFORTMAKER | DLCSRBH18AAK | EA*4X24L14A* | *96VTN0601412A* | 14,600 | $730 |
| No | 207202783 | COMFORTMAKER | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0601412A* | 13,800 | $690 |
| No | 207202785 | COMFORTMAKER | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0601412A* | 14,600 | $730 |
| No | 207202786 | COMFORTMAKER | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0601412A* | 13,800 | $690 |
| No | 207202787 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X18L14** | *96VTN0601412A* | 14,700 | $735 |
| No | 207202788 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X24L14** | *96VTN0601412A* | 14,600 | $730 |
| No | 207202789 | COMFORTMAKER | DLCSRBH18AAK | EN(A,D)4X24L17** | *96VTN0601412A* | 14,600 | $730 |
| No | 207202790 | COMFORTMAKER | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0601714A* | 14,100 | $705 |
| No | 207202791 | COMFORTMAKER | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0601714A* | 14,700 | $735 |
| No | 207202792 | COMFORTMAKER | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0601714A* | 13,900 | $695 |
| No | 207202793 | COMFORTMAKER | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0801716A* | 13,800 | $690 |
| No | 207202701 | COMFORTMAKER | DLCSRBH18AAK | FMA4X18**AL* | | 15,000 | $750 |
| No | 207202173 | COMFORTMAKER | DLCSRBH18AAK | FVM4X24***L | | 13,400 | $670 |
| No | 207202702 | COMFORTMAKER | DLCSRBH18AAK | FM(C,U)4Z18**AL* | | 15,000 | $750 |
| No | 207099160 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X24L14** | *80ES(N,L)0451412A* | 15,600 | $780 |
| No | 207202703 | COMFORTMAKER | DLCSRBH18AAK | FXM4X18**AL | | 14,500 | $725 |
| No | 207099162 | COMFORTMAKER | DLCSRBH24AAK | EA*4X24L14A* | *80ES(N,L)0451412A* | 15,700 | $785 |
| No | 207099163 | COMFORTMAKER | DLCSRBH24AAK | EA*4X30L14A* | *80ES(N,L)0451412A* | 15,500 | $775 |
| No | 207099166 | COMFORTMAKER | DLCSRBH24AAK | EA*4X36L17A* | *80ES(N,L)0451712A* | 15,500 | $775 |
| No | 207099164 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X30L14** | *80ES(N,L)0451412A* | 15,500 | $775 |
| No | 207099167 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X24L14** | *80ES(N,L)0701412A* | 15,600 | $780 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207099169 | COMFORTMAKER | DLCSRBH24AAK | EA*4X24L14A* | *80ES(N,L)0701412A* | 15,700 | $785 |
| No | 207099170 | COMFORTMAKER | DLCSRBH24AAK | EA*4X30L14A* | *80ES(N,L)0701412A* | 15,500 | $775 |
| No | 207099171 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X30L14** | *80ES(N,L)0701412A* | 15,500 | $775 |
| No | 207099173 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X24L17** | *80ES(N,L)0701712A* | 15,600 | $780 |
| No | 207099174 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X30L17** | *80ES(N,L)0701712A* | 15,400 | $770 |
| No | 207099175 | COMFORTMAKER | DLCSRBH24AAK | EA*4X36L17A* | *80ES(N,L)0701712A* | 15,400 | $770 |
| No | 207099177 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *80ES(N,L)0701712A* | 15,400 | $770 |
| No | 207099178 | COMFORTMAKER | DLCSRBH24AAK | EA*4X30L17A* | *80ES(N,L)0701712A* | 15,500 | $775 |
| No | 207099181 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X30L17** | *80ESU0401712A* | 15,400 | $770 |
| No | 207099183 | COMFORTMAKER | DLCSRBH24AAK | EA*4X36L17A* | *80ESU0401712A* | 15,300 | $765 |
| No | 207099179 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X24L17** | *80ESU0401712A* | 15,500 | $775 |
| No | 207099184 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *80ESU0401712A* | 15,400 | $770 |
| No | 207099186 | COMFORTMAKER | DLCSRBH24AAK | EA*4X30L17A* | *80ESU0401712A* | 15,400 | $770 |
| No | 207099191 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X30L17** | *80ESU0601716A | 15,500 | $775 |
| No | 207099187 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X24L17** | *80ESU0601716A | 15,600 | $780 |
| No | 207099189 | COMFORTMAKER | DLCSRBH24AAK | EA*4X24L17A* | *80ESU0601716A | 15,700 | $785 |
| No | 207099214 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X24L14** | *92ESN0601412A* | 15,600 | $780 |
| No | 207099192 | COMFORTMAKER | DLCSRBH24AAK | EA*4X36L17A* | *80ESU0601716A | 15,400 | $770 |
| No | 207099194 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *80ESU0601716A | 15,500 | $775 |
| No | 207099226 | COMFORTMAKER | DLCSRBH24AAK | EA*4X30L14A* | *92ESN0601714A* | 15,500 | $775 |
| No | 207099216 | COMFORTMAKER | DLCSRBH24AAK | EA*4X24L14A* | *92ESN0601412A* | 15,700 | $785 |
| No | 207099220 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X30L14** | *92ESN0601412A* | 15,500 | $775 |
| No | 207099218 | COMFORTMAKER | DLCSRBH24AAK | EA*4X30L14A* | *92ESN0601412A* | 15,500 | $775 |
| No | 207099223 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X24L14** | *92ESN0601714A* | 15,500 | $775 |
| No | 207099224 | COMFORTMAKER | DLCSRBH24AAK | EA*4X24L14A* | *92ESN0601714A* | 15,700 | $785 |
| No | 207099228 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X24L17** | *92ESN0801716A* | 15,500 | $775 |
| No | 207099227 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X30L14** | *92ESN0601714A* | 15,400 | $770 |
| No | 207099236 | COMFORTMAKER | DLCSRBH24AAK | EA*4X30L17A* | *92ESN0801716A* | 15,400 | $770 |
| No | 207099231 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X30L17** | *92ESN0801716A* | 15,400 | $770 |
| No | 207099230 | COMFORTMAKER | DLCSRBH24AAK | EA*4X24L17A* | *92ESN0801716A* | 15,700 | $785 |
| No | 207099233 | COMFORTMAKER | DLCSRBH24AAK | EA*4X36L17A* | *92ESN0801716A* | 15,400 | $770 |
| No | 207099234 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *92ESN0801716A* | 15,400 | $770 |
| No | 207099239 | COMFORTMAKER | DLCSRBH24AAK | EA*4X24L14A* | *95ESN0261410A* | 15,800 | $790 |
| No | 207099252 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESN0401712A* | 15,600 | $780 |
| No | 207099242 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X30L14** | *95ESN0261410A* | 15,500 | $775 |
| No | 207099240 | COMFORTMAKER | DLCSRBH24AAK | EA*4X30L14A* | *95ESN0261410A* | 15,500 | $775 |
| No | 207099350 | COMFORTMAKER | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0401410A* | 15,300 | $765 |
| No | 207099254 | COMFORTMAKER | DLCSRBH24AAK | EA*4X36L17A* | *95ESN0401712A* | 15,500 | $775 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207099338 | COMFORTMAKER | DLCSRBH24AAK | EA*4X25L17A* | *95ESN0401712A* | 15,200 | $760 |
| No | 207099256 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESN0401712A* | 15,600 | $780 |
| No | 207099257 | COMFORTMAKER | DLCSRBH24AAK | EA*4X30L17A* | *95ESN0401712A* | 15,600 | $780 |
| No | 207099340 | COMFORTMAKER | DLCSRBH24AAK | EA*4X36L21A* | *95ESN0401712A* | 15,500 | $775 |
| No | 207099341 | COMFORTMAKER | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0401712A* | 15,300 | $765 |
| No | 207099344 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X36L21** | *95ESN0401712A* | 15,600 | $780 |
| No | 207099343 | COMFORTMAKER | DLCSRBH24AAK | EA*4X37L21A* | *95ESN0401712A* | 15,200 | $760 |
| No | 207099262 | COMFORTMAKER | DLCSRBH24AAK | EA*4X24L14A* | *95ESN0601412A* | 15,800 | $790 |
| No | 207099260 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X24L14** | *95ESN0601412A* | 15,600 | $780 |
| No | 207099332 | COMFORTMAKER | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0601412A* | 15,300 | $765 |
| No | 207099263 | COMFORTMAKER | DLCSRBH24AAK | EA*4X30L14A* | *95ESN0601412A* | 15,600 | $780 |
| No | 207099265 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X30L14** | *95ESN0601412A* | 15,500 | $775 |
| No | 207099327 | COMFORTMAKER | DLCSRBH24AAK | EA*4X25L17A* | *95ESN0601412A* | 15,200 | $760 |
| No | 207099325 | COMFORTMAKER | DLCSRBH24AAK | EA*4X24L17A* | *95ESN0601412A* | 15,800 | $790 |
| No | 207099329 | COMFORTMAKER | DLCSRBH24AAK | EA*4X36L17A* | *95ESN0601412A* | 15,500 | $775 |
| No | 207099330 | COMFORTMAKER | DLCSRBH24AAK | EA*4X30L17A* | *95ESN0601412A* | 15,600 | $780 |
| No | 207099333 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X24L17** | *95ESN0601412A* | 15,600 | $780 |
| No | 207099337 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESN0601412A* | 15,500 | $775 |
| No | 207099335 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESN0601412A* | 15,500 | $775 |
| No | 207099266 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X24L17** | *95ESN0601714A* | 15,600 | $780 |
| No | 207099269 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESN0601714A* | 15,500 | $775 |
| No | 207099268 | COMFORTMAKER | DLCSRBH24AAK | EA*4X24L17A* | *95ESN0601714A* | 15,800 | $790 |
| No | 207099273 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESN0601714A* | 15,500 | $775 |
| No | 207099318 | COMFORTMAKER | DLCSRBH24AAK | EA*4X25L17A* | *95ESN0601714A* | 15,200 | $760 |
| No | 207099274 | COMFORTMAKER | DLCSRBH24AAK | EA*4X30L17A* | *95ESN0601714A* | 15,500 | $775 |
| No | 207099271 | COMFORTMAKER | DLCSRBH24AAK | EA*4X36L17A* | *95ESN0601714A* | 15,400 | $770 |
| No | 207099319 | COMFORTMAKER | DLCSRBH24AAK | EA*4X36L21A* | *95ESN0601714A* | 15,400 | $770 |
| No | 207099321 | COMFORTMAKER | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0601714A* | 15,200 | $760 |
| No | 207099196 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X24L17** | *95ESU0401712A* | 15,600 | $780 |
| No | 207099322 | COMFORTMAKER | DLCSRBH24AAK | EA*4X37L21A* | *95ESN0601714A* | 15,100 | $755 |
| No | 207099324 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X36L21** | *95ESN0601714A* | 15,500 | $775 |
| No | 207099197 | COMFORTMAKER | DLCSRBH24AAK | EA*4X24L17A* | *95ESU0401712A* | 15,700 | $785 |
| No | 207099199 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESU0401712A* | 15,500 | $775 |
| No | 207099202 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESU0401712A* | 15,500 | $775 |
| No | 207099200 | COMFORTMAKER | DLCSRBH24AAK | EA*4X36L17A* | *95ESU0401712A* | 15,400 | $770 |
| No | 207099203 | COMFORTMAKER | DLCSRBH24AAK | EA*4X30L17A* | *95ESU0401712A* | 15,500 | $775 |
| No | 207099280 | COMFORTMAKER | DLCSRBH24AAK | EA*4X30L14A* | *96VTN0401410A* | 15,600 | $780 |
| No | 207099282 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X30L14** | *96VTN0401410A* | 15,600 | $780 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207099288 | COMFORTMAKER | DLCSRBH24AAK | EA*4X36L17A* | *96VTN0401712A* | 15,500 | $775 |
| No | 207099305 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *96VTN0601714A* | 15,500 | $775 |
| No | 207099299 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X24L17** | *96VTN0601714A* | 15,600 | $780 |
| No | 207099296 | COMFORTMAKER | DLCSRBH24AAK | EA*4X30L14A* | *96VTN0601412A* | 15,600 | $780 |
| No | 207099298 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X30L14** | *96VTN0601412A* | 15,600 | $780 |
| No | 207099308 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X24L17** | *96VTN0801716A* | 15,600 | $780 |
| No | 207099301 | COMFORTMAKER | DLCSRBH24AAK | EA*4X24L17A* | *96VTN0601714A* | 15,800 | $790 |
| No | 207099302 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X30L17** | *96VTN0601714A* | 15,500 | $775 |
| No | 207099307 | COMFORTMAKER | DLCSRBH24AAK | EA*4X30L17A* | *96VTN0601714A* | 15,500 | $775 |
| No | 207099304 | COMFORTMAKER | DLCSRBH24AAK | EA*4X36L17A* | *96VTN0601714A* | 15,400 | $770 |
| No | 207099310 | COMFORTMAKER | DLCSRBH24AAK | EA*4X24L17A* | *96VTN0801716A* | 15,700 | $785 |
| No | 207099156 | COMFORTMAKER | DLCSRBH24AAK | FMA4X24**AL* | | 16,000 | $800 |
| No | 207099313 | COMFORTMAKER | DLCSRBH24AAK | EA*4X36L17A* | *96VTN0801716A* | 15,400 | $770 |
| No | 207099312 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D)4X30L17** | *96VTN0801716A* | 15,500 | $775 |
| No | 207099316 | COMFORTMAKER | DLCSRBH24AAK | EA*4X30L17A* | *96VTN0801716A* | 15,500 | $775 |
| No | 207099315 | COMFORTMAKER | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *96VTN0801716A* | 15,500 | $775 |
| No | 207099152 | COMFORTMAKER | DLCSRBH24AAK | FXM4X24**AL | | 15,500 | $775 |
| No | 207199090 | COMFORTMAKER | DLCSRBH30AAK | EA*4X30L14A* | *80ES(N,L)0451412A* | 19,200 | $960 |
| No | 207199092 | COMFORTMAKER | DLCSRBH30AAK | EA*4X30L17A* | *80ES(N,L)0451712A* | 19,100 | $955 |
| No | 207099157 | COMFORTMAKER | DLCSRBH24AAK | FM(C,U)4Z24**AL* | | 16,100 | $805 |
| No | 207199091 | COMFORTMAKER | DLCSRBH30AAK | EN(A,D)4X30L14** | *80ES(N,L)0451412A* | 19,200 | $960 |
| No | 207199095 | COMFORTMAKER | DLCSRBH30AAK | EN(A,D)4X30L14** | *80ES(N,L)0701412A* | 19,100 | $955 |
| No | 207199094 | COMFORTMAKER | DLCSRBH30AAK | EA*4X30L14A* | *80ES(N,L)0701412A* | 19,100 | $955 |
| No | 207199097 | COMFORTMAKER | DLCSRBH30AAK | EN(A,D)4X30L17** | *80ES(N,L)0701716A* | 19,300 | $965 |
| No | 207199093 | COMFORTMAKER | DLCSRBH30AAK | EN(A,D)4X30L17** | *80ES(N,L)0451712A* | 19,100 | $955 |
| No | 207199096 | COMFORTMAKER | DLCSRBH30AAK | EA*4X30L17A* | *80ES(N,L)0701716A* | 19,300 | $965 |
| No | 207199098 | COMFORTMAKER | DLCSRBH30AAK | EA*4X36L21A* | *80ES(N,L)0702116A* | 19,000 | $950 |
| No | 207199100 | COMFORTMAKER | DLCSRBH30AAK | EN(A,D)4X36L21** | *80ES(N,L)0902116A* | 19,300 | $965 |
| No | 207199099 | COMFORTMAKER | DLCSRBH30AAK | EN(A,D)4X36L21** | *80ES(N,L)0702116A* | 19,100 | $955 |
| No | 207199101 | COMFORTMAKER | DLCSRBH30AAK | EA*4X30L17A* | *80ESU0401712A* | 19,000 | $950 |
| No | 207199102 | COMFORTMAKER | DLCSRBH30AAK | EN(A,D)4X30L17** | *80ESU0401712A* | 19,000 | $950 |
| No | 207199104 | COMFORTMAKER | DLCSRBH30AAK | EN(A,D)4X30L14** | *92ESN0601412A* | 19,200 | $960 |
| No | 207199103 | COMFORTMAKER | DLCSRBH30AAK | EA*4X30L14A* | *92ESN0601412A* | 19,200 | $960 |
| No | 207199105 | COMFORTMAKER | DLCSRBH30AAK | EA*4X30L17A* | *92ESN0601714A* | 19,100 | $955 |
| No | 207199106 | COMFORTMAKER | DLCSRBH30AAK | EN(A,D)4X30L17** | *92ESN0601714A* | 19,100 | $955 |
| No | 207199107 | COMFORTMAKER | DLCSRBH30AAK | EA*4X30L17A* | *92ESN0801716A* | 19,100 | $955 |
| No | 207199108 | COMFORTMAKER | DLCSRBH30AAK | EN(A,D)4X30L17** | *92ESN0801716A* | 19,100 | $955 |
| No | 207199125 | COMFORTMAKER | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0401410A* | 19,100 | $955 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207199126 | COMFORTMAKER | DLCSRBH30AAK | END4X42L17** | *95ESN0401410A* | 19,200 | $960 |
| No | 207199127 | COMFORTMAKER | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0401712A* | 19,300 | $965 |
| No | 207199128 | COMFORTMAKER | DLCSRBH30AAK | EA*4X36L21A* | *95ESN0401712A* | 19,300 | $965 |
| No | 207199129 | COMFORTMAKER | DLCSRBH30AAK | EA*4X36L17A* | *95ESN0401712A* | 19,300 | $965 |
| No | 207199130 | COMFORTMAKER | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0401712A* | 19,000 | $950 |
| No | 207199131 | COMFORTMAKER | DLCSRBH30AAK | EA*4X42L21A* | *95ESN0401712A* | 19,200 | $960 |
| No | 207199133 | COMFORTMAKER | DLCSRBH30AAK | END4X42L17** | *95ESN0401712A* | 19,100 | $955 |
| No | 207199132 | COMFORTMAKER | DLCSRBH30AAK | EA*4X43L21A* | *95ESN0401712A* | 18,700 | $935 |
| No | 207199134 | COMFORTMAKER | DLCSRBH30AAK | EA*4X30L14A* | *95ESN0601412A* | 19,300 | $965 |
| No | 207199135 | COMFORTMAKER | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0601412A* | 19,300 | $965 |
| No | 207199136 | COMFORTMAKER | DLCSRBH30AAK | EA*4X36L17A* | *95ESN0601412A* | 19,200 | $960 |
| No | 207199137 | COMFORTMAKER | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0601412A* | 19,000 | $950 |
| No | 207199138 | COMFORTMAKER | DLCSRBH30AAK | EN(A,D)4X30L14** | *95ESN0601412A* | 19,300 | $965 |
| No | 207199139 | COMFORTMAKER | DLCSRBH30AAK | EN(A,D,W)4X36L17** | *95ESN0601412A* | 19,300 | $965 |
| No | 207199140 | COMFORTMAKER | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESN0601412A* | 19,300 | $965 |
| No | 207199141 | COMFORTMAKER | DLCSRBH30AAK | END4X42L17** | *95ESN0601412A* | 19,100 | $955 |
| No | 207199142 | COMFORTMAKER | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0601714A* | 19,300 | $965 |
| No | 207199143 | COMFORTMAKER | DLCSRBH30AAK | EA*4X36L17A* | *95ESN0601714A* | 19,200 | $960 |
| No | 207199144 | COMFORTMAKER | DLCSRBH30AAK | EA*4X36L21A* | *95ESN0601714A* | 19,200 | $960 |
| No | 207199145 | COMFORTMAKER | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0601714A* | 19,000 | $950 |
| No | 207199147 | COMFORTMAKER | DLCSRBH30AAK | EA*4X37L21A* | *95ESN0601714A* | 18,700 | $935 |
| No | 207199146 | COMFORTMAKER | DLCSRBH30AAK | EA*4X42L21A* | *95ESN0601714A* | 19,100 | $955 |
| No | 207199148 | COMFORTMAKER | DLCSRBH30AAK | EA*4X43L21A* | *95ESN0601714A* | 18,700 | $935 |
| No | 207199149 | COMFORTMAKER | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESN0601714A* | 19,200 | $960 |
| No | 207199109 | COMFORTMAKER | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0801716A* | 19,300 | $965 |
| No | 207199150 | COMFORTMAKER | DLCSRBH30AAK | EN(A,D)4X36L21** | *95ESN0601714A* | 19,200 | $960 |
| No | 207199151 | COMFORTMAKER | DLCSRBH30AAK | EN(A,D,W)4X36L17** | *95ESN0601714A* | 19,200 | $960 |
| No | 207199110 | COMFORTMAKER | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESN0801716A* | 19,300 | $965 |
| No | 207199152 | COMFORTMAKER | DLCSRBH30AAK | END4X42L17** | *95ESN0601714A* | 19,000 | $950 |
| No | 207199153 | COMFORTMAKER | DLCSRBH30AAK | EN(A,D,W)4X42L21** | *95ESN0601714A* | 19,100 | $955 |
| No | 207199115 | COMFORTMAKER | DLCSRBH30AAK | EN(A,D)4X30L14** | *96VTN0601412A* | 19,300 | $965 |
| No | 207199111 | COMFORTMAKER | DLCSRBH30AAK | EA*4X36L21A* | *95ESN0802120A* | 19,100 | $955 |
| No | 207199112 | COMFORTMAKER | DLCSRBH30AAK | EA*4X30L17A* | *95ESU0401712A* | 19,000 | $950 |
| No | 207199118 | COMFORTMAKER | DLCSRBH30AAK | EA*4X30L17A* | *96VTN0801716A* | 19,100 | $955 |
| No | 207199113 | COMFORTMAKER | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESU0401712A* | 19,000 | $950 |
| No | 207199114 | COMFORTMAKER | DLCSRBH30AAK | EA*4X30L17A* | *96VTN0401712A* | 19,300 | $965 |
| No | 207199116 | COMFORTMAKER | DLCSRBH30AAK | EA*4X30L17A* | *96VTN0601714A* | 19,100 | $955 |
| No | 207199117 | COMFORTMAKER | DLCSRBH30AAK | EN(A,D)4X30L17** | *96VTN0601714A* | 19,100 | $955 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207199119 | COMFORTMAKER | DLCSRBH30AAK | EN(A,D)4X30L17** | *96VTN0801716A* | 19,100 | $955 |
| No | 207199120 | COMFORTMAKER | DLCSRBH30AAK | EA*4X36L21A* | *96VTN0802120A* | 18,800 | $940 |
| No | 207199122 | COMFORTMAKER | DLCSRBH30AAK | EA*4X36L21A* | *96VTN1002120A* | 18,800 | $940 |
| No | 207199121 | COMFORTMAKER | DLCSRBH30AAK | EN(A,D)4X36L21** | *96VTN0802120A* | 19,000 | $950 |
| No | 207200393 | COMFORTMAKER | DLCSRBH30AAK | EN(A,D)4X36L21** | *96VTN1002120A* | 20,800 | $1,040 |
| No | 207198927 | COMFORTMAKER | DLCSRBH30AAK | FVM4X36***L | | 19,200 | $960 |
| No | 207199088 | COMFORTMAKER | DLCSRBH30AAK | FXM4X30**AL | | 18,800 | $940 |
| No | 207199087 | COMFORTMAKER | DLCSRBH30AAK | FMA4X30**AL* | | 19,400 | $970 |
| No | 207199085 | COMFORTMAKER | DLCSRBH30AAK | FEM4P30**AL | | 19,100 | $955 |
| No | 207199089 | COMFORTMAKER | DLCSRBH30AAK | FM(C,U)4Z30**AL* | | 19,200 | $960 |
| No | 207199086 | COMFORTMAKER | DLCSRBH30AAK | FEM4X30**BL | | 19,100 | $955 |
| No | 206188291 | COMFORTMAKER | DLCLRBH36AAK | DLFLDAH36XAK | | 27,000 | $1,350 |
| No | 207643012 | COMFORTMAKER | DLCMHBH24CAK | Heat pump with ducts | | 18,500 | $925 |
| No | 207643009 | COMFORTMAKER | DLCMRBH18BAK | Heat pump with ducts | | 11,800 | $590 |
| No | 207643027 | COMFORTMAKER | DLCMRBH48EAK | Heat pump with ducts | | 30,400 | $1,520 |
| No | 207643013 | COMFORTMAKER | DLCMHBH24CAK | Combination heat pumps with or without ducts | | 15,900 | $795 |
| No | 207643010 | COMFORTMAKER | DLCMRBH18BAK | Combination heat pumps with or without ducts | | 11,800 | $590 |
| No | 207643028 | COMFORTMAKER | DLCMRBH48EAK | Combination heat pumps with or without ducts | | 30,600 | $1,530 |
| No | 207643011 | COMFORTMAKER | DLCMHBH24CAK | Heat pump without ducts | | 13,300 | $665 |
| No | 207643018 | COMFORTMAKER | DLCMRBH36DAK | Heat pump without ducts | | 24,000 | $1,200 |
| No | 207643008 | COMFORTMAKER | DLCMRBH18BAK | Heat pump without ducts | | 11,800 | $590 |
| No | 206350393 | COMFORTMAKER | DLCSRBH09AAK | DLFSCAH09XAK | | 6,100 | $305 |
| No | 206350394 | COMFORTMAKER | DLCSRBH09AAK | DLFSDAH09XAK | | 6,400 | $320 |
| No | 206396078 | COMFORTMAKER | DLCSRBH12AAK | DLFSHAH12XAK | | 7,500 | $375 |
| No | 206396079 | COMFORTMAKER | DLCSRAH12AAK | DLFSHBH12XAK | | 7,500 | $375 |
| No | 206396082 | COMFORTMAKER | DLCSRAH24AAK | DLFSHBH24XAK | | 15,000 | $750 |
| No | 206396083 | COMFORTMAKER | DLCSRBH24AAK | DLFSHAH24XAK | | 15,000 | $750 |
| No | 206350395 | COMFORTMAKER | DLCSRBH12AAK | DLFSCAH12XAK | | 7,900 | $395 |
| No | 206350396 | COMFORTMAKER | DLCSRBH12AAK | DLFSDAH12XAK | | 8,300 | $415 |
| No | 206361877 | COMFORTMAKER | DLCSRBH24AAK | DLFSHBH24XAK | | 17,000 | $850 |
| No | 206361876 | COMFORTMAKER | DLCSRBH18AAK | DLFSHBH18XAK | | 11,100 | $555 |
| No | 206361873 | COMFORTMAKER | DLCSRBH12AAJ | DLFSHBH12XAJ | | 8,200 | $410 |
| No | 206350397 | COMFORTMAKER | DLCSRBH12AAK | DLFSFAH12XAK | | 8,400 | $420 |
| No | 206361875 | COMFORTMAKER | DLCSRBH12AAK | DLFSHBH12XAK | | 7,300 | $365 |
| No | 206361874 | COMFORTMAKER | DLCSRBH09AAK | DLFSHBH09XAK | | 7,400 | $370 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205767344 | COMFORTMAKER | DLCLRBH48AAK | DLFLAAH48XAK | | 36,000 | $1,800 |
| No | 205767343 | COMFORTMAKER | DLCLRBH36AAK | DLFLAAH36XAK | | 25,000 | $1,250 |
| No | 201835568 | COMFORTMAKER | DLCSRAH36AAK | DLFSHAH36XAK | | 20,600 | $1,030 |
| No | 202463644 | COMFORTMAKER | DLCPRAH18AAK | DLFPHAH18XAK | | 12,300 | $615 |
| No | 201835575 | COMFORTMAKER | DLCMRAH48EAK | Heat pump without ducts | | 30,400 | $1,520 |
| No | 201835574 | COMFORTMAKER | DLCMRAH36DAK | Heat pump without ducts | | 23,600 | $1,180 |
| No | 201835562 | COMFORTMAKER | DLCSRAH12AAJ | DLFSHAH12XAJ | | 7,100 | $355 |
| No | 201835555 | COMFORTMAKER | DLCPRAH12AAK | DLFPHAH12XAK | | 6,800 | $340 |
| No | 201835554 | COMFORTMAKER | DLCPRAH09AAK | DLFPHAH09XAK | | 7,200 | $360 |
| No | 201835563 | COMFORTMAKER | DLCSRAH09AAK | DLFSHAH09XAK | | 7,500 | $375 |
| No | 201835571 | COMFORTMAKER | DLCLRAH58AAK | DLFLDAH58XAK | | 37,600 | $1,880 |
| No | 201835595 | COMFORTMAKER | DLCLRAH58AAK | DLFLFAH58XAK | | 39,000 | $1,950 |
| No | 201835565 | COMFORTMAKER | DLCSRAH18AAK | DLFSHAH18XAK | | 11,900 | $595 |
| No | 201835564 | COMFORTMAKER | DLCSRAH12AAK | DLFSHAH12XAK | | 7,600 | $380 |
| No | 201835594 | COMFORTMAKER | DLCLRAH48AAK | DLFLCAH48XAK | | 35,000 | $1,750 |
| No | 201835570 | COMFORTMAKER | DLCLRAH48AAK | DLFLDAH48XAK | | 33,400 | $1,670 |
| No | 201835569 | COMFORTMAKER | DLCLRAH36AAK | DLFLDAH36XAK | | 27,600 | $1,380 |
| No | 201835584 | COMFORTMAKER | DLCSRAH12AAK | DLFSDAH12XAK | | 8,100 | $405 |
| No | 201835583 | COMFORTMAKER | DLCSRAH12AAK | DLFSFAH12XAK | | 9,600 | $480 |
| No | 201835591 | COMFORTMAKER | DLCLRAH36AAK | DLFLCAH36XAK | | 25,200 | $1,260 |
| No | 201835581 | COMFORTMAKER | DLCSRAH09AAK | DLFSCAH09XAK | | 6,700 | $335 |
| No | 201835585 | COMFORTMAKER | DLCSRAH18AAK | DLFSFAH18XAK | | 12,900 | $645 |
| No | 201835582 | COMFORTMAKER | DLCSRAH12AAK | DLFSCAH12XAK | | 8,200 | $410 |
| No | 201835590 | COMFORTMAKER | DLCLRAH36AAK | DLFLFAH36XAK | | 25,400 | $1,270 |
| No | 201835580 | COMFORTMAKER | DLCSRAH09AAK | DLFSDAH09XAK | | 6,800 | $340 |
| No | 208142957 | COMFORTSTAR | CPR60CD(O) | AHU60-SG2 | | 37,000 | $1,850 |
| No | 208142956 | COMFORTSTAR | CPR48CD(O) | AHU48-SG2 | | 37,000 | $1,850 |
| No | 208142955 | COMFORTSTAR | CPR36CD(O) | AHU36-SG2 | | 20,400 | $1,020 |
| No | 208142953 | COMFORTSTAR | CPR24CD(O) | AHU24-SG2 | | 21,000 | $1,050 |
| No | 208142952 | COMFORTSTAR | CPR18CD(O) | AHU18-SG2 | | 12,000 | $600 |
| No | 207658973 | COMFORTSTAR | CMZ-54-5Z | Heat pump without ducts | | 34,000 | $1,700 |
| No | 207658970 | COMFORTSTAR | CMZ-48-4Z | Heat pump without ducts | | 26,800 | $1,340 |
| No | 207658968 | COMFORTSTAR | CMZ-27-3Z | Heat pump with ducts | | 22,000 | $1,100 |
| No | 207658965 | COMFORTSTAR | CMZ-18-2Z | Heat pump with ducts | | 14,800 | $740 |
| No | 207658967 | COMFORTSTAR | CMZ-27-3Z | Heat pump without ducts | | 21,000 | $1,050 |
| No | 207658964 | COMFORTSTAR | CMZ-18-2Z | Heat pump without ducts | | 14,300 | $715 |
| No | 207658932 | COMFORTSTAR | CZP18CD(O) | CPA-18B | | 12,600 | $630 |
| No | 207658945 | COMFORTSTAR | CZP18CD(O) | TPA-18C | | 12,000 | $600 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207765975 | COMFORTSTAR | CZP18CD(O) | TPA-18 | | 12,000 | $600 |
| No | 207658955 | COMFORTSTAR | CZP18CD(O) | FPA-18 | | 12,800 | $640 |
| No | 207765976 | COMFORTSTAR | CZP24CD(O) | TIP24 | | 19,000 | $950 |
| No | 207658946 | COMFORTSTAR | CZP24CD(O) | TPA-24C | | 19,000 | $950 |
| No | 207658941 | COMFORTSTAR | CHF36CD(O) | CPA-36C | | 34,000 | $1,700 |
| No | 207765965 | COMFORTSTAR | CHF36CD(O) | CPA-36DUB | | 34,000 | $1,700 |
| No | 207658935 | COMFORTSTAR | CZP48CD(O) | CPA-48DUB | | 34,000 | $1,700 |
| No | 207765968 | COMFORTSTAR | CZP48CD(O) | TIP48 | | 30,000 | $1,500 |
| No | 207658948 | COMFORTSTAR | CZP48CD(O) | TPA-48C | | 30,000 | $1,500 |
| No | 207658958 | COMFORTSTAR | CZP48CD(O) | FPA-48DU | | 29,000 | $1,450 |
| No | 207658934 | COMFORTSTAR | CZP36CD(O) | CPA-36DUB | | 25,000 | $1,250 |
| No | 207765967 | COMFORTSTAR | CZP36CD(O) | TIP36 | | 23,000 | $1,150 |
| No | 207658947 | COMFORTSTAR | CZP36CD(O) | TPA-36C | | 23,000 | $1,150 |
| No | 207658957 | COMFORTSTAR | CZP36CD(O) | FPA-36DU | | 23,000 | $1,150 |
| No | 207658925 | COMFORTSTAR | CZP24CD(O) | CHF24CD(I) | | 16,200 | $810 |
| No | 207658923 | COMFORTSTAR | CZP12CD(O) | CHF12CD(I) | | 9,000 | $450 |
| No | 207658922 | COMFORTSTAR | CZP09CD(O) | CHF09CD(I) | | 8,500 | $425 |
| No | 207658918 | COMFORTSTAR | CGS24CD(O) | CGS24CD(I) | | 16,500 | $825 |
| No | 207804186 | COMFORTSTAR | CHI24CD(O) | CHI24CD(I) | | 16,500 | $825 |
| No | 207804185 | COMFORTSTAR | CHI18CD(O) | CHI18CD(I) | | 11,400 | $570 |
| No | 207658917 | COMFORTSTAR | CGS18CD(O) | CGS18CD(I) | | 11,400 | $570 |
| No | 207658916 | COMFORTSTAR | CGS12CD(O) | CGS12CD(I) | | 7,000 | $350 |
| No | 207804184 | COMFORTSTAR | CHI12CD(O) | CHI12CD(I) | | 7,000 | $350 |
| No | 207826041 | COMFORTSTAR | CGS09CD(O) | CGS09CD(I) | | 6,000 | $300 |
| No | 207804183 | COMFORTSTAR | CHI12CA(O) | CHI12CA(I) | | 7,800 | $390 |
| No | 207658915 | COMFORTSTAR | CGS12CA(O) | CGS12CA(I) | | 7,800 | $390 |
| No | 207658914 | COMFORTSTAR | CGS09CA(O) | CGS09CA(I) | | 6,300 | $315 |
| No | 207658933 | COMFORTSTAR | CZP24CD(O) | CPA-24B | | 20,000 | $1,000 |
| No | 207658951 | COMFORTSTAR | CHF18CD(O) | TPA-18 | | 15,600 | $780 |
| No | 207658960 | COMFORTSTAR | CHF18CD(O) | FPA-18 | | 12,000 | $600 |
| No | 207658938 | COMFORTSTAR | CHF12CD(O) | CPA-12C | | 10,600 | $530 |
| No | 207765970 | COMFORTSTAR | CHF12CD(O) | CPA-12B | | 10,600 | $530 |
| No | 207658950 | COMFORTSTAR | CHF12CD(O) | TPA-12 | | 9,900 | $495 |
| No | 207658931 | COMFORTSTAR | CZP12CD(O) | CPA-12B | | 9,300 | $465 |
| No | 207765969 | COMFORTSTAR | CHF09CD(O) | CPA-09B | | 10,100 | $505 |
| No | 207658937 | COMFORTSTAR | CHF09CD(O) | CPA-09C | | 10,100 | $505 |
| No | 207658949 | COMFORTSTAR | CHF09CD(O) | TPA-09 | | 9,000 | $450 |
| No | 207658930 | COMFORTSTAR | CZP09CD(O) | CPA-09B | | 7,700 | $385 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207658956 | COMFORTSTAR | CZP24CD(O) | FPA-24 | | 16,000 | $800 |
| No | 207765974 | COMFORTSTAR | CZP12CD(O) | TPA-12 | | 8,900 | $445 |
| No | 207658944 | COMFORTSTAR | CZP12CD(O) | TPA-12C | | 8,900 | $445 |
| No | 207658943 | COMFORTSTAR | CZP09CD(O) | TPA-09C | | 7,500 | $375 |
| No | 207765973 | COMFORTSTAR | CZP09CD(O) | TPA-09 | | 7,500 | $375 |
| No | 207658927 | COMFORTSTAR | CHF12CD(O) | CHF12CD(I) | | 10,000 | $500 |
| No | 207658926 | COMFORTSTAR | CHF09CD(O) | CHF09CD(I) | | 9,500 | $475 |
| No | 207658921 | COMFORTSTAR | CZP12CA(O) | CHF12CA(I) | | 8,400 | $420 |
| No | 9119308 | COMFORTSTAR | CPP009CD(O) | TPA-09 | | 5,800 | $290 |
| No | 202575859 | COMFORTSTAR | CPP009CD(O) | CXH009CD(I) | | 5,800 | $290 |
| No | 10595495 | COMFORTSTAR | CXH009CD(O) | CXH009CD(I) | | 6,900 | $345 |
| No | 202575861 | COMFORTSTAR | CPP018CD(O) | CXH018CD(I) | | 11,400 | $570 |
| No | 202575860 | COMFORTSTAR | CPP012CD(O) | CXH012CD(I) | | 7,700 | $385 |
| No | 202575878 | COMFORTSTAR | CM4-36-4ZX | Heat pump with ducts | | 24,600 | $1,230 |
| No | 202575862 | COMFORTSTAR | CPP024CD(O) | CXH024CD(I) | | 15,300 | $765 |
| No | 9119316 | COMFORTSTAR | CPP024CD(O) | TPA-24 | | 15,800 | $790 |
| No | 202575864 | COMFORTSTAR | CXH012CD(O) | TPA-12 | | 8,700 | $435 |
| No | 202575858 | COMFORTSTAR | CPP12CA(O)-B | CXH012CA(I) | | 7,600 | $380 |
| No | 202575867 | COMFORTSTAR | CXH012CD(O) | CPA-12B | | 8,500 | $425 |
| No | 8854585 | COMFORTSTAR | CPP018CD(O) | CPP018CD(I) | | 10,400 | $520 |
| No | 202576840 | COMFORTSTAR | CPG009CA(O)-B | CPG009CA(I)-B | | 6,000 | $300 |
| No | 202576844 | COMFORTSTAR | CPG018CD(O)-B | CPG018CD(I)-B | | 11,000 | $550 |
| No | 10595500 | COMFORTSTAR | CPP048CD(O)-DU | CPA-48DUB | | 33,400 | $1,670 |
| No | 8854582 | COMFORTSTAR | CPP009CD(O) | CPP009CD(I) | | 6,400 | $320 |
| No | 9119315 | COMFORTSTAR | CPP024CD(O) | FPA-24 | | 15,000 | $750 |
| No | 10595506 | COMFORTSTAR | CPP024CD(O) | CPA-24B | | 16,000 | $800 |
| No | 201763956 | COMFORTSTAR | CM2-18-2Z | Heat pump without ducts | | 12,000 | $600 |
| No | 201763958 | COMFORTSTAR | CM3-27-3Z | Heat pump without ducts | | 17,200 | $860 |
| No | 201763963 | COMFORTSTAR | CM4-48-4Z | Heat pump without ducts | | 24,600 | $1,230 |
| No | 8854583 | COMFORTSTAR | CPP012CA(O) | CPP012CA(I) | | 7,100 | $355 |
| No | 201763961 | COMFORTSTAR | CM5-54-5Z | Heat pump without ducts | | 29,600 | $1,480 |
| No | 10595503 | COMFORTSTAR | CPP009CD(O) | CPA-09B | | 6,800 | $340 |
| No | 202575857 | COMFORTSTAR | CPP09CA(O)-B | CXH009CA(I) | | 6,000 | $300 |
| No | 202575866 | COMFORTSTAR | CXH009CD(O) | CPA-09B | | 7,200 | $360 |
| No | 10595496 | COMFORTSTAR | CXH012CD(O) | CXH012CD(I) | | 7,800 | $390 |
| No | 9119310 | COMFORTSTAR | CPP012CD(O) | TPA-12 | | 7,500 | $375 |
| No | 9119312 | COMFORTSTAR | CPP018CD(O) | FPA-18 | | 12,000 | $600 |
| No | 9119313 | COMFORTSTAR | CPP018CD(O) | TPA-18 | | 12,000 | $600 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10595505 | COMFORTSTAR | CPP018CD(O) | CPA-18B | | 12,000 | $600 |
| No | 9119319 | COMFORTSTAR | CPP036CD(O)-DU | TPA-36DU | | 25,200 | $1,260 |
| No | 10595499 | COMFORTSTAR | CPP036CD(O)-DU | CPA-36DUB | | 27,600 | $1,380 |
| No | 9119321 | COMFORTSTAR | CPP048CD(O)-DU | FPA-48DU | | 35,000 | $1,750 |
| No | 10595502 | COMFORTSTAR | CPP060CD(O)-DU | FPA-60DU | | 39,000 | $1,950 |
| No | 9119322 | COMFORTSTAR | CPP048CD(O)-DU | TPA-48DU | | 35,000 | $1,750 |
| No | 10595501 | COMFORTSTAR | CPP060CD(O)-DU | CPA-60DU | | 37,600 | $1,880 |
| No | 202575853 | COMFORTSTAR | CPP009CD(O) | CXH009CD(I)-WIFI | | 5,800 | $290 |
| No | 202575873 | COMFORTSTAR | CM4-36-4ZX | Heat pump without ducts | | 23,200 | $1,160 |
| No | 202575855 | COMFORTSTAR | CPP018CD(O) | CXH018CD(I)-WIFI | | 11,400 | $570 |
| No | 202575854 | COMFORTSTAR | CPP012CD(O) | CXH012CD(I)-WIFI | | 7,700 | $385 |
| No | 202575856 | COMFORTSTAR | CPP024CD(O) | CXH024CD(I)-WIFI | | 15,300 | $765 |
| No | 202575851 | COMFORTSTAR | CPP09CA(O)-B | CXH009CA(I)-WIFI | | 6,000 | $300 |
| No | 202575852 | COMFORTSTAR | CPP12CA(O)-B | CXH012CA(I)-WIFI | | 7,600 | $380 |
| No | 207698038 | COMFORTSTAR | CPR36CD(O) | AHU36-SG2 | | 18,400 | $920 |
| No | 207804188 | COMFORTSTAR | CHI36CD(O) | CHI36CD(I) | | 20,000 | $1,000 |
| No | 207658978 | COMFORTSTAR | CVH-18-2SH | Combination heat pumps with or without ducts | | 11,500 | $575 |
| No | 207658975 | COMFORTSTAR | CMZ-54-5Z | Combination heat pumps with or without ducts | | 30,000 | $1,500 |
| No | 207658969 | COMFORTSTAR | CMZ-27-3Z | Combination heat pumps with or without ducts | | 16,000 | $800 |
| No | 207658974 | COMFORTSTAR | CMZ-54-5Z | Heat pump with ducts | | 30,400 | $1,520 |
| No | 207658966 | COMFORTSTAR | CMZ-18-2Z | Combination heat pumps with or without ducts | | 11,400 | $570 |
| No | 207658920 | COMFORTSTAR | CGS36CD(O) | CGS36CD(I) | | 20,000 | $1,000 |
| No | 207690471 | COMFORTSTAR | CPR60CD(O) | AHU60-SG2 | | 33,800 | $1,690 |
| No | 207690468 | COMFORTSTAR | CPR30CD(O) | AHU30-SG2 | | 19,000 | $950 |
| No | 207690469 | COMFORTSTAR | CPR36CD(0) | AHU36-SG2 | | 18,400 | $920 |
| No | 207690470 | COMFORTSTAR | CPR48CD(O) | AHU48-SG2 | | 33,000 | $1,650 |
| No | 207690466 | COMFORTSTAR | CPR18CD(O) | AHU18-SG2 | | 11,500 | $575 |
| No | 207690467 | COMFORTSTAR | CPR24CD(O) | AHU24-SG2 | | 17,000 | $850 |
| No | 207658924 | COMFORTSTAR | CZP18CD(O) | CHF18CD(I) | | 12,700 | $635 |
| No | 208142954 | COMFORTSTAR | CPR30CD(O) | AHU30-SG2 | | 19,000 | $950 |
| No | 207658981 | COMFORTSTAR | CVH-27-3SH | Combination heat pumps with or without ducts | | 17,000 | $850 |
| No | 207658959 | COMFORTSTAR | CZP60CD(O) | FPA-60DU | | 35,000 | $1,750 |
| No | 207658936 | COMFORTSTAR | CZP60CD(O) | CPA-60DU | | 37,000 | $1,850 |
| No | 9008899 | CONCERTO | MOB30-12HFN1-MV0W | MSVPC-12HRFN1-MU0W | | 8,400 | $420 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211034566 | CONCORD | 4DHV2S12S-1L | DWH212S4-*L | | 7,800 | $390 |
| No | 211034565 | CONCORD | 4DHV2S09S-1L | DWH209S4-*L | | 6,300 | $315 |
| No | 211034545 | CONCORD | 4DHP2S12S-1L | DWM212S4-*L | | 8,400 | $420 |
| No | 211034570 | CONCORD | 4DHV2S24S-1P | DWH224S4-*P | | 16,500 | $825 |
| No | 211034569 | CONCORD | 4DHV2S18S-1P | DWH218S4-*P | | 11,400 | $570 |
| No | 211034568 | CONCORD | 4DHV2S12S-1P | DWH212S4-*P | | 7,000 | $350 |
| No | 211034567 | CONCORD | 4DHV2S09S-1P | DWH209S4-*P | | 6,000 | $300 |
| No | 211034564 | CONCORD | 4DHP2S48S-1P | D33C248S4-*P | | 30,000 | $1,500 |
| No | 211034563 | CONCORD | 4DHP2S36S-1P | D33C236S4-*P | | 23,000 | $1,150 |
| No | 211034562 | CONCORD | 4DHP2S24S-1P | D33C224S4-*P | | 19,000 | $950 |
| No | 211034561 | CONCORD | 4DHP2S18S-1P | D22C118S4-*P | | 12,000 | $600 |
| No | 211034560 | CONCORD | 4DHP2S12S-1P | D22C112S4-*P | | 8,900 | $445 |
| No | 211034559 | CONCORD | 4DHPS209S-1P | D22C109S4-*P | | 7,500 | $375 |
| No | 211034558 | CONCORD | 4DHP2S48S-1P | DMD248S4-*P | | 34,000 | $1,700 |
| No | 211034557 | CONCORD | 4DHP2S36S-1P | DMD236S4-*P | | 25,000 | $1,250 |
| No | 211034556 | CONCORD | 4DHP2S24S-1P | DMD224S4-*P | | 20,000 | $1,000 |
| No | 211034555 | CONCORD | 4DHP2S18S-1P | DMD218S4-*P | | 12,600 | $630 |
| No | 211034554 | CONCORD | 4DHP2S12S-1P | DMD212S4-*P | | 9,300 | $465 |
| No | 211034553 | CONCORD | 4DHPS209S-1P | DMD209S4-*P | | 7,700 | $385 |
| No | 211034550 | CONCORD | 4DHP2S30S-1P | DWM230S4-*P | | 19,000 | $950 |
| No | 211034549 | CONCORD | 4DHP2S24S-1P | DWM224S4-*P | | 16,200 | $810 |
| No | 211034548 | CONCORD | 4DHP2S18S-1P | DWM218S4-*P | | 14,900 | $745 |
| No | 211034547 | CONCORD | 4DHP2S12S-1P | DWM212S4-*P | | 9,000 | $450 |
| No | 211034546 | CONCORD | 4DHPS209S-1P | DWM209S4-*P | | 8,500 | $425 |
| No | 208106756 | CONCORD | 4DHV2S24S-1P | DWH224S4-1P | | 16,500 | $825 |
| No | 208106755 | CONCORD | 4DHV2S18S-1P | DWH218S4-1P | | 11,400 | $570 |
| No | 208106754 | CONCORD | 4DHV2S12S-1P | DWH212S4-1P | | 7,000 | $350 |
| No | 208106752 | CONCORD | 4DHV2S12S-1L | DWH212S4-1L | | 7,800 | $390 |
| No | 208106753 | CONCORD | 4DHV2S09S-1P | DWH209S4-1P | | 6,000 | $300 |
| No | 208106751 | CONCORD | 4DHV2S09S-1L | DWH209S4-1L | | 6,300 | $315 |
| No | 208106747 | CONCORD | 4DHPS209S-1P | DWM209S4-1P | | 8,500 | $425 |
| No | 208106750 | CONCORD | 4DHPS209S-1P | DMD209S4-1P | | 7,700 | $385 |
| No | 208106749 | CONCORD | 4DHPS209S-1P | D22C109S4-1P | | 7,500 | $375 |
| No | 208106836 | CONCORD | 4DHP2S36M-1P | Heat pump without ducts | | 26,800 | $1,340 |
| No | 208106833 | CONCORD | 4DHP2S30M-1P | Heat pump without ducts | | 21,000 | $1,050 |
| No | 208106834 | CONCORD | 4DHP2S30M-1P | Heat pump with ducts | | 22,000 | $1,100 |
| No | 208106692 | CONCORD | 4DHP2S24S-1P | DWM224S4-1P | | 16,200 | $810 |
| No | 208106831 | CONCORD | 4DHP2S24M-1P | Heat pump with ducts | | 21,600 | $1,080 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208106830 | CONCORD | 4DHP2S24M-1P | Heat pump without ducts | | 20,400 | $1,020 |
| No | 208106697 | CONCORD | 4DHP2S18S-1P | DMD218S4-1P | | 12,600 | $630 |
| No | 208106691 | CONCORD | 4DHP2S18S-1P | DWM218S4-1P | | 14,900 | $745 |
| No | 208106828 | CONCORD | 4DHP2S18M-1P | Heat pump with ducts | | 14,800 | $740 |
| No | 208106827 | CONCORD | 4DHP2S18M-1P | Heat pump without ducts | | 14,300 | $715 |
| No | 208106690 | CONCORD | 4DHP2S12S-1P | DWM212S4-1P | | 9,000 | $450 |
| No | 208106696 | CONCORD | 4DHP2S12S-1P | DMD212S4-1P | | 9,300 | $465 |
| No | 208106693 | CONCORD | 4DHP2S12S-1P | D22C112S4-1P | | 8,900 | $445 |
| No | 208106746 | CONCORD | 4DHP2S12S-1L | DWM212S4-1L | | 8,400 | $420 |
| No | 206906262 | CONCORD | 4HP18V36P | E*1P36A+H4TXV02 | 80G2UH070AE12L | 23,400 | $1,170 |
| No | 206906427 | CONCORD | 4HP18V36P | EAC4X36A | 80G2UH070AE12L | 22,800 | $1,140 |
| No | 206906335 | CONCORD | 4HP18V36P | EA(C,U)1P36A+H4TXV02 | 80G2UH070AE12L | 22,800 | $1,140 |
| No | 206906477 | CONCORD | 4HP18V36P | EAH1P30A+H4TXV01 | 80G2UH070AE12L | 15,800 | $790 |
| No | 206906406 | CONCORD | 4HP18V36P | EAC4X30A | 80G2UH070AE12L | 15,800 | $790 |
| No | 206906314 | CONCORD | 4HP18V36P | EA(C,U)1P30A+H4TXV01 | 80G2UH070AE12L | 15,800 | $790 |
| No | 206906293 | CONCORD | 4HP18V36P | EA(C,U)1P24A+H4TXV01 | 80G2UH070AE12L | 16,100 | $805 |
| No | 206906279 | CONCORD | 4HP18V36P | E*1P36C+H4TXV02 | 80G2UH110CE16 | 23,400 | $1,170 |
| No | 206906287 | CONCORD | 4HP18V36P | E*1P36C+H4TXV02 | EFV16CCA | 23,200 | $1,160 |
| No | 206906286 | CONCORD | 4HP18V36P | E*1P36C+H4TXV02 | 96G2UH090CV12 | 23,200 | $1,160 |
| No | 206906285 | CONCORD | 4HP18V36P | E*1P36C+H4TXV02 | 96G1UH090CE16 | 23,400 | $1,170 |
| No | 206906282 | CONCORD | 4HP18V36P | E*1P36C+H4TXV02 | 92G1UH110CE16 | 23,200 | $1,160 |
| No | 206906281 | CONCORD | 4HP18V36P | E*1P36C+H4TXV02 | 92G1UH090CE16 | 23,200 | $1,160 |
| No | 206906280 | CONCORD | 4HP18V36P | E*1P36C+H4TXV02 | 92G1UH090CE12 | 23,400 | $1,170 |
| No | 206906278 | CONCORD | 4HP18V36P | E*1P36B+H4TXV02 | EFV12BCA | 23,400 | $1,170 |
| No | 206906277 | CONCORD | 4HP18V36P | E*1P36B+H4TXV02 | 96G2UH070BV12 | 23,400 | $1,170 |
| No | 206906276 | CONCORD | 4HP18V36P | E*1P36B+H4TXV02 | 96G2UH045BV12 | 23,600 | $1,180 |
| No | 206906275 | CONCORD | 4HP18V36P | E*1P36B+H4TXV02 | 96G1UH070BE12 | 23,200 | $1,160 |
| No | 206906273 | CONCORD | 4HP18V36P | E*1P36B+H4TXV02 | 92G1UH070BE12 | 23,400 | $1,170 |
| No | 206906272 | CONCORD | 4HP18V36P | E*1P36B+H4TXV02 | 92G1UH045BE12 | 23,400 | $1,170 |
| No | 206906271 | CONCORD | 4HP18V36P | E*1P36B+H4TXV02 | 92G1UH030BE12 | 23,400 | $1,170 |
| No | 206906268 | CONCORD | 4HP18V36P | E*1P36B+H4TXV02 | 80G2UH090BE16 | 23,400 | $1,170 |
| No | 206906267 | CONCORD | 4HP18V36P | E*1P36B+H4TXV02 | 80G2UH090BE12 | 23,400 | $1,170 |
| No | 206906266 | CONCORD | 4HP18V36P | E*1P36B+H4TXV02 | 80G1UH090BE16 | 23,200 | $1,160 |
| No | 206906265 | CONCORD | 4HP18V36P | E*1P36B+H4TXV02 | 80G1UH080BE16X | 23,600 | $1,180 |
| No | 206906264 | CONCORD | 4HP18V36P | E*1P36B+H4TXV02 | 80G1UH070BE12 | 23,200 | $1,160 |
| No | 206906261 | CONCORD | 4HP18V36P | E*1P36A+H4TXV02 | 80G2UH070AE12 | 23,400 | $1,170 |
| No | 206906260 | CONCORD | 4HP18V36P | E*1P36A+H4TXV02 | 80G1UH070AE12 | 23,200 | $1,160 |
| No | 206906259 | CONCORD | 4HP18V36P | E*1P36A+H4TXV02 | 80G1UH060AE12X | 23,200 | $1,160 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206906258 | CONCORD | 4HP18V36P | E*1P36A+H4TXV02 | 80G1UH045AE12 | 23,200 | $1,160 |
| No | 206906602 | CONCORD | 4HP18V36P | ED1P30/36C+H4TXV02 | 96G1DF090CE16 | 22,200 | $1,110 |
| No | 206906600 | CONCORD | 4HP18V36P | ED1P30/36C+H4TXV02 | 92G1DF090CE16 | 22,200 | $1,110 |
| No | 206906599 | CONCORD | 4HP18V36P | ED1P30/36B+H4TXV02 | 96G2DF070BV16 | 22,600 | $1,130 |
| No | 206906597 | CONCORD | 4HP18V36P | ED1P30/36B+H4TXV02 | 96G1DF070BE16 | 22,400 | $1,120 |
| No | 206906596 | CONCORD | 4HP18V36P | ED1P30/36B+H4TXV02 | 96G1DF045BE12 | 22,000 | $1,100 |
| No | 206906593 | CONCORD | 4HP18V36P | ED1P30/36B+H4TXV02 | 92G1DF070BE12 | 22,400 | $1,120 |
| No | 206906592 | CONCORD | 4HP18V36P | ED1P30/36B+H4TXV02 | 92G1DF045BE12 | 22,400 | $1,120 |
| No | 206906590 | CONCORD | 4HP18V36P | ED1P30/36B+H4TXV02 | 80G1DF090BE16 | 22,200 | $1,110 |
| No | 206906589 | CONCORD | 4HP18V36P | ED1P30/36B+H4TXV02 | 80G1DF070BE12 | 22,000 | $1,100 |
| No | 206906587 | CONCORD | 4HP18V36P | ED1P30/36A+H4TXV02 | 80G1DF070AE12 | 22,200 | $1,110 |
| No | 206906524 | CONCORD | 4HP18V36P | EAH1P48B+H4TXV02 | EFV12BCA | 22,000 | $1,100 |
| No | 206906523 | CONCORD | 4HP18V36P | EAH1P48B+H4TXV02 | 96G2UH070BV12 | 22,400 | $1,120 |
| No | 206906522 | CONCORD | 4HP18V36P | EAH1P48B+H4TXV02 | 96G2UH045BV12 | 22,400 | $1,120 |
| No | 206906521 | CONCORD | 4HP18V36P | EAH1P48B+H4TXV02 | 96G1UH070BE12 | 22,000 | $1,100 |
| No | 206906519 | CONCORD | 4HP18V36P | EAH1P48B+H4TXV02 | 92G1UH070BE12 | 22,200 | $1,110 |
| No | 206906518 | CONCORD | 4HP18V36P | EAH1P48B+H4TXV02 | 92G1UH045BE12 | 22,400 | $1,120 |
| No | 206906517 | CONCORD | 4HP18V36P | EAH1P48B+H4TXV02 | 92G1UH030BE12 | 22,200 | $1,110 |
| No | 206906516 | CONCORD | 4HP18V36P | EAH1P48B+H4TXV02 | 80G2UH090BV16* | 22,400 | $1,120 |
| No | 206906514 | CONCORD | 4HP18V36P | EAH1P48B+H4TXV02 | 80G2UH090BE16 | 22,200 | $1,110 |
| No | 206906513 | CONCORD | 4HP18V36P | EAH1P48B+H4TXV02 | 80G2UH090BE12 | 22,400 | $1,120 |
| No | 206906512 | CONCORD | 4HP18V36P | EAH1P48B+H4TXV02 | 80G1UH090BE16 | 22,000 | $1,100 |
| No | 206906511 | CONCORD | 4HP18V36P | EAH1P48B+H4TXV02 | 80G1UH070BE12 | 22,000 | $1,100 |
| No | 206906510 | CONCORD | 4HP18V36P | EAH1P36B+H4TXV02 | EFV12BCA | 22,200 | $1,110 |
| No | 206906509 | CONCORD | 4HP18V36P | EAH1P36B+H4TXV02 | 96G2UH070BV12 | 22,200 | $1,110 |
| No | 206906508 | CONCORD | 4HP18V36P | EAH1P36B+H4TXV02 | 96G2UH045BV12 | 22,400 | $1,120 |
| No | 206906507 | CONCORD | 4HP18V36P | EAH1P36B+H4TXV02 | 96G1UH070BE12 | 21,800 | $1,090 |
| No | 206906503 | CONCORD | 4HP18V36P | EAH1P36B+H4TXV02 | 92G1UH070BE12 | 22,200 | $1,110 |
| No | 206906502 | CONCORD | 4HP18V36P | EAH1P36B+H4TXV02 | 92G1UH045BE12 | 22,200 | $1,110 |
| No | 206906501 | CONCORD | 4HP18V36P | EAH1P36B+H4TXV02 | 92G1UH030BE12 | 22,200 | $1,110 |
| No | 206906500 | CONCORD | 4HP18V36P | EAH1P36B+H4TXV02 | 80G2UH090BV16* | 22,000 | $1,100 |
| No | 206906498 | CONCORD | 4HP18V36P | EAH1P36B+H4TXV02 | 80G2UH090BE16 | 22,200 | $1,110 |
| No | 206906497 | CONCORD | 4HP18V36P | EAH1P36B+H4TXV02 | 80G2UH090BE12 | 22,200 | $1,110 |
| No | 206906496 | CONCORD | 4HP18V36P | EAH1P36B+H4TXV02 | 80G1UH090BE16 | 22,000 | $1,100 |
| No | 206906495 | CONCORD | 4HP18V36P | EAH1P36B+H4TXV02 | 80G1UH080BE16X | 22,200 | $1,110 |
| No | 206906494 | CONCORD | 4HP18V36P | EAH1P36B+H4TXV02 | 80G1UH070BE12 | 22,000 | $1,100 |
| No | 206906471 | CONCORD | 4HP18V36P | EAC4X48C | EFV16CCA | 21,600 | $1,080 |
| No | 206906470 | CONCORD | 4HP18V36P | EAC4X48C | 96G2UH090CV12 | 21,600 | $1,080 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206906469 | CONCORD | 4HP18V36P | EAC4X48C | 96G1UH090CE16 | 21,600 | $1,080 |
| No | 206906468 | CONCORD | 4HP18V36P | EAC4X48C | 95G1UH090CE16 | 21,600 | $1,080 |
| No | 206906466 | CONCORD | 4HP18V36P | EAC4X48C | 92G1UH110CE16 | 21,400 | $1,070 |
| No | 206906465 | CONCORD | 4HP18V36P | EAC4X48C | 92G1UH090CE16 | 21,600 | $1,080 |
| No | 206906464 | CONCORD | 4HP18V36P | EAC4X48C | 92G1UH090CE12 | 21,800 | $1,090 |
| No | 206906463 | CONCORD | 4HP18V36P | EAC4X48C | 80G2UH110CE16 | 21,600 | $1,080 |
| No | 206906462 | CONCORD | 4HP18V36P | EAC4X48B | EFV12BCA | 21,600 | $1,080 |
| No | 206906461 | CONCORD | 4HP18V36P | EAC4X48B | 96G2UH070BV12 | 21,800 | $1,090 |
| No | 206906460 | CONCORD | 4HP18V36P | EAC4X48B | 96G2UH045BV12 | 21,800 | $1,090 |
| No | 206906459 | CONCORD | 4HP18V36P | EAC4X48B | 96G1UH070BE12 | 21,400 | $1,070 |
| No | 206906458 | CONCORD | 4HP18V36P | EAC4X48B | 96G1UH045BE12 | 21,400 | $1,070 |
| No | 206906455 | CONCORD | 4HP18V36P | EAC4X48B | 92G1UH070BE12 | 21,600 | $1,080 |
| No | 206906454 | CONCORD | 4HP18V36P | EAC4X48B | 92G1UH045BE12 | 21,800 | $1,090 |
| No | 206906453 | CONCORD | 4HP18V36P | EAC4X48B | 92G1UH030BE12 | 21,600 | $1,080 |
| No | 206906452 | CONCORD | 4HP18V36P | EAC4X48B | 80G2UH090BV16* | 21,600 | $1,080 |
| No | 206906450 | CONCORD | 4HP18V36P | EAC4X48B | 80G2UH090BE16 | 21,600 | $1,080 |
| No | 206906449 | CONCORD | 4HP18V36P | EAC4X48B | 80G2UH090BE12 | 21,800 | $1,090 |
| No | 206906448 | CONCORD | 4HP18V36P | EAC4X48B | 80G1UH090BE16 | 21,600 | $1,080 |
| No | 206906447 | CONCORD | 4HP18V36P | EAC4X48B | 80G1UH080BE16X | 21,800 | $1,090 |
| No | 206906446 | CONCORD | 4HP18V36P | EAC4X48B | 80G1UH070BE12 | 21,600 | $1,080 |
| No | 206906378 | CONCORD | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 96G2UH090CV12 | 21,600 | $1,080 |
| No | 206906377 | CONCORD | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 96G1UH090CE16 | 21,600 | $1,080 |
| No | 206906376 | CONCORD | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 95G1UH090CE16 | 21,600 | $1,080 |
| No | 206906374 | CONCORD | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 92G1UH110CE16 | 21,400 | $1,070 |
| No | 206906373 | CONCORD | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 92G1UH090CE16 | 21,600 | $1,080 |
| No | 206906372 | CONCORD | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 92G1UH090CE12 | 21,800 | $1,090 |
| No | 206906371 | CONCORD | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 80G2UH110CE16 | 21,600 | $1,080 |
| No | 206906370 | CONCORD | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | EFV12BCA | 21,800 | $1,090 |
| No | 206906369 | CONCORD | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 96G2UH070BV12 | 21,800 | $1,090 |
| No | 206906368 | CONCORD | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 96G2UH045BV12 | 21,800 | $1,090 |
| No | 206906367 | CONCORD | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 96G1UH070BE12 | 21,400 | $1,070 |
| No | 206906366 | CONCORD | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 96G1UH045BE12 | 21,400 | $1,070 |
| No | 206906363 | CONCORD | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 92G1UH070BE12 | 21,600 | $1,080 |
| No | 206906362 | CONCORD | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 92G1UH045BE12 | 21,800 | $1,090 |
| No | 206906361 | CONCORD | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 92G1UH030BE12 | 21,600 | $1,080 |
| No | 206906360 | CONCORD | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 80G2UH090BV16* | 21,600 | $1,080 |
| No | 206906358 | CONCORD | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 80G2UH090BE16 | 21,600 | $1,080 |
| No | 206906357 | CONCORD | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 80G2UH090BE12 | 21,800 | $1,090 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206906356 | CONCORD | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 80G1UH090BE16 | 21,600 | $1,080 |
| No | 206906355 | CONCORD | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 80G1UH080BE16X | 21,800 | $1,090 |
| No | 206906445 | CONCORD | 4HP18V36P | EAC4X36B | EFV12BCA | 22,800 | $1,140 |
| No | 206906444 | CONCORD | 4HP18V36P | EAC4X36B | 96G2UH070BV12 | 22,800 | $1,140 |
| No | 206906443 | CONCORD | 4HP18V36P | EAC4X36B | 96G2UH045BV12 | 23,000 | $1,150 |
| No | 206906442 | CONCORD | 4HP18V36P | EAC4X36B | 96G1UH070BE12 | 22,400 | $1,120 |
| No | 206906438 | CONCORD | 4HP18V36P | EAC4X36B | 92G1UH070BE12 | 22,800 | $1,140 |
| No | 206906437 | CONCORD | 4HP18V36P | EAC4X36B | 92G1UH045BE12 | 22,800 | $1,140 |
| No | 206906436 | CONCORD | 4HP18V36P | EAC4X36B | 92G1UH030BE12 | 22,600 | $1,130 |
| No | 206906433 | CONCORD | 4HP18V36P | EAC4X36B | 80G2UH090BE16 | 22,800 | $1,140 |
| No | 206906432 | CONCORD | 4HP18V36P | EAC4X36B | 80G2UH090BE12 | 22,800 | $1,140 |
| No | 206906431 | CONCORD | 4HP18V36P | EAC4X36B | 80G1UH090BE16 | 22,600 | $1,130 |
| No | 206906430 | CONCORD | 4HP18V36P | EAC4X36B | 80G1UH080BE16X | 22,800 | $1,140 |
| No | 206906429 | CONCORD | 4HP18V36P | EAC4X36B | 80G1UH070BE12 | 22,600 | $1,130 |
| No | 206906426 | CONCORD | 4HP18V36P | EAC4X36A | 80G2UH070AE12 | 22,800 | $1,140 |
| No | 206906425 | CONCORD | 4HP18V36P | EAC4X36A | 80G1UH070AE12 | 22,600 | $1,130 |
| No | 206906424 | CONCORD | 4HP18V36P | EAC4X36A | 80G1UH060AE12X | 22,400 | $1,120 |
| No | 206906423 | CONCORD | 4HP18V36P | EAC4X36A | 80G1UH045AE12 | 22,400 | $1,120 |
| No | 206906353 | CONCORD | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | EFV12BCA | 22,000 | $1,100 |
| No | 206906352 | CONCORD | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 96G2UH070BV12 | 22,800 | $1,140 |
| No | 206906351 | CONCORD | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 96G2UH045BV12 | 23,000 | $1,150 |
| No | 206906346 | CONCORD | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 92G1UH070BE12 | 22,800 | $1,140 |
| No | 206906345 | CONCORD | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 92G1UH045BE12 | 22,800 | $1,140 |
| No | 206906344 | CONCORD | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 92G1UH030BE12 | 22,600 | $1,130 |
| No | 206906341 | CONCORD | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 80G2UH090BE16 | 22,800 | $1,140 |
| No | 206906340 | CONCORD | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 80G2UH090BE12 | 22,800 | $1,140 |
| No | 206906339 | CONCORD | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 80G1UH090BE16 | 22,600 | $1,130 |
| No | 206906338 | CONCORD | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 80G1UH080BE16X | 22,800 | $1,140 |
| No | 206906337 | CONCORD | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 80G1UH070BE12 | 22,600 | $1,130 |
| No | 206906334 | CONCORD | 4HP18V36P | EA(C,U)1P36A+H4TXV02 | 80G2UH070AE12 | 22,800 | $1,140 |
| No | 206906333 | CONCORD | 4HP18V36P | EA(C,U)1P36A+H4TXV02 | 80G1UH070AE12 | 22,600 | $1,130 |
| No | 206906332 | CONCORD | 4HP18V36P | EA(C,U)1P36A+H4TXV02 | 80G1UH060AE12X | 22,400 | $1,120 |
| No | 206906331 | CONCORD | 4HP18V36P | EA(C,U)1P36A+H4TXV02 | 80G1UH045AE12 | 22,400 | $1,120 |
| No | 206906235 | CONCORD | 4HP18V36P | BCE7E36M | | 23,400 | $1,170 |
| No | 206906223 | CONCORD | 4HP18V36P | BCE5C36M*4X | | 22,400 | $1,120 |
| No | 206906222 | CONCORD | 4HP18V36P | BCE5C36M*1P+H4TXV02 | | 22,400 | $1,120 |
| No | 206906227 | CONCORD | 4HP18V36P | BCE5E42M | | 22,200 | $1,110 |
| No | 206906226 | CONCORD | 4HP18V36P | BCE5E36M | | 22,600 | $1,130 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206906231 | CONCORD | 4HP18V36P | BCE5V42M | | 22,200 | $1,110 |
| No | 206906236 | CONCORD | 4HP18V36P | BCE7E42M | | 22,000 | $1,100 |
| No | 206905447 | CONCORD | 4HP18V36P | BCE5V36M | | 22,000 | $1,100 |
| No | 206906255 | CONCORD | 4HP18V36P | E*1P23B+H4TXV01 | 96G2UH070BV12 | 15,100 | $755 |
| No | 206906254 | CONCORD | 4HP18V36P | E*1P23B+H4TXV01 | 96G2UH045BV12 | 15,100 | $755 |
| No | 206906257 | CONCORD | 4HP18V36P | E*1P23B+H4TXV01 | EFV12BCA | 15,200 | $760 |
| No | 206906256 | CONCORD | 4HP18V36P | E*1P23B+H4TXV01 | EFV08BCA | 15,300 | $765 |
| No | 206906248 | CONCORD | 4HP18V36P | E*1P23B+H4TXV01 | 92G1UH070BE12 | 15,300 | $765 |
| No | 206906247 | CONCORD | 4HP18V36P | E*1P23B+H4TXV01 | 92G1UH045BE12 | 15,400 | $770 |
| No | 206906246 | CONCORD | 4HP18V36P | E*1P23B+H4TXV01 | 92G1UH030BE12 | 15,300 | $765 |
| No | 206906245 | CONCORD | 4HP18V36P | E*1P23B+H4TXV01 | 80G2UH090BE12 | 15,300 | $765 |
| No | 206906244 | CONCORD | 4HP18V36P | E*1P23B+H4TXV01 | 80G1UH070BE12 | 15,000 | $750 |
| No | 206906241 | CONCORD | 4HP18V36P | E*1P23A+H4TXV01 | 80G2UH070AE12 | 15,400 | $770 |
| No | 206906240 | CONCORD | 4HP18V36P | E*1P23A+H4TXV01 | 80G2UH045AE12 | 14,900 | $745 |
| No | 206906239 | CONCORD | 4HP18V36P | E*1P23A+H4TXV01 | 80G1UH060AE12X | 15,300 | $765 |
| No | 206906238 | CONCORD | 4HP18V36P | E*1P23A+H4TXV01 | 80G1UH045AE12 | 15,200 | $760 |
| No | 206906237 | CONCORD | 4HP18V36P | E*1P23A+H4TXV01 | 80G1UH040AE12X | 15,300 | $765 |
| No | 206906493 | CONCORD | 4HP18V36P | EAH1P30B+H4TXV01 | EFV12BCA | 15,600 | $780 |
| No | 206906492 | CONCORD | 4HP18V36P | EAH1P30B+H4TXV01 | EFV08BCA | 15,700 | $785 |
| No | 206906491 | CONCORD | 4HP18V36P | EAH1P30B+H4TXV01 | 96G2UH070BV12 | 15,500 | $775 |
| No | 206906490 | CONCORD | 4HP18V36P | EAH1P30B+H4TXV01 | 96G2UH045BV12 | 15,600 | $780 |
| No | 206906489 | CONCORD | 4HP18V36P | EAH1P30B+H4TXV01 | 96G1UH070BE12 | 15,900 | $795 |
| No | 206906487 | CONCORD | 4HP18V36P | EAH1P30B+H4TXV01 | 96G1UH030BE08 | 15,800 | $790 |
| No | 206906483 | CONCORD | 4HP18V36P | EAH1P30B+H4TXV01 | 92G1UH070BE12 | 15,800 | $790 |
| No | 206906482 | CONCORD | 4HP18V36P | EAH1P30B+H4TXV01 | 92G1UH045BE12 | 15,900 | $795 |
| No | 206906481 | CONCORD | 4HP18V36P | EAH1P30B+H4TXV01 | 92G1UH030BE12 | 15,800 | $790 |
| No | 206906480 | CONCORD | 4HP18V36P | EAH1P30B+H4TXV01 | 80G2UH090BE12 | 15,800 | $790 |
| No | 206906479 | CONCORD | 4HP18V36P | EAH1P30B+H4TXV01 | 80G1UH070BE12 | 15,500 | $775 |
| No | 206906476 | CONCORD | 4HP18V36P | EAH1P30A+H4TXV01 | 80G2UH070AE12 | 15,800 | $790 |
| No | 206906475 | CONCORD | 4HP18V36P | EAH1P30A+H4TXV01 | 80G2UH045AE12 | 15,400 | $770 |
| No | 206906474 | CONCORD | 4HP18V36P | EAH1P30A+H4TXV01 | 80G1UH060AE12X | 15,700 | $785 |
| No | 206906473 | CONCORD | 4HP18V36P | EAH1P30A+H4TXV01 | 80G1UH045AE12 | 15,700 | $785 |
| No | 206906472 | CONCORD | 4HP18V36P | EAH1P30A+H4TXV01 | 80G1UH040AE12X | 15,700 | $785 |
| No | 206906420 | CONCORD | 4HP18V36P | EAC4X30B | 96G2UH070BV12 | 15,500 | $775 |
| No | 206906419 | CONCORD | 4HP18V36P | EAC4X30B | 96G2UH045BV12 | 15,600 | $780 |
| No | 206906422 | CONCORD | 4HP18V36P | EAC4X30B | EFV12BCA | 15,600 | $780 |
| No | 206906421 | CONCORD | 4HP18V36P | EAC4X30B | EFV08BCA | 15,900 | $795 |
| No | 206906418 | CONCORD | 4HP18V36P | EAC4X30B | 96G1UH070BE12 | 15,900 | $795 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206906416 | CONCORD | 4HP18V36P | EAC4X30B | 96G1UH030BE08 | 15,800 | $790 |
| No | 206906412 | CONCORD | 4HP18V36P | EAC4X30B | 92G1UH070BE12 | 15,800 | $790 |
| No | 206906411 | CONCORD | 4HP18V36P | EAC4X30B | 92G1UH045BE12 | 15,900 | $795 |
| No | 206906410 | CONCORD | 4HP18V36P | EAC4X30B | 92G1UH030BE12 | 15,800 | $790 |
| No | 206906409 | CONCORD | 4HP18V36P | EAC4X30B | 80G2UH090BE12 | 15,800 | $790 |
| No | 206906408 | CONCORD | 4HP18V36P | EAC4X30B | 80G1UH070BE12 | 15,600 | $780 |
| No | 206906405 | CONCORD | 4HP18V36P | EAC4X30A | 80G2UH070AE12 | 15,800 | $790 |
| No | 206906404 | CONCORD | 4HP18V36P | EAC4X30A | 80G2UH045AE12 | 15,800 | $790 |
| No | 206906403 | CONCORD | 4HP18V36P | EAC4X30A | 80G1UH060AE12X | 15,800 | $790 |
| No | 206906402 | CONCORD | 4HP18V36P | EAC4X30A | 80G1UH045AE12 | 15,700 | $785 |
| No | 206906401 | CONCORD | 4HP18V36P | EAC4X30A | 80G1UH040AE12X | 15,800 | $790 |
| No | 206906328 | CONCORD | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 96G2UH070BV12 | 15,500 | $775 |
| No | 206906327 | CONCORD | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 96G2UH045BV12 | 15,600 | $780 |
| No | 206906330 | CONCORD | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | EFV12BCA | 15,600 | $780 |
| No | 206906329 | CONCORD | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | EFV08BCA | 15,900 | $795 |
| No | 206906326 | CONCORD | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 96G1UH070BE12 | 15,900 | $795 |
| No | 206906324 | CONCORD | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 96G1UH030BE08 | 15,800 | $790 |
| No | 206906320 | CONCORD | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 92G1UH070BE12 | 15,800 | $790 |
| No | 206906319 | CONCORD | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 92G1UH045BE12 | 15,900 | $795 |
| No | 206906318 | CONCORD | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 92G1UH030BE12 | 15,800 | $790 |
| No | 206906317 | CONCORD | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 80G2UH090BE12 | 15,800 | $790 |
| No | 206906316 | CONCORD | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 80G1UH070BE12 | 15,600 | $780 |
| No | 206906313 | CONCORD | 4HP18V36P | EA(C,U)1P30A+H4TXV01 | 80G2UH070AE12 | 15,800 | $790 |
| No | 206906312 | CONCORD | 4HP18V36P | EA(C,U)1P30A+H4TXV01 | 80G2UH045AE12 | 15,800 | $790 |
| No | 206906311 | CONCORD | 4HP18V36P | EA(C,U)1P30A+H4TXV01 | 80G1UH060AE12X | 15,800 | $790 |
| No | 206906310 | CONCORD | 4HP18V36P | EA(C,U)1P30A+H4TXV01 | 80G1UH045AE12 | 15,700 | $785 |
| No | 206906309 | CONCORD | 4HP18V36P | EA(C,U)1P30A+H4TXV01 | 80G1UH040AE12X | 15,800 | $790 |
| No | 206906398 | CONCORD | 4HP18V36P | EAC4X24B | 96G2UH070BV12 | 15,900 | $795 |
| No | 206906397 | CONCORD | 4HP18V36P | EAC4X24B | 96G2UH045BV12 | 16,000 | $800 |
| No | 206906400 | CONCORD | 4HP18V36P | EAC4X24B | EFV12BCA | 16,000 | $800 |
| No | 206906391 | CONCORD | 4HP18V36P | EAC4X24B | 92G1UH070BE12 | 16,200 | $810 |
| No | 206906390 | CONCORD | 4HP18V36P | EAC4X24B | 92G1UH045BE12 | 16,200 | $810 |
| No | 206906388 | CONCORD | 4HP18V36P | EAC4X24B | 80G2UH090BE12 | 16,100 | $805 |
| No | 206906387 | CONCORD | 4HP18V36P | EAC4X24B | 80G1UH070BE12 | 15,900 | $795 |
| No | 206906384 | CONCORD | 4HP18V36P | EAC4X24A | 80G2UH070AE12 | 16,100 | $805 |
| No | 206906382 | CONCORD | 4HP18V36P | EAC4X24A | 80G1UH060AE12X | 16,100 | $805 |
| No | 206906380 | CONCORD | 4HP18V36P | EAC4X24A | 80G1UH040AE12X | 16,100 | $805 |
| No | 206906305 | CONCORD | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 96G2UH045BV12 | 16,000 | $800 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206906306 | CONCORD | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 96G2UH070BV12 | 15,900 | $795 |
| No | 206906308 | CONCORD | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | EFV12BCA | 16,000 | $800 |
| No | 206906307 | CONCORD | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | EFV08BCA | 16,300 | $815 |
| No | 206906299 | CONCORD | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 92G1UH070BE12 | 16,200 | $810 |
| No | 206906298 | CONCORD | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 92G1UH045BE12 | 16,200 | $810 |
| No | 206906296 | CONCORD | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 80G2UH090BE12 | 16,100 | $805 |
| No | 206906295 | CONCORD | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 80G1UH070BE12 | 15,900 | $795 |
| No | 206906292 | CONCORD | 4HP18V36P | EA(C,U)1P24A+H4TXV01 | 80G2UH070AE12 | 16,100 | $805 |
| No | 206906290 | CONCORD | 4HP18V36P | EA(C,U)1P24A+H4TXV01 | 80G1UH060AE12X | 16,100 | $805 |
| No | 206906288 | CONCORD | 4HP18V36P | EA(C,U)1P24A+H4TXV01 | 80G1UH040AE12X | 16,100 | $805 |
| No | 206906234 | CONCORD | 4HP18V36P | BCE7E30M | | 16,200 | $810 |
| No | 206906233 | CONCORD | 4HP18V36P | BCE7E24M | | 15,800 | $790 |
| No | 206906232 | CONCORD | 4HP18V36P | BCE7E18M | | 15,400 | $770 |
| No | 206906230 | CONCORD | 4HP18V36P | BCE5V30M | | 15,900 | $795 |
| No | 206906228 | CONCORD | 4HP18V36P | BCE5V18M | | 15,900 | $795 |
| No | 206906225 | CONCORD | 4HP18V36P | BCE5E30M | | 15,900 | $795 |
| No | 206906224 | CONCORD | 4HP18V36P | BCE5E24M | | 15,000 | $750 |
| No | 206906221 | CONCORD | 4HP18V36P | BCE5C24M*4X | | 16,100 | $805 |
| No | 206906220 | CONCORD | 4HP18V36P | BCE5C24M*1P+H4TXV01 | | 16,100 | $805 |
| No | 206906219 | CONCORD | 4HP18V36P | BCE5C18M*4X | | 15,400 | $770 |
| No | 206906218 | CONCORD | 4HP18V36P | BCE5C18M*1P+H4TXV01 | | 15,400 | $770 |
| No | 206906229 | CONCORD | 4HP18V36P | BCE5V24M | | 16,100 | $805 |
| No | 206906999 | CONCORD | 4HP18V60P | E*1P50C+H4TXV03 | 96G2UH110CV20 | 39,000 | $1,950 |
| No | 206906998 | CONCORD | 4HP18V60P | E*1P50C+H4TXV03 | 96G2UH090CV20 | 39,500 | $1,975 |
| No | 206906997 | CONCORD | 4HP18V60P | E*1P50C+H4TXV03 | 96G1UH110CE20 | 39,000 | $1,950 |
| No | 206906994 | CONCORD | 4HP18V60P | E*1P50C+H4TXV03 | 92G1UH110CE20 | 39,000 | $1,950 |
| No | 206906993 | CONCORD | 4HP18V60P | E*1P50C+H4TXV03 | 80G2UH110CV20 | 39,000 | $1,950 |
| No | 206906992 | CONCORD | 4HP18V60P | E*1P50C+H4TXV03 | 80G2UH110CE20L | 39,500 | $1,975 |
| No | 206906991 | CONCORD | 4HP18V60P | E*1P50C+H4TXV03 | 80G2UH110CE20 | 39,500 | $1,975 |
| No | 206906990 | CONCORD | 4HP18V60P | E*1P50C+H4TXV03 | 80G1UH110CE20 | 39,500 | $1,975 |
| No | 206906989 | CONCORD | 4HP18V60P | E*1P50C+H4TXV03 | 80G1UH100CE20X | 39,500 | $1,975 |
| No | 206906988 | CONCORD | 4HP18V60P | E*1P50C+H4TXV03 | 80G1UH090CE20 | 39,500 | $1,975 |
| No | 206907169 | CONCORD | 4HP18V60P | ED1P60D+H4TXV03 | EFV20DCA | 38,000 | $1,900 |
| No | 206907124 | CONCORD | 4HP18V60P | EAC4X60D | EFV20DCA | 40,000 | $2,000 |
| No | 206907123 | CONCORD | 4HP18V60P | EAC4X60D | 96G2UH135DV20 | 40,000 | $2,000 |
| No | 206907122 | CONCORD | 4HP18V60P | EAC4X60D | 80G1UH135DE20 | 40,000 | $2,000 |
| No | 206907118 | CONCORD | 4HP18V60P | EAC4X60C | 96G1UH110CE20 | 37,800 | $1,890 |
| No | 206907111 | CONCORD | 4HP18V60P | EAC4X60C | 80G1UH110CE20 | 38,000 | $1,900 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206907110 | CONCORD | 4HP18V60P | EAC4X60C | 80G1UH100CE20X | 38,000 | $1,900 |
| No | 206907109 | CONCORD | 4HP18V60P | EAC4X60C | 80G1UH090CE20 | 38,000 | $1,900 |
| No | 206907062 | CONCORD | 4HP18V60P | EA(C,U)1P60D+H4TXV03 | EFV20DCA | 40,000 | $2,000 |
| No | 206907056 | CONCORD | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 96G1UH110CE20 | 37,800 | $1,890 |
| No | 206907049 | CONCORD | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 80G1UH110CE20 | 38,000 | $1,900 |
| No | 206907048 | CONCORD | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 80G1UH100CE20X | 38,000 | $1,900 |
| No | 206907047 | CONCORD | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 80G1UH090CE20 | 38,000 | $1,900 |
| No | 206907164 | CONCORD | 4HP18V60P | ED1P50/60C+H4TXV02 | EFV16CCA | 30,400 | $1,520 |
| No | 206907096 | CONCORD | 4HP18V60P | EAC4X49C | EFV16CCA | 30,600 | $1,530 |
| No | 206907085 | CONCORD | 4HP18V60P | EAC4X49C | 80G2UH110CE16 | 30,200 | $1,510 |
| No | 206907034 | CONCORD | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | EFV16CCA | 30,600 | $1,530 |
| No | 206907023 | CONCORD | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | 80G2UH110CE16 | 30,200 | $1,510 |
| No | 206907113 | CONCORD | 4HP18V60P | EAC4X60C | 80G2UH110CE20L | 38,000 | $1,900 |
| No | 206907051 | CONCORD | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 80G2UH110CE20L | 38,000 | $1,900 |
| No | 206907130 | CONCORD | 4HP18V60P | EAH1P48C+H4TXV02 | 80G2UH110CE20L | 31,000 | $1,550 |
| No | 206907165 | CONCORD | 4HP18V60P | ED1P60D+H4TXV03 | 80G1DF110CE20 | 38,000 | $1,900 |
| No | 206907168 | CONCORD | 4HP18V60P | ED1P60D+H4TXV03 | 96G2DF110CV20 | 38,500 | $1,925 |
| No | 206907167 | CONCORD | 4HP18V60P | ED1P60D+H4TXV03 | 96G2DF090CV20 | 38,500 | $1,925 |
| No | 206907142 | CONCORD | 4HP18V60P | EAH1P51C+H4TXV03 | 80G1UH090CE20 | 36,800 | $1,840 |
| No | 206907061 | CONCORD | 4HP18V60P | EA(C,U)1P60D+H4TXV03 | 96G2UH135DV20 | 39,000 | $1,950 |
| No | 206907060 | CONCORD | 4HP18V60P | EA(C,U)1P60D+H4TXV03 | 80G1UH135DE20 | 39,000 | $1,950 |
| No | 206907120 | CONCORD | 4HP18V60P | EAC4X60C | 96G2UH110CV20 | 38,000 | $1,900 |
| No | 206907119 | CONCORD | 4HP18V60P | EAC4X60C | 96G2UH090CV20 | 38,000 | $1,900 |
| No | 206907115 | CONCORD | 4HP18V60P | EAC4X60C | 92G1UH110CE20 | 37,800 | $1,890 |
| No | 206907114 | CONCORD | 4HP18V60P | EAC4X60C | 80G2UH110CV20 | 38,000 | $1,900 |
| No | 206907112 | CONCORD | 4HP18V60P | EAC4X60C | 80G2UH110CE20 | 38,000 | $1,900 |
| No | 206907058 | CONCORD | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 96G2UH110CV20 | 38,000 | $1,900 |
| No | 206907057 | CONCORD | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 96G2UH090CV20 | 38,000 | $1,900 |
| No | 206907053 | CONCORD | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 92G1UH110CE20 | 37,800 | $1,890 |
| No | 206907052 | CONCORD | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 80G2UH110CV20 | 38,000 | $1,900 |
| No | 206907050 | CONCORD | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 80G2UH110CE20 | 38,000 | $1,900 |
| No | 206906605 | CONCORD | 4HP18V60P | BCE5V60M | | 38,500 | $1,925 |
| No | 206907095 | CONCORD | 4HP18V60P | EAC4X49C | 96G2UH110CV20 | 30,600 | $1,530 |
| No | 206907094 | CONCORD | 4HP18V60P | EAC4X49C | 96G2UH090CV20 | 30,800 | $1,540 |
| No | 206907089 | CONCORD | 4HP18V60P | EAC4X49C | 92G1UH110CE20 | 30,400 | $1,520 |
| No | 206907086 | CONCORD | 4HP18V60P | EAC4X49C | 80G2UH110CV20 | 30,400 | $1,520 |
| No | 206907084 | CONCORD | 4HP18V60P | EAC4X49C | 80G1UH110CE20 | 30,400 | $1,520 |
| No | 206907083 | CONCORD | 4HP18V60P | EAC4X49C | 80G1UH100CE20X | 30,600 | $1,530 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206907033 | CONCORD | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | 96G2UH110CV20 | 30,600 | $1,530 |
| No | 206907032 | CONCORD | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | 96G2UH090CV20 | 30,800 | $1,540 |
| No | 206907027 | CONCORD | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | 92G1UH110CE20 | 30,400 | $1,520 |
| No | 206907024 | CONCORD | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | 80G2UH110CV20 | 30,400 | $1,520 |
| No | 206907022 | CONCORD | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | 80G1UH110CE20 | 30,400 | $1,520 |
| No | 206907021 | CONCORD | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | 80G1UH100CE20X | 30,600 | $1,530 |
| No | 206907131 | CONCORD | 4HP18V60P | EAH1P48C+H4TXV02 | 80G2UH110CV20 | 31,000 | $1,550 |
| No | 206907140 | CONCORD | 4HP18V60P | EAH1P48C+H4TXV02 | 96G2UH110CV20 | 31,200 | $1,560 |
| No | 206907139 | CONCORD | 4HP18V60P | EAH1P48C+H4TXV02 | 96G2UH090CV20 | 31,400 | $1,570 |
| No | 206907134 | CONCORD | 4HP18V60P | EAH1P48C+H4TXV02 | 92G1UH110CE20 | 30,800 | $1,540 |
| No | 206907129 | CONCORD | 4HP18V60P | EAH1P48C+H4TXV02 | 80G2UH110CE20 | 31,000 | $1,550 |
| No | 206907127 | CONCORD | 4HP18V60P | EAH1P48C+H4TXV02 | 80G1UH110CE20 | 30,800 | $1,540 |
| No | 206907125 | CONCORD | 4HP18V60P | EAH1P48C+H4TXV02 | 80G1UH090CE20 | 30,800 | $1,540 |
| No | 206906987 | CONCORD | 4HP18V60P | BCE7E48M | | 32,200 | $1,610 |
| No | 206906984 | CONCORD | 4HP18V60P | BCE5E48M | | 31,600 | $1,580 |
| No | 206906983 | CONCORD | 4HP18V60P | BCE5C48M*4X | | 31,600 | $1,580 |
| No | 206906982 | CONCORD | 4HP18V60P | BCE5C48M*1P+H4TXV02 | | 31,600 | $1,580 |
| No | 206906986 | CONCORD | 4HP18V60P | BCE5V48M | | 31,400 | $1,570 |
| No | 206906591 | CONCORD | 4HP18V36P | ED1P30/36B+H4TXV02 | 80G2DF090BE16 | 22,200 | $1,110 |
| No | 206906354 | CONCORD | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 80G1UH070BE12 | 21,600 | $1,080 |
| No | 206906435 | CONCORD | 4HP18V36P | EAC4X36B | 80G2UH090BV16* | 22,800 | $1,140 |
| No | 206906343 | CONCORD | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 80G2UH090BV16* | 22,800 | $1,140 |
| No | 206906585 | CONCORD | 4HP18V36P | ED1P24B+H4TXV01 | EFV12BCA | 15,500 | $775 |
| No | 206906584 | CONCORD | 4HP18V36P | ED1P24B+H4TXV01 | EFV08BCA | 15,700 | $785 |
| No | 206906583 | CONCORD | 4HP18V36P | ED1P24B+H4TXV01 | 96G2DF070BV16 | 15,800 | $790 |
| No | 206906488 | CONCORD | 4HP18V36P | EAH1P30B+H4TXV01 | 96G1UH045BE12 | 15,900 | $795 |
| No | 206906478 | CONCORD | 4HP18V36P | EAH1P30A+H4TXV01 | 80G2UH070AV12* | 15,600 | $780 |
| No | 206906414 | CONCORD | 4HP18V36P | EAC4X30B | 95G1UH045BE12 | 15,800 | $790 |
| No | 206906407 | CONCORD | 4HP18V36P | EAC4X30A | 80G2UH070AV12* | 15,600 | $780 |
| No | 206906325 | CONCORD | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 96G1UH045BE12 | 15,900 | $795 |
| No | 206906315 | CONCORD | 4HP18V36P | EA(C,U)1P30A+H4TXV01 | 80G2UH070AV12* | 15,600 | $780 |
| No | 206906396 | CONCORD | 4HP18V36P | EAC4X24B | 96G1UH070BE12 | 16,300 | $815 |
| No | 206906395 | CONCORD | 4HP18V36P | EAC4X24B | 96G1UH045BE12 | 16,300 | $815 |
| No | 206906394 | CONCORD | 4HP18V36P | EAC4X24B | 96G1UH030BE08 | 15,800 | $790 |
| No | 206906389 | CONCORD | 4HP18V36P | EAC4X24B | 92G1UH030BE12 | 15,700 | $785 |
| No | 206906386 | CONCORD | 4HP18V36P | EAC4X24A | 80G2UH070AV12* | 16,000 | $800 |
| No | 206906304 | CONCORD | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 96G1UH070BE12 | 16,300 | $815 |
| No | 206906303 | CONCORD | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 96G1UH045BE12 | 16,300 | $815 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206906302 | CONCORD | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 96G1UH030BE08 | 15,800 | $790 |
| No | 206906294 | CONCORD | 4HP18V36P | EA(C,U)1P24A+H4TXV01 | 80G2UH070AV12* | 16,000 | $800 |
| No | 206906253 | CONCORD | 4HP18V36P | E*1P23B+H4TXV01 | 96G1UH070BE12 | 15,400 | $770 |
| No | 206906252 | CONCORD | 4HP18V36P | E*1P23B+H4TXV01 | 96G1UH045BE12 | 15,400 | $770 |
| No | 206906251 | CONCORD | 4HP18V36P | E*1P23B+H4TXV01 | 96G1UH030BE08 | 14,900 | $745 |
| No | 206906243 | CONCORD | 4HP18V36P | E*1P23A+H4TXV01 | 80G2UH070AV12* | 15,200 | $760 |
| No | 206906269 | CONCORD | 4HP18V36P | E*1P36B+H4TXV02 | 80G2UH090BE16L | 23,400 | $1,170 |
| No | 206906515 | CONCORD | 4HP18V36P | EAH1P48B+H4TXV02 | 80G2UH090BE16L | 22,200 | $1,110 |
| No | 206906499 | CONCORD | 4HP18V36P | EAH1P36B+H4TXV02 | 80G2UH090BE16L | 22,200 | $1,110 |
| No | 206906451 | CONCORD | 4HP18V36P | EAC4X48B | 80G2UH090BE16L | 21,600 | $1,080 |
| No | 206906359 | CONCORD | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 80G2UH090BE16L | 21,600 | $1,080 |
| No | 206906434 | CONCORD | 4HP18V36P | EAC4X36B | 80G2UH090BE16L | 22,800 | $1,140 |
| No | 206906342 | CONCORD | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 80G2UH090BE16L | 22,800 | $1,140 |
| No | 208106835 | CONCORD | 4DHP2S30M-1P | Combination heat pumps with or without ducts | | 16,000 | $800 |
| No | 208106832 | CONCORD | 4DHP2S24M-1P | Combination heat pumps with or without ducts | | 16,700 | $835 |
| No | 208106829 | CONCORD | 4DHP2S18M-1P | Combination heat pumps with or without ducts | | 11,400 | $570 |
| No | 206907158 | CONCORD | 4HP18V60P | ED1P50/60C+H4TXV02 | 92G1DF090CE16 | 30,600 | $1,530 |
| No | 206907159 | CONCORD | 4HP18V60P | ED1P50/60C+H4TXV02 | 95G1DF090CE16 | 30,600 | $1,530 |
| No | 206907157 | CONCORD | 4HP18V60P | ED1P50/60C+H4TXV02 | 80G1DF110CE20 | 30,400 | $1,520 |
| No | 206906575 | CONCORD | 4HP18V36P | EC4X36C | EFV16CCA | 22,600 | $1,130 |
| No | 206906574 | CONCORD | 4HP18V36P | EC4X36C | 96G2UH090CV12 | 22,800 | $1,140 |
| No | 206906573 | CONCORD | 4HP18V36P | EC4X36C | 96G1UH090CE16 | 22,800 | $1,140 |
| No | 206906572 | CONCORD | 4HP18V36P | EC4X36C | 95G1UH090CE16 | 23,000 | $1,150 |
| No | 206906571 | CONCORD | 4HP18V36P | EC4X36C | 95G1UH080CE16X | 22,800 | $1,140 |
| No | 206906570 | CONCORD | 4HP18V36P | EC4X36C | 92G1UH110CE16 | 22,800 | $1,140 |
| No | 206906568 | CONCORD | 4HP18V36P | EC4X36C | 92G1UH090CE12 | 23,000 | $1,150 |
| No | 206906567 | CONCORD | 4HP18V36P | EC4X36C | 80G2UH110CE16 | 22,800 | $1,140 |
| No | 206906565 | CONCORD | 4HP18V36P | EC4X36B | 96G2UH070BV12 | 23,000 | $1,150 |
| No | 206906566 | CONCORD | 4HP18V36P | EC4X36B | EFV12BCA | 22,800 | $1,140 |
| No | 206906564 | CONCORD | 4HP18V36P | EC4X36B | 96G2UH045BV12 | 23,000 | $1,150 |
| No | 206906563 | CONCORD | 4HP18V36P | EC4X36B | 96G1UH070BE12 | 23,200 | $1,160 |
| No | 206906569 | CONCORD | 4HP18V36P | EC4X36C | 92G1UH090CE16 | 22,600 | $1,130 |
| No | 206906561 | CONCORD | 4HP18V36P | EC4X36B | 92G1UH070BE12 | 23,200 | $1,160 |
| No | 206906560 | CONCORD | 4HP18V36P | EC4X36B | 92G1UH045BE12 | 23,200 | $1,160 |
| No | 206906562 | CONCORD | 4HP18V36P | EC4X36B | 96G1UH045BE12 | 23,200 | $1,160 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206906559 | CONCORD | 4HP18V36P | EC4X36B | 92G1UH030BE12 | 23,200 | $1,160 |
| No | 206906558 | CONCORD | 4HP18V36P | EC4X36B | 80G2UH090BV16* | 22,800 | $1,140 |
| No | 206906557 | CONCORD | 4HP18V36P | EC4X36B | 80G2UH090BE16L | 22,800 | $1,140 |
| No | 206906554 | CONCORD | 4HP18V36P | EC4X36B | 80G1UH090BE16 | 22,800 | $1,140 |
| No | 206906556 | CONCORD | 4HP18V36P | EC4X36B | 80G2UH090BE16 | 22,800 | $1,140 |
| No | 206906553 | CONCORD | 4HP18V36P | EC4X36B | 80G1UH080BE16X | 22,800 | $1,140 |
| No | 206906555 | CONCORD | 4HP18V36P | EC4X36B | 80G2UH090BE12 | 22,800 | $1,140 |
| No | 206906552 | CONCORD | 4HP18V36P | EC4X36B | 80G1UH070BE12 | 23,000 | $1,150 |
| No | 206906551 | CONCORD | 4HP18V36P | EC4X36A | 80G2UH070AV12* | 23,000 | $1,150 |
| No | 206906550 | CONCORD | 4HP18V36P | EC4X36A | 80G2UH070AE12L | 22,800 | $1,140 |
| No | 206906546 | CONCORD | 4HP18V36P | EC4X36A | 80G1UH045AE12 | 23,000 | $1,150 |
| No | 206906548 | CONCORD | 4HP18V36P | EC4X36A | 80G1UH070AE12 | 23,000 | $1,150 |
| No | 206906547 | CONCORD | 4HP18V36P | EC4X36A | 80G1UH060AE12X | 22,800 | $1,140 |
| No | 206906549 | CONCORD | 4HP18V36P | EC4X36A | 80G2UH070AE12 | 22,800 | $1,140 |
| No | 206906467 | CONCORD | 4HP18V36P | EAC4X48C | 95G1UH080CE16X | 22,000 | $1,100 |
| No | 206906457 | CONCORD | 4HP18V36P | EAC4X48B | 95G1UH060BE12X | 22,000 | $1,100 |
| No | 206906456 | CONCORD | 4HP18V36P | EAC4X48B | 95G1UH040BE12X | 22,000 | $1,100 |
| No | 206906270 | CONCORD | 4HP18V36P | E*1P36B+H4TXV02 | 80G2UH090BV16* | 22,800 | $1,140 |
| No | 206906263 | CONCORD | 4HP18V36P | E*1P36A+H4TXV02 | 80G2UH070AV12* | 23,000 | $1,150 |
| No | 206906520 | CONCORD | 4HP18V36P | EAH1P48B+H4TXV02 | 96G1UH045BE12 | 22,000 | $1,100 |
| No | 206906379 | CONCORD | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | EFV16CCA | 22,000 | $1,100 |
| No | 206906375 | CONCORD | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 95G1UH080CE16X | 22,200 | $1,110 |
| No | 206906365 | CONCORD | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 95G1UH060BE12X | 22,200 | $1,110 |
| No | 206906364 | CONCORD | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 95G1UH040BE12X | 22,200 | $1,110 |
| No | 206906350 | CONCORD | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 96G1UH070BE12 | 22,600 | $1,130 |
| No | 206906349 | CONCORD | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 96G1UH045BE12 | 22,600 | $1,130 |
| No | 206906528 | CONCORD | 4HP18V36P | EC4X23A | 80G2UH045AE12 | 15,000 | $750 |
| No | 206906527 | CONCORD | 4HP18V36P | EC4X23A | 80G1UH060AE12X | 14,900 | $745 |
| No | 206906525 | CONCORD | 4HP18V36P | EC4X23A | 80G1UH040AE12X | 14,900 | $745 |
| No | 206906417 | CONCORD | 4HP18V36P | EAC4X30B | 96G1UH045BE12 | 15,400 | $770 |
| No | 206906526 | CONCORD | 4HP18V36P | EC4X23A | 80G1UH045AE12 | 15,000 | $750 |
| No | 206906415 | CONCORD | 4HP18V36P | EAC4X30B | 95G1UH070BE12 | 15,400 | $770 |
| No | 206906413 | CONCORD | 4HP18V36P | EAC4X30B | 95G1UH040BE12X | 15,500 | $775 |
| No | 206906383 | CONCORD | 4HP18V36P | EAC4X24A | 80G2UH045AE12 | 15,300 | $765 |
| No | 206906385 | CONCORD | 4HP18V36P | EAC4X24A | 80G2UH070AE12L | 15,200 | $760 |
| No | 206906485 | CONCORD | 4HP18V36P | EAH1P30B+H4TXV01 | 95G1UH045BE12 | 15,300 | $765 |
| No | 206906484 | CONCORD | 4HP18V36P | EAH1P30B+H4TXV01 | 95G1UH040BE12X | 15,400 | $770 |
| No | 206906486 | CONCORD | 4HP18V36P | EAH1P30B+H4TXV01 | 95G1UH070BE12 | 15,400 | $770 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206906581 | CONCORD | 4HP18V36P | ED1P24B+H4TXV01 | 96G1DF070BE16 | 15,000 | $750 |
| No | 206906579 | CONCORD | 4HP18V36P | ED1P24B+H4TXV01 | 95G1DF045BE12 | 15,000 | $750 |
| No | 206906578 | CONCORD | 4HP18V36P | ED1P24B+H4TXV01 | 80G1DF070BE12 | 15,000 | $750 |
| No | 206906582 | CONCORD | 4HP18V36P | ED1P24B+H4TXV01 | 96G2DF045BV12 | 15,100 | $755 |
| No | 206906440 | CONCORD | 4HP18V36P | EAC4X36B | 95G1UH060BE12X | 22,000 | $1,100 |
| No | 206906441 | CONCORD | 4HP18V36P | EAC4X36B | 96G1UH045BE12 | 22,600 | $1,130 |
| No | 206906439 | CONCORD | 4HP18V36P | EAC4X36B | 95G1UH040BE12X | 22,000 | $1,100 |
| No | 206906428 | CONCORD | 4HP18V36P | EAC4X36A | 80G2UH070AV12* | 22,200 | $1,110 |
| No | 206906601 | CONCORD | 4HP18V36P | ED1P30/36C+H4TXV02 | 95G1DF090CE16 | 22,000 | $1,100 |
| No | 206906598 | CONCORD | 4HP18V36P | ED1P30/36B+H4TXV02 | 96G2DF045BV12 | 22,200 | $1,110 |
| No | 206906595 | CONCORD | 4HP18V36P | ED1P30/36B+H4TXV02 | 95G1DF070BE16 | 22,000 | $1,100 |
| No | 206906594 | CONCORD | 4HP18V36P | ED1P30/36B+H4TXV02 | 95G1DF045BE12 | 22,400 | $1,120 |
| No | 206906588 | CONCORD | 4HP18V36P | ED1P30/36A+H4TXV02 | 80G2DF070AE12 | 22,000 | $1,100 |
| No | 206906586 | CONCORD | 4HP18V36P | ED1P30/36A+H4TXV02 | 80G1DF045AE12 | 22,200 | $1,110 |
| No | 206906284 | CONCORD | 4HP18V36P | E*1P36C+H4TXV02 | 95G1UH090CE16 | 23,000 | $1,150 |
| No | 206906283 | CONCORD | 4HP18V36P | E*1P36C+H4TXV02 | 95G1UH080CE16X | 22,800 | $1,140 |
| No | 206906274 | CONCORD | 4HP18V36P | E*1P36B+H4TXV02 | 96G1UH045BE12 | 23,200 | $1,160 |
| No | 206906576 | CONCORD | 4HP18V36P | ED1P24A+H4TXV01 | 80G1DF045AE12 | 15,200 | $760 |
| No | 206906577 | CONCORD | 4HP18V36P | ED1P24A+H4TXV01 | 80G2DF070AE12 | 15,100 | $755 |
| No | 206906249 | CONCORD | 4HP18V36P | E*1P23B+H4TXV01 | 95G1UH045BE12 | 14,800 | $740 |
| No | 206906250 | CONCORD | 4HP18V36P | E*1P23B+H4TXV01 | 95G1UH070BE12 | 14,900 | $745 |
| No | 206906242 | CONCORD | 4HP18V36P | E*1P23A+H4TXV01 | 80G2UH070AE12L | 14,900 | $745 |
| No | 206906323 | CONCORD | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 95G1UH070BE12 | 15,400 | $770 |
| No | 206906321 | CONCORD | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 95G1UH040BE12X | 15,500 | $775 |
| No | 206906322 | CONCORD | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 95G1UH045BE12 | 15,400 | $770 |
| No | 206906297 | CONCORD | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 92G1UH030BE12 | 15,300 | $765 |
| No | 206906291 | CONCORD | 4HP18V36P | EA(C,U)1P24A+H4TXV01 | 80G2UH045AE12 | 15,300 | $765 |
| No | 206906348 | CONCORD | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 95G1UH060BE12X | 22,000 | $1,100 |
| No | 206906347 | CONCORD | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 95G1UH040BE12X | 22,000 | $1,100 |
| No | 206906336 | CONCORD | 4HP18V36P | EA(C,U)1P36A+H4TXV02 | 80G2UH070AV12* | 22,200 | $1,110 |
| No | 206906545 | CONCORD | 4HP18V36P | EC4X23B | EFV12BCA | 14,900 | $745 |
| No | 206906544 | CONCORD | 4HP18V36P | EC4X23B | EFV08BCA | 15,100 | $755 |
| No | 206906399 | CONCORD | 4HP18V36P | EAC4X24B | EFV08BCA | 15,400 | $770 |
| No | 206906542 | CONCORD | 4HP18V36P | EC4X23B | 96G2UH045BV12 | 14,900 | $745 |
| No | 206906543 | CONCORD | 4HP18V36P | EC4X23B | 96G2UH070BV12 | 14,800 | $740 |
| No | 206906541 | CONCORD | 4HP18V36P | EC4X23B | 96G1UH070BE12 | 14,800 | $740 |
| No | 206906540 | CONCORD | 4HP18V36P | EC4X23B | 96G1UH045BE12 | 14,900 | $745 |
| No | 206906537 | CONCORD | 4HP18V36P | EC4X23B | 95G1UH045BE12 | 14,800 | $740 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206906539 | CONCORD | 4HP18V36P | EC4X23B | 96G1UH030BE08 | 14,900 | $745 |
| No | 206906538 | CONCORD | 4HP18V36P | EC4X23B | 95G1UH070BE12 | 14,900 | $745 |
| No | 206906536 | CONCORD | 4HP18V36P | EC4X23B | 92G1UH070BE12 | 14,900 | $745 |
| No | 206906535 | CONCORD | 4HP18V36P | EC4X23B | 92G1UH045BE12 | 14,800 | $740 |
| No | 206906534 | CONCORD | 4HP18V36P | EC4X23B | 92G1UH030BE12 | 15,000 | $750 |
| No | 206906533 | CONCORD | 4HP18V36P | EC4X23B | 80G2UH090BE12 | 14,900 | $745 |
| No | 206906531 | CONCORD | 4HP18V36P | EC4X23A | 80G2UH070AV12* | 14,900 | $745 |
| No | 206906532 | CONCORD | 4HP18V36P | EC4X23B | 80G1UH070BE12 | 14,800 | $740 |
| No | 206906529 | CONCORD | 4HP18V36P | EC4X23A | 80G2UH070AE12 | 14,900 | $745 |
| No | 206906530 | CONCORD | 4HP18V36P | EC4X23A | 80G2UH070AE12L | 14,900 | $745 |
| No | 206907000 | CONCORD | 4HP18V60P | E*1P50C+H4TXV03 | EFV16CCA | 39,500 | $1,975 |
| No | 206906996 | CONCORD | 4HP18V60P | E*1P50C+H4TXV03 | 95G1UH110CE20 | 40,000 | $2,000 |
| No | 206906995 | CONCORD | 4HP18V60P | E*1P50C+H4TXV03 | 95G1UH100CE20X | 40,000 | $2,000 |
| No | 206907156 | CONCORD | 4HP18V60P | EAH1P60D+H4TXV03 | EFV20DCA | 36,600 | $1,830 |
| No | 206907166 | CONCORD | 4HP18V60P | ED1P60D+H4TXV03 | 95G1DF110CE20 | 37,400 | $1,870 |
| No | 206907121 | CONCORD | 4HP18V60P | EAC4X60C | EFV16CCA | 37,400 | $1,870 |
| No | 206907117 | CONCORD | 4HP18V60P | EAC4X60C | 95G1UH110CE20 | 37,200 | $1,860 |
| No | 206907116 | CONCORD | 4HP18V60P | EAC4X60C | 95G1UH100CE20X | 38,000 | $1,900 |
| No | 206907059 | CONCORD | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | EFV16CCA | 37,400 | $1,870 |
| No | 206907055 | CONCORD | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 95G1UH110CE20 | 37,200 | $1,860 |
| No | 206907054 | CONCORD | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 95G1UH100CE20X | 38,000 | $1,900 |
| No | 206906985 | CONCORD | 4HP18V60P | BCE5E60M | | 37,800 | $1,890 |
| No | 206907163 | CONCORD | 4HP18V60P | ED1P50/60C+H4TXV02 | 96G2DF110CV20 | 30,800 | $1,540 |
| No | 206907162 | CONCORD | 4HP18V60P | ED1P50/60C+H4TXV02 | 96G2DF090CV20 | 30,800 | $1,540 |
| No | 206907161 | CONCORD | 4HP18V60P | ED1P50/60C+H4TXV02 | 96G1DF090CE16 | 30,800 | $1,540 |
| No | 206907160 | CONCORD | 4HP18V60P | ED1P50/60C+H4TXV02 | 95G1DF110CE20 | 30,400 | $1,520 |
| No | 208106698 | CONCORD | 4DHP2S24S-1P | DMD224S4-1P | | 13,500 | $675 |
| No | 208106772 | CONCORD | 4DHP2S36S-1P | D33C236S4-1P | | 23,000 | $1,150 |
| No | 208106774 | CONCORD | 4DHP2S36S-1P | DMD236S4-2P | | 27,000 | $1,350 |
| No | 208106775 | CONCORD | 4DHP2S48S-1P | DMD248S4-2P | | 29,000 | $1,450 |
| No | 208106773 | CONCORD | 4DHP2S48S-1P | D33C248S4-1P | | 28,000 | $1,400 |
| No | 208106694 | CONCORD | 4DHP2S18S-1P | D22C118S4-1P | | 12,000 | $600 |
| No | 208106695 | CONCORD | 4DHP2S24S-1P | D33C224S4-1P | | 15,600 | $780 |
| No | 210605801 | Conforto | MHSZ106DA | MHWAL06DA | | 8,500 | $425 |
| No | 210605800 | Conforto | ADSZ136DA | ADWAL36DA | | 24,000 | $1,200 |
| No | 210605808 | Conforto | MHSZ118DA | MHCAS18DA | | 15,600 | $780 |
| No | 210605807 | Conforto | MHSZ112DA | MHCAS12DA | | 9,900 | $495 |
| No | 210605806 | Conforto | MHSZ109DA | MHCAS09DA | | 9,000 | $450 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210605803 | Conforto | MHSZ112DA | MHWAL12DA | | 10,000 | $500 |
| No | 210605802 | Conforto | MHSZ109DA | MHWAL09DA | | 9,500 | $475 |
| No | 211624980 | CONTINENTAL | WSEHV4860RA1-C | CPFX48A60A | | 36,000 | $1,800 |
| No | 212404691 | CONTINENTAL | CS18HV48A60 | H,DE50960 | WUV100T5BA | 38,000 | $1,900 |
| No | 212404690 | CONTINENTAL | CS18HV48A60 | H,DE50960 | WUV090T5BA | 38,000 | $1,900 |
| No | 212404692 | CONTINENTAL | CS18HV48A60 | H,DE50960 | WPV100T5BA | 38,000 | $1,900 |
| No | 212404689 | CONTINENTAL | CS18HV48A60 | H,DE50960 | WPV090T5BA | 38,000 | $1,900 |
| No | 212404683 | CONTINENTAL | WSEHV4860RA1-C | H,DE50960 | WUV100T5BA | 38,000 | $1,900 |
| No | 212404682 | CONTINENTAL | WSEHV4860RA1-C | H,DE50960 | WUV090T5BA | 38,000 | $1,900 |
| No | 212404684 | CONTINENTAL | WSEHV4860RA1-C | H,DE50960 | WPV100T5BA | 38,000 | $1,900 |
| No | 212404681 | CONTINENTAL | WSEHV4860RA1-C | H,DE50960 | WPV090T5BA | 38,000 | $1,900 |
| No | 212404715 | CONTINENTAL | CS18HV48A60 | H,DE37960+TXV | WUV080T4BA | 33,000 | $1,650 |
| No | 212404714 | CONTINENTAL | CS18HV48A60 | H,DE37960+TXV | WUV070T4BA | 33,000 | $1,650 |
| No | 212404716 | CONTINENTAL | CS18HV48A60 | H,DE37960+TXV | WPV080T4BA | 33,000 | $1,650 |
| No | 212404713 | CONTINENTAL | CS18HV48A60 | H,DE37960+TXV | WPV070T4BA | 33,000 | $1,650 |
| No | 212404707 | CONTINENTAL | WSEHV4860RA1-C | H,DE37960+TXV | WUV080T4BA | 33,000 | $1,650 |
| No | 212404706 | CONTINENTAL | WSEHV4860RA1-C | H,DE37960+TXV | WUV070T4BA | 33,000 | $1,650 |
| No | 212404708 | CONTINENTAL | WSEHV4860RA1-C | H,DE37960+TXV | WPV080T4BA | 33,000 | $1,650 |
| No | 212404705 | CONTINENTAL | WSEHV4860RA1-C | H,DE37960+TXV | WPV070T4BA | 33,000 | $1,650 |
| No | 203363519 | CONTINENTAL | CH25-09-O | CH25-09-I | | 6,900 | $345 |
| No | 203363520 | CONTINENTAL | CH25-12-O | CH25-12-I | | 7,800 | $390 |
| No | 205309940 | CONTINENTAL | CH21-18-O | CH25-18-I | | 11,400 | $570 |
| No | 205309939 | CONTINENTAL | CH21-12-O | CH25-12-I | | 7,700 | $385 |
| No | 203363526 | CONTINENTAL | CH21-18-O | CH21-18-I | | 10,400 | $520 |
| No | 205309941 | CONTINENTAL | CH21-24-O | CH25-24-I | | 15,300 | $765 |
| No | 203363517 | CONTINENTAL | CMZH-27-O | Heat pump without ducts | | 17,200 | $860 |
| No | 205309943 | CONTINENTAL | CMZH-36-O | Heat pump without ducts | | 24,600 | $1,230 |
| No | 207709205 | Convectair | 8028-C12-O | 8028-C12-I | | 10,000 | $500 |
| No | 207709204 | Convectair | 8028-C09-O | 8028-C09-I | | 9,500 | $475 |
| No | 206422438 | CONVECTAIR | 8180-O | 8180-I | | 10,900 | $545 |
| No | 206422437 | CONVECTAIR | 8120-O | 8120-I | | 7,500 | $375 |
| No | 206422436 | CONVECTAIR | 8090-O | 8090-I | | 7,100 | $355 |
| No | 207590848 | CONVECTAIR | 8222-C18-O | Combination heat pumps with or without ducts | | 11,500 | $575 |
| No | 207590851 | CONVECTAIR | 8322-C27-O | Combination heat pumps with or without ducts | | 17,000 | $850 |
| No | 209049124 | CoolTime | CA18-OD-21 | CA18-ID-21 | | 11,500 | $575 |
| No | 209049125 | CoolTime | CA09-OD-21 | CA09-ID-21 | | 6,800 | $340 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208141206 | Cooper&Hunter | CH-N60LCU-230VO | CH-60AHU | | 37,800 | $1,890 |
| No | 208101229 | Cooper&Hunter | CH-N48LCU-230VO | CH-48AHU | | 38,000 | $1,900 |
| No | 208101230 | Cooper&Hunter | CH-N36LCU-230VO | CH-36AHU | | 27,000 | $1,350 |
| No | 208101233 | Cooper&Hunter | CH-ES24-230VO | CH-M24AHU | | 17,000 | $850 |
| No | 208101231 | Cooper&Hunter | CH-ES18-230VO | CH-M18AHU | | 13,200 | $660 |
| No | 210799641 | COOPER&HUNTER | CH-55MES-230VO | Heat pump without ducts | | 34,400 | $1,720 |
| No | 210799625 | COOPER&HUNTER | CH-48MES-230VO | Heat pump without ducts | | 34,000 | $1,700 |
| No | 210799622 | COOPER&HUNTER | CH-36MES-230VO | Heat pump without ducts | | 26,800 | $1,340 |
| No | 210799620 | COOPER&HUNTER | CH-28MES-230VO | Heat pump with ducts | | 22,000 | $1,100 |
| No | 210799617 | COOPER&HUNTER | CH-18MES-230VO | Heat pump with ducts | | 14,800 | $740 |
| No | 210799619 | COOPER&HUNTER | CH-28MES-230VO | Heat pump without ducts | | 21,000 | $1,050 |
| No | 210799616 | COOPER&HUNTER | CH-18MES-230VO | Heat pump without ducts | | 14,300 | $715 |
| No | 210799696 | Cooper&Hunter | CH-06OLVWM-115VO | CH-06OLVWM-115VI | | 5,900 | $295 |
| No | 210799695 | Cooper&Hunter | CH-ES06-115VO | CH-06OLVWM-115VI | | 5,900 | $295 |
| No | 210799697 | Cooper&Hunter | CH-NY06MIA-115VO | CH-NY06MIA-115VI | | 6,800 | $340 |
| No | 210857416 | Cooper&Hunter | CH-ES09-230VO | CH-06MCT1W-230VI | | 5,700 | $285 |
| No | 210857420 | Cooper&Hunter | CH-HPR06F9-230VO | CH-06MCT1W-230VI | | 5,700 | $285 |
| No | 210857418 | Cooper&Hunter | CH-ES12-230VO | CH-12MCT1W-230VI | | 7,700 | $385 |
| No | 210857422 | Cooper&Hunter | CH-HPR12-230VO | CH-12MCT1W-230VI | | 9,500 | $475 |
| No | 210857421 | Cooper&Hunter | CH-HPR09-230VO | CH-09MCT1W-230VI | | 9,800 | $490 |
| No | 210857417 | Cooper&Hunter | CH-ES09-230VO | CH-09MCT1W-230VI | | 8,000 | $400 |
| No | 210857419 | Cooper&Hunter | CH-ES18-230VO | CH-18MCT1W-230VI | | 12,200 | $610 |
| No | 210799677 | Cooper&Hunter | CH-HPR18-230VO | CH-16MMC-230VI | | 14,700 | $735 |
| No | 210799676 | Cooper&Hunter | CH-ES18-230VO | CH-16MMC-230VI | | 13,400 | $670 |
| No | 210799674 | Cooper&Hunter | CH-ES12-230VO | CH-12MMC-230VI | | 9,200 | $460 |
| No | 210799675 | Cooper&Hunter | CH-HPR12-230VO | CH-12MMC-230VI | | 10,200 | $510 |
| No | 210799608 | Cooper&Hunter | CH-N60LCU-230VO | CH-60LCDTU/I | | 34,400 | $1,720 |
| No | 210799609 | Cooper&Hunter | CH-N60LCU-230VO | CH-60LCFC/I | | 35,000 | $1,750 |
| No | 210799586 | Cooper&Hunter | CH-ES18-230VO | CH-M18DTUI | | 12,600 | $630 |
| No | 210799585 | Cooper&Hunter | CH-ES18-230VO | CH-18MSPHCT-230VI | | 12,000 | $600 |
| No | 210799587 | Cooper&Hunter | CH-ES18-230VO | CH-18MSPHFC-230VI | | 12,800 | $640 |
| No | 210799672 | Cooper&Hunter | CH-ES18-230VO | CH-18MASTWM-230VI | | 14,900 | $745 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210799689 | Cooper&Hunter | CH-ES18-230VO | CH-B18MOLVWM-230VI | | 14,100 | $705 |
| No | 210799561 | Cooper&Hunter | CH-ES18-230VO | CH-18MOLVWM-230VI | | 14,100 | $705 |
| No | 210799574 | Cooper&Hunter | CH-NY18MIA-230VO | CH-NY18MIA-230VI | | 11,500 | $575 |
| No | 210799572 | Cooper&Hunter | CH-NY09MIA-230VO | CH-NY09MIA-230VI | | 6,900 | $345 |
| No | 210799570 | Cooper&Hunter | CH-NY09MIA-115VO | CH-NY09MIA-115VI | | 6,800 | $340 |
| No | 210799588 | Cooper&Hunter | CH-ES24-230VO | CH-N24MSPHCT-230VI | | 19,000 | $950 |
| No | 210799611 | Cooper&Hunter | CH-NHPR36LCU-230VO | CH-36LCDTU/I | | 34,000 | $1,700 |
| No | 210799606 | Cooper&Hunter | CH-N48LCU-230VO | CH-48LCDTU/I | | 34,000 | $1,700 |
| No | 210799605 | Cooper&Hunter | CH-N48LCU-230VO | CH-N48LCCT-230VI | | 30,000 | $1,500 |
| No | 210799607 | Cooper&Hunter | CH-N48LCU-230VO | CH-48LCFC/I | | 29,000 | $1,450 |
| No | 210799603 | Cooper&Hunter | CH-N36LCU-230VO | CH-36LCDTU/I | | 25,000 | $1,250 |
| No | 210799602 | Cooper&Hunter | CH-N36LCU-230VO | CH-N36LCCT-230VI | | 23,000 | $1,150 |
| No | 210799604 | Cooper&Hunter | CH-N36LCU-230VO | CH-36LCFC/I | | 23,000 | $1,150 |
| No | 210799687 | Cooper&Hunter | CH-ES09-230VO | CH-B09MOLVWM-230VI | | 8,100 | $405 |
| No | 210799559 | Cooper&Hunter | CH-ES09-230VO | CH-09MOLVWM-230VI | | 8,100 | $405 |
| No | 210799686 | Cooper&Hunter | CH-HPR06F9-230VO | CH-B06MOLVWM-230VI | | 7,500 | $375 |
| No | 210799565 | Cooper&Hunter | CH-HPR06F9-230VO | CH-06MOLVWM-230VI | | 7,500 | $375 |
| No | 210799547 | Cooper&Hunter | CH-HPR06F9-230VO | CH-06MASTWM-230VI | | 8,500 | $425 |
| No | 210799684 | Cooper&Hunter | CH-ES09-115VO | CH-B09OLVWM-115VI | | 5,900 | $295 |
| No | 210799640 | Cooper&Hunter | CH-ES09-115VO | CH-09OLVWM-115VI | | 5,900 | $295 |
| No | 210799577 | Cooper&Hunter | CH-EL36-230VO | CH-36ELSPHWM-230VI | | 24,000 | $1,200 |
| No | 210799671 | Cooper&Hunter | CH-ES24-230VO | CH-24MASTWM-230VI | | 16,200 | $810 |
| No | 210799673 | Cooper&Hunter | CH-ES12-230VO | CH-12MASTWM-230VI | | 9,000 | $450 |
| No | 210799670 | Cooper&Hunter | CH-ES09-230VO | CH-09MASTWM-230VI | | 8,500 | $425 |
| No | 210799558 | Cooper&Hunter | CH-NY24MIA-230VO | CH-24MOLV-230VI | | 16,500 | $825 |
| No | 210799557 | Cooper&Hunter | CH-NY18MIA-230VO | CH-18MOLV-230VI | | 11,400 | $570 |
| No | 210799556 | Cooper&Hunter | CH-NY12MIA-230VO | CH-12MOLV-230VI | | 7,000 | $350 |
| No | 210799579 | Cooper&Hunter | CH-NY09MIA-230VO | CH-09MOLV-230VI | | 6,000 | $300 |
| No | 210799555 | Cooper&Hunter | CH-NY12MIA-115VO | CH-12OLV-115VI | | 7,800 | $390 |
| No | 210799690 | Cooper&Hunter | CH-ES24-230VO | CH-B24MOLVWM-230VI | | 17,400 | $870 |
| No | 210799562 | Cooper&Hunter | CH-ES24-230VO | CH-24MOLVWM-230VI | | 17,400 | $870 |
| No | 210799560 | Cooper&Hunter | CH-ES12-230VO | CH-12MOLVWM-230VI | | 10,000 | $500 |
| No | 210799688 | Cooper&Hunter | CH-ES12-230VO | CH-B12MOLVWM-230VI | | 10,000 | $500 |
| No | 210799578 | Cooper&Hunter | CH-ES12-115VO | CH-12OLVWM-115VI | | 8,900 | $445 |
| No | 210799685 | Cooper&Hunter | CH-ES12-115VO | CH-B12OLVWM-115VI | | 8,900 | $445 |
| No | 210799568 | Cooper&Hunter | CH-HPR18-230VO | CH-18MOLVWM-230VI | | 11,100 | $555 |
| No | 210799693 | Cooper&Hunter | CH-HPR18-230VO | CH-B18MOLVWM-230VI | | 11,100 | $555 |
| No | 210799692 | Cooper&Hunter | CH-HPR12-230VO | CH-B12MOLVWM-230VI | | 10,300 | $515 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210799567 | Cooper&Hunter | CH-HPR12-230VO | CH-12MOLVWM-230VI | | 10,300 | $515 |
| No | 210799566 | Cooper&Hunter | CH-HPR09-230VO | CH-09MOLVWM-230VI | | 9,300 | $465 |
| No | 210799691 | Cooper&Hunter | CH-HPR09-230VO | CH-B09MOLVWM-230VI | | 9,300 | $465 |
| No | 210799589 | Cooper&Hunter | CH-ES24-230VO | CH-M24DTUI | | 20,000 | $1,000 |
| No | 210799596 | Cooper&Hunter | CH-HPR18-230VO | CH-18MSPHCT-230VI | | 15,600 | $780 |
| No | 210799598 | Cooper&Hunter | CH-HPR18-230VO | CH-18MSPHFC-230VI | | 12,000 | $600 |
| No | 210799595 | Cooper&Hunter | CH-HPR12-230VO | CH-12MSPHMC-230VI | | 9,600 | $480 |
| No | 210799594 | Cooper&Hunter | CH-HPR12-230VO | CH-M12DTUI | | 10,600 | $530 |
| No | 210799593 | Cooper&Hunter | CH-HPR12-230VO | CH-12MSPHCT-230VI | | 9,900 | $495 |
| No | 210799584 | Cooper&Hunter | CH-ES12-230VO | CH-12MSPHMC-230VI | | 9,000 | $450 |
| No | 210799583 | Cooper&Hunter | CH-ES12-230VO | CH-M12DTUI | | 9,300 | $465 |
| No | 210799592 | Cooper&Hunter | CH-HPR09-230VO | CH-M09DTUI | | 10,100 | $505 |
| No | 210799591 | Cooper&Hunter | CH-HPR09-230VO | CH-09MSPHCT-230VI | | 9,000 | $450 |
| No | 210799581 | Cooper&Hunter | CH-ES09-230VO | CH-M09DTUI | | 7,700 | $385 |
| No | 210799590 | Cooper&Hunter | CH-ES24-230VO | CH-24MSPHFC-230VI | | 16,000 | $800 |
| No | 210799582 | Cooper&Hunter | CH-ES12-230VO | CH-12MSPHCT-230VI | | 8,900 | $445 |
| No | 210799580 | Cooper&Hunter | CH-ES09-230VO | CH-09MSPHCT-230VI | | 7,500 | $375 |
| No | 210799549 | Cooper&Hunter | CH-HPR12-230VO | CH-12MASTWM-230VI | | 10,000 | $500 |
| No | 210799548 | Cooper&Hunter | CH-HPR09-230VO | CH-09MASTWM-230VI | | 9,500 | $475 |
| No | 210799554 | Cooper&Hunter | CH-NY09MIA-115VO | CH-09OLV-115VI | | 6,300 | $315 |
| No | 211290025 | CTMorley | MOU-A18H-2 | MIU-B16F-2 | | 14,700 | $735 |
| No | 211290024 | CTMorley | MOU-A12H-2 | MIU-B12F-2 | | 10,200 | $510 |
| No | 209847225 | CTMorley | MOU-A60V-4 | MIU-A60V-4 | | 37,000 | $1,850 |
| No | 209847224 | CTMorley | MOU-A48V-4 | MIU-A48V-4 | | 37,000 | $1,850 |
| No | 209847223 | CTMorley | MOU-A36V-4 | MIU-A36V-4 | | 20,400 | $1,020 |
| No | 209847221 | CTMorley | MOU-A24V-4 | MIU-A24V-4 | | 21,000 | $1,050 |
| No | 209847220 | CTMorley | MOU-A18V-4 | MIU-A18V-4 | | 12,000 | $600 |
| No | 209865027 | CTMorley | MOU-A36VH-4 | MIU-A36V-4 | | 30,400 | $1,520 |
| No | 209865026 | CTMorley | MOU-A30VH-4 | MIU-A30V-4 | | 21,000 | $1,050 |
| No | 209864936 | CTMORLEY | MOU-5A55G-2 | Heat pump without ducts | | 36,400 | $1,820 |
| No | 210288134 | CTMORLEY | MOU-4A36G-2 | Heat pump without ducts | | 26,400 | $1,320 |
| No | 210288137 | CTMORLEY | MOU-5A48G-2 | Heat pump without ducts | | 36,000 | $1,800 |
| No | 210288131 | CTMORLEY | MOU-3A27G-2 | Heat pump without ducts | | 20,000 | $1,000 |
| No | 210288132 | CTMORLEY | MOU-3A27G-2 | Heat pump with ducts | | 22,000 | $1,100 |
| No | 210288129 | CTMORLEY | MOU-2A18G-2 | Heat pump with ducts | | 14,800 | $740 |
| No | 210288128 | CTMORLEY | MOU-2A18G-2 | Heat pump without ducts | | 14,400 | $720 |
| No | 209864934 | CTMorley | MOU-A12H-2 | MIU-A12CO-2 | | 9,500 | $475 |
| No | 209864933 | CTMorley | MOU-A09H-2 | MIU-A09CO-2 | | 9,800 | $490 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 209843073 | CTMorley | MOU-A60L-2 | MIU-A60LD-2 | | 34,400 | $1,720 |
| No | 209843074 | CTMorley | MOU-A60L-2 | MIU-A60LF-2 | | 35,000 | $1,750 |
| No | 209843076 | CTMorley | MOU-A36LH-2 | MIU-A36LD-2 | | 34,000 | $1,700 |
| No | 209843071 | CTMorley | MOU-A48L-2 | MIU-A48LD-2 | | 34,000 | $1,700 |
| No | 209843070 | CTMorley | MOU-A48L-2 | MIU-A48LC-2 | | 30,000 | $1,500 |
| No | 209843072 | CTMorley | MOU-A48L-2 | MIU-A48LF-2 | | 29,000 | $1,450 |
| No | 209843068 | CTMorley | MOU-A36L-2 | MIU-A36LD-2 | | 25,000 | $1,250 |
| No | 209843067 | CTMorley | MOU-A36L-2 | MIU-A36LC-2 | | 23,000 | $1,150 |
| No | 209843069 | CTMorley | MOU-A36L-2 | MIU-A36LF-2 | | 23,000 | $1,150 |
| No | 209694744 | CTMorley | MOU-A36G-2 | MIU-A36W-2 | | 24,000 | $1,200 |
| No | 209864932 | CTMorley | MOU-A24G-2 | MIU-A24GW-2 | | 16,500 | $825 |
| No | 209864931 | CTMorley | MOU-A18G-2 | MIU-A18GW-2 | | 11,400 | $570 |
| No | 209864930 | CTMorley | MOU-A12G-2 | MIU-A12GW-2 | | 7,000 | $350 |
| No | 209864929 | CTMorley | MOU-A09G-2 | MIU-A09GW-2 | | 6,000 | $300 |
| No | 209694742 | CTMorley | MOU-A12G-1 | MIU-A12W-1 | | 7,800 | $390 |
| No | 209694741 | CTMorley | MOU-A09G-1 | MIU-A09W-1 | | 6,300 | $315 |
| No | 209694747 | CTMorley | MOU-A18H-2 | MIU-A18W-2 | | 11,100 | $555 |
| No | 209694746 | CTMorley | MOU-A12H-2 | MIU-A12W-2 | | 10,300 | $515 |
| No | 209694745 | CTMorley | MOU-A09H-2 | MIU-A09W-2 | | 9,300 | $465 |
| No | 209843061 | CTMorley | MOU-A18H-2 | MIU-A18C-2 | | 15,600 | $780 |
| No | 209843063 | CTMorley | MOU-A18H-2 | MIU-A18F-2 | | 12,000 | $600 |
| No | 209843060 | CTMorley | MOU-A12H-2 | MIU-A12F-2 | | 9,600 | $480 |
| No | 209843059 | CTMorley | MOU-A12H-2 | MIU-A12D-2 | | 10,600 | $530 |
| No | 209843058 | CTMorley | MOU-A12H-2 | MIU-A12C-2 | | 9,900 | $495 |
| No | 209843082 | CTMorley | MOU-A09H-2 | MIU-A09D-2 | | 10,100 | $505 |
| No | 209843081 | CTMorley | MOU-A09H-2 | MIU-A09C-2 | | 9,000 | $450 |
| No | 209864938 | CTMORLEY | MOU-5A55G-2 | Combination heat pumps with or without ducts | | 35,600 | $1,780 |
| No | 209864937 | CTMORLEY | MOU-5A55G-2 | Heat pump with ducts | | 35,000 | $1,750 |
| No | 209847222 | CTMORLEY | MOU-A30V-4 | MIU-A30V-4 | | 20,000 | $1,000 |
| No | 211635179 | DAIKIN | RZQ48TBVJU* | FTQ48TAVJU*A* | | 36,800 | $1,840 |
| No | 211635178 | DAIKIN | RZQ42TBVJU* | FTQ42TAVJU*A* | | 33,000 | $1,650 |
| No | 211635177 | DAIKIN | RZQ24TBVJU* | FTQ24TAVJU*A* | | 19,400 | $970 |
| No | 211635167 | DAIKIN | RZQ48TBVJU* | FCQ48AAVJU | | 34,800 | $1,740 |
| No | 211635166 | DAIKIN | RZQ42TBVJU* | FCQ42AAVJU | | 31,200 | $1,560 |
| No | 211635165 | DAIKIN | RZQ36TBVJU* | FCQ36AAVJU | | 26,200 | $1,310 |
| No | 211635164 | DAIKIN | RZQ30TBVJU* | FCQ30AAVJU | | 22,800 | $1,140 |
| No | 211635163 | DAIKIN | RZQ24TBVJU* | FCQ24AAVJU | | 18,000 | $900 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211635162 | DAIKIN | RZQ18TBVJU* | FCQ18AAVJU | | 12,300 | $615 |
| No | 211635171 | DAIKIN | RZQ24TBVJU* | FBQ24TBVJU | | 19,000 | $950 |
| No | 207158010 | DAIKIN | RXM12VVJU | FTXM12VVJU | | 8,600 | $430 |
| No | 207158009 | DAIKIN | RXM09VVJU | FTXM09VVJU | | 6,600 | $330 |
| No | 210725100 | DAIKIN | 2MXL18WMVJU* | Heat pump with ducts | | 11,600 | $580 |
| No | 210722664 | DAIKIN | 2MXL18WMVJU* | Heat pump without ducts | | 12,000 | $600 |
| No | 210800987 | DAIKIN | 5MXS48WVJU* | Combination heat pumps with or without ducts | | 30,600 | $1,530 |
| No | 210800986 | DAIKIN | 4MXS36WMVJU* | Combination heat pumps with or without ducts | | 20,600 | $1,030 |
| No | 210800985 | DAIKIN | 3MXS24WMVJU* | Combination heat pumps with or without ducts | | 15,200 | $760 |
| No | 210800984 | DAIKIN | 2MXS18WMVJU* | Combination heat pumps with or without ducts | | 12,000 | $600 |
| No | 210800990 | DAIKIN | 4MXL36WMVJU* | Combination heat pumps with or without ducts | | 22,200 | $1,110 |
| No | 210800989 | DAIKIN | 3MXL24WMVJU* | Combination heat pumps with or without ducts | | 15,200 | $760 |
| No | 210800988 | DAIKIN | 2MXL18WMVJU* | Combination heat pumps with or without ducts | | 11,800 | $590 |
| No | 210725099 | DAIKIN | 5MXS48WVJU* | Heat pump with ducts | | 30,200 | $1,510 |
| No | 210722663 | DAIKIN | 5MXS48WVJU* | Heat pump without ducts | | 31,000 | $1,550 |
| No | 210725098 | DAIKIN | 4MXS36WMVJU* | Heat pump with ducts | | 20,200 | $1,010 |
| No | 210722662 | DAIKIN | 4MXS36WMVJU* | Heat pump without ducts | | 22,000 | $1,100 |
| No | 210722661 | DAIKIN | 3MXS24WMVJU* | Heat pump without ducts | | 15,500 | $775 |
| No | 210722659 | DAIKIN | 2MXS18WMVJU* | Heat pump without ducts | | 12,000 | $600 |
| No | 210725102 | DAIKIN | 4MXL36WVJU* | Heat pump with ducts | | 22,000 | $1,100 |
| No | 210722666 | DAIKIN | 4MXL36WVJU* | Heat pump without ducts | | 22,400 | $1,120 |
| No | 210722665 | DAIKIN | 3MXL24WMVJU* | Heat pump without ducts | | 15,500 | $775 |
| No | 207216088 | DAIKIN | 2MX18AXVJU | Heat pump without ducts | | 10,700 | $535 |
| No | 211697901 | DAIKIN | RX24BXVJU | FTX24BXVJU | | 14,400 | $720 |
| No | 211697900 | DAIKIN | RX18BXVJU | FTX18BXVJU | | 14,400 | $720 |
| No | 211291634 | DAIKIN | RX12BXVJU | FTX12BXVJU | | 8,600 | $430 |
| No | 211291633 | DAIKIN | RX09BXVJU | FTX09BXVJU | | 5,800 | $290 |
| No | 210435242 | DAIKIN | DZ6VSA6010A* | DV60FECD14A* | | 34,800 | $1,740 |
| No | 210435087 | DAIKIN | DZ6VSA6010A* | DFVE60DP1400A* | | 34,800 | $1,740 |
| No | 210435101 | DAIKIN | DZ6VSA4810A* | DV60FECD14A* | | 29,800 | $1,490 |
| No | 210435100 | DAIKIN | DZ6VSA4810A* | DV48FECD14A* | | 29,800 | $1,490 |
| No | 210435099 | DAIKIN | DZ6VSA4810A* | DFVE60DP1400A* | | 29,800 | $1,490 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210435086 | DAIKIN | DZ6VSA4810A* | DFVE48DP1400A* | | 29,800 | $1,490 |
| No | 210435093 | DAIKIN | DZ6VSA3610A* | DFVE42CP1400A* | | 22,400 | $1,120 |
| No | 210435092 | DAIKIN | DZ6VSA3610A* | DV36FECC14A* | | 22,400 | $1,120 |
| No | 210435091 | DAIKIN | DZ6VSA3610A* | DV42FECC14A* | | 22,400 | $1,120 |
| No | 210435241 | DAIKIN | DZ6VSA3610A* | CA*EA3026*4A*+MBVC2000**-1A* | | 22,400 | $1,120 |
| No | 210435240 | DAIKIN | DZ6VSA3610A* | CA*EA3026*4A* | D*97MC1205DNA* | 22,400 | $1,120 |
| No | 210435239 | DAIKIN | DZ6VSA3610A* | CA*EA3026*4A* | D*96VC1205DNA* | 22,400 | $1,120 |
| No | 210435238 | DAIKIN | DZ6VSA3610A* | CA*EA3026*4A* | D*96VC1005DNA* | 22,400 | $1,120 |
| No | 210435236 | DAIKIN | DZ6VSA3610A* | CA*EA3026*4A*+MBVC1600**-1A* | | 22,400 | $1,120 |
| No | 210435235 | DAIKIN | DZ6VSA3610A* | CA*EA3026*4A* | D*97MC1005CNA* | 22,400 | $1,120 |
| No | 210435234 | DAIKIN | DZ6VSA3610A* | CA*EA3026*4A* | D*97MC0804CNA* | 22,400 | $1,120 |
| No | 210435233 | DAIKIN | DZ6VSA3610A* | CA*EA3026*4A* | D*96VC1005CNA* | 22,400 | $1,120 |
| No | 210435232 | DAIKIN | DZ6VSA3610A* | CA*EA3026*4A* | D*96VC0804CNA* | 22,400 | $1,120 |
| No | 210435231 | DAIKIN | DZ6VSA3610A* | CA*EA3026*4A* | D*96SC0805CUA* | 22,400 | $1,120 |
| No | 210435226 | DAIKIN | DZ6VSA3610A* | CA*EA3026*4A*+MBVC1200**-1A* | | 22,400 | $1,120 |
| No | 210435225 | DAIKIN | DZ6VSA3610A* | CA*EA3026*4A* | D*97MC0803BNA* | 22,400 | $1,120 |
| No | 210435224 | DAIKIN | DZ6VSA3610A* | CA*EA3026*4A* | D*97MC0603BNA* | 22,400 | $1,120 |
| No | 210435223 | DAIKIN | DZ6VSA3610A* | CA*EA3026*4A* | D*96VC0803BNA* | 22,400 | $1,120 |
| No | 210435222 | DAIKIN | DZ6VSA3610A* | CA*EA3026*4A* | D*96VC0603BNA* | 22,400 | $1,120 |
| No | 210435221 | DAIKIN | DZ6VSA3610A* | CA*EA3026*4A* | D*96VC0403BNA* | 22,400 | $1,120 |
| No | 210435220 | DAIKIN | DZ6VSA3610A* | CA*EA3026*4A* | D*96SC0603BUA* | 22,400 | $1,120 |
| No | 210435084 | DAIKIN | DZ6VSA3610A* | DFVE36CP1400A* | | 22,400 | $1,120 |
| No | 210435083 | DAIKIN | DZ6VSA3010A* | DFVE36CP1400A* | | 18,000 | $900 |
| No | 210435215 | DAIKIN | DZ6VSA3010A* | CA*EA3026*4A*+MBVC1600**-1A* | | 18,000 | $900 |
| No | 210435214 | DAIKIN | DZ6VSA3010A* | CA*EA3026*4A* | D*97MC1005CNA* | 18,000 | $900 |
| No | 210435213 | DAIKIN | DZ6VSA3010A* | CA*EA3026*4A* | D*97MC0804CNA* | 18,000 | $900 |
| No | 210435212 | DAIKIN | DZ6VSA3010A* | CA*EA3026*4A* | D*96VC1005CNA* | 18,000 | $900 |
| No | 210435211 | DAIKIN | DZ6VSA3010A* | CA*EA3026*4A* | D*96VC0804CNA* | 18,000 | $900 |
| No | 210435210 | DAIKIN | DZ6VSA3010A* | CA*EA3026*4A* | D*96SC0805CUA* | 18,000 | $900 |
| No | 210435205 | DAIKIN | DZ6VSA3010A* | CA*EA3026*4A*+MBVC1200**-1A* | | 18,000 | $900 |
| No | 210435204 | DAIKIN | DZ6VSA3010A* | CA*EA3026*4A* | D*97MC0803BNA* | 18,000 | $900 |
| No | 210435203 | DAIKIN | DZ6VSA3010A* | CA*EA3026*4A* | D*97MC0603BNA* | 18,000 | $900 |
| No | 210435202 | DAIKIN | DZ6VSA3010A* | CA*EA3026*4A* | D*96VC0803BNA* | 18,000 | $900 |
| No | 210435201 | DAIKIN | DZ6VSA3010A* | CA*EA3026*4A* | D*96VC0603BNA* | 18,000 | $900 |
| No | 210435200 | DAIKIN | DZ6VSA3010A* | CA*EA3026*4A* | D*96VC0403BNA* | 18,000 | $900 |
| No | 210435199 | DAIKIN | DZ6VSA3010A* | CA*EA3026*4A* | D*96SC0603BUA* | 18,000 | $900 |
| No | 210435194 | DAIKIN | DZ6VSA3010A* | CA*EA2422*4A*+MBVC1600**-1A* | | 18,000 | $900 |
| No | 210435193 | DAIKIN | DZ6VSA3010A* | CA*EA2422*4A* | D*97MC1005CNA* | 18,000 | $900 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210435192 | DAIKIN | DZ6VSA3010A* | CA*EA2422*4A* | D*97MC0804CNA* | 18,000 | $900 |
| No | 210435191 | DAIKIN | DZ6VSA3010A* | CA*EA2422*4A* | D*96VC1005CNA* | 18,000 | $900 |
| No | 210435190 | DAIKIN | DZ6VSA3010A* | CA*EA2422*4A* | D*96VC0804CNA* | 18,000 | $900 |
| No | 210435189 | DAIKIN | DZ6VSA3010A* | CA*EA2422*4A* | D*96SC0805CUA* | 18,000 | $900 |
| No | 210435184 | DAIKIN | DZ6VSA3010A* | CA*EA2422*4A*+MBVC1200**-1A* | | 18,000 | $900 |
| No | 210435183 | DAIKIN | DZ6VSA3010A* | CA*EA2422*4A* | D*97MC0803BNA* | 18,000 | $900 |
| No | 210435182 | DAIKIN | DZ6VSA3010A* | CA*EA2422*4A* | D*97MC0603BNA* | 18,000 | $900 |
| No | 210435181 | DAIKIN | DZ6VSA3010A* | CA*EA2422*4A* | D*96VC0803BNA* | 18,000 | $900 |
| No | 210435180 | DAIKIN | DZ6VSA3010A* | CA*EA2422*4A* | D*96VC0603BNA* | 18,000 | $900 |
| No | 210435179 | DAIKIN | DZ6VSA3010A* | CA*EA2422*4A* | D*96VC0403BNA* | 18,000 | $900 |
| No | 210435178 | DAIKIN | DZ6VSA3010A* | CA*EA2422*4A* | D*96SC0603BUA* | 18,000 | $900 |
| No | 210435090 | DAIKIN | DZ6VSA3010A* | DV36FECC14A* | | 18,000 | $900 |
| No | 210435082 | DAIKIN | DZ6VSA2410A* | DFVE24BP1400A* | | 14,600 | $730 |
| No | 210435173 | DAIKIN | DZ6VSA2410A* | CA*EA2422*4A*+MBVC1600**-1A* | | 14,600 | $730 |
| No | 210435172 | DAIKIN | DZ6VSA2410A* | CA*EA2422*4A* | D*97MC0804CNA* | 14,600 | $730 |
| No | 210435171 | DAIKIN | DZ6VSA2410A* | CA*EA2422*4A* | D*96VC0804CNA* | 14,600 | $730 |
| No | 210435170 | DAIKIN | DZ6VSA2410A* | CA*EA2422*4A* | D*96SC0805CUA* | 14,600 | $730 |
| No | 210435166 | DAIKIN | DZ6VSA2410A* | CA*EA2422*4A*+MBVC1200**-1A* | | 14,600 | $730 |
| No | 210435165 | DAIKIN | DZ6VSA2410A* | CA*EA2422*4A* | D*97MC0803BNA* | 14,600 | $730 |
| No | 210435164 | DAIKIN | DZ6VSA2410A* | CA*EA2422*4A* | D*97MC0603BNA* | 14,600 | $730 |
| No | 210435163 | DAIKIN | DZ6VSA2410A* | CA*EA2422*4A* | D*96VC0803BNA* | 14,600 | $730 |
| No | 210435162 | DAIKIN | DZ6VSA2410A* | CA*EA2422*4A* | D*96VC0603BNA* | 14,600 | $730 |
| No | 210435160 | DAIKIN | DZ6VSA2410A* | CA*EA2422*4A* | D*96SC0603BUA* | 14,600 | $730 |
| No | 210435155 | DAIKIN | DZ6VSA2410A* | CA*EA1818*4A*+MBVC1600**-1A* | | 14,600 | $730 |
| No | 210435154 | DAIKIN | DZ6VSA2410A* | CA*EA1818*4A* | D*97MC0804CNA* | 14,600 | $730 |
| No | 210435153 | DAIKIN | DZ6VSA2410A* | CA*EA1818*4A* | D*96VC0804CNA* | 14,600 | $730 |
| No | 210435152 | DAIKIN | DZ6VSA2410A* | CA*EA1818*4A* | D*96SC0805CUA* | 14,600 | $730 |
| No | 210435148 | DAIKIN | DZ6VSA2410A* | CA*EA1818*4A*+MBVC1200**-1A* | | 14,600 | $730 |
| No | 210435147 | DAIKIN | DZ6VSA2410A* | CA*EA1818*4A* | D*97MC0803BNA* | 14,600 | $730 |
| No | 210435146 | DAIKIN | DZ6VSA2410A* | CA*EA1818*4A* | D*97MC0603BNA* | 14,600 | $730 |
| No | 210435145 | DAIKIN | DZ6VSA2410A* | CA*EA1818*4A* | D*96VC0803BNA* | 14,600 | $730 |
| No | 210435144 | DAIKIN | DZ6VSA2410A* | CA*EA1818*4A* | D*96VC0603BNA* | 14,600 | $730 |
| No | 210435143 | DAIKIN | DZ6VSA2410A* | CA*EA1818*4A* | D*96VC0403BNA* | 14,600 | $730 |
| No | 210435142 | DAIKIN | DZ6VSA2410A* | CA*EA1818*4A* | D*96SC0603BUA* | 14,600 | $730 |
| No | 210435161 | DAIKIN | DZ6VSA2410A* | CA*EA2422*4A* | D*96VC0403BNA* | 14,600 | $730 |
| No | 210435089 | DAIKIN | DZ6VSA2410A* | DV24FECB14A* | | 14,600 | $730 |
| No | 210435081 | DAIKIN | DZ6VSA1810A* | DFVE24BP1400A* | | 10,800 | $540 |
| No | 210435137 | DAIKIN | DZ6VSA1810A* | CA*EA2422*4A*+MBVC1600**-1A* | | 10,800 | $540 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210435136 | DAIKIN | DZ6VSA1810A* | CA*EA2422*4A* | D*97MC0804CNA* | 10,800 | $540 |
| No | 210435135 | DAIKIN | DZ6VSA1810A* | CA*EA2422*4A* | D*96VC0804CNA* | 10,800 | $540 |
| No | 210435134 | DAIKIN | DZ6VSA1810A* | CA*EA2422*4A* | D*96SC0805CUA* | 10,800 | $540 |
| No | 210435130 | DAIKIN | DZ6VSA1810A* | CA*EA2422*4A*+MBVC1200**-1A* | | 10,800 | $540 |
| No | 210435129 | DAIKIN | DZ6VSA1810A* | CA*EA2422*4A* | D*97MC0803BNA* | 10,800 | $540 |
| No | 210435128 | DAIKIN | DZ6VSA1810A* | CA*EA2422*4A* | D*97MC0603BNA* | 10,800 | $540 |
| No | 210435127 | DAIKIN | DZ6VSA1810A* | CA*EA2422*4A* | D*96VC0803BNA* | 10,800 | $540 |
| No | 210435126 | DAIKIN | DZ6VSA1810A* | CA*EA2422*4A* | D*96VC0603BNA* | 10,800 | $540 |
| No | 210435125 | DAIKIN | DZ6VSA1810A* | CA*EA2422*4A* | D*96VC0403BNA* | 10,800 | $540 |
| No | 210435124 | DAIKIN | DZ6VSA1810A* | CA*EA2422*4A* | D*96SC0603BUA* | 10,800 | $540 |
| No | 210435119 | DAIKIN | DZ6VSA1810A* | CA*EA1818*4A*+MBVC1600**-1A* | | 10,800 | $540 |
| No | 210435118 | DAIKIN | DZ6VSA1810A* | CA*EA1818*4A* | D*97MC0804CNA* | 10,800 | $540 |
| No | 210435117 | DAIKIN | DZ6VSA1810A* | CA*EA1818*4A* | D*96VC0804CNA* | 10,800 | $540 |
| No | 210435116 | DAIKIN | DZ6VSA1810A* | CA*EA1818*4A* | D*96SC0805CUA* | 10,800 | $540 |
| No | 210435112 | DAIKIN | DZ6VSA1810A* | CA*EA1818*4A*+MBVC1200**-1A* | | 10,800 | $540 |
| No | 210435111 | DAIKIN | DZ6VSA1810A* | CA*EA1818*4A* | D*97MC0803BNA* | 10,800 | $540 |
| No | 210435110 | DAIKIN | DZ6VSA1810A* | CA*EA1818*4A* | D*97MC0603BNA* | 10,800 | $540 |
| No | 210435109 | DAIKIN | DZ6VSA1810A* | CA*EA1818*4A* | D*96VC0803BNA* | 10,800 | $540 |
| No | 210435108 | DAIKIN | DZ6VSA1810A* | CA*EA1818*4A* | D*96VC0603BNA* | 10,800 | $540 |
| No | 210435107 | DAIKIN | DZ6VSA1810A* | CA*EA1818*4A* | D*96VC0403BNA* | 10,800 | $540 |
| No | 210435106 | DAIKIN | DZ6VSA1810A* | CA*EA1818*4A* | D*96SC0603BUA* | 10,800 | $540 |
| No | 210435088 | DAIKIN | DZ6VSA1810A* | DV24FECB14A* | | 10,800 | $540 |
| No | 207168342 | DAIKIN | DZ17VSA601B* | DV60FECD14A* | | 34,800 | $1,740 |
| No | 207173041 | DAIKIN | DZ17VSA481B* | DV60FECD14A* | | 29,800 | $1,490 |
| No | 207168341 | DAIKIN | DZ17VSA481B* | DV48FECD14A* | | 29,800 | $1,490 |
| No | 207173039 | DAIKIN | DZ17VSA421B* | DV42FECC14A* | | 25,600 | $1,280 |
| No | 207173040 | DAIKIN | DZ17VSA421B* | DV60FECD14A* | | 25,600 | $1,280 |
| No | 207168340 | DAIKIN | DZ17VSA421B* | DV48FECD14A* | | 25,600 | $1,280 |
| No | 207173019 | DAIKIN | DZ17VSA361B* | CA*EA3026*4A* | D*97MC0603BNA* | 22,400 | $1,120 |
| No | 207173021 | DAIKIN | DZ17VSA361B* | CA*EA3026*4A* | D*97MC0804CNA* | 22,400 | $1,120 |
| No | 207173012 | DAIKIN | DZ17VSA361B* | CA*EA3026*4A* | D*96VC0403BNA* | 22,400 | $1,120 |
| No | 207173013 | DAIKIN | DZ17VSA361B* | CA*EA3026*4A* | D*96VC0603BNA* | 22,400 | $1,120 |
| No | 207173014 | DAIKIN | DZ17VSA361B* | CA*EA3026*4A* | DM96VC0803BNA* | 22,400 | $1,120 |
| No | 207173015 | DAIKIN | DZ17VSA361B* | CA*EA3026*4A* | D*96VC0804CNA* | 22,400 | $1,120 |
| No | 207173016 | DAIKIN | DZ17VSA361B* | CA*EA3026*4A* | D*96VC1005CNA* | 22,400 | $1,120 |
| No | 207173017 | DAIKIN | DZ17VSA361B* | CA*EA3026*4A* | DM96VC1005DNA* | 22,400 | $1,120 |
| No | 207173018 | DAIKIN | DZ17VSA361B* | CA*EA3026*4A* | D*96VC1205DNA* | 22,400 | $1,120 |
| No | 207173020 | DAIKIN | DZ17VSA361B* | CA*EA3026*4A* | D*97MC0803BNA* | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207173022 | DAIKIN | DZ17VSA361B* | CA*EA3026*4A* | D*97MC1005CNA* | 22,400 | $1,120 |
| No | 207173023 | DAIKIN | DZ17VSA361B* | CA*EA3026*4A* | DM97MC1205DNA* | 22,400 | $1,120 |
| No | 207173037 | DAIKIN | DZ17VSA361B* | CA*EA3026*4A* | D*96SC0603BUA* | 22,400 | $1,120 |
| No | 207173038 | DAIKIN | DZ17VSA361B* | CA*EA3026*4A* | D*96SC0805CUA* | 22,400 | $1,120 |
| No | 207173031 | DAIKIN | DZ17VSA361B* | CA*EA3026*4A*+MBVC1200**-1A* | | 22,400 | $1,120 |
| No | 207173032 | DAIKIN | DZ17VSA361B* | CA*EA3026*4A*+MBVC1600**-1A* | | 22,400 | $1,120 |
| No | 207173033 | DAIKIN | DZ17VSA361B* | CA*EA3026*4A*+MBVC2000**-1A* | | 22,400 | $1,120 |
| No | 207173034 | DAIKIN | DZ17VSA361B* | DV42FECC14A* | | 22,400 | $1,120 |
| No | 207168339 | DAIKIN | DZ17VSA361B* | DV36FECC14A* | | 22,400 | $1,120 |
| No | 207172996 | DAIKIN | DZ17VSA301B* | CA*EA2422*4A* | D*97MC0603BNA* | 18,000 | $900 |
| No | 207172997 | DAIKIN | DZ17VSA301B* | CA*EA2422*4A* | D*97MC0803BNA* | 18,000 | $900 |
| No | 207172998 | DAIKIN | DZ17VSA301B* | CA*EA2422*4A* | D*97MC0804CNA* | 18,000 | $900 |
| No | 207172991 | DAIKIN | DZ17VSA301B* | CA*EA2422*4A* | D*96VC0403BNA* | 18,000 | $900 |
| No | 207172992 | DAIKIN | DZ17VSA301B* | CA*EA2422*4A* | D*96VC0603BNA* | 18,000 | $900 |
| No | 207172993 | DAIKIN | DZ17VSA301B* | CA*EA2422*4A* | DM96VC0803BNA* | 18,000 | $900 |
| No | 207172994 | DAIKIN | DZ17VSA301B* | CA*EA2422*4A* | D*96VC0804CNA* | 18,000 | $900 |
| No | 207172995 | DAIKIN | DZ17VSA301B* | CA*EA2422*4A* | D*96VC1005CNA* | 18,000 | $900 |
| No | 207172999 | DAIKIN | DZ17VSA301B* | CA*EA2422*4A* | D*97MC1005CNA* | 18,000 | $900 |
| No | 207173010 | DAIKIN | DZ17VSA301B* | CA*EA2422*4A* | D*96SC0603BUA* | 18,000 | $900 |
| No | 207173011 | DAIKIN | DZ17VSA301B* | CA*EA2422*4A* | D*96SC0805CUA* | 18,000 | $900 |
| No | 207173006 | DAIKIN | DZ17VSA301B* | CA*EA2422*4A*+MBVC1200**-1A* | | 18,000 | $900 |
| No | 207173007 | DAIKIN | DZ17VSA301B* | CA*EA2422*4A*+MBVC1600**-1A* | | 18,000 | $900 |
| No | 207168338 | DAIKIN | DZ17VSA301B* | DV36FECC14A* | | 18,000 | $900 |
| No | 207172962 | DAIKIN | DZ17VSA241B* | CA*EA1818*4A* | D*97MC0603BNA* | 14,600 | $730 |
| No | 207172961 | DAIKIN | DZ17VSA241B* | CA*EA2422*4A* | D*97MC0603BNA* | 14,600 | $730 |
| No | 207172964 | DAIKIN | DZ17VSA241B* | CA*EA1818*4A* | D*97MC0803BNA* | 14,600 | $730 |
| No | 207172963 | DAIKIN | DZ17VSA241B* | CA*EA2422*4A* | D*97MC0803BNA* | 14,600 | $730 |
| No | 207172966 | DAIKIN | DZ17VSA241B* | CA*EA1818*4A* | D*97MC0804CNA* | 14,600 | $730 |
| No | 207172965 | DAIKIN | DZ17VSA241B* | CA*EA2422*4A* | D*97MC0804CNA* | 14,600 | $730 |
| No | 207172953 | DAIKIN | DZ17VSA241B* | CA*EA1818*4A* | D*96VC0403BNA* | 14,600 | $730 |
| No | 207172952 | DAIKIN | DZ17VSA241B* | CA*EA2422*4A* | D*96VC0403BNA* | 14,600 | $730 |
| No | 207172955 | DAIKIN | DZ17VSA241B* | CA*EA1818*4A* | D*96VC0603BNA* | 14,600 | $730 |
| No | 207172954 | DAIKIN | DZ17VSA241B* | CA*EA2422*4A* | D*96VC0603BNA* | 14,600 | $730 |
| No | 207172957 | DAIKIN | DZ17VSA241B* | CA*EA1818*4A* | DM96VC0803BNA* | 14,600 | $730 |
| No | 207172956 | DAIKIN | DZ17VSA241B* | CA*EA2422*4A* | DM96VC0803BNA* | 14,600 | $730 |
| No | 207172959 | DAIKIN | DZ17VSA241B* | CA*EA1818*4A* | D*96VC0804CNA* | 14,600 | $730 |
| No | 207172958 | DAIKIN | DZ17VSA241B* | CA*EA2422*4A* | D*96VC0804CNA* | 14,600 | $730 |
| No | 207172960 | DAIKIN | DZ17VSA241B* | CA*EA2422*4A* | D*96VC1005CNA* | 14,600 | $730 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207172967 | DAIKIN | DZ17VSA241B* | CA*EA2422*4A* | D*97MC1005CNA* | 14,600 | $730 |
| No | 207172989 | DAIKIN | DZ17VSA241B* | CA*EA1818*4A* | D*96SC0603BUA* | 14,600 | $730 |
| No | 207172988 | DAIKIN | DZ17VSA241B* | CA*EA2422*4A* | D*96SC0603BUA* | 14,600 | $730 |
| No | 207172990 | DAIKIN | DZ17VSA241B* | CA*EA2422*4A* | D*96SC0805CUA* | 14,600 | $730 |
| No | 207172981 | DAIKIN | DZ17VSA241B* | CA*EA1818*4A*+MBVC1200**-1A* | | 14,600 | $730 |
| No | 207172980 | DAIKIN | DZ17VSA241B* | CA*EA2422*4A*+MBVC1200**-1A* | | 14,600 | $730 |
| No | 207172983 | DAIKIN | DZ17VSA241B* | CA*EA1818*4A*+MBVC1600**-1A* | | 14,600 | $730 |
| No | 207172982 | DAIKIN | DZ17VSA241B* | CA*EA2422*4A*+MBVC1600**-1A* | | 14,600 | $730 |
| No | 207168337 | DAIKIN | DZ17VSA241B* | DV24FECB14A* | | 14,600 | $730 |
| No | 207172941 | DAIKIN | DZ17VSA181B* | CA*EA1818*4A* | D*97MC0603BNA* | 10,800 | $540 |
| No | 207172942 | DAIKIN | DZ17VSA181B* | CA*EA1818*4A* | D*97MC0803BNA* | 10,800 | $540 |
| No | 207172943 | DAIKIN | DZ17VSA181B* | CA*EA1818*4A* | D*97MC0804CNA* | 10,800 | $540 |
| No | 207172937 | DAIKIN | DZ17VSA181B* | CA*EA1818*4A* | D*96VC0403BNA* | 10,800 | $540 |
| No | 207172938 | DAIKIN | DZ17VSA181B* | CA*EA1818*4A* | D*96VC0603BNA* | 10,800 | $540 |
| No | 207172939 | DAIKIN | DZ17VSA181B* | CA*EA1818*4A* | DM96VC0803BNA* | 10,800 | $540 |
| No | 207172940 | DAIKIN | DZ17VSA181B* | CA*EA1818*4A* | D*96VC0804CNA* | 10,800 | $540 |
| No | 207172951 | DAIKIN | DZ17VSA181B* | CA*EA1818*4A* | D*96SC0603BUA* | 10,800 | $540 |
| No | 207172948 | DAIKIN | DZ17VSA181B* | CA*EA1818*4A*+MBVC1200**-1A* | | 10,800 | $540 |
| No | 207172949 | DAIKIN | DZ17VSA181B* | CA*EA1818*4A*+MBVC1600**-1A* | | 10,800 | $540 |
| No | 207168336 | DAIKIN | DZ17VSA181B* | DV24FECB14A* | | 10,800 | $540 |
| No | 210692455 | DAIKIN | DZ9VCA6010A* | CSCF4860N6D*+TXV | D*97MC1205DNA* | 32,400 | $1,620 |
| No | 210692454 | DAIKIN | DZ9VCA6010A* | CSCF4860N6D*+TXV | D*97MC1005CNA* | 32,400 | $1,620 |
| No | 210692453 | DAIKIN | DZ9VCA6010A* | CSCF4860N6D*+TXV | D*96VC1205DNA* | 32,400 | $1,620 |
| No | 210692452 | DAIKIN | DZ9VCA6010A* | CSCF4860N6D*+TXV | D*96VC1005CNA* | 32,400 | $1,620 |
| No | 210692451 | DAIKIN | DZ9VCA6010A* | CSCF4860N6D*+TXV | D*96SC0805CUA* | 32,400 | $1,620 |
| No | 210692447 | DAIKIN | DZ9VCA6010A* | CHPF4860D6D*+TXV | D*97MC1205DNA* | 32,400 | $1,620 |
| No | 210692446 | DAIKIN | DZ9VCA6010A* | CHPF4860D6D*+TXV | D*97MC1005CNA* | 32,400 | $1,620 |
| No | 210692445 | DAIKIN | DZ9VCA6010A* | CHPF4860D6D*+TXV | D*96VC1205DNA* | 32,400 | $1,620 |
| No | 210692444 | DAIKIN | DZ9VCA6010A* | CHPF4860D6D*+TXV | D*96VC1005CNA* | 32,400 | $1,620 |
| No | 210692443 | DAIKIN | DZ9VCA6010A* | CHPF4860D6D*+TXV | D*96SC0805CUA* | 32,400 | $1,620 |
| No | 210692439 | DAIKIN | DZ9VCA6010A* | CHPF4860D6D*+MBVC2000**-1A*+TXV | | 32,400 | $1,620 |
| No | 210692438 | DAIKIN | DZ9VCA6010A* | CA*F4961*6D*+TXV | D*97MC1205DNA* | 33,400 | $1,670 |
| No | 210692437 | DAIKIN | DZ9VCA6010A* | CA*F4961*6D*+TXV | D*97MC1005CNA* | 33,400 | $1,670 |
| No | 210692436 | DAIKIN | DZ9VCA6010A* | CA*F4961*6D*+TXV | D*96VC1205DNA* | 33,400 | $1,670 |
| No | 210692435 | DAIKIN | DZ9VCA6010A* | CA*F4961*6D*+TXV | D*96VC1005CNA* | 33,400 | $1,670 |
| No | 210692434 | DAIKIN | DZ9VCA6010A* | CA*F4961*6D*+TXV | D*96SC0805CUA* | 33,400 | $1,670 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210607421 | DAIKIN | DZ9VCA6010A* | CA*F4961*6D*+MBVC2000**-1A*+TX | | 34,000 | $1,700 |
| No | 210609988 | DAIKIN | DZ9VCA6010A* | DMVE60DP1400A* | | 33,400 | $1,670 |
| No | 210692430 | DAIKIN | DZ9VCA4810A* | CSCF4860N6D*+TXV | D*97MC1205DNA* | 27,000 | $1,350 |
| No | 210692429 | DAIKIN | DZ9VCA4810A* | CSCF4860N6D*+TXV | D*97MC1005CNA* | 27,000 | $1,350 |
| No | 210692428 | DAIKIN | DZ9VCA4810A* | CSCF4860N6D*+TXV | D*97MC0804CNA* | 27,000 | $1,350 |
| No | 210692427 | DAIKIN | DZ9VCA4810A* | CSCF4860N6D*+TXV | D*96VC1205DNA* | 27,000 | $1,350 |
| No | 210692426 | DAIKIN | DZ9VCA4810A* | CSCF4860N6D*+TXV | D*96VC1005CNA* | 27,000 | $1,350 |
| No | 210692425 | DAIKIN | DZ9VCA4810A* | CSCF4860N6D*+TXV | D*96SC0805CUA* | 27,000 | $1,350 |
| No | 210692424 | DAIKIN | DZ9VCA4810A* | CSCF4860N6D*+TXV | D*96VC0804CNA* | 27,000 | $1,350 |
| No | 210692418 | DAIKIN | DZ9VCA4810A* | CSCF4860N6D*+MBVC2000**-1A*+TXV | | 27,000 | $1,350 |
| No | 210692417 | DAIKIN | DZ9VCA4810A* | CSCF4860N6D*+MBVC1600**-1A*+TXV | | 27,000 | $1,350 |
| No | 210692416 | DAIKIN | DZ9VCA4810A* | CHPF4860D6D*+TXV | D*97MC1205DNA* | 27,000 | $1,350 |
| No | 210692415 | DAIKIN | DZ9VCA4810A* | CHPF4860D6D*+TXV | D*97MC1005CNA* | 27,000 | $1,350 |
| No | 210692414 | DAIKIN | DZ9VCA4810A* | CHPF4860D6D*+TXV | D*97MC0804CNA* | 27,000 | $1,350 |
| No | 210692413 | DAIKIN | DZ9VCA4810A* | CHPF4860D6D*+TXV | D*96VC1205DNA* | 27,000 | $1,350 |
| No | 210692412 | DAIKIN | DZ9VCA4810A* | CHPF4860D6D*+TXV | D*96VC1005CNA* | 27,000 | $1,350 |
| No | 210692411 | DAIKIN | DZ9VCA4810A* | CHPF4860D6D*+TXV | D*96VC0804CNA* | 27,000 | $1,350 |
| No | 210692407 | DAIKIN | DZ9VCA4810A* | CHPF4860D6D*+MBVC2000**-1A*+TXV | | 27,000 | $1,350 |
| No | 210692406 | DAIKIN | DZ9VCA4810A* | CHPF4860D6D*+MBVC1600**-1A*+TXV | | 27,000 | $1,350 |
| No | 210692405 | DAIKIN | DZ9VCA4810A* | CA*F4961*6D*+TXV | D*97MC1205DNA* | 27,000 | $1,350 |
| No | 210692404 | DAIKIN | DZ9VCA4810A* | CA*F4961*6D*+TXV | D*97MC1005CNA* | 27,000 | $1,350 |
| No | 210692403 | DAIKIN | DZ9VCA4810A* | CA*F4961*6D*+TXV | D*97MC0804CNA* | 27,000 | $1,350 |
| No | 210692402 | DAIKIN | DZ9VCA4810A* | CA*F4961*6D*+TXV | D*96VC1205DNA* | 27,000 | $1,350 |
| No | 210692401 | DAIKIN | DZ9VCA4810A* | CA*F4961*6D*+TXV | D*96VC1005CNA* | 27,000 | $1,350 |
| No | 210692400 | DAIKIN | DZ9VCA4810A* | CA*F4961*6D*+TXV | D*96SC0805CUA* | 27,000 | $1,350 |
| No | 210692399 | DAIKIN | DZ9VCA4810A* | CA*F4961*6D*+TXV | D*96VC0804CNA* | 27,000 | $1,350 |
| No | 210607579 | DAIKIN | DZ9VCA4810A* | CA*F4961*6D*+MBVC2000**-1A*+TX | | 27,000 | $1,350 |
| No | 210692393 | DAIKIN | DZ9VCA4810A* | CA*F4961*6D*+MBVC1600**-1A*+TXV | | 27,000 | $1,350 |
| No | 210692392 | DAIKIN | DZ9VCA4810A* | CA*F4860*6D*+TXV | D*97MC1205DNA* | 27,000 | $1,350 |
| No | 210692391 | DAIKIN | DZ9VCA4810A* | CA*F4860*6D*+TXV | D*97MC1005CNA* | 27,000 | $1,350 |
| No | 210692390 | DAIKIN | DZ9VCA4810A* | CA*F4860*6D*+TXV | D*97MC0804CNA* | 27,000 | $1,350 |
| No | 210692389 | DAIKIN | DZ9VCA4810A* | CA*F4860*6D*+TXV | D*96VC1205DNA* | 27,000 | $1,350 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210692388 | DAIKIN | DZ9VCA4810A* | CA*F4860*6D*+TXV | D*96VC1005CNA* | 27,000 | $1,350 |
| No | 210692387 | DAIKIN | DZ9VCA4810A* | CA*F4860*6D*+TXV | D*96SC0805CUA* | 27,000 | $1,350 |
| No | 210692386 | DAIKIN | DZ9VCA4810A* | CA*F4860*6D*+TXV | D*96VC0804CNA* | 27,000 | $1,350 |
| No | 210692381 | DAIKIN | DZ9VCA4810A* | CA*F4860*6D*+MBVC2000**-1A*+TXV | | 27,000 | $1,350 |
| No | 210692380 | DAIKIN | DZ9VCA4810A* | CA*F4860*6D*+MBVC1600**-1A*+TXV | | 27,000 | $1,350 |
| No | 210609977 | DAIKIN | DZ9VCA4810A* | DMVE60DP1400A* | | 27,000 | $1,350 |
| No | 210609976 | DAIKIN | DZ9VCA4810A* | DMVE48DP1400A* | | 27,000 | $1,350 |
| No | 210692291 | DAIKIN | DZ9VCA2410A* | CSCF3642N6D*+TXV | D*97MC0804CNA* | 14,200 | $710 |
| No | 210692290 | DAIKIN | DZ9VCA2410A* | CSCF3642N6D*+TXV | D*97MC0803BNA* | 14,200 | $710 |
| No | 210692289 | DAIKIN | DZ9VCA2410A* | CSCF3642N6D*+TXV | D*97MC0603BNA* | 14,200 | $710 |
| No | 210692288 | DAIKIN | DZ9VCA2410A* | CSCF3642N6D*+TXV | D*96VC0804CNA* | 14,200 | $710 |
| No | 210692287 | DAIKIN | DZ9VCA2410A* | CSCF3642N6D*+TXV | D*96VC0803BNA* | 14,200 | $710 |
| No | 210692286 | DAIKIN | DZ9VCA2410A* | CSCF3642N6D*+TXV | D*96VC0603BNA* | 14,200 | $710 |
| No | 210692285 | DAIKIN | DZ9VCA2410A* | CSCF3642N6D*+TXV | D*96SC0603BUA* | 14,200 | $710 |
| No | 210692284 | DAIKIN | DZ9VCA2410A* | CSCF3642N6D*+TXV | D*96VC0403BNA* | 14,200 | $710 |
| No | 210692281 | DAIKIN | DZ9VCA2410A* | CSCF3642N6D*+MBVC1200**-1A*+TXV | | 14,200 | $710 |
| No | 210692280 | DAIKIN | DZ9VCA2410A* | CHPF3642C6C*+MBVC1200**-1A*+TXV | | 14,100 | $705 |
| No | 210692279 | DAIKIN | DZ9VCA2410A* | CHPF3636B6C*+TXV | D*97MC0803BNA* | 14,200 | $710 |
| No | 210692278 | DAIKIN | DZ9VCA2410A* | CHPF3636B6C*+TXV | D*97MC0603BNA* | 14,200 | $710 |
| No | 210692277 | DAIKIN | DZ9VCA2410A* | CHPF3636B6C*+TXV | D*96VC0803BNA* | 14,200 | $710 |
| No | 210692276 | DAIKIN | DZ9VCA2410A* | CHPF3636B6C*+TXV | D*96VC0603BNA* | 14,200 | $710 |
| No | 210692275 | DAIKIN | DZ9VCA2410A* | CHPF3636B6C*+TXV | D*96SC0603BUA* | 14,200 | $710 |
| No | 210692274 | DAIKIN | DZ9VCA2410A* | CHPF3636B6C*+TXV | D*96VC0403BNA* | 14,200 | $710 |
| No | 210692271 | DAIKIN | DZ9VCA2410A* | CHPF3636B6C*+MBVC1200**-1A*+TXV | | 14,200 | $710 |
| No | 210692270 | DAIKIN | DZ9VCA2410A* | CA*F3743*6D*+TXV | D*97MC0804CNA* | 14,500 | $725 |
| No | 210692269 | DAIKIN | DZ9VCA2410A* | CA*F3743*6D*+TXV | D*97MC0803BNA* | 14,500 | $725 |
| No | 210692268 | DAIKIN | DZ9VCA2410A* | CA*F3743*6D*+TXV | D*97MC0603BNA* | 14,500 | $725 |
| No | 210692267 | DAIKIN | DZ9VCA2410A* | CA*F3743*6D*+TXV | D*96VC0804CNA* | 14,500 | $725 |
| No | 210692266 | DAIKIN | DZ9VCA2410A* | CA*F3743*6D*+TXV | D*96VC0803BNA* | 14,500 | $725 |
| No | 210692265 | DAIKIN | DZ9VCA2410A* | CA*F3743*6D*+TXV | D*96VC0603BNA* | 14,600 | $730 |
| No | 210692264 | DAIKIN | DZ9VCA2410A* | CA*F3743*6D*+TXV | D*96SC0603BUA* | 14,600 | $730 |
| No | 210692263 | DAIKIN | DZ9VCA2410A* | CA*F3743*6D*+TXV | D*96VC0403BNA* | 14,500 | $725 |
| No | 210692260 | DAIKIN | DZ9VCA2410A* | CA*F3743*6D*+MBVC1200**-1A*+TXV | | 14,500 | $725 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210692259 | DAIKIN | DZ9VCA2410A* | CA*F3137*6A*+TXV | D*97MC0803BNA* | 13,800 | $690 |
| No | 210692258 | DAIKIN | DZ9VCA2410A* | CA*F3137*6A*+TXV | D*97MC0603BNA* | 13,800 | $690 |
| No | 210692257 | DAIKIN | DZ9VCA2410A* | CA*F3137*6A*+TXV | D*96VC0803BNA* | 13,800 | $690 |
| No | 210692256 | DAIKIN | DZ9VCA2410A* | CA*F3137*6A*+TXV | D*96VC0603BNA* | 13,800 | $690 |
| No | 210692255 | DAIKIN | DZ9VCA2410A* | CA*F3137*6A*+TXV | D*96SC0603BUA* | 13,800 | $690 |
| No | 210692254 | DAIKIN | DZ9VCA2410A* | CA*F3137*6A*+TXV | D*96VC0403BNA* | 13,800 | $690 |
| No | 210607570 | DAIKIN | DZ9VCA2410A* | CA*F3137*6A*+MBVC1200**-1A*+TX | | 14,000 | $700 |
| No | 210610032 | DAIKIN | DZ9VCA2410A* | DMVE24BP1400A* | | 14,800 | $740 |
| No | 207172985 | DAIKIN | DZ17VSA241B* | CA*EA1818*4A* | D*80SC0604BUA* | 14,300 | $715 |
| No | 207172984 | DAIKIN | DZ17VSA241B* | CA*EA2422*4A* | D*80SC0604BUA* | 14,300 | $715 |
| No | 207172950 | DAIKIN | DZ17VSA181B* | CA*EA1818*4A* | D*80SC0604BUA* | 10,500 | $525 |
| No | 207172987 | DAIKIN | DZ17VSA241B* | CA*EA1818*4A* | D*80SC0805CUA* | 14,300 | $715 |
| No | 207172986 | DAIKIN | DZ17VSA241B* | CA*EA2422*4A* | D*80SC0805CUA* | 14,300 | $715 |
| No | 207172968 | DAIKIN | DZ17VSA241B* | CA*EA2422*4A* | D*80VC0603B*A* | 14,300 | $715 |
| No | 207172969 | DAIKIN | DZ17VSA241B* | CA*EA1818*4A* | D*80VC0603B*A* | 14,300 | $715 |
| No | 207172944 | DAIKIN | DZ17VSA181B* | CA*EA1818*4A* | D*80VC0603B*A* | 10,500 | $525 |
| No | 207172972 | DAIKIN | DZ17VSA241B* | CA*EA2422*4A* | D*80VC0803B*A* | 14,300 | $715 |
| No | 207172946 | DAIKIN | DZ17VSA181B* | CA*EA1818*4A* | D*80VC0803B*A* | 10,500 | $525 |
| No | 207172976 | DAIKIN | DZ17VSA241B* | CA*EA2422*4A* | D*80VC0805C*A* | 14,300 | $715 |
| No | 207172977 | DAIKIN | DZ17VSA241B* | CA*EA1818*4A* | D*80VC0805C*A* | 14,300 | $715 |
| No | 207172979 | DAIKIN | DZ17VSA241B* | CA*EA1818*4A* | D*80VC1005C*A* | 14,300 | $715 |
| No | 207172978 | DAIKIN | DZ17VSA241B* | CA*EA2422*4A* | D*80VC1005C*A* | 14,300 | $715 |
| No | 207172973 | DAIKIN | DZ17VSA241B* | CA*EA1818*4A* | D*80VC0803B*A* | 14,300 | $715 |
| No | 207172971 | DAIKIN | DZ17VSA241B* | CA*EA1818*4A* | DM80VC0604B*A* | 14,300 | $715 |
| No | 207172945 | DAIKIN | DZ17VSA181B* | CA*EA1818*4A* | DM80VC0604B*A* | 10,500 | $525 |
| No | 207172974 | DAIKIN | DZ17VSA241B* | CA*EA2422*4A* | DM80VC0804C*A* | 14,300 | $715 |
| No | 207172975 | DAIKIN | DZ17VSA241B* | CA*EA1818*4A* | DM80VC0804C*A* | 14,300 | $715 |
| No | 207172947 | DAIKIN | DZ17VSA181B* | CA*EA1818*4A* | DM80VC0804C*A* | 10,500 | $525 |
| No | 207172970 | DAIKIN | DZ17VSA241B* | CA*EA2422*4A* | DM80VC0604B*A* | 14,300 | $715 |
| No | 9116985 | DAIKIN | DZ20VC0241B* | DV25PECB14A* | | 13,600 | $680 |
| No | 9116987 | DAIKIN | DZ20VC0241B* | CA*F3636*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 9116989 | DAIKIN | DZ20VC0241B* | CA*F3743*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 9116986 | DAIKIN | DZ20VC0241B* | CA*F3137*6A*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 9116990 | DAIKIN | DZ20VC0241B* | CHPF3636B6C*+MBVC1200**-1A*+TXV | | 13,000 | $650 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 9116991 | DAIKIN | DZ20VC0241B* | CSCF3642N6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 9116992 | DAIKIN | DZ20VC0241B* | CA*F3137*6A*+TXV | D*80VC0604B*A* | 13,000 | $650 |
| No | 9116994 | DAIKIN | DZ20VC0241B* | CA*F3642*6D*+TXV | D*80VC0604B*A* | 13,000 | $650 |
| No | 9116993 | DAIKIN | DZ20VC0241B* | CA*F3636*6D*+TXV | D*80VC0604B*A* | 13,000 | $650 |
| No | 9116995 | DAIKIN | DZ20VC0241B* | CA*F3743*6D*+TXV | D*80VC0604B*A* | 13,000 | $650 |
| No | 9116998 | DAIKIN | DZ20VC0241B* | CA*F3137*6A*+TXV | D*96VC0403BNA* | 13,000 | $650 |
| No | 9117000 | DAIKIN | DZ20VC0241B* | CA*F3642*6D*+TXV | D*96VC0403BNA* | 13,000 | $650 |
| No | 9116997 | DAIKIN | DZ20VC0241B* | CSCF3642N6D*+TXV | D*80VC0604B*A* | 13,000 | $650 |
| No | 9116996 | DAIKIN | DZ20VC0241B* | CHPF3636B6C*+TXV | D*80VC0604B*A* | 13,000 | $650 |
| No | 9116999 | DAIKIN | DZ20VC0241B* | CA*F3636*6D*+TXV | D*96VC0403BNA* | 13,000 | $650 |
| No | 9117002 | DAIKIN | DZ20VC0241B* | CHPF3636B6C*+TXV | D*96VC0403BNA* | 13,000 | $650 |
| No | 9117005 | DAIKIN | DZ20VC0241B* | CA*F3636*6D*+TXV | D*96VC0603BNA* | 13,000 | $650 |
| No | 9117001 | DAIKIN | DZ20VC0241B* | CA*F3743*6D*+TXV | D*96VC0403BNA* | 13,000 | $650 |
| No | 9117003 | DAIKIN | DZ20VC0241B* | CSCF3642N6D*+TXV | D*96VC0403BNA* | 13,000 | $650 |
| No | 9117014 | DAIKIN | DZ20VC0241B* | CHPF3636B6C*+TXV | D*96VC0803BNA* | 13,000 | $650 |
| No | 9117004 | DAIKIN | DZ20VC0241B* | CA*F3137*6A*+TXV | D*96VC0603BNA* | 13,000 | $650 |
| No | 9117008 | DAIKIN | DZ20VC0241B* | CHPF3636B6C*+TXV | D*96VC0603BNA* | 13,000 | $650 |
| No | 9117009 | DAIKIN | DZ20VC0241B* | CSCF3642N6D*+TXV | D*96VC0603BNA* | 13,000 | $650 |
| No | 9117007 | DAIKIN | DZ20VC0241B* | CA*F3743*6D*+TXV | D*96VC0603BNA* | 13,000 | $650 |
| No | 9117006 | DAIKIN | DZ20VC0241B* | CA*F3642*6D*+TXV | D*96VC0603BNA* | 13,000 | $650 |
| No | 9117010 | DAIKIN | DZ20VC0241B* | CA*F3137*6A*+TXV | D*96VC0803BNA* | 13,000 | $650 |
| No | 9117013 | DAIKIN | DZ20VC0241B* | CA*F3743*6D*+TXV | D*96VC0803BNA* | 13,000 | $650 |
| No | 9117026 | DAIKIN | DZ20VC0241B* | CSCF3642N6D*+TXV | D*97MC0603BNA* | 13,000 | $650 |
| No | 9117011 | DAIKIN | DZ20VC0241B* | CA*F3636*6D*+TXV | D*96VC0803BNA* | 13,000 | $650 |
| No | 9117012 | DAIKIN | DZ20VC0241B* | CA*F3642*6D*+TXV | D*96VC0803BNA* | 13,000 | $650 |
| No | 9117041 | DAIKIN | DZ20VC0361B* | DV59PECD14A* | | 18,900 | $945 |
| No | 9117015 | DAIKIN | DZ20VC0241B* | CSCF3642N6D*+TXV | D*96VC0803BNA* | 13,000 | $650 |
| No | 9117017 | DAIKIN | DZ20VC0241B* | CA*F3642*6D*+TXV | D*96VC0804CNA* | 13,000 | $650 |
| No | 9117016 | DAIKIN | DZ20VC0241B* | CA*F3636*6D*+TXV | D*96VC0804CNA* | 13,000 | $650 |
| No | 9117018 | DAIKIN | DZ20VC0241B* | CA*F3743*6D*+TXV | D*96VC0804CNA* | 13,000 | $650 |
| No | 9117023 | DAIKIN | DZ20VC0241B* | CA*F3642*6D*+TXV | D*97MC0603BNA* | 13,000 | $650 |
| No | 9117021 | DAIKIN | DZ20VC0241B* | CA*F3137*6A*+TXV | D*97MC0603BNA* | 13,000 | $650 |
| No | 9117020 | DAIKIN | DZ20VC0241B* | CSCF3642N6D*+TXV | D*96VC0804CNA* | 13,000 | $650 |
| No | 9117022 | DAIKIN | DZ20VC0241B* | CA*F3636*6D*+TXV | D*97MC0603BNA* | 13,000 | $650 |
| No | 9117024 | DAIKIN | DZ20VC0241B* | CA*F3743*6D*+TXV | D*97MC0603BNA* | 13,000 | $650 |
| No | 9117025 | DAIKIN | DZ20VC0241B* | CHPF3636B6C*+TXV | D*97MC0603BNA* | 13,000 | $650 |
| No | 9117027 | DAIKIN | DZ20VC0241B* | CA*F3137*6A*+TXV | D*97MC0803BNA* | 13,000 | $650 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 9117028 | DAIKIN | DZ20VC0241B* | CA*F3636*6D*+TXV | D*97MC0803BNA* | 13,000 | $650 |
| No | 9117029 | DAIKIN | DZ20VC0241B* | CA*F3642*6D*+TXV | D*97MC0803BNA* | 13,000 | $650 |
| No | 9117030 | DAIKIN | DZ20VC0241B* | CA*F3743*6D*+TXV | D*97MC0803BNA* | 13,000 | $650 |
| No | 9117032 | DAIKIN | DZ20VC0241B* | CSCF3642N6D*+TXV | D*97MC0803BNA* | 13,000 | $650 |
| No | 9117031 | DAIKIN | DZ20VC0241B* | CHPF3636B6C*+TXV | D*97MC0803BNA* | 13,000 | $650 |
| No | 9117037 | DAIKIN | DZ20VC0241B* | CSCF3642N6D*+TXV | D*97MC0804CNA* | 13,000 | $650 |
| No | 9117034 | DAIKIN | DZ20VC0241B* | CA*F3642*6D*+TXV | D*97MC0804CNA* | 13,000 | $650 |
| No | 9117033 | DAIKIN | DZ20VC0241B* | CA*F3636*6D*+TXV | D*97MC0804CNA* | 13,000 | $650 |
| No | 9117035 | DAIKIN | DZ20VC0241B* | CA*F3743*6D*+TXV | D*97MC0804CNA* | 13,000 | $650 |
| No | 9117040 | DAIKIN | DZ20VC0361B* | DV37PECC14A* | | 18,900 | $945 |
| No | 9117044 | DAIKIN | DZ20VC0361B* | CA*F3743*6D*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 9117045 | DAIKIN | DZ20VC0361B* | CHPF3642C6C*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 9117042 | DAIKIN | DZ20VC0361B* | CA*F3137*6A*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 9117047 | DAIKIN | DZ20VC0361B* | CSCF3642N6D*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 9117043 | DAIKIN | DZ20VC0361B* | CA*F3642*6D*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 9117046 | DAIKIN | DZ20VC0361B* | CHPF3743C6B*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 9117048 | DAIKIN | DZ20VC0361B* | CA*F3137*6A*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 9117051 | DAIKIN | DZ20VC0361B* | CHPF3642C6C*+MBVC1600**-1A*+TXV | | 18,000 | $900 |
| No | 9117049 | DAIKIN | DZ20VC0361B* | CA*F3642*6D*+MBVC1600**-1A*+TXV | | 18,000 | $900 |
| No | 9117057 | DAIKIN | DZ20VC0361B* | CHPF3642C6C*+TXV | D*80VC0604B*A* | 18,000 | $900 |
| No | 9117052 | DAIKIN | DZ20VC0361B* | CHPF3743C6B*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 9117056 | DAIKIN | DZ20VC0361B* | CA*F3743*6D*+TXV | D*80VC0604B*A* | 18,000 | $900 |
| No | 9117053 | DAIKIN | DZ20VC0361B* | CSCF3642N6D*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 9117054 | DAIKIN | DZ20VC0361B* | CA*F3137*6A*+TXV | D*80VC0604B*A* | 18,200 | $910 |
| No | 9117055 | DAIKIN | DZ20VC0361B* | CA*F3642*6D*+TXV | D*80VC0604B*A* | 18,200 | $910 |
| No | 9117059 | DAIKIN | DZ20VC0361B* | CSCF3642N6D*+TXV | D*80VC0604B*A* | 18,200 | $910 |
| No | 9117058 | DAIKIN | DZ20VC0361B* | CHPF3743C6B*+TXV | D*80VC0604B*A* | 18,200 | $910 |
| No | 9117061 | DAIKIN | DZ20VC0361B* | CA*F3743*6D*+TXV | D*80VC0805C*A* | 18,200 | $910 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 9117060 | DAIKIN | DZ20VC0361B* | CA*F3642*6D*+TXV | D*80VC0805C*A* | 18,000 | $900 |
| No | 9117075 | DAIKIN | DZ20VC0361B* | CSCF3642N6D*+TXV | D*96VC0403BNA* | 18,200 | $910 |
| No | 9117064 | DAIKIN | DZ20VC0361B* | CSCF3642N6D*+TXV | D*80VC0805C*A* | 18,200 | $910 |
| No | 9117062 | DAIKIN | DZ20VC0361B* | CHPF3642C6C*+TXV | D*80VC0805C*A* | 18,000 | $900 |
| No | 9117063 | DAIKIN | DZ20VC0361B* | CHPF3743C6B*+TXV | D*80VC0805C*A* | 18,200 | $910 |
| No | 9117078 | DAIKIN | DZ20VC0361B* | CA*F3743*6D*+TXV | D*96VC0603BNA* | 18,200 | $910 |
| No | 9117065 | DAIKIN | DZ20VC0361B* | CA*F3642*6D*+TXV | D*80VC1005C*A* | 18,000 | $900 |
| No | 9117067 | DAIKIN | DZ20VC0361B* | CHPF3642C6C*+TXV | D*80VC1005C*A* | 18,000 | $900 |
| No | 9117066 | DAIKIN | DZ20VC0361B* | CA*F3743*6D*+TXV | D*80VC1005C*A* | 18,200 | $910 |
| No | 9117068 | DAIKIN | DZ20VC0361B* | CHPF3743C6B*+TXV | D*80VC1005C*A* | 18,200 | $910 |
| No | 9117069 | DAIKIN | DZ20VC0361B* | CSCF3642N6D*+TXV | D*80VC1005C*A* | 18,200 | $910 |
| No | 9117071 | DAIKIN | DZ20VC0361B* | CA*F3642*6D*+TXV | D*96VC0403BNA* | 18,000 | $900 |
| No | 9117070 | DAIKIN | DZ20VC0361B* | CA*F3137*6A*+TXV | D*96VC0403BNA* | 18,200 | $910 |
| No | 9117084 | DAIKIN | DZ20VC0361B* | CA*F3743*6D*+TXV | D*96VC0803BNA* | 18,200 | $910 |
| No | 9117072 | DAIKIN | DZ20VC0361B* | CA*F3743*6D*+TXV | D*96VC0403BNA* | 18,200 | $910 |
| No | 9117085 | DAIKIN | DZ20VC0361B* | CHPF3642C6C*+TXV | D*96VC0803BNA* | 18,000 | $900 |
| No | 9117074 | DAIKIN | DZ20VC0361B* | CHPF3743C6B*+TXV | D*96VC0403BNA* | 18,200 | $910 |
| No | 9117073 | DAIKIN | DZ20VC0361B* | CHPF3642C6C*+TXV | D*96VC0403BNA* | 18,000 | $900 |
| No | 9117077 | DAIKIN | DZ20VC0361B* | CA*F3642*6D*+TXV | D*96VC0603BNA* | 18,000 | $900 |
| No | 9117079 | DAIKIN | DZ20VC0361B* | CHPF3642C6C*+TXV | D*96VC0603BNA* | 18,000 | $900 |
| No | 9117076 | DAIKIN | DZ20VC0361B* | CA*F3137*6A*+TXV | D*96VC0603BNA* | 18,200 | $910 |
| No | 9117080 | DAIKIN | DZ20VC0361B* | CHPF3743C6B*+TXV | D*96VC0603BNA* | 18,200 | $910 |
| No | 9117082 | DAIKIN | DZ20VC0361B* | CA*F3137*6A*+TXV | D*96VC0803BNA* | 18,200 | $910 |
| No | 9117083 | DAIKIN | DZ20VC0361B* | CA*F3642*6D*+TXV | D*96VC0803BNA* | 18,000 | $900 |
| No | 9117081 | DAIKIN | DZ20VC0361B* | CSCF3642N6D*+TXV | D*96VC0603BNA* | 18,200 | $910 |
| No | 9117098 | DAIKIN | DZ20VC0361B* | CA*F3642*6D*+TXV | D*96VC1205DNA* | 18,000 | $900 |
| No | 9117086 | DAIKIN | DZ20VC0361B* | CHPF3743C6B*+TXV | D*96VC0803BNA* | 18,200 | $910 |
| No | 9117088 | DAIKIN | DZ20VC0361B* | CA*F3642*6D*+TXV | D*96VC0804CNA* | 18,200 | $910 |
| No | 9117089 | DAIKIN | DZ20VC0361B* | CA*F3743*6D*+TXV | D*96VC0804CNA* | 18,000 | $900 |
| No | 9117087 | DAIKIN | DZ20VC0361B* | CSCF3642N6D*+TXV | D*96VC0803BNA* | 18,200 | $910 |
| No | 9117090 | DAIKIN | DZ20VC0361B* | CHPF3642C6C*+TXV | D*96VC0804CNA* | 18,000 | $900 |
| No | 9117091 | DAIKIN | DZ20VC0361B* | CHPF3743C6B*+TXV | D*96VC0804CNA* | 18,200 | $910 |
| No | 9117092 | DAIKIN | DZ20VC0361B* | CSCF3642N6D*+TXV | D*96VC0804CNA* | 18,200 | $910 |
| No | 9117094 | DAIKIN | DZ20VC0361B* | CA*F3743*6D*+TXV | D*96VC1005CNA* | 18,200 | $910 |
| No | 9117095 | DAIKIN | DZ20VC0361B* | CHPF3642C6C*+TXV | D*96VC1005CNA* | 18,000 | $900 |
| No | 9117096 | DAIKIN | DZ20VC0361B* | CHPF3743C6B*+TXV | D*96VC1005CNA* | 18,200 | $910 |
| No | 9117093 | DAIKIN | DZ20VC0361B* | CA*F3642*6D*+TXV | D*96VC1005CNA* | 18,000 | $900 |
| No | 9117104 | DAIKIN | DZ20VC0361B* | CA*F3642*6D*+TXV | D*97MC0603BNA* | 18,000 | $900 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 9117099 | DAIKIN | DZ20VC0361B* | CA*F3743*6D*+TXV | D*96VC1205DNA* | 18,200 | $910 |
| No | 9117097 | DAIKIN | DZ20VC0361B* | CSCF3642N6D*+TXV | D*96VC1005CNA* | 18,200 | $910 |
| No | 9117103 | DAIKIN | DZ20VC0361B* | CA*F3137*6A*+TXV | D*97MC0603BNA* | 18,200 | $910 |
| No | 9117102 | DAIKIN | DZ20VC0361B* | CSCF3642N6D*+TXV | D*96VC1205DNA* | 18,200 | $910 |
| No | 9117106 | DAIKIN | DZ20VC0361B* | CHPF3642C6C*+TXV | D*97MC0603BNA* | 18,000 | $900 |
| No | 9117105 | DAIKIN | DZ20VC0361B* | CA*F3743*6D*+TXV | D*97MC0603BNA* | 18,200 | $910 |
| No | 9117109 | DAIKIN | DZ20VC0361B* | CA*F3137*6A*+TXV | D*97MC0803BNA* | 18,200 | $910 |
| No | 9117110 | DAIKIN | DZ20VC0361B* | CA*F3642*6D*+TXV | D*97MC0803BNA* | 18,000 | $900 |
| No | 9117107 | DAIKIN | DZ20VC0361B* | CHPF3743C6B*+TXV | D*97MC0603BNA* | 18,200 | $910 |
| No | 9117108 | DAIKIN | DZ20VC0361B* | CSCF3642N6D*+TXV | D*97MC0603BNA* | 18,200 | $910 |
| No | 9117111 | DAIKIN | DZ20VC0361B* | CA*F3743*6D*+TXV | D*97MC0803BNA* | 18,200 | $910 |
| No | 9117114 | DAIKIN | DZ20VC0361B* | CSCF3642N6D*+TXV | D*97MC0803BNA* | 18,200 | $910 |
| No | 9117112 | DAIKIN | DZ20VC0361B* | CHPF3642C6C*+TXV | D*97MC0803BNA* | 18,000 | $900 |
| No | 9117113 | DAIKIN | DZ20VC0361B* | CHPF3743C6B*+TXV | D*97MC0803BNA* | 18,200 | $910 |
| No | 9117117 | DAIKIN | DZ20VC0361B* | CHPF3642C6C*+TXV | D*97MC0804CNA* | 18,000 | $900 |
| No | 9117116 | DAIKIN | DZ20VC0361B* | CA*F3743*6D*+TXV | D*97MC0804CNA* | 18,000 | $900 |
| No | 9117118 | DAIKIN | DZ20VC0361B* | CHPF3743C6B*+TXV | D*97MC0804CNA* | 18,200 | $910 |
| No | 9117115 | DAIKIN | DZ20VC0361B* | CA*F3642*6D*+TXV | D*97MC0804CNA* | 18,200 | $910 |
| No | 9117119 | DAIKIN | DZ20VC0361B* | CSCF3642N6D*+TXV | D*97MC0804CNA* | 18,200 | $910 |
| No | 9117124 | DAIKIN | DZ20VC0361B* | CSCF3642N6D*+TXV | D*97MC1005CNA* | 18,200 | $910 |
| No | 9117120 | DAIKIN | DZ20VC0361B* | CA*F3642*6D*+TXV | D*97MC1005CNA* | 18,000 | $900 |
| No | 9117122 | DAIKIN | DZ20VC0361B* | CHPF3642C6C*+TXV | D*97MC1005CNA* | 18,000 | $900 |
| No | 9117121 | DAIKIN | DZ20VC0361B* | CA*F3743*6D*+TXV | D*97MC1005CNA* | 18,200 | $910 |
| No | 9117123 | DAIKIN | DZ20VC0361B* | CHPF3743C6B*+TXV | D*97MC1005CNA* | 18,200 | $910 |
| No | 9117125 | DAIKIN | DZ20VC0361B* | CA*F3642*6D*+TXV | D*97MC1205DNA* | 18,000 | $900 |
| No | 9117133 | DAIKIN | DZ20VC0481B* | CA*F4961*6D*+MBVC1600**-1A*+TXV | | 28,000 | $1,400 |
| No | 9117126 | DAIKIN | DZ20VC0361B* | CA*F3743*6D*+TXV | D*97MC1205DNA* | 18,200 | $910 |
| No | 9117131 | DAIKIN | DZ20VC0481B* | DV61PECD14A* | | 28,600 | $1,430 |
| No | 9117129 | DAIKIN | DZ20VC0361B* | CSCF3642N6D*+TXV | D*97MC1205DNA* | 18,200 | $910 |
| No | 9117132 | DAIKIN | DZ20VC0481B* | CA*F4860*6D*+MBVC1600**-1A*+TXV | | 27,400 | $1,370 |
| No | 9117134 | DAIKIN | DZ20VC0481B* | CHPF4860D6D*+MBVC1600**-1A*+TXV | | 28,000 | $1,400 |
| No | 9117136 | DAIKIN | DZ20VC0481B* | CA*F4860*6D*+MBVC2000**-1A*+TXV | | 27,400 | $1,370 |
| No | 9117135 | DAIKIN | DZ20VC0481B* | CSCF4860N6D*+MBVC1600**-1A*+TXV | | 27,400 | $1,370 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 9117139 | DAIKIN | DZ20VC0481B* | CSCF4860N6D*+MBVC2000**-1A*+TXV | | 27,400 | $1,370 |
| No | 9117138 | DAIKIN | DZ20VC0481B* | CHPF4860D6D*+MBVC2000**-1A*+TXV | | 28,000 | $1,400 |
| No | 9117140 | DAIKIN | DZ20VC0481B* | CA*F4860*6D*+TXV | D*80VC0604B*A* | 27,400 | $1,370 |
| No | 9117141 | DAIKIN | DZ20VC0481B* | CA*F4961*6D*+TXV | D*80VC0604B*A* | 28,000 | $1,400 |
| No | 9117145 | DAIKIN | DZ20VC0481B* | CA*F4961*6D*+TXV | D*80VC0805C*A* | 28,000 | $1,400 |
| No | 9117146 | DAIKIN | DZ20VC0481B* | CHPF4860D6D*+TXV | D*80VC0805C*A* | 28,000 | $1,400 |
| No | 9117143 | DAIKIN | DZ20VC0481B* | CSCF4860N6D*+TXV | D*80VC0604B*A* | 27,400 | $1,370 |
| No | 9117144 | DAIKIN | DZ20VC0481B* | CA*F4860*6D*+TXV | D*80VC0805C*A* | 27,400 | $1,370 |
| No | 9117147 | DAIKIN | DZ20VC0481B* | CSCF4860N6D*+TXV | D*80VC0805C*A* | 27,400 | $1,370 |
| No | 9117160 | DAIKIN | DZ20VC0481B* | CA*F4860*6D*+TXV | D*96VC1205DNA* | 27,400 | $1,370 |
| No | 9117148 | DAIKIN | DZ20VC0481B* | CA*F4860*6D*+TXV | D*80VC1005C*A* | 27,400 | $1,370 |
| No | 9117149 | DAIKIN | DZ20VC0481B* | CA*F4961*6D*+TXV | D*80VC1005C*A* | 28,000 | $1,400 |
| No | 9117150 | DAIKIN | DZ20VC0481B* | CHPF4860D6D*+TXV | D*80VC1005C*A* | 28,000 | $1,400 |
| No | 9117152 | DAIKIN | DZ20VC0481B* | CA*F4860*6D*+TXV | D*96VC0804CNA* | 27,400 | $1,370 |
| No | 9117151 | DAIKIN | DZ20VC0481B* | CSCF4860N6D*+TXV | D*80VC1005C*A* | 27,400 | $1,370 |
| No | 9117153 | DAIKIN | DZ20VC0481B* | CA*F4961*6D*+TXV | D*96VC0804CNA* | 28,000 | $1,400 |
| No | 9117154 | DAIKIN | DZ20VC0481B* | CHPF4860D6D*+TXV | D*96VC0804CNA* | 28,000 | $1,400 |
| No | 9117155 | DAIKIN | DZ20VC0481B* | CSCF4860N6D*+TXV | D*96VC0804CNA* | 27,400 | $1,370 |
| No | 9117157 | DAIKIN | DZ20VC0481B* | CA*F4961*6D*+TXV | D*96VC1005CNA* | 28,000 | $1,400 |
| No | 9117158 | DAIKIN | DZ20VC0481B* | CHPF4860D6D*+TXV | D*96VC1005CNA* | 28,000 | $1,400 |
| No | 9117156 | DAIKIN | DZ20VC0481B* | CA*F4860*6D*+TXV | D*96VC1005CNA* | 27,400 | $1,370 |
| No | 9117159 | DAIKIN | DZ20VC0481B* | CSCF4860N6D*+TXV | D*96VC1005CNA* | 27,400 | $1,370 |
| No | 9117161 | DAIKIN | DZ20VC0481B* | CA*F4961*6D*+TXV | D*96VC1205DNA* | 28,000 | $1,400 |
| No | 9117172 | DAIKIN | DZ20VC0481B* | CA*F4860*6D*+TXV | D*97MC1205DNA* | 27,400 | $1,370 |
| No | 9117162 | DAIKIN | DZ20VC0481B* | CHPF4860D6D*+TXV | D*96VC1205DNA* | 28,000 | $1,400 |
| No | 9117164 | DAIKIN | DZ20VC0481B* | CA*F4860*6D*+TXV | D*97MC0804CNA* | 27,400 | $1,370 |
| No | 9117163 | DAIKIN | DZ20VC0481B* | CSCF4860N6D*+TXV | D*96VC1205DNA* | 27,400 | $1,370 |
| No | 9117165 | DAIKIN | DZ20VC0481B* | CA*F4961*6D*+TXV | D*97MC0804CNA* | 28,000 | $1,400 |
| No | 9117166 | DAIKIN | DZ20VC0481B* | CHPF4860D6D*+TXV | D*97MC0804CNA* | 28,000 | $1,400 |
| No | 9117167 | DAIKIN | DZ20VC0481B* | CSCF4860N6D*+TXV | D*97MC0804CNA* | 27,400 | $1,370 |
| No | 9117168 | DAIKIN | DZ20VC0481B* | CA*F4860*6D*+TXV | D*97MC1005CNA* | 27,400 | $1,370 |
| No | 9117169 | DAIKIN | DZ20VC0481B* | CA*F4961*6D*+TXV | D*97MC1005CNA* | 28,000 | $1,400 |
| No | 9117171 | DAIKIN | DZ20VC0481B* | CSCF4860N6D*+TXV | D*97MC1005CNA* | 27,400 | $1,370 |
| No | 9117170 | DAIKIN | DZ20VC0481B* | CHPF4860D6D*+TXV | D*97MC1005CNA* | 28,000 | $1,400 |
| No | 9117173 | DAIKIN | DZ20VC0481B* | CA*F4961*6D*+TXV | D*97MC1205DNA* | 28,000 | $1,400 |
| No | 9117174 | DAIKIN | DZ20VC0481B* | CHPF4860D6D*+TXV | D*97MC1205DNA* | 28,000 | $1,400 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202327351 | DAIKIN | DZ20VC0481B* | DV59PECD14A* | | 27,000 | $1,350 |
| No | 9117175 | DAIKIN | DZ20VC0481B* | CSCF4860N6D*+TXV | D*97MC1205DNA* | 27,400 | $1,370 |
| No | 205651526 | DAIKIN | DZ20VC0241B* | CA*F3137*6A*+TXV | D*80SC0604BUA* | 13,000 | $650 |
| No | 205651528 | DAIKIN | DZ20VC0241B* | CA*F3636*6D*+TXV | D*80SC0604BUA* | 13,000 | $650 |
| No | 205651530 | DAIKIN | DZ20VC0241B* | CA*F3743*6D*+TXV | D*80SC0604BUA* | 13,000 | $650 |
| No | 205651536 | DAIKIN | DZ20VC0241B* | CA*F3137*6A*+TXV | D*96SC0603BUA* | 13,000 | $650 |
| No | 205651532 | DAIKIN | DZ20VC0241B* | CHPF3636B6C*+TXV | D*80SC0604BUA* | 13,000 | $650 |
| No | 205651538 | DAIKIN | DZ20VC0241B* | CA*F3636*6D*+TXV | D*96SC0603BUA* | 13,000 | $650 |
| No | 205651540 | DAIKIN | DZ20VC0241B* | CA*F3743*6D*+TXV | D*96SC0603BUA* | 13,000 | $650 |
| No | 205651534 | DAIKIN | DZ20VC0241B* | CSCF3642N6D*+TXV | D*80SC0604BUA* | 13,000 | $650 |
| No | 205651542 | DAIKIN | DZ20VC0241B* | CHPF3636B6C*+TXV | D*96SC0603BUA* | 13,000 | $650 |
| No | 205651566 | DAIKIN | DZ20VC0361B* | CHPF3743C6B*+TXV | D*80SC0604BUA* | 18,200 | $910 |
| No | 205651544 | DAIKIN | DZ20VC0241B* | CSCF3642N6D*+TXV | D*96SC0603BUA* | 13,000 | $650 |
| No | 205651546 | DAIKIN | DZ20VC0361B* | CA*F3137*6A*+TXV | D*80SC0604BUA* | 18,200 | $910 |
| No | 205651548 | DAIKIN | DZ20VC0361B* | CA*F3743*6D*+TXV | D*80SC0604BUA* | 18,000 | $900 |
| No | 205651552 | DAIKIN | DZ20VC0361B* | CA*F3137*6A*+TXV | D*96SC0603BUA* | 18,200 | $910 |
| No | 205651550 | DAIKIN | DZ20VC0361B* | CHPF3642C6C*+TXV | D*80SC0805CUA* | 18,000 | $900 |
| No | 205651554 | DAIKIN | DZ20VC0361B* | CA*F3743*6D*+TXV | D*96SC0603BUA* | 18,200 | $910 |
| No | 205651556 | DAIKIN | DZ20VC0361B* | CHPF3642C6C*+TXV | D*96SC0603BUA* | 18,000 | $900 |
| No | 205651558 | DAIKIN | DZ20VC0361B* | CHPF3743C6B*+TXV | D*96SC0603BUA* | 18,200 | $910 |
| No | 205651560 | DAIKIN | DZ20VC0361B* | CA*F3743*6D*+TXV | D*96SC0805CUA* | 18,200 | $910 |
| No | 205651564 | DAIKIN | DZ20VC0361B* | CHPF3642C6C*+TXV | D*80SC0604BUA* | 18,000 | $900 |
| No | 205651562 | DAIKIN | DZ20VC0361B* | CHPF3642C6C*+TXV | D*96SC0805CUA* | 18,000 | $900 |
| No | 205651572 | DAIKIN | DZ20VC0481B* | CA*F4961*6D*+TXV | D*80SC0604BUA* | 28,000 | $1,400 |
| No | 205651574 | DAIKIN | DZ20VC0481B* | CSCF4860N6D*+TXV | D*80SC0604BUA* | 27,400 | $1,370 |
| No | 205651568 | DAIKIN | DZ20VC0361B* | CHPF3743C6B*+TXV | D*80SC0805CUA* | 18,200 | $910 |
| No | 205651576 | DAIKIN | DZ20VC0481B* | CA*F4860*6D*+TXV | D*80SC0805CUA* | 27,400 | $1,370 |
| No | 205651570 | DAIKIN | DZ20VC0361B* | CHPF3743C6B*+TXV | D*96SC0805CUA* | 18,200 | $910 |
| No | 205651578 | DAIKIN | DZ20VC0481B* | CA*F4961*6D*+TXV | D*80SC0805CUA* | 27,200 | $1,360 |
| No | 205651876 | DAIKIN | DZ20VC0361B* | CA*F3642*6D*+TXV | D*96SC0603BUA* | 18,000 | $900 |
| No | 205651580 | DAIKIN | DZ20VC0481B* | CHPF4860D6D*+TXV | D*80SC0805CUA* | 27,200 | $1,360 |
| No | 205651586 | DAIKIN | DZ20VC0481B* | CA*F4961*6D*+TXV | D*96SC0805CUA* | 27,600 | $1,380 |
| No | 205651584 | DAIKIN | DZ20VC0481B* | CA*F4860*6D*+TXV | D*96SC0805CUA* | 27,400 | $1,370 |
| No | 205651870 | DAIKIN | DZ20VC0361B* | CA*F3642*6D*+TXV | D*80SC0805CUA* | 18,000 | $900 |
| No | 205651582 | DAIKIN | DZ20VC0481B* | CSCF4860N6D*+TXV | D*80SC0805CUA* | 27,400 | $1,370 |
| No | 205651588 | DAIKIN | DZ20VC0481B* | CSCF4860N6D*+TXV | D*96SC0805CUA* | 27,400 | $1,370 |
| No | 205651874 | DAIKIN | DZ20VC0361B* | CSCF3642N6D*+TXV | D*80SC0805CUA* | 18,200 | $910 |
| No | 205651872 | DAIKIN | DZ20VC0361B* | CA*F3743*6D*+TXV | D*80SC0805CUA* | 18,200 | $910 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205976197 | DAIKIN | DZ20VC0601C* | CA*F4961*6D*+TXV | D*97MC1005CNA* | 32,000 | $1,600 |
| No | 205651880 | DAIKIN | DZ20VC0361B* | CA*F3642*6D*+TXV | D*96SC0805CUA* | 18,000 | $900 |
| No | 205651878 | DAIKIN | DZ20VC0361B* | CSCF3642N6D*+TXV | D*96SC0603BUA* | 18,200 | $910 |
| No | 205651882 | DAIKIN | DZ20VC0361B* | CSCF3642N6D*+TXV | D*96SC0805CUA* | 18,200 | $910 |
| No | 205976198 | DAIKIN | DZ20VC0601C* | CA*F4961*6D*+TXV | D*97MC1205DNA* | 32,000 | $1,600 |
| No | 205651884 | DAIKIN | DZ20VC0361B* | CA*F3642*6D*+TXV | D*80SC0604BUA* | 18,200 | $910 |
| No | 205651886 | DAIKIN | DZ20VC0361B* | CSCF3642N6D*+TXV | D*80SC0604BUA* | 18,200 | $910 |
| No | 205976137 | DAIKIN | DZ20VC0601C* | CA*F4961*6D*+MBVC2000**-1A*+TXV | | 32,000 | $1,600 |
| No | 205976193 | DAIKIN | DZ20VC0601C* | CA*F4961*6D*+TXV | D*80VC0805C*A* | 32,000 | $1,600 |
| No | 205976212 | DAIKIN | DZ20VC0601C* | CSCF4860N6D*+TXV | D*96VC1005CNA* | 32,000 | $1,600 |
| No | 205976196 | DAIKIN | DZ20VC0601C* | CA*F4961*6D*+TXV | D*96VC1205DNA* | 32,000 | $1,600 |
| No | 205976195 | DAIKIN | DZ20VC0601C* | CA*F4961*6D*+TXV | D*96VC1005CNA* | 32,000 | $1,600 |
| No | 205976194 | DAIKIN | DZ20VC0601C* | CA*F4961*6D*+TXV | D*80VC1005C*A* | 32,000 | $1,600 |
| No | 205976199 | DAIKIN | DZ20VC0601C* | CA*F4961*6D*+TXV | D*80SC0805CUA* | 32,000 | $1,600 |
| No | 205976200 | DAIKIN | DZ20VC0601C* | CA*F4961*6D*+TXV | D*96SC0805CUA* | 32,000 | $1,600 |
| No | 205976201 | DAIKIN | DZ20VC0601C* | CHPF4860D6D*+TXV | D*80VC0805C*A* | 32,000 | $1,600 |
| No | 205976202 | DAIKIN | DZ20VC0601C* | CHPF4860D6D*+TXV | D*80VC1005C*A* | 32,000 | $1,600 |
| No | 205976203 | DAIKIN | DZ20VC0601C* | CHPF4860D6D*+TXV | D*96VC1005CNA* | 32,000 | $1,600 |
| No | 205976204 | DAIKIN | DZ20VC0601C* | CHPF4860D6D*+TXV | D*96VC1205DNA* | 32,000 | $1,600 |
| No | 205976205 | DAIKIN | DZ20VC0601C* | CHPF4860D6D*+TXV | D*97MC1005CNA* | 32,000 | $1,600 |
| No | 205976206 | DAIKIN | DZ20VC0601C* | CHPF4860D6D*+TXV | D*97MC1205DNA* | 32,000 | $1,600 |
| No | 205976207 | DAIKIN | DZ20VC0601C* | CHPF4860D6D*+MBVC2000**-1A*+TXV | | 32,000 | $1,600 |
| No | 205976216 | DAIKIN | DZ20VC0601C* | CSCF4860N6D*+TXV | D*80SC0805CUA* | 32,000 | $1,600 |
| No | 205976210 | DAIKIN | DZ20VC0601C* | CSCF4860N6D*+TXV | D*80VC0805C*A* | 32,000 | $1,600 |
| No | 205976209 | DAIKIN | DZ20VC0601C* | CHPF4860D6D*+TXV | D*96SC0805CUA* | 32,000 | $1,600 |
| No | 205976208 | DAIKIN | DZ20VC0601C* | CHPF4860D6D*+TXV | D*80SC0805CUA* | 32,000 | $1,600 |
| No | 205976211 | DAIKIN | DZ20VC0601C* | CSCF4860N6D*+TXV | D*80VC1005C*A* | 32,000 | $1,600 |
| No | 205976217 | DAIKIN | DZ20VC0601C* | CSCF4860N6D*+TXV | D*96SC0805CUA* | 32,000 | $1,600 |
| No | 205976214 | DAIKIN | DZ20VC0601C* | CSCF4860N6D*+TXV | D*97MC1005CNA* | 32,000 | $1,600 |
| No | 205976213 | DAIKIN | DZ20VC0601C* | CSCF4860N6D*+TXV | D*96VC1205DNA* | 32,000 | $1,600 |
| No | 205976215 | DAIKIN | DZ20VC0601C* | CSCF4860N6D*+TXV | D*97MC1205DNA* | 32,000 | $1,600 |
| No | 205976218 | DAIKIN | DZ20VC0601C* | DV61PECD14A* | | 32,600 | $1,630 |
| No | 10595346 | DAIKIN | DZ20VC0241B* | CHPF3642C6C*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 10324715 | DAIKIN | DZ20VC0601B | CA*F4961*6D*+MBVC2000**-1A*+TXV | | 32,000 | $1,600 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10324711 | DAIKIN | DZ20VC0361B* | CA*F3743*6D*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 10324709 | DAIKIN | DZ20VC0241B* | CA*F3642*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 204875689 | DAIKIN | DZ17VSA241A* | CA*EA2422*4A* | D*97MC1005CNA* | 14,300 | $715 |
| No | 204875686 | DAIKIN | DZ17VSA241A* | CA*EA1818*4A* | D*97MC0804CNA* | 14,300 | $715 |
| No | 204875683 | DAIKIN | DZ17VSA241A* | CA*EA2422*4A* | D*97MC0804CNA* | 14,300 | $715 |
| No | 204875680 | DAIKIN | DZ17VSA241A* | CA*EA1818*4A* | D*97MC0803BNA* | 14,300 | $715 |
| No | 204875677 | DAIKIN | DZ17VSA241A* | CA*EA2422*4A* | D*97MC0803BNA* | 14,300 | $715 |
| No | 204875675 | DAIKIN | DZ17VSA241A* | CA*EA1818*4A* | D*97MC0603BNA* | 14,300 | $715 |
| No | 204875669 | DAIKIN | DZ17VSA241A* | CA*EA2422*4A* | D*96VC1005CNA* | 14,300 | $715 |
| No | 204875660 | DAIKIN | DZ17VSA241A* | CA*EA1818*4A* | DM96VC0803BNA* | 14,300 | $715 |
| No | 204875663 | DAIKIN | DZ17VSA241A* | CA*EA2422*4A* | D*96VC0804CNA* | 14,300 | $715 |
| No | 204875672 | DAIKIN | DZ17VSA241A* | CA*EA2422*4A* | D*97MC0603BNA* | 14,300 | $715 |
| No | 204875657 | DAIKIN | DZ17VSA241A* | CA*EA2422*4A* | DM96VC0803BNA* | 14,300 | $715 |
| No | 204875654 | DAIKIN | DZ17VSA241A* | CA*EA1818*4A* | D*96VC0603BNA* | 14,300 | $715 |
| No | 204875666 | DAIKIN | DZ17VSA241A* | CA*EA1818*4A* | D*96VC0804CNA* | 14,300 | $715 |
| No | 204875645 | DAIKIN | DZ17VSA241A* | CA*EA2422*4A* | D*96VC0403BNA* | 14,300 | $715 |
| No | 204875384 | DAIKIN | DZ17VSA241A* | DV24FECB14A* | | 14,300 | $715 |
| No | 204875648 | DAIKIN | DZ17VSA241A* | CA*EA1818*4A* | D*96VC0403BNA* | 14,300 | $715 |
| No | 204875651 | DAIKIN | DZ17VSA241A* | CA*EA2422*4A* | D*96VC0603BNA* | 14,300 | $715 |
| No | 204875639 | DAIKIN | DZ17VSA181A* | CA*EA1818*4A*+MBVC1200**-1A* | | 10,500 | $525 |
| No | 204875642 | DAIKIN | DZ17VSA181A* | CA*EA1818*4A*+MBVC1600**-1A* | | 10,500 | $525 |
| No | 204875636 | DAIKIN | DZ17VSA181A* | CA*EA1818*4A* | DM80VC0804C*A* | 10,500 | $525 |
| No | 204875630 | DAIKIN | DZ17VSA181A* | CA*EA1818*4A* | DM80VC0604B*A* | 10,500 | $525 |
| No | 204875633 | DAIKIN | DZ17VSA181A* | CA*EA1818*4A* | D*80VC0803B*A* | 10,500 | $525 |
| No | 204875627 | DAIKIN | DZ17VSA181A* | CA*EA1818*4A* | D*80VC0603B*A* | 10,500 | $525 |
| No | 204875624 | DAIKIN | DZ17VSA181A* | CA*EA1818*4A* | D*97MC0804CNA* | 10,500 | $525 |
| No | 204875618 | DAIKIN | DZ17VSA181A* | CA*EA1818*4A* | D*97MC0603BNA* | 10,500 | $525 |
| No | 204875621 | DAIKIN | DZ17VSA181A* | CA*EA1818*4A* | D*97MC0803BNA* | 10,500 | $525 |
| No | 204875615 | DAIKIN | DZ17VSA181A* | CA*EA1818*4A* | D*96VC0804CNA* | 10,500 | $525 |
| No | 204875612 | DAIKIN | DZ17VSA181A* | CA*EA1818*4A* | DM96VC0803BNA* | 10,500 | $525 |
| No | 204875609 | DAIKIN | DZ17VSA181A* | CA*EA1818*4A* | D*96VC0603BNA* | 10,500 | $525 |
| No | 204875606 | DAIKIN | DZ17VSA181A* | CA*EA1818*4A* | D*96VC0403BNA* | 10,500 | $525 |
| No | 204875381 | DAIKIN | DZ17VSA181A* | DV24FECB14A* | | 10,500 | $525 |
| No | 204875737 | DAIKIN | DZ17VSA241A* | CA*EA1818*4A*+MBVC1600**-1A* | | 14,300 | $715 |
| No | 204875734 | DAIKIN | DZ17VSA241A* | CA*EA2422*4A*+MBVC1600**-1A* | | 14,300 | $715 |
| No | 204875729 | DAIKIN | DZ17VSA241A* | CA*EA2422*4A*+MBVC1200**-1A* | | 14,300 | $715 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204875732 | DAIKIN | DZ17VSA241A* | CA*EA1818*4A*+MBVC1200**-1A* | | 14,300 | $715 |
| No | 204875726 | DAIKIN | DZ17VSA241A* | CA*EA1818*4A* | D*80VC1005C*A* | 14,300 | $715 |
| No | 204875723 | DAIKIN | DZ17VSA241A* | CA*EA2422*4A* | D*80VC1005C*A* | 14,300 | $715 |
| No | 204875719 | DAIKIN | DZ17VSA241A* | CA*EA1818*4A* | D*80VC0805C*A* | 14,300 | $715 |
| No | 204875716 | DAIKIN | DZ17VSA241A* | CA*EA2422*4A* | D*80VC0805C*A* | 14,300 | $715 |
| No | 204875710 | DAIKIN | DZ17VSA241A* | CA*EA2422*4A* | DM80VC0804C*A* | 14,300 | $715 |
| No | 204875714 | DAIKIN | DZ17VSA241A* | CA*EA1818*4A* | DM80VC0804C*A* | 14,300 | $715 |
| No | 204875707 | DAIKIN | DZ17VSA241A* | CA*EA1818*4A* | D*80VC0803B*A* | 14,300 | $715 |
| No | 204875698 | DAIKIN | DZ17VSA241A* | CA*EA2422*4A* | DM80VC0604B*A* | 14,300 | $715 |
| No | 204875701 | DAIKIN | DZ17VSA241A* | CA*EA1818*4A* | DM80VC0604B*A* | 14,300 | $715 |
| No | 204875695 | DAIKIN | DZ17VSA241A* | CA*EA1818*4A* | D*80VC0603B*A* | 14,300 | $715 |
| No | 204875704 | DAIKIN | DZ17VSA241A* | CA*EA2422*4A* | D*80VC0803B*A* | 14,300 | $715 |
| No | 204875692 | DAIKIN | DZ17VSA241A* | CA*EA2422*4A* | D*80VC0603B*A* | 14,300 | $715 |
| No | 204717989 | DAIKIN | RXL12QMVJU9 | FVXS12NVJU | | 8,300 | $415 |
| No | 202638701 | DAIKIN | 5MXS48TVJU | Heat pump without ducts | | 31,000 | $1,550 |
| No | 202521824 | DAIKIN | 4MXL36TVJU | Heat pump without ducts | | 22,400 | $1,120 |
| No | 201851577 | DAIKIN | 3MXL24RMVJU | Heat pump without ducts | | 15,500 | $775 |
| No | 201851575 | DAIKIN | 3MXS24RMVJU | Heat pump without ducts | | 15,500 | $775 |
| No | 10324713 | DAIKIN | DZ20VC0481B* | CA*F4961*6D*+MBVC2000**-1A*+TXV | | 28,400 | $1,420 |
| No | 202682020 | DAIKIN | RX09RMVJU9 | FDMQ09RVJU | | 6,800 | $340 |
| No | 202682021 | DAIKIN | RX12RMVJU9 | FDMQ12RVJU | | 8,500 | $425 |
| No | 202682023 | DAIKIN | RX09RMVJU9 | FFQ09Q2VJU | | 6,000 | $300 |
| No | 202682024 | DAIKIN | RX12RMVJU9 | FFQ12Q2VJU | | 8,300 | $415 |
| No | 207776277 | DAIKIN | RXL09QMVJU* | FTX09NMVJU* | | 6,700 | $335 |
| No | 207776280 | DAIKIN | RXL09QMVJU* | FVXS09NVJU | | 6,200 | $310 |
| No | 207776278 | DAIKIN | RXL12QMVJU9* | FTX12NMVJU* | | 8,800 | $440 |
| No | 205663349 | DAIKIN | RXL15QMVJU* | FTX15NMVJU* | | 11,500 | $575 |
| No | 207776283 | DAIKIN | RX09RMVJU9* | FFQ09Q2VJU | | 6,000 | $300 |
| No | 207776281 | DAIKIN | RXL12QMVJU9* | FVXS12NVJU | | 8,300 | $415 |
| No | 207776282 | DAIKIN | RXL12QMVJU9* | FDMQ12RVJU | | 8,600 | $430 |
| No | 207776284 | DAIKIN | RX12RMVJU9* | FFQ12Q2VJU | | 8,300 | $415 |
| No | 207776287 | DAIKIN | RX09RMVJU9* | FDMQ09RVJU | | 6,800 | $340 |
| No | 207776290 | DAIKIN | RX12RMVJU9* | FDMQ12RVJU | | 8,500 | $425 |
| No | 205707004 | DAIKIN | RZQ42TAVJU* | FTQ42TAVJU*A* | | 34,000 | $1,700 |
| No | 205801310 | DAIKIN | RZQ18TAVJU* | FCQ18TAVJU | | 12,300 | $615 |
| No | 8849535 | DAIKIN | 2MXL18QMVJU | Heat pump without ducts | | 12,000 | $600 |
| No | 205732182 | DAIKIN | RXSQ24T*VJU* | CXTQ24TASBLUA* | D*80VC1005C*A* | 15,400 | $770 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205732185 | DAIKIN | RXSQ36T*VJU* | CXTQ36TASBLUA* | D*80VC0805C*A* | 23,600 | $1,180 |
| No | 205732187 | DAIKIN | RXSQ24T*VJU* | FXTQ24TAVJUA* | | 15,400 | $770 |
| No | 205732160 | DAIKIN | RXSQ24T*VJU* | CXTQ24TASBLUA* | D*80VC0604B*A* | 15,400 | $770 |
| No | 205732179 | DAIKIN | RXSQ24T*VJU* | CXTQ24TASBLUA* | D*80VC0603B*A* | 15,400 | $770 |
| No | 205732180 | DAIKIN | RXSQ24T*VJU* | CXTQ24TASBLUA* | D*80VC0803B*A* | 15,400 | $770 |
| No | 205732155 | DAIKIN | RXSQ24T*VJU* | CXTQ24TASBLUA* | D*96VC0603BNA* | 15,400 | $770 |
| No | 205732181 | DAIKIN | RXSQ24T*VJU* | CXTQ24TASBLUA* | D*80VC0805C*A* | 15,400 | $770 |
| No | 205732161 | DAIKIN | RXSQ24T*VJU* | CXTQ24TASBLUA* | D*96VC0403BNA* | 15,400 | $770 |
| No | 205732163 | DAIKIN | RXSQ24T*VJU* | CXTQ24TASBLUA* | D*96VC0803BNA* | 15,400 | $770 |
| No | 205732188 | DAIKIN | RXSQ36T*VJU* | FXTQ36TAVJUA* | | 23,600 | $1,180 |
| No | 205724753 | DAIKIN | RXSQ24T*VJU* | FXFQ07TVJU FXFQ07TVJU FXFQ09TVJU | | 14,000 | $700 |
| No | 205732164 | DAIKIN | RXSQ24T*VJU* | CXTQ24TASBLUA* | D*97MC0803BNA* | 15,400 | $770 |
| No | 205732162 | DAIKIN | RXSQ24T*VJU* | CXTQ24TASBLUA* | D*97MC0603BNA* | 15,400 | $770 |
| No | 205732183 | DAIKIN | RXSQ36T*VJU* | CXTQ36TASBLUA* | D*80VC0603B*A* | 23,600 | $1,180 |
| No | 205732165 | DAIKIN | RXSQ36T*VJU* | CXTQ36TASBLUA* | D*80VC0604B*A* | 23,600 | $1,180 |
| No | 205732184 | DAIKIN | RXSQ36T*VJU* | CXTQ36TASBLUA* | D*80VC0803B*A* | 23,600 | $1,180 |
| No | 205732186 | DAIKIN | RXSQ36T*VJU* | CXTQ36TASBLUA* | D*80VC1005C*A* | 23,600 | $1,180 |
| No | 205732190 | DAIKIN | RXSQ60T*VJU* | FXTQ60TAVJUA* | | 37,000 | $1,850 |
| No | 205732166 | DAIKIN | RXSQ36T*VJU* | CXTQ36TASBLUA* | D*96VC0403BNA* | 23,600 | $1,180 |
| No | 205724751 | DAIKIN | RXSQ24T*VJU* | FXMQ07PBVJU FXMQ07PBVJU FXMQ09PBVJU | | 15,000 | $750 |
| No | 205732168 | DAIKIN | RXSQ36T*VJU* | CXTQ36TASBLUA* | D*97MC0803BNA* | 23,600 | $1,180 |
| No | 205724752 | DAIKIN | RXSQ36T*VJU* | FXMQ07PBVJU FXMQ07PBVJU FXMQ07PBVJU FXMQ15PBVJU | | 22,000 | $1,100 |
| No | 205881786 | DAIKIN | RXTQ48TAVJU* | FXMQ09PBVJU FXMQ09PBVJU FXMQ15PBVJU FXMQ15PBVJU | | 32,000 | $1,600 |
| No | 205881782 | DAIKIN | RXSQ60T*VJU* | FXMQ15PBVJU FXMQ15PBVJU FXMQ15PBVJU FXMQ18PBVJU | | 34,000 | $1,700 |
| No | 205881781 | DAIKIN | RXSQ48T*VJU* | FXMQ09PBVJU FXMQ09PBVJU FXMQ15PBVJU FXMQ15PBVJU | | 32,000 | $1,600 |
| No | 205708866 | DAIKIN | RXTQ36TAVJ9* | FXMQ07PBVJU FXMQ07PBVJU FXMQ07PBVJU FXMQ15PBVJU | | 22,000 | $1,100 |
| No | 205881788 | DAIKIN | RXTQ60TAVJU* | FXMQ15PBVJU FXMQ15PBVJU FXMQ15PBVJU FXMQ18PBVJU | | 34,000 | $1,700 |
| No | 205708867 | DAIKIN | RXTQ36TAVJ9* | FXFQ07TVJU FXFQ07TVJU FXFQ07TVJU FXFQ15TVJU | | 23,600 | $1,180 |
| No | 205724755 | DAIKIN | RXSQ48T*VJU* | FXFQ07TVJU FXFQ07TVJU FXFQ15TVJU FXFQ18TVJU | | 32,200 | $1,610 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205724754 | DAIKIN | RXSQ36T*VJU* | FXFQ07TVJU FXFQ07TVJU FXFQ07TVJU FXFQ15TVJU | | 23,600 | $1,180 |
| No | 205724756 | DAIKIN | RXSQ60T*VJU* | FXFQ07TVJU FXFQ07TVJU FXFQ24TVJU FXFQ24TVJU | | 37,000 | $1,850 |
| No | 205708868 | DAIKIN | RXTQ48TAVJU* | FXFQ07TVJU FXFQ07TVJU FXFQ15TVJU FXFQ18TVJU | | 32,200 | $1,610 |
| No | 205708869 | DAIKIN | RXTQ60TAVJU* | FXFQ07TVJU FXFQ07TVJU FXFQ24TVJU FXFQ24TVJU | | 37,000 | $1,850 |
| No | 205724758 | DAIKIN | RXSQ36T*VJU* | Combination heat pumps with or without ducts | | 22,800 | $1,140 |
| No | 205881783 | DAIKIN | RXSQ48T*VJU* | Combination heat pumps with or without ducts | | 32,000 | $1,600 |
| No | 205708982 | DAIKIN | RXTQ36TAVJ9* | Combination heat pumps with or without ducts | | 22,800 | $1,140 |
| No | 205724757 | DAIKIN | RXSQ24T*VJU* | Combination heat pumps with or without ducts | | 14,500 | $725 |
| No | 205881785 | DAIKIN | RXS60T*VJU* | Combination heat pumps with or without ducts | | 35,400 | $1,770 |
| No | 205881790 | DAIKIN | RXTQ60TAVJU* | Combination heat pumps with or without ducts | | 35,400 | $1,770 |
| No | 205881789 | DAIKIN | RXTQ48TAVJU* | Combination heat pumps with or without ducts | | 32,000 | $1,600 |
| No | 201978157 | DAIKIN | RXSQ36T*VJU | FXTQ36TAVJUA* | | 23,600 | $1,180 |
| No | 10594273 | DAIKIN | RXSQ36T*VJU | CXTQ36TASBLUA* | D*97MC0803BNA* | 23,600 | $1,180 |
| No | 10594269 | DAIKIN | RXSQ36T*VJU | CXTQ36TASBLUA* | D*96VC0403BNA* | 23,600 | $1,180 |
| No | 201978159 | DAIKIN | RXSQ60T*VJU | FXTQ60TAVJUA* | | 37,000 | $1,850 |
| No | 201978155 | DAIKIN | RXSQ36T*VJU | CXTQ36TASBLUA* | D*80VC1005CXA* | 23,600 | $1,180 |
| No | 10594268 | DAIKIN | RXSQ36T*VJU | CXTQ36TASBLUA* | D*80VC0604B*A* | 23,600 | $1,180 |
| No | 201978152 | DAIKIN | RXSQ36T*VJU | CXTQ36TASBLUA* | D*80VC0603BXA* | 23,600 | $1,180 |
| No | 201978156 | DAIKIN | RXSQ24T*VJU | FXTQ24TAVJUA* | | 15,400 | $770 |
| No | 201978154 | DAIKIN | RXSQ36T*VJU | CXTQ36TASBLUA* | D*80VC0805CXA* | 23,600 | $1,180 |
| No | 10594267 | DAIKIN | RXSQ24T*VJU | CXTQ24TASBLUA* | D*97MC0803BNA* | 15,400 | $770 |
| No | 201978153 | DAIKIN | RXSQ36T*VJU | CXTQ36TASBLUA* | D*80VC0803BXA* | 23,600 | $1,180 |
| No | 10594265 | DAIKIN | RXSQ24T*VJU | CXTQ24TASBLUA* | D*97MC0603BNA* | 15,400 | $770 |
| No | 10594266 | DAIKIN | RXSQ24T*VJU | CXTQ24TASBLUA* | D*96VC0803BNA* | 15,400 | $770 |
| No | 10594259 | DAIKIN | RXSQ24T*VJU | CXTQ24TASBLUA* | D*96VC0603BNA* | 15,400 | $770 |
| No | 10594264 | DAIKIN | RXSQ24T*VJU | CXTQ24TASBLUA* | D*96VC0403BNA* | 15,400 | $770 |
| No | 201900051 | DAIKIN | RXSQ24T*VJU | CXTQ24TASBLUA* | D*80VC0803BXA* | 15,400 | $770 |
| No | 201900052 | DAIKIN | RXSQ24T*VJU | CXTQ24TASBLUA* | D*80VC0805CXA* | 15,400 | $770 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10594263 | DAIKIN | RXSQ24T*VJU | CXTQ24TASBLUA* | D*80VC0604B*A* | 15,400 | $770 |
| No | 201900050 | DAIKIN | RXSQ24T*VJU | CXTQ24TASBLUA* | D*80VC0603BXA* | 15,400 | $770 |
| No | 201900053 | DAIKIN | RXSQ24T*VJU | CXTQ24TASBLUA* | D*80VC1005CXA* | 15,400 | $770 |
| No | 10591684 | DAIKIN | RXSQ36T*VJU | Heat pump with ducts | | 22,000 | $1,100 |
| No | 10591687 | DAIKIN | RXSQ24T*VJU | Combination heat pumps with or without ducts | | 14,500 | $725 |
| No | 10591681 | DAIKIN | RXSQ24T*VJU | Heat pump with ducts | | 15,000 | $750 |
| No | 10591688 | DAIKIN | RXSQ36T*VJU | Combinaison d'unités avec et sans conduits | | 22,800 | $1,140 |
| No | 10591691 | DAIKIN | RXSQ60T*VJU | Combination heat pumps with or without ducts | | 35,500 | $1,775 |
| No | 207173030 | DAIKIN | DZ17VSA361B* | CA*EA3026*4A* | DM80VC0805D*A* | 22,000 | $1,100 |
| No | 207173003 | DAIKIN | DZ17VSA301B* | CA*EA2422*4A* | DM80VC0804C*A* | 17,600 | $880 |
| No | 207173027 | DAIKIN | DZ17VSA361B* | CA*EA3026*4A* | DM80VC0804C*A* | 22,000 | $1,100 |
| No | 207173001 | DAIKIN | DZ17VSA301B* | CA*EA2422*4A* | DM80VC0604B*A* | 17,600 | $880 |
| No | 207173025 | DAIKIN | DZ17VSA361B* | CA*EA3026*4A* | DM80VC0604B*A* | 22,000 | $1,100 |
| No | 207173028 | DAIKIN | DZ17VSA361B* | CA*EA3026*4A* | D*80VC0805C*A* | 22,000 | $1,100 |
| No | 207173029 | DAIKIN | DZ17VSA361B* | CA*EA3026*4A* | D*80VC1005C*A* | 22,000 | $1,100 |
| No | 207173005 | DAIKIN | DZ17VSA301B* | CA*EA2422*4A* | D*80VC1005C*A* | 17,600 | $880 |
| No | 207173004 | DAIKIN | DZ17VSA301B* | CA*EA2422*4A* | D*80VC0805C*A* | 17,600 | $880 |
| No | 207173026 | DAIKIN | DZ17VSA361B* | CA*EA3026*4A* | D*80VC0803B*A* | 22,000 | $1,100 |
| No | 207173002 | DAIKIN | DZ17VSA301B* | CA*EA2422*4A* | D*80VC0803B*A* | 17,600 | $880 |
| No | 207173000 | DAIKIN | DZ17VSA301B* | CA*EA2422*4A* | D*80VC0603B*A* | 17,600 | $880 |
| No | 207173024 | DAIKIN | DZ17VSA361B* | CA*EA3026*4A* | D*80VC0603B*A* | 22,000 | $1,100 |
| No | 207173036 | DAIKIN | DZ17VSA361B* | CA*EA3026*4A* | D*80SC0805CUA* | 22,000 | $1,100 |
| No | 207173009 | DAIKIN | DZ17VSA301B* | CA*EA2422*4A* | D*80SC0805CUA* | 17,600 | $880 |
| No | 207173008 | DAIKIN | DZ17VSA301B* | CA*EA2422*4A* | D*80SC0604BUA* | 17,600 | $880 |
| No | 207173035 | DAIKIN | DZ17VSA361B* | CA*EA3026*4A* | D*80SC0604BUA* | 22,000 | $1,100 |
| No | 205663366 | DAIKIN | 3MXS24RMVJU* | Combination heat pumps with or without ducts | | 15,200 | $760 |
| No | 205663367 | DAIKIN | 3MXL24RMVJU* | Combination heat pumps with or without ducts | | 15,200 | $760 |
| No | 205663365 | DAIKIN | 2MXL18QMVJU* | Combination heat pumps with or without ducts | | 11,700 | $585 |
| No | 202650862 | DAIKIN | 5MXS48TVJU | Combination heat pumps with or without ducts | | 30,600 | $1,530 |
| No | 202522140 | DAIKIN | 4MXL36TVJU | Combination heat pumps with or without ducts | | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205663353 | DAIKIN | 2MXS18NMVJU* | Combination heat pumps with or without ducts | | 12,000 | $600 |
| No | 205663368 | DAIKIN | 4MXS36RMVJU* | Combination heat pumps with or without ducts | | 20,600 | $1,030 |
| No | 204717600 | DAIKIN | RXL12QMVJU9 | FTX12NMVJU | | 8,800 | $440 |
| No | 205663354 | DAIKIN | 2MXL18QMVJU* | Heat pump without ducts | | 11,400 | $570 |
| No | 205663356 | DAIKIN | 3MXS24RMVJU* | Heat pump without ducts | | 15,500 | $775 |
| No | 205776148 | DAIKIN | RX15RMVJU* | FDMQ15RVJU | | 11,500 | $575 |
| No | 205663358 | DAIKIN | 3MXL24RMVJU* | Heat pump without ducts | | 15,500 | $775 |
| No | 205663360 | DAIKIN | 4MXS36RMVJU* | Heat pump without ducts | | 22,000 | $1,100 |
| No | 205663351 | DAIKIN | 2MXS18NMVJU* | Heat pump without ducts | | 12,000 | $600 |
| No | 205776150 | DAIKIN | RX18RMVJU9* | FDMQ18RVJU | | 13,600 | $680 |
| No | 205776151 | DAIKIN | RX24RMVJU* | FDMQ24RVJU | | 15,000 | $750 |
| No | 205663362 | DAIKIN | RX18RMVJU9* | FFQ18Q2VJU | | 14,200 | $710 |
| No | 205663346 | DAIKIN | RX15RMVJU* | FFQ15Q2VJU | | 10,600 | $530 |
| No | 205663350 | DAIKIN | RXL15QMVJU* | FVXS15NVJU | | 11,500 | $575 |
| No | 205782845 | DAIKIN | RX09AXVJU | FTX09AXVJU | | 5,700 | $285 |
| No | 205782846 | DAIKIN | RX12AXVJU | FTX12AXVJU | | 8,600 | $430 |
| No | 201851579 | DAIKIN | 4MXS36RMVJU | Heat pump without ducts | | 22,000 | $1,100 |
| No | 9966775 | DAIKIN | RX15QMVJU | FFQ15Q2VJU | | 10,600 | $530 |
| No | 9966569 | DAIKIN | RX09QMVJU | FFQ09Q2VJU | | 6,000 | $300 |
| No | 9966684 | DAIKIN | RX12QMVJU | FFQ12Q2VJU | | 8,300 | $415 |
| No | 8103542 | DAIKIN | 2MXS18NMVJU | Heat pump without ducts | | 12,000 | $600 |
| No | 5265758 | DAIKIN | RXS24LVJU | FTXS24LVJU | | 16,400 | $820 |
| No | 3208523 | DAIKIN | RXG15HVJU | FTXG15HVJU | | 11,100 | $555 |
| No | 5265757 | DAIKIN | RXS18LVJU | FTXS18LVJU | | 13,900 | $695 |
| No | 5265756 | DAIKIN | RXS15LVJU | FTXS15LVJU | | 11,900 | $595 |
| No | 3208522 | DAIKIN | RXG12HVJU | FTXG12HVJU | | 10,400 | $520 |
| No | 5265755 | DAIKIN | RXS12LVJU | FTXS12LVJU | | 9,200 | $460 |
| No | 5265753 | DAIKIN | RXS09LVJU | FTXS09LVJU | | 7,700 | $385 |
| No | 8849330 | DAIKIN | RXL15QMVJU | FTX15NMVJU | | 11,500 | $575 |
| No | 3208521 | DAIKIN | RXG09HVJU | FTXG09HVJU | | 8,100 | $405 |
| No | 8849445 | DAIKIN | RXL15QMVJU | FVXS15NVJU | | 11,500 | $575 |
| No | 8849459 | DAIKIN | RXL09QMVJU | FVXS09NVJU | | 6,200 | $310 |
| No | 204717990 | DAIKIN | RXL12QMVJU9 | FDMQ12RVJU | | 8,600 | $430 |
| No | 8849533 | DAIKIN | RXL09QMVJU | FTX09NMVJU | | 6,700 | $335 |
| No | 211994922 | Daizuki | DXFM-4823-5Z | Combination heat pumps with or without ducts | | 35,000 | $1,750 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211994920 | Daizuki | DXFM-4823-5Z | Heat pump without ducts | | 34,000 | $1,700 |
| No | 211994916 | Daizuki | DXFM-2723-3Z | Combination heat pumps with or without ducts | | 21,400 | $1,070 |
| No | 211994919 | Daizuki | DXFM-1823-2Z | Combination heat pumps with or without ducts | | 14,500 | $725 |
| No | 211994915 | Daizuki | DXFM-2723-3Z | Heat pump with ducts | | 22,000 | $1,100 |
| No | 211994918 | Daizuki | DXFM-1823-2Z | Heat pump with ducts | | 14,800 | $740 |
| No | 211994923 | Daizuki | DXFM-3623-4Z | Heat pump without ducts | | 26,800 | $1,340 |
| No | 211994914 | Daizuki | DXFM-2723-3Z | Heat pump without ducts | | 21,000 | $1,050 |
| No | 211994917 | Daizuki | DXFM-1823-2Z | Heat pump without ducts | | 14,300 | $715 |
| No | 210819422 | DAY & NIGHT | DLCSRBH30AAK | DLFSABH30XBK | | 20,400 | $1,020 |
| No | 209852060 | DAY & NIGHT | DLCURAH60AAK | DLFUAAH60XAK | | 37,000 | $1,850 |
| No | 209852057 | DAY & NIGHT | DLCURAH48AAK | DLFUAAH48XAK | | 37,000 | $1,850 |
| No | 209852064 | DAY & NIGHT | DLCURAH36AAK | DLFUAAH36XAK | | 20,400 | $1,020 |
| No | 209852066 | DAY & NIGHT | DLCURAH30ABK | DLFUAAH30XAK | | 21,000 | $1,050 |
| No | 209852063 | DAY & NIGHT | DLCURAH30AAK | DLFUAAH30XAK | | 20,000 | $1,000 |
| No | 209852056 | DAY & NIGHT | DLCURAH24AAK | DLFUAAH24XAK | | 21,000 | $1,050 |
| No | 209852062 | DAY & NIGHT | DLCURAH18AAK | DLFUAAH18XAK | | 12,000 | $600 |
| No | 207643047 | DAY & NIGHT | DLCMRBH48EAK | Heat pump without ducts | | 31,000 | $1,550 |
| No | 201835621 | DAY & NIGHT | DLCMRAH27CAK | Heat pump without ducts | | 17,800 | $890 |
| No | 208104313 | DAY & NIGHT | DLCSRBH36ABK | DLFSABH36XBK | | 25,600 | $1,280 |
| No | 207826622 | DAY & NIGHT | DLCLRCH36AAK | DLFLABH36XAK | | 25,600 | $1,280 |
| No | 207826621 | DAY & NIGHT | DLCLRCH58AAK | DLFLABH60XAK | | 34,000 | $1,700 |
| No | 207826620 | DAY & NIGHT | DLCLRCH48AAK | DLFLABH48XAK | | 37,400 | $1,870 |
| No | 207826598 | DAY & NIGHT | DLCSRBH24AAK | DLFSABH24XBK | | 16,200 | $810 |
| No | 208104314 | DAY & NIGHT | DLCSRBH30AAK11 | DLFSABH30XBK | | 19,200 | $960 |
| No | 206188299 | DAY & NIGHT | DLCLRBH48AAK | DLFLFAH48XAK | | 29,000 | $1,450 |
| No | 206188300 | DAY & NIGHT | DLCLRBH48AAK | DLFLCAH48XAK | | 29,000 | $1,450 |
| No | 206188297 | DAY & NIGHT | DLCLRBH36AAK | DLFLCAH36XAK | | 22,000 | $1,100 |
| No | 206188296 | DAY & NIGHT | DLCLRBH36AAK | DLFLFAH36XAK | | 22,000 | $1,100 |
| No | 206188301 | DAY & NIGHT | DLCLRBH48AAK | DLFLDAH48XAK | | 29,000 | $1,450 |
| No | 207202797 | DAY & NIGHT | DLCSRBH18AAK | FEM4P18**AL | | 14,700 | $735 |
| No | 207202798 | DAY & NIGHT | DLCSRBH18AAK | FEM4X18**BL | | 14,700 | $735 |
| No | 207202799 | DAY & NIGHT | DLCSRBH18AAK | EA*4X19L17A* | *80ES(N,L)0451412A* | 13,800 | $690 |
| No | 207202800 | DAY & NIGHT | DLCSRBH18AAK | EA*4X24L14A* | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207202801 | DAY & NIGHT | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207202802 | DAY & NIGHT | DLCSRBH18AAK | EA*4X25L17A* | *80ES(N,L)0451412A* | 13,800 | $690 |
| No | 207202803 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X18L14** | *80ES(N,L)0451412A* | 14,700 | $735 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207202804 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X24L14** | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207202805 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207202806 | DAY & NIGHT | DLCSRBH18AAK | EA*4X19L17A* | *80ES(N,L)0451712A* | 13,900 | $695 |
| No | 207202807 | DAY & NIGHT | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0451712A* | 14,600 | $730 |
| No | 207202808 | DAY & NIGHT | DLCSRBH18AAK | EA*4X25L17A* | *80ES(N,L)0451712A* | 13,800 | $690 |
| No | 207202809 | DAY & NIGHT | DLCSRBH18AAK | EA*4X19L17A* | *80ES(N,L)0701412A* | 13,900 | $695 |
| No | 207202810 | DAY & NIGHT | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0701412A* | 14,600 | $730 |
| No | 207202811 | DAY & NIGHT | DLCSRBH18AAK | EA*4X25L17A* | *80ES(N,L)0701412A* | 13,800 | $690 |
| No | 207202812 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X18L14** | *80ES(N,L)0701412A* | 14,700 | $735 |
| No | 207202813 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X24L14** | *80ES(N,L)0701412A* | 14,600 | $730 |
| No | 207202814 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ES(N,L)0701412A* | 14,600 | $730 |
| No | 207202815 | DAY & NIGHT | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0701712A* | 14,700 | $735 |
| No | 207202816 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ES(N,L)0701712A* | 14,700 | $735 |
| No | 207202817 | DAY & NIGHT | DLCSRBH18AAK | EA*4X19L17A* | *80ESU0401712A* | 13,700 | $685 |
| No | 207202818 | DAY & NIGHT | DLCSRBH18AAK | EA*4X24L17A* | *80ESU0401712A* | 14,500 | $725 |
| No | 207202819 | DAY & NIGHT | DLCSRBH18AAK | EA*4X25L17A* | *80ESU0401712A* | 13,600 | $680 |
| No | 207202820 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ESU0401712A* | 14,500 | $725 |
| No | 207202827 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0401410A* | 14,500 | $725 |
| No | 207202821 | DAY & NIGHT | DLCSRBH18AAK | EA*4X19L17A* | *92ESN0401410A* | 13,800 | $690 |
| No | 207202823 | DAY & NIGHT | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0401410A* | 14,500 | $725 |
| No | 207202822 | DAY & NIGHT | DLCSRBH18AAK | EA*4X24L14A* | *92ESN0401410A* | 14,500 | $725 |
| No | 207202824 | DAY & NIGHT | DLCSRBH18AAK | EA*4X25L17A* | *92ESN0401410A* | 13,700 | $685 |
| No | 207202825 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X18L14** | *92ESN0401410A* | 14,600 | $730 |
| No | 207202826 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X24L14** | *92ESN0401410A* | 14,500 | $725 |
| No | 207202829 | DAY & NIGHT | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0401712A* | 14,600 | $730 |
| No | 207202832 | DAY & NIGHT | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0601412A* | 14,600 | $730 |
| No | 207202828 | DAY & NIGHT | DLCSRBH18AAK | EA*4X19L17A* | *92ESN0401712A* | 13,900 | $695 |
| No | 207202830 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0401712A* | 14,600 | $730 |
| No | 207202831 | DAY & NIGHT | DLCSRBH18AAK | EA*4X19L17A* | *92ESN0601412A* | 14,000 | $700 |
| No | 207202834 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X18L14** | *92ESN0601412A* | 14,700 | $735 |
| No | 207202835 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X24L14** | *92ESN0601412A* | 14,600 | $730 |
| No | 207202833 | DAY & NIGHT | DLCSRBH18AAK | EA*4X25L17A* | *92ESN0601412A* | 13,800 | $690 |
| No | 207202837 | DAY & NIGHT | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0801716A* | 14,700 | $735 |
| No | 207202836 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0601412A* | 14,600 | $730 |
| No | 207202838 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0801716A* | 14,700 | $735 |
| No | 207202841 | DAY & NIGHT | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0261410A* | 13,900 | $695 |
| No | 207202840 | DAY & NIGHT | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0261410A* | 14,700 | $735 |
| No | 207202839 | DAY & NIGHT | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0261410A* | 14,100 | $705 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207202842 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X18L14** | *95ESN0261410A* | 14,800 | $740 |
| No | 207202843 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X24L14** | *95ESN0261410A* | 14,700 | $735 |
| No | 207202844 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0261410A* | 14,700 | $735 |
| No | 207202845 | DAY & NIGHT | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0401410A* | 13,900 | $695 |
| No | 207202846 | DAY & NIGHT | DLCSRBH18AAK | EA*4X24L14A* | *95ESN0401410A* | 14,600 | $730 |
| No | 207202848 | DAY & NIGHT | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0401410A* | 13,800 | $690 |
| No | 207202851 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0401410A* | 14,600 | $730 |
| No | 207202847 | DAY & NIGHT | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0401410A* | 14,600 | $730 |
| No | 207202849 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X18L14** | *95ESN0401410A* | 14,700 | $735 |
| No | 207202850 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X24L14** | *95ESN0401410A* | 14,600 | $730 |
| No | 207202852 | DAY & NIGHT | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0401712A* | 13,800 | $690 |
| No | 207202854 | DAY & NIGHT | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0401712A* | 13,700 | $685 |
| No | 207202853 | DAY & NIGHT | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0401712A* | 14,600 | $730 |
| No | 207202855 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0401712A* | 14,600 | $730 |
| No | 207202856 | DAY & NIGHT | DLCSRBH18AAK | EA*4X24L14A* | *95ESN0601412A* | 14,900 | $745 |
| No | 207202857 | DAY & NIGHT | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0601412A* | 14,900 | $745 |
| No | 207202858 | DAY & NIGHT | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0601714A* | 14,100 | $705 |
| No | 207202859 | DAY & NIGHT | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0601714A* | 14,000 | $700 |
| No | 207202860 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0601714A* | 14,700 | $735 |
| No | 207202865 | DAY & NIGHT | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0401410A* | 13,900 | $695 |
| No | 207202861 | DAY & NIGHT | DLCSRBH18AAK | EA*4X19L17A* | *95ESU0401712A* | 13,800 | $690 |
| No | 207202863 | DAY & NIGHT | DLCSRBH18AAK | EA*4X25L17A* | *95ESU0401712A* | 13,800 | $690 |
| No | 207202862 | DAY & NIGHT | DLCSRBH18AAK | EA*4X24L17A* | *95ESU0401712A* | 14,600 | $730 |
| No | 207202864 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESU0401712A* | 14,600 | $730 |
| No | 207202870 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X24L14** | *96VTN0401410A* | 14,700 | $735 |
| No | 207202866 | DAY & NIGHT | DLCSRBH18AAK | EA*4X24L14A* | *96VTN0401410A* | 14,700 | $735 |
| No | 207202874 | DAY & NIGHT | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0401712A* | 13,800 | $690 |
| No | 207202867 | DAY & NIGHT | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0401410A* | 14,700 | $735 |
| No | 207202868 | DAY & NIGHT | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0401410A* | 13,900 | $695 |
| No | 207202869 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X18L14** | *96VTN0401410A* | 14,800 | $740 |
| No | 207202875 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X24L17** | *96VTN0401712A* | 14,600 | $730 |
| No | 207202872 | DAY & NIGHT | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0401712A* | 13,900 | $695 |
| No | 207202871 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X24L17** | *96VTN0401410A* | 14,700 | $735 |
| No | 207202873 | DAY & NIGHT | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0401712A* | 14,600 | $730 |
| No | 207202876 | DAY & NIGHT | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0601412A* | 13,800 | $690 |
| No | 207202877 | DAY & NIGHT | DLCSRBH18AAK | EA*4X24L14A* | *96VTN0601412A* | 14,600 | $730 |
| No | 207202878 | DAY & NIGHT | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0601412A* | 14,600 | $730 |
| No | 207202879 | DAY & NIGHT | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0601412A* | 13,800 | $690 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207202880 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X18L14** | *96VTN0601412A* | 14,700 | $735 |
| No | 207202881 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X24L14** | *96VTN0601412A* | 14,600 | $730 |
| No | 207202882 | DAY & NIGHT | DLCSRBH18AAK | EN(A,D)4X24L17** | *96VTN0601412A* | 14,600 | $730 |
| No | 207202883 | DAY & NIGHT | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0601714A* | 14,100 | $705 |
| No | 207202884 | DAY & NIGHT | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0601714A* | 14,700 | $735 |
| No | 207202885 | DAY & NIGHT | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0601714A* | 13,900 | $695 |
| No | 207202886 | DAY & NIGHT | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0801716A* | 13,800 | $690 |
| No | 207202174 | DAY & NIGHT | DLCSRBH18AAK | FVM4X24***L | | 13,400 | $670 |
| No | 207202794 | DAY & NIGHT | DLCSRBH18AAK | FMA4X18**AL* | | 15,000 | $750 |
| No | 207202795 | DAY & NIGHT | DLCSRBH18AAK | FM(C,U)4Z18**AL* | | 15,000 | $750 |
| No | 207202796 | DAY & NIGHT | DLCSRBH18AAK | FXM4X18**AL | | 14,500 | $725 |
| No | 207099364 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X24L14** | *80ES(N,L)0451412A* | 15,600 | $780 |
| No | 207099365 | DAY & NIGHT | DLCSRBH24AAK | EA*4X24L14A* | *80ES(N,L)0451412A* | 15,700 | $785 |
| No | 207099376 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X30L14** | *80ES(N,L)0701412A* | 15,500 | $775 |
| No | 207099367 | DAY & NIGHT | DLCSRBH24AAK | EA*4X30L14A* | *80ES(N,L)0451412A* | 15,500 | $775 |
| No | 207099370 | DAY & NIGHT | DLCSRBH24AAK | EA*4X36L17A* | *80ES(N,L)0451712A* | 15,500 | $775 |
| No | 207099368 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X30L14** | *80ES(N,L)0451412A* | 15,500 | $775 |
| No | 207099371 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X24L14** | *80ES(N,L)0701412A* | 15,600 | $780 |
| No | 207099373 | DAY & NIGHT | DLCSRBH24AAK | EA*4X24L14A* | *80ES(N,L)0701412A* | 15,700 | $785 |
| No | 207099374 | DAY & NIGHT | DLCSRBH24AAK | EA*4X30L14A* | *80ES(N,L)0701412A* | 15,500 | $775 |
| No | 207099379 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X30L17** | *80ES(N,L)0701712A* | 15,400 | $770 |
| No | 207099378 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X24L17** | *80ES(N,L)0701712A* | 15,600 | $780 |
| No | 207099390 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *80ESU0401712A* | 15,400 | $770 |
| No | 207099381 | DAY & NIGHT | DLCSRBH24AAK | EA*4X36L17A* | *80ES(N,L)0701712A* | 15,400 | $770 |
| No | 207099382 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *80ES(N,L)0701712A* | 15,400 | $770 |
| No | 207099387 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X30L17** | *80ESU0401712A* | 15,400 | $770 |
| No | 207099384 | DAY & NIGHT | DLCSRBH24AAK | EA*4X30L17A* | *80ES(N,L)0701712A* | 15,500 | $775 |
| No | 207099385 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X24L17** | *80ESU0401712A* | 15,500 | $775 |
| No | 207099388 | DAY & NIGHT | DLCSRBH24AAK | EA*4X36L17A* | *80ESU0401712A* | 15,300 | $765 |
| No | 207099391 | DAY & NIGHT | DLCSRBH24AAK | EA*4X30L17A* | *80ESU0401712A* | 15,400 | $770 |
| No | 207099396 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X30L17** | *80ESU0601716A | 15,500 | $775 |
| No | 207099393 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X24L17** | *80ESU0601716A | 15,600 | $780 |
| No | 207099419 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X24L14** | *92ESN0601412A* | 15,600 | $780 |
| No | 207099397 | DAY & NIGHT | DLCSRBH24AAK | EA*4X36L17A* | *80ESU0601716A | 15,400 | $770 |
| No | 207099394 | DAY & NIGHT | DLCSRBH24AAK | EA*4X24L17A* | *80ESU0601716A | 15,700 | $785 |
| No | 207099399 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *80ESU0601716A | 15,500 | $775 |
| No | 207099421 | DAY & NIGHT | DLCSRBH24AAK | EA*4X24L14A* | *92ESN0601412A* | 15,700 | $785 |
| No | 207099424 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X30L14** | *92ESN0601412A* | 15,500 | $775 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207099422 | DAY & NIGHT | DLCSRBH24AAK | EA*4X30L14A* | *92ESN0601412A* | 15,500 | $775 |
| No | 207099427 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X24L14** | *92ESN0601714A* | 15,500 | $775 |
| No | 207099430 | DAY & NIGHT | DLCSRBH24AAK | EA*4X30L14A* | *92ESN0601714A* | 15,500 | $775 |
| No | 207099431 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X30L14** | *92ESN0601714A* | 15,400 | $770 |
| No | 207099428 | DAY & NIGHT | DLCSRBH24AAK | EA*4X24L14A* | *92ESN0601714A* | 15,700 | $785 |
| No | 207099442 | DAY & NIGHT | DLCSRBH24AAK | EA*4X24L14A* | *95ESN0261410A* | 15,800 | $790 |
| No | 207099432 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X24L17** | *92ESN0801716A* | 15,500 | $775 |
| No | 207099433 | DAY & NIGHT | DLCSRBH24AAK | EA*4X24L17A* | *92ESN0801716A* | 15,700 | $785 |
| No | 207099435 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X30L17** | *92ESN0801716A* | 15,400 | $770 |
| No | 207099436 | DAY & NIGHT | DLCSRBH24AAK | EA*4X36L17A* | *92ESN0801716A* | 15,400 | $770 |
| No | 207099443 | DAY & NIGHT | DLCSRBH24AAK | EA*4X30L14A* | *95ESN0261410A* | 15,500 | $775 |
| No | 207099437 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *92ESN0801716A* | 15,400 | $770 |
| No | 207099439 | DAY & NIGHT | DLCSRBH24AAK | EA*4X30L17A* | *92ESN0801716A* | 15,400 | $770 |
| No | 207099444 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X30L14** | *95ESN0261410A* | 15,500 | $775 |
| No | 207099457 | DAY & NIGHT | DLCSRBH24AAK | EA*4X36L17A* | *95ESN0401712A* | 15,500 | $775 |
| No | 207099460 | DAY & NIGHT | DLCSRBH24AAK | EA*4X30L17A* | *95ESN0401712A* | 15,600 | $780 |
| No | 207099455 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESN0401712A* | 15,600 | $780 |
| No | 207099556 | DAY & NIGHT | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0401410A* | 15,300 | $765 |
| No | 207099458 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESN0401712A* | 15,600 | $780 |
| No | 207099543 | DAY & NIGHT | DLCSRBH24AAK | EA*4X25L17A* | *95ESN0401712A* | 15,200 | $760 |
| No | 207099548 | DAY & NIGHT | DLCSRBH24AAK | EA*4X37L21A* | *95ESN0401712A* | 15,200 | $760 |
| No | 207099550 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X36L21** | *95ESN0401712A* | 15,600 | $780 |
| No | 207099545 | DAY & NIGHT | DLCSRBH24AAK | EA*4X36L21A* | *95ESN0401712A* | 15,500 | $775 |
| No | 207099547 | DAY & NIGHT | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0401712A* | 15,300 | $765 |
| No | 207099463 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X24L14** | *95ESN0601412A* | 15,600 | $780 |
| No | 207099465 | DAY & NIGHT | DLCSRBH24AAK | EA*4X24L14A* | *95ESN0601412A* | 15,800 | $790 |
| No | 207099466 | DAY & NIGHT | DLCSRBH24AAK | EA*4X30L14A* | *95ESN0601412A* | 15,600 | $780 |
| No | 207099531 | DAY & NIGHT | DLCSRBH24AAK | EA*4X24L17A* | *95ESN0601412A* | 15,800 | $790 |
| No | 207099540 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESN0601412A* | 15,500 | $775 |
| No | 207099532 | DAY & NIGHT | DLCSRBH24AAK | EA*4X25L17A* | *95ESN0601412A* | 15,200 | $760 |
| No | 207099468 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X30L14** | *95ESN0601412A* | 15,500 | $775 |
| No | 207099533 | DAY & NIGHT | DLCSRBH24AAK | EA*4X36L17A* | *95ESN0601412A* | 15,500 | $775 |
| No | 207099535 | DAY & NIGHT | DLCSRBH24AAK | EA*4X30L17A* | *95ESN0601412A* | 15,600 | $780 |
| No | 207099537 | DAY & NIGHT | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0601412A* | 15,300 | $765 |
| No | 207099539 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X24L17** | *95ESN0601412A* | 15,600 | $780 |
| No | 207099470 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X24L17** | *95ESN0601714A* | 15,600 | $780 |
| No | 207099542 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESN0601412A* | 15,500 | $775 |
| No | 207099471 | DAY & NIGHT | DLCSRBH24AAK | EA*4X24L17A* | *95ESN0601714A* | 15,800 | $790 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207099473 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESN0601714A* | 15,500 | $775 |
| No | 207099474 | DAY & NIGHT | DLCSRBH24AAK | EA*4X36L17A* | *95ESN0601714A* | 15,400 | $770 |
| No | 207099476 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESN0601714A* | 15,500 | $775 |
| No | 207099477 | DAY & NIGHT | DLCSRBH24AAK | EA*4X30L17A* | *95ESN0601714A* | 15,500 | $775 |
| No | 207099524 | DAY & NIGHT | DLCSRBH24AAK | EA*4X36L21A* | *95ESN0601714A* | 15,400 | $770 |
| No | 207099523 | DAY & NIGHT | DLCSRBH24AAK | EA*4X25L17A* | *95ESN0601714A* | 15,200 | $760 |
| No | 207099526 | DAY & NIGHT | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0601714A* | 15,200 | $760 |
| No | 207099529 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X36L21** | *95ESN0601714A* | 15,500 | $775 |
| No | 207099528 | DAY & NIGHT | DLCSRBH24AAK | EA*4X37L21A* | *95ESN0601714A* | 15,100 | $755 |
| No | 207099400 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X24L17** | *95ESU0401712A* | 15,600 | $780 |
| No | 207099401 | DAY & NIGHT | DLCSRBH24AAK | EA*4X24L17A* | *95ESU0401712A* | 15,700 | $785 |
| No | 207099403 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESU0401712A* | 15,500 | $775 |
| No | 207099404 | DAY & NIGHT | DLCSRBH24AAK | EA*4X36L17A* | *95ESU0401712A* | 15,400 | $770 |
| No | 207099406 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESU0401712A* | 15,500 | $775 |
| No | 207099407 | DAY & NIGHT | DLCSRBH24AAK | EA*4X30L17A* | *95ESU0401712A* | 15,500 | $775 |
| No | 207099483 | DAY & NIGHT | DLCSRBH24AAK | EA*4X30L14A* | *96VTN0401410A* | 15,600 | $780 |
| No | 207099484 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X30L14** | *96VTN0401410A* | 15,600 | $780 |
| No | 207099502 | DAY & NIGHT | DLCSRBH24AAK | EA*4X30L14A* | *96VTN0601412A* | 15,600 | $780 |
| No | 207099503 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X30L14** | *96VTN0601412A* | 15,600 | $780 |
| No | 207099493 | DAY & NIGHT | DLCSRBH24AAK | EA*4X36L17A* | *96VTN0401712A* | 15,500 | $775 |
| No | 207099505 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X24L17** | *96VTN0601714A* | 15,600 | $780 |
| No | 207099506 | DAY & NIGHT | DLCSRBH24AAK | EA*4X24L17A* | *96VTN0601714A* | 15,800 | $790 |
| No | 207099510 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *96VTN0601714A* | 15,500 | $775 |
| No | 207099509 | DAY & NIGHT | DLCSRBH24AAK | EA*4X36L17A* | *96VTN0601714A* | 15,400 | $770 |
| No | 207099507 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X30L17** | *96VTN0601714A* | 15,500 | $775 |
| No | 207099512 | DAY & NIGHT | DLCSRBH24AAK | EA*4X30L17A* | *96VTN0601714A* | 15,500 | $775 |
| No | 207099514 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X24L17** | *96VTN0801716A* | 15,600 | $780 |
| No | 207099515 | DAY & NIGHT | DLCSRBH24AAK | EA*4X24L17A* | *96VTN0801716A* | 15,700 | $785 |
| No | 207099519 | DAY & NIGHT | DLCSRBH24AAK | EA*4X36L17A* | *96VTN0801716A* | 15,400 | $770 |
| No | 207099517 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D)4X30L17** | *96VTN0801716A* | 15,500 | $775 |
| No | 207099521 | DAY & NIGHT | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *96VTN0801716A* | 15,500 | $775 |
| No | 207099522 | DAY & NIGHT | DLCSRBH24AAK | EA*4X30L17A* | *96VTN0801716A* | 15,500 | $775 |
| No | 207099359 | DAY & NIGHT | DLCSRBH24AAK | FMA4X24**AL* | | 16,000 | $800 |
| No | 207099356 | DAY & NIGHT | DLCSRBH24AAK | FXM4X24**AL | | 15,500 | $775 |
| No | 207199162 | DAY & NIGHT | DLCSRBH30AAK | EN(A,D)4X30L17** | *80ES(N,L)0451712A* | 19,100 | $955 |
| No | 207199163 | DAY & NIGHT | DLCSRBH30AAK | EA*4X30L14A* | *80ES(N,L)0701412A* | 19,100 | $955 |
| No | 207099361 | DAY & NIGHT | DLCSRBH24AAK | FM(C,U)4Z24**AL* | | 16,100 | $805 |
| No | 207199159 | DAY & NIGHT | DLCSRBH30AAK | EA*4X30L14A* | *80ES(N,L)0451412A* | 19,200 | $960 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207199161 | DAY & NIGHT | DLCSRBH30AAK | EA*4X30L17A* | *80ES(N,L)0451712A* | 19,100 | $955 |
| No | 207199160 | DAY & NIGHT | DLCSRBH30AAK | EN(A,D)4X30L14** | *80ES(N,L)0451412A* | 19,200 | $960 |
| No | 207199166 | DAY & NIGHT | DLCSRBH30AAK | EN(A,D)4X30L17** | *80ES(N,L)0701716A* | 19,300 | $965 |
| No | 207199165 | DAY & NIGHT | DLCSRBH30AAK | EA*4X30L17A* | *80ES(N,L)0701716A* | 19,300 | $965 |
| No | 207199169 | DAY & NIGHT | DLCSRBH30AAK | EN(A,D)4X36L21** | *80ES(N,L)0902116A* | 19,300 | $965 |
| No | 207199164 | DAY & NIGHT | DLCSRBH30AAK | EN(A,D)4X30L14** | *80ES(N,L)0701412A* | 19,100 | $955 |
| No | 207199167 | DAY & NIGHT | DLCSRBH30AAK | EA*4X36L21A* | *80ES(N,L)0702116A* | 19,000 | $950 |
| No | 207199168 | DAY & NIGHT | DLCSRBH30AAK | EN(A,D)4X36L21** | *80ES(N,L)0702116A* | 19,100 | $955 |
| No | 207199170 | DAY & NIGHT | DLCSRBH30AAK | EA*4X30L17A* | *80ESU0401712A* | 19,000 | $950 |
| No | 207199171 | DAY & NIGHT | DLCSRBH30AAK | EN(A,D)4X30L17** | *80ESU0401712A* | 19,000 | $950 |
| No | 207199172 | DAY & NIGHT | DLCSRBH30AAK | EA*4X30L14A* | *92ESN0601412A* | 19,200 | $960 |
| No | 207199173 | DAY & NIGHT | DLCSRBH30AAK | EN(A,D)4X30L14** | *92ESN0601412A* | 19,200 | $960 |
| No | 207199176 | DAY & NIGHT | DLCSRBH30AAK | EA*4X30L17A* | *92ESN0801716A* | 19,100 | $955 |
| No | 207199175 | DAY & NIGHT | DLCSRBH30AAK | EN(A,D)4X30L17** | *92ESN0601714A* | 19,100 | $955 |
| No | 207199174 | DAY & NIGHT | DLCSRBH30AAK | EA*4X30L17A* | *92ESN0601714A* | 19,100 | $955 |
| No | 207199177 | DAY & NIGHT | DLCSRBH30AAK | EN(A,D)4X30L17** | *92ESN0801716A* | 19,100 | $955 |
| No | 207199194 | DAY & NIGHT | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0401410A* | 19,100 | $955 |
| No | 207199195 | DAY & NIGHT | DLCSRBH30AAK | END4X42L17** | *95ESN0401410A* | 19,200 | $960 |
| No | 207199198 | DAY & NIGHT | DLCSRBH30AAK | EA*4X36L17A* | *95ESN0401712A* | 19,300 | $965 |
| No | 207199196 | DAY & NIGHT | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0401712A* | 19,300 | $965 |
| No | 207199197 | DAY & NIGHT | DLCSRBH30AAK | EA*4X36L21A* | *95ESN0401712A* | 19,300 | $965 |
| No | 207199199 | DAY & NIGHT | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0401712A* | 19,000 | $950 |
| No | 207199201 | DAY & NIGHT | DLCSRBH30AAK | EA*4X43L21A* | *95ESN0401712A* | 18,700 | $935 |
| No | 207199200 | DAY & NIGHT | DLCSRBH30AAK | EA*4X42L21A* | *95ESN0401712A* | 19,200 | $960 |
| No | 207199203 | DAY & NIGHT | DLCSRBH30AAK | EA*4X30L14A* | *95ESN0601412A* | 19,300 | $965 |
| No | 207199204 | DAY & NIGHT | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0601412A* | 19,300 | $965 |
| No | 207199202 | DAY & NIGHT | DLCSRBH30AAK | END4X42L17** | *95ESN0401712A* | 19,100 | $955 |
| No | 207199206 | DAY & NIGHT | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0601412A* | 19,000 | $950 |
| No | 207199207 | DAY & NIGHT | DLCSRBH30AAK | EN(A,D)4X30L14** | *95ESN0601412A* | 19,300 | $965 |
| No | 207199205 | DAY & NIGHT | DLCSRBH30AAK | EA*4X36L17A* | *95ESN0601412A* | 19,200 | $960 |
| No | 207199208 | DAY & NIGHT | DLCSRBH30AAK | EN(A,D,W)4X36L17** | *95ESN0601412A* | 19,300 | $965 |
| No | 207199209 | DAY & NIGHT | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESN0601412A* | 19,300 | $965 |
| No | 207199215 | DAY & NIGHT | DLCSRBH30AAK | EA*4X42L21A* | *95ESN0601714A* | 19,100 | $955 |
| No | 207199211 | DAY & NIGHT | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0601714A* | 19,300 | $965 |
| No | 207199210 | DAY & NIGHT | DLCSRBH30AAK | END4X42L17** | *95ESN0601412A* | 19,100 | $955 |
| No | 207199213 | DAY & NIGHT | DLCSRBH30AAK | EA*4X36L21A* | *95ESN0601714A* | 19,200 | $960 |
| No | 207199212 | DAY & NIGHT | DLCSRBH30AAK | EA*4X36L17A* | *95ESN0601714A* | 19,200 | $960 |
| No | 207199214 | DAY & NIGHT | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0601714A* | 19,000 | $950 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207199217 | DAY & NIGHT | DLCSRBH30AAK | EA*4X43L21A* | *95ESN0601714A* | 18,700 | $935 |
| No | 207199216 | DAY & NIGHT | DLCSRBH30AAK | EA*4X37L21A* | *95ESN0601714A* | 18,700 | $935 |
| No | 207199219 | DAY & NIGHT | DLCSRBH30AAK | EN(A,D)4X36L21** | *95ESN0601714A* | 19,200 | $960 |
| No | 207199218 | DAY & NIGHT | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESN0601714A* | 19,200 | $960 |
| No | 207199181 | DAY & NIGHT | DLCSRBH30AAK | EA*4X30L17A* | *95ESU0401712A* | 19,000 | $950 |
| No | 207199220 | DAY & NIGHT | DLCSRBH30AAK | EN(A,D,W)4X36L17** | *95ESN0601714A* | 19,200 | $960 |
| No | 207199178 | DAY & NIGHT | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0801716A* | 19,300 | $965 |
| No | 207199221 | DAY & NIGHT | DLCSRBH30AAK | END4X42L17** | *95ESN0601714A* | 19,000 | $950 |
| No | 207199222 | DAY & NIGHT | DLCSRBH30AAK | EN(A,D,W)4X42L21** | *95ESN0601714A* | 19,100 | $955 |
| No | 207199180 | DAY & NIGHT | DLCSRBH30AAK | EA*4X36L21A* | *95ESN0802120A* | 19,100 | $955 |
| No | 207199179 | DAY & NIGHT | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESN0801716A* | 19,300 | $965 |
| No | 207199183 | DAY & NIGHT | DLCSRBH30AAK | EA*4X30L17A* | *96VTN0401712A* | 19,300 | $965 |
| No | 207199182 | DAY & NIGHT | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESU0401712A* | 19,000 | $950 |
| No | 207199184 | DAY & NIGHT | DLCSRBH30AAK | EN(A,D)4X30L14** | *96VTN0601412A* | 19,300 | $965 |
| No | 207199186 | DAY & NIGHT | DLCSRBH30AAK | EN(A,D)4X30L17** | *96VTN0601714A* | 19,100 | $955 |
| No | 207199185 | DAY & NIGHT | DLCSRBH30AAK | EA*4X30L17A* | *96VTN0601714A* | 19,100 | $955 |
| No | 207199187 | DAY & NIGHT | DLCSRBH30AAK | EA*4X30L17A* | *96VTN0801716A* | 19,100 | $955 |
| No | 207199189 | DAY & NIGHT | DLCSRBH30AAK | EA*4X36L21A* | *96VTN0802120A* | 18,800 | $940 |
| No | 207199188 | DAY & NIGHT | DLCSRBH30AAK | EN(A,D)4X30L17** | *96VTN0801716A* | 19,100 | $955 |
| No | 207199191 | DAY & NIGHT | DLCSRBH30AAK | EA*4X36L21A* | *96VTN1002120A* | 18,800 | $940 |
| No | 207199190 | DAY & NIGHT | DLCSRBH30AAK | EN(A,D)4X36L21** | *96VTN0802120A* | 19,000 | $950 |
| No | 207200401 | DAY & NIGHT | DLCSRBH30AAK | EN(A,D)4X36L21** | *96VTN1002120A* | 20,800 | $1,040 |
| No | 207199157 | DAY & NIGHT | DLCSRBH30AAK | FXM4X30**AL | | 18,800 | $940 |
| No | 207199156 | DAY & NIGHT | DLCSRBH30AAK | FMA4X30**AL* | | 19,400 | $970 |
| No | 207198928 | DAY & NIGHT | DLCSRBH30AAK | FVM4X36***L | | 19,200 | $960 |
| No | 207199158 | DAY & NIGHT | DLCSRBH30AAK | FM(C,U)4Z30**AL* | | 19,200 | $960 |
| No | 207199154 | DAY & NIGHT | DLCSRBH30AAK | FEM4P30**AL | | 19,100 | $955 |
| No | 207199155 | DAY & NIGHT | DLCSRBH30AAK | FEM4X30**BL | | 19,100 | $955 |
| No | 206188298 | DAY & NIGHT | DLCLRBH36AAK | DLFLDAH36XAK | | 27,000 | $1,350 |
| No | 207643048 | DAY & NIGHT | DLCMRBH48EAK | Heat pump with ducts | | 30,400 | $1,520 |
| No | 207643033 | DAY & NIGHT | DLCMHBH24CAK | Heat pump with ducts | | 18,500 | $925 |
| No | 207643030 | DAY & NIGHT | DLCMRBH18BAK | Heat pump with ducts | | 11,800 | $590 |
| No | 207643034 | DAY & NIGHT | DLCMHBH24CAK | Combination heat pumps with or without ducts | | 15,900 | $795 |
| No | 207643031 | DAY & NIGHT | DLCMRBH18BAK | Combination heat pumps with or without ducts | | 11,800 | $590 |
| No | 207643032 | DAY & NIGHT | DLCMHBH24CAK | Heat pump without ducts | | 13,300 | $665 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207643049 | DAY & NIGHT | DLCMRBH48EAK | Combination heat pumps with or without ducts | | 30,600 | $1,530 |
| No | 207643029 | DAY & NIGHT | DLCMRBH18BAK | Heat pump without ducts | | 11,800 | $590 |
| No | 207643039 | DAY & NIGHT | DLCMRBH36DAK | Heat pump without ducts | | 24,000 | $1,200 |
| No | 206350404 | DAY & NIGHT | DLCSRBH09AAK | DLFSCAH09XAK | | 6,100 | $305 |
| No | 206350405 | DAY & NIGHT | DLCSRBH09AAK | DLFSDAH09XAK | | 6,400 | $320 |
| No | 206396088 | DAY & NIGHT | DLCSRBH12AAK | DLFSHAH12XAK | | 7,500 | $375 |
| No | 206361880 | DAY & NIGHT | DLCSRBH12AAK | DLFSHBH12XAK | | 7,300 | $365 |
| No | 206350407 | DAY & NIGHT | DLCSRBH12AAK | DLFSDAH12XAK | | 8,300 | $415 |
| No | 206396089 | DAY & NIGHT | DLCSRAH12AAK | DLFSHBH12XAK | | 7,500 | $375 |
| No | 206396092 | DAY & NIGHT | DLCSRAH24AAK | DLFSHBH24XAK | | 15,000 | $750 |
| No | 206361882 | DAY & NIGHT | DLCSRBH24AAK | DLFSHBH24XAK | | 17,000 | $850 |
| No | 206361878 | DAY & NIGHT | DLCSRBH12AAJ | DLFSHBH12XAJ | | 8,200 | $410 |
| No | 206396093 | DAY & NIGHT | DLCSRBH24AAK | DLFSHAH24XAK | | 15,000 | $750 |
| No | 206350406 | DAY & NIGHT | DLCSRBH12AAK | DLFSCAH12XAK | | 7,900 | $395 |
| No | 206361881 | DAY & NIGHT | DLCSRBH18AAK | DLFSHBH18XAK | | 11,100 | $555 |
| No | 206361879 | DAY & NIGHT | DLCSRBH09AAK | DLFSHBH09XAK | | 7,400 | $370 |
| No | 206350408 | DAY & NIGHT | DLCSRBH12AAK | DLFSFAH12XAK | | 8,400 | $420 |
| No | 205767346 | DAY & NIGHT | DLCLRBH36AAK | DLFLAAH36XAK | | 25,000 | $1,250 |
| No | 205767347 | DAY & NIGHT | DLCLRBH48AAK | DLFLAAH48XAK | | 36,000 | $1,800 |
| No | 201835616 | DAY & NIGHT | DLCSRAH36AAK | DLFSHAH36XAK | | 20,600 | $1,030 |
| No | 202463646 | DAY & NIGHT | DLCPRAH18AAK | DLFPHAH18XAK | | 12,300 | $615 |
| No | 201835623 | DAY & NIGHT | DLCMRAH48EAK | Heat pump without ducts | | 30,400 | $1,520 |
| No | 201835622 | DAY & NIGHT | DLCMRAH36DAK | Heat pump without ducts | | 23,600 | $1,180 |
| No | 201835610 | DAY & NIGHT | DLCSRAH12AAJ | DLFSHAH12XAJ | | 7,100 | $355 |
| No | 201835603 | DAY & NIGHT | DLCPRAH12AAK | DLFPHAH12XAK | | 6,800 | $340 |
| No | 201835602 | DAY & NIGHT | DLCPRAH09AAK | DLFPHAH09XAK | | 7,200 | $360 |
| No | 201835611 | DAY & NIGHT | DLCSRAH09AAK | DLFSHAH09XAK | | 7,500 | $375 |
| No | 201835619 | DAY & NIGHT | DLCLRAH58AAK | DLFLDAH58XAK | | 37,600 | $1,880 |
| No | 201835613 | DAY & NIGHT | DLCSRAH18AAK | DLFSHAH18XAK | | 11,900 | $595 |
| No | 201835612 | DAY & NIGHT | DLCSRAH12AAK | DLFSHAH12XAK | | 7,600 | $380 |
| No | 201835642 | DAY & NIGHT | DLCLRAH48AAK | DLFLCAH48XAK | | 35,000 | $1,750 |
| No | 201835643 | DAY & NIGHT | DLCLRAH58AAK | DLFLFAH58XAK | | 39,000 | $1,950 |
| No | 201835618 | DAY & NIGHT | DLCLRAH48AAK | DLFLDAH48XAK | | 33,400 | $1,670 |
| No | 201835617 | DAY & NIGHT | DLCLRAH36AAK | DLFLDAH36XAK | | 27,600 | $1,380 |
| No | 201835632 | DAY & NIGHT | DLCSRAH12AAK | DLFSDAH12XAK | | 8,100 | $405 |
| No | 201835631 | DAY & NIGHT | DLCSRAH12AAK | DLFSFAH12XAK | | 9,600 | $480 |
| No | 201835639 | DAY & NIGHT | DLCLRAH36AAK | DLFLCAH36XAK | | 25,200 | $1,260 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201835629 | DAY & NIGHT | DLCSRAH09AAK | DLFSCAH09XAK | | 6,700 | $335 |
| No | 201835633 | DAY & NIGHT | DLCSRAH18AAK | DLFSFAH18XAK | | 12,900 | $645 |
| No | 201835630 | DAY & NIGHT | DLCSRAH12AAK | DLFSCAH12XAK | | 8,200 | $410 |
| No | 201835638 | DAY & NIGHT | DLCLRAH36AAK | DLFLFAH36XAK | | 25,400 | $1,270 |
| No | 201835628 | DAY & NIGHT | DLCSRAH09AAK | DLFSDAH09XAK | | 6,800 | $340 |
| No | 207643197 | DELTA | 37HL018J24(3C) | 27WL018J24 | | 11,500 | $575 |
| No | 207658988 | DELTA | 37HL009J24(3C) | 27WL009J24 | | 6,900 | $345 |
| No | 205300163 | DENALI AIRE | DNMSHQCO9A | DNMSHQCW9A | | 5,000 | $250 |
| No | 205300165 | DENALI AIRE | DNMSHQCO24 | DNMSHQCW24 | | 14,500 | $725 |
| No | 205300164 | DENALI AIRE | DNMSHQCO18 | DNMSHQCW18 | | 11,600 | $580 |
| No | 205300162 | DENALI AIRE | DNMSHQCO12A | DNMSHQCW12A | | 7,500 | $375 |
| No | 210365427 | Dettson | MHD-18 | MHD-CC2.0-17.5-M | | 13,000 | $650 |
| No | 210365434 | Dettson | EVD-36-O | EVD-36-I | | 30,400 | $1,520 |
| No | 210365433 | Dettson | EVD-30-O | EVD-30-I | | 21,000 | $1,050 |
| No | 210857286 | DIAMONDAIR | DF55M2Z5 | Heat pump without ducts | | 36,400 | $1,820 |
| No | 210857283 | DIAMONDAIR | DF36M2Z4 | Heat pump without ducts | | 26,400 | $1,320 |
| No | 210857280 | DIAMONDAIR | DF30M2Z3 | Heat pump without ducts | | 20,000 | $1,000 |
| No | 210857281 | DIAMONDAIR | DF30M2Z3 | Heat pump with ducts | | 22,000 | $1,100 |
| No | 210857278 | DIAMONDAIR | DF18M2Z2 | Heat pump with ducts | | 14,800 | $740 |
| No | 210857277 | DIAMONDAIR | DF18M2Z2 | Heat pump without ducts | | 14,400 | $720 |
| No | 210857267 | DIAMONDAIR | D2018SHO2 | DF2018HMSI2 | | 11,100 | $555 |
| No | 210857266 | DIAMONDAIR | D2012SHO2 | DF2012HMSI2 | | 10,300 | $515 |
| No | 210857265 | DIAMONDAIR | D2009SHO2 | DF2009HMSI2 | | 9,300 | $465 |
| No | 210857271 | DIAMONDAIR | D2018SHO2 | DF2018CI | | 15,600 | $780 |
| No | 210857270 | DIAMONDAIR | D2012SHO2 | DF2012CI | | 9,900 | $495 |
| No | 210857269 | DIAMONDAIR | D2009SHO2 | DF2009CI | | 9,000 | $450 |
| No | 212388352 | DIRECT AIR | DIRM-48MAGICPRO20-OU | DIRM-48MAGICPRO20-COIL | | 32,000 | $1,600 |
| No | 212388351 | DIRECT AIR | DIRM-36MAGICPRO20-OU | DIRM-36MAGICPRO20-COIL | | 33,000 | $1,650 |
| No | 212101619 | DIRECT AIR | DIRM-24MAGICPRO20-OU | DIRM-24MAGICPRO20-COIL | | 21,000 | $1,050 |
| No | 212101621 | DIRECT AIR | DIRM-18MAGICPRO20-OU | DIRM-24MAGICPRO20-COIL | | 14,700 | $735 |
| No | 207706566 | DIRECT AIR | DIRM-36MAGICPRO20-OU | DIRM-36MAGICPRO20-AH | | 30,400 | $1,520 |
| No | 207706565 | DIRECT AIR | DIRM-30MAGICPRO20-OU | DIRM-30MAGICPRO20-AH | | 21,000 | $1,050 |
| No | 207743782 | DIRECT AIR | DIRM-48DA25-5Z | Heat pump without ducts | | 34,000 | $1,700 |
| No | 207743779 | DIRECT AIR | DIRM-36DA25-4Z | Heat pump without ducts | | 26,800 | $1,340 |
| No | 207743777 | DIRECT AIR | DIRM-27DA25-3Z | Heat pump with ducts | | 22,000 | $1,100 |
| No | 207743774 | DIRECT AIR | DIRM-18DA25-2Z | Heat pump with ducts | | 14,800 | $740 |
| No | 207743776 | DIRECT AIR | DIRM-27DA25-3Z | Heat pump without ducts | | 21,000 | $1,050 |
| No | 207743773 | DIRECT AIR | DIRM-18DA25-2Z | Heat pump without ducts | | 14,300 | $715 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207743756 | DIRECT AIR | DIRM-18DA25-1Z | DIRM-18HP-DUV | | 12,600 | $630 |
| No | 207743755 | DIRECT AIR | DIRM-18DA25-1Z | DIRM-18HP-DUH | | 12,600 | $630 |
| No | 207743741 | DIRECT AIR | DIRM-18DA25-1Z | DIRM-18HP-CA | | 12,000 | $600 |
| No | 207743730 | DIRECT AIR | DIRM-18DA25-1Z | DIRM-18HP-CF | | 12,800 | $640 |
| No | 207743721 | DIRECT AIR | DIRM-18DA25-1Z | DIRM-18HP-WM | | 14,900 | $745 |
| No | 207743743 | DIRECT AIR | DIRM-24DA25-1Z | DIRM-24HP-CA | | 19,000 | $950 |
| No | 207743762 | DIRECT AIR | DIRM-48LCDA25-1Z | DIRM-48HP-DU | | 34,000 | $1,700 |
| No | 207743746 | DIRECT AIR | DIRM-48LCDA25-1Z | DIRM-48HP-CA | | 30,000 | $1,500 |
| No | 207743735 | DIRECT AIR | DIRM-48LCDA25-1Z | DIRM-48HP-CF | | 29,000 | $1,450 |
| No | 207743761 | DIRECT AIR | DIRM-36LCDA25-1Z | DIRM-36HP-DU | | 25,000 | $1,250 |
| No | 207743745 | DIRECT AIR | DIRM-36LCDA25-1Z | DIRM-36HP-CA | | 23,000 | $1,150 |
| No | 207743734 | DIRECT AIR | DIRM-36LCDA25-1Z | DIRM-36HP-CF | | 23,000 | $1,150 |
| No | 207743723 | DIRECT AIR | DIRM-06HXPRO28-1Z | DIRM-06HP-WM | | 8,500 | $425 |
| No | 207743722 | DIRECT AIR | DIRM-24DA25-1Z | DIRM-24HP-WM | | 16,200 | $810 |
| No | 207743720 | DIRECT AIR | DIRM-12DA25-1Z | DIRM-12HP-WM | | 9,000 | $450 |
| No | 207743719 | DIRECT AIR | DIRM-09DA25-1Z | DIRM-09HP-WM | | 8,500 | $425 |
| No | 207743759 | DIRECT AIR | DIRM-24DA25-1Z | DIRM-24HP-DU | | 20,000 | $1,000 |
| No | 206377759 | DIRECT AIR | MOX430-17HFN1-MT0W | CCA3U-18HRFN1-M(C) | | 15,600 | $780 |
| No | 207743742 | DIRECT AIR | DIRM-18HXPRO28-1Z | DIRM-18HP-CA | | 15,600 | $780 |
| No | 207743731 | DIRECT AIR | DIRM-18HXPRO28-1Z | DIRM-18HP-CF | | 12,000 | $600 |
| No | 206377758 | DIRECT AIR | MOX430-17HFN1-MT0W | MUEU-18HRFN1-M(C) | | 12,000 | $600 |
| No | 207743765 | DIRECT AIR | DIRM-12HXPRO28-1Z | DIRM-12HP-CO | | 9,600 | $480 |
| No | 207743754 | DIRECT AIR | DIRM-12HXPRO28-1Z | DIRM-12HP-DUV | | 10,600 | $530 |
| No | 207743753 | DIRECT AIR | DIRM-12HXPRO28-1Z | DIRM-12HP-DUH | | 10,600 | $530 |
| No | 207743740 | DIRECT AIR | DIRM-12HXPRO28-1Z | DIRM-12HP-CA | | 9,900 | $495 |
| No | 207743764 | DIRECT AIR | DIRM-12DA25-1Z | DIRM-12HP-CO | | 9,000 | $450 |
| No | 207743752 | DIRECT AIR | DIRM-12DA25-1Z | DIRM-12HP-DUV | | 9,300 | $465 |
| No | 207743751 | DIRECT AIR | DIRM-12DA25-1Z | DIRM-12HP-DUH | | 9,300 | $465 |
| No | 207743750 | DIRECT AIR | DIRM-09HXPRO28-1Z | DIRM-09HP-DUV | | 10,100 | $505 |
| No | 207743749 | DIRECT AIR | DIRM-09HXPRO28-1Z | DIRM-09HP-DUH | | 10,100 | $505 |
| No | 207743738 | DIRECT AIR | DIRM-09HXPRO28-1Z | DIRM-09HP-CA | | 9,000 | $450 |
| No | 207743748 | DIRECT AIR | DIRM-09DA25-1Z | DIRM-09HP-DUV | | 7,700 | $385 |
| No | 207743747 | DIRECT AIR | DIRM-09DA25-1Z | DIRM-09HP-DUH | | 7,700 | $385 |
| No | 207743732 | DIRECT AIR | DIRM-24DA25-1Z | DIRM-24HP-CF | | 16,000 | $800 |
| No | 207743739 | DIRECT AIR | DIRM-12DA25-1Z | DIRM-12HP-CA | | 8,900 | $445 |
| No | 207743737 | DIRECT AIR | DIRM-09DA25-1Z | DIRM-09HP-CA | | 7,500 | $375 |
| No | 207743725 | DIRECT AIR | DIRM-12HXPRO28-1Z | DIRM-12HP-WM | | 10,000 | $500 |
| No | 207743724 | DIRECT AIR | DIRM-09HXPRO28-1Z | DIRM-09HP-WM | | 9,500 | $475 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207583107 | DIRECT AIR | DIRH-12HP23-DKO | DIRH-12HP23-DKI | | 7,500 | $375 |
| No | 207583108 | DIRECT AIR | DIRH-18HP23-DKO | DIRH-18HP23-DKI | | 11,600 | $580 |
| No | 8775829 | DIRECT AIR | MOD30-24HFN1-MT0W | CS11M-23HRFN1-MT0W | | 15,400 | $770 |
| No | 8775845 | DIRECT AIR | MOB30-12HFN1-MT0W | CCA3U-12HRFN1-M(C) | | 7,500 | $375 |
| No | 8994011 | DIRECT AIR | M2OF-18HFN1-M | Heat pump without ducts | | 12,000 | $600 |
| No | 8994012 | DIRECT AIR | M3OF-27HFN1-M | Heat pump without ducts | | 17,200 | $860 |
| No | 8994014 | DIRECT AIR | M5OF-48HFN1-M | Heat pump without ducts | | 29,600 | $1,480 |
| No | 9104551 | DIRECT AIR | MOCA31-18HFN1-MT0W | MSAED-18HRFN1-MT0W | | 11,100 | $555 |
| No | 9104550 | DIRECT AIR | MOD31-24HFN1-MT0W | MSAED-23HRFN1-MT0W | | 16,000 | $800 |
| No | 9680947 | DIRECT AIR | MOBA30-09HFN1-MT0W | CS11M-09HRFN1-MX0W(A) | | 5,800 | $290 |
| No | 203269784 | DIRECT AIR | M4OH-36HFN1-M | Heat pump without ducts | | 23,200 | $1,160 |
| No | 203269787 | DIRECT AIR | M4OH-36HFN1-M | Heat pump with ducts | | 24,600 | $1,230 |
| No | 8952870 | DIRECT AIR | MOB30-12HFN1-MV0W | CS11M-12HRFN1-MU5W | | 7,800 | $390 |
| No | 205816491 | DIRECT AIR | MOX430-17HFN1-MT0W | CS11M-18HRFN1-MT0W | | 10,900 | $545 |
| No | 207743783 | DIRECT AIR | DIRM-48DA25-5Z | Heat pump with ducts | | 30,400 | $1,520 |
| No | 207743784 | DIRECT AIR | DIRM-48DA25-5Z | Combination heat pumps with or without ducts | | 30,000 | $1,500 |
| No | 207743787 | DIRECT AIR | DIRM-18HXPRO28-2Z | Combination heat pumps with or without ducts | | 11,500 | $575 |
| No | 207743778 | DIRECT AIR | DIRM-27DA25-3Z | Combination heat pumps with or without ducts | | 16,000 | $800 |
| No | 207743775 | DIRECT AIR | DIRM-18DA25-2Z | Combination heat pumps with or without ducts | | 11,400 | $570 |
| No | 207743790 | DIRECT AIR | DIRM-28HXPRO28-3Z | Combination heat pumps with or without ducts | | 17,000 | $850 |
| No | 207743736 | DIRECT AIR | DIRM-60LCDA25-1Z | DIRM-60HP-CF | | 35,000 | $1,750 |
| No | 207743763 | DIRECT AIR | DIRM-60LCDA25-1Z | DIRM-60HP-DU | | 37,000 | $1,850 |
| No | 9680948 | DIRECT AIR | MOB30-12HFN1-MT0W | CS11M-12HRFN1-MU5W | | 7,700 | $385 |
| No | 9680950 | DIRECT AIR | MOD31-24HFN1-MT0W | CS11M-23HRFN1-MT0W | | 15,300 | $765 |
| No | 9680949 | DIRECT AIR | MOCA31-18HFN1-MT0W | CS11M-18HRFN1-MT0W | | 11,400 | $570 |
| No | 8989603 | DIRECT AIR | MOBA30-09HFN1-MT0W | MSAEB-09HRFN1-MT0W | | 6,300 | $315 |
| No | 8952869 | DIRECT AIR | MOB30-09HFN1-MX0W | CS11M-09HRFN1-MX0W(A) | | 6,900 | $345 |
| No | 8775853 | DIRECT AIR | MOD31-24HFN1-MT0W | MUEU-24HRFN1-M(C) | | 15,000 | $750 |
| No | 8775852 | DIRECT AIR | MOD31-24HFN1-MT0W | MCDU-24HRFN1-M(C) | | 15,800 | $790 |
| No | 8775850 | DIRECT AIR | MOCA31-18HFN1-MT0W | MUEU-18HRFN1-M(C) | | 12,000 | $600 |
| No | 8775849 | DIRECT AIR | MOCA31-18HFN1-MT0W | CCA3U-18HRFN1-M(C) | | 12,000 | $600 |
| No | 8775842 | DIRECT AIR | MOBA30-09HFN1-MT0W | CCA3U-09HRFN1-M(C) | | 5,800 | $290 |
| No | 212394327 | DIYCOOL | ACIQ-18-EHPB | ACIQ-18-ACL | | 13,000 | $650 |
| No | 212394337 | DIYCOOL | ACIQ-48-HPB | ACIQ-48-ACL | | 32,000 | $1,600 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 212394336 | DIYCOOL | ACIQ-36-HPB | ACIQ-36-ACL | | 33,000 | $1,650 |
| No | 212394331 | DIYCOOL | ACIQ-48-EHPB | ACIQ-48-ACL | | 30,400 | $1,520 |
| No | 212394330 | DIYCOOL | ACIQ-36-EHPB | ACIQ-36-ACL | | 19,800 | $990 |
| No | 212394334 | DIYCOOL | ACIQ-24-HPB | ACIQ-24-ACL | | 21,000 | $1,050 |
| No | 212394333 | DIYCOOL | ACIQ-18-HPB | ACIQ-18-ACL | | 14,700 | $735 |
| No | 212394332 | DIYCOOL | ACIQ-60-EHPB | ACIQ-60-ACL | | 34,000 | $1,700 |
| No | 212394329 | DIYCOOL | ACIQ-30-EHPB | ACIQ-30-ACL | | 22,000 | $1,100 |
| No | 212394328 | DIYCOOL | ACIQ-24-EHPB | ACIQ-24-ACL | | 22,000 | $1,100 |
| No | 208106633 | DIYCOOL | ACIQ-36-HPB | ACIQ-36-AHB | | 30,400 | $1,520 |
| No | 210857347 | DIYCOOL | ACIQ-06ZPL-HP230B | SCC-0609-HH-M | | 5,700 | $285 |
| No | 210857349 | DIYCOOL | ACIQ-12ZPL-HP230B | SCC-1218-HH-M | | 9,500 | $475 |
| No | 210857348 | DIYCOOL | ACIQ-09ZPL-HP230B | SCC-0609-HH-M | | 9,800 | $490 |
| No | 210857413 | DIYCOOL | ES-55Z-M5B | Heat pump without ducts | | 34,400 | $1,720 |
| No | 210857410 | DIYCOOL | ES-48Z-M5B | Heat pump without ducts | | 34,000 | $1,700 |
| No | 210857407 | DIYCOOL | ES-36Z-M4B | Heat pump without ducts | | 26,800 | $1,340 |
| No | 210857405 | DIYCOOL | ES-27Z-M3B | Heat pump with ducts | | 22,000 | $1,100 |
| No | 210857402 | DIYCOOL | ES-18Z-M2B | Heat pump with ducts | | 14,800 | $740 |
| No | 210857404 | DIYCOOL | ES-27Z-M3B | Heat pump without ducts | | 21,000 | $1,050 |
| No | 210857401 | DIYCOOL | ES-18Z-M2B | Heat pump without ducts | | 14,300 | $715 |
| No | 210857352 | DIYCOOL | ACIQ-18ZPL-HP230B | ACIQ-18FM-HH-MC | | 14,700 | $735 |
| No | 210857351 | DIYCOOL | ACIQ-12ZPL-HP230B | ACIQ-12FM-HH-MC | | 10,200 | $510 |
| No | 207825547 | DIYCOOL | ACIQ-18Z-HP230B | ACIQ-18W-HP230B | | 11,500 | $575 |
| No | 207825545 | DIYCOOL | ACIQ-09Z-HP115B | ACIQ-09W-HP115B | | 6,800 | $340 |
| No | 210857341 | DIYCOOL | ACIQ-36ZPL-HP230B | ACIQ-36CD-HH-MB | | 34,000 | $1,700 |
| No | 210857334 | DIYCOOL | ACIQ-06ZPL-HP230B | ACIQ-06W-HH-MC | | 8,500 | $425 |
| No | 207825549 | DIYCOOL | ACIQ-36Z-HP230B | ACIQ-36W-HP230B | | 24,000 | $1,200 |
| No | 207825556 | DIYCOOL | ACIQ-18ZPL-HP230B | ACIQ-18CC-HH-MB | | 15,600 | $780 |
| No | 207825562 | DIYCOOL | ACIQ-18ZPL-HP230B | ACIQ-18FM-HH-MB | | 12,000 | $600 |
| No | 207825561 | DIYCOOL | ACIQ-12ZPL-HP230B | ACIQ-12FM-HH-MB | | 9,600 | $480 |
| No | 207825558 | DIYCOOL | ACIQ-12ZPL-HP230B | ACIQ-12CD-HH-MB | | 10,600 | $530 |
| No | 207825555 | DIYCOOL | ACIQ-12ZPL-HP230B | ACIQ-12CC-HH-MB | | 9,900 | $495 |
| No | 207825557 | DIYCOOL | ACIQ-09ZPL-HP230B | ACIQ-09CD-HH-MB | | 10,100 | $505 |
| No | 207825554 | DIYCOOL | ACIQ-09ZPL-HP230B | ACIQ-09CC-HH-MB | | 9,000 | $450 |
| No | 207825551 | DIYCOOL | ACIQ-12ZPL-HP230B | ACIQ-12W-HH-MB | | 10,000 | $500 |
| No | 210857336 | DIYCOOL | ACIQ-12ZPL-HP230B | ACIQ-12W-HH-MC | | 10,000 | $500 |
| No | 210857335 | DIYCOOL | ACIQ-09ZPL-HP230B | ACIQ-09W-HH-MC | | 9,500 | $475 |
| No | 207825550 | DIYCOOL | ACIQ-09ZPL-HP230B | ACIQ-09W-HH-MB | | 9,500 | $475 |
| No | 206315624 | DIYCOOL | ACIQ-18Z-HP230 | ACIQ-18W-HP230 | | 11,000 | $550 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206315622 | DIYCOOL | ACIQ-09Z-HP115 | ACIQ-09W-HP115 | | 6,000 | $300 |
| No | 207825590 | DIYCOOL | ACIQ-18Z-HH-M2B | Combination heat pumps with or without ducts | | 11,500 | $575 |
| No | 207825593 | DIYCOOL | ACIQ-27Z-HH-M3B | Combination heat pumps with or without ducts | | 17,000 | $850 |
| No | 206315630 | DIYCOOL | ACIQ-48-HP | ACIQ-48-AH | | 36,000 | $1,800 |
| No | 206315629 | DIYCOOL | ACIQ-36-HP | ACIQ-36-AH | | 25,000 | $1,250 |
| No | 211034592 | DUCANE | 4DHV2S12S-1L | DWH212S4-*L | | 7,800 | $390 |
| No | 211034591 | DUCANE | 4DHV2S09S-1L | DWH209S4-*L | | 6,300 | $315 |
| No | 211034571 | DUCANE | 4DHP2S12S-1L | DWM212S4-*L | | 8,400 | $420 |
| No | 211034596 | DUCANE | 4DHV2S24S-1P | DWH224S4-*P | | 16,500 | $825 |
| No | 211034595 | DUCANE | 4DHV2S18S-1P | DWH218S4-*P | | 11,400 | $570 |
| No | 211034594 | DUCANE | 4DHV2S12S-1P | DWH212S4-*P | | 7,000 | $350 |
| No | 211034593 | DUCANE | 4DHV2S09S-1P | DWH209S4-*P | | 6,000 | $300 |
| No | 211034590 | DUCANE | 4DHP2S48S-1P | D33C248S4-*P | | 30,000 | $1,500 |
| No | 211034589 | DUCANE | 4DHP2S36S-1P | D33C236S4-*P | | 23,000 | $1,150 |
| No | 211034588 | DUCANE | 4DHP2S24S-1P | D33C224S4-*P | | 19,000 | $950 |
| No | 211034587 | DUCANE | 4DHP2S18S-1P | D22C118S4-*P | | 12,000 | $600 |
| No | 211034586 | DUCANE | 4DHP2S12S-1P | D22C112S4-*P | | 8,900 | $445 |
| No | 211034585 | DUCANE | 4DHPS209S-1P | D22C109S4-*P | | 7,500 | $375 |
| No | 211034584 | DUCANE | 4DHP2S48S-1P | DMD248S4-*P | | 34,000 | $1,700 |
| No | 211034583 | DUCANE | 4DHP2S36S-1P | DMD236S4-*P | | 25,000 | $1,250 |
| No | 211034582 | DUCANE | 4DHP2S24S-1P | DMD224S4-*P | | 20,000 | $1,000 |
| No | 211034581 | DUCANE | 4DHP2S18S-1P | DMD218S4-*P | | 12,600 | $630 |
| No | 211034580 | DUCANE | 4DHP2S12S-1P | DMD212S4-*P | | 9,300 | $465 |
| No | 211034579 | DUCANE | 4DHPS209S-1P | DMD209S4-*P | | 7,700 | $385 |
| No | 211034576 | DUCANE | 4DHP2S30S-1P | DWM230S4-*P | | 19,000 | $950 |
| No | 211034575 | DUCANE | 4DHP2S24S-1P | DWM224S4-*P | | 16,200 | $810 |
| No | 211034574 | DUCANE | 4DHP2S18S-1P | DWM218S4-*P | | 14,900 | $745 |
| No | 211034573 | DUCANE | 4DHP2S12S-1P | DWM212S4-*P | | 9,000 | $450 |
| No | 211034572 | DUCANE | 4DHPS209S-1P | DWM209S4-*P | | 8,500 | $425 |
| No | 208106723 | DUCANE | 4DHV2S24S-1P | DWH224S4-1P | | 16,500 | $825 |
| No | 208106722 | DUCANE | 4DHV2S18S-1P | DWH218S4-1P | | 11,400 | $570 |
| No | 208106721 | DUCANE | 4DHV2S12S-1P | DWH212S4-1P | | 7,000 | $350 |
| No | 208106719 | DUCANE | 4DHV2S12S-1L | DWH212S4-1L | | 7,800 | $390 |
| No | 208106720 | DUCANE | 4DHV2S09S-1P | DWH209S4-1P | | 6,000 | $300 |
| No | 208106718 | DUCANE | 4DHV2S09S-1L | DWH209S4-1L | | 6,300 | $315 |
| No | 208106714 | DUCANE | 4DHPS209S-1P | DWM209S4-1P | | 8,500 | $425 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208106851 | DUCANE | 4DHP2S36M-1P | Heat pump without ducts | | 26,800 | $1,340 |
| No | 208106848 | DUCANE | 4DHP2S30M-1P | Heat pump without ducts | | 21,000 | $1,050 |
| No | 208106849 | DUCANE | 4DHP2S30M-1P | Heat pump with ducts | | 22,000 | $1,100 |
| No | 208106665 | DUCANE | 4DHP2S24S-1P | DWM224S4-1P | | 16,200 | $810 |
| No | 208106846 | DUCANE | 4DHP2S24M-1P | Heat pump with ducts | | 21,600 | $1,080 |
| No | 208106845 | DUCANE | 4DHP2S24M-1P | Heat pump without ducts | | 20,400 | $1,020 |
| No | 208106670 | DUCANE | 4DHP2S18S-1P | DMD218S4-1P | | 12,600 | $630 |
| No | 208106664 | DUCANE | 4DHP2S18S-1P | DWM218S4-1P | | 14,900 | $745 |
| No | 208106843 | DUCANE | 4DHP2S18M-1P | Heat pump with ducts | | 14,800 | $740 |
| No | 208106842 | DUCANE | 4DHP2S18M-1P | Heat pump without ducts | | 14,300 | $715 |
| No | 208106669 | DUCANE | 4DHP2S12S-1P | DMD212S4-1P | | 9,300 | $465 |
| No | 208106663 | DUCANE | 4DHP2S12S-1P | DWM212S4-1P | | 9,000 | $450 |
| No | 208106666 | DUCANE | 4DHP2S12S-1P | D22C112S4-1P | | 8,900 | $445 |
| No | 208106713 | DUCANE | 4DHP2S12S-1L | DWM212S4-1L | | 8,400 | $420 |
| No | 206903656 | DUCANE | 4HP18V60P | E*1P50C+H4TXV03 | 96G2UH110CV20 | 39,000 | $1,950 |
| No | 206903655 | DUCANE | 4HP18V60P | E*1P50C+H4TXV03 | 96G2UH090CV20 | 39,500 | $1,975 |
| No | 206903654 | DUCANE | 4HP18V60P | E*1P50C+H4TXV03 | 96G1UH110CE20 | 39,000 | $1,950 |
| No | 206903651 | DUCANE | 4HP18V60P | E*1P50C+H4TXV03 | 92G1UH110CE20 | 39,000 | $1,950 |
| No | 206903650 | DUCANE | 4HP18V60P | E*1P50C+H4TXV03 | 80G2UH110CV20 | 39,000 | $1,950 |
| No | 206903649 | DUCANE | 4HP18V60P | E*1P50C+H4TXV03 | 80G2UH110CE20L | 39,500 | $1,975 |
| No | 206903648 | DUCANE | 4HP18V60P | E*1P50C+H4TXV03 | 80G2UH110CE20 | 39,500 | $1,975 |
| No | 206903647 | DUCANE | 4HP18V60P | E*1P50C+H4TXV03 | 80G1UH110CE20 | 39,500 | $1,975 |
| No | 206903646 | DUCANE | 4HP18V60P | E*1P50C+H4TXV03 | 80G1UH100CE20X | 39,500 | $1,975 |
| No | 206903645 | DUCANE | 4HP18V60P | E*1P50C+H4TXV03 | 80G1UH090CE20 | 39,500 | $1,975 |
| No | 206903721 | DUCANE | 4HP18V60P | ED1P60D+H4TXV03 | EFV20DCA | 38,000 | $1,900 |
| No | 206903701 | DUCANE | 4HP18V60P | EAC4X60D | EFV20DCA | 40,000 | $2,000 |
| No | 206903700 | DUCANE | 4HP18V60P | EAC4X60D | 96G2UH135DV20 | 40,000 | $2,000 |
| No | 206903699 | DUCANE | 4HP18V60P | EAC4X60D | 80G1UH135DE20 | 40,000 | $2,000 |
| No | 206903695 | DUCANE | 4HP18V60P | EAC4X60C | 96G1UH110CE20 | 37,800 | $1,890 |
| No | 206903688 | DUCANE | 4HP18V60P | EAC4X60C | 80G1UH110CE20 | 38,000 | $1,900 |
| No | 206903687 | DUCANE | 4HP18V60P | EAC4X60C | 80G1UH100CE20X | 38,000 | $1,900 |
| No | 206903686 | DUCANE | 4HP18V60P | EAC4X60C | 80G1UH090CE20 | 38,000 | $1,900 |
| No | 206903673 | DUCANE | 4HP18V60P | EA(C,U)1P60D+H4TXV03 | EFV20DCA | 40,000 | $2,000 |
| No | 206903667 | DUCANE | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 96G1UH110CE20 | 37,800 | $1,890 |
| No | 206903660 | DUCANE | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 80G1UH110CE20 | 38,000 | $1,900 |
| No | 206903659 | DUCANE | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 80G1UH100CE20X | 38,000 | $1,900 |
| No | 206903658 | DUCANE | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 80G1UH090CE20 | 38,000 | $1,900 |
| No | 206905166 | DUCANE | 4HP18V60P | ED1P50/60C+H4TXV02 | EFV16CCA | 30,400 | $1,520 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206905141 | DUCANE | 4HP18V60P | EAC4X49C | EFV16CCA | 30,600 | $1,530 |
| No | 206905130 | DUCANE | 4HP18V60P | EAC4X49C | 80G2UH110CE16 | 30,200 | $1,510 |
| No | 206905107 | DUCANE | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | EFV16CCA | 30,600 | $1,530 |
| No | 206905096 | DUCANE | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | 80G2UH110CE16 | 30,200 | $1,510 |
| No | 206903690 | DUCANE | 4HP18V60P | EAC4X60C | 80G2UH110CE20L | 38,000 | $1,900 |
| No | 206903662 | DUCANE | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 80G2UH110CE20L | 38,000 | $1,900 |
| No | 206905147 | DUCANE | 4HP18V60P | EAH1P48C+H4TXV02 | 80G2UH110CE20L | 31,000 | $1,550 |
| No | 206903717 | DUCANE | 4HP18V60P | ED1P60D+H4TXV03 | 80G1DF110CE20 | 38,000 | $1,900 |
| No | 206903720 | DUCANE | 4HP18V60P | ED1P60D+H4TXV03 | 96G2DF110CV20 | 38,500 | $1,925 |
| No | 206903719 | DUCANE | 4HP18V60P | ED1P60D+H4TXV03 | 96G2DF090CV20 | 38,500 | $1,925 |
| No | 206903702 | DUCANE | 4HP18V60P | EAH1P51C+H4TXV03 | 80G1UH090CE20 | 36,800 | $1,840 |
| No | 206903672 | DUCANE | 4HP18V60P | EA(C,U)1P60D+H4TXV03 | 96G2UH135DV20 | 39,000 | $1,950 |
| No | 206903671 | DUCANE | 4HP18V60P | EA(C,U)1P60D+H4TXV03 | 80G1UH135DE20 | 39,000 | $1,950 |
| No | 206903697 | DUCANE | 4HP18V60P | EAC4X60C | 96G2UH110CV20 | 38,000 | $1,900 |
| No | 206903696 | DUCANE | 4HP18V60P | EAC4X60C | 96G2UH090CV20 | 38,000 | $1,900 |
| No | 206903692 | DUCANE | 4HP18V60P | EAC4X60C | 92G1UH110CE20 | 37,800 | $1,890 |
| No | 206903691 | DUCANE | 4HP18V60P | EAC4X60C | 80G2UH110CV20 | 38,000 | $1,900 |
| No | 206903689 | DUCANE | 4HP18V60P | EAC4X60C | 80G2UH110CE20 | 38,000 | $1,900 |
| No | 206903669 | DUCANE | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 96G2UH110CV20 | 38,000 | $1,900 |
| No | 206903668 | DUCANE | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 96G2UH090CV20 | 38,000 | $1,900 |
| No | 206903664 | DUCANE | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 92G1UH110CE20 | 37,800 | $1,890 |
| No | 206903663 | DUCANE | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 80G2UH110CV20 | 38,000 | $1,900 |
| No | 206903661 | DUCANE | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 80G2UH110CE20 | 38,000 | $1,900 |
| No | 206903643 | DUCANE | 4HP18V60P | BCE5V60M | | 38,500 | $1,925 |
| No | 206905140 | DUCANE | 4HP18V60P | EAC4X49C | 96G2UH110CV20 | 30,600 | $1,530 |
| No | 206905139 | DUCANE | 4HP18V60P | EAC4X49C | 96G2UH090CV20 | 30,800 | $1,540 |
| No | 206905134 | DUCANE | 4HP18V60P | EAC4X49C | 92G1UH110CE20 | 30,400 | $1,520 |
| No | 206905131 | DUCANE | 4HP18V60P | EAC4X49C | 80G2UH110CV20 | 30,400 | $1,520 |
| No | 206905129 | DUCANE | 4HP18V60P | EAC4X49C | 80G1UH110CE20 | 30,400 | $1,520 |
| No | 206905128 | DUCANE | 4HP18V60P | EAC4X49C | 80G1UH100CE20X | 30,600 | $1,530 |
| No | 206905106 | DUCANE | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | 96G2UH110CV20 | 30,600 | $1,530 |
| No | 206905105 | DUCANE | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | 96G2UH090CV20 | 30,800 | $1,540 |
| No | 206905100 | DUCANE | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | 92G1UH110CE20 | 30,400 | $1,520 |
| No | 206905097 | DUCANE | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | 80G2UH110CV20 | 30,400 | $1,520 |
| No | 206905095 | DUCANE | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | 80G1UH110CE20 | 30,400 | $1,520 |
| No | 206905094 | DUCANE | 4HP18V60P | EA(C,U)1P49C+H4TXV02 | 80G1UH100CE20X | 30,600 | $1,530 |
| No | 206905148 | DUCANE | 4HP18V60P | EAH1P48C+H4TXV02 | 80G2UH110CV20 | 31,000 | $1,550 |
| No | 206905157 | DUCANE | 4HP18V60P | EAH1P48C+H4TXV02 | 96G2UH110CV20 | 31,200 | $1,560 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206905156 | DUCANE | 4HP18V60P | EAH1P48C+H4TXV02 | 96G2UH090CV20 | 31,400 | $1,570 |
| No | 206905151 | DUCANE | 4HP18V60P | EAH1P48C+H4TXV02 | 92G1UH110CE20 | 30,800 | $1,540 |
| No | 206905146 | DUCANE | 4HP18V60P | EAH1P48C+H4TXV02 | 80G2UH110CE20 | 31,000 | $1,550 |
| No | 206905144 | DUCANE | 4HP18V60P | EAH1P48C+H4TXV02 | 80G1UH110CE20 | 30,800 | $1,540 |
| No | 206905142 | DUCANE | 4HP18V60P | EAH1P48C+H4TXV02 | 80G1UH090CE20 | 30,800 | $1,540 |
| No | 206905073 | DUCANE | 4HP18V60P | BCE7E48M | | 32,200 | $1,610 |
| No | 206905071 | DUCANE | 4HP18V60P | BCE5E48M | | 31,600 | $1,580 |
| No | 206905070 | DUCANE | 4HP18V60P | BCE5C48M*4X | | 31,600 | $1,580 |
| No | 206905069 | DUCANE | 4HP18V60P | BCE5C48M*1P+H4TXV02 | | 31,600 | $1,580 |
| No | 206905072 | DUCANE | 4HP18V60P | BCE5V48M | | 31,400 | $1,570 |
| No | 206903022 | DUCANE | 4HP18V36P | ED1P30/36B+H4TXV02 | 80G2DF090BE16 | 22,200 | $1,110 |
| No | 206902879 | DUCANE | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 80G1UH070BE12 | 21,600 | $1,080 |
| No | 206902913 | DUCANE | 4HP18V36P | EAC4X36B | 80G2UH090BV16* | 22,800 | $1,140 |
| No | 206902864 | DUCANE | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 80G2UH090BV16* | 22,800 | $1,140 |
| No | 206903303 | DUCANE | 4HP18V36P | ED1P24B+H4TXV01 | EFV12BCA | 15,500 | $775 |
| No | 206903302 | DUCANE | 4HP18V36P | ED1P24B+H4TXV01 | EFV08BCA | 15,700 | $785 |
| No | 206903301 | DUCANE | 4HP18V36P | ED1P24B+H4TXV01 | 96G2DF070BV16 | 15,800 | $790 |
| No | 206903275 | DUCANE | 4HP18V36P | EAH1P30B+H4TXV01 | 96G1UH045BE12 | 15,900 | $795 |
| No | 206903255 | DUCANE | 4HP18V36P | EAH1P30A+H4TXV01 | 80G2UH070AV12* | 15,600 | $780 |
| No | 206903250 | DUCANE | 4HP18V36P | EAC4X30B | 95G1UH045BE12 | 15,800 | $790 |
| No | 206903233 | DUCANE | 4HP18V36P | EAC4X30A | 80G2UH070AV12* | 15,600 | $780 |
| No | 206903210 | DUCANE | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 96G1UH045BE12 | 15,900 | $795 |
| No | 206903190 | DUCANE | 4HP18V36P | EA(C,U)1P30A+H4TXV01 | 80G2UH070AV12* | 15,600 | $780 |
| No | 206903232 | DUCANE | 4HP18V36P | EAC4X24B | 96G1UH070BE12 | 16,300 | $815 |
| No | 206903231 | DUCANE | 4HP18V36P | EAC4X24B | 96G1UH045BE12 | 16,300 | $815 |
| No | 206903230 | DUCANE | 4HP18V36P | EAC4X24B | 96G1UH030BE08 | 15,800 | $790 |
| No | 206903225 | DUCANE | 4HP18V36P | EAC4X24B | 92G1UH030BE12 | 15,700 | $785 |
| No | 206903212 | DUCANE | 4HP18V36P | EAC4X24A | 80G2UH070AV12* | 16,000 | $800 |
| No | 206903189 | DUCANE | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 96G1UH070BE12 | 16,300 | $815 |
| No | 206903188 | DUCANE | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 96G1UH045BE12 | 16,300 | $815 |
| No | 206903187 | DUCANE | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 96G1UH030BE08 | 15,800 | $790 |
| No | 206903169 | DUCANE | 4HP18V36P | EA(C,U)1P24A+H4TXV01 | 80G2UH070AV12* | 16,000 | $800 |
| No | 206903168 | DUCANE | 4HP18V36P | E*1P23B+H4TXV01 | 96G1UH070BE12 | 15,400 | $770 |
| No | 206903167 | DUCANE | 4HP18V36P | E*1P23B+H4TXV01 | 96G1UH045BE12 | 15,400 | $770 |
| No | 206903166 | DUCANE | 4HP18V36P | E*1P23B+H4TXV01 | 96G1UH030BE08 | 14,900 | $745 |
| No | 206903148 | DUCANE | 4HP18V36P | E*1P23A+H4TXV01 | 80G2UH070AV12* | 15,200 | $760 |
| No | 206902846 | DUCANE | 4HP18V36P | E*1P36B+H4TXV02 | 80G2UH090BE16L | 23,400 | $1,170 |
| No | 206902984 | DUCANE | 4HP18V36P | EAH1P48B+H4TXV02 | 80G2UH090BE16L | 22,200 | $1,110 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206902968 | DUCANE | 4HP18V36P | EAH1P36B+H4TXV02 | 80G2UH090BE16L | 22,200 | $1,110 |
| No | 206902944 | DUCANE | 4HP18V36P | EAC4X48B | 80G2UH090BE16L | 21,600 | $1,080 |
| No | 206902895 | DUCANE | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 80G2UH090BE16L | 21,600 | $1,080 |
| No | 206902921 | DUCANE | 4HP18V36P | EAC4X36B | 80G2UH090BE16L | 22,800 | $1,140 |
| No | 206902872 | DUCANE | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 80G2UH090BE16L | 22,800 | $1,140 |
| No | 206902831 | DUCANE | 4HP18V36P | E*1P36A+H4TXV02 | 80G2UH070AE12L | 23,400 | $1,170 |
| No | 206902910 | DUCANE | 4HP18V36P | EAC4X36A | 80G2UH070AE12L | 22,800 | $1,140 |
| No | 206902861 | DUCANE | 4HP18V36P | EA(C,U)1P36A+H4TXV02 | 80G2UH070AE12L | 22,800 | $1,140 |
| No | 206903261 | DUCANE | 4HP18V36P | EAH1P30A+H4TXV01 | 80G2UH070AE12L | 15,800 | $790 |
| No | 206903239 | DUCANE | 4HP18V36P | EAC4X30A | 80G2UH070AE12L | 15,800 | $790 |
| No | 206903196 | DUCANE | 4HP18V36P | EA(C,U)1P30A+H4TXV01 | 80G2UH070AE12L | 15,800 | $790 |
| No | 206903175 | DUCANE | 4HP18V36P | EA(C,U)1P24A+H4TXV01 | 80G2UH070AE12L | 16,100 | $805 |
| No | 206902847 | DUCANE | 4HP18V36P | E*1P36C+H4TXV02 | 80G2UH110CE16 | 23,400 | $1,170 |
| No | 206902855 | DUCANE | 4HP18V36P | E*1P36C+H4TXV02 | EFV16CCA | 23,200 | $1,160 |
| No | 206902854 | DUCANE | 4HP18V36P | E*1P36C+H4TXV02 | 96G2UH090CV12 | 23,200 | $1,160 |
| No | 206902853 | DUCANE | 4HP18V36P | E*1P36C+H4TXV02 | 96G1UH090CE16 | 23,400 | $1,170 |
| No | 206902850 | DUCANE | 4HP18V36P | E*1P36C+H4TXV02 | 92G1UH110CE16 | 23,200 | $1,160 |
| No | 206902849 | DUCANE | 4HP18V36P | E*1P36C+H4TXV02 | 92G1UH090CE16 | 23,200 | $1,160 |
| No | 206902848 | DUCANE | 4HP18V36P | E*1P36C+H4TXV02 | 92G1UH090CE12 | 23,400 | $1,170 |
| No | 206902845 | DUCANE | 4HP18V36P | E*1P36B+H4TXV02 | EFV12BCA | 23,400 | $1,170 |
| No | 206902844 | DUCANE | 4HP18V36P | E*1P36B+H4TXV02 | 96G2UH070BV12 | 23,400 | $1,170 |
| No | 206902843 | DUCANE | 4HP18V36P | E*1P36B+H4TXV02 | 96G2UH045BV12 | 23,600 | $1,180 |
| No | 206902842 | DUCANE | 4HP18V36P | E*1P36B+H4TXV02 | 96G1UH070BE12 | 23,200 | $1,160 |
| No | 206902840 | DUCANE | 4HP18V36P | E*1P36B+H4TXV02 | 92G1UH070BE12 | 23,400 | $1,170 |
| No | 206902839 | DUCANE | 4HP18V36P | E*1P36B+H4TXV02 | 92G1UH045BE12 | 23,400 | $1,170 |
| No | 206902838 | DUCANE | 4HP18V36P | E*1P36B+H4TXV02 | 92G1UH030BE12 | 23,400 | $1,170 |
| No | 206902836 | DUCANE | 4HP18V36P | E*1P36B+H4TXV02 | 80G2UH090BE16 | 23,400 | $1,170 |
| No | 206902835 | DUCANE | 4HP18V36P | E*1P36B+H4TXV02 | 80G2UH090BE12 | 23,400 | $1,170 |
| No | 206902834 | DUCANE | 4HP18V36P | E*1P36B+H4TXV02 | 80G1UH090BE16 | 23,200 | $1,160 |
| No | 206902833 | DUCANE | 4HP18V36P | E*1P36B+H4TXV02 | 80G1UH080BE16X | 23,600 | $1,180 |
| No | 206902832 | DUCANE | 4HP18V36P | E*1P36B+H4TXV02 | 80G1UH070BE12 | 23,200 | $1,160 |
| No | 206902829 | DUCANE | 4HP18V36P | E*1P36A+H4TXV02 | 80G2UH070AE12 | 23,400 | $1,170 |
| No | 206902828 | DUCANE | 4HP18V36P | E*1P36A+H4TXV02 | 80G1UH070AE12 | 23,200 | $1,160 |
| No | 206902827 | DUCANE | 4HP18V36P | E*1P36A+H4TXV02 | 80G1UH060AE12X | 23,200 | $1,160 |
| No | 206902826 | DUCANE | 4HP18V36P | E*1P36A+H4TXV02 | 80G1UH045AE12 | 23,200 | $1,160 |
| No | 206903031 | DUCANE | 4HP18V36P | ED1P30/36C+H4TXV02 | 96G1DF090CE16 | 22,200 | $1,110 |
| No | 206903029 | DUCANE | 4HP18V36P | ED1P30/36C+H4TXV02 | 92G1DF090CE16 | 22,200 | $1,110 |
| No | 206903019 | DUCANE | 4HP18V36P | ED1P30/36B+H4TXV02 | 96G2DF070BV16 | 22,600 | $1,130 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206903028 | DUCANE | 4HP18V36P | ED1P30/36B+H4TXV02 | 96G1DF070BE16 | 22,400 | $1,120 |
| No | 206903027 | DUCANE | 4HP18V36P | ED1P30/36B+H4TXV02 | 96G1DF045BE12 | 22,000 | $1,100 |
| No | 206903024 | DUCANE | 4HP18V36P | ED1P30/36B+H4TXV02 | 92G1DF070BE12 | 22,400 | $1,120 |
| No | 206903023 | DUCANE | 4HP18V36P | ED1P30/36B+H4TXV02 | 92G1DF045BE12 | 22,400 | $1,120 |
| No | 206903021 | DUCANE | 4HP18V36P | ED1P30/36B+H4TXV02 | 80G1DF090BE16 | 22,200 | $1,110 |
| No | 206903020 | DUCANE | 4HP18V36P | ED1P30/36B+H4TXV02 | 80G1DF070BE12 | 22,000 | $1,100 |
| No | 206903016 | DUCANE | 4HP18V36P | ED1P30/36A+H4TXV02 | 80G1DF070AE12 | 22,200 | $1,110 |
| No | 206902983 | DUCANE | 4HP18V36P | EAH1P48B+H4TXV02 | EFV12BCA | 22,000 | $1,100 |
| No | 206902982 | DUCANE | 4HP18V36P | EAH1P48B+H4TXV02 | 96G2UH070BV12 | 22,400 | $1,120 |
| No | 206902981 | DUCANE | 4HP18V36P | EAH1P48B+H4TXV02 | 96G2UH045BV12 | 22,400 | $1,120 |
| No | 206902980 | DUCANE | 4HP18V36P | EAH1P48B+H4TXV02 | 96G1UH070BE12 | 22,000 | $1,100 |
| No | 206902978 | DUCANE | 4HP18V36P | EAH1P48B+H4TXV02 | 92G1UH070BE12 | 22,200 | $1,110 |
| No | 206902977 | DUCANE | 4HP18V36P | EAH1P48B+H4TXV02 | 92G1UH045BE12 | 22,400 | $1,120 |
| No | 206902976 | DUCANE | 4HP18V36P | EAH1P48B+H4TXV02 | 92G1UH030BE12 | 22,200 | $1,110 |
| No | 206902975 | DUCANE | 4HP18V36P | EAH1P48B+H4TXV02 | 80G2UH090BV16* | 22,400 | $1,120 |
| No | 206902974 | DUCANE | 4HP18V36P | EAH1P48B+H4TXV02 | 80G2UH090BE16 | 22,200 | $1,110 |
| No | 206902973 | DUCANE | 4HP18V36P | EAH1P48B+H4TXV02 | 80G2UH090BE12 | 22,400 | $1,120 |
| No | 206902972 | DUCANE | 4HP18V36P | EAH1P48B+H4TXV02 | 80G1UH090BE16 | 22,000 | $1,100 |
| No | 206902971 | DUCANE | 4HP18V36P | EAH1P48B+H4TXV02 | 80G1UH070BE12 | 22,000 | $1,100 |
| No | 206902967 | DUCANE | 4HP18V36P | EAH1P36B+H4TXV02 | EFV12BCA | 22,200 | $1,110 |
| No | 206902966 | DUCANE | 4HP18V36P | EAH1P36B+H4TXV02 | 96G2UH070BV12 | 22,200 | $1,110 |
| No | 206902965 | DUCANE | 4HP18V36P | EAH1P36B+H4TXV02 | 96G2UH045BV12 | 22,400 | $1,120 |
| No | 206902970 | DUCANE | 4HP18V36P | EAH1P36B+H4TXV02 | 96G1UH070BE12 | 21,800 | $1,090 |
| No | 206902962 | DUCANE | 4HP18V36P | EAH1P36B+H4TXV02 | 92G1UH070BE12 | 22,200 | $1,110 |
| No | 206902961 | DUCANE | 4HP18V36P | EAH1P36B+H4TXV02 | 92G1UH045BE12 | 22,200 | $1,110 |
| No | 206902960 | DUCANE | 4HP18V36P | EAH1P36B+H4TXV02 | 92G1UH030BE12 | 22,200 | $1,110 |
| No | 206902959 | DUCANE | 4HP18V36P | EAH1P36B+H4TXV02 | 80G2UH090BV16* | 22,000 | $1,100 |
| No | 206902958 | DUCANE | 4HP18V36P | EAH1P36B+H4TXV02 | 80G2UH090BE16 | 22,200 | $1,110 |
| No | 206902957 | DUCANE | 4HP18V36P | EAH1P36B+H4TXV02 | 80G2UH090BE12 | 22,200 | $1,110 |
| No | 206902956 | DUCANE | 4HP18V36P | EAH1P36B+H4TXV02 | 80G1UH090BE16 | 22,000 | $1,100 |
| No | 206902955 | DUCANE | 4HP18V36P | EAH1P36B+H4TXV02 | 80G1UH080BE16X | 22,200 | $1,110 |
| No | 206902954 | DUCANE | 4HP18V36P | EAH1P36B+H4TXV02 | 80G1UH070BE12 | 22,000 | $1,100 |
| No | 206902953 | DUCANE | 4HP18V36P | EAC4X48C | EFV16CCA | 21,600 | $1,080 |
| No | 206902952 | DUCANE | 4HP18V36P | EAC4X48C | 96G2UH090CV12 | 21,600 | $1,080 |
| No | 206902951 | DUCANE | 4HP18V36P | EAC4X48C | 96G1UH090CE16 | 21,600 | $1,080 |
| No | 206902950 | DUCANE | 4HP18V36P | EAC4X48C | 95G1UH090CE16 | 21,600 | $1,080 |
| No | 206902948 | DUCANE | 4HP18V36P | EAC4X48C | 92G1UH110CE16 | 21,400 | $1,070 |
| No | 206902947 | DUCANE | 4HP18V36P | EAC4X48C | 92G1UH090CE16 | 21,600 | $1,080 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206902946 | DUCANE | 4HP18V36P | EAC4X48C | 92G1UH090CE12 | 21,800 | $1,090 |
| No | 206902945 | DUCANE | 4HP18V36P | EAC4X48C | 80G2UH110CE16 | 21,600 | $1,080 |
| No | 206902943 | DUCANE | 4HP18V36P | EAC4X48B | EFV12BCA | 21,600 | $1,080 |
| No | 206902942 | DUCANE | 4HP18V36P | EAC4X48B | 96G2UH070BV12 | 21,800 | $1,090 |
| No | 206902941 | DUCANE | 4HP18V36P | EAC4X48B | 96G2UH045BV12 | 21,800 | $1,090 |
| No | 206902940 | DUCANE | 4HP18V36P | EAC4X48B | 96G1UH070BE12 | 21,400 | $1,070 |
| No | 206902939 | DUCANE | 4HP18V36P | EAC4X48B | 96G1UH045BE12 | 21,400 | $1,070 |
| No | 206902936 | DUCANE | 4HP18V36P | EAC4X48B | 92G1UH070BE12 | 21,600 | $1,080 |
| No | 206902935 | DUCANE | 4HP18V36P | EAC4X48B | 92G1UH045BE12 | 21,800 | $1,090 |
| No | 206902934 | DUCANE | 4HP18V36P | EAC4X48B | 92G1UH030BE12 | 21,600 | $1,080 |
| No | 206902933 | DUCANE | 4HP18V36P | EAC4X48B | 80G2UH090BV16* | 21,600 | $1,080 |
| No | 206902932 | DUCANE | 4HP18V36P | EAC4X48B | 80G2UH090BE16 | 21,600 | $1,080 |
| No | 206902931 | DUCANE | 4HP18V36P | EAC4X48B | 80G2UH090BE12 | 21,800 | $1,090 |
| No | 206902930 | DUCANE | 4HP18V36P | EAC4X48B | 80G1UH090BE16 | 21,600 | $1,080 |
| No | 206902929 | DUCANE | 4HP18V36P | EAC4X48B | 80G1UH080BE16X | 21,800 | $1,090 |
| No | 206902928 | DUCANE | 4HP18V36P | EAC4X48B | 80G1UH070BE12 | 21,600 | $1,080 |
| No | 206902903 | DUCANE | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 96G2UH090CV12 | 21,600 | $1,080 |
| No | 206902902 | DUCANE | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 96G1UH090CE16 | 21,600 | $1,080 |
| No | 206902901 | DUCANE | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 95G1UH090CE16 | 21,600 | $1,080 |
| No | 206902899 | DUCANE | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 92G1UH110CE16 | 21,400 | $1,070 |
| No | 206902898 | DUCANE | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 92G1UH090CE16 | 21,600 | $1,080 |
| No | 206902897 | DUCANE | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 92G1UH090CE12 | 21,800 | $1,090 |
| No | 206902896 | DUCANE | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 80G2UH110CE16 | 21,600 | $1,080 |
| No | 206902894 | DUCANE | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | EFV12BCA | 21,800 | $1,090 |
| No | 206902893 | DUCANE | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 96G2UH070BV12 | 21,800 | $1,090 |
| No | 206902892 | DUCANE | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 96G2UH045BV12 | 21,800 | $1,090 |
| No | 206902891 | DUCANE | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 96G1UH070BE12 | 21,400 | $1,070 |
| No | 206902890 | DUCANE | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 96G1UH045BE12 | 21,400 | $1,070 |
| No | 206902887 | DUCANE | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 92G1UH070BE12 | 21,600 | $1,080 |
| No | 206902886 | DUCANE | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 92G1UH045BE12 | 21,800 | $1,090 |
| No | 206902885 | DUCANE | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 92G1UH030BE12 | 21,600 | $1,080 |
| No | 206902884 | DUCANE | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 80G2UH090BV16* | 21,600 | $1,080 |
| No | 206902883 | DUCANE | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 80G2UH090BE16 | 21,600 | $1,080 |
| No | 206902882 | DUCANE | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 80G2UH090BE12 | 21,800 | $1,090 |
| No | 206902881 | DUCANE | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 80G1UH090BE16 | 21,600 | $1,080 |
| No | 206902880 | DUCANE | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 80G1UH080BE16X | 21,800 | $1,090 |
| No | 206902917 | DUCANE | 4HP18V36P | EAC4X36B | EFV12BCA | 22,800 | $1,140 |
| No | 206902927 | DUCANE | 4HP18V36P | EAC4X36B | 96G2UH070BV12 | 22,800 | $1,140 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206902926 | DUCANE | 4HP18V36P | EAC4X36B | 96G2UH045BV12 | 23,000 | $1,150 |
| No | 206902925 | DUCANE | 4HP18V36P | EAC4X36B | 96G1UH070BE12 | 22,400 | $1,120 |
| No | 206902924 | DUCANE | 4HP18V36P | EAC4X36B | 92G1UH070BE12 | 22,800 | $1,140 |
| No | 206902923 | DUCANE | 4HP18V36P | EAC4X36B | 92G1UH045BE12 | 22,800 | $1,140 |
| No | 206902922 | DUCANE | 4HP18V36P | EAC4X36B | 92G1UH030BE12 | 22,600 | $1,130 |
| No | 206902920 | DUCANE | 4HP18V36P | EAC4X36B | 80G2UH090BE16 | 22,800 | $1,140 |
| No | 206902919 | DUCANE | 4HP18V36P | EAC4X36B | 80G2UH090BE12 | 22,800 | $1,140 |
| No | 206902918 | DUCANE | 4HP18V36P | EAC4X36B | 80G1UH090BE16 | 22,600 | $1,130 |
| No | 206902912 | DUCANE | 4HP18V36P | EAC4X36B | 80G1UH080BE16X | 22,800 | $1,140 |
| No | 206902911 | DUCANE | 4HP18V36P | EAC4X36B | 80G1UH070BE12 | 22,600 | $1,130 |
| No | 206902909 | DUCANE | 4HP18V36P | EAC4X36A | 80G2UH070AE12 | 22,800 | $1,140 |
| No | 206902908 | DUCANE | 4HP18V36P | EAC4X36A | 80G1UH070AE12 | 22,600 | $1,130 |
| No | 206902907 | DUCANE | 4HP18V36P | EAC4X36A | 80G1UH060AE12X | 22,400 | $1,120 |
| No | 206902906 | DUCANE | 4HP18V36P | EAC4X36A | 80G1UH045AE12 | 22,400 | $1,120 |
| No | 206902868 | DUCANE | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | EFV12BCA | 22,000 | $1,100 |
| No | 206902878 | DUCANE | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 96G2UH070BV12 | 22,800 | $1,140 |
| No | 206902877 | DUCANE | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 96G2UH045BV12 | 23,000 | $1,150 |
| No | 206902875 | DUCANE | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 92G1UH070BE12 | 22,800 | $1,140 |
| No | 206902874 | DUCANE | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 92G1UH045BE12 | 22,800 | $1,140 |
| No | 206902873 | DUCANE | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 92G1UH030BE12 | 22,600 | $1,130 |
| No | 206902871 | DUCANE | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 80G2UH090BE16 | 22,800 | $1,140 |
| No | 206902870 | DUCANE | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 80G2UH090BE12 | 22,800 | $1,140 |
| No | 206902869 | DUCANE | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 80G1UH090BE16 | 22,600 | $1,130 |
| No | 206902863 | DUCANE | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 80G1UH080BE16X | 22,800 | $1,140 |
| No | 206902862 | DUCANE | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 80G1UH070BE12 | 22,600 | $1,130 |
| No | 206902860 | DUCANE | 4HP18V36P | EA(C,U)1P36A+H4TXV02 | 80G2UH070AE12 | 22,800 | $1,140 |
| No | 206902859 | DUCANE | 4HP18V36P | EA(C,U)1P36A+H4TXV02 | 80G1UH070AE12 | 22,600 | $1,130 |
| No | 206902858 | DUCANE | 4HP18V36P | EA(C,U)1P36A+H4TXV02 | 80G1UH060AE12X | 22,400 | $1,120 |
| No | 206902857 | DUCANE | 4HP18V36P | EA(C,U)1P36A+H4TXV02 | 80G1UH045AE12 | 22,400 | $1,120 |
| No | 206902824 | DUCANE | 4HP18V36P | BCE7E36M | | 23,400 | $1,170 |
| No | 206902820 | DUCANE | 4HP18V36P | BCE5C36M*4X | | 22,400 | $1,120 |
| No | 206902819 | DUCANE | 4HP18V36P | BCE5C36M*1P+H4TXV02 | | 22,400 | $1,120 |
| No | 206902822 | DUCANE | 4HP18V36P | BCE5E42M | | 22,200 | $1,110 |
| No | 206902821 | DUCANE | 4HP18V36P | BCE5E36M | | 22,600 | $1,130 |
| No | 206902823 | DUCANE | 4HP18V36P | BCE5V42M | | 22,200 | $1,110 |
| No | 206902825 | DUCANE | 4HP18V36P | BCE7E42M | | 22,000 | $1,100 |
| No | 206902818 | DUCANE | 4HP18V36P | BCE5V36M | | 22,000 | $1,100 |
| No | 206903156 | DUCANE | 4HP18V36P | E*1P23B+H4TXV01 | 96G2UH070BV12 | 15,100 | $755 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206903155 | DUCANE | 4HP18V36P | E*1P23B+H4TXV01 | 96G2UH045BV12 | 15,100 | $755 |
| No | 206903158 | DUCANE | 4HP18V36P | E*1P23B+H4TXV01 | EFV12BCA | 15,200 | $760 |
| No | 206903157 | DUCANE | 4HP18V36P | E*1P23B+H4TXV01 | EFV08BCA | 15,300 | $765 |
| No | 206903163 | DUCANE | 4HP18V36P | E*1P23B+H4TXV01 | 92G1UH070BE12 | 15,300 | $765 |
| No | 206903162 | DUCANE | 4HP18V36P | E*1P23B+H4TXV01 | 92G1UH045BE12 | 15,400 | $770 |
| No | 206903161 | DUCANE | 4HP18V36P | E*1P23B+H4TXV01 | 92G1UH030BE12 | 15,300 | $765 |
| No | 206903160 | DUCANE | 4HP18V36P | E*1P23B+H4TXV01 | 80G2UH090BE12 | 15,300 | $765 |
| No | 206903159 | DUCANE | 4HP18V36P | E*1P23B+H4TXV01 | 80G1UH070BE12 | 15,000 | $750 |
| No | 206903153 | DUCANE | 4HP18V36P | E*1P23A+H4TXV01 | 80G2UH070AE12 | 15,400 | $770 |
| No | 206903152 | DUCANE | 4HP18V36P | E*1P23A+H4TXV01 | 80G2UH045AE12 | 14,900 | $745 |
| No | 206903151 | DUCANE | 4HP18V36P | E*1P23A+H4TXV01 | 80G1UH060AE12X | 15,300 | $765 |
| No | 206903150 | DUCANE | 4HP18V36P | E*1P23A+H4TXV01 | 80G1UH045AE12 | 15,200 | $760 |
| No | 206903149 | DUCANE | 4HP18V36P | E*1P23A+H4TXV01 | 80G1UH040AE12X | 15,300 | $765 |
| No | 206903265 | DUCANE | 4HP18V36P | EAH1P30B+H4TXV01 | EFV12BCA | 15,600 | $780 |
| No | 206903264 | DUCANE | 4HP18V36P | EAH1P30B+H4TXV01 | EFV08BCA | 15,700 | $785 |
| No | 206903263 | DUCANE | 4HP18V36P | EAH1P30B+H4TXV01 | 96G2UH070BV12 | 15,500 | $775 |
| No | 206903262 | DUCANE | 4HP18V36P | EAH1P30B+H4TXV01 | 96G2UH045BV12 | 15,600 | $780 |
| No | 206903276 | DUCANE | 4HP18V36P | EAH1P30B+H4TXV01 | 96G1UH070BE12 | 15,900 | $795 |
| No | 206903274 | DUCANE | 4HP18V36P | EAH1P30B+H4TXV01 | 96G1UH030BE08 | 15,800 | $790 |
| No | 206903270 | DUCANE | 4HP18V36P | EAH1P30B+H4TXV01 | 92G1UH070BE12 | 15,800 | $790 |
| No | 206903269 | DUCANE | 4HP18V36P | EAH1P30B+H4TXV01 | 92G1UH045BE12 | 15,900 | $795 |
| No | 206903268 | DUCANE | 4HP18V36P | EAH1P30B+H4TXV01 | 92G1UH030BE12 | 15,800 | $790 |
| No | 206903267 | DUCANE | 4HP18V36P | EAH1P30B+H4TXV01 | 80G2UH090BE12 | 15,800 | $790 |
| No | 206903266 | DUCANE | 4HP18V36P | EAH1P30B+H4TXV01 | 80G1UH070BE12 | 15,500 | $775 |
| No | 206903260 | DUCANE | 4HP18V36P | EAH1P30A+H4TXV01 | 80G2UH070AE12 | 15,800 | $790 |
| No | 206903259 | DUCANE | 4HP18V36P | EAH1P30A+H4TXV01 | 80G2UH045AE12 | 15,400 | $770 |
| No | 206903258 | DUCANE | 4HP18V36P | EAH1P30A+H4TXV01 | 80G1UH060AE12X | 15,700 | $785 |
| No | 206903257 | DUCANE | 4HP18V36P | EAH1P30A+H4TXV01 | 80G1UH045AE12 | 15,700 | $785 |
| No | 206903256 | DUCANE | 4HP18V36P | EAH1P30A+H4TXV01 | 80G1UH040AE12X | 15,700 | $785 |
| No | 206903241 | DUCANE | 4HP18V36P | EAC4X30B | 96G2UH070BV12 | 15,500 | $775 |
| No | 206903240 | DUCANE | 4HP18V36P | EAC4X30B | 96G2UH045BV12 | 15,600 | $780 |
| No | 206903243 | DUCANE | 4HP18V36P | EAC4X30B | EFV12BCA | 15,600 | $780 |
| No | 206903242 | DUCANE | 4HP18V36P | EAC4X30B | EFV08BCA | 15,900 | $795 |
| No | 206903254 | DUCANE | 4HP18V36P | EAC4X30B | 96G1UH070BE12 | 15,900 | $795 |
| No | 206903252 | DUCANE | 4HP18V36P | EAC4X30B | 96G1UH030BE08 | 15,800 | $790 |
| No | 206903248 | DUCANE | 4HP18V36P | EAC4X30B | 92G1UH070BE12 | 15,800 | $790 |
| No | 206903247 | DUCANE | 4HP18V36P | EAC4X30B | 92G1UH045BE12 | 15,900 | $795 |
| No | 206903246 | DUCANE | 4HP18V36P | EAC4X30B | 92G1UH030BE12 | 15,800 | $790 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206903245 | DUCANE | 4HP18V36P | EAC4X30B | 80G2UH090BE12 | 15,800 | $790 |
| No | 206903244 | DUCANE | 4HP18V36P | EAC4X30B | 80G1UH070BE12 | 15,600 | $780 |
| No | 206903238 | DUCANE | 4HP18V36P | EAC4X30A | 80G2UH070AE12 | 15,800 | $790 |
| No | 206903237 | DUCANE | 4HP18V36P | EAC4X30A | 80G2UH045AE12 | 15,800 | $790 |
| No | 206903236 | DUCANE | 4HP18V36P | EAC4X30A | 80G1UH060AE12X | 15,800 | $790 |
| No | 206903235 | DUCANE | 4HP18V36P | EAC4X30A | 80G1UH045AE12 | 15,700 | $785 |
| No | 206903234 | DUCANE | 4HP18V36P | EAC4X30A | 80G1UH040AE12X | 15,800 | $790 |
| No | 206903198 | DUCANE | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 96G2UH070BV12 | 15,500 | $775 |
| No | 206903197 | DUCANE | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 96G2UH045BV12 | 15,600 | $780 |
| No | 206903200 | DUCANE | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | EFV12BCA | 15,600 | $780 |
| No | 206903199 | DUCANE | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | EFV08BCA | 15,900 | $795 |
| No | 206903211 | DUCANE | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 96G1UH070BE12 | 15,900 | $795 |
| No | 206903209 | DUCANE | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 96G1UH030BE08 | 15,800 | $790 |
| No | 206903205 | DUCANE | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 92G1UH070BE12 | 15,800 | $790 |
| No | 206903204 | DUCANE | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 92G1UH045BE12 | 15,900 | $795 |
| No | 206903203 | DUCANE | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 92G1UH030BE12 | 15,800 | $790 |
| No | 206903202 | DUCANE | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 80G2UH090BE12 | 15,800 | $790 |
| No | 206903201 | DUCANE | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 80G1UH070BE12 | 15,600 | $780 |
| No | 206903195 | DUCANE | 4HP18V36P | EA(C,U)1P30A+H4TXV01 | 80G2UH070AE12 | 15,800 | $790 |
| No | 206903194 | DUCANE | 4HP18V36P | EA(C,U)1P30A+H4TXV01 | 80G2UH045AE12 | 15,800 | $790 |
| No | 206903193 | DUCANE | 4HP18V36P | EA(C,U)1P30A+H4TXV01 | 80G1UH060AE12X | 15,800 | $790 |
| No | 206903192 | DUCANE | 4HP18V36P | EA(C,U)1P30A+H4TXV01 | 80G1UH045AE12 | 15,700 | $785 |
| No | 206903191 | DUCANE | 4HP18V36P | EA(C,U)1P30A+H4TXV01 | 80G1UH040AE12X | 15,800 | $790 |
| No | 206903220 | DUCANE | 4HP18V36P | EAC4X24B | 96G2UH070BV12 | 15,900 | $795 |
| No | 206903219 | DUCANE | 4HP18V36P | EAC4X24B | 96G2UH045BV12 | 16,000 | $800 |
| No | 206903222 | DUCANE | 4HP18V36P | EAC4X24B | EFV12BCA | 16,000 | $800 |
| No | 206903227 | DUCANE | 4HP18V36P | EAC4X24B | 92G1UH070BE12 | 16,200 | $810 |
| No | 206903226 | DUCANE | 4HP18V36P | EAC4X24B | 92G1UH045BE12 | 16,200 | $810 |
| No | 206903224 | DUCANE | 4HP18V36P | EAC4X24B | 80G2UH090BE12 | 16,100 | $805 |
| No | 206903223 | DUCANE | 4HP18V36P | EAC4X24B | 80G1UH070BE12 | 15,900 | $795 |
| No | 206903217 | DUCANE | 4HP18V36P | EAC4X24A | 80G2UH070AE12 | 16,100 | $805 |
| No | 206903215 | DUCANE | 4HP18V36P | EAC4X24A | 80G1UH060AE12X | 16,100 | $805 |
| No | 206903213 | DUCANE | 4HP18V36P | EAC4X24A | 80G1UH040AE12X | 16,100 | $805 |
| No | 206903176 | DUCANE | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 96G2UH045BV12 | 16,000 | $800 |
| No | 206903177 | DUCANE | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 96G2UH070BV12 | 15,900 | $795 |
| No | 206903179 | DUCANE | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | EFV12BCA | 16,000 | $800 |
| No | 206903178 | DUCANE | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | EFV08BCA | 16,300 | $815 |
| No | 206903184 | DUCANE | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 92G1UH070BE12 | 16,200 | $810 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206903183 | DUCANE | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 92G1UH045BE12 | 16,200 | $810 |
| No | 206903181 | DUCANE | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 80G2UH090BE12 | 16,100 | $805 |
| No | 206903180 | DUCANE | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 80G1UH070BE12 | 15,900 | $795 |
| No | 206903174 | DUCANE | 4HP18V36P | EA(C,U)1P24A+H4TXV01 | 80G2UH070AE12 | 16,100 | $805 |
| No | 206903172 | DUCANE | 4HP18V36P | EA(C,U)1P24A+H4TXV01 | 80G1UH060AE12X | 16,100 | $805 |
| No | 206903170 | DUCANE | 4HP18V36P | EA(C,U)1P24A+H4TXV01 | 80G1UH040AE12X | 16,100 | $805 |
| No | 206903147 | DUCANE | 4HP18V36P | BCE7E30M | | 16,200 | $810 |
| No | 206903146 | DUCANE | 4HP18V36P | BCE7E24M | | 15,800 | $790 |
| No | 206903145 | DUCANE | 4HP18V36P | BCE7E18M | | 15,400 | $770 |
| No | 206903144 | DUCANE | 4HP18V36P | BCE5V30M | | 15,900 | $795 |
| No | 206903142 | DUCANE | 4HP18V36P | BCE5V18M | | 15,900 | $795 |
| No | 206903141 | DUCANE | 4HP18V36P | BCE5E30M | | 15,900 | $795 |
| No | 206903140 | DUCANE | 4HP18V36P | BCE5E24M | | 15,000 | $750 |
| No | 206903139 | DUCANE | 4HP18V36P | BCE5C24M*4X | | 16,100 | $805 |
| No | 206903138 | DUCANE | 4HP18V36P | BCE5C24M*1P+H4TXV01 | | 16,100 | $805 |
| No | 206903137 | DUCANE | 4HP18V36P | BCE5C18M*4X | | 15,400 | $770 |
| No | 206903136 | DUCANE | 4HP18V36P | BCE5C18M*1P+H4TXV01 | | 15,400 | $770 |
| No | 206903143 | DUCANE | 4HP18V36P | BCE5V24M | | 16,100 | $805 |
| No | 208106850 | DUCANE | 4DHP2S30M-1P | Combination heat pumps with or without ducts | | 16,000 | $800 |
| No | 208106847 | DUCANE | 4DHP2S24M-1P | Combination heat pumps with or without ducts | | 16,700 | $835 |
| No | 208106844 | DUCANE | 4DHP2S18M-1P | Combination heat pumps with or without ducts | | 11,400 | $570 |
| No | 206903718 | DUCANE | 4HP18V60P | ED1P60D+H4TXV03 | 95G1DF110CE20 | 37,400 | $1,870 |
| No | 206903716 | DUCANE | 4HP18V60P | EAH1P60D+H4TXV03 | EFV20DCA | 36,600 | $1,830 |
| No | 206903698 | DUCANE | 4HP18V60P | EAC4X60C | EFV16CCA | 37,400 | $1,870 |
| No | 206903694 | DUCANE | 4HP18V60P | EAC4X60C | 95G1UH110CE20 | 37,200 | $1,860 |
| No | 206903693 | DUCANE | 4HP18V60P | EAC4X60C | 95G1UH100CE20X | 38,000 | $1,900 |
| No | 206903670 | DUCANE | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | EFV16CCA | 37,400 | $1,870 |
| No | 206903666 | DUCANE | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 95G1UH110CE20 | 37,200 | $1,860 |
| No | 206903665 | DUCANE | 4HP18V60P | EA(C,U)1P60C+H4TXV03 | 95G1UH100CE20X | 38,000 | $1,900 |
| No | 206903644 | DUCANE | 4HP18V60P | BCE5E60M | | 37,800 | $1,890 |
| No | 206905165 | DUCANE | 4HP18V60P | ED1P50/60C+H4TXV02 | 96G2DF110CV20 | 30,800 | $1,540 |
| No | 206905164 | DUCANE | 4HP18V60P | ED1P50/60C+H4TXV02 | 96G2DF090CV20 | 30,800 | $1,540 |
| No | 206905163 | DUCANE | 4HP18V60P | ED1P50/60C+H4TXV02 | 96G1DF090CE16 | 30,800 | $1,540 |
| No | 206905162 | DUCANE | 4HP18V60P | ED1P50/60C+H4TXV02 | 95G1DF110CE20 | 30,400 | $1,520 |
| No | 206905159 | DUCANE | 4HP18V60P | ED1P50/60C+H4TXV02 | 80G1DF110CE20 | 30,400 | $1,520 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206905160 | DUCANE | 4HP18V60P | ED1P50/60C+H4TXV02 | 92G1DF090CE16 | 30,600 | $1,530 |
| No | 206905161 | DUCANE | 4HP18V60P | ED1P50/60C+H4TXV02 | 95G1DF090CE16 | 30,600 | $1,530 |
| No | 206902915 | DUCANE | 4HP18V36P | EAC4X36B | 95G1UH060BE12X | 22,000 | $1,100 |
| No | 206902916 | DUCANE | 4HP18V36P | EAC4X36B | 96G1UH045BE12 | 22,600 | $1,130 |
| No | 206902914 | DUCANE | 4HP18V36P | EAC4X36B | 95G1UH040BE12X | 22,000 | $1,100 |
| No | 206902905 | DUCANE | 4HP18V36P | EAC4X36A | 80G2UH070AV12* | 22,200 | $1,110 |
| No | 206903030 | DUCANE | 4HP18V36P | ED1P30/36C+H4TXV02 | 95G1DF090CE16 | 22,000 | $1,100 |
| No | 206903018 | DUCANE | 4HP18V36P | ED1P30/36B+H4TXV02 | 96G2DF045BV12 | 22,200 | $1,110 |
| No | 206903026 | DUCANE | 4HP18V36P | ED1P30/36B+H4TXV02 | 95G1DF070BE16 | 22,000 | $1,100 |
| No | 206903025 | DUCANE | 4HP18V36P | ED1P30/36B+H4TXV02 | 95G1DF045BE12 | 22,400 | $1,120 |
| No | 206903017 | DUCANE | 4HP18V36P | ED1P30/36A+H4TXV02 | 80G2DF070AE12 | 22,000 | $1,100 |
| No | 206903015 | DUCANE | 4HP18V36P | ED1P30/36A+H4TXV02 | 80G1DF045AE12 | 22,200 | $1,110 |
| No | 206902852 | DUCANE | 4HP18V36P | E*1P36C+H4TXV02 | 95G1UH090CE16 | 23,000 | $1,150 |
| No | 206902851 | DUCANE | 4HP18V36P | E*1P36C+H4TXV02 | 95G1UH080CE16X | 22,800 | $1,140 |
| No | 206902841 | DUCANE | 4HP18V36P | E*1P36B+H4TXV02 | 96G1UH045BE12 | 23,200 | $1,160 |
| No | 206902837 | DUCANE | 4HP18V36P | E*1P36B+H4TXV02 | 80G2UH090BV16* | 22,800 | $1,140 |
| No | 206902856 | DUCANE | 4HP18V36P | EA(C,U)1P36A+H4TXV02 | 80G2UH070AV12* | 22,200 | $1,110 |
| No | 206903286 | DUCANE | 4HP18V36P | EC4X23B | EFV08BCA | 15,100 | $755 |
| No | 206903287 | DUCANE | 4HP18V36P | EC4X23B | EFV12BCA | 14,900 | $745 |
| No | 206903221 | DUCANE | 4HP18V36P | EAC4X24B | EFV08BCA | 15,400 | $770 |
| No | 206903297 | DUCANE | 4HP18V36P | EC4X23B | 96G1UH070BE12 | 14,800 | $740 |
| No | 206903284 | DUCANE | 4HP18V36P | EC4X23B | 96G2UH045BV12 | 14,900 | $745 |
| No | 206903295 | DUCANE | 4HP18V36P | EC4X23B | 96G1UH030BE08 | 14,900 | $745 |
| No | 206903294 | DUCANE | 4HP18V36P | EC4X23B | 95G1UH070BE12 | 14,900 | $745 |
| No | 206903296 | DUCANE | 4HP18V36P | EC4X23B | 96G1UH045BE12 | 14,900 | $745 |
| No | 206903285 | DUCANE | 4HP18V36P | EC4X23B | 96G2UH070BV12 | 14,800 | $740 |
| No | 206903292 | DUCANE | 4HP18V36P | EC4X23B | 92G1UH070BE12 | 14,900 | $745 |
| No | 206903293 | DUCANE | 4HP18V36P | EC4X23B | 95G1UH045BE12 | 14,800 | $740 |
| No | 206903290 | DUCANE | 4HP18V36P | EC4X23B | 92G1UH030BE12 | 15,000 | $750 |
| No | 206903291 | DUCANE | 4HP18V36P | EC4X23B | 92G1UH045BE12 | 14,800 | $740 |
| No | 206903289 | DUCANE | 4HP18V36P | EC4X23B | 80G2UH090BE12 | 14,900 | $745 |
| No | 206903288 | DUCANE | 4HP18V36P | EC4X23B | 80G1UH070BE12 | 14,800 | $740 |
| No | 206903277 | DUCANE | 4HP18V36P | EC4X23A | 80G2UH070AV12* | 14,900 | $745 |
| No | 206903283 | DUCANE | 4HP18V36P | EC4X23A | 80G2UH070AE12L | 14,900 | $745 |
| No | 206903282 | DUCANE | 4HP18V36P | EC4X23A | 80G2UH070AE12 | 14,900 | $745 |
| No | 206903281 | DUCANE | 4HP18V36P | EC4X23A | 80G2UH045AE12 | 15,000 | $750 |
| No | 206903280 | DUCANE | 4HP18V36P | EC4X23A | 80G1UH060AE12X | 14,900 | $745 |
| No | 206903279 | DUCANE | 4HP18V36P | EC4X23A | 80G1UH045AE12 | 15,000 | $750 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206903278 | DUCANE | 4HP18V36P | EC4X23A | 80G1UH040AE12X | 14,900 | $745 |
| No | 206903657 | DUCANE | 4HP18V60P | E*1P50C+H4TXV03 | EFV16CCA | 39,500 | $1,975 |
| No | 206903652 | DUCANE | 4HP18V60P | E*1P50C+H4TXV03 | 95G1UH100CE20X | 40,000 | $2,000 |
| No | 206903653 | DUCANE | 4HP18V60P | E*1P50C+H4TXV03 | 95G1UH110CE20 | 40,000 | $2,000 |
| No | 206902830 | DUCANE | 4HP18V36P | E*1P36A+H4TXV02 | 80G2UH070AV12* | 23,000 | $1,150 |
| No | 206902979 | DUCANE | 4HP18V36P | EAH1P48B+H4TXV02 | 96G1UH045BE12 | 22,000 | $1,100 |
| No | 206902904 | DUCANE | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | EFV16CCA | 22,000 | $1,100 |
| No | 206902900 | DUCANE | 4HP18V36P | EA(C,U)1P48C+H4TXV02 | 95G1UH080CE16X | 22,200 | $1,110 |
| No | 206902888 | DUCANE | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 95G1UH040BE12X | 22,200 | $1,110 |
| No | 206902889 | DUCANE | 4HP18V36P | EA(C,U)1P48B+H4TXV02 | 95G1UH060BE12X | 22,200 | $1,110 |
| No | 206902867 | DUCANE | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 96G1UH045BE12 | 22,600 | $1,130 |
| No | 206902866 | DUCANE | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 95G1UH060BE12X | 22,000 | $1,100 |
| No | 206902865 | DUCANE | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 95G1UH040BE12X | 22,000 | $1,100 |
| No | 206902876 | DUCANE | 4HP18V36P | EA(C,U)1P36B+H4TXV02 | 96G1UH070BE12 | 22,600 | $1,130 |
| No | 206903164 | DUCANE | 4HP18V36P | E*1P23B+H4TXV01 | 95G1UH045BE12 | 14,800 | $740 |
| No | 206903165 | DUCANE | 4HP18V36P | E*1P23B+H4TXV01 | 95G1UH070BE12 | 14,900 | $745 |
| No | 206903154 | DUCANE | 4HP18V36P | E*1P23A+H4TXV01 | 80G2UH070AE12L | 14,900 | $745 |
| No | 206903207 | DUCANE | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 95G1UH045BE12 | 15,400 | $770 |
| No | 206903208 | DUCANE | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 95G1UH070BE12 | 15,400 | $770 |
| No | 206903206 | DUCANE | 4HP18V36P | EA(C,U)1P30B+H4TXV01 | 95G1UH040BE12X | 15,500 | $775 |
| No | 206903182 | DUCANE | 4HP18V36P | EA(C,U)1P24B+H4TXV01 | 92G1UH030BE12 | 15,300 | $765 |
| No | 206903173 | DUCANE | 4HP18V36P | EA(C,U)1P24A+H4TXV01 | 80G2UH045AE12 | 15,300 | $765 |
| No | 206903251 | DUCANE | 4HP18V36P | EAC4X30B | 95G1UH070BE12 | 15,400 | $770 |
| No | 206903253 | DUCANE | 4HP18V36P | EAC4X30B | 96G1UH045BE12 | 15,400 | $770 |
| No | 206903249 | DUCANE | 4HP18V36P | EAC4X30B | 95G1UH040BE12X | 15,500 | $775 |
| No | 206903218 | DUCANE | 4HP18V36P | EAC4X24A | 80G2UH070AE12L | 15,200 | $760 |
| No | 206903216 | DUCANE | 4HP18V36P | EAC4X24A | 80G2UH045AE12 | 15,300 | $765 |
| No | 206903271 | DUCANE | 4HP18V36P | EAH1P30B+H4TXV01 | 95G1UH040BE12X | 15,400 | $770 |
| No | 206903273 | DUCANE | 4HP18V36P | EAH1P30B+H4TXV01 | 95G1UH070BE12 | 15,400 | $770 |
| No | 206903272 | DUCANE | 4HP18V36P | EAH1P30B+H4TXV01 | 95G1UH045BE12 | 15,300 | $765 |
| No | 206903300 | DUCANE | 4HP18V36P | ED1P24B+H4TXV01 | 96G2DF045BV12 | 15,100 | $755 |
| No | 206903307 | DUCANE | 4HP18V36P | ED1P24B+H4TXV01 | 96G1DF070BE16 | 15,000 | $750 |
| No | 206903305 | DUCANE | 4HP18V36P | ED1P24B+H4TXV01 | 95G1DF045BE12 | 15,000 | $750 |
| No | 206903299 | DUCANE | 4HP18V36P | ED1P24A+H4TXV01 | 80G2DF070AE12 | 15,100 | $755 |
| No | 206903298 | DUCANE | 4HP18V36P | ED1P24A+H4TXV01 | 80G1DF045AE12 | 15,200 | $760 |
| No | 206903304 | DUCANE | 4HP18V36P | ED1P24B+H4TXV01 | 80G1DF070BE12 | 15,000 | $750 |
| No | 206903009 | DUCANE | 4HP18V36P | EC4X36C | 92G1UH110CE16 | 22,800 | $1,140 |
| No | 206903006 | DUCANE | 4HP18V36P | EC4X36C | 80G2UH110CE16 | 22,800 | $1,140 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206903007 | DUCANE | 4HP18V36P | EC4X36C | 92G1UH090CE12 | 23,000 | $1,150 |
| No | 206903011 | DUCANE | 4HP18V36P | EC4X36C | 95G1UH090CE16 | 23,000 | $1,150 |
| No | 206903008 | DUCANE | 4HP18V36P | EC4X36C | 92G1UH090CE16 | 22,600 | $1,130 |
| No | 206903010 | DUCANE | 4HP18V36P | EC4X36C | 95G1UH080CE16X | 22,800 | $1,140 |
| No | 206903012 | DUCANE | 4HP18V36P | EC4X36C | 96G1UH090CE16 | 22,800 | $1,140 |
| No | 206903013 | DUCANE | 4HP18V36P | EC4X36C | 96G2UH090CV12 | 22,800 | $1,140 |
| No | 206903014 | DUCANE | 4HP18V36P | EC4X36C | EFV16CCA | 22,600 | $1,130 |
| No | 206903002 | DUCANE | 4HP18V36P | EC4X36B | 96G2UH045BV12 | 23,000 | $1,150 |
| No | 206903003 | DUCANE | 4HP18V36P | EC4X36B | 96G2UH070BV12 | 23,000 | $1,150 |
| No | 206903004 | DUCANE | 4HP18V36P | EC4X36B | EFV12BCA | 22,800 | $1,140 |
| No | 206903001 | DUCANE | 4HP18V36P | EC4X36B | 96G1UH070BE12 | 23,200 | $1,160 |
| No | 206902999 | DUCANE | 4HP18V36P | EC4X36B | 92G1UH070BE12 | 23,200 | $1,160 |
| No | 206903000 | DUCANE | 4HP18V36P | EC4X36B | 96G1UH045BE12 | 23,200 | $1,160 |
| No | 206902998 | DUCANE | 4HP18V36P | EC4X36B | 92G1UH045BE12 | 23,200 | $1,160 |
| No | 206902996 | DUCANE | 4HP18V36P | EC4X36B | 80G2UH090BV16* | 22,800 | $1,140 |
| No | 206902997 | DUCANE | 4HP18V36P | EC4X36B | 92G1UH030BE12 | 23,200 | $1,160 |
| No | 206903005 | DUCANE | 4HP18V36P | EC4X36B | 80G2UH090BE16L | 22,800 | $1,140 |
| No | 206902995 | DUCANE | 4HP18V36P | EC4X36B | 80G2UH090BE16 | 22,800 | $1,140 |
| No | 206902994 | DUCANE | 4HP18V36P | EC4X36B | 80G2UH090BE12 | 22,800 | $1,140 |
| No | 206902992 | DUCANE | 4HP18V36P | EC4X36B | 80G1UH080BE16X | 22,800 | $1,140 |
| No | 206902989 | DUCANE | 4HP18V36P | EC4X36A | 80G2UH070AV12* | 23,000 | $1,150 |
| No | 206902991 | DUCANE | 4HP18V36P | EC4X36B | 80G1UH070BE12 | 23,000 | $1,150 |
| No | 206902990 | DUCANE | 4HP18V36P | EC4X36A | 80G2UH070AE12L | 22,800 | $1,140 |
| No | 206902988 | DUCANE | 4HP18V36P | EC4X36A | 80G2UH070AE12 | 22,800 | $1,140 |
| No | 206902986 | DUCANE | 4HP18V36P | EC4X36A | 80G1UH060AE12X | 22,800 | $1,140 |
| No | 206902993 | DUCANE | 4HP18V36P | EC4X36B | 80G1UH090BE16 | 22,800 | $1,140 |
| No | 206902985 | DUCANE | 4HP18V36P | EC4X36A | 80G1UH045AE12 | 23,000 | $1,150 |
| No | 206902987 | DUCANE | 4HP18V36P | EC4X36A | 80G1UH070AE12 | 23,000 | $1,150 |
| No | 206902949 | DUCANE | 4HP18V36P | EAC4X48C | 95G1UH080CE16X | 22,000 | $1,100 |
| No | 206902937 | DUCANE | 4HP18V36P | EAC4X48B | 95G1UH040BE12X | 22,000 | $1,100 |
| No | 206902938 | DUCANE | 4HP18V36P | EAC4X48B | 95G1UH060BE12X | 22,000 | $1,100 |
| No | 208106671 | DUCANE | 4DHP2S24S-1P | DMD224S4-1P | | 13,500 | $675 |
| No | 208106779 | DUCANE | 4DHP2S36S-1P | DMD236S4-2P | | 27,000 | $1,350 |
| No | 208106777 | DUCANE | 4DHP2S36S-1P | D33C236S4-1P | | 23,000 | $1,150 |
| No | 208106778 | DUCANE | 4DHP2S48S-1P | D33C248S4-1P | | 28,000 | $1,400 |
| No | 208106780 | DUCANE | 4DHP2S48S-1P | DMD248S4-2P | | 29,000 | $1,450 |
| No | 208106668 | DUCANE | 4DHP2S24S-1P | D33C224S4-1P | | 15,600 | $780 |
| No | 208106667 | DUCANE | 4DHP2S18S-1P | D22C118S4-1P | | 12,000 | $600 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 209862297 | DUCTLESSAIRE | DA48-5Z-O | Heat pump without ducts | | 36,000 | $1,800 |
| No | 208136324 | DUCTLESSAIRE | DA27-3Z-0* | Heat pump without ducts | | 20,000 | $1,000 |
| No | 208136325 | DUCTLESSAIRE | DA27-3Z-0* | Heat pump with ducts | | 22,000 | $1,100 |
| No | 208136309 | DUCTLESSAIRE | DA2421-H2-O* | DA2421-H2-I* | | 18,000 | $900 |
| No | 209862296 | DUCTLESSAIRE | DA-115-12-20-O | DA-115-12-20-I | | 7,800 | $390 |
| No | 208136307 | DUCTLESSAIRE | DA1221-H2-O* | DA1221-H2-I* | | 8,200 | $410 |
| No | 208136306 | DUCTLESSAIRE | DA0921-H2-O* | DA0921-H2-I* | | 8,300 | $415 |
| No | 208136308 | DUCTLESSAIRE | DA1821-H2-O* | DA1821-H2-I* | | 14,000 | $700 |
| No | 9150139 | DUCTLESSAIRE | DA1821-H2-O | DA1821-H2-I | | 10,400 | $520 |
| No | 208136326 | DUCTLESSAIRE | DA27-3Z-0* | Combination heat pumps with or without ducts | | 16,100 | $805 |
| No | 211911402 | DUOHOME | D5OA-55HFN1-M | Combination heat pumps with or without ducts | | 35,800 | $1,790 |
| No | 211911400 | DUOHOME | D5OA-55HFN1-M | Heat pump without ducts | | 36,400 | $1,820 |
| No | 211911399 | DUOHOME | D5OG-48HFN1-M | Combination heat pumps with or without ducts | | 36,000 | $1,800 |
| No | 211911393 | DUOHOME | D3OJ-27HFN1-M | Combination heat pumps with or without ducts | | 21,000 | $1,050 |
| No | 211911394 | DUOHOME | D4OG-36HFN1-M | Heat pump without ducts | | 26,400 | $1,320 |
| No | 211911391 | DUOHOME | D3OJ-27HFN1-M | Heat pump without ducts | | 20,000 | $1,000 |
| No | 211911392 | DUOHOME | D3OJ-27HFN1-M | Heat pump with ducts | | 22,000 | $1,100 |
| No | 211911390 | DUOHOME | D2OA-18HFN1-M | Combination heat pumps with or without ducts | | 14,600 | $730 |
| No | 211911389 | DUOHOME | D2OA-18HFN1-M | Heat pump with ducts | | 14,800 | $740 |
| No | 211911397 | DUOHOME | D5OG-48HFN1-M | Heat pump without ducts | | 36,000 | $1,800 |
| No | 211911388 | DUOHOME | D2OA-18HFN1-M | Heat pump without ducts | | 14,400 | $720 |
| No | 208121842 | DUOHOME | DOE30U-48HFN1-MP0(GA) | DTI-48HWFN1-M | | 34,000 | $1,700 |
| No | 208121841 | DUOHOME | DOD30U-36HFN1-MP0(GA) | DTI-36HWFN1-M | | 25,000 | $1,250 |
| No | 207178626 | DUOHOME | DOD31-36HFN1-MP0W | DSABF-36HRFNX-MQ0W | | 24,000 | $1,200 |
| No | 208815363 | DUOHOME | DOX430-24HFN1-MR0W | DSAG11D-24HRFN1-MR0W | | 16,500 | $825 |
| No | 208815362 | DUOHOME | DOX330-18HFN1-MS0W | DSAG11C-18HRDN1-MS0W | | 11,400 | $570 |
| No | 208815361 | DUOHOME | DOX230-12HFN1-MS8W | DSAG11B-12HRFN1-MS0W | | 7,000 | $350 |
| No | 208815360 | DUOHOME | DOX230-12HFN1-BS8W | DSAG11B-12HRFN1-BS0W | | 7,800 | $390 |
| No | 207252580 | DUOHOME | DOE30U-48HFN1-MR0 | DVC-48HWFN1-M | | 33,000 | $1,650 |
| No | 207252581 | DUOHOME | DOE30U-60HFN1-MR0 | DVC-60HWFN1-M | | 33,800 | $1,690 |
| No | 206314613 | DUOHOME | DOE30U-60HFN1-M | DHG-60HWFN1-MW | | 37,600 | $1,880 |
| No | 207252579 | DUOHOME | DOD30U-36HFN1-MR0 | DVC-36HWFN1-M | | 18,400 | $920 |
| No | 206314612 | DUOHOME | DOE30U-48HFN1-M | DTI-48HWFN1-M | | 33,400 | $1,670 |
| No | 206314610 | DUOHOME | DOD31-24HFN1-MT0W | DTIU-24HWFN1-M | | 16,000 | $800 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206314611 | DUOHOME | DOD30U-36HFN1-M | DTI-36HWFN1-M | | 27,600 | $1,380 |
| No | 205355547 | DUOHOME | DOBA30-09HFN1-BS0W | DSABA-09HRFN1-BS0W | | 6,000 | $300 |
| No | 205355550 | DUOHOME | DOB30-18HFN1-MS0W | DSABD-18HRFN1-MS0W | | 11,000 | $550 |
| No | 208121840 | DUOHOME | DOE30U-60HFN1-M(GA) | DHG-60HWFN1-MW | | 37,000 | $1,850 |
| No | 210568102 | DURASTAR | DRA1U09S1B | DRAL06F1A | | 5,700 | $285 |
| No | 210568107 | DURASTAR | DRA1U12S1B | DRAL12F1A | | 7,700 | $385 |
| No | 210568104 | DURASTAR | DRA1H12S1A | DRAL12F1A | | 9,500 | $475 |
| No | 210568103 | DURASTAR | DRA1H09S1A | DRAL09F1A | | 9,800 | $490 |
| No | 210568106 | DURASTAR | DRA1U09S1B | DRAL09F1A | | 8,000 | $400 |
| No | 210568108 | DURASTAR | DRA1U18S1B | DRAL18F1A | | 12,200 | $610 |
| No | 210568110 | DURASTAR | DRA1U12S1B | DRAS12F1C | | 9,200 | $460 |
| No | 210568109 | DURASTAR | DRA1H12S1A | DRAS12F1C | | 10,200 | $510 |
| No | 210568210 | DURASTAR | DRA5U55M1B | Combination heat pumps with or without ducts | | 35,800 | $1,790 |
| No | 210568208 | DURASTAR | DRA5U55M1B | Heat pump without ducts | | 36,400 | $1,820 |
| No | 207787182 | DURASTAR | DRA5U48M1B | Combination heat pumps with or without ducts | | 36,000 | $1,800 |
| No | 207787176 | DURASTAR | DRA3U28M1B | Combination heat pumps with or without ducts | | 21,000 | $1,050 |
| No | 207787177 | DURASTAR | DRA4U36M1B | Heat pump without ducts | | 26,400 | $1,320 |
| No | 207787174 | DURASTAR | DRA3U28M1B | Heat pump without ducts | | 20,000 | $1,000 |
| No | 207787175 | DURASTAR | DRA3U28M1B | Heat pump with ducts | | 22,000 | $1,100 |
| No | 207787173 | DURASTAR | DRA2U18M1B | Combination heat pumps with or without ducts | | 14,600 | $730 |
| No | 207787172 | DURASTAR | DRA2U18M1B | Heat pump with ducts | | 14,800 | $740 |
| No | 207787180 | DURASTAR | DRA5U48M1B | Heat pump without ducts | | 36,000 | $1,800 |
| No | 207787171 | DURASTAR | DRA2U18M1B | Heat pump without ducts | | 14,400 | $720 |
| No | 207787141 | DURASTAR | DRA1U18S1B | DRAD18F1A | | 12,600 | $630 |
| No | 207787140 | DURASTAR | DRA1U18S1B | DRAC18F1A | | 12,000 | $600 |
| No | 207787142 | DURASTAR | DRA1U18S1B | DRAF18F1A | | 12,800 | $640 |
| No | 207787132 | DURASTAR | DRA1U18S1B | DRAW18F1B | | 14,100 | $705 |
| No | 207787144 | DURASTAR | DRA1U24S1B | DRAC24F1B | | 19,000 | $950 |
| No | 207787130 | DURASTAR | DRA1U09S1B | DRAW09F1B | | 8,100 | $405 |
| No | 210568097 | DURASTAR | DRA1U09S1B | DRAW06F1B | | 7,500 | $375 |
| No | 207787133 | DURASTAR | DRA1U24S1B | DRAW24F1B | | 17,400 | $870 |
| No | 207787131 | DURASTAR | DRA1U12S1B | DRAW12F1B | | 10,000 | $500 |
| No | 210568100 | DURASTAR | DRA1H18S1A | DRAW18F1B | | 11,100 | $555 |
| No | 210568099 | DURASTAR | DRA1H12S1A | DRAW12F1B | | 10,300 | $515 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210568098 | DURASTAR | DRA1H09S1A | DRAW09F1B | | 9,300 | $465 |
| No | 207787145 | DURASTAR | DRA1U24S1B | DRAD24F1A | | 20,000 | $1,000 |
| No | 210568113 | DURASTAR | DRA1H18S1A | DRAC18F1A | | 15,600 | $780 |
| No | 210568119 | DURASTAR | DRA1H18S1A | DRAF18F1A | | 12,000 | $600 |
| No | 211497017 | DURASTAR | DRA1H12S1A | DRAS12F1B | | 9,600 | $480 |
| No | 210568116 | DURASTAR | DRA1H12S1A | DRAD12F1A | | 10,600 | $530 |
| No | 210568112 | DURASTAR | DRA1H12S1A | DRAC12F1A | | 9,900 | $495 |
| No | 207787139 | DURASTAR | DRA1U12S1B | DRAS12F1B | | 9,000 | $450 |
| No | 207787138 | DURASTAR | DRA1U12S1B | DRAS12F1A | | 9,000 | $450 |
| No | 207787137 | DURASTAR | DRA1U12S1B | DRAD12F1A | | 9,300 | $465 |
| No | 210568115 | DURASTAR | DRA1H09S1A | DRAD09F1A | | 10,100 | $505 |
| No | 210568111 | DURASTAR | DRA1H09S1A | DRAC09F1A | | 9,000 | $450 |
| No | 207787135 | DURASTAR | DRA1U09S1B | DRAD09F1A | | 7,700 | $385 |
| No | 207787146 | DURASTAR | DRA1U24S1B | DRAF24F1A | | 16,000 | $800 |
| No | 207787136 | DURASTAR | DRA1U12S1B | DRAC12F1A | | 8,900 | $445 |
| No | 207787134 | DURASTAR | DRA1U09S1B | DRAC09F1A | | 7,500 | $375 |
| No | 211253518 | ECO AC | EHI-O36BAH | EHI-V36BA | | 30,400 | $1,520 |
| No | 211253517 | ECO AC | EHI-O30BAH | EHI-V30BA | | 21,000 | $1,050 |
| No | 207825504 | ECO AC | EMH-4O36BB | Heat pump without ducts | | 26,400 | $1,320 |
| No | 207825501 | ECO AC | EMH-3O27BB | Heat pump without ducts | | 20,000 | $1,000 |
| No | 207825502 | ECO AC | EMH-3O27BB | Heat pump with ducts | | 22,000 | $1,100 |
| No | 207825499 | ECO AC | EMH-2O18BB | Heat pump with ducts | | 14,800 | $740 |
| No | 207825498 | ECO AC | EMH-2O18BB | Heat pump without ducts | | 14,400 | $720 |
| No | 207825493 | ECO AC | EHH-O24BB | EHH-W24BB | | 18,000 | $900 |
| No | 207825496 | ECO AC | EHH-O18BB | EHH-D18BA | | 12,600 | $630 |
| No | 210586148 | ECO AC | EHH-O18BB | EHH-C18BA | | 12,000 | $600 |
| No | 207825491 | ECO AC | EHH-O12BB | EHH-W12BB | | 8,200 | $410 |
| No | 207826045 | ECO AC | EHH-O09BB | EHH-W09BB | | 8,300 | $415 |
| No | 207825490 | ECO AC | EHH-O9BB | EHH-W09BB | | 8,300 | $415 |
| No | 207825492 | ECO AC | EHH-O18BB | EHH-W18BB | | 14,000 | $700 |
| No | 207825489 | ECO AC | EHS-O18BB | EHS-W18BB | | 11,500 | $575 |
| No | 207825487 | ECO AC | EHS-O9BB | EHS-W09BB | | 6,900 | $345 |
| No | 207826044 | ECO AC | EHS-O09BB | EHS-W09BB | | 6,900 | $345 |
| No | 210586150 | ECO AC | EHH-O36BB | EHH-D36BA | | 25,000 | $1,250 |
| No | 206902027 | ECO AC | EHH-O24BA | EHH-D24BA | | 20,000 | $1,000 |
| No | 207825497 | ECO AC | EHH-O24BB | EHH-D24BA | | 20,000 | $1,000 |
| No | 207825495 | ECO AC | EHH-O12BB | EHH-D12BA | | 9,300 | $465 |
| No | 207825494 | ECO AC | EHH-O9BB | EHH-D09BA | | 7,700 | $385 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207826046 | ECO AC | EHH-O09BB | EHH-D09BA | | 7,700 | $385 |
| No | 210586147 | ECO AC | EHH-O12BB | EHH-C12BA | | 8,900 | $445 |
| No | 210586146 | ECO AC | EHH-O09BB | EHH-C09BA | | 7,500 | $375 |
| No | 206902026 | ECO AC | EHH-O18BA | EHH-D18BA | | 12,000 | $600 |
| No | 206902023 | ECO AC | EHH-O18BA | EHH-W18BA | | 10,400 | $520 |
| No | 206902024 | ECO AC | EHH-O09BA | EHH-D09BA | | 6,800 | $340 |
| No | 206902020 | ECO AC | EHS-O18BA | EHS-W18BA | | 11,000 | $550 |
| No | 207825503 | ECO AC | EMH-3O27BB | Combination heat pumps with or without ducts | | 16,100 | $805 |
| No | 207825500 | ECO AC | EMH-2O18BB | Combination heat pumps with or without ducts | | 11,800 | $590 |
| No | 209319635 | ECO AIR | M5OA-55HFN1-M | Heat pump without ducts | | 34,400 | $1,720 |
| No | 209270317 | ECO-AIR | MOE30U-48HFN1-MR0 | MAC-48HWFN1-M | | 30,400 | $1,520 |
| No | 211644092 | ECO-AIR | MOX230-09HFN1-MW5W | MCBU-06HRFN1-MV0W | | 5,700 | $285 |
| No | 211644094 | ECO-AIR | MOX330-12HFN1-MW5W | MCBU-12HRFN1-MV0W | | 9,500 | $475 |
| No | 211644093 | ECO-AIR | MOX330-09HFN1-MY5W | MCBU-09HRFN1-MW0W | | 9,800 | $490 |
| No | 211644091 | ECO-AIR | MOX430-18HFN1-MU0W | MFA2U-16HRFN1-MV0W | | 13,400 | $670 |
| No | 211644090 | ECO-AIR | MOX230-12HFN1-MV5W | MFA2U-12HRFN1-MW5W | | 9,200 | $460 |
| No | 211644055 | ECO-AIR | MOE30U-60HFN1-M(GA)(X) | MHG-60HWFN1-MW | | 34,400 | $1,720 |
| No | 211644051 | ECO-AIR | MOX430-18HFN1-MU0W | MTIU-18HWFN1-M | | 12,600 | $630 |
| No | 211644058 | ECO-AIR | MOX430-18HFN1-MU0W | CCA3U-18HRFN1-M(C) | | 12,000 | $600 |
| No | 211644059 | ECO-AIR | MOD33-24HFN1-MT0W | MCD1-24HRFN1-MT0W(GA) | | 19,000 | $950 |
| No | 211644066 | ECO-AIR | MOE30U-36HFN1-M(GA) | MTI-36HWFN1-M | | 34,000 | $1,700 |
| No | 211644054 | ECO-AIR | MOE30U-48HFN1-MP0(GA) | MTI-48HWFN1-M | | 34,000 | $1,700 |
| No | 211644061 | ECO-AIR | MOE30U-48HFN1-MP0(GA) | MCD1-48HRFN1-M(GA) | | 30,000 | $1,500 |
| No | 211644053 | ECO-AIR | MOD30U-36HFN1-MP0(GA) | MTI-36HWFN1-M | | 25,000 | $1,250 |
| No | 211644060 | ECO-AIR | MOD30U-36HFN1-MP0(GA) | MCD1-36HRFN1-M(GA) | | 23,000 | $1,150 |
| No | 211644052 | ECO-AIR | MOD33-24HFN1-MT0W | MTIU-24HWFN1-M | | 20,000 | $1,000 |
| No | 211644070 | ECO-AIR | MOX430-17HFN1-MT0W | CCA3U-18HRFN1-M(C) | | 15,600 | $780 |
| No | 211644063 | ECO-AIR | MOX330-12HFN1-MW5W | MTIU-12HWFN1-M | | 10,600 | $530 |
| No | 211644069 | ECO-AIR | MOX330-12HFN1-MW5W | CCA3U-12HRFN1-M(C) | | 9,900 | $495 |
| No | 211644050 | ECO-AIR | MOX230-12HFN1-MV5W | MTIU-12HWFN1-M | | 9,300 | $465 |
| No | 211644062 | ECO-AIR | MOX330-09HFN1-MY5W | MTIU-09HWFN1-M | | 10,100 | $505 |
| No | 211644068 | ECO-AIR | MOX330-09HFN1-MY5W | CCA3U-09HRFN1-M(C) | | 9,000 | $450 |
| No | 211644049 | ECO-AIR | MOX230-09HFN1-MW5W | MTIU-09HWFN1-M | | 7,700 | $385 |
| No | 211644057 | ECO-AIR | MOX230-12HFN1-MV5W | CCA3U-12HRFN1-M(C) | | 8,900 | $445 |
| No | 211644056 | ECO-AIR | MOX230-09HFN1-MW5W | CCA3U-09HRFN1-M(C) | | 7,500 | $375 |
| No | 211644111 | ECO-AIR | MOD30U-36HFN1-M(GA) | MVCU-36HWFN1-M(GA) | | 27,000 | $1,350 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 209270323 | ECO-AIR | MOE30U-48HFN1-M-[X1] | MAC-48HWFN1-M | | 32,000 | $1,600 |
| No | 208130401 | ECO-AIR | MOE30U-60HFN1-MR0 | MVC-60HWFN1-M | | 37,000 | $1,850 |
| No | 208130400 | ECO-AIR | MOE30U-48HFN1-MR0 | MVC-48HWFN1-M | | 37,000 | $1,850 |
| No | 208130399 | ECO-AIR | MOD30U-36HFN1-MR0 | MVC-36HWFN1-M | | 20,400 | $1,020 |
| No | 208130397 | ECO-AIR | MOX430U-24HFN1-MR0 | MVC-24HWFN1-M | | 21,000 | $1,050 |
| No | 208130396 | ECO-AIR | MOX330U-18HFN1-MR0 | MVC-18HWFN1-M | | 12,000 | $600 |
| No | 211644110 | ECO-AIR | MOD30U-30HFN1-M(GA) | MVC-30HWFN1-M(GA) | | 20,400 | $1,020 |
| No | 211644109 | ECO-AIR | MOD33-24HFN1-MT0W | MVC-23HWFN1-M | | 17,000 | $850 |
| No | 211644108 | ECO-AIR | MOX430-18HFN1-MU0W | MVC-18HWFN1-MW(GA) | | 13,200 | $660 |
| No | 208130405 | ECO-AIR | MOE31U-36HFN1-M | MVC-36HWFN1-M | | 30,400 | $1,520 |
| No | 208130404 | ECO-AIR | MOD30U-30HFN1-MR0(X) | MVC-30HWFN1-M | | 21,000 | $1,050 |
| No | 209270313 | ECO-AIR | MOX330-18HFN1-MR0 | MAC-24HWDN1-MN0 | | 13,000 | $650 |
| No | 209270322 | ECO-AIR | MOE31U-36HFN1-M | MAC-36HWFN1-M | | 33,000 | $1,650 |
| No | 209270316 | ECO-AIR | MOD30U-36HFN1-MR0 | MAC-36HWFN1-M | | 19,800 | $990 |
| No | 209270320 | ECO-AIR | MOD30-24HFN1-MW | MAC-24HWDN1-MN0 | | 21,000 | $1,050 |
| No | 209270319 | ECO-AIR | MOX430U-18HFN1-M | MAC-24HWDN1-MN0 | | 14,700 | $735 |
| No | 209270318 | ECO-AIR | MOE30U-60HFN1-MR0 | MAC-60HWDN1-MN0 | | 34,000 | $1,700 |
| No | 209270315 | ECO-AIR | MOD30U-30HFN1-MR0 | MAC-36HWFN1-M | | 22,000 | $1,100 |
| No | 209270314 | ECO-AIR | MOX430U-24HFN1-MR0 | MAC-24HWDN1-MN0 | | 22,000 | $1,100 |
| No | 208121877 | ECO-AIR | M5OG-48HFN1-M | Heat pump without ducts | | 34,000 | $1,700 |
| No | 208121874 | ECO-AIR | M4OG-36HFN1-M | Heat pump without ducts | | 26,800 | $1,340 |
| No | 208121872 | ECO-AIR | M3OJ-27HFN1-M | Heat pump with ducts | | 22,000 | $1,100 |
| No | 208121869 | ECO-AIR | M2OA-18HFN1-M | Heat pump with ducts | | 14,800 | $740 |
| No | 208121871 | ECO-AIR | M3OJ-27HFN1-M | Heat pump without ducts | | 21,000 | $1,050 |
| No | 208121868 | ECO-AIR | M2OA-18HFN1-M | Heat pump without ducts | | 14,300 | $715 |
| No | 208121849 | ECO-AIR | MOD30U-30HFN1-M(GA) | MSAGF-30HRFN1-MT0W | | 20,000 | $1,000 |
| No | 208121857 | ECO-AIR | MOD31-23HFN1-MT2Q1W | MSABE-23HRFN1-MT2Q1W | | 17,900 | $895 |
| No | 208121856 | ECO-AIR | MOX430-18HFN1-MT2Q1W | MSABE-18HRFN1-MT2Q1W | | 13,800 | $690 |
| No | 208121855 | ECO-AIR | MOX230-12HFN1-BV0Q1W | MSABB-12HRFN1-BV0Q1W | | 7,500 | $375 |
| No | 208121863 | ECO-AIR | MOX230-09HFN1-MW5W | MSEPB-06HRFN1-MY5W | | 8,500 | $425 |
| No | 208121862 | ECO-AIR | MOD33-24HFN1-MT0W | MSEPD-24HRFN1-MU0W | | 16,200 | $810 |
| No | 208121860 | ECO-AIR | MOX230-12HFN1-MV5W | MSEPB-12HRFN1-MW5W(GA) | | 9,000 | $450 |
| No | 208121859 | ECO-AIR | MOX230-09HFN1-MW5W | MSEPB-09HRFN1-MY5W(GA) | | 8,500 | $425 |
| No | 208121848 | ECO-AIR | MOX430-24HFN1-MR0W | MSAG11D-24HRFN1-MR0W | | 16,500 | $825 |
| No | 208121847 | ECO-AIR | MOX330-18HFN1-MS0W | MSAG11C-18HRDN1-MS0W | | 11,400 | $570 |
| No | 208121846 | ECO-AIR | MOX230-12HFN1-MS8W | MSAG11B-12HRFN1-MS0W | | 7,000 | $350 |
| No | 208121845 | ECO-AIR | MOX230-09HFN1-MT0W | MSAG11A-09HRFN1-MT0W | | 6,000 | $300 |
| No | 208121844 | ECO-AIR | MOX230-12HFN1-BS8W | MSAG11B-12HRFN1-BS0W | | 7,800 | $390 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208121843 | ECO-AIR | MOX230-09HFN1-BS5W | MSAG11A-09HRFN1-BS5W | | 6,300 | $315 |
| No | 208121865 | ECO-AIR | MOX330-12HFN1-MW5W | MSEPB-12HRFN1-MW5W(GA) | | 10,000 | $500 |
| No | 208121864 | ECO-AIR | MOX330-09HFN1-MY5W | MSEPB-09HRFN1-MY5W(GA) | | 9,500 | $475 |
| No | 208121879 | ECO-AIR | M5OG-48HFN1-M | Combination heat pumps with or without ducts | | 30,000 | $1,500 |
| No | 208121878 | ECO-AIR | M5OG-48HFN1-M | Heat pump with ducts | | 30,400 | $1,520 |
| No | 208121858 | ECO-AIR | MOD30-36HFN1-MR0Q1W | MSABF-36HRFN1-MR0Q1W | | 21,000 | $1,050 |
| No | 208121861 | ECO-AIR | MOX430-18HFN1-MT8W | MSEPC-18HRFN1-MU0W | | 12,700 | $635 |
| No | 208121873 | ECO-AIR | M3OJ-27HFN1-M | Combination heat pumps with or without ducts | | 16,000 | $800 |
| No | 208121870 | ECO-AIR | M2OA-18HFN1-M | Combination heat pumps with or without ducts | | 11,400 | $570 |
| No | 208121850 | ECO-AIR | MOD31-36HFN1-MP0W | MSAGF-36HRFNX-MR0W | | 20,000 | $1,000 |
| No | 208130398 | ECO-AIR | MOD30U-30HFN1-MR0 | MVC-30HWFN1-M | | 19,000 | $950 |
| No | 209319637 | ECO-AIR | M5OA-55HFN1-M | Combination heat pumps with or without ducts | | 34,600 | $1,730 |
| No | 209319636 | ECO-AIR | M5OA-55HFN1-M | Heat pump with ducts | | 35,000 | $1,750 |
| No | 209319643 | ECO-AIR | M3OI-28HFN1-M | Combination heat pumps with or without ducts | | 17,000 | $850 |
| No | 209319640 | ECO-AIR | M2OI-18HFN1-M | Combination heat pumps with or without ducts | | 11,500 | $575 |
| No | 211594473 | Ecoer | ESCA16H-36 | EAHAEC-36 | | 30,400 | $1,520 |
| No | 207252613 | ECOER | EODA18H-4860 | GNC4860DPT | MGH96M120D5A | 35,000 | $1,750 |
| No | 207252612 | ECOER | EODA18H-4860 | GNC4860CPT | MGH96M100C5A | 35,000 | $1,750 |
| No | 207252611 | ECOER | EODA18H-4860 | GNC4248CPT | MGH96M100C5A | 30,000 | $1,500 |
| No | 207252617 | ECOER | EODA18H-4860 | GNC3036BPT | MGH96M060B3A | 28,000 | $1,400 |
| No | 207252610 | ECOER | EODA18H-4860 | GNC3036BPT | MGH96M080B3A | 28,000 | $1,400 |
| No | 207252616 | ECOER | EODA18H-2436 | GNC3036BPT | MGH96M060B3A | 25,000 | $1,250 |
| No | 207252609 | ECOER | EODA18H-2436 | GNC3036BPT | MGH96M080B3A | 25,000 | $1,250 |
| No | 207252615 | ECOER | EODA18H-2436 | GNC2430BPT | MGH96M060B3A | 18,600 | $930 |
| No | 207252614 | ECOER | EODA18H-2436 | GNC2430BPT | MGH96M080B3A | 18,600 | $930 |
| No | 207252608 | ECOER | EODA18H-2436 | GNC2430APT | MGH96M080B3A | 18,600 | $930 |
| No | 208141158 | ECOER | EODA18H-4860B | GNC4860DPT | MGH96M100D5A | 41,000 | $2,050 |
| No | 208141157 | ECOER | EODA18H-4860B | GNC4860DPT | MGH96M120D5A | 41,000 | $2,050 |
| No | 208141156 | ECOER | EODA18H-4860B | GNC4860CPT | MGH96M100C5A | 41,000 | $2,050 |
| No | 208141155 | ECOER | EODA18H-4860B | GNC4248CPT | MGH96M080C4A | 37,000 | $1,850 |
| No | 208141154 | ECOER | EODA18H-4860B | GNC4248CPT | MGH96M100C5A | 38,000 | $1,900 |
| No | 208141153 | ECOER | EODA18H-4860B | GNC3036BPT | MGH96M060B3A | 28,000 | $1,400 |
| No | 208141152 | ECOER | EODA18H-4860B | GNC3036BPT | MGH96M080B3A | 28,000 | $1,400 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208141151 | ECOER | EODA18H-2436B | GNC4248CPT | MGH96M080C4A | 25,600 | $1,280 |
| No | 208141150 | ECOER | EODA18H-2436B | GNC4248CPT | MGH96M100C5A | 25,600 | $1,280 |
| No | 208141149 | ECOER | EODA18H-2436B | GNC3036BPT | MGH96M060B3A | 27,600 | $1,380 |
| No | 208141148 | ECOER | EODA18H-2436B | GNC3036BPT | MGH96M080B3A | 27,600 | $1,380 |
| No | 208141147 | ECOER | EODA18H-2436B | GNC2430BPT | MGH96M060B3A | 23,600 | $1,180 |
| No | 208141145 | ECOER | EODA18H-2436B | GNC2430BPT | MGH96M080B3A | 23,600 | $1,180 |
| No | 208141146 | ECOER | EODA18H-2436B | GNC2430APT | MGH96M060B3A | 22,400 | $1,120 |
| No | 208141144 | ECOER | EODA18H-2436B | GNC2430APT | MGH96M080B3A | 22,400 | $1,120 |
| No | 207861766 | ECOER | EODA18H-4860B | GNC4860DPT | | 42,000 | $2,100 |
| No | 207861765 | ECOER | EODA18H-4860B | GNC4860CPT | | 42,000 | $2,100 |
| No | 207861764 | ECOER | EODA18H-4860B | GNC4248CPT | | 38,000 | $1,900 |
| No | 207861763 | ECOER | EODA18H-2436B | GNC3036BPT | | 25,600 | $1,280 |
| No | 207861762 | ECOER | EODA18H-2436B | GNC2430BPT | | 21,000 | $1,050 |
| No | 207861761 | ECOER | EODA18H-2436B | GNC2430APT | | 21,000 | $1,050 |
| No | 207861760 | ECOER | EODA18H-4860B | EAHATN-60B | | 42,000 | $2,100 |
| No | 207861759 | ECOER | EODA18H-4860B | EAHATN-48B | | 39,000 | $1,950 |
| No | 207861758 | ECOER | EODA18H-4860B | EAHATN-36B | | 32,000 | $1,600 |
| No | 207861757 | ECOER | EODA18H-2436B | EAHATN-36B | | 27,600 | $1,380 |
| No | 207861756 | ECOER | EODA18H-2436B | EAHATN-24B | | 22,400 | $1,120 |
| No | 203376745 | ECOER | EODA18H-4860 | GNC4860DPT | | 39,000 | $1,950 |
| No | 203376744 | ECOER | EODA18H-4860 | GNC4860CPT | | 39,000 | $1,950 |
| No | 203376743 | ECOER | EODA18H-4860 | GNC4248CPT | | 33,000 | $1,650 |
| No | 203376742 | ECOER | EODA18H-2436 | GNC3036BPT | | 22,000 | $1,100 |
| No | 206395296 | ECOER | EODA18H-2436 | GNC2430BPT | | 15,400 | $770 |
| No | 203376741 | ECOER | EODA18H-2436 | GNC2430APT | | 15,400 | $770 |
| No | 202110527 | ECOER | EODA18H-4860 | EAHATN-60 | | 35,600 | $1,780 |
| No | 202337970 | ECOER | EODA18H-4860 | EAHATN-48 | | 32,000 | $1,600 |
| No | 202110529 | ECOER | EODA18H-4860 | EAHATN-36 | | 24,000 | $1,200 |
| No | 202110525 | ECOER | EODA18H-2436 | EAHATN-36 | | 24,000 | $1,200 |
| No | 202337969 | ECOER | EODA18H-2436 | EAHATN-24 | | 19,200 | $960 |
| No | 202110530 | ECOER | EODA18H-4860 | GN1836-P1 | | 24,000 | $1,200 |
| No | 202110526 | ECOER | EODA18H-2436 | GN1836-P1 | | 24,000 | $1,200 |
| No | 202110528 | ECOER | EODA18H-4860 | GN1860-P1 | | 35,600 | $1,780 |
| No | 210474688 | ECOX | EDIM024H21B | EDIM024H21B | | 16,500 | $825 |
| No | 210474694 | ECOX | EDIM018H21B | EDIM018H21B | | 11,400 | $570 |
| No | 210474689 | ECOX | EDIM012H21B | EDIM012H21B | | 7,000 | $350 |
| No | 210474690 | ECOX | EDIM009H21B | EDIM009H21B | | 6,000 | $300 |
| No | 210474691 | ECOX | EDIM012H21A | EDIM012H21A | | 7,800 | $390 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210474692 | ECOX | EDIM009H21A | EDIM009H21A | | 6,300 | $315 |
| No | 208136310 | ELIOS | DEA55HOM23230X2 | Heat pump without ducts | | 34,400 | $1,720 |
| No | 207742481 | ELIOS | DEA48HOM23230X2 | Heat pump without ducts | | 34,000 | $1,700 |
| No | 207742478 | ELIOS | DEA36HOM23230X2 | Heat pump without ducts | | 26,800 | $1,340 |
| No | 207742476 | ELIOS | DEA27HOM23230X2 | Heat pump with ducts | | 22,000 | $1,100 |
| No | 207742473 | ELIOS | DEA18HOM23230X2 | Heat pump with ducts | | 14,800 | $740 |
| No | 207742475 | ELIOS | DEA27HOM23230X2 | Heat pump without ducts | | 21,000 | $1,050 |
| No | 207742472 | ELIOS | DEA18HOM23230X2 | Heat pump without ducts | | 14,300 | $715 |
| No | 207824534 | ELIOS | DEA18HOS28230E8 | DUA24HIDU230X5 | | 15,800 | $790 |
| No | 207742447 | ELIOS | DEA18HOS25230E8 | DUA18HIDU230X5 | | 12,600 | $630 |
| No | 207742435 | ELIOS | DEA18HOS25230E8 | DUA18HICU230X5 | | 12,000 | $600 |
| No | 207742426 | ELIOS | DEA18HOS25230E8 | DEA18HIW25230E8 | | 14,900 | $745 |
| No | 207742420 | ELIOS | DEA18HOS21230S1 | DEA18HIW21230S1 | | 11,500 | $575 |
| No | 207742418 | ELIOS | DEA09HOS21115S1 | DEA09HIW21115S1 | | 6,800 | $340 |
| No | 207742436 | ELIOS | DEA24HOS25230E8 | DUA24HICU230X5 | | 19,000 | $950 |
| No | 207742456 | ELIOS | DEA36HOS28230E8 | DUA36HIDU230X5 | | 34,000 | $1,700 |
| No | 207742450 | ELIOS | DEA48HOS18230S5 | DUA48HIDU230X5 | | 34,000 | $1,700 |
| No | 207742438 | ELIOS | DEA48HOS18230S5 | DUA48HICU230X5 | | 30,000 | $1,500 |
| No | 207742449 | ELIOS | DEA36HOS18230S5 | DUA36HIDU230X5 | | 25,000 | $1,250 |
| No | 207742437 | ELIOS | DEA36HOS18230S5 | DUA36HICU230X5 | | 23,000 | $1,150 |
| No | 207742428 | ELIOS | DEA06HOS28230E8 | DEA06HIW25230E8 | | 8,500 | $425 |
| No | 208075830 | ELIOS | DEA09HOS25230E8 | DEA06HIW25230E8 | | 8,500 | $425 |
| No | 207742423 | ELIOS | DEA36HOS21230S1 | DEA36HIW21230S1 | | 24,000 | $1,200 |
| No | 207742427 | ELIOS | DEA24HOS25230E8 | DEA24HIW25230E8 | | 16,200 | $810 |
| No | 207742425 | ELIOS | DEA12HOS25230E8 | DEA12HIW25230E8 | | 9,000 | $450 |
| No | 207742424 | ELIOS | DEA09HOS25230E8 | DEA09HIW25230E8 | | 8,500 | $425 |
| No | 207742448 | ELIOS | DEA24HOS25230E8 | DUA24HIDU230X5 | | 20,000 | $1,000 |
| No | 206401447 | ELIOS | DE18HOS25230E3A | DM18HICU230X5 | | 15,600 | $780 |
| No | 207742441 | ELIOS | DEA18HOS28230E8 | DUA18HICU230X5 | | 15,600 | $780 |
| No | 207742458 | ELIOS | DEA12HOS28230E8 | DUA12HIFU230E5 | | 9,600 | $480 |
| No | 207742453 | ELIOS | DEA12HOS28230E8 | DUA12HIDU230X5 | | 10,600 | $530 |
| No | 207742440 | ELIOS | DEA12HOS28230E8 | DUA12HICU230X5 | | 9,900 | $495 |
| No | 207742459 | ELIOS | DEA12HOS25230E8 | DUA12HIFU230E5 | | 9,000 | $450 |
| No | 207742446 | ELIOS | DEA12HOS25230E8 | DUA12HIDU230X5 | | 9,300 | $465 |
| No | 207742452 | ELIOS | DEA09HOS28230E8 | DUA09HIDU230X5 | | 10,100 | $505 |
| No | 207742439 | ELIOS | DEA09HOS28230E8 | DUA09HICU230X5 | | 9,000 | $450 |
| No | 207742445 | ELIOS | DEA09HOS25230E8 | DUA09HIDU230X5 | | 7,700 | $385 |
| No | 207742434 | ELIOS | DEA12HOS25230E8 | DUA12HICU230X5 | | 8,900 | $445 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207742433 | ELIOS | DEA09HOS25230E8 | DUA09HICU230X5 | | 7,500 | $375 |
| No | 207742430 | ELIOS | DEA12HOS28230E8 | DEA12HIW25230E8 | | 10,000 | $500 |
| No | 207742429 | ELIOS | DEA09HOS28230E8 | DEA09HIW25230E8 | | 9,500 | $475 |
| No | 205300181 | ELIOS | DE36HOS18230E5 | DM36HICU230X5 | | 25,200 | $1,260 |
| No | 205300184 | ELIOS | DE12HOS25230E3 | DM12HICU230X5 | | 8,700 | $435 |
| No | 205300182 | ELIOS | DE48HOS18230E5 | DM48HICU230X5 | | 35,000 | $1,750 |
| No | 205300180 | ELIOS | DE24HOS23230E2 | DM24HICU230X5 | | 15,800 | $790 |
| No | 205300178 | ELIOS | DE12HOS23230E2 | DM12HICU230X5 | | 7,500 | $375 |
| No | 205300179 | ELIOS | DE18HOS23230E2 | DM18HICU230X5 | | 12,000 | $600 |
| No | 205300177 | ELIOS | DE09HOS23230E2 | DM09HICU230X5 | | 5,800 | $290 |
| No | 205300174 | ELIOS | DE12HOS25230E3 | DM12HIDU230X5 | | 8,500 | $425 |
| No | 205300173 | ELIOS | DE09HOS25230E3 | DM09HIDU230X5 | | 7,200 | $360 |
| No | 205300171 | ELIOS | DE48HOS18230E5 | DM48HIDU230X5 | | 33,400 | $1,670 |
| No | 205300172 | ELIOS | DE60HOS18230E5 | DM60HIDU230X5 | | 37,600 | $1,880 |
| No | 205300170 | ELIOS | DE36HOS18230E5 | DM36HIDU230X5 | | 27,600 | $1,380 |
| No | 205300169 | ELIOS | DE24HOS23230E2 | DM24HIDU230X5 | | 16,000 | $800 |
| No | 205300168 | ELIOS | DE18HOS23230E2 | DM18HIDU230X5 | | 12,000 | $600 |
| No | 205300166 | ELIOS | DE09HOS23230E2 | DM09HIDU230X5 | | 6,800 | $340 |
| No | 203238504 | ELIOS | DE18HOM23230X2 | Heat pump without ducts | | 12,000 | $600 |
| No | 205782170 | ELIOS | DE12HOS23230E2 | DM12HIFU230E5 | | 7,200 | $360 |
| No | 203238486 | ELIOS | DE09HOS23230E2 | DE09HIW23230E3 | | 5,800 | $290 |
| No | 204005774 | ELIOS | DE09HOS25230E3 | DE09HIW23230E3 | | 6,900 | $345 |
| No | 203238487 | ELIOS | DE12HOS23230E2 | DE12HIW23230E3 | | 7,700 | $385 |
| No | 204005775 | ELIOS | DE12HOS25230E3 | DE12HIW23230E3 | | 7,800 | $390 |
| No | 203238490 | ELIOS | DE24HOS23230E2 | DE24HIW23230E3 | | 15,300 | $765 |
| No | 203238488 | ELIOS | DE18HOS23230E2 | DE18HIW23230E3 | | 11,400 | $570 |
| No | 202635790 | ELIOS | DE18HOS19230S1 | DE18HIW19230S1 | | 11,000 | $550 |
| No | 202635787 | ELIOS | DE09HOS19115S1 | DE09HIW19115S1 | | 6,000 | $300 |
| No | 203238492 | ELIOS | DE09HOS23230E2 | DE09HIDU230X5 | | 6,800 | $340 |
| No | 204005778 | ELIOS | DE09HOS25230E3 | DE09HIDU230X5 | | 7,200 | $360 |
| No | 204005779 | ELIOS | DE12HOS25230E3 | DE12HIDU230X5 | | 8,500 | $425 |
| No | 203238495 | ELIOS | DE18HOS23230E2 | DE18HIDU230X5 | | 12,000 | $600 |
| No | 203238496 | ELIOS | DE24HOS23230E2 | DE24HIDU230X5 | | 16,000 | $800 |
| No | 202635809 | ELIOS | DE36HOS18230E5 | DE36HIDU230X5 | | 27,600 | $1,380 |
| No | 202635791 | ELIOS | DE48HOS18230E5 | DE48HIDU230X5 | | 33,400 | $1,670 |
| No | 202635792 | ELIOS | DE60HOS18230E5 | DE60HIDU230X5 | | 37,600 | $1,880 |
| No | 203238498 | ELIOS | DE09HOS23230E2 | DE09HICU230X5 | | 5,800 | $290 |
| No | 204005783 | ELIOS | DE12HOS25230E3 | DE12HICU230X5 | | 8,700 | $435 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203238499 | ELIOS | DE12HOS23230E2 | DE12HICU230X5 | | 7,500 | $375 |
| No | 203238506 | ELIOS | DE27HOM23230X2 | Heat pump without ducts | | 17,200 | $860 |
| No | 203238501 | ELIOS | DE18HOS23230E2 | DE18HICU230X5 | | 12,000 | $600 |
| No | 203238503 | ELIOS | DE24HOS23230E2 | DE24HICU230X5 | | 15,800 | $790 |
| No | 202635793 | ELIOS | DE36HOS18230E5 | DE36HICU230X5 | | 25,200 | $1,260 |
| No | 202635794 | ELIOS | DE48HOS18230E5 | DE48HICU230X5 | | 35,000 | $1,750 |
| No | 203238787 | ELIOS | DE36HOM23230X2 | Heat pump without ducts | | 24,600 | $1,230 |
| No | 204005786 | ELIOS | DE36HOM25230X3 | Heat pump without ducts | | 23,200 | $1,160 |
| No | 203238508 | ELIOS | DE48HOM23230X2 | Heat pump without ducts | | 29,600 | $1,480 |
| No | 204005791 | ELIOS | DE36HOM25230X3 | Heat pump with ducts | | 24,600 | $1,230 |
| No | 206377757 | ELIOS | DE12HOS42230E4 | DE12HIW42230E4 | | 6,800 | $340 |
| No | 206377755 | ELIOS | DE09HOS42230E4 | DE09HIW42230E4 | | 7,200 | $360 |
| No | 206401450 | ELIOS | DE24HOS25230E3A | DM24HICU230X5 | | 14,500 | $725 |
| No | 206401445 | ELIOS | DE18HOS25230E3A | DE18HIW23230E3 | | 10,900 | $545 |
| No | 207742482 | ELIOS | DEA48HOM23230X2 | Heat pump with ducts | | 30,400 | $1,520 |
| No | 208119830 | ELIOS | DEA18HOS28230E8 | DE18HIW23230E3 | | 10,900 | $545 |
| No | 208119828 | ELIOS | DEA09HOS28230E8 | DE09HIW23230E3 | | 7,100 | $355 |
| No | 208119829 | ELIOS | DEA12HOS28230E8 | DE12HIW23230E3 | | 7,500 | $375 |
| No | 208136312 | ELIOS | DEA55HOM23230X2 | Combination heat pumps with or without ducts | | 34,600 | $1,730 |
| No | 208136311 | ELIOS | DEA55HOM23230X2 | Heat pump with ducts | | 35,000 | $1,750 |
| No | 207742462 | ELIOS | DEA18HOM25230X3 | Combination heat pumps with or without ducts | | 11,500 | $575 |
| No | 207742477 | ELIOS | DEA27HOM23230X2 | Combination heat pumps with or without ducts | | 16,000 | $800 |
| No | 207742483 | ELIOS | DEA48HOM23230X2 | Combination heat pumps with or without ducts | | 30,000 | $1,500 |
| No | 207742474 | ELIOS | DEA18HOM23230X2 | Combination heat pumps with or without ducts | | 11,400 | $570 |
| No | 207742465 | ELIOS | DEA27HOM25230X3 | Combination heat pumps with or without ducts | | 17,000 | $850 |
| No | 207742451 | ELIOS | DEA60HOS18230S5 | DUA60HIDU230X5 | | 37,000 | $1,850 |
| No | 10298957 | EMERSON QUIET KOOL | HP-22EACH12R2O | HP-22EACH12R2I | | 7,800 | $390 |
| No | 10298958 | EMERSON QUIET KOOL | HP-20EACH18R2O | HP-20EACH18R2I | | 10,800 | $540 |
| No | 10298956 | EMERSON QUIET KOOL | HP-25EACH09R2O | HP-25EACH09R2I | | 6,900 | $345 |
| No | 208121923 | EMI | MHSZ106DA | MHWAL06DA | | 8,500 | $425 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208121922 | EMI | ADSZ136DA | ADWAL36DA | | 24,000 | $1,200 |
| No | 208121930 | EMI | MHSZ118DA | MHCAS18DA | | 15,600 | $780 |
| No | 208121929 | EMI | MHSZ112DA | MHCAS12DA | | 9,900 | $495 |
| No | 208121928 | EMI | MHSZ109DA | MHCAS09DA | | 9,000 | $450 |
| No | 208121925 | EMI | MHSZ112DA | MHWAL12DA | | 10,000 | $500 |
| No | 208121924 | EMI | MHSZ109DA | MHWAL09DA | | 9,500 | $475 |
| No | 8993368 | EMI | SZ1H18DAA | CASH18DAA | | 12,000 | $600 |
| No | 204853574 | EMI | MZ5H45DAA | Heat pump without ducts | | 29,600 | $1,480 |
| No | 204853571 | EMI | MZ2H18DAA | Heat pump without ducts | | 12,000 | $600 |
| No | 8993364 | EMI | SZ1H09DAA | CASH09DAA | | 5,800 | $290 |
| No | 8993367 | EMI | SZ1H18DAA | WALH18DAA | | 10,400 | $520 |
| No | 8993363 | EMI | SZ1H09DAA | WALH09DAA | | 6,400 | $320 |
| No | 205123803 | EMI | MZ4H36DAA | Heat pump without ducts | | 24,600 | $1,230 |
| No | 203514056 | EMI | DHSZ109DA | DHWAL09DA | | 6,900 | $345 |
| No | 204745048 | EMI | SZ1H12AAA | WALH12AAA | | 7,100 | $355 |
| No | 203514057 | EMI | DHSZ112DA | DHWAL12DA | | 7,800 | $390 |
| No | 203514060 | EMI | DHMZ436DA | Heat pump without ducts | | 23,200 | $1,160 |
| No | 204853572 | EMI | MZ3H27DAA | Heat pump without ducts | | 17,200 | $860 |
| No | 208121934 | EMI | MHMZ218DA | Combination heat pumps with or without ducts | | 11,500 | $575 |
| No | 208121937 | EMI | MHMZ327DA | Combination heat pumps with or without ducts | | 17,000 | $850 |
| No | 205965871 | ENERGI AIR | GVZC200241A* | CA*F3642*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205965872 | ENERGI AIR | GVZC200361A* | CA*F3743*6D*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 205965874 | ENERGI AIR | GVZC200241A* | CA*F3137*6A*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205965875 | ENERGI AIR | GVZC200241A* | CA*F3137*6A*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205965873 | ENERGI AIR | GVZC200481A* | CA*F4961*6D*+MBVC2000**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965879 | ENERGI AIR | GVZC200241A* | CA*F3636*6D*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205965876 | ENERGI AIR | GVZC200241A* | CA*F3137*6A*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205965877 | ENERGI AIR | GVZC200241A* | CA*F3137*6A*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205965878 | ENERGI AIR | GVZC200241A* | CA*F3137*6A*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205965880 | ENERGI AIR | GVZC200241A* | CA*F3636*6D*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205965881 | ENERGI AIR | GVZC200241A* | CA*F3636*6D*+TXV | G*VM970804CNB* | 13,000 | $650 |
| No | 205965884 | ENERGI AIR | GVZC200241A* | CA*F3636*6D*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205965885 | ENERGI AIR | GVZC200241A* | CA*F3642*6D*+TXV | G*VM970603BNB* | 13,000 | $650 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205965882 | ENERGI AIR | GVZC200241A* | CA*F3636*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205965883 | ENERGI AIR | GVZC200241A* | CA*F3636*6D*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205965886 | ENERGI AIR | GVZC200241A* | CA*F3642*6D*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205965898 | ENERGI AIR | GVZC200241A* | CHPF3636B6C*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205965895 | ENERGI AIR | GVZC200241A* | CHPF3636B6C*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205965887 | ENERGI AIR | GVZC200241A* | CA*F3642*6D*+TXV | G*VM970804CNB* | 13,000 | $650 |
| No | 205965888 | ENERGI AIR | GVZC200241A* | CA*F3743*6D*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205965889 | ENERGI AIR | GVZC200241A* | CA*F3743*6D*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205965890 | ENERGI AIR | GVZC200241A* | CA*F3743*6D*+TXV | G*VM970804CNB* | 13,000 | $650 |
| No | 205965891 | ENERGI AIR | GVZC200241A* | CA*F3743*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205965903 | ENERGI AIR | GVZC200241A* | CA*F3137*6A*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205965892 | ENERGI AIR | GVZC200241A* | CA*F3743*6D*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205965900 | ENERGI AIR | GVZC200241A* | CSCF3642N6D*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205965893 | ENERGI AIR | GVZC200241A* | CA*F3743*6D*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205965894 | ENERGI AIR | GVZC200241A* | CHPF3636B6C*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205965896 | ENERGI AIR | GVZC200241A* | CHPF3636B6C*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205965897 | ENERGI AIR | GVZC200241A* | CHPF3636B6C*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205965899 | ENERGI AIR | GVZC200241A* | CHPF3642C6C*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205965904 | ENERGI AIR | GVZC200241A* | CA*F3636*6D*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205965902 | ENERGI AIR | GVZC200241A* | AVPEC25B14A* | | 13,600 | $680 |
| No | 205965901 | ENERGI AIR | GVZC200241A* | CSCF3642N6D*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205965905 | ENERGI AIR | GVZC200241A* | CA*F3642*6D*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205965907 | ENERGI AIR | GVZC200241A* | CHPF3636B6C*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205965906 | ENERGI AIR | GVZC200241A* | CA*F3743*6D*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205965908 | ENERGI AIR | GVZC200241A* | CHPF3642C6C*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205965910 | ENERGI AIR | GVZC200361A* | CA*F3137*6A*+TXV | G*VM970803BNB* | 18,200 | $910 |
| No | 205965911 | ENERGI AIR | GVZC200361A* | CA*F3137*6A*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 205965913 | ENERGI AIR | GVZC200361A* | CA*F3137*6A*+TXV | G*VS800604BUA* | 18,200 | $910 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205965912 | ENERGI AIR | GVZC200361A* | CA*F3137*6A*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 205965909 | ENERGI AIR | GVZC200361A* | CA*F3137*6A*+TXV | G*VM970603BNB* | 18,200 | $910 |
| No | 205965914 | ENERGI AIR | GVZC200361A* | CA*F3137*6A*+TXV | G*VS960603BUA* | 18,200 | $910 |
| No | 205965916 | ENERGI AIR | GVZC200361A* | CA*F3642*6D*+TXV | G*VM970803BNB* | 18,000 | $900 |
| No | 205965919 | ENERGI AIR | GVZC200361A* | CA*F3642*6D*+TXV | G*VM971205DNB* | 18,000 | $900 |
| No | 205965918 | ENERGI AIR | GVZC200361A* | CA*F3642*6D*+TXV | G*VM971005CNB* | 18,000 | $900 |
| No | 205965917 | ENERGI AIR | GVZC200361A* | CA*F3642*6D*+TXV | G*VM970804CNB* | 18,200 | $910 |
| No | 205965915 | ENERGI AIR | GVZC200361A* | CA*F3642*6D*+TXV | G*VM970603BNB* | 18,000 | $900 |
| No | 205965931 | ENERGI AIR | GVZC200361A* | CA*F3743*6D*+TXV | G*VS800805CUA* | 18,200 | $910 |
| No | 205965922 | ENERGI AIR | GVZC200361A* | CA*F3642*6D*+TXV | G*VS800604BUA* | 18,200 | $910 |
| No | 205965920 | ENERGI AIR | GVZC200361A* | CA*F3642*6D*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 205965921 | ENERGI AIR | GVZC200361A* | CA*F3642*6D*+MBVC1600**-1A*+TXV | | 18,000 | $900 |
| No | 205965923 | ENERGI AIR | GVZC200361A* | CA*F3642*6D*+TXV | G*VS800805CUA* | 18,000 | $900 |
| No | 205965932 | ENERGI AIR | GVZC200361A* | CA*F3743*6D*+TXV | G*VS960603BUA* | 18,200 | $910 |
| No | 205965926 | ENERGI AIR | GVZC200361A* | CA*F3743*6D*+TXV | G*VM970603BNB* | 18,200 | $910 |
| No | 205965924 | ENERGI AIR | GVZC200361A* | CA*F3642*6D*+TXV | G*VS960603BUA* | 18,000 | $900 |
| No | 205965925 | ENERGI AIR | GVZC200361A* | CA*F3642*6D*+TXV | G*VS960805CUA* | 18,000 | $900 |
| No | 205965927 | ENERGI AIR | GVZC200361A* | CA*F3743*6D*+TXV | G*VM970803BNB* | 18,200 | $910 |
| No | 205965928 | ENERGI AIR | GVZC200361A* | CA*F3743*6D*+TXV | G*VM971205DNB* | 18,200 | $910 |
| No | 205965930 | ENERGI AIR | GVZC200361A* | CA*F3743*6D*+TXV | G*VS800604BUA* | 18,000 | $900 |
| No | 205965929 | ENERGI AIR | GVZC200361A* | CA*F3743*6D*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 205965934 | ENERGI AIR | GVZC200361A* | CHPF3642C6C*+TXV | G*VM970603BNB* | 18,000 | $900 |
| No | 205965933 | ENERGI AIR | GVZC200361A* | CA*F3743*6D*+TXV | G*VS960805CUA* | 18,200 | $910 |
| No | 205965935 | ENERGI AIR | GVZC200361A* | CHPF3642C6C*+TXV | G*VM970803BNB* | 18,000 | $900 |
| No | 205965936 | ENERGI AIR | GVZC200361A* | CHPF3642C6C*+TXV | G*VM970804CNB* | 18,000 | $900 |
| No | 205965937 | ENERGI AIR | GVZC200361A* | CHPF3642C6C*+TXV | G*VM971005CNB* | 18,000 | $900 |
| No | 205965938 | ENERGI AIR | GVZC200361A* | CHPF3642C6C*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 205965939 | ENERGI AIR | GVZC200361A* | CHPF3642C6C*+MBVC1600**-1A*+TXV | | 18,000 | $900 |
| No | 205965940 | ENERGI AIR | GVZC200361A* | CHPF3642C6C*+TXV | G*VS800604BUA* | 18,000 | $900 |
| No | 205965941 | ENERGI AIR | GVZC200361A* | CHPF3642C6C*+TXV | G*VS800805CUA* | 18,000 | $900 |
| No | 205965942 | ENERGI AIR | GVZC200361A* | CHPF3642C6C*+TXV | G*VS960603BUA* | 18,000 | $900 |
| No | 205965952 | ENERGI AIR | GVZC200361A* | CHPF3743C6B*+TXV | G*VS960603BUA* | 18,200 | $910 |
| No | 205965943 | ENERGI AIR | GVZC200361A* | CHPF3642C6C*+TXV | G*VS960805CUA* | 18,000 | $900 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205965944 | ENERGI AIR | GVZC200361A* | CHPF3743C6B*+TXV | G*VM970603BNB* | 18,200 | $910 |
| No | 205965945 | ENERGI AIR | GVZC200361A* | CHPF3743C6B*+TXV | G*VM970803BNB* | 18,200 | $910 |
| No | 205965946 | ENERGI AIR | GVZC200361A* | CA*F3743*6D*+TXV | G*VM970804CNB* | 18,000 | $900 |
| No | 205965950 | ENERGI AIR | GVZC200361A* | CHPF3743C6B*+TXV | G*VS800604BUA* | 18,200 | $910 |
| No | 205965947 | ENERGI AIR | GVZC200361A* | CA*F3743*6D*+TXV | G*VM971005CNB* | 18,200 | $910 |
| No | 205965948 | ENERGI AIR | GVZC200361A* | CHPF3743C6B*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 205965949 | ENERGI AIR | GVZC200361A* | CHPF3743C6B*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 205965951 | ENERGI AIR | GVZC200361A* | CHPF3743C6B*+TXV | G*VS800805CUA* | 18,200 | $910 |
| No | 205965953 | ENERGI AIR | GVZC200361A* | CHPF3743C6B*+TXV | G*VS960805CUA* | 18,200 | $910 |
| No | 205965955 | ENERGI AIR | GVZC200361A* | CSCF3642N6D*+TXV | G*VM970803BNB* | 18,200 | $910 |
| No | 205965956 | ENERGI AIR | GVZC200361A* | CSCF3642N6D*+TXV | G*VM970804CNB* | 18,200 | $910 |
| No | 205965954 | ENERGI AIR | GVZC200361A* | CSCF3642N6D*+TXV | G*VM970603BNB* | 18,200 | $910 |
| No | 205965957 | ENERGI AIR | GVZC200361A* | CSCF3642N6D*+TXV | G*VM971005CNB* | 18,200 | $910 |
| No | 205965958 | ENERGI AIR | GVZC200361A* | CSCF3642N6D*+TXV | G*VM971205DNB* | 18,200 | $910 |
| No | 205965964 | ENERGI AIR | GVZC200361A* | CSCF3642N6D*+TXV | G*VS960805CUA* | 18,200 | $910 |
| No | 205965962 | ENERGI AIR | GVZC200361A* | CSCF3642N6D*+TXV | G*VS800805CUA* | 18,200 | $910 |
| No | 205965959 | ENERGI AIR | GVZC200361A* | CSCF3642N6D*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 205965963 | ENERGI AIR | GVZC200361A* | CSCF3642N6D*+TXV | G*VS960603BUA* | 18,200 | $910 |
| No | 205965960 | ENERGI AIR | GVZC200361A* | CSCF3642N6D*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 205965961 | ENERGI AIR | GVZC200361A* | CSCF3642N6D*+TXV | G*VS800604BUA* | 18,200 | $910 |
| No | 205965968 | ENERGI AIR | GVZC200481A* | CA*F4860*6D*+MBVC2000**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965965 | ENERGI AIR | GVZC200361A* | AVPEC37C14A* | | 18,900 | $945 |
| No | 205965966 | ENERGI AIR | GVZC200361A* | AVPEC59D14A* | | 18,900 | $945 |
| No | 205965967 | ENERGI AIR | GVZC200481A* | CA*F4860*6D*+MBVC1600**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965975 | ENERGI AIR | GVZC200481A* | CSCF4860N6D*+TXV | G*VM970804CNB* | 27,400 | $1,370 |
| No | 205965971 | ENERGI AIR | GVZC200481A* | CHPF4860D6D*+TXV | G*VM971005CNB* | 27,800 | $1,390 |
| No | 205965972 | ENERGI AIR | GVZC200481A* | CHPF4860D6D*+TXV | G*VM971205DNB* | 27,800 | $1,390 |
| No | 205965970 | ENERGI AIR | GVZC200481A* | CHPF4860D6D*+TXV | G*VM970804CNB* | 28,000 | $1,400 |
| No | 205965969 | ENERGI AIR | GVZC200481A* | CA*F4860*6D*+TXV | G*VS960805CUA* | 27,400 | $1,370 |
| No | 205965973 | ENERGI AIR | GVZC200481A* | CHPF4860D6D*+MBVC1600**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965988 | ENERGI AIR | GVZC200481A* | CSCF4860N6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205965976 | ENERGI AIR | GVZC200481A* | CSCF4860N6D*+TXV | G*VM971005CNB* | 27,400 | $1,370 |
| No | 205965977 | ENERGI AIR | GVZC200481A* | CSCF4860N6D*+TXV | G*VM971205DNB* | 27,400 | $1,370 |
| No | 205965978 | ENERGI AIR | GVZC200481A* | CSCF4860N6D*+MBVC1600**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965974 | ENERGI AIR | GVZC200481A* | CHPF4860D6D*+TXV | G*VS800805CUA* | 27,200 | $1,360 |
| No | 205965981 | ENERGI AIR | GVZC200481A* | CSCF4860N6D*+TXV | G*VS800805CUA* | 27,400 | $1,370 |
| No | 205965982 | ENERGI AIR | GVZC200481A* | CSCF4860N6D*+TXV | G*VS960805CUA* | 27,400 | $1,370 |
| No | 205965983 | ENERGI AIR | GVZC200481A* | AVPEC59D14A* | | 27,000 | $1,350 |
| No | 205965979 | ENERGI AIR | GVZC200481A* | CSCF4860N6D*+MBVC2000**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965980 | ENERGI AIR | GVZC200481A* | CSCF4860N6D*+TXV | G*VS800604BUA* | 27,400 | $1,370 |
| No | 205965985 | ENERGI AIR | GVZC200481A* | CA*F4860*6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965984 | ENERGI AIR | GVZC200481A* | CA*F4860*6D*+MBVC1601**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965986 | ENERGI AIR | GVZC200481A* | CHPF4860D6D*+MBVC1601**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965987 | ENERGI AIR | GVZC200481A* | CSCF4860N6D*+MBVC1601**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965989 | ENERGI AIR | GVZC200481A* | CA*F4961*6D*+TXV | G*VM970804CNB* | 27,800 | $1,390 |
| No | 205965990 | ENERGI AIR | GVZC200481A* | CA*F4961*6D*+TXV | G*VM971005CNB* | 27,800 | $1,390 |
| No | 205965992 | ENERGI AIR | GVZC200481A* | CA*F4961*6D*+MBVC1600**-1A*+TXV | | 26,800 | $1,340 |
| No | 205965993 | ENERGI AIR | GVZC200481A* | CA*F4961*6D*+TXV | G*VS800604BUA* | 28,000 | $1,400 |
| No | 205965991 | ENERGI AIR | GVZC200481A* | CA*F4961*6D*+TXV | G*VM971205DNB* | 27,800 | $1,390 |
| No | 205965996 | ENERGI AIR | GVZC200481A* | CHPF4860D6D*+MBVC2000**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965994 | ENERGI AIR | GVZC200481A* | CA*F4961*6D*+TXV | G*VS800805CUA* | 27,200 | $1,360 |
| No | 205965995 | ENERGI AIR | GVZC200481A* | CA*F4961*6D*+TXV | G*VS960805CUA* | 27,600 | $1,380 |
| No | 205965998 | ENERGI AIR | GVZC200481A* | CA*F4961*6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966044 | ENERGI AIR | GVZC200361A* | CA*F3137*6A*+MBVC1201**-1A*+TXV | | 18,000 | $900 |
| No | 205966443 | ENERGI AIR | GVZC200361A* | CA*F3642*6D*+MBVC1201**-1A*+TXV | | 18,000 | $900 |
| No | 205965997 | ENERGI AIR | GVZC200481A* | CA*F4961*6D*+MBVC1601**-1A*+TXV | | 26,800 | $1,340 |
| No | 205966444 | ENERGI AIR | GVZC200361A* | CA*F3642*6D*+MBVC1601**-1A*+TXV | | 18,000 | $900 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966045 | ENERGI AIR | GVZC200361A* | CA*F3137*6A*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205966448 | ENERGI AIR | GVZC200361A* | CHPF3642C6C*+MBVC1601**-1A*+TXV | | 18,000 | $900 |
| No | 205966446 | ENERGI AIR | GVZC200361A* | CA*F3743*6D*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205966449 | ENERGI AIR | GVZC200361A* | CHPF3743C6B*+MBVC1201**-1A*+TXV | | 18,200 | $910 |
| No | 205966445 | ENERGI AIR | GVZC200361A* | CA*F3743*6D*+MBVC1201**-1A*+TXV | | 18,200 | $910 |
| No | 205966447 | ENERGI AIR | GVZC200361A* | CHPF3642C6C*+MBVC1201**-1A*+TXV | | 18,000 | $900 |
| No | 205966450 | ENERGI AIR | GVZC200361A* | CHPF3743C6B*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205966451 | ENERGI AIR | GVZC200361A* | CSCF3642N6D*+MBVC1201**-1A*+TXV | | 18,200 | $910 |
| No | 205966452 | ENERGI AIR | GVZC200361A* | CSCF3642N6D*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205966453 | ENERGI AIR | GVZC200481A* | CA*F4860*6D*+TXV | G*VM970804CNB* | 27,400 | $1,370 |
| No | 205966454 | ENERGI AIR | GVZC200481A* | CA*F4860*6D*+TXV | G*VM971005CNB* | 27,400 | $1,370 |
| No | 205966456 | ENERGI AIR | GVZC200481A* | CA*F4860*6D*+TXV | G*VS800805CUA* | 27,400 | $1,370 |
| No | 205966455 | ENERGI AIR | GVZC200481A* | CA*F4860*6D*+TXV | G*VM971205DNB* | 27,400 | $1,370 |
| No | 205966457 | ENERGI AIR | GVZC200481A* | CHPF4860D6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 202481357 | EVERREST EXTREME COMFORT | AVZC200481A* | AVPEC59D14A* | | 27,000 | $1,350 |
| No | 202481284 | EVERREST EXTREME COMFORT | AVZC200241A* | CHPF3642C6C*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 206720384 | FORESTAIR | FGH-30ES/MZ | Heat pump without ducts | | 18,000 | $900 |
| No | 206720387 | FORESTAIR | FGH-36ES/MZ | Heat pump without ducts | | 20,000 | $1,000 |
| No | 206720381 | FORESTAIR | FGH-24ES/MZ | Heat pump without ducts | | 16,600 | $830 |
| No | 206720390 | FORESTAIR | FGH-42ES/MZ | Heat pump without ducts | | 29,000 | $1,450 |
| No | 206720376 | FORESTAIR | FGH-12ES/E-38-O | FGH-12ES/E-38-I | | 8,300 | $415 |
| No | 206720374 | FORESTAIR | FGH-12ES/E23-O | FGH-12ES/E23-I | | 7,700 | $385 |
| No | 206720375 | FORESTAIR | FGH-18ES/E23-O | FGH-18ES/E23-I | | 12,400 | $620 |
| No | 206720373 | FORESTAIR | FGH-09ES/E23-O | FGH-09ES/E23-I | | 7,300 | $365 |
| No | 206720378 | FORESTAIR | FGH-18ES/MZ | Heat pump without ducts | | 12,800 | $640 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210693271 | FRANKLIN | ASZV906010A* | CSCF4860N6D*+TXV | G*VM971205DNB* | 32,400 | $1,620 |
| No | 210693270 | FRANKLIN | ASZV906010A* | CSCF4860N6D*+TXV | G*VM971005CNB* | 32,400 | $1,620 |
| No | 210693269 | FRANKLIN | ASZV906010A* | CSCF4860N6D*+TXV | G*VC961205DNB* | 32,400 | $1,620 |
| No | 210693268 | FRANKLIN | ASZV906010A* | CSCF4860N6D*+TXV | G*VC961005CNB* | 32,400 | $1,620 |
| No | 210693267 | FRANKLIN | ASZV906010A* | CSCF4860N6D*+TXV | G*VS960805CUA* | 32,400 | $1,620 |
| No | 210693263 | FRANKLIN | ASZV906010A* | CHPF4860D6D*+TXV | G*VM971205DNB* | 32,400 | $1,620 |
| No | 210693262 | FRANKLIN | ASZV906010A* | CHPF4860D6D*+TXV | G*VM971005CNB* | 32,400 | $1,620 |
| No | 210693261 | FRANKLIN | ASZV906010A* | CHPF4860D6D*+TXV | G*VC961205DNB* | 32,400 | $1,620 |
| No | 210693260 | FRANKLIN | ASZV906010A* | CHPF4860D6D*+TXV | G*VC961005CNB* | 32,400 | $1,620 |
| No | 210693259 | FRANKLIN | ASZV906010A* | CHPF4860D6D*+TXV | G*VS960805CUA* | 32,400 | $1,620 |
| No | 210693255 | FRANKLIN | ASZV906010A* | CHPF4860D6D*+MBVC2001**-1A*+TXV | | 32,400 | $1,620 |
| No | 210693254 | FRANKLIN | ASZV906010A* | CA*F4961*6D*+TXV | G*VM971205DNB* | 33,400 | $1,670 |
| No | 210693253 | FRANKLIN | ASZV906010A* | CA*F4961*6D*+TXV | G*VM971005CNB* | 33,400 | $1,670 |
| No | 210693252 | FRANKLIN | ASZV906010A* | CA*F4961*6D*+TXV | G*VC961205DNB* | 33,400 | $1,670 |
| No | 210693251 | FRANKLIN | ASZV906010A* | CA*F4961*6D*+TXV | G*VC961005CNB* | 33,400 | $1,670 |
| No | 210693250 | FRANKLIN | ASZV906010A* | CA*F4961*6D*+TXV | G*VS960805CUA* | 33,400 | $1,670 |
| No | 210607425 | FRANKLIN | ASZV906010A* | CA*F4961*6D*+MBVC2001**-1A*+TX | | 34,000 | $1,700 |
| No | 210609992 | FRANKLIN | ASZV906010A* | AMVE60DP1400A* | | 33,400 | $1,670 |
| No | 210693067 | FRANKLIN | GSZV906010A* | CSCF4860N6D*+TXV | G*VM971205DNB* | 32,400 | $1,620 |
| No | 210693066 | FRANKLIN | GSZV906010A* | CSCF4860N6D*+TXV | G*VM971005CNB* | 32,400 | $1,620 |
| No | 210693065 | FRANKLIN | GSZV906010A* | CSCF4860N6D*+TXV | G*VC961205DNB* | 32,400 | $1,620 |
| No | 210693064 | FRANKLIN | GSZV906010A* | CSCF4860N6D*+TXV | G*VC961005CNB* | 32,400 | $1,620 |
| No | 210693063 | FRANKLIN | GSZV906010A* | CSCF4860N6D*+TXV | G*VS960805CUA* | 32,400 | $1,620 |
| No | 210693059 | FRANKLIN | GSZV906010A* | CHPF4860D6D*+TXV | G*VM971205DNB* | 32,400 | $1,620 |
| No | 210693058 | FRANKLIN | GSZV906010A* | CHPF4860D6D*+TXV | G*VM971005CNB* | 32,400 | $1,620 |
| No | 210693057 | FRANKLIN | GSZV906010A* | CHPF4860D6D*+TXV | G*VC961205DNB* | 32,400 | $1,620 |
| No | 210693056 | FRANKLIN | GSZV906010A* | CHPF4860D6D*+TXV | G*VC961005CNB* | 32,400 | $1,620 |
| No | 210693055 | FRANKLIN | GSZV906010A* | CHPF4860D6D*+TXV | G*VS960805CUA* | 32,400 | $1,620 |
| No | 210693051 | FRANKLIN | GSZV906010A* | CHPF4860D6D*+MBVC2001**-1A*+TXV | | 32,400 | $1,620 |
| No | 210693050 | FRANKLIN | GSZV906010A* | CA*F4961*6D*+TXV | G*VM971205DNB* | 33,400 | $1,670 |
| No | 210693049 | FRANKLIN | GSZV906010A* | CA*F4961*6D*+TXV | G*VM971005CNB* | 33,400 | $1,670 |
| No | 210693048 | FRANKLIN | GSZV906010A* | CA*F4961*6D*+TXV | G*VC961205DNB* | 33,400 | $1,670 |
| No | 210693047 | FRANKLIN | GSZV906010A* | CA*F4961*6D*+TXV | G*VC961005CNB* | 33,400 | $1,670 |
| No | 210693046 | FRANKLIN | GSZV906010A* | CA*F4961*6D*+TXV | G*VS960805CUA* | 33,400 | $1,670 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210607424 | FRANKLIN | GSZV906010A* | CA*F4961*6D*+MBVC2001**-1A*+TX | | 34,000 | $1,700 |
| No | 210609991 | FRANKLIN | GSZV906010A* | AMVE60DP1400A* | | 33,400 | $1,670 |
| No | 210693246 | FRANKLIN | ASZV904810A* | CSCF4860N6D*+TXV | G*VM971205DNB* | 27,000 | $1,350 |
| No | 210693245 | FRANKLIN | ASZV904810A* | CSCF4860N6D*+TXV | G*VM971005CNB* | 27,000 | $1,350 |
| No | 210693244 | FRANKLIN | ASZV904810A* | CSCF4860N6D*+TXV | G*VM970804CNB* | 27,000 | $1,350 |
| No | 210693243 | FRANKLIN | ASZV904810A* | CSCF4860N6D*+TXV | G*VC961205DNB* | 27,000 | $1,350 |
| No | 210693242 | FRANKLIN | ASZV904810A* | CSCF4860N6D*+TXV | G*VC961005CNB* | 27,000 | $1,350 |
| No | 210693241 | FRANKLIN | ASZV904810A* | CSCF4860N6D*+TXV | G*VS960805CUA* | 27,000 | $1,350 |
| No | 210693240 | FRANKLIN | ASZV904810A* | CSCF4860N6D*+TXV | G*VC960804CNB* | 27,000 | $1,350 |
| No | 210693234 | FRANKLIN | ASZV904810A* | CSCF4860N6D*+MBVC2001**-1A*+TXV | | 27,000 | $1,350 |
| No | 210693233 | FRANKLIN | ASZV904810A* | CSCF4860N6D*+MBVC1601**-1A*+TXV | | 27,000 | $1,350 |
| No | 210693232 | FRANKLIN | ASZV904810A* | CHPF4860D6D*+TXV | G*VM971205DNB* | 27,000 | $1,350 |
| No | 210693231 | FRANKLIN | ASZV904810A* | CHPF4860D6D*+TXV | G*VM971005CNB* | 27,000 | $1,350 |
| No | 210693230 | FRANKLIN | ASZV904810A* | CHPF4860D6D*+TXV | G*VM970804CNB* | 27,000 | $1,350 |
| No | 210693229 | FRANKLIN | ASZV904810A* | CHPF4860D6D*+TXV | G*VC961205DNB* | 27,000 | $1,350 |
| No | 210693228 | FRANKLIN | ASZV904810A* | CHPF4860D6D*+TXV | G*VC961005CNB* | 27,000 | $1,350 |
| No | 210693227 | FRANKLIN | ASZV904810A* | CHPF4860D6D*+TXV | G*VC960804CNB* | 27,000 | $1,350 |
| No | 210693223 | FRANKLIN | ASZV904810A* | CHPF4860D6D*+MBVC2001**-1A*+TXV | | 27,000 | $1,350 |
| No | 210693222 | FRANKLIN | ASZV904810A* | CHPF4860D6D*+MBVC1601**-1A*+TXV | | 27,000 | $1,350 |
| No | 210693221 | FRANKLIN | ASZV904810A* | CA*F4961*6D*+TXV | G*VM971205DNB* | 27,000 | $1,350 |
| No | 210693220 | FRANKLIN | ASZV904810A* | CA*F4961*6D*+TXV | G*VM971005CNB* | 27,000 | $1,350 |
| No | 210693219 | FRANKLIN | ASZV904810A* | CA*F4961*6D*+TXV | G*VM970804CNB* | 27,000 | $1,350 |
| No | 210693218 | FRANKLIN | ASZV904810A* | CA*F4961*6D*+TXV | G*VC961205DNB* | 27,000 | $1,350 |
| No | 210693217 | FRANKLIN | ASZV904810A* | CA*F4961*6D*+TXV | G*VC961005CNB* | 27,000 | $1,350 |
| No | 210693216 | FRANKLIN | ASZV904810A* | CA*F4961*6D*+TXV | G*VS960805CUA* | 27,000 | $1,350 |
| No | 210693215 | FRANKLIN | ASZV904810A* | CA*F4961*6D*+TXV | G*VC960804CNB* | 27,000 | $1,350 |
| No | 210607418 | FRANKLIN | ASZV904810A* | CA*F4961*6D*+MBVC2001**-1A*+TX | | 27,000 | $1,350 |
| No | 210693209 | FRANKLIN | ASZV904810A* | CA*F4961*6D*+MBVC1601**-1A*+TXV | | 27,000 | $1,350 |
| No | 210693208 | FRANKLIN | ASZV904810A* | CA*F4860*6D*+TXV | G*VM971205DNB* | 27,000 | $1,350 |
| No | 210693207 | FRANKLIN | ASZV904810A* | CA*F4860*6D*+TXV | G*VM971005CNB* | 27,000 | $1,350 |
| No | 210693206 | FRANKLIN | ASZV904810A* | CA*F4860*6D*+TXV | G*VM970804CNB* | 27,000 | $1,350 |
| No | 210693205 | FRANKLIN | ASZV904810A* | CA*F4860*6D*+TXV | G*VC961205DNB* | 27,000 | $1,350 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210693204 | FRANKLIN | ASZV904810A* | CA*F4860*6D*+TXV | G*VC961005CNB* | 27,000 | $1,350 |
| No | 210693203 | FRANKLIN | ASZV904810A* | CA*F4860*6D*+TXV | G*VS960805CUA* | 27,000 | $1,350 |
| No | 210693202 | FRANKLIN | ASZV904810A* | CA*F4860*6D*+TXV | G*VC960804CNB* | 27,000 | $1,350 |
| No | 210693197 | FRANKLIN | ASZV904810A* | CA*F4860*6D*+MBVC2001**-1A*+TXV | | 27,000 | $1,350 |
| No | 210693196 | FRANKLIN | ASZV904810A* | CA*F4860*6D*+MBVC1601**-1A*+TXV | | 27,000 | $1,350 |
| No | 210609985 | FRANKLIN | ASZV904810A* | AMVE60DP1400A* | | 27,000 | $1,350 |
| No | 210609984 | FRANKLIN | ASZV904810A* | AMVE48DP1400A* | | 27,000 | $1,350 |
| No | 210693042 | FRANKLIN | GSZV904810A* | CSCF4860N6D*+TXV | G*VM971205DNB* | 27,000 | $1,350 |
| No | 210693041 | FRANKLIN | GSZV904810A* | CSCF4860N6D*+TXV | G*VM971005CNB* | 27,000 | $1,350 |
| No | 210693040 | FRANKLIN | GSZV904810A* | CSCF4860N6D*+TXV | G*VM970804CNB* | 27,000 | $1,350 |
| No | 210693039 | FRANKLIN | GSZV904810A* | CSCF4860N6D*+TXV | G*VC961205DNB* | 27,000 | $1,350 |
| No | 210693038 | FRANKLIN | GSZV904810A* | CSCF4860N6D*+TXV | G*VC961005CNB* | 27,000 | $1,350 |
| No | 210693037 | FRANKLIN | GSZV904810A* | CSCF4860N6D*+TXV | G*VS960805CUA* | 27,000 | $1,350 |
| No | 210693036 | FRANKLIN | GSZV904810A* | CSCF4860N6D*+TXV | G*VC960804CNB* | 27,000 | $1,350 |
| No | 210693030 | FRANKLIN | GSZV904810A* | CSCF4860N6D*+MBVC2001**-1A*+TXV | | 27,000 | $1,350 |
| No | 210693029 | FRANKLIN | GSZV904810A* | CSCF4860N6D*+MBVC1601**-1A*+TXV | | 27,000 | $1,350 |
| No | 210693028 | FRANKLIN | GSZV904810A* | CHPF4860D6D*+TXV | G*VM971205DNB* | 27,000 | $1,350 |
| No | 210693027 | FRANKLIN | GSZV904810A* | CHPF4860D6D*+TXV | G*VM971005CNB* | 27,000 | $1,350 |
| No | 210693026 | FRANKLIN | GSZV904810A* | CHPF4860D6D*+TXV | G*VM970804CNB* | 27,000 | $1,350 |
| No | 210693025 | FRANKLIN | GSZV904810A* | CHPF4860D6D*+TXV | G*VC961205DNB* | 27,000 | $1,350 |
| No | 210693024 | FRANKLIN | GSZV904810A* | CHPF4860D6D*+TXV | G*VC961005CNB* | 27,000 | $1,350 |
| No | 210693023 | FRANKLIN | GSZV904810A* | CHPF4860D6D*+TXV | G*VC960804CNB* | 27,000 | $1,350 |
| No | 210693019 | FRANKLIN | GSZV904810A* | CHPF4860D6D*+MBVC2001**-1A*+TXV | | 27,000 | $1,350 |
| No | 210693018 | FRANKLIN | GSZV904810A* | CHPF4860D6D*+MBVC1601**-1A*+TXV | | 27,000 | $1,350 |
| No | 210693017 | FRANKLIN | GSZV904810A* | CA*F4961*6D*+TXV | G*VM971205DNB* | 27,000 | $1,350 |
| No | 210693016 | FRANKLIN | GSZV904810A* | CA*F4961*6D*+TXV | G*VM971005CNB* | 27,000 | $1,350 |
| No | 210693015 | FRANKLIN | GSZV904810A* | CA*F4961*6D*+TXV | G*VM970804CNB* | 27,000 | $1,350 |
| No | 210693014 | FRANKLIN | GSZV904810A* | CA*F4961*6D*+TXV | G*VC961205DNB* | 27,000 | $1,350 |
| No | 210693013 | FRANKLIN | GSZV904810A* | CA*F4961*6D*+TXV | G*VC961005CNB* | 27,000 | $1,350 |
| No | 210693012 | FRANKLIN | GSZV904810A* | CA*F4961*6D*+TXV | G*VS960805CUA* | 27,000 | $1,350 |
| No | 210693011 | FRANKLIN | GSZV904810A* | CA*F4961*6D*+TXV | G*VC960804CNB* | 27,000 | $1,350 |
| No | 210607417 | FRANKLIN | GSZV904810A* | CA*F4961*6D*+MBVC2001**-1A*+TX | | 27,000 | $1,350 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210693005 | FRANKLIN | GSZV904810A* | CA*F4961*6D*+MBVC1601**-1A*+TXV | | 27,000 | $1,350 |
| No | 210693004 | FRANKLIN | GSZV904810A* | CA*F4860*6D*+TXV | G*VM971205DNB* | 27,000 | $1,350 |
| No | 210693003 | FRANKLIN | GSZV904810A* | CA*F4860*6D*+TXV | G*VM971005CNB* | 27,000 | $1,350 |
| No | 210693002 | FRANKLIN | GSZV904810A* | CA*F4860*6D*+TXV | G*VM970804CNB* | 27,000 | $1,350 |
| No | 210693001 | FRANKLIN | GSZV904810A* | CA*F4860*6D*+TXV | G*VC961205DNB* | 27,000 | $1,350 |
| No | 210693000 | FRANKLIN | GSZV904810A* | CA*F4860*6D*+TXV | G*VC961005CNB* | 27,000 | $1,350 |
| No | 210692999 | FRANKLIN | GSZV904810A* | CA*F4860*6D*+TXV | G*VS960805CUA* | 27,000 | $1,350 |
| No | 210692998 | FRANKLIN | GSZV904810A* | CA*F4860*6D*+TXV | G*VC960804CNB* | 27,000 | $1,350 |
| No | 210692993 | FRANKLIN | GSZV904810A* | CA*F4860*6D*+MBVC2001**-1A*+TXV | | 27,000 | $1,350 |
| No | 210692992 | FRANKLIN | GSZV904810A* | CA*F4860*6D*+MBVC1601**-1A*+TXV | | 27,000 | $1,350 |
| No | 210609983 | FRANKLIN | GSZV904810A* | AMVE60DP1400A* | | 27,000 | $1,350 |
| No | 210609982 | FRANKLIN | GSZV904810A* | AMVE48DP1400A* | | 27,000 | $1,350 |
| No | 210693107 | FRANKLIN | ASZV902410A* | CSCF3642N6D*+TXV | G*VM970804CNB* | 14,200 | $710 |
| No | 210693106 | FRANKLIN | ASZV902410A* | CSCF3642N6D*+TXV | G*VM970803BNB* | 14,200 | $710 |
| No | 210693105 | FRANKLIN | ASZV902410A* | CSCF3642N6D*+TXV | G*VM970603BNB* | 14,200 | $710 |
| No | 210693104 | FRANKLIN | ASZV902410A* | CSCF3642N6D*+TXV | G*VC960804CNB* | 14,200 | $710 |
| No | 210693103 | FRANKLIN | ASZV902410A* | CSCF3642N6D*+TXV | G*VC960803BNB* | 14,200 | $710 |
| No | 210693102 | FRANKLIN | ASZV902410A* | CSCF3642N6D*+TXV | G*VC960603BNB* | 14,200 | $710 |
| No | 210693101 | FRANKLIN | ASZV902410A* | CSCF3642N6D*+TXV | G*VS960603BUA* | 14,200 | $710 |
| No | 210693100 | FRANKLIN | ASZV902410A* | CSCF3642N6D*+TXV | G*VC960403BNB* | 14,200 | $710 |
| No | 210693097 | FRANKLIN | ASZV902410A* | CSCF3642N6D*+MBVC1201**-1A*+TXV | | 14,200 | $710 |
| No | 210693096 | FRANKLIN | ASZV902410A* | CHPF3642C6C*+MBVC1201**-1A*+TXV | | 14,100 | $705 |
| No | 210693095 | FRANKLIN | ASZV902410A* | CHPF3636B6C*+TXV | G*VM970803BNB* | 14,200 | $710 |
| No | 210693094 | FRANKLIN | ASZV902410A* | CHPF3636B6C*+TXV | G*VM970603BNB* | 14,200 | $710 |
| No | 210693093 | FRANKLIN | ASZV902410A* | CHPF3636B6C*+TXV | G*VC960803BNB* | 14,200 | $710 |
| No | 210693092 | FRANKLIN | ASZV902410A* | CHPF3636B6C*+TXV | G*VC960603BNB* | 14,200 | $710 |
| No | 210693091 | FRANKLIN | ASZV902410A* | CHPF3636B6C*+TXV | G*VS960603BUA* | 14,200 | $710 |
| No | 210693090 | FRANKLIN | ASZV902410A* | CHPF3636B6C*+TXV | G*VC960403BNB* | 14,200 | $710 |
| No | 210693087 | FRANKLIN | ASZV902410A* | CHPF3636B6C*+MBVC1201**-1A*+TXV | | 14,200 | $710 |
| No | 210693086 | FRANKLIN | ASZV902410A* | CA*F3743*6D*+TXV | G*VM970804CNB* | 14,500 | $725 |
| No | 210693085 | FRANKLIN | ASZV902410A* | CA*F3743*6D*+TXV | G*VM970803BNB* | 14,500 | $725 |
| No | 210693084 | FRANKLIN | ASZV902410A* | CA*F3743*6D*+TXV | G*VM970603BNB* | 14,500 | $725 |
| No | 210693083 | FRANKLIN | ASZV902410A* | CA*F3743*6D*+TXV | G*VC960804CNB* | 14,500 | $725 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210693082 | FRANKLIN | ASZV902410A* | CA*F3743*6D*+TXV | G*VC960803BNB* | 14,500 | $725 |
| No | 210693081 | FRANKLIN | ASZV902410A* | CA*F3743*6D*+TXV | G*VC960603BNB* | 14,600 | $730 |
| No | 210693080 | FRANKLIN | ASZV902410A* | CA*F3743*6D*+TXV | G*VS960603BUA* | 14,600 | $730 |
| No | 210693079 | FRANKLIN | ASZV902410A* | CA*F3743*6D*+TXV | G*VC960403BNB* | 14,500 | $725 |
| No | 210693076 | FRANKLIN | ASZV902410A* | CA*F3743*6D*+MBVC1201**-1A*+TXV | | 14,500 | $725 |
| No | 210693075 | FRANKLIN | ASZV902410A* | CA*F3137*6A*+TXV | G*VM970803BNB* | 13,800 | $690 |
| No | 210693074 | FRANKLIN | ASZV902410A* | CA*F3137*6A*+TXV | G*VM970603BNB* | 13,800 | $690 |
| No | 210693073 | FRANKLIN | ASZV902410A* | CA*F3137*6A*+TXV | G*VC960803BNB* | 13,800 | $690 |
| No | 210693072 | FRANKLIN | ASZV902410A* | CA*F3137*6A*+TXV | G*VC960603BNB* | 13,800 | $690 |
| No | 210693071 | FRANKLIN | ASZV902410A* | CA*F3137*6A*+TXV | G*VS960603BUA* | 13,800 | $690 |
| No | 210693070 | FRANKLIN | ASZV902410A* | CA*F3137*6A*+TXV | G*VC960403BNB* | 13,800 | $690 |
| No | 210607574 | FRANKLIN | ASZV902410A* | CA*F3137*6A*+MBVC1201**-1A*+TX | | 14,000 | $700 |
| No | 210610036 | FRANKLIN | ASZV902410A* | AMVE24BP1400A* | | 14,800 | $740 |
| No | 210692903 | FRANKLIN | GSZV902410A* | CSCF3642N6D*+TXV | G*VM970804CNB* | 14,200 | $710 |
| No | 210692902 | FRANKLIN | GSZV902410A* | CSCF3642N6D*+TXV | G*VM970803BNB* | 14,200 | $710 |
| No | 210692901 | FRANKLIN | GSZV902410A* | CSCF3642N6D*+TXV | G*VM970603BNB* | 14,200 | $710 |
| No | 210692900 | FRANKLIN | GSZV902410A* | CSCF3642N6D*+TXV | G*VC960804CNB* | 14,200 | $710 |
| No | 210692899 | FRANKLIN | GSZV902410A* | CSCF3642N6D*+TXV | G*VC960803BNB* | 14,200 | $710 |
| No | 210692898 | FRANKLIN | GSZV902410A* | CSCF3642N6D*+TXV | G*VC960603BNB* | 14,200 | $710 |
| No | 210692897 | FRANKLIN | GSZV902410A* | CSCF3642N6D*+TXV | G*VS960603BUA* | 14,200 | $710 |
| No | 210692896 | FRANKLIN | GSZV902410A* | CSCF3642N6D*+TXV | G*VC960403BNB* | 14,200 | $710 |
| No | 210692893 | FRANKLIN | GSZV902410A* | CSCF3642N6D*+MBVC1201**-1A*+TXV | | 14,200 | $710 |
| No | 210692892 | FRANKLIN | GSZV902410A* | CHPF3642C6C*+MBVC1201**-1A*+TXV | | 14,100 | $705 |
| No | 210692891 | FRANKLIN | GSZV902410A* | CHPF3636B6C*+TXV | G*VM970803BNB* | 14,200 | $710 |
| No | 210692890 | FRANKLIN | GSZV902410A* | CHPF3636B6C*+TXV | G*VM970603BNB* | 14,200 | $710 |
| No | 210692889 | FRANKLIN | GSZV902410A* | CHPF3636B6C*+TXV | G*VC960803BNB* | 14,200 | $710 |
| No | 210692888 | FRANKLIN | GSZV902410A* | CHPF3636B6C*+TXV | G*VC960603BNB* | 14,200 | $710 |
| No | 210692887 | FRANKLIN | GSZV902410A* | CHPF3636B6C*+TXV | G*VS960603BUA* | 14,200 | $710 |
| No | 210692886 | FRANKLIN | GSZV902410A* | CHPF3636B6C*+TXV | G*VC960403BNB* | 14,200 | $710 |
| No | 210692883 | FRANKLIN | GSZV902410A* | CHPF3636B6C*+MBVC1201**-1A*+TXV | | 14,200 | $710 |
| No | 210692882 | FRANKLIN | GSZV902410A* | CA*F3743*6D*+TXV | G*VM970804CNB* | 14,500 | $725 |
| No | 210692881 | FRANKLIN | GSZV902410A* | CA*F3743*6D*+TXV | G*VM970803BNB* | 14,500 | $725 |
| No | 210692880 | FRANKLIN | GSZV902410A* | CA*F3743*6D*+TXV | G*VM970603BNB* | 14,500 | $725 |
| No | 210692879 | FRANKLIN | GSZV902410A* | CA*F3743*6D*+TXV | G*VC960804CNB* | 14,500 | $725 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210692878 | FRANKLIN | GSZV902410A* | CA*F3743*6D*+TXV | G*VC960803BNB* | 14,500 | $725 |
| No | 210692877 | FRANKLIN | GSZV902410A* | CA*F3743*6D*+TXV | G*VC960603BNB* | 14,600 | $730 |
| No | 210692876 | FRANKLIN | GSZV902410A* | CA*F3743*6D*+TXV | G*VS960603BUA* | 14,600 | $730 |
| No | 210692875 | FRANKLIN | GSZV902410A* | CA*F3743*6D*+TXV | G*VC960403BNB* | 14,500 | $725 |
| No | 210692872 | FRANKLIN | GSZV902410A* | CA*F3743*6D*+MBVC1201**-1A*+TXV | | 14,500 | $725 |
| No | 210692871 | FRANKLIN | GSZV902410A* | CA*F3137*6A*+TXV | G*VM970803BNB* | 13,800 | $690 |
| No | 210692870 | FRANKLIN | GSZV902410A* | CA*F3137*6A*+TXV | G*VM970603BNB* | 13,800 | $690 |
| No | 210692869 | FRANKLIN | GSZV902410A* | CA*F3137*6A*+TXV | G*VC960803BNB* | 13,800 | $690 |
| No | 210692868 | FRANKLIN | GSZV902410A* | CA*F3137*6A*+TXV | G*VC960603BNB* | 13,800 | $690 |
| No | 210692867 | FRANKLIN | GSZV902410A* | CA*F3137*6A*+TXV | G*VS960603BUA* | 13,800 | $690 |
| No | 210692866 | FRANKLIN | GSZV902410A* | CA*F3137*6A*+TXV | G*VC960403BNB* | 13,800 | $690 |
| No | 210607573 | FRANKLIN | GSZV902410A* | CA*F3137*6A*+MBVC1201**-1A*+TX | | 14,000 | $700 |
| No | 210610035 | FRANKLIN | GSZV902410A* | AMVE24BP1400A* | | 14,800 | $740 |
| No | 206900434 | FRANKLIN | MSH183E23MCAA | MST183E20ACAA | | 15,600 | $780 |
| No | 206900428 | FRANKLIN | MSH123E23MCAA | MST123E21ADAA | | 10,600 | $530 |
| No | 206900433 | FRANKLIN | MSH123E23MCAA | MST123E20ACAA | | 9,900 | $495 |
| No | 206900427 | FRANKLIN | MSH093E23MCAA | MST093E21ADAA | | 10,100 | $505 |
| No | 206900432 | FRANKLIN | MSH093E23MCAA | MST093E20ACAA | | 9,000 | $450 |
| No | 201900299 | FRANKLIN | AVZC200241A* | AVPEC25B14A* | | 13,600 | $680 |
| No | 201866414 | FRANKLIN | AVZC200361A* | AVPEC37C14A* | | 18,900 | $945 |
| No | 205976243 | FRANKLIN | AVZC200601B* | CA*F4961*6D*+MBVC2001**-1A*+TXV | | 32,000 | $1,600 |
| No | 205976138 | FRANKLIN | AVZC200601B* | CA*F4961*6D*+MBVC2000**-1A*+TXV | | 32,000 | $1,600 |
| No | 201866415 | FRANKLIN | AVZC200361A* | AVPEC59D14A* | | 18,900 | $945 |
| No | 203327616 | FRANKLIN | AVZC200481A* | AVPEC59D14A* | | 27,000 | $1,350 |
| No | 205976242 | FRANKLIN | AVZC200601B* | AVPEC61D14A* | | 32,600 | $1,630 |
| No | 205976221 | FRANKLIN | AVZC200601B* | CA*F4961*6D*+TXV | G*VC961005CNB* | 32,000 | $1,600 |
| No | 205976222 | FRANKLIN | AVZC200601B* | CA*F4961*6D*+TXV | G*VC961205DNB* | 32,000 | $1,600 |
| No | 205976223 | FRANKLIN | AVZC200601B* | CA*F4961*6D*+TXV | G*VM971005CNB* | 32,000 | $1,600 |
| No | 205976219 | FRANKLIN | AVZC200601B* | CA*F4961*6D*+TXV | G*VC800805C*A* | 32,000 | $1,600 |
| No | 205976220 | FRANKLIN | AVZC200601B* | CA*F4961*6D*+TXV | G*VC801005C*A* | 32,000 | $1,600 |
| No | 205976235 | FRANKLIN | AVZC200601B* | CSCF4860N6D*+TXV | G*VC801005C*A* | 32,000 | $1,600 |
| No | 205976225 | FRANKLIN | AVZC200601B* | CA*F4961*6D*+TXV | G*VS800805CUA* | 32,000 | $1,600 |
| No | 205976226 | FRANKLIN | AVZC200601B* | CA*F4961*6D*+TXV | G*VS960805CUA* | 32,000 | $1,600 |
| No | 205976233 | FRANKLIN | AVZC200601B* | CHPF4860D6D*+MBVC2000**-1A*+TXV | | 32,000 | $1,600 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205976224 | FRANKLIN | AVZC200601B* | CA*F4961*6D*+TXV | G*VM971205DNB* | 32,000 | $1,600 |
| No | 205976244 | FRANKLIN | AVZC200601B* | CHPF4860D6D*+MBVC2001**-1A*+TXV | | 32,000 | $1,600 |
| No | 205976227 | FRANKLIN | AVZC200601B* | CHPF4860D6D*+TXV | G*VC800805C*A* | 32,000 | $1,600 |
| No | 205976228 | FRANKLIN | AVZC200601B* | CHPF4860D6D*+TXV | G*VC801005C*A* | 32,000 | $1,600 |
| No | 205976229 | FRANKLIN | AVZC200601B* | CHPF4860D6D*+TXV | G*VC961005CNB* | 32,000 | $1,600 |
| No | 205976232 | FRANKLIN | AVZC200601B* | CHPF4860D6D*+TXV | G*VM971205DNB* | 32,000 | $1,600 |
| No | 205976230 | FRANKLIN | AVZC200601B* | CHPF4860D6D*+TXV | G*VC961205DNB* | 32,000 | $1,600 |
| No | 205976231 | FRANKLIN | AVZC200601B* | CHPF4860D6D*+TXV | G*VM971005CNB* | 32,000 | $1,600 |
| No | 205976300 | FRANKLIN | AVZC200601B* | CHPF4860D6D*+TXV | G*VS800805CUA* | 32,000 | $1,600 |
| No | 205976301 | FRANKLIN | AVZC200601B* | CHPF4860D6D*+TXV | G*VS960805CUA* | 32,000 | $1,600 |
| No | 205976234 | FRANKLIN | AVZC200601B* | CSCF4860N6D*+TXV | G*VC800805C*A* | 32,000 | $1,600 |
| No | 205976236 | FRANKLIN | AVZC200601B* | CSCF4860N6D*+TXV | G*VC961005CNB* | 32,000 | $1,600 |
| No | 205976238 | FRANKLIN | AVZC200601B* | CSCF4860N6D*+TXV | G*VM971005CNB* | 32,000 | $1,600 |
| No | 205976237 | FRANKLIN | AVZC200601B* | CSCF4860N6D*+TXV | G*VC961205DNB* | 32,000 | $1,600 |
| No | 206144807 | FRANKLIN | GVZC200241A* | CA*F3137*6A*+TXV | G*VC960403BNB* | 13,000 | $650 |
| No | 206144806 | FRANKLIN | GVZC200241A* | CA*F3137*6A*+TXV | G*VC800604B*A* | 13,000 | $650 |
| No | 205976240 | FRANKLIN | AVZC200601B* | CSCF4860N6D*+TXV | G*VS800805CUA* | 32,000 | $1,600 |
| No | 206144808 | FRANKLIN | GVZC200241A* | CA*F3137*6A*+TXV | G*VC960603BNB* | 13,000 | $650 |
| No | 205976241 | FRANKLIN | AVZC200601B* | CSCF4860N6D*+TXV | G*VS960805CUA* | 32,000 | $1,600 |
| No | 205976239 | FRANKLIN | AVZC200601B* | CSCF4860N6D*+TXV | G*VM971205DNB* | 32,000 | $1,600 |
| No | 206144824 | FRANKLIN | GVZC200241A* | CA*F3743*6D*+TXV | G*VC960804CNB* | 13,000 | $650 |
| No | 206144818 | FRANKLIN | GVZC200241A* | CA*F3642*6D*+TXV | G*VC960803BNB* | 13,000 | $650 |
| No | 206144811 | FRANKLIN | GVZC200241A* | CA*F3636*6D*+TXV | G*VC960403BNB* | 13,000 | $650 |
| No | 206144810 | FRANKLIN | GVZC200241A* | CA*F3636*6D*+TXV | G*VC800604B*A* | 13,000 | $650 |
| No | 206144809 | FRANKLIN | GVZC200241A* | CA*F3137*6A*+TXV | G*VC960803BNB* | 13,000 | $650 |
| No | 206144812 | FRANKLIN | GVZC200241A* | CA*F3636*6D*+TXV | G*VC960603BNB* | 13,000 | $650 |
| No | 206144813 | FRANKLIN | GVZC200241A* | CA*F3636*6D*+TXV | G*VC960803BNB* | 13,000 | $650 |
| No | 206144815 | FRANKLIN | GVZC200241A* | CA*F3642*6D*+TXV | G*VC800604B*A* | 13,000 | $650 |
| No | 206144816 | FRANKLIN | GVZC200241A* | CA*F3642*6D*+TXV | G*VC960403BNB* | 13,000 | $650 |
| No | 206144814 | FRANKLIN | GVZC200241A* | CA*F3636*6D*+TXV | G*VC960804CNB* | 13,000 | $650 |
| No | 206144819 | FRANKLIN | GVZC200241A* | CA*F3642*6D*+TXV | G*VC960804CNB* | 13,000 | $650 |
| No | 206144820 | FRANKLIN | GVZC200241A* | CA*F3743*6D*+TXV | G*VC800604B*A* | 13,000 | $650 |
| No | 206144821 | FRANKLIN | GVZC200241A* | CA*F3743*6D*+TXV | G*VC960403BNB* | 13,000 | $650 |
| No | 206144817 | FRANKLIN | GVZC200241A* | CA*F3642*6D*+TXV | G*VC960603BNB* | 13,000 | $650 |
| No | 206144827 | FRANKLIN | GVZC200241A* | CHPF3636B6C*+TXV | G*VC960603BNB* | 13,000 | $650 |
| No | 206144823 | FRANKLIN | GVZC200241A* | CA*F3743*6D*+TXV | G*VC960803BNB* | 13,000 | $650 |
| No | 206144822 | FRANKLIN | GVZC200241A* | CA*F3743*6D*+TXV | G*VC960603BNB* | 13,000 | $650 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206144825 | FRANKLIN | GVZC200241A* | CHPF3636B6C*+TXV | G*VC800604B*A* | 13,000 | $650 |
| No | 206144826 | FRANKLIN | GVZC200241A* | CHPF3636B6C*+TXV | G*VC960403BNB* | 13,000 | $650 |
| No | 206144830 | FRANKLIN | GVZC200241A* | CSCF3642N6D*+TXV | G*VC960403BNB* | 13,000 | $650 |
| No | 206144828 | FRANKLIN | GVZC200241A* | CHPF3636B6C*+TXV | G*VC960803BNB* | 13,000 | $650 |
| No | 206144829 | FRANKLIN | GVZC200241A* | CSCF3642N6D*+TXV | G*VC800604B*A* | 13,000 | $650 |
| No | 206144831 | FRANKLIN | GVZC200241A* | CSCF3642N6D*+TXV | G*VC960603BNB* | 13,000 | $650 |
| No | 206144832 | FRANKLIN | GVZC200241A* | CSCF3642N6D*+TXV | G*VC960803BNB* | 13,000 | $650 |
| No | 206144833 | FRANKLIN | GVZC200241A* | CSCF3642N6D*+TXV | G*VC960804CNB* | 13,000 | $650 |
| No | 206144981 | FRANKLIN | GVZC200361A* | CA*F3137*6A*+TXV | G*VC960403BNB* | 18,200 | $910 |
| No | 206144835 | FRANKLIN | GVZC200241A* | CSCF3642N6D*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 206144834 | FRANKLIN | GVZC200241A* | CSCF3642N6D*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 206144836 | FRANKLIN | GVZC200241A* | CSCF3642N6D*+TXV | G*VM970804CNB* | 13,000 | $650 |
| No | 206144980 | FRANKLIN | GVZC200361A* | CA*F3137*6A*+TXV | G*VC800604B*A* | 18,200 | $910 |
| No | 206144982 | FRANKLIN | GVZC200361A* | CA*F3137*6A*+TXV | G*VC960603BNB* | 18,200 | $910 |
| No | 206144986 | FRANKLIN | GVZC200361A* | CA*F3642*6D*+TXV | G*VC801005C*A* | 18,000 | $900 |
| No | 206144983 | FRANKLIN | GVZC200361A* | CA*F3137*6A*+TXV | G*VC960803BNB* | 18,200 | $910 |
| No | 206144985 | FRANKLIN | GVZC200361A* | CA*F3642*6D*+TXV | G*VC800805C*A* | 18,000 | $900 |
| No | 206144984 | FRANKLIN | GVZC200361A* | CA*F3642*6D*+TXV | G*VC800604B*A* | 18,200 | $910 |
| No | 206144999 | FRANKLIN | GVZC200361A* | CA*F3743*6D*+TXV | G*VC960804CNB* | 18,000 | $900 |
| No | 206144987 | FRANKLIN | GVZC200361A* | CA*F3642*6D*+TXV | G*VC960403BNB* | 18,000 | $900 |
| No | 206145000 | FRANKLIN | GVZC200361A* | CA*F3743*6D*+TXV | G*VC961005CNB* | 18,200 | $910 |
| No | 206144990 | FRANKLIN | GVZC200361A* | CA*F3642*6D*+TXV | G*VC960804CNB* | 18,200 | $910 |
| No | 206144988 | FRANKLIN | GVZC200361A* | CA*F3642*6D*+TXV | G*VC960603BNB* | 18,000 | $900 |
| No | 206144989 | FRANKLIN | GVZC200361A* | CA*F3642*6D*+TXV | G*VC960803BNB* | 18,000 | $900 |
| No | 206144992 | FRANKLIN | GVZC200361A* | CA*F3642*6D*+TXV | G*VC961205DNB* | 18,000 | $900 |
| No | 206144991 | FRANKLIN | GVZC200361A* | CA*F3642*6D*+TXV | G*VC961005CNB* | 18,000 | $900 |
| No | 206144993 | FRANKLIN | GVZC200361A* | CA*F3743*6D*+TXV | G*VC800604B*A* | 18,000 | $900 |
| No | 206144994 | FRANKLIN | GVZC200361A* | CA*F3743*6D*+TXV | G*VC800805C*A* | 18,200 | $910 |
| No | 206144997 | FRANKLIN | GVZC200361A* | CA*F3743*6D*+TXV | G*VC960603BNB* | 18,200 | $910 |
| No | 206144998 | FRANKLIN | GVZC200361A* | CA*F3743*6D*+TXV | G*VC960803BNB* | 18,200 | $910 |
| No | 206144995 | FRANKLIN | GVZC200361A* | CA*F3743*6D*+TXV | G*VC801005C*A* | 18,200 | $910 |
| No | 206144996 | FRANKLIN | GVZC200361A* | CA*F3743*6D*+TXV | G*VC960403BNB* | 18,200 | $910 |
| No | 206145003 | FRANKLIN | GVZC200361A* | CHPF3642C6C*+TXV | G*VC800805C*A* | 18,000 | $900 |
| No | 206145001 | FRANKLIN | GVZC200361A* | CA*F3743*6D*+TXV | G*VC961205DNB* | 18,200 | $910 |
| No | 206145004 | FRANKLIN | GVZC200361A* | CHPF3642C6C*+TXV | G*VC801005C*A* | 18,000 | $900 |
| No | 206145005 | FRANKLIN | GVZC200361A* | CHPF3642C6C*+TXV | G*VC960403BNB* | 18,000 | $900 |
| No | 206145002 | FRANKLIN | GVZC200361A* | CHPF3642C6C*+TXV | G*VC800604B*A* | 18,000 | $900 |
| No | 206145006 | FRANKLIN | GVZC200361A* | CHPF3642C6C*+TXV | G*VC960603BNB* | 18,000 | $900 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206145007 | FRANKLIN | GVZC200361A* | CHPF3642C6C*+TXV | G*VC960803BNB* | 18,000 | $900 |
| No | 206145008 | FRANKLIN | GVZC200361A* | CHPF3642C6C*+TXV | G*VC960804CNB* | 18,000 | $900 |
| No | 206145011 | FRANKLIN | GVZC200361A* | CHPF3743C6B*+TXV | G*VC800805C*A* | 18,200 | $910 |
| No | 206145010 | FRANKLIN | GVZC200361A* | CHPF3743C6B*+TXV | G*VC800604B*A* | 18,200 | $910 |
| No | 206145009 | FRANKLIN | GVZC200361A* | CHPF3642C6C*+TXV | G*VC961005CNB* | 18,000 | $900 |
| No | 206145012 | FRANKLIN | GVZC200361A* | CHPF3743C6B*+TXV | G*VC801005C*A* | 18,200 | $910 |
| No | 206145016 | FRANKLIN | GVZC200361A* | CHPF3743C6B*+TXV | G*VC960804CNB* | 18,200 | $910 |
| No | 206145014 | FRANKLIN | GVZC200361A* | CHPF3743C6B*+TXV | G*VC960603BNB* | 18,200 | $910 |
| No | 206145017 | FRANKLIN | GVZC200361A* | CHPF3743C6B*+TXV | G*VC961005CNB* | 18,200 | $910 |
| No | 206145013 | FRANKLIN | GVZC200361A* | CHPF3743C6B*+TXV | G*VC960403BNB* | 18,200 | $910 |
| No | 206145195 | FRANKLIN | GVZC200481A* | CA*F4860*6D*+TXV | G*VC800805C*A* | 27,400 | $1,370 |
| No | 206145015 | FRANKLIN | GVZC200361A* | CHPF3743C6B*+TXV | G*VC960803BNB* | 18,200 | $910 |
| No | 206145018 | FRANKLIN | GVZC200361A* | CHPF3743C6B*+TXV | G*VM970804CNB* | 18,200 | $910 |
| No | 206145019 | FRANKLIN | GVZC200361A* | CHPF3743C6B*+TXV | G*VM971005CNB* | 18,200 | $910 |
| No | 206145020 | FRANKLIN | GVZC200361A* | CSCF3642N6D*+TXV | G*VC800604B*A* | 18,200 | $910 |
| No | 206145022 | FRANKLIN | GVZC200361A* | CSCF3642N6D*+TXV | G*VC801005C*A* | 18,200 | $910 |
| No | 206145021 | FRANKLIN | GVZC200361A* | CSCF3642N6D*+TXV | G*VC800805C*A* | 18,200 | $910 |
| No | 206145023 | FRANKLIN | GVZC200361A* | CSCF3642N6D*+TXV | G*VC960403BNB* | 18,200 | $910 |
| No | 206145024 | FRANKLIN | GVZC200361A* | CSCF3642N6D*+TXV | G*VC960603BNB* | 18,200 | $910 |
| No | 206145027 | FRANKLIN | GVZC200361A* | CSCF3642N6D*+TXV | G*VC961005CNB* | 18,200 | $910 |
| No | 206145025 | FRANKLIN | GVZC200361A* | CSCF3642N6D*+TXV | G*VC960803BNB* | 18,200 | $910 |
| No | 206145026 | FRANKLIN | GVZC200361A* | CSCF3642N6D*+TXV | G*VC960804CNB* | 18,200 | $910 |
| No | 206145194 | FRANKLIN | GVZC200481A* | CA*F4860*6D*+TXV | G*VC800604B*A* | 27,400 | $1,370 |
| No | 206145028 | FRANKLIN | GVZC200361A* | CSCF3642N6D*+TXV | G*VC961205DNB* | 18,200 | $910 |
| No | 206145196 | FRANKLIN | GVZC200481A* | CA*F4860*6D*+TXV | G*VC801005C*A* | 27,400 | $1,370 |
| No | 206145201 | FRANKLIN | GVZC200481A* | CA*F4961*6D*+TXV | G*VC800805C*A* | 27,600 | $1,380 |
| No | 206145198 | FRANKLIN | GVZC200481A* | CA*F4860*6D*+TXV | G*VC961005CNB* | 27,400 | $1,370 |
| No | 206145197 | FRANKLIN | GVZC200481A* | CA*F4860*6D*+TXV | G*VC960804CNB* | 27,400 | $1,370 |
| No | 206145200 | FRANKLIN | GVZC200481A* | CA*F4961*6D*+TXV | G*VC800604B*A* | 28,000 | $1,400 |
| No | 206145199 | FRANKLIN | GVZC200481A* | CA*F4860*6D*+TXV | G*VC961205DNB* | 27,400 | $1,370 |
| No | 206145204 | FRANKLIN | GVZC200481A* | CA*F4961*6D*+TXV | G*VC961005CNB* | 27,800 | $1,390 |
| No | 206145202 | FRANKLIN | GVZC200481A* | CA*F4961*6D*+TXV | G*VC801005C*A* | 27,800 | $1,390 |
| No | 206145203 | FRANKLIN | GVZC200481A* | CA*F4961*6D*+TXV | G*VC960804CNB* | 27,600 | $1,380 |
| No | 206145207 | FRANKLIN | GVZC200481A* | CHPF4860D6D*+TXV | G*VC801005C*A* | 27,600 | $1,380 |
| No | 206145206 | FRANKLIN | GVZC200481A* | CHPF4860D6D*+TXV | G*VC800805C*A* | 27,600 | $1,380 |
| No | 206145205 | FRANKLIN | GVZC200481A* | CA*F4961*6D*+TXV | G*VC961205DNB* | 27,800 | $1,390 |
| No | 206145208 | FRANKLIN | GVZC200481A* | CHPF4860D6D*+TXV | G*VC960804CNB* | 27,800 | $1,390 |
| No | 206145209 | FRANKLIN | GVZC200481A* | CHPF4860D6D*+TXV | G*VC961005CNB* | 27,800 | $1,390 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206145213 | FRANKLIN | GVZC200481A* | CSCF4860N6D*+TXV | G*VC801005C*A* | 27,400 | $1,370 |
| No | 206145210 | FRANKLIN | GVZC200481A* | CHPF4860D6D*+TXV | G*VC961205DNB* | 27,800 | $1,390 |
| No | 206145211 | FRANKLIN | GVZC200481A* | CSCF4860N6D*+TXV | G*VC800604B*A* | 27,400 | $1,370 |
| No | 205976275 | FRANKLIN | GVZC200601A* | CA*F4961*6D*+TXV | G*VM971005CNB* | 32,000 | $1,600 |
| No | 206145212 | FRANKLIN | GVZC200481A* | CSCF4860N6D*+TXV | G*VC800805C*A* | 27,400 | $1,370 |
| No | 206145215 | FRANKLIN | GVZC200481A* | CSCF4860N6D*+TXV | G*VC961005CNB* | 27,400 | $1,370 |
| No | 206145216 | FRANKLIN | GVZC200481A* | CSCF4860N6D*+TXV | G*VC961205DNB* | 27,400 | $1,370 |
| No | 205976140 | FRANKLIN | GVZC200601A* | CA*F4961*6D*+MBVC2000**-1A*+TXV | | 32,000 | $1,600 |
| No | 206145214 | FRANKLIN | GVZC200481A* | CSCF4860N6D*+TXV | G*VC960804CNB* | 27,400 | $1,370 |
| No | 205976293 | FRANKLIN | GVZC200601A* | AVPEC61D14A* | | 32,600 | $1,630 |
| No | 205976271 | FRANKLIN | GVZC200601A* | CA*F4961*6D*+TXV | G*VC800805C*A* | 32,000 | $1,600 |
| No | 205976272 | FRANKLIN | GVZC200601A* | CA*F4961*6D*+TXV | G*VC801005C*A* | 32,000 | $1,600 |
| No | 205976278 | FRANKLIN | GVZC200601A* | CHPF4860D6D*+TXV | G*VC801005C*A* | 32,000 | $1,600 |
| No | 205976294 | FRANKLIN | GVZC200601A* | CA*F4961*6D*+MBVC2001**-1A*+TXV | | 32,000 | $1,600 |
| No | 205976273 | FRANKLIN | GVZC200601A* | CA*F4961*6D*+TXV | G*VC961005CNB* | 32,000 | $1,600 |
| No | 205976276 | FRANKLIN | GVZC200601A* | CA*F4961*6D*+TXV | G*VM971205DNB* | 32,000 | $1,600 |
| No | 205976274 | FRANKLIN | GVZC200601A* | CA*F4961*6D*+TXV | G*VC961205DNB* | 32,000 | $1,600 |
| No | 205976304 | FRANKLIN | GVZC200601A* | CA*F4961*6D*+TXV | G*VS960805CUA* | 32,000 | $1,600 |
| No | 205976277 | FRANKLIN | GVZC200601A* | CA*F4961*6D*+TXV | G*VS800805CUA* | 32,000 | $1,600 |
| No | 205976283 | FRANKLIN | GVZC200601A* | CHPF4860D6D*+MBVC2000**-1A*+TXV | | 32,000 | $1,600 |
| No | 205976295 | FRANKLIN | GVZC200601A* | CHPF4860D6D*+MBVC2001**-1A*+TXV | | 32,000 | $1,600 |
| No | 205976305 | FRANKLIN | GVZC200601A* | CHPF4860D6D*+TXV | G*VC800805C*A* | 32,000 | $1,600 |
| No | 205976280 | FRANKLIN | GVZC200601A* | CHPF4860D6D*+TXV | G*VC961205DNB* | 32,000 | $1,600 |
| No | 205976279 | FRANKLIN | GVZC200601A* | CHPF4860D6D*+TXV | G*VC961005CNB* | 32,000 | $1,600 |
| No | 201866196 | FRANKLIN | AVZC200361A* | CA*F3642*6D*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 205976281 | FRANKLIN | GVZC200601A* | CHPF4860D6D*+TXV | G*VM971005CNB* | 32,000 | $1,600 |
| No | 205976282 | FRANKLIN | GVZC200601A* | CHPF4860D6D*+TXV | G*VM971205DNB* | 32,000 | $1,600 |
| No | 205976306 | FRANKLIN | GVZC200601A* | CHPF4860D6D*+TXV | G*VS960805CUA* | 32,000 | $1,600 |
| No | 205976284 | FRANKLIN | GVZC200601A* | CHPF4860D6D*+TXV | G*VS800805CUA* | 32,000 | $1,600 |
| No | 205976285 | FRANKLIN | GVZC200601A* | CSCF4860N6D*+TXV | G*VC800805C*A* | 32,000 | $1,600 |
| No | 205976286 | FRANKLIN | GVZC200601A* | CSCF4860N6D*+TXV | G*VC801005C*A* | 32,000 | $1,600 |
| No | 205976287 | FRANKLIN | GVZC200601A* | CSCF4860N6D*+TXV | G*VC961005CNB* | 32,000 | $1,600 |
| No | 205976289 | FRANKLIN | GVZC200601A* | CSCF4860N6D*+TXV | G*VM971005CNB* | 32,000 | $1,600 |
| No | 205976288 | FRANKLIN | GVZC200601A* | CSCF4860N6D*+TXV | G*VC961205DNB* | 32,000 | $1,600 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205976290 | FRANKLIN | GVZC200601A* | CSCF4860N6D*+TXV | G*VM971205DNB* | 32,000 | $1,600 |
| No | 205976291 | FRANKLIN | GVZC200601A* | CSCF4860N6D*+TXV | G*VS800805CUA* | 32,000 | $1,600 |
| No | 201866223 | FRANKLIN | AVZC200361A* | CHPF3642C6C*+MBVC1600**-1A*+TXV | | 18,000 | $900 |
| No | 205976292 | FRANKLIN | GVZC200601A* | CSCF4860N6D*+TXV | G*VS960805CUA* | 32,000 | $1,600 |
| No | 201866188 | FRANKLIN | AVZC200361A* | CA*F3137*6A*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 201866187 | FRANKLIN | AVZC200241A* | CA*F3137*6A*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 201866189 | FRANKLIN | AVZC200361A* | CA*F3137*6A*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 201866197 | FRANKLIN | AVZC200361A* | CA*F3642*6D*+MBVC1600**-1A*+TXV | | 18,000 | $900 |
| No | 201866222 | FRANKLIN | AVZC200361A* | CHPF3642C6C*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 201866235 | FRANKLIN | AVZC200361A* | CHPF3743C6B*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 201866236 | FRANKLIN | AVZC200361A* | CHPF3743C6B*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 201866208 | FRANKLIN | AVZC200361A* | CA*F3743*6D*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 201866251 | FRANKLIN | AVZC200361A* | CSCF3642N6D*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 201866267 | FRANKLIN | AVZC200481A* | CA*F4860*6D*+MBVC1600**-1A*+TXV | | 33,400 | $1,670 |
| No | 201866252 | FRANKLIN | AVZC200361A* | CSCF3642N6D*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 201866268 | FRANKLIN | AVZC200481A* | CA*F4860*6D*+MBVC2000**-1A*+TXV | | 33,400 | $1,670 |
| No | 201866278 | FRANKLIN | AVZC200481A* | CA*F4961*6D*+MBVC1600**-1A*+TXV | | 34,000 | $1,700 |
| No | 201866288 | FRANKLIN | AVZC200481A* | CHPF4860D6D*+MBVC1600**-1A*+TXV | | 34,000 | $1,700 |
| No | 201888227 | FRANKLIN | AVZC200241A* | CA*F3642*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 201866299 | FRANKLIN | AVZC200481A* | CSCF4860N6D*+MBVC1600**-1A*+TXV | | 33,400 | $1,670 |
| No | 201866416 | FRANKLIN | AVZC200481A* | AVPEC61D14A* | | 28,600 | $1,430 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201866289 | FRANKLIN | AVZC200481A* | CHPF4860D6D*+MBVC2000**-1A*+TXV | | 34,000 | $1,700 |
| No | 201866300 | FRANKLIN | AVZC200481A* | CSCF4860N6D*+MBVC2000**-1A*+TXV | | 33,400 | $1,670 |
| No | 201900162 | FRANKLIN | AVZC200241A* | CA*F3636*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205358222 | FRANKLIN | AVZC200241A* | CA*F3636*6D*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 201900179 | FRANKLIN | AVZC200241A* | CA*F3743*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 201900188 | FRANKLIN | AVZC200241A* | CHPF3636B6C*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 201900301 | FRANKLIN | AVZC200481A* | CA*F4961*6D*+MBVC2000**-1A*+TXV | | 34,000 | $1,700 |
| No | 201900300 | FRANKLIN | AVZC200361A* | CA*F3743*6D*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 205358230 | FRANKLIN | AVZC200361A* | CHPF3642C6C*+MBVC1201**-1A*+TXV | | 18,000 | $900 |
| No | 203327612 | FRANKLIN | AVZC200241A* | CHPF3642C6C*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205358232 | FRANKLIN | AVZC200361A* | CSCF3642N6D*+MBVC1201**-1A*+TXV | | 18,200 | $910 |
| No | 205358223 | FRANKLIN | AVZC200241A* | CA*F3743*6D*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205358221 | FRANKLIN | AVZC200241A* | CA*F3137*6A*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205358224 | FRANKLIN | AVZC200241A* | CHPF3636B6C*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205358225 | FRANKLIN | AVZC200241A* | CA*F3642*6D*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205358226 | FRANKLIN | AVZC200241A* | CHPF3642C6C*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205358227 | FRANKLIN | AVZC200361A* | CA*F3137*6A*+MBVC1201**-1A*+TXV | | 18,000 | $900 |
| No | 205358228 | FRANKLIN | AVZC200361A* | CA*F3642*6D*+MBVC1201**-1A*+TXV | | 18,000 | $900 |
| No | 205358229 | FRANKLIN | AVZC200361A* | CA*F3743*6D*+MBVC1201**-1A*+TXV | | 18,200 | $910 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205358234 | FRANKLIN | AVZC200361A* | CA*F3642*6D*+MBVC1601**-1A*+TXV | | 18,000 | $900 |
| No | 205358231 | FRANKLIN | AVZC200361A* | CHPF3743C6B*+MBVC1201**-1A*+TXV | | 18,200 | $910 |
| No | 205358235 | FRANKLIN | AVZC200361A* | CHPF3642C6C*+MBVC1601**-1A*+TXV | | 18,000 | $900 |
| No | 205358233 | FRANKLIN | AVZC200361A* | CA*F3137*6A*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205358236 | FRANKLIN | AVZC200361A* | CHPF3743C6B*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205358237 | FRANKLIN | AVZC200361A* | CSCF3642N6D*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205358239 | FRANKLIN | AVZC200481A* | CA*F4860*6D*+MBVC1601**-1A*+TXV | | 26,600 | $1,330 |
| No | 205358238 | FRANKLIN | AVZC200361A* | CA*F3743*6D*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205358242 | FRANKLIN | AVZC200481A* | CSCF4860N6D*+MBVC1601**-1A*+TXV | | 26,600 | $1,330 |
| No | 205358241 | FRANKLIN | AVZC200481A* | CHPF4860D6D*+MBVC1601**-1A*+TXV | | 26,600 | $1,330 |
| No | 205358240 | FRANKLIN | AVZC200481A* | CA*F4961*6D*+MBVC1601**-1A*+TXV | | 26,800 | $1,340 |
| No | 205358243 | FRANKLIN | AVZC200481A* | CA*F4860*6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205358244 | FRANKLIN | AVZC200481A* | CHPF4860D6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205358245 | FRANKLIN | AVZC200481A* | CSCF4860N6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965610 | FRANKLIN | GVZC200241A* | CA*F3137*6A*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205965606 | FRANKLIN | GVZC200241A* | CA*F3642*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205965608 | FRANKLIN | GVZC200481A* | CA*F4961*6D*+MBVC2000**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965607 | FRANKLIN | GVZC200361A* | CA*F3743*6D*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 205965609 | FRANKLIN | GVZC200241A* | CA*F3137*6A*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205358246 | FRANKLIN | AVZC200481A* | CA*F4961*6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965613 | FRANKLIN | GVZC200241A* | CA*F3137*6A*+TXV | G*VS960603BUA* | 13,000 | $650 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205965611 | FRANKLIN | GVZC200241A* | CA*F3137*6A*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205965615 | FRANKLIN | GVZC200241A* | CA*F3636*6D*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205965612 | FRANKLIN | GVZC200241A* | CA*F3137*6A*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205965614 | FRANKLIN | GVZC200241A* | CA*F3636*6D*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205965616 | FRANKLIN | GVZC200241A* | CA*F3636*6D*+TXV | G*VM970804CNB* | 13,000 | $650 |
| No | 205965617 | FRANKLIN | GVZC200241A* | CA*F3636*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205965619 | FRANKLIN | GVZC200241A* | CA*F3636*6D*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205965618 | FRANKLIN | GVZC200241A* | CA*F3636*6D*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205965620 | FRANKLIN | GVZC200241A* | CA*F3642*6D*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205965622 | FRANKLIN | GVZC200241A* | CA*F3642*6D*+TXV | G*VM970804CNB* | 13,000 | $650 |
| No | 205965621 | FRANKLIN | GVZC200241A* | CA*F3642*6D*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205965623 | FRANKLIN | GVZC200241A* | CA*F3743*6D*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205965625 | FRANKLIN | GVZC200241A* | CA*F3743*6D*+TXV | G*VM970804CNB* | 13,000 | $650 |
| No | 205965626 | FRANKLIN | GVZC200241A* | CA*F3743*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205965624 | FRANKLIN | GVZC200241A* | CA*F3743*6D*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205965627 | FRANKLIN | GVZC200241A* | CA*F3743*6D*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205965628 | FRANKLIN | GVZC200241A* | CA*F3743*6D*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205965631 | FRANKLIN | GVZC200241A* | CHPF3636B6C*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205965632 | FRANKLIN | GVZC200241A* | CHPF3636B6C*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205965633 | FRANKLIN | GVZC200241A* | CHPF3636B6C*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205965634 | FRANKLIN | GVZC200241A* | CHPF3642C6C*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205965630 | FRANKLIN | GVZC200241A* | CHPF3636B6C*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205965629 | FRANKLIN | GVZC200241A* | CHPF3636B6C*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205965644 | FRANKLIN | GVZC200361A* | CA*F3137*6A*+TXV | G*VM970603BNB* | 18,200 | $910 |
| No | 205965650 | FRANKLIN | GVZC200361A* | CA*F3642*6D*+TXV | G*VM970603BNB* | 18,000 | $900 |
| No | 205965635 | FRANKLIN | GVZC200241A* | CSCF3642N6D*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205965636 | FRANKLIN | GVZC200241A* | CSCF3642N6D*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205965640 | FRANKLIN | GVZC200241A* | CA*F3642*6D*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205965639 | FRANKLIN | GVZC200241A* | CA*F3636*6D*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205965638 | FRANKLIN | GVZC200241A* | CA*F3137*6A*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205965637 | FRANKLIN | GVZC200241A* | AVPEC25B14A* | | 13,600 | $680 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205965641 | FRANKLIN | GVZC200241A* | CA*F3743*6D*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205965642 | FRANKLIN | GVZC200241A* | CHPF3636B6C*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205965645 | FRANKLIN | GVZC200361A* | CA*F3137*6A*+TXV | G*VM970803BNB* | 18,200 | $910 |
| No | 205965643 | FRANKLIN | GVZC200241A* | CHPF3642C6C*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205965649 | FRANKLIN | GVZC200361A* | CA*F3137*6A*+TXV | G*VS960603BUA* | 18,200 | $910 |
| No | 205965647 | FRANKLIN | GVZC200361A* | CA*F3137*6A*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 205965646 | FRANKLIN | GVZC200361A* | CA*F3137*6A*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 205965648 | FRANKLIN | GVZC200361A* | CA*F3137*6A*+TXV | G*VS800604BUA* | 18,200 | $910 |
| No | 205965651 | FRANKLIN | GVZC200361A* | CA*F3642*6D*+TXV | G*VM970803BNB* | 18,000 | $900 |
| No | 205965666 | FRANKLIN | GVZC200361A* | CA*F3743*6D*+TXV | G*VS800805CUA* | 18,200 | $910 |
| No | 205965653 | FRANKLIN | GVZC200361A* | CA*F3642*6D*+TXV | G*VM971005CNB* | 18,000 | $900 |
| No | 205965652 | FRANKLIN | GVZC200361A* | CA*F3642*6D*+TXV | G*VM970804CNB* | 18,200 | $910 |
| No | 205965654 | FRANKLIN | GVZC200361A* | CA*F3642*6D*+TXV | G*VM971205DNB* | 18,000 | $900 |
| No | 205965655 | FRANKLIN | GVZC200361A* | CA*F3642*6D*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 205965656 | FRANKLIN | GVZC200361A* | CA*F3642*6D*+MBVC1600**-1A*+TXV | | 18,000 | $900 |
| No | 205965657 | FRANKLIN | GVZC200361A* | CA*F3642*6D*+TXV | G*VS800604BUA* | 18,200 | $910 |
| No | 205965660 | FRANKLIN | GVZC200361A* | CA*F3642*6D*+TXV | G*VS960805CUA* | 18,000 | $900 |
| No | 205965658 | FRANKLIN | GVZC200361A* | CA*F3642*6D*+TXV | G*VS800805CUA* | 18,000 | $900 |
| No | 205965659 | FRANKLIN | GVZC200361A* | CA*F3642*6D*+TXV | G*VS960603BUA* | 18,000 | $900 |
| No | 205965661 | FRANKLIN | GVZC200361A* | CA*F3743*6D*+TXV | G*VM970603BNB* | 18,200 | $910 |
| No | 205965665 | FRANKLIN | GVZC200361A* | CA*F3743*6D*+TXV | G*VS800604BUA* | 18,000 | $900 |
| No | 205965662 | FRANKLIN | GVZC200361A* | CA*F3743*6D*+TXV | G*VM970803BNB* | 18,200 | $910 |
| No | 205965663 | FRANKLIN | GVZC200361A* | CA*F3743*6D*+TXV | G*VM971205DNB* | 18,200 | $910 |
| No | 205965664 | FRANKLIN | GVZC200361A* | CA*F3743*6D*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 205965667 | FRANKLIN | GVZC200361A* | CA*F3743*6D*+TXV | G*VS960603BUA* | 18,200 | $910 |
| No | 205965669 | FRANKLIN | GVZC200361A* | CHPF3642C6C*+TXV | G*VM970603BNB* | 18,000 | $900 |
| No | 205965668 | FRANKLIN | GVZC200361A* | CA*F3743*6D*+TXV | G*VS960805CUA* | 18,200 | $910 |
| No | 205965670 | FRANKLIN | GVZC200361A* | CHPF3642C6C*+TXV | G*VM970803BNB* | 18,000 | $900 |
| No | 205965671 | FRANKLIN | GVZC200361A* | CHPF3642C6C*+TXV | G*VM970804CNB* | 18,000 | $900 |
| No | 205965673 | FRANKLIN | GVZC200361A* | CHPF3642C6C*+TXV | G*VS800604BUA* | 18,000 | $900 |
| No | 205965675 | FRANKLIN | GVZC200361A* | CHPF3642C6C*+TXV | G*VS960603BUA* | 18,000 | $900 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205965672 | FRANKLIN | GVZC200361A* | CHPF3642C6C*+TXV | G*VM971005CNB* | 18,000 | $900 |
| No | 205965674 | FRANKLIN | GVZC200361A* | CHPF3642C6C*+TXV | G*VS800805CUA* | 18,000 | $900 |
| No | 205965692 | FRANKLIN | GVZC200361A* | CSCF3642N6D*+TXV | G*VS960603BUA* | 18,200 | $910 |
| No | 205965678 | FRANKLIN | GVZC200361A* | CHPF3743C6B*+TXV | G*VM970803BNB* | 18,200 | $910 |
| No | 205965677 | FRANKLIN | GVZC200361A* | CHPF3743C6B*+TXV | G*VM970603BNB* | 18,200 | $910 |
| No | 205965676 | FRANKLIN | GVZC200361A* | CHPF3642C6C*+TXV | G*VS960805CUA* | 18,000 | $900 |
| No | 205965680 | FRANKLIN | GVZC200361A* | CHPF3743C6B*+TXV | G*VS800604BUA* | 18,200 | $910 |
| No | 205965679 | FRANKLIN | GVZC200361A* | CA*F3743*6D*+TXV | G*VM970804CNB* | 18,000 | $900 |
| No | 205965689 | FRANKLIN | GVZC200361A* | CSCF3642N6D*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 205965682 | FRANKLIN | GVZC200361A* | CHPF3743C6B*+TXV | G*VS960603BUA* | 18,200 | $910 |
| No | 205965681 | FRANKLIN | GVZC200361A* | CHPF3743C6B*+TXV | G*VS800805CUA* | 18,200 | $910 |
| No | 205965684 | FRANKLIN | GVZC200361A* | CSCF3642N6D*+TXV | G*VM970603BNB* | 18,200 | $910 |
| No | 205965683 | FRANKLIN | GVZC200361A* | CHPF3743C6B*+TXV | G*VS960805CUA* | 18,200 | $910 |
| No | 205965685 | FRANKLIN | GVZC200361A* | CSCF3642N6D*+TXV | G*VM970803BNB* | 18,200 | $910 |
| No | 205965686 | FRANKLIN | GVZC200361A* | CSCF3642N6D*+TXV | G*VM970804CNB* | 18,200 | $910 |
| No | 205965687 | FRANKLIN | GVZC200361A* | CSCF3642N6D*+TXV | G*VM971005CNB* | 18,200 | $910 |
| No | 205965688 | FRANKLIN | GVZC200361A* | CSCF3642N6D*+TXV | G*VM971205DNB* | 18,200 | $910 |
| No | 205965691 | FRANKLIN | GVZC200361A* | CSCF3642N6D*+TXV | G*VS800805CUA* | 18,200 | $910 |
| No | 205965690 | FRANKLIN | GVZC200361A* | CSCF3642N6D*+TXV | G*VS800604BUA* | 18,200 | $910 |
| No | 205965694 | FRANKLIN | GVZC200481A* | CA*F4860*6D*+MBVC1600**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965693 | FRANKLIN | GVZC200361A* | CSCF3642N6D*+TXV | G*VS960805CUA* | 18,200 | $910 |
| No | 205965708 | FRANKLIN | GVZC200481A* | CSCF4860N6D*+TXV | G*VS960805CUA* | 27,400 | $1,370 |
| No | 205965696 | FRANKLIN | GVZC200481A* | CHPF4860D6D*+TXV | G*VM970804CNB* | 28,000 | $1,400 |
| No | 205965697 | FRANKLIN | GVZC200481A* | CHPF4860D6D*+TXV | G*VM971005CNB* | 27,800 | $1,390 |
| No | 205965695 | FRANKLIN | GVZC200481A* | CA*F4860*6D*+TXV | G*VS960805CUA* | 27,400 | $1,370 |
| No | 205965699 | FRANKLIN | GVZC200481A* | CHPF4860D6D*+MBVC1600**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965698 | FRANKLIN | GVZC200481A* | CHPF4860D6D*+TXV | G*VM971205DNB* | 27,800 | $1,390 |
| No | 205965700 | FRANKLIN | GVZC200481A* | CHPF4860D6D*+TXV | G*VS800805CUA* | 27,200 | $1,360 |
| No | 205965701 | FRANKLIN | GVZC200481A* | CSCF4860N6D*+TXV | G*VM970804CNB* | 27,400 | $1,370 |
| No | 205965702 | FRANKLIN | GVZC200481A* | CSCF4860N6D*+TXV | G*VM971005CNB* | 27,400 | $1,370 |
| No | 205965717 | FRANKLIN | GVZC200481A* | CA*F4961*6D*+TXV | G*VM971005CNB* | 27,800 | $1,390 |
| No | 205965704 | FRANKLIN | GVZC200481A* | CSCF4860N6D*+MBVC1600**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965705 | FRANKLIN | GVZC200481A* | CSCF4860N6D*+MBVC2000**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965703 | FRANKLIN | GVZC200481A* | CSCF4860N6D*+TXV | G*VM971205DNB* | 27,400 | $1,370 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205965706 | FRANKLIN | GVZC200481A* | CSCF4860N6D*+TXV | G*VS800604BUA* | 27,400 | $1,370 |
| No | 205965707 | FRANKLIN | GVZC200481A* | CSCF4860N6D*+TXV | G*VS800805CUA* | 27,400 | $1,370 |
| No | 205965709 | FRANKLIN | GVZC200481A* | AVPEC59D14A* | | 27,000 | $1,350 |
| No | 205965710 | FRANKLIN | GVZC200481A* | CA*F4860*6D*+MBVC1601**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965712 | FRANKLIN | GVZC200481A* | CHPF4860D6D*+MBVC1601**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965711 | FRANKLIN | GVZC200481A* | CA*F4860*6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965715 | FRANKLIN | GVZC200481A* | CSCF4860N6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965713 | FRANKLIN | GVZC200481A* | CHPF4860D6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205965716 | FRANKLIN | GVZC200481A* | CA*F4961*6D*+TXV | G*VM970804CNB* | 27,800 | $1,390 |
| No | 205965714 | FRANKLIN | GVZC200481A* | CSCF4860N6D*+MBVC1601**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966420 | FRANKLIN | GVZC200361A* | CA*F3743*6D*+TXV | G*VM971005CNB* | 18,200 | $910 |
| No | 205965720 | FRANKLIN | GVZC200481A* | CA*F4961*6D*+TXV | G*VS800604BUA* | 28,000 | $1,400 |
| No | 205965718 | FRANKLIN | GVZC200481A* | CA*F4961*6D*+TXV | G*VM971205DNB* | 27,800 | $1,390 |
| No | 205965719 | FRANKLIN | GVZC200481A* | CA*F4961*6D*+MBVC1600**-1A*+TXV | | 26,800 | $1,340 |
| No | 205966422 | FRANKLIN | GVZC200361A* | CHPF3743C6B*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 205965721 | FRANKLIN | GVZC200481A* | CA*F4961*6D*+TXV | G*VS800805CUA* | 27,200 | $1,360 |
| No | 205965722 | FRANKLIN | GVZC200481A* | CA*F4961*6D*+TXV | G*VS960805CUA* | 27,600 | $1,380 |
| No | 205965723 | FRANKLIN | GVZC200481A* | CHPF4860D6D*+MBVC2000**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966425 | FRANKLIN | GVZC200361A* | AVPEC59D14A* | | 18,900 | $945 |
| No | 205965724 | FRANKLIN | GVZC200481A* | CA*F4961*6D*+MBVC1601**-1A*+TXV | | 26,800 | $1,340 |
| No | 205965725 | FRANKLIN | GVZC200481A* | CA*F4961*6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966043 | FRANKLIN | GVZC200361A* | CHPF3642C6C*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 205966419 | FRANKLIN | GVZC200361A* | CHPF3642C6C*+MBVC1600**-1A*+TXV | | 18,000 | $900 |
| No | 205966421 | FRANKLIN | GVZC200361A* | CHPF3743C6B*+MBVC1200**-1A*+TXV | | 18,200 | $910 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966423 | FRANKLIN | GVZC200361A* | CSCF3642N6D*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 205966428 | FRANKLIN | GVZC200361A* | CA*F3642*6D*+MBVC1201**-1A*+TXV | | 18,000 | $900 |
| No | 205966427 | FRANKLIN | GVZC200361A* | CA*F3137*6A*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205966429 | FRANKLIN | GVZC200361A* | CA*F3642*6D*+MBVC1601**-1A*+TXV | | 18,000 | $900 |
| No | 205966424 | FRANKLIN | GVZC200361A* | AVPEC37C14A* | | 18,900 | $945 |
| No | 205966426 | FRANKLIN | GVZC200361A* | CA*F3137*6A*+MBVC1201**-1A*+TXV | | 18,000 | $900 |
| No | 205966430 | FRANKLIN | GVZC200361A* | CA*F3743*6D*+MBVC1201**-1A*+TXV | | 18,200 | $910 |
| No | 205966434 | FRANKLIN | GVZC200361A* | CHPF3743C6B*+MBVC1201**-1A*+TXV | | 18,200 | $910 |
| No | 205966432 | FRANKLIN | GVZC200361A* | CHPF3642C6C*+MBVC1201**-1A*+TXV | | 18,000 | $900 |
| No | 205966431 | FRANKLIN | GVZC200361A* | CA*F3743*6D*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205966433 | FRANKLIN | GVZC200361A* | CHPF3642C6C*+MBVC1601**-1A*+TXV | | 18,000 | $900 |
| No | 205966436 | FRANKLIN | GVZC200361A* | CSCF3642N6D*+MBVC1201**-1A*+TXV | | 18,200 | $910 |
| No | 205966437 | FRANKLIN | GVZC200361A* | CSCF3642N6D*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205966435 | FRANKLIN | GVZC200361A* | CHPF3743C6B*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205966438 | FRANKLIN | GVZC200481A* | CA*F4860*6D*+TXV | G*VM970804CNB* | 27,400 | $1,370 |
| No | 205966439 | FRANKLIN | GVZC200481A* | CA*F4860*6D*+TXV | G*VM971005CNB* | 27,400 | $1,370 |
| No | 205966440 | FRANKLIN | GVZC200481A* | CA*F4860*6D*+TXV | G*VM971205DNB* | 27,400 | $1,370 |
| No | 205966442 | FRANKLIN | GVZC200481A* | CA*F4860*6D*+TXV | G*VS800805CUA* | 27,400 | $1,370 |
| No | 205966441 | FRANKLIN | GVZC200481A* | CA*F4860*6D*+MBVC2000**-1A*+TXV | | 26,600 | $1,330 |
| No | 206764064 | FRANKLIN | MSH183E23MCAA | MSH183E23AXAA | | 10,900 | $545 |
| No | 206764063 | FRANKLIN | MSH123E23MCAA | MSH123E23AXAA | | 7,500 | $375 |
| No | 206764062 | FRANKLIN | MSH093E23MCAA | MSH093E23AXAA | | 7,100 | $355 |
| No | 206764070 | FRANKLIN | MST183E23MHAA | Combination heat pumps with or without ducts | | 11,500 | $575 |
| No | 206900418 | FRANKLIN | MSH093E21MCAA | MSH093E21AXAA | | 6,400 | $320 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206900413 | FRANKLIN | MSH183E19MCAA | MSH183E19AXAA | | 11,000 | $550 |
| No | 206900416 | FRANKLIN | MSH183E21MCAA | MSH183E21AXAA | | 10,400 | $520 |
| No | 206900441 | FRANKLIN | MSH183E21MCAA | MST183E21ADAA | | 12,000 | $600 |
| No | 206900442 | FRANKLIN | MSH243E21MCAA | MST243E21ADAA | | 16,000 | $800 |
| No | 206900439 | FRANKLIN | MSH093E21MCAA | MST093E21ADAA | | 6,800 | $340 |
| No | 206900445 | FRANKLIN | MSH603E18MCAA | MST603E18ADAA | | 37,600 | $1,880 |
| No | 206900443 | FRANKLIN | MSH363E18MCAA | MST363E18ADAA | | 27,600 | $1,380 |
| No | 206900444 | FRANKLIN | MSH483E18MCAA | MST483E18ADAA | | 33,400 | $1,670 |
| No | 206900431 | FRANKLIN | MSH093E21MCAA | MST093E20ACAA | | 5,800 | $290 |
| No | 206900446 | FRANKLIN | MSH123E21MCAA | MST123E20ACAA | | 7,500 | $375 |
| No | 206900447 | FRANKLIN | MSH183E21MCAA | MST183E20ACAA | | 12,000 | $600 |
| No | 206764074 | FRANKLIN | MST363E23MHAA | Heat pump without ducts | | 23,200 | $1,160 |
| No | 206764075 | FRANKLIN | MST363E23MHAA | Heat pump with ducts | | 24,600 | $1,230 |
| No | 211238540 | FRASER-JOHNSTON | HMH72B341 | JHETC36DBCS2N1 | | 24,600 | $1,230 |
| No | 211662225 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+JMET12BS2N1+TXV | | 24,800 | $1,240 |
| No | 211662220 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+JMET12BS2N1+TXV | | 24,800 | $1,240 |
| No | 211662215 | FRASER-JOHNSTON | HMH72B361 | XAHB30CXXN1+JMET12BS2N1+TXV | | 23,800 | $1,190 |
| No | 211662210 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+JMVT12BC2N1+TXV | | 24,600 | $1,230 |
| No | 211662205 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+JMVT12BC2N1+TXV | | 24,600 | $1,230 |
| No | 211662200 | FRASER-JOHNSTON | HMH72B361 | XAHB30CXXN1+JMVT12BC2N1+TXV | | 24,200 | $1,210 |
| No | 211662195 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+TXV | TMLE040A12MP11 | 24,400 | $1,220 |
| No | 211662190 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+TXV | TM8E040A12MP11 | 24,400 | $1,220 |
| No | 211662185 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+TXV | TMLE040A12MP11 | 24,400 | $1,220 |
| No | 211662180 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+TXV | TM8E040A12MP11 | 24,400 | $1,220 |
| No | 211662175 | FRASER-JOHNSTON | HMH72B361 | XAHB30CXXN1+TXV | TMLE040A12MP11 | 23,800 | $1,190 |
| No | 211662170 | FRASER-JOHNSTON | HMH72B361 | XAHB30CXXN1+TXV | TM8E040A12MP11 | 23,800 | $1,190 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211662165 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+TXV | TL8E060A12UH11 | 24,400 | $1,220 |
| No | 211662160 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+TXV | TL8E060A12UH11 | 24,400 | $1,220 |
| No | 211662155 | FRASER-JOHNSTON | HMH72B361 | XAHB30CXXN1+TXV | TL8E060A12UH11 | 24,000 | $1,200 |
| No | 211662150 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TL8E080C16UH11 | 25,200 | $1,260 |
| No | 211662145 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TL8E080C16UH11 | 24,800 | $1,240 |
| No | 211662140 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TL8E100C20UH11 | 24,400 | $1,220 |
| No | 211662135 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TL8E100C20UH11 | 24,000 | $1,200 |
| No | 211662130 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 211662125 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 211662120 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 211662115 | FRASER-JOHNSTON | HMH72B361 | XAHB30CXXN1+TXV | TL9E060B12UH11 | 23,600 | $1,180 |
| No | 211662110 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 211662105 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TL9E080C16UH11 | 24,800 | $1,240 |
| No | 211662100 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TL9E080C16UH11 | 24,400 | $1,220 |
| No | 211662095 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TL9E100C20UH11 | 24,600 | $1,230 |
| No | 211662090 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TL9E100C20UH11 | 24,000 | $1,200 |
| No | 211662085 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+TXV | TMLE060A12MP11 | 24,400 | $1,220 |
| No | 211662080 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+TXV | TM8E060A12MP11 | 24,400 | $1,220 |
| No | 211662075 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+TXV | TMLE060A12MP11 | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211662070 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+TXV | TM8E060A12MP11 | 24,400 | $1,220 |
| No | 211662065 | FRASER-JOHNSTON | HMH72B361 | XAHB30CXXN1+TXV | TMLE060A12MP11 | 24,000 | $1,200 |
| No | 211662060 | FRASER-JOHNSTON | HMH72B361 | XAHB30CXXN1+TXV | TM8E060A12MP11 | 24,000 | $1,200 |
| No | 211662055 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 211662050 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 211662045 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 211662040 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 211662035 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 211662030 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 211662025 | FRASER-JOHNSTON | HMH72B361 | XAHB30CXXN1+TXV | TMLE080B12MP11 | 24,400 | $1,220 |
| No | 211662020 | FRASER-JOHNSTON | HMH72B361 | XAHB30CXXN1+TXV | TM8E080B12MP11 | 24,400 | $1,220 |
| No | 211662015 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TMLE080B12MP11 | 24,400 | $1,220 |
| No | 211662010 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TM8E080B12MP11 | 24,400 | $1,220 |
| No | 211662005 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TMLE080C16MP11 | 24,200 | $1,210 |
| No | 211662000 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TM8E080C16MP11 | 24,200 | $1,210 |
| No | 211661995 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TMLE080C16MP11 | 23,800 | $1,190 |
| No | 211661990 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TM8E080C16MP11 | 23,800 | $1,190 |
| No | 211661985 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+TXV | TMLE100B12MP11 | 24,400 | $1,220 |
| No | 211661980 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+TXV | TM8E100B12MP11 | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661975 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+TXV | TMLE100B12MP11 | 24,400 | $1,220 |
| No | 211661970 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+TXV | TM8E100B12MP11 | 24,400 | $1,220 |
| No | 211661965 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TMLE100B12MP11 | 24,400 | $1,220 |
| No | 211661960 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TM8E100B12MP11 | 24,400 | $1,220 |
| No | 211661955 | FRASER-JOHNSTON | HMH72B361 | XAHB30CXXN1+TXV | TMLE100B12MP11 | 24,000 | $1,200 |
| No | 211661950 | FRASER-JOHNSTON | HMH72B361 | XAHB30CXXN1+TXV | TM8E100B12MP11 | 24,000 | $1,200 |
| No | 211661945 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TMLE100B12MP11 | 24,000 | $1,200 |
| No | 211661940 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TM8E100B12MP11 | 24,000 | $1,200 |
| No | 211661935 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TMLE100C16MP11 | 24,200 | $1,210 |
| No | 211661930 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TM8E100C16MP11 | 24,200 | $1,210 |
| No | 211661925 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TMLE100C16MP11 | 23,800 | $1,190 |
| No | 211661920 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TM8E100C16MP11 | 23,800 | $1,190 |
| No | 211661915 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TMLE120C16MP11 | 24,200 | $1,210 |
| No | 211661910 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TM8E120C16MP11 | 24,200 | $1,210 |
| No | 211661905 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TMLE120C16MP11 | 23,800 | $1,190 |
| No | 211661900 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TM8E120C16MP11 | 23,800 | $1,190 |
| No | 211661895 | FRASER-JOHNSTON | HMH72B361 | XAFA30DXXN1+TXV | TPLC060A12MP13 | 25,800 | $1,290 |
| No | 211661890 | FRASER-JOHNSTON | HMH72B361 | XAFA30DXXN1+TXV | TMLV060A12MP12 | 25,800 | $1,290 |
| No | 211661885 | FRASER-JOHNSTON | HMH72B361 | XAFA30DXXN1+TXV | TM8V060A12MP12 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661880 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+TXV | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 211661875 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+TXV | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 211661870 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+TXV | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 211661865 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+TXV | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 211661860 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+TXV | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 211661855 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+TXV | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 211661850 | FRASER-JOHNSTON | HMH72B361 | XAHB30CXXN1+TXV | TPLC060A12MP13 | 24,200 | $1,210 |
| No | 211661845 | FRASER-JOHNSTON | HMH72B361 | XAHB30CXXN1+TXV | TMLV060A12MP12 | 24,200 | $1,210 |
| No | 211661840 | FRASER-JOHNSTON | HMH72B361 | XAHB30CXXN1+TXV | TM8V060A12MP12 | 24,200 | $1,210 |
| No | 211661834 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 211661829 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 211661823 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 211661818 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 211661812 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TPLC080B12MP13 | 24,800 | $1,240 |
| No | 211661807 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TM8V080B12MP12 | 24,800 | $1,240 |
| No | 211661801 | FRASER-JOHNSTON | HMH72B361 | XAHB30CXXN1+TXV | TPLC080B12MP13 | 24,000 | $1,200 |
| No | 211661796 | FRASER-JOHNSTON | HMH72B361 | XAHB30CXXN1+TXV | TM8V080B12MP12 | 24,000 | $1,200 |
| No | 211661790 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TPLC080B12MP13 | 24,200 | $1,210 |
| No | 211661785 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TM8V080B12MP12 | 24,200 | $1,210 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661776 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TPLC100C16MP13 | 25,000 | $1,250 |
| No | 211661771 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TPLC080C16MP13 | 25,000 | $1,250 |
| No | 211661766 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TMLV100C16MP12 | 25,000 | $1,250 |
| No | 211661761 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TM8V080C16MP12 | 25,000 | $1,250 |
| No | 211661756 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TM8V100C16MP12 | 25,000 | $1,250 |
| No | 211661747 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 211661742 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TPLC080C16MP13 | 24,600 | $1,230 |
| No | 211661737 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TMLV100C16MP12 | 24,600 | $1,230 |
| No | 211661727 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 211661722 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+TXV | TM8Y060A12MP11 | 24,200 | $1,210 |
| No | 211661717 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+TXV | TM8Y060A12MP11 | 24,200 | $1,210 |
| No | 211661712 | FRASER-JOHNSTON | HMH72B361 | XAHB30CXXN1+TXV | TM8Y060A12MP11 | 23,800 | $1,190 |
| No | 211661707 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+TXV | TM8Y080B12MP11 | 24,200 | $1,210 |
| No | 211661702 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+TXV | TM8Y080B12MP11 | 24,200 | $1,210 |
| No | 211661697 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TM8Y080B12MP11 | 24,200 | $1,210 |
| No | 211661692 | FRASER-JOHNSTON | HMH72B361 | XAHB30CXXN1+TXV | TM8Y080B12MP11 | 23,800 | $1,190 |
| No | 211661687 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TM8Y080B12MP11 | 23,800 | $1,190 |
| No | 211661682 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TM8Y080C16MP11 | 25,200 | $1,260 |
| No | 211661677 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TM8Y100C16MP11 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661672 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TM8Y080C16MP11 | 24,600 | $1,230 |
| No | 211661667 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TM8Y100C16MP11 | 24,600 | $1,230 |
| No | 211661662 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TM8Y100C20MP11 | 24,800 | $1,240 |
| No | 211661657 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TM8Y120C20MP11 | 24,800 | $1,240 |
| No | 211661652 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TM8Y100C20MP11 | 24,400 | $1,220 |
| No | 211661647 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TM8Y120C20MP11 | 24,400 | $1,220 |
| No | 211661642 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+TXV | TM9E040A10MP12 | 24,200 | $1,210 |
| No | 211661637 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+TXV | TM9E040A10MP12 | 24,200 | $1,210 |
| No | 211661632 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+TXV | TM9E060A10MP12 | 24,400 | $1,220 |
| No | 211661627 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+TXV | TM9E060A10MP12 | 24,400 | $1,220 |
| No | 211661622 | FRASER-JOHNSTON | HMH72B361 | XAHB30CXXN1+TXV | TM9E060A10MP12 | 24,000 | $1,200 |
| No | 211661617 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 211661612 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 211661607 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 211661602 | FRASER-JOHNSTON | HMH72B361 | XAHB30CXXN1+TXV | TM9E060B12MP12 | 24,200 | $1,210 |
| No | 211661597 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 211661592 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 211661587 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 211661582 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661577 | FRASER-JOHNSTON | HMH72B361 | XAHB30CXXN1+TXV | TM9E080B12MP12 | 24,400 | $1,220 |
| No | 211661572 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TM9E080B12MP12 | 24,400 | $1,220 |
| No | 211661567 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TM9E080C16MP12 | 25,200 | $1,260 |
| No | 211661562 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TM9E080C16MP12 | 24,800 | $1,240 |
| No | 211661557 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TM9E100C16MP12 | 24,400 | $1,220 |
| No | 211661552 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TM9E100C16MP12 | 23,800 | $1,190 |
| No | 211661547 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+TXV | TM9V040A10MP12 | 24,400 | $1,220 |
| No | 211661542 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+TXV | TM9V040A10MP12 | 24,400 | $1,220 |
| No | 211661530 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+TXV | TP9C060B12MP13 | 24,600 | $1,230 |
| No | 211661525 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+TXV | TM9V060B12MP12 | 24,600 | $1,230 |
| No | 211661518 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+TXV | TP9C060B12MP13 | 24,600 | $1,230 |
| No | 211661513 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+TXV | TM9V060B12MP12 | 24,600 | $1,230 |
| No | 211661504 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TP9C060B12MP13 | 24,600 | $1,230 |
| No | 211661497 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TM9V060B12MP12 | 24,600 | $1,230 |
| No | 211661490 | FRASER-JOHNSTON | HMH72B361 | XAHB30CXXN1+TXV | TP9C060B12MP13 | 24,000 | $1,200 |
| No | 211661485 | FRASER-JOHNSTON | HMH72B361 | XAHB30CXXN1+TXV | TM9V060B12MP12 | 24,000 | $1,200 |
| No | 211661478 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TP9C060B12MP13 | 24,200 | $1,210 |
| No | 211661473 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TM9V060B12MP12 | 24,200 | $1,210 |
| No | 211661466 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+TXV | TP9C080B12MP13 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661461 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+TXV | TM9V080B12MP12 | 24,800 | $1,240 |
| No | 211661454 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+TXV | TP9C080B12MP13 | 24,800 | $1,240 |
| No | 211661449 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+TXV | TM9V080B12MP12 | 24,800 | $1,240 |
| No | 211661442 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 211661437 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 211661430 | FRASER-JOHNSTON | HMH72B361 | XAHB30CXXN1+TXV | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 211661425 | FRASER-JOHNSTON | HMH72B361 | XAHB30CXXN1+TXV | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 211661418 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 211661413 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 211661406 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TP9C080C16MP13 | 25,200 | $1,260 |
| No | 211661401 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TM9V080C16MP12 | 25,200 | $1,260 |
| No | 211661394 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TP9C080C16MP13 | 24,800 | $1,240 |
| No | 211661389 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TM9V080C16MP12 | 24,800 | $1,240 |
| No | 211661382 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211661377 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TM9V100C16MP12 | 24,800 | $1,240 |
| No | 211661370 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TP9C100C16MP13 | 24,600 | $1,230 |
| No | 211661365 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TM9V100C16MP12 | 24,600 | $1,230 |
| No | 211661358 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TP9C100C20MP13 | 25,000 | $1,250 |
| No | 211661353 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TM9V100C20MP12 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661346 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TP9C100C20MP13 | 24,600 | $1,230 |
| No | 211661341 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TM9V100C20MP12 | 24,600 | $1,230 |
| No | 211661336 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+TXV | TM9Y060B12MP11 | 24,800 | $1,240 |
| No | 211661331 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+TXV | TM9Y060B12MP11 | 24,800 | $1,240 |
| No | 211661326 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TM9Y060B12MP11 | 24,800 | $1,240 |
| No | 211661321 | FRASER-JOHNSTON | HMH72B361 | XAHB30CXXN1+TXV | TM9Y060B12MP11 | 24,200 | $1,210 |
| No | 211661316 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TM9Y060B12MP11 | 24,200 | $1,210 |
| No | 211661311 | FRASER-JOHNSTON | HMH72B361 | XAUB30CXXN1+TXV | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211661306 | FRASER-JOHNSTON | HMH72B361 | XAFB30CXXN1+TXV | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211661301 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211661296 | FRASER-JOHNSTON | HMH72B361 | XAHB30CXXN1+TXV | TM9Y080B12MP11 | 24,400 | $1,220 |
| No | 211661291 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TM9Y080B12MP11 | 24,400 | $1,220 |
| No | 211661286 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TM9Y080C16MP11 | 24,800 | $1,240 |
| No | 211661281 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TM9Y080C16MP11 | 24,400 | $1,220 |
| No | 211661276 | FRASER-JOHNSTON | HMH72B361 | XAFC30CXXN1+TXV | TM9Y100C16MP11 | 24,800 | $1,240 |
| No | 211661271 | FRASER-JOHNSTON | HMH72B361 | XAHC30CXXN1+TXV | TM9Y100C16MP11 | 24,400 | $1,220 |
| No | 211661266 | FRASER-JOHNSTON | HMH72B241 | XAHB30CBAN1 | TM9E040A10MP12 | 15,000 | $750 |
| No | 211661261 | FRASER-JOHNSTON | HMH72B241 | XAHB30CXXN1+TXV | TM9E040A10MP12 | 15,000 | $750 |
| No | 211661256 | FRASER-JOHNSTON | HMH72B241 | XAUB30CXXN1+TXV | TM9E060A10MP12 | 15,000 | $750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661251 | FRASER-JOHNSTON | HMH72B241 | XAFB30CBAN1 | TM9E060A10MP12 | 15,000 | $750 |
| No | 211661246 | FRASER-JOHNSTON | HMH72B241 | XAFB30CXXN1+TXV | TM9E060A10MP12 | 15,000 | $750 |
| No | 211661241 | FRASER-JOHNSTON | HMH72B241 | XAHB30CBAN1 | TM9E060A10MP12 | 14,900 | $745 |
| No | 211661236 | FRASER-JOHNSTON | HMH72B241 | XAHB30CXXN1+TXV | TM9E060A10MP12 | 14,900 | $745 |
| No | 211661231 | FRASER-JOHNSTON | HMH72B241 | XAUB30CXXN1+TXV | TM9E060B12MP12 | 15,400 | $770 |
| No | 211661226 | FRASER-JOHNSTON | HMH72B241 | XAFB30CBAN1 | TM9E060B12MP12 | 15,400 | $770 |
| No | 211661221 | FRASER-JOHNSTON | HMH72B241 | XAFB30CXXN1+TXV | TM9E060B12MP12 | 15,400 | $770 |
| No | 211661216 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TM9E060B12MP12 | 15,400 | $770 |
| No | 211661211 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TM9E060B12MP12 | 15,400 | $770 |
| No | 211661206 | FRASER-JOHNSTON | HMH72B241 | XAHB30CBAN1 | TM9E060B12MP12 | 15,100 | $755 |
| No | 211661201 | FRASER-JOHNSTON | HMH72B241 | XAHB30CXXN1+TXV | TM9E060B12MP12 | 15,100 | $755 |
| No | 211661196 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TM9E060B12MP12 | 15,100 | $755 |
| No | 211661189 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TM9E060B12MP12 | 15,100 | $755 |
| No | 211661179 | FRASER-JOHNSTON | HMH72B241 | XAUB30CXXN1+TXV | TM9E080B12MP12 | 15,700 | $785 |
| No | 211661169 | FRASER-JOHNSTON | HMH72B241 | XAFB30CBAN1 | TM9E080B12MP12 | 15,700 | $785 |
| No | 211661161 | FRASER-JOHNSTON | HMH72B241 | XAFB30CXXN1+TXV | TM9E080B12MP12 | 15,700 | $785 |
| No | 211661156 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TM9E080B12MP12 | 15,700 | $785 |
| No | 211661151 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TM9E080B12MP12 | 15,700 | $785 |
| No | 211661146 | FRASER-JOHNSTON | HMH72B241 | XAHB30CBAN1 | TM9E080B12MP12 | 14,900 | $745 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661141 | FRASER-JOHNSTON | HMH72B241 | XAHB30CXXN1+TXV | TM9E080B12MP12 | 14,900 | $745 |
| No | 211661136 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TM9E080B12MP12 | 14,900 | $745 |
| No | 211661131 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TM9E080B12MP12 | 14,900 | $745 |
| No | 211661126 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TM9E080C16MP12 | 14,900 | $745 |
| No | 211661121 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TM9E080C16MP12 | 14,900 | $745 |
| No | 211661116 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TM9E080C16MP12 | 14,600 | $730 |
| No | 211661111 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TM9E080C16MP12 | 14,600 | $730 |
| No | 211661106 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TM9E100C16MP12 | 15,000 | $750 |
| No | 211661101 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TM9E100C16MP12 | 15,000 | $750 |
| No | 211661096 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TM9E100C16MP12 | 14,700 | $735 |
| No | 211661091 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TM9E100C16MP12 | 14,700 | $735 |
| No | 211661086 | FRASER-JOHNSTON | HMH72B241 | XAUB30CXXN1+TXV | TM9V040A10MP12 | 15,400 | $770 |
| No | 211661081 | FRASER-JOHNSTON | HMH72B241 | XAFB30CBAN1 | TM9V040A10MP12 | 15,400 | $770 |
| No | 211661076 | FRASER-JOHNSTON | HMH72B241 | XAFB30CXXN1+TXV | TM9V040A10MP12 | 15,400 | $770 |
| No | 211661071 | FRASER-JOHNSTON | HMH72B241 | XAHB30CBAN1 | TM9V040A10MP12 | 15,100 | $755 |
| No | 211661066 | FRASER-JOHNSTON | HMH72B241 | XAHB30CXXN1+TXV | TM9V040A10MP12 | 15,100 | $755 |
| No | 211661057 | FRASER-JOHNSTON | HMH72B241 | XAUB30CXXN1+TXV | TP9C060B12MP13 | 15,100 | $755 |
| No | 211661052 | FRASER-JOHNSTON | HMH72B241 | XAFB30CBAN1 | TP9C060B12MP13 | 15,100 | $755 |
| No | 211661047 | FRASER-JOHNSTON | HMH72B241 | XAUB30CXXN1+TXV | TM9V060B12MP12 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661042 | FRASER-JOHNSTON | HMH72B241 | XAFB30CBAN1 | TM9V060B12MP12 | 15,100 | $755 |
| No | 211661035 | FRASER-JOHNSTON | HMH72B241 | XAFB30CXXN1+TXV | TP9C060B12MP13 | 15,100 | $755 |
| No | 211661030 | FRASER-JOHNSTON | HMH72B241 | XAFB30CXXN1+TXV | TM9V060B12MP12 | 15,100 | $755 |
| No | 211661023 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TP9C060B12MP13 | 15,100 | $755 |
| No | 211661018 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TM9V060B12MP12 | 15,100 | $755 |
| No | 211661011 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TP9C060B12MP13 | 15,100 | $755 |
| No | 211661006 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TM9V060B12MP12 | 15,100 | $755 |
| No | 211660999 | FRASER-JOHNSTON | HMH72B241 | XAHB30CBAN1 | TP9C060B12MP13 | 15,100 | $755 |
| No | 211660994 | FRASER-JOHNSTON | HMH72B241 | XAHB30CBAN1 | TM9V060B12MP12 | 15,100 | $755 |
| No | 211660987 | FRASER-JOHNSTON | HMH72B241 | XAHB30CXXN1+TXV | TP9C060B12MP13 | 15,100 | $755 |
| No | 211660982 | FRASER-JOHNSTON | HMH72B241 | XAHB30CXXN1+TXV | TM9V060B12MP12 | 15,100 | $755 |
| No | 211660975 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TP9C060B12MP13 | 15,000 | $750 |
| No | 211660970 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TM9V060B12MP12 | 15,000 | $750 |
| No | 211660963 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TP9C060B12MP13 | 15,000 | $750 |
| No | 211660958 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TM9V060B12MP12 | 15,000 | $750 |
| No | 211660949 | FRASER-JOHNSTON | HMH72B241 | XAUB30CXXN1+TXV | TP9C080B12MP13 | 15,300 | $765 |
| No | 211660944 | FRASER-JOHNSTON | HMH72B241 | XAFB30CBAN1 | TP9C080B12MP13 | 15,300 | $765 |
| No | 211660939 | FRASER-JOHNSTON | HMH72B241 | XAUB30CXXN1+TXV | TM9V080B12MP12 | 15,300 | $765 |
| No | 211660934 | FRASER-JOHNSTON | HMH72B241 | XAFB30CBAN1 | TM9V080B12MP12 | 15,300 | $765 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660927 | FRASER-JOHNSTON | HMH72B241 | XAFB30CXXN1+TXV | TP9C080B12MP13 | 15,300 | $765 |
| No | 211660922 | FRASER-JOHNSTON | HMH72B241 | XAFB30CXXN1+TXV | TM9V080B12MP12 | 15,300 | $765 |
| No | 211660915 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TP9C080B12MP13 | 15,300 | $765 |
| No | 211660910 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TM9V080B12MP12 | 15,300 | $765 |
| No | 211660903 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TP9C080B12MP13 | 15,300 | $765 |
| No | 211660898 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TM9V080B12MP12 | 15,300 | $765 |
| No | 211660891 | FRASER-JOHNSTON | HMH72B241 | XAHB30CBAN1 | TP9C080B12MP13 | 14,800 | $740 |
| No | 211660886 | FRASER-JOHNSTON | HMH72B241 | XAHB30CBAN1 | TM9V080B12MP12 | 14,800 | $740 |
| No | 211660879 | FRASER-JOHNSTON | HMH72B241 | XAHB30CXXN1+TXV | TP9C080B12MP13 | 14,800 | $740 |
| No | 211660874 | FRASER-JOHNSTON | HMH72B241 | XAHB30CXXN1+TXV | TM9V080B12MP12 | 14,800 | $740 |
| No | 211660867 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TP9C080B12MP13 | 15,000 | $750 |
| No | 211660862 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TM9V080B12MP12 | 15,000 | $750 |
| No | 211660855 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 211660850 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 211660820 | FRASER-JOHNSTON | HMH72B241 | XAUB30CXXN1+TXV | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211660815 | FRASER-JOHNSTON | HMH72B241 | XAFB30CBAN1 | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211660810 | FRASER-JOHNSTON | HMH72B241 | XAFB30CXXN1+TXV | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211660805 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211660800 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TM9Y060B12MP11 | 15,400 | $770 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660795 | FRASER-JOHNSTON | HMH72B241 | XAHB30CBAN1 | TM9Y060B12MP11 | 15,100 | $755 |
| No | 211660790 | FRASER-JOHNSTON | HMH72B241 | XAHB30CXXN1+TXV | TM9Y060B12MP11 | 15,100 | $755 |
| No | 211660785 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TM9Y060B12MP11 | 14,800 | $740 |
| No | 211660780 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TM9Y060B12MP11 | 14,800 | $740 |
| No | 211660775 | FRASER-JOHNSTON | HMH72B241 | XAUB30CXXN1+TXV | TM9Y080B12MP11 | 15,100 | $755 |
| No | 211660770 | FRASER-JOHNSTON | HMH72B241 | XAFB30CBAN1 | TM9Y080B12MP11 | 15,100 | $755 |
| No | 211660765 | FRASER-JOHNSTON | HMH72B241 | XAFB30CXXN1+TXV | TM9Y080B12MP11 | 15,100 | $755 |
| No | 211660760 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TM9Y080B12MP11 | 15,100 | $755 |
| No | 211660755 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TM9Y080B12MP11 | 15,100 | $755 |
| No | 211660750 | FRASER-JOHNSTON | HMH72B241 | XAHB30CBAN1 | TM9Y080B12MP11 | 14,900 | $745 |
| No | 211660745 | FRASER-JOHNSTON | HMH72B241 | XAHB30CXXN1+TXV | TM9Y080B12MP11 | 14,900 | $745 |
| No | 211660740 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TM9Y080B12MP11 | 14,900 | $745 |
| No | 211660735 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TM9Y080B12MP11 | 14,900 | $745 |
| No | 211660730 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TM9Y080C16MP11 | 15,200 | $760 |
| No | 211660725 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TM9Y080C16MP11 | 15,200 | $760 |
| No | 211660720 | FRASER-JOHNSTON | HMH72B241 | JHETB24CBAS2N1 | | 15,000 | $750 |
| No | 211660715 | FRASER-JOHNSTON | HMH72B241 | JHVTB24CBAC2N1 | | 15,000 | $750 |
| No | 211660710 | FRASER-JOHNSTON | HMH72B241 | XAUB30CXXN1+JMET12BS2N1+TXV | | 15,100 | $755 |
| No | 211660705 | FRASER-JOHNSTON | HMH72B241 | XAFB30CBAN1+JMET12BS2N1 | | 15,100 | $755 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660700 | FRASER-JOHNSTON | HMH72B241 | XAFB30CXXN1+JMET12BS2N1+TXV | | 15,100 | $755 |
| No | 211660695 | FRASER-JOHNSTON | HMH72B241 | XAHB30CBAN1+JMET12BS2N1 | | 14,800 | $740 |
| No | 211660690 | FRASER-JOHNSTON | HMH72B241 | XAHB30CXXN1+JMET12BS2N1+TXV | | 14,800 | $740 |
| No | 211660685 | FRASER-JOHNSTON | HMH72B241 | XAUB30CXXN1+JMVT12BC2N1+TXV | | 14,900 | $745 |
| No | 211660680 | FRASER-JOHNSTON | HMH72B241 | XAFB30CBAN1+JMVT12BC2N1 | | 14,900 | $745 |
| No | 211660675 | FRASER-JOHNSTON | HMH72B241 | XAFB30CXXN1+JMVT12BC2N1+TXV | | 14,900 | $745 |
| No | 211660670 | FRASER-JOHNSTON | HMH72B241 | XAHB30CBAN1+JMVT12BC2N1 | | 14,900 | $745 |
| No | 211660665 | FRASER-JOHNSTON | HMH72B241 | XAHB30CXXN1+JMVT12BC2N1+TXV | | 14,900 | $745 |
| No | 211660660 | FRASER-JOHNSTON | HMH72B241 | XAUB30CXXN1+TXV | TL8E060A12UH11 | 15,000 | $750 |
| No | 211660655 | FRASER-JOHNSTON | HMH72B241 | XAFB30CBAN1 | TL8E060A12UH11 | 15,000 | $750 |
| No | 211660650 | FRASER-JOHNSTON | HMH72B241 | XAFB30CXXN1+TXV | TL8E060A12UH11 | 15,000 | $750 |
| No | 211660645 | FRASER-JOHNSTON | HMH72B241 | XAHB30CBAN1 | TL8E060A12UH11 | 14,700 | $735 |
| No | 211660640 | FRASER-JOHNSTON | HMH72B241 | XAHB30CXXN1+TXV | TL8E060A12UH11 | 14,700 | $735 |
| No | 211660635 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TL8E080C16UH11 | 15,600 | $780 |
| No | 211660630 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TL8E080C16UH11 | 15,600 | $780 |
| No | 211660625 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TM9Y080C16MP11 | 14,900 | $745 |
| No | 211660620 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TM9Y080C16MP11 | 14,900 | $745 |
| No | 211660615 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TM9Y100C16MP11 | 15,200 | $760 |
| No | 211660610 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TM9Y100C16MP11 | 15,200 | $760 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660605 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TM9Y100C16MP11 | 14,800 | $740 |
| No | 211660600 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TM9Y100C16MP11 | 14,800 | $740 |
| No | 211660595 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TL8E080C16UH11 | 15,300 | $765 |
| No | 211660590 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TL8E080C16UH11 | 15,300 | $765 |
| No | 211660585 | FRASER-JOHNSTON | HMH72B241 | XAUB30CXXN1+TXV | TL9E060B12UH11 | 15,100 | $755 |
| No | 211660580 | FRASER-JOHNSTON | HMH72B241 | XAFB30CBAN1 | TL9E060B12UH11 | 15,100 | $755 |
| No | 211660575 | FRASER-JOHNSTON | HMH72B241 | XAFB30CXXN1+TXV | TL9E060B12UH11 | 15,100 | $755 |
| No | 211660570 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TL9E060B12UH11 | 15,100 | $755 |
| No | 211660565 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TL9E060B12UH11 | 15,100 | $755 |
| No | 211660560 | FRASER-JOHNSTON | HMH72B241 | XAHB30CBAN1 | TL9E060B12UH11 | 14,800 | $740 |
| No | 211660555 | FRASER-JOHNSTON | HMH72B241 | XAHB30CXXN1+TXV | TL9E060B12UH11 | 14,800 | $740 |
| No | 211660550 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TL9E060B12UH11 | 14,800 | $740 |
| No | 211660545 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TL9E060B12UH11 | 14,800 | $740 |
| No | 211660540 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TL9E080C16UH11 | 15,700 | $785 |
| No | 211660535 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TL9E080C16UH11 | 15,700 | $785 |
| No | 211660530 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TL9E080C16UH11 | 15,300 | $765 |
| No | 211660525 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TL9E080C16UH11 | 15,300 | $765 |
| No | 211660520 | FRASER-JOHNSTON | HMH72B241 | XAUB30CXXN1+TXV | TMLE040A12MP11 | 15,000 | $750 |
| No | 211660515 | FRASER-JOHNSTON | HMH72B241 | XAFB30CBAN1 | TMLE040A12MP11 | 15,000 | $750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660510 | FRASER-JOHNSTON | HMH72B241 | XAUB30CXXN1+TXV | TM8E040A12MP11 | 15,000 | $750 |
| No | 211660505 | FRASER-JOHNSTON | HMH72B241 | XAFB30CBAN1 | TM8E040A12MP11 | 15,000 | $750 |
| No | 211660500 | FRASER-JOHNSTON | HMH72B241 | XAFB30CXXN1+TXV | TMLE040A12MP11 | 15,000 | $750 |
| No | 211660495 | FRASER-JOHNSTON | HMH72B241 | XAFB30CXXN1+TXV | TM8E040A12MP11 | 15,000 | $750 |
| No | 211660490 | FRASER-JOHNSTON | HMH72B241 | XAHB30CBAN1 | TMLE040A12MP11 | 14,700 | $735 |
| No | 211660485 | FRASER-JOHNSTON | HMH72B241 | XAHB30CBAN1 | TM8E040A12MP11 | 14,700 | $735 |
| No | 211660480 | FRASER-JOHNSTON | HMH72B241 | XAHB30CXXN1+TXV | TMLE040A12MP11 | 14,700 | $735 |
| No | 211660475 | FRASER-JOHNSTON | HMH72B241 | XAHB30CXXN1+TXV | TM8E040A12MP11 | 14,700 | $735 |
| No | 211660470 | FRASER-JOHNSTON | HMH72B241 | XAUB30CXXN1+TXV | TMLE060A12MP11 | 15,000 | $750 |
| No | 211660465 | FRASER-JOHNSTON | HMH72B241 | XAFB30CBAN1 | TMLE060A12MP11 | 15,000 | $750 |
| No | 211660460 | FRASER-JOHNSTON | HMH72B241 | XAUB30CXXN1+TXV | TM8E060A12MP11 | 15,000 | $750 |
| No | 211660455 | FRASER-JOHNSTON | HMH72B241 | XAFB30CBAN1 | TM8E060A12MP11 | 15,000 | $750 |
| No | 211660450 | FRASER-JOHNSTON | HMH72B241 | XAFB30CXXN1+TXV | TMLE060A12MP11 | 15,000 | $750 |
| No | 211660445 | FRASER-JOHNSTON | HMH72B241 | XAFB30CXXN1+TXV | TM8E060A12MP11 | 15,000 | $750 |
| No | 211660440 | FRASER-JOHNSTON | HMH72B241 | XAHB30CBAN1 | TMLE060A12MP11 | 14,700 | $735 |
| No | 211660435 | FRASER-JOHNSTON | HMH72B241 | XAHB30CBAN1 | TM8E060A12MP11 | 14,700 | $735 |
| No | 211660430 | FRASER-JOHNSTON | HMH72B241 | XAHB30CXXN1+TXV | TMLE060A12MP11 | 14,700 | $735 |
| No | 211660425 | FRASER-JOHNSTON | HMH72B241 | XAHB30CXXN1+TXV | TM8E060A12MP11 | 14,700 | $735 |
| No | 211660420 | FRASER-JOHNSTON | HMH72B241 | XAUB30CXXN1+TXV | TMLE080B12MP11 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660415 | FRASER-JOHNSTON | HMH72B241 | XAFB30CBAN1 | TMLE080B12MP11 | 15,100 | $755 |
| No | 211660410 | FRASER-JOHNSTON | HMH72B241 | XAUB30CXXN1+TXV | TM8E080B12MP11 | 15,100 | $755 |
| No | 211660405 | FRASER-JOHNSTON | HMH72B241 | XAFB30CBAN1 | TM8E080B12MP11 | 15,100 | $755 |
| No | 211660400 | FRASER-JOHNSTON | HMH72B241 | XAFB30CXXN1+TXV | TMLE080B12MP11 | 15,100 | $755 |
| No | 211660395 | FRASER-JOHNSTON | HMH72B241 | XAFB30CXXN1+TXV | TM8E080B12MP11 | 15,100 | $755 |
| No | 211660390 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TMLE080B12MP11 | 15,100 | $755 |
| No | 211660385 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TM8E080B12MP11 | 15,100 | $755 |
| No | 211660380 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TMLE080B12MP11 | 15,100 | $755 |
| No | 211660375 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TM8E080B12MP11 | 15,100 | $755 |
| No | 211660370 | FRASER-JOHNSTON | HMH72B241 | XAHB30CBAN1 | TMLE080B12MP11 | 14,800 | $740 |
| No | 211660365 | FRASER-JOHNSTON | HMH72B241 | XAHB30CBAN1 | TM8E080B12MP11 | 14,800 | $740 |
| No | 211660360 | FRASER-JOHNSTON | HMH72B241 | XAHB30CXXN1+TXV | TMLE080B12MP11 | 14,800 | $740 |
| No | 211660355 | FRASER-JOHNSTON | HMH72B241 | XAHB30CXXN1+TXV | TM8E080B12MP11 | 14,800 | $740 |
| No | 211660350 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TMLE080B12MP11 | 14,800 | $740 |
| No | 211660345 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TM8E080B12MP11 | 14,800 | $740 |
| No | 211660340 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TMLE080B12MP11 | 14,800 | $740 |
| No | 211660335 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TM8E080B12MP11 | 14,800 | $740 |
| No | 211660330 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TMLE080C16MP11 | 15,500 | $775 |
| No | 211660325 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TM8E080C16MP11 | 15,500 | $775 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660320 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TMLE080C16MP11 | 15,500 | $775 |
| No | 211660315 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TM8E080C16MP11 | 15,500 | $775 |
| No | 211660310 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TMLE080C16MP11 | 14,700 | $735 |
| No | 211660305 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TM8E080C16MP11 | 14,700 | $735 |
| No | 211660300 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TMLE080C16MP11 | 14,700 | $735 |
| No | 211660295 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TM8E080C16MP11 | 14,700 | $735 |
| No | 211660290 | FRASER-JOHNSTON | HMH72B241 | XAUB30CXXN1+TXV | TMLE100B12MP11 | 15,100 | $755 |
| No | 211660285 | FRASER-JOHNSTON | HMH72B241 | XAFB30CBAN1 | TMLE100B12MP11 | 15,100 | $755 |
| No | 211660280 | FRASER-JOHNSTON | HMH72B241 | XAUB30CXXN1+TXV | TM8E100B12MP11 | 15,100 | $755 |
| No | 211660275 | FRASER-JOHNSTON | HMH72B241 | XAFB30CBAN1 | TM8E100B12MP11 | 15,100 | $755 |
| No | 211660270 | FRASER-JOHNSTON | HMH72B241 | XAFB30CXXN1+TXV | TMLE100B12MP11 | 15,100 | $755 |
| No | 211660265 | FRASER-JOHNSTON | HMH72B241 | XAFB30CXXN1+TXV | TM8E100B12MP11 | 15,100 | $755 |
| No | 211660260 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TMLE100B12MP11 | 14,800 | $740 |
| No | 211660255 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660250 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TMLE100B12MP11 | 14,800 | $740 |
| No | 211660245 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660240 | FRASER-JOHNSTON | HMH72B241 | XAHB30CBAN1 | TMLE100B12MP11 | 14,800 | $740 |
| No | 211660235 | FRASER-JOHNSTON | HMH72B241 | XAHB30CBAN1 | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660230 | FRASER-JOHNSTON | HMH72B241 | XAHB30CXXN1+TXV | TMLE100B12MP11 | 14,800 | $740 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660225 | FRASER-JOHNSTON | HMH72B241 | XAHB30CXXN1+TXV | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660220 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TMLE100B12MP11 | 14,800 | $740 |
| No | 211660215 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660210 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TMLE100B12MP11 | 14,800 | $740 |
| No | 211660205 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660200 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TMLE100C16MP11 | 15,000 | $750 |
| No | 211660195 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TM8E100C16MP11 | 15,000 | $750 |
| No | 211660190 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TMLE100C16MP11 | 15,000 | $750 |
| No | 211660185 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TM8E100C16MP11 | 15,000 | $750 |
| No | 211660180 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TMLE100C16MP11 | 14,700 | $735 |
| No | 211660175 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TM8E100C16MP11 | 14,700 | $735 |
| No | 211660170 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TMLE100C16MP11 | 14,700 | $735 |
| No | 211660165 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TM8E100C16MP11 | 14,700 | $735 |
| No | 211660160 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TMLE120C16MP11 | 15,000 | $750 |
| No | 211660155 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TM8E120C16MP11 | 15,000 | $750 |
| No | 211660150 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TMLE120C16MP11 | 15,000 | $750 |
| No | 211660145 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TM8E120C16MP11 | 15,000 | $750 |
| No | 211660140 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TMLE120C16MP11 | 15,300 | $765 |
| No | 211660135 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TM8E120C16MP11 | 15,300 | $765 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660130 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TMLE120C16MP11 | 15,300 | $765 |
| No | 211660125 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TM8E120C16MP11 | 15,300 | $765 |
| No | 211660118 | FRASER-JOHNSTON | HMH72B241 | XAUB30CXXN1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 211660113 | FRASER-JOHNSTON | HMH72B241 | XAFB30CBAN1 | TPLC080B12MP13 | 15,100 | $755 |
| No | 211660108 | FRASER-JOHNSTON | HMH72B241 | XAUB30CXXN1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 211660103 | FRASER-JOHNSTON | HMH72B241 | XAFB30CBAN1 | TM8V080B12MP12 | 15,100 | $755 |
| No | 211660097 | FRASER-JOHNSTON | HMH72B241 | XAFB30CXXN1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 211660092 | FRASER-JOHNSTON | HMH72B241 | XAFB30CXXN1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 211660086 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TPLC080B12MP13 | 15,100 | $755 |
| No | 211660081 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TM8V080B12MP12 | 15,100 | $755 |
| No | 211660075 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 211660070 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 211660064 | FRASER-JOHNSTON | HMH72B241 | XAHB30CBAN1 | TPLC080B12MP13 | 14,900 | $745 |
| No | 211660059 | FRASER-JOHNSTON | HMH72B241 | XAHB30CBAN1 | TM8V080B12MP12 | 14,900 | $745 |
| No | 211660053 | FRASER-JOHNSTON | HMH72B241 | XAHB30CXXN1+TXV | TPLC080B12MP13 | 14,900 | $745 |
| No | 211660048 | FRASER-JOHNSTON | HMH72B241 | XAHB30CXXN1+TXV | TM8V080B12MP12 | 14,900 | $745 |
| No | 211660042 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TPLC080B12MP13 | 14,800 | $740 |
| No | 211660037 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TM8V080B12MP12 | 14,800 | $740 |
| No | 211660031 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TPLC080B12MP13 | 14,800 | $740 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660026 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TM8V080B12MP12 | 14,800 | $740 |
| No | 211660021 | FRASER-JOHNSTON | HMH72B241 | XAUB30CXXN1+TXV | TM8Y060A12MP11 | 15,300 | $765 |
| No | 211660016 | FRASER-JOHNSTON | HMH72B241 | XAFB30CBAN1 | TM8Y060A12MP11 | 15,300 | $765 |
| No | 211660011 | FRASER-JOHNSTON | HMH72B241 | XAFB30CXXN1+TXV | TM8Y060A12MP11 | 15,300 | $765 |
| No | 211660006 | FRASER-JOHNSTON | HMH72B241 | XAHB30CBAN1 | TM8Y060A12MP11 | 15,000 | $750 |
| No | 211660001 | FRASER-JOHNSTON | HMH72B241 | XAHB30CXXN1+TXV | TM8Y060A12MP11 | 15,000 | $750 |
| No | 211659996 | FRASER-JOHNSTON | HMH72B241 | XAUB30CXXN1+TXV | TM8Y080B12MP11 | 15,300 | $765 |
| No | 211659991 | FRASER-JOHNSTON | HMH72B241 | XAFB30CBAN1 | TM8Y080B12MP11 | 15,300 | $765 |
| No | 211659986 | FRASER-JOHNSTON | HMH72B241 | XAFB30CXXN1+TXV | TM8Y080B12MP11 | 15,300 | $765 |
| No | 211659981 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TM8Y080B12MP11 | 15,300 | $765 |
| No | 211659976 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TM8Y080B12MP11 | 15,300 | $765 |
| No | 211659971 | FRASER-JOHNSTON | HMH72B241 | XAHB30CBAN1 | TM8Y080B12MP11 | 15,000 | $750 |
| No | 211659966 | FRASER-JOHNSTON | HMH72B241 | XAHB30CXXN1+TXV | TM8Y080B12MP11 | 15,000 | $750 |
| No | 211659961 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TM8Y080B12MP11 | 15,100 | $755 |
| No | 211659956 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TM8Y080B12MP11 | 15,100 | $755 |
| No | 211659946 | FRASER-JOHNSTON | HMH72B241 | XAFC30CBAN1 | TM8Y100C16MP11 | 15,100 | $755 |
| No | 211659936 | FRASER-JOHNSTON | HMH72B241 | XAFC30CXXN1+TXV | TM8Y100C16MP11 | 15,100 | $755 |
| No | 211659931 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TM8Y080C16MP11 | 14,800 | $740 |
| No | 211659926 | FRASER-JOHNSTON | HMH72B241 | XAHC30CBAN1 | TM8Y100C16MP11 | 14,800 | $740 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211659921 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TM8Y080C16MP11 | 14,800 | $740 |
| No | 211659916 | FRASER-JOHNSTON | HMH72B241 | XAHC30CXXN1+TXV | TM8Y100C16MP11 | 14,800 | $740 |
| No | 211659911 | FRASER-JOHNSTON | HMH72B241 | XAUB30CXXN1+TXV | TM9E026A08MP12 | 15,400 | $770 |
| No | 211659906 | FRASER-JOHNSTON | HMH72B241 | XAFB30CBAN1 | TM9E026A08MP12 | 15,400 | $770 |
| No | 211659901 | FRASER-JOHNSTON | HMH72B241 | XAFB30CXXN1+TXV | TM9E026A08MP12 | 15,400 | $770 |
| No | 211659896 | FRASER-JOHNSTON | HMH72B241 | XAHB30CBAN1 | TM9E026A08MP12 | 15,100 | $755 |
| No | 211659891 | FRASER-JOHNSTON | HMH72B241 | XAHB30CXXN1+TXV | TM9E026A08MP12 | 15,100 | $755 |
| No | 207417131 | FRASER-JOHNSTON | HMH72B361 | XAFA30DXXN1+TXV | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 207417127 | FRASER-JOHNSTON | HMH72B361 | XAFA30DXXN1+TXV | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 207417034 | FRASER-JOHNSTON | HMH72B361 | XAFA30DXXN1+TXV | TM8Y060A12MP11 | 25,000 | $1,250 |
| No | 207416616 | FRASER-JOHNSTON | HMH72B361 | XAFA30DXXN1+TXV | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 207416592 | FRASER-JOHNSTON | HMH72B361 | XAFA30DXXN1+TXV | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 207416588 | FRASER-JOHNSTON | HMH72B361 | XAFA30DXXN1+TXV | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211398893 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211398879 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211398866 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211398853 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211398838 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TMLE080C16MP11 | 24,800 | $1,240 |
| No | 211398823 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TM8E080C16MP11 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211398808 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TMLE080C16MP11 | 24,800 | $1,240 |
| No | 211398797 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TM8E080C16MP11 | 24,800 | $1,240 |
| No | 211398787 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TMLE080C16MP11 | 24,800 | $1,240 |
| No | 211398773 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TM8E080C16MP11 | 24,800 | $1,240 |
| No | 211398760 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TMLE080C16MP11 | 24,800 | $1,240 |
| No | 211398745 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TM8E080C16MP11 | 24,800 | $1,240 |
| No | 211398731 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211398716 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211398701 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211398686 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211398671 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211398656 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211398641 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 211398633 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 211398619 | FRASER-JOHNSTON | HMH72B341 | 0 | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 211398604 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 211398589 | FRASER-JOHNSTON | HMH72B341 | 0 | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211398575 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211398559 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TM8E100C16MP11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211398544 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211398529 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211398514 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211398499 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211398485 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211398476 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211398466 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211398451 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211398436 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211398421 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211398406 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211398392 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211398377 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211398362 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211398350 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211398335 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TMLE120C16MP11 | 25,400 | $1,270 |
| No | 211398325 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TMLE120C16MP11 | 25,400 | $1,270 |
| No | 211398312 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TM8E120C16MP11 | 25,400 | $1,270 |
| No | 211398297 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TM8E120C16MP11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211398285 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TMLE120C16MP11 | 25,400 | $1,270 |
| No | 211398270 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TM8E120C16MP11 | 25,400 | $1,270 |
| No | 211398255 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TMLE120C16MP11 | 25,200 | $1,260 |
| No | 211398240 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TM8E120C16MP11 | 25,200 | $1,260 |
| No | 211398225 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TMLE120C16MP11 | 25,200 | $1,260 |
| No | 211398210 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TM8E120C16MP11 | 25,200 | $1,260 |
| No | 211398194 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211398179 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211398164 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211398156 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211398141 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211398126 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211398111 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211398096 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211398085 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TPLC080B12MP13 | 25,800 | $1,290 |
| No | 211398071 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TPLC080B12MP13 | 25,800 | $1,290 |
| No | 211398056 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TM8V080B12MP12 | 25,800 | $1,290 |
| No | 211398041 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TM8V080B12MP12 | 25,800 | $1,290 |
| No | 211398023 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TPLC080B12MP13 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211398008 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TM8V080B12MP12 | 25,800 | $1,290 |
| No | 211397990 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TPLC080B12MP13 | 25,200 | $1,260 |
| No | 211397975 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TM8V080B12MP12 | 25,200 | $1,260 |
| No | 211397957 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TPLC080B12MP13 | 25,200 | $1,260 |
| No | 211397942 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TM8V080B12MP12 | 25,200 | $1,260 |
| No | 211397903 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397888 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397876 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397862 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397847 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211397832 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211397795 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211397780 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211397753 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397738 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397723 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211397699 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211397672 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397657 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TPLC080C16MP13 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211397642 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211397612 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211397585 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397570 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397555 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211397525 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211397498 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TPLC100C16MP13 | 25,400 | $1,270 |
| No | 211397483 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TPLC080C16MP13 | 25,400 | $1,270 |
| No | 211397470 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TMLV100C16MP12 | 25,400 | $1,270 |
| No | 211397445 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TM8V100C16MP12 | 25,400 | $1,270 |
| No | 211397424 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TPLC100C16MP13 | 25,400 | $1,270 |
| No | 211397409 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TPLC080C16MP13 | 25,400 | $1,270 |
| No | 211397394 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TMLV100C16MP12 | 25,400 | $1,270 |
| No | 211397371 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TM8V100C16MP12 | 25,400 | $1,270 |
| No | 211397344 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TPLC100C16MP13 | 25,200 | $1,260 |
| No | 211397328 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TPLC080C16MP13 | 25,200 | $1,260 |
| No | 211397314 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TMLV100C16MP12 | 25,200 | $1,260 |
| No | 211397302 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TM8V080C16MP12 | 25,200 | $1,260 |
| No | 211397287 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TM8V100C16MP12 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211397264 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TPLC100C16MP13 | 25,200 | $1,260 |
| No | 211397249 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TPLC080C16MP13 | 25,200 | $1,260 |
| No | 211397234 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TMLV100C16MP12 | 25,200 | $1,260 |
| No | 211397219 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TM8V080C16MP12 | 25,200 | $1,260 |
| No | 211397203 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TM8V100C16MP12 | 25,200 | $1,260 |
| No | 211397179 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TPLC120C20MP13 | 25,200 | $1,260 |
| No | 211397167 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TPLC100C20MP13 | 25,200 | $1,260 |
| No | 211397158 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TMLV120C20MP12 | 25,200 | $1,260 |
| No | 211397143 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TM8V100C20MP12 | 25,200 | $1,260 |
| No | 211397130 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TM8V120C20MP12 | 25,200 | $1,260 |
| No | 211397107 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TPLC120C20MP13 | 25,200 | $1,260 |
| No | 211397092 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TPLC100C20MP13 | 25,200 | $1,260 |
| No | 211397077 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TMLV120C20MP12 | 25,200 | $1,260 |
| No | 211397062 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TM8V100C20MP12 | 25,200 | $1,260 |
| No | 211397047 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TM8V120C20MP12 | 25,200 | $1,260 |
| No | 211397032 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211397017 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211397002 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211396987 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TM8Y080B12MP11 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211396978 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211396963 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TM8Y080C16MP11 | 25,800 | $1,290 |
| No | 211396948 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TM8Y080C16MP11 | 25,800 | $1,290 |
| No | 211396933 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211396921 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211396909 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TM8Y080C16MP11 | 25,800 | $1,290 |
| No | 211396894 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211396879 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TM8Y080C16MP11 | 25,800 | $1,290 |
| No | 211396864 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211396849 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TM8Y080C16MP11 | 25,800 | $1,290 |
| No | 211396834 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211396819 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TM8Y080C16MP11 | 25,400 | $1,270 |
| No | 211396804 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211396796 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TM8Y080C16MP11 | 25,400 | $1,270 |
| No | 211396781 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211396766 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TM8Y080C16MP11 | 25,400 | $1,270 |
| No | 211396751 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211396736 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TM8Y080C16MP11 | 25,400 | $1,270 |
| No | 211396721 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TM8Y100C16MP11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211396707 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TM8Y100C20MP11 | 25,600 | $1,280 |
| No | 211396691 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TM8Y100C20MP11 | 25,600 | $1,280 |
| No | 211396680 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TM8Y120C20MP11 | 25,600 | $1,280 |
| No | 211396665 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TM8Y120C20MP11 | 25,600 | $1,280 |
| No | 211396650 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TM8Y100C20MP11 | 25,600 | $1,280 |
| No | 211396634 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TM8Y120C20MP11 | 25,600 | $1,280 |
| No | 211396624 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TM8Y100C20MP11 | 25,600 | $1,280 |
| No | 211396610 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TM8Y120C20MP11 | 25,600 | $1,280 |
| No | 211396597 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TM8Y100C20MP11 | 25,600 | $1,280 |
| No | 211396584 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TM8Y120C20MP11 | 25,600 | $1,280 |
| No | 211396568 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TM8Y100C20MP11 | 25,200 | $1,260 |
| No | 211396554 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211396537 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TM8Y100C20MP11 | 25,200 | $1,260 |
| No | 211396519 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211396496 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TM8Y100C20MP11 | 25,200 | $1,260 |
| No | 211396473 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211396449 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TM8Y100C20MP11 | 25,200 | $1,260 |
| No | 211396428 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211396405 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211396380 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211396357 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211396338 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211396312 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211396292 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TM9E080B12MP12 | 25,600 | $1,280 |
| No | 211396270 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TM9E080B12MP12 | 25,600 | $1,280 |
| No | 211396248 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TM9E080B12MP12 | 25,600 | $1,280 |
| No | 211396225 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211396205 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211396185 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TM9E080C16MP12 | 26,000 | $1,300 |
| No | 211396167 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TM9E080C16MP12 | 26,000 | $1,300 |
| No | 211396148 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TM9E080C16MP12 | 26,000 | $1,300 |
| No | 211396132 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TM9E080C16MP12 | 26,000 | $1,300 |
| No | 211396116 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TM9E080C16MP12 | 26,000 | $1,300 |
| No | 211396102 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211396086 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211396071 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211396056 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211396041 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TM9E100C16MP12 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211396029 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211396015 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211395999 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211395984 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211395970 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211395957 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211395943 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211395930 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211395905 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211395895 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211395882 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211395864 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211395834 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211395810 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211395788 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TP9C060B12MP13 | 25,200 | $1,260 |
| No | 211395768 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TM9V060B12MP12 | 25,200 | $1,260 |
| No | 211395738 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TP9C060B12MP13 | 25,200 | $1,260 |
| No | 211395719 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TM9V060B12MP12 | 25,200 | $1,260 |
| No | 211395681 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TP9C080B12MP13 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211395656 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TP9C080B12MP13 | 25,600 | $1,280 |
| No | 211395634 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TM9V080B12MP12 | 25,600 | $1,280 |
| No | 211395612 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TM9V080B12MP12 | 25,600 | $1,280 |
| No | 211395581 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TP9C080B12MP13 | 25,600 | $1,280 |
| No | 211395559 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TM9V080B12MP12 | 25,600 | $1,280 |
| No | 211395525 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TP9C080B12MP13 | 25,200 | $1,260 |
| No | 211395501 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TM9V080B12MP12 | 25,200 | $1,260 |
| No | 211395476 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TP9C080B12MP13 | 25,200 | $1,260 |
| No | 211395456 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TM9V080B12MP12 | 25,200 | $1,260 |
| No | 211395409 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395390 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395368 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211395350 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211395321 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395295 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211395259 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395238 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211395206 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395180 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TM9V080C16MP12 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211395146 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TP9C080C16MP13 | 24,800 | $1,240 |
| No | 211395124 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TM9V080C16MP12 | 24,800 | $1,240 |
| No | 211395090 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TP9C080C16MP13 | 24,800 | $1,240 |
| No | 211395074 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TM9V080C16MP12 | 24,800 | $1,240 |
| No | 211395046 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TP9C080C16MP13 | 25,000 | $1,250 |
| No | 211395034 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TM9V080C16MP12 | 25,000 | $1,250 |
| No | 211395016 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TP9C080C16MP13 | 25,000 | $1,250 |
| No | 211395002 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TM9V080C16MP12 | 25,000 | $1,250 |
| No | 211394976 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394961 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394946 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211394934 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211394915 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394900 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211394881 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394868 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211394847 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394833 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211394812 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TP9C100C16MP13 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211394797 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TM9V100C16MP12 | 24,800 | $1,240 |
| No | 211394776 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211394762 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TM9V100C16MP12 | 24,800 | $1,240 |
| No | 211394741 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211394727 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TM9V100C16MP12 | 24,800 | $1,240 |
| No | 211394709 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211394695 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TM9V100C16MP12 | 24,800 | $1,240 |
| No | 211394668 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TP9C100C20MP13 | 25,800 | $1,290 |
| No | 211394654 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TP9C100C20MP13 | 25,800 | $1,290 |
| No | 211394641 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TM9V100C20MP12 | 25,800 | $1,290 |
| No | 211394628 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TM9V100C20MP12 | 25,800 | $1,290 |
| No | 211394609 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TP9C100C20MP13 | 25,800 | $1,290 |
| No | 211394594 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TM9V100C20MP12 | 25,800 | $1,290 |
| No | 211394573 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TP9C100C20MP13 | 25,600 | $1,280 |
| No | 211394558 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TM9V100C20MP12 | 25,600 | $1,280 |
| No | 211394540 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TP9C100C20MP13 | 25,600 | $1,280 |
| No | 211394528 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TM9V100C20MP12 | 25,600 | $1,280 |
| No | 211394509 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TP9C100C20MP13 | 25,000 | $1,250 |
| No | 211394498 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TM9V100C20MP12 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211394477 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TP9C100C20MP13 | 25,000 | $1,250 |
| No | 211394464 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TM9V100C20MP12 | 25,000 | $1,250 |
| No | 211394443 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TP9C100C20MP13 | 25,200 | $1,260 |
| No | 211394428 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TM9V100C20MP12 | 25,200 | $1,260 |
| No | 211394410 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TP9C100C20MP13 | 25,200 | $1,260 |
| No | 211394398 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TM9V100C20MP12 | 25,200 | $1,260 |
| No | 211394376 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TP9C120D20MP13 | 25,400 | $1,270 |
| No | 211394363 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TM9V120D20MP12 | 25,400 | $1,270 |
| No | 211394345 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TP9C120D20MP13 | 25,400 | $1,270 |
| No | 211394331 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TM9V120D20MP12 | 25,400 | $1,270 |
| No | 211394312 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TP9C120D20MP13 | 24,800 | $1,240 |
| No | 211394299 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TM9V120D20MP12 | 24,800 | $1,240 |
| No | 211394279 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TP9C120D20MP13 | 24,800 | $1,240 |
| No | 211394264 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TM9V120D20MP12 | 24,800 | $1,240 |
| No | 211394249 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TM9Y060B12MP11 | 25,800 | $1,290 |
| No | 211394235 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TM9Y060B12MP11 | 25,800 | $1,290 |
| No | 211394222 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TM9Y060B12MP11 | 25,800 | $1,290 |
| No | 211394209 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TM9Y060B12MP11 | 25,400 | $1,270 |
| No | 211394194 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TM9Y060B12MP11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211394179 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211394164 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211394153 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211394138 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TM9Y080B12MP11 | 25,400 | $1,270 |
| No | 211394123 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TM9Y080B12MP11 | 25,400 | $1,270 |
| No | 211394110 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TM9Y080C16MP11 | 25,800 | $1,290 |
| No | 211394097 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TM9Y080C16MP11 | 25,800 | $1,290 |
| No | 211394082 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TM9Y080C16MP11 | 25,800 | $1,290 |
| No | 211394067 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TM9Y080C16MP11 | 25,400 | $1,270 |
| No | 211394052 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TM9Y080C16MP11 | 25,400 | $1,270 |
| No | 211394037 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TM9Y080C16MP11 | 25,200 | $1,260 |
| No | 211394022 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TM9Y080C16MP11 | 25,200 | $1,260 |
| No | 211394007 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TM9Y080C16MP11 | 25,000 | $1,250 |
| No | 211393992 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TM9Y080C16MP11 | 25,000 | $1,250 |
| No | 211393977 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TM9Y100C16MP11 | 25,800 | $1,290 |
| No | 211393962 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TM9Y100C16MP11 | 25,800 | $1,290 |
| No | 211393947 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TM9Y100C16MP11 | 25,800 | $1,290 |
| No | 211393932 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TM9Y100C16MP11 | 25,400 | $1,270 |
| No | 211393917 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TM9Y100C16MP11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211393902 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TM9Y100C16MP11 | 25,200 | $1,260 |
| No | 211393887 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TM9Y100C16MP11 | 25,200 | $1,260 |
| No | 211393872 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TM9Y100C16MP11 | 25,200 | $1,260 |
| No | 211393857 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TM9Y100C16MP11 | 25,200 | $1,260 |
| No | 211393842 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TM9Y120D20MP11 | 25,400 | $1,270 |
| No | 211393827 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TM9Y120D20MP11 | 25,400 | $1,270 |
| No | 211393812 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TM9Y120D20MP11 | 25,000 | $1,250 |
| No | 211393797 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TM9Y120D20MP11 | 25,000 | $1,250 |
| No | 211393782 | FRASER-JOHNSTON | HMH72B341 | XAFA30DXXN1+TXV | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 211393767 | FRASER-JOHNSTON | HMH72B341 | XAFA30DXXN1+TXV | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 211393753 | FRASER-JOHNSTON | HMH72B341 | XAFA30DXXN1+TXV | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211393738 | FRASER-JOHNSTON | HMH72B341 | XAFA30DXXN1+TXV | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 211393723 | FRASER-JOHNSTON | HMH72B341 | XAFA30DXXN1+TXV | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 211393708 | FRASER-JOHNSTON | HMH72B341 | XAFA30DXXN1+TXV | TPLC060A12MP13 | 25,800 | $1,290 |
| No | 211393693 | FRASER-JOHNSTON | HMH72B341 | XAFA30DXXN1+TXV | TMLV060A12MP12 | 25,800 | $1,290 |
| No | 211393678 | FRASER-JOHNSTON | HMH72B341 | XAFA30DXXN1+TXV | TM8V060A12MP12 | 25,800 | $1,290 |
| No | 211393663 | FRASER-JOHNSTON | HMH72B341 | XAFA30DXXN1+TXV | TM8Y060A12MP11 | 25,200 | $1,260 |
| No | 211393635 | FRASER-JOHNSTON | HMH72B341 | JHETB36DBCS2N1 | | 25,400 | $1,270 |
| No | 211393621 | FRASER-JOHNSTON | HMH72B341 | JHVTB36DBCC2N1 | | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211393608 | FRASER-JOHNSTON | HMH72B341 | JHVTC36DBCC2N1 | | 25,400 | $1,270 |
| No | 211393594 | FRASER-JOHNSTON | HMH72B341 | XAUB30CXXN1+TXV | TL8E060A12UH11 | 26,200 | $1,310 |
| No | 211393580 | FRASER-JOHNSTON | HMH72B341 | XAFB30CXXN1+TXV | TL8E060A12UH11 | 26,200 | $1,310 |
| No | 211393565 | FRASER-JOHNSTON | HMH72B341 | XAUB36DXXN1+TXV | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 211393550 | FRASER-JOHNSTON | HMH72B341 | XAFB36DBCN1 | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 211393535 | FRASER-JOHNSTON | HMH72B341 | XAFB36DXXN1+TXV | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 211393521 | FRASER-JOHNSTON | HMH72B341 | XAHB30CXXN1+TXV | TL8E060A12UH11 | 25,800 | $1,290 |
| No | 211393506 | FRASER-JOHNSTON | HMH72B341 | XAHB36DBCN1 | TL8E060A12UH11 | 25,000 | $1,250 |
| No | 211393491 | FRASER-JOHNSTON | HMH72B341 | XAHB36DXXN1+TXV | TL8E060A12UH11 | 25,000 | $1,250 |
| No | 211393476 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TL8E080C16UH11 | 26,600 | $1,330 |
| No | 211393461 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211393446 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211393432 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TL8E080C16UH11 | 26,000 | $1,300 |
| No | 211393416 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TL8E080C16UH11 | 25,800 | $1,290 |
| No | 211393402 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TL8E080C16UH11 | 25,800 | $1,290 |
| No | 211393387 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TL8E100C20UH11 | 26,400 | $1,320 |
| No | 211393372 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211393358 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211393347 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TL8E100C20UH11 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211393325 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TL8E100C20UH11 | 25,600 | $1,280 |
| No | 211393310 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TL8E100C20UH11 | 25,600 | $1,280 |
| No | 211393296 | FRASER-JOHNSTON | HMH72B341 | XAUB30CXXN1+TXV | TL9E060B12UH11 | 26,400 | $1,320 |
| No | 211393281 | FRASER-JOHNSTON | HMH72B341 | XAFB30CXXN1+TXV | TL9E060B12UH11 | 26,400 | $1,320 |
| No | 211393266 | FRASER-JOHNSTON | HMH72B341 | XAUB36DXXN1+TXV | TL9E060B12UH11 | 25,000 | $1,250 |
| No | 211393251 | FRASER-JOHNSTON | HMH72B341 | XAFB36DBCN1 | TL9E060B12UH11 | 25,000 | $1,250 |
| No | 211393243 | FRASER-JOHNSTON | HMH72B341 | XAFB36DXXN1+TXV | TL9E060B12UH11 | 25,000 | $1,250 |
| No | 211393228 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TL9E060B12UH11 | 26,400 | $1,320 |
| No | 211393213 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TL9E060B12UH11 | 25,600 | $1,280 |
| No | 211393198 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TL9E060B12UH11 | 25,600 | $1,280 |
| No | 211393183 | FRASER-JOHNSTON | HMH72B341 | XAHB30CXXN1+TXV | TL9E060B12UH11 | 25,200 | $1,260 |
| No | 211393172 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TL9E060B12UH11 | 26,000 | $1,300 |
| No | 211393157 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TL9E060B12UH11 | 24,400 | $1,220 |
| No | 211393142 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TL9E060B12UH11 | 24,400 | $1,220 |
| No | 211393127 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TL9E080C16UH11 | 26,200 | $1,310 |
| No | 211393112 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TL9E080C16UH11 | 25,800 | $1,290 |
| No | 211393097 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TL9E080C16UH11 | 25,800 | $1,290 |
| No | 211393082 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TL9E080C16UH11 | 26,400 | $1,320 |
| No | 211393073 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TL9E080C16UH11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211393064 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TL9E080C16UH11 | 25,400 | $1,270 |
| No | 211393048 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TL9E100C20UH11 | 26,400 | $1,320 |
| No | 211393034 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TL9E100C20UH11 | 26,200 | $1,310 |
| No | 211393018 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TL9E100C20UH11 | 26,200 | $1,310 |
| No | 211393003 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TL9E100C20UH11 | 26,000 | $1,300 |
| No | 211392988 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TL9E100C20UH11 | 25,600 | $1,280 |
| No | 211392973 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TL9E100C20UH11 | 25,600 | $1,280 |
| No | 211392959 | FRASER-JOHNSTON | HMH72B341 | XAUB30CXXN1+TXV | TMLE040A12MP11 | 26,200 | $1,310 |
| No | 211392944 | FRASER-JOHNSTON | HMH72B341 | XAUB30CXXN1+TXV | TM8E040A12MP11 | 26,200 | $1,310 |
| No | 211392929 | FRASER-JOHNSTON | HMH72B341 | XAFB30CXXN1+TXV | TMLE040A12MP11 | 26,200 | $1,310 |
| No | 211392914 | FRASER-JOHNSTON | HMH72B341 | XAFB30CXXN1+TXV | TM8E040A12MP11 | 26,200 | $1,310 |
| No | 211392899 | FRASER-JOHNSTON | HMH72B341 | XAUB36DXXN1+TXV | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 211392886 | FRASER-JOHNSTON | HMH72B341 | XAFB36DBCN1 | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 211392878 | FRASER-JOHNSTON | HMH72B341 | XAUB36DXXN1+TXV | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211392863 | FRASER-JOHNSTON | HMH72B341 | XAFB36DBCN1 | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211392848 | FRASER-JOHNSTON | HMH72B341 | XAFB36DXXN1+TXV | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 211392833 | FRASER-JOHNSTON | HMH72B341 | XAFB36DXXN1+TXV | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211392818 | FRASER-JOHNSTON | HMH72B341 | XAHB30CXXN1+TXV | TMLE040A12MP11 | 25,600 | $1,280 |
| No | 211392803 | FRASER-JOHNSTON | HMH72B341 | XAHB30CXXN1+TXV | TM8E040A12MP11 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211392788 | FRASER-JOHNSTON | HMH72B341 | XAHB36DBCN1 | TMLE040A12MP11 | 24,800 | $1,240 |
| No | 211392773 | FRASER-JOHNSTON | HMH72B341 | XAHB36DBCN1 | TM8E040A12MP11 | 24,800 | $1,240 |
| No | 211392758 | FRASER-JOHNSTON | HMH72B341 | XAHB36DXXN1+TXV | TMLE040A12MP11 | 24,800 | $1,240 |
| No | 211392743 | FRASER-JOHNSTON | HMH72B341 | XAHB36DXXN1+TXV | TM8E040A12MP11 | 24,800 | $1,240 |
| No | 211392728 | FRASER-JOHNSTON | HMH72B341 | XAUB30CXXN1+TXV | TMLE060A12MP11 | 26,200 | $1,310 |
| No | 211392713 | FRASER-JOHNSTON | HMH72B341 | XAUB30CXXN1+TXV | TM8E060A12MP11 | 26,200 | $1,310 |
| No | 211392699 | FRASER-JOHNSTON | HMH72B341 | XAFB30CXXN1+TXV | TMLE060A12MP11 | 26,200 | $1,310 |
| No | 211392694 | FRASER-JOHNSTON | HMH72B341 | XAFB30CXXN1+TXV | TM8E060A12MP11 | 26,200 | $1,310 |
| No | 211392681 | FRASER-JOHNSTON | HMH72B341 | XAUB36DXXN1+TXV | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 211392666 | FRASER-JOHNSTON | HMH72B341 | XAFB36DBCN1 | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 211392652 | FRASER-JOHNSTON | HMH72B341 | XAUB36DXXN1+TXV | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 211392637 | FRASER-JOHNSTON | HMH72B341 | XAFB36DBCN1 | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 211392622 | FRASER-JOHNSTON | HMH72B341 | XAFB36DXXN1+TXV | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 211392607 | FRASER-JOHNSTON | HMH72B341 | XAFB36DXXN1+TXV | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 211392592 | FRASER-JOHNSTON | HMH72B341 | XAHB30CXXN1+TXV | TMLE060A12MP11 | 25,800 | $1,290 |
| No | 211392577 | FRASER-JOHNSTON | HMH72B341 | XAHB30CXXN1+TXV | TM8E060A12MP11 | 25,800 | $1,290 |
| No | 211392563 | FRASER-JOHNSTON | HMH72B341 | XAHB36DBCN1 | TMLE060A12MP11 | 25,000 | $1,250 |
| No | 211392551 | FRASER-JOHNSTON | HMH72B341 | XAHB36DBCN1 | TM8E060A12MP11 | 25,000 | $1,250 |
| No | 211392536 | FRASER-JOHNSTON | HMH72B341 | XAHB36DXXN1+TXV | TMLE060A12MP11 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211392521 | FRASER-JOHNSTON | HMH72B341 | XAHB36DXXN1+TXV | TM8E060A12MP11 | 25,000 | $1,250 |
| No | 211392510 | FRASER-JOHNSTON | HMH72B341 | XAUB30CXXN1+TXV | TMLE080B12MP11 | 26,800 | $1,340 |
| No | 211392495 | FRASER-JOHNSTON | HMH72B341 | XAUB30CXXN1+TXV | TM8E080B12MP11 | 26,800 | $1,340 |
| No | 211392480 | FRASER-JOHNSTON | HMH72B341 | XAFB30CXXN1+TXV | TMLE080B12MP11 | 26,800 | $1,340 |
| No | 211392465 | FRASER-JOHNSTON | HMH72B341 | XAFB30CXXN1+TXV | TM8E080B12MP11 | 26,800 | $1,340 |
| No | 211392452 | FRASER-JOHNSTON | HMH72B341 | XAUB36DXXN1+TXV | TMLE080B12MP11 | 25,800 | $1,290 |
| No | 211392439 | FRASER-JOHNSTON | HMH72B341 | XAFB36DBCN1 | TMLE080B12MP11 | 25,800 | $1,290 |
| No | 211392424 | FRASER-JOHNSTON | HMH72B341 | XAUB36DXXN1+TXV | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211392413 | FRASER-JOHNSTON | HMH72B341 | XAFB36DBCN1 | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211392400 | FRASER-JOHNSTON | HMH72B341 | XAFB36DXXN1+TXV | TMLE080B12MP11 | 25,800 | $1,290 |
| No | 211392385 | FRASER-JOHNSTON | HMH72B341 | XAFB36DXXN1+TXV | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211392370 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TMLE080B12MP11 | 26,800 | $1,340 |
| No | 211392355 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TM8E080B12MP11 | 26,800 | $1,340 |
| No | 211392340 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TMLE080B12MP11 | 25,800 | $1,290 |
| No | 211392325 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211392312 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TMLE080B12MP11 | 25,800 | $1,290 |
| No | 211392298 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211392284 | FRASER-JOHNSTON | HMH72B341 | XAHB30CXXN1+TXV | TMLE080B12MP11 | 26,200 | $1,310 |
| No | 211392275 | FRASER-JOHNSTON | HMH72B341 | XAHB30CXXN1+TXV | TM8E080B12MP11 | 26,200 | $1,310 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211392265 | FRASER-JOHNSTON | HMH72B341 | XAHB36DBCN1 | TMLE080B12MP11 | 25,000 | $1,250 |
| No | 211392250 | FRASER-JOHNSTON | HMH72B341 | XAHB36DBCN1 | TM8E080B12MP11 | 25,000 | $1,250 |
| No | 211392235 | FRASER-JOHNSTON | HMH72B341 | XAHB36DXXN1+TXV | TMLE080B12MP11 | 25,000 | $1,250 |
| No | 211392220 | FRASER-JOHNSTON | HMH72B341 | XAHB36DXXN1+TXV | TM8E080B12MP11 | 25,000 | $1,250 |
| No | 211392205 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TMLE080B12MP11 | 26,400 | $1,320 |
| No | 211392195 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TM8E080B12MP11 | 26,400 | $1,320 |
| No | 211392184 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TMLE080B12MP11 | 25,000 | $1,250 |
| No | 211392168 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TM8E080B12MP11 | 25,000 | $1,250 |
| No | 211392153 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TMLE080B12MP11 | 25,000 | $1,250 |
| No | 211392138 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TM8E080B12MP11 | 25,000 | $1,250 |
| No | 211392123 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TMLE080C16MP11 | 26,000 | $1,300 |
| No | 211392108 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TM8E080C16MP11 | 26,000 | $1,300 |
| No | 211392093 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211392078 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211392063 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211392057 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211392044 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TMLE080C16MP11 | 25,600 | $1,280 |
| No | 211392029 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TM8E080C16MP11 | 25,600 | $1,280 |
| No | 211392014 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TMLE080C16MP11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211391999 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TM8E080C16MP11 | 24,600 | $1,230 |
| No | 211391984 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TMLE080C16MP11 | 24,600 | $1,230 |
| No | 211391969 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TM8E080C16MP11 | 24,600 | $1,230 |
| No | 211391954 | FRASER-JOHNSTON | HMH72B341 | XAUB30CXXN1+TXV | TMLE100B12MP11 | 26,200 | $1,310 |
| No | 211391939 | FRASER-JOHNSTON | HMH72B341 | XAUB30CXXN1+TXV | TM8E100B12MP11 | 26,200 | $1,310 |
| No | 211391924 | FRASER-JOHNSTON | HMH72B341 | XAFB30CXXN1+TXV | TMLE100B12MP11 | 26,200 | $1,310 |
| No | 211391909 | FRASER-JOHNSTON | HMH72B341 | XAFB30CXXN1+TXV | TM8E100B12MP11 | 26,200 | $1,310 |
| No | 211391894 | FRASER-JOHNSTON | HMH72B341 | XAUB36DXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211391879 | FRASER-JOHNSTON | HMH72B341 | XAFB36DBCN1 | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211391864 | FRASER-JOHNSTON | HMH72B341 | XAUB36DXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211391850 | FRASER-JOHNSTON | HMH72B341 | XAFB36DBCN1 | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211391835 | FRASER-JOHNSTON | HMH72B341 | XAFB36DXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211391821 | FRASER-JOHNSTON | HMH72B341 | XAFB36DXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211391806 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TMLE100B12MP11 | 26,200 | $1,310 |
| No | 211391791 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TM8E100B12MP11 | 26,200 | $1,310 |
| No | 211391780 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211391765 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211391750 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211391740 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211391725 | FRASER-JOHNSTON | HMH72B341 | XAHB30CXXN1+TXV | TMLE100B12MP11 | 25,800 | $1,290 |
| No | 211391710 | FRASER-JOHNSTON | HMH72B341 | XAHB30CXXN1+TXV | TM8E100B12MP11 | 25,800 | $1,290 |
| No | 211391700 | FRASER-JOHNSTON | HMH72B341 | XAHB36DBCN1 | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 211391693 | FRASER-JOHNSTON | HMH72B341 | XAHB36DBCN1 | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 211391678 | FRASER-JOHNSTON | HMH72B341 | XAHB36DXXN1+TXV | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 211391663 | FRASER-JOHNSTON | HMH72B341 | XAHB36DXXN1+TXV | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 211391648 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TMLE100B12MP11 | 25,600 | $1,280 |
| No | 211391634 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TM8E100B12MP11 | 25,600 | $1,280 |
| No | 211391626 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TMLE100B12MP11 | 24,800 | $1,240 |
| No | 211391611 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TM8E100B12MP11 | 24,800 | $1,240 |
| No | 211391596 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TMLE100B12MP11 | 24,800 | $1,240 |
| No | 211391581 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TM8E100B12MP11 | 24,800 | $1,240 |
| No | 211391566 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TMLE100C16MP11 | 26,000 | $1,300 |
| No | 211391551 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TM8E100C16MP11 | 26,000 | $1,300 |
| No | 211391536 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TMLE100C16MP11 | 25,200 | $1,260 |
| No | 211391521 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TM8E100C16MP11 | 25,200 | $1,260 |
| No | 211391506 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TMLE100C16MP11 | 25,200 | $1,260 |
| No | 211391491 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TM8E100C16MP11 | 25,200 | $1,260 |
| No | 211391476 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TMLE100C16MP11 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211391461 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TM8E100C16MP11 | 25,600 | $1,280 |
| No | 211391446 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211391431 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211391416 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211391401 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211391386 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TMLE120C16MP11 | 26,200 | $1,310 |
| No | 211391371 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TM8E120C16MP11 | 26,200 | $1,310 |
| No | 211391356 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TMLE120C16MP11 | 25,200 | $1,260 |
| No | 211391341 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TM8E120C16MP11 | 25,200 | $1,260 |
| No | 211391326 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TMLE120C16MP11 | 25,200 | $1,260 |
| No | 211391311 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TM8E120C16MP11 | 25,200 | $1,260 |
| No | 211391296 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TMLE120C16MP11 | 25,600 | $1,280 |
| No | 211391282 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TM8E120C16MP11 | 25,600 | $1,280 |
| No | 211391267 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211391252 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211391238 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211391223 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211391208 | FRASER-JOHNSTON | HMH72B341 | XAUB30CXXN1+TXV | TPLC060A12MP13 | 26,000 | $1,300 |
| No | 211391193 | FRASER-JOHNSTON | HMH72B341 | XAUB30CXXN1+TXV | TMLV060A12MP12 | 26,000 | $1,300 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211391178 | FRASER-JOHNSTON | HMH72B341 | XAUB30CXXN1+TXV | TM8V060A12MP12 | 26,000 | $1,300 |
| No | 211391163 | FRASER-JOHNSTON | HMH72B341 | XAFB30CXXN1+TXV | TPLC060A12MP13 | 26,000 | $1,300 |
| No | 211391149 | FRASER-JOHNSTON | HMH72B341 | XAFB30CXXN1+TXV | TMLV060A12MP12 | 26,000 | $1,300 |
| No | 211391134 | FRASER-JOHNSTON | HMH72B341 | XAFB30CXXN1+TXV | TM8V060A12MP12 | 26,000 | $1,300 |
| No | 211391119 | FRASER-JOHNSTON | HMH72B341 | XAUB36DXXN1+TXV | TPLC060A12MP13 | 25,600 | $1,280 |
| No | 211391104 | FRASER-JOHNSTON | HMH72B341 | XAFB36DBCN1 | TPLC060A12MP13 | 25,600 | $1,280 |
| No | 211391089 | FRASER-JOHNSTON | HMH72B341 | XAUB36DXXN1+TXV | TMLV060A12MP12 | 25,600 | $1,280 |
| No | 211391074 | FRASER-JOHNSTON | HMH72B341 | XAFB36DBCN1 | TMLV060A12MP12 | 25,600 | $1,280 |
| No | 211391059 | FRASER-JOHNSTON | HMH72B341 | XAUB36DXXN1+TXV | TM8V060A12MP12 | 25,600 | $1,280 |
| No | 211391044 | FRASER-JOHNSTON | HMH72B341 | XAFB36DBCN1 | TM8V060A12MP12 | 25,600 | $1,280 |
| No | 211391029 | FRASER-JOHNSTON | HMH72B341 | XAFB36DXXN1+TXV | TPLC060A12MP13 | 25,600 | $1,280 |
| No | 211391014 | FRASER-JOHNSTON | HMH72B341 | XAFB36DXXN1+TXV | TMLV060A12MP12 | 25,600 | $1,280 |
| No | 211390999 | FRASER-JOHNSTON | HMH72B341 | XAFB36DXXN1+TXV | TM8V060A12MP12 | 25,600 | $1,280 |
| No | 211390984 | FRASER-JOHNSTON | HMH72B341 | XAHB30CXXN1+TXV | TPLC060A12MP13 | 25,600 | $1,280 |
| No | 211390969 | FRASER-JOHNSTON | HMH72B341 | XAHB30CXXN1+TXV | TMLV060A12MP12 | 25,600 | $1,280 |
| No | 211390954 | FRASER-JOHNSTON | HMH72B341 | XAHB30CXXN1+TXV | TM8V060A12MP12 | 25,600 | $1,280 |
| No | 211390940 | FRASER-JOHNSTON | HMH72B341 | XAHB36DBCN1 | TPLC060A12MP13 | 25,200 | $1,260 |
| No | 211390925 | FRASER-JOHNSTON | HMH72B341 | XAHB36DBCN1 | TMLV060A12MP12 | 25,200 | $1,260 |
| No | 211390910 | FRASER-JOHNSTON | HMH72B341 | XAHB36DBCN1 | TM8V060A12MP12 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211390895 | FRASER-JOHNSTON | HMH72B341 | XAHB36DXXN1+TXV | TPLC060A12MP13 | 25,200 | $1,260 |
| No | 211390880 | FRASER-JOHNSTON | HMH72B341 | XAHB36DXXN1+TXV | TMLV060A12MP12 | 25,200 | $1,260 |
| No | 211390866 | FRASER-JOHNSTON | HMH72B341 | XAHB36DXXN1+TXV | TM8V060A12MP12 | 25,200 | $1,260 |
| No | 211390848 | FRASER-JOHNSTON | HMH72B341 | XAUB30CXXN1+TXV | TPLC080B12MP13 | 26,400 | $1,320 |
| No | 211390833 | FRASER-JOHNSTON | HMH72B341 | XAUB30CXXN1+TXV | TM8V080B12MP12 | 26,400 | $1,320 |
| No | 211390815 | FRASER-JOHNSTON | HMH72B341 | XAFB30CXXN1+TXV | TPLC080B12MP13 | 26,400 | $1,320 |
| No | 211390800 | FRASER-JOHNSTON | HMH72B341 | XAFB30CXXN1+TXV | TM8V080B12MP12 | 26,400 | $1,320 |
| No | 211390780 | FRASER-JOHNSTON | HMH72B341 | XAUB36DXXN1+TXV | TPLC080B12MP13 | 25,400 | $1,270 |
| No | 211390765 | FRASER-JOHNSTON | HMH72B341 | XAFB36DBCN1 | TPLC080B12MP13 | 25,400 | $1,270 |
| No | 211390750 | FRASER-JOHNSTON | HMH72B341 | XAUB36DXXN1+TXV | TM8V080B12MP12 | 25,400 | $1,270 |
| No | 211390735 | FRASER-JOHNSTON | HMH72B341 | XAFB36DBCN1 | TM8V080B12MP12 | 25,400 | $1,270 |
| No | 211390717 | FRASER-JOHNSTON | HMH72B341 | XAFB36DXXN1+TXV | TPLC080B12MP13 | 25,400 | $1,270 |
| No | 211390702 | FRASER-JOHNSTON | HMH72B341 | XAFB36DXXN1+TXV | TM8V080B12MP12 | 25,400 | $1,270 |
| No | 211390684 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TPLC080B12MP13 | 26,400 | $1,320 |
| No | 211390669 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TM8V080B12MP12 | 26,400 | $1,320 |
| No | 211390651 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TPLC080B12MP13 | 25,600 | $1,280 |
| No | 211390637 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TM8V080B12MP12 | 25,600 | $1,280 |
| No | 211390619 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TPLC080B12MP13 | 25,600 | $1,280 |
| No | 211390604 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TM8V080B12MP12 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211390586 | FRASER-JOHNSTON | HMH72B341 | XAHB30CXXN1+TXV | TPLC080B12MP13 | 25,600 | $1,280 |
| No | 211390571 | FRASER-JOHNSTON | HMH72B341 | XAHB30CXXN1+TXV | TM8V080B12MP12 | 25,600 | $1,280 |
| No | 211390553 | FRASER-JOHNSTON | HMH72B341 | XAHB36DBCN1 | TPLC080B12MP13 | 25,000 | $1,250 |
| No | 211390538 | FRASER-JOHNSTON | HMH72B341 | XAHB36DBCN1 | TM8V080B12MP12 | 25,000 | $1,250 |
| No | 211390520 | FRASER-JOHNSTON | HMH72B341 | XAHB36DXXN1+TXV | TPLC080B12MP13 | 25,000 | $1,250 |
| No | 211390505 | FRASER-JOHNSTON | HMH72B341 | XAHB36DXXN1+TXV | TM8V080B12MP12 | 25,000 | $1,250 |
| No | 211390488 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TPLC080B12MP13 | 26,000 | $1,300 |
| No | 211390473 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TM8V080B12MP12 | 26,000 | $1,300 |
| No | 211390455 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TPLC080B12MP13 | 24,800 | $1,240 |
| No | 211390440 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TM8V080B12MP12 | 24,800 | $1,240 |
| No | 211390422 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TPLC080B12MP13 | 24,800 | $1,240 |
| No | 211390408 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TM8V080B12MP12 | 24,800 | $1,240 |
| No | 211390381 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TPLC100C16MP13 | 26,400 | $1,320 |
| No | 211390366 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TPLC080C16MP13 | 26,400 | $1,320 |
| No | 211390351 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TMLV100C16MP12 | 26,400 | $1,320 |
| No | 211390337 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TM8V080C16MP12 | 26,400 | $1,320 |
| No | 211390323 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TM8V100C16MP12 | 26,400 | $1,320 |
| No | 211390298 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TPLC100C16MP13 | 25,400 | $1,270 |
| No | 211390285 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TPLC080C16MP13 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211390271 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TMLV100C16MP12 | 25,400 | $1,270 |
| No | 211390257 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TM8V080C16MP12 | 25,400 | $1,270 |
| No | 211390242 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TM8V100C16MP12 | 25,400 | $1,270 |
| No | 211390216 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TPLC100C16MP13 | 25,400 | $1,270 |
| No | 211390202 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TPLC080C16MP13 | 25,400 | $1,270 |
| No | 211390189 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TMLV100C16MP12 | 25,400 | $1,270 |
| No | 211390174 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TM8V080C16MP12 | 25,400 | $1,270 |
| No | 211390160 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TM8V100C16MP12 | 25,400 | $1,270 |
| No | 211390136 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TPLC100C16MP13 | 25,600 | $1,280 |
| No | 211390123 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TPLC080C16MP13 | 25,600 | $1,280 |
| No | 211390109 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TMLV100C16MP12 | 25,600 | $1,280 |
| No | 211390079 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TM8V100C16MP12 | 25,600 | $1,280 |
| No | 211390054 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TPLC100C16MP13 | 25,600 | $1,280 |
| No | 211390040 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TPLC080C16MP13 | 25,600 | $1,280 |
| No | 211390025 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TMLV100C16MP12 | 25,600 | $1,280 |
| No | 211389997 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TM8V100C16MP12 | 25,600 | $1,280 |
| No | 211389972 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TPLC100C16MP13 | 25,600 | $1,280 |
| No | 211389958 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TPLC080C16MP13 | 25,600 | $1,280 |
| No | 211389944 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TMLV100C16MP12 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211389914 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TM8V100C16MP12 | 25,600 | $1,280 |
| No | 211389899 | FRASER-JOHNSTON | HMH72B341 | XAUB30CXXN1+TXV | TM8Y060A12MP11 | 25,800 | $1,290 |
| No | 211389888 | FRASER-JOHNSTON | HMH72B341 | XAFB30CXXN1+TXV | TM8Y060A12MP11 | 25,800 | $1,290 |
| No | 211389878 | FRASER-JOHNSTON | HMH72B341 | XAUB36DXXN1+TXV | TM8Y060A12MP11 | 25,200 | $1,260 |
| No | 211389864 | FRASER-JOHNSTON | HMH72B341 | XAFB36DBCN1 | TM8Y060A12MP11 | 25,200 | $1,260 |
| No | 211389851 | FRASER-JOHNSTON | HMH72B341 | XAFB36DXXN1+TXV | TM8Y060A12MP11 | 25,200 | $1,260 |
| No | 211389836 | FRASER-JOHNSTON | HMH72B341 | XAHB30CXXN1+TXV | TM8Y060A12MP11 | 25,400 | $1,270 |
| No | 211389822 | FRASER-JOHNSTON | HMH72B341 | XAHB36DBCN1 | TM8Y060A12MP11 | 24,600 | $1,230 |
| No | 211389807 | FRASER-JOHNSTON | HMH72B341 | XAHB36DXXN1+TXV | TM8Y060A12MP11 | 24,600 | $1,230 |
| No | 211389792 | FRASER-JOHNSTON | HMH72B341 | XAUB30CXXN1+TXV | TM8Y080B12MP11 | 26,000 | $1,300 |
| No | 211389777 | FRASER-JOHNSTON | HMH72B341 | XAFB30CXXN1+TXV | TM8Y080B12MP11 | 26,000 | $1,300 |
| No | 211389762 | FRASER-JOHNSTON | HMH72B341 | XAUB36DXXN1+TXV | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211389747 | FRASER-JOHNSTON | HMH72B341 | XAFB36DBCN1 | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211389732 | FRASER-JOHNSTON | HMH72B341 | XAFB36DXXN1+TXV | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211389724 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TM8Y080B12MP11 | 26,000 | $1,300 |
| No | 211389710 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211389696 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211389681 | FRASER-JOHNSTON | HMH72B341 | XAHB30CXXN1+TXV | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211389666 | FRASER-JOHNSTON | HMH72B341 | XAHB36DBCN1 | TM8Y080B12MP11 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211389651 | FRASER-JOHNSTON | HMH72B341 | XAHB36DXXN1+TXV | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211389636 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211389622 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211389607 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211389577 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TM8Y100C16MP11 | 26,400 | $1,320 |
| No | 211389558 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211389529 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211389515 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TM8Y080C16MP11 | 26,600 | $1,330 |
| No | 211389500 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TM8Y100C16MP11 | 26,600 | $1,330 |
| No | 211389485 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TM8Y080C16MP11 | 25,600 | $1,280 |
| No | 211389470 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TM8Y100C16MP11 | 25,600 | $1,280 |
| No | 211389455 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TM8Y080C16MP11 | 25,600 | $1,280 |
| No | 211389444 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TM8Y100C16MP11 | 25,600 | $1,280 |
| No | 211389416 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TM8Y120C20MP11 | 27,000 | $1,350 |
| No | 211389391 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211389366 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211389351 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TM8Y100C20MP11 | 26,400 | $1,320 |
| No | 211389336 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TM8Y120C20MP11 | 26,400 | $1,320 |
| No | 211389321 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TM8Y100C20MP11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211389307 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TM8Y120C20MP11 | 25,400 | $1,270 |
| No | 211389292 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TM8Y100C20MP11 | 25,400 | $1,270 |
| No | 211389277 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TM8Y120C20MP11 | 25,400 | $1,270 |
| No | 211389263 | FRASER-JOHNSTON | HMH72B341 | XAUB30CXXN1+TXV | TM9E040A10MP12 | 25,800 | $1,290 |
| No | 211389248 | FRASER-JOHNSTON | HMH72B341 | XAFB30CXXN1+TXV | TM9E040A10MP12 | 25,800 | $1,290 |
| No | 211389240 | FRASER-JOHNSTON | HMH72B341 | XAUB30CXXN1+TXV | TM9E060A10MP12 | 26,200 | $1,310 |
| No | 211389226 | FRASER-JOHNSTON | HMH72B341 | XAFB30CXXN1+TXV | TM9E060A10MP12 | 26,200 | $1,310 |
| No | 211389211 | FRASER-JOHNSTON | HMH72B341 | XAUB36DXXN1+TXV | TM9E060A10MP12 | 25,400 | $1,270 |
| No | 211389196 | FRASER-JOHNSTON | HMH72B341 | XAFB36DBCN1 | TM9E060A10MP12 | 25,400 | $1,270 |
| No | 211389181 | FRASER-JOHNSTON | HMH72B341 | XAFB36DXXN1+TXV | TM9E060A10MP12 | 25,400 | $1,270 |
| No | 211389173 | FRASER-JOHNSTON | HMH72B341 | XAHB30CXXN1+TXV | TM9E060A10MP12 | 25,800 | $1,290 |
| No | 211389163 | FRASER-JOHNSTON | HMH72B341 | XAHB36DBCN1 | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 211389148 | FRASER-JOHNSTON | HMH72B341 | XAHB36DXXN1+TXV | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 211389133 | FRASER-JOHNSTON | HMH72B341 | XAUB30CXXN1+TXV | TM9E060B12MP12 | 26,400 | $1,320 |
| No | 211389118 | FRASER-JOHNSTON | HMH72B341 | XAFB30CXXN1+TXV | TM9E060B12MP12 | 26,400 | $1,320 |
| No | 211389103 | FRASER-JOHNSTON | HMH72B341 | XAUB36DXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211389088 | FRASER-JOHNSTON | HMH72B341 | XAFB36DBCN1 | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211389073 | FRASER-JOHNSTON | HMH72B341 | XAFB36DXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211389059 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TM9E060B12MP12 | 26,400 | $1,320 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211389044 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211389029 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211389014 | FRASER-JOHNSTON | HMH72B341 | XAHB30CXXN1+TXV | TM9E060B12MP12 | 26,000 | $1,300 |
| No | 211389000 | FRASER-JOHNSTON | HMH72B341 | XAHB36DBCN1 | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211388985 | FRASER-JOHNSTON | HMH72B341 | XAHB36DXXN1+TXV | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211388970 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TM9E060B12MP12 | 26,200 | $1,310 |
| No | 211388959 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211388944 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211388929 | FRASER-JOHNSTON | HMH72B341 | XAUB30CXXN1+TXV | TM9E080B12MP12 | 26,800 | $1,340 |
| No | 211388914 | FRASER-JOHNSTON | HMH72B341 | XAFB30CXXN1+TXV | TM9E080B12MP12 | 26,800 | $1,340 |
| No | 211388899 | FRASER-JOHNSTON | HMH72B341 | XAUB36DXXN1+TXV | TM9E080B12MP12 | 25,400 | $1,270 |
| No | 211388889 | FRASER-JOHNSTON | HMH72B341 | XAFB36DBCN1 | TM9E080B12MP12 | 25,400 | $1,270 |
| No | 211388877 | FRASER-JOHNSTON | HMH72B341 | XAFB36DXXN1+TXV | TM9E080B12MP12 | 25,400 | $1,270 |
| No | 211388862 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TM9E080B12MP12 | 26,400 | $1,320 |
| No | 211388847 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TM9E080B12MP12 | 25,800 | $1,290 |
| No | 211388832 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TM9E080B12MP12 | 25,800 | $1,290 |
| No | 211388817 | FRASER-JOHNSTON | HMH72B341 | XAHB30CXXN1+TXV | TM9E080B12MP12 | 25,800 | $1,290 |
| No | 211388802 | FRASER-JOHNSTON | HMH72B341 | XAHB36DBCN1 | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211388794 | FRASER-JOHNSTON | HMH72B341 | XAHB36DXXN1+TXV | TM9E080B12MP12 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211388779 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TM9E080B12MP12 | 26,200 | $1,310 |
| No | 211388765 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211388750 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211388735 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TM9E080C16MP12 | 26,200 | $1,310 |
| No | 211388720 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TM9E080C16MP12 | 25,200 | $1,260 |
| No | 211388706 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TM9E080C16MP12 | 25,200 | $1,260 |
| No | 211388691 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TM9E080C16MP12 | 26,800 | $1,340 |
| No | 211388676 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211388661 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211388646 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TM9E100C16MP12 | 26,200 | $1,310 |
| No | 211388631 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TM9E100C16MP12 | 25,200 | $1,260 |
| No | 211388616 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TM9E100C16MP12 | 25,200 | $1,260 |
| No | 211388602 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TM9E100C16MP12 | 25,600 | $1,280 |
| No | 211388587 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211388572 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211388560 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TM9E100C20MP12 | 25,000 | $1,250 |
| No | 211388550 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TM9E100C20MP12 | 25,000 | $1,250 |
| No | 211388545 | FRASER-JOHNSTON | HMH72B341 | XAUB30CXXN1+TXV | TM9V040A10MP12 | 25,800 | $1,290 |
| No | 211388534 | FRASER-JOHNSTON | HMH72B341 | XAFB30CXXN1+TXV | TM9V040A10MP12 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211388519 | FRASER-JOHNSTON | HMH72B341 | XAUB36DXXN1+TXV | TM9V040A10MP12 | 25,200 | $1,260 |
| No | 211388511 | FRASER-JOHNSTON | HMH72B341 | XAFB36DBCN1 | TM9V040A10MP12 | 25,200 | $1,260 |
| No | 211388501 | FRASER-JOHNSTON | HMH72B341 | XAFB36DXXN1+TXV | TM9V040A10MP12 | 25,200 | $1,260 |
| No | 211388487 | FRASER-JOHNSTON | HMH72B341 | XAHB30CXXN1+TXV | TM9V040A10MP12 | 25,200 | $1,260 |
| No | 211388473 | FRASER-JOHNSTON | HMH72B341 | XAHB36DBCN1 | TM9V040A10MP12 | 24,800 | $1,240 |
| No | 211388460 | FRASER-JOHNSTON | HMH72B341 | XAHB36DXXN1+TXV | TM9V040A10MP12 | 24,800 | $1,240 |
| No | 211388446 | FRASER-JOHNSTON | HMH72B341 | XAUB30CXXN1+TXV | TP9C060B12MP13 | 26,400 | $1,320 |
| No | 211388434 | FRASER-JOHNSTON | HMH72B341 | XAUB30CXXN1+TXV | TM9V060B12MP12 | 26,400 | $1,320 |
| No | 211388415 | FRASER-JOHNSTON | HMH72B341 | XAFB30CXXN1+TXV | TP9C060B12MP13 | 26,400 | $1,320 |
| No | 211388400 | FRASER-JOHNSTON | HMH72B341 | XAFB30CXXN1+TXV | TM9V060B12MP12 | 26,400 | $1,320 |
| No | 211388377 | FRASER-JOHNSTON | HMH72B341 | XAUB36DXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388366 | FRASER-JOHNSTON | HMH72B341 | XAFB36DBCN1 | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388352 | FRASER-JOHNSTON | HMH72B341 | XAUB36DXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388339 | FRASER-JOHNSTON | HMH72B341 | XAFB36DBCN1 | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388320 | FRASER-JOHNSTON | HMH72B341 | XAFB36DXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388306 | FRASER-JOHNSTON | HMH72B341 | XAFB36DXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388286 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TP9C060B12MP13 | 26,400 | $1,320 |
| No | 211388272 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TM9V060B12MP12 | 26,400 | $1,320 |
| No | 211388252 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TP9C060B12MP13 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211388238 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388226 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388220 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388201 | FRASER-JOHNSTON | HMH72B341 | XAHB30CXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388187 | FRASER-JOHNSTON | HMH72B341 | XAHB30CXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388171 | FRASER-JOHNSTON | HMH72B341 | XAHB36DBCN1 | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 211388157 | FRASER-JOHNSTON | HMH72B341 | XAHB36DBCN1 | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 211388137 | FRASER-JOHNSTON | HMH72B341 | XAHB36DXXN1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 211388123 | FRASER-JOHNSTON | HMH72B341 | XAHB36DXXN1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 211388103 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TP9C060B12MP13 | 26,000 | $1,300 |
| No | 211388090 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TM9V060B12MP12 | 26,000 | $1,300 |
| No | 211388072 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TP9C060B12MP13 | 25,200 | $1,260 |
| No | 211388057 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TM9V060B12MP12 | 25,200 | $1,260 |
| No | 211388038 | FRASER-JOHNSTON | HMH72B341 | 0 | TP9C060B12MP13 | 25,200 | $1,260 |
| No | 211388029 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TM9V060B12MP12 | 25,200 | $1,260 |
| No | 211388016 | FRASER-JOHNSTON | HMH72B341 | XAUB30CXXN1+TXV | TP9C080B12MP13 | 26,600 | $1,330 |
| No | 211388004 | FRASER-JOHNSTON | HMH72B341 | XAUB30CXXN1+TXV | TM9V080B12MP12 | 26,600 | $1,330 |
| No | 211387984 | FRASER-JOHNSTON | HMH72B341 | XAFB30CXXN1+TXV | TP9C080B12MP13 | 26,600 | $1,330 |
| No | 211387970 | FRASER-JOHNSTON | HMH72B341 | XAFB30CXXN1+TXV | TM9V080B12MP12 | 26,600 | $1,330 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211387953 | FRASER-JOHNSTON | HMH72B341 | XAUB36DXXN1+TXV | TP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387938 | FRASER-JOHNSTON | HMH72B341 | XAFB36DBCN1 | TP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387926 | FRASER-JOHNSTON | HMH72B341 | XAUB36DXXN1+TXV | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211387913 | FRASER-JOHNSTON | HMH72B341 | XAFB36DBCN1 | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211387892 | FRASER-JOHNSTON | HMH72B341 | XAFB36DXXN1+TXV | TP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387877 | FRASER-JOHNSTON | HMH72B341 | XAFB36DXXN1+TXV | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211387857 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TP9C080B12MP13 | 26,600 | $1,330 |
| No | 211387844 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TM9V080B12MP12 | 26,600 | $1,330 |
| No | 211387834 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387825 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211387812 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387803 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211387791 | FRASER-JOHNSTON | HMH72B341 | XAHB30CXXN1+TXV | TP9C080B12MP13 | 26,200 | $1,310 |
| No | 211387783 | FRASER-JOHNSTON | HMH72B341 | XAHB30CXXN1+TXV | TM9V080B12MP12 | 26,200 | $1,310 |
| No | 211387772 | FRASER-JOHNSTON | HMH72B341 | XAHB36DBCN1 | TP9C080B12MP13 | 25,200 | $1,260 |
| No | 211387763 | FRASER-JOHNSTON | HMH72B341 | XAHB36DBCN1 | TM9V080B12MP12 | 25,200 | $1,260 |
| No | 211387751 | FRASER-JOHNSTON | HMH72B341 | XAHB36DXXN1+TXV | TP9C080B12MP13 | 25,200 | $1,260 |
| No | 211387743 | FRASER-JOHNSTON | HMH72B341 | XAHB36DXXN1+TXV | TM9V080B12MP12 | 25,200 | $1,260 |
| No | 211387731 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TP9C080B12MP13 | 26,200 | $1,310 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211387723 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TM9V080B12MP12 | 26,200 | $1,310 |
| No | 211387712 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 211387703 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 211387691 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 211387683 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 211387671 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TP9C080C16MP13 | 26,200 | $1,310 |
| No | 211387662 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TM9V080C16MP12 | 26,200 | $1,310 |
| No | 211387651 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211387645 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211387634 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211387625 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211387613 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TP9C080C16MP13 | 25,800 | $1,290 |
| No | 211387606 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TM9V080C16MP12 | 25,800 | $1,290 |
| No | 211387595 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TP9C080C16MP13 | 25,000 | $1,250 |
| No | 211387586 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TM9V080C16MP12 | 25,000 | $1,250 |
| No | 211387574 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TP9C080C16MP13 | 25,000 | $1,250 |
| No | 211387566 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TM9V080C16MP12 | 25,000 | $1,250 |
| No | 211387554 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TP9C100C16MP13 | 26,400 | $1,320 |
| No | 211387547 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TM9V100C16MP12 | 26,400 | $1,320 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211387540 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211387531 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211387514 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211387501 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211387483 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TP9C100C16MP13 | 25,800 | $1,290 |
| No | 211387471 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TM9V100C16MP12 | 25,800 | $1,290 |
| No | 211387451 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TP9C100C16MP13 | 25,000 | $1,250 |
| No | 211387438 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TM9V100C16MP12 | 25,000 | $1,250 |
| No | 211387420 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TP9C100C16MP13 | 25,000 | $1,250 |
| No | 211387406 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TM9V100C16MP12 | 25,000 | $1,250 |
| No | 211387386 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TP9C100C20MP13 | 27,000 | $1,350 |
| No | 211387372 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TM9V100C20MP12 | 27,000 | $1,350 |
| No | 211387353 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TP9C100C20MP13 | 26,000 | $1,300 |
| No | 211387336 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TM9V100C20MP12 | 26,000 | $1,300 |
| No | 211387315 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TP9C100C20MP13 | 26,000 | $1,300 |
| No | 211387301 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TM9V100C20MP12 | 26,000 | $1,300 |
| No | 211387282 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TP9C100C20MP13 | 26,600 | $1,330 |
| No | 211387268 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TM9V100C20MP12 | 26,600 | $1,330 |
| No | 211387253 | FRASER-JOHNSTON | HMH72B341 | XAUB30CXXN1+TXV | TM9Y060B12MP11 | 26,600 | $1,330 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211387239 | FRASER-JOHNSTON | HMH72B341 | XAFB30CXXN1+TXV | TM9Y060B12MP11 | 26,600 | $1,330 |
| No | 211387225 | FRASER-JOHNSTON | HMH72B341 | XAUB36DXXN1+TXV | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211387211 | FRASER-JOHNSTON | HMH72B341 | XAFB36DBCN1 | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211387197 | FRASER-JOHNSTON | HMH72B341 | XAFB36DXXN1+TXV | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211387182 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TM9Y060B12MP11 | 26,600 | $1,330 |
| No | 211387169 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211386476 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TL8E080C16UH11 | 25,400 | $1,270 |
| No | 211386464 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211386449 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211386435 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211386421 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211386409 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211386397 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TL8E100C20UH11 | 24,800 | $1,240 |
| No | 211386384 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TL8E100C20UH11 | 24,800 | $1,240 |
| No | 211386372 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TL8E100C20UH11 | 24,800 | $1,240 |
| No | 211386361 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TL8E100C20UH11 | 24,800 | $1,240 |
| No | 211386349 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TL9E060B12UH11 | 25,800 | $1,290 |
| No | 211386337 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TL9E060B12UH11 | 25,800 | $1,290 |
| No | 211386325 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TL9E060B12UH11 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211386314 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TL9E060B12UH11 | 25,200 | $1,260 |
| No | 211386299 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TL9E060B12UH11 | 25,200 | $1,260 |
| No | 211386285 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TL9E080C16UH11 | 25,800 | $1,290 |
| No | 211386271 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TL9E080C16UH11 | 25,800 | $1,290 |
| No | 211386257 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TL9E080C16UH11 | 25,800 | $1,290 |
| No | 211386244 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TL9E080C16UH11 | 25,600 | $1,280 |
| No | 211386232 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TL9E080C16UH11 | 25,600 | $1,280 |
| No | 211386219 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TL9E080C16UH11 | 25,200 | $1,260 |
| No | 211386208 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TL9E080C16UH11 | 25,200 | $1,260 |
| No | 211386200 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TL9E080C16UH11 | 25,200 | $1,260 |
| No | 211386183 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TL9E080C16UH11 | 25,200 | $1,260 |
| No | 211386171 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211386157 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211386142 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211386124 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211386111 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211386097 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TL9E100C20UH11 | 25,000 | $1,250 |
| No | 211386083 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TL9E100C20UH11 | 25,000 | $1,250 |
| No | 211386068 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TL9E100C20UH11 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211386053 | FRASER-JOHNSTON | HMH72B341 | XAHD48FXXN1+TXV | TL9E100C20UH11 | 25,000 | $1,250 |
| No | 211386041 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TMLE080B12MP11 | 25,600 | $1,280 |
| No | 211386026 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TMLE080B12MP11 | 25,600 | $1,280 |
| No | 211386011 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TM8E080B12MP11 | 25,600 | $1,280 |
| No | 211385997 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TM8E080B12MP11 | 25,600 | $1,280 |
| No | 211385982 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TMLE080B12MP11 | 25,600 | $1,280 |
| No | 211385970 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TM8E080B12MP11 | 25,600 | $1,280 |
| No | 211385956 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TMLE080B12MP11 | 25,400 | $1,270 |
| No | 211385943 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TM8E080B12MP11 | 25,400 | $1,270 |
| No | 211385930 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TMLE080B12MP11 | 25,400 | $1,270 |
| No | 211385917 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TM8E080B12MP11 | 25,400 | $1,270 |
| No | 211385903 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211385887 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211385870 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211385856 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211385843 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211385831 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211387155 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211387140 | FRASER-JOHNSTON | HMH72B341 | XAHB30CXXN1+TXV | TM9Y060B12MP11 | 26,000 | $1,300 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211387127 | FRASER-JOHNSTON | HMH72B341 | XAHB36DBCN1 | TM9Y060B12MP11 | 25,000 | $1,250 |
| No | 211387113 | FRASER-JOHNSTON | HMH72B341 | XAHB36DXXN1+TXV | TM9Y060B12MP11 | 25,000 | $1,250 |
| No | 211387100 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TM9Y060B12MP11 | 26,000 | $1,300 |
| No | 211387088 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TM9Y060B12MP11 | 25,200 | $1,260 |
| No | 211387076 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TM9Y060B12MP11 | 25,200 | $1,260 |
| No | 211387062 | FRASER-JOHNSTON | HMH72B341 | XAUB30CXXN1+TXV | TM9Y080B12MP11 | 26,800 | $1,340 |
| No | 211387049 | FRASER-JOHNSTON | HMH72B341 | XAFB30CXXN1+TXV | TM9Y080B12MP11 | 26,800 | $1,340 |
| No | 211387035 | FRASER-JOHNSTON | HMH72B341 | XAUB36DXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211387020 | FRASER-JOHNSTON | HMH72B341 | XAFB36DBCN1 | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211387007 | FRASER-JOHNSTON | HMH72B341 | XAFB36DXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211386993 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TM9Y080B12MP11 | 26,800 | $1,340 |
| No | 211386978 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211386964 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211386950 | FRASER-JOHNSTON | HMH72B341 | XAHB30CXXN1+TXV | TM9Y080B12MP11 | 26,200 | $1,310 |
| No | 211386936 | FRASER-JOHNSTON | HMH72B341 | XAHB36DBCN1 | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211386921 | FRASER-JOHNSTON | HMH72B341 | XAHB36DXXN1+TXV | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211386908 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TM9Y080B12MP11 | 26,200 | $1,310 |
| No | 211386893 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TM9Y080B12MP11 | 25,400 | $1,270 |
| No | 211386879 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TM9Y080B12MP11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211386866 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TM9Y080C16MP11 | 26,800 | $1,340 |
| No | 211386854 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TM9Y080C16MP11 | 25,800 | $1,290 |
| No | 211386838 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TM9Y080C16MP11 | 25,800 | $1,290 |
| No | 211386825 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TM9Y080C16MP11 | 26,200 | $1,310 |
| No | 211386811 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TM9Y080C16MP11 | 25,400 | $1,270 |
| No | 211386795 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TM9Y080C16MP11 | 25,400 | $1,270 |
| No | 211386779 | FRASER-JOHNSTON | HMH72B341 | XAFC30CXXN1+TXV | TM9Y100C16MP11 | 26,000 | $1,300 |
| No | 211386765 | FRASER-JOHNSTON | HMH72B341 | XAFC36DBCN1 | TM9Y100C16MP11 | 25,800 | $1,290 |
| No | 211386752 | FRASER-JOHNSTON | HMH72B341 | XAFC36DXXN1+TXV | TM9Y100C16MP11 | 25,800 | $1,290 |
| No | 211386739 | FRASER-JOHNSTON | HMH72B341 | XAHC30CXXN1+TXV | TM9Y100C16MP11 | 25,600 | $1,280 |
| No | 211386725 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TM9Y100C16MP11 | 25,400 | $1,270 |
| No | 211386714 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TM9Y100C16MP11 | 25,400 | $1,270 |
| No | 211386700 | FRASER-JOHNSTON | HMH72B341 | XAHC36DBCN1 | TM9Y100C20MP11 | 25,600 | $1,280 |
| No | 211386686 | FRASER-JOHNSTON | HMH72B341 | XAHC36DXXN1+TXV | TM9Y100C20MP11 | 25,600 | $1,280 |
| No | 211386672 | FRASER-JOHNSTON | HMH72B341 | JHETC42FBCS2N1 | | 25,200 | $1,260 |
| No | 211386658 | FRASER-JOHNSTON | HMH72B341 | JHVTC42FBCC2N1 | | 25,000 | $1,250 |
| No | 211386645 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+JMET12CS2N1+TXV | | 25,400 | $1,270 |
| No | 211386632 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1+JMET12CS2N1 | | 25,400 | $1,270 |
| No | 211386621 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+JMET12CS2N1+TXV | | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211386607 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1+JMET12CS2N1 | | 24,800 | $1,240 |
| No | 211386592 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+JMET12CS2N1+TXV | | 24,800 | $1,240 |
| No | 211386580 | FRASER-JOHNSTON | HMH72B341 | XAUC48FXXN1+TXV | TL8E080C16UH11 | 26,000 | $1,300 |
| No | 211386570 | FRASER-JOHNSTON | HMH72B341 | XAFC48FBCN1 | TL8E080C16UH11 | 26,000 | $1,300 |
| No | 211386557 | FRASER-JOHNSTON | HMH72B341 | XAFC48FXXN1+TXV | TL8E080C16UH11 | 26,000 | $1,300 |
| No | 211386545 | FRASER-JOHNSTON | HMH72B341 | XAFD48FBCN1 | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211386533 | FRASER-JOHNSTON | HMH72B341 | XAFD48FXXN1+TXV | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211386519 | FRASER-JOHNSTON | HMH72B341 | XAHC48FBCN1 | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211386504 | FRASER-JOHNSTON | HMH72B341 | XAHC48FXXN1+TXV | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211386489 | FRASER-JOHNSTON | HMH72B341 | XAHD48FBCN1 | TL8E080C16UH11 | 25,400 | $1,270 |
| No | 208502148 | FRASER-JOHNSTON | HMH72B241 | XAHB36DXXN1+JMET08BS2N1+TXV | | 13,900 | $695 |
| No | 208503263 | FRASER-JOHNSTON | HMH72B241 | XAUB36DXXN1+JMET08BS2N1+TXV | | 14,200 | $710 |
| No | 208614024 | FRASER-JOHNSTON | HMH72B241 | XAFB36DBAN1+JMET08BS2N1 | | 14,200 | $710 |
| No | 208503246 | FRASER-JOHNSTON | HMH72B241 | XAFB36DXXN1+JMET08BS2N1+TXV | | 14,200 | $710 |
| No | 208502626 | FRASER-JOHNSTON | HMH72B241 | XAUB36DXXN1+JMET12BS2N1+TXV | | 14,200 | $710 |
| No | 208614029 | FRASER-JOHNSTON | HMH72B241 | XAFB36DBAN1+JMET12BS2N1 | | 14,200 | $710 |
| No | 208502619 | FRASER-JOHNSTON | HMH72B241 | XAFB36DXXN1+JMET12BS2N1+TXV | | 14,200 | $710 |
| No | 207434653 | FRASER-JOHNSTON | HMH72B241 | XAFC36DXXN1+MVC12CN21+TXV | | 14,300 | $715 |
| No | 207417443 | FRASER-JOHNSTON | HMH72B241 | XAFC36DXXN1+TXV | TM8Y080B12MP11 | 14,300 | $715 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208213854 | FRASER-JOHNSTON | HMH72B241 | XAHC36DXXN1+TXV | TP9C060B12MP13 | 14,300 | $715 |
| No | 208213862 | FRASER-JOHNSTON | HMH72B241 | XAHC36DXXN1+TXV | TM9V060B12MP12 | 14,300 | $715 |
| No | 208501676 | FRASER-JOHNSTON | HMH72B241 | XAHB36DXXN1+JMVT12BC2N1+TXV | | 13,900 | $695 |
| No | 207434657 | FRASER-JOHNSTON | HMH72B241 | XAUB36DXXN1+ME08BN21+TXV | | 14,100 | $705 |
| No | 207434658 | FRASER-JOHNSTON | HMH72B241 | XAFB36DXXN1+ME08BN21+TXV | | 14,100 | $705 |
| No | 207417476 | FRASER-JOHNSTON | HMH72B241 | XAUB36DXXN1+TXV | TL8E060A12UH11 | 14,400 | $720 |
| No | 207417472 | FRASER-JOHNSTON | HMH72B241 | XAFB36DXXN1+TXV | TL8E060A12UH11 | 14,400 | $720 |
| No | 207416656 | FRASER-JOHNSTON | HMH72B241 | XAFA30DXXN1+TXV | TM9E060A10MP12 | 14,600 | $730 |
| No | 208213856 | FRASER-JOHNSTON | HMH72B241 | XAHB36DXXN1+TXV | TP9C080B12MP13 | 14,200 | $710 |
| No | 208213859 | FRASER-JOHNSTON | HMH72B241 | XAHB36DXXN1+TXV | TM9V080B12MP12 | 14,200 | $710 |
| No | 207434656 | FRASER-JOHNSTON | HMH72B241 | XAUB36DXXN1+MVC12BN21+TXV | | 14,300 | $715 |
| No | 207434654 | FRASER-JOHNSTON | HMH72B241 | XAFB36DXXN1+MVC12BN21+TXV | | 14,300 | $715 |
| No | 207417191 | FRASER-JOHNSTON | HMH72B241 | XAFA30DXXN1+TXV | TMLE040A12MP11 | 14,400 | $720 |
| No | 207417187 | FRASER-JOHNSTON | HMH72B241 | XAFA30DXXN1+TXV | TM8E040A12MP11 | 14,400 | $720 |
| No | 207417459 | FRASER-JOHNSTON | HMH72B241 | XAUB36DXXN1+TXV | TM8Y060A12MP11 | 14,200 | $710 |
| No | 207417455 | FRASER-JOHNSTON | HMH72B241 | XAFB36DXXN1+TXV | TM8Y060A12MP11 | 14,200 | $710 |
| No | 207417437 | FRASER-JOHNSTON | HMH72B241 | XAUB36DXXN1+TXV | TP9C060B12MP13 | 14,600 | $730 |
| No | 207417433 | FRASER-JOHNSTON | HMH72B241 | XAUB36DXXN1+TXV | TM9V060B12MP12 | 14,600 | $730 |
| No | 207417427 | FRASER-JOHNSTON | HMH72B241 | XAFB36DXXN1+TXV | TP9C060B12MP13 | 14,600 | $730 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417423 | FRASER-JOHNSTON | HMH72B241 | XAFB36DXXN1+TXV | TM9V060B12MP12 | 14,600 | $730 |
| No | 207416620 | FRASER-JOHNSTON | HMH72B241 | XAFC36DXXN1+TXV | TM9Y060B12MP11 | 14,500 | $725 |
| No | 208614030 | FRASER-JOHNSTON | HMH72B241 | JHETB30DBAS2N1 | | 14,600 | $730 |
| No | 208501698 | FRASER-JOHNSTON | HMH72B241 | JHETB30DXXS2N1+TXV | | 14,600 | $730 |
| No | 208502141 | FRASER-JOHNSTON | HMH72B241 | XAHB36DXXN1+JMET12BS2N1+TXV | | 13,900 | $695 |
| No | 208400364 | FRASER-JOHNSTON | HMH72B241 | XAHB36DXXN1+ME08BN21+TXV | | 14,200 | $710 |
| No | 207417199 | FRASER-JOHNSTON | HMH72B241 | XAUB36DXXN1+TXV | TL9E060B12UH11 | 14,500 | $725 |
| No | 207417195 | FRASER-JOHNSTON | HMH72B241 | XAFB36DXXN1+TXV | TL9E060B12UH11 | 14,500 | $725 |
| No | 208213864 | FRASER-JOHNSTON | HMH72B241 | XAHC36DXXN1+TXV | TPLC080B12MP13 | 14,100 | $705 |
| No | 208213871 | FRASER-JOHNSTON | HMH72B241 | XAHC36DXXN1+TXV | TM8V080B12MP12 | 14,100 | $705 |
| No | 207417163 | FRASER-JOHNSTON | HMH72B241 | XAUB36DXXN1+TXV | TM9E060A10MP12 | 14,600 | $730 |
| No | 207417159 | FRASER-JOHNSTON | HMH72B241 | XAFB36DXXN1+TXV | TM9E060A10MP12 | 14,600 | $730 |
| No | 208213857 | FRASER-JOHNSTON | HMH72B241 | XAHC36DXXN1+TXV | TP9C080B12MP13 | 14,100 | $705 |
| No | 208213860 | FRASER-JOHNSTON | HMH72B241 | XAHC36DXXN1+TXV | TM9V080B12MP12 | 14,100 | $705 |
| No | 208614028 | FRASER-JOHNSTON | HMH72B241 | JHETB36DBAS2N1 | | 14,300 | $715 |
| No | 208502155 | FRASER-JOHNSTON | HMH72B241 | JHETB36DXXS2N1+TXV | | 14,300 | $715 |
| No | 208501691 | FRASER-JOHNSTON | HMH72B241 | XAUB36DXXN1+JMVT12BC2N1+TXV | | 14,000 | $700 |
| No | 208614031 | FRASER-JOHNSTON | HMH72B241 | XAFB36DBAN1+JMVT12BC2N1 | | 14,000 | $700 |
| No | 208501684 | FRASER-JOHNSTON | HMH72B241 | XAFB36DXXN1+JMVT12BC2N1+TXV | | 14,000 | $700 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207416858 | FRASER-JOHNSTON | HMH72B241 | XAFC36DXXN1+TXV | TMLE100B12MP11 | 14,300 | $715 |
| No | 207416854 | FRASER-JOHNSTON | HMH72B241 | XAFC36DXXN1+TXV | TM8E100B12MP11 | 14,300 | $715 |
| No | 208614027 | FRASER-JOHNSTON | HMH72B241 | JHETC36DBAS2N1 | | 14,200 | $710 |
| No | 208504361 | FRASER-JOHNSTON | HMH72B241 | JHETC36DXXS2N1+TXV | | 14,200 | $710 |
| No | 208400366 | FRASER-JOHNSTON | HMH72B241 | XAHC36DXXN1+MVC12CN21+TXV | | 14,000 | $700 |
| No | 208213875 | FRASER-JOHNSTON | HMH72B241 | XAHC36DXXN1+TXV | TMLE100B12MP11 | 14,000 | $700 |
| No | 208213873 | FRASER-JOHNSTON | HMH72B241 | XAHC36DXXN1+TXV | TM8E100B12MP11 | 14,000 | $700 |
| No | 208213852 | FRASER-JOHNSTON | HMH72B241 | XAHC36DXXN1+TXV | TM8Y080B12MP11 | 14,000 | $700 |
| No | 207417407 | FRASER-JOHNSTON | HMH72B241 | XAUB36DXXN1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 207417403 | FRASER-JOHNSTON | HMH72B241 | XAUB36DXXN1+TXV | TM9V080B12MP12 | 14,400 | $720 |
| No | 207417397 | FRASER-JOHNSTON | HMH72B241 | XAFB36DXXN1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 207417393 | FRASER-JOHNSTON | HMH72B241 | XAFB36DXXN1+TXV | TM9V080B12MP12 | 14,400 | $720 |
| No | 207434655 | FRASER-JOHNSTON | HMH72B241 | XAFC36DXXN1+ME12CN21+TXV | | 14,200 | $710 |
| No | 207416668 | FRASER-JOHNSTON | HMH72B241 | XAFC36DXXN1+TXV | TL9E060B12UH11 | 14,500 | $725 |
| No | 207417183 | FRASER-JOHNSTON | HMH72B241 | XAFA30DXXN1+TXV | TM8Y060A12MP11 | 14,700 | $735 |
| No | 207416648 | FRASER-JOHNSTON | HMH72B241 | XAUB36DXXN1+TXV | TM9V040A10MP12 | 14,800 | $740 |
| No | 207416644 | FRASER-JOHNSTON | HMH72B241 | XAFB36DXXN1+TXV | TM9V040A10MP12 | 14,800 | $740 |
| No | 207416628 | FRASER-JOHNSTON | HMH72B241 | XAUB36DXXN1+TXV | TM9Y060B12MP11 | 14,500 | $725 |
| No | 207416624 | FRASER-JOHNSTON | HMH72B241 | XAFB36DXXN1+TXV | TM9Y060B12MP11 | 14,500 | $725 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207416672 | FRASER-JOHNSTON | HMH72B241 | XAFA30DXXN1+TXV | TL8E060A12UH11 | 14,400 | $720 |
| No | 207416849 | FRASER-JOHNSTON | HMH72B241 | XAUB36DXXN1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 207416845 | FRASER-JOHNSTON | HMH72B241 | XAUB36DXXN1+TXV | TM8V080B12MP12 | 14,400 | $720 |
| No | 207416840 | FRASER-JOHNSTON | HMH72B241 | XAFB36DXXN1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 207416836 | FRASER-JOHNSTON | HMH72B241 | XAFB36DXXN1+TXV | TM8V080B12MP12 | 14,400 | $720 |
| No | 207417175 | FRASER-JOHNSTON | HMH72B241 | XAUB36DXXN1+TXV | TM9E026A08MP12 | 14,800 | $740 |
| No | 207417171 | FRASER-JOHNSTON | HMH72B241 | XAFB36DXXN1+TXV | TM9E026A08MP12 | 14,800 | $740 |
| No | 207416830 | FRASER-JOHNSTON | HMH72B241 | XAFC36DXXN1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 207416826 | FRASER-JOHNSTON | HMH72B241 | XAFC36DXXN1+TXV | TM9V080B12MP12 | 14,400 | $720 |
| No | 208614026 | FRASER-JOHNSTON | HMH72B241 | JHVTB36DBAC2N1 | | 14,000 | $700 |
| No | 208504350 | FRASER-JOHNSTON | HMH72B241 | JHVTB36DXXC2N1+TXV | | 14,000 | $700 |
| No | 208614025 | FRASER-JOHNSTON | HMH72B241 | JHVTC36DBAC2N1 | | 14,100 | $705 |
| No | 208503286 | FRASER-JOHNSTON | HMH72B241 | JHVTC36DXXC2N1+TXV | | 14,100 | $705 |
| No | 207417467 | FRASER-JOHNSTON | HMH72B241 | XAFC36DXXN1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 207417463 | FRASER-JOHNSTON | HMH72B241 | XAFC36DXXN1+TXV | TM8V080B12MP12 | 14,400 | $720 |
| No | 208400365 | FRASER-JOHNSTON | HMH72B241 | XAHB36DXXN1+MVC12BN21+TXV | | 14,100 | $705 |
| No | 207416874 | FRASER-JOHNSTON | HMH72B241 | XAUB36DXXN1+TXV | TMLE040A12MP11 | 14,500 | $725 |
| No | 207416870 | FRASER-JOHNSTON | HMH72B241 | XAUB36DXXN1+TXV | TM8E040A12MP11 | 14,500 | $725 |
| No | 207416866 | FRASER-JOHNSTON | HMH72B241 | XAFB36DXXN1+TXV | TMLE040A12MP11 | 14,500 | $725 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207416862 | FRASER-JOHNSTON | HMH72B241 | XAFB36DXXN1+TXV | TM8E040A12MP11 | 14,500 | $725 |
| No | 207417451 | FRASER-JOHNSTON | HMH72B241 | XAUB36DXXN1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207417447 | FRASER-JOHNSTON | HMH72B241 | XAFB36DXXN1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207417417 | FRASER-JOHNSTON | HMH72B241 | XAFC36DXXN1+TXV | TP9C060B12MP13 | 14,600 | $730 |
| No | 207417413 | FRASER-JOHNSTON | HMH72B241 | XAFC36DXXN1+TXV | TM9V060B12MP12 | 14,600 | $730 |
| No | 207417389 | FRASER-JOHNSTON | HMH72B241 | XAUB36DXXN1+TXV | TM9Y080B12MP11 | 14,600 | $730 |
| No | 207417385 | FRASER-JOHNSTON | HMH72B241 | XAFB36DXXN1+TXV | TM9Y080B12MP11 | 14,600 | $730 |
| No | 208614056 | FRASER-JOHNSTON | HMH72B361 | XAFC36DBCN1+JMET16CS2N1 | | 24,200 | $1,210 |
| No | 208500511 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+JMET16CS2N1+TXV | | 24,200 | $1,210 |
| No | 208503344 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+JMET12CS2N1+TXV | | 24,200 | $1,210 |
| No | 208614061 | FRASER-JOHNSTON | HMH72B361 | XAFC36DBCN1+JMET12CS2N1 | | 24,800 | $1,240 |
| No | 208502633 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+JMET12CS2N1+TXV | | 24,800 | $1,240 |
| No | 208503315 | FRASER-JOHNSTON | HMH72B361 | XAHB36DXXN1+JMVT12BC2N1+TXV | | 24,200 | $1,210 |
| No | 208400386 | FRASER-JOHNSTON | HMH72B361 | XAHB36DXXN1+ME12BN21+TXV | | 24,400 | $1,220 |
| No | 208400382 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+MVC12CN21+TXV | | 24,200 | $1,210 |
| No | 207416604 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 207416600 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 208214119 | FRASER-JOHNSTON | HMH72B361 | XAHB36DXXN1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 208214092 | FRASER-JOHNSTON | HMH72B361 | XAHB36DXXN1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417107 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TMLE080C16MP11 | 25,000 | $1,250 |
| No | 207417103 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TM8E080C16MP11 | 25,000 | $1,250 |
| No | 207417099 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TMLE120C16MP11 | 25,000 | $1,250 |
| No | 207417095 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TM8E120C16MP11 | 25,000 | $1,250 |
| No | 208214067 | FRASER-JOHNSTON | HMH72B361 | XAHB36DXXN1+TXV | TM8Y080B12MP11 | 24,400 | $1,220 |
| No | 207417010 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TM8Y120C20MP11 | 24,600 | $1,230 |
| No | 208214098 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TM9E060B12MP12 | 24,200 | $1,210 |
| No | 208214103 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TM9E100C16MP12 | 24,600 | $1,230 |
| No | 207416976 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+TXV | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 207416972 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+TXV | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 207416966 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+TXV | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 207416962 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+TXV | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 207416428 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TP9C100C20MP13 | 25,200 | $1,260 |
| No | 207416424 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TM9V100C20MP12 | 25,200 | $1,260 |
| No | 208214061 | FRASER-JOHNSTON | HMH72B361 | XAHB36DXXN1+TXV | TM9Y080B12MP11 | 24,400 | $1,220 |
| No | 208502170 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+JMVT12BC2N1+TXV | | 24,600 | $1,230 |
| No | 208614059 | FRASER-JOHNSTON | HMH72B361 | XAFB36DBCN1+JMVT12BC2N1 | | 24,600 | $1,230 |
| No | 208502163 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+JMVT12BC2N1+TXV | | 24,600 | $1,230 |
| No | 207434682 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+ME12BN21+TXV | | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207434681 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+ME12BN21+TXV | | 24,800 | $1,240 |
| No | 207434684 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+MVC12CN21+TXV | | 24,600 | $1,230 |
| No | 208214108 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TL8E080C16UH11 | 24,400 | $1,220 |
| No | 207417147 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+TXV | TMLE040A12MP11 | 25,000 | $1,250 |
| No | 207417143 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+TXV | TM8E040A12MP11 | 25,000 | $1,250 |
| No | 207417139 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+TXV | TMLE040A12MP11 | 25,000 | $1,250 |
| No | 207417135 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+TXV | TM8E040A12MP11 | 25,000 | $1,250 |
| No | 208501098 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+JMVT16CC2N1+TXV | | 24,000 | $1,200 |
| No | 208400385 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+ME12CN21+TXV | | 24,400 | $1,220 |
| No | 208400387 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+MVC16CN21+TXV | | 24,400 | $1,220 |
| No | 208214105 | FRASER-JOHNSTON | HMH72B361 | XAHB36DXXN1+TXV | TL9E060B12UH11 | 24,000 | $1,200 |
| No | 207416584 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+TXV | TMLE060A12MP11 | 25,200 | $1,260 |
| No | 207416580 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+TXV | TM8E060A12MP11 | 25,200 | $1,260 |
| No | 207416576 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+TXV | TMLE060A12MP11 | 25,200 | $1,260 |
| No | 207416572 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+TXV | TM8E060A12MP11 | 25,200 | $1,260 |
| No | 207416560 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+TXV | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 207416556 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+TXV | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 207416552 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+TXV | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 207416548 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+TXV | TM8E100B12MP11 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417091 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+TXV | TPLC060A12MP13 | 25,400 | $1,270 |
| No | 207417087 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+TXV | TMLV060A12MP12 | 25,400 | $1,270 |
| No | 207417083 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+TXV | TM8V060A12MP12 | 25,400 | $1,270 |
| No | 207417079 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+TXV | TPLC060A12MP13 | 25,400 | $1,270 |
| No | 207417075 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+TXV | TMLV060A12MP12 | 25,400 | $1,270 |
| No | 207417071 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+TXV | TM8V060A12MP12 | 25,400 | $1,270 |
| No | 208214091 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 208214090 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TPLC080C16MP13 | 24,600 | $1,230 |
| No | 208214109 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TMLV100C16MP12 | 24,600 | $1,230 |
| No | 208214110 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TM8V080C16MP12 | 24,600 | $1,230 |
| No | 208214113 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 207416498 | FRASER-JOHNSTON | HMH72B361 | XAFA30DXXN1+TXV | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 208214121 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 208214095 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TM8E080B12MP11 | 24,600 | $1,230 |
| No | 208214125 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TMLE100C16MP11 | 24,600 | $1,230 |
| No | 208214116 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TM8E100C16MP11 | 24,600 | $1,230 |
| No | 207416510 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TM8Y080B12MP11 | 25,000 | $1,250 |
| No | 208214099 | FRASER-JOHNSTON | HMH72B361 | XAHB36DXXN1+TXV | TM9E060B12MP12 | 24,200 | $1,210 |
| No | 207416462 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TM9E100C16MP12 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208214073 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 208214084 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 208214078 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TP9C100C16MP13 | 24,600 | $1,230 |
| No | 208214086 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TM9V100C16MP12 | 24,600 | $1,230 |
| No | 207416930 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TM9Y080B12MP11 | 25,000 | $1,250 |
| No | 207416466 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TM9E080B12MP12 | 25,200 | $1,260 |
| No | 207416458 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+TXV | TM9V040A10MP12 | 24,600 | $1,230 |
| No | 207416454 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+TXV | TM9V040A10MP12 | 24,600 | $1,230 |
| No | 208214077 | FRASER-JOHNSTON | HMH72B361 | XAHB36DXXN1+TXV | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 208214083 | FRASER-JOHNSTON | HMH72B361 | XAHB36DXXN1+TXV | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 207416938 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+TXV | TM9Y060B12MP11 | 25,000 | $1,250 |
| No | 207416934 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+TXV | TM9Y060B12MP11 | 25,000 | $1,250 |
| No | 207416926 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TM9Y080C16MP11 | 25,000 | $1,250 |
| No | 208614060 | FRASER-JOHNSTON | HMH72B361 | JHETB36DBCS2N1 | | 25,000 | $1,250 |
| No | 208502184 | FRASER-JOHNSTON | HMH72B361 | JHETB36DXXS2N1+TXV | | 25,000 | $1,250 |
| No | 207434685 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+ME16CN21+TXV | | 25,000 | $1,250 |
| No | 208214104 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TL9E060B12UH11 | 24,000 | $1,200 |
| No | 208214118 | FRASER-JOHNSTON | HMH72B361 | XAHB36DXXN1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 208214093 | FRASER-JOHNSTON | HMH72B361 | XAHB36DXXN1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207416544 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 207416540 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 207416527 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+TXV | TPLC080B12MP13 | 25,000 | $1,250 |
| No | 207416523 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+TXV | TM8V080B12MP12 | 25,000 | $1,250 |
| No | 207416518 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+TXV | TPLC080B12MP13 | 25,000 | $1,250 |
| No | 207416514 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+TXV | TM8V080B12MP12 | 25,000 | $1,250 |
| No | 207416494 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+TXV | TM9E060A10MP12 | 25,200 | $1,260 |
| No | 207416490 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+TXV | TM9E060A10MP12 | 25,200 | $1,260 |
| No | 208614058 | FRASER-JOHNSTON | HMH72B361 | JHETC36DBCS2N1 | | 24,000 | $1,200 |
| No | 208500523 | FRASER-JOHNSTON | HMH72B361 | JHETC36DXXS2N1+TXV | | 24,000 | $1,200 |
| No | 207434687 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+MVC12BN21+TXV | | 24,800 | $1,240 |
| No | 207434688 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+MVC12BN21+TXV | | 24,800 | $1,240 |
| No | 208214107 | FRASER-JOHNSTON | HMH72B361 | XAHB36DXXN1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 208214106 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TL9E080C16UH11 | 24,600 | $1,230 |
| No | 207416568 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TMLE080B12MP11 | 25,200 | $1,260 |
| No | 207416564 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TM8E080B12MP11 | 25,200 | $1,260 |
| No | 208214101 | FRASER-JOHNSTON | HMH72B361 | XAHB36DXXN1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 208214085 | FRASER-JOHNSTON | HMH72B361 | XAHB36DXXN1+TXV | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 208214076 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TP9C080B12MP13 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208214082 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 207416420 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TM9Y060B12MP11 | 25,000 | $1,250 |
| No | 208214065 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TM9Y080C16MP11 | 24,600 | $1,230 |
| No | 208214124 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 208214115 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 208214089 | FRASER-JOHNSTON | HMH72B361 | XAHB36DXXN1+TXV | TPLC080B12MP13 | 24,200 | $1,210 |
| No | 208214112 | FRASER-JOHNSTON | HMH72B361 | XAHB36DXXN1+TXV | TM8V080B12MP12 | 24,200 | $1,210 |
| No | 208214066 | FRASER-JOHNSTON | HMH72B361 | XAHB36DXXN1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 208214071 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TM8Y080C16MP11 | 24,000 | $1,200 |
| No | 208214072 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TM8Y100C16MP11 | 24,000 | $1,200 |
| No | 207416486 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 207416482 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 208614063 | FRASER-JOHNSTON | HMH72B361 | JHVTC36DBCC2N1 | | 24,400 | $1,220 |
| No | 208501705 | FRASER-JOHNSTON | HMH72B361 | JHVTC36DXXC2N1+TXV | | 24,400 | $1,220 |
| No | 208400384 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+ME16CN21+TXV | | 24,600 | $1,230 |
| No | 207416612 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+TXV | TL8E060A12UH11 | 25,000 | $1,250 |
| No | 207416608 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+TXV | TL8E060A12UH11 | 25,000 | $1,250 |
| No | 207416596 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TL9E080C16UH11 | 25,000 | $1,250 |
| No | 207417123 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+TXV | TMLE080B12MP11 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417119 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+TXV | TM8E080B12MP11 | 25,200 | $1,260 |
| No | 207417115 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+TXV | TMLE080B12MP11 | 25,200 | $1,260 |
| No | 207417111 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+TXV | TM8E080B12MP11 | 25,200 | $1,260 |
| No | 208614057 | FRASER-JOHNSTON | HMH72B361 | XAFC36DBCN1+JMVT16CC2N1 | | 24,400 | $1,220 |
| No | 208501107 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+JMVT16CC2N1+TXV | | 24,400 | $1,220 |
| No | 207434686 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+ME12CN21+TXV | | 24,800 | $1,240 |
| No | 207434683 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+MVC16CN21+TXV | | 24,800 | $1,240 |
| No | 207417151 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 207417006 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TM9E080C16MP12 | 25,000 | $1,250 |
| No | 207416448 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TP9C060B12MP13 | 24,800 | $1,240 |
| No | 207416444 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TM9V060B12MP12 | 24,800 | $1,240 |
| No | 208214075 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TP9C080C16MP13 | 24,600 | $1,230 |
| No | 208214087 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TM9V080C16MP12 | 24,600 | $1,230 |
| No | 208214063 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TM9Y060B12MP11 | 24,400 | $1,220 |
| No | 208214064 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TM9Y100C16MP11 | 24,600 | $1,230 |
| No | 208214123 | FRASER-JOHNSTON | HMH72B361 | XAHB36DXXN1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 208214114 | FRASER-JOHNSTON | HMH72B361 | XAHB36DXXN1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 207417066 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TPLC080B12MP13 | 25,000 | $1,250 |
| No | 207417062 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TM8V080B12MP12 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417030 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+TXV | TM8Y060A12MP11 | 24,800 | $1,240 |
| No | 207417026 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+TXV | TM8Y060A12MP11 | 24,800 | $1,240 |
| No | 207416506 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TM8Y080C16MP11 | 24,600 | $1,230 |
| No | 207417014 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TM8Y100C16MP11 | 24,600 | $1,230 |
| No | 208214097 | FRASER-JOHNSTON | HMH72B361 | XAHB36DXXN1+TXV | TM9E060A10MP12 | 24,200 | $1,210 |
| No | 208214122 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TMLE080C16MP11 | 24,400 | $1,220 |
| No | 208214096 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TM8E080C16MP11 | 24,400 | $1,220 |
| No | 208214127 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TMLE120C16MP11 | 24,600 | $1,230 |
| No | 208214117 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TM8E120C16MP11 | 24,600 | $1,230 |
| No | 207417054 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TPLC100C16MP13 | 25,200 | $1,260 |
| No | 207417050 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TPLC080C16MP13 | 25,200 | $1,260 |
| No | 207417046 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TMLV100C16MP12 | 25,200 | $1,260 |
| No | 207417042 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TM8V080C16MP12 | 25,200 | $1,260 |
| No | 207417038 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TM8V100C16MP12 | 25,200 | $1,260 |
| No | 208214068 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TM8Y080B12MP11 | 24,400 | $1,220 |
| No | 208214070 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TM8Y100C20MP11 | 24,200 | $1,210 |
| No | 208214069 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TM8Y120C20MP11 | 24,200 | $1,210 |
| No | 208502177 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+JMET16CS2N1+TXV | | 24,400 | $1,220 |
| No | 208614062 | FRASER-JOHNSTON | HMH72B361 | JHVTB36DBCC2N1 | | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208502641 | FRASER-JOHNSTON | HMH72B361 | JHVTB36DXXC2N1+TXV | | 25,200 | $1,260 |
| No | 208400383 | FRASER-JOHNSTON | HMH72B361 | XAHB36DXXN1+MVC12BN21+TXV | | 24,400 | $1,220 |
| No | 207417155 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TL8E080C16UH11 | 25,000 | $1,250 |
| No | 208214100 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 207416996 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 207416992 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 207416986 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 207416982 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 207416956 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TP9C080C16MP13 | 25,000 | $1,250 |
| No | 207416952 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TM9V080C16MP12 | 25,000 | $1,250 |
| No | 208214062 | FRASER-JOHNSTON | HMH72B361 | XAHB36DXXN1+TXV | TM9Y060B12MP11 | 23,800 | $1,190 |
| No | 207416922 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TM9Y100C16MP11 | 25,000 | $1,250 |
| No | 207416474 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+TXV | TM9E080B12MP12 | 25,200 | $1,260 |
| No | 207416470 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+TXV | TM9E080B12MP12 | 25,200 | $1,260 |
| No | 207417002 | FRASER-JOHNSTON | HMH72B361 | XAFA30DXXN1+TXV | TM9V040A10MP12 | 24,400 | $1,220 |
| No | 207416438 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 207416434 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 208214079 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TP9C100C20MP13 | 25,000 | $1,250 |
| No | 208214080 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TM9V100C20MP12 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208214060 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TM9Y080B12MP11 | 24,400 | $1,220 |
| No | 208214120 | FRASER-JOHNSTON | HMH72B361 | XAHB36DXXN1+TXV | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 208214094 | FRASER-JOHNSTON | HMH72B361 | XAHB36DXXN1+TXV | TM8E080B12MP11 | 24,600 | $1,230 |
| No | 207416536 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TMLE100C16MP11 | 25,000 | $1,250 |
| No | 207416532 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TM8E100C16MP11 | 25,000 | $1,250 |
| No | 208214088 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 208214111 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 207417022 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+TXV | TM8Y080B12MP11 | 25,000 | $1,250 |
| No | 207417018 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+TXV | TM8Y080B12MP11 | 25,000 | $1,250 |
| No | 207416502 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TM8Y100C20MP11 | 24,600 | $1,230 |
| No | 207416478 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 208214102 | FRASER-JOHNSTON | HMH72B361 | XAHC36DXXN1+TXV | TM9E080C16MP12 | 24,600 | $1,230 |
| No | 208214074 | FRASER-JOHNSTON | HMH72B361 | XAHB36DXXN1+TXV | TP9C060B12MP13 | 24,600 | $1,230 |
| No | 208214081 | FRASER-JOHNSTON | HMH72B361 | XAHB36DXXN1+TXV | TM9V060B12MP12 | 24,600 | $1,230 |
| No | 207416946 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TP9C100C16MP13 | 25,000 | $1,250 |
| No | 207416942 | FRASER-JOHNSTON | HMH72B361 | XAFC36DXXN1+TXV | TM9V100C16MP12 | 25,000 | $1,250 |
| No | 207416416 | FRASER-JOHNSTON | HMH72B361 | XAUB36DXXN1+TXV | TM9Y080B12MP11 | 25,000 | $1,250 |
| No | 207416412 | FRASER-JOHNSTON | HMH72B361 | XAFB36DXXN1+TXV | TM9Y080B12MP11 | 25,000 | $1,250 |
| No | 208214548 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+TXV | TL8E100C20UH11 | 35,800 | $1,790 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208214559 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+TXV | TMLE100C16MP11 | 36,000 | $1,800 |
| No | 208214553 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+TXV | TM8E100C16MP11 | 36,000 | $1,800 |
| No | 208214550 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+TXV | TM9E080C20MP12 | 36,600 | $1,830 |
| No | 208214540 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+TXV | TP9C100C20MP13 | 36,200 | $1,810 |
| No | 208214544 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+TXV | TM9V100C20MP12 | 36,200 | $1,810 |
| No | 208502191 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+JMET18DS2N1+TXV | | 35,800 | $1,790 |
| No | 208400423 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+MVC20DN21+TXV | | 36,800 | $1,840 |
| No | 208614099 | FRASER-JOHNSTON | HMH72B601 | JHETD60JBCS2N1 | | 36,400 | $1,820 |
| No | 208501715 | FRASER-JOHNSTON | HMH72B601 | JHETD60JXXS2N1+TXV | | 36,400 | $1,820 |
| No | 207434726 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+ME20DN21+TXV | | 37,200 | $1,860 |
| No | 208214556 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+TXV | TMLE080C16MP11 | 36,000 | $1,800 |
| No | 208214546 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+TXV | TM8E080C16MP11 | 36,000 | $1,800 |
| No | 208214560 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+TXV | TMLE120C16MP11 | 36,000 | $1,800 |
| No | 208214555 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+TXV | TM8E120C16MP11 | 36,000 | $1,800 |
| No | 208214551 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+TXV | TM9E120D20MP12 | 36,000 | $1,800 |
| No | 208214534 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+TXV | TM9Y100C20MP11 | 35,800 | $1,790 |
| No | 207416786 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TMLE100C20MP11 | 36,200 | $1,810 |
| No | 207416782 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TM8E100C20MP11 | 36,200 | $1,810 |
| No | 207416774 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TM8Y100C16MP11 | 36,600 | $1,830 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417346 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TM9E100C20MP12 | 37,000 | $1,850 |
| No | 207417316 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TP9C120D20MP13 | 37,400 | $1,870 |
| No | 207417312 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TM9V120D20MP12 | 37,400 | $1,870 |
| No | 208614096 | FRASER-JOHNSTON | HMH72B601 | JHVTD60JBCC2N1 | | 36,200 | $1,810 |
| No | 208501120 | FRASER-JOHNSTON | HMH72B601 | JHVTD60JXXC2N1+TXV | | 36,200 | $1,810 |
| No | 208400422 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+ME20DN21+TXV | | 36,600 | $1,830 |
| No | 208614097 | FRASER-JOHNSTON | HMH72B601 | XAFD60JBCN1+JMVT20DC2N1 | | 36,000 | $1,800 |
| No | 208500534 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+JMVT20DC2N1+TXV | | 36,000 | $1,800 |
| No | 207416822 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TL8E080C16UH11 | 36,600 | $1,830 |
| No | 207416802 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TMLE080C20MP11 | 36,400 | $1,820 |
| No | 207416798 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TM8E080C20MP11 | 36,400 | $1,820 |
| No | 207417336 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TP9C100C16MP13 | 36,800 | $1,840 |
| No | 207417332 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TM9V100C16MP12 | 36,800 | $1,840 |
| No | 208214547 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+TXV | TL9E100C20UH11 | 36,000 | $1,800 |
| No | 208214558 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+TXV | TMLE100C20MP11 | 35,600 | $1,780 |
| No | 208214554 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+TXV | TM8E100C20MP11 | 35,600 | $1,780 |
| No | 208214537 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+TXV | TM8Y080C16MP11 | 35,800 | $1,790 |
| No | 208214536 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+TXV | TM8Y100C16MP11 | 35,800 | $1,790 |
| No | 208214552 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+TXV | TM9E100C20MP12 | 36,400 | $1,820 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208214541 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+TXV | TP9C120D20MP13 | 36,200 | $1,810 |
| No | 208214543 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+TXV | TM9V120D20MP12 | 36,200 | $1,810 |
| No | 207416818 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TL8E100C20UH11 | 36,600 | $1,830 |
| No | 207417350 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TM9E080C20MP12 | 37,200 | $1,860 |
| No | 208614098 | FRASER-JOHNSTON | HMH72B601 | XAFD60JBCN1+JMET18DS2N1 | | 36,400 | $1,820 |
| No | 208500545 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+JMET18DS2N1+TXV | | 36,400 | $1,820 |
| No | 207416814 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TL9E100C20UH11 | 36,600 | $1,830 |
| No | 207416778 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TM8Y080C16MP11 | 36,600 | $1,830 |
| No | 207417326 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TP9C100C20MP13 | 36,800 | $1,840 |
| No | 207417322 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TM9V100C20MP12 | 36,800 | $1,840 |
| No | 207434725 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+MVC20DN21+TXV | | 37,200 | $1,860 |
| No | 208501113 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+JMVT20DC2N1+TXV | | 35,400 | $1,770 |
| No | 207416794 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TMLE100C16MP11 | 36,800 | $1,840 |
| No | 207416790 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TM8E100C16MP11 | 36,800 | $1,840 |
| No | 207416766 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TM8Y120C20MP11 | 36,400 | $1,820 |
| No | 207417304 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TM9Y120D20MP11 | 36,600 | $1,830 |
| No | 208214549 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+TXV | TL8E080C16UH11 | 36,000 | $1,800 |
| No | 207416810 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TMLE080C16MP11 | 36,800 | $1,840 |
| No | 207416806 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TM8E080C16MP11 | 36,800 | $1,840 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417381 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TMLE120C16MP11 | 36,600 | $1,830 |
| No | 207417377 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TM8E120C16MP11 | 36,600 | $1,830 |
| No | 207416770 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TM8Y100C20MP11 | 36,400 | $1,820 |
| No | 207417342 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TM9E120D20MP12 | 37,200 | $1,860 |
| No | 207417308 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TM9Y100C20MP11 | 36,600 | $1,830 |
| No | 208214557 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+TXV | TMLE080C20MP11 | 35,600 | $1,780 |
| No | 208214545 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+TXV | TM8E080C20MP11 | 35,600 | $1,780 |
| No | 207417370 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TPLC120C20MP13 | 37,400 | $1,870 |
| No | 207417366 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TPLC100C20MP13 | 37,400 | $1,870 |
| No | 207417362 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TMLV120C20MP12 | 37,400 | $1,870 |
| No | 207417358 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TM8V100C20MP12 | 37,400 | $1,870 |
| No | 207417354 | FRASER-JOHNSTON | HMH72B601 | XAFD60JXXN1+TXV | TM8V120C20MP12 | 37,400 | $1,870 |
| No | 208214535 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+TXV | TM8Y100C20MP11 | 35,600 | $1,780 |
| No | 208214538 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+TXV | TM8Y120C20MP11 | 35,600 | $1,780 |
| No | 208214539 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+TXV | TP9C100C16MP13 | 36,200 | $1,810 |
| No | 208214542 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+TXV | TM9V100C16MP12 | 36,200 | $1,810 |
| No | 208214533 | FRASER-JOHNSTON | HMH72B601 | XAHD60JXXN1+TXV | TM9Y120D20MP11 | 35,800 | $1,790 |
| No | 207434711 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+ME12CN21+TXV | | 29,200 | $1,460 |
| No | 208400408 | FRASER-JOHNSTON | HMH72B481 | XAHC60HXXN1+MVC12CN21+TXV | | 28,600 | $1,430 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208400411 | FRASER-JOHNSTON | HMH72B481 | XAHC60HXXN1+ME12CN21+TXV | | 28,600 | $1,430 |
| No | 207434709 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+MVC12CN21+TXV | | 28,800 | $1,440 |
| No | 207416762 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TL8E100C20UH11 | 29,800 | $1,490 |
| No | 208614082 | FRASER-JOHNSTON | HMH72B481 | JHETD48GBCS2N1 | | 29,600 | $1,480 |
| No | 208501091 | FRASER-JOHNSTON | HMH72B481 | JHETC60HXXS2N1+TXV | | 29,600 | $1,480 |
| No | 207434710 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+ME14DN21+TXV | | 30,000 | $1,500 |
| No | 207417300 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TL8E080C16UH11 | 29,200 | $1,460 |
| No | 207417533 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TMLE080C16MP11 | 30,200 | $1,510 |
| No | 207417529 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TM8E080C16MP11 | 30,200 | $1,510 |
| No | 207416730 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TPLC100C16MP13 | 29,600 | $1,480 |
| No | 207416726 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TPLC080C16MP13 | 29,600 | $1,480 |
| No | 207416722 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TMLV100C16MP12 | 29,600 | $1,480 |
| No | 207416714 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TM8V100C16MP12 | 29,600 | $1,480 |
| No | 207416892 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TP9C100C20MP13 | 31,000 | $1,550 |
| No | 207416888 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TM9V100C20MP12 | 31,000 | $1,550 |
| No | 207417207 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TM9Y100C16MP11 | 30,200 | $1,510 |
| No | 207416902 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TM8Y100C20MP11 | 29,800 | $1,490 |
| No | 207416898 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TM8Y120C20MP11 | 29,800 | $1,490 |
| No | 208400410 | FRASER-JOHNSTON | HMH72B481 | XAHD60JXXN1+ME14DN21+TXV | | 28,800 | $1,440 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207416910 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TL8E080C16UH11 | 30,200 | $1,510 |
| No | 208214409 | FRASER-JOHNSTON | HMH72B481 | XAHD60JXXN1+TXV | TMLE080C16MP11 | 29,600 | $1,480 |
| No | 208214390 | FRASER-JOHNSTON | HMH72B481 | XAHD60JXXN1+TXV | TM8E080C16MP11 | 29,600 | $1,480 |
| No | 207416914 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TM9Y100C16MP11 | 30,000 | $1,500 |
| No | 207417506 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TPLC120C20MP13 | 29,800 | $1,490 |
| No | 207417502 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TPLC100C20MP13 | 29,800 | $1,490 |
| No | 207417498 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TMLV120C20MP12 | 29,800 | $1,490 |
| No | 207417490 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TM8V120C20MP12 | 29,800 | $1,490 |
| No | 208614081 | FRASER-JOHNSTON | HMH72B481 | JHVTD60JBCC2N1 | | 29,800 | $1,490 |
| No | 208503459 | FRASER-JOHNSTON | HMH72B481 | JHVTD60JXXC2N1+TXV | | 29,800 | $1,490 |
| No | 207416758 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TMLE080C16MP11 | 30,000 | $1,500 |
| No | 207416754 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TM8E080C16MP11 | 30,000 | $1,500 |
| No | 207416718 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TM8V080C16MP12 | 29,600 | $1,480 |
| No | 208214389 | FRASER-JOHNSTON | HMH72B481 | XAHD60JXXN1+TXV | TPLC120C20MP13 | 28,800 | $1,440 |
| No | 208214386 | FRASER-JOHNSTON | HMH72B481 | XAHD60JXXN1+TXV | TPLC100C20MP13 | 28,800 | $1,440 |
| No | 208214403 | FRASER-JOHNSTON | HMH72B481 | XAHD60JXXN1+TXV | TMLV120C20MP12 | 28,800 | $1,440 |
| No | 208214402 | FRASER-JOHNSTON | HMH72B481 | XAHD60JXXN1+TXV | TM8V120C20MP12 | 28,800 | $1,440 |
| No | 208214376 | FRASER-JOHNSTON | HMH72B481 | XAHD60JXXN1+TXV | TP9C100C16MP13 | 30,400 | $1,520 |
| No | 208214380 | FRASER-JOHNSTON | HMH72B481 | XAHD60JXXN1+TXV | TM9V100C16MP12 | 30,400 | $1,520 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417203 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TM9Y120D20MP11 | 30,600 | $1,530 |
| No | 208214411 | FRASER-JOHNSTON | HMH72B481 | XAHD60JXXN1+TXV | TMLE120C16MP11 | 29,600 | $1,480 |
| No | 208214407 | FRASER-JOHNSTON | HMH72B481 | XAHD60JXXN1+TXV | TM8E120C16MP11 | 29,600 | $1,480 |
| No | 207417261 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TPLC120C20MP13 | 29,200 | $1,460 |
| No | 207417257 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TPLC100C20MP13 | 29,200 | $1,460 |
| No | 207417253 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TMLV120C20MP12 | 29,200 | $1,460 |
| No | 207417245 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TM8V120C20MP12 | 29,200 | $1,460 |
| No | 207416694 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TP9C100C16MP13 | 30,800 | $1,540 |
| No | 207416690 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TM9V100C16MP12 | 30,800 | $1,540 |
| No | 207416676 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TM9Y080C16MP11 | 30,200 | $1,510 |
| No | 208400409 | FRASER-JOHNSTON | HMH72B481 | XAHC60HXXN1+MVC16CN21+TXV | | 29,200 | $1,460 |
| No | 208614083 | FRASER-JOHNSTON | HMH72B481 | JHVTD42FBCC2N1 | | 29,800 | $1,490 |
| No | 208501158 | FRASER-JOHNSTON | HMH72B481 | JHVTC60HXXC2N1+TXV | | 29,800 | $1,490 |
| No | 207417292 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TL9E080C16UH11 | 29,600 | $1,480 |
| No | 208214399 | FRASER-JOHNSTON | HMH72B481 | XAHD60JXXN1+TXV | TM8V100C20MP12 | 29,200 | $1,460 |
| No | 208214362 | FRASER-JOHNSTON | HMH72B481 | XAHD60JXXN1+TXV | TM8Y080C16MP11 | 29,600 | $1,480 |
| No | 208214367 | FRASER-JOHNSTON | HMH72B481 | XAHD60JXXN1+TXV | TM8Y100C16MP11 | 29,600 | $1,480 |
| No | 207416704 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TP9C080C16MP13 | 30,600 | $1,530 |
| No | 207416700 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TM9V080C16MP12 | 30,600 | $1,530 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208214372 | FRASER-JOHNSTON | HMH72B481 | XAHD60JXXN1+TXV | TP9C120D20MP13 | 30,400 | $1,520 |
| No | 208214383 | FRASER-JOHNSTON | HMH72B481 | XAHD60JXXN1+TXV | TM9V120D20MP12 | 30,400 | $1,520 |
| No | 207417484 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TP9C100C16MP13 | 31,000 | $1,550 |
| No | 207417480 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TM9V100C16MP12 | 31,000 | $1,550 |
| No | 207434714 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+ME16CN21+TXV | | 30,400 | $1,520 |
| No | 208214391 | FRASER-JOHNSTON | HMH72B481 | XAHD60JXXN1+TXV | TL8E080C16UH11 | 29,600 | $1,480 |
| No | 207416750 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TMLE100C16MP11 | 30,000 | $1,500 |
| No | 207416746 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TM8E100C16MP11 | 30,000 | $1,500 |
| No | 207417284 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TPLC100C16MP13 | 29,400 | $1,470 |
| No | 207417280 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TPLC080C16MP13 | 29,400 | $1,470 |
| No | 207417276 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TMLV100C16MP12 | 29,400 | $1,470 |
| No | 207417272 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TM8V080C16MP12 | 29,400 | $1,470 |
| No | 207417268 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TM8V100C16MP12 | 29,400 | $1,470 |
| No | 207417225 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TM8Y100C20MP11 | 29,600 | $1,480 |
| No | 207417221 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TM8Y120C20MP11 | 29,600 | $1,480 |
| No | 207416684 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TP9C100C20MP13 | 31,000 | $1,550 |
| No | 207416680 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TM9V100C20MP12 | 31,000 | $1,550 |
| No | 208214357 | FRASER-JOHNSTON | HMH72B481 | XAHD60JXXN1+TXV | TM9Y120D20MP11 | 30,000 | $1,500 |
| No | 207417525 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TMLE100C16MP11 | 30,200 | $1,510 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417521 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TM8E100C16MP11 | 30,200 | $1,510 |
| No | 207434713 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+MVC14DN21+TXV | | 29,800 | $1,490 |
| No | 207416906 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TL8E100C20UH11 | 30,000 | $1,500 |
| No | 207434712 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+MVC16CN21+TXV | | 29,800 | $1,490 |
| No | 207417517 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TMLE120C16MP11 | 30,200 | $1,510 |
| No | 207417513 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TM8E120C16MP11 | 30,200 | $1,510 |
| No | 208614080 | FRASER-JOHNSTON | HMH72B481 | JHETD60JBCS2N1 | | 30,000 | $1,500 |
| No | 208503485 | FRASER-JOHNSTON | HMH72B481 | JHETD60JXXS2N1+TXV | | 30,000 | $1,500 |
| No | 208400406 | FRASER-JOHNSTON | HMH72B481 | XAHD60JXXN1+MVC14DN21+TXV | | 29,400 | $1,470 |
| No | 208214393 | FRASER-JOHNSTON | HMH72B481 | XAHD60JXXN1+TXV | TL8E100C20UH11 | 29,400 | $1,470 |
| No | 208214410 | FRASER-JOHNSTON | HMH72B481 | XAHD60JXXN1+TXV | TMLE100C16MP11 | 29,600 | $1,480 |
| No | 208214406 | FRASER-JOHNSTON | HMH72B481 | XAHD60JXXN1+TXV | TM8E100C16MP11 | 29,600 | $1,480 |
| No | 207417249 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TM8V100C20MP12 | 29,600 | $1,480 |
| No | 207417241 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TM8Y080C16MP11 | 29,800 | $1,490 |
| No | 207417237 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TM8Y100C16MP11 | 29,800 | $1,490 |
| No | 208214368 | FRASER-JOHNSTON | HMH72B481 | XAHD60JXXN1+TXV | TM8Y100C20MP11 | 29,200 | $1,460 |
| No | 208214365 | FRASER-JOHNSTON | HMH72B481 | XAHD60JXXN1+TXV | TM8Y120C20MP11 | 29,200 | $1,460 |
| No | 208214375 | FRASER-JOHNSTON | HMH72B481 | XAHD60JXXN1+TXV | TP9C100C20MP13 | 30,400 | $1,520 |
| No | 208214381 | FRASER-JOHNSTON | HMH72B481 | XAHD60JXXN1+TXV | TM9V100C20MP12 | 30,400 | $1,520 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207416742 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TMLE120C16MP11 | 30,000 | $1,500 |
| No | 207416738 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TM8E120C16MP11 | 30,000 | $1,500 |
| No | 207417494 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TM8V100C20MP12 | 29,800 | $1,490 |
| No | 207417233 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TM8Y080C16MP11 | 30,200 | $1,510 |
| No | 207417229 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TM8Y100C16MP11 | 30,200 | $1,510 |
| No | 207417215 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TP9C080C16MP13 | 30,600 | $1,530 |
| No | 207417211 | FRASER-JOHNSTON | HMH72B481 | XAFC60HXXN1+TXV | TM9V080C16MP12 | 30,600 | $1,530 |
| No | 207416882 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TP9C120D20MP13 | 30,800 | $1,540 |
| No | 207416878 | FRASER-JOHNSTON | HMH72B481 | XAFD60JXXN1+TXV | TM9V120D20MP12 | 30,800 | $1,540 |
| No | 9006287 | FRASER-JOHNSTON | TH16B6021 | AE60DX21+TXV | | 33,200 | $1,660 |
| No | 10309052 | FRASER-JOHNSTON | HL20B6021 | CM61DE4A1+MVC20DN21 | | 45,500 | $2,275 |
| No | 10525628 | FRASER-JOHNSTON | HL20B2421 | CM25BE1A1 | TM9V060B12MP12 | 21,200 | $1,060 |
| No | 10525627 | FRASER-JOHNSTON | HL20B2421 | CM25BE1A1 | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 10525630 | FRASER-JOHNSTON | HL20B2421 | CM25BE1A1 | TMLV080B12MP12 | 22,400 | $1,120 |
| No | 10525633 | FRASER-JOHNSTON | HL20B2421 | CM25BE1A1 | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 10525632 | FRASER-JOHNSTON | HL20B2421 | CM25BE1A1 | TP9C080B12MP13 | 22,400 | $1,120 |
| No | 10525629 | FRASER-JOHNSTON | HL20B2421 | CM25BE1A1 | TM9V080B12MP12 | 22,400 | $1,120 |
| No | 10525650 | FRASER-JOHNSTON | HL20B4821 | CM50CE3A1 | TM9V100C16MP12 | 44,000 | $2,200 |
| No | 10525657 | FRASER-JOHNSTON | HL20B4821 | CM50CE3A1 | TP9C100C16MP13 | 44,000 | $2,200 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201982914 | FRASER-JOHNSTON | HL20B2421 | AVV25BE121 | | 22,400 | $1,120 |
| No | 201982950 | FRASER-JOHNSTON | HL20B6021 | AVV61DE421 | | 46,000 | $2,300 |
| No | 10525631 | FRASER-JOHNSTON | HL20B2421 | CM25BE1A1 | TP9C060B12MP13 | 21,200 | $1,060 |
| No | 201982924 | FRASER-JOHNSTON | HL20B3621S | CM37BE2A1+CC | TM9V060B12MP12 | 31,600 | $1,580 |
| No | 201982932 | FRASER-JOHNSTON | HL20B3621S | CM37BE2A1+CC | TP9C060B12MP13 | 31,600 | $1,580 |
| No | 201982931 | FRASER-JOHNSTON | HL20B3621S | CM37BE2A1+CC | TM9V080B12MP12 | 31,000 | $1,550 |
| No | 201982944 | FRASER-JOHNSTON | HL20B3621S | CM37BE2A1+MVC12BN21+CC | | 30,800 | $1,540 |
| No | 201982939 | FRASER-JOHNSTON | HL20B3621S | CM37BE2A1+CC | TP9C080B12MP13 | 31,000 | $1,550 |
| No | 10309056 | FRASER-JOHNSTON | HL20B6021S | AVV61CE421+CC | | 46,000 | $2,300 |
| No | 10525665 | FRASER-JOHNSTON | HL20B6021S | CM61CE4A1+CC | TM8V100C20MP12 | 46,000 | $2,300 |
| No | 10525666 | FRASER-JOHNSTON | HL20B6021S | CM61CE4A1+CC | TM8V120C20MP12 | 46,000 | $2,300 |
| No | 10525667 | FRASER-JOHNSTON | HL20B6021S | CM61CE4A1+CC | TM9V100C20MP12 | 46,500 | $2,325 |
| No | 10525668 | FRASER-JOHNSTON | HL20B6021S | CM61CE4A1+CC | TMLV100C20MP12 | 46,000 | $2,300 |
| No | 10525669 | FRASER-JOHNSTON | HL20B6021S | CM61CE4A1+CC | TMLV120C20MP12 | 46,000 | $2,300 |
| No | 10525670 | FRASER-JOHNSTON | HL20B6021S | CM61CE4A1+CC | TP9C100C20MP13 | 46,500 | $2,325 |
| No | 10525671 | FRASER-JOHNSTON | HL20B6021S | CM61CE4A1+CC | TPLC100C20MP13 | 46,000 | $2,300 |
| No | 10525672 | FRASER-JOHNSTON | HL20B6021S | CM61CE4A1+CC | TPLC120C20MP13 | 46,000 | $2,300 |
| No | 10525673 | FRASER-JOHNSTON | HL20B6021S | CM61DE4A1+CC | TM9V120D20MP12 | 46,000 | $2,300 |
| No | 10525674 | FRASER-JOHNSTON | HL20B6021S | CM61DE4A1+CC | TP9C120D20MP13 | 46,000 | $2,300 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201982922 | FRASER-JOHNSTON | HL20B3621S | AVV37BE221+CC | | 31,000 | $1,550 |
| No | 205537303 | FRASER-JOHNSTON | TH16B3622 | CU36BXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203430831 | FRASER-JOHNSTON | TH16B3622 | CM36BBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205538525 | FRASER-JOHNSTON | TH16B3622 | CM36BXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203430825 | FRASER-JOHNSTON | TH16B3622 | CF36BBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205538517 | FRASER-JOHNSTON | TH16B3622 | CU36BXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203087061 | FRASER-JOHNSTON | TH16B3622 | CM36BBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205538509 | FRASER-JOHNSTON | TH16B3622 | CM36BXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203087045 | FRASER-JOHNSTON | TH16B3622 | CF36BBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205538491 | FRASER-JOHNSTON | TH16B3622 | CF36BXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205538483 | FRASER-JOHNSTON | TH16B3622 | CF36BXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205544336 | FRASER-JOHNSTON | TH16B3622 | CU36BXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 203088188 | FRASER-JOHNSTON | TH16B3622 | CM36BBCA1 | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205544328 | FRASER-JOHNSTON | TH16B3622 | CM36BXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 203088170 | FRASER-JOHNSTON | TH16B3622 | CF36BBCA1 | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205544317 | FRASER-JOHNSTON | TH16B3622 | CF36BXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205544309 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 203088134 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205544299 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205544289 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205544280 | FRASER-JOHNSTON | TH16B3622 | CF42BXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205544272 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TL9E080C16UH11 | 22,400 | $1,120 |
| No | 205544259 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TL9E080C16UH11 | 22,400 | $1,120 |
| No | 203087838 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205544249 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205544234 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205544222 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 203087820 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 203087784 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205544194 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205544183 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205544174 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205544164 | FRASER-JOHNSTON | TH16B3622 | CM36AXA1+TXV | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 205544157 | FRASER-JOHNSTON | TH16B3622 | CM36AXA1+TXV | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 205544153 | FRASER-JOHNSTON | TH16B3622 | CF36AXA1+TXV | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 205544149 | FRASER-JOHNSTON | TH16B3622 | CF36AXA1+TXV | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 206781239 | FRASER-JOHNSTON | TH16B3622 | CU36BXA1+TXV | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 203430991 | FRASER-JOHNSTON | TH16B3622 | CM36BBCA1 | TMLE060A12MP11 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203430985 | FRASER-JOHNSTON | TH16B3622 | CF36BBCA1 | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 206781235 | FRASER-JOHNSTON | TH16B3622 | CU36BXA1+TXV | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 206781243 | FRASER-JOHNSTON | TH16B3622 | CM36BXA1+TXV | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 203087614 | FRASER-JOHNSTON | TH16B3622 | CM36BBCA1 | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 206781231 | FRASER-JOHNSTON | TH16B3622 | CM36BXA1+TXV | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 203087595 | FRASER-JOHNSTON | TH16B3622 | CF36BBCA1 | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 206781223 | FRASER-JOHNSTON | TH16B3622 | CF36BXA1+TXV | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 206781227 | FRASER-JOHNSTON | TH16B3622 | CF36BXA1+TXV | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 205544145 | FRASER-JOHNSTON | TH16B3622 | CF42BXA1+TXV | TMLE060A12MP11 | 22,800 | $1,140 |
| No | 205544141 | FRASER-JOHNSTON | TH16B3622 | CF42BXA1+TXV | TM8E060A12MP11 | 22,800 | $1,140 |
| No | 206781219 | FRASER-JOHNSTON | TH16B3622 | CU36BXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 203430963 | FRASER-JOHNSTON | TH16B3622 | CM36BBCA1 | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 206781215 | FRASER-JOHNSTON | TH16B3622 | CM36BXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 206781211 | FRASER-JOHNSTON | TH16B3622 | CU36BXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 203087516 | FRASER-JOHNSTON | TH16B3622 | CM36BBCA1 | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 203430958 | FRASER-JOHNSTON | TH16B3622 | CF36BBCA1 | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 206781207 | FRASER-JOHNSTON | TH16B3622 | CM36BXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 203087499 | FRASER-JOHNSTON | TH16B3622 | CF36BBCA1 | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 206781195 | FRASER-JOHNSTON | TH16B3622 | CF36BXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781191 | FRASER-JOHNSTON | TH16B3622 | CF36BXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 206781187 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203430891 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 206781203 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 206781199 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 203087273 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 206781183 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 206781179 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 206781175 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205544137 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203430881 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205544213 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203430875 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205544203 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 203087235 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205544133 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 203087217 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205544117 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205544103 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781171 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 206781167 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 206781163 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 206781159 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205544093 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203430858 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205544129 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203430853 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205544085 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 203087154 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205544075 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 203087137 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205544054 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 206781155 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205544064 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203430792 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 206781151 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203430787 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 206781147 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203086929 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 206781143 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203086912 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 206781139 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 206781135 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205544042 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203430775 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205544031 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203430770 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205544017 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203086874 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205544004 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203086855 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205543962 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205543930 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205543948 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203430759 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205543993 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205543975 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203086814 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205543908 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205543895 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205543884 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205543875 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205543866 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 203430748 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 203430743 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205543852 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203086769 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205543842 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203086750 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205543819 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205543809 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 206781127 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206781123 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781119 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206781115 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781111 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203430665 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206781131 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 203430660 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206781107 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 203098234 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781103 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 203098226 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781099 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206781095 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 203430649 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206781091 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206781087 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 203098210 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781083 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781079 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781075 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206781071 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 205543791 | FRASER-JOHNSTON | TH16B3622 | CM36AXA1+TXV | TPLC060A12MP13 | 22,400 | $1,120 |
| No | 205543780 | FRASER-JOHNSTON | TH16B3622 | CM36AXA1+TXV | TMLV060A12MP12 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205543772 | FRASER-JOHNSTON | TH16B3622 | CM36AXA1+TXV | TM8V060A12MP12 | 22,400 | $1,120 |
| No | 205543742 | FRASER-JOHNSTON | TH16B3622 | CF36AXA1+TXV | TMLV060A12MP12 | 22,400 | $1,120 |
| No | 205543732 | FRASER-JOHNSTON | TH16B3622 | CF36AXA1+TXV | TM8V060A12MP12 | 22,400 | $1,120 |
| No | 205543756 | FRASER-JOHNSTON | TH16B3622 | CF36AXA1+TXV | TPLC060A12MP13 | 22,400 | $1,120 |
| No | 205543722 | FRASER-JOHNSTON | TH16B3622 | CM36AXA1+TXV | TM9E060A10MP12 | 22,600 | $1,130 |
| No | 205543710 | FRASER-JOHNSTON | TH16B3622 | CF36AXA1+TXV | TM9E060A10MP12 | 22,600 | $1,130 |
| No | 206781067 | FRASER-JOHNSTON | TH16B3622 | CF42BXA1+TXV | TM9E060B12MP12 | 22,200 | $1,110 |
| No | 205543701 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 203097864 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205543831 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 203097856 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 206781063 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205543691 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 203097840 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 206781059 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 203097832 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 206781055 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205543680 | FRASER-JOHNSTON | TH16B3622 | CU36BXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097816 | FRASER-JOHNSTON | TH16B3622 | CM36BBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205543671 | FRASER-JOHNSTON | TH16B3622 | CM36BXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097808 | FRASER-JOHNSTON | TH16B3622 | CF36BBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205543660 | FRASER-JOHNSTON | TH16B3622 | CF36BXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205543647 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 203097713 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 205543622 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 205543605 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 206781051 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 203097697 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 206781047 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 203097688 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 206781043 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 205543595 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 205543588 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 206781039 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 203097665 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 206781035 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 203097657 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 206781031 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205543580 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205543569 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 203097553 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205543560 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 206781027 | FRASER-JOHNSTON | TH16B3622 | CF42BXA1+TXV | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 203097456 | FRASER-JOHNSTON | TH16B3622 | AE36CX21+TXV | | 22,600 | $1,130 |
| No | 205543550 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+ME14DN21+TXV | | 22,000 | $1,100 |
| No | 205543542 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+ME14DN21+TXV | | 22,000 | $1,100 |
| No | 205543534 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205543515 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205543495 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TM9Y080C16MP11 | 22,600 | $1,130 |
| No | 203096962 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TM9Y080C16MP11 | 22,600 | $1,130 |
| No | 205543634 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TM9Y080C16MP11 | 22,600 | $1,130 |
| No | 205543464 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TM9Y080C16MP11 | 22,600 | $1,130 |
| No | 203096946 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TM9Y080C16MP11 | 22,600 | $1,130 |
| No | 203096915 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205543431 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205543419 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205543392 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205543377 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TM9Y120D20MP11 | 22,400 | $1,120 |
| No | 205543361 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TM9Y120D20MP11 | 22,400 | $1,120 |
| No | 205543327 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205543319 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205543308 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205543285 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205543272 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205543246 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205543233 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205543220 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205543196 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205543186 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203096748 | FRASER-JOHNSTON | TH16B3622 | AVC48CX21+TXV | | 22,400 | $1,120 |
| No | 203096700 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1+ME14DN21 | | 22,000 | $1,100 |
| No | 205543168 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+ME14DN21+TXV | | 22,000 | $1,100 |
| No | 205543160 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+ME14DN21+TXV | | 22,000 | $1,100 |
| No | 203096668 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1+MVC16CN21 | | 22,000 | $1,100 |
| No | 205543151 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+MVC16CN21+TXV | | 22,000 | $1,100 |
| No | 205543143 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+MVC16CN21+TXV | | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203096652 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1+MVC16CN21 | | 21,800 | $1,090 |
| No | 205543134 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+MVC16CN21+TXV | | 21,800 | $1,090 |
| No | 203096644 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1+MVC16CN21 | | 21,800 | $1,090 |
| No | 205543125 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+MVC16CN21+TXV | | 21,800 | $1,090 |
| No | 205543107 | FRASER-JOHNSTON | TH16B3622 | CU36BXA1+TXV | TPLC060A12MP13 | 22,200 | $1,110 |
| No | 203096541 | FRASER-JOHNSTON | TH16B3622 | CM36BBCA1 | TPLC060A12MP13 | 22,200 | $1,110 |
| No | 205543089 | FRASER-JOHNSTON | TH16B3622 | CM36BXA1+TXV | TPLC060A12MP13 | 22,200 | $1,110 |
| No | 203096512 | FRASER-JOHNSTON | TH16B3622 | CF36BBCA1 | TPLC060A12MP13 | 22,200 | $1,110 |
| No | 205543079 | FRASER-JOHNSTON | TH16B3622 | CU36BXA1+TXV | TMLV060A12MP12 | 22,200 | $1,110 |
| No | 203096533 | FRASER-JOHNSTON | TH16B3622 | CM36BBCA1 | TMLV060A12MP12 | 22,200 | $1,110 |
| No | 205543069 | FRASER-JOHNSTON | TH16B3622 | CM36BXA1+TXV | TMLV060A12MP12 | 22,200 | $1,110 |
| No | 203096504 | FRASER-JOHNSTON | TH16B3622 | CF36BBCA1 | TMLV060A12MP12 | 22,200 | $1,110 |
| No | 205543055 | FRASER-JOHNSTON | TH16B3622 | CU36BXA1+TXV | TM8V060A12MP12 | 22,200 | $1,110 |
| No | 203096525 | FRASER-JOHNSTON | TH16B3622 | CM36BBCA1 | TM8V060A12MP12 | 22,200 | $1,110 |
| No | 205543042 | FRASER-JOHNSTON | TH16B3622 | CM36BXA1+TXV | TM8V060A12MP12 | 22,200 | $1,110 |
| No | 203096496 | FRASER-JOHNSTON | TH16B3622 | CF36BBCA1 | TM8V060A12MP12 | 22,200 | $1,110 |
| No | 205542991 | FRASER-JOHNSTON | TH16B3622 | CF36BXA1+TXV | TMLV060A12MP12 | 22,200 | $1,110 |
| No | 205542980 | FRASER-JOHNSTON | TH16B3622 | CF36BXA1+TXV | TM8V060A12MP12 | 22,200 | $1,110 |
| No | 205543001 | FRASER-JOHNSTON | TH16B3622 | CF36BXA1+TXV | TPLC060A12MP13 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781019 | FRASER-JOHNSTON | TH16B3622 | CU36BXA1+TXV | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 203096153 | FRASER-JOHNSTON | TH16B3622 | CM36BBCA1 | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 206781015 | FRASER-JOHNSTON | TH16B3622 | CM36BXA1+TXV | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 203096133 | FRASER-JOHNSTON | TH16B3622 | CF36BBCA1 | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 206781011 | FRASER-JOHNSTON | TH16B3622 | CU36BXA1+TXV | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 203096145 | FRASER-JOHNSTON | TH16B3622 | CM36BBCA1 | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 206781007 | FRASER-JOHNSTON | TH16B3622 | CM36BXA1+TXV | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 203096125 | FRASER-JOHNSTON | TH16B3622 | CF36BBCA1 | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 206781001 | FRASER-JOHNSTON | TH16B3622 | CF36BXA1+TXV | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 206780997 | FRASER-JOHNSTON | TH16B3622 | CF36BXA1+TXV | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 205542963 | FRASER-JOHNSTON | TH16B3622 | CF42BXA1+TXV | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 203095799 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 205542954 | FRASER-JOHNSTON | TH16B3622 | CF42BXA1+TXV | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 205543017 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 203095791 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 205543029 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 205542942 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 205542927 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 205542908 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205542897 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 203095763 | FRASER-JOHNSTON | TH16B3622 | AVC36BX21+TXV | | 22,200 | $1,110 |
| No | 203095755 | FRASER-JOHNSTON | TH16B3622 | AVC36CX21+TXV | | 22,200 | $1,110 |
| No | 203095740 | FRASER-JOHNSTON | TH16B3622 | AVC48DX21+TXV | | 22,200 | $1,110 |
| No | 205542865 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203095333 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205542856 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203095276 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205542847 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 203095325 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205542839 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 203095269 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205542828 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203095316 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205542820 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203095261 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205542785 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205542770 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205542760 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203095300 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203095245 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203095292 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205542749 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203095237 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205542728 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205542719 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205542702 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205542672 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205542657 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 206780985 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203094997 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203094942 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 206780981 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 206780977 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 203094989 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 206780973 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 203094934 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 206780969 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203094981 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 206780965 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203094926 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 206780961 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203094965 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 206780957 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203094910 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 206780953 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203094957 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 206780949 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203094902 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 206780937 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 206780933 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 206780929 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 206780925 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 206780921 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203093763 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TPLC120C20MP13 | 22,200 | $1,110 |
| No | 206780915 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TPLC120C20MP13 | 22,200 | $1,110 |
| No | 206780911 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TPLC120C20MP13 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203093707 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TPLC120C20MP13 | 22,200 | $1,110 |
| No | 206780907 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TPLC100C20MP13 | 22,200 | $1,110 |
| No | 203093755 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TPLC100C20MP13 | 22,200 | $1,110 |
| No | 206780903 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TPLC100C20MP13 | 22,200 | $1,110 |
| No | 203093698 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TPLC100C20MP13 | 22,200 | $1,110 |
| No | 206780899 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TMLV120C20MP12 | 22,200 | $1,110 |
| No | 203093747 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TMLV120C20MP12 | 22,200 | $1,110 |
| No | 206780895 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TMLV120C20MP12 | 22,200 | $1,110 |
| No | 206780891 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TM8V100C20MP12 | 22,200 | $1,110 |
| No | 203093731 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TM8V100C20MP12 | 22,200 | $1,110 |
| No | 203093690 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TMLV120C20MP12 | 22,200 | $1,110 |
| No | 206780887 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TM8V100C20MP12 | 22,200 | $1,110 |
| No | 206780883 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TM8V120C20MP12 | 22,200 | $1,110 |
| No | 203093674 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TM8V100C20MP12 | 22,200 | $1,110 |
| No | 203093722 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TM8V120C20MP12 | 22,200 | $1,110 |
| No | 206780879 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TM8V120C20MP12 | 22,200 | $1,110 |
| No | 203093666 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TM8V120C20MP12 | 22,200 | $1,110 |
| No | 206780872 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TPLC120C20MP13 | 22,200 | $1,110 |
| No | 206780868 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TPLC100C20MP13 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780864 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TMLV120C20MP12 | 22,200 | $1,110 |
| No | 206780860 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TM8V100C20MP12 | 22,200 | $1,110 |
| No | 206780856 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TM8V120C20MP12 | 22,200 | $1,110 |
| No | 203093369 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205542611 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205542594 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 203093350 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205542578 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205542567 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 203093332 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205542551 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205542535 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 203093295 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205542485 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205542498 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 203093278 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205542301 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205542288 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205542262 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205542249 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205542239 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205542218 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205542214 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205542202 | FRASER-JOHNSTON | TH16B3622 | CM36AXA1+TXV | TM8Y060A12MP11 | 22,200 | $1,110 |
| No | 205542166 | FRASER-JOHNSTON | TH16B3622 | CF36AXA1+TXV | TM8Y060A12MP11 | 22,200 | $1,110 |
| No | 205542133 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 203092898 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205542478 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205542467 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205542454 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205542114 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 203092880 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205542107 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205542058 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 203092226 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205542313 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 203092120 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205542048 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203092209 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205542037 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203092103 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205541948 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205541938 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203091909 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205541882 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205541870 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 203091892 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205541859 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205541676 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205541847 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205541664 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 206780848 | FRASER-JOHNSTON | TH16B3622 | CU36BXA1+TXV | TM9Y080B12MP11 | 22,200 | $1,110 |
| No | 203808680 | FRASER-JOHNSTON | TH16B3622 | CM36BBCA1 | TM9Y080B12MP11 | 22,200 | $1,110 |
| No | 206780852 | FRASER-JOHNSTON | TH16B3622 | CM36BXA1+TXV | TM9Y080B12MP11 | 22,200 | $1,110 |
| No | 203808673 | FRASER-JOHNSTON | TH16B3622 | CF36BBCA1 | TM9Y080B12MP11 | 22,200 | $1,110 |
| No | 206780844 | FRASER-JOHNSTON | TH16B3622 | CF36BXA1+TXV | TM9Y080B12MP11 | 22,200 | $1,110 |
| No | 205541607 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205541595 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205541584 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205541572 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205541760 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205541742 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205541723 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 206780838 | FRASER-JOHNSTON | TH16B3622 | CU36BXA1+TXV | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 203091036 | FRASER-JOHNSTON | TH16B3622 | CM36BBCA1 | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 203090990 | FRASER-JOHNSTON | TH16B3622 | CF36BBCA1 | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 206780800 | FRASER-JOHNSTON | TH16B3622 | CU36BXA1+TXV | TM9V080B12MP12 | 22,200 | $1,110 |
| No | 206780804 | FRASER-JOHNSTON | TH16B3622 | CM36BXA1+TXV | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 203091016 | FRASER-JOHNSTON | TH16B3622 | CM36BBCA1 | TM9V080B12MP12 | 22,200 | $1,110 |
| No | 206780796 | FRASER-JOHNSTON | TH16B3622 | CM36BXA1+TXV | TM9V080B12MP12 | 22,200 | $1,110 |
| No | 206780790 | FRASER-JOHNSTON | TH16B3622 | CF36BXA1+TXV | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 206780786 | FRASER-JOHNSTON | TH16B3622 | CF36BXA1+TXV | TM9V080B12MP12 | 22,200 | $1,110 |
| No | 203090971 | FRASER-JOHNSTON | TH16B3622 | CF36BBCA1 | TM9V080B12MP12 | 22,200 | $1,110 |
| No | 205541545 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TP9C100C16MP13 | 22,000 | $1,100 |
| No | 203090625 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TP9C100C16MP13 | 22,000 | $1,100 |
| No | 205541532 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TP9C100C16MP13 | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205541521 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TM9V100C16MP12 | 22,000 | $1,100 |
| No | 203090609 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TM9V100C16MP12 | 22,000 | $1,100 |
| No | 205541510 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TM9V100C16MP12 | 22,000 | $1,100 |
| No | 205541492 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TP9C100C16MP13 | 22,000 | $1,100 |
| No | 205541481 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TM9V100C16MP12 | 22,000 | $1,100 |
| No | 205541456 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 203090401 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205541444 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 203090357 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205541432 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 203090382 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205541420 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 203090337 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205541404 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205541391 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205541374 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205541362 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205541346 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205541335 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205541321 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541309 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205541288 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541280 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205541256 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 203089078 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541245 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 203089031 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541235 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203089059 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205541224 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203089012 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205541207 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541197 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203088847 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541170 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541156 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 203088828 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205541131 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205541117 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205541099 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541081 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205144700 | FRASER-JOHNSTON | TH16B3622 | AE42CBC21 | | 22,400 | $1,120 |
| No | 203088406 | FRASER-JOHNSTON | TH16B3622 | AE42CX21+TXV | | 22,400 | $1,120 |
| No | 205537138 | FRASER-JOHNSTON | TH16B2421 | CU24AXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |
| No | 205537131 | FRASER-JOHNSTON | TH16B2421 | CM24ABAA1 | TL8E060A12UH11 | 15,200 | $760 |
| No | 205537123 | FRASER-JOHNSTON | TH16B2421 | CM24AXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |
| No | 205537116 | FRASER-JOHNSTON | TH16B2421 | CF24ABAA1 | TL8E060A12UH11 | 15,200 | $760 |
| No | 205537109 | FRASER-JOHNSTON | TH16B2421 | CF24AXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |
| No | 206782445 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 206782441 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 206782437 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 206782433 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 206782429 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 205085341 | FRASER-JOHNSTON | TH16B4821 | CM60CXA2+TXV | TL8E080C16UH11 | 27,800 | $1,390 |
| No | 205085348 | FRASER-JOHNSTON | TH16B4821 | CU60CXA2+TXV | TL8E080C16UH11 | 27,800 | $1,390 |
| No | 205085334 | FRASER-JOHNSTON | TH16B4821 | CF60CXA2+TXV | TL8E080C16UH11 | 27,800 | $1,390 |
| No | 206782473 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TL8E080C16UH11 | 29,600 | $1,480 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782469 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TL8E080C16UH11 | 29,600 | $1,480 |
| No | 205085312 | FRASER-JOHNSTON | TH16B4821 | CU60CXA2+TXV | TL8E100C20UH11 | 27,600 | $1,380 |
| No | 205085307 | FRASER-JOHNSTON | TH16B4821 | CM60CXA2+TXV | TL8E100C20UH11 | 27,600 | $1,380 |
| No | 205085301 | FRASER-JOHNSTON | TH16B4821 | CF60CXA2+TXV | TL8E100C20UH11 | 27,600 | $1,380 |
| No | 205085294 | FRASER-JOHNSTON | TH16B4821 | CU60DXA2+TXV | TL8E100C20UH11 | 27,800 | $1,390 |
| No | 205085288 | FRASER-JOHNSTON | TH16B4821 | CM60DXA2+TXV | TL8E100C20UH11 | 27,800 | $1,390 |
| No | 205085282 | FRASER-JOHNSTON | TH16B4821 | CF60DXA2+TXV | TL8E100C20UH11 | 27,800 | $1,390 |
| No | 205537100 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205537091 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205537082 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205537074 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205537065 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TL9E080C16UH11 | 29,600 | $1,480 |
| No | 205537056 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TL9E080C16UH11 | 29,600 | $1,480 |
| No | 205085246 | FRASER-JOHNSTON | TH16B4821 | CU60CXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205085240 | FRASER-JOHNSTON | TH16B4821 | CM60CXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205085235 | FRASER-JOHNSTON | TH16B4821 | CF60CXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205085229 | FRASER-JOHNSTON | TH16B4821 | CU60DXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205085223 | FRASER-JOHNSTON | TH16B4821 | CM60DXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205085218 | FRASER-JOHNSTON | TH16B4821 | CF60DXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205085147 | FRASER-JOHNSTON | TH16B4821 | CU60CXA2+TXV | TMLE080C20MP11 | 27,400 | $1,370 |
| No | 205085141 | FRASER-JOHNSTON | TH16B4821 | CM60CXA2+TXV | TMLE080C20MP11 | 27,400 | $1,370 |
| No | 205085135 | FRASER-JOHNSTON | TH16B4821 | CU60CXA2+TXV | TM8E080C20MP11 | 27,400 | $1,370 |
| No | 205085129 | FRASER-JOHNSTON | TH16B4821 | CM60CXA2+TXV | TM8E080C20MP11 | 27,400 | $1,370 |
| No | 205085124 | FRASER-JOHNSTON | TH16B4821 | CF60CXA2+TXV | TMLE080C20MP11 | 27,400 | $1,370 |
| No | 205085118 | FRASER-JOHNSTON | TH16B4821 | CF60CXA2+TXV | TM8E080C20MP11 | 27,400 | $1,370 |
| No | 205085108 | FRASER-JOHNSTON | TH16B4821 | CM60DXA2+TXV | TMLE080C20MP11 | 27,600 | $1,380 |
| No | 205085114 | FRASER-JOHNSTON | TH16B4821 | CU60DXA2+TXV | TMLE080C20MP11 | 27,600 | $1,380 |
| No | 205085103 | FRASER-JOHNSTON | TH16B4821 | CU60DXA2+TXV | TM8E080C20MP11 | 27,600 | $1,380 |
| No | 205085097 | FRASER-JOHNSTON | TH16B4821 | CM60DXA2+TXV | TM8E080C20MP11 | 27,600 | $1,380 |
| No | 205085092 | FRASER-JOHNSTON | TH16B4821 | CF60DXA2+TXV | TMLE080C20MP11 | 27,600 | $1,380 |
| No | 205085086 | FRASER-JOHNSTON | TH16B4821 | CF60DXA2+TXV | TM8E080C20MP11 | 27,600 | $1,380 |
| No | 206782425 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 203431139 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 206782421 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 206782417 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 203431128 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 203431134 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 206782413 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203431123 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 206782409 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 206782405 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 205084915 | FRASER-JOHNSTON | TH16B4821 | CU60DXA2+TXV | TMLE120C16MP11 | 27,800 | $1,390 |
| No | 205084909 | FRASER-JOHNSTON | TH16B4821 | CM60DXA2+TXV | TMLE120C16MP11 | 27,800 | $1,390 |
| No | 205084904 | FRASER-JOHNSTON | TH16B4821 | CU60DXA2+TXV | TM8E120C16MP11 | 27,800 | $1,390 |
| No | 205084899 | FRASER-JOHNSTON | TH16B4821 | CM60DXA2+TXV | TM8E120C16MP11 | 27,800 | $1,390 |
| No | 205084893 | FRASER-JOHNSTON | TH16B4821 | CF60DXA2+TXV | TMLE120C16MP11 | 27,800 | $1,390 |
| No | 205084888 | FRASER-JOHNSTON | TH16B4821 | CF60DXA2+TXV | TM8E120C16MP11 | 27,800 | $1,390 |
| No | 206782401 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TMLE120C16MP11 | 30,400 | $1,520 |
| No | 206782397 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TM8E120C16MP11 | 30,400 | $1,520 |
| No | 206782393 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TMLE120C16MP11 | 30,400 | $1,520 |
| No | 206782389 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TM8E120C16MP11 | 30,400 | $1,520 |
| No | 205084814 | FRASER-JOHNSTON | TH16B4821 | CU60DXA2+TXV | TMLE130D20MP11 | 27,800 | $1,390 |
| No | 205084808 | FRASER-JOHNSTON | TH16B4821 | CM60DXA2+TXV | TMLE130D20MP11 | 27,800 | $1,390 |
| No | 205084802 | FRASER-JOHNSTON | TH16B4821 | CU60DXA2+TXV | TM8E130D20MP11 | 27,800 | $1,390 |
| No | 205084796 | FRASER-JOHNSTON | TH16B4821 | CM60DXA2+TXV | TM8E130D20MP11 | 27,800 | $1,390 |
| No | 205084791 | FRASER-JOHNSTON | TH16B4821 | CF60DXA2+TXV | TMLE130D20MP11 | 27,800 | $1,390 |
| No | 205084785 | FRASER-JOHNSTON | TH16B4821 | CF60DXA2+TXV | TM8E130D20MP11 | 27,800 | $1,390 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205536889 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TM9E080B12MP12 | 28,600 | $1,430 |
| No | 205536880 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TM9E080B12MP12 | 28,600 | $1,430 |
| No | 205536872 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TM9E080B12MP12 | 28,600 | $1,430 |
| No | 205536864 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TM9E080B12MP12 | 28,600 | $1,430 |
| No | 205536855 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TM9E080B12MP12 | 28,600 | $1,430 |
| No | 206782385 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 206782377 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 206782373 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 206782381 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 206782369 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 205536842 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TM9E080C16MP12 | 28,800 | $1,440 |
| No | 205536835 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TM9E080C16MP12 | 28,800 | $1,440 |
| No | 205536827 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205536819 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205536803 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205536794 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205084675 | FRASER-JOHNSTON | TH16B4821 | CU60DXA2+TXV | TM9E100C20MP12 | 27,400 | $1,370 |
| No | 205536812 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205084671 | FRASER-JOHNSTON | TH16B4821 | CM60DXA2+TXV | TM9E100C20MP12 | 27,400 | $1,370 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205084667 | FRASER-JOHNSTON | TH16B4821 | CF60DXA2+TXV | TM9E100C20MP12 | 27,400 | $1,370 |
| No | 205084662 | FRASER-JOHNSTON | TH16B4821 | CU60DXA2+TXV | TM9E120D20MP12 | 27,800 | $1,390 |
| No | 205084658 | FRASER-JOHNSTON | TH16B4821 | CM60DXA2+TXV | TM9E120D20MP12 | 27,800 | $1,390 |
| No | 205084653 | FRASER-JOHNSTON | TH16B4821 | CF60DXA2+TXV | TM9E120D20MP12 | 27,800 | $1,390 |
| No | 206783056 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TL8E080C16UH11 | 33,000 | $1,650 |
| No | 206783052 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TL8E080C16UH11 | 33,000 | $1,650 |
| No | 205536785 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TL9E080C16UH11 | 32,600 | $1,630 |
| No | 206783044 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TMLE080C16MP11 | 33,000 | $1,650 |
| No | 206783040 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TM8E080C16MP11 | 33,000 | $1,650 |
| No | 205536776 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TL9E080C16UH11 | 32,600 | $1,630 |
| No | 206783036 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TMLE080C16MP11 | 33,000 | $1,650 |
| No | 206783032 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TM8E080C16MP11 | 33,000 | $1,650 |
| No | 206783028 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TMLE100C16MP11 | 33,000 | $1,650 |
| No | 206783024 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TM8E100C16MP11 | 33,000 | $1,650 |
| No | 206783020 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TMLE100C16MP11 | 33,000 | $1,650 |
| No | 206783016 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TM8E100C16MP11 | 33,000 | $1,650 |
| No | 206783012 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TMLE100C20MP11 | 32,600 | $1,630 |
| No | 206783008 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TM8E100C20MP11 | 32,600 | $1,630 |
| No | 206783004 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TMLE100C20MP11 | 32,600 | $1,630 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206783000 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TM8E100C20MP11 | 32,600 | $1,630 |
| No | 206782980 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TMLE120C20MP11 | 32,600 | $1,630 |
| No | 206782972 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TMLE120C20MP11 | 32,600 | $1,630 |
| No | 206782976 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TM8E120C20MP11 | 32,600 | $1,630 |
| No | 206782968 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TM8E120C20MP11 | 32,600 | $1,630 |
| No | 205536767 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TMLE130D20MP11 | 32,800 | $1,640 |
| No | 205536758 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TM8E130D20MP11 | 32,800 | $1,640 |
| No | 205536750 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TMLE130D20MP11 | 32,800 | $1,640 |
| No | 205536741 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TM8E130D20MP11 | 32,800 | $1,640 |
| No | 206779795 | FRASER-JOHNSTON | TH16B2421 | CM24BBAA1+MVC12BN21 | | 14,900 | $745 |
| No | 206779791 | FRASER-JOHNSTON | TH16B2421 | CM24BXA1+MVC12BN21+TXV | | 14,900 | $745 |
| No | 202101790 | FRASER-JOHNSTON | TH16B2421 | CF24BBAA1+MVC12BN21 | | 14,900 | $745 |
| No | 206779787 | FRASER-JOHNSTON | TH16B2421 | CF24BXA1+MVC12BN21+TXV | | 14,900 | $745 |
| No | 206780121 | FRASER-JOHNSTON | TH16B2421 | CM30BBAA1+MVC12BN21 | | 15,300 | $765 |
| No | 206780117 | FRASER-JOHNSTON | TH16B2421 | CM30BXA1+MVC12BN21+TXV | | 15,300 | $765 |
| No | 206780113 | FRASER-JOHNSTON | TH16B2421 | CF30BBAA1+MVC12BN21 | | 15,300 | $765 |
| No | 206780109 | FRASER-JOHNSTON | TH16B2421 | CF30BXA1+MVC12BN21+TXV | | 15,300 | $765 |
| No | 206779803 | FRASER-JOHNSTON | TH16B2421 | CM30CXA1+MVC16CN21+TXV | | 14,800 | $740 |
| No | 206779799 | FRASER-JOHNSTON | TH16B2421 | CF30CXA1+MVC16CN21+TXV | | 14,800 | $740 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780089 | FRASER-JOHNSTON | TH16B2421 | CM36CXA1+MVC16CN21+TXV | | 15,300 | $765 |
| No | 206780085 | FRASER-JOHNSTON | TH16B2421 | CF36CXA1+MVC16CN21+TXV | | 15,300 | $765 |
| No | 206779755 | FRASER-JOHNSTON | TH16B2421 | CU24AXA1+TXV | TPLC060A12MP13 | 15,000 | $750 |
| No | 206779751 | FRASER-JOHNSTON | TH16B2421 | CM24ABAA1 | TPLC060A12MP13 | 15,000 | $750 |
| No | 206779747 | FRASER-JOHNSTON | TH16B2421 | CM24AXA1+TXV | TPLC060A12MP13 | 15,000 | $750 |
| No | 202102012 | FRASER-JOHNSTON | TH16B2421 | CF24ABAA1 | TPLC060A12MP13 | 15,000 | $750 |
| No | 206779767 | FRASER-JOHNSTON | TH16B2421 | CU24AXA1+TXV | TMLV060A12MP12 | 15,000 | $750 |
| No | 206779763 | FRASER-JOHNSTON | TH16B2421 | CM24ABAA1 | TMLV060A12MP12 | 15,000 | $750 |
| No | 206779759 | FRASER-JOHNSTON | TH16B2421 | CM24AXA1+TXV | TMLV060A12MP12 | 15,000 | $750 |
| No | 202102008 | FRASER-JOHNSTON | TH16B2421 | CF24ABAA1 | TMLV060A12MP12 | 15,000 | $750 |
| No | 206779743 | FRASER-JOHNSTON | TH16B2421 | CU24AXA1+TXV | TM8V060A12MP12 | 15,000 | $750 |
| No | 206779739 | FRASER-JOHNSTON | TH16B2421 | CM24ABAA1 | TM8V060A12MP12 | 15,000 | $750 |
| No | 206779735 | FRASER-JOHNSTON | TH16B2421 | CM24AXA1+TXV | TM8V060A12MP12 | 15,000 | $750 |
| No | 202102005 | FRASER-JOHNSTON | TH16B2421 | CF24ABAA1 | TM8V060A12MP12 | 15,000 | $750 |
| No | 206779731 | FRASER-JOHNSTON | TH16B2421 | CF24AXA1+TXV | TPLC060A12MP13 | 15,000 | $750 |
| No | 206779727 | FRASER-JOHNSTON | TH16B2421 | CF24AXA1+TXV | TMLV060A12MP12 | 15,000 | $750 |
| No | 206779723 | FRASER-JOHNSTON | TH16B2421 | CF24AXA1+TXV | TM8V060A12MP12 | 15,000 | $750 |
| No | 206780643 | FRASER-JOHNSTON | TH16B2421 | CU30BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780639 | FRASER-JOHNSTON | TH16B2421 | CM30BBAA1 | TPLC080B12MP13 | 15,000 | $750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780635 | FRASER-JOHNSTON | TH16B2421 | CM30BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780631 | FRASER-JOHNSTON | TH16B2421 | CF30BBAA1 | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780627 | FRASER-JOHNSTON | TH16B2421 | CU30BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780623 | FRASER-JOHNSTON | TH16B2421 | CM30BBAA1 | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780619 | FRASER-JOHNSTON | TH16B2421 | CM30BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780615 | FRASER-JOHNSTON | TH16B2421 | CF30BBAA1 | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780610 | FRASER-JOHNSTON | TH16B2421 | CF30BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780606 | FRASER-JOHNSTON | TH16B2421 | CF30BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780169 | FRASER-JOHNSTON | TH16B2421 | CU24BXA1+TXV | TM9Y060B12MP11 | 14,900 | $745 |
| No | 206780165 | FRASER-JOHNSTON | TH16B2421 | CM24BBAA1 | TM9Y060B12MP11 | 14,900 | $745 |
| No | 206780161 | FRASER-JOHNSTON | TH16B2421 | CM24BXA1+TXV | TM9Y060B12MP11 | 14,900 | $745 |
| No | 202143775 | FRASER-JOHNSTON | TH16B2421 | CF24BBAA1 | TM9Y060B12MP11 | 14,900 | $745 |
| No | 206780177 | FRASER-JOHNSTON | TH16B2421 | CF24BXA1+TXV | TM9Y060B12MP11 | 14,900 | $745 |
| No | 206780157 | FRASER-JOHNSTON | TH16B2421 | CU24AXA1+TXV | TM9V040A10MP12 | 15,200 | $760 |
| No | 206780153 | FRASER-JOHNSTON | TH16B2421 | CM24ABAA1 | TM9V040A10MP12 | 15,200 | $760 |
| No | 202143767 | FRASER-JOHNSTON | TH16B2421 | CF24ABAA1 | TM9V040A10MP12 | 15,200 | $760 |
| No | 206780173 | FRASER-JOHNSTON | TH16B2421 | CF24AXA1+TXV | TM9V040A10MP12 | 15,200 | $760 |
| No | 206780149 | FRASER-JOHNSTON | TH16B2421 | CM24AXA1+TXV | TM9V040A10MP12 | 15,200 | $760 |
| No | 206779983 | FRASER-JOHNSTON | TH16B2421 | CU36BXA1+TXV | TP9C060B12MP13 | 14,900 | $745 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206779979 | FRASER-JOHNSTON | TH16B2421 | CM36BBAA1 | TP9C060B12MP13 | 14,900 | $745 |
| No | 206779971 | FRASER-JOHNSTON | TH16B2421 | CF36BBAA1 | TP9C060B12MP13 | 14,900 | $745 |
| No | 206779975 | FRASER-JOHNSTON | TH16B2421 | CM36BXA1+TXV | TP9C060B12MP13 | 14,900 | $745 |
| No | 206779963 | FRASER-JOHNSTON | TH16B2421 | CM36BBAA1 | TM9V060B12MP12 | 14,900 | $745 |
| No | 206779945 | FRASER-JOHNSTON | TH16B2421 | CF36BXA1+TXV | TM9V060B12MP12 | 14,900 | $745 |
| No | 206782621 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TP9C100C20MP13 | 33,000 | $1,650 |
| No | 206779959 | FRASER-JOHNSTON | TH16B2421 | CM36BXA1+TXV | TM9V060B12MP12 | 14,900 | $745 |
| No | 206779955 | FRASER-JOHNSTON | TH16B2421 | CF36BBAA1 | TM9V060B12MP12 | 14,900 | $745 |
| No | 206779949 | FRASER-JOHNSTON | TH16B2421 | CF36BXA1+TXV | TP9C060B12MP13 | 14,900 | $745 |
| No | 206782617 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TM9V100C20MP12 | 33,000 | $1,650 |
| No | 206779967 | FRASER-JOHNSTON | TH16B2421 | CU36BXA1+TXV | TM9V060B12MP12 | 14,900 | $745 |
| No | 206782611 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TP9C100C20MP13 | 33,000 | $1,650 |
| No | 206782607 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TM9V100C20MP12 | 33,000 | $1,650 |
| No | 205539554 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TP9C120D20MP13 | 32,600 | $1,630 |
| No | 205539548 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TM9V120D20MP12 | 32,600 | $1,630 |
| No | 205539536 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TP9C120D20MP13 | 32,600 | $1,630 |
| No | 9036585 | FRASER-JOHNSTON | TH16B4821 | AVC48CX21+TXV | | 27,600 | $1,380 |
| No | 206781531 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1+MVC16CN21 | | 28,000 | $1,400 |
| No | 206781527 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+MVC16CN21+TXV | | 28,000 | $1,400 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205539527 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TM9V120D20MP12 | 32,600 | $1,630 |
| No | 202100054 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1+MVC16CN21 | | 28,000 | $1,400 |
| No | 206781773 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+MVC16CN21+TXV | | 28,000 | $1,400 |
| No | 206782362 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TPLC080B12MP13 | 28,200 | $1,410 |
| No | 206782358 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TPLC080B12MP13 | 28,200 | $1,410 |
| No | 206782354 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TPLC080B12MP13 | 28,200 | $1,410 |
| No | 202100737 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TPLC080B12MP13 | 28,200 | $1,410 |
| No | 206782350 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TM8V080B12MP12 | 28,200 | $1,410 |
| No | 206782346 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TM8V080B12MP12 | 28,200 | $1,410 |
| No | 206782342 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TM8V080B12MP12 | 28,200 | $1,410 |
| No | 202100656 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TM8V080B12MP12 | 28,200 | $1,410 |
| No | 206782337 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TPLC080B12MP13 | 28,200 | $1,410 |
| No | 206782333 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TM8V080B12MP12 | 28,200 | $1,410 |
| No | 206782317 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782313 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782309 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 202100745 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782301 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782305 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782297 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 202100738 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782293 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782289 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782285 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 202100705 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782281 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782273 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 202100659 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782277 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782269 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782265 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782261 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 202100664 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782167 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782159 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782163 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782155 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782151 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782135 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782131 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782127 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782123 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782119 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782115 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782111 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782107 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782103 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782099 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782095 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782091 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782087 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782083 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782079 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782071 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782067 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782063 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782059 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782055 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782042 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TPLC120C20MP13 | 28,200 | $1,410 |
| No | 206782038 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TPLC120C20MP13 | 28,200 | $1,410 |
| No | 206782034 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TPLC120C20MP13 | 28,200 | $1,410 |
| No | 206782030 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TPLC100C20MP13 | 28,200 | $1,410 |
| No | 206782026 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TPLC100C20MP13 | 28,200 | $1,410 |
| No | 206782022 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TPLC100C20MP13 | 28,200 | $1,410 |
| No | 206782018 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TMLV120C20MP12 | 28,200 | $1,410 |
| No | 206782014 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TMLV120C20MP12 | 28,200 | $1,410 |
| No | 206782010 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TMLV120C20MP12 | 28,200 | $1,410 |
| No | 206782006 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TM8V100C20MP12 | 28,200 | $1,410 |
| No | 206782002 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TM8V100C20MP12 | 28,200 | $1,410 |
| No | 206781998 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TM8V100C20MP12 | 28,200 | $1,410 |
| No | 206781994 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TM8V120C20MP12 | 28,200 | $1,410 |
| No | 206781990 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TM8V120C20MP12 | 28,200 | $1,410 |
| No | 206781986 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TM8V120C20MP12 | 28,200 | $1,410 |
| No | 206781979 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TPLC120C20MP13 | 28,200 | $1,410 |
| No | 206781975 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TPLC100C20MP13 | 28,200 | $1,410 |
| No | 206781971 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TMLV120C20MP12 | 28,200 | $1,410 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781967 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TM8V100C20MP12 | 28,200 | $1,410 |
| No | 206781963 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TM8V120C20MP12 | 28,200 | $1,410 |
| No | 206781956 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TPLC120C20MP13 | 28,600 | $1,430 |
| No | 206781952 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TPLC100C20MP13 | 28,600 | $1,430 |
| No | 206781948 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TMLV120C20MP12 | 28,600 | $1,430 |
| No | 206781944 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TM8V100C20MP12 | 28,600 | $1,430 |
| No | 206781940 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TM8V120C20MP12 | 28,600 | $1,430 |
| No | 206781933 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TPLC120C20MP13 | 28,600 | $1,430 |
| No | 206781929 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TPLC100C20MP13 | 28,600 | $1,430 |
| No | 206781925 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TMLV120C20MP12 | 28,600 | $1,430 |
| No | 206781921 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TM8V100C20MP12 | 28,600 | $1,430 |
| No | 206781917 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TM8V120C20MP12 | 28,600 | $1,430 |
| No | 206781341 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TP9C060B12MP13 | 28,400 | $1,420 |
| No | 206781337 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TP9C060B12MP13 | 28,400 | $1,420 |
| No | 206781333 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TP9C060B12MP13 | 28,400 | $1,420 |
| No | 202100716 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TP9C060B12MP13 | 28,400 | $1,420 |
| No | 206781329 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TM9V060B12MP12 | 28,400 | $1,420 |
| No | 206781325 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TM9V060B12MP12 | 28,400 | $1,420 |
| No | 206781321 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TM9V060B12MP12 | 28,400 | $1,420 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202100676 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TM9V060B12MP12 | 28,400 | $1,420 |
| No | 206781311 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TP9C060B12MP13 | 28,400 | $1,420 |
| No | 206781307 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TM9V060B12MP12 | 28,400 | $1,420 |
| No | 206782247 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TP9C080B12MP13 | 28,200 | $1,410 |
| No | 206782243 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TP9C080B12MP13 | 28,200 | $1,410 |
| No | 206782239 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TP9C080B12MP13 | 28,200 | $1,410 |
| No | 202100719 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TP9C080B12MP13 | 28,200 | $1,410 |
| No | 206782235 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TM9V080B12MP12 | 28,200 | $1,410 |
| No | 206782231 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TM9V080B12MP12 | 28,200 | $1,410 |
| No | 206782227 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TM9V080B12MP12 | 28,200 | $1,410 |
| No | 202100681 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TM9V080B12MP12 | 28,200 | $1,410 |
| No | 206782209 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TP9C080B12MP13 | 28,200 | $1,410 |
| No | 206782205 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TM9V080B12MP12 | 28,200 | $1,410 |
| No | 206782223 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206782215 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206782219 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206782195 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 202100724 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206782191 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TM9V080C16MP12 | 28,200 | $1,410 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782187 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 202100682 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206781883 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781879 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206781869 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781865 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781861 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781857 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206781853 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206781849 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206781839 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206781843 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781833 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TP9C080C16MP13 | 29,800 | $1,490 |
| No | 206781829 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TM9V080C16MP12 | 29,800 | $1,490 |
| No | 206781823 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TP9C080C16MP13 | 29,800 | $1,490 |
| No | 206781819 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TM9V080C16MP12 | 29,800 | $1,490 |
| No | 206782183 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206782179 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206782175 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202100728 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781809 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206781805 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206781801 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206781755 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 202100689 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206781751 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206781741 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781737 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781733 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781729 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206781725 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206781721 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206781715 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781711 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206782507 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TP9C100C20MP13 | 28,200 | $1,410 |
| No | 206782503 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TP9C100C20MP13 | 28,200 | $1,410 |
| No | 206782499 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TP9C100C20MP13 | 28,200 | $1,410 |
| No | 206782495 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TM9V100C20MP12 | 28,200 | $1,410 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782491 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TM9V100C20MP12 | 28,200 | $1,410 |
| No | 206782487 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TM9V100C20MP12 | 28,200 | $1,410 |
| No | 206782481 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TP9C100C20MP13 | 28,200 | $1,410 |
| No | 206782477 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TM9V100C20MP12 | 28,200 | $1,410 |
| No | 206782463 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TP9C120D20MP13 | 29,400 | $1,470 |
| No | 206782459 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TM9V120D20MP12 | 29,400 | $1,470 |
| No | 206782453 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TP9C120D20MP13 | 29,400 | $1,470 |
| No | 206782449 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TM9V120D20MP12 | 29,400 | $1,470 |
| No | 205536123 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TP9C120D20MP13 | 28,400 | $1,420 |
| No | 205536115 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TP9C120D20MP13 | 28,400 | $1,420 |
| No | 205536106 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TP9C120D20MP13 | 28,400 | $1,420 |
| No | 205536097 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TM9V120D20MP12 | 28,400 | $1,420 |
| No | 205536090 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TM9V120D20MP12 | 28,400 | $1,420 |
| No | 205536081 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TM9V120D20MP12 | 28,400 | $1,420 |
| No | 205536068 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TP9C120D20MP13 | 28,400 | $1,420 |
| No | 205536059 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TM9V120D20MP12 | 28,400 | $1,420 |
| No | 206780289 | FRASER-JOHNSTON | TH16B2421 | CU24BXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |
| No | 206780285 | FRASER-JOHNSTON | TH16B2421 | CM24BBAA1 | TL8E060A12UH11 | 15,200 | $760 |
| No | 206780281 | FRASER-JOHNSTON | TH16B2421 | CM24BXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780277 | FRASER-JOHNSTON | TH16B2421 | CF24BBAA1 | TL8E060A12UH11 | 15,200 | $760 |
| No | 206780273 | FRASER-JOHNSTON | TH16B2421 | CF24BXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |
| No | 205541001 | FRASER-JOHNSTON | TH16B2421 | CM36BBAA1 | TL8E060A12UH11 | 15,100 | $755 |
| No | 205541013 | FRASER-JOHNSTON | TH16B2421 | CU36BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205540977 | FRASER-JOHNSTON | TH16B2421 | CF36BBAA1 | TL8E060A12UH11 | 15,100 | $755 |
| No | 205540964 | FRASER-JOHNSTON | TH16B2421 | CF36BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205540949 | FRASER-JOHNSTON | TH16B2421 | CU24BXA1+TXV | TL9E060B12UH11 | 15,300 | $765 |
| No | 205540990 | FRASER-JOHNSTON | TH16B2421 | CM36BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205540936 | FRASER-JOHNSTON | TH16B2421 | CM24BBAA1 | TL9E060B12UH11 | 15,300 | $765 |
| No | 205540925 | FRASER-JOHNSTON | TH16B2421 | CM24BXA1+TXV | TL9E060B12UH11 | 15,300 | $765 |
| No | 205540912 | FRASER-JOHNSTON | TH16B2421 | CF24BBAA1 | TL9E060B12UH11 | 15,300 | $765 |
| No | 205540898 | FRASER-JOHNSTON | TH16B2421 | CF24BXA1+TXV | TL9E060B12UH11 | 15,300 | $765 |
| No | 206780269 | FRASER-JOHNSTON | TH16B2421 | CU36CXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 206780265 | FRASER-JOHNSTON | TH16B2421 | CM36CXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 206780261 | FRASER-JOHNSTON | TH16B2421 | CF36CXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205540887 | FRASER-JOHNSTON | TH16B2421 | CU30BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 203429769 | FRASER-JOHNSTON | TH16B2421 | CM30BBAA1 | TMLE040A12MP11 | 15,100 | $755 |
| No | 205541144 | FRASER-JOHNSTON | TH16B2421 | CM30BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 203429758 | FRASER-JOHNSTON | TH16B2421 | CF30BBAA1 | TMLE040A12MP11 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205540877 | FRASER-JOHNSTON | TH16B2421 | CU30BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 203429763 | FRASER-JOHNSTON | TH16B2421 | CM30BBAA1 | TM8E040A12MP11 | 15,100 | $755 |
| No | 205540866 | FRASER-JOHNSTON | TH16B2421 | CM30BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 203429752 | FRASER-JOHNSTON | TH16B2421 | CF30BBAA1 | TM8E040A12MP11 | 15,100 | $755 |
| No | 205540853 | FRASER-JOHNSTON | TH16B2421 | CF30BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 205540842 | FRASER-JOHNSTON | TH16B2421 | CF30BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 206780237 | FRASER-JOHNSTON | TH16B2421 | CM36AXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 206780233 | FRASER-JOHNSTON | TH16B2421 | CM36AXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 206780229 | FRASER-JOHNSTON | TH16B2421 | CF36AXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 206780225 | FRASER-JOHNSTON | TH16B2421 | CF36AXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 206780221 | FRASER-JOHNSTON | TH16B2421 | CU36BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 203429725 | FRASER-JOHNSTON | TH16B2421 | CM36BBAA1 | TMLE040A12MP11 | 15,100 | $755 |
| No | 206780217 | FRASER-JOHNSTON | TH16B2421 | CM36BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 203429714 | FRASER-JOHNSTON | TH16B2421 | CF36BBAA1 | TMLE040A12MP11 | 15,100 | $755 |
| No | 206780213 | FRASER-JOHNSTON | TH16B2421 | CU36BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 206780209 | FRASER-JOHNSTON | TH16B2421 | CM36BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 203429708 | FRASER-JOHNSTON | TH16B2421 | CF36BBAA1 | TM8E040A12MP11 | 15,100 | $755 |
| No | 203429719 | FRASER-JOHNSTON | TH16B2421 | CM36BBAA1 | TM8E040A12MP11 | 15,100 | $755 |
| No | 206780205 | FRASER-JOHNSTON | TH16B2421 | CF36BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780201 | FRASER-JOHNSTON | TH16B2421 | CF36BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 205550182 | FRASER-JOHNSTON | TH16B2421 | CM30CXA1+TXV | TMLE100B12MP11 | 15,200 | $760 |
| No | 205550178 | FRASER-JOHNSTON | TH16B2421 | CM30CXA1+TXV | TM8E100B12MP11 | 15,200 | $760 |
| No | 205550174 | FRASER-JOHNSTON | TH16B2421 | CF30CXA1+TXV | TMLE100B12MP11 | 15,200 | $760 |
| No | 205550170 | FRASER-JOHNSTON | TH16B2421 | CF30CXA1+TXV | TM8E100B12MP11 | 15,200 | $760 |
| No | 206373349 | FRASER-JOHNSTON | TH16B2421 | CU24AXA1+TXV | TM9E026A08MP12 | 15,000 | $750 |
| No | 206373347 | FRASER-JOHNSTON | TH16B2421 | CM24AXA1+TXV | TM9E026A08MP12 | 15,000 | $750 |
| No | 206373348 | FRASER-JOHNSTON | TH16B2421 | CM24ABAA1 | TM9E026A08MP12 | 15,000 | $750 |
| No | 206373346 | FRASER-JOHNSTON | TH16B2421 | CF24ABAA1 | TM9E026A08MP12 | 15,000 | $750 |
| No | 206373345 | FRASER-JOHNSTON | TH16B2421 | CF24AXA1+TXV | TM9E026A08MP12 | 15,000 | $750 |
| No | 206373344 | FRASER-JOHNSTON | TH16B2421 | CU30BXA1+TXV | TM9E026A08MP12 | 15,400 | $770 |
| No | 206373343 | FRASER-JOHNSTON | TH16B2421 | CM30BBAA1 | TM9E026A08MP12 | 15,400 | $770 |
| No | 206373342 | FRASER-JOHNSTON | TH16B2421 | CM30BXA1+TXV | TM9E026A08MP12 | 15,400 | $770 |
| No | 206373341 | FRASER-JOHNSTON | TH16B2421 | CF30BBAA1 | TM9E026A08MP12 | 15,400 | $770 |
| No | 206373340 | FRASER-JOHNSTON | TH16B2421 | CF30BXA1+TXV | TM9E026A08MP12 | 15,400 | $770 |
| No | 206780197 | FRASER-JOHNSTON | TH16B2421 | CU24AXA1+TXV | TM9E040A10MP12 | 15,300 | $765 |
| No | 206780193 | FRASER-JOHNSTON | TH16B2421 | CM24ABAA1 | TM9E040A10MP12 | 15,300 | $765 |
| No | 206780189 | FRASER-JOHNSTON | TH16B2421 | CM24AXA1+TXV | TM9E040A10MP12 | 15,300 | $765 |
| No | 206780185 | FRASER-JOHNSTON | TH16B2421 | CF24ABAA1 | TM9E040A10MP12 | 15,300 | $765 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780181 | FRASER-JOHNSTON | TH16B2421 | CF24AXA1+TXV | TM9E040A10MP12 | 15,300 | $765 |
| No | 205074258 | FRASER-JOHNSTON | TH16B2421 | CF30ABAA1 | TM9E040A10MP12 | 15,200 | $760 |
| No | 205074498 | FRASER-JOHNSTON | TH16B2421 | CM30AXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205074492 | FRASER-JOHNSTON | TH16B2421 | CF30AXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540831 | FRASER-JOHNSTON | TH16B2421 | CM36AXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540818 | FRASER-JOHNSTON | TH16B2421 | CF36AXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540807 | FRASER-JOHNSTON | TH16B2421 | CU36BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540793 | FRASER-JOHNSTON | TH16B2421 | CM36BBAA1 | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540781 | FRASER-JOHNSTON | TH16B2421 | CM36BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540773 | FRASER-JOHNSTON | TH16B2421 | CF36BBAA1 | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540748 | FRASER-JOHNSTON | TH16B2421 | CU24BXA1+TXV | TM9E060A10MP12 | 15,300 | $765 |
| No | 205540758 | FRASER-JOHNSTON | TH16B2421 | CF36BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540731 | FRASER-JOHNSTON | TH16B2421 | CM24BBAA1 | TM9E060A10MP12 | 15,300 | $765 |
| No | 205540716 | FRASER-JOHNSTON | TH16B2421 | CM24BXA1+TXV | TM9E060A10MP12 | 15,300 | $765 |
| No | 205540704 | FRASER-JOHNSTON | TH16B2421 | CF24BBAA1 | TM9E060A10MP12 | 15,300 | $765 |
| No | 205540690 | FRASER-JOHNSTON | TH16B2421 | CF24BXA1+TXV | TM9E060A10MP12 | 15,300 | $765 |
| No | 205074486 | FRASER-JOHNSTON | TH16B2421 | CM30AXA1+TXV | TM9E060A10MP12 | 15,200 | $760 |
| No | 205074245 | FRASER-JOHNSTON | TH16B2421 | CF30ABAA1 | TM9E060A10MP12 | 15,200 | $760 |
| No | 205074480 | FRASER-JOHNSTON | TH16B2421 | CF30AXA1+TXV | TM9E060A10MP12 | 15,200 | $760 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205540485 | FRASER-JOHNSTON | TH16B2421 | CU36BXA1+TXV | TM9E060A10MP12 | 15,200 | $760 |
| No | 205540471 | FRASER-JOHNSTON | TH16B2421 | CM36BBAA1 | TM9E060A10MP12 | 15,200 | $760 |
| No | 205540456 | FRASER-JOHNSTON | TH16B2421 | CM36BXA1+TXV | TM9E060A10MP12 | 15,200 | $760 |
| No | 205540440 | FRASER-JOHNSTON | TH16B2421 | CF36BBAA1 | TM9E060A10MP12 | 15,200 | $760 |
| No | 205540427 | FRASER-JOHNSTON | TH16B2421 | CF36BXA1+TXV | TM9E060A10MP12 | 15,200 | $760 |
| No | 202763640 | FRASER-JOHNSTON | TH16B4821 | AVC60CX22+TXV | | 28,200 | $1,410 |
| No | 202143943 | FRASER-JOHNSTON | TH16B4821 | AE48DX21+TXV | | 28,200 | $1,410 |
| No | 206781251 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+ME14DN21+TXV | | 29,000 | $1,450 |
| No | 202143939 | FRASER-JOHNSTON | TH16B4821 | AE48DBC21 | | 28,200 | $1,410 |
| No | 206781247 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+ME14DN21+TXV | | 29,000 | $1,450 |
| No | 205540169 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205540156 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205540138 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 202143987 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205540641 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205540614 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205540602 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205540591 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205540543 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782573 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TM9Y080C16MP11 | 29,800 | $1,490 |
| No | 206782569 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TM9Y080C16MP11 | 29,800 | $1,490 |
| No | 9060450 | FRASER-JOHNSTON | TH16B2421 | AE30BX21+TXV | | 14,800 | $740 |
| No | 206838953 | FRASER-JOHNSTON | TH16B2421 | CM30BBAA1+ME08BN21 | | 15,100 | $755 |
| No | 206838949 | FRASER-JOHNSTON | TH16B2421 | CM30BXA1+ME08BN21+TXV | | 15,100 | $755 |
| No | 206838945 | FRASER-JOHNSTON | TH16B2421 | CF30BBAA1+ME08BN21 | | 15,100 | $755 |
| No | 206838941 | FRASER-JOHNSTON | TH16B2421 | CF30BXA1+ME08BN21+TXV | | 15,100 | $755 |
| No | 205536238 | FRASER-JOHNSTON | TH16B2421 | CU36BXA1+TXV | TM9Y060B12MP11 | 14,800 | $740 |
| No | 205536226 | FRASER-JOHNSTON | TH16B2421 | CM36BBAA1 | TM9Y060B12MP11 | 14,800 | $740 |
| No | 205536204 | FRASER-JOHNSTON | TH16B2421 | CF36BBAA1 | TM9Y060B12MP11 | 14,800 | $740 |
| No | 205536215 | FRASER-JOHNSTON | TH16B2421 | CM36BXA1+TXV | TM9Y060B12MP11 | 14,800 | $740 |
| No | 205536155 | FRASER-JOHNSTON | TH16B2421 | CF36BXA1+TXV | TM9Y060B12MP11 | 14,800 | $740 |
| No | 9060451 | FRASER-JOHNSTON | TH16B2421 | AVC24BX21+TXV | | 14,800 | $740 |
| No | 9060454 | FRASER-JOHNSTON | TH16B2421 | AVC36CX21+TXV | | 14,600 | $730 |
| No | 9036065 | FRASER-JOHNSTON | TH16B6021 | AVC60DX21+TXV | | 32,000 | $1,600 |
| No | 205539832 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TP9C080C16MP13 | 32,600 | $1,630 |
| No | 205539823 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TM9V080C16MP12 | 32,600 | $1,630 |
| No | 205539806 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TP9C080C16MP13 | 32,600 | $1,630 |
| No | 205539798 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TM9V080C16MP12 | 32,600 | $1,630 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 9036588 | FRASER-JOHNSTON | TH16B4821 | AVC60DX21+TXV | | 29,400 | $1,470 |
| No | 203429582 | FRASER-JOHNSTON | TH16B2421 | CM36BBAA1 | TMLE100B12MP11 | 15,000 | $750 |
| No | 205550166 | FRASER-JOHNSTON | TH16B2421 | CU36BXA1+TXV | TMLE100B12MP11 | 15,000 | $750 |
| No | 205550162 | FRASER-JOHNSTON | TH16B2421 | CM36BXA1+TXV | TMLE100B12MP11 | 15,000 | $750 |
| No | 203429571 | FRASER-JOHNSTON | TH16B2421 | CF36BBAA1 | TMLE100B12MP11 | 15,000 | $750 |
| No | 205550158 | FRASER-JOHNSTON | TH16B2421 | CU36BXA1+TXV | TM8E100B12MP11 | 15,000 | $750 |
| No | 203429577 | FRASER-JOHNSTON | TH16B2421 | CM36BBAA1 | TM8E100B12MP11 | 15,000 | $750 |
| No | 205550154 | FRASER-JOHNSTON | TH16B2421 | CM36BXA1+TXV | TM8E100B12MP11 | 15,000 | $750 |
| No | 203429566 | FRASER-JOHNSTON | TH16B2421 | CF36BBAA1 | TM8E100B12MP11 | 15,000 | $750 |
| No | 205550146 | FRASER-JOHNSTON | TH16B2421 | CF36BXA1+TXV | TMLE100B12MP11 | 15,000 | $750 |
| No | 205550142 | FRASER-JOHNSTON | TH16B2421 | CF36BXA1+TXV | TM8E100B12MP11 | 15,000 | $750 |
| No | 203064277 | FRASER-JOHNSTON | TH16B3622 | AE36BX21+TXV | | 22,200 | $1,110 |
| No | 205548017 | FRASER-JOHNSTON | TH16B2421 | CU30BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205548013 | FRASER-JOHNSTON | TH16B2421 | CM30BBAA1 | TL8E060A12UH11 | 15,100 | $755 |
| No | 205548009 | FRASER-JOHNSTON | TH16B2421 | CM30BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205548005 | FRASER-JOHNSTON | TH16B2421 | CF30BBAA1 | TL8E060A12UH11 | 15,100 | $755 |
| No | 205548001 | FRASER-JOHNSTON | TH16B2421 | CF30BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205547997 | FRASER-JOHNSTON | TH16B2421 | CU30BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547993 | FRASER-JOHNSTON | TH16B2421 | CM30BBAA1 | TL9E060B12UH11 | 15,200 | $760 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205547989 | FRASER-JOHNSTON | TH16B2421 | CM30BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547985 | FRASER-JOHNSTON | TH16B2421 | CF30BBAA1 | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547977 | FRASER-JOHNSTON | TH16B2421 | CM30CXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547973 | FRASER-JOHNSTON | TH16B2421 | CF30CXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547981 | FRASER-JOHNSTON | TH16B2421 | CF30BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547965 | FRASER-JOHNSTON | TH16B2421 | CM36BBAA1 | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547969 | FRASER-JOHNSTON | TH16B2421 | CU36BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547961 | FRASER-JOHNSTON | TH16B2421 | CM36BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547957 | FRASER-JOHNSTON | TH16B2421 | CF36BBAA1 | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547953 | FRASER-JOHNSTON | TH16B2421 | CF36BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 206780257 | FRASER-JOHNSTON | TH16B2421 | CU24AXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |
| No | 203429845 | FRASER-JOHNSTON | TH16B2421 | CM24ABAA1 | TMLE040A12MP11 | 15,200 | $760 |
| No | 206780465 | FRASER-JOHNSTON | TH16B2421 | CM24AXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |
| No | 203429856 | FRASER-JOHNSTON | TH16B2421 | CF24ABAA1 | TMLE040A12MP11 | 15,200 | $760 |
| No | 206780253 | FRASER-JOHNSTON | TH16B2421 | CU24AXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 203429840 | FRASER-JOHNSTON | TH16B2421 | CM24ABAA1 | TM8E040A12MP11 | 15,200 | $760 |
| No | 206780249 | FRASER-JOHNSTON | TH16B2421 | CM24AXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 203429851 | FRASER-JOHNSTON | TH16B2421 | CF24ABAA1 | TM8E040A12MP11 | 15,200 | $760 |
| No | 206780245 | FRASER-JOHNSTON | TH16B2421 | CF24AXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780241 | FRASER-JOHNSTON | TH16B2421 | CF24AXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 205547949 | FRASER-JOHNSTON | TH16B2421 | CU24BXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |
| No | 203429812 | FRASER-JOHNSTON | TH16B2421 | CM24BBAA1 | TMLE040A12MP11 | 15,200 | $760 |
| No | 205548243 | FRASER-JOHNSTON | TH16B2421 | CM24BXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |
| No | 203429823 | FRASER-JOHNSTON | TH16B2421 | CF24BBAA1 | TMLE040A12MP11 | 15,200 | $760 |
| No | 205548239 | FRASER-JOHNSTON | TH16B2421 | CU24BXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 203429807 | FRASER-JOHNSTON | TH16B2421 | CM24BBAA1 | TM8E040A12MP11 | 15,200 | $760 |
| No | 205548235 | FRASER-JOHNSTON | TH16B2421 | CM24BXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 203429818 | FRASER-JOHNSTON | TH16B2421 | CF24BBAA1 | TM8E040A12MP11 | 15,200 | $760 |
| No | 205548203 | FRASER-JOHNSTON | TH16B2421 | CF24BXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |
| No | 205548199 | FRASER-JOHNSTON | TH16B2421 | CF24BXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 203429790 | FRASER-JOHNSTON | TH16B2421 | CF30ABAA1 | TMLE040A12MP11 | 15,100 | $755 |
| No | 205074519 | FRASER-JOHNSTON | TH16B2421 | CM30AXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 205074271 | FRASER-JOHNSTON | TH16B2421 | CM30AXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 203429785 | FRASER-JOHNSTON | TH16B2421 | CF30ABAA1 | TM8E040A12MP11 | 15,100 | $755 |
| No | 205074266 | FRASER-JOHNSTON | TH16B2421 | CF30AXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 205074506 | FRASER-JOHNSTON | TH16B2421 | CF30AXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 205546117 | FRASER-JOHNSTON | TH16B2421 | CU24BXA1+TXV | TMLE080B12MP11 | 15,200 | $760 |
| No | 203429681 | FRASER-JOHNSTON | TH16B2421 | CM24BBAA1 | TMLE080B12MP11 | 15,200 | $760 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205546113 | FRASER-JOHNSTON | TH16B2421 | CM24BXA1+TXV | TMLE080B12MP11 | 15,200 | $760 |
| No | 203429692 | FRASER-JOHNSTON | TH16B2421 | CF24BBAA1 | TMLE080B12MP11 | 15,200 | $760 |
| No | 205546109 | FRASER-JOHNSTON | TH16B2421 | CU24BXA1+TXV | TM8E080B12MP11 | 15,200 | $760 |
| No | 203429675 | FRASER-JOHNSTON | TH16B2421 | CM24BBAA1 | TM8E080B12MP11 | 15,200 | $760 |
| No | 205546105 | FRASER-JOHNSTON | TH16B2421 | CM24BXA1+TXV | TM8E080B12MP11 | 15,200 | $760 |
| No | 203429686 | FRASER-JOHNSTON | TH16B2421 | CF24BBAA1 | TM8E080B12MP11 | 15,200 | $760 |
| No | 205546097 | FRASER-JOHNSTON | TH16B2421 | CF24BXA1+TXV | TMLE080B12MP11 | 15,200 | $760 |
| No | 205546093 | FRASER-JOHNSTON | TH16B2421 | CF24BXA1+TXV | TM8E080B12MP11 | 15,200 | $760 |
| No | 205546089 | FRASER-JOHNSTON | TH16B2421 | CU24BXA1+TXV | TMLE100B12MP11 | 15,100 | $755 |
| No | 203429648 | FRASER-JOHNSTON | TH16B2421 | CM24BBAA1 | TMLE100B12MP11 | 15,100 | $755 |
| No | 205546101 | FRASER-JOHNSTON | TH16B2421 | CM24BXA1+TXV | TMLE100B12MP11 | 15,100 | $755 |
| No | 203429659 | FRASER-JOHNSTON | TH16B2421 | CF24BBAA1 | TMLE100B12MP11 | 15,100 | $755 |
| No | 203429642 | FRASER-JOHNSTON | TH16B2421 | CM24BBAA1 | TM8E100B12MP11 | 15,100 | $755 |
| No | 205544362 | FRASER-JOHNSTON | TH16B2421 | CU24BXA1+TXV | TM8E100B12MP11 | 15,100 | $755 |
| No | 205544355 | FRASER-JOHNSTON | TH16B2421 | CM24BXA1+TXV | TM8E100B12MP11 | 15,100 | $755 |
| No | 203429653 | FRASER-JOHNSTON | TH16B2421 | CF24BBAA1 | TM8E100B12MP11 | 15,100 | $755 |
| No | 205544349 | FRASER-JOHNSTON | TH16B2421 | CF24BXA1+TXV | TMLE100B12MP11 | 15,100 | $755 |
| No | 205544342 | FRASER-JOHNSTON | TH16B2421 | CF24BXA1+TXV | TM8E100B12MP11 | 15,100 | $755 |
| No | 203429626 | FRASER-JOHNSTON | TH16B2421 | CM30BBAA1 | TMLE100B12MP11 | 15,200 | $760 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205550224 | FRASER-JOHNSTON | TH16B2421 | CM30BXA1+TXV | TMLE100B12MP11 | 15,200 | $760 |
| No | 205550202 | FRASER-JOHNSTON | TH16B2421 | CU30BXA1+TXV | TMLE100B12MP11 | 15,200 | $760 |
| No | 203429615 | FRASER-JOHNSTON | TH16B2421 | CF30BBAA1 | TMLE100B12MP11 | 15,200 | $760 |
| No | 205550198 | FRASER-JOHNSTON | TH16B2421 | CU30BXA1+TXV | TM8E100B12MP11 | 15,200 | $760 |
| No | 203429621 | FRASER-JOHNSTON | TH16B2421 | CM30BBAA1 | TM8E100B12MP11 | 15,200 | $760 |
| No | 205550194 | FRASER-JOHNSTON | TH16B2421 | CM30BXA1+TXV | TM8E100B12MP11 | 15,200 | $760 |
| No | 203429609 | FRASER-JOHNSTON | TH16B2421 | CF30BBAA1 | TM8E100B12MP11 | 15,200 | $760 |
| No | 205550190 | FRASER-JOHNSTON | TH16B2421 | CF30BXA1+TXV | TMLE100B12MP11 | 15,200 | $760 |
| No | 205550186 | FRASER-JOHNSTON | TH16B2421 | CF30BXA1+TXV | TM8E100B12MP11 | 15,200 | $760 |
| No | 206373339 | FRASER-JOHNSTON | TH16B2421 | CU24BXA1+TXV | TM9E026A08MP12 | 15,600 | $780 |
| No | 206373338 | FRASER-JOHNSTON | TH16B2421 | CM24BBAA1 | TM9E026A08MP12 | 15,600 | $780 |
| No | 206373337 | FRASER-JOHNSTON | TH16B2421 | CM24BXA1+TXV | TM9E026A08MP12 | 15,600 | $780 |
| No | 206373336 | FRASER-JOHNSTON | TH16B2421 | CF24BBAA1 | TM9E026A08MP12 | 15,600 | $780 |
| No | 206373335 | FRASER-JOHNSTON | TH16B2421 | CF24BXA1+TXV | TM9E026A08MP12 | 15,600 | $780 |
| No | 206373334 | FRASER-JOHNSTON | TH16B2421 | CM30AXA1+TXV | TM9E026A08MP12 | 14,800 | $740 |
| No | 206373333 | FRASER-JOHNSTON | TH16B2421 | CF30ABAA1 | TM9E026A08MP12 | 14,800 | $740 |
| No | 206373332 | FRASER-JOHNSTON | TH16B2421 | CF30AXA1+TXV | TM9E026A08MP12 | 14,800 | $740 |
| No | 206373331 | FRASER-JOHNSTON | TH16B2421 | CM36AXA1+TXV | TM9E026A08MP12 | 14,900 | $745 |
| No | 206373330 | FRASER-JOHNSTON | TH16B2421 | CF36AXA1+TXV | TM9E026A08MP12 | 14,900 | $745 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206373329 | FRASER-JOHNSTON | TH16B2421 | CU36BXA1+TXV | TM9E026A08MP12 | 14,900 | $745 |
| No | 206373328 | FRASER-JOHNSTON | TH16B2421 | CM36BBAA1 | TM9E026A08MP12 | 14,900 | $745 |
| No | 206373327 | FRASER-JOHNSTON | TH16B2421 | CM36BXA1+TXV | TM9E026A08MP12 | 14,900 | $745 |
| No | 206373326 | FRASER-JOHNSTON | TH16B2421 | CF36BBAA1 | TM9E026A08MP12 | 14,900 | $745 |
| No | 206373325 | FRASER-JOHNSTON | TH16B2421 | CF36BXA1+TXV | TM9E026A08MP12 | 14,900 | $745 |
| No | 205548195 | FRASER-JOHNSTON | TH16B2421 | CU24BXA1+TXV | TM9E040A10MP12 | 15,400 | $770 |
| No | 205548191 | FRASER-JOHNSTON | TH16B2421 | CM24BBAA1 | TM9E040A10MP12 | 15,400 | $770 |
| No | 205548187 | FRASER-JOHNSTON | TH16B2421 | CM24BXA1+TXV | TM9E040A10MP12 | 15,400 | $770 |
| No | 205548183 | FRASER-JOHNSTON | TH16B2421 | CF24BBAA1 | TM9E040A10MP12 | 15,400 | $770 |
| No | 205548179 | FRASER-JOHNSTON | TH16B2421 | CF24BXA1+TXV | TM9E040A10MP12 | 15,400 | $770 |
| No | 205548175 | FRASER-JOHNSTON | TH16B2421 | CU30BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205548171 | FRASER-JOHNSTON | TH16B2421 | CM30BBAA1 | TM9E040A10MP12 | 15,200 | $760 |
| No | 205548167 | FRASER-JOHNSTON | TH16B2421 | CM30BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205548163 | FRASER-JOHNSTON | TH16B2421 | CF30BBAA1 | TM9E040A10MP12 | 15,200 | $760 |
| No | 205548159 | FRASER-JOHNSTON | TH16B2421 | CF30BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205548155 | FRASER-JOHNSTON | TH16B2421 | CU24AXA1+TXV | TM9E060A10MP12 | 15,400 | $770 |
| No | 205548151 | FRASER-JOHNSTON | TH16B2421 | CM24ABAA1 | TM9E060A10MP12 | 15,400 | $770 |
| No | 205548147 | FRASER-JOHNSTON | TH16B2421 | CM24AXA1+TXV | TM9E060A10MP12 | 15,400 | $770 |
| No | 205548143 | FRASER-JOHNSTON | TH16B2421 | CF24ABAA1 | TM9E060A10MP12 | 15,400 | $770 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205548139 | FRASER-JOHNSTON | TH16B2421 | CF24AXA1+TXV | TM9E060A10MP12 | 15,400 | $770 |
| No | 205548135 | FRASER-JOHNSTON | TH16B2421 | CU30BXA1+TXV | TM9E060A10MP12 | 15,100 | $755 |
| No | 205548131 | FRASER-JOHNSTON | TH16B2421 | CM30BBAA1 | TM9E060A10MP12 | 15,100 | $755 |
| No | 205548127 | FRASER-JOHNSTON | TH16B2421 | CM30BXA1+TXV | TM9E060A10MP12 | 15,100 | $755 |
| No | 205548123 | FRASER-JOHNSTON | TH16B2421 | CF30BBAA1 | TM9E060A10MP12 | 15,100 | $755 |
| No | 205548119 | FRASER-JOHNSTON | TH16B2421 | CF30BXA1+TXV | TM9E060A10MP12 | 15,100 | $755 |
| No | 205548115 | FRASER-JOHNSTON | TH16B2421 | CM36AXA1+TXV | TM9E060A10MP12 | 15,100 | $755 |
| No | 205548111 | FRASER-JOHNSTON | TH16B2421 | CF36AXA1+TXV | TM9E060A10MP12 | 15,100 | $755 |
| No | 206779783 | FRASER-JOHNSTON | TH16B2421 | CM36BBAA1+ME08BN21 | | 15,000 | $750 |
| No | 206779779 | FRASER-JOHNSTON | TH16B2421 | CM36BXA1+ME08BN21+TXV | | 15,000 | $750 |
| No | 206779771 | FRASER-JOHNSTON | TH16B2421 | CF36BXA1+ME08BN21+TXV | | 15,000 | $750 |
| No | 206779775 | FRASER-JOHNSTON | TH16B2421 | CF36BBAA1+ME08BN21 | | 15,000 | $750 |
| No | 9060452 | FRASER-JOHNSTON | TH16B2421 | AVC30BX21+TXV | | 15,100 | $755 |
| No | 9060453 | FRASER-JOHNSTON | TH16B2421 | AVC36BX21+TXV | | 15,000 | $750 |
| No | 205547845 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+MVC20DN21+TXV | | 32,600 | $1,630 |
| No | 205547849 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+MVC20DN21+TXV | | 32,600 | $1,630 |
| No | 205547837 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TPLC120C20MP13 | 32,400 | $1,620 |
| No | 205547833 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TPLC100C20MP13 | 32,400 | $1,620 |
| No | 205547829 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TMLV120C20MP12 | 32,400 | $1,620 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205547821 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TM8V100C20MP12 | 32,400 | $1,620 |
| No | 205547817 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TM8V120C20MP12 | 32,400 | $1,620 |
| No | 205547809 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TPLC120C20MP13 | 32,400 | $1,620 |
| No | 205547805 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TPLC100C20MP13 | 32,400 | $1,620 |
| No | 205547801 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TMLV120C20MP12 | 32,400 | $1,620 |
| No | 205547793 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TM8V100C20MP12 | 32,400 | $1,620 |
| No | 205547789 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TM8V120C20MP12 | 32,400 | $1,620 |
| No | 203431216 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205547627 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205547623 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 203431211 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 205547573 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 205547569 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 205547565 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205547561 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 9854442 | FRASER-JOHNSTON | TH16B4821 | AE48CBC21 | | 28,400 | $1,420 |
| No | 9006282 | FRASER-JOHNSTON | TH16B4821 | AE48CX21+TXV | | 28,400 | $1,420 |
| No | 9854437 | FRASER-JOHNSTON | TH16B2421 | AE24BBA21 | | 15,100 | $755 |
| No | 9006272 | FRASER-JOHNSTON | TH16B2421 | AE24BX21+TXV | | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205550138 | FRASER-JOHNSTON | TH16B3622 | CM36AXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 205550134 | FRASER-JOHNSTON | TH16B3622 | CF36AXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 205550130 | FRASER-JOHNSTON | TH16B3622 | CU36BXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 203088284 | FRASER-JOHNSTON | TH16B3622 | CM36BBCA1 | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 205550150 | FRASER-JOHNSTON | TH16B3622 | CM36BXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 203088266 | FRASER-JOHNSTON | TH16B3622 | CF36BBCA1 | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 205550122 | FRASER-JOHNSTON | TH16B3622 | CF42BXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 205550126 | FRASER-JOHNSTON | TH16B3622 | CF36BXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 205550118 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 203088059 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205550114 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 203088040 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205550110 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205550106 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TL9E060B12UH11 | 22,400 | $1,120 |
| No | 203088002 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TL9E060B12UH11 | 22,400 | $1,120 |
| No | 205550102 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TL9E060B12UH11 | 22,400 | $1,120 |
| No | 203087984 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TL9E060B12UH11 | 22,400 | $1,120 |
| No | 205550098 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TL9E060B12UH11 | 22,400 | $1,120 |
| No | 205550094 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TL9E080C16UH11 | 22,600 | $1,130 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203087947 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TL9E080C16UH11 | 22,600 | $1,130 |
| No | 205550090 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TL9E080C16UH11 | 22,600 | $1,130 |
| No | 205550086 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TL9E080C16UH11 | 22,600 | $1,130 |
| No | 205550082 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TL9E080C16UH11 | 22,800 | $1,140 |
| No | 203087910 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TL9E080C16UH11 | 22,800 | $1,140 |
| No | 205550078 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TL9E080C16UH11 | 22,800 | $1,140 |
| No | 203087889 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TL9E080C16UH11 | 22,800 | $1,140 |
| No | 205550062 | FRASER-JOHNSTON | TH16B3622 | CM36AXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205550066 | FRASER-JOHNSTON | TH16B3622 | CM36AXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205550070 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TL9E080C16UH11 | 22,800 | $1,140 |
| No | 205550058 | FRASER-JOHNSTON | TH16B3622 | CF36AXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205550054 | FRASER-JOHNSTON | TH16B3622 | CF36AXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205550050 | FRASER-JOHNSTON | TH16B3622 | CU36BXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 203431024 | FRASER-JOHNSTON | TH16B3622 | CM36BBCA1 | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205550074 | FRASER-JOHNSTON | TH16B3622 | CM36BXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 203431018 | FRASER-JOHNSTON | TH16B3622 | CF36BBCA1 | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205550046 | FRASER-JOHNSTON | TH16B3622 | CU36BXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 203087728 | FRASER-JOHNSTON | TH16B3622 | CM36BBCA1 | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 203087708 | FRASER-JOHNSTON | TH16B3622 | CF36BBCA1 | TM8E040A12MP11 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205550042 | FRASER-JOHNSTON | TH16B3622 | CM36BXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205550038 | FRASER-JOHNSTON | TH16B3622 | CF36BXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205550034 | FRASER-JOHNSTON | TH16B3622 | CF36BXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205550030 | FRASER-JOHNSTON | TH16B3622 | CF42BXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205550025 | FRASER-JOHNSTON | TH16B3622 | CF42BXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205550019 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 203430947 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205550015 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205550011 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 203087463 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205550003 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205549999 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205549995 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205549991 | FRASER-JOHNSTON | TH16B3622 | CF42BXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205549987 | FRASER-JOHNSTON | TH16B3622 | CF42BXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205549983 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 203430925 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205550007 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 203430919 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TMLE080B12MP11 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549979 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 203087386 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205549975 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 203087369 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205549971 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 206780766 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TMLE080B12MP11 | 22,200 | $1,110 |
| No | 203430908 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TMLE080B12MP11 | 22,200 | $1,110 |
| No | 205549967 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 206780762 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TMLE080B12MP11 | 22,200 | $1,110 |
| No | 203430903 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TMLE080B12MP11 | 22,200 | $1,110 |
| No | 206780758 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TM8E080B12MP11 | 22,200 | $1,110 |
| No | 203087332 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TM8E080B12MP11 | 22,200 | $1,110 |
| No | 206780754 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TM8E080B12MP11 | 22,200 | $1,110 |
| No | 203087312 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TM8E080B12MP11 | 22,200 | $1,110 |
| No | 206780750 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TMLE080B12MP11 | 22,200 | $1,110 |
| No | 206780746 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TM8E080B12MP11 | 22,200 | $1,110 |
| No | 203430842 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205549963 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205549959 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203087098 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205549955 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205549951 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205549947 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205549943 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205549939 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203430814 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205549935 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203087009 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205549931 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205549915 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205549911 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205549907 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205549903 | FRASER-JOHNSTON | TH16B3622 | CF42BXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205549899 | FRASER-JOHNSTON | TH16B3622 | CF42BXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205549895 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549891 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205549887 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549883 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203430726 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549927 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549879 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 203430721 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549923 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203086699 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205549919 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203086678 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205549875 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549871 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203430709 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549867 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549863 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 203086639 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205549859 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205549855 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205549851 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549847 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205549843 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203430698 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 205549839 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 205549835 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 203086600 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 205549825 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 205549821 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 205549817 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206780738 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 203430687 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206780742 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 203430682 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206780734 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 203098267 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206780730 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 203098258 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206780726 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206780722 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 205549829 | FRASER-JOHNSTON | TH16B3622 | CU36BXA1+TXV | TPLC080B12MP13 | 22,800 | $1,140 |
| No | 203098049 | FRASER-JOHNSTON | TH16B3622 | CM36BBCA1 | TPLC080B12MP13 | 22,800 | $1,140 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549811 | FRASER-JOHNSTON | TH16B3622 | CM36BXA1+TXV | TPLC080B12MP13 | 22,800 | $1,140 |
| No | 203098021 | FRASER-JOHNSTON | TH16B3622 | CF36BBCA1 | TPLC080B12MP13 | 22,800 | $1,140 |
| No | 205549799 | FRASER-JOHNSTON | TH16B3622 | CU36BXA1+TXV | TM8V080B12MP12 | 22,800 | $1,140 |
| No | 203098033 | FRASER-JOHNSTON | TH16B3622 | CM36BBCA1 | TM8V080B12MP12 | 22,800 | $1,140 |
| No | 205549795 | FRASER-JOHNSTON | TH16B3622 | CM36BXA1+TXV | TM8V080B12MP12 | 22,800 | $1,140 |
| No | 203098005 | FRASER-JOHNSTON | TH16B3622 | CF36BBCA1 | TM8V080B12MP12 | 22,800 | $1,140 |
| No | 205549785 | FRASER-JOHNSTON | TH16B3622 | CF36BXA1+TXV | TPLC080B12MP13 | 22,800 | $1,140 |
| No | 205549777 | FRASER-JOHNSTON | TH16B3622 | CF36BXA1+TXV | TM8V080B12MP12 | 22,800 | $1,140 |
| No | 205549773 | FRASER-JOHNSTON | TH16B3622 | CU36BXA1+TXV | TM9E060A10MP12 | 23,000 | $1,150 |
| No | 203097961 | FRASER-JOHNSTON | TH16B3622 | CM36BBCA1 | TM9E060A10MP12 | 23,000 | $1,150 |
| No | 205549791 | FRASER-JOHNSTON | TH16B3622 | CM36BXA1+TXV | TM9E060A10MP12 | 23,000 | $1,150 |
| No | 203097953 | FRASER-JOHNSTON | TH16B3622 | CF36BBCA1 | TM9E060A10MP12 | 23,000 | $1,150 |
| No | 205549769 | FRASER-JOHNSTON | TH16B3622 | CF36BXA1+TXV | TM9E060A10MP12 | 23,000 | $1,150 |
| No | 205549761 | FRASER-JOHNSTON | TH16B3622 | CU36BXA1+TXV | TM9E060B12MP12 | 22,400 | $1,120 |
| No | 203097921 | FRASER-JOHNSTON | TH16B3622 | CM36BBCA1 | TM9E060B12MP12 | 22,400 | $1,120 |
| No | 205549765 | FRASER-JOHNSTON | TH16B3622 | CF42BXA1+TXV | TM9E060A10MP12 | 22,600 | $1,130 |
| No | 205549757 | FRASER-JOHNSTON | TH16B3622 | CM36BXA1+TXV | TM9E060B12MP12 | 22,400 | $1,120 |
| No | 203097913 | FRASER-JOHNSTON | TH16B3622 | CF36BBCA1 | TM9E060B12MP12 | 22,400 | $1,120 |
| No | 205549753 | FRASER-JOHNSTON | TH16B3622 | CF36BXA1+TXV | TM9E060B12MP12 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549749 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 203097897 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205549745 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205549737 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549741 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205549733 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549729 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097792 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549725 | FRASER-JOHNSTON | TH16B3622 | CF42BXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549721 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097760 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549717 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097752 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549713 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549709 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097737 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549705 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097729 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549701 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203097641 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 206780714 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 206780718 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 206780710 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 205549697 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 203097625 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205549693 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205549689 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205549685 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 203097608 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 205549681 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 203097600 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 205549673 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 205549669 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205549665 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205549661 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 203097576 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 205549677 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 205549657 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549653 | FRASER-JOHNSTON | TH16B3622 | CU36BXA1+TXV | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 203097569 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 203097504 | FRASER-JOHNSTON | TH16B3622 | CM36BBCA1 | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 205549649 | FRASER-JOHNSTON | TH16B3622 | CM36BXA1+TXV | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 203097488 | FRASER-JOHNSTON | TH16B3622 | CF36BBCA1 | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 205549637 | FRASER-JOHNSTON | TH16B3622 | CF36BXA1+TXV | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 205549629 | FRASER-JOHNSTON | TH16B3622 | CF42BXA1+TXV | TM8Y080B12MP11 | 22,200 | $1,110 |
| No | 205549617 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TM8Y100C20MP11 | 22,400 | $1,120 |
| No | 203097392 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TM8Y100C20MP11 | 22,400 | $1,120 |
| No | 205549613 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TM8Y100C20MP11 | 22,400 | $1,120 |
| No | 205549609 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TM8Y120C20MP11 | 22,400 | $1,120 |
| No | 205549605 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TM8Y120C20MP11 | 22,400 | $1,120 |
| No | 203097384 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TM8Y120C20MP11 | 22,400 | $1,120 |
| No | 205549553 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TM8Y120C20MP11 | 22,400 | $1,120 |
| No | 205549557 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TM8Y100C20MP11 | 22,400 | $1,120 |
| No | 205549533 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TM8Y100C20MP11 | 23,200 | $1,160 |
| No | 203097296 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TM8Y100C20MP11 | 23,200 | $1,160 |
| No | 205549573 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TM8Y100C20MP11 | 23,200 | $1,160 |
| No | 203097248 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TM8Y100C20MP11 | 23,200 | $1,160 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549569 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TM8Y120C20MP11 | 23,200 | $1,160 |
| No | 203097288 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TM8Y120C20MP11 | 23,200 | $1,160 |
| No | 205549565 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TM8Y120C20MP11 | 23,200 | $1,160 |
| No | 205549497 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TM8Y100C20MP11 | 23,200 | $1,160 |
| No | 205549493 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TM8Y120C20MP11 | 23,200 | $1,160 |
| No | 203097240 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TM8Y120C20MP11 | 23,200 | $1,160 |
| No | 203097153 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TM8Y100C20MP11 | 22,200 | $1,110 |
| No | 205549473 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TM8Y100C20MP11 | 22,200 | $1,110 |
| No | 205549469 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TM8Y100C20MP11 | 22,200 | $1,110 |
| No | 203097145 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TM8Y120C20MP11 | 22,200 | $1,110 |
| No | 205549465 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TM8Y120C20MP11 | 22,200 | $1,110 |
| No | 205549461 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TM8Y120C20MP11 | 22,200 | $1,110 |
| No | 205549417 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TM8Y100C20MP11 | 22,200 | $1,110 |
| No | 205549413 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TM8Y120C20MP11 | 22,200 | $1,110 |
| No | 205549393 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 203097057 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205549433 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205549385 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205549377 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203097025 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205549373 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 203097009 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205549357 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205549349 | FRASER-JOHNSTON | TH16B3622 | CF42BXA1+MVC12BN21+TXV | | 22,000 | $1,100 |
| No | 203096740 | FRASER-JOHNSTON | TH16B3622 | CM36BBCA1+ME12BN21 | | 22,200 | $1,110 |
| No | 205549361 | FRASER-JOHNSTON | TH16B3622 | CM36BXA1+ME12BN21+TXV | | 22,200 | $1,110 |
| No | 203096733 | FRASER-JOHNSTON | TH16B3622 | CF36BBCA1+ME12BN21 | | 22,200 | $1,110 |
| No | 205549345 | FRASER-JOHNSTON | TH16B3622 | CF36BXA1+ME12BN21+TXV | | 22,200 | $1,110 |
| No | 205549341 | FRASER-JOHNSTON | TH16B3622 | CF42BXA1+ME12BN21+TXV | | 22,200 | $1,110 |
| No | 203096684 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1+MVC14DN21 | | 21,800 | $1,090 |
| No | 205549337 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+MVC14DN21+TXV | | 21,800 | $1,090 |
| No | 205549333 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+MVC14DN21+TXV | | 21,800 | $1,090 |
| No | 205549325 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 203096400 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 205549321 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 205549309 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 203096385 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205549299 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549293 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 205549285 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205549303 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 203096260 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 205549279 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 203096233 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 205549267 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 203096245 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205549263 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 203096217 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205549251 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 205549243 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205549257 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549237 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549233 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 203096022 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 203096014 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205549223 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205549217 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549213 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205549227 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 203095959 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549207 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 203095939 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549201 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 203095951 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205549197 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 203095931 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205549191 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549187 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205549181 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 203095874 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 205549175 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 205549171 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 203095854 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 203095866 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 205549167 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 203095846 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TM9V080C16MP12 | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549161 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 205549157 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 203095747 | FRASER-JOHNSTON | TH16B3622 | AVC42CX21+TXV | | 22,600 | $1,130 |
| No | 205549143 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203095612 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205549139 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203095604 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549131 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549135 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549127 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203095596 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205549123 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205549111 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203095580 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205549107 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205549103 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203095572 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205549099 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205549087 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549083 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205549091 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205549075 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205549071 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203094719 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205549059 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205549055 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203094711 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549051 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549047 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 203094703 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205549043 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205549039 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203094687 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205549027 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205549023 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203094679 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205549005 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205549001 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205548993 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205548989 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205548985 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205548977 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205548973 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205549017 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205549013 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 203094492 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205549009 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 203094484 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548967 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548963 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 203094477 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548959 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548947 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 203094461 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548943 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548939 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 203094453 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TM8V120C20MP12 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205548935 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548927 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548919 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548923 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548911 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548907 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548895 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 203094212 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548891 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 203094156 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548887 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 203094203 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548883 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 203094148 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548879 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 203094196 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548875 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 203094139 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548862 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203094180 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548852 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 203094123 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548844 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 203094171 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548834 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 203094115 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548811 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548807 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548803 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548791 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548783 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548795 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548779 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548775 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548767 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548763 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548755 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548751 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205548747 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548739 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548735 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548731 | FRASER-JOHNSTON | TH16B3622 | CU36BXA1+TXV | TM8Y080B12MP11 | 22,000 | $1,100 |
| No | 203093066 | FRASER-JOHNSTON | TH16B3622 | CM36BBCA1 | TM8Y080B12MP11 | 22,000 | $1,100 |
| No | 205548827 | FRASER-JOHNSTON | TH16B3622 | CM36BXA1+TXV | TM8Y080B12MP11 | 22,000 | $1,100 |
| No | 203093013 | FRASER-JOHNSTON | TH16B3622 | CF36BBCA1 | TM8Y080B12MP11 | 22,000 | $1,100 |
| No | 205548719 | FRASER-JOHNSTON | TH16B3622 | CF36BXA1+TXV | TM8Y080B12MP11 | 22,000 | $1,100 |
| No | 205548707 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 203092681 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205548703 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 203092566 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205548699 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203092662 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205548695 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203092547 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205548655 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205548651 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205548631 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205548627 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205548607 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205548603 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205548583 | FRASER-JOHNSTON | TH16B3622 | CF42BXA1+TXV | TM9Y080B12MP11 | 22,000 | $1,100 |
| No | 205548575 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205548571 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205548567 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205548555 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205548547 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548543 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548539 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548535 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548527 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548519 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548515 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548511 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548489 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548387 | FRASER-JOHNSTON | TH16B3622 | CF42BXA1+TXV | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 205548383 | FRASER-JOHNSTON | TH16B3622 | CF42BXA1+TXV | TM9V080B12MP12 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205548501 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 203090042 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548413 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 203089997 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548409 | FRASER-JOHNSTON | TH16B3622 | CU48CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 203090025 | FRASER-JOHNSTON | TH16B3622 | CM48CBCA1 | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205548377 | FRASER-JOHNSTON | TH16B3622 | CM48CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 203089978 | FRASER-JOHNSTON | TH16B3622 | CF48CBCA1 | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205548371 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548367 | FRASER-JOHNSTON | TH16B3622 | CF48CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 203089858 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548357 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548353 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548349 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205548345 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 203089840 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205548339 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548335 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205548327 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203089670 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548319 | FRASER-JOHNSTON | TH16B3622 | CU36CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203089651 | FRASER-JOHNSTON | TH16B3622 | CM36CBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205548315 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205548323 | FRASER-JOHNSTON | TH16B3622 | CM36CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548309 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548305 | FRASER-JOHNSTON | TH16B3622 | CF36CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205548299 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 203089442 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548291 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 203089398 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548287 | FRASER-JOHNSTON | TH16B3622 | CU42CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203089424 | FRASER-JOHNSTON | TH16B3622 | CM42CBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205548283 | FRASER-JOHNSTON | TH16B3622 | CM42CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203089381 | FRASER-JOHNSTON | TH16B3622 | CF42CBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205548277 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548273 | FRASER-JOHNSTON | TH16B3622 | CF42CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 206780704 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 206780700 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+TXV | TM9V120D20MP12 | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780694 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 206780690 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+TXV | TM9V120D20MP12 | 22,000 | $1,100 |
| No | 203088566 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 205548269 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 205548265 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 203088549 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1 | TM9V120D20MP12 | 22,000 | $1,100 |
| No | 205548261 | FRASER-JOHNSTON | TH16B3622 | CU48DXA1+TXV | TM9V120D20MP12 | 22,000 | $1,100 |
| No | 205548257 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+TXV | TM9V120D20MP12 | 22,000 | $1,100 |
| No | 205548251 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 205548247 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+TXV | TM9V120D20MP12 | 22,000 | $1,100 |
| No | 203088484 | FRASER-JOHNSTON | TH16B3622 | CM48DBCA1+MVC20DN21 | | 22,000 | $1,100 |
| No | 205548099 | FRASER-JOHNSTON | TH16B3622 | CM48DXA1+MVC20DN21+TXV | | 22,000 | $1,100 |
| No | 205548095 | FRASER-JOHNSTON | TH16B3622 | CF48DXA1+MVC20DN21+TXV | | 22,000 | $1,100 |
| No | 205548091 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+MVC20DN21+TXV | | 22,000 | $1,100 |
| No | 205548087 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+MVC20DN21+TXV | | 22,000 | $1,100 |
| No | 205548083 | FRASER-JOHNSTON | TH16B3622 | CM42DXA1+MVC14DN21+TXV | | 22,200 | $1,110 |
| No | 205548079 | FRASER-JOHNSTON | TH16B3622 | CF42DXA1+MVC14DN21+TXV | | 22,200 | $1,110 |
| No | 205074559 | FRASER-JOHNSTON | TH16B2421 | CM30AXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205074307 | FRASER-JOHNSTON | TH16B2421 | CF30ABAA1 | TL8E060A12UH11 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205074553 | FRASER-JOHNSTON | TH16B2421 | CF30AXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205546769 | FRASER-JOHNSTON | TH16B2421 | CM36AXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205546765 | FRASER-JOHNSTON | TH16B2421 | CF36AXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205546761 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 205546757 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 205546753 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 205546749 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 205546717 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TL8E100C20UH11 | 28,200 | $1,410 |
| No | 205546713 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TL8E100C20UH11 | 28,200 | $1,410 |
| No | 205546709 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TL8E100C20UH11 | 28,200 | $1,410 |
| No | 205546705 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TL8E100C20UH11 | 28,200 | $1,410 |
| No | 205546701 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TL8E100C20UH11 | 28,200 | $1,410 |
| No | 205546697 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TL8E100C20UH11 | 28,600 | $1,430 |
| No | 205546693 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TL8E100C20UH11 | 28,600 | $1,430 |
| No | 205546689 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TL8E100C20UH11 | 28,600 | $1,430 |
| No | 205546685 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TL8E100C20UH11 | 28,600 | $1,430 |
| No | 205546681 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TL8E100C20UH11 | 29,400 | $1,470 |
| No | 205546677 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TL8E100C20UH11 | 29,400 | $1,470 |
| No | 205546673 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205546669 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205546665 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205546661 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205546657 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205546653 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TL9E100C20UH11 | 28,400 | $1,420 |
| No | 205546649 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TL9E100C20UH11 | 28,400 | $1,420 |
| No | 205546645 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TL9E100C20UH11 | 28,400 | $1,420 |
| No | 205546641 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TL9E100C20UH11 | 28,400 | $1,420 |
| No | 205546633 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TL9E100C20UH11 | 28,600 | $1,430 |
| No | 205546637 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TL9E100C20UH11 | 28,400 | $1,420 |
| No | 205546629 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TL9E100C20UH11 | 28,600 | $1,430 |
| No | 205546625 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TL9E100C20UH11 | 28,600 | $1,430 |
| No | 205546621 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TL9E100C20UH11 | 28,600 | $1,430 |
| No | 205546617 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TL9E100C20UH11 | 30,400 | $1,520 |
| No | 205546613 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TL9E100C20UH11 | 30,400 | $1,520 |
| No | 205546609 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TMLE080B12MP11 | 28,000 | $1,400 |
| No | 203431430 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TMLE080B12MP11 | 28,000 | $1,400 |
| No | 205546745 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TMLE080B12MP11 | 28,000 | $1,400 |
| No | 203431419 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TMLE080B12MP11 | 28,000 | $1,400 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205546741 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TM8E080B12MP11 | 28,000 | $1,400 |
| No | 203431424 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TM8E080B12MP11 | 28,000 | $1,400 |
| No | 205546737 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TM8E080B12MP11 | 28,000 | $1,400 |
| No | 203431413 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TM8E080B12MP11 | 28,000 | $1,400 |
| No | 205546729 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TMLE080B12MP11 | 28,000 | $1,400 |
| No | 205546725 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TM8E080B12MP11 | 28,000 | $1,400 |
| No | 205546721 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TMLE080C16MP11 | 28,600 | $1,430 |
| No | 203431386 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TMLE080C16MP11 | 28,600 | $1,430 |
| No | 205546733 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TMLE080C16MP11 | 28,600 | $1,430 |
| No | 203431375 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TMLE080C16MP11 | 28,600 | $1,430 |
| No | 205546605 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TM8E080C16MP11 | 28,600 | $1,430 |
| No | 203431381 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TM8E080C16MP11 | 28,600 | $1,430 |
| No | 205546601 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TM8E080C16MP11 | 28,600 | $1,430 |
| No | 203431370 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TM8E080C16MP11 | 28,600 | $1,430 |
| No | 205546597 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TMLE080C16MP11 | 28,600 | $1,430 |
| No | 205546593 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TM8E080C16MP11 | 28,600 | $1,430 |
| No | 203431353 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 205546589 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 205546585 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TMLE080C16MP11 | 27,800 | $1,390 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203431348 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205546581 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205546577 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205546573 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 205546569 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205085182 | FRASER-JOHNSTON | TH16B4821 | CU60DXA2+TXV | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 205085176 | FRASER-JOHNSTON | TH16B4821 | CM60DXA2+TXV | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 205085171 | FRASER-JOHNSTON | TH16B4821 | CU60DXA2+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205085166 | FRASER-JOHNSTON | TH16B4821 | CM60DXA2+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205085162 | FRASER-JOHNSTON | TH16B4821 | CF60DXA2+TXV | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 205085152 | FRASER-JOHNSTON | TH16B4821 | CF60DXA2+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205546557 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TMLE080C16MP11 | 30,600 | $1,530 |
| No | 205546552 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TM8E080C16MP11 | 30,600 | $1,530 |
| No | 205546547 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TMLE080C16MP11 | 30,600 | $1,530 |
| No | 205546542 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TM8E080C16MP11 | 30,600 | $1,530 |
| No | 205546538 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TMLE100B12MP11 | 27,800 | $1,390 |
| No | 205546565 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TMLE100B12MP11 | 27,800 | $1,390 |
| No | 203431287 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TMLE100B12MP11 | 27,800 | $1,390 |
| No | 203431276 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TMLE100B12MP11 | 27,800 | $1,390 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205546561 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TM8E100B12MP11 | 27,800 | $1,390 |
| No | 203431282 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TM8E100B12MP11 | 27,800 | $1,390 |
| No | 205546533 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TM8E100B12MP11 | 27,800 | $1,390 |
| No | 203431271 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TM8E100B12MP11 | 27,800 | $1,390 |
| No | 205546529 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TMLE100B12MP11 | 27,800 | $1,390 |
| No | 205546524 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TM8E100B12MP11 | 27,800 | $1,390 |
| No | 205546520 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205546515 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 203431238 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 203431249 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205546510 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 203431243 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 205546505 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 203431233 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 205546501 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205546496 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 206781500 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TMLE100C16MP11 | 30,600 | $1,530 |
| No | 206781496 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TM8E100C16MP11 | 30,600 | $1,530 |
| No | 206781492 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TMLE100C16MP11 | 30,600 | $1,530 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781488 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TM8E100C16MP11 | 30,600 | $1,530 |
| No | 205084984 | FRASER-JOHNSTON | TH16B4821 | CU60CXA2+TXV | TMLE100C20MP11 | 27,200 | $1,360 |
| No | 205084979 | FRASER-JOHNSTON | TH16B4821 | CM60CXA2+TXV | TMLE100C20MP11 | 27,200 | $1,360 |
| No | 205084973 | FRASER-JOHNSTON | TH16B4821 | CU60CXA2+TXV | TM8E100C20MP11 | 27,200 | $1,360 |
| No | 205084968 | FRASER-JOHNSTON | TH16B4821 | CM60CXA2+TXV | TM8E100C20MP11 | 27,200 | $1,360 |
| No | 205084962 | FRASER-JOHNSTON | TH16B4821 | CF60CXA2+TXV | TMLE100C20MP11 | 27,200 | $1,360 |
| No | 205084956 | FRASER-JOHNSTON | TH16B4821 | CF60CXA2+TXV | TM8E100C20MP11 | 27,200 | $1,360 |
| No | 205084950 | FRASER-JOHNSTON | TH16B4821 | CU60DXA2+TXV | TMLE100C20MP11 | 27,400 | $1,370 |
| No | 205084944 | FRASER-JOHNSTON | TH16B4821 | CM60DXA2+TXV | TMLE100C20MP11 | 27,400 | $1,370 |
| No | 205084938 | FRASER-JOHNSTON | TH16B4821 | CU60DXA2+TXV | TM8E100C20MP11 | 27,400 | $1,370 |
| No | 205084927 | FRASER-JOHNSTON | TH16B4821 | CF60DXA2+TXV | TMLE100C20MP11 | 27,400 | $1,370 |
| No | 205084932 | FRASER-JOHNSTON | TH16B4821 | CM60DXA2+TXV | TM8E100C20MP11 | 27,400 | $1,370 |
| No | 205084921 | FRASER-JOHNSTON | TH16B4821 | CF60DXA2+TXV | TM8E100C20MP11 | 27,400 | $1,370 |
| No | 203431106 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 205546491 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 205546487 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 203431101 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 205546482 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 205546477 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205546472 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 205546467 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 205084882 | FRASER-JOHNSTON | TH16B4821 | CU60CXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205084877 | FRASER-JOHNSTON | TH16B4821 | CM60CXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205084873 | FRASER-JOHNSTON | TH16B4821 | CU60CXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 205084866 | FRASER-JOHNSTON | TH16B4821 | CM60CXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 205084861 | FRASER-JOHNSTON | TH16B4821 | CF60CXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205084855 | FRASER-JOHNSTON | TH16B4821 | CF60CXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 205084849 | FRASER-JOHNSTON | TH16B4821 | CU60DXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205084844 | FRASER-JOHNSTON | TH16B4821 | CM60DXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205084838 | FRASER-JOHNSTON | TH16B4821 | CU60DXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 205084832 | FRASER-JOHNSTON | TH16B4821 | CM60DXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 205084825 | FRASER-JOHNSTON | TH16B4821 | CF60DXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205084819 | FRASER-JOHNSTON | TH16B4821 | CF60DXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 205546437 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 205546428 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 205546432 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 205546423 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 205084743 | FRASER-JOHNSTON | TH16B4821 | CU60CXA2+TXV | TM9E080C20MP12 | 27,200 | $1,360 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205084737 | FRASER-JOHNSTON | TH16B4821 | CM60CXA2+TXV | TM9E080C20MP12 | 27,200 | $1,360 |
| No | 205084726 | FRASER-JOHNSTON | TH16B4821 | CU60DXA2+TXV | TM9E080C20MP12 | 27,600 | $1,380 |
| No | 205084721 | FRASER-JOHNSTON | TH16B4821 | CM60DXA2+TXV | TM9E080C20MP12 | 27,600 | $1,380 |
| No | 205084732 | FRASER-JOHNSTON | TH16B4821 | CF60CXA2+TXV | TM9E080C20MP12 | 27,200 | $1,360 |
| No | 205084715 | FRASER-JOHNSTON | TH16B4821 | CF60DXA2+TXV | TM9E080C20MP12 | 27,600 | $1,380 |
| No | 205546456 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1 | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205546446 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205546451 | FRASER-JOHNSTON | TH16B4821 | CU48DXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205546441 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205084709 | FRASER-JOHNSTON | TH16B4821 | CU60DXA2+TXV | TM9E100C16MP12 | 28,000 | $1,400 |
| No | 205084702 | FRASER-JOHNSTON | TH16B4821 | CM60DXA2+TXV | TM9E100C16MP12 | 28,000 | $1,400 |
| No | 205084697 | FRASER-JOHNSTON | TH16B4821 | CF60DXA2+TXV | TM9E100C16MP12 | 28,000 | $1,400 |
| No | 205546462 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TM9E100C16MP12 | 28,800 | $1,440 |
| No | 205546458 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TM9E100C16MP12 | 28,800 | $1,440 |
| No | 205084691 | FRASER-JOHNSTON | TH16B4821 | CU60CXA2+TXV | TM9E100C20MP12 | 27,200 | $1,360 |
| No | 205084686 | FRASER-JOHNSTON | TH16B4821 | CM60CXA2+TXV | TM9E100C20MP12 | 27,200 | $1,360 |
| No | 205084680 | FRASER-JOHNSTON | TH16B4821 | CF60CXA2+TXV | TM9E100C20MP12 | 27,200 | $1,360 |
| No | 205546317 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TL8E100C20UH11 | 32,800 | $1,640 |
| No | 205546313 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TL8E100C20UH11 | 32,800 | $1,640 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205546309 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TL9E100C20UH11 | 32,800 | $1,640 |
| No | 205546305 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TL9E100C20UH11 | 32,800 | $1,640 |
| No | 205546301 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TMLE080C20MP11 | 32,600 | $1,630 |
| No | 205546297 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TM8E080C20MP11 | 32,600 | $1,630 |
| No | 205546293 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TMLE080C20MP11 | 32,600 | $1,630 |
| No | 205546289 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TM8E080C20MP11 | 32,600 | $1,630 |
| No | 206782996 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TMLE120C16MP11 | 32,800 | $1,640 |
| No | 206782992 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TM8E120C16MP11 | 32,800 | $1,640 |
| No | 206782988 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TMLE120C16MP11 | 32,800 | $1,640 |
| No | 206782984 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TM8E120C16MP11 | 32,800 | $1,640 |
| No | 205546285 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TM9E080C20MP12 | 32,600 | $1,630 |
| No | 205546281 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TM9E080C20MP12 | 32,600 | $1,630 |
| No | 205546277 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TM9E100C20MP12 | 32,600 | $1,630 |
| No | 205546273 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TM9E100C20MP12 | 32,600 | $1,630 |
| No | 205546269 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TM9E120D20MP12 | 33,200 | $1,660 |
| No | 205546265 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TM9E120D20MP12 | 33,200 | $1,660 |
| No | 206838937 | FRASER-JOHNSTON | TH16B2421 | CM36AXA1+TXV | TPLC060A12MP13 | 15,000 | $750 |
| No | 206838933 | FRASER-JOHNSTON | TH16B2421 | CM36AXA1+TXV | TMLV060A12MP12 | 15,000 | $750 |
| No | 206838929 | FRASER-JOHNSTON | TH16B2421 | CM36AXA1+TXV | TM8V060A12MP12 | 15,000 | $750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206838925 | FRASER-JOHNSTON | TH16B2421 | CF36AXA1+TXV | TPLC060A12MP13 | 15,000 | $750 |
| No | 206838921 | FRASER-JOHNSTON | TH16B2421 | CF36AXA1+TXV | TMLV060A12MP12 | 15,000 | $750 |
| No | 206838917 | FRASER-JOHNSTON | TH16B2421 | CF36AXA1+TXV | TM8V060A12MP12 | 15,000 | $750 |
| No | 206779716 | FRASER-JOHNSTON | TH16B2421 | CU24BXA1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 206779712 | FRASER-JOHNSTON | TH16B2421 | CM24BBAA1 | TPLC080B12MP13 | 15,100 | $755 |
| No | 206779708 | FRASER-JOHNSTON | TH16B2421 | CM24BXA1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 202102054 | FRASER-JOHNSTON | TH16B2421 | CF24BBAA1 | TPLC080B12MP13 | 15,100 | $755 |
| No | 206780682 | FRASER-JOHNSTON | TH16B2421 | CM24BBAA1 | TM8V080B12MP12 | 15,100 | $755 |
| No | 206780686 | FRASER-JOHNSTON | TH16B2421 | CU24BXA1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 206780678 | FRASER-JOHNSTON | TH16B2421 | CM24BXA1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 202102036 | FRASER-JOHNSTON | TH16B2421 | CF24BBAA1 | TM8V080B12MP12 | 15,100 | $755 |
| No | 206780655 | FRASER-JOHNSTON | TH16B2421 | CF24BXA1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 206780651 | FRASER-JOHNSTON | TH16B2421 | CF24BXA1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 206780598 | FRASER-JOHNSTON | TH16B2421 | CU36BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780594 | FRASER-JOHNSTON | TH16B2421 | CM36BBAA1 | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780590 | FRASER-JOHNSTON | TH16B2421 | CM36BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780586 | FRASER-JOHNSTON | TH16B2421 | CF36BBAA1 | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780582 | FRASER-JOHNSTON | TH16B2421 | CU36BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780578 | FRASER-JOHNSTON | TH16B2421 | CM36BBAA1 | TM8V080B12MP12 | 15,000 | $750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780574 | FRASER-JOHNSTON | TH16B2421 | CM36BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780570 | FRASER-JOHNSTON | TH16B2421 | CF36BBAA1 | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780565 | FRASER-JOHNSTON | TH16B2421 | CF36BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780561 | FRASER-JOHNSTON | TH16B2421 | CF36BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780549 | FRASER-JOHNSTON | TH16B2421 | CU36CXA1+TXV | TPLC100C16MP13 | 15,100 | $755 |
| No | 206780545 | FRASER-JOHNSTON | TH16B2421 | CM36CXA1+TXV | TPLC100C16MP13 | 15,100 | $755 |
| No | 206780541 | FRASER-JOHNSTON | TH16B2421 | CU36CXA1+TXV | TPLC080C16MP13 | 15,100 | $755 |
| No | 206780537 | FRASER-JOHNSTON | TH16B2421 | CM36CXA1+TXV | TPLC080C16MP13 | 15,100 | $755 |
| No | 206780533 | FRASER-JOHNSTON | TH16B2421 | CU36CXA1+TXV | TMLV100C16MP12 | 15,100 | $755 |
| No | 206780529 | FRASER-JOHNSTON | TH16B2421 | CM36CXA1+TXV | TMLV100C16MP12 | 15,100 | $755 |
| No | 206780525 | FRASER-JOHNSTON | TH16B2421 | CU36CXA1+TXV | TM8V080C16MP12 | 15,100 | $755 |
| No | 206780521 | FRASER-JOHNSTON | TH16B2421 | CM36CXA1+TXV | TM8V080C16MP12 | 15,100 | $755 |
| No | 206780517 | FRASER-JOHNSTON | TH16B2421 | CU36CXA1+TXV | TM8V100C16MP12 | 15,100 | $755 |
| No | 206780513 | FRASER-JOHNSTON | TH16B2421 | CM36CXA1+TXV | TM8V100C16MP12 | 15,100 | $755 |
| No | 206780505 | FRASER-JOHNSTON | TH16B2421 | CF36CXA1+TXV | TPLC100C16MP13 | 15,100 | $755 |
| No | 206780501 | FRASER-JOHNSTON | TH16B2421 | CF36CXA1+TXV | TPLC080C16MP13 | 15,100 | $755 |
| No | 206780497 | FRASER-JOHNSTON | TH16B2421 | CF36CXA1+TXV | TMLV100C16MP12 | 15,100 | $755 |
| No | 206780493 | FRASER-JOHNSTON | TH16B2421 | CF36CXA1+TXV | TM8V080C16MP12 | 15,100 | $755 |
| No | 206780489 | FRASER-JOHNSTON | TH16B2421 | CF36CXA1+TXV | TM8V100C16MP12 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205545610 | FRASER-JOHNSTON | TH16B2421 | CU30BXA1+TXV | TM9Y060B12MP11 | 15,300 | $765 |
| No | 205545601 | FRASER-JOHNSTON | TH16B2421 | CM30BBAA1 | TM9Y060B12MP11 | 15,300 | $765 |
| No | 205545594 | FRASER-JOHNSTON | TH16B2421 | CM30BXA1+TXV | TM9Y060B12MP11 | 15,300 | $765 |
| No | 205545585 | FRASER-JOHNSTON | TH16B2421 | CF30BBAA1 | TM9Y060B12MP11 | 15,300 | $765 |
| No | 205545541 | FRASER-JOHNSTON | TH16B2421 | CF30BXA1+TXV | TM9Y060B12MP11 | 15,300 | $765 |
| No | 205074545 | FRASER-JOHNSTON | TH16B2421 | CM30AXA1+TXV | TM9V040A10MP12 | 15,100 | $755 |
| No | 202143779 | FRASER-JOHNSTON | TH16B2421 | CF30ABAA1 | TM9V040A10MP12 | 15,100 | $755 |
| No | 205546397 | FRASER-JOHNSTON | TH16B2421 | CM36AXA1+TXV | TM9V040A10MP12 | 15,000 | $750 |
| No | 205074540 | FRASER-JOHNSTON | TH16B2421 | CF30AXA1+TXV | TM9V040A10MP12 | 15,100 | $755 |
| No | 205546393 | FRASER-JOHNSTON | TH16B2421 | CF36AXA1+TXV | TM9V040A10MP12 | 15,000 | $750 |
| No | 206780145 | FRASER-JOHNSTON | TH16B2421 | CU24BXA1+TXV | TP9C060B12MP13 | 15,200 | $760 |
| No | 206780141 | FRASER-JOHNSTON | TH16B2421 | CM24BBAA1 | TP9C060B12MP13 | 15,200 | $760 |
| No | 206780137 | FRASER-JOHNSTON | TH16B2421 | CM24BXA1+TXV | TP9C060B12MP13 | 15,200 | $760 |
| No | 202101775 | FRASER-JOHNSTON | TH16B2421 | CF24BBAA1 | TP9C060B12MP13 | 15,200 | $760 |
| No | 206780133 | FRASER-JOHNSTON | TH16B2421 | CU24BXA1+TXV | TM9V060B12MP12 | 15,200 | $760 |
| No | 206780129 | FRASER-JOHNSTON | TH16B2421 | CM24BBAA1 | TM9V060B12MP12 | 15,200 | $760 |
| No | 206780125 | FRASER-JOHNSTON | TH16B2421 | CM24BXA1+TXV | TM9V060B12MP12 | 15,200 | $760 |
| No | 202101771 | FRASER-JOHNSTON | TH16B2421 | CF24BBAA1 | TM9V060B12MP12 | 15,200 | $760 |
| No | 206780049 | FRASER-JOHNSTON | TH16B2421 | CF24BXA1+TXV | TP9C060B12MP13 | 15,200 | $760 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780045 | FRASER-JOHNSTON | TH16B2421 | CF24BXA1+TXV | TM9V060B12MP12 | 15,200 | $760 |
| No | 206780033 | FRASER-JOHNSTON | TH16B2421 | CU30BXA1+TXV | TP9C060B12MP13 | 15,400 | $770 |
| No | 206780029 | FRASER-JOHNSTON | TH16B2421 | CM30BBAA1 | TP9C060B12MP13 | 15,400 | $770 |
| No | 206780025 | FRASER-JOHNSTON | TH16B2421 | CM30BXA1+TXV | TP9C060B12MP13 | 15,400 | $770 |
| No | 206780021 | FRASER-JOHNSTON | TH16B2421 | CF30BBAA1 | TP9C060B12MP13 | 15,400 | $770 |
| No | 206780017 | FRASER-JOHNSTON | TH16B2421 | CU30BXA1+TXV | TM9V060B12MP12 | 15,400 | $770 |
| No | 206780013 | FRASER-JOHNSTON | TH16B2421 | CM30BBAA1 | TM9V060B12MP12 | 15,400 | $770 |
| No | 206780009 | FRASER-JOHNSTON | TH16B2421 | CM30BXA1+TXV | TM9V060B12MP12 | 15,400 | $770 |
| No | 206780005 | FRASER-JOHNSTON | TH16B2421 | CF30BBAA1 | TM9V060B12MP12 | 15,400 | $770 |
| No | 206779999 | FRASER-JOHNSTON | TH16B2421 | CF30BXA1+TXV | TP9C060B12MP13 | 15,400 | $770 |
| No | 206779995 | FRASER-JOHNSTON | TH16B2421 | CF30BXA1+TXV | TM9V060B12MP12 | 15,400 | $770 |
| No | 206780668 | FRASER-JOHNSTON | TH16B2421 | CU24BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780664 | FRASER-JOHNSTON | TH16B2421 | CM24BBAA1 | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780660 | FRASER-JOHNSTON | TH16B2421 | CM24BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 202102050 | FRASER-JOHNSTON | TH16B2421 | CF24BBAA1 | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780477 | FRASER-JOHNSTON | TH16B2421 | CU24BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780473 | FRASER-JOHNSTON | TH16B2421 | CM24BBAA1 | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780469 | FRASER-JOHNSTON | TH16B2421 | CM24BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 202102041 | FRASER-JOHNSTON | TH16B2421 | CF24BBAA1 | TM9V080B12MP12 | 15,000 | $750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780417 | FRASER-JOHNSTON | TH16B2421 | CF24BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780393 | FRASER-JOHNSTON | TH16B2421 | CM30BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780413 | FRASER-JOHNSTON | TH16B2421 | CF24BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780381 | FRASER-JOHNSTON | TH16B2421 | CM30BBAA1 | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780401 | FRASER-JOHNSTON | TH16B2421 | CU30BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780389 | FRASER-JOHNSTON | TH16B2421 | CF30BBAA1 | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780377 | FRASER-JOHNSTON | TH16B2421 | CM30BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780397 | FRASER-JOHNSTON | TH16B2421 | CM30BBAA1 | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780385 | FRASER-JOHNSTON | TH16B2421 | CU30BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780373 | FRASER-JOHNSTON | TH16B2421 | CF30BBAA1 | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780367 | FRASER-JOHNSTON | TH16B2421 | CF30BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780363 | FRASER-JOHNSTON | TH16B2421 | CF30BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780351 | FRASER-JOHNSTON | TH16B2421 | CU36BXA1+TXV | TP9C080B12MP13 | 15,100 | $755 |
| No | 206780347 | FRASER-JOHNSTON | TH16B2421 | CM36BBAA1 | TP9C080B12MP13 | 15,100 | $755 |
| No | 206780343 | FRASER-JOHNSTON | TH16B2421 | CM36BXA1+TXV | TP9C080B12MP13 | 15,100 | $755 |
| No | 206780339 | FRASER-JOHNSTON | TH16B2421 | CF36BBAA1 | TP9C080B12MP13 | 15,100 | $755 |
| No | 206780335 | FRASER-JOHNSTON | TH16B2421 | CU36BXA1+TXV | TM9V080B12MP12 | 15,100 | $755 |
| No | 206780331 | FRASER-JOHNSTON | TH16B2421 | CM36BBAA1 | TM9V080B12MP12 | 15,100 | $755 |
| No | 206780327 | FRASER-JOHNSTON | TH16B2421 | CM36BXA1+TXV | TM9V080B12MP12 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780323 | FRASER-JOHNSTON | TH16B2421 | CF36BBAA1 | TM9V080B12MP12 | 15,100 | $755 |
| No | 206780317 | FRASER-JOHNSTON | TH16B2421 | CF36BXA1+TXV | TP9C080B12MP13 | 15,100 | $755 |
| No | 206780313 | FRASER-JOHNSTON | TH16B2421 | CF36BXA1+TXV | TM9V080B12MP12 | 15,100 | $755 |
| No | 206779937 | FRASER-JOHNSTON | TH16B2421 | CU36CXA1+TXV | TP9C080C16MP13 | 15,100 | $755 |
| No | 206779933 | FRASER-JOHNSTON | TH16B2421 | CM36CXA1+TXV | TP9C080C16MP13 | 15,100 | $755 |
| No | 206779929 | FRASER-JOHNSTON | TH16B2421 | CU36CXA1+TXV | TM9V080C16MP12 | 15,100 | $755 |
| No | 206779925 | FRASER-JOHNSTON | TH16B2421 | CM36CXA1+TXV | TM9V080C16MP12 | 15,100 | $755 |
| No | 206779919 | FRASER-JOHNSTON | TH16B2421 | CF36CXA1+TXV | TP9C080C16MP13 | 15,100 | $755 |
| No | 206779915 | FRASER-JOHNSTON | TH16B2421 | CF36CXA1+TXV | TM9V080C16MP12 | 15,100 | $755 |
| No | 206780457 | FRASER-JOHNSTON | TH16B2421 | CU36CXA1+TXV | TP9C100C16MP13 | 15,100 | $755 |
| No | 206780453 | FRASER-JOHNSTON | TH16B2421 | CM36CXA1+TXV | TP9C100C16MP13 | 15,100 | $755 |
| No | 206780449 | FRASER-JOHNSTON | TH16B2421 | CU36CXA1+TXV | TM9V100C16MP12 | 15,100 | $755 |
| No | 206780445 | FRASER-JOHNSTON | TH16B2421 | CM36CXA1+TXV | TM9V100C16MP12 | 15,100 | $755 |
| No | 206780439 | FRASER-JOHNSTON | TH16B2421 | CF36CXA1+TXV | TP9C100C16MP13 | 15,100 | $755 |
| No | 206780435 | FRASER-JOHNSTON | TH16B2421 | CF36CXA1+TXV | TM9V100C16MP12 | 15,100 | $755 |
| No | 206782637 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TM9V100C16MP12 | 32,600 | $1,630 |
| No | 206782641 | FRASER-JOHNSTON | TH16B6021 | CM64DXA1+TXV | TP9C100C16MP13 | 32,600 | $1,630 |
| No | 206782631 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TP9C100C16MP13 | 32,600 | $1,630 |
| No | 206782627 | FRASER-JOHNSTON | TH16B6021 | CF64DXA1+TXV | TM9V100C16MP12 | 32,600 | $1,630 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781765 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+MVC14DN21+TXV | | 28,000 | $1,400 |
| No | 206781769 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1+MVC14DN21 | | 28,000 | $1,400 |
| No | 206781761 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+MVC14DN21+TXV | | 28,000 | $1,400 |
| No | 206781543 | FRASER-JOHNSTON | TH16B4821 | CM48DBCA1+MVC20DN21 | | 27,800 | $1,390 |
| No | 206781539 | FRASER-JOHNSTON | TH16B4821 | CM48DXA1+MVC20DN21+TXV | | 27,800 | $1,390 |
| No | 206781535 | FRASER-JOHNSTON | TH16B4821 | CF48DXA1+MVC20DN21+TXV | | 27,800 | $1,390 |
| No | 206781259 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+MVC20DN21+TXV | | 29,800 | $1,490 |
| No | 206781255 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+MVC20DN21+TXV | | 29,800 | $1,490 |
| No | 9036586 | FRASER-JOHNSTON | TH16B4821 | AVC48DX21+TXV | | 28,200 | $1,410 |
| No | 206781420 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TPLC100C16MP13 | 29,000 | $1,450 |
| No | 206781416 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TPLC080C16MP13 | 29,000 | $1,450 |
| No | 206781412 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TMLV100C16MP12 | 29,000 | $1,450 |
| No | 206781408 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TM8V080C16MP12 | 29,000 | $1,450 |
| No | 206781404 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TM8V100C16MP12 | 29,000 | $1,450 |
| No | 206781396 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TPLC100C16MP13 | 29,000 | $1,450 |
| No | 206781392 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TPLC080C16MP13 | 29,000 | $1,450 |
| No | 206781388 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TMLV100C16MP12 | 29,000 | $1,450 |
| No | 206781384 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TM8V080C16MP12 | 29,000 | $1,450 |
| No | 206781380 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TM8V100C16MP12 | 29,000 | $1,450 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781484 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TPLC120C20MP13 | 28,000 | $1,400 |
| No | 206781476 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TPLC120C20MP13 | 28,000 | $1,400 |
| No | 202100753 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TPLC120C20MP13 | 28,000 | $1,400 |
| No | 206781480 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TPLC120C20MP13 | 28,000 | $1,400 |
| No | 206781468 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TPLC100C20MP13 | 28,000 | $1,400 |
| No | 206781472 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TPLC100C20MP13 | 28,000 | $1,400 |
| No | 206781464 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TPLC100C20MP13 | 28,000 | $1,400 |
| No | 202100746 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TPLC100C20MP13 | 28,000 | $1,400 |
| No | 206781460 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TMLV120C20MP12 | 28,000 | $1,400 |
| No | 206781456 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TMLV120C20MP12 | 28,000 | $1,400 |
| No | 206781452 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TMLV120C20MP12 | 28,000 | $1,400 |
| No | 202100712 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TMLV120C20MP12 | 28,000 | $1,400 |
| No | 206781436 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TM8V100C20MP12 | 28,000 | $1,400 |
| No | 206781432 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TM8V100C20MP12 | 28,000 | $1,400 |
| No | 206781428 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TM8V100C20MP12 | 28,000 | $1,400 |
| No | 202100667 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TM8V100C20MP12 | 28,000 | $1,400 |
| No | 206781448 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TM8V120C20MP12 | 28,000 | $1,400 |
| No | 206781444 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TM8V120C20MP12 | 28,000 | $1,400 |
| No | 206781440 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TM8V120C20MP12 | 28,000 | $1,400 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202100672 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TM8V120C20MP12 | 28,000 | $1,400 |
| No | 206781367 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TPLC120C20MP13 | 28,000 | $1,400 |
| No | 206781363 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TPLC100C20MP13 | 28,000 | $1,400 |
| No | 206781359 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TMLV120C20MP12 | 28,000 | $1,400 |
| No | 206781355 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TM8V100C20MP12 | 28,000 | $1,400 |
| No | 206781705 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TP9C100C16MP13 | 29,200 | $1,460 |
| No | 206781351 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TM8V120C20MP12 | 28,000 | $1,400 |
| No | 206781701 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TM9V100C16MP12 | 29,200 | $1,460 |
| No | 206781695 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TP9C100C16MP13 | 29,200 | $1,460 |
| No | 206781691 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TM9V100C16MP12 | 29,200 | $1,460 |
| No | 206782547 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TP9C100C20MP13 | 28,400 | $1,420 |
| No | 206782543 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TP9C100C20MP13 | 28,400 | $1,420 |
| No | 206782539 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TP9C100C20MP13 | 28,400 | $1,420 |
| No | 202100731 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TP9C100C20MP13 | 28,400 | $1,420 |
| No | 206782535 | FRASER-JOHNSTON | TH16B4821 | CU48CXA1+TXV | TM9V100C20MP12 | 28,400 | $1,420 |
| No | 206782531 | FRASER-JOHNSTON | TH16B4821 | CM48CBCA1 | TM9V100C20MP12 | 28,400 | $1,420 |
| No | 206782527 | FRASER-JOHNSTON | TH16B4821 | CM48CXA1+TXV | TM9V100C20MP12 | 28,400 | $1,420 |
| No | 202100690 | FRASER-JOHNSTON | TH16B4821 | CF48CBCA1 | TM9V100C20MP12 | 28,400 | $1,420 |
| No | 206782521 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TP9C100C20MP13 | 28,400 | $1,420 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782517 | FRASER-JOHNSTON | TH16B4821 | CF48CXA1+TXV | TM9V100C20MP12 | 28,400 | $1,420 |
| No | 206781521 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TP9C100C20MP13 | 29,000 | $1,450 |
| No | 206781517 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TM9V100C20MP12 | 29,000 | $1,450 |
| No | 206781511 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TP9C100C20MP13 | 29,000 | $1,450 |
| No | 205545158 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TM8Y080C16MP11 | 29,400 | $1,470 |
| No | 205545151 | FRASER-JOHNSTON | TH16B4821 | CM64DXA1+TXV | TM8Y100C16MP11 | 29,400 | $1,470 |
| No | 206781507 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TM9V100C20MP12 | 29,000 | $1,450 |
| No | 205545109 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TM8Y080C16MP11 | 29,400 | $1,470 |
| No | 205545102 | FRASER-JOHNSTON | TH16B4821 | CF64DXA1+TXV | TM8Y100C16MP11 | 29,400 | $1,470 |
| No | 206921725 | FRASER-JOHNSTON | HMH72B241 | CF36BXA1+TXV | TM9E040A10MP12 | 14,500 | $725 |
| No | 206921729 | FRASER-JOHNSTON | HMH72B241 | CF36BBAA1 | TM9E040A10MP12 | 14,500 | $725 |
| No | 206921733 | FRASER-JOHNSTON | HMH72B241 | CM36BXA1+TXV | TM9E040A10MP12 | 14,500 | $725 |
| No | 206921737 | FRASER-JOHNSTON | HMH72B241 | CM36BBAA1 | TM9E040A10MP12 | 14,500 | $725 |
| No | 206921741 | FRASER-JOHNSTON | HMH72B241 | CU36BXA1+TXV | TM9E040A10MP12 | 14,500 | $725 |
| No | 207335181 | FRASER-JOHNSTON | HMH72B241 | CF36AXA1+TXV | TM8Y060A12MP11 | 14,200 | $710 |
| No | 207335176 | FRASER-JOHNSTON | HMH72B241 | CF36BXA1+TXV | TM8Y060A12MP11 | 14,300 | $715 |
| No | 207335182 | FRASER-JOHNSTON | HMH72B241 | CM36AXA1+TXV | TM8Y060A12MP11 | 14,200 | $710 |
| No | 207335179 | FRASER-JOHNSTON | HMH72B241 | CM36BBAA1 | TM8Y060A12MP11 | 14,300 | $715 |
| No | 207335177 | FRASER-JOHNSTON | HMH72B241 | CF36BBAA1 | TM8Y060A12MP11 | 14,300 | $715 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207335178 | FRASER-JOHNSTON | HMH72B241 | CM36BXA1+TXV | TM8Y060A12MP11 | 14,300 | $715 |
| No | 207175993 | FRASER-JOHNSTON | HMH72B241 | CM36CXA1+TXV | TM9Y060B12MP11 | 14,500 | $725 |
| No | 207335180 | FRASER-JOHNSTON | HMH72B241 | CU36BXA1+TXV | TM8Y060A12MP11 | 14,300 | $715 |
| No | 207175989 | FRASER-JOHNSTON | HMH72B241 | CF36CXA1+TXV | TM9Y060B12MP11 | 14,500 | $725 |
| No | 206921621 | FRASER-JOHNSTON | HMH72B241 | CF36CXA1+TXV | TP9C060B12MP13 | 14,500 | $725 |
| No | 206921617 | FRASER-JOHNSTON | HMH72B241 | CF36CXA1+TXV | TM9V060B12MP12 | 14,500 | $725 |
| No | 206921627 | FRASER-JOHNSTON | HMH72B241 | CM36CXA1+TXV | TM9V060B12MP12 | 14,500 | $725 |
| No | 206921635 | FRASER-JOHNSTON | HMH72B241 | CM36CXA1+TXV | TP9C060B12MP13 | 14,500 | $725 |
| No | 207335188 | FRASER-JOHNSTON | HMH72B241 | CF36CXA1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207335189 | FRASER-JOHNSTON | HMH72B241 | CM36CXA1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207335184 | FRASER-JOHNSTON | HMH72B241 | CF36BXA1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207335185 | FRASER-JOHNSTON | HMH72B241 | CF36BBAA1 | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207335186 | FRASER-JOHNSTON | HMH72B241 | CM36BXA1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207335187 | FRASER-JOHNSTON | HMH72B241 | CM36BBAA1 | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207335183 | FRASER-JOHNSTON | HMH72B241 | CU36BXA1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 206921567 | FRASER-JOHNSTON | HMH72B241 | CF36BXA1+TXV | TM9V080B12MP12 | 14,400 | $720 |
| No | 206921571 | FRASER-JOHNSTON | HMH72B241 | CF36BXA1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 206921577 | FRASER-JOHNSTON | HMH72B241 | CF36BBAA1 | TM9V080B12MP12 | 14,400 | $720 |
| No | 206921581 | FRASER-JOHNSTON | HMH72B241 | CM36BXA1+TXV | TM9V080B12MP12 | 14,400 | $720 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921585 | FRASER-JOHNSTON | HMH72B241 | CM36BBAA1 | TM9V080B12MP12 | 14,400 | $720 |
| No | 206921589 | FRASER-JOHNSTON | HMH72B241 | CU36BXA1+TXV | TM9V080B12MP12 | 14,400 | $720 |
| No | 206921593 | FRASER-JOHNSTON | HMH72B241 | CF36BBAA1 | TP9C080B12MP13 | 14,400 | $720 |
| No | 206921597 | FRASER-JOHNSTON | HMH72B241 | CM36BXA1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 206921601 | FRASER-JOHNSTON | HMH72B241 | CM36BBAA1 | TP9C080B12MP13 | 14,400 | $720 |
| No | 206921605 | FRASER-JOHNSTON | HMH72B241 | CU36BXA1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 207251158 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TM9E100C16MP12 | 31,000 | $1,550 |
| No | 207251160 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TM9E100C16MP12 | 31,000 | $1,550 |
| No | 206971540 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TM9V080C16MP12 | 30,800 | $1,540 |
| No | 206971550 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TM9V080C16MP12 | 30,800 | $1,540 |
| No | 206971544 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TP9C080C16MP13 | 30,800 | $1,540 |
| No | 206971554 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TP9C080C16MP13 | 30,800 | $1,540 |
| No | 207176157 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TM9Y100C16MP11 | 30,200 | $1,510 |
| No | 207176161 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TM9Y100C16MP11 | 30,200 | $1,510 |
| No | 206921537 | FRASER-JOHNSTON | HMH72B241 | CF36CXA1+TXV | TM9V080B12MP12 | 14,300 | $715 |
| No | 206921541 | FRASER-JOHNSTON | HMH72B241 | CF36CXA1+TXV | TP9C080B12MP13 | 14,300 | $715 |
| No | 206921547 | FRASER-JOHNSTON | HMH72B241 | CM36CXA1+TXV | TM9V080B12MP12 | 14,300 | $715 |
| No | 206921555 | FRASER-JOHNSTON | HMH72B241 | CM36CXA1+TXV | TP9C080B12MP13 | 14,300 | $715 |
| No | 207251162 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TM9E080C16MP12 | 31,200 | $1,560 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207251164 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TM9E080C16MP12 | 31,200 | $1,560 |
| No | 206971670 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TL9E080C16UH11 | 29,600 | $1,480 |
| No | 206971674 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TL9E080C16UH11 | 29,600 | $1,480 |
| No | 206921781 | FRASER-JOHNSTON | HMH72B241 | CF36CXA1+TXV | TM8V100C16MP12 | 14,300 | $715 |
| No | 206921785 | FRASER-JOHNSTON | HMH72B241 | CF36CXA1+TXV | TM8V080C16MP12 | 14,300 | $715 |
| No | 206921789 | FRASER-JOHNSTON | HMH72B241 | CF36CXA1+TXV | TMLV100C16MP12 | 14,300 | $715 |
| No | 206921793 | FRASER-JOHNSTON | HMH72B241 | CF36CXA1+TXV | TPLC080C16MP13 | 14,300 | $715 |
| No | 206921797 | FRASER-JOHNSTON | HMH72B241 | CF36CXA1+TXV | TPLC100C16MP13 | 14,300 | $715 |
| No | 206921805 | FRASER-JOHNSTON | HMH72B241 | CM36CXA1+TXV | TM8V100C16MP12 | 14,300 | $715 |
| No | 206921813 | FRASER-JOHNSTON | HMH72B241 | CM36CXA1+TXV | TM8V080C16MP12 | 14,300 | $715 |
| No | 206921821 | FRASER-JOHNSTON | HMH72B241 | CM36CXA1+TXV | TMLV100C16MP12 | 14,300 | $715 |
| No | 206921829 | FRASER-JOHNSTON | HMH72B241 | CM36CXA1+TXV | TPLC080C16MP13 | 14,300 | $715 |
| No | 206921837 | FRASER-JOHNSTON | HMH72B241 | CM36CXA1+TXV | TPLC100C16MP13 | 14,300 | $715 |
| No | 207176165 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TM9Y080C16MP11 | 30,200 | $1,510 |
| No | 207176169 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TM9Y080C16MP11 | 30,200 | $1,510 |
| No | 207335293 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TM8Y080C16MP11 | 30,200 | $1,510 |
| No | 207335294 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TM8Y080C16MP11 | 30,200 | $1,510 |
| No | 206971702 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TM8E100C16MP11 | 30,200 | $1,510 |
| No | 206971706 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TMLE100C16MP11 | 30,200 | $1,510 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206971710 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TM8E100C16MP11 | 30,200 | $1,510 |
| No | 206971714 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TMLE100C16MP11 | 30,200 | $1,510 |
| No | 206971718 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TL8E080C16UH11 | 30,200 | $1,510 |
| No | 206971722 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TL8E080C16UH11 | 30,200 | $1,510 |
| No | 206971480 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TM9V100C16MP12 | 30,800 | $1,540 |
| No | 206971484 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TP9C100C16MP13 | 30,800 | $1,540 |
| No | 206971490 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TM9V100C16MP12 | 30,800 | $1,540 |
| No | 206971494 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TP9C100C16MP13 | 30,800 | $1,540 |
| No | 206971520 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TM9V100C20MP12 | 31,000 | $1,550 |
| No | 206971524 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TP9C100C20MP13 | 31,000 | $1,550 |
| No | 206971530 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TM9V100C20MP12 | 31,000 | $1,550 |
| No | 206971534 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TP9C100C20MP13 | 31,000 | $1,550 |
| No | 206971686 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TM8E120C16MP11 | 30,200 | $1,510 |
| No | 206971690 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TMLE120C16MP11 | 30,200 | $1,510 |
| No | 206971654 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TM8E080C16MP11 | 30,200 | $1,510 |
| No | 206971694 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TM8E120C16MP11 | 30,200 | $1,510 |
| No | 206971698 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TMLE120C16MP11 | 30,200 | $1,510 |
| No | 206971658 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TMLE080C16MP11 | 30,200 | $1,510 |
| No | 206971662 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TM8E080C16MP11 | 30,200 | $1,510 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206971666 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TMLE080C16MP11 | 30,200 | $1,510 |
| No | 206971606 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TM8V100C16MP12 | 29,600 | $1,480 |
| No | 206971610 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TM8V080C16MP12 | 29,600 | $1,480 |
| No | 206971614 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TMLV100C16MP12 | 29,600 | $1,480 |
| No | 206971618 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TPLC080C16MP13 | 29,600 | $1,480 |
| No | 206971622 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TPLC100C16MP13 | 29,600 | $1,480 |
| No | 206971630 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TM8V100C16MP12 | 29,600 | $1,480 |
| No | 206971642 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TPLC080C16MP13 | 29,600 | $1,480 |
| No | 206971634 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TM8V080C16MP12 | 29,600 | $1,480 |
| No | 206971638 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TMLV100C16MP12 | 29,600 | $1,480 |
| No | 206971646 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TPLC100C16MP13 | 29,600 | $1,480 |
| No | 207176149 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TM9Y120D20MP11 | 30,600 | $1,530 |
| No | 207176153 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TM9Y120D20MP11 | 30,600 | $1,530 |
| No | 207335296 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TM8Y120C20MP11 | 29,800 | $1,490 |
| No | 207335297 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TM8Y100C20MP11 | 29,800 | $1,490 |
| No | 207335295 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TM8Y120C20MP11 | 29,800 | $1,490 |
| No | 207335298 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TM8Y100C20MP11 | 29,800 | $1,490 |
| No | 206971560 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TM8V120C20MP12 | 29,800 | $1,490 |
| No | 206971564 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TM8V100C20MP12 | 29,800 | $1,490 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206971568 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TMLV120C20MP12 | 29,800 | $1,490 |
| No | 206971572 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TPLC100C20MP13 | 29,800 | $1,490 |
| No | 206971576 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TPLC120C20MP13 | 29,800 | $1,490 |
| No | 206971583 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TM8V120C20MP12 | 29,800 | $1,490 |
| No | 206971587 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TM8V100C20MP12 | 29,800 | $1,490 |
| No | 206971591 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TMLV120C20MP12 | 29,800 | $1,490 |
| No | 206971595 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TPLC100C20MP13 | 29,800 | $1,490 |
| No | 206971599 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TPLC120C20MP13 | 29,800 | $1,490 |
| No | 206971500 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TM9V120D20MP12 | 30,800 | $1,540 |
| No | 206971504 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TP9C120D20MP13 | 30,800 | $1,540 |
| No | 206971510 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TM9V120D20MP12 | 30,800 | $1,540 |
| No | 206971514 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TP9C120D20MP13 | 30,800 | $1,540 |
| No | 206971678 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+TXV | TL8E100C20UH11 | 30,000 | $1,500 |
| No | 206971682 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+TXV | TL8E100C20UH11 | 30,000 | $1,500 |
| No | 206922359 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 206922363 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 206922537 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1 | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206922369 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 206922529 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1 | TM9E080B12MP12 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922533 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206922541 | FRASER-JOHNSTON | HMH72B361 | CU36BXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206922833 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 206922837 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 206922842 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1 | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 206922850 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1 | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 206922846 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 206922858 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1 | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 206922854 | FRASER-JOHNSTON | HMH72B361 | CU36BXA1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 206922862 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 206922866 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1 | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 206922870 | FRASER-JOHNSTON | HMH72B361 | CU36BXA1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 206922878 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+TXV | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 206922882 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+TXV | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 206922886 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+TXV | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 206922890 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1 | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 206922894 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+TXV | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 206922898 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1 | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 206922902 | FRASER-JOHNSTON | HMH72B361 | CU36BXA1+TXV | TM8V060A12MP12 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922915 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1 | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 206922906 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1 | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 206922910 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+TXV | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 206922923 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1 | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 206922919 | FRASER-JOHNSTON | HMH72B361 | CU36BXA1+TXV | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 206922927 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+TXV | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 206922931 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1 | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 206922935 | FRASER-JOHNSTON | HMH72B361 | CU36BXA1+TXV | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 206923404 | FRASER-JOHNSTON | HMH72B361 | CF36AXA1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206923408 | FRASER-JOHNSTON | HMH72B361 | CM36AXA1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206923164 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 206923168 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 206923172 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1 | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 206923176 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 206923180 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1 | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 206923184 | FRASER-JOHNSTON | HMH72B361 | CU36BXA1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 206923188 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1 | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 206923192 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 206923196 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1 | TMLE080B12MP11 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206923200 | FRASER-JOHNSTON | HMH72B361 | CU36BXA1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 206923204 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206923208 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206923212 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1 | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206923216 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206923220 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1 | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206923224 | FRASER-JOHNSTON | HMH72B361 | CU36BXA1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206923228 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1 | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206923232 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206923236 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1 | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206923240 | FRASER-JOHNSTON | HMH72B361 | CU36BXA1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206923392 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206923384 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206923388 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1 | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206923396 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1 | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206923400 | FRASER-JOHNSTON | HMH72B361 | CU36BXA1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206922309 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+TXV | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 206922313 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+TXV | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922319 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1 | TM9V080B12MP12 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922323 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+TXV | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 206922327 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1 | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 206922331 | FRASER-JOHNSTON | HMH72B361 | CU36BXA1+TXV | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 206922335 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1 | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922339 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+TXV | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922343 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1 | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922347 | FRASER-JOHNSTON | HMH72B361 | CU36BXA1+TXV | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922509 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206922513 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206922517 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 207176077 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 207176081 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1 | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 207176085 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 207176089 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1 | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 207176093 | FRASER-JOHNSTON | HMH72B361 | CU36BXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 206923027 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923031 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923039 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923035 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206923047 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923051 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 207176045 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TM9Y080C16MP11 | 24,600 | $1,230 |
| No | 207176049 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TM9Y080C16MP11 | 24,600 | $1,230 |
| No | 207176053 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TM9Y080C16MP11 | 24,600 | $1,230 |
| No | 207176113 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207176117 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1 | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207176121 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207176125 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1 | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207176129 | FRASER-JOHNSTON | HMH72B361 | CU36BXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207335240 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 207335241 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1 | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 207335242 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 206922565 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1 | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 207335243 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1 | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 207335244 | FRASER-JOHNSTON | HMH72B361 | CU36BXA1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 206922561 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+TXV | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 206922569 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+TXV | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 206922573 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1 | TM9E060B12MP12 | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922577 | FRASER-JOHNSTON | HMH72B361 | CU36BXA1+TXV | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 206922797 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TM8V080B12MP12 | 24,400 | $1,220 |
| No | 206922801 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TPLC080B12MP13 | 24,400 | $1,220 |
| No | 206922806 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TM8V080B12MP12 | 24,400 | $1,220 |
| No | 206922810 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TM8V080B12MP12 | 24,400 | $1,220 |
| No | 206922822 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TPLC080B12MP13 | 24,400 | $1,220 |
| No | 206922818 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TPLC080B12MP13 | 24,400 | $1,220 |
| No | 206923059 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923063 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923067 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1 | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923071 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923075 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1 | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923079 | FRASER-JOHNSTON | HMH72B361 | CU36BXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923084 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1 | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923088 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923092 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1 | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923096 | FRASER-JOHNSTON | HMH72B361 | CU36BXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923132 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TM8E080B12MP11 | 24,600 | $1,230 |
| No | 206923136 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TMLE080B12MP11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206923140 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TM8E080B12MP11 | 24,600 | $1,230 |
| No | 206923144 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TM8E080B12MP11 | 24,600 | $1,230 |
| No | 206923152 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 206923156 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 206971314 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TM9V080C16MP12 | 38,000 | $1,900 |
| No | 206971318 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TP9C080C16MP13 | 38,000 | $1,900 |
| No | 206971324 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TM9V080C16MP12 | 38,000 | $1,900 |
| No | 206971328 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TP9C080C16MP13 | 38,000 | $1,900 |
| No | 207335246 | FRASER-JOHNSTON | HMH72B361 | CF36AXA1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 207335245 | FRASER-JOHNSTON | HMH72B361 | CM36AXA1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 206922449 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+TXV | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 206922453 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1 | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 206922457 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+TXV | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 206922461 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1 | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 206922465 | FRASER-JOHNSTON | HMH72B361 | CU36BXA1+TXV | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 206922601 | FRASER-JOHNSTON | HMH72B361 | CF36AXA1+TXV | TM9E060A10MP12 | 24,200 | $1,210 |
| No | 206922605 | FRASER-JOHNSTON | HMH72B361 | CM36AXA1+TXV | TM9E060A10MP12 | 24,200 | $1,210 |
| No | 206923304 | FRASER-JOHNSTON | HMH72B361 | CF36AXA1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 206923300 | FRASER-JOHNSTON | HMH72B361 | CF36AXA1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206923308 | FRASER-JOHNSTON | HMH72B361 | CM36AXA1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206923312 | FRASER-JOHNSTON | HMH72B361 | CM36AXA1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 207176097 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207335252 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1 | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 207176101 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207176105 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207335250 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+TXV | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 207335254 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+TXV | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 207335256 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1 | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 207335248 | FRASER-JOHNSTON | HMH72B361 | CU36BXA1+TXV | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 207176061 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 207176065 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 207176069 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 206922229 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TM9V080C16MP12 | 24,400 | $1,220 |
| No | 206922233 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TP9C080C16MP13 | 24,400 | $1,220 |
| No | 206922239 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TM9V080C16MP12 | 24,400 | $1,220 |
| No | 206922243 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TM9V080C16MP12 | 24,400 | $1,220 |
| No | 206922251 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TP9C080C16MP13 | 24,400 | $1,220 |
| No | 206922255 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TP9C080C16MP13 | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922493 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TM9E080C16MP12 | 24,600 | $1,230 |
| No | 206922497 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TM9E080C16MP12 | 24,600 | $1,230 |
| No | 206922501 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TM9E080C16MP12 | 24,600 | $1,230 |
| No | 206923316 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TL9E080C16UH11 | 24,600 | $1,230 |
| No | 206923320 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TL9E080C16UH11 | 24,600 | $1,230 |
| No | 206923324 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TL9E080C16UH11 | 24,600 | $1,230 |
| No | 206922399 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+TXV | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 206922403 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+TXV | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922409 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1 | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 206922413 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+TXV | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 206922417 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1 | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 206922421 | FRASER-JOHNSTON | HMH72B361 | CU36BXA1+TXV | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 206922425 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1 | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922429 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+TXV | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922433 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1 | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922437 | FRASER-JOHNSTON | HMH72B361 | CU36BXA1+TXV | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922709 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TMLV100C16MP12 | 24,600 | $1,230 |
| No | 206922701 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 206922705 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TM8V080C16MP12 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922713 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TPLC080C16MP13 | 24,600 | $1,230 |
| No | 206922717 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 206922729 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 206922725 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 206922737 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TM8V080C16MP12 | 24,600 | $1,230 |
| No | 206922741 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TM8V080C16MP12 | 24,600 | $1,230 |
| No | 206922749 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TMLV100C16MP12 | 24,600 | $1,230 |
| No | 206922753 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TMLV100C16MP12 | 24,600 | $1,230 |
| No | 206922773 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 206922761 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TPLC080C16MP13 | 24,600 | $1,230 |
| No | 206922765 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TPLC080C16MP13 | 24,600 | $1,230 |
| No | 206922777 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 206923260 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206923264 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 206923268 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1 | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206923272 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206923276 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1 | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206923280 | FRASER-JOHNSTON | HMH72B361 | CU36BXA1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206923284 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1 | TMLE040A12MP11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206923288 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 206923292 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1 | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 206923296 | FRASER-JOHNSTON | HMH72B361 | CU36BXA1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 206923348 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+TXV | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 206923352 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1 | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 206922609 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TM8V120C20MP12 | 24,600 | $1,230 |
| No | 206923356 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+TXV | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 206923360 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1 | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 206923364 | FRASER-JOHNSTON | HMH72B361 | CU36BXA1+TXV | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 206922613 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TM8V100C20MP12 | 24,600 | $1,230 |
| No | 206922617 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TMLV120C20MP12 | 24,600 | $1,230 |
| No | 206922621 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TPLC100C20MP13 | 24,600 | $1,230 |
| No | 206922625 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TPLC120C20MP13 | 24,600 | $1,230 |
| No | 206922632 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TM8V120C20MP12 | 24,600 | $1,230 |
| No | 206922636 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TM8V120C20MP12 | 24,600 | $1,230 |
| No | 206922648 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TM8V100C20MP12 | 24,600 | $1,230 |
| No | 206922644 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TM8V100C20MP12 | 24,600 | $1,230 |
| No | 206922656 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TMLV120C20MP12 | 24,600 | $1,230 |
| No | 206922660 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TMLV120C20MP12 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922668 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TPLC100C20MP13 | 24,600 | $1,230 |
| No | 206922672 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TPLC100C20MP13 | 24,600 | $1,230 |
| No | 206922680 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TPLC120C20MP13 | 24,600 | $1,230 |
| No | 206922684 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TPLC120C20MP13 | 24,600 | $1,230 |
| No | 206922477 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TM9E100C16MP12 | 24,600 | $1,230 |
| No | 206922481 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TM9E100C16MP12 | 24,600 | $1,230 |
| No | 206922485 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TM9E100C16MP12 | 24,600 | $1,230 |
| No | 207335321 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TM8Y080C16MP11 | 38,000 | $1,900 |
| No | 207335322 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TM8Y080C16MP11 | 38,000 | $1,900 |
| No | 206971406 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TL8E080C16UH11 | 38,000 | $1,900 |
| No | 206971410 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TL8E080C16UH11 | 38,000 | $1,900 |
| No | 207335257 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 206922273 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 207335258 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 207335259 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 206922269 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 206922283 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 206922279 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 206922291 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TP9C080B12MP13 | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922295 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 206922149 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TM9V100C20MP12 | 24,400 | $1,220 |
| No | 206922153 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TP9C100C20MP13 | 24,400 | $1,220 |
| No | 206922171 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TP9C100C20MP13 | 24,400 | $1,220 |
| No | 206922159 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TM9V100C20MP12 | 24,400 | $1,220 |
| No | 206922963 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TM8E120C16MP11 | 24,600 | $1,230 |
| No | 206922163 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TM9V100C20MP12 | 24,400 | $1,220 |
| No | 206922175 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TP9C100C20MP13 | 24,400 | $1,220 |
| No | 206922967 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TMLE120C16MP11 | 24,600 | $1,230 |
| No | 206922971 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TM8E120C16MP11 | 24,600 | $1,230 |
| No | 206922975 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TM8E120C16MP11 | 24,600 | $1,230 |
| No | 206922983 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TMLE120C16MP11 | 24,600 | $1,230 |
| No | 206922987 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TMLE120C16MP11 | 24,600 | $1,230 |
| No | 206922995 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TM8E100C16MP11 | 24,600 | $1,230 |
| No | 206922999 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TMLE100C16MP11 | 24,600 | $1,230 |
| No | 206923003 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TM8E100C16MP11 | 24,600 | $1,230 |
| No | 206923007 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TM8E100C16MP11 | 24,600 | $1,230 |
| No | 206923015 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TMLE100C16MP11 | 24,600 | $1,230 |
| No | 206923019 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TMLE100C16MP11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206971210 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TM9V100C20MP12 | 38,000 | $1,900 |
| No | 206971214 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TP9C100C20MP13 | 38,000 | $1,900 |
| No | 206971220 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TM9V100C20MP12 | 38,000 | $1,900 |
| No | 206971224 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TP9C100C20MP13 | 38,000 | $1,900 |
| No | 206971298 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TM8E100C16MP11 | 38,000 | $1,900 |
| No | 206971302 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TMLE100C16MP11 | 38,000 | $1,900 |
| No | 206971306 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TM8E100C16MP11 | 38,000 | $1,900 |
| No | 206971310 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TMLE100C16MP11 | 38,000 | $1,900 |
| No | 206971374 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TM8E080C16MP11 | 38,000 | $1,900 |
| No | 206971378 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TMLE080C16MP11 | 38,000 | $1,900 |
| No | 206971382 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TM8E080C16MP11 | 38,000 | $1,900 |
| No | 206971386 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TMLE080C16MP11 | 38,000 | $1,900 |
| No | 206922469 | FRASER-JOHNSTON | HMH72B361 | CF36AXA1+TXV | TM9V040A10MP12 | 24,000 | $1,200 |
| No | 206922473 | FRASER-JOHNSTON | HMH72B361 | CM36AXA1+TXV | TM9V040A10MP12 | 24,000 | $1,200 |
| No | 206922939 | FRASER-JOHNSTON | HMH72B361 | CF36AXA1+TXV | TM8V060A12MP12 | 24,200 | $1,210 |
| No | 206922943 | FRASER-JOHNSTON | HMH72B361 | CF36AXA1+TXV | TMLV060A12MP12 | 24,200 | $1,210 |
| No | 206922947 | FRASER-JOHNSTON | HMH72B361 | CF36AXA1+TXV | TPLC060A12MP13 | 24,200 | $1,210 |
| No | 206922951 | FRASER-JOHNSTON | HMH72B361 | CM36AXA1+TXV | TM8V060A12MP12 | 24,200 | $1,210 |
| No | 206922189 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TM9V100C16MP12 | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922955 | FRASER-JOHNSTON | HMH72B361 | CM36AXA1+TXV | TMLV060A12MP12 | 24,200 | $1,210 |
| No | 206922959 | FRASER-JOHNSTON | HMH72B361 | CM36AXA1+TXV | TPLC060A12MP13 | 24,200 | $1,210 |
| No | 206922193 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TP9C100C16MP13 | 24,400 | $1,220 |
| No | 206922199 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TM9V100C16MP12 | 24,400 | $1,220 |
| No | 206922203 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TM9V100C16MP12 | 24,400 | $1,220 |
| No | 206922211 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TP9C100C16MP13 | 24,400 | $1,220 |
| No | 206922215 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TP9C100C16MP13 | 24,400 | $1,220 |
| No | 206971266 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TM8E120C16MP11 | 38,000 | $1,900 |
| No | 206971270 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TMLE120C16MP11 | 38,000 | $1,900 |
| No | 206971274 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TM8E120C16MP11 | 38,000 | $1,900 |
| No | 206971278 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TMLE120C16MP11 | 38,000 | $1,900 |
| No | 207176133 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TM9Y120D20MP11 | 38,000 | $1,900 |
| No | 207176137 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TM9Y120D20MP11 | 38,000 | $1,900 |
| No | 206923100 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TM8E080C16MP11 | 24,400 | $1,220 |
| No | 206923104 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TMLE080C16MP11 | 24,400 | $1,220 |
| No | 206923108 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TM8E080C16MP11 | 24,400 | $1,220 |
| No | 206923112 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TM8E080C16MP11 | 24,400 | $1,220 |
| No | 206923120 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TMLE080C16MP11 | 24,400 | $1,220 |
| No | 206923124 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TMLE080C16MP11 | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206971230 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TM9V100C16MP12 | 38,000 | $1,900 |
| No | 206971234 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TP9C100C16MP13 | 38,000 | $1,900 |
| No | 206971240 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TM9V100C16MP12 | 38,000 | $1,900 |
| No | 206971244 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TP9C100C16MP13 | 38,000 | $1,900 |
| No | 206971334 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TM9E120D20MP12 | 38,500 | $1,925 |
| No | 206971338 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TM9E120D20MP12 | 38,500 | $1,925 |
| No | 206971422 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TMLV120C20MP12 | 39,000 | $1,950 |
| No | 206971414 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TM8V120C20MP12 | 39,000 | $1,950 |
| No | 206971418 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TM8V100C20MP12 | 39,000 | $1,950 |
| No | 206971426 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TPLC100C20MP13 | 39,000 | $1,950 |
| No | 206971430 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TPLC120C20MP13 | 39,000 | $1,950 |
| No | 206971437 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TM8V120C20MP12 | 39,000 | $1,950 |
| No | 206971453 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TPLC120C20MP13 | 39,000 | $1,950 |
| No | 206971441 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TM8V100C20MP12 | 39,000 | $1,950 |
| No | 206971445 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TMLV120C20MP12 | 39,000 | $1,950 |
| No | 206971449 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TPLC100C20MP13 | 39,000 | $1,950 |
| No | 207176141 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TM9Y100C20MP11 | 38,000 | $1,900 |
| No | 207176145 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TM9Y100C20MP11 | 38,000 | $1,900 |
| No | 206971282 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TM8E100C20MP11 | 38,500 | $1,925 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206971286 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TMLE100C20MP11 | 38,500 | $1,925 |
| No | 206971290 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TM8E100C20MP11 | 38,500 | $1,925 |
| No | 206971294 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TMLE100C20MP11 | 38,500 | $1,925 |
| No | 207176037 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TM9Y100C16MP11 | 24,200 | $1,210 |
| No | 207176029 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TM9Y100C16MP11 | 24,200 | $1,210 |
| No | 207176033 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TM9Y100C16MP11 | 24,200 | $1,210 |
| No | 206971390 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TL9E100C20UH11 | 38,000 | $1,900 |
| No | 206971394 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TL9E100C20UH11 | 38,000 | $1,900 |
| No | 206971342 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TM9E100C20MP12 | 38,500 | $1,925 |
| No | 206971346 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TM9E100C20MP12 | 38,500 | $1,925 |
| No | 206971398 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TL8E100C20UH11 | 38,000 | $1,900 |
| No | 206971402 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TL8E100C20UH11 | 38,000 | $1,900 |
| No | 206971350 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TM9E080C20MP12 | 38,500 | $1,925 |
| No | 206971354 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TM9E080C20MP12 | 38,500 | $1,925 |
| No | 206971190 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TM9V120D20MP12 | 39,000 | $1,950 |
| No | 206971194 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TP9C120D20MP13 | 39,000 | $1,950 |
| No | 206971200 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TM9V120D20MP12 | 39,000 | $1,950 |
| No | 206971204 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TP9C120D20MP13 | 39,000 | $1,950 |
| No | 207335320 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TM8Y120C20MP11 | 37,800 | $1,890 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207335317 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TM8Y100C20MP11 | 37,800 | $1,890 |
| No | 207335319 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TM8Y120C20MP11 | 37,800 | $1,890 |
| No | 207335318 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TM8Y100C20MP11 | 37,800 | $1,890 |
| No | 206971250 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TM8E120C20MP11 | 37,600 | $1,880 |
| No | 206971254 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TMLE120C20MP11 | 37,600 | $1,880 |
| No | 206971258 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TM8E120C20MP11 | 37,600 | $1,880 |
| No | 206971262 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TMLE120C20MP11 | 37,600 | $1,880 |
| No | 207335261 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TM8Y080C16MP11 | 24,200 | $1,210 |
| No | 207335262 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TM8Y080C16MP11 | 24,200 | $1,210 |
| No | 207335260 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TM8Y080C16MP11 | 24,200 | $1,210 |
| No | 206923368 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TL8E080C16UH11 | 24,000 | $1,200 |
| No | 206923372 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TL8E080C16UH11 | 24,000 | $1,200 |
| No | 206923376 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TL8E080C16UH11 | 24,000 | $1,200 |
| No | 206971358 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TM8E080C20MP11 | 37,800 | $1,890 |
| No | 206922373 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 206971362 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+TXV | TMLE080C20MP11 | 37,800 | $1,890 |
| No | 206971366 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TM8E080C20MP11 | 37,800 | $1,890 |
| No | 206971370 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+TXV | TMLE080C20MP11 | 37,800 | $1,890 |
| No | 206922381 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922385 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 206922545 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 206922549 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 206922553 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 206923332 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+TXV | TL9E060B12UH11 | 24,800 | $1,240 |
| No | 206923336 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+TXV | TL9E060B12UH11 | 24,800 | $1,240 |
| No | 206923340 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1 | TL9E060B12UH11 | 24,800 | $1,240 |
| No | 206922581 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+TXV | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 206922585 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1 | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 206922589 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+TXV | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 206922593 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1 | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 206922597 | FRASER-JOHNSTON | HMH72B361 | CU36BXA1+TXV | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 206923244 | FRASER-JOHNSTON | HMH72B361 | CF36AXA1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206923248 | FRASER-JOHNSTON | HMH72B361 | CF36AXA1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206923252 | FRASER-JOHNSTON | HMH72B361 | CM36AXA1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206923256 | FRASER-JOHNSTON | HMH72B361 | CM36AXA1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206922525 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 207176109 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 206923508 | FRASER-JOHNSTON | HMH72B361 | AE36BX21+TXV | | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206971742 | FRASER-JOHNSTON | HMH72B481 | AVC60DX21+TXV | | 30,600 | $1,530 |
| No | 206971746 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+ME14DN21+TXV | | 30,000 | $1,500 |
| No | 206971750 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+ME14DN21+TXV | | 30,000 | $1,500 |
| No | 207175997 | FRASER-JOHNSTON | HMH72B241 | CU36CXA1+TXV | TM9Y060B12MP11 | 14,500 | $725 |
| No | 207176021 | FRASER-JOHNSTON | HMH72B241 | AE36BX21+TXV | | 14,300 | $715 |
| No | 207176025 | FRASER-JOHNSTON | HMH72B241 | AE36BBA21 | | 14,300 | $715 |
| No | 207176041 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TM9Y100C16MP11 | 24,200 | $1,210 |
| No | 207176057 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TM9Y080C16MP11 | 24,600 | $1,230 |
| No | 207176073 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 206922247 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TM9V080C16MP12 | 24,400 | $1,220 |
| No | 206922259 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TP9C080C16MP13 | 24,400 | $1,220 |
| No | 206922287 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 206922299 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 206922377 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 206922389 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 206922505 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TM9E080C16MP12 | 24,600 | $1,230 |
| No | 206923344 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TL9E060B12UH11 | 24,800 | $1,240 |
| No | 206923380 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TL8E080C16UH11 | 24,000 | $1,200 |
| No | 206923412 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+MVC16CN21+TXV | | 24,200 | $1,210 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206923416 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+MVC16CN21+TXV | | 24,200 | $1,210 |
| No | 206923420 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1+MVC16CN21 | | 24,200 | $1,210 |
| No | 206923424 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+MVC12CN21+TXV | | 24,000 | $1,200 |
| No | 206923428 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+MVC12CN21+TXV | | 24,000 | $1,200 |
| No | 206923432 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1+MVC12CN21 | | 24,000 | $1,200 |
| No | 206921631 | FRASER-JOHNSTON | HMH72B241 | CU36CXA1+TXV | TM9V060B12MP12 | 14,500 | $725 |
| No | 206921639 | FRASER-JOHNSTON | HMH72B241 | CU36CXA1+TXV | TP9C060B12MP13 | 14,500 | $725 |
| No | 206922129 | FRASER-JOHNSTON | HMH72B241 | AVC36BX21+TXV | | 14,300 | $715 |
| No | 206922640 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TM8V120C20MP12 | 24,600 | $1,230 |
| No | 206922652 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TM8V100C20MP12 | 24,600 | $1,230 |
| No | 206922664 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TMLV120C20MP12 | 24,600 | $1,230 |
| No | 206922676 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TPLC100C20MP13 | 24,600 | $1,230 |
| No | 206922688 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TPLC120C20MP13 | 24,600 | $1,230 |
| No | 206922733 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 206922745 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TM8V080C16MP12 | 24,600 | $1,230 |
| No | 206922757 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TMLV100C16MP12 | 24,600 | $1,230 |
| No | 206922769 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TPLC080C16MP13 | 24,600 | $1,230 |
| No | 206922781 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 206922979 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TM8E120C16MP11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922991 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TMLE120C16MP11 | 24,600 | $1,230 |
| No | 206923011 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TM8E100C16MP11 | 24,600 | $1,230 |
| No | 206923023 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TMLE100C16MP11 | 24,600 | $1,230 |
| No | 206923043 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923055 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923116 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TM8E080C16MP11 | 24,400 | $1,220 |
| No | 206923128 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TMLE080C16MP11 | 24,400 | $1,220 |
| No | 206923148 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TM8E080B12MP11 | 24,600 | $1,230 |
| No | 206923160 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 206923476 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+ME12BN21+TXV | | 24,400 | $1,220 |
| No | 206923480 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1+ME12BN21 | | 24,400 | $1,220 |
| No | 206923484 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+ME12BN21+TXV | | 24,400 | $1,220 |
| No | 206923488 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1+ME12BN21 | | 24,400 | $1,220 |
| No | 206923492 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+ME08BN21+TXV | | 23,600 | $1,180 |
| No | 206924365 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1+ME08BN21 | | 23,600 | $1,180 |
| No | 206923496 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+ME08BN21+TXV | | 23,600 | $1,180 |
| No | 206923504 | FRASER-JOHNSTON | HMH72B361 | AVC36BX21+TXV | | 24,600 | $1,230 |
| No | 206924370 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1+ME08BN21 | | 23,600 | $1,180 |
| No | 206923500 | FRASER-JOHNSTON | HMH72B361 | AVC36CX21+TXV | | 24,200 | $1,210 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921809 | FRASER-JOHNSTON | HMH72B241 | CU36CXA1+TXV | TM8V100C16MP12 | 14,300 | $715 |
| No | 206921817 | FRASER-JOHNSTON | HMH72B241 | CU36CXA1+TXV | TM8V080C16MP12 | 14,300 | $715 |
| No | 206921825 | FRASER-JOHNSTON | HMH72B241 | CU36CXA1+TXV | TMLV100C16MP12 | 14,300 | $715 |
| No | 206921833 | FRASER-JOHNSTON | HMH72B241 | CU36CXA1+TXV | TPLC080C16MP13 | 14,300 | $715 |
| No | 206921841 | FRASER-JOHNSTON | HMH72B241 | CU36CXA1+TXV | TPLC100C16MP13 | 14,300 | $715 |
| No | 206922109 | FRASER-JOHNSTON | HMH72B241 | CF36CXA1+ME12CN21+TXV | | 14,200 | $710 |
| No | 206922113 | FRASER-JOHNSTON | HMH72B241 | CM36CXA1+ME12CN21+TXV | | 14,200 | $710 |
| No | 206922167 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TM9V100C20MP12 | 24,400 | $1,220 |
| No | 206922179 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TP9C100C20MP13 | 24,400 | $1,220 |
| No | 206922207 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TM9V100C16MP12 | 24,400 | $1,220 |
| No | 206922219 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TP9C100C16MP13 | 24,400 | $1,220 |
| No | 206922489 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TM9E100C16MP12 | 24,600 | $1,230 |
| No | 206922521 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206922557 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 206923328 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TL9E080C16UH11 | 24,600 | $1,230 |
| No | 206923444 | FRASER-JOHNSTON | HMH72B361 | CM36BXA1+MVC12BN21+TXV | | 24,400 | $1,220 |
| No | 206923436 | FRASER-JOHNSTON | HMH72B361 | CF36BXA1+MVC12BN21+TXV | | 24,400 | $1,220 |
| No | 206923440 | FRASER-JOHNSTON | HMH72B361 | CF36BBCA1+MVC12BN21 | | 24,400 | $1,220 |
| No | 206923448 | FRASER-JOHNSTON | HMH72B361 | CM36BBCA1+MVC12BN21 | | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921551 | FRASER-JOHNSTON | HMH72B241 | CU36CXA1+TXV | TM9V080B12MP12 | 14,300 | $715 |
| No | 206921559 | FRASER-JOHNSTON | HMH72B241 | CU36CXA1+TXV | TP9C080B12MP13 | 14,300 | $715 |
| No | 206922125 | FRASER-JOHNSTON | HMH72B241 | AVC36CX21+TXV | | 14,200 | $710 |
| No | 206922814 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TM8V080B12MP12 | 24,400 | $1,220 |
| No | 206922826 | FRASER-JOHNSTON | HMH72B361 | CU36CXA1+TXV | TPLC080B12MP13 | 24,400 | $1,220 |
| No | 206923452 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+ME16CN21+TXV | | 23,800 | $1,190 |
| No | 206923456 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+ME16CN21+TXV | | 23,800 | $1,190 |
| No | 206923460 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1+ME16CN21 | | 23,800 | $1,190 |
| No | 206923464 | FRASER-JOHNSTON | HMH72B361 | CF36CXA1+ME12CN21+TXV | | 24,200 | $1,210 |
| No | 206923468 | FRASER-JOHNSTON | HMH72B361 | CM36CXA1+ME12CN21+TXV | | 24,200 | $1,210 |
| No | 206923472 | FRASER-JOHNSTON | HMH72B361 | CM36CBCA1+ME12CN21 | | 24,200 | $1,210 |
| No | 206922085 | FRASER-JOHNSTON | HMH72B241 | CF36CXA1+MVC12CN21+TXV | | 14,200 | $710 |
| No | 206922089 | FRASER-JOHNSTON | HMH72B241 | CM36CXA1+MVC12CN21+TXV | | 14,200 | $710 |
| No | 206922101 | FRASER-JOHNSTON | HMH72B241 | CM36BXA1+MVC12BN21+TXV | | 14,300 | $715 |
| No | 206922105 | FRASER-JOHNSTON | HMH72B241 | CM36BBAA1+MVC12BN21 | | 14,300 | $715 |
| No | 206922093 | FRASER-JOHNSTON | HMH72B241 | CF36BXA1+MVC12BN21+TXV | | 14,300 | $715 |
| No | 206922097 | FRASER-JOHNSTON | HMH72B241 | CF36BBAA1+MVC12BN21 | | 14,300 | $715 |
| No | 206922133 | FRASER-JOHNSTON | HMH72B241 | CF36BXA1+ME08BN21+TXV | | 14,100 | $705 |
| No | 206922137 | FRASER-JOHNSTON | HMH72B241 | CF36BBAA1+ME08BN21 | | 14,100 | $705 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922141 | FRASER-JOHNSTON | HMH72B241 | CM36BXA1+ME08BN21+TXV | | 14,100 | $705 |
| No | 206922145 | FRASER-JOHNSTON | HMH72B241 | CM36BBAA1+ME08BN21 | | 14,100 | $705 |
| No | 206971726 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+MVC20DN21+TXV | | 30,200 | $1,510 |
| No | 206971730 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+MVC20DN21+TXV | | 30,200 | $1,510 |
| No | 206971460 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+MVC20DN21+TXV | | 39,000 | $1,950 |
| No | 206971464 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+MVC20DN21+TXV | | 39,000 | $1,950 |
| No | 206971468 | FRASER-JOHNSTON | HMH72B601 | CF64DXA1+ME20DN21+TXV | | 39,000 | $1,950 |
| No | 206971472 | FRASER-JOHNSTON | HMH72B601 | CM64DXA1+ME20DN21+TXV | | 39,000 | $1,950 |
| No | 206971476 | FRASER-JOHNSTON | HMH72B601 | AVC60DX21+TXV | | 39,000 | $1,950 |
| No | 206921985 | FRASER-JOHNSTON | HMH72B241 | CF36AXA1+TXV | TM8V060A12MP12 | 14,100 | $705 |
| No | 206921989 | FRASER-JOHNSTON | HMH72B241 | CF36AXA1+TXV | TMLV060A12MP12 | 14,100 | $705 |
| No | 206921993 | FRASER-JOHNSTON | HMH72B241 | CF36AXA1+TXV | TPLC060A12MP13 | 14,100 | $705 |
| No | 206921997 | FRASER-JOHNSTON | HMH72B241 | CM36AXA1+TXV | TM8V060A12MP12 | 14,100 | $705 |
| No | 206922001 | FRASER-JOHNSTON | HMH72B241 | CM36AXA1+TXV | TMLV060A12MP12 | 14,100 | $705 |
| No | 206922005 | FRASER-JOHNSTON | HMH72B241 | CM36AXA1+TXV | TPLC060A12MP13 | 14,100 | $705 |
| No | 206921880 | FRASER-JOHNSTON | HMH72B241 | CF36BXA1+TXV | TM8V080B12MP12 | 14,400 | $720 |
| No | 206921884 | FRASER-JOHNSTON | HMH72B241 | CF36BXA1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 206921889 | FRASER-JOHNSTON | HMH72B241 | CF36BBAA1 | TM8V080B12MP12 | 14,400 | $720 |
| No | 206921893 | FRASER-JOHNSTON | HMH72B241 | CM36BXA1+TXV | TM8V080B12MP12 | 14,400 | $720 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921897 | FRASER-JOHNSTON | HMH72B241 | CM36BBAA1 | TM8V080B12MP12 | 14,400 | $720 |
| No | 206921901 | FRASER-JOHNSTON | HMH72B241 | CU36BXA1+TXV | TM8V080B12MP12 | 14,400 | $720 |
| No | 206921905 | FRASER-JOHNSTON | HMH72B241 | CF36BBAA1 | TPLC080B12MP13 | 14,400 | $720 |
| No | 206921909 | FRASER-JOHNSTON | HMH72B241 | CM36BXA1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 206921913 | FRASER-JOHNSTON | HMH72B241 | CM36BBAA1 | TPLC080B12MP13 | 14,400 | $720 |
| No | 206921917 | FRASER-JOHNSTON | HMH72B241 | CU36BXA1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 206922057 | FRASER-JOHNSTON | HMH72B241 | CF36BXA1+TXV | TL8E060A12UH11 | 14,500 | $725 |
| No | 206922061 | FRASER-JOHNSTON | HMH72B241 | CF36BBAA1 | TL8E060A12UH11 | 14,500 | $725 |
| No | 206922065 | FRASER-JOHNSTON | HMH72B241 | CM36BXA1+TXV | TL8E060A12UH11 | 14,500 | $725 |
| No | 206922069 | FRASER-JOHNSTON | HMH72B241 | CM36BBAA1 | TL8E060A12UH11 | 14,500 | $725 |
| No | 206922073 | FRASER-JOHNSTON | HMH72B241 | CU36BXA1+TXV | TL8E060A12UH11 | 14,500 | $725 |
| No | 206922077 | FRASER-JOHNSTON | HMH72B241 | CF36AXA1+TXV | TL8E060A12UH11 | 14,400 | $720 |
| No | 206922081 | FRASER-JOHNSTON | HMH72B241 | CM36AXA1+TXV | TL8E060A12UH11 | 14,400 | $720 |
| No | 206921853 | FRASER-JOHNSTON | HMH72B241 | CF36CXA1+TXV | TM8V080B12MP12 | 14,300 | $715 |
| No | 206921857 | FRASER-JOHNSTON | HMH72B241 | CF36CXA1+TXV | TPLC080B12MP13 | 14,300 | $715 |
| No | 206921862 | FRASER-JOHNSTON | HMH72B241 | CM36CXA1+TXV | TM8V080B12MP12 | 14,300 | $715 |
| No | 206921866 | FRASER-JOHNSTON | HMH72B241 | CU36CXA1+TXV | TM8V080B12MP12 | 14,300 | $715 |
| No | 206921870 | FRASER-JOHNSTON | HMH72B241 | CM36CXA1+TXV | TPLC080B12MP13 | 14,300 | $715 |
| No | 206921874 | FRASER-JOHNSTON | HMH72B241 | CU36CXA1+TXV | TPLC080B12MP13 | 14,300 | $715 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921925 | FRASER-JOHNSTON | HMH72B241 | CF36BXA1+TXV | TM8V060A12MP12 | 14,000 | $700 |
| No | 206921941 | FRASER-JOHNSTON | HMH72B241 | CM36BXA1+TXV | TM8V060A12MP12 | 14,000 | $700 |
| No | 206921929 | FRASER-JOHNSTON | HMH72B241 | CF36BXA1+TXV | TMLV060A12MP12 | 14,000 | $700 |
| No | 206921933 | FRASER-JOHNSTON | HMH72B241 | CF36BXA1+TXV | TPLC060A12MP13 | 14,000 | $700 |
| No | 206921937 | FRASER-JOHNSTON | HMH72B241 | CF36BBAA1 | TM8V060A12MP12 | 14,000 | $700 |
| No | 206921945 | FRASER-JOHNSTON | HMH72B241 | CM36BBAA1 | TM8V060A12MP12 | 14,000 | $700 |
| No | 206921949 | FRASER-JOHNSTON | HMH72B241 | CU36BXA1+TXV | TM8V060A12MP12 | 14,000 | $700 |
| No | 206921953 | FRASER-JOHNSTON | HMH72B241 | CF36BBAA1 | TMLV060A12MP12 | 14,000 | $700 |
| No | 206921957 | FRASER-JOHNSTON | HMH72B241 | CM36BXA1+TXV | TMLV060A12MP12 | 14,000 | $700 |
| No | 206921961 | FRASER-JOHNSTON | HMH72B241 | CM36BBAA1 | TMLV060A12MP12 | 14,000 | $700 |
| No | 206921965 | FRASER-JOHNSTON | HMH72B241 | CU36BXA1+TXV | TMLV060A12MP12 | 14,000 | $700 |
| No | 206921977 | FRASER-JOHNSTON | HMH72B241 | CM36BBAA1 | TPLC060A12MP13 | 14,000 | $700 |
| No | 206921969 | FRASER-JOHNSTON | HMH72B241 | CF36BBAA1 | TPLC060A12MP13 | 14,000 | $700 |
| No | 206921973 | FRASER-JOHNSTON | HMH72B241 | CM36BXA1+TXV | TPLC060A12MP13 | 14,000 | $700 |
| No | 206921981 | FRASER-JOHNSTON | HMH72B241 | CU36BXA1+TXV | TPLC060A12MP13 | 14,000 | $700 |
| No | 206922017 | FRASER-JOHNSTON | HMH72B241 | CM36AXA1+TXV | TM8E040A12MP11 | 14,400 | $720 |
| No | 206922009 | FRASER-JOHNSTON | HMH72B241 | CF36AXA1+TXV | TM8E040A12MP11 | 14,400 | $720 |
| No | 206922013 | FRASER-JOHNSTON | HMH72B241 | CF36AXA1+TXV | TMLE040A12MP11 | 14,400 | $720 |
| No | 206922021 | FRASER-JOHNSTON | HMH72B241 | CM36AXA1+TXV | TMLE040A12MP11 | 14,400 | $720 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922037 | FRASER-JOHNSTON | HMH72B241 | CF36BXA1+TXV | TL9E060B12UH11 | 14,500 | $725 |
| No | 206922041 | FRASER-JOHNSTON | HMH72B241 | CF36BBAA1 | TL9E060B12UH11 | 14,500 | $725 |
| No | 206922045 | FRASER-JOHNSTON | HMH72B241 | CM36BXA1+TXV | TL9E060B12UH11 | 14,500 | $725 |
| No | 206922049 | FRASER-JOHNSTON | HMH72B241 | CM36BBAA1 | TL9E060B12UH11 | 14,500 | $725 |
| No | 206922053 | FRASER-JOHNSTON | HMH72B241 | CU36BXA1+TXV | TL9E060B12UH11 | 14,500 | $725 |
| No | 206971734 | FRASER-JOHNSTON | HMH72B481 | CF64DXA1+MVC14DN21+TXV | | 29,200 | $1,460 |
| No | 206971738 | FRASER-JOHNSTON | HMH72B481 | CM64DXA1+MVC14DN21+TXV | | 29,200 | $1,460 |
| No | 206787293 | FRASER-JOHNSTON | HMH72B241 | AE36CX21+TXV | | 14,000 | $700 |
| No | 206787294 | FRASER-JOHNSTON | HMH72B361 | AE36CX21+TXV | | 24,000 | $1,200 |
| No | 206787295 | FRASER-JOHNSTON | HMH72B481 | AE60DX21+TXV | | 30,200 | $1,510 |
| No | 206787296 | FRASER-JOHNSTON | HMH72B601 | AE60DX21+TXV | | 36,800 | $1,840 |
| No | 206319899 | FRIEDRICH | VRP12K******-* | VRP12K******-* | | 7,700 | $385 |
| No | 206319901 | FRIEDRICH | VRP12R******-* | VRP12R******-* | | 7,700 | $385 |
| No | 205141512 | FRIEDRICH | FPHMR42A3A | Heat pump without ducts | | 24,000 | $1,200 |
| No | 205142789 | FRIEDRICH | FRHSR12A3A-A | FRHSW12A3B | | 8,000 | $400 |
| No | 205142788 | FRIEDRICH | FRHSR09A3A-A | FRHSW09A3B | | 6,500 | $325 |
| No | 205104719 | FRIEDRICH | FPHFR18A3A | FPHFC18A3B | | 11,000 | $550 |
| No | 7086358 | FRIEDRICH | MRH12Y3J | MWH12Y3J | | 8,800 | $440 |
| No | 203383864 | FRIEDRICH | FRHSR12A3A | FRHSW12A3A | | 8,000 | $400 |
| No | 203383867 | FRIEDRICH | FPHSR09A1A | FPHSW09A1A | | 5,000 | $250 |
| No | 203383866 | FRIEDRICH | FPHSR12A3A | FPHFW12A3A | | 7,500 | $375 |
| No | 205104716 | FRIEDRICH | FPHFR12A3A | FPHFC12A3B | | 7,000 | $350 |
| No | 205142785 | FRIEDRICH | FPHSR12A3A-A | FPHFW12A3B | | 7,500 | $375 |
| No | 205142781 | FRIEDRICH | FPHSR09A1A-A | FPHSW09A1B | | 5,000 | $250 |
| No | 205142782 | FRIEDRICH | FPHSR12A1A-A | FPHSW12A1B | | 7,500 | $375 |
| No | 205142783 | FRIEDRICH | FPHSR09A3A-A | FPHFW09A3B | | 5,000 | $250 |
| No | 205142786 | FRIEDRICH | FPHSR18A3A-A | FPHFW18A3B | | 11,600 | $580 |
| No | 204101247 | FRIEDRICH | FPHMR36A3A | Heat pump without ducts | | 23,200 | $1,160 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201763897 | FRIEDRICH | MRH09Y3JA | MWH09Y3JA | | 6,500 | $325 |
| No | 201763898 | FRIEDRICH | MRH12Y3JA | MWH12Y3JA | | 8,000 | $400 |
| No | 203383868 | FRIEDRICH | FPHSR12A1A | FPHSW12A1A | | 7,500 | $375 |
| No | 203383869 | FRIEDRICH | FPHSR18A3A | FPHFW18A3A | | 11,600 | $580 |
| No | 203383865 | FRIEDRICH | FPHSR09A3A | FPHFW09A3A | | 5,000 | $250 |
| No | 203383863 | FRIEDRICH | FRHSR09A3A | FRHSW09A3A | | 6,500 | $325 |
| No | 205150429 | FRIEDRICH | FPHMR18A3A | Heat pump without ducts | | 12,200 | $610 |
| No | 204101246 | FRIEDRICH | FPHMR24A3A | Heat pump without ducts | | 15,400 | $770 |
| No | 10221178 | FRIEDRICH | MRAD24Y3J | MWAD24Y3J | | 14,700 | $735 |
| No | 10221177 | FRIEDRICH | MRAD18Y3J | MWAD18Y3J | | 12,471 | $624 |
| No | 10221175 | FRIEDRICH | MRAD09Y1J | MWAD09Y1J | | 6,100 | $305 |
| No | 10221176 | FRIEDRICH | MRAD12Y1J | MWAD12Y1J | | 6,800 | $340 |
| No | 207657372 | FRUIKONAIRE | SIU-18DOR1 | SIU-18DIR1 | | 12,600 | $630 |
| No | 207657374 | FRUIKONAIRE | SIU-36DOR1 | SIU-36DIR1 | | 25,000 | $1,250 |
| No | 208650633 | FRUIKONAIRE | KFR-70W/A | KFR-70G/A | | 16,500 | $825 |
| No | 208650632 | FRUIKONAIRE | KFR-51W/A | KFR-51G/A | | 11,400 | $570 |
| No | 208650631 | FRUIKONAIRE | KFR-35W/A | KFR-35G/A | | 7,000 | $350 |
| No | 208650630 | FRUIKONAIRE | KFR-25W/A | KFR-25G/A | | 6,000 | $300 |
| No | 208650629 | FRUIKONAIRE | KFR-35W/B | KFR-35G/B | | 7,800 | $390 |
| No | 208650628 | FRUIKONAIRE | KFR-25W/B | KFR-25G/B | | 6,300 | $315 |
| No | 207657373 | FRUIKONAIRE | SIU-24DOR1 | SIU-24DIR1 | | 20,000 | $1,000 |
| No | 207657371 | FRUIKONAIRE | SIU-12DOR1 | SIU-12DIR1 | | 9,300 | $465 |
| No | 211306461 | FUJIECO | FES-36H2TK-M4O | Heat pump without ducts | | 21,200 | $1,060 |
| No | 211306460 | FUJIECO | FES-27H2TK-M3O | Heat pump without ducts | | 18,100 | $905 |
| No | 211306459 | FUJIECO | FES-18H2TK-M2O | Heat pump without ducts | | 12,200 | $610 |
| No | 211306454 | FUJIECO | FES-24H2TK-ES(O) | FES-24H2TK-ES(I) | | 13,900 | $695 |
| No | 211306452 | FUJIECO | FES-12H2TK-ES(O) | FES-12H2TK-ES(I) | | 7,600 | $380 |
| No | 212316954 | FUJIECO | FES-09H2TK-ES(O) | FES-09H2TK-ES(I) | | 5,900 | $295 |
| No | 210655534 | FUJIECO | FEFS-36H2MD01(O) | FEFS-36H2MD01(I) | | 25,200 | $1,260 |
| No | 204740067 | FUJITSU | AOUG09LZAH1 | ASUG09LZAS | | 7,400 | $370 |
| No | 204740066 | FUJITSU | AOUG09LZAS1 | ASUG09LZAS | | 7,400 | $370 |
| No | 204740068 | FUJITSU | AOUG12LZAS1 | ASUG12LZAS | | 10,000 | $500 |
| No | 204740069 | FUJITSU | AOUG12LZAH1 | ASUG12LZAS | | 10,000 | $500 |
| No | 204740070 | FUJITSU | AOUG15LZAS1 | ASUG15LZAS | | 11,200 | $560 |
| No | 204740071 | FUJITSU | AOUG15LZAH1 | ASUG15LZAS | | 11,200 | $560 |
| No | 6937309 | FUJITSU | AOU9RLFFH | AGU9RLF | | 7,500 | $375 |
| No | 6936995 | FUJITSU | AOU9RLFF | AGU9RLF | | 7,500 | $375 |
| No | 6936997 | FUJITSU | AOU15RLFF | AGU15RLF | | 11,600 | $580 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 6937311 | FUJITSU | AOU15RLFFH | AGU15RLF | | 11,600 | $580 |
| No | 6937310 | FUJITSU | AOU12RLFFH | AGU12RLF | | 10,600 | $530 |
| No | 206597213 | FUJITSU | AOUG15LZAH1 | ASUG15LZBS | | 11,200 | $560 |
| No | 206597208 | FUJITSU | AOUG09LZAS1 | ASUG09LZBS | | 7,400 | $370 |
| No | 206597209 | FUJITSU | AOUG09LZAH1 | ASUG09LZBS | | 7,400 | $370 |
| No | 206597212 | FUJITSU | AOUG15LZAS1 | ASUG15LZBS | | 11,200 | $560 |
| No | 207131735 | FUJITSU | AOUH24LPAS1 | ASUH24LPAS | | 15,400 | $770 |
| No | 207131734 | FUJITSU | AOUH18LPAS1 | ASUH18LPAS | | 11,200 | $560 |
| No | 207615688 | FUJITSU | AOUH09LMAS1 | ASUH09LMAS | | 7,400 | $370 |
| No | 206913028 | FUJITSU | AOUH24LMAS1 | ASUH24LMAS | | 15,700 | $785 |
| No | 207615689 | FUJITSU | AOUH12LMAS1 | ASUH12LMAS | | 8,800 | $440 |
| No | 206263450 | FUJITSU | AOUH12LMAH1 | ASUH12LMAS | | 10,300 | $515 |
| No | 206597210 | FUJITSU | AOUG12LZAS1 | ASUG12LZBS | | 10,000 | $500 |
| No | 206597211 | FUJITSU | AOUG12LZAH1 | ASUG12LZBS | | 10,000 | $500 |
| No | 204752938 | FUJITSU | AOUG12LMAS1 | ASUG12LMAS | | 10,300 | $515 |
| No | 5751311 | FUJITSU | AOU9RLFC | AUU9RLF | | 7,100 | $355 |
| No | 5751312 | FUJITSU | AOU9RLFC | ARU9RLF | | 7,300 | $365 |
| No | 5751314 | FUJITSU | AOU12RLFC | ARU12RLF | | 9,500 | $475 |
| No | 5751313 | FUJITSU | AOU12RLFC | AUU12RLF | | 10,200 | $510 |
| No | 6961728 | FUJITSU | AOU9RLFW1 | ASU9RLF1 | | 7,600 | $380 |
| No | 6961729 | FUJITSU | AOU12RLFW1 | ASU12RLF1 | | 9,400 | $470 |
| No | 8703507 | FUJITSU | AOU15RLS3 | ASU15RLS3Y | | 11,200 | $560 |
| No | 8703349 | FUJITSU | AOU9RLS3H | ASU9RLS3Y | | 7,000 | $350 |
| No | 8703506 | FUJITSU | AOU12RLS3H | ASU12RLS3Y | | 9,600 | $480 |
| No | 8703508 | FUJITSU | AOU15RLS3H | ASU15RLS3Y | | 11,200 | $560 |
| No | 8703348 | FUJITSU | AOU9RLS3 | ASU9RLS3Y | | 7,000 | $350 |
| No | 202537547 | FUJITSU | AOU24RGLX | ARU24RGLX | | 17,300 | $865 |
| No | 202537546 | FUJITSU | AOU12RLFC | ARU12RGLX | | 10,400 | $520 |
| No | 8703350 | FUJITSU | AOU12RLS3 | ASU12RLS3Y | | 9,600 | $480 |
| No | 205123807 | FUJITSU | AOU24RGLX | AMUG24LMAS | | 18,700 | $935 |
| No | 5063325 | FUJITSU | AOU9RLS2 | ASU9RLS2 | | 7,300 | $365 |
| No | 202843129 | FUJITSU | FO3620RVJCAB | FCC6021ESA | FF100215LT80M | 36,600 | $1,830 |
| No | 202843130 | FUJITSU | FO3620RVJCAB | FCC6021ESA | FF100215LT80D | 36,800 | $1,840 |
| No | 202843126 | FUJITSU | FO3620RVJCAB | FCC6021ESA | FF50173LT80M | 37,400 | $1,870 |
| No | 202843128 | FUJITSU | FO3620RVJCAB | FCC6021ESA | FF75214LT80D | 37,000 | $1,850 |
| No | 202843131 | FUJITSU | FO3620RVJCAB | FCC6021ESA | FF125245LT80M | 36,600 | $1,830 |
| No | 202843118 | FUJITSU | FO2420RVJCAB | FCC2421EUA | FF50173LT80M | 22,800 | $1,140 |
| No | 202843127 | FUJITSU | FO3620RVJCAB | FCC6021ESA | FF75173LT80M | 36,800 | $1,840 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202843114 | FUJITSU | FO3620RVJCAB | FH6021ELVJSC | | 37,400 | $1,870 |
| No | 8908617 | FUJITSU | AOU45RLXFZ | Heat pump without ducts | | 28,200 | $1,410 |
| No | 207334301 | FUJITSU | AOUH12LUAS1 | ARUH12LUAS | | 10,500 | $525 |
| No | 206263449 | FUJITSU | AOUH09LMAH1 | ASUH09LMAS | | 7,400 | $370 |
| No | 206347279 | FUJITSU | AOU48RLAVS4 | Heat pump without ducts | | 33,400 | $1,670 |
| No | 206347302 | FUJITSU | AOU48RLAVS4 | Combination heat pumps with or without ducts | | 34,000 | $1,700 |
| No | 206347278 | FUJITSU | AOU48RLAVS4 | Heat pump with ducts | | 34,600 | $1,730 |
| No | 202843119 | FUJITSU | FO2420RVJCAB | FCC2421EUA | FF75173LT80M | 22,600 | $1,130 |
| No | 202843115 | FUJITSU | FO4820RVJCAB | FH6021ELVJSC | | 41,000 | $2,050 |
| No | 202843120 | FUJITSU | FO2420RVJCAB | FCC2421EUA | FF75214LT80D | 22,600 | $1,130 |
| No | 202843117 | FUJITSU | FO2420RVJCAB | FH2421ELVJUC | | 23,000 | $1,150 |
| No | 202843121 | FUJITSU | FO2420RVJCAB | FCC2421EUA | FF100215LT80M | 22,600 | $1,130 |
| No | 202843140 | FUJITSU | FO4820RVJCAB | FCC6021ESA | FF100215LT80M | 40,000 | $2,000 |
| No | 202843122 | FUJITSU | FO2420RVJCAB | FCC2421EUA | FF100215LT80D | 22,600 | $1,130 |
| No | 202843142 | FUJITSU | FO4820RVJCAB | FCC6021ESA | FF125245LT80M | 40,000 | $2,000 |
| No | 207454671 | FUJITSU | AOUH09LEAS1 | ASUH09LMAS | | 6,700 | $335 |
| No | 207454670 | FUJITSU | AOUH12LEAS1 | ASUH12LMAS | | 7,500 | $375 |
| No | 206909901 | FUJITSU | AOUH12LPAS1 | ASUH12LPAS | | 8,800 | $440 |
| No | 206909902 | FUJITSU | AOUH09LPAS1 | ASUH09LPAS | | 6,200 | $310 |
| No | 206579742 | FUJITSU | AOUH18LUAS1 | ADUH18LUAS1 | | 14,400 | $720 |
| No | 206579743 | FUJITSU | AOUH09LUAS1 | ACUHO9LUAS1 | | 7,400 | $370 |
| No | 206579744 | FUJITSU | AOUH12LUAS1 | ACUH12LUAS1 | | 10,500 | $525 |
| No | 206579741 | FUJITSU | AOUH12LUAS1 | ADUH12LUAS1 | | 10,500 | $525 |
| No | 206579740 | FUJITSU | AOUH09LUAS1 | ADUH09LUAS1 | | 7,400 | $370 |
| No | 202537552 | FUJITSU | AOU48RGLX | AUU48RGLX | | 31,400 | $1,570 |
| No | 205123808 | FUJITSU | AOU30RGLX | AMUG30LMAS | | 22,600 | $1,130 |
| No | 205123809 | FUJITSU | AOUG36LMAS1 | AMUG36LMAS | | 30,400 | $1,520 |
| No | 205123810 | FUJITSU | AOUG48LMAS1 | AMUG48LMAS | | 39,500 | $1,975 |
| No | 202537551 | FUJITSU | AOU48RGLX | ARU48RGLX | | 31,000 | $1,550 |
| No | 202537549 | FUJITSU | AOU36RGLX | ARU36RGLX | | 23,000 | $1,150 |
| No | 8908618 | FUJITSU | AOU45RLXFZ | Heat pump with ducts | | 27,800 | $1,390 |
| No | 8071548 | FUJITSU | AOU36RLXFZ1 | Combination heat pumps with or without ducts | | 21,400 | $1,070 |
| No | 7937663 | FUJITSU | AOU18RLB | ASU18RLB | | 11,500 | $575 |
| No | 6936996 | FUJITSU | AOU12RLFF | AGU12RLF | | 10,600 | $530 |
| No | 8779046 | FUJITSU | AOU24RLXFWH | ASU24RLF | | 18,000 | $900 |
| No | 8718545 | FUJITSU | AOU24RLXFW1 | ASU24RLF | | 18,000 | $900 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204752937 | FUJITSU | AOUG09LMAS1 | ASUG09LMAS | | 7,400 | $370 |
| No | 8912451 | FUJITSU | AOU45RLXFZ | Combination heat pumps with or without ducts | | 28,000 | $1,400 |
| No | 206380029 | GCHV | COU-D24HNR1-D01-J0 | CAHI-36HNVR1-18 | | 15,400 | $770 |
| No | 206322339 | GCHV | COU-D24HNR1-D01-J0 | CAHI-24HNVR1-18 | | 15,400 | $770 |
| No | 212390326 | GE | NS22H24MA4-**A | NCHC30BT4+TDR | NF96U070S3B | 14,500 | $725 |
| No | 212390325 | GE | NS22H24MA4-**A | NCHC30BT4+TDR | NF96U045S3B | 14,500 | $725 |
| No | 212390324 | GE | NS22H24MA4-**A | NCHC30BT4+TDR | NF80L090S4B | 14,500 | $725 |
| No | 212390323 | GE | NS22H24MA4-**A | NCHC30BT4+TDR | NF80U090S4B | 14,500 | $725 |
| No | 212390322 | GE | NS22H24MA4-**A | NCHC30BT4+TDR | NF80L070S3B | 14,200 | $710 |
| No | 212390321 | GE | NS22H24MA4-**A | NCHC30BT4+TDR | NF80U070S3B | 14,200 | $710 |
| No | 212390320 | GE | NS22H24MA4-**A | NCHC30BT4+TDR | NF80U090T4B | 14,500 | $725 |
| No | 212390319 | GE | NS22H24MA4-**A | NCHC30BT4+TDR | NF95X060S3B | 14,500 | $725 |
| No | 212390318 | GE | NS22H24MA4-**A | NCHC30BT4+TDR | NF95X040S3B | 14,500 | $725 |
| No | 212390317 | GE | NS22H24MA4-**A | NCHC30BT4+TDR | NF80X080S4B | 14,700 | $735 |
| No | 212390316 | GE | NS22H24MA4-**A | NCHC30AT4+TDR | NF80L070S3A | 14,000 | $700 |
| No | 212390315 | GE | NS22H24MA4-**A | NCHC30AT4+TDR | NF80U070S3A | 14,000 | $700 |
| No | 212390314 | GE | NS22H24MA4-**A | NCHC30AT4+TDR | NF80L045S3A | 14,300 | $715 |
| No | 212390313 | GE | NS22H24MA4-**A | NCHC30AT4+TDR | NF80U045S3A | 14,300 | $715 |
| No | 212390312 | GE | NS22H24MA4-**A | NCHC30AT4+TDR | NF80U070T3A | 14,300 | $715 |
| No | 212390311 | GE | NS22H24MA4-**A | NCHC30AT4+TDR | NF80U045T3A | 13,900 | $695 |
| No | 212390310 | GE | NS22H24MA4-**A | NCHC30AT4+TDR | NF80X060S3A | 14,200 | $710 |
| No | 212390309 | GE | NS22H24MA4-**A | NCHC30AT4+TDR | NF80X040S3A | 14,200 | $710 |
| No | 212390339 | GE | NS22H60MA4-**A | NCUC50/60CT4+TDR | NF96U110S5C | 38,000 | $1,900 |
| No | 212390338 | GE | NS22H60MA4-**A | NCUC50/60CT4+TDR | NF80L110S5C | 38,500 | $1,925 |
| No | 212390337 | GE | NS22H60MA4-**A | NCUC50/60CT4+TDR | NF80U110S5C | 38,500 | $1,925 |
| No | 212390336 | GE | NS22H60MA4-**A | NCUC50/60CT4+TDR | NF80U090S5C | 38,500 | $1,925 |
| No | 212390340 | GE | NS22H60MA4-**A | NCUC50/60CT4+TDR | NF80U110T5C | 37,600 | $1,880 |
| No | 212390335 | GE | NS22H60MA4-**A | NCUC50/60CT4+TDR | NF95X100S5C | 37,800 | $1,890 |
| No | 212390334 | GE | NS22H60MA4-**A | NCUC50/60CT4+TDR | NF80X100S5C | 38,500 | $1,925 |
| No | 212390351 | GE | NS22H60MA4-**A | NCUC60CT4+TDR | NF80U110T5C | 37,200 | $1,860 |
| No | 212390350 | GE | NS22H60MA4-**A | NCUU60CP4+TDR+TXV | NF80U110T5C | 37,200 | $1,860 |
| No | 212390342 | GE | NS22H36MA4-**A | NCHC42CT4+TDR | NF80U110T5C | 22,600 | $1,130 |
| No | 212390341 | GE | NS22H36MA4-**A | NCHC36CT4+TDR | NF80U110T5C | 22,800 | $1,140 |
| No | 212390349 | GE | NS22H48MA4-**A | NCUC60CT4+TDR | NF80U110T5C | 28,800 | $1,440 |
| No | 212390346 | GE | NS22H48MA4-**A | NCUU60CP4+TDR+TXV | NF80U110T5C | 28,800 | $1,440 |
| No | 212390348 | GE | NS22H48MA4-**A | NCHC51CT4+TDR | NF80U110T5C | 28,000 | $1,400 |
| No | 212390347 | GE | NS22H48MA4-**A | NCHC48CT4+TDR | NF80U110T5C | 28,200 | $1,410 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 212349569 | GE | NS22H24MA4-**A | NCUC24BT4+TDR | NF96U070S3B | 14,800 | $740 |
| No | 212349568 | GE | NS22H24MA4-**A | NCUC24BT4+TDR | NF96U045S3B | 14,800 | $740 |
| No | 212349567 | GE | NS22H24MA4-**A | NCUC24BT4+TDR | NF80U090S4B | 14,800 | $740 |
| No | 212349566 | GE | NS22H24MA4-**A | NCUC24BT4+TDR | NF80U070S3B | 14,500 | $725 |
| No | 212349565 | GE | NS22H24MA4-**A | NCUC24BT4+TDR | NF80U090T4B | 14,800 | $740 |
| No | 212349564 | GE | NS22H24MA4-**A | NCUC24BT4+TDR | NF80X080S4B | 15,000 | $750 |
| No | 212349541 | GE | NS22H24MA4-**A | NCUU24BP4+TDR+TXV | NF96U070S3B | 14,800 | $740 |
| No | 212349540 | GE | NS22H24MA4-**A | NCUU24BP4+TDR+TXV | NF96U045S3B | 14,800 | $740 |
| No | 212349539 | GE | NS22H24MA4-**A | NCUU24BP4+TDR+TXV | NF80U090S4B | 14,800 | $740 |
| No | 212349538 | GE | NS22H24MA4-**A | NCUU24BP4+TDR+TXV | NF80U070S3B | 14,500 | $725 |
| No | 212349537 | GE | NS22H24MA4-**A | NCUU24BP4+TDR+TXV | NF80U090T4B | 14,800 | $740 |
| No | 212349536 | GE | NS22H24MA4-**A | NCUU24BP4+TDR+TXV | NF80X080S4B | 15,000 | $750 |
| No | 212349563 | GE | NS22H24MA4-**A | NCUC24AT4+TDR | NF80U070S3A | 14,500 | $725 |
| No | 212349562 | GE | NS22H24MA4-**A | NCUC24AT4+TDR | NF80U045S3A | 14,200 | $710 |
| No | 212349561 | GE | NS22H24MA4-**A | NCUC24AT4+TDR | NF80U070T3A | 14,700 | $735 |
| No | 212349560 | GE | NS22H24MA4-**A | NCUC24AT4+TDR | NF80U045T3A | 14,300 | $715 |
| No | 212349559 | GE | NS22H24MA4-**A | NCUC24AT4+TDR | NF80X060S3A | 14,700 | $735 |
| No | 212349558 | GE | NS22H24MA4-**A | NCUC24AT4+TDR | NF80X040S3A | 14,700 | $735 |
| No | 212349535 | GE | NS22H24MA4-**A | NCUU24AP4+TDR+TXV | NF80U070S3A | 14,500 | $725 |
| No | 212349534 | GE | NS22H24MA4-**A | NCUU24AP4+TDR+TXV | NF80U045S3A | 14,200 | $710 |
| No | 212349533 | GE | NS22H24MA4-**A | NCUU24AP4+TDR+TXV | NF80U070T3A | 14,700 | $735 |
| No | 212349532 | GE | NS22H24MA4-**A | NCUU24AP4+TDR+TXV | NF80U045T3A | 14,300 | $715 |
| No | 212349531 | GE | NS22H24MA4-**A | NCUU24AP4+TDR+TXV | NF80X060S3A | 14,700 | $735 |
| No | 212349530 | GE | NS22H24MA4-**A | NCUU24AP4+TDR+TXV | NF80X040S3A | 14,700 | $735 |
| No | 212349575 | GE | NS22H24MA4-**A | NCUC30BT4+TDR | NF96U070S3B | 14,400 | $720 |
| No | 212349574 | GE | NS22H24MA4-**A | NCUC30BT4+TDR | NF96U045S3B | 14,400 | $720 |
| No | 212349573 | GE | NS22H24MA4-**A | NCUC30BT4+TDR | NF80U090S4B | 14,400 | $720 |
| No | 212349572 | GE | NS22H24MA4-**A | NCUC30BT4+TDR | NF80U070S3B | 14,000 | $700 |
| No | 212349571 | GE | NS22H24MA4-**A | NCUC30BT4+TDR | NF80U090T4B | 14,400 | $720 |
| No | 212349570 | GE | NS22H24MA4-**A | NCUC30BT4+TDR | NF80X080S4B | 14,500 | $725 |
| No | 212349553 | GE | NS22H24MA4-**A | NCUU30BP4+TDR+TXV | NF96U070S3B | 14,400 | $720 |
| No | 212349552 | GE | NS22H24MA4-**A | NCUU30BP4+TDR+TXV | NF96U045S3B | 14,400 | $720 |
| No | 212349551 | GE | NS22H24MA4-**A | NCUU30BP4+TDR+TXV | NF80U090S4B | 14,400 | $720 |
| No | 212349550 | GE | NS22H24MA4-**A | NCUU30BP4+TDR+TXV | NF80U070S3B | 14,000 | $700 |
| No | 212349549 | GE | NS22H24MA4-**A | NCUU30BP4+TDR+TXV | NF80U090T4B | 14,400 | $720 |
| No | 212349548 | GE | NS22H24MA4-**A | NCUU30BP4+TDR+TXV | NF80X080S4B | 14,500 | $725 |
| No | 212349581 | GE | NS22H24MA4-**A | NCUC30AT4+TDR | NF80U070S3A | 14,000 | $700 |
| No | 212349580 | GE | NS22H24MA4-**A | NCUC30AT4+TDR | NF80U045S3A | 14,200 | $710 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 212349579 | GE | NS22H24MA4-**A | NCUC30AT4+TDR | NF80U070T3A | 14,300 | $715 |
| No | 212349578 | GE | NS22H24MA4-**A | NCUC30AT4+TDR | NF80U045T3A | 13,900 | $695 |
| No | 212349577 | GE | NS22H24MA4-**A | NCUC30AT4+TDR | NF80X060S3A | 14,200 | $710 |
| No | 212349576 | GE | NS22H24MA4-**A | NCUC30AT4+TDR | NF80X040S3A | 14,200 | $710 |
| No | 212349547 | GE | NS22H24MA4-**A | NCUU30AP4+TDR+TXV | NF80U070S3A | 14,000 | $700 |
| No | 212349546 | GE | NS22H24MA4-**A | NCUU30AP4+TDR+TXV | NF80U045S3A | 14,200 | $710 |
| No | 212349545 | GE | NS22H24MA4-**A | NCUU30AP4+TDR+TXV | NF80U070T3A | 14,300 | $715 |
| No | 212349544 | GE | NS22H24MA4-**A | NCUU30AP4+TDR+TXV | NF80U045T3A | 13,900 | $695 |
| No | 212349543 | GE | NS22H24MA4-**A | NCUU30AP4+TDR+TXV | NF80X060S3A | 14,200 | $710 |
| No | 212349542 | GE | NS22H24MA4-**A | NCUU30AP4+TDR+TXV | NF80X040S3A | 14,200 | $710 |
| No | 212349555 | GE | NS22H24MA4-**A | NAM30P1TA4 | | 14,900 | $745 |
| No | 212349557 | GE | NS22H24MA4-**A | NAM30V1TA4 | | 14,500 | $725 |
| No | 212349554 | GE | NS22H24MA4-**A | NAM24P1TA4 | | 14,700 | $735 |
| No | 212349556 | GE | NS22H24MA4-**A | NAM24V1TA4 | | 14,900 | $745 |
| No | 211709078 | GE | NS22H60MA4-**A | NCUC60CT4+TDR | NF96U110S5C | 37,800 | $1,890 |
| No | 211709077 | GE | NS22H60MA4-**A | NCUC60CT4+TDR | NF80L110S5C | 37,800 | $1,890 |
| No | 211709076 | GE | NS22H60MA4-**A | NCUC60CT4+TDR | NF80U110S5C | 37,800 | $1,890 |
| No | 211708969 | GE | NS22H60MA4-**A | NCUC60CT4+TDR | NF80U090S5C | 37,000 | $1,850 |
| No | 211709075 | GE | NS22H60MA4-**A | NCUC60CT4+TDR | NF95X100S5C | 37,600 | $1,880 |
| No | 211709074 | GE | NS22H60MA4-**A | NCUC60CT4+TDR | NF80X100S5C | 38,000 | $1,900 |
| No | 211709070 | GE | NS22H60MA4-**A | NCUU60CP4+TDR+TXV | NF96U110S5C | 37,800 | $1,890 |
| No | 211709068 | GE | NS22H60MA4-**A | NCUU60CP4+TDR+TXV | NF80L110S5C | 37,800 | $1,890 |
| No | 211709067 | GE | NS22H60MA4-**A | NCUU60CP4+TDR+TXV | NF80U110S5C | 37,800 | $1,890 |
| No | 211708967 | GE | NS22H60MA4-**A | NCUU60CP4+TDR+TXV | NF80U090S5C | 37,000 | $1,850 |
| No | 211709066 | GE | NS22H60MA4-**A | NCUU60CP4+TDR+TXV | NF80X100S5C | 38,000 | $1,900 |
| No | 211709079 | GE | NS22H60MA4-**A | NCUC60DT4+TDR | NF80U135S5D | 37,800 | $1,890 |
| No | 211709073 | GE | NS22H60MA4-**A | NCHC60DT4+TDR | NF80U135S5D | 36,800 | $1,840 |
| No | 211709071 | GE | NS22H60MA4-**A | NAM60P1TA4 | | 36,800 | $1,840 |
| No | 211709072 | GE | NS22H60MA4-**A | NAM60V1TA4 | | 37,200 | $1,860 |
| No | 211708892 | GE | NS22H36MA4-**A | NCHC42CT4+TDR | NF96U110S5C | 22,600 | $1,130 |
| No | 211708891 | GE | NS22H36MA4-**A | NCHC42CT4+TDR | NF96U090S4C | 22,400 | $1,120 |
| No | 211708890 | GE | NS22H36MA4-**A | NCHC42CT4+TDR | NF80L110S5C | 22,200 | $1,110 |
| No | 211708889 | GE | NS22H36MA4-**A | NCHC42CT4+TDR | NF80U110S5C | 22,200 | $1,110 |
| No | 211708888 | GE | NS22H36MA4-**A | NCHC42CT4+TDR | NF80U090S5C | 22,200 | $1,110 |
| No | 211708887 | GE | NS22H36MA4-**A | NCHC42CT4+TDR | NF95X100S5C | 22,600 | $1,130 |
| No | 211708886 | GE | NS22H36MA4-**A | NCHC42CT4+TDR | NF95X080S4C | 22,400 | $1,120 |
| No | 211708885 | GE | NS22H36MA4-**A | NCHC42CT4+TDR | NF80X100S5C | 22,400 | $1,120 |
| No | 211708943 | GE | NS22H36MA4-**A | NCUC48BT4+TDR | NF96U070S3B | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211708942 | GE | NS22H36MA4-**A | NCUC48BT4+TDR | NF96U045S3B | 21,800 | $1,090 |
| No | 211708941 | GE | NS22H36MA4-**A | NCUC48BT4+TDR | NF80L090S4B | 22,200 | $1,110 |
| No | 211708939 | GE | NS22H36MA4-**A | NCUC48BT4+TDR | NF80U090S4B | 22,200 | $1,110 |
| No | 211708938 | GE | NS22H36MA4-**A | NCUC48BT4+TDR | NF80L070S3B | 22,200 | $1,110 |
| No | 211708937 | GE | NS22H36MA4-**A | NCUC48BT4+TDR | NF80U070S3B | 22,200 | $1,110 |
| No | 211708936 | GE | NS22H36MA4-**A | NCUC48BT4+TDR | NF80U110T5C | 22,000 | $1,100 |
| No | 211708935 | GE | NS22H36MA4-**A | NCUC48BT4+TDR | NF80U090T4B | 22,000 | $1,100 |
| No | 211708934 | GE | NS22H36MA4-**A | NCUC48BT4+TDR | NF95X060S3B | 22,400 | $1,120 |
| No | 211708933 | GE | NS22H36MA4-**A | NCUC48BT4+TDR | NF95X040S3B | 21,800 | $1,090 |
| No | 211708932 | GE | NS22H36MA4-**A | NCUC48BT4+TDR | NF80X080S4B | 22,600 | $1,130 |
| No | 211708857 | GE | NS22H36MA4-**A | NCUU48BP4+TDR+TXV | NF96U070S3B | 22,200 | $1,110 |
| No | 211708856 | GE | NS22H36MA4-**A | NCUU48BP4+TDR+TXV | NF96U045S3B | 21,800 | $1,090 |
| No | 211708855 | GE | NS22H36MA4-**A | NCUU48BP4+TDR+TXV | NF80L090S4B | 22,200 | $1,110 |
| No | 211708854 | GE | NS22H36MA4-**A | NCUU48BP4+TDR+TXV | NF80U090S4B | 22,200 | $1,110 |
| No | 211708853 | GE | NS22H36MA4-**A | NCUU48BP4+TDR+TXV | NF80L070S3B | 22,200 | $1,110 |
| No | 211708852 | GE | NS22H36MA4-**A | NCUU48BP4+TDR+TXV | NF80U070S3B | 22,200 | $1,110 |
| No | 211708851 | GE | NS22H36MA4-**A | NCUU48BP4+TDR+TXV | NF80U110T5C | 22,000 | $1,100 |
| No | 211708850 | GE | NS22H36MA4-**A | NCUU48BP4+TDR+TXV | NF80U090T4B | 22,000 | $1,100 |
| No | 211708849 | GE | NS22H36MA4-**A | NCUU48BP4+TDR+TXV | NF95X060S3B | 22,400 | $1,120 |
| No | 211708848 | GE | NS22H36MA4-**A | NCUU48BP4+TDR+TXV | NF95X040S3B | 21,800 | $1,090 |
| No | 211708846 | GE | NS22H36MA4-**A | NCUU48BP4+TDR+TXV | NF80X080S4B | 22,600 | $1,130 |
| No | 211708865 | GE | NS22H36MA4-**A | NCHC30AT4+TDR | NF80L070S3A | 22,600 | $1,130 |
| No | 211708864 | GE | NS22H36MA4-**A | NCHC30AT4+TDR | NF80U070S3A | 22,600 | $1,130 |
| No | 211708862 | GE | NS22H36MA4-**A | NCHC30AT4+TDR | NF80L045S3A | 22,600 | $1,130 |
| No | 211708861 | GE | NS22H36MA4-**A | NCHC30AT4+TDR | NF80U045S3A | 22,600 | $1,130 |
| No | 211709060 | GE | NS22H36MA4-**A | NCHC30AT4+TDR | NF80U070T3A | 23,000 | $1,150 |
| No | 211708860 | GE | NS22H36MA4-**A | NCHC30AT4+TDR | NF80U045T3A | 23,000 | $1,150 |
| No | 211709059 | GE | NS22H36MA4-**A | NCHC30AT4+TDR | NF80X060S3A | 22,600 | $1,130 |
| No | 211709058 | GE | NS22H36MA4-**A | NCHC30AT4+TDR | NF80X040S3A | 22,600 | $1,130 |
| No | 211708931 | GE | NS22H36MA4-**A | NCUC36BT4+TDR | NF96U070S3B | 21,600 | $1,080 |
| No | 211708930 | GE | NS22H36MA4-**A | NCUC36BT4+TDR | NF80L090S4B | 21,600 | $1,080 |
| No | 211708929 | GE | NS22H36MA4-**A | NCUC36BT4+TDR | NF80U090S4B | 21,600 | $1,080 |
| No | 211708928 | GE | NS22H36MA4-**A | NCUC36BT4+TDR | NF80L070S3B | 21,600 | $1,080 |
| No | 211708927 | GE | NS22H36MA4-**A | NCUC36BT4+TDR | NF80U070S3B | 21,600 | $1,080 |
| No | 211708926 | GE | NS22H36MA4-**A | NCUC36BT4+TDR | NF80U110T5C | 21,400 | $1,070 |
| No | 211708924 | GE | NS22H36MA4-**A | NCUC36BT4+TDR | NF80U090T4B | 21,800 | $1,090 |
| No | 211708923 | GE | NS22H36MA4-**A | NCUC36BT4+TDR | NF95X060S3B | 21,800 | $1,090 |
| No | 211708922 | GE | NS22H36MA4-**A | NCUC36BT4+TDR | NF95X040S3B | 21,400 | $1,070 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211708921 | GE | NS22H36MA4-**A | NCUC36BT4+TDR | NF80X080S4B | 22,000 | $1,100 |
| No | 211708845 | GE | NS22H36MA4-**A | NCUU36BP4+TDR+TXV | NF96U070S3B | 21,600 | $1,080 |
| No | 211708844 | GE | NS22H36MA4-**A | NCUU36BP4+TDR+TXV | NF80L090S4B | 21,600 | $1,080 |
| No | 211708843 | GE | NS22H36MA4-**A | NCUU36BP4+TDR+TXV | NF80U090S4B | 21,600 | $1,080 |
| No | 211708842 | GE | NS22H36MA4-**A | NCUU36BP4+TDR+TXV | NF80L070S3B | 21,600 | $1,080 |
| No | 211708841 | GE | NS22H36MA4-**A | NCUU36BP4+TDR+TXV | NF80U070S3B | 21,600 | $1,080 |
| No | 211708840 | GE | NS22H36MA4-**A | NCUU36BP4+TDR+TXV | NF80U110T5C | 21,400 | $1,070 |
| No | 211708839 | GE | NS22H36MA4-**A | NCUU36BP4+TDR+TXV | NF80U090T4B | 21,800 | $1,090 |
| No | 211708838 | GE | NS22H36MA4-**A | NCUU36BP4+TDR+TXV | NF95X060S3B | 21,800 | $1,090 |
| No | 211708837 | GE | NS22H36MA4-**A | NCUU36BP4+TDR+TXV | NF95X040S3B | 21,400 | $1,070 |
| No | 211708836 | GE | NS22H36MA4-**A | NCUU36BP4+TDR+TXV | NF80X080S4B | 22,000 | $1,100 |
| No | 211708920 | GE | NS22H36MA4-**A | NCUC36AT4+TDR | NF80L070S3A | 21,600 | $1,080 |
| No | 211708919 | GE | NS22H36MA4-**A | NCUC36AT4+TDR | NF80U070S3A | 21,600 | $1,080 |
| No | 211708918 | GE | NS22H36MA4-**A | NCUC36AT4+TDR | NF80L045S3A | 21,600 | $1,080 |
| No | 211708917 | GE | NS22H36MA4-**A | NCUC36AT4+TDR | NF80U045S3A | 21,600 | $1,080 |
| No | 211708916 | GE | NS22H36MA4-**A | NCUC36AT4+TDR | NF80U070T3A | 21,800 | $1,090 |
| No | 211708915 | GE | NS22H36MA4-**A | NCUC36AT4+TDR | NF80U045T3A | 21,800 | $1,090 |
| No | 211708914 | GE | NS22H36MA4-**A | NCUC36AT4+TDR | NF80X060S3A | 21,600 | $1,080 |
| No | 211708913 | GE | NS22H36MA4-**A | NCUC36AT4+TDR | NF80X040S3A | 21,600 | $1,080 |
| No | 211708835 | GE | NS22H36MA4-**A | NCUU36AP4+TDR+TXV | NF80L070S3A | 21,600 | $1,080 |
| No | 211708834 | GE | NS22H36MA4-**A | NCUU36AP4+TDR+TXV | NF80U070S3A | 21,600 | $1,080 |
| No | 211708833 | GE | NS22H36MA4-**A | NCUU36AP4+TDR+TXV | NF80L045S3A | 21,600 | $1,080 |
| No | 211708832 | GE | NS22H36MA4-**A | NCUU36AP4+TDR+TXV | NF80U045S3A | 21,600 | $1,080 |
| No | 211708830 | GE | NS22H36MA4-**A | NCUU36AP4+TDR+TXV | NF80U070T3A | 21,800 | $1,090 |
| No | 211708829 | GE | NS22H36MA4-**A | NCUU36AP4+TDR+TXV | NF80U045T3A | 21,800 | $1,090 |
| No | 211708828 | GE | NS22H36MA4-**A | NCUU36AP4+TDR+TXV | NF80X060S3A | 21,600 | $1,080 |
| No | 211708827 | GE | NS22H36MA4-**A | NCUU36AP4+TDR+TXV | NF80X040S3A | 21,600 | $1,080 |
| No | 211708884 | GE | NS22H36MA4-**A | NCHC36CT4+TDR | NF96U110S5C | 22,800 | $1,140 |
| No | 211708883 | GE | NS22H36MA4-**A | NCHC36CT4+TDR | NF96U090S4C | 22,800 | $1,140 |
| No | 211708882 | GE | NS22H36MA4-**A | NCHC36CT4+TDR | NF80L110S5C | 22,600 | $1,130 |
| No | 211708881 | GE | NS22H36MA4-**A | NCHC36CT4+TDR | NF80U110S5C | 22,600 | $1,130 |
| No | 211708880 | GE | NS22H36MA4-**A | NCHC36CT4+TDR | NF80U090S5C | 22,600 | $1,130 |
| No | 211708879 | GE | NS22H36MA4-**A | NCHC36CT4+TDR | NF95X100S5C | 22,800 | $1,140 |
| No | 211708878 | GE | NS22H36MA4-**A | NCHC36CT4+TDR | NF95X080S4C | 22,800 | $1,140 |
| No | 211708876 | GE | NS22H36MA4-**A | NCHC36CT4+TDR | NF80X100S5C | 22,800 | $1,140 |
| No | 211708875 | GE | NS22H36MA4-**A | NCHC30BT4+TDR | NF96U070S3B | 22,400 | $1,120 |
| No | 211708874 | GE | NS22H36MA4-**A | NCHC30BT4+TDR | NF80L090S4B | 22,400 | $1,120 |
| No | 211708873 | GE | NS22H36MA4-**A | NCHC30BT4+TDR | NF80U090S4B | 22,200 | $1,110 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211708872 | GE | NS22H36MA4-**A | NCHC30BT4+TDR | NF80L070S3B | 22,400 | $1,120 |
| No | 211708871 | GE | NS22H36MA4-**A | NCHC30BT4+TDR | NF80U070S3B | 22,400 | $1,120 |
| No | 211708870 | GE | NS22H36MA4-**A | NCHC30BT4+TDR | NF80U110T5C | 22,600 | $1,130 |
| No | 211708869 | GE | NS22H36MA4-**A | NCHC30BT4+TDR | NF80U090T4B | 22,600 | $1,130 |
| No | 211708868 | GE | NS22H36MA4-**A | NCHC30BT4+TDR | NF95X060S3B | 22,600 | $1,130 |
| No | 211708867 | GE | NS22H36MA4-**A | NCHC30BT4+TDR | NF95X040S3B | 22,200 | $1,110 |
| No | 211708866 | GE | NS22H36MA4-**A | NCHC30BT4+TDR | NF80X080S4B | 22,800 | $1,140 |
| No | 211708912 | GE | NS22H36MA4-**A | NCUC30BT4+TDR | NF96U070S3B | 21,600 | $1,080 |
| No | 211708911 | GE | NS22H36MA4-**A | NCUC30BT4+TDR | NF80L090S4B | 21,600 | $1,080 |
| No | 211708910 | GE | NS22H36MA4-**A | NCUC30BT4+TDR | NF80U090S4B | 21,600 | $1,080 |
| No | 211708908 | GE | NS22H36MA4-**A | NCUC30BT4+TDR | NF80L070S3B | 21,600 | $1,080 |
| No | 211708907 | GE | NS22H36MA4-**A | NCUC30BT4+TDR | NF80U070S3B | 21,600 | $1,080 |
| No | 211708906 | GE | NS22H36MA4-**A | NCUC30BT4+TDR | NF80U110T5C | 21,600 | $1,080 |
| No | 211708905 | GE | NS22H36MA4-**A | NCUC30BT4+TDR | NF80U090T4B | 21,800 | $1,090 |
| No | 211708904 | GE | NS22H36MA4-**A | NCUC30BT4+TDR | NF95X060S3B | 21,800 | $1,090 |
| No | 211708903 | GE | NS22H36MA4-**A | NCUC30BT4+TDR | NF95X040S3B | 21,400 | $1,070 |
| No | 211708902 | GE | NS22H36MA4-**A | NCUC30BT4+TDR | NF80X080S4B | 21,600 | $1,080 |
| No | 211708826 | GE | NS22H36MA4-**A | NCUU30BP4+TDR+TXV | NF96U070S3B | 21,600 | $1,080 |
| No | 211708825 | GE | NS22H36MA4-**A | NCUU30BP4+TDR+TXV | NF80L090S4B | 21,600 | $1,080 |
| No | 211708824 | GE | NS22H36MA4-**A | NCUU30BP4+TDR+TXV | NF80U090S4B | 21,600 | $1,080 |
| No | 211708823 | GE | NS22H36MA4-**A | NCUU30BP4+TDR+TXV | NF80L070S3B | 21,600 | $1,080 |
| No | 211708822 | GE | NS22H36MA4-**A | NCUU30BP4+TDR+TXV | NF80U070S3B | 21,600 | $1,080 |
| No | 211708821 | GE | NS22H36MA4-**A | NCUU30BP4+TDR+TXV | NF80U110T5C | 21,600 | $1,080 |
| No | 211708820 | GE | NS22H36MA4-**A | NCUU30BP4+TDR+TXV | NF80U090T4B | 21,800 | $1,090 |
| No | 211708819 | GE | NS22H36MA4-**A | NCUU30BP4+TDR+TXV | NF95X060S3B | 21,800 | $1,090 |
| No | 211708818 | GE | NS22H36MA4-**A | NCUU30BP4+TDR+TXV | NF95X040S3B | 21,400 | $1,070 |
| No | 211708817 | GE | NS22H36MA4-**A | NCUU30BP4+TDR+TXV | NF80X080S4B | 21,600 | $1,080 |
| No | 211708901 | GE | NS22H36MA4-**A | NCUC30AT4+TDR | NF80L070S3A | 21,600 | $1,080 |
| No | 211708900 | GE | NS22H36MA4-**A | NCUC30AT4+TDR | NF80U070S3A | 21,600 | $1,080 |
| No | 211708899 | GE | NS22H36MA4-**A | NCUC30AT4+TDR | NF80L045S3A | 21,400 | $1,070 |
| No | 211708898 | GE | NS22H36MA4-**A | NCUC30AT4+TDR | NF80U045S3A | 21,400 | $1,070 |
| No | 211708897 | GE | NS22H36MA4-**A | NCUC30AT4+TDR | NF80U070T3A | 21,800 | $1,090 |
| No | 211708896 | GE | NS22H36MA4-**A | NCUC30AT4+TDR | NF80U045T3A | 21,800 | $1,090 |
| No | 211708895 | GE | NS22H36MA4-**A | NCUC30AT4+TDR | NF80X060S3A | 21,600 | $1,080 |
| No | 211708894 | GE | NS22H36MA4-**A | NCUC30AT4+TDR | NF80X040S3A | 21,600 | $1,080 |
| No | 211708815 | GE | NS22H36MA4-**A | NCUU30AP4+TDR+TXV | NF80L070S3A | 21,600 | $1,080 |
| No | 211708814 | GE | NS22H36MA4-**A | NCUU30AP4+TDR+TXV | NF80U070S3A | 21,600 | $1,080 |
| No | 211708813 | GE | NS22H36MA4-**A | NCUU30AP4+TDR+TXV | NF80L045S3A | 21,400 | $1,070 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211708812 | GE | NS22H36MA4-**A | NCUU30AP4+TDR+TXV | NF80U045S3A | 21,400 | $1,070 |
| No | 211708811 | GE | NS22H36MA4-**A | NCUU30AP4+TDR+TXV | NF80U070T3A | 21,800 | $1,090 |
| No | 211708810 | GE | NS22H36MA4-**A | NCUU30AP4+TDR+TXV | NF80U045T3A | 21,800 | $1,090 |
| No | 211708809 | GE | NS22H36MA4-**A | NCUU30AP4+TDR+TXV | NF80X060S3A | 21,600 | $1,080 |
| No | 211708808 | GE | NS22H36MA4-**A | NCUU30AP4+TDR+TXV | NF80X040S3A | 21,600 | $1,080 |
| No | 211708859 | GE | NS22H36MA4-**A | NAM42V1TA4 | | 22,200 | $1,110 |
| No | 211708858 | GE | NS22H36MA4-**A | NAM36V1TA4 | | 22,200 | $1,110 |
| No | 211708966 | GE | NS22H48MA4-**A | NCUC60CT4+TDR | NF96U110S5C | 28,800 | $1,440 |
| No | 211708965 | GE | NS22H48MA4-**A | NCUC60CT4+TDR | NF80L110S5C | 28,600 | $1,430 |
| No | 211708964 | GE | NS22H48MA4-**A | NCUC60CT4+TDR | NF80U110S5C | 28,600 | $1,430 |
| No | 211708963 | GE | NS22H48MA4-**A | NCUC60CT4+TDR | NF80U090S5C | 28,600 | $1,430 |
| No | 211708962 | GE | NS22H48MA4-**A | NCUC60CT4+TDR | NF95X100S5C | 28,800 | $1,440 |
| No | 211708961 | GE | NS22H48MA4-**A | NCUC60CT4+TDR | NF80X100S5C | 28,800 | $1,440 |
| No | 211708949 | GE | NS22H48MA4-**A | NCUU60CP4+TDR+TXV | NF96U110S5C | 28,800 | $1,440 |
| No | 211708948 | GE | NS22H48MA4-**A | NCUU60CP4+TDR+TXV | NF80L110S5C | 28,600 | $1,430 |
| No | 211708947 | GE | NS22H48MA4-**A | NCUU60CP4+TDR+TXV | NF80U110S5C | 28,600 | $1,430 |
| No | 211708946 | GE | NS22H48MA4-**A | NCUU60CP4+TDR+TXV | NF80U090S5C | 28,600 | $1,430 |
| No | 211708945 | GE | NS22H48MA4-**A | NCUU60CP4+TDR+TXV | NF95X100S5C | 28,800 | $1,440 |
| No | 211708944 | GE | NS22H48MA4-**A | NCUU60CP4+TDR+TXV | NF80X100S5C | 28,800 | $1,440 |
| No | 211708960 | GE | NS22H48MA4-**A | NCHC51CT4+TDR | NF96U110S5C | 28,200 | $1,410 |
| No | 211708959 | GE | NS22H48MA4-**A | NCHC51CT4+TDR | NF80L110S5C | 28,000 | $1,400 |
| No | 211708958 | GE | NS22H48MA4-**A | NCHC51CT4+TDR | NF80U110S5C | 28,000 | $1,400 |
| No | 211708957 | GE | NS22H48MA4-**A | NCHC51CT4+TDR | NF80U090S5C | 28,000 | $1,400 |
| No | 211708956 | GE | NS22H48MA4-**A | NCHC51CT4+TDR | NF95X100S5C | 28,400 | $1,420 |
| No | 211708954 | GE | NS22H48MA4-**A | NCHC51CT4+TDR | NF80X100S5C | 28,200 | $1,410 |
| No | 211708953 | GE | NS22H48MA4-**A | NCHC48CT4+TDR | NF96U110S5C | 28,200 | $1,410 |
| No | 211708952 | GE | NS22H48MA4-**A | NCHC48CT4+TDR | NF80L110S5C | 28,000 | $1,400 |
| No | 211708951 | GE | NS22H48MA4-**A | NCHC48CT4+TDR | NF80U110S5C | 28,000 | $1,400 |
| No | 211708950 | GE | NS22H48MA4-**A | NCHC48CT4+TDR | NF80U090S5C | 28,000 | $1,400 |
| No | 211709065 | GE | NS22H48MA4-**A | NCHC48CT4+TDR | NF95X100S5C | 28,400 | $1,420 |
| No | 211709064 | GE | NS22H48MA4-**A | NCHC48CT4+TDR | NF80X100S5C | 28,400 | $1,420 |
| No | 211709062 | GE | NS22H48MA4-**A | NAM60P1TA4 | | 28,200 | $1,410 |
| No | 209941274 | GE | NS18H60MA4-** | NCUC60DT4 | NF96U135V5D-* | 40,000 | $2,000 |
| No | 209941124 | GE | NS18H60MA4-** | NCUC60DT4 | NF80U135S5D-* | 40,000 | $2,000 |
| No | 209941233 | GE | NS18H60MA4-** | NCUC60CT4 | NF96U110S5C-* | 37,800 | $1,890 |
| No | 209941116 | GE | NS18H60MA4-** | NCUC60CT4 | NF80U110S5C-* | 38,000 | $1,900 |
| No | 209941107 | GE | NS18H60MA4-** | NCUC60CT4 | NF80X100S5C-* | 38,000 | $1,900 |
| No | 209941100 | GE | NS18H60MA4-** | NCUC60CT4 | NF80U090S5C-* | 38,000 | $1,900 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 209941231 | GE | NS18H60MA4-** | NCUU60CP4+TXV | NF96U110S5C-* | 37,800 | $1,890 |
| No | 209941114 | GE | NS18H60MA4-** | NCUU60CP4+TXV | NF80U110S5C-* | 38,000 | $1,900 |
| No | 209941105 | GE | NS18H60MA4-** | NCUU60CP4+TXV | NF80X100S5C-* | 38,000 | $1,900 |
| No | 209941098 | GE | NS18H60MA4-** | NCUU60CP4+TXV | NF80U090S5C-* | 38,000 | $1,900 |
| No | 209941101 | GE | NS18H60MA4-** | NCHC51CT4 | NF80U090S5C-* | 36,800 | $1,840 |
| No | 209941273 | GE | NS18H60MA4-** | NCUU60DP4+TXV | NF96U135V5D-* | 39,000 | $1,950 |
| No | 209941123 | GE | NS18H60MA4-** | NCUU60DP4+TXV | NF80U135S5D-* | 39,000 | $1,950 |
| No | 209941268 | GE | NS18H60MA4-** | NCUC60CT4 | NF96U110V5C-* | 38,000 | $1,900 |
| No | 209941257 | GE | NS18H60MA4-** | NCUC60CT4 | NF96U090V5C-* | 38,000 | $1,900 |
| No | 209941169 | GE | NS18H60MA4-** | NCUC60CT4 | NF80U110V5C-* | 38,000 | $1,900 |
| No | 209941164 | GE | NS18H60MA4-** | NCUC60CT4 | NF80U110T5C-* | 38,000 | $1,900 |
| No | 209941266 | GE | NS18H60MA4-** | NCUU60CP4+TXV | NF96U110V5C-* | 38,000 | $1,900 |
| No | 209941255 | GE | NS18H60MA4-** | NCUU60CP4+TXV | NF96U090V5C-* | 38,000 | $1,900 |
| No | 209941167 | GE | NS18H60MA4-** | NCUU60CP4+TXV | NF80U110V5C-* | 38,000 | $1,900 |
| No | 209941162 | GE | NS18H60MA4-** | NCUU60CP4+TXV | NF80U110T5C-* | 38,000 | $1,900 |
| No | 209941286 | GE | NS18H60MA4-** | NAM60V1TA4-** | | 38,500 | $1,925 |
| No | 209941271 | GE | NS18H60MA4-** | NCUC49CT4 | NF96U110V5C-* | 30,600 | $1,530 |
| No | 209941262 | GE | NS18H60MA4-** | NCUC49CT4 | NF96U090V5C-* | 30,800 | $1,540 |
| No | 209941174 | GE | NS18H60MA4-** | NCUC49CT4 | NF80U110V5C-* | 30,400 | $1,520 |
| No | 209941121 | GE | NS18H60MA4-** | NCUC49CT4 | NF80U110S5C-* | 30,400 | $1,520 |
| No | 209941112 | GE | NS18H60MA4-** | NCUC49CT4 | NF80X100S5C-* | 30,600 | $1,530 |
| No | 209941270 | GE | NS18H60MA4-** | NCUU49CP4+TXV | NF96U110V5C-* | 30,600 | $1,530 |
| No | 209941260 | GE | NS18H60MA4-** | NCUU49CP4+TXV | NF96U090V5C-* | 30,800 | $1,540 |
| No | 209941172 | GE | NS18H60MA4-** | NCUU49CP4+TXV | NF80U110V5C-* | 30,400 | $1,520 |
| No | 209941119 | GE | NS18H60MA4-** | NCUU49CP4+TXV | NF80U110S5C-* | 30,400 | $1,520 |
| No | 209941110 | GE | NS18H60MA4-** | NCUU49CP4+TXV | NF80X100S5C-* | 30,600 | $1,530 |
| No | 209941175 | GE | NS18H60MA4-** | NCHC48CT4 | NF80U110V5C-* | 31,000 | $1,550 |
| No | 209941272 | GE | NS18H60MA4-** | NCHC48CT4 | NF96U110V5C-* | 31,200 | $1,560 |
| No | 209941263 | GE | NS18H60MA4-** | NCHC48CT4 | NF96U090V5C-* | 31,400 | $1,570 |
| No | 209941166 | GE | NS18H60MA4-** | NCHC48CT4 | NF80U110T5C-* | 31,000 | $1,550 |
| No | 209941122 | GE | NS18H60MA4-** | NCHC48CT4 | NF80U110S5C-* | 30,800 | $1,540 |
| No | 209941104 | GE | NS18H60MA4-** | NCHC48CT4 | NF80U090S5C-* | 30,800 | $1,540 |
| No | 209941289 | GE | NS18H60MA4-** | NAM48E1TA4-** | | 31,600 | $1,580 |
| No | 209941288 | GE | NS18H60MA4-** | NAM48P1TA4 | | 31,600 | $1,580 |
| No | 209941290 | GE | NS18H60MA4-** | NAM48V1TA4-** | | 31,400 | $1,570 |
| No | 209941071 | GE | NS18H36MA4-** | NCUU48BP4+TXV | NF80U070S3B-* | 21,600 | $1,080 |
| No | 209941156 | GE | NS18H36MA4-** | NCUC36BT4 | NF80U090V4B-* | 22,800 | $1,140 |
| No | 209941154 | GE | NS18H36MA4-** | NCUU36BP4+TXV | NF80U090V4B-* | 22,800 | $1,140 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 209941214 | GE | NS18H36MA4-** | NCHC30BT4 | NF96U045S3B-* | 15,900 | $795 |
| No | 209941144 | GE | NS18H36MA4-** | NCHC30AT4 | NF80U070V3A-* | 15,600 | $780 |
| No | 209941143 | GE | NS18H36MA4-** | NCUC30AT4 | NF80U070V3A-* | 15,600 | $780 |
| No | 209941211 | GE | NS18H36MA4-** | NCUU30BP4+TXV | NF96U045S3B-* | 15,900 | $795 |
| No | 209941141 | GE | NS18H36MA4-** | NCUU30AP4+TXV | NF80U070V3A-* | 15,600 | $780 |
| No | 209941311 | GE | NS18H36MA4-** | NCUC24BT4 | NF96U070S3B-* | 16,300 | $815 |
| No | 209941212 | GE | NS18H36MA4-** | NCUC24BT4 | NF96U045S3B-* | 16,300 | $815 |
| No | 209941142 | GE | NS18H36MA4-** | NCUC24AT4 | NF80U070V3A-* | 16,000 | $800 |
| No | 209941310 | GE | NS18H36MA4-** | NCUU24BP4+TXV | NF96U070S3B-* | 16,300 | $815 |
| No | 209941210 | GE | NS18H36MA4-** | NCUU24BP4+TXV | NF96U045S3B-* | 16,300 | $815 |
| No | 209941140 | GE | NS18H36MA4-** | NCUU24AP4+TXV | NF80U070V3A-* | 16,000 | $800 |
| No | 209941248 | GE | NS18H36MA4-** | NCHC48BT4 | NF96U070V3B-* | 22,400 | $1,120 |
| No | 209941240 | GE | NS18H36MA4-** | NCHC48BT4 | NF96U045V3B-* | 22,400 | $1,120 |
| No | 209941220 | GE | NS18H36MA4-** | NCHC48BT4 | NF96U070S3B-* | 22,000 | $1,100 |
| No | 209941159 | GE | NS18H36MA4-** | NCHC48BT4 | NF80U090V4B-* | 22,400 | $1,120 |
| No | 209941150 | GE | NS18H36MA4-** | NCHC48BT4 | NF80U090T4B-* | 22,200 | $1,110 |
| No | 209941094 | GE | NS18H36MA4-** | NCHC48BT4 | NF80U090S4B-* | 22,000 | $1,100 |
| No | 209941075 | GE | NS18H36MA4-** | NCHC48BT4 | NF80U070S3B-* | 22,000 | $1,100 |
| No | 209941247 | GE | NS18H36MA4-** | NCHC36BT4 | NF96U070V3B-* | 22,200 | $1,110 |
| No | 209941239 | GE | NS18H36MA4-** | NCHC36BT4 | NF96U045V3B-* | 22,400 | $1,120 |
| No | 209941219 | GE | NS18H36MA4-** | NCHC36BT4 | NF96U070S3B-* | 21,800 | $1,090 |
| No | 209941158 | GE | NS18H36MA4-** | NCHC36BT4 | NF80U090V4B-* | 22,000 | $1,100 |
| No | 209941149 | GE | NS18H36MA4-** | NCHC36BT4 | NF80U090T4B-* | 22,200 | $1,110 |
| No | 209941093 | GE | NS18H36MA4-** | NCHC36BT4 | NF80U090S4B-* | 22,000 | $1,100 |
| No | 209941085 | GE | NS18H36MA4-** | NCHC36BT4 | NF80X080S4B-* | 22,200 | $1,110 |
| No | 209941074 | GE | NS18H36MA4-** | NCHC36BT4 | NF80U070S3B-* | 22,000 | $1,100 |
| No | 209941254 | GE | NS18H36MA4-** | NCUC48CT4 | NF96U090V3C-* | 21,600 | $1,080 |
| No | 209941225 | GE | NS18H36MA4-** | NCUC48CT4 | NF96U090S4C-* | 21,600 | $1,080 |
| No | 209941246 | GE | NS18H36MA4-** | NCUC48BT4 | NF96U070V3B-* | 21,800 | $1,090 |
| No | 209941238 | GE | NS18H36MA4-** | NCUC48BT4 | NF96U045V3B-* | 21,800 | $1,090 |
| No | 209941218 | GE | NS18H36MA4-** | NCUC48BT4 | NF96U070S3B-* | 21,400 | $1,070 |
| No | 209941207 | GE | NS18H36MA4-** | NCUC48BT4 | NF96U045S3B-* | 21,400 | $1,070 |
| No | 209941157 | GE | NS18H36MA4-** | NCUC48BT4 | NF80U090V4B-* | 21,600 | $1,080 |
| No | 209941148 | GE | NS18H36MA4-** | NCUC48BT4 | NF80U090T4B-* | 21,600 | $1,080 |
| No | 209941092 | GE | NS18H36MA4-** | NCUC48BT4 | NF80U090S4B-* | 21,600 | $1,080 |
| No | 209941084 | GE | NS18H36MA4-** | NCUC48BT4 | NF80X080S4B-* | 21,800 | $1,090 |
| No | 209941073 | GE | NS18H36MA4-** | NCUC48BT4 | NF80U070S3B-* | 21,600 | $1,080 |
| No | 209941253 | GE | NS18H36MA4-** | NCUU48CP4+TXV | NF96U090V3C-* | 21,600 | $1,080 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 209941224 | GE | NS18H36MA4-** | NCUU48CP4+TXV | NF96U090S4C-* | 21,600 | $1,080 |
| No | 209941244 | GE | NS18H36MA4-** | NCUU48BP4+TXV | NF96U070V3B-* | 21,800 | $1,090 |
| No | 209941236 | GE | NS18H36MA4-** | NCUU48BP4+TXV | NF96U045V3B-* | 21,800 | $1,090 |
| No | 209941216 | GE | NS18H36MA4-** | NCUU48BP4+TXV | NF96U070S3B-* | 21,400 | $1,070 |
| No | 209941205 | GE | NS18H36MA4-** | NCUU48BP4+TXV | NF96U045S3B-* | 21,400 | $1,070 |
| No | 209941155 | GE | NS18H36MA4-** | NCUU48BP4+TXV | NF80U090V4B-* | 21,600 | $1,080 |
| No | 209941146 | GE | NS18H36MA4-** | NCUU48BP4+TXV | NF80U090T4B-* | 21,600 | $1,080 |
| No | 209941090 | GE | NS18H36MA4-** | NCUU48BP4+TXV | NF80U090S4B-* | 21,600 | $1,080 |
| No | 209941082 | GE | NS18H36MA4-** | NCUU48BP4+TXV | NF80X080S4B-* | 21,800 | $1,090 |
| No | 209941245 | GE | NS18H36MA4-** | NCUC36BT4 | NF96U070V3B-* | 22,800 | $1,140 |
| No | 209941237 | GE | NS18H36MA4-** | NCUC36BT4 | NF96U045V3B-* | 23,000 | $1,150 |
| No | 209941217 | GE | NS18H36MA4-** | NCUC36BT4 | NF96U070S3B-* | 22,400 | $1,120 |
| No | 209941147 | GE | NS18H36MA4-** | NCUC36BT4 | NF80U090T4B-* | 22,800 | $1,140 |
| No | 209941091 | GE | NS18H36MA4-** | NCUC36BT4 | NF80U090S4B-* | 22,600 | $1,130 |
| No | 209941083 | GE | NS18H36MA4-** | NCUC36BT4 | NF80X080S4B-* | 22,800 | $1,140 |
| No | 209941072 | GE | NS18H36MA4-** | NCUC36BT4 | NF80U070S3B-* | 22,600 | $1,130 |
| No | 209941132 | GE | NS18H36MA4-** | NCUC36AT4 | NF80U070T3A-* | 22,800 | $1,140 |
| No | 209941069 | GE | NS18H36MA4-** | NCUC36AT4 | NF80U070S3A-* | 22,600 | $1,130 |
| No | 209941062 | GE | NS18H36MA4-** | NCUC36AT4 | NF80X060S3A-* | 22,400 | $1,120 |
| No | 209941057 | GE | NS18H36MA4-** | NCUC36AT4 | NF80U045S3A-* | 22,400 | $1,120 |
| No | 209941243 | GE | NS18H36MA4-** | NCUU36BP4+TXV | NF96U070V3B-* | 22,800 | $1,140 |
| No | 209941235 | GE | NS18H36MA4-** | NCUU36BP4+TXV | NF96U045V3B-* | 23,000 | $1,150 |
| No | 209941145 | GE | NS18H36MA4-** | NCUU36BP4+TXV | NF80U090T4B-* | 22,800 | $1,140 |
| No | 209941089 | GE | NS18H36MA4-** | NCUU36BP4+TXV | NF80U090S4B-* | 22,600 | $1,130 |
| No | 209941081 | GE | NS18H36MA4-** | NCUU36BP4+TXV | NF80X080S4B-* | 22,800 | $1,140 |
| No | 209941070 | GE | NS18H36MA4-** | NCUU36BP4+TXV | NF80U070S3B-* | 22,600 | $1,130 |
| No | 209941131 | GE | NS18H36MA4-** | NCUU36AP4+TXV | NF80U070T3A-* | 22,800 | $1,140 |
| No | 209941068 | GE | NS18H36MA4-** | NCUU36AP4+TXV | NF80U070S3A-* | 22,600 | $1,130 |
| No | 209941061 | GE | NS18H36MA4-** | NCUU36AP4+TXV | NF80X060S3A-* | 22,400 | $1,120 |
| No | 209941056 | GE | NS18H36MA4-** | NCUU36AP4+TXV | NF80U045S3A-* | 22,400 | $1,120 |
| No | 209941276 | GE | NS18H36MA4-** | NAM36P1TA4 | | 22,400 | $1,120 |
| No | 209941278 | GE | NS18H36MA4-** | NAM42E1TA4-** | | 22,200 | $1,110 |
| No | 209941277 | GE | NS18H36MA4-** | NAM36E1TA4-** | | 22,600 | $1,130 |
| No | 209941279 | GE | NS18H36MA4-** | NAM42V1TA4-** | | 22,200 | $1,110 |
| No | 209941275 | GE | NS18H36MA4-** | NAM36V1TA4-** | | 22,000 | $1,100 |
| No | 209941315 | GE | NS18H36MA4-** | NCHC30BT4 | NF96U070V3B-* | 15,500 | $775 |
| No | 209941314 | GE | NS18H36MA4-** | NCHC30BT4 | NF96U045V3B-* | 15,600 | $780 |
| No | 209941223 | GE | NS18H36MA4-** | NCHC30BT4 | NF96U070S3B-* | 15,900 | $795 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 209941080 | GE | NS18H36MA4-** | NCHC30BT4 | NF80U070S3B-* | 15,500 | $775 |
| No | 209941137 | GE | NS18H36MA4-** | NCHC30AT4 | NF80U070T3A-* | 15,800 | $790 |
| No | 209941130 | GE | NS18H36MA4-** | NCHC30AT4 | NF80U045T3A-* | 15,400 | $770 |
| No | 209941067 | GE | NS18H36MA4-** | NCHC30AT4 | NF80X060S3A-* | 15,700 | $785 |
| No | 209941060 | GE | NS18H36MA4-** | NCHC30AT4 | NF80U045S3A-* | 15,700 | $785 |
| No | 209941055 | GE | NS18H36MA4-** | NCHC30AT4 | NF80X040S3A-* | 15,700 | $785 |
| No | 209941252 | GE | NS18H36MA4-** | NCUC30BT4 | NF96U070V3B-* | 15,500 | $775 |
| No | 209941313 | GE | NS18H36MA4-** | NCUC30BT4 | NF96U045V3B-* | 15,600 | $780 |
| No | 209941222 | GE | NS18H36MA4-** | NCUC30BT4 | NF96U070S3B-* | 15,900 | $795 |
| No | 209941079 | GE | NS18H36MA4-** | NCUC30BT4 | NF80U070S3B-* | 15,600 | $780 |
| No | 209941136 | GE | NS18H36MA4-** | NCUC30AT4 | NF80U070T3A-* | 15,800 | $790 |
| No | 209941129 | GE | NS18H36MA4-** | NCUC30AT4 | NF80U045T3A-* | 15,800 | $790 |
| No | 209941066 | GE | NS18H36MA4-** | NCUC30AT4 | NF80X060S3A-* | 15,800 | $790 |
| No | 209941059 | GE | NS18H36MA4-** | NCUC30AT4 | NF80U045S3A-* | 15,700 | $785 |
| No | 209941054 | GE | NS18H36MA4-** | NCUC30AT4 | NF80X040S3A-* | 15,800 | $790 |
| No | 209941250 | GE | NS18H36MA4-** | NCUU30BP4+TXV | NF96U070V3B-* | 15,500 | $775 |
| No | 209941312 | GE | NS18H36MA4-** | NCUU30BP4+TXV | NF96U045V3B-* | 15,600 | $780 |
| No | 209941221 | GE | NS18H36MA4-** | NCUU30BP4+TXV | NF96U070S3B-* | 15,900 | $795 |
| No | 209941077 | GE | NS18H36MA4-** | NCUU30BP4+TXV | NF80U070S3B-* | 15,600 | $780 |
| No | 209941134 | GE | NS18H36MA4-** | NCUU30AP4+TXV | NF80U070T3A-* | 15,800 | $790 |
| No | 209941127 | GE | NS18H36MA4-** | NCUU30AP4+TXV | NF80U045T3A-* | 15,800 | $790 |
| No | 209941064 | GE | NS18H36MA4-** | NCUU30AP4+TXV | NF80X060S3A-* | 15,800 | $790 |
| No | 209941058 | GE | NS18H36MA4-** | NCUU30AP4+TXV | NF80U045S3A-* | 15,700 | $785 |
| No | 209941052 | GE | NS18H36MA4-** | NCUU30AP4+TXV | NF80X040S3A-* | 15,800 | $790 |
| No | 209941251 | GE | NS18H36MA4-** | NCUC24BT4 | NF96U070V3B-* | 15,900 | $795 |
| No | 209941242 | GE | NS18H36MA4-** | NCUC24BT4 | NF96U045V3B-* | 16,000 | $800 |
| No | 209941078 | GE | NS18H36MA4-** | NCUC24BT4 | NF80U070S3B-* | 15,900 | $795 |
| No | 209941135 | GE | NS18H36MA4-** | NCUC24AT4 | NF80U070T3A-* | 16,100 | $805 |
| No | 209941065 | GE | NS18H36MA4-** | NCUC24AT4 | NF80X060S3A-* | 16,100 | $805 |
| No | 209941053 | GE | NS18H36MA4-** | NCUC24AT4 | NF80X040S3A-* | 16,100 | $805 |
| No | 209941241 | GE | NS18H36MA4-** | NCUU24BP4+TXV | NF96U045V3B-* | 16,000 | $800 |
| No | 209941249 | GE | NS18H36MA4-** | NCUU24BP4+TXV | NF96U070V3B-* | 15,900 | $795 |
| No | 209941076 | GE | NS18H36MA4-** | NCUU24BP4+TXV | NF80U070S3B-* | 15,900 | $795 |
| No | 209941133 | GE | NS18H36MA4-** | NCUU24AP4+TXV | NF80U070T3A-* | 16,100 | $805 |
| No | 209941063 | GE | NS18H36MA4-** | NCUU24AP4+TXV | NF80X060S3A-* | 16,100 | $805 |
| No | 209941051 | GE | NS18H36MA4-** | NCUU24AP4+TXV | NF80X040S3A-* | 16,100 | $805 |
| No | 209941316 | GE | NS18H36MA4-** | NAM30V1TA4-** | | 15,900 | $795 |
| No | 209941284 | GE | NS18H36MA4-** | NAM18V1TA4-** | | 15,900 | $795 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 209941283 | GE | NS18H36MA4-** | NAM30E1TA4-** | | 15,900 | $795 |
| No | 209941282 | GE | NS18H36MA4-** | NAM24E1TA4-** | | 15,000 | $750 |
| No | 209941281 | GE | NS18H36MA4-** | NAM24P1TA4 | | 16,100 | $805 |
| No | 209941280 | GE | NS18H36MA4-** | NAM18P1TA4 | | 15,400 | $770 |
| No | 209941285 | GE | NS18H36MA4-** | NAM24V1TA4-** | | 16,100 | $805 |
| No | 209941197 | GE | NS18H60MA4-** | NCUC60CT4 | NF95X100S5C-* | 38,000 | $1,900 |
| No | 209941195 | GE | NS18H60MA4-** | NCUU60CP4+TXV | NF95X100S5C-* | 38,000 | $1,900 |
| No | 209941287 | GE | NS18H60MA4-** | NAM60E1TA4-** | 0.0 | 37,800 | $1,890 |
| No | 209941183 | GE | NS18H36MA4-** | NCHC30BT4 | NF95X040S3B-* | 15,400 | $770 |
| No | 209941213 | GE | NS18H36MA4-** | NCUC30BT4 | NF96U045S3B-* | 15,400 | $770 |
| No | 209941182 | GE | NS18H36MA4-** | NCUC30BT4 | NF95X040S3B-* | 15,500 | $775 |
| No | 209941128 | GE | NS18H36MA4-** | NCUC24AT4 | NF80U045T3A-* | 15,300 | $765 |
| No | 209941181 | GE | NS18H36MA4-** | NCUU30BP4+TXV | NF95X040S3B-* | 15,500 | $775 |
| No | 209941126 | GE | NS18H36MA4-** | NCUU24AP4+TXV | NF80U045T3A-* | 15,300 | $765 |
| No | 209941209 | GE | NS18H36MA4-** | NCHC48BT4 | NF96U045S3B-* | 22,000 | $1,100 |
| No | 209941190 | GE | NS18H36MA4-** | NCUC48CT4 | NF95X080S4C-* | 22,000 | $1,100 |
| No | 209941187 | GE | NS18H36MA4-** | NCUC48BT4 | NF95X060S3B-* | 22,000 | $1,100 |
| No | 209941179 | GE | NS18H36MA4-** | NCUC48BT4 | NF95X040S3B-* | 22,000 | $1,100 |
| No | 209941206 | GE | NS18H36MA4-** | NCUC36BT4 | NF96U045S3B-* | 22,600 | $1,130 |
| No | 209941186 | GE | NS18H36MA4-** | NCUC36BT4 | NF95X060S3B-* | 22,000 | $1,100 |
| No | 209941178 | GE | NS18H36MA4-** | NCUC36BT4 | NF95X040S3B-* | 22,000 | $1,100 |
| No | 209941139 | GE | NS18H36MA4-** | NCUC36AT4 | NF80U070V3A-* | 22,200 | $1,110 |
| No | 209941189 | GE | NS18H36MA4-** | NCUU48CP4+TXV | NF95X080S4C-* | 22,200 | $1,110 |
| No | 209941185 | GE | NS18H36MA4-** | NCUU48BP4+TXV | NF95X060S3B-* | 22,200 | $1,110 |
| No | 209941177 | GE | NS18H36MA4-** | NCUU48BP4+TXV | NF95X040S3B-* | 22,200 | $1,110 |
| No | 209941215 | GE | NS18H36MA4-** | NCUU36BP4+TXV | NF96U070S3B-* | 22,600 | $1,130 |
| No | 209941204 | GE | NS18H36MA4-** | NCUU36BP4+TXV | NF96U045S3B-* | 22,600 | $1,130 |
| No | 209941184 | GE | NS18H36MA4-** | NCUU36BP4+TXV | NF95X060S3B-* | 22,000 | $1,100 |
| No | 209941176 | GE | NS18H36MA4-** | NCUU36BP4+TXV | NF95X040S3B-* | 22,000 | $1,100 |
| No | 209941138 | GE | NS18H36MA4-** | NCUU36AP4+TXV | NF80U070V3A-* | 22,200 | $1,110 |
| No | 211729714 | GE Appliances | ASH4248UCDD** | USYM48UCDD** | | 34,600 | $1,730 |
| No | 211744614 | GE Appliances | ASH4248UCDD** | USYL42UCDD** | | 31,000 | $1,550 |
| No | 211729713 | GE Appliances | ASH4248UCDD** | USYM42UCDD** | | 31,600 | $1,580 |
| No | 211744613 | GE Appliances | ASH3036UCDD** | ASYW36TRDF** | | 25,600 | $1,280 |
| No | 211744612 | GE Appliances | ASH3036UCDD** | USYL36UCDD** | | 26,000 | $1,300 |
| No | 211727013 | GE Appliances | ASH3036UCDD** | USYM36UCDD** | | 26,800 | $1,340 |
| No | 211744611 | GE Appliances | ASH3036UCDD** | ASYW30TRDF** | | 21,400 | $1,070 |
| No | 211727012 | GE Appliances | ASH3036UCDD** | USYM30UCDD** | | 22,000 | $1,100 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211744608 | GE Appliances | ASH124UCDD** | USYL24UCDD** | | 17,400 | $870 |
| No | 211727011 | GE Appliances | ASH124UCDD** | USYM24UCDD** | | 17,400 | $870 |
| No | 210532847 | GE APPLIANCES | ASH542JCDD** | Heat pump with ducts | | 26,000 | $1,300 |
| No | 210532846 | GE APPLIANCES | ASH542JCDD** | Heat pump without ducts | | 24,000 | $1,200 |
| No | 210154197 | GE APPLIANCES | ASH436NCDD** | Heat pump with ducts | | 20,000 | $1,000 |
| No | 207783954 | GE APPLIANCES | ASH124CRDD** | ASYW24CRDD** | | 15,000 | $750 |
| No | 207783953 | GE APPLIANCES | ASH118CRDD** | ASYW18CRDD** | | 11,400 | $570 |
| No | 206842136 | GE APPLIANCES | ASH112URDSE* | USYM12UCDSA* | | 9,300 | $465 |
| No | 206842135 | GE APPLIANCES | ASH109URDSE* | USYM09UCDSA* | | 6,500 | $325 |
| No | 202588314 | GE APPLIANCES | ASH124PRDWA | ASYW24PRDWB | | 19,000 | $950 |
| No | 202588313 | GE APPLIANCES | ASH118PRDWA | ASYW18PRDWB | | 14,000 | $700 |
| No | 202588312 | GE APPLIANCES | ASH115PRDWA | ASYW15PRDWB | | 12,000 | $600 |
| No | 202588311 | GE APPLIANCES | ASH112PRDWA | ASYW12PRDWB | | 10,700 | $535 |
| No | 206842142 | GE APPLIANCES | ASH112URDSE* | AB12SC2VHA* | | 8,500 | $425 |
| No | 206842139 | GE APPLIANCES | ASH112URDSE* | USYF12UCDWA* | | 8,500 | $425 |
| No | 206842138 | GE APPLIANCES | ASH109URDSE* | USYF09UCDWA* | | 6,000 | $300 |
| No | 206842132 | GE APPLIANCES | ASH109URDSE* | ASYW09URDWD* | | 6,500 | $325 |
| No | 206842133 | GE APPLIANCES | ASH112URDSE* | ASYW12URDWD* | | 9,300 | $465 |
| No | 207698999 | GE APPLIANCES | ASH324JCDD** | Unités sans conduits | | 15,000 | $750 |
| No | 207698997 | GE APPLIANCES | ASH218JCDD** | ASYW09CRDD**,ASYW09CRDD** | | 14,700 | $735 |
| No | 207769100 | GE APPLIANCES | ASYW24TRDF** | ASH124TRDF** | | 16,500 | $825 |
| No | 207722666 | GE APPLIANCES | ASH324JCDD** | USYM07UCDD**,USYM07UCDD**,USYM09UCDSA* | | 15,000 | $750 |
| No | 207722668 | GE APPLIANCES | ASH324JCDD** | Combinaison d'unités avec et sans conduits | | 15,000 | $750 |
| No | 207802919 | GE APPLIANCES | ASH436JCDD** | USYM07UCDD**,USYM09UCDSA*,USYM09UCDSA*,USYM09UCDSA* | | 22,400 | $1,120 |
| No | 207802918 | GE APPLIANCES | ASH436JCDD** | ASYW07CRDD**,ASYW07CRDD**,ASYW07CRDD**, ASYW12CRDD** | | 22,800 | $1,140 |
| No | 208141311 | GE APPLIANCES | ASH436JCDD** | Combinaison d'unités avec et sans conduits | | 22,600 | $1,130 |
| No | 206551251 | GE APPLIANCES | ASH109CRDWA* | ASYW09CRDWA* | | 5,000 | $250 |
| No | 206551252 | GE APPLIANCES | ASH112CRDWA* | ASYW12CRDWA* | | 7,500 | $375 |
| No | 202588310 | GE APPLIANCES | ASH109PRDWA | ASYW09PRDWB | | 6,500 | $325 |
| No | 205291989 | GE APPLIANCES | ASH112URDSD* | ASYW12URDWD* | | 9,300 | $465 |
| No | 205291988 | GE APPLIANCES | ASH109URDSD* | ASYW09URDWD* | | 6,500 | $325 |
| No | 204722821 | GE APPLIANCES | ASH109CRAW** | ASYW09CRAW** | | 6,500 | $325 |
| No | 204722824 | GE APPLIANCES | ASH124CRDW** | ASYW24CRDW** | | 16,000 | $800 |
| No | 204722822 | GE APPLIANCES | ASH112CRAW** | ASYW12CRAW** | | 7,000 | $350 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204722823 | GE APPLIANCES | ASH118CRDW** | ASYW18CRDW** | | 11,200 | $560 |
| No | 209457668 | GENERALLUX | TUM-GL-36HA2/04-ES | TSC-GL-09HA2/I3TI23 ; TSC-GL-12HA2/I3TO23 ; TSC-GL-18HA2/I3TO23 | | 21,200 | $1,060 |
| No | 209457666 | GENERALLUX | TUM-GL-27HA2/03-ES | TSC-GL-09HA2/I3TI23 ; TSC-GL-12HA2/I3TO23 ; TSC-GL-18HA2/I3TO23 | | 18,100 | $905 |
| No | 209457667 | GENERALLUX | TUM-GL-18HA2/02-ES | TSC-GL-09HA2/I3TI23 ; TSC-GL-12HA2/I3TO23 ; TSC-GL-18HA2/I3TO23 | | 12,200 | $610 |
| No | 209457665 | GENERALLUX | TSC-GL-18HA2/I3TO23 | TSC-GL-18HA2/I3TO23 | | 18,000 | $900 |
| No | 209457664 | GENERALLUX | TSC-GL-12HA2/I3TO23 | TSC-GL-12HA2/I3TO23 | | 12,000 | $600 |
| No | 209457663 | GENERALLUX | TSC-GL-09HA2/I3TO23 | TSC-GL-09HA2/I3TI23 | | 9,500 | $475 |
| No | 206733681 | GENERALLUX STAR | AST-24UW3SDBTU01(O) | AST-24UW3SDBTU01(I) | | 14,500 | $725 |
| No | 206733680 | GENERALLUX STAR | AST-18UW3SBBTU00(O) | AST-18UW3SBBTU00(I) | | 11,600 | $580 |
| No | 206733678 | GENERALLUX STAR | AST-12UW3SXETU01(O) | AST-12UW3SXETU01(I) | | 7,500 | $375 |
| No | 210692863 | GOODMAN | GSZV906010A* | CSCF4860N6D*+TXV | G*VM971205DNB* | 32,400 | $1,620 |
| No | 210692862 | GOODMAN | GSZV906010A* | CSCF4860N6D*+TXV | G*VM971005CNB* | 32,400 | $1,620 |
| No | 210692861 | GOODMAN | GSZV906010A* | CSCF4860N6D*+TXV | G*VC961205DNB* | 32,400 | $1,620 |
| No | 210692860 | GOODMAN | GSZV906010A* | CSCF4860N6D*+TXV | G*VC961005CNB* | 32,400 | $1,620 |
| No | 210692859 | GOODMAN | GSZV906010A* | CSCF4860N6D*+TXV | G*VS960805CUA* | 32,400 | $1,620 |
| No | 210692855 | GOODMAN | GSZV906010A* | CHPF4860D6D*+TXV | G*VM971205DNB* | 32,400 | $1,620 |
| No | 210692854 | GOODMAN | GSZV906010A* | CHPF4860D6D*+TXV | G*VM971005CNB* | 32,400 | $1,620 |
| No | 210692853 | GOODMAN | GSZV906010A* | CHPF4860D6D*+TXV | G*VC961205DNB* | 32,400 | $1,620 |
| No | 210692852 | GOODMAN | GSZV906010A* | CHPF4860D6D*+TXV | G*VC961005CNB* | 32,400 | $1,620 |
| No | 210692851 | GOODMAN | GSZV906010A* | CHPF4860D6D*+TXV | G*VS960805CUA* | 32,400 | $1,620 |
| No | 210692847 | GOODMAN | GSZV906010A* | CHPF4860D6D*+MBVC2001**-1A*+TXV | | 32,400 | $1,620 |
| No | 210692846 | GOODMAN | GSZV906010A* | CA*F4961*6D*+TXV | G*VM971205DNB* | 33,400 | $1,670 |
| No | 210692845 | GOODMAN | GSZV906010A* | CA*F4961*6D*+TXV | G*VM971005CNB* | 33,400 | $1,670 |
| No | 210692844 | GOODMAN | GSZV906010A* | CA*F4961*6D*+TXV | G*VC961205DNB* | 33,400 | $1,670 |
| No | 210692843 | GOODMAN | GSZV906010A* | CA*F4961*6D*+TXV | G*VC961005CNB* | 33,400 | $1,670 |
| No | 210692842 | GOODMAN | GSZV906010A* | CA*F4961*6D*+TXV | G*VS960805CUA* | 33,400 | $1,670 |
| No | 210607422 | GOODMAN | GSZV906010A* | CA*F4961*6D*+MBVC2001**-1A*+TX | | 34,000 | $1,700 |
| No | 210609989 | GOODMAN | GSZV906010A* | AMVE60DP1400A* | | 33,400 | $1,670 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210692838 | GOODMAN | GSZV904810A* | CSCF4860N6D*+TXV | G*VM971205DNB* | 27,000 | $1,350 |
| No | 210692837 | GOODMAN | GSZV904810A* | CSCF4860N6D*+TXV | G*VM971005CNB* | 27,000 | $1,350 |
| No | 210692836 | GOODMAN | GSZV904810A* | CSCF4860N6D*+TXV | G*VM970804CNB* | 27,000 | $1,350 |
| No | 210692835 | GOODMAN | GSZV904810A* | CSCF4860N6D*+TXV | G*VC961205DNB* | 27,000 | $1,350 |
| No | 210692834 | GOODMAN | GSZV904810A* | CSCF4860N6D*+TXV | G*VC961005CNB* | 27,000 | $1,350 |
| No | 210692833 | GOODMAN | GSZV904810A* | CSCF4860N6D*+TXV | G*VS960805CUA* | 27,000 | $1,350 |
| No | 210692832 | GOODMAN | GSZV904810A* | CSCF4860N6D*+TXV | G*VC960804CNB* | 27,000 | $1,350 |
| No | 210692826 | GOODMAN | GSZV904810A* | CSCF4860N6D*+MBVC2001**-1A*+TXV | | 27,000 | $1,350 |
| No | 210692825 | GOODMAN | GSZV904810A* | CSCF4860N6D*+MBVC1601**-1A*+TXV | | 27,000 | $1,350 |
| No | 210692824 | GOODMAN | GSZV904810A* | CHPF4860D6D*+TXV | G*VM971205DNB* | 27,000 | $1,350 |
| No | 210692823 | GOODMAN | GSZV904810A* | CHPF4860D6D*+TXV | G*VM971005CNB* | 27,000 | $1,350 |
| No | 210692822 | GOODMAN | GSZV904810A* | CHPF4860D6D*+TXV | G*VM970804CNB* | 27,000 | $1,350 |
| No | 210692821 | GOODMAN | GSZV904810A* | CHPF4860D6D*+TXV | G*VC961205DNB* | 27,000 | $1,350 |
| No | 210692820 | GOODMAN | GSZV904810A* | CHPF4860D6D*+TXV | G*VC961005CNB* | 27,000 | $1,350 |
| No | 210692819 | GOODMAN | GSZV904810A* | CHPF4860D6D*+TXV | G*VC960804CNB* | 27,000 | $1,350 |
| No | 210692815 | GOODMAN | GSZV904810A* | CHPF4860D6D*+MBVC2001**-1A*+TXV | | 27,000 | $1,350 |
| No | 210692814 | GOODMAN | GSZV904810A* | CHPF4860D6D*+MBVC1601**-1A*+TXV | | 27,000 | $1,350 |
| No | 210692813 | GOODMAN | GSZV904810A* | CA*F4961*6D*+TXV | G*VM971205DNB* | 27,000 | $1,350 |
| No | 210692812 | GOODMAN | GSZV904810A* | CA*F4961*6D*+TXV | G*VM971005CNB* | 27,000 | $1,350 |
| No | 210692811 | GOODMAN | GSZV904810A* | CA*F4961*6D*+TXV | G*VM970804CNB* | 27,000 | $1,350 |
| No | 210692810 | GOODMAN | GSZV904810A* | CA*F4961*6D*+TXV | G*VC961205DNB* | 27,000 | $1,350 |
| No | 210692809 | GOODMAN | GSZV904810A* | CA*F4961*6D*+TXV | G*VC961005CNB* | 27,000 | $1,350 |
| No | 210692808 | GOODMAN | GSZV904810A* | CA*F4961*6D*+TXV | G*VS960805CUA* | 27,000 | $1,350 |
| No | 210692807 | GOODMAN | GSZV904810A* | CA*F4961*6D*+TXV | G*VC960804CNB* | 27,000 | $1,350 |
| No | 210607416 | GOODMAN | GSZV904810A* | CA*F4961*6D*+MBVC2001**-1A*+TX | | 27,000 | $1,350 |
| No | 210692801 | GOODMAN | GSZV904810A* | CA*F4961*6D*+MBVC1601**-1A*+TXV | | 27,000 | $1,350 |
| No | 210692800 | GOODMAN | GSZV904810A* | CA*F4860*6D*+TXV | G*VM971205DNB* | 27,000 | $1,350 |
| No | 210692799 | GOODMAN | GSZV904810A* | CA*F4860*6D*+TXV | G*VM971005CNB* | 27,000 | $1,350 |
| No | 210692798 | GOODMAN | GSZV904810A* | CA*F4860*6D*+TXV | G*VM970804CNB* | 27,000 | $1,350 |
| No | 210692797 | GOODMAN | GSZV904810A* | CA*F4860*6D*+TXV | G*VC961205DNB* | 27,000 | $1,350 |
| No | 210692796 | GOODMAN | GSZV904810A* | CA*F4860*6D*+TXV | G*VC961005CNB* | 27,000 | $1,350 |
| No | 210692795 | GOODMAN | GSZV904810A* | CA*F4860*6D*+TXV | G*VS960805CUA* | 27,000 | $1,350 |
| No | 210692794 | GOODMAN | GSZV904810A* | CA*F4860*6D*+TXV | G*VC960804CNB* | 27,000 | $1,350 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210692789 | GOODMAN | GSZV904810A* | CA*F4860*6D*+MBVC2001**-1A*+TXV | | 27,000 | $1,350 |
| No | 210692788 | GOODMAN | GSZV904810A* | CA*F4860*6D*+MBVC1601**-1A*+TXV | | 27,000 | $1,350 |
| No | 210609979 | GOODMAN | GSZV904810A* | AMVE60DP1400A* | | 27,000 | $1,350 |
| No | 210609978 | GOODMAN | GSZV904810A* | AMVE48DP1400A* | | 27,000 | $1,350 |
| No | 210692699 | GOODMAN | GSZV902410A* | CSCF3642N6D*+TXV | G*VM970804CNB* | 14,200 | $710 |
| No | 210692698 | GOODMAN | GSZV902410A* | CSCF3642N6D*+TXV | G*VM970803BNB* | 14,200 | $710 |
| No | 210692697 | GOODMAN | GSZV902410A* | CSCF3642N6D*+TXV | G*VM970603BNB* | 14,200 | $710 |
| No | 210692696 | GOODMAN | GSZV902410A* | CSCF3642N6D*+TXV | G*VC960804CNB* | 14,200 | $710 |
| No | 210692695 | GOODMAN | GSZV902410A* | CSCF3642N6D*+TXV | G*VC960803BNB* | 14,200 | $710 |
| No | 210692694 | GOODMAN | GSZV902410A* | CSCF3642N6D*+TXV | G*VC960603BNB* | 14,200 | $710 |
| No | 210692693 | GOODMAN | GSZV902410A* | CSCF3642N6D*+TXV | G*VS960603BUA* | 14,200 | $710 |
| No | 210692692 | GOODMAN | GSZV902410A* | CSCF3642N6D*+TXV | G*VC960403BNB* | 14,200 | $710 |
| No | 210692689 | GOODMAN | GSZV902410A* | CSCF3642N6D*+MBVC1201**-1A*+TXV | | 14,200 | $710 |
| No | 210692688 | GOODMAN | GSZV902410A* | CHPF3642C6C*+MBVC1201**-1A*+TXV | | 14,100 | $705 |
| No | 210692687 | GOODMAN | GSZV902410A* | CHPF3636B6C*+TXV | G*VM970803BNB* | 14,200 | $710 |
| No | 210692686 | GOODMAN | GSZV902410A* | CHPF3636B6C*+TXV | G*VM970603BNB* | 14,200 | $710 |
| No | 210692685 | GOODMAN | GSZV902410A* | CHPF3636B6C*+TXV | G*VC960803BNB* | 14,200 | $710 |
| No | 210692684 | GOODMAN | GSZV902410A* | CHPF3636B6C*+TXV | G*VC960603BNB* | 14,200 | $710 |
| No | 210692683 | GOODMAN | GSZV902410A* | CHPF3636B6C*+TXV | G*VS960603BUA* | 14,200 | $710 |
| No | 210692682 | GOODMAN | GSZV902410A* | CHPF3636B6C*+TXV | G*VC960403BNB* | 14,200 | $710 |
| No | 210692679 | GOODMAN | GSZV902410A* | CHPF3636B6C*+MBVC1201**-1A*+TXV | | 14,200 | $710 |
| No | 210692678 | GOODMAN | GSZV902410A* | CA*F3743*6D*+TXV | G*VM970804CNB* | 14,500 | $725 |
| No | 210692677 | GOODMAN | GSZV902410A* | CA*F3743*6D*+TXV | G*VM970803BNB* | 14,500 | $725 |
| No | 210692676 | GOODMAN | GSZV902410A* | CA*F3743*6D*+TXV | G*VM970603BNB* | 14,500 | $725 |
| No | 210692675 | GOODMAN | GSZV902410A* | CA*F3743*6D*+TXV | G*VC960804CNB* | 14,500 | $725 |
| No | 210692674 | GOODMAN | GSZV902410A* | CA*F3743*6D*+TXV | G*VC960803BNB* | 14,500 | $725 |
| No | 210692673 | GOODMAN | GSZV902410A* | CA*F3743*6D*+TXV | G*VC960603BNB* | 14,600 | $730 |
| No | 210692672 | GOODMAN | GSZV902410A* | CA*F3743*6D*+TXV | G*VS960603BUA* | 14,600 | $730 |
| No | 210692671 | GOODMAN | GSZV902410A* | CA*F3743*6D*+TXV | G*VC960403BNB* | 14,500 | $725 |
| No | 210692668 | GOODMAN | GSZV902410A* | CA*F3743*6D*+MBVC1201**-1A*+TXV | | 14,500 | $725 |
| No | 210692667 | GOODMAN | GSZV902410A* | CA*F3137*6A*+TXV | G*VM970803BNB* | 13,800 | $690 |
| No | 210692666 | GOODMAN | GSZV902410A* | CA*F3137*6A*+TXV | G*VM970603BNB* | 13,800 | $690 |
| No | 210692665 | GOODMAN | GSZV902410A* | CA*F3137*6A*+TXV | G*VC960803BNB* | 13,800 | $690 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210692664 | GOODMAN | GSZV902410A* | CA*F3137*6A*+TXV | G*VC960603BNB* | 13,800 | $690 |
| No | 210692663 | GOODMAN | GSZV902410A* | CA*F3137*6A*+TXV | G*VS960603BUA* | 13,800 | $690 |
| No | 210692662 | GOODMAN | GSZV902410A* | CA*F3137*6A*+TXV | G*VC960403BNB* | 13,800 | $690 |
| No | 210607571 | GOODMAN | GSZV902410A* | CA*F3137*6A*+MBVC1201**-1A*+TX | | 14,000 | $700 |
| No | 210610033 | GOODMAN | GSZV902410A* | AMVE24BP1400A* | | 14,800 | $740 |
| No | 206900426 | GOODMAN | MSH183E23MCAA | MST183E20ACAA | | 15,600 | $780 |
| No | 206900420 | GOODMAN | MSH123E23MCAA | MST123E21ADAA | | 10,600 | $530 |
| No | 206900425 | GOODMAN | MSH123E23MCAA | MST123E20ACAA | | 9,900 | $495 |
| No | 206900419 | GOODMAN | MSH093E23MCAA | MST093E21ADAA | | 10,100 | $505 |
| No | 206900424 | GOODMAN | MSH093E23MCAA | MST093E20ACAA | | 9,000 | $450 |
| No | 206144778 | GOODMAN | GVZC200241A* | CA*F3137*6A*+TXV | G*VC960803BNB* | 13,000 | $650 |
| No | 206144776 | GOODMAN | GVZC200241A* | CA*F3137*6A*+TXV | G*VC960403BNB* | 13,000 | $650 |
| No | 206144777 | GOODMAN | GVZC200241A* | CA*F3137*6A*+TXV | G*VC960603BNB* | 13,000 | $650 |
| No | 206144775 | GOODMAN | GVZC200241A* | CA*F3137*6A*+TXV | G*VC800604B*A* | 13,000 | $650 |
| No | 206144779 | GOODMAN | GVZC200241A* | CA*F3636*6D*+TXV | G*VC800604B*A* | 13,000 | $650 |
| No | 206144780 | GOODMAN | GVZC200241A* | CA*F3636*6D*+TXV | G*VC960403BNB* | 13,000 | $650 |
| No | 206144784 | GOODMAN | GVZC200241A* | CA*F3642*6D*+TXV | G*VC800604B*A* | 13,000 | $650 |
| No | 206144785 | GOODMAN | GVZC200241A* | CA*F3642*6D*+TXV | G*VC960403BNB* | 13,000 | $650 |
| No | 206144783 | GOODMAN | GVZC200241A* | CA*F3636*6D*+TXV | G*VC960804CNB* | 13,000 | $650 |
| No | 206144781 | GOODMAN | GVZC200241A* | CA*F3636*6D*+TXV | G*VC960603BNB* | 13,000 | $650 |
| No | 206144782 | GOODMAN | GVZC200241A* | CA*F3636*6D*+TXV | G*VC960803BNB* | 13,000 | $650 |
| No | 206144786 | GOODMAN | GVZC200241A* | CA*F3642*6D*+TXV | G*VC960603BNB* | 13,000 | $650 |
| No | 206144787 | GOODMAN | GVZC200241A* | CA*F3642*6D*+TXV | G*VC960803BNB* | 13,000 | $650 |
| No | 206144790 | GOODMAN | GVZC200241A* | CA*F3743*6D*+TXV | G*VC960403BNB* | 13,000 | $650 |
| No | 206144788 | GOODMAN | GVZC200241A* | CA*F3642*6D*+TXV | G*VC960804CNB* | 13,000 | $650 |
| No | 206144789 | GOODMAN | GVZC200241A* | CA*F3743*6D*+TXV | G*VC800604B*A* | 13,000 | $650 |
| No | 206144791 | GOODMAN | GVZC200241A* | CA*F3743*6D*+TXV | G*VC960603BNB* | 13,000 | $650 |
| No | 206144792 | GOODMAN | GVZC200241A* | CA*F3743*6D*+TXV | G*VC960803BNB* | 13,000 | $650 |
| No | 206144793 | GOODMAN | GVZC200241A* | CA*F3743*6D*+TXV | G*VC960804CNB* | 13,000 | $650 |
| No | 206144794 | GOODMAN | GVZC200241A* | CHPF3636B6C*+TXV | G*VC800604B*A* | 13,000 | $650 |
| No | 206144795 | GOODMAN | GVZC200241A* | CHPF3636B6C*+TXV | G*VC960403BNB* | 13,000 | $650 |
| No | 206144796 | GOODMAN | GVZC200241A* | CHPF3636B6C*+TXV | G*VC960603BNB* | 13,000 | $650 |
| No | 206144797 | GOODMAN | GVZC200241A* | CHPF3636B6C*+TXV | G*VC960803BNB* | 13,000 | $650 |
| No | 206144798 | GOODMAN | GVZC200241A* | CSCF3642N6D*+TXV | G*VC800604B*A* | 13,000 | $650 |
| No | 206144800 | GOODMAN | GVZC200241A* | CSCF3642N6D*+TXV | G*VC960603BNB* | 13,000 | $650 |
| No | 206144886 | GOODMAN | GVZC200361A* | CA*F3137*6A*+TXV | G*VC960603BNB* | 18,200 | $910 |
| No | 206144802 | GOODMAN | GVZC200241A* | CSCF3642N6D*+TXV | G*VC960804CNB* | 13,000 | $650 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206144801 | GOODMAN | GVZC200241A* | CSCF3642N6D*+TXV | G*VC960803BNB* | 13,000 | $650 |
| No | 206144799 | GOODMAN | GVZC200241A* | CSCF3642N6D*+TXV | G*VC960403BNB* | 13,000 | $650 |
| No | 206144803 | GOODMAN | GVZC200241A* | CSCF3642N6D*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 206144805 | GOODMAN | GVZC200241A* | CSCF3642N6D*+TXV | G*VM970804CNB* | 13,000 | $650 |
| No | 206144885 | GOODMAN | GVZC200361A* | CA*F3137*6A*+TXV | G*VC960403BNB* | 18,200 | $910 |
| No | 206144884 | GOODMAN | GVZC200361A* | CA*F3137*6A*+TXV | G*VC800604B*A* | 18,200 | $910 |
| No | 206144804 | GOODMAN | GVZC200241A* | CSCF3642N6D*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 206144900 | GOODMAN | GVZC200361A* | CA*F3743*6D*+TXV | G*VC960403BNB* | 18,200 | $910 |
| No | 206144888 | GOODMAN | GVZC200361A* | CA*F3642*6D*+TXV | G*VC800604B*A* | 18,200 | $910 |
| No | 206144887 | GOODMAN | GVZC200361A* | CA*F3137*6A*+TXV | G*VC960803BNB* | 18,200 | $910 |
| No | 206144889 | GOODMAN | GVZC200361A* | CA*F3642*6D*+TXV | G*VC800805C*A* | 18,000 | $900 |
| No | 206144890 | GOODMAN | GVZC200361A* | CA*F3642*6D*+TXV | G*VC801005C*A* | 18,000 | $900 |
| No | 206144891 | GOODMAN | GVZC200361A* | CA*F3642*6D*+TXV | G*VC960403BNB* | 18,000 | $900 |
| No | 206144895 | GOODMAN | GVZC200361A* | CA*F3642*6D*+TXV | G*VC961005CNB* | 18,000 | $900 |
| No | 206144894 | GOODMAN | GVZC200361A* | CA*F3642*6D*+TXV | G*VC960804CNB* | 18,200 | $910 |
| No | 206144893 | GOODMAN | GVZC200361A* | CA*F3642*6D*+TXV | G*VC960803BNB* | 18,000 | $900 |
| No | 206144892 | GOODMAN | GVZC200361A* | CA*F3642*6D*+TXV | G*VC960603BNB* | 18,000 | $900 |
| No | 206144908 | GOODMAN | GVZC200361A* | CHPF3642C6C*+TXV | G*VC801005C*A* | 18,000 | $900 |
| No | 206144896 | GOODMAN | GVZC200361A* | CA*F3642*6D*+TXV | G*VC961205DNB* | 18,000 | $900 |
| No | 206144899 | GOODMAN | GVZC200361A* | CA*F3743*6D*+TXV | G*VC801005C*A* | 18,200 | $910 |
| No | 206144897 | GOODMAN | GVZC200361A* | CA*F3743*6D*+TXV | G*VC800604B*A* | 18,000 | $900 |
| No | 206144898 | GOODMAN | GVZC200361A* | CA*F3743*6D*+TXV | G*VC800805C*A* | 18,200 | $910 |
| No | 206144901 | GOODMAN | GVZC200361A* | CA*F3743*6D*+TXV | G*VC960603BNB* | 18,200 | $910 |
| No | 206144903 | GOODMAN | GVZC200361A* | CA*F3743*6D*+TXV | G*VC960804CNB* | 18,000 | $900 |
| No | 206144904 | GOODMAN | GVZC200361A* | CA*F3743*6D*+TXV | G*VC961005CNB* | 18,200 | $910 |
| No | 206144902 | GOODMAN | GVZC200361A* | CA*F3743*6D*+TXV | G*VC960803BNB* | 18,200 | $910 |
| No | 206144905 | GOODMAN | GVZC200361A* | CA*F3743*6D*+TXV | G*VC961205DNB* | 18,200 | $910 |
| No | 206144907 | GOODMAN | GVZC200361A* | CHPF3642C6C*+TXV | G*VC800805C*A* | 18,000 | $900 |
| No | 206144909 | GOODMAN | GVZC200361A* | CHPF3642C6C*+TXV | G*VC960403BNB* | 18,000 | $900 |
| No | 206144910 | GOODMAN | GVZC200361A* | CHPF3642C6C*+TXV | G*VC960603BNB* | 18,000 | $900 |
| No | 206144906 | GOODMAN | GVZC200361A* | CHPF3642C6C*+TXV | G*VC800604B*A* | 18,000 | $900 |
| No | 206144912 | GOODMAN | GVZC200361A* | CHPF3642C6C*+TXV | G*VC960804CNB* | 18,000 | $900 |
| No | 206144915 | GOODMAN | GVZC200361A* | CHPF3743C6B*+TXV | G*VC800805C*A* | 18,200 | $910 |
| No | 206144914 | GOODMAN | GVZC200361A* | CHPF3743C6B*+TXV | G*VC800604B*A* | 18,200 | $910 |
| No | 206144911 | GOODMAN | GVZC200361A* | CHPF3642C6C*+TXV | G*VC960803BNB* | 18,000 | $900 |
| No | 206144913 | GOODMAN | GVZC200361A* | CHPF3642C6C*+TXV | G*VC961005CNB* | 18,000 | $900 |
| No | 206144916 | GOODMAN | GVZC200361A* | CHPF3743C6B*+TXV | G*VC801005C*A* | 18,200 | $910 |
| No | 206144917 | GOODMAN | GVZC200361A* | CHPF3743C6B*+TXV | G*VC960403BNB* | 18,200 | $910 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206144932 | GOODMAN | GVZC200361A* | CSCF3642N6D*+TXV | G*VC961205DNB* | 18,200 | $910 |
| No | 206144921 | GOODMAN | GVZC200361A* | CHPF3743C6B*+TXV | G*VC961005CNB* | 18,200 | $910 |
| No | 206144922 | GOODMAN | GVZC200361A* | CHPF3743C6B*+TXV | G*VM970804CNB* | 18,200 | $910 |
| No | 206144918 | GOODMAN | GVZC200361A* | CHPF3743C6B*+TXV | G*VC960603BNB* | 18,200 | $910 |
| No | 206144920 | GOODMAN | GVZC200361A* | CHPF3743C6B*+TXV | G*VC960804CNB* | 18,200 | $910 |
| No | 206144919 | GOODMAN | GVZC200361A* | CHPF3743C6B*+TXV | G*VC960803BNB* | 18,200 | $910 |
| No | 206144923 | GOODMAN | GVZC200361A* | CHPF3743C6B*+TXV | G*VM971005CNB* | 18,200 | $910 |
| No | 206144924 | GOODMAN | GVZC200361A* | CSCF3642N6D*+TXV | G*VC800604B*A* | 18,200 | $910 |
| No | 206144927 | GOODMAN | GVZC200361A* | CSCF3642N6D*+TXV | G*VC960403BNB* | 18,200 | $910 |
| No | 206144926 | GOODMAN | GVZC200361A* | CSCF3642N6D*+TXV | G*VC801005C*A* | 18,200 | $910 |
| No | 206144925 | GOODMAN | GVZC200361A* | CSCF3642N6D*+TXV | G*VC800805C*A* | 18,200 | $910 |
| No | 206144928 | GOODMAN | GVZC200361A* | CSCF3642N6D*+TXV | G*VC960603BNB* | 18,200 | $910 |
| No | 206144929 | GOODMAN | GVZC200361A* | CSCF3642N6D*+TXV | G*VC960803BNB* | 18,200 | $910 |
| No | 206145154 | GOODMAN | GVZC200481A* | CA*F4961*6D*+TXV | G*VC800604B*A* | 28,000 | $1,400 |
| No | 206144930 | GOODMAN | GVZC200361A* | CSCF3642N6D*+TXV | G*VC960804CNB* | 18,200 | $910 |
| No | 206144931 | GOODMAN | GVZC200361A* | CSCF3642N6D*+TXV | G*VC961005CNB* | 18,200 | $910 |
| No | 206145148 | GOODMAN | GVZC200481A* | CA*F4860*6D*+TXV | G*VC800604B*A* | 27,400 | $1,370 |
| No | 206145149 | GOODMAN | GVZC200481A* | CA*F4860*6D*+TXV | G*VC800805C*A* | 27,400 | $1,370 |
| No | 206145151 | GOODMAN | GVZC200481A* | CA*F4860*6D*+TXV | G*VC960804CNB* | 27,400 | $1,370 |
| No | 206145150 | GOODMAN | GVZC200481A* | CA*F4860*6D*+TXV | G*VC801005C*A* | 27,400 | $1,370 |
| No | 206145152 | GOODMAN | GVZC200481A* | CA*F4860*6D*+TXV | G*VC961005CNB* | 27,400 | $1,370 |
| No | 206145157 | GOODMAN | GVZC200481A* | CA*F4961*6D*+TXV | G*VC960804CNB* | 27,600 | $1,380 |
| No | 206145158 | GOODMAN | GVZC200481A* | CA*F4961*6D*+TXV | G*VC961005CNB* | 27,800 | $1,390 |
| No | 206145153 | GOODMAN | GVZC200481A* | CA*F4860*6D*+TXV | G*VC961205DNB* | 27,400 | $1,370 |
| No | 206145155 | GOODMAN | GVZC200481A* | CA*F4961*6D*+TXV | G*VC800805C*A* | 27,600 | $1,380 |
| No | 206145156 | GOODMAN | GVZC200481A* | CA*F4961*6D*+TXV | G*VC801005C*A* | 27,800 | $1,390 |
| No | 206145159 | GOODMAN | GVZC200481A* | CA*F4961*6D*+TXV | G*VC961205DNB* | 27,800 | $1,390 |
| No | 206145163 | GOODMAN | GVZC200481A* | CHPF4860D6D*+TXV | G*VC961005CNB* | 27,800 | $1,390 |
| No | 206145162 | GOODMAN | GVZC200481A* | CHPF4860D6D*+TXV | G*VC960804CNB* | 27,800 | $1,390 |
| No | 206145164 | GOODMAN | GVZC200481A* | CHPF4860D6D*+TXV | G*VC961205DNB* | 27,800 | $1,390 |
| No | 206145160 | GOODMAN | GVZC200481A* | CHPF4860D6D*+TXV | G*VC800805C*A* | 27,600 | $1,380 |
| No | 206145161 | GOODMAN | GVZC200481A* | CHPF4860D6D*+TXV | G*VC801005C*A* | 27,600 | $1,380 |
| No | 205976174 | GOODMAN | GVZC200601A* | CA*F4961*6D*+TXV | G*VM971205DNB* | 32,000 | $1,600 |
| No | 206145169 | GOODMAN | GVZC200481A* | CSCF4860N6D*+TXV | G*VC961005CNB* | 27,400 | $1,370 |
| No | 206145166 | GOODMAN | GVZC200481A* | CSCF4860N6D*+TXV | G*VC800805C*A* | 27,400 | $1,370 |
| No | 206145167 | GOODMAN | GVZC200481A* | CSCF4860N6D*+TXV | G*VC801005C*A* | 27,400 | $1,370 |
| No | 206145165 | GOODMAN | GVZC200481A* | CSCF4860N6D*+TXV | G*VC800604B*A* | 27,400 | $1,370 |
| No | 206145168 | GOODMAN | GVZC200481A* | CSCF4860N6D*+TXV | G*VC960804CNB* | 27,400 | $1,370 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206145170 | GOODMAN | GVZC200481A* | CSCF4860N6D*+TXV | G*VC961205DNB* | 27,400 | $1,370 |
| No | 205976190 | GOODMAN | GVZC200601A* | AVPEC61D14A* | | 32,600 | $1,630 |
| No | 205976169 | GOODMAN | GVZC200601A* | CA*F4961*6D*+TXV | G*VC800805C*A* | 32,000 | $1,600 |
| No | 205976136 | GOODMAN | GVZC200601A* | CA*F4961*6D*+MBVC2000**-1A*+TXV | | 32,000 | $1,600 |
| No | 205976191 | GOODMAN | GVZC200601A* | CA*F4961*6D*+MBVC2001**-1A*+TXV | | 32,000 | $1,600 |
| No | 205976171 | GOODMAN | GVZC200601A* | CA*F4961*6D*+TXV | G*VC961005CNB* | 32,000 | $1,600 |
| No | 205976170 | GOODMAN | GVZC200601A* | CA*F4961*6D*+TXV | G*VC801005C*A* | 32,000 | $1,600 |
| No | 205976178 | GOODMAN | GVZC200601A* | CHPF4860D6D*+TXV | G*VM971005CNB* | 32,000 | $1,600 |
| No | 205976172 | GOODMAN | GVZC200601A* | CA*F4961*6D*+TXV | G*VC961205DNB* | 32,000 | $1,600 |
| No | 205976173 | GOODMAN | GVZC200601A* | CA*F4961*6D*+TXV | G*VM971005CNB* | 32,000 | $1,600 |
| No | 205976296 | GOODMAN | GVZC200601A* | CA*F4961*6D*+TXV | G*VS800805CUA* | 32,000 | $1,600 |
| No | 205976180 | GOODMAN | GVZC200601A* | CHPF4860D6D*+MBVC2000**-1A*+TXV | | 32,000 | $1,600 |
| No | 205976297 | GOODMAN | GVZC200601A* | CA*F4961*6D*+TXV | G*VS960805CUA* | 32,000 | $1,600 |
| No | 205976192 | GOODMAN | GVZC200601A* | CHPF4860D6D*+MBVC2001**-1A*+TXV | | 32,000 | $1,600 |
| No | 205976298 | GOODMAN | GVZC200601A* | CHPF4860D6D*+TXV | G*VC800805C*A* | 32,000 | $1,600 |
| No | 205976175 | GOODMAN | GVZC200601A* | CHPF4860D6D*+TXV | G*VC801005C*A* | 32,000 | $1,600 |
| No | 205976299 | GOODMAN | GVZC200601A* | CHPF4860D6D*+TXV | G*VS960805CUA* | 32,000 | $1,600 |
| No | 205976176 | GOODMAN | GVZC200601A* | CHPF4860D6D*+TXV | G*VC961005CNB* | 32,000 | $1,600 |
| No | 205976177 | GOODMAN | GVZC200601A* | CHPF4860D6D*+TXV | G*VC961205DNB* | 32,000 | $1,600 |
| No | 205976179 | GOODMAN | GVZC200601A* | CHPF4860D6D*+TXV | G*VM971205DNB* | 32,000 | $1,600 |
| No | 205976181 | GOODMAN | GVZC200601A* | CHPF4860D6D*+TXV | G*VS800805CUA* | 32,000 | $1,600 |
| No | 205880468 | GOODMAN | GVZC200361A* | CA*F3743*6D*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 205976184 | GOODMAN | GVZC200601A* | CSCF4860N6D*+TXV | G*VC961005CNB* | 32,000 | $1,600 |
| No | 205976182 | GOODMAN | GVZC200601A* | CSCF4860N6D*+TXV | G*VC800805C*A* | 32,000 | $1,600 |
| No | 205976183 | GOODMAN | GVZC200601A* | CSCF4860N6D*+TXV | G*VC801005C*A* | 32,000 | $1,600 |
| No | 205976187 | GOODMAN | GVZC200601A* | CSCF4860N6D*+TXV | G*VM971205DNB* | 32,000 | $1,600 |
| No | 205976185 | GOODMAN | GVZC200601A* | CSCF4860N6D*+TXV | G*VC961205DNB* | 32,000 | $1,600 |
| No | 205976188 | GOODMAN | GVZC200601A* | CSCF4860N6D*+TXV | G*VS800805CUA* | 32,000 | $1,600 |
| No | 205976186 | GOODMAN | GVZC200601A* | CSCF4860N6D*+TXV | G*VM971005CNB* | 32,000 | $1,600 |
| No | 205976189 | GOODMAN | GVZC200601A* | CSCF4860N6D*+TXV | G*VS960805CUA* | 32,000 | $1,600 |
| No | 205886762 | GOODMAN | GVZC200241A* | CA*F3137*6A*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205886761 | GOODMAN | GVZC200241A* | CA*F3137*6A*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205886763 | GOODMAN | GVZC200241A* | CA*F3137*6A*+MBVC1200**-1A*+TXV | | 13,000 | $650 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205880466 | GOODMAN | GVZC200241A* | CA*F3642*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205880469 | GOODMAN | GVZC200481A* | CA*F4961*6D*+MBVC2000**-1A*+TXV | | 26,600 | $1,330 |
| No | 205886764 | GOODMAN | GVZC200241A* | CA*F3137*6A*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205886765 | GOODMAN | GVZC200241A* | CA*F3137*6A*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205886767 | GOODMAN | GVZC200241A* | CA*F3636*6D*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205886766 | GOODMAN | GVZC200241A* | CA*F3636*6D*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205886769 | GOODMAN | GVZC200241A* | CA*F3636*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205886768 | GOODMAN | GVZC200241A* | CA*F3636*6D*+TXV | G*VM970804CNB* | 13,000 | $650 |
| No | 205886775 | GOODMAN | GVZC200241A* | CA*F3743*6D*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205886771 | GOODMAN | GVZC200241A* | CA*F3636*6D*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205886774 | GOODMAN | GVZC200241A* | CA*F3642*6D*+TXV | G*VM970804CNB* | 13,000 | $650 |
| No | 205886773 | GOODMAN | GVZC200241A* | CA*F3642*6D*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205886770 | GOODMAN | GVZC200241A* | CA*F3636*6D*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205886772 | GOODMAN | GVZC200241A* | CA*F3642*6D*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205886780 | GOODMAN | GVZC200241A* | CA*F3743*6D*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205886777 | GOODMAN | GVZC200241A* | CA*F3743*6D*+TXV | G*VM970804CNB* | 13,000 | $650 |
| No | 205886778 | GOODMAN | GVZC200241A* | CA*F3743*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205886776 | GOODMAN | GVZC200241A* | CA*F3743*6D*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205886779 | GOODMAN | GVZC200241A* | CA*F3743*6D*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205886781 | GOODMAN | GVZC200241A* | CHPF3636B6C*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205886792 | GOODMAN | GVZC200241A* | CA*F3642*6D*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205886783 | GOODMAN | GVZC200241A* | CHPF3636B6C*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205886784 | GOODMAN | GVZC200241A* | CHPF3636B6C*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205886785 | GOODMAN | GVZC200241A* | CHPF3636B6C*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205886782 | GOODMAN | GVZC200241A* | CHPF3636B6C*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205886786 | GOODMAN | GVZC200241A* | CHPF3642C6C*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205886790 | GOODMAN | GVZC200241A* | CA*F3137*6A*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205886787 | GOODMAN | GVZC200241A* | CSCF3642N6D*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205886789 | GOODMAN | GVZC200241A* | AVPEC25B14A* | | 13,600 | $680 |
| No | 205886788 | GOODMAN | GVZC200241A* | CSCF3642N6D*+TXV | G*VS960603BUA* | 13,000 | $650 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205886791 | GOODMAN | GVZC200241A* | CA*F3636*6D*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205886797 | GOODMAN | GVZC200361A* | CA*F3137*6A*+TXV | G*VM970803BNB* | 18,200 | $910 |
| No | 205886793 | GOODMAN | GVZC200241A* | CA*F3743*6D*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205886796 | GOODMAN | GVZC200361A* | CA*F3137*6A*+TXV | G*VM970603BNB* | 18,200 | $910 |
| No | 205886798 | GOODMAN | GVZC200361A* | CA*F3137*6A*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 205886795 | GOODMAN | GVZC200241A* | CHPF3642C6C*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205886794 | GOODMAN | GVZC200241A* | CHPF3636B6C*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205886800 | GOODMAN | GVZC200361A* | CA*F3137*6A*+TXV | G*VS800604BUA* | 18,200 | $910 |
| No | 205886799 | GOODMAN | GVZC200361A* | CA*F3137*6A*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 205886803 | GOODMAN | GVZC200361A* | CA*F3642*6D*+TXV | G*VM970803BNB* | 18,000 | $900 |
| No | 205886801 | GOODMAN | GVZC200361A* | CA*F3137*6A*+TXV | G*VS960603BUA* | 18,200 | $910 |
| No | 205886802 | GOODMAN | GVZC200361A* | CA*F3642*6D*+TXV | G*VM970603BNB* | 18,000 | $900 |
| No | 205886809 | GOODMAN | GVZC200361A* | CA*F3642*6D*+TXV | G*VS800604BUA* | 18,200 | $910 |
| No | 205886804 | GOODMAN | GVZC200361A* | CA*F3642*6D*+TXV | G*VM970804CNB* | 18,200 | $910 |
| No | 205886808 | GOODMAN | GVZC200361A* | CA*F3642*6D*+MBVC1600**-1A*+TXV | | 18,000 | $900 |
| No | 205886805 | GOODMAN | GVZC200361A* | CA*F3642*6D*+TXV | G*VM971005CNB* | 18,000 | $900 |
| No | 205886806 | GOODMAN | GVZC200361A* | CA*F3642*6D*+TXV | G*VM971205DNB* | 18,000 | $900 |
| No | 205886807 | GOODMAN | GVZC200361A* | CA*F3642*6D*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 205886810 | GOODMAN | GVZC200361A* | CA*F3642*6D*+TXV | G*VS800805CUA* | 18,000 | $900 |
| No | 205886813 | GOODMAN | GVZC200361A* | CA*F3743*6D*+TXV | G*VM970603BNB* | 18,200 | $910 |
| No | 205886812 | GOODMAN | GVZC200361A* | CA*F3642*6D*+TXV | G*VS960805CUA* | 18,000 | $900 |
| No | 205886814 | GOODMAN | GVZC200361A* | CA*F3743*6D*+TXV | G*VM970803BNB* | 18,200 | $910 |
| No | 205886811 | GOODMAN | GVZC200361A* | CA*F3642*6D*+TXV | G*VS960603BUA* | 18,000 | $900 |
| No | 205886815 | GOODMAN | GVZC200361A* | CA*F3743*6D*+TXV | G*VM971205DNB* | 18,200 | $910 |
| No | 205886816 | GOODMAN | GVZC200361A* | CA*F3743*6D*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 205886818 | GOODMAN | GVZC200361A* | CA*F3743*6D*+TXV | G*VS800805CUA* | 18,200 | $910 |
| No | 205886817 | GOODMAN | GVZC200361A* | CA*F3743*6D*+TXV | G*VS800604BUA* | 18,000 | $900 |
| No | 205886833 | GOODMAN | GVZC200361A* | CA*F3743*6D*+TXV | G*VM970804CNB* | 18,000 | $900 |
| No | 205886819 | GOODMAN | GVZC200361A* | CA*F3743*6D*+TXV | G*VS960603BUA* | 18,200 | $910 |
| No | 205886820 | GOODMAN | GVZC200361A* | CA*F3743*6D*+TXV | G*VS960805CUA* | 18,200 | $910 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205886823 | GOODMAN | GVZC200361A* | CHPF3642C6C*+TXV | G*VM970804CNB* | 18,000 | $900 |
| No | 205886821 | GOODMAN | GVZC200361A* | CHPF3642C6C*+TXV | G*VM970603BNB* | 18,000 | $900 |
| No | 205886822 | GOODMAN | GVZC200361A* | CHPF3642C6C*+TXV | G*VM970803BNB* | 18,000 | $900 |
| No | 205886824 | GOODMAN | GVZC200361A* | CHPF3642C6C*+TXV | G*VM971005CNB* | 18,000 | $900 |
| No | 205886826 | GOODMAN | GVZC200361A* | CHPF3642C6C*+MBVC1600**-1A*+TXV | | 18,000 | $900 |
| No | 205886825 | GOODMAN | GVZC200361A* | CHPF3642C6C*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 205886828 | GOODMAN | GVZC200361A* | CHPF3642C6C*+TXV | G*VS800805CUA* | 18,000 | $900 |
| No | 205886827 | GOODMAN | GVZC200361A* | CHPF3642C6C*+TXV | G*VS800604BUA* | 18,000 | $900 |
| No | 205886829 | GOODMAN | GVZC200361A* | CHPF3642C6C*+TXV | G*VS960603BUA* | 18,000 | $900 |
| No | 205886830 | GOODMAN | GVZC200361A* | CHPF3642C6C*+TXV | G*VS960805CUA* | 18,000 | $900 |
| No | 205886831 | GOODMAN | GVZC200361A* | CHPF3743C6B*+TXV | G*VM970603BNB* | 18,200 | $910 |
| No | 205886832 | GOODMAN | GVZC200361A* | CHPF3743C6B*+TXV | G*VM970803BNB* | 18,200 | $910 |
| No | 205886842 | GOODMAN | GVZC200361A* | CSCF3642N6D*+TXV | G*VM970803BNB* | 18,200 | $910 |
| No | 205886834 | GOODMAN | GVZC200361A* | CA*F3743*6D*+TXV | G*VM971005CNB* | 18,200 | $910 |
| No | 205886835 | GOODMAN | GVZC200361A* | CHPF3743C6B*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 205886839 | GOODMAN | GVZC200361A* | CHPF3743C6B*+TXV | G*VS960603BUA* | 18,200 | $910 |
| No | 205886836 | GOODMAN | GVZC200361A* | CHPF3743C6B*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 205886838 | GOODMAN | GVZC200361A* | CHPF3743C6B*+TXV | G*VS800805CUA* | 18,200 | $910 |
| No | 205886837 | GOODMAN | GVZC200361A* | CHPF3743C6B*+TXV | G*VS800604BUA* | 18,200 | $910 |
| No | 205886840 | GOODMAN | GVZC200361A* | CHPF3743C6B*+TXV | G*VS960805CUA* | 18,200 | $910 |
| No | 205886843 | GOODMAN | GVZC200361A* | CSCF3642N6D*+TXV | G*VM970804CNB* | 18,200 | $910 |
| No | 205886841 | GOODMAN | GVZC200361A* | CSCF3642N6D*+TXV | G*VM970603BNB* | 18,200 | $910 |
| No | 205886844 | GOODMAN | GVZC200361A* | CSCF3642N6D*+TXV | G*VM971005CNB* | 18,200 | $910 |
| No | 205886845 | GOODMAN | GVZC200361A* | CSCF3642N6D*+TXV | G*VM971205DNB* | 18,200 | $910 |
| No | 205886853 | GOODMAN | GVZC200361A* | AVPEC59D14A* | | 18,900 | $945 |
| No | 205886846 | GOODMAN | GVZC200361A* | CSCF3642N6D*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 205886848 | GOODMAN | GVZC200361A* | CSCF3642N6D*+TXV | G*VS800604BUA* | 18,200 | $910 |
| No | 205886847 | GOODMAN | GVZC200361A* | CSCF3642N6D*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 205886849 | GOODMAN | GVZC200361A* | CSCF3642N6D*+TXV | G*VS800805CUA* | 18,200 | $910 |
| No | 205886861 | GOODMAN | GVZC200361A* | CHPF3642C6C*+MBVC1601**-1A*+TXV | | 18,000 | $900 |
| No | 205886850 | GOODMAN | GVZC200361A* | CSCF3642N6D*+TXV | G*VS960603BUA* | 18,200 | $910 |
| No | 205886851 | GOODMAN | GVZC200361A* | CSCF3642N6D*+TXV | G*VS960805CUA* | 18,200 | $910 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205886855 | GOODMAN | GVZC200361A* | CA*F3137*6A*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205886854 | GOODMAN | GVZC200361A* | CA*F3137*6A*+MBVC1201**-1A*+TXV | | 18,000 | $900 |
| No | 205886852 | GOODMAN | GVZC200361A* | AVPEC37C14A* | | 18,900 | $945 |
| No | 205886856 | GOODMAN | GVZC200361A* | CA*F3642*6D*+MBVC1201**-1A*+TXV | | 18,000 | $900 |
| No | 205886857 | GOODMAN | GVZC200361A* | CA*F3642*6D*+MBVC1601**-1A*+TXV | | 18,000 | $900 |
| No | 205886858 | GOODMAN | GVZC200361A* | CA*F3743*6D*+MBVC1201**-1A*+TXV | | 18,200 | $910 |
| No | 205886869 | GOODMAN | GVZC200481A* | CA*F4860*6D*+MBVC1600**-1A*+TXV | | 26,600 | $1,330 |
| No | 205886859 | GOODMAN | GVZC200361A* | CA*F3743*6D*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205886860 | GOODMAN | GVZC200361A* | CHPF3642C6C*+MBVC1201**-1A*+TXV | | 18,000 | $900 |
| No | 205886862 | GOODMAN | GVZC200361A* | CHPF3743C6B*+MBVC1201**-1A*+TXV | | 18,200 | $910 |
| No | 205886863 | GOODMAN | GVZC200361A* | CHPF3743C6B*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205886868 | GOODMAN | GVZC200481A* | CA*F4860*6D*+TXV | G*VM971205DNB* | 27,400 | $1,370 |
| No | 205886864 | GOODMAN | GVZC200361A* | CSCF3642N6D*+MBVC1201**-1A*+TXV | | 18,200 | $910 |
| No | 205886867 | GOODMAN | GVZC200481A* | CA*F4860*6D*+TXV | G*VM971005CNB* | 27,400 | $1,370 |
| No | 205886866 | GOODMAN | GVZC200481A* | CA*F4860*6D*+TXV | G*VM970804CNB* | 27,400 | $1,370 |
| No | 205886865 | GOODMAN | GVZC200361A* | CSCF3642N6D*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205886871 | GOODMAN | GVZC200481A* | CA*F4860*6D*+TXV | G*VS800805CUA* | 27,400 | $1,370 |
| No | 205886870 | GOODMAN | GVZC200481A* | CA*F4860*6D*+MBVC2000**-1A*+TXV | | 26,600 | $1,330 |
| No | 205886875 | GOODMAN | GVZC200481A* | CHPF4860D6D*+TXV | G*VM971205DNB* | 27,800 | $1,390 |
| No | 205886873 | GOODMAN | GVZC200481A* | CHPF4860D6D*+TXV | G*VM970804CNB* | 28,000 | $1,400 |
| No | 205886872 | GOODMAN | GVZC200481A* | CA*F4860*6D*+TXV | G*VS960805CUA* | 27,400 | $1,370 |
| No | 205886874 | GOODMAN | GVZC200481A* | CHPF4860D6D*+TXV | G*VM971005CNB* | 27,800 | $1,390 |
| No | 205886876 | GOODMAN | GVZC200481A* | CHPF4860D6D*+MBVC1600**-1A*+TXV | | 26,600 | $1,330 |
| No | 205886879 | GOODMAN | GVZC200481A* | CSCF4860N6D*+TXV | G*VM971005CNB* | 27,400 | $1,370 |
| No | 205886880 | GOODMAN | GVZC200481A* | CSCF4860N6D*+TXV | G*VM971205DNB* | 27,400 | $1,370 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205886881 | GOODMAN | GVZC200481A* | CSCF4860N6D*+MBVC1600**-1A*+TXV | | 26,600 | $1,330 |
| No | 205886877 | GOODMAN | GVZC200481A* | CHPF4860D6D*+TXV | G*VS800805CUA* | 27,200 | $1,360 |
| No | 205886878 | GOODMAN | GVZC200481A* | CSCF4860N6D*+TXV | G*VM970804CNB* | 27,400 | $1,370 |
| No | 205886883 | GOODMAN | GVZC200481A* | CSCF4860N6D*+TXV | G*VS800604BUA* | 27,400 | $1,370 |
| No | 205886882 | GOODMAN | GVZC200481A* | CSCF4860N6D*+MBVC2000**-1A*+TXV | | 26,600 | $1,330 |
| No | 205886885 | GOODMAN | GVZC200481A* | CSCF4860N6D*+TXV | G*VS960805CUA* | 27,400 | $1,370 |
| No | 205886884 | GOODMAN | GVZC200481A* | CSCF4860N6D*+TXV | G*VS800805CUA* | 27,400 | $1,370 |
| No | 205886886 | GOODMAN | GVZC200481A* | AVPEC59D14A* | | 27,000 | $1,350 |
| No | 205886889 | GOODMAN | GVZC200481A* | CHPF4860D6D*+MBVC1601**-1A*+TXV | | 26,600 | $1,330 |
| No | 205886890 | GOODMAN | GVZC200481A* | CHPF4860D6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205886888 | GOODMAN | GVZC200481A* | CA*F4860*6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205886887 | GOODMAN | GVZC200481A* | CA*F4860*6D*+MBVC1601**-1A*+TXV | | 26,600 | $1,330 |
| No | 205886891 | GOODMAN | GVZC200481A* | CSCF4860N6D*+MBVC1601**-1A*+TXV | | 26,600 | $1,330 |
| No | 205886892 | GOODMAN | GVZC200481A* | CSCF4860N6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205886897 | GOODMAN | GVZC200481A* | CA*F4961*6D*+TXV | G*VS800604BUA* | 28,000 | $1,400 |
| No | 205886896 | GOODMAN | GVZC200481A* | CA*F4961*6D*+MBVC1600**-1A*+TXV | | 26,800 | $1,340 |
| No | 205886898 | GOODMAN | GVZC200481A* | CA*F4961*6D*+TXV | G*VS800805CUA* | 27,200 | $1,360 |
| No | 205886894 | GOODMAN | GVZC200481A* | CA*F4961*6D*+TXV | G*VM971005CNB* | 27,800 | $1,390 |
| No | 205886893 | GOODMAN | GVZC200481A* | CA*F4961*6D*+TXV | G*VM970804CNB* | 27,800 | $1,390 |
| No | 205886895 | GOODMAN | GVZC200481A* | CA*F4961*6D*+TXV | G*VM971205DNB* | 27,800 | $1,390 |
| No | 205886900 | GOODMAN | GVZC200481A* | CHPF4860D6D*+MBVC2000**-1A*+TXV | | 26,600 | $1,330 |
| No | 205886899 | GOODMAN | GVZC200481A* | CA*F4961*6D*+TXV | G*VS960805CUA* | 27,600 | $1,380 |
| No | 205886901 | GOODMAN | GVZC200481A* | CA*F4961*6D*+MBVC1601**-1A*+TXV | | 26,800 | $1,340 |
| No | 205886902 | GOODMAN | GVZC200481A* | CA*F4961*6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 206900423 | GOODMAN | MSH093E21MCAA | MST093E20ACAA | | 5,800 | $290 |
| No | 10062563 | GOODMAN | MSH123E21MCAA | MST123E20ACAA | | 7,500 | $375 |
| No | 10300062 | GOODMAN | MST183E21MCAA | Heat pump without ducts | | 11,800 | $590 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10300063 | GOODMAN | MST363E21MCAA | Heat pump without ducts | | 25,400 | $1,270 |
| No | 202196601 | GOODMAN | MSH183E21MCAA | MST183E21ADAA | | 12,000 | $600 |
| No | 10062564 | GOODMAN | MSH183E21MCAA | MST183E20ACAA | | 12,000 | $600 |
| No | 203991088 | GOODMAN | MSH183E19MCAA | MSH183E19AXAA | | 11,000 | $550 |
| No | 10062552 | GOODMAN | MSH183E21MCAA | MSH183E21AXAA | | 10,400 | $520 |
| No | 202196602 | GOODMAN | MSH243E21MCAA | MST243E21ADAA | | 16,000 | $800 |
| No | 211755708 | GREE | 3VIR24HP230V1BO | 3VIR24HP230V1BH | | 15,000 | $750 |
| No | 211755707 | GREE | 3VIR18HP230V1BO | 3VIR18HP230V1BH | | 11,000 | $550 |
| No | 211755706 | GREE | 3VIR12HP230V1BO | 3VIR12HP230V1BH | | 7,000 | $350 |
| No | 211755705 | GREE | 3VIR09HP230V1BO | 3VIR09HP230V1BH | | 7,000 | $350 |
| No | 211755704 | GREE | 3VIR12HP115V1BO | 3VIR12HP115V1BH | | 7,000 | $350 |
| No | 211755703 | GREE | 3VIR09HP115V1BO | 3VIR09HP115V1BH | | 7,000 | $350 |
| No | 211752944 | GREE | GWHD(18)ND3PO | Heat pump without ducts | | 14,000 | $700 |
| No | 211717300 | GREE | FLEXX60HP230V1AO | FLEXX60C | | 35,200 | $1,760 |
| No | 211717299 | GREE | FLEXX60HP230V1AO | FLEXX48C | | 31,200 | $1,560 |
| No | 211717298 | GREE | FLEXX36HP230V1AO | FLEXX36C | | 22,000 | $1,100 |
| No | 211644153 | GREE | GUD60W/A-D(U) | GCAT60*/NAA | | 35,200 | $1,760 |
| No | 211644152 | GREE | GUD60W/A-D(U) | GCAT48*/NAA | | 31,200 | $1,560 |
| No | 211644151 | GREE | GUD36W/A-D(U) | GCAT36*/NAA | | 22,000 | $1,100 |
| No | 211497199 | GREE | GWH18QDXF-D3DNB2A/O | GKH(18)BB-D3DN***/I | | 11,000 | $550 |
| No | 211497198 | GREE | GWH18QDXF-D3DNB2A/O | GFH(18)DB-D3DN***/I | | 10,500 | $525 |
| No | 211497196 | GREE | GWH18AGDXF-D3DNA1A/O | GKH(18)BB-D3DN***/I | | 11,000 | $550 |
| No | 211497195 | GREE | GWH18AGDXF-D3DNA1A/O | GFH(18)DB-D3DN***/I | | 10,500 | $525 |
| No | 208158336 | GREE | GWH24AGEXH-D3DNA1A/O | GTH(24)CB-D3DN***/I | | 15,000 | $750 |
| No | 208158335 | GREE | GWH24AGEXH-D3DNA1A/O | GKH(24)BC-D3DN***/I | | 15,000 | $750 |
| No | 206839103 | GREE | 3VIR12HP115V1AO | 3VIR12HP115V1AH | | 7,700 | $385 |
| No | 206839102 | GREE | 3VIR09HP115V1AO | 3VIR09HP115V1AH | | 7,000 | $350 |
| No | 206839101 | GREE | 3VIR09HP230V1AO | 3VIR09HP230V1AH | | 7,300 | $365 |
| No | 206839099 | GREE | 3VIR12HP230V1AO | 3VIR12HP230V1AH | | 7,700 | $385 |
| No | 204581861 | GREE | GMV-12WP/A-T(U) | Heat pump with ducts | | 7,000 | $350 |
| No | 204325176 | GREE | GWH09ACD-D3DNA1A/O | GWH09AAD-D3DN***/I | | 8,000 | $400 |
| No | 202360989 | GREE | GWH09ACD-D3DNA1A/O | GWH09QD-D3DN***/I | | 8,000 | $400 |
| No | 10149903 | GREE | SAP12HP230V1AO | SAP12HP230V1AH | | 8,100 | $405 |
| No | 10149900 | GREE | SAP09HP230V1AO | SAP09HP230V1AH | | 8,000 | $400 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 9956333 | GREE | VIR24HP230V1BO | VIR24HP230V1BH | | 14,300 | $715 |
| No | 9956331 | GREE | VIR09HP230V1BO | VIR09HP230V1BH | | 7,300 | $365 |
| No | 9944776 | GREE | GWH12YD-D3DNA1A/O | GWH12AAD-D3DN***/I | | 8,100 | $405 |
| No | 9116197 | GREE | GWH12YD-D3DNA1A/O | GWH12QD-D3DN***/I | | 8,100 | $405 |
| No | 7091970 | GREE | GWH09QC-D3DNA1D/O | GWH09QC-D3DN***/I | | 7,300 | $365 |
| No | 7091967 | GREE | GWH09QC-A3DNA1D/O | GWH09QC-A3DN***/I | | 6,900 | $345 |
| No | 7070719 | GREE | GWH24QE-D3DNA1D/O | GWH24QE-D3DN***/I | | 14,300 | $715 |
| No | 206395962 | GREE | GWH18AGD-D3DNA1B/O | GWH18AGD-D3DN***/I | | 11,400 | $570 |
| No | 206839100 | GREE | 3VIR18HP230V1AO | 3VIR18HP230V1AH | | 11,400 | $570 |
| No | 209424848 | GREE | GWH12AGCXD-D3DNA1A/O | GTH(12)CA-D3DN***/I | | 7,200 | $360 |
| No | 209424847 | GREE | GWH12AGCXD-D3DNA1A/O | GKH(12)BB-D3DN***/I | | 6,900 | $345 |
| No | 209424846 | GREE | GWH12AGCXD-D3DNA1A/O | GFH(12)DA-D3DN***/I | | 6,900 | $345 |
| No | 209248930 | GREE | GWH09AGCXD-D3DNA1A/O | GWH09AFCXD-D3DN***/I | | 7,000 | $350 |
| No | 209248922 | GREE | GWH12AGCXD-D3DNA1A/O | GWH12AFCXD-D3DN***/I | | 6,300 | $315 |
| No | 210665999 | GREE | 3VIR18HP230V1BO | 3VIR18HP230V1AH | | 11,000 | $550 |
| No | 210278977 | GREE | MULTI30HP230V1EO | Heat pump without ducts | | 27,200 | $1,360 |
| No | 210278975 | GREE | MULTI24HP230V1EO | Heat pump without ducts | | 23,600 | $1,180 |
| No | 210278973 | GREE | MULTI18HP230V1EO | Heat pump without ducts | | 14,700 | $735 |
| No | 210278972 | GREE | 4LIV24HP230V1AO | 4LIV24HP230V1AH | | 13,900 | $695 |
| No | 210278971 | GREE | 3VIR12HP115V1BO | 3VIR12HP115V1AH | | 7,000 | $350 |
| No | 210278970 | GREE | 3VIR12HP230V1BO | 3VIR12HP230V1AH | | 7,000 | $350 |
| No | 210278969 | GREE | 4LIV30HP230V1AO | 4LIV30HP230V1AH | | 18,500 | $925 |
| No | 210278968 | GREE | 3VIR24HP230V1BO | 3VIR24HP230V1AH | | 15,000 | $750 |
| No | 210278967 | GREE | 3VIR09HP230V1BO | 3VIR09HP230V1AH | | 7,000 | $350 |
| No | 210278966 | GREE | 3VIR09HP115V1BO | 3VIR09HP115V1AH | | 7,000 | $350 |
| No | 210278965 | GREE | 4LIV36HP230V1AO | 4LIV36HP230V1AH | | 22,000 | $1,100 |
| No | 210278964 | GREE | 4LIV09HP115V1AO | 4LIV09HP115V1AH | | 6,000 | $300 |
| No | 210278963 | GREE | 4LIV09HP230V1AO | 4LIV09HP230V1AH | | 6,000 | $300 |
| No | 210278962 | GREE | 4LIV12HP115V1AO | 4LIV12HP115V1AH | | 6,800 | $340 |
| No | 210278961 | GREE | 4LIV12HP230V1AO | 4LIV12HP230V1AH | | 6,800 | $340 |
| No | 210278960 | GREE | 4LIV18HP230V1AO | 4LIV18HP230V1AH | | 11,200 | $560 |
| No | 209240165 | GREE | GWH09QCXB-D3DND4B/O | GWH09QCXB-D3DN***/I | | 6,100 | $305 |
| No | 208786091 | GREE | GWHD(30)ND3MO | Heat pump without ducts | | 27,200 | $1,360 |
| No | 208786090 | GREE | GWHD(24)ND3MO | Heat pump without ducts | | 23,600 | $1,180 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208786089 | GREE | GWHD(18)ND3MO | Heat pump without ducts | | 14,700 | $735 |
| No | 207318103 | GREE | GWH09AGC-D3DNA1B/O | GWH09QC-D3DN***/I | | 7,300 | $365 |
| No | 207169058 | GREE | GWH24AGE-D3DNA1A/O | GWH24QE-D3DN***/I | | 15,500 | $775 |
| No | 206913029 | GREE | GWH12AGC-D3DNA1A/O | GFH(12)DA-D3DN***/I | | 6,900 | $345 |
| No | 206839098 | GREE | 3VIR24HP230V1AO | 3VIR24HP230V1AH | | 15,500 | $775 |
| No | 206791548 | GREE | GWH12AGC-D3DNA1A/O | GWH12QC-D3DN***/I | | 7,700 | $385 |
| No | 206395963 | GREE | GWH09AGC-D3DNA1B/O | GWH09AGC-D3DN***/I | | 7,300 | $365 |
| No | 206395961 | GREE | GWH12AGC-D3DNA1A/O | GWH12AGC-D3DN***/I | | 7,700 | $385 |
| No | 206335358 | GREE | GMV-60WL/C-T(U) | Heat pump with ducts | | 36,400 | $1,820 |
| No | 206335357 | GREE | GMV-48WL/C-T(U) | Heat pump with ducts | | 32,000 | $1,600 |
| No | 206335356 | GREE | GMV-36WL/C-T(U) | Heat pump with ducts | | 25,000 | $1,250 |
| No | 206335355 | GREE | GMV-60WL/C-T(U) | Heat pump without ducts | | 41,000 | $2,050 |
| No | 206335354 | GREE | GMV-48WL/C-T(U) | Heat pump without ducts | | 32,000 | $1,600 |
| No | 206335353 | GREE | GMV-36WL/C-T(U) | Heat pump without ducts | | 25,000 | $1,250 |
| No | 204344211 | GREE | GMV-28WL/C-T(U) | Heat pump without ducts | | 20,000 | $1,000 |
| No | 204344210 | GREE | GMV-24WL/C-T(U) | Heat pump without ducts | | 16,000 | $800 |
| No | 204288781 | GREE | MULTIU42HP230V1DO | Heat pump without ducts | | 30,000 | $1,500 |
| No | 204288780 | GREE | MULTIU36HP230V1DO | Heat pump without ducts | | 29,000 | $1,450 |
| No | 202557963 | GREE | GWHD(42)ND3JO | Heat pump without ducts | | 30,000 | $1,500 |
| No | 202557962 | GREE | GWHD(36)ND3JO | Heat pump without ducts | | 29,000 | $1,450 |
| No | 202242130 | GREE | GMV-24WL/C-T(U) | Heat pump with ducts | | 16,500 | $825 |
| No | 211078862 | GREE | GWH18QDXF-D3DNB2A/O | GWH18AFDXF-D3DN***/I | | 10,800 | $540 |
| No | 211012874 | GREE | GWH09QCXB-A3DND4B/O | GWH09AFXB-A3DN***/I | | 6,300 | $315 |
| No | 210605759 | GREE | GWH18AGDXF-D3DNA1A/O | GWH18AGDXF-D3DN***/I | | 11,000 | $550 |
| No | 209550322 | GREE | GWH09AGCXD-D3DNA1A/O | GTH(09)CA-D3DN***/I | | 6,100 | $305 |
| No | 209550321 | GREE | GWH09AGCXD-D3DNA1A/O | GFH(09)DA-D3DN***/I | | 6,300 | $315 |
| No | 209550306 | GREE | GWH09QCXB-A3DND4B/O | GWH09QCXB-A3DN***/I | | 6,300 | $315 |
| No | 209482325 | GREE | GWH12QCXB-A3DND4C/O | GWH12QCXB-A3DN***/I | | 7,000 | $350 |
| No | 209482324 | GREE | GWH12QCXB-D3DND4C/O | GWH12QCXB-D3DN***/I | | 7,000 | $350 |
| No | 209424849 | GREE | GWH18ATDXD-D3DNA1A/O | GWH18ATDXD-D3DN***/I | | 11,200 | $560 |
| No | 209397902 | GREE | GWH24AGEXH-D3DNA1A/O | GWH24QEXH-D3DN***/I | | 15,000 | $750 |
| No | 209276090 | GREE | GWH12ATCXB-A3DNA1C/O | GWH12ATCXB-A3DN***/I | | 6,800 | $340 |
| No | 209276088 | GREE | GWH12ATCXB-D3DNA1C/O | GWH12ATCXB-D3DN***/I | | 6,800 | $340 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 209271944 | GREE | GWH09ATCXB-A3DNA1A/O | GWH09ATCXB-A3DN***/I | | 6,000 | $300 |
| No | 209271943 | GREE | GWH09ATCXB-D3DNA1A/O | GWH09ATCXB-D3DN***/I | | 6,000 | $300 |
| No | 209248932 | GREE | GWH24QEXF-D3DNC4C/O | GWH24ATEXF-D3DN***/I | | 13,900 | $695 |
| No | 209248931 | GREE | GWH09AGCXD-A3DNA1A/O | GWH09QCXD-A3DN***/I | | 7,000 | $350 |
| No | 209248929 | GREE | GWH09AGCXD-D3DNA1A/O | GWH09QCXD-D3DN***/I | | 7,000 | $350 |
| No | 208798358 | GREE | GWH36QFXH-D3DNB2B/O | GWH36QFXH-D3DN***/I | | 22,000 | $1,100 |
| No | 208546479 | GREE | GWH12AGCXD-A3DNA1A/O | GWH12QCXD-A3DN***/I | | 6,300 | $315 |
| No | 208120572 | GREE | GWH12AGCXD-D3DNA1A/O | GWH12QCXD-D3DN***/I | | 6,300 | $315 |
| No | 208071174 | GREE | GWH12AGCXD-A3DNA1A/O | GWH12AGCXD-A3DN***/I | | 7,000 | $350 |
| No | 208071173 | GREE | GWH12AGCXD-D3DNA1A/O | GWH12AGCXD-D3DN***/I | | 7,000 | $350 |
| No | 207708810 | GREE | GWH09AGCXD-D3DNA1A/O | GWH09AGCXD-D3DN***/I | | 7,000 | $350 |
| No | 207708809 | GREE | GWH09AGCXD-A3DNA1A/O | GWH09AGCXD-A3DN***/I | | 7,000 | $350 |
| No | 207690460 | GREE | GWH24AGEXH-D3DNA1A/O | GWH24*****-D3DN***/I | | 15,000 | $750 |
| No | 206717630 | GREE | GWH12AGC-A3DNA1A/O | GWH12AGC-A3DN***/I | | 7,700 | $385 |
| No | 9084224 | GREE | GWHD(18)ND3GO | Heat pump without ducts | | 12,800 | $640 |
| No | 9084225 | GREE | GWHD(24)ND3GO | Heat pump without ducts | | 16,600 | $830 |
| No | 9084227 | GREE | GWHD(36)ND3GO | Heat pump without ducts | | 26,600 | $1,330 |
| No | 9084226 | GREE | GWHD(30)ND3GO | Heat pump without ducts | | 18,000 | $900 |
| No | 9956415 | GREE | MULTI24HP230V1CO | Heat pump without ducts | | 16,600 | $830 |
| No | 9956416 | GREE | MULTI30HP230V1CO | Heat pump without ducts | | 18,000 | $900 |
| No | 9956417 | GREE | MULTI36HP230V1CO | Heat pump without ducts | | 26,600 | $1,330 |
| No | 9958975 | GREE | MULTI18HP230V1CO | Heat pump without ducts | | 12,800 | $640 |
| No | 9956418 | GREE | MULTI42HP230V1CO | Heat pump without ducts | | 29,000 | $1,450 |
| No | 7017642 | GREE | GWHD(42)ND3EO | Heat pump without ducts | | 29,000 | $1,450 |
| No | 7091971 | GREE | GWH12QC-D3DNA1D/O | GWH12QC-D3DN***/I | | 7,700 | $385 |
| No | 211078852 | GREE | FLEXE60HP230V1AO | FLEXE60HP230V1AH | | 30,000 | $1,500 |
| No | 211078851 | GREE | FLEXE48HP230V1AO | FLEXE48HP230V1AH | | 26,000 | $1,300 |
| No | 211078850 | GREE | FLEXE42HP230V1AO | FLEXE42HP230V1AH | | 25,000 | $1,250 |
| No | 211078849 | GREE | FLEXE36HP230V1AO | FLEXE36HP230V1AH | | 19,000 | $950 |
| No | 211078848 | GREE | FLEXE30HP230V1AO | FLEXE30HP230V1AH | | 18,600 | $930 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211078847 | GREE | FLEXE24HP230V1AO | FLEXE24HP230V1AH | | 14,600 | $730 |
| No | 210421037 | GREE | GUD60W2/D-D(U) | GUD60AH2/D-D(U) | | 30,000 | $1,500 |
| No | 210421036 | GREE | GUD48W2/D-D(U) | GUD48AH2/D-D(U) | | 26,000 | $1,300 |
| No | 210421035 | GREE | GUD42W2/D-D(U) | GUD42AH2/D-D(U) | | 25,000 | $1,250 |
| No | 210421034 | GREE | GUD36W2/D-D(U) | GUD36AH2/D-D(U) | | 19,000 | $950 |
| No | 210421033 | GREE | GUD30W2/D-D(U) | GUD30AH2/D-D(U) | | 18,600 | $930 |
| No | 210421032 | GREE | GUD24W2/D-D(U) | GUD24AH2/D-D(U) | | 14,600 | $730 |
| No | 210485364 | GREE | GWHD(30)ND3NO | Heat pump without ducts | | 27,200 | $1,360 |
| No | 210485363 | GREE | GWHD(24)ND3NO | Heat pump without ducts | | 23,600 | $1,180 |
| No | 210485362 | GREE | GWHD(18)ND3NO | Heat pump without ducts | | 14,700 | $735 |
| No | 208798357 | GREE | GWH30QFXH-D3DNB2A/O | GWH30QFXH-D3DN***/I | | 17,500 | $875 |
| No | 205959993 | GREE | GWHD(42)ND3LO | Heat pump without ducts | | 30,000 | $1,500 |
| No | 205959992 | GREE | GWHD(36)ND3LO | Heat pump without ducts | | 29,000 | $1,450 |
| No | 207201627 | GREE | 3VIR12HP230V1AO | DUCT12HP230V1BD | | 6,900 | $345 |
| No | 207201625 | GREE | 3VIR09HP230V1AO | DUCT09HP230V1BD | | 6,900 | $345 |
| No | 204893199 | GREE | GWH24QE-D3DNB2R/O | GWH24QE-D3DN***/I | | 15,000 | $750 |
| No | 206221398 | GREE | GWHD(30)ND3IO | Heat pump without ducts | | 18,000 | $900 |
| No | 206221396 | GREE | GWHD(18)ND3IO | Heat pump without ducts | | 9,500 | $475 |
| No | 206221399 | GREE | GWHD(36)ND3IO | Heat pump without ducts | | 22,000 | $1,100 |
| No | 206221397 | GREE | GWHD(24)ND3IO | Heat pump without ducts | | 13,200 | $660 |
| No | 206335347 | GREE | MULTIE18HP230V1AO | Heat pump without ducts | | 9,500 | $475 |
| No | 205291861 | GREE | LIVV36HP230V1AO | LIVV36HP230V1AH | | 22,600 | $1,130 |
| No | 205123814 | GREE | LIVV30HP230V1AO | LIVV30HP230V1AH | | 16,000 | $800 |
| No | 205093063 | GREE | LIVV24HP230V1AO | LIVV24HP230V1AH | | 15,000 | $750 |
| No | 206335349 | GREE | MULTIE30HP230V1AO | Heat pump without ducts | | 18,000 | $900 |
| No | 206335352 | GREE | GWH24AGE-D3DNA1A/O | GWH24AGE-D3DN***/I | | 15,500 | $775 |
| No | 206335350 | GREE | MULTIE36HP230V1AO | Heat pump without ducts | | 22,000 | $1,100 |
| No | 206909897 | GREE | GWHD(18)ND3IO | Heat pump with ducts | | 11,000 | $550 |
| No | 206909899 | GREE | GWHD(30)ND3IO | Heat pump with ducts | | 18,000 | $900 |
| No | 206909900 | GREE | GWHD(36)ND3IO | Heat pump with ducts | | 23,000 | $1,150 |
| No | 206909898 | GREE | GWHD(24)ND3IO | Heat pump with ducts | | 16,000 | $800 |
| No | 206913021 | GREE | MULTIE24HP230V1AO | Heat pump with ducts | | 16,000 | $800 |
| No | 206913020 | GREE | MULTIE18HP230V1AO | Heat pump with ducts | | 11,000 | $550 |
| No | 206913022 | GREE | MULTIE30HP230V1AO | Heat pump with ducts | | 18,000 | $900 |
| No | 206913033 | GREE | GWH24AGE-D3DNA1A/O | GKH(24)BC-D3DN***/I | | 15,500 | $775 |
| No | 206913023 | GREE | MULTIE36HP230V1AO | Heat pump with ducts | | 23,000 | $1,150 |
| No | 207168479 | GREE | GWH09AGC-D3DNA1B/O | GFH(09)DA-D3DN***/I | | 6,900 | $345 |
| No | 206913032 | GREE | GWH24AGE-D3DNA1A/O | GFH(24)DB-D3DN***/I | | 14,900 | $745 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206913034 | GREE | GWH24AGE-D3DNA1A/O | GTH(24)CB-D3DN***/I | | 14,800 | $740 |
| No | 207168480 | GREE | GWH09AGC-D3DNA1B/O | GTH(09)CA-D3DN***/I | | 6,900 | $345 |
| No | 207201626 | GREE | 3VIR09HP230V1AO | FLR09HP230V1BF | | 6,900 | $345 |
| No | 207201628 | GREE | 3VIR12HP230V1AO | CAS12HP230V1BC | | 6,900 | $345 |
| No | 207201633 | GREE | 3VIR24HP230V1AO | DUCT24HP230V1BD | | 14,900 | $745 |
| No | 207201629 | GREE | 3VIR12HP230V1AO | FLR12HP230V1BF | | 7,200 | $360 |
| No | 207201635 | GREE | 3VIR24HP230V1AO | FLR24HP230V1BF | | 14,800 | $740 |
| No | 207201634 | GREE | 3VIR24HP230V1AO | CAS24HP230V1BC | | 15,500 | $775 |
| No | 206221396 | GREE | GWHD(18)ND3IO | Heat pump without ducts | | 9,500 | $475 |
| No | 206335348 | GREE | MULTIE24HP230V1AO | Heat pump without ducts | | 13,200 | $660 |
| No | 9956332 | GREE | VIR18HP230V1BO | VIR18HP230V1BH | | 12,400 | $620 |
| No | 9959454 | GREE | VIR12HP230V1BO | VIR12HP230V1BH | | 7,100 | $355 |
| No | 9956330 | GREE | VIR12HP115V1BO | VIR12HP115V1BH | | 6,800 | $340 |
| No | 9956329 | GREE | VIR09HP115V1BO | VIR09HP115V1BH | | 6,100 | $305 |
| No | 9944775 | GREE | GWH09YD-D3DNA1A/O | GWH09AAD-D3DN***/I | | 5,600 | $280 |
| No | 7607465 | GREE | GWH09UC-D3DNA4C/O | GWH09UC-D3DN***/I | | 5,500 | $275 |
| No | 10146838 | GREE | GWH15QD-D3DNA5G/O | GWH15QD-D3DN***/I | | 10,300 | $515 |
| No | 8000864 | GREE | GWH18QD-D3DNA1G/O | GWH18QD-D3DN***/I | | 12,400 | $620 |
| No | 7607467 | GREE | GWH12UC-D3DNA4C/O | GWH12UC-D3DN***/I | | 8,500 | $425 |
| No | 7091968 | GREE | GWH12QC-A3DNA1D/O | GWH12QC-A3DN***/I | | 6,800 | $340 |
| No | 7280497 | GREE | GUHD24ND3FO | GKH24D3FI | | 15,700 | $785 |
| No | 7280500 | GREE | GUHD30ND3FO | GFH30D3FI | | 16,700 | $835 |
| No | 7280499 | GREE | GUHD24ND3FO | GFH24D3FI | | 16,700 | $835 |
| No | 7425273 | GREE | GMV-36WL/A-T(U) | Heat pump with ducts | | 25,200 | $1,260 |
| No | 7280498 | GREE | GUHD24ND3FO | GTH24D3FI | | 15,700 | $785 |
| No | 7280492 | GREE | GUHD18ND3FO | GFH18D3FI | | 10,900 | $545 |
| No | 7425275 | GREE | GMV-48WL/A-T(U) | Heat pump with ducts | | 32,000 | $1,600 |
| No | 202519340 | GREE | GMV-Y48WL/A-T(U) | Heat pump with ducts | | 33,000 | $1,650 |
| No | 202515509 | GREE | GMV-Y36WL/A-T(U) | Heat pump with ducts | | 25,000 | $1,250 |
| No | 7280508 | GREE | GUHD36ND3FO | GFH36D3FI | | 24,600 | $1,230 |
| No | 202541562 | GREE | GMV-28WL/C-T(U) | Heat pump with ducts | | 19,400 | $970 |
| No | 202519342 | GREE | GMV-Y60WL/A-T(U) | Heat pump with ducts | | 35,000 | $1,750 |
| No | 211729106 | Haier | 1U4248LP2HD** | USYM48UCDD** | | 34,600 | $1,730 |
| No | 211744605 | Haier | 1U4248LP2HD** | USYL42UCDD** | | 31,000 | $1,550 |
| No | 211729105 | Haier | 1U4248LP2HD** | USYM42UCDD** | | 31,600 | $1,580 |
| No | 211744606 | Haier | 1U3036LP2HD** | AW36TL2HF** | | 25,600 | $1,280 |
| No | 211744604 | Haier | 1U3036LP2HD** | USYL36UCDD** | | 26,000 | $1,300 |
| No | 211727010 | Haier | 1U3036LP2HD** | USYM36UCDD** | | 26,800 | $1,340 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211744603 | Haier | 1U3036LP2HD** | AW30TL2HF** | | 21,400 | $1,070 |
| No | 211727009 | Haier | 1U3036LP2HD** | USYM30UCDD** | | 22,000 | $1,100 |
| No | 211744600 | Haier | 1U24LP2HD** | USYL24UCDD** | | 17,400 | $870 |
| No | 211727008 | Haier | 1U24LP2HD** | USYM24UCDD** | | 17,400 | $870 |
| No | 210404028 | HAIER | 5U42MS2HD** | Heat pump with ducts | | 26,000 | $1,300 |
| No | 210404027 | HAIER | 5U42MS2HD** | Heat pump without ducts | | 24,000 | $1,200 |
| No | 210151027 | HAIER | 4U36EH2HD** | Heat pump with ducts | | 20,000 | $1,000 |
| No | 209938279 | HAIER | 1U24TE2HD** | AW24TC2HD** | | 15,000 | $750 |
| No | 209938278 | HAIER | 1U18TE2HD** | AW18TC2HD** | | 11,400 | $570 |
| No | 10225938 | HAIER | 1U48LP2VHA | AL48LP2VH* | | 24,200 | $1,210 |
| No | 10338838 | HAIER | 1U12ES2VHA | AW12ES2VH* | | 12,220 | $611 |
| No | 10225933 | HAIER | 1U24LP2VHA | AL24LP2VH* | | 15,600 | $780 |
| No | 8066788 | HAIER | 4U36MS2VHB | Heat pump with ducts | | 21,000 | $1,050 |
| No | 10316370 | HAIER | MVHP036MV2AA | Heat pump with ducts | | 23,800 | $1,190 |
| No | 10338837 | HAIER | 1U09ES2VHA | AW09ES2VH* | | 7,400 | $370 |
| No | 10225937 | HAIER | 1U36LP2VHA | AW36LP2VH* | | 31,600 | $1,580 |
| No | 10316369 | HAIER | MVHP036MV2AA | Heat pump without ducts | | 24,000 | $1,200 |
| No | 10225935 | HAIER | 1U36LP2VHA | AM36LP2VH* | | 18,800 | $940 |
| No | 8066750 | HAIER | 4U36MS2VHB | Heat pump without ducts | | 22,000 | $1,100 |
| No | 10221212 | HAIER | 1U24LP2VHA | AW24LP2VH* | | 22,000 | $1,100 |
| No | 8067004 | HAIER | 3U24MS2VHB | Heat pump without ducts | | 15,000 | $750 |
| No | 202583713 | HAIER | 1U24AP2VHA | AW24ES2VHB | | 19,000 | $950 |
| No | 202583712 | HAIER | 1U15AP2VHA | AW15ES2VHB | | 12,000 | $600 |
| No | 202583711 | HAIER | 1U12AP2VHA | AW12ES2VHB | | 10,700 | $535 |
| No | 202583710 | HAIER | 1U18AP2VHA | AW18ES2VHB | | 14,000 | $700 |
| No | 10225932 | HAIER | 1U24LP2VHA | AM24LP2VH* | | 15,300 | $765 |
| No | 207769097 | HAIER | 1U24TL2HF** | AW24TL2HF** | | 16,500 | $825 |
| No | 207698996 | HAIER | 2U18MS2HD** | AW09TC2HD**, AW09TC2HD** | | 14,700 | $735 |
| No | 207698998 | HAIER | 3U24MS2HD** | AW07TC2HD**,AW07TC2HD**,AW09TC2HD** | | 15,000 | $750 |
| No | 207722662 | HAIER | 3U24MS2HD** | USYM07UCDD**,USYM07UCDD**,USYM09UCDSA* | | 15,000 | $750 |
| No | 207722664 | HAIER | 3U24MS2HD** | ASYW07CRDD**,ASYW07CRDD**,ASYW09CRDD** | | 15,000 | $750 |
| No | 207802647 | HAIER | 4U36MS2HD** | AW07TC2HD**,AW07TC2HD**,AW07TC2HD**, AW12CT2HD** | | 22,800 | $1,140 |
| No | 207802648 | HAIER | 4U36MS2HD** | USYM07UCDD**,USYM09UCDSA*,USYM09UCDSA*,USYM09UCDSA* | | 22,400 | $1,120 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208131916 | HAIER | 4U36MS2HD** | Combinaison d'unités avec et sans conduits | | 22,600 | $1,130 |
| No | 206389355 | HAIER | 1U12EH2VHE* | USYF12UCDWA* | | 8,500 | $425 |
| No | 206389356 | HAIER | 1U12EH2VHE* | AB12SC2VHA* | | 8,500 | $425 |
| No | 206608652 | HAIER | 1U09EH2VHE* | USYF09UCDWA* | | 6,000 | $300 |
| No | 206608650 | HAIER | 1U09EH2VHE* | USYM09UCDSA* | | 6,500 | $325 |
| No | 206445819 | HAIER | 1U09EH2VHE* | AW09EH2VHD* | | 6,500 | $325 |
| No | 206389354 | HAIER | 1U12EH2VHE* | USYM12UCDSA* | | 9,300 | $465 |
| No | 206389351 | HAIER | 1U12EH2VHE* | AW12EH2VHD* | | 9,300 | $465 |
| No | 206551254 | HAIER | 1U12TE2VHA* | AW12TE2VHA* | | 7,500 | $375 |
| No | 206551253 | HAIER | 1U09TE2VHA* | AW09TE2VHA* | | 5,000 | $250 |
| No | 205291901 | HAIER | 1U09EH2VHD* | AW09EH2VHD* | | 6,500 | $325 |
| No | 205291902 | HAIER | 1U12EH2VHD* | AW12EH2VHD* | | 9,300 | $465 |
| No | 10316378 | HAIER | MVHP056MV2AA | Heat pump with ducts | | 38,000 | $1,900 |
| No | 10092556 | HAIER | 1U18ES2VHA | AW18ES2VH | | 14,000 | $700 |
| No | 10316372 | HAIER | MVHP048MV2AA | Heat pump with ducts | | 35,000 | $1,750 |
| No | 10092555 | HAIER | 1U24ES2VHA | AW24ES2VH | | 18,500 | $925 |
| No | 10225936 | HAIER | 1U36LP2VHA | AL36LP2VH* | | 20,800 | $1,040 |
| No | 202583709 | HAIER | 1U09AP2VHA | AW09ES2VHB | | 6,500 | $325 |
| No | 10316371 | HAIER | MVHP048MV2AA | Heat pump without ducts | | 35,000 | $1,750 |
| No | 10316377 | HAIER | MVHP056MV2AA | Heat pump without ducts | | 38,000 | $1,900 |
| No | 207036462 | HAXXAIR | HVHD-24E2D2 | HAHD-24E2D2 | | 15,000 | $750 |
| No | 207036473 | HAXXAIR | HVHD-48E2D2 | HAHD-48E2D2 | | 31,000 | $1,550 |
| No | 207036475 | HAXXAIR | HVHD-60E2D2 | HAHD-60E2D2 | | 40,000 | $2,000 |
| No | 204100526 | HAXXAIR | HVHM-36T2D | Heat pump without ducts | | 22,400 | $1,120 |
| No | 204032227 | HAXXAIR | HVHM-36T2D | Combination heat pumps with or without ducts | | 22,600 | $1,130 |
| No | 204628476 | HAXXAIR | HVH-18T2D | HAH-18T2D | | 11,600 | $580 |
| No | 204628475 | HAXXAIR | HVH-12T2D | HAH-12T2D | | 7,500 | $375 |
| No | 208650724 | HAXXAIR | HVHM-18T2D | HAH-09T2D HAH-12T2D | | 12,200 | $610 |
| No | 208650723 | HAXXAIR | HVHM-18T2D | HAHS-12T2D | | 12,200 | $610 |
| No | 208650725 | HAXXAIR | HVHM-18T2D | HAH09-T2D/HAH-12T2D/HAHS-12T2D/HAHC-12T2D | | 12,200 | $610 |
| No | 10258955 | HAXXAIR | HVH-18B2D | HAH-18B2D | | 11,600 | $580 |
| No | 204032224 | HAXXAIR | HVHM-24T2D | Heat pump with ducts | | 15,400 | $770 |
| No | 204032226 | HAXXAIR | HVHM-24T2D | Combination heat pumps with or without ducts | | 15,400 | $770 |
| No | 204032225 | HAXXAIR | HVHM-36T2D | Heat pump with ducts | | 22,000 | $1,100 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205921369 | HAXXAIR | HVHD-60E2D | HAHD-60E2D | | 32,400 | $1,620 |
| No | 205306853 | HAXXAIR | HVHD-24E2D | HAHD-24E2D | | 15,300 | $765 |
| No | 205921367 | HAXXAIR | HVHSC-18T2D | HAHC-18T2D | | 11,000 | $550 |
| No | 205921368 | HAXXAIR | HVHSC-18T2D | HAHS-18T2D | | 12,000 | $600 |
| No | 204198639 | HAXXAIR | HVHM-24T2D | Heat pump without ducts | | 15,400 | $770 |
| No | 210819423 | HEIL | DLCSRBH30AAK | DLFSABH30XBK | | 20,400 | $1,020 |
| No | 209852071 | HEIL | DLCURAH60AAK | DLFUAAH60XAK | | 37,000 | $1,850 |
| No | 209852068 | HEIL | DLCURAH48AAK | DLFUAAH48XAK | | 37,000 | $1,850 |
| No | 209852075 | HEIL | DLCURAH36AAK | DLFUAAH36XAK | | 20,400 | $1,020 |
| No | 209852077 | HEIL | DLCURAH30ABK | DLFUAAH30XAK | | 21,000 | $1,050 |
| No | 209852074 | HEIL | DLCURAH30AAK | DLFUAAH30XAK | | 20,000 | $1,000 |
| No | 209852067 | HEIL | DLCURAH24AAK | DLFUAAH24XAK | | 21,000 | $1,050 |
| No | 209852073 | HEIL | DLCURAH18AAK | DLFUAAH18XAK | | 12,000 | $600 |
| No | 207643068 | HEIL | DLCMRBH48EAK | Heat pump without ducts | | 31,000 | $1,550 |
| No | 201835690 | HEIL | DLCMRAH27CAK | Heat pump without ducts | | 17,800 | $890 |
| No | 208104315 | HEIL | DLCSRBH36ABK | DLFSABH36XBK | | 25,600 | $1,280 |
| No | 207826625 | HEIL | DLCLRCH36AAK | DLFLABH36XAK | | 25,600 | $1,280 |
| No | 207826624 | HEIL | DLCLRCH58AAK | DLFLABH60XAK | | 34,000 | $1,700 |
| No | 207826623 | HEIL | DLCLRCH48AAK | DLFLABH48XAK | | 37,400 | $1,870 |
| No | 207826600 | HEIL | DLCSRBH24AAK | DLFSABH24XBK | | 16,200 | $810 |
| No | 208104316 | HEIL | DLCSRBH30AAK11 | DLFSABH30XBK | | 19,200 | $960 |
| No | 206188303 | HEIL | DLCLRBH36AAK | DLFLFAH36XAK | | 22,000 | $1,100 |
| No | 206188306 | HEIL | DLCLRBH48AAK | DLFLFAH48XAK | | 29,000 | $1,450 |
| No | 206188304 | HEIL | DLCLRBH36AAK | DLFLCAH36XAK | | 22,000 | $1,100 |
| No | 206188307 | HEIL | DLCLRBH48AAK | DLFLCAH48XAK | | 29,000 | $1,450 |
| No | 206188308 | HEIL | DLCLRBH48AAK | DLFLDAH48XAK | | 29,000 | $1,450 |
| No | 207202890 | HEIL | DLCSRBH18AAK | FEM4P18**AL | | 14,700 | $735 |
| No | 207202891 | HEIL | DLCSRBH18AAK | FEM4X18**BL | | 14,700 | $735 |
| No | 207202892 | HEIL | DLCSRBH18AAK | EA*4X19L17A* | *80ES(N,L)0451412A* | 13,800 | $690 |
| No | 207202893 | HEIL | DLCSRBH18AAK | EA*4X24L14A* | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207202894 | HEIL | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207202896 | HEIL | DLCSRBH18AAK | EN(A,D)4X18L14** | *80ES(N,L)0451412A* | 14,700 | $735 |
| No | 207202895 | HEIL | DLCSRBH18AAK | EA*4X25L17A* | *80ES(N,L)0451412A* | 13,800 | $690 |
| No | 207202897 | HEIL | DLCSRBH18AAK | EN(A,D)4X24L14** | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207202902 | HEIL | DLCSRBH18AAK | EA*4X19L17A* | *80ES(N,L)0701412A* | 13,900 | $695 |
| No | 207202903 | HEIL | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0701412A* | 14,600 | $730 |
| No | 207202898 | HEIL | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207202899 | HEIL | DLCSRBH18AAK | EA*4X19L17A* | *80ES(N,L)0451712A* | 13,900 | $695 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207202900 | HEIL | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0451712A* | 14,600 | $730 |
| No | 207202901 | HEIL | DLCSRBH18AAK | EA*4X25L17A* | *80ES(N,L)0451712A* | 13,800 | $690 |
| No | 207202905 | HEIL | DLCSRBH18AAK | EN(A,D)4X18L14** | *80ES(N,L)0701412A* | 14,700 | $735 |
| No | 207202904 | HEIL | DLCSRBH18AAK | EA*4X25L17A* | *80ES(N,L)0701412A* | 13,800 | $690 |
| No | 207202906 | HEIL | DLCSRBH18AAK | EN(A,D)4X24L14** | *80ES(N,L)0701412A* | 14,600 | $730 |
| No | 207202908 | HEIL | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0701712A* | 14,700 | $735 |
| No | 207202907 | HEIL | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ES(N,L)0701412A* | 14,600 | $730 |
| No | 207202909 | HEIL | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ES(N,L)0701712A* | 14,700 | $735 |
| No | 207202911 | HEIL | DLCSRBH18AAK | EA*4X24L17A* | *80ESU0401712A* | 14,500 | $725 |
| No | 207202910 | HEIL | DLCSRBH18AAK | EA*4X19L17A* | *80ESU0401712A* | 13,700 | $685 |
| No | 207202912 | HEIL | DLCSRBH18AAK | EA*4X25L17A* | *80ESU0401712A* | 13,600 | $680 |
| No | 207202914 | HEIL | DLCSRBH18AAK | EA*4X19L17A* | *92ESN0401410A* | 13,800 | $690 |
| No | 207202913 | HEIL | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ESU0401712A* | 14,500 | $725 |
| No | 207202915 | HEIL | DLCSRBH18AAK | EA*4X24L14A* | *92ESN0401410A* | 14,500 | $725 |
| No | 207202917 | HEIL | DLCSRBH18AAK | EA*4X25L17A* | *92ESN0401410A* | 13,700 | $685 |
| No | 207202916 | HEIL | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0401410A* | 14,500 | $725 |
| No | 207202920 | HEIL | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0401410A* | 14,500 | $725 |
| No | 207202924 | HEIL | DLCSRBH18AAK | EA*4X19L17A* | *92ESN0601412A* | 14,000 | $700 |
| No | 207202918 | HEIL | DLCSRBH18AAK | EN(A,D)4X18L14** | *92ESN0401410A* | 14,600 | $730 |
| No | 207202919 | HEIL | DLCSRBH18AAK | EN(A,D)4X24L14** | *92ESN0401410A* | 14,500 | $725 |
| No | 207202921 | HEIL | DLCSRBH18AAK | EA*4X19L17A* | *92ESN0401712A* | 13,900 | $695 |
| No | 207202922 | HEIL | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0401712A* | 14,600 | $730 |
| No | 207202923 | HEIL | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0401712A* | 14,600 | $730 |
| No | 207202925 | HEIL | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0601412A* | 14,600 | $730 |
| No | 207202926 | HEIL | DLCSRBH18AAK | EA*4X25L17A* | *92ESN0601412A* | 13,800 | $690 |
| No | 207202927 | HEIL | DLCSRBH18AAK | EN(A,D)4X18L14** | *92ESN0601412A* | 14,700 | $735 |
| No | 207202928 | HEIL | DLCSRBH18AAK | EN(A,D)4X24L14** | *92ESN0601412A* | 14,600 | $730 |
| No | 207202929 | HEIL | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0601412A* | 14,600 | $730 |
| No | 207202931 | HEIL | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0801716A* | 14,700 | $735 |
| No | 207202930 | HEIL | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0801716A* | 14,700 | $735 |
| No | 207202932 | HEIL | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0261410A* | 14,100 | $705 |
| No | 207202933 | HEIL | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0261410A* | 14,700 | $735 |
| No | 207202934 | HEIL | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0261410A* | 13,900 | $695 |
| No | 207202935 | HEIL | DLCSRBH18AAK | EN(A,D)4X18L14** | *95ESN0261410A* | 14,800 | $740 |
| No | 207202936 | HEIL | DLCSRBH18AAK | EN(A,D)4X24L14** | *95ESN0261410A* | 14,700 | $735 |
| No | 207202937 | HEIL | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0261410A* | 14,700 | $735 |
| No | 207202938 | HEIL | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0401410A* | 13,900 | $695 |
| No | 207202939 | HEIL | DLCSRBH18AAK | EA*4X24L14A* | *95ESN0401410A* | 14,600 | $730 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207202941 | HEIL | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0401410A* | 13,800 | $690 |
| No | 207202940 | HEIL | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0401410A* | 14,600 | $730 |
| No | 207202942 | HEIL | DLCSRBH18AAK | EN(A,D)4X18L14** | *95ESN0401410A* | 14,700 | $735 |
| No | 207202943 | HEIL | DLCSRBH18AAK | EN(A,D)4X24L14** | *95ESN0401410A* | 14,600 | $730 |
| No | 207202945 | HEIL | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0401712A* | 13,800 | $690 |
| No | 207202944 | HEIL | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0401410A* | 14,600 | $730 |
| No | 207202946 | HEIL | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0401712A* | 14,600 | $730 |
| No | 207202947 | HEIL | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0401712A* | 13,700 | $685 |
| No | 207202951 | HEIL | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0601714A* | 14,100 | $705 |
| No | 207202948 | HEIL | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0401712A* | 14,600 | $730 |
| No | 207202949 | HEIL | DLCSRBH18AAK | EA*4X24L14A* | *95ESN0601412A* | 14,900 | $745 |
| No | 207202950 | HEIL | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0601412A* | 14,900 | $745 |
| No | 207202952 | HEIL | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0601714A* | 14,000 | $700 |
| No | 207202953 | HEIL | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0601714A* | 14,700 | $735 |
| No | 207202954 | HEIL | DLCSRBH18AAK | EA*4X19L17A* | *95ESU0401712A* | 13,800 | $690 |
| No | 207202955 | HEIL | DLCSRBH18AAK | EA*4X24L17A* | *95ESU0401712A* | 14,600 | $730 |
| No | 207202956 | HEIL | DLCSRBH18AAK | EA*4X25L17A* | *95ESU0401712A* | 13,800 | $690 |
| No | 207202958 | HEIL | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0401410A* | 13,900 | $695 |
| No | 207202959 | HEIL | DLCSRBH18AAK | EA*4X24L14A* | *96VTN0401410A* | 14,700 | $735 |
| No | 207202957 | HEIL | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESU0401712A* | 14,600 | $730 |
| No | 207202960 | HEIL | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0401410A* | 14,700 | $735 |
| No | 207202961 | HEIL | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0401410A* | 13,900 | $695 |
| No | 207202962 | HEIL | DLCSRBH18AAK | EN(A,D)4X18L14** | *96VTN0401410A* | 14,800 | $740 |
| No | 207202963 | HEIL | DLCSRBH18AAK | EN(A,D)4X24L14** | *96VTN0401410A* | 14,700 | $735 |
| No | 207202966 | HEIL | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0401712A* | 14,600 | $730 |
| No | 207202968 | HEIL | DLCSRBH18AAK | EN(A,D)4X24L17** | *96VTN0401712A* | 14,600 | $730 |
| No | 207202964 | HEIL | DLCSRBH18AAK | EN(A,D)4X24L17** | *96VTN0401410A* | 14,700 | $735 |
| No | 207202967 | HEIL | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0401712A* | 13,800 | $690 |
| No | 207202965 | HEIL | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0401712A* | 13,900 | $695 |
| No | 207202969 | HEIL | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0601412A* | 13,800 | $690 |
| No | 207202973 | HEIL | DLCSRBH18AAK | EN(A,D)4X18L14** | *96VTN0601412A* | 14,700 | $735 |
| No | 207202970 | HEIL | DLCSRBH18AAK | EA*4X24L14A* | *96VTN0601412A* | 14,600 | $730 |
| No | 207202971 | HEIL | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0601412A* | 14,600 | $730 |
| No | 207202975 | HEIL | DLCSRBH18AAK | EN(A,D)4X24L17** | *96VTN0601412A* | 14,600 | $730 |
| No | 207202974 | HEIL | DLCSRBH18AAK | EN(A,D)4X24L14** | *96VTN0601412A* | 14,600 | $730 |
| No | 207202972 | HEIL | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0601412A* | 13,800 | $690 |
| No | 207202976 | HEIL | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0601714A* | 14,100 | $705 |
| No | 207202887 | HEIL | DLCSRBH18AAK | FMA4X18**AL* | | 15,000 | $750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207202977 | HEIL | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0601714A* | 14,700 | $735 |
| No | 207202978 | HEIL | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0601714A* | 13,900 | $695 |
| No | 207202979 | HEIL | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0801716A* | 13,800 | $690 |
| No | 207202175 | HEIL | DLCSRBH18AAK | FVM4X24***L | | 13,400 | $670 |
| No | 207202888 | HEIL | DLCSRBH18AAK | FM(C,U)4Z18**AL* | | 15,000 | $750 |
| No | 207099570 | HEIL | DLCSRBH24AAK | EN(A,D)4X24L14** | *80ES(N,L)0451412A* | 15,600 | $780 |
| No | 207202889 | HEIL | DLCSRBH18AAK | FXM4X18**AL | | 14,500 | $725 |
| No | 207099571 | HEIL | DLCSRBH24AAK | EA*4X24L14A* | *80ES(N,L)0451412A* | 15,700 | $785 |
| No | 207099573 | HEIL | DLCSRBH24AAK | EA*4X30L14A* | *80ES(N,L)0451412A* | 15,500 | $775 |
| No | 207099575 | HEIL | DLCSRBH24AAK | EN(A,D)4X30L14** | *80ES(N,L)0451412A* | 15,500 | $775 |
| No | 207099576 | HEIL | DLCSRBH24AAK | EA*4X36L17A* | *80ES(N,L)0451712A* | 15,500 | $775 |
| No | 207099577 | HEIL | DLCSRBH24AAK | EN(A,D)4X24L14** | *80ES(N,L)0701412A* | 15,600 | $780 |
| No | 207099579 | HEIL | DLCSRBH24AAK | EA*4X24L14A* | *80ES(N,L)0701412A* | 15,700 | $785 |
| No | 207099580 | HEIL | DLCSRBH24AAK | EA*4X30L14A* | *80ES(N,L)0701412A* | 15,500 | $775 |
| No | 207099582 | HEIL | DLCSRBH24AAK | EN(A,D)4X30L14** | *80ES(N,L)0701412A* | 15,500 | $775 |
| No | 207099584 | HEIL | DLCSRBH24AAK | EN(A,D)4X30L17** | *80ES(N,L)0701712A* | 15,400 | $770 |
| No | 207099586 | HEIL | DLCSRBH24AAK | EA*4X36L17A* | *80ES(N,L)0701712A* | 15,400 | $770 |
| No | 207099583 | HEIL | DLCSRBH24AAK | EN(A,D)4X24L17** | *80ES(N,L)0701712A* | 15,600 | $780 |
| No | 207099589 | HEIL | DLCSRBH24AAK | EA*4X30L17A* | *80ES(N,L)0701712A* | 15,500 | $775 |
| No | 207099587 | HEIL | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *80ES(N,L)0701712A* | 15,400 | $770 |
| No | 207099591 | HEIL | DLCSRBH24AAK | EN(A,D)4X24L17** | *80ESU0401712A* | 15,500 | $775 |
| No | 207099592 | HEIL | DLCSRBH24AAK | EN(A,D)4X30L17** | *80ESU0401712A* | 15,400 | $770 |
| No | 207099602 | HEIL | DLCSRBH24AAK | EN(A,D)4X30L17** | *80ESU0601716A | 15,500 | $775 |
| No | 207099594 | HEIL | DLCSRBH24AAK | EA*4X36L17A* | *80ESU0401712A* | 15,300 | $765 |
| No | 207099596 | HEIL | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *80ESU0401712A* | 15,400 | $770 |
| No | 207099597 | HEIL | DLCSRBH24AAK | EA*4X30L17A* | *80ESU0401712A* | 15,400 | $770 |
| No | 207099599 | HEIL | DLCSRBH24AAK | EN(A,D)4X24L17** | *80ESU0601716A | 15,600 | $780 |
| No | 207099601 | HEIL | DLCSRBH24AAK | EA*4X24L17A* | *80ESU0601716A | 15,700 | $785 |
| No | 207099604 | HEIL | DLCSRBH24AAK | EA*4X36L17A* | *80ESU0601716A | 15,400 | $770 |
| No | 207099630 | HEIL | DLCSRBH24AAK | EN(A,D)4X30L14** | *92ESN0601412A* | 15,500 | $775 |
| No | 207099606 | HEIL | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *80ESU0601716A | 15,500 | $775 |
| No | 207099634 | HEIL | DLCSRBH24AAK | EA*4X24L14A* | *92ESN0601714A* | 15,700 | $785 |
| No | 207099625 | HEIL | DLCSRBH24AAK | EN(A,D)4X24L14** | *92ESN0601412A* | 15,600 | $780 |
| No | 207099629 | HEIL | DLCSRBH24AAK | EA*4X30L14A* | *92ESN0601412A* | 15,500 | $775 |
| No | 207099627 | HEIL | DLCSRBH24AAK | EA*4X24L14A* | *92ESN0601412A* | 15,700 | $785 |
| No | 207099633 | HEIL | DLCSRBH24AAK | EN(A,D)4X24L14** | *92ESN0601714A* | 15,500 | $775 |
| No | 207099639 | HEIL | DLCSRBH24AAK | EN(A,D)4X30L17** | *92ESN0801716A* | 15,400 | $770 |
| No | 207099635 | HEIL | DLCSRBH24AAK | EA*4X30L14A* | *92ESN0601714A* | 15,500 | $775 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207099636 | HEIL | DLCSRBH24AAK | EN(A,D)4X30L14** | *92ESN0601714A* | 15,400 | $770 |
| No | 207099637 | HEIL | DLCSRBH24AAK | EN(A,D)4X24L17** | *92ESN0801716A* | 15,500 | $775 |
| No | 207099638 | HEIL | DLCSRBH24AAK | EA*4X24L17A* | *92ESN0801716A* | 15,700 | $785 |
| No | 207099640 | HEIL | DLCSRBH24AAK | EA*4X36L17A* | *92ESN0801716A* | 15,400 | $770 |
| No | 207099641 | HEIL | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *92ESN0801716A* | 15,400 | $770 |
| No | 207099642 | HEIL | DLCSRBH24AAK | EA*4X30L17A* | *92ESN0801716A* | 15,400 | $770 |
| No | 207099644 | HEIL | DLCSRBH24AAK | EA*4X24L14A* | *95ESN0261410A* | 15,800 | $790 |
| No | 207099646 | HEIL | DLCSRBH24AAK | EN(A,D)4X30L14** | *95ESN0261410A* | 15,500 | $775 |
| No | 207099645 | HEIL | DLCSRBH24AAK | EA*4X30L14A* | *95ESN0261410A* | 15,500 | $775 |
| No | 207099653 | HEIL | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESN0401712A* | 15,600 | $780 |
| No | 207099717 | HEIL | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0401410A* | 15,300 | $765 |
| No | 207099654 | HEIL | DLCSRBH24AAK | EA*4X36L17A* | *95ESN0401712A* | 15,500 | $775 |
| No | 207099655 | HEIL | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESN0401712A* | 15,600 | $780 |
| No | 207099656 | HEIL | DLCSRBH24AAK | EA*4X30L17A* | *95ESN0401712A* | 15,600 | $780 |
| No | 207099710 | HEIL | DLCSRBH24AAK | EA*4X36L21A* | *95ESN0401712A* | 15,500 | $775 |
| No | 207099659 | HEIL | DLCSRBH24AAK | EA*4X24L14A* | *95ESN0601412A* | 15,800 | $790 |
| No | 207099709 | HEIL | DLCSRBH24AAK | EA*4X25L17A* | *95ESN0401712A* | 15,200 | $760 |
| No | 207099711 | HEIL | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0401712A* | 15,300 | $765 |
| No | 207099713 | HEIL | DLCSRBH24AAK | EN(A,D)4X36L21** | *95ESN0401712A* | 15,600 | $780 |
| No | 207099712 | HEIL | DLCSRBH24AAK | EA*4X37L21A* | *95ESN0401712A* | 15,200 | $760 |
| No | 207099704 | HEIL | DLCSRBH24AAK | EA*4X30L17A* | *95ESN0601412A* | 15,600 | $780 |
| No | 207099660 | HEIL | DLCSRBH24AAK | EA*4X30L14A* | *95ESN0601412A* | 15,600 | $780 |
| No | 207099658 | HEIL | DLCSRBH24AAK | EN(A,D)4X24L14** | *95ESN0601412A* | 15,600 | $780 |
| No | 207099661 | HEIL | DLCSRBH24AAK | EN(A,D)4X30L14** | *95ESN0601412A* | 15,500 | $775 |
| No | 207099703 | HEIL | DLCSRBH24AAK | EA*4X36L17A* | *95ESN0601412A* | 15,500 | $775 |
| No | 207099701 | HEIL | DLCSRBH24AAK | EA*4X24L17A* | *95ESN0601412A* | 15,800 | $790 |
| No | 207099702 | HEIL | DLCSRBH24AAK | EA*4X25L17A* | *95ESN0601412A* | 15,200 | $760 |
| No | 207099706 | HEIL | DLCSRBH24AAK | EN(A,D)4X24L17** | *95ESN0601412A* | 15,600 | $780 |
| No | 207099705 | HEIL | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0601412A* | 15,300 | $765 |
| No | 207099707 | HEIL | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESN0601412A* | 15,500 | $775 |
| No | 207099708 | HEIL | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESN0601412A* | 15,500 | $775 |
| No | 207099662 | HEIL | DLCSRBH24AAK | EN(A,D)4X24L17** | *95ESN0601714A* | 15,600 | $780 |
| No | 207099663 | HEIL | DLCSRBH24AAK | EA*4X24L17A* | *95ESN0601714A* | 15,800 | $790 |
| No | 207099664 | HEIL | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESN0601714A* | 15,500 | $775 |
| No | 207099665 | HEIL | DLCSRBH24AAK | EA*4X36L17A* | *95ESN0601714A* | 15,400 | $770 |
| No | 207099666 | HEIL | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESN0601714A* | 15,500 | $775 |
| No | 207099696 | HEIL | DLCSRBH24AAK | EA*4X25L17A* | *95ESN0601714A* | 15,200 | $760 |
| No | 207099667 | HEIL | DLCSRBH24AAK | EA*4X30L17A* | *95ESN0601714A* | 15,500 | $775 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207099697 | HEIL | DLCSRBH24AAK | EA*4X36L21A* | *95ESN0601714A* | 15,400 | $770 |
| No | 207099698 | HEIL | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0601714A* | 15,200 | $760 |
| No | 207099700 | HEIL | DLCSRBH24AAK | EN(A,D)4X36L21** | *95ESN0601714A* | 15,500 | $775 |
| No | 207099699 | HEIL | DLCSRBH24AAK | EA*4X37L21A* | *95ESN0601714A* | 15,100 | $755 |
| No | 207099607 | HEIL | DLCSRBH24AAK | EN(A,D)4X24L17** | *95ESU0401712A* | 15,600 | $780 |
| No | 207099610 | HEIL | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESU0401712A* | 15,500 | $775 |
| No | 207099609 | HEIL | DLCSRBH24AAK | EA*4X24L17A* | *95ESU0401712A* | 15,700 | $785 |
| No | 207099676 | HEIL | DLCSRBH24AAK | EA*4X36L17A* | *96VTN0401712A* | 15,500 | $775 |
| No | 207099612 | HEIL | DLCSRBH24AAK | EA*4X36L17A* | *95ESU0401712A* | 15,400 | $770 |
| No | 207099613 | HEIL | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESU0401712A* | 15,500 | $775 |
| No | 207099672 | HEIL | DLCSRBH24AAK | EN(A,D)4X30L14** | *96VTN0401410A* | 15,600 | $780 |
| No | 207099671 | HEIL | DLCSRBH24AAK | EA*4X30L14A* | *96VTN0401410A* | 15,600 | $780 |
| No | 207099615 | HEIL | DLCSRBH24AAK | EA*4X30L17A* | *95ESU0401712A* | 15,500 | $775 |
| No | 207099682 | HEIL | DLCSRBH24AAK | EA*4X30L14A* | *96VTN0601412A* | 15,600 | $780 |
| No | 207099683 | HEIL | DLCSRBH24AAK | EN(A,D)4X30L14** | *96VTN0601412A* | 15,600 | $780 |
| No | 207099691 | HEIL | DLCSRBH24AAK | EA*4X24L17A* | *96VTN0801716A* | 15,700 | $785 |
| No | 207099684 | HEIL | DLCSRBH24AAK | EN(A,D)4X24L17** | *96VTN0601714A* | 15,600 | $780 |
| No | 207099685 | HEIL | DLCSRBH24AAK | EA*4X24L17A* | *96VTN0601714A* | 15,800 | $790 |
| No | 207099686 | HEIL | DLCSRBH24AAK | EN(A,D)4X30L17** | *96VTN0601714A* | 15,500 | $775 |
| No | 207099688 | HEIL | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *96VTN0601714A* | 15,500 | $775 |
| No | 207099687 | HEIL | DLCSRBH24AAK | EA*4X36L17A* | *96VTN0601714A* | 15,400 | $770 |
| No | 207099689 | HEIL | DLCSRBH24AAK | EA*4X30L17A* | *96VTN0601714A* | 15,500 | $775 |
| No | 207099690 | HEIL | DLCSRBH24AAK | EN(A,D)4X24L17** | *96VTN0801716A* | 15,600 | $780 |
| No | 207099693 | HEIL | DLCSRBH24AAK | EA*4X36L17A* | *96VTN0801716A* | 15,400 | $770 |
| No | 207099692 | HEIL | DLCSRBH24AAK | EN(A,D)4X30L17** | *96VTN0801716A* | 15,500 | $775 |
| No | 207099694 | HEIL | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *96VTN0801716A* | 15,500 | $775 |
| No | 207099695 | HEIL | DLCSRBH24AAK | EA*4X30L17A* | *96VTN0801716A* | 15,500 | $775 |
| No | 207099562 | HEIL | DLCSRBH24AAK | FXM4X24**AL | | 15,500 | $775 |
| No | 207099565 | HEIL | DLCSRBH24AAK | FMA4X24**AL* | | 16,000 | $800 |
| No | 207099567 | HEIL | DLCSRBH24AAK | FM(C,U)4Z24**AL* | | 16,100 | $805 |
| No | 207199228 | HEIL | DLCSRBH30AAK | EA*4X30L14A* | *80ES(N,L)0451412A* | 19,200 | $960 |
| No | 207199229 | HEIL | DLCSRBH30AAK | EN(A,D)4X30L14** | *80ES(N,L)0451412A* | 19,200 | $960 |
| No | 207199230 | HEIL | DLCSRBH30AAK | EA*4X30L17A* | *80ES(N,L)0451712A* | 19,100 | $955 |
| No | 207199231 | HEIL | DLCSRBH30AAK | EN(A,D)4X30L17** | *80ES(N,L)0451712A* | 19,100 | $955 |
| No | 207199232 | HEIL | DLCSRBH30AAK | EA*4X30L14A* | *80ES(N,L)0701412A* | 19,100 | $955 |
| No | 207199239 | HEIL | DLCSRBH30AAK | EA*4X30L17A* | *80ESU0401712A* | 19,000 | $950 |
| No | 207199234 | HEIL | DLCSRBH30AAK | EA*4X30L17A* | *80ES(N,L)0701716A* | 19,300 | $965 |
| No | 207199233 | HEIL | DLCSRBH30AAK | EN(A,D)4X30L14** | *80ES(N,L)0701412A* | 19,100 | $955 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207199236 | HEIL | DLCSRBH30AAK | EA*4X36L21A* | *80ES(N,L)0702116A* | 19,000 | $950 |
| No | 207199235 | HEIL | DLCSRBH30AAK | EN(A,D)4X30L17** | *80ES(N,L)0701716A* | 19,300 | $965 |
| No | 207199237 | HEIL | DLCSRBH30AAK | EN(A,D)4X36L21** | *80ES(N,L)0702116A* | 19,100 | $955 |
| No | 207199238 | HEIL | DLCSRBH30AAK | EN(A,D)4X36L21** | *80ES(N,L)0902116A* | 19,300 | $965 |
| No | 207199245 | HEIL | DLCSRBH30AAK | EA*4X30L17A* | *92ESN0801716A* | 19,100 | $955 |
| No | 207199240 | HEIL | DLCSRBH30AAK | EN(A,D)4X30L17** | *80ESU0401712A* | 19,000 | $950 |
| No | 207199241 | HEIL | DLCSRBH30AAK | EA*4X30L14A* | *92ESN0601412A* | 19,200 | $960 |
| No | 207199242 | HEIL | DLCSRBH30AAK | EN(A,D)4X30L14** | *92ESN0601412A* | 19,200 | $960 |
| No | 207199243 | HEIL | DLCSRBH30AAK | EA*4X30L17A* | *92ESN0601714A* | 19,100 | $955 |
| No | 207199246 | HEIL | DLCSRBH30AAK | EN(A,D)4X30L17** | *92ESN0801716A* | 19,100 | $955 |
| No | 207199265 | HEIL | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0401712A* | 19,300 | $965 |
| No | 207199263 | HEIL | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0401410A* | 19,100 | $955 |
| No | 207199264 | HEIL | DLCSRBH30AAK | END4X42L17** | *95ESN0401410A* | 19,200 | $960 |
| No | 207199244 | HEIL | DLCSRBH30AAK | EN(A,D)4X30L17** | *92ESN0601714A* | 19,100 | $955 |
| No | 207199269 | HEIL | DLCSRBH30AAK | EA*4X42L21A* | *95ESN0401712A* | 19,200 | $960 |
| No | 207199266 | HEIL | DLCSRBH30AAK | EA*4X36L21A* | *95ESN0401712A* | 19,300 | $965 |
| No | 207199267 | HEIL | DLCSRBH30AAK | EA*4X36L17A* | *95ESN0401712A* | 19,300 | $965 |
| No | 207199270 | HEIL | DLCSRBH30AAK | EA*4X43L21A* | *95ESN0401712A* | 18,700 | $935 |
| No | 207199268 | HEIL | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0401712A* | 19,000 | $950 |
| No | 207199271 | HEIL | DLCSRBH30AAK | END4X42L17** | *95ESN0401712A* | 19,100 | $955 |
| No | 207199273 | HEIL | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0601412A* | 19,300 | $965 |
| No | 207199272 | HEIL | DLCSRBH30AAK | EA*4X30L14A* | *95ESN0601412A* | 19,300 | $965 |
| No | 207199274 | HEIL | DLCSRBH30AAK | EA*4X36L17A* | *95ESN0601412A* | 19,200 | $960 |
| No | 207199277 | HEIL | DLCSRBH30AAK | EN(A,D,W)4X36L17** | *95ESN0601412A* | 19,300 | $965 |
| No | 207199275 | HEIL | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0601412A* | 19,000 | $950 |
| No | 207199276 | HEIL | DLCSRBH30AAK | EN(A,D)4X30L14** | *95ESN0601412A* | 19,300 | $965 |
| No | 207199283 | HEIL | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0601714A* | 19,000 | $950 |
| No | 207199279 | HEIL | DLCSRBH30AAK | END4X42L17** | *95ESN0601412A* | 19,100 | $955 |
| No | 207199278 | HEIL | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESN0601412A* | 19,300 | $965 |
| No | 207199282 | HEIL | DLCSRBH30AAK | EA*4X36L21A* | *95ESN0601714A* | 19,200 | $960 |
| No | 207199280 | HEIL | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0601714A* | 19,300 | $965 |
| No | 207199281 | HEIL | DLCSRBH30AAK | EA*4X36L17A* | *95ESN0601714A* | 19,200 | $960 |
| No | 207199284 | HEIL | DLCSRBH30AAK | EA*4X42L21A* | *95ESN0601714A* | 19,100 | $955 |
| No | 207199285 | HEIL | DLCSRBH30AAK | EA*4X37L21A* | *95ESN0601714A* | 18,700 | $935 |
| No | 207199286 | HEIL | DLCSRBH30AAK | EA*4X43L21A* | *95ESN0601714A* | 18,700 | $935 |
| No | 207199287 | HEIL | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESN0601714A* | 19,200 | $960 |
| No | 207199288 | HEIL | DLCSRBH30AAK | EN(A,D)4X36L21** | *95ESN0601714A* | 19,200 | $960 |
| No | 207199289 | HEIL | DLCSRBH30AAK | EN(A,D,W)4X36L17** | *95ESN0601714A* | 19,200 | $960 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207199290 | HEIL | DLCSRBH30AAK | END4X42L17** | *95ESN0601714A* | 19,000 | $950 |
| No | 207199247 | HEIL | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0801716A* | 19,300 | $965 |
| No | 207199291 | HEIL | DLCSRBH30AAK | EN(A,D,W)4X42L21** | *95ESN0601714A* | 19,100 | $955 |
| No | 207199248 | HEIL | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESN0801716A* | 19,300 | $965 |
| No | 207199249 | HEIL | DLCSRBH30AAK | EA*4X36L21A* | *95ESN0802120A* | 19,100 | $955 |
| No | 207199250 | HEIL | DLCSRBH30AAK | EA*4X30L17A* | *95ESU0401712A* | 19,000 | $950 |
| No | 207199251 | HEIL | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESU0401712A* | 19,000 | $950 |
| No | 207199252 | HEIL | DLCSRBH30AAK | EA*4X30L17A* | *96VTN0401712A* | 19,300 | $965 |
| No | 207199253 | HEIL | DLCSRBH30AAK | EN(A,D)4X30L14** | *96VTN0601412A* | 19,300 | $965 |
| No | 207199255 | HEIL | DLCSRBH30AAK | EN(A,D)4X30L17** | *96VTN0601714A* | 19,100 | $955 |
| No | 207199254 | HEIL | DLCSRBH30AAK | EA*4X30L17A* | *96VTN0601714A* | 19,100 | $955 |
| No | 207199256 | HEIL | DLCSRBH30AAK | EA*4X30L17A* | *96VTN0801716A* | 19,100 | $955 |
| No | 207199258 | HEIL | DLCSRBH30AAK | EA*4X36L21A* | *96VTN0802120A* | 18,800 | $940 |
| No | 207199257 | HEIL | DLCSRBH30AAK | EN(A,D)4X30L17** | *96VTN0801716A* | 19,100 | $955 |
| No | 207199259 | HEIL | DLCSRBH30AAK | EN(A,D)4X36L21** | *96VTN0802120A* | 19,000 | $950 |
| No | 207199260 | HEIL | DLCSRBH30AAK | EA*4X36L21A* | *96VTN1002120A* | 18,800 | $940 |
| No | 207200409 | HEIL | DLCSRBH30AAK | EN(A,D)4X36L21** | *96VTN1002120A* | 20,800 | $1,040 |
| No | 207198929 | HEIL | DLCSRBH30AAK | FVM4X36***L | | 19,200 | $960 |
| No | 207199223 | HEIL | DLCSRBH30AAK | FEM4P30**AL | | 19,100 | $955 |
| No | 207199224 | HEIL | DLCSRBH30AAK | FEM4X30**BL | | 19,100 | $955 |
| No | 207199225 | HEIL | DLCSRBH30AAK | FMA4X30**AL* | | 19,400 | $970 |
| No | 207199226 | HEIL | DLCSRBH30AAK | FXM4X30**AL | | 18,800 | $940 |
| No | 207199227 | HEIL | DLCSRBH30AAK | FM(C,U)4Z30**AL* | | 19,200 | $960 |
| No | 206188305 | HEIL | DLCLRBH36AAK | DLFLDAH36XAK | | 27,000 | $1,350 |
| No | 207643054 | HEIL | DLCMHBH24CAK | Heat pump with ducts | | 18,500 | $925 |
| No | 207643069 | HEIL | DLCMRBH48EAK | Heat pump with ducts | | 30,400 | $1,520 |
| No | 207643051 | HEIL | DLCMRBH18BAK | Heat pump with ducts | | 11,800 | $590 |
| No | 207643055 | HEIL | DLCMHBH24CAK | Combination heat pumps with or without ducts | | 15,900 | $795 |
| No | 207643052 | HEIL | DLCMRBH18BAK | Combination heat pumps with or without ducts | | 11,800 | $590 |
| No | 207643070 | HEIL | DLCMRBH48EAK | Combination heat pumps with or without ducts | | 30,600 | $1,530 |
| No | 207643053 | HEIL | DLCMHBH24CAK | Heat pump without ducts | | 13,300 | $665 |
| No | 207643050 | HEIL | DLCMRBH18BAK | Heat pump without ducts | | 11,800 | $590 |
| No | 207643060 | HEIL | DLCMRBH36DAK | Heat pump without ducts | | 24,000 | $1,200 |
| No | 206350415 | HEIL | DLCSRBH09AAK | DLFSCAH09XAK | | 6,100 | $305 |
| No | 206350416 | HEIL | DLCSRBH09AAK | DLFSDAH09XAK | | 6,400 | $320 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206361885 | HEIL | DLCSRBH12AAK | DLFSHBH12XAK | | 7,300 | $365 |
| No | 206350418 | HEIL | DLCSRBH12AAK | DLFSDAH12XAK | | 8,300 | $415 |
| No | 206396099 | HEIL | DLCSRAH12AAK | DLFSHBH12XAK | | 7,500 | $375 |
| No | 206396098 | HEIL | DLCSRBH12AAK | DLFSHAH12XAK | | 7,500 | $375 |
| No | 206396102 | HEIL | DLCSRAH24AAK | DLFSHBH24XAK | | 15,000 | $750 |
| No | 206396103 | HEIL | DLCSRBH24AAK | DLFSHAH24XAK | | 15,000 | $750 |
| No | 206361883 | HEIL | DLCSRBH12AAJ | DLFSHBH12XAJ | | 8,200 | $410 |
| No | 206361887 | HEIL | DLCSRBH24AAK | DLFSHBH24XAK | | 17,000 | $850 |
| No | 206361886 | HEIL | DLCSRBH18AAK | DLFSHBH18XAK | | 11,100 | $555 |
| No | 206361884 | HEIL | DLCSRBH09AAK | DLFSHBH09XAK | | 7,400 | $370 |
| No | 206350417 | HEIL | DLCSRBH12AAK | DLFSCAH12XAK | | 7,900 | $395 |
| No | 206350419 | HEIL | DLCSRBH12AAK | DLFSFAH12XAK | | 8,400 | $420 |
| No | 205767349 | HEIL | DLCLRBH36AAK | DLFLAAH36XAK | | 25,000 | $1,250 |
| No | 205767350 | HEIL | DLCLRBH48AAK | DLFLAAH48XAK | | 36,000 | $1,800 |
| No | 201835680 | HEIL | DLCSRAH36AAK | DLFSHAH36XAK | | 20,600 | $1,030 |
| No | 202463648 | HEIL | DLCPRAH18AAK | DLFPHAH18XAK | | 12,300 | $615 |
| No | 201835694 | HEIL | DLCMRAH48EAK | Heat pump without ducts | | 30,400 | $1,520 |
| No | 201835692 | HEIL | DLCMRAH36DAK | Heat pump without ducts | | 23,600 | $1,180 |
| No | 201835668 | HEIL | DLCSRAH12AAJ | DLFSHAH12XAJ | | 7,100 | $355 |
| No | 201835654 | HEIL | DLCPRAH12AAK | DLFPHAH12XAK | | 6,800 | $340 |
| No | 201835653 | HEIL | DLCPRAH09AAK | DLFPHAH09XAK | | 7,200 | $360 |
| No | 201835670 | HEIL | DLCSRAH09AAK | DLFSHAH09XAK | | 7,500 | $375 |
| No | 201835686 | HEIL | DLCLRAH58AAK | DLFLDAH58XAK | | 37,600 | $1,880 |
| No | 201835674 | HEIL | DLCSRAH18AAK | DLFSHAH18XAK | | 11,900 | $595 |
| No | 201835672 | HEIL | DLCSRAH12AAK | DLFSHAH12XAK | | 7,600 | $380 |
| No | 201835732 | HEIL | DLCLRAH48AAK | DLFLCAH48XAK | | 35,000 | $1,750 |
| No | 201835734 | HEIL | DLCLRAH58AAK | DLFLFAH58XAK | | 39,000 | $1,950 |
| No | 201835684 | HEIL | DLCLRAH48AAK | DLFLDAH48XAK | | 33,400 | $1,670 |
| No | 201835682 | HEIL | DLCLRAH36AAK | DLFLDAH36XAK | | 27,600 | $1,380 |
| No | 201835712 | HEIL | DLCSRAH12AAK | DLFSDAH12XAK | | 8,100 | $405 |
| No | 201835710 | HEIL | DLCSRAH12AAK | DLFSFAH12XAK | | 9,600 | $480 |
| No | 201835726 | HEIL | DLCLRAH36AAK | DLFLCAH36XAK | | 25,200 | $1,260 |
| No | 201835706 | HEIL | DLCSRAH09AAK | DLFSCAH09XAK | | 6,700 | $335 |
| No | 201835714 | HEIL | DLCSRAH18AAK | DLFSFAH18XAK | | 12,900 | $645 |
| No | 201835708 | HEIL | DLCSRAH12AAK | DLFSCAH12XAK | | 8,200 | $410 |
| No | 201835724 | HEIL | DLCLRAH36AAK | DLFLFAH36XAK | | 25,400 | $1,270 |
| No | 201835704 | HEIL | DLCSRAH09AAK | DLFSDAH09XAK | | 6,800 | $340 |
| No | 204344217 | Hisense | AVW-60H3FH | AVC-09HJFA1 | | 48,000 | $2,400 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204344216 | Hisense | AVW-48H3FH | AVC-09HJFA1 | | 42,000 | $2,100 |
| No | 204344213 | Hisense | AVW-48H3FH | AVD-12HCFCH1 | | 42,000 | $2,100 |
| No | 204344215 | Hisense | AVW-36H3FH | AVC-09HJFA1 | | 33,000 | $1,650 |
| No | 204344212 | Hisense | AVW-36H3FH | AVD-09HCFCH1 | | 33,000 | $1,650 |
| No | 211717255 | HISENSE | AST-18UW3SBB**00 | AST-18UW3SBB**00 | | 11,600 | $580 |
| No | 211717256 | HISENSE | AST-12UW3SXE**01 | AST-12UW3SXE**01 | | 7,500 | $375 |
| No | 211717253 | HISENSE | AS-12UW3SXA**00 | AS-12UW3SXA**00 | | 7,000 | $350 |
| No | 205123811 | HISENSE | AMW5-42U3STA | Heat pump with ducts | | 28,400 | $1,420 |
| No | 205123813 | HISENSE | AMW5-42U3STA | Combination heat pumps with or without ducts | | 27,600 | $1,380 |
| No | 205123812 | HISENSE | AMW5-42U3STA | Heat pump without ducts | | 27,000 | $1,350 |
| No | 203459336 | HISENSE | AMW4-36U3STA | Heat pump with ducts | | 23,000 | $1,150 |
| No | 203978168 | HISENSE | AMW4-36U3STA | Combination heat pumps with or without ducts | | 22,600 | $1,130 |
| No | 203446790 | HISENSE | AMW3-24U3SAA | Heat pump with ducts | | 14,600 | $730 |
| No | 203978167 | HISENSE | AMW3-24U3SAA | Combination heat pumps with or without ducts | | 14,800 | $740 |
| No | 203978137 | HISENSE | AMW3-24U3SAA | Heat pump without ducts | | 15,000 | $750 |
| No | 204816625 | HISENSE | AMW2-18U3SFA | Heat pump with ducts | | 12,700 | $635 |
| No | 211295703 | HISENSE | AUW-36U3ST1 | AS-36UW3SDHVT00 | | 26,600 | $1,330 |
| No | 211302341 | HISENSE | AUW-24U3SA | AST-24UW3SDBDL01 | | 19,000 | $950 |
| No | 211302340 | HISENSE | AUW-18U3SF | AST-18UW3SBBDL00 | | 12,000 | $600 |
| No | 211302339 | HISENSE | AUW-12U3SS | AST-12UW3SXEDL01 | | 8,000 | $400 |
| No | 211302338 | HISENSE | AUW-09U3SS | AST-09UW3SVEDL01 | | 5,800 | $290 |
| No | 208193235 | HISENSE | AS-24UW3SKK00 | AS-24UW3SKK**00 | | 15,500 | $775 |
| No | 203377564 | HISENSE | AS-12UW1SXE00 | AS-12UW1SXE**00 | | 7,500 | $375 |
| No | 203377293 | HISENSE | AS-09UW1SVE00 | AS-09UW1SVE**00 | | 5,000 | $250 |
| No | 208193234 | HISENSE | AST-18UW3SBB01 | AST-18UW3SBB**01 | | 10,500 | $525 |
| No | 208193233 | HISENSE | AST-12UW3SXE02 | AST-12UW3SXE**02 | | 6,800 | $340 |
| No | 208193232 | HISENSE | AST-09UW3SXE01 | AST-09UW3SXE**01 | | 5,500 | $275 |
| No | 201981254 | HISENSE | AS-12UW3SXA00 | AS-12UW3SXA**00 | | 8,000 | $400 |
| No | 201981253 | HISENSE | AS-09UW3SXE00 | AS-09UW3SXE**00 | | 6,500 | $325 |
| No | 203378283 | HISENSE | AST-18UW3SBB00 | AST-18UW3SBB**00 | | 11,600 | $580 |
| No | 203845999 | HISENSE | AST-12UW3SXE01 | AST-12UW3SXE**01 | | 7,500 | $375 |
| No | 203377929 | HISENSE | AST-09UW3SVE01 | AST-09UW3SVE**01 | | 5,000 | $250 |
| No | 202911535 | HISENSE | AMW4-36U3STA | AST-09UW3SVE**00,AST-09UW3SVE**00,AST-09UW3SVE**00,AST-09UW3SVE**00 | | 22,400 | $1,120 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204816954 | HISENSE | AMW2-18U3SFA | ACT-09UR3SCA,ACT-09UR3SCA | | 12,700 | $635 |
| No | 204816953 | HISENSE | AMW2-18U3SFA | AST-09UW3SVG**01,AST-09UW3SVG**01 | | 12,700 | $635 |
| No | 206903534 | HISENSE | AUWR-60U3SP2 | AUH-60UX3SEH2 | | 40,000 | $2,000 |
| No | 206903533 | HISENSE | AUWR-48U3SP2 | AUH-48UX3SEH2 | | 31,000 | $1,550 |
| No | 206903535 | HISENSE | AUWR-36U3SA2 | AUH-36UX3SDH2 | | 24,000 | $1,200 |
| No | 206903532 | HISENSE | AUWR-24U3SF2 | AUH-24UX3SDH2 | | 15,000 | $750 |
| No | 205141567 | HISENSE | AUW-36U3ST1 | AUC-36UR3SHB1 | | 28,000 | $1,400 |
| No | 203167189 | HISENSE | AUW-24U3SA | ACT-24UR3SGB | | 19,000 | $950 |
| No | 205013613 | HISENSE | AUW-18U3SF | ACT-18UR3SGB | | 12,000 | $600 |
| No | 204976793 | HISENSE | AUW-12U3SS | ACT-12UR3SCA | | 7,600 | $380 |
| No | 204835478 | HISENSE | AUW-09U3SS | ACT-09UR3SCA | | 7,200 | $360 |
| No | 205141571 | HISENSE | AUW-36U3ST1 | AUD-36UX3SHH1 | | 28,400 | $1,420 |
| No | 205013614 | HISENSE | AUW-18U3SF | ADT-18UX3SCL | | 13,000 | $650 |
| No | 204976792 | HISENSE | AUW-12U3SS | ADT-12UX3SBL | | 7,800 | $390 |
| No | 204835479 | HISENSE | AUW-09U3SS | ADT-09UX3SBL | | 6,500 | $325 |
| No | 207641267 | HISENSE | AUW-24U3SA | AST-24UW3SDBTV01 | | 15,600 | $780 |
| No | 207641269 | HISENSE | AUW-12U3SS | AST-12UW3SXETV01 | | 7,300 | $365 |
| No | 207641268 | HISENSE | AUW-09U3SS | AST-09UW3SVETV01 | | 5,500 | $275 |
| No | 207641266 | HISENSE | AUW-18U3SF | AST-18UW3SBBTV00 | | 11,400 | $570 |
| No | 207641265 | HISENSE | AUW-36U3ST1 | AS-36UW3SDHTU00 | | 26,000 | $1,300 |
| No | 202864314 | HISENSE | AMW3-24U3SAA | AST-07UW3SVE**00AST-09UW3SVE**00AST-09UW3SVE**00 | | 15,400 | $770 |
| No | 203994976 | HITACHI | HVAHP048B21S* | HIDM024B21S, HIDM024B21S | | 32,000 | $1,600 |
| No | 203994970 | HITACHI | HVAHP048B21S* | HIC4012B21S, HIC4012B21S, HIC4012B21S, HIC4012B21S | | 32,000 | $1,600 |
| No | 203994978 | HITACHI | HVAHP060B21S* | HIDM030B21S, HIDM030B21S | | 42,000 | $2,100 |
| No | 203995170 | HITACHI | HVAHP048B21S* | NULL | | 32,000 | $1,600 |
| No | 203994965 | HITACHI | HVAHP060B21S* | HIC4012B21S, HIC4012B21S, HIC4012B21S, HIC4012B21S, HIC4012B21S | | 42,000 | $2,100 |
| No | 203995172 | HITACHI | HVAHP060B21S* | NULL | | 42,000 | $2,100 |
| No | 207656964 | HITACHI | RAS-4.0PNNBDH1 | RPK-4.0PNN1DH | | 26,000 | $1,300 |
| No | 207656960 | HITACHI | RAS-1.0PNNBDH1 | RPK-1.0PNN1DH | | 5,500 | $275 |
| No | 207656963 | HITACHI | RAS-3.0PNNBDH1 | RPK-3.0PNN1DH | | 15,600 | $780 |
| No | 207656961 | HITACHI | RAS-1.5PNNBDH1 | RPK-1.5PNN1DH | | 7,300 | $365 |
| No | 207656962 | HITACHI | RAS-2.0PNNBDH1 | RPK-2.0PNN1DH | | 11,400 | $570 |
| No | 206750854 | HITACHI | RAS-1.5PNNBDH1 | RPIL-1.5PNN1DH | | 6,600 | $330 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206750852 | HITACHI | RAS-1.0PNNBDH1 | RPIL-1.0PNN1DH | | 6,000 | $300 |
| No | 206750856 | HITACHI | RAS-2.0PNNBDH1 | RPIL-2.0PNN1DH | | 12,000 | $600 |
| No | 206750851 | HITACHI | RAS-1.0PNNBDH1 | RCIM-1.0PNN1DH | | 6,000 | $300 |
| No | 206750853 | HITACHI | RAS-1.5PNNBDH1 | RCIM-1.5PNN1DH | | 7,000 | $350 |
| No | 206750855 | HITACHI | RAS-2.0PNNBDH1 | RCI-2.0PNN1DH | | 11,000 | $550 |
| No | 206750857 | HITACHI | RAS-3.0PNNBDH1 | RCI-3.0PNN1DH | | 19,600 | $980 |
| No | 206186275 | HITACHI | RAM-S18U2HLAE | RAS-SH09RHLAE , RAS-SH09RHLAE | | 14,900 | $745 |
| No | 206186278 | HITACHI | RAM-S24U3HLAE | RAS-SH09RHLAE , RAS-SH09RHLAE ' RAS-SH07RHLAE | | 16,000 | $800 |
| No | 206186276 | HITACHI | RAM-S36U4HLAE | RAS-SH09RHLAE ,RAS-SH09RHLAE , RAS-SH09RHLAE , RAS-SH09RHLAE | | 25,000 | $1,250 |
| No | 206186277 | HITACHI | RAM-S42U5HLAE | RAS-SH09RHLAE , RAS-SH12RHLAE , RAS-SH07RHLAE , RAS-SH07RHLAE , RAS-SH07RHLAE | | 32,000 | $1,600 |
| No | 206186279 | HITACHI | RAM-S18U2HLAE | RAD-SH09QHLAE , RAD-SH09QHLAE | | 15,300 | $765 |
| No | 206186280 | HITACHI | RAM-S24U3HLAE | RAD-SH09QHLAE , RAD-SH09QHLAE , RAD-SH07QHLAE | | 16,900 | $845 |
| No | 206186282 | HITACHI | RAM-S42U5HLAE | RAD-SH09QHLAE , RAD-SH09QHLAE , RAD-SH12QHLAE , RAD-SH12QHLAE | | 33,000 | $1,650 |
| No | 206907173 | HITACHI | RAC-SH12WHLAE | RAS-SH12RHLAE | | 9,400 | $470 |
| No | 206186281 | HITACHI | RAM-S36U4HLAE | RAD-SH09QHLAE , RAD-SH09QHLAE ,RAD-SH09QHLAE ,RAD-SH09QHLAE | | 25,000 | $1,250 |
| No | 206907172 | HITACHI | RAC-SH09WHLAE | RAS-SH09RHLAE | | 7,200 | $360 |
| No | 206143042 | HITACHI | RAC-SH24WHLAE | RAS-SH24RHLAE | | 15,100 | $755 |
| No | 206143041 | HITACHI | RAC-SH18WHLAE | RAS-SH18RHLAE | | 12,200 | $610 |
| No | 207200481 | HITACHI | RAC-PH09WHLAE | RAS-PH09PHLAE | | 8,000 | $400 |
| No | 207200482 | HITACHI | RAC-PH12WHLAE | RAS-PH12PHLAE | | 9,500 | $475 |
| No | 205261895 | ICP COMMERCIAL | 38VMA060HDS3-1 | Heat pump with ducts | | 42,000 | $2,100 |
| No | 205261904 | ICP COMMERCIAL | 38VMB060HDS3-1 | Heat pump with ducts | | 42,000 | $2,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205261905 | ICP COMMERCIAL | 38VMB060HDS3-1 | Combination heat pumps with or without ducts | | 42,000 | $2,100 |
| No | 205261894 | ICP COMMERCIAL | 38VMA060HDS3-1 | Heat pump without ducts | | 42,000 | $2,100 |
| No | 205261903 | ICP COMMERCIAL | 38VMB060HDS3-1 | Heat pump without ducts | | 42,000 | $2,100 |
| No | 205261896 | ICP COMMERCIAL | 38VMA060HDS3-1 | Combination heat pumps with or without ducts | | 42,000 | $2,100 |
| No | 210365429 | INNOVAIR | MHD-18 | MHD-CC2.0-17.5-M | | 13,000 | $650 |
| No | 208106863 | INNOVAIR | SEV60H2R19 | DEV60H2R19 | | 37,000 | $1,850 |
| No | 208106862 | INNOVAIR | SEV48H2R19 | DEV48H2R19 | | 37,000 | $1,850 |
| No | 208106861 | INNOVAIR | SEV36H2R19 | DEV36H2R19 | | 20,400 | $1,020 |
| No | 208106859 | INNOVAIR | SEV24H2R19 | DEV24H2R19 | | 21,000 | $1,050 |
| No | 208106858 | INNOVAIR | SEV18H2R19 | DEV18H2R19 | | 12,000 | $600 |
| No | 210343156 | INNOVAIR | SHV36H2R20 | DEV36H2R19 | | 30,400 | $1,520 |
| No | 208286577 | INNOVAIR | WIN24H7H51(O) | WIN24H7H51(I) | | 15,500 | $775 |
| No | 208286575 | INNOVAIR | WIN18H7H51(O) | WIN18H7H51(I) | | 10,500 | $525 |
| No | 208286574 | INNOVAIR | WIN12H7H51(O) | WIN12H7H51(I) | | 6,800 | $340 |
| No | 208286573 | INNOVAIR | WIN09H7H51(O) | WIN09H7H51(I) | | 5,500 | $275 |
| No | 207659305 | INNOVAIR | VIN1439H2V32(O) | VIN1439H2V32(I) | | 24,000 | $1,200 |
| No | 205129432 | INNOVAIR | VIN520H2V51(O) | VIN520H2V51(I) | | 11,000 | $550 |
| No | 205129429 | INNOVAIR | VIN310H1V51(O) | VIN310H1V51(I) | | 6,000 | $300 |
| No | 206362550 | INNOVAIR | VEA60H2V18 | DHV60H2V18 | | 35,095 | $1,755 |
| No | 208106860 | INNOVAIR | SEV30H2R19 | DEV30H2R19 | | 19,000 | $950 |
| No | 206362548 | INNOVAIR | VEA36H2V18 | DHV36H2V18 | | 23,243 | $1,162 |
| No | 207821948 | INNOVAIR | VOM18H7R2P7 | Heat pump without ducts | | 12,200 | $610 |
| No | 206362549 | INNOVAIR | VEA48H2V18 | DHV48H2V18 | | 27,541 | $1,377 |
| No | 207821954 | INNOVAIR | VOM36H7R4P7 | Heat pump without ducts | | 23,200 | $1,160 |
| No | 206330207 | INNOVAIR | EIN10H2V32(O) | EIN10H2V32(I) | | 5,600 | $280 |
| No | 206362547 | INNOVAIR | VEA24H2V18 | DHV24H2V18 | | 15,637 | $782 |
| No | 206330208 | INNOVAIR | EIN13H2V32(O) | EIN13H2V32(I) | | 8,100 | $405 |
| No | 207821951 | INNOVAIR | VOM24H7R3P7 | Heat pump without ducts | | 15,400 | $770 |
| No | 205965999 | JANITROL | GVZC200241A* | CA*F3642*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205966000 | JANITROL | GVZC200361A* | CA*F3743*6D*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 205966001 | JANITROL | GVZC200481A* | CA*F4961*6D*+MBVC2000**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966003 | JANITROL | GVZC200241A* | CA*F3137*6A*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205966002 | JANITROL | GVZC200241A* | CA*F3137*6A*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205966005 | JANITROL | GVZC200241A* | CA*F3137*6A*+TXV | G*VS800604BUA* | 13,000 | $650 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966006 | JANITROL | GVZC200241A* | CA*F3137*6A*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205966004 | JANITROL | GVZC200241A* | CA*F3137*6A*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205966007 | JANITROL | GVZC200241A* | CA*F3636*6D*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205966008 | JANITROL | GVZC200241A* | CA*F3636*6D*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205966010 | JANITROL | GVZC200241A* | CA*F3636*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205966011 | JANITROL | GVZC200241A* | CA*F3636*6D*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205966013 | JANITROL | GVZC200241A* | CA*F3642*6D*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205966009 | JANITROL | GVZC200241A* | CA*F3636*6D*+TXV | G*VM970804CNB* | 13,000 | $650 |
| No | 205966012 | JANITROL | GVZC200241A* | CA*F3636*6D*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205966018 | JANITROL | GVZC200241A* | CA*F3743*6D*+TXV | G*VM970804CNB* | 13,000 | $650 |
| No | 205966016 | JANITROL | GVZC200241A* | CA*F3743*6D*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205966015 | JANITROL | GVZC200241A* | CA*F3642*6D*+TXV | G*VM970804CNB* | 13,000 | $650 |
| No | 205966017 | JANITROL | GVZC200241A* | CA*F3743*6D*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205966014 | JANITROL | GVZC200241A* | CA*F3642*6D*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205966019 | JANITROL | GVZC200241A* | CA*F3743*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205966021 | JANITROL | GVZC200241A* | CA*F3743*6D*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205966020 | JANITROL | GVZC200241A* | CA*F3743*6D*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205966022 | JANITROL | GVZC200241A* | CHPF3636B6C*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205966024 | JANITROL | GVZC200241A* | CHPF3636B6C*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205966025 | JANITROL | GVZC200241A* | CHPF3636B6C*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205966023 | JANITROL | GVZC200241A* | CHPF3636B6C*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205966028 | JANITROL | GVZC200241A* | CSCF3642N6D*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205966026 | JANITROL | GVZC200241A* | CHPF3636B6C*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205966037 | JANITROL | GVZC200361A* | CA*F3137*6A*+TXV | G*VM970603BNB* | 18,200 | $910 |
| No | 205966027 | JANITROL | GVZC200241A* | CHPF3642C6C*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205966029 | JANITROL | GVZC200241A* | CSCF3642N6D*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205966034 | JANITROL | GVZC200241A* | CA*F3743*6D*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205966030 | JANITROL | GVZC200241A* | AVPEC25B14A* | | 13,600 | $680 |
| No | 205966032 | JANITROL | GVZC200241A* | CA*F3636*6D*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205966031 | JANITROL | GVZC200241A* | CA*F3137*6A*+MBVC1201**-1A*+TXV | | 13,000 | $650 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966033 | JANITROL | GVZC200241A* | CA*F3642*6D*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205966040 | JANITROL | GVZC200361A* | CA*F3137*6A*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 205966038 | JANITROL | GVZC200361A* | CA*F3137*6A*+TXV | G*VM970803BNB* | 18,200 | $910 |
| No | 205966036 | JANITROL | GVZC200241A* | CHPF3642C6C*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205966039 | JANITROL | GVZC200361A* | CA*F3137*6A*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 205966035 | JANITROL | GVZC200241A* | CHPF3636B6C*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205966048 | JANITROL | GVZC200361A* | CA*F3642*6D*+TXV | G*VM970803BNB* | 18,000 | $900 |
| No | 205966049 | JANITROL | GVZC200361A* | CA*F3642*6D*+TXV | G*VM970804CNB* | 18,200 | $910 |
| No | 205966050 | JANITROL | GVZC200361A* | CA*F3642*6D*+TXV | G*VM971005CNB* | 18,000 | $900 |
| No | 205966047 | JANITROL | GVZC200361A* | CA*F3642*6D*+TXV | G*VM970603BNB* | 18,000 | $900 |
| No | 205966041 | JANITROL | GVZC200361A* | CA*F3137*6A*+TXV | G*VS800604BUA* | 18,200 | $910 |
| No | 205966046 | JANITROL | GVZC200361A* | CA*F3137*6A*+TXV | G*VS960603BUA* | 18,200 | $910 |
| No | 205966052 | JANITROL | GVZC200361A* | CA*F3642*6D*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 205966051 | JANITROL | GVZC200361A* | CA*F3642*6D*+TXV | G*VM971205DNB* | 18,000 | $900 |
| No | 205966053 | JANITROL | GVZC200361A* | CA*F3642*6D*+MBVC1600**-1A*+TXV | | 18,000 | $900 |
| No | 205966056 | JANITROL | GVZC200361A* | CA*F3642*6D*+TXV | G*VS960603BUA* | 18,000 | $900 |
| No | 205966054 | JANITROL | GVZC200361A* | CA*F3642*6D*+TXV | G*VS800604BUA* | 18,200 | $910 |
| No | 205966055 | JANITROL | GVZC200361A* | CA*F3642*6D*+TXV | G*VS800805CUA* | 18,000 | $900 |
| No | 205966057 | JANITROL | GVZC200361A* | CA*F3642*6D*+TXV | G*VS960805CUA* | 18,000 | $900 |
| No | 205966059 | JANITROL | GVZC200361A* | CA*F3743*6D*+TXV | G*VM970803BNB* | 18,200 | $910 |
| No | 205966058 | JANITROL | GVZC200361A* | CA*F3743*6D*+TXV | G*VM970603BNB* | 18,200 | $910 |
| No | 205966072 | JANITROL | GVZC200361A* | CHPF3642C6C*+TXV | G*VS800604BUA* | 18,000 | $900 |
| No | 205966060 | JANITROL | GVZC200361A* | CA*F3743*6D*+TXV | G*VM971205DNB* | 18,200 | $910 |
| No | 205966061 | JANITROL | GVZC200361A* | CA*F3743*6D*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 205966063 | JANITROL | GVZC200361A* | CA*F3743*6D*+TXV | G*VS800805CUA* | 18,200 | $910 |
| No | 205966064 | JANITROL | GVZC200361A* | CA*F3743*6D*+TXV | G*VS960603BUA* | 18,200 | $910 |
| No | 205966062 | JANITROL | GVZC200361A* | CA*F3743*6D*+TXV | G*VS800604BUA* | 18,000 | $900 |
| No | 205966065 | JANITROL | GVZC200361A* | CA*F3743*6D*+TXV | G*VS960805CUA* | 18,200 | $910 |
| No | 205966066 | JANITROL | GVZC200361A* | CHPF3642C6C*+TXV | G*VM970603BNB* | 18,000 | $900 |
| No | 205966069 | JANITROL | GVZC200361A* | CHPF3642C6C*+TXV | G*VM971005CNB* | 18,000 | $900 |
| No | 205966067 | JANITROL | GVZC200361A* | CHPF3642C6C*+TXV | G*VM970803BNB* | 18,000 | $900 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966068 | JANITROL | GVZC200361A* | CHPF3642C6C*+TXV | G*VM970804CNB* | 18,000 | $900 |
| No | 205966071 | JANITROL | GVZC200361A* | CHPF3642C6C*+MBVC1600**-1A*+TXV | | 18,000 | $900 |
| No | 205966070 | JANITROL | GVZC200361A* | CHPF3642C6C*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 205966086 | JANITROL | GVZC200361A* | CSCF3642N6D*+TXV | G*VM970603BNB* | 18,200 | $910 |
| No | 205966075 | JANITROL | GVZC200361A* | CHPF3642C6C*+TXV | G*VS960805CUA* | 18,000 | $900 |
| No | 205966073 | JANITROL | GVZC200361A* | CHPF3642C6C*+TXV | G*VS800805CUA* | 18,000 | $900 |
| No | 205966077 | JANITROL | GVZC200361A* | CHPF3743C6B*+TXV | G*VM970803BNB* | 18,200 | $910 |
| No | 205966076 | JANITROL | GVZC200361A* | CHPF3743C6B*+TXV | G*VM970603BNB* | 18,200 | $910 |
| No | 205966074 | JANITROL | GVZC200361A* | CHPF3642C6C*+TXV | G*VS960603BUA* | 18,000 | $900 |
| No | 205966078 | JANITROL | GVZC200361A* | CA*F3743*6D*+TXV | G*VM970804CNB* | 18,000 | $900 |
| No | 205966079 | JANITROL | GVZC200361A* | CA*F3743*6D*+TXV | G*VM971005CNB* | 18,200 | $910 |
| No | 205966080 | JANITROL | GVZC200361A* | CHPF3743C6B*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 205966082 | JANITROL | GVZC200361A* | CHPF3743C6B*+TXV | G*VS800604BUA* | 18,200 | $910 |
| No | 205966081 | JANITROL | GVZC200361A* | CHPF3743C6B*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 205966089 | JANITROL | GVZC200361A* | CSCF3642N6D*+TXV | G*VM971005CNB* | 18,200 | $910 |
| No | 205966083 | JANITROL | GVZC200361A* | CHPF3743C6B*+TXV | G*VS800805CUA* | 18,200 | $910 |
| No | 205966087 | JANITROL | GVZC200361A* | CSCF3642N6D*+TXV | G*VM970803BNB* | 18,200 | $910 |
| No | 205966084 | JANITROL | GVZC200361A* | CHPF3743C6B*+TXV | G*VS960603BUA* | 18,200 | $910 |
| No | 205966088 | JANITROL | GVZC200361A* | CSCF3642N6D*+TXV | G*VM970804CNB* | 18,200 | $910 |
| No | 205966085 | JANITROL | GVZC200361A* | CHPF3743C6B*+TXV | G*VS960805CUA* | 18,200 | $910 |
| No | 205966090 | JANITROL | GVZC200361A* | CSCF3642N6D*+TXV | G*VM971205DNB* | 18,200 | $910 |
| No | 205966091 | JANITROL | GVZC200361A* | CSCF3642N6D*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 205966092 | JANITROL | GVZC200361A* | CSCF3642N6D*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 205966095 | JANITROL | GVZC200361A* | CSCF3642N6D*+TXV | G*VS960603BUA* | 18,200 | $910 |
| No | 205966093 | JANITROL | GVZC200361A* | CSCF3642N6D*+TXV | G*VS800604BUA* | 18,200 | $910 |
| No | 205966094 | JANITROL | GVZC200361A* | CSCF3642N6D*+TXV | G*VS800805CUA* | 18,200 | $910 |
| No | 205966104 | JANITROL | GVZC200361A* | CA*F3743*6D*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205966105 | JANITROL | GVZC200361A* | CHPF3642C6C*+MBVC1201**-1A*+TXV | | 18,000 | $900 |
| No | 205966103 | JANITROL | GVZC200361A* | CA*F3743*6D*+MBVC1201**-1A*+TXV | | 18,200 | $910 |
| No | 205966096 | JANITROL | GVZC200361A* | CSCF3642N6D*+TXV | G*VS960805CUA* | 18,200 | $910 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966098 | JANITROL | GVZC200361A* | AVPEC59D14A* | | 18,900 | $945 |
| No | 205966097 | JANITROL | GVZC200361A* | AVPEC37C14A* | | 18,900 | $945 |
| No | 205966099 | JANITROL | GVZC200361A* | CA*F3137*6A*+MBVC1201**-1A*+TXV | | 18,000 | $900 |
| No | 205966101 | JANITROL | GVZC200361A* | CA*F3642*6D*+MBVC1201**-1A*+TXV | | 18,000 | $900 |
| No | 205966100 | JANITROL | GVZC200361A* | CA*F3137*6A*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205966102 | JANITROL | GVZC200361A* | CA*F3642*6D*+MBVC1601**-1A*+TXV | | 18,000 | $900 |
| No | 205966106 | JANITROL | GVZC200361A* | CHPF3642C6C*+MBVC1601**-1A*+TXV | | 18,000 | $900 |
| No | 205966107 | JANITROL | GVZC200361A* | CHPF3743C6B*+MBVC1201**-1A*+TXV | | 18,200 | $910 |
| No | 205966113 | JANITROL | GVZC200481A* | CHPF4860D6D*+TXV | G*VM971205DNB* | 27,800 | $1,390 |
| No | 205966110 | JANITROL | GVZC200481A* | CA*F4860*6D*+TXV | G*VS960805CUA* | 27,400 | $1,370 |
| No | 205966108 | JANITROL | GVZC200361A* | CHPF3743C6B*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205966109 | JANITROL | GVZC200481A* | CA*F4860*6D*+MBVC1600**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966111 | JANITROL | GVZC200481A* | CHPF4860D6D*+TXV | G*VM970804CNB* | 28,000 | $1,400 |
| No | 205966112 | JANITROL | GVZC200481A* | CHPF4860D6D*+TXV | G*VM971005CNB* | 27,800 | $1,390 |
| No | 205966116 | JANITROL | GVZC200481A* | CSCF4860N6D*+TXV | G*VM970804CNB* | 27,400 | $1,370 |
| No | 205966118 | JANITROL | GVZC200481A* | CSCF4860N6D*+TXV | G*VM971205DNB* | 27,400 | $1,370 |
| No | 205966117 | JANITROL | GVZC200481A* | CSCF4860N6D*+TXV | G*VM971005CNB* | 27,400 | $1,370 |
| No | 205966119 | JANITROL | GVZC200481A* | CSCF4860N6D*+MBVC1600**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966114 | JANITROL | GVZC200481A* | CHPF4860D6D*+MBVC1600**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966115 | JANITROL | GVZC200481A* | CHPF4860D6D*+TXV | G*VS800805CUA* | 27,200 | $1,360 |
| No | 205966129 | JANITROL | GVZC200481A* | CSCF4860N6D*+MBVC1601**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966121 | JANITROL | GVZC200481A* | CSCF4860N6D*+TXV | G*VS800604BUA* | 27,400 | $1,370 |
| No | 205966120 | JANITROL | GVZC200481A* | CSCF4860N6D*+MBVC2000**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966122 | JANITROL | GVZC200481A* | CSCF4860N6D*+TXV | G*VS800805CUA* | 27,400 | $1,370 |
| No | 205966124 | JANITROL | GVZC200481A* | AVPEC59D14A* | | 27,000 | $1,350 |
| No | 205966123 | JANITROL | GVZC200481A* | CSCF4860N6D*+TXV | G*VS960805CUA* | 27,400 | $1,370 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966125 | JANITROL | GVZC200481A* | CA*F4860*6D*+MBVC1601**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966131 | JANITROL | GVZC200481A* | CA*F4961*6D*+TXV | G*VM970804CNB* | 27,800 | $1,390 |
| No | 205966128 | JANITROL | GVZC200481A* | CHPF4860D6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966127 | JANITROL | GVZC200481A* | CHPF4860D6D*+MBVC1601**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966126 | JANITROL | GVZC200481A* | CA*F4860*6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966130 | JANITROL | GVZC200481A* | CSCF4860N6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966132 | JANITROL | GVZC200481A* | CA*F4961*6D*+TXV | G*VM971005CNB* | 27,800 | $1,390 |
| No | 205966134 | JANITROL | GVZC200481A* | CA*F4961*6D*+MBVC1600**-1A*+TXV | | 26,800 | $1,340 |
| No | 205966133 | JANITROL | GVZC200481A* | CA*F4961*6D*+TXV | G*VM971205DNB* | 27,800 | $1,390 |
| No | 205966137 | JANITROL | GVZC200481A* | CA*F4961*6D*+TXV | G*VS960805CUA* | 27,600 | $1,380 |
| No | 205966135 | JANITROL | GVZC200481A* | CA*F4961*6D*+TXV | G*VS800604BUA* | 28,000 | $1,400 |
| No | 205966136 | JANITROL | GVZC200481A* | CA*F4961*6D*+TXV | G*VS800805CUA* | 27,200 | $1,360 |
| No | 205966459 | JANITROL | GVZC200361A* | CSCF3642N6D*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205966458 | JANITROL | GVZC200361A* | CSCF3642N6D*+MBVC1201**-1A*+TXV | | 18,200 | $910 |
| No | 205966138 | JANITROL | GVZC200481A* | CHPF4860D6D*+MBVC2000**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966460 | JANITROL | GVZC200481A* | CA*F4860*6D*+TXV | G*VM970804CNB* | 27,400 | $1,370 |
| No | 205966139 | JANITROL | GVZC200481A* | CA*F4961*6D*+MBVC1601**-1A*+TXV | | 26,800 | $1,340 |
| No | 205966140 | JANITROL | GVZC200481A* | CA*F4961*6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966464 | JANITROL | GVZC200481A* | CA*F4860*6D*+TXV | G*VS800805CUA* | 27,400 | $1,370 |
| No | 205966463 | JANITROL | GVZC200481A* | CA*F4860*6D*+MBVC2000**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966461 | JANITROL | GVZC200481A* | CA*F4860*6D*+TXV | G*VM971005CNB* | 27,400 | $1,370 |
| No | 205966462 | JANITROL | GVZC200481A* | CA*F4860*6D*+TXV | G*VM971205DNB* | 27,400 | $1,370 |
| No | 211583740 | J-KU | JKS12HP230V1XC | JKS12HP230V1XE | | 7,000 | $350 |
| No | 211583739 | J-KU | JKS09HP230V1XC | JKS09HP230V1XE | | 6,000 | $300 |
| No | 211238537 | JOHNSON CONTROLS | HMH72B341 | JHETC36DBCS2N1 | | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211662227 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+JMET12BS2N1+TXV | | 24,800 | $1,240 |
| No | 211662222 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+JMET12BS2N1+TXV | | 24,800 | $1,240 |
| No | 211662217 | JOHNSON CONTROLS | HMH72B361 | XAHB30CXXN1+JMET12BS2N1+TXV | | 23,800 | $1,190 |
| No | 211662212 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+JMVT12BC2N1+TXV | | 24,600 | $1,230 |
| No | 211662207 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+JMVT12BC2N1+TXV | | 24,600 | $1,230 |
| No | 211662202 | JOHNSON CONTROLS | HMH72B361 | XAHB30CXXN1+JMVT12BC2N1+TXV | | 24,200 | $1,210 |
| No | 211662197 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+TXV | TMLE040A12MP11 | 24,400 | $1,220 |
| No | 211662192 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+TXV | TM8E040A12MP11 | 24,400 | $1,220 |
| No | 211662187 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+TXV | TMLE040A12MP11 | 24,400 | $1,220 |
| No | 211662182 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+TXV | TM8E040A12MP11 | 24,400 | $1,220 |
| No | 211662177 | JOHNSON CONTROLS | HMH72B361 | XAHB30CXXN1+TXV | TMLE040A12MP11 | 23,800 | $1,190 |
| No | 211662172 | JOHNSON CONTROLS | HMH72B361 | XAHB30CXXN1+TXV | TM8E040A12MP11 | 23,800 | $1,190 |
| No | 211662167 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+TXV | TL8E060A12UH11 | 24,400 | $1,220 |
| No | 211662162 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+TXV | TL8E060A12UH11 | 24,400 | $1,220 |
| No | 211662157 | JOHNSON CONTROLS | HMH72B361 | XAHB30CXXN1+TXV | TL8E060A12UH11 | 24,000 | $1,200 |
| No | 211662152 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TL8E080C16UH11 | 25,200 | $1,260 |
| No | 211662147 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TL8E080C16UH11 | 24,800 | $1,240 |
| No | 211662142 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TL8E100C20UH11 | 24,400 | $1,220 |
| No | 211662137 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TL8E100C20UH11 | 24,000 | $1,200 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211662132 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 211662127 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 211662122 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 211662117 | JOHNSON CONTROLS | HMH72B361 | XAHB30CXXN1+TXV | TL9E060B12UH11 | 23,600 | $1,180 |
| No | 211662112 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 211662107 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TL9E080C16UH11 | 24,800 | $1,240 |
| No | 211662102 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TL9E080C16UH11 | 24,400 | $1,220 |
| No | 211662097 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TL9E100C20UH11 | 24,600 | $1,230 |
| No | 211662092 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TL9E100C20UH11 | 24,000 | $1,200 |
| No | 211662087 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+TXV | TMLE060A12MP11 | 24,400 | $1,220 |
| No | 211662082 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+TXV | TM8E060A12MP11 | 24,400 | $1,220 |
| No | 211662077 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+TXV | TMLE060A12MP11 | 24,400 | $1,220 |
| No | 211662072 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+TXV | TM8E060A12MP11 | 24,400 | $1,220 |
| No | 211662067 | JOHNSON CONTROLS | HMH72B361 | XAHB30CXXN1+TXV | TMLE060A12MP11 | 24,000 | $1,200 |
| No | 211662062 | JOHNSON CONTROLS | HMH72B361 | XAHB30CXXN1+TXV | TM8E060A12MP11 | 24,000 | $1,200 |
| No | 211662057 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 211662052 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 211662047 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 211662042 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211662037 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 211662032 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 211662027 | JOHNSON CONTROLS | HMH72B361 | XAHB30CXXN1+TXV | TMLE080B12MP11 | 24,400 | $1,220 |
| No | 211662022 | JOHNSON CONTROLS | HMH72B361 | XAHB30CXXN1+TXV | TM8E080B12MP11 | 24,400 | $1,220 |
| No | 211662017 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TMLE080B12MP11 | 24,400 | $1,220 |
| No | 211662012 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TM8E080B12MP11 | 24,400 | $1,220 |
| No | 211662007 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TMLE080C16MP11 | 24,200 | $1,210 |
| No | 211662002 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TM8E080C16MP11 | 24,200 | $1,210 |
| No | 211661997 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TMLE080C16MP11 | 23,800 | $1,190 |
| No | 211661992 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TM8E080C16MP11 | 23,800 | $1,190 |
| No | 211661987 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+TXV | TMLE100B12MP11 | 24,400 | $1,220 |
| No | 211661982 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+TXV | TM8E100B12MP11 | 24,400 | $1,220 |
| No | 211661977 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+TXV | TMLE100B12MP11 | 24,400 | $1,220 |
| No | 211661972 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+TXV | TM8E100B12MP11 | 24,400 | $1,220 |
| No | 211661967 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TMLE100B12MP11 | 24,400 | $1,220 |
| No | 211661962 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TM8E100B12MP11 | 24,400 | $1,220 |
| No | 211661957 | JOHNSON CONTROLS | HMH72B361 | XAHB30CXXN1+TXV | TMLE100B12MP11 | 24,000 | $1,200 |
| No | 211661952 | JOHNSON CONTROLS | HMH72B361 | XAHB30CXXN1+TXV | TM8E100B12MP11 | 24,000 | $1,200 |
| No | 211661947 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TMLE100B12MP11 | 24,000 | $1,200 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661942 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TM8E100B12MP11 | 24,000 | $1,200 |
| No | 211661937 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TMLE100C16MP11 | 24,200 | $1,210 |
| No | 211661932 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TM8E100C16MP11 | 24,200 | $1,210 |
| No | 211661927 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TMLE100C16MP11 | 23,800 | $1,190 |
| No | 211661922 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TM8E100C16MP11 | 23,800 | $1,190 |
| No | 211661917 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TMLE120C16MP11 | 24,200 | $1,210 |
| No | 211661912 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TM8E120C16MP11 | 24,200 | $1,210 |
| No | 211661907 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TMLE120C16MP11 | 23,800 | $1,190 |
| No | 211661902 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TM8E120C16MP11 | 23,800 | $1,190 |
| No | 211661897 | JOHNSON CONTROLS | HMH72B361 | XAFA30DXXN1+TXV | TPLC060A12MP13 | 25,800 | $1,290 |
| No | 211661892 | JOHNSON CONTROLS | HMH72B361 | XAFA30DXXN1+TXV | TMLV060A12MP12 | 25,800 | $1,290 |
| No | 211661887 | JOHNSON CONTROLS | HMH72B361 | XAFA30DXXN1+TXV | TM8V060A12MP12 | 25,800 | $1,290 |
| No | 211661882 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+TXV | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 211661877 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+TXV | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 211661872 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+TXV | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 211661867 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+TXV | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 211661862 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+TXV | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 211661857 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+TXV | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 211661852 | JOHNSON CONTROLS | HMH72B361 | XAHB30CXXN1+TXV | TPLC060A12MP13 | 24,200 | $1,210 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661847 | JOHNSON CONTROLS | HMH72B361 | XAHB30CXXN1+TXV | TMLV060A12MP12 | 24,200 | $1,210 |
| No | 211661842 | JOHNSON CONTROLS | HMH72B361 | XAHB30CXXN1+TXV | TM8V060A12MP12 | 24,200 | $1,210 |
| No | 211661836 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 211661831 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 211661825 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 211661820 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 211661814 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TPLC080B12MP13 | 24,800 | $1,240 |
| No | 211661809 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TM8V080B12MP12 | 24,800 | $1,240 |
| No | 211661803 | JOHNSON CONTROLS | HMH72B361 | XAHB30CXXN1+TXV | TPLC080B12MP13 | 24,000 | $1,200 |
| No | 211661798 | JOHNSON CONTROLS | HMH72B361 | XAHB30CXXN1+TXV | TM8V080B12MP12 | 24,000 | $1,200 |
| No | 211661792 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TPLC080B12MP13 | 24,200 | $1,210 |
| No | 211661787 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TM8V080B12MP12 | 24,200 | $1,210 |
| No | 211661778 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TPLC100C16MP13 | 25,000 | $1,250 |
| No | 211661773 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TPLC080C16MP13 | 25,000 | $1,250 |
| No | 211661768 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TMLV100C16MP12 | 25,000 | $1,250 |
| No | 211661763 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TM8V080C16MP12 | 25,000 | $1,250 |
| No | 211661758 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TM8V100C16MP12 | 25,000 | $1,250 |
| No | 211661749 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 211661744 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TPLC080C16MP13 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661739 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TMLV100C16MP12 | 24,600 | $1,230 |
| No | 211661729 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 211661724 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+TXV | TM8Y060A12MP11 | 24,200 | $1,210 |
| No | 211661719 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+TXV | TM8Y060A12MP11 | 24,200 | $1,210 |
| No | 211661714 | JOHNSON CONTROLS | HMH72B361 | XAHB30CXXN1+TXV | TM8Y060A12MP11 | 23,800 | $1,190 |
| No | 211661709 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+TXV | TM8Y080B12MP11 | 24,200 | $1,210 |
| No | 211661704 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+TXV | TM8Y080B12MP11 | 24,200 | $1,210 |
| No | 211661699 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TM8Y080B12MP11 | 24,200 | $1,210 |
| No | 211661694 | JOHNSON CONTROLS | HMH72B361 | XAHB30CXXN1+TXV | TM8Y080B12MP11 | 23,800 | $1,190 |
| No | 211661689 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TM8Y080B12MP11 | 23,800 | $1,190 |
| No | 211661684 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TM8Y080C16MP11 | 25,200 | $1,260 |
| No | 211661679 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TM8Y100C16MP11 | 25,200 | $1,260 |
| No | 211661674 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TM8Y080C16MP11 | 24,600 | $1,230 |
| No | 211661669 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TM8Y100C16MP11 | 24,600 | $1,230 |
| No | 211661664 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TM8Y100C20MP11 | 24,800 | $1,240 |
| No | 211661659 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TM8Y120C20MP11 | 24,800 | $1,240 |
| No | 211661654 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TM8Y100C20MP11 | 24,400 | $1,220 |
| No | 211661649 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TM8Y120C20MP11 | 24,400 | $1,220 |
| No | 211661644 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+TXV | TM9E040A10MP12 | 24,200 | $1,210 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661639 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+TXV | TM9E040A10MP12 | 24,200 | $1,210 |
| No | 211661634 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+TXV | TM9E060A10MP12 | 24,400 | $1,220 |
| No | 211661629 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+TXV | TM9E060A10MP12 | 24,400 | $1,220 |
| No | 211661624 | JOHNSON CONTROLS | HMH72B361 | XAHB30CXXN1+TXV | TM9E060A10MP12 | 24,000 | $1,200 |
| No | 211661619 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 211661614 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 211661609 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 211661604 | JOHNSON CONTROLS | HMH72B361 | XAHB30CXXN1+TXV | TM9E060B12MP12 | 24,200 | $1,210 |
| No | 211661599 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 211661594 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 211661589 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 211661584 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 211661579 | JOHNSON CONTROLS | HMH72B361 | XAHB30CXXN1+TXV | TM9E080B12MP12 | 24,400 | $1,220 |
| No | 211661574 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TM9E080B12MP12 | 24,400 | $1,220 |
| No | 211661569 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TM9E080C16MP12 | 25,200 | $1,260 |
| No | 211661564 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TM9E080C16MP12 | 24,800 | $1,240 |
| No | 211661559 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TM9E100C16MP12 | 24,400 | $1,220 |
| No | 211661554 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TM9E100C16MP12 | 23,800 | $1,190 |
| No | 211661549 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+TXV | TM9V040A10MP12 | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661544 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+TXV | TM9V040A10MP12 | 24,400 | $1,220 |
| No | 211661532 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+TXV | TP9C060B12MP13 | 24,600 | $1,230 |
| No | 211661527 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+TXV | TM9V060B12MP12 | 24,600 | $1,230 |
| No | 211661520 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+TXV | TP9C060B12MP13 | 24,600 | $1,230 |
| No | 211661515 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+TXV | TM9V060B12MP12 | 24,600 | $1,230 |
| No | 211661508 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TP9C060B12MP13 | 24,600 | $1,230 |
| No | 211661499 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TM9V060B12MP12 | 24,600 | $1,230 |
| No | 211661492 | JOHNSON CONTROLS | HMH72B361 | XAHB30CXXN1+TXV | TP9C060B12MP13 | 24,000 | $1,200 |
| No | 211661487 | JOHNSON CONTROLS | HMH72B361 | XAHB30CXXN1+TXV | TM9V060B12MP12 | 24,000 | $1,200 |
| No | 211661480 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TP9C060B12MP13 | 24,200 | $1,210 |
| No | 211661475 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TM9V060B12MP12 | 24,200 | $1,210 |
| No | 211661468 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+TXV | TP9C080B12MP13 | 24,800 | $1,240 |
| No | 211661463 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+TXV | TM9V080B12MP12 | 24,800 | $1,240 |
| No | 211661456 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+TXV | TP9C080B12MP13 | 24,800 | $1,240 |
| No | 211661451 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+TXV | TM9V080B12MP12 | 24,800 | $1,240 |
| No | 211661444 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 211661439 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 211661432 | JOHNSON CONTROLS | HMH72B361 | XAHB30CXXN1+TXV | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 211661427 | JOHNSON CONTROLS | HMH72B361 | XAHB30CXXN1+TXV | TM9V080B12MP12 | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661420 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 211661415 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 211661408 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TP9C080C16MP13 | 25,200 | $1,260 |
| No | 211661403 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TM9V080C16MP12 | 25,200 | $1,260 |
| No | 211661396 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TP9C080C16MP13 | 24,800 | $1,240 |
| No | 211661391 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TM9V080C16MP12 | 24,800 | $1,240 |
| No | 211661384 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211661379 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TM9V100C16MP12 | 24,800 | $1,240 |
| No | 211661372 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TP9C100C16MP13 | 24,600 | $1,230 |
| No | 211661367 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TM9V100C16MP12 | 24,600 | $1,230 |
| No | 211661360 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TP9C100C20MP13 | 25,000 | $1,250 |
| No | 211661355 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TM9V100C20MP12 | 25,000 | $1,250 |
| No | 211661348 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TP9C100C20MP13 | 24,600 | $1,230 |
| No | 211661343 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TM9V100C20MP12 | 24,600 | $1,230 |
| No | 211661338 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+TXV | TM9Y060B12MP11 | 24,800 | $1,240 |
| No | 211661333 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+TXV | TM9Y060B12MP11 | 24,800 | $1,240 |
| No | 211661328 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TM9Y060B12MP11 | 24,800 | $1,240 |
| No | 211661323 | JOHNSON CONTROLS | HMH72B361 | XAHB30CXXN1+TXV | TM9Y060B12MP11 | 24,200 | $1,210 |
| No | 211661318 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TM9Y060B12MP11 | 24,200 | $1,210 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661313 | JOHNSON CONTROLS | HMH72B361 | XAUB30CXXN1+TXV | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211661308 | JOHNSON CONTROLS | HMH72B361 | XAFB30CXXN1+TXV | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211661303 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211661298 | JOHNSON CONTROLS | HMH72B361 | XAHB30CXXN1+TXV | TM9Y080B12MP11 | 24,400 | $1,220 |
| No | 211661293 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TM9Y080B12MP11 | 24,400 | $1,220 |
| No | 211661288 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TM9Y080C16MP11 | 24,800 | $1,240 |
| No | 211661283 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TM9Y080C16MP11 | 24,400 | $1,220 |
| No | 211661278 | JOHNSON CONTROLS | HMH72B361 | XAFC30CXXN1+TXV | TM9Y100C16MP11 | 24,800 | $1,240 |
| No | 211661273 | JOHNSON CONTROLS | HMH72B361 | XAHC30CXXN1+TXV | TM9Y100C16MP11 | 24,400 | $1,220 |
| No | 211661268 | JOHNSON CONTROLS | HMH72B241 | XAHB30CBAN1 | TM9E040A10MP12 | 15,000 | $750 |
| No | 211661263 | JOHNSON CONTROLS | HMH72B241 | XAHB30CXXN1+TXV | TM9E040A10MP12 | 15,000 | $750 |
| No | 211661258 | JOHNSON CONTROLS | HMH72B241 | XAUB30CXXN1+TXV | TM9E060A10MP12 | 15,000 | $750 |
| No | 211661253 | JOHNSON CONTROLS | HMH72B241 | XAFB30CBAN1 | TM9E060A10MP12 | 15,000 | $750 |
| No | 211661248 | JOHNSON CONTROLS | HMH72B241 | XAFB30CXXN1+TXV | TM9E060A10MP12 | 15,000 | $750 |
| No | 211661243 | JOHNSON CONTROLS | HMH72B241 | XAHB30CBAN1 | TM9E060A10MP12 | 14,900 | $745 |
| No | 211661238 | JOHNSON CONTROLS | HMH72B241 | XAHB30CXXN1+TXV | TM9E060A10MP12 | 14,900 | $745 |
| No | 211661233 | JOHNSON CONTROLS | HMH72B241 | XAUB30CXXN1+TXV | TM9E060B12MP12 | 15,400 | $770 |
| No | 211661228 | JOHNSON CONTROLS | HMH72B241 | XAFB30CBAN1 | TM9E060B12MP12 | 15,400 | $770 |
| No | 211661223 | JOHNSON CONTROLS | HMH72B241 | XAFB30CXXN1+TXV | TM9E060B12MP12 | 15,400 | $770 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661218 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TM9E060B12MP12 | 15,400 | $770 |
| No | 211661213 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TM9E060B12MP12 | 15,400 | $770 |
| No | 211661208 | JOHNSON CONTROLS | HMH72B241 | XAHB30CBAN1 | TM9E060B12MP12 | 15,100 | $755 |
| No | 211661203 | JOHNSON CONTROLS | HMH72B241 | XAHB30CXXN1+TXV | TM9E060B12MP12 | 15,100 | $755 |
| No | 211661198 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TM9E060B12MP12 | 15,100 | $755 |
| No | 211661193 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TM9E060B12MP12 | 15,100 | $755 |
| No | 211661183 | JOHNSON CONTROLS | HMH72B241 | XAUB30CXXN1+TXV | TM9E080B12MP12 | 15,700 | $785 |
| No | 211661172 | JOHNSON CONTROLS | HMH72B241 | XAFB30CBAN1 | TM9E080B12MP12 | 15,700 | $785 |
| No | 211661163 | JOHNSON CONTROLS | HMH72B241 | XAFB30CXXN1+TXV | TM9E080B12MP12 | 15,700 | $785 |
| No | 211661158 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TM9E080B12MP12 | 15,700 | $785 |
| No | 211661153 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TM9E080B12MP12 | 15,700 | $785 |
| No | 211661148 | JOHNSON CONTROLS | HMH72B241 | XAHB30CBAN1 | TM9E080B12MP12 | 14,900 | $745 |
| No | 211661143 | JOHNSON CONTROLS | HMH72B241 | XAHB30CXXN1+TXV | TM9E080B12MP12 | 14,900 | $745 |
| No | 211661138 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TM9E080B12MP12 | 14,900 | $745 |
| No | 211661133 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TM9E080B12MP12 | 14,900 | $745 |
| No | 211661128 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TM9E080C16MP12 | 14,900 | $745 |
| No | 211661123 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TM9E080C16MP12 | 14,900 | $745 |
| No | 211661118 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TM9E080C16MP12 | 14,600 | $730 |
| No | 211661113 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TM9E080C16MP12 | 14,600 | $730 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661108 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TM9E100C16MP12 | 15,000 | $750 |
| No | 211661103 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TM9E100C16MP12 | 15,000 | $750 |
| No | 211661098 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TM9E100C16MP12 | 14,700 | $735 |
| No | 211661093 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TM9E100C16MP12 | 14,700 | $735 |
| No | 211661088 | JOHNSON CONTROLS | HMH72B241 | XAUB30CXXN1+TXV | TM9V040A10MP12 | 15,400 | $770 |
| No | 211661083 | JOHNSON CONTROLS | HMH72B241 | XAFB30CBAN1 | TM9V040A10MP12 | 15,400 | $770 |
| No | 211661078 | JOHNSON CONTROLS | HMH72B241 | XAFB30CXXN1+TXV | TM9V040A10MP12 | 15,400 | $770 |
| No | 211661073 | JOHNSON CONTROLS | HMH72B241 | XAHB30CBAN1 | TM9V040A10MP12 | 15,100 | $755 |
| No | 211661068 | JOHNSON CONTROLS | HMH72B241 | XAHB30CXXN1+TXV | TM9V040A10MP12 | 15,100 | $755 |
| No | 211661059 | JOHNSON CONTROLS | HMH72B241 | XAUB30CXXN1+TXV | TP9C060B12MP13 | 15,100 | $755 |
| No | 211661054 | JOHNSON CONTROLS | HMH72B241 | XAFB30CBAN1 | TP9C060B12MP13 | 15,100 | $755 |
| No | 211661049 | JOHNSON CONTROLS | HMH72B241 | XAUB30CXXN1+TXV | TM9V060B12MP12 | 15,100 | $755 |
| No | 211661044 | JOHNSON CONTROLS | HMH72B241 | XAFB30CBAN1 | TM9V060B12MP12 | 15,100 | $755 |
| No | 211661037 | JOHNSON CONTROLS | HMH72B241 | XAFB30CXXN1+TXV | TP9C060B12MP13 | 15,100 | $755 |
| No | 211661032 | JOHNSON CONTROLS | HMH72B241 | XAFB30CXXN1+TXV | TM9V060B12MP12 | 15,100 | $755 |
| No | 211661025 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TP9C060B12MP13 | 15,100 | $755 |
| No | 211661020 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TM9V060B12MP12 | 15,100 | $755 |
| No | 211661013 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TP9C060B12MP13 | 15,100 | $755 |
| No | 211661008 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TM9V060B12MP12 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661001 | JOHNSON CONTROLS | HMH72B241 | XAHB30CBAN1 | TP9C060B12MP13 | 15,100 | $755 |
| No | 211660996 | JOHNSON CONTROLS | HMH72B241 | XAHB30CBAN1 | TM9V060B12MP12 | 15,100 | $755 |
| No | 211660989 | JOHNSON CONTROLS | HMH72B241 | XAHB30CXXN1+TXV | TP9C060B12MP13 | 15,100 | $755 |
| No | 211660984 | JOHNSON CONTROLS | HMH72B241 | XAHB30CXXN1+TXV | TM9V060B12MP12 | 15,100 | $755 |
| No | 211660977 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TP9C060B12MP13 | 15,000 | $750 |
| No | 211660972 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TM9V060B12MP12 | 15,000 | $750 |
| No | 211660965 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TP9C060B12MP13 | 15,000 | $750 |
| No | 211660960 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TM9V060B12MP12 | 15,000 | $750 |
| No | 211660951 | JOHNSON CONTROLS | HMH72B241 | XAUB30CXXN1+TXV | TP9C080B12MP13 | 15,300 | $765 |
| No | 211660946 | JOHNSON CONTROLS | HMH72B241 | XAFB30CBAN1 | TP9C080B12MP13 | 15,300 | $765 |
| No | 211660941 | JOHNSON CONTROLS | HMH72B241 | XAUB30CXXN1+TXV | TM9V080B12MP12 | 15,300 | $765 |
| No | 211660936 | JOHNSON CONTROLS | HMH72B241 | XAFB30CBAN1 | TM9V080B12MP12 | 15,300 | $765 |
| No | 211660929 | JOHNSON CONTROLS | HMH72B241 | XAFB30CXXN1+TXV | TP9C080B12MP13 | 15,300 | $765 |
| No | 211660924 | JOHNSON CONTROLS | HMH72B241 | XAFB30CXXN1+TXV | TM9V080B12MP12 | 15,300 | $765 |
| No | 211660917 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TP9C080B12MP13 | 15,300 | $765 |
| No | 211660912 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TM9V080B12MP12 | 15,300 | $765 |
| No | 211660905 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TP9C080B12MP13 | 15,300 | $765 |
| No | 211660900 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TM9V080B12MP12 | 15,300 | $765 |
| No | 211660893 | JOHNSON CONTROLS | HMH72B241 | XAHB30CBAN1 | TP9C080B12MP13 | 14,800 | $740 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660888 | JOHNSON CONTROLS | HMH72B241 | XAHB30CBAN1 | TM9V080B12MP12 | 14,800 | $740 |
| No | 211660881 | JOHNSON CONTROLS | HMH72B241 | XAHB30CXXN1+TXV | TP9C080B12MP13 | 14,800 | $740 |
| No | 211660876 | JOHNSON CONTROLS | HMH72B241 | XAHB30CXXN1+TXV | TM9V080B12MP12 | 14,800 | $740 |
| No | 211660869 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TP9C080B12MP13 | 15,000 | $750 |
| No | 211660864 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TM9V080B12MP12 | 15,000 | $750 |
| No | 211660857 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 211660852 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 211660822 | JOHNSON CONTROLS | HMH72B241 | XAUB30CXXN1+TXV | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211660817 | JOHNSON CONTROLS | HMH72B241 | XAFB30CBAN1 | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211660812 | JOHNSON CONTROLS | HMH72B241 | XAFB30CXXN1+TXV | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211660807 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211660802 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211660797 | JOHNSON CONTROLS | HMH72B241 | XAHB30CBAN1 | TM9Y060B12MP11 | 15,100 | $755 |
| No | 211660792 | JOHNSON CONTROLS | HMH72B241 | XAHB30CXXN1+TXV | TM9Y060B12MP11 | 15,100 | $755 |
| No | 211660787 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TM9Y060B12MP11 | 14,800 | $740 |
| No | 211660782 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TM9Y060B12MP11 | 14,800 | $740 |
| No | 211660777 | JOHNSON CONTROLS | HMH72B241 | XAUB30CXXN1+TXV | TM9Y080B12MP11 | 15,100 | $755 |
| No | 211660772 | JOHNSON CONTROLS | HMH72B241 | XAFB30CBAN1 | TM9Y080B12MP11 | 15,100 | $755 |
| No | 211660767 | JOHNSON CONTROLS | HMH72B241 | XAFB30CXXN1+TXV | TM9Y080B12MP11 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660762 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TM9Y080B12MP11 | 15,100 | $755 |
| No | 211660757 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TM9Y080B12MP11 | 15,100 | $755 |
| No | 211660752 | JOHNSON CONTROLS | HMH72B241 | XAHB30CBAN1 | TM9Y080B12MP11 | 14,900 | $745 |
| No | 211660747 | JOHNSON CONTROLS | HMH72B241 | XAHB30CXXN1+TXV | TM9Y080B12MP11 | 14,900 | $745 |
| No | 211660742 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TM9Y080B12MP11 | 14,900 | $745 |
| No | 211660737 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TM9Y080B12MP11 | 14,900 | $745 |
| No | 211660732 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TM9Y080C16MP11 | 15,200 | $760 |
| No | 211660727 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TM9Y080C16MP11 | 15,200 | $760 |
| No | 211660722 | JOHNSON CONTROLS | HMH72B241 | JHETB24CBAS2N1 | | 15,000 | $750 |
| No | 211660717 | JOHNSON CONTROLS | HMH72B241 | JHVTB24CBAC2N1 | | 15,000 | $750 |
| No | 211660712 | JOHNSON CONTROLS | HMH72B241 | XAUB30CXXN1+JMET12BS2N1+TXV | | 15,100 | $755 |
| No | 211660707 | JOHNSON CONTROLS | HMH72B241 | XAFB30CBAN1+JMET12BS2N1 | | 15,100 | $755 |
| No | 211660702 | JOHNSON CONTROLS | HMH72B241 | XAFB30CXXN1+JMET12BS2N1+TXV | | 15,100 | $755 |
| No | 211660697 | JOHNSON CONTROLS | HMH72B241 | XAHB30CBAN1+JMET12BS2N1 | | 14,800 | $740 |
| No | 211660692 | JOHNSON CONTROLS | HMH72B241 | XAHB30CXXN1+JMET12BS2N1+TXV | | 14,800 | $740 |
| No | 211660687 | JOHNSON CONTROLS | HMH72B241 | XAUB30CXXN1+JMVT12BC2N1+TXV | | 14,900 | $745 |
| No | 211660682 | JOHNSON CONTROLS | HMH72B241 | XAFB30CBAN1+JMVT12BC2N1 | | 14,900 | $745 |
| No | 211660677 | JOHNSON CONTROLS | HMH72B241 | XAFB30CXXN1+JMVT12BC2N1+TXV | | 14,900 | $745 |
| No | 211660672 | JOHNSON CONTROLS | HMH72B241 | XAHB30CBAN1+JMVT12BC2N1 | | 14,900 | $745 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660667 | JOHNSON CONTROLS | HMH72B241 | XAHB30CXXN1+JMVT12BC2N1+TXV | | 14,900 | $745 |
| No | 211660662 | JOHNSON CONTROLS | HMH72B241 | XAUB30CXXN1+TXV | TL8E060A12UH11 | 15,000 | $750 |
| No | 211660657 | JOHNSON CONTROLS | HMH72B241 | XAFB30CBAN1 | TL8E060A12UH11 | 15,000 | $750 |
| No | 211660652 | JOHNSON CONTROLS | HMH72B241 | XAFB30CXXN1+TXV | TL8E060A12UH11 | 15,000 | $750 |
| No | 211660647 | JOHNSON CONTROLS | HMH72B241 | XAHB30CBAN1 | TL8E060A12UH11 | 14,700 | $735 |
| No | 211660642 | JOHNSON CONTROLS | HMH72B241 | XAHB30CXXN1+TXV | TL8E060A12UH11 | 14,700 | $735 |
| No | 211660637 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TL8E080C16UH11 | 15,600 | $780 |
| No | 211660632 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TL8E080C16UH11 | 15,600 | $780 |
| No | 211660627 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TM9Y080C16MP11 | 14,900 | $745 |
| No | 211660622 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TM9Y080C16MP11 | 14,900 | $745 |
| No | 211660617 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TM9Y100C16MP11 | 15,200 | $760 |
| No | 211660612 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TM9Y100C16MP11 | 15,200 | $760 |
| No | 211660607 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TM9Y100C16MP11 | 14,800 | $740 |
| No | 211660602 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TM9Y100C16MP11 | 14,800 | $740 |
| No | 211660597 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TL8E080C16UH11 | 15,300 | $765 |
| No | 211660592 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TL8E080C16UH11 | 15,300 | $765 |
| No | 211660587 | JOHNSON CONTROLS | HMH72B241 | XAUB30CXXN1+TXV | TL9E060B12UH11 | 15,100 | $755 |
| No | 211660582 | JOHNSON CONTROLS | HMH72B241 | XAFB30CBAN1 | TL9E060B12UH11 | 15,100 | $755 |
| No | 211660577 | JOHNSON CONTROLS | HMH72B241 | XAFB30CXXN1+TXV | TL9E060B12UH11 | 15,100 | $755 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660572 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TL9E060B12UH11 | 15,100 | $755 |
| No | 211660567 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TL9E060B12UH11 | 15,100 | $755 |
| No | 211660562 | JOHNSON CONTROLS | HMH72B241 | XAHB30CBAN1 | TL9E060B12UH11 | 14,800 | $740 |
| No | 211660557 | JOHNSON CONTROLS | HMH72B241 | XAHB30CXXN1+TXV | TL9E060B12UH11 | 14,800 | $740 |
| No | 211660552 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TL9E060B12UH11 | 14,800 | $740 |
| No | 211660547 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TL9E060B12UH11 | 14,800 | $740 |
| No | 211660542 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TL9E080C16UH11 | 15,700 | $785 |
| No | 211660537 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TL9E080C16UH11 | 15,700 | $785 |
| No | 211660532 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TL9E080C16UH11 | 15,300 | $765 |
| No | 211660527 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TL9E080C16UH11 | 15,300 | $765 |
| No | 211660522 | JOHNSON CONTROLS | HMH72B241 | XAUB30CXXN1+TXV | TMLE040A12MP11 | 15,000 | $750 |
| No | 211660517 | JOHNSON CONTROLS | HMH72B241 | XAFB30CBAN1 | TMLE040A12MP11 | 15,000 | $750 |
| No | 211660512 | JOHNSON CONTROLS | HMH72B241 | XAUB30CXXN1+TXV | TM8E040A12MP11 | 15,000 | $750 |
| No | 211660507 | JOHNSON CONTROLS | HMH72B241 | XAFB30CBAN1 | TM8E040A12MP11 | 15,000 | $750 |
| No | 211660502 | JOHNSON CONTROLS | HMH72B241 | XAFB30CXXN1+TXV | TMLE040A12MP11 | 15,000 | $750 |
| No | 211660497 | JOHNSON CONTROLS | HMH72B241 | XAFB30CXXN1+TXV | TM8E040A12MP11 | 15,000 | $750 |
| No | 211660492 | JOHNSON CONTROLS | HMH72B241 | XAHB30CBAN1 | TMLE040A12MP11 | 14,700 | $735 |
| No | 211660487 | JOHNSON CONTROLS | HMH72B241 | XAHB30CBAN1 | TM8E040A12MP11 | 14,700 | $735 |
| No | 211660482 | JOHNSON CONTROLS | HMH72B241 | XAHB30CXXN1+TXV | TMLE040A12MP11 | 14,700 | $735 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660477 | JOHNSON CONTROLS | HMH72B241 | XAHB30CXXN1+TXV | TM8E040A12MP11 | 14,700 | $735 |
| No | 211660472 | JOHNSON CONTROLS | HMH72B241 | XAUB30CXXN1+TXV | TMLE060A12MP11 | 15,000 | $750 |
| No | 211660467 | JOHNSON CONTROLS | HMH72B241 | XAFB30CBAN1 | TMLE060A12MP11 | 15,000 | $750 |
| No | 211660462 | JOHNSON CONTROLS | HMH72B241 | XAUB30CXXN1+TXV | TM8E060A12MP11 | 15,000 | $750 |
| No | 211660457 | JOHNSON CONTROLS | HMH72B241 | XAFB30CBAN1 | TM8E060A12MP11 | 15,000 | $750 |
| No | 211660452 | JOHNSON CONTROLS | HMH72B241 | XAFB30CXXN1+TXV | TMLE060A12MP11 | 15,000 | $750 |
| No | 211660447 | JOHNSON CONTROLS | HMH72B241 | XAFB30CXXN1+TXV | TM8E060A12MP11 | 15,000 | $750 |
| No | 211660442 | JOHNSON CONTROLS | HMH72B241 | XAHB30CBAN1 | TMLE060A12MP11 | 14,700 | $735 |
| No | 211660437 | JOHNSON CONTROLS | HMH72B241 | XAHB30CBAN1 | TM8E060A12MP11 | 14,700 | $735 |
| No | 211660432 | JOHNSON CONTROLS | HMH72B241 | XAHB30CXXN1+TXV | TMLE060A12MP11 | 14,700 | $735 |
| No | 211660427 | JOHNSON CONTROLS | HMH72B241 | XAHB30CXXN1+TXV | TM8E060A12MP11 | 14,700 | $735 |
| No | 211660422 | JOHNSON CONTROLS | HMH72B241 | XAUB30CXXN1+TXV | TMLE080B12MP11 | 15,100 | $755 |
| No | 211660417 | JOHNSON CONTROLS | HMH72B241 | XAFB30CBAN1 | TMLE080B12MP11 | 15,100 | $755 |
| No | 211660412 | JOHNSON CONTROLS | HMH72B241 | XAUB30CXXN1+TXV | TM8E080B12MP11 | 15,100 | $755 |
| No | 211660407 | JOHNSON CONTROLS | HMH72B241 | XAFB30CBAN1 | TM8E080B12MP11 | 15,100 | $755 |
| No | 211660402 | JOHNSON CONTROLS | HMH72B241 | XAFB30CXXN1+TXV | TMLE080B12MP11 | 15,100 | $755 |
| No | 211660397 | JOHNSON CONTROLS | HMH72B241 | XAFB30CXXN1+TXV | TM8E080B12MP11 | 15,100 | $755 |
| No | 211660392 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TMLE080B12MP11 | 15,100 | $755 |
| No | 211660387 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TM8E080B12MP11 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660382 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TMLE080B12MP11 | 15,100 | $755 |
| No | 211660377 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TM8E080B12MP11 | 15,100 | $755 |
| No | 211660372 | JOHNSON CONTROLS | HMH72B241 | XAHB30CBAN1 | TMLE080B12MP11 | 14,800 | $740 |
| No | 211660367 | JOHNSON CONTROLS | HMH72B241 | XAHB30CBAN1 | TM8E080B12MP11 | 14,800 | $740 |
| No | 211660362 | JOHNSON CONTROLS | HMH72B241 | XAHB30CXXN1+TXV | TMLE080B12MP11 | 14,800 | $740 |
| No | 211660357 | JOHNSON CONTROLS | HMH72B241 | XAHB30CXXN1+TXV | TM8E080B12MP11 | 14,800 | $740 |
| No | 211660352 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TMLE080B12MP11 | 14,800 | $740 |
| No | 211660347 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TM8E080B12MP11 | 14,800 | $740 |
| No | 211660342 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TMLE080B12MP11 | 14,800 | $740 |
| No | 211660337 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TM8E080B12MP11 | 14,800 | $740 |
| No | 211660332 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TMLE080C16MP11 | 15,500 | $775 |
| No | 211660327 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TM8E080C16MP11 | 15,500 | $775 |
| No | 211660322 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TMLE080C16MP11 | 15,500 | $775 |
| No | 211660317 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TM8E080C16MP11 | 15,500 | $775 |
| No | 211660312 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TMLE080C16MP11 | 14,700 | $735 |
| No | 211660307 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TM8E080C16MP11 | 14,700 | $735 |
| No | 211660302 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TMLE080C16MP11 | 14,700 | $735 |
| No | 211660297 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TM8E080C16MP11 | 14,700 | $735 |
| No | 211660292 | JOHNSON CONTROLS | HMH72B241 | XAUB30CXXN1+TXV | TMLE100B12MP11 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660287 | JOHNSON CONTROLS | HMH72B241 | XAFB30CBAN1 | TMLE100B12MP11 | 15,100 | $755 |
| No | 211660282 | JOHNSON CONTROLS | HMH72B241 | XAUB30CXXN1+TXV | TM8E100B12MP11 | 15,100 | $755 |
| No | 211660277 | JOHNSON CONTROLS | HMH72B241 | XAFB30CBAN1 | TM8E100B12MP11 | 15,100 | $755 |
| No | 211660272 | JOHNSON CONTROLS | HMH72B241 | XAFB30CXXN1+TXV | TMLE100B12MP11 | 15,100 | $755 |
| No | 211660267 | JOHNSON CONTROLS | HMH72B241 | XAFB30CXXN1+TXV | TM8E100B12MP11 | 15,100 | $755 |
| No | 211660262 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TMLE100B12MP11 | 14,800 | $740 |
| No | 211660257 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660252 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TMLE100B12MP11 | 14,800 | $740 |
| No | 211660247 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660242 | JOHNSON CONTROLS | HMH72B241 | XAHB30CBAN1 | TMLE100B12MP11 | 14,800 | $740 |
| No | 211660237 | JOHNSON CONTROLS | HMH72B241 | XAHB30CBAN1 | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660232 | JOHNSON CONTROLS | HMH72B241 | XAHB30CXXN1+TXV | TMLE100B12MP11 | 14,800 | $740 |
| No | 211660227 | JOHNSON CONTROLS | HMH72B241 | XAHB30CXXN1+TXV | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660222 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TMLE100B12MP11 | 14,800 | $740 |
| No | 211660217 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660212 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TMLE100B12MP11 | 14,800 | $740 |
| No | 211660207 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660202 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TMLE100C16MP11 | 15,000 | $750 |
| No | 211660197 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TM8E100C16MP11 | 15,000 | $750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660192 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TMLE100C16MP11 | 15,000 | $750 |
| No | 211660187 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TM8E100C16MP11 | 15,000 | $750 |
| No | 211660182 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TMLE100C16MP11 | 14,700 | $735 |
| No | 211660177 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TM8E100C16MP11 | 14,700 | $735 |
| No | 211660172 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TMLE100C16MP11 | 14,700 | $735 |
| No | 211660167 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TM8E100C16MP11 | 14,700 | $735 |
| No | 211660162 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TMLE120C16MP11 | 15,000 | $750 |
| No | 211660157 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TM8E120C16MP11 | 15,000 | $750 |
| No | 211660152 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TMLE120C16MP11 | 15,000 | $750 |
| No | 211660147 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TM8E120C16MP11 | 15,000 | $750 |
| No | 211660142 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TMLE120C16MP11 | 15,300 | $765 |
| No | 211660137 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TM8E120C16MP11 | 15,300 | $765 |
| No | 211660132 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TMLE120C16MP11 | 15,300 | $765 |
| No | 211660127 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TM8E120C16MP11 | 15,300 | $765 |
| No | 211660120 | JOHNSON CONTROLS | HMH72B241 | XAUB30CXXN1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 211660115 | JOHNSON CONTROLS | HMH72B241 | XAFB30CBAN1 | TPLC080B12MP13 | 15,100 | $755 |
| No | 211660110 | JOHNSON CONTROLS | HMH72B241 | XAUB30CXXN1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 211660105 | JOHNSON CONTROLS | HMH72B241 | XAFB30CBAN1 | TM8V080B12MP12 | 15,100 | $755 |
| No | 211660099 | JOHNSON CONTROLS | HMH72B241 | XAFB30CXXN1+TXV | TPLC080B12MP13 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660094 | JOHNSON CONTROLS | HMH72B241 | XAFB30CXXN1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 211660088 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TPLC080B12MP13 | 15,100 | $755 |
| No | 211660083 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TM8V080B12MP12 | 15,100 | $755 |
| No | 211660077 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 211660072 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 211660066 | JOHNSON CONTROLS | HMH72B241 | XAHB30CBAN1 | TPLC080B12MP13 | 14,900 | $745 |
| No | 211660061 | JOHNSON CONTROLS | HMH72B241 | XAHB30CBAN1 | TM8V080B12MP12 | 14,900 | $745 |
| No | 211660055 | JOHNSON CONTROLS | HMH72B241 | XAHB30CXXN1+TXV | TPLC080B12MP13 | 14,900 | $745 |
| No | 211660050 | JOHNSON CONTROLS | HMH72B241 | XAHB30CXXN1+TXV | TM8V080B12MP12 | 14,900 | $745 |
| No | 211660044 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TPLC080B12MP13 | 14,800 | $740 |
| No | 211660039 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TM8V080B12MP12 | 14,800 | $740 |
| No | 211660033 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TPLC080B12MP13 | 14,800 | $740 |
| No | 211660028 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TM8V080B12MP12 | 14,800 | $740 |
| No | 211660023 | JOHNSON CONTROLS | HMH72B241 | XAUB30CXXN1+TXV | TM8Y060A12MP11 | 15,300 | $765 |
| No | 211660018 | JOHNSON CONTROLS | HMH72B241 | XAFB30CBAN1 | TM8Y060A12MP11 | 15,300 | $765 |
| No | 211660013 | JOHNSON CONTROLS | HMH72B241 | XAFB30CXXN1+TXV | TM8Y060A12MP11 | 15,300 | $765 |
| No | 211660008 | JOHNSON CONTROLS | HMH72B241 | XAHB30CBAN1 | TM8Y060A12MP11 | 15,000 | $750 |
| No | 211660003 | JOHNSON CONTROLS | HMH72B241 | XAHB30CXXN1+TXV | TM8Y060A12MP11 | 15,000 | $750 |
| No | 211659998 | JOHNSON CONTROLS | HMH72B241 | XAUB30CXXN1+TXV | TM8Y080B12MP11 | 15,300 | $765 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211659993 | JOHNSON CONTROLS | HMH72B241 | XAFB30CBAN1 | TM8Y080B12MP11 | 15,300 | $765 |
| No | 211659988 | JOHNSON CONTROLS | HMH72B241 | XAFB30CXXN1+TXV | TM8Y080B12MP11 | 15,300 | $765 |
| No | 211659983 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TM8Y080B12MP11 | 15,300 | $765 |
| No | 211659978 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TM8Y080B12MP11 | 15,300 | $765 |
| No | 211659973 | JOHNSON CONTROLS | HMH72B241 | XAHB30CBAN1 | TM8Y080B12MP11 | 15,000 | $750 |
| No | 211659968 | JOHNSON CONTROLS | HMH72B241 | XAHB30CXXN1+TXV | TM8Y080B12MP11 | 15,000 | $750 |
| No | 211659963 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TM8Y080B12MP11 | 15,100 | $755 |
| No | 211659958 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TM8Y080B12MP11 | 15,100 | $755 |
| No | 211659948 | JOHNSON CONTROLS | HMH72B241 | XAFC30CBAN1 | TM8Y100C16MP11 | 15,100 | $755 |
| No | 211659938 | JOHNSON CONTROLS | HMH72B241 | XAFC30CXXN1+TXV | TM8Y100C16MP11 | 15,100 | $755 |
| No | 211659933 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TM8Y080C16MP11 | 14,800 | $740 |
| No | 211659928 | JOHNSON CONTROLS | HMH72B241 | XAHC30CBAN1 | TM8Y100C16MP11 | 14,800 | $740 |
| No | 211659923 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TM8Y080C16MP11 | 14,800 | $740 |
| No | 211659918 | JOHNSON CONTROLS | HMH72B241 | XAHC30CXXN1+TXV | TM8Y100C16MP11 | 14,800 | $740 |
| No | 211659913 | JOHNSON CONTROLS | HMH72B241 | XAUB30CXXN1+TXV | TM9E026A08MP12 | 15,400 | $770 |
| No | 211659908 | JOHNSON CONTROLS | HMH72B241 | XAFB30CBAN1 | TM9E026A08MP12 | 15,400 | $770 |
| No | 211659903 | JOHNSON CONTROLS | HMH72B241 | XAFB30CXXN1+TXV | TM9E026A08MP12 | 15,400 | $770 |
| No | 211659898 | JOHNSON CONTROLS | HMH72B241 | XAHB30CBAN1 | TM9E026A08MP12 | 15,100 | $755 |
| No | 211659893 | JOHNSON CONTROLS | HMH72B241 | XAHB30CXXN1+TXV | TM9E026A08MP12 | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210817753 | JOHNSON CONTROLS | HMH72B361 | XAFA30DXXN1+TXV | TM8Y060A12MP11 | 25,000 | $1,250 |
| No | 210817750 | JOHNSON CONTROLS | HMH72B361 | XAFA30DXXN1+TXV | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 210817745 | JOHNSON CONTROLS | HMH72B361 | XAFA30DXXN1+TXV | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 210815084 | JOHNSON CONTROLS | HMH72B361 | XAFA30DXXN1+TXV | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 210810617 | JOHNSON CONTROLS | HMH72B361 | XAFA30DXXN1+TXV | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 210808449 | JOHNSON CONTROLS | HMH72B361 | XAFA30DXXN1+TXV | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211398885 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211398871 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211398859 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211398844 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TMLE080C16MP11 | 24,800 | $1,240 |
| No | 211398829 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TM8E080C16MP11 | 24,800 | $1,240 |
| No | 211398814 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TMLE080C16MP11 | 24,800 | $1,240 |
| No | 211398799 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TM8E080C16MP11 | 24,800 | $1,240 |
| No | 211398792 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TMLE080C16MP11 | 24,800 | $1,240 |
| No | 211398779 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TM8E080C16MP11 | 24,800 | $1,240 |
| No | 211398766 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TMLE080C16MP11 | 24,800 | $1,240 |
| No | 211398751 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TM8E080C16MP11 | 24,800 | $1,240 |
| No | 211398737 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211398722 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TMLE100B12MP11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211398707 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211398692 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211398677 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211398662 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211398647 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 211398635 | JOHNSON CONTROLS | HMH72B341 | 0 | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 211398625 | JOHNSON CONTROLS | HMH72B341 | 0 | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 211398610 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 211398595 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211398580 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211398565 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211398550 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211398535 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211398520 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211398505 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211398491 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211398478 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211398472 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211398457 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TMLE100C16MP11 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211398442 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211398427 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211398412 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211398397 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211398383 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211398368 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211398356 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211398341 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TMLE120C16MP11 | 25,400 | $1,270 |
| No | 211398327 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TMLE120C16MP11 | 25,400 | $1,270 |
| No | 211398318 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TM8E120C16MP11 | 25,400 | $1,270 |
| No | 211398303 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TM8E120C16MP11 | 25,400 | $1,270 |
| No | 211398290 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TMLE120C16MP11 | 25,400 | $1,270 |
| No | 211398276 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TM8E120C16MP11 | 25,400 | $1,270 |
| No | 211398261 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TMLE120C16MP11 | 25,200 | $1,260 |
| No | 211398246 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TM8E120C16MP11 | 25,200 | $1,260 |
| No | 211398231 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TMLE120C16MP11 | 25,200 | $1,260 |
| No | 211398216 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TM8E120C16MP11 | 25,200 | $1,260 |
| No | 211398201 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211398185 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TM8E120C16MP11 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211398170 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211398158 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211398147 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211398132 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211398117 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211398102 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211398087 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TPLC080B12MP13 | 25,800 | $1,290 |
| No | 211398077 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TPLC080B12MP13 | 25,800 | $1,290 |
| No | 211398062 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TM8V080B12MP12 | 25,800 | $1,290 |
| No | 211398047 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TM8V080B12MP12 | 25,800 | $1,290 |
| No | 211398029 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TPLC080B12MP13 | 25,800 | $1,290 |
| No | 211398014 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TM8V080B12MP12 | 25,800 | $1,290 |
| No | 211397996 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TPLC080B12MP13 | 25,200 | $1,260 |
| No | 211397981 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TM8V080B12MP12 | 25,200 | $1,260 |
| No | 211397963 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TPLC080B12MP13 | 25,200 | $1,260 |
| No | 211397948 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TM8V080B12MP12 | 25,200 | $1,260 |
| No | 211397909 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397894 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397879 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TPLC080C16MP13 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211397868 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397853 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211397838 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211397801 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211397786 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211397759 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397744 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397729 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211397705 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211397678 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397663 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397648 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211397618 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211397591 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397576 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397561 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211397531 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211397504 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TPLC100C16MP13 | 25,400 | $1,270 |
| No | 211397489 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TPLC080C16MP13 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211397474 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TMLV100C16MP12 | 25,400 | $1,270 |
| No | 211397451 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TM8V100C16MP12 | 25,400 | $1,270 |
| No | 211397430 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TPLC100C16MP13 | 25,400 | $1,270 |
| No | 211397415 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TPLC080C16MP13 | 25,400 | $1,270 |
| No | 211397400 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TMLV100C16MP12 | 25,400 | $1,270 |
| No | 211397376 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TM8V100C16MP12 | 25,400 | $1,270 |
| No | 211397350 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TPLC100C16MP13 | 25,200 | $1,260 |
| No | 211397334 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TPLC080C16MP13 | 25,200 | $1,260 |
| No | 211397320 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TMLV100C16MP12 | 25,200 | $1,260 |
| No | 211397308 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TM8V080C16MP12 | 25,200 | $1,260 |
| No | 211397293 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TM8V100C16MP12 | 25,200 | $1,260 |
| No | 211397270 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TPLC100C16MP13 | 25,200 | $1,260 |
| No | 211397255 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TPLC080C16MP13 | 25,200 | $1,260 |
| No | 211397240 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TMLV100C16MP12 | 25,200 | $1,260 |
| No | 211397225 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TM8V080C16MP12 | 25,200 | $1,260 |
| No | 211397209 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TM8V100C16MP12 | 25,200 | $1,260 |
| No | 211397185 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TPLC120C20MP13 | 25,200 | $1,260 |
| No | 211397170 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TPLC100C20MP13 | 25,200 | $1,260 |
| No | 211397164 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TMLV120C20MP12 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211397149 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TM8V100C20MP12 | 25,200 | $1,260 |
| No | 211397134 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TM8V120C20MP12 | 25,200 | $1,260 |
| No | 211397113 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TPLC120C20MP13 | 25,200 | $1,260 |
| No | 211397098 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TPLC100C20MP13 | 25,200 | $1,260 |
| No | 211397083 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TMLV120C20MP12 | 25,200 | $1,260 |
| No | 211397068 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TM8V100C20MP12 | 25,200 | $1,260 |
| No | 211397053 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TM8V120C20MP12 | 25,200 | $1,260 |
| No | 211397038 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211397023 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211397008 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211396993 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211396981 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211396969 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TM8Y080C16MP11 | 25,800 | $1,290 |
| No | 211396954 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TM8Y080C16MP11 | 25,800 | $1,290 |
| No | 211396939 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211396924 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211396915 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TM8Y080C16MP11 | 25,800 | $1,290 |
| No | 211396900 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211396885 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TM8Y080C16MP11 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211396870 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211396855 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TM8Y080C16MP11 | 25,800 | $1,290 |
| No | 211396840 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211396825 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TM8Y080C16MP11 | 25,400 | $1,270 |
| No | 211396810 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211396800 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TM8Y080C16MP11 | 25,400 | $1,270 |
| No | 211396787 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211396772 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TM8Y080C16MP11 | 25,400 | $1,270 |
| No | 211396757 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211396742 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TM8Y080C16MP11 | 25,400 | $1,270 |
| No | 211396727 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211396713 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TM8Y100C20MP11 | 25,600 | $1,280 |
| No | 211396698 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TM8Y100C20MP11 | 25,600 | $1,280 |
| No | 211396684 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TM8Y120C20MP11 | 25,600 | $1,280 |
| No | 211396671 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TM8Y120C20MP11 | 25,600 | $1,280 |
| No | 211396656 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TM8Y100C20MP11 | 25,600 | $1,280 |
| No | 211396641 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TM8Y120C20MP11 | 25,600 | $1,280 |
| No | 211396626 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TM8Y100C20MP11 | 25,600 | $1,280 |
| No | 211396617 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TM8Y120C20MP11 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211396601 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TM8Y100C20MP11 | 25,600 | $1,280 |
| No | 211396589 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TM8Y120C20MP11 | 25,600 | $1,280 |
| No | 211396574 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TM8Y100C20MP11 | 25,200 | $1,260 |
| No | 211396559 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211396545 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TM8Y100C20MP11 | 25,200 | $1,260 |
| No | 211396528 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211396505 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TM8Y100C20MP11 | 25,200 | $1,260 |
| No | 211396483 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211396459 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TM8Y100C20MP11 | 25,200 | $1,260 |
| No | 211396435 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211396414 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211396389 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211396367 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211396346 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211396322 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211396299 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TM9E080B12MP12 | 25,600 | $1,280 |
| No | 211396279 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TM9E080B12MP12 | 25,600 | $1,280 |
| No | 211396257 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TM9E080B12MP12 | 25,600 | $1,280 |
| No | 211396234 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TM9E080B12MP12 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211396213 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211396194 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TM9E080C16MP12 | 26,000 | $1,300 |
| No | 211396173 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TM9E080C16MP12 | 26,000 | $1,300 |
| No | 211396157 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TM9E080C16MP12 | 26,000 | $1,300 |
| No | 211396137 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TM9E080C16MP12 | 26,000 | $1,300 |
| No | 211396123 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TM9E080C16MP12 | 26,000 | $1,300 |
| No | 211396109 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211396092 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211396077 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211396061 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211396047 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211396033 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211396021 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211396006 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211395990 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211395975 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211395963 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211395948 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211395935 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TM9E100C16MP12 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211395911 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211395900 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211395888 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211395872 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211395844 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211395820 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211395796 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TP9C060B12MP13 | 25,200 | $1,260 |
| No | 211395776 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TM9V060B12MP12 | 25,200 | $1,260 |
| No | 211395748 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TP9C060B12MP13 | 25,200 | $1,260 |
| No | 211395728 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TM9V060B12MP12 | 25,200 | $1,260 |
| No | 211395685 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TP9C080B12MP13 | 25,600 | $1,280 |
| No | 211395666 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TP9C080B12MP13 | 25,600 | $1,280 |
| No | 211395640 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TM9V080B12MP12 | 25,600 | $1,280 |
| No | 211395621 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TM9V080B12MP12 | 25,600 | $1,280 |
| No | 211395591 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TP9C080B12MP13 | 25,600 | $1,280 |
| No | 211395567 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TM9V080B12MP12 | 25,600 | $1,280 |
| No | 211395535 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TP9C080B12MP13 | 25,200 | $1,260 |
| No | 211395510 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TM9V080B12MP12 | 25,200 | $1,260 |
| No | 211395483 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TP9C080B12MP13 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211395465 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TM9V080B12MP12 | 25,200 | $1,260 |
| No | 211395419 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395400 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395376 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211395359 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211395331 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395306 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211395269 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395245 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211395215 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395190 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211395156 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TP9C080C16MP13 | 24,800 | $1,240 |
| No | 211395133 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TM9V080C16MP12 | 24,800 | $1,240 |
| No | 211395102 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TP9C080C16MP13 | 24,800 | $1,240 |
| No | 211395081 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TM9V080C16MP12 | 24,800 | $1,240 |
| No | 211395051 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TP9C080C16MP13 | 25,000 | $1,250 |
| No | 211395040 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TM9V080C16MP12 | 25,000 | $1,250 |
| No | 211395021 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TP9C080C16MP13 | 25,000 | $1,250 |
| No | 211395008 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TM9V080C16MP12 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211394982 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394967 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394952 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211394938 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211394920 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394906 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211394887 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394873 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211394853 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394839 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211394818 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211394803 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TM9V100C16MP12 | 24,800 | $1,240 |
| No | 211394782 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211394767 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TM9V100C16MP12 | 24,800 | $1,240 |
| No | 211394747 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211394732 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TM9V100C16MP12 | 24,800 | $1,240 |
| No | 211394715 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211394701 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TM9V100C16MP12 | 24,800 | $1,240 |
| No | 211394674 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TP9C100C20MP13 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211394659 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TP9C100C20MP13 | 25,800 | $1,290 |
| No | 211394647 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TM9V100C20MP12 | 25,800 | $1,290 |
| No | 211394632 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TM9V100C20MP12 | 25,800 | $1,290 |
| No | 211394615 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TP9C100C20MP13 | 25,800 | $1,290 |
| No | 211394600 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TM9V100C20MP12 | 25,800 | $1,290 |
| No | 211394579 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TP9C100C20MP13 | 25,600 | $1,280 |
| No | 211394564 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TM9V100C20MP12 | 25,600 | $1,280 |
| No | 211394545 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TP9C100C20MP13 | 25,600 | $1,280 |
| No | 211394532 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TM9V100C20MP12 | 25,600 | $1,280 |
| No | 211394514 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TP9C100C20MP13 | 25,000 | $1,250 |
| No | 211394501 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TM9V100C20MP12 | 25,000 | $1,250 |
| No | 211394483 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TP9C100C20MP13 | 25,000 | $1,250 |
| No | 211394469 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TM9V100C20MP12 | 25,000 | $1,250 |
| No | 211394449 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TP9C100C20MP13 | 25,200 | $1,260 |
| No | 211394434 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TM9V100C20MP12 | 25,200 | $1,260 |
| No | 211394414 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TP9C100C20MP13 | 25,200 | $1,260 |
| No | 211394401 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TM9V100C20MP12 | 25,200 | $1,260 |
| No | 211394382 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TP9C120D20MP13 | 25,400 | $1,270 |
| No | 211394367 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TM9V120D20MP12 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211394350 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TP9C120D20MP13 | 25,400 | $1,270 |
| No | 211394337 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TM9V120D20MP12 | 25,400 | $1,270 |
| No | 211394318 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TP9C120D20MP13 | 24,800 | $1,240 |
| No | 211394305 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TM9V120D20MP12 | 24,800 | $1,240 |
| No | 211394285 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TP9C120D20MP13 | 24,800 | $1,240 |
| No | 211394270 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TM9V120D20MP12 | 24,800 | $1,240 |
| No | 211394255 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TM9Y060B12MP11 | 25,800 | $1,290 |
| No | 211394240 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TM9Y060B12MP11 | 25,800 | $1,290 |
| No | 211394228 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TM9Y060B12MP11 | 25,800 | $1,290 |
| No | 211394213 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TM9Y060B12MP11 | 25,400 | $1,270 |
| No | 211394200 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TM9Y060B12MP11 | 25,400 | $1,270 |
| No | 211394185 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211394170 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211394159 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211394144 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TM9Y080B12MP11 | 25,400 | $1,270 |
| No | 211394129 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TM9Y080B12MP11 | 25,400 | $1,270 |
| No | 211394116 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TM9Y080C16MP11 | 25,800 | $1,290 |
| No | 211394101 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TM9Y080C16MP11 | 25,800 | $1,290 |
| No | 211394088 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TM9Y080C16MP11 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211394073 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TM9Y080C16MP11 | 25,400 | $1,270 |
| No | 211394058 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TM9Y080C16MP11 | 25,400 | $1,270 |
| No | 211394043 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TM9Y080C16MP11 | 25,200 | $1,260 |
| No | 211394028 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TM9Y080C16MP11 | 25,200 | $1,260 |
| No | 211394013 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TM9Y080C16MP11 | 25,000 | $1,250 |
| No | 211393998 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TM9Y080C16MP11 | 25,000 | $1,250 |
| No | 211393983 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TM9Y100C16MP11 | 25,800 | $1,290 |
| No | 211393968 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TM9Y100C16MP11 | 25,800 | $1,290 |
| No | 211393953 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TM9Y100C16MP11 | 25,800 | $1,290 |
| No | 211393938 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TM9Y100C16MP11 | 25,400 | $1,270 |
| No | 211393923 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TM9Y100C16MP11 | 25,400 | $1,270 |
| No | 211393908 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TM9Y100C16MP11 | 25,200 | $1,260 |
| No | 211393893 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TM9Y100C16MP11 | 25,200 | $1,260 |
| No | 211393878 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TM9Y100C16MP11 | 25,200 | $1,260 |
| No | 211393863 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TM9Y100C16MP11 | 25,200 | $1,260 |
| No | 211393848 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TM9Y120D20MP11 | 25,400 | $1,270 |
| No | 211393833 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TM9Y120D20MP11 | 25,400 | $1,270 |
| No | 211393818 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TM9Y120D20MP11 | 25,000 | $1,250 |
| No | 211393803 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TM9Y120D20MP11 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211393788 | JOHNSON CONTROLS | HMH72B341 | XAFA30DXXN1+TXV | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 211393773 | JOHNSON CONTROLS | HMH72B341 | XAFA30DXXN1+TXV | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 211393758 | JOHNSON CONTROLS | HMH72B341 | XAFA30DXXN1+TXV | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211393744 | JOHNSON CONTROLS | HMH72B341 | XAFA30DXXN1+TXV | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 211393729 | JOHNSON CONTROLS | HMH72B341 | XAFA30DXXN1+TXV | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 211393714 | JOHNSON CONTROLS | HMH72B341 | XAFA30DXXN1+TXV | TPLC060A12MP13 | 25,800 | $1,290 |
| No | 211393699 | JOHNSON CONTROLS | HMH72B341 | XAFA30DXXN1+TXV | TMLV060A12MP12 | 25,800 | $1,290 |
| No | 211393683 | JOHNSON CONTROLS | HMH72B341 | XAFA30DXXN1+TXV | TM8V060A12MP12 | 25,800 | $1,290 |
| No | 211393669 | JOHNSON CONTROLS | HMH72B341 | XAFA30DXXN1+TXV | TM8Y060A12MP11 | 25,200 | $1,260 |
| No | 211393641 | JOHNSON CONTROLS | HMH72B341 | JHETB36DBCS2N1 | | 25,400 | $1,270 |
| No | 211393626 | JOHNSON CONTROLS | HMH72B341 | JHVTB36DBCC2N1 | | 25,200 | $1,260 |
| No | 211393613 | JOHNSON CONTROLS | HMH72B341 | JHVTC36DBCC2N1 | | 25,400 | $1,270 |
| No | 211393599 | JOHNSON CONTROLS | HMH72B341 | XAUB30CXXN1+TXV | TL8E060A12UH11 | 26,200 | $1,310 |
| No | 211393586 | JOHNSON CONTROLS | HMH72B341 | XAFB30CXXN1+TXV | TL8E060A12UH11 | 26,200 | $1,310 |
| No | 211393571 | JOHNSON CONTROLS | HMH72B341 | XAUB36DXXN1+TXV | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 211393556 | JOHNSON CONTROLS | HMH72B341 | XAFB36DBCN1 | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 211393541 | JOHNSON CONTROLS | HMH72B341 | XAFB36DXXN1+TXV | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 211393527 | JOHNSON CONTROLS | HMH72B341 | XAHB30CXXN1+TXV | TL8E060A12UH11 | 25,800 | $1,290 |
| No | 211393512 | JOHNSON CONTROLS | HMH72B341 | XAHB36DBCN1 | TL8E060A12UH11 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211393496 | JOHNSON CONTROLS | HMH72B341 | XAHB36DXXN1+TXV | TL8E060A12UH11 | 25,000 | $1,250 |
| No | 211393482 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TL8E080C16UH11 | 26,600 | $1,330 |
| No | 211393467 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211393452 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211393437 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TL8E080C16UH11 | 26,000 | $1,300 |
| No | 211393423 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TL8E080C16UH11 | 25,800 | $1,290 |
| No | 211393408 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TL8E080C16UH11 | 25,800 | $1,290 |
| No | 211393393 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TL8E100C20UH11 | 26,400 | $1,320 |
| No | 211393378 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211393363 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211393349 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TL8E100C20UH11 | 25,800 | $1,290 |
| No | 211393331 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TL8E100C20UH11 | 25,600 | $1,280 |
| No | 211393316 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TL8E100C20UH11 | 25,600 | $1,280 |
| No | 211393301 | JOHNSON CONTROLS | HMH72B341 | XAUB30CXXN1+TXV | TL9E060B12UH11 | 26,400 | $1,320 |
| No | 211393287 | JOHNSON CONTROLS | HMH72B341 | XAFB30CXXN1+TXV | TL9E060B12UH11 | 26,400 | $1,320 |
| No | 211393272 | JOHNSON CONTROLS | HMH72B341 | XAUB36DXXN1+TXV | TL9E060B12UH11 | 25,000 | $1,250 |
| No | 211393257 | JOHNSON CONTROLS | HMH72B341 | XAFB36DBCN1 | TL9E060B12UH11 | 25,000 | $1,250 |
| No | 211393248 | JOHNSON CONTROLS | HMH72B341 | XAFB36DXXN1+TXV | TL9E060B12UH11 | 25,000 | $1,250 |
| No | 211393234 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TL9E060B12UH11 | 26,400 | $1,320 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211393219 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TL9E060B12UH11 | 25,600 | $1,280 |
| No | 211393204 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TL9E060B12UH11 | 25,600 | $1,280 |
| No | 211393189 | JOHNSON CONTROLS | HMH72B341 | XAHB30CXXN1+TXV | TL9E060B12UH11 | 25,200 | $1,260 |
| No | 211393176 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TL9E060B12UH11 | 26,000 | $1,300 |
| No | 211393163 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TL9E060B12UH11 | 24,400 | $1,220 |
| No | 211393148 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TL9E060B12UH11 | 24,400 | $1,220 |
| No | 211393133 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TL9E080C16UH11 | 26,200 | $1,310 |
| No | 211393118 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TL9E080C16UH11 | 25,800 | $1,290 |
| No | 211393103 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TL9E080C16UH11 | 25,800 | $1,290 |
| No | 211393088 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TL9E080C16UH11 | 26,400 | $1,320 |
| No | 211393075 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TL9E080C16UH11 | 25,400 | $1,270 |
| No | 211393069 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TL9E080C16UH11 | 25,400 | $1,270 |
| No | 211393054 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TL9E100C20UH11 | 26,400 | $1,320 |
| No | 211393040 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TL9E100C20UH11 | 26,200 | $1,310 |
| No | 211393024 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TL9E100C20UH11 | 26,200 | $1,310 |
| No | 211393009 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TL9E100C20UH11 | 26,000 | $1,300 |
| No | 211392994 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TL9E100C20UH11 | 25,600 | $1,280 |
| No | 211392979 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TL9E100C20UH11 | 25,600 | $1,280 |
| No | 211392964 | JOHNSON CONTROLS | HMH72B341 | XAUB30CXXN1+TXV | TMLE040A12MP11 | 26,200 | $1,310 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211392950 | JOHNSON CONTROLS | HMH72B341 | XAUB30CXXN1+TXV | TM8E040A12MP11 | 26,200 | $1,310 |
| No | 211392935 | JOHNSON CONTROLS | HMH72B341 | XAFB30CXXN1+TXV | TMLE040A12MP11 | 26,200 | $1,310 |
| No | 211392920 | JOHNSON CONTROLS | HMH72B341 | XAFB30CXXN1+TXV | TM8E040A12MP11 | 26,200 | $1,310 |
| No | 211392905 | JOHNSON CONTROLS | HMH72B341 | XAUB36DXXN1+TXV | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 211392891 | JOHNSON CONTROLS | HMH72B341 | XAFB36DBCN1 | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 211392883 | JOHNSON CONTROLS | HMH72B341 | XAUB36DXXN1+TXV | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211392869 | JOHNSON CONTROLS | HMH72B341 | XAFB36DBCN1 | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211392854 | JOHNSON CONTROLS | HMH72B341 | XAFB36DXXN1+TXV | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 211392839 | JOHNSON CONTROLS | HMH72B341 | XAFB36DXXN1+TXV | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211392824 | JOHNSON CONTROLS | HMH72B341 | XAHB30CXXN1+TXV | TMLE040A12MP11 | 25,600 | $1,280 |
| No | 211392809 | JOHNSON CONTROLS | HMH72B341 | XAHB30CXXN1+TXV | TM8E040A12MP11 | 25,600 | $1,280 |
| No | 211392794 | JOHNSON CONTROLS | HMH72B341 | XAHB36DBCN1 | TMLE040A12MP11 | 24,800 | $1,240 |
| No | 211392779 | JOHNSON CONTROLS | HMH72B341 | XAHB36DBCN1 | TM8E040A12MP11 | 24,800 | $1,240 |
| No | 211392764 | JOHNSON CONTROLS | HMH72B341 | XAHB36DXXN1+TXV | TMLE040A12MP11 | 24,800 | $1,240 |
| No | 211392749 | JOHNSON CONTROLS | HMH72B341 | XAHB36DXXN1+TXV | TM8E040A12MP11 | 24,800 | $1,240 |
| No | 211392734 | JOHNSON CONTROLS | HMH72B341 | XAUB30CXXN1+TXV | TMLE060A12MP11 | 26,200 | $1,310 |
| No | 211392719 | JOHNSON CONTROLS | HMH72B341 | XAUB30CXXN1+TXV | TM8E060A12MP11 | 26,200 | $1,310 |
| No | 211392704 | JOHNSON CONTROLS | HMH72B341 | XAFB30CXXN1+TXV | TMLE060A12MP11 | 26,200 | $1,310 |
| No | 211392696 | JOHNSON CONTROLS | HMH72B341 | XAFB30CXXN1+TXV | TM8E060A12MP11 | 26,200 | $1,310 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211392687 | JOHNSON CONTROLS | HMH72B341 | XAUB36DXXN1+TXV | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 211392672 | JOHNSON CONTROLS | HMH72B341 | XAFB36DBCN1 | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 211392657 | JOHNSON CONTROLS | HMH72B341 | XAUB36DXXN1+TXV | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 211392643 | JOHNSON CONTROLS | HMH72B341 | XAFB36DBCN1 | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 211392628 | JOHNSON CONTROLS | HMH72B341 | XAFB36DXXN1+TXV | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 211392613 | JOHNSON CONTROLS | HMH72B341 | XAFB36DXXN1+TXV | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 211392598 | JOHNSON CONTROLS | HMH72B341 | XAHB30CXXN1+TXV | TMLE060A12MP11 | 25,800 | $1,290 |
| No | 211392583 | JOHNSON CONTROLS | HMH72B341 | XAHB30CXXN1+TXV | TM8E060A12MP11 | 25,800 | $1,290 |
| No | 211392568 | JOHNSON CONTROLS | HMH72B341 | XAHB36DBCN1 | TMLE060A12MP11 | 25,000 | $1,250 |
| No | 211392555 | JOHNSON CONTROLS | HMH72B341 | XAHB36DBCN1 | TM8E060A12MP11 | 25,000 | $1,250 |
| No | 211392542 | JOHNSON CONTROLS | HMH72B341 | XAHB36DXXN1+TXV | TMLE060A12MP11 | 25,000 | $1,250 |
| No | 211392527 | JOHNSON CONTROLS | HMH72B341 | XAHB36DXXN1+TXV | TM8E060A12MP11 | 25,000 | $1,250 |
| No | 211392516 | JOHNSON CONTROLS | HMH72B341 | XAUB30CXXN1+TXV | TMLE080B12MP11 | 26,800 | $1,340 |
| No | 211392501 | JOHNSON CONTROLS | HMH72B341 | XAUB30CXXN1+TXV | TM8E080B12MP11 | 26,800 | $1,340 |
| No | 211392486 | JOHNSON CONTROLS | HMH72B341 | XAFB30CXXN1+TXV | TMLE080B12MP11 | 26,800 | $1,340 |
| No | 211392471 | JOHNSON CONTROLS | HMH72B341 | XAFB30CXXN1+TXV | TM8E080B12MP11 | 26,800 | $1,340 |
| No | 211392456 | JOHNSON CONTROLS | HMH72B341 | XAUB36DXXN1+TXV | TMLE080B12MP11 | 25,800 | $1,290 |
| No | 211392445 | JOHNSON CONTROLS | HMH72B341 | XAFB36DBCN1 | TMLE080B12MP11 | 25,800 | $1,290 |
| No | 211392430 | JOHNSON CONTROLS | HMH72B341 | XAUB36DXXN1+TXV | TM8E080B12MP11 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211392415 | JOHNSON CONTROLS | HMH72B341 | XAFB36DBCN1 | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211392405 | JOHNSON CONTROLS | HMH72B341 | XAFB36DXXN1+TXV | TMLE080B12MP11 | 25,800 | $1,290 |
| No | 211392391 | JOHNSON CONTROLS | HMH72B341 | XAFB36DXXN1+TXV | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211392376 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TMLE080B12MP11 | 26,800 | $1,340 |
| No | 211392361 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TM8E080B12MP11 | 26,800 | $1,340 |
| No | 211392346 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TMLE080B12MP11 | 25,800 | $1,290 |
| No | 211392331 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211392316 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TMLE080B12MP11 | 25,800 | $1,290 |
| No | 211392304 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211392289 | JOHNSON CONTROLS | HMH72B341 | XAHB30CXXN1+TXV | TMLE080B12MP11 | 26,200 | $1,310 |
| No | 211392277 | JOHNSON CONTROLS | HMH72B341 | XAHB30CXXN1+TXV | TM8E080B12MP11 | 26,200 | $1,310 |
| No | 211392271 | JOHNSON CONTROLS | HMH72B341 | XAHB36DBCN1 | TMLE080B12MP11 | 25,000 | $1,250 |
| No | 211392256 | JOHNSON CONTROLS | HMH72B341 | XAHB36DBCN1 | TM8E080B12MP11 | 25,000 | $1,250 |
| No | 211392241 | JOHNSON CONTROLS | HMH72B341 | XAHB36DXXN1+TXV | TMLE080B12MP11 | 25,000 | $1,250 |
| No | 211392226 | JOHNSON CONTROLS | HMH72B341 | XAHB36DXXN1+TXV | TM8E080B12MP11 | 25,000 | $1,250 |
| No | 211392211 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TMLE080B12MP11 | 26,400 | $1,320 |
| No | 211392197 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TM8E080B12MP11 | 26,400 | $1,320 |
| No | 211392190 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TMLE080B12MP11 | 25,000 | $1,250 |
| No | 211392174 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TM8E080B12MP11 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211392159 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TMLE080B12MP11 | 25,000 | $1,250 |
| No | 211392144 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TM8E080B12MP11 | 25,000 | $1,250 |
| No | 211392129 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TMLE080C16MP11 | 26,000 | $1,300 |
| No | 211392114 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TM8E080C16MP11 | 26,000 | $1,300 |
| No | 211392099 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211392084 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211392069 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211392059 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211392050 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TMLE080C16MP11 | 25,600 | $1,280 |
| No | 211392035 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TM8E080C16MP11 | 25,600 | $1,280 |
| No | 211392020 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TMLE080C16MP11 | 24,600 | $1,230 |
| No | 211392006 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TM8E080C16MP11 | 24,600 | $1,230 |
| No | 211391990 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TMLE080C16MP11 | 24,600 | $1,230 |
| No | 211391975 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TM8E080C16MP11 | 24,600 | $1,230 |
| No | 211391960 | JOHNSON CONTROLS | HMH72B341 | XAUB30CXXN1+TXV | TMLE100B12MP11 | 26,200 | $1,310 |
| No | 211391945 | JOHNSON CONTROLS | HMH72B341 | XAUB30CXXN1+TXV | TM8E100B12MP11 | 26,200 | $1,310 |
| No | 211391930 | JOHNSON CONTROLS | HMH72B341 | XAFB30CXXN1+TXV | TMLE100B12MP11 | 26,200 | $1,310 |
| No | 211391915 | JOHNSON CONTROLS | HMH72B341 | XAFB30CXXN1+TXV | TM8E100B12MP11 | 26,200 | $1,310 |
| No | 211391900 | JOHNSON CONTROLS | HMH72B341 | XAUB36DXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211391885 | JOHNSON CONTROLS | HMH72B341 | XAFB36DBCN1 | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211391870 | JOHNSON CONTROLS | HMH72B341 | XAUB36DXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211391855 | JOHNSON CONTROLS | HMH72B341 | XAFB36DBCN1 | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211391841 | JOHNSON CONTROLS | HMH72B341 | XAFB36DXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211391827 | JOHNSON CONTROLS | HMH72B341 | XAFB36DXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211391812 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TMLE100B12MP11 | 26,200 | $1,310 |
| No | 211391797 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TM8E100B12MP11 | 26,200 | $1,310 |
| No | 211391784 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211391771 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211391756 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211391743 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211391731 | JOHNSON CONTROLS | HMH72B341 | XAHB30CXXN1+TXV | TMLE100B12MP11 | 25,800 | $1,290 |
| No | 211391716 | JOHNSON CONTROLS | HMH72B341 | XAHB30CXXN1+TXV | TM8E100B12MP11 | 25,800 | $1,290 |
| No | 211391702 | JOHNSON CONTROLS | HMH72B341 | XAHB36DBCN1 | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 211391697 | JOHNSON CONTROLS | HMH72B341 | XAHB36DBCN1 | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 211391684 | JOHNSON CONTROLS | HMH72B341 | XAHB36DXXN1+TXV | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 211391669 | JOHNSON CONTROLS | HMH72B341 | XAHB36DXXN1+TXV | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 211391654 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TMLE100B12MP11 | 25,600 | $1,280 |
| No | 211391639 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TM8E100B12MP11 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211391628 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TMLE100B12MP11 | 24,800 | $1,240 |
| No | 211391617 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TM8E100B12MP11 | 24,800 | $1,240 |
| No | 211391602 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TMLE100B12MP11 | 24,800 | $1,240 |
| No | 211391587 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TM8E100B12MP11 | 24,800 | $1,240 |
| No | 211391572 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TMLE100C16MP11 | 26,000 | $1,300 |
| No | 211391557 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TM8E100C16MP11 | 26,000 | $1,300 |
| No | 211391542 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TMLE100C16MP11 | 25,200 | $1,260 |
| No | 211391527 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TM8E100C16MP11 | 25,200 | $1,260 |
| No | 211391512 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TMLE100C16MP11 | 25,200 | $1,260 |
| No | 211391497 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TM8E100C16MP11 | 25,200 | $1,260 |
| No | 211391482 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TMLE100C16MP11 | 25,600 | $1,280 |
| No | 211391467 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TM8E100C16MP11 | 25,600 | $1,280 |
| No | 211391452 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211391437 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211391422 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211391407 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211391392 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TMLE120C16MP11 | 26,200 | $1,310 |
| No | 211391377 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TM8E120C16MP11 | 26,200 | $1,310 |
| No | 211391362 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TMLE120C16MP11 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211391347 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TM8E120C16MP11 | 25,200 | $1,260 |
| No | 211391332 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TMLE120C16MP11 | 25,200 | $1,260 |
| No | 211391317 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TM8E120C16MP11 | 25,200 | $1,260 |
| No | 211391302 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TMLE120C16MP11 | 25,600 | $1,280 |
| No | 211391288 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TM8E120C16MP11 | 25,600 | $1,280 |
| No | 211391273 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211391258 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211391243 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211391229 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211391214 | JOHNSON CONTROLS | HMH72B341 | XAUB30CXXN1+TXV | TPLC060A12MP13 | 26,000 | $1,300 |
| No | 211391199 | JOHNSON CONTROLS | HMH72B341 | XAUB30CXXN1+TXV | TMLV060A12MP12 | 26,000 | $1,300 |
| No | 211391184 | JOHNSON CONTROLS | HMH72B341 | XAUB30CXXN1+TXV | TM8V060A12MP12 | 26,000 | $1,300 |
| No | 211391169 | JOHNSON CONTROLS | HMH72B341 | XAFB30CXXN1+TXV | TPLC060A12MP13 | 26,000 | $1,300 |
| No | 211391154 | JOHNSON CONTROLS | HMH72B341 | XAFB30CXXN1+TXV | TMLV060A12MP12 | 26,000 | $1,300 |
| No | 211391140 | JOHNSON CONTROLS | HMH72B341 | XAFB30CXXN1+TXV | TM8V060A12MP12 | 26,000 | $1,300 |
| No | 211391125 | JOHNSON CONTROLS | HMH72B341 | XAUB36DXXN1+TXV | TPLC060A12MP13 | 25,600 | $1,280 |
| No | 211391110 | JOHNSON CONTROLS | HMH72B341 | XAFB36DBCN1 | TPLC060A12MP13 | 25,600 | $1,280 |
| No | 211391095 | JOHNSON CONTROLS | HMH72B341 | XAUB36DXXN1+TXV | TMLV060A12MP12 | 25,600 | $1,280 |
| No | 211391080 | JOHNSON CONTROLS | HMH72B341 | XAFB36DBCN1 | TMLV060A12MP12 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211391065 | JOHNSON CONTROLS | HMH72B341 | XAUB36DXXN1+TXV | TM8V060A12MP12 | 25,600 | $1,280 |
| No | 211391050 | JOHNSON CONTROLS | HMH72B341 | XAFB36DBCN1 | TM8V060A12MP12 | 25,600 | $1,280 |
| No | 211391035 | JOHNSON CONTROLS | HMH72B341 | XAFB36DXXN1+TXV | TPLC060A12MP13 | 25,600 | $1,280 |
| No | 211391020 | JOHNSON CONTROLS | HMH72B341 | XAFB36DXXN1+TXV | TMLV060A12MP12 | 25,600 | $1,280 |
| No | 211391005 | JOHNSON CONTROLS | HMH72B341 | XAFB36DXXN1+TXV | TM8V060A12MP12 | 25,600 | $1,280 |
| No | 211390990 | JOHNSON CONTROLS | HMH72B341 | XAHB30CXXN1+TXV | TPLC060A12MP13 | 25,600 | $1,280 |
| No | 211390975 | JOHNSON CONTROLS | HMH72B341 | XAHB30CXXN1+TXV | TMLV060A12MP12 | 25,600 | $1,280 |
| No | 211390960 | JOHNSON CONTROLS | HMH72B341 | XAHB30CXXN1+TXV | TM8V060A12MP12 | 25,600 | $1,280 |
| No | 211390945 | JOHNSON CONTROLS | HMH72B341 | XAHB36DBCN1 | TPLC060A12MP13 | 25,200 | $1,260 |
| No | 211390931 | JOHNSON CONTROLS | HMH72B341 | XAHB36DBCN1 | TMLV060A12MP12 | 25,200 | $1,260 |
| No | 211390916 | JOHNSON CONTROLS | HMH72B341 | XAHB36DBCN1 | TM8V060A12MP12 | 25,200 | $1,260 |
| No | 211390901 | JOHNSON CONTROLS | HMH72B341 | XAHB36DXXN1+TXV | TPLC060A12MP13 | 25,200 | $1,260 |
| No | 211390886 | JOHNSON CONTROLS | HMH72B341 | XAHB36DXXN1+TXV | TMLV060A12MP12 | 25,200 | $1,260 |
| No | 211390872 | JOHNSON CONTROLS | HMH72B341 | XAHB36DXXN1+TXV | TM8V060A12MP12 | 25,200 | $1,260 |
| No | 211390854 | JOHNSON CONTROLS | HMH72B341 | XAUB30CXXN1+TXV | TPLC080B12MP13 | 26,400 | $1,320 |
| No | 211390839 | JOHNSON CONTROLS | HMH72B341 | XAUB30CXXN1+TXV | TM8V080B12MP12 | 26,400 | $1,320 |
| No | 211390821 | JOHNSON CONTROLS | HMH72B341 | XAFB30CXXN1+TXV | TPLC080B12MP13 | 26,400 | $1,320 |
| No | 211390806 | JOHNSON CONTROLS | HMH72B341 | XAFB30CXXN1+TXV | TM8V080B12MP12 | 26,400 | $1,320 |
| No | 211390786 | JOHNSON CONTROLS | HMH72B341 | XAUB36DXXN1+TXV | TPLC080B12MP13 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211390771 | JOHNSON CONTROLS | HMH72B341 | XAFB36DBCN1 | TPLC080B12MP13 | 25,400 | $1,270 |
| No | 211390756 | JOHNSON CONTROLS | HMH72B341 | XAUB36DXXN1+TXV | TM8V080B12MP12 | 25,400 | $1,270 |
| No | 211390741 | JOHNSON CONTROLS | HMH72B341 | XAFB36DBCN1 | TM8V080B12MP12 | 25,400 | $1,270 |
| No | 211390723 | JOHNSON CONTROLS | HMH72B341 | XAFB36DXXN1+TXV | TPLC080B12MP13 | 25,400 | $1,270 |
| No | 211390708 | JOHNSON CONTROLS | HMH72B341 | XAFB36DXXN1+TXV | TM8V080B12MP12 | 25,400 | $1,270 |
| No | 211390690 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TPLC080B12MP13 | 26,400 | $1,320 |
| No | 211390675 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TM8V080B12MP12 | 26,400 | $1,320 |
| No | 211390657 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TPLC080B12MP13 | 25,600 | $1,280 |
| No | 211390642 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TM8V080B12MP12 | 25,600 | $1,280 |
| No | 211390625 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TPLC080B12MP13 | 25,600 | $1,280 |
| No | 211390610 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TM8V080B12MP12 | 25,600 | $1,280 |
| No | 211390592 | JOHNSON CONTROLS | HMH72B341 | XAHB30CXXN1+TXV | TPLC080B12MP13 | 25,600 | $1,280 |
| No | 211390577 | JOHNSON CONTROLS | HMH72B341 | XAHB30CXXN1+TXV | TM8V080B12MP12 | 25,600 | $1,280 |
| No | 211390559 | JOHNSON CONTROLS | HMH72B341 | XAHB36DBCN1 | TPLC080B12MP13 | 25,000 | $1,250 |
| No | 211390544 | JOHNSON CONTROLS | HMH72B341 | XAHB36DBCN1 | TM8V080B12MP12 | 25,000 | $1,250 |
| No | 211390526 | JOHNSON CONTROLS | HMH72B341 | XAHB36DXXN1+TXV | TPLC080B12MP13 | 25,000 | $1,250 |
| No | 211390511 | JOHNSON CONTROLS | HMH72B341 | XAHB36DXXN1+TXV | TM8V080B12MP12 | 25,000 | $1,250 |
| No | 211390493 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TPLC080B12MP13 | 26,000 | $1,300 |
| No | 211390479 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TM8V080B12MP12 | 26,000 | $1,300 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211390461 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TPLC080B12MP13 | 24,800 | $1,240 |
| No | 211390446 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TM8V080B12MP12 | 24,800 | $1,240 |
| No | 211390428 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TPLC080B12MP13 | 24,800 | $1,240 |
| No | 211390413 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TM8V080B12MP12 | 24,800 | $1,240 |
| No | 211390387 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TPLC100C16MP13 | 26,400 | $1,320 |
| No | 211390372 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TPLC080C16MP13 | 26,400 | $1,320 |
| No | 211390357 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TMLV100C16MP12 | 26,400 | $1,320 |
| No | 211390342 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TM8V080C16MP12 | 26,400 | $1,320 |
| No | 211390329 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TM8V100C16MP12 | 26,400 | $1,320 |
| No | 211390304 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TPLC100C16MP13 | 25,400 | $1,270 |
| No | 211390290 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TPLC080C16MP13 | 25,400 | $1,270 |
| No | 211390277 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TMLV100C16MP12 | 25,400 | $1,270 |
| No | 211390263 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TM8V080C16MP12 | 25,400 | $1,270 |
| No | 211390248 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TM8V100C16MP12 | 25,400 | $1,270 |
| No | 211390222 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TPLC100C16MP13 | 25,400 | $1,270 |
| No | 211390207 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TPLC080C16MP13 | 25,400 | $1,270 |
| No | 211390194 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TMLV100C16MP12 | 25,400 | $1,270 |
| No | 211390180 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TM8V080C16MP12 | 25,400 | $1,270 |
| No | 211390166 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TM8V100C16MP12 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211390142 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TPLC100C16MP13 | 25,600 | $1,280 |
| No | 211390128 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TPLC080C16MP13 | 25,600 | $1,280 |
| No | 211390114 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TMLV100C16MP12 | 25,600 | $1,280 |
| No | 211390085 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TM8V100C16MP12 | 25,600 | $1,280 |
| No | 211390058 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TPLC100C16MP13 | 25,600 | $1,280 |
| No | 211390045 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TPLC080C16MP13 | 25,600 | $1,280 |
| No | 211390031 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TMLV100C16MP12 | 25,600 | $1,280 |
| No | 211390002 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TM8V100C16MP12 | 25,600 | $1,280 |
| No | 211389978 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TPLC100C16MP13 | 25,600 | $1,280 |
| No | 211389964 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TPLC080C16MP13 | 25,600 | $1,280 |
| No | 211389949 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TMLV100C16MP12 | 25,600 | $1,280 |
| No | 211389920 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TM8V100C16MP12 | 25,600 | $1,280 |
| No | 211389905 | JOHNSON CONTROLS | HMH72B341 | XAUB30CXXN1+TXV | TM8Y060A12MP11 | 25,800 | $1,290 |
| No | 211389890 | JOHNSON CONTROLS | HMH72B341 | XAFB30CXXN1+TXV | TM8Y060A12MP11 | 25,800 | $1,290 |
| No | 211389883 | JOHNSON CONTROLS | HMH72B341 | XAUB36DXXN1+TXV | TM8Y060A12MP11 | 25,200 | $1,260 |
| No | 211389870 | JOHNSON CONTROLS | HMH72B341 | XAFB36DBCN1 | TM8Y060A12MP11 | 25,200 | $1,260 |
| No | 211389856 | JOHNSON CONTROLS | HMH72B341 | XAFB36DXXN1+TXV | TM8Y060A12MP11 | 25,200 | $1,260 |
| No | 211389842 | JOHNSON CONTROLS | HMH72B341 | XAHB30CXXN1+TXV | TM8Y060A12MP11 | 25,400 | $1,270 |
| No | 211389827 | JOHNSON CONTROLS | HMH72B341 | XAHB36DBCN1 | TM8Y060A12MP11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211389813 | JOHNSON CONTROLS | HMH72B341 | XAHB36DXXN1+TXV | TM8Y060A12MP11 | 24,600 | $1,230 |
| No | 211389798 | JOHNSON CONTROLS | HMH72B341 | XAUB30CXXN1+TXV | TM8Y080B12MP11 | 26,000 | $1,300 |
| No | 211389783 | JOHNSON CONTROLS | HMH72B341 | XAFB30CXXN1+TXV | TM8Y080B12MP11 | 26,000 | $1,300 |
| No | 211389768 | JOHNSON CONTROLS | HMH72B341 | XAUB36DXXN1+TXV | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211389753 | JOHNSON CONTROLS | HMH72B341 | XAFB36DBCN1 | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211389738 | JOHNSON CONTROLS | HMH72B341 | XAFB36DXXN1+TXV | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211389726 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TM8Y080B12MP11 | 26,000 | $1,300 |
| No | 211389716 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211389702 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211389687 | JOHNSON CONTROLS | HMH72B341 | XAHB30CXXN1+TXV | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211389672 | JOHNSON CONTROLS | HMH72B341 | XAHB36DBCN1 | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211389657 | JOHNSON CONTROLS | HMH72B341 | XAHB36DXXN1+TXV | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211389642 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211389628 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211389613 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211389583 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TM8Y100C16MP11 | 26,400 | $1,320 |
| No | 211389564 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211389535 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211389520 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TM8Y080C16MP11 | 26,600 | $1,330 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211389506 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TM8Y100C16MP11 | 26,600 | $1,330 |
| No | 211389491 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TM8Y080C16MP11 | 25,600 | $1,280 |
| No | 211389476 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TM8Y100C16MP11 | 25,600 | $1,280 |
| No | 211389461 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TM8Y080C16MP11 | 25,600 | $1,280 |
| No | 211389447 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TM8Y100C16MP11 | 25,600 | $1,280 |
| No | 211389420 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TM8Y120C20MP11 | 27,000 | $1,350 |
| No | 211389397 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211389371 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211389357 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TM8Y100C20MP11 | 26,400 | $1,320 |
| No | 211389342 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TM8Y120C20MP11 | 26,400 | $1,320 |
| No | 211389327 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TM8Y100C20MP11 | 25,400 | $1,270 |
| No | 211389313 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TM8Y120C20MP11 | 25,400 | $1,270 |
| No | 211389298 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TM8Y100C20MP11 | 25,400 | $1,270 |
| No | 211389283 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TM8Y120C20MP11 | 25,400 | $1,270 |
| No | 211389268 | JOHNSON CONTROLS | HMH72B341 | XAUB30CXXN1+TXV | TM9E040A10MP12 | 25,800 | $1,290 |
| No | 211389254 | JOHNSON CONTROLS | HMH72B341 | XAFB30CXXN1+TXV | TM9E040A10MP12 | 25,800 | $1,290 |
| No | 211389244 | JOHNSON CONTROLS | HMH72B341 | XAUB30CXXN1+TXV | TM9E060A10MP12 | 26,200 | $1,310 |
| No | 211389232 | JOHNSON CONTROLS | HMH72B341 | XAFB30CXXN1+TXV | TM9E060A10MP12 | 26,200 | $1,310 |
| No | 211389217 | JOHNSON CONTROLS | HMH72B341 | XAUB36DXXN1+TXV | TM9E060A10MP12 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211389202 | JOHNSON CONTROLS | HMH72B341 | XAFB36DBCN1 | TM9E060A10MP12 | 25,400 | $1,270 |
| No | 211389187 | JOHNSON CONTROLS | HMH72B341 | XAFB36DXXN1+TXV | TM9E060A10MP12 | 25,400 | $1,270 |
| No | 211389175 | JOHNSON CONTROLS | HMH72B341 | XAHB30CXXN1+TXV | TM9E060A10MP12 | 25,800 | $1,290 |
| No | 211389168 | JOHNSON CONTROLS | HMH72B341 | XAHB36DBCN1 | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 211389154 | JOHNSON CONTROLS | HMH72B341 | XAHB36DXXN1+TXV | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 211389139 | JOHNSON CONTROLS | HMH72B341 | XAUB30CXXN1+TXV | TM9E060B12MP12 | 26,400 | $1,320 |
| No | 211389124 | JOHNSON CONTROLS | HMH72B341 | XAFB30CXXN1+TXV | TM9E060B12MP12 | 26,400 | $1,320 |
| No | 211389109 | JOHNSON CONTROLS | HMH72B341 | XAUB36DXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211389094 | JOHNSON CONTROLS | HMH72B341 | XAFB36DBCN1 | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211389079 | JOHNSON CONTROLS | HMH72B341 | XAFB36DXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211389065 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TM9E060B12MP12 | 26,400 | $1,320 |
| No | 211389050 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211389035 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211389020 | JOHNSON CONTROLS | HMH72B341 | XAHB30CXXN1+TXV | TM9E060B12MP12 | 26,000 | $1,300 |
| No | 211389005 | JOHNSON CONTROLS | HMH72B341 | XAHB36DBCN1 | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211388991 | JOHNSON CONTROLS | HMH72B341 | XAHB36DXXN1+TXV | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211388976 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TM9E060B12MP12 | 26,200 | $1,310 |
| No | 211388962 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211388950 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TM9E060B12MP12 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211388935 | JOHNSON CONTROLS | HMH72B341 | XAUB30CXXN1+TXV | TM9E080B12MP12 | 26,800 | $1,340 |
| No | 211388920 | JOHNSON CONTROLS | HMH72B341 | XAFB30CXXN1+TXV | TM9E080B12MP12 | 26,800 | $1,340 |
| No | 211388905 | JOHNSON CONTROLS | HMH72B341 | XAUB36DXXN1+TXV | TM9E080B12MP12 | 25,400 | $1,270 |
| No | 211388891 | JOHNSON CONTROLS | HMH72B341 | XAFB36DBCN1 | TM9E080B12MP12 | 25,400 | $1,270 |
| No | 211388883 | JOHNSON CONTROLS | HMH72B341 | XAFB36DXXN1+TXV | TM9E080B12MP12 | 25,400 | $1,270 |
| No | 211388868 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TM9E080B12MP12 | 26,400 | $1,320 |
| No | 211388853 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TM9E080B12MP12 | 25,800 | $1,290 |
| No | 211388838 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TM9E080B12MP12 | 25,800 | $1,290 |
| No | 211388823 | JOHNSON CONTROLS | HMH72B341 | XAHB30CXXN1+TXV | TM9E080B12MP12 | 25,800 | $1,290 |
| No | 211388808 | JOHNSON CONTROLS | HMH72B341 | XAHB36DBCN1 | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211388797 | JOHNSON CONTROLS | HMH72B341 | XAHB36DXXN1+TXV | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211388785 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TM9E080B12MP12 | 26,200 | $1,310 |
| No | 211388771 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211388756 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211388741 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TM9E080C16MP12 | 26,200 | $1,310 |
| No | 211388726 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TM9E080C16MP12 | 25,200 | $1,260 |
| No | 211388711 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TM9E080C16MP12 | 25,200 | $1,260 |
| No | 211388697 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TM9E080C16MP12 | 26,800 | $1,340 |
| No | 211388682 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TM9E080C16MP12 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211388667 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211388652 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TM9E100C16MP12 | 26,200 | $1,310 |
| No | 211388637 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TM9E100C16MP12 | 25,200 | $1,260 |
| No | 211388622 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TM9E100C16MP12 | 25,200 | $1,260 |
| No | 211388608 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TM9E100C16MP12 | 25,600 | $1,280 |
| No | 211388593 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211388578 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211388564 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TM9E100C20MP12 | 25,000 | $1,250 |
| No | 211388554 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TM9E100C20MP12 | 25,000 | $1,250 |
| No | 211388547 | JOHNSON CONTROLS | HMH72B341 | XAUB30CXXN1+TXV | TM9V040A10MP12 | 25,800 | $1,290 |
| No | 211388540 | JOHNSON CONTROLS | HMH72B341 | XAFB30CXXN1+TXV | TM9V040A10MP12 | 25,800 | $1,290 |
| No | 211388525 | JOHNSON CONTROLS | HMH72B341 | XAUB36DXXN1+TXV | TM9V040A10MP12 | 25,200 | $1,260 |
| No | 211388513 | JOHNSON CONTROLS | HMH72B341 | XAFB36DBCN1 | TM9V040A10MP12 | 25,200 | $1,260 |
| No | 211388508 | JOHNSON CONTROLS | HMH72B341 | XAFB36DXXN1+TXV | TM9V040A10MP12 | 25,200 | $1,260 |
| No | 211388493 | JOHNSON CONTROLS | HMH72B341 | XAHB30CXXN1+TXV | TM9V040A10MP12 | 25,200 | $1,260 |
| No | 211388478 | JOHNSON CONTROLS | HMH72B341 | XAHB36DBCN1 | TM9V040A10MP12 | 24,800 | $1,240 |
| No | 211388464 | JOHNSON CONTROLS | HMH72B341 | XAHB36DXXN1+TXV | TM9V040A10MP12 | 24,800 | $1,240 |
| No | 211388448 | JOHNSON CONTROLS | HMH72B341 | XAUB30CXXN1+TXV | TP9C060B12MP13 | 26,400 | $1,320 |
| No | 211388440 | JOHNSON CONTROLS | HMH72B341 | XAUB30CXXN1+TXV | TM9V060B12MP12 | 26,400 | $1,320 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211388421 | JOHNSON CONTROLS | HMH72B341 | XAFB30CXXN1+TXV | TP9C060B12MP13 | 26,400 | $1,320 |
| No | 211388407 | JOHNSON CONTROLS | HMH72B341 | XAFB30CXXN1+TXV | TM9V060B12MP12 | 26,400 | $1,320 |
| No | 211388381 | JOHNSON CONTROLS | HMH72B341 | XAUB36DXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388372 | JOHNSON CONTROLS | HMH72B341 | XAFB36DBCN1 | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388357 | JOHNSON CONTROLS | HMH72B341 | XAUB36DXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388341 | JOHNSON CONTROLS | HMH72B341 | XAFB36DBCN1 | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388325 | JOHNSON CONTROLS | HMH72B341 | XAFB36DXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388312 | JOHNSON CONTROLS | HMH72B341 | XAFB36DXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388292 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TP9C060B12MP13 | 26,400 | $1,320 |
| No | 211388277 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TM9V060B12MP12 | 26,400 | $1,320 |
| No | 211388258 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388243 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388228 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388223 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388206 | JOHNSON CONTROLS | HMH72B341 | XAHB30CXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388192 | JOHNSON CONTROLS | HMH72B341 | XAHB30CXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388177 | JOHNSON CONTROLS | HMH72B341 | XAHB36DBCN1 | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 211388163 | JOHNSON CONTROLS | HMH72B341 | XAHB36DBCN1 | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 211388143 | JOHNSON CONTROLS | HMH72B341 | XAHB36DXXN1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211388129 | JOHNSON CONTROLS | HMH72B341 | XAHB36DXXN1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 211388109 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TP9C060B12MP13 | 26,000 | $1,300 |
| No | 211388094 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TM9V060B12MP12 | 26,000 | $1,300 |
| No | 211388077 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TP9C060B12MP13 | 25,200 | $1,260 |
| No | 211388063 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TM9V060B12MP12 | 25,200 | $1,260 |
| No | 211388045 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TP9C060B12MP13 | 25,200 | $1,260 |
| No | 211388031 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TM9V060B12MP12 | 25,200 | $1,260 |
| No | 211388020 | JOHNSON CONTROLS | HMH72B341 | XAUB30CXXN1+TXV | TP9C080B12MP13 | 26,600 | $1,330 |
| No | 211388009 | JOHNSON CONTROLS | HMH72B341 | XAUB30CXXN1+TXV | TM9V080B12MP12 | 26,600 | $1,330 |
| No | 211387989 | JOHNSON CONTROLS | HMH72B341 | XAFB30CXXN1+TXV | TP9C080B12MP13 | 26,600 | $1,330 |
| No | 211387975 | JOHNSON CONTROLS | HMH72B341 | XAFB30CXXN1+TXV | TM9V080B12MP12 | 26,600 | $1,330 |
| No | 211387958 | JOHNSON CONTROLS | HMH72B341 | XAUB36DXXN1+TXV | TP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387945 | JOHNSON CONTROLS | HMH72B341 | XAFB36DBCN1 | TP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387930 | JOHNSON CONTROLS | HMH72B341 | XAUB36DXXN1+TXV | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211387918 | JOHNSON CONTROLS | HMH72B341 | XAFB36DBCN1 | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211387897 | JOHNSON CONTROLS | HMH72B341 | XAFB36DXXN1+TXV | TP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387883 | JOHNSON CONTROLS | HMH72B341 | XAFB36DXXN1+TXV | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211387862 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TP9C080B12MP13 | 26,600 | $1,330 |
| No | 211387849 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TM9V080B12MP12 | 26,600 | $1,330 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211387836 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387828 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211387816 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387807 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211387795 | JOHNSON CONTROLS | HMH72B341 | XAHB30CXXN1+TXV | TP9C080B12MP13 | 26,200 | $1,310 |
| No | 211387786 | JOHNSON CONTROLS | HMH72B341 | XAHB30CXXN1+TXV | TM9V080B12MP12 | 26,200 | $1,310 |
| No | 211387775 | JOHNSON CONTROLS | HMH72B341 | XAHB36DBCN1 | TP9C080B12MP13 | 25,200 | $1,260 |
| No | 211387766 | JOHNSON CONTROLS | HMH72B341 | XAHB36DBCN1 | TM9V080B12MP12 | 25,200 | $1,260 |
| No | 211387754 | JOHNSON CONTROLS | HMH72B341 | XAHB36DXXN1+TXV | TP9C080B12MP13 | 25,200 | $1,260 |
| No | 211387746 | JOHNSON CONTROLS | HMH72B341 | XAHB36DXXN1+TXV | TM9V080B12MP12 | 25,200 | $1,260 |
| No | 211387735 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TP9C080B12MP13 | 26,200 | $1,310 |
| No | 211387726 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TM9V080B12MP12 | 26,200 | $1,310 |
| No | 211387715 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 211387706 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 211387695 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 211387686 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 211387675 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TP9C080C16MP13 | 26,200 | $1,310 |
| No | 211387666 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TM9V080C16MP12 | 26,200 | $1,310 |
| No | 211387654 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TP9C080C16MP13 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211387647 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211387638 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211387629 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211387616 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TP9C080C16MP13 | 25,800 | $1,290 |
| No | 211387609 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TM9V080C16MP12 | 25,800 | $1,290 |
| No | 211387598 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TP9C080C16MP13 | 25,000 | $1,250 |
| No | 211387590 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TM9V080C16MP12 | 25,000 | $1,250 |
| No | 211387577 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TP9C080C16MP13 | 25,000 | $1,250 |
| No | 211387569 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TM9V080C16MP12 | 25,000 | $1,250 |
| No | 211387557 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TP9C100C16MP13 | 26,400 | $1,320 |
| No | 211387549 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TM9V100C16MP12 | 26,400 | $1,320 |
| No | 211387542 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211387534 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211387520 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211387506 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211387488 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TP9C100C16MP13 | 25,800 | $1,290 |
| No | 211387476 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TM9V100C16MP12 | 25,800 | $1,290 |
| No | 211387457 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TP9C100C16MP13 | 25,000 | $1,250 |
| No | 211387443 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TM9V100C16MP12 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211387426 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TP9C100C16MP13 | 25,000 | $1,250 |
| No | 211387411 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TM9V100C16MP12 | 25,000 | $1,250 |
| No | 211387393 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TP9C100C20MP13 | 27,000 | $1,350 |
| No | 211387377 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TM9V100C20MP12 | 27,000 | $1,350 |
| No | 211387358 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TP9C100C20MP13 | 26,000 | $1,300 |
| No | 211387343 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TM9V100C20MP12 | 26,000 | $1,300 |
| No | 211387321 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TP9C100C20MP13 | 26,000 | $1,300 |
| No | 211387307 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TM9V100C20MP12 | 26,000 | $1,300 |
| No | 211387288 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TP9C100C20MP13 | 26,600 | $1,330 |
| No | 211387273 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TM9V100C20MP12 | 26,600 | $1,330 |
| No | 211387260 | JOHNSON CONTROLS | HMH72B341 | XAUB30CXXN1+TXV | TM9Y060B12MP11 | 26,600 | $1,330 |
| No | 211387245 | JOHNSON CONTROLS | HMH72B341 | XAFB30CXXN1+TXV | TM9Y060B12MP11 | 26,600 | $1,330 |
| No | 211387231 | JOHNSON CONTROLS | HMH72B341 | XAUB36DXXN1+TXV | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211387217 | JOHNSON CONTROLS | HMH72B341 | XAFB36DBCN1 | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211387202 | JOHNSON CONTROLS | HMH72B341 | XAFB36DXXN1+TXV | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211387188 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TM9Y060B12MP11 | 26,600 | $1,330 |
| No | 211387175 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211387162 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211386468 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TL8E100C20UH11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211386455 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211386441 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211386427 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211386413 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211386402 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TL8E100C20UH11 | 24,800 | $1,240 |
| No | 211386389 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TL8E100C20UH11 | 24,800 | $1,240 |
| No | 211386377 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TL8E100C20UH11 | 24,800 | $1,240 |
| No | 211386365 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TL8E100C20UH11 | 24,800 | $1,240 |
| No | 211386353 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TL9E060B12UH11 | 25,800 | $1,290 |
| No | 211386342 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TL9E060B12UH11 | 25,800 | $1,290 |
| No | 211386329 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TL9E060B12UH11 | 25,800 | $1,290 |
| No | 211386319 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TL9E060B12UH11 | 25,200 | $1,260 |
| No | 211386305 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TL9E060B12UH11 | 25,200 | $1,260 |
| No | 211386291 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TL9E080C16UH11 | 25,800 | $1,290 |
| No | 211386277 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TL9E080C16UH11 | 25,800 | $1,290 |
| No | 211386262 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TL9E080C16UH11 | 25,800 | $1,290 |
| No | 211386250 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TL9E080C16UH11 | 25,600 | $1,280 |
| No | 211386238 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TL9E080C16UH11 | 25,600 | $1,280 |
| No | 211386224 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TL9E080C16UH11 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211386211 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TL9E080C16UH11 | 25,200 | $1,260 |
| No | 211386203 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TL9E080C16UH11 | 25,200 | $1,260 |
| No | 211386194 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TL9E080C16UH11 | 25,200 | $1,260 |
| No | 211386176 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211386162 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211386148 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211386130 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211386116 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211386102 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TL9E100C20UH11 | 25,000 | $1,250 |
| No | 211386089 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TL9E100C20UH11 | 25,000 | $1,250 |
| No | 211386074 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TL9E100C20UH11 | 25,000 | $1,250 |
| No | 211386060 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TL9E100C20UH11 | 25,000 | $1,250 |
| No | 211386047 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TMLE080B12MP11 | 25,600 | $1,280 |
| No | 211386031 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TMLE080B12MP11 | 25,600 | $1,280 |
| No | 211386017 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TM8E080B12MP11 | 25,600 | $1,280 |
| No | 211386002 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TM8E080B12MP11 | 25,600 | $1,280 |
| No | 211385988 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TMLE080B12MP11 | 25,600 | $1,280 |
| No | 211385976 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TM8E080B12MP11 | 25,600 | $1,280 |
| No | 211385962 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TMLE080B12MP11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211385949 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TM8E080B12MP11 | 25,400 | $1,270 |
| No | 211385935 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TMLE080B12MP11 | 25,400 | $1,270 |
| No | 211385922 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TM8E080B12MP11 | 25,400 | $1,270 |
| No | 211385909 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211385893 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211385877 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211385861 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211385848 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211385835 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211385826 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211387146 | JOHNSON CONTROLS | HMH72B341 | XAHB30CXXN1+TXV | TM9Y060B12MP11 | 26,000 | $1,300 |
| No | 211387133 | JOHNSON CONTROLS | HMH72B341 | XAHB36DBCN1 | TM9Y060B12MP11 | 25,000 | $1,250 |
| No | 211387119 | JOHNSON CONTROLS | HMH72B341 | XAHB36DXXN1+TXV | TM9Y060B12MP11 | 25,000 | $1,250 |
| No | 211387105 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TM9Y060B12MP11 | 26,000 | $1,300 |
| No | 211387093 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TM9Y060B12MP11 | 25,200 | $1,260 |
| No | 211387081 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TM9Y060B12MP11 | 25,200 | $1,260 |
| No | 211387068 | JOHNSON CONTROLS | HMH72B341 | XAUB30CXXN1+TXV | TM9Y080B12MP11 | 26,800 | $1,340 |
| No | 211387055 | JOHNSON CONTROLS | HMH72B341 | XAFB30CXXN1+TXV | TM9Y080B12MP11 | 26,800 | $1,340 |
| No | 211387041 | JOHNSON CONTROLS | HMH72B341 | XAUB36DXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211387026 | JOHNSON CONTROLS | HMH72B341 | XAFB36DBCN1 | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211387012 | JOHNSON CONTROLS | HMH72B341 | XAFB36DXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211386999 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TM9Y080B12MP11 | 26,800 | $1,340 |
| No | 211386984 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211386969 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211386955 | JOHNSON CONTROLS | HMH72B341 | XAHB30CXXN1+TXV | TM9Y080B12MP11 | 26,200 | $1,310 |
| No | 211386942 | JOHNSON CONTROLS | HMH72B341 | XAHB36DBCN1 | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211386928 | JOHNSON CONTROLS | HMH72B341 | XAHB36DXXN1+TXV | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211386913 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TM9Y080B12MP11 | 26,200 | $1,310 |
| No | 211386899 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TM9Y080B12MP11 | 25,400 | $1,270 |
| No | 211386885 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TM9Y080B12MP11 | 25,400 | $1,270 |
| No | 211386873 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TM9Y080C16MP11 | 26,800 | $1,340 |
| No | 211386859 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TM9Y080C16MP11 | 25,800 | $1,290 |
| No | 211386845 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TM9Y080C16MP11 | 25,800 | $1,290 |
| No | 211386830 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TM9Y080C16MP11 | 26,200 | $1,310 |
| No | 211386816 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TM9Y080C16MP11 | 25,400 | $1,270 |
| No | 211386802 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TM9Y080C16MP11 | 25,400 | $1,270 |
| No | 211386785 | JOHNSON CONTROLS | HMH72B341 | XAFC30CXXN1+TXV | TM9Y100C16MP11 | 26,000 | $1,300 |
| No | 211386771 | JOHNSON CONTROLS | HMH72B341 | XAFC36DBCN1 | TM9Y100C16MP11 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211386757 | JOHNSON CONTROLS | HMH72B341 | XAFC36DXXN1+TXV | TM9Y100C16MP11 | 25,800 | $1,290 |
| No | 211386744 | JOHNSON CONTROLS | HMH72B341 | XAHC30CXXN1+TXV | TM9Y100C16MP11 | 25,600 | $1,280 |
| No | 211386730 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TM9Y100C16MP11 | 25,400 | $1,270 |
| No | 211386719 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TM9Y100C16MP11 | 25,400 | $1,270 |
| No | 211386705 | JOHNSON CONTROLS | HMH72B341 | XAHC36DBCN1 | TM9Y100C20MP11 | 25,600 | $1,280 |
| No | 211386691 | JOHNSON CONTROLS | HMH72B341 | XAHC36DXXN1+TXV | TM9Y100C20MP11 | 25,600 | $1,280 |
| No | 211386677 | JOHNSON CONTROLS | HMH72B341 | JHETC42FBCS2N1 | | 25,200 | $1,260 |
| No | 211386663 | JOHNSON CONTROLS | HMH72B341 | JHVTC42FBCC2N1 | | 25,000 | $1,250 |
| No | 211386650 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+JMET12CS2N1+TXV | | 25,400 | $1,270 |
| No | 211386638 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1+JMET12CS2N1 | | 25,400 | $1,270 |
| No | 211386625 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+JMET12CS2N1+TXV | | 25,400 | $1,270 |
| No | 211386613 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1+JMET12CS2N1 | | 24,800 | $1,240 |
| No | 211386598 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+JMET12CS2N1+TXV | | 24,800 | $1,240 |
| No | 211386584 | JOHNSON CONTROLS | HMH72B341 | XAUC48FXXN1+TXV | TL8E080C16UH11 | 26,000 | $1,300 |
| No | 211386574 | JOHNSON CONTROLS | HMH72B341 | XAFC48FBCN1 | TL8E080C16UH11 | 26,000 | $1,300 |
| No | 211386562 | JOHNSON CONTROLS | HMH72B341 | XAFC48FXXN1+TXV | TL8E080C16UH11 | 26,000 | $1,300 |
| No | 211386549 | JOHNSON CONTROLS | HMH72B341 | XAFD48FBCN1 | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211386537 | JOHNSON CONTROLS | HMH72B341 | XAFD48FXXN1+TXV | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211386525 | JOHNSON CONTROLS | HMH72B341 | XAHC48FBCN1 | TL8E080C16UH11 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211386510 | JOHNSON CONTROLS | HMH72B341 | XAHC48FXXN1+TXV | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211386495 | JOHNSON CONTROLS | HMH72B341 | XAHD48FBCN1 | TL8E080C16UH11 | 25,400 | $1,270 |
| No | 211386481 | JOHNSON CONTROLS | HMH72B341 | XAHD48FXXN1+TXV | TL8E080C16UH11 | 25,400 | $1,270 |
| No | 211911409 | Journey Comfort | CC230ODU36 | CC230HWU36 | | 24,000 | $1,200 |
| No | 211273247 | Journey Comfort | RGV18ODU60 | RGV18AHU60 | | 37,000 | $1,850 |
| No | 211273246 | Journey Comfort | RGV18ODU48 | RGV18AHU48 | | 37,000 | $1,850 |
| No | 211273245 | Journey Comfort | RGV18ODU36 | RGV18AHU36 | | 20,400 | $1,020 |
| No | 211273244 | Journey Comfort | RGV18ODU24 | RGV18AHU24 | | 21,000 | $1,050 |
| No | 211793574 | KADEN | KO-PSX12HP-2AAMA | KI-PSX12CW-2AAMA | | 7,700 | $385 |
| No | 211793572 | KADEN | KO-PSX09HP-2AAMA | KI-PSX09CW-2AAMA | | 8,000 | $400 |
| No | 211793576 | KADEN | KO-PSX18HP-2AAMA | KI-PSX18CW-2AAMA | | 12,200 | $610 |
| No | 211793569 | KADEN | KO-PS555HP-2AAMA | Heat pump without ducts | | 34,400 | $1,720 |
| No | 211793567 | KADEN | KO-PS548HP-2AAMA | Heat pump without ducts | | 34,000 | $1,700 |
| No | 211793575 | KADEN | KO-PSX18HP-2AAMA | KI-PSX18CT-2AAMA | | 12,000 | $600 |
| No | 211793558 | KADEN | KO-PSX18HP-2AAMA | KI-PSX18WM-2AAMA | | 14,900 | $745 |
| No | 211793577 | KADEN | KO-PSX24HP-2AAMA | KI-PSX24CT-2AAMA | | 19,000 | $950 |
| No | 211793564 | KADEN | KO-PS327HP-2AAMA | Heat pump with ducts | | 22,000 | $1,100 |
| No | 211793561 | KADEN | KO-PS218HP-2AAMA | Heat pump with ducts | | 14,800 | $740 |
| No | 211793565 | KADEN | KO-PS436HP-2AAMA | Heat pump without ducts | | 26,800 | $1,340 |
| No | 211793563 | KADEN | KO-PS327HP-2AAMA | Heat pump without ducts | | 21,000 | $1,050 |
| No | 211793560 | KADEN | KO-PS218HP-2AAMA | Heat pump without ducts | | 14,300 | $715 |
| No | 211793559 | KADEN | KO-PSX24HP-2AAMA | KI-PSX24WM-2AAMA | | 16,200 | $810 |
| No | 211793557 | KADEN | KO-PSX12HP-2AAMA | KI-PSX12WM-2AAMA | | 9,000 | $450 |
| No | 211793556 | KADEN | KO-PSX09HP-2AAMA | KI-PSX09WM-2AAMA | | 8,500 | $425 |
| No | 211793573 | KADEN | KO-PSX12HP-2AAMA | KI-PSX12CT-2AAMA | | 8,900 | $445 |
| No | 211793571 | KADEN | KO-PSX09HP-2AAMA | KI-PSX09CT-2AAMA | | 7,500 | $375 |
| No | 211793555 | KADEN | KO-PSX12HP-1AAMA | KI-PSX12WM-1AAMA | | 8,400 | $420 |
| No | 211793554 | KADEN | KO-PSX09HP-1AAMA | KI-PSX09WM-1AAMA | | 8,400 | $420 |
| No | 208836317 | Kanartic | KEOS-18UHE-NA | KEOS-18UHE-NA | | 11,100 | $555 |
| No | 208836319 | Kanartic | KEOS-12UHE-NA | KEOS-12UHE-NA | | 10,300 | $515 |
| No | 208836320 | Kanartic | KEOS-09UHE-NA | KEOS-09UHE-NA | | 9,300 | $465 |
| No | 212360155 | KANIONco | KWSMO-48R410AIHH | Combination heat pumps with or without ducts | | 36,000 | $1,800 |
| No | 212360149 | KANIONco | KWSMO-27R410AIHH | Combination heat pumps with or without ducts | | 21,000 | $1,050 |
| No | 212360150 | KANIONco | KWSMO-36R410AIHH | Heat pump without ducts | | 26,400 | $1,320 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 212360147 | KANIONco | KWSMO-27R410AIHH | Heat pump without ducts | | 20,000 | $1,000 |
| No | 212360148 | KANIONco | KWSMO-27R410AIHH | Heat pump with ducts | | 22,000 | $1,100 |
| No | 212360146 | KANIONco | KWSMO-18R410AIHH | Combination heat pumps with or without ducts | | 14,600 | $730 |
| No | 212360145 | KANIONco | KWSMO-18R410AIHH | Heat pump with ducts | | 14,800 | $740 |
| No | 212360153 | KANIONco | KWSMO-48R410AIHH | Heat pump without ducts | | 36,000 | $1,800 |
| No | 212360144 | KANIONco | KWSMO-18R410AIHH | Heat pump without ducts | | 14,400 | $720 |
| No | 212360141 | KANIONco | KWSM-24IR410AHS18.5MVODU | KWSM-24IR410AHS18.5MVIDU | | 16,500 | $825 |
| No | 212360140 | KANIONco | KWSM-18IR410AHS19.5MVODU | KWSM-18IR410AHS19.5MVIDU | | 11,400 | $570 |
| No | 212360139 | KANIONco | KWSM-12IR410AHS20.5MVODU | KWSM-12IR410AHS20.5MVIDU | | 7,000 | $350 |
| No | 212360138 | KANIONco | KWSM-09IR410AHS21.5MVODU | KWSM-09IR410AHS21.5MVIDU | | 6,000 | $300 |
| No | 212360137 | KANIONco | KWSM-12IR410AHS20MVLODU | KWSM-12IR410AHS20MVLIDU | | 7,800 | $390 |
| No | 212361755 | KANIONco | KWSM-09IR410AHS20MVLODU | KWSM-09IR410AHS20MVLIDU | | 6,300 | $315 |
| No | 207691855 | KANIONCO | KWSMO-36R410AIHMV | Heat pump without ducts | | 26,400 | $1,320 |
| No | 207691852 | KANIONCO | KWSMO-48R410AIHMV | Heat pump without ducts | | 36,000 | $1,800 |
| No | 207691849 | KANIONCO | KWSMO-30R410AIHMV | Heat pump without ducts | | 20,000 | $1,000 |
| No | 207691850 | KANIONCO | KWSMO-30R410AIHMV | Heat pump with ducts | | 22,000 | $1,100 |
| No | 207691848 | KANIONCO | KWSMO-18R410AIHMV | Heat pump with ducts | | 14,800 | $740 |
| No | 207805781 | KANIONCO | KWSMO-18R410AIHMV | Heat pump without ducts | | 14,400 | $720 |
| No | 207699082 | KANIONco | KWSM-24IR410AHS21MV | KWSM-24IR410AHS21MV | | 18,000 | $900 |
| No | 207645899 | KANIONco | KWSM-24IR410AHS23MV | KWSM-24IR410AHS22MV | | 18,000 | $900 |
| No | 207645875 | KANIONco | KWSM-12IR410AHS24MV | KWSM-12IR410AHS23MV | | 8,200 | $410 |
| No | 207699080 | KANIONco | KWSM-12IR410AHS22MV | KWSM-12IR410AHS22MV | | 8,200 | $410 |
| No | 207699079 | KANIONco | KWSM-09IR410AHS24MV | KWSM-09IR410AHS24MV | | 8,300 | $415 |
| No | 207645874 | KANIONco | KWSM-09IR410AHS26MV | KWSM-09IR410AHS25MV | | 8,300 | $415 |
| No | 207699077 | KANIONco | KWSM-09IR410AHS24MVL | KWSM-09IR410AHS24MVL | | 6,000 | $300 |
| No | 207699081 | KANIONco | KWSM-18IR410AHS23.5MV | KWSM-18IR410AHS23.5MV | | 14,000 | $700 |
| No | 207645876 | KANIONco | KWSM-18IR410AHS23.7MV | KWSM-18IR410AHS23.6MV | | 14,000 | $700 |
| No | 207645873 | KANIONco | KWSM-12IR410AHS21.7MVL | KWSM-12IR410AHS21.6MVL | | 8,400 | $420 |
| No | 207645872 | KANIONco | KWSM-09IR410AHS26MVL | KWSM-09IR410AHS25MVL | | 8,400 | $420 |
| No | 207699078 | KANIONco | KWSM-12IR410AHS21.5MVL | KWSM-12IR410AHS21.5MVL | | 8,400 | $420 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207645887 | KANIONco | KWSM-18IR410AHS21MV | KWSM-18IR410AHS20MV | | 11,500 | $575 |
| No | 207699093 | KANIONco | KWSM-18IR410AHS19MV | KWSM-18IR410AHS19MV | | 11,500 | $575 |
| No | 207645885 | KANIONco | KWSM-09IR410AHS21.7MV | KWSM-09IR410AHS21.6MV | | 6,900 | $345 |
| No | 207699091 | KANIONco | KWSM-09IR410AHS21.5MV | KWSM-09IR410AHS21.5MV | | 6,900 | $345 |
| No | 207645883 | KANIONco | KWSM-09IR410AHS20.7MVL | KWSM-09IR410AHS20.6MVL | | 6,800 | $340 |
| No | 207699089 | KANIONco | KWSM-09IR410AHS20.5MVL | KWSM-09IR410AHS20.5MVL | | 6,800 | $340 |
| No | 205645145 | KANIONCO | KWSMO-30R410AIH | Heat pump without ducts | | 17,200 | $860 |
| No | 205645146 | KANIONCO | KWSMO-36R410AIH | Heat pump without ducts | | 24,600 | $1,230 |
| No | 204760839 | KANIONCO | KWSM-09IR410AHS21 | KWSM-09IR410AHS21 | | 6,400 | $320 |
| No | 205645144 | KANIONCO | KWSMO-18R410AIH | Heat pump without ducts | | 12,000 | $600 |
| No | 205572568 | KANIONCO | KWSM-12IR410AHS25 | KWSM-12IR410AHS25 | | 7,800 | $390 |
| No | 205746736 | KANIONCO | KWSM-09IR410AHS25 | KWSM-09IR410AHS25 | | 6,900 | $345 |
| No | 204760849 | KANIONCO | KD-48R410AH | KD-48R410AH | | 33,400 | $1,670 |
| No | 204760848 | KANIONCO | KD-36R410AH | KD-36R410AH | | 27,600 | $1,380 |
| No | 204760846 | KANIONCO | KD-18R410AH | KD-18R410AH | | 12,000 | $600 |
| No | 204760844 | KANIONCO | KD-09R410AH | KD-09R410AH | | 5,800 | $290 |
| No | 204760835 | KANIONCO | KWSM-18IR410AHS19 | KWSM-18IR410AHS19 | | 11,000 | $550 |
| No | 204760838 | KANIONCO | KWSM-12IR410AHS21L | KWSM-12IR410AHS21L | | 7,100 | $355 |
| No | 204760847 | KANIONCO | KD-24R410AH | KD-24R410AH | | 16,000 | $800 |
| No | 204760841 | KANIONCO | KWSM-18IR410AHS21 | KWSM-18IR410AHS21 | | 10,400 | $520 |
| No | 204760831 | KANIONCO | KWSM-09IR410AHS19L | KWSM-09IR410AHS19L | | 6,000 | $300 |
| No | 207657366 | KARDA | 3KARDA36MZ4 | Heat pump without ducts | | 26,400 | $1,320 |
| No | 207657368 | KARDA | 3KARDA48MZ5 | Heat pump without ducts | | 36,000 | $1,800 |
| No | 207657363 | KARDA | 3KARDA27MZ3 | Heat pump without ducts | | 20,000 | $1,000 |
| No | 207657362 | KARDA | 3KARDA27MZ3 | Heat pump with ducts | | 22,000 | $1,100 |
| No | 207657360 | KARDA | 3KARDA18MZ2 | Heat pump with ducts | | 14,800 | $740 |
| No | 207657359 | KARDA | 3KARDA18MZ2 | Heat pump without ducts | | 14,400 | $720 |
| No | 210410112 | KARDA | 3KARDA12SZO | 3KARDA12CON-2 | | 10,200 | $510 |
| No | 207430430 | KARDA | 3KARDA18SZO | 3KARDA18UVW | | 11,100 | $555 |
| No | 207430432 | KARDA | 3KARDA12SZO | 3KARDA12UVW | | 10,300 | $515 |
| No | 207430429 | KARDA | 3KARDA09SZO | 3KARDA09UVW | | 9,300 | $465 |
| No | 207796641 | KARDA | 3KARDA18SZO | 3KARDA18UVC | | 15,600 | $780 |
| No | 207796640 | KARDA | 3KARDA12SZO | 3KARDA12CON | | 9,600 | $480 |
| No | 207796639 | KARDA | 3KARDA12SZO | 3KARDA12UVD | | 10,600 | $530 |
| No | 207796638 | KARDA | 3KARDA12SZO | 3KARDA12UVC | | 9,900 | $495 |
| No | 207796637 | KARDA | 3KARDA09SZO | 3KARDA09UVD | | 10,100 | $505 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202608468 | KARDA | 2PAMSH48-MZO5 | Heat pump without ducts | | 29,600 | $1,480 |
| No | 202608467 | KARDA | 2PAMSH27-MZO3 | Heat pump without ducts | | 17,200 | $860 |
| No | 202608469 | KARDA | 2PAMSH18-MZO2 | Heat pump without ducts | | 12,000 | $600 |
| No | 201830345 | KARDA | 1PAMSHH09-SZO-25 | 1PAMSHH09-SZW-25 | | 6,900 | $345 |
| No | 201830346 | KARDA | 1PAMSHH12-SZO-22.5 | 1PAMSHH12-SZW-22.5 | | 7,800 | $390 |
| No | 205823036 | KARDA | 2KARDA48MZ5 | Heat pump without ducts | | 29,600 | $1,480 |
| No | 205756426 | KARDA | 1KARDA09SZO25 | 1KARDA09UVW | | 6,900 | $345 |
| No | 205823033 | KARDA | 2KARDA18MZ2 | Heat pump without ducts | | 12,000 | $600 |
| No | 205756427 | KARDA | 1KARDA12SZO22.5 | 1KARDA12UVW | | 7,800 | $390 |
| No | 205724750 | KARDA | 2KARDA27MZ3 | Heat pump without ducts | | 17,200 | $860 |
| No | 207657369 | KARDA | 3KARDA48MZ5 | Heat pump with ducts | | 30,400 | $1,520 |
| No | 207614052 | KARDA | 3KARDA12SZO | 1KARDA12UVW | | 7,600 | $380 |
| No | 205823030 | KARDA | 2KARDA36MZ4 | Heat pump without ducts | | 24,600 | $1,230 |
| No | 205921403 | KARDA | 1PAMSHH12-SZO-22.5 | 2KARDA12UVCS | | 8,700 | $435 |
| No | 206348120 | KARDA | 1KARDA09SZO25 | 2PAMSDH09 | | 7,200 | $360 |
| No | 205921404 | KARDA | 1PAMSHH12-SZO-22.5 | 2KARDA12UVD | | 8,500 | $425 |
| No | 207657364 | KARDA | 3KARDA27MZ3 | Combination heat pumps with or without ducts | | 16,100 | $805 |
| No | 207657370 | KARDA | 3KARDA48MZ5 | Combination heat pumps with or without ducts | | 30,600 | $1,530 |
| No | 207657361 | KARDA | 3KARDA18MZ2 | Combination heat pumps with or without ducts | | 11,800 | $590 |
| No | 207614053 | KARDA | 1KARDA09SZO25 | 1KARDA09UVW-2 | | 7,000 | $350 |
| No | 210819424 | KEEPRITE | DLCSRBH30AAK | DLFSABH30XBK | | 20,400 | $1,020 |
| No | 209852082 | KEEPRITE | DLCURAH60AAK | DLFUAAH60XAK | | 37,000 | $1,850 |
| No | 209852079 | KEEPRITE | DLCURAH48AAK | DLFUAAH48XAK | | 37,000 | $1,850 |
| No | 209852086 | KEEPRITE | DLCURAH36AAK | DLFUAAH36XAK | | 20,400 | $1,020 |
| No | 209852088 | KEEPRITE | DLCURAH30ABK | DLFUAAH30XAK | | 21,000 | $1,050 |
| No | 209852085 | KEEPRITE | DLCURAH30AAK | DLFUAAH30XAK | | 20,000 | $1,000 |
| No | 209852078 | KEEPRITE | DLCURAH24AAK | DLFUAAH24XAK | | 21,000 | $1,050 |
| No | 209852084 | KEEPRITE | DLCURAH18AAK | DLFUAAH18XAK | | 12,000 | $600 |
| No | 207643089 | KEEPRITE | DLCMRBH48EAK | Heat pump without ducts | | 31,000 | $1,550 |
| No | 201835691 | KEEPRITE | DLCMRAH27CAK | Heat pump without ducts | | 17,800 | $890 |
| No | 207826628 | KEEPRITE | DLCLRCH36AAK | DLFLABH36XAK | | 25,600 | $1,280 |
| No | 208104317 | KEEPRITE | DLCSRBH36ABK | DLFSABH36XBK | | 25,600 | $1,280 |
| No | 207826626 | KEEPRITE | DLCLRCH48AAK | DLFLABH48XAK | | 37,400 | $1,870 |
| No | 207826627 | KEEPRITE | DLCLRCH58AAK | DLFLABH60XAK | | 34,000 | $1,700 |
| No | 207826602 | KEEPRITE | DLCSRBH24AAK | DLFSABH24XBK | | 16,200 | $810 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208104318 | KEEPRITE | DLCSRBH30AAK11 | DLFSABH30XBK | | 19,200 | $960 |
| No | 206188310 | KEEPRITE | DLCLRBH36AAK | DLFLFAH36XAK | | 22,000 | $1,100 |
| No | 206188313 | KEEPRITE | DLCLRBH48AAK | DLFLFAH48XAK | | 29,000 | $1,450 |
| No | 206188314 | KEEPRITE | DLCLRBH48AAK | DLFLCAH48XAK | | 29,000 | $1,450 |
| No | 206188311 | KEEPRITE | DLCLRBH36AAK | DLFLCAH36XAK | | 22,000 | $1,100 |
| No | 206188315 | KEEPRITE | DLCLRBH48AAK | DLFLDAH48XAK | | 29,000 | $1,450 |
| No | 207202983 | KEEPRITE | DLCSRBH18AAK | FEM4P18**AL | | 14,700 | $735 |
| No | 207202984 | KEEPRITE | DLCSRBH18AAK | FEM4X18**BL | | 14,700 | $735 |
| No | 207199292 | KEEPRITE | DLCSRBH30AAK | FEM4P30**AL | | 19,100 | $955 |
| No | 207199293 | KEEPRITE | DLCSRBH30AAK | FEM4X30**BL | | 19,100 | $955 |
| No | 207202985 | KEEPRITE | DLCSRBH18AAK | EA*4X19L17A* | *80ES(N,L)0451412A* | 13,800 | $690 |
| No | 207202986 | KEEPRITE | DLCSRBH18AAK | EA*4X24L14A* | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207202987 | KEEPRITE | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207202991 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207202989 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X18L14** | *80ES(N,L)0451412A* | 14,700 | $735 |
| No | 207202990 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X24L14** | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207202988 | KEEPRITE | DLCSRBH18AAK | EA*4X25L17A* | *80ES(N,L)0451412A* | 13,800 | $690 |
| No | 207202992 | KEEPRITE | DLCSRBH18AAK | EA*4X19L17A* | *80ES(N,L)0451712A* | 13,900 | $695 |
| No | 207202993 | KEEPRITE | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0451712A* | 14,600 | $730 |
| No | 207202996 | KEEPRITE | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0701412A* | 14,600 | $730 |
| No | 207202994 | KEEPRITE | DLCSRBH18AAK | EA*4X25L17A* | *80ES(N,L)0451712A* | 13,800 | $690 |
| No | 207202999 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X24L14** | *80ES(N,L)0701412A* | 14,600 | $730 |
| No | 207202995 | KEEPRITE | DLCSRBH18AAK | EA*4X19L17A* | *80ES(N,L)0701412A* | 13,900 | $695 |
| No | 207202997 | KEEPRITE | DLCSRBH18AAK | EA*4X25L17A* | *80ES(N,L)0701412A* | 13,800 | $690 |
| No | 207202998 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X18L14** | *80ES(N,L)0701412A* | 14,700 | $735 |
| No | 207203000 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ES(N,L)0701412A* | 14,600 | $730 |
| No | 207203002 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ES(N,L)0701712A* | 14,700 | $735 |
| No | 207203008 | KEEPRITE | DLCSRBH18AAK | EA*4X24L14A* | *92ESN0401410A* | 14,500 | $725 |
| No | 207203001 | KEEPRITE | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0701712A* | 14,700 | $735 |
| No | 207203003 | KEEPRITE | DLCSRBH18AAK | EA*4X19L17A* | *80ESU0401712A* | 13,700 | $685 |
| No | 207203004 | KEEPRITE | DLCSRBH18AAK | EA*4X24L17A* | *80ESU0401712A* | 14,500 | $725 |
| No | 207203005 | KEEPRITE | DLCSRBH18AAK | EA*4X25L17A* | *80ESU0401712A* | 13,600 | $680 |
| No | 207203010 | KEEPRITE | DLCSRBH18AAK | EA*4X25L17A* | *92ESN0401410A* | 13,700 | $685 |
| No | 207203006 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ESU0401712A* | 14,500 | $725 |
| No | 207203007 | KEEPRITE | DLCSRBH18AAK | EA*4X19L17A* | *92ESN0401410A* | 13,800 | $690 |
| No | 207203014 | KEEPRITE | DLCSRBH18AAK | EA*4X19L17A* | *92ESN0401712A* | 13,900 | $695 |
| No | 207203009 | KEEPRITE | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0401410A* | 14,500 | $725 |
| No | 207203012 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X24L14** | *92ESN0401410A* | 14,500 | $725 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207203011 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X18L14** | *92ESN0401410A* | 14,600 | $730 |
| No | 207203013 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0401410A* | 14,500 | $725 |
| No | 207203021 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X24L14** | *92ESN0601412A* | 14,600 | $730 |
| No | 207203015 | KEEPRITE | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0401712A* | 14,600 | $730 |
| No | 207203018 | KEEPRITE | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0601412A* | 14,600 | $730 |
| No | 207203017 | KEEPRITE | DLCSRBH18AAK | EA*4X19L17A* | *92ESN0601412A* | 14,000 | $700 |
| No | 207203016 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0401712A* | 14,600 | $730 |
| No | 207203019 | KEEPRITE | DLCSRBH18AAK | EA*4X25L17A* | *92ESN0601412A* | 13,800 | $690 |
| No | 207203020 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X18L14** | *92ESN0601412A* | 14,700 | $735 |
| No | 207203022 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0601412A* | 14,600 | $730 |
| No | 207203023 | KEEPRITE | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0801716A* | 14,700 | $735 |
| No | 207203024 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0801716A* | 14,700 | $735 |
| No | 207203025 | KEEPRITE | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0261410A* | 14,100 | $705 |
| No | 207203026 | KEEPRITE | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0261410A* | 14,700 | $735 |
| No | 207203028 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X18L14** | *95ESN0261410A* | 14,800 | $740 |
| No | 207203030 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0261410A* | 14,700 | $735 |
| No | 207203027 | KEEPRITE | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0261410A* | 13,900 | $695 |
| No | 207203029 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X24L14** | *95ESN0261410A* | 14,700 | $735 |
| No | 207203032 | KEEPRITE | DLCSRBH18AAK | EA*4X24L14A* | *95ESN0401410A* | 14,600 | $730 |
| No | 207203039 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0401410A* | 14,600 | $730 |
| No | 207203031 | KEEPRITE | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0401410A* | 13,900 | $695 |
| No | 207203033 | KEEPRITE | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0401410A* | 14,600 | $730 |
| No | 207203036 | KEEPRITE | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0401410A* | 13,800 | $690 |
| No | 207203037 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X18L14** | *95ESN0401410A* | 14,700 | $735 |
| No | 207203040 | KEEPRITE | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0401712A* | 13,800 | $690 |
| No | 207203041 | KEEPRITE | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0401712A* | 14,600 | $730 |
| No | 207203038 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X24L14** | *95ESN0401410A* | 14,600 | $730 |
| No | 207203042 | KEEPRITE | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0401712A* | 13,700 | $685 |
| No | 207203045 | KEEPRITE | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0601412A* | 14,900 | $745 |
| No | 207203043 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0401712A* | 14,600 | $730 |
| No | 207203047 | KEEPRITE | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0601714A* | 14,000 | $700 |
| No | 207203046 | KEEPRITE | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0601714A* | 14,100 | $705 |
| No | 207203044 | KEEPRITE | DLCSRBH18AAK | EA*4X24L14A* | *95ESN0601412A* | 14,900 | $745 |
| No | 207203051 | KEEPRITE | DLCSRBH18AAK | EA*4X25L17A* | *95ESU0401712A* | 13,800 | $690 |
| No | 207203048 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0601714A* | 14,700 | $735 |
| No | 207203049 | KEEPRITE | DLCSRBH18AAK | EA*4X19L17A* | *95ESU0401712A* | 13,800 | $690 |
| No | 207203050 | KEEPRITE | DLCSRBH18AAK | EA*4X24L17A* | *95ESU0401712A* | 14,600 | $730 |
| No | 207203053 | KEEPRITE | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0401410A* | 13,900 | $695 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207203052 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESU0401712A* | 14,600 | $730 |
| No | 207203054 | KEEPRITE | DLCSRBH18AAK | EA*4X24L14A* | *96VTN0401410A* | 14,700 | $735 |
| No | 207203055 | KEEPRITE | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0401410A* | 14,700 | $735 |
| No | 207203056 | KEEPRITE | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0401410A* | 13,900 | $695 |
| No | 207203057 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X18L14** | *96VTN0401410A* | 14,800 | $740 |
| No | 207203058 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X24L14** | *96VTN0401410A* | 14,700 | $735 |
| No | 207203060 | KEEPRITE | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0401712A* | 13,900 | $695 |
| No | 207203059 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X24L17** | *96VTN0401410A* | 14,700 | $735 |
| No | 207203062 | KEEPRITE | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0401712A* | 13,800 | $690 |
| No | 207203061 | KEEPRITE | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0401712A* | 14,600 | $730 |
| No | 207203063 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X24L17** | *96VTN0401712A* | 14,600 | $730 |
| No | 207203065 | KEEPRITE | DLCSRBH18AAK | EA*4X24L14A* | *96VTN0601412A* | 14,600 | $730 |
| No | 207203064 | KEEPRITE | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0601412A* | 13,800 | $690 |
| No | 207203067 | KEEPRITE | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0601412A* | 13,800 | $690 |
| No | 207203066 | KEEPRITE | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0601412A* | 14,600 | $730 |
| No | 207203068 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X18L14** | *96VTN0601412A* | 14,700 | $735 |
| No | 207203069 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X24L14** | *96VTN0601412A* | 14,600 | $730 |
| No | 207203070 | KEEPRITE | DLCSRBH18AAK | EN(A,D)4X24L17** | *96VTN0601412A* | 14,600 | $730 |
| No | 207203071 | KEEPRITE | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0601714A* | 14,100 | $705 |
| No | 207203072 | KEEPRITE | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0601714A* | 14,700 | $735 |
| No | 207203074 | KEEPRITE | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0801716A* | 13,800 | $690 |
| No | 207203073 | KEEPRITE | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0601714A* | 13,900 | $695 |
| No | 207202176 | KEEPRITE | DLCSRBH18AAK | FVM4X24***L | | 13,400 | $670 |
| No | 207202980 | KEEPRITE | DLCSRBH18AAK | FMA4X18**AL* | | 15,000 | $750 |
| No | 207202981 | KEEPRITE | DLCSRBH18AAK | FM(C,U)4Z18**AL* | | 15,000 | $750 |
| No | 207099727 | KEEPRITE | DLCSRBH24AAK | EA*4X24L14A* | *80ES(N,L)0451412A* | 15,700 | $785 |
| No | 207202982 | KEEPRITE | DLCSRBH18AAK | FXM4X18**AL | | 14,500 | $725 |
| No | 207099726 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X24L14** | *80ES(N,L)0451412A* | 15,600 | $780 |
| No | 207099728 | KEEPRITE | DLCSRBH24AAK | EA*4X30L14A* | *80ES(N,L)0451412A* | 15,500 | $775 |
| No | 207099729 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X30L14** | *80ES(N,L)0451412A* | 15,500 | $775 |
| No | 207099730 | KEEPRITE | DLCSRBH24AAK | EA*4X36L17A* | *80ES(N,L)0451712A* | 15,500 | $775 |
| No | 207099731 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X24L14** | *80ES(N,L)0701412A* | 15,600 | $780 |
| No | 207099733 | KEEPRITE | DLCSRBH24AAK | EA*4X30L14A* | *80ES(N,L)0701412A* | 15,500 | $775 |
| No | 207099732 | KEEPRITE | DLCSRBH24AAK | EA*4X24L14A* | *80ES(N,L)0701412A* | 15,700 | $785 |
| No | 207099734 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X30L14** | *80ES(N,L)0701412A* | 15,500 | $775 |
| No | 207099735 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X24L17** | *80ES(N,L)0701712A* | 15,600 | $780 |
| No | 207099736 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X30L17** | *80ES(N,L)0701712A* | 15,400 | $770 |
| No | 207099737 | KEEPRITE | DLCSRBH24AAK | EA*4X36L17A* | *80ES(N,L)0701712A* | 15,400 | $770 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207099738 | KEEPRITE | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *80ES(N,L)0701712A* | 15,400 | $770 |
| No | 207099739 | KEEPRITE | DLCSRBH24AAK | EA*4X30L17A* | *80ES(N,L)0701712A* | 15,500 | $775 |
| No | 207099740 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X24L17** | *80ESU0401712A* | 15,500 | $775 |
| No | 207099741 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X30L17** | *80ESU0401712A* | 15,400 | $770 |
| No | 207099742 | KEEPRITE | DLCSRBH24AAK | EA*4X36L17A* | *80ESU0401712A* | 15,300 | $765 |
| No | 207099748 | KEEPRITE | DLCSRBH24AAK | EA*4X36L17A* | *80ESU0601716A | 15,400 | $770 |
| No | 207099743 | KEEPRITE | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *80ESU0401712A* | 15,400 | $770 |
| No | 207099744 | KEEPRITE | DLCSRBH24AAK | EA*4X30L17A* | *80ESU0401712A* | 15,400 | $770 |
| No | 207099746 | KEEPRITE | DLCSRBH24AAK | EA*4X24L17A* | *80ESU0601716A | 15,700 | $785 |
| No | 207099745 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X24L17** | *80ESU0601716A | 15,600 | $780 |
| No | 207099767 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X24L14** | *92ESN0601714A* | 15,500 | $775 |
| No | 207099747 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X30L17** | *80ESU0601716A | 15,500 | $775 |
| No | 207099763 | KEEPRITE | DLCSRBH24AAK | EA*4X24L14A* | *92ESN0601412A* | 15,700 | $785 |
| No | 207099749 | KEEPRITE | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *80ESU0601716A | 15,500 | $775 |
| No | 207099765 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X30L14** | *92ESN0601412A* | 15,500 | $775 |
| No | 207099762 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X24L14** | *92ESN0601412A* | 15,600 | $780 |
| No | 207099764 | KEEPRITE | DLCSRBH24AAK | EA*4X30L14A* | *92ESN0601412A* | 15,500 | $775 |
| No | 207099768 | KEEPRITE | DLCSRBH24AAK | EA*4X24L14A* | *92ESN0601714A* | 15,700 | $785 |
| No | 207099769 | KEEPRITE | DLCSRBH24AAK | EA*4X30L14A* | *92ESN0601714A* | 15,500 | $775 |
| No | 207099772 | KEEPRITE | DLCSRBH24AAK | EA*4X24L17A* | *92ESN0801716A* | 15,700 | $785 |
| No | 207099770 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X30L14** | *92ESN0601714A* | 15,400 | $770 |
| No | 207099774 | KEEPRITE | DLCSRBH24AAK | EA*4X36L17A* | *92ESN0801716A* | 15,400 | $770 |
| No | 207099771 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X24L17** | *92ESN0801716A* | 15,500 | $775 |
| No | 207099773 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X30L17** | *92ESN0801716A* | 15,400 | $770 |
| No | 207099775 | KEEPRITE | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *92ESN0801716A* | 15,400 | $770 |
| No | 207099776 | KEEPRITE | DLCSRBH24AAK | EA*4X30L17A* | *92ESN0801716A* | 15,400 | $770 |
| No | 207099779 | KEEPRITE | DLCSRBH24AAK | EA*4X30L14A* | *95ESN0261410A* | 15,500 | $775 |
| No | 207099778 | KEEPRITE | DLCSRBH24AAK | EA*4X24L14A* | *95ESN0261410A* | 15,800 | $790 |
| No | 207099788 | KEEPRITE | DLCSRBH24AAK | EA*4X36L17A* | *95ESN0401712A* | 15,500 | $775 |
| No | 207099780 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X30L14** | *95ESN0261410A* | 15,500 | $775 |
| No | 207099787 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESN0401712A* | 15,600 | $780 |
| No | 207099851 | KEEPRITE | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0401410A* | 15,300 | $765 |
| No | 207099846 | KEEPRITE | DLCSRBH24AAK | EA*4X37L21A* | *95ESN0401712A* | 15,200 | $760 |
| No | 207099789 | KEEPRITE | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESN0401712A* | 15,600 | $780 |
| No | 207099790 | KEEPRITE | DLCSRBH24AAK | EA*4X30L17A* | *95ESN0401712A* | 15,600 | $780 |
| No | 207099843 | KEEPRITE | DLCSRBH24AAK | EA*4X25L17A* | *95ESN0401712A* | 15,200 | $760 |
| No | 207099844 | KEEPRITE | DLCSRBH24AAK | EA*4X36L21A* | *95ESN0401712A* | 15,500 | $775 |
| No | 207099794 | KEEPRITE | DLCSRBH24AAK | EA*4X30L14A* | *95ESN0601412A* | 15,600 | $780 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207099792 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X24L14** | *95ESN0601412A* | 15,600 | $780 |
| No | 207099793 | KEEPRITE | DLCSRBH24AAK | EA*4X24L14A* | *95ESN0601412A* | 15,800 | $790 |
| No | 207099847 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X36L21** | *95ESN0401712A* | 15,600 | $780 |
| No | 207099845 | KEEPRITE | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0401712A* | 15,300 | $765 |
| No | 207099795 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X30L14** | *95ESN0601412A* | 15,500 | $775 |
| No | 207099835 | KEEPRITE | DLCSRBH24AAK | EA*4X24L17A* | *95ESN0601412A* | 15,800 | $790 |
| No | 207099836 | KEEPRITE | DLCSRBH24AAK | EA*4X25L17A* | *95ESN0601412A* | 15,200 | $760 |
| No | 207099837 | KEEPRITE | DLCSRBH24AAK | EA*4X36L17A* | *95ESN0601412A* | 15,500 | $775 |
| No | 207099838 | KEEPRITE | DLCSRBH24AAK | EA*4X30L17A* | *95ESN0601412A* | 15,600 | $780 |
| No | 207099840 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X24L17** | *95ESN0601412A* | 15,600 | $780 |
| No | 207099839 | KEEPRITE | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0601412A* | 15,300 | $765 |
| No | 207099841 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESN0601412A* | 15,500 | $775 |
| No | 207099842 | KEEPRITE | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESN0601412A* | 15,500 | $775 |
| No | 207099796 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X24L17** | *95ESN0601714A* | 15,600 | $780 |
| No | 207099797 | KEEPRITE | DLCSRBH24AAK | EA*4X24L17A* | *95ESN0601714A* | 15,800 | $790 |
| No | 207099798 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESN0601714A* | 15,500 | $775 |
| No | 207099799 | KEEPRITE | DLCSRBH24AAK | EA*4X36L17A* | *95ESN0601714A* | 15,400 | $770 |
| No | 207099800 | KEEPRITE | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESN0601714A* | 15,500 | $775 |
| No | 207099801 | KEEPRITE | DLCSRBH24AAK | EA*4X30L17A* | *95ESN0601714A* | 15,500 | $775 |
| No | 207099830 | KEEPRITE | DLCSRBH24AAK | EA*4X25L17A* | *95ESN0601714A* | 15,200 | $760 |
| No | 207099753 | KEEPRITE | DLCSRBH24AAK | EA*4X36L17A* | *95ESU0401712A* | 15,400 | $770 |
| No | 207099833 | KEEPRITE | DLCSRBH24AAK | EA*4X37L21A* | *95ESN0601714A* | 15,100 | $755 |
| No | 207099832 | KEEPRITE | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0601714A* | 15,200 | $760 |
| No | 207099831 | KEEPRITE | DLCSRBH24AAK | EA*4X36L21A* | *95ESN0601714A* | 15,400 | $770 |
| No | 207099750 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X24L17** | *95ESU0401712A* | 15,600 | $780 |
| No | 207099834 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X36L21** | *95ESN0601714A* | 15,500 | $775 |
| No | 207099754 | KEEPRITE | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESU0401712A* | 15,500 | $775 |
| No | 207099751 | KEEPRITE | DLCSRBH24AAK | EA*4X24L17A* | *95ESU0401712A* | 15,700 | $785 |
| No | 207099817 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X30L14** | *96VTN0601412A* | 15,600 | $780 |
| No | 207099752 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESU0401712A* | 15,500 | $775 |
| No | 207099755 | KEEPRITE | DLCSRBH24AAK | EA*4X30L17A* | *95ESU0401712A* | 15,500 | $775 |
| No | 207099805 | KEEPRITE | DLCSRBH24AAK | EA*4X30L14A* | *96VTN0401410A* | 15,600 | $780 |
| No | 207099816 | KEEPRITE | DLCSRBH24AAK | EA*4X30L14A* | *96VTN0601412A* | 15,600 | $780 |
| No | 207099810 | KEEPRITE | DLCSRBH24AAK | EA*4X36L17A* | *96VTN0401712A* | 15,500 | $775 |
| No | 207099806 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X30L14** | *96VTN0401410A* | 15,600 | $780 |
| No | 207099818 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X24L17** | *96VTN0601714A* | 15,600 | $780 |
| No | 207099819 | KEEPRITE | DLCSRBH24AAK | EA*4X24L17A* | *96VTN0601714A* | 15,800 | $790 |
| No | 207099820 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X30L17** | *96VTN0601714A* | 15,500 | $775 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207099821 | KEEPRITE | DLCSRBH24AAK | EA*4X36L17A* | *96VTN0601714A* | 15,400 | $770 |
| No | 207099823 | KEEPRITE | DLCSRBH24AAK | EA*4X30L17A* | *96VTN0601714A* | 15,500 | $775 |
| No | 207099822 | KEEPRITE | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *96VTN0601714A* | 15,500 | $775 |
| No | 207099826 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X30L17** | *96VTN0801716A* | 15,500 | $775 |
| No | 207099825 | KEEPRITE | DLCSRBH24AAK | EA*4X24L17A* | *96VTN0801716A* | 15,700 | $785 |
| No | 207099828 | KEEPRITE | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *96VTN0801716A* | 15,500 | $775 |
| No | 207099824 | KEEPRITE | DLCSRBH24AAK | EN(A,D)4X24L17** | *96VTN0801716A* | 15,600 | $780 |
| No | 207099827 | KEEPRITE | DLCSRBH24AAK | EA*4X36L17A* | *96VTN0801716A* | 15,400 | $770 |
| No | 207099829 | KEEPRITE | DLCSRBH24AAK | EA*4X30L17A* | *96VTN0801716A* | 15,500 | $775 |
| No | 207099721 | KEEPRITE | DLCSRBH24AAK | FXM4X24**AL | | 15,500 | $775 |
| No | 207099723 | KEEPRITE | DLCSRBH24AAK | FMA4X24**AL* | | 16,000 | $800 |
| No | 207199297 | KEEPRITE | DLCSRBH30AAK | EA*4X30L14A* | *80ES(N,L)0451412A* | 19,200 | $960 |
| No | 207099724 | KEEPRITE | DLCSRBH24AAK | FM(C,U)4Z24**AL* | | 16,100 | $805 |
| No | 207199298 | KEEPRITE | DLCSRBH30AAK | EN(A,D)4X30L14** | *80ES(N,L)0451412A* | 19,200 | $960 |
| No | 207199299 | KEEPRITE | DLCSRBH30AAK | EA*4X30L17A* | *80ES(N,L)0451712A* | 19,100 | $955 |
| No | 207199300 | KEEPRITE | DLCSRBH30AAK | EN(A,D)4X30L17** | *80ES(N,L)0451712A* | 19,100 | $955 |
| No | 207199301 | KEEPRITE | DLCSRBH30AAK | EA*4X30L14A* | *80ES(N,L)0701412A* | 19,100 | $955 |
| No | 207199302 | KEEPRITE | DLCSRBH30AAK | EN(A,D)4X30L14** | *80ES(N,L)0701412A* | 19,100 | $955 |
| No | 207199303 | KEEPRITE | DLCSRBH30AAK | EA*4X30L17A* | *80ES(N,L)0701716A* | 19,300 | $965 |
| No | 207199309 | KEEPRITE | DLCSRBH30AAK | EN(A,D)4X30L17** | *80ESU0401712A* | 19,000 | $950 |
| No | 207199305 | KEEPRITE | DLCSRBH30AAK | EA*4X36L21A* | *80ES(N,L)0702116A* | 19,000 | $950 |
| No | 207199304 | KEEPRITE | DLCSRBH30AAK | EN(A,D)4X30L17** | *80ES(N,L)0701716A* | 19,300 | $965 |
| No | 207199306 | KEEPRITE | DLCSRBH30AAK | EN(A,D)4X36L21** | *80ES(N,L)0702116A* | 19,100 | $955 |
| No | 207199307 | KEEPRITE | DLCSRBH30AAK | EN(A,D)4X36L21** | *80ES(N,L)0902116A* | 19,300 | $965 |
| No | 207199308 | KEEPRITE | DLCSRBH30AAK | EA*4X30L17A* | *80ESU0401712A* | 19,000 | $950 |
| No | 207199311 | KEEPRITE | DLCSRBH30AAK | EN(A,D)4X30L14** | *92ESN0601412A* | 19,200 | $960 |
| No | 207199310 | KEEPRITE | DLCSRBH30AAK | EA*4X30L14A* | *92ESN0601412A* | 19,200 | $960 |
| No | 207199313 | KEEPRITE | DLCSRBH30AAK | EN(A,D)4X30L17** | *92ESN0601714A* | 19,100 | $955 |
| No | 207199314 | KEEPRITE | DLCSRBH30AAK | EA*4X30L17A* | *92ESN0801716A* | 19,100 | $955 |
| No | 207199312 | KEEPRITE | DLCSRBH30AAK | EA*4X30L17A* | *92ESN0601714A* | 19,100 | $955 |
| No | 207199315 | KEEPRITE | DLCSRBH30AAK | EN(A,D)4X30L17** | *92ESN0801716A* | 19,100 | $955 |
| No | 207199332 | KEEPRITE | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0401410A* | 19,100 | $955 |
| No | 207199337 | KEEPRITE | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0401712A* | 19,000 | $950 |
| No | 207199333 | KEEPRITE | DLCSRBH30AAK | END4X42L17** | *95ESN0401410A* | 19,200 | $960 |
| No | 207199334 | KEEPRITE | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0401712A* | 19,300 | $965 |
| No | 207199336 | KEEPRITE | DLCSRBH30AAK | EA*4X36L17A* | *95ESN0401712A* | 19,300 | $965 |
| No | 207199335 | KEEPRITE | DLCSRBH30AAK | EA*4X36L21A* | *95ESN0401712A* | 19,300 | $965 |
| No | 207199338 | KEEPRITE | DLCSRBH30AAK | EA*4X42L21A* | *95ESN0401712A* | 19,200 | $960 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207199339 | KEEPRITE | DLCSRBH30AAK | EA*4X43L21A* | *95ESN0401712A* | 18,700 | $935 |
| No | 207199341 | KEEPRITE | DLCSRBH30AAK | EA*4X30L14A* | *95ESN0601412A* | 19,300 | $965 |
| No | 207199345 | KEEPRITE | DLCSRBH30AAK | EN(A,D)4X30L14** | *95ESN0601412A* | 19,300 | $965 |
| No | 207199342 | KEEPRITE | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0601412A* | 19,300 | $965 |
| No | 207199340 | KEEPRITE | DLCSRBH30AAK | END4X42L17** | *95ESN0401712A* | 19,100 | $955 |
| No | 207199343 | KEEPRITE | DLCSRBH30AAK | EA*4X36L17A* | *95ESN0601412A* | 19,200 | $960 |
| No | 207199344 | KEEPRITE | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0601412A* | 19,000 | $950 |
| No | 207199347 | KEEPRITE | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESN0601412A* | 19,300 | $965 |
| No | 207199349 | KEEPRITE | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0601714A* | 19,300 | $965 |
| No | 207199354 | KEEPRITE | DLCSRBH30AAK | EA*4X37L21A* | *95ESN0601714A* | 18,700 | $935 |
| No | 207199346 | KEEPRITE | DLCSRBH30AAK | EN(A,D,W)4X36L17** | *95ESN0601412A* | 19,300 | $965 |
| No | 207199348 | KEEPRITE | DLCSRBH30AAK | END4X42L17** | *95ESN0601412A* | 19,100 | $955 |
| No | 207199351 | KEEPRITE | DLCSRBH30AAK | EA*4X36L21A* | *95ESN0601714A* | 19,200 | $960 |
| No | 207199350 | KEEPRITE | DLCSRBH30AAK | EA*4X36L17A* | *95ESN0601714A* | 19,200 | $960 |
| No | 207199359 | KEEPRITE | DLCSRBH30AAK | END4X42L17** | *95ESN0601714A* | 19,000 | $950 |
| No | 207199353 | KEEPRITE | DLCSRBH30AAK | EA*4X42L21A* | *95ESN0601714A* | 19,100 | $955 |
| No | 207199352 | KEEPRITE | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0601714A* | 19,000 | $950 |
| No | 207199355 | KEEPRITE | DLCSRBH30AAK | EA*4X43L21A* | *95ESN0601714A* | 18,700 | $935 |
| No | 207199357 | KEEPRITE | DLCSRBH30AAK | EN(A,D)4X36L21** | *95ESN0601714A* | 19,200 | $960 |
| No | 207199356 | KEEPRITE | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESN0601714A* | 19,200 | $960 |
| No | 207199358 | KEEPRITE | DLCSRBH30AAK | EN(A,D,W)4X36L17** | *95ESN0601714A* | 19,200 | $960 |
| No | 207199317 | KEEPRITE | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESN0801716A* | 19,300 | $965 |
| No | 207199360 | KEEPRITE | DLCSRBH30AAK | EN(A,D,W)4X42L21** | *95ESN0601714A* | 19,100 | $955 |
| No | 207199316 | KEEPRITE | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0801716A* | 19,300 | $965 |
| No | 207199319 | KEEPRITE | DLCSRBH30AAK | EA*4X30L17A* | *95ESU0401712A* | 19,000 | $950 |
| No | 207199318 | KEEPRITE | DLCSRBH30AAK | EA*4X36L21A* | *95ESN0802120A* | 19,100 | $955 |
| No | 207199321 | KEEPRITE | DLCSRBH30AAK | EA*4X30L17A* | *96VTN0401712A* | 19,300 | $965 |
| No | 207199322 | KEEPRITE | DLCSRBH30AAK | EN(A,D)4X30L14** | *96VTN0601412A* | 19,300 | $965 |
| No | 207199320 | KEEPRITE | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESU0401712A* | 19,000 | $950 |
| No | 207199323 | KEEPRITE | DLCSRBH30AAK | EA*4X30L17A* | *96VTN0601714A* | 19,100 | $955 |
| No | 207199324 | KEEPRITE | DLCSRBH30AAK | EN(A,D)4X30L17** | *96VTN0601714A* | 19,100 | $955 |
| No | 207199325 | KEEPRITE | DLCSRBH30AAK | EA*4X30L17A* | *96VTN0801716A* | 19,100 | $955 |
| No | 207199326 | KEEPRITE | DLCSRBH30AAK | EN(A,D)4X30L17** | *96VTN0801716A* | 19,100 | $955 |
| No | 207199327 | KEEPRITE | DLCSRBH30AAK | EA*4X36L21A* | *96VTN0802120A* | 18,800 | $940 |
| No | 207199295 | KEEPRITE | DLCSRBH30AAK | FXM4X30**AL | | 18,800 | $940 |
| No | 207199328 | KEEPRITE | DLCSRBH30AAK | EN(A,D)4X36L21** | *96VTN0802120A* | 19,000 | $950 |
| No | 207199329 | KEEPRITE | DLCSRBH30AAK | EA*4X36L21A* | *96VTN1002120A* | 18,800 | $940 |
| No | 207200417 | KEEPRITE | DLCSRBH30AAK | EN(A,D)4X36L21** | *96VTN1002120A* | 20,800 | $1,040 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207198930 | KEEPRITE | DLCSRBH30AAK | FVM4X36***L | | 19,200 | $960 |
| No | 207199294 | KEEPRITE | DLCSRBH30AAK | FMA4X30**AL* | | 19,400 | $970 |
| No | 207199296 | KEEPRITE | DLCSRBH30AAK | FM(C,U)4Z30**AL* | | 19,200 | $960 |
| No | 206188312 | KEEPRITE | DLCLRBH36AAK | DLFLDAH36XAK | | 27,000 | $1,350 |
| No | 207643072 | KEEPRITE | DLCMRBH18BAK | Heat pump with ducts | | 11,800 | $590 |
| No | 207643075 | KEEPRITE | DLCMHBH24CAK | Heat pump with ducts | | 18,500 | $925 |
| No | 207643090 | KEEPRITE | DLCMRBH48EAK | Heat pump with ducts | | 30,400 | $1,520 |
| No | 207643076 | KEEPRITE | DLCMHBH24CAK | Combination heat pumps with or without ducts | | 15,900 | $795 |
| No | 207643073 | KEEPRITE | DLCMRBH18BAK | Combination heat pumps with or without ducts | | 11,800 | $590 |
| No | 207643091 | KEEPRITE | DLCMRBH48EAK | Combination heat pumps with or without ducts | | 30,600 | $1,530 |
| No | 207643074 | KEEPRITE | DLCMHBH24CAK | Heat pump without ducts | | 13,300 | $665 |
| No | 207643081 | KEEPRITE | DLCMRBH36DAK | Heat pump without ducts | | 24,000 | $1,200 |
| No | 207643071 | KEEPRITE | DLCMRBH18BAK | Heat pump without ducts | | 11,800 | $590 |
| No | 206350426 | KEEPRITE | DLCSRBH09AAK | DLFSCAH09XAK | | 6,100 | $305 |
| No | 206350427 | KEEPRITE | DLCSRBH09AAK | DLFSDAH09XAK | | 6,400 | $320 |
| No | 206396108 | KEEPRITE | DLCSRBH12AAK | DLFSHAH12XAK | | 7,500 | $375 |
| No | 206361890 | KEEPRITE | DLCSRBH12AAK | DLFSHBH12XAK | | 7,300 | $365 |
| No | 206350429 | KEEPRITE | DLCSRBH12AAK | DLFSDAH12XAK | | 8,300 | $415 |
| No | 206396109 | KEEPRITE | DLCSRAH12AAK | DLFSHBH12XAK | | 7,500 | $375 |
| No | 206396112 | KEEPRITE | DLCSRAH24AAK | DLFSHBH24XAK | | 15,000 | $750 |
| No | 206396113 | KEEPRITE | DLCSRBH24AAK | DLFSHAH24XAK | | 15,000 | $750 |
| No | 206361892 | KEEPRITE | DLCSRBH24AAK | DLFSHBH24XAK | | 17,000 | $850 |
| No | 206361888 | KEEPRITE | DLCSRBH12AAJ | DLFSHBH12XAJ | | 8,200 | $410 |
| No | 206361891 | KEEPRITE | DLCSRBH18AAK | DLFSHBH18XAK | | 11,100 | $555 |
| No | 206361889 | KEEPRITE | DLCSRBH09AAK | DLFSHBH09XAK | | 7,400 | $370 |
| No | 206350428 | KEEPRITE | DLCSRBH12AAK | DLFSCAH12XAK | | 7,900 | $395 |
| No | 206350430 | KEEPRITE | DLCSRBH12AAK | DLFSFAH12XAK | | 8,400 | $420 |
| No | 205767352 | KEEPRITE | DLCLRBH36AAK | DLFLAAH36XAK | | 25,000 | $1,250 |
| No | 205767353 | KEEPRITE | DLCLRBH48AAK | DLFLAAH48XAK | | 36,000 | $1,800 |
| No | 201835681 | KEEPRITE | DLCSRAH36AAK | DLFSHAH36XAK | | 20,600 | $1,030 |
| No | 202463650 | KEEPRITE | DLCPRAH18AAK | DLFPHAH18XAK | | 12,300 | $615 |
| No | 201835695 | KEEPRITE | DLCMRAH48EAK | Heat pump without ducts | | 30,400 | $1,520 |
| No | 201835693 | KEEPRITE | DLCMRAH36DAK | Heat pump without ducts | | 23,600 | $1,180 |
| No | 201835669 | KEEPRITE | DLCSRAH12AAJ | DLFSHAH12XAJ | | 7,100 | $355 |
| No | 201835655 | KEEPRITE | DLCPRAH12AAK | DLFPHAH12XAK | | 6,800 | $340 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201835652 | KEEPRITE | DLCPRAH09AAK | DLFPHAH09XAK | | 7,200 | $360 |
| No | 201835671 | KEEPRITE | DLCSRAH09AAK | DLFSHAH09XAK | | 7,500 | $375 |
| No | 201835687 | KEEPRITE | DLCLRAH58AAK | DLFLDAH58XAK | | 37,600 | $1,880 |
| No | 201835673 | KEEPRITE | DLCSRAH12AAK | DLFSHAH12XAK | | 7,600 | $380 |
| No | 201835675 | KEEPRITE | DLCSRAH18AAK | DLFSHAH18XAK | | 11,900 | $595 |
| No | 201835733 | KEEPRITE | DLCLRAH48AAK | DLFLCAH48XAK | | 35,000 | $1,750 |
| No | 201835735 | KEEPRITE | DLCLRAH58AAK | DLFLFAH58XAK | | 39,000 | $1,950 |
| No | 201835685 | KEEPRITE | DLCLRAH48AAK | DLFLDAH48XAK | | 33,400 | $1,670 |
| No | 201835683 | KEEPRITE | DLCLRAH36AAK | DLFLDAH36XAK | | 27,600 | $1,380 |
| No | 201835713 | KEEPRITE | DLCSRAH12AAK | DLFSDAH12XAK | | 8,100 | $405 |
| No | 201835711 | KEEPRITE | DLCSRAH12AAK | DLFSFAH12XAK | | 9,600 | $480 |
| No | 201835727 | KEEPRITE | DLCLRAH36AAK | DLFLCAH36XAK | | 25,200 | $1,260 |
| No | 201835707 | KEEPRITE | DLCSRAH09AAK | DLFSCAH09XAK | | 6,700 | $335 |
| No | 201835715 | KEEPRITE | DLCSRAH18AAK | DLFSFAH18XAK | | 12,900 | $645 |
| No | 201835709 | KEEPRITE | DLCSRAH12AAK | DLFSCAH12XAK | | 8,200 | $410 |
| No | 201835725 | KEEPRITE | DLCLRAH36AAK | DLFLFAH36XAK | | 25,400 | $1,270 |
| No | 201835705 | KEEPRITE | DLCSRAH09AAK | DLFSDAH09XAK | | 6,800 | $340 |
| No | 210819425 | KENMORE | DLCSRBH30AAK | DLFSABH30XBK | | 20,400 | $1,020 |
| No | 207643110 | KENMORE | DLCMRBH48EAK | Heat pump without ducts | | 31,000 | $1,550 |
| No | 201835787 | KENMORE | DLCMRAH27CAK | Heat pump without ducts | | 17,800 | $890 |
| No | 207826631 | KENMORE | DLCLRCH36AAK | DLFLABH36XAK | | 25,600 | $1,280 |
| No | 208104319 | KENMORE | DLCSRBH36ABK | DLFSABH36XBK | | 25,600 | $1,280 |
| No | 207826630 | KENMORE | DLCLRCH58AAK | DLFLABH60XAK | | 34,000 | $1,700 |
| No | 207826629 | KENMORE | DLCLRCH48AAK | DLFLABH48XAK | | 37,400 | $1,870 |
| No | 207826604 | KENMORE | DLCSRBH24AAK | DLFSABH24XBK | | 16,200 | $810 |
| No | 208104320 | KENMORE | DLCSRBH30AAK11 | DLFSABH30XBK | | 19,200 | $960 |
| No | 206188320 | KENMORE | DLCLRBH48AAK | DLFLFAH48XAK | | 29,000 | $1,450 |
| No | 206188317 | KENMORE | DLCLRBH36AAK | DLFLFAH36XAK | | 22,000 | $1,100 |
| No | 206188321 | KENMORE | DLCLRBH48AAK | DLFLCAH48XAK | | 29,000 | $1,450 |
| No | 206188318 | KENMORE | DLCLRBH36AAK | DLFLCAH36XAK | | 22,000 | $1,100 |
| No | 206188322 | KENMORE | DLCLRBH48AAK | DLFLDAH48XAK | | 29,000 | $1,450 |
| No | 206188319 | KENMORE | DLCLRBH36AAK | DLFLDAH36XAK | | 27,000 | $1,350 |
| No | 207643096 | KENMORE | DLCMHBH24CAK | Heat pump with ducts | | 18,500 | $925 |
| No | 207643111 | KENMORE | DLCMRBH48EAK | Heat pump with ducts | | 30,400 | $1,520 |
| No | 207643093 | KENMORE | DLCMRBH18BAK | Heat pump with ducts | | 11,800 | $590 |
| No | 207643097 | KENMORE | DLCMHBH24CAK | Combination heat pumps with or without ducts | | 15,900 | $795 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207643094 | KENMORE | DLCMRBH18BAK | Combination heat pumps with or without ducts | | 11,800 | $590 |
| No | 207643112 | KENMORE | DLCMRBH48EAK | Combination heat pumps with or without ducts | | 30,600 | $1,530 |
| No | 207643095 | KENMORE | DLCMHBH24CAK | Heat pump without ducts | | 13,300 | $665 |
| No | 207643092 | KENMORE | DLCMRBH18BAK | Heat pump without ducts | | 11,800 | $590 |
| No | 207643102 | KENMORE | DLCMRBH36DAK | Heat pump without ducts | | 24,000 | $1,200 |
| No | 206350437 | KENMORE | DLCSRBH09AAK | DLFSCAH09XAK | | 6,100 | $305 |
| No | 206350438 | KENMORE | DLCSRBH09AAK | DLFSDAH09XAK | | 6,400 | $320 |
| No | 206396118 | KENMORE | DLCSRBH12AAK | DLFSHAH12XAK | | 7,500 | $375 |
| No | 206361895 | KENMORE | DLCSRBH12AAK | DLFSHBH12XAK | | 7,300 | $365 |
| No | 206350440 | KENMORE | DLCSRBH12AAK | DLFSDAH12XAK | | 8,300 | $415 |
| No | 206361893 | KENMORE | DLCSRBH12AAJ | DLFSHBH12XAJ | | 8,200 | $410 |
| No | 206396119 | KENMORE | DLCSRAH12AAK | DLFSHBH12XAK | | 7,500 | $375 |
| No | 206396122 | KENMORE | DLCSRAH24AAK | DLFSHBH24XAK | | 15,000 | $750 |
| No | 206396123 | KENMORE | DLCSRBH24AAK | DLFSHAH24XAK | | 15,000 | $750 |
| No | 206361897 | KENMORE | DLCSRBH24AAK | DLFSHBH24XAK | | 17,000 | $850 |
| No | 206361896 | KENMORE | DLCSRBH18AAK | DLFSHBH18XAK | | 11,100 | $555 |
| No | 206350439 | KENMORE | DLCSRBH12AAK | DLFSCAH12XAK | | 7,900 | $395 |
| No | 206361894 | KENMORE | DLCSRBH09AAK | DLFSHBH09XAK | | 7,400 | $370 |
| No | 206350441 | KENMORE | DLCSRBH12AAK | DLFSFAH12XAK | | 8,400 | $420 |
| No | 205767356 | KENMORE | DLCLRBH48AAK | DLFLAAH48XAK | | 36,000 | $1,800 |
| No | 205767355 | KENMORE | DLCLRBH36AAK | DLFLAAH36XAK | | 25,000 | $1,250 |
| No | 201835776 | KENMORE | DLCSRAH36AAK | DLFSHAH36XAK | | 20,600 | $1,030 |
| No | 202463652 | KENMORE | DLCPRAH18AAK | DLFPHAH18XAK | | 12,300 | $615 |
| No | 201835790 | KENMORE | DLCMRAH48EAK | Heat pump without ducts | | 30,400 | $1,520 |
| No | 201835788 | KENMORE | DLCMRAH36DAK | Heat pump without ducts | | 23,600 | $1,180 |
| No | 201835764 | KENMORE | DLCSRAH12AAJ | DLFSHAH12XAJ | | 7,100 | $355 |
| No | 201835751 | KENMORE | DLCPRAH12AAK | DLFPHAH12XAK | | 6,800 | $340 |
| No | 201835749 | KENMORE | DLCPRAH09AAK | DLFPHAH09XAK | | 7,200 | $360 |
| No | 201835766 | KENMORE | DLCSRAH09AAK | DLFSHAH09XAK | | 7,500 | $375 |
| No | 201835783 | KENMORE | DLCLRAH58AAK | DLFLDAH58XAK | | 37,600 | $1,880 |
| No | 201835770 | KENMORE | DLCSRAH18AAK | DLFSHAH18XAK | | 11,900 | $595 |
| No | 201835768 | KENMORE | DLCSRAH12AAK | DLFSHAH12XAK | | 7,600 | $380 |
| No | 201835829 | KENMORE | DLCLRAH48AAK | DLFLCAH48XAK | | 35,000 | $1,750 |
| No | 201835831 | KENMORE | DLCLRAH58AAK | DLFLFAH58XAK | | 39,000 | $1,950 |
| No | 201835780 | KENMORE | DLCLRAH48AAK | DLFLDAH48XAK | | 33,400 | $1,670 |
| No | 201835778 | KENMORE | DLCLRAH36AAK | DLFLDAH36XAK | | 27,600 | $1,380 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201835809 | KENMORE | DLCSRAH12AAK | DLFSDAH12XAK | | 8,100 | $405 |
| No | 201835807 | KENMORE | DLCSRAH12AAK | DLFSFAH12XAK | | 9,600 | $480 |
| No | 201835823 | KENMORE | DLCLRAH36AAK | DLFLCAH36XAK | | 25,200 | $1,260 |
| No | 201835803 | KENMORE | DLCSRAH09AAK | DLFSCAH09XAK | | 6,700 | $335 |
| No | 201835811 | KENMORE | DLCSRAH18AAK | DLFSFAH18XAK | | 12,900 | $645 |
| No | 201835805 | KENMORE | DLCSRAH12AAK | DLFSCAH12XAK | | 8,200 | $410 |
| No | 201835821 | KENMORE | DLCLRAH36AAK | DLFLFAH36XAK | | 25,400 | $1,270 |
| No | 201835801 | KENMORE | DLCSRAH09AAK | DLFSDAH09XAK | | 6,800 | $340 |
| No | 207657393 | KERR | A-KMH06SV-1 | B-KMH06SV-1 | | 8,500 | $425 |
| No | 206347317 | KERR | A-KMH18SU-1A | B-KMH18CU-1 | | 15,600 | $780 |
| No | 210568254 | KERR | A-KMH18SV-1 | B-KMH18CU-1 | | 15,600 | $780 |
| No | 210568250 | KERR | A-KMH18SV-1 | B-KMH18UU-1 | | 12,000 | $600 |
| No | 206347322 | KERR | A-KMH18SU-1A | B-KMH18UU-1 | | 12,000 | $600 |
| No | 210568251 | KERR | A-KMH12SV-1 | B-KMH12FU-1 | | 9,600 | $480 |
| No | 210568257 | KERR | A-KMH12SV-1 | B-KMH12DU-1 | | 10,600 | $530 |
| No | 210568256 | KERR | A-KMH12SV-1 | B-KMH12CU-1 | | 9,900 | $495 |
| No | 210568255 | KERR | A-KMH09SV-1 | B-KMH09DU-1 | | 10,100 | $505 |
| No | 210568249 | KERR | A-KMH09SV-1 | B-KMH09CU-1 | | 9,000 | $450 |
| No | 207657395 | KERR | A-KMH12SV-1 | B-KMH12SV-1 | | 10,000 | $500 |
| No | 207657394 | KERR | A-KMH09SV-1 | B-KMH09SV-1 | | 9,500 | $475 |
| No | 9710790 | KERR | A-KMH12SU-1 | B-KMH12SU-1 | | 7,800 | $390 |
| No | 9710789 | KERR | A-KMH09SU-1 | B-KMH09SU-1 | | 6,900 | $345 |
| No | 201866484 | KERR | A-KMH36QU-1 | Heat pump with ducts | | 24,600 | $1,230 |
| No | 201866481 | KERR | A-KMH36QU-1 | Heat pump without ducts | | 23,200 | $1,160 |
| No | 202110997 | KERR | A-KMH09SU-1 | B-KMH09DU-1 | | 7,200 | $360 |
| No | 202110998 | KERR | A-KMH12SU-1 | B-KMH12DU-1 | | 8,500 | $425 |
| No | 206347316 | KERR | A-KMH12SU-1 | B-KMH12CU-1 | | 8,700 | $435 |
| No | 202195107 | KERR | A-KMH48PU-1 | Heat pump without ducts | | 29,600 | $1,480 |
| No | 206347318 | KERR | A-KMH24SU-1A | B-KMH24CU-1 | | 14,500 | $725 |
| No | 205747697 | KERR | A-KMH18SU-1A | B-KMH18SU-1A | | 10,900 | $545 |
| No | 208141195 | KERR | A-KMH18SV-1 | B-KMH18SU-1 | | 10,900 | $545 |
| No | 206913572 | KERR | A-KMH18SU-1 | B-KMH18SU-1A | | 10,900 | $545 |
| No | 208141194 | KERR | A-KMH12SV-1 | B-KMH12SU-1 | | 7,600 | $380 |
| No | 207657600 | KERR | A-KMH18DV-1 | Combination heat pumps with or without ducts | | 11,500 | $575 |
| No | 208141193 | KERR | A-KMH09SV-1 | B-KMH09SU-1 | | 7,100 | $355 |
| No | 206913037 | KERR | A-KMH18SU-1A | B-KMH18SU-1 | | 10,900 | $545 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207657603 | KERR | A-KMH28TV-1 | Combination heat pumps with or without ducts | | 17,000 | $850 |
| No | 212361364 | KINGHOME | KU60UHO | KCA60*I | | 35,200 | $1,760 |
| No | 212361363 | KINGHOME | KU60UHO | KCA48*I | | 31,200 | $1,560 |
| No | 212361362 | KINGHOME | KU36UHO | KCA36*I | | 22,000 | $1,100 |
| No | 211749846 | KINGHOME | KAM24HO | KM24HT1DI | | 14,800 | $740 |
| No | 211749845 | KINGHOME | KAM24HO | KM24HK1DI | | 15,500 | $775 |
| No | 211749844 | KINGHOME | KAM24HO | KM24HF1DI | | 14,900 | $745 |
| No | 211749840 | KINGHOME | KAM12HO | KM12HT1DI | | 7,200 | $360 |
| No | 211749839 | KINGHOME | KAM12HO | KM12HK1DI | | 6,900 | $345 |
| No | 211749838 | KINGHOME | KAM12HO | KM12HF1DI | | 6,900 | $345 |
| No | 211749837 | KINGHOME | KAM09HO | KM09HT1DI | | 6,900 | $345 |
| No | 211749836 | KINGHOME | KAM09HO | KM09HF1DI | | 6,900 | $345 |
| No | 211497154 | KINGHOME | KM30H5O | Heat pump without ducts | | 27,200 | $1,360 |
| No | 211497153 | KINGHOME | KM24H5O | Heat pump without ducts | | 23,600 | $1,180 |
| No | 211497152 | KINGHOME | KM18H5O | Heat pump without ducts | | 14,700 | $735 |
| No | 211497150 | KINGHOME | KD60UHO | KD60UHI | | 30,000 | $1,500 |
| No | 211497149 | KINGHOME | KD48UHO | KD48UHI | | 26,000 | $1,300 |
| No | 211497148 | KINGHOME | KD42UHO | KD42UHI | | 25,000 | $1,250 |
| No | 211497147 | KINGHOME | KD36UHO | KD36UHI | | 19,000 | $950 |
| No | 211497146 | KINGHOME | KD30UHO | KD30UHI | | 18,600 | $930 |
| No | 211497145 | KINGHOME | KD24UHO | KD24UHI | | 14,600 | $730 |
| No | 208141285 | KINGHOME | KW24HQ17SDO | KW24HQ17SDI | | 13,900 | $695 |
| No | 204462625 | KINGHOME | KM42UH5O | Heat pump without ducts | | 30,000 | $1,500 |
| No | 204462624 | KINGHOME | KM36UH5O | Heat pump without ducts | | 29,000 | $1,450 |
| No | 211177527 | KINGHOME | KW36HQ20SDO | KW36HQ20SDI | | 22,000 | $1,100 |
| No | 211177526 | KINGHOME | KW18HP25SDO | KW18HP25SDI | | 11,000 | $550 |
| No | 211164219 | KINGHOME | KW30HQ20SDO | KW30HQ20SDI | | 18,500 | $925 |
| No | 211151018 | KINGHOME | KW18HQ25SDO | KW18HQ25SDI | | 10,800 | $540 |
| No | 209847251 | KINGHOME | KW24HQ25SDO | KW24HQ25SDI | | 15,000 | $750 |
| No | 209847250 | KINGHOME | KW09HQ25SAO | KW09HQ25SAI | | 7,000 | $350 |
| No | 209847249 | KINGHOME | KW09HQ25SDO | KW09HQ25SDI | | 7,000 | $350 |
| No | 209847248 | KINGHOME | KW12HQ25SAO | KW12HQ25SAI | | 6,300 | $315 |
| No | 209847247 | KINGHOME | KW12HQ25SDO | KW12HQ25SDI | | 6,300 | $315 |
| No | 10340478 | KINGHOME | KM30H4O | Heat pump without ducts | | 18,000 | $900 |
| No | 10339781 | KINGHOME | KM24H4O | Heat pump without ducts | | 16,600 | $830 |
| No | 10339674 | KINGHOME | KM18H4O | Heat pump without ducts | | 12,800 | $640 |
| No | 204462787 | KINGHOME | KU21-ODU24-4 | KU21-CDU24-4 | | 16,500 | $825 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204462789 | KINGHOME | KU21-ODU36-4 | KU21-CDU36-4 | | 29,400 | $1,470 |
| No | 204462788 | KINGHOME | KU21-ODU30-4 | KU21-CDU30-4 | | 17,500 | $875 |
| No | 10338158 | KINGHOME | KW12HTBA3DO | KW12HTBA3DI | | 8,000 | $400 |
| No | 10338835 | KINGHOME | KW12HUCA4DO | KW12HUCA4DI | | 8,500 | $425 |
| No | 10333037 | KINGHOME | KW12HQ2B8DO | KW12HQ2B8DI | | 7,700 | $385 |
| No | 203493070 | KINGHOME | KW12HQ3D6DO | KW12HQ3D6DI | | 8,300 | $415 |
| No | 203493069 | KINGHOME | KW09HQ3D6DO | KW09HQ3D6DI | | 7,300 | $365 |
| No | 10333036 | KINGHOME | KW09HQ2B8DO | KW09HQ2B8DI | | 7,300 | $365 |
| No | 10340613 | KINGHOME | KM42H4O | Heat pump without ducts | | 29,000 | $1,450 |
| No | 10338834 | KINGHOME | KW09HUCA4DO | KW09HUCA4DI | | 5,380 | $269 |
| No | 204760469 | KINGHOME | KW12HQ2B8AO | KW12HQ2B8AI | | 6,800 | $340 |
| No | 10338165 | KINGHOME | KU21-ODU24-3 | KU21-CDU24-3 | | 16,700 | $835 |
| No | 204462788 | KINGHOME | KU21-ODU30-4 | KU21-CDU30-4 | | 17,500 | $875 |
| No | 10338143 | KINGHOME | KU21-ODU30-3 | KU21-CDU30-3 | | 16,700 | $835 |
| No | 204462789 | KINGHOME | KU21-ODU36-4 | KU21-CDU36-4 | | 29,400 | $1,470 |
| No | 10338148 | KINGHOME | KU21-ODU36-3 | KU21-CDU36-3 | | 24,600 | $1,230 |
| No | 10338157 | KINGHOME | KW09HTBA3DO | KW09HTBA3DI | | 5,800 | $290 |
| No | 10338159 | KINGHOME | KW18HTCA3DO | KW18HTCA3DI | | 12,100 | $605 |
| No | 10333042 | KINGHOME | KU21-ODU18-3 | KU21-CDU18-3 | | 10,900 | $545 |
| No | 204462627 | KINGHOME | KU21-ODU18-4 | KU21-CDU18-4S | | 12,500 | $625 |
| No | 10340485 | KINGHOME | KM36H4O | Heat pump without ducts | | 20,000 | $1,000 |
| No | 10333026 | KINGHOME | KW24HQ3B8DO | KW24HQ3B8DI | | 16,000 | $800 |
| No | 204760468 | KINGHOME | KW09HQ2B8AO | KW09HQ2B8AI | | 6,100 | $305 |
| No | 209862177 | KLIMAIRE | KSIR060-H218-2 | KDIS060-H2G1 | | 34,400 | $1,720 |
| No | 209862180 | KLIMAIRE | KSIR060-H218-2 | KFUF060-H2G1 | | 35,000 | $1,750 |
| No | 209862152 | KLIMAIRE | KSIE024-H220-O-2 | KSIE024-H220-IW-2 | | 18,000 | $900 |
| No | 209862193 | KLIMAIRE | KMIR436-H217-2 | Heat pump without ducts | | 26,400 | $1,320 |
| No | 209862187 | KLIMAIRE | KMIR327-H217-2 | Heat pump without ducts | | 20,000 | $1,000 |
| No | 209862188 | KLIMAIRE | KMIR327-H217-2 | Heat pump with ducts | | 22,000 | $1,100 |
| No | 209862182 | KLIMAIRE | KMIR218-H221-2 | Heat pump with ducts | | 14,800 | $740 |
| No | 209862196 | KLIMAIRE | KMIR545-H219-2 | Heat pump without ducts | | 36,000 | $1,800 |
| No | 209862181 | KLIMAIRE | KMIR218-H221-2 | Heat pump without ducts | | 14,400 | $720 |
| No | 209862162 | KLIMAIRE | KSIE018-H220-O-2 | KDIP18-H2 | | 12,600 | $630 |
| No | 209862159 | KLIMAIRE | KSIE018-H220-O-2 | KTIR18-H2 | | 12,000 | $600 |
| No | 209862164 | KLIMAIRE | KSIE018-H220-O-2 | KUIR18-H2 | | 12,800 | $640 |
| No | 209862150 | KLIMAIRE | KSIE012-H220-O-2 | KSIE012-H220-IW-2 | | 8,200 | $410 |
| No | 209862149 | KLIMAIRE | KSIE009-H221-O-2 | KSIE009-H221-IW-2 | | 8,300 | $415 |
| No | 209862147 | KLIMAIRE | KSIE009-H121-O-2 | KSIE009-H121-IW-2 | | 6,000 | $300 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 209862151 | KLIMAIRE | KSIE018-H220-O-2 | KSIE018-H220-IW-2 | | 14,000 | $700 |
| No | 209862148 | KLIMAIRE | KSIE012-H120-O-2 | KSIE012-H120-IW-2 | | 8,400 | $420 |
| No | 209862143 | KLIMAIRE | KSIV018-H219-O-2 | KSIV018-H219-IW-2 | | 11,500 | $575 |
| No | 209862141 | KLIMAIRE | KSIV009-H219-O-2 | KSIV009-H219-IW-2 | | 6,900 | $345 |
| No | 209862139 | KLIMAIRE | KSIV009-H119-O-2 | KSIV009-H119-IW-2 | | 6,800 | $340 |
| No | 212316045 | KLIMAIRE | KSIE024-H220-O-2 | KTIS24-H2 | | 19,000 | $950 |
| No | 209862176 | KLIMAIRE | KSIR048-H218-2 | KDIR048-H2G1 | | 34,000 | $1,700 |
| No | 212316047 | KLIMAIRE | KSIR048-H218-2 | KTIS48-H2 | | 30,000 | $1,500 |
| No | 209862179 | KLIMAIRE | KSIR048-H218-2 | KFUF048-H2G1 | | 29,000 | $1,450 |
| No | 209862175 | KLIMAIRE | KSIR036-H218-2 | KDIR036-H2G1 | | 25,000 | $1,250 |
| No | 212316046 | KLIMAIRE | KSIR036-H218-2 | KTIS36-H2 | | 23,000 | $1,150 |
| No | 209862178 | KLIMAIRE | KSIR036-H218-2 | KFUF036-H2G1 | | 23,000 | $1,150 |
| No | 209862146 | KLIMAIRE | KSIR036-H215-O-2 | KSIR036-H215-IW-2 | | 24,000 | $1,200 |
| No | 209862155 | KLIMAIRE | KSIH018-H220-O-2 | KSIH018-H220-IW-2 | | 11,100 | $555 |
| No | 209862154 | KLIMAIRE | KSIH012-H222-O-2 | KSIH012-H222-IW-2 | | 10,300 | $515 |
| No | 209862153 | KLIMAIRE | KSIH009-H225-O-2 | KSIH009-H225-IW-2 | | 9,300 | $465 |
| No | 209862163 | KLIMAIRE | KSIE024-H220-O-2 | KDIP24-H2 | | 20,000 | $1,000 |
| No | 209862168 | KLIMAIRE | KSIH018-H220-O-2 | KTIR18-H2 | | 15,600 | $780 |
| No | 209862173 | KLIMAIRE | KSIH018-H220-O-2 | KUIR18-H2 | | 12,000 | $600 |
| No | 209862171 | KLIMAIRE | KSIH012-H222-O-2 | KDIP12-H2 | | 10,600 | $530 |
| No | 209862167 | KLIMAIRE | KSIH012-H222-O-2 | KTIR12-H2 | | 9,900 | $495 |
| No | 209862161 | KLIMAIRE | KSIE012-H220-O-2 | KDIP12-H2 | | 9,300 | $465 |
| No | 209862170 | KLIMAIRE | KSIH009-H225-O-2 | KDIP09-H2 | | 10,100 | $505 |
| No | 209862166 | KLIMAIRE | KSIH009-H225-O-2 | KTIR09-H2 | | 9,000 | $450 |
| No | 209862160 | KLIMAIRE | KSIE009-H221-O-2 | KDIP09-H2 | | 7,700 | $385 |
| No | 209862165 | KLIMAIRE | KSIE024-H220-O-2 | KUIR24-H2 | | 16,000 | $800 |
| No | 209862158 | KLIMAIRE | KSIE012-H220-O-2 | KTIR12-H2 | | 8,900 | $445 |
| No | 209862157 | KLIMAIRE | KSIE009-H221-O-2 | KTIR09-H2 | | 7,500 | $375 |
| No | 212316042 | KLIMAIRE | KOIF36H2-1S | KIDF36H2-1S | | 30,400 | $1,520 |
| No | 212316041 | KLIMAIRE | KOIF30H2-1S | KIDF30H2-1S | | 21,000 | $1,050 |
| No | 212331385 | LBG Products | LCHB48DO | LCHB48DA | | 30,400 | $1,520 |
| No | 212331379 | LBG Products | LCHB18DO | LCHB24DA | | 13,000 | $650 |
| No | 212331393 | LBG Products | LCUHB48DO | LCHB48DA | | 32,000 | $1,600 |
| No | 212331392 | LBG Products | LCUHB36DO | LCHB36DA | | 33,000 | $1,650 |
| No | 212331383 | LBG Products | LCHB36DO | LCHB36DA | | 19,800 | $990 |
| No | 212331389 | LBG Products | LCUHB24DO | LCHB24DA | | 21,000 | $1,050 |
| No | 212331388 | LBG Products | LCUHB18DO | LCHB24DA | | 14,700 | $735 |
| No | 212331386 | LBG Products | LCHB60DO | LCHB60DA | | 34,000 | $1,700 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 212331382 | LBG Products | LCHB30DO | LCHB36DA | | 22,000 | $1,100 |
| No | 212331381 | LBG Products | LCHB24DO | LCHB24DA | | 22,000 | $1,100 |
| No | 208136305 | LBG Products | LCHB60DO | LCHB60DHNI | | 37,000 | $1,850 |
| No | 208136304 | LBG Products | LCHB48DO | LCHB48DHNI | | 37,000 | $1,850 |
| No | 208136303 | LBG Products | LCHB36DO | LCHB36DHNI | | 20,400 | $1,020 |
| No | 208136301 | LBG Products | LCHB24DO | LCHB24DHNI | | 21,000 | $1,050 |
| No | 208136300 | LBG Products | LCHB18DO | LCHB18DHNI | | 12,000 | $600 |
| No | 207641311 | LBG PRODUCTS | LMHB36DO | Heat pump without ducts | | 26,400 | $1,320 |
| No | 207641313 | LBG PRODUCTS | LMHB48DO | Heat pump without ducts | | 36,000 | $1,800 |
| No | 207641308 | LBG Products | LMHB27DO | Heat pump without ducts | | 20,000 | $1,000 |
| No | 207641307 | LBG Products | LMHB27DO | Heat pump with ducts | | 22,000 | $1,100 |
| No | 207641305 | LBG Products | LMHB18DO | Heat pump with ducts | | 14,800 | $740 |
| No | 207641304 | LBG Products | LMHB18DO | Heat pump without ducts | | 14,400 | $720 |
| No | 208130819 | LBG Products | LUHB60DO | LUHB60DFI | | 34,400 | $1,720 |
| No | 208130825 | LBG Products | LUHB60DO | LUHB60DZDI | | 35,000 | $1,750 |
| No | 208130815 | LBG Products | LBHB18DUWO | LMHB18DFI | | 12,600 | $630 |
| No | 208130809 | LBG Products | LBHB18DUWO | LMHB18DSI | | 12,000 | $600 |
| No | 208130821 | LBG Products | LBHB18DUWO | LMHB18DZDI | | 12,800 | $640 |
| No | 208130805 | LBG Products | LBHB18DUWO | LBHB18DUWI | | 14,100 | $705 |
| No | 208130810 | LBG Products | LBHB24DUWO | LMHB24DSI | | 19,000 | $950 |
| No | 208130841 | LBG Products | LUUHB36DO | LUHB36DFI | | 34,000 | $1,700 |
| No | 208130818 | LBG Products | LUHB48DO | LUHB48DFI | | 34,000 | $1,700 |
| No | 208130812 | LBG Products | LUHB48DO | LUHB48DSI | | 30,000 | $1,500 |
| No | 208130824 | LBG Products | LUHB48DO | LUHB48DZDI | | 29,000 | $1,450 |
| No | 208130817 | LBG Products | LUHB36DO | LUHB36DFI | | 25,000 | $1,250 |
| No | 208130811 | LBG Products | LUHB36DO | LUHB36DSI | | 23,000 | $1,150 |
| No | 208130823 | LBG Products | LUHB36DO | LUHB36DZDI | | 23,000 | $1,150 |
| No | 208130803 | LBG Products | LBHB09DUWO | LBHB09DUWI | | 8,100 | $405 |
| No | 208130826 | LBG Products | LBHB06DVWO | LBHB06DVWI | | 7,500 | $375 |
| No | 207251119 | LBG Products | LBH36DTO | LBH36DTI | | 24,000 | $1,200 |
| No | 207251117 | LBG Products | LBH24DTO | LBH24DTI | | 16,500 | $825 |
| No | 207251118 | LBG Products | LBH18DTO | LBH18DTI | | 11,400 | $570 |
| No | 207251120 | LBG Products | LBH12DTO | LBH12DTI | | 7,000 | $350 |
| No | 207251115 | LBG Products | LBH09DTO | LBH09DTI | | 6,000 | $300 |
| No | 207251116 | LBG Products | LBH12ATO | LBH12ATI | | 7,800 | $390 |
| No | 208130806 | LBG Products | LBHB24DUWO | LBHB24DUWI | | 17,400 | $870 |
| No | 208130804 | LBG Products | LBHB12DUWO | LBHB12DUWI | | 10,000 | $500 |
| No | 208130829 | LBG Products | LBHB18DVWO | LBHB18DUWI | | 11,100 | $555 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208130828 | LBG Products | LBHB12DVWO | LBHB12DUWI | | 10,300 | $515 |
| No | 208130827 | LBG Products | LBHB09DVWO | LBHB09DUWI | | 9,300 | $465 |
| No | 208130816 | LBG Products | LBHB24DUWO | LMHB24DFI | | 20,000 | $1,000 |
| No | 208130833 | LBG Products | LBHB18DVWO | LMHB18DSI | | 15,600 | $780 |
| No | 208130844 | LBG Products | LBHB18DVWO | LMHB18DZDI | | 12,000 | $600 |
| No | 208130843 | LBG Products | LBHB12DVWO | LMHB12DZGI | | 9,600 | $480 |
| No | 208130838 | LBG Products | LBHB12DVWO | LMHB12DFI | | 10,600 | $530 |
| No | 208130832 | LBG Products | LBHB12DVWO | LMHB12DSI | | 9,900 | $495 |
| No | 208130820 | LBG Products | LBHB12DUWO | LMHB12DZGI | | 9,000 | $450 |
| No | 208130814 | LBG Products | LBHB12DUWO | LMHB12DFI | | 9,300 | $465 |
| No | 208130837 | LBG Products | LBHB09DVWO | LMHB09DFI | | 10,100 | $505 |
| No | 208130831 | LBG Products | LBHB09DVWO | LMHB09DSI | | 9,000 | $450 |
| No | 208130813 | LBG Products | LBHB09DUWO | LMHB09DFI | | 7,700 | $385 |
| No | 208130822 | LBG Products | LBHB24DUWO | LMHB24DZDI | | 16,000 | $800 |
| No | 208130808 | LBG Products | LBHB12DUWO | LMHB12DSI | | 8,900 | $445 |
| No | 208130807 | LBG Products | LBHB09DUWO | LMHB09DSI | | 7,500 | $375 |
| No | 207251114 | LBG Products | LBH09ATO | LBH09ATI | | 6,300 | $315 |
| No | 207629153 | LBG PRODUCTS | LBHB09DYWO | LBHB09DYWI | | 7,300 | $365 |
| No | 207629154 | LBG PRODUCTS | LBHB12DYWO | LBHB12DYWI | | 7,300 | $365 |
| No | 207641328 | LBG PRODUCTS | LCHB60DO | LCHB60DHNI | | 33,800 | $1,690 |
| No | 207641314 | LBG PRODUCTS | LMHB48DO | Heat pump with ducts | | 30,400 | $1,520 |
| No | 207641306 | LBG PRODUCTS | LMHB18DO | Combination heat pumps with or without ducts | | 11,800 | $590 |
| No | 207641309 | LBG PRODUCTS | LMHB27DO | Combination heat pumps with or without ducts | | 16,100 | $805 |
| No | 207641315 | LBG PRODUCTS | LMHB48DO | Combination heat pumps with or without ducts | | 30,600 | $1,530 |
| No | 208136302 | LBG PRODUCTS | LCHB30DO | LCHB30DHNI | | 19,000 | $950 |
| No | 207641321 | LBG PRODUCTS | LMUHB27DO | Combination heat pumps with or without ducts | | 16,900 | $845 |
| No | 206853247 | LBG PRODUCTS | LBH24DWO | LBH24DWI | | 14,600 | $730 |
| No | 211034462 | LENNOX | MHB012S4S-1L | MWHB012S4-*L | | 7,800 | $390 |
| No | 211034461 | LENNOX | MHB009S4S-1L | MWHB009S4-*L | | 6,300 | $315 |
| No | 211034415 | LENNOX | MPC012S4S-1L | MWMC012S4-*L | | 8,400 | $420 |
| No | 207699101 | LENNOX | MPC048S4M-1P | Heat pump without ducts | | 34,000 | $1,700 |
| No | 211034466 | LENNOX | MHB024S4S-1P | MWHB024S4-*P | | 16,500 | $825 |
| No | 211034465 | LENNOX | MHB018S4S-1P | MWHB018S4-*P | | 11,400 | $570 |
| No | 211034464 | LENNOX | MHB012S4S-1P | MWHB012S4-*P | | 7,000 | $350 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211034463 | LENNOX | MHB009S4S-1P | MWHB009S4-*P | | 6,000 | $300 |
| No | 211034457 | LENNOX | MLB018S4S-1P | M22A018S4-*P | | 15,600 | $780 |
| No | 211034456 | LENNOX | MLB012S4S-1P | M22A012S4-*P | | 9,900 | $495 |
| No | 211034455 | LENNOX | MLB009S4S-1P | M22A009S4-*P | | 9,000 | $450 |
| No | 211034453 | LENNOX | MLB036S4S-2P | MCFA036S4-*P | | 32,000 | $1,600 |
| No | 211034451 | LENNOX | MLB018S4S-1P | MCFB018S4-*P | | 12,000 | $600 |
| No | 211034450 | LENNOX | MLB012S4S-1P | MFMA012S4-*P | | 9,600 | $480 |
| No | 211034445 | LENNOX | MLB012S4S-1P | MMDB012S4-*P | | 10,600 | $530 |
| No | 211034444 | LENNOX | MLB009S4S-1P | MMDB009S4-*P | | 10,100 | $505 |
| No | 211034441 | LENNOX | MLB012S4S-1P | MWMC012S4-*P | | 10,000 | $500 |
| No | 211034440 | LENNOX | MLB009S4S-1P | MWMC009S4-*P | | 9,500 | $475 |
| No | 211034439 | LENNOX | MPC048S4S-1P | M33C048S4-*P | | 30,000 | $1,500 |
| No | 211034438 | LENNOX | MPC036S4S-1P | M33C036S4-*P | | 23,000 | $1,150 |
| No | 211034437 | LENNOX | MPC024S4S-1P | M33C024S4-*P | | 19,000 | $950 |
| No | 211034436 | LENNOX | MPC018S4S-1P | M22A018S4-*P | | 12,000 | $600 |
| No | 211034435 | LENNOX | MPC012S4S-1P | M22A012S4-*P | | 8,900 | $445 |
| No | 211034434 | LENNOX | MPC009S4S-1P | M22A009S4-*P | | 7,500 | $375 |
| No | 211034433 | LENNOX | MPC048S4S-1P | MCFA048S4-*P | | 29,000 | $1,450 |
| No | 211034432 | LENNOX | MPC036S4S-1P | MCFA036S4-*P | | 23,000 | $1,150 |
| No | 211034431 | LENNOX | MPC024S4S-1P | MCFA024S4-*P | | 16,000 | $800 |
| No | 211034430 | LENNOX | MPC018S4S-1P | MCFB018S4-*P | | 12,800 | $640 |
| No | 211034429 | LENNOX | MPC012S4S-1P | MFMA012S4-*P | | 9,000 | $450 |
| No | 211034428 | LENNOX | MPC048S4S-1P | MMDB048S4-*P | | 34,000 | $1,700 |
| No | 211034427 | LENNOX | MPC036S4S-1P | MMDB036S4-*P | | 25,000 | $1,250 |
| No | 211034426 | LENNOX | MPC024S4S-1P | MMDB024S4-*P | | 20,000 | $1,000 |
| No | 211034425 | LENNOX | MPC018S4S-1P | MMDB018S4-*P | | 12,600 | $630 |
| No | 211034424 | LENNOX | MPC012S4S-1P | MMDB012S4-*P | | 9,300 | $465 |
| No | 211034423 | LENNOX | MPC009S4S-1P | MMDB009S4-*P | | 7,700 | $385 |
| No | 211034420 | LENNOX | MPC030S4S-1P | MWMC030S4-*P | | 19,000 | $950 |
| No | 211034419 | LENNOX | MPC024S4S-1P | MWMC024S4-*P | | 16,200 | $810 |
| No | 211034418 | LENNOX | MPC018S4S-1P | MWMC018S4-*P | | 14,900 | $745 |
| No | 211034417 | LENNOX | MPC012S4S-1P | MWMC012S4-*P | | 9,000 | $450 |
| No | 211034416 | LENNOX | MPC009S4S-1P | MWMC009S4-*P | | 8,500 | $425 |
| No | 207683512 | LENNOX | MPC036S4S-1P | MCFA036S4-2P | | 23,000 | $1,150 |
| No | 207768724 | LENNOX | MPC036S4M-1P | Heat pump without ducts | | 26,800 | $1,340 |
| No | 207699110 | LENNOX | MPC030S4M-1P | Heat pump without ducts | | 21,000 | $1,050 |
| No | 207699111 | LENNOX | MPC030S4M-1P | Heat pump with ducts | | 22,000 | $1,100 |
| No | 207683500 | LENNOX | MPC024S4S-1P | MWMC024S4-1P | | 16,200 | $810 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207683511 | LENNOX | MPC024S4S-1P | MCFA024S4-2P | | 16,000 | $800 |
| No | 207699116 | LENNOX | MPC024S4M-1P | Heat pump without ducts | | 15,000 | $750 |
| No | 207699117 | LENNOX | MPC024S4M-1P | Heat pump with ducts | | 22,000 | $1,100 |
| No | 207683505 | LENNOX | MPC018S4S-1P | MMDB018S4-2P | | 12,600 | $630 |
| No | 207683510 | LENNOX | MPC018S4S-1P | MCFB018S4-2P | | 12,800 | $640 |
| No | 207683499 | LENNOX | MPC018S4S-1P | MWMC018S4-1P | | 14,900 | $745 |
| No | 207768722 | LENNOX | MPC018S4M-1P | Heat pump with ducts | | 14,800 | $740 |
| No | 207768721 | LENNOX | MPC018S4M-1P | Heat pump without ducts | | 14,300 | $715 |
| No | 207683498 | LENNOX | MPC012S4S-1P | MWMC012S4-1P | | 9,000 | $450 |
| No | 207683504 | LENNOX | MPC012S4S-1P | MMDB012S4-2P | | 9,300 | $465 |
| No | 207683509 | LENNOX | MPC012S4S-1P | MFMA012S4-1P | | 9,000 | $450 |
| No | 207683515 | LENNOX | MPC012S4S-1P | M22A012S4-2P | | 8,900 | $445 |
| No | 207683496 | LENNOX | MPC012S4S-1L | MWMC012S4-1L | | 8,400 | $420 |
| No | 207683497 | LENNOX | MPC009S4S-1P | MWMC009S4-1P | | 8,500 | $425 |
| No | 207683503 | LENNOX | MPC009S4S-1P | MMDB009S4-2P | | 7,700 | $385 |
| No | 207683514 | LENNOX | MPC009S4S-1P | M22A009S4-2P | | 7,500 | $375 |
| No | 10058829 | LENNOX | MPB048S4S-1P | MCFA048S4-1P | | 35,000 | $1,750 |
| No | 10058839 | LENNOX | MPB048S4S-1P | M33B048S4-1P | | 35,000 | $1,750 |
| No | 10528568 | LENNOX | MPB048S4S-1P | MMDB048S4-1P | | 34,000 | $1,700 |
| No | 10528567 | LENNOX | MPB036S4S-1P | MMDB036S4-1P | | 25,000 | $1,250 |
| No | 10062014 | LENNOX | MPB036S4M-1P | Heat pump without ducts | | 24,600 | $1,230 |
| No | 203343587 | LENNOX | MPB030S4M-2P | Heat pump without ducts | | 17,200 | $860 |
| No | 203343586 | LENNOX | MPB018S4M-2P | Heat pump without ducts | | 11,800 | $590 |
| No | 10062010 | LENNOX | MPB018S4M-1P | Heat pump without ducts | | 11,800 | $590 |
| No | 206188242 | LENNOX | MPB012S4S-1P | MFMA012S4-1P | | 7,200 | $360 |
| No | 10056169 | LENNOX | MPB009S4S-1P | MWMA009S4-1P | | 5,800 | $290 |
| No | 10056170 | LENNOX | MPB009S4S-1P | MWMA009S4-2P | | 5,800 | $290 |
| No | 201796630 | LENNOX | MPB009S4S-1P | MWMA009S4-3P | | 5,800 | $290 |
| No | 205782162 | LENNOX | MLB036S4S-1P | MCFA036S4-2P | | 25,000 | $1,250 |
| No | 207699105 | LENNOX | MLB036S4M-1P | Heat pump with ducts | | 35,000 | $1,750 |
| No | 207768730 | LENNOX | MLB030S4M-1P | Heat pump without ducts | | 26,600 | $1,330 |
| No | 207768731 | LENNOX | MLB030S4M-1P | Heat pump with ducts | | 27,000 | $1,350 |
| No | 207683525 | LENNOX | MLB012S4S-1P | MMDB012S4-2P | | 10,600 | $530 |
| No | 207683521 | LENNOX | MLB012S4S-1P | MWMC012S4-1P | | 10,000 | $500 |
| No | 207683532 | LENNOX | MLB012S4S-1P | M22A012S4-2P | | 9,900 | $495 |
| No | 207683524 | LENNOX | MLB009S4S-1P | MMDB009S4-2P | | 10,100 | $505 |
| No | 207683520 | LENNOX | MLB009S4S-1P | MWMC009S4-1P | | 9,500 | $475 |
| No | 207683531 | LENNOX | MLB009S4S-1P | M22A009S4-2P | | 9,000 | $450 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 9920047 | LENNOX | MLA024S4S-1P | MWMA024S4-2P | | 15,400 | $770 |
| No | 9920041 | LENNOX | MLA012S4S-1P | MWMA012S4-2P | | 7,800 | $390 |
| No | 201796633 | LENNOX | MLA012S4S-1P | MWMA012S4-3P | | 7,800 | $390 |
| No | 10528570 | LENNOX | MLA012S4S-1P | MMDB012S4-2P | | 10,600 | $530 |
| No | 201796632 | LENNOX | MLA009S4S-1P | MWMA009S4-3P | | 6,900 | $345 |
| No | 10528569 | LENNOX | MLA009S4S-1P | MMDB009S4-2P | | 10,100 | $505 |
| No | 208106646 | Lennox | MHB024S4S-1P | MWHB024S4-1P | | 16,500 | $825 |
| No | 208106645 | Lennox | MHB018S4S-1P | MWHB018S4-1P | | 11,400 | $570 |
| No | 208106644 | Lennox | MHB012S4S-1P | MWHB012S4-1P | | 7,000 | $350 |
| No | 208106642 | Lennox | MHB012S4S-1L | MWHB012S4-1L | | 7,800 | $390 |
| No | 208106643 | Lennox | MHB009S4S-1P | MWHB009S4-1P | | 6,000 | $300 |
| No | 208106641 | Lennox | MHB009S4S-1L | MWHB009S4-1L | | 6,300 | $315 |
| No | 204631576 | LENNOX | VPB048H4M-3P | Combination heat pumps with or without ducts | | 34,000 | $1,700 |
| No | 204631575 | LENNOX | VPB036H4M-3P | Combination heat pumps with or without ducts | | 28,000 | $1,400 |
| No | 204631572 | LENNOX | VPB048H4M-3P | Heat pump without ducts | | 34,000 | $1,700 |
| No | 204631571 | LENNOX | VPB048H4M-3P | Heat pump with ducts | | 34,000 | $1,700 |
| No | 211467879 | LENNOX | EL22XPV-036-230A** | CR33-48B*+TDR+TXV | SLP99DF070XV36B* | 21,800 | $1,090 |
| No | 211467878 | LENNOX | EL22XPV-036-230A** | CR33-48B*+TDR+TXV | SL280DF090V48B* | 21,800 | $1,090 |
| No | 211467877 | LENNOX | EL22XPV-036-230A** | CR33-48B*+TDR+TXV | ML296DF070XV48B* | 22,000 | $1,100 |
| No | 211467876 | LENNOX | EL22XPV-036-230A** | CR33-48B*+TDR+TXV | ML296DF045XV36B* | 22,000 | $1,100 |
| No | 211467875 | LENNOX | EL22XPV-036-230A** | CR33-48B*+TDR+TXV | ML196DF070XE48B* | 21,800 | $1,090 |
| No | 211467874 | LENNOX | EL22XPV-036-230A** | CR33-48B*+TDR+TXV | ML196DF045XE36B* | 21,600 | $1,080 |
| No | 211467873 | LENNOX | EL22XPV-036-230A** | CR33-48B*+TDR+TXV | ML193DF070XE36B* | 21,600 | $1,080 |
| No | 211467872 | LENNOX | EL22XPV-036-230A** | CR33-48B*+TDR+TXV | ML193DF045XE36B* | 21,800 | $1,090 |
| No | 211467871 | LENNOX | EL22XPV-036-230A** | CR33-48B*+TDR+TXV | ML180DF090E48B* | 21,400 | $1,070 |
| No | 211467870 | LENNOX | EL22XPV-036-230A** | CR33-48B*+TDR+TXV | ML180DF070E36B* | 21,600 | $1,080 |
| No | 211467869 | LENNOX | EL22XPV-036-230A** | CR33-48B*+TDR+TXV | EL296DF070XV48B* | 22,000 | $1,100 |
| No | 211467868 | LENNOX | EL22XPV-036-230A** | CR33-48B*+TDR+TXV | EL296DF070XE48B* | 21,800 | $1,090 |
| No | 211467867 | LENNOX | EL22XPV-036-230A** | CR33-48B*+TDR+TXV | EL296DF045XV36B* | 22,000 | $1,100 |
| No | 211467866 | LENNOX | EL22XPV-036-230A** | CR33-48B*+TDR+TXV | EL280DF090E48B* | 21,600 | $1,080 |
| No | 211799261 | LENNOX | EL22XPV-036-230A** | CX35-48C+TDR | SLP99UH110XV60C* | 22,400 | $1,120 |
| No | 211799259 | LENNOX | EL22XPV-036-230A** | CX35-48C+TDR | SLP99UH090XV48C* | 22,400 | $1,120 |
| No | 211799258 | LENNOX | EL22XPV-036-230A** | CX35-48C+TDR | SLP99UH090XV36C* | 22,400 | $1,120 |
| No | 211799256 | LENNOX | EL22XPV-036-230A** | CX35-48C+TDR | SL297UH080NV48C* | 22,400 | $1,120 |
| No | 211799248 | LENNOX | EL22XPV-036-230A** | CX35-48C+TDR | EL296UH110XV48C* | 22,400 | $1,120 |
| No | 211799245 | LENNOX | EL22XPV-036-230A** | CX35-48C+TDR | EL296UH090XV48C* | 22,400 | $1,120 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211799244 | LENNOX | EL22XPV-036-230A** | CX35-48C+TDR | EL296UH090XV36C* | 22,400 | $1,120 |
| No | 211799238 | LENNOX | EL22XPV-036-230A** | C35-48C+TDR+TXV | SLP99UH110XV60C* | 22,400 | $1,120 |
| No | 211799236 | LENNOX | EL22XPV-036-230A** | C35-48C+TDR+TXV | SLP99UH090XV48C* | 22,400 | $1,120 |
| No | 211799235 | LENNOX | EL22XPV-036-230A** | C35-48C+TDR+TXV | SLP99UH090XV36C* | 22,400 | $1,120 |
| No | 211799233 | LENNOX | EL22XPV-036-230A** | C35-48C+TDR+TXV | SL297UH080NV48C* | 22,400 | $1,120 |
| No | 211799225 | LENNOX | EL22XPV-036-230A** | C35-48C+TDR+TXV | EL296UH110XV48C* | 22,400 | $1,120 |
| No | 211799222 | LENNOX | EL22XPV-036-230A** | C35-48C+TDR+TXV | EL296UH090XV48C* | 22,400 | $1,120 |
| No | 211799221 | LENNOX | EL22XPV-036-230A** | C35-48C+TDR+TXV | EL296UH090XV36C* | 22,400 | $1,120 |
| No | 211841350 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | SLP99UH070XV36B* | 14,300 | $715 |
| No | 211841349 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | SL297UH060NV36B* | 14,400 | $720 |
| No | 211841348 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | SL297UH040NV36B* | 14,400 | $720 |
| No | 211841347 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | SL280UH090XV48B* | 14,300 | $715 |
| No | 211841346 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | SL280UH090V48B* | 14,300 | $715 |
| No | 211841345 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | SL280UH090V36B* | 14,300 | $715 |
| No | 211841344 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | SL280UH080NV48B* | 14,400 | $720 |
| No | 211841343 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | SL280DF060NV36B* | 14,400 | $720 |
| No | 211841342 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | ML296UH070XV36B* | 14,400 | $720 |
| No | 211841341 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | ML296UH045XV36B* | 14,200 | $710 |
| No | 211841340 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | ML196UH070XE48B* | 14,700 | $735 |
| No | 211841339 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | ML196UH070XE36B* | 14,500 | $725 |
| No | 211841338 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | ML196UH045XE36B* | 14,500 | $725 |
| No | 211841337 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | ML196UH030XE36B* | 14,500 | $725 |
| No | 211841336 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | ML193UH070XE36B* | 14,400 | $720 |
| No | 211841335 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | ML193UH045XE36B* | 14,500 | $725 |
| No | 211841334 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | ML193UH030XE36B* | 14,500 | $725 |
| No | 211841333 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | ML180UH090XE48B* | 14,500 | $725 |
| No | 211841332 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | ML180UH090V48B* | 14,400 | $720 |
| No | 211841331 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | ML180UH090E48B* | 14,500 | $725 |
| No | 211841330 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | ML180UH070XE36B* | 14,200 | $710 |
| No | 211841329 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | ML180UH070V48B* | 14,200 | $710 |
| No | 211841328 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | ML180UH070V36B* | 14,100 | $705 |
| No | 211841327 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | ML180UH070E36B* | 14,200 | $710 |
| No | 211841326 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | EL296UH070XV36B* | 14,400 | $720 |
| No | 211841325 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | EL296UH070XE36B* | 14,500 | $725 |
| No | 211841324 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | EL296UH045XV36B* | 14,400 | $720 |
| No | 211841323 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | EL296UH045XE36B* | 14,500 | $725 |
| No | 211841322 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | EL280UH090XE48B* | 14,500 | $725 |
| No | 211841321 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | EL280UH090E48B* | 14,500 | $725 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211841320 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | EL280UH090E36B* | 14,400 | $720 |
| No | 211841319 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | EL196UH070XE36B* | 14,500 | $725 |
| No | 211841318 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | EL196UH045XE36B* | 14,500 | $725 |
| No | 211841317 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | EL196UH030XE36B* | 14,500 | $725 |
| No | 211841316 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | EL195UH060NE36B* | 14,500 | $725 |
| No | 211841315 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | EL195UH040NE36B* | 14,500 | $725 |
| No | 211841314 | LENNOX | EL22XPV-024-230A** | CHX35-30B-**-*+TDR | EL180UH080NE48B* | 14,700 | $735 |
| No | 211841313 | LENNOX | EL22XPV-024-230A** | CHX35-30A-**-*+TDR | SL280UH070XV36A* | 14,300 | $715 |
| No | 211841312 | LENNOX | EL22XPV-024-230A** | CHX35-30A-**-*+TDR | SL280UH070V36A* | 14,300 | $715 |
| No | 211841311 | LENNOX | EL22XPV-024-230A** | CHX35-30A-**-*+TDR | SL280UH060NV36A* | 14,300 | $715 |
| No | 211841310 | LENNOX | EL22XPV-024-230A** | CHX35-30A-**-*+TDR | ML180UH070XE36A* | 14,000 | $700 |
| No | 211841309 | LENNOX | EL22XPV-024-230A** | CHX35-30A-**-*+TDR | ML180UH070V36A* | 14,300 | $715 |
| No | 211841308 | LENNOX | EL22XPV-024-230A** | CHX35-30A-**-*+TDR | ML180UH070E36A* | 14,000 | $700 |
| No | 211841307 | LENNOX | EL22XPV-024-230A** | CHX35-30A-**-*+TDR | ML180UH045XE36A* | 14,300 | $715 |
| No | 211841306 | LENNOX | EL22XPV-024-230A** | CHX35-30A-**-*+TDR | ML180UH045V36A* | 13,900 | $695 |
| No | 211841305 | LENNOX | EL22XPV-024-230A** | CHX35-30A-**-*+TDR | ML180UH045E36A* | 14,300 | $715 |
| No | 211841304 | LENNOX | EL22XPV-024-230A** | CHX35-30A-**-*+TDR | ML180UH030V36A* | 13,900 | $695 |
| No | 211841303 | LENNOX | EL22XPV-024-230A** | CHX35-30A-**-*+TDR | EL280UH070XE36A* | 14,300 | $715 |
| No | 211841302 | LENNOX | EL22XPV-024-230A** | CHX35-30A-**-*+TDR | EL280UH070E36A* | 14,300 | $715 |
| No | 211841301 | LENNOX | EL22XPV-024-230A** | CHX35-30A-**-*+TDR | EL280UH045E36A* | 13,900 | $695 |
| No | 211841300 | LENNOX | EL22XPV-024-230A** | CHX35-30A-**-*+TDR | EL180UH060NE36A* | 14,200 | $710 |
| No | 211841299 | LENNOX | EL22XPV-024-230A** | CHX35-30A-**-*+TDR | EL180UH040NE36A* | 14,200 | $710 |
| No | 211694794 | LENNOX | EL22XPV-024-230A** | CR33-24B+TDR+TXV | SLP99DF070XV36B* | 15,000 | $750 |
| No | 211694793 | LENNOX | EL22XPV-024-230A** | CR33-24B+TDR+TXV | SL280DF090V48B* | 15,100 | $755 |
| No | 211694792 | LENNOX | EL22XPV-024-230A** | CR33-24B+TDR+TXV | ML296DF045XV36B* | 15,000 | $750 |
| No | 211694791 | LENNOX | EL22XPV-024-230A** | CR33-24B+TDR+TXV | ML196DF070XE48B* | 15,000 | $750 |
| No | 211694790 | LENNOX | EL22XPV-024-230A** | CR33-24B+TDR+TXV | ML196DF045XE36B* | 15,000 | $750 |
| No | 211694789 | LENNOX | EL22XPV-024-230A** | CR33-24B+TDR+TXV | ML193DF070XE36B* | 14,900 | $745 |
| No | 211694788 | LENNOX | EL22XPV-024-230A** | CR33-24B+TDR+TXV | ML193DF045XE36B* | 14,900 | $745 |
| No | 211694787 | LENNOX | EL22XPV-024-230A** | CR33-24B+TDR+TXV | ML180DF090E48B* | 15,100 | $755 |
| No | 211694786 | LENNOX | EL22XPV-024-230A** | CR33-24B+TDR+TXV | ML180DF070E36B* | 15,000 | $750 |
| No | 211694785 | LENNOX | EL22XPV-024-230A** | CR33-24B+TDR+TXV | EL296DF070XV48B* | 15,200 | $760 |
| No | 211694784 | LENNOX | EL22XPV-024-230A** | CR33-24B+TDR+TXV | EL296DF070XE48B* | 14,900 | $745 |
| No | 211694783 | LENNOX | EL22XPV-024-230A** | CR33-24B+TDR+TXV | EL296DF045XV36B* | 15,000 | $750 |
| No | 211694782 | LENNOX | EL22XPV-024-230A** | CR33-24B+TDR+TXV | EL296DF045XE36B* | 14,900 | $745 |
| No | 211694781 | LENNOX | EL22XPV-024-230A** | CR33-24B+TDR+TXV | EL280DF090E48B* | 15,000 | $750 |
| No | 211694780 | LENNOX | EL22XPV-024-230A** | CR33-24A+TDR+TXV | SL280DF070V36A* | 15,000 | $750 |
| No | 211694779 | LENNOX | EL22XPV-024-230A** | CR33-24A+TDR+TXV | ML180DF070E36A* | 14,900 | $745 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211694778 | LENNOX | EL22XPV-024-230A** | CR33-24A+TDR+TXV | ML180DF045E36A* | 14,900 | $745 |
| No | 211694777 | LENNOX | EL22XPV-024-230A** | CR33-24A+TDR+TXV | EL280DF070E36A* | 15,000 | $750 |
| No | 211694846 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | SLP99UH070XV36B* | 14,700 | $735 |
| No | 211694845 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | SL297UH060NV36B* | 14,700 | $735 |
| No | 211694844 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | SL297UH040NV36B* | 14,700 | $735 |
| No | 211694843 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | SL280UH090XV48B* | 14,600 | $730 |
| No | 211694842 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | SL280UH090V48B* | 14,600 | $730 |
| No | 211694841 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | SL280UH090V36B* | 14,600 | $730 |
| No | 211694840 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | SL280UH080NV48B* | 14,800 | $740 |
| No | 211694839 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | SL280DF060NV36B* | 14,700 | $735 |
| No | 211694838 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | ML296UH070XV36B* | 14,700 | $735 |
| No | 211694837 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | ML296UH045XV36B* | 14,600 | $730 |
| No | 211694836 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | ML196UH070XE48B* | 15,000 | $750 |
| No | 211694835 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | ML196UH070XE36B* | 14,800 | $740 |
| No | 211694834 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | ML196UH045XE36B* | 14,800 | $740 |
| No | 211694833 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | ML196UH030XE36B* | 14,800 | $740 |
| No | 211694832 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | ML193UH070XE36B* | 14,700 | $735 |
| No | 211694831 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | ML193UH045XE36B* | 14,800 | $740 |
| No | 211694830 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | ML193UH030XE36B* | 14,800 | $740 |
| No | 211694829 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | ML180UH090XE48B* | 14,800 | $740 |
| No | 211694828 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | ML180UH090V48B* | 14,700 | $735 |
| No | 211694827 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | ML180UH090E48B* | 14,800 | $740 |
| No | 211694826 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | ML180UH070XE36B* | 14,500 | $725 |
| No | 211694825 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | ML180UH070V48B* | 14,500 | $725 |
| No | 211694824 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | ML180UH070V36B* | 14,500 | $725 |
| No | 211694823 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | ML180UH070E36B* | 14,500 | $725 |
| No | 211694822 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | EL296UH070XV36B* | 14,700 | $735 |
| No | 211694821 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | EL296UH070XE36B* | 14,800 | $740 |
| No | 211694820 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | EL296UH045XV36B* | 14,800 | $740 |
| No | 211694819 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | EL296UH045XE36B* | 14,800 | $740 |
| No | 211694818 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | EL280UH090XE48B* | 14,800 | $740 |
| No | 211694817 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | EL280UH090E48B* | 14,800 | $740 |
| No | 211694816 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | EL280UH090E36B* | 14,700 | $735 |
| No | 211694815 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | EL196UH070XE36B* | 14,800 | $740 |
| No | 211694814 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | EL196UH045XE36B* | 14,800 | $740 |
| No | 211694813 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | EL196UH030XE36B* | 14,800 | $740 |
| No | 211694812 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | EL195UH060NE36B* | 14,800 | $740 |
| No | 211694811 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | EL195UH040NE36B* | 14,800 | $740 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211694810 | LENNOX | EL22XPV-024-230A** | CX35-24B+TDR | EL180UH080NE48B* | 15,000 | $750 |
| No | 211694715 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | SLP99UH070XV36B* | 14,700 | $735 |
| No | 211694714 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | SL297UH060NV36B* | 14,700 | $735 |
| No | 211694713 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | SL297UH040NV36B* | 14,700 | $735 |
| No | 211694712 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | SL280UH090XV48B* | 14,600 | $730 |
| No | 211694711 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | SL280UH090V48B* | 14,600 | $730 |
| No | 211694710 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | SL280UH090V36B* | 14,600 | $730 |
| No | 211694709 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | SL280UH080NV48B* | 14,800 | $740 |
| No | 211694708 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | SL280DF060NV36B* | 14,700 | $735 |
| No | 211694707 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | ML296UH070XV36B* | 14,700 | $735 |
| No | 211694706 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | ML296UH045XV36B* | 14,600 | $730 |
| No | 211694705 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | ML196UH070XE48B* | 15,000 | $750 |
| No | 211694704 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | ML196UH070XE36B* | 14,800 | $740 |
| No | 211694703 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | ML196UH045XE36B* | 14,800 | $740 |
| No | 211694702 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | ML196UH030XE36B* | 14,800 | $740 |
| No | 211694701 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | ML193UH070XE36B* | 14,700 | $735 |
| No | 211694700 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | ML193UH045XE36B* | 14,800 | $740 |
| No | 211694699 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | ML193UH030XE36B* | 14,800 | $740 |
| No | 211694698 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | ML180UH090XE48B* | 14,800 | $740 |
| No | 211694697 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | ML180UH090V48B* | 14,700 | $735 |
| No | 211694696 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | ML180UH090E48B* | 14,800 | $740 |
| No | 211694695 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | ML180UH070XE36B* | 14,500 | $725 |
| No | 211694694 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | ML180UH070V48B* | 14,500 | $725 |
| No | 211694693 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | ML180UH070V36B* | 14,500 | $725 |
| No | 211694692 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | ML180UH070E36B* | 14,500 | $725 |
| No | 211694691 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | EL296UH070XV36B* | 14,700 | $735 |
| No | 211694690 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | EL296UH070XE36B* | 14,800 | $740 |
| No | 211694689 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | EL296UH045XV36B* | 14,800 | $740 |
| No | 211694688 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | EL296UH045XE36B* | 14,800 | $740 |
| No | 211694687 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | EL280UH090XE48B* | 14,800 | $740 |
| No | 211694686 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | EL280UH090E48B* | 14,800 | $740 |
| No | 211694685 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | EL280UH090E36B* | 14,700 | $735 |
| No | 211694684 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | EL196UH070XE36B* | 14,800 | $740 |
| No | 211694683 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | EL196UH045XE36B* | 14,800 | $740 |
| No | 211694682 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | EL196UH030XE36B* | 14,800 | $740 |
| No | 211694681 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | EL195UH060NE36B* | 14,800 | $740 |
| No | 211694680 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | EL195UH040NE36B* | 14,800 | $740 |
| No | 211694679 | LENNOX | EL22XPV-024-230A** | C35-24B+TDR+TXV | EL180UH080NE48B* | 15,000 | $750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211694809 | LENNOX | EL22XPV-024-230A** | CX35-24A+TDR | SL280UH070XV36A* | 14,700 | $735 |
| No | 211694808 | LENNOX | EL22XPV-024-230A** | CX35-24A+TDR | SL280UH070V36A* | 14,700 | $735 |
| No | 211694807 | LENNOX | EL22XPV-024-230A** | CX35-24A+TDR | SL280UH060NV36A* | 14,700 | $735 |
| No | 211694806 | LENNOX | EL22XPV-024-230A** | CX35-24A+TDR | ML180UH070XE36A* | 14,500 | $725 |
| No | 211694805 | LENNOX | EL22XPV-024-230A** | CX35-24A+TDR | ML180UH070V36A* | 14,400 | $720 |
| No | 211694804 | LENNOX | EL22XPV-024-230A** | CX35-24A+TDR | ML180UH070E36A* | 14,500 | $725 |
| No | 211694803 | LENNOX | EL22XPV-024-230A** | CX35-24A+TDR | ML180UH045XE36A* | 14,200 | $710 |
| No | 211694802 | LENNOX | EL22XPV-024-230A** | CX35-24A+TDR | ML180UH045V36A* | 14,300 | $715 |
| No | 211694801 | LENNOX | EL22XPV-024-230A** | CX35-24A+TDR | ML180UH045E36A* | 14,200 | $710 |
| No | 211694800 | LENNOX | EL22XPV-024-230A** | CX35-24A+TDR | ML180UH030V36A* | 14,300 | $715 |
| No | 211694799 | LENNOX | EL22XPV-024-230A** | CX35-24A+TDR | EL280UH070XE36A* | 14,700 | $735 |
| No | 211694798 | LENNOX | EL22XPV-024-230A** | CX35-24A+TDR | EL280UH070E36A* | 14,700 | $735 |
| No | 211694797 | LENNOX | EL22XPV-024-230A** | CX35-24A+TDR | EL280UH045E36A* | 14,300 | $715 |
| No | 211694796 | LENNOX | EL22XPV-024-230A** | CX35-24A+TDR | EL180UH060NE36A* | 14,700 | $735 |
| No | 211694795 | LENNOX | EL22XPV-024-230A** | CX35-24A+TDR | EL180UH040NE36A* | 14,700 | $735 |
| No | 211694678 | LENNOX | EL22XPV-024-230A** | C35-24A+TDR+TXV | SL280UH070XV36A* | 14,700 | $735 |
| No | 211694677 | LENNOX | EL22XPV-024-230A** | C35-24A+TDR+TXV | SL280UH070V36A* | 14,700 | $735 |
| No | 211694676 | LENNOX | EL22XPV-024-230A** | C35-24A+TDR+TXV | SL280UH060NV36A* | 14,700 | $735 |
| No | 211694675 | LENNOX | EL22XPV-024-230A** | C35-24A+TDR+TXV | ML180UH070XE36A* | 14,500 | $725 |
| No | 211694674 | LENNOX | EL22XPV-024-230A** | C35-24A+TDR+TXV | ML180UH070V36A* | 14,400 | $720 |
| No | 211694673 | LENNOX | EL22XPV-024-230A** | C35-24A+TDR+TXV | ML180UH070E36A* | 14,500 | $725 |
| No | 211694672 | LENNOX | EL22XPV-024-230A** | C35-24A+TDR+TXV | ML180UH045XE36A* | 14,200 | $710 |
| No | 211694671 | LENNOX | EL22XPV-024-230A** | C35-24A+TDR+TXV | ML180UH045V36A* | 14,300 | $715 |
| No | 211694670 | LENNOX | EL22XPV-024-230A** | C35-24A+TDR+TXV | ML180UH045E36A* | 14,200 | $710 |
| No | 211694669 | LENNOX | EL22XPV-024-230A** | C35-24A+TDR+TXV | ML180UH030V36A* | 14,300 | $715 |
| No | 211694668 | LENNOX | EL22XPV-024-230A** | C35-24A+TDR+TXV | EL280UH070XE36A* | 14,700 | $735 |
| No | 211694667 | LENNOX | EL22XPV-024-230A** | C35-24A+TDR+TXV | EL280UH070E36A* | 14,700 | $735 |
| No | 211694666 | LENNOX | EL22XPV-024-230A** | C35-24A+TDR+TXV | EL280UH045E36A* | 14,300 | $715 |
| No | 211694665 | LENNOX | EL22XPV-024-230A** | C35-24A+TDR+TXV | EL180UH060NE36A* | 14,700 | $735 |
| No | 211694664 | LENNOX | EL22XPV-024-230A** | C35-24A+TDR+TXV | EL180UH040NE36A* | 14,700 | $735 |
| No | 211694883 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | SLP99DF070XV36B* | 14,200 | $710 |
| No | 211694884 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | SLP99UH070XV36B* | 14,200 | $710 |
| No | 211694882 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | SL297UH060NV36B* | 14,200 | $710 |
| No | 211694881 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | SL297UH040NV36B* | 14,200 | $710 |
| No | 211694880 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | SL280UH090XV48B* | 14,100 | $705 |
| No | 211694879 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | SL280UH090V48B* | 14,100 | $705 |
| No | 211694878 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | SL280UH090V36B* | 14,100 | $705 |
| No | 211694877 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | SL280UH080NV48B* | 14,300 | $715 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211694876 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | SL280DF060NV36B* | 14,200 | $710 |
| No | 211694875 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | ML296UH070XV36B* | 14,200 | $710 |
| No | 211694874 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | ML296UH045XV36B* | 14,100 | $705 |
| No | 211694873 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | ML196UH070XE48B* | 14,600 | $730 |
| No | 211694872 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | ML196UH070XE36B* | 14,400 | $720 |
| No | 211694871 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | ML196UH045XE36B* | 14,400 | $720 |
| No | 211694870 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | ML196UH030XE36B* | 13,900 | $695 |
| No | 211694869 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | ML193UH070XE36B* | 14,200 | $710 |
| No | 211694868 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | ML193UH045XE36B* | 14,300 | $715 |
| No | 211694867 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | ML193UH030XE36B* | 13,800 | $690 |
| No | 211694866 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | ML180UH090XE48B* | 14,400 | $720 |
| No | 211694865 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | ML180UH090V48B* | 14,200 | $710 |
| No | 211694864 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | ML180UH090E48B* | 14,400 | $720 |
| No | 211694863 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | ML180UH070XE36B* | 14,000 | $700 |
| No | 211694862 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | ML180UH070V48B* | 14,100 | $705 |
| No | 211694861 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | ML180UH070V36B* | 14,000 | $700 |
| No | 211694860 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | ML180UH070E36B* | 14,000 | $700 |
| No | 211694859 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | EL296UH070XV36B* | 14,200 | $710 |
| No | 211694858 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | EL296UH070XE36B* | 14,300 | $715 |
| No | 211694857 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | EL296UH045XV36B* | 14,300 | $715 |
| No | 211694856 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | EL296UH045XE36B* | 14,300 | $715 |
| No | 211694855 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | EL280UH090XE48B* | 14,400 | $720 |
| No | 211694854 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | EL280UH090E48B* | 14,400 | $720 |
| No | 211694853 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | EL280UH090E36B* | 14,300 | $715 |
| No | 211694852 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | EL196UH070XE36B* | 14,400 | $720 |
| No | 211694851 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | EL196UH045XE36B* | 14,400 | $720 |
| No | 211694850 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | EL196UH030XE36B* | 13,900 | $695 |
| No | 211694849 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | EL195UH060NE36B* | 14,400 | $720 |
| No | 211694848 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | EL195UH040NE36B* | 14,400 | $720 |
| No | 211694847 | LENNOX | EL22XPV-024-230A** | CX35-30B+TDR | EL180UH080NE48B* | 14,500 | $725 |
| No | 211694767 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | SLP99DF070XV36B* | 14,200 | $710 |
| No | 211694768 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | SLP99UH070XV36B* | 14,200 | $710 |
| No | 211694766 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | SL297UH060NV36B* | 14,200 | $710 |
| No | 211694765 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | SL297UH040NV36B* | 14,200 | $710 |
| No | 211694764 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | SL280UH090XV48B* | 14,100 | $705 |
| No | 211694763 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | SL280UH090V48B* | 14,100 | $705 |
| No | 211694762 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | SL280UH090V36B* | 14,100 | $705 |
| No | 211694761 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | SL280UH080NV48B* | 14,300 | $715 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211694760 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | SL280DF060NV36B* | 14,200 | $710 |
| No | 211694759 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | ML296UH070XV36B* | 14,200 | $710 |
| No | 211694758 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | ML296UH045XV36B* | 14,100 | $705 |
| No | 211694757 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | ML196UH070XE48B* | 14,600 | $730 |
| No | 211694756 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | ML196UH070XE36B* | 14,400 | $720 |
| No | 211694755 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | ML196UH045XE36B* | 14,400 | $720 |
| No | 211694754 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | ML196UH030XE36B* | 13,900 | $695 |
| No | 211694753 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | ML193UH070XE36B* | 14,200 | $710 |
| No | 211694752 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | ML193UH045XE36B* | 14,300 | $715 |
| No | 211694751 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | ML193UH030XE36B* | 13,800 | $690 |
| No | 211694750 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | ML180UH090XE48B* | 14,400 | $720 |
| No | 211694749 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | ML180UH090V48B* | 14,200 | $710 |
| No | 211694748 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | ML180UH090E48B* | 14,400 | $720 |
| No | 211694747 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | ML180UH070XE36B* | 14,000 | $700 |
| No | 211694746 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | ML180UH070V48B* | 14,100 | $705 |
| No | 211694745 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | ML180UH070V36B* | 14,000 | $700 |
| No | 211694744 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | ML180UH070E36B* | 14,000 | $700 |
| No | 211694743 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | EL296UH070XV36B* | 14,200 | $710 |
| No | 211694742 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | EL296UH070XE36B* | 14,300 | $715 |
| No | 211694741 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | EL296UH045XV36B* | 14,300 | $715 |
| No | 211694740 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | EL296UH045XE36B* | 14,300 | $715 |
| No | 211694739 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | EL280UH090XE48B* | 14,400 | $720 |
| No | 211694738 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | EL280UH090E48B* | 14,400 | $720 |
| No | 211694737 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | EL280UH090E36B* | 14,300 | $715 |
| No | 211694736 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | EL196UH070XE36B* | 14,400 | $720 |
| No | 211694735 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | EL196UH045XE36B* | 14,400 | $720 |
| No | 211694734 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | EL196UH030XE36B* | 13,900 | $695 |
| No | 211694733 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | EL195UH060NE36B* | 14,400 | $720 |
| No | 211694732 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | EL195UH040NE36B* | 14,400 | $720 |
| No | 211694731 | LENNOX | EL22XPV-024-230A** | C35-30B+TDR+TXV | EL180UH080NE48B* | 14,500 | $725 |
| No | 211694899 | LENNOX | EL22XPV-024-230A** | CX35-30A+TDR | SL280UH070XV36A* | 14,200 | $710 |
| No | 211694898 | LENNOX | EL22XPV-024-230A** | CX35-30A+TDR | SL280UH070V36A* | 14,200 | $710 |
| No | 211694897 | LENNOX | EL22XPV-024-230A** | CX35-30A+TDR | SL280UH060NV36A* | 14,200 | $710 |
| No | 211694896 | LENNOX | EL22XPV-024-230A** | CX35-30A+TDR | ML180UH070XE36A* | 14,000 | $700 |
| No | 211694895 | LENNOX | EL22XPV-024-230A** | CX35-30A+TDR | ML180UH070V36A* | 14,000 | $700 |
| No | 211694894 | LENNOX | EL22XPV-024-230A** | CX35-30A+TDR | ML180UH070E36A* | 14,000 | $700 |
| No | 211694893 | LENNOX | EL22XPV-024-230A** | CX35-30A+TDR | ML180UH045XE36A* | 14,200 | $710 |
| No | 211694892 | LENNOX | EL22XPV-024-230A** | CX35-30A+TDR | ML180UH045V36A* | 13,900 | $695 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211694891 | LENNOX | EL22XPV-024-230A** | CX35-30A+TDR | ML180UH045E36A* | 14,200 | $710 |
| No | 211694890 | LENNOX | EL22XPV-024-230A** | CX35-30A+TDR | ML180UH030V36A* | 13,900 | $695 |
| No | 211694889 | LENNOX | EL22XPV-024-230A** | CX35-30A+TDR | EL280UH070XE36A* | 14,300 | $715 |
| No | 211694888 | LENNOX | EL22XPV-024-230A** | CX35-30A+TDR | EL280UH070E36A* | 14,300 | $715 |
| No | 211694887 | LENNOX | EL22XPV-024-230A** | CX35-30A+TDR | EL280UH045E36A* | 13,900 | $695 |
| No | 211694886 | LENNOX | EL22XPV-024-230A** | CX35-30A+TDR | EL180UH060NE36A* | 14,200 | $710 |
| No | 211694885 | LENNOX | EL22XPV-024-230A** | CX35-30A+TDR | EL180UH040NE36A* | 14,200 | $710 |
| No | 211694730 | LENNOX | EL22XPV-024-230A** | C35-30A+TDR+TXV | SL280UH070XV36A* | 14,200 | $710 |
| No | 211694729 | LENNOX | EL22XPV-024-230A** | C35-30A+TDR+TXV | SL280UH070V36A* | 14,200 | $710 |
| No | 211694728 | LENNOX | EL22XPV-024-230A** | C35-30A+TDR+TXV | SL280UH060NV36A* | 14,200 | $710 |
| No | 211694727 | LENNOX | EL22XPV-024-230A** | C35-30A+TDR+TXV | ML180UH070XE36A* | 14,000 | $700 |
| No | 211694726 | LENNOX | EL22XPV-024-230A** | C35-30A+TDR+TXV | ML180UH070V36A* | 14,000 | $700 |
| No | 211694725 | LENNOX | EL22XPV-024-230A** | C35-30A+TDR+TXV | ML180UH070E36A* | 14,000 | $700 |
| No | 211694724 | LENNOX | EL22XPV-024-230A** | C35-30A+TDR+TXV | ML180UH045XE36A* | 14,200 | $710 |
| No | 211694723 | LENNOX | EL22XPV-024-230A** | C35-30A+TDR+TXV | ML180UH045V36A* | 13,900 | $695 |
| No | 211694722 | LENNOX | EL22XPV-024-230A** | C35-30A+TDR+TXV | ML180UH045E36A* | 14,200 | $710 |
| No | 211694721 | LENNOX | EL22XPV-024-230A** | C35-30A+TDR+TXV | ML180UH030V36A* | 13,900 | $695 |
| No | 211694720 | LENNOX | EL22XPV-024-230A** | C35-30A+TDR+TXV | EL280UH070XE36A* | 14,300 | $715 |
| No | 211694719 | LENNOX | EL22XPV-024-230A** | C35-30A+TDR+TXV | EL280UH070E36A* | 14,300 | $715 |
| No | 211694718 | LENNOX | EL22XPV-024-230A** | C35-30A+TDR+TXV | EL280UH045E36A* | 13,900 | $695 |
| No | 211694717 | LENNOX | EL22XPV-024-230A** | C35-30A+TDR+TXV | EL180UH060NE36A* | 14,200 | $710 |
| No | 211694716 | LENNOX | EL22XPV-024-230A** | C35-30A+TDR+TXV | EL180UH040NE36A* | 14,200 | $710 |
| No | 211694770 | LENNOX | EL22XPV-024-230A** | CBA25UH-030-230-** | | 14,900 | $745 |
| No | 211694772 | LENNOX | EL22XPV-024-230A** | CBA25UHV-030-230-** | | 14,500 | $725 |
| No | 211694769 | LENNOX | EL22XPV-024-230A** | CBA25UH-024-230-** | | 14,700 | $735 |
| No | 211694771 | LENNOX | EL22XPV-024-230A** | CBA25UHV-024-230-** | | 14,900 | $745 |
| No | 211694773 | LENNOX | EL22XPV-024-230A** | CBA27UHE-018-230*+TDR | | 14,100 | $705 |
| No | 211694774 | LENNOX | EL22XPV-024-230A** | CBA27UHE-024-230*+TDR | | 14,500 | $725 |
| No | 211694776 | LENNOX | EL22XPV-024-230A** | CBA38MV-018/024-230*+TDR | | 14,400 | $720 |
| No | 211752874 | LENNOX | EL22XPV-060-230A** | C35-50/60C+TDR+TXV | SLP99UH110XV60C* | 38,000 | $1,900 |
| No | 211752932 | LENNOX | EL22XPV-060-230A** | C35-50/60C+TDR+TXV | SLP99UH090XV60C* | 38,000 | $1,900 |
| No | 211752931 | LENNOX | EL22XPV-060-230A** | C35-50/60C+TDR+TXV | SLP99UH090XV48C* | 38,500 | $1,925 |
| No | 211752873 | LENNOX | EL22XPV-060-230A** | C35-50/60C+TDR+TXV | SL280UH110XV60C* | 37,800 | $1,890 |
| No | 211752872 | LENNOX | EL22XPV-060-230A** | C35-50/60C+TDR+TXV | SL280UH110V60C* | 37,800 | $1,890 |
| No | 211752870 | LENNOX | EL22XPV-060-230A** | C35-50/60C+TDR+TXV | SL280UH090XV60C* | 37,800 | $1,890 |
| No | 211752869 | LENNOX | EL22XPV-060-230A** | C35-50/60C+TDR+TXV | SL280UH090V60C* | 37,800 | $1,890 |
| No | 211752865 | LENNOX | EL22XPV-060-230A** | C35-50/60C+TDR+TXV | EL296UH110XV60C* | 38,000 | $1,900 |
| No | 211752921 | LENNOX | EL22XPV-060-230A** | C35-50/60C+TDR+TXV | EL296UH090XV60C* | 38,000 | $1,900 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211752920 | LENNOX | EL22XPV-060-230A** | C35-50/60C+TDR+TXV | EL296UH090XV48C* | 38,500 | $1,925 |
| No | 211752930 | LENNOX | EL22XPV-060-230A** | C35-50/60C+TDR+TXV | SL297UH080NV60C* | 38,000 | $1,900 |
| No | 211752871 | LENNOX | EL22XPV-060-230A** | C35-50/60C+TDR+TXV | SL280UH100NV60C* | 38,000 | $1,900 |
| No | 211752868 | LENNOX | EL22XPV-060-230A** | C35-50/60C+TDR+TXV | SL280UH080NV60C* | 38,000 | $1,900 |
| No | 211752867 | LENNOX | EL22XPV-060-230A** | C35-50/60C+TDR+TXV | ML296UH110XV60C* | 37,800 | $1,890 |
| No | 211752929 | LENNOX | EL22XPV-060-230A** | C35-50/60C+TDR+TXV | ML296UH090XV48C* | 38,500 | $1,925 |
| No | 211752928 | LENNOX | EL22XPV-060-230A** | C35-50/60C+TDR+TXV | ML196UH110XE60C* | 38,000 | $1,900 |
| No | 211752927 | LENNOX | EL22XPV-060-230A** | C35-50/60C+TDR+TXV | ML196UH090XE60C* | 38,000 | $1,900 |
| No | 211752926 | LENNOX | EL22XPV-060-230A** | C35-50/60C+TDR+TXV | ML193UH110XE60C* | 38,000 | $1,900 |
| No | 211752925 | LENNOX | EL22XPV-060-230A** | C35-50/60C+TDR+TXV | ML180UH110XE60C* | 38,500 | $1,925 |
| No | 211752866 | LENNOX | EL22XPV-060-230A** | C35-50/60C+TDR+TXV | ML180UH110V60C* | 37,800 | $1,890 |
| No | 211752924 | LENNOX | EL22XPV-060-230A** | C35-50/60C+TDR+TXV | ML180UH110E60C* | 38,500 | $1,925 |
| No | 211752923 | LENNOX | EL22XPV-060-230A** | C35-50/60C+TDR+TXV | ML180UH090E60C* | 38,500 | $1,925 |
| No | 211752922 | LENNOX | EL22XPV-060-230A** | C35-50/60C+TDR+TXV | EL296UH110XE60C* | 38,000 | $1,900 |
| No | 211752864 | LENNOX | EL22XPV-060-230A** | C35-50/60C+TDR+TXV | EL280UH110XE60C* | 37,600 | $1,880 |
| No | 211752863 | LENNOX | EL22XPV-060-230A** | C35-50/60C+TDR+TXV | EL280UH110E60C* | 37,600 | $1,880 |
| No | 211752919 | LENNOX | EL22XPV-060-230A** | C35-50/60C+TDR+TXV | EL196UH110XE60C* | 38,000 | $1,900 |
| No | 211752918 | LENNOX | EL22XPV-060-230A** | C35-50/60C+TDR+TXV | EL195UH100NE60C* | 37,800 | $1,890 |
| No | 211752917 | LENNOX | EL22XPV-060-230A** | C35-50/60C+TDR+TXV | EL180UH100NE60C* | 38,500 | $1,925 |
| No | 211752862 | LENNOX | EL22XPV-060-230A** | CX35-50/60C+TDR | SLP99UH110XV60C* | 38,000 | $1,900 |
| No | 211752916 | LENNOX | EL22XPV-060-230A** | CX35-50/60C+TDR | SLP99UH090XV60C* | 38,000 | $1,900 |
| No | 211752915 | LENNOX | EL22XPV-060-230A** | CX35-50/60C+TDR | SLP99UH090XV48C* | 38,500 | $1,925 |
| No | 211752861 | LENNOX | EL22XPV-060-230A** | CX35-50/60C+TDR | SL280UH110XV60C* | 37,800 | $1,890 |
| No | 211752860 | LENNOX | EL22XPV-060-230A** | CX35-50/60C+TDR | SL280UH110V60C* | 37,800 | $1,890 |
| No | 211752858 | LENNOX | EL22XPV-060-230A** | CX35-50/60C+TDR | SL280UH090XV60C* | 37,800 | $1,890 |
| No | 211752857 | LENNOX | EL22XPV-060-230A** | CX35-50/60C+TDR | SL280UH090V60C* | 37,800 | $1,890 |
| No | 211752853 | LENNOX | EL22XPV-060-230A** | CX35-50/60C+TDR | EL296UH110XV60C* | 38,000 | $1,900 |
| No | 211752905 | LENNOX | EL22XPV-060-230A** | CX35-50/60C+TDR | EL296UH090XV60C* | 38,000 | $1,900 |
| No | 211752904 | LENNOX | EL22XPV-060-230A** | CX35-50/60C+TDR | EL296UH090XV48C* | 38,500 | $1,925 |
| No | 211752914 | LENNOX | EL22XPV-060-230A** | CX35-50/60C+TDR | SL297UH080NV60C* | 38,000 | $1,900 |
| No | 211752859 | LENNOX | EL22XPV-060-230A** | CX35-50/60C+TDR | SL280UH100NV60C* | 38,000 | $1,900 |
| No | 211752856 | LENNOX | EL22XPV-060-230A** | CX35-50/60C+TDR | SL280UH080NV60C* | 38,000 | $1,900 |
| No | 211752855 | LENNOX | EL22XPV-060-230A** | CX35-50/60C+TDR | ML296UH110XV60C* | 37,800 | $1,890 |
| No | 211752913 | LENNOX | EL22XPV-060-230A** | CX35-50/60C+TDR | ML296UH090XV48C* | 38,500 | $1,925 |
| No | 211752912 | LENNOX | EL22XPV-060-230A** | CX35-50/60C+TDR | ML196UH110XE60C* | 38,000 | $1,900 |
| No | 211752911 | LENNOX | EL22XPV-060-230A** | CX35-50/60C+TDR | ML196UH090XE60C* | 38,000 | $1,900 |
| No | 211752910 | LENNOX | EL22XPV-060-230A** | CX35-50/60C+TDR | ML193UH110XE60C* | 38,000 | $1,900 |
| No | 211752909 | LENNOX | EL22XPV-060-230A** | CX35-50/60C+TDR | ML180UH110XE60C* | 38,500 | $1,925 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211752854 | LENNOX | EL22XPV-060-230A** | CX35-50/60C+TDR | ML180UH110V60C* | 37,800 | $1,890 |
| No | 211752908 | LENNOX | EL22XPV-060-230A** | CX35-50/60C+TDR | ML180UH110E60C* | 38,500 | $1,925 |
| No | 211752907 | LENNOX | EL22XPV-060-230A** | CX35-50/60C+TDR | ML180UH090E60C* | 38,500 | $1,925 |
| No | 211752906 | LENNOX | EL22XPV-060-230A** | CX35-50/60C+TDR | EL296UH110XE60C* | 38,000 | $1,900 |
| No | 211752852 | LENNOX | EL22XPV-060-230A** | CX35-50/60C+TDR | EL280UH110XE60C* | 37,600 | $1,880 |
| No | 211752851 | LENNOX | EL22XPV-060-230A** | CX35-50/60C+TDR | EL280UH110E60C* | 37,600 | $1,880 |
| No | 211752903 | LENNOX | EL22XPV-060-230A** | CX35-50/60C+TDR | EL196UH110XE60C* | 38,000 | $1,900 |
| No | 211752902 | LENNOX | EL22XPV-060-230A** | CX35-50/60C+TDR | EL195UH100NE60C* | 37,800 | $1,890 |
| No | 211752901 | LENNOX | EL22XPV-060-230A** | CX35-50/60C+TDR | EL180UH100NE60C* | 38,500 | $1,925 |
| No | 211465316 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | SLP99UH110XV60C* | 37,400 | $1,870 |
| No | 211465315 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | SLP99UH090XV60C* | 37,600 | $1,880 |
| No | 211465314 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | SLP99UH090XV48C* | 37,800 | $1,890 |
| No | 211465313 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | SL297UH080NV60C* | 37,600 | $1,880 |
| No | 211465312 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | SL280UH110XV60C* | 37,400 | $1,870 |
| No | 211465311 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | SL280UH110V60C* | 37,400 | $1,870 |
| No | 211465310 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | SL280UH100NV60C* | 37,400 | $1,870 |
| No | 211465309 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | SL280UH090XV60C* | 37,400 | $1,870 |
| No | 211465308 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | SL280UH090V60C* | 37,400 | $1,870 |
| No | 211465307 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | SL280UH080NV60C* | 37,400 | $1,870 |
| No | 211465306 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | ML296UH110XV60C* | 37,200 | $1,860 |
| No | 211465305 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | ML296UH090XV48C* | 37,800 | $1,890 |
| No | 211465304 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | ML196UH110XE60C* | 37,800 | $1,890 |
| No | 211465303 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | ML196UH090XE60C* | 37,800 | $1,890 |
| No | 211465302 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | ML193UH110XE60C* | 37,800 | $1,890 |
| No | 211465301 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | ML180UH110XE60C* | 37,800 | $1,890 |
| No | 211465300 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | ML180UH110V60C* | 37,200 | $1,860 |
| No | 211465299 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | ML180UH110E60C* | 37,800 | $1,890 |
| No | 211465298 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | ML180UH090E60C* | 37,000 | $1,850 |
| No | 211465297 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | EL296UH110XV60C* | 37,400 | $1,870 |
| No | 211465296 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | EL296UH110XV48C* | 37,800 | $1,890 |
| No | 211465295 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | EL296UH110XE60C* | 37,800 | $1,890 |
| No | 211465294 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | EL296UH090XV60C* | 37,600 | $1,880 |
| No | 211465293 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | EL296UH090XV48C* | 37,800 | $1,890 |
| No | 211465292 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | EL280UH110XE60C* | 37,200 | $1,860 |
| No | 211465291 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | EL280UH110E60C* | 37,200 | $1,860 |
| No | 211465290 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | EL196UH110XE60C* | 37,800 | $1,890 |
| No | 211465289 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | EL195UH100NE60C* | 37,600 | $1,880 |
| No | 211465288 | LENNOX | EL22XPV-060-230A** | CX35-60C+TDR | EL180UH100NE60C* | 38,000 | $1,900 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211465257 | LENNOX | EL22XPV-060-230A** | C35-60C+TDR+TXV | SLP99UH110XV60C* | 37,400 | $1,870 |
| No | 211465256 | LENNOX | EL22XPV-060-230A** | C35-60C+TDR+TXV | SLP99UH090XV60C* | 37,600 | $1,880 |
| No | 211465255 | LENNOX | EL22XPV-060-230A** | C35-60C+TDR+TXV | SLP99UH090XV48C* | 37,800 | $1,890 |
| No | 211465254 | LENNOX | EL22XPV-060-230A** | C35-60C+TDR+TXV | SL297UH080NV60C* | 37,600 | $1,880 |
| No | 211465253 | LENNOX | EL22XPV-060-230A** | C35-60C+TDR+TXV | SL280UH110XV60C* | 37,400 | $1,870 |
| No | 211465252 | LENNOX | EL22XPV-060-230A** | C35-60C+TDR+TXV | SL280UH110V60C* | 37,400 | $1,870 |
| No | 211465251 | LENNOX | EL22XPV-060-230A** | C35-60C+TDR+TXV | SL280UH100NV60C* | 37,400 | $1,870 |
| No | 211465250 | LENNOX | EL22XPV-060-230A** | C35-60C+TDR+TXV | SL280UH090XV60C* | 37,400 | $1,870 |
| No | 211465249 | LENNOX | EL22XPV-060-230A** | C35-60C+TDR+TXV | SL280UH090V60C* | 37,400 | $1,870 |
| No | 211465248 | LENNOX | EL22XPV-060-230A** | C35-60C+TDR+TXV | SL280UH080NV60C* | 37,400 | $1,870 |
| No | 211465247 | LENNOX | EL22XPV-060-230A** | C35-60C+TDR+TXV | ML296UH110XV60C* | 37,200 | $1,860 |
| No | 211465246 | LENNOX | EL22XPV-060-230A** | C35-60C+TDR+TXV | ML296UH090XV48C* | 37,800 | $1,890 |
| No | 211465245 | LENNOX | EL22XPV-060-230A** | C35-60C+TDR+TXV | ML196UH110XE60C* | 37,800 | $1,890 |
| No | 211465244 | LENNOX | EL22XPV-060-230A** | C35-60C+TDR+TXV | ML196UH090XE60C* | 37,800 | $1,890 |
| No | 211465243 | LENNOX | EL22XPV-060-230A** | C35-60C+TDR+TXV | ML193UH110XE60C* | 37,800 | $1,890 |
| No | 211465242 | LENNOX | EL22XPV-060-230A** | C35-60C+TDR+TXV | ML180UH110XE60C* | 37,800 | $1,890 |
| No | 211465241 | LENNOX | EL22XPV-060-230A** | C35-60C+TDR+TXV | ML180UH110V60C* | 37,200 | $1,860 |
| No | 211465240 | LENNOX | EL22XPV-060-230A** | C35-60C+TDR+TXV | ML180UH110E60C* | 37,800 | $1,890 |
| No | 211465239 | LENNOX | EL22XPV-060-230A** | C35-60C+TDR+TXV | ML180UH090E60C* | 37,000 | $1,850 |
| No | 211465238 | LENNOX | EL22XPV-060-230A** | C35-60C+TDR+TXV | EL296UH110XV60C* | 37,400 | $1,870 |
| No | 211465237 | LENNOX | EL22XPV-060-230A** | C35-60C+TDR+TXV | EL296UH110XV48C* | 37,800 | $1,890 |
| No | 211465236 | LENNOX | EL22XPV-060-230A** | C35-60C+TDR+TXV | EL296UH110XE60C* | 37,800 | $1,890 |
| No | 211465235 | LENNOX | EL22XPV-060-230A** | C35-60C+TDR+TXV | EL296UH090XV60C* | 37,600 | $1,880 |
| No | 211465234 | LENNOX | EL22XPV-060-230A** | C35-60C+TDR+TXV | EL296UH090XV48C* | 37,800 | $1,890 |
| No | 211465233 | LENNOX | EL22XPV-060-230A** | C35-60C+TDR+TXV | EL280UH110XE60C* | 37,200 | $1,860 |
| No | 211465232 | LENNOX | EL22XPV-060-230A** | C35-60C+TDR+TXV | EL280UH110E60C* | 37,200 | $1,860 |
| No | 211465231 | LENNOX | EL22XPV-060-230A** | C35-60C+TDR+TXV | EL196UH110XE60C* | 37,800 | $1,890 |
| No | 211465230 | LENNOX | EL22XPV-060-230A** | C35-60C+TDR+TXV | EL180UH100NE60C* | 38,000 | $1,900 |
| No | 211465322 | LENNOX | EL22XPV-060-230A** | CX35-60D+TDR | SLP99UH135XV60D* | 37,600 | $1,880 |
| No | 211465321 | LENNOX | EL22XPV-060-230A** | CX35-60D+TDR | SL280UH135V60D* | 37,400 | $1,870 |
| No | 211465320 | LENNOX | EL22XPV-060-230A** | CX35-60D+TDR | ML196UH135XE60D* | 37,800 | $1,890 |
| No | 211465319 | LENNOX | EL22XPV-060-230A** | CX35-60D+TDR | ML180UH135E60D* | 37,800 | $1,890 |
| No | 211465318 | LENNOX | EL22XPV-060-230A** | CX35-60D+TDR | EL296UH135XV60D* | 37,600 | $1,880 |
| No | 211465317 | LENNOX | EL22XPV-060-230A** | CX35-60D+TDR | EL296UH135XE60D* | 38,000 | $1,900 |
| No | 211465265 | LENNOX | EL22XPV-060-230A** | CHX35-60D-**-*+TDR | SLP99UH135XV60D* | 36,400 | $1,820 |
| No | 211465264 | LENNOX | EL22XPV-060-230A** | CHX35-60D-**-*+TDR | SL280UH135V60D* | 36,200 | $1,810 |
| No | 211465263 | LENNOX | EL22XPV-060-230A** | CHX35-60D-**-*+TDR | ML196UH135XE60D* | 36,600 | $1,830 |
| No | 211465262 | LENNOX | EL22XPV-060-230A** | CHX35-60D-**-*+TDR | ML180UH135E60D* | 36,800 | $1,840 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211465261 | LENNOX | EL22XPV-060-230A** | CHX35-60D-**-*+TDR | EL296UH135XV60D* | 36,200 | $1,810 |
| No | 211465260 | LENNOX | EL22XPV-060-230A** | CHX35-60D-**-*+TDR | EL296UH135XE60D* | 36,400 | $1,820 |
| No | 211465274 | LENNOX | EL22XPV-060-230A** | CR33-50/60+TDR+TXV | SL280DF110V60C* | 38,000 | $1,900 |
| No | 211465273 | LENNOX | EL22XPV-060-230A** | CR33-50/60+TDR+TXV | SL280DF090V60C* | 38,000 | $1,900 |
| No | 211465272 | LENNOX | EL22XPV-060-230A** | CR33-50/60+TDR+TXV | SL280DF080NV60C* | 38,500 | $1,925 |
| No | 211465276 | LENNOX | EL22XPV-060-230A** | CR33-50/60+TDR+TXV | SLP99DF110XV60C* | 38,500 | $1,925 |
| No | 211465275 | LENNOX | EL22XPV-060-230A** | CR33-50/60+TDR+TXV | SLP99DF090XV60C* | 38,500 | $1,925 |
| No | 211465271 | LENNOX | EL22XPV-060-230A** | CR33-50/60+TDR+TXV | ML296DF090XV60C* | 38,500 | $1,925 |
| No | 211465270 | LENNOX | EL22XPV-060-230A** | CR33-50/60+TDR+TXV | ML196DF110XE60C* | 38,500 | $1,925 |
| No | 211465269 | LENNOX | EL22XPV-060-230A** | CR33-50/60+TDR+TXV | ML180DF110E60C* | 37,600 | $1,880 |
| No | 211465268 | LENNOX | EL22XPV-060-230A** | CR33-50/60+TDR+TXV | EL296DF110XV60C* | 38,500 | $1,925 |
| No | 211465267 | LENNOX | EL22XPV-060-230A** | CR33-50/60+TDR+TXV | EL296DF110XE60C* | 38,000 | $1,900 |
| No | 211465266 | LENNOX | EL22XPV-060-230A** | CR33-50/60+TDR+TXV | EL296DF090XV60C* | 38,500 | $1,925 |
| No | 211465285 | LENNOX | EL22XPV-060-230A** | CR33-60+TDR+TXV | SL280DF110V60C* | 38,000 | $1,900 |
| No | 211465284 | LENNOX | EL22XPV-060-230A** | CR33-60+TDR+TXV | SL280DF090V60C* | 38,000 | $1,900 |
| No | 211465283 | LENNOX | EL22XPV-060-230A** | CR33-60+TDR+TXV | SL280DF080NV60C* | 38,500 | $1,925 |
| No | 211465287 | LENNOX | EL22XPV-060-230A** | CR33-60+TDR+TXV | SLP99DF110XV60C* | 38,500 | $1,925 |
| No | 211465286 | LENNOX | EL22XPV-060-230A** | CR33-60+TDR+TXV | SLP99DF090XV60C* | 38,500 | $1,925 |
| No | 211465282 | LENNOX | EL22XPV-060-230A** | CR33-60+TDR+TXV | ML296DF090XV60C* | 38,500 | $1,925 |
| No | 211465281 | LENNOX | EL22XPV-060-230A** | CR33-60+TDR+TXV | ML196DF110XE60C* | 38,500 | $1,925 |
| No | 211465280 | LENNOX | EL22XPV-060-230A** | CR33-60+TDR+TXV | ML180DF110E60C* | 37,600 | $1,880 |
| No | 211465279 | LENNOX | EL22XPV-060-230A** | CR33-60+TDR+TXV | EL296DF110XV60C* | 38,500 | $1,925 |
| No | 211465278 | LENNOX | EL22XPV-060-230A** | CR33-60+TDR+TXV | EL296DF110XE60C* | 38,000 | $1,900 |
| No | 211465277 | LENNOX | EL22XPV-060-230A** | CR33-60+TDR+TXV | EL296DF090XV60C* | 38,500 | $1,925 |
| No | 211465258 | LENNOX | EL22XPV-060-230A** | CBA25UH-060-230-** | | 36,800 | $1,840 |
| No | 211465259 | LENNOX | EL22XPV-060-230A** | CBA25UHV-060-230-** | | 37,200 | $1,860 |
| No | 211465323 | LENNOX | EL22XPV-060-230A** | CBA27UHE-060-230-** | | 37,000 | $1,850 |
| No | 211465229 | LENNOX | EL22XPV-060-230A** | CBA38MV-060-230*+TDR | | 37,000 | $1,850 |
| No | 211467835 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | SL297UH080NV48C* | 22,600 | $1,130 |
| No | 211467834 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | SL280UH110XV60C* | 22,400 | $1,120 |
| No | 211467833 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | SL280UH110V60C* | 22,400 | $1,120 |
| No | 211467832 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | SL280UH100NV60C* | 22,400 | $1,120 |
| No | 211467831 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | SL280UH090XV60C* | 22,400 | $1,120 |
| No | 211467830 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | SL280UH090V60C* | 22,400 | $1,120 |
| No | 211467829 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | SL280UH080NV60C* | 22,400 | $1,120 |
| No | 211467828 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | ML296UH110XV60C* | 22,400 | $1,120 |
| No | 211467827 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | ML296UH090XV48C* | 22,400 | $1,120 |
| No | 211467826 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | ML196UH110XE60C* | 22,600 | $1,130 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211467825 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | ML196UH090XE60C* | 22,400 | $1,120 |
| No | 211467824 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | ML196UH090XE48C* | 22,400 | $1,120 |
| No | 211467823 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | ML196UH090XE36C* | 22,200 | $1,110 |
| No | 211467822 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | ML193UH110XE60C* | 22,400 | $1,120 |
| No | 211467821 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | ML193UH110XE48C* | 22,200 | $1,110 |
| No | 211467820 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | ML193UH090XE48C* | 22,400 | $1,120 |
| No | 211467819 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | ML193UH090XE36C* | 22,400 | $1,120 |
| No | 211467818 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | ML180UH110XE60C* | 22,200 | $1,110 |
| No | 211467817 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | ML180UH110V60C* | 22,400 | $1,120 |
| No | 211467816 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | ML180UH110E60C* | 22,200 | $1,110 |
| No | 211467815 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | ML180UH090E60C* | 22,200 | $1,110 |
| No | 211467814 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | EL296UH110XV60C* | 22,400 | $1,120 |
| No | 211467813 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | EL296UH110XV48C* | 22,600 | $1,130 |
| No | 211467812 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | EL296UH110XE60C* | 22,600 | $1,130 |
| No | 211467811 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | EL296UH090XV60C* | 22,600 | $1,130 |
| No | 211467810 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | EL296UH090XV48C* | 22,600 | $1,130 |
| No | 211467809 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | EL296UH090XV36C* | 22,600 | $1,130 |
| No | 211467808 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | EL296UH090XE48C* | 22,200 | $1,110 |
| No | 211467807 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | EL280UH110XE60C* | 22,600 | $1,130 |
| No | 211467806 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | EL280UH110E60C* | 22,600 | $1,130 |
| No | 211467805 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | EL280UH110E48C* | 22,000 | $1,100 |
| No | 211467804 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | EL196UH110XE60C* | 22,600 | $1,130 |
| No | 211467803 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | EL196UH090XE48C* | 22,400 | $1,120 |
| No | 211467802 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | EL195UH100NE60C* | 22,600 | $1,130 |
| No | 211467801 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | EL195UH080NE48C* | 22,400 | $1,120 |
| No | 211467800 | LENNOX | EL22XPV-036-230A** | CHX35-42C-**-*+TDR | EL180UH100NE60C* | 22,400 | $1,120 |
| No | 211468010 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | SLP99UH070XV36B* | 22,600 | $1,130 |
| No | 211468009 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | SL297UH060NV36B* | 22,600 | $1,130 |
| No | 211468008 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | SL297UH040NV36B* | 22,600 | $1,130 |
| No | 211468007 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | SL280UH090XV48B* | 22,400 | $1,120 |
| No | 211468006 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | SL280UH090V48B* | 22,400 | $1,120 |
| No | 211468005 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | SL280UH090V36B* | 22,400 | $1,120 |
| No | 211468004 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | SL280UH080NV48B* | 22,600 | $1,130 |
| No | 211468003 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | ML296UH070XV36B* | 22,400 | $1,120 |
| No | 211468002 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | ML296UH045XV36B* | 22,400 | $1,120 |
| No | 211468001 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | ML196UH070XE48B* | 22,400 | $1,120 |
| No | 211468000 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | ML196UH070XE36B* | 22,200 | $1,110 |
| No | 211467999 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | ML196UH045XE36B* | 21,800 | $1,090 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211467998 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | ML196UH030XE36B* | 22,200 | $1,110 |
| No | 211467997 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | ML193UH070XE36B* | 22,200 | $1,110 |
| No | 211467996 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | ML193UH045XE36B* | 22,400 | $1,120 |
| No | 211467995 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | ML193UH030XE36B* | 22,400 | $1,120 |
| No | 211467994 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | ML180UH090XE48B* | 22,200 | $1,110 |
| No | 211467993 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | ML180UH090V48B* | 22,200 | $1,110 |
| No | 211467992 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | ML180UH090E48B* | 22,200 | $1,110 |
| No | 211467991 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | ML180UH070XE36B* | 22,200 | $1,110 |
| No | 211467990 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | ML180UH070V48B* | 22,200 | $1,110 |
| No | 211467989 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | ML180UH070V36B* | 22,200 | $1,110 |
| No | 211467988 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | ML180UH070E36B* | 22,200 | $1,110 |
| No | 211467987 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | EL296UH070XV36B* | 22,600 | $1,130 |
| No | 211467986 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | EL296UH070XE36B* | 22,200 | $1,110 |
| No | 211467985 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | EL296UH045XV36B* | 22,600 | $1,130 |
| No | 211467984 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | EL296UH045XE36B* | 22,400 | $1,120 |
| No | 211467983 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | EL280UH090XE48B* | 22,000 | $1,100 |
| No | 211467982 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | EL280UH090E48B* | 22,000 | $1,100 |
| No | 211467981 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | EL280UH090E36B* | 22,000 | $1,100 |
| No | 211467980 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | EL196UH070XE36B* | 22,200 | $1,110 |
| No | 211467979 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | EL196UH045XE36B* | 21,800 | $1,090 |
| No | 211467978 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | EL196UH030XE36B* | 22,200 | $1,110 |
| No | 211467977 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | EL195UH060NE36B* | 22,400 | $1,120 |
| No | 211467976 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | EL195UH040NE36B* | 21,800 | $1,090 |
| No | 211467975 | LENNOX | EL22XPV-036-230A** | CX35-48B+TDR | EL180UH080NE48B* | 22,600 | $1,130 |
| No | 211467717 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | SLP99UH070XV36B* | 22,600 | $1,130 |
| No | 211467716 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | SL297UH060NV36B* | 22,600 | $1,130 |
| No | 211467715 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | SL297UH040NV36B* | 22,600 | $1,130 |
| No | 211467714 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | SL280UH090XV48B* | 22,400 | $1,120 |
| No | 211467713 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | SL280UH090V48B* | 22,400 | $1,120 |
| No | 211467712 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | SL280UH090V36B* | 22,400 | $1,120 |
| No | 211467711 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | SL280UH080NV48B* | 22,600 | $1,130 |
| No | 211467710 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | ML296UH070XV36B* | 22,400 | $1,120 |
| No | 211467709 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | ML296UH045XV36B* | 22,400 | $1,120 |
| No | 211467708 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | ML196UH070XE48B* | 22,400 | $1,120 |
| No | 211467707 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | ML196UH070XE36B* | 22,200 | $1,110 |
| No | 211467706 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | ML196UH045XE36B* | 21,800 | $1,090 |
| No | 211467705 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | ML196UH030XE36B* | 22,200 | $1,110 |
| No | 211467704 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | ML193UH070XE36B* | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211467703 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | ML193UH045XE36B* | 22,400 | $1,120 |
| No | 211467702 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | ML193UH030XE36B* | 22,400 | $1,120 |
| No | 211467701 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | ML180UH090XE48B* | 22,200 | $1,110 |
| No | 211467700 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | ML180UH090V48B* | 22,200 | $1,110 |
| No | 211467699 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | ML180UH090E48B* | 22,200 | $1,110 |
| No | 211467698 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | ML180UH070XE36B* | 22,200 | $1,110 |
| No | 211467697 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | ML180UH070V48B* | 22,200 | $1,110 |
| No | 211467696 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | ML180UH070V36B* | 22,200 | $1,110 |
| No | 211467695 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | ML180UH070E36B* | 22,200 | $1,110 |
| No | 211467694 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | EL296UH070XV36B* | 22,600 | $1,130 |
| No | 211467693 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | EL296UH070XE36B* | 22,200 | $1,110 |
| No | 211467692 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | EL296UH045XV36B* | 22,600 | $1,130 |
| No | 211467691 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | EL296UH045XE36B* | 22,400 | $1,120 |
| No | 211467690 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | EL280UH090XE48B* | 22,000 | $1,100 |
| No | 211467689 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | EL280UH090E48B* | 22,000 | $1,100 |
| No | 211467688 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | EL280UH090E36B* | 22,000 | $1,100 |
| No | 211467687 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | EL196UH070XE36B* | 22,200 | $1,110 |
| No | 211467686 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | EL196UH045XE36B* | 21,800 | $1,090 |
| No | 211467685 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | EL196UH030XE36B* | 22,200 | $1,110 |
| No | 211467684 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | EL195UH060NE36B* | 22,400 | $1,120 |
| No | 211467683 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | EL195UH040NE36B* | 21,800 | $1,090 |
| No | 211467682 | LENNOX | EL22XPV-036-230A** | C35-48B+TDR+TXV | EL180UH080NE48B* | 22,600 | $1,130 |
| No | 211468017 | LENNOX | EL22XPV-036-230A** | CHX35-30A-**-*+TDR | SL280UH070XV36A* | 23,200 | $1,160 |
| No | 211468016 | LENNOX | EL22XPV-036-230A** | CHX35-30A-**-*+TDR | SL280UH070V36A* | 23,200 | $1,160 |
| No | 211467729 | LENNOX | EL22XPV-036-230A** | CHX35-30A-**-*+TDR | ML180UH070XE36A* | 22,600 | $1,130 |
| No | 211468015 | LENNOX | EL22XPV-036-230A** | CHX35-30A-**-*+TDR | ML180UH070V36A* | 23,000 | $1,150 |
| No | 211467728 | LENNOX | EL22XPV-036-230A** | CHX35-30A-**-*+TDR | ML180UH070E36A* | 22,600 | $1,130 |
| No | 211467727 | LENNOX | EL22XPV-036-230A** | CHX35-30A-**-*+TDR | ML180UH045XE36A* | 22,600 | $1,130 |
| No | 211467726 | LENNOX | EL22XPV-036-230A** | CHX35-30A-**-*+TDR | ML180UH045V36A* | 22,800 | $1,140 |
| No | 211467725 | LENNOX | EL22XPV-036-230A** | CHX35-30A-**-*+TDR | ML180UH045E36A* | 22,600 | $1,130 |
| No | 211467724 | LENNOX | EL22XPV-036-230A** | CHX35-30A-**-*+TDR | ML180UH030V36A* | 22,800 | $1,140 |
| No | 211468014 | LENNOX | EL22XPV-036-230A** | CHX35-30A-**-*+TDR | EL280UH070XE36A* | 23,000 | $1,150 |
| No | 211468013 | LENNOX | EL22XPV-036-230A** | CHX35-30A-**-*+TDR | EL280UH070E36A* | 23,000 | $1,150 |
| No | 211467723 | LENNOX | EL22XPV-036-230A** | CHX35-30A-**-*+TDR | EL280UH045E36A* | 23,000 | $1,150 |
| No | 211468012 | LENNOX | EL22XPV-036-230A** | CHX35-30A-**-*+TDR | EL180UH060NE36A* | 22,600 | $1,130 |
| No | 211468011 | LENNOX | EL22XPV-036-230A** | CHX35-30A-**-*+TDR | EL180UH040NE36A* | 22,600 | $1,130 |
| No | 211467865 | LENNOX | EL22XPV-036-230A** | CR33-30/36C+TDR+TXV | SLP99DF090XV48C* | 23,400 | $1,170 |
| No | 211467864 | LENNOX | EL22XPV-036-230A** | CR33-30/36C+TDR+TXV | SLP99DF090XV36C* | 23,200 | $1,160 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211467863 | LENNOX | EL22XPV-036-230A** | CR33-30/36C+TDR+TXV | ML296DF090XV60C* | 22,800 | $1,140 |
| No | 211467862 | LENNOX | EL22XPV-036-230A** | CR33-30/36C+TDR+TXV | ML196DF110XE60C* | 23,000 | $1,150 |
| No | 211467861 | LENNOX | EL22XPV-036-230A** | CR33-30/36C+TDR+TXV | ML196DF090XE48C* | 22,800 | $1,140 |
| No | 211467860 | LENNOX | EL22XPV-036-230A** | CR33-30/36C+TDR+TXV | ML193DF090XE48C* | 22,800 | $1,140 |
| No | 211467859 | LENNOX | EL22XPV-036-230A** | CR33-30/36C+TDR+TXV | ML180DF110E60C* | 22,800 | $1,140 |
| No | 211467858 | LENNOX | EL22XPV-036-230A** | CR33-30/36C+TDR+TXV | EL296DF110XE60C* | 23,000 | $1,150 |
| No | 211467857 | LENNOX | EL22XPV-036-230A** | CR33-30/36C+TDR+TXV | EL296DF090XE48C* | 22,800 | $1,140 |
| No | 211467856 | LENNOX | EL22XPV-036-230A** | CR33-30/36B+TDR+TXV | SLP99DF070XV36B* | 23,200 | $1,160 |
| No | 211467855 | LENNOX | EL22XPV-036-230A** | CR33-30/36B+TDR+TXV | SL280DF090V48B* | 23,200 | $1,160 |
| No | 211467854 | LENNOX | EL22XPV-036-230A** | CR33-30/36B+TDR+TXV | ML296DF070XV48B* | 22,800 | $1,140 |
| No | 211468023 | LENNOX | EL22XPV-036-230A** | CR33-30/36B+TDR+TXV | ML296DF045XV36B* | 23,200 | $1,160 |
| No | 211467853 | LENNOX | EL22XPV-036-230A** | CR33-30/36B+TDR+TXV | ML196DF070XE48B* | 23,200 | $1,160 |
| No | 211467852 | LENNOX | EL22XPV-036-230A** | CR33-30/36B+TDR+TXV | ML196DF045XE36B* | 22,800 | $1,140 |
| No | 211467851 | LENNOX | EL22XPV-036-230A** | CR33-30/36B+TDR+TXV | ML193DF070XE36B* | 23,000 | $1,150 |
| No | 211467850 | LENNOX | EL22XPV-036-230A** | CR33-30/36B+TDR+TXV | ML193DF045XE36B* | 23,000 | $1,150 |
| No | 211467849 | LENNOX | EL22XPV-036-230A** | CR33-30/36B+TDR+TXV | ML180DF090E48B* | 22,800 | $1,140 |
| No | 211467848 | LENNOX | EL22XPV-036-230A** | CR33-30/36B+TDR+TXV | ML180DF070E36B* | 22,600 | $1,130 |
| No | 211467847 | LENNOX | EL22XPV-036-230A** | CR33-30/36B+TDR+TXV | EL296DF070XV48B* | 23,400 | $1,170 |
| No | 211467846 | LENNOX | EL22XPV-036-230A** | CR33-30/36B+TDR+TXV | EL296DF070XE48B* | 23,000 | $1,150 |
| No | 211467845 | LENNOX | EL22XPV-036-230A** | CR33-30/36B+TDR+TXV | EL296DF045XV36B* | 23,400 | $1,170 |
| No | 211467844 | LENNOX | EL22XPV-036-230A** | CR33-30/36B+TDR+TXV | EL280DF090E48B* | 22,800 | $1,140 |
| No | 211467843 | LENNOX | EL22XPV-036-230A** | CR33-30/36A+TDR+TXV | SL280DF070V36A* | 23,400 | $1,170 |
| No | 211467842 | LENNOX | EL22XPV-036-230A** | CR33-30/36A+TDR+TXV | ML180DF070E36A* | 22,800 | $1,140 |
| No | 211467841 | LENNOX | EL22XPV-036-230A** | CR33-30/36A+TDR+TXV | EL280DF070E36A* | 22,800 | $1,140 |
| No | 211467974 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | SLP99UH070XV36B* | 22,000 | $1,100 |
| No | 211467973 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | SL297UH060NV36B* | 22,200 | $1,110 |
| No | 211467972 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | SL297UH040NV36B* | 22,000 | $1,100 |
| No | 211467971 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | SL280UH090XV48B* | 22,000 | $1,100 |
| No | 211467970 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | SL280UH090V48B* | 22,000 | $1,100 |
| No | 211467969 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | SL280UH090V36B* | 22,000 | $1,100 |
| No | 211467968 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | SL280UH080NV48B* | 22,000 | $1,100 |
| No | 211467967 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | ML296UH070XV36B* | 22,000 | $1,100 |
| No | 211467966 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | ML296UH045XV36B* | 22,000 | $1,100 |
| No | 211467965 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | ML196UH070XE48B* | 22,000 | $1,100 |
| No | 211467964 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | ML196UH070XE36B* | 21,600 | $1,080 |
| No | 211467963 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | ML196UH030XE36B* | 21,600 | $1,080 |
| No | 211467962 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | ML193UH070XE36B* | 21,800 | $1,090 |
| No | 211467961 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | ML193UH045XE36B* | 21,800 | $1,090 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211467960 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | ML193UH030XE36B* | 21,800 | $1,090 |
| No | 211467959 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | ML180UH090XE48B* | 21,600 | $1,080 |
| No | 211467958 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | ML180UH090V48B* | 21,800 | $1,090 |
| No | 211467957 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | ML180UH090E48B* | 21,600 | $1,080 |
| No | 211467956 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | ML180UH070XE36B* | 21,600 | $1,080 |
| No | 211467955 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | ML180UH070V48B* | 21,400 | $1,070 |
| No | 211467954 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | ML180UH070V36B* | 21,600 | $1,080 |
| No | 211467953 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | ML180UH070E36B* | 21,600 | $1,080 |
| No | 211467952 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | EL296UH070XV36B* | 22,000 | $1,100 |
| No | 211467951 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | EL296UH070XE36B* | 21,600 | $1,080 |
| No | 211467950 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | EL296UH045XV36B* | 22,200 | $1,110 |
| No | 211467949 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | EL296UH045XE36B* | 21,800 | $1,090 |
| No | 211467948 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | EL280UH090XE48B* | 21,400 | $1,070 |
| No | 211467947 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | EL280UH090E48B* | 21,400 | $1,070 |
| No | 211467946 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | EL280UH090E36B* | 21,800 | $1,090 |
| No | 211467945 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | EL196UH070XE36B* | 21,600 | $1,080 |
| No | 211467944 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | EL196UH030XE36B* | 21,600 | $1,080 |
| No | 211467943 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | EL195UH060NE36B* | 21,800 | $1,090 |
| No | 211467942 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | EL195UH040NE36B* | 21,400 | $1,070 |
| No | 211467941 | LENNOX | EL22XPV-036-230A** | CX35-36B+TDR | EL180UH080NE48B* | 22,000 | $1,100 |
| No | 211467681 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | SLP99UH070XV36B* | 22,000 | $1,100 |
| No | 211467680 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | SL297UH060NV36B* | 22,200 | $1,110 |
| No | 211467679 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | SL297UH040NV36B* | 22,000 | $1,100 |
| No | 211467678 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | SL280UH090XV48B* | 22,000 | $1,100 |
| No | 211467677 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | SL280UH090V48B* | 22,000 | $1,100 |
| No | 211467676 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | SL280UH090V36B* | 22,000 | $1,100 |
| No | 211467675 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | SL280UH080NV48B* | 22,000 | $1,100 |
| No | 211467674 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | ML296UH070XV36B* | 22,000 | $1,100 |
| No | 211467673 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | ML296UH045XV36B* | 22,000 | $1,100 |
| No | 211467672 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | ML196UH070XE48B* | 22,000 | $1,100 |
| No | 211467671 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | ML196UH070XE36B* | 21,600 | $1,080 |
| No | 211467670 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | ML196UH030XE36B* | 21,600 | $1,080 |
| No | 211467669 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | ML193UH070XE36B* | 21,800 | $1,090 |
| No | 211467668 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | ML193UH045XE36B* | 21,800 | $1,090 |
| No | 211467667 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | ML193UH030XE36B* | 21,800 | $1,090 |
| No | 211467666 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | ML180UH090XE48B* | 21,600 | $1,080 |
| No | 211467665 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | ML180UH090V48B* | 21,800 | $1,090 |
| No | 211467664 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | ML180UH090E48B* | 21,600 | $1,080 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211467663 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | ML180UH070XE36B* | 21,600 | $1,080 |
| No | 211467662 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | ML180UH070V48B* | 21,400 | $1,070 |
| No | 211467661 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | ML180UH070V36B* | 21,600 | $1,080 |
| No | 211467660 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | ML180UH070E36B* | 21,600 | $1,080 |
| No | 211467659 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | EL296UH070XV36B* | 22,000 | $1,100 |
| No | 211467658 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | EL296UH070XE36B* | 21,600 | $1,080 |
| No | 211467657 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | EL296UH045XV36B* | 22,200 | $1,110 |
| No | 211467656 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | EL296UH045XE36B* | 21,800 | $1,090 |
| No | 211467655 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | EL280UH090XE48B* | 21,400 | $1,070 |
| No | 211467654 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | EL280UH090E48B* | 21,400 | $1,070 |
| No | 211467653 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | EL280UH090E36B* | 21,800 | $1,090 |
| No | 211467652 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | EL196UH070XE36B* | 21,600 | $1,080 |
| No | 211467651 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | EL196UH030XE36B* | 21,600 | $1,080 |
| No | 211467650 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | EL195UH060NE36B* | 21,800 | $1,090 |
| No | 211467649 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | EL195UH040NE36B* | 21,400 | $1,070 |
| No | 211467648 | LENNOX | EL22XPV-036-230A** | C35-36B+TDR+TXV | EL180UH080NE48B* | 22,000 | $1,100 |
| No | 211467940 | LENNOX | EL22XPV-036-230A** | CX35-36A+TDR | SL280UH070XV36A* | 22,200 | $1,110 |
| No | 211467939 | LENNOX | EL22XPV-036-230A** | CX35-36A+TDR | SL280UH070V36A* | 22,200 | $1,110 |
| No | 211467938 | LENNOX | EL22XPV-036-230A** | CX35-36A+TDR | ML180UH070XE36A* | 21,600 | $1,080 |
| No | 211467937 | LENNOX | EL22XPV-036-230A** | CX35-36A+TDR | ML180UH070V36A* | 21,800 | $1,090 |
| No | 211467936 | LENNOX | EL22XPV-036-230A** | CX35-36A+TDR | ML180UH070E36A* | 21,600 | $1,080 |
| No | 211467935 | LENNOX | EL22XPV-036-230A** | CX35-36A+TDR | ML180UH045XE36A* | 21,600 | $1,080 |
| No | 211467934 | LENNOX | EL22XPV-036-230A** | CX35-36A+TDR | ML180UH045V36A* | 21,800 | $1,090 |
| No | 211467933 | LENNOX | EL22XPV-036-230A** | CX35-36A+TDR | ML180UH045E36A* | 21,600 | $1,080 |
| No | 211467932 | LENNOX | EL22XPV-036-230A** | CX35-36A+TDR | ML180UH030V36A* | 21,800 | $1,090 |
| No | 211467931 | LENNOX | EL22XPV-036-230A** | CX35-36A+TDR | EL280UH070XE36A* | 21,800 | $1,090 |
| No | 211467930 | LENNOX | EL22XPV-036-230A** | CX35-36A+TDR | EL280UH070E36A* | 21,800 | $1,090 |
| No | 211467929 | LENNOX | EL22XPV-036-230A** | CX35-36A+TDR | EL280UH045E36A* | 21,800 | $1,090 |
| No | 211467928 | LENNOX | EL22XPV-036-230A** | CX35-36A+TDR | EL180UH060NE36A* | 21,600 | $1,080 |
| No | 211467927 | LENNOX | EL22XPV-036-230A** | CX35-36A+TDR | EL180UH040NE36A* | 21,600 | $1,080 |
| No | 211467647 | LENNOX | EL22XPV-036-230A** | C35-36A+TDR+TXV | SL280UH070XV36A* | 22,200 | $1,110 |
| No | 211467646 | LENNOX | EL22XPV-036-230A** | C35-36A+TDR+TXV | SL280UH070V36A* | 22,200 | $1,110 |
| No | 211467645 | LENNOX | EL22XPV-036-230A** | C35-36A+TDR+TXV | ML180UH070XE36A* | 21,600 | $1,080 |
| No | 211467644 | LENNOX | EL22XPV-036-230A** | C35-36A+TDR+TXV | ML180UH070V36A* | 21,800 | $1,090 |
| No | 211467643 | LENNOX | EL22XPV-036-230A** | C35-36A+TDR+TXV | ML180UH070E36A* | 21,600 | $1,080 |
| No | 211467642 | LENNOX | EL22XPV-036-230A** | C35-36A+TDR+TXV | ML180UH045XE36A* | 21,600 | $1,080 |
| No | 211467641 | LENNOX | EL22XPV-036-230A** | C35-36A+TDR+TXV | ML180UH045V36A* | 21,800 | $1,090 |
| No | 211467640 | LENNOX | EL22XPV-036-230A** | C35-36A+TDR+TXV | ML180UH045E36A* | 21,600 | $1,080 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211467639 | LENNOX | EL22XPV-036-230A** | C35-36A+TDR+TXV | ML180UH030V36A* | 21,800 | $1,090 |
| No | 211467638 | LENNOX | EL22XPV-036-230A** | C35-36A+TDR+TXV | EL280UH070XE36A* | 21,800 | $1,090 |
| No | 211467637 | LENNOX | EL22XPV-036-230A** | C35-36A+TDR+TXV | EL280UH070E36A* | 21,800 | $1,090 |
| No | 211467636 | LENNOX | EL22XPV-036-230A** | C35-36A+TDR+TXV | EL280UH045E36A* | 21,800 | $1,090 |
| No | 211467635 | LENNOX | EL22XPV-036-230A** | C35-36A+TDR+TXV | EL180UH060NE36A* | 21,600 | $1,080 |
| No | 211467634 | LENNOX | EL22XPV-036-230A** | C35-36A+TDR+TXV | EL180UH040NE36A* | 21,600 | $1,080 |
| No | 211467799 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | SLP99UH110XV60C* | 22,800 | $1,140 |
| No | 211467798 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | SLP99UH090XV60C* | 22,800 | $1,140 |
| No | 211467797 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | SLP99UH090XV48C* | 23,000 | $1,150 |
| No | 211467796 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | SLP99UH090XV36C* | 23,000 | $1,150 |
| No | 211467795 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | SL297UH080NV60C* | 23,000 | $1,150 |
| No | 211467794 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | SL297UH080NV48C* | 22,800 | $1,140 |
| No | 211467793 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | SL280UH110XV60C* | 22,800 | $1,140 |
| No | 211467792 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | SL280UH110V60C* | 22,800 | $1,140 |
| No | 211467791 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | SL280UH100NV60C* | 22,800 | $1,140 |
| No | 211467790 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | SL280UH090XV60C* | 22,800 | $1,140 |
| No | 211467789 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | SL280UH090V60C* | 22,800 | $1,140 |
| No | 211467788 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | SL280UH080NV60C* | 22,800 | $1,140 |
| No | 211467787 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | ML296UH110XV60C* | 22,400 | $1,120 |
| No | 211467786 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | ML296UH090XV48C* | 22,600 | $1,130 |
| No | 211467785 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | ML196UH110XE60C* | 22,800 | $1,140 |
| No | 211467784 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | ML196UH090XE60C* | 22,800 | $1,140 |
| No | 211467783 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | ML196UH090XE48C* | 22,800 | $1,140 |
| No | 211467782 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | ML196UH090XE36C* | 22,600 | $1,130 |
| No | 211467781 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | ML193UH110XE60C* | 22,800 | $1,140 |
| No | 211467780 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | ML193UH110XE48C* | 22,600 | $1,130 |
| No | 211467779 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | ML193UH090XE48C* | 22,600 | $1,130 |
| No | 211467778 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | ML193UH090XE36C* | 22,800 | $1,140 |
| No | 211467777 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | ML180UH110XE60C* | 22,600 | $1,130 |
| No | 211467776 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | ML180UH110V60C* | 22,600 | $1,130 |
| No | 211467775 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | ML180UH110E60C* | 22,600 | $1,130 |
| No | 211467774 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | ML180UH090E60C* | 22,600 | $1,130 |
| No | 211467773 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | EL296UH110XV60C* | 22,800 | $1,140 |
| No | 211467772 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | EL296UH110XV48C* | 23,000 | $1,150 |
| No | 211467771 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | EL296UH110XE60C* | 22,800 | $1,140 |
| No | 211467770 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | EL296UH090XV60C* | 22,800 | $1,140 |
| No | 211467769 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | EL296UH090XV48C* | 23,000 | $1,150 |
| No | 211467768 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | EL296UH090XV36C* | 23,000 | $1,150 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211467767 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | EL296UH090XE48C* | 22,600 | $1,130 |
| No | 211467766 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | EL280UH110XE60C* | 22,800 | $1,140 |
| No | 211467765 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | EL280UH110E60C* | 22,800 | $1,140 |
| No | 211467764 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | EL280UH110E48C* | 22,400 | $1,120 |
| No | 211467763 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | EL196UH110XE60C* | 22,800 | $1,140 |
| No | 211467762 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | EL196UH090XE48C* | 22,400 | $1,120 |
| No | 211467761 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | EL195UH100NE60C* | 22,800 | $1,140 |
| No | 211467760 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | EL195UH080NE48C* | 22,800 | $1,140 |
| No | 211467759 | LENNOX | EL22XPV-036-230A** | CHX35-36C-**-*+TDR | EL180UH100NE60C* | 22,800 | $1,140 |
| No | 211467758 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | SLP99UH070XV36B* | 23,000 | $1,150 |
| No | 211467757 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | SL297UH060NV36B* | 23,000 | $1,150 |
| No | 211467756 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | SL297UH040NV36B* | 23,000 | $1,150 |
| No | 211467755 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | SL280UH090XV48B* | 22,600 | $1,130 |
| No | 211467754 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | SL280UH090V48B* | 22,600 | $1,130 |
| No | 211467753 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | SL280UH090V36B* | 22,800 | $1,140 |
| No | 211467752 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | SL280UH080NV48B* | 22,800 | $1,140 |
| No | 211468022 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | ML296UH070XV36B* | 22,800 | $1,140 |
| No | 211468021 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | ML296UH045XV36B* | 22,800 | $1,140 |
| No | 211468020 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | ML196UH070XE48B* | 22,800 | $1,140 |
| No | 211467751 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | ML196UH070XE36B* | 22,400 | $1,120 |
| No | 211467750 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | ML196UH030XE36B* | 22,400 | $1,120 |
| No | 211467749 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | ML193UH070XE36B* | 22,600 | $1,130 |
| No | 211467748 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | ML193UH045XE36B* | 22,600 | $1,130 |
| No | 211468019 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | ML193UH030XE36B* | 22,600 | $1,130 |
| No | 211467747 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | ML180UH090XE48B* | 22,400 | $1,120 |
| No | 211467746 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | ML180UH090V48B* | 22,600 | $1,130 |
| No | 211467745 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | ML180UH090E48B* | 22,200 | $1,110 |
| No | 211467744 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | ML180UH070XE36B* | 22,400 | $1,120 |
| No | 211467743 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | ML180UH070V48B* | 22,200 | $1,110 |
| No | 211467742 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | ML180UH070V36B* | 22,400 | $1,120 |
| No | 211467741 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | ML180UH070E36B* | 22,400 | $1,120 |
| No | 211467740 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | EL296UH070XV36B* | 23,000 | $1,150 |
| No | 211467739 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | EL296UH070XE36B* | 22,400 | $1,120 |
| No | 211468018 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | EL296UH045XV36B* | 23,000 | $1,150 |
| No | 211467738 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | EL296UH045XE36B* | 22,600 | $1,130 |
| No | 211467737 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | EL280UH090XE48B* | 22,600 | $1,130 |
| No | 211467736 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | EL280UH090E48B* | 22,600 | $1,130 |
| No | 211467735 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | EL280UH090E36B* | 22,600 | $1,130 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211467734 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | EL196UH070XE36B* | 22,400 | $1,120 |
| No | 211467733 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | EL196UH030XE36B* | 22,400 | $1,120 |
| No | 211467732 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | EL195UH060NE36B* | 22,600 | $1,130 |
| No | 211467731 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | EL195UH040NE36B* | 22,200 | $1,110 |
| No | 211467730 | LENNOX | EL22XPV-036-230A** | CHX35-30B-**-*+TDR | EL180UH080NE48B* | 22,800 | $1,140 |
| No | 211467926 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | SLP99UH070XV36B* | 22,000 | $1,100 |
| No | 211467925 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | SL297UH060NV36B* | 22,200 | $1,110 |
| No | 211467924 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | SL297UH040NV36B* | 22,000 | $1,100 |
| No | 211467923 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | SL280UH090XV48B* | 21,800 | $1,090 |
| No | 211467922 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | SL280UH090V48B* | 21,800 | $1,090 |
| No | 211467921 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | SL280UH090V36B* | 21,800 | $1,090 |
| No | 211467920 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | SL280UH080NV48B* | 22,000 | $1,100 |
| No | 211467919 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | ML296UH070XV36B* | 22,000 | $1,100 |
| No | 211467918 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | ML296UH045XV36B* | 22,000 | $1,100 |
| No | 211467917 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | ML196UH070XE48B* | 21,800 | $1,090 |
| No | 211467916 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | ML196UH070XE36B* | 21,600 | $1,080 |
| No | 211467915 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | ML196UH030XE36B* | 21,800 | $1,090 |
| No | 211467914 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | ML193UH070XE36B* | 21,800 | $1,090 |
| No | 211467913 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | ML193UH045XE36B* | 21,800 | $1,090 |
| No | 211467912 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | ML193UH030XE36B* | 21,800 | $1,090 |
| No | 211467911 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | ML180UH090XE48B* | 21,600 | $1,080 |
| No | 211467910 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | ML180UH090V48B* | 21,600 | $1,080 |
| No | 211467909 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | ML180UH090E48B* | 21,600 | $1,080 |
| No | 211467908 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | ML180UH070XE36B* | 21,600 | $1,080 |
| No | 211467907 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | ML180UH070V48B* | 21,400 | $1,070 |
| No | 211467906 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | ML180UH070V36B* | 21,600 | $1,080 |
| No | 211467905 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | ML180UH070E36B* | 21,600 | $1,080 |
| No | 211467904 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | EL296UH070XV36B* | 22,000 | $1,100 |
| No | 211467903 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | EL296UH070XE36B* | 21,600 | $1,080 |
| No | 211467902 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | EL296UH045XV36B* | 22,200 | $1,110 |
| No | 211467901 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | EL296UH045XE36B* | 21,600 | $1,080 |
| No | 211467900 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | EL280UH090XE48B* | 21,600 | $1,080 |
| No | 211467899 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | EL280UH090E48B* | 21,600 | $1,080 |
| No | 211467898 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | EL280UH090E36B* | 21,800 | $1,090 |
| No | 211467897 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | EL196UH030XE36B* | 21,600 | $1,080 |
| No | 211467896 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | EL195UH060NE36B* | 21,800 | $1,090 |
| No | 211467895 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | EL195UH040NE36B* | 21,400 | $1,070 |
| No | 211467894 | LENNOX | EL22XPV-036-230A** | CX35-30B+TDR | EL180UH080NE48B* | 21,600 | $1,080 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211467633 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | SLP99UH070XV36B* | 22,000 | $1,100 |
| No | 211467632 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | SL297UH060NV36B* | 22,200 | $1,110 |
| No | 211467631 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | SL297UH040NV36B* | 22,000 | $1,100 |
| No | 211467630 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | SL280UH090XV48B* | 21,800 | $1,090 |
| No | 211467629 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | SL280UH090V48B* | 21,800 | $1,090 |
| No | 211467628 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | SL280UH090V36B* | 21,800 | $1,090 |
| No | 211467627 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | SL280UH080NV48B* | 22,000 | $1,100 |
| No | 211467626 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | ML296UH070XV36B* | 22,000 | $1,100 |
| No | 211467625 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | ML296UH045XV36B* | 22,000 | $1,100 |
| No | 211467624 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | ML196UH070XE48B* | 21,800 | $1,090 |
| No | 211467623 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | ML196UH070XE36B* | 21,600 | $1,080 |
| No | 211467622 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | ML196UH030XE36B* | 21,800 | $1,090 |
| No | 211467621 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | ML193UH070XE36B* | 21,800 | $1,090 |
| No | 211467620 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | ML193UH045XE36B* | 21,800 | $1,090 |
| No | 211467619 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | ML193UH030XE36B* | 21,800 | $1,090 |
| No | 211467618 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | ML180UH090XE48B* | 21,600 | $1,080 |
| No | 211467617 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | ML180UH090V48B* | 21,600 | $1,080 |
| No | 211467616 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | ML180UH090E48B* | 21,600 | $1,080 |
| No | 211467615 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | ML180UH070XE36B* | 21,600 | $1,080 |
| No | 211467614 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | ML180UH070V48B* | 21,400 | $1,070 |
| No | 211467613 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | ML180UH070V36B* | 21,600 | $1,080 |
| No | 211467612 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | ML180UH070E36B* | 21,600 | $1,080 |
| No | 211467611 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | EL296UH070XV36B* | 22,000 | $1,100 |
| No | 211467610 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | EL296UH070XE36B* | 21,600 | $1,080 |
| No | 211467609 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | EL296UH045XV36B* | 22,200 | $1,110 |
| No | 211467608 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | EL296UH045XE36B* | 21,600 | $1,080 |
| No | 211467607 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | EL280UH090XE48B* | 21,600 | $1,080 |
| No | 211467606 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | EL280UH090E48B* | 21,600 | $1,080 |
| No | 211467605 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | EL280UH090E36B* | 21,800 | $1,090 |
| No | 211467604 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | EL196UH030XE36B* | 21,600 | $1,080 |
| No | 211467603 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | EL195UH060NE36B* | 21,800 | $1,090 |
| No | 211467602 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | EL195UH040NE36B* | 21,400 | $1,070 |
| No | 211467601 | LENNOX | EL22XPV-036-230A** | C35-30B+TDR+TXV | EL180UH080NE48B* | 21,600 | $1,080 |
| No | 211467893 | LENNOX | EL22XPV-036-230A** | CX35-30A+TDR | SL280UH070XV36A* | 22,000 | $1,100 |
| No | 211467892 | LENNOX | EL22XPV-036-230A** | CX35-30A+TDR | SL280UH070V36A* | 22,000 | $1,100 |
| No | 211467891 | LENNOX | EL22XPV-036-230A** | CX35-30A+TDR | ML180UH070XE36A* | 21,600 | $1,080 |
| No | 211467890 | LENNOX | EL22XPV-036-230A** | CX35-30A+TDR | ML180UH070V36A* | 21,800 | $1,090 |
| No | 211467889 | LENNOX | EL22XPV-036-230A** | CX35-30A+TDR | ML180UH070E36A* | 21,600 | $1,080 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211467888 | LENNOX | EL22XPV-036-230A** | CX35-30A+TDR | ML180UH045XE36A* | 21,400 | $1,070 |
| No | 211467887 | LENNOX | EL22XPV-036-230A** | CX35-30A+TDR | ML180UH045V36A* | 21,600 | $1,080 |
| No | 211467886 | LENNOX | EL22XPV-036-230A** | CX35-30A+TDR | ML180UH045E36A* | 21,400 | $1,070 |
| No | 211467885 | LENNOX | EL22XPV-036-230A** | CX35-30A+TDR | ML180UH030V36A* | 21,600 | $1,080 |
| No | 211467884 | LENNOX | EL22XPV-036-230A** | CX35-30A+TDR | EL280UH070XE36A* | 21,800 | $1,090 |
| No | 211467883 | LENNOX | EL22XPV-036-230A** | CX35-30A+TDR | EL280UH070E36A* | 21,800 | $1,090 |
| No | 211467882 | LENNOX | EL22XPV-036-230A** | CX35-30A+TDR | EL280UH045E36A* | 21,800 | $1,090 |
| No | 211467881 | LENNOX | EL22XPV-036-230A** | CX35-30A+TDR | EL180UH060NE36A* | 21,600 | $1,080 |
| No | 211467880 | LENNOX | EL22XPV-036-230A** | CX35-30A+TDR | EL180UH040NE36A* | 21,600 | $1,080 |
| No | 211467600 | LENNOX | EL22XPV-036-230A** | C35-30A+TDR+TXV | SL280UH070XV36A* | 22,000 | $1,100 |
| No | 211467599 | LENNOX | EL22XPV-036-230A** | C35-30A+TDR+TXV | SL280UH070V36A* | 22,000 | $1,100 |
| No | 211467598 | LENNOX | EL22XPV-036-230A** | C35-30A+TDR+TXV | ML180UH070XE36A* | 21,600 | $1,080 |
| No | 211467597 | LENNOX | EL22XPV-036-230A** | C35-30A+TDR+TXV | ML180UH070V36A* | 21,800 | $1,090 |
| No | 211467596 | LENNOX | EL22XPV-036-230A** | C35-30A+TDR+TXV | ML180UH070E36A* | 21,600 | $1,080 |
| No | 211467595 | LENNOX | EL22XPV-036-230A** | C35-30A+TDR+TXV | ML180UH045XE36A* | 21,400 | $1,070 |
| No | 211467594 | LENNOX | EL22XPV-036-230A** | C35-30A+TDR+TXV | ML180UH045V36A* | 21,600 | $1,080 |
| No | 211467593 | LENNOX | EL22XPV-036-230A** | C35-30A+TDR+TXV | ML180UH045E36A* | 21,400 | $1,070 |
| No | 211467592 | LENNOX | EL22XPV-036-230A** | C35-30A+TDR+TXV | ML180UH030V36A* | 21,600 | $1,080 |
| No | 211467591 | LENNOX | EL22XPV-036-230A** | C35-30A+TDR+TXV | EL280UH070XE36A* | 21,800 | $1,090 |
| No | 211467590 | LENNOX | EL22XPV-036-230A** | C35-30A+TDR+TXV | EL280UH070E36A* | 21,800 | $1,090 |
| No | 211467589 | LENNOX | EL22XPV-036-230A** | C35-30A+TDR+TXV | EL280UH045E36A* | 21,800 | $1,090 |
| No | 211467588 | LENNOX | EL22XPV-036-230A** | C35-30A+TDR+TXV | EL180UH060NE36A* | 21,600 | $1,080 |
| No | 211467587 | LENNOX | EL22XPV-036-230A** | C35-30A+TDR+TXV | EL180UH040NE36A* | 21,600 | $1,080 |
| No | 211467719 | LENNOX | EL22XPV-036-230A** | CBA25UHV-042-230-** | | 22,200 | $1,110 |
| No | 211467718 | LENNOX | EL22XPV-036-230A** | CBA25UHV-036-230-** | | 22,200 | $1,110 |
| No | 211467721 | LENNOX | EL22XPV-036-230A** | CBA27UHE-042-230*+TDR | | 22,200 | $1,110 |
| No | 211467722 | LENNOX | EL22XPV-036-230A** | CBA38MV-042-230*+TDR | | 22,800 | $1,140 |
| No | 211467720 | LENNOX | EL22XPV-036-230A** | CBA27UHE-036-230*+TDR | | 23,000 | $1,150 |
| No | 211467586 | LENNOX | EL22XPV-036-230A** | CBA38MV-036-230*+TDR | | 22,800 | $1,140 |
| No | 211455259 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | SLP99UH110XV60C* | 28,800 | $1,440 |
| No | 211455258 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | SLP99UH090XV60C* | 28,800 | $1,440 |
| No | 211455257 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | SLP99UH090XV48C* | 29,000 | $1,450 |
| No | 211455256 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | SL297UH080NV60C* | 29,000 | $1,450 |
| No | 211455255 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | SL297UH080NV48C* | 29,000 | $1,450 |
| No | 211455254 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | SL280UH110XV60C* | 28,600 | $1,430 |
| No | 211455253 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | SL280UH110V60C* | 28,600 | $1,430 |
| No | 211455252 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | SL280UH100NV60C* | 28,800 | $1,440 |
| No | 211455251 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | SL280UH090XV60C* | 28,400 | $1,420 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211455250 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | SL280UH090V60C* | 28,400 | $1,420 |
| No | 211455249 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | SL280UH080NV60C* | 28,800 | $1,440 |
| No | 211455248 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | ML296UH110XV60C* | 28,600 | $1,430 |
| No | 211455247 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | ML296UH090XV48C* | 28,800 | $1,440 |
| No | 211455246 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | ML196UH110XE60C* | 28,800 | $1,440 |
| No | 211455245 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | ML196UH090XE60C* | 28,600 | $1,430 |
| No | 211455244 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | ML193UH110XE60C* | 28,600 | $1,430 |
| No | 211455243 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | ML180UH110XE60C* | 28,600 | $1,430 |
| No | 211455242 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | ML180UH110V60C* | 28,600 | $1,430 |
| No | 211455241 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | ML180UH110E60C* | 28,600 | $1,430 |
| No | 211455240 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | ML180UH090E60C* | 28,600 | $1,430 |
| No | 211455239 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | EL296UH110XV60C* | 28,800 | $1,440 |
| No | 211455238 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | EL296UH110XV48C* | 29,000 | $1,450 |
| No | 211455237 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | EL296UH110XE60C* | 28,800 | $1,440 |
| No | 211455236 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | EL296UH090XV60C* | 29,000 | $1,450 |
| No | 211455235 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | EL296UH090XV48C* | 29,000 | $1,450 |
| No | 211455234 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | EL280UH110XE60C* | 28,800 | $1,440 |
| No | 211455233 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | EL280UH110E60C* | 28,800 | $1,440 |
| No | 211455232 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | EL280UH110E48C* | 28,400 | $1,420 |
| No | 211455231 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | EL196UH110XE60C* | 28,800 | $1,440 |
| No | 211455230 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | EL195UH100NE60C* | 28,800 | $1,440 |
| No | 211455229 | LENNOX | EL22XPV-048-230A** | CX35-60C+TDR | EL180UH100NE60C* | 28,800 | $1,440 |
| No | 211455165 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | SLP99UH110XV60C* | 28,800 | $1,440 |
| No | 211455164 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | SLP99UH090XV60C* | 28,800 | $1,440 |
| No | 211455163 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | SLP99UH090XV48C* | 29,000 | $1,450 |
| No | 211455162 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | SL297UH080NV60C* | 29,000 | $1,450 |
| No | 211455161 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | SL297UH080NV48C* | 29,000 | $1,450 |
| No | 211455160 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | SL280UH110XV60C* | 28,600 | $1,430 |
| No | 211455159 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | SL280UH110V60C* | 28,600 | $1,430 |
| No | 211455158 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | SL280UH100NV60C* | 28,800 | $1,440 |
| No | 211455157 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | SL280UH090XV60C* | 28,400 | $1,420 |
| No | 211455156 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | SL280UH090V60C* | 28,400 | $1,420 |
| No | 211455155 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | SL280UH080NV60C* | 28,800 | $1,440 |
| No | 211455154 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | ML296UH110XV60C* | 28,600 | $1,430 |
| No | 211455153 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | ML296UH090XV48C* | 28,800 | $1,440 |
| No | 211455152 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | ML196UH110XE60C* | 28,800 | $1,440 |
| No | 211455151 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | ML196UH090XE60C* | 28,600 | $1,430 |
| No | 211455150 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | ML193UH110XE60C* | 28,600 | $1,430 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211455149 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | ML180UH110XE60C* | 28,600 | $1,430 |
| No | 211455148 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | ML180UH110V60C* | 28,600 | $1,430 |
| No | 211455147 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | ML180UH110E60C* | 28,600 | $1,430 |
| No | 211455146 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | ML180UH090E60C* | 28,600 | $1,430 |
| No | 211455145 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | EL296UH110XV60C* | 28,800 | $1,440 |
| No | 211455144 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | EL296UH110XV48C* | 29,000 | $1,450 |
| No | 211455143 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | EL296UH110XE60C* | 28,800 | $1,440 |
| No | 211455142 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | EL296UH090XV60C* | 29,000 | $1,450 |
| No | 211455141 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | EL296UH090XV48C* | 29,000 | $1,450 |
| No | 211455140 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | EL280UH110XE60C* | 28,800 | $1,440 |
| No | 211455139 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | EL280UH110E60C* | 28,800 | $1,440 |
| No | 211455138 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | EL280UH110E48C* | 28,400 | $1,420 |
| No | 211455137 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | EL196UH110XE60C* | 28,800 | $1,440 |
| No | 211455136 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | EL195UH100NE60C* | 28,800 | $1,440 |
| No | 211455135 | LENNOX | EL22XPV-048-230A** | C35-60C+TDR+TXV | EL180UH100NE60C* | 28,800 | $1,440 |
| No | 211455228 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | SLP99UH110XV60C* | 28,200 | $1,410 |
| No | 211455227 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | SLP99UH090XV60C* | 28,200 | $1,410 |
| No | 211455226 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | SLP99UH090XV48C* | 28,400 | $1,420 |
| No | 211455225 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | SL297UH080NV60C* | 28,400 | $1,420 |
| No | 211455224 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | SL297UH080NV48C* | 28,400 | $1,420 |
| No | 211455223 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | SL280UH110XV60C* | 28,200 | $1,410 |
| No | 211455222 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | SL280UH110V60C* | 28,200 | $1,410 |
| No | 211455221 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | SL280UH100NV60C* | 28,200 | $1,410 |
| No | 211455220 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | SL280UH090XV60C* | 27,800 | $1,390 |
| No | 211455219 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | SL280UH090V60C* | 27,800 | $1,390 |
| No | 211455218 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | SL280UH080NV60C* | 28,200 | $1,410 |
| No | 211455217 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | ML296UH110XV60C* | 28,000 | $1,400 |
| No | 211455216 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | ML296UH090XV48C* | 28,400 | $1,420 |
| No | 211455215 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | ML196UH110XE60C* | 28,200 | $1,410 |
| No | 211455214 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | ML196UH090XE60C* | 28,000 | $1,400 |
| No | 211455213 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | ML193UH110XE60C* | 28,000 | $1,400 |
| No | 211455212 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | ML180UH110XE60C* | 28,000 | $1,400 |
| No | 211455211 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | ML180UH110V60C* | 28,000 | $1,400 |
| No | 211455210 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | ML180UH110E60C* | 28,000 | $1,400 |
| No | 211455209 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | ML180UH090E60C* | 28,000 | $1,400 |
| No | 211455208 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | EL296UH110XV60C* | 28,200 | $1,410 |
| No | 211455207 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | EL296UH110XV48C* | 28,400 | $1,420 |
| No | 211455206 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | EL296UH110XE60C* | 28,200 | $1,410 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211455205 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | EL296UH090XV60C* | 28,400 | $1,420 |
| No | 211455204 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | EL296UH090XV48C* | 28,400 | $1,420 |
| No | 211455203 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | EL280UH110XE60C* | 28,000 | $1,400 |
| No | 211455202 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | EL280UH110E60C* | 28,000 | $1,400 |
| No | 211455201 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | EL280UH110E48C* | 27,800 | $1,390 |
| No | 211455200 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | EL196UH110XE60C* | 28,200 | $1,410 |
| No | 211455199 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | EL195UH100NE60C* | 28,400 | $1,420 |
| No | 211455198 | LENNOX | EL22XPV-048-230A** | CHX35-51/61C-**-*+TDR | EL180UH100NE60C* | 28,200 | $1,410 |
| No | 211455197 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | SLP99UH110XV60C* | 28,400 | $1,420 |
| No | 211455196 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | SLP99UH090XV60C* | 28,400 | $1,420 |
| No | 211455195 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | SLP99UH090XV48C* | 28,600 | $1,430 |
| No | 211455194 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | SL297UH080NV60C* | 28,400 | $1,420 |
| No | 211455193 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | SL297UH080NV48C* | 28,400 | $1,420 |
| No | 211455192 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | SL280UH110XV60C* | 28,200 | $1,410 |
| No | 211455191 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | SL280UH110V60C* | 28,200 | $1,410 |
| No | 211455190 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | SL280UH100NV60C* | 28,400 | $1,420 |
| No | 211455189 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | SL280UH090XV60C* | 28,000 | $1,400 |
| No | 211455188 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | SL280UH090V60C* | 28,000 | $1,400 |
| No | 211455187 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | SL280UH080NV60C* | 28,200 | $1,410 |
| No | 211455186 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | ML296UH110XV60C* | 28,200 | $1,410 |
| No | 211455185 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | ML296UH090XV48C* | 28,400 | $1,420 |
| No | 211455184 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | ML196UH110XE60C* | 28,200 | $1,410 |
| No | 211455183 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | ML196UH090XE60C* | 28,200 | $1,410 |
| No | 211455182 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | ML193UH110XE60C* | 28,000 | $1,400 |
| No | 211455273 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | ML193UH110XE48C* | 27,800 | $1,390 |
| No | 211455272 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | ML193UH090XE48C* | 28,000 | $1,400 |
| No | 211455181 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | ML180UH110XE60C* | 28,000 | $1,400 |
| No | 211455180 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | ML180UH110V60C* | 28,000 | $1,400 |
| No | 211455179 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | ML180UH110E60C* | 28,000 | $1,400 |
| No | 211455178 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | ML180UH090E60C* | 28,000 | $1,400 |
| No | 211455177 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | EL296UH110XV60C* | 28,400 | $1,420 |
| No | 211455176 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | EL296UH110XV48C* | 28,600 | $1,430 |
| No | 211455175 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | EL296UH110XE60C* | 28,200 | $1,410 |
| No | 211455174 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | EL296UH090XV60C* | 28,400 | $1,420 |
| No | 211455173 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | EL296UH090XV48C* | 28,600 | $1,430 |
| No | 211455172 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | EL280UH110XE60C* | 28,200 | $1,410 |
| No | 211455171 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | EL280UH110E60C* | 28,200 | $1,410 |
| No | 211455170 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | EL280UH110E48C* | 27,800 | $1,390 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211455169 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | EL196UH110XE60C* | 28,200 | $1,410 |
| No | 211455271 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | EL195UH100NE60C* | 28,400 | $1,420 |
| No | 211455270 | LENNOX | EL22XPV-048-230A** | CHX35-48C-**-*+TDR | EL180UH100NE60C* | 28,400 | $1,420 |
| No | 211455261 | LENNOX | EL22XPV-048-230A** | CBA25UH-060-230-** | | 28,200 | $1,410 |
| No | 211455263 | LENNOX | EL22XPV-048-230A** | CBA25UHV-060-230-** | | 28,000 | $1,400 |
| No | 211455262 | LENNOX | EL22XPV-048-230A** | CBA25UHV-048-230-** | | 28,600 | $1,430 |
| No | 211455166 | LENNOX | EL22XPV-048-230A** | CBA27UHE-048-230*+TDR | | 27,800 | $1,390 |
| No | 211455168 | LENNOX | EL22XPV-048-230A** | CBA38MV-048-230*+TDR | | 28,400 | $1,420 |
| No | 211455167 | LENNOX | EL22XPV-048-230A** | CBA27UHE-060-230*+TDR | | 27,000 | $1,350 |
| No | 211455134 | LENNOX | EL22XPV-048-230A** | CBA38MV-060-230*+TDR | | 27,200 | $1,360 |
| No | 204631570 | LENNOX | VPB036H4M-3P | Heat pump without ducts | | 28,000 | $1,400 |
| No | 204631569 | LENNOX | VPB036H4M-3P | Heat pump with ducts | | 28,000 | $1,400 |
| No | 207699112 | LENNOX | MPC030S4M-1P | Combinaison d'unités avec et sans conduits | | 16,000 | $800 |
| No | 207699118 | LENNOX | MPC024S4M-1P | Combinaison d'unités avec et sans conduits | | 15,165 | $758 |
| No | 207768723 | LENNOX | MPC018S4M-1P | Combinaison d'unités avec et sans conduits | | 11,000 | $550 |
| No | 10062016 | LENNOX | MPB048S4M-1P | Heat pump without ducts | | 29,600 | $1,480 |
| No | 201796628 | LENNOX | MPB009S4S-1L | MWMB009S4-2L | | 6,500 | $325 |
| No | 207699097 | LENNOX | MLB036S4S-2P | MCFA036S4-2P | | 25,000 | $1,250 |
| No | 207768732 | LENNOX | MLB030S4M-1P | Combinaison d'unités avec et sans conduits | | 17,152 | $858 |
| No | 207768729 | LENNOX | MLB018S4M-1P | Combinaison d'unités avec et sans conduits | | 11,000 | $550 |
| No | 204330673 | LENNOX | MLA036S4M-1P | Heat pump with ducts | | 24,600 | $1,230 |
| No | 10093941 | LENNOX | XP20-024-230A** | CX35-30B+TDR | EL296UH045XV36B | 13,000 | $650 |
| No | 10093927 | LENNOX | XP20-024-230A** | C35-30B+TDR+TXV | EL296UH045XV36B | 13,000 | $650 |
| No | 10093928 | LENNOX | XP20-024-230A** | C35-30B+TDR+TXV | EL296UH070XV36B | 13,000 | $650 |
| No | 10093945 | LENNOX | XP20-024-230A** | CX35-30B+TDR | SLP98UH070XV36B | 13,000 | $650 |
| No | 10093931 | LENNOX | XP20-024-230A** | C35-30B+TDR+TXV | SLP98UH070XV36B | 13,000 | $650 |
| No | 10093942 | LENNOX | XP20-024-230A** | CX35-30B+TDR | EL296UH070XV36B | 13,000 | $650 |
| No | 201953305 | LENNOX | XP20-036-230A** | CBA38MV-042-230*+TDR | | 21,400 | $1,070 |
| No | 201842142 | LENNOX | XP20-024-230A** | CBA38MV-018/024-230*+TDR | | 13,600 | $680 |
| No | 201842143 | LENNOX | XP20-024-230A** | CBA38MV-030-230*+TDR | | 14,000 | $700 |
| No | 202192030 | LENNOX | XP20-024-230A** | CHX35-30B-**-*+TDR | EL296UH045XV36B* | 14,400 | $720 |
| No | 202192031 | LENNOX | XP20-024-230A** | CHX35-30B-**-*+TDR | EL296UH070XV36B* | 14,400 | $720 |
| No | 202192033 | LENNOX | XP20-024-230A** | CHX35-30B-**-*+TDR | SLP98UH070XV36B-** | 14,400 | $720 |
| No | 8550432 | LENNOX | XP20-024-230A** | CR33-48B*+TDR+TXV | EL296DF045XV36B* | 14,700 | $735 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 8550433 | LENNOX | XP20-024-230A** | CR33-48B*+TDR+TXV | SLP98DF070XV36B-** | 14,700 | $735 |
| No | 8550434 | LENNOX | XP20-024-230A** | CR33-48B*+TDR+TXV | SLP98DF090XV36C-** | 14,700 | $735 |
| No | 203237240 | LENNOX | XP20-036-230A** | CR33-50/60*+TDR+TXV | EL296DF090XV60C* | 21,200 | $1,060 |
| No | 202192038 | LENNOX | XP20-036-230A** | CHX35-48C-**-*+TDR | EL296UH090XV36C* | 21,600 | $1,080 |
| No | 203237241 | LENNOX | XP20-036-230A** | CR33-50/60*+TDR+TXV | EL296DF110XV60C* | 21,200 | $1,060 |
| No | 8550482 | LENNOX | XP20-036-230A** | CR33-50/60*+TDR+TXV | SLP98DF090XV36C-** | 21,200 | $1,060 |
| No | 201842144 | LENNOX | XP20-048-230A** | CBA38MV-060-230*+TDR | | 26,400 | $1,320 |
| No | 201842145 | LENNOX | XP20-060-230A** | CBA38MV-060-230*+TDR | | 36,200 | $1,810 |
| No | 202189867 | LENNOX | XP20-060-230A** | CHX35-60D-**-*+TDR | SLP98UH135XV60D-** | 36,600 | $1,830 |
| No | 202189875 | LENNOX | XP20-048-230A** | CHX35-60D-**-*+TDR | SLP98UH135XV60D-** | 29,200 | $1,460 |
| No | 202189869 | LENNOX | XP20-060-230A** | CHX35-60D-**-*+TDR | EL296UH135XV60D* | 36,600 | $1,830 |
| No | 8561579 | LENNOX | XP20-060-230A** | CR33-60+TDR | EL296DF090XV60C-** | 36,400 | $1,820 |
| No | 8561580 | LENNOX | XP20-060-230A** | CR33-60+TDR | EL296DF110XV60C-** | 36,400 | $1,820 |
| No | 8561583 | LENNOX | XP20-060-230A** | CR33-60+TDR | SLP98DF090XV60C* | 36,400 | $1,820 |
| No | 10092279 | LENNOX | XP25-024-230-** | C35-36B+TDR+TXV | EL296UH045XV36B* | 13,800 | $690 |
| No | 8561584 | LENNOX | XP20-060-230A** | CR33-60+TDR | SLP98DF110XV60C-** | 36,400 | $1,820 |
| No | 10092280 | LENNOX | XP25-024-230-** | C35-36B+TDR+TXV | EL296UH070XV36B* | 13,800 | $690 |
| No | 10092281 | LENNOX | XP25-024-230-** | C35-36B+TDR+TXV | SLP98DF070XV36B* | 13,800 | $690 |
| No | 201953308 | LENNOX | XP25-024-230-** | CBA38MV-036-230*+TDR | | 13,600 | $680 |
| No | 202192157 | LENNOX | XP25-024-230-** | CHX35-42B-**-*+TDR | EL296UH045XV36B* | 14,600 | $730 |
| No | 202192158 | LENNOX | XP25-024-230-** | CHX35-42B-**-*+TDR | EL296UH070XV36B* | 14,600 | $730 |
| No | 202192160 | LENNOX | XP25-024-230-** | CHX35-42C-**-*+TDR | EL296UH090XV36C* | 14,200 | $710 |
| No | 202192159 | LENNOX | XP25-024-230-** | CHX35-42B-**-*+TDR | SLP98UH070XV36B* | 14,600 | $730 |
| No | 202192161 | LENNOX | XP25-024-230-** | CHX35-42C-**-*+TDR | SLP98UH090XV36C* | 14,200 | $710 |
| No | 10092245 | LENNOX | XP25-024-230-** | CX35-36B+TDR | EL296UH045XV36B* | 13,800 | $690 |
| No | 10092246 | LENNOX | XP25-024-230-** | CX35-36B+TDR | EL296UH070XV36B* | 13,800 | $690 |
| No | 10444469 | LENNOX | XP25-024-230-** | CX35-36B+TDR | SLP98UH070XV36B* | 13,800 | $690 |
| No | 202192165 | LENNOX | XP25-036-230-** | CHX35-42B-**-*+TDR | SLP98UH070XV36B* | 19,600 | $980 |
| No | 202192164 | LENNOX | XP25-036-230-** | CHX35-42B-**-*+TDR | EL296UH070XV36B* | 19,800 | $990 |
| No | 7133800 | LENNOX | XP25-036-230-** | CR33-50/60*+TDR+TXV | SLP98DF070XV36B* | 20,000 | $1,000 |
| No | 202192163 | LENNOX | XP25-036-230-** | CHX35-42B-**-*+TDR | EL296UH045XV36B* | 19,800 | $990 |
| No | 201930688 | LENNOX | XP25-036-230-** | CBA38MV-042-230*+TDR | | 21,400 | $1,070 |
| No | 5947719 | LENNOX | XP25-036-230-** | CR33-50/60*+TDR+TXV | SLP98DF090XV36C-** | 20,000 | $1,000 |
| No | 201924837 | LENNOX | XP25-048-230-** | CBA38MV-048-230*+TDR | | 31,600 | $1,580 |
| No | 202073556 | LENNOX | XP25-048-230-** | CBA38MV-060-230*+TDR | | 30,000 | $1,500 |
| No | 5947775 | LENNOX | XP25-048-230-** | CR33-50/60*+TDR+TXV | EL296DF090XV60C-** | 30,400 | $1,520 |
| No | 5947776 | LENNOX | XP25-048-230-** | CR33-50/60*+TDR+TXV | EL296DF110XV60C-** | 30,400 | $1,520 |
| No | 5947779 | LENNOX | XP25-048-230-** | CR33-50/60*+TDR+TXV | SLP98DF090XV48C-** | 30,400 | $1,520 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 5947780 | LENNOX | XP25-048-230-** | CR33-50/60*+TDR+TXV | SLP98DF090XV60C-** | 30,400 | $1,520 |
| No | 5947849 | LENNOX | XP25-048-230-** | CR33-60+TDR | EL296DF090XV60C-** | 30,400 | $1,520 |
| No | 5947781 | LENNOX | XP25-048-230-** | CR33-50/60*+TDR+TXV | SLP98DF110XV60C-** | 30,400 | $1,520 |
| No | 5947853 | LENNOX | XP25-048-230-** | CR33-60+TDR | SLP98DF090XV48C-** | 30,400 | $1,520 |
| No | 5947850 | LENNOX | XP25-048-230-** | CR33-60+TDR | EL296DF110XV60C-** | 30,400 | $1,520 |
| No | 5947854 | LENNOX | XP25-048-230-** | CR33-60+TDR | SLP98DF110XV60C-** | 30,400 | $1,520 |
| No | 5947857 | LENNOX | XP25-060-230-** | CR33-60+TDR | EL296DF110XV60C-** | 35,600 | $1,780 |
| No | 202327813 | LENNOX | XP25-048-230-** | CX35-49C+TDR | SLP98UH110XV60C* | 30,000 | $1,500 |
| No | 5947856 | LENNOX | XP25-060-230-** | CR33-60+TDR | EL296DF090XV60C-** | 35,600 | $1,780 |
| No | 201930689 | LENNOX | XP25-060-230-** | CBA38MV-060-230*+TDR | | 36,000 | $1,800 |
| No | 7979864 | LENNOX | XP25-060-230-** | CR33-60+TDR | SLP98DF090XV60C* | 35,600 | $1,780 |
| No | 5947861 | LENNOX | XP25-060-230-** | CR33-60+TDR | SLP98DF110XV60C-** | 35,600 | $1,780 |
| No | 202192167 | LENNOX | XP25-048-230-** | CHX35-60D-**-*+TDR | EL296UH135XV60D* | 30,200 | $1,510 |
| No | 202192168 | LENNOX | XP25-048-230-** | CHX35-60D-**-*+TDR | SLP98UH135XV60D* | 30,200 | $1,510 |
| No | 206322109 | LENNOX | XP20-036-230B** | CX35-60D+TDR | SLP99UH135XV60D* | 20,200 | $1,010 |
| No | 205743238 | LENNOX | XP20-036-230B** | CX35-60D+TDR | EL296UH135XV60D* | 20,200 | $1,010 |
| No | 206322106 | LENNOX | XP20-036-230B** | CX35-48C+TDR | SLP99UH090XV48C* | 20,600 | $1,030 |
| No | 206322107 | LENNOX | XP20-036-230B** | CX35-48C+TDR | SLP99UH090XV60C* | 20,600 | $1,030 |
| No | 206322108 | LENNOX | XP20-036-230B** | CX35-48C+TDR | SLP99UH110XV60C* | 20,400 | $1,020 |
| No | 206322105 | LENNOX | XP20-036-230B** | CX35-48C+TDR | SLP99UH090XV36C* | 20,600 | $1,030 |
| No | 205743231 | LENNOX | XP20-036-230B** | CX35-48C+TDR | SL297UH080NV48C* | 20,600 | $1,030 |
| No | 205743233 | LENNOX | XP20-036-230B** | CX35-48C+TDR | SL297UH080NV60C* | 20,400 | $1,020 |
| No | 205743221 | LENNOX | XP20-036-230B** | CX35-48C+TDR | EL296UH090XV48C* | 20,600 | $1,030 |
| No | 205743223 | LENNOX | XP20-036-230B** | CX35-48C+TDR | EL296UH110XV48C* | 20,400 | $1,020 |
| No | 205743222 | LENNOX | XP20-036-230B** | CX35-48C+TDR | EL296UH090XV60C* | 20,600 | $1,030 |
| No | 205743220 | LENNOX | XP20-036-230B** | CX35-48C+TDR | EL296UH090XV36C* | 20,600 | $1,030 |
| No | 205743211 | LENNOX | XP20-036-230B** | CX35-48B+TDR | EL296UH070XV36B* | 20,800 | $1,040 |
| No | 205743216 | LENNOX | XP20-036-230B** | CX35-48B+TDR | SL297UH040NV36B* | 20,600 | $1,030 |
| No | 205743218 | LENNOX | XP20-036-230B** | CX35-48B+TDR | SL297UH060NV36B* | 20,600 | $1,030 |
| No | 205743210 | LENNOX | XP20-036-230B** | CX35-48B+TDR | EL296UH045XV36B* | 20,600 | $1,030 |
| No | 205743224 | LENNOX | XP20-036-230B** | CX35-48C+TDR | EL296UH110XV60C* | 20,400 | $1,020 |
| No | 206322103 | LENNOX | XP20-036-230B** | CX35-36B+TDR | SLP99UH070XV36B* | 20,600 | $1,030 |
| No | 205743207 | LENNOX | XP20-036-230B** | CX35-36B+TDR | SL297UH040NV36B* | 20,400 | $1,020 |
| No | 205743208 | LENNOX | XP20-036-230B** | CX35-36B+TDR | SL297UH060NV36B* | 20,600 | $1,030 |
| No | 205743202 | LENNOX | XP20-036-230B** | CX35-36B+TDR | EL296UH070XV36B* | 20,600 | $1,030 |
| No | 205743201 | LENNOX | XP20-036-230B** | CX35-36B+TDR | EL296UH045XV36B* | 20,600 | $1,030 |
| No | 206322102 | LENNOX | XP20-036-230B** | CR33-50/60+TDR+TXV | SLP99DF110XV60C* | 20,600 | $1,030 |
| No | 206322101 | LENNOX | XP20-036-230B** | CR33-50/60+TDR+TXV | SLP99DF090XV60C* | 20,600 | $1,030 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206322100 | LENNOX | XP20-036-230B** | CR33-50/60+TDR+TXV | SLP99DF090XV48C* | 20,600 | $1,030 |
| No | 206322099 | LENNOX | XP20-036-230B** | CR33-50/60+TDR+TXV | SLP99DF090XV36C* | 20,600 | $1,030 |
| No | 206322098 | LENNOX | XP20-036-230B** | CR33-48C*+TDR+TXV | SLP99DF110XV60C* | 21,400 | $1,070 |
| No | 205743191 | LENNOX | XP20-036-230B** | CR33-50/60+TDR+TXV | EL296DF110XV60C* | 20,600 | $1,030 |
| No | 205743190 | LENNOX | XP20-036-230B** | CR33-50/60+TDR+TXV | EL296DF090XV60C* | 20,600 | $1,030 |
| No | 206322096 | LENNOX | XP20-036-230B** | CR33-48C*+TDR+TXV | SLP99DF090XV48C* | 21,400 | $1,070 |
| No | 206322097 | LENNOX | XP20-036-230B** | CR33-48C*+TDR+TXV | SLP99DF090XV60C* | 21,400 | $1,070 |
| No | 206322104 | LENNOX | XP20-036-230B** | CX35-48B+TDR | SLP99UH070XV36B* | 20,800 | $1,040 |
| No | 206322094 | LENNOX | XP20-036-230B** | CR33-48B*+TDR+TXV | SLP99DF070XV36B* | 21,600 | $1,080 |
| No | 205743178 | LENNOX | XP20-036-230B** | CR33-48B*+TDR+TXV | EL296DF070XV48B* | 21,600 | $1,080 |
| No | 205743182 | LENNOX | XP20-036-230B** | CR33-48C*+TDR+TXV | EL296DF110XV60C* | 21,400 | $1,070 |
| No | 205743177 | LENNOX | XP20-036-230B** | CR33-48B*+TDR+TXV | EL296DF045XV36B* | 21,600 | $1,080 |
| No | 205743181 | LENNOX | XP20-036-230B** | CR33-48C*+TDR+TXV | EL296DF090XV60C* | 21,400 | $1,070 |
| No | 206322095 | LENNOX | XP20-036-230B** | CR33-48C*+TDR+TXV | SLP99DF090XV36C* | 21,400 | $1,070 |
| No | 205743172 | LENNOX | XP20-036-230B** | CHX35-51/61C-**-*+TDR | SL297UH080NV60C* | 20,200 | $1,010 |
| No | 206322090 | LENNOX | XP20-036-230B** | CHX35-51/61C-**-*+TDR | SLP99UH090XV36C* | 20,200 | $1,010 |
| No | 205743171 | LENNOX | XP20-036-230B** | CHX35-51/61C-**-*+TDR | SL297UH080NV48C* | 20,200 | $1,010 |
| No | 206322092 | LENNOX | XP20-036-230B** | CHX35-51/61C-**-*+TDR | SLP99UH090XV60C* | 20,200 | $1,010 |
| No | 206322093 | LENNOX | XP20-036-230B** | CHX35-51/61C-**-*+TDR | SLP99UH110XV60C* | 20,000 | $1,000 |
| No | 205743164 | LENNOX | XP20-036-230B** | CHX35-51/61C-**-*+TDR | EL296UH110XV60C* | 20,000 | $1,000 |
| No | 205743160 | LENNOX | XP20-036-230B** | CHX35-51/61C-**-*+TDR | EL296UH090XV36C* | 20,200 | $1,010 |
| No | 205743161 | LENNOX | XP20-036-230B** | CHX35-51/61C-**-*+TDR | EL296UH090XV48C* | 20,200 | $1,010 |
| No | 205743163 | LENNOX | XP20-036-230B** | CHX35-51/61C-**-*+TDR | EL296UH110XV48C* | 20,000 | $1,000 |
| No | 205743162 | LENNOX | XP20-036-230B** | CHX35-51/61C-**-*+TDR | EL296UH090XV60C* | 20,200 | $1,010 |
| No | 205743157 | LENNOX | XP20-036-230B** | CHX35-48B-**-*+TDR | SL297UH060NV36B* | 20,600 | $1,030 |
| No | 205743150 | LENNOX | XP20-036-230B** | CHX35-48B-**-*+TDR | EL296UH045XV36B* | 20,600 | $1,030 |
| No | 205743156 | LENNOX | XP20-036-230B** | CHX35-48B-**-*+TDR | SL297UH040NV36B* | 20,600 | $1,030 |
| No | 206322088 | LENNOX | XP20-036-230B** | CH35-51C+TDR+TXV | SLP99UH110XV60C* | 20,000 | $1,000 |
| No | 206322086 | LENNOX | XP20-036-230B** | CH35-51C+TDR+TXV | SLP99UH090XV48C* | 20,200 | $1,010 |
| No | 205743145 | LENNOX | XP20-036-230B** | CH35-51C+TDR+TXV | SL297UH080NV60C* | 20,200 | $1,010 |
| No | 205743135 | LENNOX | XP20-036-230B** | CH35-51C+TDR+TXV | EL296UH110XV60C* | 20,000 | $1,000 |
| No | 205743144 | LENNOX | XP20-036-230B** | CH35-51C+TDR+TXV | SL297UH080NV48C* | 20,200 | $1,010 |
| No | 206322091 | LENNOX | XP20-036-230B** | CHX35-51/61C-**-*+TDR | SLP99UH090XV48C* | 20,200 | $1,010 |
| No | 206322087 | LENNOX | XP20-036-230B** | CH35-51C+TDR+TXV | SLP99UH090XV60C* | 20,200 | $1,010 |
| No | 205743151 | LENNOX | XP20-036-230B** | CHX35-48B-**-*+TDR | EL296UH070XV36B* | 20,800 | $1,040 |
| No | 206322085 | LENNOX | XP20-036-230B** | CH35-51C+TDR+TXV | SLP99UH090XV36C* | 20,200 | $1,010 |
| No | 206322089 | LENNOX | XP20-036-230B** | CHX35-48B-**-*+TDR | SLP99UH070XV36B* | 20,600 | $1,030 |
| No | 206322084 | LENNOX | XP20-036-230B** | CH35-48B+TDR+TXV | SLP99UH070XV36B* | 20,600 | $1,030 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205743133 | LENNOX | XP20-036-230B** | CH35-51C+TDR+TXV | EL296UH090XV60C* | 20,200 | $1,010 |
| No | 205743130 | LENNOX | XP20-036-230B** | CH35-51C+TDR+TXV | EL296UH090XV36C* | 20,200 | $1,010 |
| No | 205743134 | LENNOX | XP20-036-230B** | CH35-51C+TDR+TXV | EL296UH110XV48C* | 20,000 | $1,000 |
| No | 205743132 | LENNOX | XP20-036-230B** | CH35-51C+TDR+TXV | EL296UH090XV48C* | 20,200 | $1,010 |
| No | 205743128 | LENNOX | XP20-036-230B** | CH35-48B+TDR+TXV | SL297UH060NV36B* | 20,600 | $1,030 |
| No | 205743127 | LENNOX | XP20-036-230B** | CH35-48B+TDR+TXV | SL297UH040NV36B* | 20,600 | $1,030 |
| No | 206322083 | LENNOX | XP20-036-230B** | CH23-65+TDR+TXV | SLP99UH135XV60D* | 20,600 | $1,030 |
| No | 205743122 | LENNOX | XP20-036-230B** | CH35-48B+TDR+TXV | EL296UH070XV36B* | 20,800 | $1,040 |
| No | 206322081 | LENNOX | XP20-036-230B** | CH23-65+TDR+TXV | SLP99UH090XV60C* | 20,600 | $1,030 |
| No | 205743121 | LENNOX | XP20-036-230B** | CH35-48B+TDR+TXV | EL296UH045XV36B* | 20,600 | $1,030 |
| No | 206322082 | LENNOX | XP20-036-230B** | CH23-65+TDR+TXV | SLP99UH110XV60C* | 20,600 | $1,030 |
| No | 206322080 | LENNOX | XP20-036-230B** | CH23-65+TDR+TXV | SLP99UH090XV48C* | 20,600 | $1,030 |
| No | 206322079 | LENNOX | XP20-036-230B** | CH23-65+TDR+TXV | SLP99UH090XV36C* | 20,800 | $1,040 |
| No | 205743111 | LENNOX | XP20-036-230B** | CH23-65+TDR+TXV | SL297UH060NV36B* | 20,800 | $1,040 |
| No | 206322078 | LENNOX | XP20-036-230B** | CH23-65+TDR+TXV | SLP99UH070XV36B* | 21,000 | $1,050 |
| No | 205743112 | LENNOX | XP20-036-230B** | CH23-65+TDR+TXV | SL297UH080NV48C* | 20,600 | $1,030 |
| No | 205743113 | LENNOX | XP20-036-230B** | CH23-65+TDR+TXV | SL297UH080NV60C* | 20,600 | $1,030 |
| No | 205743093 | LENNOX | XP20-036-230B** | CH23-65+TDR+TXV | EL296UH110XV60C* | 20,600 | $1,030 |
| No | 205743094 | LENNOX | XP20-036-230B** | CH23-65+TDR+TXV | EL296UH135XV60D* | 20,600 | $1,030 |
| No | 205743089 | LENNOX | XP20-036-230B** | CH23-65+TDR+TXV | EL296UH090XV36C* | 20,800 | $1,040 |
| No | 205743087 | LENNOX | XP20-036-230B** | CH23-65+TDR+TXV | EL296UH070XV36B* | 21,000 | $1,050 |
| No | 205743092 | LENNOX | XP20-036-230B** | CH23-65+TDR+TXV | EL296UH110XV48C* | 20,600 | $1,030 |
| No | 205743086 | LENNOX | XP20-036-230B** | CH23-65+TDR+TXV | EL296UH045XV36B* | 21,000 | $1,050 |
| No | 205743091 | LENNOX | XP20-036-230B** | CH23-65+TDR+TXV | EL296UH090XV60C* | 20,600 | $1,030 |
| No | 205743083 | LENNOX | XP20-036-230B** | CBA38MV-030-230*+TDR | | 20,800 | $1,040 |
| No | 205743084 | LENNOX | XP20-036-230B** | CBA38MV-042-230*+TDR | | 19,400 | $970 |
| No | 206322077 | LENNOX | XP20-036-230B** | C35-60D+TDR+TXV | SLP99UH135XV60D* | 20,200 | $1,010 |
| No | 206361977 | LENNOX | XP20-036-230B** | C35-48C+TDR+TXV | SLP99UH110XV60C* | 20,400 | $1,020 |
| No | 206361976 | LENNOX | XP20-036-230B** | C35-48C+TDR+TXV | SLP99UH090XV60C* | 20,600 | $1,030 |
| No | 205743080 | LENNOX | XP20-036-230B** | C35-60D+TDR+TXV | EL296UH135XV60D* | 20,200 | $1,010 |
| No | 206361973 | LENNOX | XP20-036-230B** | C35-48C+TDR+TXV | SL297UH080NV60C* | 20,400 | $1,020 |
| No | 206361975 | LENNOX | XP20-036-230B** | C35-48C+TDR+TXV | SLP99UH090XV48C* | 20,600 | $1,030 |
| No | 206361974 | LENNOX | XP20-036-230B** | C35-48C+TDR+TXV | SLP99UH090XV36C* | 20,600 | $1,030 |
| No | 205743037 | LENNOX | XP20-036-230B** | CBA38MV-036-230*+TDR | | 20,800 | $1,040 |
| No | 206361972 | LENNOX | XP20-036-230B** | C35-48C+TDR+TXV | SL297UH080NV48C* | 20,600 | $1,030 |
| No | 206361964 | LENNOX | XP20-036-230B** | C35-48C+TDR+TXV | EL296UH110XV48C* | 20,400 | $1,020 |
| No | 206361965 | LENNOX | XP20-036-230B** | C35-48C+TDR+TXV | EL296UH110XV60C* | 20,400 | $1,020 |
| No | 206361963 | LENNOX | XP20-036-230B** | C35-48C+TDR+TXV | EL296UH090XV60C* | 20,600 | $1,030 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206322072 | LENNOX | XP20-036-230B** | C35-48B+TDR+TXV | SLP99UH070XV36B* | 20,800 | $1,040 |
| No | 206361961 | LENNOX | XP20-036-230B** | C35-48C+TDR+TXV | EL296UH090XV36C* | 20,600 | $1,030 |
| No | 206361962 | LENNOX | XP20-036-230B** | C35-48C+TDR+TXV | EL296UH090XV48C* | 20,600 | $1,030 |
| No | 205743071 | LENNOX | XP20-036-230B** | C35-48B+TDR+TXV | SL297UH060NV36B* | 20,600 | $1,030 |
| No | 205743070 | LENNOX | XP20-036-230B** | C35-48B+TDR+TXV | SL297UH040NV36B* | 20,600 | $1,030 |
| No | 205743051 | LENNOX | XP20-036-230B** | C35-48B+TDR+TXV | EL296UH045XV36B* | 20,600 | $1,030 |
| No | 206322071 | LENNOX | XP20-036-230B** | C35-36B+TDR+TXV | SLP99UH070XV36B* | 20,600 | $1,030 |
| No | 205743052 | LENNOX | XP20-036-230B** | C35-48B+TDR+TXV | EL296UH070XV36B* | 20,800 | $1,040 |
| No | 205743049 | LENNOX | XP20-036-230B** | C35-36B+TDR+TXV | SL297UH060NV36B* | 20,600 | $1,030 |
| No | 205743042 | LENNOX | XP20-036-230B** | C35-36B+TDR+TXV | EL296UH070XV36B* | 20,600 | $1,030 |
| No | 205743048 | LENNOX | XP20-036-230B** | C35-36B+TDR+TXV | SL297UH040NV36B* | 20,400 | $1,020 |
| No | 205743041 | LENNOX | XP20-036-230B** | C35-36B+TDR+TXV | EL296UH045XV36B* | 20,600 | $1,030 |
| No | 205743110 | LENNOX | XP20-036-230B** | CH23-65+TDR+TXV | SL297UH040NV36B* | 20,800 | $1,040 |
| No | 205743090 | LENNOX | XP20-036-230B** | CH23-65+TDR+TXV | EL296UH090XV48C* | 20,600 | $1,030 |
| No | 206368369 | LENNOX | XP25-036-230A** | CX35-48C+TDR | SLP99UH090XV60C* | 21,000 | $1,050 |
| No | 206368368 | LENNOX | XP25-036-230A** | CX35-48C+TDR | SLP99UH090XV48C* | 21,000 | $1,050 |
| No | 205747055 | LENNOX | XP25-036-230A** | CBA38MV-048-230*+TDR | | 20,800 | $1,040 |
| No | 205747134 | LENNOX | XP25-036-230A** | CX35-48C+TDR | SL297UH080NV60C* | 21,000 | $1,050 |
| No | 205747133 | LENNOX | XP25-036-230A** | CX35-48C+TDR | SL297UH080NV48C* | 21,000 | $1,050 |
| No | 205747124 | LENNOX | XP25-036-230A** | CX35-48C+TDR | EL296UH090XV60C* | 21,000 | $1,050 |
| No | 206368364 | LENNOX | XP25-036-230A** | C35-48C+TDR+TXV | SLP99UH090XV48C* | 21,000 | $1,050 |
| No | 206368365 | LENNOX | XP25-036-230A** | C35-48C+TDR+TXV | SLP99UH090XV60C* | 21,000 | $1,050 |
| No | 205747123 | LENNOX | XP25-036-230A** | CX35-48C+TDR | EL296UH090XV48C* | 21,000 | $1,050 |
| No | 205747045 | LENNOX | XP25-036-230A** | C35-48C+TDR+TXV | SL297UH080NV60C* | 21,000 | $1,050 |
| No | 205747034 | LENNOX | XP25-036-230A** | C35-48C+TDR+TXV | EL296UH090XV48C* | 21,000 | $1,050 |
| No | 206368370 | LENNOX | XP25-036-230A** | CX35-48C+TDR | SLP99UH110XV60C* | 21,000 | $1,050 |
| No | 205747035 | LENNOX | XP25-036-230A** | C35-48C+TDR+TXV | EL296UH090XV60C* | 21,000 | $1,050 |
| No | 205747044 | LENNOX | XP25-036-230A** | C35-48C+TDR+TXV | SL297UH080NV48C* | 21,000 | $1,050 |
| No | 205747126 | LENNOX | XP25-036-230A** | CX35-48C+TDR | EL296UH110XV60C* | 21,000 | $1,050 |
| No | 205747125 | LENNOX | XP25-036-230A** | CX35-48C+TDR | EL296UH110XV48C* | 21,000 | $1,050 |
| No | 206368366 | LENNOX | XP25-036-230A** | C35-48C+TDR+TXV | SLP99UH110XV60C* | 21,000 | $1,050 |
| No | 205747037 | LENNOX | XP25-036-230A** | C35-48C+TDR+TXV | EL296UH110XV60C* | 21,000 | $1,050 |
| No | 206368363 | LENNOX | XP25-036-230A** | C35-48C+TDR+TXV | SLP99UH090XV36C* | 21,000 | $1,050 |
| No | 205747122 | LENNOX | XP25-036-230A** | CX35-48C+TDR | EL296UH090XV36C* | 21,000 | $1,050 |
| No | 205747054 | LENNOX | XP25-036-230A** | CBA38MV-042-230*+TDR | | 21,000 | $1,050 |
| No | 205747033 | LENNOX | XP25-036-230A** | C35-48C+TDR+TXV | EL296UH090XV36C* | 21,000 | $1,050 |
| No | 205747119 | LENNOX | XP25-036-230A** | CX35-48B+TDR | SL297UH040NV36B* | 21,200 | $1,060 |
| No | 205747030 | LENNOX | XP25-036-230A** | C35-48B+TDR+TXV | SL297UH040NV36B* | 21,200 | $1,060 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205747025 | LENNOX | XP25-036-230A** | C35-48B+TDR+TXV | EL296UH070XV36B* | 21,200 | $1,060 |
| No | 205747024 | LENNOX | XP25-036-230A** | C35-48B+TDR+TXV | EL296UH045XV36B* | 21,200 | $1,060 |
| No | 205747036 | LENNOX | XP25-036-230A** | C35-48C+TDR+TXV | EL296UH110XV48C* | 21,000 | $1,050 |
| No | 205747113 | LENNOX | XP25-036-230A** | CX35-48B+TDR | EL296UH045XV36B* | 21,200 | $1,060 |
| No | 206368367 | LENNOX | XP25-036-230A** | CX35-48C+TDR | SLP99UH090XV36C* | 21,000 | $1,050 |
| No | 205747031 | LENNOX | XP25-036-230A** | C35-48B+TDR+TXV | SL297UH060NV36B* | 21,200 | $1,060 |
| No | 205747143 | LENNOX | XP25-036-230A** | CBA38MV-036-230*+TDR | | 21,200 | $1,060 |
| No | 205747053 | LENNOX | XP25-036-230A** | CBA38MV-030-230*+TDR | | 21,200 | $1,060 |
| No | 205747114 | LENNOX | XP25-036-230A** | CX35-48B+TDR | EL296UH070XV36B* | 21,200 | $1,060 |
| No | 205747061 | LENNOX | XP25-036-230A** | CH23-65+TDR+TXV | EL296UH110XV48C* | 22,000 | $1,100 |
| No | 205747062 | LENNOX | XP25-036-230A** | CH23-65+TDR+TXV | EL296UH110XV60C* | 22,000 | $1,100 |
| No | 205747063 | LENNOX | XP25-036-230A** | CH23-65+TDR+TXV | EL296UH135XV60D* | 22,000 | $1,100 |
| No | 206185742 | LENNOX | XP25-036-230A** | CX35-48B+TDR | SLP99UH070XV36B* | 21,200 | $1,060 |
| No | 206366300 | LENNOX | XP25-036-230A** | CH23-65+TDR+TXV | SLP99UH090XV48C* | 22,000 | $1,100 |
| No | 205747080 | LENNOX | XP25-036-230A** | CH23-65+TDR+TXV | SL297UH080NV60C* | 22,000 | $1,100 |
| No | 205747120 | LENNOX | XP25-036-230A** | CX35-48B+TDR | SL297UH060NV36B* | 21,200 | $1,060 |
| No | 206185741 | LENNOX | XP25-036-230A** | C35-48B+TDR+TXV | SLP99UH070XV36B* | 21,200 | $1,060 |
| No | 205747060 | LENNOX | XP25-036-230A** | CH23-65+TDR+TXV | EL296UH090XV60C* | 22,000 | $1,100 |
| No | 205747079 | LENNOX | XP25-036-230A** | CH23-65+TDR+TXV | SL297UH080NV48C* | 22,000 | $1,100 |
| No | 205747059 | LENNOX | XP25-036-230A** | CH23-65+TDR+TXV | EL296UH090XV48C* | 22,000 | $1,100 |
| No | 206366307 | LENNOX | XP25-036-230A** | CX35-60D+TDR | SLP99UH135XV60D* | 21,200 | $1,060 |
| No | 206366299 | LENNOX | XP25-036-230A** | CH23-65+TDR+TXV | SLP99UH090XV36C* | 22,200 | $1,110 |
| No | 205747139 | LENNOX | XP25-036-230A** | CX35-60D+TDR | EL296UH135XV60D* | 21,200 | $1,060 |
| No | 205747058 | LENNOX | XP25-036-230A** | CH23-65+TDR+TXV | EL296UH090XV36C* | 22,200 | $1,110 |
| No | 205747050 | LENNOX | XP25-036-230A** | C35-60D+TDR+TXV | EL296UH135XV60D* | 21,200 | $1,060 |
| No | 205747077 | LENNOX | XP25-036-230A** | CH23-65+TDR+TXV | SL297UH040NV36B* | 22,200 | $1,110 |
| No | 205747078 | LENNOX | XP25-036-230A** | CH23-65+TDR+TXV | SL297UH060NV36B* | 22,200 | $1,110 |
| No | 205747093 | LENNOX | XP25-036-230A** | CH35-48B+TDR+TXV | SL297UH040NV36B* | 20,600 | $1,030 |
| No | 205747102 | LENNOX | XP25-036-230A** | CHX35-48B-**-*+TDR | SL297UH040NV36B* | 20,600 | $1,030 |
| No | 206366301 | LENNOX | XP25-036-230A** | CH23-65+TDR+TXV | SLP99UH090XV60C* | 22,000 | $1,100 |
| No | 206366305 | LENNOX | XP25-036-230A** | CHX35-48B-**-*+TDR | SLP99UH070XV36B* | 20,800 | $1,040 |
| No | 206366297 | LENNOX | XP25-036-230A** | C35-60D+TDR+TXV | SLP99UH135XV60D* | 21,200 | $1,060 |
| No | 205747097 | LENNOX | XP25-036-230A** | CHX35-48B-**-*+TDR | EL296UH070XV36B* | 20,800 | $1,040 |
| No | 205747103 | LENNOX | XP25-036-230A** | CHX35-48B-**-*+TDR | SL297UH060NV36B* | 20,800 | $1,040 |
| No | 206366304 | LENNOX | XP25-036-230A** | CH35-48B+TDR+TXV | SLP99UH070XV36B* | 20,800 | $1,040 |
| No | 205747094 | LENNOX | XP25-036-230A** | CH35-48B+TDR+TXV | SL297UH060NV36B* | 20,800 | $1,040 |
| No | 206366302 | LENNOX | XP25-036-230A** | CH23-65+TDR+TXV | SLP99UH110XV60C* | 22,000 | $1,100 |
| No | 205747088 | LENNOX | XP25-036-230A** | CH35-48B+TDR+TXV | EL296UH070XV36B* | 20,800 | $1,040 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205747096 | LENNOX | XP25-036-230A** | CHX35-48B-**-*+TDR | EL296UH045XV36B* | 20,800 | $1,040 |
| No | 206321972 | LENNOX | XP25-036-230A** | CR33-50/60+TDR+TXV | SLP99DF110XV60C* | 21,000 | $1,050 |
| No | 205747087 | LENNOX | XP25-036-230A** | CH35-48B+TDR+TXV | EL296UH045XV36B* | 20,800 | $1,040 |
| No | 206366303 | LENNOX | XP25-036-230A** | CH23-65+TDR+TXV | SLP99UH135XV60D* | 22,000 | $1,100 |
| No | 205747105 | LENNOX | XP25-036-230A** | CR33-50/60+TDR+TXV | EL296DF090XV60C* | 21,000 | $1,050 |
| No | 206321971 | LENNOX | XP25-036-230A** | CR33-50/60+TDR+TXV | SLP99DF090XV60C* | 21,000 | $1,050 |
| No | 205747106 | LENNOX | XP25-036-230A** | CR33-50/60+TDR+TXV | EL296DF110XV60C* | 21,000 | $1,050 |
| No | 206366306 | LENNOX | XP25-036-230A** | CR33-50/60+TDR+TXV | SLP99DF090XV48C* | 21,000 | $1,050 |
| No | 205747056 | LENNOX | XP25-036-230A** | CH23-65+TDR+TXV | EL296UH045XV36B* | 22,200 | $1,110 |
| No | 206321956 | LENNOX | XP25-036-230A** | CR33-50/60*+TDR+TXV | SLP99DF090XV36C* | 21,000 | $1,050 |
| No | 206366298 | LENNOX | XP25-036-230A** | CH23-65+TDR+TXV | SLP99UH070XV36B* | 22,200 | $1,110 |
| No | 205747057 | LENNOX | XP25-036-230A** | CH23-65+TDR+TXV | EL296UH070XV36B* | 22,200 | $1,110 |
| No | 206841566 | LENNOX | EL18XPV-060-230A** | CX35-49C+TDR | SLP99UH090XV60C* | 36,400 | $1,820 |
| No | 206841565 | LENNOX | EL18XPV-060-230A** | CX35-49C+TDR | SL297UH080NV60C* | 36,200 | $1,810 |
| No | 206841549 | LENNOX | EL18XPV-060-230A** | CX35-49C+TDR | EL296UH090XV60C* | 36,400 | $1,820 |
| No | 206841567 | LENNOX | EL18XPV-060-230A** | CX35-49C+TDR | SLP99UH110XV60C* | 36,200 | $1,810 |
| No | 206841517 | LENNOX | EL18XPV-060-230A** | C35-60C+TDR+TXV | SLP99UH110XV60C* | 36,800 | $1,840 |
| No | 206841551 | LENNOX | EL18XPV-060-230A** | CX35-49C+TDR | EL296UH110XV60C* | 36,200 | $1,810 |
| No | 206841515 | LENNOX | EL18XPV-060-230A** | C35-60C+TDR+TXV | SL297UH080NV60C* | 36,600 | $1,830 |
| No | 206841516 | LENNOX | EL18XPV-060-230A** | C35-60C+TDR+TXV | SLP99UH090XV60C* | 36,800 | $1,840 |
| No | 206841502 | LENNOX | EL18XPV-060-230A** | C35-60C+TDR+TXV | EL296UH110XV60C* | 36,800 | $1,840 |
| No | 206841494 | LENNOX | EL18XPV-060-230A** | C35-49C+TDR+TXV | SLP99UH110XV60C* | 36,200 | $1,810 |
| No | 206841493 | LENNOX | EL18XPV-060-230A** | C35-49C+TDR+TXV | SLP99UH090XV60C* | 36,400 | $1,820 |
| No | 206841500 | LENNOX | EL18XPV-060-230A** | C35-60C+TDR+TXV | EL296UH090XV60C* | 36,800 | $1,840 |
| No | 206841492 | LENNOX | EL18XPV-060-230A** | C35-49C+TDR+TXV | SL297UH080NV60C* | 36,200 | $1,810 |
| No | 206841442 | LENNOX | EL18XPV-060-230A** | CX35-60C+TDR | SLP99UH110XV60C* | 36,800 | $1,840 |
| No | 206841478 | LENNOX | EL18XPV-060-230A** | C35-49C+TDR+TXV | EL296UH110XV60C* | 36,200 | $1,810 |
| No | 206841441 | LENNOX | EL18XPV-060-230A** | CX35-60C+TDR | SLP99UH090XV60C* | 36,800 | $1,840 |
| No | 206841476 | LENNOX | EL18XPV-060-230A** | C35-49C+TDR+TXV | EL296UH090XV60C* | 36,400 | $1,820 |
| No | 206841444 | LENNOX | EL18XPV-060-230A** | CX35-60D+TDR | EL296UH135XV60D* | 35,600 | $1,780 |
| No | 206841447 | LENNOX | EL18XPV-060-230A** | CX35-60D+TDR | SLP99UH135XV60D* | 35,200 | $1,760 |
| No | 206841440 | LENNOX | EL18XPV-060-230A** | CX35-60C+TDR | SL297UH080NV60C* | 36,600 | $1,830 |
| No | 206841427 | LENNOX | EL18XPV-060-230A** | CX35-60C+TDR | EL296UH110XV60C* | 36,800 | $1,840 |
| No | 206841395 | LENNOX | EL18XPV-060-230A** | CHX35-60D-**-*+TDR | SLP99UH135XV60D* | 36,000 | $1,800 |
| No | 206841425 | LENNOX | EL18XPV-060-230A** | CX35-60C+TDR | EL296UH090XV60C* | 36,800 | $1,840 |
| No | 206841392 | LENNOX | EL18XPV-060-230A** | CHX35-60D-**-*+TDR | EL296UH135XV60D* | 36,200 | $1,810 |
| No | 206841390 | LENNOX | EL18XPV-060-230A** | CHX35-51/61C-**-*+TDR | SLP99UH110XV60C* | 36,400 | $1,820 |
| No | 206841389 | LENNOX | EL18XPV-060-230A** | CHX35-51/61C-**-*+TDR | SLP99UH090XV60C* | 36,600 | $1,830 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206841388 | LENNOX | EL18XPV-060-230A** | CHX35-51/61C-**-*+TDR | SL297UH080NV60C* | 36,400 | $1,820 |
| No | 206841372 | LENNOX | EL18XPV-060-230A** | CHX35-51/61C-**-*+TDR | EL296UH090XV60C* | 36,600 | $1,830 |
| No | 206841374 | LENNOX | EL18XPV-060-230A** | CHX35-51/61C-**-*+TDR | EL296UH110XV60C* | 36,400 | $1,820 |
| No | 206841341 | LENNOX | EL18XPV-060-230A** | CH35-60D+TDR+TXV | EL296UH135XV60D* | 36,200 | $1,810 |
| No | 206841344 | LENNOX | EL18XPV-060-230A** | CH35-60D+TDR+TXV | SLP99UH135XV60D* | 36,000 | $1,800 |
| No | 206841323 | LENNOX | EL18XPV-060-230A** | CH35-51C+TDR+TXV | EL296UH110XV60C* | 36,400 | $1,820 |
| No | 206841293 | LENNOX | EL18XPV-060-230A** | C35-60D+TDR+TXV | SLP99UH135XV60D* | 35,200 | $1,760 |
| No | 206841338 | LENNOX | EL18XPV-060-230A** | CH35-51C+TDR+TXV | SLP99UH090XV60C* | 36,600 | $1,830 |
| No | 206841337 | LENNOX | EL18XPV-060-230A** | CH35-51C+TDR+TXV | SL297UH080NV60C* | 36,400 | $1,820 |
| No | 206841321 | LENNOX | EL18XPV-060-230A** | CH35-51C+TDR+TXV | EL296UH090XV60C* | 36,600 | $1,830 |
| No | 206841290 | LENNOX | EL18XPV-060-230A** | C35-60D+TDR+TXV | EL296UH135XV60D* | 35,600 | $1,780 |
| No | 206841286 | LENNOX | EL18XPV-048-230A** | CR33-60+TDR+TXV | SLP99DF110XV60C* | 30,800 | $1,540 |
| No | 206841339 | LENNOX | EL18XPV-060-230A** | CH35-51C+TDR+TXV | SLP99UH110XV60C* | 36,400 | $1,820 |
| No | 206841288 | LENNOX | EL18XPV-060-230A** | CBA38MV-060-230*+TDR | | 35,800 | $1,790 |
| No | 206841285 | LENNOX | EL18XPV-048-230A** | CR33-60+TDR+TXV | SLP99DF090XV60C* | 30,800 | $1,540 |
| No | 206841277 | LENNOX | EL18XPV-048-230A** | CR33-60+TDR+TXV | EL296DF110XV60C* | 30,800 | $1,540 |
| No | 206841275 | LENNOX | EL18XPV-048-230A** | CR33-60+TDR+TXV | EL296DF090XV60C* | 30,800 | $1,540 |
| No | 206841271 | LENNOX | EL18XPV-048-230A** | CR33-50/60+TDR+TXV | SLP99DF090XV60C* | 30,800 | $1,540 |
| No | 206841270 | LENNOX | EL18XPV-048-230A** | CR33-50/60+TDR+TXV | SLP99DF090XV48C* | 30,800 | $1,540 |
| No | 206841272 | LENNOX | EL18XPV-048-230A** | CR33-50/60+TDR+TXV | SLP99DF110XV60C* | 30,800 | $1,540 |
| No | 206841263 | LENNOX | EL18XPV-048-230A** | CR33-50/60+TDR+TXV | EL296DF110XV60C* | 30,800 | $1,540 |
| No | 206841261 | LENNOX | EL18XPV-048-230A** | CR33-50/60+TDR+TXV | EL296DF090XV60C* | 30,800 | $1,540 |
| No | 206841257 | LENNOX | EL18XPV-048-230A** | CHX35-51/61C-**-*+TDR | SLP99UH090XV60C* | 30,800 | $1,540 |
| No | 206841258 | LENNOX | EL18XPV-048-230A** | CHX35-51/61C-**-*+TDR | SLP99UH110XV60C* | 30,800 | $1,540 |
| No | 206841255 | LENNOX | EL18XPV-048-230A** | CHX35-51/61C-**-*+TDR | SL297UH080NV60C* | 30,800 | $1,540 |
| No | 206841284 | LENNOX | EL18XPV-048-230A** | CR33-60+TDR+TXV | SLP99DF090XV48C* | 30,800 | $1,540 |
| No | 206841256 | LENNOX | EL18XPV-048-230A** | CHX35-51/61C-**-*+TDR | SLP99UH090XV48C* | 31,000 | $1,550 |
| No | 206841254 | LENNOX | EL18XPV-048-230A** | CHX35-51/61C-**-*+TDR | SL297UH080NV48C* | 30,800 | $1,540 |
| No | 206841240 | LENNOX | EL18XPV-048-230A** | CHX35-51/61C-**-*+TDR | EL296UH110XV60C* | 30,800 | $1,540 |
| No | 206841238 | LENNOX | EL18XPV-048-230A** | CHX35-51/61C-**-*+TDR | EL296UH090XV60C* | 30,800 | $1,540 |
| No | 206841237 | LENNOX | EL18XPV-048-230A** | CHX35-51/61C-**-*+TDR | EL296UH090XV48C* | 31,000 | $1,550 |
| No | 206841239 | LENNOX | EL18XPV-048-230A** | CHX35-51/61C-**-*+TDR | EL296UH110XV48C* | 30,800 | $1,540 |
| No | 206841234 | LENNOX | EL18XPV-048-230A** | CH35-51C+TDR+TXV | SLP99UH110XV60C* | 30,800 | $1,540 |
| No | 206841233 | LENNOX | EL18XPV-048-230A** | CH35-51C+TDR+TXV | SLP99UH090XV60C* | 30,800 | $1,540 |
| No | 206841231 | LENNOX | EL18XPV-048-230A** | CH35-51C+TDR+TXV | SL297UH080NV60C* | 30,800 | $1,540 |
| No | 206841232 | LENNOX | EL18XPV-048-230A** | CH35-51C+TDR+TXV | SLP99UH090XV48C* | 31,000 | $1,550 |
| No | 206841216 | LENNOX | EL18XPV-048-230A** | CH35-51C+TDR+TXV | EL296UH110XV60C* | 30,800 | $1,540 |
| No | 206841230 | LENNOX | EL18XPV-048-230A** | CH35-51C+TDR+TXV | SL297UH080NV48C* | 30,800 | $1,540 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206841215 | LENNOX | EL18XPV-048-230A** | CH35-51C+TDR+TXV | EL296UH110XV48C* | 30,800 | $1,540 |
| No | 206841214 | LENNOX | EL18XPV-048-230A** | CH35-51C+TDR+TXV | EL296UH090XV60C* | 30,800 | $1,540 |
| No | 206841213 | LENNOX | EL18XPV-048-230A** | CH35-51C+TDR+TXV | EL296UH090XV48C* | 31,000 | $1,550 |
| No | 206841210 | LENNOX | EL18XPV-048-230A** | CX35-50/60C+TDR | SLP99UH110XV60C* | 30,800 | $1,540 |
| No | 206841208 | LENNOX | EL18XPV-048-230A** | CX35-50/60C+TDR | SLP99UH090XV48C* | 30,800 | $1,540 |
| No | 206841206 | LENNOX | EL18XPV-048-230A** | CX35-50/60C+TDR | SL297UH080NV48C* | 30,800 | $1,540 |
| No | 206841209 | LENNOX | EL18XPV-048-230A** | CX35-50/60C+TDR | SLP99UH090XV60C* | 30,800 | $1,540 |
| No | 206841207 | LENNOX | EL18XPV-048-230A** | CX35-50/60C+TDR | SL297UH080NV60C* | 30,800 | $1,540 |
| No | 206841192 | LENNOX | EL18XPV-048-230A** | CX35-50/60C+TDR | EL296UH110XV48C* | 30,800 | $1,540 |
| No | 206841193 | LENNOX | EL18XPV-048-230A** | CX35-50/60C+TDR | EL296UH110XV60C* | 30,800 | $1,540 |
| No | 206841191 | LENNOX | EL18XPV-048-230A** | CX35-50/60C+TDR | EL296UH090XV60C* | 30,800 | $1,540 |
| No | 206841190 | LENNOX | EL18XPV-048-230A** | CX35-50/60C+TDR | EL296UH090XV48C* | 30,800 | $1,540 |
| No | 206841185 | LENNOX | EL18XPV-048-230A** | CX35-49C+TDR | SLP99UH090XV48C* | 31,200 | $1,560 |
| No | 206841187 | LENNOX | EL18XPV-048-230A** | CX35-49C+TDR | SLP99UH110XV60C* | 31,200 | $1,560 |
| No | 206841184 | LENNOX | EL18XPV-048-230A** | CX35-49C+TDR | SL297UH080NV60C* | 31,200 | $1,560 |
| No | 206841183 | LENNOX | EL18XPV-048-230A** | CX35-49C+TDR | SL297UH080NV48C* | 31,200 | $1,560 |
| No | 206841167 | LENNOX | EL18XPV-048-230A** | CX35-49C+TDR | EL296UH110XV60C* | 31,200 | $1,560 |
| No | 206841166 | LENNOX | EL18XPV-048-230A** | CX35-49C+TDR | EL296UH110XV48C* | 31,200 | $1,560 |
| No | 206841164 | LENNOX | EL18XPV-048-230A** | CX35-49C+TDR | EL296UH090XV48C* | 31,200 | $1,560 |
| No | 206841134 | LENNOX | EL18XPV-048-230A** | C35-50/60C+TDR+TXV | SLP99UH090XV60C* | 30,800 | $1,540 |
| No | 206841135 | LENNOX | EL18XPV-048-230A** | C35-50/60C+TDR+TXV | SLP99UH110XV60C* | 30,800 | $1,540 |
| No | 206841132 | LENNOX | EL18XPV-048-230A** | C35-50/60C+TDR+TXV | SL297UH080NV60C* | 30,800 | $1,540 |
| No | 206841118 | LENNOX | EL18XPV-048-230A** | C35-50/60C+TDR+TXV | EL296UH110XV60C* | 30,800 | $1,540 |
| No | 206841131 | LENNOX | EL18XPV-048-230A** | C35-50/60C+TDR+TXV | SL297UH080NV48C* | 30,800 | $1,540 |
| No | 206841165 | LENNOX | EL18XPV-048-230A** | CX35-49C+TDR | EL296UH090XV60C* | 31,200 | $1,560 |
| No | 206841186 | LENNOX | EL18XPV-048-230A** | CX35-49C+TDR | SLP99UH090XV60C* | 31,200 | $1,560 |
| No | 206841112 | LENNOX | EL18XPV-048-230A** | C35-49C+TDR+TXV | SLP99UH110XV60C* | 31,200 | $1,560 |
| No | 206841116 | LENNOX | EL18XPV-048-230A** | C35-50/60C+TDR+TXV | EL296UH090XV60C* | 30,800 | $1,540 |
| No | 206841111 | LENNOX | EL18XPV-048-230A** | C35-49C+TDR+TXV | SLP99UH090XV60C* | 31,200 | $1,560 |
| No | 206841110 | LENNOX | EL18XPV-048-230A** | C35-49C+TDR+TXV | SLP99UH090XV48C* | 31,200 | $1,560 |
| No | 206841108 | LENNOX | EL18XPV-048-230A** | C35-49C+TDR+TXV | SL297UH080NV48C* | 31,200 | $1,560 |
| No | 206841109 | LENNOX | EL18XPV-048-230A** | C35-49C+TDR+TXV | SL297UH080NV60C* | 31,200 | $1,560 |
| No | 206841133 | LENNOX | EL18XPV-048-230A** | C35-50/60C+TDR+TXV | SLP99UH090XV48C* | 30,800 | $1,540 |
| No | 206841091 | LENNOX | EL18XPV-048-230A** | C35-49C+TDR+TXV | EL296UH110XV48C* | 31,200 | $1,560 |
| No | 206841092 | LENNOX | EL18XPV-048-230A** | C35-49C+TDR+TXV | EL296UH110XV60C* | 31,200 | $1,560 |
| No | 206841090 | LENNOX | EL18XPV-048-230A** | C35-49C+TDR+TXV | EL296UH090XV60C* | 31,200 | $1,560 |
| No | 206841089 | LENNOX | EL18XPV-048-230A** | C35-49C+TDR+TXV | EL296UH090XV48C* | 31,200 | $1,560 |
| No | 206841117 | LENNOX | EL18XPV-048-230A** | C35-50/60C+TDR+TXV | EL296UH110XV48C* | 30,800 | $1,540 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206841076 | LENNOX | EL18XPV-036-230A** | CR33-30/36B+TDR+TXV | SLP99DF070XV36B* | 22,000 | $1,100 |
| No | 206841082 | LENNOX | EL18XPV-048-230A** | CBA38MV-048-230*+TDR | | 31,000 | $1,550 |
| No | 206841079 | LENNOX | EL18XPV-036-230A** | CR33-30/36C+TDR+TXV | SLP99DF090XV48C* | 22,000 | $1,100 |
| No | 206841078 | LENNOX | EL18XPV-036-230A** | CR33-30/36C+TDR+TXV | SLP99DF090XV36C* | 21,800 | $1,090 |
| No | 206841066 | LENNOX | EL18XPV-036-230A** | CR33-30/36B+TDR+TXV | EL296DF070XV48B* | 22,000 | $1,100 |
| No | 206841115 | LENNOX | EL18XPV-048-230A** | C35-50/60C+TDR+TXV | EL296UH090XV48C* | 30,800 | $1,540 |
| No | 206841055 | LENNOX | EL18XPV-036-230A** | CHX35-48B-**-*+TDR | SLP99UH070XV36B* | 20,400 | $1,020 |
| No | 206841064 | LENNOX | EL18XPV-036-230A** | CR33-30/36B+TDR+TXV | EL296DF045XV36B* | 22,000 | $1,100 |
| No | 206841035 | LENNOX | EL18XPV-036-230A** | CHX35-48B-**-*+TDR | EL296UH070XV36B* | 20,400 | $1,020 |
| No | 206841053 | LENNOX | EL18XPV-036-230A** | CHX35-48B-**-*+TDR | SL297UH040NV36B* | 20,400 | $1,020 |
| No | 206841033 | LENNOX | EL18XPV-036-230A** | CHX35-48B-**-*+TDR | EL296UH045XV36B* | 20,600 | $1,030 |
| No | 206841029 | LENNOX | EL18XPV-036-230A** | CH35-48B+TDR+TXV | SLP99UH070XV36B* | 20,400 | $1,020 |
| No | 206841028 | LENNOX | EL18XPV-036-230A** | CH35-48B+TDR+TXV | SL297UH060NV36B* | 20,400 | $1,020 |
| No | 206841027 | LENNOX | EL18XPV-036-230A** | CH35-48B+TDR+TXV | SL297UH040NV36B* | 20,400 | $1,020 |
| No | 206840906 | LENNOX | EL18XPV-036-230A** | CH35-48B+TDR+TXV | EL296UH045XV36B* | 20,600 | $1,030 |
| No | 206840908 | LENNOX | EL18XPV-036-230A** | CH35-48B+TDR+TXV | EL296UH070XV36B* | 20,400 | $1,020 |
| No | 206841018 | LENNOX | EL18XPV-036-230A** | CX35-30B+TDR | SLP99UH070XV36B* | 20,600 | $1,030 |
| No | 206841054 | LENNOX | EL18XPV-036-230A** | CHX35-48B-**-*+TDR | SL297UH060NV36B* | 20,400 | $1,020 |
| No | 206841016 | LENNOX | EL18XPV-036-230A** | CX35-30B+TDR | SL297UH040NV36B* | 20,600 | $1,030 |
| No | 206841003 | LENNOX | EL18XPV-036-230A** | CX35-30B+TDR | EL296UH045XV36B* | 20,800 | $1,040 |
| No | 206841004 | LENNOX | EL18XPV-036-230A** | CX35-30B+TDR | EL296UH070XV36B* | 20,600 | $1,030 |
| No | 206840989 | LENNOX | EL18XPV-036-230A** | CX35-30/36C+TDR | SLP99UH090XV36C* | 20,800 | $1,040 |
| No | 206840987 | LENNOX | EL18XPV-036-230A** | CX35-30/36C+TDR | EL296UH090XV36C* | 20,800 | $1,040 |
| No | 206841017 | LENNOX | EL18XPV-036-230A** | CX35-30B+TDR | SL297UH060NV36B* | 20,600 | $1,030 |
| No | 206840986 | LENNOX | EL18XPV-036-230A** | CX35-30/36B+TDR | SLP99UH070XV36B* | 20,800 | $1,040 |
| No | 206840984 | LENNOX | EL18XPV-036-230A** | CX35-30/36B+TDR | SL297UH040NV36B* | 20,800 | $1,040 |
| No | 206840973 | LENNOX | EL18XPV-036-230A** | CX35-30/36B+TDR | EL296UH070XV36B* | 20,800 | $1,040 |
| No | 206840985 | LENNOX | EL18XPV-036-230A** | CX35-30/36B+TDR | SL297UH060NV36B* | 20,800 | $1,040 |
| No | 206840971 | LENNOX | EL18XPV-036-230A** | CX35-30/36B+TDR | EL296UH045XV36B* | 21,000 | $1,050 |
| No | 206840956 | LENNOX | EL18XPV-036-230A** | CHX35-36C-**-*+TDR | SLP99UH090XV36C* | 20,800 | $1,040 |
| No | 206840955 | LENNOX | EL18XPV-036-230A** | CHX35-36C-**-*+TDR | SL297UH080NV48C* | 20,800 | $1,040 |
| No | 206840952 | LENNOX | EL18XPV-036-230A** | CHX35-36C-**-*+TDR | EL296UH090XV36C* | 20,800 | $1,040 |
| No | 206840949 | LENNOX | EL18XPV-036-230A** | CHX35-36B-**-*+TDR | SLP99UH070XV36B* | 21,400 | $1,070 |
| No | 206840948 | LENNOX | EL18XPV-036-230A** | CHX35-36B-**-*+TDR | SL297UH060NV36B* | 21,400 | $1,070 |
| No | 206840934 | LENNOX | EL18XPV-036-230A** | CHX35-36B-**-*+TDR | EL296UH070XV36B* | 21,400 | $1,070 |
| No | 206840933 | LENNOX | EL18XPV-036-230A** | CHX35-36B-**-*+TDR | EL296UH045XV36B* | 21,400 | $1,070 |
| No | 206840902 | LENNOX | EL18XPV-036-230A** | CH35-36C+TDR+TXV | SLP99UH090XV36C* | 20,800 | $1,040 |
| No | 206840895 | LENNOX | EL18XPV-036-230A** | CH35-36B+TDR+TXV | SLP99UH070XV36B* | 21,400 | $1,070 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206840894 | LENNOX | EL18XPV-036-230A** | CH35-36B+TDR+TXV | SL297UH060NV36B* | 21,400 | $1,070 |
| No | 206840901 | LENNOX | EL18XPV-036-230A** | CH35-36C+TDR+TXV | SL297UH080NV48C* | 20,800 | $1,040 |
| No | 206840893 | LENNOX | EL18XPV-036-230A** | CH35-36B+TDR+TXV | SL297UH040NV36B* | 21,400 | $1,070 |
| No | 206840947 | LENNOX | EL18XPV-036-230A** | CHX35-36B-**-*+TDR | SL297UH040NV36B* | 21,400 | $1,070 |
| No | 206840880 | LENNOX | EL18XPV-036-230A** | CH35-36B+TDR+TXV | EL296UH070XV36B* | 21,400 | $1,070 |
| No | 206840861 | LENNOX | EL18XPV-036-230A** | C35-30B+TDR+TXV | SL297UH060NV36B* | 20,600 | $1,030 |
| No | 206840862 | LENNOX | EL18XPV-036-230A** | C35-30B+TDR+TXV | SLP99UH070XV36B* | 20,600 | $1,030 |
| No | 206840879 | LENNOX | EL18XPV-036-230A** | CH35-36B+TDR+TXV | EL296UH045XV36B* | 21,400 | $1,070 |
| No | 206840898 | LENNOX | EL18XPV-036-230A** | CH35-36C+TDR+TXV | EL296UH090XV36C* | 20,800 | $1,040 |
| No | 206840848 | LENNOX | EL18XPV-036-230A** | C35-30B+TDR+TXV | EL296UH070XV36B* | 20,600 | $1,030 |
| No | 206840860 | LENNOX | EL18XPV-036-230A** | C35-30B+TDR+TXV | SL297UH040NV36B* | 20,600 | $1,030 |
| No | 206840831 | LENNOX | EL18XPV-036-230A** | C35-30/36C+TDR+TXV | EL296UH090XV36C* | 20,800 | $1,040 |
| No | 206840833 | LENNOX | EL18XPV-036-230A** | C35-30/36C+TDR+TXV | SLP99UH090XV36C* | 20,800 | $1,040 |
| No | 206840847 | LENNOX | EL18XPV-036-230A** | C35-30B+TDR+TXV | EL296UH045XV36B* | 20,800 | $1,040 |
| No | 206840800 | LENNOX | EL18XPV-036-230A** | CBA38MV-036-230*+TDR | | 21,200 | $1,060 |
| No | 206840815 | LENNOX | EL18XPV-036-230A** | C35-30/36B+TDR+TXV | EL296UH045XV36B* | 21,000 | $1,050 |
| No | 206840830 | LENNOX | EL18XPV-036-230A** | C35-30/36B+TDR+TXV | SLP99UH070XV36B* | 20,800 | $1,040 |
| No | 206840817 | LENNOX | EL18XPV-036-230A** | C35-30/36B+TDR+TXV | EL296UH070XV36B* | 20,800 | $1,040 |
| No | 206840829 | LENNOX | EL18XPV-036-230A** | C35-30/36B+TDR+TXV | SL297UH060NV36B* | 20,800 | $1,040 |
| No | 206840828 | LENNOX | EL18XPV-036-230A** | C35-30/36B+TDR+TXV | SL297UH040NV36B* | 20,800 | $1,040 |
| No | 206840797 | LENNOX | EL18XPV-024-230A** | CX35-24B+TDR | SL297UH060NV36B* | 14,800 | $740 |
| No | 206840786 | LENNOX | EL18XPV-024-230A** | CX35-24B+TDR | EL296UH070XV36B* | 14,800 | $740 |
| No | 206840798 | LENNOX | EL18XPV-024-230A** | CX35-24B+TDR | SLP99UH070XV36B* | 14,800 | $740 |
| No | 206840796 | LENNOX | EL18XPV-024-230A** | CX35-24B+TDR | SL297UH040NV36B* | 14,800 | $740 |
| No | 206840784 | LENNOX | EL18XPV-024-230A** | CX35-24B+TDR | EL296UH045XV36B* | 14,800 | $740 |
| No | 206840753 | LENNOX | EL18XPV-024-230A** | C35-24B+TDR+TXV | SLP99UH070XV36B* | 14,800 | $740 |
| No | 206840751 | LENNOX | EL18XPV-024-230A** | C35-24B+TDR+TXV | SL297UH040NV36B* | 14,800 | $740 |
| No | 206840752 | LENNOX | EL18XPV-024-230A** | C35-24B+TDR+TXV | SL297UH060NV36B* | 14,800 | $740 |
| No | 206840739 | LENNOX | EL18XPV-024-230A** | C35-24B+TDR+TXV | EL296UH045XV36B* | 14,800 | $740 |
| No | 206840741 | LENNOX | EL18XPV-024-230A** | C35-24B+TDR+TXV | EL296UH070XV36B* | 14,800 | $740 |
| No | 206840722 | LENNOX | EL18XPV-024-230A** | CX35-30B+TDR | SLP99UH070XV36B* | 14,700 | $735 |
| No | 206840710 | LENNOX | EL18XPV-024-230A** | CX35-30B+TDR | EL296UH070XV36B* | 14,700 | $735 |
| No | 206840708 | LENNOX | EL18XPV-024-230A** | CX35-30B+TDR | EL296UH045XV36B* | 14,800 | $740 |
| No | 206840689 | LENNOX | EL18XPV-024-230A** | CX35-30/36C+TDR | EL296UH090XV36C* | 15,200 | $760 |
| No | 206840720 | LENNOX | EL18XPV-024-230A** | CX35-30B+TDR | SL297UH040NV36B* | 14,800 | $740 |
| No | 206840691 | LENNOX | EL18XPV-024-230A** | CX35-30/36C+TDR | SLP99UH090XV36C* | 15,200 | $760 |
| No | 206840688 | LENNOX | EL18XPV-024-230A** | CX35-30/36B+TDR | SLP99UH070XV36B* | 15,300 | $765 |
| No | 206840687 | LENNOX | EL18XPV-024-230A** | CX35-30/36B+TDR | SL297UH060NV36B* | 15,300 | $765 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206840686 | LENNOX | EL18XPV-024-230A** | CX35-30/36B+TDR | SL297UH040NV36B* | 15,300 | $765 |
| No | 206840721 | LENNOX | EL18XPV-024-230A** | CX35-30B+TDR | SL297UH060NV36B* | 14,800 | $740 |
| No | 206840652 | LENNOX | EL18XPV-024-230A** | CHX35-30B-**-*+TDR | SL297UH040NV36B* | 14,900 | $745 |
| No | 206840658 | LENNOX | EL18XPV-024-230A** | CR33-24B+TDR+TXV | SLP99UH070XV36B* | 15,400 | $770 |
| No | 206840676 | LENNOX | EL18XPV-024-230A** | CX35-30/36B+TDR | EL296UH070XV36B* | 15,300 | $765 |
| No | 206840653 | LENNOX | EL18XPV-024-230A** | CHX35-30B-**-*+TDR | SL297UH060NV36B* | 14,900 | $745 |
| No | 206840654 | LENNOX | EL18XPV-024-230A** | CHX35-30B-**-*+TDR | SLP99UH070XV36B* | 14,900 | $745 |
| No | 206840642 | LENNOX | EL18XPV-024-230A** | CHX35-30B-**-*+TDR | EL296UH070XV36B* | 14,900 | $745 |
| No | 206840640 | LENNOX | EL18XPV-024-230A** | CHX35-30B-**-*+TDR | EL296UH045XV36B* | 14,900 | $745 |
| No | 206840623 | LENNOX | EL18XPV-024-230A** | CHX35-24B-**-*+TDR | SLP99UH070XV36B* | 14,800 | $740 |
| No | 206840621 | LENNOX | EL18XPV-024-230A** | CHX35-24B-**-*+TDR | SL297UH040NV36B* | 14,800 | $740 |
| No | 206840622 | LENNOX | EL18XPV-024-230A** | CHX35-24B-**-*+TDR | SL297UH060NV36B* | 14,800 | $740 |
| No | 206840592 | LENNOX | EL18XPV-024-230A** | CH35-30B+TDR+TXV | SLP99UH070XV36B* | 14,900 | $745 |
| No | 206840609 | LENNOX | EL18XPV-024-230A** | CHX35-24B-**-*+TDR | EL296UH045XV36B* | 14,900 | $745 |
| No | 206840591 | LENNOX | EL18XPV-024-230A** | CH35-30B+TDR+TXV | SL297UH060NV36B* | 14,900 | $745 |
| No | 206840590 | LENNOX | EL18XPV-024-230A** | CH35-30B+TDR+TXV | SL297UH040NV36B* | 14,900 | $745 |
| No | 206840580 | LENNOX | EL18XPV-024-230A** | CH35-30B+TDR+TXV | EL296UH070XV36B* | 14,900 | $745 |
| No | 206840578 | LENNOX | EL18XPV-024-230A** | CH35-30B+TDR+TXV | EL296UH045XV36B* | 14,900 | $745 |
| No | 206840674 | LENNOX | EL18XPV-024-230A** | CX35-30/36B+TDR | EL296UH045XV36B* | 15,300 | $765 |
| No | 206840561 | LENNOX | EL18XPV-024-230A** | CH35-24B+TDR+TXV | SLP99UH070XV36B* | 14,800 | $740 |
| No | 206840611 | LENNOX | EL18XPV-024-230A** | CHX35-24B-**-*+TDR | EL296UH070XV36B* | 14,800 | $740 |
| No | 206840547 | LENNOX | EL18XPV-024-230A** | CH35-24B+TDR+TXV | EL296UH045XV36B* | 14,900 | $745 |
| No | 206840559 | LENNOX | EL18XPV-024-230A** | CH35-24B+TDR+TXV | SL297UH040NV36B* | 14,800 | $740 |
| No | 206840560 | LENNOX | EL18XPV-024-230A** | CH35-24B+TDR+TXV | SL297UH060NV36B* | 14,800 | $740 |
| No | 206840530 | LENNOX | EL18XPV-024-230A** | C35-30B+TDR+TXV | SLP99UH070XV36B* | 14,700 | $735 |
| No | 206840529 | LENNOX | EL18XPV-024-230A** | C35-30B+TDR+TXV | SL297UH060NV36B* | 14,800 | $740 |
| No | 206840518 | LENNOX | EL18XPV-024-230A** | C35-30B+TDR+TXV | EL296UH070XV36B* | 14,700 | $735 |
| No | 206840509 | LENNOX | EL18XPV-024-230A** | C35-30/36C+TDR+TXV | SLP99UH090XV36C* | 15,200 | $760 |
| No | 206840528 | LENNOX | EL18XPV-024-230A** | C35-30B+TDR+TXV | SL297UH040NV36B* | 14,800 | $740 |
| No | 206840516 | LENNOX | EL18XPV-024-230A** | C35-30B+TDR+TXV | EL296UH045XV36B* | 14,800 | $740 |
| No | 206840507 | LENNOX | EL18XPV-024-230A** | C35-30/36C+TDR+TXV | EL296UH090XV36C* | 15,200 | $760 |
| No | 206840506 | LENNOX | EL18XPV-024-230A** | C35-30/36B+TDR+TXV | SLP99UH070XV36B* | 15,300 | $765 |
| No | 206840494 | LENNOX | EL18XPV-024-230A** | C35-30/36B+TDR+TXV | EL296UH070XV36B* | 15,300 | $765 |
| No | 206840504 | LENNOX | EL18XPV-024-230A** | C35-30/36B+TDR+TXV | SL297UH040NV36B* | 15,300 | $765 |
| No | 206840505 | LENNOX | EL18XPV-024-230A** | C35-30/36B+TDR+TXV | SL297UH060NV36B* | 15,300 | $765 |
| No | 206840549 | LENNOX | EL18XPV-024-230A** | CH35-24B+TDR+TXV | EL296UH070XV36B* | 14,800 | $740 |
| No | 206840492 | LENNOX | EL18XPV-024-230A** | C35-30/36B+TDR+TXV | EL296UH045XV36B* | 15,300 | $765 |
| No | 206840767 | LENNOX | EL18XPV-024-230A** | CBA38MV-030-230*+TDR | | 15,100 | $755 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206840476 | LENNOX | EL18XPV-024-230A** | CBA38MV-018/024-230*+TDR | | 14,800 | $740 |
| No | 206841539 | LENNOX | EL18XPV-060-230A** | CX35-48C+TDR | SL280UH100NV60C* | 36,600 | $1,830 |
| No | 206841514 | LENNOX | EL18XPV-060-230A** | C35-60C+TDR+TXV | SL280UH110XV60C* | 36,600 | $1,830 |
| No | 206841563 | LENNOX | EL18XPV-060-230A** | CX35-49C+TDR | SL280UH110V60C* | 36,200 | $1,810 |
| No | 206841536 | LENNOX | EL18XPV-060-230A** | CX35-48C+TDR | SL280UH080NV60C* | 36,600 | $1,830 |
| No | 206841564 | LENNOX | EL18XPV-060-230A** | CX35-49C+TDR | SL280UH110XV60C* | 36,200 | $1,810 |
| No | 206841513 | LENNOX | EL18XPV-060-230A** | C35-60C+TDR+TXV | SL280UH110V60C* | 36,600 | $1,830 |
| No | 206841511 | LENNOX | EL18XPV-060-230A** | C35-60C+TDR+TXV | SL280UH090XV60C* | 36,400 | $1,820 |
| No | 206841512 | LENNOX | EL18XPV-060-230A** | C35-60C+TDR+TXV | SL280UH100NV60C* | 36,200 | $1,810 |
| No | 206841510 | LENNOX | EL18XPV-060-230A** | C35-60C+TDR+TXV | SL280UH090V60C* | 36,400 | $1,820 |
| No | 206841509 | LENNOX | EL18XPV-060-230A** | C35-60C+TDR+TXV | SL280UH080NV60C* | 36,200 | $1,810 |
| No | 206841490 | LENNOX | EL18XPV-060-230A** | C35-49C+TDR+TXV | SL280UH110V60C* | 36,200 | $1,810 |
| No | 206841466 | LENNOX | EL18XPV-060-230A** | C35-48C+TDR+TXV | SL280UH100NV60C* | 36,600 | $1,830 |
| No | 206841463 | LENNOX | EL18XPV-060-230A** | C35-48C+TDR+TXV | SL280UH080NV60C* | 36,600 | $1,830 |
| No | 206841446 | LENNOX | EL18XPV-060-230A** | CX35-60D+TDR | SL280UH135V60D* | 35,400 | $1,770 |
| No | 206841439 | LENNOX | EL18XPV-060-230A** | CX35-60C+TDR | SL280UH110XV60C* | 36,600 | $1,830 |
| No | 206841436 | LENNOX | EL18XPV-060-230A** | CX35-60C+TDR | SL280UH090XV60C* | 36,400 | $1,820 |
| No | 206841438 | LENNOX | EL18XPV-060-230A** | CX35-60C+TDR | SL280UH110V60C* | 36,600 | $1,830 |
| No | 206841437 | LENNOX | EL18XPV-060-230A** | CX35-60C+TDR | SL280UH100NV60C* | 36,200 | $1,810 |
| No | 206841435 | LENNOX | EL18XPV-060-230A** | CX35-60C+TDR | SL280UH090V60C* | 36,400 | $1,820 |
| No | 206841421 | LENNOX | EL18XPV-060-230A** | CR33-60+TDR+TXV | SL280DF110V60C* | 35,000 | $1,750 |
| No | 206841420 | LENNOX | EL18XPV-060-230A** | CR33-60+TDR+TXV | SL280DF090V60C* | 35,000 | $1,750 |
| No | 206841491 | LENNOX | EL18XPV-060-230A** | C35-49C+TDR+TXV | SL280UH110XV60C* | 36,200 | $1,810 |
| No | 206841434 | LENNOX | EL18XPV-060-230A** | CX35-60C+TDR | SL280UH080NV60C* | 36,200 | $1,810 |
| No | 206841385 | LENNOX | EL18XPV-060-230A** | CHX35-51/61C-**-*+TDR | SL280UH100NV60C* | 36,000 | $1,800 |
| No | 206841410 | LENNOX | EL18XPV-060-230A** | CR33-50/60+TDR+TXV | SL280DF090V60C* | 35,000 | $1,750 |
| No | 206841411 | LENNOX | EL18XPV-060-230A** | CR33-50/60+TDR+TXV | SL280DF110V60C* | 35,000 | $1,750 |
| No | 206841394 | LENNOX | EL18XPV-060-230A** | CHX35-60D-**-*+TDR | SL280UH135V60D* | 36,200 | $1,810 |
| No | 206841387 | LENNOX | EL18XPV-060-230A** | CHX35-51/61C-**-*+TDR | SL280UH110XV60C* | 36,400 | $1,820 |
| No | 206841386 | LENNOX | EL18XPV-060-230A** | CHX35-51/61C-**-*+TDR | SL280UH110V60C* | 36,400 | $1,820 |
| No | 206841383 | LENNOX | EL18XPV-060-230A** | CHX35-51/61C-**-*+TDR | SL280UH090V60C* | 36,200 | $1,810 |
| No | 206841343 | LENNOX | EL18XPV-060-230A** | CH35-60D+TDR+TXV | SL280UH135V60D* | 36,200 | $1,810 |
| No | 206841336 | LENNOX | EL18XPV-060-230A** | CH35-51C+TDR+TXV | SL280UH110XV60C* | 36,400 | $1,820 |
| No | 206841384 | LENNOX | EL18XPV-060-230A** | CHX35-51/61C-**-*+TDR | SL280UH090XV60C* | 36,200 | $1,810 |
| No | 206841382 | LENNOX | EL18XPV-060-230A** | CHX35-51/61C-**-*+TDR | SL280UH080NV60C* | 36,000 | $1,800 |
| No | 206841335 | LENNOX | EL18XPV-060-230A** | CH35-51C+TDR+TXV | SL280UH110V60C* | 36,400 | $1,820 |
| No | 206841333 | LENNOX | EL18XPV-060-230A** | CH35-51C+TDR+TXV | SL280UH090XV60C* | 36,200 | $1,810 |
| No | 206841334 | LENNOX | EL18XPV-060-230A** | CH35-51C+TDR+TXV | SL280UH100NV60C* | 36,000 | $1,800 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206841283 | LENNOX | EL18XPV-048-230A** | CR33-60+TDR+TXV | SL280DF110V60C* | 30,400 | $1,520 |
| No | 206841332 | LENNOX | EL18XPV-060-230A** | CH35-51C+TDR+TXV | SL280UH090V60C* | 36,200 | $1,810 |
| No | 206841292 | LENNOX | EL18XPV-060-230A** | C35-60D+TDR+TXV | SL280UH135V60D* | 35,400 | $1,770 |
| No | 206841331 | LENNOX | EL18XPV-060-230A** | CH35-51C+TDR+TXV | SL280UH080NV60C* | 36,000 | $1,800 |
| No | 206841282 | LENNOX | EL18XPV-048-230A** | CR33-60+TDR+TXV | SL280DF090V60C* | 30,600 | $1,530 |
| No | 206841253 | LENNOX | EL18XPV-048-230A** | CHX35-51/61C-**-*+TDR | SL280UH110XV60C* | 30,800 | $1,540 |
| No | 206841252 | LENNOX | EL18XPV-048-230A** | CHX35-51/61C-**-*+TDR | SL280UH110V60C* | 30,800 | $1,540 |
| No | 206841269 | LENNOX | EL18XPV-048-230A** | CR33-50/60+TDR+TXV | SL280DF110V60C* | 30,400 | $1,520 |
| No | 206841268 | LENNOX | EL18XPV-048-230A** | CR33-50/60+TDR+TXV | SL280DF090V60C* | 30,600 | $1,530 |
| No | 206841250 | LENNOX | EL18XPV-048-230A** | CHX35-51/61C-**-*+TDR | SL280UH090XV60C* | 30,800 | $1,540 |
| No | 206841251 | LENNOX | EL18XPV-048-230A** | CHX35-51/61C-**-*+TDR | SL280UH100NV60C* | 30,600 | $1,530 |
| No | 206841249 | LENNOX | EL18XPV-048-230A** | CHX35-51/61C-**-*+TDR | SL280UH090V60C* | 30,800 | $1,540 |
| No | 206841248 | LENNOX | EL18XPV-048-230A** | CHX35-51/61C-**-*+TDR | SL280UH080NV60C* | 30,600 | $1,530 |
| No | 206841228 | LENNOX | EL18XPV-048-230A** | CH35-51C+TDR+TXV | SL280UH110V60C* | 30,800 | $1,540 |
| No | 206841227 | LENNOX | EL18XPV-048-230A** | CH35-51C+TDR+TXV | SL280UH100NV60C* | 30,600 | $1,530 |
| No | 206841226 | LENNOX | EL18XPV-048-230A** | CH35-51C+TDR+TXV | SL280UH090XV60C* | 30,800 | $1,540 |
| No | 206841225 | LENNOX | EL18XPV-048-230A** | CH35-51C+TDR+TXV | SL280UH090V60C* | 30,800 | $1,540 |
| No | 206841224 | LENNOX | EL18XPV-048-230A** | CH35-51C+TDR+TXV | SL280UH080NV60C* | 30,600 | $1,530 |
| No | 206841205 | LENNOX | EL18XPV-048-230A** | CX35-50/60C+TDR | SL280UH110XV60C* | 30,800 | $1,540 |
| No | 206841203 | LENNOX | EL18XPV-048-230A** | CX35-50/60C+TDR | SL280UH100NV60C* | 30,400 | $1,520 |
| No | 206841202 | LENNOX | EL18XPV-048-230A** | CX35-50/60C+TDR | SL280UH090XV60C* | 30,600 | $1,530 |
| No | 206841201 | LENNOX | EL18XPV-048-230A** | CX35-50/60C+TDR | SL280UH090V60C* | 30,600 | $1,530 |
| No | 206841182 | LENNOX | EL18XPV-048-230A** | CX35-49C+TDR | SL280UH110XV60C* | 31,200 | $1,560 |
| No | 206841200 | LENNOX | EL18XPV-048-230A** | CX35-50/60C+TDR | SL280UH080NV60C* | 30,400 | $1,520 |
| No | 206841181 | LENNOX | EL18XPV-048-230A** | CX35-49C+TDR | SL280UH110V60C* | 31,200 | $1,560 |
| No | 206841229 | LENNOX | EL18XPV-048-230A** | CH35-51C+TDR+TXV | SL280UH110XV60C* | 30,800 | $1,540 |
| No | 206841204 | LENNOX | EL18XPV-048-230A** | CX35-50/60C+TDR | SL280UH110V60C* | 30,800 | $1,540 |
| No | 206841180 | LENNOX | EL18XPV-048-230A** | CX35-49C+TDR | SL280UH100NV60C* | 31,000 | $1,550 |
| No | 206841178 | LENNOX | EL18XPV-048-230A** | CX35-49C+TDR | SL280UH090V60C* | 31,200 | $1,560 |
| No | 206841287 | LENNOX | EL18XPV-048-230A** | CHX35-48B-**-*+TDR | SL280UH090XV48B* | 31,600 | $1,580 |
| No | 206841157 | LENNOX | EL18XPV-048-230A** | CHX35-48B-**-*+TDR | SL280UH090V48B* | 31,600 | $1,580 |
| No | 206841149 | LENNOX | EL18XPV-048-230A** | CH35-48B+TDR+TXV | SL280UH090XV48B* | 31,600 | $1,580 |
| No | 206841156 | LENNOX | EL18XPV-048-230A** | CHX35-48B-**-*+TDR | SL280UH080NV48B* | 31,400 | $1,570 |
| No | 206841148 | LENNOX | EL18XPV-048-230A** | CH35-48B+TDR+TXV | SL280UH090V48B* | 31,600 | $1,580 |
| No | 206841147 | LENNOX | EL18XPV-048-230A** | CH35-48B+TDR+TXV | SL280UH080NV48B* | 31,400 | $1,570 |
| No | 206841130 | LENNOX | EL18XPV-048-230A** | C35-50/60C+TDR+TXV | SL280UH110XV60C* | 30,800 | $1,540 |
| No | 206841128 | LENNOX | EL18XPV-048-230A** | C35-50/60C+TDR+TXV | SL280UH100NV60C* | 30,400 | $1,520 |
| No | 206841129 | LENNOX | EL18XPV-048-230A** | C35-50/60C+TDR+TXV | SL280UH110V60C* | 30,800 | $1,540 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206841177 | LENNOX | EL18XPV-048-230A** | CX35-49C+TDR | SL280UH080NV60C* | 31,000 | $1,550 |
| No | 206841107 | LENNOX | EL18XPV-048-230A** | C35-49C+TDR+TXV | SL280UH110XV60C* | 31,200 | $1,560 |
| No | 206841125 | LENNOX | EL18XPV-048-230A** | C35-50/60C+TDR+TXV | SL280UH080NV60C* | 30,400 | $1,520 |
| No | 206841179 | LENNOX | EL18XPV-048-230A** | CX35-49C+TDR | SL280UH090XV60C* | 31,200 | $1,560 |
| No | 206841127 | LENNOX | EL18XPV-048-230A** | C35-50/60C+TDR+TXV | SL280UH090XV60C* | 30,600 | $1,530 |
| No | 206841106 | LENNOX | EL18XPV-048-230A** | C35-49C+TDR+TXV | SL280UH110V60C* | 31,200 | $1,560 |
| No | 206841105 | LENNOX | EL18XPV-048-230A** | C35-49C+TDR+TXV | SL280UH100NV60C* | 31,000 | $1,550 |
| No | 206841126 | LENNOX | EL18XPV-048-230A** | C35-50/60C+TDR+TXV | SL280UH090V60C* | 30,600 | $1,530 |
| No | 206841104 | LENNOX | EL18XPV-048-230A** | C35-49C+TDR+TXV | SL280UH090XV60C* | 31,200 | $1,560 |
| No | 206841103 | LENNOX | EL18XPV-048-230A** | C35-49C+TDR+TXV | SL280UH090V60C* | 31,200 | $1,560 |
| No | 206841052 | LENNOX | EL18XPV-036-230A** | CHX35-48B-**-*+TDR | SL280UH090XV48B* | 20,400 | $1,020 |
| No | 206841059 | LENNOX | EL18XPV-036-230A** | CR33-30/36A+TDR+TXV | SL280DF070V36A* | 22,000 | $1,100 |
| No | 206841102 | LENNOX | EL18XPV-048-230A** | C35-49C+TDR+TXV | SL280UH080NV60C* | 31,000 | $1,550 |
| No | 206841051 | LENNOX | EL18XPV-036-230A** | CHX35-48B-**-*+TDR | SL280UH090V48B* | 20,400 | $1,020 |
| No | 206841050 | LENNOX | EL18XPV-036-230A** | CHX35-48B-**-*+TDR | SL280UH090V36B* | 20,200 | $1,010 |
| No | 206841026 | LENNOX | EL18XPV-036-230A** | CH35-48B+TDR+TXV | SL280UH090XV48B* | 20,400 | $1,020 |
| No | 206841025 | LENNOX | EL18XPV-036-230A** | CH35-48B+TDR+TXV | SL280UH090V48B* | 20,400 | $1,020 |
| No | 206841024 | LENNOX | EL18XPV-036-230A** | CH35-48B+TDR+TXV | SL280UH090V36B* | 20,200 | $1,010 |
| No | 206841049 | LENNOX | EL18XPV-036-230A** | CHX35-48B-**-*+TDR | SL280UH080NV48B* | 20,200 | $1,010 |
| No | 206841023 | LENNOX | EL18XPV-036-230A** | CH35-48B+TDR+TXV | SL280UH080NV48B* | 20,200 | $1,010 |
| No | 206841014 | LENNOX | EL18XPV-036-230A** | CX35-30B+TDR | SL280UH090V48B* | 20,600 | $1,030 |
| No | 206840999 | LENNOX | EL18XPV-036-230A** | CX35-30A+TDR | SL280UH070XV36A* | 20,600 | $1,030 |
| No | 206841015 | LENNOX | EL18XPV-036-230A** | CX35-30B+TDR | SL280UH090XV48B* | 20,600 | $1,030 |
| No | 206841013 | LENNOX | EL18XPV-036-230A** | CX35-30B+TDR | SL280UH080NV48B* | 20,400 | $1,020 |
| No | 206841075 | LENNOX | EL18XPV-036-230A** | CR33-30/36B+TDR+TXV | SL280DF090V48B* | 21,800 | $1,090 |
| No | 206840997 | LENNOX | EL18XPV-036-230A** | CX35-30A+TDR | SL280UH060NV36A* | 20,600 | $1,030 |
| No | 206840964 | LENNOX | EL18XPV-036-230A** | CX35-30/36A+TDR | SL280UH070V36A* | 21,000 | $1,050 |
| No | 206840983 | LENNOX | EL18XPV-036-230A** | CX35-30/36B+TDR | SL280UH090V36B* | 20,800 | $1,040 |
| No | 206840965 | LENNOX | EL18XPV-036-230A** | CX35-30/36A+TDR | SL280UH070XV36A* | 21,000 | $1,050 |
| No | 206840946 | LENNOX | EL18XPV-036-230A** | CHX35-36B-**-*+TDR | SL280UH090XV48B* | 21,400 | $1,070 |
| No | 206840963 | LENNOX | EL18XPV-036-230A** | CX35-30/36A+TDR | SL280UH060NV36A* | 20,800 | $1,040 |
| No | 206840945 | LENNOX | EL18XPV-036-230A** | CHX35-36B-**-*+TDR | SL280UH090V48B* | 21,400 | $1,070 |
| No | 206840944 | LENNOX | EL18XPV-036-230A** | CHX35-36B-**-*+TDR | SL280UH090V36B* | 21,200 | $1,060 |
| No | 206840943 | LENNOX | EL18XPV-036-230A** | CHX35-36B-**-*+TDR | SL280UH080NV48B* | 21,200 | $1,060 |
| No | 206840926 | LENNOX | EL18XPV-036-230A** | CHX35-36A-**-*+TDR | SL280UH070V36A* | 20,800 | $1,040 |
| No | 206840927 | LENNOX | EL18XPV-036-230A** | CHX35-36A-**-*+TDR | SL280UH070XV36A* | 20,800 | $1,040 |
| No | 206840925 | LENNOX | EL18XPV-036-230A** | CHX35-36A-**-*+TDR | SL280UH060NV36A* | 20,600 | $1,030 |
| No | 206840892 | LENNOX | EL18XPV-036-230A** | CH35-36B+TDR+TXV | SL280UH090XV48B* | 21,400 | $1,070 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206840891 | LENNOX | EL18XPV-036-230A** | CH35-36B+TDR+TXV | SL280UH090V48B* | 21,400 | $1,070 |
| No | 206840890 | LENNOX | EL18XPV-036-230A** | CH35-36B+TDR+TXV | SL280UH090V36B* | 21,200 | $1,060 |
| No | 206840873 | LENNOX | EL18XPV-036-230A** | CH35-36A+TDR+TXV | SL280UH070XV36A* | 20,800 | $1,040 |
| No | 206840889 | LENNOX | EL18XPV-036-230A** | CH35-36B+TDR+TXV | SL280UH080NV48B* | 21,200 | $1,060 |
| No | 206840871 | LENNOX | EL18XPV-036-230A** | CH35-36A+TDR+TXV | SL280UH060NV36A* | 20,600 | $1,030 |
| No | 206840872 | LENNOX | EL18XPV-036-230A** | CH35-36A+TDR+TXV | SL280UH070V36A* | 20,800 | $1,040 |
| No | 206840998 | LENNOX | EL18XPV-036-230A** | CX35-30A+TDR | SL280UH070V36A* | 20,600 | $1,030 |
| No | 206840843 | LENNOX | EL18XPV-036-230A** | C35-30A+TDR+TXV | SL280UH070XV36A* | 20,600 | $1,030 |
| No | 206840859 | LENNOX | EL18XPV-036-230A** | C35-30B+TDR+TXV | SL280UH090XV48B* | 20,600 | $1,030 |
| No | 206840857 | LENNOX | EL18XPV-036-230A** | C35-30B+TDR+TXV | SL280UH080NV48B* | 20,400 | $1,020 |
| No | 206840858 | LENNOX | EL18XPV-036-230A** | C35-30B+TDR+TXV | SL280UH090V48B* | 20,600 | $1,030 |
| No | 206840842 | LENNOX | EL18XPV-036-230A** | C35-30A+TDR+TXV | SL280UH070V36A* | 20,600 | $1,030 |
| No | 206840841 | LENNOX | EL18XPV-036-230A** | C35-30A+TDR+TXV | SL280UH060NV36A* | 20,600 | $1,030 |
| No | 206840809 | LENNOX | EL18XPV-036-230A** | C35-30/36A+TDR+TXV | SL280UH070XV36A* | 21,000 | $1,050 |
| No | 206840827 | LENNOX | EL18XPV-036-230A** | C35-30/36B+TDR+TXV | SL280UH090V36B* | 20,800 | $1,040 |
| No | 206840808 | LENNOX | EL18XPV-036-230A** | C35-30/36A+TDR+TXV | SL280UH070V36A* | 21,000 | $1,050 |
| No | 206840779 | LENNOX | EL18XPV-024-230A** | CX35-24A+TDR | SL280UH070XV36A* | 14,800 | $740 |
| No | 206840795 | LENNOX | EL18XPV-024-230A** | CX35-24B+TDR | SL280UH090V36B* | 14,700 | $735 |
| No | 206840778 | LENNOX | EL18XPV-024-230A** | CX35-24A+TDR | SL280UH070V36A* | 14,800 | $740 |
| No | 206840777 | LENNOX | EL18XPV-024-230A** | CX35-24A+TDR | SL280UH060NV36A* | 14,700 | $735 |
| No | 206840750 | LENNOX | EL18XPV-024-230A** | C35-24B+TDR+TXV | SL280UH090V36B* | 14,700 | $735 |
| No | 206840732 | LENNOX | EL18XPV-024-230A** | C35-24A+TDR+TXV | SL280UH060NV36A* | 14,700 | $735 |
| No | 206840734 | LENNOX | EL18XPV-024-230A** | C35-24A+TDR+TXV | SL280UH070XV36A* | 14,800 | $740 |
| No | 206840703 | LENNOX | EL18XPV-024-230A** | CX35-30A+TDR | SL280UH070XV36A* | 14,700 | $735 |
| No | 206840702 | LENNOX | EL18XPV-024-230A** | CX35-30A+TDR | SL280UH070V36A* | 14,700 | $735 |
| No | 206840685 | LENNOX | EL18XPV-024-230A** | CX35-30/36B+TDR | SL280UH090V36B* | 15,200 | $760 |
| No | 206840701 | LENNOX | EL18XPV-024-230A** | CX35-30A+TDR | SL280UH060NV36A* | 14,700 | $735 |
| No | 206840719 | LENNOX | EL18XPV-024-230A** | CX35-30B+TDR | SL280UH090V36B* | 14,700 | $735 |
| No | 206840733 | LENNOX | EL18XPV-024-230A** | C35-24A+TDR+TXV | SL280UH070V36A* | 14,800 | $740 |
| No | 206840807 | LENNOX | EL18XPV-036-230A** | C35-30/36A+TDR+TXV | SL280UH060NV36A* | 20,800 | $1,040 |
| No | 206840668 | LENNOX | EL18XPV-024-230A** | CX35-30/36A+TDR | SL280UH070V36A* | 15,300 | $765 |
| No | 206840669 | LENNOX | EL18XPV-024-230A** | CX35-30/36A+TDR | SL280UH070XV36A* | 15,300 | $765 |
| No | 206840667 | LENNOX | EL18XPV-024-230A** | CX35-30/36A+TDR | SL280UH060NV36A* | 15,200 | $760 |
| No | 206840657 | LENNOX | EL18XPV-024-230A** | CR33-24A+TDR+TXV | SL280DF070V36A* | 15,400 | $770 |
| No | 206840635 | LENNOX | EL18XPV-024-230A** | CHX35-30A-**-*+TDR | SL280UH070XV36A* | 14,400 | $720 |
| No | 206840651 | LENNOX | EL18XPV-024-230A** | CHX35-30B-**-*+TDR | SL280UH090V36B* | 14,800 | $740 |
| No | 206840620 | LENNOX | EL18XPV-024-230A** | CHX35-24B-**-*+TDR | SL280UH090V36B* | 14,800 | $740 |
| No | 206840633 | LENNOX | EL18XPV-024-230A** | CHX35-30A-**-*+TDR | SL280UH060NV36A* | 14,300 | $715 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206840634 | LENNOX | EL18XPV-024-230A** | CHX35-30A-**-*+TDR | SL280UH070V36A* | 14,400 | $720 |
| No | 206840602 | LENNOX | EL18XPV-024-230A** | CHX35-24A-**-*+TDR | SL280UH060NV36A* | 15,400 | $770 |
| No | 206840603 | LENNOX | EL18XPV-024-230A** | CHX35-24A-**-*+TDR | SL280UH070V36A* | 15,400 | $770 |
| No | 206840604 | LENNOX | EL18XPV-024-230A** | CHX35-24A-**-*+TDR | SL280UH070XV36A* | 15,400 | $770 |
| No | 206840589 | LENNOX | EL18XPV-024-230A** | CH35-30B+TDR+TXV | SL280UH090V36B* | 14,800 | $740 |
| No | 206840573 | LENNOX | EL18XPV-024-230A** | CH35-30A+TDR+TXV | SL280UH070XV36A* | 14,400 | $720 |
| No | 206840571 | LENNOX | EL18XPV-024-230A** | CH35-30A+TDR+TXV | SL280UH060NV36A* | 14,300 | $715 |
| No | 206840572 | LENNOX | EL18XPV-024-230A** | CH35-30A+TDR+TXV | SL280UH070V36A* | 14,400 | $720 |
| No | 206840542 | LENNOX | EL18XPV-024-230A** | CH35-24A+TDR+TXV | SL280UH070XV36A* | 15,400 | $770 |
| No | 206840541 | LENNOX | EL18XPV-024-230A** | CH35-24A+TDR+TXV | SL280UH070V36A* | 15,400 | $770 |
| No | 206840558 | LENNOX | EL18XPV-024-230A** | CH35-24B+TDR+TXV | SL280UH090V36B* | 14,800 | $740 |
| No | 206840540 | LENNOX | EL18XPV-024-230A** | CH35-24A+TDR+TXV | SL280UH060NV36A* | 15,400 | $770 |
| No | 206840511 | LENNOX | EL18XPV-024-230A** | C35-30A+TDR+TXV | SL280UH070XV36A* | 14,700 | $735 |
| No | 206840527 | LENNOX | EL18XPV-024-230A** | C35-30B+TDR+TXV | SL280UH090V36B* | 14,700 | $735 |
| No | 206840503 | LENNOX | EL18XPV-024-230A** | C35-30/36B+TDR+TXV | SL280UH090V36B* | 15,200 | $760 |
| No | 206840763 | LENNOX | EL18XPV-024-230A** | C35-30A+TDR+TXV | SL280UH060NV36A* | 14,700 | $735 |
| No | 206840510 | LENNOX | EL18XPV-024-230A** | C35-30A+TDR+TXV | SL280UH070V36A* | 14,700 | $735 |
| No | 206840487 | LENNOX | EL18XPV-024-230A** | C35-30/36A+TDR+TXV | SL280UH070XV36A* | 15,300 | $765 |
| No | 206840485 | LENNOX | EL18XPV-024-230A** | C35-30/36A+TDR+TXV | SL280UH060NV36A* | 15,200 | $760 |
| No | 206840486 | LENNOX | EL18XPV-024-230A** | C35-30/36A+TDR+TXV | SL280UH070V36A* | 15,300 | $765 |
| No | 207436664 | LENNOX | SL25XPV-060-230A** | CHX35-51/61C-**-*+TDR | SLP99UH090XV60C* | 48,500 | $2,425 |
| No | 207436661 | LENNOX | SL25XPV-060-230A** | CHX35-51/61C-**-*+TDR | SL280UH110V60C* | 48,500 | $2,425 |
| No | 207436665 | LENNOX | SL25XPV-060-230A** | CHX35-51/61C-**-*+TDR | SLP99UH110XV60C* | 48,500 | $2,425 |
| No | 207436663 | LENNOX | SL25XPV-060-230A** | CHX35-51/61C-**-*+TDR | SL297UH080NV60C* | 48,500 | $2,425 |
| No | 207436662 | LENNOX | SL25XPV-060-230A** | CHX35-51/61C-**-*+TDR | SL280UH110XV60C* | 48,500 | $2,425 |
| No | 207436660 | LENNOX | SL25XPV-060-230A** | CHX35-51/61C-**-*+TDR | SL280UH100NV60C* | 48,000 | $2,400 |
| No | 207436658 | LENNOX | SL25XPV-060-230A** | CHX35-51/61C-**-*+TDR | SL280UH090V60C* | 48,000 | $2,400 |
| No | 207436659 | LENNOX | SL25XPV-060-230A** | CHX35-51/61C-**-*+TDR | SL280UH090XV60C* | 48,000 | $2,400 |
| No | 207436656 | LENNOX | SL25XPV-060-230A** | CHX35-51/61C-**-*+TDR | EL296UH110XV60C* | 48,500 | $2,425 |
| No | 207436657 | LENNOX | SL25XPV-060-230A** | CHX35-51/61C-**-*+TDR | SL280UH080NV60C* | 48,000 | $2,400 |
| No | 207436655 | LENNOX | SL25XPV-060-230A** | CHX35-51/61C-**-*+TDR | EL296UH090XV60C* | 48,500 | $2,425 |
| No | 207436698 | LENNOX | SL25XPV-060-230A** | CX35-60D+TDR | EL296UH135XV60D* | 43,500 | $2,175 |
| No | 207436700 | LENNOX | SL25XPV-060-230A** | CX35-60D+TDR | SLP99UH135XV60D* | 43,500 | $2,175 |
| No | 207436699 | LENNOX | SL25XPV-060-230A** | CX35-60D+TDR | SL280UH135V60D* | 43,500 | $2,175 |
| No | 207436697 | LENNOX | SL25XPV-060-230A** | CX35-60C+TDR | SLP99UH110XV60C* | 44,500 | $2,225 |
| No | 207436695 | LENNOX | SL25XPV-060-230A** | CX35-60C+TDR | SL297UH080NV60C* | 44,500 | $2,225 |
| No | 207436696 | LENNOX | SL25XPV-060-230A** | CX35-60C+TDR | SLP99UH090XV60C* | 45,000 | $2,250 |
| No | 207436693 | LENNOX | SL25XPV-060-230A** | CX35-60C+TDR | SL280UH110V60C* | 44,500 | $2,225 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207436691 | LENNOX | SL25XPV-060-230A** | CX35-60C+TDR | SL280UH090XV60C* | 44,500 | $2,225 |
| No | 207436692 | LENNOX | SL25XPV-060-230A** | CX35-60C+TDR | SL280UH100NV60C* | 44,000 | $2,200 |
| No | 207436690 | LENNOX | SL25XPV-060-230A** | CX35-60C+TDR | SL280UH090V60C* | 44,500 | $2,225 |
| No | 207436689 | LENNOX | SL25XPV-060-230A** | CX35-60C+TDR | SL280UH080NV60C* | 44,000 | $2,200 |
| No | 207436686 | LENNOX | SL25XPV-060-230A** | CX35-49C+TDR | SLP99UH110XV60C* | 43,500 | $2,175 |
| No | 207436688 | LENNOX | SL25XPV-060-230A** | CX35-60C+TDR | EL296UH110XV60C* | 44,500 | $2,225 |
| No | 207436687 | LENNOX | SL25XPV-060-230A** | CX35-60C+TDR | EL296UH090XV60C* | 45,000 | $2,250 |
| No | 207436694 | LENNOX | SL25XPV-060-230A** | CX35-60C+TDR | SL280UH110XV60C* | 44,500 | $2,225 |
| No | 207436685 | LENNOX | SL25XPV-060-230A** | CX35-49C+TDR | SLP99UH090XV60C* | 43,500 | $2,175 |
| No | 207436681 | LENNOX | SL25XPV-060-230A** | CX35-49C+TDR | SL280UH100NV60C* | 43,000 | $2,150 |
| No | 207436683 | LENNOX | SL25XPV-060-230A** | CX35-49C+TDR | SL280UH110XV60C* | 43,500 | $2,175 |
| No | 207436679 | LENNOX | SL25XPV-060-230A** | CX35-49C+TDR | SL280UH090V60C* | 43,500 | $2,175 |
| No | 207436680 | LENNOX | SL25XPV-060-230A** | CX35-49C+TDR | SL280UH090XV60C* | 43,500 | $2,175 |
| No | 207436678 | LENNOX | SL25XPV-060-230A** | CX35-49C+TDR | SL280UH080NV60C* | 43,000 | $2,150 |
| No | 207436676 | LENNOX | SL25XPV-060-230A** | CX35-49C+TDR | EL296UH090XV60C* | 43,500 | $2,175 |
| No | 207436600 | LENNOX | SL25XPV-048-230A** | CX35-49C+TDR | SLP99UH110XV60C* | 43,500 | $2,175 |
| No | 207436677 | LENNOX | SL25XPV-060-230A** | CX35-49C+TDR | EL296UH110XV60C* | 43,500 | $2,175 |
| No | 207436682 | LENNOX | SL25XPV-060-230A** | CX35-49C+TDR | SL280UH110V60C* | 43,500 | $2,175 |
| No | 207436599 | LENNOX | SL25XPV-048-230A** | CX35-49C+TDR | SLP99UH090XV60C* | 43,500 | $2,175 |
| No | 207436588 | LENNOX | SL25XPV-048-230A** | CX35-49C+TDR | EL296UH110XV48C* | 43,500 | $2,175 |
| No | 207436589 | LENNOX | SL25XPV-048-230A** | CX35-49C+TDR | EL296UH110XV60C* | 43,500 | $2,175 |
| No | 207436587 | LENNOX | SL25XPV-048-230A** | CX35-49C+TDR | EL296UH090XV60C* | 43,500 | $2,175 |
| No | 207436586 | LENNOX | SL25XPV-048-230A** | CX35-49C+TDR | EL296UH090XV48C* | 43,500 | $2,175 |
| No | 207436684 | LENNOX | SL25XPV-060-230A** | CX35-49C+TDR | SL297UH080NV60C* | 43,500 | $2,175 |
| No | 207436674 | LENNOX | SL25XPV-060-230A** | CR33-50/60+TDR+TXV | SLP99DF090XV60C* | 44,000 | $2,200 |
| No | 207436675 | LENNOX | SL25XPV-060-230A** | CR33-50/60+TDR+TXV | SLP99DF110XV60C* | 44,000 | $2,200 |
| No | 207436673 | LENNOX | SL25XPV-060-230A** | CR33-50/60+TDR+TXV | SL280DF110V60C* | 43,500 | $2,175 |
| No | 207436671 | LENNOX | SL25XPV-060-230A** | CR33-50/60+TDR+TXV | SL280DF080NV60C* | 44,000 | $2,200 |
| No | 207436672 | LENNOX | SL25XPV-060-230A** | CR33-50/60+TDR+TXV | SL280DF090V60C* | 43,500 | $2,175 |
| No | 207436670 | LENNOX | SL25XPV-060-230A** | CR33-50/60+TDR+TXV | EL296DF110XV60C* | 44,000 | $2,200 |
| No | 207436651 | LENNOX | SL25XPV-060-230A** | CH35-51C+TDR+TXV | SLP99UH110XV60C* | 48,500 | $2,425 |
| No | 207436669 | LENNOX | SL25XPV-060-230A** | CR33-50/60+TDR+TXV | EL296DF090XV60C* | 44,000 | $2,200 |
| No | 207436649 | LENNOX | SL25XPV-060-230A** | CH35-51C+TDR+TXV | SL297UH080NV60C* | 48,500 | $2,425 |
| No | 207436650 | LENNOX | SL25XPV-060-230A** | CH35-51C+TDR+TXV | SLP99UH090XV60C* | 48,500 | $2,425 |
| No | 207436598 | LENNOX | SL25XPV-048-230A** | CX35-49C+TDR | SLP99UH090XV48C* | 43,500 | $2,175 |
| No | 207436648 | LENNOX | SL25XPV-060-230A** | CH35-51C+TDR+TXV | SL280UH110XV60C* | 48,500 | $2,425 |
| No | 207436647 | LENNOX | SL25XPV-060-230A** | CH35-51C+TDR+TXV | SL280UH110V60C* | 48,500 | $2,425 |
| No | 207436646 | LENNOX | SL25XPV-060-230A** | CH35-51C+TDR+TXV | SL280UH100NV60C* | 48,000 | $2,400 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207436643 | LENNOX | SL25XPV-060-230A** | CH35-51C+TDR+TXV | SL280UH080NV60C* | 48,000 | $2,400 |
| No | 207436645 | LENNOX | SL25XPV-060-230A** | CH35-51C+TDR+TXV | SL280UH090XV60C* | 48,000 | $2,400 |
| No | 207436644 | LENNOX | SL25XPV-060-230A** | CH35-51C+TDR+TXV | SL280UH090V60C* | 48,000 | $2,400 |
| No | 207436641 | LENNOX | SL25XPV-060-230A** | CH35-51C+TDR+TXV | EL296UH090XV60C* | 48,500 | $2,425 |
| No | 207436642 | LENNOX | SL25XPV-060-230A** | CH35-51C+TDR+TXV | EL296UH110XV60C* | 48,500 | $2,425 |
| No | 207436640 | LENNOX | SL25XPV-060-230A** | C35-60D+TDR+TXV | SLP99UH135XV60D* | 43,500 | $2,175 |
| No | 207436639 | LENNOX | SL25XPV-060-230A** | C35-60D+TDR+TXV | SL280UH135V60D* | 43,500 | $2,175 |
| No | 207436638 | LENNOX | SL25XPV-060-230A** | C35-60D+TDR+TXV | EL296UH135XV60D* | 43,500 | $2,175 |
| No | 207436637 | LENNOX | SL25XPV-060-230A** | C35-60C+TDR+TXV | SLP99UH110XV60C* | 44,500 | $2,225 |
| No | 207436635 | LENNOX | SL25XPV-060-230A** | C35-60C+TDR+TXV | SL297UH080NV60C* | 44,500 | $2,225 |
| No | 207436634 | LENNOX | SL25XPV-060-230A** | C35-60C+TDR+TXV | SL280UH110XV60C* | 44,500 | $2,225 |
| No | 207436636 | LENNOX | SL25XPV-060-230A** | C35-60C+TDR+TXV | SLP99UH090XV60C* | 45,000 | $2,250 |
| No | 207436633 | LENNOX | SL25XPV-060-230A** | C35-60C+TDR+TXV | SL280UH110V60C* | 44,500 | $2,225 |
| No | 207436632 | LENNOX | SL25XPV-060-230A** | C35-60C+TDR+TXV | SL280UH100NV60C* | 44,000 | $2,200 |
| No | 207436627 | LENNOX | SL25XPV-060-230A** | C35-60C+TDR+TXV | EL296UH090XV60C* | 45,000 | $2,250 |
| No | 207436626 | LENNOX | SL25XPV-060-230A** | C35-49C+TDR+TXV | SLP99UH110XV60C* | 43,500 | $2,175 |
| No | 207436630 | LENNOX | SL25XPV-060-230A** | C35-60C+TDR+TXV | SL280UH090V60C* | 44,500 | $2,225 |
| No | 207436628 | LENNOX | SL25XPV-060-230A** | C35-60C+TDR+TXV | EL296UH110XV60C* | 44,500 | $2,225 |
| No | 207436631 | LENNOX | SL25XPV-060-230A** | C35-60C+TDR+TXV | SL280UH090XV60C* | 44,500 | $2,225 |
| No | 207436629 | LENNOX | SL25XPV-060-230A** | C35-60C+TDR+TXV | SL280UH080NV60C* | 44,000 | $2,200 |
| No | 207436625 | LENNOX | SL25XPV-060-230A** | C35-49C+TDR+TXV | SLP99UH090XV60C* | 43,500 | $2,175 |
| No | 207436624 | LENNOX | SL25XPV-060-230A** | C35-49C+TDR+TXV | SL297UH080NV60C* | 43,500 | $2,175 |
| No | 207436621 | LENNOX | SL25XPV-060-230A** | C35-49C+TDR+TXV | SL280UH100NV60C* | 43,000 | $2,150 |
| No | 207436622 | LENNOX | SL25XPV-060-230A** | C35-49C+TDR+TXV | SL280UH110V60C* | 43,500 | $2,175 |
| No | 207436623 | LENNOX | SL25XPV-060-230A** | C35-49C+TDR+TXV | SL280UH110XV60C* | 43,500 | $2,175 |
| No | 207436620 | LENNOX | SL25XPV-060-230A** | C35-49C+TDR+TXV | SL280UH090XV60C* | 43,500 | $2,175 |
| No | 207436619 | LENNOX | SL25XPV-060-230A** | C35-49C+TDR+TXV | SL280UH090V60C* | 43,500 | $2,175 |
| No | 207436617 | LENNOX | SL25XPV-060-230A** | C35-49C+TDR+TXV | EL296UH110XV60C* | 43,500 | $2,175 |
| No | 207436616 | LENNOX | SL25XPV-060-230A** | C35-49C+TDR+TXV | EL296UH090XV60C* | 43,500 | $2,175 |
| No | 207436618 | LENNOX | SL25XPV-060-230A** | C35-49C+TDR+TXV | SL280UH080NV60C* | 43,000 | $2,150 |
| No | 207436524 | LENNOX | SL25XPV-048-230A** | C35-49C+TDR+TXV | SLP99UH090XV60C* | 43,500 | $2,175 |
| No | 207436525 | LENNOX | SL25XPV-048-230A** | C35-49C+TDR+TXV | SLP99UH110XV60C* | 43,500 | $2,175 |
| No | 207436523 | LENNOX | SL25XPV-048-230A** | C35-49C+TDR+TXV | SLP99UH090XV48C* | 43,500 | $2,175 |
| No | 207436514 | LENNOX | SL25XPV-048-230A** | C35-49C+TDR+TXV | EL296UH110XV60C* | 43,500 | $2,175 |
| No | 207436513 | LENNOX | SL25XPV-048-230A** | C35-49C+TDR+TXV | EL296UH110XV48C* | 43,500 | $2,175 |
| No | 207436512 | LENNOX | SL25XPV-048-230A** | C35-49C+TDR+TXV | EL296UH090XV60C* | 43,500 | $2,175 |
| No | 207436145 | LENNOX | SL25XPV-060-230A** | CBA38MV-060-230*+TDR | | 45,500 | $2,275 |
| No | 207436511 | LENNOX | SL25XPV-048-230A** | C35-49C+TDR+TXV | EL296UH090XV48C* | 43,500 | $2,175 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207436431 | LENNOX | SL25XPV-036-230A** | CHX35-48C-**-*+TDR | SLP99UH090XV60C* | 30,200 | $1,510 |
| No | 207436430 | LENNOX | SL25XPV-036-230A** | CHX35-48C-**-*+TDR | SLP99UH090XV48C* | 30,400 | $1,520 |
| No | 207436429 | LENNOX | SL25XPV-036-230A** | CHX35-48C-**-*+TDR | SLP99UH090XV36C* | 30,400 | $1,520 |
| No | 207436428 | LENNOX | SL25XPV-036-230A** | CHX35-48C-**-*+TDR | SL297UH080NV60C* | 30,400 | $1,520 |
| No | 207436427 | LENNOX | SL25XPV-036-230A** | CHX35-48C-**-*+TDR | SL297UH080NV48C* | 30,200 | $1,510 |
| No | 207436426 | LENNOX | SL25XPV-036-230A** | CHX35-48C-**-*+TDR | SL280UH110XV60C* | 30,200 | $1,510 |
| No | 207436425 | LENNOX | SL25XPV-036-230A** | CHX35-48C-**-*+TDR | SL280UH110V60C* | 30,200 | $1,510 |
| No | 207436424 | LENNOX | SL25XPV-036-230A** | CHX35-48C-**-*+TDR | SL280UH100NV60C* | 30,000 | $1,500 |
| No | 207436422 | LENNOX | SL25XPV-036-230A** | CHX35-48C-**-*+TDR | SL280UH090V60C* | 30,200 | $1,510 |
| No | 207436421 | LENNOX | SL25XPV-036-230A** | CHX35-48C-**-*+TDR | SL280UH080NV60C* | 30,200 | $1,510 |
| No | 207436419 | LENNOX | SL25XPV-036-230A** | CHX35-48C-**-*+TDR | EL296UH110XV48C* | 30,200 | $1,510 |
| No | 207436417 | LENNOX | SL25XPV-036-230A** | CHX35-48C-**-*+TDR | EL296UH090XV48C* | 30,400 | $1,520 |
| No | 207436416 | LENNOX | SL25XPV-036-230A** | CHX35-48C-**-*+TDR | EL296UH090XV36C* | 30,400 | $1,520 |
| No | 207436432 | LENNOX | SL25XPV-036-230A** | CHX35-48C-**-*+TDR | SLP99UH110XV60C* | 30,400 | $1,520 |
| No | 207436423 | LENNOX | SL25XPV-036-230A** | CHX35-48C-**-*+TDR | SL280UH090XV60C* | 30,200 | $1,510 |
| No | 207436420 | LENNOX | SL25XPV-036-230A** | CHX35-48C-**-*+TDR | EL296UH110XV60C* | 30,400 | $1,520 |
| No | 207436398 | LENNOX | SL25XPV-036-230A** | CHX35-42C-**-*+TDR | SL280UH100NV60C* | 29,800 | $1,490 |
| No | 207436418 | LENNOX | SL25XPV-036-230A** | CHX35-48C-**-*+TDR | EL296UH090XV60C* | 30,200 | $1,510 |
| No | 207436395 | LENNOX | SL25XPV-036-230A** | CHX35-42C-**-*+TDR | SL280UH080NV60C* | 29,800 | $1,490 |
| No | 207436596 | LENNOX | SL25XPV-048-230A** | CX35-49C+TDR | SL297UH080NV48C* | 43,500 | $2,175 |
| No | 207436597 | LENNOX | SL25XPV-048-230A** | CX35-49C+TDR | SL297UH080NV60C* | 43,500 | $2,175 |
| No | 207436594 | LENNOX | SL25XPV-048-230A** | CX35-49C+TDR | SL280UH110V60C* | 43,500 | $2,175 |
| No | 207436593 | LENNOX | SL25XPV-048-230A** | CX35-49C+TDR | SL280UH100NV60C* | 43,000 | $2,150 |
| No | 207436595 | LENNOX | SL25XPV-048-230A** | CX35-49C+TDR | SL280UH110XV60C* | 43,500 | $2,175 |
| No | 207436592 | LENNOX | SL25XPV-048-230A** | CX35-49C+TDR | SL280UH090XV60C* | 43,000 | $2,150 |
| No | 207436591 | LENNOX | SL25XPV-048-230A** | CX35-49C+TDR | SL280UH090V60C* | 43,000 | $2,150 |
| No | 207436590 | LENNOX | SL25XPV-048-230A** | CX35-49C+TDR | SL280UH080NV60C* | 43,000 | $2,150 |
| No | 207436521 | LENNOX | SL25XPV-048-230A** | C35-49C+TDR+TXV | SL297UH080NV48C* | 43,500 | $2,175 |
| No | 207436520 | LENNOX | SL25XPV-048-230A** | C35-49C+TDR+TXV | SL280UH110XV60C* | 43,500 | $2,175 |
| No | 207436522 | LENNOX | SL25XPV-048-230A** | C35-49C+TDR+TXV | SL297UH080NV60C* | 43,500 | $2,175 |
| No | 207436519 | LENNOX | SL25XPV-048-230A** | C35-49C+TDR+TXV | SL280UH110V60C* | 43,500 | $2,175 |
| No | 207436518 | LENNOX | SL25XPV-048-230A** | C35-49C+TDR+TXV | SL280UH100NV60C* | 43,000 | $2,150 |
| No | 207436517 | LENNOX | SL25XPV-048-230A** | C35-49C+TDR+TXV | SL280UH090XV60C* | 43,000 | $2,150 |
| No | 207436515 | LENNOX | SL25XPV-048-230A** | C35-49C+TDR+TXV | SL280UH080NV60C* | 43,000 | $2,150 |
| No | 207436516 | LENNOX | SL25XPV-048-230A** | C35-49C+TDR+TXV | SL280UH090V60C* | 43,000 | $2,150 |
| No | 207436437 | LENNOX | SL25XPV-036-230A** | CR33-48B*+TDR+TXV | SLP99DF070XV36B* | 34,200 | $1,710 |
| No | 207436380 | LENNOX | SL25XPV-036-230A** | CH35-48C+TDR+TXV | SLP99UH110XV60C* | 30,400 | $1,520 |
| No | 207436434 | LENNOX | SL25XPV-036-230A** | CR33-48B*+TDR+TXV | EL296DF070XV48B* | 34,200 | $1,710 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207436378 | LENNOX | SL25XPV-036-230A** | CH35-48C+TDR+TXV | SLP99UH090XV48C* | 30,400 | $1,520 |
| No | 207436379 | LENNOX | SL25XPV-036-230A** | CH35-48C+TDR+TXV | SLP99UH090XV60C* | 30,200 | $1,510 |
| No | 207436376 | LENNOX | SL25XPV-036-230A** | CH35-48C+TDR+TXV | SL297UH080NV60C* | 30,400 | $1,520 |
| No | 207436377 | LENNOX | SL25XPV-036-230A** | CH35-48C+TDR+TXV | SLP99UH090XV36C* | 30,400 | $1,520 |
| No | 207436375 | LENNOX | SL25XPV-036-230A** | CH35-48C+TDR+TXV | SL297UH080NV48C* | 30,200 | $1,510 |
| No | 207436374 | LENNOX | SL25XPV-036-230A** | CH35-48C+TDR+TXV | SL280UH110XV60C* | 30,200 | $1,510 |
| No | 207436373 | LENNOX | SL25XPV-036-230A** | CH35-48C+TDR+TXV | SL280UH110V60C* | 30,200 | $1,510 |
| No | 207436372 | LENNOX | SL25XPV-036-230A** | CH35-48C+TDR+TXV | SL280UH100NV60C* | 30,000 | $1,500 |
| No | 207436369 | LENNOX | SL25XPV-036-230A** | CH35-48C+TDR+TXV | SL280UH080NV60C* | 30,200 | $1,510 |
| No | 207436371 | LENNOX | SL25XPV-036-230A** | CH35-48C+TDR+TXV | SL280UH090XV60C* | 30,200 | $1,510 |
| No | 207436366 | LENNOX | SL25XPV-036-230A** | CH35-48C+TDR+TXV | EL296UH090XV60C* | 30,200 | $1,510 |
| No | 207436368 | LENNOX | SL25XPV-036-230A** | CH35-48C+TDR+TXV | EL296UH110XV60C* | 30,400 | $1,520 |
| No | 207436367 | LENNOX | SL25XPV-036-230A** | CH35-48C+TDR+TXV | EL296UH110XV48C* | 30,200 | $1,510 |
| No | 207436433 | LENNOX | SL25XPV-036-230A** | CR33-48B*+TDR+TXV | EL296DF045XV36B* | 34,200 | $1,710 |
| No | 207436365 | LENNOX | SL25XPV-036-230A** | CH35-48C+TDR+TXV | EL296UH090XV48C* | 30,400 | $1,520 |
| No | 207436364 | LENNOX | SL25XPV-036-230A** | CH35-48C+TDR+TXV | EL296UH090XV36C* | 30,400 | $1,520 |
| No | 207436370 | LENNOX | SL25XPV-036-230A** | CH35-48C+TDR+TXV | SL280UH090V60C* | 30,200 | $1,510 |
| No | 207436346 | LENNOX | SL25XPV-036-230A** | CH35-42C+TDR+TXV | SL280UH100NV60C* | 29,800 | $1,490 |
| No | 207436343 | LENNOX | SL25XPV-036-230A** | CH35-42C+TDR+TXV | SL280UH080NV60C* | 29,800 | $1,490 |
| No | 207436225 | LENNOX | SL25XPV-024-230A** | CR33-50/60+TDR+TXV | SLP99DF090XV36C* | 24,800 | $1,240 |
| No | 207436224 | LENNOX | SL25XPV-024-230A** | CR33-50/60+TDR+TXV | SL280DF110V60C* | 24,800 | $1,240 |
| No | 207436143 | LENNOX | SL25XPV-036-230A** | CBA38MV-060-230*+TDR | | 31,800 | $1,590 |
| No | 10058816 | LENNOX | MPB009S4S-1P | MMDA009S4-2P | | 6,200 | $310 |
| No | 207683506 | LENNOX | MPC024S4S-1P | MMDB024S4-2P | | 13,500 | $675 |
| No | 207683528 | LENNOX | MLB012S4S-1P | MFMA012S4-1P | | 8,400 | $420 |
| No | 207683518 | LENNOX | MPC036S4S-1P | M33C036S4-1P | | 23,000 | $1,150 |
| No | 207683519 | LENNOX | MPC048S4S-1P | M33C048S4-1P | | 28,000 | $1,400 |
| No | 207683507 | LENNOX | MPC036S4S-1P | MMDB036S4-2P | | 27,000 | $1,350 |
| No | 207683513 | LENNOX | MPC048S4S-1P | MCFA048S4-2P | | 29,000 | $1,450 |
| No | 207683517 | LENNOX | MPC024S4S-1P | M33C024S4-1P | | 15,600 | $780 |
| No | 207683508 | LENNOX | MPC048S4S-1P | MMDB048S4-2P | | 29,000 | $1,450 |
| No | 207683516 | LENNOX | MPC018S4S-1P | M22A018S4-2P | | 12,000 | $600 |
| No | 201796631 | LENNOX | MPB012S4S-1P | MWMA012S4-3P | | 7,700 | $385 |
| No | 201796629 | LENNOX | MPB012S4S-1L | MWMB012S4-2L | | 7,600 | $380 |
| No | 10058835 | LENNOX | MPB018S4S-1P | M22A018S4-2P | | 12,000 | $600 |
| No | 10058836 | LENNOX | MPB024S4S-1P | M33A024S4-1P | | 15,800 | $790 |
| No | 10058834 | LENNOX | MPB018S4S-1P | M22A018S4-1P | | 12,000 | $600 |
| No | 10058833 | LENNOX | MPB012S4S-1P | M22A012S4-2P | | 7,500 | $375 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10058831 | LENNOX | MPB009S4S-1P | M22A009S4-2P | | 5,800 | $290 |
| No | 10058830 | LENNOX | MPB009S4S-1P | M22A009S4-1P | | 5,800 | $290 |
| No | 10058832 | LENNOX | MPB012S4S-1P | M22A012S4-1P | | 7,500 | $375 |
| No | 10058827 | LENNOX | MPB024S4S-1P | MCFA024S4-2P | | 15,000 | $750 |
| No | 10058826 | LENNOX | MPB024S4S-1P | MCFA024S4-1P | | 15,000 | $750 |
| No | 10058825 | LENNOX | MPB018S4S-1P | MCFB018S4-2P | | 12,000 | $600 |
| No | 10056176 | LENNOX | MPB024S4S-1P | MWMA024S4-2P | | 15,300 | $765 |
| No | 10056175 | LENNOX | MPB024S4S-1P | MWMA024S4-1P | | 15,300 | $765 |
| No | 10056172 | LENNOX | MPB012S4S-1P | MWMA012S4-2P | | 7,700 | $385 |
| No | 10056174 | LENNOX | MPB018S4S-1P | MWMA018S4-2P | | 11,400 | $570 |
| No | 10056173 | LENNOX | MPB018S4S-1P | MWMA018S4-1P | | 11,400 | $570 |
| No | 10056171 | LENNOX | MPB012S4S-1P | MWMA012S4-1P | | 7,700 | $385 |
| No | 10056168 | LENNOX | MPB012S4S-1L | MWMB012S4-1L | | 7,600 | $380 |
| No | 9920038 | LENNOX | MLA009S4S-1P | MWMA009S4-2P | | 6,900 | $345 |
| No | 206717004 | LG | LMU481HV | Heat pump with ducts | | 33,800 | $1,690 |
| No | 10070561 | LG | ARUB060GSS4 | Heat pump without ducts | | 42,500 | $2,125 |
| No | 10271657 | LG | ARUB060GSS4 | Heat pump with ducts | | 42,500 | $2,125 |
| No | 208132538 | LG | LMU243HV | Combination heat pumps with or without ducts | | 14,750 | $738 |
| No | 208131887 | LG | LMU243HV | Heat pump with ducts | | 14,600 | $730 |
| No | 208131886 | LG | LMU243HV | Heat pump without ducts | | 14,900 | $745 |
| No | 208131891 | LG | LMU363HV | Heat pump with ducts | | 20,000 | $1,000 |
| No | 208132539 | LG | LMU303HV | Combination heat pumps with or without ducts | | 19,000 | $950 |
| No | 208132540 | LG | LMU363HV | Combination heat pumps with or without ducts | | 20,400 | $1,020 |
| No | 208131889 | LG | LMU303HV | Heat pump with ducts | | 18,000 | $900 |
| No | 208131890 | LG | LMU363HV | Heat pump without ducts | | 21,000 | $1,050 |
| No | 208131888 | LG | LMU303HV | Heat pump without ducts | | 20,000 | $1,000 |
| No | 206716999 | LG | LMU481HV | Heat pump without ducts | | 33,800 | $1,690 |
| No | 206221544 | LG | LMU240HV | Heat pump without ducts | | 15,200 | $760 |
| No | 10514710 | LG | ARUN060GSS4 | Heat pump without ducts | | 40,000 | $2,000 |
| No | 10070562 | LG | ARUN024GSS4 | Heat pump without ducts | | 18,000 | $900 |
| No | 8111358 | LG | LMU480HV | Heat pump without ducts | | 34,080 | $1,704 |
| No | 10271659 | LG | ARUB060GSS4 | Combination heat pumps with or without ducts | | 40,000 | $2,000 |
| No | 206717010 | LG | LMU481HV | Combination heat pumps with or without ducts | | 33,800 | $1,690 |
| No | 206717005 | LG | LMU541HV | Unités avec conduits | | 37,200 | $1,860 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206717000 | LG | LMU541HV | Heat pump without ducts | | 37,200 | $1,860 |
| No | 206717011 | LG | LMU541HV | Combinaison d'unités avec et sans conduits | | 37,200 | $1,860 |
| No | 204825179 | LG | LAU150HYV3 | LAN150HYV3 | | 10,900 | $545 |
| No | 10516995 | LG | ARUN060GSS4 | Combination heat pumps with or without ducts | | 40,000 | $2,000 |
| No | 206221551 | LG | LMU240HV | Heat pump with ducts | | 14,500 | $725 |
| No | 206221552 | LG | LMU240HV | Combination heat pumps with or without ducts | | 14,800 | $740 |
| No | 205788769 | LG | LUU360HHV | LHN368HV | | 25,000 | $1,250 |
| No | 205788768 | LG | LUU360HHV | LCN369HV | | 25,400 | $1,270 |
| No | 205788773 | LG | LUU360HHV | LVN361HV4 | | 23,800 | $1,190 |
| No | 205788764 | LG | LUU240HHV | LCN249HV | | 17,400 | $870 |
| No | 205788775 | LG | LUU240HHV | LVN241HV4 | | 18,300 | $915 |
| No | 205788763 | LG | LUU180HHV | LCN188HV4 | | 13,600 | $680 |
| No | 205788774 | LG | LUU180HHV | LVN181HV4 | | 13,400 | $670 |
| No | 6233140 | LG | LAU120HYV | LAN120HYV | | 8,400 | $420 |
| No | 203381517 | LG | LUU127HV | LCN128HV4 | | 9,100 | $455 |
| No | 204825178 | LG | LAU120HYV3 | LAN120HYV3 | | 8,300 | $415 |
| No | 204825177 | LG | LAU090HYV3 | LAN090HYV3 | | 6,700 | $335 |
| No | 10570123 | LG | LSU120HSV5 | LSN120HSV5 | | 8,200 | $410 |
| No | 10567391 | LG | LSU180HSV5 | LSN180HSV5 | | 13,250 | $663 |
| No | 10567390 | LG | LSU180HSV5 | LAN180HSV5 | | 13,250 | $663 |
| No | 10567394 | LG | LSU090HSV5 | LSN090HSV5 | | 6,600 | $330 |
| No | 10570122 | LG | LSU120HSV5 | LAN120HSV5 | | 8,350 | $418 |
| No | 10567393 | LG | LSU090HSV5 | LAN090HSV5 | | 6,690 | $335 |
| No | 8584526 | LG | LAU240HYV1 | LAN240HYV1 | | 17,200 | $860 |
| No | 7947563 | LG | LAU090HYV1 | LAN090HYV1 | | 6,750 | $338 |
| No | 8111355 | LG | LMU30CHV | Heat pump without ducts | | 19,600 | $980 |
| No | 7184507 | LG | LMU24CHV | Combination heat pumps with or without ducts | | 14,250 | $713 |
| No | 8584525 | LG | LAU180HYV1 | LAN180HYV1 | | 13,000 | $650 |
| No | 7180063 | LG | LMU36CHV | Heat pump without ducts | | 20,000 | $1,000 |
| No | 10513886 | LG | LUU188HV | LVN180HV4 | | 12,600 | $630 |
| No | 5859621 | LG | LUU247HV | LHN247HV | | 17,600 | $880 |
| No | 5859622 | LG | LUU367HV | LHN367HV | | 24,600 | $1,230 |
| No | 10401183 | LG | LUU488HV | LVN480HV | | 37,000 | $1,850 |
| No | 10400575 | LG | LUU428HV | LVN420HV | | 30,600 | $1,530 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 8111360 | LG | LMU480HV | Combination heat pumps with or without ducts | | 34,300 | $1,715 |
| No | 8111357 | LG | LMU480HV | Heat pump with ducts | | 33,600 | $1,680 |
| No | 8898929 | LG | LMU600HV | Heat pump with ducts | | 43,000 | $2,150 |
| No | 7184505 | LG | LMU24CHV | Heat pump with ducts | | 14,000 | $700 |
| No | 7184506 | LG | LMU18CHV | Combination heat pumps with or without ducts | | 13,250 | $663 |
| No | 7180061 | LG | LMU18CHV | Heat pump with ducts | | 13,000 | $650 |
| No | 8111356 | LG | LMU30CHV | Heat pump with ducts | | 19,000 | $950 |
| No | 7184508 | LG | LMU36CHV | Combination heat pumps with or without ducts | | 19,750 | $988 |
| No | 8111359 | LG | LMU30CHV | Combination heat pumps with or without ducts | | 19,300 | $965 |
| No | 7180064 | LG | LMU36CHV | Heat pump with ducts | | 19,500 | $975 |
| No | 203381526 | LG | LUU097HV | LCN098HV4 | | 7,000 | $350 |
| No | 9122552 | LG | LSU243HLV | LSN243HLV | | 17,900 | $895 |
| No | 7180062 | LG | LMU24CHV | Heat pump without ducts | | 14,500 | $725 |
| No | 8931559 | LG | LUU127HV | LDN127HV4 | | 10,000 | $500 |
| No | 10570124 | LG | LGU121HSV3 | LGN121HSV3 | | 8,200 | $410 |
| No | 7484109 | LG | LSU090HSV4 | LAN090HSV4 | | 6,600 | $330 |
| No | 5859619 | LG | LUU187HV | LCN187HV | | 12,500 | $625 |
| No | 10399150 | LG | LUU368HV | LVN360HV4 | | 25,600 | $1,280 |
| No | 8717934 | LG | ARUN048GSS4 | Combination heat pumps with or without ducts | | 32,000 | $1,600 |
| No | 10514711 | LG | ARUN060GSS4 | Heat pump with ducts | | 40,000 | $2,000 |
| No | 10271658 | LG | ARUN024GSS4 | Combination heat pumps with or without ducts | | 17,500 | $875 |
| No | 10513887 | LG | LUU248HV | LVN240HV4 | | 18,000 | $900 |
| No | 8898930 | LG | LMU600HV | Combination heat pumps with or without ducts | | 42,000 | $2,100 |
| No | 8898928 | LG | LMU600HV | Heat pump without ducts | | 41,000 | $2,050 |
| No | 205049407 | LG | LUU127HV | LQN120HV4 | | 9,200 | $460 |
| No | 204825182 | LG | LSU243HLV3 | LSN243HLV3 | | 15,800 | $790 |
| No | 204825180 | LG | LAU180HYV3 | LAN180HYV3 | | 13,100 | $655 |
| No | 204825181 | LG | LAU240HYV3 | LAN240HYV3 | | 15,800 | $790 |
| No | 210693475 | LIBERTY HEATING & AIR CONDITIONING | ASZV906010A* | CSCF4860N6D*+TXV | G*VM971205DNB* | 32,400 | $1,620 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210693474 | LIBERTY HEATING & AIR CONDITIONING | ASZV906010A* | CSCF4860N6D*+TXV | G*VM971005CNB* | 32,400 | $1,620 |
| No | 210693473 | LIBERTY HEATING & AIR CONDITIONING | ASZV906010A* | CSCF4860N6D*+TXV | G*VC961205DNB* | 32,400 | $1,620 |
| No | 210693472 | LIBERTY HEATING & AIR CONDITIONING | ASZV906010A* | CSCF4860N6D*+TXV | G*VC961005CNB* | 32,400 | $1,620 |
| No | 210693471 | LIBERTY HEATING & AIR CONDITIONING | ASZV906010A* | CSCF4860N6D*+TXV | G*VS960805CUA* | 32,400 | $1,620 |
| No | 210693467 | LIBERTY HEATING & AIR CONDITIONING | ASZV906010A* | CHPF4860D6D*+TXV | G*VM971205DNB* | 32,400 | $1,620 |
| No | 210693466 | LIBERTY HEATING & AIR CONDITIONING | ASZV906010A* | CHPF4860D6D*+TXV | G*VM971005CNB* | 32,400 | $1,620 |
| No | 210693465 | LIBERTY HEATING & AIR CONDITIONING | ASZV906010A* | CHPF4860D6D*+TXV | G*VC961205DNB* | 32,400 | $1,620 |
| No | 210693464 | LIBERTY HEATING & AIR CONDITIONING | ASZV906010A* | CHPF4860D6D*+TXV | G*VC961005CNB* | 32,400 | $1,620 |
| No | 210693463 | LIBERTY HEATING & AIR CONDITIONING | ASZV906010A* | CHPF4860D6D*+TXV | G*VS960805CUA* | 32,400 | $1,620 |
| No | 210693459 | LIBERTY HEATING & AIR CONDITIONING | ASZV906010A* | CHPF4860D6D*+MBVC2001**-1A*+TXV | | 32,400 | $1,620 |
| No | 210693458 | LIBERTY HEATING & AIR CONDITIONING | ASZV906010A* | CA*F4961*6D*+TXV | G*VM971205DNB* | 33,400 | $1,670 |
| No | 210693457 | LIBERTY HEATING & AIR CONDITIONING | ASZV906010A* | CA*F4961*6D*+TXV | G*VM971005CNB* | 33,400 | $1,670 |
| No | 210693456 | LIBERTY HEATING & AIR CONDITIONING | ASZV906010A* | CA*F4961*6D*+TXV | G*VC961205DNB* | 33,400 | $1,670 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210693455 | LIBERTY HEATING & AIR CONDITIONING | ASZV906010A* | CA*F4961*6D*+TXV | G*VC961005CNB* | 33,400 | $1,670 |
| No | 210693454 | LIBERTY HEATING & AIR CONDITIONING | ASZV906010A* | CA*F4961*6D*+TXV | G*VS960805CUA* | 33,400 | $1,670 |
| No | 210607426 | LIBERTY HEATING & AIR CONDITIONING | ASZV906010A* | CA*F4961*6D*+MBVC2001**-1A*+TX | | 34,000 | $1,700 |
| No | 210609993 | LIBERTY HEATING & AIR CONDITIONING | ASZV906010A* | AMVE60DP1400A* | | 33,400 | $1,670 |
| No | 210693450 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CSCF4860N6D*+TXV | G*VM971205DNB* | 27,000 | $1,350 |
| No | 210693449 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CSCF4860N6D*+TXV | G*VM971005CNB* | 27,000 | $1,350 |
| No | 210693448 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CSCF4860N6D*+TXV | G*VM970804CNB* | 27,000 | $1,350 |
| No | 210693447 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CSCF4860N6D*+TXV | G*VC961205DNB* | 27,000 | $1,350 |
| No | 210693446 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CSCF4860N6D*+TXV | G*VC961005CNB* | 27,000 | $1,350 |
| No | 210693445 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CSCF4860N6D*+TXV | G*VS960805CUA* | 27,000 | $1,350 |
| No | 210693444 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CSCF4860N6D*+TXV | G*VC960804CNB* | 27,000 | $1,350 |
| No | 210693438 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CSCF4860N6D*+MBVC2001**-1A*+TXV | | 27,000 | $1,350 |
| No | 210693437 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CSCF4860N6D*+MBVC1601**-1A*+TXV | | 27,000 | $1,350 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210693436 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CHPF4860D6D*+TXV | G*VM971205DNB* | 27,000 | $1,350 |
| No | 210693435 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CHPF4860D6D*+TXV | G*VM971005CNB* | 27,000 | $1,350 |
| No | 210693434 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CHPF4860D6D*+TXV | G*VM970804CNB* | 27,000 | $1,350 |
| No | 210693433 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CHPF4860D6D*+TXV | G*VC961205DNB* | 27,000 | $1,350 |
| No | 210693432 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CHPF4860D6D*+TXV | G*VC961005CNB* | 27,000 | $1,350 |
| No | 210693431 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CHPF4860D6D*+TXV | G*VC960804CNB* | 27,000 | $1,350 |
| No | 210693427 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CHPF4860D6D*+MBVC2001**-1A*+TXV | | 27,000 | $1,350 |
| No | 210693426 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CHPF4860D6D*+MBVC1601**-1A*+TXV | | 27,000 | $1,350 |
| No | 210693425 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CA*F4961*6D*+TXV | G*VM971205DNB* | 27,000 | $1,350 |
| No | 210693424 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CA*F4961*6D*+TXV | G*VM971005CNB* | 27,000 | $1,350 |
| No | 210693423 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CA*F4961*6D*+TXV | G*VM970804CNB* | 27,000 | $1,350 |
| No | 210693422 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CA*F4961*6D*+TXV | G*VC961205DNB* | 27,000 | $1,350 |
| No | 210693421 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CA*F4961*6D*+TXV | G*VC961005CNB* | 27,000 | $1,350 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210693420 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CA*F4961*6D*+TXV | G*VS960805CUA* | 27,000 | $1,350 |
| No | 210693419 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CA*F4961*6D*+TXV | G*VC960804CNB* | 27,000 | $1,350 |
| No | 210607420 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CA*F4961*6D*+MBVC2001**-1A*+TX | | 27,000 | $1,350 |
| No | 210693413 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CA*F4961*6D*+MBVC1601**-1A*+TXV | | 27,000 | $1,350 |
| No | 210693412 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CA*F4860*6D*+TXV | G*VM971205DNB* | 27,000 | $1,350 |
| No | 210693411 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CA*F4860*6D*+TXV | G*VM971005CNB* | 27,000 | $1,350 |
| No | 210693410 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CA*F4860*6D*+TXV | G*VM970804CNB* | 27,000 | $1,350 |
| No | 210693409 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CA*F4860*6D*+TXV | G*VC961205DNB* | 27,000 | $1,350 |
| No | 210693408 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CA*F4860*6D*+TXV | G*VC961005CNB* | 27,000 | $1,350 |
| No | 210693407 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CA*F4860*6D*+TXV | G*VS960805CUA* | 27,000 | $1,350 |
| No | 210693406 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CA*F4860*6D*+TXV | G*VC960804CNB* | 27,000 | $1,350 |
| No | 210693401 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CA*F4860*6D*+MBVC2001**-1A*+TXV | | 27,000 | $1,350 |
| No | 210693400 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | CA*F4860*6D*+MBVC1601**-1A*+TXV | | 27,000 | $1,350 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210609987 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | AMVE60DP1400A* | | 27,000 | $1,350 |
| No | 210609986 | LIBERTY HEATING & AIR CONDITIONING | ASZV904810A* | AMVE48DP1400A* | | 27,000 | $1,350 |
| No | 210693311 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CSCF3642N6D*+TXV | G*VM970804CNB* | 14,200 | $710 |
| No | 210693310 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CSCF3642N6D*+TXV | G*VM970803BNB* | 14,200 | $710 |
| No | 210693309 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CSCF3642N6D*+TXV | G*VM970603BNB* | 14,200 | $710 |
| No | 210693308 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CSCF3642N6D*+TXV | G*VC960804CNB* | 14,200 | $710 |
| No | 210693307 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CSCF3642N6D*+TXV | G*VC960803BNB* | 14,200 | $710 |
| No | 210693306 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CSCF3642N6D*+TXV | G*VC960603BNB* | 14,200 | $710 |
| No | 210693305 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CSCF3642N6D*+TXV | G*VS960603BUA* | 14,200 | $710 |
| No | 210693304 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CSCF3642N6D*+TXV | G*VC960403BNB* | 14,200 | $710 |
| No | 210693301 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CSCF3642N6D*+MBVC1201**-1A*+TXV | | 14,200 | $710 |
| No | 210693300 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CHPF3642C6C*+MBVC1201**-1A*+TXV | | 14,100 | $705 |
| No | 210693299 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CHPF3636B6C*+TXV | G*VM970803BNB* | 14,200 | $710 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210693298 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CHPF3636B6C*+TXV | G*VM970603BNB* | 14,200 | $710 |
| No | 210693297 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CHPF3636B6C*+TXV | G*VC960803BNB* | 14,200 | $710 |
| No | 210693296 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CHPF3636B6C*+TXV | G*VC960603BNB* | 14,200 | $710 |
| No | 210693295 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CHPF3636B6C*+TXV | G*VS960603BUA* | 14,200 | $710 |
| No | 210693294 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CHPF3636B6C*+TXV | G*VC960403BNB* | 14,200 | $710 |
| No | 210693291 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CHPF3636B6C*+MBVC1201**-1A*+TXV | | 14,200 | $710 |
| No | 210693290 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CA*F3743*6D*+TXV | G*VM970804CNB* | 14,500 | $725 |
| No | 210693289 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CA*F3743*6D*+TXV | G*VM970803BNB* | 14,500 | $725 |
| No | 210693288 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CA*F3743*6D*+TXV | G*VM970603BNB* | 14,500 | $725 |
| No | 210693287 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CA*F3743*6D*+TXV | G*VC960804CNB* | 14,500 | $725 |
| No | 210693286 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CA*F3743*6D*+TXV | G*VC960803BNB* | 14,500 | $725 |
| No | 210693285 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CA*F3743*6D*+TXV | G*VC960603BNB* | 14,600 | $730 |
| No | 210693284 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CA*F3743*6D*+TXV | G*VS960603BUA* | 14,600 | $730 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210693283 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CA*F3743*6D*+TXV | G*VC960403BNB* | 14,500 | $725 |
| No | 210693280 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CA*F3743*6D*+MBVC1201**-1A*+TXV | | 14,500 | $725 |
| No | 210693279 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CA*F3137*6A*+TXV | G*VM970803BNB* | 13,800 | $690 |
| No | 210693278 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CA*F3137*6A*+TXV | G*VM970603BNB* | 13,800 | $690 |
| No | 210693277 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CA*F3137*6A*+TXV | G*VC960803BNB* | 13,800 | $690 |
| No | 210693276 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CA*F3137*6A*+TXV | G*VC960603BNB* | 13,800 | $690 |
| No | 210693275 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CA*F3137*6A*+TXV | G*VS960603BUA* | 13,800 | $690 |
| No | 210693274 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CA*F3137*6A*+TXV | G*VC960403BNB* | 13,800 | $690 |
| No | 210607575 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | CA*F3137*6A*+MBVC1201**-1A*+TX | | 14,000 | $700 |
| No | 210610037 | LIBERTY HEATING & AIR CONDITIONING | ASZV902410A* | AMVE24BP1400A* | | 14,800 | $740 |
| No | 203258604 | LIBERTY HEATING & AIR CONDITIONING | AVZC200241A* | AVPEC25B14A* | | 13,600 | $680 |
| No | 203258605 | LIBERTY HEATING & AIR CONDITIONING | AVZC200361A* | AVPEC37C14A* | | 18,900 | $945 |
| No | 205976247 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | CA*F4961*6D*+TXV | G*VC961005CNB* | 32,000 | $1,600 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203258606 | LIBERTY HEATING & AIR CONDITIONING | AVZC200361A* | AVPEC59D14A* | | 18,900 | $945 |
| No | 203258614 | LIBERTY HEATING & AIR CONDITIONING | AVZC200481A* | AVPEC59D14A* | | 27,000 | $1,350 |
| No | 205976252 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | CA*F4961*6D*+TXV | G*VS960805CUA* | 32,000 | $1,600 |
| No | 205976269 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | CA*F4961*6D*+MBVC2001**-1A*+TXV | | 32,000 | $1,600 |
| No | 205976268 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | AVPEC61D14A* | | 32,600 | $1,630 |
| No | 205976139 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | CA*F4961*6D*+MBVC2000**-1A*+TXV | | 32,000 | $1,600 |
| No | 205976245 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | CA*F4961*6D*+TXV | G*VC800805C*A* | 32,000 | $1,600 |
| No | 205976246 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | CA*F4961*6D*+TXV | G*VC801005C*A* | 32,000 | $1,600 |
| No | 205976250 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | CA*F4961*6D*+TXV | G*VM971205DNB* | 32,000 | $1,600 |
| No | 205976248 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | CA*F4961*6D*+TXV | G*VC961205DNB* | 32,000 | $1,600 |
| No | 205976251 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | CA*F4961*6D*+TXV | G*VS800805CUA* | 32,000 | $1,600 |
| No | 205976249 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | CA*F4961*6D*+TXV | G*VM971005CNB* | 32,000 | $1,600 |
| No | 205976270 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | CHPF4860D6D*+MBVC2001**-1A*+TXV | | 32,000 | $1,600 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205976254 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | CHPF4860D6D*+TXV | G*VC961005CNB* | 32,000 | $1,600 |
| No | 205976302 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | CHPF4860D6D*+TXV | G*VC800805C*A* | 32,000 | $1,600 |
| No | 205976255 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | CHPF4860D6D*+TXV | G*VC961205DNB* | 32,000 | $1,600 |
| No | 205976258 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | CHPF4860D6D*+MBVC2000**-1A*+TXV | | 32,000 | $1,600 |
| No | 205976253 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | CHPF4860D6D*+TXV | G*VC801005C*A* | 32,000 | $1,600 |
| No | 205976256 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | CHPF4860D6D*+TXV | G*VM971005CNB* | 32,000 | $1,600 |
| No | 205976257 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | CHPF4860D6D*+TXV | G*VM971205DNB* | 32,000 | $1,600 |
| No | 205976261 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | CSCF4860N6D*+TXV | G*VC801005C*A* | 32,000 | $1,600 |
| No | 205976267 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | CSCF4860N6D*+TXV | G*VS960805CUA* | 32,000 | $1,600 |
| No | 205976259 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | CHPF4860D6D*+TXV | G*VS800805CUA* | 32,000 | $1,600 |
| No | 205976303 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | CHPF4860D6D*+TXV | G*VS960805CUA* | 32,000 | $1,600 |
| No | 205976260 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | CSCF4860N6D*+TXV | G*VC800805C*A* | 32,000 | $1,600 |
| No | 205976262 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | CSCF4860N6D*+TXV | G*VC961005CNB* | 32,000 | $1,600 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205976263 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | CSCF4860N6D*+TXV | G*VC961205DNB* | 32,000 | $1,600 |
| No | 205976264 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | CSCF4860N6D*+TXV | G*VM971005CNB* | 32,000 | $1,600 |
| No | 205976266 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | CSCF4860N6D*+TXV | G*VS800805CUA* | 32,000 | $1,600 |
| No | 205976265 | LIBERTY HEATING & AIR CONDITIONING | AVZC200601B* | CSCF4860N6D*+TXV | G*VM971205DNB* | 32,000 | $1,600 |
| No | 206145086 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3642*6D*+TXV | G*VC960804CNB* | 18,200 | $910 |
| No | 206145076 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3137*6A*+TXV | G*VC800604B*A* | 18,200 | $910 |
| No | 206145077 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3137*6A*+TXV | G*VC960403BNB* | 18,200 | $910 |
| No | 206145080 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3642*6D*+TXV | G*VC800604B*A* | 18,200 | $910 |
| No | 206145078 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3137*6A*+TXV | G*VC960603BNB* | 18,200 | $910 |
| No | 206145079 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3137*6A*+TXV | G*VC960803BNB* | 18,200 | $910 |
| No | 206145081 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3642*6D*+TXV | G*VC800805C*A* | 18,000 | $900 |
| No | 206145083 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3642*6D*+TXV | G*VC960403BNB* | 18,000 | $900 |
| No | 206145082 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3642*6D*+TXV | G*VC801005C*A* | 18,000 | $900 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206145084 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3642*6D*+TXV | G*VC960603BNB* | 18,000 | $900 |
| No | 206145085 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3642*6D*+TXV | G*VC960803BNB* | 18,000 | $900 |
| No | 206145092 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3743*6D*+TXV | G*VC960403BNB* | 18,200 | $910 |
| No | 206145090 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3743*6D*+TXV | G*VC800805C*A* | 18,200 | $910 |
| No | 206145089 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3743*6D*+TXV | G*VC800604B*A* | 18,000 | $900 |
| No | 206145087 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3642*6D*+TXV | G*VC961005CNB* | 18,000 | $900 |
| No | 206145088 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3642*6D*+TXV | G*VC961205DNB* | 18,000 | $900 |
| No | 206145091 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3743*6D*+TXV | G*VC801005C*A* | 18,200 | $910 |
| No | 206145098 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3642C6C*+TXV | G*VC800604B*A* | 18,000 | $900 |
| No | 206145094 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3743*6D*+TXV | G*VC960803BNB* | 18,200 | $910 |
| No | 206145096 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3743*6D*+TXV | G*VC961005CNB* | 18,200 | $910 |
| No | 206145093 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3743*6D*+TXV | G*VC960603BNB* | 18,200 | $910 |
| No | 206145095 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3743*6D*+TXV | G*VC960804CNB* | 18,000 | $900 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206145097 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3743*6D*+TXV | G*VC961205DNB* | 18,200 | $910 |
| No | 206145101 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3642C6C*+TXV | G*VC960403BNB* | 18,000 | $900 |
| No | 206145100 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3642C6C*+TXV | G*VC801005C*A* | 18,000 | $900 |
| No | 206145099 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3642C6C*+TXV | G*VC800805C*A* | 18,000 | $900 |
| No | 206145102 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3642C6C*+TXV | G*VC960603BNB* | 18,000 | $900 |
| No | 206145104 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3642C6C*+TXV | G*VC960804CNB* | 18,000 | $900 |
| No | 206145103 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3642C6C*+TXV | G*VC960803BNB* | 18,000 | $900 |
| No | 206145107 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3743C6B*+TXV | G*VC800805C*A* | 18,200 | $910 |
| No | 206145105 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3642C6C*+TXV | G*VC961005CNB* | 18,000 | $900 |
| No | 206145106 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3743C6B*+TXV | G*VC800604B*A* | 18,200 | $910 |
| No | 206145108 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3743C6B*+TXV | G*VC801005C*A* | 18,200 | $910 |
| No | 206145109 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3743C6B*+TXV | G*VC960403BNB* | 18,200 | $910 |
| No | 206145111 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3743C6B*+TXV | G*VC960803BNB* | 18,200 | $910 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206145112 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3743C6B*+TXV | G*VC960804CNB* | 18,200 | $910 |
| No | 206145110 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3743C6B*+TXV | G*VC960603BNB* | 18,200 | $910 |
| No | 206145115 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3743C6B*+TXV | G*VM971005CNB* | 18,200 | $910 |
| No | 206145113 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3743C6B*+TXV | G*VC961005CNB* | 18,200 | $910 |
| No | 206145114 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3743C6B*+TXV | G*VM970804CNB* | 18,200 | $910 |
| No | 206145121 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CSCF3642N6D*+TXV | G*VC960803BNB* | 18,200 | $910 |
| No | 206145117 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CSCF3642N6D*+TXV | G*VC800805C*A* | 18,200 | $910 |
| No | 206145120 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CSCF3642N6D*+TXV | G*VC960603BNB* | 18,200 | $910 |
| No | 206145119 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CSCF3642N6D*+TXV | G*VC960403BNB* | 18,200 | $910 |
| No | 206145118 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CSCF3642N6D*+TXV | G*VC801005C*A* | 18,200 | $910 |
| No | 206145116 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CSCF3642N6D*+TXV | G*VC800604B*A* | 18,200 | $910 |
| No | 206145122 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CSCF3642N6D*+TXV | G*VC960804CNB* | 18,200 | $910 |
| No | 206145123 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CSCF3642N6D*+TXV | G*VC961005CNB* | 18,200 | $910 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206145240 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4860*6D*+TXV | G*VC800604B*A* | 27,400 | $1,370 |
| No | 206145243 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4860*6D*+TXV | G*VC960804CNB* | 27,400 | $1,370 |
| No | 206145241 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4860*6D*+TXV | G*VC800805C*A* | 27,400 | $1,370 |
| No | 206145124 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CSCF3642N6D*+TXV | G*VC961205DNB* | 18,200 | $910 |
| No | 206145242 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4860*6D*+TXV | G*VC801005C*A* | 27,400 | $1,370 |
| No | 206145251 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4961*6D*+TXV | G*VC961205DNB* | 27,800 | $1,390 |
| No | 206145244 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4860*6D*+TXV | G*VC961005CNB* | 27,400 | $1,370 |
| No | 206145256 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CHPF4860D6D*+TXV | G*VC961205DNB* | 27,800 | $1,390 |
| No | 206145245 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4860*6D*+TXV | G*VC961205DNB* | 27,400 | $1,370 |
| No | 206145247 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4961*6D*+TXV | G*VC800805C*A* | 27,600 | $1,380 |
| No | 206145246 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4961*6D*+TXV | G*VC800604B*A* | 28,000 | $1,400 |
| No | 206145255 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CHPF4860D6D*+TXV | G*VC961005CNB* | 27,800 | $1,390 |
| No | 206145248 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4961*6D*+TXV | G*VC801005C*A* | 27,800 | $1,390 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206145249 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4961*6D*+TXV | G*VC960804CNB* | 27,600 | $1,380 |
| No | 206145250 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4961*6D*+TXV | G*VC961005CNB* | 27,800 | $1,390 |
| No | 206145252 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CHPF4860D6D*+TXV | G*VC800805C*A* | 27,600 | $1,380 |
| No | 206145253 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CHPF4860D6D*+TXV | G*VC801005C*A* | 27,600 | $1,380 |
| No | 206145254 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CHPF4860D6D*+TXV | G*VC960804CNB* | 27,800 | $1,390 |
| No | 206145259 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CSCF4860N6D*+TXV | G*VC801005C*A* | 27,400 | $1,370 |
| No | 206145258 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CSCF4860N6D*+TXV | G*VC800805C*A* | 27,400 | $1,370 |
| No | 206145257 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CSCF4860N6D*+TXV | G*VC800604B*A* | 27,400 | $1,370 |
| No | 203258320 | LIBERTY HEATING & AIR CONDITIONING | AVZC200361A* | CA*F3642*6D*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 206145260 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CSCF4860N6D*+TXV | G*VC960804CNB* | 27,400 | $1,370 |
| No | 203258313 | LIBERTY HEATING & AIR CONDITIONING | AVZC200361A* | CA*F3137*6A*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 206145262 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CSCF4860N6D*+TXV | G*VC961205DNB* | 27,400 | $1,370 |
| No | 206145261 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CSCF4860N6D*+TXV | G*VC961005CNB* | 27,400 | $1,370 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203258225 | LIBERTY HEATING & AIR CONDITIONING | AVZC200241A* | CA*F3137*6A*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 203258253 | LIBERTY HEATING & AIR CONDITIONING | AVZC200241A* | CA*F3636*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 203258303 | LIBERTY HEATING & AIR CONDITIONING | AVZC200241A* | CHPF3636B6C*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 203258396 | LIBERTY HEATING & AIR CONDITIONING | AVZC200481A* | CA*F4860*6D*+MBVC1600**-1A*+TXV | | 33,400 | $1,670 |
| No | 203258294 | LIBERTY HEATING & AIR CONDITIONING | AVZC200241A* | CA*F3743*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 203258312 | LIBERTY HEATING & AIR CONDITIONING | AVZC200361A* | CA*F3137*6A*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 203258321 | LIBERTY HEATING & AIR CONDITIONING | AVZC200361A* | CA*F3642*6D*+MBVC1600**-1A*+TXV | | 18,000 | $900 |
| No | 203258336 | LIBERTY HEATING & AIR CONDITIONING | AVZC200361A* | CA*F3743*6D*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 203258352 | LIBERTY HEATING & AIR CONDITIONING | AVZC200361A* | CHPF3642C6C*+MBVC1600**-1A*+TXV | | 18,000 | $900 |
| No | 203258351 | LIBERTY HEATING & AIR CONDITIONING | AVZC200361A* | CHPF3642C6C*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 203258366 | LIBERTY HEATING & AIR CONDITIONING | AVZC200361A* | CHPF3743C6B*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 203258381 | LIBERTY HEATING & AIR CONDITIONING | AVZC200361A* | CSCF3642N6D*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 203258380 | LIBERTY HEATING & AIR CONDITIONING | AVZC200361A* | CSCF3642N6D*+MBVC1200**-1A*+TXV | | 18,200 | $910 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203258397 | LIBERTY HEATING & AIR CONDITIONING | AVZC200481A* | CA*F4860*6D*+MBVC2000**-1A*+TXV | | 33,400 | $1,670 |
| No | 203258367 | LIBERTY HEATING & AIR CONDITIONING | AVZC200361A* | CHPF3743C6B*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 203258407 | LIBERTY HEATING & AIR CONDITIONING | AVZC200481A* | CA*F4961*6D*+MBVC1600**-1A*+TXV | | 34,000 | $1,700 |
| No | 203258417 | LIBERTY HEATING & AIR CONDITIONING | AVZC200481A* | CHPF4860D6D*+MBVC1600**-1A*+TXV | | 34,000 | $1,700 |
| No | 203258418 | LIBERTY HEATING & AIR CONDITIONING | AVZC200481A* | CHPF4860D6D*+MBVC2000**-1A*+TXV | | 34,000 | $1,700 |
| No | 203258427 | LIBERTY HEATING & AIR CONDITIONING | AVZC200481A* | CSCF4860N6D*+MBVC1600**-1A*+TXV | | 33,400 | $1,670 |
| No | 203258607 | LIBERTY HEATING & AIR CONDITIONING | AVZC200481A* | AVPEC61D14A* | | 28,600 | $1,430 |
| No | 203258609 | LIBERTY HEATING & AIR CONDITIONING | AVZC200241A* | CA*F3642*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 203258428 | LIBERTY HEATING & AIR CONDITIONING | AVZC200481A* | CSCF4860N6D*+MBVC2000**-1A*+TXV | | 33,400 | $1,670 |
| No | 203258610 | LIBERTY HEATING & AIR CONDITIONING | AVZC200361A* | CA*F3743*6D*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 205966142 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3743*6D*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 203258611 | LIBERTY HEATING & AIR CONDITIONING | AVZC200481A* | CA*F4961*6D*+MBVC2000**-1A*+TXV | | 34,000 | $1,700 |
| No | 203258613 | LIBERTY HEATING & AIR CONDITIONING | AVZC200241A* | CHPF3642C6C*+MBVC1200**-1A*+TXV | | 13,000 | $650 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966143 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4961*6D*+MBVC2000**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966141 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CA*F3642*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205966144 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CA*F3137*6A*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205966145 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CA*F3137*6A*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205966151 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CA*F3636*6D*+TXV | G*VM970804CNB* | 13,000 | $650 |
| No | 205966150 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CA*F3636*6D*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205966149 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CA*F3636*6D*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205966147 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CA*F3137*6A*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205966146 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CA*F3137*6A*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205966148 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CA*F3137*6A*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205966152 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CA*F3636*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205966156 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CA*F3642*6D*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205966153 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CA*F3636*6D*+TXV | G*VS800604BUA* | 13,000 | $650 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966157 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CA*F3642*6D*+TXV | G*VM970804CNB* | 13,000 | $650 |
| No | 205966155 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CA*F3642*6D*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205966158 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CA*F3743*6D*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205966154 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CA*F3636*6D*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205966168 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CHPF3636B6C*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205966160 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CA*F3743*6D*+TXV | G*VM970804CNB* | 13,000 | $650 |
| No | 205966161 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CA*F3743*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205966159 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CA*F3743*6D*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205966171 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CSCF3642N6D*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205966162 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CA*F3743*6D*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205966163 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CA*F3743*6D*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205966164 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CHPF3636B6C*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205966165 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CHPF3636B6C*+TXV | G*VM970803BNB* | 13,000 | $650 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966166 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CHPF3636B6C*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205966169 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CHPF3642C6C*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205966167 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CHPF3636B6C*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205966172 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | AVPEC25B14A* | | 13,600 | $680 |
| No | 205966170 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CSCF3642N6D*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205966177 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CHPF3636B6C*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205966176 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CA*F3743*6D*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205966174 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CA*F3636*6D*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205966173 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CA*F3137*6A*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205966175 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CA*F3642*6D*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205966178 | LIBERTY HEATING & AIR CONDITIONING | GVZC200241A* | CHPF3642C6C*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205966183 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3137*6A*+TXV | G*VS800604BUA* | 18,200 | $910 |
| No | 205966181 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3137*6A*+MBVC1200**-1A*+TXV | | 18,000 | $900 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966180 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3137*6A*+TXV | G*VM970803BNB* | 18,200 | $910 |
| No | 205966182 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3137*6A*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 205966184 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3137*6A*+TXV | G*VS960603BUA* | 18,200 | $910 |
| No | 205966179 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3137*6A*+TXV | G*VM970603BNB* | 18,200 | $910 |
| No | 205966187 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3642*6D*+TXV | G*VM970804CNB* | 18,200 | $910 |
| No | 205966185 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3642*6D*+TXV | G*VM970603BNB* | 18,000 | $900 |
| No | 205966186 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3642*6D*+TXV | G*VM970803BNB* | 18,000 | $900 |
| No | 205966189 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3642*6D*+TXV | G*VM971205DNB* | 18,000 | $900 |
| No | 205966188 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3642*6D*+TXV | G*VM971005CNB* | 18,000 | $900 |
| No | 205966190 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3642*6D*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 205966193 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3642*6D*+TXV | G*VS800805CUA* | 18,000 | $900 |
| No | 205966198 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3743*6D*+TXV | G*VM971205DNB* | 18,200 | $910 |
| No | 205966194 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3642*6D*+TXV | G*VS960603BUA* | 18,000 | $900 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966192 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3642*6D*+TXV | G*VS800604BUA* | 18,200 | $910 |
| No | 205966191 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3642*6D*+MBVC1600**-1A*+TXV | | 18,000 | $900 |
| No | 205966199 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3743*6D*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 205966196 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3743*6D*+TXV | G*VM970603BNB* | 18,200 | $910 |
| No | 205966197 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3743*6D*+TXV | G*VM970803BNB* | 18,200 | $910 |
| No | 205966195 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3642*6D*+TXV | G*VS960805CUA* | 18,000 | $900 |
| No | 205966200 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3743*6D*+TXV | G*VS800604BUA* | 18,000 | $900 |
| No | 205966206 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3642C6C*+TXV | G*VM970804CNB* | 18,000 | $900 |
| No | 205966201 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3743*6D*+TXV | G*VS800805CUA* | 18,200 | $910 |
| No | 205966203 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3743*6D*+TXV | G*VS960805CUA* | 18,200 | $910 |
| No | 205966202 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3743*6D*+TXV | G*VS960603BUA* | 18,200 | $910 |
| No | 205966205 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3642C6C*+TXV | G*VM970803BNB* | 18,000 | $900 |
| No | 205966204 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3642C6C*+TXV | G*VM970603BNB* | 18,000 | $900 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966211 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3642C6C*+TXV | G*VS800805CUA* | 18,000 | $900 |
| No | 205966207 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3642C6C*+TXV | G*VM971005CNB* | 18,000 | $900 |
| No | 205966212 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3642C6C*+TXV | G*VS960603BUA* | 18,000 | $900 |
| No | 205966209 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3642C6C*+MBVC1600**-1A*+TXV | | 18,000 | $900 |
| No | 205966208 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3642C6C*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 205966210 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3642C6C*+TXV | G*VS800604BUA* | 18,000 | $900 |
| No | 205966213 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3642C6C*+TXV | G*VS960805CUA* | 18,000 | $900 |
| No | 205966217 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3743*6D*+TXV | G*VM971005CNB* | 18,200 | $910 |
| No | 205966214 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3743C6B*+TXV | G*VM970603BNB* | 18,200 | $910 |
| No | 205966215 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3743C6B*+TXV | G*VM970803BNB* | 18,200 | $910 |
| No | 205966216 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3743*6D*+TXV | G*VM970804CNB* | 18,000 | $900 |
| No | 205966218 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3743C6B*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 205966219 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3743C6B*+MBVC1600**-1A*+TXV | | 18,200 | $910 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966223 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3743C6B*+TXV | G*VS960805CUA* | 18,200 | $910 |
| No | 205966220 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3743C6B*+TXV | G*VS800604BUA* | 18,200 | $910 |
| No | 205966221 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3743C6B*+TXV | G*VS800805CUA* | 18,200 | $910 |
| No | 205966222 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3743C6B*+TXV | G*VS960603BUA* | 18,200 | $910 |
| No | 205966225 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CSCF3642N6D*+TXV | G*VM970803BNB* | 18,200 | $910 |
| No | 205966224 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CSCF3642N6D*+TXV | G*VM970603BNB* | 18,200 | $910 |
| No | 205966228 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CSCF3642N6D*+TXV | G*VM971205DNB* | 18,200 | $910 |
| No | 205966227 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CSCF3642N6D*+TXV | G*VM971005CNB* | 18,200 | $910 |
| No | 205966230 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CSCF3642N6D*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 205966226 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CSCF3642N6D*+TXV | G*VM970804CNB* | 18,200 | $910 |
| No | 205966229 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CSCF3642N6D*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 205966231 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CSCF3642N6D*+TXV | G*VS800604BUA* | 18,200 | $910 |
| No | 205966233 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CSCF3642N6D*+TXV | G*VS960603BUA* | 18,200 | $910 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966235 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | AVPEC37C14A* | | 18,900 | $945 |
| No | 205966232 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CSCF3642N6D*+TXV | G*VS800805CUA* | 18,200 | $910 |
| No | 205966236 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | AVPEC59D14A* | | 18,900 | $945 |
| No | 205966234 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CSCF3642N6D*+TXV | G*VS960805CUA* | 18,200 | $910 |
| No | 205966237 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3137*6A*+MBVC1201**-1A*+TXV | | 18,000 | $900 |
| No | 205966243 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4860*6D*+TXV | G*VS960805CUA* | 27,400 | $1,370 |
| No | 205966239 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3642*6D*+MBVC1201**-1A*+TXV | | 18,000 | $900 |
| No | 205966242 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4860*6D*+MBVC1600**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966238 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3137*6A*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205966240 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3642*6D*+MBVC1601**-1A*+TXV | | 18,000 | $900 |
| No | 205966241 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3743*6D*+MBVC1201**-1A*+TXV | | 18,200 | $910 |
| No | 205966244 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CHPF4860D6D*+TXV | G*VM970804CNB* | 28,000 | $1,400 |
| No | 205966245 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CHPF4860D6D*+TXV | G*VM971005CNB* | 27,800 | $1,390 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966246 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CHPF4860D6D*+TXV | G*VM971205DNB* | 27,800 | $1,390 |
| No | 205966248 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CHPF4860D6D*+TXV | G*VS800805CUA* | 27,200 | $1,360 |
| No | 205966247 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CHPF4860D6D*+MBVC1600**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966250 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CSCF4860N6D*+TXV | G*VM971005CNB* | 27,400 | $1,370 |
| No | 205966249 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CSCF4860N6D*+TXV | G*VM970804CNB* | 27,400 | $1,370 |
| No | 205966256 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CSCF4860N6D*+TXV | G*VS960805CUA* | 27,400 | $1,370 |
| No | 205966255 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CSCF4860N6D*+TXV | G*VS800805CUA* | 27,400 | $1,370 |
| No | 205966252 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CSCF4860N6D*+MBVC1600**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966251 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CSCF4860N6D*+TXV | G*VM971205DNB* | 27,400 | $1,370 |
| No | 205966254 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CSCF4860N6D*+TXV | G*VS800604BUA* | 27,400 | $1,370 |
| No | 205966253 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CSCF4860N6D*+MBVC2000**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966265 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4961*6D*+TXV | G*VM971005CNB* | 27,800 | $1,390 |
| No | 205966259 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4860*6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966258 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4860*6D*+MBVC1601**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966257 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | AVPEC59D14A* | | 27,000 | $1,350 |
| No | 205966260 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CHPF4860D6D*+MBVC1601**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966272 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4961*6D*+MBVC1601**-1A*+TXV | | 26,800 | $1,340 |
| No | 205966262 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CSCF4860N6D*+MBVC1601**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966264 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4961*6D*+TXV | G*VM970804CNB* | 27,800 | $1,390 |
| No | 205966263 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CSCF4860N6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966261 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CHPF4860D6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966269 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4961*6D*+TXV | G*VS800805CUA* | 27,200 | $1,360 |
| No | 205966266 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4961*6D*+TXV | G*VM971205DNB* | 27,800 | $1,390 |
| No | 205966267 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4961*6D*+MBVC1600**-1A*+TXV | | 26,800 | $1,340 |
| No | 205966270 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4961*6D*+TXV | G*VS960805CUA* | 27,600 | $1,380 |
| No | 205966268 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4961*6D*+TXV | G*VS800604BUA* | 28,000 | $1,400 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966271 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CHPF4860D6D*+MBVC2000**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966273 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4961*6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966465 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CA*F3743*6D*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205966466 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3642C6C*+MBVC1201**-1A*+TXV | | 18,000 | $900 |
| No | 205966467 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3642C6C*+MBVC1601**-1A*+TXV | | 18,000 | $900 |
| No | 205966468 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3743C6B*+MBVC1201**-1A*+TXV | | 18,200 | $910 |
| No | 205966471 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CSCF3642N6D*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205966469 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CHPF3743C6B*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205966474 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4860*6D*+TXV | G*VM971205DNB* | 27,400 | $1,370 |
| No | 205966470 | LIBERTY HEATING & AIR CONDITIONING | GVZC200361A* | CSCF3642N6D*+MBVC1201**-1A*+TXV | | 18,200 | $910 |
| No | 205966472 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4860*6D*+TXV | G*VM970804CNB* | 27,400 | $1,370 |
| No | 205966475 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4860*6D*+MBVC2000**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966473 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4860*6D*+TXV | G*VM971005CNB* | 27,400 | $1,370 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966476 | LIBERTY HEATING & AIR CONDITIONING | GVZC200481A* | CA*F4860*6D*+TXV | G*VS800805CUA* | 27,400 | $1,370 |
| No | 208816902 | LIVART | LF360U | LF360N | | 25,200 | $1,260 |
| No | 208141165 | LIVART | LVA18HRN1-19 | LVA18HRN1-19 | | 11,500 | $575 |
| No | 208141163 | LIVART | LVA09HRN1-19 | LVA09HRN1-19 | | 6,900 | $345 |
| No | 209550326 | LIVART | LVAS12KU | LVAS12KN | | 8,900 | $445 |
| No | 211238542 | LUXAIRE | HMH72B341 | JHETC36DBCS2N1 | | 24,600 | $1,230 |
| No | 211719795 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | LPLC060A12MP13 | 25,000 | $1,250 |
| No | 211719793 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | LPLC060A12MP13 | 25,000 | $1,250 |
| No | 211719756 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | LPLC060A12MP13 | 24,200 | $1,210 |
| No | 211719754 | LUXAIRE | HMH72B361 | XAFA30DXXN1+TXV | LPLC060A12MP13 | 25,800 | $1,290 |
| No | 211662224 | LUXAIRE | HMH72B361 | XAUB30CXXN1+JMET12BS2N1+TXV | | 24,800 | $1,240 |
| No | 211662219 | LUXAIRE | HMH72B361 | XAFB30CXXN1+JMET12BS2N1+TXV | | 24,800 | $1,240 |
| No | 211662214 | LUXAIRE | HMH72B361 | XAHB30CXXN1+JMET12BS2N1+TXV | | 23,800 | $1,190 |
| No | 211662209 | LUXAIRE | HMH72B361 | XAUB30CXXN1+JMVT12BC2N1+TXV | | 24,600 | $1,230 |
| No | 211662204 | LUXAIRE | HMH72B361 | XAFB30CXXN1+JMVT12BC2N1+TXV | | 24,600 | $1,230 |
| No | 211662199 | LUXAIRE | HMH72B361 | XAHB30CXXN1+JMVT12BC2N1+TXV | | 24,200 | $1,210 |
| No | 211662194 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | TMLE040A12MP11 | 24,400 | $1,220 |
| No | 211662189 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | TM8E040A12MP11 | 24,400 | $1,220 |
| No | 211662184 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | TMLE040A12MP11 | 24,400 | $1,220 |
| No | 211662179 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | TM8E040A12MP11 | 24,400 | $1,220 |
| No | 211662174 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | TMLE040A12MP11 | 23,800 | $1,190 |
| No | 211662169 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | TM8E040A12MP11 | 23,800 | $1,190 |
| No | 211662164 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | TL8E060A12UH11 | 24,400 | $1,220 |
| No | 211662159 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | TL8E060A12UH11 | 24,400 | $1,220 |
| No | 211662154 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | TL8E060A12UH11 | 24,000 | $1,200 |
| No | 211662149 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TL8E080C16UH11 | 25,200 | $1,260 |
| No | 211662144 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TL8E080C16UH11 | 24,800 | $1,240 |
| No | 211662139 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TL8E100C20UH11 | 24,400 | $1,220 |
| No | 211662134 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TL8E100C20UH11 | 24,000 | $1,200 |
| No | 211662129 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 211662124 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211662119 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 211662114 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | TL9E060B12UH11 | 23,600 | $1,180 |
| No | 211662109 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 211662104 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TL9E080C16UH11 | 24,800 | $1,240 |
| No | 211662099 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TL9E080C16UH11 | 24,400 | $1,220 |
| No | 211662094 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TL9E100C20UH11 | 24,600 | $1,230 |
| No | 211662089 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TL9E100C20UH11 | 24,000 | $1,200 |
| No | 211662084 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | TMLE060A12MP11 | 24,400 | $1,220 |
| No | 211662079 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | TM8E060A12MP11 | 24,400 | $1,220 |
| No | 211662074 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | TMLE060A12MP11 | 24,400 | $1,220 |
| No | 211662069 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | TM8E060A12MP11 | 24,400 | $1,220 |
| No | 211662064 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | TMLE060A12MP11 | 24,000 | $1,200 |
| No | 211662059 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | TM8E060A12MP11 | 24,000 | $1,200 |
| No | 211662054 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 211662049 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 211662044 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 211662039 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 211662034 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 211662029 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 211662024 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | TMLE080B12MP11 | 24,400 | $1,220 |
| No | 211662019 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | TM8E080B12MP11 | 24,400 | $1,220 |
| No | 211662014 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TMLE080B12MP11 | 24,400 | $1,220 |
| No | 211662009 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TM8E080B12MP11 | 24,400 | $1,220 |
| No | 211662004 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TMLE080C16MP11 | 24,200 | $1,210 |
| No | 211661999 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TM8E080C16MP11 | 24,200 | $1,210 |
| No | 211661994 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TMLE080C16MP11 | 23,800 | $1,190 |
| No | 211661989 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TM8E080C16MP11 | 23,800 | $1,190 |
| No | 211661984 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | TMLE100B12MP11 | 24,400 | $1,220 |
| No | 211661979 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | TM8E100B12MP11 | 24,400 | $1,220 |
| No | 211661974 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | TMLE100B12MP11 | 24,400 | $1,220 |
| No | 211661969 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | TM8E100B12MP11 | 24,400 | $1,220 |
| No | 211661964 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TMLE100B12MP11 | 24,400 | $1,220 |
| No | 211661959 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TM8E100B12MP11 | 24,400 | $1,220 |
| No | 211661954 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | TMLE100B12MP11 | 24,000 | $1,200 |
| No | 211661949 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | TM8E100B12MP11 | 24,000 | $1,200 |
| No | 211661944 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TMLE100B12MP11 | 24,000 | $1,200 |
| No | 211661939 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TM8E100B12MP11 | 24,000 | $1,200 |
| No | 211661934 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TMLE100C16MP11 | 24,200 | $1,210 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661929 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TM8E100C16MP11 | 24,200 | $1,210 |
| No | 211661924 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TMLE100C16MP11 | 23,800 | $1,190 |
| No | 211661919 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TM8E100C16MP11 | 23,800 | $1,190 |
| No | 211661914 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TMLE120C16MP11 | 24,200 | $1,210 |
| No | 211661909 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TM8E120C16MP11 | 24,200 | $1,210 |
| No | 211661904 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TMLE120C16MP11 | 23,800 | $1,190 |
| No | 211661899 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TM8E120C16MP11 | 23,800 | $1,190 |
| No | 211661894 | LUXAIRE | HMH72B361 | XAFA30DXXN1+TXV | TPLC060A12MP13 | 25,800 | $1,290 |
| No | 211661889 | LUXAIRE | HMH72B361 | XAFA30DXXN1+TXV | TMLV060A12MP12 | 25,800 | $1,290 |
| No | 211661884 | LUXAIRE | HMH72B361 | XAFA30DXXN1+TXV | TM8V060A12MP12 | 25,800 | $1,290 |
| No | 211661879 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 211661874 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 211661869 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 211661864 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 211661859 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 211661854 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 211661849 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | TPLC060A12MP13 | 24,200 | $1,210 |
| No | 211661844 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | TMLV060A12MP12 | 24,200 | $1,210 |
| No | 211661839 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | TM8V060A12MP12 | 24,200 | $1,210 |
| No | 211661837 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | LPLC080B12MP13 | 24,600 | $1,230 |
| No | 211661833 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 211661828 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 211661826 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | LPLC080B12MP13 | 24,600 | $1,230 |
| No | 211661822 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 211661817 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 211661815 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | LPLC080B12MP13 | 24,800 | $1,240 |
| No | 211661811 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TPLC080B12MP13 | 24,800 | $1,240 |
| No | 211661806 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TM8V080B12MP12 | 24,800 | $1,240 |
| No | 211661804 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | LPLC080B12MP13 | 24,000 | $1,200 |
| No | 211661800 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | TPLC080B12MP13 | 24,000 | $1,200 |
| No | 211661795 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | TM8V080B12MP12 | 24,000 | $1,200 |
| No | 211661793 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | LPLC080B12MP13 | 24,200 | $1,210 |
| No | 211661789 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TPLC080B12MP13 | 24,200 | $1,210 |
| No | 211661784 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TM8V080B12MP12 | 24,200 | $1,210 |
| No | 211661782 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | LPLC100C16MP13 | 25,000 | $1,250 |
| No | 211661780 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | LPLC080C16MP13 | 25,000 | $1,250 |
| No | 211661775 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TPLC100C16MP13 | 25,000 | $1,250 |
| No | 211661770 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TPLC080C16MP13 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661765 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TMLV100C16MP12 | 25,000 | $1,250 |
| No | 211661760 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TM8V080C16MP12 | 25,000 | $1,250 |
| No | 211661755 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TM8V100C16MP12 | 25,000 | $1,250 |
| No | 211661753 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | LPLC100C16MP13 | 24,600 | $1,230 |
| No | 211661751 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | LPLC080C16MP13 | 24,600 | $1,230 |
| No | 211661746 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 211661741 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TPLC080C16MP13 | 24,600 | $1,230 |
| No | 211661736 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TMLV100C16MP12 | 24,600 | $1,230 |
| No | 211661726 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 211661721 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | TM8Y060A12MP11 | 24,200 | $1,210 |
| No | 211661716 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | TM8Y060A12MP11 | 24,200 | $1,210 |
| No | 211661711 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | TM8Y060A12MP11 | 23,800 | $1,190 |
| No | 211661706 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | TM8Y080B12MP11 | 24,200 | $1,210 |
| No | 211661701 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | TM8Y080B12MP11 | 24,200 | $1,210 |
| No | 211661696 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TM8Y080B12MP11 | 24,200 | $1,210 |
| No | 211661691 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | TM8Y080B12MP11 | 23,800 | $1,190 |
| No | 211661686 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TM8Y080B12MP11 | 23,800 | $1,190 |
| No | 211661681 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TM8Y080C16MP11 | 25,200 | $1,260 |
| No | 211661676 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TM8Y100C16MP11 | 25,200 | $1,260 |
| No | 211661671 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TM8Y080C16MP11 | 24,600 | $1,230 |
| No | 211661666 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TM8Y100C16MP11 | 24,600 | $1,230 |
| No | 211661661 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TM8Y100C20MP11 | 24,800 | $1,240 |
| No | 211661656 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TM8Y120C20MP11 | 24,800 | $1,240 |
| No | 211661651 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TM8Y100C20MP11 | 24,400 | $1,220 |
| No | 211661646 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TM8Y120C20MP11 | 24,400 | $1,220 |
| No | 211661641 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | TM9E040A10MP12 | 24,200 | $1,210 |
| No | 211661636 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | TM9E040A10MP12 | 24,200 | $1,210 |
| No | 211661631 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | TM9E060A10MP12 | 24,400 | $1,220 |
| No | 211661626 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | TM9E060A10MP12 | 24,400 | $1,220 |
| No | 211661621 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | TM9E060A10MP12 | 24,000 | $1,200 |
| No | 211661616 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 211661611 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 211661606 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 211661601 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | TM9E060B12MP12 | 24,200 | $1,210 |
| No | 211661596 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 211661591 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 211661586 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 211661581 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661576 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | TM9E080B12MP12 | 24,400 | $1,220 |
| No | 211661571 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TM9E080B12MP12 | 24,400 | $1,220 |
| No | 211661566 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TM9E080C16MP12 | 25,200 | $1,260 |
| No | 211661561 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TM9E080C16MP12 | 24,800 | $1,240 |
| No | 211661556 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TM9E100C16MP12 | 24,400 | $1,220 |
| No | 211661551 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TM9E100C16MP12 | 23,800 | $1,190 |
| No | 211661546 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | TM9V040A10MP12 | 24,400 | $1,220 |
| No | 211661541 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | TM9V040A10MP12 | 24,400 | $1,220 |
| No | 211661534 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | LP9C060B12MP13 | 24,600 | $1,230 |
| No | 211661529 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | TP9C060B12MP13 | 24,600 | $1,230 |
| No | 211661524 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | TM9V060B12MP12 | 24,600 | $1,230 |
| No | 211661522 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | LP9C060B12MP13 | 24,600 | $1,230 |
| No | 211661517 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | TP9C060B12MP13 | 24,600 | $1,230 |
| No | 211661512 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | TM9V060B12MP12 | 24,600 | $1,230 |
| No | 211661510 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | LP9C060B12MP13 | 24,600 | $1,230 |
| No | 211661502 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TP9C060B12MP13 | 24,600 | $1,230 |
| No | 211661496 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TM9V060B12MP12 | 24,600 | $1,230 |
| No | 211661494 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | LP9C060B12MP13 | 24,000 | $1,200 |
| No | 211661489 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | TP9C060B12MP13 | 24,000 | $1,200 |
| No | 211661484 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | TM9V060B12MP12 | 24,000 | $1,200 |
| No | 211661482 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | LP9C060B12MP13 | 24,200 | $1,210 |
| No | 211661477 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TP9C060B12MP13 | 24,200 | $1,210 |
| No | 211661472 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TM9V060B12MP12 | 24,200 | $1,210 |
| No | 211661470 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | LP9C080B12MP13 | 24,800 | $1,240 |
| No | 211661465 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | TP9C080B12MP13 | 24,800 | $1,240 |
| No | 211661460 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | TM9V080B12MP12 | 24,800 | $1,240 |
| No | 211661458 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | LP9C080B12MP13 | 24,800 | $1,240 |
| No | 211661453 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | TP9C080B12MP13 | 24,800 | $1,240 |
| No | 211661448 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | TM9V080B12MP12 | 24,800 | $1,240 |
| No | 211661446 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | LP9C080B12MP13 | 25,000 | $1,250 |
| No | 211661441 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 211661436 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 211661434 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | LP9C080B12MP13 | 24,400 | $1,220 |
| No | 211661429 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 211661424 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 211661422 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | LP9C080B12MP13 | 24,600 | $1,230 |
| No | 211661417 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 211661412 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TM9V080B12MP12 | 24,600 | $1,230 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661410 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | LP9C080C16MP13 | 25,200 | $1,260 |
| No | 211661405 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TP9C080C16MP13 | 25,200 | $1,260 |
| No | 211661400 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TM9V080C16MP12 | 25,200 | $1,260 |
| No | 211661398 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | LP9C080C16MP13 | 24,800 | $1,240 |
| No | 211661393 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TP9C080C16MP13 | 24,800 | $1,240 |
| No | 211661388 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TM9V080C16MP12 | 24,800 | $1,240 |
| No | 211661386 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | LP9C100C16MP13 | 24,800 | $1,240 |
| No | 211661381 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211661376 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TM9V100C16MP12 | 24,800 | $1,240 |
| No | 211661374 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | LP9C100C16MP13 | 24,600 | $1,230 |
| No | 211661369 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TP9C100C16MP13 | 24,600 | $1,230 |
| No | 211661364 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TM9V100C16MP12 | 24,600 | $1,230 |
| No | 211661362 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | LP9C100C20MP13 | 25,000 | $1,250 |
| No | 211661357 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TP9C100C20MP13 | 25,000 | $1,250 |
| No | 211661352 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TM9V100C20MP12 | 25,000 | $1,250 |
| No | 211661350 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | LP9C100C20MP13 | 24,600 | $1,230 |
| No | 211661345 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TP9C100C20MP13 | 24,600 | $1,230 |
| No | 211661340 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TM9V100C20MP12 | 24,600 | $1,230 |
| No | 211661335 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | TM9Y060B12MP11 | 24,800 | $1,240 |
| No | 211661330 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | TM9Y060B12MP11 | 24,800 | $1,240 |
| No | 211661325 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TM9Y060B12MP11 | 24,800 | $1,240 |
| No | 211661320 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | TM9Y060B12MP11 | 24,200 | $1,210 |
| No | 211661315 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TM9Y060B12MP11 | 24,200 | $1,210 |
| No | 211661310 | LUXAIRE | HMH72B361 | XAUB30CXXN1+TXV | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211661305 | LUXAIRE | HMH72B361 | XAFB30CXXN1+TXV | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211661300 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211661295 | LUXAIRE | HMH72B361 | XAHB30CXXN1+TXV | TM9Y080B12MP11 | 24,400 | $1,220 |
| No | 211661290 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TM9Y080B12MP11 | 24,400 | $1,220 |
| No | 211661285 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TM9Y080C16MP11 | 24,800 | $1,240 |
| No | 211661280 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TM9Y080C16MP11 | 24,400 | $1,220 |
| No | 211661275 | LUXAIRE | HMH72B361 | XAFC30CXXN1+TXV | TM9Y100C16MP11 | 24,800 | $1,240 |
| No | 211661270 | LUXAIRE | HMH72B361 | XAHC30CXXN1+TXV | TM9Y100C16MP11 | 24,400 | $1,220 |
| No | 211661265 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | TM9E040A10MP12 | 15,000 | $750 |
| No | 211661260 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | TM9E040A10MP12 | 15,000 | $750 |
| No | 211661255 | LUXAIRE | HMH72B241 | XAUB30CXXN1+TXV | TM9E060A10MP12 | 15,000 | $750 |
| No | 211661250 | LUXAIRE | HMH72B241 | XAFB30CBAN1 | TM9E060A10MP12 | 15,000 | $750 |
| No | 211661245 | LUXAIRE | HMH72B241 | XAFB30CXXN1+TXV | TM9E060A10MP12 | 15,000 | $750 |
| No | 211661240 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | TM9E060A10MP12 | 14,900 | $745 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661235 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | TM9E060A10MP12 | 14,900 | $745 |
| No | 211661230 | LUXAIRE | HMH72B241 | XAUB30CXXN1+TXV | TM9E060B12MP12 | 15,400 | $770 |
| No | 211661225 | LUXAIRE | HMH72B241 | XAFB30CBAN1 | TM9E060B12MP12 | 15,400 | $770 |
| No | 211661220 | LUXAIRE | HMH72B241 | XAFB30CXXN1+TXV | TM9E060B12MP12 | 15,400 | $770 |
| No | 211661215 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TM9E060B12MP12 | 15,400 | $770 |
| No | 211661210 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TM9E060B12MP12 | 15,400 | $770 |
| No | 211661205 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | TM9E060B12MP12 | 15,100 | $755 |
| No | 211661200 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | TM9E060B12MP12 | 15,100 | $755 |
| No | 211661195 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TM9E060B12MP12 | 15,100 | $755 |
| No | 211661187 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TM9E060B12MP12 | 15,100 | $755 |
| No | 211661177 | LUXAIRE | HMH72B241 | XAUB30CXXN1+TXV | TM9E080B12MP12 | 15,700 | $785 |
| No | 211661167 | LUXAIRE | HMH72B241 | XAFB30CBAN1 | TM9E080B12MP12 | 15,700 | $785 |
| No | 211661160 | LUXAIRE | HMH72B241 | XAFB30CXXN1+TXV | TM9E080B12MP12 | 15,700 | $785 |
| No | 211661155 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TM9E080B12MP12 | 15,700 | $785 |
| No | 211661150 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TM9E080B12MP12 | 15,700 | $785 |
| No | 211661145 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | TM9E080B12MP12 | 14,900 | $745 |
| No | 211661140 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | TM9E080B12MP12 | 14,900 | $745 |
| No | 211661135 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TM9E080B12MP12 | 14,900 | $745 |
| No | 211661130 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TM9E080B12MP12 | 14,900 | $745 |
| No | 211661125 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TM9E080C16MP12 | 14,900 | $745 |
| No | 211661120 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TM9E080C16MP12 | 14,900 | $745 |
| No | 211661115 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TM9E080C16MP12 | 14,600 | $730 |
| No | 211661110 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TM9E080C16MP12 | 14,600 | $730 |
| No | 211661105 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TM9E100C16MP12 | 15,000 | $750 |
| No | 211661100 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TM9E100C16MP12 | 15,000 | $750 |
| No | 211661095 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TM9E100C16MP12 | 14,700 | $735 |
| No | 211661090 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TM9E100C16MP12 | 14,700 | $735 |
| No | 211661085 | LUXAIRE | HMH72B241 | XAUB30CXXN1+TXV | TM9V040A10MP12 | 15,400 | $770 |
| No | 211661080 | LUXAIRE | HMH72B241 | XAFB30CBAN1 | TM9V040A10MP12 | 15,400 | $770 |
| No | 211661075 | LUXAIRE | HMH72B241 | XAFB30CXXN1+TXV | TM9V040A10MP12 | 15,400 | $770 |
| No | 211661070 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | TM9V040A10MP12 | 15,100 | $755 |
| No | 211661065 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | TM9V040A10MP12 | 15,100 | $755 |
| No | 211661063 | LUXAIRE | HMH72B241 | XAUB30CXXN1+TXV | LP9C060B12MP13 | 15,100 | $755 |
| No | 211661061 | LUXAIRE | HMH72B241 | XAFB30CBAN1 | LP9C060B12MP13 | 15,100 | $755 |
| No | 211661056 | LUXAIRE | HMH72B241 | XAUB30CXXN1+TXV | TP9C060B12MP13 | 15,100 | $755 |
| No | 211661051 | LUXAIRE | HMH72B241 | XAFB30CBAN1 | TP9C060B12MP13 | 15,100 | $755 |
| No | 211661046 | LUXAIRE | HMH72B241 | XAUB30CXXN1+TXV | TM9V060B12MP12 | 15,100 | $755 |
| No | 211661041 | LUXAIRE | HMH72B241 | XAFB30CBAN1 | TM9V060B12MP12 | 15,100 | $755 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211661039 | LUXAIRE | HMH72B241 | XAFB30CXXN1+TXV | LP9C060B12MP13 | 15,100 | $755 |
| No | 211661034 | LUXAIRE | HMH72B241 | XAFB30CXXN1+TXV | TP9C060B12MP13 | 15,100 | $755 |
| No | 211661029 | LUXAIRE | HMH72B241 | XAFB30CXXN1+TXV | TM9V060B12MP12 | 15,100 | $755 |
| No | 211661027 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | LP9C060B12MP13 | 15,100 | $755 |
| No | 211661022 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TP9C060B12MP13 | 15,100 | $755 |
| No | 211661017 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TM9V060B12MP12 | 15,100 | $755 |
| No | 211661015 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | LP9C060B12MP13 | 15,100 | $755 |
| No | 211661010 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TP9C060B12MP13 | 15,100 | $755 |
| No | 211661005 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TM9V060B12MP12 | 15,100 | $755 |
| No | 211661003 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | LP9C060B12MP13 | 15,100 | $755 |
| No | 211660998 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | TP9C060B12MP13 | 15,100 | $755 |
| No | 211660993 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | TM9V060B12MP12 | 15,100 | $755 |
| No | 211660991 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | LP9C060B12MP13 | 15,100 | $755 |
| No | 211660986 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | TP9C060B12MP13 | 15,100 | $755 |
| No | 211660981 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | TM9V060B12MP12 | 15,100 | $755 |
| No | 211660979 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | LP9C060B12MP13 | 15,000 | $750 |
| No | 211660974 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TP9C060B12MP13 | 15,000 | $750 |
| No | 211660969 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TM9V060B12MP12 | 15,000 | $750 |
| No | 211660967 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | LP9C060B12MP13 | 15,000 | $750 |
| No | 211660962 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TP9C060B12MP13 | 15,000 | $750 |
| No | 211660957 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TM9V060B12MP12 | 15,000 | $750 |
| No | 211660955 | LUXAIRE | HMH72B241 | XAUB30CXXN1+TXV | LP9C080B12MP13 | 15,300 | $765 |
| No | 211660953 | LUXAIRE | HMH72B241 | XAFB30CBAN1 | LP9C080B12MP13 | 15,300 | $765 |
| No | 211660948 | LUXAIRE | HMH72B241 | XAUB30CXXN1+TXV | TP9C080B12MP13 | 15,300 | $765 |
| No | 211660943 | LUXAIRE | HMH72B241 | XAFB30CBAN1 | TP9C080B12MP13 | 15,300 | $765 |
| No | 211660938 | LUXAIRE | HMH72B241 | XAUB30CXXN1+TXV | TM9V080B12MP12 | 15,300 | $765 |
| No | 211660933 | LUXAIRE | HMH72B241 | XAFB30CBAN1 | TM9V080B12MP12 | 15,300 | $765 |
| No | 211660931 | LUXAIRE | HMH72B241 | XAFB30CXXN1+TXV | LP9C080B12MP13 | 15,300 | $765 |
| No | 211660926 | LUXAIRE | HMH72B241 | XAFB30CXXN1+TXV | TP9C080B12MP13 | 15,300 | $765 |
| No | 211660921 | LUXAIRE | HMH72B241 | XAFB30CXXN1+TXV | TM9V080B12MP12 | 15,300 | $765 |
| No | 211660919 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | LP9C080B12MP13 | 15,300 | $765 |
| No | 211660914 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TP9C080B12MP13 | 15,300 | $765 |
| No | 211660909 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TM9V080B12MP12 | 15,300 | $765 |
| No | 211660907 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | LP9C080B12MP13 | 15,300 | $765 |
| No | 211660902 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TP9C080B12MP13 | 15,300 | $765 |
| No | 211660897 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TM9V080B12MP12 | 15,300 | $765 |
| No | 211660895 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | LP9C080B12MP13 | 14,800 | $740 |
| No | 211660890 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | TP9C080B12MP13 | 14,800 | $740 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660885 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | TM9V080B12MP12 | 14,800 | $740 |
| No | 211660883 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | LP9C080B12MP13 | 14,800 | $740 |
| No | 211660878 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | TP9C080B12MP13 | 14,800 | $740 |
| No | 211660873 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | TM9V080B12MP12 | 14,800 | $740 |
| No | 211660871 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | LP9C080B12MP13 | 15,000 | $750 |
| No | 211660866 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TP9C080B12MP13 | 15,000 | $750 |
| No | 211660861 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TM9V080B12MP12 | 15,000 | $750 |
| No | 211660859 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | LP9C080B12MP13 | 15,000 | $750 |
| No | 211660854 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 211660849 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 211660819 | LUXAIRE | HMH72B241 | XAUB30CXXN1+TXV | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211660814 | LUXAIRE | HMH72B241 | XAFB30CBAN1 | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211660809 | LUXAIRE | HMH72B241 | XAFB30CXXN1+TXV | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211660804 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211660799 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211660794 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | TM9Y060B12MP11 | 15,100 | $755 |
| No | 211660789 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | TM9Y060B12MP11 | 15,100 | $755 |
| No | 211660784 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TM9Y060B12MP11 | 14,800 | $740 |
| No | 211660779 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TM9Y060B12MP11 | 14,800 | $740 |
| No | 211660774 | LUXAIRE | HMH72B241 | XAUB30CXXN1+TXV | TM9Y080B12MP11 | 15,100 | $755 |
| No | 211660769 | LUXAIRE | HMH72B241 | XAFB30CBAN1 | TM9Y080B12MP11 | 15,100 | $755 |
| No | 211660764 | LUXAIRE | HMH72B241 | XAFB30CXXN1+TXV | TM9Y080B12MP11 | 15,100 | $755 |
| No | 211660759 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TM9Y080B12MP11 | 15,100 | $755 |
| No | 211660754 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TM9Y080B12MP11 | 15,100 | $755 |
| No | 211660749 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | TM9Y080B12MP11 | 14,900 | $745 |
| No | 211660744 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | TM9Y080B12MP11 | 14,900 | $745 |
| No | 211660739 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TM9Y080B12MP11 | 14,900 | $745 |
| No | 211660734 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TM9Y080B12MP11 | 14,900 | $745 |
| No | 211660729 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TM9Y080C16MP11 | 15,200 | $760 |
| No | 211660724 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TM9Y080C16MP11 | 15,200 | $760 |
| No | 211660719 | LUXAIRE | HMH72B241 | JHETB24CBAS2N1 | | 15,000 | $750 |
| No | 211660714 | LUXAIRE | HMH72B241 | JHVTB24CBAC2N1 | | 15,000 | $750 |
| No | 211660709 | LUXAIRE | HMH72B241 | XAUB30CXXN1+JMET12BS2N1+TXV | | 15,100 | $755 |
| No | 211660704 | LUXAIRE | HMH72B241 | XAFB30CBAN1+JMET12BS2N1 | | 15,100 | $755 |
| No | 211660699 | LUXAIRE | HMH72B241 | XAFB30CXXN1+JMET12BS2N1+TXV | | 15,100 | $755 |
| No | 211660694 | LUXAIRE | HMH72B241 | XAHB30CBAN1+JMET12BS2N1 | | 14,800 | $740 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660689 | LUXAIRE | HMH72B241 | XAHB30CXXN1+JMET12BS2N1+TXV | | 14,800 | $740 |
| No | 211660684 | LUXAIRE | HMH72B241 | XAUB30CXXN1+JMVT12BC2N1+TXV | | 14,900 | $745 |
| No | 211660679 | LUXAIRE | HMH72B241 | XAFB30CBAN1+JMVT12BC2N1 | | 14,900 | $745 |
| No | 211660674 | LUXAIRE | HMH72B241 | XAFB30CXXN1+JMVT12BC2N1+TXV | | 14,900 | $745 |
| No | 211660669 | LUXAIRE | HMH72B241 | XAHB30CBAN1+JMVT12BC2N1 | | 14,900 | $745 |
| No | 211660664 | LUXAIRE | HMH72B241 | XAHB30CXXN1+JMVT12BC2N1+TXV | | 14,900 | $745 |
| No | 211660659 | LUXAIRE | HMH72B241 | XAUB30CXXN1+TXV | TL8E060A12UH11 | 15,000 | $750 |
| No | 211660654 | LUXAIRE | HMH72B241 | XAFB30CBAN1 | TL8E060A12UH11 | 15,000 | $750 |
| No | 211660649 | LUXAIRE | HMH72B241 | XAFB30CXXN1+TXV | TL8E060A12UH11 | 15,000 | $750 |
| No | 211660644 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | TL8E060A12UH11 | 14,700 | $735 |
| No | 211660639 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | TL8E060A12UH11 | 14,700 | $735 |
| No | 211660634 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TL8E080C16UH11 | 15,600 | $780 |
| No | 211660629 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TL8E080C16UH11 | 15,600 | $780 |
| No | 211660624 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TM9Y080C16MP11 | 14,900 | $745 |
| No | 211660619 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TM9Y080C16MP11 | 14,900 | $745 |
| No | 211660614 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TM9Y100C16MP11 | 15,200 | $760 |
| No | 211660609 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TM9Y100C16MP11 | 15,200 | $760 |
| No | 211660604 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TM9Y100C16MP11 | 14,800 | $740 |
| No | 211660599 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TM9Y100C16MP11 | 14,800 | $740 |
| No | 211660594 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TL8E080C16UH11 | 15,300 | $765 |
| No | 211660589 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TL8E080C16UH11 | 15,300 | $765 |
| No | 211660584 | LUXAIRE | HMH72B241 | XAUB30CXXN1+TXV | TL9E060B12UH11 | 15,100 | $755 |
| No | 211660579 | LUXAIRE | HMH72B241 | XAFB30CBAN1 | TL9E060B12UH11 | 15,100 | $755 |
| No | 211660574 | LUXAIRE | HMH72B241 | XAFB30CXXN1+TXV | TL9E060B12UH11 | 15,100 | $755 |
| No | 211660569 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TL9E060B12UH11 | 15,100 | $755 |
| No | 211660564 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TL9E060B12UH11 | 15,100 | $755 |
| No | 211660559 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | TL9E060B12UH11 | 14,800 | $740 |
| No | 211660554 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | TL9E060B12UH11 | 14,800 | $740 |
| No | 211660549 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TL9E060B12UH11 | 14,800 | $740 |
| No | 211660544 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TL9E060B12UH11 | 14,800 | $740 |
| No | 211660539 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TL9E080C16UH11 | 15,700 | $785 |
| No | 211660534 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TL9E080C16UH11 | 15,700 | $785 |
| No | 211660529 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TL9E080C16UH11 | 15,300 | $765 |
| No | 211660524 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TL9E080C16UH11 | 15,300 | $765 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660519 | LUXAIRE | HMH72B241 | XAUB30CXXN1+TXV | TMLE040A12MP11 | 15,000 | $750 |
| No | 211660514 | LUXAIRE | HMH72B241 | XAFB30CBAN1 | TMLE040A12MP11 | 15,000 | $750 |
| No | 211660509 | LUXAIRE | HMH72B241 | XAUB30CXXN1+TXV | TM8E040A12MP11 | 15,000 | $750 |
| No | 211660504 | LUXAIRE | HMH72B241 | XAFB30CBAN1 | TM8E040A12MP11 | 15,000 | $750 |
| No | 211660499 | LUXAIRE | HMH72B241 | XAFB30CXXN1+TXV | TMLE040A12MP11 | 15,000 | $750 |
| No | 211660494 | LUXAIRE | HMH72B241 | XAFB30CXXN1+TXV | TM8E040A12MP11 | 15,000 | $750 |
| No | 211660489 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | TMLE040A12MP11 | 14,700 | $735 |
| No | 211660484 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | TM8E040A12MP11 | 14,700 | $735 |
| No | 211660479 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | TMLE040A12MP11 | 14,700 | $735 |
| No | 211660474 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | TM8E040A12MP11 | 14,700 | $735 |
| No | 211660469 | LUXAIRE | HMH72B241 | XAUB30CXXN1+TXV | TMLE060A12MP11 | 15,000 | $750 |
| No | 211660464 | LUXAIRE | HMH72B241 | XAFB30CBAN1 | TMLE060A12MP11 | 15,000 | $750 |
| No | 211660459 | LUXAIRE | HMH72B241 | XAUB30CXXN1+TXV | TM8E060A12MP11 | 15,000 | $750 |
| No | 211660454 | LUXAIRE | HMH72B241 | XAFB30CBAN1 | TM8E060A12MP11 | 15,000 | $750 |
| No | 211660449 | LUXAIRE | HMH72B241 | XAFB30CXXN1+TXV | TMLE060A12MP11 | 15,000 | $750 |
| No | 211660444 | LUXAIRE | HMH72B241 | XAFB30CXXN1+TXV | TM8E060A12MP11 | 15,000 | $750 |
| No | 211660439 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | TMLE060A12MP11 | 14,700 | $735 |
| No | 211660434 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | TM8E060A12MP11 | 14,700 | $735 |
| No | 211660429 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | TMLE060A12MP11 | 14,700 | $735 |
| No | 211660424 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | TM8E060A12MP11 | 14,700 | $735 |
| No | 211660419 | LUXAIRE | HMH72B241 | XAUB30CXXN1+TXV | TMLE080B12MP11 | 15,100 | $755 |
| No | 211660414 | LUXAIRE | HMH72B241 | XAFB30CBAN1 | TMLE080B12MP11 | 15,100 | $755 |
| No | 211660409 | LUXAIRE | HMH72B241 | XAUB30CXXN1+TXV | TM8E080B12MP11 | 15,100 | $755 |
| No | 211660404 | LUXAIRE | HMH72B241 | XAFB30CBAN1 | TM8E080B12MP11 | 15,100 | $755 |
| No | 211660399 | LUXAIRE | HMH72B241 | XAFB30CXXN1+TXV | TMLE080B12MP11 | 15,100 | $755 |
| No | 211660394 | LUXAIRE | HMH72B241 | XAFB30CXXN1+TXV | TM8E080B12MP11 | 15,100 | $755 |
| No | 211660389 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TMLE080B12MP11 | 15,100 | $755 |
| No | 211660384 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TM8E080B12MP11 | 15,100 | $755 |
| No | 211660379 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TMLE080B12MP11 | 15,100 | $755 |
| No | 211660374 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TM8E080B12MP11 | 15,100 | $755 |
| No | 211660369 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | TMLE080B12MP11 | 14,800 | $740 |
| No | 211660364 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | TM8E080B12MP11 | 14,800 | $740 |
| No | 211660359 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | TMLE080B12MP11 | 14,800 | $740 |
| No | 211660354 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | TM8E080B12MP11 | 14,800 | $740 |
| No | 211660349 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TMLE080B12MP11 | 14,800 | $740 |
| No | 211660344 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TM8E080B12MP11 | 14,800 | $740 |
| No | 211660339 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TMLE080B12MP11 | 14,800 | $740 |
| No | 211660334 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TM8E080B12MP11 | 14,800 | $740 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660329 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TMLE080C16MP11 | 15,500 | $775 |
| No | 211660324 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TM8E080C16MP11 | 15,500 | $775 |
| No | 211660319 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TMLE080C16MP11 | 15,500 | $775 |
| No | 211660314 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TM8E080C16MP11 | 15,500 | $775 |
| No | 211660309 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TMLE080C16MP11 | 14,700 | $735 |
| No | 211660304 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TM8E080C16MP11 | 14,700 | $735 |
| No | 211660299 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TMLE080C16MP11 | 14,700 | $735 |
| No | 211660294 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TM8E080C16MP11 | 14,700 | $735 |
| No | 211660289 | LUXAIRE | HMH72B241 | XAUB30CXXN1+TXV | TMLE100B12MP11 | 15,100 | $755 |
| No | 211660284 | LUXAIRE | HMH72B241 | XAFB30CBAN1 | TMLE100B12MP11 | 15,100 | $755 |
| No | 211660279 | LUXAIRE | HMH72B241 | XAUB30CXXN1+TXV | TM8E100B12MP11 | 15,100 | $755 |
| No | 211660274 | LUXAIRE | HMH72B241 | XAFB30CBAN1 | TM8E100B12MP11 | 15,100 | $755 |
| No | 211660269 | LUXAIRE | HMH72B241 | XAFB30CXXN1+TXV | TMLE100B12MP11 | 15,100 | $755 |
| No | 211660264 | LUXAIRE | HMH72B241 | XAFB30CXXN1+TXV | TM8E100B12MP11 | 15,100 | $755 |
| No | 211660259 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TMLE100B12MP11 | 14,800 | $740 |
| No | 211660254 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660249 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TMLE100B12MP11 | 14,800 | $740 |
| No | 211660244 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660239 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | TMLE100B12MP11 | 14,800 | $740 |
| No | 211660234 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660229 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | TMLE100B12MP11 | 14,800 | $740 |
| No | 211660224 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660219 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TMLE100B12MP11 | 14,800 | $740 |
| No | 211660214 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660209 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TMLE100B12MP11 | 14,800 | $740 |
| No | 211660204 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TM8E100B12MP11 | 14,800 | $740 |
| No | 211660199 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TMLE100C16MP11 | 15,000 | $750 |
| No | 211660194 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TM8E100C16MP11 | 15,000 | $750 |
| No | 211660189 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TMLE100C16MP11 | 15,000 | $750 |
| No | 211660184 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TM8E100C16MP11 | 15,000 | $750 |
| No | 211660179 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TMLE100C16MP11 | 14,700 | $735 |
| No | 211660174 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TM8E100C16MP11 | 14,700 | $735 |
| No | 211660169 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TMLE100C16MP11 | 14,700 | $735 |
| No | 211660164 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TM8E100C16MP11 | 14,700 | $735 |
| No | 211660159 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TMLE120C16MP11 | 15,000 | $750 |
| No | 211660154 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TM8E120C16MP11 | 15,000 | $750 |
| No | 211660149 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TMLE120C16MP11 | 15,000 | $750 |
| No | 211660144 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TM8E120C16MP11 | 15,000 | $750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211660139 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TMLE120C16MP11 | 15,300 | $765 |
| No | 211660134 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TM8E120C16MP11 | 15,300 | $765 |
| No | 211660129 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TMLE120C16MP11 | 15,300 | $765 |
| No | 211660124 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TM8E120C16MP11 | 15,300 | $765 |
| No | 211660122 | LUXAIRE | HMH72B241 | XAUB30CXXN1+TXV | LPLC080B12MP13 | 15,100 | $755 |
| No | 211660121 | LUXAIRE | HMH72B241 | XAFB30CBAN1 | LPLC080B12MP13 | 15,100 | $755 |
| No | 211660117 | LUXAIRE | HMH72B241 | XAUB30CXXN1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 211660112 | LUXAIRE | HMH72B241 | XAFB30CBAN1 | TPLC080B12MP13 | 15,100 | $755 |
| No | 211660107 | LUXAIRE | HMH72B241 | XAUB30CXXN1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 211660102 | LUXAIRE | HMH72B241 | XAFB30CBAN1 | TM8V080B12MP12 | 15,100 | $755 |
| No | 211660100 | LUXAIRE | HMH72B241 | XAFB30CXXN1+TXV | LPLC080B12MP13 | 15,100 | $755 |
| No | 211660096 | LUXAIRE | HMH72B241 | XAFB30CXXN1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 211660091 | LUXAIRE | HMH72B241 | XAFB30CXXN1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 211660089 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | LPLC080B12MP13 | 15,100 | $755 |
| No | 211660085 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TPLC080B12MP13 | 15,100 | $755 |
| No | 211660080 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TM8V080B12MP12 | 15,100 | $755 |
| No | 211660078 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | LPLC080B12MP13 | 15,100 | $755 |
| No | 211660074 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 211660069 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 211660067 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | LPLC080B12MP13 | 14,900 | $745 |
| No | 211660063 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | TPLC080B12MP13 | 14,900 | $745 |
| No | 211660058 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | TM8V080B12MP12 | 14,900 | $745 |
| No | 211660056 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | LPLC080B12MP13 | 14,900 | $745 |
| No | 211660052 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | TPLC080B12MP13 | 14,900 | $745 |
| No | 211660047 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | TM8V080B12MP12 | 14,900 | $745 |
| No | 211660045 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | LPLC080B12MP13 | 14,800 | $740 |
| No | 211660041 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TPLC080B12MP13 | 14,800 | $740 |
| No | 211660036 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TM8V080B12MP12 | 14,800 | $740 |
| No | 211660034 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | LPLC080B12MP13 | 14,800 | $740 |
| No | 211660030 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TPLC080B12MP13 | 14,800 | $740 |
| No | 211660025 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TM8V080B12MP12 | 14,800 | $740 |
| No | 211660020 | LUXAIRE | HMH72B241 | XAUB30CXXN1+TXV | TM8Y060A12MP11 | 15,300 | $765 |
| No | 211660015 | LUXAIRE | HMH72B241 | XAFB30CBAN1 | TM8Y060A12MP11 | 15,300 | $765 |
| No | 211660010 | LUXAIRE | HMH72B241 | XAFB30CXXN1+TXV | TM8Y060A12MP11 | 15,300 | $765 |
| No | 211660005 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | TM8Y060A12MP11 | 15,000 | $750 |
| No | 211660000 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | TM8Y060A12MP11 | 15,000 | $750 |
| No | 211659995 | LUXAIRE | HMH72B241 | XAUB30CXXN1+TXV | TM8Y080B12MP11 | 15,300 | $765 |
| No | 211659990 | LUXAIRE | HMH72B241 | XAFB30CBAN1 | TM8Y080B12MP11 | 15,300 | $765 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211659985 | LUXAIRE | HMH72B241 | XAFB30CXXN1+TXV | TM8Y080B12MP11 | 15,300 | $765 |
| No | 211659980 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TM8Y080B12MP11 | 15,300 | $765 |
| No | 211659975 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TM8Y080B12MP11 | 15,300 | $765 |
| No | 211659970 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | TM8Y080B12MP11 | 15,000 | $750 |
| No | 211659965 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | TM8Y080B12MP11 | 15,000 | $750 |
| No | 211659960 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TM8Y080B12MP11 | 15,100 | $755 |
| No | 211659955 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TM8Y080B12MP11 | 15,100 | $755 |
| No | 211659945 | LUXAIRE | HMH72B241 | XAFC30CBAN1 | TM8Y100C16MP11 | 15,100 | $755 |
| No | 211659935 | LUXAIRE | HMH72B241 | XAFC30CXXN1+TXV | TM8Y100C16MP11 | 15,100 | $755 |
| No | 211659930 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TM8Y080C16MP11 | 14,800 | $740 |
| No | 211659925 | LUXAIRE | HMH72B241 | XAHC30CBAN1 | TM8Y100C16MP11 | 14,800 | $740 |
| No | 211659920 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TM8Y080C16MP11 | 14,800 | $740 |
| No | 211659915 | LUXAIRE | HMH72B241 | XAHC30CXXN1+TXV | TM8Y100C16MP11 | 14,800 | $740 |
| No | 211659910 | LUXAIRE | HMH72B241 | XAUB30CXXN1+TXV | TM9E026A08MP12 | 15,400 | $770 |
| No | 211659905 | LUXAIRE | HMH72B241 | XAFB30CBAN1 | TM9E026A08MP12 | 15,400 | $770 |
| No | 211659900 | LUXAIRE | HMH72B241 | XAFB30CXXN1+TXV | TM9E026A08MP12 | 15,400 | $770 |
| No | 211659895 | LUXAIRE | HMH72B241 | XAHB30CBAN1 | TM9E026A08MP12 | 15,100 | $755 |
| No | 211659890 | LUXAIRE | HMH72B241 | XAHB30CXXN1+TXV | TM9E026A08MP12 | 15,100 | $755 |
| No | 207417130 | LUXAIRE | HMH72B361 | XAFA30DXXN1+TXV | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 207417126 | LUXAIRE | HMH72B361 | XAFA30DXXN1+TXV | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 207417033 | LUXAIRE | HMH72B361 | XAFA30DXXN1+TXV | TM8Y060A12MP11 | 25,000 | $1,250 |
| No | 207416615 | LUXAIRE | HMH72B361 | XAFA30DXXN1+TXV | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 207416591 | LUXAIRE | HMH72B361 | XAFA30DXXN1+TXV | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 207416587 | LUXAIRE | HMH72B361 | XAFA30DXXN1+TXV | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211719799 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | LPLC060A12MP13 | 26,000 | $1,300 |
| No | 211719797 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | LPLC060A12MP13 | 26,000 | $1,300 |
| No | 211719789 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | LPLC060A12MP13 | 25,600 | $1,280 |
| No | 211719786 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | LPLC060A12MP13 | 25,600 | $1,280 |
| No | 211719784 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | LPLC060A12MP13 | 25,600 | $1,280 |
| No | 211719724 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | LPLC060A12MP13 | 25,200 | $1,260 |
| No | 211719722 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | LPLC060A12MP13 | 25,200 | $1,260 |
| No | 211719720 | LUXAIRE | HMH72B341 | XAFA30DXXN1+TXV | LPLC060A12MP13 | 25,800 | $1,290 |
| No | 211719718 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | LPLC060A12MP13 | 25,600 | $1,280 |
| No | 211398891 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211398876 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211398864 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211398850 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211398835 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TMLE080C16MP11 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211398820 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TM8E080C16MP11 | 24,800 | $1,240 |
| No | 211398805 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TMLE080C16MP11 | 24,800 | $1,240 |
| No | 211398796 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TM8E080C16MP11 | 24,800 | $1,240 |
| No | 211398785 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TMLE080C16MP11 | 24,800 | $1,240 |
| No | 211398770 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TM8E080C16MP11 | 24,800 | $1,240 |
| No | 211398757 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TMLE080C16MP11 | 24,800 | $1,240 |
| No | 211398742 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TM8E080C16MP11 | 24,800 | $1,240 |
| No | 211398728 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211398713 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211398698 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211398683 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211398668 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211398653 | LUXAIRE | HMH72B341 | 0 | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211398638 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 211398631 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 211398616 | LUXAIRE | HMH72B341 | 0 | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 211398601 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 211398586 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211398571 | LUXAIRE | HMH72B341 | 0 | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211398557 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211398541 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211398526 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211398511 | LUXAIRE | HMH72B341 | 0 | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211398497 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211398482 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211398475 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211398463 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211398448 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211398433 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211398418 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211398403 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211398389 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211398374 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211398359 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211398347 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211398332 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TMLE120C16MP11 | 25,400 | $1,270 |
| No | 211398324 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TMLE120C16MP11 | 25,400 | $1,270 |
| No | 211398309 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TM8E120C16MP11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211398294 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TM8E120C16MP11 | 25,400 | $1,270 |
| No | 211398282 | LUXAIRE | HMH72B341 | 0 | TMLE120C16MP11 | 25,400 | $1,270 |
| No | 211398267 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TM8E120C16MP11 | 25,400 | $1,270 |
| No | 211398252 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TMLE120C16MP11 | 25,200 | $1,260 |
| No | 211398237 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TM8E120C16MP11 | 25,200 | $1,260 |
| No | 211398222 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TMLE120C16MP11 | 25,200 | $1,260 |
| No | 211398207 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TM8E120C16MP11 | 25,200 | $1,260 |
| No | 211398191 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211398176 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211398161 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211398153 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211398138 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211398123 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211398108 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211398093 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211398089 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | LPLC080B12MP13 | 25,800 | $1,290 |
| No | 211398088 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | LPLC080B12MP13 | 25,800 | $1,290 |
| No | 211398083 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TPLC080B12MP13 | 25,800 | $1,290 |
| No | 211398068 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TPLC080B12MP13 | 25,800 | $1,290 |
| No | 211398053 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TM8V080B12MP12 | 25,800 | $1,290 |
| No | 211398038 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TM8V080B12MP12 | 25,800 | $1,290 |
| No | 211398032 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | LPLC080B12MP13 | 25,800 | $1,290 |
| No | 211398020 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TPLC080B12MP13 | 25,800 | $1,290 |
| No | 211398005 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TM8V080B12MP12 | 25,800 | $1,290 |
| No | 211397999 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | LPLC080B12MP13 | 25,200 | $1,260 |
| No | 211397987 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TPLC080B12MP13 | 25,200 | $1,260 |
| No | 211397972 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TM8V080B12MP12 | 25,200 | $1,260 |
| No | 211397966 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | LPLC080B12MP13 | 25,200 | $1,260 |
| No | 211397954 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TPLC080B12MP13 | 25,200 | $1,260 |
| No | 211397939 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TM8V080B12MP12 | 25,200 | $1,260 |
| No | 211397933 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | LPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397927 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | LPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397921 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | LPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397915 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | LPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397900 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397885 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397874 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397859 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TPLC080C16MP13 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211397844 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211397829 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211397792 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211397777 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211397771 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | LPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397765 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | LPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397750 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397735 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397720 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211397696 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211397691 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | LPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397685 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | LPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397669 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397654 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397639 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211397609 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211397603 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | LPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397597 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | LPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397582 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TPLC100C16MP13 | 25,800 | $1,290 |
| No | 211397567 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TPLC080C16MP13 | 25,800 | $1,290 |
| No | 211397552 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211397522 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211397516 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | LPLC100C16MP13 | 25,400 | $1,270 |
| No | 211397510 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | LPLC080C16MP13 | 25,400 | $1,270 |
| No | 211397495 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TPLC100C16MP13 | 25,400 | $1,270 |
| No | 211397480 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TPLC080C16MP13 | 25,400 | $1,270 |
| No | 211397469 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TMLV100C16MP12 | 25,400 | $1,270 |
| No | 211397442 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TM8V100C16MP12 | 25,400 | $1,270 |
| No | 211397438 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | LPLC100C16MP13 | 25,400 | $1,270 |
| No | 211397436 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | LPLC080C16MP13 | 25,400 | $1,270 |
| No | 211397421 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TPLC100C16MP13 | 25,400 | $1,270 |
| No | 211397406 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TPLC080C16MP13 | 25,400 | $1,270 |
| No | 211397391 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TMLV100C16MP12 | 25,400 | $1,270 |
| No | 211397368 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TM8V100C16MP12 | 25,400 | $1,270 |
| No | 211397362 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | LPLC100C16MP13 | 25,200 | $1,260 |
| No | 211397356 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | LPLC080C16MP13 | 25,200 | $1,260 |
| No | 211397341 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TPLC100C16MP13 | 25,200 | $1,260 |
| No | 211397325 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TPLC080C16MP13 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211397311 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TMLV100C16MP12 | 25,200 | $1,260 |
| No | 211397299 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TM8V080C16MP12 | 25,200 | $1,260 |
| No | 211397284 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TM8V100C16MP12 | 25,200 | $1,260 |
| No | 211397278 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | LPLC100C16MP13 | 25,200 | $1,260 |
| No | 211397274 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | LPLC080C16MP13 | 25,200 | $1,260 |
| No | 211397261 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TPLC100C16MP13 | 25,200 | $1,260 |
| No | 211397246 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TPLC080C16MP13 | 25,200 | $1,260 |
| No | 211397231 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TMLV100C16MP12 | 25,200 | $1,260 |
| No | 211397216 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TM8V080C16MP12 | 25,200 | $1,260 |
| No | 211397201 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TM8V100C16MP12 | 25,200 | $1,260 |
| No | 211397195 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | LPLC120C20MP13 | 25,200 | $1,260 |
| No | 211397188 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | LPLC100C20MP13 | 25,200 | $1,260 |
| No | 211397176 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TPLC120C20MP13 | 25,200 | $1,260 |
| No | 211397166 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TPLC100C20MP13 | 25,200 | $1,260 |
| No | 211397155 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TMLV120C20MP12 | 25,200 | $1,260 |
| No | 211397140 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TM8V100C20MP12 | 25,200 | $1,260 |
| No | 211397129 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TM8V120C20MP12 | 25,200 | $1,260 |
| No | 211397122 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | LPLC120C20MP13 | 25,200 | $1,260 |
| No | 211397116 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | LPLC100C20MP13 | 25,200 | $1,260 |
| No | 211397104 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TPLC120C20MP13 | 25,200 | $1,260 |
| No | 211397089 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TPLC100C20MP13 | 25,200 | $1,260 |
| No | 211397074 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TMLV120C20MP12 | 25,200 | $1,260 |
| No | 211397059 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TM8V100C20MP12 | 25,200 | $1,260 |
| No | 211397044 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TM8V120C20MP12 | 25,200 | $1,260 |
| No | 211397029 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211397014 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211396999 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211396984 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211396975 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211396960 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TM8Y080C16MP11 | 25,800 | $1,290 |
| No | 211396945 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TM8Y080C16MP11 | 25,800 | $1,290 |
| No | 211396930 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211396920 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211396906 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TM8Y080C16MP11 | 25,800 | $1,290 |
| No | 211396891 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211396876 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TM8Y080C16MP11 | 25,800 | $1,290 |
| No | 211396861 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211396846 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TM8Y080C16MP11 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211396831 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211396816 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TM8Y080C16MP11 | 25,400 | $1,270 |
| No | 211396802 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211396793 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TM8Y080C16MP11 | 25,400 | $1,270 |
| No | 211396778 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211396763 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TM8Y080C16MP11 | 25,400 | $1,270 |
| No | 211396748 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211396733 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TM8Y080C16MP11 | 25,400 | $1,270 |
| No | 211396719 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211396703 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TM8Y100C20MP11 | 25,600 | $1,280 |
| No | 211396688 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TM8Y100C20MP11 | 25,600 | $1,280 |
| No | 211396677 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TM8Y120C20MP11 | 25,600 | $1,280 |
| No | 211396662 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TM8Y120C20MP11 | 25,600 | $1,280 |
| No | 211396647 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TM8Y100C20MP11 | 25,600 | $1,280 |
| No | 211396631 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TM8Y120C20MP11 | 25,600 | $1,280 |
| No | 211396623 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TM8Y100C20MP11 | 25,600 | $1,280 |
| No | 211396607 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TM8Y120C20MP11 | 25,600 | $1,280 |
| No | 211396595 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TM8Y100C20MP11 | 25,600 | $1,280 |
| No | 211396580 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TM8Y120C20MP11 | 25,600 | $1,280 |
| No | 211396564 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TM8Y100C20MP11 | 25,200 | $1,260 |
| No | 211396551 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211396534 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TM8Y100C20MP11 | 25,200 | $1,260 |
| No | 211396515 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211396491 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TM8Y100C20MP11 | 25,200 | $1,260 |
| No | 211396469 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211396444 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TM8Y100C20MP11 | 25,200 | $1,260 |
| No | 211396423 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211396400 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211396376 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211396354 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211396334 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211396308 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211396287 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TM9E080B12MP12 | 25,600 | $1,280 |
| No | 211396266 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TM9E080B12MP12 | 25,600 | $1,280 |
| No | 211396243 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TM9E080B12MP12 | 25,600 | $1,280 |
| No | 211396220 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211396201 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211396181 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TM9E080C16MP12 | 26,000 | $1,300 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211396165 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TM9E080C16MP12 | 26,000 | $1,300 |
| No | 211396143 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TM9E080C16MP12 | 26,000 | $1,300 |
| No | 211396130 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TM9E080C16MP12 | 26,000 | $1,300 |
| No | 211396113 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TM9E080C16MP12 | 26,000 | $1,300 |
| No | 211396098 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211396084 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211396068 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211396053 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211396038 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211396026 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211396012 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211395996 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211395982 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211395968 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211395954 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211395941 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211395927 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211395921 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | LP9C060B12MP13 | 25,600 | $1,280 |
| No | 211395916 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | LP9C060B12MP13 | 25,600 | $1,280 |
| No | 211395903 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211395893 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211395880 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211395861 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211395853 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | LP9C060B12MP13 | 25,600 | $1,280 |
| No | 211395830 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211395807 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211395799 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | LP9C060B12MP13 | 25,200 | $1,260 |
| No | 211395785 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TP9C060B12MP13 | 25,200 | $1,260 |
| No | 211395765 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TM9V060B12MP12 | 25,200 | $1,260 |
| No | 211395757 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | LP9C060B12MP13 | 25,200 | $1,260 |
| No | 211395734 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TP9C060B12MP13 | 25,200 | $1,260 |
| No | 211395717 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TM9V060B12MP12 | 25,200 | $1,260 |
| No | 211395706 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | LP9C080B12MP13 | 25,600 | $1,280 |
| No | 211395696 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | LP9C080B12MP13 | 25,600 | $1,280 |
| No | 211395675 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TP9C080B12MP13 | 25,600 | $1,280 |
| No | 211395651 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TP9C080B12MP13 | 25,600 | $1,280 |
| No | 211395631 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TM9V080B12MP12 | 25,600 | $1,280 |
| No | 211395607 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TM9V080B12MP12 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211395600 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | LP9C080B12MP13 | 25,600 | $1,280 |
| No | 211395576 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TP9C080B12MP13 | 25,600 | $1,280 |
| No | 211395554 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TM9V080B12MP12 | 25,600 | $1,280 |
| No | 211395544 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | LP9C080B12MP13 | 25,200 | $1,260 |
| No | 211395519 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TP9C080B12MP13 | 25,200 | $1,260 |
| No | 211395500 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TM9V080B12MP12 | 25,200 | $1,260 |
| No | 211395492 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | LP9C080B12MP13 | 25,200 | $1,260 |
| No | 211395472 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TP9C080B12MP13 | 25,200 | $1,260 |
| No | 211395450 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TM9V080B12MP12 | 25,200 | $1,260 |
| No | 211395440 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | LP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395430 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | LP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395404 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395385 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395365 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211395347 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211395338 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | LP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395316 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395290 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211395280 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | LP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395255 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395234 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211395224 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | LP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395201 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211395175 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211395165 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | LP9C080C16MP13 | 24,800 | $1,240 |
| No | 211395143 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TP9C080C16MP13 | 24,800 | $1,240 |
| No | 211395118 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TM9V080C16MP12 | 24,800 | $1,240 |
| No | 211395109 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | LP9C080C16MP13 | 24,800 | $1,240 |
| No | 211395088 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TP9C080C16MP13 | 24,800 | $1,240 |
| No | 211395070 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TM9V080C16MP12 | 24,800 | $1,240 |
| No | 211395060 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | LP9C080C16MP13 | 25,000 | $1,250 |
| No | 211395044 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TP9C080C16MP13 | 25,000 | $1,250 |
| No | 211395032 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TM9V080C16MP12 | 25,000 | $1,250 |
| No | 211395027 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | LP9C080C16MP13 | 25,000 | $1,250 |
| No | 211395013 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TP9C080C16MP13 | 25,000 | $1,250 |
| No | 211394999 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TM9V080C16MP12 | 25,000 | $1,250 |
| No | 211394994 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | LP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394988 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | LP9C100C16MP13 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211394973 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394959 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394944 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211394931 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211394926 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | LP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394912 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394898 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211394893 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | LP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394878 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394865 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211394859 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | LP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394844 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211394830 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211394824 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | LP9C100C16MP13 | 24,800 | $1,240 |
| No | 211394809 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211394794 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TM9V100C16MP12 | 24,800 | $1,240 |
| No | 211394788 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | LP9C100C16MP13 | 24,800 | $1,240 |
| No | 211394773 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211394759 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TM9V100C16MP12 | 24,800 | $1,240 |
| No | 211394753 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | LP9C100C16MP13 | 24,800 | $1,240 |
| No | 211394738 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211394724 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TM9V100C16MP12 | 24,800 | $1,240 |
| No | 211394718 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | LP9C100C16MP13 | 24,800 | $1,240 |
| No | 211394706 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211394692 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TM9V100C16MP12 | 24,800 | $1,240 |
| No | 211394686 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | LP9C100C20MP13 | 25,800 | $1,290 |
| No | 211394680 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | LP9C100C20MP13 | 25,800 | $1,290 |
| No | 211394665 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TP9C100C20MP13 | 25,800 | $1,290 |
| No | 211394653 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TP9C100C20MP13 | 25,800 | $1,290 |
| No | 211394638 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TM9V100C20MP12 | 25,800 | $1,290 |
| No | 211394627 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TM9V100C20MP12 | 25,800 | $1,290 |
| No | 211394621 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | LP9C100C20MP13 | 25,800 | $1,290 |
| No | 211394606 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TP9C100C20MP13 | 25,800 | $1,290 |
| No | 211394591 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TM9V100C20MP12 | 25,800 | $1,290 |
| No | 211394585 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | LP9C100C20MP13 | 25,600 | $1,280 |
| No | 211394570 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TP9C100C20MP13 | 25,600 | $1,280 |
| No | 211394556 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TM9V100C20MP12 | 25,600 | $1,280 |
| No | 211394551 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | LP9C100C20MP13 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211394537 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TP9C100C20MP13 | 25,600 | $1,280 |
| No | 211394526 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TM9V100C20MP12 | 25,600 | $1,280 |
| No | 211394520 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | LP9C100C20MP13 | 25,000 | $1,250 |
| No | 211394506 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TP9C100C20MP13 | 25,000 | $1,250 |
| No | 211394495 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TM9V100C20MP12 | 25,000 | $1,250 |
| No | 211394489 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | LP9C100C20MP13 | 25,000 | $1,250 |
| No | 211394475 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TP9C100C20MP13 | 25,000 | $1,250 |
| No | 211394461 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TM9V100C20MP12 | 25,000 | $1,250 |
| No | 211394455 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | LP9C100C20MP13 | 25,200 | $1,260 |
| No | 211394440 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TP9C100C20MP13 | 25,200 | $1,260 |
| No | 211394425 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TM9V100C20MP12 | 25,200 | $1,260 |
| No | 211394419 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | LP9C100C20MP13 | 25,200 | $1,260 |
| No | 211394407 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TP9C100C20MP13 | 25,200 | $1,260 |
| No | 211394395 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TM9V100C20MP12 | 25,200 | $1,260 |
| No | 211394388 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | LP9C120D20MP13 | 25,400 | $1,270 |
| No | 211394373 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TP9C120D20MP13 | 25,400 | $1,270 |
| No | 211394362 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TM9V120D20MP12 | 25,400 | $1,270 |
| No | 211394356 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | LP9C120D20MP13 | 25,400 | $1,270 |
| No | 211394342 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TP9C120D20MP13 | 25,400 | $1,270 |
| No | 211394328 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TM9V120D20MP12 | 25,400 | $1,270 |
| No | 211394322 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | LP9C120D20MP13 | 24,800 | $1,240 |
| No | 211394309 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TP9C120D20MP13 | 24,800 | $1,240 |
| No | 211394296 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TM9V120D20MP12 | 24,800 | $1,240 |
| No | 211394291 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | LP9C120D20MP13 | 24,800 | $1,240 |
| No | 211394276 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TP9C120D20MP13 | 24,800 | $1,240 |
| No | 211394261 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TM9V120D20MP12 | 24,800 | $1,240 |
| No | 211394246 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TM9Y060B12MP11 | 25,800 | $1,290 |
| No | 211394234 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TM9Y060B12MP11 | 25,800 | $1,290 |
| No | 211394219 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TM9Y060B12MP11 | 25,800 | $1,290 |
| No | 211394206 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TM9Y060B12MP11 | 25,400 | $1,270 |
| No | 211394191 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TM9Y060B12MP11 | 25,400 | $1,270 |
| No | 211394176 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211394161 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211394150 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211394135 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TM9Y080B12MP11 | 25,400 | $1,270 |
| No | 211394122 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TM9Y080B12MP11 | 25,400 | $1,270 |
| No | 211394107 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TM9Y080C16MP11 | 25,800 | $1,290 |
| No | 211394094 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TM9Y080C16MP11 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211394079 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TM9Y080C16MP11 | 25,800 | $1,290 |
| No | 211394064 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TM9Y080C16MP11 | 25,400 | $1,270 |
| No | 211394049 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TM9Y080C16MP11 | 25,400 | $1,270 |
| No | 211394034 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TM9Y080C16MP11 | 25,200 | $1,260 |
| No | 211394019 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TM9Y080C16MP11 | 25,200 | $1,260 |
| No | 211394004 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TM9Y080C16MP11 | 25,000 | $1,250 |
| No | 211393989 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TM9Y080C16MP11 | 25,000 | $1,250 |
| No | 211393974 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TM9Y100C16MP11 | 25,800 | $1,290 |
| No | 211393959 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TM9Y100C16MP11 | 25,800 | $1,290 |
| No | 211393944 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TM9Y100C16MP11 | 25,800 | $1,290 |
| No | 211393929 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TM9Y100C16MP11 | 25,400 | $1,270 |
| No | 211393914 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TM9Y100C16MP11 | 25,400 | $1,270 |
| No | 211393899 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TM9Y100C16MP11 | 25,200 | $1,260 |
| No | 211393884 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TM9Y100C16MP11 | 25,200 | $1,260 |
| No | 211393869 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TM9Y100C16MP11 | 25,200 | $1,260 |
| No | 211393854 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TM9Y100C16MP11 | 25,200 | $1,260 |
| No | 211393839 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TM9Y120D20MP11 | 25,400 | $1,270 |
| No | 211393824 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TM9Y120D20MP11 | 25,400 | $1,270 |
| No | 211393809 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TM9Y120D20MP11 | 25,000 | $1,250 |
| No | 211393794 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TM9Y120D20MP11 | 25,000 | $1,250 |
| No | 211393779 | LUXAIRE | HMH72B341 | XAFA30DXXN1+TXV | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 211393764 | LUXAIRE | HMH72B341 | XAFA30DXXN1+TXV | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 211393750 | LUXAIRE | HMH72B341 | XAFA30DXXN1+TXV | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211393735 | LUXAIRE | HMH72B341 | XAFA30DXXN1+TXV | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 211393720 | LUXAIRE | HMH72B341 | XAFA30DXXN1+TXV | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 211393705 | LUXAIRE | HMH72B341 | XAFA30DXXN1+TXV | TPLC060A12MP13 | 25,800 | $1,290 |
| No | 211393690 | LUXAIRE | HMH72B341 | XAFA30DXXN1+TXV | TMLV060A12MP12 | 25,800 | $1,290 |
| No | 211393675 | LUXAIRE | HMH72B341 | XAFA30DXXN1+TXV | TM8V060A12MP12 | 25,800 | $1,290 |
| No | 211393660 | LUXAIRE | HMH72B341 | XAFA30DXXN1+TXV | TM8Y060A12MP11 | 25,200 | $1,260 |
| No | 211393632 | LUXAIRE | HMH72B341 | JHETB36DBCS2N1 | | 25,400 | $1,270 |
| No | 211393619 | LUXAIRE | HMH72B341 | JHVTB36DBCC2N1 | | 25,200 | $1,260 |
| No | 211393605 | LUXAIRE | HMH72B341 | JHVTC36DBCC2N1 | | 25,400 | $1,270 |
| No | 211393591 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | TL8E060A12UH11 | 26,200 | $1,310 |
| No | 211393577 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | TL8E060A12UH11 | 26,200 | $1,310 |
| No | 211393562 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 211393547 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 211393532 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 211393518 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | TL8E060A12UH11 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211393502 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | TL8E060A12UH11 | 25,000 | $1,250 |
| No | 211393488 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | TL8E060A12UH11 | 25,000 | $1,250 |
| No | 211393473 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TL8E080C16UH11 | 26,600 | $1,330 |
| No | 211393458 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211393443 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211393429 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TL8E080C16UH11 | 26,000 | $1,300 |
| No | 211393414 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TL8E080C16UH11 | 25,800 | $1,290 |
| No | 211393399 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TL8E080C16UH11 | 25,800 | $1,290 |
| No | 211393384 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TL8E100C20UH11 | 26,400 | $1,320 |
| No | 211393369 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211393355 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211393346 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TL8E100C20UH11 | 25,800 | $1,290 |
| No | 211393322 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TL8E100C20UH11 | 25,600 | $1,280 |
| No | 211393307 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TL8E100C20UH11 | 25,600 | $1,280 |
| No | 211393293 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | TL9E060B12UH11 | 26,400 | $1,320 |
| No | 211393278 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | TL9E060B12UH11 | 26,400 | $1,320 |
| No | 211393263 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | TL9E060B12UH11 | 25,000 | $1,250 |
| No | 211393250 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | TL9E060B12UH11 | 25,000 | $1,250 |
| No | 211393240 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | TL9E060B12UH11 | 25,000 | $1,250 |
| No | 211393225 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TL9E060B12UH11 | 26,400 | $1,320 |
| No | 211393210 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TL9E060B12UH11 | 25,600 | $1,280 |
| No | 211393195 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TL9E060B12UH11 | 25,600 | $1,280 |
| No | 211393180 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | TL9E060B12UH11 | 25,200 | $1,260 |
| No | 211393169 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TL9E060B12UH11 | 26,000 | $1,300 |
| No | 211393154 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TL9E060B12UH11 | 24,400 | $1,220 |
| No | 211393139 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TL9E060B12UH11 | 24,400 | $1,220 |
| No | 211393124 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TL9E080C16UH11 | 26,200 | $1,310 |
| No | 211393109 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TL9E080C16UH11 | 25,800 | $1,290 |
| No | 211393094 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TL9E080C16UH11 | 25,800 | $1,290 |
| No | 211393079 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TL9E080C16UH11 | 26,400 | $1,320 |
| No | 211393072 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TL9E080C16UH11 | 25,400 | $1,270 |
| No | 211393060 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TL9E080C16UH11 | 25,400 | $1,270 |
| No | 211393045 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TL9E100C20UH11 | 26,400 | $1,320 |
| No | 211393031 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TL9E100C20UH11 | 26,200 | $1,310 |
| No | 211393015 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TL9E100C20UH11 | 26,200 | $1,310 |
| No | 211393000 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TL9E100C20UH11 | 26,000 | $1,300 |
| No | 211392985 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TL9E100C20UH11 | 25,600 | $1,280 |
| No | 211392970 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TL9E100C20UH11 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211392956 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | TMLE040A12MP11 | 26,200 | $1,310 |
| No | 211392941 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | TM8E040A12MP11 | 26,200 | $1,310 |
| No | 211392926 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | TMLE040A12MP11 | 26,200 | $1,310 |
| No | 211392911 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | TM8E040A12MP11 | 26,200 | $1,310 |
| No | 211392896 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 211392885 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 211392875 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211392860 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211392845 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 211392830 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211392815 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | TMLE040A12MP11 | 25,600 | $1,280 |
| No | 211392800 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | TM8E040A12MP11 | 25,600 | $1,280 |
| No | 211392785 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | TMLE040A12MP11 | 24,800 | $1,240 |
| No | 211392770 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | TM8E040A12MP11 | 24,800 | $1,240 |
| No | 211392755 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | TMLE040A12MP11 | 24,800 | $1,240 |
| No | 211392740 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | TM8E040A12MP11 | 24,800 | $1,240 |
| No | 211392725 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | TMLE060A12MP11 | 26,200 | $1,310 |
| No | 211392710 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | TM8E060A12MP11 | 26,200 | $1,310 |
| No | 211392698 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | TMLE060A12MP11 | 26,200 | $1,310 |
| No | 211392693 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | TM8E060A12MP11 | 26,200 | $1,310 |
| No | 211392678 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 211392663 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 211392649 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 211392634 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 211392619 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 211392604 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 211392589 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | TMLE060A12MP11 | 25,800 | $1,290 |
| No | 211392574 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | TM8E060A12MP11 | 25,800 | $1,290 |
| No | 211392559 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | TMLE060A12MP11 | 25,000 | $1,250 |
| No | 211392548 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | TM8E060A12MP11 | 25,000 | $1,250 |
| No | 211392533 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | TMLE060A12MP11 | 25,000 | $1,250 |
| No | 211392520 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | TM8E060A12MP11 | 25,000 | $1,250 |
| No | 211392507 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | TMLE080B12MP11 | 26,800 | $1,340 |
| No | 211392492 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | TM8E080B12MP11 | 26,800 | $1,340 |
| No | 211392477 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | TMLE080B12MP11 | 26,800 | $1,340 |
| No | 211392462 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | TM8E080B12MP11 | 26,800 | $1,340 |
| No | 211392451 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | TMLE080B12MP11 | 25,800 | $1,290 |
| No | 211392436 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | TMLE080B12MP11 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211392421 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211392411 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211392396 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | TMLE080B12MP11 | 25,800 | $1,290 |
| No | 211392382 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211392367 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TMLE080B12MP11 | 26,800 | $1,340 |
| No | 211392352 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TM8E080B12MP11 | 26,800 | $1,340 |
| No | 211392337 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TMLE080B12MP11 | 25,800 | $1,290 |
| No | 211392322 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211392311 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TMLE080B12MP11 | 25,800 | $1,290 |
| No | 211392295 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211392281 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | TMLE080B12MP11 | 26,200 | $1,310 |
| No | 211392274 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | TM8E080B12MP11 | 26,200 | $1,310 |
| No | 211392262 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | TMLE080B12MP11 | 25,000 | $1,250 |
| No | 211392247 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | TM8E080B12MP11 | 25,000 | $1,250 |
| No | 211392232 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | TMLE080B12MP11 | 25,000 | $1,250 |
| No | 211392217 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | TM8E080B12MP11 | 25,000 | $1,250 |
| No | 211392202 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TMLE080B12MP11 | 26,400 | $1,320 |
| No | 211392194 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TM8E080B12MP11 | 26,400 | $1,320 |
| No | 211392181 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TMLE080B12MP11 | 25,000 | $1,250 |
| No | 211392165 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TM8E080B12MP11 | 25,000 | $1,250 |
| No | 211392150 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TMLE080B12MP11 | 25,000 | $1,250 |
| No | 211392135 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TM8E080B12MP11 | 25,000 | $1,250 |
| No | 211392120 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TMLE080C16MP11 | 26,000 | $1,300 |
| No | 211392105 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TM8E080C16MP11 | 26,000 | $1,300 |
| No | 211392090 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211392075 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211392061 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211392056 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211392041 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TMLE080C16MP11 | 25,600 | $1,280 |
| No | 211392026 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TM8E080C16MP11 | 25,600 | $1,280 |
| No | 211392012 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TMLE080C16MP11 | 24,600 | $1,230 |
| No | 211391996 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TM8E080C16MP11 | 24,600 | $1,230 |
| No | 211391981 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TMLE080C16MP11 | 24,600 | $1,230 |
| No | 211391966 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TM8E080C16MP11 | 24,600 | $1,230 |
| No | 211391951 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | TMLE100B12MP11 | 26,200 | $1,310 |
| No | 211391936 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | TM8E100B12MP11 | 26,200 | $1,310 |
| No | 211391921 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | TMLE100B12MP11 | 26,200 | $1,310 |
| No | 211391906 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | TM8E100B12MP11 | 26,200 | $1,310 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211391891 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211391876 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211391861 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211391847 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211391832 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211391818 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211391803 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TMLE100B12MP11 | 26,200 | $1,310 |
| No | 211391788 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TM8E100B12MP11 | 26,200 | $1,310 |
| No | 211391777 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211391762 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211391747 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211391737 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211391722 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | TMLE100B12MP11 | 25,800 | $1,290 |
| No | 211391707 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | TM8E100B12MP11 | 25,800 | $1,290 |
| No | 211391699 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 211391690 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 211391675 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 211391660 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 211391645 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TMLE100B12MP11 | 25,600 | $1,280 |
| No | 211391631 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TM8E100B12MP11 | 25,600 | $1,280 |
| No | 211391623 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TMLE100B12MP11 | 24,800 | $1,240 |
| No | 211391608 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TM8E100B12MP11 | 24,800 | $1,240 |
| No | 211391593 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TMLE100B12MP11 | 24,800 | $1,240 |
| No | 211391578 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TM8E100B12MP11 | 24,800 | $1,240 |
| No | 211391563 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TMLE100C16MP11 | 26,000 | $1,300 |
| No | 211391548 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TM8E100C16MP11 | 26,000 | $1,300 |
| No | 211391533 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TMLE100C16MP11 | 25,200 | $1,260 |
| No | 211391518 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TM8E100C16MP11 | 25,200 | $1,260 |
| No | 211391503 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TMLE100C16MP11 | 25,200 | $1,260 |
| No | 211391488 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TM8E100C16MP11 | 25,200 | $1,260 |
| No | 211391473 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TMLE100C16MP11 | 25,600 | $1,280 |
| No | 211391458 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TM8E100C16MP11 | 25,600 | $1,280 |
| No | 211391444 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211391428 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211391413 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211391398 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211391383 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TMLE120C16MP11 | 26,200 | $1,310 |
| No | 211391368 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TM8E120C16MP11 | 26,200 | $1,310 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211391353 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TMLE120C16MP11 | 25,200 | $1,260 |
| No | 211391338 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TM8E120C16MP11 | 25,200 | $1,260 |
| No | 211391323 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TMLE120C16MP11 | 25,200 | $1,260 |
| No | 211391308 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TM8E120C16MP11 | 25,200 | $1,260 |
| No | 211391294 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TMLE120C16MP11 | 25,600 | $1,280 |
| No | 211391279 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TM8E120C16MP11 | 25,600 | $1,280 |
| No | 211391264 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211391249 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211391235 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211391220 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211391205 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | TPLC060A12MP13 | 26,000 | $1,300 |
| No | 211391190 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | TMLV060A12MP12 | 26,000 | $1,300 |
| No | 211391175 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | TM8V060A12MP12 | 26,000 | $1,300 |
| No | 211391160 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | TPLC060A12MP13 | 26,000 | $1,300 |
| No | 211391146 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | TMLV060A12MP12 | 26,000 | $1,300 |
| No | 211391131 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | TM8V060A12MP12 | 26,000 | $1,300 |
| No | 211391116 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | TPLC060A12MP13 | 25,600 | $1,280 |
| No | 211391101 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | TPLC060A12MP13 | 25,600 | $1,280 |
| No | 211391086 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | TMLV060A12MP12 | 25,600 | $1,280 |
| No | 211391071 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | TMLV060A12MP12 | 25,600 | $1,280 |
| No | 211391056 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | TM8V060A12MP12 | 25,600 | $1,280 |
| No | 211391041 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | TM8V060A12MP12 | 25,600 | $1,280 |
| No | 211391026 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | TPLC060A12MP13 | 25,600 | $1,280 |
| No | 211391011 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | TMLV060A12MP12 | 25,600 | $1,280 |
| No | 211390996 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | TM8V060A12MP12 | 25,600 | $1,280 |
| No | 211390981 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | TPLC060A12MP13 | 25,600 | $1,280 |
| No | 211390966 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | TMLV060A12MP12 | 25,600 | $1,280 |
| No | 211390951 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | TM8V060A12MP12 | 25,600 | $1,280 |
| No | 211390937 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | TPLC060A12MP13 | 25,200 | $1,260 |
| No | 211390922 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | TMLV060A12MP12 | 25,200 | $1,260 |
| No | 211390907 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | TM8V060A12MP12 | 25,200 | $1,260 |
| No | 211390892 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | TPLC060A12MP13 | 25,200 | $1,260 |
| No | 211390878 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | TMLV060A12MP12 | 25,200 | $1,260 |
| No | 211390863 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | TM8V060A12MP12 | 25,200 | $1,260 |
| No | 211390857 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | LPLC080B12MP13 | 26,400 | $1,320 |
| No | 211390845 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | TPLC080B12MP13 | 26,400 | $1,320 |
| No | 211390830 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | TM8V080B12MP12 | 26,400 | $1,320 |
| No | 211390824 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | LPLC080B12MP13 | 26,400 | $1,320 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211390812 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | TPLC080B12MP13 | 26,400 | $1,320 |
| No | 211390797 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | TM8V080B12MP12 | 26,400 | $1,320 |
| No | 211390792 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | LPLC080B12MP13 | 25,400 | $1,270 |
| No | 211390789 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | LPLC080B12MP13 | 25,400 | $1,270 |
| No | 211390777 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | TPLC080B12MP13 | 25,400 | $1,270 |
| No | 211390762 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | TPLC080B12MP13 | 25,400 | $1,270 |
| No | 211390747 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | TM8V080B12MP12 | 25,400 | $1,270 |
| No | 211390732 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | TM8V080B12MP12 | 25,400 | $1,270 |
| No | 211390726 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | LPLC080B12MP13 | 25,400 | $1,270 |
| No | 211390714 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | TPLC080B12MP13 | 25,400 | $1,270 |
| No | 211390699 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | TM8V080B12MP12 | 25,400 | $1,270 |
| No | 211390693 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | LPLC080B12MP13 | 26,400 | $1,320 |
| No | 211390681 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TPLC080B12MP13 | 26,400 | $1,320 |
| No | 211390666 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TM8V080B12MP12 | 26,400 | $1,320 |
| No | 211390660 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | LPLC080B12MP13 | 25,600 | $1,280 |
| No | 211390648 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TPLC080B12MP13 | 25,600 | $1,280 |
| No | 211390634 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TM8V080B12MP12 | 25,600 | $1,280 |
| No | 211390628 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | LPLC080B12MP13 | 25,600 | $1,280 |
| No | 211390616 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TPLC080B12MP13 | 25,600 | $1,280 |
| No | 211390601 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TM8V080B12MP12 | 25,600 | $1,280 |
| No | 211390595 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | LPLC080B12MP13 | 25,600 | $1,280 |
| No | 211390583 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | TPLC080B12MP13 | 25,600 | $1,280 |
| No | 211390568 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | TM8V080B12MP12 | 25,600 | $1,280 |
| No | 211390562 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | LPLC080B12MP13 | 25,000 | $1,250 |
| No | 211390550 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | TPLC080B12MP13 | 25,000 | $1,250 |
| No | 211390535 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | TM8V080B12MP12 | 25,000 | $1,250 |
| No | 211390529 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | LPLC080B12MP13 | 25,000 | $1,250 |
| No | 211390518 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | TPLC080B12MP13 | 25,000 | $1,250 |
| No | 211390502 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | TM8V080B12MP12 | 25,000 | $1,250 |
| No | 211390496 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | LPLC080B12MP13 | 26,000 | $1,300 |
| No | 211390485 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TPLC080B12MP13 | 26,000 | $1,300 |
| No | 211390470 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TM8V080B12MP12 | 26,000 | $1,300 |
| No | 211390464 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | LPLC080B12MP13 | 24,800 | $1,240 |
| No | 211390452 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TPLC080B12MP13 | 24,800 | $1,240 |
| No | 211390437 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TM8V080B12MP12 | 24,800 | $1,240 |
| No | 211390431 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | LPLC080B12MP13 | 24,800 | $1,240 |
| No | 211390419 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TPLC080B12MP13 | 24,800 | $1,240 |
| No | 211390405 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TM8V080B12MP12 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211390399 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | LPLC100C16MP13 | 26,400 | $1,320 |
| No | 211390393 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | LPLC080C16MP13 | 26,400 | $1,320 |
| No | 211390378 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TPLC100C16MP13 | 26,400 | $1,320 |
| No | 211390363 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TPLC080C16MP13 | 26,400 | $1,320 |
| No | 211390348 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TMLV100C16MP12 | 26,400 | $1,320 |
| No | 211390334 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TM8V080C16MP12 | 26,400 | $1,320 |
| No | 211390321 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TM8V100C16MP12 | 26,400 | $1,320 |
| No | 211390315 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | LPLC100C16MP13 | 25,400 | $1,270 |
| No | 211390310 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | LPLC080C16MP13 | 25,400 | $1,270 |
| No | 211390296 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TPLC100C16MP13 | 25,400 | $1,270 |
| No | 211390282 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TPLC080C16MP13 | 25,400 | $1,270 |
| No | 211390268 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TMLV100C16MP12 | 25,400 | $1,270 |
| No | 211390254 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TM8V080C16MP12 | 25,400 | $1,270 |
| No | 211390239 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TM8V100C16MP12 | 25,400 | $1,270 |
| No | 211390234 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | LPLC100C16MP13 | 25,400 | $1,270 |
| No | 211390228 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | LPLC080C16MP13 | 25,400 | $1,270 |
| No | 211390213 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TPLC100C16MP13 | 25,400 | $1,270 |
| No | 211390199 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TPLC080C16MP13 | 25,400 | $1,270 |
| No | 211390186 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TMLV100C16MP12 | 25,400 | $1,270 |
| No | 211390172 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TM8V080C16MP12 | 25,400 | $1,270 |
| No | 211390158 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TM8V100C16MP12 | 25,400 | $1,270 |
| No | 211390153 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | LPLC100C16MP13 | 25,600 | $1,280 |
| No | 211390147 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | LPLC080C16MP13 | 25,600 | $1,280 |
| No | 211390134 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TPLC100C16MP13 | 25,600 | $1,280 |
| No | 211390120 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TPLC080C16MP13 | 25,600 | $1,280 |
| No | 211390106 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TMLV100C16MP12 | 25,600 | $1,280 |
| No | 211390076 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TM8V100C16MP12 | 25,600 | $1,280 |
| No | 211390070 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | LPLC100C16MP13 | 25,600 | $1,280 |
| No | 211390064 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | LPLC080C16MP13 | 25,600 | $1,280 |
| No | 211390051 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TPLC100C16MP13 | 25,600 | $1,280 |
| No | 211390037 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TPLC080C16MP13 | 25,600 | $1,280 |
| No | 211390022 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TMLV100C16MP12 | 25,600 | $1,280 |
| No | 211389995 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TM8V100C16MP12 | 25,600 | $1,280 |
| No | 211389989 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | LPLC100C16MP13 | 25,600 | $1,280 |
| No | 211389984 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | LPLC080C16MP13 | 25,600 | $1,280 |
| No | 211389970 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TPLC100C16MP13 | 25,600 | $1,280 |
| No | 211389955 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TPLC080C16MP13 | 25,600 | $1,280 |
| No | 211389941 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TMLV100C16MP12 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211389911 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TM8V100C16MP12 | 25,600 | $1,280 |
| No | 211389896 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | TM8Y060A12MP11 | 25,800 | $1,290 |
| No | 211389887 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | TM8Y060A12MP11 | 25,800 | $1,290 |
| No | 211389876 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | TM8Y060A12MP11 | 25,200 | $1,260 |
| No | 211389861 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | TM8Y060A12MP11 | 25,200 | $1,260 |
| No | 211389848 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | TM8Y060A12MP11 | 25,200 | $1,260 |
| No | 211389833 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | TM8Y060A12MP11 | 25,400 | $1,270 |
| No | 211389819 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | TM8Y060A12MP11 | 24,600 | $1,230 |
| No | 211389804 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | TM8Y060A12MP11 | 24,600 | $1,230 |
| No | 211389789 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | TM8Y080B12MP11 | 26,000 | $1,300 |
| No | 211389774 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | TM8Y080B12MP11 | 26,000 | $1,300 |
| No | 211389759 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211389744 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211389729 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211389722 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TM8Y080B12MP11 | 26,000 | $1,300 |
| No | 211389707 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211389693 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211389678 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211389663 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211389648 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211389634 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211389619 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211389604 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211389574 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TM8Y100C16MP11 | 26,400 | $1,320 |
| No | 211389556 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211389526 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211389512 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TM8Y080C16MP11 | 26,600 | $1,330 |
| No | 211389497 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TM8Y100C16MP11 | 26,600 | $1,330 |
| No | 211389482 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TM8Y080C16MP11 | 25,600 | $1,280 |
| No | 211389467 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TM8Y100C16MP11 | 25,600 | $1,280 |
| No | 211389452 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TM8Y080C16MP11 | 25,600 | $1,280 |
| No | 211389441 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TM8Y100C16MP11 | 25,600 | $1,280 |
| No | 211389415 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TM8Y120C20MP11 | 27,000 | $1,350 |
| No | 211389388 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211389363 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211389348 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TM8Y100C20MP11 | 26,400 | $1,320 |
| No | 211389333 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TM8Y120C20MP11 | 26,400 | $1,320 |
| No | 211389318 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TM8Y100C20MP11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211389304 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TM8Y120C20MP11 | 25,400 | $1,270 |
| No | 211389289 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TM8Y100C20MP11 | 25,400 | $1,270 |
| No | 211389274 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TM8Y120C20MP11 | 25,400 | $1,270 |
| No | 211389260 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | TM9E040A10MP12 | 25,800 | $1,290 |
| No | 211389246 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | TM9E040A10MP12 | 25,800 | $1,290 |
| No | 211389238 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | TM9E060A10MP12 | 26,200 | $1,310 |
| No | 211389223 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | TM9E060A10MP12 | 26,200 | $1,310 |
| No | 211389208 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | TM9E060A10MP12 | 25,400 | $1,270 |
| No | 211389193 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | TM9E060A10MP12 | 25,400 | $1,270 |
| No | 211389178 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | TM9E060A10MP12 | 25,400 | $1,270 |
| No | 211389172 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | TM9E060A10MP12 | 25,800 | $1,290 |
| No | 211389159 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 211389145 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 211389130 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | TM9E060B12MP12 | 26,400 | $1,320 |
| No | 211389115 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | TM9E060B12MP12 | 26,400 | $1,320 |
| No | 211389100 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211389085 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211389070 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211389056 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TM9E060B12MP12 | 26,400 | $1,320 |
| No | 211389041 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211389026 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211389011 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | TM9E060B12MP12 | 26,000 | $1,300 |
| No | 211388997 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211388982 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211388967 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TM9E060B12MP12 | 26,200 | $1,310 |
| No | 211388956 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211388941 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211388926 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | TM9E080B12MP12 | 26,800 | $1,340 |
| No | 211388911 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | TM9E080B12MP12 | 26,800 | $1,340 |
| No | 211388896 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | TM9E080B12MP12 | 25,400 | $1,270 |
| No | 211388888 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | TM9E080B12MP12 | 25,400 | $1,270 |
| No | 211388874 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | TM9E080B12MP12 | 25,400 | $1,270 |
| No | 211388859 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TM9E080B12MP12 | 26,400 | $1,320 |
| No | 211388844 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TM9E080B12MP12 | 25,800 | $1,290 |
| No | 211388829 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TM9E080B12MP12 | 25,800 | $1,290 |
| No | 211388814 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | TM9E080B12MP12 | 25,800 | $1,290 |
| No | 211388799 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211388791 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | TM9E080B12MP12 | 25,000 | $1,250 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211388777 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TM9E080B12MP12 | 26,200 | $1,310 |
| No | 211388762 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211388747 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211388732 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TM9E080C16MP12 | 26,200 | $1,310 |
| No | 211388717 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TM9E080C16MP12 | 25,200 | $1,260 |
| No | 211388702 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TM9E080C16MP12 | 25,200 | $1,260 |
| No | 211388688 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TM9E080C16MP12 | 26,800 | $1,340 |
| No | 211388673 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211388658 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211388643 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TM9E100C16MP12 | 26,200 | $1,310 |
| No | 211388628 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TM9E100C16MP12 | 25,200 | $1,260 |
| No | 211388613 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TM9E100C16MP12 | 25,200 | $1,260 |
| No | 211388599 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TM9E100C16MP12 | 25,600 | $1,280 |
| No | 211388584 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211388569 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211388558 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TM9E100C20MP12 | 25,000 | $1,250 |
| No | 211388549 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TM9E100C20MP12 | 25,000 | $1,250 |
| No | 211388544 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | TM9V040A10MP12 | 25,800 | $1,290 |
| No | 211388531 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | TM9V040A10MP12 | 25,800 | $1,290 |
| No | 211388516 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | TM9V040A10MP12 | 25,200 | $1,260 |
| No | 211388510 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | TM9V040A10MP12 | 25,200 | $1,260 |
| No | 211388498 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | TM9V040A10MP12 | 25,200 | $1,260 |
| No | 211388484 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | TM9V040A10MP12 | 25,200 | $1,260 |
| No | 211388470 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | TM9V040A10MP12 | 24,800 | $1,240 |
| No | 211388458 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | TM9V040A10MP12 | 24,800 | $1,240 |
| No | 211388454 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | LP9C060B12MP13 | 26,400 | $1,320 |
| No | 211388445 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | TP9C060B12MP13 | 26,400 | $1,320 |
| No | 211388431 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | TM9V060B12MP12 | 26,400 | $1,320 |
| No | 211388426 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | LP9C060B12MP13 | 26,400 | $1,320 |
| No | 211388412 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | TP9C060B12MP13 | 26,400 | $1,320 |
| No | 211388397 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | TM9V060B12MP12 | 26,400 | $1,320 |
| No | 211388392 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | LP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388387 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | LP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388376 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388363 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388348 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388338 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388332 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | LP9C060B12MP13 | 25,600 | $1,280 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211388318 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388303 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388297 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | LP9C060B12MP13 | 26,400 | $1,320 |
| No | 211388283 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TP9C060B12MP13 | 26,400 | $1,320 |
| No | 211388269 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TM9V060B12MP12 | 26,400 | $1,320 |
| No | 211388264 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | LP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388249 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388235 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388230 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | LP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388225 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388217 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388212 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | LP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388198 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211388186 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211388183 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | LP9C060B12MP13 | 25,000 | $1,250 |
| No | 211388169 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 211388154 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 211388148 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | LP9C060B12MP13 | 25,000 | $1,250 |
| No | 211388134 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 211388120 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 211388114 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | LP9C060B12MP13 | 26,000 | $1,300 |
| No | 211388100 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TP9C060B12MP13 | 26,000 | $1,300 |
| No | 211388087 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TM9V060B12MP12 | 26,000 | $1,300 |
| No | 211388082 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | LP9C060B12MP13 | 25,200 | $1,260 |
| No | 211388069 | LUXAIRE | HMH72B341 | 0 | TP9C060B12MP13 | 25,200 | $1,260 |
| No | 211388055 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TM9V060B12MP12 | 25,200 | $1,260 |
| No | 211388049 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | LP9C060B12MP13 | 25,200 | $1,260 |
| No | 211388035 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TP9C060B12MP13 | 25,200 | $1,260 |
| No | 211388028 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TM9V060B12MP12 | 25,200 | $1,260 |
| No | 211388024 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | LP9C080B12MP13 | 26,600 | $1,330 |
| No | 211388014 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | TP9C080B12MP13 | 26,600 | $1,330 |
| No | 211388001 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | TM9V080B12MP12 | 26,600 | $1,330 |
| No | 211387995 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | LP9C080B12MP13 | 26,600 | $1,330 |
| No | 211387981 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | TP9C080B12MP13 | 26,600 | $1,330 |
| No | 211387968 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | TM9V080B12MP12 | 26,600 | $1,330 |
| No | 211387964 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | LP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387962 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | LP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387950 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | TP9C080B12MP13 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211387935 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | TP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387923 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211387909 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211387904 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | LP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387889 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | TP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387874 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211387868 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | LP9C080B12MP13 | 26,600 | $1,330 |
| No | 211387854 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TP9C080B12MP13 | 26,600 | $1,330 |
| No | 211387841 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TM9V080B12MP12 | 26,600 | $1,330 |
| No | 211387838 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | LP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387833 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387823 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211387819 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | LP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387810 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TP9C080B12MP13 | 25,800 | $1,290 |
| No | 211387802 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211387798 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | LP9C080B12MP13 | 26,200 | $1,310 |
| No | 211387790 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | TP9C080B12MP13 | 26,200 | $1,310 |
| No | 211387781 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | TM9V080B12MP12 | 26,200 | $1,310 |
| No | 211387778 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | LP9C080B12MP13 | 25,200 | $1,260 |
| No | 211387770 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | TP9C080B12MP13 | 25,200 | $1,260 |
| No | 211387761 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | TM9V080B12MP12 | 25,200 | $1,260 |
| No | 211387758 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | LP9C080B12MP13 | 25,200 | $1,260 |
| No | 211387750 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | TP9C080B12MP13 | 25,200 | $1,260 |
| No | 211387741 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | TM9V080B12MP12 | 25,200 | $1,260 |
| No | 211387738 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | LP9C080B12MP13 | 26,200 | $1,310 |
| No | 211387729 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TP9C080B12MP13 | 26,200 | $1,310 |
| No | 211387721 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TM9V080B12MP12 | 26,200 | $1,310 |
| No | 211387718 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | LP9C080B12MP13 | 25,000 | $1,250 |
| No | 211387710 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 211387701 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 211387698 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | LP9C080B12MP13 | 25,000 | $1,250 |
| No | 211387690 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 211387681 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 211387678 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | LP9C080C16MP13 | 26,200 | $1,310 |
| No | 211387670 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TP9C080C16MP13 | 26,200 | $1,310 |
| No | 211387661 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TM9V080C16MP12 | 26,200 | $1,310 |
| No | 211387658 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | LP9C080C16MP13 | 25,400 | $1,270 |
| No | 211387649 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TP9C080C16MP13 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211387644 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211387641 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | LP9C080C16MP13 | 25,400 | $1,270 |
| No | 211387632 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211387623 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211387620 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | LP9C080C16MP13 | 25,800 | $1,290 |
| No | 211387612 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TP9C080C16MP13 | 25,800 | $1,290 |
| No | 211387604 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TM9V080C16MP12 | 25,800 | $1,290 |
| No | 211387601 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | LP9C080C16MP13 | 25,000 | $1,250 |
| No | 211387593 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TP9C080C16MP13 | 25,000 | $1,250 |
| No | 211387584 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TM9V080C16MP12 | 25,000 | $1,250 |
| No | 211387581 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | LP9C080C16MP13 | 25,000 | $1,250 |
| No | 211387572 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TP9C080C16MP13 | 25,000 | $1,250 |
| No | 211387564 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TM9V080C16MP12 | 25,000 | $1,250 |
| No | 211387561 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | LP9C100C16MP13 | 26,400 | $1,320 |
| No | 211387553 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TP9C100C16MP13 | 26,400 | $1,320 |
| No | 211387546 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TM9V100C16MP12 | 26,400 | $1,320 |
| No | 211387544 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | LP9C100C16MP13 | 25,400 | $1,270 |
| No | 211387538 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211387529 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211387525 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | LP9C100C16MP13 | 25,400 | $1,270 |
| No | 211387511 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211387498 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211387493 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | LP9C100C16MP13 | 25,800 | $1,290 |
| No | 211387480 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TP9C100C16MP13 | 25,800 | $1,290 |
| No | 211387468 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TM9V100C16MP12 | 25,800 | $1,290 |
| No | 211387463 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | LP9C100C16MP13 | 25,000 | $1,250 |
| No | 211387448 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TP9C100C16MP13 | 25,000 | $1,250 |
| No | 211387437 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TM9V100C16MP12 | 25,000 | $1,250 |
| No | 211387431 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | LP9C100C16MP13 | 25,000 | $1,250 |
| No | 211387417 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TP9C100C16MP13 | 25,000 | $1,250 |
| No | 211387404 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TM9V100C16MP12 | 25,000 | $1,250 |
| No | 211387399 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | LP9C100C20MP13 | 27,000 | $1,350 |
| No | 211387383 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TP9C100C20MP13 | 27,000 | $1,350 |
| No | 211387369 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TM9V100C20MP12 | 27,000 | $1,350 |
| No | 211387364 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | LP9C100C20MP13 | 26,000 | $1,300 |
| No | 211387349 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TP9C100C20MP13 | 26,000 | $1,300 |
| No | 211387333 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TM9V100C20MP12 | 26,000 | $1,300 |
| No | 211387326 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | LP9C100C20MP13 | 26,000 | $1,300 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211387313 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TP9C100C20MP13 | 26,000 | $1,300 |
| No | 211387298 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TM9V100C20MP12 | 26,000 | $1,300 |
| No | 211387294 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | LP9C100C20MP13 | 26,600 | $1,330 |
| No | 211387278 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TP9C100C20MP13 | 26,600 | $1,330 |
| No | 211387265 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TM9V100C20MP12 | 26,600 | $1,330 |
| No | 211387251 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | TM9Y060B12MP11 | 26,600 | $1,330 |
| No | 211387237 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | TM9Y060B12MP11 | 26,600 | $1,330 |
| No | 211387222 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211387208 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211387194 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211387180 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TM9Y060B12MP11 | 26,600 | $1,330 |
| No | 211387167 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211386473 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TL8E080C16UH11 | 25,400 | $1,270 |
| No | 211386461 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211386446 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211386432 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211386419 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211386406 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211386394 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TL8E100C20UH11 | 24,800 | $1,240 |
| No | 211386383 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TL8E100C20UH11 | 24,800 | $1,240 |
| No | 211386370 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TL8E100C20UH11 | 24,800 | $1,240 |
| No | 211386359 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TL8E100C20UH11 | 24,800 | $1,240 |
| No | 211386347 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TL9E060B12UH11 | 25,800 | $1,290 |
| No | 211386334 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TL9E060B12UH11 | 25,800 | $1,290 |
| No | 211386323 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TL9E060B12UH11 | 25,800 | $1,290 |
| No | 211386311 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TL9E060B12UH11 | 25,200 | $1,260 |
| No | 211386296 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TL9E060B12UH11 | 25,200 | $1,260 |
| No | 211386283 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TL9E080C16UH11 | 25,800 | $1,290 |
| No | 211386268 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TL9E080C16UH11 | 25,800 | $1,290 |
| No | 211386254 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TL9E080C16UH11 | 25,800 | $1,290 |
| No | 211386243 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TL9E080C16UH11 | 25,600 | $1,280 |
| No | 211386229 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TL9E080C16UH11 | 25,600 | $1,280 |
| No | 211386216 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TL9E080C16UH11 | 25,200 | $1,260 |
| No | 211386206 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TL9E080C16UH11 | 25,200 | $1,260 |
| No | 211386198 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TL9E080C16UH11 | 25,200 | $1,260 |
| No | 211386181 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TL9E080C16UH11 | 25,200 | $1,260 |
| No | 211386168 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211386154 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TL9E100C20UH11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211386138 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211386121 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211386108 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211386094 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TL9E100C20UH11 | 25,000 | $1,250 |
| No | 211386080 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TL9E100C20UH11 | 25,000 | $1,250 |
| No | 211386065 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TL9E100C20UH11 | 25,000 | $1,250 |
| No | 211386051 | LUXAIRE | HMH72B341 | XAHD48FXXN1+TXV | TL9E100C20UH11 | 25,000 | $1,250 |
| No | 211386038 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TMLE080B12MP11 | 25,600 | $1,280 |
| No | 211386024 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TMLE080B12MP11 | 25,600 | $1,280 |
| No | 211386008 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TM8E080B12MP11 | 25,600 | $1,280 |
| No | 211385994 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TM8E080B12MP11 | 25,600 | $1,280 |
| No | 211385980 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TMLE080B12MP11 | 25,600 | $1,280 |
| No | 211385967 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TM8E080B12MP11 | 25,600 | $1,280 |
| No | 211385954 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TMLE080B12MP11 | 25,400 | $1,270 |
| No | 211385941 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TM8E080B12MP11 | 25,400 | $1,270 |
| No | 211385927 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TMLE080B12MP11 | 25,400 | $1,270 |
| No | 211385915 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TM8E080B12MP11 | 25,400 | $1,270 |
| No | 211385900 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211385884 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211385868 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211385853 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211385840 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211385830 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211387151 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211387138 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | TM9Y060B12MP11 | 26,000 | $1,300 |
| No | 211387124 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | TM9Y060B12MP11 | 25,000 | $1,250 |
| No | 211387110 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | TM9Y060B12MP11 | 25,000 | $1,250 |
| No | 211387097 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TM9Y060B12MP11 | 26,000 | $1,300 |
| No | 211387086 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TM9Y060B12MP11 | 25,200 | $1,260 |
| No | 211387073 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TM9Y060B12MP11 | 25,200 | $1,260 |
| No | 211387060 | LUXAIRE | HMH72B341 | XAUB30CXXN1+TXV | TM9Y080B12MP11 | 26,800 | $1,340 |
| No | 211387047 | LUXAIRE | HMH72B341 | XAFB30CXXN1+TXV | TM9Y080B12MP11 | 26,800 | $1,340 |
| No | 211387032 | LUXAIRE | HMH72B341 | XAUB36DXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211387018 | LUXAIRE | HMH72B341 | XAFB36DBCN1 | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211387004 | LUXAIRE | HMH72B341 | XAFB36DXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211386990 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TM9Y080B12MP11 | 26,800 | $1,340 |
| No | 211386975 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211386960 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211386948 | LUXAIRE | HMH72B341 | XAHB30CXXN1+TXV | TM9Y080B12MP11 | 26,200 | $1,310 |
| No | 211386934 | LUXAIRE | HMH72B341 | XAHB36DBCN1 | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211386918 | LUXAIRE | HMH72B341 | XAHB36DXXN1+TXV | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211386904 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TM9Y080B12MP11 | 26,200 | $1,310 |
| No | 211386890 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TM9Y080B12MP11 | 25,400 | $1,270 |
| No | 211386877 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TM9Y080B12MP11 | 25,400 | $1,270 |
| No | 211386864 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TM9Y080C16MP11 | 26,800 | $1,340 |
| No | 211386851 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TM9Y080C16MP11 | 25,800 | $1,290 |
| No | 211386835 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TM9Y080C16MP11 | 25,800 | $1,290 |
| No | 211386822 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TM9Y080C16MP11 | 26,200 | $1,310 |
| No | 211386808 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TM9Y080C16MP11 | 25,400 | $1,270 |
| No | 211386792 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TM9Y080C16MP11 | 25,400 | $1,270 |
| No | 211386776 | LUXAIRE | HMH72B341 | XAFC30CXXN1+TXV | TM9Y100C16MP11 | 26,000 | $1,300 |
| No | 211386762 | LUXAIRE | HMH72B341 | XAFC36DBCN1 | TM9Y100C16MP11 | 25,800 | $1,290 |
| No | 211386749 | LUXAIRE | HMH72B341 | XAFC36DXXN1+TXV | TM9Y100C16MP11 | 25,800 | $1,290 |
| No | 211386736 | LUXAIRE | HMH72B341 | XAHC30CXXN1+TXV | TM9Y100C16MP11 | 25,600 | $1,280 |
| No | 211386723 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TM9Y100C16MP11 | 25,400 | $1,270 |
| No | 211386711 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TM9Y100C16MP11 | 25,400 | $1,270 |
| No | 211386697 | LUXAIRE | HMH72B341 | XAHC36DBCN1 | TM9Y100C20MP11 | 25,600 | $1,280 |
| No | 211386683 | LUXAIRE | HMH72B341 | XAHC36DXXN1+TXV | TM9Y100C20MP11 | 25,600 | $1,280 |
| No | 211386669 | LUXAIRE | HMH72B341 | JHETC42FBCS2N1 | | 25,200 | $1,260 |
| No | 211386655 | LUXAIRE | HMH72B341 | JHVTC42FBCC2N1 | | 25,000 | $1,250 |
| No | 211386643 | LUXAIRE | HMH72B341 | XAUC48FXXN1+JMET12CS2N1+TXV | | 25,400 | $1,270 |
| No | 211386629 | LUXAIRE | HMH72B341 | XAFC48FBCN1+JMET12CS2N1 | | 25,400 | $1,270 |
| No | 211386618 | LUXAIRE | HMH72B341 | XAFC48FXXN1+JMET12CS2N1+TXV | | 25,400 | $1,270 |
| No | 211386604 | LUXAIRE | HMH72B341 | XAHC48FBCN1+JMET12CS2N1 | | 24,800 | $1,240 |
| No | 211386589 | LUXAIRE | HMH72B341 | XAHC48FXXN1+JMET12CS2N1+TXV | | 24,800 | $1,240 |
| No | 211386579 | LUXAIRE | HMH72B341 | XAUC48FXXN1+TXV | TL8E080C16UH11 | 26,000 | $1,300 |
| No | 211386568 | LUXAIRE | HMH72B341 | XAFC48FBCN1 | TL8E080C16UH11 | 26,000 | $1,300 |
| No | 211386554 | LUXAIRE | HMH72B341 | XAFC48FXXN1+TXV | TL8E080C16UH11 | 26,000 | $1,300 |
| No | 211386543 | LUXAIRE | HMH72B341 | XAFD48FBCN1 | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211386530 | LUXAIRE | HMH72B341 | XAFD48FXXN1+TXV | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211386516 | LUXAIRE | HMH72B341 | XAHC48FBCN1 | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211386501 | LUXAIRE | HMH72B341 | XAHC48FXXN1+TXV | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211386487 | LUXAIRE | HMH72B341 | XAHD48FBCN1 | TL8E080C16UH11 | 25,400 | $1,270 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208502146 | LUXAIRE | HMH72B241 | XAHB36DXXN1+JMET08BS2N1+TXV | | 13,900 | $695 |
| No | 208503261 | LUXAIRE | HMH72B241 | XAUB36DXXN1+JMET08BS2N1+TXV | | 14,200 | $710 |
| No | 208614023 | LUXAIRE | HMH72B241 | XAFB36DBAN1+JMET08BS2N1 | | 14,200 | $710 |
| No | 208503244 | LUXAIRE | HMH72B241 | XAFB36DXXN1+JMET08BS2N1+TXV | | 14,200 | $710 |
| No | 208502624 | LUXAIRE | HMH72B241 | XAUB36DXXN1+JMET12BS2N1+TXV | | 14,200 | $710 |
| No | 208614018 | LUXAIRE | HMH72B241 | XAFB36DBAN1+JMET12BS2N1 | | 14,200 | $710 |
| No | 208502617 | LUXAIRE | HMH72B241 | XAFB36DXXN1+JMET12BS2N1+TXV | | 14,200 | $710 |
| No | 207434652 | LUXAIRE | HMH72B241 | XAFC36DXXN1+MVC12CN21+TXV | | 14,300 | $715 |
| No | 207417442 | LUXAIRE | HMH72B241 | XAFC36DXXN1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 208213835 | LUXAIRE | HMH72B241 | XAHC36DXXN1+TXV | LP9C060B12MP13 | 14,300 | $715 |
| No | 208213833 | LUXAIRE | HMH72B241 | XAHC36DXXN1+TXV | TP9C060B12MP13 | 14,300 | $715 |
| No | 208213824 | LUXAIRE | HMH72B241 | XAHC36DXXN1+TXV | TM9V060B12MP12 | 14,300 | $715 |
| No | 208501674 | LUXAIRE | HMH72B241 | XAHB36DXXN1+JMVT12BC2N1+TXV | | 13,900 | $695 |
| No | 207434648 | LUXAIRE | HMH72B241 | XAUB36DXXN1+ME08BN21+TXV | | 14,100 | $705 |
| No | 207434647 | LUXAIRE | HMH72B241 | XAFB36DXXN1+ME08BN21+TXV | | 14,100 | $705 |
| No | 207417475 | LUXAIRE | HMH72B241 | XAUB36DXXN1+TXV | TL8E060A12UH11 | 14,400 | $720 |
| No | 207417471 | LUXAIRE | HMH72B241 | XAFB36DXXN1+TXV | TL8E060A12UH11 | 14,400 | $720 |
| No | 207416655 | LUXAIRE | HMH72B241 | XAFA30DXXN1+TXV | TM9E060A10MP12 | 14,600 | $730 |
| No | 208213837 | LUXAIRE | HMH72B241 | XAHB36DXXN1+TXV | LP9C080B12MP13 | 14,200 | $710 |
| No | 208213831 | LUXAIRE | HMH72B241 | XAHB36DXXN1+TXV | TP9C080B12MP13 | 14,200 | $710 |
| No | 208213827 | LUXAIRE | HMH72B241 | XAHB36DXXN1+TXV | TM9V080B12MP12 | 14,200 | $710 |
| No | 207434649 | LUXAIRE | HMH72B241 | XAUB36DXXN1+MVC12BN21+TXV | | 14,300 | $715 |
| No | 207434651 | LUXAIRE | HMH72B241 | XAFB36DXXN1+MVC12BN21+TXV | | 14,300 | $715 |
| No | 207417190 | LUXAIRE | HMH72B241 | XAFA30DXXN1+TXV | TMLE040A12MP11 | 14,400 | $720 |
| No | 207417186 | LUXAIRE | HMH72B241 | XAFA30DXXN1+TXV | TM8E040A12MP11 | 14,400 | $720 |
| No | 207417458 | LUXAIRE | HMH72B241 | XAUB36DXXN1+TXV | TM8Y060A12MP11 | 14,200 | $710 |
| No | 207417454 | LUXAIRE | HMH72B241 | XAFB36DXXN1+TXV | TM8Y060A12MP11 | 14,200 | $710 |
| No | 207417440 | LUXAIRE | HMH72B241 | XAUB36DXXN1+TXV | LP9C060B12MP13 | 14,600 | $730 |
| No | 207417436 | LUXAIRE | HMH72B241 | XAUB36DXXN1+TXV | TP9C060B12MP13 | 14,600 | $730 |
| No | 207417432 | LUXAIRE | HMH72B241 | XAUB36DXXN1+TXV | TM9V060B12MP12 | 14,600 | $730 |
| No | 207417430 | LUXAIRE | HMH72B241 | XAFB36DXXN1+TXV | LP9C060B12MP13 | 14,600 | $730 |
| No | 207417426 | LUXAIRE | HMH72B241 | XAFB36DXXN1+TXV | TP9C060B12MP13 | 14,600 | $730 |
| No | 207417422 | LUXAIRE | HMH72B241 | XAFB36DXXN1+TXV | TM9V060B12MP12 | 14,600 | $730 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207416619 | LUXAIRE | HMH72B241 | XAFC36DXXN1+TXV | TM9Y060B12MP11 | 14,500 | $725 |
| No | 208614017 | LUXAIRE | HMH72B241 | JHETB30DBAS2N1 | | 14,600 | $730 |
| No | 208501697 | LUXAIRE | HMH72B241 | JHETB30DXXS2N1+TXV | | 14,600 | $730 |
| No | 208502139 | LUXAIRE | HMH72B241 | XAHB36DXXN1+JMET12BS2N1+TXV | | 13,900 | $695 |
| No | 208400363 | LUXAIRE | HMH72B241 | XAHB36DXXN1+ME08BN21+TXV | | 14,200 | $710 |
| No | 207417198 | LUXAIRE | HMH72B241 | XAUB36DXXN1+TXV | TL9E060B12UH11 | 14,500 | $725 |
| No | 207417194 | LUXAIRE | HMH72B241 | XAFB36DXXN1+TXV | TL9E060B12UH11 | 14,500 | $725 |
| No | 208213839 | LUXAIRE | HMH72B241 | XAHC36DXXN1+TXV | LPLC080B12MP13 | 14,100 | $705 |
| No | 208213841 | LUXAIRE | HMH72B241 | XAHC36DXXN1+TXV | TPLC080B12MP13 | 14,100 | $705 |
| No | 208213829 | LUXAIRE | HMH72B241 | XAHC36DXXN1+TXV | TM8V080B12MP12 | 14,100 | $705 |
| No | 207417162 | LUXAIRE | HMH72B241 | XAUB36DXXN1+TXV | TM9E060A10MP12 | 14,600 | $730 |
| No | 207417158 | LUXAIRE | HMH72B241 | XAFB36DXXN1+TXV | TM9E060A10MP12 | 14,600 | $730 |
| No | 208213836 | LUXAIRE | HMH72B241 | XAHC36DXXN1+TXV | LP9C080B12MP13 | 14,100 | $705 |
| No | 208213830 | LUXAIRE | HMH72B241 | XAHC36DXXN1+TXV | TP9C080B12MP13 | 14,100 | $705 |
| No | 208213826 | LUXAIRE | HMH72B241 | XAHC36DXXN1+TXV | TM9V080B12MP12 | 14,100 | $705 |
| No | 208614019 | LUXAIRE | HMH72B241 | JHETB36DBAS2N1 | | 14,300 | $715 |
| No | 208502153 | LUXAIRE | HMH72B241 | JHETB36DXXS2N1+TXV | | 14,300 | $715 |
| No | 208501689 | LUXAIRE | HMH72B241 | XAUB36DXXN1+JMVT12BC2N1+TXV | | 14,000 | $700 |
| No | 208614016 | LUXAIRE | HMH72B241 | XAFB36DBAN1+JMVT12BC2N1 | | 14,000 | $700 |
| No | 208501682 | LUXAIRE | HMH72B241 | XAFB36DXXN1+JMVT12BC2N1+TXV | | 14,000 | $700 |
| No | 207416857 | LUXAIRE | HMH72B241 | XAFC36DXXN1+TXV | TMLE100B12MP11 | 14,300 | $715 |
| No | 207416853 | LUXAIRE | HMH72B241 | XAFC36DXXN1+TXV | TM8E100B12MP11 | 14,300 | $715 |
| No | 208614020 | LUXAIRE | HMH72B241 | JHETC36DBAS2N1 | | 14,200 | $710 |
| No | 208504358 | LUXAIRE | HMH72B241 | JHETC36DXXS2N1+TXV | | 14,200 | $710 |
| No | 208400361 | LUXAIRE | HMH72B241 | XAHC36DXXN1+MVC12CN21+TXV | | 14,000 | $700 |
| No | 208213814 | LUXAIRE | HMH72B241 | XAHC36DXXN1+TXV | TMLE100B12MP11 | 14,000 | $700 |
| No | 208213816 | LUXAIRE | HMH72B241 | XAHC36DXXN1+TXV | TM8E100B12MP11 | 14,000 | $700 |
| No | 208213843 | LUXAIRE | HMH72B241 | XAHC36DXXN1+TXV | TM8Y080B12MP11 | 14,000 | $700 |
| No | 207417410 | LUXAIRE | HMH72B241 | XAUB36DXXN1+TXV | LP9C080B12MP13 | 14,400 | $720 |
| No | 207417406 | LUXAIRE | HMH72B241 | XAUB36DXXN1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 207417402 | LUXAIRE | HMH72B241 | XAUB36DXXN1+TXV | TM9V080B12MP12 | 14,400 | $720 |
| No | 207417400 | LUXAIRE | HMH72B241 | XAFB36DXXN1+TXV | LP9C080B12MP13 | 14,400 | $720 |
| No | 207417396 | LUXAIRE | HMH72B241 | XAFB36DXXN1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 207417392 | LUXAIRE | HMH72B241 | XAFB36DXXN1+TXV | TM9V080B12MP12 | 14,400 | $720 |
| No | 207434650 | LUXAIRE | HMH72B241 | XAFC36DXXN1+ME12CN21+TXV | | 14,200 | $710 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207416667 | LUXAIRE | HMH72B241 | XAFC36DXXN1+TXV | TL9E060B12UH11 | 14,500 | $725 |
| No | 207417182 | LUXAIRE | HMH72B241 | XAFA30DXXN1+TXV | TM8Y060A12MP11 | 14,700 | $735 |
| No | 207416647 | LUXAIRE | HMH72B241 | XAUB36DXXN1+TXV | TM9V040A10MP12 | 14,800 | $740 |
| No | 207416643 | LUXAIRE | HMH72B241 | XAFB36DXXN1+TXV | TM9V040A10MP12 | 14,800 | $740 |
| No | 207416627 | LUXAIRE | HMH72B241 | XAUB36DXXN1+TXV | TM9Y060B12MP11 | 14,500 | $725 |
| No | 207416623 | LUXAIRE | HMH72B241 | XAFB36DXXN1+TXV | TM9Y060B12MP11 | 14,500 | $725 |
| No | 207416671 | LUXAIRE | HMH72B241 | XAFA30DXXN1+TXV | TL8E060A12UH11 | 14,400 | $720 |
| No | 207416851 | LUXAIRE | HMH72B241 | XAUB36DXXN1+TXV | LPLC080B12MP13 | 14,400 | $720 |
| No | 207416848 | LUXAIRE | HMH72B241 | XAUB36DXXN1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 207416844 | LUXAIRE | HMH72B241 | XAUB36DXXN1+TXV | TM8V080B12MP12 | 14,400 | $720 |
| No | 207416842 | LUXAIRE | HMH72B241 | XAFB36DXXN1+TXV | LPLC080B12MP13 | 14,400 | $720 |
| No | 207416839 | LUXAIRE | HMH72B241 | XAFB36DXXN1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 207416835 | LUXAIRE | HMH72B241 | XAFB36DXXN1+TXV | TM8V080B12MP12 | 14,400 | $720 |
| No | 207417174 | LUXAIRE | HMH72B241 | XAUB36DXXN1+TXV | TM9E026A08MP12 | 14,800 | $740 |
| No | 207417170 | LUXAIRE | HMH72B241 | XAFB36DXXN1+TXV | TM9E026A08MP12 | 14,800 | $740 |
| No | 207416833 | LUXAIRE | HMH72B241 | XAFC36DXXN1+TXV | LP9C080B12MP13 | 14,400 | $720 |
| No | 207416829 | LUXAIRE | HMH72B241 | XAFC36DXXN1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 207416825 | LUXAIRE | HMH72B241 | XAFC36DXXN1+TXV | TM9V080B12MP12 | 14,400 | $720 |
| No | 208614021 | LUXAIRE | HMH72B241 | JHVTB36DBAC2N1 | | 14,000 | $700 |
| No | 208504348 | LUXAIRE | HMH72B241 | JHVTB36DXXC2N1+TXV | | 14,000 | $700 |
| No | 208614022 | LUXAIRE | HMH72B241 | JHVTC36DBAC2N1 | | 14,100 | $705 |
| No | 208503281 | LUXAIRE | HMH72B241 | JHVTC36DXXC2N1+TXV | | 14,100 | $705 |
| No | 207417469 | LUXAIRE | HMH72B241 | XAFC36DXXN1+TXV | LPLC080B12MP13 | 14,400 | $720 |
| No | 207417466 | LUXAIRE | HMH72B241 | XAFC36DXXN1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 207417462 | LUXAIRE | HMH72B241 | XAFC36DXXN1+TXV | TM8V080B12MP12 | 14,400 | $720 |
| No | 208400362 | LUXAIRE | HMH72B241 | XAHB36DXXN1+MVC12BN21+TXV | | 14,100 | $705 |
| No | 207416873 | LUXAIRE | HMH72B241 | XAUB36DXXN1+TXV | TMLE040A12MP11 | 14,500 | $725 |
| No | 207416869 | LUXAIRE | HMH72B241 | XAUB36DXXN1+TXV | TM8E040A12MP11 | 14,500 | $725 |
| No | 207416865 | LUXAIRE | HMH72B241 | XAFB36DXXN1+TXV | TMLE040A12MP11 | 14,500 | $725 |
| No | 207416861 | LUXAIRE | HMH72B241 | XAFB36DXXN1+TXV | TM8E040A12MP11 | 14,500 | $725 |
| No | 207417450 | LUXAIRE | HMH72B241 | XAUB36DXXN1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207417446 | LUXAIRE | HMH72B241 | XAFB36DXXN1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207417420 | LUXAIRE | HMH72B241 | XAFC36DXXN1+TXV | LP9C060B12MP13 | 14,600 | $730 |
| No | 207417416 | LUXAIRE | HMH72B241 | XAFC36DXXN1+TXV | TP9C060B12MP13 | 14,600 | $730 |
| No | 207417412 | LUXAIRE | HMH72B241 | XAFC36DXXN1+TXV | TM9V060B12MP12 | 14,600 | $730 |
| No | 207417388 | LUXAIRE | HMH72B241 | XAUB36DXXN1+TXV | TM9Y080B12MP11 | 14,600 | $730 |
| No | 207417384 | LUXAIRE | HMH72B241 | XAFB36DXXN1+TXV | TM9Y080B12MP11 | 14,600 | $730 |
| No | 208614055 | LUXAIRE | HMH72B361 | XAFC36DBCN1+JMET16CS2N1 | | 24,200 | $1,210 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208500508 | LUXAIRE | HMH72B361 | XAFC36DXXN1+JMET16CS2N1+TXV | | 24,200 | $1,210 |
| No | 208503342 | LUXAIRE | HMH72B361 | XAHC36DXXN1+JMET12CS2N1+TXV | | 24,200 | $1,210 |
| No | 208614050 | LUXAIRE | HMH72B361 | XAFC36DBCN1+JMET12CS2N1 | | 24,800 | $1,240 |
| No | 208502632 | LUXAIRE | HMH72B361 | XAFC36DXXN1+JMET12CS2N1+TXV | | 24,800 | $1,240 |
| No | 208503309 | LUXAIRE | HMH72B361 | XAHB36DXXN1+JMVT12BC2N1+TXV | | 24,200 | $1,210 |
| No | 208400377 | LUXAIRE | HMH72B361 | XAHB36DXXN1+ME12BN21+TXV | | 24,400 | $1,220 |
| No | 208400381 | LUXAIRE | HMH72B361 | XAHC36DXXN1+MVC12CN21+TXV | | 24,200 | $1,210 |
| No | 207416603 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 207416599 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 208213989 | LUXAIRE | HMH72B361 | XAHB36DXXN1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 208214012 | LUXAIRE | HMH72B361 | XAHB36DXXN1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 207417106 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TMLE080C16MP11 | 25,000 | $1,250 |
| No | 207417102 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TM8E080C16MP11 | 25,000 | $1,250 |
| No | 207417098 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TMLE120C16MP11 | 25,000 | $1,250 |
| No | 207417094 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TM8E120C16MP11 | 25,000 | $1,250 |
| No | 208214051 | LUXAIRE | HMH72B361 | XAHB36DXXN1+TXV | TM8Y080B12MP11 | 24,400 | $1,220 |
| No | 207417009 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TM8Y120C20MP11 | 24,600 | $1,230 |
| No | 208214004 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TM9E060B12MP12 | 24,200 | $1,210 |
| No | 208214001 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TM9E100C16MP12 | 24,600 | $1,230 |
| No | 207416979 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | LP9C080B12MP13 | 25,000 | $1,250 |
| No | 207416975 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 207416971 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 207416969 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | LP9C080B12MP13 | 25,000 | $1,250 |
| No | 207416965 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 207416961 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 207416431 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | LP9C100C20MP13 | 25,200 | $1,260 |
| No | 207416427 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TP9C100C20MP13 | 25,200 | $1,260 |
| No | 207416423 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TM9V100C20MP12 | 25,200 | $1,260 |
| No | 208214057 | LUXAIRE | HMH72B361 | XAHB36DXXN1+TXV | TM9Y080B12MP11 | 24,400 | $1,220 |
| No | 208502168 | LUXAIRE | HMH72B361 | XAUB36DXXN1+JMVT12BC2N1+TXV | | 24,600 | $1,230 |
| No | 208614052 | LUXAIRE | HMH72B361 | XAFB36DBCN1+JMVT12BC2N1 | | 24,600 | $1,230 |
| No | 208502161 | LUXAIRE | HMH72B361 | XAFB36DXXN1+JMVT12BC2N1+TXV | | 24,600 | $1,230 |
| No | 207434679 | LUXAIRE | HMH72B361 | XAUB36DXXN1+ME12BN21+TXV | | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207434680 | LUXAIRE | HMH72B361 | XAFB36DXXN1+ME12BN21+TXV | | 24,800 | $1,240 |
| No | 207434677 | LUXAIRE | HMH72B361 | XAFC36DXXN1+MVC12CN21+TXV | | 24,600 | $1,230 |
| No | 208213997 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TL8E080C16UH11 | 24,400 | $1,220 |
| No | 207417146 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | TMLE040A12MP11 | 25,000 | $1,250 |
| No | 207417142 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | TM8E040A12MP11 | 25,000 | $1,250 |
| No | 207417138 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | TMLE040A12MP11 | 25,000 | $1,250 |
| No | 207417134 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | TM8E040A12MP11 | 25,000 | $1,250 |
| No | 208501096 | LUXAIRE | HMH72B361 | XAHC36DXXN1+JMVT16CC2N1+TXV | | 24,000 | $1,200 |
| No | 208400378 | LUXAIRE | HMH72B361 | XAHC36DXXN1+ME12CN21+TXV | | 24,400 | $1,220 |
| No | 208400376 | LUXAIRE | HMH72B361 | XAHC36DXXN1+MVC16CN21+TXV | | 24,400 | $1,220 |
| No | 208213999 | LUXAIRE | HMH72B361 | XAHB36DXXN1+TXV | TL9E060B12UH11 | 24,000 | $1,200 |
| No | 207416583 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | TMLE060A12MP11 | 25,200 | $1,260 |
| No | 207416579 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | TM8E060A12MP11 | 25,200 | $1,260 |
| No | 207416575 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | TMLE060A12MP11 | 25,200 | $1,260 |
| No | 207416571 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | TM8E060A12MP11 | 25,200 | $1,260 |
| No | 207416559 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 207416555 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 207416551 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 207416547 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 207417090 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | TPLC060A12MP13 | 25,400 | $1,270 |
| No | 207417086 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | TMLV060A12MP12 | 25,400 | $1,270 |
| No | 207417082 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | TM8V060A12MP12 | 25,400 | $1,270 |
| No | 207417078 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | TPLC060A12MP13 | 25,400 | $1,270 |
| No | 207417074 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | TMLV060A12MP12 | 25,400 | $1,270 |
| No | 207417070 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | TM8V060A12MP12 | 25,400 | $1,270 |
| No | 208214025 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | LPLC100C16MP13 | 24,600 | $1,230 |
| No | 208214033 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | LPLC080C16MP13 | 24,600 | $1,230 |
| No | 208214044 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 208214043 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TPLC080C16MP13 | 24,600 | $1,230 |
| No | 208214007 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TMLV100C16MP12 | 24,600 | $1,230 |
| No | 208214023 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TM8V080C16MP12 | 24,600 | $1,230 |
| No | 208214024 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 207416497 | LUXAIRE | HMH72B361 | XAFA30DXXN1+TXV | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 208213987 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 208214008 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TM8E080B12MP11 | 24,600 | $1,230 |
| No | 208213983 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TMLE100C16MP11 | 24,600 | $1,230 |
| No | 208213992 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TM8E100C16MP11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207416509 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TM8Y080B12MP11 | 25,000 | $1,250 |
| No | 208214003 | LUXAIRE | HMH72B361 | XAHB36DXXN1+TXV | TM9E060B12MP12 | 24,200 | $1,210 |
| No | 207416461 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TM9E100C16MP12 | 25,000 | $1,250 |
| No | 208214037 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | LP9C060B12MP13 | 24,400 | $1,220 |
| No | 208214026 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 208214017 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 208214039 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | LP9C100C16MP13 | 24,600 | $1,230 |
| No | 208214045 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TP9C100C16MP13 | 24,600 | $1,230 |
| No | 208214019 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TM9V100C16MP12 | 24,600 | $1,230 |
| No | 207416929 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TM9Y080B12MP11 | 25,000 | $1,250 |
| No | 207416465 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TM9E080B12MP12 | 25,200 | $1,260 |
| No | 207416457 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | TM9V040A10MP12 | 24,600 | $1,230 |
| No | 207416453 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | TM9V040A10MP12 | 24,600 | $1,230 |
| No | 208214036 | LUXAIRE | HMH72B361 | XAHB36DXXN1+TXV | LP9C080B12MP13 | 24,400 | $1,220 |
| No | 208214030 | LUXAIRE | HMH72B361 | XAHB36DXXN1+TXV | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 208214014 | LUXAIRE | HMH72B361 | XAHB36DXXN1+TXV | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 207416937 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | TM9Y060B12MP11 | 25,000 | $1,250 |
| No | 207416933 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | TM9Y060B12MP11 | 25,000 | $1,250 |
| No | 207416925 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TM9Y080C16MP11 | 25,000 | $1,250 |
| No | 208614051 | LUXAIRE | HMH72B361 | JHETB36DBCS2N1 | | 25,000 | $1,250 |
| No | 208502182 | LUXAIRE | HMH72B361 | JHETB36DXXS2N1+TXV | | 25,000 | $1,250 |
| No | 207434676 | LUXAIRE | HMH72B361 | XAFC36DXXN1+ME16CN21+TXV | | 25,000 | $1,250 |
| No | 208214000 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TL9E060B12UH11 | 24,000 | $1,200 |
| No | 208213990 | LUXAIRE | HMH72B361 | XAHB36DXXN1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 208214011 | LUXAIRE | HMH72B361 | XAHB36DXXN1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 207416543 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 207416539 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 207416529 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | LPLC080B12MP13 | 25,000 | $1,250 |
| No | 207416526 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | TPLC080B12MP13 | 25,000 | $1,250 |
| No | 207416522 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | TM8V080B12MP12 | 25,000 | $1,250 |
| No | 207416520 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | LPLC080B12MP13 | 25,000 | $1,250 |
| No | 207416517 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | TPLC080B12MP13 | 25,000 | $1,250 |
| No | 207416513 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | TM8V080B12MP12 | 25,000 | $1,250 |
| No | 207416493 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | TM9E060A10MP12 | 25,200 | $1,260 |
| No | 207416489 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | TM9E060A10MP12 | 25,200 | $1,260 |
| No | 208614053 | LUXAIRE | HMH72B361 | JHETC36DBCS2N1 | | 24,000 | $1,200 |
| No | 208500520 | LUXAIRE | HMH72B361 | JHETC36DXXS2N1+TXV | | 24,000 | $1,200 |
| No | 207434674 | LUXAIRE | HMH72B361 | XAUB36DXXN1+MVC12BN21+TXV | | 24,800 | $1,240 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207434673 | LUXAIRE | HMH72B361 | XAFB36DXXN1+MVC12BN21+TXV | | 24,800 | $1,240 |
| No | 208213996 | LUXAIRE | HMH72B361 | XAHB36DXXN1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 208213998 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TL9E080C16UH11 | 24,600 | $1,230 |
| No | 207416567 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TMLE080B12MP11 | 25,200 | $1,260 |
| No | 207416563 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TM8E080B12MP11 | 25,200 | $1,260 |
| No | 208214006 | LUXAIRE | HMH72B361 | XAHB36DXXN1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 208214016 | LUXAIRE | HMH72B361 | XAHB36DXXN1+TXV | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 208214035 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | LP9C080B12MP13 | 24,600 | $1,230 |
| No | 208214029 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 208214013 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 207416419 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TM9Y060B12MP11 | 25,000 | $1,250 |
| No | 208214058 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TM9Y080C16MP11 | 24,600 | $1,230 |
| No | 208213984 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 208213993 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 208214032 | LUXAIRE | HMH72B361 | XAHB36DXXN1+TXV | LPLC080B12MP13 | 24,200 | $1,210 |
| No | 208214042 | LUXAIRE | HMH72B361 | XAHB36DXXN1+TXV | TPLC080B12MP13 | 24,200 | $1,210 |
| No | 208214022 | LUXAIRE | HMH72B361 | XAHB36DXXN1+TXV | TM8V080B12MP12 | 24,200 | $1,210 |
| No | 208214050 | LUXAIRE | HMH72B361 | XAHB36DXXN1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 208214053 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TM8Y080C16MP11 | 24,000 | $1,200 |
| No | 208214048 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TM8Y100C16MP11 | 24,000 | $1,200 |
| No | 207416485 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 207416481 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 208614048 | LUXAIRE | HMH72B361 | JHVTC36DBCC2N1 | | 24,400 | $1,220 |
| No | 208501703 | LUXAIRE | HMH72B361 | JHVTC36DXXC2N1+TXV | | 24,400 | $1,220 |
| No | 208400379 | LUXAIRE | HMH72B361 | XAHC36DXXN1+ME16CN21+TXV | | 24,600 | $1,230 |
| No | 207416611 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | TL8E060A12UH11 | 25,000 | $1,250 |
| No | 207416607 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | TL8E060A12UH11 | 25,000 | $1,250 |
| No | 207416595 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TL9E080C16UH11 | 25,000 | $1,250 |
| No | 207417122 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | TMLE080B12MP11 | 25,200 | $1,260 |
| No | 207417118 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | TM8E080B12MP11 | 25,200 | $1,260 |
| No | 207417114 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | TMLE080B12MP11 | 25,200 | $1,260 |
| No | 207417110 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | TM8E080B12MP11 | 25,200 | $1,260 |
| No | 208614054 | LUXAIRE | HMH72B361 | XAFC36DBCN1+JMVT16CC2N1 | | 24,400 | $1,220 |
| No | 208501104 | LUXAIRE | HMH72B361 | XAFC36DXXN1+JMVT16CC2N1+TXV | | 24,400 | $1,220 |
| No | 207434675 | LUXAIRE | HMH72B361 | XAFC36DXXN1+ME12CN21+TXV | | 24,800 | $1,240 |
| No | 207434678 | LUXAIRE | HMH72B361 | XAFC36DXXN1+MVC16CN21+TXV | | 24,800 | $1,240 |
| No | 207417150 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417005 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TM9E080C16MP12 | 25,000 | $1,250 |
| No | 207416451 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | LP9C060B12MP13 | 24,800 | $1,240 |
| No | 207416447 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TP9C060B12MP13 | 24,800 | $1,240 |
| No | 207416443 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TM9V060B12MP12 | 24,800 | $1,240 |
| No | 208214034 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | LP9C080C16MP13 | 24,600 | $1,230 |
| No | 208214028 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TP9C080C16MP13 | 24,600 | $1,230 |
| No | 208214015 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TM9V080C16MP12 | 24,600 | $1,230 |
| No | 208214054 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TM9Y060B12MP11 | 24,400 | $1,220 |
| No | 208214059 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TM9Y100C16MP11 | 24,600 | $1,230 |
| No | 208213985 | LUXAIRE | HMH72B361 | XAHB36DXXN1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 208213994 | LUXAIRE | HMH72B361 | XAHB36DXXN1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 207417068 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | LPLC080B12MP13 | 25,000 | $1,250 |
| No | 207417065 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TPLC080B12MP13 | 25,000 | $1,250 |
| No | 207417061 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TM8V080B12MP12 | 25,000 | $1,250 |
| No | 207417029 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | TM8Y060A12MP11 | 24,800 | $1,240 |
| No | 207417025 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | TM8Y060A12MP11 | 24,800 | $1,240 |
| No | 207416505 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TM8Y080C16MP11 | 24,600 | $1,230 |
| No | 207417013 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TM8Y100C16MP11 | 24,600 | $1,230 |
| No | 208213995 | LUXAIRE | HMH72B361 | XAHB36DXXN1+TXV | TM9E060A10MP12 | 24,200 | $1,210 |
| No | 208213986 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TMLE080C16MP11 | 24,400 | $1,220 |
| No | 208214010 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TM8E080C16MP11 | 24,400 | $1,220 |
| No | 208213982 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TMLE120C16MP11 | 24,600 | $1,230 |
| No | 208213991 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TM8E120C16MP11 | 24,600 | $1,230 |
| No | 207417059 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | LPLC100C16MP13 | 25,200 | $1,260 |
| No | 207417057 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | LPLC080C16MP13 | 25,200 | $1,260 |
| No | 207417053 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TPLC100C16MP13 | 25,200 | $1,260 |
| No | 207417049 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TPLC080C16MP13 | 25,200 | $1,260 |
| No | 207417045 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TMLV100C16MP12 | 25,200 | $1,260 |
| No | 207417041 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TM8V080C16MP12 | 25,200 | $1,260 |
| No | 207417037 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TM8V100C16MP12 | 25,200 | $1,260 |
| No | 208214052 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TM8Y080B12MP11 | 24,400 | $1,220 |
| No | 208214049 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TM8Y100C20MP11 | 24,200 | $1,210 |
| No | 208214047 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TM8Y120C20MP11 | 24,200 | $1,210 |
| No | 208502175 | LUXAIRE | HMH72B361 | XAHC36DXXN1+JMET16CS2N1+TXV | | 24,400 | $1,220 |
| No | 208614049 | LUXAIRE | HMH72B361 | JHVTB36DBCC2N1 | | 25,200 | $1,260 |
| No | 208502639 | LUXAIRE | HMH72B361 | JHVTB36DXXC2N1+TXV | | 25,200 | $1,260 |
| No | 208400380 | LUXAIRE | HMH72B361 | XAHB36DXXN1+MVC12BN21+TXV | | 24,400 | $1,220 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417154 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TL8E080C16UH11 | 25,000 | $1,250 |
| No | 208214005 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 207416999 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | LP9C060B12MP13 | 25,000 | $1,250 |
| No | 207416995 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 207416991 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 207416989 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | LP9C060B12MP13 | 25,000 | $1,250 |
| No | 207416985 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 207416981 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 207416959 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | LP9C080C16MP13 | 25,000 | $1,250 |
| No | 207416955 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TP9C080C16MP13 | 25,000 | $1,250 |
| No | 207416951 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TM9V080C16MP12 | 25,000 | $1,250 |
| No | 208214055 | LUXAIRE | HMH72B361 | XAHB36DXXN1+TXV | TM9Y060B12MP11 | 23,800 | $1,190 |
| No | 207416921 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TM9Y100C16MP11 | 25,000 | $1,250 |
| No | 207416473 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | TM9E080B12MP12 | 25,200 | $1,260 |
| No | 207416469 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | TM9E080B12MP12 | 25,200 | $1,260 |
| No | 207417001 | LUXAIRE | HMH72B361 | XAFA30DXXN1+TXV | TM9V040A10MP12 | 24,400 | $1,220 |
| No | 207416441 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | LP9C080B12MP13 | 25,000 | $1,250 |
| No | 207416437 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 207416433 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 208214040 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | LP9C100C20MP13 | 25,000 | $1,250 |
| No | 208214046 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TP9C100C20MP13 | 25,000 | $1,250 |
| No | 208214020 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TM9V100C20MP12 | 25,000 | $1,250 |
| No | 208214056 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TM9Y080B12MP11 | 24,400 | $1,220 |
| No | 208213988 | LUXAIRE | HMH72B361 | XAHB36DXXN1+TXV | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 208214009 | LUXAIRE | HMH72B361 | XAHB36DXXN1+TXV | TM8E080B12MP11 | 24,600 | $1,230 |
| No | 207416535 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TMLE100C16MP11 | 25,000 | $1,250 |
| No | 207416531 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TM8E100C16MP11 | 25,000 | $1,250 |
| No | 208214031 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | LPLC080B12MP13 | 24,600 | $1,230 |
| No | 208214041 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 208214021 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 207417021 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | TM8Y080B12MP11 | 25,000 | $1,250 |
| No | 207417017 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | TM8Y080B12MP11 | 25,000 | $1,250 |
| No | 207416501 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TM8Y100C20MP11 | 24,600 | $1,230 |
| No | 207416477 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 208214002 | LUXAIRE | HMH72B361 | XAHC36DXXN1+TXV | TM9E080C16MP12 | 24,600 | $1,230 |
| No | 208214038 | LUXAIRE | HMH72B361 | XAHB36DXXN1+TXV | LP9C060B12MP13 | 24,600 | $1,230 |
| No | 208214027 | LUXAIRE | HMH72B361 | XAHB36DXXN1+TXV | TP9C060B12MP13 | 24,600 | $1,230 |
| No | 208214018 | LUXAIRE | HMH72B361 | XAHB36DXXN1+TXV | TM9V060B12MP12 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207416949 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | LP9C100C16MP13 | 25,000 | $1,250 |
| No | 207416945 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TP9C100C16MP13 | 25,000 | $1,250 |
| No | 207416941 | LUXAIRE | HMH72B361 | XAFC36DXXN1+TXV | TM9V100C16MP12 | 25,000 | $1,250 |
| No | 207416415 | LUXAIRE | HMH72B361 | XAUB36DXXN1+TXV | TM9Y080B12MP11 | 25,000 | $1,250 |
| No | 207416411 | LUXAIRE | HMH72B361 | XAFB36DXXN1+TXV | TM9Y080B12MP11 | 25,000 | $1,250 |
| No | 208214510 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | TL8E100C20UH11 | 35,800 | $1,790 |
| No | 208214503 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | TMLE100C16MP11 | 36,000 | $1,800 |
| No | 208214509 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | TM8E100C16MP11 | 36,000 | $1,800 |
| No | 208214513 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | TM9E080C20MP12 | 36,600 | $1,830 |
| No | 208214522 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | LP9C100C20MP13 | 36,200 | $1,810 |
| No | 208214525 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | TP9C100C20MP13 | 36,200 | $1,810 |
| No | 208214519 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | TM9V100C20MP12 | 36,200 | $1,810 |
| No | 208502189 | LUXAIRE | HMH72B601 | XAHD60JXXN1+JMET18DS2N1+TXV | | 35,800 | $1,790 |
| No | 208400420 | LUXAIRE | HMH72B601 | XAHD60JXXN1+MVC20DN21+TXV | | 36,800 | $1,840 |
| No | 208614092 | LUXAIRE | HMH72B601 | JHETD60JBCS2N1 | | 36,400 | $1,820 |
| No | 208501711 | LUXAIRE | HMH72B601 | JHETD60JXXS2N1+TXV | | 36,400 | $1,820 |
| No | 207434723 | LUXAIRE | HMH72B601 | XAFD60JXXN1+ME20DN21+TXV | | 37,200 | $1,860 |
| No | 208214506 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | TMLE080C16MP11 | 36,000 | $1,800 |
| No | 208214516 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | TM8E080C16MP11 | 36,000 | $1,800 |
| No | 208214502 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | TMLE120C16MP11 | 36,000 | $1,800 |
| No | 208214507 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | TM8E120C16MP11 | 36,000 | $1,800 |
| No | 208214515 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | TM9E120D20MP12 | 36,000 | $1,800 |
| No | 208214532 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | TM9Y100C20MP11 | 35,800 | $1,790 |
| No | 207416785 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TMLE100C20MP11 | 36,200 | $1,810 |
| No | 207416781 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TM8E100C20MP11 | 36,200 | $1,810 |
| No | 207416773 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TM8Y100C16MP11 | 36,600 | $1,830 |
| No | 207417345 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TM9E100C20MP12 | 37,000 | $1,850 |
| No | 207417319 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | LP9C120D20MP13 | 37,400 | $1,870 |
| No | 207417315 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TP9C120D20MP13 | 37,400 | $1,870 |
| No | 207417311 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TM9V120D20MP12 | 37,400 | $1,870 |
| No | 208614095 | LUXAIRE | HMH72B601 | JHVTD60JBCC2N1 | | 36,200 | $1,810 |
| No | 208501118 | LUXAIRE | HMH72B601 | JHVTD60JXXC2N1+TXV | | 36,200 | $1,810 |
| No | 208400421 | LUXAIRE | HMH72B601 | XAHD60JXXN1+ME20DN21+TXV | | 36,600 | $1,830 |
| No | 208614094 | LUXAIRE | HMH72B601 | XAFD60JBCN1+JMVT20DC2N1 | | 36,000 | $1,800 |
| No | 208500532 | LUXAIRE | HMH72B601 | XAFD60JXXN1+JMVT20DC2N1+TXV | | 36,000 | $1,800 |
| No | 207416821 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TL8E080C16UH11 | 36,600 | $1,830 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207416801 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TMLE080C20MP11 | 36,400 | $1,820 |
| No | 207416797 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TM8E080C20MP11 | 36,400 | $1,820 |
| No | 207417339 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | LP9C100C16MP13 | 36,800 | $1,840 |
| No | 207417335 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TP9C100C16MP13 | 36,800 | $1,840 |
| No | 207417331 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TM9V100C16MP12 | 36,800 | $1,840 |
| No | 208214512 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | TL9E100C20UH11 | 36,000 | $1,800 |
| No | 208214504 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | TMLE100C20MP11 | 35,600 | $1,780 |
| No | 208214508 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | TM8E100C20MP11 | 35,600 | $1,780 |
| No | 208214530 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | TM8Y080C16MP11 | 35,800 | $1,790 |
| No | 208214529 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | TM8Y100C16MP11 | 35,800 | $1,790 |
| No | 208214514 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | TM9E100C20MP12 | 36,400 | $1,820 |
| No | 208214523 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | LP9C120D20MP13 | 36,200 | $1,810 |
| No | 208214526 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | TP9C120D20MP13 | 36,200 | $1,810 |
| No | 208214520 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | TM9V120D20MP12 | 36,200 | $1,810 |
| No | 207416817 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TL8E100C20UH11 | 36,600 | $1,830 |
| No | 207417349 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TM9E080C20MP12 | 37,200 | $1,860 |
| No | 208614093 | LUXAIRE | HMH72B601 | XAFD60JBCN1+JMET18DS2N1 | | 36,400 | $1,820 |
| No | 208500542 | LUXAIRE | HMH72B601 | XAFD60JXXN1+JMET18DS2N1+TXV | | 36,400 | $1,820 |
| No | 207416813 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TL9E100C20UH11 | 36,600 | $1,830 |
| No | 207416777 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TM8Y080C16MP11 | 36,600 | $1,830 |
| No | 207417329 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | LP9C100C20MP13 | 36,800 | $1,840 |
| No | 207417325 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TP9C100C20MP13 | 36,800 | $1,840 |
| No | 207417321 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TM9V100C20MP12 | 36,800 | $1,840 |
| No | 207434724 | LUXAIRE | HMH72B601 | XAFD60JXXN1+MVC20DN21+TXV | | 37,200 | $1,860 |
| No | 208501111 | LUXAIRE | HMH72B601 | XAHD60JXXN1+JMVT20DC2N1+TXV | | 35,400 | $1,770 |
| No | 207416793 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TMLE100C16MP11 | 36,800 | $1,840 |
| No | 207416789 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TM8E100C16MP11 | 36,800 | $1,840 |
| No | 207416765 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TM8Y120C20MP11 | 36,400 | $1,820 |
| No | 207417303 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TM9Y120D20MP11 | 36,600 | $1,830 |
| No | 208214511 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | TL8E080C16UH11 | 36,000 | $1,800 |
| No | 207416809 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TMLE080C16MP11 | 36,800 | $1,840 |
| No | 207416805 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TM8E080C16MP11 | 36,800 | $1,840 |
| No | 207417380 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TMLE120C16MP11 | 36,600 | $1,830 |
| No | 207417376 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TM8E120C16MP11 | 36,600 | $1,830 |
| No | 207416769 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TM8Y100C20MP11 | 36,400 | $1,820 |
| No | 207417341 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TM9E120D20MP12 | 37,200 | $1,860 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207417307 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TM9Y100C20MP11 | 36,600 | $1,830 |
| No | 208214505 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | TMLE080C20MP11 | 35,600 | $1,780 |
| No | 208214517 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | TM8E080C20MP11 | 35,600 | $1,780 |
| No | 207417374 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | LPLC120C20MP13 | 37,400 | $1,870 |
| No | 207417372 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | LPLC100C20MP13 | 37,400 | $1,870 |
| No | 207417369 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TPLC120C20MP13 | 37,400 | $1,870 |
| No | 207417365 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TPLC100C20MP13 | 37,400 | $1,870 |
| No | 207417361 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TMLV120C20MP12 | 37,400 | $1,870 |
| No | 207417357 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TM8V100C20MP12 | 37,400 | $1,870 |
| No | 207417353 | LUXAIRE | HMH72B601 | XAFD60JXXN1+TXV | TM8V120C20MP12 | 37,400 | $1,870 |
| No | 208214528 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | TM8Y100C20MP11 | 35,600 | $1,780 |
| No | 208214527 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | TM8Y120C20MP11 | 35,600 | $1,780 |
| No | 208214521 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | LP9C100C16MP13 | 36,200 | $1,810 |
| No | 208214524 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | TP9C100C16MP13 | 36,200 | $1,810 |
| No | 208214518 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | TM9V100C16MP12 | 36,200 | $1,810 |
| No | 208214531 | LUXAIRE | HMH72B601 | XAHD60JXXN1+TXV | TM9Y120D20MP11 | 35,800 | $1,790 |
| No | 207434706 | LUXAIRE | HMH72B481 | XAFC60HXXN1+ME12CN21+TXV | | 29,200 | $1,460 |
| No | 208400403 | LUXAIRE | HMH72B481 | XAHC60HXXN1+MVC12CN21+TXV | | 28,600 | $1,430 |
| No | 208400400 | LUXAIRE | HMH72B481 | XAHC60HXXN1+ME12CN21+TXV | | 28,600 | $1,430 |
| No | 207434708 | LUXAIRE | HMH72B481 | XAFC60HXXN1+MVC12CN21+TXV | | 28,800 | $1,440 |
| No | 207416761 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TL8E100C20UH11 | 29,800 | $1,490 |
| No | 208614077 | LUXAIRE | HMH72B481 | JHETD48GBCS2N1 | | 29,600 | $1,480 |
| No | 208501089 | LUXAIRE | HMH72B481 | JHETC60HXXS2N1+TXV | | 29,600 | $1,480 |
| No | 207434707 | LUXAIRE | HMH72B481 | XAFD60JXXN1+ME14DN21+TXV | | 30,000 | $1,500 |
| No | 207417299 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TL8E080C16UH11 | 29,200 | $1,460 |
| No | 207417532 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TMLE080C16MP11 | 30,200 | $1,510 |
| No | 207417528 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TM8E080C16MP11 | 30,200 | $1,510 |
| No | 207416735 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | LPLC100C16MP13 | 29,600 | $1,480 |
| No | 207416733 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | LPLC080C16MP13 | 29,600 | $1,480 |
| No | 207416729 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TPLC100C16MP13 | 29,600 | $1,480 |
| No | 207416725 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TPLC080C16MP13 | 29,600 | $1,480 |
| No | 207416721 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TMLV100C16MP12 | 29,600 | $1,480 |
| No | 207416713 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TM8V100C16MP12 | 29,600 | $1,480 |
| No | 207416895 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | LP9C100C20MP13 | 31,000 | $1,550 |
| No | 207416891 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TP9C100C20MP13 | 31,000 | $1,550 |
| No | 207416887 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TM9V100C20MP12 | 31,000 | $1,550 |
| No | 207417206 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TM9Y100C16MP11 | 30,200 | $1,510 |
| No | 207416901 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TM8Y100C20MP11 | 29,800 | $1,490 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207416897 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TM8Y120C20MP11 | 29,800 | $1,490 |
| No | 208400401 | LUXAIRE | HMH72B481 | XAHD60JXXN1+ME14DN21+TXV | | 28,800 | $1,440 |
| No | 207416909 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TL8E080C16UH11 | 30,200 | $1,510 |
| No | 208214291 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | TMLE080C16MP11 | 29,600 | $1,480 |
| No | 208214305 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | TM8E080C16MP11 | 29,600 | $1,480 |
| No | 207416913 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TM9Y100C16MP11 | 30,000 | $1,500 |
| No | 207417510 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | LPLC120C20MP13 | 29,800 | $1,490 |
| No | 207417508 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | LPLC100C20MP13 | 29,800 | $1,490 |
| No | 207417505 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TPLC120C20MP13 | 29,800 | $1,490 |
| No | 207417501 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TPLC100C20MP13 | 29,800 | $1,490 |
| No | 207417497 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TMLV120C20MP12 | 29,800 | $1,490 |
| No | 207417489 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TM8V120C20MP12 | 29,800 | $1,490 |
| No | 208614078 | LUXAIRE | HMH72B481 | JHVTD60JBCC2N1 | | 29,800 | $1,490 |
| No | 208503457 | LUXAIRE | HMH72B481 | JHVTD60JXXC2N1+TXV | | 29,800 | $1,490 |
| No | 207416757 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TMLE080C16MP11 | 30,000 | $1,500 |
| No | 207416753 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TM8E080C16MP11 | 30,000 | $1,500 |
| No | 207416717 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TM8V080C16MP12 | 29,600 | $1,480 |
| No | 208214322 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | LPLC120C20MP13 | 28,800 | $1,440 |
| No | 208214320 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | LPLC100C20MP13 | 28,800 | $1,440 |
| No | 208214312 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | TPLC120C20MP13 | 28,800 | $1,440 |
| No | 208214334 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | TPLC100C20MP13 | 28,800 | $1,440 |
| No | 208214303 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | TMLV120C20MP12 | 28,800 | $1,440 |
| No | 208214304 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | TM8V120C20MP12 | 28,800 | $1,440 |
| No | 208214333 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | LP9C100C16MP13 | 30,400 | $1,520 |
| No | 208214341 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | TP9C100C16MP13 | 30,400 | $1,520 |
| No | 208214310 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | TM9V100C16MP12 | 30,400 | $1,520 |
| No | 207417202 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TM9Y120D20MP11 | 30,600 | $1,530 |
| No | 208214289 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | TMLE120C16MP11 | 29,600 | $1,480 |
| No | 208214293 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | TM8E120C16MP11 | 29,600 | $1,480 |
| No | 207417265 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | LPLC120C20MP13 | 29,200 | $1,460 |
| No | 207417263 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | LPLC100C20MP13 | 29,200 | $1,460 |
| No | 207417260 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TPLC120C20MP13 | 29,200 | $1,460 |
| No | 207417256 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TPLC100C20MP13 | 29,200 | $1,460 |
| No | 207417252 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TMLV120C20MP12 | 29,200 | $1,460 |
| No | 207417244 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TM8V120C20MP12 | 29,200 | $1,460 |
| No | 207416697 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | LP9C100C16MP13 | 30,800 | $1,540 |
| No | 207416693 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TP9C100C16MP13 | 30,800 | $1,540 |
| No | 207416689 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TM9V100C16MP12 | 30,800 | $1,540 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207416675 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TM9Y080C16MP11 | 30,200 | $1,510 |
| No | 208400402 | LUXAIRE | HMH72B481 | XAHC60HXXN1+MVC16CN21+TXV | | 29,200 | $1,460 |
| No | 208614076 | LUXAIRE | HMH72B481 | JHVTD42FBCC2N1 | | 29,800 | $1,490 |
| No | 208501156 | LUXAIRE | HMH72B481 | JHVTC60HXXC2N1+TXV | | 29,800 | $1,490 |
| No | 207417291 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TL9E080C16UH11 | 29,600 | $1,480 |
| No | 208214315 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | TM8V100C20MP12 | 29,200 | $1,460 |
| No | 208214350 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | TM8Y080C16MP11 | 29,600 | $1,480 |
| No | 208214349 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | TM8Y100C16MP11 | 29,600 | $1,480 |
| No | 207416707 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | LP9C080C16MP13 | 30,600 | $1,530 |
| No | 207416703 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TP9C080C16MP13 | 30,600 | $1,530 |
| No | 207416699 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TM9V080C16MP12 | 30,600 | $1,530 |
| No | 208214325 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | LP9C120D20MP13 | 30,400 | $1,520 |
| No | 208214339 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | TP9C120D20MP13 | 30,400 | $1,520 |
| No | 208214318 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | TM9V120D20MP12 | 30,400 | $1,520 |
| No | 207417487 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | LP9C100C16MP13 | 31,000 | $1,550 |
| No | 207417483 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TP9C100C16MP13 | 31,000 | $1,550 |
| No | 207417479 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TM9V100C16MP12 | 31,000 | $1,550 |
| No | 207434703 | LUXAIRE | HMH72B481 | XAFC60HXXN1+ME16CN21+TXV | | 30,400 | $1,520 |
| No | 208214298 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | TL8E080C16UH11 | 29,600 | $1,480 |
| No | 207416749 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TMLE100C16MP11 | 30,000 | $1,500 |
| No | 207416745 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TM8E100C16MP11 | 30,000 | $1,500 |
| No | 207417289 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | LPLC100C16MP13 | 29,400 | $1,470 |
| No | 207417287 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | LPLC080C16MP13 | 29,400 | $1,470 |
| No | 207417283 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TPLC100C16MP13 | 29,400 | $1,470 |
| No | 207417279 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TPLC080C16MP13 | 29,400 | $1,470 |
| No | 207417275 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TMLV100C16MP12 | 29,400 | $1,470 |
| No | 207417271 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TM8V080C16MP12 | 29,400 | $1,470 |
| No | 207417267 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TM8V100C16MP12 | 29,400 | $1,470 |
| No | 207417224 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TM8Y100C20MP11 | 29,600 | $1,480 |
| No | 207417220 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TM8Y120C20MP11 | 29,600 | $1,480 |
| No | 207416687 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | LP9C100C20MP13 | 31,000 | $1,550 |
| No | 207416683 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TP9C100C20MP13 | 31,000 | $1,550 |
| No | 207416679 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TM9V100C20MP12 | 31,000 | $1,550 |
| No | 208214352 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | TM9Y120D20MP11 | 30,000 | $1,500 |
| No | 207417524 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TMLE100C16MP11 | 30,200 | $1,510 |
| No | 207417520 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TM8E100C16MP11 | 30,200 | $1,510 |
| No | 207434704 | LUXAIRE | HMH72B481 | XAFD60JXXN1+MVC14DN21+TXV | | 29,800 | $1,490 |
| No | 207416905 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TL8E100C20UH11 | 30,000 | $1,500 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207434705 | LUXAIRE | HMH72B481 | XAFC60HXXN1+MVC16CN21+TXV | | 29,800 | $1,490 |
| No | 207417516 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TMLE120C16MP11 | 30,200 | $1,510 |
| No | 207417512 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TM8E120C16MP11 | 30,200 | $1,510 |
| No | 208614079 | LUXAIRE | HMH72B481 | JHETD60JBCS2N1 | | 30,000 | $1,500 |
| No | 208503474 | LUXAIRE | HMH72B481 | JHETD60JXXS2N1+TXV | | 30,000 | $1,500 |
| No | 208400405 | LUXAIRE | HMH72B481 | XAHD60JXXN1+MVC14DN21+TXV | | 29,400 | $1,470 |
| No | 208214300 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | TL8E100C20UH11 | 29,400 | $1,470 |
| No | 208214290 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | TMLE100C16MP11 | 29,600 | $1,480 |
| No | 208214294 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | TM8E100C16MP11 | 29,600 | $1,480 |
| No | 207417248 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TM8V100C20MP12 | 29,600 | $1,480 |
| No | 207417240 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TM8Y080C16MP11 | 29,800 | $1,490 |
| No | 207417236 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TM8Y100C16MP11 | 29,800 | $1,490 |
| No | 208214346 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | TM8Y100C20MP11 | 29,200 | $1,460 |
| No | 208214345 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | TM8Y120C20MP11 | 29,200 | $1,460 |
| No | 208214331 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | LP9C100C20MP13 | 30,400 | $1,520 |
| No | 208214340 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | TP9C100C20MP13 | 30,400 | $1,520 |
| No | 208214308 | LUXAIRE | HMH72B481 | XAHD60JXXN1+TXV | TM9V100C20MP12 | 30,400 | $1,520 |
| No | 207416741 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TMLE120C16MP11 | 30,000 | $1,500 |
| No | 207416737 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TM8E120C16MP11 | 30,000 | $1,500 |
| No | 207417493 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TM8V100C20MP12 | 29,800 | $1,490 |
| No | 207417232 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TM8Y080C16MP11 | 30,200 | $1,510 |
| No | 207417228 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TM8Y100C16MP11 | 30,200 | $1,510 |
| No | 207417218 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | LP9C080C16MP13 | 30,600 | $1,530 |
| No | 207417214 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TP9C080C16MP13 | 30,600 | $1,530 |
| No | 207417210 | LUXAIRE | HMH72B481 | XAFC60HXXN1+TXV | TM9V080C16MP12 | 30,600 | $1,530 |
| No | 207416885 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | LP9C120D20MP13 | 30,800 | $1,540 |
| No | 207416881 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TP9C120D20MP13 | 30,800 | $1,540 |
| No | 207416877 | LUXAIRE | HMH72B481 | XAFD60JXXN1+TXV | TM9V120D20MP12 | 30,800 | $1,540 |
| No | 9006286 | LUXAIRE | TH16B6021 | AE60DX21+TXV | | 33,200 | $1,660 |
| No | 10309051 | LUXAIRE | HL20B6021 | CM61DE4A1+MVC20DN21 | | 45,500 | $2,275 |
| No | 10525676 | LUXAIRE | HL20B2421 | CM25BE1A1 | LP9C080B12MP13 | 22,400 | $1,120 |
| No | 10525675 | LUXAIRE | HL20B2421 | CM25BE1A1 | LP9C060B12MP13 | 21,200 | $1,060 |
| No | 10525677 | LUXAIRE | HL20B2421 | CM25BE1A1 | LPLC080B12MP13 | 22,400 | $1,120 |
| No | 10525681 | LUXAIRE | HL20B2421 | CM25BE1A1 | TMLV080B12MP12 | 22,400 | $1,120 |
| No | 10525678 | LUXAIRE | HL20B2421 | CM25BE1A1 | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 10525682 | LUXAIRE | HL20B2421 | CM25BE1A1 | TP9C060B12MP13 | 21,200 | $1,060 |
| No | 10525680 | LUXAIRE | HL20B2421 | CM25BE1A1 | TM9V080B12MP12 | 22,400 | $1,120 |
| No | 10525679 | LUXAIRE | HL20B2421 | CM25BE1A1 | TM9V060B12MP12 | 21,200 | $1,060 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10525684 | LUXAIRE | HL20B2421 | CM25BE1A1 | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 10525683 | LUXAIRE | HL20B2421 | CM25BE1A1 | TP9C080B12MP13 | 22,400 | $1,120 |
| No | 10525701 | LUXAIRE | HL20B4821 | CM50CE3A1 | LP9C100C16MP13 | 44,000 | $2,200 |
| No | 10525719 | LUXAIRE | HL20B4821 | CM50CE3A1 | TP9C100C16MP13 | 44,000 | $2,200 |
| No | 201982913 | LUXAIRE | HL20B2421S | AVV25BE121 | | 22,400 | $1,120 |
| No | 201982949 | LUXAIRE | HL20B6021 | AVV61DE421 | | 46,000 | $2,300 |
| No | 10525712 | LUXAIRE | HL20B4821 | CM50CE3A1 | TM9V100C16MP12 | 44,000 | $2,200 |
| No | 201982927 | LUXAIRE | HL20B3621S | CM37BE2A1+CC | TM9V060B12MP12 | 31,600 | $1,580 |
| No | 201982928 | LUXAIRE | HL20B3621S | CM37BE2A1+CC | TM9V080B12MP12 | 31,000 | $1,550 |
| No | 201982935 | LUXAIRE | HL20B3621S | CM37BE2A1+CC | TP9C060B12MP13 | 31,600 | $1,580 |
| No | 201982936 | LUXAIRE | HL20B3621S | CM37BE2A1+CC | TP9C080B12MP13 | 31,000 | $1,550 |
| No | 201982941 | LUXAIRE | HL20B3621S | CM37BE2A1+CC | LP9C060B12MP13 | 31,600 | $1,580 |
| No | 201982942 | LUXAIRE | HL20B3621S | CM37BE2A1+CC | LP9C080B12MP13 | 31,000 | $1,550 |
| No | 201982947 | LUXAIRE | HL20B3621S | CM37BE2A1+MVC12BN21+CC | | 30,800 | $1,540 |
| No | 10309055 | LUXAIRE | HL20B6021S | AVV61CE421+CC | | 46,000 | $2,300 |
| No | 10525728 | LUXAIRE | HL20B6021S | CM61CE4A1+CC | LP9C100C20MP13 | 46,500 | $2,325 |
| No | 10525729 | LUXAIRE | HL20B6021S | CM61CE4A1+CC | LPLC100C20MP13 | 46,000 | $2,300 |
| No | 10525730 | LUXAIRE | HL20B6021S | CM61CE4A1+CC | LPLC120C20MP13 | 46,000 | $2,300 |
| No | 10525731 | LUXAIRE | HL20B6021S | CM61CE4A1+CC | TM8V100C20MP12 | 46,000 | $2,300 |
| No | 10525732 | LUXAIRE | HL20B6021S | CM61CE4A1+CC | TM8V120C20MP12 | 46,000 | $2,300 |
| No | 10525733 | LUXAIRE | HL20B6021S | CM61CE4A1+CC | TM9V100C20MP12 | 46,500 | $2,325 |
| No | 10525734 | LUXAIRE | HL20B6021S | CM61CE4A1+CC | TMLV100C20MP12 | 46,000 | $2,300 |
| No | 10525735 | LUXAIRE | HL20B6021S | CM61CE4A1+CC | TMLV120C20MP12 | 46,000 | $2,300 |
| No | 10525736 | LUXAIRE | HL20B6021S | CM61CE4A1+CC | TP9C100C20MP13 | 46,500 | $2,325 |
| No | 10525737 | LUXAIRE | HL20B6021S | CM61CE4A1+CC | TPLC100C20MP13 | 46,000 | $2,300 |
| No | 10525739 | LUXAIRE | HL20B6021S | CM61DE4A1+CC | LP9C120D20MP13 | 46,000 | $2,300 |
| No | 10525738 | LUXAIRE | HL20B6021S | CM61CE4A1+CC | TPLC120C20MP13 | 46,000 | $2,300 |
| No | 10525740 | LUXAIRE | HL20B6021S | CM61DE4A1+CC | TM9V120D20MP12 | 46,000 | $2,300 |
| No | 10525741 | LUXAIRE | HL20B6021S | CM61DE4A1+CC | TP9C120D20MP13 | 46,000 | $2,300 |
| No | 201982923 | LUXAIRE | HL20B3621S | AVV37BE221+CC | | 31,000 | $1,550 |
| No | 205537301 | LUXAIRE | TH16B3622 | CU36BXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203430829 | LUXAIRE | TH16B3622 | CM36BBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205538523 | LUXAIRE | TH16B3622 | CM36BXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203430824 | LUXAIRE | TH16B3622 | CF36BBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205538507 | LUXAIRE | TH16B3622 | CM36BXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205538514 | LUXAIRE | TH16B3622 | CU36BXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203087058 | LUXAIRE | TH16B3622 | CM36BBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203087041 | LUXAIRE | TH16B3622 | CF36BBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205538489 | LUXAIRE | TH16B3622 | CF36BXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205544334 | LUXAIRE | TH16B3622 | CU36BXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 203088183 | LUXAIRE | TH16B3622 | CM36BBCA1 | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205538480 | LUXAIRE | TH16B3622 | CF36BXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205544326 | LUXAIRE | TH16B3622 | CM36BXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 203088166 | LUXAIRE | TH16B3622 | CF36BBCA1 | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205544315 | LUXAIRE | TH16B3622 | CF36BXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205544306 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 203088130 | LUXAIRE | TH16B3622 | CM36CBCA1 | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205544297 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205544287 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205544278 | LUXAIRE | TH16B3622 | CF42BXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205544257 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TL9E080C16UH11 | 22,400 | $1,120 |
| No | 205544246 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205544269 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TL9E080C16UH11 | 22,400 | $1,120 |
| No | 203087833 | LUXAIRE | TH16B3622 | CM48CBCA1 | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205544230 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 203087815 | LUXAIRE | TH16B3622 | CF48CBCA1 | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205544220 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 203087779 | LUXAIRE | TH16B3622 | CM48DBCA1 | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205544192 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205544180 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205544172 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205544156 | LUXAIRE | TH16B3622 | CM36AXA1+TXV | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 205544162 | LUXAIRE | TH16B3622 | CM36AXA1+TXV | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 205544152 | LUXAIRE | TH16B3622 | CF36AXA1+TXV | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 205544148 | LUXAIRE | TH16B3622 | CF36AXA1+TXV | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 206781238 | LUXAIRE | TH16B3622 | CU36BXA1+TXV | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 203430989 | LUXAIRE | TH16B3622 | CM36BBCA1 | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 206781242 | LUXAIRE | TH16B3622 | CM36BXA1+TXV | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 206781234 | LUXAIRE | TH16B3622 | CU36BXA1+TXV | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 203430984 | LUXAIRE | TH16B3622 | CF36BBCA1 | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 203087609 | LUXAIRE | TH16B3622 | CM36BBCA1 | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 206781230 | LUXAIRE | TH16B3622 | CM36BXA1+TXV | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 203087589 | LUXAIRE | TH16B3622 | CF36BBCA1 | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 206781226 | LUXAIRE | TH16B3622 | CF36BXA1+TXV | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 206781222 | LUXAIRE | TH16B3622 | CF36BXA1+TXV | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 205544144 | LUXAIRE | TH16B3622 | CF42BXA1+TXV | TMLE060A12MP11 | 22,800 | $1,140 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205544140 | LUXAIRE | TH16B3622 | CF42BXA1+TXV | TM8E060A12MP11 | 22,800 | $1,140 |
| No | 206781218 | LUXAIRE | TH16B3622 | CU36BXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 203430962 | LUXAIRE | TH16B3622 | CM36BBCA1 | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 206781214 | LUXAIRE | TH16B3622 | CM36BXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 203430956 | LUXAIRE | TH16B3622 | CF36BBCA1 | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 206781210 | LUXAIRE | TH16B3622 | CU36BXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 203087512 | LUXAIRE | TH16B3622 | CM36BBCA1 | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 206781206 | LUXAIRE | TH16B3622 | CM36BXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 203087495 | LUXAIRE | TH16B3622 | CF36BBCA1 | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 206781194 | LUXAIRE | TH16B3622 | CF36BXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 206781190 | LUXAIRE | TH16B3622 | CF36BXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 206781186 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 206781202 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203430890 | LUXAIRE | TH16B3622 | CM36CBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 206781198 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 203087269 | LUXAIRE | TH16B3622 | CM36CBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 206781182 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 206781178 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 206781174 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205544136 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203430879 | LUXAIRE | TH16B3622 | CM42CBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205544211 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203430874 | LUXAIRE | TH16B3622 | CF42CBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205544200 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 203087231 | LUXAIRE | TH16B3622 | CM42CBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205544132 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 203087211 | LUXAIRE | TH16B3622 | CF42CBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205544114 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205544099 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 206781170 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 206781166 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 206781162 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 206781158 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205544091 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203430857 | LUXAIRE | TH16B3622 | CM48CBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205544127 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203430851 | LUXAIRE | TH16B3622 | CF48CBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205544082 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203087150 | LUXAIRE | TH16B3622 | CM48CBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205544073 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205544061 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203087132 | LUXAIRE | TH16B3622 | CF48CBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205544051 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 206781154 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203430791 | LUXAIRE | TH16B3622 | CM42CBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 206781150 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203430785 | LUXAIRE | TH16B3622 | CF42CBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 206781146 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203086926 | LUXAIRE | TH16B3622 | CM42CBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 206781142 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203086909 | LUXAIRE | TH16B3622 | CF42CBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 206781138 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 206781134 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205544039 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203430774 | LUXAIRE | TH16B3622 | CM48CBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205544029 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203430769 | LUXAIRE | TH16B3622 | CF48CBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205544015 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203086871 | LUXAIRE | TH16B3622 | CM48CBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205544001 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203086850 | LUXAIRE | TH16B3622 | CF48CBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205543960 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205543943 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205543924 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205543988 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205543972 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203430758 | LUXAIRE | TH16B3622 | CM36CBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 203086808 | LUXAIRE | TH16B3622 | CM36CBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205543906 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205543892 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205543882 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205543872 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 203430747 | LUXAIRE | TH16B3622 | CM42CBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205543863 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 203430741 | LUXAIRE | TH16B3622 | CF42CBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205543850 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203086764 | LUXAIRE | TH16B3622 | CM42CBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205543839 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203086746 | LUXAIRE | TH16B3622 | CF42CBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205543817 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205543806 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 206781126 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206781118 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206781114 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781122 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781110 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 203430664 | LUXAIRE | TH16B3622 | CM48CBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206781130 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 203430658 | LUXAIRE | TH16B3622 | CF48CBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206781106 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 203098232 | LUXAIRE | TH16B3622 | CM48CBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781102 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 203098224 | LUXAIRE | TH16B3622 | CF48CBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781098 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206781094 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 203430647 | LUXAIRE | TH16B3622 | CM48DBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206781090 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206781086 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 203098208 | LUXAIRE | TH16B3622 | CM48DBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781082 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781078 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206781074 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206781070 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 205543788 | LUXAIRE | TH16B3622 | CM36AXA1+TXV | TPLC060A12MP13 | 22,400 | $1,120 |
| No | 205543778 | LUXAIRE | TH16B3622 | CM36AXA1+TXV | TMLV060A12MP12 | 22,400 | $1,120 |
| No | 205543770 | LUXAIRE | TH16B3622 | CM36AXA1+TXV | TM8V060A12MP12 | 22,400 | $1,120 |
| No | 205543752 | LUXAIRE | TH16B3622 | CF36AXA1+TXV | TPLC060A12MP13 | 22,400 | $1,120 |
| No | 205543740 | LUXAIRE | TH16B3622 | CF36AXA1+TXV | TMLV060A12MP12 | 22,400 | $1,120 |
| No | 205543729 | LUXAIRE | TH16B3622 | CF36AXA1+TXV | TM8V060A12MP12 | 22,400 | $1,120 |
| No | 205543718 | LUXAIRE | TH16B3622 | CM36AXA1+TXV | TM9E060A10MP12 | 22,600 | $1,130 |
| No | 205543708 | LUXAIRE | TH16B3622 | CF36AXA1+TXV | TM9E060A10MP12 | 22,600 | $1,130 |
| No | 206781066 | LUXAIRE | TH16B3622 | CF42BXA1+TXV | TM9E060B12MP12 | 22,200 | $1,110 |
| No | 205543697 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205543828 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203097862 | LUXAIRE | TH16B3622 | CM42CBCA1 | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 203097854 | LUXAIRE | TH16B3622 | CF42CBCA1 | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205543688 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 206781062 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 203097838 | LUXAIRE | TH16B3622 | CM48CBCA1 | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 206781058 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 203097830 | LUXAIRE | TH16B3622 | CF48CBCA1 | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 206781054 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205543677 | LUXAIRE | TH16B3622 | CU36BXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097814 | LUXAIRE | TH16B3622 | CM36BBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205543669 | LUXAIRE | TH16B3622 | CM36BXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097806 | LUXAIRE | TH16B3622 | CF36BBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205543657 | LUXAIRE | TH16B3622 | CF36BXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205543644 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 203097711 | LUXAIRE | TH16B3622 | CM36CBCA1 | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 205543618 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 205543602 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 206781050 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 203097695 | LUXAIRE | TH16B3622 | CM42CBCA1 | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 206781046 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 203097686 | LUXAIRE | TH16B3622 | CF42CBCA1 | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 206781042 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 205543593 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 205543585 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 206781038 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 203097663 | LUXAIRE | TH16B3622 | CM48CBCA1 | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 206781034 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 203097655 | LUXAIRE | TH16B3622 | CF48CBCA1 | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 206781030 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 203097551 | LUXAIRE | TH16B3622 | CM48DBCA1 | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205543577 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205543567 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205543557 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 206781026 | LUXAIRE | TH16B3622 | CF42BXA1+TXV | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 203097454 | LUXAIRE | TH16B3622 | AE36CX21+TXV | | 22,600 | $1,130 |
| No | 205543548 | LUXAIRE | TH16B3622 | CM42DXA1+ME14DN21+TXV | | 22,000 | $1,100 |
| No | 205543541 | LUXAIRE | TH16B3622 | CF42DXA1+ME14DN21+TXV | | 22,000 | $1,100 |
| No | 205543531 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205543512 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205543491 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TM9Y080C16MP11 | 22,600 | $1,130 |
| No | 203096960 | LUXAIRE | TH16B3622 | CM48CBCA1 | TM9Y080C16MP11 | 22,600 | $1,130 |
| No | 205543631 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TM9Y080C16MP11 | 22,600 | $1,130 |
| No | 203096944 | LUXAIRE | TH16B3622 | CF48CBCA1 | TM9Y080C16MP11 | 22,600 | $1,130 |
| No | 205543461 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TM9Y080C16MP11 | 22,600 | $1,130 |
| No | 203096913 | LUXAIRE | TH16B3622 | CM48DBCA1 | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205543427 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205543417 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205543390 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205543375 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TM9Y120D20MP11 | 22,400 | $1,120 |
| No | 205543359 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TM9Y120D20MP11 | 22,400 | $1,120 |
| No | 205543342 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | LPLC100C16MP13 | 22,200 | $1,110 |
| No | 205543335 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | LPLC080C16MP13 | 22,200 | $1,110 |
| No | 205543323 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205543316 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205543305 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205543282 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205543269 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205543256 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | LPLC080C16MP13 | 22,200 | $1,110 |
| No | 205543243 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205543262 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | LPLC100C16MP13 | 22,200 | $1,110 |
| No | 205543229 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205543217 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205543194 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205543183 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203096746 | LUXAIRE | TH16B3622 | AVC48CX21+TXV | | 22,400 | $1,120 |
| No | 203096698 | LUXAIRE | TH16B3622 | CM48DBCA1+ME14DN21 | | 22,000 | $1,100 |
| No | 205543166 | LUXAIRE | TH16B3622 | CM48DXA1+ME14DN21+TXV | | 22,000 | $1,100 |
| No | 205543158 | LUXAIRE | TH16B3622 | CF48DXA1+ME14DN21+TXV | | 22,000 | $1,100 |
| No | 203096666 | LUXAIRE | TH16B3622 | CM36CBCA1+MVC16CN21 | | 22,000 | $1,100 |
| No | 205543150 | LUXAIRE | TH16B3622 | CM36CXA1+MVC16CN21+TXV | | 22,000 | $1,100 |
| No | 205543141 | LUXAIRE | TH16B3622 | CF36CXA1+MVC16CN21+TXV | | 22,000 | $1,100 |
| No | 203096650 | LUXAIRE | TH16B3622 | CM42CBCA1+MVC16CN21 | | 21,800 | $1,090 |
| No | 205543133 | LUXAIRE | TH16B3622 | CM42CXA1+MVC16CN21+TXV | | 21,800 | $1,090 |
| No | 203096642 | LUXAIRE | TH16B3622 | CF42CBCA1+MVC16CN21 | | 21,800 | $1,090 |
| No | 205543121 | LUXAIRE | TH16B3622 | CF42CXA1+MVC16CN21+TXV | | 21,800 | $1,090 |
| No | 205543106 | LUXAIRE | TH16B3622 | CU36BXA1+TXV | TPLC060A12MP13 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203096539 | LUXAIRE | TH16B3622 | CM36BBCA1 | TPLC060A12MP13 | 22,200 | $1,110 |
| No | 205543087 | LUXAIRE | TH16B3622 | CM36BXA1+TXV | TPLC060A12MP13 | 22,200 | $1,110 |
| No | 203096511 | LUXAIRE | TH16B3622 | CF36BBCA1 | TPLC060A12MP13 | 22,200 | $1,110 |
| No | 205543077 | LUXAIRE | TH16B3622 | CU36BXA1+TXV | TMLV060A12MP12 | 22,200 | $1,110 |
| No | 205543066 | LUXAIRE | TH16B3622 | CM36BXA1+TXV | TMLV060A12MP12 | 22,200 | $1,110 |
| No | 203096531 | LUXAIRE | TH16B3622 | CM36BBCA1 | TMLV060A12MP12 | 22,200 | $1,110 |
| No | 203096502 | LUXAIRE | TH16B3622 | CF36BBCA1 | TMLV060A12MP12 | 22,200 | $1,110 |
| No | 205543051 | LUXAIRE | TH16B3622 | CU36BXA1+TXV | TM8V060A12MP12 | 22,200 | $1,110 |
| No | 205543038 | LUXAIRE | TH16B3622 | CM36BXA1+TXV | TM8V060A12MP12 | 22,200 | $1,110 |
| No | 203096494 | LUXAIRE | TH16B3622 | CF36BBCA1 | TM8V060A12MP12 | 22,200 | $1,110 |
| No | 203096523 | LUXAIRE | TH16B3622 | CM36BBCA1 | TM8V060A12MP12 | 22,200 | $1,110 |
| No | 205542999 | LUXAIRE | TH16B3622 | CF36BXA1+TXV | TPLC060A12MP13 | 22,200 | $1,110 |
| No | 205542988 | LUXAIRE | TH16B3622 | CF36BXA1+TXV | TMLV060A12MP12 | 22,200 | $1,110 |
| No | 205542977 | LUXAIRE | TH16B3622 | CF36BXA1+TXV | TM8V060A12MP12 | 22,200 | $1,110 |
| No | 203096159 | LUXAIRE | TH16B3622 | CM36BBCA1 | LP9C060B12MP13 | 22,400 | $1,120 |
| No | 206781022 | LUXAIRE | TH16B3622 | CM36BXA1+TXV | LP9C060B12MP13 | 22,400 | $1,120 |
| No | 206781024 | LUXAIRE | TH16B3622 | CU36BXA1+TXV | LP9C060B12MP13 | 22,400 | $1,120 |
| No | 203096139 | LUXAIRE | TH16B3622 | CF36BBCA1 | LP9C060B12MP13 | 22,400 | $1,120 |
| No | 206781018 | LUXAIRE | TH16B3622 | CU36BXA1+TXV | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 203096151 | LUXAIRE | TH16B3622 | CM36BBCA1 | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 206781014 | LUXAIRE | TH16B3622 | CM36BXA1+TXV | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 203096131 | LUXAIRE | TH16B3622 | CF36BBCA1 | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 206781010 | LUXAIRE | TH16B3622 | CU36BXA1+TXV | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 203096143 | LUXAIRE | TH16B3622 | CM36BBCA1 | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 206781006 | LUXAIRE | TH16B3622 | CM36BXA1+TXV | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 206781004 | LUXAIRE | TH16B3622 | CF36BXA1+TXV | LP9C060B12MP13 | 22,400 | $1,120 |
| No | 203096123 | LUXAIRE | TH16B3622 | CF36BBCA1 | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 206781000 | LUXAIRE | TH16B3622 | CF36BXA1+TXV | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 206780996 | LUXAIRE | TH16B3622 | CF36BXA1+TXV | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 205542971 | LUXAIRE | TH16B3622 | CF42BXA1+TXV | LP9C060B12MP13 | 22,400 | $1,120 |
| No | 205542960 | LUXAIRE | TH16B3622 | CF42BXA1+TXV | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 205542952 | LUXAIRE | TH16B3622 | CF42BXA1+TXV | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 203095805 | LUXAIRE | TH16B3622 | CM48DBCA1 | LP9C080C16MP13 | 22,000 | $1,100 |
| No | 205543100 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | LP9C080C16MP13 | 22,000 | $1,100 |
| No | 205543095 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | LP9C080C16MP13 | 22,000 | $1,100 |
| No | 203095797 | LUXAIRE | TH16B3622 | CM48DBCA1 | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 205543026 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 205543014 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203095789 | LUXAIRE | TH16B3622 | CM48DBCA1 | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 205542939 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 205542924 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 205542918 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | LP9C080C16MP13 | 22,000 | $1,100 |
| No | 205542894 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 205542905 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 203095761 | LUXAIRE | TH16B3622 | AVC36BX21+TXV | | 22,200 | $1,110 |
| No | 203095753 | LUXAIRE | TH16B3622 | AVC36CX21+TXV | | 22,200 | $1,110 |
| No | 203095738 | LUXAIRE | TH16B3622 | AVC48DX21+TXV | | 22,200 | $1,110 |
| No | 205542888 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | LPLC100C16MP13 | 22,200 | $1,110 |
| No | 203095343 | LUXAIRE | TH16B3622 | CM42CBCA1 | LPLC100C16MP13 | 22,200 | $1,110 |
| No | 205542881 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | LPLC100C16MP13 | 22,200 | $1,110 |
| No | 203095286 | LUXAIRE | TH16B3622 | CF42CBCA1 | LPLC100C16MP13 | 22,200 | $1,110 |
| No | 205542877 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | LPLC080C16MP13 | 22,200 | $1,110 |
| No | 203095339 | LUXAIRE | TH16B3622 | CM42CBCA1 | LPLC080C16MP13 | 22,200 | $1,110 |
| No | 205542872 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | LPLC080C16MP13 | 22,200 | $1,110 |
| No | 203095282 | LUXAIRE | TH16B3622 | CF42CBCA1 | LPLC080C16MP13 | 22,200 | $1,110 |
| No | 205542863 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203095331 | LUXAIRE | TH16B3622 | CM42CBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205542854 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203095274 | LUXAIRE | TH16B3622 | CF42CBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205542845 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 203095323 | LUXAIRE | TH16B3622 | CM42CBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205542836 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 203095267 | LUXAIRE | TH16B3622 | CF42CBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205542826 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205542817 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203095259 | LUXAIRE | TH16B3622 | CF42CBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203095314 | LUXAIRE | TH16B3622 | CM42CBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205542782 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203095298 | LUXAIRE | TH16B3622 | CM42CBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205542767 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203095243 | LUXAIRE | TH16B3622 | CF42CBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205542757 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203095290 | LUXAIRE | TH16B3622 | CM42CBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203095235 | LUXAIRE | TH16B3622 | CF42CBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205542736 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | LPLC080C16MP13 | 22,200 | $1,110 |
| No | 205542747 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205542726 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205542741 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | LPLC100C16MP13 | 22,200 | $1,110 |
| No | 205542713 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205542697 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205542668 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205542654 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 206780994 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | LPLC100C16MP13 | 22,200 | $1,110 |
| No | 206780992 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | LPLC100C16MP13 | 22,200 | $1,110 |
| No | 203095008 | LUXAIRE | TH16B3622 | CM48CBCA1 | LPLC100C16MP13 | 22,200 | $1,110 |
| No | 203094951 | LUXAIRE | TH16B3622 | CF48CBCA1 | LPLC100C16MP13 | 22,200 | $1,110 |
| No | 206780990 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | LPLC080C16MP13 | 22,200 | $1,110 |
| No | 203095003 | LUXAIRE | TH16B3622 | CM48CBCA1 | LPLC080C16MP13 | 22,200 | $1,110 |
| No | 206780988 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | LPLC080C16MP13 | 22,200 | $1,110 |
| No | 206780984 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203094947 | LUXAIRE | TH16B3622 | CF48CBCA1 | LPLC080C16MP13 | 22,200 | $1,110 |
| No | 203094995 | LUXAIRE | TH16B3622 | CM48CBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 206780980 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203094940 | LUXAIRE | TH16B3622 | CF48CBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 206780976 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 203094987 | LUXAIRE | TH16B3622 | CM48CBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 206780972 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 203094932 | LUXAIRE | TH16B3622 | CF48CBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 206780968 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203094979 | LUXAIRE | TH16B3622 | CM48CBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 206780964 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203094923 | LUXAIRE | TH16B3622 | CF48CBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 206780960 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203094963 | LUXAIRE | TH16B3622 | CM48CBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 206780956 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203094908 | LUXAIRE | TH16B3622 | CF48CBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 206780952 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203094955 | LUXAIRE | TH16B3622 | CM48CBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 206780948 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203094900 | LUXAIRE | TH16B3622 | CF48CBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 206780942 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | LPLC100C16MP13 | 22,200 | $1,110 |
| No | 206780940 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | LPLC080C16MP13 | 22,200 | $1,110 |
| No | 206780936 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 206780932 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780928 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 206780924 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 206780920 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203093773 | LUXAIRE | TH16B3622 | CM48CBCA1 | LPLC120C20MP13 | 22,200 | $1,110 |
| No | 206780946 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | LPLC120C20MP13 | 22,200 | $1,110 |
| No | 206780918 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | LPLC120C20MP13 | 22,200 | $1,110 |
| No | 203093716 | LUXAIRE | TH16B3622 | CF48CBCA1 | LPLC120C20MP13 | 22,200 | $1,110 |
| No | 206780944 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | LPLC100C20MP13 | 22,200 | $1,110 |
| No | 203093769 | LUXAIRE | TH16B3622 | CM48CBCA1 | LPLC100C20MP13 | 22,200 | $1,110 |
| No | 206780943 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | LPLC100C20MP13 | 22,200 | $1,110 |
| No | 203093713 | LUXAIRE | TH16B3622 | CF48CBCA1 | LPLC100C20MP13 | 22,200 | $1,110 |
| No | 206780914 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TPLC120C20MP13 | 22,200 | $1,110 |
| No | 203093761 | LUXAIRE | TH16B3622 | CM48CBCA1 | TPLC120C20MP13 | 22,200 | $1,110 |
| No | 206780910 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TPLC120C20MP13 | 22,200 | $1,110 |
| No | 203093705 | LUXAIRE | TH16B3622 | CF48CBCA1 | TPLC120C20MP13 | 22,200 | $1,110 |
| No | 206780906 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TPLC100C20MP13 | 22,200 | $1,110 |
| No | 203093753 | LUXAIRE | TH16B3622 | CM48CBCA1 | TPLC100C20MP13 | 22,200 | $1,110 |
| No | 206780902 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TPLC100C20MP13 | 22,200 | $1,110 |
| No | 203093696 | LUXAIRE | TH16B3622 | CF48CBCA1 | TPLC100C20MP13 | 22,200 | $1,110 |
| No | 206780898 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TMLV120C20MP12 | 22,200 | $1,110 |
| No | 203093745 | LUXAIRE | TH16B3622 | CM48CBCA1 | TMLV120C20MP12 | 22,200 | $1,110 |
| No | 206780894 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TMLV120C20MP12 | 22,200 | $1,110 |
| No | 203093688 | LUXAIRE | TH16B3622 | CF48CBCA1 | TMLV120C20MP12 | 22,200 | $1,110 |
| No | 206780890 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TM8V100C20MP12 | 22,200 | $1,110 |
| No | 203093729 | LUXAIRE | TH16B3622 | CM48CBCA1 | TM8V100C20MP12 | 22,200 | $1,110 |
| No | 206780886 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TM8V100C20MP12 | 22,200 | $1,110 |
| No | 203093672 | LUXAIRE | TH16B3622 | CF48CBCA1 | TM8V100C20MP12 | 22,200 | $1,110 |
| No | 206780882 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TM8V120C20MP12 | 22,200 | $1,110 |
| No | 203093720 | LUXAIRE | TH16B3622 | CM48CBCA1 | TM8V120C20MP12 | 22,200 | $1,110 |
| No | 206780878 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TM8V120C20MP12 | 22,200 | $1,110 |
| No | 203093664 | LUXAIRE | TH16B3622 | CF48CBCA1 | TM8V120C20MP12 | 22,200 | $1,110 |
| No | 206780876 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | LPLC120C20MP13 | 22,200 | $1,110 |
| No | 206780874 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | LPLC100C20MP13 | 22,200 | $1,110 |
| No | 206780871 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TPLC120C20MP13 | 22,200 | $1,110 |
| No | 206780867 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TPLC100C20MP13 | 22,200 | $1,110 |
| No | 206780863 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TMLV120C20MP12 | 22,200 | $1,110 |
| No | 206780859 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TM8V100C20MP12 | 22,200 | $1,110 |
| No | 206780855 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TM8V120C20MP12 | 22,200 | $1,110 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205542646 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | LPLC120C20MP13 | 22,400 | $1,120 |
| No | 203093392 | LUXAIRE | TH16B3622 | CM48DBCA1 | LPLC120C20MP13 | 22,400 | $1,120 |
| No | 205542638 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | LPLC120C20MP13 | 22,400 | $1,120 |
| No | 205542631 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | LPLC100C20MP13 | 22,400 | $1,120 |
| No | 203093383 | LUXAIRE | TH16B3622 | CM48DBCA1 | LPLC100C20MP13 | 22,400 | $1,120 |
| No | 205542621 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | LPLC100C20MP13 | 22,400 | $1,120 |
| No | 203093365 | LUXAIRE | TH16B3622 | CM48DBCA1 | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205542608 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205542590 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 203093346 | LUXAIRE | TH16B3622 | CM48DBCA1 | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205542576 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205542561 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205542547 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205542532 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 203093327 | LUXAIRE | TH16B3622 | CM48DBCA1 | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 203093291 | LUXAIRE | TH16B3622 | CM48DBCA1 | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205542495 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205542484 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 203093273 | LUXAIRE | TH16B3622 | CM48DBCA1 | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205542297 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205542285 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205542279 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | LPLC120C20MP13 | 22,400 | $1,120 |
| No | 205542259 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205542247 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205542272 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | LPLC100C20MP13 | 22,400 | $1,120 |
| No | 205542235 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205542217 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205542212 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205542199 | LUXAIRE | TH16B3622 | CM36AXA1+TXV | TM8Y060A12MP11 | 22,200 | $1,110 |
| No | 205542163 | LUXAIRE | TH16B3622 | CF36AXA1+TXV | TM8Y060A12MP11 | 22,200 | $1,110 |
| No | 205542129 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 203092893 | LUXAIRE | TH16B3622 | CM36CBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205542475 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205542452 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205542464 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203092876 | LUXAIRE | TH16B3622 | CM36CBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205542112 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205542105 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205542056 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 203092222 | LUXAIRE | TH16B3622 | CM48CBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205542310 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 203092116 | LUXAIRE | TH16B3622 | CF48CBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205542046 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203092203 | LUXAIRE | TH16B3622 | CM48CBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205542034 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203092099 | LUXAIRE | TH16B3622 | CF48CBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205541946 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205541935 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203091906 | LUXAIRE | TH16B3622 | CM48DBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205541879 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205541867 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 203091887 | LUXAIRE | TH16B3622 | CM48DBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205541856 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205541844 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205541673 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 206780847 | LUXAIRE | TH16B3622 | CU36BXA1+TXV | TM9Y080B12MP11 | 22,200 | $1,110 |
| No | 203808679 | LUXAIRE | TH16B3622 | CM36BBCA1 | TM9Y080B12MP11 | 22,200 | $1,110 |
| No | 205541662 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 206780851 | LUXAIRE | TH16B3622 | CM36BXA1+TXV | TM9Y080B12MP11 | 22,200 | $1,110 |
| No | 203808672 | LUXAIRE | TH16B3622 | CF36BBCA1 | TM9Y080B12MP11 | 22,200 | $1,110 |
| No | 206780843 | LUXAIRE | TH16B3622 | CF36BXA1+TXV | TM9Y080B12MP11 | 22,200 | $1,110 |
| No | 205541604 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205541593 | LUXAIRE | TH16B3622 | CM42CBCA1 | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205541582 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205541569 | LUXAIRE | TH16B3622 | CF42CBCA1 | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205541758 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205541739 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205541719 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 206780807 | LUXAIRE | TH16B3622 | CU36BXA1+TXV | LP9C080B12MP13 | 22,200 | $1,110 |
| No | 203091050 | LUXAIRE | TH16B3622 | CM36BBCA1 | LP9C080B12MP13 | 22,200 | $1,110 |
| No | 206780841 | LUXAIRE | TH16B3622 | CM36BXA1+TXV | LP9C080B12MP13 | 22,200 | $1,110 |
| No | 203091003 | LUXAIRE | TH16B3622 | CF36BBCA1 | LP9C080B12MP13 | 22,200 | $1,110 |
| No | 206780837 | LUXAIRE | TH16B3622 | CU36BXA1+TXV | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 203091031 | LUXAIRE | TH16B3622 | CM36BBCA1 | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 206780803 | LUXAIRE | TH16B3622 | CM36BXA1+TXV | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 206780799 | LUXAIRE | TH16B3622 | CU36BXA1+TXV | TM9V080B12MP12 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203091011 | LUXAIRE | TH16B3622 | CM36BBCA1 | TM9V080B12MP12 | 22,200 | $1,110 |
| No | 203090983 | LUXAIRE | TH16B3622 | CF36BBCA1 | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 206780795 | LUXAIRE | TH16B3622 | CM36BXA1+TXV | TM9V080B12MP12 | 22,200 | $1,110 |
| No | 203090967 | LUXAIRE | TH16B3622 | CF36BBCA1 | TM9V080B12MP12 | 22,200 | $1,110 |
| No | 206780793 | LUXAIRE | TH16B3622 | CF36BXA1+TXV | LP9C080B12MP13 | 22,200 | $1,110 |
| No | 206780789 | LUXAIRE | TH16B3622 | CF36BXA1+TXV | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 206780785 | LUXAIRE | TH16B3622 | CF36BXA1+TXV | TM9V080B12MP12 | 22,200 | $1,110 |
| No | 205541705 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | LP9C100C16MP13 | 22,000 | $1,100 |
| No | 205541553 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | LP9C100C16MP13 | 22,000 | $1,100 |
| No | 205541542 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TP9C100C16MP13 | 22,000 | $1,100 |
| No | 203090640 | LUXAIRE | TH16B3622 | CM36CBCA1 | LP9C100C16MP13 | 22,000 | $1,100 |
| No | 203090621 | LUXAIRE | TH16B3622 | CM36CBCA1 | TP9C100C16MP13 | 22,000 | $1,100 |
| No | 205541529 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TP9C100C16MP13 | 22,000 | $1,100 |
| No | 205541518 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TM9V100C16MP12 | 22,000 | $1,100 |
| No | 203090606 | LUXAIRE | TH16B3622 | CM36CBCA1 | TM9V100C16MP12 | 22,000 | $1,100 |
| No | 205541508 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TM9V100C16MP12 | 22,000 | $1,100 |
| No | 205541502 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | LP9C100C16MP13 | 22,000 | $1,100 |
| No | 205541489 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TP9C100C16MP13 | 22,000 | $1,100 |
| No | 205541478 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TM9V100C16MP12 | 22,000 | $1,100 |
| No | 205541470 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | LP9C100C16MP13 | 21,800 | $1,090 |
| No | 203090413 | LUXAIRE | TH16B3622 | CM42CBCA1 | LP9C100C16MP13 | 21,800 | $1,090 |
| No | 205541465 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | LP9C100C16MP13 | 21,800 | $1,090 |
| No | 203090370 | LUXAIRE | TH16B3622 | CF42CBCA1 | LP9C100C16MP13 | 21,800 | $1,090 |
| No | 205541453 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 203090396 | LUXAIRE | TH16B3622 | CM42CBCA1 | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205541441 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 203090351 | LUXAIRE | TH16B3622 | CF42CBCA1 | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205541429 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 203090377 | LUXAIRE | TH16B3622 | CM42CBCA1 | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205541418 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 203090332 | LUXAIRE | TH16B3622 | CF42CBCA1 | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205541412 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | LP9C100C16MP13 | 21,800 | $1,090 |
| No | 205541401 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205541383 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | LP9C100C16MP13 | 21,800 | $1,090 |
| No | 205541388 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205541371 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205541359 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205541354 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | LP9C100C16MP13 | 21,800 | $1,090 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205541343 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205541328 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | LP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541332 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205541318 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541304 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205541295 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | LP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541286 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541274 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205541269 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | LP9C100C20MP13 | 22,400 | $1,120 |
| No | 203089092 | LUXAIRE | TH16B3622 | CM48CBCA1 | LP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541264 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | LP9C100C20MP13 | 22,400 | $1,120 |
| No | 203089044 | LUXAIRE | TH16B3622 | CF48CBCA1 | LP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541253 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 203089073 | LUXAIRE | TH16B3622 | CM48CBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541243 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 203089026 | LUXAIRE | TH16B3622 | CF48CBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541232 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203089054 | LUXAIRE | TH16B3622 | CM48CBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205541221 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203089009 | LUXAIRE | TH16B3622 | CF48CBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205541216 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | LP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541204 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541194 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203088862 | LUXAIRE | TH16B3622 | CM48DBCA1 | LP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541180 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | LP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541187 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | LP9C100C20MP13 | 22,400 | $1,120 |
| No | 203088843 | LUXAIRE | TH16B3622 | CM48DBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541166 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 203088822 | LUXAIRE | TH16B3622 | CM48DBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205541128 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205541153 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541114 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205541108 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | LP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541095 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205541078 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205144647 | LUXAIRE | TH16B3622 | AE42CBC21 | | 22,400 | $1,120 |
| No | 203088402 | LUXAIRE | TH16B3622 | AE42CX21+TXV | | 22,400 | $1,120 |
| No | 205537137 | LUXAIRE | TH16B2421 | CU24AXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205537129 | LUXAIRE | TH16B2421 | CM24ABAA1 | TL8E060A12UH11 | 15,200 | $760 |
| No | 205537121 | LUXAIRE | TH16B2421 | CM24AXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |
| No | 205537107 | LUXAIRE | TH16B2421 | CF24AXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |
| No | 206782444 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 205537114 | LUXAIRE | TH16B2421 | CF24ABAA1 | TL8E060A12UH11 | 15,200 | $760 |
| No | 206782440 | LUXAIRE | TH16B4821 | CM48CBCA1 | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 206782436 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 206782432 | LUXAIRE | TH16B4821 | CF48CBCA1 | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 206782428 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 205085346 | LUXAIRE | TH16B4821 | CU60CXA2+TXV | TL8E080C16UH11 | 27,800 | $1,390 |
| No | 205085340 | LUXAIRE | TH16B4821 | CM60CXA2+TXV | TL8E080C16UH11 | 27,800 | $1,390 |
| No | 205085333 | LUXAIRE | TH16B4821 | CF60CXA2+TXV | TL8E080C16UH11 | 27,800 | $1,390 |
| No | 206782472 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TL8E080C16UH11 | 29,600 | $1,480 |
| No | 206782468 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TL8E080C16UH11 | 29,600 | $1,480 |
| No | 205085311 | LUXAIRE | TH16B4821 | CU60CXA2+TXV | TL8E100C20UH11 | 27,600 | $1,380 |
| No | 205085305 | LUXAIRE | TH16B4821 | CM60CXA2+TXV | TL8E100C20UH11 | 27,600 | $1,380 |
| No | 205085299 | LUXAIRE | TH16B4821 | CF60CXA2+TXV | TL8E100C20UH11 | 27,600 | $1,380 |
| No | 205085293 | LUXAIRE | TH16B4821 | CU60DXA2+TXV | TL8E100C20UH11 | 27,800 | $1,390 |
| No | 205085286 | LUXAIRE | TH16B4821 | CM60DXA2+TXV | TL8E100C20UH11 | 27,800 | $1,390 |
| No | 205085281 | LUXAIRE | TH16B4821 | CF60DXA2+TXV | TL8E100C20UH11 | 27,800 | $1,390 |
| No | 205537098 | LUXAIRE | TH16B4821 | CM48DBCA1 | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205537089 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205537080 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205537072 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205537062 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TL9E080C16UH11 | 29,600 | $1,480 |
| No | 205537054 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TL9E080C16UH11 | 29,600 | $1,480 |
| No | 205085244 | LUXAIRE | TH16B4821 | CU60CXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205085239 | LUXAIRE | TH16B4821 | CM60CXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205085233 | LUXAIRE | TH16B4821 | CF60CXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205085228 | LUXAIRE | TH16B4821 | CU60DXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205085222 | LUXAIRE | TH16B4821 | CM60DXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205085216 | LUXAIRE | TH16B4821 | CF60DXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205085146 | LUXAIRE | TH16B4821 | CU60CXA2+TXV | TMLE080C20MP11 | 27,400 | $1,370 |
| No | 205085139 | LUXAIRE | TH16B4821 | CM60CXA2+TXV | TMLE080C20MP11 | 27,400 | $1,370 |
| No | 205085134 | LUXAIRE | TH16B4821 | CU60CXA2+TXV | TM8E080C20MP11 | 27,400 | $1,370 |
| No | 205085128 | LUXAIRE | TH16B4821 | CM60CXA2+TXV | TM8E080C20MP11 | 27,400 | $1,370 |
| No | 205085123 | LUXAIRE | TH16B4821 | CF60CXA2+TXV | TMLE080C20MP11 | 27,400 | $1,370 |
| No | 205085117 | LUXAIRE | TH16B4821 | CF60CXA2+TXV | TM8E080C20MP11 | 27,400 | $1,370 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205085112 | LUXAIRE | TH16B4821 | CU60DXA2+TXV | TMLE080C20MP11 | 27,600 | $1,380 |
| No | 205085107 | LUXAIRE | TH16B4821 | CM60DXA2+TXV | TMLE080C20MP11 | 27,600 | $1,380 |
| No | 205085096 | LUXAIRE | TH16B4821 | CM60DXA2+TXV | TM8E080C20MP11 | 27,600 | $1,380 |
| No | 205085090 | LUXAIRE | TH16B4821 | CF60DXA2+TXV | TMLE080C20MP11 | 27,600 | $1,380 |
| No | 205085101 | LUXAIRE | TH16B4821 | CU60DXA2+TXV | TM8E080C20MP11 | 27,600 | $1,380 |
| No | 205085084 | LUXAIRE | TH16B4821 | CF60DXA2+TXV | TM8E080C20MP11 | 27,600 | $1,380 |
| No | 206782424 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 203431138 | LUXAIRE | TH16B4821 | CM48CBCA1 | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 203431127 | LUXAIRE | TH16B4821 | CF48CBCA1 | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 206782420 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 206782416 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 203431132 | LUXAIRE | TH16B4821 | CM48CBCA1 | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 206782412 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 203431121 | LUXAIRE | TH16B4821 | CF48CBCA1 | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 206782408 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 206782404 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 205084914 | LUXAIRE | TH16B4821 | CU60DXA2+TXV | TMLE120C16MP11 | 27,800 | $1,390 |
| No | 205084908 | LUXAIRE | TH16B4821 | CM60DXA2+TXV | TMLE120C16MP11 | 27,800 | $1,390 |
| No | 205084903 | LUXAIRE | TH16B4821 | CU60DXA2+TXV | TM8E120C16MP11 | 27,800 | $1,390 |
| No | 205084897 | LUXAIRE | TH16B4821 | CM60DXA2+TXV | TM8E120C16MP11 | 27,800 | $1,390 |
| No | 205084892 | LUXAIRE | TH16B4821 | CF60DXA2+TXV | TMLE120C16MP11 | 27,800 | $1,390 |
| No | 205084887 | LUXAIRE | TH16B4821 | CF60DXA2+TXV | TM8E120C16MP11 | 27,800 | $1,390 |
| No | 206782400 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TMLE120C16MP11 | 30,400 | $1,520 |
| No | 206782396 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TM8E120C16MP11 | 30,400 | $1,520 |
| No | 206782392 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TMLE120C16MP11 | 30,400 | $1,520 |
| No | 206782388 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TM8E120C16MP11 | 30,400 | $1,520 |
| No | 205084812 | LUXAIRE | TH16B4821 | CU60DXA2+TXV | TMLE130D20MP11 | 27,800 | $1,390 |
| No | 205084807 | LUXAIRE | TH16B4821 | CM60DXA2+TXV | TMLE130D20MP11 | 27,800 | $1,390 |
| No | 205084801 | LUXAIRE | TH16B4821 | CU60DXA2+TXV | TM8E130D20MP11 | 27,800 | $1,390 |
| No | 205084795 | LUXAIRE | TH16B4821 | CM60DXA2+TXV | TM8E130D20MP11 | 27,800 | $1,390 |
| No | 205084789 | LUXAIRE | TH16B4821 | CF60DXA2+TXV | TMLE130D20MP11 | 27,800 | $1,390 |
| No | 205084783 | LUXAIRE | TH16B4821 | CF60DXA2+TXV | TM8E130D20MP11 | 27,800 | $1,390 |
| No | 205536886 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TM9E080B12MP12 | 28,600 | $1,430 |
| No | 205536878 | LUXAIRE | TH16B4821 | CM48CBCA1 | TM9E080B12MP12 | 28,600 | $1,430 |
| No | 205536870 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TM9E080B12MP12 | 28,600 | $1,430 |
| No | 205536862 | LUXAIRE | TH16B4821 | CF48CBCA1 | TM9E080B12MP12 | 28,600 | $1,430 |
| No | 205536852 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TM9E080B12MP12 | 28,600 | $1,430 |
| No | 206782384 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782380 | LUXAIRE | TH16B4821 | CM48CBCA1 | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 206782376 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 206782372 | LUXAIRE | TH16B4821 | CF48CBCA1 | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 206782368 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 205536840 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TM9E080C16MP12 | 28,800 | $1,440 |
| No | 205536833 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TM9E080C16MP12 | 28,800 | $1,440 |
| No | 205536825 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205536817 | LUXAIRE | TH16B4821 | CM48CBCA1 | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205536810 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205536800 | LUXAIRE | TH16B4821 | CF48CBCA1 | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205536791 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205084670 | LUXAIRE | TH16B4821 | CM60DXA2+TXV | TM9E100C20MP12 | 27,400 | $1,370 |
| No | 205084674 | LUXAIRE | TH16B4821 | CU60DXA2+TXV | TM9E100C20MP12 | 27,400 | $1,370 |
| No | 205084665 | LUXAIRE | TH16B4821 | CF60DXA2+TXV | TM9E100C20MP12 | 27,400 | $1,370 |
| No | 205084661 | LUXAIRE | TH16B4821 | CU60DXA2+TXV | TM9E120D20MP12 | 27,800 | $1,390 |
| No | 205084657 | LUXAIRE | TH16B4821 | CM60DXA2+TXV | TM9E120D20MP12 | 27,800 | $1,390 |
| No | 205084652 | LUXAIRE | TH16B4821 | CF60DXA2+TXV | TM9E120D20MP12 | 27,800 | $1,390 |
| No | 206783055 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TL8E080C16UH11 | 33,000 | $1,650 |
| No | 206783051 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TL8E080C16UH11 | 33,000 | $1,650 |
| No | 205536783 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TL9E080C16UH11 | 32,600 | $1,630 |
| No | 205536773 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TL9E080C16UH11 | 32,600 | $1,630 |
| No | 206783043 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TMLE080C16MP11 | 33,000 | $1,650 |
| No | 206783039 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TM8E080C16MP11 | 33,000 | $1,650 |
| No | 206783035 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TMLE080C16MP11 | 33,000 | $1,650 |
| No | 206783031 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TM8E080C16MP11 | 33,000 | $1,650 |
| No | 206783027 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TMLE100C16MP11 | 33,000 | $1,650 |
| No | 206783023 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TM8E100C16MP11 | 33,000 | $1,650 |
| No | 206783019 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TMLE100C16MP11 | 33,000 | $1,650 |
| No | 206783015 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TM8E100C16MP11 | 33,000 | $1,650 |
| No | 206783011 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TMLE100C20MP11 | 32,600 | $1,630 |
| No | 206783007 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TM8E100C20MP11 | 32,600 | $1,630 |
| No | 206783003 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TMLE100C20MP11 | 32,600 | $1,630 |
| No | 206782999 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TM8E100C20MP11 | 32,600 | $1,630 |
| No | 206782979 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TMLE120C20MP11 | 32,600 | $1,630 |
| No | 206782975 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TM8E120C20MP11 | 32,600 | $1,630 |
| No | 206782971 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TMLE120C20MP11 | 32,600 | $1,630 |
| No | 206782967 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TM8E120C20MP11 | 32,600 | $1,630 |
| No | 205536764 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TMLE130D20MP11 | 32,800 | $1,640 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205536756 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TM8E130D20MP11 | 32,800 | $1,640 |
| No | 205536748 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TMLE130D20MP11 | 32,800 | $1,640 |
| No | 205536739 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TM8E130D20MP11 | 32,800 | $1,640 |
| No | 206779794 | LUXAIRE | TH16B2421 | CM24BBAA1+MVC12BN21 | | 14,900 | $745 |
| No | 206779790 | LUXAIRE | TH16B2421 | CM24BXA1+MVC12BN21+TXV | | 14,900 | $745 |
| No | 202101789 | LUXAIRE | TH16B2421 | CF24BBAA1+MVC12BN21 | | 14,900 | $745 |
| No | 206779786 | LUXAIRE | TH16B2421 | CF24BXA1+MVC12BN21+TXV | | 14,900 | $745 |
| No | 206780120 | LUXAIRE | TH16B2421 | CM30BBAA1+MVC12BN21 | | 15,300 | $765 |
| No | 206780116 | LUXAIRE | TH16B2421 | CM30BXA1+MVC12BN21+TXV | | 15,300 | $765 |
| No | 206780112 | LUXAIRE | TH16B2421 | CF30BBAA1+MVC12BN21 | | 15,300 | $765 |
| No | 206780108 | LUXAIRE | TH16B2421 | CF30BXA1+MVC12BN21+TXV | | 15,300 | $765 |
| No | 206779802 | LUXAIRE | TH16B2421 | CM30CXA1+MVC16CN21+TXV | | 14,800 | $740 |
| No | 206779798 | LUXAIRE | TH16B2421 | CF30CXA1+MVC16CN21+TXV | | 14,800 | $740 |
| No | 206780088 | LUXAIRE | TH16B2421 | CM36CXA1+MVC16CN21+TXV | | 15,300 | $765 |
| No | 206780084 | LUXAIRE | TH16B2421 | CF36CXA1+MVC16CN21+TXV | | 15,300 | $765 |
| No | 206779754 | LUXAIRE | TH16B2421 | CU24AXA1+TXV | TPLC060A12MP13 | 15,000 | $750 |
| No | 206779750 | LUXAIRE | TH16B2421 | CM24ABAA1 | TPLC060A12MP13 | 15,000 | $750 |
| No | 206779746 | LUXAIRE | TH16B2421 | CM24AXA1+TXV | TPLC060A12MP13 | 15,000 | $750 |
| No | 202102013 | LUXAIRE | TH16B2421 | CF24ABAA1 | TPLC060A12MP13 | 15,000 | $750 |
| No | 206779766 | LUXAIRE | TH16B2421 | CU24AXA1+TXV | TMLV060A12MP12 | 15,000 | $750 |
| No | 206779762 | LUXAIRE | TH16B2421 | CM24ABAA1 | TMLV060A12MP12 | 15,000 | $750 |
| No | 206779758 | LUXAIRE | TH16B2421 | CM24AXA1+TXV | TMLV060A12MP12 | 15,000 | $750 |
| No | 202102007 | LUXAIRE | TH16B2421 | CF24ABAA1 | TMLV060A12MP12 | 15,000 | $750 |
| No | 206779742 | LUXAIRE | TH16B2421 | CU24AXA1+TXV | TM8V060A12MP12 | 15,000 | $750 |
| No | 206779738 | LUXAIRE | TH16B2421 | CM24ABAA1 | TM8V060A12MP12 | 15,000 | $750 |
| No | 206779734 | LUXAIRE | TH16B2421 | CM24AXA1+TXV | TM8V060A12MP12 | 15,000 | $750 |
| No | 206779730 | LUXAIRE | TH16B2421 | CF24AXA1+TXV | TPLC060A12MP13 | 15,000 | $750 |
| No | 202102002 | LUXAIRE | TH16B2421 | CF24ABAA1 | TM8V060A12MP12 | 15,000 | $750 |
| No | 206779726 | LUXAIRE | TH16B2421 | CF24AXA1+TXV | TMLV060A12MP12 | 15,000 | $750 |
| No | 206779722 | LUXAIRE | TH16B2421 | CF24AXA1+TXV | TM8V060A12MP12 | 15,000 | $750 |
| No | 206780647 | LUXAIRE | TH16B2421 | CM30BBAA1 | LPLC080B12MP13 | 15,000 | $750 |
| No | 206780648 | LUXAIRE | TH16B2421 | CU30BXA1+TXV | LPLC080B12MP13 | 15,000 | $750 |
| No | 206780646 | LUXAIRE | TH16B2421 | CM30BXA1+TXV | LPLC080B12MP13 | 15,000 | $750 |
| No | 206780645 | LUXAIRE | TH16B2421 | CF30BBAA1 | LPLC080B12MP13 | 15,000 | $750 |
| No | 206780642 | LUXAIRE | TH16B2421 | CU30BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780638 | LUXAIRE | TH16B2421 | CM30BBAA1 | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780634 | LUXAIRE | TH16B2421 | CM30BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780630 | LUXAIRE | TH16B2421 | CF30BBAA1 | TPLC080B12MP13 | 15,000 | $750 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780626 | LUXAIRE | TH16B2421 | CU30BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780622 | LUXAIRE | TH16B2421 | CM30BBAA1 | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780618 | LUXAIRE | TH16B2421 | CM30BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780614 | LUXAIRE | TH16B2421 | CF30BBAA1 | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780609 | LUXAIRE | TH16B2421 | CF30BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780612 | LUXAIRE | TH16B2421 | CF30BXA1+TXV | LPLC080B12MP13 | 15,000 | $750 |
| No | 206780605 | LUXAIRE | TH16B2421 | CF30BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780168 | LUXAIRE | TH16B2421 | CU24BXA1+TXV | TM9Y060B12MP11 | 14,900 | $745 |
| No | 206780164 | LUXAIRE | TH16B2421 | CM24BBAA1 | TM9Y060B12MP11 | 14,900 | $745 |
| No | 206780160 | LUXAIRE | TH16B2421 | CM24BXA1+TXV | TM9Y060B12MP11 | 14,900 | $745 |
| No | 202143774 | LUXAIRE | TH16B2421 | CF24BBAA1 | TM9Y060B12MP11 | 14,900 | $745 |
| No | 206780176 | LUXAIRE | TH16B2421 | CF24BXA1+TXV | TM9Y060B12MP11 | 14,900 | $745 |
| No | 206780152 | LUXAIRE | TH16B2421 | CM24ABAA1 | TM9V040A10MP12 | 15,200 | $760 |
| No | 206780156 | LUXAIRE | TH16B2421 | CU24AXA1+TXV | TM9V040A10MP12 | 15,200 | $760 |
| No | 206780148 | LUXAIRE | TH16B2421 | CM24AXA1+TXV | TM9V040A10MP12 | 15,200 | $760 |
| No | 202143766 | LUXAIRE | TH16B2421 | CF24ABAA1 | TM9V040A10MP12 | 15,200 | $760 |
| No | 206780172 | LUXAIRE | TH16B2421 | CF24AXA1+TXV | TM9V040A10MP12 | 15,200 | $760 |
| No | 206779990 | LUXAIRE | TH16B2421 | CM36BBAA1 | LP9C060B12MP13 | 14,900 | $745 |
| No | 206779992 | LUXAIRE | TH16B2421 | CU36BXA1+TXV | LP9C060B12MP13 | 14,900 | $745 |
| No | 206779988 | LUXAIRE | TH16B2421 | CM36BXA1+TXV | LP9C060B12MP13 | 14,900 | $745 |
| No | 206779986 | LUXAIRE | TH16B2421 | CF36BBAA1 | LP9C060B12MP13 | 14,900 | $745 |
| No | 206779982 | LUXAIRE | TH16B2421 | CU36BXA1+TXV | TP9C060B12MP13 | 14,900 | $745 |
| No | 206779978 | LUXAIRE | TH16B2421 | CM36BBAA1 | TP9C060B12MP13 | 14,900 | $745 |
| No | 206779974 | LUXAIRE | TH16B2421 | CM36BXA1+TXV | TP9C060B12MP13 | 14,900 | $745 |
| No | 206779970 | LUXAIRE | TH16B2421 | CF36BBAA1 | TP9C060B12MP13 | 14,900 | $745 |
| No | 206779952 | LUXAIRE | TH16B2421 | CF36BXA1+TXV | LP9C060B12MP13 | 14,900 | $745 |
| No | 206779944 | LUXAIRE | TH16B2421 | CF36BXA1+TXV | TM9V060B12MP12 | 14,900 | $745 |
| No | 206779958 | LUXAIRE | TH16B2421 | CM36BXA1+TXV | TM9V060B12MP12 | 14,900 | $745 |
| No | 206782624 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | LP9C100C20MP13 | 33,000 | $1,650 |
| No | 206779962 | LUXAIRE | TH16B2421 | CM36BBAA1 | TM9V060B12MP12 | 14,900 | $745 |
| No | 206779966 | LUXAIRE | TH16B2421 | CU36BXA1+TXV | TM9V060B12MP12 | 14,900 | $745 |
| No | 206779948 | LUXAIRE | TH16B2421 | CF36BXA1+TXV | TP9C060B12MP13 | 14,900 | $745 |
| No | 206779954 | LUXAIRE | TH16B2421 | CF36BBAA1 | TM9V060B12MP12 | 14,900 | $745 |
| No | 206782620 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TP9C100C20MP13 | 33,000 | $1,650 |
| No | 206782614 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | LP9C100C20MP13 | 33,000 | $1,650 |
| No | 206782610 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TP9C100C20MP13 | 33,000 | $1,650 |
| No | 206782606 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TM9V100C20MP12 | 33,000 | $1,650 |
| No | 205539559 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | LP9C120D20MP13 | 32,600 | $1,630 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782616 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TM9V100C20MP12 | 33,000 | $1,650 |
| No | 205539546 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TM9V120D20MP12 | 32,600 | $1,630 |
| No | 205539552 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TP9C120D20MP13 | 32,600 | $1,630 |
| No | 205539534 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TP9C120D20MP13 | 32,600 | $1,630 |
| No | 205539525 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TM9V120D20MP12 | 32,600 | $1,630 |
| No | 9036350 | LUXAIRE | TH16B4821 | AVC48CX21+TXV | | 27,600 | $1,380 |
| No | 205539542 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | LP9C120D20MP13 | 32,600 | $1,630 |
| No | 206781530 | LUXAIRE | TH16B4821 | CM48CBCA1+MVC16CN21 | | 28,000 | $1,400 |
| No | 206781526 | LUXAIRE | TH16B4821 | CM48CXA1+MVC16CN21+TXV | | 28,000 | $1,400 |
| No | 202100053 | LUXAIRE | TH16B4821 | CF48CBCA1+MVC16CN21 | | 28,000 | $1,400 |
| No | 206781772 | LUXAIRE | TH16B4821 | CF48CXA1+MVC16CN21+TXV | | 28,000 | $1,400 |
| No | 206782366 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | LPLC080B12MP13 | 28,200 | $1,410 |
| No | 206782365 | LUXAIRE | TH16B4821 | CM48CBCA1 | LPLC080B12MP13 | 28,200 | $1,410 |
| No | 206782364 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | LPLC080B12MP13 | 28,200 | $1,410 |
| No | 206782361 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TPLC080B12MP13 | 28,200 | $1,410 |
| No | 206782357 | LUXAIRE | TH16B4821 | CM48CBCA1 | TPLC080B12MP13 | 28,200 | $1,410 |
| No | 202100765 | LUXAIRE | TH16B4821 | CF48CBCA1 | LPLC080B12MP13 | 28,200 | $1,410 |
| No | 206782353 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TPLC080B12MP13 | 28,200 | $1,410 |
| No | 202100735 | LUXAIRE | TH16B4821 | CF48CBCA1 | TPLC080B12MP13 | 28,200 | $1,410 |
| No | 206782345 | LUXAIRE | TH16B4821 | CM48CBCA1 | TM8V080B12MP12 | 28,200 | $1,410 |
| No | 206782349 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TM8V080B12MP12 | 28,200 | $1,410 |
| No | 206782341 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TM8V080B12MP12 | 28,200 | $1,410 |
| No | 202100655 | LUXAIRE | TH16B4821 | CF48CBCA1 | TM8V080B12MP12 | 28,200 | $1,410 |
| No | 206782339 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | LPLC080B12MP13 | 28,200 | $1,410 |
| No | 206782336 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TPLC080B12MP13 | 28,200 | $1,410 |
| No | 206782332 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TM8V080B12MP12 | 28,200 | $1,410 |
| No | 206782330 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | LPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782328 | LUXAIRE | TH16B4821 | CM48CBCA1 | LPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782326 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | LPLC100C16MP13 | 28,000 | $1,400 |
| No | 202100769 | LUXAIRE | TH16B4821 | CF48CBCA1 | LPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782324 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | LPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782322 | LUXAIRE | TH16B4821 | CM48CBCA1 | LPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782320 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | LPLC080C16MP13 | 28,000 | $1,400 |
| No | 202100766 | LUXAIRE | TH16B4821 | CF48CBCA1 | LPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782316 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782312 | LUXAIRE | TH16B4821 | CM48CBCA1 | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782308 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 202100743 | LUXAIRE | TH16B4821 | CF48CBCA1 | TPLC100C16MP13 | 28,000 | $1,400 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782304 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782300 | LUXAIRE | TH16B4821 | CM48CBCA1 | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782296 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 202100740 | LUXAIRE | TH16B4821 | CF48CBCA1 | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782292 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782284 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782288 | LUXAIRE | TH16B4821 | CM48CBCA1 | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 202100703 | LUXAIRE | TH16B4821 | CF48CBCA1 | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782280 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 202100660 | LUXAIRE | TH16B4821 | CF48CBCA1 | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782276 | LUXAIRE | TH16B4821 | CM48CBCA1 | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782268 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782272 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782264 | LUXAIRE | TH16B4821 | CM48CBCA1 | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782260 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 202100663 | LUXAIRE | TH16B4821 | CF48CBCA1 | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782172 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | LPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782170 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | LPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782166 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782162 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782158 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782154 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782148 | LUXAIRE | TH16B4821 | CM48DBCA1 | LPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782146 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | LPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782150 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782144 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | LPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782142 | LUXAIRE | TH16B4821 | CM48DBCA1 | LPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782140 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | LPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782138 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | LPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782130 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782134 | LUXAIRE | TH16B4821 | CM48DBCA1 | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782126 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782122 | LUXAIRE | TH16B4821 | CM48DBCA1 | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782118 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782114 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782110 | LUXAIRE | TH16B4821 | CM48DBCA1 | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782106 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782102 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782098 | LUXAIRE | TH16B4821 | CM48DBCA1 | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782094 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782090 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782086 | LUXAIRE | TH16B4821 | CM48DBCA1 | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782082 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782078 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782074 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | LPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782070 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782076 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | LPLC100C16MP13 | 28,000 | $1,400 |
| No | 206782066 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206782062 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206782058 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206782054 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206782050 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | LPLC120C20MP13 | 28,200 | $1,410 |
| No | 206782052 | LUXAIRE | TH16B4821 | CM48DBCA1 | LPLC120C20MP13 | 28,200 | $1,410 |
| No | 206782048 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | LPLC120C20MP13 | 28,200 | $1,410 |
| No | 206782045 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | LPLC100C20MP13 | 28,200 | $1,410 |
| No | 206782046 | LUXAIRE | TH16B4821 | CM48DBCA1 | LPLC100C20MP13 | 28,200 | $1,410 |
| No | 206782044 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | LPLC100C20MP13 | 28,200 | $1,410 |
| No | 206782041 | LUXAIRE | TH16B4821 | CM48DBCA1 | TPLC120C20MP13 | 28,200 | $1,410 |
| No | 206782037 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TPLC120C20MP13 | 28,200 | $1,410 |
| No | 206782033 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TPLC120C20MP13 | 28,200 | $1,410 |
| No | 206782029 | LUXAIRE | TH16B4821 | CM48DBCA1 | TPLC100C20MP13 | 28,200 | $1,410 |
| No | 206782025 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TPLC100C20MP13 | 28,200 | $1,410 |
| No | 206782021 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TPLC100C20MP13 | 28,200 | $1,410 |
| No | 206782017 | LUXAIRE | TH16B4821 | CM48DBCA1 | TMLV120C20MP12 | 28,200 | $1,410 |
| No | 206782013 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TMLV120C20MP12 | 28,200 | $1,410 |
| No | 206782009 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TMLV120C20MP12 | 28,200 | $1,410 |
| No | 206782005 | LUXAIRE | TH16B4821 | CM48DBCA1 | TM8V100C20MP12 | 28,200 | $1,410 |
| No | 206782001 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TM8V100C20MP12 | 28,200 | $1,410 |
| No | 206781997 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TM8V100C20MP12 | 28,200 | $1,410 |
| No | 206781993 | LUXAIRE | TH16B4821 | CM48DBCA1 | TM8V120C20MP12 | 28,200 | $1,410 |
| No | 206781989 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TM8V120C20MP12 | 28,200 | $1,410 |
| No | 206781985 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TM8V120C20MP12 | 28,200 | $1,410 |
| No | 206781981 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | LPLC100C20MP13 | 28,200 | $1,410 |
| No | 206781983 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | LPLC120C20MP13 | 28,200 | $1,410 |
| No | 206781978 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TPLC120C20MP13 | 28,200 | $1,410 |
| No | 206781974 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TPLC100C20MP13 | 28,200 | $1,410 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781970 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TMLV120C20MP12 | 28,200 | $1,410 |
| No | 206781966 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TM8V100C20MP12 | 28,200 | $1,410 |
| No | 206781962 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TM8V120C20MP12 | 28,200 | $1,410 |
| No | 206781960 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | LPLC120C20MP13 | 28,600 | $1,430 |
| No | 206781958 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | LPLC100C20MP13 | 28,600 | $1,430 |
| No | 206781955 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TPLC120C20MP13 | 28,600 | $1,430 |
| No | 206781951 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TPLC100C20MP13 | 28,600 | $1,430 |
| No | 206781947 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TMLV120C20MP12 | 28,600 | $1,430 |
| No | 206781943 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TM8V100C20MP12 | 28,600 | $1,430 |
| No | 206781939 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TM8V120C20MP12 | 28,600 | $1,430 |
| No | 206781937 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | LPLC120C20MP13 | 28,600 | $1,430 |
| No | 206781935 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | LPLC100C20MP13 | 28,600 | $1,430 |
| No | 206781932 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TPLC120C20MP13 | 28,600 | $1,430 |
| No | 206781928 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TPLC100C20MP13 | 28,600 | $1,430 |
| No | 206781924 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TMLV120C20MP12 | 28,600 | $1,430 |
| No | 206781920 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TM8V100C20MP12 | 28,600 | $1,430 |
| No | 206781916 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TM8V120C20MP12 | 28,600 | $1,430 |
| No | 206781348 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | LP9C060B12MP13 | 28,400 | $1,420 |
| No | 206781346 | LUXAIRE | TH16B4821 | CM48CBCA1 | LP9C060B12MP13 | 28,400 | $1,420 |
| No | 206781344 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | LP9C060B12MP13 | 28,400 | $1,420 |
| No | 202100754 | LUXAIRE | TH16B4821 | CF48CBCA1 | LP9C060B12MP13 | 28,400 | $1,420 |
| No | 206781340 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TP9C060B12MP13 | 28,400 | $1,420 |
| No | 206781336 | LUXAIRE | TH16B4821 | CM48CBCA1 | TP9C060B12MP13 | 28,400 | $1,420 |
| No | 202100717 | LUXAIRE | TH16B4821 | CF48CBCA1 | TP9C060B12MP13 | 28,400 | $1,420 |
| No | 206781332 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TP9C060B12MP13 | 28,400 | $1,420 |
| No | 206781328 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TM9V060B12MP12 | 28,400 | $1,420 |
| No | 206781324 | LUXAIRE | TH16B4821 | CM48CBCA1 | TM9V060B12MP12 | 28,400 | $1,420 |
| No | 206781320 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TM9V060B12MP12 | 28,400 | $1,420 |
| No | 206781314 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | LP9C060B12MP13 | 28,400 | $1,420 |
| No | 202100675 | LUXAIRE | TH16B4821 | CF48CBCA1 | TM9V060B12MP12 | 28,400 | $1,420 |
| No | 206781310 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TP9C060B12MP13 | 28,400 | $1,420 |
| No | 206781306 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TM9V060B12MP12 | 28,400 | $1,420 |
| No | 206782254 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | LP9C080B12MP13 | 28,200 | $1,410 |
| No | 206782252 | LUXAIRE | TH16B4821 | CM48CBCA1 | LP9C080B12MP13 | 28,200 | $1,410 |
| No | 206782250 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | LP9C080B12MP13 | 28,200 | $1,410 |
| No | 206782246 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TP9C080B12MP13 | 28,200 | $1,410 |
| No | 202100757 | LUXAIRE | TH16B4821 | CF48CBCA1 | LP9C080B12MP13 | 28,200 | $1,410 |
| No | 206782242 | LUXAIRE | TH16B4821 | CM48CBCA1 | TP9C080B12MP13 | 28,200 | $1,410 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782238 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TP9C080B12MP13 | 28,200 | $1,410 |
| No | 202100718 | LUXAIRE | TH16B4821 | CF48CBCA1 | TP9C080B12MP13 | 28,200 | $1,410 |
| No | 206782234 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TM9V080B12MP12 | 28,200 | $1,410 |
| No | 206782230 | LUXAIRE | TH16B4821 | CM48CBCA1 | TM9V080B12MP12 | 28,200 | $1,410 |
| No | 206782226 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TM9V080B12MP12 | 28,200 | $1,410 |
| No | 202100679 | LUXAIRE | TH16B4821 | CF48CBCA1 | TM9V080B12MP12 | 28,200 | $1,410 |
| No | 206782212 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | LP9C080B12MP13 | 28,200 | $1,410 |
| No | 206782208 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TP9C080B12MP13 | 28,200 | $1,410 |
| No | 206782204 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TM9V080B12MP12 | 28,200 | $1,410 |
| No | 206782202 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | LP9C080C16MP13 | 28,200 | $1,410 |
| No | 206782200 | LUXAIRE | TH16B4821 | CM48CBCA1 | LP9C080C16MP13 | 28,200 | $1,410 |
| No | 206782198 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | LP9C080C16MP13 | 28,200 | $1,410 |
| No | 202100758 | LUXAIRE | TH16B4821 | CF48CBCA1 | LP9C080C16MP13 | 28,200 | $1,410 |
| No | 206782222 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206782218 | LUXAIRE | TH16B4821 | CM48CBCA1 | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206782214 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 202100725 | LUXAIRE | TH16B4821 | CF48CBCA1 | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206782194 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206782190 | LUXAIRE | TH16B4821 | CM48CBCA1 | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206782186 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 202100685 | LUXAIRE | TH16B4821 | CF48CBCA1 | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206781886 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | LP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781882 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781878 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206781874 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | LP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781876 | LUXAIRE | TH16B4821 | CM48DBCA1 | LP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781872 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | LP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781868 | LUXAIRE | TH16B4821 | CM48DBCA1 | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781864 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781860 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781856 | LUXAIRE | TH16B4821 | CM48DBCA1 | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206781852 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206781848 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206781846 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | LP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781842 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206781838 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206781836 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | LP9C080C16MP13 | 29,800 | $1,490 |
| No | 206781832 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TP9C080C16MP13 | 29,800 | $1,490 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781826 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | LP9C080C16MP13 | 29,800 | $1,490 |
| No | 206781828 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TM9V080C16MP12 | 29,800 | $1,490 |
| No | 206781822 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TP9C080C16MP13 | 29,800 | $1,490 |
| No | 206781818 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TM9V080C16MP12 | 29,800 | $1,490 |
| No | 206781816 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | LP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781814 | LUXAIRE | TH16B4821 | CM48CBCA1 | LP9C100C16MP13 | 28,000 | $1,400 |
| No | 202100761 | LUXAIRE | TH16B4821 | CF48CBCA1 | LP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781812 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | LP9C100C16MP13 | 28,000 | $1,400 |
| No | 206782182 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206782178 | LUXAIRE | TH16B4821 | CM48CBCA1 | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206782174 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 202100726 | LUXAIRE | TH16B4821 | CF48CBCA1 | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781808 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206781804 | LUXAIRE | TH16B4821 | CM48CBCA1 | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206781800 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 202100686 | LUXAIRE | TH16B4821 | CF48CBCA1 | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206781758 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | LP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781754 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781750 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206781748 | LUXAIRE | TH16B4821 | CM48DBCA1 | LP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781746 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | LP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781744 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | LP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781740 | LUXAIRE | TH16B4821 | CM48DBCA1 | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781736 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781732 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781728 | LUXAIRE | TH16B4821 | CM48DBCA1 | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206781724 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206781720 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206781718 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | LP9C100C16MP13 | 28,000 | $1,400 |
| No | 206781710 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206782514 | LUXAIRE | TH16B4821 | CM48DBCA1 | LP9C100C20MP13 | 28,200 | $1,410 |
| No | 206781714 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206782512 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | LP9C100C20MP13 | 28,200 | $1,410 |
| No | 206782510 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | LP9C100C20MP13 | 28,200 | $1,410 |
| No | 206782502 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TP9C100C20MP13 | 28,200 | $1,410 |
| No | 206782506 | LUXAIRE | TH16B4821 | CM48DBCA1 | TP9C100C20MP13 | 28,200 | $1,410 |
| No | 206782498 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TP9C100C20MP13 | 28,200 | $1,410 |
| No | 206782494 | LUXAIRE | TH16B4821 | CM48DBCA1 | TM9V100C20MP12 | 28,200 | $1,410 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206782490 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TM9V100C20MP12 | 28,200 | $1,410 |
| No | 206782486 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TM9V100C20MP12 | 28,200 | $1,410 |
| No | 206782484 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | LP9C100C20MP13 | 28,200 | $1,410 |
| No | 206782480 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TP9C100C20MP13 | 28,200 | $1,410 |
| No | 206782476 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TM9V100C20MP12 | 28,200 | $1,410 |
| No | 206782466 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | LP9C120D20MP13 | 29,400 | $1,470 |
| No | 206782462 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TP9C120D20MP13 | 29,400 | $1,470 |
| No | 206782458 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TM9V120D20MP12 | 29,400 | $1,470 |
| No | 206782456 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | LP9C120D20MP13 | 29,400 | $1,470 |
| No | 206782452 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TP9C120D20MP13 | 29,400 | $1,470 |
| No | 206782448 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TM9V120D20MP12 | 29,400 | $1,470 |
| No | 205536129 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | LP9C120D20MP13 | 28,400 | $1,420 |
| No | 205536137 | LUXAIRE | TH16B4821 | CM48DBCA1 | LP9C120D20MP13 | 28,400 | $1,420 |
| No | 205536121 | LUXAIRE | TH16B4821 | CM48DBCA1 | TP9C120D20MP13 | 28,400 | $1,420 |
| No | 205536113 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TP9C120D20MP13 | 28,400 | $1,420 |
| No | 205536132 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | LP9C120D20MP13 | 28,400 | $1,420 |
| No | 205536104 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TP9C120D20MP13 | 28,400 | $1,420 |
| No | 205536096 | LUXAIRE | TH16B4821 | CM48DBCA1 | TM9V120D20MP12 | 28,400 | $1,420 |
| No | 205536088 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TM9V120D20MP12 | 28,400 | $1,420 |
| No | 205536079 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TM9V120D20MP12 | 28,400 | $1,420 |
| No | 205536074 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | LP9C120D20MP13 | 28,400 | $1,420 |
| No | 205536066 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TP9C120D20MP13 | 28,400 | $1,420 |
| No | 205536058 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TM9V120D20MP12 | 28,400 | $1,420 |
| No | 206780288 | LUXAIRE | TH16B2421 | CU24BXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |
| No | 206780284 | LUXAIRE | TH16B2421 | CM24BBAA1 | TL8E060A12UH11 | 15,200 | $760 |
| No | 206780280 | LUXAIRE | TH16B2421 | CM24BXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |
| No | 206780276 | LUXAIRE | TH16B2421 | CF24BBAA1 | TL8E060A12UH11 | 15,200 | $760 |
| No | 206780272 | LUXAIRE | TH16B2421 | CF24BXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |
| No | 205541010 | LUXAIRE | TH16B2421 | CU36BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205540998 | LUXAIRE | TH16B2421 | CM36BBAA1 | TL8E060A12UH11 | 15,100 | $755 |
| No | 205540986 | LUXAIRE | TH16B2421 | CM36BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205540972 | LUXAIRE | TH16B2421 | CF36BBAA1 | TL8E060A12UH11 | 15,100 | $755 |
| No | 205540960 | LUXAIRE | TH16B2421 | CF36BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205540946 | LUXAIRE | TH16B2421 | CU24BXA1+TXV | TL9E060B12UH11 | 15,300 | $765 |
| No | 205540934 | LUXAIRE | TH16B2421 | CM24BBAA1 | TL9E060B12UH11 | 15,300 | $765 |
| No | 205540921 | LUXAIRE | TH16B2421 | CM24BXA1+TXV | TL9E060B12UH11 | 15,300 | $765 |
| No | 205540909 | LUXAIRE | TH16B2421 | CF24BBAA1 | TL9E060B12UH11 | 15,300 | $765 |
| No | 205540896 | LUXAIRE | TH16B2421 | CF24BXA1+TXV | TL9E060B12UH11 | 15,300 | $765 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780268 | LUXAIRE | TH16B2421 | CU36CXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 206780264 | LUXAIRE | TH16B2421 | CM36CXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 206780260 | LUXAIRE | TH16B2421 | CF36CXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205540885 | LUXAIRE | TH16B2421 | CU30BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 203429767 | LUXAIRE | TH16B2421 | CM30BBAA1 | TMLE040A12MP11 | 15,100 | $755 |
| No | 205541141 | LUXAIRE | TH16B2421 | CM30BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 203429756 | LUXAIRE | TH16B2421 | CF30BBAA1 | TMLE040A12MP11 | 15,100 | $755 |
| No | 205540874 | LUXAIRE | TH16B2421 | CU30BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 203429762 | LUXAIRE | TH16B2421 | CM30BBAA1 | TM8E040A12MP11 | 15,100 | $755 |
| No | 205540862 | LUXAIRE | TH16B2421 | CM30BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 203429751 | LUXAIRE | TH16B2421 | CF30BBAA1 | TM8E040A12MP11 | 15,100 | $755 |
| No | 205540850 | LUXAIRE | TH16B2421 | CF30BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 205540839 | LUXAIRE | TH16B2421 | CF30BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 206780236 | LUXAIRE | TH16B2421 | CM36AXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 206780232 | LUXAIRE | TH16B2421 | CM36AXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 206780228 | LUXAIRE | TH16B2421 | CF36AXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 206780224 | LUXAIRE | TH16B2421 | CF36AXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 206780220 | LUXAIRE | TH16B2421 | CU36BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 206780216 | LUXAIRE | TH16B2421 | CM36BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 203429723 | LUXAIRE | TH16B2421 | CM36BBAA1 | TMLE040A12MP11 | 15,100 | $755 |
| No | 203429712 | LUXAIRE | TH16B2421 | CF36BBAA1 | TMLE040A12MP11 | 15,100 | $755 |
| No | 206780212 | LUXAIRE | TH16B2421 | CU36BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 203429718 | LUXAIRE | TH16B2421 | CM36BBAA1 | TM8E040A12MP11 | 15,100 | $755 |
| No | 206780208 | LUXAIRE | TH16B2421 | CM36BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 203429707 | LUXAIRE | TH16B2421 | CF36BBAA1 | TM8E040A12MP11 | 15,100 | $755 |
| No | 206780204 | LUXAIRE | TH16B2421 | CF36BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 206780200 | LUXAIRE | TH16B2421 | CF36BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 205550181 | LUXAIRE | TH16B2421 | CM30CXA1+TXV | TMLE100B12MP11 | 15,200 | $760 |
| No | 205550177 | LUXAIRE | TH16B2421 | CM30CXA1+TXV | TM8E100B12MP11 | 15,200 | $760 |
| No | 205550173 | LUXAIRE | TH16B2421 | CF30CXA1+TXV | TMLE100B12MP11 | 15,200 | $760 |
| No | 205550169 | LUXAIRE | TH16B2421 | CF30CXA1+TXV | TM8E100B12MP11 | 15,200 | $760 |
| No | 206373300 | LUXAIRE | TH16B2421 | CU24AXA1+TXV | TM9E026A08MP12 | 15,000 | $750 |
| No | 206373301 | LUXAIRE | TH16B2421 | CM24ABAA1 | TM9E026A08MP12 | 15,000 | $750 |
| No | 206373302 | LUXAIRE | TH16B2421 | CM24AXA1+TXV | TM9E026A08MP12 | 15,000 | $750 |
| No | 206373303 | LUXAIRE | TH16B2421 | CF24ABAA1 | TM9E026A08MP12 | 15,000 | $750 |
| No | 206373305 | LUXAIRE | TH16B2421 | CU30BXA1+TXV | TM9E026A08MP12 | 15,400 | $770 |
| No | 206373306 | LUXAIRE | TH16B2421 | CM30BBAA1 | TM9E026A08MP12 | 15,400 | $770 |
| No | 206373304 | LUXAIRE | TH16B2421 | CF24AXA1+TXV | TM9E026A08MP12 | 15,000 | $750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206373307 | LUXAIRE | TH16B2421 | CM30BXA1+TXV | TM9E026A08MP12 | 15,400 | $770 |
| No | 206373308 | LUXAIRE | TH16B2421 | CF30BBAA1 | TM9E026A08MP12 | 15,400 | $770 |
| No | 206780196 | LUXAIRE | TH16B2421 | CU24AXA1+TXV | TM9E040A10MP12 | 15,300 | $765 |
| No | 206780192 | LUXAIRE | TH16B2421 | CM24ABAA1 | TM9E040A10MP12 | 15,300 | $765 |
| No | 206373309 | LUXAIRE | TH16B2421 | CF30BXA1+TXV | TM9E026A08MP12 | 15,400 | $770 |
| No | 206780184 | LUXAIRE | TH16B2421 | CF24ABAA1 | TM9E040A10MP12 | 15,300 | $765 |
| No | 206780180 | LUXAIRE | TH16B2421 | CF24AXA1+TXV | TM9E040A10MP12 | 15,300 | $765 |
| No | 206780188 | LUXAIRE | TH16B2421 | CM24AXA1+TXV | TM9E040A10MP12 | 15,300 | $765 |
| No | 205074496 | LUXAIRE | TH16B2421 | CM30AXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205074256 | LUXAIRE | TH16B2421 | CF30ABAA1 | TM9E040A10MP12 | 15,200 | $760 |
| No | 205074491 | LUXAIRE | TH16B2421 | CF30AXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540828 | LUXAIRE | TH16B2421 | CM36AXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540815 | LUXAIRE | TH16B2421 | CF36AXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540802 | LUXAIRE | TH16B2421 | CU36BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540789 | LUXAIRE | TH16B2421 | CM36BBAA1 | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540778 | LUXAIRE | TH16B2421 | CM36BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540770 | LUXAIRE | TH16B2421 | CF36BBAA1 | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540756 | LUXAIRE | TH16B2421 | CF36BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205540744 | LUXAIRE | TH16B2421 | CU24BXA1+TXV | TM9E060A10MP12 | 15,300 | $765 |
| No | 205540725 | LUXAIRE | TH16B2421 | CM24BBAA1 | TM9E060A10MP12 | 15,300 | $765 |
| No | 205540713 | LUXAIRE | TH16B2421 | CM24BXA1+TXV | TM9E060A10MP12 | 15,300 | $765 |
| No | 205540700 | LUXAIRE | TH16B2421 | CF24BBAA1 | TM9E060A10MP12 | 15,300 | $765 |
| No | 205540686 | LUXAIRE | TH16B2421 | CF24BXA1+TXV | TM9E060A10MP12 | 15,300 | $765 |
| No | 205074485 | LUXAIRE | TH16B2421 | CM30AXA1+TXV | TM9E060A10MP12 | 15,200 | $760 |
| No | 205074244 | LUXAIRE | TH16B2421 | CF30ABAA1 | TM9E060A10MP12 | 15,200 | $760 |
| No | 205074478 | LUXAIRE | TH16B2421 | CF30AXA1+TXV | TM9E060A10MP12 | 15,200 | $760 |
| No | 205540480 | LUXAIRE | TH16B2421 | CU36BXA1+TXV | TM9E060A10MP12 | 15,200 | $760 |
| No | 205540467 | LUXAIRE | TH16B2421 | CM36BBAA1 | TM9E060A10MP12 | 15,200 | $760 |
| No | 205540452 | LUXAIRE | TH16B2421 | CM36BXA1+TXV | TM9E060A10MP12 | 15,200 | $760 |
| No | 205540437 | LUXAIRE | TH16B2421 | CF36BBAA1 | TM9E060A10MP12 | 15,200 | $760 |
| No | 205540422 | LUXAIRE | TH16B2421 | CF36BXA1+TXV | TM9E060A10MP12 | 15,200 | $760 |
| No | 202143938 | LUXAIRE | TH16B4821 | AE48DBC21 | | 28,200 | $1,410 |
| No | 202763639 | LUXAIRE | TH16B4821 | AVC60CX22+TXV | | 28,200 | $1,410 |
| No | 202143942 | LUXAIRE | TH16B4821 | AE48DX21+TXV | | 28,200 | $1,410 |
| No | 206781250 | LUXAIRE | TH16B4821 | CM64DXA1+ME14DN21+TXV | | 29,000 | $1,450 |
| No | 206781246 | LUXAIRE | TH16B4821 | CF64DXA1+ME14DN21+TXV | | 29,000 | $1,450 |
| No | 205540165 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205540152 | LUXAIRE | TH16B4821 | CM48CBCA1 | TM9Y080C16MP11 | 28,600 | $1,430 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205540134 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 202143986 | LUXAIRE | TH16B4821 | CF48CBCA1 | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205540637 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205540611 | LUXAIRE | TH16B4821 | CM48DBCA1 | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205540599 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205540589 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205540540 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 206782572 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TM9Y080C16MP11 | 29,800 | $1,490 |
| No | 206782568 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TM9Y080C16MP11 | 29,800 | $1,490 |
| No | 9060440 | LUXAIRE | TH16B2421 | AE30BX21+TXV | | 14,800 | $740 |
| No | 206838952 | LUXAIRE | TH16B2421 | CM30BBAA1+ME08BN21 | | 15,100 | $755 |
| No | 206838948 | LUXAIRE | TH16B2421 | CM30BXA1+ME08BN21+TXV | | 15,100 | $755 |
| No | 206838944 | LUXAIRE | TH16B2421 | CF30BBAA1+ME08BN21 | | 15,100 | $755 |
| No | 206838940 | LUXAIRE | TH16B2421 | CF30BXA1+ME08BN21+TXV | | 15,100 | $755 |
| No | 205536235 | LUXAIRE | TH16B2421 | CU36BXA1+TXV | TM9Y060B12MP11 | 14,800 | $740 |
| No | 205536222 | LUXAIRE | TH16B2421 | CM36BBAA1 | TM9Y060B12MP11 | 14,800 | $740 |
| No | 205536212 | LUXAIRE | TH16B2421 | CM36BXA1+TXV | TM9Y060B12MP11 | 14,800 | $740 |
| No | 205536201 | LUXAIRE | TH16B2421 | CF36BBAA1 | TM9Y060B12MP11 | 14,800 | $740 |
| No | 205536152 | LUXAIRE | TH16B2421 | CF36BXA1+TXV | TM9Y060B12MP11 | 14,800 | $740 |
| No | 9060441 | LUXAIRE | TH16B2421 | AVC24BX21+TXV | | 14,800 | $740 |
| No | 9060444 | LUXAIRE | TH16B2421 | AVC36CX21+TXV | | 14,600 | $730 |
| No | 9036037 | LUXAIRE | TH16B6021 | AVC60DX21+TXV | | 32,000 | $1,600 |
| No | 205539840 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | LP9C080C16MP13 | 32,600 | $1,630 |
| No | 205539830 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TP9C080C16MP13 | 32,600 | $1,630 |
| No | 205539818 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TM9V080C16MP12 | 32,600 | $1,630 |
| No | 205539815 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | LP9C080C16MP13 | 32,600 | $1,630 |
| No | 205539803 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TP9C080C16MP13 | 32,600 | $1,630 |
| No | 205539795 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TM9V080C16MP12 | 32,600 | $1,630 |
| No | 9036353 | LUXAIRE | TH16B4821 | AVC60DX21+TXV | | 29,400 | $1,470 |
| No | 205550165 | LUXAIRE | TH16B2421 | CU36BXA1+TXV | TMLE100B12MP11 | 15,000 | $750 |
| No | 203429581 | LUXAIRE | TH16B2421 | CM36BBAA1 | TMLE100B12MP11 | 15,000 | $750 |
| No | 205550161 | LUXAIRE | TH16B2421 | CM36BXA1+TXV | TMLE100B12MP11 | 15,000 | $750 |
| No | 203429570 | LUXAIRE | TH16B2421 | CF36BBAA1 | TMLE100B12MP11 | 15,000 | $750 |
| No | 205550157 | LUXAIRE | TH16B2421 | CU36BXA1+TXV | TM8E100B12MP11 | 15,000 | $750 |
| No | 203429575 | LUXAIRE | TH16B2421 | CM36BBAA1 | TM8E100B12MP11 | 15,000 | $750 |
| No | 205550153 | LUXAIRE | TH16B2421 | CM36BXA1+TXV | TM8E100B12MP11 | 15,000 | $750 |
| No | 203429565 | LUXAIRE | TH16B2421 | CF36BBAA1 | TM8E100B12MP11 | 15,000 | $750 |
| No | 205550145 | LUXAIRE | TH16B2421 | CF36BXA1+TXV | TMLE100B12MP11 | 15,000 | $750 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205550141 | LUXAIRE | TH16B2421 | CF36BXA1+TXV | TM8E100B12MP11 | 15,000 | $750 |
| No | 203064269 | LUXAIRE | TH16B3622 | AE36BX21+TXV | | 22,200 | $1,110 |
| No | 205548016 | LUXAIRE | TH16B2421 | CU30BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205548012 | LUXAIRE | TH16B2421 | CM30BBAA1 | TL8E060A12UH11 | 15,100 | $755 |
| No | 205548008 | LUXAIRE | TH16B2421 | CM30BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205548004 | LUXAIRE | TH16B2421 | CF30BBAA1 | TL8E060A12UH11 | 15,100 | $755 |
| No | 205548000 | LUXAIRE | TH16B2421 | CF30BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205547996 | LUXAIRE | TH16B2421 | CU30BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547992 | LUXAIRE | TH16B2421 | CM30BBAA1 | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547988 | LUXAIRE | TH16B2421 | CM30BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547984 | LUXAIRE | TH16B2421 | CF30BBAA1 | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547980 | LUXAIRE | TH16B2421 | CF30BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547976 | LUXAIRE | TH16B2421 | CM30CXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547972 | LUXAIRE | TH16B2421 | CF30CXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547968 | LUXAIRE | TH16B2421 | CU36BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547964 | LUXAIRE | TH16B2421 | CM36BBAA1 | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547960 | LUXAIRE | TH16B2421 | CM36BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205547952 | LUXAIRE | TH16B2421 | CF36BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 206780256 | LUXAIRE | TH16B2421 | CU24AXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |
| No | 205547956 | LUXAIRE | TH16B2421 | CF36BBAA1 | TL9E060B12UH11 | 15,200 | $760 |
| No | 203429844 | LUXAIRE | TH16B2421 | CM24ABAA1 | TMLE040A12MP11 | 15,200 | $760 |
| No | 206780464 | LUXAIRE | TH16B2421 | CM24AXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |
| No | 203429855 | LUXAIRE | TH16B2421 | CF24ABAA1 | TMLE040A12MP11 | 15,200 | $760 |
| No | 206780252 | LUXAIRE | TH16B2421 | CU24AXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 203429838 | LUXAIRE | TH16B2421 | CM24ABAA1 | TM8E040A12MP11 | 15,200 | $760 |
| No | 206780248 | LUXAIRE | TH16B2421 | CM24AXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 203429849 | LUXAIRE | TH16B2421 | CF24ABAA1 | TM8E040A12MP11 | 15,200 | $760 |
| No | 206780244 | LUXAIRE | TH16B2421 | CF24AXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |
| No | 206780240 | LUXAIRE | TH16B2421 | CF24AXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 205547948 | LUXAIRE | TH16B2421 | CU24BXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |
| No | 203429811 | LUXAIRE | TH16B2421 | CM24BBAA1 | TMLE040A12MP11 | 15,200 | $760 |
| No | 205548242 | LUXAIRE | TH16B2421 | CM24BXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |
| No | 203429822 | LUXAIRE | TH16B2421 | CF24BBAA1 | TMLE040A12MP11 | 15,200 | $760 |
| No | 205548238 | LUXAIRE | TH16B2421 | CU24BXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 203429806 | LUXAIRE | TH16B2421 | CM24BBAA1 | TM8E040A12MP11 | 15,200 | $760 |
| No | 205548234 | LUXAIRE | TH16B2421 | CM24BXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 203429817 | LUXAIRE | TH16B2421 | CF24BBAA1 | TM8E040A12MP11 | 15,200 | $760 |
| No | 205548202 | LUXAIRE | TH16B2421 | CF24BXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205548198 | LUXAIRE | TH16B2421 | CF24BXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 205074516 | LUXAIRE | TH16B2421 | CM30AXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 203429789 | LUXAIRE | TH16B2421 | CF30ABAA1 | TMLE040A12MP11 | 15,100 | $755 |
| No | 205074270 | LUXAIRE | TH16B2421 | CM30AXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 203429783 | LUXAIRE | TH16B2421 | CF30ABAA1 | TM8E040A12MP11 | 15,100 | $755 |
| No | 205074265 | LUXAIRE | TH16B2421 | CF30AXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 205074504 | LUXAIRE | TH16B2421 | CF30AXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 203429680 | LUXAIRE | TH16B2421 | CM24BBAA1 | TMLE080B12MP11 | 15,200 | $760 |
| No | 205546116 | LUXAIRE | TH16B2421 | CU24BXA1+TXV | TMLE080B12MP11 | 15,200 | $760 |
| No | 205546112 | LUXAIRE | TH16B2421 | CM24BXA1+TXV | TMLE080B12MP11 | 15,200 | $760 |
| No | 203429690 | LUXAIRE | TH16B2421 | CF24BBAA1 | TMLE080B12MP11 | 15,200 | $760 |
| No | 205546108 | LUXAIRE | TH16B2421 | CU24BXA1+TXV | TM8E080B12MP11 | 15,200 | $760 |
| No | 203429674 | LUXAIRE | TH16B2421 | CM24BBAA1 | TM8E080B12MP11 | 15,200 | $760 |
| No | 205546104 | LUXAIRE | TH16B2421 | CM24BXA1+TXV | TM8E080B12MP11 | 15,200 | $760 |
| No | 203429685 | LUXAIRE | TH16B2421 | CF24BBAA1 | TM8E080B12MP11 | 15,200 | $760 |
| No | 205546096 | LUXAIRE | TH16B2421 | CF24BXA1+TXV | TMLE080B12MP11 | 15,200 | $760 |
| No | 205546092 | LUXAIRE | TH16B2421 | CF24BXA1+TXV | TM8E080B12MP11 | 15,200 | $760 |
| No | 205546088 | LUXAIRE | TH16B2421 | CU24BXA1+TXV | TMLE100B12MP11 | 15,100 | $755 |
| No | 203429646 | LUXAIRE | TH16B2421 | CM24BBAA1 | TMLE100B12MP11 | 15,100 | $755 |
| No | 205546100 | LUXAIRE | TH16B2421 | CM24BXA1+TXV | TMLE100B12MP11 | 15,100 | $755 |
| No | 203429657 | LUXAIRE | TH16B2421 | CF24BBAA1 | TMLE100B12MP11 | 15,100 | $755 |
| No | 205544361 | LUXAIRE | TH16B2421 | CU24BXA1+TXV | TM8E100B12MP11 | 15,100 | $755 |
| No | 203429641 | LUXAIRE | TH16B2421 | CM24BBAA1 | TM8E100B12MP11 | 15,100 | $755 |
| No | 205544354 | LUXAIRE | TH16B2421 | CM24BXA1+TXV | TM8E100B12MP11 | 15,100 | $755 |
| No | 203429652 | LUXAIRE | TH16B2421 | CF24BBAA1 | TM8E100B12MP11 | 15,100 | $755 |
| No | 205544347 | LUXAIRE | TH16B2421 | CF24BXA1+TXV | TMLE100B12MP11 | 15,100 | $755 |
| No | 205544339 | LUXAIRE | TH16B2421 | CF24BXA1+TXV | TM8E100B12MP11 | 15,100 | $755 |
| No | 205550201 | LUXAIRE | TH16B2421 | CU30BXA1+TXV | TMLE100B12MP11 | 15,200 | $760 |
| No | 203429625 | LUXAIRE | TH16B2421 | CM30BBAA1 | TMLE100B12MP11 | 15,200 | $760 |
| No | 205550222 | LUXAIRE | TH16B2421 | CM30BXA1+TXV | TMLE100B12MP11 | 15,200 | $760 |
| No | 205550197 | LUXAIRE | TH16B2421 | CU30BXA1+TXV | TM8E100B12MP11 | 15,200 | $760 |
| No | 203429619 | LUXAIRE | TH16B2421 | CM30BBAA1 | TM8E100B12MP11 | 15,200 | $760 |
| No | 203429614 | LUXAIRE | TH16B2421 | CF30BBAA1 | TMLE100B12MP11 | 15,200 | $760 |
| No | 205550193 | LUXAIRE | TH16B2421 | CM30BXA1+TXV | TM8E100B12MP11 | 15,200 | $760 |
| No | 203429608 | LUXAIRE | TH16B2421 | CF30BBAA1 | TM8E100B12MP11 | 15,200 | $760 |
| No | 205550189 | LUXAIRE | TH16B2421 | CF30BXA1+TXV | TMLE100B12MP11 | 15,200 | $760 |
| No | 205550185 | LUXAIRE | TH16B2421 | CF30BXA1+TXV | TM8E100B12MP11 | 15,200 | $760 |
| No | 206373310 | LUXAIRE | TH16B2421 | CU24BXA1+TXV | TM9E026A08MP12 | 15,600 | $780 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206373311 | LUXAIRE | TH16B2421 | CM24BBAA1 | TM9E026A08MP12 | 15,600 | $780 |
| No | 206373312 | LUXAIRE | TH16B2421 | CM24BXA1+TXV | TM9E026A08MP12 | 15,600 | $780 |
| No | 206373313 | LUXAIRE | TH16B2421 | CF24BBAA1 | TM9E026A08MP12 | 15,600 | $780 |
| No | 206373314 | LUXAIRE | TH16B2421 | CF24BXA1+TXV | TM9E026A08MP12 | 15,600 | $780 |
| No | 206373315 | LUXAIRE | TH16B2421 | CM30AXA1+TXV | TM9E026A08MP12 | 14,800 | $740 |
| No | 206373316 | LUXAIRE | TH16B2421 | CF30ABAA1 | TM9E026A08MP12 | 14,800 | $740 |
| No | 206373317 | LUXAIRE | TH16B2421 | CF30AXA1+TXV | TM9E026A08MP12 | 14,800 | $740 |
| No | 206373318 | LUXAIRE | TH16B2421 | CM36AXA1+TXV | TM9E026A08MP12 | 14,900 | $745 |
| No | 206373319 | LUXAIRE | TH16B2421 | CF36AXA1+TXV | TM9E026A08MP12 | 14,900 | $745 |
| No | 206373320 | LUXAIRE | TH16B2421 | CU36BXA1+TXV | TM9E026A08MP12 | 14,900 | $745 |
| No | 206373322 | LUXAIRE | TH16B2421 | CM36BXA1+TXV | TM9E026A08MP12 | 14,900 | $745 |
| No | 206373321 | LUXAIRE | TH16B2421 | CM36BBAA1 | TM9E026A08MP12 | 14,900 | $745 |
| No | 206373323 | LUXAIRE | TH16B2421 | CF36BBAA1 | TM9E026A08MP12 | 14,900 | $745 |
| No | 206373324 | LUXAIRE | TH16B2421 | CF36BXA1+TXV | TM9E026A08MP12 | 14,900 | $745 |
| No | 205548194 | LUXAIRE | TH16B2421 | CU24BXA1+TXV | TM9E040A10MP12 | 15,400 | $770 |
| No | 205548190 | LUXAIRE | TH16B2421 | CM24BBAA1 | TM9E040A10MP12 | 15,400 | $770 |
| No | 205548186 | LUXAIRE | TH16B2421 | CM24BXA1+TXV | TM9E040A10MP12 | 15,400 | $770 |
| No | 205548182 | LUXAIRE | TH16B2421 | CF24BBAA1 | TM9E040A10MP12 | 15,400 | $770 |
| No | 205548174 | LUXAIRE | TH16B2421 | CU30BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205548178 | LUXAIRE | TH16B2421 | CF24BXA1+TXV | TM9E040A10MP12 | 15,400 | $770 |
| No | 205548170 | LUXAIRE | TH16B2421 | CM30BBAA1 | TM9E040A10MP12 | 15,200 | $760 |
| No | 205548162 | LUXAIRE | TH16B2421 | CF30BBAA1 | TM9E040A10MP12 | 15,200 | $760 |
| No | 205548166 | LUXAIRE | TH16B2421 | CM30BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205548158 | LUXAIRE | TH16B2421 | CF30BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205548154 | LUXAIRE | TH16B2421 | CU24AXA1+TXV | TM9E060A10MP12 | 15,400 | $770 |
| No | 205548150 | LUXAIRE | TH16B2421 | CM24ABAA1 | TM9E060A10MP12 | 15,400 | $770 |
| No | 205548146 | LUXAIRE | TH16B2421 | CM24AXA1+TXV | TM9E060A10MP12 | 15,400 | $770 |
| No | 205548142 | LUXAIRE | TH16B2421 | CF24ABAA1 | TM9E060A10MP12 | 15,400 | $770 |
| No | 205548138 | LUXAIRE | TH16B2421 | CF24AXA1+TXV | TM9E060A10MP12 | 15,400 | $770 |
| No | 205548134 | LUXAIRE | TH16B2421 | CU30BXA1+TXV | TM9E060A10MP12 | 15,100 | $755 |
| No | 205548130 | LUXAIRE | TH16B2421 | CM30BBAA1 | TM9E060A10MP12 | 15,100 | $755 |
| No | 205548126 | LUXAIRE | TH16B2421 | CM30BXA1+TXV | TM9E060A10MP12 | 15,100 | $755 |
| No | 205548118 | LUXAIRE | TH16B2421 | CF30BXA1+TXV | TM9E060A10MP12 | 15,100 | $755 |
| No | 205548114 | LUXAIRE | TH16B2421 | CM36AXA1+TXV | TM9E060A10MP12 | 15,100 | $755 |
| No | 205548122 | LUXAIRE | TH16B2421 | CF30BBAA1 | TM9E060A10MP12 | 15,100 | $755 |
| No | 205548110 | LUXAIRE | TH16B2421 | CF36AXA1+TXV | TM9E060A10MP12 | 15,100 | $755 |
| No | 206779782 | LUXAIRE | TH16B2421 | CM36BBAA1+ME08BN21 | | 15,000 | $750 |
| No | 206779778 | LUXAIRE | TH16B2421 | CM36BXA1+ME08BN21+TXV | | 15,000 | $750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206779770 | LUXAIRE | TH16B2421 | CF36BXA1+ME08BN21+TXV | | 15,000 | $750 |
| No | 206779774 | LUXAIRE | TH16B2421 | CF36BBAA1+ME08BN21 | | 15,000 | $750 |
| No | 9060442 | LUXAIRE | TH16B2421 | AVC30BX21+TXV | | 15,100 | $755 |
| No | 9060443 | LUXAIRE | TH16B2421 | AVC36BX21+TXV | | 15,000 | $750 |
| No | 205547848 | LUXAIRE | TH16B6021 | CM64DXA1+MVC20DN21+TXV | | 32,600 | $1,630 |
| No | 205547844 | LUXAIRE | TH16B6021 | CF64DXA1+MVC20DN21+TXV | | 32,600 | $1,630 |
| No | 205547842 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | LPLC120C20MP13 | 32,400 | $1,620 |
| No | 205547840 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | LPLC100C20MP13 | 32,400 | $1,620 |
| No | 205547836 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TPLC120C20MP13 | 32,400 | $1,620 |
| No | 205547832 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TPLC100C20MP13 | 32,400 | $1,620 |
| No | 205547828 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TMLV120C20MP12 | 32,400 | $1,620 |
| No | 205547820 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TM8V100C20MP12 | 32,400 | $1,620 |
| No | 205547814 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | LPLC120C20MP13 | 32,400 | $1,620 |
| No | 205547812 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | LPLC100C20MP13 | 32,400 | $1,620 |
| No | 205547808 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TPLC120C20MP13 | 32,400 | $1,620 |
| No | 205547816 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TM8V120C20MP12 | 32,400 | $1,620 |
| No | 205547804 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TPLC100C20MP13 | 32,400 | $1,620 |
| No | 205547800 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TMLV120C20MP12 | 32,400 | $1,620 |
| No | 205547792 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TM8V100C20MP12 | 32,400 | $1,620 |
| No | 205547788 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TM8V120C20MP12 | 32,400 | $1,620 |
| No | 203431215 | LUXAIRE | TH16B4821 | CM48DBCA1 | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205547626 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205547622 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 203431209 | LUXAIRE | TH16B4821 | CM48DBCA1 | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 205547572 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 205547568 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 205547564 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205547560 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 9854443 | LUXAIRE | TH16B4821 | AE48CBC21 | | 28,400 | $1,420 |
| No | 9854438 | LUXAIRE | TH16B2421 | AE24BBA21 | | 15,100 | $755 |
| No | 9006281 | LUXAIRE | TH16B4821 | AE48CX21+TXV | | 28,400 | $1,420 |
| No | 9006271 | LUXAIRE | TH16B2421 | AE24BX21+TXV | | 15,100 | $755 |
| No | 205550137 | LUXAIRE | TH16B3622 | CM36AXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 205550129 | LUXAIRE | TH16B3622 | CU36BXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 205550133 | LUXAIRE | TH16B3622 | CF36AXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 203088279 | LUXAIRE | TH16B3622 | CM36BBCA1 | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 205550149 | LUXAIRE | TH16B3622 | CM36BXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 203088261 | LUXAIRE | TH16B3622 | CF36BBCA1 | TL8E060A12UH11 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205550125 | LUXAIRE | TH16B3622 | CF36BXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 205550121 | LUXAIRE | TH16B3622 | CF42BXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 205550117 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 203088054 | LUXAIRE | TH16B3622 | CM42CBCA1 | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205550113 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205550105 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TL9E060B12UH11 | 22,400 | $1,120 |
| No | 205550109 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 203088033 | LUXAIRE | TH16B3622 | CF42CBCA1 | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 203087997 | LUXAIRE | TH16B3622 | CM48CBCA1 | TL9E060B12UH11 | 22,400 | $1,120 |
| No | 205550101 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TL9E060B12UH11 | 22,400 | $1,120 |
| No | 203087979 | LUXAIRE | TH16B3622 | CF48CBCA1 | TL9E060B12UH11 | 22,400 | $1,120 |
| No | 205550097 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TL9E060B12UH11 | 22,400 | $1,120 |
| No | 205550093 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TL9E080C16UH11 | 22,600 | $1,130 |
| No | 203087942 | LUXAIRE | TH16B3622 | CM36CBCA1 | TL9E080C16UH11 | 22,600 | $1,130 |
| No | 205550089 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TL9E080C16UH11 | 22,600 | $1,130 |
| No | 205550085 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TL9E080C16UH11 | 22,600 | $1,130 |
| No | 205550081 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TL9E080C16UH11 | 22,800 | $1,140 |
| No | 203087904 | LUXAIRE | TH16B3622 | CM42CBCA1 | TL9E080C16UH11 | 22,800 | $1,140 |
| No | 203087884 | LUXAIRE | TH16B3622 | CF42CBCA1 | TL9E080C16UH11 | 22,800 | $1,140 |
| No | 205550069 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TL9E080C16UH11 | 22,800 | $1,140 |
| No | 205550077 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TL9E080C16UH11 | 22,800 | $1,140 |
| No | 205550065 | LUXAIRE | TH16B3622 | CM36AXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205550057 | LUXAIRE | TH16B3622 | CF36AXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205550061 | LUXAIRE | TH16B3622 | CM36AXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205550053 | LUXAIRE | TH16B3622 | CF36AXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205550049 | LUXAIRE | TH16B3622 | CU36BXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 203431022 | LUXAIRE | TH16B3622 | CM36BBCA1 | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205550073 | LUXAIRE | TH16B3622 | CM36BXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 203431017 | LUXAIRE | TH16B3622 | CF36BBCA1 | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205550045 | LUXAIRE | TH16B3622 | CU36BXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 203087722 | LUXAIRE | TH16B3622 | CM36BBCA1 | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205550041 | LUXAIRE | TH16B3622 | CM36BXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 203087703 | LUXAIRE | TH16B3622 | CF36BBCA1 | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205550037 | LUXAIRE | TH16B3622 | CF36BXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205550033 | LUXAIRE | TH16B3622 | CF36BXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205550029 | LUXAIRE | TH16B3622 | CF42BXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205550022 | LUXAIRE | TH16B3622 | CF42BXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205550018 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203430945 | LUXAIRE | TH16B3622 | CM36CBCA1 | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205550014 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205550010 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 203087458 | LUXAIRE | TH16B3622 | CM36CBCA1 | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205549998 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205550002 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205549994 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205549990 | LUXAIRE | TH16B3622 | CF42BXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205549986 | LUXAIRE | TH16B3622 | CF42BXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205549982 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 203430923 | LUXAIRE | TH16B3622 | CM42CBCA1 | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205550006 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 203430918 | LUXAIRE | TH16B3622 | CF42CBCA1 | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205549978 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 203087381 | LUXAIRE | TH16B3622 | CM42CBCA1 | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205549974 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 203087365 | LUXAIRE | TH16B3622 | CF42CBCA1 | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205549970 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205549966 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 206780765 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TMLE080B12MP11 | 22,200 | $1,110 |
| No | 206780761 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TMLE080B12MP11 | 22,200 | $1,110 |
| No | 203430907 | LUXAIRE | TH16B3622 | CM48CBCA1 | TMLE080B12MP11 | 22,200 | $1,110 |
| No | 203430901 | LUXAIRE | TH16B3622 | CF48CBCA1 | TMLE080B12MP11 | 22,200 | $1,110 |
| No | 206780757 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TM8E080B12MP11 | 22,200 | $1,110 |
| No | 203087327 | LUXAIRE | TH16B3622 | CM48CBCA1 | TM8E080B12MP11 | 22,200 | $1,110 |
| No | 206780753 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TM8E080B12MP11 | 22,200 | $1,110 |
| No | 203087307 | LUXAIRE | TH16B3622 | CF48CBCA1 | TM8E080B12MP11 | 22,200 | $1,110 |
| No | 206780745 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TM8E080B12MP11 | 22,200 | $1,110 |
| No | 206780749 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TMLE080B12MP11 | 22,200 | $1,110 |
| No | 203430840 | LUXAIRE | TH16B3622 | CM48DBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205549962 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205549958 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203087094 | LUXAIRE | TH16B3622 | CM48DBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205549954 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205549950 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205549946 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205549942 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205549938 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203430813 | LUXAIRE | TH16B3622 | CM36CBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205549934 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205549930 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205549914 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203087005 | LUXAIRE | TH16B3622 | CM36CBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205549910 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205549906 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205549902 | LUXAIRE | TH16B3622 | CF42BXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205549898 | LUXAIRE | TH16B3622 | CF42BXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205549894 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549890 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205549886 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549882 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203430725 | LUXAIRE | TH16B3622 | CM48CBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549926 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 203430719 | LUXAIRE | TH16B3622 | CF48CBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549878 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549922 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203086693 | LUXAIRE | TH16B3622 | CM48CBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203086671 | LUXAIRE | TH16B3622 | CF48CBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205549874 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549918 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205549870 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203430708 | LUXAIRE | TH16B3622 | CM48DBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549866 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549862 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 203086635 | LUXAIRE | TH16B3622 | CM48DBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205549858 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205549854 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205549850 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205549846 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203430697 | LUXAIRE | TH16B3622 | CM36CBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 205549838 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 205549842 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 205549834 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 203098280 | LUXAIRE | TH16B3622 | CM36CBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 205549824 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 205549820 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549816 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206780737 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 203430686 | LUXAIRE | TH16B3622 | CM42CBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206780741 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 203430680 | LUXAIRE | TH16B3622 | CF42CBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206780733 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 203098265 | LUXAIRE | TH16B3622 | CM42CBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206780729 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 203098257 | LUXAIRE | TH16B3622 | CF42CBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206780725 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206780721 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 205549814 | LUXAIRE | TH16B3622 | CU36BXA1+TXV | LPLC080B12MP13 | 22,800 | $1,140 |
| No | 203098055 | LUXAIRE | TH16B3622 | CM36BBCA1 | LPLC080B12MP13 | 22,800 | $1,140 |
| No | 205549832 | LUXAIRE | TH16B3622 | CM36BXA1+TXV | LPLC080B12MP13 | 22,800 | $1,140 |
| No | 203098027 | LUXAIRE | TH16B3622 | CF36BBCA1 | LPLC080B12MP13 | 22,800 | $1,140 |
| No | 205549828 | LUXAIRE | TH16B3622 | CU36BXA1+TXV | TPLC080B12MP13 | 22,800 | $1,140 |
| No | 203098047 | LUXAIRE | TH16B3622 | CM36BBCA1 | TPLC080B12MP13 | 22,800 | $1,140 |
| No | 205549810 | LUXAIRE | TH16B3622 | CM36BXA1+TXV | TPLC080B12MP13 | 22,800 | $1,140 |
| No | 203098019 | LUXAIRE | TH16B3622 | CF36BBCA1 | TPLC080B12MP13 | 22,800 | $1,140 |
| No | 205549798 | LUXAIRE | TH16B3622 | CU36BXA1+TXV | TM8V080B12MP12 | 22,800 | $1,140 |
| No | 203098031 | LUXAIRE | TH16B3622 | CM36BBCA1 | TM8V080B12MP12 | 22,800 | $1,140 |
| No | 205549794 | LUXAIRE | TH16B3622 | CM36BXA1+TXV | TM8V080B12MP12 | 22,800 | $1,140 |
| No | 203098003 | LUXAIRE | TH16B3622 | CF36BBCA1 | TM8V080B12MP12 | 22,800 | $1,140 |
| No | 205549788 | LUXAIRE | TH16B3622 | CF36BXA1+TXV | LPLC080B12MP13 | 22,800 | $1,140 |
| No | 205549784 | LUXAIRE | TH16B3622 | CF36BXA1+TXV | TPLC080B12MP13 | 22,800 | $1,140 |
| No | 205549776 | LUXAIRE | TH16B3622 | CF36BXA1+TXV | TM8V080B12MP12 | 22,800 | $1,140 |
| No | 205549772 | LUXAIRE | TH16B3622 | CU36BXA1+TXV | TM9E060A10MP12 | 23,000 | $1,150 |
| No | 203097959 | LUXAIRE | TH16B3622 | CM36BBCA1 | TM9E060A10MP12 | 23,000 | $1,150 |
| No | 205549790 | LUXAIRE | TH16B3622 | CM36BXA1+TXV | TM9E060A10MP12 | 23,000 | $1,150 |
| No | 203097951 | LUXAIRE | TH16B3622 | CF36BBCA1 | TM9E060A10MP12 | 23,000 | $1,150 |
| No | 205549768 | LUXAIRE | TH16B3622 | CF36BXA1+TXV | TM9E060A10MP12 | 23,000 | $1,150 |
| No | 205549764 | LUXAIRE | TH16B3622 | CF42BXA1+TXV | TM9E060A10MP12 | 22,600 | $1,130 |
| No | 205549760 | LUXAIRE | TH16B3622 | CU36BXA1+TXV | TM9E060B12MP12 | 22,400 | $1,120 |
| No | 203097918 | LUXAIRE | TH16B3622 | CM36BBCA1 | TM9E060B12MP12 | 22,400 | $1,120 |
| No | 205549756 | LUXAIRE | TH16B3622 | CM36BXA1+TXV | TM9E060B12MP12 | 22,400 | $1,120 |
| No | 203097911 | LUXAIRE | TH16B3622 | CF36BBCA1 | TM9E060B12MP12 | 22,400 | $1,120 |
| No | 205549752 | LUXAIRE | TH16B3622 | CF36BXA1+TXV | TM9E060B12MP12 | 22,400 | $1,120 |
| No | 205549748 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203097894 | LUXAIRE | TH16B3622 | CM36CBCA1 | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205549744 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205549740 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205549736 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097790 | LUXAIRE | TH16B3622 | CM36CBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549732 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549728 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549724 | LUXAIRE | TH16B3622 | CF42BXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549720 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097758 | LUXAIRE | TH16B3622 | CM42CBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549716 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097750 | LUXAIRE | TH16B3622 | CF42CBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549712 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549708 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097735 | LUXAIRE | TH16B3622 | CM48CBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097727 | LUXAIRE | TH16B3622 | CF48CBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549704 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205549700 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203097639 | LUXAIRE | TH16B3622 | CM48DBCA1 | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 206780717 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 206780713 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 206780709 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 205549696 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 203097623 | LUXAIRE | TH16B3622 | CM36CBCA1 | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205549692 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205549688 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205549684 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 203097606 | LUXAIRE | TH16B3622 | CM42CBCA1 | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 205549680 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 203097598 | LUXAIRE | TH16B3622 | CF42CBCA1 | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 205549672 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 205549668 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205549664 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205549660 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 203097574 | LUXAIRE | TH16B3622 | CM48CBCA1 | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 205549676 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 203097567 | LUXAIRE | TH16B3622 | CF48CBCA1 | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 205549656 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549652 | LUXAIRE | TH16B3622 | CU36BXA1+TXV | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 205549648 | LUXAIRE | TH16B3622 | CM36BXA1+TXV | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 203097486 | LUXAIRE | TH16B3622 | CF36BBCA1 | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 203097502 | LUXAIRE | TH16B3622 | CM36BBCA1 | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 205549636 | LUXAIRE | TH16B3622 | CF36BXA1+TXV | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 205549628 | LUXAIRE | TH16B3622 | CF42BXA1+TXV | TM8Y080B12MP11 | 22,200 | $1,110 |
| No | 205549616 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TM8Y100C20MP11 | 22,400 | $1,120 |
| No | 203097390 | LUXAIRE | TH16B3622 | CM36CBCA1 | TM8Y100C20MP11 | 22,400 | $1,120 |
| No | 205549612 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TM8Y100C20MP11 | 22,400 | $1,120 |
| No | 205549608 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TM8Y120C20MP11 | 22,400 | $1,120 |
| No | 203097382 | LUXAIRE | TH16B3622 | CM36CBCA1 | TM8Y120C20MP11 | 22,400 | $1,120 |
| No | 205549604 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TM8Y120C20MP11 | 22,400 | $1,120 |
| No | 205549556 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TM8Y100C20MP11 | 22,400 | $1,120 |
| No | 205549552 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TM8Y120C20MP11 | 22,400 | $1,120 |
| No | 205549532 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TM8Y100C20MP11 | 23,200 | $1,160 |
| No | 203097294 | LUXAIRE | TH16B3622 | CM42CBCA1 | TM8Y100C20MP11 | 23,200 | $1,160 |
| No | 205549572 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TM8Y100C20MP11 | 23,200 | $1,160 |
| No | 203097246 | LUXAIRE | TH16B3622 | CF42CBCA1 | TM8Y100C20MP11 | 23,200 | $1,160 |
| No | 205549568 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TM8Y120C20MP11 | 23,200 | $1,160 |
| No | 203097286 | LUXAIRE | TH16B3622 | CM42CBCA1 | TM8Y120C20MP11 | 23,200 | $1,160 |
| No | 205549564 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TM8Y120C20MP11 | 23,200 | $1,160 |
| No | 203097238 | LUXAIRE | TH16B3622 | CF42CBCA1 | TM8Y120C20MP11 | 23,200 | $1,160 |
| No | 205549492 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TM8Y120C20MP11 | 23,200 | $1,160 |
| No | 203097151 | LUXAIRE | TH16B3622 | CM48DBCA1 | TM8Y100C20MP11 | 22,200 | $1,110 |
| No | 205549496 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TM8Y100C20MP11 | 23,200 | $1,160 |
| No | 205549472 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TM8Y100C20MP11 | 22,200 | $1,110 |
| No | 205549468 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TM8Y100C20MP11 | 22,200 | $1,110 |
| No | 203097143 | LUXAIRE | TH16B3622 | CM48DBCA1 | TM8Y120C20MP11 | 22,200 | $1,110 |
| No | 205549464 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TM8Y120C20MP11 | 22,200 | $1,110 |
| No | 205549460 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TM8Y120C20MP11 | 22,200 | $1,110 |
| No | 205549416 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TM8Y100C20MP11 | 22,200 | $1,110 |
| No | 205549412 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TM8Y120C20MP11 | 22,200 | $1,110 |
| No | 205549392 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 203097055 | LUXAIRE | TH16B3622 | CM36CBCA1 | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205549432 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205549384 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205549376 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 203097023 | LUXAIRE | TH16B3622 | CM42CBCA1 | TM9Y080C16MP11 | 22,800 | $1,140 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549372 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 203097008 | LUXAIRE | TH16B3622 | CF42CBCA1 | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205549356 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205549348 | LUXAIRE | TH16B3622 | CF42BXA1+MVC12BN21+TXV | | 22,000 | $1,100 |
| No | 203096738 | LUXAIRE | TH16B3622 | CM36BBCA1+ME12BN21 | | 22,200 | $1,110 |
| No | 205549360 | LUXAIRE | TH16B3622 | CM36BXA1+ME12BN21+TXV | | 22,200 | $1,110 |
| No | 203096731 | LUXAIRE | TH16B3622 | CF36BBCA1+ME12BN21 | | 22,200 | $1,110 |
| No | 205549344 | LUXAIRE | TH16B3622 | CF36BXA1+ME12BN21+TXV | | 22,200 | $1,110 |
| No | 203096682 | LUXAIRE | TH16B3622 | CM48DBCA1+MVC14DN21 | | 21,800 | $1,090 |
| No | 205549336 | LUXAIRE | TH16B3622 | CM48DXA1+MVC14DN21+TXV | | 21,800 | $1,090 |
| No | 205549340 | LUXAIRE | TH16B3622 | CF42BXA1+ME12BN21+TXV | | 22,200 | $1,110 |
| No | 205549332 | LUXAIRE | TH16B3622 | CF48DXA1+MVC14DN21+TXV | | 21,800 | $1,090 |
| No | 205549330 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | LPLC080B12MP13 | 22,400 | $1,120 |
| No | 203096406 | LUXAIRE | TH16B3622 | CM36CBCA1 | LPLC080B12MP13 | 22,400 | $1,120 |
| No | 205549328 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | LPLC080B12MP13 | 22,400 | $1,120 |
| No | 203096399 | LUXAIRE | TH16B3622 | CM36CBCA1 | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 205549320 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 205549324 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 203096383 | LUXAIRE | TH16B3622 | CM36CBCA1 | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205549298 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205549308 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205549296 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | LPLC080B12MP13 | 22,400 | $1,120 |
| No | 205549292 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 205549284 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205549282 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | LPLC080B12MP13 | 22,400 | $1,120 |
| No | 203096266 | LUXAIRE | TH16B3622 | CM42CBCA1 | LPLC080B12MP13 | 22,400 | $1,120 |
| No | 205549306 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | LPLC080B12MP13 | 22,400 | $1,120 |
| No | 203096239 | LUXAIRE | TH16B3622 | CF42CBCA1 | LPLC080B12MP13 | 22,400 | $1,120 |
| No | 205549302 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 203096258 | LUXAIRE | TH16B3622 | CM42CBCA1 | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 203096231 | LUXAIRE | TH16B3622 | CF42CBCA1 | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 205549278 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 205549266 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 203096243 | LUXAIRE | TH16B3622 | CM42CBCA1 | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205549262 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 203096215 | LUXAIRE | TH16B3622 | CF42CBCA1 | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205549254 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | LPLC080B12MP13 | 22,400 | $1,120 |
| No | 205549250 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549242 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205549240 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | LP9C080C16MP13 | 22,200 | $1,110 |
| No | 203096028 | LUXAIRE | TH16B3622 | CM36CBCA1 | LP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549260 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | LP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549256 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 203096020 | LUXAIRE | TH16B3622 | CM36CBCA1 | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549236 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549232 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 203096012 | LUXAIRE | TH16B3622 | CM36CBCA1 | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205549222 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205549220 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | LP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549216 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549212 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205549210 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | LP9C080C16MP13 | 22,200 | $1,110 |
| No | 203095965 | LUXAIRE | TH16B3622 | CM42CBCA1 | LP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549230 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | LP9C080C16MP13 | 22,200 | $1,110 |
| No | 203095945 | LUXAIRE | TH16B3622 | CF42CBCA1 | LP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549226 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 203095957 | LUXAIRE | TH16B3622 | CM42CBCA1 | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549206 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 203095937 | LUXAIRE | TH16B3622 | CF42CBCA1 | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549200 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 203095949 | LUXAIRE | TH16B3622 | CM42CBCA1 | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205549196 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 203095929 | LUXAIRE | TH16B3622 | CF42CBCA1 | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205549194 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | LP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549190 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 205549186 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205549184 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | LP9C080C16MP13 | 22,000 | $1,100 |
| No | 203095880 | LUXAIRE | TH16B3622 | CM48CBCA1 | LP9C080C16MP13 | 22,000 | $1,100 |
| No | 205549204 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | LP9C080C16MP13 | 22,000 | $1,100 |
| No | 203095860 | LUXAIRE | TH16B3622 | CF48CBCA1 | LP9C080C16MP13 | 22,000 | $1,100 |
| No | 205549180 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 203095872 | LUXAIRE | TH16B3622 | CM48CBCA1 | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 205549174 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 203095852 | LUXAIRE | TH16B3622 | CF48CBCA1 | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 205549170 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 203095864 | LUXAIRE | TH16B3622 | CM48CBCA1 | TM9V080C16MP12 | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549166 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 203095844 | LUXAIRE | TH16B3622 | CF48CBCA1 | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 205549160 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 205549164 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | LP9C080C16MP13 | 22,000 | $1,100 |
| No | 205549156 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 203095746 | LUXAIRE | TH16B3622 | AVC42CX21+TXV | | 22,600 | $1,130 |
| No | 205549178 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | LPLC100C16MP13 | 22,200 | $1,110 |
| No | 205549154 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | LPLC100C16MP13 | 22,200 | $1,110 |
| No | 205549152 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | LPLC080C16MP13 | 22,200 | $1,110 |
| No | 203095622 | LUXAIRE | TH16B3622 | CM36CBCA1 | LPLC100C16MP13 | 22,200 | $1,110 |
| No | 203095618 | LUXAIRE | TH16B3622 | CM36CBCA1 | LPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549146 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | LPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549142 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203095610 | LUXAIRE | TH16B3622 | CM36CBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205549138 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205549134 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 203095602 | LUXAIRE | TH16B3622 | CM36CBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549130 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549126 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203095594 | LUXAIRE | TH16B3622 | CM36CBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205549122 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205549110 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203095578 | LUXAIRE | TH16B3622 | CM36CBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205549106 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205549102 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203095570 | LUXAIRE | TH16B3622 | CM36CBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205549098 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205549096 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | LPLC100C16MP13 | 22,200 | $1,110 |
| No | 205549094 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | LPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549090 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205549086 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549074 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205549082 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205549070 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203094728 | LUXAIRE | TH16B3622 | CM48DBCA1 | LPLC100C16MP13 | 22,200 | $1,110 |
| No | 205549150 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | LPLC100C16MP13 | 22,200 | $1,110 |
| No | 205549148 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | LPLC100C16MP13 | 22,200 | $1,110 |
| No | 203094725 | LUXAIRE | TH16B3622 | CM48DBCA1 | LPLC080C16MP13 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205549068 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | LPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549066 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | LPLC080C16MP13 | 22,200 | $1,110 |
| No | 203094717 | LUXAIRE | TH16B3622 | CM48DBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205549058 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203094708 | LUXAIRE | TH16B3622 | CM48DBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549054 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205549050 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205549046 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 203094701 | LUXAIRE | TH16B3622 | CM48DBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205549038 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205549042 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203094685 | LUXAIRE | TH16B3622 | CM48DBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205549026 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205549022 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203094677 | LUXAIRE | TH16B3622 | CM48DBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205549004 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205549000 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205548998 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | LPLC100C16MP13 | 22,200 | $1,110 |
| No | 205548996 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | LPLC080C16MP13 | 22,200 | $1,110 |
| No | 205548992 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205548988 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205548984 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205548976 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205548972 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205548970 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | LPLC120C20MP13 | 22,400 | $1,120 |
| No | 203094502 | LUXAIRE | TH16B3622 | CM36CBCA1 | LPLC120C20MP13 | 22,400 | $1,120 |
| No | 205549064 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | LPLC120C20MP13 | 22,400 | $1,120 |
| No | 203094498 | LUXAIRE | TH16B3622 | CM36CBCA1 | LPLC100C20MP13 | 22,400 | $1,120 |
| No | 205549016 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205549062 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | LPLC100C20MP13 | 22,400 | $1,120 |
| No | 205549020 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | LPLC100C20MP13 | 22,400 | $1,120 |
| No | 203094490 | LUXAIRE | TH16B3622 | CM36CBCA1 | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205549012 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205549008 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 203094482 | LUXAIRE | TH16B3622 | CM36CBCA1 | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548966 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548962 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 203094475 | LUXAIRE | TH16B3622 | CM36CBCA1 | TMLV120C20MP12 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205548958 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548946 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 203094459 | LUXAIRE | TH16B3622 | CM36CBCA1 | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548942 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548938 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 203094451 | LUXAIRE | TH16B3622 | CM36CBCA1 | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548934 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548932 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | LPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548930 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | LPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548926 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548922 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548918 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548910 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548906 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548904 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | LPLC120C20MP13 | 22,400 | $1,120 |
| No | 203094221 | LUXAIRE | TH16B3622 | CM42CBCA1 | LPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548902 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | LPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548900 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | LPLC100C20MP13 | 22,400 | $1,120 |
| No | 203094166 | LUXAIRE | TH16B3622 | CF42CBCA1 | LPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548898 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | LPLC100C20MP13 | 22,400 | $1,120 |
| No | 203094162 | LUXAIRE | TH16B3622 | CF42CBCA1 | LPLC100C20MP13 | 22,400 | $1,120 |
| No | 203094217 | LUXAIRE | TH16B3622 | CM42CBCA1 | LPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548894 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 203094210 | LUXAIRE | TH16B3622 | CM42CBCA1 | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 203094154 | LUXAIRE | TH16B3622 | CF42CBCA1 | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548886 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548890 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 203094201 | LUXAIRE | TH16B3622 | CM42CBCA1 | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548882 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 203094145 | LUXAIRE | TH16B3622 | CF42CBCA1 | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 203094194 | LUXAIRE | TH16B3622 | CM42CBCA1 | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548878 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548874 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 203094137 | LUXAIRE | TH16B3622 | CF42CBCA1 | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548859 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 203094177 | LUXAIRE | TH16B3622 | CM42CBCA1 | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548850 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 203094121 | LUXAIRE | TH16B3622 | CF42CBCA1 | TM8V100C20MP12 | 22,400 | $1,120 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203094170 | LUXAIRE | TH16B3622 | CM42CBCA1 | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548842 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548832 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 203094114 | LUXAIRE | TH16B3622 | CF42CBCA1 | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548816 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | LPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548810 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548806 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548802 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548814 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | LPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548794 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548790 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548788 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | LPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548786 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | LPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548782 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548778 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548774 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548766 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548762 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548760 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | LPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548758 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | LPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548754 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205548750 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205548746 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205548738 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205548734 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205548730 | LUXAIRE | TH16B3622 | CU36BXA1+TXV | TM8Y080B12MP11 | 22,000 | $1,100 |
| No | 203093062 | LUXAIRE | TH16B3622 | CM36BBCA1 | TM8Y080B12MP11 | 22,000 | $1,100 |
| No | 205548826 | LUXAIRE | TH16B3622 | CM36BXA1+TXV | TM8Y080B12MP11 | 22,000 | $1,100 |
| No | 203093008 | LUXAIRE | TH16B3622 | CF36BBCA1 | TM8Y080B12MP11 | 22,000 | $1,100 |
| No | 205548718 | LUXAIRE | TH16B3622 | CF36BXA1+TXV | TM8Y080B12MP11 | 22,000 | $1,100 |
| No | 205548706 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205548702 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 203092676 | LUXAIRE | TH16B3622 | CM42CBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 203092561 | LUXAIRE | TH16B3622 | CF42CBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205548698 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203092657 | LUXAIRE | TH16B3622 | CM42CBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205548694 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203092541 | LUXAIRE | TH16B3622 | CF42CBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205548650 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205548630 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205548654 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205548626 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205548606 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205548582 | LUXAIRE | TH16B3622 | CF42BXA1+TXV | TM9Y080B12MP11 | 22,000 | $1,100 |
| No | 205548602 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205548574 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205548570 | LUXAIRE | TH16B3622 | CM36CBCA1 | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205548566 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205548554 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205548546 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548542 | LUXAIRE | TH16B3622 | CM48CBCA1 | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548538 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548534 | LUXAIRE | TH16B3622 | CF48CBCA1 | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548526 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548514 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548510 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548518 | LUXAIRE | TH16B3622 | CM48DBCA1 | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548488 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205548390 | LUXAIRE | TH16B3622 | CF42BXA1+TXV | LP9C080B12MP13 | 22,200 | $1,110 |
| No | 205548386 | LUXAIRE | TH16B3622 | CF42BXA1+TXV | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 205548382 | LUXAIRE | TH16B3622 | CF42BXA1+TXV | TM9V080B12MP12 | 22,200 | $1,110 |
| No | 205548380 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | LP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548504 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | LP9C100C16MP13 | 21,800 | $1,090 |
| No | 203090009 | LUXAIRE | TH16B3622 | CF48CBCA1 | LP9C100C16MP13 | 21,800 | $1,090 |
| No | 203090057 | LUXAIRE | TH16B3622 | CM48CBCA1 | LP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548500 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 203090038 | LUXAIRE | TH16B3622 | CM48CBCA1 | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548412 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 203089991 | LUXAIRE | TH16B3622 | CF48CBCA1 | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548408 | LUXAIRE | TH16B3622 | CU48CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 203090019 | LUXAIRE | TH16B3622 | CM48CBCA1 | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205548376 | LUXAIRE | TH16B3622 | CM48CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 203089973 | LUXAIRE | TH16B3622 | CF48CBCA1 | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205548370 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548374 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | LP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548366 | LUXAIRE | TH16B3622 | CF48CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203089870 | LUXAIRE | TH16B3622 | CM48DBCA1 | LP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548364 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | LP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548362 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | LP9C100C16MP13 | 21,800 | $1,090 |
| No | 203089855 | LUXAIRE | TH16B3622 | CM48DBCA1 | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548356 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548352 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 203089836 | LUXAIRE | TH16B3622 | CM48DBCA1 | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205548348 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205548344 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205548338 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548342 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | LP9C100C16MP13 | 21,800 | $1,090 |
| No | 205548334 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 203089685 | LUXAIRE | TH16B3622 | CM36CBCA1 | LP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548332 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | LP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548330 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | LP9C100C20MP13 | 22,400 | $1,120 |
| No | 203089667 | LUXAIRE | TH16B3622 | CM36CBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548322 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548326 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548318 | LUXAIRE | TH16B3622 | CU36CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203089647 | LUXAIRE | TH16B3622 | CM36CBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205548314 | LUXAIRE | TH16B3622 | CM36CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205548312 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | LP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548308 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548304 | LUXAIRE | TH16B3622 | CF36CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205548302 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | LP9C100C20MP13 | 22,400 | $1,120 |
| No | 203089456 | LUXAIRE | TH16B3622 | CM42CBCA1 | LP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548360 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | LP9C100C20MP13 | 22,400 | $1,120 |
| No | 203089412 | LUXAIRE | TH16B3622 | CF42CBCA1 | LP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548298 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 203089439 | LUXAIRE | TH16B3622 | CM42CBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 203089393 | LUXAIRE | TH16B3622 | CF42CBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548286 | LUXAIRE | TH16B3622 | CU42CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205548290 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 203089420 | LUXAIRE | TH16B3622 | CM42CBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205548282 | LUXAIRE | TH16B3622 | CM42CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203089377 | LUXAIRE | TH16B3622 | CF42CBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205548280 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | LP9C100C20MP13 | 22,400 | $1,120 |
| No | 205548276 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205548272 | LUXAIRE | TH16B3622 | CF42CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 206780707 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | LP9C120D20MP13 | 22,000 | $1,100 |
| No | 206780703 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 206780699 | LUXAIRE | TH16B3622 | CM42DXA1+TXV | TM9V120D20MP12 | 22,000 | $1,100 |
| No | 206780697 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | LP9C120D20MP13 | 22,000 | $1,100 |
| No | 206780693 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 206780689 | LUXAIRE | TH16B3622 | CF42DXA1+TXV | TM9V120D20MP12 | 22,000 | $1,100 |
| No | 203088579 | LUXAIRE | TH16B3622 | CM48DBCA1 | LP9C120D20MP13 | 22,000 | $1,100 |
| No | 205548296 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | LP9C120D20MP13 | 22,000 | $1,100 |
| No | 205548294 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | LP9C120D20MP13 | 22,000 | $1,100 |
| No | 203088562 | LUXAIRE | TH16B3622 | CM48DBCA1 | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 205548268 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 205548264 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 203088544 | LUXAIRE | TH16B3622 | CM48DBCA1 | TM9V120D20MP12 | 22,000 | $1,100 |
| No | 205548260 | LUXAIRE | TH16B3622 | CU48DXA1+TXV | TM9V120D20MP12 | 22,000 | $1,100 |
| No | 205548256 | LUXAIRE | TH16B3622 | CM48DXA1+TXV | TM9V120D20MP12 | 22,000 | $1,100 |
| No | 205548254 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | LP9C120D20MP13 | 22,000 | $1,100 |
| No | 205548246 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TM9V120D20MP12 | 22,000 | $1,100 |
| No | 203088479 | LUXAIRE | TH16B3622 | CM48DBCA1+MVC20DN21 | | 22,000 | $1,100 |
| No | 205548250 | LUXAIRE | TH16B3622 | CF48DXA1+TXV | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 205548098 | LUXAIRE | TH16B3622 | CM48DXA1+MVC20DN21+TXV | | 22,000 | $1,100 |
| No | 205548094 | LUXAIRE | TH16B3622 | CF48DXA1+MVC20DN21+TXV | | 22,000 | $1,100 |
| No | 205548090 | LUXAIRE | TH16B3622 | CM42DXA1+MVC20DN21+TXV | | 22,000 | $1,100 |
| No | 205548086 | LUXAIRE | TH16B3622 | CF42DXA1+MVC20DN21+TXV | | 22,000 | $1,100 |
| No | 205548082 | LUXAIRE | TH16B3622 | CM42DXA1+MVC14DN21+TXV | | 22,200 | $1,110 |
| No | 205548078 | LUXAIRE | TH16B3622 | CF42DXA1+MVC14DN21+TXV | | 22,200 | $1,110 |
| No | 205074558 | LUXAIRE | TH16B2421 | CM30AXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205074550 | LUXAIRE | TH16B2421 | CF30AXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205074305 | LUXAIRE | TH16B2421 | CF30ABAA1 | TL8E060A12UH11 | 15,100 | $755 |
| No | 205546768 | LUXAIRE | TH16B2421 | CM36AXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205546764 | LUXAIRE | TH16B2421 | CF36AXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205546760 | LUXAIRE | TH16B4821 | CM48DBCA1 | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 205546756 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 205546752 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 205546748 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 205546716 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TL8E100C20UH11 | 28,200 | $1,410 |
| No | 205546712 | LUXAIRE | TH16B4821 | CM48CBCA1 | TL8E100C20UH11 | 28,200 | $1,410 |
| No | 205546708 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TL8E100C20UH11 | 28,200 | $1,410 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205546704 | LUXAIRE | TH16B4821 | CF48CBCA1 | TL8E100C20UH11 | 28,200 | $1,410 |
| No | 205546700 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TL8E100C20UH11 | 28,200 | $1,410 |
| No | 205546696 | LUXAIRE | TH16B4821 | CM48DBCA1 | TL8E100C20UH11 | 28,600 | $1,430 |
| No | 205546692 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TL8E100C20UH11 | 28,600 | $1,430 |
| No | 205546688 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TL8E100C20UH11 | 28,600 | $1,430 |
| No | 205546684 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TL8E100C20UH11 | 28,600 | $1,430 |
| No | 205546680 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TL8E100C20UH11 | 29,400 | $1,470 |
| No | 205546676 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TL8E100C20UH11 | 29,400 | $1,470 |
| No | 205546672 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205546668 | LUXAIRE | TH16B4821 | CM48CBCA1 | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205546664 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205546660 | LUXAIRE | TH16B4821 | CF48CBCA1 | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205546656 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205546652 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TL9E100C20UH11 | 28,400 | $1,420 |
| No | 205546648 | LUXAIRE | TH16B4821 | CM48CBCA1 | TL9E100C20UH11 | 28,400 | $1,420 |
| No | 205546644 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TL9E100C20UH11 | 28,400 | $1,420 |
| No | 205546640 | LUXAIRE | TH16B4821 | CF48CBCA1 | TL9E100C20UH11 | 28,400 | $1,420 |
| No | 205546636 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TL9E100C20UH11 | 28,400 | $1,420 |
| No | 205546632 | LUXAIRE | TH16B4821 | CM48DBCA1 | TL9E100C20UH11 | 28,600 | $1,430 |
| No | 205546628 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TL9E100C20UH11 | 28,600 | $1,430 |
| No | 205546624 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TL9E100C20UH11 | 28,600 | $1,430 |
| No | 205546620 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TL9E100C20UH11 | 28,600 | $1,430 |
| No | 205546616 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TL9E100C20UH11 | 30,400 | $1,520 |
| No | 205546608 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TMLE080B12MP11 | 28,000 | $1,400 |
| No | 205546612 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TL9E100C20UH11 | 30,400 | $1,520 |
| No | 203431428 | LUXAIRE | TH16B4821 | CM48CBCA1 | TMLE080B12MP11 | 28,000 | $1,400 |
| No | 205546744 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TMLE080B12MP11 | 28,000 | $1,400 |
| No | 203431417 | LUXAIRE | TH16B4821 | CF48CBCA1 | TMLE080B12MP11 | 28,000 | $1,400 |
| No | 205546740 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TM8E080B12MP11 | 28,000 | $1,400 |
| No | 203431423 | LUXAIRE | TH16B4821 | CM48CBCA1 | TM8E080B12MP11 | 28,000 | $1,400 |
| No | 205546736 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TM8E080B12MP11 | 28,000 | $1,400 |
| No | 203431412 | LUXAIRE | TH16B4821 | CF48CBCA1 | TM8E080B12MP11 | 28,000 | $1,400 |
| No | 205546728 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TMLE080B12MP11 | 28,000 | $1,400 |
| No | 205546724 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TM8E080B12MP11 | 28,000 | $1,400 |
| No | 205546720 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TMLE080C16MP11 | 28,600 | $1,430 |
| No | 203431385 | LUXAIRE | TH16B4821 | CM48CBCA1 | TMLE080C16MP11 | 28,600 | $1,430 |
| No | 205546732 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TMLE080C16MP11 | 28,600 | $1,430 |
| No | 203431374 | LUXAIRE | TH16B4821 | CF48CBCA1 | TMLE080C16MP11 | 28,600 | $1,430 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205546604 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TM8E080C16MP11 | 28,600 | $1,430 |
| No | 203431379 | LUXAIRE | TH16B4821 | CM48CBCA1 | TM8E080C16MP11 | 28,600 | $1,430 |
| No | 205546600 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TM8E080C16MP11 | 28,600 | $1,430 |
| No | 203431368 | LUXAIRE | TH16B4821 | CF48CBCA1 | TM8E080C16MP11 | 28,600 | $1,430 |
| No | 205546596 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TMLE080C16MP11 | 28,600 | $1,430 |
| No | 205546592 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TM8E080C16MP11 | 28,600 | $1,430 |
| No | 203431352 | LUXAIRE | TH16B4821 | CM48DBCA1 | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 205546588 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 205546584 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 203431346 | LUXAIRE | TH16B4821 | CM48DBCA1 | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205546580 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205546576 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205546572 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 205546568 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205085181 | LUXAIRE | TH16B4821 | CU60DXA2+TXV | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 205085175 | LUXAIRE | TH16B4821 | CM60DXA2+TXV | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 205085169 | LUXAIRE | TH16B4821 | CU60DXA2+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205085165 | LUXAIRE | TH16B4821 | CM60DXA2+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205085161 | LUXAIRE | TH16B4821 | CF60DXA2+TXV | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 205085151 | LUXAIRE | TH16B4821 | CF60DXA2+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205546556 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TMLE080C16MP11 | 30,600 | $1,530 |
| No | 205546551 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TM8E080C16MP11 | 30,600 | $1,530 |
| No | 205546546 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TMLE080C16MP11 | 30,600 | $1,530 |
| No | 205546541 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TM8E080C16MP11 | 30,600 | $1,530 |
| No | 205546537 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TMLE100B12MP11 | 27,800 | $1,390 |
| No | 203431286 | LUXAIRE | TH16B4821 | CM48CBCA1 | TMLE100B12MP11 | 27,800 | $1,390 |
| No | 205546564 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TMLE100B12MP11 | 27,800 | $1,390 |
| No | 203431275 | LUXAIRE | TH16B4821 | CF48CBCA1 | TMLE100B12MP11 | 27,800 | $1,390 |
| No | 205546560 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TM8E100B12MP11 | 27,800 | $1,390 |
| No | 203431281 | LUXAIRE | TH16B4821 | CM48CBCA1 | TM8E100B12MP11 | 27,800 | $1,390 |
| No | 203431270 | LUXAIRE | TH16B4821 | CF48CBCA1 | TM8E100B12MP11 | 27,800 | $1,390 |
| No | 205546532 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TM8E100B12MP11 | 27,800 | $1,390 |
| No | 205546528 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TMLE100B12MP11 | 27,800 | $1,390 |
| No | 205546518 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205546523 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TM8E100B12MP11 | 27,800 | $1,390 |
| No | 203431248 | LUXAIRE | TH16B4821 | CM48CBCA1 | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205546513 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 203431237 | LUXAIRE | TH16B4821 | CF48CBCA1 | TMLE100C16MP11 | 28,000 | $1,400 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205546509 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 203431242 | LUXAIRE | TH16B4821 | CM48CBCA1 | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 205546504 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 203431231 | LUXAIRE | TH16B4821 | CF48CBCA1 | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 205546499 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205546495 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 206781499 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TMLE100C16MP11 | 30,600 | $1,530 |
| No | 206781495 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TM8E100C16MP11 | 30,600 | $1,530 |
| No | 206781491 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TMLE100C16MP11 | 30,600 | $1,530 |
| No | 206781487 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TM8E100C16MP11 | 30,600 | $1,530 |
| No | 205084983 | LUXAIRE | TH16B4821 | CU60CXA2+TXV | TMLE100C20MP11 | 27,200 | $1,360 |
| No | 205084978 | LUXAIRE | TH16B4821 | CM60CXA2+TXV | TMLE100C20MP11 | 27,200 | $1,360 |
| No | 205084972 | LUXAIRE | TH16B4821 | CU60CXA2+TXV | TM8E100C20MP11 | 27,200 | $1,360 |
| No | 205084966 | LUXAIRE | TH16B4821 | CM60CXA2+TXV | TM8E100C20MP11 | 27,200 | $1,360 |
| No | 205084961 | LUXAIRE | TH16B4821 | CF60CXA2+TXV | TMLE100C20MP11 | 27,200 | $1,360 |
| No | 205084955 | LUXAIRE | TH16B4821 | CF60CXA2+TXV | TM8E100C20MP11 | 27,200 | $1,360 |
| No | 205084949 | LUXAIRE | TH16B4821 | CU60DXA2+TXV | TMLE100C20MP11 | 27,400 | $1,370 |
| No | 205084943 | LUXAIRE | TH16B4821 | CM60DXA2+TXV | TMLE100C20MP11 | 27,400 | $1,370 |
| No | 205084937 | LUXAIRE | TH16B4821 | CU60DXA2+TXV | TM8E100C20MP11 | 27,400 | $1,370 |
| No | 205084931 | LUXAIRE | TH16B4821 | CM60DXA2+TXV | TM8E100C20MP11 | 27,400 | $1,370 |
| No | 205084926 | LUXAIRE | TH16B4821 | CF60DXA2+TXV | TMLE100C20MP11 | 27,400 | $1,370 |
| No | 205084919 | LUXAIRE | TH16B4821 | CF60DXA2+TXV | TM8E100C20MP11 | 27,400 | $1,370 |
| No | 203431105 | LUXAIRE | TH16B4821 | CM48DBCA1 | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 205546490 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 205546486 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 203431099 | LUXAIRE | TH16B4821 | CM48DBCA1 | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 205546480 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 205546476 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 205546471 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 205546466 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 205084880 | LUXAIRE | TH16B4821 | CU60CXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205084876 | LUXAIRE | TH16B4821 | CM60CXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205084872 | LUXAIRE | TH16B4821 | CU60CXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 205084865 | LUXAIRE | TH16B4821 | CM60CXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 205084860 | LUXAIRE | TH16B4821 | CF60CXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205084854 | LUXAIRE | TH16B4821 | CF60CXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 205084848 | LUXAIRE | TH16B4821 | CU60DXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205084842 | LUXAIRE | TH16B4821 | CM60DXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205084836 | LUXAIRE | TH16B4821 | CU60DXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 205084824 | LUXAIRE | TH16B4821 | CF60DXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205084830 | LUXAIRE | TH16B4821 | CM60DXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 205084818 | LUXAIRE | TH16B4821 | CF60DXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 205546436 | LUXAIRE | TH16B4821 | CM48DBCA1 | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 205546431 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 205546427 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 205546422 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 205084742 | LUXAIRE | TH16B4821 | CU60CXA2+TXV | TM9E080C20MP12 | 27,200 | $1,360 |
| No | 205084736 | LUXAIRE | TH16B4821 | CM60CXA2+TXV | TM9E080C20MP12 | 27,200 | $1,360 |
| No | 205084725 | LUXAIRE | TH16B4821 | CU60DXA2+TXV | TM9E080C20MP12 | 27,600 | $1,380 |
| No | 205084731 | LUXAIRE | TH16B4821 | CF60CXA2+TXV | TM9E080C20MP12 | 27,200 | $1,360 |
| No | 205084719 | LUXAIRE | TH16B4821 | CM60DXA2+TXV | TM9E080C20MP12 | 27,600 | $1,380 |
| No | 205084713 | LUXAIRE | TH16B4821 | CF60DXA2+TXV | TM9E080C20MP12 | 27,600 | $1,380 |
| No | 205546454 | LUXAIRE | TH16B4821 | CM48DBCA1 | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205546450 | LUXAIRE | TH16B4821 | CU48DXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205546445 | LUXAIRE | TH16B4821 | CM48DXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205546440 | LUXAIRE | TH16B4821 | CF48DXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205084707 | LUXAIRE | TH16B4821 | CU60DXA2+TXV | TM9E100C16MP12 | 28,000 | $1,400 |
| No | 205084701 | LUXAIRE | TH16B4821 | CM60DXA2+TXV | TM9E100C16MP12 | 28,000 | $1,400 |
| No | 205084696 | LUXAIRE | TH16B4821 | CF60DXA2+TXV | TM9E100C16MP12 | 28,000 | $1,400 |
| No | 205546461 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TM9E100C16MP12 | 28,800 | $1,440 |
| No | 205546320 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TM9E100C16MP12 | 28,800 | $1,440 |
| No | 205084690 | LUXAIRE | TH16B4821 | CU60CXA2+TXV | TM9E100C20MP12 | 27,200 | $1,360 |
| No | 205084684 | LUXAIRE | TH16B4821 | CM60CXA2+TXV | TM9E100C20MP12 | 27,200 | $1,360 |
| No | 205084678 | LUXAIRE | TH16B4821 | CF60CXA2+TXV | TM9E100C20MP12 | 27,200 | $1,360 |
| No | 205546316 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TL8E100C20UH11 | 32,800 | $1,640 |
| No | 205546312 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TL8E100C20UH11 | 32,800 | $1,640 |
| No | 205546308 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TL9E100C20UH11 | 32,800 | $1,640 |
| No | 205546304 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TL9E100C20UH11 | 32,800 | $1,640 |
| No | 205546300 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TMLE080C20MP11 | 32,600 | $1,630 |
| No | 205546292 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TMLE080C20MP11 | 32,600 | $1,630 |
| No | 205546296 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TM8E080C20MP11 | 32,600 | $1,630 |
| No | 206782995 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TMLE120C16MP11 | 32,800 | $1,640 |
| No | 205546288 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TM8E080C20MP11 | 32,600 | $1,630 |
| No | 206782991 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TM8E120C16MP11 | 32,800 | $1,640 |
| No | 206782987 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TMLE120C16MP11 | 32,800 | $1,640 |
| No | 206782983 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TM8E120C16MP11 | 32,800 | $1,640 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205546284 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TM9E080C20MP12 | 32,600 | $1,630 |
| No | 205546280 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TM9E080C20MP12 | 32,600 | $1,630 |
| No | 205546276 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TM9E100C20MP12 | 32,600 | $1,630 |
| No | 205546272 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TM9E100C20MP12 | 32,600 | $1,630 |
| No | 205546268 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TM9E120D20MP12 | 33,200 | $1,660 |
| No | 205546264 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TM9E120D20MP12 | 33,200 | $1,660 |
| No | 206838936 | LUXAIRE | TH16B2421 | CM36AXA1+TXV | TPLC060A12MP13 | 15,000 | $750 |
| No | 206838932 | LUXAIRE | TH16B2421 | CM36AXA1+TXV | TMLV060A12MP12 | 15,000 | $750 |
| No | 206838928 | LUXAIRE | TH16B2421 | CM36AXA1+TXV | TM8V060A12MP12 | 15,000 | $750 |
| No | 206838924 | LUXAIRE | TH16B2421 | CF36AXA1+TXV | TPLC060A12MP13 | 15,000 | $750 |
| No | 206838920 | LUXAIRE | TH16B2421 | CF36AXA1+TXV | TMLV060A12MP12 | 15,000 | $750 |
| No | 206838916 | LUXAIRE | TH16B2421 | CF36AXA1+TXV | TM8V060A12MP12 | 15,000 | $750 |
| No | 206779720 | LUXAIRE | TH16B2421 | CU24BXA1+TXV | LPLC080B12MP13 | 15,100 | $755 |
| No | 206779719 | LUXAIRE | TH16B2421 | CM24BBAA1 | LPLC080B12MP13 | 15,100 | $755 |
| No | 206779718 | LUXAIRE | TH16B2421 | CM24BXA1+TXV | LPLC080B12MP13 | 15,100 | $755 |
| No | 202102059 | LUXAIRE | TH16B2421 | CF24BBAA1 | LPLC080B12MP13 | 15,100 | $755 |
| No | 206779715 | LUXAIRE | TH16B2421 | CU24BXA1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 206779711 | LUXAIRE | TH16B2421 | CM24BBAA1 | TPLC080B12MP13 | 15,100 | $755 |
| No | 206779707 | LUXAIRE | TH16B2421 | CM24BXA1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 202102053 | LUXAIRE | TH16B2421 | CF24BBAA1 | TPLC080B12MP13 | 15,100 | $755 |
| No | 206780685 | LUXAIRE | TH16B2421 | CU24BXA1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 206780681 | LUXAIRE | TH16B2421 | CM24BBAA1 | TM8V080B12MP12 | 15,100 | $755 |
| No | 206780677 | LUXAIRE | TH16B2421 | CM24BXA1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 202102038 | LUXAIRE | TH16B2421 | CF24BBAA1 | TM8V080B12MP12 | 15,100 | $755 |
| No | 206780657 | LUXAIRE | TH16B2421 | CF24BXA1+TXV | LPLC080B12MP13 | 15,100 | $755 |
| No | 206780654 | LUXAIRE | TH16B2421 | CF24BXA1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 206780650 | LUXAIRE | TH16B2421 | CF24BXA1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 206780603 | LUXAIRE | TH16B2421 | CU36BXA1+TXV | LPLC080B12MP13 | 15,000 | $750 |
| No | 206780601 | LUXAIRE | TH16B2421 | CM36BXA1+TXV | LPLC080B12MP13 | 15,000 | $750 |
| No | 206780602 | LUXAIRE | TH16B2421 | CM36BBAA1 | LPLC080B12MP13 | 15,000 | $750 |
| No | 206780600 | LUXAIRE | TH16B2421 | CF36BBAA1 | LPLC080B12MP13 | 15,000 | $750 |
| No | 206780597 | LUXAIRE | TH16B2421 | CU36BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780593 | LUXAIRE | TH16B2421 | CM36BBAA1 | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780589 | LUXAIRE | TH16B2421 | CM36BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780585 | LUXAIRE | TH16B2421 | CF36BBAA1 | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780581 | LUXAIRE | TH16B2421 | CU36BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780577 | LUXAIRE | TH16B2421 | CM36BBAA1 | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780573 | LUXAIRE | TH16B2421 | CM36BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780567 | LUXAIRE | TH16B2421 | CF36BXA1+TXV | LPLC080B12MP13 | 15,000 | $750 |
| No | 206780569 | LUXAIRE | TH16B2421 | CF36BBAA1 | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780564 | LUXAIRE | TH16B2421 | CF36BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206780560 | LUXAIRE | TH16B2421 | CF36BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206780558 | LUXAIRE | TH16B2421 | CU36CXA1+TXV | LPLC100C16MP13 | 15,100 | $755 |
| No | 206780556 | LUXAIRE | TH16B2421 | CM36CXA1+TXV | LPLC100C16MP13 | 15,100 | $755 |
| No | 206780552 | LUXAIRE | TH16B2421 | CM36CXA1+TXV | LPLC080C16MP13 | 15,100 | $755 |
| No | 206780548 | LUXAIRE | TH16B2421 | CU36CXA1+TXV | TPLC100C16MP13 | 15,100 | $755 |
| No | 206780554 | LUXAIRE | TH16B2421 | CU36CXA1+TXV | LPLC080C16MP13 | 15,100 | $755 |
| No | 206780544 | LUXAIRE | TH16B2421 | CM36CXA1+TXV | TPLC100C16MP13 | 15,100 | $755 |
| No | 206780540 | LUXAIRE | TH16B2421 | CU36CXA1+TXV | TPLC080C16MP13 | 15,100 | $755 |
| No | 206780536 | LUXAIRE | TH16B2421 | CM36CXA1+TXV | TPLC080C16MP13 | 15,100 | $755 |
| No | 206780532 | LUXAIRE | TH16B2421 | CU36CXA1+TXV | TMLV100C16MP12 | 15,100 | $755 |
| No | 206780528 | LUXAIRE | TH16B2421 | CM36CXA1+TXV | TMLV100C16MP12 | 15,100 | $755 |
| No | 206780524 | LUXAIRE | TH16B2421 | CU36CXA1+TXV | TM8V080C16MP12 | 15,100 | $755 |
| No | 206780520 | LUXAIRE | TH16B2421 | CM36CXA1+TXV | TM8V080C16MP12 | 15,100 | $755 |
| No | 206780516 | LUXAIRE | TH16B2421 | CU36CXA1+TXV | TM8V100C16MP12 | 15,100 | $755 |
| No | 206780512 | LUXAIRE | TH16B2421 | CM36CXA1+TXV | TM8V100C16MP12 | 15,100 | $755 |
| No | 206780510 | LUXAIRE | TH16B2421 | CF36CXA1+TXV | LPLC100C16MP13 | 15,100 | $755 |
| No | 206780504 | LUXAIRE | TH16B2421 | CF36CXA1+TXV | TPLC100C16MP13 | 15,100 | $755 |
| No | 206780500 | LUXAIRE | TH16B2421 | CF36CXA1+TXV | TPLC080C16MP13 | 15,100 | $755 |
| No | 206780508 | LUXAIRE | TH16B2421 | CF36CXA1+TXV | LPLC080C16MP13 | 15,100 | $755 |
| No | 206780496 | LUXAIRE | TH16B2421 | CF36CXA1+TXV | TMLV100C16MP12 | 15,100 | $755 |
| No | 206780492 | LUXAIRE | TH16B2421 | CF36CXA1+TXV | TM8V080C16MP12 | 15,100 | $755 |
| No | 205545600 | LUXAIRE | TH16B2421 | CM30BBAA1 | TM9Y060B12MP11 | 15,300 | $765 |
| No | 206780488 | LUXAIRE | TH16B2421 | CF36CXA1+TXV | TM8V100C16MP12 | 15,100 | $755 |
| No | 205545608 | LUXAIRE | TH16B2421 | CU30BXA1+TXV | TM9Y060B12MP11 | 15,300 | $765 |
| No | 205545592 | LUXAIRE | TH16B2421 | CM30BXA1+TXV | TM9Y060B12MP11 | 15,300 | $765 |
| No | 205545584 | LUXAIRE | TH16B2421 | CF30BBAA1 | TM9Y060B12MP11 | 15,300 | $765 |
| No | 205545539 | LUXAIRE | TH16B2421 | CF30BXA1+TXV | TM9Y060B12MP11 | 15,300 | $765 |
| No | 205074544 | LUXAIRE | TH16B2421 | CM30AXA1+TXV | TM9V040A10MP12 | 15,100 | $755 |
| No | 202143778 | LUXAIRE | TH16B2421 | CF30ABAA1 | TM9V040A10MP12 | 15,100 | $755 |
| No | 205074538 | LUXAIRE | TH16B2421 | CF30AXA1+TXV | TM9V040A10MP12 | 15,100 | $755 |
| No | 205546396 | LUXAIRE | TH16B2421 | CM36AXA1+TXV | TM9V040A10MP12 | 15,000 | $750 |
| No | 205546392 | LUXAIRE | TH16B2421 | CF36AXA1+TXV | TM9V040A10MP12 | 15,000 | $750 |
| No | 206780082 | LUXAIRE | TH16B2421 | CU24BXA1+TXV | LP9C060B12MP13 | 15,200 | $760 |
| No | 206780080 | LUXAIRE | TH16B2421 | CM24BBAA1 | LP9C060B12MP13 | 15,200 | $760 |
| No | 206780078 | LUXAIRE | TH16B2421 | CM24BXA1+TXV | LP9C060B12MP13 | 15,200 | $760 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202101778 | LUXAIRE | TH16B2421 | CF24BBAA1 | LP9C060B12MP13 | 15,200 | $760 |
| No | 206780144 | LUXAIRE | TH16B2421 | CU24BXA1+TXV | TP9C060B12MP13 | 15,200 | $760 |
| No | 206780140 | LUXAIRE | TH16B2421 | CM24BBAA1 | TP9C060B12MP13 | 15,200 | $760 |
| No | 206780136 | LUXAIRE | TH16B2421 | CM24BXA1+TXV | TP9C060B12MP13 | 15,200 | $760 |
| No | 202101776 | LUXAIRE | TH16B2421 | CF24BBAA1 | TP9C060B12MP13 | 15,200 | $760 |
| No | 206780132 | LUXAIRE | TH16B2421 | CU24BXA1+TXV | TM9V060B12MP12 | 15,200 | $760 |
| No | 206780128 | LUXAIRE | TH16B2421 | CM24BBAA1 | TM9V060B12MP12 | 15,200 | $760 |
| No | 206780124 | LUXAIRE | TH16B2421 | CM24BXA1+TXV | TM9V060B12MP12 | 15,200 | $760 |
| No | 206780052 | LUXAIRE | TH16B2421 | CF24BXA1+TXV | LP9C060B12MP13 | 15,200 | $760 |
| No | 206780048 | LUXAIRE | TH16B2421 | CF24BXA1+TXV | TP9C060B12MP13 | 15,200 | $760 |
| No | 202101772 | LUXAIRE | TH16B2421 | CF24BBAA1 | TM9V060B12MP12 | 15,200 | $760 |
| No | 206780044 | LUXAIRE | TH16B2421 | CF24BXA1+TXV | TM9V060B12MP12 | 15,200 | $760 |
| No | 206780038 | LUXAIRE | TH16B2421 | CM30BXA1+TXV | LP9C060B12MP13 | 15,400 | $770 |
| No | 206780036 | LUXAIRE | TH16B2421 | CF30BBAA1 | LP9C060B12MP13 | 15,400 | $770 |
| No | 206780040 | LUXAIRE | TH16B2421 | CM30BBAA1 | LP9C060B12MP13 | 15,400 | $770 |
| No | 206780042 | LUXAIRE | TH16B2421 | CU30BXA1+TXV | LP9C060B12MP13 | 15,400 | $770 |
| No | 206780032 | LUXAIRE | TH16B2421 | CU30BXA1+TXV | TP9C060B12MP13 | 15,400 | $770 |
| No | 206780028 | LUXAIRE | TH16B2421 | CM30BBAA1 | TP9C060B12MP13 | 15,400 | $770 |
| No | 206780024 | LUXAIRE | TH16B2421 | CM30BXA1+TXV | TP9C060B12MP13 | 15,400 | $770 |
| No | 206780020 | LUXAIRE | TH16B2421 | CF30BBAA1 | TP9C060B12MP13 | 15,400 | $770 |
| No | 206780016 | LUXAIRE | TH16B2421 | CU30BXA1+TXV | TM9V060B12MP12 | 15,400 | $770 |
| No | 206780012 | LUXAIRE | TH16B2421 | CM30BBAA1 | TM9V060B12MP12 | 15,400 | $770 |
| No | 206780008 | LUXAIRE | TH16B2421 | CM30BXA1+TXV | TM9V060B12MP12 | 15,400 | $770 |
| No | 206780004 | LUXAIRE | TH16B2421 | CF30BBAA1 | TM9V060B12MP12 | 15,400 | $770 |
| No | 206780002 | LUXAIRE | TH16B2421 | CF30BXA1+TXV | LP9C060B12MP13 | 15,400 | $770 |
| No | 206779998 | LUXAIRE | TH16B2421 | CF30BXA1+TXV | TP9C060B12MP13 | 15,400 | $770 |
| No | 206779994 | LUXAIRE | TH16B2421 | CF30BXA1+TXV | TM9V060B12MP12 | 15,400 | $770 |
| No | 206780675 | LUXAIRE | TH16B2421 | CU24BXA1+TXV | LP9C080B12MP13 | 15,000 | $750 |
| No | 206780673 | LUXAIRE | TH16B2421 | CM24BBAA1 | LP9C080B12MP13 | 15,000 | $750 |
| No | 206780671 | LUXAIRE | TH16B2421 | CM24BXA1+TXV | LP9C080B12MP13 | 15,000 | $750 |
| No | 202102056 | LUXAIRE | TH16B2421 | CF24BBAA1 | LP9C080B12MP13 | 15,000 | $750 |
| No | 206780667 | LUXAIRE | TH16B2421 | CU24BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780659 | LUXAIRE | TH16B2421 | CM24BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 202102049 | LUXAIRE | TH16B2421 | CF24BBAA1 | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780663 | LUXAIRE | TH16B2421 | CM24BBAA1 | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780476 | LUXAIRE | TH16B2421 | CU24BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780472 | LUXAIRE | TH16B2421 | CM24BBAA1 | TM9V080B12MP12 | 15,000 | $750 |
| No | 202102040 | LUXAIRE | TH16B2421 | CF24BBAA1 | TM9V080B12MP12 | 15,000 | $750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206780468 | LUXAIRE | TH16B2421 | CM24BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780416 | LUXAIRE | TH16B2421 | CF24BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780388 | LUXAIRE | TH16B2421 | CF30BBAA1 | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780408 | LUXAIRE | TH16B2421 | CM30BBAA1 | LP9C080B12MP13 | 15,000 | $750 |
| No | 206780380 | LUXAIRE | TH16B2421 | CM30BBAA1 | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780400 | LUXAIRE | TH16B2421 | CU30BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780384 | LUXAIRE | TH16B2421 | CU30BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780412 | LUXAIRE | TH16B2421 | CF24BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780420 | LUXAIRE | TH16B2421 | CF24BXA1+TXV | LP9C080B12MP13 | 15,000 | $750 |
| No | 206780392 | LUXAIRE | TH16B2421 | CM30BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780404 | LUXAIRE | TH16B2421 | CF30BBAA1 | LP9C080B12MP13 | 15,000 | $750 |
| No | 206780376 | LUXAIRE | TH16B2421 | CM30BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780396 | LUXAIRE | TH16B2421 | CM30BBAA1 | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780406 | LUXAIRE | TH16B2421 | CM30BXA1+TXV | LP9C080B12MP13 | 15,000 | $750 |
| No | 206780410 | LUXAIRE | TH16B2421 | CU30BXA1+TXV | LP9C080B12MP13 | 15,000 | $750 |
| No | 206780372 | LUXAIRE | TH16B2421 | CF30BBAA1 | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780370 | LUXAIRE | TH16B2421 | CF30BXA1+TXV | LP9C080B12MP13 | 15,000 | $750 |
| No | 206780366 | LUXAIRE | TH16B2421 | CF30BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 206780362 | LUXAIRE | TH16B2421 | CF30BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 206780360 | LUXAIRE | TH16B2421 | CU36BXA1+TXV | LP9C080B12MP13 | 15,100 | $755 |
| No | 206780358 | LUXAIRE | TH16B2421 | CM36BBAA1 | LP9C080B12MP13 | 15,100 | $755 |
| No | 206780356 | LUXAIRE | TH16B2421 | CM36BXA1+TXV | LP9C080B12MP13 | 15,100 | $755 |
| No | 206780354 | LUXAIRE | TH16B2421 | CF36BBAA1 | LP9C080B12MP13 | 15,100 | $755 |
| No | 206780350 | LUXAIRE | TH16B2421 | CU36BXA1+TXV | TP9C080B12MP13 | 15,100 | $755 |
| No | 206780346 | LUXAIRE | TH16B2421 | CM36BBAA1 | TP9C080B12MP13 | 15,100 | $755 |
| No | 206780342 | LUXAIRE | TH16B2421 | CM36BXA1+TXV | TP9C080B12MP13 | 15,100 | $755 |
| No | 206780338 | LUXAIRE | TH16B2421 | CF36BBAA1 | TP9C080B12MP13 | 15,100 | $755 |
| No | 206780334 | LUXAIRE | TH16B2421 | CU36BXA1+TXV | TM9V080B12MP12 | 15,100 | $755 |
| No | 206780330 | LUXAIRE | TH16B2421 | CM36BBAA1 | TM9V080B12MP12 | 15,100 | $755 |
| No | 206780326 | LUXAIRE | TH16B2421 | CM36BXA1+TXV | TM9V080B12MP12 | 15,100 | $755 |
| No | 206780320 | LUXAIRE | TH16B2421 | CF36BXA1+TXV | LP9C080B12MP13 | 15,100 | $755 |
| No | 206780322 | LUXAIRE | TH16B2421 | CF36BBAA1 | TM9V080B12MP12 | 15,100 | $755 |
| No | 206780316 | LUXAIRE | TH16B2421 | CF36BXA1+TXV | TP9C080B12MP13 | 15,100 | $755 |
| No | 206780312 | LUXAIRE | TH16B2421 | CF36BXA1+TXV | TM9V080B12MP12 | 15,100 | $755 |
| No | 206779942 | LUXAIRE | TH16B2421 | CU36CXA1+TXV | LP9C080C16MP13 | 15,100 | $755 |
| No | 206779940 | LUXAIRE | TH16B2421 | CM36CXA1+TXV | LP9C080C16MP13 | 15,100 | $755 |
| No | 206779936 | LUXAIRE | TH16B2421 | CU36CXA1+TXV | TP9C080C16MP13 | 15,100 | $755 |
| No | 206779932 | LUXAIRE | TH16B2421 | CM36CXA1+TXV | TP9C080C16MP13 | 15,100 | $755 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206779928 | LUXAIRE | TH16B2421 | CU36CXA1+TXV | TM9V080C16MP12 | 15,100 | $755 |
| No | 206779924 | LUXAIRE | TH16B2421 | CM36CXA1+TXV | TM9V080C16MP12 | 15,100 | $755 |
| No | 206779922 | LUXAIRE | TH16B2421 | CF36CXA1+TXV | LP9C080C16MP13 | 15,100 | $755 |
| No | 206779918 | LUXAIRE | TH16B2421 | CF36CXA1+TXV | TP9C080C16MP13 | 15,100 | $755 |
| No | 206779914 | LUXAIRE | TH16B2421 | CF36CXA1+TXV | TM9V080C16MP12 | 15,100 | $755 |
| No | 206780462 | LUXAIRE | TH16B2421 | CU36CXA1+TXV | LP9C100C16MP13 | 15,100 | $755 |
| No | 206780460 | LUXAIRE | TH16B2421 | CM36CXA1+TXV | LP9C100C16MP13 | 15,100 | $755 |
| No | 206780456 | LUXAIRE | TH16B2421 | CU36CXA1+TXV | TP9C100C16MP13 | 15,100 | $755 |
| No | 206780452 | LUXAIRE | TH16B2421 | CM36CXA1+TXV | TP9C100C16MP13 | 15,100 | $755 |
| No | 206780448 | LUXAIRE | TH16B2421 | CU36CXA1+TXV | TM9V100C16MP12 | 15,100 | $755 |
| No | 206780444 | LUXAIRE | TH16B2421 | CM36CXA1+TXV | TM9V100C16MP12 | 15,100 | $755 |
| No | 206780442 | LUXAIRE | TH16B2421 | CF36CXA1+TXV | LP9C100C16MP13 | 15,100 | $755 |
| No | 206780438 | LUXAIRE | TH16B2421 | CF36CXA1+TXV | TP9C100C16MP13 | 15,100 | $755 |
| No | 206780434 | LUXAIRE | TH16B2421 | CF36CXA1+TXV | TM9V100C16MP12 | 15,100 | $755 |
| No | 206782644 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | LP9C100C16MP13 | 32,600 | $1,630 |
| No | 206782640 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TP9C100C16MP13 | 32,600 | $1,630 |
| No | 206782636 | LUXAIRE | TH16B6021 | CM64DXA1+TXV | TM9V100C16MP12 | 32,600 | $1,630 |
| No | 206782634 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | LP9C100C16MP13 | 32,600 | $1,630 |
| No | 206782630 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TP9C100C16MP13 | 32,600 | $1,630 |
| No | 206782626 | LUXAIRE | TH16B6021 | CF64DXA1+TXV | TM9V100C16MP12 | 32,600 | $1,630 |
| No | 206781768 | LUXAIRE | TH16B4821 | CM48DBCA1+MVC14DN21 | | 28,000 | $1,400 |
| No | 206781764 | LUXAIRE | TH16B4821 | CM48DXA1+MVC14DN21+TXV | | 28,000 | $1,400 |
| No | 206781760 | LUXAIRE | TH16B4821 | CF48DXA1+MVC14DN21+TXV | | 28,000 | $1,400 |
| No | 206781542 | LUXAIRE | TH16B4821 | CM48DBCA1+MVC20DN21 | | 27,800 | $1,390 |
| No | 206781538 | LUXAIRE | TH16B4821 | CM48DXA1+MVC20DN21+TXV | | 27,800 | $1,390 |
| No | 206781534 | LUXAIRE | TH16B4821 | CF48DXA1+MVC20DN21+TXV | | 27,800 | $1,390 |
| No | 206781258 | LUXAIRE | TH16B4821 | CM64DXA1+MVC20DN21+TXV | | 29,800 | $1,490 |
| No | 9036351 | LUXAIRE | TH16B4821 | AVC48DX21+TXV | | 28,200 | $1,410 |
| No | 206781254 | LUXAIRE | TH16B4821 | CF64DXA1+MVC20DN21+TXV | | 29,800 | $1,490 |
| No | 206781425 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | LPLC100C16MP13 | 29,000 | $1,450 |
| No | 206781423 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | LPLC080C16MP13 | 29,000 | $1,450 |
| No | 206781419 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TPLC100C16MP13 | 29,000 | $1,450 |
| No | 206781415 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TPLC080C16MP13 | 29,000 | $1,450 |
| No | 206781411 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TMLV100C16MP12 | 29,000 | $1,450 |
| No | 206781407 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TM8V080C16MP12 | 29,000 | $1,450 |
| No | 206781403 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TM8V100C16MP12 | 29,000 | $1,450 |
| No | 206781399 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | LPLC080C16MP13 | 29,000 | $1,450 |
| No | 206781395 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TPLC100C16MP13 | 29,000 | $1,450 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781391 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TPLC080C16MP13 | 29,000 | $1,450 |
| No | 206781401 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | LPLC100C16MP13 | 29,000 | $1,450 |
| No | 206781387 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TMLV100C16MP12 | 29,000 | $1,450 |
| No | 206781383 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TM8V080C16MP12 | 29,000 | $1,450 |
| No | 206781379 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TM8V100C16MP12 | 29,000 | $1,450 |
| No | 206781377 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | LPLC120C20MP13 | 28,000 | $1,400 |
| No | 206781375 | LUXAIRE | TH16B4821 | CM48CBCA1 | LPLC120C20MP13 | 28,000 | $1,400 |
| No | 206781373 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | LPLC120C20MP13 | 28,000 | $1,400 |
| No | 202100773 | LUXAIRE | TH16B4821 | CF48CBCA1 | LPLC120C20MP13 | 28,000 | $1,400 |
| No | 206781504 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | LPLC100C20MP13 | 28,000 | $1,400 |
| No | 206781503 | LUXAIRE | TH16B4821 | CM48CBCA1 | LPLC100C20MP13 | 28,000 | $1,400 |
| No | 206781502 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | LPLC100C20MP13 | 28,000 | $1,400 |
| No | 206781483 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TPLC120C20MP13 | 28,000 | $1,400 |
| No | 202100770 | LUXAIRE | TH16B4821 | CF48CBCA1 | LPLC100C20MP13 | 28,000 | $1,400 |
| No | 206781479 | LUXAIRE | TH16B4821 | CM48CBCA1 | TPLC120C20MP13 | 28,000 | $1,400 |
| No | 206781475 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TPLC120C20MP13 | 28,000 | $1,400 |
| No | 202100751 | LUXAIRE | TH16B4821 | CF48CBCA1 | TPLC120C20MP13 | 28,000 | $1,400 |
| No | 206781471 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TPLC100C20MP13 | 28,000 | $1,400 |
| No | 206781467 | LUXAIRE | TH16B4821 | CM48CBCA1 | TPLC100C20MP13 | 28,000 | $1,400 |
| No | 206781463 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TPLC100C20MP13 | 28,000 | $1,400 |
| No | 202100748 | LUXAIRE | TH16B4821 | CF48CBCA1 | TPLC100C20MP13 | 28,000 | $1,400 |
| No | 206781459 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TMLV120C20MP12 | 28,000 | $1,400 |
| No | 206781455 | LUXAIRE | TH16B4821 | CM48CBCA1 | TMLV120C20MP12 | 28,000 | $1,400 |
| No | 206781451 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TMLV120C20MP12 | 28,000 | $1,400 |
| No | 202100711 | LUXAIRE | TH16B4821 | CF48CBCA1 | TMLV120C20MP12 | 28,000 | $1,400 |
| No | 206781431 | LUXAIRE | TH16B4821 | CM48CBCA1 | TM8V100C20MP12 | 28,000 | $1,400 |
| No | 206781435 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TM8V100C20MP12 | 28,000 | $1,400 |
| No | 206781427 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TM8V100C20MP12 | 28,000 | $1,400 |
| No | 202100668 | LUXAIRE | TH16B4821 | CF48CBCA1 | TM8V100C20MP12 | 28,000 | $1,400 |
| No | 206781447 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TM8V120C20MP12 | 28,000 | $1,400 |
| No | 206781443 | LUXAIRE | TH16B4821 | CM48CBCA1 | TM8V120C20MP12 | 28,000 | $1,400 |
| No | 206781439 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TM8V120C20MP12 | 28,000 | $1,400 |
| No | 202100671 | LUXAIRE | TH16B4821 | CF48CBCA1 | TM8V120C20MP12 | 28,000 | $1,400 |
| No | 206781371 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | LPLC120C20MP13 | 28,000 | $1,400 |
| No | 206781369 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | LPLC100C20MP13 | 28,000 | $1,400 |
| No | 206781366 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TPLC120C20MP13 | 28,000 | $1,400 |
| No | 206781362 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TPLC100C20MP13 | 28,000 | $1,400 |
| No | 206781358 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TMLV120C20MP12 | 28,000 | $1,400 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206781354 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TM8V100C20MP12 | 28,000 | $1,400 |
| No | 206781350 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TM8V120C20MP12 | 28,000 | $1,400 |
| No | 206781708 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | LP9C100C16MP13 | 29,200 | $1,460 |
| No | 206781704 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TP9C100C16MP13 | 29,200 | $1,460 |
| No | 206781700 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TM9V100C16MP12 | 29,200 | $1,460 |
| No | 206781698 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | LP9C100C16MP13 | 29,200 | $1,460 |
| No | 206781694 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TP9C100C16MP13 | 29,200 | $1,460 |
| No | 206781690 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TM9V100C16MP12 | 29,200 | $1,460 |
| No | 206782554 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | LP9C100C20MP13 | 28,400 | $1,420 |
| No | 206782552 | LUXAIRE | TH16B4821 | CM48CBCA1 | LP9C100C20MP13 | 28,400 | $1,420 |
| No | 206782550 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | LP9C100C20MP13 | 28,400 | $1,420 |
| No | 202100762 | LUXAIRE | TH16B4821 | CF48CBCA1 | LP9C100C20MP13 | 28,400 | $1,420 |
| No | 206782546 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TP9C100C20MP13 | 28,400 | $1,420 |
| No | 206782542 | LUXAIRE | TH16B4821 | CM48CBCA1 | TP9C100C20MP13 | 28,400 | $1,420 |
| No | 206782538 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TP9C100C20MP13 | 28,400 | $1,420 |
| No | 202100733 | LUXAIRE | TH16B4821 | CF48CBCA1 | TP9C100C20MP13 | 28,400 | $1,420 |
| No | 206782534 | LUXAIRE | TH16B4821 | CU48CXA1+TXV | TM9V100C20MP12 | 28,400 | $1,420 |
| No | 206782530 | LUXAIRE | TH16B4821 | CM48CBCA1 | TM9V100C20MP12 | 28,400 | $1,420 |
| No | 206782526 | LUXAIRE | TH16B4821 | CM48CXA1+TXV | TM9V100C20MP12 | 28,400 | $1,420 |
| No | 202100692 | LUXAIRE | TH16B4821 | CF48CBCA1 | TM9V100C20MP12 | 28,400 | $1,420 |
| No | 206782524 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | LP9C100C20MP13 | 28,400 | $1,420 |
| No | 206782520 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TP9C100C20MP13 | 28,400 | $1,420 |
| No | 206782516 | LUXAIRE | TH16B4821 | CF48CXA1+TXV | TM9V100C20MP12 | 28,400 | $1,420 |
| No | 206781524 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | LP9C100C20MP13 | 29,000 | $1,450 |
| No | 206781520 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TP9C100C20MP13 | 29,000 | $1,450 |
| No | 206781516 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TM9V100C20MP12 | 29,000 | $1,450 |
| No | 206781514 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | LP9C100C20MP13 | 29,000 | $1,450 |
| No | 206781510 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TP9C100C20MP13 | 29,000 | $1,450 |
| No | 205545157 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TM8Y080C16MP11 | 29,400 | $1,470 |
| No | 206781506 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TM9V100C20MP12 | 29,000 | $1,450 |
| No | 205545150 | LUXAIRE | TH16B4821 | CM64DXA1+TXV | TM8Y100C16MP11 | 29,400 | $1,470 |
| No | 205545107 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TM8Y080C16MP11 | 29,400 | $1,470 |
| No | 205545101 | LUXAIRE | TH16B4821 | CF64DXA1+TXV | TM8Y100C16MP11 | 29,400 | $1,470 |
| No | 206921724 | LUXAIRE | HMH72B241 | CF36BXA1+TXV | TM9E040A10MP12 | 14,500 | $725 |
| No | 206921728 | LUXAIRE | HMH72B241 | CF36BBAA1 | TM9E040A10MP12 | 14,500 | $725 |
| No | 206921732 | LUXAIRE | HMH72B241 | CM36BXA1+TXV | TM9E040A10MP12 | 14,500 | $725 |
| No | 206921736 | LUXAIRE | HMH72B241 | CM36BBAA1 | TM9E040A10MP12 | 14,500 | $725 |
| No | 206921740 | LUXAIRE | HMH72B241 | CU36BXA1+TXV | TM9E040A10MP12 | 14,500 | $725 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207335163 | LUXAIRE | HMH72B241 | CF36AXA1+TXV | TM8Y060A12MP11 | 14,200 | $710 |
| No | 207335162 | LUXAIRE | HMH72B241 | CM36AXA1+TXV | TM8Y060A12MP11 | 14,200 | $710 |
| No | 207335166 | LUXAIRE | HMH72B241 | CF36BXA1+TXV | TM8Y060A12MP11 | 14,300 | $715 |
| No | 207335168 | LUXAIRE | HMH72B241 | CF36BBAA1 | TM8Y060A12MP11 | 14,300 | $715 |
| No | 207335167 | LUXAIRE | HMH72B241 | CM36BXA1+TXV | TM8Y060A12MP11 | 14,300 | $715 |
| No | 207335165 | LUXAIRE | HMH72B241 | CM36BBAA1 | TM8Y060A12MP11 | 14,300 | $715 |
| No | 207335164 | LUXAIRE | HMH72B241 | CU36BXA1+TXV | TM8Y060A12MP11 | 14,300 | $715 |
| No | 207175988 | LUXAIRE | HMH72B241 | CF36CXA1+TXV | TM9Y060B12MP11 | 14,500 | $725 |
| No | 207175992 | LUXAIRE | HMH72B241 | CM36CXA1+TXV | TM9Y060B12MP11 | 14,500 | $725 |
| No | 206921620 | LUXAIRE | HMH72B241 | CF36CXA1+TXV | TP9C060B12MP13 | 14,500 | $725 |
| No | 206921616 | LUXAIRE | HMH72B241 | CF36CXA1+TXV | TM9V060B12MP12 | 14,500 | $725 |
| No | 206921624 | LUXAIRE | HMH72B241 | CF36CXA1+TXV | LP9C060B12MP13 | 14,500 | $725 |
| No | 206921626 | LUXAIRE | HMH72B241 | CM36CXA1+TXV | TM9V060B12MP12 | 14,500 | $725 |
| No | 206921634 | LUXAIRE | HMH72B241 | CM36CXA1+TXV | TP9C060B12MP13 | 14,500 | $725 |
| No | 206921642 | LUXAIRE | HMH72B241 | CM36CXA1+TXV | LP9C060B12MP13 | 14,500 | $725 |
| No | 207335175 | LUXAIRE | HMH72B241 | CF36CXA1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207335174 | LUXAIRE | HMH72B241 | CM36CXA1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207335173 | LUXAIRE | HMH72B241 | CF36BXA1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207335172 | LUXAIRE | HMH72B241 | CF36BBAA1 | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207335171 | LUXAIRE | HMH72B241 | CM36BXA1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207335170 | LUXAIRE | HMH72B241 | CM36BBAA1 | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207335169 | LUXAIRE | HMH72B241 | CU36BXA1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 206921566 | LUXAIRE | HMH72B241 | CF36BXA1+TXV | TM9V080B12MP12 | 14,400 | $720 |
| No | 206921570 | LUXAIRE | HMH72B241 | CF36BXA1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 206921574 | LUXAIRE | HMH72B241 | CF36BXA1+TXV | LP9C080B12MP13 | 14,400 | $720 |
| No | 206921580 | LUXAIRE | HMH72B241 | CM36BXA1+TXV | TM9V080B12MP12 | 14,400 | $720 |
| No | 206921576 | LUXAIRE | HMH72B241 | CF36BBAA1 | TM9V080B12MP12 | 14,400 | $720 |
| No | 206921584 | LUXAIRE | HMH72B241 | CM36BBAA1 | TM9V080B12MP12 | 14,400 | $720 |
| No | 206921588 | LUXAIRE | HMH72B241 | CU36BXA1+TXV | TM9V080B12MP12 | 14,400 | $720 |
| No | 206921596 | LUXAIRE | HMH72B241 | CM36BXA1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 206921592 | LUXAIRE | HMH72B241 | CF36BBAA1 | TP9C080B12MP13 | 14,400 | $720 |
| No | 206921600 | LUXAIRE | HMH72B241 | CM36BBAA1 | TP9C080B12MP13 | 14,400 | $720 |
| No | 206921604 | LUXAIRE | HMH72B241 | CU36BXA1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 206921608 | LUXAIRE | HMH72B241 | CF36BBAA1 | LP9C080B12MP13 | 14,400 | $720 |
| No | 206921610 | LUXAIRE | HMH72B241 | CM36BXA1+TXV | LP9C080B12MP13 | 14,400 | $720 |
| No | 206921612 | LUXAIRE | HMH72B241 | CM36BBAA1 | LP9C080B12MP13 | 14,400 | $720 |
| No | 206921614 | LUXAIRE | HMH72B241 | CU36BXA1+TXV | LP9C080B12MP13 | 14,400 | $720 |
| No | 207251149 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TM9E100C16MP12 | 31,000 | $1,550 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207251151 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TM9E100C16MP12 | 31,000 | $1,550 |
| No | 206971539 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TM9V080C16MP12 | 30,800 | $1,540 |
| No | 206971553 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TP9C080C16MP13 | 30,800 | $1,540 |
| No | 206971543 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TP9C080C16MP13 | 30,800 | $1,540 |
| No | 206971547 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | LP9C080C16MP13 | 30,800 | $1,540 |
| No | 206971549 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TM9V080C16MP12 | 30,800 | $1,540 |
| No | 206971557 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | LP9C080C16MP13 | 30,800 | $1,540 |
| No | 206921536 | LUXAIRE | HMH72B241 | CF36CXA1+TXV | TM9V080B12MP12 | 14,300 | $715 |
| No | 207176156 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TM9Y100C16MP11 | 30,200 | $1,510 |
| No | 207176160 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TM9Y100C16MP11 | 30,200 | $1,510 |
| No | 206921540 | LUXAIRE | HMH72B241 | CF36CXA1+TXV | TP9C080B12MP13 | 14,300 | $715 |
| No | 206921544 | LUXAIRE | HMH72B241 | CF36CXA1+TXV | LP9C080B12MP13 | 14,300 | $715 |
| No | 206921546 | LUXAIRE | HMH72B241 | CM36CXA1+TXV | TM9V080B12MP12 | 14,300 | $715 |
| No | 206921554 | LUXAIRE | HMH72B241 | CM36CXA1+TXV | TP9C080B12MP13 | 14,300 | $715 |
| No | 207251153 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TM9E080C16MP12 | 31,200 | $1,560 |
| No | 206921562 | LUXAIRE | HMH72B241 | CM36CXA1+TXV | LP9C080B12MP13 | 14,300 | $715 |
| No | 207251155 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TM9E080C16MP12 | 31,200 | $1,560 |
| No | 206971669 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TL9E080C16UH11 | 29,600 | $1,480 |
| No | 206971673 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TL9E080C16UH11 | 29,600 | $1,480 |
| No | 206921780 | LUXAIRE | HMH72B241 | CF36CXA1+TXV | TM8V100C16MP12 | 14,300 | $715 |
| No | 206921784 | LUXAIRE | HMH72B241 | CF36CXA1+TXV | TM8V080C16MP12 | 14,300 | $715 |
| No | 206921788 | LUXAIRE | HMH72B241 | CF36CXA1+TXV | TMLV100C16MP12 | 14,300 | $715 |
| No | 206921792 | LUXAIRE | HMH72B241 | CF36CXA1+TXV | TPLC080C16MP13 | 14,300 | $715 |
| No | 206921796 | LUXAIRE | HMH72B241 | CF36CXA1+TXV | TPLC100C16MP13 | 14,300 | $715 |
| No | 206921800 | LUXAIRE | HMH72B241 | CF36CXA1+TXV | LPLC080C16MP13 | 14,300 | $715 |
| No | 206921802 | LUXAIRE | HMH72B241 | CF36CXA1+TXV | LPLC100C16MP13 | 14,300 | $715 |
| No | 206921804 | LUXAIRE | HMH72B241 | CM36CXA1+TXV | TM8V100C16MP12 | 14,300 | $715 |
| No | 206921812 | LUXAIRE | HMH72B241 | CM36CXA1+TXV | TM8V080C16MP12 | 14,300 | $715 |
| No | 206921820 | LUXAIRE | HMH72B241 | CM36CXA1+TXV | TMLV100C16MP12 | 14,300 | $715 |
| No | 206921828 | LUXAIRE | HMH72B241 | CM36CXA1+TXV | TPLC080C16MP13 | 14,300 | $715 |
| No | 206921836 | LUXAIRE | HMH72B241 | CM36CXA1+TXV | TPLC100C16MP13 | 14,300 | $715 |
| No | 206921844 | LUXAIRE | HMH72B241 | CM36CXA1+TXV | LPLC080C16MP13 | 14,300 | $715 |
| No | 206921848 | LUXAIRE | HMH72B241 | CM36CXA1+TXV | LPLC100C16MP13 | 14,300 | $715 |
| No | 207176164 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TM9Y080C16MP11 | 30,200 | $1,510 |
| No | 207176168 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TM9Y080C16MP11 | 30,200 | $1,510 |
| No | 207335288 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TM8Y080C16MP11 | 30,200 | $1,510 |
| No | 207335287 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TM8Y080C16MP11 | 30,200 | $1,510 |
| No | 206971701 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TM8E100C16MP11 | 30,200 | $1,510 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206971705 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TMLE100C16MP11 | 30,200 | $1,510 |
| No | 206971709 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TM8E100C16MP11 | 30,200 | $1,510 |
| No | 206971713 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TMLE100C16MP11 | 30,200 | $1,510 |
| No | 206971487 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | LP9C100C16MP13 | 30,800 | $1,540 |
| No | 206971717 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TL8E080C16UH11 | 30,200 | $1,510 |
| No | 206971721 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TL8E080C16UH11 | 30,200 | $1,510 |
| No | 206971479 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TM9V100C16MP12 | 30,800 | $1,540 |
| No | 206971483 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TP9C100C16MP13 | 30,800 | $1,540 |
| No | 206971489 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TM9V100C16MP12 | 30,800 | $1,540 |
| No | 206971493 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TP9C100C16MP13 | 30,800 | $1,540 |
| No | 206971497 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | LP9C100C16MP13 | 30,800 | $1,540 |
| No | 206971519 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TM9V100C20MP12 | 31,000 | $1,550 |
| No | 206971527 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | LP9C100C20MP13 | 31,000 | $1,550 |
| No | 206971523 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TP9C100C20MP13 | 31,000 | $1,550 |
| No | 206971529 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TM9V100C20MP12 | 31,000 | $1,550 |
| No | 206971533 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TP9C100C20MP13 | 31,000 | $1,550 |
| No | 206971537 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | LP9C100C20MP13 | 31,000 | $1,550 |
| No | 206971685 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TM8E120C16MP11 | 30,200 | $1,510 |
| No | 206971689 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TMLE120C16MP11 | 30,200 | $1,510 |
| No | 206971697 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TMLE120C16MP11 | 30,200 | $1,510 |
| No | 206971693 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TM8E120C16MP11 | 30,200 | $1,510 |
| No | 206971653 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TM8E080C16MP11 | 30,200 | $1,510 |
| No | 206971657 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TMLE080C16MP11 | 30,200 | $1,510 |
| No | 206971661 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TM8E080C16MP11 | 30,200 | $1,510 |
| No | 206971665 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TMLE080C16MP11 | 30,200 | $1,510 |
| No | 206971605 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TM8V100C16MP12 | 29,600 | $1,480 |
| No | 206971613 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TMLV100C16MP12 | 29,600 | $1,480 |
| No | 206971609 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TM8V080C16MP12 | 29,600 | $1,480 |
| No | 206971617 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TPLC080C16MP13 | 29,600 | $1,480 |
| No | 206971621 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TPLC100C16MP13 | 29,600 | $1,480 |
| No | 206971627 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | LPLC100C16MP13 | 29,600 | $1,480 |
| No | 206971625 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | LPLC080C16MP13 | 29,600 | $1,480 |
| No | 206971629 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TM8V100C16MP12 | 29,600 | $1,480 |
| No | 206971633 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TM8V080C16MP12 | 29,600 | $1,480 |
| No | 206971637 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TMLV100C16MP12 | 29,600 | $1,480 |
| No | 206971641 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TPLC080C16MP13 | 29,600 | $1,480 |
| No | 206971645 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TPLC100C16MP13 | 29,600 | $1,480 |
| No | 206971649 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | LPLC080C16MP13 | 29,600 | $1,480 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207176148 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TM9Y120D20MP11 | 30,600 | $1,530 |
| No | 206971651 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | LPLC100C16MP13 | 29,600 | $1,480 |
| No | 207176152 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TM9Y120D20MP11 | 30,600 | $1,530 |
| No | 207335292 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TM8Y120C20MP11 | 29,800 | $1,490 |
| No | 207335289 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TM8Y100C20MP11 | 29,800 | $1,490 |
| No | 207335291 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TM8Y120C20MP11 | 29,800 | $1,490 |
| No | 207335290 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TM8Y100C20MP11 | 29,800 | $1,490 |
| No | 206971559 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TM8V120C20MP12 | 29,800 | $1,490 |
| No | 206971563 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TM8V100C20MP12 | 29,800 | $1,490 |
| No | 206971575 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TPLC120C20MP13 | 29,800 | $1,490 |
| No | 206971567 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TMLV120C20MP12 | 29,800 | $1,490 |
| No | 206971571 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TPLC100C20MP13 | 29,800 | $1,490 |
| No | 206971578 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | LPLC100C20MP13 | 29,800 | $1,490 |
| No | 206971582 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TM8V120C20MP12 | 29,800 | $1,490 |
| No | 206971580 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | LPLC120C20MP13 | 29,800 | $1,490 |
| No | 206971586 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TM8V100C20MP12 | 29,800 | $1,490 |
| No | 206971590 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TMLV120C20MP12 | 29,800 | $1,490 |
| No | 206971594 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TPLC100C20MP13 | 29,800 | $1,490 |
| No | 206971598 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TPLC120C20MP13 | 29,800 | $1,490 |
| No | 206971499 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TM9V120D20MP12 | 30,800 | $1,540 |
| No | 206971601 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | LPLC100C20MP13 | 29,800 | $1,490 |
| No | 206971603 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | LPLC120C20MP13 | 29,800 | $1,490 |
| No | 206971503 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TP9C120D20MP13 | 30,800 | $1,540 |
| No | 206971507 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | LP9C120D20MP13 | 30,800 | $1,540 |
| No | 206971509 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TM9V120D20MP12 | 30,800 | $1,540 |
| No | 206971513 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TP9C120D20MP13 | 30,800 | $1,540 |
| No | 206971681 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | TL8E100C20UH11 | 30,000 | $1,500 |
| No | 206971517 | LUXAIRE | HMH72B481 | CM64DXA1+TXV | LP9C120D20MP13 | 30,800 | $1,540 |
| No | 206971677 | LUXAIRE | HMH72B481 | CF64DXA1+TXV | TL8E100C20UH11 | 30,000 | $1,500 |
| No | 206922358 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 206922362 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 206922366 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | LP9C060B12MP13 | 25,000 | $1,250 |
| No | 206922368 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 206922528 | LUXAIRE | HMH72B361 | CF36BBCA1 | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206922532 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206922536 | LUXAIRE | HMH72B361 | CM36BBCA1 | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206922540 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206922832 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922845 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 206922836 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 206922839 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | LPLC080B12MP13 | 24,600 | $1,230 |
| No | 206922841 | LUXAIRE | HMH72B361 | CF36BBCA1 | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 206922849 | LUXAIRE | HMH72B361 | CM36BBCA1 | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 206922853 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 206922857 | LUXAIRE | HMH72B361 | CF36BBCA1 | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 206922861 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 206922865 | LUXAIRE | HMH72B361 | CM36BBCA1 | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 206922869 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 206922872 | LUXAIRE | HMH72B361 | CF36BBCA1 | LPLC080B12MP13 | 24,600 | $1,230 |
| No | 206922873 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | LPLC080B12MP13 | 24,600 | $1,230 |
| No | 206922874 | LUXAIRE | HMH72B361 | CM36BBCA1 | LPLC080B12MP13 | 24,600 | $1,230 |
| No | 206922875 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | LPLC080B12MP13 | 24,600 | $1,230 |
| No | 206922877 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 206922881 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 206922885 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 206922889 | LUXAIRE | HMH72B361 | CF36BBCA1 | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 206922893 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 206922897 | LUXAIRE | HMH72B361 | CM36BBCA1 | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 206922901 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 206922905 | LUXAIRE | HMH72B361 | CF36BBCA1 | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 206922909 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 206922913 | LUXAIRE | HMH72B361 | CM36BBCA1 | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 206922918 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 206922922 | LUXAIRE | HMH72B361 | CF36BBCA1 | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 206922934 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 206922926 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 206922930 | LUXAIRE | HMH72B361 | CM36BBCA1 | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 206923403 | LUXAIRE | HMH72B361 | CF36AXA1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206923407 | LUXAIRE | HMH72B361 | CM36AXA1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206923163 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 206923167 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 206923171 | LUXAIRE | HMH72B361 | CF36BBCA1 | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 206923175 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 206923179 | LUXAIRE | HMH72B361 | CM36BBCA1 | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 206923183 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 206923187 | LUXAIRE | HMH72B361 | CF36BBCA1 | TMLE080B12MP11 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206923191 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 206923195 | LUXAIRE | HMH72B361 | CM36BBCA1 | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 206923199 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 206923203 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206923219 | LUXAIRE | HMH72B361 | CM36BBCA1 | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206923207 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206923211 | LUXAIRE | HMH72B361 | CF36BBCA1 | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206923215 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206923223 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206923227 | LUXAIRE | HMH72B361 | CF36BBCA1 | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206923231 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206923235 | LUXAIRE | HMH72B361 | CM36BBCA1 | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206923239 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206923383 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206923387 | LUXAIRE | HMH72B361 | CF36BBCA1 | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206923391 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206923395 | LUXAIRE | HMH72B361 | CM36BBCA1 | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206923399 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206922308 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 206922312 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922316 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | LP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922326 | LUXAIRE | HMH72B361 | CM36BBCA1 | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 206922318 | LUXAIRE | HMH72B361 | CF36BBCA1 | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 206922322 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 206922330 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 206922334 | LUXAIRE | HMH72B361 | CF36BBCA1 | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922338 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922342 | LUXAIRE | HMH72B361 | CM36BBCA1 | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922346 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922350 | LUXAIRE | HMH72B361 | CF36BBCA1 | LP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922352 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | LP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922354 | LUXAIRE | HMH72B361 | CM36BBCA1 | LP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922356 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | LP9C080B12MP13 | 24,600 | $1,230 |
| No | 206922508 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206922512 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206922516 | LUXAIRE | HMH72B361 | CM36CBCA1 | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 207176076 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 207176080 | LUXAIRE | HMH72B361 | CF36BBCA1 | TM9Y080B12MP11 | 24,600 | $1,230 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207176084 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 207176088 | LUXAIRE | HMH72B361 | CM36BBCA1 | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 207176092 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 206923026 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923034 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923030 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923046 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923038 | LUXAIRE | HMH72B361 | CM36CBCA1 | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923050 | LUXAIRE | HMH72B361 | CM36CBCA1 | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 207176044 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TM9Y080C16MP11 | 24,600 | $1,230 |
| No | 207176112 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207176048 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TM9Y080C16MP11 | 24,600 | $1,230 |
| No | 207176052 | LUXAIRE | HMH72B361 | CM36CBCA1 | TM9Y080C16MP11 | 24,600 | $1,230 |
| No | 207176116 | LUXAIRE | HMH72B361 | CF36BBCA1 | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207176120 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207176124 | LUXAIRE | HMH72B361 | CM36BBCA1 | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207176128 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207335222 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 207335224 | LUXAIRE | HMH72B361 | CF36BBCA1 | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 207335223 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 207335228 | LUXAIRE | HMH72B361 | CM36BBCA1 | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 207335227 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 206922560 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 206922564 | LUXAIRE | HMH72B361 | CF36BBCA1 | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 206922568 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 206922572 | LUXAIRE | HMH72B361 | CM36BBCA1 | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 206922576 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 206922796 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TM8V080B12MP12 | 24,400 | $1,220 |
| No | 206922800 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TPLC080B12MP13 | 24,400 | $1,220 |
| No | 206922803 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | LPLC080B12MP13 | 24,400 | $1,220 |
| No | 206922805 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TM8V080B12MP12 | 24,400 | $1,220 |
| No | 206922809 | LUXAIRE | HMH72B361 | CM36CBCA1 | TM8V080B12MP12 | 24,400 | $1,220 |
| No | 206922821 | LUXAIRE | HMH72B361 | CM36CBCA1 | TPLC080B12MP13 | 24,400 | $1,220 |
| No | 206922817 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TPLC080B12MP13 | 24,400 | $1,220 |
| No | 206922828 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | LPLC080B12MP13 | 24,400 | $1,220 |
| No | 206922829 | LUXAIRE | HMH72B361 | CM36CBCA1 | LPLC080B12MP13 | 24,400 | $1,220 |
| No | 206923058 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923062 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206923066 | LUXAIRE | HMH72B361 | CF36BBCA1 | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923070 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923074 | LUXAIRE | HMH72B361 | CM36BBCA1 | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923078 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923083 | LUXAIRE | HMH72B361 | CF36BBCA1 | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923087 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923091 | LUXAIRE | HMH72B361 | CM36BBCA1 | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923095 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923131 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TM8E080B12MP11 | 24,600 | $1,230 |
| No | 206923151 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 206923135 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 206923139 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TM8E080B12MP11 | 24,600 | $1,230 |
| No | 206971313 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TM9V080C16MP12 | 38,000 | $1,900 |
| No | 206923143 | LUXAIRE | HMH72B361 | CM36CBCA1 | TM8E080B12MP11 | 24,600 | $1,230 |
| No | 206923155 | LUXAIRE | HMH72B361 | CM36CBCA1 | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 206971317 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TP9C080C16MP13 | 38,000 | $1,900 |
| No | 206971321 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | LP9C080C16MP13 | 38,000 | $1,900 |
| No | 207335226 | LUXAIRE | HMH72B361 | CM36AXA1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 206971323 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TM9V080C16MP12 | 38,000 | $1,900 |
| No | 206971327 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TP9C080C16MP13 | 38,000 | $1,900 |
| No | 206971331 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | LP9C080C16MP13 | 38,000 | $1,900 |
| No | 207335225 | LUXAIRE | HMH72B361 | CF36AXA1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 206922448 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 206922452 | LUXAIRE | HMH72B361 | CF36BBCA1 | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 206922456 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 206922460 | LUXAIRE | HMH72B361 | CM36BBCA1 | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 206922464 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 206922600 | LUXAIRE | HMH72B361 | CF36AXA1+TXV | TM9E060A10MP12 | 24,200 | $1,210 |
| No | 206922604 | LUXAIRE | HMH72B361 | CM36AXA1+TXV | TM9E060A10MP12 | 24,200 | $1,210 |
| No | 206923299 | LUXAIRE | HMH72B361 | CF36AXA1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206923303 | LUXAIRE | HMH72B361 | CF36AXA1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 206923307 | LUXAIRE | HMH72B361 | CM36AXA1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 207335233 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 206923311 | LUXAIRE | HMH72B361 | CM36AXA1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 207176096 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207176100 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207176104 | LUXAIRE | HMH72B361 | CM36CBCA1 | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207335232 | LUXAIRE | HMH72B361 | CF36BBCA1 | TM8Y080B12MP11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207335231 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 207335230 | LUXAIRE | HMH72B361 | CM36BBCA1 | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 207335229 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 207176060 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 207176064 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 207176068 | LUXAIRE | HMH72B361 | CM36CBCA1 | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 206922228 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TM9V080C16MP12 | 24,400 | $1,220 |
| No | 206922232 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TP9C080C16MP13 | 24,400 | $1,220 |
| No | 206922236 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | LP9C080C16MP13 | 24,400 | $1,220 |
| No | 206922238 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TM9V080C16MP12 | 24,400 | $1,220 |
| No | 206922242 | LUXAIRE | HMH72B361 | CM36CBCA1 | TM9V080C16MP12 | 24,400 | $1,220 |
| No | 206922250 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TP9C080C16MP13 | 24,400 | $1,220 |
| No | 206922254 | LUXAIRE | HMH72B361 | CM36CBCA1 | TP9C080C16MP13 | 24,400 | $1,220 |
| No | 206922262 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | LP9C080C16MP13 | 24,400 | $1,220 |
| No | 206922492 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TM9E080C16MP12 | 24,600 | $1,230 |
| No | 206922264 | LUXAIRE | HMH72B361 | CM36CBCA1 | LP9C080C16MP13 | 24,400 | $1,220 |
| No | 206922496 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TM9E080C16MP12 | 24,600 | $1,230 |
| No | 206922500 | LUXAIRE | HMH72B361 | CM36CBCA1 | TM9E080C16MP12 | 24,600 | $1,230 |
| No | 206923315 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TL9E080C16UH11 | 24,600 | $1,230 |
| No | 206923319 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TL9E080C16UH11 | 24,600 | $1,230 |
| No | 206923323 | LUXAIRE | HMH72B361 | CM36CBCA1 | TL9E080C16UH11 | 24,600 | $1,230 |
| No | 206922408 | LUXAIRE | HMH72B361 | CF36BBCA1 | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 206922398 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 206922402 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922406 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | LP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922412 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 206922416 | LUXAIRE | HMH72B361 | CM36BBCA1 | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 206922420 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 206922424 | LUXAIRE | HMH72B361 | CF36BBCA1 | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922428 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922432 | LUXAIRE | HMH72B361 | CM36BBCA1 | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922436 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922440 | LUXAIRE | HMH72B361 | CF36BBCA1 | LP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922704 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TM8V080C16MP12 | 24,600 | $1,230 |
| No | 206922442 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | LP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922444 | LUXAIRE | HMH72B361 | CM36BBCA1 | LP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922446 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | LP9C060B12MP13 | 24,400 | $1,220 |
| No | 206922700 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TM8V100C16MP12 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922708 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TMLV100C16MP12 | 24,600 | $1,230 |
| No | 206922712 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TPLC080C16MP13 | 24,600 | $1,230 |
| No | 206922716 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 206922720 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | LPLC080C16MP13 | 24,600 | $1,230 |
| No | 206922722 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | LPLC100C16MP13 | 24,600 | $1,230 |
| No | 206922724 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 206922728 | LUXAIRE | HMH72B361 | CM36CBCA1 | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 206922752 | LUXAIRE | HMH72B361 | CM36CBCA1 | TMLV100C16MP12 | 24,600 | $1,230 |
| No | 206922736 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TM8V080C16MP12 | 24,600 | $1,230 |
| No | 206922740 | LUXAIRE | HMH72B361 | CM36CBCA1 | TM8V080C16MP12 | 24,600 | $1,230 |
| No | 206922748 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TMLV100C16MP12 | 24,600 | $1,230 |
| No | 206922772 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 206922760 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TPLC080C16MP13 | 24,600 | $1,230 |
| No | 206922764 | LUXAIRE | HMH72B361 | CM36CBCA1 | TPLC080C16MP13 | 24,600 | $1,230 |
| No | 206922776 | LUXAIRE | HMH72B361 | CM36CBCA1 | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 206922784 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | LPLC080C16MP13 | 24,600 | $1,230 |
| No | 206922786 | LUXAIRE | HMH72B361 | CM36CBCA1 | LPLC080C16MP13 | 24,600 | $1,230 |
| No | 206922790 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | LPLC100C16MP13 | 24,600 | $1,230 |
| No | 206922792 | LUXAIRE | HMH72B361 | CM36CBCA1 | LPLC100C16MP13 | 24,600 | $1,230 |
| No | 206923259 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206923263 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 206923267 | LUXAIRE | HMH72B361 | CF36BBCA1 | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206923271 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206923275 | LUXAIRE | HMH72B361 | CM36BBCA1 | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206923279 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206923283 | LUXAIRE | HMH72B361 | CF36BBCA1 | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 206923287 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 206923291 | LUXAIRE | HMH72B361 | CM36BBCA1 | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 206923295 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 206923347 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 206923351 | LUXAIRE | HMH72B361 | CF36BBCA1 | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 206923355 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 206923359 | LUXAIRE | HMH72B361 | CM36BBCA1 | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 206923363 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 206922608 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TM8V120C20MP12 | 24,600 | $1,230 |
| No | 206922612 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TM8V100C20MP12 | 24,600 | $1,230 |
| No | 206922616 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TMLV120C20MP12 | 24,600 | $1,230 |
| No | 206922620 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TPLC100C20MP13 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922629 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | LPLC120C20MP13 | 24,600 | $1,230 |
| No | 206922624 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TPLC120C20MP13 | 24,600 | $1,230 |
| No | 206922635 | LUXAIRE | HMH72B361 | CM36CBCA1 | TM8V120C20MP12 | 24,600 | $1,230 |
| No | 206922627 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | LPLC100C20MP13 | 24,600 | $1,230 |
| No | 206922631 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TM8V120C20MP12 | 24,600 | $1,230 |
| No | 206922643 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TM8V100C20MP12 | 24,600 | $1,230 |
| No | 206922647 | LUXAIRE | HMH72B361 | CM36CBCA1 | TM8V100C20MP12 | 24,600 | $1,230 |
| No | 206922655 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TMLV120C20MP12 | 24,600 | $1,230 |
| No | 206922659 | LUXAIRE | HMH72B361 | CM36CBCA1 | TMLV120C20MP12 | 24,600 | $1,230 |
| No | 206922667 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TPLC100C20MP13 | 24,600 | $1,230 |
| No | 206922671 | LUXAIRE | HMH72B361 | CM36CBCA1 | TPLC100C20MP13 | 24,600 | $1,230 |
| No | 206922679 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TPLC120C20MP13 | 24,600 | $1,230 |
| No | 206922683 | LUXAIRE | HMH72B361 | CM36CBCA1 | TPLC120C20MP13 | 24,600 | $1,230 |
| No | 206922690 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | LPLC100C20MP13 | 24,600 | $1,230 |
| No | 206922691 | LUXAIRE | HMH72B361 | CM36CBCA1 | LPLC100C20MP13 | 24,600 | $1,230 |
| No | 206922694 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | LPLC120C20MP13 | 24,600 | $1,230 |
| No | 206922476 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TM9E100C16MP12 | 24,600 | $1,230 |
| No | 206922696 | LUXAIRE | HMH72B361 | CM36CBCA1 | LPLC120C20MP13 | 24,600 | $1,230 |
| No | 206922480 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TM9E100C16MP12 | 24,600 | $1,230 |
| No | 206922484 | LUXAIRE | HMH72B361 | CM36CBCA1 | TM9E100C16MP12 | 24,600 | $1,230 |
| No | 207335312 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TM8Y080C16MP11 | 38,000 | $1,900 |
| No | 207335311 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TM8Y080C16MP11 | 38,000 | $1,900 |
| No | 206971405 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TL8E080C16UH11 | 38,000 | $1,900 |
| No | 206971409 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TL8E080C16UH11 | 38,000 | $1,900 |
| No | 207335234 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 207335236 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 207335235 | LUXAIRE | HMH72B361 | CM36CBCA1 | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 206922268 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 206922272 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 206922276 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | LP9C080B12MP13 | 24,400 | $1,220 |
| No | 206922278 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 206922282 | LUXAIRE | HMH72B361 | CM36CBCA1 | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 206922290 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 206922294 | LUXAIRE | HMH72B361 | CM36CBCA1 | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 206922302 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | LP9C080B12MP13 | 24,400 | $1,220 |
| No | 206922148 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TM9V100C20MP12 | 24,400 | $1,220 |
| No | 206922304 | LUXAIRE | HMH72B361 | CM36CBCA1 | LP9C080B12MP13 | 24,400 | $1,220 |
| No | 206922158 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TM9V100C20MP12 | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922152 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TP9C100C20MP13 | 24,400 | $1,220 |
| No | 206922156 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | LP9C100C20MP13 | 24,400 | $1,220 |
| No | 206922162 | LUXAIRE | HMH72B361 | CM36CBCA1 | TM9V100C20MP12 | 24,400 | $1,220 |
| No | 206922170 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TP9C100C20MP13 | 24,400 | $1,220 |
| No | 206922174 | LUXAIRE | HMH72B361 | CM36CBCA1 | TP9C100C20MP13 | 24,400 | $1,220 |
| No | 206922182 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | LP9C100C20MP13 | 24,400 | $1,220 |
| No | 206922962 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TM8E120C16MP11 | 24,600 | $1,230 |
| No | 206922184 | LUXAIRE | HMH72B361 | CM36CBCA1 | LP9C100C20MP13 | 24,400 | $1,220 |
| No | 206922966 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TMLE120C16MP11 | 24,600 | $1,230 |
| No | 206922970 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TM8E120C16MP11 | 24,600 | $1,230 |
| No | 206922974 | LUXAIRE | HMH72B361 | CM36CBCA1 | TM8E120C16MP11 | 24,600 | $1,230 |
| No | 206922982 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TMLE120C16MP11 | 24,600 | $1,230 |
| No | 206922986 | LUXAIRE | HMH72B361 | CM36CBCA1 | TMLE120C16MP11 | 24,600 | $1,230 |
| No | 206922994 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TM8E100C16MP11 | 24,600 | $1,230 |
| No | 206922998 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TMLE100C16MP11 | 24,600 | $1,230 |
| No | 206923002 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TM8E100C16MP11 | 24,600 | $1,230 |
| No | 206923006 | LUXAIRE | HMH72B361 | CM36CBCA1 | TM8E100C16MP11 | 24,600 | $1,230 |
| No | 206923014 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TMLE100C16MP11 | 24,600 | $1,230 |
| No | 206923018 | LUXAIRE | HMH72B361 | CM36CBCA1 | TMLE100C16MP11 | 24,600 | $1,230 |
| No | 206971209 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TM9V100C20MP12 | 38,000 | $1,900 |
| No | 206971213 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TP9C100C20MP13 | 38,000 | $1,900 |
| No | 206971297 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TM8E100C16MP11 | 38,000 | $1,900 |
| No | 206971217 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | LP9C100C20MP13 | 38,000 | $1,900 |
| No | 206971219 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TM9V100C20MP12 | 38,000 | $1,900 |
| No | 206971223 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TP9C100C20MP13 | 38,000 | $1,900 |
| No | 206971227 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | LP9C100C20MP13 | 38,000 | $1,900 |
| No | 206971305 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TM8E100C16MP11 | 38,000 | $1,900 |
| No | 206971301 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TMLE100C16MP11 | 38,000 | $1,900 |
| No | 206971309 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TMLE100C16MP11 | 38,000 | $1,900 |
| No | 206971373 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TM8E080C16MP11 | 38,000 | $1,900 |
| No | 206971377 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TMLE080C16MP11 | 38,000 | $1,900 |
| No | 206971385 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TMLE080C16MP11 | 38,000 | $1,900 |
| No | 206971381 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TM8E080C16MP11 | 38,000 | $1,900 |
| No | 206922468 | LUXAIRE | HMH72B361 | CF36AXA1+TXV | TM9V040A10MP12 | 24,000 | $1,200 |
| No | 206922472 | LUXAIRE | HMH72B361 | CM36AXA1+TXV | TM9V040A10MP12 | 24,000 | $1,200 |
| No | 206922938 | LUXAIRE | HMH72B361 | CF36AXA1+TXV | TM8V060A12MP12 | 24,200 | $1,210 |
| No | 206922942 | LUXAIRE | HMH72B361 | CF36AXA1+TXV | TMLV060A12MP12 | 24,200 | $1,210 |
| No | 206922946 | LUXAIRE | HMH72B361 | CF36AXA1+TXV | TPLC060A12MP13 | 24,200 | $1,210 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922950 | LUXAIRE | HMH72B361 | CM36AXA1+TXV | TM8V060A12MP12 | 24,200 | $1,210 |
| No | 206922954 | LUXAIRE | HMH72B361 | CM36AXA1+TXV | TMLV060A12MP12 | 24,200 | $1,210 |
| No | 206922958 | LUXAIRE | HMH72B361 | CM36AXA1+TXV | TPLC060A12MP13 | 24,200 | $1,210 |
| No | 206922188 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TM9V100C16MP12 | 24,400 | $1,220 |
| No | 206922192 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TP9C100C16MP13 | 24,400 | $1,220 |
| No | 206922196 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | LP9C100C16MP13 | 24,400 | $1,220 |
| No | 206922198 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TM9V100C16MP12 | 24,400 | $1,220 |
| No | 206922202 | LUXAIRE | HMH72B361 | CM36CBCA1 | TM9V100C16MP12 | 24,400 | $1,220 |
| No | 206922222 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | LP9C100C16MP13 | 24,400 | $1,220 |
| No | 206922210 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TP9C100C16MP13 | 24,400 | $1,220 |
| No | 206922214 | LUXAIRE | HMH72B361 | CM36CBCA1 | TP9C100C16MP13 | 24,400 | $1,220 |
| No | 206971273 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TM8E120C16MP11 | 38,000 | $1,900 |
| No | 206922224 | LUXAIRE | HMH72B361 | CM36CBCA1 | LP9C100C16MP13 | 24,400 | $1,220 |
| No | 206971265 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TM8E120C16MP11 | 38,000 | $1,900 |
| No | 206971269 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TMLE120C16MP11 | 38,000 | $1,900 |
| No | 206971277 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TMLE120C16MP11 | 38,000 | $1,900 |
| No | 207176132 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TM9Y120D20MP11 | 38,000 | $1,900 |
| No | 207176136 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TM9Y120D20MP11 | 38,000 | $1,900 |
| No | 206923099 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TM8E080C16MP11 | 24,400 | $1,220 |
| No | 206923103 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TMLE080C16MP11 | 24,400 | $1,220 |
| No | 206923107 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TM8E080C16MP11 | 24,400 | $1,220 |
| No | 206923111 | LUXAIRE | HMH72B361 | CM36CBCA1 | TM8E080C16MP11 | 24,400 | $1,220 |
| No | 206923119 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TMLE080C16MP11 | 24,400 | $1,220 |
| No | 206923123 | LUXAIRE | HMH72B361 | CM36CBCA1 | TMLE080C16MP11 | 24,400 | $1,220 |
| No | 206971229 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TM9V100C16MP12 | 38,000 | $1,900 |
| No | 206971233 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TP9C100C16MP13 | 38,000 | $1,900 |
| No | 206971239 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TM9V100C16MP12 | 38,000 | $1,900 |
| No | 206971237 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | LP9C100C16MP13 | 38,000 | $1,900 |
| No | 206971243 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TP9C100C16MP13 | 38,000 | $1,900 |
| No | 206971247 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | LP9C100C16MP13 | 38,000 | $1,900 |
| No | 206971333 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TM9E120D20MP12 | 38,500 | $1,925 |
| No | 206971337 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TM9E120D20MP12 | 38,500 | $1,925 |
| No | 206971413 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TM8V120C20MP12 | 39,000 | $1,950 |
| No | 206971417 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TM8V100C20MP12 | 39,000 | $1,950 |
| No | 206971421 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TMLV120C20MP12 | 39,000 | $1,950 |
| No | 206971425 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TPLC100C20MP13 | 39,000 | $1,950 |
| No | 206971429 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TPLC120C20MP13 | 39,000 | $1,950 |
| No | 206971432 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | LPLC100C20MP13 | 39,000 | $1,950 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206971434 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | LPLC120C20MP13 | 39,000 | $1,950 |
| No | 206971436 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TM8V120C20MP12 | 39,000 | $1,950 |
| No | 206971440 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TM8V100C20MP12 | 39,000 | $1,950 |
| No | 206971444 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TMLV120C20MP12 | 39,000 | $1,950 |
| No | 206971448 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TPLC100C20MP13 | 39,000 | $1,950 |
| No | 206971452 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TPLC120C20MP13 | 39,000 | $1,950 |
| No | 206971455 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | LPLC100C20MP13 | 39,000 | $1,950 |
| No | 206971457 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | LPLC120C20MP13 | 39,000 | $1,950 |
| No | 207176140 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TM9Y100C20MP11 | 38,000 | $1,900 |
| No | 207176144 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TM9Y100C20MP11 | 38,000 | $1,900 |
| No | 206971293 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TMLE100C20MP11 | 38,500 | $1,925 |
| No | 206971281 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TM8E100C20MP11 | 38,500 | $1,925 |
| No | 206971285 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TMLE100C20MP11 | 38,500 | $1,925 |
| No | 207176036 | LUXAIRE | HMH72B361 | CM36CBCA1 | TM9Y100C16MP11 | 24,200 | $1,210 |
| No | 206971289 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TM8E100C20MP11 | 38,500 | $1,925 |
| No | 207176028 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TM9Y100C16MP11 | 24,200 | $1,210 |
| No | 207176032 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TM9Y100C16MP11 | 24,200 | $1,210 |
| No | 206971389 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TL9E100C20UH11 | 38,000 | $1,900 |
| No | 206971393 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TL9E100C20UH11 | 38,000 | $1,900 |
| No | 206971341 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TM9E100C20MP12 | 38,500 | $1,925 |
| No | 206971345 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TM9E100C20MP12 | 38,500 | $1,925 |
| No | 206971397 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TL8E100C20UH11 | 38,000 | $1,900 |
| No | 206971401 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TL8E100C20UH11 | 38,000 | $1,900 |
| No | 206971349 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TM9E080C20MP12 | 38,500 | $1,925 |
| No | 206971353 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TM9E080C20MP12 | 38,500 | $1,925 |
| No | 206971189 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TM9V120D20MP12 | 39,000 | $1,950 |
| No | 206971193 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TP9C120D20MP13 | 39,000 | $1,950 |
| No | 206971197 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | LP9C120D20MP13 | 39,000 | $1,950 |
| No | 206971199 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TM9V120D20MP12 | 39,000 | $1,950 |
| No | 206971203 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TP9C120D20MP13 | 39,000 | $1,950 |
| No | 206971207 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | LP9C120D20MP13 | 39,000 | $1,950 |
| No | 207335316 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TM8Y120C20MP11 | 37,800 | $1,890 |
| No | 207335313 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TM8Y100C20MP11 | 37,800 | $1,890 |
| No | 207335315 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TM8Y120C20MP11 | 37,800 | $1,890 |
| No | 207335314 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TM8Y100C20MP11 | 37,800 | $1,890 |
| No | 206971261 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TMLE120C20MP11 | 37,600 | $1,880 |
| No | 206971249 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TM8E120C20MP11 | 37,600 | $1,880 |
| No | 206971253 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TMLE120C20MP11 | 37,600 | $1,880 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206971257 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TM8E120C20MP11 | 37,600 | $1,880 |
| No | 207335239 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TM8Y080C16MP11 | 24,200 | $1,210 |
| No | 207335238 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TM8Y080C16MP11 | 24,200 | $1,210 |
| No | 207335237 | LUXAIRE | HMH72B361 | CM36CBCA1 | TM8Y080C16MP11 | 24,200 | $1,210 |
| No | 206923367 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TL8E080C16UH11 | 24,000 | $1,200 |
| No | 206923371 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TL8E080C16UH11 | 24,000 | $1,200 |
| No | 206923375 | LUXAIRE | HMH72B361 | CM36CBCA1 | TL8E080C16UH11 | 24,000 | $1,200 |
| No | 206971357 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TM8E080C20MP11 | 37,800 | $1,890 |
| No | 206971361 | LUXAIRE | HMH72B601 | CF64DXA1+TXV | TMLE080C20MP11 | 37,800 | $1,890 |
| No | 206971365 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TM8E080C20MP11 | 37,800 | $1,890 |
| No | 206971369 | LUXAIRE | HMH72B601 | CM64DXA1+TXV | TMLE080C20MP11 | 37,800 | $1,890 |
| No | 206922372 | LUXAIRE | HMH72B361 | CM36CBCA1 | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 206922380 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 206922384 | LUXAIRE | HMH72B361 | CM36CBCA1 | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 206922392 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | LP9C060B12MP13 | 25,000 | $1,250 |
| No | 206922394 | LUXAIRE | HMH72B361 | CM36CBCA1 | LP9C060B12MP13 | 25,000 | $1,250 |
| No | 206922544 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 206922548 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 206922552 | LUXAIRE | HMH72B361 | CM36CBCA1 | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 206923331 | LUXAIRE | HMH72B361 | CF36CXA1+TXV | TL9E060B12UH11 | 24,800 | $1,240 |
| No | 206923335 | LUXAIRE | HMH72B361 | CM36CXA1+TXV | TL9E060B12UH11 | 24,800 | $1,240 |
| No | 206923339 | LUXAIRE | HMH72B361 | CM36CBCA1 | TL9E060B12UH11 | 24,800 | $1,240 |
| No | 206922580 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 206922584 | LUXAIRE | HMH72B361 | CF36BBCA1 | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 206922588 | LUXAIRE | HMH72B361 | CM36BXA1+TXV | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 206922592 | LUXAIRE | HMH72B361 | CM36BBCA1 | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 206922596 | LUXAIRE | HMH72B361 | CU36BXA1+TXV | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 206923243 | LUXAIRE | HMH72B361 | CF36AXA1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206923247 | LUXAIRE | HMH72B361 | CF36AXA1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206923251 | LUXAIRE | HMH72B361 | CM36AXA1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206923255 | LUXAIRE | HMH72B361 | CM36AXA1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206922524 | LUXAIRE | HMH72B361 | CF36BXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 207176108 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 206923507 | LUXAIRE | HMH72B361 | AE36BX21+TXV | | 24,400 | $1,220 |
| No | 206971741 | LUXAIRE | HMH72B481 | AVC60DX21+TXV | | 30,600 | $1,530 |
| No | 206971745 | LUXAIRE | HMH72B481 | CF64DXA1+ME14DN21+TXV | | 30,000 | $1,500 |
| No | 206971749 | LUXAIRE | HMH72B481 | CM64DXA1+ME14DN21+TXV | | 30,000 | $1,500 |
| No | 207175996 | LUXAIRE | HMH72B241 | CU36CXA1+TXV | TM9Y060B12MP11 | 14,500 | $725 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207176020 | LUXAIRE | HMH72B241 | AE36BX21+TXV | | 14,300 | $715 |
| No | 207176024 | LUXAIRE | HMH72B241 | AE36BBA21 | | 14,300 | $715 |
| No | 207176040 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TM9Y100C16MP11 | 24,200 | $1,210 |
| No | 207176056 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TM9Y080C16MP11 | 24,600 | $1,230 |
| No | 207176072 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 206922246 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TM9V080C16MP12 | 24,400 | $1,220 |
| No | 206922258 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TP9C080C16MP13 | 24,400 | $1,220 |
| No | 206922266 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | LP9C080C16MP13 | 24,400 | $1,220 |
| No | 206922286 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 206922298 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 206922306 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | LP9C080B12MP13 | 24,400 | $1,220 |
| No | 206922376 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 206922388 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 206922396 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | LP9C060B12MP13 | 25,000 | $1,250 |
| No | 206922504 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TM9E080C16MP12 | 24,600 | $1,230 |
| No | 206923343 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TL9E060B12UH11 | 24,800 | $1,240 |
| No | 206923379 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TL8E080C16UH11 | 24,000 | $1,200 |
| No | 206923411 | LUXAIRE | HMH72B361 | CF36CXA1+MVC16CN21+TXV | | 24,200 | $1,210 |
| No | 206923415 | LUXAIRE | HMH72B361 | CM36CXA1+MVC16CN21+TXV | | 24,200 | $1,210 |
| No | 206923419 | LUXAIRE | HMH72B361 | CM36CBCA1+MVC16CN21 | | 24,200 | $1,210 |
| No | 206923423 | LUXAIRE | HMH72B361 | CF36CXA1+MVC12CN21+TXV | | 24,000 | $1,200 |
| No | 206923427 | LUXAIRE | HMH72B361 | CM36CXA1+MVC12CN21+TXV | | 24,000 | $1,200 |
| No | 206923431 | LUXAIRE | HMH72B361 | CM36CBCA1+MVC12CN21 | | 24,000 | $1,200 |
| No | 206921630 | LUXAIRE | HMH72B241 | CU36CXA1+TXV | TM9V060B12MP12 | 14,500 | $725 |
| No | 206921638 | LUXAIRE | HMH72B241 | CU36CXA1+TXV | TP9C060B12MP13 | 14,500 | $725 |
| No | 206921644 | LUXAIRE | HMH72B241 | CU36CXA1+TXV | LP9C060B12MP13 | 14,500 | $725 |
| No | 206922128 | LUXAIRE | HMH72B241 | AVC36BX21+TXV | | 14,300 | $715 |
| No | 206922639 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TM8V120C20MP12 | 24,600 | $1,230 |
| No | 206922651 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TM8V100C20MP12 | 24,600 | $1,230 |
| No | 206922663 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TMLV120C20MP12 | 24,600 | $1,230 |
| No | 206922675 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TPLC100C20MP13 | 24,600 | $1,230 |
| No | 206922692 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | LPLC100C20MP13 | 24,600 | $1,230 |
| No | 206922687 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TPLC120C20MP13 | 24,600 | $1,230 |
| No | 206922698 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | LPLC120C20MP13 | 24,600 | $1,230 |
| No | 206922732 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 206922744 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TM8V080C16MP12 | 24,600 | $1,230 |
| No | 206922756 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TMLV100C16MP12 | 24,600 | $1,230 |
| No | 206922768 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TPLC080C16MP13 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922780 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 206922794 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | LPLC100C16MP13 | 24,600 | $1,230 |
| No | 206922788 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | LPLC080C16MP13 | 24,600 | $1,230 |
| No | 206922978 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TM8E120C16MP11 | 24,600 | $1,230 |
| No | 206922990 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TMLE120C16MP11 | 24,600 | $1,230 |
| No | 206923010 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TM8E100C16MP11 | 24,600 | $1,230 |
| No | 206923022 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TMLE100C16MP11 | 24,600 | $1,230 |
| No | 206923042 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206923054 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206923115 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TM8E080C16MP11 | 24,400 | $1,220 |
| No | 206923127 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TMLE080C16MP11 | 24,400 | $1,220 |
| No | 206923147 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TM8E080B12MP11 | 24,600 | $1,230 |
| No | 206923159 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 206923475 | LUXAIRE | HMH72B361 | CF36BXA1+ME12BN21+TXV | | 24,400 | $1,220 |
| No | 206923479 | LUXAIRE | HMH72B361 | CF36BBCA1+ME12BN21 | | 24,400 | $1,220 |
| No | 206923483 | LUXAIRE | HMH72B361 | CM36BXA1+ME12BN21+TXV | | 24,400 | $1,220 |
| No | 206923487 | LUXAIRE | HMH72B361 | CM36BBCA1+ME12BN21 | | 24,400 | $1,220 |
| No | 206923491 | LUXAIRE | HMH72B361 | CF36BXA1+ME08BN21+TXV | | 23,600 | $1,180 |
| No | 206924355 | LUXAIRE | HMH72B361 | CF36BBCA1+ME08BN21 | | 23,600 | $1,180 |
| No | 206923495 | LUXAIRE | HMH72B361 | CM36BXA1+ME08BN21+TXV | | 23,600 | $1,180 |
| No | 206924359 | LUXAIRE | HMH72B361 | CM36BBCA1+ME08BN21 | | 23,600 | $1,180 |
| No | 206923499 | LUXAIRE | HMH72B361 | AVC36CX21+TXV | | 24,200 | $1,210 |
| No | 206923503 | LUXAIRE | HMH72B361 | AVC36BX21+TXV | | 24,600 | $1,230 |
| No | 206921808 | LUXAIRE | HMH72B241 | CU36CXA1+TXV | TM8V100C16MP12 | 14,300 | $715 |
| No | 206921816 | LUXAIRE | HMH72B241 | CU36CXA1+TXV | TM8V080C16MP12 | 14,300 | $715 |
| No | 206921824 | LUXAIRE | HMH72B241 | CU36CXA1+TXV | TMLV100C16MP12 | 14,300 | $715 |
| No | 206921832 | LUXAIRE | HMH72B241 | CU36CXA1+TXV | TPLC080C16MP13 | 14,300 | $715 |
| No | 206921840 | LUXAIRE | HMH72B241 | CU36CXA1+TXV | TPLC100C16MP13 | 14,300 | $715 |
| No | 206921846 | LUXAIRE | HMH72B241 | CU36CXA1+TXV | LPLC080C16MP13 | 14,300 | $715 |
| No | 206921850 | LUXAIRE | HMH72B241 | CU36CXA1+TXV | LPLC100C16MP13 | 14,300 | $715 |
| No | 206922108 | LUXAIRE | HMH72B241 | CF36CXA1+ME12CN21+TXV | | 14,200 | $710 |
| No | 206922112 | LUXAIRE | HMH72B241 | CM36CXA1+ME12CN21+TXV | | 14,200 | $710 |
| No | 206922166 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TM9V100C20MP12 | 24,400 | $1,220 |
| No | 206922178 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TP9C100C20MP13 | 24,400 | $1,220 |
| No | 206922186 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | LP9C100C20MP13 | 24,400 | $1,220 |
| No | 206922206 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TM9V100C16MP12 | 24,400 | $1,220 |
| No | 206922218 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TP9C100C16MP13 | 24,400 | $1,220 |
| No | 206922226 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | LP9C100C16MP13 | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206922488 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TM9E100C16MP12 | 24,600 | $1,230 |
| No | 206922520 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206922556 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 206923327 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TL9E080C16UH11 | 24,600 | $1,230 |
| No | 206923435 | LUXAIRE | HMH72B361 | CF36BXA1+MVC12BN21+TXV | | 24,400 | $1,220 |
| No | 206923439 | LUXAIRE | HMH72B361 | CF36BBCA1+MVC12BN21 | | 24,400 | $1,220 |
| No | 206923443 | LUXAIRE | HMH72B361 | CM36BXA1+MVC12BN21+TXV | | 24,400 | $1,220 |
| No | 206923447 | LUXAIRE | HMH72B361 | CM36BBCA1+MVC12BN21 | | 24,400 | $1,220 |
| No | 206921550 | LUXAIRE | HMH72B241 | CU36CXA1+TXV | TM9V080B12MP12 | 14,300 | $715 |
| No | 206921558 | LUXAIRE | HMH72B241 | CU36CXA1+TXV | TP9C080B12MP13 | 14,300 | $715 |
| No | 206921564 | LUXAIRE | HMH72B241 | CU36CXA1+TXV | LP9C080B12MP13 | 14,300 | $715 |
| No | 206922124 | LUXAIRE | HMH72B241 | AVC36CX21+TXV | | 14,200 | $710 |
| No | 206922813 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TM8V080B12MP12 | 24,400 | $1,220 |
| No | 206922830 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | LPLC080B12MP13 | 24,400 | $1,220 |
| No | 206922825 | LUXAIRE | HMH72B361 | CU36CXA1+TXV | TPLC080B12MP13 | 24,400 | $1,220 |
| No | 206923451 | LUXAIRE | HMH72B361 | CF36CXA1+ME16CN21+TXV | | 23,800 | $1,190 |
| No | 206923455 | LUXAIRE | HMH72B361 | CM36CXA1+ME16CN21+TXV | | 23,800 | $1,190 |
| No | 206923459 | LUXAIRE | HMH72B361 | CM36CBCA1+ME16CN21 | | 23,800 | $1,190 |
| No | 206923467 | LUXAIRE | HMH72B361 | CM36CXA1+ME12CN21+TXV | | 24,200 | $1,210 |
| No | 206923463 | LUXAIRE | HMH72B361 | CF36CXA1+ME12CN21+TXV | | 24,200 | $1,210 |
| No | 206922084 | LUXAIRE | HMH72B241 | CF36CXA1+MVC12CN21+TXV | | 14,200 | $710 |
| No | 206923471 | LUXAIRE | HMH72B361 | CM36CBCA1+ME12CN21 | | 24,200 | $1,210 |
| No | 206922088 | LUXAIRE | HMH72B241 | CM36CXA1+MVC12CN21+TXV | | 14,200 | $710 |
| No | 206922092 | LUXAIRE | HMH72B241 | CF36BXA1+MVC12BN21+TXV | | 14,300 | $715 |
| No | 206922096 | LUXAIRE | HMH72B241 | CF36BBAA1+MVC12BN21 | | 14,300 | $715 |
| No | 206922100 | LUXAIRE | HMH72B241 | CM36BXA1+MVC12BN21+TXV | | 14,300 | $715 |
| No | 206922104 | LUXAIRE | HMH72B241 | CM36BBAA1+MVC12BN21 | | 14,300 | $715 |
| No | 206922132 | LUXAIRE | HMH72B241 | CF36BXA1+ME08BN21+TXV | | 14,100 | $705 |
| No | 206922136 | LUXAIRE | HMH72B241 | CF36BBAA1+ME08BN21 | | 14,100 | $705 |
| No | 206922140 | LUXAIRE | HMH72B241 | CM36BXA1+ME08BN21+TXV | | 14,100 | $705 |
| No | 206922144 | LUXAIRE | HMH72B241 | CM36BBAA1+ME08BN21 | | 14,100 | $705 |
| No | 206971725 | LUXAIRE | HMH72B481 | CF64DXA1+MVC20DN21+TXV | | 30,200 | $1,510 |
| No | 206971729 | LUXAIRE | HMH72B481 | CM64DXA1+MVC20DN21+TXV | | 30,200 | $1,510 |
| No | 206971459 | LUXAIRE | HMH72B601 | CF64DXA1+MVC20DN21+TXV | | 39,000 | $1,950 |
| No | 206971463 | LUXAIRE | HMH72B601 | CM64DXA1+MVC20DN21+TXV | | 39,000 | $1,950 |
| No | 206971471 | LUXAIRE | HMH72B601 | CM64DXA1+ME20DN21+TXV | | 39,000 | $1,950 |
| No | 206971467 | LUXAIRE | HMH72B601 | CF64DXA1+ME20DN21+TXV | | 39,000 | $1,950 |
| No | 206921984 | LUXAIRE | HMH72B241 | CF36AXA1+TXV | TM8V060A12MP12 | 14,100 | $705 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206971475 | LUXAIRE | HMH72B601 | AVC60DX21+TXV | | 39,000 | $1,950 |
| No | 206921992 | LUXAIRE | HMH72B241 | CF36AXA1+TXV | TPLC060A12MP13 | 14,100 | $705 |
| No | 206921988 | LUXAIRE | HMH72B241 | CF36AXA1+TXV | TMLV060A12MP12 | 14,100 | $705 |
| No | 206921996 | LUXAIRE | HMH72B241 | CM36AXA1+TXV | TM8V060A12MP12 | 14,100 | $705 |
| No | 206922000 | LUXAIRE | HMH72B241 | CM36AXA1+TXV | TMLV060A12MP12 | 14,100 | $705 |
| No | 206922004 | LUXAIRE | HMH72B241 | CM36AXA1+TXV | TPLC060A12MP13 | 14,100 | $705 |
| No | 206921879 | LUXAIRE | HMH72B241 | CF36BXA1+TXV | TM8V080B12MP12 | 14,400 | $720 |
| No | 206921883 | LUXAIRE | HMH72B241 | CF36BXA1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 206921886 | LUXAIRE | HMH72B241 | CF36BXA1+TXV | LPLC080B12MP13 | 14,400 | $720 |
| No | 206921888 | LUXAIRE | HMH72B241 | CF36BBAA1 | TM8V080B12MP12 | 14,400 | $720 |
| No | 206921892 | LUXAIRE | HMH72B241 | CM36BXA1+TXV | TM8V080B12MP12 | 14,400 | $720 |
| No | 206921896 | LUXAIRE | HMH72B241 | CM36BBAA1 | TM8V080B12MP12 | 14,400 | $720 |
| No | 206921900 | LUXAIRE | HMH72B241 | CU36BXA1+TXV | TM8V080B12MP12 | 14,400 | $720 |
| No | 206921919 | LUXAIRE | HMH72B241 | CF36BBAA1 | LPLC080B12MP13 | 14,400 | $720 |
| No | 206921904 | LUXAIRE | HMH72B241 | CF36BBAA1 | TPLC080B12MP13 | 14,400 | $720 |
| No | 206921908 | LUXAIRE | HMH72B241 | CM36BXA1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 206921912 | LUXAIRE | HMH72B241 | CM36BBAA1 | TPLC080B12MP13 | 14,400 | $720 |
| No | 206921916 | LUXAIRE | HMH72B241 | CU36BXA1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 206921920 | LUXAIRE | HMH72B241 | CM36BXA1+TXV | LPLC080B12MP13 | 14,400 | $720 |
| No | 206921921 | LUXAIRE | HMH72B241 | CM36BBAA1 | LPLC080B12MP13 | 14,400 | $720 |
| No | 206921922 | LUXAIRE | HMH72B241 | CU36BXA1+TXV | LPLC080B12MP13 | 14,400 | $720 |
| No | 206922056 | LUXAIRE | HMH72B241 | CF36BXA1+TXV | TL8E060A12UH11 | 14,500 | $725 |
| No | 206922060 | LUXAIRE | HMH72B241 | CF36BBAA1 | TL8E060A12UH11 | 14,500 | $725 |
| No | 206922064 | LUXAIRE | HMH72B241 | CM36BXA1+TXV | TL8E060A12UH11 | 14,500 | $725 |
| No | 206922068 | LUXAIRE | HMH72B241 | CM36BBAA1 | TL8E060A12UH11 | 14,500 | $725 |
| No | 206922072 | LUXAIRE | HMH72B241 | CU36BXA1+TXV | TL8E060A12UH11 | 14,500 | $725 |
| No | 206922076 | LUXAIRE | HMH72B241 | CF36AXA1+TXV | TL8E060A12UH11 | 14,400 | $720 |
| No | 206922080 | LUXAIRE | HMH72B241 | CM36AXA1+TXV | TL8E060A12UH11 | 14,400 | $720 |
| No | 206921852 | LUXAIRE | HMH72B241 | CF36CXA1+TXV | TM8V080B12MP12 | 14,300 | $715 |
| No | 206921856 | LUXAIRE | HMH72B241 | CF36CXA1+TXV | TPLC080B12MP13 | 14,300 | $715 |
| No | 206921859 | LUXAIRE | HMH72B241 | CF36CXA1+TXV | LPLC080B12MP13 | 14,300 | $715 |
| No | 206921861 | LUXAIRE | HMH72B241 | CM36CXA1+TXV | TM8V080B12MP12 | 14,300 | $715 |
| No | 206921865 | LUXAIRE | HMH72B241 | CU36CXA1+TXV | TM8V080B12MP12 | 14,300 | $715 |
| No | 206921869 | LUXAIRE | HMH72B241 | CM36CXA1+TXV | TPLC080B12MP13 | 14,300 | $715 |
| No | 206921873 | LUXAIRE | HMH72B241 | CU36CXA1+TXV | TPLC080B12MP13 | 14,300 | $715 |
| No | 206921877 | LUXAIRE | HMH72B241 | CU36CXA1+TXV | LPLC080B12MP13 | 14,300 | $715 |
| No | 206921876 | LUXAIRE | HMH72B241 | CM36CXA1+TXV | LPLC080B12MP13 | 14,300 | $715 |
| No | 206921924 | LUXAIRE | HMH72B241 | CF36BXA1+TXV | TM8V060A12MP12 | 14,000 | $700 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921928 | LUXAIRE | HMH72B241 | CF36BXA1+TXV | TMLV060A12MP12 | 14,000 | $700 |
| No | 206921932 | LUXAIRE | HMH72B241 | CF36BXA1+TXV | TPLC060A12MP13 | 14,000 | $700 |
| No | 206921936 | LUXAIRE | HMH72B241 | CF36BBAA1 | TM8V060A12MP12 | 14,000 | $700 |
| No | 206921940 | LUXAIRE | HMH72B241 | CM36BXA1+TXV | TM8V060A12MP12 | 14,000 | $700 |
| No | 206921944 | LUXAIRE | HMH72B241 | CM36BBAA1 | TM8V060A12MP12 | 14,000 | $700 |
| No | 206921948 | LUXAIRE | HMH72B241 | CU36BXA1+TXV | TM8V060A12MP12 | 14,000 | $700 |
| No | 206921952 | LUXAIRE | HMH72B241 | CF36BBAA1 | TMLV060A12MP12 | 14,000 | $700 |
| No | 206921956 | LUXAIRE | HMH72B241 | CM36BXA1+TXV | TMLV060A12MP12 | 14,000 | $700 |
| No | 206921960 | LUXAIRE | HMH72B241 | CM36BBAA1 | TMLV060A12MP12 | 14,000 | $700 |
| No | 206921964 | LUXAIRE | HMH72B241 | CU36BXA1+TXV | TMLV060A12MP12 | 14,000 | $700 |
| No | 206921972 | LUXAIRE | HMH72B241 | CM36BXA1+TXV | TPLC060A12MP13 | 14,000 | $700 |
| No | 206921968 | LUXAIRE | HMH72B241 | CF36BBAA1 | TPLC060A12MP13 | 14,000 | $700 |
| No | 206921976 | LUXAIRE | HMH72B241 | CM36BBAA1 | TPLC060A12MP13 | 14,000 | $700 |
| No | 206921980 | LUXAIRE | HMH72B241 | CU36BXA1+TXV | TPLC060A12MP13 | 14,000 | $700 |
| No | 206922008 | LUXAIRE | HMH72B241 | CF36AXA1+TXV | TM8E040A12MP11 | 14,400 | $720 |
| No | 206922012 | LUXAIRE | HMH72B241 | CF36AXA1+TXV | TMLE040A12MP11 | 14,400 | $720 |
| No | 206922016 | LUXAIRE | HMH72B241 | CM36AXA1+TXV | TM8E040A12MP11 | 14,400 | $720 |
| No | 206922020 | LUXAIRE | HMH72B241 | CM36AXA1+TXV | TMLE040A12MP11 | 14,400 | $720 |
| No | 206922036 | LUXAIRE | HMH72B241 | CF36BXA1+TXV | TL9E060B12UH11 | 14,500 | $725 |
| No | 206922040 | LUXAIRE | HMH72B241 | CF36BBAA1 | TL9E060B12UH11 | 14,500 | $725 |
| No | 206922044 | LUXAIRE | HMH72B241 | CM36BXA1+TXV | TL9E060B12UH11 | 14,500 | $725 |
| No | 206922048 | LUXAIRE | HMH72B241 | CM36BBAA1 | TL9E060B12UH11 | 14,500 | $725 |
| No | 206922052 | LUXAIRE | HMH72B241 | CU36BXA1+TXV | TL9E060B12UH11 | 14,500 | $725 |
| No | 206971737 | LUXAIRE | HMH72B481 | CM64DXA1+MVC14DN21+TXV | | 29,200 | $1,460 |
| No | 206971733 | LUXAIRE | HMH72B481 | CF64DXA1+MVC14DN21+TXV | | 29,200 | $1,460 |
| No | 206787297 | LUXAIRE | HMH72B241 | AE36CX21+TXV | | 14,000 | $700 |
| No | 206787298 | LUXAIRE | HMH72B361 | AE36CX21+TXV | | 24,000 | $1,200 |
| No | 206787299 | LUXAIRE | HMH72B481 | AE60DX21+TXV | | 30,200 | $1,510 |
| No | 206787300 | LUXAIRE | HMH72B601 | AE60DX21+TXV | | 36,800 | $1,840 |
| No | 212348361 | MAXI AIR | NE-T52-PLA12INT | NE-T52-PLA12EXT | | 8,200 | $410 |
| No | 212348364 | MAXI AIR | NE-T52-PLA18INT | NE-T52-PLA18EXT | | 14,000 | $700 |
| No | 212348360 | MAXI AIR | NE-T52-SUPAE12E | NE-T52-SUPAE12I | | 10,000 | $500 |
| No | 210426580 | MAXI AIR | MAXS-2430 | AHMS-3015 | | 21,000 | $1,050 |
| No | 203238009 | MAXI AIR | YS21F-12HRDN1 | YS21F-12HRDN1 | | 8,200 | $410 |
| No | 203238010 | MAXI AIR | YS21F-18HRDN1 | YS21F-18HRDN1 | | 14,000 | $700 |
| No | 206799640 | MAXI AIR CENTRAL | CLASS36CC | AHAN3615 | | 19,800 | $990 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206799638 | MAXI AIR CENTRAL | CLASS24CC | AHAN2410 | | 15,400 | $770 |
| No | 204012243 | MAX-R | MAX-R/9K30-OUT | MAX-R/9K30-INT | | 6,900 | $345 |
| No | 204012248 | MAX-R | MAX-R/18K20-OUT | MAX-R/18K20-INT | | 11,000 | $550 |
| No | 204012251 | MAX-R | MAX-R(MZ)36K30 | Heat pump without ducts | | 23,200 | $1,160 |
| No | 204012244 | MAX-R | MAX-R/12K30-OUT | MAX-R/12K30-INT | | 7,800 | $390 |
| No | 207338192 | MAX-R | MAX-R18K30MZGR | Heat pump without ducts | | 12,800 | $640 |
| No | 205982977 | MAX-R | MAX-R12K30GR23(OUT) | MAX-R12K30GR23(IN) | | 6,800 | $340 |
| No | 207338193 | MAX-R | MAX-R24K30MZGR | Heat pump without ducts | | 16,600 | $830 |
| No | 207338194 | MAX-R | MAX-R36K30MZGR | Heat pump without ducts | | 18,000 | $900 |
| No | 205982975 | MAX-R | MAX-R18K30GR23(OUT) | MAX-R18K30GR23(IN) | | 12,400 | $620 |
| No | 205982979 | MAX-R | MAX-R 12K35 GR38 (OUT) | MAX-R 12K35 GR38 (INT) | | 8,300 | $415 |
| No | 208101916 | MDV | MOX330U-18HFN1-MR0 | MAC-24HWDN1-MN0 | | 13,000 | $650 |
| No | 208101915 | MDV | MOE30U-48HFN1-M-[X1] | MAC-48HWDN1-MN0 | | 32,000 | $1,600 |
| No | 208101914 | MDV | MOE31U-36HFN1-M | MAC-36HWDN1-MN0 | | 33,000 | $1,650 |
| No | 208101913 | MDV | MOE30U-48HFN1-MR0 | MAC-48HWDN1-MN0 | | 30,500 | $1,525 |
| No | 208101912 | MDV | MOD30U-36HFN1-MR0 | MAC-36HWDN1-MN0 | | 19,800 | $990 |
| No | 208101910 | MDV | MOD30-24HFN1-MW | MAC-24HWDN1-MN0 | | 21,000 | $1,050 |
| No | 208101909 | MDV | MOX430U-18HFN1-M | MAC-24HWDN1-MN0 | | 14,700 | $735 |
| No | 208101908 | MDV | MOE30U-60HFN1-MR0 | MAC-60HWDN1-MN0 | | 34,000 | $1,700 |
| No | 208101907 | MDV | MOD30U-30HFN1-MR0 | MAC-36HWDN1-MN0 | | 22,000 | $1,100 |
| No | 208101906 | MDV | MOX430U-24HFN1-MR0 | MAC-24HWDN1-MN0 | | 22,000 | $1,100 |
| No | 209960481 | MDV | MOE31U-36HFN1-MR0 | MVC-36HWFN1-MR0 | | 30,400 | $1,520 |
| No | 207785326 | MDV | MOE31U-60HFN1-MR0 | MVC-60HWFN1-MR0 | | 37,000 | $1,850 |
| No | 207785325 | MDV | MOE30U-48HFN1-MQ3 | MVC-48HWFN1-MQ3 | | 37,000 | $1,850 |
| No | 207785327 | MDV | MOD31U-36HFN1-MR0 | MVC-36HWFN1-MR0 | | 20,400 | $1,020 |
| No | 207785324 | MDV | MOD30U-30HFN1-MR0Q1W | MVC-30HWFN1-MQ1W | | 19,000 | $950 |
| No | 207785323 | MDV | MOD31-23HFN1-MT2Q1W | MVC-23HWFN1-MQ1W | | 18,000 | $900 |
| No | 207785322 | MDV | MOX430-18HFN1-MT2Q1W | MVC-18HWFN1-MQ1W | | 14,800 | $740 |
| No | 207699010 | MDV | MOE31U-36HFN1-M | MVC-36HWFN1-M | | 30,400 | $1,520 |
| No | 207699009 | MDV | MOD30U-30HFN1-MR0(X) | MVC-30HWFN1-M | | 21,000 | $1,050 |
| No | 210135404 | MDV | MOE30U-60HFN1-MR0 | MVC-60HWFN1-MQ0 | | 37,000 | $1,850 |
| No | 207825918 | MDV | MOE30U-60HFN1-MR0 | MVC-60HWFN1-M | | 37,000 | $1,850 |
| No | 207825917 | MDV | MOE30U-48HFN1-MR0 | MVC-48HWFN1-M | | 37,000 | $1,850 |
| No | 207825916 | MDV | MOD30U-36HFN1-MR0 | MVC-36HWFN1-M | | 20,400 | $1,020 |
| No | 207825914 | MDV | MOX430U-24HFN1-MR0 | MVC-24HWFN1-M | | 21,000 | $1,050 |
| No | 207825913 | MDV | MOX330U-18HFN1-MR0 | MVC-18HWFN1-M | | 12,000 | $600 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207802619 | MDV | MOE30U-60HFN1-M(GA)(X) | MVC-60HWFN1-M(GA) | | 37,800 | $1,890 |
| No | 207802618 | MDV | MOE30U-48HFN1-MP0(GA) | MVC-48HWFN1-M(GA) | | 38,000 | $1,900 |
| No | 207802617 | MDV | MOD30U-36HFN1-MP0(GA) | MVC-36HWFN1-M(GA) | | 27,000 | $1,350 |
| No | 208102122 | MDV | MOD30U-36HFN1-M(GA) | MVCU-36HWFN1-M(GA) | | 27,000 | $1,350 |
| No | 207802616 | MDV | MOD30U-30HFN1-M(GA) | MVC-30HWFN1-M(GA) | | 20,400 | $1,020 |
| No | 207742578 | MDV | MOD33-24HFN1-MT0W | MVC-23HWFN1-M | | 17,000 | $850 |
| No | 207742577 | MDV | MOX430-18HFN1-MU0W | MVC-18HWFN1-MW(GA) | | 13,200 | $660 |
| No | 210321396 | MDV | MOX430-17HFN1-MT0W | MAC-24HWDN1-MN0-N | | 13,000 | $650 |
| No | 200059311 | MDV | MOBA30-12HFN1-BP0W | MSAEB-12HRFN1-BQ0W | | 7,200 | $360 |
| No | 8856677 | MDV | M4OF-36HFN1-M | CS11M-09HRFN1-MX0W(A) | | 24,600 | $1,230 |
| No | 200059317 | MDV | MOB30-18HFN1-MP0W | MSAEC-18HRDN1-MP0W | | 11,400 | $570 |
| No | 10028968 | MDV | MOE30U-48HFN1-M* | MTI-48HWFN1-M | | 33,400 | $1,670 |
| No | 8704431 | MDV | MOB30-09HFN1-MX0W | CS11M-09HRFN1-MX0W(A) | | 6,900 | $345 |
| No | 8740667 | MDV | MOBA30-09HFN1-MT0W | CCA3U-09HRFN1-M(C) | | 5,800 | $290 |
| No | 9101403 | MDV | MOCA31-18HFN1-MT0W | CS11M-18HRFN1-MT0W | | 11,400 | $570 |
| No | 8779030 | MDV | MOB32-09HFN1-MX0W | CS11M-09HRFN1-MX0W(A) | | 6,900 | $345 |
| No | 9101401 | MDV | MOBA30-09HFN1-MT0W | CS11M-09HRFN1-MX0W(A) | | 5,800 | $290 |
| No | 9101402 | MDV | MOB30-12HFN1-MT0W | CS11M-12HRFN1-MU5W | | 7,700 | $385 |
| No | 9101404 | MDV | MOD31-24HFN1-MT0W | CS11M-23HRFN1-MT0W | | 15,300 | $765 |
| No | 8779031 | MDV | MOB32-12HFN1-MV0W | MCA3U-12HRFN1-M(C) | | 8,200 | $410 |
| No | 8740664 | MDV | MOB30-12HFN1-MV0W | CCA3U-12HRFN1-M(C) | | 8,700 | $435 |
| No | 8740674 | MDV | MOD31-24HFN1-MT0W | MCDU-24HRFN1-M(C) | | 15,800 | $790 |
| No | 8738631 | MDV | MOB30-12HFN1-BV0W | MS11M-12HRFN1-BV0W | | 7,600 | $380 |
| No | 8688148 | MDV | MOBA30-09HFN1-MT0W | MSABB-09HRFN1-MT0W | | 6,400 | $320 |
| No | 8719215 | MDV | MOCA31-18HFN1-MT0W | MSABE-18HRFN1-MT0W | | 10,400 | $520 |
| No | 8779182 | MDV | MOB01-12HFN1-BT0W | MSMBB-12HRFN1-BT0W | | 7,100 | $355 |
| No | 200059281 | MDV | MOCA30-09HFN1-MZA5W | MSOP1B-09HRFN1-MZA5W | | 7,200 | $360 |
| No | 200059283 | MDV | MOCA30-12HFN1-MZ50W | MSOP1B-12HRFN1-MZ50W | | 6,800 | $340 |
| No | 200059293 | MDV | MOB30-12HFN1-MV0W | MTIU-12HWFN1-M | | 8,500 | $425 |
| No | 200059299 | MDV | MOD31-24HFN1-MT0W | MTIU-24HWFN1-M | | 16,000 | $800 |
| No | 8856675 | MDV | M2OF-18HFN1-M | CS11M-09HRFN1-MX0W(A) | | 12,000 | $600 |
| No | 8856676 | MDV | M3OF-27HFN1-M | CS11M-09HRFN1-MX0W(A) | | 17,200 | $860 |
| No | 8740675 | MDV | MOD31-24HFN1-MT0W | MUEU-24HRFN1-M(C) | | 15,000 | $750 |
| No | 8967208 | MDV | M5OF-48HFN1-M | CS11M-09HRFN1-MX0W(A) | | 29,600 | $1,480 |
| No | 200059291 | MDV | MOBA30-09HFN1-MT0W | MTIU-09HWFN1-M | | 6,800 | $340 |
| No | 205767334 | MDV | MOE30U-36HFN1-M-[X] | MUE-36HRFN1-M(C) | | 25,000 | $1,250 |
| No | 205782860 | MDV | MOD01-23HFN1-MT0W | MVB-24HWFN1-M | | 17,500 | $875 |
| No | 205823024 | MDV | MOE30U-32HFN1-M-[X] | MCD-32HRFN1-M(D) | | 23,000 | $1,150 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205823025 | MDV | MOE30U-32HFN1-M-[X] | MUE-32HRFN1-M(C) | | 23,000 | $1,150 |
| No | 206361867 | MDV | MOD33-24HFN1-MT0W | MSAG11D-23HRFN1-MU0W | | 16,800 | $840 |
| No | 206143045 | MDV | MOD30U-36HFN1-MP0 | MUE-36HRFN1-M(C) | | 22,000 | $1,100 |
| No | 206361859 | MDV | MOX430-18HFN1-MT8W | MSAG11D-18HRFN1-MT8W | | 11,900 | $595 |
| No | 206361862 | MDV | MOX430-17HFN1-MT0W | MSAG11D-18HRFN1-MT8W | | 11,100 | $555 |
| No | 206361864 | MDV | MOX230-12HFN1-BW0W | MSAG11B-12HRFN1-BU5W | | 8,200 | $410 |
| No | 206369563 | MDV | MOD31-36HFN1-MP0W | MSABF-36HRFNX-MQ0W | | 24,000 | $1,200 |
| No | 206361860 | MDV | MOX330-09HFN1-MY5W | MSAG11B-09HRFN1-MX7W(GA) | | 7,400 | $370 |
| No | 206369558 | MDV | MOX230-09HFN1-MW5W | MSEPB-09HRFN1-MY5W(GA) | | 6,100 | $305 |
| No | 206369561 | MDV | MOD33-24HFN1-MT0W | MSEPD-24HRFN1-MU0W | | 14,200 | $710 |
| No | 202147804 | MDV | MOB30-09HFN1-BX0W | MSABB-09HRFN1-BX0W | | 5,800 | $290 |
| No | 8687736 | MDV | MOB30-12HFN1-BT0W | MSABB-12HRFN1-BT0W | | 7,100 | $355 |
| No | 8704432 | MDV | MOB30-12HFN1-MV0W | CS11M-12HRFN1-MU5W | | 7,800 | $390 |
| No | 8779033 | MDV | MOB32-12HFN1-MV0W | CS11M-12HRFN1-MU5W | | 7,800 | $390 |
| No | 10028967 | MDV | MOD30U-36HFN1-M* | MTI-36HWFN1-M | | 27,600 | $1,380 |
| No | 200059289 | MDV | MOB30-09HFN1-MX0W | MTIU-09HWFN1-M | | 7,200 | $360 |
| No | 8739928 | MDV | MOB30-12HFN1-MT0W | CCA3U-12HRFN1-M(C) | | 7,500 | $375 |
| No | 8739929 | MDV | MOB30-12HFN1-MT0W | CFAU-12HRFN1-M(C) | | 7,200 | $360 |
| No | 8740671 | MDV | MOCA31-18HFN1-MT0W | CCA3U-18HRFN1-M(C) | | 12,000 | $600 |
| No | 200059297 | MDV | MOCA31-18HFN1-MT0W | MTIU-18HWFN1-M | | 12,000 | $600 |
| No | 8858349 | MDV | M3OF-27HFN1-M** | MSMBB-09HRFN1-MW0W | | 17,800 | $890 |
| No | 8740676 | MDV | MOD30U-36HFN1-M | MCD-36HRFN1-M(C) | | 25,200 | $1,260 |
| No | 8740672 | MDV | MOCA31-18HFN1-MT0W | MUEU-18HRFN1-M(C) | | 12,000 | $600 |
| No | 8819860 | MDV | MOE30U-48HFN1-M | MUE-48HRFN1-M(C) | | 35,000 | $1,750 |
| No | 8819859 | MDV | MOE30U-48HFN1-M | MCD-48HRFN1-M(D) | | 35,000 | $1,750 |
| No | 200059285 | MDV | MOE30U-60HFN1-M | MHG-60HWFN1-MW | | 37,600 | $1,880 |
| No | 200059287 | MDV | MOE30U-60HFN1-M | MUE-60HRFN1-MW | | 39,000 | $1,950 |
| No | 8994415 | MDV | M4OH-36HFN1-M | CS11M-09HRFN1-MX0W(A) | | 23,200 | $1,160 |
| No | 201810029 | MDV | M4OH-36HFN1-M | MTIU-09HWFN1-M | | 24,600 | $1,230 |
| No | 202576816 | MDV | MOBA30-09HFN1-BS0W | MSABA-09HRFN1-BS0W | | 6,000 | $300 |
| No | 202576820 | MDV | MOB30-18HFN1-MS0W | MSABD-18HRFN1-MS0W | | 11,000 | $550 |
| No | 206369559 | MDV | MOX230-12HFN1-MV5W | MSEPB-12HRFN1-MW5W(GA) | | 8,000 | $400 |
| No | 206369513 | MDV | MOX330-18HFN1-MS0W | MSAG11C-18HRDN1-MS0W | | 11,400 | $570 |
| No | 206369509 | MDV | MOX230-09HFN1-BS5W | MSAG11A-09HRFN1-BS5W | | 6,000 | $300 |
| No | 206369511 | MDV | MOX230-09HFN1-MT0W | MSAG11A-09HRFN1-MT0W | | 6,000 | $300 |
| No | 206369512 | MDV | MOX230-12HFN1-MS8W | MSAG11B-12HRFN1-MS0W | | 7,000 | $350 |
| No | 206369507 | MDV | MOX330-18HFN1-MS0W | MSAEC-18HRDN1-MP0W | | 11,900 | $595 |
| No | 206361865 | MDV | MOX230-09HFN1-MW5W | MSAG11B-09HRFN1-MV8W(GA) | | 6,100 | $305 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206369506 | MDV | MOX230-12HFN1-MS8W | MSAEB-12HRFN1-MQ0W | | 7,000 | $350 |
| No | 206369505 | MDV | MOX230-09HFN1-MT0W | MSAEA-09HRDN1-MQ0W | | 5,800 | $290 |
| No | 206369560 | MDV | MOX430-18HFN1-MT8W | MSEPC-18HRFN1-MU0W | | 12,700 | $635 |
| No | 206330123 | MDV | MOX330-09HFN1-MY5W | MTIU-09HWFN1-M | | 6,400 | $320 |
| No | 205993854 | MDV | MOX430-17HFN1-MT0W | MSEPC-18HRFN1-MU0W | | 10,800 | $540 |
| No | 205993844 | MDV | MOX230-12HFN1-BW0W | MSEPB-12HRFN1-BW0W | | 7,400 | $370 |
| No | 205993845 | MDV | MOX330-09HFN1-MY5W | MSEPB-09HRFN1-MY5W(GA) | | 7,500 | $375 |
| No | 206330126 | MDV | MOX330-12HFN1-MW5W | MCA3U-12HRFN1-M(C) | | 7,900 | $395 |
| No | 206330135 | MDV | MOD30-24HFN1-MU0W | MCDU-24HRFN1-M(C) | | 14,500 | $725 |
| No | 206330125 | MDV | MOX230-12HFN1-MV5W | MFAU-12HRFN1-M(C) | | 6,900 | $345 |
| No | 206330119 | MDV | MOX230-12HFN1-MV5W | MCA3U-12HRFN1-M(C) | | 7,800 | $390 |
| No | 206330118 | MDV | MOX230-09HFN1-MW5W | MCA3U-09HRFN1-M(C) | | 6,100 | $305 |
| No | 206330121 | MDV | MOX230-09HFN1-MW5W | MTIU-09HWFN1-M | | 6,300 | $315 |
| No | 206330124 | MDV | MOX230-12HFN1-MV5W | MTIU-12HWFN1-M | | 8,300 | $415 |
| No | 205993851 | MDV | MOX230-12HFN1-BW0W | MS11M-12HRFN1-BV0W | | 6,800 | $340 |
| No | 207338220 | MDV | MOX230-12HFN1-BV0Q1W | MSABB-12HRFN1-BV0Q1W | | 7,400 | $370 |
| No | 207338212 | MDV | MOE30U-36HFN1-M(GA) | MUE-36HRFN1-M(C) | | 25,000 | $1,250 |
| No | 207339192 | MDV | M3OH-27HFN1-MQ1 | MSABB-09HRFN1-MS0Q1W | | 16,000 | $800 |
| No | 207338206 | MDV | MOD30U-36HFN1-MP0(GA) | MUE-36HRFN1-M(C) | | 22,000 | $1,100 |
| No | 207339191 | MDV | M2OA-18HFN1-MQ1 | MSABB-09HRFN1-MS0Q1W | | 12,000 | $600 |
| No | 205993846 | MDV | MOX330-12HFN1-MW5W | MSEPB-12HRFN1-MW5W(GA) | | 7,500 | $375 |
| No | 205746254 | MDV | MOX430-17HFN1-MT0W | CS11M-18HRFN1-MT0W | | 10,900 | $545 |
| No | 206361861 | MDV | MOX330-12HFN1-MW5W | MSAG11B-12HRFN1-MV0W(GA) | | 7,300 | $365 |
| No | 206330127 | MDV | MOX330-12HFN1-MW5W | MTIU-12HWFN1-M | | 8,300 | $415 |
| No | 206361866 | MDV | MOX230-12HFN1-MV5W | MSAG11B-12HRFN1-MV0W(GA) | | 8,000 | $400 |
| No | 202415591 | MDV | MOD30-18HFN1-MZ22W | MSAB2F-18HRFN1-MZ22W | | 12,300 | $615 |
| No | 206714980 | MDV | M2OA-18HFN1-M | MTIU-09HWFN1-M | | 11,800 | $590 |
| No | 202160451 | MDV | MOB30-09HFN1-BV0W | MS11M-09HRFN1-BV0W | | 6,000 | $300 |
| No | 206714974 | MDV | M2OI-18HFN1-M | MTIU-09HWFN1-M | | 11,000 | $550 |
| No | 206714978 | MDV | M4OH-36HFN1-M-20 | MSEPB-09HRFN1-MY5W(GA) | | 22,000 | $1,100 |
| No | 206714973 | MDV | M2OA-18HFN1-M | MSEPB-09HRFN1-MY5W(GA) | | 11,000 | $550 |
| No | 206714976 | MDV | M3OI-28HFN1-M | MSEPB-09HRFN1-MY5W(GA) | | 17,500 | $875 |
| No | 206714975 | MDV | M3OJ-27HFN1-M | MSEPB-09HRFN1-MY5W(GA) | | 16,000 | $800 |
| No | 206714977 | MDV | M4OG-36HFN1-M | MSEPB-09HRFN1-MY5W(GA) | | 23,000 | $1,150 |
| No | 205993853 | MDV | MOX330-12HFN1-MW5W | CS11M-12HRFN1-MU5W | | 7,500 | $375 |
| No | 205993852 | MDV | MOX330-09HFN1-MY5W | CS11M-09HRFN1-MX0W(A) | | 7,100 | $355 |
| No | 208132555 | MDV | M5OA-55HFN1-M* | 42 | | 35,600 | $1,780 |
| No | 208132548 | MDV | M5OA-55HFN1-M* | MTIU-09HWFN1-M | | 35,000 | $1,750 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208132547 | MDV | M5OA-55HFN1-M* | MSAG11B-09HRFN1-MX7W(GA) | | 36,400 | $1,820 |
| No | 208132546 | MDV | M5OA-55HFN1-M | MTIU-09HWFN1-M | | 35,000 | $1,750 |
| No | 208132545 | MDV | M5OA-55HFN1-M | MSEPB-09HRFN1-MY5W(GA) | | 34,400 | $1,720 |
| No | 208132554 | MDV | M5OA-55HFN1-M | 42 | | 34,600 | $1,730 |
| No | 207641258 | MDV | M3OI-28HFN1-M* | MSAG11B-09HRFN1-MX7W(GA) | | 17,400 | $870 |
| No | 207618261 | MDV | M3OI-24HFN1-M | 42 | | 16,500 | $825 |
| No | 207617656 | MDV | M3OI-24HFN1-M | MTIU-09HWFN1-M | | 18,000 | $900 |
| No | 207617655 | MDV | M3OI-24HFN1-M | MSEPB-09HRFN1-MY5W(GA) | | 15,000 | $750 |
| No | 206716988 | MDV | M2OI-18HFN1-M | 42 | | 11,500 | $575 |
| No | 207641256 | MDV | M2OI-18HFN1-M* | MTIU-09HWFN1-M | | 11,000 | $550 |
| No | 207641261 | MDV | M5OG-48HFN1-M* | 42 | | 30,600 | $1,530 |
| No | 207641230 | MDV | M5OG-48HFN1-M | 42 | | 30,000 | $1,500 |
| No | 207641260 | MDV | M5OG-48HFN1-M* | MTIU-09HWFN1-M | | 30,400 | $1,520 |
| No | 207641227 | MDV | M5OG-48HFN1-M | MTIU-09HWFN1-M | | 30,400 | $1,520 |
| No | 207641226 | MDV | M5OG-48HFN1-M | MSEPB-09HRFN1-MY5W(GA) | | 29,600 | $1,480 |
| No | 207641253 | MDV | M4OG-36HFN1-M* | MSAG11B-09HRFN1-MX7W(GA) | | 24,000 | $1,200 |
| No | 207617652 | MDV | M4OG-30HFN1-M | MSEPB-06HRFN1-MY5W | | 17,500 | $875 |
| No | 207641254 | MDV | M3OJ-27HFN1-M* | 42 | | 16,100 | $805 |
| No | 207641252 | MDV | M3OJ-27HFN1-M* | MSAG11B-09HRFN1-MX7W(GA) | | 16,200 | $810 |
| No | 207641243 | MDV | M3OJ-27HFN1-M* | MTIU-09HWFN1-M | | 16,000 | $800 |
| No | 207618260 | MDV | M4OG-30HFN1-M | 42 | | 18,200 | $910 |
| No | 206714981 | MDV | M3OJ-27HFN1-M | MTIU-09HWFN1-M | | 16,000 | $800 |
| No | 207641242 | MDV | M3OJ-24HFN1-M* | 42 | | 15,900 | $795 |
| No | 207641233 | MDV | M3OJ-24HFN1-M* | MSAG11B-09HRFN1-MX7W(GA) | | 13,764 | $688 |
| No | 207641241 | MDV | M3OJ-24HFN1-M* | MTIU-09HWFN1-M | | 18,500 | $925 |
| No | 207618258 | MDV | M3OJ-24HFN1-M | 42 | | 16,700 | $835 |
| No | 207617649 | MDV | M3OJ-24HFN1-M | MSEPB-09HRFN1-MY5W(GA) | | 15,000 | $750 |
| No | 207641240 | MDV | M2OA-18HFN1-M* | 42 | | 11,800 | $590 |
| No | 207617651 | MDV | M3OJ-24HFN1-M | MTIU-09HWFN1-M | | 18,500 | $925 |
| No | 206716989 | MDV | M3OJ-27HFN1-M | 42 | | 16,000 | $800 |
| No | 207641239 | MDV | M2OA-18HFN1-M* | MTIU-09HWFN1-M | | 11,800 | $590 |
| No | 207641232 | MDV | M2OA-18HFN1-M* | MSAG11B-09HRFN1-MX7W(GA) | | 11,800 | $590 |
| No | 206716987 | MDV | M2OA-18HFN1-M | 42 | | 11,400 | $570 |
| No | 207825915 | MDV | MOD30U-30HFN1-MR0 | MVC-30HWFN1-M | | 19,000 | $950 |
| No | 208101266 | MDV | MOE30U-60HFN1-M(GA)(X) | MUE-60HRFN1-MW | | 35,000 | $1,750 |
| No | 208101267 | MDV | MOE30U-60HFN1-M(GA)(X) | MHG-60HWFN1-MW | | 34,400 | $1,720 |
| No | 207861769 | MDV | MOD30U-30HFN1-M(GA) | MSEPD-30HRFN1-MS8W | | 19,000 | $950 |
| No | 206330120 | MDV | MOD33-24HFN1-MT0W | MUEU-24HRFN1-M(C) | | 12,000 | $600 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207861767 | MDV | MOD30U-30HFN1-M(GA) | MSAGF-30HRFN1-MT0W | | 20,000 | $1,000 |
| No | 207178564 | MDV | MOX230-09HFN1-MW5W | MSEPB-06HRFN1-MY5W | | 9,000 | $450 |
| No | 207613861 | MDV | MOX430-18HFN1-MU0W | MSAG11D-18HRFN1-MT8W | | 11,900 | $595 |
| No | 207613862 | MDV | MOX430-18HFN1-MU0W | MSEPC-18HRFN1-MU0W | | 12,700 | $635 |
| No | 207614048 | MDV | MOX430-18HFN1-MU0W | MTIU-18HWFN1-M | | 12,000 | $600 |
| No | 207613860 | MDV | MOD30-18HFN1-MZ20W | MSEPD-18HRFN1-MZ22W | | 11,000 | $550 |
| No | 207614046 | MDV | MOX430-18HFN1-MU0W | MUEU-18HRFN1-M(C) | | 12,300 | $615 |
| No | 207591143 | MDV | MOX430-09HFN1-MZG5W | MSEPC-09HRFN1-MZB5W | | 7,300 | $365 |
| No | 207591140 | MDV | MOX430-12HFN1-MZ60W | MSOP1B-12HRFN1-MZ60W | | 6,900 | $345 |
| No | 207591141 | MDV | MOX430-09HFN1-MZG5W | MSOP1B-09HRFN1-MZG5W | | 6,900 | $345 |
| No | 207591142 | MDV | MOX430-12HFN1-MZ60W | MSEPC-12HRFN1-MZ40W | | 7,300 | $365 |
| No | 207645898 | MDV | MOD33-24HFN1-MT0W | MSABE-24HRFN1-MU0W | | 15,000 | $750 |
| No | 207591137 | MDV | MOX430-18HFN1-MU0W | MSABE-18HRFN1-MW5W | | 11,500 | $575 |
| No | 207591145 | MDV | MOX230-12HFN1-MV5W | MSABB-12HRFN1-MV0W | | 7,800 | $390 |
| No | 207591144 | MDV | MOX230-09HFN1-MW5W | MSABB-09HRFN1-MX0W | | 6,000 | $300 |
| No | 207591136 | MDV | MOX230-12HFN1-BW0W | MSABB-12HRFN1-BU5W | | 7,800 | $390 |
| No | 207591134 | MDV | MOX330-18HFN1-MS0W | MSABD-18HRFN1-MS1W | | 12,000 | $600 |
| No | 207591139 | MDV | MOX230-09HFN1-BW0W | MSABB-09HRFN1-BW0W | | 7,800 | $390 |
| No | 207591130 | MDV | MOX230-09HFN1-BS5W | MSABA-09HRFN1-BT5W | | 5,800 | $290 |
| No | 206369514 | MDV | MOX430-24HFN1-MR0W | MSAG11D-24HRFN1-MR0W | | 14,800 | $740 |
| No | 206369510 | MDV | MOX230-12HFN1-BS8W | MSAG11B-12HRFN1-BS0W | | 7,000 | $350 |
| No | 207339193 | MDV | M4OH-36HFN1-MQ1 | MSABB-09HRFN1-MS0Q1W | | 28,000 | $1,400 |
| No | 207338223 | MDV | MOD30-36HFN1-MR0Q1W | MSABF-36HRFN1-MR0Q1W | | 21,000 | $1,050 |
| No | 207338221 | MDV | MOX430-18HFN1-MT2Q1W | MSABE-18HRFN1-MT2Q1W | | 11,500 | $575 |
| No | 207338222 | MDV | MOD31-23HFN1-MT2Q1W | MSABE-23HRFN1-MT2Q1W | | 15,500 | $775 |
| No | 207201641 | MDV | MOE30U-60HFN1-MR0 | MVC-60HWFN1-M | | 33,800 | $1,690 |
| No | 207178567 | MDV | MOD31-36HFN1-MP0W | MSAGF-36HRFNX-MR0W | | 20,000 | $1,000 |
| No | 207201639 | MDV | MOD30U-36HFN1-MR0 | MVC-36HWFN1-M | | 18,400 | $920 |
| No | 207201640 | MDV | MOE30U-48HFN1-MR0 | MVC-48HWFN1-M | | 33,000 | $1,650 |
| No | 207201637 | MDV | MOX430U-24HFN1-MR0 | MVC-24HWFN1-M | | 17,000 | $850 |
| No | 207201638 | MDV | MOD30U-30HFN1-MR0 | MVC-30HWFN1-M | | 19,000 | $950 |
| No | 207201636 | MDV | MOX330U-18HFN1-MR0 | MVC-18HWFN1-M | | 11,500 | $575 |
| No | 204713920 | MDV | M2OF-18HFN1-M（M2OF-18HFN1-MCA） | CS11M-09HRFN1-MX0W(A) | | 12,000 | $600 |
| No | 207215956 | MDV | MOX230-09HFN1-MW5W | MSAG11B-09HRFN1-MX7W(GA) | | 6,100 | $305 |
| No | 207641259 | MDV | M3OI-28HFN1-M* | 42 | | 16,900 | $845 |
| No | 207641247 | MDV | M3OI-28HFN1-M* | MTIU-09HWFN1-M | | 16,500 | $825 |
| No | 206714982 | MDV | M3OI-28HFN1-M | MTIU-09HWFN1-M | | 16,500 | $825 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206716990 | MDV | M3OI-28HFN1-M | 42 | | 17,000 | $850 |
| No | 209248927 | MDV | MOX430-18HFN1-MU0W | MFA2U-16HRFN1-MV0W | | 13,800 | $690 |
| No | 209248926 | MDV | MOX230-12HFN1-MV5W | MFA2U-12HRFN1-MW5W | | 9,200 | $460 |
| No | 209248925 | MDV | MOX230-09HFN1-MY2W | MFA2U-09HRFN1-MY6W | | 9,800 | $490 |
| No | 209248924 | MDV | MOX330-12HFN1-MW5W | MFA2U-12HRFN1-MW5W | | 10,600 | $530 |
| No | 209248923 | MDV | MOX330-09HFN1-MY6W | MFA2U-09HRFN1-MY6W | | 11,000 | $550 |
| No | 207614045 | MDV | MOE30U-60HFN1-M(GA) | MHG-60HWFN1-MW | | 37,000 | $1,850 |
| No | 207614044 | MDV | MOE30U-60HFN1-M(GA) | MUE-60HRFN1-MW | | 35,000 | $1,750 |
| No | 207614047 | MDV | MOX430-18HFN1-MU0W | MCA3U-18HRFN1-M(C) | | 12,000 | $600 |
| No | 206330131 | MDV | MOX430-17HFN1-MT0W | MCA3U-18HRFN1-M(C) | | 11,000 | $550 |
| No | 206330133 | MDV | MOD33-24HFN1-MT0W | MTIU-24HWFN1-M | | 13,500 | $675 |
| No | 206330122 | MDV | MOX330-09HFN1-MY5W | MCA3U-09HRFN1-M(C) | | 6,100 | $305 |
| No | 206330128 | MDV | MOX330-12HFN1-MW5W | MFAU-12HRFN1-M(C) | | 8,400 | $420 |
| No | 207614049 | MDV | MOX430-17HFN1-MT0W | MTIU-24HWFN1-M | | 11,500 | $575 |
| No | 206714986 | MDV | M5OF-48HFN1-M-20 | Heat pump without ducts | | 29,600 | $1,480 |
| No | 207338207 | MDV | MOD30U-36HFN1-MP0(GA) | MCD1-36HRFN1-M(GA) | | 23,000 | $1,150 |
| No | 207338210 | MDV | MOE30U-48HFN1-MP0(GA) | MCD1-48HRFN1-M(GA) | | 28,000 | $1,400 |
| No | 207338208 | MDV | MOD30U-36HFN1-MP0(GA) | MTI-36HWFN1-M | | 27,000 | $1,350 |
| No | 207338211 | MDV | MOE30U-48HFN1-MP0(GA) | MTI-48HWFN1-M | | 29,000 | $1,450 |
| No | 207338209 | MDV | MOE30U-48HFN1-MP0(GA) | MUE-48HRFN1-M(C) | | 29,000 | $1,450 |
| No | 207338218 | MDV | MOD33-24HFN1-MT0W | MCD1-24HRFN1-MT0W(GA) | | 15,600 | $780 |
| No | 206330130 | MDV | MOX430-17HFN1-MT0W | MUEU-18HRFN1-M(C) | | 12,000 | $600 |
| No | 206143049 | MDV | MOE30U-48HFN1-MP0 | MCD-48HRFN1-M(D) | | 29,000 | $1,450 |
| No | 206143046 | MDV | MOD30U-36HFN1-MP0 | MCD-36HRFN1-M(C) | | 22,000 | $1,100 |
| No | 206143047 | MDV | MOD30U-36HFN1-MP0 | MTI-36HWFN1-M | | 27,000 | $1,350 |
| No | 206143048 | MDV | MOE30U-48HFN1-MP0 | MUE-48HRFN1-M(C) | | 29,000 | $1,450 |
| No | 206143050 | MDV | MOE30U-48HFN1-MP0 | MTI-48HWFN1-M | | 29,000 | $1,450 |
| No | 205130932 | MDV | MOE30U-48HFN1-MP0 | MVB-48HWFN1-M | | 36,000 | $1,800 |
| No | 205130931 | MDV | MOD30U-36HFN1-MP0 | MVB-36HWFN1-M | | 25,000 | $1,250 |
| No | 208771558 | MIDEA | MOD30U-36HFN1-M(GA) | MFGD-36HRFN1-MQ5W | | 25,200 | $1,260 |
| No | 208771557 | MIDEA | MOD30U-36HFN1-M(GA) | MFGD-36HRFN1-MQ6W | | 25,200 | $1,260 |
| No | 208568357 | MIDEA | MOX430-18HFN1-MU0W | CCA3U-18HRFN1-M(C) | | 12,000 | $600 |
| No | 208568359 | MIDEA | MOX430-18HFN1-MU0W | MUEU-18HRFN1-M(C) | | 12,800 | $640 |
| No | 208568350 | MIDEA | MOX430-18HFN1-MU0W | MSEPC-18HRFN1-MU0W | | 14,900 | $745 |
| No | 208568339 | MIDEA | MOX230-09HFN1-BW0W-9K | MSAG11B-09HRFN1-BU5W-9K | | 5,900 | $295 |
| No | 208568351 | MIDEA | MOD32-24HFN1-MT0W | MSEPD-24HRFN1-MU0W | | 16,200 | $810 |
| No | 208568348 | MIDEA | MOX230-12HFN1-MV5W | MSEPB-12HRFN1-MW5W(GA) | | 9,000 | $450 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211871344 | MIDEA | MASAG24-21HS2GB* | MASAG24-21HS2GA | | 16,500 | $825 |
| No | 212349510 | MIDEA | MOX330-18HFN1-MS0W | MSAG11C-18HRDN1-MS0W | | 11,400 | $570 |
| No | 211871343 | MIDEA | MASAG18-21HS2GB* | MASAG18-21HS2GA | | 11,400 | $570 |
| No | 211871346 | MIDEA | MASAG12-21HS2GB* | MASAG12-21HS2GA | | 7,000 | $350 |
| No | 211871345 | MIDEA | MASAG09-21HS2GB* | MASAG09-21HS2GA | | 6,000 | $300 |
| No | 211871341 | MIDEA | MASAG12-21HS1GB* | MASAG12-21HS1GA | | 7,800 | $390 |
| No | 211871342 | MIDEA | MASAG09-21HS1GB* | MASAG09-21HS1GA | | 6,300 | $315 |
| No | 208568341 | MIDEA | MOD32-24HFN1-MT0W | MSAG11D-23HRFN1-MU0W | | 17,400 | $870 |
| No | 208568355 | MIDEA | MOX230-12HFN1-MV5W | CCA3U-12HRFN1-M(C) | | 8,900 | $445 |
| No | 208568353 | MIDEA | MOX230-09HFN1-MW5W | CCA3U-09HRFN1-M(C) | | 7,500 | $375 |
| No | 207659307 | MIDEA | M3OJ-27HFN1-M-CO | Heat pump without ducts | | 20,000 | $1,000 |
| No | 207683283 | MIDEA | M3OJ-27HFN1-M | Heat pump without ducts | | 20,000 | $1,000 |
| No | 207683282 | MIDEA | M3OJ-27HFN1-M | Heat pump with ducts | | 22,000 | $1,100 |
| No | 207659306 | MIDEA | M3OJ-27HFN1-M-CO | Heat pump with ducts | | 22,000 | $1,100 |
| No | 207826706 | MIDEA | M5OG-48HFN1-M | Heat pump without ducts | | 34,000 | $1,700 |
| No | 207826702 | MIDEA | MOX430-18HFN1-MU0W | MTIU-18HWFN1-M | | 12,600 | $630 |
| No | 207821933 | MIDEA | MOX430-18HFN1-MU0W | MSAG11D-18HRFN1-MT8W | | 14,100 | $705 |
| No | 207821939 | MIDEA | MOD33-24HFN1-MT0W | MCD1-24HRFN1-MT0W(GA) | | 19,000 | $950 |
| No | 207826700 | MIDEA | MOE30U-48HFN1-MP0(GA) | MTI-48HWFN1-M | | 34,000 | $1,700 |
| No | 207821941 | MIDEA | MOE30U-48HFN1-MP0(GA) | MCD1-48HRFN1-M(GA) | | 30,000 | $1,500 |
| No | 207821943 | MIDEA | MOE30U-48HFN1-MP0(GA) | MUE-48HRFN1-M(C) | | 29,000 | $1,450 |
| No | 207826699 | MIDEA | MOD30U-36HFN1-MP0(GA) | MTI-36HWFN1-M | | 25,000 | $1,250 |
| No | 207821940 | MIDEA | MOD30U-36HFN1-MP0(GA) | MCD1-36HRFN1-M(GA) | | 23,000 | $1,150 |
| No | 207821942 | MIDEA | MOD30U-36HFN1-MP0(GA) | MUE-36HRFN1-M(C) | | 23,000 | $1,150 |
| No | 207821930 | MIDEA | MOX230-09HFN1-MW5W | MSAG11B-09HRFN1-MX7W(GA) | | 8,100 | $405 |
| No | 207821929 | MIDEA | MOX230-09HFN1-BW0W | MSAG11B-09HRFN1-BU5W | | 5,900 | $295 |
| No | 207826703 | MIDEA | M4OG-36HFN1-M | Heat pump without ducts | | 26,800 | $1,340 |
| No | 207683277 | MIDEA | MOD31-36HFN1-MP0W | MSABF-36HRFNX-MQ0W | | 24,000 | $1,200 |
| No | 207826696 | MIDEA | MOD33-24HFN1-MT0W | MSEPD-24HRFN1-MU0W | | 16,200 | $810 |
| No | 207826693 | MIDEA | MOX230-09HFN1-MW5W | MSEPB-09HRFN1-MY5W(GA) | | 8,500 | $425 |
| No | 207821928 | MIDEA | MOX230-09HFN1-BS5W | MSAG11A-09HRFN1-BS5W | | 6,300 | $315 |
| No | 207821935 | MIDEA | MOD33-24HFN1-MT0W | MSAG11D-23HRFN1-MU0W | | 17,400 | $870 |
| No | 207821932 | MIDEA | MOX230-12HFN1-MV5W | MSAG11B-12HRFN1-MV0W(GA) | | 10,000 | $500 |
| No | 207821931 | MIDEA | MOX230-12HFN1-BW0W | MSAG11B-12HRFN1-BU5W | | 8,900 | $445 |
| No | 207821934 | MIDEA | MOX430-18HFN1-MT8W | MSAG11D-18HRFN1-MT8W | | 14,100 | $705 |
| No | 207826698 | MIDEA | MOD33-24HFN1-MT0W | MTIU-24HWFN1-M | | 20,000 | $1,000 |
| No | 207742396 | MIDEA | MOX230-12HFN1-MV5W | MTIU-12HWFN1-M | | 9,300 | $465 |
| No | 207826697 | MIDEA | MOD33-24HFN1-MT0W | MUEU-24HRFN1-M(C) | | 16,000 | $800 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207826694 | MIDEA | MOX330-12HFN1-MW5W | MSEPB-12HRFN1-MW5W(GA) | | 10,000 | $500 |
| No | 208650614 | MIDEA | MOE30U-60HFN1-MR0 | MVC-60HWFN1-M | | 37,000 | $1,850 |
| No | 208650613 | MIDEA | MOE30U-48HFN1-MR0 | MVC-48HWFN1-M | | 37,000 | $1,850 |
| No | 208650612 | MIDEA | MOD30U-36HFN1-MR0 | MVC-36HWFN1-M | | 20,400 | $1,020 |
| No | 208650610 | MIDEA | MOX430U-24HFN1-MR0 | MVC-24HWFN1-M | | 21,000 | $1,050 |
| No | 208650609 | MIDEA | MOX330U-18HFN1-MR0 | MVC-18HWFN1-M | | 12,000 | $600 |
| No | 210819426 | MIDEA | DLCSRBH30AAK | DLFSABH30XBK | | 20,400 | $1,020 |
| No | 210819419 | MIDEA | 38MARBQ30AA3 | 40MBABQ30XB3 | | 20,400 | $1,020 |
| No | 208102136 | MIDEA | 38MARBQ30AA311 | DHMAHBQ30XA3 | | 19,000 | $950 |
| No | 206350308 | MIDEA | 38MARBQ30AA3 | DHMAHBQ30XA3 | | 19,000 | $950 |
| No | 209852104 | MIDEA | DLCURAH60AAK | DLFUAAH60XAK | | 37,000 | $1,850 |
| No | 209852101 | MIDEA | DLCURAH48AAK | DLFUAAH48XAK | | 37,000 | $1,850 |
| No | 209852108 | MIDEA | DLCURAH36AAK | DLFUAAH36XAK | | 20,400 | $1,020 |
| No | 209852110 | MIDEA | DLCURAH30ABK | DLFUAAH30XAK | | 21,000 | $1,050 |
| No | 209852107 | MIDEA | DLCURAH30AAK | DLFUAAH30XAK | | 20,000 | $1,000 |
| No | 209852100 | MIDEA | DLCURAH24AAK | DLFUAAH24XAK | | 21,000 | $1,050 |
| No | 209852106 | MIDEA | DLCURAH18AAK | DLFUAAH18XAK | | 12,000 | $600 |
| No | 208447922 | MIDEA | 38MURAQ60AA3 | 40MUAAQ60XA3 | | 37,000 | $1,850 |
| No | 208447915 | MIDEA | 38MURAQ48AA3 | 40MUAAQ48XA3 | | 37,000 | $1,850 |
| No | 208447916 | MIDEA | 38MURAQ36AA3 | 40MUAAQ36XA3 | | 20,400 | $1,020 |
| No | 208447920 | MIDEA | 38MURAQ30AB3 | 40MUAAQ30XA3 | | 21,000 | $1,050 |
| No | 209852148 | MIDEA | 38MURAQ30AA3 | 40MUAAQ30XA3 | | 20,000 | $1,000 |
| No | 208447917 | MIDEA | 38MURAQ24AA3 | 40MUAAQ24XA3 | | 21,000 | $1,050 |
| No | 209911731 | MIDEA | 38MURAQ18AA3 | 40MUAAQ18XA3 | | 12,000 | $600 |
| No | 9006311 | MIDEA | M3OF-27HFN1-M | Heat pump without ducts | | 17,200 | $860 |
| No | 9006313 | MIDEA | M5OF-48HFN1-M | Heat pump without ducts | | 29,600 | $1,480 |
| No | 9006310 | MIDEA | M2OF-18HFN1-M | Heat pump without ducts | | 12,000 | $600 |
| No | 9006312 | MIDEA | M4OF-36HFN1-M | Heat pump without ducts | | 24,600 | $1,230 |
| No | 207643131 | MIDEA | DLCMRBH48EAK | Heat pump without ducts | | 31,000 | $1,550 |
| No | 207642978 | MIDEA | 38MGRBQ48EA3 | Heat pump without ducts | | 29,600 | $1,480 |
| No | 204711109 | MIDEA | 38MGRQ24C--3 | Heat pump without ducts | | 17,200 | $860 |
| No | 201847005 | MIDEA | 38MGRQ48E--3 | Heat pump without ducts | | 29,600 | $1,480 |
| No | 201847001 | MIDEA | 38MGRQ18B--3 | Heat pump without ducts | | 12,000 | $600 |
| No | 201771973 | MIDEA | DLCMRAH27CAK | Heat pump without ducts | | 17,800 | $890 |
| No | 208104308 | MIDEA | 38MARBQ36AB3 | 40MBABQ36XB3 | | 25,600 | $1,280 |
| No | 207826683 | MIDEA | 38MBRCQ58AA3 | 40MBABQ60XA3 | | 34,000 | $1,700 |
| No | 207826682 | MIDEA | 38MBRCQ48AA3 | 40MBABQ48XA3 | | 37,400 | $1,870 |
| No | 207826681 | MIDEA | 38MBRCQ36AA3 | 40MBABQ36XA3 | | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208104321 | MIDEA | DLCSRBH36ABK | DLFSABH36XBK | | 25,600 | $1,280 |
| No | 207826634 | MIDEA | DLCLRCH36AAK | DLFLABH36XAK | | 25,600 | $1,280 |
| No | 207826633 | MIDEA | DLCLRCH58AAK | DLFLABH60XAK | | 34,000 | $1,700 |
| No | 207826632 | MIDEA | DLCLRCH48AAK | DLFLABH48XAK | | 37,400 | $1,870 |
| No | 208104322 | MIDEA | DLCSRBH30AAK11 | DLFSABH30XBK | | 19,200 | $960 |
| No | 207826606 | MIDEA | DLCSRBH24AAK | DLFSABH24XBK | | 16,200 | $810 |
| No | 208104307 | MIDEA | 38MARBQ30AA311 | 40MBABQ30XB3 | | 19,200 | $960 |
| No | 207826680 | MIDEA | 38MARBQ24AA3 | 40MBABQ24XB3 | | 16,200 | $810 |
| No | 206188327 | MIDEA | DLCLRBH48AAK | DLFLFAH48XAK | | 29,000 | $1,450 |
| No | 206188324 | MIDEA | DLCLRBH36AAK | DLFLFAH36XAK | | 22,000 | $1,100 |
| No | 206188328 | MIDEA | DLCLRBH48AAK | DLFLCAH48XAK | | 29,000 | $1,450 |
| No | 206188325 | MIDEA | DLCLRBH36AAK | DLFLCAH36XAK | | 22,000 | $1,100 |
| No | 206188329 | MIDEA | DLCLRBH48AAK | DLFLDAH48XAK | | 29,000 | $1,450 |
| No | 206188326 | MIDEA | DLCLRBH36AAK | DLFLDAH36XAK | | 27,000 | $1,350 |
| No | 207643117 | MIDEA | DLCMHBH24CAK | Heat pump with ducts | | 18,500 | $925 |
| No | 207643132 | MIDEA | DLCMRBH48EAK | Heat pump with ducts | | 30,400 | $1,520 |
| No | 207643114 | MIDEA | DLCMRBH18BAK | Heat pump with ducts | | 11,800 | $590 |
| No | 207643118 | MIDEA | DLCMHBH24CAK | Combination heat pumps with or without ducts | | 15,900 | $795 |
| No | 207643115 | MIDEA | DLCMRBH18BAK | Combination heat pumps with or without ducts | | 11,800 | $590 |
| No | 207643133 | MIDEA | DLCMRBH48EAK | Combination heat pumps with or without ducts | | 30,600 | $1,530 |
| No | 207643116 | MIDEA | DLCMHBH24CAK | Heat pump without ducts | | 13,300 | $665 |
| No | 207643113 | MIDEA | DLCMRBH18BAK | Heat pump without ducts | | 11,800 | $590 |
| No | 207643123 | MIDEA | DLCMRBH36DAK | Heat pump without ducts | | 24,000 | $1,200 |
| No | 207642964 | MIDEA | 38MGHBQ24CA3 | Heat pump with ducts | | 18,500 | $925 |
| No | 207642961 | MIDEA | 38MGRBQ18BA3 | Heat pump with ducts | | 11,800 | $590 |
| No | 207642979 | MIDEA | 38MGRBQ48EA3 | Heat pump with ducts | | 30,400 | $1,520 |
| No | 207642965 | MIDEA | 38MGHBQ24CA3 | Combination heat pumps with or without ducts | | 16,700 | $835 |
| No | 207642962 | MIDEA | 38MGRBQ18BA3 | Combination heat pumps with or without ducts | | 11,400 | $570 |
| No | 207642963 | MIDEA | 38MGHBQ24CA3 | Heat pump without ducts | | 15,000 | $750 |
| No | 207642980 | MIDEA | 38MGRBQ48EA3 | Combination heat pumps with or without ducts | | 30,000 | $1,500 |
| No | 207642960 | MIDEA | 38MGRBQ18BA3 | Heat pump without ducts | | 11,000 | $550 |
| No | 207642969 | MIDEA | 38MGRBQ36DA3 | Heat pump without ducts | | 23,400 | $1,170 |
| No | 206400660 | MIDEA | 38MARBQ09AA3 | DHMSHAQ09XA3 | | 7,500 | $375 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201846996 | MIDEA | 38MAQB12R--3 | 40MBDQ12---3 | | 8,500 | $425 |
| No | 206350448 | MIDEA | DLCSRBH09AAK | DLFSCAH09XAK | | 6,100 | $305 |
| No | 206350449 | MIDEA | DLCSRBH09AAK | DLFSDAH09XAK | | 6,400 | $320 |
| No | 206350372 | MIDEA | 38MARBQ09AA3 | 40MBDQ09--3 | | 6,400 | $320 |
| No | 206350319 | MIDEA | 38MARBQ12AA3 | DHMAHBQ12XA3 | | 7,500 | $375 |
| No | 206350320 | MIDEA | 38MARBQ18AA3 | DHMAHBQ18XA3 | | 10,800 | $540 |
| No | 206350371 | MIDEA | 38MARBQ09AA3 | 40MBCQ09--3 | | 6,100 | $305 |
| No | 206396128 | MIDEA | DLCSRBH12AAK | DLFSHAH12XAK | | 7,500 | $375 |
| No | 206361900 | MIDEA | DLCSRBH12AAK | DLFSHBH12XAK | | 7,300 | $365 |
| No | 206350451 | MIDEA | DLCSRBH12AAK | DLFSDAH12XAK | | 8,300 | $415 |
| No | 206188277 | MIDEA | 38MBRBQ36AA3 | 40MBDQ36---3 | | 27,000 | $1,350 |
| No | 206188280 | MIDEA | 38MBRBQ48AA3 | 40MBDQ48---3 | | 29,000 | $1,450 |
| No | 206350374 | MIDEA | 38MARBQ12AA3 | 40MBDQ12--3 | | 8,300 | $415 |
| No | 205962797 | MIDEA | 38MBRBQ48AA3 | 40MBAAQ48XA3 | | 36,000 | $1,800 |
| No | 205962796 | MIDEA | 38MBRBQ36AA3 | 40MBAAQ36XA3 | | 25,000 | $1,250 |
| No | 206396052 | MIDEA | 38MAQB12R--3 | DHMAHBQ12XA3 | | 7,500 | $375 |
| No | 206396129 | MIDEA | DLCSRAH12AAK | DLFSHBH12XAK | | 7,500 | $375 |
| No | 206396054 | MIDEA | 38MAQB24R--3 | DHMAHBQ24XA3 | | 18,800 | $940 |
| No | 206396132 | MIDEA | DLCSRAH24AAK | DLFSHBH24XAK | | 15,000 | $750 |
| No | 206396133 | MIDEA | DLCSRBH24AAK | DLFSHAH24XAK | | 15,000 | $750 |
| No | 206361902 | MIDEA | DLCSRBH24AAK | DLFSHBH24XAK | | 17,000 | $850 |
| No | 206396053 | MIDEA | 38MAQB18R--3 | DHMAHBQ18XA3 | | 11,000 | $550 |
| No | 206400662 | MIDEA | 38MARBQ18AA3 | DHMSHAQ18XA3 | | 10,800 | $540 |
| No | 206361898 | MIDEA | DLCSRBH12AAJ | DLFSHBH12XAJ | | 8,200 | $410 |
| No | 206361901 | MIDEA | DLCSRBH18AAK | DLFSHBH18XAK | | 11,100 | $555 |
| No | 206396051 | MIDEA | 38MAQB09R--3 | DHMAHBQ09XA3 | | 7,000 | $350 |
| No | 206400663 | MIDEA | 38MARBQ24AA3 | DHMSHAQ24XA3 | | 19,800 | $990 |
| No | 206350317 | MIDEA | 38MARBQ12AA1 | DHMAHBQ12XA1 | | 7,400 | $370 |
| No | 206350318 | MIDEA | 38MARBQ09AA3 | DHMAHBQ09XA3 | | 7,500 | $375 |
| No | 206361899 | MIDEA | DLCSRBH09AAK | DLFSHBH09XAK | | 7,400 | $370 |
| No | 206400661 | MIDEA | 38MARBQ12AA3 | DHMSHAQ12XA3 | | 7,500 | $375 |
| No | 206188276 | MIDEA | 38MBRBQ36AA3 | 40MBCQ36---3 | | 22,000 | $1,100 |
| No | 206188279 | MIDEA | 38MBRBQ48AA3 | 40MBCQ48---3 | | 29,000 | $1,450 |
| No | 206350452 | MIDEA | DLCSRBH12AAK | DLFSFAH12XAK | | 8,400 | $420 |
| No | 206350373 | MIDEA | 38MARBQ12AA3 | 40MBCQ12--3 | | 7,900 | $395 |
| No | 206350450 | MIDEA | DLCSRBH12AAK | DLFSCAH12XAK | | 7,900 | $395 |
| No | 206188278 | MIDEA | 38MBRBQ48AA3 | 40MBFQ48---3 | | 29,000 | $1,450 |
| No | 206188275 | MIDEA | 38MBRBQ36AA3 | 40MBFQ36---3 | | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206350375 | MIDEA | 38MARBQ12AA3 | 40MBFQ12--3 | | 8,400 | $420 |
| No | 205767359 | MIDEA | DLCLRBH48AAK | DLFLAAH48XAK | | 36,000 | $1,800 |
| No | 205767358 | MIDEA | DLCLRBH36AAK | DLFLAAH36XAK | | 25,000 | $1,250 |
| No | 201756552 | MIDEA | DLCSRAH36AAK | DLFSHAH36XAK | | 20,600 | $1,030 |
| No | 201846989 | MIDEA | 38MAQB12R--3 | DHMSHAQ12XA3 | | 7,800 | $390 |
| No | 202463654 | MIDEA | DLCPRAH18AAK | DLFPHAH18XAK | | 12,300 | $615 |
| No | 202463640 | MIDEA | 38MPRAQ18AA3 | DHMPHAQ18XA3 | | 12,300 | $615 |
| No | 201753970 | MIDEA | 38MPRAQ09AA3 | DHMPHAQ09XA3 | | 7,200 | $360 |
| No | 201753971 | MIDEA | 38MPRAQ12AA3 | DHMPHAQ12XA3 | | 6,800 | $340 |
| No | 201771975 | MIDEA | DLCMRAH48EAK | Heat pump without ducts | | 30,400 | $1,520 |
| No | 201771974 | MIDEA | DLCMRAH36DAK | Heat pump without ducts | | 23,600 | $1,180 |
| No | 201846994 | MIDEA | 38MAQB18R--3 | 40MBCQ18---3 | | 12,000 | $600 |
| No | 201756546 | MIDEA | DLCSRAH12AAJ | DLFSHAH12XAJ | | 7,100 | $355 |
| No | 201755033 | MIDEA | DLCPRAH12AAK | DLFPHAH12XAK | | 6,800 | $340 |
| No | 201753972 | MIDEA | DLCPRAH09AAK | DLFPHAH09XAK | | 7,200 | $360 |
| No | 201756547 | MIDEA | DLCSRAH09AAK | DLFSHAH09XAK | | 7,500 | $375 |
| No | 201847061 | MIDEA | 38MBRQ58A--3 | 40MBDQ58---3 | | 37,600 | $1,880 |
| No | 201771971 | MIDEA | DLCLRAH58AAK | DLFLDAH58XAK | | 37,600 | $1,880 |
| No | 201756549 | MIDEA | DLCSRAH18AAK | DLFSHAH18XAK | | 11,900 | $595 |
| No | 201756548 | MIDEA | DLCSRAH12AAK | DLFSHAH12XAK | | 7,600 | $380 |
| No | 201847058 | MIDEA | 38MBRQ48A--3 | 40MBCQ48---3 | | 35,000 | $1,750 |
| No | 201796619 | MIDEA | DLCLRAH48AAK | DLFLCAH48XAK | | 35,000 | $1,750 |
| No | 201847060 | MIDEA | 38MBRQ48A--3 | 40MBDQ48---3 | | 33,400 | $1,670 |
| No | 201796620 | MIDEA | DLCLRAH58AAK | DLFLFAH58XAK | | 39,000 | $1,950 |
| No | 201771970 | MIDEA | DLCLRAH48AAK | DLFLDAH48XAK | | 33,400 | $1,670 |
| No | 201847065 | MIDEA | 38MBRQ58A--3 | 40MBFQ58---3 | | 39,000 | $1,950 |
| No | 201846987 | MIDEA | 38MAQB12R--1 | DHMSHAQ12XA1 | | 7,600 | $380 |
| No | 201846993 | MIDEA | 38MAQB12R--3 | 40MBCQ12---3 | | 8,700 | $435 |
| No | 201847056 | MIDEA | 38MAQB24R--3 | 40MBCQ24---3 | | 16,200 | $810 |
| No | 201846999 | MIDEA | 38MAQB12R--3 | 40MBFQ12---3 | | 9,600 | $480 |
| No | 201846990 | MIDEA | 38MAQB18R--3 | DHMSHAQ18XA3 | | 10,800 | $540 |
| No | 201847000 | MIDEA | 38MAQB18R--3 | 40MBFQ18---3 | | 13,400 | $670 |
| No | 201846992 | MIDEA | 38MAQB09R--3 | 40MBCQ09---3 | | 6,700 | $335 |
| No | 201847059 | MIDEA | 38MBRQ36A--3 | 40MBDQ36---3 | | 27,600 | $1,380 |
| No | 201771969 | MIDEA | DLCLRAH36AAK | DLFLDAH36XAK | | 27,600 | $1,380 |
| No | 201796609 | MIDEA | DLCSRAH12AAK | DLFSDAH12XAK | | 8,100 | $405 |
| No | 201847057 | MIDEA | 38MBRQ36A--3 | 40MBCQ36---3 | | 25,200 | $1,260 |
| No | 201796608 | MIDEA | DLCSRAH12AAK | DLFSFAH12XAK | | 9,600 | $480 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201796616 | MIDEA | DLCLRAH36AAK | DLFLCAH36XAK | | 25,200 | $1,260 |
| No | 201796606 | MIDEA | DLCSRAH09AAK | DLFSCAH09XAK | | 6,700 | $335 |
| No | 201796610 | MIDEA | DLCSRAH18AAK | DLFSFAH18XAK | | 12,900 | $645 |
| No | 201847063 | MIDEA | 38MBRQ36A--3 | 40MBFQ36---3 | | 25,400 | $1,270 |
| No | 201796615 | MIDEA | DLCLRAH36AAK | DLFLFAH36XAK | | 25,400 | $1,270 |
| No | 201796605 | MIDEA | DLCSRAH09AAK | DLFSDAH09XAK | | 6,800 | $340 |
| No | 201796607 | MIDEA | DLCSRAH12AAK | DLFSCAH12XAK | | 8,200 | $410 |
| No | 201846995 | MIDEA | 38MAQB09R--3 | 40MBDQ09---3 | | 7,200 | $360 |
| No | 201846997 | MIDEA | 38MAQB18R--3 | 40MBDQ18---3 | | 13,400 | $670 |
| No | 201847075 | MIDEA | 38MGRQ48E--3 | Heat pump with ducts | | 34,000 | $1,700 |
| No | 204707612 | MIDEA | 38MGRQ24C--3 | Heat pump with ducts | | 17,600 | $880 |
| No | 201847071 | MIDEA | 38MGRQ18B--3 | Heat pump with ducts | | 11,500 | $575 |
| No | 204722809 | MIDEA | 38MGRQ48E--3 | Combination heat pumps with or without ducts | | 31,800 | $1,590 |
| No | 204722806 | MIDEA | 38MGRQ24C--3 | Combination heat pumps with or without ducts | | 17,400 | $870 |
| No | 204722805 | MIDEA | 38MGRQ18B--3 | Combination heat pumps with or without ducts | | 11,700 | $585 |
| No | 207862057 | MIRAGE | OVMH361B | Heat pump without ducts | | 26,400 | $1,320 |
| No | 207862054 | MIRAGE | OVMH271B | Heat pump without ducts | | 20,000 | $1,000 |
| No | 207862055 | MIRAGE | OVMH271B | Heat pump with ducts | | 22,000 | $1,100 |
| No | 207862052 | MIRAGE | OVMH181B | Heat pump with ducts | | 14,800 | $740 |
| No | 207862060 | MIRAGE | OVMH481B | Heat pump without ducts | | 36,000 | $1,800 |
| No | 207862051 | MIRAGE | OVMH181B | Heat pump without ducts | | 14,400 | $720 |
| No | 211911379 | MITS AIR | MOE30U-48HFN1-MR0 | MAC-48HWFN1-M | | 30,400 | $1,520 |
| No | 211911375 | MITS AIR | MOE30U-48HFN1-MR0 | MAC-48HWDN1-MN0 | | 30,400 | $1,520 |
| No | 212104222 | MITS AIR | MOX330U-18HFN1-MR0 | MAC-24HWDN1-MN0 | | 13,000 | $650 |
| No | 211911371 | MITS AIR | MOX330-18HFN1-MR0 | MAC-24HWDN1-MN0 | | 13,000 | $650 |
| No | 211911387 | MITS AIR | MOE30U-48HFN1-M-[X1] | MAC-48HWFN1-M | | 32,000 | $1,600 |
| No | 211911384 | MITS AIR | MOE30U-48HFN1-M-[X1] | MAC-48HWDN1-MN0 | | 32,000 | $1,600 |
| No | 211911383 | MITS AIR | MOE31U-36HFN1-M | MAC-36HWDN1-MN0 | | 33,000 | $1,650 |
| No | 211911386 | MITS AIR | MOE31U-36HFN1-M | MAC-36HWFN1-M | | 33,000 | $1,650 |
| No | 211911378 | MITS AIR | MOD30U-36HFN1-MR0 | MAC-36HWFN1-M | | 19,800 | $990 |
| No | 211911374 | MITS AIR | MOD30U-36HFN1-MR0 | MAC-36HWDN1-MN0 | | 19,800 | $990 |
| No | 211911381 | MITS AIR | MOD30-24HFN1-MW | MAC-24HWDN1-MN0 | | 21,000 | $1,050 |
| No | 211911380 | MITS AIR | MOX430U-18HFN1-M | MAC-24HWDN1-MN0 | | 14,700 | $735 |
| No | 211911376 | MITS AIR | MOE30U-60HFN1-MR0 | MAC-60HWDN1-MN0 | | 34,000 | $1,700 |
| No | 211911373 | MITS AIR | MOD30U-30HFN1-MR0 | MAC-36HWDN1-MN0 | | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211911377 | MITS AIR | MOD30U-30HFN1-MR0 | MAC-36HWFN1-M | | 22,000 | $1,100 |
| No | 212104225 | MITS AIR | MOX430U-24HFN1-MR0 | MAC-24HWDN1-MN0 | | 22,000 | $1,100 |
| No | 211911372 | MITS AIR | MOX430-24HFN1-MR0 | MAC-24HWDN1-MN0 | | 22,000 | $1,100 |
| No | 211257308 | MITS AIR | MOE31U-36HFN1-M | MVC-36HWFN1-M | | 30,400 | $1,520 |
| No | 211257307 | MITS AIR | MOD30U-30HFN1-MR0(X) | MVC-30HWFN1-M | | 21,000 | $1,050 |
| No | 207252578 | MITS AIR | MOE30U-60HFN1-MR0 | MVC-60HWFN1-M | | 33,800 | $1,690 |
| No | 207252577 | MITS AIR | MOE30U-48HFN1-MR0 | MVC-48HWFN1-M | | 33,000 | $1,650 |
| No | 207252576 | MITS AIR | MOD30U-36HFN1-MR0 | MVC-36HWFN1-M | | 18,400 | $920 |
| No | 207252574 | MITS AIR | MOX430U-24HFN1-MR0 | MVC-24HWFN1-M | | 17,000 | $850 |
| No | 207252573 | MITS AIR | MOX330U-18HFN1-MR0 | MVC-18HWFN1-M | | 11,500 | $575 |
| No | 207252575 | MITS AIR | MOD30U-30HFN1-MR0 | MVC-30HWFN1-M | | 19,000 | $950 |
| No | 207679256 | Mitsubishi Electric | MUZ-GS24NAHZ*** | MSZ-GS24NA*** | | 13,300 | $665 |
| No | 207679254 | Mitsubishi Electric | MUZ-GS15NAHZ*** | MSZ-GS15NA*** | | 8,700 | $435 |
| No | 207679253 | Mitsubishi Electric | MUZ-GS12NAHZ*** | MSZ-GS12NA*** | | 7,600 | $380 |
| No | 207679252 | Mitsubishi Electric | MUZ-GS09NAHZ*** | MSZ-GS09NA*** | | 5,700 | $285 |
| No | 206374536 | MITSUBISHI ELECTRIC | SUZ-KA12NAHZ | APEADA0121AA70A | | 9,000 | $450 |
| No | 206374538 | MITSUBISHI ELECTRIC | SUZ-KA15NAHZ | APEADA0151AA70A | | 11,700 | $585 |
| No | 207679246 | Mitsubishi Electric | MUZ-GS24NA*** | MSZ-GS24NA*** | | 17,600 | $880 |
| No | 207679245 | Mitsubishi Electric | MUZ-GS18NA*** | MSZ-GS18NA*** | | 13,300 | $665 |
| No | 207679244 | Mitsubishi Electric | MUZ-GS15NA*** | MSZ-GS15NA*** | | 12,100 | $605 |
| No | 207679243 | Mitsubishi Electric | MUZ-GS12NA*** | MSZ-GS12NA*** | | 9,000 | $450 |
| No | 207679242 | Mitsubishi Electric | MUZ-GS09NA*** | MSZ-GS09NA*** | | 6,500 | $325 |
| No | 201754475 | MITSUBISHI ELECTRIC | PUZ-A36NKA7*** | PEAD-A36AA* | | 20,400 | $1,020 |
| No | 201754547 | MITSUBISHI ELECTRIC | PUZ-A36NKA7*** | PVA-A36AA* | | 24,000 | $1,200 |
| No | 201754481 | MITSUBISHI ELECTRIC | PUZ-A42NKA7*** | PEAD-A42AA* | | 26,600 | $1,330 |
| No | 207702706 | MITSUBISHI ELECTRIC | SUZ-KA12NAHZ | PEAD-A12AA* | | 8,800 | $440 |
| No | 201754546 | MITSUBISHI ELECTRIC | PUZ-A30NHA7*** | PVA-A30AA* | | 18,000 | $900 |
| No | 201754545 | MITSUBISHI ELECTRIC | PUZ-A30NHA7*** | PCA-A30KA* | | 18,800 | $940 |
| No | 201754470 | MITSUBISHI ELECTRIC | PUZ-A30NHA7*** | PLA-A30EA* | | 18,100 | $905 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201754468 | MITSUBISHI ELECTRIC | PUZ-A30NHA7*** | PEAD-A30AA* | | 18,800 | $940 |
| No | 201754462 | MITSUBISHI ELECTRIC | PUZ-A24NHA7*** | PKA-A24KA* | | 15,700 | $785 |
| No | 201754460 | MITSUBISHI ELECTRIC | PUZ-A24NHA7*** | PCA-A24KA* | | 15,400 | $770 |
| No | 201754463 | MITSUBISHI ELECTRIC | PUZ-A24NHA7*** | PVA-A24AA* | | 15,000 | $750 |
| No | 201754461 | MITSUBISHI ELECTRIC | PUZ-A24NHA7*** | PEAD-A24AA* | | 15,400 | $770 |
| No | 201754318 | MITSUBISHI ELECTRIC | PUZ-A24NHA7 | PLA-A24EA* | | 14,900 | $745 |
| No | 207702711 | MITSUBISHI ELECTRIC | SUZ-KA18NA2 | PEAD-A18AA* | | 14,000 | $700 |
| No | 207702707 | MITSUBISHI ELECTRIC | SUZ-KA15NA2 | PEAD-A15AA* | | 10,500 | $525 |
| No | 207702709 | MITSUBISHI ELECTRIC | SUZ-KA15NAHZ | PEAD-A15AA* | | 11,700 | $585 |
| No | 207702701 | MITSUBISHI ELECTRIC | SUZ-KA12NA2 | PEAD-A12AA* | | 9,700 | $485 |
| No | 207702695 | MITSUBISHI ELECTRIC | SUZ-KA09NA2 | PEAD-A09AA* | | 7,600 | $380 |
| No | 211289251 | MITSUBISHI ELECTRIC | SUZ-KA15NA2 | SLZ-KF15NA | | 11,900 | $595 |
| No | 209832206 | Mitsubishi Electric | MUZ-FS15NAH*** | MSZ-FS15NA*** | | 10,000 | $500 |
| No | 209832205 | Mitsubishi Electric | MUZ-FS15NA*** | MSZ-FS15NA*** | | 10,000 | $500 |
| No | 209832204 | Mitsubishi Electric | MUZ-FS12NAH*** | MSZ-FS12NA*** | | 8,400 | $420 |
| No | 209832203 | Mitsubishi Electric | MUZ-FS12NA*** | MSZ-FS12NA*** | | 8,400 | $420 |
| No | 209832202 | Mitsubishi Electric | MUZ-FS09NAH*** | MSZ-FS09NA*** | | 5,900 | $295 |
| No | 209832201 | Mitsubishi Electric | MUZ-FS09NA*** | MSZ-FS09NA*** | | 5,900 | $295 |
| No | 209832200 | Mitsubishi Electric | MUZ-FS06NAH*** | MSZ-FS06NA*** | | 5,900 | $295 |
| No | 209832199 | Mitsubishi Electric | MUZ-FS06NA*** | MSZ-FS06NA*** | | 5,900 | $295 |
| No | 209832209 | MITSUBISHI ELECTRIC | MUZ-GL24NA*** | MSZ-GL24NA*** | | 16,000 | $800 |
| No | 211289249 | MITSUBISHI ELECTRIC | SUZ-KA12NAHZ | SLZ-KF12NA* | | 8,300 | $415 |
| No | 207699119 | MITSUBISHI ELECTRIC | SUZ-KA09NA2 | MLZ-KP09NA* | | 7,700 | $385 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211289244 | MITSUBISHI ELECTRIC | SUZ-KA09NA2 | SLZ-KF09NA | | 6,900 | $345 |
| No | 211289247 | MITSUBISHI ELECTRIC | SUZ-KA12NA2 | SLZ-KF12NA* | | 8,900 | $445 |
| No | 211289257 | MITSUBISHI ELECTRIC | SUZ-KA12NA2 | SVZ-KP12NA* | | 9,900 | $495 |
| No | 207699122 | MITSUBISHI ELECTRIC | SUZ-KA12NA2 | MLZ-KP12NA* | | 9,900 | $495 |
| No | 211289259 | MITSUBISHI ELECTRIC | SUZ-KA18NA2 | SVZ-KP18NA* | | 14,000 | $700 |
| No | 211289254 | MITSUBISHI ELECTRIC | SUZ-KA18NA2 | SLZ-KF18NA* | | 12,900 | $645 |
| No | 207699125 | MITSUBISHI ELECTRIC | SUZ-KA18NA2 | MLZ-KP18NA* | | 13,100 | $655 |
| No | 211289256 | MITSUBISHI ELECTRIC | SUZ-KA18NAHZ | SVZ-KP18NA* | | 14,300 | $715 |
| No | 202680602 | MITSUBISHI ELECTRIC | MUZ-HM15NA*** | MSZ-HM15NA*** | | 11,500 | $575 |
| No | 202680603 | MITSUBISHI ELECTRIC | MUZ-HM18NA*** | MSZ-HM18NA*** | | 11,500 | $575 |
| No | 201754319 | MITSUBISHI ELECTRIC | PUZ-A36NKA7*** | PLA-A36EA* | | 22,000 | $1,100 |
| No | 201754480 | MITSUBISHI ELECTRIC | PUZ-A42NKA7*** | PCA-A42KA* | | 28,200 | $1,410 |
| No | 201754474 | MITSUBISHI ELECTRIC | PUZ-A36NKA7*** | PCA-A36KA* | | 21,200 | $1,060 |
| No | 201754483 | MITSUBISHI ELECTRIC | PUZ-A42NKA7*** | PVA-A42AA* | | 28,400 | $1,420 |
| No | 211259280 | MITSUBISHI ELECTRIC | PUZ-HA42NKA1 | PCA-A42KA* | | 38,500 | $1,925 |
| No | 209310457 | MITSUBISHI ELECTRIC | MXZ-4C36NA4*** | Heat pump without ducts | | 22,400 | $1,120 |
| No | 209310455 | MITSUBISHI ELECTRIC | MXZ-3C30NA4*** | Heat pump without ducts | | 18,600 | $930 |
| No | 209310453 | MITSUBISHI ELECTRIC | MXZ-3C24NA4*** | Heat pump without ducts | | 14,300 | $715 |
| No | 209424920 | MITSUBISHI ELECTRIC | MXZ-2C20NA4*** | Heat pump without ducts | | 13,500 | $675 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202680594 | MITSUBISHI ELECTRIC | MUZ-GL09NA*** | MSZ-GL09NA*** | | 6,700 | $335 |
| No | 202680595 | MITSUBISHI ELECTRIC | MUZ-GL12NA*** | MSZ-GL12NA*** | | 9,200 | $460 |
| No | 202680596 | MITSUBISHI ELECTRIC | MUZ-GL15NA*** | MSZ-GL15NA*** | | 12,100 | $605 |
| No | 209832268 | MITSUBISHI ELECTRIC | MUZ-GL18NA*** | MSZ-GL18NA*** | | 13,800 | $690 |
| No | 210819459 | MITSUBISHI ELECTRIC | MUFZ-KJ09NAHZ*** | MFZ-KJ09NA*** | | 7,500 | $375 |
| No | 210819460 | MITSUBISHI ELECTRIC | MUFZ-KJ12NAHZ*** | MFZ-KJ12NA*** | | 8,800 | $440 |
| No | 209447987 | MITSUBISHI ELECTRIC | PUZ-A42NKA7*** | PAA-A42CA1 | | 32,800 | $1,640 |
| No | 209447986 | MITSUBISHI ELECTRIC | PUZ-A42NKA7*** | PAA-A42BA1 | | 32,800 | $1,640 |
| No | 209447985 | MITSUBISHI ELECTRIC | PUZ-A36NKA7*** | PAA-A36CA1 | | 29,400 | $1,470 |
| No | 209447984 | MITSUBISHI ELECTRIC | PUZ-A36NKA7*** | PAA-A36BA1 | | 29,400 | $1,470 |
| No | 209447983 | MITSUBISHI ELECTRIC | PUZ-A30NHA7*** | PAA-A30BA1 | | 21,000 | $1,050 |
| No | 209447982 | MITSUBISHI ELECTRIC | PUZ-A30NHA7*** | PAA-A30AA1 | | 21,000 | $1,050 |
| No | 209447981 | MITSUBISHI ELECTRIC | PUZ-A24NHA7*** | PAA-A24BA1 | | 15,600 | $780 |
| No | 209447980 | MITSUBISHI ELECTRIC | PUZ-A24NHA7*** | PAA-A24AA1 | | 15,600 | $780 |
| No | 209447979 | MITSUBISHI ELECTRIC | PUZ-A24NHA7*** | PAA-A18BA1 | | 13,800 | $690 |
| No | 209447978 | MITSUBISHI ELECTRIC | PUZ-A24NHA7*** | PAA-A18AA1 | | 13,800 | $690 |
| No | 209836198 | MITSUBISHI ELECTRIC | MXZ-3C24NA3 | Heat pump without ducts | | 14,600 | $730 |
| No | 209836197 | MITSUBISHI ELECTRIC | MXZ-2C20NA3 | Heat pump without ducts | | 13,500 | $675 |
| No | 209949002 | MITSUBISHI ELECTRIC | MXZ-4C36NA3 | Combination heat pumps with or without ducts | | 21,200 | $1,060 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 209836184 | MITSUBISHI ELECTRIC | MXZ-4C36NA3 | Heat pump with ducts | | 20,200 | $1,010 |
| No | 209836200 | MITSUBISHI ELECTRIC | MXZ-4C36NA3 | Heat pump without ducts | | 22,200 | $1,110 |
| No | 201754908 | MITSUBISHI ELECTRIC | MXZ-3C30NAHZ2 | Heat pump without ducts | | 18,000 | $900 |
| No | 204629562 | MITSUBISHI ELECTRIC | MUZ-FH18NA2 | NTXWPH18A112A* | | 13,700 | $685 |
| No | 204629569 | MITSUBISHI ELECTRIC | MUZ-FH18NA2 | NAXWPH18A112A* | | 13,700 | $685 |
| No | 204629256 | MITSUBISHI ELECTRIC | NTXSPH18A112A* | MSZ-FH18NA2 | | 13,700 | $685 |
| No | 204629343 | MITSUBISHI ELECTRIC | NAXSPH18A112A* | MSZ-FH18NA2 | | 13,700 | $685 |
| No | 204629348 | MITSUBISHI ELECTRIC | NAXSPB18A112A* | MSZ-FH18NA2 | | 13,700 | $685 |
| No | 204629344 | MITSUBISHI ELECTRIC | NAXSPB06A112A* | MSZ-FH06NA | | 5,900 | $295 |
| No | 204629345 | MITSUBISHI ELECTRIC | NAXSPB09A112A* | MSZ-FH09NA | | 6,700 | $335 |
| No | 204629346 | MITSUBISHI ELECTRIC | NAXSPB12A112A* | MSZ-FH12NA | | 8,100 | $405 |
| No | 204629349 | MITSUBISHI ELECTRIC | NAXSPF09A112A* | MFZ-KJ09NA*** | | 7,500 | $375 |
| No | 204629339 | MITSUBISHI ELECTRIC | NAXSPH06A112A* | MSZ-FH06NA | | 5,900 | $295 |
| No | 204629350 | MITSUBISHI ELECTRIC | NAXSPF12A112A* | MFZ-KJ12NA*** | | 8,800 | $440 |
| No | 204629341 | MITSUBISHI ELECTRIC | NAXSPH12A112A* | MSZ-FH12NA | | 8,100 | $405 |
| No | 204629340 | MITSUBISHI ELECTRIC | NAXSPH09A112A* | MSZ-FH09NA | | 6,700 | $335 |
| No | 204629342 | MITSUBISHI ELECTRIC | NAXSPH15A112A* | MSZ-FH15NA | | 11,000 | $550 |
| No | 204629259 | MITSUBISHI ELECTRIC | NTXSPB12A112A* | MSZ-FH12NA | | 8,100 | $405 |
| No | 204629258 | MITSUBISHI ELECTRIC | NTXSPB09A112A* | MSZ-FH09NA | | 6,700 | $335 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204629260 | MITSUBISHI ELECTRIC | NTXSPB15A112A* | MSZ-FH15NA | | 11,000 | $550 |
| No | 204629257 | MITSUBISHI ELECTRIC | NTXSPB06A112A* | MSZ-FH06NA | | 5,900 | $295 |
| No | 204629261 | MITSUBISHI ELECTRIC | NTXSPB18A112A* | MSZ-FH18NA2 | | 13,700 | $685 |
| No | 204629263 | MITSUBISHI ELECTRIC | NTXSPF12A112A* | MFZ-KJ12NA*** | | 8,800 | $440 |
| No | 204629262 | MITSUBISHI ELECTRIC | NTXSPF09A112A* | MFZ-KJ09NA*** | | 7,500 | $375 |
| No | 204629253 | MITSUBISHI ELECTRIC | NTXSPH09A112A* | MSZ-FH09NA | | 6,700 | $335 |
| No | 204629219 | MITSUBISHI ELECTRIC | MUZ-FH09NAH | NAXWPH09A112A* | | 6,700 | $335 |
| No | 204629252 | MITSUBISHI ELECTRIC | NTXSPH06A112A* | MSZ-FH06NA | | 5,900 | $295 |
| No | 204629570 | MITSUBISHI ELECTRIC | MUZ-FH06NAH | NAXWPH06A112A* | | 5,900 | $295 |
| No | 204629255 | MITSUBISHI ELECTRIC | NTXSPH15A112A* | MSZ-FH15NA | | 11,000 | $550 |
| No | 204629254 | MITSUBISHI ELECTRIC | NTXSPH12A112A* | MSZ-FH12NA | | 8,100 | $405 |
| No | 204629563 | MITSUBISHI ELECTRIC | MUZ-FH06NAH | NTXWPH06A112A* | | 5,900 | $295 |
| No | 204629565 | MITSUBISHI ELECTRIC | MUZ-FH06NA | NAXWPH06A112A* | | 5,900 | $295 |
| No | 204629566 | MITSUBISHI ELECTRIC | MUZ-FH09NA | NAXWPH09A112A* | | 6,700 | $335 |
| No | 204629174 | MITSUBISHI ELECTRIC | MUZ-FH09NAH | NTXWPH09A112A* | | 6,700 | $335 |
| No | 204629560 | MITSUBISHI ELECTRIC | MUZ-FH12NA | NTXWPH12A112A* | | 8,100 | $405 |
| No | 204629558 | MITSUBISHI ELECTRIC | MUZ-FH06NA | NTXWPH06A112A* | | 5,900 | $295 |
| No | 204629568 | MITSUBISHI ELECTRIC | MUZ-FH15NA | NAXWPH15A112A* | | 11,000 | $550 |
| No | 204629559 | MITSUBISHI ELECTRIC | MUZ-FH09NA | NTXWPH09A112A* | | 6,700 | $335 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204629220 | MITSUBISHI ELECTRIC | MUZ-FH12NAH | NAXWPH12A112A* | | 8,100 | $405 |
| No | 204629567 | MITSUBISHI ELECTRIC | MUZ-FH12NA | NAXWPH12A112A* | | 8,100 | $405 |
| No | 204629176 | MITSUBISHI ELECTRIC | MUZ-FH15NAH | NTXWPH15A112A* | | 11,000 | $550 |
| No | 204629175 | MITSUBISHI ELECTRIC | MUZ-FH12NAH | NTXWPH12A112A* | | 8,100 | $405 |
| No | 204629221 | MITSUBISHI ELECTRIC | MUZ-FH15NAH | NAXWPH15A112A* | | 11,000 | $550 |
| No | 204629564 | MITSUBISHI ELECTRIC | MUZ-FH18NAH2 | NTXWPH18A112A* | | 13,700 | $685 |
| No | 204629561 | MITSUBISHI ELECTRIC | MUZ-FH15NA | NTXWPH15A112A* | | 11,000 | $550 |
| No | 204629571 | MITSUBISHI ELECTRIC | MUZ-FH18NAH2 | NAXWPH18A112A* | | 13,700 | $685 |
| No | 206908463 | MITSUBISHI ELECTRIC | MXZ-2C20NAHZ2*** | Heat pump with ducts | | 13,700 | $685 |
| No | 201754445 | MITSUBISHI ELECTRIC | PUMY-P36NKMU* | Heat pump without ducts | | 26,400 | $1,320 |
| No | 201754446 | MITSUBISHI ELECTRIC | PUMY-P48NKMU* | Heat pump with ducts | | 35,000 | $1,750 |
| No | 201755027 | MITSUBISHI ELECTRIC | PUMY-P48NKMU* | Combination heat pumps with or without ducts | | 31,400 | $1,570 |
| No | 201754447 | MITSUBISHI ELECTRIC | PUMY-P48NKMU* | Heat pump without ducts | | 31,400 | $1,570 |
| No | 201754639 | MITSUBISHI ELECTRIC | PUMY-P60NKMU* | Heat pump with ducts | | 41,500 | $2,075 |
| No | 201755026 | MITSUBISHI ELECTRIC | PUMY-P36NKMU* | Combination heat pumps with or without ducts | | 26,500 | $1,325 |
| No | 207342460 | MITSUBISHI ELECTRIC | MXZ-2C20NA3 | Heat pump with ducts | | 12,500 | $625 |
| No | 207348692 | MITSUBISHI ELECTRIC | MXZ-2C20NAHZ3 | Combination heat pumps with or without ducts | | 13,700 | $685 |
| No | 207348691 | MITSUBISHI ELECTRIC | MXZ-2C20NA3 | Combination heat pumps with or without ducts | | 13,000 | $650 |
| No | 207342468 | MITSUBISHI ELECTRIC | MXZ-3C30NA3 | Heat pump with ducts | | 15,100 | $755 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207342464 | MITSUBISHI ELECTRIC | MXZ-3C24NA3 | Heat pump with ducts | | 14,000 | $700 |
| No | 207348693 | MITSUBISHI ELECTRIC | MXZ-3C24NA3 | Combination heat pumps with or without ducts | | 14,000 | $700 |
| No | 207348695 | MITSUBISHI ELECTRIC | MXZ-3C30NA3 | Combination heat pumps with or without ducts | | 15,500 | $775 |
| No | 207342467 | MITSUBISHI ELECTRIC | MXZ-3C30NA3 | Heat pump without ducts | | 16,000 | $800 |
| No | 207525854 | MITSUBISHI ELECTRIC | MXZ-SM36NAM | Combination heat pumps with or without ducts | | 26,400 | $1,320 |
| No | 207517151 | MITSUBISHI ELECTRIC | MXZ-SM36NAM | Heat pump with ducts | | 26,600 | $1,330 |
| No | 207517150 | MITSUBISHI ELECTRIC | MXZ-SM36NAM | Heat pump without ducts | | 26,400 | $1,320 |
| No | 207525857 | MITSUBISHI ELECTRIC | MXZ-SM48NAM | Combination heat pumps with or without ducts | | 33,200 | $1,660 |
| No | 207517157 | MITSUBISHI ELECTRIC | MXZ-SM48NAM | Heat pump with ducts | | 35,000 | $1,750 |
| No | 207517156 | MITSUBISHI ELECTRIC | MXZ-SM48NAM | Heat pump without ducts | | 31,400 | $1,570 |
| No | 202680606 | MITSUBISHI ELECTRIC | MUZ-HM15NAH** | MSZ-HM15NA** | | 11,500 | $575 |
| No | 202680605 | MITSUBISHI ELECTRIC | MUZ-HM12NAH** | MSZ-HM12NA** | | 7,600 | $380 |
| No | 202680604 | MITSUBISHI ELECTRIC | MUZ-HM09NAH** | MSZ-HM09NA** | | 6,700 | $335 |
| No | 202680607 | MITSUBISHI ELECTRIC | MUZ-HM18NAH** | MSZ-HM18NA** | | 11,500 | $575 |
| No | 202680608 | MITSUBISHI ELECTRIC | MUZ-HM24NAH** | MSZ-HM24NA** | | 18,500 | $925 |
| No | 204834276 | MITSUBISHI ELECTRIC | PUMY-P60NKMU3 | Heat pump without ducts | | 41,500 | $2,075 |
| No | 204834217 | MITSUBISHI ELECTRIC | PUMY-P60NKMU3 | Heat pump with ducts | | 40,500 | $2,025 |
| No | 204926542 | MITSUBISHI ELECTRIC | PUMY-P60NKMU3 | Combination heat pumps with or without ducts | | 41,000 | $2,050 |
| No | 201755942 | MITSUBISHI ELECTRIC | MXZ-3C30NA2 | Heat pump without ducts | | 16,000 | $800 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201755943 | MITSUBISHI ELECTRIC | MXZ-4C36NA2 | Heat pump without ducts | | 22,200 | $1,110 |
| No | 201754303 | MITSUBISHI ELECTRIC | MUZ-FH18NAH2 | MSZ-FH18NA** | | 12,480 | $624 |
| No | 201754302 | MITSUBISHI ELECTRIC | MUZ-FH18NA2 | MSZ-FH18NA** | | 13,700 | $685 |
| No | 201754642 | MITSUBISHI ELECTRIC | MXZ-2C20NA2 | Heat pump without ducts | | 13,500 | $675 |
| No | 204629363 | MITSUBISHI ELECTRIC | NAXSMT18A112A* | MSZ-HM18NA*** | | 11,500 | $575 |
| No | 204629556 | MITSUBISHI ELECTRIC | NAXSMT24A112A* | MSZ-HM24NA*** | | 18,500 | $925 |
| No | 204629554 | MITSUBISHI ELECTRIC | NTXSMT24A112A* | MSZ-HM24NA*** | | 18,500 | $925 |
| No | 204629355 | MITSUBISHI ELECTRIC | NAXSST15A112A* | MSZ-GL15NA*** | | 12,100 | $605 |
| No | 204629354 | MITSUBISHI ELECTRIC | NAXSST12A112A* | MSZ-GL12NA*** | | 9,200 | $460 |
| No | 204629353 | MITSUBISHI ELECTRIC | NAXSST09A112A* | MSZ-GL09NA*** | | 6,700 | $335 |
| No | 204629356 | MITSUBISHI ELECTRIC | NAXSST18A112A* | MSZ-GL18NA*** | | 13,800 | $690 |
| No | 204629357 | MITSUBISHI ELECTRIC | NAXSST24A112A* | MSZ-GL24NA*** | | 16,000 | $800 |
| No | 204629283 | MITSUBISHI ELECTRIC | NTXSKS09A112A* | MLZ-KP09NA | | 7,700 | $385 |
| No | 204629285 | MITSUBISHI ELECTRIC | NTXSKS18A112A* | MLZ-KP18NA | | 13,100 | $655 |
| No | 204629284 | MITSUBISHI ELECTRIC | NTXSKS12A112A* | MLZ-KP12NA | | 9,900 | $495 |
| No | 204629273 | MITSUBISHI ELECTRIC | NTXSMT09A112A* | MSZ-HM09NA*** | | 6,700 | $335 |
| No | 204629276 | MITSUBISHI ELECTRIC | NTXSMT18A112A* | MSZ-HM18NA*** | | 11,500 | $575 |
| No | 204629275 | MITSUBISHI ELECTRIC | NTXSMT15A112A* | MSZ-HM15NA*** | | 11,500 | $575 |
| No | 204629274 | MITSUBISHI ELECTRIC | NTXSMT12A112A* | MSZ-HM12NA*** | | 7,600 | $380 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204629266 | MITSUBISHI ELECTRIC | NTXSST09A112A* | MSZ-GL09NA*** | | 6,700 | $335 |
| No | 204629270 | MITSUBISHI ELECTRIC | NTXSST24A112A* | MSZ-GL24NA*** | | 16,000 | $800 |
| No | 204629267 | MITSUBISHI ELECTRIC | NTXSST12A112A* | MSZ-GL12NA*** | | 9,200 | $460 |
| No | 204629269 | MITSUBISHI ELECTRIC | NTXSST18A112A* | MSZ-GL18NA*** | | 13,800 | $690 |
| No | 204629268 | MITSUBISHI ELECTRIC | NTXSST15A112A* | MSZ-GL15NA*** | | 12,100 | $605 |
| No | 204629236 | MITSUBISHI ELECTRIC | SUZ-KA09NA2 | NAXUKS09A112A* | | 7,700 | $385 |
| No | 204629199 | MITSUBISHI ELECTRIC | SUZ-KA09NA2 | NTXCKS09A112A* | | 6,900 | $345 |
| No | 204629196 | MITSUBISHI ELECTRIC | SUZ-KA09NA2 | NTXUKS09A112A* | | 7,700 | $385 |
| No | 204629239 | MITSUBISHI ELECTRIC | SUZ-KA09NA2 | NAXCKS09A112A* | | 6,900 | $345 |
| No | 204629200 | MITSUBISHI ELECTRIC | SUZ-KA12NA2 | NTXCKS12A112A* | | 8,900 | $445 |
| No | 204629203 | MITSUBISHI ELECTRIC | SUZ-KA09NA2 | NTXDKS09A112A* | | 7,600 | $380 |
| No | 204629243 | MITSUBISHI ELECTRIC | SUZ-KA09NA2 | NAXDKS09A112A* | | 7,600 | $380 |
| No | 204629197 | MITSUBISHI ELECTRIC | SUZ-KA12NA2 | NTXUKS12A112A* | | 9,900 | $495 |
| No | 204629204 | MITSUBISHI ELECTRIC | SUZ-KA12NA2 | NTXDKS12A112A* | | 10,000 | $500 |
| No | 204629244 | MITSUBISHI ELECTRIC | SUZ-KA12NA2 | NAXDKS12A112A* | | 10,000 | $500 |
| No | 204629237 | MITSUBISHI ELECTRIC | SUZ-KA12NA2 | NAXUKS12A112A* | | 9,900 | $495 |
| No | 204629214 | MITSUBISHI ELECTRIC | SUZ-KA12NA2 | NTXAMT12A112A* | | 9,900 | $495 |
| No | 204629247 | MITSUBISHI ELECTRIC | SUZ-KA12NA2 | NAXAMT12A112A* | | 9,900 | $495 |
| No | 204629240 | MITSUBISHI ELECTRIC | SUZ-KA12NA2 | NAXCKS12A112A* | | 8,900 | $445 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206328090 | MITSUBISHI ELECTRIC | SUZ-KA12NAHZ | NTXDKS12A112AA | | 9,000 | $450 |
| No | 206328096 | MITSUBISHI ELECTRIC | SUZ-KA12NAHZ | NTXCKS12A112AA | | 8,300 | $415 |
| No | 206374537 | MITSUBISHI ELECTRIC | SUZ-KA12NAHZ | TPEADA0121AA70A | | 9,000 | $450 |
| No | 206328110 | MITSUBISHI ELECTRIC | SUZ-KA12NAHZ | NAXDKS12A112AA | | 9,000 | $450 |
| No | 204629205 | MITSUBISHI ELECTRIC | SUZ-KA15NA2 | NTXDKS15A112A* | | 11,700 | $585 |
| No | 204629201 | MITSUBISHI ELECTRIC | SUZ-KA15NA2 | NTXCKS15A112A* | | 11,900 | $595 |
| No | 206328116 | MITSUBISHI ELECTRIC | SUZ-KA12NAHZ | NAXCKS12A112AA | | 8,300 | $415 |
| No | 204629245 | MITSUBISHI ELECTRIC | SUZ-KA15NA2 | NAXDKS15A112A* | | 11,700 | $585 |
| No | 204629241 | MITSUBISHI ELECTRIC | SUZ-KA15NA2 | NAXCKS15A112A* | | 11,900 | $595 |
| No | 204629206 | MITSUBISHI ELECTRIC | SUZ-KA18NA2 | NTXDKS18A112A* | | 13,900 | $695 |
| No | 206328113 | MITSUBISHI ELECTRIC | SUZ-KA18NAHZ | NAXDKS18A112AA | | 14,200 | $710 |
| No | 206374539 | MITSUBISHI ELECTRIC | SUZ-KA15NAHZ | TPEADA0151AA70A | | 11,700 | $585 |
| No | 204629202 | MITSUBISHI ELECTRIC | SUZ-KA18NA2 | NTXCKS18A112A* | | 12,900 | $645 |
| No | 204629198 | MITSUBISHI ELECTRIC | SUZ-KA18NA2 | NTXUKS18A112A* | | 13,100 | $655 |
| No | 204629215 | MITSUBISHI ELECTRIC | SUZ-KA18NA2 | NTXAMT18A112A* | | 14,000 | $700 |
| No | 204629238 | MITSUBISHI ELECTRIC | SUZ-KA18NA2 | NAXUKS18A112A* | | 13,100 | $655 |
| No | 206328093 | MITSUBISHI ELECTRIC | SUZ-KA18NAHZ | NTXDKS18A112AA | | 14,200 | $710 |
| No | 204629242 | MITSUBISHI ELECTRIC | SUZ-KA18NA2 | NAXCKS18A112A* | | 12,900 | $645 |
| No | 204629246 | MITSUBISHI ELECTRIC | SUZ-KA18NA2 | NAXDKS18A112A* | | 13,900 | $695 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204629248 | MITSUBISHI ELECTRIC | SUZ-KA18NA2 | NAXAMT18A112A* | | 14,000 | $700 |
| No | 206328102 | MITSUBISHI ELECTRIC | SUZ-KA18NAHZ | NTXAMT18A112AA | | 14,300 | $715 |
| No | 206328121 | MITSUBISHI ELECTRIC | SUZ-KA18NAHZ | NAXAMT18A112AA | | 14,300 | $715 |
| No | 204629573 | MITSUBISHI ELECTRIC | MUFZ-KJ12NAHZ*** | NAXFKS12A112A* | | 8,800 | $440 |
| No | 204629572 | MITSUBISHI ELECTRIC | MUFZ-KJ09NAHZ*** | NAXFKS09A112A* | | 7,500 | $375 |
| No | 204629177 | MITSUBISHI ELECTRIC | MUFZ-KJ09NAHZ*** | NTXFKS09A112A* | | 7,500 | $375 |
| No | 204629178 | MITSUBISHI ELECTRIC | MUFZ-KJ12NAHZ*** | NTXFKS12A112A* | | 8,800 | $440 |
| No | 204629182 | MITSUBISHI ELECTRIC | MUZ-GL12NA*** | NTXWST12A112A* | | 9,200 | $460 |
| No | 204629222 | MITSUBISHI ELECTRIC | MUZ-GL09NA*** | NAXWST09A112A* | | 6,700 | $335 |
| No | 204629181 | MITSUBISHI ELECTRIC | MUZ-GL09NA*** | NTXWST09A112A* | | 6,700 | $335 |
| No | 204629187 | MITSUBISHI ELECTRIC | MUZ-HM12NA*** | NTXWMT12A112A* | | 7,600 | $380 |
| No | 204629183 | MITSUBISHI ELECTRIC | MUZ-GL15NA*** | NTXWST15A112A* | | 12,100 | $605 |
| No | 204629223 | MITSUBISHI ELECTRIC | MUZ-GL12NA*** | NAXWST12A112A* | | 9,200 | $460 |
| No | 204629184 | MITSUBISHI ELECTRIC | MUZ-GL18NA*** | NTXWST18A112A* | | 13,800 | $690 |
| No | 204629224 | MITSUBISHI ELECTRIC | MUZ-GL15NA*** | NAXWST15A112A* | | 12,100 | $605 |
| No | 204629185 | MITSUBISHI ELECTRIC | MUZ-GL24NA*** | NTXWST24A112A* | | 16,000 | $800 |
| No | 204629576 | MITSUBISHI ELECTRIC | MUZ-GL18NA*** | NAXWST18A112A* | | 13,800 | $690 |
| No | 204629225 | MITSUBISHI ELECTRIC | MUZ-GL24NA*** | NAXWST24A112A* | | 16,000 | $800 |
| No | 202680601 | MITSUBISHI ELECTRIC | MUZ-HM12NA*** | MSZ-HM12NA*** | | 7,600 | $380 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204629186 | MITSUBISHI ELECTRIC | MUZ-HM09NA*** | NTXWMT09A112A* | | 6,700 | $335 |
| No | 204629227 | MITSUBISHI ELECTRIC | MUZ-HM12NA*** | NAXWMT12A112A* | | 7,600 | $380 |
| No | 202680600 | MITSUBISHI ELECTRIC | MUZ-HM09NA*** | MSZ-HM09NA*** | | 6,700 | $335 |
| No | 204629226 | MITSUBISHI ELECTRIC | MUZ-HM09NA*** | NAXWMT09A112A* | | 6,700 | $335 |
| No | 204629188 | MITSUBISHI ELECTRIC | MUZ-HM15NA*** | NTXWMT15A112A* | | 11,500 | $575 |
| No | 204629189 | MITSUBISHI ELECTRIC | MUZ-HM18NA*** | NTXWMT18A112A* | | 11,500 | $575 |
| No | 204629229 | MITSUBISHI ELECTRIC | MUZ-HM18NA*** | NAXWMT18A112A* | | 11,500 | $575 |
| No | 204629553 | MITSUBISHI ELECTRIC | MUZ-HM24NA*** | NAXWMT24A112A* | | 18,500 | $925 |
| No | 204629228 | MITSUBISHI ELECTRIC | MUZ-HM15NA*** | NAXWMT15A112A* | | 11,500 | $575 |
| No | 204629552 | MITSUBISHI ELECTRIC | MUZ-HM24NA*** | NTXWMT24A112A* | | 18,500 | $925 |
| No | 204629360 | MITSUBISHI ELECTRIC | NAXSMT09A112A* | MSZ-HM09NA*** | | 6,700 | $335 |
| No | 204629372 | MITSUBISHI ELECTRIC | NAXSKS18A112A* | MLZ-KP18NA | | 13,100 | $655 |
| No | 204629370 | MITSUBISHI ELECTRIC | NAXSKS09A112A* | MLZ-KP09NA | | 7,700 | $385 |
| No | 204629361 | MITSUBISHI ELECTRIC | NAXSMT12A112A* | MSZ-HM12NA*** | | 7,600 | $380 |
| No | 204629362 | MITSUBISHI ELECTRIC | NAXSMT15A112A* | MSZ-HM15NA*** | | 11,500 | $575 |
| No | 204629371 | MITSUBISHI ELECTRIC | NAXSKS12A112A* | MLZ-KP12NA | | 9,900 | $495 |
| No | 201754299 | MITSUBISHI ELECTRIC | MUZ-FH12NAH | MSZ-FH12NA** | | 8,100 | $405 |
| No | 204834271 | MITSUBISHI ELECTRIC | PUMY-P36NKMU3 | | | 26,600 | $1,330 |
| No | 204834215 | MITSUBISHI ELECTRIC | PUMY-P48NKMU3 | Heat pump with ducts | | 35,000 | $1,750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204926538 | MITSUBISHI ELECTRIC | PUMY-P36NKMU3 | Combination heat pumps with or without ducts | | 26,400 | $1,320 |
| No | 204926540 | MITSUBISHI ELECTRIC | PUMY-P48NKMU3 | Combination heat pumps with or without ducts | | 33,200 | $1,660 |
| No | 204834274 | MITSUBISHI ELECTRIC | PUMY-P48NKMU3 | Heat pump without ducts | | 31,400 | $1,570 |
| No | 204834270 | MITSUBISHI ELECTRIC | PUMY-P36NKMU3 | Heat pump without ducts | | 26,400 | $1,320 |
| No | 202423532 | MITSUBISHI ELECTRIC | PUMY-P36NKMU2 | Heat pump with ducts | | 26,600 | $1,330 |
| No | 202680599 | MITSUBISHI ELECTRIC | MUZ-GL15NAH*** | MSZ-GL15NA*** | | 12,100 | $605 |
| No | 204834264 | MITSUBISHI ELECTRIC | MXZ-8C48NA2 | Heat pump without ducts | | 33,000 | $1,650 |
| No | 204834265 | MITSUBISHI ELECTRIC | MXZ-8C48NA2 | Heat pump with ducts | | 33,000 | $1,650 |
| No | 204926515 | MITSUBISHI ELECTRIC | MXZ-8C48NA2 | Combination heat pumps with or without ducts | | 33,000 | $1,650 |
| No | 202412084 | MITSUBISHI ELECTRIC | PUMY-P36NKMU2 | Heat pump without ducts | | 26,400 | $1,320 |
| No | 202412087 | MITSUBISHI ELECTRIC | PUMY-P48NKMU2 | Heat pump without ducts | | 31,400 | $1,570 |
| No | 202426338 | MITSUBISHI ELECTRIC | PUMY-P48NKMU2 | Combination heat pumps with or without ducts | | 33,200 | $1,660 |
| No | 201754425 | MITSUBISHI ELECTRIC | MUZ-FE09NAH | MSZ-FE09NA | | 6,700 | $335 |
| No | 201754295 | MITSUBISHI ELECTRIC | MUZ-FE12NAH | MSZ-FE12NA** | | 7,800 | $390 |
| No | 204627020 | MITSUBISHI ELECTRIC | SUZ-KA12NAHZ | SEZ-KD12NA4 | | 9,000 | $450 |
| No | 204627022 | MITSUBISHI ELECTRIC | SUZ-KA18NAHZ | SEZ-KD18NA4 | | 14,200 | $710 |
| No | 202392035 | MITSUBISHI ELECTRIC | SUZ-KA09NAH2 | MLZ-KP09NA | | 7,700 | $385 |
| No | 202392027 | MITSUBISHI ELECTRIC | SUZ-KA09NA2 | SEZ-KD09NA | | 7,600 | $380 |
| No | 201849577 | MITSUBISHI ELECTRIC | MUZ-GL09NAH-U1 | MSZ-GL09NA-U1 | | 6,700 | $335 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201754314 | MITSUBISHI ELECTRIC | MUZ-GL18NAH-U1 | MSZ-GL18NA-U1 | | 13,800 | $690 |
| No | 201754298 | MITSUBISHI ELECTRIC | MUZ-FH12NA | MSZ-FH12NA | | 8,000 | $400 |
| No | 202392036 | MITSUBISHI ELECTRIC | SUZ-KA12NAH2 | MLZ-KP12NA | | 9,900 | $495 |
| No | 202426337 | MITSUBISHI ELECTRIC | PUMY-P36NKMU2 | Combination heat pumps with or without ducts | | 28,728 | $1,436 |
| No | 202392056 | MITSUBISHI ELECTRIC | SUZ-KA18NAH2 | SVZ-KP18NA | | 14,000 | $700 |
| No | 202392055 | MITSUBISHI ELECTRIC | SUZ-KA12NAH2 | SVZ-KP12NA | | 9,900 | $495 |
| No | 202392052 | MITSUBISHI ELECTRIC | SUZ-KA18NAH2 | SLZ-KF18NA | | 12,900 | $645 |
| No | 202392051 | MITSUBISHI ELECTRIC | SUZ-KA12NAH2 | SLZ-KF12NA | | 8,900 | $445 |
| No | 202392050 | MITSUBISHI ELECTRIC | SUZ-KA09NAH2 | SLZ-KF09NA | | 6,900 | $345 |
| No | 202392037 | MITSUBISHI ELECTRIC | SUZ-KA18NAH2 | MLZ-KP18NA | | 13,100 | $655 |
| No | 202392034 | MITSUBISHI ELECTRIC | SUZ-KA18NAH2 | SEZ-KD18NA | | 13,900 | $695 |
| No | 202392033 | MITSUBISHI ELECTRIC | SUZ-KA15NAH2 | SEZ-KD15NA | | 11,700 | $585 |
| No | 202392031 | MITSUBISHI ELECTRIC | SUZ-KA09NAH2 | SEZ-KD09NA | | 7,600 | $380 |
| No | 202392032 | MITSUBISHI ELECTRIC | SUZ-KA12NAH2 | SEZ-KD12NA | | 10,000 | $500 |
| No | 202392030 | MITSUBISHI ELECTRIC | SUZ-KA18NA2 | SEZ-KD18NA | | 13,900 | $695 |
| No | 202392029 | MITSUBISHI ELECTRIC | SUZ-KA15NA2 | SEZ-KD15NA | | 11,700 | $585 |
| No | 202392028 | MITSUBISHI ELECTRIC | SUZ-KA12NA2 | SEZ-KD12NA | | 10,000 | $500 |
| No | 201755029 | MITSUBISHI ELECTRIC | MUZ-GL24NAH*** | MSZ-GL24NA*** | | 16,000 | $800 |
| No | 201754487 | MITSUBISHI ELECTRIC | PUZ-HA30NHA5 | PVA-A30AA* | | 22,600 | $1,130 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201754310 | MITSUBISHI ELECTRIC | MUZ-GL12NAH-U1 | MSZ-GL12NA-U1 | | 9,200 | $460 |
| No | 201754312 | MITSUBISHI ELECTRIC | MUZ-GL15NAH-U1 | MSZ-GL15NA-U1 | | 12,200 | $610 |
| No | 201754301 | MITSUBISHI ELECTRIC | MUZ-FH15NAH | MSZ-FH15NA | | 11,070 | $554 |
| No | 201754300 | MITSUBISHI ELECTRIC | MUZ-FH15NA | MSZ-FH15NA | | 11,000 | $550 |
| No | 201754297 | MITSUBISHI ELECTRIC | MUZ-FH09NAH | MSZ-FH09NA** | | 6,700 | $335 |
| No | 201754910 | MITSUBISHI ELECTRIC | MXZ-4C36NA2 | Heat pump with ducts | | 20,200 | $1,010 |
| No | 201849505 | MITSUBISHI ELECTRIC | MUZ-HM24NA*** | MSZ-HM24NA-U1 | | 18,500 | $925 |
| No | 201755015 | MITSUBISHI ELECTRIC | MXZ-3C24NA2 | Combination heat pumps with or without ducts | | 14,000 | $700 |
| No | 201755013 | MITSUBISHI ELECTRIC | MXZ-2C20NA2 | Combination heat pumps with or without ducts | | 13,000 | $650 |
| No | 201754903 | MITSUBISHI ELECTRIC | MXZ-3C24NA2 | Heat pump with ducts | | 14,000 | $700 |
| No | 201754900 | MITSUBISHI ELECTRIC | MXZ-2C20NAHZ2 | Heat pump with ducts | | 13,700 | $685 |
| No | 201754643 | MITSUBISHI ELECTRIC | MXZ-2C20NA2 | Heat pump with ducts | | 12,500 | $625 |
| No | 201754906 | MITSUBISHI ELECTRIC | MXZ-3C24NAHZ2 | Heat pump with ducts | | 14,000 | $700 |
| No | 201754907 | MITSUBISHI ELECTRIC | MXZ-3C30NA2 | Heat pump with ducts | | 15,100 | $755 |
| No | 201755019 | MITSUBISHI ELECTRIC | MXZ-4C36NA2 | Combination heat pumps with or without ducts | | 21,200 | $1,060 |
| No | 201755017 | MITSUBISHI ELECTRIC | MXZ-3C30NA2 | Combination heat pumps with or without ducts | | 15,550 | $778 |
| No | 201754442 | MITSUBISHI ELECTRIC | MXZ-8C48NA | Heat pump without ducts | | 33,000 | $1,650 |
| No | 202392063 | MITSUBISHI ELECTRIC | SUZ-KA15NAH2 | SLZ-KF15NA | | 11,900 | $595 |
| No | 201755023 | MITSUBISHI ELECTRIC | MXZ-8C48NA | Combination heat pumps with or without ducts | | 34,000 | $1,700 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202680598 | MITSUBISHI ELECTRIC | MUZ-GL12NAH*** | MSZ-GL12NA*** | | 9,200 | $460 |
| No | 202680597 | MITSUBISHI ELECTRIC | MUZ-GL09NAH*** | MSZ-GL09NA*** | | 6,700 | $335 |
| No | 201754427 | MITSUBISHI ELECTRIC | MUZ-FH06NAH | MSZ-FH06NA** | | 5,900 | $295 |
| No | 201754426 | MITSUBISHI ELECTRIC | MUZ-FH06NA | MSZ-FH06NA** | | 5,900 | $295 |
| No | 201754296 | MITSUBISHI ELECTRIC | MUZ-FH09NA | MSZ-FH09NA | | 6,700 | $335 |
| No | 202392045 | MITSUBISHI ELECTRIC | SUZ-KA15NAH2 | PEAD-A15AA | | 11,300 | $565 |
| No | 211306397 | Mitsutomo | HO-SZ06-AB-Q | HJ-UZ06-AB-Q | | 5,700 | $285 |
| No | 211306399 | Mitsutomo | HO-SZ12-AB-Q | HJ-UZ12-AB-Q | | 9,500 | $475 |
| No | 211306398 | Mitsutomo | HO-SZ09-AB-Q | HJ-UZ09-AB-Q | | 9,800 | $490 |
| No | 211306392 | Mitsutomo | HO-SZ06-AB-Q | HW-SZ06-AB-Q | | 7,500 | $375 |
| No | 211306391 | Mitsutomo | RO-SZ36-AB-Q | RW-SZ36-AB-Q | | 24,000 | $1,200 |
| No | 211306389 | Mitsutomo | RO-SZ24-AB-Q | RW-SZ24-AB-Q | | 16,500 | $825 |
| No | 211306388 | Mitsutomo | RO-SZ18-AB-Q | RW-SZ18-AB-Q | | 11,400 | $570 |
| No | 211306387 | Mitsutomo | RO-SZ12-AB-Q | RW-SZ12-AB-Q | | 7,000 | $350 |
| No | 211306386 | Mitsutomo | RO-SZ09-AB-Q | RW-SZ09-AB-Q | | 6,000 | $300 |
| No | 211306385 | Mitsutomo | RO-SZ12-AB-J | RW-SZ12-AB-J | | 7,800 | $390 |
| No | 211306384 | Mitsutomo | RO-SZ09-AB-J | RW-SZ09-AB-J | | 6,300 | $315 |
| No | 211306395 | Mitsutomo | HO-SZ18-AB-Q | HW-SZ18-AB-Q | | 11,100 | $555 |
| No | 211306394 | Mitsutomo | HO-SZ12-AB-Q | HW-SZ12-AB-Q | | 10,300 | $515 |
| No | 211306393 | Mitsutomo | HO-SZ09-AB-Q | HW-SZ09-AB-Q | | 9,300 | $465 |
| No | 211306381 | Mitsutomo | UHO36-NB-Q | UHM36-CB-Q | | 30,400 | $1,520 |
| No | 211306380 | Mitsutomo | UHO30-NB-Q | UHM30-CB-Q | | 21,000 | $1,050 |
| No | 210586143 | MOOVAIR | DMA18HOS28230E8 | CUAC24HACU000X5 | | 13,000 | $650 |
| No | 212361761 | MOOVAIR | DMA36HOS20230E7 | CUB36HAC20CWT7A | | 33,000 | $1,650 |
| No | 212361759 | MOOVAIR | DMA24HOS20230E7 | CUB24HAC20BWT7A | | 21,000 | $1,050 |
| No | 212361758 | MOOVAIR | DMA18HOS20230E7 | CUB24HAC20BWT7A | | 14,700 | $735 |
| No | 208080667 | MOOVAIR | DMA60HOS19230E7 | FMA60HIAHUU230X7 | | 37,000 | $1,850 |
| No | 207706561 | MOOVAIR | DMA36HOS20230E7 | FMA36HIAHUU230X7 | | 30,400 | $1,520 |
| No | 207706560 | MOOVAIR | DMA30HOS20230E7 | FMA30HIAHUU230X7 | | 21,000 | $1,050 |
| No | 208136316 | MOOVAIR | DMA55HOM23230X2 | Heat pump without ducts | | 34,400 | $1,720 |
| No | 207742538 | MOOVAIR | DMA48HOM23230X2 | Heat pump without ducts | | 34,000 | $1,700 |
| No | 207742535 | MOOVAIR | DMA36HOM23230X2 | Heat pump without ducts | | 26,800 | $1,340 |
| No | 207742533 | MOOVAIR | DMA27HOM23230X2 | Heat pump with ducts | | 22,000 | $1,100 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207742530 | MOOVAIR | DMA18HOM23230X2 | Heat pump with ducts | | 14,800 | $740 |
| No | 207742532 | MOOVAIR | DMA27HOM23230X2 | Heat pump without ducts | | 21,000 | $1,050 |
| No | 207742529 | MOOVAIR | DMA18HOM23230X2 | Heat pump without ducts | | 14,300 | $715 |
| No | 207824533 | MOOVAIR | DMA18HOS28230E8 | DUA24HIDU230X5 | | 15,800 | $790 |
| No | 207742516 | MOOVAIR | DMA18HOS25230E8 | DUA18HIDU230X5 | | 12,600 | $630 |
| No | 207742504 | MOOVAIR | DMA18HOS25230E8 | DUA18HICU230X5 | | 12,000 | $600 |
| No | 207742492 | MOOVAIR | DMA18HOS25230E8 | DMA18HIW25230E8 | | 14,900 | $745 |
| No | 207742486 | MOOVAIR | DMA18HOS21230S1 | DMA18HIW21230S1 | | 11,500 | $575 |
| No | 207742484 | MOOVAIR | DMA09HOS21115S1 | DMA09HIW21115S1 | | 6,800 | $340 |
| No | 207742505 | MOOVAIR | DMA24HOS25230E8 | DUA24HICU230X5 | | 19,000 | $950 |
| No | 207742525 | MOOVAIR | DMA36HOS28230E8 | DUA36HIDU230X5 | | 34,000 | $1,700 |
| No | 207742519 | MOOVAIR | DMA48HOS18230S5 | DUA48HIDU230X5 | | 34,000 | $1,700 |
| No | 207742507 | MOOVAIR | DMA48HOS18230S5 | DUA48HICU230X5 | | 30,000 | $1,500 |
| No | 207742518 | MOOVAIR | DMA36HOS18230S5 | DUA36HIDU230X5 | | 25,000 | $1,250 |
| No | 207742506 | MOOVAIR | DMA36HOS18230S5 | DUA36HICU230X5 | | 23,000 | $1,150 |
| No | 208075829 | MOOVAIR | DMA09HOS25230E8 | DMA06HIW25230E8 | | 8,500 | $425 |
| No | 207742494 | MOOVAIR | DMA06HOS28230E8 | DMA06HIW25230E8 | | 8,500 | $425 |
| No | 207742489 | MOOVAIR | DMA36HOS21230S1 | DMA36HIW21230S1 | | 24,000 | $1,200 |
| No | 207742493 | MOOVAIR | DMA24HOS25230E8 | DMA24HIW25230E8 | | 16,200 | $810 |
| No | 207742491 | MOOVAIR | DMA12HOS25230E8 | DMA12HIW25230E8 | | 9,000 | $450 |
| No | 207742490 | MOOVAIR | DMA09HOS25230E8 | DMA09HIW25230E8 | | 8,500 | $425 |
| No | 207742517 | MOOVAIR | DMA24HOS25230E8 | DUA24HIDU230X5 | | 20,000 | $1,000 |
| No | 207742510 | MOOVAIR | DMA18HOS28230E8 | DUA18HICU230X5 | | 15,600 | $780 |
| No | 206401441 | MOOVAIR | DM18HOS25230E3A | DM18HICU230X5 | | 15,600 | $780 |
| No | 207742527 | MOOVAIR | DMA12HOS28230E8 | DUA12HIFU230E5 | | 9,600 | $480 |
| No | 207742522 | MOOVAIR | DMA12HOS28230E8 | DUA12HIDU230X5 | | 10,600 | $530 |
| No | 207742509 | MOOVAIR | DMA12HOS28230E8 | DUA12HICU230X5 | | 9,900 | $495 |
| No | 207742528 | MOOVAIR | DMA12HOS25230E8 | DUA12HIFU230E5 | | 9,000 | $450 |
| No | 207742515 | MOOVAIR | DMA12HOS25230E8 | DUA12HIDU230X5 | | 9,300 | $465 |
| No | 207742521 | MOOVAIR | DMA09HOS28230E8 | DUA09HIDU230X5 | | 10,100 | $505 |
| No | 207742508 | MOOVAIR | DMA09HOS28230E8 | DUA09HICU230X5 | | 9,000 | $450 |
| No | 207742514 | MOOVAIR | DMA09HOS25230E8 | DUA09HIDU230X5 | | 7,700 | $385 |
| No | 207742503 | MOOVAIR | DMA12HOS25230E8 | DUA12HICU230X5 | | 8,900 | $445 |
| No | 207742502 | MOOVAIR | DMA09HOS25230E8 | DUA09HICU230X5 | | 7,500 | $375 |
| No | 207742496 | MOOVAIR | DMA12HOS28230E8 | DMA12HIW25230E8 | | 10,000 | $500 |
| No | 207742495 | MOOVAIR | DMA09HOS28230E8 | DMA09HIW25230E8 | | 9,500 | $475 |
| No | 207742499 | MOOVAIR | DMA09HOS42230E4 | DMA09HIW42230E4 | | 6,900 | $345 |
| No | 207742501 | MOOVAIR | DMA18HOS42230E4 | DMA18HIW42230E4 | | 11,000 | $550 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207742500 | MOOVAIR | DMA12HOS42230E4 | DMA12HIW42230E4 | | 6,900 | $345 |
| No | 203238520 | MOOVAIR | DM48HOM23230X2 | Heat pump without ducts | | 29,600 | $1,480 |
| No | 205782168 | MOOVAIR | DM12HOS23230E2 | DM12HIFU230E5 | | 7,200 | $360 |
| No | 203238789 | MOOVAIR | DM36HOM23230X2 | Heat pump without ducts | | 24,600 | $1,230 |
| No | 204005744 | MOOVAIR | DM09HOS23230E2 | DM09HICU230X5 | | 5,800 | $290 |
| No | 204005732 | MOOVAIR | DM09HOS25230E3 | DM09HIW23230E3 | | 6,900 | $345 |
| No | 203238509 | MOOVAIR | DM09HOS23230E2 | DM09HIW23230E3 | | 5,800 | $290 |
| No | 203238512 | MOOVAIR | DM18HOS23230E2 | DM18HIW23230E3 | | 11,400 | $570 |
| No | 203238510 | MOOVAIR | DM12HOS23230E2 | DM12HIW23230E3 | | 7,700 | $385 |
| No | 204005761 | MOOVAIR | DM36HOM25230X3 | Heat pump with ducts | | 24,600 | $1,230 |
| No | 203238514 | MOOVAIR | DM24HOS23230E2 | DM24HIW23230E3 | | 15,300 | $765 |
| No | 204005749 | MOOVAIR | DM12HOS25230E3 | DM12HICU230X5 | | 8,700 | $435 |
| No | 204005747 | MOOVAIR | DM24HOS23230E2 | DM24HICU230X5 | | 15,800 | $790 |
| No | 202635799 | MOOVAIR | DM09HOS19115S1 | DM09HIW19115S1 | | 6,000 | $300 |
| No | 204005739 | MOOVAIR | DM24HOS23230E2 | DM24HIDU230X5 | | 16,000 | $800 |
| No | 202635801 | MOOVAIR | DM18HOS19230S1 | DM18HIW19230S1 | | 11,000 | $550 |
| No | 204005754 | MOOVAIR | DM48HOS18230E5 | DM48HIDU230X5 | | 33,400 | $1,670 |
| No | 204005741 | MOOVAIR | DM12HOS25230E3 | DM12HIDU230X5 | | 8,500 | $425 |
| No | 203238518 | MOOVAIR | DM27HOM23230X2 | Heat pump without ducts | | 17,200 | $860 |
| No | 204005736 | MOOVAIR | DM09HOS23230E2 | DM09HIDU230X5 | | 6,800 | $340 |
| No | 204005733 | MOOVAIR | DM12HOS25230E3 | DM12HIW23230E3 | | 7,800 | $390 |
| No | 204005740 | MOOVAIR | DM09HOS25230E3 | DM09HIDU230X5 | | 7,200 | $360 |
| No | 204005745 | MOOVAIR | DM12HOS23230E2 | DM12HICU230X5 | | 7,500 | $375 |
| No | 204005738 | MOOVAIR | DM18HOS23230E2 | DM18HIDU230X5 | | 12,000 | $600 |
| No | 204005746 | MOOVAIR | DM18HOS23230E2 | DM18HICU230X5 | | 12,000 | $600 |
| No | 204005753 | MOOVAIR | DM36HOS18230E5 | DM36HIDU230X5 | | 27,600 | $1,380 |
| No | 204005752 | MOOVAIR | DM36HOM25230X3 | Heat pump without ducts | | 23,200 | $1,160 |
| No | 204005757 | MOOVAIR | DM36HOS18230E5 | DM36HICU230X5 | | 25,200 | $1,260 |
| No | 204005758 | MOOVAIR | DM48HOS18230E5 | DM48HICU230X5 | | 35,000 | $1,750 |
| No | 204005755 | MOOVAIR | DM60HOS18230E5 | DM60HIDU230X5 | | 37,600 | $1,880 |
| No | 206377754 | MOOVAIR | DM09HOS42230E4 | DM09HIW42230E4 | | 7,200 | $360 |
| No | 206377756 | MOOVAIR | DM12HOS42230E4 | DM12HIW42230E4 | | 6,800 | $340 |
| No | 206401444 | MOOVAIR | DM24HOS25230E3A | DM24HICU230X5 | | 14,500 | $725 |
| No | 202635803 | MOOVAIR | DM18HOM23230X2 | Heat pump without ducts | | 12,000 | $600 |
| No | 206401439 | MOOVAIR | DM18HOS25230E3A | DM18HIW23230E3 | | 10,900 | $545 |
| No | 207742539 | MOOVAIR | DMA48HOM23230X2 | Heat pump with ducts | | 30,400 | $1,520 |
| No | 208119825 | MOOVAIR | DMA12HOS28230E8 | DM12HIW23230E3 | | 7,600 | $380 |
| No | 202635804 | MOOVAIR | DM27HOM23230X2 | Heat pump without ducts | | 17,200 | $860 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202635806 | MOOVAIR | DM48HOM23230X2 | Heat pump without ducts | | 29,600 | $1,480 |
| No | 208119824 | MOOVAIR | DMA09HOS28230E8 | DM09HIW23230E3 | | 7,100 | $355 |
| No | 208119826 | MOOVAIR | DMA18HOS28230E8 | DM18HIW23230E3 | | 10,900 | $545 |
| No | 203238516 | MOOVAIR | DM18HOM23230X2 | Heat pump without ducts | | 12,000 | $600 |
| No | 208136318 | MOOVAIR | DMA55HOM23230X2 | Combination heat pumps with or without ducts | | 34,600 | $1,730 |
| No | 208136317 | MOOVAIR | DMA55HOM23230X2 | Heat pump with ducts | | 35,000 | $1,750 |
| No | 207742534 | MOOVAIR | DMA27HOM23230X2 | Combination heat pumps with or without ducts | | 16,000 | $800 |
| No | 207742531 | MOOVAIR | DMA18HOM23230X2 | Combination heat pumps with or without ducts | | 11,400 | $570 |
| No | 207742540 | MOOVAIR | DMA48HOM23230X2 | Combination heat pumps with or without ducts | | 30,000 | $1,500 |
| No | 207742543 | MOOVAIR | DMA18HOM25230X3 | Combination heat pumps with or without ducts | | 11,500 | $575 |
| No | 207742546 | MOOVAIR | DMA27HOM25230X3 | Combination heat pumps with or without ducts | | 17,000 | $850 |
| No | 207742520 | MOOVAIR | DMA60HOS18230S5 | DUA60HIDU230X5 | | 37,000 | $1,850 |
| No | 210279122 | MRCOOL | CENTRAL-36-HP-C-230A00 | CENTRAL-36-HP-MUAH230A00 | | 30,400 | $1,520 |
| No | 211644132 | MRCOOL | MVP-36-HP-C-230-00 | MVP-36-HP-MUAH-230-00 | | 20,400 | $1,020 |
| No | 208960638 | MRCOOL | CENTRAL-36-HP-C-23000 | CENTRAL-36-HP-MUAH-23000 | | 20,400 | $1,020 |
| No | 208960640 | MRCOOL | CENTRAL-60-HP-C-23000 | CENTRAL-60-HP-MUAH-23000 | | 37,000 | $1,850 |
| No | 211644133 | MRCOOL | MVP-60-HP-C-230-00 | MVP-60-HP-MUAH-230-00 | | 37,000 | $1,850 |
| No | 211644135 | MRCOOL | MVP-48-HP-C-230-00 | MVP-48-HP-MUAH-230-00 | | 37,000 | $1,850 |
| No | 208960639 | MRCOOL | CENTRAL-48-HP-C-23000 | CENTRAL-48-HP-MUAH-23000 | | 37,000 | $1,850 |
| No | 208960637 | MRCOOL | CENTRAL-30-HP-C-23025 | CENTRAL-30-HP-MUAH-23025 | | 19,000 | $950 |
| No | 211644134 | MRCOOL | MVP-30-HP-C-230-25 | MVP-30-HP-MUAH-230-25 | | 19,000 | $950 |
| No | 211644118 | MRCOOL | MVP-24-HP-C-230-25 | MVP-24-HP-MUAH-230-25 | | 18,000 | $900 |
| No | 208960636 | MRCOOL | CENTRAL-24-HP-C-23025 | CENTRAL-24-HP-MUAH-23025 | | 18,000 | $900 |
| No | 208960635 | MRCOOL | CENTRAL-18-HP-C-23025 | CENTRAL-18-HP-MUAH-23025 | | 14,800 | $740 |
| No | 211644119 | MRCOOL | MVP-18-HP-C-230-25 | MVP-18-HP-MUAH-230-25 | | 14,800 | $740 |
| No | 208959771 | MRCOOL | DIY-MULTI4-36HP230C | Heat pump with ducts | | 23,000 | $1,150 |
| No | 208552972 | MRCOOL | DIY-MULTI5-48HP230C | Heat pump without ducts | | 36,000 | $1,800 |
| No | 208959768 | MRCOOL | DIY-MULTI5-48HP230C | Heat pump with ducts | | 34,800 | $1,740 |
| No | 208552838 | MRCOOL | MULTI5-48HP230B | Heat pump without ducts | | 34,000 | $1,700 |
| No | 208552957 | MRCOOL | MULTI4-36HP230B | Heat pump without ducts | | 26,800 | $1,340 |
| No | 208959770 | MRCOOL | DIY-MULTI3-27HP230C | Heat pump with ducts | | 21,000 | $1,050 |
| No | 207339195 | MRCOOL | DIY-MULTI3-27HP230C | Heat pump without ducts | | 20,000 | $1,000 |
| No | 207339196 | MRCOOL | DIY-MULTI2-18HP230C | Heat pump without ducts | | 13,500 | $675 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208552953 | MRCOOL | MULTI3-27HP230B | Heat pump with ducts | | 22,000 | $1,100 |
| No | 208552830 | MRCOOL | MULTI2-18HP230B | Heat pump with ducts | | 14,800 | $740 |
| No | 208552834 | MRCOOL | MULTI3-27HP230B | Heat pump without ducts | | 21,000 | $1,050 |
| No | 208552828 | MRCOOL | MULTI2-18HP230B | Heat pump without ducts | | 14,300 | $715 |
| No | 209862113 | MRCOOL | DIY-18-HP-C-230C25 | DIYCASSETTE18HP-230C25 | | 14,000 | $700 |
| No | 208552815 | MRCOOL | O-ES-18-HP-C-230B | O-18-HP-WMAH-230B | | 14,900 | $745 |
| No | 208552804 | MRCOOL | A-18-HP-C-230C | A-18-HP-WMAH-230C | | 11,500 | $575 |
| No | 208552799 | MRCOOL | A-12-HP-C-115C | A-09-HP-WMAH-230C | | 6,900 | $345 |
| No | 208552794 | MRCOOL | A-09-HP-C-115C | A-09-HP-WMAH-115C | | 6,800 | $340 |
| No | 207339189 | MRCOOL | DIY-24-HP-C-230C | DIY-24-HP-WMAH-230C25 | | 17,900 | $895 |
| No | 208552791 | MRCOOL | DIY-24-HP-C-230C25 | DIY-24-HP-WMAH-230C25 | | 17,900 | $895 |
| No | 208552788 | MRCOOL | DIY-18-HP-C-230C25 | DIY-18-HP-WMAH-230C25 | | 13,800 | $690 |
| No | 207339188 | MRCOOL | DIY-18-HP-C-230C | DIY-18-HP-WMAH-230C25 | | 13,800 | $690 |
| No | 207339187 | MRCOOL | DIY-12-HP-C-115C | DIY-12-HP-WMAH-115C25 | | 7,500 | $375 |
| No | 208552787 | MRCOOL | DIY-12-HP-C-115C25 | DIY-12-HP-WMAH-115C25 | | 7,500 | $375 |
| No | 208552808 | MRCOOL | A-36-HP-C-230C | A-36-HP-WMAH-230C | | 24,000 | $1,200 |
| No | 208552817 | MRCOOL | O-ES-24-HP-C-230B | O-24-HP-WMAH-230B | | 16,200 | $810 |
| No | 208552813 | MRCOOL | O-ES-12-HP-C-230B | O-12-HP-WMAH-230B | | 9,000 | $450 |
| No | 208552810 | MRCOOL | O-ES-09-HP-C-230B | O-09-HP-WMAH-230B | | 8,500 | $425 |
| No | 208552821 | MRCOOL | O-HH-12-HP-C-230B | O-12-HP-WMAH-230B | | 10,000 | $500 |
| No | 207339162 | MRCOOL | O-HH-12-HP-C-230A | O-12-HP-WMAH-230B | | 10,000 | $500 |
| No | 207339161 | MRCOOL | O-HH-09-HP-C-230A | O-09-HP-WMAH-230B | | 9,500 | $475 |
| No | 208552819 | MRCOOL | O-HH-09-HP-C-230B | O-09-HP-WMAH-230B | | 9,500 | $475 |
| No | 210265865 | MRCOOL | DIY-MULTI4-36HP230C | Combination heat pumps with or without ducts | | 28,400 | $1,420 |
| No | 210265864 | MRCOOL | DIY-MULTI3-27HP230C | Combination heat pumps with or without ducts | | 16,500 | $825 |
| No | 204783911 | MRCOOL | O-ES-09-HP-C-230 | O-09-HP-WMAH-230A | | 5,800 | $290 |
| No | 204783915 | MRCOOL | O-HH-09-HP-C-230 | O-09-HP-WMAH-230A | | 6,900 | $345 |
| No | 204783912 | MRCOOL | O-ES-12-HP-C-230 | O-12-HP-WMAH-230A | | 7,700 | $385 |
| No | 204783916 | MRCOOL | O-HH-12-HP-C-230 | O-12-HP-WMAH-230A | | 7,800 | $390 |
| No | 204469768 | MRCOOL | O-HH-09-HP-C-230 | DUCT-09HP-230 | | 7,200 | $360 |
| No | 204783913 | MRCOOL | O-ES-18-HP-C-230 | O-18-HP-WMAH-230A | | 11,400 | $570 |
| No | 204783914 | MRCOOL | O-ES-24-HP-C-230 | O-24-HP-WMAH-230A | | 15,300 | $765 |
| No | 202918800 | MRCOOL | A-18-HP-C-230B | A-18-HP-WMAH-230B | | 11,000 | $550 |
| No | 204469761 | MRCOOL | O-ES-09-HP-C-230 | DUCT-09HP-230 | | 6,800 | $340 |
| No | 204469763 | MRCOOL | O-ES-18-HP-C-230 | DUCT-18HP-230 | | 12,000 | $600 |
| No | 204469769 | MRCOOL | O-HH-12-HP-C-230 | DUCT-12HP-230 | | 8,500 | $425 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204469764 | MRCOOL | O-ES-24-HP-C-230 | DUCT-24HP-230 | | 16,000 | $800 |
| No | 204340473 | MRCOOL | O-HH-12-HP-C-230 | CASSETTE12HP-230 | | 8,700 | $435 |
| No | 8977708 | MRCOOL | MULTI3-27HP230V1 | Heat pump without ducts | | 17,200 | $860 |
| No | 204469759 | MRCOOL | O-ES-18-HP-C-230 | CASSETTE18HP-230 | | 12,000 | $600 |
| No | 204469760 | MRCOOL | O-ES-24-HP-C-230 | CASSETTE24HP-230 | | 15,800 | $790 |
| No | 204469758 | MRCOOL | O-ES-12-HP-C-230 | CASSETTE12HP-230 | | 7,500 | $375 |
| No | 8977707 | MRCOOL | MULTI2-18HP230V1 | Heat pump without ducts | | 12,000 | $600 |
| No | 8977709 | MRCOOL | MULTI4-36HP230V1 | Heat pump without ducts | | 24,600 | $1,230 |
| No | 204711122 | MRCOOL | DIY-12-HP-C-115B | DIY-12-HP-WMAH-115B | | 7,200 | $360 |
| No | 8977710 | MRCOOL | MULTI5-48HP230V1 | Heat pump without ducts | | 29,600 | $1,480 |
| No | 204711124 | MRCOOL | DIY-24-HP-C-230B | DIY-24-HP-WMAH-230B | | 14,800 | $740 |
| No | 204711123 | MRCOOL | DIY-18-HP-C-230B | DIY-18-HP-WMAH-230B | | 11,300 | $565 |
| No | 207339194 | MRCOOL | DIY-MULTI4-36HP230C | Heat pump without ducts | | 28,000 | $1,400 |
| No | 207339190 | MRCOOL | DIY-36-HP-C-230C | DIY-36-HP-WMAH-230C25 | | 21,000 | $1,050 |
| No | 205415980 | MRCOOL | A-09-HP-C-115B | A-09-HP-WMAH-115B | | 6,000 | $300 |
| No | 208552967 | MRCOOL | MULTI5-48HP230B | Combination heat pumps with or without ducts | | 30,000 | $1,500 |
| No | 208552965 | MRCOOL | MULTI5-48HP230B | Heat pump with ducts | | 30,400 | $1,520 |
| No | 208552955 | MRCOOL | MULTI3-27HP230B | Combination heat pumps with or without ducts | | 16,000 | $800 |
| No | 208552832 | MRCOOL | MULTI2-18HP230B | Combination heat pumps with or without ducts | | 11,400 | $570 |
| No | 208552793 | MRCOOL | DIY-36-HP-C-230C25 | DIY-36-HP-WMAH-230C25 | | 21,000 | $1,050 |
| No | 208674973 | NAKS | NAKS-MULTI AC-27K-208-230 | Heat pump with ducts | | 22,000 | $1,100 |
| No | 208674971 | NAKS | NAKS-MULTI AC-18K-208-230 | Heat pump with ducts | | 14,800 | $740 |
| No | 208674983 | NAKS | NAKS-SPLIT AC-18K-ODU-208-230 | NAKS-SPLIT AC-18K-IDU-208-230 | | 14,100 | $705 |
| No | 208674981 | NAKS | NAKS-SPLIT AC-9K-ODU-208-230 | NAKS-SPLIT AC-9K-IDU-208-230 | | 8,100 | $405 |
| No | 208674979 | NAKS | NAKS-SPLIT AC-9K-ODU-115 | NAKS-SPLIT AC-9K-IDU-115 | | 5,900 | $295 |
| No | 208674984 | NAKS | NAKS-SPLIT AC-24K-ODU-208-230 | NAKS-SPLIT AC-24K-IDU-208-230 | | 17,400 | $870 |
| No | 208674982 | NAKS | NAKS-SPLIT AC-12K-ODU-208-230 | NAKS-SPLIT AC-12K-IDU-208-230 | | 10,000 | $500 |
| No | 208674980 | NAKS | NAKS-SPLIT AC-12K-ODU-115 | NAKS-SPLIT AC-12K-IDU-115 | | 8,900 | $445 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208674978 | NAKS | NAKS-MULTI AC-48K-208-230 | Combination heat pumps with or without ducts | | 30,600 | $1,530 |
| No | 208674977 | NAKS | NAKS-MULTI AC-48K-208-230 | Heat pump with ducts | | 30,400 | $1,520 |
| No | 208674974 | NAKS | NAKS-MULTI AC-27K-208-230 | Combination heat pumps with or without ducts | | 16,100 | $805 |
| No | 208674972 | NAKS | NAKS-MULTI AC-18K-208-230 | Combination heat pumps with or without ducts | | 11,800 | $590 |
| No | 208674986 | NAKS | NAKS-SPLIT AC-36K-ODU-208-230 | NAKS-SPLIT AC-36K-IDU-208-230 | | 20,000 | $1,000 |
| No | 211624976 | NAPOLEON | WSEHV4860RA1-N | NPFX48A60A | | 36,000 | $1,800 |
| No | 212404687 | NAPOLEON | NS18HV48A60 | H,DE50960 | WUV100T5BA | 38,000 | $1,900 |
| No | 212404686 | NAPOLEON | NS18HV48A60 | H,DE50960 | WUV090T5BA | 38,000 | $1,900 |
| No | 212404688 | NAPOLEON | NS18HV48A60 | H,DE50960 | WPV100T5BA | 38,000 | $1,900 |
| No | 212404685 | NAPOLEON | NS18HV48A60 | H,DE50960 | WPV090T5BA | 38,000 | $1,900 |
| No | 212404679 | NAPOLEON | WSEHV4860RA1-N | H,DE50960 | WUV100T5BA | 38,000 | $1,900 |
| No | 212404678 | NAPOLEON | WSEHV4860RA1-N | H,DE50960 | WUV090T5BA | 38,000 | $1,900 |
| No | 212404680 | NAPOLEON | WSEHV4860RA1-N | H,DE50960 | WPV100T5BA | 38,000 | $1,900 |
| No | 212404677 | NAPOLEON | WSEHV4860RA1-N | H,DE50960 | WPV090T5BA | 38,000 | $1,900 |
| No | 212404711 | NAPOLEON | NS18HV48A60 | H,DE37960+TXV | WUV080T4BA | 33,000 | $1,650 |
| No | 212404710 | NAPOLEON | NS18HV48A60 | H,DE37960+TXV | WUV070T4BA | 33,000 | $1,650 |
| No | 212404712 | NAPOLEON | NS18HV48A60 | H,DE37960+TXV | WPV080T4BA | 33,000 | $1,650 |
| No | 212404709 | NAPOLEON | NS18HV48A60 | H,DE37960+TXV | WPV070T4BA | 33,000 | $1,650 |
| No | 212404703 | NAPOLEON | WSEHV4860RA1-N | H,DE37960+TXV | WUV080T4BA | 33,000 | $1,650 |
| No | 212404702 | NAPOLEON | WSEHV4860RA1-N | H,DE37960+TXV | WUV070T4BA | 33,000 | $1,650 |
| No | 212404704 | NAPOLEON | WSEHV4860RA1-N | H,DE37960+TXV | WPV080T4BA | 33,000 | $1,650 |
| No | 212404701 | NAPOLEON | WSEHV4860RA1-N | H,DE37960+TXV | WPV070T4BA | 33,000 | $1,650 |
| No | 207683231 | NAPOLEON | NDHAS22-18-O | NDHAS22-18-I | | 14,100 | $705 |
| No | 207683229 | NAPOLEON | NDHBS20-18-O | NDHBS20-18-I | | 11,400 | $570 |
| No | 207683228 | NAPOLEON | NDHBS20-12-O | NDHBS20-12-I | | 7,000 | $350 |
| No | 207683232 | NAPOLEON | NDHAS22-24-O | NDHAS22-24-I | | 17,400 | $870 |
| No | 207683230 | NAPOLEON | NDHAS22-12-O | NDHAS22-12-I | | 10,000 | $500 |
| No | 207683234 | NAPOLEON | NDHAS26-12-O | NDHAS26-12-I | | 10,000 | $500 |
| No | 207683233 | NAPOLEON | NDHAS26-09-O | NDHAS26-09-I | | 9,500 | $475 |
| No | 8952855 | NAPOLEON | NH25-09F-O | NH25-09F-I | | 6,900 | $345 |
| No | 205309938 | NAPOLEON | NH21-24F-O | NH25-24F-I | | 15,300 | $765 |
| No | 8952856 | NAPOLEON | NH25-12F-O | NH25-12F-I | | 7,800 | $390 |
| No | 205309935 | NAPOLEON | NH21-09F-O | NH25-09F-I | | 5,800 | $290 |
| No | 205309936 | NAPOLEON | NH21-12F-O | NH25-12F-I | | 7,700 | $385 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205309937 | NAPOLEON | NH21-18F-O | NH25-18F-I | | 11,400 | $570 |
| No | 8952863 | NAPOLEON | NH21-18F-O | NH21-18F-I | | 10,400 | $520 |
| No | 8952861 | NAPOLEON | NH21-09F-O | NH21-09F-I | | 6,400 | $320 |
| No | 203363530 | NAPOLEON | NMZO-27F-B | Heat pump without ducts | | 17,200 | $860 |
| No | 203363533 | NAPOLEON | NHAS-18-O | NHAS-18-I | | 11,000 | $550 |
| No | 205309942 | NAPOLEON | NMZO-36F-B | Heat pump without ducts | | 24,600 | $1,230 |
| No | 206597271 | NAPOLEON | NH25-18H-O | NH25-18F-I | | 10,900 | $545 |
| No | 207683240 | NAPOLEON | NDHAM-28-O | Combination heat pumps with or without ducts | | 16,900 | $845 |
| No | 211744620 | NG Trade | OBMH241A | IBMH241A | | 16,500 | $825 |
| No | 211744619 | NG Trade | OBMH181A | IBMH181A | | 11,400 | $570 |
| No | 211744618 | NG Trade | OBMH121A | IBMH121A | | 7,000 | $350 |
| No | 211744617 | NG Trade | OBMH120A | IBMH120A | | 7,800 | $390 |
| No | 211744616 | NG Trade | OBMH090A | IBMH090A | | 6,300 | $315 |
| No | 211709679 | NOVAIR | LEA18SZ25SK-O | 2LEA18UUSK-I | | 14,900 | $745 |
| No | 211709681 | NOVAIR | LEA09SZ25SK-O | 2LEA06UUSK-I | | 8,500 | $425 |
| No | 211709680 | NOVAIR | LEA24SZ25SK-O | 2LEA24UUSK-I | | 16,200 | $810 |
| No | 211709678 | NOVAIR | LEA12SZ25SK-O | 2LEA12UUSK-I | | 9,000 | $450 |
| No | 211709677 | NOVAIR | LEA09SZ25SK-O | 2LEA09UUSK-I | | 8,500 | $425 |
| No | 211709683 | NOVAIR | LEA12SZ35SK-O | 2LEA12UUSK-I | | 10,000 | $500 |
| No | 211709682 | NOVAIR | LEA09SZ35SK-O | 2LEA09UUSK-I | | 9,500 | $475 |
| No | 211253510 | NOVAIR | LEA36-EVOX-30-O | LEA36-EVOX-30-I | | 30,400 | $1,520 |
| No | 211253509 | NOVAIR | LEA30-EVOX-30-O | LEA30-EVOX-30-I | | 21,000 | $1,050 |
| No | 207641271 | NOVAIR | LEA36MZ-4P-25SK-O | Heat pump without ducts | | 26,400 | $1,320 |
| No | 207641274 | NOVAIR | LEA27MZ-3P-25SK-O | Heat pump without ducts | | 20,000 | $1,000 |
| No | 207641273 | NOVAIR | LEA27MZ-3P-25SK-O | Heat pump with ducts | | 22,000 | $1,100 |
| No | 207641277 | NOVAIR | LEA18MZ-2P-25SK-O | Heat pump with ducts | | 14,800 | $740 |
| No | 207641276 | NOVAIR | LEA18MZ-2P-25SK-O | Heat pump without ducts | | 14,400 | $720 |
| No | 207526946 | NOVAIR | LEA09SZ25SK-O | LEA09UUSK-I | | 8,100 | $405 |
| No | 207526952 | NOVAIR | LEA18SZ15SK-O | LEA1815SK-I | | 11,400 | $570 |
| No | 207526950 | NOVAIR | LEA12SZ15SK-O | LEA1215SK-I | | 7,800 | $390 |
| No | 207526945 | NOVAIR | LEA12SZ25SK-O | LEA12UUSK-I | | 10,000 | $500 |
| No | 207526948 | NOVAIR | LEA18SZ35SK-O | LEA18UUSK-I | | 11,100 | $555 |
| No | 207539337 | NOVAIR | LEA12SZ35SK-O | LEA12UUSK-I | | 10,300 | $515 |
| No | 207526947 | NOVAIR | LEA09SZ35SK-O | LEA09UUSK-I | | 9,300 | $465 |
| No | 207526951 | NOVAIR | LEA18SZ25SK-O | LEA18UUSK-I | | 14,100 | $705 |
| No | 207526949 | NOVAIR | LEA09SZ15SK-O | LEA0915SK-I | | 6,300 | $315 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207641275 | NOVAIR | LEA27MZ-3P-25SK-O | Combination heat pumps with or without ducts | | 16,100 | $805 |
| No | 207641278 | NOVAIR | LEA18MZ-2P-25SK-O | Combination heat pumps with or without ducts | | 11,800 | $590 |
| No | 209416883 | NOVAIR | LEA28MZ-3P-35SK-O | Combination heat pumps with or without ducts | | 16,900 | $845 |
| No | 205281385 | NOVAIR PLUS | 24EVANVO | 24EVCNVI | | 15,800 | $790 |
| No | 205281383 | NOVAIR PLUS | 18EVANVO | 18EVCNVI | | 12,000 | $600 |
| No | 205281380 | NOVAIR PLUS | 12EVONVO | 12EVCNVI | | 8,700 | $435 |
| No | 205281386 | NOVAIR PLUS | 09EVONVO | 09EVDNVI | | 7,200 | $360 |
| No | 205281393 | NOVAIR PLUS | 24EVANVO | 24EVDNVI | | 16,000 | $800 |
| No | 205281391 | NOVAIR PLUS | 18EVANVO | 18EVDNVI | | 12,000 | $600 |
| No | 205281388 | NOVAIR PLUS | 12EVONVO | 12EVDNVI | | 8,500 | $425 |
| No | 205281379 | NOVAIR PLUS | 09EVANVO | 09EVCNVI | | 5,800 | $290 |
| No | 205281387 | NOVAIR PLUS | 09EVANVO | 09EVDNVI | | 6,800 | $340 |
| No | 205281397 | NOVAIR PLUS | 27EVANVMO | Heat pump without ducts | | 17,200 | $860 |
| No | 205281381 | NOVAIR PLUS | 12EVANVO | 12EVONVI | | 7,500 | $375 |
| No | 201786770 | NOVAIR PLUS | 24EVONVO | 24EVONVI | | 15,400 | $770 |
| No | 205281377 | NOVAIR PLUS | 24EVANVO | 24EVANVI | | 15,300 | $765 |
| No | 201786765 | NOVAIR PLUS | 09EVONVO | 09EVONVI | | 6,900 | $345 |
| No | 201786767 | NOVAIR PLUS | 12EVONVO | 12EVONVI | | 7,800 | $390 |
| No | 205281403 | NOVAIR PLUS | 48EVANVMO | Heat pump without ducts | | 29,600 | $1,480 |
| No | 205421170 | NOVAIR PLUS | 09EVANVO | 09EVANVI | | 6,400 | $320 |
| No | 205281376 | NOVAIR PLUS | 18EVANVO | 18EVANVI | | 10,400 | $520 |
| No | 206909906 | Olimpia Splendid | OS-CENIH09EI | OS-SENIH09EI | | 5,900 | $295 |
| No | 207506897 | Olimpia Splendid | OS-CENIH36EI | OS-SENIH36EI | | 24,000 | $1,200 |
| No | 207506895 | Olimpia Splendid | OS-CENIH24EI | OS-SENIH24EI | | 17,400 | $870 |
| No | 207506893 | Olimpia Splendid | OS-CENIH12EI | OS-SENIH12EI | | 8,900 | $445 |
| No | 207506894 | Olimpia Splendid | OS-CENIH18EI | OS-SENIH18EI | | 14,100 | $705 |
| No | 205966274 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CA*F3642*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205966275 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3743*6D*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 205966277 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CA*F3137*6A*+TXV | G*VM970603BNB* | 13,000 | $650 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966276 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CA*F4961*6D*+MBVC2000**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966280 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CA*F3137*6A*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205966279 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CA*F3137*6A*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205966278 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CA*F3137*6A*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205966281 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CA*F3137*6A*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205966284 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CA*F3636*6D*+TXV | G*VM970804CNB* | 13,000 | $650 |
| No | 205966296 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CA*F3743*6D*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205966283 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CA*F3636*6D*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205966282 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CA*F3636*6D*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205966285 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CA*F3636*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205966286 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CA*F3636*6D*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205966291 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CA*F3743*6D*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205966287 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CA*F3636*6D*+TXV | G*VS960603BUA* | 13,000 | $650 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966289 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CA*F3642*6D*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205966290 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CA*F3642*6D*+TXV | G*VM970804CNB* | 13,000 | $650 |
| No | 205966288 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CA*F3642*6D*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205966292 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CA*F3743*6D*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205966295 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CA*F3743*6D*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205966294 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CA*F3743*6D*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205966293 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CA*F3743*6D*+TXV | G*VM970804CNB* | 13,000 | $650 |
| No | 205966297 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CHPF3636B6C*+TXV | G*VM970603BNB* | 13,000 | $650 |
| No | 205966298 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CHPF3636B6C*+TXV | G*VM970803BNB* | 13,000 | $650 |
| No | 205966299 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CHPF3636B6C*+MBVC1200**-1A*+TXV | | 13,000 | $650 |
| No | 205966300 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CHPF3636B6C*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205966301 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CHPF3636B6C*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205966302 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CHPF3642C6C*+MBVC1200**-1A*+TXV | | 13,000 | $650 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966303 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CSCF3642N6D*+TXV | G*VS800604BUA* | 13,000 | $650 |
| No | 205966304 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CSCF3642N6D*+TXV | G*VS960603BUA* | 13,000 | $650 |
| No | 205966307 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CA*F3636*6D*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205966306 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CA*F3137*6A*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205966305 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | AVPEC25B14A* | | 13,600 | $680 |
| No | 205966315 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3137*6A*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 205966314 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3137*6A*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 205966311 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CHPF3642C6C*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205966308 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CA*F3642*6D*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205966309 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CA*F3743*6D*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205966310 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200241A* | CHPF3636B6C*+MBVC1201**-1A*+TXV | | 13,000 | $650 |
| No | 205966312 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3137*6A*+TXV | G*VM970603BNB* | 18,200 | $910 |
| No | 205966313 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3137*6A*+TXV | G*VM970803BNB* | 18,200 | $910 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966316 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3137*6A*+TXV | G*VS800604BUA* | 18,200 | $910 |
| No | 205966317 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3137*6A*+TXV | G*VS960603BUA* | 18,200 | $910 |
| No | 205966318 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3642*6D*+TXV | G*VM970603BNB* | 18,000 | $900 |
| No | 205966320 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3642*6D*+TXV | G*VM970804CNB* | 18,200 | $910 |
| No | 205966323 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3642*6D*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 205966319 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3642*6D*+TXV | G*VM970803BNB* | 18,000 | $900 |
| No | 205966321 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3642*6D*+TXV | G*VM971005CNB* | 18,000 | $900 |
| No | 205966322 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3642*6D*+TXV | G*VM971205DNB* | 18,000 | $900 |
| No | 205966324 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3642*6D*+MBVC1600**-1A*+TXV | | 18,000 | $900 |
| No | 205966328 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3642*6D*+TXV | G*VS960805CUA* | 18,000 | $900 |
| No | 205966326 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3642*6D*+TXV | G*VS800805CUA* | 18,000 | $900 |
| No | 205966329 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3743*6D*+TXV | G*VM970603BNB* | 18,200 | $910 |
| No | 205966330 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3743*6D*+TXV | G*VM970803BNB* | 18,200 | $910 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966327 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3642*6D*+TXV | G*VS960603BUA* | 18,000 | $900 |
| No | 205966325 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3642*6D*+TXV | G*VS800604BUA* | 18,200 | $910 |
| No | 205966332 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3743*6D*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 205966333 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3743*6D*+TXV | G*VS800604BUA* | 18,000 | $900 |
| No | 205966340 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CHPF3642C6C*+TXV | G*VM971005CNB* | 18,000 | $900 |
| No | 205966331 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3743*6D*+TXV | G*VM971205DNB* | 18,200 | $910 |
| No | 205966334 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3743*6D*+TXV | G*VS800805CUA* | 18,200 | $910 |
| No | 205966335 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3743*6D*+TXV | G*VS960603BUA* | 18,200 | $910 |
| No | 205966336 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3743*6D*+TXV | G*VS960805CUA* | 18,200 | $910 |
| No | 205966338 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CHPF3642C6C*+TXV | G*VM970803BNB* | 18,000 | $900 |
| No | 205966339 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CHPF3642C6C*+TXV | G*VM970804CNB* | 18,000 | $900 |
| No | 205966337 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CHPF3642C6C*+TXV | G*VM970603BNB* | 18,000 | $900 |
| No | 205966350 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3743*6D*+TXV | G*VM971005CNB* | 18,200 | $910 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966342 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CHPF3642C6C*+MBVC1600**-1A*+TXV | | 18,000 | $900 |
| No | 205966341 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CHPF3642C6C*+MBVC1200**-1A*+TXV | | 18,000 | $900 |
| No | 205966343 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CHPF3642C6C*+TXV | G*VS800604BUA* | 18,000 | $900 |
| No | 205966344 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CHPF3642C6C*+TXV | G*VS800805CUA* | 18,000 | $900 |
| No | 205966345 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CHPF3642C6C*+TXV | G*VS960603BUA* | 18,000 | $900 |
| No | 205966346 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CHPF3642C6C*+TXV | G*VS960805CUA* | 18,000 | $900 |
| No | 205966348 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CHPF3743C6B*+TXV | G*VM970803BNB* | 18,200 | $910 |
| No | 205966349 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3743*6D*+TXV | G*VM970804CNB* | 18,000 | $900 |
| No | 205966347 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CHPF3743C6B*+TXV | G*VM970603BNB* | 18,200 | $910 |
| No | 205966351 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CHPF3743C6B*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 205966352 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CHPF3743C6B*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 205966353 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CHPF3743C6B*+TXV | G*VS800604BUA* | 18,200 | $910 |
| No | 205966354 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CHPF3743C6B*+TXV | G*VS800805CUA* | 18,200 | $910 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966357 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CSCF3642N6D*+TXV | G*VM970603BNB* | 18,200 | $910 |
| No | 205966358 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CSCF3642N6D*+TXV | G*VM970803BNB* | 18,200 | $910 |
| No | 205966356 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CHPF3743C6B*+TXV | G*VS960805CUA* | 18,200 | $910 |
| No | 205966355 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CHPF3743C6B*+TXV | G*VS960603BUA* | 18,200 | $910 |
| No | 205966380 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CSCF3642N6D*+MBVC1201**-1A*+TXV | | 18,200 | $910 |
| No | 205966359 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CSCF3642N6D*+TXV | G*VM970804CNB* | 18,200 | $910 |
| No | 205966360 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CSCF3642N6D*+TXV | G*VM971005CNB* | 18,200 | $910 |
| No | 205966362 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CSCF3642N6D*+MBVC1200**-1A*+TXV | | 18,200 | $910 |
| No | 205966361 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CSCF3642N6D*+TXV | G*VM971205DNB* | 18,200 | $910 |
| No | 205966364 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CSCF3642N6D*+TXV | G*VS800604BUA* | 18,200 | $910 |
| No | 205966363 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CSCF3642N6D*+MBVC1600**-1A*+TXV | | 18,200 | $910 |
| No | 205966365 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CSCF3642N6D*+TXV | G*VS800805CUA* | 18,200 | $910 |
| No | 205966368 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | AVPEC37C14A* | | 18,900 | $945 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966367 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CSCF3642N6D*+TXV | G*VS960805CUA* | 18,200 | $910 |
| No | 205966366 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CSCF3642N6D*+TXV | G*VS960603BUA* | 18,200 | $910 |
| No | 205966378 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CHPF3743C6B*+MBVC1201**-1A*+TXV | | 18,200 | $910 |
| No | 205966369 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | AVPEC59D14A* | | 18,900 | $945 |
| No | 205966370 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3137*6A*+MBVC1201**-1A*+TXV | | 18,000 | $900 |
| No | 205966372 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3642*6D*+MBVC1201**-1A*+TXV | | 18,000 | $900 |
| No | 205966371 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3137*6A*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205966373 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3642*6D*+MBVC1601**-1A*+TXV | | 18,000 | $900 |
| No | 205966375 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3743*6D*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205966374 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CA*F3743*6D*+MBVC1201**-1A*+TXV | | 18,200 | $910 |
| No | 205966376 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CHPF3642C6C*+MBVC1201**-1A*+TXV | | 18,000 | $900 |
| No | 205966379 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CHPF3743C6B*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205966377 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CHPF3642C6C*+MBVC1601**-1A*+TXV | | 18,000 | $900 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966395 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CSCF4860N6D*+TXV | G*VM971005CNB* | 27,400 | $1,370 |
| No | 205966382 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CA*F4860*6D*+TXV | G*VM970804CNB* | 27,400 | $1,370 |
| No | 205966381 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200361A* | CSCF3642N6D*+MBVC1601**-1A*+TXV | | 18,200 | $910 |
| No | 205966385 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CA*F4860*6D*+MBVC1600**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966386 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CA*F4860*6D*+MBVC2000**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966383 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CA*F4860*6D*+TXV | G*VM971005CNB* | 27,400 | $1,370 |
| No | 205966384 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CA*F4860*6D*+TXV | G*VM971205DNB* | 27,400 | $1,370 |
| No | 205966387 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CA*F4860*6D*+TXV | G*VS800805CUA* | 27,400 | $1,370 |
| No | 205966388 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CA*F4860*6D*+TXV | G*VS960805CUA* | 27,400 | $1,370 |
| No | 205966391 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CHPF4860D6D*+TXV | G*VM971205DNB* | 27,800 | $1,390 |
| No | 205966389 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CHPF4860D6D*+TXV | G*VM970804CNB* | 28,000 | $1,400 |
| No | 205966390 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CHPF4860D6D*+TXV | G*VM971005CNB* | 27,800 | $1,390 |
| No | 205966402 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | AVPEC59D14A* | | 27,000 | $1,350 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966392 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CHPF4860D6D*+MBVC1600**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966394 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CSCF4860N6D*+TXV | G*VM970804CNB* | 27,400 | $1,370 |
| No | 205966393 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CHPF4860D6D*+TXV | G*VS800805CUA* | 27,200 | $1,360 |
| No | 205966407 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CSCF4860N6D*+MBVC1601**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966396 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CSCF4860N6D*+TXV | G*VM971205DNB* | 27,400 | $1,370 |
| No | 205966397 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CSCF4860N6D*+MBVC1600**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966398 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CSCF4860N6D*+MBVC2000**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966400 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CSCF4860N6D*+TXV | G*VS800805CUA* | 27,400 | $1,370 |
| No | 205966399 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CSCF4860N6D*+TXV | G*VS800604BUA* | 27,400 | $1,370 |
| No | 205966403 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CA*F4860*6D*+MBVC1601**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966401 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CSCF4860N6D*+TXV | G*VS960805CUA* | 27,400 | $1,370 |
| No | 205966404 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CA*F4860*6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966416 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CHPF4860D6D*+MBVC2000**-1A*+TXV | | 26,600 | $1,330 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205966405 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CHPF4860D6D*+MBVC1601**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966410 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CA*F4961*6D*+TXV | G*VM971005CNB* | 27,800 | $1,390 |
| No | 205966408 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CSCF4860N6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966409 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CA*F4961*6D*+TXV | G*VM970804CNB* | 27,800 | $1,390 |
| No | 205966406 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CHPF4860D6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 205966415 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CA*F4961*6D*+TXV | G*VS960805CUA* | 27,600 | $1,380 |
| No | 205966412 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CA*F4961*6D*+MBVC1600**-1A*+TXV | | 26,800 | $1,340 |
| No | 205966414 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CA*F4961*6D*+TXV | G*VS800805CUA* | 27,200 | $1,360 |
| No | 205966413 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CA*F4961*6D*+TXV | G*VS800604BUA* | 28,000 | $1,400 |
| No | 205966411 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CA*F4961*6D*+TXV | G*VM971205DNB* | 27,800 | $1,390 |
| No | 205966417 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CA*F4961*6D*+MBVC1601**-1A*+TXV | | 26,800 | $1,340 |
| No | 205966418 | ONE HOUR AIR CONDITIONING AND HEATING | GVZC200481A* | CA*F4961*6D*+MBVC2001**-1A*+TXV | | 26,600 | $1,330 |
| No | 9085571 | OUELLET | OTP-C24000-E | OTP-C24000-I | | 14,600 | $730 |
| No | 9085569 | OUELLET | OTP-C12000-E | OTP-C12000-I | | 7,100 | $355 |
| No | 205047854 | PANASONIC | CU-XE18WKUA | CS-XE18WKUAW | | 14,000 | $700 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205047851 | PANASONIC | CU-XE9WKUA | CS-XE9WKUAW | | 8,000 | $400 |
| No | 8860533 | PANASONIC | CU-XE9SKUA | CS-XE9SKUA | | 8,000 | $400 |
| No | 10221199 | PANASONIC | CU-3E19RBU-5 | Heat pump without ducts | | 20,800 | $1,040 |
| No | 8861565 | PANASONIC | CU-XE12SKUA | CS-XE12SKUA | | 10,400 | $520 |
| No | 9571162 | PANASONIC | CU-XE15SKUA | CS-XE15SKUA | | 11,000 | $550 |
| No | 201900210 | PANASONIC | CU-XE12SKUA-1 | CS-XE12SKUA-1 | | 12,500 | $625 |
| No | 7958199 | PANASONIC | CU-E12RKUA | CS-E12RKUAW | | 10,500 | $525 |
| No | 7958198 | PANASONIC | CU-E9RKUA | CS-E9RKUAW | | 8,100 | $405 |
| No | 7958200 | PANASONIC | CU-E18RKUA | CS-E18RKUAW | | 12,000 | $600 |
| No | 9125308 | PANASONIC | CU-E9SD3UA | CS-E9SD3UAW | | 7,900 | $395 |
| No | 9125309 | PANASONIC | CU-E12SD3UA | CS-E12SD3UAW | | 9,500 | $475 |
| No | 205047853 | PANASONIC | CU-XE15WKUA | CS-XE15WKUAW | | 11,000 | $550 |
| No | 205047852 | PANASONIC | CU-XE12WKUA | CS-XE12WKUAW | | 10,000 | $500 |
| No | 207683274 | Pasapair | AMZSAC-OU23V-18 | AMZSAC-IN23V-18 | | 11,400 | $570 |
| No | 207683275 | Pasapair | AMZSAC-OU11V-12 | AMZSAC-IN11V-12 | | 7,800 | $390 |
| No | 210819417 | PAYNE | 38MARBQ30AA3 | 40MBABQ30XB3 | | 20,400 | $1,020 |
| No | 208102134 | PAYNE | 38MARBQ30AA311 | DHMAHBQ30XA3 | | 19,000 | $950 |
| No | 206350306 | PAYNE | 38MARBQ30AA3 | DHMAHBQ30XA3 | | 19,000 | $950 |
| No | 209852146 | PAYNE | 38MURAQ60AA3 | 40MUAAQ60XA3 | | 37,000 | $1,850 |
| No | 209911729 | PAYNE | 38MURAQ48AA3 | 40MUAAQ48XA3 | | 37,000 | $1,850 |
| No | 208447905 | PAYNE | 38MURAQ36AA3 | 40MUAAQ36XA3 | | 20,400 | $1,020 |
| No | 208447899 | PAYNE | 38MURAQ30AB3 | 40MUAAQ30XA3 | | 21,000 | $1,050 |
| No | 208447903 | PAYNE | 38MURAQ30AA3 | 40MUAAQ30XA3 | | 20,000 | $1,000 |
| No | 208447902 | PAYNE | 38MURAQ24AA3 | 40MUAAQ24XA3 | | 21,000 | $1,050 |
| No | 208447900 | PAYNE | 38MURAQ18AA3 | 40MUAAQ18XA3 | | 12,000 | $600 |
| No | 207642936 | PAYNE | 38MGRBQ48EA3 | Heat pump without ducts | | 29,600 | $1,480 |
| No | 204711108 | PAYNE | 38MGRQ24C--3 | Heat pump without ducts | | 17,200 | $860 |
| No | 201846985 | PAYNE | 38MGRQ48E--3 | Heat pump without ducts | | 29,600 | $1,480 |
| No | 201846981 | PAYNE | 38MGRQ18B--3 | Heat pump without ducts | | 12,000 | $600 |
| No | 207826673 | PAYNE | 38MBRCQ58AA3 | 40MBABQ60XA3 | | 34,000 | $1,700 |
| No | 207826672 | PAYNE | 38MBRCQ48AA3 | 40MBABQ48XA3 | | 37,400 | $1,870 |
| No | 208104304 | PAYNE | 38MARBQ36AB3 | 40MBABQ36XB3 | | 25,600 | $1,280 |
| No | 207826671 | PAYNE | 38MBRCQ36AA3 | 40MBABQ36XA3 | | 25,600 | $1,280 |
| No | 208104303 | PAYNE | 38MARBQ30AA311 | 40MBABQ30XB3 | | 19,200 | $960 |
| No | 203380989 | PAYNE | 38MAQB18R--3 | FMA4X18**AL* | | 10,800 | $540 |
| No | 203380991 | PAYNE | 38MAQB30R--3 | FMA4X30**AL* | | 21,200 | $1,060 |
| No | 204344200 | PAYNE | 38MAQB18R--3 | FV4CNF002 | | 11,000 | $550 |
| No | 204344199 | PAYNE | 38MAQB12R--3 | FV4CNF002 | | 6,400 | $320 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203380988 | PAYNE | 38MAQB12R--3 | FMA4X18**AL* | | 7,600 | $380 |
| No | 203381008 | PAYNE | 38MAQB36R--3 | FM(C,U)4Z36**AL* | | 19,000 | $950 |
| No | 203381007 | PAYNE | 38MAQB30R--3 | FM(C,U)4Z30**AL* | | 20,200 | $1,010 |
| No | 207642922 | PAYNE | 38MGHBQ24CA3 | Heat pump with ducts | | 18,500 | $925 |
| No | 207642919 | PAYNE | 38MGRBQ18BA3 | Heat pump with ducts | | 11,800 | $590 |
| No | 207642937 | PAYNE | 38MGRBQ48EA3 | Heat pump with ducts | | 30,400 | $1,520 |
| No | 207642923 | PAYNE | 38MGHBQ24CA3 | Combination heat pumps with or without ducts | | 16,700 | $835 |
| No | 207642920 | PAYNE | 38MGRBQ18BA3 | Combination heat pumps with or without ducts | | 11,400 | $570 |
| No | 207642927 | PAYNE | 38MGRBQ36DA3 | Heat pump without ducts | | 23,400 | $1,170 |
| No | 207642938 | PAYNE | 38MGRBQ48EA3 | Combination heat pumps with or without ducts | | 30,000 | $1,500 |
| No | 207642921 | PAYNE | 38MGHBQ24CA3 | Heat pump without ducts | | 15,000 | $750 |
| No | 207642918 | PAYNE | 38MGRBQ18BA3 | Heat pump without ducts | | 11,000 | $550 |
| No | 206400654 | PAYNE | 38MARBQ09AA3 | DHMSHAQ09XA3 | | 7,500 | $375 |
| No | 201846976 | PAYNE | 38MAQB12R--3 | 40MBDQ12---3 | | 8,500 | $425 |
| No | 206350350 | PAYNE | 38MARBQ09AA3 | 40MBDQ09--3 | | 6,400 | $320 |
| No | 206350314 | PAYNE | 38MARBQ12AA3 | DHMAHBQ12XA3 | | 7,500 | $375 |
| No | 206350315 | PAYNE | 38MARBQ18AA3 | DHMAHBQ18XA3 | | 10,800 | $540 |
| No | 206350349 | PAYNE | 38MARBQ09AA3 | 40MBCQ09--3 | | 6,100 | $305 |
| No | 206188263 | PAYNE | 38MBRBQ36AA3 | 40MBDQ36---3 | | 27,000 | $1,350 |
| No | 206188266 | PAYNE | 38MBRBQ48AA3 | 40MBDQ48---3 | | 29,000 | $1,450 |
| No | 206350352 | PAYNE | 38MARBQ12AA3 | 40MBDQ12--3 | | 8,300 | $415 |
| No | 205788725 | PAYNE | 38MBRBQ48AA3 | 40MBAAQ48XA3 | | 36,000 | $1,800 |
| No | 205788724 | PAYNE | 38MBRBQ36AA3 | 40MBAAQ36XA3 | | 25,000 | $1,250 |
| No | 206396047 | PAYNE | 38MAQB24R--3 | DHMAHBQ24XA3 | | 18,800 | $940 |
| No | 206396045 | PAYNE | 38MAQB12R--3 | DHMAHBQ12XA3 | | 7,500 | $375 |
| No | 206400656 | PAYNE | 38MARBQ18AA3 | DHMSHAQ18XA3 | | 10,800 | $540 |
| No | 206396046 | PAYNE | 38MAQB18R--3 | DHMAHBQ18XA3 | | 11,000 | $550 |
| No | 206400657 | PAYNE | 38MARBQ24AA3 | DHMSHAQ24XA3 | | 19,800 | $990 |
| No | 206396044 | PAYNE | 38MAQB09R--3 | DHMAHBQ09XA3 | | 7,000 | $350 |
| No | 206350312 | PAYNE | 38MARBQ12AA1 | DHMAHBQ12XA1 | | 7,400 | $370 |
| No | 206400655 | PAYNE | 38MARBQ12AA3 | DHMSHAQ12XA3 | | 7,500 | $375 |
| No | 206188262 | PAYNE | 38MBRBQ36AA3 | 40MBCQ36---3 | | 22,000 | $1,100 |
| No | 206350313 | PAYNE | 38MARBQ09AA3 | DHMAHBQ09XA3 | | 7,500 | $375 |
| No | 206188265 | PAYNE | 38MBRBQ48AA3 | 40MBCQ48---3 | | 29,000 | $1,450 |
| No | 206350351 | PAYNE | 38MARBQ12AA3 | 40MBCQ12--3 | | 7,900 | $395 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206188261 | PAYNE | 38MBRBQ36AA3 | 40MBFQ36---3 | | 22,000 | $1,100 |
| No | 206188264 | PAYNE | 38MBRBQ48AA3 | 40MBFQ48---3 | | 29,000 | $1,450 |
| No | 206350353 | PAYNE | 38MARBQ12AA3 | 40MBFQ12--3 | | 8,400 | $420 |
| No | 201846969 | PAYNE | 38MAQB12R--3 | DHMSHAQ12XA3 | | 7,800 | $390 |
| No | 202463638 | PAYNE | 38MPRAQ18AA3 | DHMPHAQ18XA3 | | 12,300 | $615 |
| No | 201753410 | PAYNE | 38MPRAQ09AA3 | DHMPHAQ09XA3 | | 7,200 | $360 |
| No | 201753413 | PAYNE | 38MPRAQ12AA3 | DHMPHAQ12XA3 | | 6,800 | $340 |
| No | 201846974 | PAYNE | 38MAQB18R--3 | 40MBCQ18---3 | | 12,000 | $600 |
| No | 201847044 | PAYNE | 38MBRQ58A--3 | 40MBDQ58---3 | | 37,600 | $1,880 |
| No | 201847043 | PAYNE | 38MBRQ48A--3 | 40MBDQ48---3 | | 33,400 | $1,670 |
| No | 201847041 | PAYNE | 38MBRQ48A--3 | 40MBCQ48---3 | | 35,000 | $1,750 |
| No | 201847048 | PAYNE | 38MBRQ58A--3 | 40MBFQ58---3 | | 39,000 | $1,950 |
| No | 201846967 | PAYNE | 38MAQB12R--1 | DHMSHAQ12XA1 | | 7,600 | $380 |
| No | 201846973 | PAYNE | 38MAQB12R--3 | 40MBCQ12---3 | | 8,700 | $435 |
| No | 201847039 | PAYNE | 38MAQB24R--3 | 40MBCQ24---3 | | 16,200 | $810 |
| No | 201846979 | PAYNE | 38MAQB12R--3 | 40MBFQ12---3 | | 9,600 | $480 |
| No | 201846970 | PAYNE | 38MAQB18R--3 | DHMSHAQ18XA3 | | 10,800 | $540 |
| No | 201846980 | PAYNE | 38MAQB18R--3 | 40MBFQ18---3 | | 13,400 | $670 |
| No | 201846972 | PAYNE | 38MAQB09R--3 | 40MBCQ09---3 | | 6,700 | $335 |
| No | 201847042 | PAYNE | 38MBRQ36A--3 | 40MBDQ36---3 | | 27,600 | $1,380 |
| No | 201847040 | PAYNE | 38MBRQ36A--3 | 40MBCQ36---3 | | 25,200 | $1,260 |
| No | 201847046 | PAYNE | 38MBRQ36A--3 | 40MBFQ36---3 | | 25,400 | $1,270 |
| No | 201846975 | PAYNE | 38MAQB09R--3 | 40MBDQ09---3 | | 7,200 | $360 |
| No | 201846977 | PAYNE | 38MAQB18R--3 | 40MBDQ18---3 | | 13,400 | $670 |
| No | 201847070 | PAYNE | 38MGRQ48E--3 | Heat pump with ducts | | 34,000 | $1,700 |
| No | 204707611 | PAYNE | 38MGRQ24C--3 | Heat pump with ducts | | 17,600 | $880 |
| No | 201847066 | PAYNE | 38MGRQ18B--3 | Heat pump with ducts | | 11,500 | $575 |
| No | 204722804 | PAYNE | 38MGRQ48E--3 | Combination heat pumps with or without ducts | | 31,800 | $1,590 |
| No | 204722801 | PAYNE | 38MGRQ24C--3 | Combination heat pumps with or without ducts | | 17,400 | $870 |
| No | 204722800 | PAYNE | 38MGRQ18B--3 | Combination heat pumps with or without ducts | | 11,700 | $585 |
| No | 211253526 | PERFECTAIRE | 3PAHHSD36-SZO | 3PAHHSD36-AHU | | 30,400 | $1,520 |
| No | 211253525 | PERFECTAIRE | 3PAHHSD30-SZO | 3PAHHSD30-AHU | | 21,000 | $1,050 |
| No | 211253529 | PERFECTAIRE | 3PAMSH55-MZO5 | Heat pump without ducts | | 36,400 | $1,820 |
| No | 211253535 | PERFECTAIRE | 3PAMSHH06-SZO | 3PAMSHH06-UVW | | 7,500 | $375 |
| No | 207657354 | PERFECTAIRE | 3PAMSH36-MZO4 | Heat pump without ducts | | 26,400 | $1,320 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207657356 | PERFECTAIRE | 3PAMSH48-MZO5 | Heat pump without ducts | | 36,000 | $1,800 |
| No | 207657351 | PERFECTAIRE | 3PAMSH27-MZO3 | Heat pump without ducts | | 20,000 | $1,000 |
| No | 207657350 | PERFECTAIRE | 3PAMSH27-MZO3 | Heat pump with ducts | | 22,000 | $1,100 |
| No | 207657348 | PERFECTAIRE | 3PAMSH18-MZO2 | Heat pump with ducts | | 14,800 | $740 |
| No | 207657347 | PERFECTAIRE | 3PAMSH18-MZO2 | Heat pump without ducts | | 14,400 | $720 |
| No | 210410111 | PERFECTAIRE | 3PAMSHH12-SZO | 3PAMSCONH12-2 | | 10,200 | $510 |
| No | 208815368 | PERFECTAIRE | 3PAMSHH18-SZO | 3PAMSHH18-UVW | | 11,100 | $555 |
| No | 207614055 | PERFECTAIRE | 3PAMSHH12-SZO | 3PAMSHH12-UVW | | 10,300 | $515 |
| No | 207614054 | PERFECTAIRE | 3PAMSHH09-SZO | 3PAMSHH09-UVW | | 9,300 | $465 |
| No | 207796632 | PERFECTAIRE | 3PAMSHH18-SZO | 3PAMSCH18 | | 15,600 | $780 |
| No | 207796634 | PERFECTAIRE | 3PAMSHH18-SZO | 3PAMSFCH18 | | 12,000 | $600 |
| No | 207796631 | PERFECTAIRE | 3PAMSHH12-SZO | 3PAMSCONH12 | | 9,600 | $480 |
| No | 207796630 | PERFECTAIRE | 3PAMSHH12-SZO | 3PAMSDH12 | | 10,600 | $530 |
| No | 207796629 | PERFECTAIRE | 3PAMSHH12-SZO | 3PAMSCH12 | | 9,900 | $495 |
| No | 207796628 | PERFECTAIRE | 3PAMSHH09-SZO | 3PAMSDH09 | | 10,100 | $505 |
| No | 202585747 | PERFECTAIRE | 2PAMSH18-MZO2 | Heat pump without ducts | | 12,000 | $600 |
| No | 202585746 | PERFECTAIRE | 2PAMSH27-MZO3 | Heat pump without ducts | | 17,200 | $860 |
| No | 9856845 | PERFECTAIRE | 1PAMSHH12-SZO-22.5 | 1PAMSHH12-SZW-22.5 | | 7,800 | $390 |
| No | 9856844 | PERFECTAIRE | 1PAMSHH09-SZO-25 | 1PAMSHH09-SZW-25 | | 6,900 | $345 |
| No | 9964800 | PERFECTAIRE | 2PAMSH48-MZO5 | Heat pump without ducts | | 29,600 | $1,480 |
| No | 205645139 | PERFECTAIRE | 2PAMS36-HH-MZO4 | Heat pump with ducts | | 24,600 | $1,230 |
| No | 205645138 | PERFECTAIRE | 2PAMS36-HH-MZO4 | Heat pump without ducts | | 23,200 | $1,160 |
| No | 207657357 | PERFECTAIRE | 3PAMSH48-MZO5 | Heat pump with ducts | | 30,400 | $1,520 |
| No | 207192280 | PERFECTAIRE | 1PAMSHH24-SZW-20.5 | 2PAMSCH24 | | 14,500 | $725 |
| No | 207338159 | PERFECTAIRE | 3PAMSHH18-SZO-20.5 | 2PAMSHH18-SZW-20 | | 10,900 | $545 |
| No | 207192285 | PERFECTAIRE | 1PAMSHH12-SZO-22.5 | 2PAMSCH12 | | 8,700 | $435 |
| No | 207192289 | PERFECTAIRE | 1PAMSHH12-SZO-22.5 | 2PAMSDH12 | | 8,500 | $425 |
| No | 207192288 | PERFECTAIRE | 1PAMSHH09-SZO-25 | 2PAMSDH09 | | 7,200 | $360 |
| No | 207192283 | PERFECTAIRE | 2PAMSH18-MZO | 2PAMSH18-MZW | | 10,400 | $520 |
| No | 207657358 | PERFECTAIRE | 3PAMSH48-MZO5 | Combination heat pumps with or without ducts | | 30,600 | $1,530 |
| No | 207657349 | PERFECTAIRE | 3PAMSH18-MZO2 | Combination heat pumps with or without ducts | | 11,800 | $590 |
| No | 207657352 | PERFECTAIRE | 3PAMSH27-MZO3 | Combination heat pumps with or without ducts | | 16,100 | $805 |
| No | 207657340 | PERFECTAIRE | 3PAMS27-HH-MZO3 | Combination heat pumps with or without ducts | | 16,900 | $845 |
| No | 205653641 | PERFECTAIRE | 3PAMSHQCO09 | 3PAMSHQCW09 | | 5,000 | $250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206428592 | PERFECTAIRE | 3PAMSHHQC24-MZO3 | Heat pump without ducts | | 15,400 | $770 |
| No | 206428591 | PERFECTAIRE | 3PAMSHHQC18-MZO2 | Heat pump without ducts | | 12,200 | $610 |
| No | 205653643 | PERFECTAIRE | 3PAMSHQCO18 | 3PAMSHQCW18 | | 11,600 | $580 |
| No | 205653644 | PERFECTAIRE | 3PAMSHQCO24 | 3PAMSHQCW24 | | 14,500 | $725 |
| No | 205653642 | PERFECTAIRE | 3PAMSHQCO12 | 3PAMSHQCW12 | | 7,500 | $375 |
| No | 208121967 | PIONEER | YN040GMFI22M4E | Heat pump without ducts | | 26,400 | $1,320 |
| No | 208121970 | PIONEER | YN050GMFI22M5E | Heat pump without ducts | | 36,000 | $1,800 |
| No | 207028598 | PIONEER | YH4860GHFD18R2 | DR060GHFD18HT2 | | 40,000 | $2,000 |
| No | 207028597 | PIONEER | YH4248GHFD18R2 | DR048GHFD18HT2 | | 31,000 | $1,550 |
| No | 207028595 | PIONEER | YH3036GHFD18R2 | DR036GHFD18HT2 | | 24,000 | $1,200 |
| No | 207028594 | PIONEER | YH1824GHFD18R2 | DR024GHFD18HT2 | | 15,000 | $750 |
| No | 208121964 | PIONEER | YN030GMFI22M3E | Heat pump without ducts | | 20,000 | $1,000 |
| No | 208121965 | PIONEER | YN030GMFI22M3E | Heat pump with ducts | | 22,000 | $1,100 |
| No | 208121962 | PIONEER | YN020GMFI22M2E | Heat pump with ducts | | 14,800 | $740 |
| No | 208121961 | PIONEER | YN020GMFI22M2E | Heat pump without ducts | | 14,400 | $720 |
| No | 208101241 | PIONEER | YN024GMFI22RPE | WS024GMFI22HLE | | 18,000 | $900 |
| No | 208141953 | PIONEER | YN018GMFI22RPE | RB018GMFILDFHD | | 12,600 | $630 |
| No | 208191863 | PIONEER | YN018GMFI22RPE | CB018GMFILCFHD | | 12,000 | $600 |
| No | 208141956 | PIONEER | YN018GMFI22RPE | UB018GMFILCFHD | | 12,800 | $640 |
| No | 208101239 | PIONEER | YN012GMFI22RPE | WS012GMFI22HLE | | 8,200 | $410 |
| No | 208101238 | PIONEER | YN009GMFI22RPE | WS009GMFI22HLE | | 8,300 | $415 |
| No | 208101240 | PIONEER | YN018GMFI22RPE | WS018GMFI22HLE | | 14,000 | $700 |
| No | 208101237 | PIONEER | YN012AMFI22RPE | WS012AMFI22HLE | | 8,400 | $420 |
| No | 208101236 | PIONEER | YN009AMFI22RPE | WS009AMFI22HLE | | 8,400 | $420 |
| No | 208101249 | PIONEER | YN018GMFI20RPD | WS018GMFI20HLD | | 11,500 | $575 |
| No | 208101235 | PIONEER | YN009GMFI20RPD | WS009GMFI20HLD | | 6,900 | $345 |
| No | 208101234 | PIONEER | YN009AMFI20RPD | WS009AMFI20HLD | | 6,800 | $340 |
| No | 208191864 | PIONEER | YN024GMFI22RPE | CB024GMFILDFHE | | 19,000 | $950 |
| No | 208121947 | PIONEER | YN024GMFI20RPD | CB024GMFILDFHE | | 19,000 | $950 |
| No | 208121955 | PIONEER | YN048GMFI18RUE | RB048GMFILDFHD | | 34,000 | $1,700 |
| No | 208121949 | PIONEER | YN048GMFI18RUE | CB048GMFILDFHE | | 30,000 | $1,500 |
| No | 208121960 | PIONEER | YN048GMFI18RUE | UB048GMFILCFHD | | 29,000 | $1,450 |
| No | 208121954 | PIONEER | YN036GMFI18RUE | RB036GMFILDFHD | | 25,000 | $1,250 |
| No | 208121948 | PIONEER | YN036GMFI18RUE | CB036GMFILDFHE | | 23,000 | $1,150 |
| No | 208121959 | PIONEER | YN036GMFI18RUE | UB036GMFILCFHD | | 23,000 | $1,150 |
| No | 208101252 | PIONEER | YN036GMFI20RPD | WS036GMFI20HLD | | 24,000 | $1,200 |
| No | 208141954 | PIONEER | YN024GMFI22RPE | RB024GMFILDFHD | | 20,000 | $1,000 |
| No | 208141955 | PIONEER | YN012GMFI22RPE | FB012GMFILDFHE | | 9,000 | $450 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208141952 | PIONEER | YN012GMFI22RPE | RB012GMFILDFHD | | 9,300 | $465 |
| No | 208141951 | PIONEER | YN009GMFI22RPE | RB009GMFILDFHD | | 7,700 | $385 |
| No | 208141957 | PIONEER | YN024GMFI22RPE | UB024GMFILCFHD | | 16,000 | $800 |
| No | 208191861 | PIONEER | YN012GMFI22RPE | CB012GMFILCFHD | | 8,900 | $445 |
| No | 208121945 | PIONEER | YN012GMFI20RPD | CB012GMFILCFHD | | 8,900 | $445 |
| No | 208121944 | PIONEER | YN009GMFI20RPD | CB009GMFILCFHD | | 7,500 | $375 |
| No | 208191857 | PIONEER | YN009GMFI22RPE | CB009GMFILCFHD | | 7,500 | $375 |
| No | 202576838 | PIONEER | YN018GMFI19RPD | WS018GMFI19HLD | | 11,000 | $550 |
| No | 8819849 | PIONEER | YN009GMFI22RPD | WS009GMFI22HLD | | 6,400 | $320 |
| No | 202576834 | PIONEER | YN009AMFI19RPD | WS009AMFI19HLD | | 6,000 | $300 |
| No | 8819851 | PIONEER | YN018GMFI22RPD | WS018GMFI22HLD | | 10,400 | $520 |
| No | 8819848 | PIONEER | YN012AMFI22RPD | WS012AMFI22HLD | | 7,100 | $355 |
| No | 207698169 | PIONEER | YN040GLFI22M4D | YN040GLFI22M4D | | 23,000 | $1,150 |
| No | 207698163 | PIONEER | YN030GLFI22M3D | YN030GLFI22M3D | | 16,400 | $820 |
| No | 207698162 | PIONEER | YN020GLFI22M2D | YN020GLFI22M2D | | 13,700 | $685 |
| No | 207743771 | PIONEER | YN024GLFI22RPD | WT024GLFI22HLD | | 13,900 | $695 |
| No | 207743770 | PIONEER | YN018GLFI22RPD | WT018GLFI22HLD | | 10,000 | $500 |
| No | 207743769 | PIONEER | YN012GLFI22RPD | WT012GLFI22HLD | | 7,600 | $380 |
| No | 207743768 | PIONEER | YN009GLFI22RPD | WT009GLFI22HLD | | 5,900 | $295 |
| No | 207743767 | PIONEER | YN012ALFI22RPD | WT012ALFI22HLD | | 7,100 | $355 |
| No | 207743766 | PIONEER | YN009ALFI22RPD | WT009ALFI22HLD | | 5,900 | $295 |
| No | 212394338 | PolarWave | ACIQ-18-EHPB | ACIQ-18-ACL | | 13,000 | $650 |
| No | 212394348 | PolarWave | ACIQ-48-HPB | ACIQ-48-ACL | | 32,000 | $1,600 |
| No | 212394347 | PolarWave | ACIQ-36-HPB | ACIQ-36-ACL | | 33,000 | $1,650 |
| No | 212394342 | PolarWave | ACIQ-48-EHPB | ACIQ-48-ACL | | 30,400 | $1,520 |
| No | 212394341 | PolarWave | ACIQ-36-EHPB | ACIQ-36-ACL | | 19,800 | $990 |
| No | 212394345 | PolarWave | ACIQ-24-HPB | ACIQ-24-ACL | | 21,000 | $1,050 |
| No | 212394344 | PolarWave | ACIQ-18-HPB | ACIQ-18-ACL | | 14,700 | $735 |
| No | 212394343 | PolarWave | ACIQ-60-EHPB | ACIQ-60-ACL | | 34,000 | $1,700 |
| No | 212394340 | PolarWave | ACIQ-30-EHPB | ACIQ-30-ACL | | 22,000 | $1,100 |
| No | 212394339 | PolarWave | ACIQ-24-EHPB | ACIQ-24-ACL | | 22,000 | $1,100 |
| No | 212316111 | PolarWave | ACIQ-06ZPL-HP230B | SCC-0609-HH-M | | 5,700 | $285 |
| No | 212316113 | PolarWave | ACIQ-12ZPL-HP230B | SCC-1218-HH-M | | 9,500 | $475 |
| No | 212316112 | PolarWave | ACIQ-09ZPL-HP230B | SCC-0609-HH-M | | 9,800 | $490 |
| No | 212316116 | PolarWave | ACIQ-18ZPL-HP230B | ACIQ-18FM-HH-MC | | 14,700 | $735 |
| No | 212316115 | PolarWave | ACIQ-12ZPL-HP230B | ACIQ-12FM-HH-MC | | 10,200 | $510 |
| No | 212316134 | PolarWave | ES-55Z-M5B | Combination heat pumps with or without ducts | | 34,800 | $1,740 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 212316132 | PolarWave | ES-55Z-M5B | Heat pump without ducts | | 34,400 | $1,720 |
| No | 212316131 | PolarWave | ES-48Z-M5B | Combination heat pumps with or without ducts | | 35,000 | $1,750 |
| No | 212316129 | PolarWave | ES-48Z-M5B | Heat pump without ducts | | 34,000 | $1,700 |
| No | 212316068 | PolarWave | ACIQ-18Z-HP230B | ACIQ-18W-HP230B | | 11,500 | $575 |
| No | 212316066 | PolarWave | ACIQ-09Z-HP115B | ACIQ-09W-HP115B | | 6,800 | $340 |
| No | 212316105 | PolarWave | ACIQ-36ZPL-HP230B | ACIQ-36CD-HH-MB | | 34,000 | $1,700 |
| No | 212316098 | PolarWave | ACIQ-06ZPL-HP230B | ACIQ-06W-HH-MC | | 8,500 | $425 |
| No | 212316125 | PolarWave | ES-27Z-M3B | Combination heat pumps with or without ducts | | 21,400 | $1,070 |
| No | 212316122 | PolarWave | ES-18Z-M2B | Combination heat pumps with or without ducts | | 14,500 | $725 |
| No | 212316124 | PolarWave | ES-27Z-M3B | Heat pump with ducts | | 22,000 | $1,100 |
| No | 212316121 | PolarWave | ES-18Z-M2B | Heat pump with ducts | | 14,800 | $740 |
| No | 212316126 | PolarWave | ES-36Z-M4B | Heat pump without ducts | | 26,800 | $1,340 |
| No | 212316123 | PolarWave | ES-27Z-M3B | Heat pump without ducts | | 21,000 | $1,050 |
| No | 212316120 | PolarWave | ES-18Z-M2B | Heat pump without ducts | | 14,300 | $715 |
| No | 212316070 | PolarWave | ACIQ-36Z-HP230B | ACIQ-36W-HP230B | | 24,000 | $1,200 |
| No | 212316077 | PolarWave | ACIQ-18ZPL-HP230B | ACIQ-18CC-HH-MB | | 15,600 | $780 |
| No | 212316083 | PolarWave | ACIQ-18ZPL-HP230B | ACIQ-18FM-HH-MB | | 12,000 | $600 |
| No | 212316082 | PolarWave | ACIQ-12ZPL-HP230B | ACIQ-12FM-HH-MB | | 9,600 | $480 |
| No | 212316079 | PolarWave | ACIQ-12ZPL-HP230B | ACIQ-12CD-HH-MB | | 10,600 | $530 |
| No | 212316076 | PolarWave | ACIQ-12ZPL-HP230B | ACIQ-12CC-HH-MB | | 9,900 | $495 |
| No | 212316078 | PolarWave | ACIQ-09ZPL-HP230B | ACIQ-09CD-HH-MB | | 10,100 | $505 |
| No | 212316075 | PolarWave | ACIQ-09ZPL-HP230B | ACIQ-09CC-HH-MB | | 9,000 | $450 |
| No | 212316072 | PolarWave | ACIQ-12ZPL-HP230B | ACIQ-12W-HH-MB | | 10,000 | $500 |
| No | 212316100 | PolarWave | ACIQ-12ZPL-HP230B | ACIQ-12W-HH-MC | | 10,000 | $500 |
| No | 212316099 | PolarWave | ACIQ-09ZPL-HP230B | ACIQ-09W-HH-MC | | 9,500 | $475 |
| No | 212316071 | PolarWave | ACIQ-09ZPL-HP230B | ACIQ-09W-HH-MB | | 9,500 | $475 |
| No | 211991200 | PREMIUM LEVELLA | PIAWMZ488800B | Combination heat pumps with or without ducts | | 36,000 | $1,800 |
| No | 211991193 | PREMIUM LEVELLA | PIAWMZ278800B | Combination heat pumps with or without ducts | | 21,000 | $1,050 |
| No | 211991194 | PREMIUM LEVELLA | PIAWMZ368800B | Heat pump without ducts | | 26,400 | $1,320 |
| No | 211991190 | PREMIUM LEVELLA | PIAWMZ278800B | Heat pump without ducts | | 20,000 | $1,000 |
| No | 211991191 | PREMIUM LEVELLA | PIAWMZ278800B | Heat pump with ducts | | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211991189 | PREMIUM LEVELLA | PIAWMZ188800B | Combination heat pumps with or without ducts | | 14,600 | $730 |
| No | 211991187 | PREMIUM LEVELLA | PIAWMZ188800B | Heat pump with ducts | | 14,800 | $740 |
| No | 211991197 | PREMIUM LEVELLA | PIAWMZ488800B | Heat pump without ducts | | 36,000 | $1,800 |
| No | 211991186 | PREMIUM LEVELLA | PIAWMZ188800B | Heat pump without ducts | | 14,400 | $720 |
| No | 209862117 | PREMIUM LEVELLA | PIAW243800B | PIAW243790A | | 16,500 | $825 |
| No | 209862115 | PREMIUM LEVELLA | PIAW183800B | PIAW183790A | | 11,400 | $570 |
| No | 209862114 | PREMIUM LEVELLA | PIAW123800B | PIAW123790A | | 7,000 | $350 |
| No | 209862121 | PREMIUM LEVELLA | PIAW93800B | PIAW93790A | | 6,000 | $300 |
| No | 209862116 | PREMIUM LEVELLA | PIAW123700B | PIAW123690A | | 7,800 | $390 |
| No | 209862119 | PREMIUM LEVELLA | PIAW93700B | PIAW93690A | | 6,300 | $315 |
| No | 207659286 | PREMIUM LEVELLA | PIAW182800B | PIAW182790A | | 11,500 | $575 |
| No | 207659284 | PREMIUM LEVELLA | PIAW92800B | PIAW92790A | | 6,900 | $345 |
| No | 207659290 | PREMIUM LEVELLA | PIAW92700B | PIAW92690A | | 6,800 | $340 |
| No | 207659289 | PREMIUM LEVELLA | PIAW362800B | PIAW362790A | | 24,000 | $1,200 |
| No | 210655381 | Relief Sciences | LANG36OD25-3 | Heat pump without ducts | | 26,400 | $1,320 |
| No | 210655378 | Relief Sciences | LANG27OD25-3 | Heat pump without ducts | | 20,000 | $1,000 |
| No | 210655379 | Relief Sciences | LANG27OD25-3 | Heat pump with ducts | | 22,000 | $1,100 |
| No | 210655376 | Relief Sciences | LANG24OD25-2 | Heat pump with ducts | | 14,800 | $740 |
| No | 210655375 | Relief Sciences | LANG24OD25-2 | Heat pump without ducts | | 14,400 | $720 |
| No | 210655373 | Relief Sciences | LANG09OD25-1 | LANG09ID-25 | | 8,100 | $405 |
| No | 210655374 | Relief Sciences | LANG12OD25-1 | LANG12ID-25 | | 10,000 | $500 |
| No | 10061724 | RHEEM | ROMH45AFXZJ | Heat pump without ducts | | 28,200 | $1,410 |
| No | 202141084 | RHEEM | RP2048BJV | RCF6021SEA | R802VA100521M | 40,000 | $2,000 |
| No | 202141086 | RHEEM | RP2048BJV | RCF6021SEA | R802VA125524M | 40,000 | $2,000 |
| No | 202141076 | RHEEM | RP2036BJV | RCF6021SEA | R97VB100M521U | 37,000 | $1,850 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202141080 | RHEEM | RP2036BJV | RCF6021SEA | R98VB100M521U | 37,000 | $1,850 |
| No | 202141081 | RHEEM | RP2036BJV | RCF6021SEA | R98VB115M524U | 37,000 | $1,850 |
| No | 202141079 | RHEEM | RP2036BJV | RCF6021SEA | R98VB085M521U | 37,000 | $1,850 |
| No | 202141078 | RHEEM | RP2036BJV | RCF6021SEA | R97VB115M524U | 37,000 | $1,850 |
| No | 202141074 | RHEEM | RP2036BJV | RCF6021SEA | R97VB085M521U | 37,000 | $1,850 |
| No | 202141067 | RHEEM | RP2036BJV | RCF6021SEA | R802VA100521M | 36,600 | $1,830 |
| No | 202141070 | RHEEM | RP2036BJV | RCF6021SEA | R96VA0852521M | 37,000 | $1,850 |
| No | 202141068 | RHEEM | RP2036BJV | RCF6021SEA | R802VA100521Z | 36,800 | $1,840 |
| No | 202141072 | RHEEM | RP2036BJV | RCF6021SEA | R96VA1152524M | 37,000 | $1,850 |
| No | 202141062 | RHEEM | RP2024BJV | RCF2421UEA | R98VB060M317U | 22,800 | $1,140 |
| No | 202141071 | RHEEM | RP2036BJV | RCF6021SEA | R96VA1002521M | 37,000 | $1,850 |
| No | 202141066 | RHEEM | RP2036BJV | RCF6021SEA | R802VA075421Z | 37,000 | $1,850 |
| No | 202141069 | RHEEM | RP2036BJV | RCF6021SEA | R802VA125524M | 36,600 | $1,830 |
| No | 202141063 | RHEEM | RP2024BJV | RCF2421UEA | R98VB070M317U | 22,800 | $1,140 |
| No | 202141064 | RHEEM | RP2036BJV | RCF6021SEA | R802VA050317M | 37,400 | $1,870 |
| No | 202141059 | RHEEM | RP2024BJV | RCF2421UEA | R97VB060M317U | 22,800 | $1,140 |
| No | 202141061 | RHEEM | RP2024BJV | RCF2421UEA | R97VB070M317U | 22,800 | $1,140 |
| No | 202141065 | RHEEM | RP2036BJV | RCF6021SEA | R802VA075317M | 36,800 | $1,840 |
| No | 202141057 | RHEEM | RP2024BJV | RCF2421UEA | R96VA0602317M | 22,800 | $1,140 |
| No | 202141056 | RHEEM | RP2024BJV | RCF2421UEA | R802VA100521Z | 22,600 | $1,130 |
| No | 202141055 | RHEEM | RP2024BJV | RCF2421UEA | R802VA100521M | 22,600 | $1,130 |
| No | 202140938 | RHEEM | RP2036BJV | RHMV6021SEAC | | 37,400 | $1,870 |
| No | 202141054 | RHEEM | RP2024BJV | RCF2421UEA | R802VA075421Z | 22,600 | $1,130 |
| No | 202141053 | RHEEM | RP2024BJV | RCF2421UEA | R802VA075317M | 22,600 | $1,130 |
| No | 202141052 | RHEEM | RP2024BJV | RCF2421UEA | R802VA050317M | 22,800 | $1,140 |
| No | 202140939 | RHEEM | RP2048BJV | RHMV6021SEAC | | 41,000 | $2,050 |
| No | 202141048 | RHEEM | RP2024BJV | RHMV2421UEAC | | 23,000 | $1,150 |
| No | 202141075 | RHEEM | RP2036BJV | RCF6021SEA+R97VB100M521K | | 39,000 | $1,950 |
| No | 202141073 | RHEEM | RP2036BJV | RCF6021SEA+R97VB085M521K | | 39,000 | $1,950 |
| No | 202141077 | RHEEM | RP2036BJV | RCF6021SEA+R97VB115M524K | | 39,000 | $1,950 |
| No | 202141060 | RHEEM | RP2024BJV | RCF2421UEA+R97VB070M317K | | 24,200 | $1,210 |
| No | 202141058 | RHEEM | RP2024BJV | RCF2421UEA+R97VB060M317K | | 24,200 | $1,210 |
| No | 10595448 | RHEEM | ROMH45AFXZJ | Heat pump with ducts | | 27,800 | $1,390 |
| No | 10595371 | RHEEM | ROSH09AHHJ | RIWH09AHWJ | | 7,000 | $350 |
| No | 10595373 | RHEEM | ROSH12AHHJ | RIWH12AHWJ | | 9,600 | $480 |
| No | 10595375 | RHEEM | ROSH15AHHJ | RIWH15AHWJ | | 11,200 | $560 |
| No | 10595386 | RHEEM | ROSH12AFFHJ | RIFH12AVFJ | | 10,600 | $530 |
| No | 10595389 | RHEEM | ROSH15AFFHJ | RIFH15AVFJ | | 11,600 | $580 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10595379 | RHEEM | ROSH24AHXHJ | RIWH24AVFJ | | 18,000 | $900 |
| No | 206137898 | RHEEM | RP1736HJVXA | RHMV3621MNAC | | 30,400 | $1,520 |
| No | 10595399 | RHEEM | ROSH09AFCJ | RIDH09AVFJ | | 7,300 | $365 |
| No | 10595383 | RHEEM | ROSH09AFFHJ | RIFH09AVFJ | | 7,500 | $375 |
| No | 206137897 | RHEEM | RP1730HJVXA | RHMV3021SNAC | | 22,600 | $1,130 |
| No | 10595401 | RHEEM | ROSH12AFCJ | RIDH12AVFJ | | 9,500 | $475 |
| No | 206137896 | RHEEM | RP1724HJVXA | RHMV2421MNAC | | 18,700 | $935 |
| No | 10061712 | RHEEM | ROSH12AHWJ | RIWH12AHWJ | | 9,600 | $480 |
| No | 10061714 | RHEEM | ROSH15AHWJ | RIWH15AHWJ | | 11,200 | $560 |
| No | 206137899 | RHEEM | RP1748HJVXA | RHMV4821SNAC | | 39,500 | $1,975 |
| No | 10061716 | RHEEM | ROSH09AHWJ | RIWH09AHWJ | | 7,000 | $350 |
| No | 10595405 | RHEEM | ROSH09AFCJ | RICH09AVFJ | | 7,100 | $355 |
| No | 10595407 | RHEEM | ROSH12AFCJ | RICH12AVFJ | | 10,200 | $510 |
| No | 10595392 | RHEEM | ROSH09AFFJ | RIFH09AVFJ | | 7,500 | $375 |
| No | 10595394 | RHEEM | ROSH12AFFJ | RIFH12AVFJ | | 10,600 | $530 |
| No | 10595396 | RHEEM | ROSH15AFFJ | RIFH15AVFJ | | 11,600 | $580 |
| No | 10061722 | RHEEM | ROSH24AXFWJ | RIWH24AVFJ | | 18,000 | $900 |
| No | 206309261 | RHEEM | ROSH48VGSN | RICH48AXCJ | | 31,400 | $1,570 |
| No | 10061704 | RHEEM | ROSH18ASJ | RIWH18ASJ | | 11,500 | $575 |
| No | 10061702 | RHEEM | ROSH12AFWJ | RIWH12AVFJ | | 9,400 | $470 |
| No | 10061699 | RHEEM | ROSH09AFWJ | RIWH09AVFJ | | 7,600 | $380 |
| No | 207131762 | RHEEM | ROSH12BFWJ | RIWH12BVFJ | | 10,300 | $515 |
| No | 207131760 | RHEEM | ROSH09BFWJ | RIWH09BVFJ | | 7,400 | $370 |
| No | 10595446 | RHEEM | ROMH36AFXZJ | Combination heat pumps with or without ducts | | 21,400 | $1,070 |
| No | 10595450 | RHEEM | ROMH45AFXZJ | Combination heat pumps with or without ducts | | 28,000 | $1,400 |
| No | 212394371 | RUNTRU | E4HL5042A1000A | 4TXCC009DS3 | | 30,000 | $1,500 |
| No | 212394365 | RUNTRU | E4HL5036A1000A | 4TXCB004DS3 | | 19,100 | $955 |
| No | 207642984 | RUNTRU | M4THS2309A11N** | M4MHW2309A1N0** | | 7,300 | $365 |
| No | 205118674 | RUNTRU | M4THS1809A11N** | M4MHW1809A1N0** | | 6,800 | $340 |
| No | 205118691 | RUNTRU | M4TLS1824A11N** | M4MLW1824A1N0** | | 16,000 | $800 |
| No | 210488276 | RUNTRU | M4THM1930A14N** | Heat pump without ducts | | 27,200 | $1,360 |
| No | 210488275 | RUNTRU | M4THM1924A13N** | Heat pump without ducts | | 23,600 | $1,180 |
| No | 210488274 | RUNTRU | M4THM1918A12N** | Heat pump without ducts | | 14,700 | $735 |
| No | 207642986 | RUNTRU | M4THS2312A11N** | M4MHW2312A1N0** | | 7,700 | $385 |
| No | 208120593 | RUNTRU | M4THS2318A11N** | M4MHW2318A1N0** | N/A | 11,400 | $570 |
| No | 208120591 | RUNTRU | M4THS2324A11N** | M4MHW2324A1N0** | N/A | 15,500 | $775 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205118677 | RUNTRU | M4THS1812A11N** | M4MHW1812A1N0** | | 7,100 | $355 |
| No | 205118697 | RUNTRU | M4THS1818A11N** | M4MHW1818A1N0** | | 12,400 | $620 |
| No | 205118682 | RUNTRU | M4TLS1809A11N** | M4MLW1809A1N0** | | 5,800 | $290 |
| No | 207141969 | RUUD | ROSH12BFWJ | UIWH12BVFJ | | 10,300 | $515 |
| No | 206221489 | RUUD | ROSH09AFWJ | UIWH09AVFJ | | 7,600 | $380 |
| No | 206221490 | RUUD | ROSH12AFWJ | UIWH12AVFJ | | 9,400 | $470 |
| No | 206221511 | RUUD | ROSH09AFFJ | RIFH09AVFJ | | 7,500 | $375 |
| No | 206221513 | RUUD | ROSH15AFFJ | RIFH15AVFJ | | 11,600 | $580 |
| No | 206221518 | RUUD | ROSH12AFCJ | RICH12AVFJ | | 10,200 | $510 |
| No | 206221517 | RUUD | ROSH09AFCJ | RICH09AVFJ | | 7,100 | $355 |
| No | 206221497 | RUUD | ROSH09AHWJ | UIWH09AHWJ | | 7,000 | $350 |
| No | 206221495 | RUUD | ROSH12AHWJ | UIWH12AHWJ | | 9,600 | $480 |
| No | 206221496 | RUUD | ROSH15AHWJ | UIWH15AHWJ | | 11,200 | $560 |
| No | 206221515 | RUUD | ROSH12AFCJ | RIDH12AVFJ | | 9,500 | $475 |
| No | 206221514 | RUUD | ROSH09AFCJ | RIDH09AVFJ | | 7,300 | $365 |
| No | 206221508 | RUUD | ROSH09AFFHJ | RIFH09AVFJ | | 7,500 | $375 |
| No | 206221510 | RUUD | ROSH15AFFHJ | RIFH15AVFJ | | 11,600 | $580 |
| No | 206221509 | RUUD | ROSH12AFFHJ | RIFH12AVFJ | | 10,600 | $530 |
| No | 206221504 | RUUD | ROSH15AHHJ | UIWH15AHWJ | | 11,200 | $560 |
| No | 206221503 | RUUD | ROSH12AHHJ | UIWH12AHWJ | | 9,600 | $480 |
| No | 206221502 | RUUD | ROSH09AHHJ | UIWH09AHWJ | | 7,000 | $350 |
| No | 206221501 | RUUD | ROMH45AFXZJ | Heat pump without ducts | | 28,200 | $1,410 |
| No | 202141105 | RUUD | UP2024BJV | RCF2421UEA | U802VA075317M | 22,600 | $1,130 |
| No | 202141107 | RUUD | UP2024BJV | RCF2421UE | U802VA100521M | 22,600 | $1,130 |
| No | 202141108 | RUUD | UP2024BJV | RCF2421UEA | U802VA100521Z | 22,600 | $1,130 |
| No | 202141106 | RUUD | UP2024BJV | RCF2421UEA | U802VA075421Z | 22,600 | $1,130 |
| No | 202141049 | RUUD | UP2036BJV | RHMV6021SEAC | | 37,400 | $1,870 |
| No | 202141050 | RUUD | UP2048BJV | RHMV6021SEAC | | 41,000 | $2,050 |
| No | 202141104 | RUUD | UP2024BJV | RCF2421UEA | U802VA050317M | 22,800 | $1,140 |
| No | 202141158 | RUUD | UP2024BJV | RHMV2421UEAC | | 23,000 | $1,150 |
| No | 202141136 | RUUD | UP2048BJV | RCF6021SEA | U802VA100521M | 40,000 | $2,000 |
| No | 202141132 | RUUD | UP2036BJV | RCF6021SEA | U98VB100M521U | 37,000 | $1,850 |
| No | 202141133 | RUUD | UP2036BJV | RCF6021SEA | U98VB115M524U | 37,000 | $1,850 |
| No | 202141138 | RUUD | UP2048BJV | RCF6021SEA | U802VA125524M | 40,000 | $2,000 |
| No | 202141130 | RUUD | UP2036BJV | RCF6021SEA | U97VB115M524U | 37,000 | $1,850 |
| No | 202141131 | RUUD | UP2036BJV | RCF6021SEA | U98VB085M521U | 37,000 | $1,850 |
| No | 202141123 | RUUD | UP2036BJV | RCF6021SEA | U96VA1002521M | 37,000 | $1,850 |
| No | 202141126 | RUUD | UP2036BJV | RCF6021SEA | U97VB085M521U | 37,000 | $1,850 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202141119 | RUUD | UP2036BJV | RCF6021SEA | U802VA100521M | 36,600 | $1,830 |
| No | 202141128 | RUUD | UP2036BJV | RCF6021SEA | U97VB100M521U | 37,000 | $1,850 |
| No | 202141124 | RUUD | UP2036BJV | RCF6021SEA | U96VA1152524M | 37,000 | $1,850 |
| No | 202141120 | RUUD | UP2036BJV | RCF6021SEA | U802VA100521Z | 36,800 | $1,840 |
| No | 202141115 | RUUD | UP2024BJV | RCF2421UEA | U98VB070M317U | 22,800 | $1,140 |
| No | 202141121 | RUUD | UP2036BJV | RCF6021SEA | U802VA125524M | 36,600 | $1,830 |
| No | 202141122 | RUUD | UP2036BJV | RCF6021SEA | U96VA0852521M | 37,000 | $1,850 |
| No | 202141116 | RUUD | UP2036BJV | RCF6021SEA | U802VA050317M | 37,400 | $1,870 |
| No | 202141117 | RUUD | UP2036BJV | RCF6021SEA | U802VA075317M | 36,800 | $1,840 |
| No | 202141114 | RUUD | UP2024BJV | RCF2421UEA | U98VB060M317U | 22,800 | $1,140 |
| No | 202141118 | RUUD | UP2036BJV | RCF6021SEA | U802VA075421Z | 37,000 | $1,850 |
| No | 202141129 | RUUD | UP2036BJV | RCF6021SEA+U97VB115M524K | | 39,000 | $1,950 |
| No | 202141113 | RUUD | UP2024BJV | RCF2421UEA | U97VB070M317U | 22,800 | $1,140 |
| No | 202141111 | RUUD | UP2024BJV | RCF2421UEA | U97VB060M317U | 22,800 | $1,140 |
| No | 202141109 | RUUD | UP2024BJV | RCF2421UEA | U96VA0602317M | 22,800 | $1,140 |
| No | 202141127 | RUUD | UP2036BJV | RCF6021SEA+U97VB100M521K | | 39,000 | $1,950 |
| No | 202141125 | RUUD | UP2036BJV | RCF6021SEA+U97VB085M521K | | 39,000 | $1,950 |
| No | 202141110 | RUUD | UP2024BJV | RCF2421UEA+U97VB060M317K | | 24,200 | $1,210 |
| No | 202141112 | RUUD | UP2024BJV | RCF2421UEA+U97VB070M317K | | 24,200 | $1,210 |
| No | 206221535 | RUUD | ROMH45AFXZJ | Heat pump with ducts | | 27,800 | $1,390 |
| No | 206221506 | RUUD | ROSH24AHXHJ | UIWH24AVFJ | | 18,000 | $900 |
| No | 206221512 | RUUD | ROSH12AFFJ | RIFH12AVFJ | | 10,600 | $530 |
| No | 206221500 | RUUD | ROSH24AXFWJ | UIWH24AVFJ | | 18,000 | $900 |
| No | 206309260 | RUUD | ROSH48VGSN | RICH48AXCJ | | 31,400 | $1,570 |
| No | 206221491 | RUUD | ROSH18ASJ | UIWH18ASJ | | 11,500 | $575 |
| No | 207141968 | RUUD | ROSH09BFWJ | UIWH09BVFJ | | 7,400 | $370 |
| No | 206221534 | RUUD | ROMH36AFXZJ | Combination heat pumps with or without ducts | | 21,400 | $1,070 |
| No | 206221536 | RUUD | ROMH45AFXZJ | Combination heat pumps with or without ducts | | 28,000 | $1,400 |
| No | 206143962 | RUUD | RP1736HJVXA | RHMV3621MNAC | | 30,400 | $1,520 |
| No | 206143960 | RUUD | RP1724HJVXA | RHMV2421MNAC | | 18,700 | $935 |
| No | 206143963 | RUUD | RP1748HJVXA | RHMV4821SNAC | | 39,500 | $1,975 |
| No | 206143961 | RUUD | RP1730HJVXA | RHMV3021SNAC | | 22,600 | $1,130 |
| No | 207465463 | SAMSUNG | AC036BXADCH | AC036BNTDCH | | 30,400 | $1,520 |
| No | 207465469 | SAMSUNG | AC048BXADCH | AC048BNHDCH | | 43,000 | $2,150 |
| No | 207465466 | SAMSUNG | AC042BXADCH | AC042BNHDCH | | 43,500 | $2,175 |
| No | 207465462 | SAMSUNG | AC036BXADCH | AC036BNHDCH | | 35,400 | $1,770 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207465441 | SAMSUNG | AC012BXADCH | AC012BNHDCH | | 12,100 | $605 |
| No | 207465435 | SAMSUNG | AC030BXADCH | AC030BN4DCH | | 33,200 | $1,660 |
| No | 207465468 | SAMSUNG | AC048BXADCH | AC048BN6DCH | | 42,000 | $2,100 |
| No | 207465465 | SAMSUNG | AC042BXADCH | AC042BN6DCH | | 42,000 | $2,100 |
| No | 207465457 | SAMSUNG | AC030BXADCH | AC030BN6DCH | | 31,200 | $1,560 |
| No | 207465443 | SAMSUNG | AC012BXADCH | AC012BNLDCH | | 13,500 | $675 |
| No | 207465440 | SAMSUNG | AC009BXADCH | AC009BNLDCH | | 12,400 | $620 |
| No | 207465444 | SAMSUNG | AC012BXADCH | AC012BNNDCH | | 11,500 | $575 |
| No | 207462387 | SAMSUNG | AC009BXADCH | AC009BNNDCH | | 10,000 | $500 |
| No | 207698070 | SAMSUNG | AC030BXSCCH | AC030BNHDCH | | 33,400 | $1,670 |
| No | 207465455 | SAMSUNG | AC024BXADCH | AC024BNHDCH | | 33,200 | $1,660 |
| No | 207465438 | SAMSUNG | AC009BXADCH | AC009BNHDCH | | 11,300 | $565 |
| No | 207465446 | SAMSUNG | AC018BXADCH | AC018BN6DCH | | 23,000 | $1,150 |
| No | 207465454 | SAMSUNG | AC024BXADCH | AC024BNADCH | | 26,000 | $1,300 |
| No | 207465453 | SAMSUNG | AC024BXADCH | AC024BN6DCH | | 29,200 | $1,460 |
| No | 207465470 | SAMSUNG | AC048BXADCH | AC048BNZDCH | | 43,000 | $2,150 |
| No | 207465467 | SAMSUNG | AC042BXADCH | AC042BNZDCH | | 41,500 | $2,075 |
| No | 207465464 | SAMSUNG | AC036BXADCH | AC036BNZDCH | | 34,800 | $1,740 |
| No | 207465456 | SAMSUNG | AC024BXADCH | AC024BNZDCH | | 25,800 | $1,290 |
| No | 207465452 | SAMSUNG | AC018BXADCH | AC018BNZDCH | | 18,700 | $935 |
| No | 207465451 | SAMSUNG | AC018BXADCH | AC018BNNDCH | | 12,900 | $645 |
| No | 207465447 | SAMSUNG | AC018BXADCH | AC018BNADCH | | 13,100 | $655 |
| No | 205132636 | SAMSUNG | AR18TSFABWKX | AR18TSFABWKN | | 11,500 | $575 |
| No | 205132629 | SAMSUNG | AR12TSFABWKX | AR12TSFABWKN | | 7,500 | $375 |
| No | 205132630 | SAMSUNG | AR09TSFABWKX | AR09TSFABWKN | | 6,700 | $335 |
| No | 207465450 | SAMSUNG | AC018BXADCH | AC018BNLDCH | | 12,800 | $640 |
| No | 205132635 | SAMSUNG | AR18TSFACWKX | AR18TSFABWKN | | 12,000 | $600 |
| No | 207698063 | SAMSUNG | AR15BSFACWKXCV | AR15BSFACWKNCV | | 11,500 | $575 |
| No | 205132627 | SAMSUNG | AR12TSFACWKX | AR12TSFABWKN | | 7,500 | $375 |
| No | 205132628 | SAMSUNG | AR09TSFACWKX | AR09TSFABWKN | | 6,700 | $335 |
| No | 207698064 | SAMSUNG | AR36BSHUMGMX | AR36BSHUMGMN | | 25,800 | $1,290 |
| No | 207349917 | SAMSUNG | AJ020BXS3CH | Heat pump without ducts | | 10,500 | $525 |
| No | 207349374 | SAMSUNG | AJ048BXJ5CH | Heat pump without ducts | | 28,400 | $1,420 |
| No | 207350090 | SAMSUNG | AJ036BXJ4CH | Combination heat pumps with or without ducts | | 21,200 | $1,060 |
| No | 207350089 | SAMSUNG | AJ024BXJ3CH | Combination heat pumps with or without ducts | | 14,000 | $700 |
| No | 207349915 | SAMSUNG | AJ024BXJ3CH | Heat pump without ducts | | 13,500 | $675 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207350087 | SAMSUNG | AJ020BXJ2CH | Combination heat pumps with or without ducts | | 12,100 | $605 |
| No | 207349914 | SAMSUNG | AJ020BXJ2CH | Heat pump without ducts | | 11,500 | $575 |
| No | 207349916 | SAMSUNG | AJ036BXJ4CH | Heat pump without ducts | | 21,000 | $1,050 |
| No | 207349353 | SAMSUNG | AR09BSFCMWKX | AR09BSFCMWKN | | 6,700 | $335 |
| No | 207349354 | SAMSUNG | AR12BSFCMWKX | AR12BSFCMWKN | | 7,300 | $365 |
| No | 207349355 | SAMSUNG | AR18BSFCMWKX | AR18BSFCMWKN | | 13,000 | $650 |
| No | 207350094 | SAMSUNG | AJ024BXS4CH | Combination heat pumps with or without ducts | | 14,800 | $740 |
| No | 207350092 | SAMSUNG | AJ020BXS3CH | Combination heat pumps with or without ducts | | 11,700 | $585 |
| No | 207350096 | SAMSUNG | AJ030BXS4CH | Combination heat pumps with or without ducts | | 15,600 | $780 |
| No | 205132633 | SAMSUNG | AR24TSFACWKX | AR24TSFABWKN | | 16,000 | $800 |
| No | 205132634 | SAMSUNG | AR24TSFABWKX | AR24TSFABWKN | | 16,000 | $800 |
| No | 208650697 | SEA BREEZE | 24H421ZOMI | 24H421ZIMI | | 16,500 | $825 |
| No | 208650696 | SEA BREEZE | 18H421ZOMI | 18H421ZIMI | | 11,400 | $570 |
| No | 208650695 | SEA BREEZE | 12H421ZOMI | 12H421ZIMI | | 7,000 | $350 |
| No | 208650694 | SEA BREEZE | 9H421ZOMI | 9H421ZIMI | | 6,000 | $300 |
| No | 208650693 | SEA BREEZE | 12H421YOMI | 12H421YIMI | | 7,800 | $390 |
| No | 208650692 | SEA BREEZE | 9H421YOMI | 9H421YIMI | | 6,300 | $315 |
| No | 208128300 | SEA BREEZE+ | SZ24H424ZMO | AH24H424ZMI | | 17,000 | $850 |
| No | 208128288 | SEA BREEZE+ | MZ36H424ZMO | Heat pump without ducts | | 26,400 | $1,320 |
| No | 208128291 | SEA BREEZE+ | MZ48H424ZMO | Heat pump without ducts | | 36,000 | $1,800 |
| No | 208128283 | SEA BREEZE+ | MZ18H424ZMO | Heat pump with ducts | | 14,800 | $740 |
| No | 208128282 | SEA BREEZE+ | MZ18H424ZMO | Heat pump without ducts | | 14,400 | $720 |
| No | 210410113 | SEA BREEZE+ | SZ12H424ZMO | SCA12H424ZMI | | 7,700 | $385 |
| No | 210404149 | SEA BREEZE+ | SZ9H424ZMO | SCA9H424ZMI | | 8,000 | $400 |
| No | 210410114 | SEA BREEZE+ | SZ18H424ZMO | SCA18H424ZMI | | 12,200 | $610 |
| No | 210410116 | SEA BREEZE+ | SZ18H424ZMO | C18H424ZMI | | 13,400 | $670 |
| No | 210410115 | SEA BREEZE+ | SZ12H424ZMO | C12H424ZMI | | 9,200 | $460 |
| No | 208128278 | SEA BREEZE+ | SZ18H424ZMO | D18H424ZMI | | 12,600 | $630 |
| No | 208128272 | SEA BREEZE+ | SZ18H424ZMO | CA18H424ZMI | | 12,000 | $600 |
| No | 208128280 | SEA BREEZE+ | SZ18H424ZMO | FC18H424ZMI | | 12,800 | $640 |
| No | 208128264 | SEA BREEZE+ | SZ18H424ZMO | WM18H424ZMI | | 14,100 | $705 |
| No | 208128273 | SEA BREEZE+ | SZ24H424ZMO | CA24H424ZMI | | 19,000 | $950 |
| No | 208674954 | SEA BREEZE+ | SZ9H424ZMO | WM9H424ZMI | | 8,100 | $405 |
| No | 208128266 | SEA BREEZE+ | SZ9H424ZMO | WM6H424ZMI | | 7,500 | $375 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208128265 | SEA BREEZE+ | SZ24H424ZMO | WM24H424ZMI | | 17,400 | $870 |
| No | 208128263 | SEA BREEZE+ | SZ12H424ZMO | WM12H424ZMI | | 10,000 | $500 |
| No | 208816890 | SEA BREEZE+ | HSZ18H424ZMO | WM18H424ZMI | | 11,100 | $555 |
| No | 208128267 | SEA BREEZE+ | HSZ12H424ZMO | WM12H424ZMI | | 10,300 | $515 |
| No | 208816889 | SEA BREEZE+ | HSZ9H424ZMO | WM9H424ZMI | | 9,300 | $465 |
| No | 208128279 | SEA BREEZE+ | SZ24H424ZMO | D24H424ZMI | | 20,000 | $1,000 |
| No | 208128269 | SEA BREEZE+ | HSZ12H424ZMO | D12H424ZMI | | 10,600 | $530 |
| No | 208128268 | SEA BREEZE+ | HSZ12H424ZMO | CA12H424ZMI | | 9,900 | $495 |
| No | 208128277 | SEA BREEZE+ | SZ12H424ZMO | D12H424ZMI | | 9,300 | $465 |
| No | 208128276 | SEA BREEZE+ | SZ9H424ZMO | D9H424ZMI | | 7,700 | $385 |
| No | 208128281 | SEA BREEZE+ | SZ24H424ZMO | FC24H424ZMI | | 16,000 | $800 |
| No | 208128271 | SEA BREEZE+ | SZ12H424ZMO | CA12H424ZMI | | 8,900 | $445 |
| No | 208128270 | SEA BREEZE+ | SZ9H424ZMO | CA9H424ZMI | | 7,500 | $375 |
| No | 208128293 | SEA BREEZE+ | MZ48H424ZMO | Combination heat pumps with or without ducts | | 30,600 | $1,530 |
| No | 208128292 | SEA BREEZE+ | MZ48H424ZMO | Heat pump with ducts | | 30,400 | $1,520 |
| No | 208128287 | SEA BREEZE+ | MZ27H424ZMO | Combination heat pumps with or without ducts | | 15,900 | $795 |
| No | 208128284 | SEA BREEZE+ | MZ18H424ZMO | Combination heat pumps with or without ducts | | 11,800 | $590 |
| No | 208128285 | SEA BREEZE+ | MZ27H424ZMO | Heat pump without ducts | | 13,764 | $688 |
| No | 208128286 | SEA BREEZE+ | MZ27H424ZMO | Heat pump with ducts | | 18,500 | $925 |
| No | 208128296 | SEA BREEZE+ | HMZ28H424ZMO | Combination heat pumps with or without ducts | | 16,900 | $845 |
| No | 208816897 | SEA BREEZE+ | HMZ24H424ZMO | Combination heat pumps with or without ducts | | 16,500 | $825 |
| No | 210426579 | SENVILLE | SENDC-36HF-OM | SENDC-36HF-IM | | 30,400 | $1,520 |
| No | 207641338 | SENVILLE | SENA/48HF/MOQ | Heat pump without ducts | | 34,000 | $1,700 |
| No | 207641335 | SENVILLE | SENA/36HF/MOQ | Heat pump without ducts | | 26,800 | $1,340 |
| No | 207641333 | SENVILLE | SENA/30HF/MOQ | Heat pump with ducts | | 22,000 | $1,100 |
| No | 207641330 | SENVILLE | SENA/18HF/MOQ | Heat pump with ducts | | 14,800 | $740 |
| No | 207641332 | SENVILLE | SENA/30HF/MOQ | Heat pump without ducts | | 21,000 | $1,050 |
| No | 207641329 | SENVILLE | SENA/18HF/MOQ | Heat pump without ducts | | 14,300 | $715 |
| No | 210372990 | SENVILLE | SENA/12HF/OQ | SENA-12HF-IFU | | 10,200 | $510 |
| No | 207613967 | SENVILLE | SENL/18CD/OY | SENL/18CD/IY | | 11,500 | $575 |
| No | 207613965 | SENVILLE | SENL/09CD220/OY | SENL/09CD220/IY | | 6,900 | $345 |
| No | 207613963 | SENVILLE | SENL/09CD/OY | SENL/09CD/IY | | 6,800 | $340 |
| No | 207571417 | SENVILLE | SENL/36CD/OY | SENL/36CD/IY | | 24,000 | $1,200 |
| No | 207657626 | SENVILLE | SENL/36CD/OY | SENL/36CD/IY | | 24,000 | $1,200 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207641343 | SENVILLE | SENA/18HF/OQ | SENA/18HF/ICZ | | 15,600 | $780 |
| No | 207641350 | SENVILLE | SENA/18HF/OQ | SENA/18HF/IF | | 12,000 | $600 |
| No | 207641349 | SENVILLE | SENA/12HF/OQ | SENA/12HF/IFQ | | 9,600 | $480 |
| No | 207641346 | SENVILLE | SENA/12HF/OQ | SENA/12HF/ID | | 10,600 | $530 |
| No | 207641342 | SENVILLE | SENA/12HF/OQ | SENA/12HF/ICZ | | 9,900 | $495 |
| No | 207641345 | SENVILLE | SENA/09HF/OQ | SENA/09HF/ID | | 10,100 | $505 |
| No | 207641341 | SENVILLE | SENA/09HF/OQ | SENA/09HF/ICZ | | 9,000 | $450 |
| No | 207571419 | SENVILLE | SENA/12HF/OQ | SENA/12HF/IQ | | 10,000 | $500 |
| No | 207657628 | SENVILLE | SENA/12HF/OQ | SENA/12HF/IQ | | 10,000 | $500 |
| No | 207657627 | SENVILLE | SENA/09HF/OQ | SENA/09HF/IQ | | 9,500 | $475 |
| No | 207571418 | SENVILLE | SENA/09HF/OQ | SENA/09HF/IQ | | 9,500 | $475 |
| No | 202606685 | SENVILLE | SENL/18CD/OX | SENL/18CD/IX | | 11,000 | $550 |
| No | 8977720 | SENVILLE | SENA/48HF/MOZ | Heat pump without ducts | | 29,600 | $1,480 |
| No | 202606683 | SENVILLE | SENL/09CD/OX | SENL/09CD/IX | | 6,000 | $300 |
| No | 8858355 | SENVILLE | SENA/30HF/MOZ | Heat pump without ducts | | 17,200 | $860 |
| No | 8858354 | SENVILLE | SENA/18HF/MOZ | Heat pump without ducts | | 12,000 | $600 |
| No | 8797150 | SENVILLE | SENA/12HF/OZ | SENA/12HF/IZ | | 7,800 | $390 |
| No | 8858356 | SENVILLE | SENA/36HF/MOZ | Heat pump without ducts | | 24,600 | $1,230 |
| No | 8797149 | SENVILLE | SENA/09HF/OZ | SENA/09HF/IZ | | 6,900 | $345 |
| No | 207641339 | SENVILLE | SENA/48HF/MOQ | Heat pump with ducts | | 30,400 | $1,520 |
| No | 207641340 | SENVILLE | SENA/48HF/MOQ | Combination heat pumps with or without ducts | | 30,000 | $1,500 |
| No | 207641334 | SENVILLE | SENA/30HF/MOQ | Combination heat pumps with or without ducts | | 16,000 | $800 |
| No | 207641331 | SENVILLE | SENA/18HF/MOQ | Combination heat pumps with or without ducts | | 11,400 | $570 |
| No | 205921390 | SENVILLE | SENA/09HF/OZ | SENA/09HF/ID | | 7,200 | $360 |
| No | 205921391 | SENVILLE | SENA/12HF/OZ | SENA/12HF/ID | | 8,500 | $425 |
| No | 210301933 | SHARP | AE-X18ZU | AY-XPC18ZU | | 13,800 | $690 |
| No | 209423517 | SHARP | AE-X15ZU | AY-XPC15ZU | | 11,000 | $550 |
| No | 209424784 | SHARP | AE-X18ZHU | AY-XP18ZHU | | 14,000 | $700 |
| No | 210363336 | SHARP | AE-X24ZU | AY-XPC24ZU | | 16,000 | $800 |
| No | 209423516 | SHARP | AE-X12ZHU | AY-XP12ZHU | | 9,500 | $475 |
| No | 209270207 | SHARP | AE-X12ZU | AY-XPC12ZU | | 9,000 | $450 |
| No | 8950554 | SHARP | AE-X2M20TU | Heat pump without ducts | | 14,000 | $700 |
| No | 8796425 | SHARP | AE-X18THU | AY-XP18THU | | 13,600 | $680 |
| No | 8674934 | SHARP | AE-X18TU | AY-XPC18TU | | 12,000 | $600 |
| No | 8693471 | SHARP | AE-X24TU | AY-XP24TU | | 14,000 | $700 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 8796398 | SHARP | AE-X12THU | AY-XP12THU | | 8,500 | $425 |
| No | 8740799 | SHARP | AE-X12TU | AY-XPC12TU | | 8,400 | $420 |
| No | 208447954 | SLIMAIR | SHC4Z36VC2AG | Heat pump without ducts | | 26,400 | $1,320 |
| No | 208447957 | SLIMAIR | SHC5Z48VC2AG | Heat pump without ducts | | 36,000 | $1,800 |
| No | 208447951 | SLIMAIR | SHC3Z27VC2AG | Heat pump without ducts | | 20,000 | $1,000 |
| No | 208447952 | SLIMAIR | SHC3Z27VC2AG | Heat pump with ducts | | 22,000 | $1,100 |
| No | 208447949 | SLIMAIR | SHC2Z18VC2AG | Heat pump with ducts | | 14,800 | $740 |
| No | 208447948 | SLIMAIR | SHC2Z18VC2AG | Heat pump without ducts | | 14,400 | $720 |
| No | 210857477 | SLIMAIR | SHC18VE2AG | SHLZ18VC2AG | | 12,000 | $600 |
| No | 210857478 | SLIMAIR | SHC24VE2AG | SHLZ24VC2AG | | 19,000 | $950 |
| No | 210857476 | SLIMAIR | SHC12VE2AG | SHLZ12VC2AG | | 8,900 | $445 |
| No | 210857475 | SLIMAIR | SHC09VE2AG | SHLZ09VC2AG | | 7,500 | $375 |
| No | 208447938 | SLIMAIR | SHC18VE2AG | SHM18VE2AG | | 14,100 | $705 |
| No | 208447946 | SLIMAIR | SHC18VE2AG | SHMZ18VC2AG | | 14,100 | $705 |
| No | 208447944 | SLIMAIR | SHC09VE2AG | SHMZ09VC2AG | | 8,100 | $405 |
| No | 208447936 | SLIMAIR | SHC09VE2AG | SHM09VE2AG | | 8,100 | $405 |
| No | 208447934 | SLIMAIR | SHC09VE1AG | SHM09VE1AG | | 5,900 | $295 |
| No | 208447933 | SLIMAIR | SHC36VB2AB | SHM36VB2AB | | 24,000 | $1,200 |
| No | 208447931 | SLIMAIR | SHC24VC2AG | SHM24VC2AG | | 16,500 | $825 |
| No | 208447930 | SLIMAIR | SHC18VC2AG | SHM18VC2AG | | 11,400 | $570 |
| No | 208447929 | SLIMAIR | SHC12VC2AG | SHM12VC2AG | | 7,000 | $350 |
| No | 208447928 | SLIMAIR | SHC09VC2AG | SHM09VC2AG | | 6,000 | $300 |
| No | 208447927 | SLIMAIR | SHC12VC1AG | SHM12VC1AG | | 7,800 | $390 |
| No | 208447926 | SLIMAIR | SHC09VC1AG | SHM09VC1AG | | 6,300 | $315 |
| No | 208447947 | SLIMAIR | SHC24VE2AG | SHMZ24VC2AG | | 17,400 | $870 |
| No | 208447939 | SLIMAIR | SHC24VE2AG | SHM24VE2AG | | 17,400 | $870 |
| No | 208447945 | SLIMAIR | SHC12VE2AG | SHMZ12VC2AG | | 10,000 | $500 |
| No | 208447937 | SLIMAIR | SHC12VE2AG | SHM12VE2AG | | 10,000 | $500 |
| No | 208447935 | SLIMAIR | SHC12VE1AG | SHM12VE1AG | | 8,900 | $445 |
| No | 208447942 | SLIMAIR | SHCD18VC2AG | SHMZ18VC2AG | | 11,100 | $555 |
| No | 208447941 | SLIMAIR | SHCD12VC2AG | SHMZ12VC2AG | | 10,300 | $515 |
| No | 208447940 | SLIMAIR | SHCD09VC2AG | SHMZ09VC2AG | | 9,300 | $465 |
| No | 208447959 | SLIMAIR | SHC5Z48VC2AG | Combination heat pumps with or without ducts | | 31,200 | $1,560 |
| No | 208447958 | SLIMAIR | SHC5Z48VC2AG | Heat pump with ducts | | 30,400 | $1,520 |
| No | 208447953 | SLIMAIR | SHC3Z27VC2AG | Combination heat pumps with or without ducts | | 16,100 | $805 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208447950 | SLIMAIR | SHC2Z18VC2AG | Combination heat pumps with or without ducts | | 11,800 | $590 |
| No | 209852126 | SMART COMFORT | DLCURAH60AAK | DLFUAAH60XAK | | 37,000 | $1,850 |
| No | 209852123 | SMART COMFORT | DLCURAH48AAK | DLFUAAH48XAK | | 37,000 | $1,850 |
| No | 209852130 | SMART COMFORT | DLCURAH36AAK | DLFUAAH36XAK | | 20,400 | $1,020 |
| No | 209852132 | SMART COMFORT | DLCURAH30ABK | DLFUAAH30XAK | | 21,000 | $1,050 |
| No | 209852129 | SMART COMFORT | DLCURAH30AAK | DLFUAAH30XAK | | 20,000 | $1,000 |
| No | 209852122 | SMART COMFORT | DLCURAH24AAK | DLFUAAH24XAK | | 21,000 | $1,050 |
| No | 209852128 | SMART COMFORT | DLCURAH18AAK | DLFUAAH18XAK | | 12,000 | $600 |
| No | 207643173 | SMART COMFORT | DLCMRBH48EAK | Heat pump without ducts | | 31,000 | $1,550 |
| No | 202119270 | SMART COMFORT | DLCMRAH27CAK | Heat pump without ducts | | 17,800 | $890 |
| No | 207199362 | SMART COMFORT | DLCSRBH30AAK | FEM4X30**BL | | 19,100 | $955 |
| No | 207203078 | SMART COMFORT | DLCSRBH18AAK | FEM4P18**AL | | 14,700 | $735 |
| No | 207203079 | SMART COMFORT | DLCSRBH18AAK | FEM4X18**BL | | 14,700 | $735 |
| No | 207199361 | SMART COMFORT | DLCSRBH30AAK | FEM4P30**AL | | 19,100 | $955 |
| No | 207203080 | SMART COMFORT | DLCSRBH18AAK | EA*4X19L17A* | *80ES(N,L)0451412A* | 13,800 | $690 |
| No | 207203082 | SMART COMFORT | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207203081 | SMART COMFORT | DLCSRBH18AAK | EA*4X24L14A* | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207203083 | SMART COMFORT | DLCSRBH18AAK | EA*4X25L17A* | *80ES(N,L)0451412A* | 13,800 | $690 |
| No | 207203084 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X18L14** | *80ES(N,L)0451412A* | 14,700 | $735 |
| No | 207203085 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X24L14** | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207203086 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207203087 | SMART COMFORT | DLCSRBH18AAK | EA*4X19L17A* | *80ES(N,L)0451712A* | 13,900 | $695 |
| No | 207203088 | SMART COMFORT | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0451712A* | 14,600 | $730 |
| No | 207203089 | SMART COMFORT | DLCSRBH18AAK | EA*4X25L17A* | *80ES(N,L)0451712A* | 13,800 | $690 |
| No | 207203090 | SMART COMFORT | DLCSRBH18AAK | EA*4X19L17A* | *80ES(N,L)0701412A* | 13,900 | $695 |
| No | 207203091 | SMART COMFORT | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0701412A* | 14,600 | $730 |
| No | 207203093 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X18L14** | *80ES(N,L)0701412A* | 14,700 | $735 |
| No | 207203092 | SMART COMFORT | DLCSRBH18AAK | EA*4X25L17A* | *80ES(N,L)0701412A* | 13,800 | $690 |
| No | 207203094 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X24L14** | *80ES(N,L)0701412A* | 14,600 | $730 |
| No | 207203095 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ES(N,L)0701412A* | 14,600 | $730 |
| No | 207203096 | SMART COMFORT | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0701712A* | 14,700 | $735 |
| No | 207203097 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ES(N,L)0701712A* | 14,700 | $735 |
| No | 207203099 | SMART COMFORT | DLCSRBH18AAK | EA*4X24L17A* | *80ESU0401712A* | 14,500 | $725 |
| No | 207203100 | SMART COMFORT | DLCSRBH18AAK | EA*4X25L17A* | *80ESU0401712A* | 13,600 | $680 |
| No | 207203098 | SMART COMFORT | DLCSRBH18AAK | EA*4X19L17A* | *80ESU0401712A* | 13,700 | $685 |
| No | 207203101 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ESU0401712A* | 14,500 | $725 |
| No | 207203105 | SMART COMFORT | DLCSRBH18AAK | EA*4X25L17A* | *92ESN0401410A* | 13,700 | $685 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207203102 | SMART COMFORT | DLCSRBH18AAK | EA*4X19L17A* | *92ESN0401410A* | 13,800 | $690 |
| No | 207203108 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0401410A* | 14,500 | $725 |
| No | 207203109 | SMART COMFORT | DLCSRBH18AAK | EA*4X19L17A* | *92ESN0401712A* | 13,900 | $695 |
| No | 207203103 | SMART COMFORT | DLCSRBH18AAK | EA*4X24L14A* | *92ESN0401410A* | 14,500 | $725 |
| No | 207203104 | SMART COMFORT | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0401410A* | 14,500 | $725 |
| No | 207203106 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X18L14** | *92ESN0401410A* | 14,600 | $730 |
| No | 207203107 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X24L14** | *92ESN0401410A* | 14,500 | $725 |
| No | 207203110 | SMART COMFORT | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0401712A* | 14,600 | $730 |
| No | 207203112 | SMART COMFORT | DLCSRBH18AAK | EA*4X19L17A* | *92ESN0601412A* | 14,000 | $700 |
| No | 207203111 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0401712A* | 14,600 | $730 |
| No | 207203113 | SMART COMFORT | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0601412A* | 14,600 | $730 |
| No | 207203115 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X18L14** | *92ESN0601412A* | 14,700 | $735 |
| No | 207203114 | SMART COMFORT | DLCSRBH18AAK | EA*4X25L17A* | *92ESN0601412A* | 13,800 | $690 |
| No | 207203116 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X24L14** | *92ESN0601412A* | 14,600 | $730 |
| No | 207203117 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0601412A* | 14,600 | $730 |
| No | 207203118 | SMART COMFORT | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0801716A* | 14,700 | $735 |
| No | 207203119 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0801716A* | 14,700 | $735 |
| No | 207203121 | SMART COMFORT | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0261410A* | 14,700 | $735 |
| No | 207203120 | SMART COMFORT | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0261410A* | 14,100 | $705 |
| No | 207203123 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X18L14** | *95ESN0261410A* | 14,800 | $740 |
| No | 207203124 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X24L14** | *95ESN0261410A* | 14,700 | $735 |
| No | 207203122 | SMART COMFORT | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0261410A* | 13,900 | $695 |
| No | 207203125 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0261410A* | 14,700 | $735 |
| No | 207203133 | SMART COMFORT | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0401712A* | 13,800 | $690 |
| No | 207203131 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X24L14** | *95ESN0401410A* | 14,600 | $730 |
| No | 207203126 | SMART COMFORT | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0401410A* | 13,900 | $695 |
| No | 207203130 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X18L14** | *95ESN0401410A* | 14,700 | $735 |
| No | 207203128 | SMART COMFORT | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0401410A* | 14,600 | $730 |
| No | 207203127 | SMART COMFORT | DLCSRBH18AAK | EA*4X24L14A* | *95ESN0401410A* | 14,600 | $730 |
| No | 207203129 | SMART COMFORT | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0401410A* | 13,800 | $690 |
| No | 207203132 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0401410A* | 14,600 | $730 |
| No | 207203134 | SMART COMFORT | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0401712A* | 14,600 | $730 |
| No | 207203135 | SMART COMFORT | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0401712A* | 13,700 | $685 |
| No | 207203138 | SMART COMFORT | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0601412A* | 14,900 | $745 |
| No | 207203137 | SMART COMFORT | DLCSRBH18AAK | EA*4X24L14A* | *95ESN0601412A* | 14,900 | $745 |
| No | 207203136 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0401712A* | 14,600 | $730 |
| No | 207203139 | SMART COMFORT | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0601714A* | 14,100 | $705 |
| No | 207203141 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0601714A* | 14,700 | $735 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207203140 | SMART COMFORT | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0601714A* | 14,000 | $700 |
| No | 207203142 | SMART COMFORT | DLCSRBH18AAK | EA*4X19L17A* | *95ESU0401712A* | 13,800 | $690 |
| No | 207203143 | SMART COMFORT | DLCSRBH18AAK | EA*4X24L17A* | *95ESU0401712A* | 14,600 | $730 |
| No | 207203144 | SMART COMFORT | DLCSRBH18AAK | EA*4X25L17A* | *95ESU0401712A* | 13,800 | $690 |
| No | 207203145 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESU0401712A* | 14,600 | $730 |
| No | 207203146 | SMART COMFORT | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0401410A* | 13,900 | $695 |
| No | 207203147 | SMART COMFORT | DLCSRBH18AAK | EA*4X24L14A* | *96VTN0401410A* | 14,700 | $735 |
| No | 207203148 | SMART COMFORT | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0401410A* | 14,700 | $735 |
| No | 207203156 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X24L17** | *96VTN0401712A* | 14,600 | $730 |
| No | 207203150 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X18L14** | *96VTN0401410A* | 14,800 | $740 |
| No | 207203149 | SMART COMFORT | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0401410A* | 13,900 | $695 |
| No | 207203152 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X24L17** | *96VTN0401410A* | 14,700 | $735 |
| No | 207203154 | SMART COMFORT | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0401712A* | 14,600 | $730 |
| No | 207203151 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X24L14** | *96VTN0401410A* | 14,700 | $735 |
| No | 207203153 | SMART COMFORT | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0401712A* | 13,900 | $695 |
| No | 207203160 | SMART COMFORT | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0601412A* | 13,800 | $690 |
| No | 207203155 | SMART COMFORT | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0401712A* | 13,800 | $690 |
| No | 207203164 | SMART COMFORT | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0601714A* | 14,100 | $705 |
| No | 207203157 | SMART COMFORT | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0601412A* | 13,800 | $690 |
| No | 207203158 | SMART COMFORT | DLCSRBH18AAK | EA*4X24L14A* | *96VTN0601412A* | 14,600 | $730 |
| No | 207203159 | SMART COMFORT | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0601412A* | 14,600 | $730 |
| No | 207203161 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X18L14** | *96VTN0601412A* | 14,700 | $735 |
| No | 207203163 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X24L17** | *96VTN0601412A* | 14,600 | $730 |
| No | 207203162 | SMART COMFORT | DLCSRBH18AAK | EN(A,D)4X24L14** | *96VTN0601412A* | 14,600 | $730 |
| No | 207203165 | SMART COMFORT | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0601714A* | 14,700 | $735 |
| No | 207203167 | SMART COMFORT | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0801716A* | 13,800 | $690 |
| No | 207203166 | SMART COMFORT | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0601714A* | 13,900 | $695 |
| No | 207202177 | SMART COMFORT | DLCSRBH18AAK | FVM4X24***L | | 13,400 | $670 |
| No | 207203075 | SMART COMFORT | DLCSRBH18AAK | FMA4X18**AL* | | 15,000 | $750 |
| No | 207099861 | SMART COMFORT | DLCSRBH24AAK | EA*4X24L14A* | *80ES(N,L)0451412A* | 15,700 | $785 |
| No | 207203076 | SMART COMFORT | DLCSRBH18AAK | FM(C,U)4Z18**AL* | | 15,000 | $750 |
| No | 207099860 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X24L14** | *80ES(N,L)0451412A* | 15,600 | $780 |
| No | 207203077 | SMART COMFORT | DLCSRBH18AAK | FXM4X18**AL | | 14,500 | $725 |
| No | 207099862 | SMART COMFORT | DLCSRBH24AAK | EA*4X30L14A* | *80ES(N,L)0451412A* | 15,500 | $775 |
| No | 207099864 | SMART COMFORT | DLCSRBH24AAK | EA*4X36L17A* | *80ES(N,L)0451712A* | 15,500 | $775 |
| No | 207099863 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X30L14** | *80ES(N,L)0451412A* | 15,500 | $775 |
| No | 207099865 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X24L14** | *80ES(N,L)0701412A* | 15,600 | $780 |
| No | 207099866 | SMART COMFORT | DLCSRBH24AAK | EA*4X24L14A* | *80ES(N,L)0701412A* | 15,700 | $785 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207099867 | SMART COMFORT | DLCSRBH24AAK | EA*4X30L14A* | *80ES(N,L)0701412A* | 15,500 | $775 |
| No | 207099869 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X24L17** | *80ES(N,L)0701712A* | 15,600 | $780 |
| No | 207099868 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X30L14** | *80ES(N,L)0701412A* | 15,500 | $775 |
| No | 207099870 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X30L17** | *80ES(N,L)0701712A* | 15,400 | $770 |
| No | 207099873 | SMART COMFORT | DLCSRBH24AAK | EA*4X30L17A* | *80ES(N,L)0701712A* | 15,500 | $775 |
| No | 207099871 | SMART COMFORT | DLCSRBH24AAK | EA*4X36L17A* | *80ES(N,L)0701712A* | 15,400 | $770 |
| No | 207099872 | SMART COMFORT | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *80ES(N,L)0701712A* | 15,400 | $770 |
| No | 207099874 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X24L17** | *80ESU0401712A* | 15,500 | $775 |
| No | 207099877 | SMART COMFORT | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *80ESU0401712A* | 15,400 | $770 |
| No | 207099875 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X30L17** | *80ESU0401712A* | 15,400 | $770 |
| No | 207099876 | SMART COMFORT | DLCSRBH24AAK | EA*4X36L17A* | *80ESU0401712A* | 15,300 | $765 |
| No | 207099878 | SMART COMFORT | DLCSRBH24AAK | EA*4X30L17A* | *80ESU0401712A* | 15,400 | $770 |
| No | 207099879 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X24L17** | *80ESU0601716A | 15,600 | $780 |
| No | 207099880 | SMART COMFORT | DLCSRBH24AAK | EA*4X24L17A* | *80ESU0601716A | 15,700 | $785 |
| No | 207099881 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X30L17** | *80ESU0601716A | 15,500 | $775 |
| No | 207099883 | SMART COMFORT | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *80ESU0601716A | 15,500 | $775 |
| No | 207099882 | SMART COMFORT | DLCSRBH24AAK | EA*4X36L17A* | *80ESU0601716A | 15,400 | $770 |
| No | 207099896 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X24L14** | *92ESN0601412A* | 15,600 | $780 |
| No | 207099897 | SMART COMFORT | DLCSRBH24AAK | EA*4X24L14A* | *92ESN0601412A* | 15,700 | $785 |
| No | 207099905 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X24L17** | *92ESN0801716A* | 15,500 | $775 |
| No | 207099898 | SMART COMFORT | DLCSRBH24AAK | EA*4X30L14A* | *92ESN0601412A* | 15,500 | $775 |
| No | 207099899 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X30L14** | *92ESN0601412A* | 15,500 | $775 |
| No | 207099901 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X24L14** | *92ESN0601714A* | 15,500 | $775 |
| No | 207099902 | SMART COMFORT | DLCSRBH24AAK | EA*4X24L14A* | *92ESN0601714A* | 15,700 | $785 |
| No | 207099904 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X30L14** | *92ESN0601714A* | 15,400 | $770 |
| No | 207099903 | SMART COMFORT | DLCSRBH24AAK | EA*4X30L14A* | *92ESN0601714A* | 15,500 | $775 |
| No | 207099907 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X30L17** | *92ESN0801716A* | 15,400 | $770 |
| No | 207099906 | SMART COMFORT | DLCSRBH24AAK | EA*4X24L17A* | *92ESN0801716A* | 15,700 | $785 |
| No | 207099908 | SMART COMFORT | DLCSRBH24AAK | EA*4X36L17A* | *92ESN0801716A* | 15,400 | $770 |
| No | 207099910 | SMART COMFORT | DLCSRBH24AAK | EA*4X30L17A* | *92ESN0801716A* | 15,400 | $770 |
| No | 207099909 | SMART COMFORT | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *92ESN0801716A* | 15,400 | $770 |
| No | 207099913 | SMART COMFORT | DLCSRBH24AAK | EA*4X30L14A* | *95ESN0261410A* | 15,500 | $775 |
| No | 207099914 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X30L14** | *95ESN0261410A* | 15,500 | $775 |
| No | 207099912 | SMART COMFORT | DLCSRBH24AAK | EA*4X24L14A* | *95ESN0261410A* | 15,800 | $790 |
| No | 207099985 | SMART COMFORT | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0401410A* | 15,300 | $765 |
| No | 207099921 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESN0401712A* | 15,600 | $780 |
| No | 207099922 | SMART COMFORT | DLCSRBH24AAK | EA*4X36L17A* | *95ESN0401712A* | 15,500 | $775 |
| No | 207099924 | SMART COMFORT | DLCSRBH24AAK | EA*4X30L17A* | *95ESN0401712A* | 15,600 | $780 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207099923 | SMART COMFORT | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESN0401712A* | 15,600 | $780 |
| No | 207099977 | SMART COMFORT | DLCSRBH24AAK | EA*4X25L17A* | *95ESN0401712A* | 15,200 | $760 |
| No | 207099928 | SMART COMFORT | DLCSRBH24AAK | EA*4X30L14A* | *95ESN0601412A* | 15,600 | $780 |
| No | 207099978 | SMART COMFORT | DLCSRBH24AAK | EA*4X36L21A* | *95ESN0401712A* | 15,500 | $775 |
| No | 207099981 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X36L21** | *95ESN0401712A* | 15,600 | $780 |
| No | 207099979 | SMART COMFORT | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0401712A* | 15,300 | $765 |
| No | 207099980 | SMART COMFORT | DLCSRBH24AAK | EA*4X37L21A* | *95ESN0401712A* | 15,200 | $760 |
| No | 207099926 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X24L14** | *95ESN0601412A* | 15,600 | $780 |
| No | 207099927 | SMART COMFORT | DLCSRBH24AAK | EA*4X24L14A* | *95ESN0601412A* | 15,800 | $790 |
| No | 207099929 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X30L14** | *95ESN0601412A* | 15,500 | $775 |
| No | 207099970 | SMART COMFORT | DLCSRBH24AAK | EA*4X25L17A* | *95ESN0601412A* | 15,200 | $760 |
| No | 207099969 | SMART COMFORT | DLCSRBH24AAK | EA*4X24L17A* | *95ESN0601412A* | 15,800 | $790 |
| No | 207099971 | SMART COMFORT | DLCSRBH24AAK | EA*4X36L17A* | *95ESN0601412A* | 15,500 | $775 |
| No | 207099972 | SMART COMFORT | DLCSRBH24AAK | EA*4X30L17A* | *95ESN0601412A* | 15,600 | $780 |
| No | 207099974 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X24L17** | *95ESN0601412A* | 15,600 | $780 |
| No | 207099973 | SMART COMFORT | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0601412A* | 15,300 | $765 |
| No | 207099975 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESN0601412A* | 15,500 | $775 |
| No | 207099976 | SMART COMFORT | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESN0601412A* | 15,500 | $775 |
| No | 207099930 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X24L17** | *95ESN0601714A* | 15,600 | $780 |
| No | 207099931 | SMART COMFORT | DLCSRBH24AAK | EA*4X24L17A* | *95ESN0601714A* | 15,800 | $790 |
| No | 207099933 | SMART COMFORT | DLCSRBH24AAK | EA*4X36L17A* | *95ESN0601714A* | 15,400 | $770 |
| No | 207099932 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESN0601714A* | 15,500 | $775 |
| No | 207099934 | SMART COMFORT | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESN0601714A* | 15,500 | $775 |
| No | 207099935 | SMART COMFORT | DLCSRBH24AAK | EA*4X30L17A* | *95ESN0601714A* | 15,500 | $775 |
| No | 207099964 | SMART COMFORT | DLCSRBH24AAK | EA*4X25L17A* | *95ESN0601714A* | 15,200 | $760 |
| No | 207099965 | SMART COMFORT | DLCSRBH24AAK | EA*4X36L21A* | *95ESN0601714A* | 15,400 | $770 |
| No | 207099967 | SMART COMFORT | DLCSRBH24AAK | EA*4X37L21A* | *95ESN0601714A* | 15,100 | $755 |
| No | 207099966 | SMART COMFORT | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0601714A* | 15,200 | $760 |
| No | 207099968 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X36L21** | *95ESN0601714A* | 15,500 | $775 |
| No | 207099885 | SMART COMFORT | DLCSRBH24AAK | EA*4X24L17A* | *95ESU0401712A* | 15,700 | $785 |
| No | 207099884 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X24L17** | *95ESU0401712A* | 15,600 | $780 |
| No | 207099940 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X30L14** | *96VTN0401410A* | 15,600 | $780 |
| No | 207099886 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESU0401712A* | 15,500 | $775 |
| No | 207099887 | SMART COMFORT | DLCSRBH24AAK | EA*4X36L17A* | *95ESU0401712A* | 15,400 | $770 |
| No | 207099888 | SMART COMFORT | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESU0401712A* | 15,500 | $775 |
| No | 207099889 | SMART COMFORT | DLCSRBH24AAK | EA*4X30L17A* | *95ESU0401712A* | 15,500 | $775 |
| No | 207099939 | SMART COMFORT | DLCSRBH24AAK | EA*4X30L14A* | *96VTN0401410A* | 15,600 | $780 |
| No | 207099952 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X24L17** | *96VTN0601714A* | 15,600 | $780 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207099944 | SMART COMFORT | DLCSRBH24AAK | EA*4X36L17A* | *96VTN0401712A* | 15,500 | $775 |
| No | 207099950 | SMART COMFORT | DLCSRBH24AAK | EA*4X30L14A* | *96VTN0601412A* | 15,600 | $780 |
| No | 207099951 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X30L14** | *96VTN0601412A* | 15,600 | $780 |
| No | 207099956 | SMART COMFORT | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *96VTN0601714A* | 15,500 | $775 |
| No | 207099954 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X30L17** | *96VTN0601714A* | 15,500 | $775 |
| No | 207099953 | SMART COMFORT | DLCSRBH24AAK | EA*4X24L17A* | *96VTN0601714A* | 15,800 | $790 |
| No | 207099957 | SMART COMFORT | DLCSRBH24AAK | EA*4X30L17A* | *96VTN0601714A* | 15,500 | $775 |
| No | 207099955 | SMART COMFORT | DLCSRBH24AAK | EA*4X36L17A* | *96VTN0601714A* | 15,400 | $770 |
| No | 207099959 | SMART COMFORT | DLCSRBH24AAK | EA*4X24L17A* | *96VTN0801716A* | 15,700 | $785 |
| No | 207099960 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X30L17** | *96VTN0801716A* | 15,500 | $775 |
| No | 207099958 | SMART COMFORT | DLCSRBH24AAK | EN(A,D)4X24L17** | *96VTN0801716A* | 15,600 | $780 |
| No | 207199367 | SMART COMFORT | DLCSRBH30AAK | EN(A,D)4X30L14** | *80ES(N,L)0451412A* | 19,200 | $960 |
| No | 207099961 | SMART COMFORT | DLCSRBH24AAK | EA*4X36L17A* | *96VTN0801716A* | 15,400 | $770 |
| No | 207099962 | SMART COMFORT | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *96VTN0801716A* | 15,500 | $775 |
| No | 207099963 | SMART COMFORT | DLCSRBH24AAK | EA*4X30L17A* | *96VTN0801716A* | 15,500 | $775 |
| No | 207099857 | SMART COMFORT | DLCSRBH24AAK | FMA4X24**AL* | | 16,000 | $800 |
| No | 207099855 | SMART COMFORT | DLCSRBH24AAK | FXM4X24**AL | | 15,500 | $775 |
| No | 207099858 | SMART COMFORT | DLCSRBH24AAK | FM(C,U)4Z24**AL* | | 16,100 | $805 |
| No | 207199366 | SMART COMFORT | DLCSRBH30AAK | EA*4X30L14A* | *80ES(N,L)0451412A* | 19,200 | $960 |
| No | 207199370 | SMART COMFORT | DLCSRBH30AAK | EA*4X30L14A* | *80ES(N,L)0701412A* | 19,100 | $955 |
| No | 207199368 | SMART COMFORT | DLCSRBH30AAK | EA*4X30L17A* | *80ES(N,L)0451712A* | 19,100 | $955 |
| No | 207199369 | SMART COMFORT | DLCSRBH30AAK | EN(A,D)4X30L17** | *80ES(N,L)0451712A* | 19,100 | $955 |
| No | 207199371 | SMART COMFORT | DLCSRBH30AAK | EN(A,D)4X30L14** | *80ES(N,L)0701412A* | 19,100 | $955 |
| No | 207199377 | SMART COMFORT | DLCSRBH30AAK | EA*4X30L17A* | *80ESU0401712A* | 19,000 | $950 |
| No | 207199372 | SMART COMFORT | DLCSRBH30AAK | EA*4X30L17A* | *80ES(N,L)0701716A* | 19,300 | $965 |
| No | 207199373 | SMART COMFORT | DLCSRBH30AAK | EN(A,D)4X30L17** | *80ES(N,L)0701716A* | 19,300 | $965 |
| No | 207199376 | SMART COMFORT | DLCSRBH30AAK | EN(A,D)4X36L21** | *80ES(N,L)0902116A* | 19,300 | $965 |
| No | 207199374 | SMART COMFORT | DLCSRBH30AAK | EA*4X36L21A* | *80ES(N,L)0702116A* | 19,000 | $950 |
| No | 207199375 | SMART COMFORT | DLCSRBH30AAK | EN(A,D)4X36L21** | *80ES(N,L)0702116A* | 19,100 | $955 |
| No | 207199378 | SMART COMFORT | DLCSRBH30AAK | EN(A,D)4X30L17** | *80ESU0401712A* | 19,000 | $950 |
| No | 207199381 | SMART COMFORT | DLCSRBH30AAK | EA*4X30L17A* | *92ESN0601714A* | 19,100 | $955 |
| No | 207199380 | SMART COMFORT | DLCSRBH30AAK | EN(A,D)4X30L14** | *92ESN0601412A* | 19,200 | $960 |
| No | 207199379 | SMART COMFORT | DLCSRBH30AAK | EA*4X30L14A* | *92ESN0601412A* | 19,200 | $960 |
| No | 207199382 | SMART COMFORT | DLCSRBH30AAK | EN(A,D)4X30L17** | *92ESN0601714A* | 19,100 | $955 |
| No | 207199384 | SMART COMFORT | DLCSRBH30AAK | EN(A,D)4X30L17** | *92ESN0801716A* | 19,100 | $955 |
| No | 207199383 | SMART COMFORT | DLCSRBH30AAK | EA*4X30L17A* | *92ESN0801716A* | 19,100 | $955 |
| No | 207199401 | SMART COMFORT | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0401410A* | 19,100 | $955 |
| No | 207199402 | SMART COMFORT | DLCSRBH30AAK | END4X42L17** | *95ESN0401410A* | 19,200 | $960 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207199403 | SMART COMFORT | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0401712A* | 19,300 | $965 |
| No | 207199404 | SMART COMFORT | DLCSRBH30AAK | EA*4X36L21A* | *95ESN0401712A* | 19,300 | $965 |
| No | 207199405 | SMART COMFORT | DLCSRBH30AAK | EA*4X36L17A* | *95ESN0401712A* | 19,300 | $965 |
| No | 207199406 | SMART COMFORT | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0401712A* | 19,000 | $950 |
| No | 207199407 | SMART COMFORT | DLCSRBH30AAK | EA*4X42L21A* | *95ESN0401712A* | 19,200 | $960 |
| No | 207199408 | SMART COMFORT | DLCSRBH30AAK | EA*4X43L21A* | *95ESN0401712A* | 18,700 | $935 |
| No | 207199409 | SMART COMFORT | DLCSRBH30AAK | END4X42L17** | *95ESN0401712A* | 19,100 | $955 |
| No | 207199410 | SMART COMFORT | DLCSRBH30AAK | EA*4X30L14A* | *95ESN0601412A* | 19,300 | $965 |
| No | 207199412 | SMART COMFORT | DLCSRBH30AAK | EA*4X36L17A* | *95ESN0601412A* | 19,200 | $960 |
| No | 207199415 | SMART COMFORT | DLCSRBH30AAK | EN(A,D,W)4X36L17** | *95ESN0601412A* | 19,300 | $965 |
| No | 207199411 | SMART COMFORT | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0601412A* | 19,300 | $965 |
| No | 207199413 | SMART COMFORT | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0601412A* | 19,000 | $950 |
| No | 207199414 | SMART COMFORT | DLCSRBH30AAK | EN(A,D)4X30L14** | *95ESN0601412A* | 19,300 | $965 |
| No | 207199417 | SMART COMFORT | DLCSRBH30AAK | END4X42L17** | *95ESN0601412A* | 19,100 | $955 |
| No | 207199416 | SMART COMFORT | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESN0601412A* | 19,300 | $965 |
| No | 207199418 | SMART COMFORT | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0601714A* | 19,300 | $965 |
| No | 207199419 | SMART COMFORT | DLCSRBH30AAK | EA*4X36L17A* | *95ESN0601714A* | 19,200 | $960 |
| No | 207199420 | SMART COMFORT | DLCSRBH30AAK | EA*4X36L21A* | *95ESN0601714A* | 19,200 | $960 |
| No | 207199422 | SMART COMFORT | DLCSRBH30AAK | EA*4X42L21A* | *95ESN0601714A* | 19,100 | $955 |
| No | 207199421 | SMART COMFORT | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0601714A* | 19,000 | $950 |
| No | 207199425 | SMART COMFORT | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESN0601714A* | 19,200 | $960 |
| No | 207199423 | SMART COMFORT | DLCSRBH30AAK | EA*4X37L21A* | *95ESN0601714A* | 18,700 | $935 |
| No | 207199424 | SMART COMFORT | DLCSRBH30AAK | EA*4X43L21A* | *95ESN0601714A* | 18,700 | $935 |
| No | 207199426 | SMART COMFORT | DLCSRBH30AAK | EN(A,D)4X36L21** | *95ESN0601714A* | 19,200 | $960 |
| No | 207199428 | SMART COMFORT | DLCSRBH30AAK | END4X42L17** | *95ESN0601714A* | 19,000 | $950 |
| No | 207199427 | SMART COMFORT | DLCSRBH30AAK | EN(A,D,W)4X36L17** | *95ESN0601714A* | 19,200 | $960 |
| No | 207199385 | SMART COMFORT | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0801716A* | 19,300 | $965 |
| No | 207199429 | SMART COMFORT | DLCSRBH30AAK | EN(A,D,W)4X42L21** | *95ESN0601714A* | 19,100 | $955 |
| No | 207199386 | SMART COMFORT | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESN0801716A* | 19,300 | $965 |
| No | 207199388 | SMART COMFORT | DLCSRBH30AAK | EA*4X30L17A* | *95ESU0401712A* | 19,000 | $950 |
| No | 207199387 | SMART COMFORT | DLCSRBH30AAK | EA*4X36L21A* | *95ESN0802120A* | 19,100 | $955 |
| No | 207199389 | SMART COMFORT | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESU0401712A* | 19,000 | $950 |
| No | 207199390 | SMART COMFORT | DLCSRBH30AAK | EA*4X30L17A* | *96VTN0401712A* | 19,300 | $965 |
| No | 207199391 | SMART COMFORT | DLCSRBH30AAK | EN(A,D)4X30L14** | *96VTN0601412A* | 19,300 | $965 |
| No | 207199392 | SMART COMFORT | DLCSRBH30AAK | EA*4X30L17A* | *96VTN0601714A* | 19,100 | $955 |
| No | 207199393 | SMART COMFORT | DLCSRBH30AAK | EN(A,D)4X30L17** | *96VTN0601714A* | 19,100 | $955 |
| No | 207199394 | SMART COMFORT | DLCSRBH30AAK | EA*4X30L17A* | *96VTN0801716A* | 19,100 | $955 |
| No | 207200425 | SMART COMFORT | DLCSRBH30AAK | EN(A,D)4X36L21** | *96VTN1002120A* | 20,800 | $1,040 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207199395 | SMART COMFORT | DLCSRBH30AAK | EN(A,D)4X30L17** | *96VTN0801716A* | 19,100 | $955 |
| No | 207199396 | SMART COMFORT | DLCSRBH30AAK | EA*4X36L21A* | *96VTN0802120A* | 18,800 | $940 |
| No | 207199397 | SMART COMFORT | DLCSRBH30AAK | EN(A,D)4X36L21** | *96VTN0802120A* | 19,000 | $950 |
| No | 207199398 | SMART COMFORT | DLCSRBH30AAK | EA*4X36L21A* | *96VTN1002120A* | 18,800 | $940 |
| No | 207199365 | SMART COMFORT | DLCSRBH30AAK | FM(C,U)4Z30**AL* | | 19,200 | $960 |
| No | 207198931 | SMART COMFORT | DLCSRBH30AAK | FVM4X36***L | | 19,200 | $960 |
| No | 207199363 | SMART COMFORT | DLCSRBH30AAK | FMA4X30**AL* | | 19,400 | $970 |
| No | 207199364 | SMART COMFORT | DLCSRBH30AAK | FXM4X30**AL | | 18,800 | $940 |
| No | 206188347 | SMART COMFORT | DLCLRBH36AAK | DLFLDAH36XAK | | 27,000 | $1,350 |
| No | 207643159 | SMART COMFORT | DLCMHBH24CAK | Heat pump with ducts | | 18,500 | $925 |
| No | 207643160 | SMART COMFORT | DLCMHBH24CAK | Combination heat pumps with or without ducts | | 15,900 | $795 |
| No | 207643156 | SMART COMFORT | DLCMRBH18BAK | Heat pump with ducts | | 11,800 | $590 |
| No | 207643174 | SMART COMFORT | DLCMRBH48EAK | Heat pump with ducts | | 30,400 | $1,520 |
| No | 207643175 | SMART COMFORT | DLCMRBH48EAK | Combination heat pumps with or without ducts | | 30,600 | $1,530 |
| No | 207643157 | SMART COMFORT | DLCMRBH18BAK | Combination heat pumps with or without ducts | | 11,800 | $590 |
| No | 207643158 | SMART COMFORT | DLCMHBH24CAK | Heat pump without ducts | | 13,300 | $665 |
| No | 207643155 | SMART COMFORT | DLCMRBH18BAK | Heat pump without ducts | | 11,800 | $590 |
| No | 207643165 | SMART COMFORT | DLCMRBH36DAK | Heat pump without ducts | | 24,000 | $1,200 |
| No | 202119267 | SMART COMFORT | DLCSRAH36AAK | DLFSHAH36XAK | | 20,600 | $1,030 |
| No | 202463658 | SMART COMFORT | DLCPRAH18AAK | DLFPHAH18XAK | | 12,300 | $615 |
| No | 202119335 | SMART COMFORT | DLCMRAH48EAK | Heat pump without ducts | | 30,400 | $1,520 |
| No | 202119271 | SMART COMFORT | DLCMRAH36DAK | Heat pump without ducts | | 23,600 | $1,180 |
| No | 202119262 | SMART COMFORT | DLCSRAH09AAK | DLFSHAH09XAK | | 7,500 | $375 |
| No | 202119334 | SMART COMFORT | DLCLRAH58AAK | DLFLDAH58XAK | | 37,600 | $1,880 |
| No | 202119264 | SMART COMFORT | DLCSRAH18AAK | DLFSHAH18XAK | | 11,900 | $595 |
| No | 202119263 | SMART COMFORT | DLCSRAH12AAK | DLFSHAH12XAK | | 7,600 | $380 |
| No | 202119337 | SMART COMFORT | DLCLRAH48AAK | DLFLCAH48XAK | | 35,000 | $1,750 |
| No | 202119338 | SMART COMFORT | DLCLRAH58AAK | DLFLFAH58XAK | | 39,000 | $1,950 |
| No | 202119333 | SMART COMFORT | DLCLRAH48AAK | DLFLDAH48XAK | | 33,400 | $1,670 |
| No | 202119268 | SMART COMFORT | DLCLRAH36AAK | DLFLDAH36XAK | | 27,600 | $1,380 |
| No | 202119280 | SMART COMFORT | DLCSRAH12AAK | DLFSDAH12XAK | | 8,100 | $405 |
| No | 202119279 | SMART COMFORT | DLCSRAH12AAK | DLFSFAH12XAK | | 9,600 | $480 |
| No | 202119287 | SMART COMFORT | DLCLRAH36AAK | DLFLCAH36XAK | | 25,200 | $1,260 |
| No | 202119277 | SMART COMFORT | DLCSRAH09AAK | DLFSCAH09XAK | | 6,700 | $335 |
| No | 202119281 | SMART COMFORT | DLCSRAH18AAK | DLFSFAH18XAK | | 12,900 | $645 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202119278 | SMART COMFORT | DLCSRAH12AAK | DLFSCAH12XAK | | 8,200 | $410 |
| No | 202119286 | SMART COMFORT | DLCLRAH36AAK | DLFLFAH36XAK | | 25,400 | $1,270 |
| No | 202119276 | SMART COMFORT | DLCSRAH09AAK | DLFSDAH09XAK | | 6,800 | $340 |
| No | 211726674 | Star Air Kontrol | SAK-60-DTMS/220V* | SAK-60-DTMS/220V | | 34,400 | $1,720 |
| No | 211504109 | Star Air Kontrol | SAK-24-21MS/220 | SAK-24-21MS/220 | | 18,000 | $900 |
| No | 211726677 | Star Air Kontrol | SAK-48-21MUZ/220(OUT)* | Combination heat pumps with or without ducts | | 36,000 | $1,800 |
| No | 211726675 | Star Air Kontrol | SAK-27-22MUZ/220(OUT)* | Combination heat pumps with or without ducts | | 21,000 | $1,050 |
| No | 211726670 | Star Air Kontrol | SAK-36-22MUZ/220(OUT)* | Heat pump without ducts | | 26,400 | $1,320 |
| No | 211726668 | Star Air Kontrol | SAK-27-22MUZ/220(OUT)* | Heat pump without ducts | | 20,000 | $1,000 |
| No | 211726669 | Star Air Kontrol | SAK-27-22MUZ/220(OUT)* | Heat pump with ducts | | 22,000 | $1,100 |
| No | 211726667 | Star Air Kontrol | SAK-18-21MUZ/220(OUT)* | Combination heat pumps with or without ducts | | 14,600 | $730 |
| No | 211726666 | Star Air Kontrol | SAK-18-21MUZ/220(OUT)* | Heat pump with ducts | | 14,800 | $740 |
| No | 211726672 | Star Air Kontrol | SAK-48-21MUZ/220(OUT)* | Heat pump without ducts | | 36,000 | $1,800 |
| No | 211726665 | Star Air Kontrol | SAK-18-21MUZ/220(OUT)* | Heat pump without ducts | | 14,400 | $720 |
| No | 211726521 | Star Air Kontrol | SAK-18-DTMS/220V | SAK-18-DTMS/220V | | 12,600 | $630 |
| No | 211726524 | Star Air Kontrol | SAK-18-CC(OD)/220VOLT | SAK-18-20CC/220(IN) | | 12,000 | $600 |
| No | 211504105 | Star Air Kontrol | SAK-12-22MS/220 | SAK-12-22MS/220 | | 8,200 | $410 |
| No | 211504107 | Star Air Kontrol | SAK-18-24MS/220 | SAK-18-24MS/220 | | 14,000 | $700 |
| No | 211504104 | Star Air Kontrol | SAK-12-22MS/110 | SAK-12-22MS/110 | | 8,400 | $420 |
| No | 211504100 | Star Air Kontrol | SAK-18-19MS/220 | SAK-18-19MS/220 | | 11,500 | $575 |
| No | 211726525 | Star Air Kontrol | SAK-24-CC(OD)/220VOLT | SAK-24-20CC/220(IN) | | 19,000 | $950 |
| No | 211726664 | Star Air Kontrol | SAK-48-DTMS/220V* | SAK-48-DTMS/220V | | 34,000 | $1,700 |
| No | 211726527 | Star Air Kontrol | SAK-48-CC(OD)/220VOLT | SAK-48-20CC/220(IN) | | 30,000 | $1,500 |
| No | 211726663 | Star Air Kontrol | SAK-36-DTMS/220V* | SAK-36-DTMS/220V | | 25,000 | $1,250 |
| No | 211726526 | Star Air Kontrol | SAK-36-CC(OD)/220VOLT | SAK-36-20CC/220(IN) | | 23,000 | $1,150 |
| No | 211504111 | Star Air Kontrol | SAK-36MS/220V | SAK-36MS/220V | | 24,000 | $1,200 |
| No | 211726522 | Star Air Kontrol | SAK-24-DTMS/220V | SAK-24-DTMS/220V | | 20,000 | $1,000 |
| No | 211726523 | Star Air Kontrol | SAK-12-CC(OD)/220VOLT | SAK-12-20CC/220(IN) | | 8,900 | $445 |
| No | 211726532 | Star Air Kontrol | SAK-60ADN2-M18M | SAK-60WN1-M18 | | 37,000 | $1,850 |
| No | 211726531 | Star Air Kontrol | SAK-48ADN2-M18M | SAK-48WN1-M18 | | 37,000 | $1,850 |
| No | 211726530 | Star Air Kontrol | SAK-36ADN2-M18M | SAK-36WN1-M18 | | 20,400 | $1,020 |
| No | 211726529 | Star Air Kontrol | SAK-24ADN2-M18M | SAK-24WN1-M18 | | 21,000 | $1,050 |
| No | 211726528 | Star Air Kontrol | SAK-18ADN2-M18M | SAK-18WN1-M18 | | 12,000 | $600 |
| No | 212394349 | STEALTH | ACIQ-18-EHPB | ACIQ-18-ACL | | 13,000 | $650 |
| No | 212394359 | STEALTH | ACIQ-48-HPB | ACIQ-48-ACL | | 32,000 | $1,600 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 212394358 | STEALTH | ACIQ-36-HPB | ACIQ-36-ACL | | 33,000 | $1,650 |
| No | 212394353 | STEALTH | ACIQ-48-EHPB | ACIQ-48-ACL | | 30,400 | $1,520 |
| No | 212394352 | STEALTH | ACIQ-36-EHPB | ACIQ-36-ACL | | 19,800 | $990 |
| No | 212394356 | STEALTH | ACIQ-24-HPB | ACIQ-24-ACL | | 21,000 | $1,050 |
| No | 212394355 | STEALTH | ACIQ-18-HPB | ACIQ-18-ACL | | 14,700 | $735 |
| No | 212394354 | STEALTH | ACIQ-60-EHPB | ACIQ-60-ACL | | 34,000 | $1,700 |
| No | 212394351 | STEALTH | ACIQ-30-EHPB | ACIQ-30-ACL | | 22,000 | $1,100 |
| No | 212394350 | STEALTH | ACIQ-24-EHPB | ACIQ-24-ACL | | 22,000 | $1,100 |
| No | 212316197 | STEALTH | ACIQ-06ZPL-HP230B | SCC-0609-HH-M | | 5,700 | $285 |
| No | 212316199 | STEALTH | ACIQ-12ZPL-HP230B | SCC-1218-HH-M | | 9,500 | $475 |
| No | 212316198 | STEALTH | ACIQ-09ZPL-HP230B | SCC-0609-HH-M | | 9,800 | $490 |
| No | 212316202 | STEALTH | ACIQ-18ZPL-HP230B | ACIQ-18FM-HH-MC | | 14,700 | $735 |
| No | 212316201 | STEALTH | ACIQ-12ZPL-HP230B | ACIQ-12FM-HH-MC | | 10,200 | $510 |
| No | 212316220 | STEALTH | ES-55Z-M5B | Combination heat pumps with or without ducts | | 34,800 | $1,740 |
| No | 212316218 | STEALTH | ES-55Z-M5B | Heat pump without ducts | | 34,400 | $1,720 |
| No | 212316217 | STEALTH | ES-48Z-M5B | Combination heat pumps with or without ducts | | 35,000 | $1,750 |
| No | 212316215 | STEALTH | ES-48Z-M5B | Heat pump without ducts | | 34,000 | $1,700 |
| No | 212316154 | STEALTH | ACIQ-18Z-HP230B | ACIQ-18W-HP230B | | 11,500 | $575 |
| No | 212316152 | STEALTH | ACIQ-09Z-HP115B | ACIQ-09W-HP115B | | 6,800 | $340 |
| No | 212316191 | STEALTH | ACIQ-36ZPL-HP230B | ACIQ-36CD-HH-MB | | 34,000 | $1,700 |
| No | 212316184 | STEALTH | ACIQ-06ZPL-HP230B | ACIQ-06W-HH-MC | | 8,500 | $425 |
| No | 212316211 | STEALTH | ES-27Z-M3B | Combination heat pumps with or without ducts | | 21,400 | $1,070 |
| No | 212316208 | STEALTH | ES-18Z-M2B | Combination heat pumps with or without ducts | | 14,500 | $725 |
| No | 212316210 | STEALTH | ES-27Z-M3B | Heat pump with ducts | | 22,000 | $1,100 |
| No | 212316207 | STEALTH | ES-18Z-M2B | Heat pump with ducts | | 14,800 | $740 |
| No | 212316212 | STEALTH | ES-36Z-M4B | Heat pump without ducts | | 26,800 | $1,340 |
| No | 212316209 | STEALTH | ES-27Z-M3B | Heat pump without ducts | | 21,000 | $1,050 |
| No | 212316206 | STEALTH | ES-18Z-M2B | Heat pump without ducts | | 14,300 | $715 |
| No | 212316156 | STEALTH | ACIQ-36Z-HP230B | ACIQ-36W-HP230B | | 24,000 | $1,200 |
| No | 212316163 | STEALTH | ACIQ-18ZPL-HP230B | ACIQ-18CC-HH-MB | | 15,600 | $780 |
| No | 212316169 | STEALTH | ACIQ-18ZPL-HP230B | ACIQ-18FM-HH-MB | | 12,000 | $600 |
| No | 212316168 | STEALTH | ACIQ-12ZPL-HP230B | ACIQ-12FM-HH-MB | | 9,600 | $480 |
| No | 212316165 | STEALTH | ACIQ-12ZPL-HP230B | ACIQ-12CD-HH-MB | | 10,600 | $530 |
| No | 212316162 | STEALTH | ACIQ-12ZPL-HP230B | ACIQ-12CC-HH-MB | | 9,900 | $495 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 212316164 | STEALTH | ACIQ-09ZPL-HP230B | ACIQ-09CD-HH-MB | | 10,100 | $505 |
| No | 212316161 | STEALTH | ACIQ-09ZPL-HP230B | ACIQ-09CC-HH-MB | | 9,000 | $450 |
| No | 212316158 | STEALTH | ACIQ-12ZPL-HP230B | ACIQ-12W-HH-MB | | 10,000 | $500 |
| No | 212316186 | STEALTH | ACIQ-12ZPL-HP230B | ACIQ-12W-HH-MC | | 10,000 | $500 |
| No | 212316185 | STEALTH | ACIQ-09ZPL-HP230B | ACIQ-09W-HH-MC | | 9,500 | $475 |
| No | 212316157 | STEALTH | ACIQ-09ZPL-HP230B | ACIQ-09W-HH-MB | | 9,500 | $475 |
| No | 209948158 | SUNCHILLERS | M36ODU-ULTP | Heat pump without ducts | | 26,400 | $1,320 |
| No | 207804195 | SUNCHILLERS | M48ODU-UL2P | Heat pump without ducts | | 34,000 | $1,700 |
| No | 207804190 | SUNCHILLERS | M27ODU-UL2P | Heat pump with ducts | | 22,000 | $1,100 |
| No | 207804199 | SUNCHILLERS | M18ODU-UL2P | Heat pump with ducts | | 14,800 | $740 |
| No | 207804192 | SUNCHILLERS | M36ODU-UL2P | Heat pump without ducts | | 26,800 | $1,340 |
| No | 207804189 | SUNCHILLERS | M27ODU-UL2P | Heat pump without ducts | | 21,000 | $1,050 |
| No | 207804198 | SUNCHILLERS | M18ODU-UL2P | Heat pump without ducts | | 14,300 | $715 |
| No | 208447611 | SUNCHILLERS | 24WODU-UL | 24WIDU-UL | | 16,200 | $810 |
| No | 208447610 | SUNCHILLERS | 12WODU-UL | 12WIDU-UL | | 9,000 | $450 |
| No | 208447609 | SUNCHILLERS | 9WODU-UL | 9WIDU-UL | | 8,500 | $425 |
| No | 208447613 | SUNCHILLERS | 24WODU-UL | 24DIDU-UL | | 20,000 | $1,000 |
| No | 208447612 | SUNCHILLERS | 12WODU-UL | 12DIDU-UL | | 9,300 | $465 |
| No | 207742404 | SUPREME | YS25E-18HRDN1 | YS25E-18HRDN1 | | 14,900 | $745 |
| No | 207742403 | SUPREME | YS25E-12HRDN1 | YS25E-12HRDN1 | | 9,000 | $450 |
| No | 203238005 | SUPREME | YS25M-12HRDN1 | YS25M-12HRDN1 | | 7,800 | $390 |
| No | 206799641 | SUPREME CENTRAL | SUPRM24CC | AHAN2410 | | 15,400 | $770 |
| No | 206799643 | SUPREME CENTRAL | SUPRM36CC | AHAN3615 | | 19,800 | $990 |
| No | 207688892 | TCL | TSC-24HA2/I3TI20 | TSC-24HA2/I3TI20-I | | 13,900 | $695 |
| No | 207688889 | TCL | TSC-09HA2/I3TI23 | TSC-09HA2/I3TI23-I | | 5,900 | $295 |
| No | 207688887 | TCL | TSC-09HA1/I3TI22 | TSC-09HA1/I3TI22-I | | 5,900 | $295 |
| No | 207688888 | TCL | TSC-12HA1/I3TI22 | TSC-12HA1/I3TI22-I | | 7,100 | $355 |
| No | 207688890 | TCL | TSC-12HA2/I3TI23 | TSC-12HA2/I3TI23-I | | 7,600 | $380 |
| No | 207659295 | TEMPBLUE | TBG43VX036PH3N1H | TBH43VX036-H3N1H | | 24,000 | $1,200 |
| No | 210819427 | TEMPSTAR | DLCSRBH30AAK | DLFSABH30XBK | | 20,400 | $1,020 |
| No | 209852115 | TEMPSTAR | DLCURAH60AAK | DLFUAAH60XAK | | 37,000 | $1,850 |
| No | 209852112 | TEMPSTAR | DLCURAH48AAK | DLFUAAH48XAK | | 37,000 | $1,850 |
| No | 209852119 | TEMPSTAR | DLCURAH36AAK | DLFUAAH36XAK | | 20,400 | $1,020 |
| No | 209852121 | TEMPSTAR | DLCURAH30ABK | DLFUAAH30XAK | | 21,000 | $1,050 |
| No | 209852118 | TEMPSTAR | DLCURAH30AAK | DLFUAAH30XAK | | 20,000 | $1,000 |
| No | 209852111 | TEMPSTAR | DLCURAH24AAK | DLFUAAH24XAK | | 21,000 | $1,050 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 209852117 | TEMPSTAR | DLCURAH18AAK | DLFUAAH18XAK | | 12,000 | $600 |
| No | 207643152 | TEMPSTAR | DLCMRBH48EAK | Heat pump without ducts | | 31,000 | $1,550 |
| No | 201835786 | TEMPSTAR | DLCMRAH27CAK | Heat pump without ducts | | 17,800 | $890 |
| No | 207826635 | TEMPSTAR | DLCLRCH48AAK | DLFLABH48XAK | | 37,400 | $1,870 |
| No | 208104323 | TEMPSTAR | DLCSRBH36ABK | DLFSABH36XBK | | 25,600 | $1,280 |
| No | 207826637 | TEMPSTAR | DLCLRCH36AAK | DLFLABH36XAK | | 25,600 | $1,280 |
| No | 207826636 | TEMPSTAR | DLCLRCH58AAK | DLFLABH60XAK | | 34,000 | $1,700 |
| No | 207826608 | TEMPSTAR | DLCSRBH24AAK | DLFSABH24XBK | | 16,200 | $810 |
| No | 208104324 | TEMPSTAR | DLCSRBH30AAK11 | DLFSABH30XBK | | 19,200 | $960 |
| No | 206188334 | TEMPSTAR | DLCLRBH48AAK | DLFLFAH48XAK | | 29,000 | $1,450 |
| No | 206188331 | TEMPSTAR | DLCLRBH36AAK | DLFLFAH36XAK | | 22,000 | $1,100 |
| No | 206188335 | TEMPSTAR | DLCLRBH48AAK | DLFLCAH48XAK | | 29,000 | $1,450 |
| No | 206188332 | TEMPSTAR | DLCLRBH36AAK | DLFLCAH36XAK | | 22,000 | $1,100 |
| No | 206188336 | TEMPSTAR | DLCLRBH48AAK | DLFLDAH48XAK | | 29,000 | $1,450 |
| No | 207199431 | TEMPSTAR | DLCSRBH30AAK | FEM4X30**BL | | 19,100 | $955 |
| No | 207203171 | TEMPSTAR | DLCSRBH18AAK | FEM4P18**AL | | 14,700 | $735 |
| No | 207203172 | TEMPSTAR | DLCSRBH18AAK | FEM4X18**BL | | 14,700 | $735 |
| No | 207199430 | TEMPSTAR | DLCSRBH30AAK | FEM4P30**AL | | 19,100 | $955 |
| No | 207203173 | TEMPSTAR | DLCSRBH18AAK | EA*4X19L17A* | *80ES(N,L)0451412A* | 13,800 | $690 |
| No | 207203178 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X24L14** | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207203176 | TEMPSTAR | DLCSRBH18AAK | EA*4X25L17A* | *80ES(N,L)0451412A* | 13,800 | $690 |
| No | 207203174 | TEMPSTAR | DLCSRBH18AAK | EA*4X24L14A* | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207203175 | TEMPSTAR | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207203177 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X18L14** | *80ES(N,L)0451412A* | 14,700 | $735 |
| No | 207203179 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ES(N,L)0451412A* | 14,600 | $730 |
| No | 207203180 | TEMPSTAR | DLCSRBH18AAK | EA*4X19L17A* | *80ES(N,L)0451712A* | 13,900 | $695 |
| No | 207203181 | TEMPSTAR | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0451712A* | 14,600 | $730 |
| No | 207203183 | TEMPSTAR | DLCSRBH18AAK | EA*4X19L17A* | *80ES(N,L)0701412A* | 13,900 | $695 |
| No | 207203182 | TEMPSTAR | DLCSRBH18AAK | EA*4X25L17A* | *80ES(N,L)0451712A* | 13,800 | $690 |
| No | 207203184 | TEMPSTAR | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0701412A* | 14,600 | $730 |
| No | 207203185 | TEMPSTAR | DLCSRBH18AAK | EA*4X25L17A* | *80ES(N,L)0701412A* | 13,800 | $690 |
| No | 207203188 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ES(N,L)0701412A* | 14,600 | $730 |
| No | 207203189 | TEMPSTAR | DLCSRBH18AAK | EA*4X24L17A* | *80ES(N,L)0701712A* | 14,700 | $735 |
| No | 207203187 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X24L14** | *80ES(N,L)0701412A* | 14,600 | $730 |
| No | 207203186 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X18L14** | *80ES(N,L)0701412A* | 14,700 | $735 |
| No | 207203191 | TEMPSTAR | DLCSRBH18AAK | EA*4X19L17A* | *80ESU0401712A* | 13,700 | $685 |
| No | 207203194 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ESU0401712A* | 14,500 | $725 |
| No | 207203190 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X24L17** | *80ES(N,L)0701712A* | 14,700 | $735 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207203192 | TEMPSTAR | DLCSRBH18AAK | EA*4X24L17A* | *80ESU0401712A* | 14,500 | $725 |
| No | 207203193 | TEMPSTAR | DLCSRBH18AAK | EA*4X25L17A* | *80ESU0401712A* | 13,600 | $680 |
| No | 207203195 | TEMPSTAR | DLCSRBH18AAK | EA*4X19L17A* | *92ESN0401410A* | 13,800 | $690 |
| No | 207203202 | TEMPSTAR | DLCSRBH18AAK | EA*4X19L17A* | *92ESN0401712A* | 13,900 | $695 |
| No | 207203197 | TEMPSTAR | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0401410A* | 14,500 | $725 |
| No | 207203196 | TEMPSTAR | DLCSRBH18AAK | EA*4X24L14A* | *92ESN0401410A* | 14,500 | $725 |
| No | 207203198 | TEMPSTAR | DLCSRBH18AAK | EA*4X25L17A* | *92ESN0401410A* | 13,700 | $685 |
| No | 207203199 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X18L14** | *92ESN0401410A* | 14,600 | $730 |
| No | 207203200 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X24L14** | *92ESN0401410A* | 14,500 | $725 |
| No | 207203201 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0401410A* | 14,500 | $725 |
| No | 207203203 | TEMPSTAR | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0401712A* | 14,600 | $730 |
| No | 207203204 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0401712A* | 14,600 | $730 |
| No | 207203205 | TEMPSTAR | DLCSRBH18AAK | EA*4X19L17A* | *92ESN0601412A* | 14,000 | $700 |
| No | 207203206 | TEMPSTAR | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0601412A* | 14,600 | $730 |
| No | 207203207 | TEMPSTAR | DLCSRBH18AAK | EA*4X25L17A* | *92ESN0601412A* | 13,800 | $690 |
| No | 207203208 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X18L14** | *92ESN0601412A* | 14,700 | $735 |
| No | 207203209 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X24L14** | *92ESN0601412A* | 14,600 | $730 |
| No | 207203210 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0601412A* | 14,600 | $730 |
| No | 207203211 | TEMPSTAR | DLCSRBH18AAK | EA*4X24L17A* | *92ESN0801716A* | 14,700 | $735 |
| No | 207203213 | TEMPSTAR | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0261410A* | 14,100 | $705 |
| No | 207203212 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X24L17** | *92ESN0801716A* | 14,700 | $735 |
| No | 207203220 | TEMPSTAR | DLCSRBH18AAK | EA*4X24L14A* | *95ESN0401410A* | 14,600 | $730 |
| No | 207203217 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X24L14** | *95ESN0261410A* | 14,700 | $735 |
| No | 207203214 | TEMPSTAR | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0261410A* | 14,700 | $735 |
| No | 207203216 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X18L14** | *95ESN0261410A* | 14,800 | $740 |
| No | 207203215 | TEMPSTAR | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0261410A* | 13,900 | $695 |
| No | 207203218 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0261410A* | 14,700 | $735 |
| No | 207203219 | TEMPSTAR | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0401410A* | 13,900 | $695 |
| No | 207203222 | TEMPSTAR | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0401410A* | 13,800 | $690 |
| No | 207203223 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X18L14** | *95ESN0401410A* | 14,700 | $735 |
| No | 207203224 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X24L14** | *95ESN0401410A* | 14,600 | $730 |
| No | 207203221 | TEMPSTAR | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0401410A* | 14,600 | $730 |
| No | 207203225 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0401410A* | 14,600 | $730 |
| No | 207203226 | TEMPSTAR | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0401712A* | 13,800 | $690 |
| No | 207203228 | TEMPSTAR | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0401712A* | 13,700 | $685 |
| No | 207203227 | TEMPSTAR | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0401712A* | 14,600 | $730 |
| No | 207203229 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0401712A* | 14,600 | $730 |
| No | 207203230 | TEMPSTAR | DLCSRBH18AAK | EA*4X24L14A* | *95ESN0601412A* | 14,900 | $745 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207203231 | TEMPSTAR | DLCSRBH18AAK | EA*4X24L17A* | *95ESN0601412A* | 14,900 | $745 |
| No | 207203232 | TEMPSTAR | DLCSRBH18AAK | EA*4X19L17A* | *95ESN0601714A* | 14,100 | $705 |
| No | 207203233 | TEMPSTAR | DLCSRBH18AAK | EA*4X25L17A* | *95ESN0601714A* | 14,000 | $700 |
| No | 207203234 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESN0601714A* | 14,700 | $735 |
| No | 207203240 | TEMPSTAR | DLCSRBH18AAK | EA*4X24L14A* | *96VTN0401410A* | 14,700 | $735 |
| No | 207203235 | TEMPSTAR | DLCSRBH18AAK | EA*4X19L17A* | *95ESU0401712A* | 13,800 | $690 |
| No | 207203236 | TEMPSTAR | DLCSRBH18AAK | EA*4X24L17A* | *95ESU0401712A* | 14,600 | $730 |
| No | 207203237 | TEMPSTAR | DLCSRBH18AAK | EA*4X25L17A* | *95ESU0401712A* | 13,800 | $690 |
| No | 207203238 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X24L17** | *95ESU0401712A* | 14,600 | $730 |
| No | 207203241 | TEMPSTAR | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0401410A* | 14,700 | $735 |
| No | 207203239 | TEMPSTAR | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0401410A* | 13,900 | $695 |
| No | 207203242 | TEMPSTAR | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0401410A* | 13,900 | $695 |
| No | 207203243 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X18L14** | *96VTN0401410A* | 14,800 | $740 |
| No | 207203244 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X24L14** | *96VTN0401410A* | 14,700 | $735 |
| No | 207203245 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X24L17** | *96VTN0401410A* | 14,700 | $735 |
| No | 207203246 | TEMPSTAR | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0401712A* | 13,900 | $695 |
| No | 207203247 | TEMPSTAR | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0401712A* | 14,600 | $730 |
| No | 207203248 | TEMPSTAR | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0401712A* | 13,800 | $690 |
| No | 207203249 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X24L17** | *96VTN0401712A* | 14,600 | $730 |
| No | 207203253 | TEMPSTAR | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0601412A* | 13,800 | $690 |
| No | 207203250 | TEMPSTAR | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0601412A* | 13,800 | $690 |
| No | 207203251 | TEMPSTAR | DLCSRBH18AAK | EA*4X24L14A* | *96VTN0601412A* | 14,600 | $730 |
| No | 207203254 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X18L14** | *96VTN0601412A* | 14,700 | $735 |
| No | 207203255 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X24L14** | *96VTN0601412A* | 14,600 | $730 |
| No | 207203252 | TEMPSTAR | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0601412A* | 14,600 | $730 |
| No | 207203256 | TEMPSTAR | DLCSRBH18AAK | EN(A,D)4X24L17** | *96VTN0601412A* | 14,600 | $730 |
| No | 207203257 | TEMPSTAR | DLCSRBH18AAK | EA*4X19L17A* | *96VTN0601714A* | 14,100 | $705 |
| No | 207203258 | TEMPSTAR | DLCSRBH18AAK | EA*4X24L17A* | *96VTN0601714A* | 14,700 | $735 |
| No | 207203259 | TEMPSTAR | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0601714A* | 13,900 | $695 |
| No | 207203260 | TEMPSTAR | DLCSRBH18AAK | EA*4X25L17A* | *96VTN0801716A* | 13,800 | $690 |
| No | 207202178 | TEMPSTAR | DLCSRBH18AAK | FVM4X24***L | | 13,400 | $670 |
| No | 207203170 | TEMPSTAR | DLCSRBH18AAK | FXM4X18**AL | | 14,500 | $725 |
| No | 207203169 | TEMPSTAR | DLCSRBH18AAK | FM(C,U)4Z18**AL* | | 15,000 | $750 |
| No | 207203168 | TEMPSTAR | DLCSRBH18AAK | FMA4X18**AL* | | 15,000 | $750 |
| No | 207099994 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X24L14** | *80ES(N,L)0451412A* | 15,600 | $780 |
| No | 207099995 | TEMPSTAR | DLCSRBH24AAK | EA*4X24L14A* | *80ES(N,L)0451412A* | 15,700 | $785 |
| No | 207099996 | TEMPSTAR | DLCSRBH24AAK | EA*4X30L14A* | *80ES(N,L)0451412A* | 15,500 | $775 |
| No | 207100002 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X30L14** | *80ES(N,L)0701412A* | 15,500 | $775 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207099997 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X30L14** | *80ES(N,L)0451412A* | 15,500 | $775 |
| No | 207099998 | TEMPSTAR | DLCSRBH24AAK | EA*4X36L17A* | *80ES(N,L)0451712A* | 15,500 | $775 |
| No | 207100000 | TEMPSTAR | DLCSRBH24AAK | EA*4X24L14A* | *80ES(N,L)0701412A* | 15,700 | $785 |
| No | 207099999 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X24L14** | *80ES(N,L)0701412A* | 15,600 | $780 |
| No | 207100001 | TEMPSTAR | DLCSRBH24AAK | EA*4X30L14A* | *80ES(N,L)0701412A* | 15,500 | $775 |
| No | 207100004 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X30L17** | *80ES(N,L)0701712A* | 15,400 | $770 |
| No | 207100003 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X24L17** | *80ES(N,L)0701712A* | 15,600 | $780 |
| No | 207100005 | TEMPSTAR | DLCSRBH24AAK | EA*4X36L17A* | *80ES(N,L)0701712A* | 15,400 | $770 |
| No | 207100006 | TEMPSTAR | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *80ES(N,L)0701712A* | 15,400 | $770 |
| No | 207100011 | TEMPSTAR | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *80ESU0401712A* | 15,400 | $770 |
| No | 207100016 | TEMPSTAR | DLCSRBH24AAK | EA*4X36L17A* | *80ESU0601716A | 15,400 | $770 |
| No | 207100008 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X24L17** | *80ESU0401712A* | 15,500 | $775 |
| No | 207100007 | TEMPSTAR | DLCSRBH24AAK | EA*4X30L17A* | *80ES(N,L)0701712A* | 15,500 | $775 |
| No | 207100010 | TEMPSTAR | DLCSRBH24AAK | EA*4X36L17A* | *80ESU0401712A* | 15,300 | $765 |
| No | 207100009 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X30L17** | *80ESU0401712A* | 15,400 | $770 |
| No | 207100012 | TEMPSTAR | DLCSRBH24AAK | EA*4X30L17A* | *80ESU0401712A* | 15,400 | $770 |
| No | 207100014 | TEMPSTAR | DLCSRBH24AAK | EA*4X24L17A* | *80ESU0601716A | 15,700 | $785 |
| No | 207100013 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X24L17** | *80ESU0601716A | 15,600 | $780 |
| No | 207100015 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X30L17** | *80ESU0601716A | 15,500 | $775 |
| No | 207100030 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X24L14** | *92ESN0601412A* | 15,600 | $780 |
| No | 207100017 | TEMPSTAR | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *80ESU0601716A | 15,500 | $775 |
| No | 207100031 | TEMPSTAR | DLCSRBH24AAK | EA*4X24L14A* | *92ESN0601412A* | 15,700 | $785 |
| No | 207100032 | TEMPSTAR | DLCSRBH24AAK | EA*4X30L14A* | *92ESN0601412A* | 15,500 | $775 |
| No | 207100038 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X30L14** | *92ESN0601714A* | 15,400 | $770 |
| No | 207100035 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X24L14** | *92ESN0601714A* | 15,500 | $775 |
| No | 207100036 | TEMPSTAR | DLCSRBH24AAK | EA*4X24L14A* | *92ESN0601714A* | 15,700 | $785 |
| No | 207100033 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X30L14** | *92ESN0601412A* | 15,500 | $775 |
| No | 207100037 | TEMPSTAR | DLCSRBH24AAK | EA*4X30L14A* | *92ESN0601714A* | 15,500 | $775 |
| No | 207100039 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X24L17** | *92ESN0801716A* | 15,500 | $775 |
| No | 207100040 | TEMPSTAR | DLCSRBH24AAK | EA*4X24L17A* | *92ESN0801716A* | 15,700 | $785 |
| No | 207100041 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X30L17** | *92ESN0801716A* | 15,400 | $770 |
| No | 207100042 | TEMPSTAR | DLCSRBH24AAK | EA*4X36L17A* | *92ESN0801716A* | 15,400 | $770 |
| No | 207100044 | TEMPSTAR | DLCSRBH24AAK | EA*4X30L17A* | *92ESN0801716A* | 15,400 | $770 |
| No | 207100043 | TEMPSTAR | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *92ESN0801716A* | 15,400 | $770 |
| No | 207100046 | TEMPSTAR | DLCSRBH24AAK | EA*4X24L14A* | *95ESN0261410A* | 15,800 | $790 |
| No | 207100048 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X30L14** | *95ESN0261410A* | 15,500 | $775 |
| No | 207100047 | TEMPSTAR | DLCSRBH24AAK | EA*4X30L14A* | *95ESN0261410A* | 15,500 | $775 |
| No | 207100056 | TEMPSTAR | DLCSRBH24AAK | EA*4X36L17A* | *95ESN0401712A* | 15,500 | $775 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207100119 | TEMPSTAR | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0401410A* | 15,300 | $765 |
| No | 207100055 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESN0401712A* | 15,600 | $780 |
| No | 207100057 | TEMPSTAR | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESN0401712A* | 15,600 | $780 |
| No | 207100113 | TEMPSTAR | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0401712A* | 15,300 | $765 |
| No | 207100058 | TEMPSTAR | DLCSRBH24AAK | EA*4X30L17A* | *95ESN0401712A* | 15,600 | $780 |
| No | 207100112 | TEMPSTAR | DLCSRBH24AAK | EA*4X36L21A* | *95ESN0401712A* | 15,500 | $775 |
| No | 207100111 | TEMPSTAR | DLCSRBH24AAK | EA*4X25L17A* | *95ESN0401712A* | 15,200 | $760 |
| No | 207100115 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X36L21** | *95ESN0401712A* | 15,600 | $780 |
| No | 207100114 | TEMPSTAR | DLCSRBH24AAK | EA*4X37L21A* | *95ESN0401712A* | 15,200 | $760 |
| No | 207100061 | TEMPSTAR | DLCSRBH24AAK | EA*4X24L14A* | *95ESN0601412A* | 15,800 | $790 |
| No | 207100060 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X24L14** | *95ESN0601412A* | 15,600 | $780 |
| No | 207100062 | TEMPSTAR | DLCSRBH24AAK | EA*4X30L14A* | *95ESN0601412A* | 15,600 | $780 |
| No | 207100063 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X30L14** | *95ESN0601412A* | 15,500 | $775 |
| No | 207100104 | TEMPSTAR | DLCSRBH24AAK | EA*4X25L17A* | *95ESN0601412A* | 15,200 | $760 |
| No | 207100103 | TEMPSTAR | DLCSRBH24AAK | EA*4X24L17A* | *95ESN0601412A* | 15,800 | $790 |
| No | 207100110 | TEMPSTAR | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESN0601412A* | 15,500 | $775 |
| No | 207100106 | TEMPSTAR | DLCSRBH24AAK | EA*4X30L17A* | *95ESN0601412A* | 15,600 | $780 |
| No | 207100105 | TEMPSTAR | DLCSRBH24AAK | EA*4X36L17A* | *95ESN0601412A* | 15,500 | $775 |
| No | 207100107 | TEMPSTAR | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0601412A* | 15,300 | $765 |
| No | 207100109 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESN0601412A* | 15,500 | $775 |
| No | 207100108 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X24L17** | *95ESN0601412A* | 15,600 | $780 |
| No | 207100098 | TEMPSTAR | DLCSRBH24AAK | EA*4X25L17A* | *95ESN0601714A* | 15,200 | $760 |
| No | 207100064 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X24L17** | *95ESN0601714A* | 15,600 | $780 |
| No | 207100065 | TEMPSTAR | DLCSRBH24AAK | EA*4X24L17A* | *95ESN0601714A* | 15,800 | $790 |
| No | 207100067 | TEMPSTAR | DLCSRBH24AAK | EA*4X36L17A* | *95ESN0601714A* | 15,400 | $770 |
| No | 207100066 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESN0601714A* | 15,500 | $775 |
| No | 207100068 | TEMPSTAR | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESN0601714A* | 15,500 | $775 |
| No | 207100069 | TEMPSTAR | DLCSRBH24AAK | EA*4X30L17A* | *95ESN0601714A* | 15,500 | $775 |
| No | 207100099 | TEMPSTAR | DLCSRBH24AAK | EA*4X36L21A* | *95ESN0601714A* | 15,400 | $770 |
| No | 207100100 | TEMPSTAR | DLCSRBH24AAK | EA*4X37L17A* | *95ESN0601714A* | 15,200 | $760 |
| No | 207100101 | TEMPSTAR | DLCSRBH24AAK | EA*4X37L21A* | *95ESN0601714A* | 15,100 | $755 |
| No | 207100102 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X36L21** | *95ESN0601714A* | 15,500 | $775 |
| No | 207100018 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X24L17** | *95ESU0401712A* | 15,600 | $780 |
| No | 207100019 | TEMPSTAR | DLCSRBH24AAK | EA*4X24L17A* | *95ESU0401712A* | 15,700 | $785 |
| No | 207100020 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X30L17** | *95ESU0401712A* | 15,500 | $775 |
| No | 207100021 | TEMPSTAR | DLCSRBH24AAK | EA*4X36L17A* | *95ESU0401712A* | 15,400 | $770 |
| No | 207100022 | TEMPSTAR | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *95ESU0401712A* | 15,500 | $775 |
| No | 207100023 | TEMPSTAR | DLCSRBH24AAK | EA*4X30L17A* | *95ESU0401712A* | 15,500 | $775 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207100073 | TEMPSTAR | DLCSRBH24AAK | EA*4X30L14A* | *96VTN0401410A* | 15,600 | $780 |
| No | 207100078 | TEMPSTAR | DLCSRBH24AAK | EA*4X36L17A* | *96VTN0401712A* | 15,500 | $775 |
| No | 207100074 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X30L14** | *96VTN0401410A* | 15,600 | $780 |
| No | 207100085 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X30L14** | *96VTN0601412A* | 15,600 | $780 |
| No | 207100084 | TEMPSTAR | DLCSRBH24AAK | EA*4X30L14A* | *96VTN0601412A* | 15,600 | $780 |
| No | 207100086 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X24L17** | *96VTN0601714A* | 15,600 | $780 |
| No | 207100087 | TEMPSTAR | DLCSRBH24AAK | EA*4X24L17A* | *96VTN0601714A* | 15,800 | $790 |
| No | 207100090 | TEMPSTAR | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *96VTN0601714A* | 15,500 | $775 |
| No | 207100089 | TEMPSTAR | DLCSRBH24AAK | EA*4X36L17A* | *96VTN0601714A* | 15,400 | $770 |
| No | 207100088 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X30L17** | *96VTN0601714A* | 15,500 | $775 |
| No | 207100093 | TEMPSTAR | DLCSRBH24AAK | EA*4X24L17A* | *96VTN0801716A* | 15,700 | $785 |
| No | 207100097 | TEMPSTAR | DLCSRBH24AAK | EA*4X30L17A* | *96VTN0801716A* | 15,500 | $775 |
| No | 207100091 | TEMPSTAR | DLCSRBH24AAK | EA*4X30L17A* | *96VTN0601714A* | 15,500 | $775 |
| No | 207100092 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X24L17** | *96VTN0801716A* | 15,600 | $780 |
| No | 207100094 | TEMPSTAR | DLCSRBH24AAK | EN(A,D)4X30L17** | *96VTN0801716A* | 15,500 | $775 |
| No | 207100096 | TEMPSTAR | DLCSRBH24AAK | EN(A,D,W)4X36L17** | *96VTN0801716A* | 15,500 | $775 |
| No | 207100095 | TEMPSTAR | DLCSRBH24AAK | EA*4X36L17A* | *96VTN0801716A* | 15,400 | $770 |
| No | 207099989 | TEMPSTAR | DLCSRBH24AAK | FXM4X24**AL | | 15,500 | $775 |
| No | 207099991 | TEMPSTAR | DLCSRBH24AAK | FMA4X24**AL* | | 16,000 | $800 |
| No | 207199438 | TEMPSTAR | DLCSRBH30AAK | EN(A,D)4X30L17** | *80ES(N,L)0451712A* | 19,100 | $955 |
| No | 207199439 | TEMPSTAR | DLCSRBH30AAK | EA*4X30L14A* | *80ES(N,L)0701412A* | 19,100 | $955 |
| No | 207199435 | TEMPSTAR | DLCSRBH30AAK | EA*4X30L14A* | *80ES(N,L)0451412A* | 19,200 | $960 |
| No | 207099992 | TEMPSTAR | DLCSRBH24AAK | FM(C,U)4Z24**AL* | | 16,100 | $805 |
| No | 207199436 | TEMPSTAR | DLCSRBH30AAK | EN(A,D)4X30L14** | *80ES(N,L)0451412A* | 19,200 | $960 |
| No | 207199437 | TEMPSTAR | DLCSRBH30AAK | EA*4X30L17A* | *80ES(N,L)0451712A* | 19,100 | $955 |
| No | 207199441 | TEMPSTAR | DLCSRBH30AAK | EA*4X30L17A* | *80ES(N,L)0701716A* | 19,300 | $965 |
| No | 207199440 | TEMPSTAR | DLCSRBH30AAK | EN(A,D)4X30L14** | *80ES(N,L)0701412A* | 19,100 | $955 |
| No | 207199445 | TEMPSTAR | DLCSRBH30AAK | EN(A,D)4X36L21** | *80ES(N,L)0902116A* | 19,300 | $965 |
| No | 207199442 | TEMPSTAR | DLCSRBH30AAK | EN(A,D)4X30L17** | *80ES(N,L)0701716A* | 19,300 | $965 |
| No | 207199443 | TEMPSTAR | DLCSRBH30AAK | EA*4X36L21A* | *80ES(N,L)0702116A* | 19,000 | $950 |
| No | 207199444 | TEMPSTAR | DLCSRBH30AAK | EN(A,D)4X36L21** | *80ES(N,L)0702116A* | 19,100 | $955 |
| No | 207199451 | TEMPSTAR | DLCSRBH30AAK | EN(A,D)4X30L17** | *92ESN0601714A* | 19,100 | $955 |
| No | 207199446 | TEMPSTAR | DLCSRBH30AAK | EA*4X30L17A* | *80ESU0401712A* | 19,000 | $950 |
| No | 207199447 | TEMPSTAR | DLCSRBH30AAK | EN(A,D)4X30L17** | *80ESU0401712A* | 19,000 | $950 |
| No | 207199449 | TEMPSTAR | DLCSRBH30AAK | EN(A,D)4X30L14** | *92ESN0601412A* | 19,200 | $960 |
| No | 207199448 | TEMPSTAR | DLCSRBH30AAK | EA*4X30L14A* | *92ESN0601412A* | 19,200 | $960 |
| No | 207199450 | TEMPSTAR | DLCSRBH30AAK | EA*4X30L17A* | *92ESN0601714A* | 19,100 | $955 |
| No | 207199452 | TEMPSTAR | DLCSRBH30AAK | EA*4X30L17A* | *92ESN0801716A* | 19,100 | $955 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207199472 | TEMPSTAR | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0401712A* | 19,300 | $965 |
| No | 207199453 | TEMPSTAR | DLCSRBH30AAK | EN(A,D)4X30L17** | *92ESN0801716A* | 19,100 | $955 |
| No | 207199470 | TEMPSTAR | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0401410A* | 19,100 | $955 |
| No | 207199474 | TEMPSTAR | DLCSRBH30AAK | EA*4X36L17A* | *95ESN0401712A* | 19,300 | $965 |
| No | 207199471 | TEMPSTAR | DLCSRBH30AAK | END4X42L17** | *95ESN0401410A* | 19,200 | $960 |
| No | 207199478 | TEMPSTAR | DLCSRBH30AAK | END4X42L17** | *95ESN0401712A* | 19,100 | $955 |
| No | 207199473 | TEMPSTAR | DLCSRBH30AAK | EA*4X36L21A* | *95ESN0401712A* | 19,300 | $965 |
| No | 207199477 | TEMPSTAR | DLCSRBH30AAK | EA*4X43L21A* | *95ESN0401712A* | 18,700 | $935 |
| No | 207199475 | TEMPSTAR | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0401712A* | 19,000 | $950 |
| No | 207199476 | TEMPSTAR | DLCSRBH30AAK | EA*4X42L21A* | *95ESN0401712A* | 19,200 | $960 |
| No | 207199479 | TEMPSTAR | DLCSRBH30AAK | EA*4X30L14A* | *95ESN0601412A* | 19,300 | $965 |
| No | 207199480 | TEMPSTAR | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0601412A* | 19,300 | $965 |
| No | 207199482 | TEMPSTAR | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0601412A* | 19,000 | $950 |
| No | 207199481 | TEMPSTAR | DLCSRBH30AAK | EA*4X36L17A* | *95ESN0601412A* | 19,200 | $960 |
| No | 207199484 | TEMPSTAR | DLCSRBH30AAK | EN(A,D,W)4X36L17** | *95ESN0601412A* | 19,300 | $965 |
| No | 207199483 | TEMPSTAR | DLCSRBH30AAK | EN(A,D)4X30L14** | *95ESN0601412A* | 19,300 | $965 |
| No | 207199485 | TEMPSTAR | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESN0601412A* | 19,300 | $965 |
| No | 207199486 | TEMPSTAR | DLCSRBH30AAK | END4X42L17** | *95ESN0601412A* | 19,100 | $955 |
| No | 207199487 | TEMPSTAR | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0601714A* | 19,300 | $965 |
| No | 207199488 | TEMPSTAR | DLCSRBH30AAK | EA*4X36L17A* | *95ESN0601714A* | 19,200 | $960 |
| No | 207199489 | TEMPSTAR | DLCSRBH30AAK | EA*4X36L21A* | *95ESN0601714A* | 19,200 | $960 |
| No | 207199490 | TEMPSTAR | DLCSRBH30AAK | EA*4X37L17A* | *95ESN0601714A* | 19,000 | $950 |
| No | 207199491 | TEMPSTAR | DLCSRBH30AAK | EA*4X42L21A* | *95ESN0601714A* | 19,100 | $955 |
| No | 207199494 | TEMPSTAR | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESN0601714A* | 19,200 | $960 |
| No | 207199492 | TEMPSTAR | DLCSRBH30AAK | EA*4X37L21A* | *95ESN0601714A* | 18,700 | $935 |
| No | 207199493 | TEMPSTAR | DLCSRBH30AAK | EA*4X43L21A* | *95ESN0601714A* | 18,700 | $935 |
| No | 207199496 | TEMPSTAR | DLCSRBH30AAK | EN(A,D,W)4X36L17** | *95ESN0601714A* | 19,200 | $960 |
| No | 207199495 | TEMPSTAR | DLCSRBH30AAK | EN(A,D)4X36L21** | *95ESN0601714A* | 19,200 | $960 |
| No | 207199497 | TEMPSTAR | DLCSRBH30AAK | END4X42L17** | *95ESN0601714A* | 19,000 | $950 |
| No | 207199498 | TEMPSTAR | DLCSRBH30AAK | EN(A,D,W)4X42L21** | *95ESN0601714A* | 19,100 | $955 |
| No | 207199454 | TEMPSTAR | DLCSRBH30AAK | EA*4X30L17A* | *95ESN0801716A* | 19,300 | $965 |
| No | 207199456 | TEMPSTAR | DLCSRBH30AAK | EA*4X36L21A* | *95ESN0802120A* | 19,100 | $955 |
| No | 207199455 | TEMPSTAR | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESN0801716A* | 19,300 | $965 |
| No | 207199457 | TEMPSTAR | DLCSRBH30AAK | EA*4X30L17A* | *95ESU0401712A* | 19,000 | $950 |
| No | 207199459 | TEMPSTAR | DLCSRBH30AAK | EA*4X30L17A* | *96VTN0401712A* | 19,300 | $965 |
| No | 207199458 | TEMPSTAR | DLCSRBH30AAK | EN(A,D)4X30L17** | *95ESU0401712A* | 19,000 | $950 |
| No | 207199461 | TEMPSTAR | DLCSRBH30AAK | EA*4X30L17A* | *96VTN0601714A* | 19,100 | $955 |
| No | 207199460 | TEMPSTAR | DLCSRBH30AAK | EN(A,D)4X30L14** | *96VTN0601412A* | 19,300 | $965 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207199462 | TEMPSTAR | DLCSRBH30AAK | EN(A,D)4X30L17** | *96VTN0601714A* | 19,100 | $955 |
| No | 207199463 | TEMPSTAR | DLCSRBH30AAK | EA*4X30L17A* | *96VTN0801716A* | 19,100 | $955 |
| No | 207199464 | TEMPSTAR | DLCSRBH30AAK | EN(A,D)4X30L17** | *96VTN0801716A* | 19,100 | $955 |
| No | 207199467 | TEMPSTAR | DLCSRBH30AAK | EA*4X36L21A* | *96VTN1002120A* | 18,800 | $940 |
| No | 207199434 | TEMPSTAR | DLCSRBH30AAK | FM(C,U)4Z30**AL* | | 19,200 | $960 |
| No | 207200433 | TEMPSTAR | DLCSRBH30AAK | EN(A,D)4X36L21** | *96VTN1002120A* | 20,800 | $1,040 |
| No | 207199465 | TEMPSTAR | DLCSRBH30AAK | EA*4X36L21A* | *96VTN0802120A* | 18,800 | $940 |
| No | 207199466 | TEMPSTAR | DLCSRBH30AAK | EN(A,D)4X36L21** | *96VTN0802120A* | 19,000 | $950 |
| No | 207198932 | TEMPSTAR | DLCSRBH30AAK | FVM4X36***L | | 19,200 | $960 |
| No | 207199433 | TEMPSTAR | DLCSRBH30AAK | FXM4X30**AL | | 18,800 | $940 |
| No | 207199432 | TEMPSTAR | DLCSRBH30AAK | FMA4X30**AL* | | 19,400 | $970 |
| No | 206188333 | TEMPSTAR | DLCLRBH36AAK | DLFLDAH36XAK | | 27,000 | $1,350 |
| No | 207643138 | TEMPSTAR | DLCMHBH24CAK | Heat pump with ducts | | 18,500 | $925 |
| No | 207643135 | TEMPSTAR | DLCMRBH18BAK | Heat pump with ducts | | 11,800 | $590 |
| No | 207643153 | TEMPSTAR | DLCMRBH48EAK | Heat pump with ducts | | 30,400 | $1,520 |
| No | 207643139 | TEMPSTAR | DLCMHBH24CAK | Combination heat pumps with or without ducts | | 15,900 | $795 |
| No | 207643136 | TEMPSTAR | DLCMRBH18BAK | Combination heat pumps with or without ducts | | 11,800 | $590 |
| No | 207643154 | TEMPSTAR | DLCMRBH48EAK | Combination heat pumps with or without ducts | | 30,600 | $1,530 |
| No | 207643137 | TEMPSTAR | DLCMHBH24CAK | Heat pump without ducts | | 13,300 | $665 |
| No | 207643134 | TEMPSTAR | DLCMRBH18BAK | Heat pump without ducts | | 11,800 | $590 |
| No | 207643144 | TEMPSTAR | DLCMRBH36DAK | Heat pump without ducts | | 24,000 | $1,200 |
| No | 206350460 | TEMPSTAR | DLCSRBH09AAK | DLFSDAH09XAK | | 6,400 | $320 |
| No | 206350459 | TEMPSTAR | DLCSRBH09AAK | DLFSCAH09XAK | | 6,100 | $305 |
| No | 206396138 | TEMPSTAR | DLCSRBH12AAK | DLFSHAH12XAK | | 7,500 | $375 |
| No | 206361905 | TEMPSTAR | DLCSRBH12AAK | DLFSHBH12XAK | | 7,300 | $365 |
| No | 206350462 | TEMPSTAR | DLCSRBH12AAK | DLFSDAH12XAK | | 8,300 | $415 |
| No | 206396139 | TEMPSTAR | DLCSRAH12AAK | DLFSHBH12XAK | | 7,500 | $375 |
| No | 206361907 | TEMPSTAR | DLCSRBH24AAK | DLFSHBH24XAK | | 17,000 | $850 |
| No | 206361903 | TEMPSTAR | DLCSRBH12AAJ | DLFSHBH12XAJ | | 8,200 | $410 |
| No | 206396142 | TEMPSTAR | DLCSRAH24AAK | DLFSHBH24XAK | | 15,000 | $750 |
| No | 206396143 | TEMPSTAR | DLCSRBH24AAK | DLFSHAH24XAK | | 15,000 | $750 |
| No | 206350461 | TEMPSTAR | DLCSRBH12AAK | DLFSCAH12XAK | | 7,900 | $395 |
| No | 206361906 | TEMPSTAR | DLCSRBH18AAK | DLFSHBH18XAK | | 11,100 | $555 |
| No | 206361904 | TEMPSTAR | DLCSRBH09AAK | DLFSHBH09XAK | | 7,400 | $370 |
| No | 206350463 | TEMPSTAR | DLCSRBH12AAK | DLFSFAH12XAK | | 8,400 | $420 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205767361 | TEMPSTAR | DLCLRBH36AAK | DLFLAAH36XAK | | 25,000 | $1,250 |
| No | 205767362 | TEMPSTAR | DLCLRBH48AAK | DLFLAAH48XAK | | 36,000 | $1,800 |
| No | 201835777 | TEMPSTAR | DLCSRAH36AAK | DLFSHAH36XAK | | 20,600 | $1,030 |
| No | 202463656 | TEMPSTAR | DLCPRAH18AAK | DLFPHAH18XAK | | 12,300 | $615 |
| No | 201835791 | TEMPSTAR | DLCMRAH48EAK | Heat pump without ducts | | 30,400 | $1,520 |
| No | 201835789 | TEMPSTAR | DLCMRAH36DAK | Heat pump without ducts | | 23,600 | $1,180 |
| No | 201835765 | TEMPSTAR | DLCSRAH12AAJ | DLFSHAH12XAJ | | 7,100 | $355 |
| No | 201835750 | TEMPSTAR | DLCPRAH12AAK | DLFPHAH12XAK | | 6,800 | $340 |
| No | 201835748 | TEMPSTAR | DLCPRAH09AAK | DLFPHAH09XAK | | 7,200 | $360 |
| No | 201835767 | TEMPSTAR | DLCSRAH09AAK | DLFSHAH09XAK | | 7,500 | $375 |
| No | 201835782 | TEMPSTAR | DLCLRAH58AAK | DLFLDAH58XAK | | 37,600 | $1,880 |
| No | 201835771 | TEMPSTAR | DLCSRAH18AAK | DLFSHAH18XAK | | 11,900 | $595 |
| No | 201835769 | TEMPSTAR | DLCSRAH12AAK | DLFSHAH12XAK | | 7,600 | $380 |
| No | 201835828 | TEMPSTAR | DLCLRAH48AAK | DLFLCAH48XAK | | 35,000 | $1,750 |
| No | 201835830 | TEMPSTAR | DLCLRAH58AAK | DLFLFAH58XAK | | 39,000 | $1,950 |
| No | 201835781 | TEMPSTAR | DLCLRAH48AAK | DLFLDAH48XAK | | 33,400 | $1,670 |
| No | 201835779 | TEMPSTAR | DLCLRAH36AAK | DLFLDAH36XAK | | 27,600 | $1,380 |
| No | 201835808 | TEMPSTAR | DLCSRAH12AAK | DLFSDAH12XAK | | 8,100 | $405 |
| No | 201835806 | TEMPSTAR | DLCSRAH12AAK | DLFSFAH12XAK | | 9,600 | $480 |
| No | 201835822 | TEMPSTAR | DLCLRAH36AAK | DLFLCAH36XAK | | 25,200 | $1,260 |
| No | 201835802 | TEMPSTAR | DLCSRAH09AAK | DLFSCAH09XAK | | 6,700 | $335 |
| No | 201835810 | TEMPSTAR | DLCSRAH18AAK | DLFSFAH18XAK | | 12,900 | $645 |
| No | 201835804 | TEMPSTAR | DLCSRAH12AAK | DLFSCAH12XAK | | 8,200 | $410 |
| No | 201835820 | TEMPSTAR | DLCLRAH36AAK | DLFLFAH36XAK | | 25,400 | $1,270 |
| No | 201835800 | TEMPSTAR | DLCSRAH09AAK | DLFSDAH09XAK | | 6,800 | $340 |
| No | 209843051 | TGM | MMRSHT36AS4 | Heat pump without ducts | | 26,400 | $1,320 |
| No | 209843048 | TGM | MMRSHT27AS3 | Heat pump without ducts | | 20,000 | $1,000 |
| No | 209843049 | TGM | MMRSHT27AS3 | Heat pump with ducts | | 22,000 | $1,100 |
| No | 209843046 | TGM | MMRSHT18AS2 | Heat pump with ducts | | 14,800 | $740 |
| No | 209843054 | TGM | MMRSHT48AS5 | Heat pump without ducts | | 36,000 | $1,800 |
| No | 209843045 | TGM | MMRSHT18AS2 | Heat pump without ducts | | 14,400 | $720 |
| No | 209843018 | TGM | MRSVHT18AS | MFCHT18S | | 12,600 | $630 |
| No | 209843013 | TGM | MRSVHT18AS | MC4VHT18S | | 12,000 | $600 |
| No | 209843023 | TGM | MC4VHT18S | MUVHT18S | | 12,800 | $640 |
| No | 209843014 | TGM | MRSVHT24AS | MC4VHT24S | | 19,000 | $950 |
| No | 209843021 | TGM | MRSVHT48AS | MFCHT48S | | 34,000 | $1,700 |
| No | 209843016 | TGM | MRSVHT48AS | MC4VHT48S | | 30,000 | $1,500 |
| No | 209843026 | TGM | MRSVHT48AS | MUVHT48S | | 29,000 | $1,450 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 209843020 | TGM | MRSVHT36AS | MFCHT36S | | 25,000 | $1,250 |
| No | 209843015 | TGM | MRSVHT36AS | MC4VHT36S | | 23,000 | $1,150 |
| No | 209843025 | TGM | MRSVHT36AS | MUVHT36S | | 23,000 | $1,150 |
| No | 209843019 | TGM | MRSVHT24AS | MFCHT24S | | 20,000 | $1,000 |
| No | 209843017 | TGM | MRSVHT12AS | MFCHT12S | | 9,300 | $465 |
| No | 209843024 | TGM | MRSVHT24AS | MUVHT24S | | 16,000 | $800 |
| No | 209843012 | TGM | MRSVHT12AS | MC4VHT12S | | 8,900 | $445 |
| No | 209550325 | TGM | MRAPT24AS | MWAPT24S | | 16,200 | $810 |
| No | 209550324 | TGM | MRAPT12AS | MWAPT12S | | 10,000 | $500 |
| No | 211126505 | THERMAL ZONE | TZPLV602AA | TZHVLE6024JA | | 37,000 | $1,850 |
| No | 211126513 | THERMAL ZONE | TZPLV482AA | TZHVLE4821JA | | 37,000 | $1,850 |
| No | 211126511 | THERMAL ZONE | TZPLV362AA | TZHVLE3621JA | | 20,400 | $1,020 |
| No | 211126502 | THERMAL ZONE | TZPLV242AA | TZHVLE2417JA | | 21,000 | $1,050 |
| No | 211126508 | THERMAL ZONE | TZPLV182AA | TZHVLE1817JA | | 12,000 | $600 |
| No | 211126510 | THERMAL ZONE | TZPLV362PA | TZHVLE3621JA | | 30,400 | $1,520 |
| No | 211126506 | THERMAL ZONE | TZPLV302PA | TZHVLE3021JA | | 21,000 | $1,050 |
| No | 209549035 | THERMOCORE SYSTEMS | T423Q-H260-C | Heat pump without ducts | | 34,400 | $1,720 |
| No | 209549019 | THERMOCORE SYSTEMS | T4C18S-H260-C-2 | T3C18S-H260-EDT | | 34,400 | $1,720 |
| No | 209549025 | THERMOCORE SYSTEMS | T4C18S-H260-C-2 | T3C18S-H260-ESC | | 35,000 | $1,750 |
| No | 209549005 | THERMOCORE SYSTEMS | T421S-H224-C | T421S-H224-E | | 18,000 | $900 |
| No | 209549032 | THERMOCORE SYSTEMS | T425D-H248-C | Heat pump without ducts | | 34,000 | $1,700 |
| No | 209549027 | THERMOCORE SYSTEMS | T423D-H224-C | Heat pump with ducts | | 21,600 | $1,080 |
| No | 209549026 | THERMOCORE SYSTEMS | T423D-H224-C | Heat pump without ducts | | 20,400 | $1,020 |
| No | 209549013 | THERMOCORE SYSTEMS | T5HH22S-H218-C | T3-OS218-EC | | 12,000 | $600 |
| No | 209549020 | THERMOCORE SYSTEMS | T5HH22S-H218-C | T3-OS218-ESC | | 12,800 | $640 |
| No | 209549003 | THERMOCORE SYSTEMS | T422S-H212-C | T422S-H212-E | | 8,200 | $410 |
| No | 209549002 | THERMOCORE SYSTEMS | T424S-H209-C | T424S-H209-E | | 8,300 | $415 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 209549004 | THERMOCORE SYSTEMS | T424S-H218-C | T424S-H218-E | | 14,000 | $700 |
| No | 209548997 | THERMOCORE SYSTEMS | T5E19S-H218-C | T5E19S-H218-E | | 11,500 | $575 |
| No | 209548995 | THERMOCORE SYSTEMS | T5E22S-H209-C | T5E22S-H209-E | | 6,900 | $345 |
| No | 209548993 | THERMOCORE SYSTEMS | T5E21S-H109-C | T5E21S-H109-E | | 6,800 | $340 |
| No | 209549014 | THERMOCORE SYSTEMS | T5HH22S-H224-C | T3-OS224-EC | | 19,000 | $950 |
| No | 209549017 | THERMOCORE SYSTEMS | T4C18S-H248-C | T4C17S-H248-EC | | 30,000 | $1,500 |
| No | 209549023 | THERMOCORE SYSTEMS | T4C18S-H248-C | T3C18S-H248-ED | | 29,000 | $1,450 |
| No | 209549016 | THERMOCORE SYSTEMS | T4C18S-H236-C | T4C18S-H236-EC | | 23,000 | $1,150 |
| No | 209549022 | THERMOCORE SYSTEMS | T4C18S-H236-C | T3C16S-H236-ED | | 23,000 | $1,150 |
| No | 209549006 | THERMOCORE SYSTEMS | T5HH27S-H206-C | T5HH27S-H206-E | | 8,500 | $425 |
| No | 209549029 | THERMOCORE SYSTEMS | T424D-H236-C | Heat pump without ducts | | 26,800 | $1,340 |
| No | 209549001 | THERMOCORE SYSTEMS | T6E18S-H236-C | T6E18S-H236-E | | 24,000 | $1,200 |
| No | 209549015 | THERMOCORE SYSTEMS | T5HH28S-H209-C | T3-OS209-EC | | 9,000 | $450 |
| No | 209549021 | THERMOCORE SYSTEMS | T5HH22S-H224-C | T3-OS224-ESC | | 16,000 | $800 |
| No | 209549012 | THERMOCORE SYSTEMS | T5HH26S-H212-C | T3-OS212-EC | | 8,900 | $445 |
| No | 209549011 | THERMOCORE SYSTEMS | T5HH27S-H209-C | T3-OS209-EC | | 7,500 | $375 |
| No | 209549008 | THERMOCORE SYSTEMS | T5HH26S-H212-C | T5HH26S-H212-E | | 10,000 | $500 |
| No | 209549007 | THERMOCORE SYSTEMS | T5HH28S-H209-C | T5HH28S-H209-E | | 9,500 | $475 |
| No | 209862199 | THERMOCORE SYSTEMS | T3D16S-H260-AHU-C | T3D16S-H260-AHU | | 37,000 | $1,850 |
| No | 207742408 | TK'S | T4C-36HFN1 | Heat pump without ducts | | 26,400 | $1,320 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207742406 | TK'S | T2C-18HFN1 | Heat pump with ducts | | 14,800 | $740 |
| No | 207742411 | TK'S | T5C-48HFN1 | Heat pump without ducts | | 36,000 | $1,800 |
| No | 207742405 | TK'S | T2C-18HFN1 | Heat pump without ducts | | 14,400 | $720 |
| No | 205807088 | TK'S | TWS-18HRDN1 | TWS-18HRDN1 | | 11,500 | $575 |
| No | 205807086 | TK'S | TWS-09HRDN1 | TWS-09HRDN1 | | 6,900 | $345 |
| No | 205782686 | TK'S | TWS-09HRDN1-B | TWS-09HRDN1-B | | 6,800 | $340 |
| No | 210448882 | TOP LIFE | TOP-18HA2/TI21-O | TOP-18HA2/TI21-I | | 10,000 | $500 |
| No | 210448881 | TOP LIFE | TOP-12HA2/TI23-O | TOP-12HA2/TI23-I | | 7,600 | $380 |
| No | 9854720 | TOSHIBA CARRIER | RAV-SP240AT2-UL | RAV-SP241BT-UL | | 19,800 | $990 |
| No | 3638308 | TOSHIBA CARRIER | RAV-SP240AT2-UL | RAV-SP240CT-UL | | 18,300 | $915 |
| No | 3638309 | TOSHIBA CARRIER | RAV-SP300AT2-UL | RAV-SP300UT-UL | | 19,700 | $985 |
| No | 3638303 | TOSHIBA CARRIER | RAV-SP180AT2-UL | RAV-SP180KRT-UL | | 11,800 | $590 |
| No | 3638312 | TOSHIBA CARRIER | RAV-SP360AT2-UL | RAV-SP360CT-UL | | 25,800 | $1,290 |
| No | 3638311 | TOSHIBA CARRIER | RAV-SP360AT2-UL | RAV-SP360UT-UL | | 23,200 | $1,160 |
| No | 3638305 | TOSHIBA CARRIER | RAV-SP180AT2-UL | RAV-SP180CT-UL | | 11,900 | $595 |
| No | 9854722 | TOSHIBA CARRIER | RAV-SP300AT2-UL | RAV-SP301BT-UL | | 20,600 | $1,030 |
| No | 3638304 | TOSHIBA CARRIER | RAV-SP180AT2-UL | RAV-SP180UT-UL | | 11,300 | $565 |
| No | 9854795 | TOSHIBA CARRIER | RAV-SP360AT2-UL | RAV-SP361BT-UL | | 21,400 | $1,070 |
| No | 3638314 | TOSHIBA CARRIER | RAV-SP420AT2-UL | RAV-SP420CT-UL | | 28,600 | $1,430 |
| No | 9854719 | TOSHIBA CARRIER | RAV-SP180AT2-UL | RAV-SP181BT-UL | | 11,000 | $550 |
| No | 9854796 | TOSHIBA CARRIER | RAV-SP420AT2-UL | RAV-SP421BT-UL | | 32,200 | $1,610 |
| No | 3638313 | TOSHIBA CARRIER | RAV-SP420AT2-UL | RAV-SP420UT-UL | | 24,800 | $1,240 |
| No | 10053545 | TOSHIBA CARRIER | MCY-MAP0607HS-UL | Heat pump with ducts | | 40,000 | $2,000 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10052878 | TOSHIBA CARRIER | MCY-MAP0487HS-UL | Heat pump with ducts | | 33,000 | $1,650 |
| No | 10190447 | TOSHIBA CARRIER | MCY-MAP0607HS-UL | Combination heat pumps with or without ducts | | 40,000 | $2,000 |
| No | 10157790 | TOSHIBA CARRIER | MCY-MAP0487HS-UL | Combination heat pumps with or without ducts | | 32,500 | $1,625 |
| No | 10053546 | TOSHIBA CARRIER | MCY-MAP0607HS-UL | Heat pump without ducts | | 40,000 | $2,000 |
| No | 212361368 | TOSOT | TU60-48WADU | TCAT60H/NAA | | 35,200 | $1,760 |
| No | 212361367 | TOSOT | TU60-48WADU | TCAT48H/NAA | | 31,200 | $1,560 |
| No | 212361366 | TOSOT | TU36-24WADU | TCAT36F/NAA | | 22,000 | $1,100 |
| No | 211727023 | TOSOT | TM30HMO | Heat pump without ducts | | 27,200 | $1,360 |
| No | 211727022 | TOSOT | TM24HMO | Heat pump without ducts | | 23,600 | $1,180 |
| No | 211727021 | TOSOT | TM18HMO | Heat pump without ducts | | 14,700 | $735 |
| No | 9108748 | TOSOT | TW24HQ2C2DO | TW24HQ2C2DI | | 14,300 | $715 |
| No | 9108745 | TOSOT | TW09HQ2C2DO | TW09HQ2C2DI | | 7,300 | $365 |
| No | 211164221 | TOSOT | TW12HXCA5DO | TW12HXCA5DI | | 6,800 | $340 |
| No | 211164220 | TOSOT | TW09HXCA5DO | TW09HXCA5DI | | 6,000 | $300 |
| No | 204344221 | TOSOT | TM42H5O | Heat pump without ducts | | 30,000 | $1,500 |
| No | 204344220 | TOSOT | TM36H5O | Heat pump without ducts | | 29,000 | $1,450 |
| No | 211177536 | TOSOT | TW09HXCA5AO | TW09HXCA5AI | | 6,000 | $300 |
| No | 211177538 | TOSOT | TW18HXCA5DO | TW18HXCA5DI | | 11,200 | $560 |
| No | 211177537 | TOSOT | TW12HXCA5AO | TW12HXCA5AI | | 6,800 | $340 |
| No | 211177525 | TOSOT | TW36HXQ2B2DO | TW36HXQ2B2DI | | 22,000 | $1,100 |
| No | 211177524 | TOSOT | TW30HXQ2B2DO | TW30HXQ2B2DI | | 18,500 | $925 |
| No | 211177523 | TOSOT | TW24HXP2A1DO | TW24HXP2A1DI | | 15,000 | $750 |
| No | 211177522 | TOSOT | TW18HXP2A1DO | TW18HXP2A1DI | | 11,000 | $550 |
| No | 211177521 | TOSOT | TW12HXP2A1DO | TW12HXP2A1DI | | 7,000 | $350 |
| No | 211177520 | TOSOT | TW09HXP2A1DO | TW09HXP2A1DI | | 7,000 | $350 |
| No | 211177519 | TOSOT | TW12HXP2A1AO | TW12HXP2A1AI | | 7,000 | $350 |
| No | 211177518 | TOSOT | TW09HXP2A1AO | TW09HXP2A1AI | | 7,000 | $350 |
| No | 211177517 | TOSOT | TW24HXCA5DO | TW24HXCA5DI | | 13,900 | $695 |
| No | 211164241 | TOSOT | TM30HX4O | Heat pump without ducts | | 27,200 | $1,360 |
| No | 211164240 | TOSOT | TM24HX4O | Heat pump without ducts | | 23,600 | $1,180 |
| No | 211164239 | TOSOT | TM18HX4O | Heat pump without ducts | | 14,700 | $735 |
| No | 211078858 | TOSOT | TUD60W2/D-D(U) | TUD60AH2/D-D(U) | | 30,000 | $1,500 |
| No | 211078857 | TOSOT | TUD48W2/D-D(U) | TUD48AH2/D-D(U) | | 26,000 | $1,300 |
| No | 211078856 | TOSOT | TUD42W2/D-D(U) | TUD42AH2/D-D(U) | | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211078855 | TOSOT | TUD36W2/D-D(U) | TUD36AH2/D-D(U) | | 19,000 | $950 |
| No | 211078854 | TOSOT | TUD30W2/D-D(U) | TUD30AH2/D-D(U) | | 18,600 | $930 |
| No | 211078853 | TOSOT | TUD24W2/D-D(U) | TUD24AH2/D-D(U) | | 14,600 | $730 |
| No | 210921188 | TOSOT | TWH18AG25A2DO | TWH18AG25A2DI | | 11,000 | $550 |
| No | 210485389 | TOSOT | TWH36QF25B4DO | TWH36QF25B4DI | | 22,000 | $1,100 |
| No | 210485388 | TOSOT | TWH30QF25B4DO | TWH30QF25B4DI | | 17,500 | $875 |
| No | 210485387 | TOSOT | TWH24AG25A2DO | TWH24AG25A2DI | | 15,000 | $750 |
| No | 210485386 | TOSOT | TWH12AG25A2DO | TWH12AG25A2DI | | 7,000 | $350 |
| No | 210485385 | TOSOT | TWH12AG25A2AO | TWH12AG25A2AI | | 7,000 | $350 |
| No | 210485384 | TOSOT | TWH09AG25A2DO | TWH09AG25A2DI | | 7,000 | $350 |
| No | 210485383 | TOSOT | TWH09AG25A2AO | TWH09AG25A2AI | | 7,000 | $350 |
| No | 210485382 | TOSOT | TWH24ATEXF-D3DNA3EO | TWH24ATEXF-D3DNA3EI | | 13,900 | $695 |
| No | 210485381 | TOSOT | TWH18ATDXD-D3DNA3AO | TWH18ATDXD-D3DNA3AI | | 11,200 | $560 |
| No | 210485380 | TOSOT | TWH12ATCXB-A3DNA3CO | TWH12ATCXB-A3DNA3CI | | 6,800 | $340 |
| No | 210485379 | TOSOT | TWH12ATCXB-D3DNA3CO | TWH12ATCXB-D3DNA3CI | | 6,800 | $340 |
| No | 210485378 | TOSOT | TWH09ATCXB-A3DNA3AO | TWH09ATCXB-A3DNA3AI | | 6,000 | $300 |
| No | 210485377 | TOSOT | TWH09ATCXB-D3DNA3AO | TWH09ATCXB-D3DNA3AI | | 6,000 | $300 |
| No | 10064023 | TOSOT | TM36H4O | Heat pump without ducts | | 26,600 | $1,330 |
| No | 10064021 | TOSOT | TM30H4O | Heat pump without ducts | | 18,000 | $900 |
| No | 10064019 | TOSOT | TM24H4O | Heat pump without ducts | | 16,600 | $830 |
| No | 10064025 | TOSOT | TM42H3O | Heat pump without ducts | | 29,000 | $1,450 |
| No | 10611536 | TOSOT | TW12HQ2C2AO(WIFI) | TW12HQ2C2AI(WIFI) | | 6,800 | $340 |
| No | 10064017 | TOSOT | TM18H4O | Heat pump without ducts | | 12,800 | $640 |
| No | 9108746 | TOSOT | TW12HQ2C2DO | TW12HQ2C2DI | | 7,700 | $385 |
| No | 205416004 | TOSOT | TUHD18ND3F1O | TFH18D3F3I | | 12,500 | $625 |
| No | 205416005 | TOSOT | TUHD24ND3F1O | TFH24D3F3I | | 16,500 | $825 |
| No | 10616184 | TOSOT | TU36H3O | TU36HFI | | 24,600 | $1,230 |
| No | 10609450 | TOSOT | TU24H3O | TU24HFI | | 16,700 | $835 |
| No | 10544537 | TOSOT | TU18H3O | TU18HFI | | 10,900 | $545 |
| No | 10611533 | TOSOT | TW09HQ2C2AO(WIFI) | TW09HQ2C2AI(WIFI) | | 6,100 | $305 |
| No | 202126395 | TOSOT | TW09HQ2A3DO | TW09HQ2A3DI | | 6,800 | $340 |
| No | 10062018 | TOSOT | TW09HQ3D6DO | TW09HQ3D6DI | | 5,600 | $280 |
| No | 202134393 | TOSOT | TW18HQ2A3DO | TW18HQ2A3DI | | 12,400 | $620 |
| No | 9108747 | TOSOT | TW18HQ2C2DO | TW18HQ2C2DI | | 12,400 | $620 |
| No | 202134394 | TOSOT | TW24HQ2A3DO | TW24HQ2A3DI | | 14,600 | $730 |
| No | 202134392 | TOSOT | TW12HQ2A3DO | TW12HQ2A3DI | | 7,100 | $355 |
| No | 10062019 | TOSOT | TW12HQ3D6DO | TW12HQ3D6DI | | 8,100 | $405 |
| No | 9128595 | TOSOT | TMVRF-OC48KHP | Heat pump with ducts | | 32,000 | $1,600 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 9128591 | TOSOT | TMVRF-OC36KHP | Heat pump with ducts | | 25,200 | $1,260 |
| No | 205082081 | TOSOT | TMVRF-OC28KHP | Heat pump with ducts | | 19,400 | $970 |
| No | 205049534 | TOSOT | TMVRF-OC24KHP | Heat pump with ducts | | 16,500 | $825 |
| No | 212391563 | Trane | 4TWV7X60A1 | 4TXCD010DS3 | S8V2D120M5PDA | 49,500 | $2,475 |
| No | 212391562 | Trane | 4TWV7X60A1 | 4TXCD010DS3 | S8V2D120M5PCA | 49,500 | $2,475 |
| No | 212391559 | Trane | 4TWV7X60A1 | 4PX*DU60BS3 | S8V2D120M5PDA | 49,500 | $2,475 |
| No | 212391558 | Trane | 4TWV7X60A1 | 4PX*DU60BS3 | S8V2D120M5PCA | 49,500 | $2,475 |
| No | 212391365 | Trane | 4TWV7X48A1 | 4TXCD010DS3 | S8V2D120M5PDA | 37,000 | $1,850 |
| No | 212391366 | Trane | 4TWV7X48A1 | 4TXCD010DS3 | S8V2D120M5PCA | 37,000 | $1,850 |
| No | 212391364 | Trane | 4TWV7X48A1 | 4TXCD008DS3 | S8V2D120M5PDA | 37,600 | $1,880 |
| No | 212391363 | Trane | 4TWV7X48A1 | 4TXCD008DS3 | S8V2D120M5PCA | 37,600 | $1,880 |
| No | 212391359 | Trane | 4TWV7X48A1 | 4TXCC009DS3 | S8V2C100M5PDA | 37,200 | $1,860 |
| No | 212391362 | Trane | 4TWV7X48A1 | 4TXCC009DS3 | S8V2C100M5PCA | 37,200 | $1,860 |
| No | 212391360 | Trane | 4TWV7X48A1 | 4TXCC009DS3 | S8V2C080M5PDA | 37,000 | $1,850 |
| No | 212391361 | Trane | 4TWV7X48A1 | 4TXCC009DS3 | S8V2C080M5PCA | 37,000 | $1,850 |
| No | 212391539 | Trane | 4TWV7X48A1 | 4TXCC007DS3 | S8V2C100M5PDA | 37,600 | $1,880 |
| No | 212391543 | Trane | 4TWV7X48A1 | 4TXCC007DS3 | S8V2C100M5PCA | 37,600 | $1,880 |
| No | 212391541 | Trane | 4TWV7X48A1 | 4TXCC007DS3 | S8V2C080M5PDA | 37,400 | $1,870 |
| No | 212391535 | Trane | 4TWV7X48A1 | 4TXCC005DS3 | S8V2C100M5PDA | 37,600 | $1,880 |
| No | 212391537 | Trane | 4TWV7X48A1 | 4TXCC005DS3 | S8V2C100M5PCA | 37,600 | $1,880 |
| No | 212391523 | Trane | 4TWV7X48A1 | 4TXCB006DS3 | S8V2B080M4PDA | 37,400 | $1,870 |
| No | 212391529 | Trane | 4TWV7X48A1 | 4TXCB006DS3 | S8V2B080M4PCA | 37,400 | $1,870 |
| No | 212391527 | Trane | 4TWV7X48A1 | 4TXCB006DS3 | S8V2B060M4PDA | 37,400 | $1,870 |
| No | 212391525 | Trane | 4TWV7X48A1 | 4TXCB006DS3 | S8V2B060M4PCA | 37,400 | $1,870 |
| No | 212391358 | Trane | 4TWV7X48A1 | 4PX*DU60BS3 | S8V2D120M5PDA | 37,000 | $1,850 |
| No | 212391357 | Trane | 4TWV7X48A1 | 4PX*DU60BS3 | S8V2D120M5PCA | 37,000 | $1,850 |
| No | 212391355 | Trane | 4TWV7X48A1 | 4PX*DU48BS3 | S8V2D120M5PDA | 37,600 | $1,880 |
| No | 212391356 | Trane | 4TWV7X48A1 | 4PX*DU48BS3 | S8V2D120M5PCA | 37,600 | $1,880 |
| No | 212391515 | Trane | 4TWV7X48A1 | 4PX*DD60BS3 | S8V2D120M5PDA | 37,000 | $1,850 |
| No | 212391517 | Trane | 4TWV7X48A1 | 4PX*DD60BS3 | S8V2D120M5PCA | 37,000 | $1,850 |
| No | 212391353 | Trane | 4TWV7X48A1 | 4PX*CU60BS3 | S8V2C100M5PDA | 37,200 | $1,860 |
| No | 212391352 | Trane | 4TWV7X48A1 | 4PX*CU60BS3 | S8V2C100M5PCA | 37,200 | $1,860 |
| No | 212391351 | Trane | 4TWV7X48A1 | 4PX*CU60BS3 | S8V2C080M5PDA | 37,000 | $1,850 |
| No | 212391354 | Trane | 4TWV7X48A1 | 4PX*CU60BS3 | S8V2C080M5PCA | 37,000 | $1,850 |
| No | 212391503 | Trane | 4TWV7X48A1 | 4PX*CU48BS3 | S8V2C100M5PDA | 37,600 | $1,880 |
| No | 212391507 | Trane | 4TWV7X48A1 | 4PX*CU48BS3 | S8V2C100M5PCA | 37,600 | $1,880 |
| No | 212391505 | Trane | 4TWV7X48A1 | 4PX*CU48BS3 | S8V2C080M5PDA | 37,400 | $1,870 |
| No | 212391509 | Trane | 4TWV7X48A1 | 4PX*CU48BS3 | S8V2C080M5PCA | 37,400 | $1,870 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 212391501 | Trane | 4TWV7X48A1 | 4PX*CU42BS3 | S8V2C100M5PDA | 38,000 | $1,900 |
| No | 212391495 | Trane | 4TWV7X48A1 | 4PX*CU42BS3 | S8V2C100M5PCA | 38,000 | $1,900 |
| No | 212391350 | Trane | 4TWV7X48A1 | 4PX*CD60BS3 | S8V2C100M5PDA | 37,200 | $1,860 |
| No | 212391348 | Trane | 4TWV7X48A1 | 4PX*CD60BS3 | S8V2C100M5PCA | 37,200 | $1,860 |
| No | 212391349 | Trane | 4TWV7X48A1 | 4PX*CD60BS3 | S8V2C080M5PDA | 37,000 | $1,850 |
| No | 212391347 | Trane | 4TWV7X48A1 | 4PX*CD60BS3 | S8V2C080M5PCA | 37,000 | $1,850 |
| No | 212391479 | Trane | 4TWV7X48A1 | 4PX*BU48BS3 | S8V2B080M4PDA | 37,400 | $1,870 |
| No | 212391481 | Trane | 4TWV7X48A1 | 4PX*BU48BS3 | S8V2B080M4PCA | 37,400 | $1,870 |
| No | 212391477 | Trane | 4TWV7X48A1 | 4PX*BU48BS3 | S8V2B060M4PDA | 37,400 | $1,870 |
| No | 212391475 | Trane | 4TWV7X48A1 | 4PX*BU48BS3 | S8V2B060M4PCA | 37,400 | $1,870 |
| No | 212391344 | Trane | 4TWV7X36A1 | 4TXCC005DS3 | S8V2C100M5PDA | 26,400 | $1,320 |
| No | 212391345 | Trane | 4TWV7X36A1 | 4TXCC005DS3 | S8V2C100M5PCA | 26,400 | $1,320 |
| No | 212391342 | Trane | 4TWV7X36A1 | 4TXCB006DS3 | S8V2B080M4PDA | 26,600 | $1,330 |
| No | 212391340 | Trane | 4TWV7X36A1 | 4TXCB006DS3 | S8V2B080M4PCA | 26,600 | $1,330 |
| No | 212391339 | Trane | 4TWV7X36A1 | 4TXCB006DS3 | S8V2B060M4PDA | 26,600 | $1,330 |
| No | 212391338 | Trane | 4TWV7X36A1 | 4TXCB006DS3 | S8V2B060M4PCA | 26,600 | $1,330 |
| No | 212391337 | Trane | 4TWV7X36A1 | 4TXCB006DS3 | S8V2A040M3PDA | 25,200 | $1,260 |
| No | 212391341 | Trane | 4TWV7X36A1 | 4TXCB006DS3 | S8V2A040M3PCA | 25,200 | $1,260 |
| No | 212391448 | Trane | 4TWV7X36A1 | 4TXCB004DS3 | S8V2B080M4PDA | 26,400 | $1,320 |
| No | 212391450 | Trane | 4TWV7X36A1 | 4TXCB004DS3 | S8V2B080M4PCA | 26,400 | $1,320 |
| No | 212391446 | Trane | 4TWV7X36A1 | 4TXCB004DS3 | S8V2B060M4PDA | 26,200 | $1,310 |
| No | 212391456 | Trane | 4TWV7X36A1 | 4TXCB004DS3 | S8V2B060M4PCA | 26,200 | $1,310 |
| No | 212391452 | Trane | 4TWV7X36A1 | 4TXCB004DS3 | S8V2A040M3PDA | 25,000 | $1,250 |
| No | 212391454 | Trane | 4TWV7X36A1 | 4TXCB004DS3 | S8V2A040M3PCA | 25,000 | $1,250 |
| No | 212391335 | Trane | 4TWV7X36A1 | 4PX*CU48BS3 | S8V2C100M5PDA | 26,400 | $1,320 |
| No | 212391334 | Trane | 4TWV7X36A1 | 4PX*CU48BS3 | S8V2C100M5PCA | 26,400 | $1,320 |
| No | 212391333 | Trane | 4TWV7X36A1 | 4PX*CU48BS3 | S8V2C080M5PDA | 26,200 | $1,310 |
| No | 212391336 | Trane | 4TWV7X36A1 | 4PX*CU48BS3 | S8V2C080M5PCA | 26,200 | $1,310 |
| No | 212391329 | Trane | 4TWV7X36A1 | 4PX*CU42BS3 | S8V2C100M5PDA | 26,600 | $1,330 |
| No | 212391332 | Trane | 4TWV7X36A1 | 4PX*CU42BS3 | S8V2C100M5PCA | 26,600 | $1,330 |
| No | 212391331 | Trane | 4TWV7X36A1 | 4PX*CU42BS3 | S8V2C080M5PDA | 26,400 | $1,320 |
| No | 212391330 | Trane | 4TWV7X36A1 | 4PX*CU42BS3 | S8V2C080M5PCA | 26,400 | $1,320 |
| No | 212391325 | Trane | 4TWV7X36A1 | 4PX*CU36BS3 | S8V2C100M5PDA | 26,200 | $1,310 |
| No | 212391327 | Trane | 4TWV7X36A1 | 4PX*CU36BS3 | S8V2C100M5PCA | 26,200 | $1,310 |
| No | 212391326 | Trane | 4TWV7X36A1 | 4PX*CU36BS3 | S8V2C080M5PDA | 25,800 | $1,290 |
| No | 212391328 | Trane | 4TWV7X36A1 | 4PX*CU36BS3 | S8V2C080M5PCA | 25,800 | $1,290 |
| No | 212391318 | Trane | 4TWV7X36A1 | 4PX*BU42BS3 | S8V2B080M4PDA | 26,800 | $1,340 |
| No | 212391315 | Trane | 4TWV7X36A1 | 4PX*BU42BS3 | S8V2B080M4PCA | 26,800 | $1,340 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 212391316 | Trane | 4TWV7X36A1 | 4PX*BU42BS3 | S8V2B060M4PDA | 26,800 | $1,340 |
| No | 212391317 | Trane | 4TWV7X36A1 | 4PX*BU42BS3 | S8V2B060M4PCA | 26,800 | $1,340 |
| No | 212391414 | Trane | 4TWV7X36A1 | 4PX*BU36BS3 | S8V2B080M4PDA | 26,200 | $1,310 |
| No | 212391404 | Trane | 4TWV7X36A1 | 4PX*BU36BS3 | S8V2B080M4PCA | 26,200 | $1,310 |
| No | 212391406 | Trane | 4TWV7X36A1 | 4PX*BU36BS3 | S8V2B060M4PDA | 26,400 | $1,320 |
| No | 212391408 | Trane | 4TWV7X36A1 | 4PX*BU36BS3 | S8V2B060M4PCA | 26,400 | $1,320 |
| No | 212391410 | Trane | 4TWV7X36A1 | 4PX*BU36BS3 | S8V2A040M3PDA | 25,000 | $1,250 |
| No | 212391412 | Trane | 4TWV7X36A1 | 4PX*BU36BS3 | S8V2A040M3PCA | 25,000 | $1,250 |
| No | 212391309 | Trane | 4TWV7X24A1 | 4PX*BU36BS3 | S8V2A040M3PDA | 16,300 | $815 |
| No | 212391310 | Trane | 4TWV7X24A1 | 4PX*BU36BS3 | S8V2A040M3PCA | 16,300 | $815 |
| No | 207820957 | TRANE | 4TWV8X60A1 | TEM8B0C60V51+TDR | N/A | 48,500 | $2,425 |
| No | 207526363 | TRANE | 4TWV8X60A1 | TEM8A0D60V51+TDR | N/A | 48,000 | $2,400 |
| No | 210636929 | TRANE | 4TWV8X60A1 | TEM8A0D48V41+TDR | N/A | 48,500 | $2,425 |
| No | 210636927 | TRANE | 4TWV8X60A1 | TEM8A0C48V41+TDR | N/A | 48,500 | $2,425 |
| No | 211081288 | TRANE | 4TWV8X60A1 | 4TXCD010DS3 | S8V2D120M5PDA | 49,500 | $2,475 |
| No | 210691927 | TRANE | 4TWV8X60A1 | 4TXCD010DS3 | S8V2D120M5PCA | 49,500 | $2,475 |
| No | 211081285 | TRANE | 4TWV8X60A1 | 4PX*DU60BS3 | S8V2D120M5PDA | 49,500 | $2,475 |
| No | 210691923 | TRANE | 4TWV8X60A1 | 4PX*DU60BS3 | S8V2D120M5PCA | 49,500 | $2,475 |
| No | 207820955 | TRANE | 4TWV8X48A1 | TEM8B0C60V51+TDR | N/A | 36,600 | $1,830 |
| No | 207526361 | TRANE | 4TWV8X48A1 | TEM8A0D60V51+TDR | N/A | 36,400 | $1,820 |
| No | 207526360 | TRANE | 4TWV8X48A1 | TEM8A0D48V41+TDR | N/A | 37,000 | $1,850 |
| No | 207526358 | TRANE | 4TWV8X48A1 | TEM8A0C48V41+TDR | N/A | 36,600 | $1,830 |
| No | 207526357 | TRANE | 4TWV8X48A1 | TEM8A0C42V41+TDR | N/A | 36,600 | $1,830 |
| No | 210929572 | TRANE | 4TWV8X48A1 | TAMXB0C60V51 | N/A | 35,800 | $1,790 |
| No | 210929571 | TRANE | 4TWV8X48A1 | TAMXB0C48V41 | N/A | 35,600 | $1,780 |
| No | 207690043 | TRANE | 4TWV8X48A1 | TAMXA0C60V51 | N/A | 35,800 | $1,790 |
| No | 207526335 | TRANE | 4TWV8X48A1 | TAM9A0C60V51 | N/A | 35,800 | $1,790 |
| No | 207526334 | TRANE | 4TWV8X48A1 | TAM9A0C48V41 | N/A | 35,600 | $1,780 |
| No | 207805626 | TRANE | 4TWV8X48A1 | 4TXCD010DS3+P0V0D000M50SC+RP | N/A | 36,400 | $1,820 |
| No | 207805625 | TRANE | 4TWV8X48A1 | 4TXCD010DS3+P0V0C000M50SC+RP | N/A | 35,400 | $1,770 |
| No | 207526494 | TRANE | 4TWV8X48A1 | 4TXCD010DS3 | S9V2D120U5VSA+RP | 36,800 | $1,840 |
| No | 208185415 | TRANE | 4TWV8X48A1 | 4TXCD010DS3 | S9V2D120U5PSB+RP | 36,800 | $1,840 |
| No | 207599993 | TRANE | 4TWV8X48A1 | 4TXCD010DS3 | S9V2C100U5PSB+RP | 35,800 | $1,790 |
| No | 207526495 | TRANE | 4TWV8X48A1 | 4TXCD010DS3 | S9V2C100U4VSA+RP | 35,800 | $1,790 |
| No | 208185416 | TRANE | 4TWV8X48A1 | 4TXCD010DS3 | S9V2C100U4PSB+RP | 35,800 | $1,790 |
| No | 208185414 | TRANE | 4TWV8X48A1 | 4TXCD010DS3 | S9V2C080U5PSB+RP | 35,800 | $1,790 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211081281 | TRANE | 4TWV8X48A1 | 4TXCD010DS3 | S8V2D120M5PDA | 37,000 | $1,850 |
| No | 210691920 | TRANE | 4TWV8X48A1 | 4TXCD010DS3 | S8V2D120M5PCA | 37,000 | $1,850 |
| No | 211081280 | TRANE | 4TWV8X48A1 | 4TXCD010DS3 | S8V2C100M5PDA | 36,000 | $1,800 |
| No | 210691919 | TRANE | 4TWV8X48A1 | 4TXCD010DS3 | S8V2C100M5PCA | 36,000 | $1,800 |
| No | 211088977 | TRANE | 4TWV8X48A1 | 4TXCD010DS3 | S8V2C080M5PDA | 35,800 | $1,790 |
| No | 210692197 | TRANE | 4TWV8X48A1 | 4TXCD010DS3 | S8V2C080M5PCA | 35,800 | $1,790 |
| No | 207526904 | TRANE | 4TWV8X48A1 | 4TXCD010DS3 | L8V1C100U5VSA+RP | 35,600 | $1,780 |
| No | 207526303 | TRANE | 4TWV8X48A1 | 4TXCD010DS3 | *UHMD120ACV5 | 36,600 | $1,830 |
| No | 211596945 | TRANE | 4TWV8X48A1 | 4TXCD010DS3 | *UD2D120B9V5+RP | 36,800 | $1,840 |
| No | 207526300 | TRANE | 4TWV8X48A1 | 4TXCD010DS3 | *UD2D120ACV5 | 37,000 | $1,850 |
| No | 210641034 | TRANE | 4TWV8X48A1 | 4TXCD010DS3 | *UD2D120A9V5+RP | 37,000 | $1,850 |
| No | 210641033 | TRANE | 4TWV8X48A1 | 4TXCD010DS3 | *UD2C100B9V5+RP | 35,800 | $1,790 |
| No | 211289063 | TRANE | 4TWV8X48A1 | 4TXCD010DS3 | *UD2C100ACV5 | 36,200 | $1,810 |
| No | 210641030 | TRANE | 4TWV8X48A1 | 4TXCD010DS3 | *UD2C100A9V5+RP | 35,600 | $1,780 |
| No | 210641032 | TRANE | 4TWV8X48A1 | 4TXCD010DS3 | *UD2C080B9V4+RP | 35,600 | $1,780 |
| No | 211596946 | TRANE | 4TWV8X48A1 | 4TXCD010DS3 | *UD2C080ACV4 | 35,600 | $1,780 |
| No | 210641031 | TRANE | 4TWV8X48A1 | 4TXCD010DS3 | *UD2C080A9V4+RP | 36,000 | $1,800 |
| No | 207805623 | TRANE | 4TWV8X48A1 | 4TXCD008DS3+P0V0D000M50SC+RP | N/A | 37,000 | $1,850 |
| No | 207805624 | TRANE | 4TWV8X48A1 | 4TXCD008DS3+P0V0C000M50SC+RP | N/A | 36,000 | $1,800 |
| No | 210653701 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | S9V2D120U5VSA+RP | 37,200 | $1,860 |
| No | 210653702 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | S9V2D120U5PSB+RP | 37,200 | $1,860 |
| No | 207599990 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | S9V2D120D5PSB+RP | 36,200 | $1,810 |
| No | 210653703 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | S9V2C100U5PSB+RP | 36,200 | $1,810 |
| No | 210653704 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | S9V2C100U4VSA+RP | 36,200 | $1,810 |
| No | 210653700 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | S9V2C100U4PSB+RP | 36,200 | $1,810 |
| No | 210653697 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | S9V2C080U5PSB+RP | 36,200 | $1,810 |
| No | 211081279 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | S8V2D120M5PDA | 37,600 | $1,880 |
| No | 210691918 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | S8V2D120M5PCA | 37,600 | $1,880 |
| No | 211088975 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | S8V2C100M5PDA | 36,400 | $1,820 |
| No | 210692195 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | S8V2C100M5PCA | 36,400 | $1,820 |
| No | 211088976 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | S8V2C080M5PDA | 36,200 | $1,810 |
| No | 210692196 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | S8V2C080M5PCA | 36,200 | $1,810 |
| No | 210653698 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | L8V1C100U5VSA+RP | 36,200 | $1,810 |
| No | 210653699 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | *UHMD120ACV5 | 37,000 | $1,850 |
| No | 211596944 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | *UD2D120B9V5+RP | 37,200 | $1,860 |
| No | 211289062 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | *UD2D120ACV5 | 37,400 | $1,870 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210641028 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | *UD2D120A9V5+RP | 37,400 | $1,870 |
| No | 210641029 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | *UD2C100B9V5+RP | 36,200 | $1,810 |
| No | 211289061 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | *UD2C100ACV5 | 36,600 | $1,830 |
| No | 210641026 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | *UD2C080B9V4+RP | 36,200 | $1,810 |
| No | 211598145 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | *UD2C080ACV4 | 36,000 | $1,800 |
| No | 210641027 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | *UD2C080A9V4+RP | 36,400 | $1,820 |
| No | 207805622 | TRANE | 4TWV8X48A1 | 4TXCC009DS3+P0V0C000M50SC+RP | N/A | 36,600 | $1,830 |
| No | 208185413 | TRANE | 4TWV8X48A1 | 4TXCC009DS3 | S9V2C100U5PSB+RP | 37,000 | $1,850 |
| No | 207526492 | TRANE | 4TWV8X48A1 | 4TXCC009DS3 | S9V2C100U4VSA+RP | 37,000 | $1,850 |
| No | 208185411 | TRANE | 4TWV8X48A1 | 4TXCC009DS3 | S9V2C100U4PSB+RP | 37,000 | $1,850 |
| No | 208185412 | TRANE | 4TWV8X48A1 | 4TXCC009DS3 | S9V2C080U5PSB+RP | 37,000 | $1,850 |
| No | 211081278 | TRANE | 4TWV8X48A1 | 4TXCC009DS3 | S8V2C100M5PDA | 37,200 | $1,860 |
| No | 210691917 | TRANE | 4TWV8X48A1 | 4TXCC009DS3 | S8V2C100M5PCA | 37,200 | $1,860 |
| No | 211081277 | TRANE | 4TWV8X48A1 | 4TXCC009DS3 | S8V2C080M5PDA | 37,000 | $1,850 |
| No | 210691916 | TRANE | 4TWV8X48A1 | 4TXCC009DS3 | S8V2C080M5PCA | 37,000 | $1,850 |
| No | 210653696 | TRANE | 4TWV8X48A1 | 4TXCC009DS3 | L8V1C100U5VSA+RP | 36,800 | $1,840 |
| No | 210641024 | TRANE | 4TWV8X48A1 | 4TXCC009DS3 | *UD2C100B9V5+RP | 37,000 | $1,850 |
| No | 207526298 | TRANE | 4TWV8X48A1 | 4TXCC009DS3 | *UD2C100ACV5 | 37,400 | $1,870 |
| No | 210641023 | TRANE | 4TWV8X48A1 | 4TXCC009DS3 | *UD2C100A9V5+RP | 36,800 | $1,840 |
| No | 210641021 | TRANE | 4TWV8X48A1 | 4TXCC009DS3 | *UD2C080B9V4+RP | 36,800 | $1,840 |
| No | 207526295 | TRANE | 4TWV8X48A1 | 4TXCC009DS3 | *UD2C080ACV4 | 36,600 | $1,830 |
| No | 210641022 | TRANE | 4TWV8X48A1 | 4TXCC009DS3 | *UD2C080A9V4+RP | 37,200 | $1,860 |
| No | 207805621 | TRANE | 4TWV8X48A1 | 4TXCC007DS3+P0V0C000M50SC+RP | N/A | 37,200 | $1,860 |
| No | 208185410 | TRANE | 4TWV8X48A1 | 4TXCC007DS3 | S9V2C100U5PSB+RP | 37,400 | $1,870 |
| No | 207526489 | TRANE | 4TWV8X48A1 | 4TXCC007DS3 | S9V2C100U4VSA+RP | 37,400 | $1,870 |
| No | 207599988 | TRANE | 4TWV8X48A1 | 4TXCC007DS3 | S9V2C100U4PSB+RP | 37,400 | $1,870 |
| No | 210653862 | TRANE | 4TWV8X48A1 | 4TXCC007DS3 | S9V2C100D5PSB+RP | 36,400 | $1,820 |
| No | 210653861 | TRANE | 4TWV8X48A1 | 4TXCC007DS3 | S9V2C100D4VSA+RP | 36,400 | $1,820 |
| No | 207599989 | TRANE | 4TWV8X48A1 | 4TXCC007DS3 | S9V2C100D4PSB+RP | 36,400 | $1,820 |
| No | 208185409 | TRANE | 4TWV8X48A1 | 4TXCC007DS3 | S9V2C080U5PSB+RP | 37,400 | $1,870 |
| No | 211081276 | TRANE | 4TWV8X48A1 | 4TXCC007DS3 | S8V2C100M5PDA | 37,600 | $1,880 |
| No | 210691915 | TRANE | 4TWV8X48A1 | 4TXCC007DS3 | S8V2C100M5PCA | 37,600 | $1,880 |
| No | 211081275 | TRANE | 4TWV8X48A1 | 4TXCC007DS3 | S8V2C080M5PDA | 37,400 | $1,870 |
| No | 210691914 | TRANE | 4TWV8X48A1 | 4TXCC007DS3 | S8V2C080M5PCA | 37,400 | $1,870 |
| No | 207526903 | TRANE | 4TWV8X48A1 | 4TXCC007DS3 | L8V1C100U5VSA+RP | 37,400 | $1,870 |
| No | 210641017 | TRANE | 4TWV8X48A1 | 4TXCC007DS3 | *UD2C100B9V5+RP | 37,400 | $1,870 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207526292 | TRANE | 4TWV8X48A1 | 4TXCC007DS3 | *UD2C100ACV5 | 37,800 | $1,890 |
| No | 210641018 | TRANE | 4TWV8X48A1 | 4TXCC007DS3 | *UD2C100A9V5+RP | 37,200 | $1,860 |
| No | 210641019 | TRANE | 4TWV8X48A1 | 4TXCC007DS3 | *UD2C080B9V4+RP | 37,000 | $1,850 |
| No | 207526294 | TRANE | 4TWV8X48A1 | 4TXCC007DS3 | *UD2C080ACV4 | 37,200 | $1,860 |
| No | 210641020 | TRANE | 4TWV8X48A1 | 4TXCC007DS3 | *UD2C080A9V4+RP | 37,600 | $1,880 |
| No | 210653863 | TRANE | 4TWV8X48A1 | 4TXCC007DS3 | *DHMC100ACV4 | 36,200 | $1,810 |
| No | 207805620 | TRANE | 4TWV8X48A1 | 4TXCC005DS3+P0V0C000M50SC+RP | N/A | 37,000 | $1,850 |
| No | 210653691 | TRANE | 4TWV8X48A1 | 4TXCC005DS3 | S9V2C100U5PSB+RP | 37,000 | $1,850 |
| No | 210653695 | TRANE | 4TWV8X48A1 | 4TXCC005DS3 | S9V2C100U4VSA+RP | 37,400 | $1,870 |
| No | 210653694 | TRANE | 4TWV8X48A1 | 4TXCC005DS3 | S9V2C100U4PSB+RP | 37,000 | $1,850 |
| No | 210653693 | TRANE | 4TWV8X48A1 | 4TXCC005DS3 | S9V2C080U5PSB+RP | 37,000 | $1,850 |
| No | 211088974 | TRANE | 4TWV8X48A1 | 4TXCC005DS3 | S8V2C100M5PDA | 37,200 | $1,860 |
| No | 210692194 | TRANE | 4TWV8X48A1 | 4TXCC005DS3 | S8V2C100M5PCA | 37,200 | $1,860 |
| No | 210653692 | TRANE | 4TWV8X48A1 | 4TXCC005DS3 | L8V1C100U5VSA+RP | 37,200 | $1,860 |
| No | 211598144 | TRANE | 4TWV8X48A1 | 4TXCC005DS3 | *UD2C080ACV4 | 37,000 | $1,850 |
| No | 210653689 | TRANE | 4TWV8X48A1 | 4TXCB006DS3 | S9V2B080U4VSA+RP | 37,800 | $1,890 |
| No | 207599985 | TRANE | 4TWV8X48A1 | 4TXCB006DS3 | S9V2B080U4PSB+RP | 37,800 | $1,890 |
| No | 210653860 | TRANE | 4TWV8X48A1 | 4TXCB006DS3 | S9V2B080D4VSA+RP | 36,600 | $1,830 |
| No | 207599987 | TRANE | 4TWV8X48A1 | 4TXCB006DS3 | S9V2B080D4PSB+RP | 36,600 | $1,830 |
| No | 211081273 | TRANE | 4TWV8X48A1 | 4TXCB006DS3 | S8V2B080M4PDA | 37,400 | $1,870 |
| No | 210691912 | TRANE | 4TWV8X48A1 | 4TXCB006DS3 | S8V2B080M4PCA | 37,400 | $1,870 |
| No | 211081274 | TRANE | 4TWV8X48A1 | 4TXCB006DS3 | S8V2B060M4PDA | 37,400 | $1,870 |
| No | 210691913 | TRANE | 4TWV8X48A1 | 4TXCB006DS3 | S8V2B060M4PCA | 37,400 | $1,870 |
| No | 210653690 | TRANE | 4TWV8X48A1 | 4TXCB006DS3 | L8V1B080U4VSA+RP | 37,400 | $1,870 |
| No | 207805618 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3+P0V0D000M50SC+RP | N/A | 36,400 | $1,820 |
| No | 207805619 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3+P0V0C000M50SC+RP | N/A | 35,400 | $1,770 |
| No | 207526487 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | S9V2D120U5VSA+RP | 36,800 | $1,840 |
| No | 210653688 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | S9V2D120U5PSB+RP | 36,800 | $1,840 |
| No | 207599984 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | S9V2C100U5PSB+RP | 35,800 | $1,790 |
| No | 207526488 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | S9V2C100U4VSA+RP | 35,800 | $1,790 |
| No | 210653687 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | S9V2C100U4PSB+RP | 35,800 | $1,790 |
| No | 210653686 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | S9V2C080U5PSB+RP | 35,800 | $1,790 |
| No | 211081271 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | S8V2D120M5PDA | 37,000 | $1,850 |
| No | 210691911 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | S8V2D120M5PCA | 37,000 | $1,850 |
| No | 211081272 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | S8V2C100M5PDA | 36,000 | $1,800 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210691910 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | S8V2C100M5PCA | 36,000 | $1,800 |
| No | 211088972 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | S8V2C080M5PDA | 35,800 | $1,790 |
| No | 210692192 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | S8V2C080M5PCA | 35,800 | $1,790 |
| No | 207526902 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | L8V1C100U5VSA+RP | 35,600 | $1,780 |
| No | 207526274 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | *UHMD120ACV5 | 36,600 | $1,830 |
| No | 211596943 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | *UD2D120B9V5+RP | 36,800 | $1,840 |
| No | 207526273 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | *UD2D120ACV5 | 37,000 | $1,850 |
| No | 210641013 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | *UD2D120A9V5+RP | 37,000 | $1,850 |
| No | 210641015 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | *UD2C100B9V5+RP | 35,800 | $1,790 |
| No | 211289060 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | *UD2C100ACV5 | 36,200 | $1,810 |
| No | 210641016 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | *UD2C100A9V5+RP | 35,600 | $1,780 |
| No | 210641014 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | *UD2C080B9V4+RP | 35,600 | $1,780 |
| No | 211596942 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | *UD2C080ACV4 | 35,600 | $1,780 |
| No | 210641012 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | *UD2C080A9V4+RP | 36,000 | $1,800 |
| No | 207805617 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3+P0V0D000M50SC+RP | N/A | 37,000 | $1,850 |
| No | 207805616 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3+P0V0C000M50SC+RP | N/A | 36,000 | $1,800 |
| No | 210653680 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3 | S9V2D120U5VSA+RP | 37,200 | $1,860 |
| No | 210653681 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3 | S9V2D120U5PSB+RP | 37,200 | $1,860 |
| No | 207526524 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3 | S9V2D120D5PSB+RP | 36,200 | $1,810 |
| No | 210653682 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3 | S9V2C100U5PSB+RP | 36,200 | $1,810 |
| No | 210653683 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3 | S9V2C100U4VSA+RP | 36,200 | $1,810 |
| No | 210653684 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3 | S9V2C100U4PSB+RP | 36,200 | $1,810 |
| No | 210653685 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3 | S9V2C080U5PSB+RP | 36,200 | $1,810 |
| No | 211081270 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3 | S8V2D120M5PDA | 37,600 | $1,880 |
| No | 210691909 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3 | S8V2D120M5PCA | 37,600 | $1,880 |
| No | 211088970 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3 | S8V2C100M5PDA | 36,400 | $1,820 |
| No | 210692191 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3 | S8V2C100M5PCA | 36,400 | $1,820 |
| No | 211088971 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3 | S8V2C080M5PDA | 36,200 | $1,810 |
| No | 210692190 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3 | S8V2C080M5PCA | 36,200 | $1,810 |
| No | 210653679 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3 | L8V1C100U5VSA+RP | 36,200 | $1,810 |
| No | 210653678 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3 | *UHMD120ACV5 | 37,000 | $1,850 |
| No | 211596941 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3 | *UD2D120B9V5+RP | 37,200 | $1,860 |
| No | 211289059 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3 | *UD2D120ACV5 | 37,400 | $1,870 |
| No | 210641008 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3 | *UD2D120A9V5+RP | 37,400 | $1,870 |
| No | 210641011 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3 | *UD2C100B9V5+RP | 36,200 | $1,810 |
| No | 211289058 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3 | *UD2C100ACV5 | 36,600 | $1,830 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210641010 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3 | *UD2C080B9V4+RP | 36,200 | $1,810 |
| No | 211598143 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3 | *UD2C080ACV4 | 36,000 | $1,800 |
| No | 210641009 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3 | *UD2C080A9V4+RP | 36,400 | $1,820 |
| No | 207805612 | TRANE | 4TWV8X48A1 | 4PX*DD60BS3+P0V0D000M50SC+RP | N/A | 36,400 | $1,820 |
| No | 207805613 | TRANE | 4TWV8X48A1 | 4PX*DD60BS3+P0V0C000M50SC+RP | N/A | 35,400 | $1,770 |
| No | 211596940 | TRANE | 4TWV8X48A1 | 4PX*DD60BS3+HORIZ-RT | *UD2D120B9V5+RP | 36,200 | $1,810 |
| No | 211289057 | TRANE | 4TWV8X48A1 | 4PX*DD60BS3+HORIZ-RT | *UD2D120ACV5 | 37,000 | $1,850 |
| No | 210641006 | TRANE | 4TWV8X48A1 | 4PX*DD60BS3+HORIZ-RT | *UD2D120A9V5+RP | 36,200 | $1,810 |
| No | 211289056 | TRANE | 4TWV8X48A1 | 4PX*DD60BS3+HORIZ-RT | *UD2C100ACV5 | 36,200 | $1,810 |
| No | 211596939 | TRANE | 4TWV8X48A1 | 4PX*DD60BS3+HORIZ-RT | *UD2C080ACV4 | 35,400 | $1,770 |
| No | 210653677 | TRANE | 4TWV8X48A1 | 4PX*DD60BS3 | S9V2D120D5PSB+RP | 36,800 | $1,840 |
| No | 210653676 | TRANE | 4TWV8X48A1 | 4PX*DD60BS3 | S9V2C100D5PSB+RP | 35,800 | $1,790 |
| No | 207526486 | TRANE | 4TWV8X48A1 | 4PX*DD60BS3 | S9V2C100D4VSA+RP | 35,600 | $1,780 |
| No | 211081268 | TRANE | 4TWV8X48A1 | 4PX*DD60BS3 | S8V2D120M5PDA | 37,000 | $1,850 |
| No | 210691908 | TRANE | 4TWV8X48A1 | 4PX*DD60BS3 | S8V2D120M5PCA | 37,000 | $1,850 |
| No | 211081269 | TRANE | 4TWV8X48A1 | 4PX*DD60BS3 | S8V2C100M5PDA | 36,000 | $1,800 |
| No | 210691907 | TRANE | 4TWV8X48A1 | 4PX*DD60BS3 | S8V2C100M5PCA | 36,000 | $1,800 |
| No | 207526316 | TRANE | 4TWV8X48A1 | 4PX*DD60BS3 | *DHMC100ACV4 | 35,600 | $1,780 |
| No | 207526314 | TRANE | 4TWV8X48A1 | 4PX*DD60BS3 | *DD2D120ACV5 | 36,400 | $1,820 |
| No | 210641000 | TRANE | 4TWV8X48A1 | 4PX*DD60BS3 | *DD2D120A9V5+RP | 36,600 | $1,830 |
| No | 207805607 | TRANE | 4TWV8X48A1 | 4PX*CU60BS3+P0V0C000M50SC+RP | N/A | 36,600 | $1,830 |
| No | 208121978 | TRANE | 4TWV8X48A1 | 4PX*CU60BS3 | S9V2C100U5PSB+RP | 37,000 | $1,850 |
| No | 207526483 | TRANE | 4TWV8X48A1 | 4PX*CU60BS3 | S9V2C100U4VSA+RP | 37,000 | $1,850 |
| No | 210653673 | TRANE | 4TWV8X48A1 | 4PX*CU60BS3 | S9V2C100U4PSB+RP | 37,000 | $1,850 |
| No | 210653674 | TRANE | 4TWV8X48A1 | 4PX*CU60BS3 | S9V2C080U5PSB+RP | 37,000 | $1,850 |
| No | 211081267 | TRANE | 4TWV8X48A1 | 4PX*CU60BS3 | S8V2C100M5PDA | 37,200 | $1,860 |
| No | 210691906 | TRANE | 4TWV8X48A1 | 4PX*CU60BS3 | S8V2C100M5PCA | 37,200 | $1,860 |
| No | 211081266 | TRANE | 4TWV8X48A1 | 4PX*CU60BS3 | S8V2C080M5PDA | 37,000 | $1,850 |
| No | 210691905 | TRANE | 4TWV8X48A1 | 4PX*CU60BS3 | S8V2C080M5PCA | 37,000 | $1,850 |
| No | 207526901 | TRANE | 4TWV8X48A1 | 4PX*CU60BS3 | L8V1C100U5VSA+RP | 36,800 | $1,840 |
| No | 210640997 | TRANE | 4TWV8X48A1 | 4PX*CU60BS3 | *UD2C100B9V5+RP | 37,000 | $1,850 |
| No | 207526269 | TRANE | 4TWV8X48A1 | 4PX*CU60BS3 | *UD2C100ACV5 | 37,400 | $1,870 |
| No | 210640999 | TRANE | 4TWV8X48A1 | 4PX*CU60BS3 | *UD2C100A9V5+RP | 36,800 | $1,840 |
| No | 210640996 | TRANE | 4TWV8X48A1 | 4PX*CU60BS3 | *UD2C080B9V4+RP | 36,800 | $1,840 |
| No | 207526270 | TRANE | 4TWV8X48A1 | 4PX*CU60BS3 | *UD2C080ACV4 | 36,600 | $1,830 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210640998 | TRANE | 4TWV8X48A1 | 4PX*CU60BS3 | *UD2C080A9V4+RP | 37,200 | $1,860 |
| No | 207805606 | TRANE | 4TWV8X48A1 | 4PX*CU48BS3+P0V0C000M50SC+RP | N/A | 37,200 | $1,860 |
| No | 210653671 | TRANE | 4TWV8X48A1 | 4PX*CU48BS3 | S9V2C100U5PSB+RP | 37,400 | $1,870 |
| No | 207526481 | TRANE | 4TWV8X48A1 | 4PX*CU48BS3 | S9V2C100U4VSA+RP | 37,400 | $1,870 |
| No | 207599983 | TRANE | 4TWV8X48A1 | 4PX*CU48BS3 | S9V2C100U4PSB+RP | 37,400 | $1,870 |
| No | 207526522 | TRANE | 4TWV8X48A1 | 4PX*CU48BS3 | S9V2C100D5PSB+RP | 36,400 | $1,820 |
| No | 210653859 | TRANE | 4TWV8X48A1 | 4PX*CU48BS3 | S9V2C100D4VSA+RP | 36,400 | $1,820 |
| No | 207526521 | TRANE | 4TWV8X48A1 | 4PX*CU48BS3 | S9V2C100D4PSB+RP | 36,400 | $1,820 |
| No | 210653672 | TRANE | 4TWV8X48A1 | 4PX*CU48BS3 | S9V2C080U5PSB+RP | 37,400 | $1,870 |
| No | 211081265 | TRANE | 4TWV8X48A1 | 4PX*CU48BS3 | S8V2C100M5PDA | 37,600 | $1,880 |
| No | 210691903 | TRANE | 4TWV8X48A1 | 4PX*CU48BS3 | S8V2C100M5PCA | 37,600 | $1,880 |
| No | 211081264 | TRANE | 4TWV8X48A1 | 4PX*CU48BS3 | S8V2C080M5PDA | 37,400 | $1,870 |
| No | 210691904 | TRANE | 4TWV8X48A1 | 4PX*CU48BS3 | S8V2C080M5PCA | 37,400 | $1,870 |
| No | 207526900 | TRANE | 4TWV8X48A1 | 4PX*CU48BS3 | L8V1C100U5VSA+RP | 37,400 | $1,870 |
| No | 210640992 | TRANE | 4TWV8X48A1 | 4PX*CU48BS3 | *UD2C100B9V5+RP | 37,400 | $1,870 |
| No | 207526265 | TRANE | 4TWV8X48A1 | 4PX*CU48BS3 | *UD2C100ACV5 | 37,800 | $1,890 |
| No | 210640994 | TRANE | 4TWV8X48A1 | 4PX*CU48BS3 | *UD2C100A9V5+RP | 37,200 | $1,860 |
| No | 210640993 | TRANE | 4TWV8X48A1 | 4PX*CU48BS3 | *UD2C080B9V4+RP | 37,000 | $1,850 |
| No | 207526267 | TRANE | 4TWV8X48A1 | 4PX*CU48BS3 | *UD2C080ACV4 | 37,200 | $1,860 |
| No | 210640995 | TRANE | 4TWV8X48A1 | 4PX*CU48BS3 | *UD2C080A9V4+RP | 37,600 | $1,880 |
| No | 210653858 | TRANE | 4TWV8X48A1 | 4PX*CU48BS3 | *DHMC100ACV4 | 36,200 | $1,810 |
| No | 207805605 | TRANE | 4TWV8X48A1 | 4PX*CU42BS3+P0V0C000M50SC+RP | N/A | 37,400 | $1,870 |
| No | 210653666 | TRANE | 4TWV8X48A1 | 4PX*CU42BS3 | S9V2C100U5PSB+RP | 37,800 | $1,890 |
| No | 210653667 | TRANE | 4TWV8X48A1 | 4PX*CU42BS3 | S9V2C100U4VSA+RP | 37,600 | $1,880 |
| No | 210653668 | TRANE | 4TWV8X48A1 | 4PX*CU42BS3 | S9V2C100U4PSB+RP | 37,600 | $1,880 |
| No | 210653670 | TRANE | 4TWV8X48A1 | 4PX*CU42BS3 | S9V2C080U5PSB+RP | 37,800 | $1,890 |
| No | 211081263 | TRANE | 4TWV8X48A1 | 4PX*CU42BS3 | S8V2C100M5PDA | 38,000 | $1,900 |
| No | 210691902 | TRANE | 4TWV8X48A1 | 4PX*CU42BS3 | S8V2C100M5PCA | 38,000 | $1,900 |
| No | 210653669 | TRANE | 4TWV8X48A1 | 4PX*CU42BS3 | L8V1C100U5VSA+RP | 37,600 | $1,880 |
| No | 210640989 | TRANE | 4TWV8X48A1 | 4PX*CU42BS3 | *UD2C100B9V5+RP | 37,800 | $1,890 |
| No | 211596938 | TRANE | 4TWV8X48A1 | 4PX*CU42BS3 | *UD2C100ACV5 | 37,800 | $1,890 |
| No | 210640990 | TRANE | 4TWV8X48A1 | 4PX*CU42BS3 | *UD2C080B9V4+RP | 37,200 | $1,860 |
| No | 211596937 | TRANE | 4TWV8X48A1 | 4PX*CU42BS3 | *UD2C080ACV4 | 37,400 | $1,870 |
| No | 210640987 | TRANE | 4TWV8X48A1 | 4PX*CU42BS3 | *UD2C080A9V4+RP | 38,000 | $1,900 |
| No | 207805603 | TRANE | 4TWV8X48A1 | 4PX*CD60BS3+P0V0C000M50SC+RP | N/A | 36,600 | $1,830 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211289055 | TRANE | 4TWV8X48A1 | 4PX*CD60BS3+HORIZ-RT | *UD2C100ACV5 | 37,200 | $1,860 |
| No | 210640985 | TRANE | 4TWV8X48A1 | 4PX*CD60BS3+HORIZ-RT | *UD2C080B9V4+RP | 36,600 | $1,830 |
| No | 211596936 | TRANE | 4TWV8X48A1 | 4PX*CD60BS3+HORIZ-RT | *UD2C080ACV4 | 36,600 | $1,830 |
| No | 209449882 | TRANE | 4TWV8X48A1 | 4PX*CD60BS3 | S9V2C100D5PSB+RP | 37,000 | $1,850 |
| No | 207526480 | TRANE | 4TWV8X48A1 | 4PX*CD60BS3 | S9V2C100D4VSA+RP | 36,800 | $1,840 |
| No | 211081261 | TRANE | 4TWV8X48A1 | 4PX*CD60BS3 | S8V2C100M5PDA | 37,200 | $1,860 |
| No | 210691900 | TRANE | 4TWV8X48A1 | 4PX*CD60BS3 | S8V2C100M5PCA | 37,200 | $1,860 |
| No | 211081260 | TRANE | 4TWV8X48A1 | 4PX*CD60BS3 | S8V2C080M5PDA | 37,000 | $1,850 |
| No | 210691899 | TRANE | 4TWV8X48A1 | 4PX*CD60BS3 | S8V2C080M5PCA | 37,000 | $1,850 |
| No | 207526264 | TRANE | 4TWV8X48A1 | 4PX*CD60BS3 | *DHMC100ACV4 | 36,800 | $1,840 |
| No | 210640982 | TRANE | 4TWV8X48A1 | 4PX*CD60BS3 | *DD2C100A9V5+RP | 36,800 | $1,840 |
| No | 210653655 | TRANE | 4TWV8X48A1 | 4PX*BU48BS3 | S9V2B080U4VSA+RP | 37,800 | $1,890 |
| No | 207599981 | TRANE | 4TWV8X48A1 | 4PX*BU48BS3 | S9V2B080U4PSB+RP | 37,800 | $1,890 |
| No | 210653857 | TRANE | 4TWV8X48A1 | 4PX*BU48BS3 | S9V2B080D4VSA+RP | 36,600 | $1,830 |
| No | 207526550 | TRANE | 4TWV8X48A1 | 4PX*BU48BS3 | S9V2B080D4PSB+RP | 36,600 | $1,830 |
| No | 211081259 | TRANE | 4TWV8X48A1 | 4PX*BU48BS3 | S8V2B080M4PDA | 37,400 | $1,870 |
| No | 210691897 | TRANE | 4TWV8X48A1 | 4PX*BU48BS3 | S8V2B080M4PCA | 37,400 | $1,870 |
| No | 211081258 | TRANE | 4TWV8X48A1 | 4PX*BU48BS3 | S8V2B060M4PDA | 37,400 | $1,870 |
| No | 210691898 | TRANE | 4TWV8X48A1 | 4PX*BU48BS3 | S8V2B060M4PCA | 37,400 | $1,870 |
| No | 210653656 | TRANE | 4TWV8X48A1 | 4PX*BU48BS3 | L8V1B080U4VSA+RP | 37,400 | $1,870 |
| No | 207526354 | TRANE | 4TWV8X36A1 | TEM8A0C42V41+TDR | N/A | 26,200 | $1,310 |
| No | 207526353 | TRANE | 4TWV8X36A1 | TEM8A0C36V31+TDR | N/A | 26,200 | $1,310 |
| No | 207526352 | TRANE | 4TWV8X36A1 | TEM8A0B30V31+TDR | N/A | 26,600 | $1,330 |
| No | 210929569 | TRANE | 4TWV8X36A1 | TAMXB0C36V31 | N/A | 25,800 | $1,290 |
| No | 210929568 | TRANE | 4TWV8X36A1 | TAMXB0B30V31 | N/A | 26,200 | $1,310 |
| No | 207690038 | TRANE | 4TWV8X36A1 | TAMXA0B30V31 | N/A | 26,200 | $1,310 |
| No | 207526331 | TRANE | 4TWV8X36A1 | TAM9A0C36V31 | N/A | 25,800 | $1,290 |
| No | 207526330 | TRANE | 4TWV8X36A1 | TAM9A0B30V31 | N/A | 26,200 | $1,310 |
| No | 207526476 | TRANE | 4TWV8X36A1 | 4TXCC005DS3 | S9V2C100U4VSA+RP | 25,800 | $1,290 |
| No | 208185408 | TRANE | 4TWV8X36A1 | 4TXCC005DS3 | S9V2C100U4PSB+RP | 25,800 | $1,290 |
| No | 210653650 | TRANE | 4TWV8X36A1 | 4TXCC005DS3 | S9V2C100D4VSA+RP | 25,400 | $1,270 |
| No | 210653652 | TRANE | 4TWV8X36A1 | 4TXCC005DS3 | S9V2C100D4PSB+RP | 25,400 | $1,270 |
| No | 211081257 | TRANE | 4TWV8X36A1 | 4TXCC005DS3 | S8V2C100M5PDA | 26,200 | $1,310 |
| No | 210691896 | TRANE | 4TWV8X36A1 | 4TXCC005DS3 | S8V2C100M5PCA | 26,200 | $1,310 |
| No | 210640975 | TRANE | 4TWV8X36A1 | 4TXCC005DS3 | *UD2C100B9V5+RP | 25,800 | $1,290 |
| No | 207526288 | TRANE | 4TWV8X36A1 | 4TXCC005DS3 | *UD2C100ACV5 | 26,400 | $1,320 |
| No | 210640974 | TRANE | 4TWV8X36A1 | 4TXCC005DS3 | *UD2C100A9V5+RP | 26,200 | $1,310 |
| No | 210640973 | TRANE | 4TWV8X36A1 | 4TXCC005DS3 | *UD2C080B9V4+RP | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207526286 | TRANE | 4TWV8X36A1 | 4TXCC005DS3 | *UD2C080ACV4 | 26,000 | $1,300 |
| No | 210640972 | TRANE | 4TWV8X36A1 | 4TXCC005DS3 | *UD2C080A9V4+RP | 25,800 | $1,290 |
| No | 210653651 | TRANE | 4TWV8X36A1 | 4TXCC005DS3 | *DHMC100ACV4 | 25,600 | $1,280 |
| No | 211596935 | TRANE | 4TWV8X36A1 | 4TXCC005DS3 | *DD2C100ACV5 | 25,600 | $1,280 |
| No | 210640976 | TRANE | 4TWV8X36A1 | 4TXCC005DS3 | *DD2C100A9V5+RP | 25,200 | $1,260 |
| No | 211081254 | TRANE | 4TWV8X36A1 | 4TXCB006DS3 | S8V2B080M4PDA | 26,600 | $1,330 |
| No | 210691894 | TRANE | 4TWV8X36A1 | 4TXCB006DS3 | S8V2B080M4PCA | 26,600 | $1,330 |
| No | 211081253 | TRANE | 4TWV8X36A1 | 4TXCB006DS3 | S8V2B060M4PDA | 26,600 | $1,330 |
| No | 210691893 | TRANE | 4TWV8X36A1 | 4TXCB006DS3 | S8V2B060M4PCA | 26,600 | $1,330 |
| No | 211081255 | TRANE | 4TWV8X36A1 | 4TXCB006DS3 | S8V2A040M3PDA | 25,200 | $1,260 |
| No | 210691892 | TRANE | 4TWV8X36A1 | 4TXCB006DS3 | S8V2A040M3PCA | 25,200 | $1,260 |
| No | 210653649 | TRANE | 4TWV8X36A1 | 4TXCB006DS3 | L8V1B080U4VSA+RP | 26,600 | $1,330 |
| No | 210653648 | TRANE | 4TWV8X36A1 | 4TXCB006DS3 | L8V1A060U3VSA+RP | 25,400 | $1,270 |
| No | 210653647 | TRANE | 4TWV8X36A1 | 4TXCB006DS3 | L8V1A040U3VSA+RP | 25,400 | $1,270 |
| No | 209459221 | TRANE | 4TWV8X36A1 | 4TXCB006DS3 | *UD2B080ACV3 | 26,000 | $1,300 |
| No | 211596934 | TRANE | 4TWV8X36A1 | 4TXCB006DS3 | *UD2B060ACV3 | 26,200 | $1,310 |
| No | 210640970 | TRANE | 4TWV8X36A1 | 4TXCB006DS3 | *UD2B060A9V3+RP | 26,000 | $1,300 |
| No | 207526675 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | S9V2B080U4VSA+RP | 25,800 | $1,290 |
| No | 210653639 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | S9V2B080U4PSB+RP | 26,000 | $1,300 |
| No | 210653645 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | S9V2B080D4PSB+RP | 25,600 | $1,280 |
| No | 207526470 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | S9V2B060U3VSA+RP | 26,000 | $1,300 |
| No | 208185403 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | S9V2B060U3PSB+RP | 26,000 | $1,300 |
| No | 207526471 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | S9V2B040U3VSA+RP | 26,000 | $1,300 |
| No | 208185404 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | S9V2B040U3PSB+RP | 26,000 | $1,300 |
| No | 210653641 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | S9V2B040D3PSB+RP | 25,600 | $1,280 |
| No | 211081252 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | S8V2B080M4PDA | 26,400 | $1,320 |
| No | 210691890 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | S8V2B080M4PCA | 26,400 | $1,320 |
| No | 211081251 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | S8V2B060M4PDA | 26,200 | $1,310 |
| No | 210691889 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | S8V2B060M4PCA | 26,200 | $1,310 |
| No | 211081250 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | S8V2A040M3PDA | 25,000 | $1,250 |
| No | 210691891 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | S8V2A040M3PCA | 25,000 | $1,250 |
| No | 210653638 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | L8V1B080U4VSA+RP | 26,400 | $1,320 |
| No | 210653637 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | L8V1A060U3VSA+RP | 25,000 | $1,250 |
| No | 210653636 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | L8V1A040U3VSA+RP | 24,800 | $1,240 |
| No | 207526280 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | *UHMB080ACV3 | 25,800 | $1,290 |
| No | 207526281 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | *UHMB060ACV3 | 26,000 | $1,300 |
| No | 207526279 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | *UD2B080ACV3 | 25,600 | $1,280 |
| No | 207526282 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | *UD2B060ACV3 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210653640 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | *DHMB080ACV3 | 25,400 | $1,270 |
| No | 211596933 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | *DD2B080ACV3 | 25,600 | $1,280 |
| No | 211596932 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | *DD2B060ACV3 | 25,800 | $1,290 |
| No | 210640969 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | *DD2B060A9V3+RP | 25,600 | $1,280 |
| No | 210640966 | TRANE | 4TWV8X36A1 | 4PX*DU48BS3 | *DD2D120A9V5+RP | 25,200 | $1,260 |
| No | 207526469 | TRANE | 4TWV8X36A1 | 4PX*CU48BS3 | S9V2C100U4VSA+RP | 26,000 | $1,300 |
| No | 210653634 | TRANE | 4TWV8X36A1 | 4PX*CU48BS3 | S9V2C100U4PSB+RP | 26,000 | $1,300 |
| No | 210653633 | TRANE | 4TWV8X36A1 | 4PX*CU48BS3 | S9V2C100D4VSA+RP | 25,400 | $1,270 |
| No | 207526520 | TRANE | 4TWV8X36A1 | 4PX*CU48BS3 | S9V2C100D4PSB+RP | 25,400 | $1,270 |
| No | 211081249 | TRANE | 4TWV8X36A1 | 4PX*CU48BS3 | S8V2C100M5PDA | 26,400 | $1,320 |
| No | 210691887 | TRANE | 4TWV8X36A1 | 4PX*CU48BS3 | S8V2C100M5PCA | 26,400 | $1,320 |
| No | 211081248 | TRANE | 4TWV8X36A1 | 4PX*CU48BS3 | S8V2C080M5PDA | 26,200 | $1,310 |
| No | 210691888 | TRANE | 4TWV8X36A1 | 4PX*CU48BS3 | S8V2C080M5PCA | 26,200 | $1,310 |
| No | 210640964 | TRANE | 4TWV8X36A1 | 4PX*CU48BS3 | *UD2C100B9V5+RP | 26,000 | $1,300 |
| No | 207526260 | TRANE | 4TWV8X36A1 | 4PX*CU48BS3 | *UD2C100ACV5 | 26,400 | $1,320 |
| No | 210640963 | TRANE | 4TWV8X36A1 | 4PX*CU48BS3 | *UD2C100A9V5+RP | 26,200 | $1,310 |
| No | 210640962 | TRANE | 4TWV8X36A1 | 4PX*CU48BS3 | *UD2C080B9V4+RP | 26,000 | $1,300 |
| No | 207526257 | TRANE | 4TWV8X36A1 | 4PX*CU48BS3 | *UD2C080ACV4 | 26,000 | $1,300 |
| No | 210640961 | TRANE | 4TWV8X36A1 | 4PX*CU48BS3 | *UD2C080A9V4+RP | 26,000 | $1,300 |
| No | 210653635 | TRANE | 4TWV8X36A1 | 4PX*CU48BS3 | *DHMC100ACV4 | 25,800 | $1,290 |
| No | 207526519 | TRANE | 4TWV8X36A1 | 4PX*CU48BS3 | *DD2C100ACV5 | 25,400 | $1,270 |
| No | 210640965 | TRANE | 4TWV8X36A1 | 4PX*CU48BS3 | *DD2C100A9V5+RP | 25,400 | $1,270 |
| No | 210653631 | TRANE | 4TWV8X36A1 | 4PX*CU42BS3 | S9V2C100U4VSA+RP | 26,200 | $1,310 |
| No | 210653630 | TRANE | 4TWV8X36A1 | 4PX*CU42BS3 | S9V2C100U4PSB+RP | 26,200 | $1,310 |
| No | 210653632 | TRANE | 4TWV8X36A1 | 4PX*CU42BS3 | S9V2C100D4VSA+RP | 25,600 | $1,280 |
| No | 210653629 | TRANE | 4TWV8X36A1 | 4PX*CU42BS3 | S9V2C100D4PSB+RP | 25,600 | $1,280 |
| No | 211081247 | TRANE | 4TWV8X36A1 | 4PX*CU42BS3 | S8V2C100M5PDA | 26,600 | $1,330 |
| No | 210691886 | TRANE | 4TWV8X36A1 | 4PX*CU42BS3 | S8V2C100M5PCA | 26,600 | $1,330 |
| No | 211081246 | TRANE | 4TWV8X36A1 | 4PX*CU42BS3 | S8V2C080M5PDA | 26,400 | $1,320 |
| No | 210691885 | TRANE | 4TWV8X36A1 | 4PX*CU42BS3 | S8V2C080M5PCA | 26,400 | $1,320 |
| No | 210640959 | TRANE | 4TWV8X36A1 | 4PX*CU42BS3 | *UD2C100B9V5+RP | 26,200 | $1,310 |
| No | 211289054 | TRANE | 4TWV8X36A1 | 4PX*CU42BS3 | *UD2C100ACV5 | 26,600 | $1,330 |
| No | 210640958 | TRANE | 4TWV8X36A1 | 4PX*CU42BS3 | *UD2C100A9V5+RP | 26,400 | $1,320 |
| No | 210640957 | TRANE | 4TWV8X36A1 | 4PX*CU42BS3 | *UD2C080B9V4+RP | 26,200 | $1,310 |
| No | 211596931 | TRANE | 4TWV8X36A1 | 4PX*CU42BS3 | *UD2C080ACV4 | 26,200 | $1,310 |
| No | 210640956 | TRANE | 4TWV8X36A1 | 4PX*CU42BS3 | *UD2C080A9V4+RP | 26,200 | $1,310 |
| No | 207526554 | TRANE | 4TWV8X36A1 | 4PX*CU42BS3 | *DHMC100ACV4 | 25,800 | $1,290 |
| No | 207526553 | TRANE | 4TWV8X36A1 | 4PX*CU42BS3 | *DD2C100ACV5 | 25,600 | $1,280 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210640960 | TRANE | 4TWV8X36A1 | 4PX*CU42BS3 | *DD2C100A9V5+RP | 25,400 | $1,270 |
| No | 207526468 | TRANE | 4TWV8X36A1 | 4PX*CU36BS3 | S9V2C100U4VSA+RP | 25,800 | $1,290 |
| No | 210653628 | TRANE | 4TWV8X36A1 | 4PX*CU36BS3 | S9V2C100U4PSB+RP | 25,600 | $1,280 |
| No | 211081245 | TRANE | 4TWV8X36A1 | 4PX*CU36BS3 | S8V2C100M5PDA | 26,200 | $1,310 |
| No | 210691883 | TRANE | 4TWV8X36A1 | 4PX*CU36BS3 | S8V2C100M5PCA | 26,200 | $1,310 |
| No | 211081244 | TRANE | 4TWV8X36A1 | 4PX*CU36BS3 | S8V2C080M5PDA | 25,800 | $1,290 |
| No | 210691884 | TRANE | 4TWV8X36A1 | 4PX*CU36BS3 | S8V2C080M5PCA | 25,800 | $1,290 |
| No | 210640955 | TRANE | 4TWV8X36A1 | 4PX*CU36BS3 | *UD2C100B9V5+RP | 25,600 | $1,280 |
| No | 207526256 | TRANE | 4TWV8X36A1 | 4PX*CU36BS3 | *UD2C100ACV5 | 26,000 | $1,300 |
| No | 210640954 | TRANE | 4TWV8X36A1 | 4PX*CU36BS3 | *UD2C100A9V5+RP | 26,000 | $1,300 |
| No | 210640953 | TRANE | 4TWV8X36A1 | 4PX*CU36BS3 | *UD2C080B9V4+RP | 25,800 | $1,290 |
| No | 207526255 | TRANE | 4TWV8X36A1 | 4PX*CU36BS3 | *UD2C080ACV4 | 25,600 | $1,280 |
| No | 210640952 | TRANE | 4TWV8X36A1 | 4PX*CU36BS3 | *UD2C080A9V4+RP | 25,800 | $1,290 |
| No | 207526548 | TRANE | 4TWV8X36A1 | 4PX*CD42BS3 | S9V2C100D4PSB+RP | 25,600 | $1,280 |
| No | 207526549 | TRANE | 4TWV8X36A1 | 4PX*CD42BS3 | *DD2C100ACV5 | 25,600 | $1,280 |
| No | 207526466 | TRANE | 4TWV8X36A1 | 4PX*CD36BS3 | S9V2C100D4VSA+RP | 26,400 | $1,320 |
| No | 210653622 | TRANE | 4TWV8X36A1 | 4PX*BU48BS3 | S9V2B080D4VSA+RP | 25,600 | $1,280 |
| No | 207526515 | TRANE | 4TWV8X36A1 | 4PX*BU48BS3 | S9V2B080D4PSB+RP | 25,600 | $1,280 |
| No | 210653623 | TRANE | 4TWV8X36A1 | 4PX*BU48BS3 | S9V2B080D3VSA+RP | 25,400 | $1,270 |
| No | 207526516 | TRANE | 4TWV8X36A1 | 4PX*BU48BS3 | S9V2B080D3PSB+RP | 25,400 | $1,270 |
| No | 207526517 | TRANE | 4TWV8X36A1 | 4PX*BU48BS3 | S9V2B060D3PSB+RP | 25,600 | $1,280 |
| No | 210653621 | TRANE | 4TWV8X36A1 | 4PX*BU48BS3 | S9V2B040D3PSB+RP | 25,800 | $1,290 |
| No | 210653624 | TRANE | 4TWV8X36A1 | 4PX*BU48BS3 | *DHMB080ACV3 | 25,400 | $1,270 |
| No | 207526513 | TRANE | 4TWV8X36A1 | 4PX*BU48BS3 | *DD2B080ACV3 | 25,600 | $1,280 |
| No | 210640940 | TRANE | 4TWV8X36A1 | 4PX*BU48BS3 | *DD2B080A9V3+RP | 25,400 | $1,270 |
| No | 211596928 | TRANE | 4TWV8X36A1 | 4PX*BU48BS3 | *DD2B060ACV3 | 26,000 | $1,300 |
| No | 210640941 | TRANE | 4TWV8X36A1 | 4PX*BU48BS3 | *DD2B060A9V3+RP | 25,200 | $1,260 |
| No | 210653617 | TRANE | 4TWV8X36A1 | 4PX*BU42BS3 | S9V2B080U4VSA+RP | 26,400 | $1,320 |
| No | 207526770 | TRANE | 4TWV8X36A1 | 4PX*BU42BS3 | S9V2B080U4PSB+RP | 26,400 | $1,320 |
| No | 210653615 | TRANE | 4TWV8X36A1 | 4PX*BU42BS3 | S9V2B060U3VSA+RP | 26,400 | $1,320 |
| No | 210653614 | TRANE | 4TWV8X36A1 | 4PX*BU42BS3 | S9V2B060U3PSB+RP | 26,400 | $1,320 |
| No | 210653613 | TRANE | 4TWV8X36A1 | 4PX*BU42BS3 | S9V2B040U3VSA+RP | 26,400 | $1,320 |
| No | 210653612 | TRANE | 4TWV8X36A1 | 4PX*BU42BS3 | S9V2B040U3PSB+RP | 26,400 | $1,320 |
| No | 211081239 | TRANE | 4TWV8X36A1 | 4PX*BU42BS3 | S8V2B080M4PDA | 26,800 | $1,340 |
| No | 210691878 | TRANE | 4TWV8X36A1 | 4PX*BU42BS3 | S8V2B080M4PCA | 26,800 | $1,340 |
| No | 211081238 | TRANE | 4TWV8X36A1 | 4PX*BU42BS3 | S8V2B060M4PDA | 26,800 | $1,340 |
| No | 210691877 | TRANE | 4TWV8X36A1 | 4PX*BU42BS3 | S8V2B060M4PCA | 26,800 | $1,340 |
| No | 210653616 | TRANE | 4TWV8X36A1 | 4PX*BU42BS3 | L8V1B080U4VSA+RP | 26,800 | $1,340 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210653620 | TRANE | 4TWV8X36A1 | 4PX*BU42BS3 | L8V1A060U3VSA+RP | 25,600 | $1,280 |
| No | 210653618 | TRANE | 4TWV8X36A1 | 4PX*BU42BS3 | *UHMB080ACV3 | 26,400 | $1,320 |
| No | 210653611 | TRANE | 4TWV8X36A1 | 4PX*BU42BS3 | *UHMB060ACV3 | 26,400 | $1,320 |
| No | 211596927 | TRANE | 4TWV8X36A1 | 4PX*BU42BS3 | *UD2B080ACV3 | 26,400 | $1,320 |
| No | 211596926 | TRANE | 4TWV8X36A1 | 4PX*BU42BS3 | *UD2B060ACV3 | 26,400 | $1,320 |
| No | 210640939 | TRANE | 4TWV8X36A1 | 4PX*BU42BS3 | *UD2B060A9V3+RP | 26,400 | $1,320 |
| No | 210653605 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | S9V2B080U4VSA+RP | 26,000 | $1,300 |
| No | 210653602 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | S9V2B080U4PSB+RP | 26,000 | $1,300 |
| No | 207526512 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | S9V2B080D3PSB+RP | 25,400 | $1,270 |
| No | 207526462 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | S9V2B060U3VSA+RP | 26,000 | $1,300 |
| No | 210653603 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | S9V2B060U3PSB+RP | 26,000 | $1,300 |
| No | 207526511 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | S9V2B060D3PSB+RP | 25,400 | $1,270 |
| No | 207526460 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | S9V2B040U3VSA+RP | 26,000 | $1,300 |
| No | 210653604 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | S9V2B040U3PSB+RP | 26,000 | $1,300 |
| No | 207526547 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | S9V2B040D3PSB+RP | 25,600 | $1,280 |
| No | 211081236 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | S8V2B080M4PDA | 26,400 | $1,320 |
| No | 210691875 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | S8V2B080M4PCA | 26,400 | $1,320 |
| No | 211081235 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | S8V2B060M4PDA | 26,400 | $1,320 |
| No | 210691873 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | S8V2B060M4PCA | 26,400 | $1,320 |
| No | 211081234 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | S8V2A040M3PDA | 25,000 | $1,250 |
| No | 210691874 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | S8V2A040M3PCA | 25,000 | $1,250 |
| No | 210653601 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | L8V1B080U4VSA+RP | 26,400 | $1,320 |
| No | 210653606 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | L8V1A060U3VSA+RP | 25,000 | $1,250 |
| No | 207526241 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | *UHMB080ACV3 | 26,000 | $1,300 |
| No | 207526244 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | *UHMB060ACV3 | 26,000 | $1,300 |
| No | 207526243 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | *UD2B080ACV3 | 25,800 | $1,290 |
| No | 207526242 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | *UD2B060ACV3 | 25,800 | $1,290 |
| No | 210653600 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | *DHMB080ACV3 | 25,400 | $1,270 |
| No | 211596925 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | *DD2B080ACV3 | 25,400 | $1,270 |
| No | 210640935 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | *DD2B080A9V3+RP | 25,600 | $1,280 |
| No | 211596924 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | *DD2B060ACV3 | 25,800 | $1,290 |
| No | 210640934 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | *DD2B060A9V3+RP | 25,600 | $1,280 |
| No | 207526545 | TRANE | 4TWV8X36A1 | 4PX*BD42BS3 | S9V2B080D4PSB+RP | 26,000 | $1,300 |
| No | 207526546 | TRANE | 4TWV8X36A1 | 4PX*BD42BS3 | S9V2B080D3PSB+RP | 25,800 | $1,290 |
| No | 207526544 | TRANE | 4TWV8X36A1 | 4PX*BD42BS3 | S9V2B060D3PSB+RP | 25,800 | $1,290 |
| No | 207526542 | TRANE | 4TWV8X36A1 | 4PX*BD42BS3 | S9V2B040D3PSB+RP | 26,000 | $1,300 |
| No | 207526543 | TRANE | 4TWV8X36A1 | 4PX*BD42BS3 | *DD2B080ACV3 | 25,800 | $1,290 |
| No | 207526896 | TRANE | 4TWV8X36A1 | 4PX*BD42BS3 | *DD2B060ACV3 | 26,000 | $1,300 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207526351 | TRANE | 4TWV8X24A1 | TEM8A0B30V31+TDR | N/A | 16,700 | $835 |
| No | 211596920 | TRANE | 4TWV8X24A1 | TEM8A0B24V21+TDR | N/A | 17,600 | $880 |
| No | 211015538 | TRANE | 4TWV8X24A1 | TAMXB0B30V31 | N/A | 17,100 | $855 |
| No | 207526329 | TRANE | 4TWV8X24A1 | TAM9A0B30V31 | N/A | 17,100 | $855 |
| No | 207526224 | TRANE | 4TWV8X24A1 | 4TXFH024CZ3 | *DHMB080ACV3 | 16,800 | $840 |
| No | 207526220 | TRANE | 4TWV8X24A1 | 4TXFH024CZ3 | *DHMB060BCV3 | 16,800 | $840 |
| No | 207526219 | TRANE | 4TWV8X24A1 | 4TXFH024CZ3 | *DD2B060ACV3 | 16,800 | $840 |
| No | 211092929 | TRANE | 4TWV8X24A1 | 4TXCB004DS3 | S8V2B080M4PDA | 17,100 | $855 |
| No | 211092899 | TRANE | 4TWV8X24A1 | 4TXCB004DS3 | S8V2B080M4PCA | 17,100 | $855 |
| No | 211081228 | TRANE | 4TWV8X24A1 | 4TXCB004DS3 | S8V2B060M4PDA | 17,100 | $855 |
| No | 210691863 | TRANE | 4TWV8X24A1 | 4TXCB004DS3 | S8V2B060M4PCA | 17,100 | $855 |
| No | 211092930 | TRANE | 4TWV8X24A1 | 4TXCB004DS3 | S8V2A040M3PDA | 16,300 | $815 |
| No | 211092900 | TRANE | 4TWV8X24A1 | 4TXCB004DS3 | S8V2A040M3PCA | 16,300 | $815 |
| No | 210653595 | TRANE | 4TWV8X24A1 | 4TXCB004DS3 | L8V1B080U4VSA+RP | 17,000 | $850 |
| No | 210653594 | TRANE | 4TWV8X24A1 | 4TXCB004DS3 | L8V1A040U3VSA+RP | 16,600 | $830 |
| No | 211596919 | TRANE | 4TWV8X24A1 | 4TXCB004DS3 | *UHMB080ACV3 | 16,800 | $840 |
| No | 210640927 | TRANE | 4TWV8X24A1 | 4TXCB004DS3 | *UD2B080A9V3+RP | 16,900 | $845 |
| No | 210640926 | TRANE | 4TWV8X24A1 | 4TXCB004DS3 | *UD2B060A9V3+RP | 17,000 | $850 |
| No | 210653591 | TRANE | 4TWV8X24A1 | 4TXCB003DS3 | S9V2B040U3VSA+RP | 17,900 | $895 |
| No | 210653590 | TRANE | 4TWV8X24A1 | 4TXCB003DS3 | S9V2B040U3PSB+RP | 17,900 | $895 |
| No | 211081227 | TRANE | 4TWV8X24A1 | 4TXCB003DS3 | S8V2B080M4PDA | 18,000 | $900 |
| No | 210691859 | TRANE | 4TWV8X24A1 | 4TXCB003DS3 | S8V2B080M4PCA | 18,000 | $900 |
| No | 211081226 | TRANE | 4TWV8X24A1 | 4TXCB003DS3 | S8V2B060M4PDA | 17,900 | $895 |
| No | 210691857 | TRANE | 4TWV8X24A1 | 4TXCB003DS3 | S8V2B060M4PCA | 17,900 | $895 |
| No | 210653586 | TRANE | 4TWV8X24A1 | 4TXCB003DS3 | *UHMB080ACV3 | 17,700 | $885 |
| No | 210653581 | TRANE | 4TWV8X24A1 | 4PX*BU36BS3 | S9V2B080D3PSB+RP | 16,700 | $835 |
| No | 211596917 | TRANE | 4TWV8X24A1 | 4PX*BU36BS3 | S9V2B060U3PSB+RP | 16,900 | $845 |
| No | 207526392 | TRANE | 4TWV8X24A1 | 4PX*BU36BS3 | S9V2B040U3PSB+RP | 17,000 | $850 |
| No | 211092928 | TRANE | 4TWV8X24A1 | 4PX*BU36BS3 | S8V2B080M4PDA | 17,100 | $855 |
| No | 211092897 | TRANE | 4TWV8X24A1 | 4PX*BU36BS3 | S8V2B080M4PCA | 17,100 | $855 |
| No | 211092926 | TRANE | 4TWV8X24A1 | 4PX*BU36BS3 | S8V2A040M3PDA | 16,300 | $815 |
| No | 211092898 | TRANE | 4TWV8X24A1 | 4PX*BU36BS3 | S8V2A040M3PCA | 16,300 | $815 |
| No | 210653582 | TRANE | 4TWV8X24A1 | 4PX*BU36BS3 | L8V1B080U4VSA+RP | 17,000 | $850 |
| No | 210653580 | TRANE | 4TWV8X24A1 | 4PX*BU36BS3 | L8V1A060U3VSA+RP | 16,500 | $825 |
| No | 207526234 | TRANE | 4TWV8X24A1 | 4PX*BU36BS3 | *UHMB080ACV3 | 16,800 | $840 |
| No | 210640923 | TRANE | 4TWV8X24A1 | 4PX*BU36BS3 | *UD2B080A9V3+RP | 16,900 | $845 |
| No | 210640924 | TRANE | 4TWV8X24A1 | 4PX*BU36BS3 | *UD2B060A9V3+RP | 17,000 | $850 |
| No | 207820947 | TRANE | 4TWV0X60A1 | TEM8B0C60V51+TDR | N/A | 48,500 | $2,425 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207526350 | TRANE | 4TWV0X60A1 | TEM8A0D60V51+TDR | N/A | 48,000 | $2,400 |
| No | 207526349 | TRANE | 4TWV0X60A1 | TEM8A0D48V41+TDR | N/A | 48,500 | $2,425 |
| No | 207708987 | TRANE | 4TWV0X60A1 | TEM8A0C48V41+TDR | N/A | 48,500 | $2,425 |
| No | 211081224 | TRANE | 4TWV0X60A1 | 4TXCD010DS3 | S8V2D120M5PDA | 49,500 | $2,475 |
| No | 210691855 | TRANE | 4TWV0X60A1 | 4TXCD010DS3 | S8V2D120M5PCA | 49,500 | $2,475 |
| No | 211081220 | TRANE | 4TWV0X60A1 | 4PX*DU60BS3 | S8V2D120M5PDA | 49,500 | $2,475 |
| No | 210691852 | TRANE | 4TWV0X60A1 | 4PX*DU60BS3 | S8V2D120M5PCA | 49,500 | $2,475 |
| No | 207820945 | TRANE | 4TWV0X48A1 | TEM8B0C60V51+TDR | N/A | 36,000 | $1,800 |
| No | 207526347 | TRANE | 4TWV0X48A1 | TEM8A0D60V51+TDR | N/A | 35,800 | $1,790 |
| No | 207526346 | TRANE | 4TWV0X48A1 | TEM8A0D48V41+TDR | N/A | 36,200 | $1,810 |
| No | 207526344 | TRANE | 4TWV0X48A1 | TEM8A0C48V41+TDR | N/A | 36,000 | $1,800 |
| No | 207526343 | TRANE | 4TWV0X48A1 | TEM8A0C42V41+TDR | N/A | 36,000 | $1,800 |
| No | 210929566 | TRANE | 4TWV0X48A1 | TAMXB0C60V51 | N/A | 35,200 | $1,760 |
| No | 210929565 | TRANE | 4TWV0X48A1 | TAMXB0C48V41 | N/A | 35,200 | $1,760 |
| No | 207690035 | TRANE | 4TWV0X48A1 | TAMXA0C60V51 | N/A | 35,200 | $1,760 |
| No | 207526327 | TRANE | 4TWV0X48A1 | TAM9A0C60V51 | N/A | 35,200 | $1,760 |
| No | 207526326 | TRANE | 4TWV0X48A1 | TAM9A0C48V41 | N/A | 35,200 | $1,760 |
| No | 207526557 | TRANE | 4TWV0X48A1 | 4TXFH064AZ3 | *UD2C080ACV4 | 35,800 | $1,790 |
| No | 207805579 | TRANE | 4TWV0X48A1 | 4TXCD010DS3+P0V0D000M50SC+RP | N/A | 35,800 | $1,790 |
| No | 207805578 | TRANE | 4TWV0X48A1 | 4TXCD010DS3+P0V0C000M50SC+RP | N/A | 34,800 | $1,740 |
| No | 207526445 | TRANE | 4TWV0X48A1 | 4TXCD010DS3 | S9V2D120U5VSA+RP | 36,200 | $1,810 |
| No | 208185426 | TRANE | 4TWV0X48A1 | 4TXCD010DS3 | S9V2D120U5PSB+RP | 36,200 | $1,810 |
| No | 210653848 | TRANE | 4TWV0X48A1 | 4TXCD010DS3 | S9V2D120D5PSB+RP | 35,000 | $1,750 |
| No | 207526446 | TRANE | 4TWV0X48A1 | 4TXCD010DS3 | S9V2C100U4VSA+RP | 35,200 | $1,760 |
| No | 211088963 | TRANE | 4TWV0X48A1 | 4TXCD010DS3 | S8V2D120M5PDA | 36,400 | $1,820 |
| No | 210692183 | TRANE | 4TWV0X48A1 | 4TXCD010DS3 | S8V2D120M5PCA | 36,400 | $1,820 |
| No | 207559010 | TRANE | 4TWV0X48A1 | 4TXCD010DS3 | *UHMD120ACV5 | 35,800 | $1,790 |
| No | 211596915 | TRANE | 4TWV0X48A1 | 4TXCD010DS3 | *UD2D120B9V5+RP | 36,200 | $1,810 |
| No | 207559030 | TRANE | 4TWV0X48A1 | 4TXCD010DS3 | *UD2D120ACV5 | 36,400 | $1,820 |
| No | 210640905 | TRANE | 4TWV0X48A1 | 4TXCD010DS3 | *UD2D120A9V5+RP | 36,200 | $1,810 |
| No | 207805576 | TRANE | 4TWV0X48A1 | 4TXCD008DS3+P0V0D000M50SC+RP | N/A | 36,200 | $1,810 |
| No | 210653554 | TRANE | 4TWV0X48A1 | 4TXCD008DS3 | S9V2D120U5VSA+RP | 36,600 | $1,830 |
| No | 210653561 | TRANE | 4TWV0X48A1 | 4TXCD008DS3 | S9V2D120U5PSB+RP | 36,600 | $1,830 |
| No | 211081216 | TRANE | 4TWV0X48A1 | 4TXCD008DS3 | S8V2D120M5PDA | 36,800 | $1,840 |
| No | 210691847 | TRANE | 4TWV0X48A1 | 4TXCD008DS3 | S8V2D120M5PCA | 36,800 | $1,840 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207805575 | TRANE | 4TWV0X48A1 | 4TXCC009DS3+P0V0C000M50SC+RP | N/A | 36,000 | $1,800 |
| No | 207782205 | TRANE | 4TWV0X48A1 | 4TXCC009DS3 | S9V2C100U5PSB+RP | 36,400 | $1,820 |
| No | 207526443 | TRANE | 4TWV0X48A1 | 4TXCC009DS3 | S9V2C100U4VSA+RP | 36,200 | $1,810 |
| No | 208185400 | TRANE | 4TWV0X48A1 | 4TXCC009DS3 | S9V2C100U4PSB+RP | 36,200 | $1,810 |
| No | 210653846 | TRANE | 4TWV0X48A1 | 4TXCC009DS3 | S9V2C100D5PSB+RP | 35,200 | $1,760 |
| No | 210653845 | TRANE | 4TWV0X48A1 | 4TXCC009DS3 | S9V2C100D4VSA+RP | 35,200 | $1,760 |
| No | 210653844 | TRANE | 4TWV0X48A1 | 4TXCC009DS3 | S9V2C100D4PSB+RP | 35,200 | $1,760 |
| No | 210653553 | TRANE | 4TWV0X48A1 | 4TXCC009DS3 | S9V2C080U5PSB+RP | 36,400 | $1,820 |
| No | 211088959 | TRANE | 4TWV0X48A1 | 4TXCC009DS3 | S8V2C100M5PDA | 36,600 | $1,830 |
| No | 210692180 | TRANE | 4TWV0X48A1 | 4TXCC009DS3 | S8V2C100M5PCA | 36,600 | $1,830 |
| No | 208554520 | TRANE | 4TWV0X48A1 | 4TXCC009DS3 | L8V1C100U5VSA+RP | 36,200 | $1,810 |
| No | 210640895 | TRANE | 4TWV0X48A1 | 4TXCC009DS3 | *UD2C100B9V5+RP | 36,400 | $1,820 |
| No | 207559028 | TRANE | 4TWV0X48A1 | 4TXCC009DS3 | *UD2C100ACV5 | 36,600 | $1,830 |
| No | 210640894 | TRANE | 4TWV0X48A1 | 4TXCC009DS3 | *UD2C080B9V4+RP | 36,000 | $1,800 |
| No | 207559005 | TRANE | 4TWV0X48A1 | 4TXCC009DS3 | *UD2C080ACV4 | 36,000 | $1,800 |
| No | 210640893 | TRANE | 4TWV0X48A1 | 4TXCC009DS3 | *UD2C080A9V4+RP | 36,600 | $1,830 |
| No | 207559029 | TRANE | 4TWV0X48A1 | 4TXCC009DS3 | *DHMC100ACV4 | 35,000 | $1,750 |
| No | 207805574 | TRANE | 4TWV0X48A1 | 4TXCC007DS3+P0V0C000M50SC+RP | N/A | 36,400 | $1,820 |
| No | 207526388 | TRANE | 4TWV0X48A1 | 4TXCC007DS3 | S9V2C100D5PSB+RP | 36,000 | $1,800 |
| No | 207805571 | TRANE | 4TWV0X48A1 | 4PX*DU60BS3+P0V0D000M50SC+RP | N/A | 35,800 | $1,790 |
| No | 207805572 | TRANE | 4TWV0X48A1 | 4PX*DU60BS3+P0V0C000M50SC+RP | N/A | 34,800 | $1,740 |
| No | 207526440 | TRANE | 4TWV0X48A1 | 4PX*DU60BS3 | S9V2D120U5VSA+RP | 36,200 | $1,810 |
| No | 210653544 | TRANE | 4TWV0X48A1 | 4PX*DU60BS3 | S9V2D120U5PSB+RP | 36,200 | $1,810 |
| No | 207526439 | TRANE | 4TWV0X48A1 | 4PX*DU60BS3 | S9V2C100U4VSA+RP | 35,200 | $1,760 |
| No | 211088956 | TRANE | 4TWV0X48A1 | 4PX*DU60BS3 | S8V2D120M5PDA | 36,400 | $1,820 |
| No | 210692176 | TRANE | 4TWV0X48A1 | 4PX*DU60BS3 | S8V2D120M5PCA | 36,400 | $1,820 |
| No | 207558985 | TRANE | 4TWV0X48A1 | 4PX*DU60BS3 | *UHMD120ACV5 | 35,800 | $1,790 |
| No | 211596912 | TRANE | 4TWV0X48A1 | 4PX*DU60BS3 | *UD2D120B9V5+RP | 36,200 | $1,810 |
| No | 207559027 | TRANE | 4TWV0X48A1 | 4PX*DU60BS3 | *UD2D120ACV5 | 36,400 | $1,820 |
| No | 210640884 | TRANE | 4TWV0X48A1 | 4PX*DU60BS3 | *UD2D120A9V5+RP | 36,200 | $1,810 |
| No | 207805569 | TRANE | 4TWV0X48A1 | 4PX*DU48BS3+P0V0D000M50SC+RP | N/A | 36,200 | $1,810 |
| No | 210653540 | TRANE | 4TWV0X48A1 | 4PX*DU48BS3 | S9V2D120U5VSA+RP | 36,600 | $1,830 |
| No | 210653539 | TRANE | 4TWV0X48A1 | 4PX*DU48BS3 | S9V2D120U5PSB+RP | 36,600 | $1,830 |
| No | 207526509 | TRANE | 4TWV0X48A1 | 4PX*DU48BS3 | S9V2D120D5PSB+RP | 35,800 | $1,790 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211081209 | TRANE | 4TWV0X48A1 | 4PX*DU48BS3 | S8V2D120M5PDA | 36,800 | $1,840 |
| No | 210691840 | TRANE | 4TWV0X48A1 | 4PX*DU48BS3 | S8V2D120M5PCA | 36,800 | $1,840 |
| No | 207805566 | TRANE | 4TWV0X48A1 | 4PX*DD60BS3+P0V0D000M50SC+RP | N/A | 35,800 | $1,790 |
| No | 207526438 | TRANE | 4TWV0X48A1 | 4PX*DD60BS3 | S9V2C100D4VSA+RP | 35,000 | $1,750 |
| No | 211088952 | TRANE | 4TWV0X48A1 | 4PX*DD60BS3 | S8V2D120M5PDA | 36,400 | $1,820 |
| No | 210692173 | TRANE | 4TWV0X48A1 | 4PX*DD60BS3 | S8V2D120M5PCA | 36,400 | $1,820 |
| No | 207559036 | TRANE | 4TWV0X48A1 | 4PX*DD60BS3 | *DD2D120ACV5 | 35,800 | $1,790 |
| No | 210640873 | TRANE | 4TWV0X48A1 | 4PX*DD60BS3 | *DD2D120A9V5+RP | 36,600 | $1,830 |
| No | 207805564 | TRANE | 4TWV0X48A1 | 4PX*CU60BS3+P0V0C000M50SC+RP | N/A | 36,000 | $1,800 |
| No | 207782202 | TRANE | 4TWV0X48A1 | 4PX*CU60BS3 | S9V2C100U5PSB+RP | 36,400 | $1,820 |
| No | 207526436 | TRANE | 4TWV0X48A1 | 4PX*CU60BS3 | S9V2C100U4VSA+RP | 36,200 | $1,810 |
| No | 210653530 | TRANE | 4TWV0X48A1 | 4PX*CU60BS3 | S9V2C100U4PSB+RP | 36,200 | $1,810 |
| No | 210653528 | TRANE | 4TWV0X48A1 | 4PX*CU60BS3 | S9V2C080U5PSB+RP | 36,400 | $1,820 |
| No | 211088950 | TRANE | 4TWV0X48A1 | 4PX*CU60BS3 | S8V2C100M5PDA | 36,600 | $1,830 |
| No | 210692171 | TRANE | 4TWV0X48A1 | 4PX*CU60BS3 | S8V2C100M5PCA | 36,600 | $1,830 |
| No | 210653529 | TRANE | 4TWV0X48A1 | 4PX*CU60BS3 | L8V1C100U5VSA+RP | 36,200 | $1,810 |
| No | 210640871 | TRANE | 4TWV0X48A1 | 4PX*CU60BS3 | *UD2C100B9V5+RP | 36,400 | $1,820 |
| No | 207559025 | TRANE | 4TWV0X48A1 | 4PX*CU60BS3 | *UD2C100ACV5 | 36,600 | $1,830 |
| No | 210640870 | TRANE | 4TWV0X48A1 | 4PX*CU60BS3 | *UD2C080B9V4+RP | 36,000 | $1,800 |
| No | 207558983 | TRANE | 4TWV0X48A1 | 4PX*CU60BS3 | *UD2C080ACV4 | 36,000 | $1,800 |
| No | 207805563 | TRANE | 4TWV0X48A1 | 4PX*CU48BS3+P0V0C000M50SC+RP | N/A | 36,400 | $1,820 |
| No | 207526507 | TRANE | 4TWV0X48A1 | 4PX*CU48BS3 | S9V2C100D5PSB+RP | 36,000 | $1,800 |
| No | 207526506 | TRANE | 4TWV0X48A1 | 4PX*CU48BS3 | S9V2C100D4PSB+RP | 36,000 | $1,800 |
| No | 207526433 | TRANE | 4TWV0X48A1 | 4PX*CD60BS3 | S9V2C100D4VSA+RP | 36,200 | $1,810 |
| No | 207526340 | TRANE | 4TWV0X36A1 | TEM8A0C42V41+TDR | N/A | 26,400 | $1,320 |
| No | 207526339 | TRANE | 4TWV0X36A1 | TEM8A0C36V31+TDR | N/A | 26,400 | $1,320 |
| No | 207526338 | TRANE | 4TWV0X36A1 | TEM8A0B30V31+TDR | N/A | 27,000 | $1,350 |
| No | 210929563 | TRANE | 4TWV0X36A1 | TAMXB0C36V31 | N/A | 26,000 | $1,300 |
| No | 210929562 | TRANE | 4TWV0X36A1 | TAMXB0B30V31 | N/A | 26,400 | $1,320 |
| No | 207690045 | TRANE | 4TWV0X36A1 | TAMXA0B30V31 | N/A | 26,400 | $1,320 |
| No | 207526324 | TRANE | 4TWV0X36A1 | TAM9A0C36V31 | N/A | 26,000 | $1,300 |
| No | 207559046 | TRANE | 4TWV0X36A1 | TAM9A0B30V31 | N/A | 26,400 | $1,320 |
| No | 207526431 | TRANE | 4TWV0X36A1 | 4TXCC005DS3 | S9V2C100U4VSA+RP | 26,000 | $1,300 |
| No | 208185398 | TRANE | 4TWV0X36A1 | 4TXCC005DS3 | S9V2C100U4PSB+RP | 25,800 | $1,290 |
| No | 207526430 | TRANE | 4TWV0X36A1 | 4TXCC005DS3 | S9V2C100D4VSA+RP | 25,400 | $1,270 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210653508 | TRANE | 4TWV0X36A1 | 4TXCC005DS3 | S9V2C100D4PSB+RP | 25,400 | $1,270 |
| No | 211081201 | TRANE | 4TWV0X36A1 | 4TXCC005DS3 | S8V2C100M5PDA | 26,600 | $1,330 |
| No | 210691831 | TRANE | 4TWV0X36A1 | 4TXCC005DS3 | S8V2C100M5PCA | 26,600 | $1,330 |
| No | 210640846 | TRANE | 4TWV0X36A1 | 4TXCC005DS3 | *UD2C100B9V5+RP | 25,800 | $1,290 |
| No | 207559001 | TRANE | 4TWV0X36A1 | 4TXCC005DS3 | *UD2C100ACV5 | 26,800 | $1,340 |
| No | 210640847 | TRANE | 4TWV0X36A1 | 4TXCC005DS3 | *UD2C100A9V5+RP | 26,000 | $1,300 |
| No | 210640848 | TRANE | 4TWV0X36A1 | 4TXCC005DS3 | *UD2C080B9V4+RP | 26,000 | $1,300 |
| No | 207559000 | TRANE | 4TWV0X36A1 | 4TXCC005DS3 | *UD2C080ACV4 | 26,000 | $1,300 |
| No | 210640845 | TRANE | 4TWV0X36A1 | 4TXCC005DS3 | *UD2C080A9V4+RP | 26,000 | $1,300 |
| No | 210653509 | TRANE | 4TWV0X36A1 | 4TXCC005DS3 | *DHMC100ACV4 | 25,800 | $1,290 |
| No | 211596905 | TRANE | 4TWV0X36A1 | 4TXCC005DS3 | *DD2C100ACV5 | 25,400 | $1,270 |
| No | 209326026 | TRANE | 4TWV0X36A1 | 4TXCB004DS3 | S9V2B080U4VSA+RP | 26,000 | $1,300 |
| No | 208185396 | TRANE | 4TWV0X36A1 | 4TXCB004DS3 | S9V2B080U4PSB+RP | 26,000 | $1,300 |
| No | 207526424 | TRANE | 4TWV0X36A1 | 4TXCB004DS3 | S9V2B060U3VSA+RP | 26,000 | $1,300 |
| No | 208185394 | TRANE | 4TWV0X36A1 | 4TXCB004DS3 | S9V2B060U3PSB+RP | 26,000 | $1,300 |
| No | 207526423 | TRANE | 4TWV0X36A1 | 4TXCB004DS3 | S9V2B040U3VSA+RP | 26,200 | $1,310 |
| No | 208185395 | TRANE | 4TWV0X36A1 | 4TXCB004DS3 | S9V2B040U3PSB+RP | 26,200 | $1,310 |
| No | 211081197 | TRANE | 4TWV0X36A1 | 4TXCB004DS3 | S8V2B080M4PDA | 26,600 | $1,330 |
| No | 210691830 | TRANE | 4TWV0X36A1 | 4TXCB004DS3 | S8V2B080M4PCA | 26,600 | $1,330 |
| No | 211081198 | TRANE | 4TWV0X36A1 | 4TXCB004DS3 | S8V2B060M4PDA | 26,800 | $1,340 |
| No | 210691829 | TRANE | 4TWV0X36A1 | 4TXCB004DS3 | S8V2B060M4PCA | 26,800 | $1,340 |
| No | 207558992 | TRANE | 4TWV0X36A1 | 4TXCB004DS3 | *UHMB080ACV3 | 26,400 | $1,320 |
| No | 207558993 | TRANE | 4TWV0X36A1 | 4TXCB004DS3 | *UHMB060ACV3 | 26,000 | $1,300 |
| No | 207558995 | TRANE | 4TWV0X36A1 | 4TXCB004DS3 | *UD2B080ACV3 | 25,600 | $1,280 |
| No | 207558996 | TRANE | 4TWV0X36A1 | 4TXCB004DS3 | *UD2B060ACV3 | 25,800 | $1,290 |
| No | 211596904 | TRANE | 4TWV0X36A1 | 4TXCB004DS3 | *DD2B080ACV3 | 25,600 | $1,280 |
| No | 211596903 | TRANE | 4TWV0X36A1 | 4TXCB004DS3 | *DD2B060ACV3 | 26,000 | $1,300 |
| No | 210640839 | TRANE | 4TWV0X36A1 | 4PX*DU48BS3 | *DD2D120A9V5+RP | 25,600 | $1,280 |
| No | 207526422 | TRANE | 4TWV0X36A1 | 4PX*CU48BS3 | S9V2C100U4VSA+RP | 26,200 | $1,310 |
| No | 207526385 | TRANE | 4TWV0X36A1 | 4PX*CU48BS3 | S9V2C100U4PSB+RP | 26,200 | $1,310 |
| No | 210653499 | TRANE | 4TWV0X36A1 | 4PX*CU48BS3 | S9V2C100D4VSA+RP | 25,600 | $1,280 |
| No | 207526540 | TRANE | 4TWV0X36A1 | 4PX*CU48BS3 | S9V2C100D4PSB+RP | 25,600 | $1,280 |
| No | 211081195 | TRANE | 4TWV0X36A1 | 4PX*CU48BS3 | S8V2C100M5PDA | 26,800 | $1,340 |
| No | 210691826 | TRANE | 4TWV0X36A1 | 4PX*CU48BS3 | S8V2C100M5PCA | 26,800 | $1,340 |
| No | 211081196 | TRANE | 4TWV0X36A1 | 4PX*CU48BS3 | S8V2C080M5PDA | 26,600 | $1,330 |
| No | 210691827 | TRANE | 4TWV0X36A1 | 4PX*CU48BS3 | S8V2C080M5PCA | 26,600 | $1,330 |
| No | 210640834 | TRANE | 4TWV0X36A1 | 4PX*CU48BS3 | *UD2C100B9V5+RP | 26,200 | $1,310 |
| No | 207558974 | TRANE | 4TWV0X36A1 | 4PX*CU48BS3 | *UD2C100ACV5 | 26,800 | $1,340 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210640835 | TRANE | 4TWV0X36A1 | 4PX*CU48BS3 | *UD2C100A9V5+RP | 26,400 | $1,320 |
| No | 210640836 | TRANE | 4TWV0X36A1 | 4PX*CU48BS3 | *UD2C080B9V4+RP | 26,200 | $1,310 |
| No | 207558973 | TRANE | 4TWV0X36A1 | 4PX*CU48BS3 | *UD2C080ACV4 | 26,400 | $1,320 |
| No | 210640837 | TRANE | 4TWV0X36A1 | 4PX*CU48BS3 | *UD2C080A9V4+RP | 26,200 | $1,310 |
| No | 210653498 | TRANE | 4TWV0X36A1 | 4PX*CU48BS3 | *DHMC100ACV4 | 26,000 | $1,300 |
| No | 211596902 | TRANE | 4TWV0X36A1 | 4PX*CU48BS3 | *DD2C100ACV5 | 25,400 | $1,270 |
| No | 210640838 | TRANE | 4TWV0X36A1 | 4PX*CU48BS3 | *DD2C100A9V5+RP | 25,400 | $1,270 |
| No | 210653495 | TRANE | 4TWV0X36A1 | 4PX*CU42BS3 | S9V2C100U4VSA+RP | 26,400 | $1,320 |
| No | 210653494 | TRANE | 4TWV0X36A1 | 4PX*CU42BS3 | S9V2C100U4PSB+RP | 26,400 | $1,320 |
| No | 211081194 | TRANE | 4TWV0X36A1 | 4PX*CU42BS3 | S8V2C100M5PDA | 27,000 | $1,350 |
| No | 210691824 | TRANE | 4TWV0X36A1 | 4PX*CU42BS3 | S8V2C100M5PCA | 27,000 | $1,350 |
| No | 211081193 | TRANE | 4TWV0X36A1 | 4PX*CU42BS3 | S8V2C080M5PDA | 26,800 | $1,340 |
| No | 210691825 | TRANE | 4TWV0X36A1 | 4PX*CU42BS3 | S8V2C080M5PCA | 26,800 | $1,340 |
| No | 210640833 | TRANE | 4TWV0X36A1 | 4PX*CU42BS3 | *UD2C100B9V5+RP | 26,400 | $1,320 |
| No | 211289039 | TRANE | 4TWV0X36A1 | 4PX*CU42BS3 | *UD2C100ACV5 | 27,000 | $1,350 |
| No | 210640831 | TRANE | 4TWV0X36A1 | 4PX*CU42BS3 | *UD2C100A9V5+RP | 26,600 | $1,330 |
| No | 210640832 | TRANE | 4TWV0X36A1 | 4PX*CU42BS3 | *UD2C080B9V4+RP | 26,400 | $1,320 |
| No | 211596901 | TRANE | 4TWV0X36A1 | 4PX*CU42BS3 | *UD2C080ACV4 | 26,600 | $1,330 |
| No | 210640829 | TRANE | 4TWV0X36A1 | 4PX*CU42BS3 | *UD2C080A9V4+RP | 26,400 | $1,320 |
| No | 207526552 | TRANE | 4TWV0X36A1 | 4PX*CU42BS3 | *DHMC100ACV4 | 26,200 | $1,310 |
| No | 207526551 | TRANE | 4TWV0X36A1 | 4PX*CU42BS3 | *DD2C100ACV5 | 25,600 | $1,280 |
| No | 210640830 | TRANE | 4TWV0X36A1 | 4PX*CU42BS3 | *DD2C100A9V5+RP | 26,000 | $1,300 |
| No | 207526421 | TRANE | 4TWV0X36A1 | 4PX*CU36BS3 | S9V2C100U4VSA+RP | 25,800 | $1,290 |
| No | 210653493 | TRANE | 4TWV0X36A1 | 4PX*CU36BS3 | S9V2C100U4PSB+RP | 25,800 | $1,290 |
| No | 211081191 | TRANE | 4TWV0X36A1 | 4PX*CU36BS3 | S8V2C100M5PDA | 26,400 | $1,320 |
| No | 210691822 | TRANE | 4TWV0X36A1 | 4PX*CU36BS3 | S8V2C100M5PCA | 26,400 | $1,320 |
| No | 211081192 | TRANE | 4TWV0X36A1 | 4PX*CU36BS3 | S8V2C080M5PDA | 26,400 | $1,320 |
| No | 210691823 | TRANE | 4TWV0X36A1 | 4PX*CU36BS3 | S8V2C080M5PCA | 26,400 | $1,320 |
| No | 210640825 | TRANE | 4TWV0X36A1 | 4PX*CU36BS3 | *UD2C100B9V5+RP | 25,800 | $1,290 |
| No | 207558969 | TRANE | 4TWV0X36A1 | 4PX*CU36BS3 | *UD2C100ACV5 | 26,400 | $1,320 |
| No | 210640826 | TRANE | 4TWV0X36A1 | 4PX*CU36BS3 | *UD2C100A9V5+RP | 26,000 | $1,300 |
| No | 210640828 | TRANE | 4TWV0X36A1 | 4PX*CU36BS3 | *UD2C080B9V4+RP | 25,800 | $1,290 |
| No | 207558971 | TRANE | 4TWV0X36A1 | 4PX*CU36BS3 | *UD2C080ACV4 | 26,000 | $1,300 |
| No | 210640827 | TRANE | 4TWV0X36A1 | 4PX*CU36BS3 | *UD2C080A9V4+RP | 26,000 | $1,300 |
| No | 207526538 | TRANE | 4TWV0X36A1 | 4PX*CD42BS3 | S9V2C100D4PSB+RP | 25,800 | $1,290 |
| No | 207526419 | TRANE | 4TWV0X36A1 | 4PX*CD36BS3 | S9V2C100D4VSA+RP | 26,600 | $1,330 |
| No | 207526383 | TRANE | 4TWV0X36A1 | 4PX*CD36BS3 | S9V2C100D4PSB+RP | 26,600 | $1,330 |
| No | 210653490 | TRANE | 4TWV0X36A1 | 4PX*BU48BS3 | S9V2B080D4VSA+RP | 25,600 | $1,280 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207526535 | TRANE | 4TWV0X36A1 | 4PX*BU48BS3 | S9V2B080D4PSB+RP | 25,600 | $1,280 |
| No | 210653488 | TRANE | 4TWV0X36A1 | 4PX*BU48BS3 | S9V2B080D3VSA+RP | 25,600 | $1,280 |
| No | 207526536 | TRANE | 4TWV0X36A1 | 4PX*BU48BS3 | S9V2B080D3PSB+RP | 25,600 | $1,280 |
| No | 207526537 | TRANE | 4TWV0X36A1 | 4PX*BU48BS3 | S9V2B060D3PSB+RP | 25,600 | $1,280 |
| No | 207526534 | TRANE | 4TWV0X36A1 | 4PX*BU48BS3 | S9V2B040D3PSB+RP | 25,800 | $1,290 |
| No | 210653489 | TRANE | 4TWV0X36A1 | 4PX*BU48BS3 | *DHMB080ACV3 | 25,400 | $1,270 |
| No | 207526533 | TRANE | 4TWV0X36A1 | 4PX*BU48BS3 | *DD2B080ACV3 | 26,000 | $1,300 |
| No | 210640813 | TRANE | 4TWV0X36A1 | 4PX*BU48BS3 | *DD2B080A9V3+RP | 25,400 | $1,270 |
| No | 211596898 | TRANE | 4TWV0X36A1 | 4PX*BU48BS3 | *DD2B060ACV3 | 26,400 | $1,320 |
| No | 210640814 | TRANE | 4TWV0X36A1 | 4PX*BU48BS3 | *DD2B060A9V3+RP | 25,800 | $1,290 |
| No | 210653479 | TRANE | 4TWV0X36A1 | 4PX*BU42BS3 | S9V2B080U4VSA+RP | 26,600 | $1,330 |
| No | 210653480 | TRANE | 4TWV0X36A1 | 4PX*BU42BS3 | S9V2B080U4PSB+RP | 26,600 | $1,330 |
| No | 210653481 | TRANE | 4TWV0X36A1 | 4PX*BU42BS3 | S9V2B060U3VSA+RP | 26,600 | $1,330 |
| No | 210653482 | TRANE | 4TWV0X36A1 | 4PX*BU42BS3 | S9V2B060U3PSB+RP | 26,600 | $1,330 |
| No | 210653483 | TRANE | 4TWV0X36A1 | 4PX*BU42BS3 | S9V2B040U3VSA+RP | 26,600 | $1,330 |
| No | 210653484 | TRANE | 4TWV0X36A1 | 4PX*BU42BS3 | S9V2B040U3PSB+RP | 26,600 | $1,330 |
| No | 211081184 | TRANE | 4TWV0X36A1 | 4PX*BU42BS3 | S8V2B080M4PDA | 27,400 | $1,370 |
| No | 210691817 | TRANE | 4TWV0X36A1 | 4PX*BU42BS3 | S8V2B080M4PCA | 27,400 | $1,370 |
| No | 211081185 | TRANE | 4TWV0X36A1 | 4PX*BU42BS3 | S8V2B060M4PDA | 27,200 | $1,360 |
| No | 210691815 | TRANE | 4TWV0X36A1 | 4PX*BU42BS3 | S8V2B060M4PCA | 27,200 | $1,360 |
| No | 210653485 | TRANE | 4TWV0X36A1 | 4PX*BU42BS3 | L8V1B080U4VSA+RP | 27,200 | $1,360 |
| No | 210653478 | TRANE | 4TWV0X36A1 | 4PX*BU42BS3 | *UHMB080ACV3 | 26,800 | $1,340 |
| No | 210653477 | TRANE | 4TWV0X36A1 | 4PX*BU42BS3 | *UHMB060ACV3 | 26,600 | $1,330 |
| No | 211596897 | TRANE | 4TWV0X36A1 | 4PX*BU42BS3 | *UD2B080ACV3 | 26,400 | $1,320 |
| No | 211596896 | TRANE | 4TWV0X36A1 | 4PX*BU42BS3 | *UD2B060ACV3 | 26,600 | $1,330 |
| No | 210640811 | TRANE | 4TWV0X36A1 | 4PX*BU42BS3 | *UD2B060A9V3+RP | 26,600 | $1,330 |
| No | 207526907 | TRANE | 4TWV0X36A1 | 4PX*BU36BS3 | S9V2B080U4VSA+RP | 26,000 | $1,300 |
| No | 210610551 | TRANE | 4TWV0X36A1 | 4PX*BU36BS3 | S9V2B080U4PSB+RP | 26,000 | $1,300 |
| No | 207526413 | TRANE | 4TWV0X36A1 | 4PX*BU36BS3 | S9V2B060U3VSA+RP | 26,000 | $1,300 |
| No | 210653470 | TRANE | 4TWV0X36A1 | 4PX*BU36BS3 | S9V2B060U3PSB+RP | 26,000 | $1,300 |
| No | 207526415 | TRANE | 4TWV0X36A1 | 4PX*BU36BS3 | S9V2B040U3VSA+RP | 26,200 | $1,310 |
| No | 210653469 | TRANE | 4TWV0X36A1 | 4PX*BU36BS3 | S9V2B040U3PSB+RP | 26,200 | $1,310 |
| No | 211081181 | TRANE | 4TWV0X36A1 | 4PX*BU36BS3 | S8V2B080M4PDA | 26,800 | $1,340 |
| No | 210691814 | TRANE | 4TWV0X36A1 | 4PX*BU36BS3 | S8V2B080M4PCA | 26,800 | $1,340 |
| No | 211081182 | TRANE | 4TWV0X36A1 | 4PX*BU36BS3 | S8V2B060M4PDA | 26,800 | $1,340 |
| No | 210691813 | TRANE | 4TWV0X36A1 | 4PX*BU36BS3 | S8V2B060M4PCA | 26,800 | $1,340 |
| No | 207558956 | TRANE | 4TWV0X36A1 | 4PX*BU36BS3 | *UHMB080ACV3 | 26,400 | $1,320 |
| No | 207558960 | TRANE | 4TWV0X36A1 | 4PX*BU36BS3 | *UHMB060ACV3 | 26,200 | $1,310 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207558957 | TRANE | 4TWV0X36A1 | 4PX*BU36BS3 | *UD2B080ACV3 | 25,600 | $1,280 |
| No | 207558959 | TRANE | 4TWV0X36A1 | 4PX*BU36BS3 | *UD2B060ACV3 | 25,600 | $1,280 |
| No | 211596894 | TRANE | 4TWV0X36A1 | 4PX*BU36BS3 | *DD2B080ACV3 | 25,600 | $1,280 |
| No | 211596895 | TRANE | 4TWV0X36A1 | 4PX*BU36BS3 | *DD2B060ACV3 | 26,000 | $1,300 |
| No | 207526532 | TRANE | 4TWV0X36A1 | 4PX*BD42BS3 | S9V2B080D4PSB+RP | 25,800 | $1,290 |
| No | 207526531 | TRANE | 4TWV0X36A1 | 4PX*BD42BS3 | S9V2B080D3PSB+RP | 25,800 | $1,290 |
| No | 207526530 | TRANE | 4TWV0X36A1 | 4PX*BD42BS3 | S9V2B060D3PSB+RP | 25,800 | $1,290 |
| No | 207526528 | TRANE | 4TWV0X36A1 | 4PX*BD42BS3 | S9V2B040D3PSB+RP | 26,000 | $1,300 |
| No | 207526529 | TRANE | 4TWV0X36A1 | 4PX*BD42BS3 | *DD2B080ACV3 | 26,000 | $1,300 |
| No | 207526373 | TRANE | 4TWV0X36A1 | 4PX*BD36BS3 | S9V2B080D4PSB+RP | 26,800 | $1,340 |
| No | 207526337 | TRANE | 4TWV0X24A1 | TEM8A0B30V31+TDR | N/A | 17,600 | $880 |
| No | 210636920 | TRANE | 4TWV0X24A1 | TEM8A0B24V21+TDR | N/A | 17,600 | $880 |
| No | 210929561 | TRANE | 4TWV0X24A1 | TAMXB0B30V31 | N/A | 17,100 | $855 |
| No | 207526323 | TRANE | 4TWV0X24A1 | TAM9A0B30V31 | N/A | 17,100 | $855 |
| No | 207558935 | TRANE | 4TWV0X24A1 | 4TXFH024CZ3 | *DHMB080ACV3 | 16,800 | $840 |
| No | 207558932 | TRANE | 4TWV0X24A1 | 4TXFH024CZ3 | *DHMB060BCV3 | 16,800 | $840 |
| No | 207558930 | TRANE | 4TWV0X24A1 | 4TXFH024CZ3 | *DD2B060ACV3 | 16,800 | $840 |
| No | 211088943 | TRANE | 4TWV0X24A1 | 4TXCB004DS3 | S8V2B080M4PDA | 17,200 | $860 |
| No | 210692163 | TRANE | 4TWV0X24A1 | 4TXCB004DS3 | S8V2B080M4PCA | 17,200 | $860 |
| No | 211081175 | TRANE | 4TWV0X24A1 | 4TXCB004DS3 | S8V2A040M3PDA | 16,400 | $820 |
| No | 210691806 | TRANE | 4TWV0X24A1 | 4TXCB004DS3 | S8V2A040M3PCA | 16,400 | $820 |
| No | 210653462 | TRANE | 4TWV0X24A1 | 4TXCB004DS3 | L8V1A060U3VSA+RP | 16,500 | $825 |
| No | 210653461 | TRANE | 4TWV0X24A1 | 4TXCB004DS3 | L8V1A040U3VSA+RP | 16,600 | $830 |
| No | 210288157 | TRANE | 4TWV0X24A1 | 4TXCB004DS3 | *UHMB060ACV3 | 16,800 | $840 |
| No | 210640798 | TRANE | 4TWV0X24A1 | 4TXCB004DS3 | *UD2B080A9V3+RP | 16,900 | $845 |
| No | 210640799 | TRANE | 4TWV0X24A1 | 4TXCB004DS3 | *UD2B060A9V3+RP | 16,700 | $835 |
| No | 210653452 | TRANE | 4TWV0X24A1 | 4TXCB003DS3 | S9V2B040U3VSA+RP | 17,900 | $895 |
| No | 210653455 | TRANE | 4TWV0X24A1 | 4TXCB003DS3 | S9V2B040U3PSB+RP | 17,900 | $895 |
| No | 211081172 | TRANE | 4TWV0X24A1 | 4TXCB003DS3 | S8V2B080M4PDA | 18,000 | $900 |
| No | 210691803 | TRANE | 4TWV0X24A1 | 4TXCB003DS3 | S8V2B080M4PCA | 18,000 | $900 |
| No | 211081173 | TRANE | 4TWV0X24A1 | 4TXCB003DS3 | S8V2B060M4PDA | 17,900 | $895 |
| No | 210691805 | TRANE | 4TWV0X24A1 | 4TXCB003DS3 | S8V2B060M4PCA | 17,900 | $895 |
| No | 210653459 | TRANE | 4TWV0X24A1 | 4TXCB003DS3 | *UHMB080ACV3 | 17,700 | $885 |
| No | 207526405 | TRANE | 4TWV0X24A1 | 4PX*BU36BS3 | S9V2B060U3VSA+RP | 16,900 | $845 |
| No | 207526404 | TRANE | 4TWV0X24A1 | 4PX*BU36BS3 | S9V2B040U3VSA+RP | 17,000 | $850 |
| No | 207526368 | TRANE | 4TWV0X24A1 | 4PX*BU36BS3 | S9V2B040U3PSB+RP | 17,000 | $850 |
| No | 211088941 | TRANE | 4TWV0X24A1 | 4PX*BU36BS3 | S8V2B080M4PDA | 17,100 | $855 |
| No | 210692161 | TRANE | 4TWV0X24A1 | 4PX*BU36BS3 | S8V2B080M4PCA | 17,100 | $855 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211088942 | TRANE | 4TWV0X24A1 | 4PX*BU36BS3 | S8V2B060M4PDA | 17,100 | $855 |
| No | 210692162 | TRANE | 4TWV0X24A1 | 4PX*BU36BS3 | S8V2B060M4PCA | 17,100 | $855 |
| No | 211081171 | TRANE | 4TWV0X24A1 | 4PX*BU36BS3 | S8V2A040M3PDA | 16,400 | $820 |
| No | 210691802 | TRANE | 4TWV0X24A1 | 4PX*BU36BS3 | S8V2A040M3PCA | 16,400 | $820 |
| No | 210653451 | TRANE | 4TWV0X24A1 | 4PX*BU36BS3 | L8V1B080U4VSA+RP | 17,000 | $850 |
| No | 210653450 | TRANE | 4TWV0X24A1 | 4PX*BU36BS3 | L8V1A060U3VSA+RP | 16,500 | $825 |
| No | 207558947 | TRANE | 4TWV0X24A1 | 4PX*BU36BS3 | *UHMB060ACV3 | 16,800 | $840 |
| No | 210640796 | TRANE | 4TWV0X24A1 | 4PX*BU36BS3 | *UD2B080A9V3+RP | 16,900 | $845 |
| No | 210640795 | TRANE | 4TWV0X24A1 | 4PX*BU36BS3 | *UD2B060A9V3+RP | 17,000 | $850 |
| No | 211455293 | TRANE | 4TWV0024A1 | TEM8A0B24V21+TDR | N/A | 17,600 | $880 |
| No | 207820927 | TRANE | 4TWL9060A1 | TEM8B0C60V51+TDR | N/A | 37,800 | $1,890 |
| No | 201922269 | TRANE | 4TWL9060A1 | TEM8A0D60V51+TDR | N/A | 38,000 | $1,900 |
| No | 201922268 | TRANE | 4TWL9060A1 | TEM8A0D48V41+TDR | N/A | 38,500 | $1,925 |
| No | 207708973 | TRANE | 4TWL9060A1 | TEM8A0C48V41+TDR | N/A | 38,000 | $1,900 |
| No | 201923714 | TRANE | 4TWL9060A1 | TAM9A0C60V51 | N/A | 38,000 | $1,900 |
| No | 207804977 | TRANE | 4TWL9060A1 | 4TXCD010DS3+P0V0D000M50SC+RP | N/A | 38,000 | $1,900 |
| No | 207804978 | TRANE | 4TWL9060A1 | 4TXCD010DS3+P0V0C000M50SC+RP | N/A | 37,000 | $1,850 |
| No | 210653449 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | S9V2D120U5VSA+RP | 38,500 | $1,925 |
| No | 201922250 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | S9V2D120U5PSB+RP | 38,500 | $1,925 |
| No | 201922249 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | S9V2C100U5PSB+RP | 37,400 | $1,870 |
| No | 211306987 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | S9V2C100D5PSB+RP | 36,400 | $1,820 |
| No | 201922248 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | S9V2C080U5PSB+RP | 37,600 | $1,880 |
| No | 211081170 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | S8V2D120M5PDA | 38,500 | $1,925 |
| No | 210691801 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | S8V2D120M5PCA | 38,500 | $1,925 |
| No | 211081168 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | S8V2C100M5PDA | 37,400 | $1,870 |
| No | 210691799 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | S8V2C100M5PCA | 37,400 | $1,870 |
| No | 211081169 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | S8V2C080M5PDA | 37,400 | $1,870 |
| No | 210691800 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | S8V2C080M5PCA | 37,400 | $1,870 |
| No | 207352639 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | L8V1C100U5VSA+RP | 37,400 | $1,870 |
| No | 201922247 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | *UHMD120ACV5 | 38,000 | $1,900 |
| No | 211596243 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | *UD2D120B9V5+RP | 38,500 | $1,925 |
| No | 201922244 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | *UD2D120ACV5 | 39,000 | $1,950 |
| No | 210649552 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | *UD2D120A9V5+RP | 38,000 | $1,900 |
| No | 210649551 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | *UD2C100B9V5+RP | 36,800 | $1,840 |
| No | 201922243 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | *UD2C100ACV5 | 37,000 | $1,850 |
| No | 210649550 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | *UD2C100A9V5+RP | 37,400 | $1,870 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211306986 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | *DD2C100A9V5+RP | 35,400 | $1,770 |
| No | 207804975 | TRANE | 4TWL9060A1 | 4TXCD008DS3+P0V0D000M50SC+RP | N/A | 38,500 | $1,925 |
| No | 207804976 | TRANE | 4TWL9060A1 | 4TXCD008DS3+P0V0C000M50SC+RP | N/A | 37,400 | $1,870 |
| No | 210653446 | TRANE | 4TWL9060A1 | 4TXCD008DS3 | S9V2D120U5VSA+RP | 39,000 | $1,950 |
| No | 201922235 | TRANE | 4TWL9060A1 | 4TXCD008DS3 | S9V2D120U5PSB+RP | 39,000 | $1,950 |
| No | 210653447 | TRANE | 4TWL9060A1 | 4TXCD008DS3 | S9V2D120D5PSB+RP | 38,000 | $1,900 |
| No | 201922239 | TRANE | 4TWL9060A1 | 4TXCD008DS3 | S9V2C100U5PSB+RP | 37,800 | $1,890 |
| No | 210653448 | TRANE | 4TWL9060A1 | 4TXCD008DS3 | S9V2C100D5PSB+RP | 37,000 | $1,850 |
| No | 201922240 | TRANE | 4TWL9060A1 | 4TXCD008DS3 | S9V2C080U5PSB+RP | 38,000 | $1,900 |
| No | 211081166 | TRANE | 4TWL9060A1 | 4TXCD008DS3 | S8V2D120M5PDA | 39,000 | $1,950 |
| No | 210691797 | TRANE | 4TWL9060A1 | 4TXCD008DS3 | S8V2D120M5PCA | 39,000 | $1,950 |
| No | 211081167 | TRANE | 4TWL9060A1 | 4TXCD008DS3 | S8V2C100M5PDA | 38,000 | $1,900 |
| No | 210691798 | TRANE | 4TWL9060A1 | 4TXCD008DS3 | S8V2C100M5PCA | 38,000 | $1,900 |
| No | 211081165 | TRANE | 4TWL9060A1 | 4TXCD008DS3 | S8V2C080M5PDA | 38,000 | $1,900 |
| No | 210691796 | TRANE | 4TWL9060A1 | 4TXCD008DS3 | S8V2C080M5PCA | 38,000 | $1,900 |
| No | 210653445 | TRANE | 4TWL9060A1 | 4TXCD008DS3 | L8V1C100U5VSA+RP | 37,800 | $1,890 |
| No | 201922234 | TRANE | 4TWL9060A1 | 4TXCD008DS3 | *UHMD120ACV5 | 38,500 | $1,925 |
| No | 207804974 | TRANE | 4TWL9060A1 | 4TXCC009DS3+P0V0C000M50SC+RP | N/A | 38,000 | $1,900 |
| No | 201922222 | TRANE | 4TWL9060A1 | 4TXCC009DS3 | S9V2C100U5PSB+RP | 38,500 | $1,925 |
| No | 201922228 | TRANE | 4TWL9060A1 | 4TXCC009DS3 | S9V2C080U5PSB+RP | 38,500 | $1,925 |
| No | 211081164 | TRANE | 4TWL9060A1 | 4TXCC009DS3 | S8V2C100M5PDA | 38,500 | $1,925 |
| No | 210691795 | TRANE | 4TWL9060A1 | 4TXCC009DS3 | S8V2C100M5PCA | 38,500 | $1,925 |
| No | 211081163 | TRANE | 4TWL9060A1 | 4TXCC009DS3 | S8V2C080M5PDA | 38,500 | $1,925 |
| No | 210691794 | TRANE | 4TWL9060A1 | 4TXCC009DS3 | S8V2C080M5PCA | 38,500 | $1,925 |
| No | 207352638 | TRANE | 4TWL9060A1 | 4TXCC009DS3 | L8V1C100U5VSA+RP | 38,500 | $1,925 |
| No | 201922226 | TRANE | 4TWL9060A1 | 4TXCC009DS3 | *UD2C100ACV5 | 38,000 | $1,900 |
| No | 211306985 | TRANE | 4TWL9060A1 | 4TXCC009DS3 | *DD2C100A9V5+RP | 36,600 | $1,830 |
| No | 207804973 | TRANE | 4TWL9060A1 | 4TXCC007DS3+P0V0C000M50SC+RP | N/A | 38,500 | $1,925 |
| No | 201922218 | TRANE | 4TWL9060A1 | 4TXCC007DS3 | S9V2C100U5PSB+RP | 39,000 | $1,950 |
| No | 210653444 | TRANE | 4TWL9060A1 | 4TXCC007DS3 | S9V2C100D5PSB+RP | 38,000 | $1,900 |
| No | 201922214 | TRANE | 4TWL9060A1 | 4TXCC007DS3 | S9V2C080U5PSB+RP | 39,000 | $1,950 |
| No | 211081162 | TRANE | 4TWL9060A1 | 4TXCC007DS3 | S8V2C100M5PDA | 39,000 | $1,950 |
| No | 210691793 | TRANE | 4TWL9060A1 | 4TXCC007DS3 | S8V2C100M5PCA | 39,000 | $1,950 |
| No | 211081161 | TRANE | 4TWL9060A1 | 4TXCC007DS3 | S8V2C080M5PDA | 39,000 | $1,950 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210691792 | TRANE | 4TWL9060A1 | 4TXCC007DS3 | S8V2C080M5PCA | 39,000 | $1,950 |
| No | 210653443 | TRANE | 4TWL9060A1 | 4TXCC007DS3 | L8V1C100U5VSA+RP | 39,000 | $1,950 |
| No | 207804972 | TRANE | 4TWL9060A1 | 4PX*DU60BS3+P0V0D000M50SC+RP | N/A | 38,000 | $1,900 |
| No | 207804971 | TRANE | 4TWL9060A1 | 4PX*DU60BS3+P0V0C000M50SC+RP | N/A | 37,000 | $1,850 |
| No | 210653442 | TRANE | 4TWL9060A1 | 4PX*DU60BS3 | S9V2D120U5VSA+RP | 38,500 | $1,925 |
| No | 201922212 | TRANE | 4TWL9060A1 | 4PX*DU60BS3 | S9V2D120U5PSB+RP | 38,500 | $1,925 |
| No | 201922211 | TRANE | 4TWL9060A1 | 4PX*DU60BS3 | S9V2C100U5PSB+RP | 37,400 | $1,870 |
| No | 201922210 | TRANE | 4TWL9060A1 | 4PX*DU60BS3 | S9V2C080U5PSB+RP | 37,600 | $1,880 |
| No | 211081160 | TRANE | 4TWL9060A1 | 4PX*DU60BS3 | S8V2D120M5PDA | 38,500 | $1,925 |
| No | 210691791 | TRANE | 4TWL9060A1 | 4PX*DU60BS3 | S8V2D120M5PCA | 38,500 | $1,925 |
| No | 211081159 | TRANE | 4TWL9060A1 | 4PX*DU60BS3 | S8V2C100M5PDA | 37,600 | $1,880 |
| No | 210691790 | TRANE | 4TWL9060A1 | 4PX*DU60BS3 | S8V2C100M5PCA | 37,600 | $1,880 |
| No | 211081158 | TRANE | 4TWL9060A1 | 4PX*DU60BS3 | S8V2C080M5PDA | 37,400 | $1,870 |
| No | 210691789 | TRANE | 4TWL9060A1 | 4PX*DU60BS3 | S8V2C080M5PCA | 37,400 | $1,870 |
| No | 207352637 | TRANE | 4TWL9060A1 | 4PX*DU60BS3 | L8V1C100U5VSA+RP | 37,400 | $1,870 |
| No | 201922213 | TRANE | 4TWL9060A1 | 4PX*DU60BS3 | *UHMD120ACV5 | 38,000 | $1,900 |
| No | 211596242 | TRANE | 4TWL9060A1 | 4PX*DU60BS3 | *UD2D120B9V5+RP | 38,000 | $1,900 |
| No | 201922206 | TRANE | 4TWL9060A1 | 4PX*DU60BS3 | *UD2D120ACV5 | 38,500 | $1,925 |
| No | 210649549 | TRANE | 4TWL9060A1 | 4PX*DU60BS3 | *UD2D120A9V5+RP | 37,600 | $1,880 |
| No | 210649548 | TRANE | 4TWL9060A1 | 4PX*DU60BS3 | *UD2C100B9V5+RP | 36,400 | $1,820 |
| No | 201922205 | TRANE | 4TWL9060A1 | 4PX*DU60BS3 | *UD2C100ACV5 | 37,000 | $1,850 |
| No | 210649547 | TRANE | 4TWL9060A1 | 4PX*DU60BS3 | *UD2C100A9V5+RP | 36,800 | $1,840 |
| No | 211306984 | TRANE | 4TWL9060A1 | 4PX*DU60BS3 | *DD2C100A9V5+RP | 35,800 | $1,790 |
| No | 210653440 | TRANE | 4TWL9060A1 | 4PX*DU48BS3 | S9V2D120D5PSB+RP | 38,000 | $1,900 |
| No | 210653441 | TRANE | 4TWL9060A1 | 4PX*DU48BS3 | S9V2C100D5PSB+RP | 36,800 | $1,840 |
| No | 210653439 | TRANE | 4TWL9060A1 | 4PX*DU48BS3 | *DD2D120ACV5 | 38,500 | $1,925 |
| No | 211306983 | TRANE | 4TWL9060A1 | 4PX*DU48BS3 | *DD2C100ACV5 | 37,200 | $1,860 |
| No | 207804967 | TRANE | 4TWL9060A1 | 4PX*DD60BS3+P0V0D000M50SC+RP | N/A | 38,000 | $1,900 |
| No | 207804968 | TRANE | 4TWL9060A1 | 4PX*DD60BS3+P0V0C000M50SC+RP | N/A | 37,000 | $1,850 |
| No | 210649546 | TRANE | 4TWL9060A1 | 4PX*DD60BS3+HORIZ-RT | *UD2C100A9V5+RP | 36,800 | $1,840 |
| No | 203978687 | TRANE | 4TWL9060A1 | 4PX*DD60BS3 | S9V2D120D5PSB+RP | 38,500 | $1,925 |
| No | 203864389 | TRANE | 4TWL9060A1 | 4PX*DD60BS3 | S9V2C100D5PSB+RP | 37,200 | $1,860 |
| No | 211081157 | TRANE | 4TWL9060A1 | 4PX*DD60BS3 | S8V2D120M5PDA | 38,500 | $1,925 |
| No | 210691788 | TRANE | 4TWL9060A1 | 4PX*DD60BS3 | S8V2D120M5PCA | 38,500 | $1,925 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211081156 | TRANE | 4TWL9060A1 | 4PX*DD60BS3 | S8V2C100M5PDA | 37,600 | $1,880 |
| No | 210691787 | TRANE | 4TWL9060A1 | 4PX*DD60BS3 | S8V2C100M5PCA | 37,600 | $1,880 |
| No | 211081155 | TRANE | 4TWL9060A1 | 4PX*DD60BS3 | S8V2C080M5PDA | 37,400 | $1,870 |
| No | 210691786 | TRANE | 4TWL9060A1 | 4PX*DD60BS3 | S8V2C080M5PCA | 37,400 | $1,870 |
| No | 210649545 | TRANE | 4TWL9060A1 | 4PX*DD60BS3 | *DD2D120A9V5+RP | 37,400 | $1,870 |
| No | 210649544 | TRANE | 4TWL9060A1 | 4PX*DD60BS3 | *DD2C100A9V5+RP | 36,200 | $1,810 |
| No | 207804966 | TRANE | 4TWL9060A1 | 4PX*CU60BS3+P0V0C000M50SC+RP | N/A | 38,000 | $1,900 |
| No | 201922178 | TRANE | 4TWL9060A1 | 4PX*CU60BS3 | S9V2C100U5PSB+RP | 38,500 | $1,925 |
| No | 201922177 | TRANE | 4TWL9060A1 | 4PX*CU60BS3 | S9V2C080U5PSB+RP | 38,500 | $1,925 |
| No | 211081154 | TRANE | 4TWL9060A1 | 4PX*CU60BS3 | S8V2C100M5PDA | 38,500 | $1,925 |
| No | 210691785 | TRANE | 4TWL9060A1 | 4PX*CU60BS3 | S8V2C100M5PCA | 38,500 | $1,925 |
| No | 211081153 | TRANE | 4TWL9060A1 | 4PX*CU60BS3 | S8V2C080M5PDA | 38,500 | $1,925 |
| No | 210691784 | TRANE | 4TWL9060A1 | 4PX*CU60BS3 | S8V2C080M5PCA | 38,500 | $1,925 |
| No | 207352636 | TRANE | 4TWL9060A1 | 4PX*CU60BS3 | L8V1C100U5VSA+RP | 38,500 | $1,925 |
| No | 201922180 | TRANE | 4TWL9060A1 | 4PX*CU60BS3 | *UD2C100ACV5 | 38,000 | $1,900 |
| No | 211306982 | TRANE | 4TWL9060A1 | 4PX*CU60BS3 | *DD2C100A9V5+RP | 37,000 | $1,850 |
| No | 211286026 | TRANE | 4TWL9060A1 | 4PX*CU48BS3+P0V0C000M50SC+RP | N/A | 38,500 | $1,925 |
| No | 210653437 | TRANE | 4TWL9060A1 | 4PX*CU48BS3 | S9V2C100D5PSB+RP | 38,500 | $1,925 |
| No | 211081152 | TRANE | 4TWL9060A1 | 4PX*CU48BS3 | S8V2C100M5PDA | 39,000 | $1,950 |
| No | 210691783 | TRANE | 4TWL9060A1 | 4PX*CU48BS3 | S8V2C100M5PCA | 39,000 | $1,950 |
| No | 211081151 | TRANE | 4TWL9060A1 | 4PX*CU48BS3 | S8V2C080M5PDA | 39,000 | $1,950 |
| No | 210691782 | TRANE | 4TWL9060A1 | 4PX*CU48BS3 | S8V2C080M5PCA | 39,000 | $1,950 |
| No | 210653436 | TRANE | 4TWL9060A1 | 4PX*CU48BS3 | L8V1C100U5VSA+RP | 39,000 | $1,950 |
| No | 210653438 | TRANE | 4TWL9060A1 | 4PX*CU48BS3 | *DD2C100ACV5 | 38,000 | $1,900 |
| No | 207804964 | TRANE | 4TWL9060A1 | 4PX*CD60BS3+P0V0C000M50SC+RP | N/A | 38,000 | $1,900 |
| No | 201922161 | TRANE | 4TWL9060A1 | 4PX*CD60BS3 | S9V2C100D5PSB+RP | 38,500 | $1,925 |
| No | 211081150 | TRANE | 4TWL9060A1 | 4PX*CD60BS3 | S8V2C100M5PDA | 38,500 | $1,925 |
| No | 210691781 | TRANE | 4TWL9060A1 | 4PX*CD60BS3 | S8V2C100M5PCA | 38,500 | $1,925 |
| No | 211081149 | TRANE | 4TWL9060A1 | 4PX*CD60BS3 | S8V2C080M5PDA | 38,500 | $1,925 |
| No | 210691780 | TRANE | 4TWL9060A1 | 4PX*CD60BS3 | S8V2C080M5PCA | 38,500 | $1,925 |
| No | 207820925 | TRANE | 4TWL9048A1 | TEM8B0C60V51+TDR | N/A | 31,200 | $1,560 |
| No | 207335060 | TRANE | 4TWL9048A1 | TEM8A0D60V51+TDR | N/A | 32,000 | $1,600 |
| No | 201922159 | TRANE | 4TWL9048A1 | TEM8A0D48V41+TDR | N/A | 32,200 | $1,610 |
| No | 201922157 | TRANE | 4TWL9048A1 | TEM8A0C48V41+TDR | N/A | 31,400 | $1,570 |
| No | 207804061 | TRANE | 4TWL9048A1 | TEM8A0C42V41+TDR | N/A | 32,000 | $1,600 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922156 | TRANE | 4TWL9048A1 | Heat pump with ducts | N/A | 31,600 | $1,580 |
| No | 201923708 | TRANE | 4TWL9048A1 | TAM9A0C48V41 | N/A | 31,600 | $1,580 |
| No | 201922155 | TRANE | 4TWL9048A1 | TAM9A0C42V41 | N/A | 31,600 | $1,580 |
| No | 206392942 | TRANE | 4TWL9048A1 | 4TXFH064AZ3 | *UD2C080ACV4 | 31,600 | $1,580 |
| No | 207804963 | TRANE | 4TWL9048A1 | 4TXCD010DS3+P0V0D000M50SC+RP | N/A | 31,400 | $1,570 |
| No | 207804962 | TRANE | 4TWL9048A1 | 4TXCD010DS3+P0V0C000M50SC+RP | N/A | 30,600 | $1,530 |
| No | 210653434 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | S9V2D120U5VSA+RP | 31,800 | $1,590 |
| No | 201922139 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | S9V2D120U5PSB+RP | 31,800 | $1,590 |
| No | 201922134 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | S9V2D120D5PSB+RP | 30,800 | $1,540 |
| No | 201922140 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | S9V2C100U5PSB+RP | 31,000 | $1,550 |
| No | 210653435 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | S9V2C100U4VSA+RP | 30,800 | $1,540 |
| No | 201922141 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | S9V2C100U4PSB+RP | 30,800 | $1,540 |
| No | 201922127 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | S9V2C100D5PSB+RP | 30,000 | $1,500 |
| No | 210653830 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | S9V2C100D4VSA+RP | 29,800 | $1,490 |
| No | 201922128 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | S9V2C100D4PSB+RP | 29,800 | $1,490 |
| No | 201922142 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | S9V2C080U5PSB+RP | 30,800 | $1,540 |
| No | 211081147 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | S8V2D120M5PDA | 31,800 | $1,590 |
| No | 210691778 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | S8V2D120M5PCA | 31,800 | $1,590 |
| No | 211088801 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | S8V2C100M5PDA | 31,000 | $1,550 |
| No | 210692160 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | S8V2C100M5PCA | 31,000 | $1,550 |
| No | 211081148 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | S8V2C080M5PDA | 30,800 | $1,540 |
| No | 210691779 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | S8V2C080M5PCA | 30,800 | $1,540 |
| No | 207352634 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | L8V1C100U5VSA+RP | 30,800 | $1,540 |
| No | 201922143 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | *UHMD120ACV5 | 31,600 | $1,580 |
| No | 201922144 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | *UHMC100ACV4 | 30,800 | $1,540 |
| No | 201922145 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | *UD2D140ACV5 | 31,800 | $1,590 |
| No | 201922148 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | *UD2D120ACV5 | 31,800 | $1,590 |
| No | 201922150 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | *UD2C100ACV5 | 31,200 | $1,560 |
| No | 201922135 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | *UD2C080ACV4 | 30,800 | $1,540 |
| No | 201922129 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | *DHMD120BCV5 | 31,000 | $1,550 |
| No | 201922130 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | *DHMC100ACV4 | 30,200 | $1,510 |
| No | 201922131 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | *DD2D120ACV5 | 30,800 | $1,540 |
| No | 201922132 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | *DD2C100ACV5 | 30,000 | $1,500 |
| No | 207804961 | TRANE | 4TWL9048A1 | 4TXCD008DS3+P0V0D000M50SC+RP | N/A | 32,000 | $1,600 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207804960 | TRANE | 4TWL9048A1 | 4TXCD008DS3+P0V0C000M50SC+RP | N/A | 31,000 | $1,550 |
| No | 210653432 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | S9V2D120U5VSA+RP | 32,200 | $1,610 |
| No | 201922121 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | S9V2D120U5PSB+RP | 32,200 | $1,610 |
| No | 201922111 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | S9V2D120D5PSB+RP | 31,400 | $1,570 |
| No | 201922122 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | S9V2C100U5PSB+RP | 31,400 | $1,570 |
| No | 210653433 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | S9V2C100U4VSA+RP | 31,200 | $1,560 |
| No | 201922123 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | S9V2C100U4PSB+RP | 31,200 | $1,560 |
| No | 201922112 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | S9V2C100D5PSB+RP | 30,600 | $1,530 |
| No | 210653829 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | S9V2C100D4VSA+RP | 30,400 | $1,520 |
| No | 201922113 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | S9V2C100D4PSB+RP | 30,400 | $1,520 |
| No | 201922124 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | S9V2C080U5PSB+RP | 31,400 | $1,570 |
| No | 211081146 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | S8V2D120M5PDA | 32,200 | $1,610 |
| No | 210691777 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | S8V2D120M5PCA | 32,200 | $1,610 |
| No | 211088799 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | S8V2C100M5PDA | 31,400 | $1,570 |
| No | 210692158 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | S8V2C100M5PCA | 31,400 | $1,570 |
| No | 211088800 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | S8V2C080M5PDA | 31,200 | $1,560 |
| No | 210692159 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | S8V2C080M5PCA | 31,200 | $1,560 |
| No | 207352633 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | L8V1C100U5VSA+RP | 31,200 | $1,560 |
| No | 201922099 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | *UHMD120ACV5 | 32,200 | $1,610 |
| No | 201922100 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | *UHMC100ACV4 | 31,200 | $1,560 |
| No | 201922101 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | *UD2D140ACV5 | 32,200 | $1,610 |
| No | 201922104 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | *UD2D120ACV5 | 32,200 | $1,610 |
| No | 201922107 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | *UD2C100ACV5 | 31,400 | $1,570 |
| No | 201922108 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | *UD2C080ACV4 | 31,200 | $1,560 |
| No | 201922114 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | *DHMD120BCV5 | 31,600 | $1,580 |
| No | 201922115 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | *DHMC100ACV4 | 30,600 | $1,530 |
| No | 201922116 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | *DD2D120ACV5 | 31,400 | $1,570 |
| No | 201922118 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | *DD2C100ACV5 | 30,600 | $1,530 |
| No | 207804959 | TRANE | 4TWL9048A1 | 4TXCC009DS3+P0V0C000M50SC+RP | N/A | 31,600 | $1,580 |
| No | 201922094 | TRANE | 4TWL9048A1 | 4TXCC009DS3 | S9V2C100U5PSB+RP | 32,000 | $1,600 |
| No | 210653430 | TRANE | 4TWL9048A1 | 4TXCC009DS3 | S9V2C100U4VSA+RP | 31,800 | $1,590 |
| No | 201922093 | TRANE | 4TWL9048A1 | 4TXCC009DS3 | S9V2C100U4PSB+RP | 31,800 | $1,590 |
| No | 201922087 | TRANE | 4TWL9048A1 | 4TXCC009DS3 | S9V2C100D5PSB+RP | 31,000 | $1,550 |
| No | 210653431 | TRANE | 4TWL9048A1 | 4TXCC009DS3 | S9V2C100D4VSA+RP | 30,800 | $1,540 |
| No | 201922086 | TRANE | 4TWL9048A1 | 4TXCC009DS3 | S9V2C100D4PSB+RP | 30,800 | $1,540 |
| No | 201922092 | TRANE | 4TWL9048A1 | 4TXCC009DS3 | S9V2C080U5PSB+RP | 31,800 | $1,590 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211081145 | TRANE | 4TWL9048A1 | 4TXCC009DS3 | S8V2C100M5PDA | 32,000 | $1,600 |
| No | 210691776 | TRANE | 4TWL9048A1 | 4TXCC009DS3 | S8V2C100M5PCA | 32,000 | $1,600 |
| No | 211081144 | TRANE | 4TWL9048A1 | 4TXCC009DS3 | S8V2C080M5PDA | 31,800 | $1,590 |
| No | 210691775 | TRANE | 4TWL9048A1 | 4TXCC009DS3 | S8V2C080M5PCA | 31,800 | $1,590 |
| No | 207352632 | TRANE | 4TWL9048A1 | 4TXCC009DS3 | L8V1C100U5VSA+RP | 31,800 | $1,590 |
| No | 201922090 | TRANE | 4TWL9048A1 | 4TXCC009DS3 | *UHMC100ACV4 | 31,800 | $1,590 |
| No | 201922088 | TRANE | 4TWL9048A1 | 4TXCC009DS3 | *UD2C100ACV5 | 32,200 | $1,610 |
| No | 201922096 | TRANE | 4TWL9048A1 | 4TXCC009DS3 | *UD2C080ACV4 | 31,800 | $1,590 |
| No | 201922085 | TRANE | 4TWL9048A1 | 4TXCC009DS3 | *DHMC100ACV4 | 31,000 | $1,550 |
| No | 201922084 | TRANE | 4TWL9048A1 | 4TXCC009DS3 | *DD2C100ACV5 | 30,800 | $1,540 |
| No | 207804958 | TRANE | 4TWL9048A1 | 4TXCC007DS3+P0V0C000M50SC+RP | N/A | 31,800 | $1,590 |
| No | 201922075 | TRANE | 4TWL9048A1 | 4TXCC007DS3 | S9V2C100U5PSB+RP | 32,400 | $1,620 |
| No | 210653429 | TRANE | 4TWL9048A1 | 4TXCC007DS3 | S9V2C100U4VSA+RP | 32,000 | $1,600 |
| No | 201922076 | TRANE | 4TWL9048A1 | 4TXCC007DS3 | S9V2C100U4PSB+RP | 32,200 | $1,610 |
| No | 201922071 | TRANE | 4TWL9048A1 | 4TXCC007DS3 | S9V2C100D5PSB+RP | 31,600 | $1,580 |
| No | 210653428 | TRANE | 4TWL9048A1 | 4TXCC007DS3 | S9V2C100D4VSA+RP | 31,400 | $1,570 |
| No | 201922070 | TRANE | 4TWL9048A1 | 4TXCC007DS3 | S9V2C100D4PSB+RP | 31,400 | $1,570 |
| No | 201922074 | TRANE | 4TWL9048A1 | 4TXCC007DS3 | S9V2C080U5PSB+RP | 32,400 | $1,620 |
| No | 211081143 | TRANE | 4TWL9048A1 | 4TXCC007DS3 | S8V2C100M5PDA | 32,200 | $1,610 |
| No | 210691774 | TRANE | 4TWL9048A1 | 4TXCC007DS3 | S8V2C100M5PCA | 32,200 | $1,610 |
| No | 211081142 | TRANE | 4TWL9048A1 | 4TXCC007DS3 | S8V2C080M5PDA | 32,200 | $1,610 |
| No | 210691773 | TRANE | 4TWL9048A1 | 4TXCC007DS3 | S8V2C080M5PCA | 32,200 | $1,610 |
| No | 207352631 | TRANE | 4TWL9048A1 | 4TXCC007DS3 | L8V1C100U5VSA+RP | 32,000 | $1,600 |
| No | 201922081 | TRANE | 4TWL9048A1 | 4TXCC007DS3 | *UHMC100ACV4 | 32,200 | $1,610 |
| No | 201922078 | TRANE | 4TWL9048A1 | 4TXCC007DS3 | *UD2C100ACV5 | 32,200 | $1,610 |
| No | 201922072 | TRANE | 4TWL9048A1 | 4TXCC007DS3 | *UD2C080ACV4 | 32,200 | $1,610 |
| No | 201922069 | TRANE | 4TWL9048A1 | 4TXCC007DS3 | *DHMC100ACV4 | 32,000 | $1,600 |
| No | 201922080 | TRANE | 4TWL9048A1 | 4TXCC007DS3 | *DD2C100ACV5 | 31,400 | $1,570 |
| No | 210653427 | TRANE | 4TWL9048A1 | 4TXCC005DS3 | S9V2C100U4VSA+RP | 32,600 | $1,630 |
| No | 210653426 | TRANE | 4TWL9048A1 | 4TXCC005DS3 | S9V2C100U4PSB+RP | 32,600 | $1,630 |
| No | 210653425 | TRANE | 4TWL9048A1 | 4TXCC005DS3 | S9V2C080U5PSB+RP | 32,800 | $1,640 |
| No | 211081141 | TRANE | 4TWL9048A1 | 4TXCC005DS3 | S8V2C080M5PDA | 32,600 | $1,630 |
| No | 210691772 | TRANE | 4TWL9048A1 | 4TXCC005DS3 | S8V2C080M5PCA | 32,600 | $1,630 |
| No | 201922068 | TRANE | 4TWL9048A1 | 4TXCC005DS3 | *UHMC100ACV4 | 32,600 | $1,630 |
| No | 201922065 | TRANE | 4TWL9048A1 | 4TXCC005DS3 | *UD2C100ACV5 | 32,600 | $1,630 |
| No | 201922067 | TRANE | 4TWL9048A1 | 4TXCC005DS3 | *UD2C080ACV4 | 32,600 | $1,630 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208185441 | TRANE | 4TWL9048A1 | 4TXCB006DS3+P0V0B000M40SC+RP | N/A | 31,600 | $1,580 |
| No | 210653423 | TRANE | 4TWL9048A1 | 4TXCB006DS3 | S9V2B080U4VSA+RP | 32,600 | $1,630 |
| No | 201922062 | TRANE | 4TWL9048A1 | 4TXCB006DS3 | S9V2B080U4PSB+RP | 32,600 | $1,630 |
| No | 210653424 | TRANE | 4TWL9048A1 | 4TXCB006DS3 | S9V2B080D4VSA+RP | 31,600 | $1,580 |
| No | 201922064 | TRANE | 4TWL9048A1 | 4TXCB006DS3 | S9V2B080D4PSB+RP | 31,600 | $1,580 |
| No | 201922063 | TRANE | 4TWL9048A1 | 4TXCB006DS3 | S9V2B060U4PSB+RP | 32,600 | $1,630 |
| No | 211081139 | TRANE | 4TWL9048A1 | 4TXCB006DS3 | S8V2B080M4PDA | 32,600 | $1,630 |
| No | 210691771 | TRANE | 4TWL9048A1 | 4TXCB006DS3 | S8V2B080M4PCA | 32,600 | $1,630 |
| No | 211081140 | TRANE | 4TWL9048A1 | 4TXCB006DS3 | S8V2B060M4PDA | 32,600 | $1,630 |
| No | 210691770 | TRANE | 4TWL9048A1 | 4TXCB006DS3 | S8V2B060M4PCA | 32,600 | $1,630 |
| No | 210653422 | TRANE | 4TWL9048A1 | 4TXCB006DS3 | L8V1B080U4VSA+RP | 32,600 | $1,630 |
| No | 207804956 | TRANE | 4TWL9048A1 | 4PX*DU60BS3+P0V0D000M50SC+RP | N/A | 31,400 | $1,570 |
| No | 207804955 | TRANE | 4TWL9048A1 | 4PX*DU60BS3+P0V0C000M50SC+RP | N/A | 30,600 | $1,530 |
| No | 210653418 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | S9V2D120U5VSA+RP | 31,600 | $1,580 |
| No | 201922060 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | S9V2D120U5PSB+RP | 31,800 | $1,590 |
| No | 210653421 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | S9V2D120D5PSB+RP | 30,800 | $1,540 |
| No | 201922059 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | S9V2C100U5PSB+RP | 31,000 | $1,550 |
| No | 210653417 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | S9V2C100U4VSA+RP | 30,800 | $1,540 |
| No | 201922058 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | S9V2C100U4PSB+RP | 30,800 | $1,540 |
| No | 210653828 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | S9V2C100D5PSB+RP | 30,000 | $1,500 |
| No | 210653827 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | S9V2C100D4VSA+RP | 29,800 | $1,490 |
| No | 210653826 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | S9V2C100D4PSB+RP | 29,800 | $1,490 |
| No | 201922014 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | S9V2C080U5PSB+RP | 31,000 | $1,550 |
| No | 211081137 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | S8V2D120M5PDA | 31,800 | $1,590 |
| No | 210691769 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | S8V2D120M5PCA | 31,800 | $1,590 |
| No | 211088798 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | S8V2C100M5PDA | 30,800 | $1,540 |
| No | 210692157 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | S8V2C100M5PCA | 30,800 | $1,540 |
| No | 211081138 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | S8V2C080M5PDA | 30,800 | $1,540 |
| No | 210691768 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | S8V2C080M5PCA | 30,800 | $1,540 |
| No | 207352630 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | L8V1C100U5VSA+RP | 30,800 | $1,540 |
| No | 201922061 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | *UHMD120ACV5 | 31,600 | $1,580 |
| No | 201922028 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | *UHMC100ACV4 | 30,800 | $1,540 |
| No | 201922034 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | *UD2D140ACV5 | 31,800 | $1,590 |
| No | 201922050 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | *UD2D120ACV5 | 31,800 | $1,590 |
| No | 201922053 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | *UD2C100ACV5 | 31,200 | $1,560 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922056 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | *UD2C080ACV4 | 30,800 | $1,540 |
| No | 210653420 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | *DHMD120BCV5 | 31,000 | $1,550 |
| No | 210653825 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | *DHMC100ACV4 | 30,000 | $1,500 |
| No | 210653419 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | *DD2D120ACV5 | 30,600 | $1,530 |
| No | 210649543 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | *DD2D120A9V5+RP | 30,600 | $1,530 |
| No | 210653824 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | *DD2C100ACV5 | 30,000 | $1,500 |
| No | 207804954 | TRANE | 4TWL9048A1 | 4PX*DU48BS3+P0V0D000M50SC+RP | N/A | 31,800 | $1,590 |
| No | 207804953 | TRANE | 4TWL9048A1 | 4PX*DU48BS3+P0V0C000M50SC+RP | N/A | 31,200 | $1,560 |
| No | 210653415 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | S9V2D120U5VSA+RP | 32,200 | $1,610 |
| No | 201922011 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | S9V2D120U5PSB+RP | 32,200 | $1,610 |
| No | 210653412 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | S9V2D120D5PSB+RP | 31,600 | $1,580 |
| No | 201922010 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | S9V2C100U5PSB+RP | 31,200 | $1,560 |
| No | 210653416 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | S9V2C100U4VSA+RP | 31,400 | $1,570 |
| No | 201922009 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | S9V2C100U4PSB+RP | 31,200 | $1,560 |
| No | 210653823 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | S9V2C100D5PSB+RP | 30,600 | $1,530 |
| No | 210653822 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | S9V2C100D4VSA+RP | 30,400 | $1,520 |
| No | 210653819 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | S9V2C100D4PSB+RP | 30,400 | $1,520 |
| No | 201921996 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | S9V2C080U5PSB+RP | 31,400 | $1,570 |
| No | 211081136 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | S8V2D120M5PDA | 32,400 | $1,620 |
| No | 210691767 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | S8V2D120M5PCA | 32,400 | $1,620 |
| No | 211088796 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | S8V2C100M5PDA | 31,400 | $1,570 |
| No | 210692156 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | S8V2C100M5PCA | 31,400 | $1,570 |
| No | 211088797 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | S8V2C080M5PDA | 31,200 | $1,560 |
| No | 210692155 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | S8V2C080M5PCA | 31,200 | $1,560 |
| No | 207352629 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | L8V1C100U5VSA+RP | 31,200 | $1,560 |
| No | 201921995 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | *UHMD120ACV5 | 32,200 | $1,610 |
| No | 201922008 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | *UHMC100ACV4 | 31,200 | $1,560 |
| No | 201921997 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | *UD2D140ACV5 | 32,200 | $1,610 |
| No | 201922000 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | *UD2D120ACV5 | 32,200 | $1,610 |
| No | 201922003 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | *UD2C100ACV5 | 31,400 | $1,570 |
| No | 201922004 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | *UD2C080ACV4 | 31,200 | $1,560 |
| No | 210653413 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | *DHMD120BCV5 | 31,600 | $1,580 |
| No | 210653820 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | *DHMC100ACV4 | 30,800 | $1,540 |
| No | 210653414 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | *DD2D120ACV5 | 31,600 | $1,580 |
| No | 210649542 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | *DD2D120A9V5+RP | 31,200 | $1,560 |
| No | 210653821 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | *DD2C100ACV5 | 30,600 | $1,530 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207804949 | TRANE | 4TWL9048A1 | 4PX*DD60BS3+P0V0D000M50SC+RP | N/A | 31,400 | $1,570 |
| No | 207804950 | TRANE | 4TWL9048A1 | 4PX*DD60BS3+P0V0C000M50SC+RP | N/A | 30,600 | $1,530 |
| No | 201921992 | TRANE | 4TWL9048A1 | 4PX*DD60BS3+HORIZ-RT | *UD2D140ACV5 | 31,800 | $1,590 |
| No | 201921980 | TRANE | 4TWL9048A1 | 4PX*DD60BS3+HORIZ-RT | *UD2D120ACV5 | 32,000 | $1,600 |
| No | 201921983 | TRANE | 4TWL9048A1 | 4PX*DD60BS3+HORIZ-RT | *UD2C100ACV5 | 31,200 | $1,560 |
| No | 201921986 | TRANE | 4TWL9048A1 | 4PX*DD60BS3+HORIZ-RT | *UD2C080ACV4 | 30,800 | $1,540 |
| No | 201921974 | TRANE | 4TWL9048A1 | 4PX*DD60BS3 | S9V2D120D5PSB+RP | 31,800 | $1,590 |
| No | 201921977 | TRANE | 4TWL9048A1 | 4PX*DD60BS3 | S9V2C100D5PSB+RP | 31,000 | $1,550 |
| No | 210653411 | TRANE | 4TWL9048A1 | 4PX*DD60BS3 | S9V2C100D4VSA+RP | 30,800 | $1,540 |
| No | 201921970 | TRANE | 4TWL9048A1 | 4PX*DD60BS3 | S9V2C100D4PSB+RP | 30,800 | $1,540 |
| No | 211081135 | TRANE | 4TWL9048A1 | 4PX*DD60BS3 | S8V2D120M5PDA | 31,800 | $1,590 |
| No | 210691766 | TRANE | 4TWL9048A1 | 4PX*DD60BS3 | S8V2D120M5PCA | 31,800 | $1,590 |
| No | 211088795 | TRANE | 4TWL9048A1 | 4PX*DD60BS3 | S8V2C100M5PDA | 31,000 | $1,550 |
| No | 210692154 | TRANE | 4TWL9048A1 | 4PX*DD60BS3 | S8V2C100M5PCA | 31,000 | $1,550 |
| No | 211081134 | TRANE | 4TWL9048A1 | 4PX*DD60BS3 | S8V2C080M5PDA | 30,800 | $1,540 |
| No | 210691765 | TRANE | 4TWL9048A1 | 4PX*DD60BS3 | S8V2C080M5PCA | 30,800 | $1,540 |
| No | 201921976 | TRANE | 4TWL9048A1 | 4PX*DD60BS3 | *DHMD120BCV5 | 32,000 | $1,600 |
| No | 201921975 | TRANE | 4TWL9048A1 | 4PX*DD60BS3 | *DHMC100ACV4 | 31,000 | $1,550 |
| No | 201921979 | TRANE | 4TWL9048A1 | 4PX*DD60BS3 | *DD2D120ACV5 | 31,800 | $1,590 |
| No | 201921972 | TRANE | 4TWL9048A1 | 4PX*DD60BS3 | *DD2C100ACV5 | 31,000 | $1,550 |
| No | 207804944 | TRANE | 4TWL9048A1 | 4PX*CU60BS3+P0V0C000M50SC+RP | N/A | 31,600 | $1,580 |
| No | 201921943 | TRANE | 4TWL9048A1 | 4PX*CU60BS3 | S9V2C100U5PSB+RP | 32,000 | $1,600 |
| No | 210653406 | TRANE | 4TWL9048A1 | 4PX*CU60BS3 | S9V2C100U4VSA+RP | 31,800 | $1,590 |
| No | 201921946 | TRANE | 4TWL9048A1 | 4PX*CU60BS3 | S9V2C100U4PSB+RP | 31,800 | $1,590 |
| No | 210653409 | TRANE | 4TWL9048A1 | 4PX*CU60BS3 | S9V2C100D5PSB+RP | 31,000 | $1,550 |
| No | 210653410 | TRANE | 4TWL9048A1 | 4PX*CU60BS3 | S9V2C100D4VSA+RP | 30,800 | $1,540 |
| No | 202544273 | TRANE | 4TWL9048A1 | 4PX*CU60BS3 | S9V2C100D4PSB+RP | 30,800 | $1,540 |
| No | 201921940 | TRANE | 4TWL9048A1 | 4PX*CU60BS3 | S9V2C080U5PSB+RP | 31,800 | $1,590 |
| No | 211081132 | TRANE | 4TWL9048A1 | 4PX*CU60BS3 | S8V2C100M5PDA | 32,000 | $1,600 |
| No | 210691764 | TRANE | 4TWL9048A1 | 4PX*CU60BS3 | S8V2C100M5PCA | 32,000 | $1,600 |
| No | 211081133 | TRANE | 4TWL9048A1 | 4PX*CU60BS3 | S8V2C080M5PDA | 31,800 | $1,590 |
| No | 210691763 | TRANE | 4TWL9048A1 | 4PX*CU60BS3 | S8V2C080M5PCA | 31,800 | $1,590 |
| No | 207352628 | TRANE | 4TWL9048A1 | 4PX*CU60BS3 | L8V1C100U5VSA+RP | 31,800 | $1,590 |
| No | 201921938 | TRANE | 4TWL9048A1 | 4PX*CU60BS3 | *UHMC100ACV4 | 31,800 | $1,590 |
| No | 201921944 | TRANE | 4TWL9048A1 | 4PX*CU60BS3 | *UD2C100ACV5 | 32,200 | $1,610 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201921945 | TRANE | 4TWL9048A1 | 4PX*CU60BS3 | *UD2C080ACV4 | 31,800 | $1,590 |
| No | 210653408 | TRANE | 4TWL9048A1 | 4PX*CU60BS3 | *DHMC100ACV4 | 31,000 | $1,550 |
| No | 210653407 | TRANE | 4TWL9048A1 | 4PX*CU60BS3 | *DD2C100ACV5 | 30,800 | $1,540 |
| No | 210649541 | TRANE | 4TWL9048A1 | 4PX*CU60BS3 | *DD2C100A9V5+RP | 30,800 | $1,540 |
| No | 207804943 | TRANE | 4TWL9048A1 | 4PX*CU48BS3+P0V0C000M50SC+RP | N/A | 32,000 | $1,600 |
| No | 201921936 | TRANE | 4TWL9048A1 | 4PX*CU48BS3 | S9V2C100U5PSB+RP | 32,400 | $1,620 |
| No | 210653401 | TRANE | 4TWL9048A1 | 4PX*CU48BS3 | S9V2C100U4VSA+RP | 32,200 | $1,610 |
| No | 201921935 | TRANE | 4TWL9048A1 | 4PX*CU48BS3 | S9V2C100U4PSB+RP | 32,200 | $1,610 |
| No | 210653405 | TRANE | 4TWL9048A1 | 4PX*CU48BS3 | S9V2C100D5PSB+RP | 31,600 | $1,580 |
| No | 210653404 | TRANE | 4TWL9048A1 | 4PX*CU48BS3 | S9V2C100D4VSA+RP | 31,400 | $1,570 |
| No | 210653403 | TRANE | 4TWL9048A1 | 4PX*CU48BS3 | S9V2C100D4PSB+RP | 31,400 | $1,570 |
| No | 201921928 | TRANE | 4TWL9048A1 | 4PX*CU48BS3 | S9V2C080U5PSB+RP | 32,400 | $1,620 |
| No | 211081130 | TRANE | 4TWL9048A1 | 4PX*CU48BS3 | S8V2C100M5PDA | 32,200 | $1,610 |
| No | 210691762 | TRANE | 4TWL9048A1 | 4PX*CU48BS3 | S8V2C100M5PCA | 32,200 | $1,610 |
| No | 211081131 | TRANE | 4TWL9048A1 | 4PX*CU48BS3 | S8V2C080M5PDA | 32,200 | $1,610 |
| No | 210691761 | TRANE | 4TWL9048A1 | 4PX*CU48BS3 | S8V2C080M5PCA | 32,200 | $1,610 |
| No | 207352627 | TRANE | 4TWL9048A1 | 4PX*CU48BS3 | L8V1C100U5VSA+RP | 32,200 | $1,610 |
| No | 201921927 | TRANE | 4TWL9048A1 | 4PX*CU48BS3 | *UHMC100ACV4 | 32,200 | $1,610 |
| No | 201921933 | TRANE | 4TWL9048A1 | 4PX*CU48BS3 | *UD2C100ACV5 | 32,400 | $1,620 |
| No | 201921930 | TRANE | 4TWL9048A1 | 4PX*CU48BS3 | *UD2C080ACV4 | 32,200 | $1,610 |
| No | 210653402 | TRANE | 4TWL9048A1 | 4PX*CU48BS3 | *DHMC100ACV4 | 31,600 | $1,580 |
| No | 207259421 | TRANE | 4TWL9048A1 | 4PX*CU48BS3 | *DD2C100ACV5 | 31,400 | $1,570 |
| No | 210649540 | TRANE | 4TWL9048A1 | 4PX*CU48BS3 | *DD2C100A9V5+RP | 31,000 | $1,550 |
| No | 207804942 | TRANE | 4TWL9048A1 | 4PX*CU42BS3+P0V0C000M50SC+RP | N/A | 32,400 | $1,620 |
| No | 201921924 | TRANE | 4TWL9048A1 | 4PX*CU42BS3 | S9V2C100U5PSB+RP | 32,600 | $1,630 |
| No | 210653397 | TRANE | 4TWL9048A1 | 4PX*CU42BS3 | S9V2C100U4VSA+RP | 32,600 | $1,630 |
| No | 201921923 | TRANE | 4TWL9048A1 | 4PX*CU42BS3 | S9V2C100U4PSB+RP | 32,400 | $1,620 |
| No | 210653400 | TRANE | 4TWL9048A1 | 4PX*CU42BS3 | S9V2C100D5PSB+RP | 31,800 | $1,590 |
| No | 210653399 | TRANE | 4TWL9048A1 | 4PX*CU42BS3 | S9V2C100D4VSA+RP | 31,800 | $1,590 |
| No | 210653398 | TRANE | 4TWL9048A1 | 4PX*CU42BS3 | S9V2C100D4PSB+RP | 32,000 | $1,600 |
| No | 201921922 | TRANE | 4TWL9048A1 | 4PX*CU42BS3 | S9V2C080U5PSB+RP | 32,600 | $1,630 |
| No | 211081128 | TRANE | 4TWL9048A1 | 4PX*CU42BS3 | S8V2C100M5PDA | 32,600 | $1,630 |
| No | 210691760 | TRANE | 4TWL9048A1 | 4PX*CU42BS3 | S8V2C100M5PCA | 32,600 | $1,630 |
| No | 211081129 | TRANE | 4TWL9048A1 | 4PX*CU42BS3 | S8V2C080M5PDA | 32,600 | $1,630 |
| No | 210691759 | TRANE | 4TWL9048A1 | 4PX*CU42BS3 | S8V2C080M5PCA | 32,600 | $1,630 |
| No | 207352626 | TRANE | 4TWL9048A1 | 4PX*CU42BS3 | L8V1C100U5VSA+RP | 32,400 | $1,620 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201921926 | TRANE | 4TWL9048A1 | 4PX*CU42BS3 | *UHMC100ACV4 | 32,400 | $1,620 |
| No | 201921919 | TRANE | 4TWL9048A1 | 4PX*CU42BS3 | *UD2C100ACV5 | 32,600 | $1,630 |
| No | 201921921 | TRANE | 4TWL9048A1 | 4PX*CU42BS3 | *UD2C080ACV4 | 32,400 | $1,620 |
| No | 202586171 | TRANE | 4TWL9048A1 | 4PX*CU42BS3 | *DHMC100ACV4 | 32,200 | $1,610 |
| No | 202586170 | TRANE | 4TWL9048A1 | 4PX*CU42BS3 | *DD2C100ACV5 | 32,000 | $1,600 |
| No | 210649539 | TRANE | 4TWL9048A1 | 4PX*CU42BS3 | *DD2C100A9V5+RP | 31,600 | $1,580 |
| No | 207804940 | TRANE | 4TWL9048A1 | 4PX*CD60BS3+P0V0C000M50SC+RP | N/A | 31,400 | $1,570 |
| No | 201921908 | TRANE | 4TWL9048A1 | 4PX*CD60BS3+HORIZ-RT | *UD2C100ACV5 | 32,200 | $1,610 |
| No | 201921911 | TRANE | 4TWL9048A1 | 4PX*CD60BS3+HORIZ-RT | *UD2C080ACV4 | 31,800 | $1,590 |
| No | 201921900 | TRANE | 4TWL9048A1 | 4PX*CD60BS3 | S9V2C100D5PSB+RP | 31,800 | $1,590 |
| No | 210653396 | TRANE | 4TWL9048A1 | 4PX*CD60BS3 | S9V2C100D4VSA+RP | 31,800 | $1,590 |
| No | 201921901 | TRANE | 4TWL9048A1 | 4PX*CD60BS3 | S9V2C100D4PSB+RP | 31,800 | $1,590 |
| No | 211081126 | TRANE | 4TWL9048A1 | 4PX*CD60BS3 | S8V2C100M5PDA | 31,800 | $1,590 |
| No | 210691757 | TRANE | 4TWL9048A1 | 4PX*CD60BS3 | S8V2C100M5PCA | 31,800 | $1,590 |
| No | 211081127 | TRANE | 4TWL9048A1 | 4PX*CD60BS3 | S8V2C080M5PDA | 31,800 | $1,590 |
| No | 210691758 | TRANE | 4TWL9048A1 | 4PX*CD60BS3 | S8V2C080M5PCA | 31,800 | $1,590 |
| No | 201921903 | TRANE | 4TWL9048A1 | 4PX*CD60BS3 | *DHMC100ACV4 | 31,800 | $1,590 |
| No | 201921904 | TRANE | 4TWL9048A1 | 4PX*CD60BS3 | *DD2C100ACV5 | 31,800 | $1,590 |
| No | 211289102 | TRANE | 4TWL9048A1 | 4PX*BU48BS3+P0V0B000M40SC+RP | N/A | 31,400 | $1,570 |
| No | 210653395 | TRANE | 4TWL9048A1 | 4PX*BU48BS3 | S9V2B080U4VSA+RP | 32,600 | $1,630 |
| No | 201921887 | TRANE | 4TWL9048A1 | 4PX*BU48BS3 | S9V2B080U4PSB+RP | 32,600 | $1,630 |
| No | 210653394 | TRANE | 4TWL9048A1 | 4PX*BU48BS3 | S9V2B080D4VSA+RP | 31,600 | $1,580 |
| No | 207786383 | TRANE | 4TWL9048A1 | 4PX*BU48BS3 | S9V2B080D4PSB+RP | 31,600 | $1,580 |
| No | 201921886 | TRANE | 4TWL9048A1 | 4PX*BU48BS3 | S9V2B060U4PSB+RP | 32,600 | $1,630 |
| No | 211081124 | TRANE | 4TWL9048A1 | 4PX*BU48BS3 | S8V2B080M4PDA | 32,600 | $1,630 |
| No | 210691756 | TRANE | 4TWL9048A1 | 4PX*BU48BS3 | S8V2B080M4PCA | 32,600 | $1,630 |
| No | 211081125 | TRANE | 4TWL9048A1 | 4PX*BU48BS3 | S8V2B060M4PDA | 32,400 | $1,620 |
| No | 210691755 | TRANE | 4TWL9048A1 | 4PX*BU48BS3 | S8V2B060M4PCA | 32,400 | $1,620 |
| No | 210653393 | TRANE | 4TWL9048A1 | 4PX*BU48BS3 | L8V1B080U4VSA+RP | 32,600 | $1,630 |
| No | 210653818 | TRANE | 4TWL9048A1 | 4PX*BU42BS3 | S9V2B080D4VSA+RP | 32,000 | $1,600 |
| No | 210653817 | TRANE | 4TWL9048A1 | 4PX*BU42BS3 | S9V2B080D4PSB+RP | 32,000 | $1,600 |
| No | 210636916 | TRANE | 4TWL9036A1 | TEM8A0D60V51+TDR | N/A | 23,400 | $1,170 |
| No | 201921882 | TRANE | 4TWL9036A1 | TEM8A0D48V41+TDR | N/A | 23,600 | $1,180 |
| No | 201921881 | TRANE | 4TWL9036A1 | TEM8A0C48V41+TDR | N/A | 23,000 | $1,150 |
| No | 201921880 | TRANE | 4TWL9036A1 | TEM8A0C42V41+TDR | N/A | 23,400 | $1,170 |
| No | 201921879 | TRANE | 4TWL9036A1 | TEM8A0C36V31+TDR | N/A | 23,200 | $1,160 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202538580 | TRANE | 4TWL9036A1 | TEM8A0B30V31+TDR | N/A | 24,200 | $1,210 |
| No | 208480481 | TRANE | 4TWL9036A1 | TAM9A0C48V41 | N/A | 23,000 | $1,150 |
| No | 201921878 | TRANE | 4TWL9036A1 | TAM9A0C42V41 | N/A | 22,800 | $1,140 |
| No | 201921877 | TRANE | 4TWL9036A1 | TAM9A0B30V31 | N/A | 24,000 | $1,200 |
| No | 201921870 | TRANE | 4TWL9036A1 | 4TXFH036CZ3 | *UD2C100ACV5 | 23,400 | $1,170 |
| No | 201921866 | TRANE | 4TWL9036A1 | 4TXFH036CZ3 | *UD2C080ACV4 | 23,200 | $1,160 |
| No | 201921868 | TRANE | 4TWL9036A1 | 4TXFH036CZ3 | *UD2B080ACV3 | 23,600 | $1,180 |
| No | 201921869 | TRANE | 4TWL9036A1 | 4TXFH036CZ3 | *UD2B060ACV3 | 23,600 | $1,180 |
| No | 206216700 | TRANE | 4TWL9036A1 | 4TXFH036CZ3 | *DHMB060BCV3 | 23,600 | $1,180 |
| No | 211081123 | TRANE | 4TWL9036A1 | 4TXCD010DS3 | S8V2D120M5PDA | 23,200 | $1,160 |
| No | 210691754 | TRANE | 4TWL9036A1 | 4TXCD010DS3 | S8V2D120M5PCA | 23,200 | $1,160 |
| No | 210649538 | TRANE | 4TWL9036A1 | 4TXCD010DS3 | *UD2D120A9V5+RP | 23,400 | $1,170 |
| No | 211081122 | TRANE | 4TWL9036A1 | 4TXCD008DS3 | S8V2D120M5PDA | 23,600 | $1,180 |
| No | 210691753 | TRANE | 4TWL9036A1 | 4TXCD008DS3 | S8V2D120M5PCA | 23,600 | $1,180 |
| No | 210649536 | TRANE | 4TWL9036A1 | 4TXCD008DS3 | *UD2D120A9V5+RP | 23,600 | $1,180 |
| No | 210649537 | TRANE | 4TWL9036A1 | 4TXCD008DS3 | *DD2D120A9V5+RP | 22,600 | $1,130 |
| No | 209559372 | TRANE | 4TWL9036A1 | 4TXCC009DS3 | S9V2C100U4VSA+RP | 23,000 | $1,150 |
| No | 210653392 | TRANE | 4TWL9036A1 | 4TXCC009DS3 | S9V2C100U4PSB+RP | 22,800 | $1,140 |
| No | 211081121 | TRANE | 4TWL9036A1 | 4TXCC009DS3 | S8V2C100M5PDA | 23,400 | $1,170 |
| No | 210691752 | TRANE | 4TWL9036A1 | 4TXCC009DS3 | S8V2C100M5PCA | 23,400 | $1,170 |
| No | 211081120 | TRANE | 4TWL9036A1 | 4TXCC009DS3 | S8V2C080M5PDA | 23,200 | $1,160 |
| No | 210691751 | TRANE | 4TWL9036A1 | 4TXCC009DS3 | S8V2C080M5PCA | 23,200 | $1,160 |
| No | 210653391 | TRANE | 4TWL9036A1 | 4TXCC009DS3 | L8V1C100U5VSA+RP | 23,200 | $1,160 |
| No | 201921852 | TRANE | 4TWL9036A1 | 4TXCC009DS3 | *UHMC100ACV4 | 23,200 | $1,160 |
| No | 210649535 | TRANE | 4TWL9036A1 | 4TXCC009DS3 | *UD2C100B9V5+RP | 23,200 | $1,160 |
| No | 201921851 | TRANE | 4TWL9036A1 | 4TXCC009DS3 | *UD2C100ACV5 | 23,400 | $1,170 |
| No | 210649534 | TRANE | 4TWL9036A1 | 4TXCC009DS3 | *UD2C100A9V5+RP | 23,200 | $1,160 |
| No | 210649533 | TRANE | 4TWL9036A1 | 4TXCC009DS3 | *UD2C080B9V4+RP | 23,200 | $1,160 |
| No | 201921850 | TRANE | 4TWL9036A1 | 4TXCC009DS3 | *UD2C080ACV4 | 23,200 | $1,160 |
| No | 210649532 | TRANE | 4TWL9036A1 | 4TXCC009DS3 | *UD2C080A9V4+RP | 23,600 | $1,180 |
| No | 210653388 | TRANE | 4TWL9036A1 | 4TXCC007DS3 | S9V2C100U4VSA+RP | 23,400 | $1,170 |
| No | 201921846 | TRANE | 4TWL9036A1 | 4TXCC007DS3 | S9V2C100U4PSB+RP | 23,000 | $1,150 |
| No | 210653390 | TRANE | 4TWL9036A1 | 4TXCC007DS3 | S9V2C100D4VSA+RP | 22,800 | $1,140 |
| No | 210653389 | TRANE | 4TWL9036A1 | 4TXCC007DS3 | S9V2C100D4PSB+RP | 22,800 | $1,140 |
| No | 211081119 | TRANE | 4TWL9036A1 | 4TXCC007DS3 | S8V2C100M5PDA | 23,400 | $1,170 |
| No | 210691750 | TRANE | 4TWL9036A1 | 4TXCC007DS3 | S8V2C100M5PCA | 23,400 | $1,170 |
| No | 211081118 | TRANE | 4TWL9036A1 | 4TXCC007DS3 | S8V2C080M5PDA | 23,400 | $1,170 |
| No | 210691749 | TRANE | 4TWL9036A1 | 4TXCC007DS3 | S8V2C080M5PCA | 23,400 | $1,170 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210653387 | TRANE | 4TWL9036A1 | 4TXCC007DS3 | L8V1C100U5VSA+RP | 23,200 | $1,160 |
| No | 201921838 | TRANE | 4TWL9036A1 | 4TXCC007DS3 | *UHMC100ACV4 | 23,200 | $1,160 |
| No | 210649530 | TRANE | 4TWL9036A1 | 4TXCC007DS3 | *UD2C100B9V5+RP | 23,200 | $1,160 |
| No | 201921839 | TRANE | 4TWL9036A1 | 4TXCC007DS3 | *UD2C100ACV5 | 23,600 | $1,180 |
| No | 210649527 | TRANE | 4TWL9036A1 | 4TXCC007DS3 | *UD2C100A9V5+RP | 23,600 | $1,180 |
| No | 210649528 | TRANE | 4TWL9036A1 | 4TXCC007DS3 | *UD2C080B9V4+RP | 23,000 | $1,150 |
| No | 201921840 | TRANE | 4TWL9036A1 | 4TXCC007DS3 | *UD2C080ACV4 | 23,400 | $1,170 |
| No | 210649529 | TRANE | 4TWL9036A1 | 4TXCC007DS3 | *UD2C080A9V4+RP | 23,400 | $1,170 |
| No | 201921848 | TRANE | 4TWL9036A1 | 4TXCC007DS3 | *DHMC100ACV4 | 23,000 | $1,150 |
| No | 201921847 | TRANE | 4TWL9036A1 | 4TXCC007DS3 | *DD2C100ACV5 | 23,000 | $1,150 |
| No | 210649531 | TRANE | 4TWL9036A1 | 4TXCC007DS3 | *DD2C100A9V5+RP | 22,400 | $1,120 |
| No | 210653385 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | S9V2C100U4VSA+RP | 23,400 | $1,170 |
| No | 201921836 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | S9V2C100U4PSB+RP | 23,400 | $1,170 |
| No | 210653384 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | S9V2C100D4VSA+RP | 23,000 | $1,150 |
| No | 210653386 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | S9V2C100D4PSB+RP | 23,000 | $1,150 |
| No | 211081117 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | S8V2C100M5PDA | 23,800 | $1,190 |
| No | 210691748 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | S8V2C100M5PCA | 23,800 | $1,190 |
| No | 211081116 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | S8V2C080M5PDA | 23,600 | $1,180 |
| No | 210691747 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | S8V2C080M5PCA | 23,600 | $1,180 |
| No | 210653383 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | L8V1C100U5VSA+RP | 23,800 | $1,190 |
| No | 201921823 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | *UHMC100ACV4 | 23,600 | $1,180 |
| No | 210649525 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | *UD2C100B9V5+RP | 23,600 | $1,180 |
| No | 201921822 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | *UD2C100ACV5 | 23,600 | $1,180 |
| No | 210649522 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | *UD2C100A9V5+RP | 23,600 | $1,180 |
| No | 210649523 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | *UD2C080B9V4+RP | 23,600 | $1,180 |
| No | 201921821 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | *UD2C080ACV4 | 23,600 | $1,180 |
| No | 210649524 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | *UD2C080A9V4+RP | 23,200 | $1,160 |
| No | 201921825 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | *DHMC100ACV4 | 23,400 | $1,170 |
| No | 201921826 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | *DD2C100ACV5 | 23,400 | $1,170 |
| No | 210649526 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | *DD2C100A9V5+RP | 23,000 | $1,150 |
| No | 207804936 | TRANE | 4TWL9036A1 | 4TXCB006DS3+P0V0B000M40SC+RP | N/A | 22,400 | $1,120 |
| No | 207804935 | TRANE | 4TWL9036A1 | 4TXCB006DS3+P0V0A000M30SC+RP | N/A | 22,000 | $1,100 |
| No | 204433491 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | S9V2B080U4VSA+RP | 23,400 | $1,170 |
| No | 210653376 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | S9V2B080U4PSB+RP | 23,400 | $1,170 |
| No | 208106947 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | S9V2B080D4VSA+RP | 23,000 | $1,150 |
| No | 210653372 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | S9V2B080D4PSB+RP | 23,000 | $1,150 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207062442 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | S9V2B080D3VSA+RP | 23,000 | $1,150 |
| No | 210653373 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | S9V2B080D3PSB+RP | 23,000 | $1,150 |
| No | 203334083 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | S9V2B060U4PSB+RP | 23,600 | $1,180 |
| No | 210653377 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | S9V2B060U3VSA+RP | 23,600 | $1,180 |
| No | 205805506 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | S9V2B060U3PSB+RP | 23,600 | $1,180 |
| No | 210653374 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | S9V2B060D3PSB+RP | 23,000 | $1,150 |
| No | 210653378 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | S9V2B040U3VSA+RP | 23,600 | $1,180 |
| No | 205807173 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | S9V2B040U3PSB+RP | 23,200 | $1,160 |
| No | 210653375 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | S9V2B040D3PSB+RP | 23,200 | $1,160 |
| No | 211081114 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | S8V2B080M4PDA | 23,800 | $1,190 |
| No | 210691746 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | S8V2B080M4PCA | 23,800 | $1,190 |
| No | 211081115 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | S8V2B060M4PDA | 23,600 | $1,180 |
| No | 210691745 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | S8V2B060M4PCA | 23,600 | $1,180 |
| No | 211081113 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | S8V2A040M3PDA | 22,800 | $1,140 |
| No | 210691744 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | S8V2A040M3PCA | 22,800 | $1,140 |
| No | 210653379 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | L8V1B080U4VSA+RP | 23,600 | $1,180 |
| No | 210653380 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | L8V1A060U3VSA+RP | 22,800 | $1,140 |
| No | 210653381 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | L8V1A040U3VSA+RP | 22,800 | $1,140 |
| No | 206392932 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | *UHMB080ACV3 | 23,400 | $1,170 |
| No | 210653382 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | *UHMB060ACV3 | 23,800 | $1,190 |
| No | 205070363 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | *UD2B080ACV3 | 23,800 | $1,190 |
| No | 210649521 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | *UD2B080A9V3+RP | 23,200 | $1,160 |
| No | 207062436 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | *UD2B060ACV3 | 23,800 | $1,190 |
| No | 210649520 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | *UD2B060A9V3+RP | 23,400 | $1,170 |
| No | 201921819 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | *DHMB080ACV3 | 23,000 | $1,150 |
| No | 201921816 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | *DHMB060BCV3 | 23,200 | $1,160 |
| No | 201921817 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | *DD2B080ACV3 | 23,000 | $1,150 |
| No | 210649519 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | *DD2B080A9V3+RP | 22,800 | $1,140 |
| No | 201921818 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | *DD2B060ACV3 | 23,400 | $1,170 |
| No | 210649518 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | *DD2B060A9V3+RP | 23,000 | $1,150 |
| No | 207804934 | TRANE | 4TWL9036A1 | 4TXCB004DS3+P0V0B000M40SC+RP | N/A | 22,800 | $1,140 |
| No | 207804933 | TRANE | 4TWL9036A1 | 4TXCB004DS3+P0V0A000M30SC+RP | N/A | 22,200 | $1,110 |
| No | 204433488 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | S9V2B080U4VSA+RP | 23,600 | $1,180 |
| No | 210653371 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | S9V2B080U4PSB+RP | 23,600 | $1,180 |
| No | 208106946 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | S9V2B080D4VSA+RP | 23,000 | $1,150 |
| No | 204013222 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | S9V2B080D4PSB+RP | 23,200 | $1,160 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210653367 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | S9V2B080D3VSA+RP | 23,200 | $1,160 |
| No | 201921810 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | S9V2B080D3PSB+RP | 23,200 | $1,160 |
| No | 207782161 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | S9V2B060U4PSB+RP | 23,600 | $1,180 |
| No | 207063276 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | S9V2B060U3VSA+RP | 23,600 | $1,180 |
| No | 205805504 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | S9V2B060U3PSB+RP | 23,600 | $1,180 |
| No | 202382479 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | S9V2B060D3PSB+RP | 23,200 | $1,160 |
| No | 207062440 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | S9V2B040U3VSA+RP | 23,800 | $1,190 |
| No | 205807175 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | S9V2B040U3PSB+RP | 23,600 | $1,180 |
| No | 210653366 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | S9V2B040D3PSB+RP | 23,200 | $1,160 |
| No | 211081112 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | S8V2B080M4PDA | 24,000 | $1,200 |
| No | 210691742 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | S8V2B080M4PCA | 24,000 | $1,200 |
| No | 211081111 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | S8V2B060M4PDA | 23,800 | $1,190 |
| No | 210691743 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | S8V2B060M4PCA | 23,800 | $1,190 |
| No | 211081110 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | S8V2A040M3PDA | 23,000 | $1,150 |
| No | 210691741 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | S8V2A040M3PCA | 23,000 | $1,150 |
| No | 210653370 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | L8V1B080U4VSA+RP | 24,000 | $1,200 |
| No | 210653369 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | L8V1A060U3VSA+RP | 22,800 | $1,140 |
| No | 210653368 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | L8V1A040U3VSA+RP | 23,000 | $1,150 |
| No | 206392934 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | *UHMB080ACV3 | 23,600 | $1,180 |
| No | 204431301 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | *UHMB060ACV3 | 23,800 | $1,190 |
| No | 205070362 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | *UD2B080ACV3 | 23,800 | $1,190 |
| No | 210649515 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | *UD2B080A9V3+RP | 23,400 | $1,170 |
| No | 201921811 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | *UD2B060ACV3 | 24,000 | $1,200 |
| No | 210649516 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | *UD2B060A9V3+RP | 23,600 | $1,180 |
| No | 201921809 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | *DHMB080ACV3 | 23,200 | $1,160 |
| No | 201921808 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | *DHMB060BCV3 | 23,400 | $1,170 |
| No | 201921812 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | *DD2B080ACV3 | 23,200 | $1,160 |
| No | 210649517 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | *DD2B080A9V3+RP | 23,000 | $1,150 |
| No | 201921815 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | *DD2B060ACV3 | 23,400 | $1,170 |
| No | 210649514 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | *DD2B060A9V3+RP | 23,200 | $1,160 |
| No | 211081109 | TRANE | 4TWL9036A1 | 4PX*DU60BS3 | S8V2D120M5PDA | 23,200 | $1,160 |
| No | 210691740 | TRANE | 4TWL9036A1 | 4PX*DU60BS3 | S8V2D120M5PCA | 23,200 | $1,160 |
| No | 210649513 | TRANE | 4TWL9036A1 | 4PX*DU60BS3 | *UD2D120A9V5+RP | 23,400 | $1,170 |
| No | 211081108 | TRANE | 4TWL9036A1 | 4PX*DU48BS3 | S8V2D120M5PDA | 23,600 | $1,180 |
| No | 210691739 | TRANE | 4TWL9036A1 | 4PX*DU48BS3 | S8V2D120M5PCA | 23,600 | $1,180 |
| No | 210649511 | TRANE | 4TWL9036A1 | 4PX*DU48BS3 | *UD2D120A9V5+RP | 23,600 | $1,180 |
| No | 210649512 | TRANE | 4TWL9036A1 | 4PX*DU48BS3 | *DD2D120A9V5+RP | 22,600 | $1,130 |
| No | 210649510 | TRANE | 4TWL9036A1 | 4PX*DD60BS3+HORIZ-RT | *UD2D120A9V5+RP | 23,400 | $1,170 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211081107 | TRANE | 4TWL9036A1 | 4PX*DD60BS3 | S8V2D120M5PDA | 23,400 | $1,170 |
| No | 210691738 | TRANE | 4TWL9036A1 | 4PX*DD60BS3 | S8V2D120M5PCA | 23,400 | $1,170 |
| No | 210649509 | TRANE | 4TWL9036A1 | 4PX*DD60BS3 | *DD2D120A9V5+RP | 23,200 | $1,160 |
| No | 210653365 | TRANE | 4TWL9036A1 | 4PX*CU60BS3 | S9V2C100U4VSA+RP | 23,000 | $1,150 |
| No | 210653364 | TRANE | 4TWL9036A1 | 4PX*CU60BS3 | S9V2C100U4PSB+RP | 23,000 | $1,150 |
| No | 211081106 | TRANE | 4TWL9036A1 | 4PX*CU60BS3 | S8V2C100M5PDA | 23,200 | $1,160 |
| No | 210691737 | TRANE | 4TWL9036A1 | 4PX*CU60BS3 | S8V2C100M5PCA | 23,200 | $1,160 |
| No | 211081105 | TRANE | 4TWL9036A1 | 4PX*CU60BS3 | S8V2C080M5PDA | 23,200 | $1,160 |
| No | 210691736 | TRANE | 4TWL9036A1 | 4PX*CU60BS3 | S8V2C080M5PCA | 23,200 | $1,160 |
| No | 210653363 | TRANE | 4TWL9036A1 | 4PX*CU60BS3 | L8V1C100U5VSA+RP | 23,200 | $1,160 |
| No | 210649508 | TRANE | 4TWL9036A1 | 4PX*CU60BS3 | *UD2C100B9V5+RP | 23,200 | $1,160 |
| No | 201921763 | TRANE | 4TWL9036A1 | 4PX*CU60BS3 | *UD2C100ACV5 | 23,200 | $1,160 |
| No | 210649507 | TRANE | 4TWL9036A1 | 4PX*CU60BS3 | *UD2C100A9V5+RP | 23,200 | $1,160 |
| No | 210649506 | TRANE | 4TWL9036A1 | 4PX*CU60BS3 | *UD2C080B9V4+RP | 23,200 | $1,160 |
| No | 201921770 | TRANE | 4TWL9036A1 | 4PX*CU60BS3 | *UD2C080ACV4 | 23,200 | $1,160 |
| No | 210649505 | TRANE | 4TWL9036A1 | 4PX*CU60BS3 | *UD2C080A9V4+RP | 23,600 | $1,180 |
| No | 210653362 | TRANE | 4TWL9036A1 | 4PX*CU48BS3 | S9V2C100U4VSA+RP | 23,400 | $1,170 |
| No | 201921758 | TRANE | 4TWL9036A1 | 4PX*CU48BS3 | S9V2C100U4PSB+RP | 23,200 | $1,160 |
| No | 210653357 | TRANE | 4TWL9036A1 | 4PX*CU48BS3 | S9V2C100D4VSA+RP | 22,800 | $1,140 |
| No | 210653358 | TRANE | 4TWL9036A1 | 4PX*CU48BS3 | S9V2C100D4PSB+RP | 22,800 | $1,140 |
| No | 211081104 | TRANE | 4TWL9036A1 | 4PX*CU48BS3 | S8V2C100M5PDA | 23,600 | $1,180 |
| No | 210691735 | TRANE | 4TWL9036A1 | 4PX*CU48BS3 | S8V2C100M5PCA | 23,600 | $1,180 |
| No | 211081103 | TRANE | 4TWL9036A1 | 4PX*CU48BS3 | S8V2C080M5PDA | 23,400 | $1,170 |
| No | 210691734 | TRANE | 4TWL9036A1 | 4PX*CU48BS3 | S8V2C080M5PCA | 23,400 | $1,170 |
| No | 210653359 | TRANE | 4TWL9036A1 | 4PX*CU48BS3 | L8V1C100U5VSA+RP | 23,400 | $1,170 |
| No | 201921746 | TRANE | 4TWL9036A1 | 4PX*CU48BS3 | *UHMC100ACV4 | 23,400 | $1,170 |
| No | 210649503 | TRANE | 4TWL9036A1 | 4PX*CU48BS3 | *UD2C100B9V5+RP | 23,400 | $1,170 |
| No | 201921761 | TRANE | 4TWL9036A1 | 4PX*CU48BS3 | *UD2C100ACV5 | 23,600 | $1,180 |
| No | 210649500 | TRANE | 4TWL9036A1 | 4PX*CU48BS3 | *UD2C100A9V5+RP | 23,600 | $1,180 |
| No | 210649501 | TRANE | 4TWL9036A1 | 4PX*CU48BS3 | *UD2C080B9V4+RP | 23,400 | $1,170 |
| No | 201921741 | TRANE | 4TWL9036A1 | 4PX*CU48BS3 | *UD2C080ACV4 | 23,400 | $1,170 |
| No | 210649502 | TRANE | 4TWL9036A1 | 4PX*CU48BS3 | *UD2C080A9V4+RP | 23,400 | $1,170 |
| No | 210653361 | TRANE | 4TWL9036A1 | 4PX*CU48BS3 | *DHMC100ACV4 | 23,000 | $1,150 |
| No | 210653360 | TRANE | 4TWL9036A1 | 4PX*CU48BS3 | *DD2C100ACV5 | 23,000 | $1,150 |
| No | 210649504 | TRANE | 4TWL9036A1 | 4PX*CU48BS3 | *DD2C100A9V5+RP | 22,800 | $1,140 |
| No | 210653356 | TRANE | 4TWL9036A1 | 4PX*CU42BS3 | S9V2C100U4VSA+RP | 23,600 | $1,180 |
| No | 201921714 | TRANE | 4TWL9036A1 | 4PX*CU42BS3 | S9V2C100U4PSB+RP | 23,400 | $1,170 |
| No | 210653354 | TRANE | 4TWL9036A1 | 4PX*CU42BS3 | S9V2C100D4VSA+RP | 22,800 | $1,140 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210653353 | TRANE | 4TWL9036A1 | 4PX*CU42BS3 | S9V2C100D4PSB+RP | 22,800 | $1,140 |
| No | 211081102 | TRANE | 4TWL9036A1 | 4PX*CU42BS3 | S8V2C100M5PDA | 23,800 | $1,190 |
| No | 210691733 | TRANE | 4TWL9036A1 | 4PX*CU42BS3 | S8V2C100M5PCA | 23,800 | $1,190 |
| No | 211081101 | TRANE | 4TWL9036A1 | 4PX*CU42BS3 | S8V2C080M5PDA | 23,600 | $1,180 |
| No | 210691732 | TRANE | 4TWL9036A1 | 4PX*CU42BS3 | S8V2C080M5PCA | 23,600 | $1,180 |
| No | 210653355 | TRANE | 4TWL9036A1 | 4PX*CU42BS3 | L8V1C100U5VSA+RP | 23,600 | $1,180 |
| No | 201921727 | TRANE | 4TWL9036A1 | 4PX*CU42BS3 | *UHMC100ACV4 | 23,400 | $1,170 |
| No | 210649498 | TRANE | 4TWL9036A1 | 4PX*CU42BS3 | *UD2C100B9V5+RP | 23,600 | $1,180 |
| No | 201921730 | TRANE | 4TWL9036A1 | 4PX*CU42BS3 | *UD2C100ACV5 | 23,800 | $1,190 |
| No | 210649497 | TRANE | 4TWL9036A1 | 4PX*CU42BS3 | *UD2C100A9V5+RP | 23,400 | $1,170 |
| No | 210649496 | TRANE | 4TWL9036A1 | 4PX*CU42BS3 | *UD2C080B9V4+RP | 23,600 | $1,180 |
| No | 201921732 | TRANE | 4TWL9036A1 | 4PX*CU42BS3 | *UD2C080ACV4 | 23,400 | $1,170 |
| No | 210649495 | TRANE | 4TWL9036A1 | 4PX*CU42BS3 | *UD2C080A9V4+RP | 23,600 | $1,180 |
| No | 202586169 | TRANE | 4TWL9036A1 | 4PX*CU42BS3 | *DHMC100ACV4 | 23,200 | $1,160 |
| No | 202586168 | TRANE | 4TWL9036A1 | 4PX*CU42BS3 | *DD2C100ACV5 | 23,000 | $1,150 |
| No | 210649499 | TRANE | 4TWL9036A1 | 4PX*CU42BS3 | *DD2C100A9V5+RP | 22,800 | $1,140 |
| No | 210653351 | TRANE | 4TWL9036A1 | 4PX*CU36BS3 | S9V2C100U4VSA+RP | 23,200 | $1,160 |
| No | 201921702 | TRANE | 4TWL9036A1 | 4PX*CU36BS3 | S9V2C100U4PSB+RP | 23,400 | $1,170 |
| No | 210653347 | TRANE | 4TWL9036A1 | 4PX*CU36BS3 | S9V2C100D4VSA+RP | 23,200 | $1,160 |
| No | 210653348 | TRANE | 4TWL9036A1 | 4PX*CU36BS3 | S9V2C100D4PSB+RP | 23,000 | $1,150 |
| No | 211081100 | TRANE | 4TWL9036A1 | 4PX*CU36BS3 | S8V2C100M5PDA | 23,800 | $1,190 |
| No | 210691731 | TRANE | 4TWL9036A1 | 4PX*CU36BS3 | S8V2C100M5PCA | 23,800 | $1,190 |
| No | 211081099 | TRANE | 4TWL9036A1 | 4PX*CU36BS3 | S8V2C080M5PDA | 23,600 | $1,180 |
| No | 210691730 | TRANE | 4TWL9036A1 | 4PX*CU36BS3 | S8V2C080M5PCA | 23,600 | $1,180 |
| No | 210653352 | TRANE | 4TWL9036A1 | 4PX*CU36BS3 | L8V1C100U5VSA+RP | 23,400 | $1,170 |
| No | 201921708 | TRANE | 4TWL9036A1 | 4PX*CU36BS3 | *UHMC100ACV4 | 23,400 | $1,170 |
| No | 210649493 | TRANE | 4TWL9036A1 | 4PX*CU36BS3 | *UD2C100B9V5+RP | 23,600 | $1,180 |
| No | 201921709 | TRANE | 4TWL9036A1 | 4PX*CU36BS3 | *UD2C100ACV5 | 23,600 | $1,180 |
| No | 210649490 | TRANE | 4TWL9036A1 | 4PX*CU36BS3 | *UD2C100A9V5+RP | 23,600 | $1,180 |
| No | 210649491 | TRANE | 4TWL9036A1 | 4PX*CU36BS3 | *UD2C080B9V4+RP | 23,600 | $1,180 |
| No | 201921710 | TRANE | 4TWL9036A1 | 4PX*CU36BS3 | *UD2C080ACV4 | 23,600 | $1,180 |
| No | 210649492 | TRANE | 4TWL9036A1 | 4PX*CU36BS3 | *UD2C080A9V4+RP | 23,200 | $1,160 |
| No | 210653349 | TRANE | 4TWL9036A1 | 4PX*CU36BS3 | *DHMC100ACV4 | 23,600 | $1,180 |
| No | 210653350 | TRANE | 4TWL9036A1 | 4PX*CU36BS3 | *DD2C100ACV5 | 23,400 | $1,170 |
| No | 210649494 | TRANE | 4TWL9036A1 | 4PX*CU36BS3 | *DD2C100A9V5+RP | 23,000 | $1,150 |
| No | 210649487 | TRANE | 4TWL9036A1 | 4PX*CD60BS3+HORIZ-RT | *UD2C100B9V5+RP | 23,000 | $1,150 |
| No | 201921699 | TRANE | 4TWL9036A1 | 4PX*CD60BS3+HORIZ-RT | *UD2C100ACV5 | 23,000 | $1,150 |
| No | 210649488 | TRANE | 4TWL9036A1 | 4PX*CD60BS3+HORIZ-RT | *UD2C100A9V5+RP | 23,200 | $1,160 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210649489 | TRANE | 4TWL9036A1 | 4PX*CD60BS3+HORIZ-RT | *UD2C080B9V4+RP | 22,800 | $1,140 |
| No | 201921700 | TRANE | 4TWL9036A1 | 4PX*CD60BS3+HORIZ-RT | *UD2C080ACV4 | 23,200 | $1,160 |
| No | 210649486 | TRANE | 4TWL9036A1 | 4PX*CD60BS3+HORIZ-RT | *UD2C080A9V4+RP | 23,200 | $1,160 |
| No | 210653346 | TRANE | 4TWL9036A1 | 4PX*CD60BS3 | S9V2C100D4VSA+RP | 22,800 | $1,140 |
| No | 210653345 | TRANE | 4TWL9036A1 | 4PX*CD60BS3 | S9V2C100D4PSB+RP | 23,000 | $1,150 |
| No | 211081098 | TRANE | 4TWL9036A1 | 4PX*CD60BS3 | S8V2C100M5PDA | 23,200 | $1,160 |
| No | 210691729 | TRANE | 4TWL9036A1 | 4PX*CD60BS3 | S8V2C100M5PCA | 23,200 | $1,160 |
| No | 211081097 | TRANE | 4TWL9036A1 | 4PX*CD60BS3 | S8V2C080M5PDA | 23,000 | $1,150 |
| No | 210691728 | TRANE | 4TWL9036A1 | 4PX*CD60BS3 | S8V2C080M5PCA | 23,000 | $1,150 |
| No | 201921697 | TRANE | 4TWL9036A1 | 4PX*CD60BS3 | *DHMC100ACV4 | 23,200 | $1,160 |
| No | 201921698 | TRANE | 4TWL9036A1 | 4PX*CD60BS3 | *DD2C100ACV5 | 23,000 | $1,150 |
| No | 210649485 | TRANE | 4TWL9036A1 | 4PX*CD60BS3 | *DD2C100A9V5+RP | 23,000 | $1,150 |
| No | 210649484 | TRANE | 4TWL9036A1 | 4PX*CD42BS3+HORIZ-RT | *UD2C100B9V5+RP | 23,400 | $1,170 |
| No | 210653344 | TRANE | 4TWL9036A1 | 4PX*CD42BS3+HORIZ-RT | *UD2C100ACV5 | 23,600 | $1,180 |
| No | 210649483 | TRANE | 4TWL9036A1 | 4PX*CD42BS3+HORIZ-RT | *UD2C100A9V5+RP | 23,600 | $1,180 |
| No | 210649482 | TRANE | 4TWL9036A1 | 4PX*CD42BS3+HORIZ-RT | *UD2C080B9V4+RP | 23,400 | $1,170 |
| No | 210653343 | TRANE | 4TWL9036A1 | 4PX*CD42BS3+HORIZ-RT | *UD2C080ACV4 | 23,600 | $1,180 |
| No | 210649481 | TRANE | 4TWL9036A1 | 4PX*CD42BS3+HORIZ-RT | *UD2C080A9V4+RP | 23,600 | $1,180 |
| No | 210653342 | TRANE | 4TWL9036A1 | 4PX*CD42BS3 | S9V2C100D4VSA+RP | 23,400 | $1,170 |
| No | 201921676 | TRANE | 4TWL9036A1 | 4PX*CD42BS3 | S9V2C100D4PSB+RP | 23,400 | $1,170 |
| No | 211081096 | TRANE | 4TWL9036A1 | 4PX*CD42BS3 | S8V2C100M5PDA | 23,600 | $1,180 |
| No | 210691727 | TRANE | 4TWL9036A1 | 4PX*CD42BS3 | S8V2C100M5PCA | 23,600 | $1,180 |
| No | 211081095 | TRANE | 4TWL9036A1 | 4PX*CD42BS3 | S8V2C080M5PDA | 23,600 | $1,180 |
| No | 210691726 | TRANE | 4TWL9036A1 | 4PX*CD42BS3 | S8V2C080M5PCA | 23,600 | $1,180 |
| No | 201921673 | TRANE | 4TWL9036A1 | 4PX*CD42BS3 | *DHMC100ACV4 | 23,600 | $1,180 |
| No | 201921674 | TRANE | 4TWL9036A1 | 4PX*CD42BS3 | *DD2C100ACV5 | 23,600 | $1,180 |
| No | 210649480 | TRANE | 4TWL9036A1 | 4PX*CD42BS3 | *DD2C100A9V5+RP | 23,400 | $1,170 |
| No | 210649479 | TRANE | 4TWL9036A1 | 4PX*CD36BS3+HORIZ-RT | *UD2C100B9V5+RP | 23,800 | $1,190 |
| No | 201921668 | TRANE | 4TWL9036A1 | 4PX*CD36BS3+HORIZ-RT | *UD2C100ACV5 | 23,800 | $1,190 |
| No | 210649478 | TRANE | 4TWL9036A1 | 4PX*CD36BS3+HORIZ-RT | *UD2C100A9V5+RP | 23,600 | $1,180 |
| No | 210649476 | TRANE | 4TWL9036A1 | 4PX*CD36BS3+HORIZ-RT | *UD2C080B9V4+RP | 23,800 | $1,190 |
| No | 201921667 | TRANE | 4TWL9036A1 | 4PX*CD36BS3+HORIZ-RT | *UD2C080ACV4 | 23,800 | $1,190 |
| No | 210649477 | TRANE | 4TWL9036A1 | 4PX*CD36BS3+HORIZ-RT | *UD2C080A9V4+RP | 23,800 | $1,190 |
| No | 201921664 | TRANE | 4TWL9036A1 | 4PX*CD36BS3 | S9V2C100D4PSB+RP | 23,600 | $1,180 |
| No | 211081094 | TRANE | 4TWL9036A1 | 4PX*CD36BS3 | S8V2C100M5PDA | 24,000 | $1,200 |
| No | 210691725 | TRANE | 4TWL9036A1 | 4PX*CD36BS3 | S8V2C100M5PCA | 24,000 | $1,200 |
| No | 211081093 | TRANE | 4TWL9036A1 | 4PX*CD36BS3 | S8V2C080M5PDA | 23,800 | $1,190 |
| No | 210691724 | TRANE | 4TWL9036A1 | 4PX*CD36BS3 | S8V2C080M5PCA | 23,800 | $1,190 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210653341 | TRANE | 4TWL9036A1 | 4PX*CD36BS3 | *DHMC100ACV4 | 24,000 | $1,200 |
| No | 210653340 | TRANE | 4TWL9036A1 | 4PX*CD36BS3 | *DD2C100ACV5 | 24,000 | $1,200 |
| No | 210649475 | TRANE | 4TWL9036A1 | 4PX*CD36BS3 | *DD2C100A9V5+RP | 23,200 | $1,160 |
| No | 207804932 | TRANE | 4TWL9036A1 | 4PX*BU48BS3+P0V0B000M40SC+RP | N/A | 22,600 | $1,130 |
| No | 207804931 | TRANE | 4TWL9036A1 | 4PX*BU48BS3+P0V0A000M30SC+RP | N/A | 22,000 | $1,100 |
| No | 210653323 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | S9V2B080U4VSA+RP | 23,400 | $1,170 |
| No | 210653339 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | S9V2B080U4PSB+RP | 23,400 | $1,170 |
| No | 208106944 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | S9V2B080D4VSA+RP | 22,800 | $1,140 |
| No | 210653329 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | S9V2B080D4PSB+RP | 23,000 | $1,150 |
| No | 210653328 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | S9V2B080D3VSA+RP | 23,000 | $1,150 |
| No | 210653327 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | S9V2B080D3PSB+RP | 23,000 | $1,150 |
| No | 210653321 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | S9V2B060U4PSB+RP | 23,600 | $1,180 |
| No | 210653330 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | S9V2B060U3VSA+RP | 23,600 | $1,180 |
| No | 210653331 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | S9V2B060U3PSB+RP | 23,600 | $1,180 |
| No | 210653326 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | S9V2B060D3PSB+RP | 23,000 | $1,150 |
| No | 210653332 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | S9V2B040U3VSA+RP | 23,600 | $1,180 |
| No | 210653333 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | S9V2B040U3PSB+RP | 23,600 | $1,180 |
| No | 210653325 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | S9V2B040D3PSB+RP | 23,000 | $1,150 |
| No | 211081091 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | S8V2B080M4PDA | 23,800 | $1,190 |
| No | 210691723 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | S8V2B080M4PCA | 23,800 | $1,190 |
| No | 211081092 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | S8V2B060M4PDA | 23,800 | $1,190 |
| No | 210691722 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | S8V2B060M4PCA | 23,800 | $1,190 |
| No | 211081090 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | S8V2A040M3PDA | 22,800 | $1,140 |
| No | 210691721 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | S8V2A040M3PCA | 22,800 | $1,140 |
| No | 210653334 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | L8V1B080U4VSA+RP | 23,800 | $1,190 |
| No | 210653335 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | L8V1A060U3VSA+RP | 22,800 | $1,140 |
| No | 210653336 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | L8V1A040U3VSA+RP | 22,800 | $1,140 |
| No | 210653337 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | *UHMB080ACV3 | 23,600 | $1,180 |
| No | 210653338 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | *UHMB060ACV3 | 23,800 | $1,190 |
| No | 205070360 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | *UD2B080ACV3 | 23,600 | $1,180 |
| No | 210649471 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | *UD2B080A9V3+RP | 23,200 | $1,160 |
| No | 210653322 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | *UD2B060ACV3 | 23,800 | $1,190 |
| No | 210649472 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | *UD2B060A9V3+RP | 23,400 | $1,170 |
| No | 202544271 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | *DHMB080ACV3 | 23,000 | $1,150 |
| No | 202544272 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | *DHMB060BCV3 | 23,200 | $1,160 |
| No | 210653324 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | *DD2B080ACV3 | 23,000 | $1,150 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210649474 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | *DD2B080A9V3+RP | 22,800 | $1,140 |
| No | 206214526 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | *DD2B060ACV3 | 23,200 | $1,160 |
| No | 210649473 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | *DD2B060A9V3+RP | 23,000 | $1,150 |
| No | 207804930 | TRANE | 4TWL9036A1 | 4PX*BU42BS3+P0V0B000M40SC+RP | N/A | 23,000 | $1,150 |
| No | 207804929 | TRANE | 4TWL9036A1 | 4PX*BU42BS3+P0V0A000M30SC+RP | N/A | 22,200 | $1,110 |
| No | 210653300 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | S9V2B080U4VSA+RP | 23,600 | $1,180 |
| No | 210653311 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | S9V2B080U4PSB+RP | 23,600 | $1,180 |
| No | 210653310 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | S9V2B080D4VSA+RP | 23,000 | $1,150 |
| No | 210653309 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | S9V2B080D4PSB+RP | 23,000 | $1,150 |
| No | 210653308 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | S9V2B080D3VSA+RP | 23,000 | $1,150 |
| No | 210653307 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | S9V2B080D3PSB+RP | 23,000 | $1,150 |
| No | 210653298 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | S9V2B060U4PSB+RP | 23,800 | $1,190 |
| No | 210653299 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | S9V2B060U3VSA+RP | 23,600 | $1,180 |
| No | 210653312 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | S9V2B060U3PSB+RP | 23,600 | $1,180 |
| No | 210653306 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | S9V2B060D3PSB+RP | 23,000 | $1,150 |
| No | 210653313 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | S9V2B040U3VSA+RP | 23,800 | $1,190 |
| No | 210653314 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | S9V2B040U3PSB+RP | 23,800 | $1,190 |
| No | 210653305 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | S9V2B040D3PSB+RP | 23,200 | $1,160 |
| No | 211081089 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | S8V2B080M4PDA | 24,000 | $1,200 |
| No | 210691720 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | S8V2B080M4PCA | 24,000 | $1,200 |
| No | 211081088 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | S8V2B060M4PDA | 24,000 | $1,200 |
| No | 210691719 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | S8V2B060M4PCA | 24,000 | $1,200 |
| No | 211081087 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | S8V2A040M3PDA | 23,000 | $1,150 |
| No | 210691718 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | S8V2A040M3PCA | 23,000 | $1,150 |
| No | 210653315 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | L8V1B080U4VSA+RP | 23,800 | $1,190 |
| No | 210653316 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | L8V1A060U3VSA+RP | 23,000 | $1,150 |
| No | 210653317 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | L8V1A040U3VSA+RP | 23,000 | $1,150 |
| No | 210653318 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | *UHMB080ACV3 | 23,800 | $1,190 |
| No | 210653319 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | *UHMB060ACV3 | 23,800 | $1,190 |
| No | 205070358 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | *UD2B080ACV3 | 23,800 | $1,190 |
| No | 210649468 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | *UD2B080A9V3+RP | 23,600 | $1,180 |
| No | 210653320 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | *UD2B060ACV3 | 24,000 | $1,200 |
| No | 210649469 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | *UD2B060A9V3+RP | 23,600 | $1,180 |
| No | 210653304 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | *DHMB080ACV3 | 23,200 | $1,160 |
| No | 210653303 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | *DHMB060BCV3 | 23,000 | $1,150 |
| No | 210653302 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | *DD2B080ACV3 | 23,200 | $1,160 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210649470 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | *DD2B080A9V3+RP | 22,800 | $1,140 |
| No | 210653301 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | *DD2B060ACV3 | 23,400 | $1,170 |
| No | 210649467 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | *DD2B060A9V3+RP | 23,200 | $1,160 |
| No | 207804928 | TRANE | 4TWL9036A1 | 4PX*BU36BS3+P0V0B000M40SC+RP | N/A | 22,800 | $1,140 |
| No | 207804927 | TRANE | 4TWL9036A1 | 4PX*BU36BS3+P0V0A000M30SC+RP | N/A | 22,200 | $1,110 |
| No | 210653283 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | S9V2B080U4VSA+RP | 23,600 | $1,180 |
| No | 204013221 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | S9V2B080U4PSB+RP | 23,400 | $1,170 |
| No | 208106943 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | S9V2B080D4VSA+RP | 22,800 | $1,140 |
| No | 210653292 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | S9V2B080D4PSB+RP | 23,200 | $1,160 |
| No | 210653291 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | S9V2B080D3VSA+RP | 23,200 | $1,160 |
| No | 210653290 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | S9V2B080D3PSB+RP | 23,200 | $1,160 |
| No | 206901672 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | S9V2B060U4PSB+RP | 23,600 | $1,180 |
| No | 210653297 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | S9V2B060U3VSA+RP | 23,600 | $1,180 |
| No | 210653296 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | S9V2B060U3PSB+RP | 23,600 | $1,180 |
| No | 210653289 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | S9V2B060D3PSB+RP | 23,200 | $1,160 |
| No | 210653295 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | S9V2B040U3VSA+RP | 23,800 | $1,190 |
| No | 203297108 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | S9V2B040U3PSB+RP | 23,800 | $1,190 |
| No | 210653288 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | S9V2B040D3PSB+RP | 23,200 | $1,160 |
| No | 211081086 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | S8V2B080M4PDA | 24,000 | $1,200 |
| No | 210691717 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | S8V2B080M4PCA | 24,000 | $1,200 |
| No | 211081085 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | S8V2B060M4PDA | 24,000 | $1,200 |
| No | 210691716 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | S8V2B060M4PCA | 24,000 | $1,200 |
| No | 211081084 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | S8V2A040M3PDA | 22,800 | $1,140 |
| No | 210691715 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | S8V2A040M3PCA | 22,800 | $1,140 |
| No | 210653294 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | L8V1B080U4VSA+RP | 24,000 | $1,200 |
| No | 210653293 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | L8V1A060U3VSA+RP | 23,000 | $1,150 |
| No | 210653285 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | L8V1A040U3VSA+RP | 22,800 | $1,140 |
| No | 208121977 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | *UHMB080ACV3 | 23,800 | $1,190 |
| No | 207335057 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | *UHMB060ACV3 | 23,800 | $1,190 |
| No | 205070356 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | *UD2B080ACV3 | 23,800 | $1,190 |
| No | 207783932 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | *UD2B080A9V3+RP | 23,200 | $1,160 |
| No | 201921662 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | *UD2B060ACV3 | 24,000 | $1,200 |
| No | 210649464 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | *UD2B060A9V3+RP | 23,600 | $1,180 |
| No | 206315458 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | *DHMB080ACV3 | 23,200 | $1,160 |
| No | 210653287 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | *DHMB060BCV3 | 23,400 | $1,170 |
| No | 210653286 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | *DD2B080ACV3 | 23,200 | $1,160 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210649466 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | *DD2B080A9V3+RP | 23,000 | $1,150 |
| No | 210653284 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | *DD2B060ACV3 | 23,400 | $1,170 |
| No | 210649465 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | *DD2B060A9V3+RP | 23,200 | $1,160 |
| No | 211289035 | TRANE | 4TWL9036A1 | 4PX*BU30BS3 | *UD2B060ACV3 | 24,400 | $1,220 |
| No | 211289036 | TRANE | 4TWL9036A1 | 4PX*BU30BS3 | *DD2B060ACV3 | 24,200 | $1,210 |
| No | 207804922 | TRANE | 4TWL9036A1 | 4PX*BD42BS3+P0V0B000M40SC+RP | N/A | 22,800 | $1,140 |
| No | 207804921 | TRANE | 4TWL9036A1 | 4PX*BD42BS3+P0V0A000M30SC+RP | N/A | 22,200 | $1,110 |
| No | 210653280 | TRANE | 4TWL9036A1 | 4PX*BD42BS3+HORIZ-RT | *UD2B080ACV3 | 23,800 | $1,190 |
| No | 210649463 | TRANE | 4TWL9036A1 | 4PX*BD42BS3+HORIZ-RT | *UD2B080A9V3+RP | 23,400 | $1,170 |
| No | 210653279 | TRANE | 4TWL9036A1 | 4PX*BD42BS3+HORIZ-RT | *UD2B060ACV3 | 23,800 | $1,190 |
| No | 210649462 | TRANE | 4TWL9036A1 | 4PX*BD42BS3+HORIZ-RT | *UD2B060A9V3+RP | 23,600 | $1,180 |
| No | 208106941 | TRANE | 4TWL9036A1 | 4PX*BD42BS3 | S9V2B080D4VSA+RP | 23,600 | $1,180 |
| No | 210653272 | TRANE | 4TWL9036A1 | 4PX*BD42BS3 | S9V2B080D4PSB+RP | 23,600 | $1,180 |
| No | 210653273 | TRANE | 4TWL9036A1 | 4PX*BD42BS3 | S9V2B080D3VSA+RP | 23,600 | $1,180 |
| No | 210653274 | TRANE | 4TWL9036A1 | 4PX*BD42BS3 | S9V2B080D3PSB+RP | 23,600 | $1,180 |
| No | 210653275 | TRANE | 4TWL9036A1 | 4PX*BD42BS3 | S9V2B060D3PSB+RP | 23,600 | $1,180 |
| No | 210653278 | TRANE | 4TWL9036A1 | 4PX*BD42BS3 | S9V2B040D3PSB+RP | 23,800 | $1,190 |
| No | 211081083 | TRANE | 4TWL9036A1 | 4PX*BD42BS3 | S8V2B080M4PDA | 24,000 | $1,200 |
| No | 210691714 | TRANE | 4TWL9036A1 | 4PX*BD42BS3 | S8V2B080M4PCA | 24,000 | $1,200 |
| No | 211081082 | TRANE | 4TWL9036A1 | 4PX*BD42BS3 | S8V2B060M4PDA | 24,000 | $1,200 |
| No | 210691713 | TRANE | 4TWL9036A1 | 4PX*BD42BS3 | S8V2B060M4PCA | 24,000 | $1,200 |
| No | 211081081 | TRANE | 4TWL9036A1 | 4PX*BD42BS3 | S8V2A040M3PDA | 23,000 | $1,150 |
| No | 210691712 | TRANE | 4TWL9036A1 | 4PX*BD42BS3 | S8V2A040M3PCA | 23,000 | $1,150 |
| No | 210653277 | TRANE | 4TWL9036A1 | 4PX*BD42BS3 | *DHMB080ACV3 | 23,600 | $1,180 |
| No | 210653276 | TRANE | 4TWL9036A1 | 4PX*BD42BS3 | *DHMB060BCV3 | 23,800 | $1,190 |
| No | 201921658 | TRANE | 4TWL9036A1 | 4PX*BD42BS3 | *DD2B080ACV3 | 23,600 | $1,180 |
| No | 210649461 | TRANE | 4TWL9036A1 | 4PX*BD42BS3 | *DD2B080A9V3+RP | 23,400 | $1,170 |
| No | 201921659 | TRANE | 4TWL9036A1 | 4PX*BD42BS3 | *DD2B060ACV3 | 24,000 | $1,200 |
| No | 210649460 | TRANE | 4TWL9036A1 | 4PX*BD42BS3 | *DD2B060A9V3+RP | 23,400 | $1,170 |
| No | 207804919 | TRANE | 4TWL9036A1 | 4PX*BD36BS3+P0V0B000M40SC+RP | N/A | 23,000 | $1,150 |
| No | 207804918 | TRANE | 4TWL9036A1 | 4PX*BD36BS3+P0V0A000M30SC+RP | N/A | 22,600 | $1,130 |
| No | 201921652 | TRANE | 4TWL9036A1 | 4PX*BD36BS3+HORIZ-RT | *UD2B080ACV3 | 24,000 | $1,200 |
| No | 210649459 | TRANE | 4TWL9036A1 | 4PX*BD36BS3+HORIZ-RT | *UD2B080A9V3+RP | 24,000 | $1,200 |
| No | 201921651 | TRANE | 4TWL9036A1 | 4PX*BD36BS3+HORIZ-RT | *UD2B060ACV3 | 24,200 | $1,210 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 210649458 | TRANE | 4TWL9036A1 | 4PX*BD36BS3+HORIZ-RT | *UD2B060A9V3+RP | 23,800 | $1,190 |
| No | 208106940 | TRANE | 4TWL9036A1 | 4PX*BD36BS3 | S9V2B080D4VSA+RP | 23,600 | $1,180 |
| No | 201921647 | TRANE | 4TWL9036A1 | 4PX*BD36BS3 | S9V2B080D4PSB+RP | 23,800 | $1,190 |
| No | 210653271 | TRANE | 4TWL9036A1 | 4PX*BD36BS3 | S9V2B080D3VSA+RP | 23,800 | $1,190 |
| No | 201921643 | TRANE | 4TWL9036A1 | 4PX*BD36BS3 | S9V2B080D3PSB+RP | 23,800 | $1,190 |
| No | 201921642 | TRANE | 4TWL9036A1 | 4PX*BD36BS3 | S9V2B060D3PSB+RP | 23,800 | $1,190 |
| No | 201921640 | TRANE | 4TWL9036A1 | 4PX*BD36BS3 | S9V2B040D3PSB+RP | 24,000 | $1,200 |
| No | 211081079 | TRANE | 4TWL9036A1 | 4PX*BD36BS3 | S8V2B080M4PDA | 24,200 | $1,210 |
| No | 210691711 | TRANE | 4TWL9036A1 | 4PX*BD36BS3 | S8V2B080M4PCA | 24,200 | $1,210 |
| No | 211081078 | TRANE | 4TWL9036A1 | 4PX*BD36BS3 | S8V2B060M4PDA | 24,000 | $1,200 |
| No | 210691710 | TRANE | 4TWL9036A1 | 4PX*BD36BS3 | S8V2B060M4PCA | 24,000 | $1,200 |
| No | 211081080 | TRANE | 4TWL9036A1 | 4PX*BD36BS3 | S8V2A040M3PDA | 23,000 | $1,150 |
| No | 210691709 | TRANE | 4TWL9036A1 | 4PX*BD36BS3 | S8V2A040M3PCA | 23,000 | $1,150 |
| No | 201921641 | TRANE | 4TWL9036A1 | 4PX*BD36BS3 | *DHMB080ACV3 | 24,000 | $1,200 |
| No | 201921648 | TRANE | 4TWL9036A1 | 4PX*BD36BS3 | *DHMB060BCV3 | 24,000 | $1,200 |
| No | 201921645 | TRANE | 4TWL9036A1 | 4PX*BD36BS3 | *DD2B080ACV3 | 23,800 | $1,190 |
| No | 210649456 | TRANE | 4TWL9036A1 | 4PX*BD36BS3 | *DD2B080A9V3+RP | 23,600 | $1,180 |
| No | 201921646 | TRANE | 4TWL9036A1 | 4PX*BD36BS3 | *DD2B060ACV3 | 24,200 | $1,210 |
| No | 210649457 | TRANE | 4TWL9036A1 | 4PX*BD36BS3 | *DD2B060A9V3+RP | 23,600 | $1,180 |
| No | 201923003 | TRANE | 4TWL9024A1 | TEM8A0B30V31+TDR | N/A | 14,200 | $710 |
| No | 201923158 | TRANE | 4TWL9024A1 | TEM8A0B24V21+TDR | N/A | 14,100 | $705 |
| No | 201923002 | TRANE | 4TWL9024A1 | TAM9A0C36V31 | N/A | 13,600 | $680 |
| No | 201978188 | TRANE | 4TWL9024A1 | TAM9A0A24V21 | N/A | 14,100 | $705 |
| No | 207804917 | TRANE | 4TWL9024A1 | 4TXCB003DS3+P0V0A000M30SC+RP | N/A | 13,300 | $665 |
| No | 210653267 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | S9V2B080D3VSA+RP | 13,800 | $690 |
| No | 201922971 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | S9V2B080D3PSB+RP | 13,800 | $690 |
| No | 207782151 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | S9V2B060U4PSB+RP | 14,200 | $710 |
| No | 206909920 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | S9V2B060U3VSA+RP | 14,300 | $715 |
| No | 201923129 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | S9V2B060U3PSB+RP | 14,200 | $710 |
| No | 201923130 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | S9V2B060D3PSB+RP | 13,800 | $690 |
| No | 207062438 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | S9V2B040U3VSA+RP | 14,300 | $715 |
| No | 201923128 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | S9V2B040U3PSB+RP | 14,300 | $715 |
| No | 201922968 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | S9V2B040D3PSB+RP | 13,900 | $695 |
| No | 211088794 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | S8V2B080M4PDA | 14,400 | $720 |
| No | 210692153 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | S8V2B080M4PCA | 14,400 | $720 |
| No | 211081077 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | S8V2B060M4PDA | 14,400 | $720 |
| No | 210691708 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | S8V2B060M4PCA | 14,400 | $720 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211088793 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | S8V2A040M3PDA | 13,700 | $685 |
| No | 210692152 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | S8V2A040M3PCA | 13,700 | $685 |
| No | 210653270 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | L8V1B080U4VSA+RP | 14,300 | $715 |
| No | 210653269 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | L8V1A060U3VSA+RP | 13,800 | $690 |
| No | 210653268 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | L8V1A040U3VSA+RP | 14,000 | $700 |
| No | 201921636 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | *UHMB080ACV3 | 14,100 | $705 |
| No | 201921635 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | *UHMB060ACV3 | 14,200 | $710 |
| No | 210649453 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | *UD2B080A9V3+RP | 14,000 | $700 |
| No | 210649452 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | *UD2B060A9V3+RP | 14,000 | $700 |
| No | 201922969 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | *DHMB080ACV3 | 13,900 | $695 |
| No | 201922966 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | *DHMB060BCV3 | 13,900 | $695 |
| No | 210649455 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | *DD2B080A9V3+RP | 13,300 | $665 |
| No | 201922965 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | *DD2B060ACV3 | 14,000 | $700 |
| No | 210649454 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | *DD2B060A9V3+RP | 13,500 | $675 |
| No | 211081076 | TRANE | 4TWL9024A1 | 4TXCA002DS3 | S8V2A040M3PDA | 14,500 | $725 |
| No | 210691707 | TRANE | 4TWL9024A1 | 4TXCA002DS3 | S8V2A040M3PCA | 14,500 | $725 |
| No | 210653266 | TRANE | 4TWL9024A1 | 4TXCA002DS3 | L8V1A060U3VSA+RP | 14,700 | $735 |
| No | 210653265 | TRANE | 4TWL9024A1 | 4PX*BU42BS3 | S9V2B060U4PSB+RP | 13,800 | $690 |
| No | 210653264 | TRANE | 4TWL9024A1 | 4PX*BU42BS3 | S9V2B060U3VSA+RP | 13,700 | $685 |
| No | 201922951 | TRANE | 4TWL9024A1 | 4PX*BU42BS3 | S9V2B060U3PSB+RP | 13,700 | $685 |
| No | 201923120 | TRANE | 4TWL9024A1 | 4PX*BU42BS3 | S9V2B040U3PSB+RP | 13,800 | $690 |
| No | 211088792 | TRANE | 4TWL9024A1 | 4PX*BU42BS3 | S8V2A040M3PDA | 13,400 | $670 |
| No | 210692151 | TRANE | 4TWL9024A1 | 4PX*BU42BS3 | S8V2A040M3PCA | 13,400 | $670 |
| No | 210649451 | TRANE | 4TWL9024A1 | 4PX*BU42BS3 | *UD2B080A9V3+RP | 13,500 | $675 |
| No | 210649450 | TRANE | 4TWL9024A1 | 4PX*BU42BS3 | *UD2B060A9V3+RP | 13,600 | $680 |
| No | 207804915 | TRANE | 4TWL9024A1 | 4PX*BU30BS3+P0V0A000M30SC+RP | N/A | 13,300 | $665 |
| No | 210653254 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | S9V2B080D3VSA+RP | 13,800 | $690 |
| No | 210653257 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | S9V2B080D3PSB+RP | 13,800 | $690 |
| No | 207782150 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | S9V2B060U4PSB+RP | 14,000 | $700 |
| No | 210653259 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | S9V2B060U3VSA+RP | 14,200 | $710 |
| No | 201923114 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | S9V2B060U3PSB+RP | 14,200 | $710 |
| No | 210653256 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | S9V2B060D3PSB+RP | 13,800 | $690 |
| No | 210653263 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | S9V2B040U3VSA+RP | 14,300 | $715 |
| No | 201923113 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | S9V2B040U3PSB+RP | 14,100 | $705 |
| No | 210653255 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | S9V2B040D3PSB+RP | 13,900 | $695 |
| No | 211088790 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | S8V2B080M4PDA | 14,300 | $715 |
| No | 210692150 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | S8V2B080M4PCA | 14,300 | $715 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211081075 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | S8V2B060M4PDA | 14,400 | $720 |
| No | 210691706 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | S8V2B060M4PCA | 14,400 | $720 |
| No | 211088791 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | S8V2A040M3PDA | 13,800 | $690 |
| No | 210692149 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | S8V2A040M3PCA | 13,800 | $690 |
| No | 210653262 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | L8V1B080U4VSA+RP | 14,200 | $710 |
| No | 210653261 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | L8V1A060U3VSA+RP | 13,900 | $695 |
| No | 210653260 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | L8V1A040U3VSA+RP | 14,000 | $700 |
| No | 201921632 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | *UHMB080ACV3 | 14,100 | $705 |
| No | 201921631 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | *UHMB060ACV3 | 14,000 | $700 |
| No | 210649447 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | *UD2B080A9V3+RP | 14,000 | $700 |
| No | 210649446 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | *UD2B060A9V3+RP | 14,000 | $700 |
| No | 210653258 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | *DHMB060BCV3 | 13,900 | $695 |
| No | 210649449 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | *DD2B080A9V3+RP | 13,300 | $665 |
| No | 210649448 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | *DD2B060A9V3+RP | 13,500 | $675 |
| No | 210653251 | TRANE | 4TWL9024A1 | 4PX*BU24BS3 | S9V2B080D3VSA+RP | 14,300 | $715 |
| No | 207782149 | TRANE | 4TWL9024A1 | 4PX*BU24BS3 | S9V2B060U4PSB+RP | 14,300 | $715 |
| No | 210653253 | TRANE | 4TWL9024A1 | 4PX*BU24BS3 | S9V2B060U3VSA+RP | 14,300 | $715 |
| No | 201923111 | TRANE | 4TWL9024A1 | 4PX*BU24BS3 | S9V2B060U3PSB+RP | 14,300 | $715 |
| No | 210653250 | TRANE | 4TWL9024A1 | 4PX*BU24BS3 | S9V2B060D3PSB+RP | 14,300 | $715 |
| No | 210653252 | TRANE | 4TWL9024A1 | 4PX*BU24BS3 | S9V2B040U3VSA+RP | 14,400 | $720 |
| No | 201923112 | TRANE | 4TWL9024A1 | 4PX*BU24BS3 | S9V2B040U3PSB+RP | 14,400 | $720 |
| No | 210653249 | TRANE | 4TWL9024A1 | 4PX*BU24BS3 | S9V2B040D3PSB+RP | 14,400 | $720 |
| No | 211088789 | TRANE | 4TWL9024A1 | 4PX*BU24BS3 | S8V2A040M3PDA | 13,900 | $695 |
| No | 210692148 | TRANE | 4TWL9024A1 | 4PX*BU24BS3 | S8V2A040M3PCA | 13,900 | $695 |
| No | 210653245 | TRANE | 4TWL9024A1 | 4PX*BU24BS3 | L8V1B080U4VSA+RP | 14,400 | $720 |
| No | 210653246 | TRANE | 4TWL9024A1 | 4PX*BU24BS3 | L8V1A060U3VSA+RP | 14,100 | $705 |
| No | 210653247 | TRANE | 4TWL9024A1 | 4PX*BU24BS3 | L8V1A040U3VSA+RP | 14,100 | $705 |
| No | 201921623 | TRANE | 4TWL9024A1 | 4PX*BU24BS3 | *UHMB080ACV3 | 14,200 | $710 |
| No | 201921624 | TRANE | 4TWL9024A1 | 4PX*BU24BS3 | *UHMB060ACV3 | 14,300 | $715 |
| No | 210649442 | TRANE | 4TWL9024A1 | 4PX*BU24BS3 | *UD2B080A9V3+RP | 14,300 | $715 |
| No | 210649443 | TRANE | 4TWL9024A1 | 4PX*BU24BS3 | *UD2B060A9V3+RP | 14,300 | $715 |
| No | 210653248 | TRANE | 4TWL9024A1 | 4PX*BU24BS3 | *DHMB080ACV3 | 14,400 | $720 |
| No | 210649445 | TRANE | 4TWL9024A1 | 4PX*BU24BS3 | *DD2B080A9V3+RP | 14,300 | $715 |
| No | 210649444 | TRANE | 4TWL9024A1 | 4PX*BU24BS3 | *DD2B060A9V3+RP | 14,200 | $710 |
| No | 210649441 | TRANE | 4TWL9024A1 | 4PX*BD36BS3+HORIZ-RT | *UD2B080A9V3+RP | 13,400 | $670 |
| No | 210649440 | TRANE | 4TWL9024A1 | 4PX*BD36BS3+HORIZ-RT | *UD2B060A9V3+RP | 13,700 | $685 |
| No | 210653244 | TRANE | 4TWL9024A1 | 4PX*BD36BS3 | S9V2B080D3VSA+RP | 13,700 | $685 |
| No | 201923091 | TRANE | 4TWL9024A1 | 4PX*BD36BS3 | S9V2B080D3PSB+RP | 13,700 | $685 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201923090 | TRANE | 4TWL9024A1 | 4PX*BD36BS3 | S9V2B060D3PSB+RP | 13,600 | $680 |
| No | 211088788 | TRANE | 4TWL9024A1 | 4PX*BD36BS3 | S8V2B060M4PDA | 13,900 | $695 |
| No | 210692147 | TRANE | 4TWL9024A1 | 4PX*BD36BS3 | S8V2B060M4PCA | 13,900 | $695 |
| No | 211081074 | TRANE | 4TWL9024A1 | 4PX*BD36BS3 | S8V2A040M3PDA | 13,300 | $665 |
| No | 210691705 | TRANE | 4TWL9024A1 | 4PX*BD36BS3 | S8V2A040M3PCA | 13,300 | $665 |
| No | 201921616 | TRANE | 4TWL9024A1 | 4PX*BD36BS3 | *DHMB060BCV3 | 13,700 | $685 |
| No | 210649439 | TRANE | 4TWL9024A1 | 4PX*BD36BS3 | *DD2B080A9V3+RP | 13,400 | $670 |
| No | 210649438 | TRANE | 4TWL9024A1 | 4PX*BD36BS3 | *DD2B060A9V3+RP | 13,400 | $670 |
| No | 207804913 | TRANE | 4TWL9024A1 | 4PX*BD30BS3+P0V0A000M30SC+RP | N/A | 13,300 | $665 |
| No | 210649437 | TRANE | 4TWL9024A1 | 4PX*BD30BS3+HORIZ-RT | *UD2B080A9V3+RP | 14,000 | $700 |
| No | 210649436 | TRANE | 4TWL9024A1 | 4PX*BD30BS3+HORIZ-RT | *UD2B060A9V3+RP | 14,000 | $700 |
| No | 210653243 | TRANE | 4TWL9024A1 | 4PX*BD30BS3 | S9V2B080D3VSA+RP | 14,200 | $710 |
| No | 201922929 | TRANE | 4TWL9024A1 | 4PX*BD30BS3 | S9V2B080D3PSB+RP | 14,000 | $700 |
| No | 201922930 | TRANE | 4TWL9024A1 | 4PX*BD30BS3 | S9V2B060D3PSB+RP | 14,100 | $705 |
| No | 201922931 | TRANE | 4TWL9024A1 | 4PX*BD30BS3 | S9V2B040D3PSB+RP | 14,200 | $710 |
| No | 211088785 | TRANE | 4TWL9024A1 | 4PX*BD30BS3 | S8V2B080M4PDA | 14,400 | $720 |
| No | 210692146 | TRANE | 4TWL9024A1 | 4PX*BD30BS3 | S8V2B080M4PCA | 14,400 | $720 |
| No | 211088787 | TRANE | 4TWL9024A1 | 4PX*BD30BS3 | S8V2B060M4PDA | 14,400 | $720 |
| No | 210692145 | TRANE | 4TWL9024A1 | 4PX*BD30BS3 | S8V2B060M4PCA | 14,400 | $720 |
| No | 211088786 | TRANE | 4TWL9024A1 | 4PX*BD30BS3 | S8V2A040M3PDA | 13,800 | $690 |
| No | 210692144 | TRANE | 4TWL9024A1 | 4PX*BD30BS3 | S8V2A040M3PCA | 13,800 | $690 |
| No | 201921614 | TRANE | 4TWL9024A1 | 4PX*BD30BS3 | *DHMB080ACV3 | 14,300 | $715 |
| No | 201921613 | TRANE | 4TWL9024A1 | 4PX*BD30BS3 | *DHMB060BCV3 | 14,200 | $710 |
| No | 210649434 | TRANE | 4TWL9024A1 | 4PX*BD30BS3 | *DD2B080A9V3+RP | 13,800 | $690 |
| No | 210649435 | TRANE | 4TWL9024A1 | 4PX*BD30BS3 | *DD2B060A9V3+RP | 13,900 | $695 |
| No | 211081073 | TRANE | 4TWL9024A1 | 4PX*AU24BS3 | S8V2A040M3PDA | 14,500 | $725 |
| No | 210691704 | TRANE | 4TWL9024A1 | 4PX*AU24BS3 | S8V2A040M3PCA | 14,500 | $725 |
| No | 210653242 | TRANE | 4TWL9024A1 | 4PX*AU24BS3 | L8V1A060U3VSA+RP | 14,700 | $735 |
| No | 210653241 | TRANE | 4TWL9024A1 | 4PX*AU24BS3 | L8V1A040U3VSA+RP | 14,700 | $735 |
| No | 212361356 | TRANE | 4TXD2060A10NU** | 4RXCD060AS3HC** | | 35,200 | $1,760 |
| No | 212361355 | TRANE | 4TXD2060A10NU** | 4RXCD048AS3HC** | | 31,200 | $1,560 |
| No | 212361354 | TRANE | 4TXD2036A10NU** | 4RXCB036AS3HC** | | 22,000 | $1,100 |
| No | 207629145 | TRANE | 4TXK2530A10N0** | 4MXW2530A10N0** | N/A | 16,000 | $800 |
| No | 207629143 | TRANE | 4TXK2509A10N0** | 4MXW2509A10N0** | N/A | 7,300 | $365 |
| No | 204340354 | TRANE | 4TXK3809B10NU** | 4MXW3809B10NU** | | 5,600 | $280 |
| No | 8759400 | TRANE | 4TWV0036A1 | 4PX*BU48BS3 | *UD2B080ACV3 | 26,800 | $1,340 |
| No | 8761410 | TRANE | 4TWV0036A1 | 4TXCB006DS3 | *UHMB080ACV3 | 27,000 | $1,350 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 8761470 | TRANE | 4TWV8036A1 | 4TXCC007DS3 | *UHMB080ACV3 | 26,800 | $1,340 |
| No | 8761420 | TRANE | 4TWV0036A1 | 4TXCC007DS3 | *UHMC100ACV4 | 26,800 | $1,340 |
| No | 8759390 | TRANE | 4TWV0036A1 | 4PX*BD48BS3 | *DD2B080ACV3 | 27,200 | $1,360 |
| No | 10511170 | TRANE | 4TWV0036A1 | 4PX*BD48BS3 | S9V2B080D4PSB+RP | 26,800 | $1,340 |
| No | 202541563 | TRANE | 4TXK2309A10N0** | 4MXW2309A10N0** | | 6,800 | $340 |
| No | 8935202 | TRANE | 4TWV0024A1 | 4TXCB004DS3 | *UD2B060ACV3 | 16,800 | $840 |
| No | 201923001 | TRANE | 4TWL9024A1 | 4TXFH036CZ3 | *UD2B100ACV3 | 13,300 | $665 |
| No | 201923117 | TRANE | 4TWL9024A1 | 4PX*BU42BS3 | *UD2B100ACV3 | 13,800 | $690 |
| No | 201923689 | TRANE | 4TWL9024A1 | 4PX*BU48BS3 | *UD2B100ACV3 | 13,700 | $685 |
| No | 201923691 | TRANE | 4TWL9024A1 | 4TXCB006DS3 | *UD2B100ACV3 | 13,700 | $685 |
| No | 9119408 | TRANE | 4TWV8024A1 | 4PX*BD36BS3 | *DHMB060BCV3 | 17,400 | $870 |
| No | 201923148 | TRANE | 4TWL9024A1 | 4TXFH024CZ3 | *UD2B100ACV3 | 13,500 | $675 |
| No | 201922973 | TRANE | 4TWL9024A1 | 4TXCB004DS3 | *UD2B100ACV3 | 13,400 | $670 |
| No | 201922944 | TRANE | 4TWL9024A1 | 4PX*BU36BS3 | *UD2B100ACV3 | 13,400 | $670 |
| No | 10093516 | TRANE | 4TWV8060A1 | TAM9A0C60V51 | | 48,000 | $2,400 |
| No | 207526309 | TRANE | 4TWV8X24A1 | 4TXCB003DS3 | *UD2B060ACV3 | 17,600 | $880 |
| No | 9150123 | TRANE | 4TXK3812A10NU** | 4MXW3812A10NU** | | 8,100 | $405 |
| No | 7599437 | TRANE | 4TWV0036A1 | *AM8C0C48V41 | | 25,400 | $1,270 |
| No | 7151531 | TRANE | 4TXK2709A10N0AA | 4MXW2709A10N0AA | | 5,800 | $290 |
| No | 6796636 | TRANE | 4TWV8037A1 | 4TXCB004CC3 | *UD2B080ACV3 | 25,800 | $1,290 |
| No | 6992578 | TRANE | 4TWV0036A1 | *AM8C0B30V21 | | 26,200 | $1,310 |
| No | 7125586 | TRANE | 4TWV0036A1 | 4TXCB004CC3 | *UHMB060ACV3 | 26,000 | $1,300 |
| No | 6796638 | TRANE | 4TWV8037A1 | 4TXCC007CC3 | *UD2C080ACV4 | 25,800 | $1,290 |
| No | 6796635 | TRANE | 4TWV8037A1 | *AM8C0B30V21 | | 26,200 | $1,310 |
| No | 201923083 | TRANE | 4TWL9024A1 | 4PX*BD24BS3 | S9V2B060D3PSB+RP | 14,200 | $710 |
| No | 6796602 | TRANE | 4TWV0036A1 | 4TXCC007CC3 | *UD2C100ACV5 | 25,600 | $1,280 |
| No | 6750234 | TRANE | 4TWV8036A1 | *AM8C0C36V31 | | 25,200 | $1,260 |
| No | 6796600 | TRANE | 4TWV0036A1 | 4TXCC007CC3 | *UD2C080ACV4 | 25,800 | $1,290 |
| No | 6749942 | TRANE | 4TWV0024A1 | *AM8C0B30V21 | | 16,800 | $840 |
| No | 6750459 | TRANE | 4TWV8024A1 | *AM8C0B30V21 | | 16,800 | $840 |
| No | 8854988 | TRANE | 4TWV8024A1 | 4TXCB003DS3 | *UD2B060ACV3 | 17,600 | $880 |
| No | 8761457 | TRANE | 4TWV8036A1 | 4TXCB006DS3 | *UHMB060ACV3 | 26,400 | $1,320 |
| No | 8761448 | TRANE | 4TWV8036A1 | 4TXCB004DS3 | *UHMB060ACV3 | 26,600 | $1,330 |
| No | 8759496 | TRANE | 4TWV8037A1 | 4PX*BU48BS3 | *UD2B060ACV3 | 26,800 | $1,340 |
| No | 8759495 | TRANE | 4TWV8037A1 | 4PX*BU48BS3 | *UD2B080ACV3 | 26,800 | $1,340 |
| No | 8759473 | TRANE | 4TWV8036A1 | 4PX*CU48BS3 | *UD2B100ACV3 | 26,800 | $1,340 |
| No | 8759471 | TRANE | 4TWV8036A1 | 4PX*CU36BS3 | *UD2B100ACV3 | 26,200 | $1,310 |
| No | 202492136 | TRANE | 4TWV0036A1 | 4PX*CD42BS3 | *DD2C100ACV5 | 25,800 | $1,290 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201921867 | TRANE | 4TWL9036A1 | 4TXFH036CZ3 | *UD2B100ACV3 | 22,600 | $1,130 |
| No | 201921841 | TRANE | 4TWL9036A1 | 4TXCC007DS3 | *UD2B100ACV3 | 23,600 | $1,180 |
| No | 201921739 | TRANE | 4TWL9036A1 | 4PX*CU48BS3 | *UD2B100ACV3 | 23,600 | $1,180 |
| No | 201921722 | TRANE | 4TWL9036A1 | 4PX*CU42BS3 | *UD2B100ACV3 | 23,600 | $1,180 |
| No | 201921711 | TRANE | 4TWL9036A1 | 4PX*CU36BS3 | *UD2B100ACV3 | 23,000 | $1,150 |
| No | 201921653 | TRANE | 4TWL9036A1 | 4PX*BD36BS3+HORIZ-RT | *UD2B100ACV3 | 23,400 | $1,170 |
| No | 201921634 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | *UD2B100ACV3 | 14,100 | $705 |
| No | 10511297 | TRANE | 4TWV8036A1 | 4TXCC005DS3 | S9V2C100D4PSB+RP | 25,400 | $1,270 |
| No | 10153725 | TRANE | 4TWV8037A1 | TEM8A0D48V41+TDR | N/A | 25,800 | $1,290 |
| No | 10153724 | TRANE | 4TWV8037A1 | TEM8A0C48V41+TDR | N/A | 25,200 | $1,260 |
| No | 10093503 | TRANE | 4TWV8024A1 | TAM9A0C36V31 | N/A | 16,900 | $845 |
| No | 8761492 | TRANE | 4TWV8037A1 | 4TXCC007DS3 | *UHMC100ACV4 | 26,800 | $1,340 |
| No | 8761473 | TRANE | 4TWV8036A1 | 4TXCC007DS3 | *UHMC100ACV4 | 26,600 | $1,330 |
| No | 8761409 | TRANE | 4TWV0036A1 | 4TXCB006DS3 | *UHMB060ACV3 | 26,400 | $1,320 |
| No | 7125597 | TRANE | 4TWV8037A1 | 4TXFH036CZ3 | *DHMB060BCV3 | 25,800 | $1,290 |
| No | 6796641 | TRANE | 4TWV8037A1 | 4TXFH036CZ3 | *UD2C080ACV4 | 25,600 | $1,280 |
| No | 8761493 | TRANE | 4TWV8037A1 | 4TXCC007DS3 | *UD2C100ACV5 | 26,600 | $1,330 |
| No | 8761494 | TRANE | 4TWV8037A1 | 4TXCC007DS3 | *UD2C080ACV4 | 26,600 | $1,330 |
| No | 8761485 | TRANE | 4TWV8037A1 | 4TXCB006DS3 | *UHMB080ACV3 | 27,000 | $1,350 |
| No | 8761483 | TRANE | 4TWV8037A1 | 4TXCB006DS3 | *UD2B080ACV3 | 26,800 | $1,340 |
| No | 8761486 | TRANE | 4TWV8037A1 | 4TXCB006DS3 | *UD2B060ACV3 | 26,800 | $1,340 |
| No | 8761478 | TRANE | 4TWV8037A1 | 4TXCB004DS3 | *UD2B080ACV3 | 26,000 | $1,300 |
| No | 8761471 | TRANE | 4TWV8036A1 | 4TXCC007DS3 | *UD2C100ACV5 | 26,200 | $1,310 |
| No | 8761468 | TRANE | 4TWV8036A1 | 4TXCC007DS3 | *UD2C080ACV4 | 26,400 | $1,320 |
| No | 8761467 | TRANE | 4TWV8036A1 | 4TXCC007DS3 | *UD2B100ACV3 | 26,800 | $1,340 |
| No | 8761459 | TRANE | 4TWV8036A1 | 4TXCB006DS3 | *UD2B060ACV3 | 26,600 | $1,330 |
| No | 8761458 | TRANE | 4TWV8036A1 | 4TXCB006DS3 | *UD2B080ACV3 | 26,600 | $1,330 |
| No | 8761443 | TRANE | 4TWV8024A1 | 4TXCB004DS3 | *DD2B060ACV3 | 16,500 | $825 |
| No | 8761454 | TRANE | 4TWV8036A1 | 4TXCB006DS3 | *UHMB080ACV3 | 26,600 | $1,330 |
| No | 8761444 | TRANE | 4TWV8024A1 | 4TXCB004DS3 | *UHMB080ACV3 | 16,900 | $845 |
| No | 8761421 | TRANE | 4TWV0036A1 | 4TXCC007DS3 | *UD2C080ACV4 | 26,600 | $1,330 |
| No | 8761418 | TRANE | 4TWV0036A1 | 4TXCC007DS3 | *UD2C100ACV5 | 26,600 | $1,330 |
| No | 8761411 | TRANE | 4TWV0036A1 | 4TXCB006DS3 | *UD2B080ACV3 | 26,800 | $1,340 |
| No | 8761406 | TRANE | 4TWV0036A1 | 4TXCB004DS3 | *UD2B080ACV3 | 26,000 | $1,300 |
| No | 8761398 | TRANE | 4TWV0024A1 | 4TXCB004DS3 | *UHMB060ACV3 | 16,900 | $845 |
| No | 8761399 | TRANE | 4TWV0024A1 | 4TXCB004DS3 | *UHMB080ACV3 | 16,900 | $845 |
| No | 8759502 | TRANE | 4TWV8037A1 | 4PX*CD48BS3 | *DD2C100ACV5 | 27,000 | $1,350 |
| No | 8759486 | TRANE | 4TWV8037A1 | 4PX*BD48BS3 | *DD2B080ACV3 | 27,200 | $1,360 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 8759494 | TRANE | 4TWV8037A1 | 4PX*BU36BS3 | *UD2B080ACV3 | 26,000 | $1,300 |
| No | 8759479 | TRANE | 4TWV8036A1 | 4PX*CU60BS3 | *UD2B100ACV3 | 26,400 | $1,320 |
| No | 6796642 | TRANE | 4TWV8037A1 | 4TXFH036CZ3 | *UD2B080ACV3 | 25,600 | $1,280 |
| No | 6796623 | TRANE | 4TWV8024A1 | 4TXFH024CZ3 | *DD2B060ACV3 | 16,600 | $830 |
| No | 6796621 | TRANE | 4TWV8024A1 | 4TXFH024CZ3 | *UD2B060ACV3 | 16,200 | $810 |
| No | 6796605 | TRANE | 4TWV0036A1 | 4TXFH036CZ3 | *UD2B080ACV3 | 25,600 | $1,280 |
| No | 201923093 | TRANE | 4TWL9024A1 | 4PX*BD36BS3+HORIZ-RT | *UD2B100ACV3 | 13,800 | $690 |
| No | 201921625 | TRANE | 4TWL9024A1 | 4PX*BU24BS3 | *UD2B100ACV3 | 14,100 | $705 |
| No | 201921617 | TRANE | 4TWL9024A1 | 4PX*BD42BS3+HORIZ-RT | *UD2B100ACV3 | 13,200 | $660 |
| No | 201808683 | TRANE | 4TWV0036A1 | 4PX*BD48BS3 | S9V2B080D3VSA+RP | 26,800 | $1,340 |
| No | 10511307 | TRANE | 4TWV8037A1 | 4PX*BD48BS3 | S9V2B080D4PSB+RP | 26,800 | $1,340 |
| No | 10511306 | TRANE | 4TWV8037A1 | 4PX*BD48BS3 | S9V2B040D3PSB+RP | 26,800 | $1,340 |
| No | 10511308 | TRANE | 4TWV8037A1 | 4PX*BD48BS3 | S9V2B080D3PSB+RP | 26,800 | $1,340 |
| No | 10511172 | TRANE | 4TWV0036A1 | 4PX*BD48BS3 | S9V2B080D3PSB+RP | 26,800 | $1,340 |
| No | 10511169 | TRANE | 4TWV0036A1 | 4PX*BD48BS3 | S9V2B040D3PSB+RP | 26,800 | $1,340 |
| No | 9045934 | TRANE | 4TXM2236A15N0** | Heat pump without ducts | | 25,000 | $1,250 |
| No | 9045933 | TRANE | 4TXM2224A14N0** | Heat pump without ducts | | 18,000 | $900 |
| No | 9057065 | TRANE | 4TXM2230A15N0** | Heat pump without ducts | | 27,000 | $1,350 |
| No | 9045932 | TRANE | 4TXM2218A12N0** | Heat pump without ducts | | 12,800 | $640 |
| No | 9057064 | TRANE | 4TXM2221A13N0** | Heat pump without ducts | | 16,800 | $840 |
| No | 201921820 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | *UD2B100ACV3 | 23,000 | $1,150 |
| No | 201921630 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | *UD2B100ACV3 | 14,100 | $705 |
| No | 201921620 | TRANE | 4TWL9024A1 | 4PX*BD48BS3+HORIZ-RT | *UD2B100ACV3 | 13,800 | $690 |
| No | 201808880 | TRANE | 4TWV8037A1 | 4PX*BD48BS3 | S9V2B080D3VSA+RP | 26,800 | $1,340 |
| No | 9058675 | TRANE | 4TXM2242A15N0** | Heat pump without ducts | | 29,000 | $1,450 |
| No | 201922961 | TRANE | 4TWL9024A1 | 4PX*CU42BS3 | *UD2C080ACV4 | 13,800 | $690 |
| No | 201923110 | TRANE | 4TWL9024A1 | 4PX*BD48BS3+HORIZ-RT | S9V2B040U3PSB+RP | 13,900 | $695 |
| No | 201923107 | TRANE | 4TWL9024A1 | 4PX*BD48BS3 | S9V2B040D3PSB+RP | 13,900 | $695 |
| No | 201922992 | TRANE | 4TWL9024A1 | 4TXCC007DS3 | *UD2C080ACV4 | 13,600 | $680 |
| No | 201922962 | TRANE | 4TWL9024A1 | 4PX*CU42BS3 | *UHMC100ACV4 | 13,900 | $695 |
| No | 201922964 | TRANE | 4TWL9024A1 | 4PX*CU48BS3 | *UD2C080ACV4 | 13,600 | $680 |
| No | 201922991 | TRANE | 4TWL9024A1 | 4TXCC007DS3 | *UHMC100ACV4 | 13,700 | $685 |
| No | 201922963 | TRANE | 4TWL9024A1 | 4PX*CU48BS3 | *UHMC100ACV4 | 13,700 | $685 |
| No | 201923140 | TRANE | 4TWL9024A1 | 4TXCB006DS3 | S9V2B060U3PSB+RP | 13,500 | $675 |
| No | 201923121 | TRANE | 4TWL9024A1 | 4PX*BU48BS3 | S9V2B060U3PSB+RP | 13,500 | $675 |
| No | 201923119 | TRANE | 4TWL9024A1 | 4PX*BU42BS3 | *UD2B060ACV3 | 13,800 | $690 |
| No | 201923118 | TRANE | 4TWL9024A1 | 4PX*BU42BS3 | *UD2B080ACV3 | 13,800 | $690 |
| No | 201923109 | TRANE | 4TWL9024A1 | 4PX*BD48BS3+HORIZ-RT | S9V2B060U3PSB+RP | 13,800 | $690 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201923106 | TRANE | 4TWL9024A1 | 4PX*BD48BS3 | S9V2B060D3PSB+RP | 13,800 | $690 |
| No | 201923124 | TRANE | 4TWL9024A1 | 4PX*BU48BS3 | *UD2B080ACV3 | 13,600 | $680 |
| No | 201923144 | TRANE | 4TWL9024A1 | 4TXCC009DS3 | *UD2C080ACV4 | 13,400 | $670 |
| No | 201923127 | TRANE | 4TWL9024A1 | 4PX*CU60BS3 | *UD2C080ACV4 | 13,400 | $670 |
| No | 201923136 | TRANE | 4TWL9024A1 | 4TXCB006DS3 | *UD2B080ACV3 | 13,600 | $680 |
| No | 201923004 | TRANE | 4TWL9024A1 | TEM8A0C36V31+TDR | | 13,300 | $665 |
| No | 201922950 | TRANE | 4TWL9024A1 | 4PX*BU42BS3 | S9V2B080U3PSB+RP | 13,700 | $685 |
| No | 201923141 | TRANE | 4TWL9024A1 | 4TXCB006DS3 | S9V2B040U3PSB+RP | 13,600 | $680 |
| No | 201923122 | TRANE | 4TWL9024A1 | 4PX*BU48BS3 | S9V2B040U3PSB+RP | 13,600 | $680 |
| No | 201923092 | TRANE | 4TWL9024A1 | 4PX*BD36BS3+HORIZ-RT | *UD2B060ACV3 | 13,900 | $695 |
| No | 201921619 | TRANE | 4TWL9024A1 | 4PX*BD48BS3 | *DD2B060ACV3 | 13,800 | $690 |
| No | 201922986 | TRANE | 4TWL9024A1 | 4TXCB006DS3 | S9V2B080U3PSB+RP | 13,500 | $675 |
| No | 201922952 | TRANE | 4TWL9024A1 | 4PX*BU48BS3 | S9V2B080U3PSB+RP | 13,500 | $675 |
| No | 201922981 | TRANE | 4TWL9024A1 | 4TXCB006DS3 | S9V2B040D3PSB+RP | 13,400 | $670 |
| No | 201922956 | TRANE | 4TWL9024A1 | 4PX*CD36BS3+HORIZ-RT | *UD2C080ACV4 | 13,700 | $685 |
| No | 201921622 | TRANE | 4TWL9024A1 | 4PX*BD48BS3+HORIZ-RT | *UD2B060ACV3 | 13,800 | $690 |
| No | 201923126 | TRANE | 4TWL9024A1 | 4PX*CU60BS3 | *UHMC100ACV4 | 13,500 | $675 |
| No | 201922984 | TRANE | 4TWL9024A1 | 4TXCB006DS3 | *DD2B080ACV3 | 13,500 | $675 |
| No | 201922967 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | S9V2B080U3PSB+RP | 14,100 | $705 |
| No | 201922939 | TRANE | 4TWL9024A1 | 4PX*BD48BS3 | S9V2B080D3PSB+RP | 13,800 | $690 |
| No | 201922942 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | S9V2B080U3PSB+RP | 14,100 | $705 |
| No | 201923143 | TRANE | 4TWL9024A1 | 4TXCC009DS3 | *UHMC100ACV4 | 13,500 | $675 |
| No | 201921638 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | *UD2B060ACV3 | 14,100 | $705 |
| No | 201921628 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | *UD2B060ACV3 | 14,100 | $705 |
| No | 201921857 | TRANE | 4TWL9036A1 | 4TXCD008DS3 | *UD2D120ACV5 | 23,400 | $1,170 |
| No | 201922940 | TRANE | 4TWL9024A1 | 4PX*BD48BS3+HORIZ-RT | S9V2B080U3PSB+RP | 13,800 | $690 |
| No | 201921618 | TRANE | 4TWL9024A1 | 4PX*BD48BS3 | *DHMB060BCV3 | 13,900 | $695 |
| No | 201921797 | TRANE | 4TWL9036A1 | 4PX*DU48BS3 | *UD2D120ACV5 | 23,400 | $1,170 |
| No | 201923089 | TRANE | 4TWL9024A1 | 4PX*BD36BS3 | *DD2B080ACV3 | 13,800 | $690 |
| No | 201922935 | TRANE | 4TWL9024A1 | 4PX*BD36BS3+HORIZ-RT | *UD2B080ACV3 | 13,800 | $690 |
| No | 201922948 | TRANE | 4TWL9024A1 | 4PX*BU42BS3 | *UHMB080ACV3 | 14,000 | $700 |
| No | 201923151 | TRANE | 4TWL9024A1 | 4TXFH024CZ3 | *UD2C080ACV4 | 13,400 | $670 |
| No | 201923137 | TRANE | 4TWL9024A1 | 4TXCB006DS3 | *UD2B060ACV3 | 13,600 | $680 |
| No | 201923123 | TRANE | 4TWL9024A1 | 4PX*BU48BS3 | *UD2B060ACV3 | 13,600 | $680 |
| No | 201922997 | TRANE | 4TWL9024A1 | 4TXFH024CZ3 | S9V2B040U3PSB+RP | 13,400 | $670 |
| No | 201922996 | TRANE | 4TWL9024A1 | 4TXFH024CZ3 | S9V2B060U3PSB+RP | 13,400 | $670 |
| No | 201921860 | TRANE | 4TWL9036A1 | 4TXCD010DS3 | *UD2D120ACV5 | 23,000 | $1,150 |
| No | 201921800 | TRANE | 4TWL9036A1 | 4PX*DU60BS3 | *UD2D120ACV5 | 23,000 | $1,150 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201923125 | TRANE | 4TWL9024A1 | 4PX*CD60BS3+HORIZ-RT | *UD2C080ACV4 | 13,400 | $670 |
| No | 201922960 | TRANE | 4TWL9024A1 | 4PX*CU36BS3 | *UD2C080ACV4 | 13,300 | $665 |
| No | 201922989 | TRANE | 4TWL9024A1 | 4TXCC005DS3 | *UD2C080ACV4 | 13,300 | $665 |
| No | 201923095 | TRANE | 4TWL9024A1 | 4PX*BD36BS3+HORIZ-RT | S9V2B080U3PSB+RP | 13,700 | $685 |
| No | 201923094 | TRANE | 4TWL9024A1 | 4PX*BD36BS3+HORIZ-RT | S9V2B060U3PSB+RP | 13,700 | $685 |
| No | 201922953 | TRANE | 4TWL9024A1 | 4PX*BU48BS3 | *UHMB060ACV3 | 13,800 | $690 |
| No | 201922934 | TRANE | 4TWL9024A1 | 4PX*BD36BS3 | S9V2B040D3PSB+RP | 13,800 | $690 |
| No | 201922936 | TRANE | 4TWL9024A1 | 4PX*BD36BS3+HORIZ-RT | S9V2B040U3PSB+RP | 13,800 | $690 |
| No | 201921621 | TRANE | 4TWL9024A1 | 4PX*BD48BS3+HORIZ-RT | *UD2B080ACV3 | 13,700 | $685 |
| No | 201921637 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | *UD2B080ACV3 | 14,000 | $700 |
| No | 201921629 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | *UD2B080ACV3 | 14,000 | $700 |
| No | 201922988 | TRANE | 4TWL9024A1 | 4TXCB006DS3 | *UHMB060ACV3 | 13,800 | $690 |
| No | 201921856 | TRANE | 4TWL9036A1 | 4TXCD008DS3 | *UD2D140ACV5 | 23,400 | $1,170 |
| No | 201921792 | TRANE | 4TWL9036A1 | 4PX*DU48BS3 | *UD2D140ACV5 | 23,400 | $1,170 |
| No | 201922949 | TRANE | 4TWL9024A1 | 4PX*BU42BS3 | *UHMB060ACV3 | 14,000 | $700 |
| No | 201921863 | TRANE | 4TWL9036A1 | 4TXCD010DS3 | *UD2D140ACV5 | 23,000 | $1,150 |
| No | 201923147 | TRANE | 4TWL9024A1 | 4TXFH024CZ3 | S9V2B080U3PSB+RP | 13,400 | $670 |
| No | 201922933 | TRANE | 4TWL9024A1 | 4PX*BD36BS3 | *DD2B060ACV3 | 13,800 | $690 |
| No | 201923139 | TRANE | 4TWL9024A1 | 4TXCB006DS3 | S9V2B060D3PSB+RP | 13,300 | $665 |
| No | 201921803 | TRANE | 4TWL9036A1 | 4PX*DU60BS3 | *UD2D140ACV5 | 23,000 | $1,150 |
| No | 206910642 | TRANE | 4TWL9024A1 | 4PX*BD48BS3+HORIZ-RT | S9V2B060U4PSBC+RP | 13,300 | $665 |
| No | 201923150 | TRANE | 4TWL9024A1 | 4TXFH024CZ3 | *UD2B060ACV3 | 13,400 | $670 |
| No | 201923145 | TRANE | 4TWL9024A1 | 4TXFH024CZ3 | *UHMC100ACV4 | 13,500 | $675 |
| No | 201922985 | TRANE | 4TWL9024A1 | 4TXCB006DS3 | *DD2B060ACV3 | 13,300 | $665 |
| No | 201922972 | TRANE | 4TWL9024A1 | 4TXCB004DS3 | *UD2B060ACV3 | 13,400 | $670 |
| No | 201922943 | TRANE | 4TWL9024A1 | 4PX*BU36BS3 | *UD2B060ACV3 | 13,400 | $670 |
| No | 201921713 | TRANE | 4TWL9036A1 | 4PX*CU42BS3 | S9V2B080U4PSB+RP | 23,800 | $1,190 |
| No | 201921845 | TRANE | 4TWL9036A1 | 4TXCC007DS3 | S9V2B080U4PSB+RP | 23,600 | $1,180 |
| No | 201921843 | TRANE | 4TWL9036A1 | 4TXCC007DS3 | S9V2B040U3PSB+RP | 23,600 | $1,180 |
| No | 201921756 | TRANE | 4TWL9036A1 | 4PX*CU48BS3 | S9V2B080U4PSB+RP | 23,600 | $1,180 |
| No | 201921744 | TRANE | 4TWL9036A1 | 4PX*CU48BS3 | S9V2B040U3PSB+RP | 23,600 | $1,180 |
| No | 201922979 | TRANE | 4TWL9024A1 | 4TXCB004DS3 | S9V2B080U3PSB+RP | 13,300 | $665 |
| No | 201922947 | TRANE | 4TWL9024A1 | 4PX*BU36BS3 | S9V2B080U3PSB+RP | 13,300 | $665 |
| No | 201922954 | TRANE | 4TWL9024A1 | 4PX*BU48BS3 | *UHMB080ACV3 | 13,800 | $690 |
| No | 201922987 | TRANE | 4TWL9024A1 | 4TXCB006DS3 | *UHMB080ACV3 | 13,800 | $690 |
| No | 201923000 | TRANE | 4TWL9024A1 | 4TXFH036CZ3 | *UD2C080ACV4 | 13,200 | $660 |
| No | 201921725 | TRANE | 4TWL9036A1 | 4PX*CU42BS3 | S9V2B040U3PSB+RP | 23,800 | $1,190 |
| No | 201922999 | TRANE | 4TWL9024A1 | 4TXFH036CZ3 | *UD2B080ACV3 | 13,300 | $665 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201921849 | TRANE | 4TWL9036A1 | 4TXCC007DS3 | S9V2B060U4PSB+RP | 23,400 | $1,170 |
| No | 201921751 | TRANE | 4TWL9036A1 | 4PX*CU48BS3 | S9V2B060U4PSB+RP | 23,400 | $1,170 |
| No | 201921865 | TRANE | 4TWL9036A1 | 4TXCD010DS3+HORIZ-LT | *DD2D120ACV5 | 22,800 | $1,140 |
| No | 201921837 | TRANE | 4TWL9036A1 | 4TXCC007DS3 | S9V2B060U3PSB+RP | 23,600 | $1,180 |
| No | 201923155 | TRANE | 4TWL9024A1 | 4TXFH036CZ3 | S9V2B060U3PSB+RP | 13,200 | $660 |
| No | 206918555 | TRANE | 4TWL9036A1 | TEM6A0D48H41+TDR+RP | | 22,200 | $1,110 |
| No | 201921749 | TRANE | 4TWL9036A1 | 4PX*CU48BS3 | S9V2B060U3PSB+RP | 23,600 | $1,180 |
| No | 201923138 | TRANE | 4TWL9024A1 | 4TXCB006DS3 | S9V2B080D3PSB+RP | 13,300 | $665 |
| No | 201922983 | TRANE | 4TWL9024A1 | 4TXCB006DS3 | *DHMB060BCV3 | 13,400 | $670 |
| No | 201923153 | TRANE | 4TWL9024A1 | 4TXFH036CZ3 | S9V2B040U3PSB+RP | 13,200 | $660 |
| No | 201921734 | TRANE | 4TWL9036A1 | 4PX*CU42BS3 | S9V2B060U3PSB+RP | 23,600 | $1,180 |
| No | 201922970 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | *DD2B080ACV3 | 13,800 | $690 |
| No | 206910658 | TRANE | 4TWL9036A1 | 4TXCC007DS3 | S9V2C100U5PSBC+RP | 22,800 | $1,140 |
| No | 206910655 | TRANE | 4TWL9036A1 | 4PX*CU48BS3 | S9V2C100U5PSBC+RP | 22,800 | $1,140 |
| No | 201921720 | TRANE | 4TWL9036A1 | 4PX*CU42BS3 | S9V2B060U4PSB+RP | 23,600 | $1,180 |
| No | 201921753 | TRANE | 4TWL9036A1 | 4PX*CU48BS3 | S9V2B080U3PSB+RP | 23,400 | $1,170 |
| No | 201921844 | TRANE | 4TWL9036A1 | 4TXCC007DS3 | S9V2B080U3PSB+RP | 23,400 | $1,170 |
| No | 206910654 | TRANE | 4TWL9036A1 | 4PX*CU42BS3 | S9V2C100U5PSBC+RP | 23,000 | $1,150 |
| No | 201921787 | TRANE | 4TWL9036A1 | 4PX*DD60BS3+HORIZ-RT | *UD2D120ACV5 | 23,000 | $1,150 |
| No | 201923154 | TRANE | 4TWL9024A1 | 4TXFH036CZ3 | S9V2B080U3PSB+RP | 13,200 | $660 |
| No | 201923149 | TRANE | 4TWL9024A1 | 4TXFH024CZ3 | *UD2B080ACV3 | 13,400 | $670 |
| No | 201923131 | TRANE | 4TWL9024A1 | 4TXCB004DS3 | *UD2B080ACV3 | 13,300 | $665 |
| No | 201923115 | TRANE | 4TWL9024A1 | 4PX*BU36BS3 | *UD2B080ACV3 | 13,300 | $665 |
| No | 201922990 | TRANE | 4TWL9024A1 | 4TXCC005DS3 | *UHMC100ACV4 | 13,400 | $670 |
| No | 201922959 | TRANE | 4TWL9024A1 | 4PX*CU36BS3 | *UHMC100ACV4 | 13,400 | $670 |
| No | 201921615 | TRANE | 4TWL9024A1 | 4PX*BD30BS3 | *DD2B060ACV3 | 14,100 | $705 |
| No | 201923108 | TRANE | 4TWL9024A1 | 4PX*BD48BS3 | *DHMB080ACV3 | 14,100 | $705 |
| No | 201921782 | TRANE | 4TWL9036A1 | 4PX*DD60BS3 | *DHMD120BCV5 | 23,000 | $1,150 |
| No | 201921718 | TRANE | 4TWL9036A1 | 4PX*CU42BS3 | S9V2B080U3PSB+RP | 23,600 | $1,180 |
| No | 201921790 | TRANE | 4TWL9036A1 | 4PX*DD60BS3+HORIZ-RT | *UD2D140ACV5 | 23,200 | $1,160 |
| No | 201922980 | TRANE | 4TWL9024A1 | 4TXCB004DS3 | S9V2B060U3PSB+RP | 13,200 | $660 |
| No | 201922946 | TRANE | 4TWL9024A1 | 4PX*BU36BS3 | S9V2B060U3PSB+RP | 13,200 | $660 |
| No | 206910645 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | S9V2B060U4PSBC+RP | 13,600 | $680 |
| No | 201921861 | TRANE | 4TWL9036A1 | 4TXCD010DS3 | *UHMD120ACV5 | 23,400 | $1,170 |
| No | 201921864 | TRANE | 4TWL9036A1 | 4TXCD010DS3 | *DD2D120ACV5 | 22,400 | $1,120 |
| No | 206910644 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | S9V2B060U4PSBC+RP | 13,600 | $680 |
| No | 201921802 | TRANE | 4TWL9036A1 | 4PX*DU60BS3 | *UHMD120ACV5 | 23,400 | $1,170 |
| No | 201921766 | TRANE | 4TWL9036A1 | 4PX*CU60BS3 | *UHMC100ACV4 | 23,000 | $1,150 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201921842 | TRANE | 4TWL9036A1 | 4TXCC007DS3 | *UD2B080ACV3 | 23,400 | $1,170 |
| No | 201921737 | TRANE | 4TWL9036A1 | 4PX*CU48BS3 | *UD2B080ACV3 | 23,400 | $1,170 |
| No | 201923157 | TRANE | 4TWL9024A1 | 4TXFH036CZ3 | *UHMC100ACV4 | 13,300 | $665 |
| No | 201921859 | TRANE | 4TWL9036A1 | 4TXCD008DS3 | *DD2D120ACV5 | 22,600 | $1,130 |
| No | 201923703 | TRANE | 4TWL9036A1 | TAM9A0C36V31 | | 22,800 | $1,140 |
| No | 201922974 | TRANE | 4TWL9024A1 | 4TXCB004DS3 | *DD2B060ACV3 | 13,200 | $660 |
| No | 201922978 | TRANE | 4TWL9024A1 | 4TXCB004DS3 | S9V2B040U3PSB+RP | 13,300 | $665 |
| No | 201922945 | TRANE | 4TWL9024A1 | 4PX*BU36BS3 | S9V2B040U3PSB+RP | 13,300 | $665 |
| No | 204780286 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | P0V0B000M40SA+RP | 23,000 | $1,150 |
| No | 204780280 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | P0V0B000M40SA+RP | 23,000 | $1,150 |
| No | 201923156 | TRANE | 4TWL9024A1 | 4TXFH036CZ3 | *UD2B060ACV3 | 13,200 | $660 |
| No | 201922982 | TRANE | 4TWL9024A1 | 4TXCB006DS3 | *DHMB080ACV3 | 13,700 | $685 |
| No | 201921858 | TRANE | 4TWL9036A1 | 4TXCD008DS3 | *DHMD120BCV5 | 23,000 | $1,150 |
| No | 201921686 | TRANE | 4TWL9036A1 | 4PX*CD48BS3 | S9V2C100D4PSB+RP | 23,800 | $1,190 |
| No | 201923146 | TRANE | 4TWL9024A1 | 4TXFH024CZ3 | *UHMB080ACV3 | 13,600 | $680 |
| No | 201923134 | TRANE | 4TWL9024A1 | 4TXCB004DS3 | S9V2B060D3PSB+RP | 13,100 | $655 |
| No | 204433489 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | S9V2B080U3VSA+RP | 23,200 | $1,160 |
| No | 206908444 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | S9V2B060U3PSA+RP | 13,600 | $680 |
| No | 201921784 | TRANE | 4TWL9036A1 | 4PX*DD60BS3 | *DD2D120ACV5 | 22,800 | $1,140 |
| No | 201921862 | TRANE | 4TWL9036A1 | 4TXCD010DS3 | *DHMD120BCV5 | 22,200 | $1,110 |
| No | 206918553 | TRANE | 4TWL9036A1 | TEM6A0C36H31+TDR+RP | | 22,200 | $1,110 |
| No | 201922932 | TRANE | 4TWL9024A1 | 4PX*BD36BS3 | *DHMB080ACV3 | 14,000 | $700 |
| No | 201923132 | TRANE | 4TWL9024A1 | 4TXCB004DS3 | *DD2B080ACV3 | 13,100 | $655 |
| No | 201923103 | TRANE | 4TWL9024A1 | 4PX*BD42BS3+HORIZ-RT | *UD2B080ACV3 | 13,300 | $665 |
| No | 201923102 | TRANE | 4TWL9024A1 | 4PX*BD42BS3+HORIZ-RT | *UD2B060ACV3 | 13,300 | $665 |
| No | 201923097 | TRANE | 4TWL9024A1 | 4PX*BD42BS3 | *DD2B080ACV3 | 13,300 | $665 |
| No | 201921716 | TRANE | 4TWL9036A1 | 4PX*CU42BS3 | *UD2B080ACV3 | 23,600 | $1,180 |
| No | 205962244 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | P0V0B000M40SB+RP | 22,400 | $1,120 |
| No | 205962240 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | P0V0B000M40SB+RP | 22,400 | $1,120 |
| No | 204780278 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | P0V0B000M40SA+RP | 23,200 | $1,160 |
| No | 201923101 | TRANE | 4TWL9024A1 | 4PX*BD42BS3+HORIZ-RT | S9V2B060U3PSB+RP | 13,200 | $660 |
| No | 201923099 | TRANE | 4TWL9024A1 | 4PX*BD42BS3 | S9V2B060D3PSB+RP | 13,200 | $660 |
| No | 201921855 | TRANE | 4TWL9036A1 | 4TXCD008DS3 | *UHMD120ACV5 | 23,400 | $1,170 |
| No | 201922976 | TRANE | 4TWL9024A1 | 4TXCB004DS3 | S9V2B040D3PSB+RP | 13,100 | $655 |
| No | 201921794 | TRANE | 4TWL9036A1 | 4PX*DU48BS3 | *UHMD120ACV5 | 23,400 | $1,170 |
| No | 201922977 | TRANE | 4TWL9024A1 | 4TXCB004DS3 | S9V2B080D3PSB+RP | 13,100 | $655 |
| No | 201921772 | TRANE | 4TWL9036A1 | 4PX*DD48BS3 | *DD2D120ACV5 | 23,600 | $1,180 |
| No | 201921780 | TRANE | 4TWL9036A1 | 4PX*DD48BS3+HORIZ-RT | *UD2D120ACV5 | 23,600 | $1,180 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922995 | TRANE | 4TWL9024A1 | 4TXFH024CZ3 | *UHMB060ACV3 | 13,500 | $675 |
| No | 206918554 | TRANE | 4TWL9036A1 | TEM6A0C42H41+TDR+RP | | 22,400 | $1,120 |
| No | 201922993 | TRANE | 4TWL9024A1 | 4TXCC007DS3 | *DHMC100ACV4 | 13,800 | $690 |
| No | 201921871 | TRANE | 4TWL9036A1 | 4TXFH036CZ3 | *UD2D120ACV5 | 22,600 | $1,130 |
| No | 206910653 | TRANE | 4TWL9036A1 | 4PX*CU36BS3 | S9V2C100U5PSBC+RP | 22,800 | $1,140 |
| No | 201921691 | TRANE | 4TWL9036A1 | 4PX*CD48BS3+HORIZ-RT | S9V2C100U4PSB+RP | 23,600 | $1,180 |
| No | 206910641 | TRANE | 4TWL9024A1 | 4PX*BD36BS3+HORIZ-RT | S9V2B060U4PSBC+RP | 13,200 | $660 |
| No | 201923105 | TRANE | 4TWL9024A1 | 4PX*BD42BS3+HORIZ-RT | S9V2B080U3PSB+RP | 13,100 | $655 |
| No | 201923104 | TRANE | 4TWL9024A1 | 4PX*BD42BS3+HORIZ-RT | S9V2B040U3PSB+RP | 13,200 | $660 |
| No | 201923096 | TRANE | 4TWL9024A1 | 4PX*BD42BS3 | S9V2B040D3PSB+RP | 13,200 | $660 |
| No | 201923152 | TRANE | 4TWL9024A1 | 4TXFH036CZ3 | *UHMB080ACV3 | 13,400 | $670 |
| No | 201923100 | TRANE | 4TWL9024A1 | 4PX*BD42BS3 | S9V2B080D3PSB+RP | 13,100 | $655 |
| No | 206852869 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | S9V2B060U3VSAB+RP | 23,000 | $1,150 |
| No | 201921694 | TRANE | 4TWL9036A1 | 4PX*CD48BS3+HORIZ-RT | *UD2C100ACV5 | 23,600 | $1,180 |
| No | 201922958 | TRANE | 4TWL9024A1 | 4PX*CD60BS3 | *DHMC100ACV4 | 13,800 | $690 |
| No | 201921876 | TRANE | 4TWL9036A1 | 4TXFH036CZ3 | *UHMD120ACV5 | 23,200 | $1,160 |
| No | 201923098 | TRANE | 4TWL9024A1 | 4PX*BD42BS3 | *DD2B060ACV3 | 13,200 | $660 |
| No | 201921835 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | S9V2B080U4PSB+RP | 23,000 | $1,150 |
| No | 201921703 | TRANE | 4TWL9036A1 | 4PX*CU36BS3 | S9V2B080U4PSB+RP | 23,000 | $1,150 |
| No | 201921688 | TRANE | 4TWL9036A1 | 4PX*CD48BS3 | S9V2B060U3PSB+RP | 23,800 | $1,190 |
| No | 201921685 | TRANE | 4TWL9036A1 | 4PX*CD48BS3 | S9V2B040D3PSB+RP | 23,800 | $1,190 |
| No | 201921692 | TRANE | 4TWL9036A1 | 4PX*CD48BS3+HORIZ-RT | S9V2B040U3PSB+RP | 23,800 | $1,190 |
| No | 201922955 | TRANE | 4TWL9024A1 | 4PX*CD36BS3 | *DHMC100ACV4 | 14,100 | $705 |
| No | 201921872 | TRANE | 4TWL9036A1 | 4TXFH036CZ3 | *UD2D140ACV5 | 22,600 | $1,130 |
| No | 201921775 | TRANE | 4TWL9036A1 | 4PX*DD48BS3 | *DHMD120BCV5 | 23,600 | $1,180 |
| No | 201921777 | TRANE | 4TWL9036A1 | 4PX*DD48BS3+HORIZ-RT | *UD2D140ACV5 | 23,600 | $1,180 |
| No | 201921854 | TRANE | 4TWL9036A1 | 4TXCC009DS3 | *DD2C100ACV5 | 22,000 | $1,100 |
| No | 201921827 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | S9V2B040U3PSB+RP | 23,000 | $1,150 |
| No | 201921824 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | S9V2B060U3PSB+RP | 23,000 | $1,150 |
| No | 201921707 | TRANE | 4TWL9036A1 | 4PX*CU36BS3 | S9V2B060U3PSB+RP | 23,000 | $1,150 |
| No | 201921706 | TRANE | 4TWL9036A1 | 4PX*CU36BS3 | S9V2B040U3PSB+RP | 23,000 | $1,150 |
| No | 201921690 | TRANE | 4TWL9036A1 | 4PX*CD48BS3+HORIZ-RT | S9V2B080U4PSB+RP | 23,800 | $1,190 |
| No | 201921684 | TRANE | 4TWL9036A1 | 4PX*CD48BS3 | S9V2B080D3PSB+RP | 23,800 | $1,190 |
| No | 201921689 | TRANE | 4TWL9036A1 | 4PX*CD48BS3+HORIZ-RT | S9V2B080U3PSB+RP | 23,800 | $1,190 |
| No | 201921687 | TRANE | 4TWL9036A1 | 4PX*CD48BS3 | S9V2B080D4PSB+RP | 23,800 | $1,190 |
| No | 202919211 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | S9V2B080U3PSB+RP | 23,000 | $1,150 |
| No | 201921833 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | S9V2B060U4PSB+RP | 22,800 | $1,140 |
| No | 201921660 | TRANE | 4TWL9036A1 | 4PX*BD48BS3 | S9V2B080D3PSB+RP | 23,800 | $1,190 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201921693 | TRANE | 4TWL9036A1 | 4PX*CD48BS3+HORIZ-RT | *UD2C080ACV4 | 23,600 | $1,180 |
| No | 201921834 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | S9V2B080U3PSB+RP | 23,000 | $1,150 |
| No | 201922938 | TRANE | 4TWL9024A1 | 4PX*BD42BS3 | *DHMB060BCV3 | 13,300 | $665 |
| No | 201921704 | TRANE | 4TWL9036A1 | 4PX*CU36BS3 | S9V2B080U3PSB+RP | 23,000 | $1,150 |
| No | 201922998 | TRANE | 4TWL9024A1 | 4TXFH036CZ3 | *UHMB060ACV3 | 13,300 | $665 |
| No | 201921705 | TRANE | 4TWL9036A1 | 4PX*CU36BS3 | S9V2B060U4PSB+RP | 22,800 | $1,140 |
| No | 201921875 | TRANE | 4TWL9036A1 | 4TXFH036CZ3 | *UHMC100ACV4 | 22,600 | $1,130 |
| No | 205962238 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | P0V0B000M40SB+RP | 22,600 | $1,130 |
| No | 204780288 | TRANE | 4TWL9036A1 | 4TXFH036CZ3 | P0V0B000M40SA+RP | 22,200 | $1,110 |
| No | 201921681 | TRANE | 4TWL9036A1 | 4PX*CD48BS3 | *DD2C100ACV5 | 23,600 | $1,180 |
| No | 201921644 | TRANE | 4TWL9036A1 | 4PX*BD36BS3 | S9V2C100D4PSB+RP | 23,600 | $1,180 |
| No | 201921633 | TRANE | 4TWL9024A1 | 4PX*BU36BS3 | *UHMB060ACV3 | 13,400 | $670 |
| No | 201921695 | TRANE | 4TWL9036A1 | 4PX*CD48BS3+HORIZ-RT | *UD2B060ACV3 | 23,800 | $1,190 |
| No | 201921639 | TRANE | 4TWL9024A1 | 4TXCB004DS3 | *UHMB060ACV3 | 13,400 | $670 |
| No | 201921650 | TRANE | 4TWL9036A1 | 4PX*BD36BS3+HORIZ-RT | S9V2C100U4PSB+RP | 23,600 | $1,180 |
| No | 201921683 | TRANE | 4TWL9036A1 | 4PX*CD48BS3 | *DD2B060ACV3 | 23,600 | $1,180 |
| No | 206910652 | TRANE | 4TWL9036A1 | 4PX*CD48BS3+HORIZ-RT | S9V2C100U5PSBC+RP | 23,000 | $1,150 |
| No | 206910651 | TRANE | 4TWL9036A1 | 4PX*CD48BS3 | S9V2C100D5PSBC+RP | 23,000 | $1,150 |
| No | 201923135 | TRANE | 4TWL9024A1 | 4TXCB004DS3 | *UHMB080ACV3 | 13,500 | $675 |
| No | 201923133 | TRANE | 4TWL9024A1 | 4TXCB004DS3 | *DHMB060BCV3 | 13,100 | $655 |
| No | 204780258 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | P0V0A000M30SA+RP | 13,300 | $665 |
| No | 201923116 | TRANE | 4TWL9024A1 | 4PX*BU36BS3 | *UHMB080ACV3 | 13,500 | $675 |
| No | 206910650 | TRANE | 4TWL9036A1 | 4PX*CD42BS3 | S9V2C100D5PSBC+RP | 22,400 | $1,120 |
| No | 204780287 | TRANE | 4TWL9036A1 | 4TXFH036CZ3 | P0V0A000M30SA+RP | 22,200 | $1,110 |
| No | 201921830 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | *UD2B080ACV3 | 23,000 | $1,150 |
| No | 201921712 | TRANE | 4TWL9036A1 | 4PX*CU36BS3 | *UD2B080ACV3 | 23,000 | $1,150 |
| No | 204013220 | TRANE | 4TWL9036A1 | 4PX*BD48BS3 | S9V2B080D4PSB+RP | 23,600 | $1,180 |
| No | 206910657 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | S9V2C100U5PSBC+RP | 22,200 | $1,110 |
| No | 204780255 | TRANE | 4TWL9024A1 | 4PX*BD48BS3 | P0V0A000M30SA+RP | 13,000 | $650 |
| No | 201921665 | TRANE | 4TWL9036A1 | 4PX*CD36BS3+HORIZ-RT | S9V2B040U3PSB+RP | 23,600 | $1,180 |
| No | 204780256 | TRANE | 4TWL9024A1 | 4PX*BD48BS3+HORIZ-RT | P0V0A000M30SA+RP | 13,000 | $650 |
| No | 201921874 | TRANE | 4TWL9036A1 | 4TXFH036CZ3 | *UHMB080ACV3 | 23,200 | $1,160 |
| No | 204780260 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | P0V0A000M30SA+RP | 13,300 | $665 |
| No | 204780272 | TRANE | 4TWL9036A1 | 4PX*BD48BS3+HORIZ-RT | P0V0B000M40SA+RP | 23,400 | $1,170 |
| No | 204780270 | TRANE | 4TWL9036A1 | 4PX*BD48BS3 | P0V0B000M40SA+RP | 23,400 | $1,170 |
| No | 201922927 | TRANE | 4TWL9024A1 | 4PX*BD24BS3 | *DD2B080ACV3 | 14,300 | $715 |
| No | 201922928 | TRANE | 4TWL9024A1 | 4PX*BD24BS3+HORIZ-RT | *DD2B080ACV3 | 14,300 | $715 |
| No | 201921675 | TRANE | 4TWL9036A1 | 4PX*CD42BS3 | *DD2B060ACV3 | 23,000 | $1,150 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201921669 | TRANE | 4TWL9036A1 | 4PX*CD36BS3+HORIZ-RT | S9V2B060U3PSB+RP | 23,600 | $1,180 |
| No | 201921678 | TRANE | 4TWL9036A1 | 4PX*CD42BS3 | S9V2B080D3PSB+RP | 23,000 | $1,150 |
| No | 204433487 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | S9V2B080U3VSA+RP | 22,800 | $1,140 |
| No | 204780277 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | P0V0A000M30SA+RP | 22,600 | $1,130 |
| No | 201921672 | TRANE | 4TWL9036A1 | 4PX*CD36BS3+HORIZ-RT | S9V2C100U4PSB+RP | 23,400 | $1,170 |
| No | 205962222 | TRANE | 4TWL9024A1 | 4PX*BD48BS3 | P0V0A000M30SB+RP | 12,700 | $635 |
| No | 201923696 | TRANE | 4TWL9024A1 | TAM9A0B30V31 | | 13,000 | $650 |
| No | 206910647 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | S9V2B060U4PSBC+RP | 22,400 | $1,120 |
| No | 201921670 | TRANE | 4TWL9036A1 | 4PX*CD36BS3+HORIZ-RT | S9V2B080U3PSB+RP | 23,600 | $1,180 |
| No | 204780276 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | P0V0B000M40SA+RP | 22,400 | $1,120 |
| No | 201923142 | TRANE | 4TWL9024A1 | 4TXCC005DS3 | *DHMC100ACV4 | 13,600 | $680 |
| No | 201922975 | TRANE | 4TWL9024A1 | 4TXCB004DS3 | *DHMB080ACV3 | 13,400 | $670 |
| No | 204780275 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | P0V0A000M30SA+RP | 22,000 | $1,100 |
| No | 201921873 | TRANE | 4TWL9036A1 | 4TXFH036CZ3 | *UHMB060ACV3 | 23,200 | $1,160 |
| No | 201922941 | TRANE | 4TWL9024A1 | 4PX*BU24BS3 | S9V2B080U3PSB+RP | 14,000 | $700 |
| No | 201921671 | TRANE | 4TWL9036A1 | 4PX*CD36BS3+HORIZ-RT | S9V2B080U4PSB+RP | 23,600 | $1,180 |
| No | 201921663 | TRANE | 4TWL9036A1 | 4PX*CD36BS3 | S9V2B080D4PSB+RP | 23,600 | $1,180 |
| No | 201921655 | TRANE | 4TWL9036A1 | 4PX*BD36BS3+HORIZ-RT | S9V2B060U3PSB+RP | 23,600 | $1,180 |
| No | 206910656 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | S9V2B060U4PSBC+RP | 22,200 | $1,110 |
| No | 205962243 | TRANE | 4TWL9036A1 | 4TXCB006DS3 | P0V0A000M30SB+RP | 21,800 | $1,090 |
| No | 201921654 | TRANE | 4TWL9036A1 | 4PX*BD36BS3+HORIZ-RT | S9V2B040U3PSB+RP | 23,600 | $1,180 |
| No | 201922937 | TRANE | 4TWL9024A1 | 4PX*BD42BS3 | *DHMB080ACV3 | 13,500 | $675 |
| No | 205962239 | TRANE | 4TWL9036A1 | 4PX*BU48BS3 | P0V0A000M30SB+RP | 21,800 | $1,090 |
| No | 204780284 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | P0V0B000M40SA+RP | 22,400 | $1,120 |
| No | 201923085 | TRANE | 4TWL9024A1 | 4PX*BD24BS3 | S9V2B080D3PSB+RP | 14,200 | $710 |
| No | 205962234 | TRANE | 4TWL9036A1 | 4PX*BD48BS3+HORIZ-RT | P0V0B000M40SB+RP | 22,800 | $1,140 |
| No | 205962233 | TRANE | 4TWL9036A1 | 4PX*BD48BS3 | P0V0B000M40SB+RP | 22,800 | $1,140 |
| No | 201921680 | TRANE | 4TWL9036A1 | 4PX*CD42BS3 | S9V2B040D3PSB+RP | 22,800 | $1,140 |
| No | 201921677 | TRANE | 4TWL9036A1 | 4PX*CD42BS3 | S9V2B080D4PSB+RP | 23,000 | $1,150 |
| No | 201921656 | TRANE | 4TWL9036A1 | 4PX*BD36BS3+HORIZ-RT | S9V2B080U3PSB+RP | 23,600 | $1,180 |
| No | 206852867 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | S9V2B060U3VSAB+RP | 22,600 | $1,130 |
| No | 201921682 | TRANE | 4TWL9036A1 | 4PX*CD48BS3 | *DHMC100ACV4 | 24,400 | $1,220 |
| No | 201921627 | TRANE | 4TWL9024A1 | 4PX*BU24BS3 | *UD2B060ACV3 | 14,000 | $700 |
| No | 201921626 | TRANE | 4TWL9024A1 | 4PX*BU24BS3 | *UD2B080ACV3 | 14,000 | $700 |
| No | 201921657 | TRANE | 4TWL9036A1 | 4PX*BD36BS3+HORIZ-RT | S9V2B080U4PSB+RP | 23,600 | $1,180 |
| No | 201921679 | TRANE | 4TWL9036A1 | 4PX*CD42BS3 | S9V2B060D3PSB+RP | 22,800 | $1,140 |
| No | 201921649 | TRANE | 4TWL9036A1 | 4PX*BD36BS3+HORIZ-RT | *DD2B060ACV3 | 23,600 | $1,180 |
| No | 201921666 | TRANE | 4TWL9036A1 | 4PX*CD36BS3+HORIZ-RT | *UD2B060ACV3 | 23,600 | $1,180 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204780254 | TRANE | 4TWL9024A1 | 4PX*BD30BS3 | P0V0A000M30SA+RP | 13,300 | $665 |
| No | 205962223 | TRANE | 4TWL9024A1 | 4PX*BU30BS3 | P0V0A000M30SB+RP | 13,000 | $650 |
| No | 205962225 | TRANE | 4TWL9024A1 | 4TXCB003DS3 | P0V0A000M30SB+RP | 13,000 | $650 |
| No | 201922994 | TRANE | 4TWL9024A1 | 4TXCC009DS3 | *DHMC100ACV4 | 13,200 | $660 |
| No | 201923084 | TRANE | 4TWL9024A1 | 4PX*BD24BS3 | S9V2B040D3PSB+RP | 14,200 | $710 |
| No | 205962237 | TRANE | 4TWL9036A1 | 4PX*BU42BS3 | P0V0A000M30SB+RP | 22,000 | $1,100 |
| No | 205962221 | TRANE | 4TWL9024A1 | 4PX*BD30BS3 | P0V0A000M30SB+RP | 13,100 | $655 |
| No | 205962242 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | P0V0B000M40SB+RP | 21,600 | $1,080 |
| No | 205962236 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | P0V0B000M40SB+RP | 21,600 | $1,080 |
| No | 204780268 | TRANE | 4TWL9036A1 | 4PX*BD42BS3+HORIZ-RT | P0V0B000M40SA+RP | 22,800 | $1,140 |
| No | 204780266 | TRANE | 4TWL9036A1 | 4PX*BD42BS3 | P0V0B000M40SA+RP | 22,800 | $1,140 |
| No | 201922957 | TRANE | 4TWL9024A1 | 4PX*CD42BS3 | *DHMC100ACV4 | 13,600 | $680 |
| No | 206214516 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | *DD2B080ACV3 | 22,000 | $1,100 |
| No | 206910649 | TRANE | 4TWL9036A1 | 4PX*CD36BS3+HORIZ-RT | S9V2C100U5PSBC+RP | 23,000 | $1,150 |
| No | 206910648 | TRANE | 4TWL9036A1 | 4PX*CD36BS3 | S9V2C100D5PSBC+RP | 23,000 | $1,150 |
| No | 204780283 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | P0V0A000M30SA+RP | 22,000 | $1,100 |
| No | 204780261 | TRANE | 4TWL9036A1 | 4PX*BD36BS3 | P0V0B000M40SA+RP | 23,200 | $1,160 |
| No | 206910643 | TRANE | 4TWL9024A1 | 4PX*BU24BS3 | S9V2B060U4PSBC+RP | 13,500 | $675 |
| No | 204780264 | TRANE | 4TWL9036A1 | 4PX*BD36BS3+HORIZ-RT | P0V0B000M40SA+RP | 23,200 | $1,160 |
| No | 204780271 | TRANE | 4TWL9036A1 | 4PX*BD48BS3+HORIZ-RT | P0V0A000M30SA+RP | 22,600 | $1,130 |
| No | 205962230 | TRANE | 4TWL9036A1 | 4PX*BD42BS3 | P0V0B000M40SB+RP | 21,800 | $1,090 |
| No | 204780269 | TRANE | 4TWL9036A1 | 4PX*BD48BS3 | P0V0A000M30SA+RP | 22,600 | $1,130 |
| No | 205962241 | TRANE | 4TWL9036A1 | 4TXCB004DS3 | P0V0A000M30SB+RP | 21,200 | $1,060 |
| No | 205962235 | TRANE | 4TWL9036A1 | 4PX*BU36BS3 | P0V0A000M30SB+RP | 21,200 | $1,060 |
| No | 205962231 | TRANE | 4TWL9036A1 | 4PX*BD42BS3+HORIZ-RT | P0V0B000M40SB+RP | 21,800 | $1,090 |
| No | 206214518 | TRANE | 4TWL9036A1 | 4TXCC005DS3 | *DD2B060ACV3 | 21,600 | $1,080 |
| No | 205962232 | TRANE | 4TWL9036A1 | 4PX*BD48BS3 | P0V0A000M30SB+RP | 22,200 | $1,110 |
| No | 206912348 | TRANE | 4TWL9036A1 | 4PX*BD48BS3 | P0V0A000M30SC+RP | 22,200 | $1,110 |
| No | 204780265 | TRANE | 4TWL9036A1 | 4PX*BD42BS3 | P0V0A000M30SA+RP | 22,000 | $1,100 |
| No | 204780267 | TRANE | 4TWL9036A1 | 4PX*BD42BS3+HORIZ-RT | P0V0A000M30SA+RP | 22,000 | $1,100 |
| No | 206918611 | TRANE | 4TWL9036A1 | TEM6A0B30H21+TDR+RP | | 22,200 | $1,110 |
| No | 201921611 | TRANE | 4TWL9024A1 | 4PX*BD24BS3+HORIZ-RT | *DHMB080ACV3 | 14,300 | $715 |
| No | 201921610 | TRANE | 4TWL9024A1 | 4PX*BD24BS3 | *DHMB080ACV3 | 14,300 | $715 |
| No | 201921612 | TRANE | 4TWL9024A1 | 4PX*BD24BS3+HORIZ-RT | *DHMB060BCV3 | 14,100 | $705 |
| No | 201921609 | TRANE | 4TWL9024A1 | 4PX*BD24BS3 | *DHMB060BCV3 | 14,100 | $705 |
| No | 205962219 | TRANE | 4TWL9024A1 | 4PX*AU24BS3 | P0V0A000M30SB+RP | 13,400 | $670 |
| No | 206910646 | TRANE | 4TWL9036A1 | 4PX*BD36BS3+HORIZ-RT | S9V2B060U4PSBC+RP | 23,000 | $1,150 |
| No | 204780263 | TRANE | 4TWL9036A1 | 4PX*BD36BS3+HORIZ-RT | P0V0A000M30SA+RP | 22,600 | $1,130 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204780259 | TRANE | 4TWL9024A1 | 4TXCA002DS3 | P0V0A000M30SA+RP | 13,600 | $680 |
| No | 205962228 | TRANE | 4TWL9036A1 | 4PX*BD36BS3+HORIZ-RT | P0V0B000M40SB+RP | 22,800 | $1,140 |
| No | 205962227 | TRANE | 4TWL9036A1 | 4PX*BD36BS3 | P0V0B000M40SB+RP | 22,800 | $1,140 |
| No | 204780262 | TRANE | 4TWL9036A1 | 4PX*BD36BS3 | P0V0A000M30SA+RP | 22,400 | $1,120 |
| No | 205962229 | TRANE | 4TWL9036A1 | 4PX*BD42BS3 | P0V0A000M30SB+RP | 21,400 | $1,070 |
| No | 206912345 | TRANE | 4TWL9036A1 | 4PX*BD42BS3 | P0V0A000M30SC+RP | 21,400 | $1,070 |
| No | 204780250 | TRANE | 4TWL9024A1 | 4PX*AD24BS3 | P0V0A000M30SA+RP | 13,800 | $690 |
| No | 204780257 | TRANE | 4TWL9024A1 | 4PX*BU24BS3 | P0V0A000M30SA+RP | 13,200 | $660 |
| No | 206315456 | TRANE | 4TWL9036A1 | 4PX*CU36BS3 | *DHMB080ACV3 | 22,000 | $1,100 |
| No | 201921701 | TRANE | 4TWL9036A1 | 4PX*CU30BS3 | *UHMC100ACV4 | 24,200 | $1,210 |
| No | 201921807 | TRANE | 4TWL9036A1 | 4TXCB003DS3 | *UHMB080ACV3 | 24,400 | $1,220 |
| No | 201921661 | TRANE | 4TWL9036A1 | 4PX*BU30BS3 | *UHMB080ACV3 | 24,400 | $1,220 |
| No | 205962218 | TRANE | 4TWL9024A1 | 4PX*AD24BS3 | P0V0A000M30SB+RP | 13,500 | $675 |
| No | 205962224 | TRANE | 4TWL9024A1 | 4TXCA002DS3 | P0V0A000M30SB+RP | 13,600 | $680 |
| No | 204780253 | TRANE | 4TWL9024A1 | 4PX*BD24BS3+HORIZ-RT | P0V0A000M30SA+RP | 13,300 | $665 |
| No | 205962226 | TRANE | 4TWL9036A1 | 4PX*BD36BS3 | P0V0A000M30SB+RP | 22,200 | $1,110 |
| No | 204780252 | TRANE | 4TWL9024A1 | 4PX*BD24BS3 | P0V0A000M30SA+RP | 13,300 | $665 |
| No | 205962220 | TRANE | 4TWL9024A1 | 4PX*BD24BS3 | P0V0A000M30SB+RP | 13,100 | $655 |
| No | 207558989 | TRANE | 4TWV0X24A1 | 4TXCB004DS3 | *DHMB060BCV3 | 16,500 | $825 |
| No | 8761440 | TRANE | 4TWV8024A1 | 4TXCB004DS3 | *DHMB060BCV3 | 16,500 | $825 |
| No | 207526277 | TRANE | 4TWV8X24A1 | 4TXCB004DS3 | *DHMB060BCV3 | 16,500 | $825 |
| No | 8761401 | TRANE | 4TWV0024A1 | 4TXCB004DS3 | *DHMB060BCV3 | 16,500 | $825 |
| No | 207526342 | TRANE | 4TWV0X36A1 | TEM8A0D48V41+TDR | | 25,800 | $1,290 |
| No | 207526504 | TRANE | 4TWV0X24A1 | 4TXCB003DS3 | *UD2B060ACV3 | 17,500 | $875 |
| No | 10153700 | TRANE | 4TWV0036A1 | TEM8A0D48V41+TDR | | 25,800 | $1,290 |
| No | 207526455 | TRANE | 4TWV8X24A1 | 4TXCB004DS3 | S9V2B040U3VSA+RP | 16,800 | $840 |
| No | 207526452 | TRANE | 4TWV8X24A1 | 4PX*BU36BS3 | S9V2B040U3VSA+RP | 16,800 | $840 |
| No | 207526409 | TRANE | 4TWV0X24A1 | 4TXCB004DS3 | S9V2B040U3VSA+RP | 16,800 | $840 |
| No | 207526395 | TRANE | 4TWV8X24A1 | 4TXCB004DS3 | S9V2B040U3PSB+RP | 16,800 | $840 |
| No | 201808812 | TRANE | 4TWV8024A1 | 4TXCB004DS3 | S9V2B040U3VSA+RP | 16,800 | $840 |
| No | 207526372 | TRANE | 4TWV0X24A1 | 4TXCB004DS3 | S9V2B040U3PSB+RP | 16,800 | $840 |
| No | 201808804 | TRANE | 4TWV8024A1 | 4PX*BU36BS3 | S9V2B040U3VSA+RP | 16,800 | $840 |
| No | 10511253 | TRANE | 4TWV8024A1 | 4TXCB004DS3 | S9V2B040U3PSB+RP | 16,800 | $840 |
| No | 201808652 | TRANE | 4TWV0024A1 | 4PX*BU36BS3 | S9V2B040U3VSA+RP | 16,800 | $840 |
| No | 10511164 | TRANE | 4TWV0024A1 | 4TXCB004DS3 | S9V2B040U3PSB+RP | 16,800 | $840 |
| No | 10511156 | TRANE | 4TWV0024A1 | 4PX*BU36BS3 | S9V2B040U3PSB+RP | 16,800 | $840 |
| No | 207526356 | TRANE | 4TWV8X36A1 | TEM8A0D48V41+TDR | | 25,800 | $1,290 |
| No | 10153718 | TRANE | 4TWV8036A1 | TEM8A0D48V41+TDR | | 25,800 | $1,290 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201808672 | TRANE | 4TWV0024A1 | 4TXCB004DS3 | S9V2B040U3VSA+RP | 16,800 | $840 |
| No | 10511247 | TRANE | 4TWV8024A1 | 4PX*BU36BS3 | S9V2B040U3PSB+RP | 16,800 | $840 |
| No | 10093494 | TRANE | 4TWV0024A1 | TAM9A0B30V31 | | 16,800 | $840 |
| No | 207526457 | TRANE | 4TWV8X24A1 | 4TXCB004DS3 | S9V2B080U3VSA+RP | 16,800 | $840 |
| No | 207526454 | TRANE | 4TWV8X24A1 | 4PX*BU36BS3 | S9V2B080U3VSA+RP | 16,800 | $840 |
| No | 207526406 | TRANE | 4TWV0X24A1 | 4PX*BU36BS3 | S9V2B080U3VSA+RP | 16,800 | $840 |
| No | 207526408 | TRANE | 4TWV0X24A1 | 4TXCB004DS3 | S9V2B080U3VSA+RP | 16,800 | $840 |
| No | 207526394 | TRANE | 4TWV8X24A1 | 4TXCB004DS3 | S9V2B080U3PSB+RP | 16,800 | $840 |
| No | 207526393 | TRANE | 4TWV8X24A1 | 4PX*BU36BS3 | S9V2B080U3PSB+RP | 16,800 | $840 |
| No | 207526370 | TRANE | 4TWV0X24A1 | 4TXCB004DS3 | S9V2B080U3PSB+RP | 16,800 | $840 |
| No | 207526369 | TRANE | 4TWV0X24A1 | 4PX*BU36BS3 | S9V2B080U3PSB+RP | 16,800 | $840 |
| No | 201808819 | TRANE | 4TWV8024A1 | 4TXCB004DS3 | S9V2B080U3VSA+RP | 16,800 | $840 |
| No | 201808669 | TRANE | 4TWV0024A1 | 4TXCB004DS3 | S9V2B080U3VSA+RP | 16,800 | $840 |
| No | 201808809 | TRANE | 4TWV8024A1 | 4PX*BU36BS3 | S9V2B080U3VSA+RP | 16,800 | $840 |
| No | 201808661 | TRANE | 4TWV0024A1 | 4PX*BU36BS3 | S9V2B080U3VSA+RP | 16,800 | $840 |
| No | 10511249 | TRANE | 4TWV8024A1 | 4PX*BU36BS3 | S9V2B080U3PSB+RP | 16,800 | $840 |
| No | 10511250 | TRANE | 4TWV8024A1 | 4TXCB004DS3 | S9V2B080U3PSB+RP | 16,800 | $840 |
| No | 10511160 | TRANE | 4TWV0024A1 | 4TXCB004DS3 | S9V2B080U3PSB+RP | 16,800 | $840 |
| No | 10511157 | TRANE | 4TWV0024A1 | 4PX*BU36BS3 | S9V2B080U3PSB+RP | 16,800 | $840 |
| No | 10153717 | TRANE | 4TWV8036A1 | TEM8A0C48V41+TDR | | 25,400 | $1,270 |
| No | 6796596 | TRANE | 4TWV0024A1 | 4TXFH024CZ3 | *DD2B060ACV3 | 16,600 | $830 |
| No | 10093504 | TRANE | 4TWV8036A1 | TAM9A0B30V31 | | 26,600 | $1,330 |
| No | 202325437 | TRANE | 4TWV0024A1 | 4TXCB003DS3 | *UD2B060ACV3 | 17,500 | $875 |
| No | 207526355 | TRANE | 4TWV8X36A1 | TEM8A0C48V41+TDR | | 25,400 | $1,270 |
| No | 207558968 | TRANE | 4TWV0X36A1 | 4PX*CD48BS3 | *DHMC100ACV4 | 27,600 | $1,380 |
| No | 10153714 | TRANE | 4TWV8036A1 | TEM8A0C36V31+TDR | | 25,600 | $1,280 |
| No | 10153696 | TRANE | 4TWV0036A1 | TEM8A0C36V31+TDR | | 25,600 | $1,280 |
| No | 207526453 | TRANE | 4TWV8X24A1 | 4PX*BU36BS3 | S9V2B060U3VSA+RP | 16,700 | $835 |
| No | 207526456 | TRANE | 4TWV8X24A1 | 4TXCB004DS3 | S9V2B060U3VSA+RP | 16,700 | $835 |
| No | 207526407 | TRANE | 4TWV0X24A1 | 4TXCB004DS3 | S9V2B060U3VSA+RP | 16,700 | $835 |
| No | 201808816 | TRANE | 4TWV8024A1 | 4TXCB004DS3 | S9V2B060U3VSA+RP | 16,700 | $835 |
| No | 207526371 | TRANE | 4TWV0X24A1 | 4TXCB004DS3 | S9V2B060U3PSB+RP | 16,700 | $835 |
| No | 201808805 | TRANE | 4TWV8024A1 | 4PX*BU36BS3 | S9V2B060U3VSA+RP | 16,700 | $835 |
| No | 201808656 | TRANE | 4TWV0024A1 | 4PX*BU36BS3 | S9V2B060U3VSA+RP | 16,700 | $835 |
| No | 10511255 | TRANE | 4TWV8024A1 | 4TXCB004DS3 | S9V2B060U3PSB+RP | 16,700 | $835 |
| No | 10511161 | TRANE | 4TWV0024A1 | 4TXCB004DS3 | S9V2B060U3PSB+RP | 16,700 | $835 |
| No | 10511158 | TRANE | 4TWV0024A1 | 4PX*BU36BS3 | S9V2B060U3PSB+RP | 16,700 | $835 |
| No | 10153699 | TRANE | 4TWV0036A1 | TEM8A0C48V41+TDR | | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201808666 | TRANE | 4TWV0024A1 | 4TXCB004DS3 | S9V2B060U3VSA+RP | 16,700 | $835 |
| No | 207526341 | TRANE | 4TWV0X36A1 | TEM8A0C48V41+TDR | | 25,200 | $1,260 |
| No | 10511248 | TRANE | 4TWV8024A1 | 4PX*BU36BS3 | S9V2B060U3PSB+RP | 16,700 | $835 |
| No | 10511203 | TRANE | 4TWV0036A1 | 4TXCC007DS3 | S9V2C100U4PSB+RP | 26,400 | $1,320 |
| No | 10511186 | TRANE | 4TWV0036A1 | 4PX*CU48BS3 | S9V2C100U4PSB+RP | 26,400 | $1,320 |
| No | 207526432 | TRANE | 4TWV0X36A1 | 4TXCC007DS3 | S9V2C100U4VSA+RP | 26,400 | $1,320 |
| No | 201808900 | TRANE | 4TWV8037A1 | 4PX*CU48BS3 | S9V2C100U4VSA+RP | 26,400 | $1,320 |
| No | 201808921 | TRANE | 4TWV8037A1 | 4TXCC007DS3 | S9V2C100U4VSA+RP | 26,400 | $1,320 |
| No | 201808741 | TRANE | 4TWV0036A1 | 4TXCC007DS3 | S9V2C100U4VSA+RP | 26,400 | $1,320 |
| No | 10511339 | TRANE | 4TWV8037A1 | 4TXCC007DS3 | S9V2C100U4PSB+RP | 26,400 | $1,320 |
| No | 201808713 | TRANE | 4TWV0036A1 | 4PX*CU48BS3 | S9V2C100U4VSA+RP | 26,400 | $1,320 |
| No | 10511322 | TRANE | 4TWV8037A1 | 4PX*CU48BS3 | S9V2C100U4PSB+RP | 26,400 | $1,320 |
| No | 207526603 | TRANE | 4TWV8X24A1 | 4TXFH024CZ3 | P0V0A000M30SA+RP | 16,600 | $830 |
| No | 204780390 | TRANE | 4TWV8024A1 | 4TXFH024CZ3 | P0V0A000M30SA+RP | 16,600 | $830 |
| No | 10153694 | TRANE | 4TWV0024A1 | TEM8A0B30V31+TDR | | 17,000 | $850 |
| No | 206910676 | TRANE | 4TWV8036A1 | 4PX*CU48BS3 | S9V2C100U5PSBC+RP | 25,600 | $1,280 |
| No | 207526788 | TRANE | 4TWV8X36A1 | 4PX*CU48BS3 | S9V2C100U5PSBC+RP | 25,600 | $1,280 |
| No | 10511254 | TRANE | 4TWV8024A1 | 4TXCB004DS3 | S9V2B040D3PSB+RP | 16,700 | $835 |
| No | 202365954 | TRANE | 4TWV8036A1 | 4PX*CU48BS3 | S9V2C100D4PSB+RP | 25,600 | $1,280 |
| No | 207526560 | TRANE | 4TWV0X24A1 | 4TXFH024CZ3 | P0V0A000M30SA+RP | 16,600 | $830 |
| No | 207526505 | TRANE | 4TWV0X24A1 | 4PX*BU36BS3 | *DHMB060BCV3 | 16,800 | $840 |
| No | 204780347 | TRANE | 4TWV0024A1 | 4TXFH024CZ3 | P0V0A000M30SA+RP | 16,600 | $830 |
| No | 10511159 | TRANE | 4TWV0024A1 | 4TXCB004DS3 | S9V2B040D3PSB+RP | 16,700 | $835 |
| No | 202365939 | TRANE | 4TWV0024A1 | 4PX*BU36BS3 | *DHMB060BCV3 | 16,800 | $840 |
| No | 9122738 | TRANE | 4TWV0024A1 | 4PX*BU42BS3 | *UHMB060ACV3 | 17,300 | $865 |
| No | 207559045 | TRANE | 4TWV0X24A1 | 4PX*BU42BS3 | *UHMB060ACV3 | 17,300 | $865 |
| No | 207559024 | TRANE | 4TWV0X36A1 | 4TXFH036CZ3 | *DD2B060ACV3 | 26,400 | $1,320 |
| No | 10093507 | TRANE | 4TWV8037A1 | TAM9A0B30V31 | | 26,200 | $1,310 |
| No | 10093495 | TRANE | 4TWV0036A1 | TAM9A0B30V31 | | 26,200 | $1,310 |
| No | 8939381 | TRANE | 4TWV0036A1 | 4TXFH036CZ3 | *DD2B060ACV3 | 26,400 | $1,320 |
| No | 207526465 | TRANE | 4TWV8X36A1 | 4PX*BU48BS3 | S9V2B080U3VSA+RP | 26,600 | $1,330 |
| No | 207526400 | TRANE | 4TWV8X36A1 | 4TXCB006DS3 | S9V2B080U3PSB+RP | 26,600 | $1,330 |
| No | 207526397 | TRANE | 4TWV8X36A1 | 4PX*BU48BS3 | S9V2B080U3PSB+RP | 26,600 | $1,330 |
| No | 201808868 | TRANE | 4TWV8036A1 | 4TXCB006DS3 | S9V2B080U3VSA+RP | 26,600 | $1,330 |
| No | 10511294 | TRANE | 4TWV8036A1 | 4TXCB006DS3 | S9V2B080U3PSB+RP | 26,600 | $1,330 |
| No | 8761441 | TRANE | 4TWV8024A1 | 4TXCB004DS3 | *UHMB060ACV3 | 16,900 | $845 |
| No | 10511271 | TRANE | 4TWV8036A1 | 4PX*BU48BS3 | S9V2B080U3PSB+RP | 26,600 | $1,330 |
| No | 207526474 | TRANE | 4TWV8X36A1 | 4TXCB006DS3 | S9V2B080U3VSA+RP | 26,600 | $1,330 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201808842 | TRANE | 4TWV8036A1 | 4PX*BU48BS3 | S9V2B080U3VSA+RP | 26,600 | $1,330 |
| No | 10153721 | TRANE | 4TWV8037A1 | TEM8A0C36V31+TDR | | 25,600 | $1,280 |
| No | 10511292 | TRANE | 4TWV8036A1 | 4TXCB006DS3 | S9V2B060U4PSB+RP | 26,400 | $1,320 |
| No | 10511270 | TRANE | 4TWV8036A1 | 4PX*BU48BS3 | S9V2B060U4PSB+RP | 26,400 | $1,320 |
| No | 207526278 | TRANE | 4TWV8X24A1 | 4TXCB004DS3 | *UHMB060ACV3 | 16,900 | $845 |
| No | 207526478 | TRANE | 4TWV8X36A1 | 4TXCD008DS3 | S9V2C100D4VSA+RP | 25,200 | $1,260 |
| No | 207526402 | TRANE | 4TWV8X36A1 | 4TXCD008DS3 | S9V2C100D4PSB+RP | 25,200 | $1,260 |
| No | 201808876 | TRANE | 4TWV8036A1 | 4TXCD008DS3 | S9V2C100D4VSA+RP | 25,200 | $1,260 |
| No | 10511300 | TRANE | 4TWV8036A1 | 4TXCD008DS3 | S9V2C100D4PSB+RP | 25,200 | $1,260 |
| No | 207526477 | TRANE | 4TWV8X36A1 | 4TXCC007DS3 | S9V2C100U4VSA+RP | 26,200 | $1,310 |
| No | 201808874 | TRANE | 4TWV8036A1 | 4TXCC007DS3 | S9V2C100U4VSA+RP | 26,200 | $1,310 |
| No | 201808854 | TRANE | 4TWV8036A1 | 4PX*CU48BS3 | S9V2C100U4VSA+RP | 26,200 | $1,310 |
| No | 10511298 | TRANE | 4TWV8036A1 | 4TXCC007DS3 | S9V2C100U4PSB+RP | 26,200 | $1,310 |
| No | 10511277 | TRANE | 4TWV8036A1 | 4PX*CU48BS3 | S9V2C100U4PSB+RP | 26,200 | $1,310 |
| No | 8759475 | TRANE | 4TWV8036A1 | 4PX*CU48BS3 | *UHMC100ACV4 | 26,600 | $1,330 |
| No | 10511246 | TRANE | 4TWV8024A1 | 4PX*BD36BS3 | S9V2B040D3PSB+RP | 17,300 | $865 |
| No | 8759402 | TRANE | 4TWV0036A1 | 4PX*BU48BS3 | *UD2B060ACV3 | 26,800 | $1,340 |
| No | 10511296 | TRANE | 4TWV8036A1 | 4TXCC005DS3 | S9V2C100U4PSB+RP | 26,000 | $1,300 |
| No | 207526571 | TRANE | 4TWV0X36A1 | 4PX*BU42BS3 | P0V0B000M40SA+RP | 26,200 | $1,310 |
| No | 207526401 | TRANE | 4TWV8X36A1 | 4TXCB006DS3 | S9V2B080D3PSB+RP | 25,400 | $1,270 |
| No | 10511295 | TRANE | 4TWV8036A1 | 4TXCB006DS3 | S9V2B080D3PSB+RP | 25,400 | $1,270 |
| No | 207558964 | TRANE | 4TWV0X36A1 | 4PX*BU48BS3 | *UHMB080ACV3 | 27,000 | $1,350 |
| No | 8759499 | TRANE | 4TWV8037A1 | 4PX*BU48BS3 | *UHMB080ACV3 | 27,000 | $1,350 |
| No | 8759404 | TRANE | 4TWV0036A1 | 4PX*BU48BS3 | *UHMB080ACV3 | 27,000 | $1,350 |
| No | 207526518 | TRANE | 4TWV8X36A1 | 4PX*CU36BS3 | S9V2C100D4PSB+RP | 25,400 | $1,270 |
| No | 202365952 | TRANE | 4TWV8036A1 | 4PX*CU36BS3 | S9V2C100D4PSB+RP | 25,400 | $1,270 |
| No | 207558934 | TRANE | 4TWV0X36A1 | 4TXFH036CZ3 | *UD2C080ACV4 | 25,600 | $1,280 |
| No | 6796604 | TRANE | 4TWV0036A1 | 4TXFH036CZ3 | *UD2C080ACV4 | 25,600 | $1,280 |
| No | 202365950 | TRANE | 4TWV8036A1 | 4PX*BU48BS3 | S9V2B080D3PSB+RP | 25,600 | $1,280 |
| No | 10153716 | TRANE | 4TWV8036A1 | TEM8A0C42V41+TDR | | 25,600 | $1,280 |
| No | 207526615 | TRANE | 4TWV8X36A1 | 4PX*BU42BS3 | P0V0B000M40SA+RP | 26,000 | $1,300 |
| No | 204780402 | TRANE | 4TWV8036A1 | 4PX*BU42BS3 | P0V0B000M40SA+RP | 26,000 | $1,300 |
| No | 207526789 | TRANE | 4TWV8X36A1 | 4TXCC005DS3 | S9V2C100U5PSBC+RP | 25,400 | $1,270 |
| No | 207526787 | TRANE | 4TWV8X36A1 | 4PX*CU36BS3 | S9V2C100U5PSBC+RP | 25,400 | $1,270 |
| No | 206910675 | TRANE | 4TWV8036A1 | 4PX*CU36BS3 | S9V2C100U5PSBC+RP | 25,400 | $1,270 |
| No | 207526247 | TRANE | 4TWV8X36A1 | 4PX*BU48BS3 | *UD2B060ACV3 | 26,600 | $1,330 |
| No | 8759456 | TRANE | 4TWV8036A1 | 4PX*BU48BS3 | *UD2B060ACV3 | 26,600 | $1,330 |
| No | 8759453 | TRANE | 4TWV8036A1 | 4PX*BU48BS3 | *UHMB080ACV3 | 26,600 | $1,330 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206910677 | TRANE | 4TWV8036A1 | 4TXCC005DS3 | S9V2C100U5PSBC+RP | 25,400 | $1,270 |
| No | 207526245 | TRANE | 4TWV8X36A1 | 4PX*BU48BS3 | *UHMB080ACV3 | 26,600 | $1,330 |
| No | 207526322 | TRANE | 4TWV8X24A1 | 4PX*BU42BS3 | *UHMB060ACV3 | 17,000 | $850 |
| No | 202492153 | TRANE | 4TWV8037A1 | 4PX*CU48BS3 | S9V2C100D4PSB+RP | 25,200 | $1,260 |
| No | 9122739 | TRANE | 4TWV8024A1 | 4PX*BU42BS3 | *UHMB060ACV3 | 17,000 | $850 |
| No | 202492137 | TRANE | 4TWV0036A1 | 4PX*CU48BS3 | S9V2C100D4PSB+RP | 25,200 | $1,260 |
| No | 8759416 | TRANE | 4TWV0036A1 | 4PX*CU48BS3 | *UD2C100ACV5 | 26,600 | $1,330 |
| No | 201808719 | TRANE | 4TWV0036A1 | 4TXCB004DS3 | S9V2B060U3VSA+RP | 26,200 | $1,310 |
| No | 201808685 | TRANE | 4TWV0036A1 | 4PX*BU36BS3 | S9V2B060U3VSA+RP | 26,200 | $1,310 |
| No | 201808902 | TRANE | 4TWV8037A1 | 4TXCB004DS3 | S9V2B060U3VSA+RP | 26,200 | $1,310 |
| No | 10511330 | TRANE | 4TWV8037A1 | 4TXCB004DS3 | S9V2B060U3PSB+RP | 26,200 | $1,310 |
| No | 207559021 | TRANE | 4TWV0X24A1 | 4PX*BD36BS3+HORIZ-RT | *UD2B060ACV3 | 17,200 | $860 |
| No | 10511309 | TRANE | 4TWV8037A1 | 4PX*BU36BS3 | S9V2B060U3PSB+RP | 26,200 | $1,310 |
| No | 10511173 | TRANE | 4TWV0036A1 | 4PX*BU36BS3 | S9V2B080U4PSB+RP | 26,000 | $1,300 |
| No | 10511193 | TRANE | 4TWV0036A1 | 4TXCB004DS3 | S9V2B060U3PSB+RP | 26,200 | $1,310 |
| No | 8939374 | TRANE | 4TWV0024A1 | 4PX*BD36BS3+HORIZ-RT | *UD2B060ACV3 | 17,200 | $860 |
| No | 207526258 | TRANE | 4TWV8X36A1 | 4PX*CU48BS3 | *UHMC100ACV4 | 26,600 | $1,330 |
| No | 207526390 | TRANE | 4TWV8X24A1 | 4PX*BD36BS3 | S9V2B080D3PSB+RP | 17,300 | $865 |
| No | 207526391 | TRANE | 4TWV8X24A1 | 4PX*BD36BS3 | S9V2B040D3PSB+RP | 17,300 | $865 |
| No | 10511245 | TRANE | 4TWV8024A1 | 4PX*BD36BS3 | S9V2B080D3PSB+RP | 17,300 | $865 |
| No | 207526451 | TRANE | 4TWV8X24A1 | 4PX*BD36BS3 | S9V2B080D3VSA+RP | 17,300 | $865 |
| No | 207526403 | TRANE | 4TWV0X24A1 | 4PX*BD36BS3 | S9V2B080D3VSA+RP | 17,300 | $865 |
| No | 201808801 | TRANE | 4TWV8024A1 | 4PX*BD36BS3 | S9V2B080D3VSA+RP | 17,300 | $865 |
| No | 207526366 | TRANE | 4TWV0X24A1 | 4PX*BD36BS3 | S9V2B080D3PSB+RP | 17,300 | $865 |
| No | 201808647 | TRANE | 4TWV0024A1 | 4PX*BD36BS3 | S9V2B080D3VSA+RP | 17,300 | $865 |
| No | 10511154 | TRANE | 4TWV0024A1 | 4PX*BD36BS3 | S9V2B080D3PSB+RP | 17,300 | $865 |
| No | 207526365 | TRANE | 4TWV0X24A1 | 4PX*BD36BS3 | S9V2B040D3PSB+RP | 17,300 | $865 |
| No | 10511153 | TRANE | 4TWV0024A1 | 4PX*BD36BS3 | S9V2B040D3PSB+RP | 17,300 | $865 |
| No | 6796624 | TRANE | 4TWV8024A1 | 4TXFH024CZ3 | *DHMB060BCV3 | 16,700 | $835 |
| No | 207526776 | TRANE | 4TWV0X36A1 | 4PX*CU48BS3 | S9V2C100U5PSBC+RP | 25,600 | $1,280 |
| No | 206910679 | TRANE | 4TWV8037A1 | 4PX*CU48BS3 | S9V2C100U5PSBC+RP | 25,600 | $1,280 |
| No | 206910664 | TRANE | 4TWV0036A1 | 4PX*CU48BS3 | S9V2C100U5PSBC+RP | 25,600 | $1,280 |
| No | 10511251 | TRANE | 4TWV8024A1 | 4TXCB004DS3 | S9V2B060D3PSB+RP | 16,500 | $825 |
| No | 10511163 | TRANE | 4TWV0024A1 | 4TXCB004DS3 | S9V2B060D3PSB+RP | 16,500 | $825 |
| No | 207526429 | TRANE | 4TWV0X36A1 | 4TXCB006DS3 | S9V2B080U3VSA+RP | 26,600 | $1,330 |
| No | 207526416 | TRANE | 4TWV0X36A1 | 4PX*BU48BS3 | S9V2B080U3VSA+RP | 26,600 | $1,330 |
| No | 201808914 | TRANE | 4TWV8037A1 | 4TXCB006DS3 | S9V2B080U3VSA+RP | 26,600 | $1,330 |
| No | 207526382 | TRANE | 4TWV0X36A1 | 4PX*BU48BS3 | S9V2B080U3PSB+RP | 26,600 | $1,330 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201808888 | TRANE | 4TWV8037A1 | 4PX*BU48BS3 | S9V2B080U3VSA+RP | 26,600 | $1,330 |
| No | 207526387 | TRANE | 4TWV0X36A1 | 4TXCB006DS3 | S9V2B080U3PSB+RP | 26,600 | $1,330 |
| No | 201808734 | TRANE | 4TWV0036A1 | 4TXCB006DS3 | S9V2B080U3VSA+RP | 26,600 | $1,330 |
| No | 201808695 | TRANE | 4TWV0036A1 | 4PX*BU48BS3 | S9V2B080U3VSA+RP | 26,600 | $1,330 |
| No | 10511318 | TRANE | 4TWV8037A1 | 4PX*BU48BS3 | S9V2B080U3PSB+RP | 26,600 | $1,330 |
| No | 10511180 | TRANE | 4TWV0036A1 | 4PX*BU48BS3 | S9V2B080U3PSB+RP | 26,600 | $1,330 |
| No | 10511196 | TRANE | 4TWV0036A1 | 4TXCB006DS3 | S9V2B080U3PSB+RP | 26,600 | $1,330 |
| No | 8759457 | TRANE | 4TWV8036A1 | 4PX*BU48BS3 | *UHMB060ACV3 | 26,400 | $1,320 |
| No | 207526248 | TRANE | 4TWV8X36A1 | 4PX*BU48BS3 | *UHMB060ACV3 | 26,400 | $1,320 |
| No | 207559020 | TRANE | 4TWV0X24A1 | 4PX*BD36BS3 | *DHMB060BCV3 | 17,400 | $870 |
| No | 10511334 | TRANE | 4TWV8037A1 | 4TXCB006DS3 | S9V2B080U3PSB+RP | 26,600 | $1,330 |
| No | 8759474 | TRANE | 4TWV8036A1 | 4PX*CU48BS3 | *UD2C080ACV4 | 26,400 | $1,320 |
| No | 8935201 | TRANE | 4TWV0024A1 | 4PX*BD36BS3 | *DHMB060BCV3 | 17,400 | $870 |
| No | 207526475 | TRANE | 4TWV8X36A1 | 4TXCB006DS3 | S9V2B040U3VSA+RP | 26,400 | $1,320 |
| No | 207526464 | TRANE | 4TWV8X36A1 | 4PX*BU48BS3 | S9V2B040U3VSA+RP | 26,400 | $1,320 |
| No | 201808870 | TRANE | 4TWV8036A1 | 4TXCB006DS3 | S9V2B040U3VSA+RP | 26,400 | $1,320 |
| No | 201808839 | TRANE | 4TWV8036A1 | 4PX*BU48BS3 | S9V2B040U3VSA+RP | 26,400 | $1,320 |
| No | 10511290 | TRANE | 4TWV8036A1 | 4TXCB006DS3 | S9V2B040U3PSB+RP | 26,400 | $1,320 |
| No | 10511288 | TRANE | 4TWV8036A1 | 4TXCB006DS3 | S9V2B080U4PSB+RP | 26,400 | $1,320 |
| No | 10511273 | TRANE | 4TWV8036A1 | 4PX*BU48BS3 | S9V2B040U3PSB+RP | 26,400 | $1,320 |
| No | 10511272 | TRANE | 4TWV8036A1 | 4PX*BU48BS3 | S9V2B080U4PSB+RP | 26,400 | $1,320 |
| No | 10511332 | TRANE | 4TWV8037A1 | 4TXCB006DS3 | S9V2B080U4PSB+RP | 26,600 | $1,330 |
| No | 10511315 | TRANE | 4TWV8037A1 | 4PX*BU48BS3 | S9V2B080U4PSB+RP | 26,600 | $1,330 |
| No | 10511200 | TRANE | 4TWV0036A1 | 4TXCB006DS3 | S9V2B080U4PSB+RP | 26,600 | $1,330 |
| No | 10511181 | TRANE | 4TWV0036A1 | 4PX*BU48BS3 | S9V2B080U4PSB+RP | 26,600 | $1,330 |
| No | 202365953 | TRANE | 4TWV8036A1 | 4PX*CU48BS3 | *DD2C100ACV5 | 25,800 | $1,290 |
| No | 10511198 | TRANE | 4TWV0036A1 | 4TXCB006DS3 | S9V2B060U4PSB+RP | 26,400 | $1,320 |
| No | 10511316 | TRANE | 4TWV8037A1 | 4PX*BU48BS3 | S9V2B060U4PSB+RP | 26,400 | $1,320 |
| No | 10511182 | TRANE | 4TWV0036A1 | 4PX*BU48BS3 | S9V2B060U4PSB+RP | 26,400 | $1,320 |
| No | 10511335 | TRANE | 4TWV8037A1 | 4TXCB006DS3 | S9V2B060U4PSB+RP | 26,400 | $1,320 |
| No | 207526463 | TRANE | 4TWV8X36A1 | 4PX*BU48BS3 | S9V2B060U3VSA+RP | 26,400 | $1,320 |
| No | 201808865 | TRANE | 4TWV8036A1 | 4TXCB006DS3 | S9V2B060U3VSA+RP | 26,400 | $1,320 |
| No | 10511289 | TRANE | 4TWV8036A1 | 4TXCB006DS3 | S9V2B060U3PSB+RP | 26,400 | $1,320 |
| No | 10511269 | TRANE | 4TWV8036A1 | 4PX*BU48BS3 | S9V2B060U3PSB+RP | 26,400 | $1,320 |
| No | 207526473 | TRANE | 4TWV8X36A1 | 4TXCB006DS3 | S9V2B060U3VSA+RP | 26,400 | $1,320 |
| No | 8759415 | TRANE | 4TWV0036A1 | 4PX*CU48BS3 | *UD2C080ACV4 | 26,600 | $1,330 |
| No | 8759509 | TRANE | 4TWV8037A1 | 4PX*CU48BS3 | *UD2C080ACV4 | 26,600 | $1,330 |
| No | 207526880 | TRANE | 4TWV0X36A1 | TEM6A0C36H31+TDR+RP | | 25,000 | $1,250 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201808836 | TRANE | 4TWV8036A1 | 4PX*BU48BS3 | S9V2B060U3VSA+RP | 26,400 | $1,320 |
| No | 206918569 | TRANE | 4TWV8037A1 | TEM6A0C36H31+TDR+RP | | 25,000 | $1,250 |
| No | 206918561 | TRANE | 4TWV0036A1 | TEM6A0C36H31+TDR+RP | | 25,000 | $1,250 |
| No | 207526389 | TRANE | 4TWV8X24A1 | 4PX*BD36BS3 | S9V2B060D3PSB+RP | 17,200 | $860 |
| No | 10511244 | TRANE | 4TWV8024A1 | 4PX*BD36BS3 | S9V2B060D3PSB+RP | 17,200 | $860 |
| No | 207526367 | TRANE | 4TWV0X24A1 | 4PX*BD36BS3 | S9V2B060D3PSB+RP | 17,200 | $860 |
| No | 10511155 | TRANE | 4TWV0024A1 | 4PX*BD36BS3 | S9V2B060D3PSB+RP | 17,200 | $860 |
| No | 8759418 | TRANE | 4TWV0036A1 | 4PX*CU48BS3 | *UHMC100ACV4 | 26,800 | $1,340 |
| No | 8759478 | TRANE | 4TWV8036A1 | 4PX*CU48BS3 | *UD2C100ACV5 | 26,200 | $1,310 |
| No | 207558975 | TRANE | 4TWV0X36A1 | 4PX*CU48BS3 | *UHMC100ACV4 | 26,800 | $1,340 |
| No | 207526458 | TRANE | 4TWV8X24A1 | 4TXCB004DS3 | S9V2B080D3VSA+RP | 16,500 | $825 |
| No | 206223111 | TRANE | 4TWV8X36A1 | TAMXA0B30V3PA | | 26,000 | $1,300 |
| No | 207526410 | TRANE | 4TWV0X24A1 | 4TXCB004DS3 | S9V2B080D3VSA+RP | 16,500 | $825 |
| No | 201808822 | TRANE | 4TWV8024A1 | 4TXCB004DS3 | S9V2B080D3VSA+RP | 16,500 | $825 |
| No | 10511162 | TRANE | 4TWV0024A1 | 4TXCB004DS3 | S9V2B080D3PSB+RP | 16,500 | $825 |
| No | 10511252 | TRANE | 4TWV8024A1 | 4TXCB004DS3 | S9V2B080D3PSB+RP | 16,500 | $825 |
| No | 201808675 | TRANE | 4TWV0024A1 | 4TXCB004DS3 | S9V2B080D3VSA+RP | 16,500 | $825 |
| No | 207526575 | TRANE | 4TWV0X36A1 | 4TXCB004DS3 | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 8759408 | TRANE | 4TWV0036A1 | 4PX*CD48BS3 | *DHMC100ACV4 | 27,600 | $1,380 |
| No | 207526886 | TRANE | 4TWV8X36A1 | TEM6A0C36H31+TDR+RP | | 24,800 | $1,240 |
| No | 8759454 | TRANE | 4TWV8036A1 | 4PX*BU48BS3 | *UD2B080ACV3 | 26,600 | $1,330 |
| No | 204780362 | TRANE | 4TWV0036A1 | 4TXCB004DS3 | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 207526246 | TRANE | 4TWV8X36A1 | 4PX*BU48BS3 | *UD2B080ACV3 | 26,600 | $1,330 |
| No | 206918567 | TRANE | 4TWV8036A1 | TEM6A0C36H31+TDR+RP | | 24,800 | $1,240 |
| No | 207526895 | TRANE | 4TWV8X24A1 | TEM6A0B30H21+TDR+RP | | 16,600 | $830 |
| No | 206918615 | TRANE | 4TWV8024A1 | TEM6A0B30H21+TDR+RP | | 16,600 | $830 |
| No | 207526427 | TRANE | 4TWV0X36A1 | 4TXCB006DS3 | S9V2B060U3VSA+RP | 26,400 | $1,320 |
| No | 207526428 | TRANE | 4TWV0X36A1 | 4TXCB006DS3 | S9V2B040U3VSA+RP | 26,400 | $1,320 |
| No | 207526418 | TRANE | 4TWV0X36A1 | 4PX*BU48BS3 | S9V2B040U3VSA+RP | 26,400 | $1,320 |
| No | 207526417 | TRANE | 4TWV0X36A1 | 4PX*BU48BS3 | S9V2B060U3VSA+RP | 26,400 | $1,320 |
| No | 201808912 | TRANE | 4TWV8037A1 | 4TXCB006DS3 | S9V2B060U3VSA+RP | 26,400 | $1,320 |
| No | 201808910 | TRANE | 4TWV8037A1 | 4TXCB006DS3 | S9V2B040U3VSA+RP | 26,400 | $1,320 |
| No | 201808890 | TRANE | 4TWV8037A1 | 4PX*BU48BS3 | S9V2B060U3VSA+RP | 26,400 | $1,320 |
| No | 201808892 | TRANE | 4TWV8037A1 | 4PX*BU48BS3 | S9V2B040U3VSA+RP | 26,400 | $1,320 |
| No | 201808729 | TRANE | 4TWV0036A1 | 4TXCB006DS3 | S9V2B040U3VSA+RP | 26,400 | $1,320 |
| No | 201808728 | TRANE | 4TWV0036A1 | 4TXCB006DS3 | S9V2B060U3VSA+RP | 26,400 | $1,320 |
| No | 201808701 | TRANE | 4TWV0036A1 | 4PX*BU48BS3 | S9V2B040U3VSA+RP | 26,400 | $1,320 |
| No | 10511333 | TRANE | 4TWV8037A1 | 4TXCB006DS3 | S9V2B040U3PSB+RP | 26,400 | $1,320 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10511317 | TRANE | 4TWV8037A1 | 4PX*BU48BS3 | S9V2B060U3PSB+RP | 26,400 | $1,320 |
| No | 10511336 | TRANE | 4TWV8037A1 | 4TXCB006DS3 | S9V2B060U3PSB+RP | 26,400 | $1,320 |
| No | 10511314 | TRANE | 4TWV8037A1 | 4PX*BU48BS3 | S9V2B040U3PSB+RP | 26,400 | $1,320 |
| No | 10511199 | TRANE | 4TWV0036A1 | 4TXCB006DS3 | S9V2B060U3PSB+RP | 26,400 | $1,320 |
| No | 10511197 | TRANE | 4TWV0036A1 | 4TXCB006DS3 | S9V2B040U3PSB+RP | 26,400 | $1,320 |
| No | 10511179 | TRANE | 4TWV0036A1 | 4PX*BU48BS3 | S9V2B040U3PSB+RP | 26,400 | $1,320 |
| No | 201808697 | TRANE | 4TWV0036A1 | 4PX*BU48BS3 | S9V2B060U3VSA+RP | 26,400 | $1,320 |
| No | 10511178 | TRANE | 4TWV0036A1 | 4PX*BU48BS3 | S9V2B060U3PSB+RP | 26,400 | $1,320 |
| No | 10511176 | TRANE | 4TWV0036A1 | 4PX*BU36BS3 | S9V2B060U3PSB+RP | 26,200 | $1,310 |
| No | 10511311 | TRANE | 4TWV8037A1 | 4PX*BU36BS3 | S9V2B080U3PSB+RP | 26,000 | $1,300 |
| No | 201808886 | TRANE | 4TWV8037A1 | 4PX*BU36BS3 | S9V2B080U3VSA+RP | 26,000 | $1,300 |
| No | 10511177 | TRANE | 4TWV0036A1 | 4PX*BU36BS3 | S9V2B040U3PSB+RP | 26,200 | $1,310 |
| No | 207526892 | TRANE | 4TWV0X24A1 | TEM6A0B24H21+TDR+RP | | 16,600 | $830 |
| No | 206918612 | TRANE | 4TWV0024A1 | TEM6A0B24H21+TDR+RP | | 16,600 | $830 |
| No | 207558946 | TRANE | 4TWV0X24A1 | 4PX*BU36BS3 | *UHMB080ACV3 | 16,900 | $845 |
| No | 207526233 | TRANE | 4TWV8X24A1 | 4PX*BU36BS3 | *UHMB060ACV3 | 16,900 | $845 |
| No | 8759438 | TRANE | 4TWV8024A1 | 4PX*BU36BS3 | *UHMB080ACV3 | 16,900 | $845 |
| No | 8759436 | TRANE | 4TWV8024A1 | 4PX*BU36BS3 | *UHMB060ACV3 | 16,900 | $845 |
| No | 8759384 | TRANE | 4TWV0024A1 | 4PX*BU36BS3 | *UHMB060ACV3 | 16,900 | $845 |
| No | 8759383 | TRANE | 4TWV0024A1 | 4PX*BU36BS3 | *UHMB080ACV3 | 16,900 | $845 |
| No | 207526884 | TRANE | 4TWV0X48A1 | TEM6A0D60H51+TDR+RP | | 35,000 | $1,750 |
| No | 206918565 | TRANE | 4TWV0048A1 | TEM6A0D60H51+TDR+RP | | 35,000 | $1,750 |
| No | 206918576 | TRANE | 4TWV8049A1 | TEM6A0D60H51+TDR+RP | | 35,000 | $1,750 |
| No | 207526259 | TRANE | 4TWV8X36A1 | 4PX*CU48BS3 | *UHMB080ACV3 | 26,800 | $1,340 |
| No | 8759477 | TRANE | 4TWV8036A1 | 4PX*CU48BS3 | *UHMB080ACV3 | 26,800 | $1,340 |
| No | 10511291 | TRANE | 4TWV8036A1 | 4TXCB006DS3 | S9V2B080D4PSB+RP | 25,400 | $1,270 |
| No | 10153712 | TRANE | 4TWV8024A1 | TEM8A0B30V31+TDR | | 16,700 | $835 |
| No | 10511299 | TRANE | 4TWV8036A1 | 4TXCC007DS3 | S9V2C100D4PSB+RP | 25,000 | $1,250 |
| No | 10511201 | TRANE | 4TWV0036A1 | 4TXCC005DS3 | S9V2C100U4PSB+RP | 26,000 | $1,300 |
| No | 10511185 | TRANE | 4TWV0036A1 | 4PX*CU36BS3 | S9V2C100U4PSB+RP | 26,000 | $1,300 |
| No | 201808916 | TRANE | 4TWV8037A1 | 4TXCC005DS3 | S9V2C100U4VSA+RP | 26,000 | $1,300 |
| No | 201808740 | TRANE | 4TWV0036A1 | 4TXCC005DS3 | S9V2C100U4VSA+RP | 26,000 | $1,300 |
| No | 201808898 | TRANE | 4TWV8037A1 | 4PX*CU36BS3 | S9V2C100U4VSA+RP | 26,000 | $1,300 |
| No | 201808710 | TRANE | 4TWV0036A1 | 4PX*CU36BS3 | S9V2C100U4VSA+RP | 26,000 | $1,300 |
| No | 10511321 | TRANE | 4TWV8037A1 | 4PX*CU36BS3 | S9V2C100U4PSB+RP | 26,000 | $1,300 |
| No | 10511338 | TRANE | 4TWV8037A1 | 4TXCC005DS3 | S9V2C100U4PSB+RP | 26,000 | $1,300 |
| No | 8759511 | TRANE | 4TWV8037A1 | 4PX*CU48BS3 | *UHMC100ACV4 | 26,800 | $1,340 |
| No | 10511175 | TRANE | 4TWV0036A1 | 4PX*BU36BS3 | S9V2B060U4PSB+RP | 26,000 | $1,300 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201808872 | TRANE | 4TWV8036A1 | 4TXCC005DS3 | S9V2C100U4VSA+RP | 26,000 | $1,300 |
| No | 201808850 | TRANE | 4TWV8036A1 | 4PX*CU36BS3 | S9V2C100U4VSA+RP | 26,000 | $1,300 |
| No | 10511276 | TRANE | 4TWV8036A1 | 4PX*CU36BS3 | S9V2C100U4PSB+RP | 26,000 | $1,300 |
| No | 204780418 | TRANE | 4TWV8037A1 | 4PX*BU42BS3 | P0V0B000M40SA+RP | 26,200 | $1,310 |
| No | 204780358 | TRANE | 4TWV0036A1 | 4PX*BU42BS3 | P0V0B000M40SA+RP | 26,200 | $1,310 |
| No | 207558961 | TRANE | 4TWV0X36A1 | 4PX*BU48BS3 | *UD2B060ACV3 | 26,800 | $1,340 |
| No | 201808882 | TRANE | 4TWV8037A1 | 4PX*BU36BS3 | S9V2B060U3VSA+RP | 26,200 | $1,310 |
| No | 202365949 | TRANE | 4TWV8036A1 | 4PX*BU48BS3 | S9V2B080D4PSB+RP | 25,600 | $1,280 |
| No | 204780399 | TRANE | 4TWV8036A1 | 4PX*BU36BS3 | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 207526612 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 7125590 | TRANE | 4TWV8024A1 | 4TXFH024CZ3 | *DHMB080ACV3 | 16,700 | $835 |
| No | 10511293 | TRANE | 4TWV8036A1 | 4TXCB006DS3 | S9V2B040D3PSB+RP | 25,200 | $1,260 |
| No | 10511287 | TRANE | 4TWV8036A1 | 4TXCB006DS3 | S9V2B060D3PSB+RP | 25,200 | $1,260 |
| No | 201808904 | TRANE | 4TWV8037A1 | 4TXCB004DS3 | S9V2B040U3VSA+RP | 26,200 | $1,310 |
| No | 201808884 | TRANE | 4TWV8037A1 | 4PX*BU36BS3 | S9V2B040U3VSA+RP | 26,200 | $1,310 |
| No | 201808716 | TRANE | 4TWV0036A1 | 4TXCB004DS3 | S9V2B040U3VSA+RP | 26,200 | $1,310 |
| No | 201808692 | TRANE | 4TWV0036A1 | 4PX*BU36BS3 | S9V2B040U3VSA+RP | 26,200 | $1,310 |
| No | 10511331 | TRANE | 4TWV8037A1 | 4TXCB004DS3 | S9V2B040U3PSB+RP | 26,200 | $1,310 |
| No | 10511313 | TRANE | 4TWV8037A1 | 4PX*BU36BS3 | S9V2B040U3PSB+RP | 26,200 | $1,310 |
| No | 10511187 | TRANE | 4TWV0036A1 | 4TXCB004DS3 | S9V2B040U3PSB+RP | 26,200 | $1,310 |
| No | 201808860 | TRANE | 4TWV8036A1 | 4TXCB004DS3 | S9V2B040U3VSA+RP | 26,200 | $1,310 |
| No | 201808828 | TRANE | 4TWV8036A1 | 4PX*BU36BS3 | S9V2B040U3VSA+RP | 26,200 | $1,310 |
| No | 10511280 | TRANE | 4TWV8036A1 | 4TXCB004DS3 | S9V2B040U3PSB+RP | 26,200 | $1,310 |
| No | 10511265 | TRANE | 4TWV8036A1 | 4PX*BU36BS3 | S9V2B040U3PSB+RP | 26,200 | $1,310 |
| No | 207526601 | TRANE | 4TWV0X48A1 | 4TXCD010DS3 | P0V0C000M50SA+RP | 34,400 | $1,720 |
| No | 204780388 | TRANE | 4TWV0048A1 | 4TXCD010DS3 | P0V0C000M50SA+RP | 34,400 | $1,720 |
| No | 207558991 | TRANE | 4TWV0X24A1 | 4TXCB004DS3 | *DD2B060ACV3 | 16,500 | $825 |
| No | 8761402 | TRANE | 4TWV0024A1 | 4TXCB004DS3 | *DD2B060ACV3 | 16,500 | $825 |
| No | 10153698 | TRANE | 4TWV0036A1 | TEM8A0C42V41+TDR | | 25,200 | $1,260 |
| No | 207526598 | TRANE | 4TWV0X48A1 | 4TXCD008DS3 | P0V0D000M50SA+RP | 35,800 | $1,790 |
| No | 204780385 | TRANE | 4TWV0048A1 | 4TXCD008DS3 | P0V0D000M50SA+RP | 35,800 | $1,790 |
| No | 10511189 | TRANE | 4TWV0036A1 | 4TXCB004DS3 | S9V2B060U4PSB+RP | 26,000 | $1,300 |
| No | 207526381 | TRANE | 4TWV0X36A1 | 4PX*BU36BS3 | S9V2B080U3PSB+RP | 26,000 | $1,300 |
| No | 10511174 | TRANE | 4TWV0036A1 | 4PX*BU36BS3 | S9V2B080U3PSB+RP | 26,000 | $1,300 |
| No | 10511267 | TRANE | 4TWV8036A1 | 4PX*BU36BS3 | S9V2B060U4PSB+RP | 26,000 | $1,300 |
| No | 10511278 | TRANE | 4TWV8036A1 | 4TXCB004DS3 | S9V2B060U4PSB+RP | 26,000 | $1,300 |
| No | 10511310 | TRANE | 4TWV8037A1 | 4PX*BU36BS3 | S9V2B060U4PSB+RP | 26,000 | $1,300 |
| No | 7125592 | TRANE | 4TWV8036A1 | 4TXFH036CZ3 | *DHMB060BCV3 | 25,600 | $1,280 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207526225 | TRANE | 4TWV8X36A1 | 4TXFH036CZ3 | *DHMB060BCV3 | 25,600 | $1,280 |
| No | 10511329 | TRANE | 4TWV8037A1 | 4TXCB004DS3 | S9V2B060U4PSB+RP | 26,000 | $1,300 |
| No | 202365951 | TRANE | 4TWV8036A1 | 4PX*BU48BS3 | S9V2B060D3PSB+RP | 25,400 | $1,270 |
| No | 10511286 | TRANE | 4TWV8036A1 | 4TXCB004DS3 | S9V2B080U4PSB+RP | 26,200 | $1,310 |
| No | 10511264 | TRANE | 4TWV8036A1 | 4PX*BU36BS3 | S9V2B080U4PSB+RP | 26,200 | $1,310 |
| No | 6796597 | TRANE | 4TWV0024A1 | 4TXFH024CZ3 | *DHMB060BCV3 | 16,400 | $820 |
| No | 8759414 | TRANE | 4TWV0036A1 | 4PX*CU36BS3 | *UD2C080ACV4 | 26,400 | $1,320 |
| No | 8759469 | TRANE | 4TWV8036A1 | 4PX*CU36BS3 | *UD2C080ACV4 | 26,200 | $1,310 |
| No | 201808857 | TRANE | 4TWV8036A1 | 4TXCB004DS3 | S9V2B060U3VSA+RP | 26,200 | $1,310 |
| No | 10511279 | TRANE | 4TWV8036A1 | 4TXCB004DS3 | S9V2B060U3PSB+RP | 26,200 | $1,310 |
| No | 10511266 | TRANE | 4TWV8036A1 | 4PX*BU36BS3 | S9V2B060U3PSB+RP | 26,200 | $1,310 |
| No | 201808833 | TRANE | 4TWV8036A1 | 4PX*BU36BS3 | S9V2B060U3VSA+RP | 26,200 | $1,310 |
| No | 204780486 | TRANE | 4TWV8049A1 | 4TXCD008DS3 | P0V0D000M50SA+RP | 35,800 | $1,790 |
| No | 202492144 | TRANE | 4TWV8036A1 | 4PX*BU36BS3 | S9V2B040D3PSB+RP | 25,600 | $1,280 |
| No | 202365947 | TRANE | 4TWV8036A1 | 4PX*BU48BS3 | *DD2B080ACV3 | 25,600 | $1,280 |
| No | 206918568 | TRANE | 4TWV8036A1 | TEM6A0C42H41+TDR+RP | | 25,000 | $1,250 |
| No | 207526887 | TRANE | 4TWV8X36A1 | TEM6A0C42H41+TDR+RP | | 25,000 | $1,250 |
| No | 207526467 | TRANE | 4TWV8X36A1 | 4PX*CD48BS3 | S9V2C100D4VSA+RP | 26,600 | $1,330 |
| No | 207526398 | TRANE | 4TWV8X36A1 | 4PX*CD48BS3 | S9V2C100D4PSB+RP | 26,600 | $1,330 |
| No | 201808847 | TRANE | 4TWV8036A1 | 4PX*CD48BS3 | S9V2C100D4VSA+RP | 26,600 | $1,330 |
| No | 10511275 | TRANE | 4TWV8036A1 | 4PX*CD48BS3 | S9V2C100D4PSB+RP | 26,600 | $1,330 |
| No | 207526253 | TRANE | 4TWV8X36A1 | 4PX*CU36BS3 | *UHMC100ACV4 | 26,200 | $1,310 |
| No | 8759466 | TRANE | 4TWV8036A1 | 4PX*CU36BS3 | *UHMC100ACV4 | 26,200 | $1,310 |
| No | 207526881 | TRANE | 4TWV0X36A1 | TEM6A0C42H41+TDR+RP | | 25,000 | $1,250 |
| No | 8759411 | TRANE | 4TWV0036A1 | 4PX*CU36BS3 | *UD2C100ACV5 | 26,400 | $1,320 |
| No | 206918570 | TRANE | 4TWV8037A1 | TEM6A0C42H41+TDR+RP | | 25,000 | $1,250 |
| No | 206918562 | TRANE | 4TWV0036A1 | TEM6A0C42H41+TDR+RP | | 25,000 | $1,250 |
| No | 207526778 | TRANE | 4TWV0X36A1 | 4TXCC005DS3 | S9V2C100U5PSBC+RP | 25,200 | $1,260 |
| No | 207526774 | TRANE | 4TWV0X36A1 | 4PX*CU36BS3 | S9V2C100U5PSBC+RP | 25,200 | $1,260 |
| No | 206910680 | TRANE | 4TWV8037A1 | 4TXCC005DS3 | S9V2C100U5PSBC+RP | 25,200 | $1,260 |
| No | 206910678 | TRANE | 4TWV8037A1 | 4PX*CU36BS3 | S9V2C100U5PSBC+RP | 25,200 | $1,260 |
| No | 206910666 | TRANE | 4TWV0036A1 | 4TXCC005DS3 | S9V2C100U5PSBC+RP | 25,200 | $1,260 |
| No | 204780422 | TRANE | 4TWV8037A1 | 4TXCB004DS3 | P0V0B000M40SA+RP | 25,400 | $1,270 |
| No | 206910662 | TRANE | 4TWV0036A1 | 4PX*CU36BS3 | S9V2C100U5PSBC+RP | 25,200 | $1,260 |
| No | 8761461 | TRANE | 4TWV8036A1 | 4TXCC005DS3 | *UD2C080ACV4 | 26,200 | $1,310 |
| No | 206910663 | TRANE | 4TWV0036A1 | 4PX*CU48BS3 | S9V2C100D5PSBC+RP | 24,800 | $1,240 |
| No | 202492131 | TRANE | 4TWV0036A1 | 4PX*BU48BS3 | S9V2B040D3PSB+RP | 25,000 | $1,250 |
| No | 207526775 | TRANE | 4TWV0X36A1 | 4PX*CU48BS3 | S9V2C100D5PSBC+RP | 24,800 | $1,240 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207526619 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 204780406 | TRANE | 4TWV8036A1 | 4TXCB004DS3 | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 202586173 | TRANE | 4TWV0036A1 | 4PX*CU42BS3 | *DHMC100ACV4 | 26,800 | $1,340 |
| No | 207526290 | TRANE | 4TWV8X36A1 | 4TXCC005DS3 | *UHMC100ACV4 | 26,200 | $1,310 |
| No | 206753731 | TRANE | 4TWV8036A1 | 4PX*BU42BS3 | S9V2B080U4PSB+RP | 26,000 | $1,300 |
| No | 8761466 | TRANE | 4TWV8036A1 | 4TXCC005DS3 | *UHMC100ACV4 | 26,200 | $1,310 |
| No | 202492147 | TRANE | 4TWV8037A1 | 4PX*BU48BS3 | S9V2B060D3PSB+RP | 25,400 | $1,270 |
| No | 202492134 | TRANE | 4TWV0036A1 | 4PX*BU48BS3 | S9V2B060D3PSB+RP | 25,400 | $1,270 |
| No | 8761489 | TRANE | 4TWV8037A1 | 4TXCC005DS3 | *UD2C080ACV4 | 26,400 | $1,320 |
| No | 8761416 | TRANE | 4TWV0036A1 | 4TXCC005DS3 | *UD2C080ACV4 | 26,400 | $1,320 |
| No | 8759507 | TRANE | 4TWV8037A1 | 4PX*CU36BS3 | *UD2C080ACV4 | 26,400 | $1,320 |
| No | 8759470 | TRANE | 4TWV8036A1 | 4PX*CU36BS3 | *UD2C100ACV5 | 26,000 | $1,300 |
| No | 10153722 | TRANE | 4TWV8037A1 | TEM8A0C42V41+TDR | | 25,200 | $1,260 |
| No | 8761463 | TRANE | 4TWV8036A1 | 4TXCC005DS3 | *UD2C100ACV5 | 26,000 | $1,300 |
| No | 207526596 | TRANE | 4TWV0X48A1 | 4TXCC007DS3 | P0V0C000M50SA+RP | 36,000 | $1,800 |
| No | 207526584 | TRANE | 4TWV0X48A1 | 4PX*CU48BS3 | P0V0C000M50SA+RP | 36,000 | $1,800 |
| No | 204780455 | TRANE | 4TWV8049A1 | 4PX*CU48BS3 | P0V0C000M50SA+RP | 36,000 | $1,800 |
| No | 204780383 | TRANE | 4TWV0048A1 | 4TXCC007DS3 | P0V0C000M50SA+RP | 36,000 | $1,800 |
| No | 204780371 | TRANE | 4TWV0048A1 | 4PX*CU48BS3 | P0V0C000M50SA+RP | 36,000 | $1,800 |
| No | 207526569 | TRANE | 4TWV0X36A1 | 4PX*BU36BS3 | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 207526514 | TRANE | 4TWV8X36A1 | 4PX*BU48BS3 | *DHMB060BCV3 | 25,800 | $1,290 |
| No | 204780415 | TRANE | 4TWV8037A1 | 4PX*BU36BS3 | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 202365948 | TRANE | 4TWV8036A1 | 4PX*BU48BS3 | *DHMB060BCV3 | 25,800 | $1,290 |
| No | 204780356 | TRANE | 4TWV0036A1 | 4PX*BU36BS3 | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 207526414 | TRANE | 4TWV0X36A1 | 4PX*BU36BS3 | S9V2B080U3VSA+RP | 26,000 | $1,300 |
| No | 207526386 | TRANE | 4TWV0X36A1 | 4TXCB004DS3 | S9V2B080U3PSB+RP | 26,000 | $1,300 |
| No | 201808689 | TRANE | 4TWV0036A1 | 4PX*BU36BS3 | S9V2B080U3VSA+RP | 26,000 | $1,300 |
| No | 201808906 | TRANE | 4TWV8037A1 | 4TXCB004DS3 | S9V2B080U3VSA+RP | 26,000 | $1,300 |
| No | 201808722 | TRANE | 4TWV0036A1 | 4TXCB004DS3 | S9V2B080U3VSA+RP | 26,000 | $1,300 |
| No | 10511190 | TRANE | 4TWV0036A1 | 4TXCB004DS3 | S9V2B080U3PSB+RP | 26,000 | $1,300 |
| No | 207526425 | TRANE | 4TWV0X36A1 | 4TXCB004DS3 | S9V2B080U3VSA+RP | 26,000 | $1,300 |
| No | 10511328 | TRANE | 4TWV8037A1 | 4TXCB004DS3 | S9V2B080U3PSB+RP | 26,000 | $1,300 |
| No | 207526396 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | S9V2B080U3PSB+RP | 26,000 | $1,300 |
| No | 207526461 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | S9V2B080U3VSA+RP | 26,000 | $1,300 |
| No | 207526472 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | S9V2B080U3VSA+RP | 26,000 | $1,300 |
| No | 207526399 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | S9V2B080U3PSB+RP | 26,000 | $1,300 |
| No | 201808862 | TRANE | 4TWV8036A1 | 4TXCB004DS3 | S9V2B080U3VSA+RP | 26,000 | $1,300 |
| No | 201808831 | TRANE | 4TWV8036A1 | 4PX*BU36BS3 | S9V2B080U3VSA+RP | 26,000 | $1,300 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10511268 | TRANE | 4TWV8036A1 | 4PX*BU36BS3 | S9V2B080U3PSB+RP | 26,000 | $1,300 |
| No | 10511327 | TRANE | 4TWV8037A1 | 4TXCB004DS3 | S9V2B080U4PSB+RP | 26,000 | $1,300 |
| No | 10511312 | TRANE | 4TWV8037A1 | 4PX*BU36BS3 | S9V2B080U4PSB+RP | 26,000 | $1,300 |
| No | 10511191 | TRANE | 4TWV0036A1 | 4TXCB004DS3 | S9V2B080U4PSB+RP | 26,000 | $1,300 |
| No | 10511281 | TRANE | 4TWV8036A1 | 4TXCB004DS3 | S9V2B080U3PSB+RP | 26,000 | $1,300 |
| No | 202365945 | TRANE | 4TWV8036A1 | 4PX*BU36BS3 | S9V2B060D3PSB+RP | 25,400 | $1,270 |
| No | 207558998 | TRANE | 4TWV0X36A1 | 4TXCC005DS3 | *UHMC100ACV4 | 26,200 | $1,310 |
| No | 207558970 | TRANE | 4TWV0X36A1 | 4PX*CU36BS3 | *UHMC100ACV4 | 26,200 | $1,310 |
| No | 8761414 | TRANE | 4TWV0036A1 | 4TXCC005DS3 | *UHMC100ACV4 | 26,200 | $1,310 |
| No | 8759504 | TRANE | 4TWV8037A1 | 4PX*CU36BS3 | *UD2C100ACV5 | 26,400 | $1,320 |
| No | 8759413 | TRANE | 4TWV0036A1 | 4PX*CU36BS3 | *UHMC100ACV4 | 26,200 | $1,310 |
| No | 8759451 | TRANE | 4TWV8036A1 | 4PX*BU36BS3 | *UD2B080ACV3 | 26,400 | $1,320 |
| No | 8761490 | TRANE | 4TWV8037A1 | 4TXCC005DS3 | *UHMC100ACV4 | 26,200 | $1,310 |
| No | 8759506 | TRANE | 4TWV8037A1 | 4PX*CU36BS3 | *UHMC100ACV4 | 26,200 | $1,310 |
| No | 202365946 | TRANE | 4TWV8036A1 | 4PX*BU36BS3 | S9V2B080D3PSB+RP | 25,400 | $1,270 |
| No | 202492149 | TRANE | 4TWV8037A1 | 4PX*BU48BS3 | *DD2B080ACV3 | 25,800 | $1,290 |
| No | 202492130 | TRANE | 4TWV0036A1 | 4PX*BU48BS3 | *DD2B080ACV3 | 25,800 | $1,290 |
| No | 202492150 | TRANE | 4TWV8037A1 | 4PX*BU48BS3 | S9V2B080D3PSB+RP | 25,200 | $1,260 |
| No | 205262064 | TRANE | 4TWV8036A1 | 4TXCB004DS3 | S9V2B080U4VSA+RP | 25,600 | $1,280 |
| No | 202492133 | TRANE | 4TWV0036A1 | 4PX*BU48BS3 | S9V2B080D3PSB+RP | 25,200 | $1,260 |
| No | 204780403 | TRANE | 4TWV8036A1 | 4PX*BU48BS3 | P0V0B000M40SA+RP | 25,000 | $1,250 |
| No | 207526616 | TRANE | 4TWV8X36A1 | 4PX*BU48BS3 | P0V0B000M40SA+RP | 25,000 | $1,250 |
| No | 202492151 | TRANE | 4TWV8037A1 | 4PX*BU48BS3 | S9V2B080D4PSB+RP | 25,200 | $1,260 |
| No | 8759395 | TRANE | 4TWV0036A1 | 4PX*BU36BS3 | *UHMB080ACV3 | 26,600 | $1,330 |
| No | 202492132 | TRANE | 4TWV0036A1 | 4PX*BU48BS3 | S9V2B080D4PSB+RP | 25,200 | $1,260 |
| No | 8761487 | TRANE | 4TWV8037A1 | 4TXCC005DS3 | *UD2C100ACV5 | 26,400 | $1,320 |
| No | 207526251 | TRANE | 4TWV8X36A1 | 4PX*CD48BS3 | *DD2C100ACV5 | 26,800 | $1,340 |
| No | 206223105 | TRANE | 4TWV8X24A1 | TAMXA0B30V3PA | | 15,800 | $790 |
| No | 8759461 | TRANE | 4TWV8036A1 | 4PX*CD48BS3 | *DD2C100ACV5 | 26,800 | $1,340 |
| No | 207526223 | TRANE | 4TWV8X36A1 | 4TXFH036CZ3 | *UD2C080ACV4 | 25,200 | $1,260 |
| No | 6796634 | TRANE | 4TWV8036A1 | 4TXFH036CZ3 | *UD2C080ACV4 | 25,200 | $1,260 |
| No | 8761482 | TRANE | 4TWV8037A1 | 4TXCB006DS3 | *UHMB060ACV3 | 26,600 | $1,330 |
| No | 207526379 | TRANE | 4TWV0X36A1 | 4PX*BD48BS3 | S9V2B060D3PSB+RP | 27,000 | $1,350 |
| No | 10511305 | TRANE | 4TWV8037A1 | 4PX*BD48BS3 | S9V2B060D3PSB+RP | 27,000 | $1,350 |
| No | 10511171 | TRANE | 4TWV0036A1 | 4PX*BD48BS3 | S9V2B060D3PSB+RP | 27,000 | $1,350 |
| No | 10511260 | TRANE | 4TWV8036A1 | 4PX*BD48BS3 | S9V2B060D3PSB+RP | 26,800 | $1,340 |
| No | 207526765 | TRANE | 4TWV8X36A1 | 4PX*CU48BS3 | S9V2B080U4PSA+RP | 25,000 | $1,250 |
| No | 10511263 | TRANE | 4TWV8036A1 | 4PX*BD48BS3 | S9V2B040D3PSB+RP | 26,800 | $1,340 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 8761417 | TRANE | 4TWV0036A1 | 4TXCC005DS3 | *UD2C100ACV5 | 26,400 | $1,320 |
| No | 206118929 | TRANE | 4TWV8036A1 | 4PX*CU48BS3 | S9V2B080U4PSA+RP | 25,000 | $1,250 |
| No | 207526777 | TRANE | 4TWV0X36A1 | 4TXCC005DS3 | S9V2C100D5PSBC+RP | 25,000 | $1,250 |
| No | 206910665 | TRANE | 4TWV0036A1 | 4TXCC005DS3 | S9V2C100D5PSBC+RP | 25,000 | $1,250 |
| No | 8761447 | TRANE | 4TWV8036A1 | 4TXCB004DS3 | *UHMB080ACV3 | 26,400 | $1,320 |
| No | 8759448 | TRANE | 4TWV8036A1 | 4PX*BU36BS3 | *UHMB080ACV3 | 26,400 | $1,320 |
| No | 8759449 | TRANE | 4TWV8036A1 | 4PX*BU36BS3 | *UD2B060ACV3 | 26,400 | $1,320 |
| No | 207558938 | TRANE | 4TWV0X36A1 | 4TXFH036CZ3 | *DHMB060BCV3 | 25,800 | $1,290 |
| No | 7125588 | TRANE | 4TWV0036A1 | 4TXFH036CZ3 | *DHMB060BCV3 | 25,800 | $1,290 |
| No | 207526459 | TRANE | 4TWV8X36A1 | 4PX*BD48BS3 | S9V2B080D3VSA+RP | 26,800 | $1,340 |
| No | 201808825 | TRANE | 4TWV8036A1 | 4PX*BD48BS3 | S9V2B080D3VSA+RP | 26,800 | $1,340 |
| No | 207526771 | TRANE | 4TWV0X36A1 | 4PX*BU36BS3 | S9V2B060U4PSBC+RP | 25,400 | $1,270 |
| No | 10511261 | TRANE | 4TWV8036A1 | 4PX*BD48BS3 | S9V2B080D3PSB+RP | 26,800 | $1,340 |
| No | 206910659 | TRANE | 4TWV0036A1 | 4PX*BU36BS3 | S9V2B060U4PSBC+RP | 25,400 | $1,270 |
| No | 207526786 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | S9V2B060U4PSBC+RP | 25,400 | $1,270 |
| No | 206910674 | TRANE | 4TWV8036A1 | 4PX*BU36BS3 | S9V2B060U4PSBC+RP | 25,400 | $1,270 |
| No | 207526722 | TRANE | 4TWV8X36A1 | 4PX*BU42BS3 | P0V0B000M40SB+RP | 25,400 | $1,270 |
| No | 205962354 | TRANE | 4TWV8036A1 | 4PX*BU42BS3 | P0V0B000M40SB+RP | 25,400 | $1,270 |
| No | 207558927 | TRANE | 4TWV0X24A1 | 4TXFH024CZ3 | *UD2B060ACV3 | 16,300 | $815 |
| No | 207558933 | TRANE | 4TWV0X36A1 | 4TXFH036CZ3 | *UHMB080ACV3 | 25,600 | $1,280 |
| No | 6796594 | TRANE | 4TWV0024A1 | 4TXFH024CZ3 | *UD2B060ACV3 | 16,300 | $815 |
| No | 6796603 | TRANE | 4TWV0036A1 | 4TXFH036CZ3 | *UHMB080ACV3 | 25,600 | $1,280 |
| No | 10511262 | TRANE | 4TWV8036A1 | 4PX*BD48BS3 | S9V2B080D4PSB+RP | 26,800 | $1,340 |
| No | 207558966 | TRANE | 4TWV0X36A1 | 4PX*CD48BS3 | *DD2C100ACV5 | 27,000 | $1,350 |
| No | 8759407 | TRANE | 4TWV0036A1 | 4PX*CD48BS3 | *DD2C100ACV5 | 27,000 | $1,350 |
| No | 8761477 | TRANE | 4TWV8037A1 | 4TXCB004DS3 | *UD2B060ACV3 | 26,200 | $1,310 |
| No | 8761407 | TRANE | 4TWV0036A1 | 4TXCB004DS3 | *UD2B060ACV3 | 26,200 | $1,310 |
| No | 8759493 | TRANE | 4TWV8037A1 | 4PX*BU36BS3 | *UD2B060ACV3 | 26,200 | $1,310 |
| No | 207526332 | TRANE | 4TWV8X36A1 | TAM9A0C42V41 | | 25,400 | $1,270 |
| No | 10093506 | TRANE | 4TWV8036A1 | TAM9A0C42V41 | | 25,400 | $1,270 |
| No | 207526773 | TRANE | 4TWV0X36A1 | 4PX*CD42BS3 | S9V2C100D5PSBC+RP | 25,200 | $1,260 |
| No | 206910661 | TRANE | 4TWV0036A1 | 4PX*CD42BS3 | S9V2C100D5PSBC+RP | 25,200 | $1,260 |
| No | 207526573 | TRANE | 4TWV0X36A1 | 4PX*BU48BS3 | P0V0B000M40SA+RP | 25,200 | $1,260 |
| No | 204780360 | TRANE | 4TWV0036A1 | 4PX*BU48BS3 | P0V0B000M40SA+RP | 25,200 | $1,260 |
| No | 204780420 | TRANE | 4TWV8037A1 | 4PX*BU48BS3 | P0V0B000M40SA+RP | 25,200 | $1,260 |
| No | 8761403 | TRANE | 4TWV0036A1 | 4TXCB004DS3 | *UHMB080ACV3 | 26,600 | $1,330 |
| No | 8759490 | TRANE | 4TWV8037A1 | 4PX*BU36BS3 | *UHMB080ACV3 | 26,600 | $1,330 |
| No | 8761481 | TRANE | 4TWV8037A1 | 4TXCB004DS3 | *UHMB080ACV3 | 26,600 | $1,330 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 6796643 | TRANE | 4TWV8037A1 | 4TXFH036CZ3 | *UHMB080ACV3 | 25,600 | $1,280 |
| No | 10511220 | TRANE | 4TWV0048A1 | 4TXCC007DS3 | S9V2C100D5PSB+RP | 35,200 | $1,760 |
| No | 8761446 | TRANE | 4TWV8036A1 | 4TXCB004DS3 | *UD2B080ACV3 | 26,400 | $1,320 |
| No | 202492148 | TRANE | 4TWV8037A1 | 4PX*BU48BS3 | S9V2B040D3PSB+RP | 25,000 | $1,250 |
| No | 10093508 | TRANE | 4TWV8037A1 | TAM9A0C36V31 | | 25,200 | $1,260 |
| No | 10093496 | TRANE | 4TWV0036A1 | TAM9A0C36V31 | | 25,200 | $1,260 |
| No | 204780404 | TRANE | 4TWV8036A1 | 4PX*BU48BS3 | P0V0A000M30SA+RP | 24,200 | $1,210 |
| No | 207526617 | TRANE | 4TWV8X36A1 | 4PX*BU48BS3 | P0V0A000M30SA+RP | 24,200 | $1,210 |
| No | 207526574 | TRANE | 4TWV0X36A1 | 4PX*BU48BS3 | P0V0A000M30SA+RP | 24,400 | $1,220 |
| No | 204780419 | TRANE | 4TWV8037A1 | 4PX*BU48BS3 | P0V0A000M30SA+RP | 24,400 | $1,220 |
| No | 202492152 | TRANE | 4TWV8037A1 | 4PX*CD42BS3 | S9V2C100D4PSB+RP | 25,400 | $1,270 |
| No | 204780361 | TRANE | 4TWV0036A1 | 4PX*BU48BS3 | P0V0A000M30SA+RP | 24,400 | $1,220 |
| No | 202492135 | TRANE | 4TWV0036A1 | 4PX*CD42BS3 | S9V2C100D4PSB+RP | 25,400 | $1,270 |
| No | 202492145 | TRANE | 4TWV8036A1 | 4PX*CD42BS3 | S9V2C100D4PSB+RP | 25,400 | $1,270 |
| No | 202586174 | TRANE | 4TWV8036A1 | 4PX*CU42BS3 | *DD2C100ACV5 | 25,200 | $1,260 |
| No | 8759397 | TRANE | 4TWV0036A1 | 4PX*BU36BS3 | *UD2B060ACV3 | 26,200 | $1,310 |
| No | 8759452 | TRANE | 4TWV8036A1 | 4PX*BU36BS3 | *UHMB060ACV3 | 26,600 | $1,330 |
| No | 204780359 | TRANE | 4TWV0036A1 | 4PX*BU42BS3 | P0V0A000M30SA+RP | 25,400 | $1,270 |
| No | 204780417 | TRANE | 4TWV8037A1 | 4PX*BU42BS3 | P0V0A000M30SA+RP | 25,400 | $1,270 |
| No | 8761464 | TRANE | 4TWV8036A1 | 4TXCC005DS3 | *UHMB080ACV3 | 26,200 | $1,310 |
| No | 207526572 | TRANE | 4TWV0X36A1 | 4PX*BU42BS3 | P0V0A000M30SA+RP | 25,400 | $1,270 |
| No | 8759467 | TRANE | 4TWV8036A1 | 4PX*CU36BS3 | *UHMB080ACV3 | 26,200 | $1,310 |
| No | 207526289 | TRANE | 4TWV8X36A1 | 4TXCC005DS3 | *UHMB080ACV3 | 26,200 | $1,310 |
| No | 201808844 | TRANE | 4TWV8036A1 | 4PX*CD36BS3 | S9V2C100D4VSA+RP | 26,600 | $1,330 |
| No | 10511274 | TRANE | 4TWV8036A1 | 4PX*CD36BS3 | S9V2C100D4PSB+RP | 26,600 | $1,330 |
| No | 207526254 | TRANE | 4TWV8X36A1 | 4PX*CU36BS3 | *UHMB080ACV3 | 26,200 | $1,310 |
| No | 8761450 | TRANE | 4TWV8036A1 | 4TXCB004DS3 | *UD2B060ACV3 | 26,400 | $1,320 |
| No | 206223108 | TRANE | 4TWV8X48A1 | TAMXA0C48V4PA | | 34,800 | $1,740 |
| No | 205962364 | TRANE | 4TWV8037A1 | 4PX*BU42BS3 | P0V0B000M40SB+RP | 25,400 | $1,270 |
| No | 207526681 | TRANE | 4TWV0X36A1 | 4PX*BU42BS3 | P0V0B000M40SB+RP | 25,400 | $1,270 |
| No | 205962313 | TRANE | 4TWV0036A1 | 4PX*BU42BS3 | P0V0B000M40SB+RP | 25,400 | $1,270 |
| No | 207526238 | TRANE | 4TWV8X36A1 | 4PX*BD48BS3 | *DD2B080ACV3 | 27,000 | $1,350 |
| No | 204780363 | TRANE | 4TWV0036A1 | 4TXCB004DS3 | P0V0A000M30SA+RP | 24,800 | $1,240 |
| No | 207526576 | TRANE | 4TWV0X36A1 | 4TXCB004DS3 | P0V0A000M30SA+RP | 24,800 | $1,240 |
| No | 8759443 | TRANE | 4TWV8036A1 | 4PX*BD48BS3 | *DD2B080ACV3 | 27,000 | $1,350 |
| No | 202492146 | TRANE | 4TWV8036A1 | 4PX*CD42BS3 | *DD2C100ACV5 | 25,600 | $1,280 |
| No | 8759396 | TRANE | 4TWV0036A1 | 4PX*BU36BS3 | *UD2B080ACV3 | 26,000 | $1,300 |
| No | 8761479 | TRANE | 4TWV8037A1 | 4TXCB004DS3 | *UHMB060ACV3 | 26,200 | $1,310 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 8761404 | TRANE | 4TWV0036A1 | 4TXCB004DS3 | *UHMB060ACV3 | 26,200 | $1,310 |
| No | 8759491 | TRANE | 4TWV8037A1 | 4PX*BU36BS3 | *UHMB060ACV3 | 26,200 | $1,310 |
| No | 207558962 | TRANE | 4TWV0X36A1 | 4PX*BU48BS3 | *UHMB060ACV3 | 26,400 | $1,320 |
| No | 8759497 | TRANE | 4TWV8037A1 | 4PX*BU48BS3 | *UHMB060ACV3 | 26,400 | $1,320 |
| No | 8759403 | TRANE | 4TWV0036A1 | 4PX*BU48BS3 | *UHMB060ACV3 | 26,400 | $1,320 |
| No | 10511395 | TRANE | 4TWV8049A1 | 4PX*CU48BS3 | S9V2C100U5PSB+RP | 36,600 | $1,830 |
| No | 10511414 | TRANE | 4TWV8049A1 | 4TXCC007DS3 | S9V2C100U5PSB+RP | 36,600 | $1,830 |
| No | 202492141 | TRANE | 4TWV8036A1 | 4PX*BD42BS3 | S9V2B060D3PSB+RP | 25,800 | $1,290 |
| No | 207526567 | TRANE | 4TWV0X36A1 | 4PX*BD42BS3+HORIZ-RT | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 204780411 | TRANE | 4TWV8037A1 | 4PX*BD42BS3 | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 204780413 | TRANE | 4TWV8037A1 | 4PX*BD42BS3+HORIZ-RT | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 204780354 | TRANE | 4TWV0036A1 | 4PX*BD42BS3+HORIZ-RT | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 202492125 | TRANE | 4TWV0036A1 | 4PX*BD42BS3 | S9V2B040D3PSB+RP | 25,600 | $1,280 |
| No | 206223107 | TRANE | 4TWV8X36A1 | TAMXA0C42V4PA | | 25,000 | $1,250 |
| No | 207558937 | TRANE | 4TWV0X36A1 | 4TXFH036CZ3 | *UHMB060ACV3 | 25,600 | $1,280 |
| No | 7125587 | TRANE | 4TWV0036A1 | 4TXFH036CZ3 | *UHMB060ACV3 | 25,600 | $1,280 |
| No | 205962366 | TRANE | 4TWV8037A1 | 4TXCB004DS3 | P0V0B000M40SB+RP | 24,600 | $1,230 |
| No | 207526684 | TRANE | 4TWV0X36A1 | 4TXCB004DS3 | P0V0B000M40SB+RP | 24,600 | $1,230 |
| No | 7125596 | TRANE | 4TWV8037A1 | 4TXFH036CZ3 | *UHMB060ACV3 | 25,600 | $1,280 |
| No | 205962316 | TRANE | 4TWV0036A1 | 4TXCB004DS3 | P0V0B000M40SB+RP | 24,600 | $1,230 |
| No | 10511283 | TRANE | 4TWV8036A1 | 4TXCB004DS3 | S9V2B080D3PSB+RP | 25,600 | $1,280 |
| No | 204780416 | TRANE | 4TWV8037A1 | 4PX*BU36BS3 | P0V0A000M30SA+RP | 24,800 | $1,240 |
| No | 205962362 | TRANE | 4TWV8037A1 | 4PX*BU36BS3 | P0V0B000M40SB+RP | 24,800 | $1,240 |
| No | 207526680 | TRANE | 4TWV0X36A1 | 4PX*BU36BS3 | P0V0B000M40SB+RP | 24,800 | $1,240 |
| No | 205962312 | TRANE | 4TWV0036A1 | 4PX*BU36BS3 | P0V0B000M40SB+RP | 24,800 | $1,240 |
| No | 10153695 | TRANE | 4TWV0036A1 | TEM8A0B30V31+TDR | | 26,200 | $1,310 |
| No | 207558965 | TRANE | 4TWV0X36A1 | 4PX*CD36BS3 | *DD2C100ACV5 | 27,200 | $1,360 |
| No | 8759406 | TRANE | 4TWV0036A1 | 4PX*CD36BS3 | *DD2C100ACV5 | 27,200 | $1,360 |
| No | 207526611 | TRANE | 4TWV8X36A1 | 4PX*BD42BS3+HORIZ-RT | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 207526608 | TRANE | 4TWV8X36A1 | 4PX*BD42BS3 | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 204780398 | TRANE | 4TWV8036A1 | 4PX*BD42BS3+HORIZ-RT | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 204780395 | TRANE | 4TWV8036A1 | 4PX*BD42BS3 | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 8761462 | TRANE | 4TWV8036A1 | 4TXCC005DS3 | *UD2B100ACV3 | 26,200 | $1,310 |
| No | 207526348 | TRANE | 4TWV0X60A1 | TEM8A0C60V51+TDR | | 50,000 | $2,500 |
| No | 202492139 | TRANE | 4TWV8036A1 | 4PX*BD42BS3 | S9V2B040D3PSB+RP | 25,600 | $1,280 |
| No | 202586178 | TRANE | 4TWV8037A1 | 4PX*CU42BS3 | *DD2C100ACV5 | 25,400 | $1,270 |
| No | 207526287 | TRANE | 4TWV8X36A1 | 4TXCC005DS3 | *UD2B100ACV3 | 26,200 | $1,310 |
| No | 202492129 | TRANE | 4TWV0036A1 | 4PX*BD42BS3 | S9V2B080D4PSB+RP | 25,600 | $1,280 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10153708 | TRANE | 4TWV0060A1 | TEM8A0C60V51+TDR | | 50,000 | $2,500 |
| No | 202492128 | TRANE | 4TWV0036A1 | 4PX*BD42BS3 | S9V2B080D3PSB+RP | 25,600 | $1,280 |
| No | 202586172 | TRANE | 4TWV0036A1 | 4PX*CU42BS3 | *DD2C100ACV5 | 25,400 | $1,270 |
| No | 202492143 | TRANE | 4TWV8036A1 | 4PX*BD42BS3 | S9V2B080D3PSB+RP | 25,600 | $1,280 |
| No | 10093505 | TRANE | 4TWV8036A1 | TAM9A0C36V31 | | 25,200 | $1,260 |
| No | 207526222 | TRANE | 4TWV8X36A1 | 4TXFH036CZ3 | *UD2B080ACV3 | 25,400 | $1,270 |
| No | 6796633 | TRANE | 4TWV8036A1 | 4TXFH036CZ3 | *UD2B080ACV3 | 25,400 | $1,270 |
| No | 10153711 | TRANE | 4TWV0060A1 | TEM8A0D60V51+TDR | | 49,500 | $2,475 |
| No | 207177308 | TRANE | 4TWV8036A1 | 4PX*BD42BS3 | *DD2B060ACV3 | 25,800 | $1,290 |
| No | 10524440 | TRANE | 4TWV8024A1 | 4TXCB003DS3 | *UHMB060ACV3 | 18,000 | $900 |
| No | 10524439 | TRANE | 4TWV8024A1 | 4PX*BU30BS3 | *UHMB060ACV3 | 18,000 | $900 |
| No | 205962357 | TRANE | 4TWV8036A1 | 4TXCB004DS3 | P0V0B000M40SB+RP | 24,600 | $1,230 |
| No | 207526725 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | P0V0B000M40SB+RP | 24,600 | $1,230 |
| No | 10511202 | TRANE | 4TWV0036A1 | 4TXCC005DS3 | S9V2C100D4PSB+RP | 25,600 | $1,280 |
| No | 10511337 | TRANE | 4TWV8037A1 | 4TXCC005DS3 | S9V2C100D4PSB+RP | 25,600 | $1,280 |
| No | 201808918 | TRANE | 4TWV8037A1 | 4TXCC005DS3 | S9V2C100D4VSA+RP | 25,600 | $1,280 |
| No | 201808737 | TRANE | 4TWV0036A1 | 4TXCC005DS3 | S9V2C100D4VSA+RP | 25,600 | $1,280 |
| No | 205962353 | TRANE | 4TWV8036A1 | 4PX*BU36BS3 | P0V0B000M40SB+RP | 24,800 | $1,240 |
| No | 207526721 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | P0V0B000M40SB+RP | 24,800 | $1,240 |
| No | 202492126 | TRANE | 4TWV0036A1 | 4PX*BD42BS3 | *DD2B080ACV3 | 26,000 | $1,300 |
| No | 202492140 | TRANE | 4TWV8036A1 | 4PX*BD42BS3 | *DD2B080ACV3 | 25,800 | $1,290 |
| No | 202586175 | TRANE | 4TWV8036A1 | 4PX*CU42BS3 | *DHMC100ACV4 | 25,800 | $1,290 |
| No | 207526362 | TRANE | 4TWV8X60A1 | TEM8A0C60V51+TDR | | 49,000 | $2,450 |
| No | 10153739 | TRANE | 4TWV8060A1 | TEM8A0C60V51+TDR | | 49,000 | $2,450 |
| No | 10153742 | TRANE | 4TWV8060A1 | TEM8A0D60V51+TDR | | 48,500 | $2,425 |
| No | 207526565 | TRANE | 4TWV0X36A1 | 4PX*BD42BS3 | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 10093509 | TRANE | 4TWV8037A1 | TAM9A0C42V41 | | 25,000 | $1,250 |
| No | 202492127 | TRANE | 4TWV0036A1 | 4PX*BD42BS3 | S9V2B060D3PSB+RP | 25,600 | $1,280 |
| No | 204780352 | TRANE | 4TWV0036A1 | 4PX*BD42BS3 | P0V0B000M40SA+RP | 25,600 | $1,280 |
| No | 202492142 | TRANE | 4TWV8036A1 | 4PX*BD42BS3 | S9V2B080D4PSB+RP | 25,600 | $1,280 |
| No | 201808894 | TRANE | 4TWV8037A1 | 4PX*CD36BS3 | S9V2C100D4VSA+RP | 26,600 | $1,330 |
| No | 201808704 | TRANE | 4TWV0036A1 | 4PX*CD36BS3 | S9V2C100D4VSA+RP | 26,600 | $1,330 |
| No | 8759500 | TRANE | 4TWV8037A1 | 4PX*CD36BS3 | *DD2C100ACV5 | 27,200 | $1,360 |
| No | 10511183 | TRANE | 4TWV0036A1 | 4PX*CD36BS3 | S9V2C100D4PSB+RP | 26,600 | $1,330 |
| No | 10511319 | TRANE | 4TWV8037A1 | 4PX*CD36BS3 | S9V2C100D4PSB+RP | 26,600 | $1,330 |
| No | 207526325 | TRANE | 4TWV0X36A1 | TAM9A0C42V41 | | 24,800 | $1,240 |
| No | 204780357 | TRANE | 4TWV0036A1 | 4PX*BU36BS3 | P0V0A000M30SA+RP | 24,800 | $1,240 |
| No | 10093497 | TRANE | 4TWV0036A1 | TAM9A0C42V41 | | 24,800 | $1,240 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207526570 | TRANE | 4TWV0X36A1 | 4PX*BU36BS3 | P0V0A000M30SA+RP | 24,800 | $1,240 |
| No | 207526613 | TRANE | 4TWV8X36A1 | 4PX*BU36BS3 | P0V0A000M30SA+RP | 24,800 | $1,240 |
| No | 204780405 | TRANE | 4TWV8036A1 | 4TXCB004DS3 | P0V0A000M30SA+RP | 24,800 | $1,240 |
| No | 207526618 | TRANE | 4TWV8X36A1 | 4TXCB004DS3 | P0V0A000M30SA+RP | 24,800 | $1,240 |
| No | 204780400 | TRANE | 4TWV8036A1 | 4PX*BU36BS3 | P0V0A000M30SA+RP | 24,800 | $1,240 |
| No | 207526673 | TRANE | 4TWV8X60A1 | 4TXCD010DS3 | P0V0D000M50SA+RP | 49,000 | $2,450 |
| No | 207526667 | TRANE | 4TWV8X60A1 | 4PX*DU60BS3 | P0V0D000M50SA+RP | 49,000 | $2,450 |
| No | 207526651 | TRANE | 4TWV0X60A1 | 4PX*DU60BS3 | P0V0D000M50SA+RP | 49,000 | $2,450 |
| No | 207526656 | TRANE | 4TWV0X60A1 | 4TXCD010DS3 | P0V0D000M50SA+RP | 49,000 | $2,450 |
| No | 204836667 | TRANE | 4TWV8060A1 | 4TXCD010DS3 | P0V0D000M50SA+RP | 49,000 | $2,450 |
| No | 204836654 | TRANE | 4TWV8060A1 | 4PX*DU60BS3 | P0V0D000M50SA+RP | 49,000 | $2,450 |
| No | 10511192 | TRANE | 4TWV0036A1 | 4TXCB004DS3 | S9V2B040D3PSB+RP | 25,400 | $1,270 |
| No | 204836633 | TRANE | 4TWV0060A1 | 4TXCD010DS3 | P0V0D000M50SA+RP | 49,000 | $2,450 |
| No | 10511285 | TRANE | 4TWV8036A1 | 4TXCB004DS3 | S9V2B040D3PSB+RP | 25,400 | $1,270 |
| No | 10511326 | TRANE | 4TWV8037A1 | 4TXCB004DS3 | S9V2B040D3PSB+RP | 25,400 | $1,270 |
| No | 204836623 | TRANE | 4TWV0060A1 | 4PX*DU60BS3 | P0V0D000M50SA+RP | 49,000 | $2,450 |
| No | 207526556 | TRANE | 4TWV0X36A1 | 4TXCB004DS3 | *DHMB060BCV3 | 25,400 | $1,270 |
| No | 204780421 | TRANE | 4TWV8037A1 | 4TXCB004DS3 | P0V0A000M30SA+RP | 24,800 | $1,240 |
| No | 202636141 | TRANE | 4TWV0036A1 | 4TXCB004DS3 | *DHMB060BCV3 | 25,400 | $1,270 |
| No | 8759399 | TRANE | 4TWV0036A1 | 4PX*BU36BS3 | *UHMB060ACV3 | 26,200 | $1,310 |
| No | 10153720 | TRANE | 4TWV8037A1 | TEM8A0B30V31+TDR | | 26,000 | $1,300 |
| No | 207526250 | TRANE | 4TWV8X36A1 | 4PX*CD36BS3 | *DD2C100ACV5 | 26,800 | $1,340 |
| No | 8759460 | TRANE | 4TWV8036A1 | 4PX*CD36BS3 | *DD2C100ACV5 | 26,800 | $1,340 |
| No | 207526239 | TRANE | 4TWV8X36A1 | 4PX*BD48BS3 | *DHMB080ACV3 | 27,200 | $1,360 |
| No | 8759444 | TRANE | 4TWV8036A1 | 4PX*BD48BS3 | *DHMB080ACV3 | 27,200 | $1,360 |
| No | 10511284 | TRANE | 4TWV8036A1 | 4TXCB004DS3 | S9V2B060D3PSB+RP | 25,400 | $1,270 |
| No | 10511282 | TRANE | 4TWV8036A1 | 4TXCB004DS3 | S9V2B080D4PSB+RP | 25,400 | $1,270 |
| No | 10511323 | TRANE | 4TWV8037A1 | 4TXCB004DS3 | S9V2B080D4PSB+RP | 25,400 | $1,270 |
| No | 205962314 | TRANE | 4TWV0036A1 | 4PX*BU42BS3 | P0V0A000M30SB+RP | 24,800 | $1,240 |
| No | 10511195 | TRANE | 4TWV0036A1 | 4TXCB004DS3 | S9V2B080D4PSB+RP | 25,400 | $1,270 |
| No | 205962363 | TRANE | 4TWV8037A1 | 4PX*BU42BS3 | P0V0A000M30SB+RP | 24,800 | $1,240 |
| No | 207526682 | TRANE | 4TWV0X36A1 | 4PX*BU42BS3 | P0V0A000M30SB+RP | 24,800 | $1,240 |
| No | 10511304 | TRANE | 4TWV8037A1 | 4PX*BD36BS3 | S9V2B080D4PSB+RP | 26,800 | $1,340 |
| No | 10511165 | TRANE | 4TWV0036A1 | 4PX*BD36BS3 | S9V2B080D4PSB+RP | 26,800 | $1,340 |
| No | 202586177 | TRANE | 4TWV8037A1 | 4PX*BD42BS3 | *DHMB060BCV3 | 26,000 | $1,300 |
| No | 207526221 | TRANE | 4TWV8X36A1 | 4TXFH036CZ3 | *UHMB080ACV3 | 25,200 | $1,260 |
| No | 6796632 | TRANE | 4TWV8036A1 | 4TXFH036CZ3 | *UHMB080ACV3 | 25,200 | $1,260 |
| No | 202586176 | TRANE | 4TWV8037A1 | 4PX*BD42BS3 | *DD2B080ACV3 | 25,800 | $1,290 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207526796 | TRANE | 4TWV0X36A1 | 4PX*BU42BS3 | P0V0A000M30SC+RP | 24,800 | $1,240 |
| No | 206912430 | TRANE | 4TWV0036A1 | 4PX*BU42BS3 | P0V0A000M30SC+RP | 24,800 | $1,240 |
| No | 207526559 | TRANE | 4TWV0X24A1 | 4TXCB003DS3 | P0V0A000M30SA+RP | 17,100 | $855 |
| No | 207526602 | TRANE | 4TWV8X24A1 | 4TXCB003DS3 | P0V0A000M30SA+RP | 17,100 | $855 |
| No | 204780389 | TRANE | 4TWV8024A1 | 4TXCB003DS3 | P0V0A000M30SA+RP | 17,100 | $855 |
| No | 204780346 | TRANE | 4TWV0024A1 | 4TXCB003DS3 | P0V0A000M30SA+RP | 17,100 | $855 |
| No | 10511238 | TRANE | 4TWV0060A1 | 4TXCD010DS3 | S9V2C080U5PSB+RP | 50,500 | $2,525 |
| No | 10511230 | TRANE | 4TWV0060A1 | 4PX*DU60BS3 | S9V2C080U5PSB+RP | 50,500 | $2,525 |
| No | 207526226 | TRANE | 4TWV8X36A1 | 4TXFH036CZ3 | *UHMB060ACV3 | 25,400 | $1,270 |
| No | 7125593 | TRANE | 4TWV8036A1 | 4TXFH036CZ3 | *UHMB060ACV3 | 25,400 | $1,270 |
| No | 8939391 | TRANE | 4TWV8037A1 | 4PX*CD48BS3 | *DHMC100ACV4 | 27,200 | $1,360 |
| No | 207558929 | TRANE | 4TWV0X24A1 | 4TXFH024CZ3 | *UHMB060ACV3 | 16,400 | $820 |
| No | 207526218 | TRANE | 4TWV8X24A1 | 4TXFH024CZ3 | *UHMB060ACV3 | 16,400 | $820 |
| No | 6796595 | TRANE | 4TWV0024A1 | 4TXFH024CZ3 | *UHMB060ACV3 | 16,400 | $820 |
| No | 6796622 | TRANE | 4TWV8024A1 | 4TXFH024CZ3 | *UHMB060ACV3 | 16,400 | $820 |
| No | 207526499 | TRANE | 4TWV8X60A1 | 4TXCD010DS3 | S9V2D120U5VSA+RP | 50,000 | $2,500 |
| No | 207526497 | TRANE | 4TWV8X60A1 | 4PX*DU60BS3 | S9V2D120U5VSA+RP | 50,000 | $2,500 |
| No | 207526450 | TRANE | 4TWV0X60A1 | 4TXCD010DS3 | S9V2D120U5VSA+RP | 50,000 | $2,500 |
| No | 207526448 | TRANE | 4TWV0X60A1 | 4PX*DU60BS3 | S9V2D120U5VSA+RP | 50,000 | $2,500 |
| No | 201808987 | TRANE | 4TWV8060A1 | 4PX*DU60BS3 | S9V2D120U5VSA+RP | 50,000 | $2,500 |
| No | 201808991 | TRANE | 4TWV8060A1 | 4TXCD010DS3 | S9V2D120U5VSA+RP | 50,000 | $2,500 |
| No | 10511447 | TRANE | 4TWV8060A1 | 4TXCD010DS3 | S9V2D120U5PSB+RP | 50,000 | $2,500 |
| No | 201808792 | TRANE | 4TWV0060A1 | 4PX*DU60BS3 | S9V2D120U5VSA+RP | 50,000 | $2,500 |
| No | 10511439 | TRANE | 4TWV8060A1 | 4PX*DU60BS3 | S9V2D120U5PSB+RP | 50,000 | $2,500 |
| No | 10511241 | TRANE | 4TWV0060A1 | 4TXCD010DS3 | S9V2D120U5PSB+RP | 50,000 | $2,500 |
| No | 206223106 | TRANE | 4TWV8X36A1 | TAMXA0C36V3PA |  | 24,800 | $1,240 |
| No | 201808798 | TRANE | 4TWV0060A1 | 4TXCD010DS3 | S9V2D120U5VSA+RP | 50,000 | $2,500 |
| No | 10511231 | TRANE | 4TWV0060A1 | 4PX*DU60BS3 | S9V2D120U5PSB+RP | 50,000 | $2,500 |
| No | 10511259 | TRANE | 4TWV8036A1 | 4PX*BD36BS3 | S9V2B080D3PSB+RP | 26,600 | $1,330 |
| No | 201808908 | TRANE | 4TWV8037A1 | 4TXCB004DS3 | S9V2B080D3VSA+RP | 25,400 | $1,270 |
| No | 10511325 | TRANE | 4TWV8037A1 | 4TXCB004DS3 | S9V2B080D3PSB+RP | 25,400 | $1,270 |
| No | 10511194 | TRANE | 4TWV0036A1 | 4TXCB004DS3 | S9V2B080D3PSB+RP | 25,400 | $1,270 |
| No | 207526426 | TRANE | 4TWV0X36A1 | 4TXCB004DS3 | S9V2B080D3VSA+RP | 25,400 | $1,270 |
| No | 10511188 | TRANE | 4TWV0036A1 | 4TXCB004DS3 | S9V2B060D3PSB+RP | 25,400 | $1,270 |
| No | 10511324 | TRANE | 4TWV8037A1 | 4TXCB004DS3 | S9V2B060D3PSB+RP | 25,400 | $1,270 |
| No | 205962355 | TRANE | 4TWV8036A1 | 4PX*BU42BS3 | P0V0A000M30SB+RP | 24,600 | $1,230 |
| No | 207526837 | TRANE | 4TWV8X36A1 | 4PX*BU42BS3 | P0V0A000M30SC+RP | 24,600 | $1,230 |
| No | 201808725 | TRANE | 4TWV0036A1 | 4TXCB004DS3 | S9V2B080D3VSA+RP | 25,400 | $1,270 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10511258 | TRANE | 4TWV8036A1 | 4PX*BD36BS3 | S9V2B080D4PSB+RP | 26,600 | $1,330 |
| No | 10511437 | TRANE | 4TWV8060A1 | 4PX*CU60BS3 | S9V2C080U5PSB+RP | 50,500 | $2,525 |
| No | 206912471 | TRANE | 4TWV8036A1 | 4PX*BU42BS3 | P0V0A000M30SC+RP | 24,600 | $1,230 |
| No | 10511444 | TRANE | 4TWV8060A1 | 4TXCC009DS3 | S9V2C080U5PSB+RP | 50,500 | $2,525 |
| No | 10511235 | TRANE | 4TWV0060A1 | 4TXCC009DS3 | S9V2C080U5PSB+RP | 50,500 | $2,525 |
| No | 207526723 | TRANE | 4TWV8X36A1 | 4PX*BU42BS3 | P0V0A000M30SB+RP | 24,600 | $1,230 |
| No | 10511228 | TRANE | 4TWV0060A1 | 4PX*CU60BS3 | S9V2C080U5PSB+RP | 50,500 | $2,525 |
| No | 210435407 | TRANE | 4TXM2130A14N0** | Heat pump without ducts | | 27,200 | $1,360 |
| No | 210435406 | TRANE | 4TXM2124A13N0** | Heat pump without ducts | | 23,600 | $1,180 |
| No | 210435405 | TRANE | 4TXM2118A12N0** | Heat pump without ducts | | 14,700 | $735 |
| No | 7151533 | TRANE | 4TXK2712A10NAA | 4MXW2712A10N0AA | | 8,000 | $400 |
| No | 207629147 | TRANE | 4TXK2536A10N0** | 4MXW2536A10N0** | | 22,600 | $1,130 |
| No | 10093511 | TRANE | 4TWV8048A1 | TAM9A0C48V41 | | 36,400 | $1,820 |
| No | 207629149 | TRANE | 4TXK2512A10N0** | 4MXW2512A10N0** | N/A | 7,700 | $385 |
| No | 207642981 | TRANE | 4TXK2518A10N0** | 4MXW2518A10N0** | N/A | 11,400 | $570 |
| No | 207629151 | TRANE | 4TXK2524A10N0** | 4MXW2524A10N0** | N/A | 15,500 | $775 |
| No | 8759538 | TRANE | 4TWV8049A1 | 4PX*CU60BS3 | *UHMC100ACV4 | 36,000 | $1,800 |
| No | 8761519 | TRANE | 4TWV8049A1 | 4TXCC009DS3 | *UHMC100ACV4 | 36,000 | $1,800 |
| No | 204780426 | TRANE | 4TWV8048A1 | 4PX*CD42BS3 | P0V0C000M50SA+RP | 36,200 | $1,810 |
| No | 207526623 | TRANE | 4TWV8X48A1 | 4PX*CD42BS3 | P0V0C000M50SA+RP | 36,200 | $1,810 |
| No | 205962411 | TRANE | 4TWV8049A1 | 4TXCD008DS3 | P0V0C000M50SB+RP | 34,800 | $1,740 |
| No | 8759427 | TRANE | 4TWV0048A1 | 4PX*CU60BS3 | *UD2C080ACV4 | 35,800 | $1,790 |
| No | 205962328 | TRANE | 4TWV0048A1 | 4PX*DU48BS3 | P0V0C000M50SB+RP | 34,800 | $1,740 |
| No | 207526696 | TRANE | 4TWV0X48A1 | 4PX*DU48BS3 | P0V0C000M50SB+RP | 34,800 | $1,740 |
| No | 207526312 | TRANE | 4TWV8X48A1 | 4TXCD010DS3 | *DHMC100ACV4 | 35,600 | $1,780 |
| No | 207526558 | TRANE | 4TWV0X48A1 | 4TXFH064AZ3 | *UHMC100ACV4 | 35,800 | $1,790 |
| No | 202492138 | TRANE | 4TWV0048A1 | 4PX*BU48BS3 | S9V2B080D4PSB+RP | 36,400 | $1,820 |
| No | 204506563 | TRANE | 4TWV0048A1 | 4TXFH064AZ3 | *UHMC100ACV4 | 35,800 | $1,790 |
| No | 207526541 | TRANE | 4TWV0X48A1 | 4PX*BU48BS3 | S9V2B080D4PSB+RP | 36,400 | $1,820 |
| No | 8939393 | TRANE | 4TWV8048A1 | 4TXCD010DS3 | *DHMC100ACV4 | 35,600 | $1,780 |
| No | 207526583 | TRANE | 4TWV0X48A1 | 4PX*CU42BS3 | P0V0C000M50SA+RP | 36,200 | $1,810 |
| No | 204780370 | TRANE | 4TWV0048A1 | 4PX*CU42BS3 | P0V0C000M50SA+RP | 36,200 | $1,810 |
| No | 204780454 | TRANE | 4TWV8049A1 | 4PX*CU42BS3 | P0V0C000M50SA+RP | 36,200 | $1,810 |
| No | 8761428 | TRANE | 4TWV0048A1 | 4TXCC009DS3 | *UHMC100ACV4 | 36,000 | $1,800 |
| No | 207559007 | TRANE | 4TWV0X48A1 | 4TXCC009DS3 | *UHMC100ACV4 | 36,000 | $1,800 |
| No | 202365941 | TRANE | 4TWV0048A1 | 4PX*CU48BS3 | S9V2C100D5PSB+RP | 35,400 | $1,770 |
| No | 204836634 | TRANE | 4TWV8048A1 | 4PX*CD48BS3 | P0V0C000M50SA+RP | 37,200 | $1,860 |
| No | 204836636 | TRANE | 4TWV8048A1 | 4PX*CD48BS3+HORIZ-RT | P0V0C000M50SA+RP | 37,200 | $1,860 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205962368 | TRANE | 4TWV8048A1 | 4PX*CD48BS3 | P0V0C000M50SB+RP | 37,200 | $1,860 |
| No | 205962369 | TRANE | 4TWV8048A1 | 4PX*CD48BS3+HORIZ-RT | P0V0C000M50SB+RP | 37,200 | $1,860 |
| No | 207526657 | TRANE | 4TWV8X48A1 | 4PX*CD48BS3 | P0V0C000M50SA+RP | 37,200 | $1,860 |
| No | 207526658 | TRANE | 4TWV8X48A1 | 4PX*CD48BS3+HORIZ-RT | P0V0C000M50SA+RP | 37,200 | $1,860 |
| No | 207526727 | TRANE | 4TWV8X48A1 | 4PX*CD48BS3 | P0V0C000M50SB+RP | 37,200 | $1,860 |
| No | 207526728 | TRANE | 4TWV8X48A1 | 4PX*CD48BS3+HORIZ-RT | P0V0C000M50SB+RP | 37,200 | $1,860 |
| No | 10511405 | TRANE | 4TWV8049A1 | 4PX*DU48BS3 | S9V2B080U4PSB+RP | 36,800 | $1,840 |
| No | 10511425 | TRANE | 4TWV8049A1 | 4TXCD008DS3 | S9V2B080U4PSB+RP | 36,800 | $1,840 |
| No | 10511215 | TRANE | 4TWV0048A1 | 4TXCB006DS3 | S9V2B080D4PSB+RP | 35,400 | $1,770 |
| No | 10511412 | TRANE | 4TWV8049A1 | 4TXCB006DS3 | S9V2B080D4PSB+RP | 35,400 | $1,770 |
| No | 206910667 | TRANE | 4TWV0048A1 | 4PX*CD60BS3 | S9V2C100D5PSBC+RP | 35,600 | $1,780 |
| No | 207526779 | TRANE | 4TWV0X48A1 | 4PX*CD60BS3 | S9V2C100D5PSBC+RP | 35,600 | $1,780 |
| No | 8759428 | TRANE | 4TWV0048A1 | 4PX*DU60BS3 | *UHMC100ACV4 | 35,800 | $1,790 |
| No | 207558984 | TRANE | 4TWV0X48A1 | 4PX*DU60BS3 | *UHMC100ACV4 | 35,800 | $1,790 |
| No | 9119413 | TRANE | 4TWV8048A1 | 4PX*DD60BS3 | *DD2C100ACV5 | 36,400 | $1,820 |
| No | 8759429 | TRANE | 4TWV0048A1 | 4PX*DU60BS3 | *UHMD120ACV5 | 36,400 | $1,820 |
| No | 207526317 | TRANE | 4TWV8X48A1 | 4PX*DD60BS3 | *DD2C100ACV5 | 36,400 | $1,820 |
| No | 206910673 | TRANE | 4TWV0048A1 | 4TXCD010DS3 | S9V2C100U5PSBC+RP | 34,200 | $1,710 |
| No | 206910670 | TRANE | 4TWV0048A1 | 4PX*DU60BS3 | S9V2C100U5PSBC+RP | 34,200 | $1,710 |
| No | 207526782 | TRANE | 4TWV0X48A1 | 4PX*DU60BS3 | S9V2C100U5PSBC+RP | 34,200 | $1,710 |
| No | 207526785 | TRANE | 4TWV0X48A1 | 4TXCD010DS3 | S9V2C100U5PSBC+RP | 34,200 | $1,710 |
| No | 10511205 | TRANE | 4TWV0048A1 | 4PX*BU48BS3 | S9V2B080U4PSB+RP | 37,200 | $1,860 |
| No | 10511214 | TRANE | 4TWV0048A1 | 4TXCB006DS3 | S9V2B080U4PSB+RP | 37,200 | $1,860 |
| No | 10511389 | TRANE | 4TWV8049A1 | 4PX*BU48BS3 | S9V2B080U4PSB+RP | 37,200 | $1,860 |
| No | 10511410 | TRANE | 4TWV8049A1 | 4TXCB006DS3 | S9V2B080U4PSB+RP | 37,200 | $1,860 |
| No | 10153728 | TRANE | 4TWV8048A1 | TEM8A0C48V41+TDR | | 34,200 | $1,710 |
| No | 10153726 | TRANE | 4TWV8048A1 | TEM8A0C42V41+TDR | | 36,000 | $1,800 |
| No | 8759425 | TRANE | 4TWV0048A1 | 4PX*CU60BS3 | *UHMC100ACV4 | 36,000 | $1,800 |
| No | 207558982 | TRANE | 4TWV0X48A1 | 4PX*CU60BS3 | *UHMC100ACV4 | 36,000 | $1,800 |
| No | 9119411 | TRANE | 4TWV8048A1 | 4PX*DD60BS3 | *DHMD120BCV5 | 36,400 | $1,820 |
| No | 207526315 | TRANE | 4TWV8X48A1 | 4PX*DD60BS3 | *DHMD120BCV5 | 36,400 | $1,820 |
| No | 10093510 | TRANE | 4TWV8048A1 | TAM9A0C42V41 | | 36,200 | $1,810 |
| No | 10511403 | TRANE | 4TWV8049A1 | 4PX*DD60BS3 | S9V2C100D5PSB+RP | 35,000 | $1,750 |
| No | 207526333 | TRANE | 4TWV8X48A1 | TAM9A0C42V41 | | 36,200 | $1,810 |
| No | 204340748 | TRANE | 4TWV0048A1 | 4TXFH064AZ3 | *UD2C080ACV4 | 36,200 | $1,810 |
| No | 206910668 | TRANE | 4TWV0048A1 | 4PX*CU48BS3 | S9V2C100U5PSBC+RP | 35,800 | $1,790 |
| No | 207526783 | TRANE | 4TWV0X48A1 | 4TXCC007DS3 | S9V2C100U5PSBC+RP | 35,800 | $1,790 |
| No | 206910671 | TRANE | 4TWV0048A1 | 4TXCC007DS3 | S9V2C100U5PSBC+RP | 35,800 | $1,790 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207526780 | TRANE | 4TWV0X48A1 | 4PX*CU48BS3 | S9V2C100U5PSBC+RP | 35,800 | $1,790 |
| No | 10511402 | TRANE | 4TWV8049A1 | 4PX*DD60BS3 | S9V2C100D4PSB+RP | 35,000 | $1,750 |
| No | 201808761 | TRANE | 4TWV0048A1 | 4PX*DD60BS3 | S9V2C100D4VSA+RP | 35,000 | $1,750 |
| No | 201808967 | TRANE | 4TWV8049A1 | 4PX*DD60BS3 | S9V2C100D4VSA+RP | 35,000 | $1,750 |
| No | 10511340 | TRANE | 4TWV8048A1 | 4PX*BD48BS3 | S9V2B080D4PSB+RP | 39,000 | $1,950 |
| No | 10511404 | TRANE | 4TWV8049A1 | 4PX*DU48BS3 | S9V2B060U4PSB+RP | 36,800 | $1,840 |
| No | 10511427 | TRANE | 4TWV8049A1 | 4TXCD008DS3 | S9V2B060U4PSB+RP | 36,800 | $1,840 |
| No | 205962318 | TRANE | 4TWV0048A1 | 4PX*CD60BS3 | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 205962380 | TRANE | 4TWV8048A1 | 4PX*DD60BS3 | P0V0C000M50SB+RP | 34,600 | $1,730 |
| No | 205962319 | TRANE | 4TWV0048A1 | 4PX*CD60BS3+HORIZ-RT | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 205962382 | TRANE | 4TWV8048A1 | 4PX*DD60BS3+HORIZ-RT | P0V0C000M50SB+RP | 34,600 | $1,730 |
| No | 205962395 | TRANE | 4TWV8049A1 | 4PX*CD60BS3 | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 207526687 | TRANE | 4TWV0X48A1 | 4PX*CD60BS3+HORIZ-RT | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 205962396 | TRANE | 4TWV8049A1 | 4PX*CD60BS3+HORIZ-RT | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 207526686 | TRANE | 4TWV0X48A1 | 4PX*CD60BS3 | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 207526739 | TRANE | 4TWV8X48A1 | 4PX*DD60BS3 | P0V0C000M50SB+RP | 34,600 | $1,730 |
| No | 207526741 | TRANE | 4TWV8X48A1 | 4PX*DD60BS3+HORIZ-RT | P0V0C000M50SB+RP | 34,600 | $1,730 |
| No | 205962377 | TRANE | 4TWV8048A1 | 4PX*DD48BS3+HORIZ-RT | P0V0D000M50SB+RP | 37,000 | $1,850 |
| No | 205962375 | TRANE | 4TWV8048A1 | 4PX*DD48BS3 | P0V0D000M50SB+RP | 37,000 | $1,850 |
| No | 207526736 | TRANE | 4TWV8X48A1 | 4PX*DD48BS3+HORIZ-RT | P0V0D000M50SB+RP | 37,000 | $1,850 |
| No | 207526734 | TRANE | 4TWV8X48A1 | 4PX*DD48BS3 | P0V0D000M50SB+RP | 37,000 | $1,850 |
| No | 202365944 | TRANE | 4TWV0048A1 | 4PX*DU60BS3 | *DD2D120ACV5 | 34,600 | $1,730 |
| No | 207526510 | TRANE | 4TWV0X48A1 | 4PX*DU60BS3 | *DD2D120ACV5 | 34,600 | $1,730 |
| No | 206918571 | TRANE | 4TWV8048A1 | TEM6A0C42H41+TDR+RP | | 35,600 | $1,780 |
| No | 207526888 | TRANE | 4TWV8X48A1 | TEM6A0C42H41+TDR+RP | | 35,600 | $1,780 |
| No | 202365940 | TRANE | 4TWV0048A1 | 4PX*CU48BS3 | S9V2C100D4PSB+RP | 36,000 | $1,800 |
| No | 202365943 | TRANE | 4TWV0048A1 | 4PX*DU48BS3 | S9V2D120D5PSB+RP | 35,600 | $1,780 |
| No | 207559014 | TRANE | 4TWV0X48A1 | 4TXCD010DS3 | *DD2D120ACV5 | 34,400 | $1,720 |
| No | 8761435 | TRANE | 4TWV0048A1 | 4TXCD010DS3 | *DD2D120ACV5 | 34,400 | $1,720 |
| No | 201808746 | TRANE | 4TWV0048A1 | 4PX*CD60BS3 | S9V2C100D4VSA+RP | 36,400 | $1,820 |
| No | 10511206 | TRANE | 4TWV0048A1 | 4PX*CD60BS3 | S9V2C100D4PSB+RP | 36,400 | $1,820 |
| No | 10511392 | TRANE | 4TWV8049A1 | 4PX*CD60BS3 | S9V2C100D4PSB+RP | 36,400 | $1,820 |
| No | 201808957 | TRANE | 4TWV8049A1 | 4PX*CD60BS3 | S9V2C100D4VSA+RP | 36,400 | $1,820 |
| No | 10511356 | TRANE | 4TWV8048A1 | 4PX*DD48BS3 | S9V2D120D5PSB+RP | 38,000 | $1,900 |
| No | 201808923 | TRANE | 4TWV8048A1 | 4PX*CD48BS3 | S9V2C100D4VSA+RP | 38,500 | $1,925 |
| No | 10511344 | TRANE | 4TWV8048A1 | 4PX*CD48BS3 | S9V2C100D4PSB+RP | 38,500 | $1,925 |
| No | 207526479 | TRANE | 4TWV8X48A1 | 4PX*CD48BS3 | S9V2C100D4VSA+RP | 38,500 | $1,925 |
| No | 204836642 | TRANE | 4TWV8048A1 | 4PX*DD48BS3+HORIZ-RT | P0V0D000M50SA+RP | 37,200 | $1,860 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204836640 | TRANE | 4TWV8048A1 | 4PX*DD48BS3 | P0V0D000M50SA+RP | 37,200 | $1,860 |
| No | 207526660 | TRANE | 4TWV8X48A1 | 4PX*DD48BS3 | P0V0D000M50SA+RP | 37,200 | $1,860 |
| No | 207526661 | TRANE | 4TWV8X48A1 | 4PX*DD48BS3+HORIZ-RT | P0V0D000M50SA+RP | 37,200 | $1,860 |
| No | 205962321 | TRANE | 4TWV0048A1 | 4PX*CU48BS3 | P0V0C000M50SB+RP | 35,800 | $1,790 |
| No | 205962324 | TRANE | 4TWV0048A1 | 4PX*DD60BS3 | P0V0D000M50SB+RP | 35,000 | $1,750 |
| No | 204780424 | TRANE | 4TWV8048A1 | 4PX*BU42BS3 | P0V0B000M40SA+RP | 35,000 | $1,750 |
| No | 205962400 | TRANE | 4TWV8049A1 | 4PX*DD60BS3 | P0V0D000M50SB+RP | 35,000 | $1,750 |
| No | 205962403 | TRANE | 4TWV8049A1 | 4PX*DD60BS3+HORIZ-RT | P0V0D000M50SB+RP | 35,000 | $1,750 |
| No | 207526692 | TRANE | 4TWV0X48A1 | 4PX*DD60BS3 | P0V0D000M50SB+RP | 35,000 | $1,750 |
| No | 205962332 | TRANE | 4TWV0048A1 | 4TXCC007DS3 | P0V0C000M50SB+RP | 35,800 | $1,790 |
| No | 207526621 | TRANE | 4TWV8X48A1 | 4PX*BU42BS3 | P0V0B000M40SA+RP | 35,000 | $1,750 |
| No | 205962398 | TRANE | 4TWV8049A1 | 4PX*CU48BS3 | P0V0C000M50SB+RP | 35,800 | $1,790 |
| No | 205962409 | TRANE | 4TWV8049A1 | 4TXCC007DS3 | P0V0C000M50SB+RP | 35,800 | $1,790 |
| No | 207526689 | TRANE | 4TWV0X48A1 | 4PX*CU48BS3 | P0V0C000M50SB+RP | 35,800 | $1,790 |
| No | 207526700 | TRANE | 4TWV0X48A1 | 4TXCC007DS3 | P0V0C000M50SB+RP | 35,800 | $1,790 |
| No | 10511207 | TRANE | 4TWV0048A1 | 4PX*CU48BS3 | S9V2C080U5PSB+RP | 36,600 | $1,830 |
| No | 10511218 | TRANE | 4TWV0048A1 | 4TXCC007DS3 | S9V2C080U5PSB+RP | 36,600 | $1,830 |
| No | 10511417 | TRANE | 4TWV8049A1 | 4TXCC007DS3 | S9V2C080U5PSB+RP | 36,600 | $1,830 |
| No | 10511393 | TRANE | 4TWV8049A1 | 4PX*CU48BS3 | S9V2C080U5PSB+RP | 36,600 | $1,830 |
| No | 204780368 | TRANE | 4TWV0048A1 | 4PX*CD60BS3 | P0V0C000M50SA+RP | 35,600 | $1,780 |
| No | 204780369 | TRANE | 4TWV0048A1 | 4PX*CD60BS3+HORIZ-RT | P0V0C000M50SA+RP | 35,600 | $1,780 |
| No | 204780452 | TRANE | 4TWV8049A1 | 4PX*CD60BS3 | P0V0C000M50SA+RP | 35,600 | $1,780 |
| No | 204780453 | TRANE | 4TWV8049A1 | 4PX*CD60BS3+HORIZ-RT | P0V0C000M50SA+RP | 35,600 | $1,780 |
| No | 207526581 | TRANE | 4TWV0X48A1 | 4PX*CD60BS3 | P0V0C000M50SA+RP | 35,600 | $1,780 |
| No | 207526582 | TRANE | 4TWV0X48A1 | 4PX*CD60BS3+HORIZ-RT | P0V0C000M50SA+RP | 35,600 | $1,780 |
| No | 204780435 | TRANE | 4TWV8048A1 | 4PX*DD60BS3+HORIZ-RT | P0V0C000M50SA+RP | 34,800 | $1,740 |
| No | 204780432 | TRANE | 4TWV8048A1 | 4PX*DD60BS3 | P0V0C000M50SA+RP | 34,800 | $1,740 |
| No | 207526629 | TRANE | 4TWV8X48A1 | 4PX*DD60BS3 | P0V0C000M50SA+RP | 34,800 | $1,740 |
| No | 207526632 | TRANE | 4TWV8X48A1 | 4PX*DD60BS3+HORIZ-RT | P0V0C000M50SA+RP | 34,800 | $1,740 |
| No | 10511358 | TRANE | 4TWV8048A1 | 4PX*DD60BS3 | S9V2C100D4PSB+RP | 35,600 | $1,780 |
| No | 201808937 | TRANE | 4TWV8048A1 | 4PX*DD60BS3 | S9V2C100D4VSA+RP | 35,600 | $1,780 |
| No | 8759519 | TRANE | 4TWV8048A1 | 4PX*CU48BS3 | *UHMC100ACV4 | 37,200 | $1,860 |
| No | 207526266 | TRANE | 4TWV8X48A1 | 4PX*CU48BS3 | *UHMC100ACV4 | 37,200 | $1,860 |
| No | 10511217 | TRANE | 4TWV0048A1 | 4TXCC007DS3 | S9V2C100D4PSB+RP | 35,200 | $1,760 |
| No | 207526442 | TRANE | 4TWV0X48A1 | 4TXCC007DS3 | S9V2C100U4VSA+RP | 37,000 | $1,850 |
| No | 10511416 | TRANE | 4TWV8049A1 | 4TXCC007DS3 | S9V2C100D4PSB+RP | 35,200 | $1,760 |
| No | 10511222 | TRANE | 4TWV0048A1 | 4TXCD008DS3 | S9V2D120D5PSB+RP | 35,000 | $1,750 |
| No | 10511428 | TRANE | 4TWV8049A1 | 4TXCD008DS3 | S9V2D120D5PSB+RP | 35,000 | $1,750 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204780479 | TRANE | 4TWV8049A1 | 4TXCC007DS3 | P0V0C000M50SA+RP | 36,000 | $1,800 |
| No | 204780373 | TRANE | 4TWV0048A1 | 4PX*DD60BS3 | P0V0D000M50SA+RP | 35,200 | $1,760 |
| No | 10511396 | TRANE | 4TWV8049A1 | 4PX*CU48BS3 | S9V2D120U5PSB+RP | 36,800 | $1,840 |
| No | 204780457 | TRANE | 4TWV8049A1 | 4PX*DD60BS3 | P0V0D000M50SA+RP | 35,200 | $1,760 |
| No | 204780460 | TRANE | 4TWV8049A1 | 4PX*DD60BS3+HORIZ-RT | P0V0D000M50SA+RP | 35,200 | $1,760 |
| No | 207526586 | TRANE | 4TWV0X48A1 | 4PX*DD60BS3 | P0V0D000M50SA+RP | 35,200 | $1,760 |
| No | 10511426 | TRANE | 4TWV8049A1 | 4TXCD008DS3 | S9V2C100D4PSB+RP | 35,200 | $1,760 |
| No | 201808752 | TRANE | 4TWV0048A1 | 4PX*CU48BS3 | S9V2D120U5VSA+RP | 36,800 | $1,840 |
| No | 10511413 | TRANE | 4TWV8049A1 | 4TXCC007DS3 | S9V2D120U5PSB+RP | 36,800 | $1,840 |
| No | 201808770 | TRANE | 4TWV0048A1 | 4TXCC007DS3 | S9V2D120U5VSA+RP | 36,800 | $1,840 |
| No | 201808961 | TRANE | 4TWV8049A1 | 4PX*CU48BS3 | S9V2D120U5VSA+RP | 36,800 | $1,840 |
| No | 201808975 | TRANE | 4TWV8049A1 | 4TXCC007DS3 | S9V2D120U5VSA+RP | 36,800 | $1,840 |
| No | 207526435 | TRANE | 4TWV0X48A1 | 4PX*CU48BS3 | S9V2D120U5VSA+RP | 36,800 | $1,840 |
| No | 207526441 | TRANE | 4TWV0X48A1 | 4TXCC007DS3 | S9V2D120U5VSA+RP | 36,800 | $1,840 |
| No | 10511343 | TRANE | 4TWV8048A1 | 4PX*CD48BS3 | S9V2C100D5PSB+RP | 38,500 | $1,925 |
| No | 8759518 | TRANE | 4TWV8048A1 | 4PX*CU48BS3 | *UD2C100ACV5 | 37,200 | $1,860 |
| No | 8759525 | TRANE | 4TWV8048A1 | 4PX*CU60BS3 | *UD2C080ACV4 | 36,400 | $1,820 |
| No | 207526638 | TRANE | 4TWV8X48A1 | 4TXCC005DS3 | P0V0C000M50SA+RP | 36,000 | $1,800 |
| No | 204780441 | TRANE | 4TWV8048A1 | 4TXCC005DS3 | P0V0C000M50SA+RP | 36,000 | $1,800 |
| No | 205962387 | TRANE | 4TWV8048A1 | 4TXCC005DS3 | P0V0C000M50SB+RP | 36,000 | $1,800 |
| No | 207526746 | TRANE | 4TWV8X48A1 | 4TXCC005DS3 | P0V0C000M50SB+RP | 36,000 | $1,800 |
| No | 10511418 | TRANE | 4TWV8049A1 | 4TXCC007DS3 | S9V2C100D5PSB+RP | 35,200 | $1,760 |
| No | 204780378 | TRANE | 4TWV0048A1 | 4PX*DU48BS3 | P0V0D000M50SA+RP | 35,800 | $1,790 |
| No | 205962327 | TRANE | 4TWV0048A1 | 4PX*DU48BS3 | P0V0D000M50SB+RP | 35,800 | $1,790 |
| No | 205962334 | TRANE | 4TWV0048A1 | 4TXCD008DS3 | P0V0D000M50SB+RP | 35,800 | $1,790 |
| No | 205962404 | TRANE | 4TWV8049A1 | 4PX*DU48BS3 | P0V0D000M50SB+RP | 35,800 | $1,790 |
| No | 207526591 | TRANE | 4TWV0X48A1 | 4PX*DU48BS3 | P0V0D000M50SA+RP | 35,800 | $1,790 |
| No | 207526695 | TRANE | 4TWV0X48A1 | 4PX*DU48BS3 | P0V0D000M50SB+RP | 35,800 | $1,790 |
| No | 205962412 | TRANE | 4TWV8049A1 | 4TXCD008DS3 | P0V0D000M50SB+RP | 35,800 | $1,790 |
| No | 207526702 | TRANE | 4TWV0X48A1 | 4TXCD008DS3 | P0V0D000M50SB+RP | 35,800 | $1,790 |
| No | 204780427 | TRANE | 4TWV8048A1 | 4PX*CD60BS3 | P0V0C000M50SA+RP | 35,800 | $1,790 |
| No | 204780428 | TRANE | 4TWV8048A1 | 4PX*CD60BS3+HORIZ-RT | P0V0C000M50SA+RP | 35,800 | $1,790 |
| No | 205962371 | TRANE | 4TWV8048A1 | 4PX*CD60BS3+HORIZ-RT | P0V0C000M50SB+RP | 35,800 | $1,790 |
| No | 205962370 | TRANE | 4TWV8048A1 | 4PX*CD60BS3 | P0V0C000M50SB+RP | 35,800 | $1,790 |
| No | 207526625 | TRANE | 4TWV8X48A1 | 4PX*CD60BS3+HORIZ-RT | P0V0C000M50SA+RP | 35,800 | $1,790 |
| No | 207526624 | TRANE | 4TWV8X48A1 | 4PX*CD60BS3 | P0V0C000M50SA+RP | 35,800 | $1,790 |
| No | 207526729 | TRANE | 4TWV8X48A1 | 4PX*CD60BS3 | P0V0C000M50SB+RP | 35,800 | $1,790 |
| No | 207526730 | TRANE | 4TWV8X48A1 | 4PX*CD60BS3+HORIZ-RT | P0V0C000M50SB+RP | 35,800 | $1,790 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 8759515 | TRANE | 4TWV8048A1 | 4PX*CD60BS3 | *DD2C100ACV5 | 36,800 | $1,840 |
| No | 207526263 | TRANE | 4TWV8X48A1 | 4PX*CD60BS3 | *DD2C100ACV5 | 36,800 | $1,840 |
| No | 10511419 | TRANE | 4TWV8049A1 | 4TXCC007DS3 | S9V2D120D5PSB+RP | 35,200 | $1,760 |
| No | 8759526 | TRANE | 4TWV8048A1 | 4PX*CU60BS3 | *UHMC100ACV4 | 36,600 | $1,830 |
| No | 207526271 | TRANE | 4TWV8X48A1 | 4PX*CU60BS3 | *UHMC100ACV4 | 36,600 | $1,830 |
| No | 8761497 | TRANE | 4TWV8048A1 | 4TXCC007DS3 | *UD2C100ACV5 | 37,200 | $1,860 |
| No | 205962326 | TRANE | 4TWV0048A1 | 4PX*DD60BS3+HORIZ-RT | P0V0D000M50SB+RP | 35,400 | $1,770 |
| No | 204780375 | TRANE | 4TWV0048A1 | 4PX*DD60BS3+HORIZ-RT | P0V0D000M50SA+RP | 35,400 | $1,770 |
| No | 205962383 | TRANE | 4TWV8048A1 | 4PX*DU48BS3 | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 207526588 | TRANE | 4TWV0X48A1 | 4PX*DD60BS3+HORIZ-RT | P0V0D000M50SA+RP | 35,400 | $1,770 |
| No | 205962391 | TRANE | 4TWV8048A1 | 4TXCD008DS3 | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 207526694 | TRANE | 4TWV0X48A1 | 4PX*DD60BS3+HORIZ-RT | P0V0D000M50SB+RP | 35,400 | $1,770 |
| No | 207526742 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3 | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 207526750 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 9119410 | TRANE | 4TWV8048A1 | 4PX*DD60BS3 | *DD2D120ACV5 | 36,800 | $1,840 |
| No | 207526293 | TRANE | 4TWV8X48A1 | 4TXCC007DS3 | *UHMC100ACV4 | 37,200 | $1,860 |
| No | 202492154 | TRANE | 4TWV8048A1 | 4PX*BU48BS3 | S9V2B080D4PSB+RP | 36,800 | $1,840 |
| No | 8761498 | TRANE | 4TWV8048A1 | 4TXCC007DS3 | *UHMC100ACV4 | 37,200 | $1,860 |
| No | 207526784 | TRANE | 4TWV0X48A1 | 4TXCC009DS3 | S9V2C100U5PSBC+RP | 35,600 | $1,780 |
| No | 10511424 | TRANE | 4TWV8049A1 | 4TXCD008DS3 | S9V2C100D5PSB+RP | 35,200 | $1,760 |
| No | 206910669 | TRANE | 4TWV0048A1 | 4PX*CU60BS3 | S9V2C100U5PSBC+RP | 35,600 | $1,780 |
| No | 206910672 | TRANE | 4TWV0048A1 | 4TXCC009DS3 | S9V2C100U5PSBC+RP | 35,600 | $1,780 |
| No | 207526781 | TRANE | 4TWV0X48A1 | 4PX*CU60BS3 | S9V2C100U5PSBC+RP | 35,600 | $1,780 |
| No | 204780425 | TRANE | 4TWV8048A1 | 4PX*BU48BS3 | P0V0B000M40SA+RP | 37,000 | $1,850 |
| No | 207526622 | TRANE | 4TWV8X48A1 | 4PX*BU48BS3 | P0V0B000M40SA+RP | 37,000 | $1,850 |
| No | 207526272 | TRANE | 4TWV8X48A1 | 4PX*CU60BS3 | *UD2D120ACV5 | 36,600 | $1,830 |
| No | 10511341 | TRANE | 4TWV8048A1 | 4PX*BU48BS3 | S9V2B080U4PSB+RP | 37,800 | $1,890 |
| No | 10511365 | TRANE | 4TWV8048A1 | 4TXCB006DS3 | S9V2B080U4PSB+RP | 37,800 | $1,890 |
| No | 8759527 | TRANE | 4TWV8048A1 | 4PX*CU60BS3 | *UD2D120ACV5 | 36,600 | $1,830 |
| No | 8761500 | TRANE | 4TWV8048A1 | 4TXCC007DS3 | *UD2C080ACV4 | 37,600 | $1,880 |
| No | 8759521 | TRANE | 4TWV8048A1 | 4PX*CU48BS3 | *UD2C080ACV4 | 37,600 | $1,880 |
| No | 10511210 | TRANE | 4TWV0048A1 | 4PX*DD60BS3 | S9V2D120D5PSB+RP | 36,200 | $1,810 |
| No | 10511401 | TRANE | 4TWV8049A1 | 4PX*DD60BS3 | S9V2D120D5PSB+RP | 36,200 | $1,810 |
| No | 8759522 | TRANE | 4TWV8048A1 | 4PX*CU48BS3 | *UD2D120ACV5 | 37,600 | $1,880 |
| No | 207526268 | TRANE | 4TWV8X48A1 | 4PX*CU48BS3 | *UD2D120ACV5 | 37,600 | $1,880 |
| No | 8759523 | TRANE | 4TWV8048A1 | 4PX*CU60BS3 | *UD2C100ACV5 | 36,600 | $1,830 |
| No | 10511367 | TRANE | 4TWV8048A1 | 4TXCB006DS3 | S9V2B080D4PSB+RP | 36,000 | $1,800 |
| No | 8761503 | TRANE | 4TWV8048A1 | 4TXCC009DS3 | *UD2C080ACV4 | 36,400 | $1,820 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205962333 | TRANE | 4TWV0048A1 | 4TXCC009DS3 | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 205962410 | TRANE | 4TWV8049A1 | 4TXCC009DS3 | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 207526690 | TRANE | 4TWV0X48A1 | 4PX*CU60BS3 | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 205962322 | TRANE | 4TWV0048A1 | 4PX*CU60BS3 | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 207526701 | TRANE | 4TWV0X48A1 | 4TXCC009DS3 | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 205962399 | TRANE | 4TWV8049A1 | 4PX*CU60BS3 | P0V0C000M50SB+RP | 35,400 | $1,770 |
| No | 8759530 | TRANE | 4TWV8048A1 | 4PX*DU60BS3 | *UHMD120ACV5 | 37,200 | $1,860 |
| No | 8233839 | TRANE | 4TWV8048A1 | 4TXFH064AZ3 | *UHMD120ACV5 | 37,600 | $1,880 |
| No | 207526228 | TRANE | 4TWV8X48A1 | 4TXFH064AZ3 | *UHMD120ACV5 | 37,600 | $1,880 |
| No | 205962372 | TRANE | 4TWV8048A1 | 4PX*CU42BS3 | P0V0C000M50SB+RP | 36,800 | $1,840 |
| No | 8761514 | TRANE | 4TWV8048A1 | 4TXCD010DS3 | *UHMD120ACV5 | 37,200 | $1,860 |
| No | 207526731 | TRANE | 4TWV8X48A1 | 4PX*CU42BS3 | P0V0C000M50SB+RP | 36,800 | $1,840 |
| No | 8761505 | TRANE | 4TWV8048A1 | 4TXCC009DS3 | *UHMC100ACV4 | 36,600 | $1,830 |
| No | 207526297 | TRANE | 4TWV8X48A1 | 4TXCC009DS3 | *UHMC100ACV4 | 36,600 | $1,830 |
| No | 10511360 | TRANE | 4TWV8048A1 | 4PX*DD60BS3 | S9V2C100D5PSB+RP | 36,000 | $1,800 |
| No | 8233838 | TRANE | 4TWV8048A1 | 4TXFH064AZ3 | *UHMC100ACV4 | 37,000 | $1,850 |
| No | 207526227 | TRANE | 4TWV8X48A1 | 4TXFH064AZ3 | *UHMC100ACV4 | 37,000 | $1,850 |
| No | 201808786 | TRANE | 4TWV0048A1 | 4TXCD010DS3 | S9V2C100U4VSA+RP | 36,400 | $1,820 |
| No | 10511225 | TRANE | 4TWV0048A1 | 4TXCD010DS3 | S9V2C100U4PSB+RP | 36,400 | $1,820 |
| No | 10511212 | TRANE | 4TWV0048A1 | 4PX*DU60BS3 | S9V2C100U4PSB+RP | 36,400 | $1,820 |
| No | 10511430 | TRANE | 4TWV8049A1 | 4TXCD010DS3 | S9V2C100U4PSB+RP | 36,400 | $1,820 |
| No | 10511407 | TRANE | 4TWV8049A1 | 4PX*DU60BS3 | S9V2C100U4PSB+RP | 36,400 | $1,820 |
| No | 201808968 | TRANE | 4TWV8049A1 | 4PX*DU60BS3 | S9V2C100U4VSA+RP | 36,400 | $1,820 |
| No | 201808764 | TRANE | 4TWV0048A1 | 4PX*DU60BS3 | S9V2C100U4VSA+RP | 36,400 | $1,820 |
| No | 201808981 | TRANE | 4TWV8049A1 | 4TXCD010DS3 | S9V2C100U4VSA+RP | 36,400 | $1,820 |
| No | 202365955 | TRANE | 4TWV8048A1 | 4PX*CU48BS3 | S9V2C100D4PSB+RP | 36,200 | $1,810 |
| No | 10511366 | TRANE | 4TWV8048A1 | 4TXCB006DS3 | S9V2B060U4PSB+RP | 37,800 | $1,890 |
| No | 10511342 | TRANE | 4TWV8048A1 | 4PX*BU48BS3 | S9V2B060U4PSB+RP | 37,800 | $1,890 |
| No | 207599982 | TRANE | 4TWV8X48A1 | 4PX*BU48BS3 | S9V2B060U4PSB+RP | 37,800 | $1,890 |
| No | 207599986 | TRANE | 4TWV8X48A1 | 4TXCB006DS3 | S9V2B060U4PSB+RP | 37,800 | $1,890 |
| No | 205962392 | TRANE | 4TWV8048A1 | 4TXCD010DS3 | P0V0C000M50SB+RP | 35,000 | $1,750 |
| No | 207526751 | TRANE | 4TWV8X48A1 | 4TXCD010DS3 | P0V0C000M50SB+RP | 35,000 | $1,750 |
| No | 205962386 | TRANE | 4TWV8048A1 | 4PX*DU60BS3 | P0V0C000M50SB+RP | 35,000 | $1,750 |
| No | 207526745 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | P0V0C000M50SB+RP | 35,000 | $1,750 |
| No | 10093515 | TRANE | 4TWV8049A1 | TAM9A0C60V51 | | 35,600 | $1,780 |
| No | 10093500 | TRANE | 4TWV0048A1 | TAM9A0C60V51 | | 35,600 | $1,780 |
| No | 10511400 | TRANE | 4TWV8049A1 | 4PX*CU60BS3 | S9V2D120U5PSB+RP | 36,400 | $1,820 |
| No | 10511397 | TRANE | 4TWV8049A1 | 4PX*CU60BS3 | S9V2C080U5PSB+RP | 36,400 | $1,820 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206223109 | TRANE | 4TWV8X48A1 | TAMXA0C60V5PA | | 35,200 | $1,760 |
| No | 10511421 | TRANE | 4TWV8049A1 | 4TXCC009DS3 | S9V2D120U5PSB+RP | 36,400 | $1,820 |
| No | 202365958 | TRANE | 4TWV8048A1 | 4PX*DU48BS3 | S9V2D120D5PSB+RP | 36,000 | $1,800 |
| No | 10511422 | TRANE | 4TWV8049A1 | 4TXCC009DS3 | S9V2C080U5PSB+RP | 36,400 | $1,820 |
| No | 201808758 | TRANE | 4TWV0048A1 | 4PX*CU60BS3 | S9V2D120U5VSA+RP | 36,400 | $1,820 |
| No | 201808779 | TRANE | 4TWV0048A1 | 4TXCC009DS3 | S9V2D120U5VSA+RP | 36,400 | $1,820 |
| No | 201808979 | TRANE | 4TWV8049A1 | 4TXCC009DS3 | S9V2D120U5VSA+RP | 36,400 | $1,820 |
| No | 201808965 | TRANE | 4TWV8049A1 | 4PX*CU60BS3 | S9V2D120U5VSA+RP | 36,400 | $1,820 |
| No | 207526437 | TRANE | 4TWV0X48A1 | 4PX*CU60BS3 | S9V2D120U5VSA+RP | 36,400 | $1,820 |
| No | 207526444 | TRANE | 4TWV0X48A1 | 4TXCC009DS3 | S9V2D120U5VSA+RP | 36,400 | $1,820 |
| No | 204780444 | TRANE | 4TWV8048A1 | 4TXCD008DS3 | P0V0C000M50SA+RP | 35,600 | $1,780 |
| No | 204780436 | TRANE | 4TWV8048A1 | 4PX*DU48BS3 | P0V0C000M50SA+RP | 35,600 | $1,780 |
| No | 207526633 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3 | P0V0C000M50SA+RP | 35,600 | $1,780 |
| No | 207526641 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | P0V0C000M50SA+RP | 35,600 | $1,780 |
| No | 202365959 | TRANE | 4TWV8048A1 | 4PX*DU60BS3 | *DD2D120ACV5 | 35,200 | $1,760 |
| No | 207599992 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | S9V2C100D5PSB+RP | 35,200 | $1,760 |
| No | 205962374 | TRANE | 4TWV8048A1 | 4PX*CU60BS3 | P0V0C000M50SB+RP | 35,600 | $1,780 |
| No | 10511381 | TRANE | 4TWV8048A1 | 4TXCD008DS3 | S9V2C100D5PSB+RP | 35,200 | $1,760 |
| No | 207526525 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | *DD2D120ACV5 | 35,200 | $1,760 |
| No | 205962389 | TRANE | 4TWV8048A1 | 4TXCC009DS3 | P0V0C000M50SB+RP | 35,600 | $1,780 |
| No | 207526733 | TRANE | 4TWV8X48A1 | 4PX*CU60BS3 | P0V0C000M50SB+RP | 35,600 | $1,780 |
| No | 207526748 | TRANE | 4TWV8X48A1 | 4TXCC009DS3 | P0V0C000M50SB+RP | 35,600 | $1,780 |
| No | 10511398 | TRANE | 4TWV8049A1 | 4PX*CU60BS3 | S9V2C100U4PSB+RP | 36,600 | $1,830 |
| No | 10511420 | TRANE | 4TWV8049A1 | 4TXCC009DS3 | S9V2C100U4PSB+RP | 36,600 | $1,830 |
| No | 201808755 | TRANE | 4TWV0048A1 | 4PX*CU60BS3 | S9V2C100U4VSA+RP | 36,600 | $1,830 |
| No | 201808776 | TRANE | 4TWV0048A1 | 4TXCC009DS3 | S9V2C100U4VSA+RP | 36,600 | $1,830 |
| No | 201808977 | TRANE | 4TWV8049A1 | 4TXCC009DS3 | S9V2C100U4VSA+RP | 36,600 | $1,830 |
| No | 201808963 | TRANE | 4TWV8049A1 | 4PX*CU60BS3 | S9V2C100U4VSA+RP | 36,600 | $1,830 |
| No | 8761507 | TRANE | 4TWV8048A1 | 4TXCC009DS3 | *UD2C100ACV5 | 36,600 | $1,830 |
| No | 207526626 | TRANE | 4TWV8X48A1 | 4PX*CU42BS3 | P0V0C000M50SA+RP | 37,000 | $1,850 |
| No | 204780429 | TRANE | 4TWV8048A1 | 4PX*CU42BS3 | P0V0C000M50SA+RP | 37,000 | $1,850 |
| No | 204780372 | TRANE | 4TWV0048A1 | 4PX*CU60BS3 | P0V0C000M50SA+RP | 35,600 | $1,780 |
| No | 204780463 | TRANE | 4TWV8049A1 | 4PX*DU48BS3 | P0V0D000M50SA+RP | 35,800 | $1,790 |
| No | 204780456 | TRANE | 4TWV8049A1 | 4PX*CU60BS3 | P0V0C000M50SA+RP | 35,600 | $1,780 |
| No | 207526585 | TRANE | 4TWV0X48A1 | 4PX*CU60BS3 | P0V0C000M50SA+RP | 35,600 | $1,780 |
| No | 10511213 | TRANE | 4TWV0048A1 | 4PX*DU60BS3 | S9V2C080U5PSB+RP | 36,400 | $1,820 |
| No | 10511406 | TRANE | 4TWV8049A1 | 4PX*DU60BS3 | S9V2C080U5PSB+RP | 36,400 | $1,820 |
| No | 10511223 | TRANE | 4TWV0048A1 | 4TXCD010DS3 | S9V2C080U5PSB+RP | 36,400 | $1,820 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10511432 | TRANE | 4TWV8049A1 | 4TXCD010DS3 | S9V2C080U5PSB+RP | 36,400 | $1,820 |
| No | 207526526 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | *DHMD120BCV5 | 35,600 | $1,780 |
| No | 202365960 | TRANE | 4TWV8048A1 | 4PX*DU60BS3 | *DHMD120BCV5 | 35,600 | $1,780 |
| No | 202365956 | TRANE | 4TWV8048A1 | 4PX*CU48BS3 | S9V2C100D5PSB+RP | 36,200 | $1,810 |
| No | 8759529 | TRANE | 4TWV8048A1 | 4PX*DU60BS3 | *UD2D120ACV5 | 37,000 | $1,850 |
| No | 8761509 | TRANE | 4TWV8048A1 | 4TXCD010DS3 | *UD2D120ACV5 | 37,000 | $1,850 |
| No | 10511408 | TRANE | 4TWV8049A1 | 4PX*DU60BS3 | S9V2C100U5PSB+RP | 36,400 | $1,820 |
| No | 10511431 | TRANE | 4TWV8049A1 | 4TXCD010DS3 | S9V2C100U5PSB+RP | 36,400 | $1,820 |
| No | 201808925 | TRANE | 4TWV8048A1 | 4PX*CD60BS3 | S9V2C100D4VSA+RP | 37,400 | $1,870 |
| No | 10511346 | TRANE | 4TWV8048A1 | 4PX*CD60BS3 | S9V2C100D4PSB+RP | 37,400 | $1,870 |
| No | 10511373 | TRANE | 4TWV8048A1 | 4TXCC007DS3 | S9V2C100D4PSB+RP | 35,800 | $1,790 |
| No | 207526732 | TRANE | 4TWV8X48A1 | 4PX*CU48BS3 | P0V0C000M50SB+RP | 36,600 | $1,830 |
| No | 205962373 | TRANE | 4TWV8048A1 | 4PX*CU48BS3 | P0V0C000M50SB+RP | 36,600 | $1,830 |
| No | 205962388 | TRANE | 4TWV8048A1 | 4TXCC007DS3 | P0V0C000M50SB+RP | 36,600 | $1,830 |
| No | 207526747 | TRANE | 4TWV8X48A1 | 4TXCC007DS3 | P0V0C000M50SB+RP | 36,600 | $1,830 |
| No | 10511371 | TRANE | 4TWV8048A1 | 4TXCC007DS3 | S9V2C100U4PSB+RP | 37,600 | $1,880 |
| No | 201808942 | TRANE | 4TWV8048A1 | 4TXCC007DS3 | S9V2C100U4VSA+RP | 37,600 | $1,880 |
| No | 201808926 | TRANE | 4TWV8048A1 | 4PX*CU48BS3 | S9V2C100U4VSA+RP | 37,600 | $1,880 |
| No | 10511348 | TRANE | 4TWV8048A1 | 4PX*CU48BS3 | S9V2C100U4PSB+RP | 37,600 | $1,880 |
| No | 10511224 | TRANE | 4TWV0048A1 | 4TXCD010DS3 | S9V2D120U5PSB+RP | 36,400 | $1,820 |
| No | 10511211 | TRANE | 4TWV0048A1 | 4PX*DU60BS3 | S9V2D120U5PSB+RP | 36,400 | $1,820 |
| No | 10511409 | TRANE | 4TWV8049A1 | 4PX*DU60BS3 | S9V2D120U5PSB+RP | 36,400 | $1,820 |
| No | 201808767 | TRANE | 4TWV0048A1 | 4PX*DU60BS3 | S9V2D120U5VSA+RP | 36,400 | $1,820 |
| No | 10511429 | TRANE | 4TWV8049A1 | 4TXCD010DS3 | S9V2D120U5PSB+RP | 36,400 | $1,820 |
| No | 201808783 | TRANE | 4TWV0048A1 | 4TXCD010DS3 | S9V2D120U5VSA+RP | 36,400 | $1,820 |
| No | 201808983 | TRANE | 4TWV8049A1 | 4TXCD010DS3 | S9V2D120U5VSA+RP | 36,400 | $1,820 |
| No | 201808971 | TRANE | 4TWV8049A1 | 4PX*DU60BS3 | S9V2D120U5VSA+RP | 36,400 | $1,820 |
| No | 204780433 | TRANE | 4TWV8048A1 | 4PX*DD60BS3 | P0V0D000M50SA+RP | 36,000 | $1,800 |
| No | 204780434 | TRANE | 4TWV8048A1 | 4PX*DD60BS3+HORIZ-RT | P0V0D000M50SA+RP | 36,000 | $1,800 |
| No | 205962379 | TRANE | 4TWV8048A1 | 4PX*DD60BS3 | P0V0D000M50SB+RP | 36,000 | $1,800 |
| No | 205962381 | TRANE | 4TWV8048A1 | 4PX*DD60BS3+HORIZ-RT | P0V0D000M50SB+RP | 36,000 | $1,800 |
| No | 207526630 | TRANE | 4TWV8X48A1 | 4PX*DD60BS3 | P0V0D000M50SA+RP | 36,000 | $1,800 |
| No | 207526631 | TRANE | 4TWV8X48A1 | 4PX*DD60BS3+HORIZ-RT | P0V0D000M50SA+RP | 36,000 | $1,800 |
| No | 207526738 | TRANE | 4TWV8X48A1 | 4PX*DD60BS3 | P0V0D000M50SB+RP | 36,000 | $1,800 |
| No | 207526740 | TRANE | 4TWV8X48A1 | 4PX*DD60BS3+HORIZ-RT | P0V0D000M50SB+RP | 36,000 | $1,800 |
| No | 10511345 | TRANE | 4TWV8048A1 | 4PX*CD60BS3 | S9V2C100D5PSB+RP | 37,200 | $1,860 |
| No | 207526635 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | P0V0C000M50SA+RP | 35,200 | $1,760 |
| No | 204780438 | TRANE | 4TWV8048A1 | 4PX*DU60BS3 | P0V0C000M50SA+RP | 35,200 | $1,760 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10511423 | TRANE | 4TWV8049A1 | 4TXCC009DS3 | S9V2C100U5PSB+RP | 36,600 | $1,830 |
| No | 204780431 | TRANE | 4TWV8048A1 | 4PX*CU60BS3 | P0V0C000M50SA+RP | 35,800 | $1,790 |
| No | 10511399 | TRANE | 4TWV8049A1 | 4PX*CU60BS3 | S9V2C100U5PSB+RP | 36,600 | $1,830 |
| No | 204780443 | TRANE | 4TWV8048A1 | 4TXCC009DS3 | P0V0C000M50SA+RP | 35,800 | $1,790 |
| No | 207526628 | TRANE | 4TWV8X48A1 | 4PX*CU60BS3 | P0V0C000M50SA+RP | 35,800 | $1,790 |
| No | 207526640 | TRANE | 4TWV8X48A1 | 4TXCC009DS3 | P0V0C000M50SA+RP | 35,800 | $1,790 |
| No | 10511379 | TRANE | 4TWV8048A1 | 4TXCD008DS3 | S9V2D120D5PSB+RP | 35,600 | $1,780 |
| No | 10511380 | TRANE | 4TWV8048A1 | 4TXCD008DS3 | S9V2C100D4PSB+RP | 35,800 | $1,790 |
| No | 201808951 | TRANE | 4TWV8048A1 | 4TXCD008DS3 | S9V2C100D4VSA+RP | 35,800 | $1,790 |
| No | 207526493 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | S9V2C100D4VSA+RP | 35,800 | $1,790 |
| No | 207599991 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | S9V2C100D4PSB+RP | 35,800 | $1,790 |
| No | 204780468 | TRANE | 4TWV8049A1 | 4PX*DU60BS3 | P0V0D000M50SA+RP | 35,600 | $1,780 |
| No | 204780387 | TRANE | 4TWV0048A1 | 4TXCD010DS3 | P0V0D000M50SA+RP | 35,600 | $1,780 |
| No | 204780379 | TRANE | 4TWV0048A1 | 4PX*DU60BS3 | P0V0D000M50SA+RP | 35,600 | $1,780 |
| No | 204780492 | TRANE | 4TWV8049A1 | 4TXCD010DS3 | P0V0D000M50SA+RP | 35,600 | $1,780 |
| No | 205962329 | TRANE | 4TWV0048A1 | 4PX*DU60BS3 | P0V0D000M50SB+RP | 35,600 | $1,780 |
| No | 205962337 | TRANE | 4TWV0048A1 | 4TXCD010DS3 | P0V0D000M50SB+RP | 35,600 | $1,780 |
| No | 205962414 | TRANE | 4TWV8049A1 | 4TXCD010DS3 | P0V0D000M50SB+RP | 35,600 | $1,780 |
| No | 205962406 | TRANE | 4TWV8049A1 | 4PX*DU60BS3 | P0V0D000M50SB+RP | 35,600 | $1,780 |
| No | 207526592 | TRANE | 4TWV0X48A1 | 4PX*DU60BS3 | P0V0D000M50SA+RP | 35,600 | $1,780 |
| No | 207526600 | TRANE | 4TWV0X48A1 | 4TXCD010DS3 | P0V0D000M50SA+RP | 35,600 | $1,780 |
| No | 207526697 | TRANE | 4TWV0X48A1 | 4PX*DU60BS3 | P0V0D000M50SB+RP | 35,600 | $1,780 |
| No | 207526705 | TRANE | 4TWV0X48A1 | 4TXCD010DS3 | P0V0D000M50SB+RP | 35,600 | $1,780 |
| No | 207526345 | TRANE | 4TWV0X48A1 | TEM8A0C60V51+TDR | | 36,200 | $1,810 |
| No | 10153704 | TRANE | 4TWV0048A1 | TEM8A0C60V51+TDR | | 36,200 | $1,810 |
| No | 10153735 | TRANE | 4TWV8049A1 | TEM8A0C60V51+TDR | | 36,200 | $1,810 |
| No | 10511369 | TRANE | 4TWV8048A1 | 4TXCC007DS3 | S9V2D120D5PSB+RP | 35,800 | $1,790 |
| No | 202365957 | TRANE | 4TWV8048A1 | 4PX*CU60BS3 | *DD2C100ACV5 | 35,800 | $1,790 |
| No | 207526523 | TRANE | 4TWV8X48A1 | 4PX*CU60BS3 | *DD2C100ACV5 | 35,800 | $1,790 |
| No | 10511374 | TRANE | 4TWV8048A1 | 4TXCC007DS3 | S9V2C100D5PSB+RP | 35,800 | $1,790 |
| No | 10511221 | TRANE | 4TWV0048A1 | 4TXCC009DS3 | S9V2C100U4PSB+RP | 36,600 | $1,830 |
| No | 10511209 | TRANE | 4TWV0048A1 | 4PX*CU60BS3 | S9V2C100U4PSB+RP | 36,600 | $1,830 |
| No | 206918564 | TRANE | 4TWV0048A1 | TEM6A0D48H41+TDR+RP | | 35,200 | $1,760 |
| No | 207526883 | TRANE | 4TWV0X48A1 | TEM6A0D48H41+TDR+RP | | 35,200 | $1,760 |
| No | 206918575 | TRANE | 4TWV8049A1 | TEM6A0D48H41+TDR+RP | | 35,200 | $1,760 |
| No | 10511368 | TRANE | 4TWV8048A1 | 4TXCC007DS3 | S9V2C100U5PSB+RP | 37,800 | $1,890 |
| No | 205962384 | TRANE | 4TWV8048A1 | 4PX*DU48BS3 | P0V0D000M50SB+RP | 36,600 | $1,830 |
| No | 10511347 | TRANE | 4TWV8048A1 | 4PX*CU48BS3 | S9V2C100U5PSB+RP | 37,800 | $1,890 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205962390 | TRANE | 4TWV8048A1 | 4TXCD008DS3 | P0V0D000M50SB+RP | 36,600 | $1,830 |
| No | 204780445 | TRANE | 4TWV8048A1 | 4TXCD008DS3 | P0V0D000M50SA+RP | 36,600 | $1,830 |
| No | 207526743 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3 | P0V0D000M50SB+RP | 36,600 | $1,830 |
| No | 10511362 | TRANE | 4TWV8048A1 | 4PX*DU60BS3 | S9V2C100U5PSB+RP | 36,600 | $1,830 |
| No | 207526642 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | P0V0D000M50SA+RP | 36,600 | $1,830 |
| No | 207526749 | TRANE | 4TWV8X48A1 | 4TXCD008DS3 | P0V0D000M50SB+RP | 36,600 | $1,830 |
| No | 10511385 | TRANE | 4TWV8048A1 | 4TXCD010DS3 | S9V2C100U5PSB+RP | 36,600 | $1,830 |
| No | 10511359 | TRANE | 4TWV8048A1 | 4PX*DD60BS3 | S9V2D120D5PSB+RP | 37,000 | $1,850 |
| No | 10511349 | TRANE | 4TWV8048A1 | 4PX*CU48BS3 | S9V2D120U5PSB+RP | 37,800 | $1,890 |
| No | 10511350 | TRANE | 4TWV8048A1 | 4PX*CU48BS3 | S9V2C080U5PSB+RP | 37,800 | $1,890 |
| No | 10511370 | TRANE | 4TWV8048A1 | 4TXCC007DS3 | S9V2C080U5PSB+RP | 37,800 | $1,890 |
| No | 10511372 | TRANE | 4TWV8048A1 | 4TXCC007DS3 | S9V2D120U5PSB+RP | 37,800 | $1,890 |
| No | 201808945 | TRANE | 4TWV8048A1 | 4TXCC007DS3 | S9V2D120U5VSA+RP | 37,800 | $1,890 |
| No | 201808929 | TRANE | 4TWV8048A1 | 4PX*CU48BS3 | S9V2D120U5VSA+RP | 37,800 | $1,890 |
| No | 207526482 | TRANE | 4TWV8X48A1 | 4PX*CU48BS3 | S9V2D120U5VSA+RP | 37,800 | $1,890 |
| No | 207526490 | TRANE | 4TWV8X48A1 | 4TXCC007DS3 | S9V2D120U5VSA+RP | 37,800 | $1,890 |
| No | 10093512 | TRANE | 4TWV8048A1 | TAM9A0C60V51 | | 36,200 | $1,810 |
| No | 10153738 | TRANE | 4TWV8049A1 | TEM8A0D60V51+TDR | | 35,800 | $1,790 |
| No | 10153707 | TRANE | 4TWV0048A1 | TEM8A0D60V51+TDR | | 35,800 | $1,790 |
| No | 207526637 | TRANE | 4TWV8X48A1 | 4TXCB006DS3 | P0V0B000M40SA+RP | 37,000 | $1,850 |
| No | 204780440 | TRANE | 4TWV8048A1 | 4TXCB006DS3 | P0V0B000M40SA+RP | 37,000 | $1,850 |
| No | 207526890 | TRANE | 4TWV8X48A1 | TEM6A0D60H51+TDR+RP | | 35,400 | $1,770 |
| No | 206918573 | TRANE | 4TWV8048A1 | TEM6A0D60H51+TDR+RP | | 35,400 | $1,770 |
| No | 205962385 | TRANE | 4TWV8048A1 | 4PX*DU60BS3 | P0V0D000M50SB+RP | 36,000 | $1,800 |
| No | 205962393 | TRANE | 4TWV8048A1 | 4TXCD010DS3 | P0V0D000M50SB+RP | 36,000 | $1,800 |
| No | 207526752 | TRANE | 4TWV8X48A1 | 4TXCD010DS3 | P0V0D000M50SB+RP | 36,000 | $1,800 |
| No | 207526744 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | P0V0D000M50SB+RP | 36,000 | $1,800 |
| No | 10511353 | TRANE | 4TWV8048A1 | 4PX*CU60BS3 | S9V2C100U4PSB+RP | 37,400 | $1,870 |
| No | 201808931 | TRANE | 4TWV8048A1 | 4PX*CU60BS3 | S9V2C100U4VSA+RP | 37,400 | $1,870 |
| No | 10511375 | TRANE | 4TWV8048A1 | 4TXCC009DS3 | S9V2C100U4PSB+RP | 37,400 | $1,870 |
| No | 201808949 | TRANE | 4TWV8048A1 | 4TXCC009DS3 | S9V2C100U4VSA+RP | 37,400 | $1,870 |
| No | 10153734 | TRANE | 4TWV8049A1 | TEM8A0C48V41+TDR | | 35,600 | $1,780 |
| No | 10153703 | TRANE | 4TWV0048A1 | TEM8A0C48V41+TDR | | 35,600 | $1,780 |
| No | 10511352 | TRANE | 4TWV8048A1 | 4PX*CU60BS3 | S9V2C080U5PSB+RP | 37,200 | $1,860 |
| No | 10511376 | TRANE | 4TWV8048A1 | 4TXCC009DS3 | S9V2C080U5PSB+RP | 37,200 | $1,860 |
| No | 207526359 | TRANE | 4TWV8X48A1 | TEM8A0C60V51+TDR | | 36,800 | $1,840 |
| No | 10153729 | TRANE | 4TWV8048A1 | TEM8A0C60V51+TDR | | 36,800 | $1,840 |
| No | 10511383 | TRANE | 4TWV8048A1 | 4TXCD010DS3 | S9V2C100U4PSB+RP | 37,200 | $1,860 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10511363 | TRANE | 4TWV8048A1 | 4PX*DU60BS3 | S9V2C100U4PSB+RP | 37,200 | $1,860 |
| No | 201808941 | TRANE | 4TWV8048A1 | 4PX*DU60BS3 | S9V2C100U4VSA+RP | 37,200 | $1,860 |
| No | 201808955 | TRANE | 4TWV8048A1 | 4TXCD010DS3 | S9V2C100U4VSA+RP | 37,200 | $1,860 |
| No | 10153705 | TRANE | 4TWV0048A1 | TEM8A0D48V41+TDR | | 36,200 | $1,810 |
| No | 10153737 | TRANE | 4TWV8049A1 | TEM8A0D48V41+TDR | | 36,200 | $1,810 |
| No | 10511351 | TRANE | 4TWV8048A1 | 4PX*CU60BS3 | S9V2D120U5PSB+RP | 37,200 | $1,860 |
| No | 10511377 | TRANE | 4TWV8048A1 | 4TXCC009DS3 | S9V2D120U5PSB+RP | 37,200 | $1,860 |
| No | 201808933 | TRANE | 4TWV8048A1 | 4PX*CU60BS3 | S9V2D120U5VSA+RP | 37,200 | $1,860 |
| No | 201808947 | TRANE | 4TWV8048A1 | 4TXCC009DS3 | S9V2D120U5VSA+RP | 37,200 | $1,860 |
| No | 207526484 | TRANE | 4TWV8X48A1 | 4PX*CU60BS3 | S9V2D120U5VSA+RP | 37,200 | $1,860 |
| No | 207526491 | TRANE | 4TWV8X48A1 | 4TXCC009DS3 | S9V2D120U5VSA+RP | 37,200 | $1,860 |
| No | 204780439 | TRANE | 4TWV8048A1 | 4PX*DU60BS3 | P0V0D000M50SA+RP | 36,200 | $1,810 |
| No | 204780446 | TRANE | 4TWV8048A1 | 4TXCD010DS3 | P0V0D000M50SA+RP | 36,200 | $1,810 |
| No | 207526636 | TRANE | 4TWV8X48A1 | 4PX*DU60BS3 | P0V0D000M50SA+RP | 36,200 | $1,810 |
| No | 207526643 | TRANE | 4TWV8X48A1 | 4TXCD010DS3 | P0V0D000M50SA+RP | 36,200 | $1,810 |
| No | 10511354 | TRANE | 4TWV8048A1 | 4PX*CU60BS3 | S9V2C100U5PSB+RP | 37,400 | $1,870 |
| No | 10511378 | TRANE | 4TWV8048A1 | 4TXCC009DS3 | S9V2C100U5PSB+RP | 37,400 | $1,870 |
| No | 207526889 | TRANE | 4TWV8X48A1 | TEM6A0D48H41+TDR+RP | | 35,800 | $1,790 |
| No | 206918572 | TRANE | 4TWV8048A1 | TEM6A0D48H41+TDR+RP | | 35,800 | $1,790 |
| No | 10511382 | TRANE | 4TWV8048A1 | 4TXCD010DS3 | S9V2C080U5PSB+RP | 37,200 | $1,860 |
| No | 10511364 | TRANE | 4TWV8048A1 | 4PX*DU60BS3 | S9V2C080U5PSB+RP | 37,200 | $1,860 |
| No | 10511384 | TRANE | 4TWV8048A1 | 4TXCD010DS3 | S9V2D120U5PSB+RP | 37,200 | $1,860 |
| No | 201808953 | TRANE | 4TWV8048A1 | 4TXCD010DS3 | S9V2D120U5VSA+RP | 37,200 | $1,860 |
| No | 201808939 | TRANE | 4TWV8048A1 | 4PX*DU60BS3 | S9V2D120U5VSA+RP | 37,200 | $1,860 |
| No | 10153732 | TRANE | 4TWV8048A1 | TEM8A0D60V51+TDR | | 36,400 | $1,820 |
| No | 204780430 | TRANE | 4TWV8048A1 | 4PX*CU48BS3 | P0V0C000M50SA+RP | 36,800 | $1,840 |
| No | 204780442 | TRANE | 4TWV8048A1 | 4TXCC007DS3 | P0V0C000M50SA+RP | 36,800 | $1,840 |
| No | 207526627 | TRANE | 4TWV8X48A1 | 4PX*CU48BS3 | P0V0C000M50SA+RP | 36,800 | $1,840 |
| No | 207526639 | TRANE | 4TWV8X48A1 | 4TXCC007DS3 | P0V0C000M50SA+RP | 36,800 | $1,840 |
| No | 207526634 | TRANE | 4TWV8X48A1 | 4PX*DU48BS3 | P0V0D000M50SA+RP | 36,600 | $1,830 |
| No | 10153730 | TRANE | 4TWV8048A1 | TEM8A0D48V41+TDR | | 36,600 | $1,830 |
| No | 204780437 | TRANE | 4TWV8048A1 | 4PX*DU48BS3 | P0V0D000M50SA+RP | 36,600 | $1,830 |
| No | 201921950 | TRANE | 4TWL9048A1 | 4PX*DD48BS3 | *DHMC100ACV4 | 32,400 | $1,620 |
| No | 10511361 | TRANE | 4TWV8048A1 | 4PX*DU60BS3 | S9V2D120U5PSB+RP | 37,200 | $1,860 |
| No | 201922255 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | *DHMC100ACV4 | 36,200 | $1,810 |
| No | 201922181 | TRANE | 4TWL9060A1 | 4PX*DD60BS3 | *DHMC100ACV4 | 37,400 | $1,870 |
| No | 201921954 | TRANE | 4TWL9048A1 | 4PX*DD48BS3 | *DD2C100ACV5 | 32,000 | $1,600 |
| No | 201922251 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | *DD2C100ACV5 | 36,600 | $1,830 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922219 | TRANE | 4TWL9060A1 | 4TXCC007DS3 | *DHMC100ACV4 | 37,800 | $1,890 |
| No | 201922223 | TRANE | 4TWL9060A1 | 4TXCC009DS3 | *DHMC100ACV4 | 37,200 | $1,860 |
| No | 201921959 | TRANE | 4TWL9048A1 | 4PX*DD48BS3+HORIZ-RT | *UD2C100ACV5 | 32,000 | $1,600 |
| No | 201921957 | TRANE | 4TWL9048A1 | 4PX*DD48BS3+HORIZ-RT | *UD2C080ACV4 | 32,000 | $1,600 |
| No | 201922160 | TRANE | 4TWL9060A1 | 4PX*CD60BS3 | *DHMC100ACV4 | 38,500 | $1,925 |
| No | 201922236 | TRANE | 4TWL9060A1 | 4TXCD008DS3 | *DD2C100ACV5 | 35,800 | $1,790 |
| No | 201921889 | TRANE | 4TWL9048A1 | 4PX*CD48BS3 | *DHMC100ACV4 | 33,800 | $1,690 |
| No | 201921956 | TRANE | 4TWL9048A1 | 4PX*DD48BS3+HORIZ-RT | S9V2C080U5PSB+RP | 31,800 | $1,590 |
| No | 206197340 | TRANE | 4TWL9048A1 | 4PX*CD48BS3 | S9V2B080D4PSB+RP | 31,400 | $1,570 |
| No | 201921949 | TRANE | 4TWL9048A1 | 4PX*DD48BS3 | S9V2C100D4PSB+RP | 32,000 | $1,600 |
| No | 201921967 | TRANE | 4TWL9048A1 | 4PX*DD48BS3+HORIZ-RT | S9V2C100U4PSB+RP | 32,000 | $1,600 |
| No | 201921947 | TRANE | 4TWL9048A1 | 4PX*DD48BS3 | S9V2C100D5PSB+RP | 31,800 | $1,590 |
| No | 201921966 | TRANE | 4TWL9048A1 | 4PX*DD48BS3+HORIZ-RT | S9V2C100U5PSB+RP | 31,800 | $1,590 |
| No | 201921883 | TRANE | 4TWL9048A1 | 4PX*BD48BS3 | S9V2B080D4PSB+RP | 33,200 | $1,660 |
| No | 201921884 | TRANE | 4TWL9048A1 | 4PX*BD48BS3+HORIZ-RT | S9V2B080U4PSB+RP | 33,200 | $1,660 |
| No | 204780289 | TRANE | 4TWL9048A1 | 4PX*BD42BS3 | P0V0B000M40SA+RP | 31,000 | $1,550 |
| No | 201921885 | TRANE | 4TWL9048A1 | 4PX*BD48BS3+HORIZ-RT | S9V2B060U4PSB+RP | 33,200 | $1,660 |
| No | 201922258 | TRANE | 4TWL9060A1 | 4TXCD010DS3+HORIZ-LT | *DD2C100ACV5 | 37,600 | $1,880 |
| No | 201921990 | TRANE | 4TWL9048A1 | 4PX*DD60BS3+HORIZ-RT | S9V2C100U4PSB+RP | 30,600 | $1,530 |
| No | 201922183 | TRANE | 4TWL9060A1 | 4PX*DD60BS3 | *DHMD120BCV5 | 38,500 | $1,925 |
| No | 201921916 | TRANE | 4TWL9048A1 | 4PX*CU36BS3 | *UD2C080ACV4 | 31,600 | $1,580 |
| No | 201922220 | TRANE | 4TWL9060A1 | 4TXCC007DS3 | *DD2C100ACV5 | 37,200 | $1,860 |
| No | 204836590 | TRANE | 4TWL9060A1 | 4PX*DU48BS3 | P0V0C000M50SA+RP | 34,800 | $1,740 |
| No | 201922192 | TRANE | 4TWL9060A1 | 4PX*DD60BS3+HORIZ-RT | *UD2C100ACV5 | 37,400 | $1,870 |
| No | 201921948 | TRANE | 4TWL9048A1 | 4PX*DD48BS3 | *DHMD120BCV5 | 33,000 | $1,650 |
| No | 201922185 | TRANE | 4TWL9060A1 | 4PX*DD60BS3+HORIZ-RT | *UD2D140ACV5 | 39,000 | $1,950 |
| No | 201921895 | TRANE | 4TWL9048A1 | 4PX*CD48BS3+HORIZ-RT | *UD2C100ACV5 | 33,000 | $1,650 |
| No | 201921991 | TRANE | 4TWL9048A1 | 4PX*DD60BS3+HORIZ-RT | S9V2C080U5PSB+RP | 30,600 | $1,530 |
| No | 201922191 | TRANE | 4TWL9060A1 | 4PX*DD60BS3+HORIZ-RT | *UD2C080ACV4 | 37,200 | $1,860 |
| No | 201921989 | TRANE | 4TWL9048A1 | 4PX*DD60BS3+HORIZ-RT | S9V2C100U5PSB+RP | 30,600 | $1,530 |
| No | 201921915 | TRANE | 4TWL9048A1 | 4PX*CU36BS3 | *UHMC100ACV4 | 31,800 | $1,590 |
| No | 201922237 | TRANE | 4TWL9060A1 | 4TXCD008DS3 | *DD2D120ACV5 | 36,600 | $1,830 |
| No | 201921888 | TRANE | 4TWL9048A1 | 4PX*CD48BS3 | S9V2C100D4PSB+RP | 33,000 | $1,650 |
| No | 201921898 | TRANE | 4TWL9048A1 | 4PX*CD48BS3+HORIZ-RT | S9V2C100U4PSB+RP | 33,000 | $1,650 |
| No | 201921914 | TRANE | 4TWL9048A1 | 4PX*CU36BS3 | *UD2C100ACV5 | 32,000 | $1,600 |
| No | 201921897 | TRANE | 4TWL9048A1 | 4PX*CD48BS3+HORIZ-RT | *UD2C080ACV4 | 33,200 | $1,660 |
| No | 201921890 | TRANE | 4TWL9048A1 | 4PX*CD48BS3 | *DD2C100ACV5 | 33,200 | $1,660 |
| No | 201921968 | TRANE | 4TWL9048A1 | 4PX*DD48BS3+HORIZ-RT | *UD2D140ACV5 | 33,200 | $1,660 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922245 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | *UD2D140ACV5 | 39,000 | $1,950 |
| No | 204780291 | TRANE | 4TWL9048A1 | 4PX*BD48BS3+HORIZ-RT | P0V0B000M40SA+RP | 32,600 | $1,630 |
| No | 201922207 | TRANE | 4TWL9060A1 | 4PX*DU60BS3 | *UD2D140ACV5 | 39,000 | $1,950 |
| No | 204780290 | TRANE | 4TWL9048A1 | 4PX*BD48BS3 | P0V0B000M40SA+RP | 32,600 | $1,630 |
| No | 201921962 | TRANE | 4TWL9048A1 | 4PX*DD48BS3+HORIZ-RT | *UD2D120ACV5 | 33,000 | $1,650 |
| No | 201922184 | TRANE | 4TWL9060A1 | 4PX*DD60BS3 | *DD2C100ACV5 | 37,000 | $1,850 |
| No | 201921951 | TRANE | 4TWL9048A1 | 4PX*DD48BS3 | *DD2D120ACV5 | 33,000 | $1,650 |
| No | 205962255 | TRANE | 4TWL9048A1 | 4PX*DD48BS3+HORIZ-RT | P0V0C000M50SB+RP | 31,000 | $1,550 |
| No | 204780302 | TRANE | 4TWL9048A1 | 4PX*DD48BS3 | P0V0C000M50SA+RP | 31,000 | $1,550 |
| No | 205962253 | TRANE | 4TWL9048A1 | 4PX*DD48BS3 | P0V0C000M50SB+RP | 31,000 | $1,550 |
| No | 204780305 | TRANE | 4TWL9048A1 | 4PX*DD48BS3+HORIZ-RT | P0V0C000M50SA+RP | 31,000 | $1,550 |
| No | 201921953 | TRANE | 4TWL9048A1 | 4PX*DD48BS3 | S9V2D120D5PSB+RP | 32,800 | $1,640 |
| No | 201921965 | TRANE | 4TWL9048A1 | 4PX*DD48BS3+HORIZ-RT | S9V2D120U5PSB+RP | 32,800 | $1,640 |
| No | 201922152 | TRANE | 4TWL9048A1 | 4TXCD010DS3+HORIZ-LT | *DD2C100ACV5 | 31,000 | $1,550 |
| No | 201922188 | TRANE | 4TWL9060A1 | 4PX*DD60BS3+HORIZ-RT | *UD2D120ACV5 | 39,000 | $1,950 |
| No | 201922162 | TRANE | 4TWL9060A1 | 4PX*CD60BS3 | *DD2C100ACV5 | 38,000 | $1,900 |
| No | 206325973 | TRANE | 4TWL9048A1 | 4PX*CU48BS3 | S9V2B080U4PSA+RP | 30,800 | $1,540 |
| No | 201921893 | TRANE | 4TWL9048A1 | 4PX*CD48BS3+HORIZ-RT | S9V2C080U5PSB+RP | 33,000 | $1,650 |
| No | 204780294 | TRANE | 4TWL9048A1 | 4PX*CD42BS3 | P0V0C000M50SA+RP | 30,800 | $1,540 |
| No | 205962245 | TRANE | 4TWL9048A1 | 4PX*CD42BS3 | P0V0C000M50SB+RP | 30,800 | $1,540 |
| No | 201922167 | TRANE | 4TWL9060A1 | 4PX*CD60BS3+HORIZ-RT | *UD2C100ACV5 | 38,500 | $1,925 |
| No | 201922168 | TRANE | 4TWL9060A1 | 4PX*CD60BS3+HORIZ-RT | S9V2C080U5PSB+RP | 38,000 | $1,900 |
| No | 201922241 | TRANE | 4TWL9060A1 | 4TXCD008DS3 | *DHMD120BCV5 | 37,000 | $1,850 |
| No | 205962276 | TRANE | 4TWL9060A1 | 4PX*DD60BS3 | P0V0C000M50SB+RP | 35,800 | $1,790 |
| No | 201921891 | TRANE | 4TWL9048A1 | 4PX*CD48BS3 | S9V2C100D5PSB+RP | 33,000 | $1,650 |
| No | 201921899 | TRANE | 4TWL9048A1 | 4PX*CD48BS3+HORIZ-RT | S9V2C100U5PSB+RP | 33,000 | $1,650 |
| No | 201922193 | TRANE | 4TWL9060A1 | 4PX*DD60BS3+HORIZ-RT | S9V2C080U5PSB+RP | 36,600 | $1,830 |
| No | 201922194 | TRANE | 4TWL9060A1 | 4PX*DD60BS3+HORIZ-RT | S9V2C100U5PSB+RP | 36,800 | $1,840 |
| No | 201922224 | TRANE | 4TWL9060A1 | 4TXCC009DS3 | *DD2C100ACV5 | 36,400 | $1,820 |
| No | 201922209 | TRANE | 4TWL9060A1 | 4PX*DU60BS3 | *UD2C080ACV4 | 37,200 | $1,860 |
| No | 201922242 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | *UD2C080ACV4 | 37,200 | $1,860 |
| No | 201922208 | TRANE | 4TWL9060A1 | 4PX*DU60BS3 | *UHMC100ACV4 | 37,000 | $1,850 |
| No | 201922246 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | *UHMC100ACV4 | 37,000 | $1,850 |
| No | 201922169 | TRANE | 4TWL9060A1 | 4PX*CD60BS3+HORIZ-RT | *UD2C080ACV4 | 38,500 | $1,925 |
| No | 204780292 | TRANE | 4TWL9048A1 | 4PX*BU42BS3 | P0V0B000M40SA+RP | 30,400 | $1,520 |
| No | 201921910 | TRANE | 4TWL9048A1 | 4PX*CD60BS3+HORIZ-RT | S9V2C100U4PSB+RP | 32,000 | $1,600 |
| No | 205962260 | TRANE | 4TWL9048A1 | 4PX*DD60BS3+HORIZ-RT | P0V0C000M50SB+RP | 29,800 | $1,490 |
| No | 201921907 | TRANE | 4TWL9048A1 | 4PX*CD60BS3+HORIZ-RT | S9V2C100U5PSB+RP | 31,800 | $1,590 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201921906 | TRANE | 4TWL9048A1 | 4PX*CD60BS3+HORIZ-RT | S9V2C080U5PSB+RP | 31,800 | $1,590 |
| No | 205962258 | TRANE | 4TWL9048A1 | 4PX*DD60BS3 | P0V0C000M50SB+RP | 29,800 | $1,490 |
| No | 204836578 | TRANE | 4TWL9060A1 | 4PX*CU48BS3 | P0V0C000M50SA+RP | 36,000 | $1,800 |
| No | 206918556 | TRANE | 4TWL9048A1 | TEM6A0C42H41+TDR+RP | | 30,400 | $1,520 |
| No | 201922254 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | *DHMD120BCV5 | 36,400 | $1,820 |
| No | 204836582 | TRANE | 4TWL9060A1 | 4PX*DD60BS3 | P0V0C000M50SA+RP | 36,000 | $1,800 |
| No | 201922182 | TRANE | 4TWL9060A1 | 4PX*DD60BS3 | *DD2D120ACV5 | 38,000 | $1,900 |
| No | 201921988 | TRANE | 4TWL9048A1 | 4PX*DD60BS3+HORIZ-RT | S9V2D120U5PSB+RP | 31,600 | $1,580 |
| No | 204836586 | TRANE | 4TWL9060A1 | 4PX*DD60BS3+HORIZ-RT | P0V0C000M50SA+RP | 35,600 | $1,780 |
| No | 201922221 | TRANE | 4TWL9060A1 | 4TXCC009DS3 | S9V2C100D5PSB+RP | 36,800 | $1,840 |
| No | 205962278 | TRANE | 4TWL9060A1 | 4PX*DD60BS3+HORIZ-RT | P0V0C000M50SB+RP | 35,600 | $1,780 |
| No | 204780318 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | P0V0C000M50SA+RP | 30,200 | $1,510 |
| No | 204780311 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | P0V0C000M50SA+RP | 30,200 | $1,510 |
| No | 205962261 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | P0V0C000M50SB+RP | 30,200 | $1,510 |
| No | 205962268 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | P0V0C000M50SB+RP | 30,200 | $1,510 |
| No | 205962247 | TRANE | 4TWL9048A1 | 4PX*CD48BS3+HORIZ-RT | P0V0C000M50SB+RP | 32,000 | $1,600 |
| No | 205962246 | TRANE | 4TWL9048A1 | 4PX*CD48BS3 | P0V0C000M50SB+RP | 32,000 | $1,600 |
| No | 201922253 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | *DD2D120ACV5 | 36,600 | $1,830 |
| No | 205962279 | TRANE | 4TWL9060A1 | 4PX*DU60BS3 | P0V0C000M50SB+RP | 35,800 | $1,790 |
| No | 205962286 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | P0V0C000M50SB+RP | 35,800 | $1,790 |
| No | 204780315 | TRANE | 4TWL9048A1 | 4TXCC005DS3 | P0V0C000M50SA+RP | 30,800 | $1,540 |
| No | 205962265 | TRANE | 4TWL9048A1 | 4TXCC005DS3 | P0V0C000M50SB+RP | 30,800 | $1,540 |
| No | 201922166 | TRANE | 4TWL9060A1 | 4PX*CD60BS3+HORIZ-RT | S9V2C100U5PSB+RP | 38,000 | $1,900 |
| No | 201922201 | TRANE | 4TWL9060A1 | 4PX*DU48BS3 | *UHMC100ACV4 | 37,400 | $1,870 |
| No | 201922233 | TRANE | 4TWL9060A1 | 4TXCD008DS3 | *UHMC100ACV4 | 37,400 | $1,870 |
| No | 204780306 | TRANE | 4TWL9048A1 | 4PX*DD60BS3 | P0V0C000M50SA+RP | 30,000 | $1,500 |
| No | 205962272 | TRANE | 4TWL9060A1 | 4PX*CD60BS3 | P0V0C000M50SB+RP | 37,000 | $1,850 |
| No | 204780308 | TRANE | 4TWL9048A1 | 4PX*DD60BS3+HORIZ-RT | P0V0C000M50SA+RP | 30,000 | $1,500 |
| No | 205962273 | TRANE | 4TWL9060A1 | 4PX*CD60BS3+HORIZ-RT | P0V0C000M50SB+RP | 37,000 | $1,850 |
| No | 201922197 | TRANE | 4TWL9060A1 | 4PX*DU48BS3 | *UD2C080ACV4 | 37,200 | $1,860 |
| No | 201922238 | TRANE | 4TWL9060A1 | 4TXCD008DS3 | *UD2C080ACV4 | 37,200 | $1,860 |
| No | 204780314 | TRANE | 4TWL9048A1 | 4TXCB006DS3 | P0V0B000M40SA+RP | 31,400 | $1,570 |
| No | 201922229 | TRANE | 4TWL9060A1 | 4TXCC009DS3 | *UHMC100ACV4 | 38,000 | $1,900 |
| No | 204836592 | TRANE | 4TWL9060A1 | 4PX*DU48BS3 | P0V0D000M50SA+RP | 36,000 | $1,800 |
| No | 201922176 | TRANE | 4TWL9060A1 | 4PX*CU60BS3 | *UHMC100ACV4 | 38,000 | $1,900 |
| No | 205962254 | TRANE | 4TWL9048A1 | 4PX*DD48BS3 | P0V0D000M50SB+RP | 31,800 | $1,590 |
| No | 205962256 | TRANE | 4TWL9048A1 | 4PX*DD48BS3+HORIZ-RT | P0V0D000M50SB+RP | 31,800 | $1,590 |
| No | 204780293 | TRANE | 4TWL9048A1 | 4PX*BU48BS3 | P0V0B000M40SA+RP | 32,000 | $1,600 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922200 | TRANE | 4TWL9060A1 | 4PX*DU48BS3 | *UD2D140ACV5 | 39,000 | $1,950 |
| No | 201922232 | TRANE | 4TWL9060A1 | 4TXCD008DS3 | *UD2D140ACV5 | 39,000 | $1,950 |
| No | 204836596 | TRANE | 4TWL9060A1 | 4PX*DU60BS3 | P0V0C000M50SA+RP | 36,000 | $1,800 |
| No | 204836606 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | P0V0C000M50SA+RP | 36,000 | $1,800 |
| No | 204780295 | TRANE | 4TWL9048A1 | 4PX*CD48BS3 | P0V0C000M50SA+RP | 32,200 | $1,610 |
| No | 204780296 | TRANE | 4TWL9048A1 | 4PX*CD48BS3+HORIZ-RT | P0V0C000M50SA+RP | 32,200 | $1,610 |
| No | 204836574 | TRANE | 4TWL9060A1 | 4PX*CD60BS3 | P0V0C000M50SA+RP | 37,200 | $1,860 |
| No | 204836576 | TRANE | 4TWL9060A1 | 4PX*CD60BS3+HORIZ-RT | P0V0C000M50SA+RP | 37,200 | $1,860 |
| No | 201923159 | TRANE | 4TWL9060A1 | 4PX*CU60BS3 | *UD2C080ACV4 | 38,500 | $1,925 |
| No | 201923160 | TRANE | 4TWL9060A1 | 4TXCC009DS3 | *UD2C080ACV4 | 38,500 | $1,925 |
| No | 201922204 | TRANE | 4TWL9060A1 | 4PX*DU48BS3 | S9V2C100U5PSB+RP | 37,000 | $1,850 |
| No | 204780303 | TRANE | 4TWL9048A1 | 4PX*DD48BS3 | P0V0D000M50SA+RP | 32,000 | $1,600 |
| No | 204780304 | TRANE | 4TWL9048A1 | 4PX*DD48BS3+HORIZ-RT | P0V0D000M50SA+RP | 32,000 | $1,600 |
| No | 205962263 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | P0V0C000M50SB+RP | 30,000 | $1,500 |
| No | 205962270 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | P0V0C000M50SB+RP | 30,000 | $1,500 |
| No | 205962284 | TRANE | 4TWL9060A1 | 4TXCD008DS3 | P0V0C000M50SB+RP | 36,200 | $1,810 |
| No | 201922154 | TRANE | 4TWL9048A1 | 4TXCD010DS3+HORIZ-LT | *DD2D120ACV5 | 32,000 | $1,600 |
| No | 201922173 | TRANE | 4TWL9060A1 | 4PX*CU48BS3 | *UHMC100ACV4 | 38,500 | $1,925 |
| No | 201922215 | TRANE | 4TWL9060A1 | 4TXCC007DS3 | *UHMC100ACV4 | 38,500 | $1,925 |
| No | 201922196 | TRANE | 4TWL9060A1 | 4PX*DU48BS3 | S9V2C080U5PSB+RP | 37,000 | $1,850 |
| No | 205962249 | TRANE | 4TWL9048A1 | 4PX*CD60BS3+HORIZ-RT | P0V0C000M50SB+RP | 31,000 | $1,550 |
| No | 204780298 | TRANE | 4TWL9048A1 | 4PX*CD60BS3+HORIZ-RT | P0V0C000M50SA+RP | 31,000 | $1,550 |
| No | 204780297 | TRANE | 4TWL9048A1 | 4PX*CD60BS3 | P0V0C000M50SA+RP | 31,000 | $1,550 |
| No | 205962248 | TRANE | 4TWL9048A1 | 4PX*CD60BS3 | P0V0C000M50SB+RP | 31,000 | $1,550 |
| No | 201922190 | TRANE | 4TWL9060A1 | 4PX*DD60BS3+HORIZ-RT | S9V2D120U5PSB+RP | 37,600 | $1,880 |
| No | 201922267 | TRANE | 4TWL9060A1 | TEM8A0C60V51+TDR | | 38,500 | $1,925 |
| No | 201922230 | TRANE | 4TWL9060A1 | 4TXCD008DS3 | *UD2C100ACV5 | 37,200 | $1,860 |
| No | 201922198 | TRANE | 4TWL9060A1 | 4PX*DU48BS3 | *UD2C100ACV5 | 37,200 | $1,860 |
| No | 205962259 | TRANE | 4TWL9048A1 | 4PX*DD60BS3+HORIZ-RT | P0V0D000M50SB+RP | 30,600 | $1,530 |
| No | 205962250 | TRANE | 4TWL9048A1 | 4PX*CU42BS3 | P0V0C000M50SB+RP | 31,600 | $1,580 |
| No | 205962257 | TRANE | 4TWL9048A1 | 4PX*DD60BS3 | P0V0D000M50SB+RP | 30,600 | $1,530 |
| No | 204836602 | TRANE | 4TWL9060A1 | 4TXCD008DS3 | P0V0C000M50SA+RP | 36,400 | $1,820 |
| No | 205962282 | TRANE | 4TWL9060A1 | 4TXCC009DS3 | P0V0C000M50SB+RP | 37,000 | $1,850 |
| No | 205962274 | TRANE | 4TWL9060A1 | 4PX*CU60BS3 | P0V0C000M50SB+RP | 37,000 | $1,850 |
| No | 201922202 | TRANE | 4TWL9060A1 | 4PX*DU48BS3 | *UHMD120ACV5 | 39,000 | $1,950 |
| No | 204780321 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | P0V0C000M50SA+RP | 30,200 | $1,510 |
| No | 204780312 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | P0V0C000M50SA+RP | 30,200 | $1,510 |
| No | 201922217 | TRANE | 4TWL9060A1 | 4TXCC007DS3 | *UD2C080ACV4 | 38,500 | $1,925 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 201922174 | TRANE | 4TWL9060A1 | 4PX*CU48BS3 | *UD2C080ACV4 | 38,500 | $1,925 |
| No | 206918559 | TRANE | 4TWL9060A1 | TEM6A0D48H41+TDR+RP | | 36,800 | $1,840 |
| No | 201922172 | TRANE | 4TWL9060A1 | 4PX*CU48BS3 | S9V2C080U5PSB+RP | 38,000 | $1,900 |
| No | 204780307 | TRANE | 4TWL9048A1 | 4PX*DD60BS3 | P0V0D000M50SA+RP | 30,800 | $1,540 |
| No | 204780309 | TRANE | 4TWL9048A1 | 4PX*DD60BS3+HORIZ-RT | P0V0D000M50SA+RP | 30,800 | $1,540 |
| No | 205962251 | TRANE | 4TWL9048A1 | 4PX*CU48BS3 | P0V0C000M50SB+RP | 31,400 | $1,570 |
| No | 205962266 | TRANE | 4TWL9048A1 | 4TXCC007DS3 | P0V0C000M50SB+RP | 31,400 | $1,570 |
| No | 204780299 | TRANE | 4TWL9048A1 | 4PX*CU42BS3 | P0V0C000M50SA+RP | 31,800 | $1,590 |
| No | 204836584 | TRANE | 4TWL9060A1 | 4PX*DD60BS3 | P0V0D000M50SA+RP | 36,600 | $1,830 |
| No | 204836588 | TRANE | 4TWL9060A1 | 4PX*DD60BS3+HORIZ-RT | P0V0D000M50SA+RP | 36,600 | $1,830 |
| No | 205962275 | TRANE | 4TWL9060A1 | 4PX*DD60BS3 | P0V0D000M50SB+RP | 36,600 | $1,830 |
| No | 205962277 | TRANE | 4TWL9060A1 | 4PX*DD60BS3+HORIZ-RT | P0V0D000M50SB+RP | 36,600 | $1,830 |
| No | 204836600 | TRANE | 4TWL9060A1 | 4TXCC009DS3 | P0V0C000M50SA+RP | 37,200 | $1,860 |
| No | 204836580 | TRANE | 4TWL9060A1 | 4PX*CU60BS3 | P0V0C000M50SA+RP | 37,200 | $1,860 |
| No | 204836594 | TRANE | 4TWL9060A1 | 4PX*DU60BS3 | P0V0D000M50SA+RP | 37,000 | $1,850 |
| No | 204836608 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | P0V0D000M50SA+RP | 37,000 | $1,850 |
| No | 205962280 | TRANE | 4TWL9060A1 | 4PX*DU60BS3 | P0V0D000M50SB+RP | 37,000 | $1,850 |
| No | 205962285 | TRANE | 4TWL9060A1 | 4TXCD010DS3 | P0V0D000M50SB+RP | 37,000 | $1,850 |
| No | 206918558 | TRANE | 4TWL9048A1 | TEM6A0D60H51+TDR+RP | | 30,200 | $1,510 |
| No | 204836598 | TRANE | 4TWL9060A1 | 4TXCC007DS3 | P0V0C000M50SA+RP | 37,400 | $1,870 |
| No | 205962281 | TRANE | 4TWL9060A1 | 4TXCC007DS3 | P0V0C000M50SB+RP | 37,400 | $1,870 |
| No | 204780316 | TRANE | 4TWL9048A1 | 4TXCC007DS3 | P0V0C000M50SA+RP | 31,600 | $1,580 |
| No | 204780300 | TRANE | 4TWL9048A1 | 4PX*CU48BS3 | P0V0C000M50SA+RP | 31,600 | $1,580 |
| No | 205962267 | TRANE | 4TWL9048A1 | 4TXCC009DS3 | P0V0C000M50SB+RP | 31,000 | $1,550 |
| No | 204780317 | TRANE | 4TWL9048A1 | 4TXCC009DS3 | P0V0C000M50SA+RP | 31,000 | $1,550 |
| No | 204780301 | TRANE | 4TWL9048A1 | 4PX*CU60BS3 | P0V0C000M50SA+RP | 31,000 | $1,550 |
| No | 205962252 | TRANE | 4TWL9048A1 | 4PX*CU60BS3 | P0V0C000M50SB+RP | 31,000 | $1,550 |
| No | 201922256 | TRANE | 4TWL9060A1 | 4TXCD010DS3+HORIZ-LT | *DD2D120ACV5 | 37,400 | $1,870 |
| No | 201922199 | TRANE | 4TWL9060A1 | 4PX*DU48BS3 | *UD2D120ACV5 | 38,500 | $1,925 |
| No | 201922231 | TRANE | 4TWL9060A1 | 4TXCD008DS3 | *UD2D120ACV5 | 38,500 | $1,925 |
| No | 201922170 | TRANE | 4TWL9060A1 | 4PX*CU48BS3 | *UD2C100ACV5 | 38,500 | $1,925 |
| No | 201922216 | TRANE | 4TWL9060A1 | 4TXCC007DS3 | *UD2C100ACV5 | 38,500 | $1,925 |
| No | 204780319 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | P0V0D000M50SA+RP | 31,400 | $1,570 |
| No | 201922171 | TRANE | 4TWL9060A1 | 4PX*CU48BS3 | S9V2C100U5PSB+RP | 38,500 | $1,925 |
| No | 204780310 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | P0V0D000M50SA+RP | 31,400 | $1,570 |
| No | 205962269 | TRANE | 4TWL9048A1 | 4TXCD008DS3 | P0V0D000M50SB+RP | 31,400 | $1,570 |
| No | 205962262 | TRANE | 4TWL9048A1 | 4PX*DU48BS3 | P0V0D000M50SB+RP | 31,400 | $1,570 |
| No | 201922203 | TRANE | 4TWL9060A1 | 4PX*DU48BS3 | S9V2D120U5PSB+RP | 38,000 | $1,900 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206918557 | TRANE | 4TWL9048A1 | TEM6A0D48H41+TDR+RP | | 30,600 | $1,530 |
| No | 204780320 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | P0V0D000M50SA+RP | 31,000 | $1,550 |
| No | 205962271 | TRANE | 4TWL9048A1 | 4TXCD010DS3 | P0V0D000M50SB+RP | 31,000 | $1,550 |
| No | 204780313 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | P0V0D000M50SA+RP | 31,000 | $1,550 |
| No | 205962264 | TRANE | 4TWL9048A1 | 4PX*DU60BS3 | P0V0D000M50SB+RP | 31,000 | $1,550 |
| No | 204836604 | TRANE | 4TWL9060A1 | 4TXCD008DS3 | P0V0D000M50SA+RP | 37,200 | $1,860 |
| No | 205962283 | TRANE | 4TWL9060A1 | 4TXCD008DS3 | P0V0D000M50SB+RP | 37,200 | $1,860 |
| No | 201922158 | TRANE | 4TWL9048A1 | TEM8A0C60V51+TDR | | 31,400 | $1,570 |
| No | 8761501 | TRANE | 4TWV8048A1 | 4TXCC009DS3 | *UD2D120ACV5 | 36,600 | $1,830 |
| No | 10511208 | TRANE | 4TWV0048A1 | 4PX*CU48BS3 | S9V2C100U4PSB+RP | 37,000 | $1,850 |
| No | 10511219 | TRANE | 4TWV0048A1 | 4TXCC007DS3 | S9V2C100U4PSB+RP | 37,000 | $1,850 |
| No | 10511391 | TRANE | 4TWV8049A1 | 4PX*CD60BS3 | S9V2C100D5PSB+RP | 36,400 | $1,820 |
| No | 10511394 | TRANE | 4TWV8049A1 | 4PX*CU48BS3 | S9V2C100U4PSB+RP | 37,000 | $1,850 |
| No | 10511415 | TRANE | 4TWV8049A1 | 4TXCC007DS3 | S9V2C100U4PSB+RP | 37,000 | $1,850 |
| No | 201808749 | TRANE | 4TWV0048A1 | 4PX*CU48BS3 | S9V2C100U4VSA+RP | 37,000 | $1,850 |
| No | 201808773 | TRANE | 4TWV0048A1 | 4TXCC007DS3 | S9V2C100U4VSA+RP | 37,000 | $1,850 |
| No | 201808959 | TRANE | 4TWV8049A1 | 4PX*CU48BS3 | S9V2C100U4VSA+RP | 37,000 | $1,850 |
| No | 201808973 | TRANE | 4TWV8049A1 | 4TXCC007DS3 | S9V2C100U4VSA+RP | 37,000 | $1,850 |
| No | 202365942 | TRANE | 4TWV0048A1 | 4PX*CU60BS3 | *DD2C100ACV5 | 35,200 | $1,760 |
| No | 8759537 | TRANE | 4TWV8049A1 | 4PX*CU60BS3 | *UD2C080ACV4 | 35,800 | $1,790 |
| No | 8759542 | TRANE | 4TWV8049A1 | 4PX*DU60BS3 | *UHMD120ACV5 | 36,400 | $1,820 |
| No | 8761425 | TRANE | 4TWV0048A1 | 4TXCC009DS3 | *UD2C080ACV4 | 35,800 | $1,790 |
| No | 8759541 | TRANE | 4TWV8049A1 | 4PX*DU60BS3 | *UHMC100ACV4 | 35,800 | $1,790 |
| No | 8761431 | TRANE | 4TWV0048A1 | 4TXCD010DS3 | *UHMD120ACV5 | 36,400 | $1,820 |
| No | 8761432 | TRANE | 4TWV0048A1 | 4TXCD010DS3 | *UHMC100ACV4 | 35,800 | $1,790 |
| No | 8761496 | TRANE | 4TWV8048A1 | 4TXCC007DS3 | *UD2D120ACV5 | 37,600 | $1,880 |
| No | 8761529 | TRANE | 4TWV8049A1 | 4TXCD010DS3 | *UHMC100ACV4 | 35,800 | $1,790 |
| No | 6749944 | TRANE | 4TWV0048A1 | *AM8C0C48V41 | | 34,000 | $1,700 |
| No | 6750235 | TRANE | 4TWV8048A1 | *AM8C0C48V41 | | 34,400 | $1,720 |
| No | 6750461 | TRANE | 4TWV8049A1 | *AM8C0C48V41 | | 34,000 | $1,700 |
| No | 6796639 | TRANE | 4TWV8037A1 | 4TXCC007CC3 | *UD2C100ACV5 | 25,600 | $1,280 |
| No | 7161152 | TRANE | 4TWV0048A1 | *AM8C0C60V51 | | 34,200 | $1,710 |
| No | 10093499 | TRANE | 4TWV0048A1 | TAM9A0C48V41 | | 34,000 | $1,700 |
| No | 8761525 | TRANE | 4TWV8049A1 | 4TXCD010DS3 | *DD2D120ACV5 | 34,400 | $1,720 |
| No | 202703124 | TRANE | 4TXK2318A10N0** | 4MXW2318A10N0** | N/A | 12,400 | $620 |
| No | 202635845 | TRANE | 4TXK2312A10N0** | 4MXW2312A10N0** | N/A | 7,100 | $355 |
| No | 8761530 | TRANE | 4TWV8049A1 | 4TXCD010DS3 | *UHMD120ACV5 | 36,400 | $1,820 |
| No | 8761520 | TRANE | 4TWV8049A1 | 4TXCC009DS3 | *UD2C080ACV4 | 35,800 | $1,790 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207705541 | TRANE / MITSUBISHI ELECTRIC | NTXSSH24A112** | NAXWST24B112** | | 13,300 | $665 |
| No | 207705535 | TRANE / MITSUBISHI ELECTRIC | NTXSSH24A112** | NTXWST24B112** | | 13,300 | $665 |
| No | 207705528 | TRANE / MITSUBISHI ELECTRIC | NTXSSH24A112** | MSZ-GS24NA*** | | 13,300 | $665 |
| No | 207705539 | TRANE / MITSUBISHI ELECTRIC | NTXSSH15A112** | NAXWST15B112** | | 8,700 | $435 |
| No | 207705532 | TRANE / MITSUBISHI ELECTRIC | NTXSSH15A112** | NTXWST15B112** | | 8,700 | $435 |
| No | 207705526 | TRANE / MITSUBISHI ELECTRIC | NTXSSH15A112** | MSZ-GS15NA*** | | 8,700 | $435 |
| No | 207705537 | TRANE / MITSUBISHI ELECTRIC | NTXSSH12A112** | NAXWST12B112** | | 7,600 | $380 |
| No | 207705531 | TRANE / MITSUBISHI ELECTRIC | NTXSSH12A112** | NTXWST12B112** | | 7,600 | $380 |
| No | 207705525 | TRANE / MITSUBISHI ELECTRIC | NTXSSH12A112** | MSZ-GS12NA*** | | 7,600 | $380 |
| No | 207705536 | TRANE / MITSUBISHI ELECTRIC | NTXSSH09A112** | NAXWST09B112** | | 5,700 | $285 |
| No | 207705529 | TRANE / MITSUBISHI ELECTRIC | NTXSSH09A112** | NTXWST09B112** | | 5,700 | $285 |
| No | 207705524 | TRANE / MITSUBISHI ELECTRIC | NTXSSH09A112** | MSZ-GS09NA*** | | 5,700 | $285 |
| No | 207705497 | TRANE / MITSUBISHI ELECTRIC | MUZ-GS24NAHZ*** | NTXWST24B112** | | 13,300 | $665 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207705495 | TRANE / MITSUBISHI ELECTRIC | MUZ-GS15NAHZ*** | NTXWST15B112** | | 8,700 | $435 |
| No | 207705494 | TRANE / MITSUBISHI ELECTRIC | MUZ-GS12NAHZ*** | NTXWST12B112** | | 7,600 | $380 |
| No | 207705492 | TRANE / MITSUBISHI ELECTRIC | MUZ-GS09NAHZ*** | NTXWST09B112** | | 5,700 | $285 |
| No | 207705522 | Trane / Mitsubishi Electric | NTXSST24B112** | NAXWST24B112** | | 17,600 | $880 |
| No | 207705516 | Trane / Mitsubishi Electric | NTXSST24B112** | NTXWST24B112** | | 17,600 | $880 |
| No | 207705510 | Trane / Mitsubishi Electric | NTXSST24B112** | MSZ-GS24NA*** | | 17,600 | $880 |
| No | 207705521 | Trane / Mitsubishi Electric | NTXSST18B112** | NAXWST18B112** | | 13,300 | $665 |
| No | 207705515 | Trane / Mitsubishi Electric | NTXSST18B112** | NTXWST18B112** | | 13,300 | $665 |
| No | 207705509 | Trane / Mitsubishi Electric | NTXSST18B112** | MSZ-GS18NA*** | | 13,300 | $665 |
| No | 207705520 | Trane / Mitsubishi Electric | NTXSST15B112** | NAXWST15B112** | | 12,100 | $605 |
| No | 207705513 | Trane / Mitsubishi Electric | NTXSST15B112** | NTXWST15B112** | | 12,100 | $605 |
| No | 207705508 | Trane / Mitsubishi Electric | NTXSST15B112** | MSZ-GS15NA*** | | 12,100 | $605 |
| No | 207705519 | Trane / Mitsubishi Electric | NTXSST12B112** | NAXWST12B112** | | 9,000 | $450 |
| No | 207705512 | Trane / Mitsubishi Electric | NTXSST12B112** | NTXWST12B112** | | 9,000 | $450 |
| No | 207705506 | Trane / Mitsubishi Electric | NTXSST12B112** | MSZ-GS12NA*** | | 9,000 | $450 |
| No | 207705517 | Trane / Mitsubishi Electric | NTXSST09B112** | NAXWST09B112** | | 6,500 | $325 |
| No | 207705511 | Trane / Mitsubishi Electric | NTXSST09B112** | NTXWST09B112** | | 6,500 | $325 |
| No | 207705505 | Trane / Mitsubishi Electric | NTXSST09B112** | MSZ-GS09NA*** | | 6,500 | $325 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207705484 | Trane / Mitsubishi Electric | MUZ-GS24NA*** | NTXWST24B112** | | 17,600 | $880 |
| No | 207705483 | Trane / Mitsubishi Electric | MUZ-GS18NA*** | NTXWST18B112** | | 13,300 | $665 |
| No | 207705482 | Trane / Mitsubishi Electric | MUZ-GS15NA*** | NTXWST15B112** | | 12,100 | $605 |
| No | 207705480 | Trane / Mitsubishi Electric | MUZ-GS12NA*** | NTXWST12B112** | | 9,000 | $450 |
| No | 207705479 | Trane / Mitsubishi Electric | MUZ-GS09NA*** | NTXWST09B112** | | 6,500 | $325 |
| No | 211150926 | Trane / Mitsubishi Electric | TRUZA0421KA70** | PAA-A42CA* | | 32,800 | $1,640 |
| No | 211150925 | Trane / Mitsubishi Electric | TRUZA0421KA70** | PAA-A42BA* | | 32,800 | $1,640 |
| No | 211150924 | Trane / Mitsubishi Electric | TRUZA0361KA70** | PAA-A36CA* | | 29,400 | $1,470 |
| No | 211150923 | Trane / Mitsubishi Electric | TRUZA0361KA70** | PAA-A36BA* | | 29,400 | $1,470 |
| No | 211150922 | Trane / Mitsubishi Electric | TRUZA0301HA70** | PAA-A30BA* | | 21,000 | $1,050 |
| No | 211150921 | Trane / Mitsubishi Electric | TRUZA0301HA70** | PAA-A30AA* | | 21,000 | $1,050 |
| No | 211150920 | Trane / Mitsubishi Electric | TRUZA0241HA70** | PAA-A24BA* | | 15,600 | $780 |
| No | 211150919 | Trane / Mitsubishi Electric | TRUZA0241HA70** | PAA-A24AA* | | 15,600 | $780 |
| No | 211150918 | Trane / Mitsubishi Electric | TRUZA0241HA70** | PAA-A18BA* | | 13,800 | $690 |
| No | 211150917 | Trane / Mitsubishi Electric | TRUZA0241HA70** | PAA-A18AA* | | 13,800 | $690 |
| No | 209832998 | Trane / Mitsubishi Electric | NTXSPB15B112A* | MSZ-FS15NA*** | | 10,000 | $500 |
| No | 209832997 | Trane / Mitsubishi Electric | NTXSPH15B112A* | NAXWPH15B112A* | | 10,000 | $500 |
| No | 209832996 | Trane / Mitsubishi Electric | NTXSPH15B112A* | MSZ-FS15NA*** | | 10,000 | $500 |
| No | 209832261 | Trane / Mitsubishi Electric | NTXSPH15B112A* | NTXWPH15B112A* | | 10,000 | $500 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 209832995 | Trane / Mitsubishi Electric | MUZ-FS15NA*** | NTXWPH15B112A* | | 10,000 | $500 |
| No | 209832993 | Trane / Mitsubishi Electric | NTXSPB12B112A* | MSZ-FS12NA*** | | 8,400 | $420 |
| No | 209832992 | Trane / Mitsubishi Electric | NTXSPH12B112A* | NAXWPH12B112A* | | 8,400 | $420 |
| No | 209832991 | Trane / Mitsubishi Electric | NTXSPH12B112A* | MSZ-FS12NA*** | | 8,400 | $420 |
| No | 209832260 | Trane / Mitsubishi Electric | NTXSPH12B112A* | NTXWPH12B112A* | | 8,400 | $420 |
| No | 209832990 | Trane / Mitsubishi Electric | MUZ-FS12NA*** | NTXWPH12B112A* | | 8,400 | $420 |
| No | 209832988 | Trane / Mitsubishi Electric | NTXSPB09B112A* | MSZ-FS09NA*** | | 5,900 | $295 |
| No | 209832987 | Trane / Mitsubishi Electric | NTXSPH09B112A* | NAXWPH09B112A* | | 5,900 | $295 |
| No | 209832986 | Trane / Mitsubishi Electric | NTXSPH09B112A* | MSZ-FS09NA*** | | 5,900 | $295 |
| No | 209832259 | Trane / Mitsubishi Electric | NTXSPH09B112A* | NTXWPH09B112A* | | 5,900 | $295 |
| No | 209832985 | Trane / Mitsubishi Electric | MUZ-FS09NA*** | NTXWPH09B112A* | | 5,900 | $295 |
| No | 209832983 | Trane / Mitsubishi Electric | NTXSPB06B112A* | MSZ-FS06NA*** | | 5,900 | $295 |
| No | 209832982 | Trane / Mitsubishi Electric | NTXSPH06B112A* | NAXWPH06B112A* | | 5,900 | $295 |
| No | 209832981 | Trane / Mitsubishi Electric | NTXSPH06B112A* | MSZ-FS06NA*** | | 5,900 | $295 |
| No | 209832258 | Trane / Mitsubishi Electric | NTXSPH06B112A* | NTXWPH06B112A* | | 5,900 | $295 |
| No | 209832980 | Trane / Mitsubishi Electric | MUZ-FS06NA*** | NTXWPH06B112A* | | 5,900 | $295 |
| No | 209310462 | TRANE / MITSUBISHI ELECTRIC | NTXMMX36A142C* | Heat pump without ducts | | 22,400 | $1,120 |
| No | 209310460 | TRANE / MITSUBISHI ELECTRIC | NTXMMX30A132C* | Heat pump without ducts | | 18,600 | $930 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 209310458 | TRANE / MITSUBISHI ELECTRIC | NTXMMX24A132C* | Heat pump without ducts | | 14,300 | $715 |
| No | 209424923 | TRANE / MITSUBISHI ELECTRIC | NTXMMX20A122C* | Heat pump without ducts | | 13,500 | $675 |
| No | 207342931 | TRANE / MITSUBISHI ELECTRIC | NTXMMX24A132** | Heat pump without ducts | | 14,000 | $700 |
| No | 207342928 | TRANE / MITSUBISHI ELECTRIC | NTXMMX20A122** | Heat pump with ducts | | 12,500 | $625 |
| No | 207342929 | TRANE / MITSUBISHI ELECTRIC | NTXMMX20A122** | Heat pump without ducts | | 13,500 | $675 |
| No | 207348699 | TRANE / MITSUBISHI ELECTRIC | NTXMMX20A122** | Combination heat pumps with or without ducts | | 13,000 | $650 |
| No | 207348700 | TRANE / MITSUBISHI ELECTRIC | NTXMMX24A132** | Combination heat pumps with or without ducts | | 14,000 | $700 |
| No | 207342933 | TRANE / MITSUBISHI ELECTRIC | NTXMMX30A132** | Heat pump with ducts | | 15,100 | $755 |
| No | 207342930 | TRANE / MITSUBISHI ELECTRIC | NTXMMX24A132** | Heat pump with ducts | | 14,000 | $700 |
| No | 207348701 | TRANE / MITSUBISHI ELECTRIC | NTXMMX30A132** | Combination heat pumps with or without ducts | | 15,500 | $775 |
| No | 207348702 | TRANE / MITSUBISHI ELECTRIC | NTXMMX36A142** | Combination heat pumps with or without ducts | | 21,200 | $1,060 |
| No | 207342932 | TRANE / MITSUBISHI ELECTRIC | NTXMMX30A132** | Heat pump without ducts | | 16,000 | $800 |
| No | 207342934 | TRANE / MITSUBISHI ELECTRIC | NTXMMX36A142** | Heat pump with ducts | | 20,200 | $1,010 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207342935 | TRANE / MITSUBISHI ELECTRIC | NTXMMX36A142** | Heat pump without ducts | | 22,200 | $1,110 |
| No | 207348704 | TRANE / MITSUBISHI ELECTRIC | NTXMPH20A122** | Combination heat pumps with or without ducts | | 13,700 | $685 |
| No | 207525860 | TRANE / MITSUBISHI ELECTRIC | NTXMSM36A142A* | Combination heat pumps with or without ducts | | 26,400 | $1,320 |
| No | 207518835 | TRANE / MITSUBISHI ELECTRIC | NTXMSM36A142A* | Heat pump with ducts | | 26,600 | $1,330 |
| No | 207518839 | TRANE / MITSUBISHI ELECTRIC | NTXMSM48A182A* | Heat pump without ducts | | 31,400 | $1,570 |
| No | 207517162 | TRANE / MITSUBISHI ELECTRIC | NTXMSM36A142A* | Heat pump without ducts | | 26,400 | $1,320 |
| No | 207525863 | TRANE / MITSUBISHI ELECTRIC | NTXMSM48A182A* | Combination heat pumps with or without ducts | | 33,200 | $1,660 |
| No | 207517166 | TRANE / MITSUBISHI ELECTRIC | NTXMSM48A182A* | Heat pump with ducts | | 35,000 | $1,750 |
| No | 206908465 | TRANE / MITSUBISHI ELECTRIC | NTXMPH20A122A** | Heat pump with ducts | | 13,700 | $685 |
| No | 202354903 | TRANE / MITSUBISHI ELECTRIC | NTXMMX36A142A* | Heat pump without ducts | | 22,200 | $1,110 |
| No | 202354901 | TRANE / MITSUBISHI ELECTRIC | NTXMMX30A132A* | Heat pump without ducts | | 16,000 | $800 |
| No | 202392004 | TRANE / MITSUBISHI ELECTRIC | NTXMMX20A122A* | Combination heat pumps with or without ducts | | 13,000 | $650 |
| No | 202373742 | TRANE / MITSUBISHI ELECTRIC | NTXMMX20A122A* | Heat pump without ducts | | 13,500 | $675 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202373709 | TRANE / MITSUBISHI ELECTRIC | NTXMMX20A122A* | Heat pump with ducts | | 12,500 | $625 |
| No | 204795700 | TRANE / MITSUBISHI ELECTRIC | TRUZA0361KA70B* | TPVA0A0361AA70A | | 24,000 | $1,200 |
| No | 204795701 | TRANE / MITSUBISHI ELECTRIC | TRUZA0361KA70N* | TPVA0A0361AA70A | | 24,000 | $1,200 |
| No | 204795682 | TRANE / MITSUBISHI ELECTRIC | TRUZA0181KA70B* | TPKA0A0181HA70A | | 11,300 | $565 |
| No | 204795674 | TRANE / MITSUBISHI ELECTRIC | TRUZA0301HA70B* | TPEADA0301AA70A | | 18,500 | $925 |
| No | 204795703 | TRANE / MITSUBISHI ELECTRIC | TRUZA0421KA70N* | TPVA0A0421AA70A | | 28,400 | $1,420 |
| No | 204795699 | TRANE / MITSUBISHI ELECTRIC | TRUZA0301HA70N* | TPVA0A0301AA70A | | 18,000 | $900 |
| No | 204795698 | TRANE / MITSUBISHI ELECTRIC | TRUZA0301HA70B* | TPVA0A0301AA70A | | 18,000 | $900 |
| No | 204795675 | TRANE / MITSUBISHI ELECTRIC | TRUZA0301HA70N* | TPEADA0301AA70A | | 18,500 | $925 |
| No | 204795702 | TRANE / MITSUBISHI ELECTRIC | TRUZA0421KA70B* | TPVA0A0421AA70A | | 28,400 | $1,420 |
| No | 204795668 | TRANE / MITSUBISHI ELECTRIC | TRUZA0421KA70B* | TPCA0A0421KA70A | | 31,800 | $1,590 |
| No | 204795669 | TRANE / MITSUBISHI ELECTRIC | TRUZA0421KA70N* | TPCA0A0421KA70A | | 31,800 | $1,590 |
| No | 204795666 | TRANE / MITSUBISHI ELECTRIC | TRUZA0361KA70B* | TPCA0A0361KA70A | | 21,000 | $1,050 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204795679 | TRANE / MITSUBISHI ELECTRIC | TRUZA0421KA70N* | TPEADA0421AA70A | | 30,600 | $1,530 |
| No | 204795678 | TRANE / MITSUBISHI ELECTRIC | TRUZA0421KA70B* | TPEADA0421AA70A | | 30,600 | $1,530 |
| No | 204795667 | TRANE / MITSUBISHI ELECTRIC | TRUZA0361KA70N* | TPCA0A0361KA70A | | 21,000 | $1,050 |
| No | 202850706 | TRANE / MITSUBISHI ELECTRIC | TUMYP0481AK42** | Heat pump with ducts | | 35,000 | $1,750 |
| No | 204834218 | TRANE / MITSUBISHI ELECTRIC | TUMYP0481AK43** | Heat pump with ducts | | 35,000 | $1,750 |
| No | 204795694 | TRANE / MITSUBISHI ELECTRIC | TRUZA0181KA70B* | TPVA0A0181AA70A | | 12,000 | $600 |
| No | 204795672 | TRANE / MITSUBISHI ELECTRIC | TRUZA0241HA70B* | TPEADA0241AA70A | | 14,800 | $740 |
| No | 204795673 | TRANE / MITSUBISHI ELECTRIC | TRUZA0241HA70N* | TPEADA0241AA70A | | 14,800 | $740 |
| No | 204795690 | TRANE / MITSUBISHI ELECTRIC | TRUZA0301HA70B* | TPLA0A0301EA70A | | 18,100 | $905 |
| No | 204795691 | TRANE / MITSUBISHI ELECTRIC | TRUZA0301HA70N* | TPLA0A0301EA70A | | 18,100 | $905 |
| No | 204795676 | TRANE / MITSUBISHI ELECTRIC | TRUZA0361KA70B* | TPEADA0361AA70A | | 20,800 | $1,040 |
| No | 204795680 | TRANE / MITSUBISHI ELECTRIC | TRUZA0121KA70B* | TPKA0A0121HA70A | | 9,200 | $460 |
| No | 204795677 | TRANE / MITSUBISHI ELECTRIC | TRUZA0361KA70N* | TPEADA0361AA70A | | 20,800 | $1,040 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202850716 | TRANE / MITSUBISHI ELECTRIC | TUMYP0481AK42** | Combination heat pumps with or without ducts | | 33,200 | $1,660 |
| No | 204795662 | TRANE / MITSUBISHI ELECTRIC | TRUZA0241HA70B* | TPCA0A0241KA70A | | 15,400 | $770 |
| No | 204795663 | TRANE / MITSUBISHI ELECTRIC | TRUZA0241HA70N* | TPCA0A0241KA70A | | 15,400 | $770 |
| No | 204795684 | TRANE / MITSUBISHI ELECTRIC | TRUZA0241HA70B* | TPKA0A0241KA70A | | 15,700 | $785 |
| No | 204795685 | TRANE / MITSUBISHI ELECTRIC | TRUZA0241HA70N* | TPKA0A0241KA70A | | 15,700 | $785 |
| No | 204795696 | TRANE / MITSUBISHI ELECTRIC | TRUZA0241HA70B* | TPVA0A0241AA70A | | 15,000 | $750 |
| No | 204795697 | TRANE / MITSUBISHI ELECTRIC | TRUZA0241HA70N* | TPVA0A0241AA70A | | 15,000 | $750 |
| No | 204926548 | TRANE / MITSUBISHI ELECTRIC | TUMYP0481AK43** | Combination heat pumps with or without ducts | | 33,200 | $1,660 |
| No | 202850705 | TRANE / MITSUBISHI ELECTRIC | TUMYP0361AK42** | Heat pump with ducts | | 26,600 | $1,330 |
| No | 202850710 | TRANE / MITSUBISHI ELECTRIC | TUMYP0481AK42** | Heat pump without ducts | | 31,400 | $1,570 |
| No | 204834278 | TRANE / MITSUBISHI ELECTRIC | TUMYP0361AK43** | Heat pump with ducts | | 26,600 | $1,330 |
| No | 204813325 | TRANE / MITSUBISHI ELECTRIC | TRUZA0361KA70B* | TPLA0A0361EA70A | | 22,000 | $1,100 |
| No | 204813326 | TRANE / MITSUBISHI ELECTRIC | TRUZA0361KA70N* | TPLA0A0361EA70A | | 22,000 | $1,100 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204834281 | TRANE / MITSUBISHI ELECTRIC | TUMYP0481AK43** | Heat pump without ducts | | 31,400 | $1,570 |
| No | 204813328 | TRANE / MITSUBISHI ELECTRIC | TRUZA0121KA70B* | TPVA0A0121AA70A | | 9,900 | $495 |
| No | 202850709 | TRANE / MITSUBISHI ELECTRIC | TUMYP0361AK42** | Heat pump without ducts | | 26,400 | $1,320 |
| No | 204813318 | TRANE / MITSUBISHI ELECTRIC | TRUZA0181KA70B* | TPLA0A0181EA70A | | 11,000 | $550 |
| No | 204813315 | TRANE / MITSUBISHI ELECTRIC | TRUZA0121KA70B* | TPLA0A0121EA70A | | 10,100 | $505 |
| No | 204834277 | TRANE / MITSUBISHI ELECTRIC | TUMYP0361AK43** | Heat pump without ducts | | 26,400 | $1,320 |
| No | 204926547 | TRANE / MITSUBISHI ELECTRIC | TUMYP0361AK43** | Combination heat pumps with or without ducts | | 26,400 | $1,320 |
| No | 204834252 | TRANE / MITSUBISHI ELECTRIC | NTXMMX48A182B* | Heat pump without ducts | | 33,000 | $1,650 |
| No | 204834253 | TRANE / MITSUBISHI ELECTRIC | NTXMMX48A182B* | Heat pump with ducts | | 33,000 | $1,650 |
| No | 204926527 | TRANE / MITSUBISHI ELECTRIC | NTXMMX48A182B* | Combination heat pumps with or without ducts | | 33,000 | $1,650 |
| No | 204793344 | TRANE / MITSUBISHI ELECTRIC | NTXSKH12A112AA | TPEADA0121AA70A | | 9,000 | $450 |
| No | 204793349 | TRANE / MITSUBISHI ELECTRIC | NTXSKH15A112AA | TPEADA0151AA70A | | 11,700 | $585 |
| No | 204793342 | TRANE / MITSUBISHI ELECTRIC | NTXSKH12A112AA | NTXDKS12A112AA | | 9,000 | $450 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 204793350 | TRANE / MITSUBISHI ELECTRIC | NTXSKH18A112AA | NTXDKS18A112AA | | 14,200 | $710 |
| No | 204793343 | TRANE / MITSUBISHI ELECTRIC | NTXSKH12A112AA | NTXCKS12A112AA | | 8,300 | $415 |
| No | 204793353 | TRANE / MITSUBISHI ELECTRIC | NTXSKH18A112AA | NTXAMT18A112AA | | 14,300 | $715 |
| No | 202373728 | TRANE / MITSUBISHI ELECTRIC | NTXSPH15A112AA | NTXWPH15A112AA | | 11,000 | $550 |
| No | 202354907 | TRANE / MITSUBISHI ELECTRIC | NTXMPH30A132AA | Heat pump without ducts | | 18,000 | $900 |
| No | 202373734 | TRANE / MITSUBISHI ELECTRIC | NTXSST15A112AA | NTXWST15A112AA | | 12,200 | $610 |
| No | 202373723 | TRANE / MITSUBISHI ELECTRIC | NTXSPB06A112AA | NTXWPH06A112AA | | 5,900 | $295 |
| No | 202392233 | TRANE / MITSUBISHI ELECTRIC | NTXSKS18A112AA | NTXUKS18A112AA | | 13,100 | $655 |
| No | 202392231 | TRANE / MITSUBISHI ELECTRIC | NTXSKS18A112AA | NTXDKS18A112AA | | 13,900 | $695 |
| No | 202392237 | TRANE / MITSUBISHI ELECTRIC | NTXSKS18A112AA | NTXCKS18A112AA | | 12,900 | $645 |
| No | 202392221 | TRANE / MITSUBISHI ELECTRIC | NTXSKS12A112AA | NTXCKS12A112AA | | 8,900 | $445 |
| No | 202392219 | TRANE / MITSUBISHI ELECTRIC | NTXSKS12A112AA | NTXUKS12A112AA | | 9,900 | $495 |
| No | 202392225 | TRANE / MITSUBISHI ELECTRIC | NTXSKS15A112AA | NTXDKS15A112AA | | 11,700 | $585 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202392217 | TRANE / MITSUBISHI ELECTRIC | NTXSKS12A112AA | NTXDKS12A112AA | | 10,000 | $500 |
| No | 202392213 | TRANE / MITSUBISHI ELECTRIC | NTXSKS09A112AA | NTXCKS09A112AA | | 6,900 | $345 |
| No | 202392209 | TRANE / MITSUBISHI ELECTRIC | NTXSKS09A112AA | NTXUKS09A112AA | | 7,700 | $385 |
| No | 202392207 | TRANE / MITSUBISHI ELECTRIC | NTXSKS09A112AA | NTXDKS09A112AA | | 7,600 | $380 |
| No | 202373736 | TRANE / MITSUBISHI ELECTRIC | NTXSST24A112AA | NTXWST24A112AA | | 16,000 | $800 |
| No | 202373732 | TRANE / MITSUBISHI ELECTRIC | NTXSST09A112AA | NTXWST09A112AA | | 6,700 | $335 |
| No | 202373730 | TRANE / MITSUBISHI ELECTRIC | NTXSPH18A112AA | NTXWPH18A112AA | | 13,700 | $685 |
| No | 202373729 | TRANE / MITSUBISHI ELECTRIC | NTXSPB15A112AA | NTXWPH15A112AA | | 11,070 | $554 |
| No | 202373727 | TRANE / MITSUBISHI ELECTRIC | NTXSPB12A112AA | NTXWPH12A112AA | | 8,100 | $405 |
| No | 202373725 | TRANE / MITSUBISHI ELECTRIC | NTXSPB09A112AA | NTXWPH09A112AA | | 6,700 | $335 |
| No | 202373735 | TRANE / MITSUBISHI ELECTRIC | NTXSST18A112AA | NTXWST18A112AA | | 13,800 | $690 |
| No | 202373733 | TRANE / MITSUBISHI ELECTRIC | NTXSST12A112AA | NTXWST12A112AA | | 9,200 | $460 |
| No | 202373731 | TRANE / MITSUBISHI ELECTRIC | NTXSPB18A112AA | NTXWPH18A112AA | | 12,480 | $624 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202373726 | TRANE / MITSUBISHI ELECTRIC | NTXSPH12A112AA | NTXWPH12A112AA | | 8,000 | $400 |
| No | 202373724 | TRANE / MITSUBISHI ELECTRIC | NTXSPH09A112AA | NTXWPH09A112AA | | 6,700 | $335 |
| No | 202373722 | TRANE / MITSUBISHI ELECTRIC | NTXSPH06A112AA | NTXWPH06A112AA | | 5,900 | $295 |
| No | 202373717 | TRANE / MITSUBISHI ELECTRIC | NTXSPF12A112AA | NTXFKS12A112AA | | 8,800 | $440 |
| No | 202354902 | TRANE / MITSUBISHI ELECTRIC | NTXMMX36A142AA | Heat pump with ducts | | 20,200 | $1,010 |
| No | 202373741 | TRANE / MITSUBISHI ELECTRIC | NTXSMT24A112AA | NTXWMT24A112AA | | 18,500 | $925 |
| No | 202366329 | TRANE / MITSUBISHI ELECTRIC | NTXMMX24A132AA | Combination heat pumps with or without ducts | | 14,000 | $700 |
| No | 202354898 | TRANE / MITSUBISHI ELECTRIC | NTXMMX24A132AA | Heat pump with ducts | | 14,000 | $700 |
| No | 202373710 | TRANE / MITSUBISHI ELECTRIC | NTXMPH20A122AA | Heat pump with ducts | | 13,700 | $685 |
| No | 202354904 | TRANE / MITSUBISHI ELECTRIC | NTXMPH24A132AA | Heat pump with ducts | | 14,000 | $700 |
| No | 202354900 | TRANE / MITSUBISHI ELECTRIC | NTXMMX30A132AA | Heat pump with ducts | | 15,100 | $755 |
| No | 202366331 | TRANE / MITSUBISHI ELECTRIC | NTXMMX36A142AA | Combination heat pumps with or without ducts | | 21,200 | $1,060 |
| No | 202366330 | TRANE / MITSUBISHI ELECTRIC | NTXMMX30A132AA | Combination heat pumps with or without ducts | | 15,550 | $778 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202373739 | TRANE / MITSUBISHI ELECTRIC | NTXSMT15A112AA | NTXWMT15A112AA | | 11,500 | $575 |
| No | 202373737 | TRANE / MITSUBISHI ELECTRIC | NTXSMT09A112AA | NTXWMT09A112AA | | 6,700 | $335 |
| No | 202373740 | TRANE / MITSUBISHI ELECTRIC | NTXSMT18A112AA | NTXWMT18A112AA | | 11,500 | $575 |
| No | 202373738 | TRANE / MITSUBISHI ELECTRIC | NTXSMT12A112AA | NTXWMT12A112AA | | 7,600 | $380 |
| No | 202373746 | TRANE / MITSUBISHI ELECTRIC | NTXMMX48A182AA | Heat pump without ducts | | 33,000 | $1,650 |
| No | 202392229 | TRANE / MITSUBISHI ELECTRIC | NTXSKS15A112AA | NTXCKS15A112AA | | 11,900 | $595 |
| No | 202392012 | TRANE / MITSUBISHI ELECTRIC | NTXMMX48A182AA | Combination heat pumps with or without ducts | | 34,000 | $1,700 |
| No | 202373716 | TRANE / MITSUBISHI ELECTRIC | NTXSPF09A112AA | NTXFKS09A112AA | | 7,500 | $375 |
| No | 202392227 | TRANE / MITSUBISHI ELECTRIC | NTXSKS15A112AA | PEAD-A15AA | | 11,300 | $565 |
| No | 202392215 | TRANE / MITSUBISHI ELECTRIC | NTXSKS12A112AA | PEAD-A12AA | | 9,900 | $495 |
| No | 202392211 | TRANE / MITSUBISHI ELECTRIC | NTXSKS09A112AA | PEAD-A09AA7 | | 7,600 | $380 |
| No | 202392239 | TRANE / MITSUBISHI ELECTRIC | NTXSKS18A112AA | NTXAMT18A112AA | | 14,000 | $700 |
| No | 202392223 | TRANE / MITSUBISHI ELECTRIC | NTXSKS12A112AA | NTXAMT12A112AA | | 9,900 | $495 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208284013 | TRUST AIR CONDITIONERS | AH60H/O44P | AH60H/I44P | | 37,000 | $1,850 |
| No | 208284012 | TRUST AIR CONDITIONERS | AH48H/O44P | AH48H/I44P | | 37,000 | $1,850 |
| No | 208284011 | TRUST AIR CONDITIONERS | AH36H/O44P | AH36H/I44P | | 20,400 | $1,020 |
| No | 208284009 | TRUST AIR CONDITIONERS | AH24H/O44P | AH24H/I44P | | 21,000 | $1,050 |
| No | 208284007 | TRUST AIR CONDITIONERS | AH18H/O44P | AH18H/I44P | | 12,000 | $600 |
| No | 208284017 | TRUST AIR CONDITIONERS | AA36H/O44P | AH36H/I44P | | 30,400 | $1,520 |
| No | 208284016 | TRUST AIR CONDITIONERS | AA30H/O44P | AH30H/I44P | | 21,000 | $1,050 |
| No | 208284482 | TRUST AIR CONDITIONERS | M5S48H/O4S4P | Heat pump without ducts | | 34,000 | $1,700 |
| No | 208284479 | TRUST AIR CONDITIONERS | M4S36H/O4S4P | Heat pump without ducts | | 26,800 | $1,340 |
| No | 208284477 | TRUST AIR CONDITIONERS | M3S27H/O4S4P | Heat pump with ducts | | 22,000 | $1,100 |
| No | 208284474 | TRUST AIR CONDITIONERS | M2S18H/O4S4P | Heat pump with ducts | | 14,800 | $740 |
| No | 208284476 | TRUST AIR CONDITIONERS | M3S27H/O4S4P | Heat pump without ducts | | 21,000 | $1,050 |
| No | 208284473 | TRUST AIR CONDITIONERS | M2S18H/O4S4P | Heat pump without ducts | | 14,300 | $715 |
| No | 208816928 | TRUST AIR CONDITIONERS | OUS18H/O4S4P | IUMDL18H/I43P | | 12,600 | $630 |
| No | 208280101 | TRUST AIR CONDITIONERS | IS18H/O4S41P | IUMDL18H/I43P | | 12,600 | $630 |
| No | 208280076 | TRUST AIR CONDITIONERS | IS18H/O4S41P | IUMC418H/I41P | | 12,000 | $600 |
| No | 208816920 | TRUST AIR CONDITIONERS | OUS18H/O4S4P | IUMC418H/I41P | | 12,000 | $600 |
| No | 208816936 | TRUST AIR CONDITIONERS | OUS18H/O4S4P | IUMFC18H/I41P | | 12,800 | $640 |
| No | 208280155 | TRUST AIR CONDITIONERS | IS18H/O4S41P | IUMFC18H/I41P | | 12,800 | $640 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208816911 | TRUST AIR CONDITIONERS | OUS18H/O4S4P | IUMW118H/I41P | | 14,900 | $745 |
| No | 208816921 | TRUST AIR CONDITIONERS | OUS24H/O4S4P | IUMC424H/I41P | | 19,000 | $950 |
| No | 208280078 | TRUST AIR CONDITIONERS | IS24H/O4S41P | IUMC424H/I41P | | 19,000 | $950 |
| No | 208280125 | TRUST AIR CONDITIONERS | OAH36H/O4S41P | IUMDL36H/I43P | | 34,000 | $1,700 |
| No | 208280109 | TRUST AIR CONDITIONERS | OUS48H/O4S41P | IUMDL48H/I43P | | 34,000 | $1,700 |
| No | 208280082 | TRUST AIR CONDITIONERS | OUS48H/O4S41P | IUMC448H/I41P | | 30,000 | $1,500 |
| No | 208280163 | TRUST AIR CONDITIONERS | OUS48H/O4S41P | IUMFC48H/I41P | | 29,000 | $1,450 |
| No | 208280107 | TRUST AIR CONDITIONERS | OUS36H/O4S41P | IUMDL36H/I43P | | 25,000 | $1,250 |
| No | 208280080 | TRUST AIR CONDITIONERS | OUS36H/O4S41P | IUMC436H/I41P | | 23,000 | $1,150 |
| No | 208280161 | TRUST AIR CONDITIONERS | OUS36H/O4S41P | IUMFC36H/I41P | | 23,000 | $1,150 |
| No | 208280058 | TRUST AIR CONDITIONERS | IS09H/O4S41P | IS06H/I4S41P | | 8,500 | $425 |
| No | 208816913 | TRUST AIR CONDITIONERS | OUS09H/O4S4P | IUMW106H/I41P | | 8,500 | $425 |
| No | 208816912 | TRUST AIR CONDITIONERS | OUS24H/O4S4P | IUMW124H/I41P | | 16,200 | $810 |
| No | 208280055 | TRUST AIR CONDITIONERS | IS24H/O4S41P | IS24H/I4S41P | | 16,200 | $810 |
| No | 208816910 | TRUST AIR CONDITIONERS | OUS12H/O4S4P | IUMW112H/I41P | | 9,000 | $450 |
| No | 208280051 | TRUST AIR CONDITIONERS | IS12H/O4S41P | IS12H/I4S41P | | 9,000 | $450 |
| No | 208280048 | TRUST AIR CONDITIONERS | IS09H/O4S41P | IS09H/I4S41P | | 8,500 | $425 |
| No | 208816909 | TRUST AIR CONDITIONERS | OUS09H/O4S4P | IUMW109H/I41P | | 8,500 | $425 |
| No | 208280036 | TRUST AIR CONDITIONERS | CE24H/O4S41P | CE24H/I4S41P | | 16,500 | $825 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208280033 | TRUST AIR CONDITIONERS | CE18H/O4S41P | CE18H/I4S41P | | 11,400 | $570 |
| No | 208280030 | TRUST AIR CONDITIONERS | CE12H/O4S41P | CE12H/I4S41P | | 7,000 | $350 |
| No | 208280028 | TRUST AIR CONDITIONERS | CE09H/O4S41P | CE09H/I4S41P | | 6,000 | $300 |
| No | 208280025 | TRUST AIR CONDITIONERS | CE12H/O4S41R | CE12H/I4S41R | | 7,800 | $390 |
| No | 208816929 | TRUST AIR CONDITIONERS | OUS24H/O4S4P | IUMDL24H/I43P | | 20,000 | $1,000 |
| No | 208280104 | TRUST AIR CONDITIONERS | IS24H/O4S41P | IUMDL24H/I43P | | 20,000 | $1,000 |
| No | 208280089 | TRUST AIR CONDITIONERS | AS18H/O4S41P | IUMC418H/I41P | | 15,600 | $780 |
| No | 208816924 | TRUST AIR CONDITIONERS | OAH18H/O4S4P | IUMC418H/I41P | | 15,600 | $780 |
| No | 208280165 | TRUST AIR CONDITIONERS | AS18H/O4S41P | IUMFC18H/I41P | | 12,000 | $600 |
| No | 208816938 | TRUST AIR CONDITIONERS | OAH18H/O4S4P | IUMFC18H/I41P | | 12,000 | $600 |
| No | 208816935 | TRUST AIR CONDITIONERS | OAH12H/O4S4P | IUMCO12H/I41P | | 9,600 | $480 |
| No | 208280132 | TRUST AIR CONDITIONERS | AS12H/O4S41P | IUMCO12H/I41P | | 9,600 | $480 |
| No | 208280117 | TRUST AIR CONDITIONERS | AS12H/O4S41P | IUMDL12H/I43P | | 10,600 | $530 |
| No | 208816931 | TRUST AIR CONDITIONERS | OAH12H/O4S4P | IUMDL12H/I43P | | 10,600 | $530 |
| No | 208816923 | TRUST AIR CONDITIONERS | OAH12H/O4S4P | IUMC412H/I41P | | 9,900 | $495 |
| No | 208280086 | TRUST AIR CONDITIONERS | AS12H/O4S41P | IUMC412H/I41P | | 9,900 | $495 |
| No | 208280129 | TRUST AIR CONDITIONERS | IS12H/O4S41P | IUMCO12H/I41P | | 9,000 | $450 |
| No | 208816934 | TRUST AIR CONDITIONERS | OUS12H/O4S4P | IUMCO12H/I41P | | 9,000 | $450 |
| No | 208816927 | TRUST AIR CONDITIONERS | OUS12H/O4S4P | IUMDL12H/I43P | | 9,300 | $465 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208280099 | TRUST AIR CONDITIONERS | IS12H/O4S41P | IUMDL12H/I43P | | 9,300 | $465 |
| No | 208280115 | TRUST AIR CONDITIONERS | AS09H/O4S41P | IUMDL09H/I43P | | 10,100 | $505 |
| No | 208816930 | TRUST AIR CONDITIONERS | OAH09H/O4S4P | IUMDL09H/I43P | | 10,100 | $505 |
| No | 208816922 | TRUST AIR CONDITIONERS | OAH09H/O4S4P | IUMC409H/I41P | | 9,000 | $450 |
| No | 208280085 | TRUST AIR CONDITIONERS | AS09H/O4S41P | IUMC409H/I41P | | 9,000 | $450 |
| No | 208280097 | TRUST AIR CONDITIONERS | IS09H/O4S41P | IUMDL09H/I43P | | 7,700 | $385 |
| No | 208816926 | TRUST AIR CONDITIONERS | OUS09H/O4S4P | IUMDL09H/I43P | | 7,700 | $385 |
| No | 208280159 | TRUST AIR CONDITIONERS | IS24H/O4S41P | IUMFC24H/I41P | | 16,000 | $800 |
| No | 208816937 | TRUST AIR CONDITIONERS | OUS24H/O4S4P | IUMFC24H/I41P | | 16,000 | $800 |
| No | 208280074 | TRUST AIR CONDITIONERS | IS12H/O4S41P | IUMC412H/I41P | | 8,900 | $445 |
| No | 208816919 | TRUST AIR CONDITIONERS | OUS12H/O4S4P | IUMC412H/I41P | | 8,900 | $445 |
| No | 208816918 | TRUST AIR CONDITIONERS | OUS09H/O4S4P | IUMC409H/I41P | | 7,500 | $375 |
| No | 208280070 | TRUST AIR CONDITIONERS | IS09H/O4S41P | IUMC409H/I41P | | 7,500 | $375 |
| No | 208280062 | TRUST AIR CONDITIONERS | AS12H/O4S41P | IS12H/I4S41P | | 10,000 | $500 |
| No | 208816915 | TRUST AIR CONDITIONERS | OAH12H/O4S4P | IUMW112H/I41P | | 10,000 | $500 |
| No | 208816914 | TRUST AIR CONDITIONERS | OAH09H/O4S4P | IUMW109H/I41P | | 9,500 | $475 |
| No | 208280061 | TRUST AIR CONDITIONERS | AS09H/O4S41P | IS09H/I4S41P | | 9,500 | $475 |
| No | 208280044 | TRUST AIR CONDITIONERS | IS12H/O4S41R | IS12H/I4S41R | | 8,400 | $420 |
| No | 208280023 | TRUST AIR CONDITIONERS | CE09H/O4S41R | CE09H/I4S41R | | 6,300 | $315 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208284490 | TRUST AIR CONDITIONERS | M3H27H/O4S4P | Combination heat pumps with or without ducts | | 17,000 | $850 |
| No | 208284487 | TRUST AIR CONDITIONERS | M2H18H/O4S4P | Combination heat pumps with or without ducts | | 11,500 | $575 |
| No | 208284484 | TRUST AIR CONDITIONERS | M5S48H/O4S4P | Combination heat pumps with or without ducts | | 30,000 | $1,500 |
| No | 208284483 | TRUST AIR CONDITIONERS | M5S48H/O4S4P | Heat pump with ducts | | 30,400 | $1,520 |
| No | 208284478 | TRUST AIR CONDITIONERS | M3S27H/O4S4P | Combination heat pumps with or without ducts | | 16,000 | $800 |
| No | 208284475 | TRUST AIR CONDITIONERS | M2S18H/O4S4P | Combination heat pumps with or without ducts | | 11,400 | $570 |
| No | 208284010 | TRUST AIR CONDITIONERS | AH30H/O44P | AH30H/I44P | | 19,000 | $950 |
| No | 208280042 | TRUST AIR CONDITIONERS | CE36H/O4S41P | CE36H/I4S41P | | 20,000 | $1,000 |
| No | 208280053 | TRUST AIR CONDITIONERS | IS18H/O4S41P | IS18H/I4S41P | | 12,700 | $635 |
| No | 208280112 | TRUST AIR CONDITIONERS | OUS60H/O4S41P | IUMDL60H/I43P | | 37,000 | $1,850 |
| No | 205725746 | ULTRA MAXI AIR | LSAB-18HRDN1 | LSAB-18HRDN1 | | 11,500 | $575 |
| No | 207524718 | UTOPIAN SYSTEMS | 23935 | 23934 | | 17,400 | $870 |
| No | 205497614 | VALIEV | VWSM-18IR410AHS21 | VWSM-18IR410AHS21 | | 10,400 | $520 |
| No | 206347314 | VALIEV | VWSM-12IR410AHS21L | VWSM-12IR410AHS21L | | 7,100 | $355 |
| No | 211126529 | Viking Air | XJ23-24-4C-HC-2-M | XJ23-24-4E-HC-2-M | | 16,500 | $825 |
| No | 211126528 | Viking Air | XJ23-18-4C-HC-2-M | XJ23-18-4E-HC-2-M | | 16,500 | $825 |
| No | 211126527 | Viking Air | XJ23-12-4C-HC-2-M | XJ23-12-4E-HC-2-M | | 11,400 | $570 |
| No | 211126526 | Viking Air | XJ23-09-4C-HC-2-M | XJ23-09-4E-HC-2-M | | 7,000 | $350 |
| No | 211126525 | Viking Air | XJ23-12-4C-HC-1-110V | XJ23-12-4E-HC-1-110V | | 6,000 | $300 |
| No | 211126524 | Viking Air | XJ23-09-4C-HC-1-110V | XJ23-09-4E-HC-1-110V | | 7,800 | $390 |
| No | 211126523 | Viking Air | XJ21-24-4C-HC-2-M | XJ21-24-4E-HC-2-M | | 6,300 | $315 |
| No | 211164223 | WABBAN | BB12HXCA5DO | BB12HXCA5DI | | 6,800 | $340 |
| No | 211164222 | WABBAN | BB09HXCA5DO | BB09HXCA5DI | | 6,000 | $300 |
| No | 211177535 | WABBAN | BB24HXCA5DO | BB24HXCA5DI | | 13,900 | $695 |
| No | 211164249 | WABBAN | BB12HXCA5AO | BB12HXCA5AI | | 6,800 | $340 |
| No | 211164250 | WABBAN | BB18HXCA5DO | BB18HXCA5DI | | 11,200 | $560 |
| No | 211164251 | WABBAN | BB09HXCA5AO | BB09HXCA5AI | | 6,000 | $300 |
| No | 211717278 | WABBAN | BB30HXQ2B2DO | BB30HXQ2B2DI | | 17,500 | $875 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211717279 | WABBAN | BB36HXQ2B2DO | BB36HXQ2B2DI | | 22,000 | $1,100 |
| No | 210627716 | WABBAN | BB09HXP2A1DO | BB09HXP2A1DI | | 7,000 | $350 |
| No | 210627717 | WABBAN | BB12HXP2A1DO | BB12HXP2A1DI | | 7,000 | $350 |
| No | 210627719 | WABBAN | BB18HXP2A1DO | BB18HXP2A1DI | | 11,000 | $550 |
| No | 210627718 | WABBAN | BB24HXP2A1DO | BB24HXP2A1DI | | 15,000 | $750 |
| No | 211174351 | WABBAN | BBM18HX4O | Heat pump without ducts | | 14,700 | $735 |
| No | 211174352 | WABBAN | BBM24HX4O | Heat pump without ducts | | 23,600 | $1,180 |
| No | 211174353 | WABBAN | BBM30HX4O | Heat pump without ducts | | 27,200 | $1,360 |
| No | 201903177 | WABBAN | BBM24H4O | Heat pump without ducts | | 16,600 | $830 |
| No | 201903178 | WABBAN | BBM30H4O | Heat pump without ducts | | 18,000 | $900 |
| No | 201903181 | WABBAN | BBM42H4O | Heat pump without ducts | | 29,000 | $1,450 |
| No | 201903173 | WABBAN | BB12HQ3D6DO | BB12HQ3D6DI | | 8,300 | $415 |
| No | 201903165 | WABBAN | BB12HQ2A3DO | BB12HQ2A3DI | | 7,700 | $385 |
| No | 201903164 | WABBAN | BB09HQ2A3DO | BB09HQ2A3DI | | 6,800 | $340 |
| No | 201903171 | WABBAN | BB09HQ3D6DO | BB09HQ3D6DI | | 5,600 | $280 |
| No | 201903176 | WABBAN | BBM18H4O | Heat pump without ducts | | 12,800 | $640 |
| No | 201903180 | WABBAN | BBM36H4O | Heat pump without ducts | | 20,000 | $1,000 |
| No | 208102135 | WEATHERMAKER | 38MARBQ30AA311 | DHMAHBQ30XA3 | | 19,000 | $950 |
| No | 206350310 | WEATHERMAKER | 38MARBQ30AA3 | DHMAHBQ30XA3 | | 19,000 | $950 |
| No | 208447910 | WEATHERMAKER | 38MURAQ60AA3 | 40MUAAQ60XA3 | | 37,000 | $1,850 |
| No | 208447912 | WEATHERMAKER | 38MURAQ48AA3 | 40MUAAQ48XA3 | | 37,000 | $1,850 |
| No | 208447908 | WEATHERMAKER | 38MURAQ36AA3 | 40MUAAQ36XA3 | | 20,400 | $1,020 |
| No | 209852147 | WEATHERMAKER | 38MURAQ30AB3 | 40MUAAQ30XA3 | | 21,000 | $1,050 |
| No | 208447911 | WEATHERMAKER | 38MURAQ30AA3 | 40MUAAQ30XA3 | | 20,000 | $1,000 |
| No | 208447909 | WEATHERMAKER | 38MURAQ24AA3 | 40MUAAQ24XA3 | | 21,000 | $1,050 |
| No | 208447907 | WEATHERMAKER | 38MURAQ18AA3 | 40MUAAQ18XA3 | | 12,000 | $600 |
| No | 207642957 | WEATHERMAKER | 38MGRBQ48EA3 | Heat pump without ducts | | 29,600 | $1,480 |
| No | 207826678 | WEATHERMAKER | 38MBRCQ58AA3 | 40MBABQ60XA3 | | 34,000 | $1,700 |
| No | 207826677 | WEATHERMAKER | 38MBRCQ48AA3 | 40MBABQ48XA3 | | 37,400 | $1,870 |
| No | 207826676 | WEATHERMAKER | 38MBRCQ36AA3 | 40MBABQ36XA3 | | 25,600 | $1,280 |
| No | 208104306 | WEATHERMAKER | 38MARBQ36AB3 | 40MBABQ36XB3 | | 25,600 | $1,280 |
| No | 208104305 | WEATHERMAKER | 38MARBQ30AA311 | 40MBABQ30XB3 | | 19,200 | $960 |
| No | 207642943 | WEATHERMAKER | 38MGHBQ24CA3 | Heat pump with ducts | | 18,500 | $925 |
| No | 207642958 | WEATHERMAKER | 38MGRBQ48EA3 | Heat pump with ducts | | 30,400 | $1,520 |
| No | 207642940 | WEATHERMAKER | 38MGRBQ18BA3 | Heat pump with ducts | | 11,800 | $590 |
| No | 207642944 | WEATHERMAKER | 38MGHBQ24CA3 | Combination heat pumps with or without ducts | | 16,700 | $835 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207642941 | WEATHERMAKER | 38MGRBQ18BA3 | Combination heat pumps with or without ducts | | 11,400 | $570 |
| No | 207642942 | WEATHERMAKER | 38MGHBQ24CA3 | Heat pump without ducts | | 15,000 | $750 |
| No | 207642959 | WEATHERMAKER | 38MGRBQ48EA3 | Combination heat pumps with or without ducts | | 30,000 | $1,500 |
| No | 207642939 | WEATHERMAKER | 38MGRBQ18BA3 | Heat pump without ducts | | 11,000 | $550 |
| No | 207642948 | WEATHERMAKER | 38MGRBQ36DA3 | Heat pump without ducts | | 23,400 | $1,170 |
| No | 206400666 | WEATHERMAKER | 38MARBQ09AA3 | DHMSHAQ09XA3 | | 7,500 | $375 |
| No | 206350361 | WEATHERMAKER | 38MARBQ09AA3 | 40MBDQ09--3 | | 6,400 | $320 |
| No | 206350324 | WEATHERMAKER | 38MARBQ12AA3 | DHMAHBQ12XA3 | | 7,500 | $375 |
| No | 206350325 | WEATHERMAKER | 38MARBQ18AA3 | DHMAHBQ18XA3 | | 10,800 | $540 |
| No | 206350360 | WEATHERMAKER | 38MARBQ09AA3 | 40MBCQ09--3 | | 6,100 | $305 |
| No | 206188270 | WEATHERMAKER | 38MBRBQ36AA3 | 40MBDQ36---3 | | 27,000 | $1,350 |
| No | 206188273 | WEATHERMAKER | 38MBRBQ48AA3 | 40MBDQ48---3 | | 29,000 | $1,450 |
| No | 206350363 | WEATHERMAKER | 38MARBQ12AA3 | 40MBDQ12--3 | | 8,300 | $415 |
| No | 205788721 | WEATHERMAKER | 38MBRBQ48AA3 | 40MBAAQ48XA3 | | 36,000 | $1,800 |
| No | 205788720 | WEATHERMAKER | 38MBRBQ36AA3 | 40MBAAQ36XA3 | | 25,000 | $1,250 |
| No | 206396060 | WEATHERMAKER | 38MAQB18R--3 | DHMAHBQ18XA3 | | 11,000 | $550 |
| No | 206396059 | WEATHERMAKER | 38MAQB12R--3 | DHMAHBQ12XA3 | | 7,500 | $375 |
| No | 206400668 | WEATHERMAKER | 38MARBQ18AA3 | DHMSHAQ18XA3 | | 10,800 | $540 |
| No | 206396061 | WEATHERMAKER | 38MAQB24R--3 | DHMAHBQ24XA3 | | 18,800 | $940 |
| No | 206400669 | WEATHERMAKER | 38MARBQ24AA3 | DHMSHAQ24XA3 | | 19,800 | $990 |
| No | 206396058 | WEATHERMAKER | 38MAQB09R--3 | DHMAHBQ09XA3 | | 7,000 | $350 |
| No | 206350322 | WEATHERMAKER | 38MARBQ12AA1 | DHMAHBQ12XA1 | | 7,400 | $370 |
| No | 206400667 | WEATHERMAKER | 38MARBQ12AA3 | DHMSHAQ12XA3 | | 7,500 | $375 |
| No | 206350362 | WEATHERMAKER | 38MARBQ12AA3 | 40MBCQ12--3 | | 7,900 | $395 |
| No | 206188272 | WEATHERMAKER | 38MBRBQ48AA3 | 40MBCQ48---3 | | 29,000 | $1,450 |
| No | 206350323 | WEATHERMAKER | 38MARBQ09AA3 | DHMAHBQ09XA3 | | 7,500 | $375 |
| No | 206188269 | WEATHERMAKER | 38MBRBQ36AA3 | 40MBCQ36---3 | | 22,000 | $1,100 |
| No | 206188271 | WEATHERMAKER | 38MBRBQ48AA3 | 40MBFQ48---3 | | 29,000 | $1,450 |
| No | 206350364 | WEATHERMAKER | 38MARBQ12AA3 | 40MBFQ12--3 | | 8,400 | $420 |
| No | 206188268 | WEATHERMAKER | 38MBRBQ36AA3 | 40MBFQ36---3 | | 22,000 | $1,100 |
| No | 207337195 | WESTINGHOUSE | WHZ12SZA21S | WHZ12WMA21S | | 7,000 | $350 |
| No | 207337194 | WESTINGHOUSE | WHZ09SZA21S | WHZ09WMA21S | | 6,000 | $300 |
| No | 205417836 | WESTINGHOUSE | WHP18SZA21S | WHP18WMA21S | | 11,600 | $580 |
| No | 205417834 | WESTINGHOUSE | WHP12SZA21S | WHP12WMA21S | | 7,500 | $375 |
| No | 205417832 | WESTINGHOUSE | WHP09SZA21S | WHP09WMA21S | | 5,000 | $250 |
| No | 208404160 | WESTINGHOUSE | WHP42M5A21S | Heat pump with ducts | | 28,400 | $1,420 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208404161 | WESTINGHOUSE | WHP42M5A21S | Combination heat pumps with or without ducts | | 27,600 | $1,380 |
| No | 206517597 | WESTINGHOUSE | WHP42M5A21S | Heat pump without ducts | | 27,000 | $1,350 |
| No | 208404158 | WESTINGHOUSE | WHP36M4A21S | Heat pump with ducts | | 23,000 | $1,150 |
| No | 208404159 | WESTINGHOUSE | WHP36M4A21S | Combination heat pumps with or without ducts | | 22,600 | $1,130 |
| No | 205446269 | WESTINGHOUSE | WHP36M4A21S | Heat pump without ducts | | 22,400 | $1,120 |
| No | 208404156 | WESTINGHOUSE | WHP24M3A21S | Heat pump with ducts | | 14,600 | $730 |
| No | 208404157 | WESTINGHOUSE | WHP24M3A21S | Combination heat pumps with or without ducts | | 14,800 | $740 |
| No | 205470409 | WESTINGHOUSE | WHP24M3A21S | Heat pump without ducts | | 15,000 | $750 |
| No | 208404154 | WESTINGHOUSE | WHP18M2A21S | Heat pump with ducts | | 12,700 | $635 |
| No | 208404155 | WESTINGHOUSE | WHP18M2A21S | Combination heat pumps with or without ducts | | 12,700 | $635 |
| No | 205470408 | WESTINGHOUSE | WHP18M2A21S | Heat pump without ducts | | 12,700 | $635 |
| No | 207506892 | WESTINGHOUSE | WHM60SZA21S | WHM60DMA21S | | 40,000 | $2,000 |
| No | 207506891 | WESTINGHOUSE | WHM48SZA21S | WHM48DMA21S | | 31,000 | $1,550 |
| No | 207506890 | WESTINGHOUSE | WHM36SZA21S | WHM36DMA21S | | 24,000 | $1,200 |
| No | 207506889 | WESTINGHOUSE | WHM24SZA21S | WHM24DMA21S | | 15,000 | $750 |
| No | 207237539 | WESTINGHOUSE | WHU36SZA21S | WHU36CTA21S | | 28,000 | $1,400 |
| No | 207237538 | WESTINGHOUSE | WHU24SZA21S | WHU24CTA21S | | 19,000 | $950 |
| No | 207237537 | WESTINGHOUSE | WHU18SZA21S | WHU18CTA21S | | 12,000 | $600 |
| No | 207237536 | WESTINGHOUSE | WHU12SZA21S | WHU12CTA21S | | 7,600 | $380 |
| No | 207237535 | WESTINGHOUSE | WHU09SZA21S | WHU09CTA21S | | 7,200 | $360 |
| No | 207237544 | WESTINGHOUSE | WHU36SZA21S | WHU36DHA21S | | 28,400 | $1,420 |
| No | 207237542 | WESTINGHOUSE | WHU18SZA21S | WHU18DHA21S | | 13,000 | $650 |
| No | 207237541 | WESTINGHOUSE | WHU12SZA21S | WHU12DHA21S | | 7,800 | $390 |
| No | 207237540 | WESTINGHOUSE | WHU09SZA21S | WHU09DHA21S | | 6,500 | $325 |
| No | 9038619 | WILLIS | WUHO12KW22S | WUHI12KHW | | 7,800 | $390 |
| No | 9038618 | WILLIS | WUHO09KW25S | WUHI09KHW | | 6,900 | $345 |
| No | 9038626 | WILLIS | WSM09MH20S/O | WSM09MH20S/I | | 6,300 | $315 |
| No | 9038629 | WILLIS | WSM24MH20S/O | WSM24MH20S/I | | 16,000 | $800 |
| No | 208106988 | YONAN | YOE-60HFN1 | YHG-60HWFN1 | | 34,400 | $1,720 |
| No | 208106989 | YONAN | YOE-60HFN1 | YUE-60HRFN1 | | 35,000 | $1,750 |
| No | 207671407 | YONAN | YSA21-24HRN1 | YSA21-24HRN1 | | 18,000 | $900 |
| No | 207691827 | YONAN | YSMO-36HRN1 | Heat pump without ducts | | 26,400 | $1,320 |
| No | 207691833 | YONAN | YSMO-30HRN1 | Heat pump without ducts | | 20,000 | $1,000 |
| No | 207691834 | YONAN | YSMO-30HRN1 | Heat pump with ducts | | 22,000 | $1,100 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207691825 | YONAN | YSMO-18HRN1 | Heat pump with ducts | | 14,800 | $740 |
| No | 207691830 | YONAN | YSMO-48HRN1 | Heat pump without ducts | | 36,000 | $1,800 |
| No | 207691824 | YONAN | YSMO-18HRN1 | Heat pump without ducts | | 14,400 | $720 |
| No | 208106977 | YONAN | YOX-18HFN1 | YTI-18HWFN1 | | 12,600 | $630 |
| No | 208106976 | YONAN | YOX-18HFN1 | YCA-18HRFN1 | | 12,000 | $600 |
| No | 208106978 | YONAN | YOX-18HFN1 | YUE-18HRFN1 | | 12,800 | $640 |
| No | 207671410 | YONAN | YSA25-18HRN1 | YSA25-18HRN1 | | 14,900 | $745 |
| No | 207671405 | YONAN | YSA21-12HRN1 | YSA21-12HRN1 | | 8,200 | $410 |
| No | 207671404 | YONAN | YSA21-09HRN1 | YSA21-09HRN1 | | 8,300 | $415 |
| No | 207671402 | YONAN | YSA21-09HRN1B | YSA21-09HRN1B | | 6,000 | $300 |
| No | 207671406 | YONAN | YSA21-18HRN1 | YSA21-18HRN1 | | 14,000 | $700 |
| No | 207671403 | YONAN | YSA21-12HRN1B | YSA21-12HRN1B | | 8,400 | $420 |
| No | 207671400 | YONAN | YSA19-18HRN1 | YSA19-18HRN1 | | 11,500 | $575 |
| No | 207671398 | YONAN | YSA19-09HRN1 | YSA19-09HRN1 | | 6,900 | $345 |
| No | 207671396 | YONAN | YSA19-09HRN1B | YSA19-09HRN1B | | 6,800 | $340 |
| No | 208106979 | YONAN | YOD-24HFN1 | YCD-24HRFN1 | | 19,000 | $950 |
| No | 208106986 | YONAN | YOE-48HFN1 | YTI-48HWFN1 | | 34,000 | $1,700 |
| No | 208106985 | YONAN | YOE-48HFN1 | YCD-48HRFN1 | | 30,000 | $1,500 |
| No | 208106987 | YONAN | YOE-48HFN1 | YUE-48HRFN1 | | 29,000 | $1,450 |
| No | 208106983 | YONAN | YOD-36HFN1 | YTI-36HWFN1 | | 25,000 | $1,250 |
| No | 208106982 | YONAN | YOD-36HFN1 | YCD-36HRFN1 | | 23,000 | $1,150 |
| No | 208106984 | YONAN | YOD-36HFN1 | YUE-36HRFN1 | | 23,000 | $1,150 |
| No | 207671413 | YONAN | YSA19-36HRN1 | YSA19-36HRN1 | | 24,000 | $1,200 |
| No | 207671411 | YONAN | YSA25-24HRN1 | YSA25-24HRN1 | | 16,200 | $810 |
| No | 207671409 | YONAN | YSA25-12HRN1 | YSA25-12HRN1 | | 9,000 | $450 |
| No | 207671408 | YONAN | YSA25-09HRN1 | YSA25-09HRN1 | | 8,500 | $425 |
| No | 208106980 | YONAN | YOD-24HFN1 | YTI-24HWFN1 | | 20,000 | $1,000 |
| No | 208106975 | YONAN | YOX-12HFN1 | YTI-12HWFN1 | | 9,300 | $465 |
| No | 208106973 | YONAN | YOX-09HFN1 | YTI-09HWFN1 | | 7,700 | $385 |
| No | 208106981 | YONAN | YOD-24HFN1 | YUE-24HRFN1 | | 16,000 | $800 |
| No | 208106974 | YONAN | YOX-12HFN1 | YCA-12HRFN1 | | 8,900 | $445 |
| No | 208106972 | YONAN | YOX-09HFN1 | YCA-09HRFN1 | | 7,500 | $375 |
| No | 211380164 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TL8E100C20UH11 | 24,800 | $1,240 |
| No | 211380161 | YORK | HMH72B341 | XAHD48FBCN1 | TL8E100C20UH11 | 24,800 | $1,240 |
| No | 211380158 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TL8E100C20UH11 | 24,800 | $1,240 |
| No | 211380155 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TL9E060B12UH11 | 25,800 | $1,290 |
| No | 211380152 | YORK | HMH72B341 | XAFC48FBCN1 | TL9E060B12UH11 | 25,800 | $1,290 |
| No | 211380149 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TL9E060B12UH11 | 25,800 | $1,290 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211380146 | YORK | HMH72B341 | XAHC48FBCN1 | TL9E060B12UH11 | 25,200 | $1,260 |
| No | 211380143 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TL9E060B12UH11 | 25,200 | $1,260 |
| No | 211380140 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TL9E080C16UH11 | 25,800 | $1,290 |
| No | 211380137 | YORK | HMH72B341 | XAFC48FBCN1 | TL9E080C16UH11 | 25,800 | $1,290 |
| No | 211380134 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TL9E080C16UH11 | 25,800 | $1,290 |
| No | 211380131 | YORK | HMH72B341 | XAFD48FBCN1 | TL9E080C16UH11 | 25,600 | $1,280 |
| No | 211380128 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TL9E080C16UH11 | 25,600 | $1,280 |
| No | 211380125 | YORK | HMH72B341 | XAHC48FBCN1 | TL9E080C16UH11 | 25,200 | $1,260 |
| No | 211380122 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TL9E080C16UH11 | 25,200 | $1,260 |
| No | 211380119 | YORK | HMH72B341 | XAHD48FBCN1 | TL9E080C16UH11 | 25,200 | $1,260 |
| No | 211380116 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TL9E080C16UH11 | 25,200 | $1,260 |
| No | 211380113 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211380111 | YORK | HMH72B341 | XAFC48FBCN1 | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211380108 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211380105 | YORK | HMH72B341 | XAFD48FBCN1 | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211380102 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TL9E100C20UH11 | 25,400 | $1,270 |
| No | 211380099 | YORK | HMH72B341 | XAHC48FBCN1 | TL9E100C20UH11 | 25,000 | $1,250 |
| No | 211380097 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TL9E100C20UH11 | 25,000 | $1,250 |
| No | 211380094 | YORK | HMH72B341 | XAHD48FBCN1 | TL9E100C20UH11 | 25,000 | $1,250 |
| No | 211380091 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TL9E100C20UH11 | 25,000 | $1,250 |
| No | 211380088 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TMLE080B12MP11 | 25,600 | $1,280 |
| No | 211380085 | YORK | HMH72B341 | XAFC48FBCN1 | TMLE080B12MP11 | 25,600 | $1,280 |
| No | 211380082 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TM8E080B12MP11 | 25,600 | $1,280 |
| No | 211380079 | YORK | HMH72B341 | XAFC48FBCN1 | TM8E080B12MP11 | 25,600 | $1,280 |
| No | 211380076 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TMLE080B12MP11 | 25,600 | $1,280 |
| No | 211380074 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TM8E080B12MP11 | 25,600 | $1,280 |
| No | 211380071 | YORK | HMH72B341 | XAHC48FBCN1 | TMLE080B12MP11 | 25,400 | $1,270 |
| No | 211380068 | YORK | HMH72B341 | XAHC48FBCN1 | TM8E080B12MP11 | 25,400 | $1,270 |
| No | 211380065 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TMLE080B12MP11 | 25,400 | $1,270 |
| No | 211380063 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TM8E080B12MP11 | 25,400 | $1,270 |
| No | 211380060 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211380057 | YORK | HMH72B341 | XAFC48FBCN1 | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211380054 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211380051 | YORK | HMH72B341 | XAFC48FBCN1 | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211380048 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211380045 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211380043 | YORK | HMH72B341 | XAFD48FBCN1 | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211380040 | YORK | HMH72B341 | XAFD48FBCN1 | TM8E080C16MP11 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211380037 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211380034 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211380031 | YORK | HMH72B341 | XAHC48FBCN1 | TMLE080C16MP11 | 24,800 | $1,240 |
| No | 211380028 | YORK | HMH72B341 | XAHC48FBCN1 | TM8E080C16MP11 | 24,800 | $1,240 |
| No | 211380025 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TMLE080C16MP11 | 24,800 | $1,240 |
| No | 211380022 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TM8E080C16MP11 | 24,800 | $1,240 |
| No | 211380019 | YORK | HMH72B341 | XAHD48FBCN1 | TMLE080C16MP11 | 24,800 | $1,240 |
| No | 211380016 | YORK | HMH72B341 | XAHD48FBCN1 | TM8E080C16MP11 | 24,800 | $1,240 |
| No | 211380013 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TMLE080C16MP11 | 24,800 | $1,240 |
| No | 211380010 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TM8E080C16MP11 | 24,800 | $1,240 |
| No | 211380007 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211380004 | YORK | HMH72B341 | XAFC48FBCN1 | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211380001 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211379998 | YORK | HMH72B341 | XAFC48FBCN1 | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211379995 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211379992 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211379989 | YORK | HMH72B341 | XAHC48FBCN1 | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 211379986 | YORK | HMH72B341 | XAHC48FBCN1 | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 211379983 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 211379980 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 211379977 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211379974 | YORK | HMH72B341 | XAFC48FBCN1 | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211379972 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211379969 | YORK | HMH72B341 | XAFC48FBCN1 | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211379966 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211379963 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211379960 | YORK | HMH72B341 | XAFD48FBCN1 | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211379957 | YORK | HMH72B341 | XAFD48FBCN1 | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211379954 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TMLE100C16MP11 | 25,400 | $1,270 |
| No | 211379952 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TM8E100C16MP11 | 25,400 | $1,270 |
| No | 211379949 | YORK | HMH72B341 | XAHC48FBCN1 | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211379946 | YORK | HMH72B341 | XAHC48FBCN1 | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211379943 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211379940 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211379937 | YORK | HMH72B341 | XAHD48FBCN1 | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211379935 | YORK | HMH72B341 | XAHD48FBCN1 | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211379932 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211379929 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TM8E100C16MP11 | 24,800 | $1,240 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211379926 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TMLE120C16MP11 | 25,400 | $1,270 |
| No | 211379924 | YORK | HMH72B341 | XAFC48FBCN1 | TMLE120C16MP11 | 25,400 | $1,270 |
| No | 211379921 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TM8E120C16MP11 | 25,400 | $1,270 |
| No | 211379918 | YORK | HMH72B341 | XAFC48FBCN1 | TM8E120C16MP11 | 25,400 | $1,270 |
| No | 211379915 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TMLE120C16MP11 | 25,400 | $1,270 |
| No | 211379912 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TM8E120C16MP11 | 25,400 | $1,270 |
| No | 211379909 | YORK | HMH72B341 | XAFD48FBCN1 | TMLE120C16MP11 | 25,200 | $1,260 |
| No | 211379907 | YORK | HMH72B341 | XAFD48FBCN1 | TM8E120C16MP11 | 25,200 | $1,260 |
| No | 211379904 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TMLE120C16MP11 | 25,200 | $1,260 |
| No | 211379901 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TM8E120C16MP11 | 25,200 | $1,260 |
| No | 211379897 | YORK | HMH72B341 | XAHC48FBCN1 | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211379895 | YORK | HMH72B341 | XAHC48FBCN1 | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211379892 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211379890 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211379887 | YORK | HMH72B341 | XAHD48FBCN1 | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211379884 | YORK | HMH72B341 | XAHD48FBCN1 | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211379881 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211379877 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211379874 | YORK | HMH72B341 | XAUC48FXXN1+TXV | YPLC080B12MP13 | 25,800 | $1,290 |
| No | 211379871 | YORK | HMH72B341 | XAFC48FBCN1 | YPLC080B12MP13 | 25,800 | $1,290 |
| No | 211379868 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TPLC080B12MP13 | 25,800 | $1,290 |
| No | 211379866 | YORK | HMH72B341 | XAFC48FBCN1 | TPLC080B12MP13 | 25,800 | $1,290 |
| No | 211379863 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TM8V080B12MP12 | 25,800 | $1,290 |
| No | 211379860 | YORK | HMH72B341 | XAFC48FBCN1 | TM8V080B12MP12 | 25,800 | $1,290 |
| No | 211379858 | YORK | HMH72B341 | XAFC48FXXN1+TXV | YPLC080B12MP13 | 25,800 | $1,290 |
| No | 211379856 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TPLC080B12MP13 | 25,800 | $1,290 |
| No | 211379853 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TM8V080B12MP12 | 25,800 | $1,290 |
| No | 211379850 | YORK | HMH72B341 | XAHC48FBCN1 | YPLC080B12MP13 | 25,200 | $1,260 |
| No | 211379847 | YORK | HMH72B341 | XAHC48FBCN1 | TPLC080B12MP13 | 25,200 | $1,260 |
| No | 211379844 | YORK | HMH72B341 | XAHC48FBCN1 | TM8V080B12MP12 | 25,200 | $1,260 |
| No | 211379842 | YORK | HMH72B341 | XAHC48FXXN1+TXV | YPLC080B12MP13 | 25,200 | $1,260 |
| No | 211379839 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TPLC080B12MP13 | 25,200 | $1,260 |
| No | 211379836 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TM8V080B12MP12 | 25,200 | $1,260 |
| No | 211379834 | YORK | HMH72B341 | XAUC48FXXN1+TXV | YPLC100C16MP13 | 25,800 | $1,290 |
| No | 211379831 | YORK | HMH72B341 | XAFC48FBCN1 | YPLC100C16MP13 | 25,800 | $1,290 |
| No | 211379828 | YORK | HMH72B341 | XAUC48FXXN1+TXV | YPLC080C16MP13 | 25,800 | $1,290 |
| No | 211379825 | YORK | HMH72B341 | XAFC48FBCN1 | YPLC080C16MP13 | 25,800 | $1,290 |
| No | 211379822 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TPLC100C16MP13 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211379819 | YORK | HMH72B341 | XAFC48FBCN1 | TPLC100C16MP13 | 25,800 | $1,290 |
| No | 211379816 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TPLC080C16MP13 | 25,800 | $1,290 |
| No | 211379813 | YORK | HMH72B341 | XAFC48FBCN1 | TPLC080C16MP13 | 25,800 | $1,290 |
| No | 211379811 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211379809 | YORK | HMH72B341 | XAFC48FBCN1 | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211379802 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211379800 | YORK | HMH72B341 | XAFC48FBCN1 | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211379797 | YORK | HMH72B341 | XAFC48FXXN1+TXV | YPLC100C16MP13 | 25,800 | $1,290 |
| No | 211379794 | YORK | HMH72B341 | XAFC48FXXN1+TXV | YPLC080C16MP13 | 25,800 | $1,290 |
| No | 211379791 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TPLC100C16MP13 | 25,800 | $1,290 |
| No | 211379788 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TPLC080C16MP13 | 25,800 | $1,290 |
| No | 211379785 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211379779 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211379777 | YORK | HMH72B341 | XAFD48FBCN1 | YPLC100C16MP13 | 25,800 | $1,290 |
| No | 211379774 | YORK | HMH72B341 | XAFD48FBCN1 | YPLC080C16MP13 | 25,800 | $1,290 |
| No | 211379772 | YORK | HMH72B341 | XAFD48FBCN1 | TPLC100C16MP13 | 25,800 | $1,290 |
| No | 211379768 | YORK | HMH72B341 | XAFD48FBCN1 | TPLC080C16MP13 | 25,800 | $1,290 |
| No | 211379765 | YORK | HMH72B341 | XAFD48FBCN1 | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211379759 | YORK | HMH72B341 | XAFD48FBCN1 | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211379756 | YORK | HMH72B341 | XAFD48FXXN1+TXV | YPLC100C16MP13 | 25,800 | $1,290 |
| No | 211379753 | YORK | HMH72B341 | XAFD48FXXN1+TXV | YPLC080C16MP13 | 25,800 | $1,290 |
| No | 211379750 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TPLC100C16MP13 | 25,800 | $1,290 |
| No | 211379747 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TPLC080C16MP13 | 25,800 | $1,290 |
| No | 211379745 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TMLV100C16MP12 | 25,800 | $1,290 |
| No | 211379739 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TM8V100C16MP12 | 25,800 | $1,290 |
| No | 211379736 | YORK | HMH72B341 | XAHC48FBCN1 | YPLC100C16MP13 | 25,400 | $1,270 |
| No | 211379733 | YORK | HMH72B341 | XAHC48FBCN1 | YPLC080C16MP13 | 25,400 | $1,270 |
| No | 211379730 | YORK | HMH72B341 | XAHC48FBCN1 | TPLC100C16MP13 | 25,400 | $1,270 |
| No | 211379727 | YORK | HMH72B341 | XAHC48FBCN1 | TPLC080C16MP13 | 25,400 | $1,270 |
| No | 211379724 | YORK | HMH72B341 | XAHC48FBCN1 | TMLV100C16MP12 | 25,400 | $1,270 |
| No | 211379718 | YORK | HMH72B341 | XAHC48FBCN1 | TM8V100C16MP12 | 25,400 | $1,270 |
| No | 211379715 | YORK | HMH72B341 | XAHC48FXXN1+TXV | YPLC100C16MP13 | 25,400 | $1,270 |
| No | 211379712 | YORK | HMH72B341 | XAHC48FXXN1+TXV | YPLC080C16MP13 | 25,400 | $1,270 |
| No | 211379709 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TPLC100C16MP13 | 25,400 | $1,270 |
| No | 211379706 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TPLC080C16MP13 | 25,400 | $1,270 |
| No | 211379703 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TMLV100C16MP12 | 25,400 | $1,270 |
| No | 211379698 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TM8V100C16MP12 | 25,400 | $1,270 |
| No | 211379695 | YORK | HMH72B341 | XAHD48FBCN1 | YPLC100C16MP13 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211379692 | YORK | HMH72B341 | XAHD48FBCN1 | YPLC080C16MP13 | 25,200 | $1,260 |
| No | 211379689 | YORK | HMH72B341 | XAHD48FBCN1 | TPLC100C16MP13 | 25,200 | $1,260 |
| No | 211379686 | YORK | HMH72B341 | XAHD48FBCN1 | TPLC080C16MP13 | 25,200 | $1,260 |
| No | 211379684 | YORK | HMH72B341 | XAHD48FBCN1 | TMLV100C16MP12 | 25,200 | $1,260 |
| No | 211379681 | YORK | HMH72B341 | XAHD48FBCN1 | TM8V080C16MP12 | 25,200 | $1,260 |
| No | 211379678 | YORK | HMH72B341 | XAHD48FBCN1 | TM8V100C16MP12 | 25,200 | $1,260 |
| No | 211379675 | YORK | HMH72B341 | XAHD48FXXN1+TXV | YPLC100C16MP13 | 25,200 | $1,260 |
| No | 211379672 | YORK | HMH72B341 | XAHD48FXXN1+TXV | YPLC080C16MP13 | 25,200 | $1,260 |
| No | 211379669 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TPLC100C16MP13 | 25,200 | $1,260 |
| No | 211379667 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TPLC080C16MP13 | 25,200 | $1,260 |
| No | 211379664 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TMLV100C16MP12 | 25,200 | $1,260 |
| No | 211379661 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TM8V080C16MP12 | 25,200 | $1,260 |
| No | 211379658 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TM8V100C16MP12 | 25,200 | $1,260 |
| No | 211379655 | YORK | HMH72B341 | XAHC48FBCN1 | YPLC120C20MP13 | 25,200 | $1,260 |
| No | 211379652 | YORK | HMH72B341 | XAHC48FBCN1 | YPLC100C20MP13 | 25,200 | $1,260 |
| No | 211379649 | YORK | HMH72B341 | XAHC48FBCN1 | TPLC120C20MP13 | 25,200 | $1,260 |
| No | 211379647 | YORK | HMH72B341 | XAHC48FBCN1 | TPLC100C20MP13 | 25,200 | $1,260 |
| No | 211379644 | YORK | HMH72B341 | XAHC48FBCN1 | TMLV120C20MP12 | 25,200 | $1,260 |
| No | 211379642 | YORK | HMH72B341 | XAHC48FBCN1 | TM8V100C20MP12 | 25,200 | $1,260 |
| No | 211379639 | YORK | HMH72B341 | XAHC48FBCN1 | TM8V120C20MP12 | 25,200 | $1,260 |
| No | 211379636 | YORK | HMH72B341 | XAHC48FXXN1+TXV | YPLC120C20MP13 | 25,200 | $1,260 |
| No | 211379633 | YORK | HMH72B341 | XAHC48FXXN1+TXV | YPLC100C20MP13 | 25,200 | $1,260 |
| No | 211379630 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TPLC120C20MP13 | 25,200 | $1,260 |
| No | 211379627 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TPLC100C20MP13 | 25,200 | $1,260 |
| No | 211379624 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TMLV120C20MP12 | 25,200 | $1,260 |
| No | 211379621 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TM8V100C20MP12 | 25,200 | $1,260 |
| No | 211379618 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TM8V120C20MP12 | 25,200 | $1,260 |
| No | 211379615 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211379612 | YORK | HMH72B341 | XAFC48FBCN1 | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211379608 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211379605 | YORK | HMH72B341 | XAHC48FBCN1 | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211379602 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211379599 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TM8Y080C16MP11 | 25,800 | $1,290 |
| No | 211379596 | YORK | HMH72B341 | XAFC48FBCN1 | TM8Y080C16MP11 | 25,800 | $1,290 |
| No | 211379593 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211379590 | YORK | HMH72B341 | XAFC48FBCN1 | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211379475 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TM9E080B12MP12 | 25,600 | $1,280 |
| No | 211379587 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TM8Y080C16MP11 | 25,800 | $1,290 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211379472 | YORK | HMH72B341 | XAHC48FBCN1 | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211379584 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211379469 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211379582 | YORK | HMH72B341 | XAFD48FBCN1 | TM8Y080C16MP11 | 25,800 | $1,290 |
| No | 211379466 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TM9E080C16MP12 | 26,000 | $1,300 |
| No | 211379579 | YORK | HMH72B341 | XAFD48FBCN1 | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211379463 | YORK | HMH72B341 | XAFC48FBCN1 | TM9E080C16MP12 | 26,000 | $1,300 |
| No | 211379576 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TM8Y080C16MP11 | 25,800 | $1,290 |
| No | 211379460 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TM9E080C16MP12 | 26,000 | $1,300 |
| No | 211379573 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TM8Y100C16MP11 | 25,800 | $1,290 |
| No | 211379457 | YORK | HMH72B341 | XAFD48FBCN1 | TM9E080C16MP12 | 26,000 | $1,300 |
| No | 211379570 | YORK | HMH72B341 | XAHC48FBCN1 | TM8Y080C16MP11 | 25,400 | $1,270 |
| No | 211379454 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TM9E080C16MP12 | 26,000 | $1,300 |
| No | 211379568 | YORK | HMH72B341 | XAHC48FBCN1 | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211379451 | YORK | HMH72B341 | XAHC48FBCN1 | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211379449 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211379565 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TM8Y080C16MP11 | 25,400 | $1,270 |
| No | 211379562 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211379446 | YORK | HMH72B341 | XAHD48FBCN1 | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211379559 | YORK | HMH72B341 | XAHD48FBCN1 | TM8Y080C16MP11 | 25,400 | $1,270 |
| No | 211379443 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211379556 | YORK | HMH72B341 | XAHD48FBCN1 | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211379440 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211379553 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TM8Y080C16MP11 | 25,400 | $1,270 |
| No | 211379438 | YORK | HMH72B341 | XAFC48FBCN1 | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211379550 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211379435 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211379548 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TM8Y100C20MP11 | 25,600 | $1,280 |
| No | 211379432 | YORK | HMH72B341 | XAFD48FBCN1 | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211379545 | YORK | HMH72B341 | XAFC48FBCN1 | TM8Y100C20MP11 | 25,600 | $1,280 |
| No | 211379429 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TM9E100C16MP12 | 25,400 | $1,270 |
| No | 211379542 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TM8Y120C20MP11 | 25,600 | $1,280 |
| No | 211379426 | YORK | HMH72B341 | XAHC48FBCN1 | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211379539 | YORK | HMH72B341 | XAFC48FBCN1 | TM8Y120C20MP11 | 25,600 | $1,280 |
| No | 211379423 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211379537 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TM8Y100C20MP11 | 25,600 | $1,280 |
| No | 211379421 | YORK | HMH72B341 | XAHD48FBCN1 | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211379534 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TM8Y120C20MP11 | 25,600 | $1,280 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211379418 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211379415 | YORK | HMH72B341 | XAUC48FXXN1+TXV | YP9C060B12MP13 | 25,600 | $1,280 |
| No | 211379531 | YORK | HMH72B341 | XAFD48FBCN1 | TM8Y100C20MP11 | 25,600 | $1,280 |
| No | 211379528 | YORK | HMH72B341 | XAFD48FBCN1 | TM8Y120C20MP11 | 25,600 | $1,280 |
| No | 211379412 | YORK | HMH72B341 | XAFC48FBCN1 | YP9C060B12MP13 | 25,600 | $1,280 |
| No | 211379525 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TM8Y100C20MP11 | 25,600 | $1,280 |
| No | 211379409 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211379522 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TM8Y120C20MP11 | 25,600 | $1,280 |
| No | 211379406 | YORK | HMH72B341 | XAFC48FBCN1 | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211379519 | YORK | HMH72B341 | XAHC48FBCN1 | TM8Y100C20MP11 | 25,200 | $1,260 |
| No | 211379404 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211379516 | YORK | HMH72B341 | XAHC48FBCN1 | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211379401 | YORK | HMH72B341 | XAFC48FBCN1 | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211379514 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TM8Y100C20MP11 | 25,200 | $1,260 |
| No | 211379398 | YORK | HMH72B341 | XAFC48FXXN1+TXV | YP9C060B12MP13 | 25,600 | $1,280 |
| No | 211379511 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211379396 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211379508 | YORK | HMH72B341 | XAHD48FBCN1 | TM8Y100C20MP11 | 25,200 | $1,260 |
| No | 211379393 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211379389 | YORK | HMH72B341 | XAHC48FBCN1 | YP9C060B12MP13 | 25,200 | $1,260 |
| No | 211379505 | YORK | HMH72B341 | XAHD48FBCN1 | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211379386 | YORK | HMH72B341 | XAHC48FBCN1 | TP9C060B12MP13 | 25,200 | $1,260 |
| No | 211379502 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TM8Y100C20MP11 | 25,200 | $1,260 |
| No | 211379384 | YORK | HMH72B341 | XAHC48FBCN1 | TM9V060B12MP12 | 25,200 | $1,260 |
| No | 211379499 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211379381 | YORK | HMH72B341 | XAHC48FXXN1+TXV | YP9C060B12MP13 | 25,200 | $1,260 |
| No | 211379496 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211379493 | YORK | HMH72B341 | XAFC48FBCN1 | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211379379 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TP9C060B12MP13 | 25,200 | $1,260 |
| No | 211379490 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211379376 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TM9V060B12MP12 | 25,200 | $1,260 |
| No | 211379487 | YORK | HMH72B341 | XAHC48FBCN1 | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211379373 | YORK | HMH72B341 | XAUC48FXXN1+TXV | YP9C080B12MP13 | 25,600 | $1,280 |
| No | 211379484 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211379370 | YORK | HMH72B341 | XAFC48FBCN1 | YP9C080B12MP13 | 25,600 | $1,280 |
| No | 211379481 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TM9E080B12MP12 | 25,600 | $1,280 |
| No | 211379367 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TP9C080B12MP13 | 25,600 | $1,280 |
| No | 211379478 | YORK | HMH72B341 | XAFC48FBCN1 | TM9E080B12MP12 | 25,600 | $1,280 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211379364 | YORK | HMH72B341 | XAFC48FBCN1 | TP9C080B12MP13 | 25,600 | $1,280 |
| No | 211379361 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TM9V080B12MP12 | 25,600 | $1,280 |
| No | 211379357 | YORK | HMH72B341 | XAFC48FBCN1 | TM9V080B12MP12 | 25,600 | $1,280 |
| No | 211379354 | YORK | HMH72B341 | XAFC48FXXN1+TXV | YP9C080B12MP13 | 25,600 | $1,280 |
| No | 211379351 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TP9C080B12MP13 | 25,600 | $1,280 |
| No | 211379348 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TM9V080B12MP12 | 25,600 | $1,280 |
| No | 211379345 | YORK | HMH72B341 | XAHC48FBCN1 | YP9C080B12MP13 | 25,200 | $1,260 |
| No | 211379342 | YORK | HMH72B341 | XAHC48FBCN1 | TP9C080B12MP13 | 25,200 | $1,260 |
| No | 211379339 | YORK | HMH72B341 | XAHC48FBCN1 | TM9V080B12MP12 | 25,200 | $1,260 |
| No | 211379336 | YORK | HMH72B341 | XAHC48FXXN1+TXV | YP9C080B12MP13 | 25,200 | $1,260 |
| No | 211379333 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TP9C080B12MP13 | 25,200 | $1,260 |
| No | 211379330 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TM9V080B12MP12 | 25,200 | $1,260 |
| No | 211379327 | YORK | HMH72B341 | XAUC48FXXN1+TXV | YP9C080C16MP13 | 25,400 | $1,270 |
| No | 211379324 | YORK | HMH72B341 | XAFC48FBCN1 | YP9C080C16MP13 | 25,400 | $1,270 |
| No | 211379321 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211379318 | YORK | HMH72B341 | XAFC48FBCN1 | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211379315 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211379312 | YORK | HMH72B341 | XAFC48FBCN1 | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211379309 | YORK | HMH72B341 | XAFC48FXXN1+TXV | YP9C080C16MP13 | 25,400 | $1,270 |
| No | 211379306 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211379303 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211379300 | YORK | HMH72B341 | XAFD48FBCN1 | YP9C080C16MP13 | 25,400 | $1,270 |
| No | 211379297 | YORK | HMH72B341 | XAFD48FBCN1 | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211379294 | YORK | HMH72B341 | XAFD48FBCN1 | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211379291 | YORK | HMH72B341 | XAFD48FXXN1+TXV | YP9C080C16MP13 | 25,400 | $1,270 |
| No | 211379288 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211379285 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211379282 | YORK | HMH72B341 | XAHC48FBCN1 | YP9C080C16MP13 | 24,800 | $1,240 |
| No | 211379279 | YORK | HMH72B341 | XAHC48FBCN1 | TP9C080C16MP13 | 24,800 | $1,240 |
| No | 211379276 | YORK | HMH72B341 | XAHC48FBCN1 | TM9V080C16MP12 | 24,800 | $1,240 |
| No | 211379273 | YORK | HMH72B341 | XAHC48FXXN1+TXV | YP9C080C16MP13 | 24,800 | $1,240 |
| No | 211379270 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TP9C080C16MP13 | 24,800 | $1,240 |
| No | 211379267 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TM9V080C16MP12 | 24,800 | $1,240 |
| No | 211379264 | YORK | HMH72B341 | XAHD48FBCN1 | YP9C080C16MP13 | 25,000 | $1,250 |
| No | 211379261 | YORK | HMH72B341 | XAHD48FBCN1 | TP9C080C16MP13 | 25,000 | $1,250 |
| No | 211379258 | YORK | HMH72B341 | XAHD48FBCN1 | TM9V080C16MP12 | 25,000 | $1,250 |
| No | 211379255 | YORK | HMH72B341 | XAHD48FXXN1+TXV | YP9C080C16MP13 | 25,000 | $1,250 |
| No | 211379252 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TP9C080C16MP13 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211379249 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TM9V080C16MP12 | 25,000 | $1,250 |
| No | 211379246 | YORK | HMH72B341 | XAUC48FXXN1+TXV | YP9C100C16MP13 | 25,400 | $1,270 |
| No | 211379243 | YORK | HMH72B341 | XAFC48FBCN1 | YP9C100C16MP13 | 25,400 | $1,270 |
| No | 211379240 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211379238 | YORK | HMH72B341 | XAFC48FBCN1 | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211379236 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211379232 | YORK | HMH72B341 | XAFC48FBCN1 | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211379229 | YORK | HMH72B341 | XAFC48FXXN1+TXV | YP9C100C16MP13 | 25,400 | $1,270 |
| No | 211379226 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211379225 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211379223 | YORK | HMH72B341 | XAFD48FBCN1 | YP9C100C16MP13 | 25,400 | $1,270 |
| No | 211379220 | YORK | HMH72B341 | XAFD48FBCN1 | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211379217 | YORK | HMH72B341 | XAFD48FBCN1 | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211379214 | YORK | HMH72B341 | XAFD48FXXN1+TXV | YP9C100C16MP13 | 25,400 | $1,270 |
| No | 211379212 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211379209 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211379206 | YORK | HMH72B341 | XAHC48FBCN1 | YP9C100C16MP13 | 24,800 | $1,240 |
| No | 211379203 | YORK | HMH72B341 | XAHC48FBCN1 | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211379200 | YORK | HMH72B341 | XAHC48FBCN1 | TM9V100C16MP12 | 24,800 | $1,240 |
| No | 211379197 | YORK | HMH72B341 | XAHC48FXXN1+TXV | YP9C100C16MP13 | 24,800 | $1,240 |
| No | 211379194 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211379191 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TM9V100C16MP12 | 24,800 | $1,240 |
| No | 211379188 | YORK | HMH72B341 | XAHD48FBCN1 | YP9C100C16MP13 | 24,800 | $1,240 |
| No | 211379185 | YORK | HMH72B341 | XAHD48FBCN1 | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211379182 | YORK | HMH72B341 | XAHD48FBCN1 | TM9V100C16MP12 | 24,800 | $1,240 |
| No | 211379179 | YORK | HMH72B341 | XAHD48FXXN1+TXV | YP9C100C16MP13 | 24,800 | $1,240 |
| No | 211379176 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211379173 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TM9V100C16MP12 | 24,800 | $1,240 |
| No | 211379170 | YORK | HMH72B341 | XAUC48FXXN1+TXV | YP9C100C20MP13 | 25,800 | $1,290 |
| No | 211379167 | YORK | HMH72B341 | XAFC48FBCN1 | YP9C100C20MP13 | 25,800 | $1,290 |
| No | 211379164 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TP9C100C20MP13 | 25,800 | $1,290 |
| No | 211379163 | YORK | HMH72B341 | XAFC48FBCN1 | TP9C100C20MP13 | 25,800 | $1,290 |
| No | 211379161 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TM9V100C20MP12 | 25,800 | $1,290 |
| No | 211379157 | YORK | HMH72B341 | XAFC48FBCN1 | TM9V100C20MP12 | 25,800 | $1,290 |
| No | 211379154 | YORK | HMH72B341 | XAFC48FXXN1+TXV | YP9C100C20MP13 | 25,800 | $1,290 |
| No | 211379151 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TP9C100C20MP13 | 25,800 | $1,290 |
| No | 211379148 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TM9V100C20MP12 | 25,800 | $1,290 |
| No | 211379145 | YORK | HMH72B341 | XAFD48FBCN1 | YP9C100C20MP13 | 25,600 | $1,280 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211379142 | YORK | HMH72B341 | XAFD48FBCN1 | TP9C100C20MP13 | 25,600 | $1,280 |
| No | 211379139 | YORK | HMH72B341 | XAFD48FBCN1 | TM9V100C20MP12 | 25,600 | $1,280 |
| No | 211379138 | YORK | HMH72B341 | XAFD48FXXN1+TXV | YP9C100C20MP13 | 25,600 | $1,280 |
| No | 211379137 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TP9C100C20MP13 | 25,600 | $1,280 |
| No | 211379134 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TM9V100C20MP12 | 25,600 | $1,280 |
| No | 211379131 | YORK | HMH72B341 | XAHC48FBCN1 | YP9C100C20MP13 | 25,000 | $1,250 |
| No | 211379128 | YORK | HMH72B341 | XAHC48FBCN1 | TP9C100C20MP13 | 25,000 | $1,250 |
| No | 211379125 | YORK | HMH72B341 | XAHC48FBCN1 | TM9V100C20MP12 | 25,000 | $1,250 |
| No | 211379122 | YORK | HMH72B341 | XAHC48FXXN1+TXV | YP9C100C20MP13 | 25,000 | $1,250 |
| No | 211379119 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TP9C100C20MP13 | 25,000 | $1,250 |
| No | 211379116 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TM9V100C20MP12 | 25,000 | $1,250 |
| No | 211379113 | YORK | HMH72B341 | XAHD48FBCN1 | YP9C100C20MP13 | 25,200 | $1,260 |
| No | 211379110 | YORK | HMH72B341 | XAHD48FBCN1 | TP9C100C20MP13 | 25,200 | $1,260 |
| No | 211379107 | YORK | HMH72B341 | XAHD48FBCN1 | TM9V100C20MP12 | 25,200 | $1,260 |
| No | 211379104 | YORK | HMH72B341 | XAHD48FXXN1+TXV | YP9C100C20MP13 | 25,200 | $1,260 |
| No | 211379101 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TP9C100C20MP13 | 25,200 | $1,260 |
| No | 211379098 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TM9V100C20MP12 | 25,200 | $1,260 |
| No | 211379095 | YORK | HMH72B341 | XAFD48FBCN1 | YP9C120D20MP13 | 25,400 | $1,270 |
| No | 211379092 | YORK | HMH72B341 | XAFD48FBCN1 | TP9C120D20MP13 | 25,400 | $1,270 |
| No | 211379089 | YORK | HMH72B341 | XAFD48FBCN1 | TM9V120D20MP12 | 25,400 | $1,270 |
| No | 211379086 | YORK | HMH72B341 | XAFD48FXXN1+TXV | YP9C120D20MP13 | 25,400 | $1,270 |
| No | 211379083 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TP9C120D20MP13 | 25,400 | $1,270 |
| No | 211379080 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TM9V120D20MP12 | 25,400 | $1,270 |
| No | 211379077 | YORK | HMH72B341 | XAHD48FBCN1 | YP9C120D20MP13 | 24,800 | $1,240 |
| No | 211379074 | YORK | HMH72B341 | XAHD48FBCN1 | TP9C120D20MP13 | 24,800 | $1,240 |
| No | 211379071 | YORK | HMH72B341 | XAHD48FBCN1 | TM9V120D20MP12 | 24,800 | $1,240 |
| No | 211379068 | YORK | HMH72B341 | XAHD48FXXN1+TXV | YP9C120D20MP13 | 24,800 | $1,240 |
| No | 211379065 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TP9C120D20MP13 | 24,800 | $1,240 |
| No | 211379064 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TM9V120D20MP12 | 24,800 | $1,240 |
| No | 211379060 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TM9Y060B12MP11 | 25,800 | $1,290 |
| No | 211379057 | YORK | HMH72B341 | XAFC48FBCN1 | TM9Y060B12MP11 | 25,800 | $1,290 |
| No | 211379054 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TM9Y060B12MP11 | 25,800 | $1,290 |
| No | 211379051 | YORK | HMH72B341 | XAHC48FBCN1 | TM9Y060B12MP11 | 25,400 | $1,270 |
| No | 211379049 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TM9Y060B12MP11 | 25,400 | $1,270 |
| No | 211379045 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211379043 | YORK | HMH72B341 | XAFC48FBCN1 | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211379040 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211379039 | YORK | HMH72B341 | XAHC48FBCN1 | TM9Y080B12MP11 | 25,400 | $1,270 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211379036 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TM9Y080B12MP11 | 25,400 | $1,270 |
| No | 211379033 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TM9Y080C16MP11 | 25,800 | $1,290 |
| No | 211379030 | YORK | HMH72B341 | XAFC48FBCN1 | TM9Y080C16MP11 | 25,800 | $1,290 |
| No | 211379027 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TM9Y080C16MP11 | 25,800 | $1,290 |
| No | 211379024 | YORK | HMH72B341 | XAFD48FBCN1 | TM9Y080C16MP11 | 25,400 | $1,270 |
| No | 211379021 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TM9Y080C16MP11 | 25,400 | $1,270 |
| No | 211379018 | YORK | HMH72B341 | XAHC48FBCN1 | TM9Y080C16MP11 | 25,200 | $1,260 |
| No | 211379015 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TM9Y080C16MP11 | 25,200 | $1,260 |
| No | 211379013 | YORK | HMH72B341 | XAHD48FBCN1 | TM9Y080C16MP11 | 25,000 | $1,250 |
| No | 211379012 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TM9Y080C16MP11 | 25,000 | $1,250 |
| No | 211379009 | YORK | HMH72B341 | XAUC48FXXN1+TXV | TM9Y100C16MP11 | 25,800 | $1,290 |
| No | 211379006 | YORK | HMH72B341 | XAFC48FBCN1 | TM9Y100C16MP11 | 25,800 | $1,290 |
| No | 211379003 | YORK | HMH72B341 | XAFC48FXXN1+TXV | TM9Y100C16MP11 | 25,800 | $1,290 |
| No | 211379000 | YORK | HMH72B341 | XAFD48FBCN1 | TM9Y100C16MP11 | 25,400 | $1,270 |
| No | 211378997 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TM9Y100C16MP11 | 25,400 | $1,270 |
| No | 211378994 | YORK | HMH72B341 | XAHC48FBCN1 | TM9Y100C16MP11 | 25,200 | $1,260 |
| No | 211378991 | YORK | HMH72B341 | XAHC48FXXN1+TXV | TM9Y100C16MP11 | 25,200 | $1,260 |
| No | 211378988 | YORK | HMH72B341 | XAHD48FBCN1 | TM9Y100C16MP11 | 25,200 | $1,260 |
| No | 211378987 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TM9Y100C16MP11 | 25,200 | $1,260 |
| No | 211378984 | YORK | HMH72B341 | XAFD48FBCN1 | TM9Y120D20MP11 | 25,400 | $1,270 |
| No | 211378981 | YORK | HMH72B341 | XAFD48FXXN1+TXV | TM9Y120D20MP11 | 25,400 | $1,270 |
| No | 211378978 | YORK | HMH72B341 | XAHD48FBCN1 | TM9Y120D20MP11 | 25,000 | $1,250 |
| No | 211378975 | YORK | HMH72B341 | XAHD48FXXN1+TXV | TM9Y120D20MP11 | 25,000 | $1,250 |
| No | 211378972 | YORK | HMH72B341 | XAFA30DXXN1+TXV | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 211378969 | YORK | HMH72B341 | XAFA30DXXN1+TXV | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 211378966 | YORK | HMH72B341 | XAFA30DXXN1+TXV | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211378963 | YORK | HMH72B341 | XAFA30DXXN1+TXV | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 211378960 | YORK | HMH72B341 | XAFA30DXXN1+TXV | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 211378957 | YORK | HMH72B341 | XAFA30DXXN1+TXV | YPLC060A12MP13 | 25,800 | $1,290 |
| No | 211378954 | YORK | HMH72B341 | XAFA30DXXN1+TXV | TPLC060A12MP13 | 25,800 | $1,290 |
| No | 211378951 | YORK | HMH72B341 | XAFA30DXXN1+TXV | TMLV060A12MP12 | 25,800 | $1,290 |
| No | 211378948 | YORK | HMH72B341 | XAFA30DXXN1+TXV | TM8V060A12MP12 | 25,800 | $1,290 |
| No | 211378945 | YORK | HMH72B341 | XAFA30DXXN1+TXV | TM8Y060A12MP11 | 25,200 | $1,260 |
| No | 211378939 | YORK | HMH72B341 | JHETB36DBCS2N1 | | 25,400 | $1,270 |
| No | 211378935 | YORK | HMH72B341 | JHVTB36DBCC2N1 | | 25,200 | $1,260 |
| No | 211378932 | YORK | HMH72B341 | JHVTC36DBCC2N1 | | 25,400 | $1,270 |
| No | 211378929 | YORK | HMH72B341 | XAUB30CXXN1+TXV | TL8E060A12UH11 | 26,200 | $1,310 |
| No | 211378927 | YORK | HMH72B341 | XAFB30CXXN1+TXV | TL8E060A12UH11 | 26,200 | $1,310 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211378926 | YORK | HMH72B341 | XAUB36DXXN1+TXV | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 211378923 | YORK | HMH72B341 | XAFB36DBCN1 | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 211378920 | YORK | HMH72B341 | XAFB36DXXN1+TXV | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 211378917 | YORK | HMH72B341 | XAHB30CXXN1+TXV | TL8E060A12UH11 | 25,800 | $1,290 |
| No | 211378914 | YORK | HMH72B341 | XAHB36DBCN1 | TL8E060A12UH11 | 25,000 | $1,250 |
| No | 211378913 | YORK | HMH72B341 | XAHB36DXXN1+TXV | TL8E060A12UH11 | 25,000 | $1,250 |
| No | 211378911 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TL8E080C16UH11 | 26,600 | $1,330 |
| No | 211378908 | YORK | HMH72B341 | XAFC36DBCN1 | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211378905 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TL8E080C16UH11 | 25,600 | $1,280 |
| No | 211378902 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TL8E080C16UH11 | 26,000 | $1,300 |
| No | 211378899 | YORK | HMH72B341 | XAHC36DBCN1 | TL8E080C16UH11 | 25,800 | $1,290 |
| No | 211378896 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TL8E080C16UH11 | 25,800 | $1,290 |
| No | 211378893 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TL8E100C20UH11 | 26,400 | $1,320 |
| No | 211378890 | YORK | HMH72B341 | XAFC36DBCN1 | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211378887 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TL8E100C20UH11 | 25,400 | $1,270 |
| No | 211378884 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TL8E100C20UH11 | 25,800 | $1,290 |
| No | 211378881 | YORK | HMH72B341 | XAHC36DBCN1 | TL8E100C20UH11 | 25,600 | $1,280 |
| No | 211378878 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TL8E100C20UH11 | 25,600 | $1,280 |
| No | 211378876 | YORK | HMH72B341 | XAUB30CXXN1+TXV | TL9E060B12UH11 | 26,400 | $1,320 |
| No | 211378875 | YORK | HMH72B341 | XAFB30CXXN1+TXV | TL9E060B12UH11 | 26,400 | $1,320 |
| No | 211378873 | YORK | HMH72B341 | XAUB36DXXN1+TXV | TL9E060B12UH11 | 25,000 | $1,250 |
| No | 211378870 | YORK | HMH72B341 | XAFB36DBCN1 | TL9E060B12UH11 | 25,000 | $1,250 |
| No | 211378867 | YORK | HMH72B341 | XAFB36DXXN1+TXV | TL9E060B12UH11 | 25,000 | $1,250 |
| No | 211378864 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TL9E060B12UH11 | 26,400 | $1,320 |
| No | 211378861 | YORK | HMH72B341 | XAFC36DBCN1 | TL9E060B12UH11 | 25,600 | $1,280 |
| No | 211378858 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TL9E060B12UH11 | 25,600 | $1,280 |
| No | 211378855 | YORK | HMH72B341 | XAHB30CXXN1+TXV | TL9E060B12UH11 | 25,200 | $1,260 |
| No | 211378852 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TL9E060B12UH11 | 26,000 | $1,300 |
| No | 211378850 | YORK | HMH72B341 | XAHC36DBCN1 | TL9E060B12UH11 | 24,400 | $1,220 |
| No | 211378847 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TL9E060B12UH11 | 24,400 | $1,220 |
| No | 211378844 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TL9E080C16UH11 | 26,200 | $1,310 |
| No | 211378841 | YORK | HMH72B341 | XAFC36DBCN1 | TL9E080C16UH11 | 25,800 | $1,290 |
| No | 211378838 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TL9E080C16UH11 | 25,800 | $1,290 |
| No | 211378835 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TL9E080C16UH11 | 26,400 | $1,320 |
| No | 211378832 | YORK | HMH72B341 | XAHC36DBCN1 | TL9E080C16UH11 | 25,400 | $1,270 |
| No | 211378829 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TL9E080C16UH11 | 25,400 | $1,270 |
| No | 211378826 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TL9E100C20UH11 | 26,400 | $1,320 |
| No | 211378823 | YORK | HMH72B341 | XAFC36DBCN1 | TL9E100C20UH11 | 26,200 | $1,310 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211378822 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TL9E100C20UH11 | 26,200 | $1,310 |
| No | 211378819 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TL9E100C20UH11 | 26,000 | $1,300 |
| No | 211378816 | YORK | HMH72B341 | XAHC36DBCN1 | TL9E100C20UH11 | 25,600 | $1,280 |
| No | 211378813 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TL9E100C20UH11 | 25,600 | $1,280 |
| No | 211378810 | YORK | HMH72B341 | XAUB30CXXN1+TXV | TMLE040A12MP11 | 26,200 | $1,310 |
| No | 211378809 | YORK | HMH72B341 | XAUB30CXXN1+TXV | TM8E040A12MP11 | 26,200 | $1,310 |
| No | 211378806 | YORK | HMH72B341 | XAFB30CXXN1+TXV | TMLE040A12MP11 | 26,200 | $1,310 |
| No | 211378802 | YORK | HMH72B341 | XAFB30CXXN1+TXV | TM8E040A12MP11 | 26,200 | $1,310 |
| No | 211378799 | YORK | HMH72B341 | XAUB36DXXN1+TXV | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 211378797 | YORK | HMH72B341 | XAFB36DBCN1 | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 211378794 | YORK | HMH72B341 | XAUB36DXXN1+TXV | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211378790 | YORK | HMH72B341 | XAFB36DBCN1 | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211378787 | YORK | HMH72B341 | XAFB36DXXN1+TXV | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 211378784 | YORK | HMH72B341 | XAFB36DXXN1+TXV | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211378781 | YORK | HMH72B341 | XAHB30CXXN1+TXV | TMLE040A12MP11 | 25,600 | $1,280 |
| No | 211378778 | YORK | HMH72B341 | XAHB30CXXN1+TXV | TM8E040A12MP11 | 25,600 | $1,280 |
| No | 211378775 | YORK | HMH72B341 | XAHB36DBCN1 | TMLE040A12MP11 | 24,800 | $1,240 |
| No | 211378772 | YORK | HMH72B341 | XAHB36DBCN1 | TM8E040A12MP11 | 24,800 | $1,240 |
| No | 211378769 | YORK | HMH72B341 | XAHB36DXXN1+TXV | TMLE040A12MP11 | 24,800 | $1,240 |
| No | 211378766 | YORK | HMH72B341 | XAHB36DXXN1+TXV | TM8E040A12MP11 | 24,800 | $1,240 |
| No | 211378763 | YORK | HMH72B341 | XAUB30CXXN1+TXV | TMLE060A12MP11 | 26,200 | $1,310 |
| No | 211378760 | YORK | HMH72B341 | XAUB30CXXN1+TXV | TM8E060A12MP11 | 26,200 | $1,310 |
| No | 211378757 | YORK | HMH72B341 | XAFB30CXXN1+TXV | TMLE060A12MP11 | 26,200 | $1,310 |
| No | 211378754 | YORK | HMH72B341 | XAFB30CXXN1+TXV | TM8E060A12MP11 | 26,200 | $1,310 |
| No | 211378751 | YORK | HMH72B341 | XAUB36DXXN1+TXV | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 211378749 | YORK | HMH72B341 | XAFB36DBCN1 | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 211378748 | YORK | HMH72B341 | XAUB36DXXN1+TXV | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 211378745 | YORK | HMH72B341 | XAFB36DBCN1 | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 211378742 | YORK | HMH72B341 | XAFB36DXXN1+TXV | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 211378739 | YORK | HMH72B341 | XAFB36DXXN1+TXV | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 211378736 | YORK | HMH72B341 | XAHB30CXXN1+TXV | TMLE060A12MP11 | 25,800 | $1,290 |
| No | 211378733 | YORK | HMH72B341 | XAHB30CXXN1+TXV | TM8E060A12MP11 | 25,800 | $1,290 |
| No | 211378730 | YORK | HMH72B341 | XAHB36DBCN1 | TMLE060A12MP11 | 25,000 | $1,250 |
| No | 211378727 | YORK | HMH72B341 | XAHB36DBCN1 | TM8E060A12MP11 | 25,000 | $1,250 |
| No | 211378724 | YORK | HMH72B341 | XAHB36DXXN1+TXV | TMLE060A12MP11 | 25,000 | $1,250 |
| No | 211378723 | YORK | HMH72B341 | XAHB36DXXN1+TXV | TM8E060A12MP11 | 25,000 | $1,250 |
| No | 211378721 | YORK | HMH72B341 | XAUB30CXXN1+TXV | TMLE080B12MP11 | 26,800 | $1,340 |
| No | 211378718 | YORK | HMH72B341 | XAUB30CXXN1+TXV | TM8E080B12MP11 | 26,800 | $1,340 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211378715 | YORK | HMH72B341 | XAFB30CXXN1+TXV | TMLE080B12MP11 | 26,800 | $1,340 |
| No | 211378712 | YORK | HMH72B341 | XAFB30CXXN1+TXV | TM8E080B12MP11 | 26,800 | $1,340 |
| No | 211378709 | YORK | HMH72B341 | XAUB36DXXN1+TXV | TMLE080B12MP11 | 25,800 | $1,290 |
| No | 211378706 | YORK | HMH72B341 | XAFB36DBCN1 | TMLE080B12MP11 | 25,800 | $1,290 |
| No | 211378703 | YORK | HMH72B341 | XAUB36DXXN1+TXV | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211378700 | YORK | HMH72B341 | XAFB36DBCN1 | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211378697 | YORK | HMH72B341 | XAFB36DXXN1+TXV | TMLE080B12MP11 | 25,800 | $1,290 |
| No | 211378694 | YORK | HMH72B341 | XAFB36DXXN1+TXV | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211378691 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TMLE080B12MP11 | 26,800 | $1,340 |
| No | 211378688 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TM8E080B12MP11 | 26,800 | $1,340 |
| No | 211378685 | YORK | HMH72B341 | XAFC36DBCN1 | TMLE080B12MP11 | 25,800 | $1,290 |
| No | 211378682 | YORK | HMH72B341 | XAFC36DBCN1 | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211378679 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TMLE080B12MP11 | 25,800 | $1,290 |
| No | 211378676 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TM8E080B12MP11 | 25,800 | $1,290 |
| No | 211378674 | YORK | HMH72B341 | XAHB30CXXN1+TXV | TMLE080B12MP11 | 26,200 | $1,310 |
| No | 211378673 | YORK | HMH72B341 | XAHB30CXXN1+TXV | TM8E080B12MP11 | 26,200 | $1,310 |
| No | 211378671 | YORK | HMH72B341 | XAHB36DBCN1 | TMLE080B12MP11 | 25,000 | $1,250 |
| No | 211378668 | YORK | HMH72B341 | XAHB36DBCN1 | TM8E080B12MP11 | 25,000 | $1,250 |
| No | 211378665 | YORK | HMH72B341 | XAHB36DXXN1+TXV | TMLE080B12MP11 | 25,000 | $1,250 |
| No | 211378662 | YORK | HMH72B341 | XAHB36DXXN1+TXV | TM8E080B12MP11 | 25,000 | $1,250 |
| No | 211378659 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TMLE080B12MP11 | 26,400 | $1,320 |
| No | 211378656 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TM8E080B12MP11 | 26,400 | $1,320 |
| No | 211378653 | YORK | HMH72B341 | XAHC36DBCN1 | TMLE080B12MP11 | 25,000 | $1,250 |
| No | 211378650 | YORK | HMH72B341 | XAHC36DBCN1 | TM8E080B12MP11 | 25,000 | $1,250 |
| No | 211378647 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TMLE080B12MP11 | 25,000 | $1,250 |
| No | 211378644 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TM8E080B12MP11 | 25,000 | $1,250 |
| No | 211378641 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TMLE080C16MP11 | 26,000 | $1,300 |
| No | 211378638 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TM8E080C16MP11 | 26,000 | $1,300 |
| No | 211378636 | YORK | HMH72B341 | XAFC36DBCN1 | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211378633 | YORK | HMH72B341 | XAFC36DBCN1 | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211378630 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TMLE080C16MP11 | 25,200 | $1,260 |
| No | 211378627 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TM8E080C16MP11 | 25,200 | $1,260 |
| No | 211378625 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TMLE080C16MP11 | 25,600 | $1,280 |
| No | 211378622 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TM8E080C16MP11 | 25,600 | $1,280 |
| No | 211378619 | YORK | HMH72B341 | XAHC36DBCN1 | TMLE080C16MP11 | 24,600 | $1,230 |
| No | 211378616 | YORK | HMH72B341 | XAHC36DBCN1 | TM8E080C16MP11 | 24,600 | $1,230 |
| No | 211378613 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TMLE080C16MP11 | 24,600 | $1,230 |
| No | 211378611 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TM8E080C16MP11 | 24,600 | $1,230 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211378609 | YORK | HMH72B341 | XAUB30CXXN1+TXV | TMLE100B12MP11 | 26,200 | $1,310 |
| No | 211378606 | YORK | HMH72B341 | XAUB30CXXN1+TXV | TM8E100B12MP11 | 26,200 | $1,310 |
| No | 211378603 | YORK | HMH72B341 | XAFB30CXXN1+TXV | TMLE100B12MP11 | 26,200 | $1,310 |
| No | 211378600 | YORK | HMH72B341 | XAFB30CXXN1+TXV | TM8E100B12MP11 | 26,200 | $1,310 |
| No | 211378597 | YORK | HMH72B341 | XAUB36DXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211378594 | YORK | HMH72B341 | XAFB36DBCN1 | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211378591 | YORK | HMH72B341 | XAUB36DXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211378588 | YORK | HMH72B341 | XAFB36DBCN1 | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211378585 | YORK | HMH72B341 | XAFB36DXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211378582 | YORK | HMH72B341 | XAFB36DXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211378579 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TMLE100B12MP11 | 26,200 | $1,310 |
| No | 211378576 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TM8E100B12MP11 | 26,200 | $1,310 |
| No | 211378573 | YORK | HMH72B341 | XAFC36DBCN1 | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211378570 | YORK | HMH72B341 | XAFC36DBCN1 | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211378567 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TMLE100B12MP11 | 25,400 | $1,270 |
| No | 211378564 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TM8E100B12MP11 | 25,400 | $1,270 |
| No | 211378561 | YORK | HMH72B341 | XAHB30CXXN1+TXV | TMLE100B12MP11 | 25,800 | $1,290 |
| No | 211378558 | YORK | HMH72B341 | XAHB30CXXN1+TXV | TM8E100B12MP11 | 25,800 | $1,290 |
| No | 211378555 | YORK | HMH72B341 | XAHB36DBCN1 | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 211378552 | YORK | HMH72B341 | XAHB36DBCN1 | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 211378549 | YORK | HMH72B341 | XAHB36DXXN1+TXV | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 211378546 | YORK | HMH72B341 | XAHB36DXXN1+TXV | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 211378543 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TMLE100B12MP11 | 25,600 | $1,280 |
| No | 211378540 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TM8E100B12MP11 | 25,600 | $1,280 |
| No | 211378537 | YORK | HMH72B341 | XAHC36DBCN1 | TMLE100B12MP11 | 24,800 | $1,240 |
| No | 211378534 | YORK | HMH72B341 | XAHC36DBCN1 | TM8E100B12MP11 | 24,800 | $1,240 |
| No | 211378531 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TMLE100B12MP11 | 24,800 | $1,240 |
| No | 211378528 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TM8E100B12MP11 | 24,800 | $1,240 |
| No | 211378525 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TMLE100C16MP11 | 26,000 | $1,300 |
| No | 211378522 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TM8E100C16MP11 | 26,000 | $1,300 |
| No | 211378519 | YORK | HMH72B341 | XAFC36DBCN1 | TMLE100C16MP11 | 25,200 | $1,260 |
| No | 211378516 | YORK | HMH72B341 | XAFC36DBCN1 | TM8E100C16MP11 | 25,200 | $1,260 |
| No | 211378513 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TMLE100C16MP11 | 25,200 | $1,260 |
| No | 211378510 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TM8E100C16MP11 | 25,200 | $1,260 |
| No | 211378507 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TMLE100C16MP11 | 25,600 | $1,280 |
| No | 211378504 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TM8E100C16MP11 | 25,600 | $1,280 |
| No | 211378501 | YORK | HMH72B341 | XAHC36DBCN1 | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211378498 | YORK | HMH72B341 | XAHC36DBCN1 | TM8E100C16MP11 | 24,800 | $1,240 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211378495 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TMLE100C16MP11 | 24,800 | $1,240 |
| No | 211378492 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TM8E100C16MP11 | 24,800 | $1,240 |
| No | 211378489 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TMLE120C16MP11 | 26,200 | $1,310 |
| No | 211378486 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TM8E120C16MP11 | 26,200 | $1,310 |
| No | 211378483 | YORK | HMH72B341 | XAFC36DBCN1 | TMLE120C16MP11 | 25,200 | $1,260 |
| No | 211378480 | YORK | HMH72B341 | XAFC36DBCN1 | TM8E120C16MP11 | 25,200 | $1,260 |
| No | 211378477 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TMLE120C16MP11 | 25,200 | $1,260 |
| No | 211378474 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TM8E120C16MP11 | 25,200 | $1,260 |
| No | 211378471 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TMLE120C16MP11 | 25,600 | $1,280 |
| No | 211378468 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TM8E120C16MP11 | 25,600 | $1,280 |
| No | 211378465 | YORK | HMH72B341 | XAHC36DBCN1 | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211378462 | YORK | HMH72B341 | XAHC36DBCN1 | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211378459 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TMLE120C16MP11 | 24,800 | $1,240 |
| No | 211378456 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TM8E120C16MP11 | 24,800 | $1,240 |
| No | 211378453 | YORK | HMH72B341 | XAUB30CXXN1+TXV | YPLC060A12MP13 | 26,000 | $1,300 |
| No | 211378450 | YORK | HMH72B341 | XAUB30CXXN1+TXV | TPLC060A12MP13 | 26,000 | $1,300 |
| No | 211378447 | YORK | HMH72B341 | XAUB30CXXN1+TXV | TMLV060A12MP12 | 26,000 | $1,300 |
| No | 211378444 | YORK | HMH72B341 | XAUB30CXXN1+TXV | TM8V060A12MP12 | 26,000 | $1,300 |
| No | 211378441 | YORK | HMH72B341 | XAFB30CXXN1+TXV | YPLC060A12MP13 | 26,000 | $1,300 |
| No | 211378438 | YORK | HMH72B341 | XAFB30CXXN1+TXV | TPLC060A12MP13 | 26,000 | $1,300 |
| No | 211378435 | YORK | HMH72B341 | XAFB30CXXN1+TXV | TMLV060A12MP12 | 26,000 | $1,300 |
| No | 211378432 | YORK | HMH72B341 | XAFB30CXXN1+TXV | TM8V060A12MP12 | 26,000 | $1,300 |
| No | 211378429 | YORK | HMH72B341 | XAUB36DXXN1+TXV | YPLC060A12MP13 | 25,600 | $1,280 |
| No | 211378426 | YORK | HMH72B341 | XAFB36DBCN1 | YPLC060A12MP13 | 25,600 | $1,280 |
| No | 211378423 | YORK | HMH72B341 | XAUB36DXXN1+TXV | TPLC060A12MP13 | 25,600 | $1,280 |
| No | 211378420 | YORK | HMH72B341 | XAFB36DBCN1 | TPLC060A12MP13 | 25,600 | $1,280 |
| No | 211378417 | YORK | HMH72B341 | XAUB36DXXN1+TXV | TMLV060A12MP12 | 25,600 | $1,280 |
| No | 211378414 | YORK | HMH72B341 | XAFB36DBCN1 | TMLV060A12MP12 | 25,600 | $1,280 |
| No | 211378411 | YORK | HMH72B341 | XAUB36DXXN1+TXV | TM8V060A12MP12 | 25,600 | $1,280 |
| No | 211378408 | YORK | HMH72B341 | XAFB36DBCN1 | TM8V060A12MP12 | 25,600 | $1,280 |
| No | 211378405 | YORK | HMH72B341 | XAFB36DXXN1+TXV | YPLC060A12MP13 | 25,600 | $1,280 |
| No | 211378402 | YORK | HMH72B341 | XAFB36DXXN1+TXV | TPLC060A12MP13 | 25,600 | $1,280 |
| No | 211378398 | YORK | HMH72B341 | XAFB36DXXN1+TXV | TMLV060A12MP12 | 25,600 | $1,280 |
| No | 211378395 | YORK | HMH72B341 | XAFB36DXXN1+TXV | TM8V060A12MP12 | 25,600 | $1,280 |
| No | 211378392 | YORK | HMH72B341 | XAHB30CXXN1+TXV | YPLC060A12MP13 | 25,600 | $1,280 |
| No | 211378389 | YORK | HMH72B341 | XAHB30CXXN1+TXV | TPLC060A12MP13 | 25,600 | $1,280 |
| No | 211378386 | YORK | HMH72B341 | XAHB30CXXN1+TXV | TMLV060A12MP12 | 25,600 | $1,280 |
| No | 211378383 | YORK | HMH72B341 | XAHB30CXXN1+TXV | TM8V060A12MP12 | 25,600 | $1,280 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211378380 | YORK | HMH72B341 | XAHB36DBCN1 | YPLC060A12MP13 | 25,200 | $1,260 |
| No | 211378377 | YORK | HMH72B341 | XAHB36DBCN1 | TPLC060A12MP13 | 25,200 | $1,260 |
| No | 211378374 | YORK | HMH72B341 | XAHB36DBCN1 | TMLV060A12MP12 | 25,200 | $1,260 |
| No | 211378371 | YORK | HMH72B341 | XAHB36DBCN1 | TM8V060A12MP12 | 25,200 | $1,260 |
| No | 211378368 | YORK | HMH72B341 | XAHB36DXXN1+TXV | YPLC060A12MP13 | 25,200 | $1,260 |
| No | 211378365 | YORK | HMH72B341 | XAHB36DXXN1+TXV | TPLC060A12MP13 | 25,200 | $1,260 |
| No | 211378362 | YORK | HMH72B341 | XAHB36DXXN1+TXV | TMLV060A12MP12 | 25,200 | $1,260 |
| No | 211378359 | YORK | HMH72B341 | XAHB36DXXN1+TXV | TM8V060A12MP12 | 25,200 | $1,260 |
| No | 211378356 | YORK | HMH72B341 | XAUB30CXXN1+TXV | YPLC080B12MP13 | 26,400 | $1,320 |
| No | 211378353 | YORK | HMH72B341 | XAUB30CXXN1+TXV | TPLC080B12MP13 | 26,400 | $1,320 |
| No | 211378350 | YORK | HMH72B341 | XAUB30CXXN1+TXV | TM8V080B12MP12 | 26,400 | $1,320 |
| No | 211378347 | YORK | HMH72B341 | XAFB30CXXN1+TXV | YPLC080B12MP13 | 26,400 | $1,320 |
| No | 211378344 | YORK | HMH72B341 | XAFB30CXXN1+TXV | TPLC080B12MP13 | 26,400 | $1,320 |
| No | 211378341 | YORK | HMH72B341 | XAFB30CXXN1+TXV | TM8V080B12MP12 | 26,400 | $1,320 |
| No | 211378338 | YORK | HMH72B341 | XAUB36DXXN1+TXV | YPLC080B12MP13 | 25,400 | $1,270 |
| No | 211378335 | YORK | HMH72B341 | XAFB36DBCN1 | YPLC080B12MP13 | 25,400 | $1,270 |
| No | 211378332 | YORK | HMH72B341 | XAUB36DXXN1+TXV | TPLC080B12MP13 | 25,400 | $1,270 |
| No | 211378329 | YORK | HMH72B341 | XAFB36DBCN1 | TPLC080B12MP13 | 25,400 | $1,270 |
| No | 211378326 | YORK | HMH72B341 | XAUB36DXXN1+TXV | TM8V080B12MP12 | 25,400 | $1,270 |
| No | 211378323 | YORK | HMH72B341 | XAFB36DBCN1 | TM8V080B12MP12 | 25,400 | $1,270 |
| No | 211378320 | YORK | HMH72B341 | XAFB36DXXN1+TXV | YPLC080B12MP13 | 25,400 | $1,270 |
| No | 211378317 | YORK | HMH72B341 | XAFB36DXXN1+TXV | TPLC080B12MP13 | 25,400 | $1,270 |
| No | 211378315 | YORK | HMH72B341 | XAFB36DXXN1+TXV | TM8V080B12MP12 | 25,400 | $1,270 |
| No | 211378311 | YORK | HMH72B341 | XAFC30CXXN1+TXV | YPLC080B12MP13 | 26,400 | $1,320 |
| No | 211378308 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TPLC080B12MP13 | 26,400 | $1,320 |
| No | 211378305 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TM8V080B12MP12 | 26,400 | $1,320 |
| No | 211378302 | YORK | HMH72B341 | XAFC36DBCN1 | YPLC080B12MP13 | 25,600 | $1,280 |
| No | 211378299 | YORK | HMH72B341 | XAFC36DBCN1 | TPLC080B12MP13 | 25,600 | $1,280 |
| No | 211378296 | YORK | HMH72B341 | XAFC36DBCN1 | TM8V080B12MP12 | 25,600 | $1,280 |
| No | 211378293 | YORK | HMH72B341 | XAFC36DXXN1+TXV | YPLC080B12MP13 | 25,600 | $1,280 |
| No | 211378290 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TPLC080B12MP13 | 25,600 | $1,280 |
| No | 211378287 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TM8V080B12MP12 | 25,600 | $1,280 |
| No | 211378284 | YORK | HMH72B341 | XAHB30CXXN1+TXV | YPLC080B12MP13 | 25,600 | $1,280 |
| No | 211378281 | YORK | HMH72B341 | XAHB30CXXN1+TXV | TPLC080B12MP13 | 25,600 | $1,280 |
| No | 211378278 | YORK | HMH72B341 | XAHB30CXXN1+TXV | TM8V080B12MP12 | 25,600 | $1,280 |
| No | 211378275 | YORK | HMH72B341 | XAHB36DBCN1 | YPLC080B12MP13 | 25,000 | $1,250 |
| No | 211378272 | YORK | HMH72B341 | XAHB36DBCN1 | TPLC080B12MP13 | 25,000 | $1,250 |
| No | 211378269 | YORK | HMH72B341 | XAHB36DBCN1 | TM8V080B12MP12 | 25,000 | $1,250 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211378266 | YORK | HMH72B341 | XAHB36DXXN1+TXV | YPLC080B12MP13 | 25,000 | $1,250 |
| No | 211378263 | YORK | HMH72B341 | XAHB36DXXN1+TXV | TPLC080B12MP13 | 25,000 | $1,250 |
| No | 211378260 | YORK | HMH72B341 | XAHB36DXXN1+TXV | TM8V080B12MP12 | 25,000 | $1,250 |
| No | 211378257 | YORK | HMH72B341 | XAHC30CXXN1+TXV | YPLC080B12MP13 | 26,000 | $1,300 |
| No | 211378254 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TPLC080B12MP13 | 26,000 | $1,300 |
| No | 211378251 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TM8V080B12MP12 | 26,000 | $1,300 |
| No | 211378248 | YORK | HMH72B341 | XAHC36DBCN1 | YPLC080B12MP13 | 24,800 | $1,240 |
| No | 211378245 | YORK | HMH72B341 | XAHC36DBCN1 | TPLC080B12MP13 | 24,800 | $1,240 |
| No | 211378242 | YORK | HMH72B341 | XAHC36DBCN1 | TM8V080B12MP12 | 24,800 | $1,240 |
| No | 211378239 | YORK | HMH72B341 | XAHC36DXXN1+TXV | YPLC080B12MP13 | 24,800 | $1,240 |
| No | 211378236 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TPLC080B12MP13 | 24,800 | $1,240 |
| No | 211378233 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TM8V080B12MP12 | 24,800 | $1,240 |
| No | 211378230 | YORK | HMH72B341 | XAFC30CXXN1+TXV | YPLC100C16MP13 | 26,400 | $1,320 |
| No | 211378227 | YORK | HMH72B341 | XAFC30CXXN1+TXV | YPLC080C16MP13 | 26,400 | $1,320 |
| No | 211378224 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TPLC100C16MP13 | 26,400 | $1,320 |
| No | 211378221 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TPLC080C16MP13 | 26,400 | $1,320 |
| No | 211378218 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TMLV100C16MP12 | 26,400 | $1,320 |
| No | 211378215 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TM8V080C16MP12 | 26,400 | $1,320 |
| No | 211378212 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TM8V100C16MP12 | 26,400 | $1,320 |
| No | 211378209 | YORK | HMH72B341 | XAFC36DBCN1 | YPLC100C16MP13 | 25,400 | $1,270 |
| No | 211378206 | YORK | HMH72B341 | XAFC36DBCN1 | YPLC080C16MP13 | 25,400 | $1,270 |
| No | 211378203 | YORK | HMH72B341 | XAFC36DBCN1 | TPLC100C16MP13 | 25,400 | $1,270 |
| No | 211378200 | YORK | HMH72B341 | XAFC36DBCN1 | TPLC080C16MP13 | 25,400 | $1,270 |
| No | 211378197 | YORK | HMH72B341 | XAFC36DBCN1 | TMLV100C16MP12 | 25,400 | $1,270 |
| No | 211378194 | YORK | HMH72B341 | XAFC36DBCN1 | TM8V080C16MP12 | 25,400 | $1,270 |
| No | 211378191 | YORK | HMH72B341 | XAFC36DBCN1 | TM8V100C16MP12 | 25,400 | $1,270 |
| No | 211378188 | YORK | HMH72B341 | XAFC36DXXN1+TXV | YPLC100C16MP13 | 25,400 | $1,270 |
| No | 211378185 | YORK | HMH72B341 | XAFC36DXXN1+TXV | YPLC080C16MP13 | 25,400 | $1,270 |
| No | 211378182 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TPLC100C16MP13 | 25,400 | $1,270 |
| No | 211378179 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TPLC080C16MP13 | 25,400 | $1,270 |
| No | 211378176 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TMLV100C16MP12 | 25,400 | $1,270 |
| No | 211378173 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TM8V080C16MP12 | 25,400 | $1,270 |
| No | 211378171 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TM8V100C16MP12 | 25,400 | $1,270 |
| No | 211378168 | YORK | HMH72B341 | XAHC30CXXN1+TXV | YPLC100C16MP13 | 25,600 | $1,280 |
| No | 211378165 | YORK | HMH72B341 | XAHC30CXXN1+TXV | YPLC080C16MP13 | 25,600 | $1,280 |
| No | 211378163 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TPLC100C16MP13 | 25,600 | $1,280 |
| No | 211378160 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TPLC080C16MP13 | 25,600 | $1,280 |
| No | 211378157 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TMLV100C16MP12 | 25,600 | $1,280 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211378151 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TM8V100C16MP12 | 25,600 | $1,280 |
| No | 211378149 | YORK | HMH72B341 | XAHC36DBCN1 | YPLC100C16MP13 | 25,600 | $1,280 |
| No | 211378146 | YORK | HMH72B341 | XAHC36DBCN1 | YPLC080C16MP13 | 25,600 | $1,280 |
| No | 211378143 | YORK | HMH72B341 | XAHC36DBCN1 | TPLC100C16MP13 | 25,600 | $1,280 |
| No | 211378140 | YORK | HMH72B341 | XAHC36DBCN1 | TPLC080C16MP13 | 25,600 | $1,280 |
| No | 211378138 | YORK | HMH72B341 | XAHC36DBCN1 | TMLV100C16MP12 | 25,600 | $1,280 |
| No | 211378132 | YORK | HMH72B341 | XAHC36DBCN1 | TM8V100C16MP12 | 25,600 | $1,280 |
| No | 211378130 | YORK | HMH72B341 | XAHC36DXXN1+TXV | YPLC100C16MP13 | 25,600 | $1,280 |
| No | 211378127 | YORK | HMH72B341 | XAHC36DXXN1+TXV | YPLC080C16MP13 | 25,600 | $1,280 |
| No | 211378124 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TPLC100C16MP13 | 25,600 | $1,280 |
| No | 211378122 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TPLC080C16MP13 | 25,600 | $1,280 |
| No | 211378119 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TMLV100C16MP12 | 25,600 | $1,280 |
| No | 211378113 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TM8V100C16MP12 | 25,600 | $1,280 |
| No | 211378110 | YORK | HMH72B341 | XAUB30CXXN1+TXV | TM8Y060A12MP11 | 25,800 | $1,290 |
| No | 211378107 | YORK | HMH72B341 | XAFB30CXXN1+TXV | TM8Y060A12MP11 | 25,800 | $1,290 |
| No | 211378105 | YORK | HMH72B341 | XAUB36DXXN1+TXV | TM8Y060A12MP11 | 25,200 | $1,260 |
| No | 211378102 | YORK | HMH72B341 | XAFB36DBCN1 | TM8Y060A12MP11 | 25,200 | $1,260 |
| No | 211378099 | YORK | HMH72B341 | XAFB36DXXN1+TXV | TM8Y060A12MP11 | 25,200 | $1,260 |
| No | 211378097 | YORK | HMH72B341 | XAHB30CXXN1+TXV | TM8Y060A12MP11 | 25,400 | $1,270 |
| No | 211378094 | YORK | HMH72B341 | XAHB36DBCN1 | TM8Y060A12MP11 | 24,600 | $1,230 |
| No | 211378091 | YORK | HMH72B341 | XAHB36DXXN1+TXV | TM8Y060A12MP11 | 24,600 | $1,230 |
| No | 211378088 | YORK | HMH72B341 | XAUB30CXXN1+TXV | TM8Y080B12MP11 | 26,000 | $1,300 |
| No | 211378085 | YORK | HMH72B341 | XAFB30CXXN1+TXV | TM8Y080B12MP11 | 26,000 | $1,300 |
| No | 211378082 | YORK | HMH72B341 | XAUB36DXXN1+TXV | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211378079 | YORK | HMH72B341 | XAFB36DBCN1 | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211378076 | YORK | HMH72B341 | XAFB36DXXN1+TXV | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211378073 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TM8Y080B12MP11 | 26,000 | $1,300 |
| No | 211378070 | YORK | HMH72B341 | XAFC36DBCN1 | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211378067 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TM8Y080B12MP11 | 25,200 | $1,260 |
| No | 211378064 | YORK | HMH72B341 | XAHB30CXXN1+TXV | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211378061 | YORK | HMH72B341 | XAHB36DBCN1 | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211378058 | YORK | HMH72B341 | XAHB36DXXN1+TXV | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211378055 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TM8Y080B12MP11 | 25,400 | $1,270 |
| No | 211378052 | YORK | HMH72B341 | XAHC36DBCN1 | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211378049 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TM8Y080B12MP11 | 24,800 | $1,240 |
| No | 211378043 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TM8Y100C16MP11 | 26,400 | $1,320 |
| No | 211378037 | YORK | HMH72B341 | XAFC36DBCN1 | TM8Y100C16MP11 | 25,400 | $1,270 |
| No | 211378031 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TM8Y100C16MP11 | 25,400 | $1,270 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211378028 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TM8Y080C16MP11 | 26,600 | $1,330 |
| No | 211378025 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TM8Y100C16MP11 | 26,600 | $1,330 |
| No | 211378022 | YORK | HMH72B341 | XAHC36DBCN1 | TM8Y080C16MP11 | 25,600 | $1,280 |
| No | 211378019 | YORK | HMH72B341 | XAHC36DBCN1 | TM8Y100C16MP11 | 25,600 | $1,280 |
| No | 211378016 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TM8Y080C16MP11 | 25,600 | $1,280 |
| No | 211378013 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TM8Y100C16MP11 | 25,600 | $1,280 |
| No | 211378008 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TM8Y120C20MP11 | 27,000 | $1,350 |
| No | 211378002 | YORK | HMH72B341 | XAFC36DBCN1 | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211377996 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TM8Y120C20MP11 | 25,200 | $1,260 |
| No | 211377993 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TM8Y100C20MP11 | 26,400 | $1,320 |
| No | 211377990 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TM8Y120C20MP11 | 26,400 | $1,320 |
| No | 211377987 | YORK | HMH72B341 | XAHC36DBCN1 | TM8Y100C20MP11 | 25,400 | $1,270 |
| No | 211377984 | YORK | HMH72B341 | XAHC36DBCN1 | TM8Y120C20MP11 | 25,400 | $1,270 |
| No | 211377981 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TM8Y100C20MP11 | 25,400 | $1,270 |
| No | 211377978 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TM8Y120C20MP11 | 25,400 | $1,270 |
| No | 211377975 | YORK | HMH72B341 | XAUB30CXXN1+TXV | TM9E040A10MP12 | 25,800 | $1,290 |
| No | 211377972 | YORK | HMH72B341 | XAFB30CXXN1+TXV | TM9E040A10MP12 | 25,800 | $1,290 |
| No | 211377969 | YORK | HMH72B341 | XAUB30CXXN1+TXV | TM9E060A10MP12 | 26,200 | $1,310 |
| No | 211377966 | YORK | HMH72B341 | XAFB30CXXN1+TXV | TM9E060A10MP12 | 26,200 | $1,310 |
| No | 211377963 | YORK | HMH72B341 | XAUB36DXXN1+TXV | TM9E060A10MP12 | 25,400 | $1,270 |
| No | 211377960 | YORK | HMH72B341 | XAFB36DBCN1 | TM9E060A10MP12 | 25,400 | $1,270 |
| No | 211377957 | YORK | HMH72B341 | XAFB36DXXN1+TXV | TM9E060A10MP12 | 25,400 | $1,270 |
| No | 211377954 | YORK | HMH72B341 | XAHB30CXXN1+TXV | TM9E060A10MP12 | 25,800 | $1,290 |
| No | 211377951 | YORK | HMH72B341 | XAHB36DBCN1 | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 211377948 | YORK | HMH72B341 | XAHB36DXXN1+TXV | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 211377945 | YORK | HMH72B341 | XAUB30CXXN1+TXV | TM9E060B12MP12 | 26,400 | $1,320 |
| No | 211377942 | YORK | HMH72B341 | XAFB30CXXN1+TXV | TM9E060B12MP12 | 26,400 | $1,320 |
| No | 211377939 | YORK | HMH72B341 | XAUB36DXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211377936 | YORK | HMH72B341 | XAFB36DBCN1 | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211377933 | YORK | HMH72B341 | XAFB36DXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211377931 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TM9E060B12MP12 | 26,400 | $1,320 |
| No | 211377928 | YORK | HMH72B341 | XAFC36DBCN1 | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211377926 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TM9E060B12MP12 | 25,800 | $1,290 |
| No | 211377923 | YORK | HMH72B341 | XAHB30CXXN1+TXV | TM9E060B12MP12 | 26,000 | $1,300 |
| No | 211377920 | YORK | HMH72B341 | XAHB36DBCN1 | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211377917 | YORK | HMH72B341 | XAHB36DXXN1+TXV | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211377914 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TM9E060B12MP12 | 26,200 | $1,310 |
| No | 211377911 | YORK | HMH72B341 | XAHC36DBCN1 | TM9E060B12MP12 | 25,200 | $1,260 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211377908 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TM9E060B12MP12 | 25,200 | $1,260 |
| No | 211377905 | YORK | HMH72B341 | XAUB30CXXN1+TXV | TM9E080B12MP12 | 26,800 | $1,340 |
| No | 211377903 | YORK | HMH72B341 | XAFB30CXXN1+TXV | TM9E080B12MP12 | 26,800 | $1,340 |
| No | 211377900 | YORK | HMH72B341 | XAUB36DXXN1+TXV | TM9E080B12MP12 | 25,400 | $1,270 |
| No | 211377897 | YORK | HMH72B341 | XAFB36DBCN1 | TM9E080B12MP12 | 25,400 | $1,270 |
| No | 211377894 | YORK | HMH72B341 | XAFB36DXXN1+TXV | TM9E080B12MP12 | 25,400 | $1,270 |
| No | 211377890 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TM9E080B12MP12 | 26,400 | $1,320 |
| No | 211377888 | YORK | HMH72B341 | XAFC36DBCN1 | TM9E080B12MP12 | 25,800 | $1,290 |
| No | 211377884 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TM9E080B12MP12 | 25,800 | $1,290 |
| No | 211377881 | YORK | HMH72B341 | XAHB30CXXN1+TXV | TM9E080B12MP12 | 25,800 | $1,290 |
| No | 211377878 | YORK | HMH72B341 | XAHB36DBCN1 | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211377875 | YORK | HMH72B341 | XAHB36DXXN1+TXV | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211377873 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TM9E080B12MP12 | 26,200 | $1,310 |
| No | 211377870 | YORK | HMH72B341 | XAHC36DBCN1 | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211377867 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TM9E080B12MP12 | 25,000 | $1,250 |
| No | 211377864 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TM9E080C16MP12 | 26,200 | $1,310 |
| No | 211377862 | YORK | HMH72B341 | XAFC36DBCN1 | TM9E080C16MP12 | 25,200 | $1,260 |
| No | 211377861 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TM9E080C16MP12 | 25,200 | $1,260 |
| No | 211377860 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TM9E080C16MP12 | 26,800 | $1,340 |
| No | 211377859 | YORK | HMH72B341 | XAHC36DBCN1 | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211377858 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TM9E080C16MP12 | 25,600 | $1,280 |
| No | 211377857 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TM9E100C16MP12 | 26,200 | $1,310 |
| No | 211377855 | YORK | HMH72B341 | XAFC36DBCN1 | TM9E100C16MP12 | 25,200 | $1,260 |
| No | 211377852 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TM9E100C16MP12 | 25,200 | $1,260 |
| No | 211377849 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TM9E100C16MP12 | 25,600 | $1,280 |
| No | 211377846 | YORK | HMH72B341 | XAHC36DBCN1 | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211377843 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TM9E100C16MP12 | 24,800 | $1,240 |
| No | 211377840 | YORK | HMH72B341 | XAHC36DBCN1 | TM9E100C20MP12 | 25,000 | $1,250 |
| No | 211377837 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TM9E100C20MP12 | 25,000 | $1,250 |
| No | 211377834 | YORK | HMH72B341 | XAUB30CXXN1+TXV | TM9V040A10MP12 | 25,800 | $1,290 |
| No | 211377831 | YORK | HMH72B341 | XAFB30CXXN1+TXV | TM9V040A10MP12 | 25,800 | $1,290 |
| No | 211377828 | YORK | HMH72B341 | XAUB36DXXN1+TXV | TM9V040A10MP12 | 25,200 | $1,260 |
| No | 211377825 | YORK | HMH72B341 | XAFB36DBCN1 | TM9V040A10MP12 | 25,200 | $1,260 |
| No | 211377822 | YORK | HMH72B341 | XAFB36DXXN1+TXV | TM9V040A10MP12 | 25,200 | $1,260 |
| No | 211377819 | YORK | HMH72B341 | XAHB30CXXN1+TXV | TM9V040A10MP12 | 25,200 | $1,260 |
| No | 211377816 | YORK | HMH72B341 | XAHB36DBCN1 | TM9V040A10MP12 | 24,800 | $1,240 |
| No | 211377813 | YORK | HMH72B341 | XAHB36DXXN1+TXV | TM9V040A10MP12 | 24,800 | $1,240 |
| No | 211377810 | YORK | HMH72B341 | XAUB30CXXN1+TXV | YP9C060B12MP13 | 26,400 | $1,320 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211377807 | YORK | HMH72B341 | XAUB30CXXN1+TXV | TP9C060B12MP13 | 26,400 | $1,320 |
| No | 211377804 | YORK | HMH72B341 | XAUB30CXXN1+TXV | TM9V060B12MP12 | 26,400 | $1,320 |
| No | 211377801 | YORK | HMH72B341 | XAFB30CXXN1+TXV | YP9C060B12MP13 | 26,400 | $1,320 |
| No | 211377798 | YORK | HMH72B341 | XAFB30CXXN1+TXV | TP9C060B12MP13 | 26,400 | $1,320 |
| No | 211377795 | YORK | HMH72B341 | XAFB30CXXN1+TXV | TM9V060B12MP12 | 26,400 | $1,320 |
| No | 211377792 | YORK | HMH72B341 | XAUB36DXXN1+TXV | YP9C060B12MP13 | 25,600 | $1,280 |
| No | 211377789 | YORK | HMH72B341 | XAFB36DBCN1 | YP9C060B12MP13 | 25,600 | $1,280 |
| No | 211377786 | YORK | HMH72B341 | XAUB36DXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211377783 | YORK | HMH72B341 | XAFB36DBCN1 | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211377780 | YORK | HMH72B341 | XAUB36DXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211377777 | YORK | HMH72B341 | XAFB36DBCN1 | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211377774 | YORK | HMH72B341 | XAFB36DXXN1+TXV | YP9C060B12MP13 | 25,600 | $1,280 |
| No | 211377771 | YORK | HMH72B341 | XAFB36DXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211377768 | YORK | HMH72B341 | XAFB36DXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211377765 | YORK | HMH72B341 | XAFC30CXXN1+TXV | YP9C060B12MP13 | 26,400 | $1,320 |
| No | 211377762 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TP9C060B12MP13 | 26,400 | $1,320 |
| No | 211377760 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TM9V060B12MP12 | 26,400 | $1,320 |
| No | 211377757 | YORK | HMH72B341 | XAFC36DBCN1 | YP9C060B12MP13 | 25,600 | $1,280 |
| No | 211377756 | YORK | HMH72B341 | XAFC36DBCN1 | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211377755 | YORK | HMH72B341 | XAFC36DBCN1 | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211377754 | YORK | HMH72B341 | XAFC36DXXN1+TXV | YP9C060B12MP13 | 25,600 | $1,280 |
| No | 211377752 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211377749 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211377746 | YORK | HMH72B341 | XAHB30CXXN1+TXV | YP9C060B12MP13 | 25,600 | $1,280 |
| No | 211377743 | YORK | HMH72B341 | XAHB30CXXN1+TXV | TP9C060B12MP13 | 25,600 | $1,280 |
| No | 211377740 | YORK | HMH72B341 | XAHB30CXXN1+TXV | TM9V060B12MP12 | 25,600 | $1,280 |
| No | 211377737 | YORK | HMH72B341 | XAHB36DBCN1 | YP9C060B12MP13 | 25,000 | $1,250 |
| No | 211377734 | YORK | HMH72B341 | XAHB36DBCN1 | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 211377731 | YORK | HMH72B341 | XAHB36DBCN1 | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 211377728 | YORK | HMH72B341 | XAHB36DXXN1+TXV | YP9C060B12MP13 | 25,000 | $1,250 |
| No | 211377725 | YORK | HMH72B341 | XAHB36DXXN1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 211377722 | YORK | HMH72B341 | XAHB36DXXN1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 211377719 | YORK | HMH72B341 | XAHC30CXXN1+TXV | YP9C060B12MP13 | 26,000 | $1,300 |
| No | 211377716 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TP9C060B12MP13 | 26,000 | $1,300 |
| No | 211377713 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TM9V060B12MP12 | 26,000 | $1,300 |
| No | 211377710 | YORK | HMH72B341 | XAHC36DBCN1 | YP9C060B12MP13 | 25,200 | $1,260 |
| No | 211377707 | YORK | HMH72B341 | XAHC36DBCN1 | TP9C060B12MP13 | 25,200 | $1,260 |
| No | 211377704 | YORK | HMH72B341 | XAHC36DBCN1 | TM9V060B12MP12 | 25,200 | $1,260 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211377701 | YORK | HMH72B341 | XAHC36DXXN1+TXV | YP9C060B12MP13 | 25,200 | $1,260 |
| No | 211377699 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TP9C060B12MP13 | 25,200 | $1,260 |
| No | 211377696 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TM9V060B12MP12 | 25,200 | $1,260 |
| No | 211377693 | YORK | HMH72B341 | XAUB30CXXN1+TXV | YP9C080B12MP13 | 26,600 | $1,330 |
| No | 211377690 | YORK | HMH72B341 | XAUB30CXXN1+TXV | TP9C080B12MP13 | 26,600 | $1,330 |
| No | 211377687 | YORK | HMH72B341 | XAUB30CXXN1+TXV | TM9V080B12MP12 | 26,600 | $1,330 |
| No | 211377684 | YORK | HMH72B341 | XAFB30CXXN1+TXV | YP9C080B12MP13 | 26,600 | $1,330 |
| No | 211377682 | YORK | HMH72B341 | XAFB30CXXN1+TXV | TP9C080B12MP13 | 26,600 | $1,330 |
| No | 211377681 | YORK | HMH72B341 | XAFB30CXXN1+TXV | TM9V080B12MP12 | 26,600 | $1,330 |
| No | 211377679 | YORK | HMH72B341 | XAUB36DXXN1+TXV | YP9C080B12MP13 | 25,800 | $1,290 |
| No | 211377676 | YORK | HMH72B341 | XAFB36DBCN1 | YP9C080B12MP13 | 25,800 | $1,290 |
| No | 211377673 | YORK | HMH72B341 | XAUB36DXXN1+TXV | TP9C080B12MP13 | 25,800 | $1,290 |
| No | 211377670 | YORK | HMH72B341 | XAFB36DBCN1 | TP9C080B12MP13 | 25,800 | $1,290 |
| No | 211377667 | YORK | HMH72B341 | XAUB36DXXN1+TXV | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211377664 | YORK | HMH72B341 | XAFB36DBCN1 | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211377661 | YORK | HMH72B341 | XAFB36DXXN1+TXV | YP9C080B12MP13 | 25,800 | $1,290 |
| No | 211377658 | YORK | HMH72B341 | XAFB36DXXN1+TXV | TP9C080B12MP13 | 25,800 | $1,290 |
| No | 211377655 | YORK | HMH72B341 | XAFB36DXXN1+TXV | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211377652 | YORK | HMH72B341 | XAFC30CXXN1+TXV | YP9C080B12MP13 | 26,600 | $1,330 |
| No | 211377649 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TP9C080B12MP13 | 26,600 | $1,330 |
| No | 211377646 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TM9V080B12MP12 | 26,600 | $1,330 |
| No | 211377643 | YORK | HMH72B341 | XAFC36DBCN1 | YP9C080B12MP13 | 25,800 | $1,290 |
| No | 211377640 | YORK | HMH72B341 | XAFC36DBCN1 | TP9C080B12MP13 | 25,800 | $1,290 |
| No | 211377637 | YORK | HMH72B341 | XAFC36DBCN1 | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211377634 | YORK | HMH72B341 | XAFC36DXXN1+TXV | YP9C080B12MP13 | 25,800 | $1,290 |
| No | 211377631 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TP9C080B12MP13 | 25,800 | $1,290 |
| No | 211377628 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TM9V080B12MP12 | 25,800 | $1,290 |
| No | 211377625 | YORK | HMH72B341 | XAHB30CXXN1+TXV | YP9C080B12MP13 | 26,200 | $1,310 |
| No | 211377622 | YORK | HMH72B341 | XAHB30CXXN1+TXV | TP9C080B12MP13 | 26,200 | $1,310 |
| No | 211377619 | YORK | HMH72B341 | XAHB30CXXN1+TXV | TM9V080B12MP12 | 26,200 | $1,310 |
| No | 211377616 | YORK | HMH72B341 | XAHB36DBCN1 | YP9C080B12MP13 | 25,200 | $1,260 |
| No | 211377614 | YORK | HMH72B341 | XAHB36DBCN1 | TP9C080B12MP13 | 25,200 | $1,260 |
| No | 211377611 | YORK | HMH72B341 | XAHB36DBCN1 | TM9V080B12MP12 | 25,200 | $1,260 |
| No | 211377608 | YORK | HMH72B341 | XAHB36DXXN1+TXV | YP9C080B12MP13 | 25,200 | $1,260 |
| No | 211377605 | YORK | HMH72B341 | XAHB36DXXN1+TXV | TP9C080B12MP13 | 25,200 | $1,260 |
| No | 211377602 | YORK | HMH72B341 | XAHB36DXXN1+TXV | TM9V080B12MP12 | 25,200 | $1,260 |
| No | 211377599 | YORK | HMH72B341 | XAHC30CXXN1+TXV | YP9C080B12MP13 | 26,200 | $1,310 |
| No | 211377596 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TP9C080B12MP13 | 26,200 | $1,310 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211377593 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TM9V080B12MP12 | 26,200 | $1,310 |
| No | 211377590 | YORK | HMH72B341 | XAHC36DBCN1 | YP9C080B12MP13 | 25,000 | $1,250 |
| No | 211377587 | YORK | HMH72B341 | XAHC36DBCN1 | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 211377584 | YORK | HMH72B341 | XAHC36DBCN1 | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 211377581 | YORK | HMH72B341 | XAHC36DXXN1+TXV | YP9C080B12MP13 | 25,000 | $1,250 |
| No | 211377580 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 211377579 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 211377578 | YORK | HMH72B341 | XAFC30CXXN1+TXV | YP9C080C16MP13 | 26,200 | $1,310 |
| No | 211377577 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TP9C080C16MP13 | 26,200 | $1,310 |
| No | 211377576 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TM9V080C16MP12 | 26,200 | $1,310 |
| No | 211377575 | YORK | HMH72B341 | XAFC36DBCN1 | YP9C080C16MP13 | 25,400 | $1,270 |
| No | 211377574 | YORK | HMH72B341 | XAFC36DBCN1 | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211377572 | YORK | HMH72B341 | XAFC36DBCN1 | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211377568 | YORK | HMH72B341 | XAFC36DXXN1+TXV | YP9C080C16MP13 | 25,400 | $1,270 |
| No | 211377565 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TP9C080C16MP13 | 25,400 | $1,270 |
| No | 211377562 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TM9V080C16MP12 | 25,400 | $1,270 |
| No | 211377559 | YORK | HMH72B341 | XAHC30CXXN1+TXV | YP9C080C16MP13 | 25,800 | $1,290 |
| No | 211377556 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TP9C080C16MP13 | 25,800 | $1,290 |
| No | 211377553 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TM9V080C16MP12 | 25,800 | $1,290 |
| No | 211377550 | YORK | HMH72B341 | XAHC36DBCN1 | YP9C080C16MP13 | 25,000 | $1,250 |
| No | 211377548 | YORK | HMH72B341 | XAHC36DBCN1 | TP9C080C16MP13 | 25,000 | $1,250 |
| No | 211377545 | YORK | HMH72B341 | XAHC36DBCN1 | TM9V080C16MP12 | 25,000 | $1,250 |
| No | 211377542 | YORK | HMH72B341 | XAHC36DXXN1+TXV | YP9C080C16MP13 | 25,000 | $1,250 |
| No | 211377539 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TP9C080C16MP13 | 25,000 | $1,250 |
| No | 211377536 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TM9V080C16MP12 | 25,000 | $1,250 |
| No | 211377533 | YORK | HMH72B341 | XAFC30CXXN1+TXV | YP9C100C16MP13 | 26,400 | $1,320 |
| No | 211377530 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TP9C100C16MP13 | 26,400 | $1,320 |
| No | 211377527 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TM9V100C16MP12 | 26,400 | $1,320 |
| No | 211377524 | YORK | HMH72B341 | XAFC36DBCN1 | YP9C100C16MP13 | 25,400 | $1,270 |
| No | 211377521 | YORK | HMH72B341 | XAFC36DBCN1 | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211377518 | YORK | HMH72B341 | XAFC36DBCN1 | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211377515 | YORK | HMH72B341 | XAFC36DXXN1+TXV | YP9C100C16MP13 | 25,400 | $1,270 |
| No | 211377512 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TP9C100C16MP13 | 25,400 | $1,270 |
| No | 211377509 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TM9V100C16MP12 | 25,400 | $1,270 |
| No | 211377506 | YORK | HMH72B341 | XAHC30CXXN1+TXV | YP9C100C16MP13 | 25,800 | $1,290 |
| No | 211377503 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TP9C100C16MP13 | 25,800 | $1,290 |
| No | 211377500 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TM9V100C16MP12 | 25,800 | $1,290 |
| No | 211377497 | YORK | HMH72B341 | XAHC36DBCN1 | YP9C100C16MP13 | 25,000 | $1,250 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211377494 | YORK | HMH72B341 | XAHC36DBCN1 | TP9C100C16MP13 | 25,000 | $1,250 |
| No | 211377491 | YORK | HMH72B341 | XAHC36DBCN1 | TM9V100C16MP12 | 25,000 | $1,250 |
| No | 211377488 | YORK | HMH72B341 | XAHC36DXXN1+TXV | YP9C100C16MP13 | 25,000 | $1,250 |
| No | 211377485 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TP9C100C16MP13 | 25,000 | $1,250 |
| No | 211377482 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TM9V100C16MP12 | 25,000 | $1,250 |
| No | 211377479 | YORK | HMH72B341 | XAFC30CXXN1+TXV | YP9C100C20MP13 | 27,000 | $1,350 |
| No | 211377476 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TP9C100C20MP13 | 27,000 | $1,350 |
| No | 211377473 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TM9V100C20MP12 | 27,000 | $1,350 |
| No | 211377471 | YORK | HMH72B341 | XAFC36DBCN1 | YP9C100C20MP13 | 26,000 | $1,300 |
| No | 211377468 | YORK | HMH72B341 | XAFC36DBCN1 | TP9C100C20MP13 | 26,000 | $1,300 |
| No | 211377465 | YORK | HMH72B341 | XAFC36DBCN1 | TM9V100C20MP12 | 26,000 | $1,300 |
| No | 211377462 | YORK | HMH72B341 | XAFC36DXXN1+TXV | YP9C100C20MP13 | 26,000 | $1,300 |
| No | 211377459 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TP9C100C20MP13 | 26,000 | $1,300 |
| No | 211377456 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TM9V100C20MP12 | 26,000 | $1,300 |
| No | 211377453 | YORK | HMH72B341 | XAHC30CXXN1+TXV | YP9C100C20MP13 | 26,600 | $1,330 |
| No | 211377450 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TP9C100C20MP13 | 26,600 | $1,330 |
| No | 211377447 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TM9V100C20MP12 | 26,600 | $1,330 |
| No | 211377444 | YORK | HMH72B341 | XAUB30CXXN1+TXV | TM9Y060B12MP11 | 26,600 | $1,330 |
| No | 211377441 | YORK | HMH72B341 | XAFB30CXXN1+TXV | TM9Y060B12MP11 | 26,600 | $1,330 |
| No | 211377438 | YORK | HMH72B341 | XAUB36DXXN1+TXV | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211377435 | YORK | HMH72B341 | XAFB36DBCN1 | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211377432 | YORK | HMH72B341 | XAFB36DXXN1+TXV | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211377429 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TM9Y060B12MP11 | 26,600 | $1,330 |
| No | 211377426 | YORK | HMH72B341 | XAFC36DBCN1 | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211377423 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TM9Y060B12MP11 | 25,600 | $1,280 |
| No | 211377420 | YORK | HMH72B341 | XAHB30CXXN1+TXV | TM9Y060B12MP11 | 26,000 | $1,300 |
| No | 211377417 | YORK | HMH72B341 | XAHB36DBCN1 | TM9Y060B12MP11 | 25,000 | $1,250 |
| No | 211377414 | YORK | HMH72B341 | XAHB36DXXN1+TXV | TM9Y060B12MP11 | 25,000 | $1,250 |
| No | 211377411 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TM9Y060B12MP11 | 26,000 | $1,300 |
| No | 211377408 | YORK | HMH72B341 | XAHC36DBCN1 | TM9Y060B12MP11 | 25,200 | $1,260 |
| No | 211377405 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TM9Y060B12MP11 | 25,200 | $1,260 |
| No | 211377402 | YORK | HMH72B341 | XAUB30CXXN1+TXV | TM9Y080B12MP11 | 26,800 | $1,340 |
| No | 211377399 | YORK | HMH72B341 | XAFB30CXXN1+TXV | TM9Y080B12MP11 | 26,800 | $1,340 |
| No | 211377396 | YORK | HMH72B341 | XAUB36DXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211377393 | YORK | HMH72B341 | XAFB36DBCN1 | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211377391 | YORK | HMH72B341 | XAFB36DXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211377389 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TM9Y080B12MP11 | 26,800 | $1,340 |
| No | 211377388 | YORK | HMH72B341 | XAFC36DBCN1 | TM9Y080B12MP11 | 25,800 | $1,290 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211377387 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TM9Y080B12MP11 | 25,800 | $1,290 |
| No | 211377386 | YORK | HMH72B341 | XAHB30CXXN1+TXV | TM9Y080B12MP11 | 26,200 | $1,310 |
| No | 211377384 | YORK | HMH72B341 | XAHB36DBCN1 | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211377381 | YORK | HMH72B341 | XAHB36DXXN1+TXV | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211377378 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TM9Y080B12MP11 | 26,200 | $1,310 |
| No | 211377375 | YORK | HMH72B341 | XAHC36DBCN1 | TM9Y080B12MP11 | 25,400 | $1,270 |
| No | 211377372 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TM9Y080B12MP11 | 25,400 | $1,270 |
| No | 211377369 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TM9Y080C16MP11 | 26,800 | $1,340 |
| No | 211377366 | YORK | HMH72B341 | XAFC36DBCN1 | TM9Y080C16MP11 | 25,800 | $1,290 |
| No | 211377363 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TM9Y080C16MP11 | 25,800 | $1,290 |
| No | 211377360 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TM9Y080C16MP11 | 26,200 | $1,310 |
| No | 211377357 | YORK | HMH72B341 | XAHC36DBCN1 | TM9Y080C16MP11 | 25,400 | $1,270 |
| No | 211377355 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TM9Y080C16MP11 | 25,400 | $1,270 |
| No | 211377352 | YORK | HMH72B341 | XAFC30CXXN1+TXV | TM9Y100C16MP11 | 26,000 | $1,300 |
| No | 211377349 | YORK | HMH72B341 | XAFC36DBCN1 | TM9Y100C16MP11 | 25,800 | $1,290 |
| No | 211377346 | YORK | HMH72B341 | XAFC36DXXN1+TXV | TM9Y100C16MP11 | 25,800 | $1,290 |
| No | 211377343 | YORK | HMH72B341 | XAHC30CXXN1+TXV | TM9Y100C16MP11 | 25,600 | $1,280 |
| No | 211377340 | YORK | HMH72B341 | XAHC36DBCN1 | TM9Y100C16MP11 | 25,400 | $1,270 |
| No | 211377337 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TM9Y100C16MP11 | 25,400 | $1,270 |
| No | 211377334 | YORK | HMH72B341 | XAHC36DBCN1 | TM9Y100C20MP11 | 25,600 | $1,280 |
| No | 211377331 | YORK | HMH72B341 | XAHC36DXXN1+TXV | TM9Y100C20MP11 | 25,600 | $1,280 |
| No | 211238140 | YORK | HMH72B341 | JHETC36DBCS2N1 | | 24,600 | $1,230 |
| No | 211659855 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TM8E080B12MP11 | 24,400 | $1,220 |
| No | 211659854 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TMLE080C16MP11 | 24,200 | $1,210 |
| No | 211659853 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TM8E080C16MP11 | 24,200 | $1,210 |
| No | 211659852 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TMLE080C16MP11 | 23,800 | $1,190 |
| No | 211659851 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TM8E080C16MP11 | 23,800 | $1,190 |
| No | 211659850 | YORK | HMH72B361 | XAUB30CXXN1+TXV | TMLE100B12MP11 | 24,400 | $1,220 |
| No | 211659849 | YORK | HMH72B361 | XAUB30CXXN1+TXV | TM8E100B12MP11 | 24,400 | $1,220 |
| No | 211659848 | YORK | HMH72B361 | XAFB30CXXN1+TXV | TMLE100B12MP11 | 24,400 | $1,220 |
| No | 211659847 | YORK | HMH72B361 | XAFB30CXXN1+TXV | TM8E100B12MP11 | 24,400 | $1,220 |
| No | 211659846 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TMLE100B12MP11 | 24,400 | $1,220 |
| No | 211659845 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TM8E100B12MP11 | 24,400 | $1,220 |
| No | 211659844 | YORK | HMH72B361 | XAHB30CXXN1+TXV | TMLE100B12MP11 | 24,000 | $1,200 |
| No | 211659843 | YORK | HMH72B361 | XAHB30CXXN1+TXV | TM8E100B12MP11 | 24,000 | $1,200 |
| No | 211659842 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TMLE100B12MP11 | 24,000 | $1,200 |
| No | 211659841 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TM8E100B12MP11 | 24,000 | $1,200 |
| No | 211659840 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TMLE100C16MP11 | 24,200 | $1,210 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211659839 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TM8E100C16MP11 | 24,200 | $1,210 |
| No | 211659838 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TMLE100C16MP11 | 23,800 | $1,190 |
| No | 211659837 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TM8E100C16MP11 | 23,800 | $1,190 |
| No | 211659836 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TMLE120C16MP11 | 24,200 | $1,210 |
| No | 211659835 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TM8E120C16MP11 | 24,200 | $1,210 |
| No | 211659834 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TMLE120C16MP11 | 23,800 | $1,190 |
| No | 211659833 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TM8E120C16MP11 | 23,800 | $1,190 |
| No | 211659832 | YORK | HMH72B361 | XAFA30DXXN1+TXV | YPLC060A12MP13 | 25,800 | $1,290 |
| No | 211659831 | YORK | HMH72B361 | XAFA30DXXN1+TXV | TPLC060A12MP13 | 25,800 | $1,290 |
| No | 211659830 | YORK | HMH72B361 | XAFA30DXXN1+TXV | TMLV060A12MP12 | 25,800 | $1,290 |
| No | 211659829 | YORK | HMH72B361 | XAFA30DXXN1+TXV | TM8V060A12MP12 | 25,800 | $1,290 |
| No | 211659828 | YORK | HMH72B361 | XAUB30CXXN1+TXV | YPLC060A12MP13 | 25,000 | $1,250 |
| No | 211659827 | YORK | HMH72B361 | XAUB30CXXN1+TXV | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 211659826 | YORK | HMH72B361 | XAUB30CXXN1+TXV | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 211659825 | YORK | HMH72B361 | XAUB30CXXN1+TXV | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 211659824 | YORK | HMH72B361 | XAFB30CXXN1+TXV | YPLC060A12MP13 | 25,000 | $1,250 |
| No | 211659823 | YORK | HMH72B361 | XAFB30CXXN1+TXV | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 211659822 | YORK | HMH72B361 | XAFB30CXXN1+TXV | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 211659821 | YORK | HMH72B361 | XAFB30CXXN1+TXV | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 211659820 | YORK | HMH72B361 | XAHB30CXXN1+TXV | YPLC060A12MP13 | 24,200 | $1,210 |
| No | 211659819 | YORK | HMH72B361 | XAHB30CXXN1+TXV | TPLC060A12MP13 | 24,200 | $1,210 |
| No | 211659818 | YORK | HMH72B361 | XAHB30CXXN1+TXV | TMLV060A12MP12 | 24,200 | $1,210 |
| No | 211659817 | YORK | HMH72B361 | XAHB30CXXN1+TXV | TM8V060A12MP12 | 24,200 | $1,210 |
| No | 211659816 | YORK | HMH72B361 | XAUB30CXXN1+TXV | YPLC080B12MP13 | 24,600 | $1,230 |
| No | 211659815 | YORK | HMH72B361 | XAUB30CXXN1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 211659814 | YORK | HMH72B361 | XAUB30CXXN1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 211659813 | YORK | HMH72B361 | XAFB30CXXN1+TXV | YPLC080B12MP13 | 24,600 | $1,230 |
| No | 211659812 | YORK | HMH72B361 | XAFB30CXXN1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 211659811 | YORK | HMH72B361 | XAFB30CXXN1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 211659810 | YORK | HMH72B361 | XAFC30CXXN1+TXV | YPLC080B12MP13 | 24,800 | $1,240 |
| No | 211659809 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TPLC080B12MP13 | 24,800 | $1,240 |
| No | 211659808 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TM8V080B12MP12 | 24,800 | $1,240 |
| No | 211659807 | YORK | HMH72B361 | XAHB30CXXN1+TXV | YPLC080B12MP13 | 24,000 | $1,200 |
| No | 211659806 | YORK | HMH72B361 | XAHB30CXXN1+TXV | TPLC080B12MP13 | 24,000 | $1,200 |
| No | 211659805 | YORK | HMH72B361 | XAHB30CXXN1+TXV | TM8V080B12MP12 | 24,000 | $1,200 |
| No | 211659804 | YORK | HMH72B361 | XAHC30CXXN1+TXV | YPLC080B12MP13 | 24,200 | $1,210 |
| No | 211659803 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TPLC080B12MP13 | 24,200 | $1,210 |
| No | 211659802 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TM8V080B12MP12 | 24,200 | $1,210 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211659801 | YORK | HMH72B361 | XAFC30CXXN1+TXV | YPLC100C16MP13 | 25,000 | $1,250 |
| No | 211659800 | YORK | HMH72B361 | XAFC30CXXN1+TXV | YPLC080C16MP13 | 25,000 | $1,250 |
| No | 211659799 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TPLC100C16MP13 | 25,000 | $1,250 |
| No | 211659798 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TPLC080C16MP13 | 25,000 | $1,250 |
| No | 211659797 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TMLV100C16MP12 | 25,000 | $1,250 |
| No | 211659796 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TM8V080C16MP12 | 25,000 | $1,250 |
| No | 211659795 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TM8V100C16MP12 | 25,000 | $1,250 |
| No | 211659794 | YORK | HMH72B361 | XAHC30CXXN1+TXV | YPLC100C16MP13 | 24,600 | $1,230 |
| No | 211659793 | YORK | HMH72B361 | XAHC30CXXN1+TXV | YPLC080C16MP13 | 24,600 | $1,230 |
| No | 211659792 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 211659791 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TPLC080C16MP13 | 24,600 | $1,230 |
| No | 211659790 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TMLV100C16MP12 | 24,600 | $1,230 |
| No | 211659788 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 211659787 | YORK | HMH72B361 | XAUB30CXXN1+TXV | TM8Y060A12MP11 | 24,200 | $1,210 |
| No | 211659786 | YORK | HMH72B361 | XAFB30CXXN1+TXV | TM8Y060A12MP11 | 24,200 | $1,210 |
| No | 211659785 | YORK | HMH72B361 | XAHB30CXXN1+TXV | TM8Y060A12MP11 | 23,800 | $1,190 |
| No | 211659784 | YORK | HMH72B361 | XAUB30CXXN1+TXV | TM8Y080B12MP11 | 24,200 | $1,210 |
| No | 211659783 | YORK | HMH72B361 | XAFB30CXXN1+TXV | TM8Y080B12MP11 | 24,200 | $1,210 |
| No | 211659782 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TM8Y080B12MP11 | 24,200 | $1,210 |
| No | 211659781 | YORK | HMH72B361 | XAHB30CXXN1+TXV | TM8Y080B12MP11 | 23,800 | $1,190 |
| No | 211659780 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TM8Y080B12MP11 | 23,800 | $1,190 |
| No | 211659779 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TM8Y080C16MP11 | 25,200 | $1,260 |
| No | 211659778 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TM8Y100C16MP11 | 25,200 | $1,260 |
| No | 211659777 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TM8Y080C16MP11 | 24,600 | $1,230 |
| No | 211659776 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TM8Y100C16MP11 | 24,600 | $1,230 |
| No | 211659775 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TM8Y100C20MP11 | 24,800 | $1,240 |
| No | 211659774 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TM8Y120C20MP11 | 24,800 | $1,240 |
| No | 211659773 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TM8Y100C20MP11 | 24,400 | $1,220 |
| No | 211659772 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TM8Y120C20MP11 | 24,400 | $1,220 |
| No | 211659771 | YORK | HMH72B361 | XAUB30CXXN1+TXV | TM9E040A10MP12 | 24,200 | $1,210 |
| No | 211659770 | YORK | HMH72B361 | XAFB30CXXN1+TXV | TM9E040A10MP12 | 24,200 | $1,210 |
| No | 211659769 | YORK | HMH72B361 | XAUB30CXXN1+TXV | TM9E060A10MP12 | 24,400 | $1,220 |
| No | 211659768 | YORK | HMH72B361 | XAFB30CXXN1+TXV | TM9E060A10MP12 | 24,400 | $1,220 |
| No | 211659767 | YORK | HMH72B361 | XAHB30CXXN1+TXV | TM9E060A10MP12 | 24,000 | $1,200 |
| No | 211659766 | YORK | HMH72B361 | XAUB30CXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 211659765 | YORK | HMH72B361 | XAFB30CXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 211659764 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 211659763 | YORK | HMH72B361 | XAHB30CXXN1+TXV | TM9E060B12MP12 | 24,200 | $1,210 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211659762 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 211659761 | YORK | HMH72B361 | XAUB30CXXN1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 211659760 | YORK | HMH72B361 | XAFB30CXXN1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 211659759 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 211659758 | YORK | HMH72B361 | XAHB30CXXN1+TXV | TM9E080B12MP12 | 24,400 | $1,220 |
| No | 211659757 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TM9E080B12MP12 | 24,400 | $1,220 |
| No | 211659756 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TM9E080C16MP12 | 25,200 | $1,260 |
| No | 211659755 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TM9E080C16MP12 | 24,800 | $1,240 |
| No | 211659754 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TM9E100C16MP12 | 24,400 | $1,220 |
| No | 211659753 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TM9E100C16MP12 | 23,800 | $1,190 |
| No | 211659752 | YORK | HMH72B361 | XAUB30CXXN1+TXV | TM9V040A10MP12 | 24,400 | $1,220 |
| No | 211659751 | YORK | HMH72B361 | XAFB30CXXN1+TXV | TM9V040A10MP12 | 24,400 | $1,220 |
| No | 211659749 | YORK | HMH72B361 | XAUB30CXXN1+TXV | YP9C060B12MP13 | 24,600 | $1,230 |
| No | 211659748 | YORK | HMH72B361 | XAUB30CXXN1+TXV | TP9C060B12MP13 | 24,600 | $1,230 |
| No | 211659747 | YORK | HMH72B361 | XAUB30CXXN1+TXV | TM9V060B12MP12 | 24,600 | $1,230 |
| No | 211659746 | YORK | HMH72B361 | XAFB30CXXN1+TXV | YP9C060B12MP13 | 24,600 | $1,230 |
| No | 211659745 | YORK | HMH72B361 | XAFB30CXXN1+TXV | TP9C060B12MP13 | 24,600 | $1,230 |
| No | 211659744 | YORK | HMH72B361 | XAFB30CXXN1+TXV | TM9V060B12MP12 | 24,600 | $1,230 |
| No | 211659743 | YORK | HMH72B361 | XAFC30CXXN1+TXV | YP9C060B12MP13 | 24,600 | $1,230 |
| No | 211659742 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TP9C060B12MP13 | 24,600 | $1,230 |
| No | 211659741 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TM9V060B12MP12 | 24,600 | $1,230 |
| No | 211659740 | YORK | HMH72B361 | XAHB30CXXN1+TXV | YP9C060B12MP13 | 24,000 | $1,200 |
| No | 211659739 | YORK | HMH72B361 | XAHB30CXXN1+TXV | TP9C060B12MP13 | 24,000 | $1,200 |
| No | 211659738 | YORK | HMH72B361 | XAHB30CXXN1+TXV | TM9V060B12MP12 | 24,000 | $1,200 |
| No | 211659737 | YORK | HMH72B361 | XAHC30CXXN1+TXV | YP9C060B12MP13 | 24,200 | $1,210 |
| No | 211659736 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TP9C060B12MP13 | 24,200 | $1,210 |
| No | 211659735 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TM9V060B12MP12 | 24,200 | $1,210 |
| No | 211659734 | YORK | HMH72B361 | XAUB30CXXN1+TXV | YP9C080B12MP13 | 24,800 | $1,240 |
| No | 211659733 | YORK | HMH72B361 | XAUB30CXXN1+TXV | TP9C080B12MP13 | 24,800 | $1,240 |
| No | 211659732 | YORK | HMH72B361 | XAUB30CXXN1+TXV | TM9V080B12MP12 | 24,800 | $1,240 |
| No | 211659731 | YORK | HMH72B361 | XAFB30CXXN1+TXV | YP9C080B12MP13 | 24,800 | $1,240 |
| No | 211659730 | YORK | HMH72B361 | XAFB30CXXN1+TXV | TP9C080B12MP13 | 24,800 | $1,240 |
| No | 211659729 | YORK | HMH72B361 | XAFB30CXXN1+TXV | TM9V080B12MP12 | 24,800 | $1,240 |
| No | 211659728 | YORK | HMH72B361 | XAFC30CXXN1+TXV | YP9C080B12MP13 | 25,000 | $1,250 |
| No | 211659727 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 211659726 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 211659725 | YORK | HMH72B361 | XAHB30CXXN1+TXV | YP9C080B12MP13 | 24,400 | $1,220 |
| No | 211659724 | YORK | HMH72B361 | XAHB30CXXN1+TXV | TP9C080B12MP13 | 24,400 | $1,220 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211659723 | YORK | HMH72B361 | XAHB30CXXN1+TXV | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 211659722 | YORK | HMH72B361 | XAHC30CXXN1+TXV | YP9C080B12MP13 | 24,600 | $1,230 |
| No | 211659721 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 211659720 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 211659719 | YORK | HMH72B361 | XAFC30CXXN1+TXV | YP9C080C16MP13 | 25,200 | $1,260 |
| No | 211659718 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TP9C080C16MP13 | 25,200 | $1,260 |
| No | 211659717 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TM9V080C16MP12 | 25,200 | $1,260 |
| No | 211659716 | YORK | HMH72B361 | XAHC30CXXN1+TXV | YP9C080C16MP13 | 24,800 | $1,240 |
| No | 211659715 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TP9C080C16MP13 | 24,800 | $1,240 |
| No | 211659714 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TM9V080C16MP12 | 24,800 | $1,240 |
| No | 211659713 | YORK | HMH72B361 | XAFC30CXXN1+TXV | YP9C100C16MP13 | 24,800 | $1,240 |
| No | 211659712 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TP9C100C16MP13 | 24,800 | $1,240 |
| No | 211659711 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TM9V100C16MP12 | 24,800 | $1,240 |
| No | 211659710 | YORK | HMH72B361 | XAHC30CXXN1+TXV | YP9C100C16MP13 | 24,600 | $1,230 |
| No | 211659709 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TP9C100C16MP13 | 24,600 | $1,230 |
| No | 211659708 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TM9V100C16MP12 | 24,600 | $1,230 |
| No | 211659707 | YORK | HMH72B361 | XAFC30CXXN1+TXV | YP9C100C20MP13 | 25,000 | $1,250 |
| No | 211659706 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TP9C100C20MP13 | 25,000 | $1,250 |
| No | 211659705 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TM9V100C20MP12 | 25,000 | $1,250 |
| No | 211659704 | YORK | HMH72B361 | XAHC30CXXN1+TXV | YP9C100C20MP13 | 24,600 | $1,230 |
| No | 211659703 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TP9C100C20MP13 | 24,600 | $1,230 |
| No | 211659702 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TM9V100C20MP12 | 24,600 | $1,230 |
| No | 211659701 | YORK | HMH72B361 | XAUB30CXXN1+TXV | TM9Y060B12MP11 | 24,800 | $1,240 |
| No | 211659700 | YORK | HMH72B361 | XAFB30CXXN1+TXV | TM9Y060B12MP11 | 24,800 | $1,240 |
| No | 211659699 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TM9Y060B12MP11 | 24,800 | $1,240 |
| No | 211659698 | YORK | HMH72B361 | XAHB30CXXN1+TXV | TM9Y060B12MP11 | 24,200 | $1,210 |
| No | 211659697 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TM9Y060B12MP11 | 24,200 | $1,210 |
| No | 211659696 | YORK | HMH72B361 | XAUB30CXXN1+TXV | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211659695 | YORK | HMH72B361 | XAFB30CXXN1+TXV | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211659694 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TM9Y080B12MP11 | 24,800 | $1,240 |
| No | 211659693 | YORK | HMH72B361 | XAHB30CXXN1+TXV | TM9Y080B12MP11 | 24,400 | $1,220 |
| No | 211659692 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TM9Y080B12MP11 | 24,400 | $1,220 |
| No | 211659691 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TM9Y080C16MP11 | 24,800 | $1,240 |
| No | 211659690 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TM9Y080C16MP11 | 24,400 | $1,220 |
| No | 211659689 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TM9Y100C16MP11 | 24,800 | $1,240 |
| No | 211659688 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TM9Y100C16MP11 | 24,400 | $1,220 |
| No | 211659687 | YORK | HMH72B241 | XAHB30CBAN1 | TM9E040A10MP12 | 15,000 | $750 |
| No | 211659686 | YORK | HMH72B241 | XAHB30CXXN1+TXV | TM9E040A10MP12 | 15,000 | $750 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211659685 | YORK | HMH72B241 | XAUB30CXXN1+TXV | TM9E060A10MP12 | 15,000 | $750 |
| No | 211659684 | YORK | HMH72B241 | XAFB30CBAN1 | TM9E060A10MP12 | 15,000 | $750 |
| No | 211659683 | YORK | HMH72B241 | XAFB30CXXN1+TXV | TM9E060A10MP12 | 15,000 | $750 |
| No | 211659682 | YORK | HMH72B241 | XAHB30CBAN1 | TM9E060A10MP12 | 14,900 | $745 |
| No | 211659681 | YORK | HMH72B241 | XAHB30CXXN1+TXV | TM9E060A10MP12 | 14,900 | $745 |
| No | 211659680 | YORK | HMH72B241 | XAUB30CXXN1+TXV | TM9E060B12MP12 | 15,400 | $770 |
| No | 211659679 | YORK | HMH72B241 | XAFB30CBAN1 | TM9E060B12MP12 | 15,400 | $770 |
| No | 211659678 | YORK | HMH72B241 | XAFB30CXXN1+TXV | TM9E060B12MP12 | 15,400 | $770 |
| No | 211659677 | YORK | HMH72B241 | XAFC30CBAN1 | TM9E060B12MP12 | 15,400 | $770 |
| No | 211659676 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TM9E060B12MP12 | 15,400 | $770 |
| No | 211659675 | YORK | HMH72B241 | XAHB30CBAN1 | TM9E060B12MP12 | 15,100 | $755 |
| No | 211659674 | YORK | HMH72B241 | XAHB30CXXN1+TXV | TM9E060B12MP12 | 15,100 | $755 |
| No | 211659673 | YORK | HMH72B241 | XAHC30CBAN1 | TM9E060B12MP12 | 15,100 | $755 |
| No | 211659672 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TM9E060B12MP12 | 15,100 | $755 |
| No | 211659671 | YORK | HMH72B241 | XAUB30CXXN1+TXV | TM9E080B12MP12 | 15,700 | $785 |
| No | 211659670 | YORK | HMH72B241 | XAFB30CBAN1 | TM9E080B12MP12 | 15,700 | $785 |
| No | 211659669 | YORK | HMH72B241 | XAFB30CXXN1+TXV | TM9E080B12MP12 | 15,700 | $785 |
| No | 211659668 | YORK | HMH72B241 | XAFC30CBAN1 | TM9E080B12MP12 | 15,700 | $785 |
| No | 211659667 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TM9E080B12MP12 | 15,700 | $785 |
| No | 211659666 | YORK | HMH72B241 | XAHB30CBAN1 | TM9E080B12MP12 | 14,900 | $745 |
| No | 211659665 | YORK | HMH72B241 | XAHB30CXXN1+TXV | TM9E080B12MP12 | 14,900 | $745 |
| No | 211659664 | YORK | HMH72B241 | XAHC30CBAN1 | TM9E080B12MP12 | 14,900 | $745 |
| No | 211659663 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TM9E080B12MP12 | 14,900 | $745 |
| No | 211659662 | YORK | HMH72B241 | XAFC30CBAN1 | TM9E080C16MP12 | 14,900 | $745 |
| No | 211659661 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TM9E080C16MP12 | 14,900 | $745 |
| No | 211659660 | YORK | HMH72B241 | XAHC30CBAN1 | TM9E080C16MP12 | 14,600 | $730 |
| No | 211659659 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TM9E080C16MP12 | 14,600 | $730 |
| No | 211659658 | YORK | HMH72B241 | XAFC30CBAN1 | TM9E100C16MP12 | 15,000 | $750 |
| No | 211659657 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TM9E100C16MP12 | 15,000 | $750 |
| No | 211659656 | YORK | HMH72B241 | XAHC30CBAN1 | TM9E100C16MP12 | 14,700 | $735 |
| No | 211659655 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TM9E100C16MP12 | 14,700 | $735 |
| No | 211659654 | YORK | HMH72B241 | XAUB30CXXN1+TXV | TM9V040A10MP12 | 15,400 | $770 |
| No | 211659653 | YORK | HMH72B241 | XAFB30CBAN1 | TM9V040A10MP12 | 15,400 | $770 |
| No | 211659652 | YORK | HMH72B241 | XAFB30CXXN1+TXV | TM9V040A10MP12 | 15,400 | $770 |
| No | 211659651 | YORK | HMH72B241 | XAHB30CBAN1 | TM9V040A10MP12 | 15,100 | $755 |
| No | 211659650 | YORK | HMH72B241 | XAHB30CXXN1+TXV | TM9V040A10MP12 | 15,100 | $755 |
| No | 211659649 | YORK | HMH72B241 | XAUB30CXXN1+TXV | YP9C060B12MP13 | 15,100 | $755 |
| No | 211659648 | YORK | HMH72B241 | XAFB30CBAN1 | YP9C060B12MP13 | 15,100 | $755 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211659647 | YORK | HMH72B241 | XAUB30CXXN1+TXV | TP9C060B12MP13 | 15,100 | $755 |
| No | 211659646 | YORK | HMH72B241 | XAFB30CBAN1 | TP9C060B12MP13 | 15,100 | $755 |
| No | 211659645 | YORK | HMH72B241 | XAUB30CXXN1+TXV | TM9V060B12MP12 | 15,100 | $755 |
| No | 211659644 | YORK | HMH72B241 | XAFB30CBAN1 | TM9V060B12MP12 | 15,100 | $755 |
| No | 211659643 | YORK | HMH72B241 | XAFB30CXXN1+TXV | YP9C060B12MP13 | 15,100 | $755 |
| No | 211659642 | YORK | HMH72B241 | XAFB30CXXN1+TXV | TP9C060B12MP13 | 15,100 | $755 |
| No | 211659641 | YORK | HMH72B241 | XAFB30CXXN1+TXV | TM9V060B12MP12 | 15,100 | $755 |
| No | 211659640 | YORK | HMH72B241 | XAFC30CBAN1 | YP9C060B12MP13 | 15,100 | $755 |
| No | 211659639 | YORK | HMH72B241 | XAFC30CBAN1 | TP9C060B12MP13 | 15,100 | $755 |
| No | 211659638 | YORK | HMH72B241 | XAFC30CBAN1 | TM9V060B12MP12 | 15,100 | $755 |
| No | 211659637 | YORK | HMH72B241 | XAFC30CXXN1+TXV | YP9C060B12MP13 | 15,100 | $755 |
| No | 211659636 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TP9C060B12MP13 | 15,100 | $755 |
| No | 211659635 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TM9V060B12MP12 | 15,100 | $755 |
| No | 211659634 | YORK | HMH72B241 | XAHB30CBAN1 | YP9C060B12MP13 | 15,100 | $755 |
| No | 211659633 | YORK | HMH72B241 | XAHB30CBAN1 | TP9C060B12MP13 | 15,100 | $755 |
| No | 211659632 | YORK | HMH72B241 | XAHB30CBAN1 | TM9V060B12MP12 | 15,100 | $755 |
| No | 211659631 | YORK | HMH72B241 | XAHB30CXXN1+TXV | YP9C060B12MP13 | 15,100 | $755 |
| No | 211659630 | YORK | HMH72B241 | XAHB30CXXN1+TXV | TP9C060B12MP13 | 15,100 | $755 |
| No | 211659629 | YORK | HMH72B241 | XAHB30CXXN1+TXV | TM9V060B12MP12 | 15,100 | $755 |
| No | 211659628 | YORK | HMH72B241 | XAHC30CBAN1 | YP9C060B12MP13 | 15,000 | $750 |
| No | 211659627 | YORK | HMH72B241 | XAHC30CBAN1 | TP9C060B12MP13 | 15,000 | $750 |
| No | 211659626 | YORK | HMH72B241 | XAHC30CBAN1 | TM9V060B12MP12 | 15,000 | $750 |
| No | 211659625 | YORK | HMH72B241 | XAHC30CXXN1+TXV | YP9C060B12MP13 | 15,000 | $750 |
| No | 211659624 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TP9C060B12MP13 | 15,000 | $750 |
| No | 211659623 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TM9V060B12MP12 | 15,000 | $750 |
| No | 211659622 | YORK | HMH72B241 | XAUB30CXXN1+TXV | YP9C080B12MP13 | 15,300 | $765 |
| No | 211659621 | YORK | HMH72B241 | XAFB30CBAN1 | YP9C080B12MP13 | 15,300 | $765 |
| No | 211659620 | YORK | HMH72B241 | XAUB30CXXN1+TXV | TP9C080B12MP13 | 15,300 | $765 |
| No | 211659619 | YORK | HMH72B241 | XAFB30CBAN1 | TP9C080B12MP13 | 15,300 | $765 |
| No | 211659618 | YORK | HMH72B241 | XAUB30CXXN1+TXV | TM9V080B12MP12 | 15,300 | $765 |
| No | 211659617 | YORK | HMH72B241 | XAFB30CBAN1 | TM9V080B12MP12 | 15,300 | $765 |
| No | 211659616 | YORK | HMH72B241 | XAFB30CXXN1+TXV | YP9C080B12MP13 | 15,300 | $765 |
| No | 211659615 | YORK | HMH72B241 | XAFB30CXXN1+TXV | TP9C080B12MP13 | 15,300 | $765 |
| No | 211659614 | YORK | HMH72B241 | XAFB30CXXN1+TXV | TM9V080B12MP12 | 15,300 | $765 |
| No | 211659613 | YORK | HMH72B241 | XAFC30CBAN1 | YP9C080B12MP13 | 15,300 | $765 |
| No | 211659612 | YORK | HMH72B241 | XAFC30CBAN1 | TP9C080B12MP13 | 15,300 | $765 |
| No | 211659611 | YORK | HMH72B241 | XAFC30CBAN1 | TM9V080B12MP12 | 15,300 | $765 |
| No | 211659610 | YORK | HMH72B241 | XAFC30CXXN1+TXV | YP9C080B12MP13 | 15,300 | $765 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211659609 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TP9C080B12MP13 | 15,300 | $765 |
| No | 211659608 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TM9V080B12MP12 | 15,300 | $765 |
| No | 211659607 | YORK | HMH72B241 | XAHB30CBAN1 | YP9C080B12MP13 | 14,800 | $740 |
| No | 211659606 | YORK | HMH72B241 | XAHB30CBAN1 | TP9C080B12MP13 | 14,800 | $740 |
| No | 211659605 | YORK | HMH72B241 | XAHB30CBAN1 | TM9V080B12MP12 | 14,800 | $740 |
| No | 211659604 | YORK | HMH72B241 | XAHB30CXXN1+TXV | YP9C080B12MP13 | 14,800 | $740 |
| No | 211659603 | YORK | HMH72B241 | XAHB30CXXN1+TXV | TP9C080B12MP13 | 14,800 | $740 |
| No | 211659602 | YORK | HMH72B241 | XAHB30CXXN1+TXV | TM9V080B12MP12 | 14,800 | $740 |
| No | 211659601 | YORK | HMH72B241 | XAHC30CBAN1 | YP9C080B12MP13 | 15,000 | $750 |
| No | 211659600 | YORK | HMH72B241 | XAHC30CBAN1 | TP9C080B12MP13 | 15,000 | $750 |
| No | 211659599 | YORK | HMH72B241 | XAHC30CBAN1 | TM9V080B12MP12 | 15,000 | $750 |
| No | 211659598 | YORK | HMH72B241 | XAHC30CXXN1+TXV | YP9C080B12MP13 | 15,000 | $750 |
| No | 211659597 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 211659596 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 211659590 | YORK | HMH72B241 | XAUB30CXXN1+TXV | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211659589 | YORK | HMH72B241 | XAFB30CBAN1 | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211659588 | YORK | HMH72B241 | XAFB30CXXN1+TXV | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211659587 | YORK | HMH72B241 | XAFC30CBAN1 | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211659586 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TM9Y060B12MP11 | 15,400 | $770 |
| No | 211659585 | YORK | HMH72B241 | XAHB30CBAN1 | TM9Y060B12MP11 | 15,100 | $755 |
| No | 211659584 | YORK | HMH72B241 | XAHB30CXXN1+TXV | TM9Y060B12MP11 | 15,100 | $755 |
| No | 211659583 | YORK | HMH72B241 | XAHC30CBAN1 | TM9Y060B12MP11 | 14,800 | $740 |
| No | 211659582 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TM9Y060B12MP11 | 14,800 | $740 |
| No | 211659581 | YORK | HMH72B241 | XAUB30CXXN1+TXV | TM9Y080B12MP11 | 15,100 | $755 |
| No | 211659580 | YORK | HMH72B241 | XAFB30CBAN1 | TM9Y080B12MP11 | 15,100 | $755 |
| No | 211659579 | YORK | HMH72B241 | XAFB30CXXN1+TXV | TM9Y080B12MP11 | 15,100 | $755 |
| No | 211659578 | YORK | HMH72B241 | XAFC30CBAN1 | TM9Y080B12MP11 | 15,100 | $755 |
| No | 211659577 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TM9Y080B12MP11 | 15,100 | $755 |
| No | 211659576 | YORK | HMH72B241 | XAHB30CBAN1 | TM9Y080B12MP11 | 14,900 | $745 |
| No | 211659575 | YORK | HMH72B241 | XAHB30CXXN1+TXV | TM9Y080B12MP11 | 14,900 | $745 |
| No | 211659574 | YORK | HMH72B241 | XAHC30CBAN1 | TM9Y080B12MP11 | 14,900 | $745 |
| No | 211659573 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TM9Y080B12MP11 | 14,900 | $745 |
| No | 211659572 | YORK | HMH72B241 | XAFC30CBAN1 | TM9Y080C16MP11 | 15,200 | $760 |
| No | 211659571 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TM9Y080C16MP11 | 15,200 | $760 |
| No | 211659570 | YORK | HMH72B241 | JHETB24CBAS2N1 | | 15,000 | $750 |
| No | 211659569 | YORK | HMH72B241 | JHVTB24CBAC2N1 | | 15,000 | $750 |
| No | 211659568 | YORK | HMH72B241 | XAUB30CXXN1+JMET12BS2N1+TXV | | 15,100 | $755 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211659567 | YORK | HMH72B241 | XAFB30CBAN1+JMET12BS2N1 | | 15,100 | $755 |
| No | 211659566 | YORK | HMH72B241 | XAFB30CXXN1+JMET12BS2N1+TXV | | 15,100 | $755 |
| No | 211659565 | YORK | HMH72B241 | XAHB30CBAN1+JMET12BS2N1 | | 14,800 | $740 |
| No | 211659564 | YORK | HMH72B241 | XAHB30CXXN1+JMET12BS2N1+TXV | | 14,800 | $740 |
| No | 211659563 | YORK | HMH72B241 | XAUB30CXXN1+JMVT12BC2N1+TXV | | 14,900 | $745 |
| No | 211659562 | YORK | HMH72B241 | XAFB30CBAN1+JMVT12BC2N1 | | 14,900 | $745 |
| No | 211659561 | YORK | HMH72B241 | XAFB30CXXN1+JMVT12BC2N1+TXV | | 14,900 | $745 |
| No | 211659560 | YORK | HMH72B241 | XAHB30CBAN1+JMVT12BC2N1 | | 14,900 | $745 |
| No | 211659559 | YORK | HMH72B241 | XAHB30CXXN1+JMVT12BC2N1+TXV | | 14,900 | $745 |
| No | 211659558 | YORK | HMH72B241 | XAUB30CXXN1+TXV | TL8E060A12UH11 | 15,000 | $750 |
| No | 211659557 | YORK | HMH72B241 | XAFB30CBAN1 | TL8E060A12UH11 | 15,000 | $750 |
| No | 211659556 | YORK | HMH72B241 | XAFB30CXXN1+TXV | TL8E060A12UH11 | 15,000 | $750 |
| No | 211659555 | YORK | HMH72B241 | XAHB30CBAN1 | TL8E060A12UH11 | 14,700 | $735 |
| No | 211659554 | YORK | HMH72B241 | XAHB30CXXN1+TXV | TL8E060A12UH11 | 14,700 | $735 |
| No | 211659553 | YORK | HMH72B241 | XAFC30CBAN1 | TL8E080C16UH11 | 15,600 | $780 |
| No | 211659552 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TL8E080C16UH11 | 15,600 | $780 |
| No | 211659551 | YORK | HMH72B241 | XAHC30CBAN1 | TM9Y080C16MP11 | 14,900 | $745 |
| No | 211659550 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TM9Y080C16MP11 | 14,900 | $745 |
| No | 211659549 | YORK | HMH72B241 | XAFC30CBAN1 | TM9Y100C16MP11 | 15,200 | $760 |
| No | 211659548 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TM9Y100C16MP11 | 15,200 | $760 |
| No | 211659547 | YORK | HMH72B241 | XAHC30CBAN1 | TM9Y100C16MP11 | 14,800 | $740 |
| No | 211659546 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TM9Y100C16MP11 | 14,800 | $740 |
| No | 211659545 | YORK | HMH72B241 | XAHC30CBAN1 | TL8E080C16UH11 | 15,300 | $765 |
| No | 211659544 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TL8E080C16UH11 | 15,300 | $765 |
| No | 211659543 | YORK | HMH72B241 | XAUB30CXXN1+TXV | TL9E060B12UH11 | 15,100 | $755 |
| No | 211659542 | YORK | HMH72B241 | XAFB30CBAN1 | TL9E060B12UH11 | 15,100 | $755 |
| No | 211659541 | YORK | HMH72B241 | XAFB30CXXN1+TXV | TL9E060B12UH11 | 15,100 | $755 |
| No | 211659540 | YORK | HMH72B241 | XAFC30CBAN1 | TL9E060B12UH11 | 15,100 | $755 |
| No | 211659539 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TL9E060B12UH11 | 15,100 | $755 |
| No | 211659538 | YORK | HMH72B241 | XAHB30CBAN1 | TL9E060B12UH11 | 14,800 | $740 |
| No | 211659537 | YORK | HMH72B241 | XAHB30CXXN1+TXV | TL9E060B12UH11 | 14,800 | $740 |
| No | 211659536 | YORK | HMH72B241 | XAHC30CBAN1 | TL9E060B12UH11 | 14,800 | $740 |
| No | 211659535 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TL9E060B12UH11 | 14,800 | $740 |
| No | 211659534 | YORK | HMH72B241 | XAFC30CBAN1 | TL9E080C16UH11 | 15,700 | $785 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211659533 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TL9E080C16UH11 | 15,700 | $785 |
| No | 211659532 | YORK | HMH72B241 | XAHC30CBAN1 | TL9E080C16UH11 | 15,300 | $765 |
| No | 211659531 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TL9E080C16UH11 | 15,300 | $765 |
| No | 211659530 | YORK | HMH72B241 | XAUB30CXXN1+TXV | TMLE040A12MP11 | 15,000 | $750 |
| No | 211659529 | YORK | HMH72B241 | XAFB30CBAN1 | TMLE040A12MP11 | 15,000 | $750 |
| No | 211659528 | YORK | HMH72B241 | XAUB30CXXN1+TXV | TM8E040A12MP11 | 15,000 | $750 |
| No | 211659527 | YORK | HMH72B241 | XAFB30CBAN1 | TM8E040A12MP11 | 15,000 | $750 |
| No | 211659526 | YORK | HMH72B241 | XAFB30CXXN1+TXV | TMLE040A12MP11 | 15,000 | $750 |
| No | 211659525 | YORK | HMH72B241 | XAFB30CXXN1+TXV | TM8E040A12MP11 | 15,000 | $750 |
| No | 211659524 | YORK | HMH72B241 | XAHB30CBAN1 | TMLE040A12MP11 | 14,700 | $735 |
| No | 211659523 | YORK | HMH72B241 | XAHB30CBAN1 | TM8E040A12MP11 | 14,700 | $735 |
| No | 211659522 | YORK | HMH72B241 | XAHB30CXXN1+TXV | TMLE040A12MP11 | 14,700 | $735 |
| No | 211659521 | YORK | HMH72B241 | XAHB30CXXN1+TXV | TM8E040A12MP11 | 14,700 | $735 |
| No | 211659520 | YORK | HMH72B241 | XAUB30CXXN1+TXV | TMLE060A12MP11 | 15,000 | $750 |
| No | 211659519 | YORK | HMH72B241 | XAFB30CBAN1 | TMLE060A12MP11 | 15,000 | $750 |
| No | 211659518 | YORK | HMH72B241 | XAUB30CXXN1+TXV | TM8E060A12MP11 | 15,000 | $750 |
| No | 211659517 | YORK | HMH72B241 | XAFB30CBAN1 | TM8E060A12MP11 | 15,000 | $750 |
| No | 211659516 | YORK | HMH72B241 | XAFB30CXXN1+TXV | TMLE060A12MP11 | 15,000 | $750 |
| No | 211659515 | YORK | HMH72B241 | XAFB30CXXN1+TXV | TM8E060A12MP11 | 15,000 | $750 |
| No | 211659514 | YORK | HMH72B241 | XAHB30CBAN1 | TMLE060A12MP11 | 14,700 | $735 |
| No | 211659513 | YORK | HMH72B241 | XAHB30CBAN1 | TM8E060A12MP11 | 14,700 | $735 |
| No | 211659512 | YORK | HMH72B241 | XAHB30CXXN1+TXV | TMLE060A12MP11 | 14,700 | $735 |
| No | 211659511 | YORK | HMH72B241 | XAHB30CXXN1+TXV | TM8E060A12MP11 | 14,700 | $735 |
| No | 211659510 | YORK | HMH72B241 | XAUB30CXXN1+TXV | TMLE080B12MP11 | 15,100 | $755 |
| No | 211659509 | YORK | HMH72B241 | XAFB30CBAN1 | TMLE080B12MP11 | 15,100 | $755 |
| No | 211659508 | YORK | HMH72B241 | XAUB30CXXN1+TXV | TM8E080B12MP11 | 15,100 | $755 |
| No | 211659507 | YORK | HMH72B241 | XAFB30CBAN1 | TM8E080B12MP11 | 15,100 | $755 |
| No | 211659506 | YORK | HMH72B241 | XAFB30CXXN1+TXV | TMLE080B12MP11 | 15,100 | $755 |
| No | 211659505 | YORK | HMH72B241 | XAFB30CXXN1+TXV | TM8E080B12MP11 | 15,100 | $755 |
| No | 211659504 | YORK | HMH72B241 | XAFC30CBAN1 | TMLE080B12MP11 | 15,100 | $755 |
| No | 211659503 | YORK | HMH72B241 | XAFC30CBAN1 | TM8E080B12MP11 | 15,100 | $755 |
| No | 211659502 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TMLE080B12MP11 | 15,100 | $755 |
| No | 211659501 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TM8E080B12MP11 | 15,100 | $755 |
| No | 211659500 | YORK | HMH72B241 | XAHB30CBAN1 | TMLE080B12MP11 | 14,800 | $740 |
| No | 211659499 | YORK | HMH72B241 | XAHB30CBAN1 | TM8E080B12MP11 | 14,800 | $740 |
| No | 211659498 | YORK | HMH72B241 | XAHB30CXXN1+TXV | TMLE080B12MP11 | 14,800 | $740 |
| No | 211659497 | YORK | HMH72B241 | XAHB30CXXN1+TXV | TM8E080B12MP11 | 14,800 | $740 |
| No | 211659496 | YORK | HMH72B241 | XAHC30CBAN1 | TMLE080B12MP11 | 14,800 | $740 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211659495 | YORK | HMH72B241 | XAHC30CBAN1 | TM8E080B12MP11 | 14,800 | $740 |
| No | 211659494 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TMLE080B12MP11 | 14,800 | $740 |
| No | 211659493 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TM8E080B12MP11 | 14,800 | $740 |
| No | 211659492 | YORK | HMH72B241 | XAFC30CBAN1 | TMLE080C16MP11 | 15,500 | $775 |
| No | 211659491 | YORK | HMH72B241 | XAFC30CBAN1 | TM8E080C16MP11 | 15,500 | $775 |
| No | 211659490 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TMLE080C16MP11 | 15,500 | $775 |
| No | 211659489 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TM8E080C16MP11 | 15,500 | $775 |
| No | 211659488 | YORK | HMH72B241 | XAHC30CBAN1 | TMLE080C16MP11 | 14,700 | $735 |
| No | 211659487 | YORK | HMH72B241 | XAHC30CBAN1 | TM8E080C16MP11 | 14,700 | $735 |
| No | 211659486 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TMLE080C16MP11 | 14,700 | $735 |
| No | 211659485 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TM8E080C16MP11 | 14,700 | $735 |
| No | 211659484 | YORK | HMH72B241 | XAUB30CXXN1+TXV | TMLE100B12MP11 | 15,100 | $755 |
| No | 211659483 | YORK | HMH72B241 | XAFB30CBAN1 | TMLE100B12MP11 | 15,100 | $755 |
| No | 211659482 | YORK | HMH72B241 | XAUB30CXXN1+TXV | TM8E100B12MP11 | 15,100 | $755 |
| No | 211659481 | YORK | HMH72B241 | XAFB30CBAN1 | TM8E100B12MP11 | 15,100 | $755 |
| No | 211659480 | YORK | HMH72B241 | XAFB30CXXN1+TXV | TMLE100B12MP11 | 15,100 | $755 |
| No | 211659479 | YORK | HMH72B241 | XAFB30CXXN1+TXV | TM8E100B12MP11 | 15,100 | $755 |
| No | 211659478 | YORK | HMH72B241 | XAFC30CBAN1 | TMLE100B12MP11 | 14,800 | $740 |
| No | 211659477 | YORK | HMH72B241 | XAFC30CBAN1 | TM8E100B12MP11 | 14,800 | $740 |
| No | 211659476 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TMLE100B12MP11 | 14,800 | $740 |
| No | 211659475 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TM8E100B12MP11 | 14,800 | $740 |
| No | 211659474 | YORK | HMH72B241 | XAHB30CBAN1 | TMLE100B12MP11 | 14,800 | $740 |
| No | 211659473 | YORK | HMH72B241 | XAHB30CBAN1 | TM8E100B12MP11 | 14,800 | $740 |
| No | 211659472 | YORK | HMH72B241 | XAHB30CXXN1+TXV | TMLE100B12MP11 | 14,800 | $740 |
| No | 211659471 | YORK | HMH72B241 | XAHB30CXXN1+TXV | TM8E100B12MP11 | 14,800 | $740 |
| No | 211659470 | YORK | HMH72B241 | XAHC30CBAN1 | TMLE100B12MP11 | 14,800 | $740 |
| No | 211659469 | YORK | HMH72B241 | XAHC30CBAN1 | TM8E100B12MP11 | 14,800 | $740 |
| No | 211659468 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TMLE100B12MP11 | 14,800 | $740 |
| No | 211659467 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TM8E100B12MP11 | 14,800 | $740 |
| No | 211659466 | YORK | HMH72B241 | XAFC30CBAN1 | TMLE100C16MP11 | 15,000 | $750 |
| No | 211659465 | YORK | HMH72B241 | XAFC30CBAN1 | TM8E100C16MP11 | 15,000 | $750 |
| No | 211659464 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TMLE100C16MP11 | 15,000 | $750 |
| No | 211659463 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TM8E100C16MP11 | 15,000 | $750 |
| No | 211659462 | YORK | HMH72B241 | XAHC30CBAN1 | TMLE100C16MP11 | 14,700 | $735 |
| No | 211659461 | YORK | HMH72B241 | XAHC30CBAN1 | TM8E100C16MP11 | 14,700 | $735 |
| No | 211659460 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TMLE100C16MP11 | 14,700 | $735 |
| No | 211659459 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TM8E100C16MP11 | 14,700 | $735 |
| No | 211659458 | YORK | HMH72B241 | XAFC30CBAN1 | TMLE120C16MP11 | 15,000 | $750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211659457 | YORK | HMH72B241 | XAFC30CBAN1 | TM8E120C16MP11 | 15,000 | $750 |
| No | 211659456 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TMLE120C16MP11 | 15,000 | $750 |
| No | 211659455 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TM8E120C16MP11 | 15,000 | $750 |
| No | 211659454 | YORK | HMH72B241 | XAHC30CBAN1 | TMLE120C16MP11 | 15,300 | $765 |
| No | 211659453 | YORK | HMH72B241 | XAHC30CBAN1 | TM8E120C16MP11 | 15,300 | $765 |
| No | 211659452 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TMLE120C16MP11 | 15,300 | $765 |
| No | 211659451 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TM8E120C16MP11 | 15,300 | $765 |
| No | 211659450 | YORK | HMH72B241 | XAUB30CXXN1+TXV | YPLC080B12MP13 | 15,100 | $755 |
| No | 211659449 | YORK | HMH72B241 | XAFB30CBAN1 | YPLC080B12MP13 | 15,100 | $755 |
| No | 211659448 | YORK | HMH72B241 | XAUB30CXXN1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 211659447 | YORK | HMH72B241 | XAFB30CBAN1 | TPLC080B12MP13 | 15,100 | $755 |
| No | 211659446 | YORK | HMH72B241 | XAUB30CXXN1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 211659445 | YORK | HMH72B241 | XAFB30CBAN1 | TM8V080B12MP12 | 15,100 | $755 |
| No | 211659444 | YORK | HMH72B241 | XAFB30CXXN1+TXV | YPLC080B12MP13 | 15,100 | $755 |
| No | 211659443 | YORK | HMH72B241 | XAFB30CXXN1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 211659442 | YORK | HMH72B241 | XAFB30CXXN1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 211659441 | YORK | HMH72B241 | XAFC30CBAN1 | YPLC080B12MP13 | 15,100 | $755 |
| No | 211659440 | YORK | HMH72B241 | XAFC30CBAN1 | TPLC080B12MP13 | 15,100 | $755 |
| No | 211659439 | YORK | HMH72B241 | XAFC30CBAN1 | TM8V080B12MP12 | 15,100 | $755 |
| No | 211659438 | YORK | HMH72B241 | XAFC30CXXN1+TXV | YPLC080B12MP13 | 15,100 | $755 |
| No | 211659437 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 211659436 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 211659435 | YORK | HMH72B241 | XAHB30CBAN1 | YPLC080B12MP13 | 14,900 | $745 |
| No | 211659434 | YORK | HMH72B241 | XAHB30CBAN1 | TPLC080B12MP13 | 14,900 | $745 |
| No | 211659433 | YORK | HMH72B241 | XAHB30CBAN1 | TM8V080B12MP12 | 14,900 | $745 |
| No | 211659432 | YORK | HMH72B241 | XAHB30CXXN1+TXV | YPLC080B12MP13 | 14,900 | $745 |
| No | 211659431 | YORK | HMH72B241 | XAHB30CXXN1+TXV | TPLC080B12MP13 | 14,900 | $745 |
| No | 211659430 | YORK | HMH72B241 | XAHB30CXXN1+TXV | TM8V080B12MP12 | 14,900 | $745 |
| No | 211659429 | YORK | HMH72B241 | XAHC30CBAN1 | YPLC080B12MP13 | 14,800 | $740 |
| No | 211659428 | YORK | HMH72B241 | XAHC30CBAN1 | TPLC080B12MP13 | 14,800 | $740 |
| No | 211659427 | YORK | HMH72B241 | XAHC30CBAN1 | TM8V080B12MP12 | 14,800 | $740 |
| No | 211659426 | YORK | HMH72B241 | XAHC30CXXN1+TXV | YPLC080B12MP13 | 14,800 | $740 |
| No | 211659425 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TPLC080B12MP13 | 14,800 | $740 |
| No | 211659424 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TM8V080B12MP12 | 14,800 | $740 |
| No | 211659423 | YORK | HMH72B241 | XAUB30CXXN1+TXV | TM8Y060A12MP11 | 15,300 | $765 |
| No | 211659422 | YORK | HMH72B241 | XAFB30CBAN1 | TM8Y060A12MP11 | 15,300 | $765 |
| No | 211659421 | YORK | HMH72B241 | XAFB30CXXN1+TXV | TM8Y060A12MP11 | 15,300 | $765 |
| No | 211659420 | YORK | HMH72B241 | XAHB30CBAN1 | TM8Y060A12MP11 | 15,000 | $750 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211659419 | YORK | HMH72B241 | XAHB30CXXN1+TXV | TM8Y060A12MP11 | 15,000 | $750 |
| No | 211659418 | YORK | HMH72B241 | XAUB30CXXN1+TXV | TM8Y080B12MP11 | 15,300 | $765 |
| No | 211659417 | YORK | HMH72B241 | XAFB30CBAN1 | TM8Y080B12MP11 | 15,300 | $765 |
| No | 211659416 | YORK | HMH72B241 | XAFB30CXXN1+TXV | TM8Y080B12MP11 | 15,300 | $765 |
| No | 211659415 | YORK | HMH72B241 | XAFC30CBAN1 | TM8Y080B12MP11 | 15,300 | $765 |
| No | 211659414 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TM8Y080B12MP11 | 15,300 | $765 |
| No | 211659413 | YORK | HMH72B241 | XAHB30CBAN1 | TM8Y080B12MP11 | 15,000 | $750 |
| No | 211659412 | YORK | HMH72B241 | XAHB30CXXN1+TXV | TM8Y080B12MP11 | 15,000 | $750 |
| No | 211659411 | YORK | HMH72B241 | XAHC30CBAN1 | TM8Y080B12MP11 | 15,100 | $755 |
| No | 211659410 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TM8Y080B12MP11 | 15,100 | $755 |
| No | 211659408 | YORK | HMH72B241 | XAFC30CBAN1 | TM8Y100C16MP11 | 15,100 | $755 |
| No | 211659406 | YORK | HMH72B241 | XAFC30CXXN1+TXV | TM8Y100C16MP11 | 15,100 | $755 |
| No | 211659405 | YORK | HMH72B241 | XAHC30CBAN1 | TM8Y080C16MP11 | 14,800 | $740 |
| No | 211659404 | YORK | HMH72B241 | XAHC30CBAN1 | TM8Y100C16MP11 | 14,800 | $740 |
| No | 211659403 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TM8Y080C16MP11 | 14,800 | $740 |
| No | 211659402 | YORK | HMH72B241 | XAHC30CXXN1+TXV | TM8Y100C16MP11 | 14,800 | $740 |
| No | 211659401 | YORK | HMH72B241 | XAUB30CXXN1+TXV | TM9E026A08MP12 | 15,400 | $770 |
| No | 211659400 | YORK | HMH72B241 | XAFB30CBAN1 | TM9E026A08MP12 | 15,400 | $770 |
| No | 211659399 | YORK | HMH72B241 | XAFB30CXXN1+TXV | TM9E026A08MP12 | 15,400 | $770 |
| No | 211659398 | YORK | HMH72B241 | XAHB30CBAN1 | TM9E026A08MP12 | 15,100 | $755 |
| No | 211659397 | YORK | HMH72B241 | XAHB30CXXN1+TXV | TM9E026A08MP12 | 15,100 | $755 |
| No | 211659393 | YORK | HMH72B361 | XAUB30CXXN1+JMET12BS2N1+TXV | | 24,800 | $1,240 |
| No | 211659392 | YORK | HMH72B361 | XAFB30CXXN1+JMET12BS2N1+TXV | | 24,800 | $1,240 |
| No | 211659391 | YORK | HMH72B361 | XAHB30CXXN1+JMET12BS2N1+TXV | | 23,800 | $1,190 |
| No | 211659390 | YORK | HMH72B361 | XAUB30CXXN1+JMVT12BC2N1+TXV | | 24,600 | $1,230 |
| No | 211659389 | YORK | HMH72B361 | XAFB30CXXN1+JMVT12BC2N1+TXV | | 24,600 | $1,230 |
| No | 211659388 | YORK | HMH72B361 | XAHB30CXXN1+JMVT12BC2N1+TXV | | 24,200 | $1,210 |
| No | 211659387 | YORK | HMH72B361 | XAUB30CXXN1+TXV | TMLE040A12MP11 | 24,400 | $1,220 |
| No | 211659386 | YORK | HMH72B361 | XAUB30CXXN1+TXV | TM8E040A12MP11 | 24,400 | $1,220 |
| No | 211659385 | YORK | HMH72B361 | XAFB30CXXN1+TXV | TMLE040A12MP11 | 24,400 | $1,220 |
| No | 211659384 | YORK | HMH72B361 | XAFB30CXXN1+TXV | TM8E040A12MP11 | 24,400 | $1,220 |
| No | 211659383 | YORK | HMH72B361 | XAHB30CXXN1+TXV | TMLE040A12MP11 | 23,800 | $1,190 |
| No | 211659382 | YORK | HMH72B361 | XAHB30CXXN1+TXV | TM8E040A12MP11 | 23,800 | $1,190 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211659381 | YORK | HMH72B361 | XAUB30CXXN1+TXV | TL8E060A12UH11 | 24,400 | $1,220 |
| No | 211659380 | YORK | HMH72B361 | XAFB30CXXN1+TXV | TL8E060A12UH11 | 24,400 | $1,220 |
| No | 211659379 | YORK | HMH72B361 | XAHB30CXXN1+TXV | TL8E060A12UH11 | 24,000 | $1,200 |
| No | 211659378 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TL8E080C16UH11 | 25,200 | $1,260 |
| No | 211659377 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TL8E080C16UH11 | 24,800 | $1,240 |
| No | 211659376 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TL8E100C20UH11 | 24,400 | $1,220 |
| No | 211659375 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TL8E100C20UH11 | 24,000 | $1,200 |
| No | 211659374 | YORK | HMH72B361 | XAUB30CXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 211659373 | YORK | HMH72B361 | XAFB30CXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 211659372 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 211659371 | YORK | HMH72B361 | XAHB30CXXN1+TXV | TL9E060B12UH11 | 23,600 | $1,180 |
| No | 211659370 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 211659369 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TL9E080C16UH11 | 24,800 | $1,240 |
| No | 211659368 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TL9E080C16UH11 | 24,400 | $1,220 |
| No | 211659367 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TL9E100C20UH11 | 24,600 | $1,230 |
| No | 211659366 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TL9E100C20UH11 | 24,000 | $1,200 |
| No | 211659365 | YORK | HMH72B361 | XAUB30CXXN1+TXV | TMLE060A12MP11 | 24,400 | $1,220 |
| No | 211659364 | YORK | HMH72B361 | XAUB30CXXN1+TXV | TM8E060A12MP11 | 24,400 | $1,220 |
| No | 211659363 | YORK | HMH72B361 | XAFB30CXXN1+TXV | TMLE060A12MP11 | 24,400 | $1,220 |
| No | 211659362 | YORK | HMH72B361 | XAFB30CXXN1+TXV | TM8E060A12MP11 | 24,400 | $1,220 |
| No | 211659361 | YORK | HMH72B361 | XAHB30CXXN1+TXV | TMLE060A12MP11 | 24,000 | $1,200 |
| No | 211659360 | YORK | HMH72B361 | XAHB30CXXN1+TXV | TM8E060A12MP11 | 24,000 | $1,200 |
| No | 211659359 | YORK | HMH72B361 | XAUB30CXXN1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 211659358 | YORK | HMH72B361 | XAUB30CXXN1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 211659357 | YORK | HMH72B361 | XAFB30CXXN1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 211659356 | YORK | HMH72B361 | XAFB30CXXN1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 211659355 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 211659354 | YORK | HMH72B361 | XAFC30CXXN1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 211659353 | YORK | HMH72B361 | XAHB30CXXN1+TXV | TMLE080B12MP11 | 24,400 | $1,220 |
| No | 211659352 | YORK | HMH72B361 | XAHB30CXXN1+TXV | TM8E080B12MP11 | 24,400 | $1,220 |
| No | 211659351 | YORK | HMH72B361 | XAHC30CXXN1+TXV | TMLE080B12MP11 | 24,400 | $1,220 |
| No | 207356243 | YORK | HMH72B361 | XAFA30DXXN1+TXV | TMLE060A12MP11 | 25,400 | $1,270 |
| No | 207356241 | YORK | HMH72B361 | XAFA30DXXN1+TXV | TM8E060A12MP11 | 25,400 | $1,270 |
| No | 207356193 | YORK | HMH72B361 | XAFA30DXXN1+TXV | TM8Y060A12MP11 | 25,000 | $1,250 |
| No | 207355991 | YORK | HMH72B361 | XAFA30DXXN1+TXV | TL8E060A12UH11 | 25,400 | $1,270 |
| No | 207355980 | YORK | HMH72B361 | XAFA30DXXN1+TXV | TMLE040A12MP11 | 25,200 | $1,260 |
| No | 207355978 | YORK | HMH72B361 | XAFA30DXXN1+TXV | TM8E040A12MP11 | 25,200 | $1,260 |
| No | 211380224 | YORK | HMH72B341 | JHETC42FBCS2N1 | | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 211380222 | YORK | HMH72B341 | JHVTC42FBCC2N1 | | 25,000 | $1,250 |
| No | 211380219 | YORK | HMH72B341 | XAUC48FXXN1+JMET12CS2N1+TXV | | 25,400 | $1,270 |
| No | 211380216 | YORK | HMH72B341 | XAFC48FBCN1+JMET12CS2N1 | | 25,400 | $1,270 |
| No | 211380214 | YORK | HMH72B341 | XAFC48FXXN1+JMET12CS2N1+TXV | | 25,400 | $1,270 |
| No | 208500185 | YORK | HMH72B241 | XAHB36DXXN1+JMET08BS2N1+TXV | | 13,900 | $695 |
| No | 208500434 | YORK | HMH72B241 | XAUB36DXXN1+JMET08BS2N1+TXV | | 14,200 | $710 |
| No | 208613189 | YORK | HMH72B241 | XAFB36DBAN1+JMET08BS2N1 | | 14,200 | $710 |
| No | 208500432 | YORK | HMH72B241 | XAFB36DXXN1+JMET08BS2N1+TXV | | 14,200 | $710 |
| No | 208500337 | YORK | HMH72B241 | XAUB36DXXN1+JMET12BS2N1+TXV | | 14,200 | $710 |
| No | 208613157 | YORK | HMH72B241 | XAFB36DBAN1+JMET12BS2N1 | | 14,200 | $710 |
| No | 208500335 | YORK | HMH72B241 | XAFB36DXXN1+JMET12BS2N1+TXV | | 14,200 | $710 |
| No | 207430568 | YORK | HMH72B241 | XAFC36DXXN1+MVC12CN21+TXV | | 14,300 | $715 |
| No | 207356394 | YORK | HMH72B241 | XAFC36DXXN1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 208197569 | YORK | HMH72B241 | XAHC36DXXN1+TXV | YP9C060B12MP13 | 14,300 | $715 |
| No | 208197566 | YORK | HMH72B241 | XAHC36DXXN1+TXV | TP9C060B12MP13 | 14,300 | $715 |
| No | 208197563 | YORK | HMH72B241 | XAHC36DXXN1+TXV | TM9V060B12MP12 | 14,300 | $715 |
| No | 208500017 | YORK | HMH72B241 | XAHB36DXXN1+JMVT12BC2N1+TXV | | 13,900 | $695 |
| No | 207430578 | YORK | HMH72B241 | XAUB36DXXN1+ME08BN21+TXV | | 14,100 | $705 |
| No | 207430577 | YORK | HMH72B241 | XAFB36DXXN1+ME08BN21+TXV | | 14,100 | $705 |
| No | 207356410 | YORK | HMH72B241 | XAUB36DXXN1+TXV | TL8E060A12UH11 | 14,400 | $720 |
| No | 207356408 | YORK | HMH72B241 | XAFB36DXXN1+TXV | TL8E060A12UH11 | 14,400 | $720 |
| No | 207356011 | YORK | HMH72B241 | XAFA30DXXN1+TXV | TM9E060A10MP12 | 14,600 | $730 |
| No | 208197856 | YORK | HMH72B241 | XAHB36DXXN1+TXV | YP9C080B12MP13 | 14,200 | $710 |
| No | 208197854 | YORK | HMH72B241 | XAHB36DXXN1+TXV | TP9C080B12MP13 | 14,200 | $710 |
| No | 208197852 | YORK | HMH72B241 | XAHB36DXXN1+TXV | TM9V080B12MP12 | 14,200 | $710 |
| No | 207430570 | YORK | HMH72B241 | XAUB36DXXN1+MVC12BN21+TXV | | 14,300 | $715 |
| No | 207430569 | YORK | HMH72B241 | XAFB36DXXN1+MVC12BN21+TXV | | 14,300 | $715 |
| No | 207356269 | YORK | HMH72B241 | XAFA30DXXN1+TXV | TMLE040A12MP11 | 14,400 | $720 |
| No | 207356267 | YORK | HMH72B241 | XAFA30DXXN1+TXV | TM8E040A12MP11 | 14,400 | $720 |
| No | 207356401 | YORK | HMH72B241 | XAUB36DXXN1+TXV | TM8Y060A12MP11 | 14,200 | $710 |
| No | 207356399 | YORK | HMH72B241 | XAFB36DXXN1+TXV | TM8Y060A12MP11 | 14,200 | $710 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207356392 | YORK | HMH72B241 | XAUB36DXXN1+TXV | YP9C060B12MP13 | 14,600 | $730 |
| No | 207356391 | YORK | HMH72B241 | XAUB36DXXN1+TXV | TP9C060B12MP13 | 14,600 | $730 |
| No | 207356389 | YORK | HMH72B241 | XAUB36DXXN1+TXV | TM9V060B12MP12 | 14,600 | $730 |
| No | 207356387 | YORK | HMH72B241 | XAFB36DXXN1+TXV | YP9C060B12MP13 | 14,600 | $730 |
| No | 207356385 | YORK | HMH72B241 | XAFB36DXXN1+TXV | TP9C060B12MP13 | 14,600 | $730 |
| No | 207356384 | YORK | HMH72B241 | XAFB36DXXN1+TXV | TM9V060B12MP12 | 14,600 | $730 |
| No | 207355993 | YORK | HMH72B241 | XAFC36DXXN1+TXV | TM9Y060B12MP11 | 14,500 | $725 |
| No | 208613098 | YORK | HMH72B241 | JHETB30DBAS2N1 | | 14,600 | $730 |
| No | 208500025 | YORK | HMH72B241 | JHETB30DXXS2N1+TXV | | 14,600 | $730 |
| No | 208500182 | YORK | HMH72B241 | XAHB36DXXN1+JMET12BS2N1+TXV | | 13,900 | $695 |
| No | 208206690 | YORK | HMH72B241 | XAHB36DXXN1+ME08BN21+TXV | | 14,200 | $710 |
| No | 207356273 | YORK | HMH72B241 | XAUB36DXXN1+TXV | TL9E060B12UH11 | 14,500 | $725 |
| No | 207356271 | YORK | HMH72B241 | XAFB36DXXN1+TXV | TL9E060B12UH11 | 14,500 | $725 |
| No | 208197880 | YORK | HMH72B241 | XAHC36DXXN1+TXV | YPLC080B12MP13 | 14,100 | $705 |
| No | 208197877 | YORK | HMH72B241 | XAHC36DXXN1+TXV | TPLC080B12MP13 | 14,100 | $705 |
| No | 208197874 | YORK | HMH72B241 | XAHC36DXXN1+TXV | TM8V080B12MP12 | 14,100 | $705 |
| No | 207356257 | YORK | HMH72B241 | XAUB36DXXN1+TXV | TM9E060A10MP12 | 14,600 | $730 |
| No | 207356255 | YORK | HMH72B241 | XAFB36DXXN1+TXV | TM9E060A10MP12 | 14,600 | $730 |
| No | 208197849 | YORK | HMH72B241 | XAHC36DXXN1+TXV | YP9C080B12MP13 | 14,100 | $705 |
| No | 208197846 | YORK | HMH72B241 | XAHC36DXXN1+TXV | TP9C080B12MP13 | 14,100 | $705 |
| No | 208197843 | YORK | HMH72B241 | XAHC36DXXN1+TXV | TM9V080B12MP12 | 14,100 | $705 |
| No | 208613132 | YORK | HMH72B241 | JHETB36DBAS2N1 | | 14,300 | $715 |
| No | 208500187 | YORK | HMH72B241 | JHETB36DXXS2N1+TXV | | 14,300 | $715 |
| No | 208500023 | YORK | HMH72B241 | XAUB36DXXN1+JMVT12BC2N1+TXV | | 14,000 | $700 |
| No | 208613097 | YORK | HMH72B241 | XAFB36DBAN1+JMVT12BC2N1 | | 14,000 | $700 |
| No | 208500020 | YORK | HMH72B241 | XAFB36DXXN1+JMVT12BC2N1+TXV | | 14,000 | $700 |
| No | 207356108 | YORK | HMH72B241 | XAFC36DXXN1+TXV | TMLE100B12MP11 | 14,300 | $715 |
| No | 207356106 | YORK | HMH72B241 | XAFC36DXXN1+TXV | TM8E100B12MP11 | 14,300 | $715 |
| No | 208613215 | YORK | HMH72B241 | JHETC36DBAS2N1 | | 14,200 | $710 |
| No | 208500563 | YORK | HMH72B241 | JHETC36DXXS2N1+TXV | | 14,200 | $710 |
| No | 208206694 | YORK | HMH72B241 | XAHC36DXXN1+MVC12CN21+TXV | | 14,000 | $700 |
| No | 208197886 | YORK | HMH72B241 | XAHC36DXXN1+TXV | TMLE100B12MP11 | 14,000 | $700 |
| No | 208197883 | YORK | HMH72B241 | XAHC36DXXN1+TXV | TM8E100B12MP11 | 14,000 | $700 |
| No | 208197868 | YORK | HMH72B241 | XAHC36DXXN1+TXV | TM8Y080B12MP11 | 14,000 | $700 |
| No | 207356377 | YORK | HMH72B241 | XAUB36DXXN1+TXV | YP9C080B12MP13 | 14,400 | $720 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207356375 | YORK | HMH72B241 | XAUB36DXXN1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 207356373 | YORK | HMH72B241 | XAUB36DXXN1+TXV | TM9V080B12MP12 | 14,400 | $720 |
| No | 207356372 | YORK | HMH72B241 | XAFB36DXXN1+TXV | YP9C080B12MP13 | 14,400 | $720 |
| No | 207356370 | YORK | HMH72B241 | XAFB36DXXN1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 207356369 | YORK | HMH72B241 | XAFB36DXXN1+TXV | TM9V080B12MP12 | 14,400 | $720 |
| No | 207430571 | YORK | HMH72B241 | XAFC36DXXN1+ME12CN21+TXV | | 14,200 | $710 |
| No | 207356016 | YORK | HMH72B241 | XAFC36DXXN1+TXV | TL9E060B12UH11 | 14,500 | $725 |
| No | 207356266 | YORK | HMH72B241 | XAFA30DXXN1+TXV | TM8Y060A12MP11 | 14,700 | $735 |
| No | 207356007 | YORK | HMH72B241 | XAUB36DXXN1+TXV | TM9V040A10MP12 | 14,800 | $740 |
| No | 207356004 | YORK | HMH72B241 | XAFB36DXXN1+TXV | TM9V040A10MP12 | 14,800 | $740 |
| No | 207355997 | YORK | HMH72B241 | XAUB36DXXN1+TXV | TM9Y060B12MP11 | 14,500 | $725 |
| No | 207355995 | YORK | HMH72B241 | XAFB36DXXN1+TXV | TM9Y060B12MP11 | 14,500 | $725 |
| No | 207356018 | YORK | HMH72B241 | XAFA30DXXN1+TXV | TL8E060A12UH11 | 14,400 | $720 |
| No | 207356104 | YORK | HMH72B241 | XAUB36DXXN1+TXV | YPLC080B12MP13 | 14,400 | $720 |
| No | 207356102 | YORK | HMH72B241 | XAUB36DXXN1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 207356100 | YORK | HMH72B241 | XAUB36DXXN1+TXV | TM8V080B12MP12 | 14,400 | $720 |
| No | 207356099 | YORK | HMH72B241 | XAFB36DXXN1+TXV | YPLC080B12MP13 | 14,400 | $720 |
| No | 207356097 | YORK | HMH72B241 | XAFB36DXXN1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 207356095 | YORK | HMH72B241 | XAFB36DXXN1+TXV | TM8V080B12MP12 | 14,400 | $720 |
| No | 207356262 | YORK | HMH72B241 | XAUB36DXXN1+TXV | TM9E026A08MP12 | 14,800 | $740 |
| No | 207356260 | YORK | HMH72B241 | XAFB36DXXN1+TXV | TM9E026A08MP12 | 14,800 | $740 |
| No | 207356094 | YORK | HMH72B241 | XAFC36DXXN1+TXV | YP9C080B12MP13 | 14,400 | $720 |
| No | 207356092 | YORK | HMH72B241 | XAFC36DXXN1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 207356090 | YORK | HMH72B241 | XAFC36DXXN1+TXV | TM9V080B12MP12 | 14,400 | $720 |
| No | 208613214 | YORK | HMH72B241 | JHVTB36DBAC2N1 | | 14,000 | $700 |
| No | 208500561 | YORK | HMH72B241 | JHVTB36DXXC2N1+TXV | | 14,000 | $700 |
| No | 208613190 | YORK | HMH72B241 | JHVTC36DBAC2N1 | | 14,100 | $705 |
| No | 208500436 | YORK | HMH72B241 | JHVTC36DXXC2N1+TXV | | 14,100 | $705 |
| No | 207356407 | YORK | HMH72B241 | XAFC36DXXN1+TXV | YPLC080B12MP13 | 14,400 | $720 |
| No | 207356404 | YORK | HMH72B241 | XAFC36DXXN1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 207356402 | YORK | HMH72B241 | XAFC36DXXN1+TXV | TM8V080B12MP12 | 14,400 | $720 |
| No | 208206698 | YORK | HMH72B241 | XAHB36DXXN1+MVC12BN21+TXV | | 14,100 | $705 |
| No | 207356115 | YORK | HMH72B241 | XAUB36DXXN1+TXV | TMLE040A12MP11 | 14,500 | $725 |
| No | 207356113 | YORK | HMH72B241 | XAUB36DXXN1+TXV | TM8E040A12MP11 | 14,500 | $725 |
| No | 207356111 | YORK | HMH72B241 | XAFB36DXXN1+TXV | TMLE040A12MP11 | 14,500 | $725 |
| No | 207356110 | YORK | HMH72B241 | XAFB36DXXN1+TXV | TM8E040A12MP11 | 14,500 | $725 |
| No | 207356397 | YORK | HMH72B241 | XAUB36DXXN1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207356395 | YORK | HMH72B241 | XAFB36DXXN1+TXV | TM8Y080B12MP11 | 14,300 | $715 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207356382 | YORK | HMH72B241 | XAFC36DXXN1+TXV | YP9C060B12MP13 | 14,600 | $730 |
| No | 207356380 | YORK | HMH72B241 | XAFC36DXXN1+TXV | TP9C060B12MP13 | 14,600 | $730 |
| No | 207356378 | YORK | HMH72B241 | XAFC36DXXN1+TXV | TM9V060B12MP12 | 14,600 | $730 |
| No | 207356367 | YORK | HMH72B241 | XAUB36DXXN1+TXV | TM9Y080B12MP11 | 14,600 | $730 |
| No | 207356365 | YORK | HMH72B241 | XAFB36DXXN1+TXV | TM9Y080B12MP11 | 14,600 | $730 |
| No | 208613216 | YORK | HMH72B361 | XAFC36DBCN1+JMET16CS2N1 | | 24,200 | $1,210 |
| No | 208500566 | YORK | HMH72B361 | XAFC36DXXN1+JMET16CS2N1+TXV | | 24,200 | $1,210 |
| No | 208500440 | YORK | HMH72B361 | XAHC36DXXN1+JMET12CS2N1+TXV | | 24,200 | $1,210 |
| No | 208613158 | YORK | HMH72B361 | XAFC36DBCN1+JMET12CS2N1 | | 24,800 | $1,240 |
| No | 208500338 | YORK | HMH72B361 | XAFC36DXXN1+JMET12CS2N1+TXV | | 24,800 | $1,240 |
| No | 208500438 | YORK | HMH72B361 | XAHB36DXXN1+JMVT12BC2N1+TXV | | 24,200 | $1,210 |
| No | 208206704 | YORK | HMH72B361 | XAHB36DXXN1+ME12BN21+TXV | | 24,400 | $1,220 |
| No | 208206629 | YORK | HMH72B361 | XAHC36DXXN1+MVC12CN21+TXV | | 24,200 | $1,210 |
| No | 207355986 | YORK | HMH72B361 | XAUB36DXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 207355984 | YORK | HMH72B361 | XAFB36DXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 208197547 | YORK | HMH72B361 | XAHB36DXXN1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 208197544 | YORK | HMH72B361 | XAHB36DXXN1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 207356232 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TMLE080C16MP11 | 25,000 | $1,250 |
| No | 207356231 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TM8E080C16MP11 | 25,000 | $1,250 |
| No | 207356229 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TMLE120C16MP11 | 25,000 | $1,250 |
| No | 207356227 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TM8E120C16MP11 | 25,000 | $1,250 |
| No | 208197487 | YORK | HMH72B361 | XAHB36DXXN1+TXV | TM8Y080B12MP11 | 24,400 | $1,220 |
| No | 207356182 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TM8Y120C20MP11 | 24,600 | $1,230 |
| No | 208197780 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TM9E060B12MP12 | 24,200 | $1,210 |
| No | 208197774 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TM9E100C16MP12 | 24,600 | $1,230 |
| No | 207356166 | YORK | HMH72B361 | XAUB36DXXN1+TXV | YP9C080B12MP13 | 25,000 | $1,250 |
| No | 207356164 | YORK | HMH72B361 | XAUB36DXXN1+TXV | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 207356162 | YORK | HMH72B361 | XAUB36DXXN1+TXV | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 207356160 | YORK | HMH72B361 | XAFB36DXXN1+TXV | YP9C080B12MP13 | 25,000 | $1,250 |
| No | 207356159 | YORK | HMH72B361 | XAFB36DXXN1+TXV | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 207356157 | YORK | HMH72B361 | XAFB36DXXN1+TXV | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 207355902 | YORK | HMH72B361 | XAFC36DXXN1+TXV | YP9C100C20MP13 | 25,200 | $1,260 |
| No | 207355900 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TP9C100C20MP13 | 25,200 | $1,260 |
| No | 207355899 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TM9V100C20MP12 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208197737 | YORK | HMH72B361 | XAHB36DXXN1+TXV | TM9Y080B12MP11 | 24,400 | $1,220 |
| No | 208500193 | YORK | HMH72B361 | XAUB36DXXN1+JMVT12BC2N1+TXV | | 24,600 | $1,230 |
| No | 208613133 | YORK | HMH72B361 | XAFB36DBCN1+JMVT12BC2N1 | | 24,600 | $1,230 |
| No | 208500190 | YORK | HMH72B361 | XAFB36DXXN1+JMVT12BC2N1+TXV | | 24,600 | $1,230 |
| No | 207430567 | YORK | HMH72B361 | XAUB36DXXN1+ME12BN21+TXV | | 24,800 | $1,240 |
| No | 207430566 | YORK | HMH72B361 | XAFB36DXXN1+ME12BN21+TXV | | 24,800 | $1,240 |
| No | 207430563 | YORK | HMH72B361 | XAFC36DXXN1+MVC12CN21+TXV | | 24,600 | $1,230 |
| No | 208197832 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TL8E080C16UH11 | 24,400 | $1,220 |
| No | 207356250 | YORK | HMH72B361 | XAUB36DXXN1+TXV | TMLE040A12MP11 | 25,000 | $1,250 |
| No | 207356248 | YORK | HMH72B361 | XAUB36DXXN1+TXV | TM8E040A12MP11 | 25,000 | $1,250 |
| No | 207356246 | YORK | HMH72B361 | XAFB36DXXN1+TXV | TMLE040A12MP11 | 25,000 | $1,250 |
| No | 207356245 | YORK | HMH72B361 | XAFB36DXXN1+TXV | TM8E040A12MP11 | 25,000 | $1,250 |
| No | 208500730 | YORK | HMH72B361 | XAHC36DXXN1+JMVT16CC2N1+TXV | | 24,000 | $1,200 |
| No | 208206688 | YORK | HMH72B361 | XAHC36DXXN1+ME12CN21+TXV | | 24,400 | $1,220 |
| No | 208206702 | YORK | HMH72B361 | XAHC36DXXN1+MVC16CN21+TXV | | 24,400 | $1,220 |
| No | 208197557 | YORK | HMH72B361 | XAHB36DXXN1+TXV | TL9E060B12UH11 | 24,000 | $1,200 |
| No | 207355977 | YORK | HMH72B361 | XAUB36DXXN1+TXV | TMLE060A12MP11 | 25,200 | $1,260 |
| No | 207355975 | YORK | HMH72B361 | XAUB36DXXN1+TXV | TM8E060A12MP11 | 25,200 | $1,260 |
| No | 207355973 | YORK | HMH72B361 | XAFB36DXXN1+TXV | TMLE060A12MP11 | 25,200 | $1,260 |
| No | 207355972 | YORK | HMH72B361 | XAFB36DXXN1+TXV | TM8E060A12MP11 | 25,200 | $1,260 |
| No | 207355966 | YORK | HMH72B361 | XAUB36DXXN1+TXV | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 207355964 | YORK | HMH72B361 | XAUB36DXXN1+TXV | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 207355962 | YORK | HMH72B361 | XAFB36DXXN1+TXV | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 207355961 | YORK | HMH72B361 | XAFB36DXXN1+TXV | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 207356225 | YORK | HMH72B361 | XAUB36DXXN1+TXV | YPLC060A12MP13 | 25,400 | $1,270 |
| No | 207356223 | YORK | HMH72B361 | XAUB36DXXN1+TXV | TPLC060A12MP13 | 25,400 | $1,270 |
| No | 207356222 | YORK | HMH72B361 | XAUB36DXXN1+TXV | TMLV060A12MP12 | 25,400 | $1,270 |
| No | 207356220 | YORK | HMH72B361 | XAUB36DXXN1+TXV | TM8V060A12MP12 | 25,400 | $1,270 |
| No | 207356218 | YORK | HMH72B361 | XAFB36DXXN1+TXV | YPLC060A12MP13 | 25,400 | $1,270 |
| No | 207356216 | YORK | HMH72B361 | XAFB36DXXN1+TXV | TPLC060A12MP13 | 25,400 | $1,270 |
| No | 207356214 | YORK | HMH72B361 | XAFB36DXXN1+TXV | TMLV060A12MP12 | 25,400 | $1,270 |
| No | 207356212 | YORK | HMH72B361 | XAFB36DXXN1+TXV | TM8V060A12MP12 | 25,400 | $1,270 |
| No | 208197512 | YORK | HMH72B361 | XAHC36DXXN1+TXV | YPLC100C16MP13 | 24,600 | $1,230 |
| No | 208197509 | YORK | HMH72B361 | XAHC36DXXN1+TXV | YPLC080C16MP13 | 24,600 | $1,230 |
| No | 208197506 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TPLC100C16MP13 | 24,600 | $1,230 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208197503 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TPLC080C16MP13 | 24,600 | $1,230 |
| No | 208197499 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TMLV100C16MP12 | 24,600 | $1,230 |
| No | 208197496 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TM8V080C16MP12 | 24,600 | $1,230 |
| No | 208197494 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 207355935 | YORK | HMH72B361 | XAFA30DXXN1+TXV | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 208197541 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 208197538 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TM8E080B12MP11 | 24,600 | $1,230 |
| No | 208197810 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TMLE100C16MP11 | 24,600 | $1,230 |
| No | 208197807 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TM8E100C16MP11 | 24,600 | $1,230 |
| No | 207355941 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TM8Y080B12MP11 | 25,000 | $1,250 |
| No | 208197783 | YORK | HMH72B361 | XAHB36DXXN1+TXV | TM9E060B12MP12 | 24,200 | $1,210 |
| No | 207355919 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TM9E100C16MP12 | 25,000 | $1,250 |
| No | 208197462 | YORK | HMH72B361 | XAHC36DXXN1+TXV | YP9C060B12MP13 | 24,400 | $1,220 |
| No | 208197459 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 208197455 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 208197753 | YORK | HMH72B361 | XAHC36DXXN1+TXV | YP9C100C16MP13 | 24,600 | $1,230 |
| No | 208197750 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TP9C100C16MP13 | 24,600 | $1,230 |
| No | 208197747 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TM9V100C16MP12 | 24,600 | $1,230 |
| No | 207356141 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TM9Y080B12MP11 | 25,000 | $1,250 |
| No | 207355921 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TM9E080B12MP12 | 25,200 | $1,260 |
| No | 207355916 | YORK | HMH72B361 | XAUB36DXXN1+TXV | TM9V040A10MP12 | 24,600 | $1,230 |
| No | 207355915 | YORK | HMH72B361 | XAFB36DXXN1+TXV | TM9V040A10MP12 | 24,600 | $1,230 |
| No | 208197452 | YORK | HMH72B361 | XAHB36DXXN1+TXV | YP9C080B12MP13 | 24,400 | $1,220 |
| No | 208197449 | YORK | HMH72B361 | XAHB36DXXN1+TXV | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 208197446 | YORK | HMH72B361 | XAHB36DXXN1+TXV | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 207356144 | YORK | HMH72B361 | XAUB36DXXN1+TXV | TM9Y060B12MP11 | 25,000 | $1,250 |
| No | 207356142 | YORK | HMH72B361 | XAFB36DXXN1+TXV | TM9Y060B12MP11 | 25,000 | $1,250 |
| No | 207356139 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TM9Y080C16MP11 | 25,000 | $1,250 |
| No | 208613134 | YORK | HMH72B361 | JHETB36DBCS2N1 | | 25,000 | $1,250 |
| No | 208500199 | YORK | HMH72B361 | JHETB36DXXS2N1+TXV | | 25,000 | $1,250 |
| No | 207430564 | YORK | HMH72B361 | XAFC36DXXN1+ME16CN21+TXV | | 25,000 | $1,250 |
| No | 208197553 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TL9E060B12UH11 | 24,000 | $1,200 |
| No | 208197829 | YORK | HMH72B361 | XAHB36DXXN1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 208197826 | YORK | HMH72B361 | XAHB36DXXN1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 207355959 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TMLE100B12MP11 | 25,000 | $1,250 |
| No | 207355957 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TM8E100B12MP11 | 25,000 | $1,250 |
| No | 207355952 | YORK | HMH72B361 | XAUB36DXXN1+TXV | YPLC080B12MP13 | 25,000 | $1,250 |
| No | 207355949 | YORK | HMH72B361 | XAUB36DXXN1+TXV | TPLC080B12MP13 | 25,000 | $1,250 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207355947 | YORK | HMH72B361 | XAUB36DXXN1+TXV | TM8V080B12MP12 | 25,000 | $1,250 |
| No | 207355946 | YORK | HMH72B361 | XAFB36DXXN1+TXV | YPLC080B12MP13 | 25,000 | $1,250 |
| No | 207355944 | YORK | HMH72B361 | XAFB36DXXN1+TXV | TPLC080B12MP13 | 25,000 | $1,250 |
| No | 207355942 | YORK | HMH72B361 | XAFB36DXXN1+TXV | TM8V080B12MP12 | 25,000 | $1,250 |
| No | 207355933 | YORK | HMH72B361 | XAUB36DXXN1+TXV | TM9E060A10MP12 | 25,200 | $1,260 |
| No | 207355931 | YORK | HMH72B361 | XAFB36DXXN1+TXV | TM9E060A10MP12 | 25,200 | $1,260 |
| No | 208613217 | YORK | HMH72B361 | JHETC36DBCS2N1 | | 24,000 | $1,200 |
| No | 208500569 | YORK | HMH72B361 | JHETC36DXXS2N1+TXV | | 24,000 | $1,200 |
| No | 207430580 | YORK | HMH72B361 | XAUB36DXXN1+MVC12BN21+TXV | | 24,800 | $1,240 |
| No | 207430579 | YORK | HMH72B361 | XAFB36DXXN1+MVC12BN21+TXV | | 24,800 | $1,240 |
| No | 208197834 | YORK | HMH72B361 | XAHB36DXXN1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 208197550 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TL9E080C16UH11 | 24,600 | $1,230 |
| No | 207355970 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TMLE080B12MP11 | 25,200 | $1,260 |
| No | 207355968 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TM8E080B12MP11 | 25,200 | $1,260 |
| No | 208197471 | YORK | HMH72B361 | XAHB36DXXN1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 208197464 | YORK | HMH72B361 | XAHB36DXXN1+TXV | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 208197762 | YORK | HMH72B361 | XAHC36DXXN1+TXV | YP9C080B12MP13 | 24,600 | $1,230 |
| No | 208197759 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 208197756 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 207355897 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TM9Y060B12MP11 | 25,000 | $1,250 |
| No | 208197421 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TM9Y080C16MP11 | 24,600 | $1,230 |
| No | 208197528 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 208197525 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 208197522 | YORK | HMH72B361 | XAHB36DXXN1+TXV | YPLC080B12MP13 | 24,200 | $1,210 |
| No | 208197518 | YORK | HMH72B361 | XAHB36DXXN1+TXV | TPLC080B12MP13 | 24,200 | $1,210 |
| No | 208197515 | YORK | HMH72B361 | XAHB36DXXN1+TXV | TM8V080B12MP12 | 24,200 | $1,210 |
| No | 208197490 | YORK | HMH72B361 | XAHB36DXXN1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 208197484 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TM8Y080C16MP11 | 24,000 | $1,200 |
| No | 208197481 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TM8Y100C16MP11 | 24,000 | $1,200 |
| No | 207355929 | YORK | HMH72B361 | XAUB36DXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 207355928 | YORK | HMH72B361 | XAFB36DXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 208613099 | YORK | HMH72B361 | JHVTC36DBCC2N1 | | 24,400 | $1,220 |
| No | 208500029 | YORK | HMH72B361 | JHVTC36DXXC2N1+TXV | | 24,400 | $1,220 |
| No | 208206686 | YORK | HMH72B361 | XAHC36DXXN1+ME16CN21+TXV | | 24,600 | $1,230 |
| No | 207355989 | YORK | HMH72B361 | XAUB36DXXN1+TXV | TL8E060A12UH11 | 25,000 | $1,250 |
| No | 207355988 | YORK | HMH72B361 | XAFB36DXXN1+TXV | TL8E060A12UH11 | 25,000 | $1,250 |
| No | 207355983 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TL9E080C16UH11 | 25,000 | $1,250 |
| No | 207356239 | YORK | HMH72B361 | XAUB36DXXN1+TXV | TMLE080B12MP11 | 25,200 | $1,260 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207356237 | YORK | HMH72B361 | XAUB36DXXN1+TXV | TM8E080B12MP11 | 25,200 | $1,260 |
| No | 207356236 | YORK | HMH72B361 | XAFB36DXXN1+TXV | TMLE080B12MP11 | 25,200 | $1,260 |
| No | 207356234 | YORK | HMH72B361 | XAFB36DXXN1+TXV | TM8E080B12MP11 | 25,200 | $1,260 |
| No | 208613245 | YORK | HMH72B361 | XAFC36DBCN1+JMVT16CC2N1 | | 24,400 | $1,220 |
| No | 208500733 | YORK | HMH72B361 | XAFC36DXXN1+JMVT16CC2N1+TXV | | 24,400 | $1,220 |
| No | 207430565 | YORK | HMH72B361 | XAFC36DXXN1+ME12CN21+TXV | | 24,800 | $1,240 |
| No | 207430562 | YORK | HMH72B361 | XAFC36DXXN1+MVC16CN21+TXV | | 24,800 | $1,240 |
| No | 207356251 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TL9E060B12UH11 | 24,600 | $1,230 |
| No | 207356180 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TM9E080C16MP12 | 25,000 | $1,250 |
| No | 207355913 | YORK | HMH72B361 | XAFC36DXXN1+TXV | YP9C060B12MP13 | 24,800 | $1,240 |
| No | 207355911 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TP9C060B12MP13 | 24,800 | $1,240 |
| No | 207355910 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TM9V060B12MP12 | 24,800 | $1,240 |
| No | 208197443 | YORK | HMH72B361 | XAHC36DXXN1+TXV | YP9C080C16MP13 | 24,600 | $1,230 |
| No | 208197440 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TP9C080C16MP13 | 24,600 | $1,230 |
| No | 208197436 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TM9V080C16MP12 | 24,600 | $1,230 |
| No | 208197741 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TM9Y060B12MP11 | 24,400 | $1,220 |
| No | 208197416 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TM9Y100C16MP11 | 24,600 | $1,230 |
| No | 208197817 | YORK | HMH72B361 | XAHB36DXXN1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 208197814 | YORK | HMH72B361 | XAHB36DXXN1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 207356211 | YORK | HMH72B361 | XAFC36DXXN1+TXV | YPLC080B12MP13 | 25,000 | $1,250 |
| No | 207356209 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TPLC080B12MP13 | 25,000 | $1,250 |
| No | 207356207 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TM8V080B12MP12 | 25,000 | $1,250 |
| No | 207356191 | YORK | HMH72B361 | XAUB36DXXN1+TXV | TM8Y060A12MP11 | 24,800 | $1,240 |
| No | 207356189 | YORK | HMH72B361 | XAFB36DXXN1+TXV | TM8Y060A12MP11 | 24,800 | $1,240 |
| No | 207355939 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TM8Y080C16MP11 | 24,600 | $1,230 |
| No | 207356184 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TM8Y100C16MP11 | 24,600 | $1,230 |
| No | 208197475 | YORK | HMH72B361 | XAHB36DXXN1+TXV | TM9E060A10MP12 | 24,200 | $1,210 |
| No | 208197534 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TMLE080C16MP11 | 24,400 | $1,220 |
| No | 208197531 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TM8E080C16MP11 | 24,400 | $1,220 |
| No | 208197804 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TMLE120C16MP11 | 24,600 | $1,230 |
| No | 208197801 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TM8E120C16MP11 | 24,600 | $1,230 |
| No | 207356205 | YORK | HMH72B361 | XAFC36DXXN1+TXV | YPLC100C16MP13 | 25,200 | $1,260 |
| No | 207356203 | YORK | HMH72B361 | XAFC36DXXN1+TXV | YPLC080C16MP13 | 25,200 | $1,260 |
| No | 207356202 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TPLC100C16MP13 | 25,200 | $1,260 |
| No | 207356200 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TPLC080C16MP13 | 25,200 | $1,260 |
| No | 207356198 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TMLV100C16MP12 | 25,200 | $1,260 |
| No | 207356196 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TM8V080C16MP12 | 25,200 | $1,260 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207356194 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TM8V100C16MP12 | 25,200 | $1,260 |
| No | 208197789 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TM8Y080B12MP11 | 24,400 | $1,220 |
| No | 208197478 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TM8Y100C20MP11 | 24,200 | $1,210 |
| No | 208197786 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TM8Y120C20MP11 | 24,200 | $1,210 |
| No | 208500196 | YORK | HMH72B361 | XAHC36DXXN1+JMET16CS2N1+TXV | | 24,400 | $1,220 |
| No | 208613159 | YORK | HMH72B361 | JHVTB36DBCC2N1 | | 25,200 | $1,260 |
| No | 208500340 | YORK | HMH72B361 | JHVTB36DXXC2N1+TXV | | 25,200 | $1,260 |
| No | 208206673 | YORK | HMH72B361 | XAHB36DXXN1+MVC12BN21+TXV | | 24,400 | $1,220 |
| No | 207356253 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TL8E080C16UH11 | 25,000 | $1,250 |
| No | 208197777 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 207356176 | YORK | HMH72B361 | XAUB36DXXN1+TXV | YP9C060B12MP13 | 25,000 | $1,250 |
| No | 207356174 | YORK | HMH72B361 | XAUB36DXXN1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 207356173 | YORK | HMH72B361 | XAUB36DXXN1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 207356171 | YORK | HMH72B361 | XAFB36DXXN1+TXV | YP9C060B12MP13 | 25,000 | $1,250 |
| No | 207356169 | YORK | HMH72B361 | XAFB36DXXN1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 207356168 | YORK | HMH72B361 | XAFB36DXXN1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 207356155 | YORK | HMH72B361 | XAFC36DXXN1+TXV | YP9C080C16MP13 | 25,000 | $1,250 |
| No | 207356153 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TP9C080C16MP13 | 25,000 | $1,250 |
| No | 207356151 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TM9V080C16MP12 | 25,000 | $1,250 |
| No | 208197744 | YORK | HMH72B361 | XAHB36DXXN1+TXV | TM9Y060B12MP11 | 23,800 | $1,190 |
| No | 207356137 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TM9Y100C16MP11 | 25,000 | $1,250 |
| No | 207355924 | YORK | HMH72B361 | XAUB36DXXN1+TXV | TM9E080B12MP12 | 25,200 | $1,260 |
| No | 207355923 | YORK | HMH72B361 | XAFB36DXXN1+TXV | TM9E080B12MP12 | 25,200 | $1,260 |
| No | 207356178 | YORK | HMH72B361 | XAFA30DXXN1+TXV | TM9V040A10MP12 | 24,400 | $1,220 |
| No | 207355908 | YORK | HMH72B361 | XAFC36DXXN1+TXV | YP9C080B12MP13 | 25,000 | $1,250 |
| No | 207355906 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TP9C080B12MP13 | 25,000 | $1,250 |
| No | 207355904 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TM9V080B12MP12 | 25,000 | $1,250 |
| No | 208197433 | YORK | HMH72B361 | XAHC36DXXN1+TXV | YP9C100C20MP13 | 25,000 | $1,250 |
| No | 208197430 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TP9C100C20MP13 | 25,000 | $1,250 |
| No | 208197427 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TM9V100C20MP12 | 25,000 | $1,250 |
| No | 208197424 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TM9Y080B12MP11 | 24,400 | $1,220 |
| No | 208197823 | YORK | HMH72B361 | XAHB36DXXN1+TXV | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 208197820 | YORK | HMH72B361 | XAHB36DXXN1+TXV | TM8E080B12MP11 | 24,600 | $1,230 |
| No | 207355955 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TMLE100C16MP11 | 25,000 | $1,250 |
| No | 207355954 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TM8E100C16MP11 | 25,000 | $1,250 |
| No | 208197799 | YORK | HMH72B361 | XAHC36DXXN1+TXV | YPLC080B12MP13 | 24,600 | $1,230 |
| No | 208197796 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 208197792 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 207356187 | YORK | HMH72B361 | XAUB36DXXN1+TXV | TM8Y080B12MP11 | 25,000 | $1,250 |
| No | 207356185 | YORK | HMH72B361 | XAFB36DXXN1+TXV | TM8Y080B12MP11 | 25,000 | $1,250 |
| No | 207355937 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TM8Y100C20MP11 | 24,600 | $1,230 |
| No | 207355926 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 208197468 | YORK | HMH72B361 | XAHC36DXXN1+TXV | TM9E080C16MP12 | 24,600 | $1,230 |
| No | 208197771 | YORK | HMH72B361 | XAHB36DXXN1+TXV | YP9C060B12MP13 | 24,600 | $1,230 |
| No | 208197768 | YORK | HMH72B361 | XAHB36DXXN1+TXV | TP9C060B12MP13 | 24,600 | $1,230 |
| No | 208197765 | YORK | HMH72B361 | XAHB36DXXN1+TXV | TM9V060B12MP12 | 24,600 | $1,230 |
| No | 207356149 | YORK | HMH72B361 | XAFC36DXXN1+TXV | YP9C100C16MP13 | 25,000 | $1,250 |
| No | 207356148 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TP9C100C16MP13 | 25,000 | $1,250 |
| No | 207356146 | YORK | HMH72B361 | XAFC36DXXN1+TXV | TM9V100C16MP12 | 25,000 | $1,250 |
| No | 207355895 | YORK | HMH72B361 | XAUB36DXXN1+TXV | TM9Y080B12MP11 | 25,000 | $1,250 |
| No | 207355893 | YORK | HMH72B361 | XAFB36DXXN1+TXV | TM9Y080B12MP11 | 25,000 | $1,250 |
| No | 208197620 | YORK | HMH72B601 | XAHD60JXXN1+TXV | TL8E100C20UH11 | 35,800 | $1,790 |
| No | 208197942 | YORK | HMH72B601 | XAHD60JXXN1+TXV | TMLE100C16MP11 | 36,000 | $1,800 |
| No | 208197939 | YORK | HMH72B601 | XAHD60JXXN1+TXV | TM8E100C16MP11 | 36,000 | $1,800 |
| No | 208197924 | YORK | HMH72B601 | XAHD60JXXN1+TXV | TM9E080C20MP12 | 36,600 | $1,830 |
| No | 208197604 | YORK | HMH72B601 | XAHD60JXXN1+TXV | YP9C100C20MP13 | 36,200 | $1,810 |
| No | 208197601 | YORK | HMH72B601 | XAHD60JXXN1+TXV | TP9C100C20MP13 | 36,200 | $1,810 |
| No | 208197597 | YORK | HMH72B601 | XAHD60JXXN1+TXV | TM9V100C20MP12 | 36,200 | $1,810 |
| No | 208500201 | YORK | HMH72B601 | XAHD60JXXN1+JMET18DS2N1+TXV | | 35,800 | $1,790 |
| No | 208206710 | YORK | HMH72B601 | XAHD60JXXN1+MVC20DN21+TXV | | 36,800 | $1,840 |
| No | 208613100 | YORK | HMH72B601 | JHETD60JBCS2N1 | | 36,400 | $1,820 |
| No | 208500032 | YORK | HMH72B601 | JHETD60JXXS2N1+TXV | | 36,400 | $1,820 |
| No | 207430575 | YORK | HMH72B601 | XAFD60JXXN1+ME20DN21+TXV | | 37,200 | $1,860 |
| No | 208197954 | YORK | HMH72B601 | XAHD60JXXN1+TXV | TMLE080C16MP11 | 36,000 | $1,800 |
| No | 208197951 | YORK | HMH72B601 | XAHD60JXXN1+TXV | TM8E080C16MP11 | 36,000 | $1,800 |
| No | 208197936 | YORK | HMH72B601 | XAHD60JXXN1+TXV | TMLE120C16MP11 | 36,000 | $1,800 |
| No | 208197933 | YORK | HMH72B601 | XAHD60JXXN1+TXV | TM8E120C16MP11 | 36,000 | $1,800 |
| No | 208197918 | YORK | HMH72B601 | XAHD60JXXN1+TXV | TM9E120D20MP12 | 36,000 | $1,800 |
| No | 208197897 | YORK | HMH72B601 | XAHD60JXXN1+TXV | TM9Y100C20MP11 | 35,800 | $1,790 |
| No | 207356072 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TMLE100C20MP11 | 36,200 | $1,810 |
| No | 207356070 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TM8E100C20MP11 | 36,200 | $1,810 |
| No | 207356067 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TM8Y100C16MP11 | 36,600 | $1,830 |
| No | 207356346 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TM9E100C20MP12 | 37,000 | $1,850 |
| No | 207356331 | YORK | HMH72B601 | XAFD60JXXN1+TXV | YP9C120D20MP13 | 37,400 | $1,870 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207356329 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TP9C120D20MP13 | 37,400 | $1,870 |
| No | 207356328 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TM9V120D20MP12 | 37,400 | $1,870 |
| No | 208613246 | YORK | HMH72B601 | JHVTD60JBCC2N1 | | 36,200 | $1,810 |
| No | 208500739 | YORK | HMH72B601 | JHVTD60JXXC2N1+TXV | | 36,200 | $1,810 |
| No | 208206692 | YORK | HMH72B601 | XAHD60JXXN1+ME20DN21+TXV | | 36,600 | $1,830 |
| No | 208613218 | YORK | HMH72B601 | XAFD60JBCN1+JMVT20DC2N1 | | 36,000 | $1,800 |
| No | 208500572 | YORK | HMH72B601 | XAFD60JXXN1+JMVT20DC2N1+TXV | | 36,000 | $1,800 |
| No | 207356088 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TL8E080C16UH11 | 36,600 | $1,830 |
| No | 207356079 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TMLE080C20MP11 | 36,400 | $1,820 |
| No | 207356077 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TM8E080C20MP11 | 36,400 | $1,820 |
| No | 207356341 | YORK | HMH72B601 | XAFD60JXXN1+TXV | YP9C100C16MP13 | 36,800 | $1,840 |
| No | 207356340 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TP9C100C16MP13 | 36,800 | $1,840 |
| No | 207356338 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TM9V100C16MP12 | 36,800 | $1,840 |
| No | 208197956 | YORK | HMH72B601 | XAHD60JXXN1+TXV | TL9E100C20UH11 | 36,000 | $1,800 |
| No | 208197617 | YORK | HMH72B601 | XAHD60JXXN1+TXV | TMLE100C20MP11 | 35,600 | $1,780 |
| No | 208197614 | YORK | HMH72B601 | XAHD60JXXN1+TXV | TM8E100C20MP11 | 35,600 | $1,780 |
| No | 208197611 | YORK | HMH72B601 | XAHD60JXXN1+TXV | TM8Y080C16MP11 | 35,800 | $1,790 |
| No | 208197608 | YORK | HMH72B601 | XAHD60JXXN1+TXV | TM8Y100C16MP11 | 35,800 | $1,790 |
| No | 208197921 | YORK | HMH72B601 | XAHD60JXXN1+TXV | TM9E100C20MP12 | 36,400 | $1,820 |
| No | 208197906 | YORK | HMH72B601 | XAHD60JXXN1+TXV | YP9C120D20MP13 | 36,200 | $1,810 |
| No | 208197903 | YORK | HMH72B601 | XAHD60JXXN1+TXV | TP9C120D20MP13 | 36,200 | $1,810 |
| No | 208197900 | YORK | HMH72B601 | XAHD60JXXN1+TXV | TM9V120D20MP12 | 36,200 | $1,810 |
| No | 207356086 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TL8E100C20UH11 | 36,600 | $1,830 |
| No | 207356347 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TM9E080C20MP12 | 37,200 | $1,860 |
| No | 208613219 | YORK | HMH72B601 | XAFD60JBCN1+JMET18DS2N1 | | 36,400 | $1,820 |
| No | 208500574 | YORK | HMH72B601 | XAFD60JXXN1+JMET18DS2N1+TXV | | 36,400 | $1,820 |
| No | 207356085 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TL9E100C20UH11 | 36,600 | $1,830 |
| No | 207356069 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TM8Y080C16MP11 | 36,600 | $1,830 |
| No | 207356336 | YORK | HMH72B601 | XAFD60JXXN1+TXV | YP9C100C20MP13 | 36,800 | $1,840 |
| No | 207356335 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TP9C100C20MP13 | 36,800 | $1,840 |
| No | 207356333 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TM9V100C20MP12 | 36,800 | $1,840 |
| No | 207430572 | YORK | HMH72B601 | XAFD60JXXN1+MVC20DN21+TXV | | 37,200 | $1,860 |
| No | 208500736 | YORK | HMH72B601 | XAHD60JXXN1+JMVT20DC2N1+TXV | | 35,400 | $1,770 |
| No | 207356076 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TMLE100C16MP11 | 36,800 | $1,840 |
| No | 207356074 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TM8E100C16MP11 | 36,800 | $1,840 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207356063 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TM8Y120C20MP11 | 36,400 | $1,820 |
| No | 207356324 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TM9Y120D20MP11 | 36,600 | $1,830 |
| No | 208197959 | YORK | HMH72B601 | XAHD60JXXN1+TXV | TL8E080C16UH11 | 36,000 | $1,800 |
| No | 207356083 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TMLE080C16MP11 | 36,800 | $1,840 |
| No | 207356081 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TM8E080C16MP11 | 36,800 | $1,840 |
| No | 207356363 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TMLE120C16MP11 | 36,600 | $1,830 |
| No | 207356362 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TM8E120C16MP11 | 36,600 | $1,830 |
| No | 207356065 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TM8Y100C20MP11 | 36,400 | $1,820 |
| No | 207356343 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TM9E120D20MP12 | 37,200 | $1,860 |
| No | 207356326 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TM9Y100C20MP11 | 36,600 | $1,830 |
| No | 208197948 | YORK | HMH72B601 | XAHD60JXXN1+TXV | TMLE080C20MP11 | 35,600 | $1,780 |
| No | 208197945 | YORK | HMH72B601 | XAHD60JXXN1+TXV | TM8E080C20MP11 | 35,600 | $1,780 |
| No | 207356360 | YORK | HMH72B601 | XAFD60JXXN1+TXV | YPLC120C20MP13 | 37,400 | $1,870 |
| No | 207356358 | YORK | HMH72B601 | XAFD60JXXN1+TXV | YPLC100C20MP13 | 37,400 | $1,870 |
| No | 207356356 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TPLC120C20MP13 | 37,400 | $1,870 |
| No | 207356354 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TPLC100C20MP13 | 37,400 | $1,870 |
| No | 207356352 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TMLV120C20MP12 | 37,400 | $1,870 |
| No | 207356351 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TM8V100C20MP12 | 37,400 | $1,870 |
| No | 207356349 | YORK | HMH72B601 | XAFD60JXXN1+TXV | TM8V120C20MP12 | 37,400 | $1,870 |
| No | 208197930 | YORK | HMH72B601 | XAHD60JXXN1+TXV | TM8Y100C20MP11 | 35,600 | $1,780 |
| No | 208197927 | YORK | HMH72B601 | XAHD60JXXN1+TXV | TM8Y120C20MP11 | 35,600 | $1,780 |
| No | 208197915 | YORK | HMH72B601 | XAHD60JXXN1+TXV | YP9C100C16MP13 | 36,200 | $1,810 |
| No | 208197912 | YORK | HMH72B601 | XAHD60JXXN1+TXV | TP9C100C16MP13 | 36,200 | $1,810 |
| No | 208197909 | YORK | HMH72B601 | XAHD60JXXN1+TXV | TM9V100C16MP12 | 36,200 | $1,810 |
| No | 208197894 | YORK | HMH72B601 | XAHD60JXXN1+TXV | TM9Y120D20MP11 | 35,800 | $1,790 |
| No | 207430574 | YORK | HMH72B481 | XAFC60HXXN1+ME12CN21+TXV | | 29,200 | $1,460 |
| No | 208206701 | YORK | HMH72B481 | XAHC60HXXN1+MVC12CN21+TXV | | 28,600 | $1,430 |
| No | 208206714 | YORK | HMH72B481 | XAHC60HXXN1+ME12CN21+TXV | | 28,600 | $1,430 |
| No | 207430576 | YORK | HMH72B481 | XAFC60HXXN1+MVC12CN21+TXV | | 28,800 | $1,440 |
| No | 207356061 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TL8E100C20UH11 | 29,800 | $1,490 |
| No | 208613244 | YORK | HMH72B481 | JHETC60HBCS2N1 | | 29,600 | $1,480 |
| No | 208500727 | YORK | HMH72B481 | JHETC60HXXS2N1+TXV | | 29,600 | $1,480 |
| No | 207430573 | YORK | HMH72B481 | XAFD60JXXN1+ME14DN21+TXV | | 30,000 | $1,500 |
| No | 207356322 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TL8E080C16UH11 | 29,200 | $1,460 |
| No | 207356439 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TMLE080C16MP11 | 30,200 | $1,510 |
| No | 207356437 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TM8E080C16MP11 | 30,200 | $1,510 |
| No | 207356049 | YORK | HMH72B481 | XAFD60JXXN1+TXV | YPLC100C16MP13 | 29,600 | $1,480 |
| No | 207356048 | YORK | HMH72B481 | XAFD60JXXN1+TXV | YPLC080C16MP13 | 29,600 | $1,480 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207356046 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TPLC100C16MP13 | 29,600 | $1,480 |
| No | 207356044 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TPLC080C16MP13 | 29,600 | $1,480 |
| No | 207356042 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TMLV100C16MP12 | 29,600 | $1,480 |
| No | 207356039 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TM8V100C16MP12 | 29,600 | $1,480 |
| No | 207356125 | YORK | HMH72B481 | XAFD60JXXN1+TXV | YP9C100C20MP13 | 31,000 | $1,550 |
| No | 207356123 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TP9C100C20MP13 | 31,000 | $1,550 |
| No | 207356121 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TM9V100C20MP12 | 31,000 | $1,550 |
| No | 207356276 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TM9Y100C16MP11 | 30,200 | $1,510 |
| No | 207356128 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TM8Y100C20MP11 | 29,800 | $1,490 |
| No | 207356126 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TM8Y120C20MP11 | 29,800 | $1,490 |
| No | 208206708 | YORK | HMH72B481 | XAHD60JXXN1+ME14DN21+TXV |  | 28,800 | $1,440 |
| No | 207356131 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TL8E080C16UH11 | 30,200 | $1,510 |
| No | 208197725 | YORK | HMH72B481 | XAHD60JXXN1+TXV | TMLE080C16MP11 | 29,600 | $1,480 |
| No | 208197724 | YORK | HMH72B481 | XAHD60JXXN1+TXV | TM8E080C16MP11 | 29,600 | $1,480 |
| No | 207356133 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TM9Y100C16MP11 | 30,000 | $1,500 |
| No | 207356428 | YORK | HMH72B481 | XAFD60JXXN1+TXV | YPLC120C20MP13 | 29,800 | $1,490 |
| No | 207356426 | YORK | HMH72B481 | XAFD60JXXN1+TXV | YPLC100C20MP13 | 29,800 | $1,490 |
| No | 207356425 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TPLC120C20MP13 | 29,800 | $1,490 |
| No | 207356423 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TPLC100C20MP13 | 29,800 | $1,490 |
| No | 207356421 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TMLV120C20MP12 | 29,800 | $1,490 |
| No | 207356417 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TM8V120C20MP12 | 29,800 | $1,490 |
| No | 208613193 | YORK | HMH72B481 | JHVTD60JBCC2N1 |  | 29,800 | $1,490 |
| No | 208500445 | YORK | HMH72B481 | JHVTD60JXXC2N1+TXV |  | 29,800 | $1,490 |
| No | 207356060 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TMLE080C16MP11 | 30,000 | $1,500 |
| No | 207356058 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TM8E080C16MP11 | 30,000 | $1,500 |
| No | 207356041 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TM8V080C16MP12 | 29,600 | $1,480 |
| No | 208197692 | YORK | HMH72B481 | XAHD60JXXN1+TXV | YPLC120C20MP13 | 28,800 | $1,440 |
| No | 208197690 | YORK | HMH72B481 | XAHD60JXXN1+TXV | YPLC100C20MP13 | 28,800 | $1,440 |
| No | 208197688 | YORK | HMH72B481 | XAHD60JXXN1+TXV | TPLC120C20MP13 | 28,800 | $1,440 |
| No | 208197685 | YORK | HMH72B481 | XAHD60JXXN1+TXV | TPLC100C20MP13 | 28,800 | $1,440 |
| No | 208197682 | YORK | HMH72B481 | XAHD60JXXN1+TXV | TMLV120C20MP12 | 28,800 | $1,440 |
| No | 208197676 | YORK | HMH72B481 | XAHD60JXXN1+TXV | TM8V120C20MP12 | 28,800 | $1,440 |
| No | 208197648 | YORK | HMH72B481 | XAHD60JXXN1+TXV | YP9C100C16MP13 | 30,400 | $1,520 |
| No | 208197646 | YORK | HMH72B481 | XAHD60JXXN1+TXV | TP9C100C16MP13 | 30,400 | $1,520 |
| No | 208197642 | YORK | HMH72B481 | XAHD60JXXN1+TXV | TM9V100C16MP12 | 30,400 | $1,520 |
| No | 207356275 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TM9Y120D20MP11 | 30,600 | $1,530 |
| No | 208197718 | YORK | HMH72B481 | XAHD60JXXN1+TXV | TMLE120C16MP11 | 29,600 | $1,480 |
| No | 208197715 | YORK | HMH72B481 | XAHD60JXXN1+TXV | TM8E120C16MP11 | 29,600 | $1,480 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207356305 | YORK | HMH72B481 | XAFC60HXXN1+TXV | YPLC120C20MP13 | 29,200 | $1,460 |
| No | 207356303 | YORK | HMH72B481 | XAFC60HXXN1+TXV | YPLC100C20MP13 | 29,200 | $1,460 |
| No | 207356301 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TPLC120C20MP13 | 29,200 | $1,460 |
| No | 207356299 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TPLC100C20MP13 | 29,200 | $1,460 |
| No | 207356298 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TMLV120C20MP12 | 29,200 | $1,460 |
| No | 207356294 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TM8V120C20MP12 | 29,200 | $1,460 |
| No | 207356030 | YORK | HMH72B481 | XAFC60HXXN1+TXV | YP9C100C16MP13 | 30,800 | $1,540 |
| No | 207356028 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TP9C100C16MP13 | 30,800 | $1,540 |
| No | 207356027 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TM9V100C16MP12 | 30,800 | $1,540 |
| No | 207356019 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TM9Y080C16MP11 | 30,200 | $1,510 |
| No | 208206712 | YORK | HMH72B481 | XAHC60HXXN1+MVC16CN21+TXV | | 29,200 | $1,460 |
| No | 208613064 | YORK | HMH72B481 | JHVTC60HBCC2N1 | | 29,800 | $1,490 |
| No | 208499839 | YORK | HMH72B481 | JHVTC60HXXC2N1+TXV | | 29,800 | $1,490 |
| No | 207356319 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TL9E080C16UH11 | 29,600 | $1,480 |
| No | 208197679 | YORK | HMH72B481 | XAHD60JXXN1+TXV | TM8V100C20MP12 | 29,200 | $1,460 |
| No | 208197990 | YORK | HMH72B481 | XAHD60JXXN1+TXV | TM8Y080C16MP11 | 29,600 | $1,480 |
| No | 208197987 | YORK | HMH72B481 | XAHD60JXXN1+TXV | TM8Y100C16MP11 | 29,600 | $1,480 |
| No | 207356035 | YORK | HMH72B481 | XAFD60JXXN1+TXV | YP9C080C16MP13 | 30,600 | $1,530 |
| No | 207356034 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TP9C080C16MP13 | 30,600 | $1,530 |
| No | 207356032 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TM9V080C16MP12 | 30,600 | $1,530 |
| No | 208197968 | YORK | HMH72B481 | XAHD60JXXN1+TXV | YP9C120D20MP13 | 30,400 | $1,520 |
| No | 208197965 | YORK | HMH72B481 | XAHD60JXXN1+TXV | TP9C120D20MP13 | 30,400 | $1,520 |
| No | 208197962 | YORK | HMH72B481 | XAHD60JXXN1+TXV | TM9V120D20MP12 | 30,400 | $1,520 |
| No | 207356415 | YORK | HMH72B481 | XAFD60JXXN1+TXV | YP9C100C16MP13 | 31,000 | $1,550 |
| No | 207356414 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TP9C100C16MP13 | 31,000 | $1,550 |
| No | 207356412 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TM9V100C16MP12 | 31,000 | $1,550 |
| No | 207430583 | YORK | HMH72B481 | XAFC60HXXN1+ME16CN21+TXV | | 30,400 | $1,520 |
| No | 208198028 | YORK | HMH72B481 | XAHD60JXXN1+TXV | TL8E080C16UH11 | 29,600 | $1,480 |
| No | 207356056 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TMLE100C16MP11 | 30,000 | $1,500 |
| No | 207356055 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TM8E100C16MP11 | 30,000 | $1,500 |
| No | 207356317 | YORK | HMH72B481 | XAFC60HXXN1+TXV | YPLC100C16MP13 | 29,400 | $1,470 |
| No | 207356315 | YORK | HMH72B481 | XAFC60HXXN1+TXV | YPLC080C16MP13 | 29,400 | $1,470 |
| No | 207356314 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TPLC100C16MP13 | 29,400 | $1,470 |
| No | 207356312 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TPLC080C16MP13 | 29,400 | $1,470 |
| No | 207356310 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TMLV100C16MP12 | 29,400 | $1,470 |
| No | 207356308 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TM8V080C16MP12 | 29,400 | $1,470 |
| No | 207356307 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TM8V100C16MP12 | 29,400 | $1,470 |
| No | 207356285 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TM8Y100C20MP11 | 29,600 | $1,480 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207356283 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TM8Y120C20MP11 | 29,600 | $1,480 |
| No | 207356025 | YORK | HMH72B481 | XAFC60HXXN1+TXV | YP9C100C20MP13 | 31,000 | $1,550 |
| No | 207356023 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TP9C100C20MP13 | 31,000 | $1,550 |
| No | 207356021 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TM9V100C20MP12 | 31,000 | $1,550 |
| No | 208197623 | YORK | HMH72B481 | XAHD60JXXN1+TXV | TM9Y120D20MP11 | 30,000 | $1,500 |
| No | 207356436 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TMLE100C16MP11 | 30,200 | $1,510 |
| No | 207356434 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TM8E100C16MP11 | 30,200 | $1,510 |
| No | 207430582 | YORK | HMH72B481 | XAFD60JXXN1+MVC14DN21+TXV | | 29,800 | $1,490 |
| No | 207356130 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TL8E100C20UH11 | 30,000 | $1,500 |
| No | 207430581 | YORK | HMH72B481 | XAFC60HXXN1+MVC16CN21+TXV | | 29,800 | $1,490 |
| No | 207356432 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TMLE120C16MP11 | 30,200 | $1,510 |
| No | 207356430 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TM8E120C16MP11 | 30,200 | $1,510 |
| No | 208613194 | YORK | HMH72B481 | JHETD60JBCS2N1 | | 30,000 | $1,500 |
| No | 208500447 | YORK | HMH72B481 | JHETD60JXXS2N1+TXV | | 30,000 | $1,500 |
| No | 208206699 | YORK | HMH72B481 | XAHD60JXXN1+MVC14DN21+TXV | | 29,400 | $1,470 |
| No | 208197730 | YORK | HMH72B481 | XAHD60JXXN1+TXV | TL8E100C20UH11 | 29,400 | $1,470 |
| No | 208198022 | YORK | HMH72B481 | XAHD60JXXN1+TXV | TMLE100C16MP11 | 29,600 | $1,480 |
| No | 208198020 | YORK | HMH72B481 | XAHD60JXXN1+TXV | TM8E100C16MP11 | 29,600 | $1,480 |
| No | 207356296 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TM8V100C20MP12 | 29,600 | $1,480 |
| No | 207356292 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TM8Y080C16MP11 | 29,800 | $1,490 |
| No | 207356291 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TM8Y100C16MP11 | 29,800 | $1,490 |
| No | 208197667 | YORK | HMH72B481 | XAHD60JXXN1+TXV | TM8Y100C20MP11 | 29,200 | $1,460 |
| No | 208197665 | YORK | HMH72B481 | XAHD60JXXN1+TXV | TM8Y120C20MP11 | 29,200 | $1,460 |
| No | 208197639 | YORK | HMH72B481 | XAHD60JXXN1+TXV | YP9C100C20MP13 | 30,400 | $1,520 |
| No | 208197636 | YORK | HMH72B481 | XAHD60JXXN1+TXV | TP9C100C20MP13 | 30,400 | $1,520 |
| No | 208197633 | YORK | HMH72B481 | XAHD60JXXN1+TXV | TM9V100C20MP12 | 30,400 | $1,520 |
| No | 207356053 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TMLE120C16MP11 | 30,000 | $1,500 |
| No | 207356051 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TM8E120C16MP11 | 30,000 | $1,500 |
| No | 207356419 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TM8V100C20MP12 | 29,800 | $1,490 |
| No | 207356289 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TM8Y080C16MP11 | 30,200 | $1,510 |
| No | 207356287 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TM8Y100C16MP11 | 30,200 | $1,510 |
| No | 207356281 | YORK | HMH72B481 | XAFC60HXXN1+TXV | YP9C080C16MP13 | 30,600 | $1,530 |
| No | 207356280 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TP9C080C16MP13 | 30,600 | $1,530 |
| No | 207356278 | YORK | HMH72B481 | XAFC60HXXN1+TXV | TM9V080C16MP12 | 30,600 | $1,530 |
| No | 207356119 | YORK | HMH72B481 | XAFD60JXXN1+TXV | YP9C120D20MP13 | 30,800 | $1,540 |
| No | 207356117 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TP9C120D20MP13 | 30,800 | $1,540 |
| No | 207356116 | YORK | HMH72B481 | XAFD60JXXN1+TXV | TM9V120D20MP12 | 30,800 | $1,540 |
| No | 203994974 | YORK | YVAHP048B21S* | YIDM024B21S, YIDM024B21S | | 32,000 | $1,600 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203994968 | YORK | YVAHP048B21S* | YIC4012B21S, YIC4012B21S, YIC4012B21S, YIC4012B21S | | 32,000 | $1,600 |
| No | 203994964 | YORK | YVAHP060B21S* | YIC4012B21S, YIC4012B21S, YIC4012B21S, YIC4012B21S, YIC4012B21S | | 42,000 | $2,100 |
| No | 203995168 | YORK | YVAHP048B21S* | NULL | | 32,000 | $1,600 |
| No | 203994977 | YORK | YVAHP060B21S* | YIDM030B21S, YIDM030B21S | | 42,000 | $2,100 |
| No | 203995171 | YORK | YVAHP060B21S* | NULL | | 42,000 | $2,100 |
| No | 10524896 | YORK | YZV24B21 | CM25BE1A1 | YPLC080B12MP13 | 22,400 | $1,120 |
| No | 10524894 | YORK | YZV24B21 | CM25BE1A1 | YP9C060B12MP13 | 21,200 | $1,060 |
| No | 10524893 | YORK | YZV24B21 | CM25BE1A1 | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 10524891 | YORK | YZV24B21 | CM25BE1A1 | TP9C060B12MP13 | 21,200 | $1,060 |
| No | 10524890 | YORK | YZV24B21 | CM25BE1A1 | TMLV080B12MP12 | 22,400 | $1,120 |
| No | 10524892 | YORK | YZV24B21 | CM25BE1A1 | TP9C080B12MP13 | 22,400 | $1,120 |
| No | 10524888 | YORK | YZV24B21 | CM25BE1A1 | TM9V060B12MP12 | 21,200 | $1,060 |
| No | 10524887 | YORK | YZV24B21 | CM25BE1A1 | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 10309027 | YORK | YZV60B21 | CM61DE4A1+MVC20DN21 | | 45,500 | $2,275 |
| No | 9006269 | YORK | YHM60B21 | AE60DX21+TXV | | 33,200 | $1,660 |
| No | 10525209 | YORK | YZV48B21 | CM50CE3A1 | TM9V100C16MP12 | 44,000 | $2,200 |
| No | 10525216 | YORK | YZV48B21 | CM50CE3A1 | TP9C100C16MP13 | 44,000 | $2,200 |
| No | 10525223 | YORK | YZV48B21 | CM50CE3A1 | YP9C100C16MP13 | 44,000 | $2,200 |
| No | 10525808 | YORK | YZV24B21 | AVV25BE121 | | 22,400 | $1,120 |
| No | 10525809 | YORK | YZV60B21 | AVV61DE421 | | 46,000 | $2,300 |
| No | 10524889 | YORK | YZV24B21 | CM25BE1A1 | TM9V080B12MP12 | 22,400 | $1,120 |
| No | 10524895 | YORK | YZV24B21 | CM25BE1A1 | YP9C080B12MP13 | 22,400 | $1,120 |
| No | 201876867 | YORK | YZV36B21 | CM37BE2A1+CC | TM9V060B12MP12 | 31,600 | $1,580 |
| No | 201876870 | YORK | YZV36B21 | CM37BE2A1+CC | TP9C080B12MP13 | 31,000 | $1,550 |
| No | 201876868 | YORK | YZV36B21 | CM37BE2A1+CC | TM9V080B12MP12 | 31,000 | $1,550 |
| No | 201876871 | YORK | YZV36B21 | CM37BE2A1+CC | YP9C060B12MP13 | 31,600 | $1,580 |
| No | 201876869 | YORK | YZV36B21 | CM37BE2A1+CC | TP9C060B12MP13 | 31,600 | $1,580 |
| No | 201876872 | YORK | YZV36B21 | CM37BE2A1+CC | YP9C080B12MP13 | 31,000 | $1,550 |
| No | 202066910 | YORK | YZV36B21 | CM37BE2A1+MVC12BN21+CC | | 30,800 | $1,540 |
| No | 10309026 | YORK | YZV60B21 | AVV61CE421+CC | | 46,000 | $2,300 |
| No | 10525232 | YORK | YZV60B21 | CM61CE4A1+CC | TM8V100C20MP12 | 46,000 | $2,300 |
| No | 10525233 | YORK | YZV60B21 | CM61CE4A1+CC | TM8V120C20MP12 | 46,000 | $2,300 |
| No | 10525234 | YORK | YZV60B21 | CM61CE4A1+CC | TM9V100C20MP12 | 46,500 | $2,325 |
| No | 10525236 | YORK | YZV60B21 | CM61CE4A1+CC | TMLV120C20MP12 | 46,000 | $2,300 |
| No | 10525235 | YORK | YZV60B21 | CM61CE4A1+CC | TMLV100C20MP12 | 46,000 | $2,300 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 10525237 | YORK | YZV60B21 | CM61CE4A1+CC | TP9C100C20MP13 | 46,500 | $2,325 |
| No | 10525238 | YORK | YZV60B21 | CM61CE4A1+CC | TPLC100C20MP13 | 46,000 | $2,300 |
| No | 10525239 | YORK | YZV60B21 | CM61CE4A1+CC | TPLC120C20MP13 | 46,000 | $2,300 |
| No | 10525240 | YORK | YZV60B21 | CM61CE4A1+CC | YP9C100C20MP13 | 46,500 | $2,325 |
| No | 10525241 | YORK | YZV60B21 | CM61CE4A1+CC | YPLC100C20MP13 | 46,000 | $2,300 |
| No | 10525242 | YORK | YZV60B21 | CM61CE4A1+CC | YPLC120C20MP13 | 46,000 | $2,300 |
| No | 10525243 | YORK | YZV60B21 | CM61DE4A1+CC | TM9V120D20MP12 | 46,000 | $2,300 |
| No | 10525244 | YORK | YZV60B21 | CM61DE4A1+CC | TP9C120D20MP13 | 46,000 | $2,300 |
| No | 10525245 | YORK | YZV60B21 | CM61DE4A1+CC | YP9C120D20MP13 | 46,000 | $2,300 |
| No | 201876866 | YORK | YZV36B21 | AVV37BE221+CC | | 31,000 | $1,550 |
| No | 205535998 | YORK | YHM36B22 | CU36BXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203422930 | YORK | YHM36B22 | CM36BBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205536690 | YORK | YHM36B22 | CM36BXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203422929 | YORK | YHM36B22 | CF36BBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205536164 | YORK | YHM36B22 | CU36BXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203112440 | YORK | YHM36B22 | CM36BBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205536162 | YORK | YHM36B22 | CM36BXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203112438 | YORK | YHM36B22 | CF36BBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205536160 | YORK | YHM36B22 | CF36BXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205536158 | YORK | YHM36B22 | CF36BXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205537318 | YORK | YHM36B22 | CU36BXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 203112633 | YORK | YHM36B22 | CM36BBCA1 | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 203112631 | YORK | YHM36B22 | CF36BBCA1 | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205537315 | YORK | YHM36B22 | CF36BXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205537313 | YORK | YHM36B22 | CU36CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205537317 | YORK | YHM36B22 | CM36BXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 203112623 | YORK | YHM36B22 | CM36CBCA1 | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205537311 | YORK | YHM36B22 | CM36CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205537309 | YORK | YHM36B22 | CF36CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205537308 | YORK | YHM36B22 | CF42BXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205537306 | YORK | YHM36B22 | CM42DXA1+TXV | TL9E080C16UH11 | 22,400 | $1,120 |
| No | 205537302 | YORK | YHM36B22 | CU48CXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205537304 | YORK | YHM36B22 | CF42DXA1+TXV | TL9E080C16UH11 | 22,400 | $1,120 |
| No | 203112565 | YORK | YHM36B22 | CM48CBCA1 | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205537300 | YORK | YHM36B22 | CM48CXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 203112561 | YORK | YHM36B22 | CF48CBCA1 | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205537299 | YORK | YHM36B22 | CF48CXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 203112554 | YORK | YHM36B22 | CM48DBCA1 | TL9E080C16UH11 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205537297 | YORK | YHM36B22 | CU48DXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205537295 | YORK | YHM36B22 | CM48DXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205537294 | YORK | YHM36B22 | CF48DXA1+TXV | TL9E080C16UH11 | 22,200 | $1,110 |
| No | 205537292 | YORK | YHM36B22 | CM36AXA1+TXV | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 205537291 | YORK | YHM36B22 | CM36AXA1+TXV | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 205537287 | YORK | YHM36B22 | CF36AXA1+TXV | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 205537290 | YORK | YHM36B22 | CF36AXA1+TXV | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 206779194 | YORK | YHM36B22 | CU36BXA1+TXV | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 203422981 | YORK | YHM36B22 | CM36BBCA1 | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 206779197 | YORK | YHM36B22 | CM36BXA1+TXV | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 203422978 | YORK | YHM36B22 | CF36BBCA1 | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 206779196 | YORK | YHM36B22 | CU36BXA1+TXV | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 203112522 | YORK | YHM36B22 | CM36BBCA1 | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 206779195 | YORK | YHM36B22 | CM36BXA1+TXV | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 203112519 | YORK | YHM36B22 | CF36BBCA1 | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 206779193 | YORK | YHM36B22 | CF36BXA1+TXV | TMLE060A12MP11 | 22,400 | $1,120 |
| No | 206779192 | YORK | YHM36B22 | CF36BXA1+TXV | TM8E060A12MP11 | 22,400 | $1,120 |
| No | 205537286 | YORK | YHM36B22 | CF42BXA1+TXV | TMLE060A12MP11 | 22,800 | $1,140 |
| No | 205537284 | YORK | YHM36B22 | CF42BXA1+TXV | TM8E060A12MP11 | 22,800 | $1,140 |
| No | 206779191 | YORK | YHM36B22 | CU36BXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 203422972 | YORK | YHM36B22 | CM36BBCA1 | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 206779190 | YORK | YHM36B22 | CM36BXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 203422971 | YORK | YHM36B22 | CF36BBCA1 | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 206779189 | YORK | YHM36B22 | CU36BXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 203112504 | YORK | YHM36B22 | CM36BBCA1 | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 206779188 | YORK | YHM36B22 | CM36BXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 203112501 | YORK | YHM36B22 | CF36BBCA1 | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 206779185 | YORK | YHM36B22 | CF36BXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 206779184 | YORK | YHM36B22 | CF36BXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 206779183 | YORK | YHM36B22 | CU36CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203422953 | YORK | YHM36B22 | CM36CBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 206779187 | YORK | YHM36B22 | CM36CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 206779186 | YORK | YHM36B22 | CU36CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 203112462 | YORK | YHM36B22 | CM36CBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 206779182 | YORK | YHM36B22 | CM36CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 206779181 | YORK | YHM36B22 | CF36CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 206779180 | YORK | YHM36B22 | CF36CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205537283 | YORK | YHM36B22 | CU42CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203422949 | YORK | YHM36B22 | CM42CBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205537281 | YORK | YHM36B22 | CM42CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203422948 | YORK | YHM36B22 | CF42CBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205537279 | YORK | YHM36B22 | CU42CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 203112458 | YORK | YHM36B22 | CM42CBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205537276 | YORK | YHM36B22 | CM42CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 203112456 | YORK | YHM36B22 | CF42CBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205537273 | YORK | YHM36B22 | CF42CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205537271 | YORK | YHM36B22 | CF42CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 206779179 | YORK | YHM36B22 | CM42DXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 206779178 | YORK | YHM36B22 | CM42DXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 206779177 | YORK | YHM36B22 | CF42DXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 206779176 | YORK | YHM36B22 | CF42DXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205537269 | YORK | YHM36B22 | CU48CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203422939 | YORK | YHM36B22 | CM48CBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205537274 | YORK | YHM36B22 | CM48CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203422938 | YORK | YHM36B22 | CF48CBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205537268 | YORK | YHM36B22 | CU48CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205537265 | YORK | YHM36B22 | CM48CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 203112450 | YORK | YHM36B22 | CM48CBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205537263 | YORK | YHM36B22 | CF48CXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 203112448 | YORK | YHM36B22 | CF48CBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205537262 | YORK | YHM36B22 | CF48CXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 206779175 | YORK | YHM36B22 | CU42CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203422919 | YORK | YHM36B22 | CM42CBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 206779174 | YORK | YHM36B22 | CM42CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203422916 | YORK | YHM36B22 | CF42CBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 206779173 | YORK | YHM36B22 | CU42CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203112426 | YORK | YHM36B22 | CM42CBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 206779172 | YORK | YHM36B22 | CM42CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203112424 | YORK | YHM36B22 | CF42CBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 206779171 | YORK | YHM36B22 | CF42CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 206779170 | YORK | YHM36B22 | CF42CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205537260 | YORK | YHM36B22 | CU48CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203422914 | YORK | YHM36B22 | CM48CBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205537258 | YORK | YHM36B22 | CM48CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203422911 | YORK | YHM36B22 | CF48CBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205537256 | YORK | YHM36B22 | CU48CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203112420 | YORK | YHM36B22 | CM48CBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205537253 | YORK | YHM36B22 | CM48CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203112418 | YORK | YHM36B22 | CF48CBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205537248 | YORK | YHM36B22 | CF48CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205537247 | YORK | YHM36B22 | CF48CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205537245 | YORK | YHM36B22 | CU36CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 203422909 | YORK | YHM36B22 | CM36CBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205537251 | YORK | YHM36B22 | CM36CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 203112414 | YORK | YHM36B22 | CM36CBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205537250 | YORK | YHM36B22 | CU36CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205537242 | YORK | YHM36B22 | CM36CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205537241 | YORK | YHM36B22 | CF36CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205537239 | YORK | YHM36B22 | CF36CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205537237 | YORK | YHM36B22 | CU42CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 203422905 | YORK | YHM36B22 | CM42CBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205537236 | YORK | YHM36B22 | CM42CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 203422904 | YORK | YHM36B22 | CF42CBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205537232 | YORK | YHM36B22 | CU42CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203112410 | YORK | YHM36B22 | CM42CBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203112408 | YORK | YHM36B22 | CF42CBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205537231 | YORK | YHM36B22 | CM42CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205537220 | YORK | YHM36B22 | CF42CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205537218 | YORK | YHM36B22 | CF42CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 206779168 | YORK | YHM36B22 | CM42DXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206779166 | YORK | YHM36B22 | CF42DXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206779165 | YORK | YHM36B22 | CF42DXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206779167 | YORK | YHM36B22 | CM42DXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206779164 | YORK | YHM36B22 | CU48CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 203422882 | YORK | YHM36B22 | CM48CBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206779169 | YORK | YHM36B22 | CM48CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 203422879 | YORK | YHM36B22 | CF48CBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206779163 | YORK | YHM36B22 | CU48CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206779162 | YORK | YHM36B22 | CM48CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 203112378 | YORK | YHM36B22 | CF48CBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 203112379 | YORK | YHM36B22 | CM48CBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206779161 | YORK | YHM36B22 | CF48CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206779160 | YORK | YHM36B22 | CF48CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 203422877 | YORK | YHM36B22 | CM48DBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206779159 | YORK | YHM36B22 | CU48DXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206779158 | YORK | YHM36B22 | CM48DXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 203112374 | YORK | YHM36B22 | CM48DBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206779157 | YORK | YHM36B22 | CU48DXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206779156 | YORK | YHM36B22 | CM48DXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206779155 | YORK | YHM36B22 | CF48DXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206779154 | YORK | YHM36B22 | CF48DXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 205537216 | YORK | YHM36B22 | CM36AXA1+TXV | YPLC060A12MP13 | 22,400 | $1,120 |
| No | 205537213 | YORK | YHM36B22 | CM36AXA1+TXV | TPLC060A12MP13 | 22,400 | $1,120 |
| No | 205537212 | YORK | YHM36B22 | CM36AXA1+TXV | TMLV060A12MP12 | 22,400 | $1,120 |
| No | 205537204 | YORK | YHM36B22 | CF36AXA1+TXV | TPLC060A12MP13 | 22,400 | $1,120 |
| No | 205537207 | YORK | YHM36B22 | CF36AXA1+TXV | YPLC060A12MP13 | 22,400 | $1,120 |
| No | 205537210 | YORK | YHM36B22 | CM36AXA1+TXV | TM8V060A12MP12 | 22,400 | $1,120 |
| No | 205537200 | YORK | YHM36B22 | CF36AXA1+TXV | TM8V060A12MP12 | 22,400 | $1,120 |
| No | 205537202 | YORK | YHM36B22 | CF36AXA1+TXV | TMLV060A12MP12 | 22,400 | $1,120 |
| No | 205537198 | YORK | YHM36B22 | CM36AXA1+TXV | TM9E060A10MP12 | 22,600 | $1,130 |
| No | 205537196 | YORK | YHM36B22 | CF36AXA1+TXV | TM9E060A10MP12 | 22,600 | $1,130 |
| No | 206779153 | YORK | YHM36B22 | CF42BXA1+TXV | TM9E060B12MP12 | 22,200 | $1,110 |
| No | 205537195 | YORK | YHM36B22 | CU42CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 203112278 | YORK | YHM36B22 | CM42CBCA1 | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205537229 | YORK | YHM36B22 | CM42CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 203112276 | YORK | YHM36B22 | CF42CBCA1 | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205537226 | YORK | YHM36B22 | CF42CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 206779152 | YORK | YHM36B22 | CU48CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 206779151 | YORK | YHM36B22 | CM48CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 203112270 | YORK | YHM36B22 | CF48CBCA1 | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 203112272 | YORK | YHM36B22 | CM48CBCA1 | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 206779150 | YORK | YHM36B22 | CF48CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205537225 | YORK | YHM36B22 | CU36BXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203112266 | YORK | YHM36B22 | CM36BBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205537223 | YORK | YHM36B22 | CM36BXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203112264 | YORK | YHM36B22 | CF36BBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205537193 | YORK | YHM36B22 | CF36BXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205537191 | YORK | YHM36B22 | CU36CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 203112240 | YORK | YHM36B22 | CM36CBCA1 | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 205537187 | YORK | YHM36B22 | CM36CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 205537186 | YORK | YHM36B22 | CF36CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 206779149 | YORK | YHM36B22 | CU42CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203112236 | YORK | YHM36B22 | CM42CBCA1 | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 203112234 | YORK | YHM36B22 | CF42CBCA1 | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 206779148 | YORK | YHM36B22 | CM42CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 206779147 | YORK | YHM36B22 | CF42CXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 205537184 | YORK | YHM36B22 | CM42DXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 205537182 | YORK | YHM36B22 | CF42DXA1+TXV | TM9E080C16MP12 | 22,400 | $1,120 |
| No | 206779146 | YORK | YHM36B22 | CU48CXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 203112228 | YORK | YHM36B22 | CM48CBCA1 | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 206779145 | YORK | YHM36B22 | CM48CXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 203112226 | YORK | YHM36B22 | CF48CBCA1 | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 206779144 | YORK | YHM36B22 | CF48CXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 203112199 | YORK | YHM36B22 | CM48DBCA1 | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205537179 | YORK | YHM36B22 | CU48DXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205537177 | YORK | YHM36B22 | CM48DXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205537176 | YORK | YHM36B22 | CF48DXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 206779143 | YORK | YHM36B22 | CF42BXA1+TXV | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 203112175 | YORK | YHM36B22 | AE36CX21+TXV | | 22,600 | $1,130 |
| No | 205537170 | YORK | YHM36B22 | CM42DXA1+ME14DN21+TXV | | 22,000 | $1,100 |
| No | 205537168 | YORK | YHM36B22 | CF42DXA1+ME14DN21+TXV | | 22,000 | $1,100 |
| No | 205537166 | YORK | YHM36B22 | CM42DXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205537160 | YORK | YHM36B22 | CF42DXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205537156 | YORK | YHM36B22 | CU48CXA1+TXV | TM9Y080C16MP11 | 22,600 | $1,130 |
| No | 203112050 | YORK | YHM36B22 | CM48CBCA1 | TM9Y080C16MP11 | 22,600 | $1,130 |
| No | 205537189 | YORK | YHM36B22 | CM48CXA1+TXV | TM9Y080C16MP11 | 22,600 | $1,130 |
| No | 203112046 | YORK | YHM36B22 | CF48CBCA1 | TM9Y080C16MP11 | 22,600 | $1,130 |
| No | 205537155 | YORK | YHM36B22 | CF48CXA1+TXV | TM9Y080C16MP11 | 22,600 | $1,130 |
| No | 203112038 | YORK | YHM36B22 | CM48DBCA1 | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205537151 | YORK | YHM36B22 | CU48DXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205537148 | YORK | YHM36B22 | CM48DXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205537139 | YORK | YHM36B22 | CF48DXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205537135 | YORK | YHM36B22 | CM42DXA1+TXV | TM9Y120D20MP11 | 22,400 | $1,120 |
| No | 205537130 | YORK | YHM36B22 | CF42DXA1+TXV | TM9Y120D20MP11 | 22,400 | $1,120 |
| No | 205537127 | YORK | YHM36B22 | CM42DXA1+TXV | YPLC100C16MP13 | 22,200 | $1,110 |
| No | 205537125 | YORK | YHM36B22 | CM42DXA1+TXV | YPLC080C16MP13 | 22,200 | $1,110 |
| No | 205537122 | YORK | YHM36B22 | CM42DXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205537119 | YORK | YHM36B22 | CM42DXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205537117 | YORK | YHM36B22 | CM42DXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205537113 | YORK | YHM36B22 | CM42DXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205537111 | YORK | YHM36B22 | CM42DXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205537106 | YORK | YHM36B22 | CF42DXA1+TXV | YPLC080C16MP13 | 22,200 | $1,110 |
| No | 205537108 | YORK | YHM36B22 | CF42DXA1+TXV | YPLC100C16MP13 | 22,200 | $1,110 |
| No | 205537104 | YORK | YHM36B22 | CF42DXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205537102 | YORK | YHM36B22 | CF42DXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205537101 | YORK | YHM36B22 | CF42DXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205537095 | YORK | YHM36B22 | CF42DXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203111990 | YORK | YHM36B22 | AVC48CX21+TXV | | 22,400 | $1,120 |
| No | 205537097 | YORK | YHM36B22 | CF42DXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205537146 | YORK | YHM36B22 | CM48DXA1+ME14DN21+TXV | | 22,000 | $1,100 |
| No | 203111978 | YORK | YHM36B22 | CM48DBCA1+ME14DN21 | | 22,000 | $1,100 |
| No | 205537144 | YORK | YHM36B22 | CF48DXA1+ME14DN21+TXV | | 22,000 | $1,100 |
| No | 203111970 | YORK | YHM36B22 | CM36CBCA1+MVC16CN21 | | 22,000 | $1,100 |
| No | 205537094 | YORK | YHM36B22 | CM36CXA1+MVC16CN21+TXV | | 22,000 | $1,100 |
| No | 205537092 | YORK | YHM36B22 | CF36CXA1+MVC16CN21+TXV | | 22,000 | $1,100 |
| No | 203111966 | YORK | YHM36B22 | CM42CBCA1+MVC16CN21 | | 21,800 | $1,090 |
| No | 205537090 | YORK | YHM36B22 | CM42CXA1+MVC16CN21+TXV | | 21,800 | $1,090 |
| No | 203111964 | YORK | YHM36B22 | CF42CBCA1+MVC16CN21 | | 21,800 | $1,090 |
| No | 203111936 | YORK | YHM36B22 | CM36BBCA1 | YPLC060A12MP13 | 22,200 | $1,110 |
| No | 205537086 | YORK | YHM36B22 | CU36BXA1+TXV | YPLC060A12MP13 | 22,200 | $1,110 |
| No | 205537085 | YORK | YHM36B22 | CM36BXA1+TXV | YPLC060A12MP13 | 22,200 | $1,110 |
| No | 203111928 | YORK | YHM36B22 | CF36BBCA1 | YPLC060A12MP13 | 22,200 | $1,110 |
| No | 205537088 | YORK | YHM36B22 | CF42CXA1+MVC16CN21+TXV | | 21,800 | $1,090 |
| No | 205537083 | YORK | YHM36B22 | CU36BXA1+TXV | TPLC060A12MP13 | 22,200 | $1,110 |
| No | 203111934 | YORK | YHM36B22 | CM36BBCA1 | TPLC060A12MP13 | 22,200 | $1,110 |
| No | 205537081 | YORK | YHM36B22 | CM36BXA1+TXV | TPLC060A12MP13 | 22,200 | $1,110 |
| No | 203111926 | YORK | YHM36B22 | CF36BBCA1 | TPLC060A12MP13 | 22,200 | $1,110 |
| No | 205537079 | YORK | YHM36B22 | CU36BXA1+TXV | TMLV060A12MP12 | 22,200 | $1,110 |
| No | 203111932 | YORK | YHM36B22 | CM36BBCA1 | TMLV060A12MP12 | 22,200 | $1,110 |
| No | 205537077 | YORK | YHM36B22 | CM36BXA1+TXV | TMLV060A12MP12 | 22,200 | $1,110 |
| No | 203111924 | YORK | YHM36B22 | CF36BBCA1 | TMLV060A12MP12 | 22,200 | $1,110 |
| No | 205537076 | YORK | YHM36B22 | CU36BXA1+TXV | TM8V060A12MP12 | 22,200 | $1,110 |
| No | 203111930 | YORK | YHM36B22 | CM36BBCA1 | TM8V060A12MP12 | 22,200 | $1,110 |
| No | 205537073 | YORK | YHM36B22 | CM36BXA1+TXV | TM8V060A12MP12 | 22,200 | $1,110 |
| No | 205537064 | YORK | YHM36B22 | CF36BXA1+TXV | YPLC060A12MP13 | 22,200 | $1,110 |
| No | 203111922 | YORK | YHM36B22 | CF36BBCA1 | TM8V060A12MP12 | 22,200 | $1,110 |
| No | 205537061 | YORK | YHM36B22 | CF36BXA1+TXV | TMLV060A12MP12 | 22,200 | $1,110 |
| No | 205537060 | YORK | YHM36B22 | CF36BXA1+TXV | TM8V060A12MP12 | 22,200 | $1,110 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205537063 | YORK | YHM36B22 | CF36BXA1+TXV | TPLC060A12MP13 | 22,200 | $1,110 |
| No | 206779142 | YORK | YHM36B22 | CU36BXA1+TXV | YP9C060B12MP13 | 22,400 | $1,120 |
| No | 203111823 | YORK | YHM36B22 | CM36BBCA1 | YP9C060B12MP13 | 22,400 | $1,120 |
| No | 206779141 | YORK | YHM36B22 | CM36BXA1+TXV | YP9C060B12MP13 | 22,400 | $1,120 |
| No | 203111817 | YORK | YHM36B22 | CF36BBCA1 | YP9C060B12MP13 | 22,400 | $1,120 |
| No | 206779140 | YORK | YHM36B22 | CU36BXA1+TXV | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 203111821 | YORK | YHM36B22 | CM36BBCA1 | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 206779139 | YORK | YHM36B22 | CM36BXA1+TXV | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 203111815 | YORK | YHM36B22 | CF36BBCA1 | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 206779138 | YORK | YHM36B22 | CU36BXA1+TXV | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 203111818 | YORK | YHM36B22 | CM36BBCA1 | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 206779137 | YORK | YHM36B22 | CM36BXA1+TXV | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 203111813 | YORK | YHM36B22 | CF36BBCA1 | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 206779136 | YORK | YHM36B22 | CF36BXA1+TXV | YP9C060B12MP13 | 22,400 | $1,120 |
| No | 206779135 | YORK | YHM36B22 | CF36BXA1+TXV | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 206779134 | YORK | YHM36B22 | CF36BXA1+TXV | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 205537058 | YORK | YHM36B22 | CF42BXA1+TXV | YP9C060B12MP13 | 22,400 | $1,120 |
| No | 205537055 | YORK | YHM36B22 | CF42BXA1+TXV | TP9C060B12MP13 | 22,400 | $1,120 |
| No | 205537053 | YORK | YHM36B22 | CF42BXA1+TXV | TM9V060B12MP12 | 22,400 | $1,120 |
| No | 205537071 | YORK | YHM36B22 | CU48DXA1+TXV | YP9C080C16MP13 | 22,000 | $1,100 |
| No | 205537070 | YORK | YHM36B22 | CM48DXA1+TXV | YP9C080C16MP13 | 22,000 | $1,100 |
| No | 203111716 | YORK | YHM36B22 | CM48DBCA1 | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 203111718 | YORK | YHM36B22 | CM48DBCA1 | YP9C080C16MP13 | 22,000 | $1,100 |
| No | 205537066 | YORK | YHM36B22 | CM48DXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 205537067 | YORK | YHM36B22 | CU48DXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 203111714 | YORK | YHM36B22 | CM48DBCA1 | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 205537051 | YORK | YHM36B22 | CU48DXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 205537050 | YORK | YHM36B22 | CM48DXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 205537048 | YORK | YHM36B22 | CF48DXA1+TXV | YP9C080C16MP13 | 22,000 | $1,100 |
| No | 205537046 | YORK | YHM36B22 | CF48DXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 205537044 | YORK | YHM36B22 | CF48DXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 203111706 | YORK | YHM36B22 | AVC36BX21+TXV | | 22,200 | $1,110 |
| No | 203111704 | YORK | YHM36B22 | AVC36CX21+TXV | | 22,200 | $1,110 |
| No | 203111700 | YORK | YHM36B22 | AVC48DX21+TXV | | 22,200 | $1,110 |
| No | 205537042 | YORK | YHM36B22 | CU42CXA1+TXV | YPLC100C16MP13 | 22,200 | $1,110 |
| No | 203111582 | YORK | YHM36B22 | CM42CBCA1 | YPLC100C16MP13 | 22,200 | $1,110 |
| No | 205537040 | YORK | YHM36B22 | CM42CXA1+TXV | YPLC100C16MP13 | 22,200 | $1,110 |
| No | 203111566 | YORK | YHM36B22 | CF42CBCA1 | YPLC100C16MP13 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205537039 | YORK | YHM36B22 | CU42CXA1+TXV | YPLC080C16MP13 | 22,200 | $1,110 |
| No | 203111581 | YORK | YHM36B22 | CM42CBCA1 | YPLC080C16MP13 | 22,200 | $1,110 |
| No | 203111564 | YORK | YHM36B22 | CF42CBCA1 | YPLC080C16MP13 | 22,200 | $1,110 |
| No | 205537038 | YORK | YHM36B22 | CM42CXA1+TXV | YPLC080C16MP13 | 22,200 | $1,110 |
| No | 203111579 | YORK | YHM36B22 | CM42CBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205537036 | YORK | YHM36B22 | CU42CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205537033 | YORK | YHM36B22 | CM42CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203111562 | YORK | YHM36B22 | CF42CBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205537031 | YORK | YHM36B22 | CU42CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 203111576 | YORK | YHM36B22 | CM42CBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205537028 | YORK | YHM36B22 | CM42CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 203111560 | YORK | YHM36B22 | CF42CBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 203111575 | YORK | YHM36B22 | CM42CBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205537023 | YORK | YHM36B22 | CM42CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205537025 | YORK | YHM36B22 | CU42CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203111558 | YORK | YHM36B22 | CF42CBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205537018 | YORK | YHM36B22 | CU42CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203111570 | YORK | YHM36B22 | CM42CBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205537015 | YORK | YHM36B22 | CM42CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203111554 | YORK | YHM36B22 | CF42CBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205537013 | YORK | YHM36B22 | CU42CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203111568 | YORK | YHM36B22 | CM42CBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205537011 | YORK | YHM36B22 | CM42CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203111551 | YORK | YHM36B22 | CF42CBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205537002 | YORK | YHM36B22 | CF42CXA1+TXV | YPLC100C16MP13 | 22,200 | $1,110 |
| No | 205537000 | YORK | YHM36B22 | CF42CXA1+TXV | YPLC080C16MP13 | 22,200 | $1,110 |
| No | 205536999 | YORK | YHM36B22 | CF42CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205536997 | YORK | YHM36B22 | CF42CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205536995 | YORK | YHM36B22 | CF42CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205536993 | YORK | YHM36B22 | CF42CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205536991 | YORK | YHM36B22 | CF42CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 206779130 | YORK | YHM36B22 | CU48CXA1+TXV | YPLC100C16MP13 | 22,200 | $1,110 |
| No | 203111485 | YORK | YHM36B22 | CM48CBCA1 | YPLC100C16MP13 | 22,200 | $1,110 |
| No | 206779133 | YORK | YHM36B22 | CM48CXA1+TXV | YPLC100C16MP13 | 22,200 | $1,110 |
| No | 203111468 | YORK | YHM36B22 | CF48CBCA1 | YPLC100C16MP13 | 22,200 | $1,110 |
| No | 206779132 | YORK | YHM36B22 | CU48CXA1+TXV | YPLC080C16MP13 | 22,200 | $1,110 |
| No | 203111483 | YORK | YHM36B22 | CM48CBCA1 | YPLC080C16MP13 | 22,200 | $1,110 |
| No | 203111466 | YORK | YHM36B22 | CF48CBCA1 | YPLC080C16MP13 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206779131 | YORK | YHM36B22 | CM48CXA1+TXV | YPLC080C16MP13 | 22,200 | $1,110 |
| No | 206779129 | YORK | YHM36B22 | CU48CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203111480 | YORK | YHM36B22 | CM48CBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203111464 | YORK | YHM36B22 | CF48CBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 206779128 | YORK | YHM36B22 | CM48CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 206779127 | YORK | YHM36B22 | CU48CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 203111478 | YORK | YHM36B22 | CM48CBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 206779126 | YORK | YHM36B22 | CM48CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 203111462 | YORK | YHM36B22 | CF48CBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 206779125 | YORK | YHM36B22 | CU48CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203111476 | YORK | YHM36B22 | CM48CBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203111460 | YORK | YHM36B22 | CF48CBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 206779123 | YORK | YHM36B22 | CU48CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 206779124 | YORK | YHM36B22 | CM48CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203111471 | YORK | YHM36B22 | CM48CBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 206779122 | YORK | YHM36B22 | CM48CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203111455 | YORK | YHM36B22 | CF48CBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 206779121 | YORK | YHM36B22 | CU48CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203111470 | YORK | YHM36B22 | CM48CBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 206779120 | YORK | YHM36B22 | CM48CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203111453 | YORK | YHM36B22 | CF48CBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 206779117 | YORK | YHM36B22 | CF48CXA1+TXV | YPLC100C16MP13 | 22,200 | $1,110 |
| No | 206779116 | YORK | YHM36B22 | CF48CXA1+TXV | YPLC080C16MP13 | 22,200 | $1,110 |
| No | 206779115 | YORK | YHM36B22 | CF48CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 206779114 | YORK | YHM36B22 | CF48CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 206779113 | YORK | YHM36B22 | CF48CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 206779112 | YORK | YHM36B22 | CF48CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 206779111 | YORK | YHM36B22 | CF48CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 206779110 | YORK | YHM36B22 | CU48CXA1+TXV | YPLC120C20MP13 | 22,200 | $1,110 |
| No | 203111131 | YORK | YHM36B22 | CM48CBCA1 | YPLC120C20MP13 | 22,200 | $1,110 |
| No | 203111115 | YORK | YHM36B22 | CF48CBCA1 | YPLC120C20MP13 | 22,200 | $1,110 |
| No | 206779118 | YORK | YHM36B22 | CU48CXA1+TXV | YPLC100C20MP13 | 22,200 | $1,110 |
| No | 203111130 | YORK | YHM36B22 | CM48CBCA1 | YPLC100C20MP13 | 22,200 | $1,110 |
| No | 206779109 | YORK | YHM36B22 | CM48CXA1+TXV | YPLC100C20MP13 | 22,200 | $1,110 |
| No | 203111112 | YORK | YHM36B22 | CF48CBCA1 | YPLC100C20MP13 | 22,200 | $1,110 |
| No | 206779119 | YORK | YHM36B22 | CM48CXA1+TXV | YPLC120C20MP13 | 22,200 | $1,110 |
| No | 206779108 | YORK | YHM36B22 | CU48CXA1+TXV | TPLC120C20MP13 | 22,200 | $1,110 |
| No | 203111128 | YORK | YHM36B22 | CM48CBCA1 | TPLC120C20MP13 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206779107 | YORK | YHM36B22 | CM48CXA1+TXV | TPLC120C20MP13 | 22,200 | $1,110 |
| No | 203111110 | YORK | YHM36B22 | CF48CBCA1 | TPLC120C20MP13 | 22,200 | $1,110 |
| No | 206779106 | YORK | YHM36B22 | CU48CXA1+TXV | TPLC100C20MP13 | 22,200 | $1,110 |
| No | 203111125 | YORK | YHM36B22 | CM48CBCA1 | TPLC100C20MP13 | 22,200 | $1,110 |
| No | 206779105 | YORK | YHM36B22 | CM48CXA1+TXV | TPLC100C20MP13 | 22,200 | $1,110 |
| No | 203111108 | YORK | YHM36B22 | CF48CBCA1 | TPLC100C20MP13 | 22,200 | $1,110 |
| No | 206779104 | YORK | YHM36B22 | CU48CXA1+TXV | TMLV120C20MP12 | 22,200 | $1,110 |
| No | 203111123 | YORK | YHM36B22 | CM48CBCA1 | TMLV120C20MP12 | 22,200 | $1,110 |
| No | 206779103 | YORK | YHM36B22 | CM48CXA1+TXV | TMLV120C20MP12 | 22,200 | $1,110 |
| No | 203111106 | YORK | YHM36B22 | CF48CBCA1 | TMLV120C20MP12 | 22,200 | $1,110 |
| No | 206779102 | YORK | YHM36B22 | CU48CXA1+TXV | TM8V100C20MP12 | 22,200 | $1,110 |
| No | 203111119 | YORK | YHM36B22 | CM48CBCA1 | TM8V100C20MP12 | 22,200 | $1,110 |
| No | 206779101 | YORK | YHM36B22 | CM48CXA1+TXV | TM8V100C20MP12 | 22,200 | $1,110 |
| No | 203111102 | YORK | YHM36B22 | CF48CBCA1 | TM8V100C20MP12 | 22,200 | $1,110 |
| No | 206779100 | YORK | YHM36B22 | CU48CXA1+TXV | TM8V120C20MP12 | 22,200 | $1,110 |
| No | 203111117 | YORK | YHM36B22 | CM48CBCA1 | TM8V120C20MP12 | 22,200 | $1,110 |
| No | 206779099 | YORK | YHM36B22 | CM48CXA1+TXV | TM8V120C20MP12 | 22,200 | $1,110 |
| No | 203111100 | YORK | YHM36B22 | CF48CBCA1 | TM8V120C20MP12 | 22,200 | $1,110 |
| No | 206779097 | YORK | YHM36B22 | CF48CXA1+TXV | YPLC100C20MP13 | 22,200 | $1,110 |
| No | 206779098 | YORK | YHM36B22 | CF48CXA1+TXV | YPLC120C20MP13 | 22,200 | $1,110 |
| No | 206779096 | YORK | YHM36B22 | CF48CXA1+TXV | TPLC120C20MP13 | 22,200 | $1,110 |
| No | 206779095 | YORK | YHM36B22 | CF48CXA1+TXV | TPLC100C20MP13 | 22,200 | $1,110 |
| No | 206779094 | YORK | YHM36B22 | CF48CXA1+TXV | TMLV120C20MP12 | 22,200 | $1,110 |
| No | 206779093 | YORK | YHM36B22 | CF48CXA1+TXV | TM8V100C20MP12 | 22,200 | $1,110 |
| No | 206779092 | YORK | YHM36B22 | CF48CXA1+TXV | TM8V120C20MP12 | 22,200 | $1,110 |
| No | 203077642 | YORK | YHM36B22 | CM48DBCA1 | YPLC120C20MP13 | 22,400 | $1,120 |
| No | 205537009 | YORK | YHM36B22 | CU48DXA1+TXV | YPLC120C20MP13 | 22,400 | $1,120 |
| No | 205537007 | YORK | YHM36B22 | CM48DXA1+TXV | YPLC120C20MP13 | 22,400 | $1,120 |
| No | 203077637 | YORK | YHM36B22 | CM48DBCA1 | YPLC100C20MP13 | 22,400 | $1,120 |
| No | 205537004 | YORK | YHM36B22 | CM48DXA1+TXV | YPLC100C20MP13 | 22,400 | $1,120 |
| No | 203077633 | YORK | YHM36B22 | CM48DBCA1 | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205537006 | YORK | YHM36B22 | CU48DXA1+TXV | YPLC100C20MP13 | 22,400 | $1,120 |
| No | 205536990 | YORK | YHM36B22 | CU48DXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205536988 | YORK | YHM36B22 | CM48DXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 203077627 | YORK | YHM36B22 | CM48DBCA1 | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205536987 | YORK | YHM36B22 | CU48DXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205536985 | YORK | YHM36B22 | CM48DXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 203077624 | YORK | YHM36B22 | CM48DBCA1 | TMLV120C20MP12 | 22,400 | $1,120 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205536984 | YORK | YHM36B22 | CU48DXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205536982 | YORK | YHM36B22 | CM48DXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 203077615 | YORK | YHM36B22 | CM48DBCA1 | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205536974 | YORK | YHM36B22 | CU48DXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205536972 | YORK | YHM36B22 | CM48DXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 203077610 | YORK | YHM36B22 | CM48DBCA1 | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205536959 | YORK | YHM36B22 | CU48DXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205536956 | YORK | YHM36B22 | CF48DXA1+TXV | YPLC120C20MP13 | 22,400 | $1,120 |
| No | 205536958 | YORK | YHM36B22 | CM48DXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205536954 | YORK | YHM36B22 | CF48DXA1+TXV | YPLC100C20MP13 | 22,400 | $1,120 |
| No | 205536951 | YORK | YHM36B22 | CF48DXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205536950 | YORK | YHM36B22 | CF48DXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205536948 | YORK | YHM36B22 | CF48DXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205536944 | YORK | YHM36B22 | CF48DXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205536943 | YORK | YHM36B22 | CF48DXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205536941 | YORK | YHM36B22 | CM36AXA1+TXV | TM8Y060A12MP11 | 22,200 | $1,110 |
| No | 205536931 | YORK | YHM36B22 | CU36CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205536937 | YORK | YHM36B22 | CF36AXA1+TXV | TM8Y060A12MP11 | 22,200 | $1,110 |
| No | 203077514 | YORK | YHM36B22 | CM36CBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205536970 | YORK | YHM36B22 | CM36CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205536968 | YORK | YHM36B22 | CU36CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203077510 | YORK | YHM36B22 | CM36CBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205536967 | YORK | YHM36B22 | CM36CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205536918 | YORK | YHM36B22 | CF36CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205536916 | YORK | YHM36B22 | CF36CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203077348 | YORK | YHM36B22 | CM48CBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205536909 | YORK | YHM36B22 | CU48CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205536923 | YORK | YHM36B22 | CM48CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 203077320 | YORK | YHM36B22 | CF48CBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205536922 | YORK | YHM36B22 | CU48CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203077343 | YORK | YHM36B22 | CM48CBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205536907 | YORK | YHM36B22 | CM48CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203077314 | YORK | YHM36B22 | CF48CBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205536888 | YORK | YHM36B22 | CF48CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205536887 | YORK | YHM36B22 | CF48CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205536893 | YORK | YHM36B22 | CU48DXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 203077262 | YORK | YHM36B22 | CM48DBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205536890 | YORK | YHM36B22 | CM48DXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203077257 | YORK | YHM36B22 | CM48DBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205536877 | YORK | YHM36B22 | CU48DXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205536857 | YORK | YHM36B22 | CF48DXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205536876 | YORK | YHM36B22 | CM48DXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 206779090 | YORK | YHM36B22 | CU36BXA1+TXV | TM9Y080B12MP11 | 22,200 | $1,110 |
| No | 205536856 | YORK | YHM36B22 | CF48DXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203808676 | YORK | YHM36B22 | CM36BBCA1 | TM9Y080B12MP11 | 22,200 | $1,110 |
| No | 203808669 | YORK | YHM36B22 | CF36BBCA1 | TM9Y080B12MP11 | 22,200 | $1,110 |
| No | 206779091 | YORK | YHM36B22 | CM36BXA1+TXV | TM9Y080B12MP11 | 22,200 | $1,110 |
| No | 206779089 | YORK | YHM36B22 | CF36BXA1+TXV | TM9Y080B12MP11 | 22,200 | $1,110 |
| No | 205536848 | YORK | YHM36B22 | CU42CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205536847 | YORK | YHM36B22 | CM42CBCA1 | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205536845 | YORK | YHM36B22 | CM42CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205536844 | YORK | YHM36B22 | CF42CBCA1 | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205536828 | YORK | YHM36B22 | CF42CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205536824 | YORK | YHM36B22 | CM42DXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205536820 | YORK | YHM36B22 | CF42DXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 206779078 | YORK | YHM36B22 | CU36BXA1+TXV | YP9C080B12MP13 | 22,200 | $1,110 |
| No | 203077046 | YORK | YHM36B22 | CM36BBCA1 | YP9C080B12MP13 | 22,200 | $1,110 |
| No | 206779088 | YORK | YHM36B22 | CM36BXA1+TXV | YP9C080B12MP13 | 22,200 | $1,110 |
| No | 203077032 | YORK | YHM36B22 | CF36BBCA1 | YP9C080B12MP13 | 22,200 | $1,110 |
| No | 206779087 | YORK | YHM36B22 | CU36BXA1+TXV | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 203077042 | YORK | YHM36B22 | CM36BBCA1 | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 206779086 | YORK | YHM36B22 | CM36BXA1+TXV | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 203077026 | YORK | YHM36B22 | CF36BBCA1 | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 203077037 | YORK | YHM36B22 | CM36BBCA1 | TM9V080B12MP12 | 22,200 | $1,110 |
| No | 206779077 | YORK | YHM36B22 | CU36BXA1+TXV | TM9V080B12MP12 | 22,200 | $1,110 |
| No | 206779076 | YORK | YHM36B22 | CM36BXA1+TXV | TM9V080B12MP12 | 22,200 | $1,110 |
| No | 203077021 | YORK | YHM36B22 | CF36BBCA1 | TM9V080B12MP12 | 22,200 | $1,110 |
| No | 206779075 | YORK | YHM36B22 | CF36BXA1+TXV | YP9C080B12MP13 | 22,200 | $1,110 |
| No | 206779074 | YORK | YHM36B22 | CF36BXA1+TXV | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 206779073 | YORK | YHM36B22 | CF36BXA1+TXV | TM9V080B12MP12 | 22,200 | $1,110 |
| No | 205536816 | YORK | YHM36B22 | CU36CXA1+TXV | YP9C100C16MP13 | 22,000 | $1,100 |
| No | 203076917 | YORK | YHM36B22 | CM36CBCA1 | YP9C100C16MP13 | 22,000 | $1,100 |
| No | 205536837 | YORK | YHM36B22 | CU36CXA1+TXV | TP9C100C16MP13 | 22,000 | $1,100 |
| No | 203076913 | YORK | YHM36B22 | CM36CBCA1 | TP9C100C16MP13 | 22,000 | $1,100 |
| No | 205536834 | YORK | YHM36B22 | CM36CXA1+TXV | TP9C100C16MP13 | 22,000 | $1,100 |
| No | 205536839 | YORK | YHM36B22 | CM36CXA1+TXV | YP9C100C16MP13 | 22,000 | $1,100 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205536832 | YORK | YHM36B22 | CU36CXA1+TXV | TM9V100C16MP12 | 22,000 | $1,100 |
| No | 203076909 | YORK | YHM36B22 | CM36CBCA1 | TM9V100C16MP12 | 22,000 | $1,100 |
| No | 205536813 | YORK | YHM36B22 | CM36CXA1+TXV | TM9V100C16MP12 | 22,000 | $1,100 |
| No | 205536811 | YORK | YHM36B22 | CF36CXA1+TXV | YP9C100C16MP13 | 22,000 | $1,100 |
| No | 205536809 | YORK | YHM36B22 | CF36CXA1+TXV | TP9C100C16MP13 | 22,000 | $1,100 |
| No | 205536806 | YORK | YHM36B22 | CU42CXA1+TXV | YP9C100C16MP13 | 21,800 | $1,090 |
| No | 203076853 | YORK | YHM36B22 | CM42CBCA1 | YP9C100C16MP13 | 21,800 | $1,090 |
| No | 205536830 | YORK | YHM36B22 | CM42CXA1+TXV | YP9C100C16MP13 | 21,800 | $1,090 |
| No | 205536808 | YORK | YHM36B22 | CF36CXA1+TXV | TM9V100C16MP12 | 22,000 | $1,100 |
| No | 203076838 | YORK | YHM36B22 | CF42CBCA1 | YP9C100C16MP13 | 21,800 | $1,090 |
| No | 205536804 | YORK | YHM36B22 | CU42CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 203076847 | YORK | YHM36B22 | CM42CBCA1 | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205536802 | YORK | YHM36B22 | CM42CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 203076833 | YORK | YHM36B22 | CF42CBCA1 | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 203076842 | YORK | YHM36B22 | CM42CBCA1 | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205536799 | YORK | YHM36B22 | CM42CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205536801 | YORK | YHM36B22 | CU42CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 203076829 | YORK | YHM36B22 | CF42CBCA1 | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205536784 | YORK | YHM36B22 | CF42CXA1+TXV | YP9C100C16MP13 | 21,800 | $1,090 |
| No | 205536782 | YORK | YHM36B22 | CF42CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205536781 | YORK | YHM36B22 | CF42CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205536779 | YORK | YHM36B22 | CM42DXA1+TXV | YP9C100C16MP13 | 21,800 | $1,090 |
| No | 205536777 | YORK | YHM36B22 | CM42DXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205536775 | YORK | YHM36B22 | CM42DXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205536774 | YORK | YHM36B22 | CF42DXA1+TXV | YP9C100C16MP13 | 21,800 | $1,090 |
| No | 205536772 | YORK | YHM36B22 | CF42DXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205536770 | YORK | YHM36B22 | CF42DXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205536768 | YORK | YHM36B22 | CM42DXA1+TXV | YP9C100C20MP13 | 22,400 | $1,120 |
| No | 205536765 | YORK | YHM36B22 | CM42DXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205536763 | YORK | YHM36B22 | CF42DXA1+TXV | YP9C100C20MP13 | 22,400 | $1,120 |
| No | 205536766 | YORK | YHM36B22 | CM42DXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205536757 | YORK | YHM36B22 | CU48CXA1+TXV | YP9C100C20MP13 | 22,400 | $1,120 |
| No | 205536759 | YORK | YHM36B22 | CF42DXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203076443 | YORK | YHM36B22 | CM48CBCA1 | YP9C100C20MP13 | 22,400 | $1,120 |
| No | 205536761 | YORK | YHM36B22 | CF42DXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205536797 | YORK | YHM36B22 | CM48CXA1+TXV | YP9C100C20MP13 | 22,400 | $1,120 |
| No | 203076431 | YORK | YHM36B22 | CF48CBCA1 | YP9C100C20MP13 | 22,400 | $1,120 |
| No | 205536795 | YORK | YHM36B22 | CU48CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203076439 | YORK | YHM36B22 | CM48CBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205536793 | YORK | YHM36B22 | CM48CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 203076427 | YORK | YHM36B22 | CF48CBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205536792 | YORK | YHM36B22 | CU48CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203076435 | YORK | YHM36B22 | CM48CBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203076422 | YORK | YHM36B22 | CF48CBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205536789 | YORK | YHM36B22 | CM48CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205536753 | YORK | YHM36B22 | CF48CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205536755 | YORK | YHM36B22 | CF48CXA1+TXV | YP9C100C20MP13 | 22,400 | $1,120 |
| No | 205536751 | YORK | YHM36B22 | CF48CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203076377 | YORK | YHM36B22 | CM48DBCA1 | YP9C100C20MP13 | 22,400 | $1,120 |
| No | 205536788 | YORK | YHM36B22 | CU48DXA1+TXV | YP9C100C20MP13 | 22,400 | $1,120 |
| No | 205536786 | YORK | YHM36B22 | CM48DXA1+TXV | YP9C100C20MP13 | 22,400 | $1,120 |
| No | 203076371 | YORK | YHM36B22 | CM48DBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205536749 | YORK | YHM36B22 | CU48DXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205536747 | YORK | YHM36B22 | CM48DXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 203076366 | YORK | YHM36B22 | CM48DBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205536744 | YORK | YHM36B22 | CU48DXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205536742 | YORK | YHM36B22 | CM48DXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205536740 | YORK | YHM36B22 | CF48DXA1+TXV | YP9C100C20MP13 | 22,400 | $1,120 |
| No | 205536738 | YORK | YHM36B22 | CF48DXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205536736 | YORK | YHM36B22 | CF48DXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205144618 | YORK | YHM36B22 | AE42CBC21 | | 22,400 | $1,120 |
| No | 203076252 | YORK | YHM36B22 | AE42CX21+TXV | | 22,400 | $1,120 |
| No | 205535945 | YORK | YHM24B21 | CU24AXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |
| No | 202613897 | YORK | YHM24B21 | CM24ABAA1 | TL8E060A12UH11 | 15,200 | $760 |
| No | 205535949 | YORK | YHM24B21 | CM24AXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |
| No | 205535944 | YORK | YHM24B21 | CF24AXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |
| No | 202613898 | YORK | YHM24B21 | CF24ABAA1 | TL8E060A12UH11 | 15,200 | $760 |
| No | 206779533 | YORK | YHM48B21 | CU48CXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 206779682 | YORK | YHM48B21 | CM48CXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 202586534 | YORK | YHM48B21 | CM48CBCA1 | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 202586533 | YORK | YHM48B21 | CF48CBCA1 | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 206779556 | YORK | YHM48B21 | CF48CXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 205073808 | YORK | YHM48B21 | CU60CXA2+TXV | TL8E080C16UH11 | 27,800 | $1,390 |
| No | 205073805 | YORK | YHM48B21 | CF60CXA2+TXV | TL8E080C16UH11 | 27,800 | $1,390 |
| No | 205073807 | YORK | YHM48B21 | CM60CXA2+TXV | TL8E080C16UH11 | 27,800 | $1,390 |
| No | 206779532 | YORK | YHM48B21 | CM64DXA1+TXV | TL8E080C16UH11 | 29,600 | $1,480 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206779531 | YORK | YHM48B21 | CF64DXA1+TXV | TL8E080C16UH11 | 29,600 | $1,480 |
| No | 205073798 | YORK | YHM48B21 | CU60CXA2+TXV | TL8E100C20UH11 | 27,600 | $1,380 |
| No | 205073796 | YORK | YHM48B21 | CM60CXA2+TXV | TL8E100C20UH11 | 27,600 | $1,380 |
| No | 205073794 | YORK | YHM48B21 | CF60CXA2+TXV | TL8E100C20UH11 | 27,600 | $1,380 |
| No | 205073793 | YORK | YHM48B21 | CU60DXA2+TXV | TL8E100C20UH11 | 27,800 | $1,390 |
| No | 205073791 | YORK | YHM48B21 | CM60DXA2+TXV | TL8E100C20UH11 | 27,800 | $1,390 |
| No | 205073789 | YORK | YHM48B21 | CF60DXA2+TXV | TL8E100C20UH11 | 27,800 | $1,390 |
| No | 205535938 | YORK | YHM48B21 | CU48DXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 202586515 | YORK | YHM48B21 | CM48DBCA1 | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205535937 | YORK | YHM48B21 | CM48DXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205535935 | YORK | YHM48B21 | CM64DXA1+TXV | TL9E080C16UH11 | 29,600 | $1,480 |
| No | 205535936 | YORK | YHM48B21 | CF48DXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205535934 | YORK | YHM48B21 | CF64DXA1+TXV | TL9E080C16UH11 | 29,600 | $1,480 |
| No | 205073778 | YORK | YHM48B21 | CU60CXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205073777 | YORK | YHM48B21 | CM60CXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205073776 | YORK | YHM48B21 | CF60CXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205073774 | YORK | YHM48B21 | CU60DXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205073773 | YORK | YHM48B21 | CM60DXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205073771 | YORK | YHM48B21 | CF60DXA2+TXV | TL9E100C20UH11 | 27,800 | $1,390 |
| No | 205073750 | YORK | YHM48B21 | CU60CXA2+TXV | TMLE080C20MP11 | 27,400 | $1,370 |
| No | 205073749 | YORK | YHM48B21 | CM60CXA2+TXV | TMLE080C20MP11 | 27,400 | $1,370 |
| No | 205073745 | YORK | YHM48B21 | CM60CXA2+TXV | TM8E080C20MP11 | 27,400 | $1,370 |
| No | 205073747 | YORK | YHM48B21 | CU60CXA2+TXV | TM8E080C20MP11 | 27,400 | $1,370 |
| No | 205073744 | YORK | YHM48B21 | CF60CXA2+TXV | TMLE080C20MP11 | 27,400 | $1,370 |
| No | 205073742 | YORK | YHM48B21 | CF60CXA2+TXV | TM8E080C20MP11 | 27,400 | $1,370 |
| No | 205073741 | YORK | YHM48B21 | CU60DXA2+TXV | TMLE080C20MP11 | 27,600 | $1,380 |
| No | 205073739 | YORK | YHM48B21 | CM60DXA2+TXV | TMLE080C20MP11 | 27,600 | $1,380 |
| No | 205073738 | YORK | YHM48B21 | CU60DXA2+TXV | TM8E080C20MP11 | 27,600 | $1,380 |
| No | 205073736 | YORK | YHM48B21 | CM60DXA2+TXV | TM8E080C20MP11 | 27,600 | $1,380 |
| No | 205073735 | YORK | YHM48B21 | CF60DXA2+TXV | TMLE080C20MP11 | 27,600 | $1,380 |
| No | 205073733 | YORK | YHM48B21 | CF60DXA2+TXV | TM8E080C20MP11 | 27,600 | $1,380 |
| No | 206779526 | YORK | YHM48B21 | CU48CXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 203423010 | YORK | YHM48B21 | CM48CBCA1 | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 206779555 | YORK | YHM48B21 | CM48CXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 203423007 | YORK | YHM48B21 | CF48CBCA1 | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 206779530 | YORK | YHM48B21 | CU48CXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 202586475 | YORK | YHM48B21 | CM48CBCA1 | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 206779529 | YORK | YHM48B21 | CM48CXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202586474 | YORK | YHM48B21 | CF48CBCA1 | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 206779528 | YORK | YHM48B21 | CF48CXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 206779527 | YORK | YHM48B21 | CF48CXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 205073682 | YORK | YHM48B21 | CU60DXA2+TXV | TMLE120C16MP11 | 27,800 | $1,390 |
| No | 205073680 | YORK | YHM48B21 | CM60DXA2+TXV | TMLE120C16MP11 | 27,800 | $1,390 |
| No | 205073679 | YORK | YHM48B21 | CU60DXA2+TXV | TM8E120C16MP11 | 27,800 | $1,390 |
| No | 205073676 | YORK | YHM48B21 | CM60DXA2+TXV | TM8E120C16MP11 | 27,800 | $1,390 |
| No | 205073673 | YORK | YHM48B21 | CF60DXA2+TXV | TM8E120C16MP11 | 27,800 | $1,390 |
| No | 206779525 | YORK | YHM48B21 | CM64DXA1+TXV | TMLE120C16MP11 | 30,400 | $1,520 |
| No | 205073674 | YORK | YHM48B21 | CF60DXA2+TXV | TMLE120C16MP11 | 27,800 | $1,390 |
| No | 206779524 | YORK | YHM48B21 | CM64DXA1+TXV | TM8E120C16MP11 | 30,400 | $1,520 |
| No | 206779523 | YORK | YHM48B21 | CF64DXA1+TXV | TMLE120C16MP11 | 30,400 | $1,520 |
| No | 206779522 | YORK | YHM48B21 | CF64DXA1+TXV | TM8E120C16MP11 | 30,400 | $1,520 |
| No | 205073653 | YORK | YHM48B21 | CU60DXA2+TXV | TMLE130D20MP11 | 27,800 | $1,390 |
| No | 205073651 | YORK | YHM48B21 | CM60DXA2+TXV | TMLE130D20MP11 | 27,800 | $1,390 |
| No | 205073649 | YORK | YHM48B21 | CU60DXA2+TXV | TM8E130D20MP11 | 27,800 | $1,390 |
| No | 205073647 | YORK | YHM48B21 | CM60DXA2+TXV | TM8E130D20MP11 | 27,800 | $1,390 |
| No | 205073645 | YORK | YHM48B21 | CF60DXA2+TXV | TMLE130D20MP11 | 27,800 | $1,390 |
| No | 205073643 | YORK | YHM48B21 | CF60DXA2+TXV | TM8E130D20MP11 | 27,800 | $1,390 |
| No | 205535928 | YORK | YHM48B21 | CU48CXA1+TXV | TM9E080B12MP12 | 28,600 | $1,430 |
| No | 202586465 | YORK | YHM48B21 | CM48CBCA1 | TM9E080B12MP12 | 28,600 | $1,430 |
| No | 205535943 | YORK | YHM48B21 | CM48CXA1+TXV | TM9E080B12MP12 | 28,600 | $1,430 |
| No | 202586464 | YORK | YHM48B21 | CF48CBCA1 | TM9E080B12MP12 | 28,600 | $1,430 |
| No | 205535942 | YORK | YHM48B21 | CF48CXA1+TXV | TM9E080B12MP12 | 28,600 | $1,430 |
| No | 202586461 | YORK | YHM48B21 | CM48CBCA1 | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 206779520 | YORK | YHM48B21 | CM48CXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 206779521 | YORK | YHM48B21 | CU48CXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 202586460 | YORK | YHM48B21 | CF48CBCA1 | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 206779519 | YORK | YHM48B21 | CF48CXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 205535941 | YORK | YHM48B21 | CM64DXA1+TXV | TM9E080C16MP12 | 28,800 | $1,440 |
| No | 205535940 | YORK | YHM48B21 | CF64DXA1+TXV | TM9E080C16MP12 | 28,800 | $1,440 |
| No | 205535939 | YORK | YHM48B21 | CU48CXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 202586452 | YORK | YHM48B21 | CM48CBCA1 | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205535933 | YORK | YHM48B21 | CM48CXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 202586451 | YORK | YHM48B21 | CF48CBCA1 | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205535927 | YORK | YHM48B21 | CF48CXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205073611 | YORK | YHM48B21 | CU60DXA2+TXV | TM9E100C20MP12 | 27,400 | $1,370 |
| No | 205073609 | YORK | YHM48B21 | CM60DXA2+TXV | TM9E100C20MP12 | 27,400 | $1,370 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205073608 | YORK | YHM48B21 | CF60DXA2+TXV | TM9E100C20MP12 | 27,400 | $1,370 |
| No | 205073606 | YORK | YHM48B21 | CU60DXA2+TXV | TM9E120D20MP12 | 27,800 | $1,390 |
| No | 205073604 | YORK | YHM48B21 | CM60DXA2+TXV | TM9E120D20MP12 | 27,800 | $1,390 |
| No | 205073602 | YORK | YHM48B21 | CF60DXA2+TXV | TM9E120D20MP12 | 27,800 | $1,390 |
| No | 206779705 | YORK | YHM60B21 | CM64DXA1+TXV | TL8E080C16UH11 | 33,000 | $1,650 |
| No | 206779704 | YORK | YHM60B21 | CF64DXA1+TXV | TL8E080C16UH11 | 33,000 | $1,650 |
| No | 205535926 | YORK | YHM60B21 | CM64DXA1+TXV | TL9E080C16UH11 | 32,600 | $1,630 |
| No | 205535925 | YORK | YHM60B21 | CF64DXA1+TXV | TL9E080C16UH11 | 32,600 | $1,630 |
| No | 206779702 | YORK | YHM60B21 | CM64DXA1+TXV | TMLE080C16MP11 | 33,000 | $1,650 |
| No | 206779701 | YORK | YHM60B21 | CM64DXA1+TXV | TM8E080C16MP11 | 33,000 | $1,650 |
| No | 206779700 | YORK | YHM60B21 | CF64DXA1+TXV | TMLE080C16MP11 | 33,000 | $1,650 |
| No | 206779699 | YORK | YHM60B21 | CF64DXA1+TXV | TM8E080C16MP11 | 33,000 | $1,650 |
| No | 206779698 | YORK | YHM60B21 | CM64DXA1+TXV | TMLE100C16MP11 | 33,000 | $1,650 |
| No | 206779697 | YORK | YHM60B21 | CM64DXA1+TXV | TM8E100C16MP11 | 33,000 | $1,650 |
| No | 206779696 | YORK | YHM60B21 | CF64DXA1+TXV | TMLE100C16MP11 | 33,000 | $1,650 |
| No | 206779695 | YORK | YHM60B21 | CF64DXA1+TXV | TM8E100C16MP11 | 33,000 | $1,650 |
| No | 206779694 | YORK | YHM60B21 | CM64DXA1+TXV | TMLE100C20MP11 | 32,600 | $1,630 |
| No | 206779693 | YORK | YHM60B21 | CM64DXA1+TXV | TM8E100C20MP11 | 32,600 | $1,630 |
| No | 206779692 | YORK | YHM60B21 | CF64DXA1+TXV | TMLE100C20MP11 | 32,600 | $1,630 |
| No | 206779691 | YORK | YHM60B21 | CF64DXA1+TXV | TM8E100C20MP11 | 32,600 | $1,630 |
| No | 206779686 | YORK | YHM60B21 | CM64DXA1+TXV | TMLE120C20MP11 | 32,600 | $1,630 |
| No | 206779684 | YORK | YHM60B21 | CF64DXA1+TXV | TMLE120C20MP11 | 32,600 | $1,630 |
| No | 206779683 | YORK | YHM60B21 | CF64DXA1+TXV | TM8E120C20MP11 | 32,600 | $1,630 |
| No | 206779685 | YORK | YHM60B21 | CM64DXA1+TXV | TM8E120C20MP11 | 32,600 | $1,630 |
| No | 205535924 | YORK | YHM60B21 | CM64DXA1+TXV | TMLE130D20MP11 | 32,800 | $1,640 |
| No | 205535923 | YORK | YHM60B21 | CM64DXA1+TXV | TM8E130D20MP11 | 32,800 | $1,640 |
| No | 205535922 | YORK | YHM60B21 | CF64DXA1+TXV | TMLE130D20MP11 | 32,800 | $1,640 |
| No | 205535921 | YORK | YHM60B21 | CF64DXA1+TXV | TM8E130D20MP11 | 32,800 | $1,640 |
| No | 206778850 | YORK | YHM24B21 | CM24BBAA1+MVC12BN21 | | 14,900 | $745 |
| No | 206778849 | YORK | YHM24B21 | CM24BXA1+MVC12BN21+TXV | | 14,900 | $745 |
| No | 202099388 | YORK | YHM24B21 | CF24BBAA1+MVC12BN21 | | 14,900 | $745 |
| No | 206778798 | YORK | YHM24B21 | CF24BXA1+MVC12BN21+TXV | | 14,900 | $745 |
| No | 206778895 | YORK | YHM24B21 | CM30BXA1+MVC12BN21+TXV | | 15,300 | $765 |
| No | 206778896 | YORK | YHM24B21 | CM30BBAA1+MVC12BN21 | | 15,300 | $765 |
| No | 206778894 | YORK | YHM24B21 | CF30BBAA1+MVC12BN21 | | 15,300 | $765 |
| No | 206778893 | YORK | YHM24B21 | CF30BXA1+MVC12BN21+TXV | | 15,300 | $765 |
| No | 206778851 | YORK | YHM24B21 | CF30CXA1+MVC16CN21+TXV | | 14,800 | $740 |
| No | 206778852 | YORK | YHM24B21 | CM30CXA1+MVC16CN21+TXV | | 14,800 | $740 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206778888 | YORK | YHM24B21 | CM36CXA1+MVC16CN21+TXV | | 15,300 | $765 |
| No | 206778793 | YORK | YHM24B21 | CU24AXA1+TXV | YPLC060A12MP13 | 15,000 | $750 |
| No | 206778887 | YORK | YHM24B21 | CF36CXA1+MVC16CN21+TXV | | 15,300 | $765 |
| No | 206778792 | YORK | YHM24B21 | CM24ABAA1 | YPLC060A12MP13 | 15,000 | $750 |
| No | 206778791 | YORK | YHM24B21 | CM24AXA1+TXV | YPLC060A12MP13 | 15,000 | $750 |
| No | 202099106 | YORK | YHM24B21 | CF24ABAA1 | YPLC060A12MP13 | 15,000 | $750 |
| No | 206778790 | YORK | YHM24B21 | CU24AXA1+TXV | TPLC060A12MP13 | 15,000 | $750 |
| No | 206778789 | YORK | YHM24B21 | CM24ABAA1 | TPLC060A12MP13 | 15,000 | $750 |
| No | 206778788 | YORK | YHM24B21 | CM24AXA1+TXV | TPLC060A12MP13 | 15,000 | $750 |
| No | 202099105 | YORK | YHM24B21 | CF24ABAA1 | TPLC060A12MP13 | 15,000 | $750 |
| No | 206778787 | YORK | YHM24B21 | CU24AXA1+TXV | TMLV060A12MP12 | 15,000 | $750 |
| No | 206778785 | YORK | YHM24B21 | CM24AXA1+TXV | TMLV060A12MP12 | 15,000 | $750 |
| No | 202099104 | YORK | YHM24B21 | CF24ABAA1 | TMLV060A12MP12 | 15,000 | $750 |
| No | 206778786 | YORK | YHM24B21 | CM24ABAA1 | TMLV060A12MP12 | 15,000 | $750 |
| No | 206778784 | YORK | YHM24B21 | CU24AXA1+TXV | TM8V060A12MP12 | 15,000 | $750 |
| No | 206778783 | YORK | YHM24B21 | CM24ABAA1 | TM8V060A12MP12 | 15,000 | $750 |
| No | 206778782 | YORK | YHM24B21 | CM24AXA1+TXV | TM8V060A12MP12 | 15,000 | $750 |
| No | 206778781 | YORK | YHM24B21 | CF24AXA1+TXV | YPLC060A12MP13 | 15,000 | $750 |
| No | 202099103 | YORK | YHM24B21 | CF24ABAA1 | TM8V060A12MP12 | 15,000 | $750 |
| No | 206778779 | YORK | YHM24B21 | CF24AXA1+TXV | TMLV060A12MP12 | 15,000 | $750 |
| No | 206778780 | YORK | YHM24B21 | CF24AXA1+TXV | TPLC060A12MP13 | 15,000 | $750 |
| No | 206778778 | YORK | YHM24B21 | CF24AXA1+TXV | TM8V060A12MP12 | 15,000 | $750 |
| No | 206779040 | YORK | YHM24B21 | CU30BXA1+TXV | YPLC080B12MP13 | 15,000 | $750 |
| No | 206779039 | YORK | YHM24B21 | CM30BBAA1 | YPLC080B12MP13 | 15,000 | $750 |
| No | 206779038 | YORK | YHM24B21 | CM30BXA1+TXV | YPLC080B12MP13 | 15,000 | $750 |
| No | 206779037 | YORK | YHM24B21 | CF30BBAA1 | YPLC080B12MP13 | 15,000 | $750 |
| No | 206779036 | YORK | YHM24B21 | CU30BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206779035 | YORK | YHM24B21 | CM30BBAA1 | TPLC080B12MP13 | 15,000 | $750 |
| No | 206779034 | YORK | YHM24B21 | CM30BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206779033 | YORK | YHM24B21 | CF30BBAA1 | TPLC080B12MP13 | 15,000 | $750 |
| No | 206779032 | YORK | YHM24B21 | CU30BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206779031 | YORK | YHM24B21 | CM30BBAA1 | TM8V080B12MP12 | 15,000 | $750 |
| No | 206779030 | YORK | YHM24B21 | CM30BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206779029 | YORK | YHM24B21 | CF30BBAA1 | TM8V080B12MP12 | 15,000 | $750 |
| No | 206779028 | YORK | YHM24B21 | CF30BXA1+TXV | YPLC080B12MP13 | 15,000 | $750 |
| No | 206779027 | YORK | YHM24B21 | CF30BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206779026 | YORK | YHM24B21 | CF30BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206778904 | YORK | YHM24B21 | CU24BXA1+TXV | TM9Y060B12MP11 | 14,900 | $745 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206778903 | YORK | YHM24B21 | CM24BBAA1 | TM9Y060B12MP11 | 14,900 | $745 |
| No | 206778902 | YORK | YHM24B21 | CM24BXA1+TXV | TM9Y060B12MP11 | 14,900 | $745 |
| No | 206778901 | YORK | YHM24B21 | CF24BXA1+TXV | TM9Y060B12MP11 | 14,900 | $745 |
| No | 206778899 | YORK | YHM24B21 | CU24AXA1+TXV | TM9V040A10MP12 | 15,200 | $760 |
| No | 202143648 | YORK | YHM24B21 | CF24BBAA1 | TM9Y060B12MP11 | 14,900 | $745 |
| No | 206778898 | YORK | YHM24B21 | CM24ABAA1 | TM9V040A10MP12 | 15,200 | $760 |
| No | 206778897 | YORK | YHM24B21 | CM24AXA1+TXV | TM9V040A10MP12 | 15,200 | $760 |
| No | 202143646 | YORK | YHM24B21 | CF24ABAA1 | TM9V040A10MP12 | 15,200 | $760 |
| No | 206778900 | YORK | YHM24B21 | CF24AXA1+TXV | TM9V040A10MP12 | 15,200 | $760 |
| No | 206778830 | YORK | YHM24B21 | CU36BXA1+TXV | YP9C060B12MP13 | 14,900 | $745 |
| No | 206778828 | YORK | YHM24B21 | CM36BXA1+TXV | YP9C060B12MP13 | 14,900 | $745 |
| No | 206778829 | YORK | YHM24B21 | CM36BBAA1 | YP9C060B12MP13 | 14,900 | $745 |
| No | 206778827 | YORK | YHM24B21 | CF36BBAA1 | YP9C060B12MP13 | 14,900 | $745 |
| No | 206778826 | YORK | YHM24B21 | CU36BXA1+TXV | TP9C060B12MP13 | 14,900 | $745 |
| No | 206778825 | YORK | YHM24B21 | CM36BBAA1 | TP9C060B12MP13 | 14,900 | $745 |
| No | 206778824 | YORK | YHM24B21 | CM36BXA1+TXV | TP9C060B12MP13 | 14,900 | $745 |
| No | 206778822 | YORK | YHM24B21 | CU36BXA1+TXV | TM9V060B12MP12 | 14,900 | $745 |
| No | 206779580 | YORK | YHM60B21 | CM64DXA1+TXV | YP9C100C20MP13 | 33,000 | $1,650 |
| No | 206778817 | YORK | YHM24B21 | CF36BXA1+TXV | TP9C060B12MP13 | 14,900 | $745 |
| No | 206779579 | YORK | YHM60B21 | CM64DXA1+TXV | TP9C100C20MP13 | 33,000 | $1,650 |
| No | 206778820 | YORK | YHM24B21 | CM36BXA1+TXV | TM9V060B12MP12 | 14,900 | $745 |
| No | 206778819 | YORK | YHM24B21 | CF36BBAA1 | TM9V060B12MP12 | 14,900 | $745 |
| No | 206778816 | YORK | YHM24B21 | CF36BXA1+TXV | TM9V060B12MP12 | 14,900 | $745 |
| No | 206778821 | YORK | YHM24B21 | CM36BBAA1 | TM9V060B12MP12 | 14,900 | $745 |
| No | 206778818 | YORK | YHM24B21 | CF36BXA1+TXV | YP9C060B12MP13 | 14,900 | $745 |
| No | 206778823 | YORK | YHM24B21 | CF36BBAA1 | TP9C060B12MP13 | 14,900 | $745 |
| No | 206779577 | YORK | YHM60B21 | CF64DXA1+TXV | YP9C100C20MP13 | 33,000 | $1,650 |
| No | 206779578 | YORK | YHM60B21 | CM64DXA1+TXV | TM9V100C20MP12 | 33,000 | $1,650 |
| No | 206779576 | YORK | YHM60B21 | CF64DXA1+TXV | TP9C100C20MP13 | 33,000 | $1,650 |
| No | 205536565 | YORK | YHM60B21 | CM64DXA1+TXV | YP9C120D20MP13 | 32,600 | $1,630 |
| No | 205536562 | YORK | YHM60B21 | CM64DXA1+TXV | TM9V120D20MP12 | 32,600 | $1,630 |
| No | 206779575 | YORK | YHM60B21 | CF64DXA1+TXV | TM9V100C20MP12 | 33,000 | $1,650 |
| No | 205536561 | YORK | YHM60B21 | CF64DXA1+TXV | YP9C120D20MP13 | 32,600 | $1,630 |
| No | 205536560 | YORK | YHM60B21 | CF64DXA1+TXV | TP9C120D20MP13 | 32,600 | $1,630 |
| No | 205536564 | YORK | YHM60B21 | CM64DXA1+TXV | TP9C120D20MP13 | 32,600 | $1,630 |
| No | 205536558 | YORK | YHM60B21 | CF64DXA1+TXV | TM9V120D20MP12 | 32,600 | $1,630 |
| No | 9035723 | YORK | YHM48B21 | AVC48CX21+TXV | | 27,600 | $1,380 |
| No | 206779283 | YORK | YHM48B21 | CM48CBCA1+MVC16CN21 | | 28,000 | $1,400 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206779282 | YORK | YHM48B21 | CM48CXA1+MVC16CN21+TXV | | 28,000 | $1,400 |
| No | 9920318 | YORK | YHM48B21 | CF48CBCA1+MVC16CN21 | | 28,000 | $1,400 |
| No | 206779281 | YORK | YHM48B21 | CF48CXA1+MVC16CN21+TXV | | 28,000 | $1,400 |
| No | 206779514 | YORK | YHM48B21 | CM48CBCA1 | YPLC080B12MP13 | 28,200 | $1,410 |
| No | 206779515 | YORK | YHM48B21 | CU48CXA1+TXV | YPLC080B12MP13 | 28,200 | $1,410 |
| No | 206779513 | YORK | YHM48B21 | CM48CXA1+TXV | YPLC080B12MP13 | 28,200 | $1,410 |
| No | 202098780 | YORK | YHM48B21 | CF48CBCA1 | YPLC080B12MP13 | 28,200 | $1,410 |
| No | 206779518 | YORK | YHM48B21 | CU48CXA1+TXV | TPLC080B12MP13 | 28,200 | $1,410 |
| No | 206779517 | YORK | YHM48B21 | CM48CBCA1 | TPLC080B12MP13 | 28,200 | $1,410 |
| No | 206779516 | YORK | YHM48B21 | CM48CXA1+TXV | TPLC080B12MP13 | 28,200 | $1,410 |
| No | 202098770 | YORK | YHM48B21 | CF48CBCA1 | TPLC080B12MP13 | 28,200 | $1,410 |
| No | 206779512 | YORK | YHM48B21 | CU48CXA1+TXV | TM8V080B12MP12 | 28,200 | $1,410 |
| No | 206779511 | YORK | YHM48B21 | CM48CBCA1 | TM8V080B12MP12 | 28,200 | $1,410 |
| No | 206779510 | YORK | YHM48B21 | CM48CXA1+TXV | TM8V080B12MP12 | 28,200 | $1,410 |
| No | 202098750 | YORK | YHM48B21 | CF48CBCA1 | TM8V080B12MP12 | 28,200 | $1,410 |
| No | 206779509 | YORK | YHM48B21 | CF48CXA1+TXV | YPLC080B12MP13 | 28,200 | $1,410 |
| No | 206779508 | YORK | YHM48B21 | CF48CXA1+TXV | TPLC080B12MP13 | 28,200 | $1,410 |
| No | 206779507 | YORK | YHM48B21 | CF48CXA1+TXV | TM8V080B12MP12 | 28,200 | $1,410 |
| No | 206779506 | YORK | YHM48B21 | CU48CXA1+TXV | YPLC100C16MP13 | 28,000 | $1,400 |
| No | 206779505 | YORK | YHM48B21 | CM48CBCA1 | YPLC100C16MP13 | 28,000 | $1,400 |
| No | 206779504 | YORK | YHM48B21 | CM48CXA1+TXV | YPLC100C16MP13 | 28,000 | $1,400 |
| No | 202098782 | YORK | YHM48B21 | CF48CBCA1 | YPLC100C16MP13 | 28,000 | $1,400 |
| No | 206779503 | YORK | YHM48B21 | CU48CXA1+TXV | YPLC080C16MP13 | 28,000 | $1,400 |
| No | 206779502 | YORK | YHM48B21 | CM48CBCA1 | YPLC080C16MP13 | 28,000 | $1,400 |
| No | 202098781 | YORK | YHM48B21 | CF48CBCA1 | YPLC080C16MP13 | 28,000 | $1,400 |
| No | 206779501 | YORK | YHM48B21 | CM48CXA1+TXV | YPLC080C16MP13 | 28,000 | $1,400 |
| No | 206779499 | YORK | YHM48B21 | CM48CBCA1 | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206779498 | YORK | YHM48B21 | CM48CXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206779500 | YORK | YHM48B21 | CU48CXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 202098772 | YORK | YHM48B21 | CF48CBCA1 | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206779497 | YORK | YHM48B21 | CU48CXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206779495 | YORK | YHM48B21 | CM48CXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206779496 | YORK | YHM48B21 | CM48CBCA1 | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 202098771 | YORK | YHM48B21 | CF48CBCA1 | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206779494 | YORK | YHM48B21 | CU48CXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206779493 | YORK | YHM48B21 | CM48CBCA1 | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206779492 | YORK | YHM48B21 | CM48CXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 202098762 | YORK | YHM48B21 | CF48CBCA1 | TMLV100C16MP12 | 28,000 | $1,400 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206779491 | YORK | YHM48B21 | CU48CXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206779490 | YORK | YHM48B21 | CM48CBCA1 | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206779489 | YORK | YHM48B21 | CM48CXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 202098751 | YORK | YHM48B21 | CF48CBCA1 | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206779488 | YORK | YHM48B21 | CU48CXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206779487 | YORK | YHM48B21 | CM48CBCA1 | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206779486 | YORK | YHM48B21 | CM48CXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 202098752 | YORK | YHM48B21 | CF48CBCA1 | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206779463 | YORK | YHM48B21 | CF48CXA1+TXV | YPLC100C16MP13 | 28,000 | $1,400 |
| No | 206779462 | YORK | YHM48B21 | CF48CXA1+TXV | YPLC080C16MP13 | 28,000 | $1,400 |
| No | 206779461 | YORK | YHM48B21 | CF48CXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206779460 | YORK | YHM48B21 | CF48CXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206779459 | YORK | YHM48B21 | CF48CXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206779458 | YORK | YHM48B21 | CF48CXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206779456 | YORK | YHM48B21 | CM48DBCA1 | YPLC100C16MP13 | 28,000 | $1,400 |
| No | 206779455 | YORK | YHM48B21 | CU48DXA1+TXV | YPLC100C16MP13 | 28,000 | $1,400 |
| No | 206779454 | YORK | YHM48B21 | CM48DXA1+TXV | YPLC100C16MP13 | 28,000 | $1,400 |
| No | 206779457 | YORK | YHM48B21 | CF48CXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206779453 | YORK | YHM48B21 | CM48DBCA1 | YPLC080C16MP13 | 28,000 | $1,400 |
| No | 206779452 | YORK | YHM48B21 | CU48DXA1+TXV | YPLC080C16MP13 | 28,000 | $1,400 |
| No | 206779451 | YORK | YHM48B21 | CM48DXA1+TXV | YPLC080C16MP13 | 28,000 | $1,400 |
| No | 206779450 | YORK | YHM48B21 | CM48DBCA1 | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206779449 | YORK | YHM48B21 | CU48DXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206779448 | YORK | YHM48B21 | CM48DXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206779447 | YORK | YHM48B21 | CM48DBCA1 | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206779446 | YORK | YHM48B21 | CU48DXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206779445 | YORK | YHM48B21 | CM48DXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206779443 | YORK | YHM48B21 | CU48DXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206779444 | YORK | YHM48B21 | CM48DBCA1 | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206779441 | YORK | YHM48B21 | CM48DBCA1 | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206779442 | YORK | YHM48B21 | CM48DXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206779440 | YORK | YHM48B21 | CU48DXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206779439 | YORK | YHM48B21 | CM48DXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206779438 | YORK | YHM48B21 | CM48DBCA1 | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206779437 | YORK | YHM48B21 | CU48DXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206779435 | YORK | YHM48B21 | CF48DXA1+TXV | YPLC100C16MP13 | 28,000 | $1,400 |
| No | 206779436 | YORK | YHM48B21 | CM48DXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206779434 | YORK | YHM48B21 | CF48DXA1+TXV | YPLC080C16MP13 | 28,000 | $1,400 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206779433 | YORK | YHM48B21 | CF48DXA1+TXV | TPLC100C16MP13 | 28,000 | $1,400 |
| No | 206779432 | YORK | YHM48B21 | CF48DXA1+TXV | TPLC080C16MP13 | 28,000 | $1,400 |
| No | 206779431 | YORK | YHM48B21 | CF48DXA1+TXV | TMLV100C16MP12 | 28,000 | $1,400 |
| No | 206779430 | YORK | YHM48B21 | CF48DXA1+TXV | TM8V080C16MP12 | 28,000 | $1,400 |
| No | 206779429 | YORK | YHM48B21 | CF48DXA1+TXV | TM8V100C16MP12 | 28,000 | $1,400 |
| No | 206779428 | YORK | YHM48B21 | CM48DBCA1 | YPLC120C20MP13 | 28,200 | $1,410 |
| No | 206779427 | YORK | YHM48B21 | CU48DXA1+TXV | YPLC120C20MP13 | 28,200 | $1,410 |
| No | 206779426 | YORK | YHM48B21 | CM48DXA1+TXV | YPLC120C20MP13 | 28,200 | $1,410 |
| No | 206779425 | YORK | YHM48B21 | CM48DBCA1 | YPLC100C20MP13 | 28,200 | $1,410 |
| No | 206779424 | YORK | YHM48B21 | CU48DXA1+TXV | YPLC100C20MP13 | 28,200 | $1,410 |
| No | 206779423 | YORK | YHM48B21 | CM48DXA1+TXV | YPLC100C20MP13 | 28,200 | $1,410 |
| No | 206779422 | YORK | YHM48B21 | CM48DBCA1 | TPLC120C20MP13 | 28,200 | $1,410 |
| No | 206779421 | YORK | YHM48B21 | CU48DXA1+TXV | TPLC120C20MP13 | 28,200 | $1,410 |
| No | 206779419 | YORK | YHM48B21 | CM48DBCA1 | TPLC100C20MP13 | 28,200 | $1,410 |
| No | 206779420 | YORK | YHM48B21 | CM48DXA1+TXV | TPLC120C20MP13 | 28,200 | $1,410 |
| No | 206779417 | YORK | YHM48B21 | CM48DXA1+TXV | TPLC100C20MP13 | 28,200 | $1,410 |
| No | 206779416 | YORK | YHM48B21 | CM48DBCA1 | TMLV120C20MP12 | 28,200 | $1,410 |
| No | 206779418 | YORK | YHM48B21 | CU48DXA1+TXV | TPLC100C20MP13 | 28,200 | $1,410 |
| No | 206779415 | YORK | YHM48B21 | CU48DXA1+TXV | TMLV120C20MP12 | 28,200 | $1,410 |
| No | 206779413 | YORK | YHM48B21 | CM48DBCA1 | TM8V100C20MP12 | 28,200 | $1,410 |
| No | 206779414 | YORK | YHM48B21 | CM48DXA1+TXV | TMLV120C20MP12 | 28,200 | $1,410 |
| No | 206779412 | YORK | YHM48B21 | CU48DXA1+TXV | TM8V100C20MP12 | 28,200 | $1,410 |
| No | 206779411 | YORK | YHM48B21 | CM48DXA1+TXV | TM8V100C20MP12 | 28,200 | $1,410 |
| No | 206779410 | YORK | YHM48B21 | CM48DBCA1 | TM8V120C20MP12 | 28,200 | $1,410 |
| No | 206779409 | YORK | YHM48B21 | CU48DXA1+TXV | TM8V120C20MP12 | 28,200 | $1,410 |
| No | 206779408 | YORK | YHM48B21 | CM48DXA1+TXV | TM8V120C20MP12 | 28,200 | $1,410 |
| No | 206779407 | YORK | YHM48B21 | CF48DXA1+TXV | YPLC120C20MP13 | 28,200 | $1,410 |
| No | 206779406 | YORK | YHM48B21 | CF48DXA1+TXV | YPLC100C20MP13 | 28,200 | $1,410 |
| No | 206779405 | YORK | YHM48B21 | CF48DXA1+TXV | TPLC120C20MP13 | 28,200 | $1,410 |
| No | 206779404 | YORK | YHM48B21 | CF48DXA1+TXV | TPLC100C20MP13 | 28,200 | $1,410 |
| No | 206779402 | YORK | YHM48B21 | CF48DXA1+TXV | TM8V100C20MP12 | 28,200 | $1,410 |
| No | 206779403 | YORK | YHM48B21 | CF48DXA1+TXV | TMLV120C20MP12 | 28,200 | $1,410 |
| No | 206779401 | YORK | YHM48B21 | CF48DXA1+TXV | TM8V120C20MP12 | 28,200 | $1,410 |
| No | 206779400 | YORK | YHM48B21 | CM64DXA1+TXV | YPLC120C20MP13 | 28,600 | $1,430 |
| No | 206779399 | YORK | YHM48B21 | CM64DXA1+TXV | YPLC100C20MP13 | 28,600 | $1,430 |
| No | 206779398 | YORK | YHM48B21 | CM64DXA1+TXV | TPLC120C20MP13 | 28,600 | $1,430 |
| No | 206779397 | YORK | YHM48B21 | CM64DXA1+TXV | TPLC100C20MP13 | 28,600 | $1,430 |
| No | 206779396 | YORK | YHM48B21 | CM64DXA1+TXV | TMLV120C20MP12 | 28,600 | $1,430 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206779395 | YORK | YHM48B21 | CM64DXA1+TXV | TM8V100C20MP12 | 28,600 | $1,430 |
| No | 206779394 | YORK | YHM48B21 | CM64DXA1+TXV | TM8V120C20MP12 | 28,600 | $1,430 |
| No | 206779393 | YORK | YHM48B21 | CF64DXA1+TXV | YPLC120C20MP13 | 28,600 | $1,430 |
| No | 206779392 | YORK | YHM48B21 | CF64DXA1+TXV | YPLC100C20MP13 | 28,600 | $1,430 |
| No | 206779391 | YORK | YHM48B21 | CF64DXA1+TXV | TPLC120C20MP13 | 28,600 | $1,430 |
| No | 206779390 | YORK | YHM48B21 | CF64DXA1+TXV | TPLC100C20MP13 | 28,600 | $1,430 |
| No | 206779389 | YORK | YHM48B21 | CF64DXA1+TXV | TMLV120C20MP12 | 28,600 | $1,430 |
| No | 206779388 | YORK | YHM48B21 | CF64DXA1+TXV | TM8V100C20MP12 | 28,600 | $1,430 |
| No | 206779387 | YORK | YHM48B21 | CF64DXA1+TXV | TM8V120C20MP12 | 28,600 | $1,430 |
| No | 206779221 | YORK | YHM48B21 | CU48CXA1+TXV | YP9C060B12MP13 | 28,400 | $1,420 |
| No | 206779220 | YORK | YHM48B21 | CM48CBCA1 | YP9C060B12MP13 | 28,400 | $1,420 |
| No | 206779219 | YORK | YHM48B21 | CM48CXA1+TXV | YP9C060B12MP13 | 28,400 | $1,420 |
| No | 202098775 | YORK | YHM48B21 | CF48CBCA1 | YP9C060B12MP13 | 28,400 | $1,420 |
| No | 206779231 | YORK | YHM48B21 | CU48CXA1+TXV | TP9C060B12MP13 | 28,400 | $1,420 |
| No | 206779230 | YORK | YHM48B21 | CM48CBCA1 | TP9C060B12MP13 | 28,400 | $1,420 |
| No | 202098765 | YORK | YHM48B21 | CF48CBCA1 | TP9C060B12MP13 | 28,400 | $1,420 |
| No | 206779229 | YORK | YHM48B21 | CM48CXA1+TXV | TP9C060B12MP13 | 28,400 | $1,420 |
| No | 206779218 | YORK | YHM48B21 | CU48CXA1+TXV | TM9V060B12MP12 | 28,400 | $1,420 |
| No | 206779217 | YORK | YHM48B21 | CM48CBCA1 | TM9V060B12MP12 | 28,400 | $1,420 |
| No | 206779216 | YORK | YHM48B21 | CM48CXA1+TXV | TM9V060B12MP12 | 28,400 | $1,420 |
| No | 202098755 | YORK | YHM48B21 | CF48CBCA1 | TM9V060B12MP12 | 28,400 | $1,420 |
| No | 206779215 | YORK | YHM48B21 | CF48CXA1+TXV | YP9C060B12MP13 | 28,400 | $1,420 |
| No | 206779214 | YORK | YHM48B21 | CF48CXA1+TXV | TP9C060B12MP13 | 28,400 | $1,420 |
| No | 206779213 | YORK | YHM48B21 | CF48CXA1+TXV | TM9V060B12MP12 | 28,400 | $1,420 |
| No | 206779484 | YORK | YHM48B21 | CU48CXA1+TXV | YP9C080B12MP13 | 28,200 | $1,410 |
| No | 206779483 | YORK | YHM48B21 | CM48CBCA1 | YP9C080B12MP13 | 28,200 | $1,410 |
| No | 206779482 | YORK | YHM48B21 | CM48CXA1+TXV | YP9C080B12MP13 | 28,200 | $1,410 |
| No | 202098776 | YORK | YHM48B21 | CF48CBCA1 | YP9C080B12MP13 | 28,200 | $1,410 |
| No | 206779481 | YORK | YHM48B21 | CU48CXA1+TXV | TP9C080B12MP13 | 28,200 | $1,410 |
| No | 206779480 | YORK | YHM48B21 | CM48CBCA1 | TP9C080B12MP13 | 28,200 | $1,410 |
| No | 206779479 | YORK | YHM48B21 | CM48CXA1+TXV | TP9C080B12MP13 | 28,200 | $1,410 |
| No | 206779478 | YORK | YHM48B21 | CU48CXA1+TXV | TM9V080B12MP12 | 28,200 | $1,410 |
| No | 202098766 | YORK | YHM48B21 | CF48CBCA1 | TP9C080B12MP13 | 28,200 | $1,410 |
| No | 206779477 | YORK | YHM48B21 | CM48CBCA1 | TM9V080B12MP12 | 28,200 | $1,410 |
| No | 202098756 | YORK | YHM48B21 | CF48CBCA1 | TM9V080B12MP12 | 28,200 | $1,410 |
| No | 206779475 | YORK | YHM48B21 | CF48CXA1+TXV | YP9C080B12MP13 | 28,200 | $1,410 |
| No | 206779476 | YORK | YHM48B21 | CM48CXA1+TXV | TM9V080B12MP12 | 28,200 | $1,410 |
| No | 206779474 | YORK | YHM48B21 | CF48CXA1+TXV | TP9C080B12MP13 | 28,200 | $1,410 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206779473 | YORK | YHM48B21 | CF48CXA1+TXV | TM9V080B12MP12 | 28,200 | $1,410 |
| No | 206779472 | YORK | YHM48B21 | CU48CXA1+TXV | YP9C080C16MP13 | 28,200 | $1,410 |
| No | 206779471 | YORK | YHM48B21 | CM48CBCA1 | YP9C080C16MP13 | 28,200 | $1,410 |
| No | 206779470 | YORK | YHM48B21 | CM48CXA1+TXV | YP9C080C16MP13 | 28,200 | $1,410 |
| No | 202098777 | YORK | YHM48B21 | CF48CBCA1 | YP9C080C16MP13 | 28,200 | $1,410 |
| No | 206779469 | YORK | YHM48B21 | CU48CXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206779468 | YORK | YHM48B21 | CM48CBCA1 | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206779467 | YORK | YHM48B21 | CM48CXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 202098767 | YORK | YHM48B21 | CF48CBCA1 | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206779466 | YORK | YHM48B21 | CU48CXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206779465 | YORK | YHM48B21 | CM48CBCA1 | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206779464 | YORK | YHM48B21 | CM48CXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 202098757 | YORK | YHM48B21 | CF48CBCA1 | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206779379 | YORK | YHM48B21 | CF48CXA1+TXV | YP9C080C16MP13 | 28,200 | $1,410 |
| No | 206779378 | YORK | YHM48B21 | CF48CXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206779377 | YORK | YHM48B21 | CF48CXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206779375 | YORK | YHM48B21 | CU48DXA1+TXV | YP9C080C16MP13 | 28,200 | $1,410 |
| No | 206779374 | YORK | YHM48B21 | CM48DXA1+TXV | YP9C080C16MP13 | 28,200 | $1,410 |
| No | 206779376 | YORK | YHM48B21 | CM48DBCA1 | YP9C080C16MP13 | 28,200 | $1,410 |
| No | 206779373 | YORK | YHM48B21 | CM48DBCA1 | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206779372 | YORK | YHM48B21 | CU48DXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206779371 | YORK | YHM48B21 | CM48DXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206779370 | YORK | YHM48B21 | CM48DBCA1 | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206779367 | YORK | YHM48B21 | CF48DXA1+TXV | YP9C080C16MP13 | 28,200 | $1,410 |
| No | 206779369 | YORK | YHM48B21 | CU48DXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206779368 | YORK | YHM48B21 | CM48DXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206779366 | YORK | YHM48B21 | CF48DXA1+TXV | TP9C080C16MP13 | 28,200 | $1,410 |
| No | 206779365 | YORK | YHM48B21 | CF48DXA1+TXV | TM9V080C16MP12 | 28,200 | $1,410 |
| No | 206779364 | YORK | YHM48B21 | CM64DXA1+TXV | YP9C080C16MP13 | 29,800 | $1,490 |
| No | 206779363 | YORK | YHM48B21 | CM64DXA1+TXV | TP9C080C16MP13 | 29,800 | $1,490 |
| No | 206779362 | YORK | YHM48B21 | CM64DXA1+TXV | TM9V080C16MP12 | 29,800 | $1,490 |
| No | 206779361 | YORK | YHM48B21 | CF64DXA1+TXV | YP9C080C16MP13 | 29,800 | $1,490 |
| No | 206779360 | YORK | YHM48B21 | CF64DXA1+TXV | TP9C080C16MP13 | 29,800 | $1,490 |
| No | 206779359 | YORK | YHM48B21 | CF64DXA1+TXV | TM9V080C16MP12 | 29,800 | $1,490 |
| No | 206779358 | YORK | YHM48B21 | CU48CXA1+TXV | YP9C100C16MP13 | 28,000 | $1,400 |
| No | 206779357 | YORK | YHM48B21 | CM48CBCA1 | YP9C100C16MP13 | 28,000 | $1,400 |
| No | 206779356 | YORK | YHM48B21 | CM48CXA1+TXV | YP9C100C16MP13 | 28,000 | $1,400 |
| No | 202098778 | YORK | YHM48B21 | CF48CBCA1 | YP9C100C16MP13 | 28,000 | $1,400 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206779355 | YORK | YHM48B21 | CU48CXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206779354 | YORK | YHM48B21 | CM48CBCA1 | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 202098768 | YORK | YHM48B21 | CF48CBCA1 | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206779353 | YORK | YHM48B21 | CM48CXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206779352 | YORK | YHM48B21 | CU48CXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206779350 | YORK | YHM48B21 | CM48CXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206779351 | YORK | YHM48B21 | CM48CBCA1 | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 202098758 | YORK | YHM48B21 | CF48CBCA1 | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206779343 | YORK | YHM48B21 | CF48CXA1+TXV | YP9C100C16MP13 | 28,000 | $1,400 |
| No | 206779342 | YORK | YHM48B21 | CF48CXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206779341 | YORK | YHM48B21 | CF48CXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206779340 | YORK | YHM48B21 | CM48DBCA1 | YP9C100C16MP13 | 28,000 | $1,400 |
| No | 206779339 | YORK | YHM48B21 | CU48DXA1+TXV | YP9C100C16MP13 | 28,000 | $1,400 |
| No | 206779338 | YORK | YHM48B21 | CM48DXA1+TXV | YP9C100C16MP13 | 28,000 | $1,400 |
| No | 206779337 | YORK | YHM48B21 | CM48DBCA1 | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206779336 | YORK | YHM48B21 | CU48DXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206779335 | YORK | YHM48B21 | CM48DXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206779334 | YORK | YHM48B21 | CM48DBCA1 | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206779333 | YORK | YHM48B21 | CU48DXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206779331 | YORK | YHM48B21 | CF48DXA1+TXV | YP9C100C16MP13 | 28,000 | $1,400 |
| No | 206779332 | YORK | YHM48B21 | CM48DXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206779330 | YORK | YHM48B21 | CF48DXA1+TXV | TP9C100C16MP13 | 28,000 | $1,400 |
| No | 206779329 | YORK | YHM48B21 | CF48DXA1+TXV | TM9V100C16MP12 | 28,000 | $1,400 |
| No | 206779551 | YORK | YHM48B21 | CM48DBCA1 | YP9C100C20MP13 | 28,200 | $1,410 |
| No | 206779550 | YORK | YHM48B21 | CU48DXA1+TXV | YP9C100C20MP13 | 28,200 | $1,410 |
| No | 206779549 | YORK | YHM48B21 | CM48DXA1+TXV | YP9C100C20MP13 | 28,200 | $1,410 |
| No | 206779548 | YORK | YHM48B21 | CM48DBCA1 | TP9C100C20MP13 | 28,200 | $1,410 |
| No | 206779547 | YORK | YHM48B21 | CU48DXA1+TXV | TP9C100C20MP13 | 28,200 | $1,410 |
| No | 206779546 | YORK | YHM48B21 | CM48DXA1+TXV | TP9C100C20MP13 | 28,200 | $1,410 |
| No | 206779545 | YORK | YHM48B21 | CM48DBCA1 | TM9V100C20MP12 | 28,200 | $1,410 |
| No | 206779543 | YORK | YHM48B21 | CM48DXA1+TXV | TM9V100C20MP12 | 28,200 | $1,410 |
| No | 206779544 | YORK | YHM48B21 | CU48DXA1+TXV | TM9V100C20MP12 | 28,200 | $1,410 |
| No | 206779542 | YORK | YHM48B21 | CF48DXA1+TXV | YP9C100C20MP13 | 28,200 | $1,410 |
| No | 206779541 | YORK | YHM48B21 | CF48DXA1+TXV | TP9C100C20MP13 | 28,200 | $1,410 |
| No | 206779540 | YORK | YHM48B21 | CF48DXA1+TXV | TM9V100C20MP12 | 28,200 | $1,410 |
| No | 206779539 | YORK | YHM48B21 | CM64DXA1+TXV | YP9C120D20MP13 | 29,400 | $1,470 |
| No | 206779538 | YORK | YHM48B21 | CM64DXA1+TXV | TP9C120D20MP13 | 29,400 | $1,470 |
| No | 206779537 | YORK | YHM48B21 | CM64DXA1+TXV | TM9V120D20MP12 | 29,400 | $1,470 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206779536 | YORK | YHM48B21 | CF64DXA1+TXV | YP9C120D20MP13 | 29,400 | $1,470 |
| No | 206779535 | YORK | YHM48B21 | CF64DXA1+TXV | TP9C120D20MP13 | 29,400 | $1,470 |
| No | 206779534 | YORK | YHM48B21 | CF64DXA1+TXV | TM9V120D20MP12 | 29,400 | $1,470 |
| No | 205535860 | YORK | YHM48B21 | CM48DBCA1 | YP9C120D20MP13 | 28,400 | $1,420 |
| No | 205535859 | YORK | YHM48B21 | CU48DXA1+TXV | YP9C120D20MP13 | 28,400 | $1,420 |
| No | 205535858 | YORK | YHM48B21 | CM48DXA1+TXV | YP9C120D20MP13 | 28,400 | $1,420 |
| No | 205535857 | YORK | YHM48B21 | CM48DBCA1 | TP9C120D20MP13 | 28,400 | $1,420 |
| No | 205535855 | YORK | YHM48B21 | CM48DXA1+TXV | TP9C120D20MP13 | 28,400 | $1,420 |
| No | 205535856 | YORK | YHM48B21 | CU48DXA1+TXV | TP9C120D20MP13 | 28,400 | $1,420 |
| No | 205535854 | YORK | YHM48B21 | CM48DBCA1 | TM9V120D20MP12 | 28,400 | $1,420 |
| No | 205535853 | YORK | YHM48B21 | CU48DXA1+TXV | TM9V120D20MP12 | 28,400 | $1,420 |
| No | 205535851 | YORK | YHM48B21 | CF48DXA1+TXV | YP9C120D20MP13 | 28,400 | $1,420 |
| No | 205535852 | YORK | YHM48B21 | CM48DXA1+TXV | TM9V120D20MP12 | 28,400 | $1,420 |
| No | 205535850 | YORK | YHM48B21 | CF48DXA1+TXV | TP9C120D20MP13 | 28,400 | $1,420 |
| No | 205535849 | YORK | YHM48B21 | CF48DXA1+TXV | TM9V120D20MP12 | 28,400 | $1,420 |
| No | 206778927 | YORK | YHM24B21 | CU24BXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |
| No | 202586560 | YORK | YHM24B21 | CM24BBAA1 | TL8E060A12UH11 | 15,200 | $760 |
| No | 206779044 | YORK | YHM24B21 | CM24BXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |
| No | 206778978 | YORK | YHM24B21 | CF24BXA1+TXV | TL8E060A12UH11 | 15,200 | $760 |
| No | 205536727 | YORK | YHM24B21 | CU36BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 202586272 | YORK | YHM24B21 | CF24BBAA1 | TL8E060A12UH11 | 15,200 | $760 |
| No | 202586267 | YORK | YHM24B21 | CM36BBAA1 | TL8E060A12UH11 | 15,100 | $755 |
| No | 205536746 | YORK | YHM24B21 | CM36BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 202586266 | YORK | YHM24B21 | CF36BBAA1 | TL8E060A12UH11 | 15,100 | $755 |
| No | 205536726 | YORK | YHM24B21 | CF36BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205536724 | YORK | YHM24B21 | CU24BXA1+TXV | TL9E060B12UH11 | 15,300 | $765 |
| No | 202586559 | YORK | YHM24B21 | CM24BBAA1 | TL9E060B12UH11 | 15,300 | $765 |
| No | 205536723 | YORK | YHM24B21 | CM24BXA1+TXV | TL9E060B12UH11 | 15,300 | $765 |
| No | 202586264 | YORK | YHM24B21 | CF24BBAA1 | TL9E060B12UH11 | 15,300 | $765 |
| No | 205536721 | YORK | YHM24B21 | CF24BXA1+TXV | TL9E060B12UH11 | 15,300 | $765 |
| No | 206778925 | YORK | YHM24B21 | CU36CXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 206778924 | YORK | YHM24B21 | CM36CXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 206778923 | YORK | YHM24B21 | CF36CXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205536719 | YORK | YHM24B21 | CU30BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 205536718 | YORK | YHM24B21 | CM30BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 203422734 | YORK | YHM24B21 | CM30BBAA1 | TMLE040A12MP11 | 15,100 | $755 |
| No | 203422733 | YORK | YHM24B21 | CF30BBAA1 | TMLE040A12MP11 | 15,100 | $755 |
| No | 205536715 | YORK | YHM24B21 | CU30BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202586248 | YORK | YHM24B21 | CM30BBAA1 | TM8E040A12MP11 | 15,100 | $755 |
| No | 205536714 | YORK | YHM24B21 | CM30BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 205536712 | YORK | YHM24B21 | CF30BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 205536710 | YORK | YHM24B21 | CF30BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 202586247 | YORK | YHM24B21 | CF30BBAA1 | TM8E040A12MP11 | 15,100 | $755 |
| No | 206778916 | YORK | YHM24B21 | CM36AXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 206778915 | YORK | YHM24B21 | CM36AXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 206778914 | YORK | YHM24B21 | CF36AXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 206778913 | YORK | YHM24B21 | CF36AXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 206778912 | YORK | YHM24B21 | CU36BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 203422728 | YORK | YHM24B21 | CM36BBAA1 | TMLE040A12MP11 | 15,100 | $755 |
| No | 203422727 | YORK | YHM24B21 | CF36BBAA1 | TMLE040A12MP11 | 15,100 | $755 |
| No | 206778917 | YORK | YHM24B21 | CM36BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 206778911 | YORK | YHM24B21 | CU36BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 202586244 | YORK | YHM24B21 | CM36BBAA1 | TM8E040A12MP11 | 15,100 | $755 |
| No | 206778910 | YORK | YHM24B21 | CM36BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 202586243 | YORK | YHM24B21 | CF36BBAA1 | TM8E040A12MP11 | 15,100 | $755 |
| No | 206778909 | YORK | YHM24B21 | CF36BXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 206778908 | YORK | YHM24B21 | CF36BXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 205539632 | YORK | YHM24B21 | CM30CXA1+TXV | TMLE100B12MP11 | 15,200 | $760 |
| No | 205539629 | YORK | YHM24B21 | CM30CXA1+TXV | TM8E100B12MP11 | 15,200 | $760 |
| No | 205539628 | YORK | YHM24B21 | CF30CXA1+TXV | TMLE100B12MP11 | 15,200 | $760 |
| No | 205539625 | YORK | YHM24B21 | CF30CXA1+TXV | TM8E100B12MP11 | 15,200 | $760 |
| No | 206371017 | YORK | YHM24B21 | CU24AXA1+TXV | TM9E026A08MP12 | 15,000 | $750 |
| No | 202586554 | YORK | YHM24B21 | CM24ABAA1 | TM9E026A08MP12 | 15,000 | $750 |
| No | 206371015 | YORK | YHM24B21 | CM24AXA1+TXV | TM9E026A08MP12 | 15,000 | $750 |
| No | 202586230 | YORK | YHM24B21 | CF24ABAA1 | TM9E026A08MP12 | 15,000 | $750 |
| No | 206371014 | YORK | YHM24B21 | CF24AXA1+TXV | TM9E026A08MP12 | 15,000 | $750 |
| No | 206371012 | YORK | YHM24B21 | CU30BXA1+TXV | TM9E026A08MP12 | 15,400 | $770 |
| No | 202586224 | YORK | YHM24B21 | CM30BBAA1 | TM9E026A08MP12 | 15,400 | $770 |
| No | 206371010 | YORK | YHM24B21 | CM30BXA1+TXV | TM9E026A08MP12 | 15,400 | $770 |
| No | 202586223 | YORK | YHM24B21 | CF30BBAA1 | TM9E026A08MP12 | 15,400 | $770 |
| No | 206371008 | YORK | YHM24B21 | CF30BXA1+TXV | TM9E026A08MP12 | 15,400 | $770 |
| No | 206778907 | YORK | YHM24B21 | CU24AXA1+TXV | TM9E040A10MP12 | 15,300 | $765 |
| No | 202586552 | YORK | YHM24B21 | CM24ABAA1 | TM9E040A10MP12 | 15,300 | $765 |
| No | 206778906 | YORK | YHM24B21 | CM24AXA1+TXV | TM9E040A10MP12 | 15,300 | $765 |
| No | 202586217 | YORK | YHM24B21 | CF24ABAA1 | TM9E040A10MP12 | 15,300 | $765 |
| No | 205074040 | YORK | YHM24B21 | CM30AXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202586213 | YORK | YHM24B21 | CF30ABAA1 | TM9E040A10MP12 | 15,200 | $760 |
| No | 206778905 | YORK | YHM24B21 | CF24AXA1+TXV | TM9E040A10MP12 | 15,300 | $765 |
| No | 205074039 | YORK | YHM24B21 | CF30AXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205536708 | YORK | YHM24B21 | CM36AXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205536707 | YORK | YHM24B21 | CF36AXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 202586207 | YORK | YHM24B21 | CM36BBAA1 | TM9E040A10MP12 | 15,200 | $760 |
| No | 205536705 | YORK | YHM24B21 | CU36BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205536703 | YORK | YHM24B21 | CM36BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 202586206 | YORK | YHM24B21 | CF36BBAA1 | TM9E040A10MP12 | 15,200 | $760 |
| No | 205536702 | YORK | YHM24B21 | CF36BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205536700 | YORK | YHM24B21 | CU24BXA1+TXV | TM9E060A10MP12 | 15,300 | $765 |
| No | 202586549 | YORK | YHM24B21 | CM24BBAA1 | TM9E060A10MP12 | 15,300 | $765 |
| No | 205536698 | YORK | YHM24B21 | CM24BXA1+TXV | TM9E060A10MP12 | 15,300 | $765 |
| No | 202586202 | YORK | YHM24B21 | CF24BBAA1 | TM9E060A10MP12 | 15,300 | $765 |
| No | 205536696 | YORK | YHM24B21 | CF24BXA1+TXV | TM9E060A10MP12 | 15,300 | $765 |
| No | 205074035 | YORK | YHM24B21 | CM30AXA1+TXV | TM9E060A10MP12 | 15,200 | $760 |
| No | 202586200 | YORK | YHM24B21 | CF30ABAA1 | TM9E060A10MP12 | 15,200 | $760 |
| No | 205074034 | YORK | YHM24B21 | CF30AXA1+TXV | TM9E060A10MP12 | 15,200 | $760 |
| No | 205536694 | YORK | YHM24B21 | CU36BXA1+TXV | TM9E060A10MP12 | 15,200 | $760 |
| No | 202586194 | YORK | YHM24B21 | CM36BBAA1 | TM9E060A10MP12 | 15,200 | $760 |
| No | 202586193 | YORK | YHM24B21 | CF36BBAA1 | TM9E060A10MP12 | 15,200 | $760 |
| No | 205536659 | YORK | YHM24B21 | CF36BXA1+TXV | TM9E060A10MP12 | 15,200 | $760 |
| No | 205536693 | YORK | YHM24B21 | CM36BXA1+TXV | TM9E060A10MP12 | 15,200 | $760 |
| No | 202763637 | YORK | YHM48B21 | AVC60CX22+TXV | | 28,200 | $1,410 |
| No | 202143685 | YORK | YHM48B21 | AE48DBC21 | | 28,200 | $1,410 |
| No | 202143686 | YORK | YHM48B21 | AE48DX21+TXV | | 28,200 | $1,410 |
| No | 206779199 | YORK | YHM48B21 | CM64DXA1+ME14DN21+TXV | | 29,000 | $1,450 |
| No | 206779198 | YORK | YHM48B21 | CF64DXA1+ME14DN21+TXV | | 29,000 | $1,450 |
| No | 205536627 | YORK | YHM48B21 | CU48CXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205536625 | YORK | YHM48B21 | CM48CBCA1 | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 9920303 | YORK | YHM48B21 | CF48CBCA1 | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205536623 | YORK | YHM48B21 | CM48CXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205536684 | YORK | YHM48B21 | CF48CXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205536679 | YORK | YHM48B21 | CM48DBCA1 | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205536678 | YORK | YHM48B21 | CU48DXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205536676 | YORK | YHM48B21 | CM48DXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 205536668 | YORK | YHM48B21 | CF48DXA1+TXV | TM9Y080C16MP11 | 28,600 | $1,430 |
| No | 206779681 | YORK | YHM48B21 | CM64DXA1+TXV | TM9Y080C16MP11 | 29,800 | $1,490 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206779680 | YORK | YHM48B21 | CF64DXA1+TXV | TM9Y080C16MP11 | 29,800 | $1,490 |
| No | 9060330 | YORK | YHM24B21 | AE30BX21+TXV | | 14,800 | $740 |
| No | 206838914 | YORK | YHM24B21 | CM30BBAA1+ME08BN21 | | 15,100 | $755 |
| No | 206838913 | YORK | YHM24B21 | CM30BXA1+ME08BN21+TXV | | 15,100 | $755 |
| No | 206838912 | YORK | YHM24B21 | CF30BBAA1+ME08BN21 | | 15,100 | $755 |
| No | 206838911 | YORK | YHM24B21 | CF30BXA1+ME08BN21+TXV | | 15,100 | $755 |
| No | 205535870 | YORK | YHM24B21 | CU36BXA1+TXV | TM9Y060B12MP11 | 14,800 | $740 |
| No | 205535869 | YORK | YHM24B21 | CM36BBAA1 | TM9Y060B12MP11 | 14,800 | $740 |
| No | 205535868 | YORK | YHM24B21 | CM36BXA1+TXV | TM9Y060B12MP11 | 14,800 | $740 |
| No | 205535867 | YORK | YHM24B21 | CF36BBAA1 | TM9Y060B12MP11 | 14,800 | $740 |
| No | 205535862 | YORK | YHM24B21 | CF36BXA1+TXV | TM9Y060B12MP11 | 14,800 | $740 |
| No | 9060331 | YORK | YHM24B21 | AVC24BX21+TXV | | 14,800 | $740 |
| No | 9060334 | YORK | YHM24B21 | AVC36CX21+TXV | | 14,600 | $730 |
| No | 9035958 | YORK | YHM60B21 | AVC60DX21+TXV | | 32,000 | $1,600 |
| No | 205536528 | YORK | YHM60B21 | CM64DXA1+TXV | YP9C080C16MP13 | 32,600 | $1,630 |
| No | 205536527 | YORK | YHM60B21 | CM64DXA1+TXV | TP9C080C16MP13 | 32,600 | $1,630 |
| No | 205536525 | YORK | YHM60B21 | CM64DXA1+TXV | TM9V080C16MP12 | 32,600 | $1,630 |
| No | 205536524 | YORK | YHM60B21 | CF64DXA1+TXV | YP9C080C16MP13 | 32,600 | $1,630 |
| No | 205536522 | YORK | YHM60B21 | CF64DXA1+TXV | TP9C080C16MP13 | 32,600 | $1,630 |
| No | 9035726 | YORK | YHM48B21 | AVC60DX21+TXV | | 29,400 | $1,470 |
| No | 205539624 | YORK | YHM24B21 | CU36BXA1+TXV | TMLE100B12MP11 | 15,000 | $750 |
| No | 205536520 | YORK | YHM60B21 | CF64DXA1+TXV | TM9V080C16MP12 | 32,600 | $1,630 |
| No | 205539621 | YORK | YHM24B21 | CM36BXA1+TXV | TMLE100B12MP11 | 15,000 | $750 |
| No | 203422705 | YORK | YHM24B21 | CM36BBAA1 | TMLE100B12MP11 | 15,000 | $750 |
| No | 205539619 | YORK | YHM24B21 | CU36BXA1+TXV | TM8E100B12MP11 | 15,000 | $750 |
| No | 203422704 | YORK | YHM24B21 | CF36BBAA1 | TMLE100B12MP11 | 15,000 | $750 |
| No | 202586233 | YORK | YHM24B21 | CM36BBAA1 | TM8E100B12MP11 | 15,000 | $750 |
| No | 205539617 | YORK | YHM24B21 | CM36BXA1+TXV | TM8E100B12MP11 | 15,000 | $750 |
| No | 202586232 | YORK | YHM24B21 | CF36BBAA1 | TM8E100B12MP11 | 15,000 | $750 |
| No | 205539615 | YORK | YHM24B21 | CF36BXA1+TXV | TMLE100B12MP11 | 15,000 | $750 |
| No | 205539613 | YORK | YHM24B21 | CF36BXA1+TXV | TM8E100B12MP11 | 15,000 | $750 |
| No | 203064060 | YORK | YHM36B22 | AE36BX21+TXV | | 22,200 | $1,110 |
| No | 205538646 | YORK | YHM24B21 | CU30BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 202586270 | YORK | YHM24B21 | CM30BBAA1 | TL8E060A12UH11 | 15,100 | $755 |
| No | 205538653 | YORK | YHM24B21 | CM30BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 202586269 | YORK | YHM24B21 | CF30BBAA1 | TL8E060A12UH11 | 15,100 | $755 |
| No | 205538644 | YORK | YHM24B21 | CF30BXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205538643 | YORK | YHM24B21 | CU30BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 202586262 | YORK | YHM24B21 | CM30BBAA1 | TL9E060B12UH11 | 15,200 | $760 |
| No | 205538642 | YORK | YHM24B21 | CM30BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 202586261 | YORK | YHM24B21 | CF30BBAA1 | TL9E060B12UH11 | 15,200 | $760 |
| No | 205538640 | YORK | YHM24B21 | CF30BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205538636 | YORK | YHM24B21 | CF30CXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205538638 | YORK | YHM24B21 | CM30CXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 205538635 | YORK | YHM24B21 | CU36BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 202586258 | YORK | YHM24B21 | CM36BBAA1 | TL9E060B12UH11 | 15,200 | $760 |
| No | 205538633 | YORK | YHM24B21 | CM36BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 202586257 | YORK | YHM24B21 | CF36BBAA1 | TL9E060B12UH11 | 15,200 | $760 |
| No | 205538632 | YORK | YHM24B21 | CF36BXA1+TXV | TL9E060B12UH11 | 15,200 | $760 |
| No | 206778922 | YORK | YHM24B21 | CU24AXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |
| No | 203422747 | YORK | YHM24B21 | CM24ABAA1 | TMLE040A12MP11 | 15,200 | $760 |
| No | 206778926 | YORK | YHM24B21 | CM24AXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |
| No | 203422748 | YORK | YHM24B21 | CF24ABAA1 | TMLE040A12MP11 | 15,200 | $760 |
| No | 206778921 | YORK | YHM24B21 | CU24AXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 202586558 | YORK | YHM24B21 | CM24ABAA1 | TM8E040A12MP11 | 15,200 | $760 |
| No | 206778920 | YORK | YHM24B21 | CM24AXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 202586254 | YORK | YHM24B21 | CF24ABAA1 | TM8E040A12MP11 | 15,200 | $760 |
| No | 206778919 | YORK | YHM24B21 | CF24AXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |
| No | 206778918 | YORK | YHM24B21 | CF24AXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 205538630 | YORK | YHM24B21 | CU24BXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |
| No | 203422742 | YORK | YHM24B21 | CM24BBAA1 | TMLE040A12MP11 | 15,200 | $760 |
| No | 205538629 | YORK | YHM24B21 | CM24BXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |
| No | 203422743 | YORK | YHM24B21 | CF24BBAA1 | TMLE040A12MP11 | 15,200 | $760 |
| No | 205538628 | YORK | YHM24B21 | CU24BXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 202586557 | YORK | YHM24B21 | CM24BBAA1 | TM8E040A12MP11 | 15,200 | $760 |
| No | 205538626 | YORK | YHM24B21 | CM24BXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 202586252 | YORK | YHM24B21 | CF24BBAA1 | TM8E040A12MP11 | 15,200 | $760 |
| No | 205538623 | YORK | YHM24B21 | CF24BXA1+TXV | TMLE040A12MP11 | 15,200 | $760 |
| No | 205538621 | YORK | YHM24B21 | CF24BXA1+TXV | TM8E040A12MP11 | 15,200 | $760 |
| No | 205074011 | YORK | YHM24B21 | CM30AXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 203422738 | YORK | YHM24B21 | CF30ABAA1 | TMLE040A12MP11 | 15,100 | $755 |
| No | 202586250 | YORK | YHM24B21 | CF30ABAA1 | TM8E040A12MP11 | 15,100 | $755 |
| No | 205074048 | YORK | YHM24B21 | CM30AXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 205074047 | YORK | YHM24B21 | CF30AXA1+TXV | TMLE040A12MP11 | 15,100 | $755 |
| No | 205074045 | YORK | YHM24B21 | CF30AXA1+TXV | TM8E040A12MP11 | 15,100 | $755 |
| No | 205537479 | YORK | YHM24B21 | CU24BXA1+TXV | TMLE080B12MP11 | 15,200 | $760 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203422721 | YORK | YHM24B21 | CM24BBAA1 | TMLE080B12MP11 | 15,200 | $760 |
| No | 205537459 | YORK | YHM24B21 | CM24BXA1+TXV | TMLE080B12MP11 | 15,200 | $760 |
| No | 203422723 | YORK | YHM24B21 | CF24BBAA1 | TMLE080B12MP11 | 15,200 | $760 |
| No | 205537457 | YORK | YHM24B21 | CU24BXA1+TXV | TM8E080B12MP11 | 15,200 | $760 |
| No | 202586556 | YORK | YHM24B21 | CM24BBAA1 | TM8E080B12MP11 | 15,200 | $760 |
| No | 205537454 | YORK | YHM24B21 | CM24BXA1+TXV | TM8E080B12MP11 | 15,200 | $760 |
| No | 202586241 | YORK | YHM24B21 | CF24BBAA1 | TM8E080B12MP11 | 15,200 | $760 |
| No | 205537450 | YORK | YHM24B21 | CF24BXA1+TXV | TMLE080B12MP11 | 15,200 | $760 |
| No | 205537449 | YORK | YHM24B21 | CF24BXA1+TXV | TM8E080B12MP11 | 15,200 | $760 |
| No | 205537447 | YORK | YHM24B21 | CU24BXA1+TXV | TMLE100B12MP11 | 15,100 | $755 |
| No | 203422715 | YORK | YHM24B21 | CM24BBAA1 | TMLE100B12MP11 | 15,100 | $755 |
| No | 205537452 | YORK | YHM24B21 | CM24BXA1+TXV | TMLE100B12MP11 | 15,100 | $755 |
| No | 203422718 | YORK | YHM24B21 | CF24BBAA1 | TMLE100B12MP11 | 15,100 | $755 |
| No | 205537443 | YORK | YHM24B21 | CU24BXA1+TXV | TM8E100B12MP11 | 15,100 | $755 |
| No | 202586555 | YORK | YHM24B21 | CM24BBAA1 | TM8E100B12MP11 | 15,100 | $755 |
| No | 205537441 | YORK | YHM24B21 | CM24BXA1+TXV | TM8E100B12MP11 | 15,100 | $755 |
| No | 202586239 | YORK | YHM24B21 | CF24BBAA1 | TM8E100B12MP11 | 15,100 | $755 |
| No | 205537321 | YORK | YHM24B21 | CF24BXA1+TXV | TMLE100B12MP11 | 15,100 | $755 |
| No | 205537320 | YORK | YHM24B21 | CF24BXA1+TXV | TM8E100B12MP11 | 15,100 | $755 |
| No | 205539640 | YORK | YHM24B21 | CU30BXA1+TXV | TMLE100B12MP11 | 15,200 | $760 |
| No | 203422713 | YORK | YHM24B21 | CM30BBAA1 | TMLE100B12MP11 | 15,200 | $760 |
| No | 205539649 | YORK | YHM24B21 | CM30BXA1+TXV | TMLE100B12MP11 | 15,200 | $760 |
| No | 203422710 | YORK | YHM24B21 | CF30BBAA1 | TMLE100B12MP11 | 15,200 | $760 |
| No | 205539638 | YORK | YHM24B21 | CU30BXA1+TXV | TM8E100B12MP11 | 15,200 | $760 |
| No | 205539636 | YORK | YHM24B21 | CM30BXA1+TXV | TM8E100B12MP11 | 15,200 | $760 |
| No | 202586236 | YORK | YHM24B21 | CF30BBAA1 | TM8E100B12MP11 | 15,200 | $760 |
| No | 202586237 | YORK | YHM24B21 | CM30BBAA1 | TM8E100B12MP11 | 15,200 | $760 |
| No | 205539634 | YORK | YHM24B21 | CF30BXA1+TXV | TMLE100B12MP11 | 15,200 | $760 |
| No | 205539633 | YORK | YHM24B21 | CF30BXA1+TXV | TM8E100B12MP11 | 15,200 | $760 |
| No | 206370889 | YORK | YHM24B21 | CU24BXA1+TXV | TM9E026A08MP12 | 15,600 | $780 |
| No | 202586553 | YORK | YHM24B21 | CM24BBAA1 | TM9E026A08MP12 | 15,600 | $780 |
| No | 206370887 | YORK | YHM24B21 | CM24BXA1+TXV | TM9E026A08MP12 | 15,600 | $780 |
| No | 202586228 | YORK | YHM24B21 | CF24BBAA1 | TM9E026A08MP12 | 15,600 | $780 |
| No | 206370885 | YORK | YHM24B21 | CF24BXA1+TXV | TM9E026A08MP12 | 15,600 | $780 |
| No | 206370883 | YORK | YHM24B21 | CM30AXA1+TXV | TM9E026A08MP12 | 14,800 | $740 |
| No | 202586226 | YORK | YHM24B21 | CF30ABAA1 | TM9E026A08MP12 | 14,800 | $740 |
| No | 206370881 | YORK | YHM24B21 | CF30AXA1+TXV | TM9E026A08MP12 | 14,800 | $740 |
| No | 206370879 | YORK | YHM24B21 | CM36AXA1+TXV | TM9E026A08MP12 | 14,900 | $745 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206370878 | YORK | YHM24B21 | CF36AXA1+TXV | TM9E026A08MP12 | 14,900 | $745 |
| No | 206370876 | YORK | YHM24B21 | CU36BXA1+TXV | TM9E026A08MP12 | 14,900 | $745 |
| No | 202586220 | YORK | YHM24B21 | CM36BBAA1 | TM9E026A08MP12 | 14,900 | $745 |
| No | 206370874 | YORK | YHM24B21 | CM36BXA1+TXV | TM9E026A08MP12 | 14,900 | $745 |
| No | 202586219 | YORK | YHM24B21 | CF36BBAA1 | TM9E026A08MP12 | 14,900 | $745 |
| No | 206370872 | YORK | YHM24B21 | CF36BXA1+TXV | TM9E026A08MP12 | 14,900 | $745 |
| No | 205538619 | YORK | YHM24B21 | CU24BXA1+TXV | TM9E040A10MP12 | 15,400 | $770 |
| No | 202586551 | YORK | YHM24B21 | CM24BBAA1 | TM9E040A10MP12 | 15,400 | $770 |
| No | 205538624 | YORK | YHM24B21 | CM24BXA1+TXV | TM9E040A10MP12 | 15,400 | $770 |
| No | 202586215 | YORK | YHM24B21 | CF24BBAA1 | TM9E040A10MP12 | 15,400 | $770 |
| No | 205538618 | YORK | YHM24B21 | CF24BXA1+TXV | TM9E040A10MP12 | 15,400 | $770 |
| No | 205538617 | YORK | YHM24B21 | CU30BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 202586211 | YORK | YHM24B21 | CM30BBAA1 | TM9E040A10MP12 | 15,200 | $760 |
| No | 205538615 | YORK | YHM24B21 | CM30BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 202586210 | YORK | YHM24B21 | CF30BBAA1 | TM9E040A10MP12 | 15,200 | $760 |
| No | 205538613 | YORK | YHM24B21 | CF30BXA1+TXV | TM9E040A10MP12 | 15,200 | $760 |
| No | 205538612 | YORK | YHM24B21 | CU24AXA1+TXV | TM9E060A10MP12 | 15,400 | $770 |
| No | 202586550 | YORK | YHM24B21 | CM24ABAA1 | TM9E060A10MP12 | 15,400 | $770 |
| No | 205538610 | YORK | YHM24B21 | CM24AXA1+TXV | TM9E060A10MP12 | 15,400 | $770 |
| No | 202586204 | YORK | YHM24B21 | CF24ABAA1 | TM9E060A10MP12 | 15,400 | $770 |
| No | 205538608 | YORK | YHM24B21 | CF24AXA1+TXV | TM9E060A10MP12 | 15,400 | $770 |
| No | 205538606 | YORK | YHM24B21 | CU30BXA1+TXV | TM9E060A10MP12 | 15,100 | $755 |
| No | 202586198 | YORK | YHM24B21 | CM30BBAA1 | TM9E060A10MP12 | 15,100 | $755 |
| No | 205538605 | YORK | YHM24B21 | CM30BXA1+TXV | TM9E060A10MP12 | 15,100 | $755 |
| No | 202586197 | YORK | YHM24B21 | CF30BBAA1 | TM9E060A10MP12 | 15,100 | $755 |
| No | 205538603 | YORK | YHM24B21 | CF30BXA1+TXV | TM9E060A10MP12 | 15,100 | $755 |
| No | 205538602 | YORK | YHM24B21 | CM36AXA1+TXV | TM9E060A10MP12 | 15,100 | $755 |
| No | 205538600 | YORK | YHM24B21 | CF36AXA1+TXV | TM9E060A10MP12 | 15,100 | $755 |
| No | 206778797 | YORK | YHM24B21 | CM36BBAA1+ME08BN21 | | 15,000 | $750 |
| No | 206778796 | YORK | YHM24B21 | CM36BXA1+ME08BN21+TXV | | 15,000 | $750 |
| No | 206778795 | YORK | YHM24B21 | CF36BBAA1+ME08BN21 | | 15,000 | $750 |
| No | 206778794 | YORK | YHM24B21 | CF36BXA1+ME08BN21+TXV | | 15,000 | $750 |
| No | 9060332 | YORK | YHM24B21 | AVC30BX21+TXV | | 15,100 | $755 |
| No | 9060333 | YORK | YHM24B21 | AVC36BX21+TXV | | 15,000 | $750 |
| No | 205538496 | YORK | YHM60B21 | CM64DXA1+MVC20DN21+TXV | | 32,600 | $1,630 |
| No | 205538494 | YORK | YHM60B21 | CF64DXA1+MVC20DN21+TXV | | 32,600 | $1,630 |
| No | 205538490 | YORK | YHM60B21 | CM64DXA1+TXV | YPLC100C20MP13 | 32,400 | $1,620 |
| No | 205538488 | YORK | YHM60B21 | CM64DXA1+TXV | TPLC120C20MP13 | 32,400 | $1,620 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205538492 | YORK | YHM60B21 | CM64DXA1+TXV | YPLC120C20MP13 | 32,400 | $1,620 |
| No | 205538486 | YORK | YHM60B21 | CM64DXA1+TXV | TPLC100C20MP13 | 32,400 | $1,620 |
| No | 205538484 | YORK | YHM60B21 | CM64DXA1+TXV | TMLV120C20MP12 | 32,400 | $1,620 |
| No | 205538479 | YORK | YHM60B21 | CM64DXA1+TXV | TM8V120C20MP12 | 32,400 | $1,620 |
| No | 205538478 | YORK | YHM60B21 | CF64DXA1+TXV | YPLC120C20MP13 | 32,400 | $1,620 |
| No | 205538476 | YORK | YHM60B21 | CF64DXA1+TXV | YPLC100C20MP13 | 32,400 | $1,620 |
| No | 205538481 | YORK | YHM60B21 | CM64DXA1+TXV | TM8V100C20MP12 | 32,400 | $1,620 |
| No | 205538474 | YORK | YHM60B21 | CF64DXA1+TXV | TPLC120C20MP13 | 32,400 | $1,620 |
| No | 205538472 | YORK | YHM60B21 | CF64DXA1+TXV | TPLC100C20MP13 | 32,400 | $1,620 |
| No | 205538470 | YORK | YHM60B21 | CF64DXA1+TXV | TMLV120C20MP12 | 32,400 | $1,620 |
| No | 205538464 | YORK | YHM60B21 | CF64DXA1+TXV | TM8V120C20MP12 | 32,400 | $1,620 |
| No | 205538466 | YORK | YHM60B21 | CF64DXA1+TXV | TM8V100C20MP12 | 32,400 | $1,620 |
| No | 203423021 | YORK | YHM48B21 | CM48DBCA1 | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205538380 | YORK | YHM48B21 | CU48DXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205538379 | YORK | YHM48B21 | CM48DXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 202586482 | YORK | YHM48B21 | CM48DBCA1 | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 205538353 | YORK | YHM48B21 | CU48DXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 205538352 | YORK | YHM48B21 | CM48DXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 205538351 | YORK | YHM48B21 | CF48DXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205538349 | YORK | YHM48B21 | CF48DXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 9100301 | YORK | YHM48B21 | AE48CBC21 | | 28,400 | $1,420 |
| No | 9006236 | YORK | YHM48B21 | AE48CX21+TXV | | 28,400 | $1,420 |
| No | 9854428 | YORK | YHM24B21 | AE24BBA21 | | 15,100 | $755 |
| No | 205539611 | YORK | YHM36B22 | CM36AXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 9006267 | YORK | YHM24B21 | AE24BX21+TXV | | 15,100 | $755 |
| No | 205539608 | YORK | YHM36B22 | CF36AXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 205539607 | YORK | YHM36B22 | CU36BXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 203112651 | YORK | YHM36B22 | CM36BBCA1 | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 205539616 | YORK | YHM36B22 | CM36BXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 203112647 | YORK | YHM36B22 | CF36BBCA1 | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 205539605 | YORK | YHM36B22 | CF36BXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 205539603 | YORK | YHM36B22 | CF42BXA1+TXV | TL8E060A12UH11 | 22,400 | $1,120 |
| No | 205539601 | YORK | YHM36B22 | CU42CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 203112609 | YORK | YHM36B22 | CM42CBCA1 | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205539599 | YORK | YHM36B22 | CM42CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 203112605 | YORK | YHM36B22 | CF42CBCA1 | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205539598 | YORK | YHM36B22 | CF42CXA1+TXV | TL9E060B12UH11 | 22,600 | $1,130 |
| No | 205539595 | YORK | YHM36B22 | CU48CXA1+TXV | TL9E060B12UH11 | 22,400 | $1,120 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203112598 | YORK | YHM36B22 | CM48CBCA1 | TL9E060B12UH11 | 22,400 | $1,120 |
| No | 205539593 | YORK | YHM36B22 | CM48CXA1+TXV | TL9E060B12UH11 | 22,400 | $1,120 |
| No | 203112595 | YORK | YHM36B22 | CF48CBCA1 | TL9E060B12UH11 | 22,400 | $1,120 |
| No | 205539591 | YORK | YHM36B22 | CF48CXA1+TXV | TL9E060B12UH11 | 22,400 | $1,120 |
| No | 205539590 | YORK | YHM36B22 | CU36CXA1+TXV | TL9E080C16UH11 | 22,600 | $1,130 |
| No | 203112587 | YORK | YHM36B22 | CM36CBCA1 | TL9E080C16UH11 | 22,600 | $1,130 |
| No | 205539588 | YORK | YHM36B22 | CM36CXA1+TXV | TL9E080C16UH11 | 22,600 | $1,130 |
| No | 205539586 | YORK | YHM36B22 | CF36CXA1+TXV | TL9E080C16UH11 | 22,600 | $1,130 |
| No | 205539585 | YORK | YHM36B22 | CU42CXA1+TXV | TL9E080C16UH11 | 22,800 | $1,140 |
| No | 203112579 | YORK | YHM36B22 | CM42CBCA1 | TL9E080C16UH11 | 22,800 | $1,140 |
| No | 205539582 | YORK | YHM36B22 | CM42CXA1+TXV | TL9E080C16UH11 | 22,800 | $1,140 |
| No | 203112577 | YORK | YHM36B22 | CF42CBCA1 | TL9E080C16UH11 | 22,800 | $1,140 |
| No | 205539578 | YORK | YHM36B22 | CF42CXA1+TXV | TL9E080C16UH11 | 22,800 | $1,140 |
| No | 205539577 | YORK | YHM36B22 | CM36AXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205539575 | YORK | YHM36B22 | CM36AXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205539574 | YORK | YHM36B22 | CF36AXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205539570 | YORK | YHM36B22 | CF36AXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205539567 | YORK | YHM36B22 | CU36BXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 203422991 | YORK | YHM36B22 | CM36BBCA1 | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205539581 | YORK | YHM36B22 | CM36BXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 203422990 | YORK | YHM36B22 | CF36BBCA1 | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205539564 | YORK | YHM36B22 | CU36BXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 203112544 | YORK | YHM36B22 | CM36BBCA1 | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205539561 | YORK | YHM36B22 | CM36BXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 203112540 | YORK | YHM36B22 | CF36BBCA1 | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205539558 | YORK | YHM36B22 | CF36BXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205539556 | YORK | YHM36B22 | CF36BXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205539553 | YORK | YHM36B22 | CF42BXA1+TXV | TMLE040A12MP11 | 22,400 | $1,120 |
| No | 205539549 | YORK | YHM36B22 | CF42BXA1+TXV | TM8E040A12MP11 | 22,400 | $1,120 |
| No | 205539547 | YORK | YHM36B22 | CU36CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 203422967 | YORK | YHM36B22 | CM36CBCA1 | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205539545 | YORK | YHM36B22 | CM36CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 203112495 | YORK | YHM36B22 | CM36CBCA1 | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205539539 | YORK | YHM36B22 | CM36CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205539543 | YORK | YHM36B22 | CU36CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205539537 | YORK | YHM36B22 | CF36CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205539535 | YORK | YHM36B22 | CF36CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205539533 | YORK | YHM36B22 | CF42BXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205539532 | YORK | YHM36B22 | CF42BXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205539530 | YORK | YHM36B22 | CU42CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 203422961 | YORK | YHM36B22 | CM42CBCA1 | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205539541 | YORK | YHM36B22 | CM42CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 203422960 | YORK | YHM36B22 | CF42CBCA1 | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205539528 | YORK | YHM36B22 | CU42CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205539526 | YORK | YHM36B22 | CM42CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 203112481 | YORK | YHM36B22 | CM42CBCA1 | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 203112477 | YORK | YHM36B22 | CF42CBCA1 | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 205539524 | YORK | YHM36B22 | CF42CXA1+TXV | TMLE080B12MP11 | 22,400 | $1,120 |
| No | 205539522 | YORK | YHM36B22 | CF42CXA1+TXV | TM8E080B12MP11 | 22,400 | $1,120 |
| No | 206779068 | YORK | YHM36B22 | CU48CXA1+TXV | TMLE080B12MP11 | 22,200 | $1,110 |
| No | 203422958 | YORK | YHM36B22 | CM48CBCA1 | TMLE080B12MP11 | 22,200 | $1,110 |
| No | 206779067 | YORK | YHM36B22 | CM48CXA1+TXV | TMLE080B12MP11 | 22,200 | $1,110 |
| No | 203422955 | YORK | YHM36B22 | CF48CBCA1 | TMLE080B12MP11 | 22,200 | $1,110 |
| No | 206779066 | YORK | YHM36B22 | CU48CXA1+TXV | TM8E080B12MP11 | 22,200 | $1,110 |
| No | 203112470 | YORK | YHM36B22 | CM48CBCA1 | TM8E080B12MP11 | 22,200 | $1,110 |
| No | 206779065 | YORK | YHM36B22 | CM48CXA1+TXV | TM8E080B12MP11 | 22,200 | $1,110 |
| No | 203112467 | YORK | YHM36B22 | CF48CBCA1 | TM8E080B12MP11 | 22,200 | $1,110 |
| No | 206779064 | YORK | YHM36B22 | CF48CXA1+TXV | TMLE080B12MP11 | 22,200 | $1,110 |
| No | 206779063 | YORK | YHM36B22 | CF48CXA1+TXV | TM8E080B12MP11 | 22,200 | $1,110 |
| No | 203422934 | YORK | YHM36B22 | CM48DBCA1 | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205539521 | YORK | YHM36B22 | CU48DXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205539518 | YORK | YHM36B22 | CM48DXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205539516 | YORK | YHM36B22 | CU48DXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 203112444 | YORK | YHM36B22 | CM48DBCA1 | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205539514 | YORK | YHM36B22 | CM48DXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205539512 | YORK | YHM36B22 | CF48DXA1+TXV | TMLE080C16MP11 | 22,200 | $1,110 |
| No | 205539509 | YORK | YHM36B22 | CF48DXA1+TXV | TM8E080C16MP11 | 22,200 | $1,110 |
| No | 205539507 | YORK | YHM36B22 | CU36CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 203422925 | YORK | YHM36B22 | CM36CBCA1 | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205539505 | YORK | YHM36B22 | CM36CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205539502 | YORK | YHM36B22 | CU36CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 203112434 | YORK | YHM36B22 | CM36CBCA1 | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205539491 | YORK | YHM36B22 | CM36CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205539486 | YORK | YHM36B22 | CF36CXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205539489 | YORK | YHM36B22 | CF36CXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |
| No | 205539483 | YORK | YHM36B22 | CF42BXA1+TXV | TMLE100B12MP11 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205539480 | YORK | YHM36B22 | CF42BXA1+TXV | TM8E100B12MP11 | 22,400 | $1,120 |
| No | 205539478 | YORK | YHM36B22 | CM42DXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205539475 | YORK | YHM36B22 | CM42DXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205539473 | YORK | YHM36B22 | CF42DXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205539469 | YORK | YHM36B22 | CF42DXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205539467 | YORK | YHM36B22 | CU48CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 203422899 | YORK | YHM36B22 | CM48CBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205539501 | YORK | YHM36B22 | CM48CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 203422898 | YORK | YHM36B22 | CF48CBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205539497 | YORK | YHM36B22 | CU48CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203112402 | YORK | YHM36B22 | CM48CBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205539494 | YORK | YHM36B22 | CM48CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203112400 | YORK | YHM36B22 | CF48CBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205539463 | YORK | YHM36B22 | CF48CXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205539462 | YORK | YHM36B22 | CF48CXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203422896 | YORK | YHM36B22 | CM48DBCA1 | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205539459 | YORK | YHM36B22 | CU48DXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205539456 | YORK | YHM36B22 | CM48DXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205539453 | YORK | YHM36B22 | CU48DXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 203112395 | YORK | YHM36B22 | CM48DBCA1 | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205539450 | YORK | YHM36B22 | CM48DXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205539446 | YORK | YHM36B22 | CF48DXA1+TXV | TM8E100C16MP11 | 22,200 | $1,110 |
| No | 205539447 | YORK | YHM36B22 | CF48DXA1+TXV | TMLE100C16MP11 | 22,200 | $1,110 |
| No | 205539444 | YORK | YHM36B22 | CU36CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 203422892 | YORK | YHM36B22 | CM36CBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 205539442 | YORK | YHM36B22 | CM36CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 205539441 | YORK | YHM36B22 | CU36CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 203112391 | YORK | YHM36B22 | CM36CBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 205539436 | YORK | YHM36B22 | CM36CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 205539434 | YORK | YHM36B22 | CF36CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 205539432 | YORK | YHM36B22 | CF36CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206779061 | YORK | YHM36B22 | CU42CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 203422888 | YORK | YHM36B22 | CM42CBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206779062 | YORK | YHM36B22 | CM42CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206779060 | YORK | YHM36B22 | CU42CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 203422887 | YORK | YHM36B22 | CF42CBCA1 | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 203112387 | YORK | YHM36B22 | CM42CBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206779059 | YORK | YHM36B22 | CM42CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203112385 | YORK | YHM36B22 | CF42CBCA1 | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 206779058 | YORK | YHM36B22 | CF42CXA1+TXV | TMLE120C16MP11 | 22,200 | $1,110 |
| No | 206779057 | YORK | YHM36B22 | CF42CXA1+TXV | TM8E120C16MP11 | 22,200 | $1,110 |
| No | 205539431 | YORK | YHM36B22 | CU36BXA1+TXV | YPLC080B12MP13 | 22,800 | $1,140 |
| No | 203112329 | YORK | YHM36B22 | CM36BBCA1 | YPLC080B12MP13 | 22,800 | $1,140 |
| No | 205539438 | YORK | YHM36B22 | CM36BXA1+TXV | YPLC080B12MP13 | 22,800 | $1,140 |
| No | 203112320 | YORK | YHM36B22 | CF36BBCA1 | YPLC080B12MP13 | 22,800 | $1,140 |
| No | 205539430 | YORK | YHM36B22 | CU36BXA1+TXV | TPLC080B12MP13 | 22,800 | $1,140 |
| No | 203112326 | YORK | YHM36B22 | CM36BBCA1 | TPLC080B12MP13 | 22,800 | $1,140 |
| No | 205539427 | YORK | YHM36B22 | CM36BXA1+TXV | TPLC080B12MP13 | 22,800 | $1,140 |
| No | 203112317 | YORK | YHM36B22 | CF36BBCA1 | TPLC080B12MP13 | 22,800 | $1,140 |
| No | 205539420 | YORK | YHM36B22 | CU36BXA1+TXV | TM8V080B12MP12 | 22,800 | $1,140 |
| No | 203112323 | YORK | YHM36B22 | CM36BBCA1 | TM8V080B12MP12 | 22,800 | $1,140 |
| No | 205539417 | YORK | YHM36B22 | CM36BXA1+TXV | TM8V080B12MP12 | 22,800 | $1,140 |
| No | 203112314 | YORK | YHM36B22 | CF36BBCA1 | TM8V080B12MP12 | 22,800 | $1,140 |
| No | 205539415 | YORK | YHM36B22 | CF36BXA1+TXV | YPLC080B12MP13 | 22,800 | $1,140 |
| No | 205539413 | YORK | YHM36B22 | CF36BXA1+TXV | TPLC080B12MP13 | 22,800 | $1,140 |
| No | 205539409 | YORK | YHM36B22 | CF36BXA1+TXV | TM8V080B12MP12 | 22,800 | $1,140 |
| No | 205539408 | YORK | YHM36B22 | CU36BXA1+TXV | TM9E060A10MP12 | 23,000 | $1,150 |
| No | 203112302 | YORK | YHM36B22 | CM36BBCA1 | TM9E060A10MP12 | 23,000 | $1,150 |
| No | 205539406 | YORK | YHM36B22 | CM36BXA1+TXV | TM9E060A10MP12 | 23,000 | $1,150 |
| No | 203112300 | YORK | YHM36B22 | CF36BBCA1 | TM9E060A10MP12 | 23,000 | $1,150 |
| No | 205539400 | YORK | YHM36B22 | CF36BXA1+TXV | TM9E060A10MP12 | 23,000 | $1,150 |
| No | 205539398 | YORK | YHM36B22 | CF42BXA1+TXV | TM9E060A10MP12 | 22,600 | $1,130 |
| No | 205539397 | YORK | YHM36B22 | CU36BXA1+TXV | TM9E060B12MP12 | 22,400 | $1,120 |
| No | 203112292 | YORK | YHM36B22 | CM36BBCA1 | TM9E060B12MP12 | 22,400 | $1,120 |
| No | 205539403 | YORK | YHM36B22 | CM36BXA1+TXV | TM9E060B12MP12 | 22,400 | $1,120 |
| No | 203112290 | YORK | YHM36B22 | CF36BBCA1 | TM9E060B12MP12 | 22,400 | $1,120 |
| No | 205539395 | YORK | YHM36B22 | CF36BXA1+TXV | TM9E060B12MP12 | 22,400 | $1,120 |
| No | 205539393 | YORK | YHM36B22 | CU36CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 203112286 | YORK | YHM36B22 | CM36CBCA1 | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205539391 | YORK | YHM36B22 | CM36CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205539389 | YORK | YHM36B22 | CF36CXA1+TXV | TM9E060B12MP12 | 22,600 | $1,130 |
| No | 205539388 | YORK | YHM36B22 | CU36CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203112260 | YORK | YHM36B22 | CM36CBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205539387 | YORK | YHM36B22 | CM36CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205539385 | YORK | YHM36B22 | CF36CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205539383 | YORK | YHM36B22 | CF42BXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205539381 | YORK | YHM36B22 | CU42CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203112252 | YORK | YHM36B22 | CM42CBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205539392 | YORK | YHM36B22 | CM42CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203112250 | YORK | YHM36B22 | CF42CBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205539379 | YORK | YHM36B22 | CF42CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205539378 | YORK | YHM36B22 | CU48CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203112246 | YORK | YHM36B22 | CM48CBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203112244 | YORK | YHM36B22 | CF48CBCA1 | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205539377 | YORK | YHM36B22 | CM48CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 205539376 | YORK | YHM36B22 | CF48CXA1+TXV | TM9E080B12MP12 | 22,400 | $1,120 |
| No | 203112222 | YORK | YHM36B22 | CM48DBCA1 | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 206779056 | YORK | YHM36B22 | CU48DXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 206779055 | YORK | YHM36B22 | CM48DXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 206779054 | YORK | YHM36B22 | CF48DXA1+TXV | TM9E080C16MP12 | 22,200 | $1,110 |
| No | 205539374 | YORK | YHM36B22 | CU36CXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 203112218 | YORK | YHM36B22 | CM36CBCA1 | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205539371 | YORK | YHM36B22 | CM36CXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205539370 | YORK | YHM36B22 | CF36CXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205539369 | YORK | YHM36B22 | CU42CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 203112214 | YORK | YHM36B22 | CM42CBCA1 | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 205539372 | YORK | YHM36B22 | CM42CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 203112211 | YORK | YHM36B22 | CF42CBCA1 | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 205539366 | YORK | YHM36B22 | CF42CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 205539365 | YORK | YHM36B22 | CM42DXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205539363 | YORK | YHM36B22 | CF42DXA1+TXV | TM9E100C16MP12 | 22,600 | $1,130 |
| No | 205539361 | YORK | YHM36B22 | CU48CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 203112205 | YORK | YHM36B22 | CM48CBCA1 | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 205539360 | YORK | YHM36B22 | CM48CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 205539359 | YORK | YHM36B22 | CF48CXA1+TXV | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 205539357 | YORK | YHM36B22 | CU36BXA1+TXV | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 203112203 | YORK | YHM36B22 | CF48CBCA1 | TM9E100C16MP12 | 22,200 | $1,110 |
| No | 203112188 | YORK | YHM36B22 | CM36BBCA1 | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 205539355 | YORK | YHM36B22 | CM36BXA1+TXV | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 203112183 | YORK | YHM36B22 | CF36BBCA1 | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 205539346 | YORK | YHM36B22 | CF36BXA1+TXV | TM9Y060B12MP11 | 22,600 | $1,130 |
| No | 205539343 | YORK | YHM36B22 | CF42BXA1+TXV | TM8Y080B12MP11 | 22,200 | $1,110 |
| No | 205539337 | YORK | YHM36B22 | CU36CXA1+TXV | TM8Y100C20MP11 | 22,400 | $1,120 |
| No | 203112159 | YORK | YHM36B22 | CM36CBCA1 | TM8Y100C20MP11 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205539350 | YORK | YHM36B22 | CM36CXA1+TXV | TM8Y100C20MP11 | 22,400 | $1,120 |
| No | 205539348 | YORK | YHM36B22 | CU36CXA1+TXV | TM8Y120C20MP11 | 22,400 | $1,120 |
| No | 203112157 | YORK | YHM36B22 | CM36CBCA1 | TM8Y120C20MP11 | 22,400 | $1,120 |
| No | 205539335 | YORK | YHM36B22 | CM36CXA1+TXV | TM8Y120C20MP11 | 22,400 | $1,120 |
| No | 205539313 | YORK | YHM36B22 | CF36CXA1+TXV | TM8Y120C20MP11 | 22,400 | $1,120 |
| No | 205539315 | YORK | YHM36B22 | CF36CXA1+TXV | TM8Y100C20MP11 | 22,400 | $1,120 |
| No | 205539304 | YORK | YHM36B22 | CU42CXA1+TXV | TM8Y100C20MP11 | 23,200 | $1,160 |
| No | 203112135 | YORK | YHM36B22 | CM42CBCA1 | TM8Y100C20MP11 | 23,200 | $1,160 |
| No | 205539320 | YORK | YHM36B22 | CM42CXA1+TXV | TM8Y100C20MP11 | 23,200 | $1,160 |
| No | 203112123 | YORK | YHM36B22 | CF42CBCA1 | TM8Y100C20MP11 | 23,200 | $1,160 |
| No | 205539318 | YORK | YHM36B22 | CU42CXA1+TXV | TM8Y120C20MP11 | 23,200 | $1,160 |
| No | 203112132 | YORK | YHM36B22 | CM42CBCA1 | TM8Y120C20MP11 | 23,200 | $1,160 |
| No | 205539302 | YORK | YHM36B22 | CM42CXA1+TXV | TM8Y120C20MP11 | 23,200 | $1,160 |
| No | 203112121 | YORK | YHM36B22 | CF42CBCA1 | TM8Y120C20MP11 | 23,200 | $1,160 |
| No | 205539283 | YORK | YHM36B22 | CF42CXA1+TXV | TM8Y100C20MP11 | 23,200 | $1,160 |
| No | 205539281 | YORK | YHM36B22 | CF42CXA1+TXV | TM8Y120C20MP11 | 23,200 | $1,160 |
| No | 203112099 | YORK | YHM36B22 | CM48DBCA1 | TM8Y100C20MP11 | 22,200 | $1,110 |
| No | 205539286 | YORK | YHM36B22 | CU48DXA1+TXV | TM8Y100C20MP11 | 22,200 | $1,110 |
| No | 205539284 | YORK | YHM36B22 | CM48DXA1+TXV | TM8Y100C20MP11 | 22,200 | $1,110 |
| No | 203112096 | YORK | YHM36B22 | CM48DBCA1 | TM8Y120C20MP11 | 22,200 | $1,110 |
| No | 205539271 | YORK | YHM36B22 | CM48DXA1+TXV | TM8Y120C20MP11 | 22,200 | $1,110 |
| No | 205539272 | YORK | YHM36B22 | CU48DXA1+TXV | TM8Y120C20MP11 | 22,200 | $1,110 |
| No | 205539255 | YORK | YHM36B22 | CF48DXA1+TXV | TM8Y100C20MP11 | 22,200 | $1,110 |
| No | 205539253 | YORK | YHM36B22 | CF48DXA1+TXV | TM8Y120C20MP11 | 22,200 | $1,110 |
| No | 205539244 | YORK | YHM36B22 | CU36CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 203112075 | YORK | YHM36B22 | CM36CBCA1 | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205539242 | YORK | YHM36B22 | CM36CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205539235 | YORK | YHM36B22 | CF36CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205539232 | YORK | YHM36B22 | CU42CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 203112066 | YORK | YHM36B22 | CM42CBCA1 | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205539239 | YORK | YHM36B22 | CM42CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 203112062 | YORK | YHM36B22 | CF42CBCA1 | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205539227 | YORK | YHM36B22 | CF42CXA1+TXV | TM9Y080C16MP11 | 22,800 | $1,140 |
| No | 205539224 | YORK | YHM36B22 | CF42BXA1+MVC12BN21+TXV | | 22,000 | $1,100 |
| No | 203111988 | YORK | YHM36B22 | CM36BBCA1+ME12BN21 | | 22,200 | $1,110 |
| No | 205539223 | YORK | YHM36B22 | CM36BXA1+ME12BN21+TXV | | 22,200 | $1,110 |
| No | 203111986 | YORK | YHM36B22 | CF36BBCA1+ME12BN21 | | 22,200 | $1,110 |
| No | 205539221 | YORK | YHM36B22 | CF36BXA1+ME12BN21+TXV | | 22,200 | $1,110 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205539219 | YORK | YHM36B22 | CF42BXA1+ME12BN21+TXV | | 22,200 | $1,110 |
| No | 203111974 | YORK | YHM36B22 | CM48DBCA1+MVC14DN21 | | 21,800 | $1,090 |
| No | 205539217 | YORK | YHM36B22 | CM48DXA1+MVC14DN21+TXV | | 21,800 | $1,090 |
| No | 205539216 | YORK | YHM36B22 | CF48DXA1+MVC14DN21+TXV | | 21,800 | $1,090 |
| No | 205539214 | YORK | YHM36B22 | CU36CXA1+TXV | YPLC080B12MP13 | 22,400 | $1,120 |
| No | 203111894 | YORK | YHM36B22 | CM36CBCA1 | YPLC080B12MP13 | 22,400 | $1,120 |
| No | 205539212 | YORK | YHM36B22 | CM36CXA1+TXV | YPLC080B12MP13 | 22,400 | $1,120 |
| No | 205539210 | YORK | YHM36B22 | CU36CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 203111892 | YORK | YHM36B22 | CM36CBCA1 | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 205539208 | YORK | YHM36B22 | CM36CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 205539204 | YORK | YHM36B22 | CU36CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 203111889 | YORK | YHM36B22 | CM36CBCA1 | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205539200 | YORK | YHM36B22 | CM36CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205539199 | YORK | YHM36B22 | CF36CXA1+TXV | YPLC080B12MP13 | 22,400 | $1,120 |
| No | 205539197 | YORK | YHM36B22 | CF36CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 203111853 | YORK | YHM36B22 | CM42CBCA1 | YPLC080B12MP13 | 22,400 | $1,120 |
| No | 205539191 | YORK | YHM36B22 | CU42CXA1+TXV | YPLC080B12MP13 | 22,400 | $1,120 |
| No | 205539192 | YORK | YHM36B22 | CF36CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205539202 | YORK | YHM36B22 | CM42CXA1+TXV | YPLC080B12MP13 | 22,400 | $1,120 |
| No | 203111845 | YORK | YHM36B22 | CF42CBCA1 | YPLC080B12MP13 | 22,400 | $1,120 |
| No | 205539189 | YORK | YHM36B22 | CU42CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 203111852 | YORK | YHM36B22 | CM42CBCA1 | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 205539187 | YORK | YHM36B22 | CM42CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 203111843 | YORK | YHM36B22 | CF42CBCA1 | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 205539179 | YORK | YHM36B22 | CU42CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 203111847 | YORK | YHM36B22 | CM42CBCA1 | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205539177 | YORK | YHM36B22 | CM42CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205539174 | YORK | YHM36B22 | CF42CXA1+TXV | YPLC080B12MP13 | 22,400 | $1,120 |
| No | 203111839 | YORK | YHM36B22 | CF42CBCA1 | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205539173 | YORK | YHM36B22 | CF42CXA1+TXV | TPLC080B12MP13 | 22,400 | $1,120 |
| No | 205539169 | YORK | YHM36B22 | CF42CXA1+TXV | TM8V080B12MP12 | 22,400 | $1,120 |
| No | 205539167 | YORK | YHM36B22 | CU36CXA1+TXV | YP9C080C16MP13 | 22,200 | $1,110 |
| No | 203111783 | YORK | YHM36B22 | CM36CBCA1 | YP9C080C16MP13 | 22,200 | $1,110 |
| No | 205539165 | YORK | YHM36B22 | CM36CXA1+TXV | YP9C080C16MP13 | 22,200 | $1,110 |
| No | 205539164 | YORK | YHM36B22 | CU36CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 203111782 | YORK | YHM36B22 | CM36CBCA1 | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 205539162 | YORK | YHM36B22 | CM36CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 205539160 | YORK | YHM36B22 | CU36CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203111780 | YORK | YHM36B22 | CM36CBCA1 | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205539158 | YORK | YHM36B22 | CM36CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205539157 | YORK | YHM36B22 | CF36CXA1+TXV | YP9C080C16MP13 | 22,200 | $1,110 |
| No | 205539155 | YORK | YHM36B22 | CF36CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 205539154 | YORK | YHM36B22 | CF36CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205539152 | YORK | YHM36B22 | CU42CXA1+TXV | YP9C080C16MP13 | 22,200 | $1,110 |
| No | 203111765 | YORK | YHM36B22 | CM42CBCA1 | YP9C080C16MP13 | 22,200 | $1,110 |
| No | 205539151 | YORK | YHM36B22 | CM42CXA1+TXV | YP9C080C16MP13 | 22,200 | $1,110 |
| No | 203111759 | YORK | YHM36B22 | CF42CBCA1 | YP9C080C16MP13 | 22,200 | $1,110 |
| No | 205539149 | YORK | YHM36B22 | CU42CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 203111763 | YORK | YHM36B22 | CM42CBCA1 | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 205539147 | YORK | YHM36B22 | CM42CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 203111757 | YORK | YHM36B22 | CF42CBCA1 | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 205539146 | YORK | YHM36B22 | CU42CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 203111761 | YORK | YHM36B22 | CM42CBCA1 | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205539144 | YORK | YHM36B22 | CM42CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205539140 | YORK | YHM36B22 | CF42CXA1+TXV | YP9C080C16MP13 | 22,200 | $1,110 |
| No | 203111755 | YORK | YHM36B22 | CF42CBCA1 | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205539139 | YORK | YHM36B22 | CF42CXA1+TXV | TP9C080C16MP13 | 22,200 | $1,110 |
| No | 205539137 | YORK | YHM36B22 | CF42CXA1+TXV | TM9V080C16MP12 | 22,200 | $1,110 |
| No | 205539136 | YORK | YHM36B22 | CU48CXA1+TXV | YP9C080C16MP13 | 22,000 | $1,100 |
| No | 203111741 | YORK | YHM36B22 | CM48CBCA1 | YP9C080C16MP13 | 22,000 | $1,100 |
| No | 205539142 | YORK | YHM36B22 | CM48CXA1+TXV | YP9C080C16MP13 | 22,000 | $1,100 |
| No | 203111735 | YORK | YHM36B22 | CF48CBCA1 | YP9C080C16MP13 | 22,000 | $1,100 |
| No | 205539134 | YORK | YHM36B22 | CU48CXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 205539132 | YORK | YHM36B22 | CM48CXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 203111733 | YORK | YHM36B22 | CF48CBCA1 | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 203111739 | YORK | YHM36B22 | CM48CBCA1 | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 205539130 | YORK | YHM36B22 | CU48CXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 205539128 | YORK | YHM36B22 | CM48CXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 203111737 | YORK | YHM36B22 | CM48CBCA1 | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 203111731 | YORK | YHM36B22 | CF48CBCA1 | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 205539126 | YORK | YHM36B22 | CF48CXA1+TXV | YP9C080C16MP13 | 22,000 | $1,100 |
| No | 205539125 | YORK | YHM36B22 | CF48CXA1+TXV | TP9C080C16MP13 | 22,000 | $1,100 |
| No | 205539123 | YORK | YHM36B22 | CF48CXA1+TXV | TM9V080C16MP12 | 22,000 | $1,100 |
| No | 203111702 | YORK | YHM36B22 | AVC42CX21+TXV | | 22,600 | $1,130 |
| No | 205539121 | YORK | YHM36B22 | CU36CXA1+TXV | YPLC100C16MP13 | 22,200 | $1,110 |
| No | 203111665 | YORK | YHM36B22 | CM36CBCA1 | YPLC100C16MP13 | 22,200 | $1,110 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205539119 | YORK | YHM36B22 | CM36CXA1+TXV | YPLC100C16MP13 | 22,200 | $1,110 |
| No | 205539117 | YORK | YHM36B22 | CU36CXA1+TXV | YPLC080C16MP13 | 22,200 | $1,110 |
| No | 203111663 | YORK | YHM36B22 | CM36CBCA1 | YPLC080C16MP13 | 22,200 | $1,110 |
| No | 205539115 | YORK | YHM36B22 | CM36CXA1+TXV | YPLC080C16MP13 | 22,200 | $1,110 |
| No | 205539113 | YORK | YHM36B22 | CU36CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203111661 | YORK | YHM36B22 | CM36CBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205539111 | YORK | YHM36B22 | CM36CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205539109 | YORK | YHM36B22 | CU36CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 203111659 | YORK | YHM36B22 | CM36CBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205539108 | YORK | YHM36B22 | CM36CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205539106 | YORK | YHM36B22 | CU36CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203111657 | YORK | YHM36B22 | CM36CBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205539104 | YORK | YHM36B22 | CM36CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205539099 | YORK | YHM36B22 | CU36CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203111652 | YORK | YHM36B22 | CM36CBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205539097 | YORK | YHM36B22 | CM36CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205539096 | YORK | YHM36B22 | CU36CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203111650 | YORK | YHM36B22 | CM36CBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205539094 | YORK | YHM36B22 | CM36CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205539093 | YORK | YHM36B22 | CF36CXA1+TXV | YPLC100C16MP13 | 22,200 | $1,110 |
| No | 205539091 | YORK | YHM36B22 | CF36CXA1+TXV | YPLC080C16MP13 | 22,200 | $1,110 |
| No | 205539087 | YORK | YHM36B22 | CF36CXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205539088 | YORK | YHM36B22 | CF36CXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205539085 | YORK | YHM36B22 | CF36CXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205539081 | YORK | YHM36B22 | CF36CXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205539080 | YORK | YHM36B22 | CF36CXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 203111402 | YORK | YHM36B22 | CM48DBCA1 | YPLC100C16MP13 | 22,200 | $1,110 |
| No | 205539078 | YORK | YHM36B22 | CU48DXA1+TXV | YPLC100C16MP13 | 22,200 | $1,110 |
| No | 205539077 | YORK | YHM36B22 | CM48DXA1+TXV | YPLC100C16MP13 | 22,200 | $1,110 |
| No | 205539073 | YORK | YHM36B22 | CU48DXA1+TXV | YPLC080C16MP13 | 22,200 | $1,110 |
| No | 205539070 | YORK | YHM36B22 | CM48DXA1+TXV | YPLC080C16MP13 | 22,200 | $1,110 |
| No | 203111400 | YORK | YHM36B22 | CM48DBCA1 | YPLC080C16MP13 | 22,200 | $1,110 |
| No | 203111398 | YORK | YHM36B22 | CM48DBCA1 | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205539068 | YORK | YHM36B22 | CU48DXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205539066 | YORK | YHM36B22 | CM48DXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 203111396 | YORK | YHM36B22 | CM48DBCA1 | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205539064 | YORK | YHM36B22 | CU48DXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205539062 | YORK | YHM36B22 | CM48DXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 203111395 | YORK | YHM36B22 | CM48DBCA1 | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205539060 | YORK | YHM36B22 | CU48DXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205539058 | YORK | YHM36B22 | CM48DXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 203111390 | YORK | YHM36B22 | CM48DBCA1 | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205539054 | YORK | YHM36B22 | CU48DXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205539052 | YORK | YHM36B22 | CM48DXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 203111388 | YORK | YHM36B22 | CM48DBCA1 | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205539045 | YORK | YHM36B22 | CM48DXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205539047 | YORK | YHM36B22 | CU48DXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205539044 | YORK | YHM36B22 | CF48DXA1+TXV | YPLC100C16MP13 | 22,200 | $1,110 |
| No | 205539043 | YORK | YHM36B22 | CF48DXA1+TXV | YPLC080C16MP13 | 22,200 | $1,110 |
| No | 205539042 | YORK | YHM36B22 | CF48DXA1+TXV | TPLC100C16MP13 | 22,200 | $1,110 |
| No | 205539040 | YORK | YHM36B22 | CF48DXA1+TXV | TPLC080C16MP13 | 22,200 | $1,110 |
| No | 205539039 | YORK | YHM36B22 | CF48DXA1+TXV | TMLV100C16MP12 | 22,200 | $1,110 |
| No | 205539035 | YORK | YHM36B22 | CF48DXA1+TXV | TM8V080C16MP12 | 22,200 | $1,110 |
| No | 205539032 | YORK | YHM36B22 | CU36CXA1+TXV | YPLC120C20MP13 | 22,400 | $1,120 |
| No | 203111339 | YORK | YHM36B22 | CM36CBCA1 | YPLC120C20MP13 | 22,400 | $1,120 |
| No | 205539033 | YORK | YHM36B22 | CF48DXA1+TXV | TM8V100C16MP12 | 22,200 | $1,110 |
| No | 205539050 | YORK | YHM36B22 | CM36CXA1+TXV | YPLC120C20MP13 | 22,400 | $1,120 |
| No | 205539048 | YORK | YHM36B22 | CU36CXA1+TXV | YPLC100C20MP13 | 22,400 | $1,120 |
| No | 205539030 | YORK | YHM36B22 | CM36CXA1+TXV | YPLC100C20MP13 | 22,400 | $1,120 |
| No | 203111337 | YORK | YHM36B22 | CM36CBCA1 | YPLC100C20MP13 | 22,400 | $1,120 |
| No | 205539029 | YORK | YHM36B22 | CU36CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 203111335 | YORK | YHM36B22 | CM36CBCA1 | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205539028 | YORK | YHM36B22 | CM36CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205539026 | YORK | YHM36B22 | CU36CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205539024 | YORK | YHM36B22 | CM36CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 203111333 | YORK | YHM36B22 | CM36CBCA1 | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205539022 | YORK | YHM36B22 | CU36CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 203111331 | YORK | YHM36B22 | CM36CBCA1 | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205539021 | YORK | YHM36B22 | CM36CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205539016 | YORK | YHM36B22 | CU36CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 203111327 | YORK | YHM36B22 | CM36CBCA1 | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205539014 | YORK | YHM36B22 | CM36CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205539013 | YORK | YHM36B22 | CU36CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 203111325 | YORK | YHM36B22 | CM36CBCA1 | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205539009 | YORK | YHM36B22 | CM36CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205539007 | YORK | YHM36B22 | CF36CXA1+TXV | YPLC120C20MP13 | 22,400 | $1,120 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205539005 | YORK | YHM36B22 | CF36CXA1+TXV | YPLC100C20MP13 | 22,400 | $1,120 |
| No | 205539003 | YORK | YHM36B22 | CF36CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205539002 | YORK | YHM36B22 | CF36CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205539000 | YORK | YHM36B22 | CF36CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205538996 | YORK | YHM36B22 | CF36CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205538994 | YORK | YHM36B22 | CF36CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205538993 | YORK | YHM36B22 | CU42CXA1+TXV | YPLC120C20MP13 | 22,400 | $1,120 |
| No | 203111261 | YORK | YHM36B22 | CM42CBCA1 | YPLC120C20MP13 | 22,400 | $1,120 |
| No | 205539012 | YORK | YHM36B22 | CM42CXA1+TXV | YPLC120C20MP13 | 22,400 | $1,120 |
| No | 203111244 | YORK | YHM36B22 | CF42CBCA1 | YPLC120C20MP13 | 22,400 | $1,120 |
| No | 205539011 | YORK | YHM36B22 | CU42CXA1+TXV | YPLC100C20MP13 | 22,400 | $1,120 |
| No | 203111259 | YORK | YHM36B22 | CM42CBCA1 | YPLC100C20MP13 | 22,400 | $1,120 |
| No | 205538991 | YORK | YHM36B22 | CM42CXA1+TXV | YPLC100C20MP13 | 22,400 | $1,120 |
| No | 203111243 | YORK | YHM36B22 | CF42CBCA1 | YPLC100C20MP13 | 22,400 | $1,120 |
| No | 205538989 | YORK | YHM36B22 | CU42CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 203111257 | YORK | YHM36B22 | CM42CBCA1 | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205538987 | YORK | YHM36B22 | CM42CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 203111241 | YORK | YHM36B22 | CF42CBCA1 | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205538985 | YORK | YHM36B22 | CU42CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 203111254 | YORK | YHM36B22 | CM42CBCA1 | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205538983 | YORK | YHM36B22 | CM42CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 203111238 | YORK | YHM36B22 | CF42CBCA1 | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205538981 | YORK | YHM36B22 | CU42CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 203111252 | YORK | YHM36B22 | CM42CBCA1 | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205538979 | YORK | YHM36B22 | CM42CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 203111237 | YORK | YHM36B22 | CF42CBCA1 | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205538973 | YORK | YHM36B22 | CU42CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 203111249 | YORK | YHM36B22 | CM42CBCA1 | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205538972 | YORK | YHM36B22 | CM42CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 203111232 | YORK | YHM36B22 | CF42CBCA1 | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205538971 | YORK | YHM36B22 | CU42CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 203111246 | YORK | YHM36B22 | CM42CBCA1 | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205538969 | YORK | YHM36B22 | CM42CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 203111231 | YORK | YHM36B22 | CF42CBCA1 | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205538951 | YORK | YHM36B22 | CF42CXA1+TXV | YPLC120C20MP13 | 22,400 | $1,120 |
| No | 205538950 | YORK | YHM36B22 | CF42CXA1+TXV | YPLC100C20MP13 | 22,400 | $1,120 |
| No | 205538947 | YORK | YHM36B22 | CF42CXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205538946 | YORK | YHM36B22 | CF42CXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205538944 | YORK | YHM36B22 | CF42CXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205538940 | YORK | YHM36B22 | CF42CXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205538938 | YORK | YHM36B22 | CF42CXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205538935 | YORK | YHM36B22 | CM42DXA1+TXV | YPLC100C20MP13 | 22,400 | $1,120 |
| No | 205538937 | YORK | YHM36B22 | CM42DXA1+TXV | YPLC120C20MP13 | 22,400 | $1,120 |
| No | 205538933 | YORK | YHM36B22 | CM42DXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205538932 | YORK | YHM36B22 | CM42DXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205538926 | YORK | YHM36B22 | CM42DXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205538930 | YORK | YHM36B22 | CM42DXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205538922 | YORK | YHM36B22 | CF42DXA1+TXV | YPLC120C20MP13 | 22,400 | $1,120 |
| No | 205538924 | YORK | YHM36B22 | CM42DXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205538920 | YORK | YHM36B22 | CF42DXA1+TXV | YPLC100C20MP13 | 22,400 | $1,120 |
| No | 205538918 | YORK | YHM36B22 | CF42DXA1+TXV | TPLC120C20MP13 | 22,400 | $1,120 |
| No | 205538916 | YORK | YHM36B22 | CF42DXA1+TXV | TPLC100C20MP13 | 22,400 | $1,120 |
| No | 205538914 | YORK | YHM36B22 | CF42DXA1+TXV | TMLV120C20MP12 | 22,400 | $1,120 |
| No | 205538910 | YORK | YHM36B22 | CF42DXA1+TXV | TM8V100C20MP12 | 22,400 | $1,120 |
| No | 205538908 | YORK | YHM36B22 | CF42DXA1+TXV | TM8V120C20MP12 | 22,400 | $1,120 |
| No | 205538907 | YORK | YHM36B22 | CU36BXA1+TXV | TM8Y080B12MP11 | 22,000 | $1,100 |
| No | 203077554 | YORK | YHM36B22 | CM36BBCA1 | TM8Y080B12MP11 | 22,000 | $1,100 |
| No | 205538967 | YORK | YHM36B22 | CM36BXA1+TXV | TM8Y080B12MP11 | 22,000 | $1,100 |
| No | 205538958 | YORK | YHM36B22 | CF36BXA1+TXV | TM8Y080B12MP11 | 22,000 | $1,100 |
| No | 205538952 | YORK | YHM36B22 | CU42CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 203077541 | YORK | YHM36B22 | CF36BBCA1 | TM8Y080B12MP11 | 22,000 | $1,100 |
| No | 203077460 | YORK | YHM36B22 | CM42CBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205538905 | YORK | YHM36B22 | CM42CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 203077431 | YORK | YHM36B22 | CF42CBCA1 | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205538904 | YORK | YHM36B22 | CU42CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203077456 | YORK | YHM36B22 | CM42CBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 203077427 | YORK | YHM36B22 | CF42CBCA1 | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205538871 | YORK | YHM36B22 | CF42CXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205538902 | YORK | YHM36B22 | CM42CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205538870 | YORK | YHM36B22 | CF42CXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205538863 | YORK | YHM36B22 | CM42DXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205538862 | YORK | YHM36B22 | CM42DXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205538854 | YORK | YHM36B22 | CF42DXA1+TXV | TM8Y080C16MP11 | 22,000 | $1,100 |
| No | 205538852 | YORK | YHM36B22 | CF42DXA1+TXV | TM8Y100C16MP11 | 22,000 | $1,100 |
| No | 205538845 | YORK | YHM36B22 | CF42BXA1+TXV | TM9Y080B12MP11 | 22,000 | $1,100 |
| No | 205538842 | YORK | YHM36B22 | CU36CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205538840 | YORK | YHM36B22 | CM36CBCA1 | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205538837 | YORK | YHM36B22 | CM36CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205538883 | YORK | YHM36B22 | CF36CXA1+TXV | TM9Y100C16MP11 | 22,200 | $1,110 |
| No | 205538879 | YORK | YHM36B22 | CU48CXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205538878 | YORK | YHM36B22 | CM48CBCA1 | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205538876 | YORK | YHM36B22 | CM48CXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205538875 | YORK | YHM36B22 | CF48CBCA1 | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205538833 | YORK | YHM36B22 | CF48CXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205538829 | YORK | YHM36B22 | CM48DBCA1 | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205538827 | YORK | YHM36B22 | CU48DXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205538817 | YORK | YHM36B22 | CF48DXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205538770 | YORK | YHM36B22 | CF42BXA1+TXV | YP9C080B12MP13 | 22,200 | $1,110 |
| No | 205538826 | YORK | YHM36B22 | CM48DXA1+TXV | TM9Y100C16MP11 | 22,000 | $1,100 |
| No | 205538768 | YORK | YHM36B22 | CF42BXA1+TXV | TP9C080B12MP13 | 22,200 | $1,110 |
| No | 205538766 | YORK | YHM36B22 | CF42BXA1+TXV | TM9V080B12MP12 | 22,200 | $1,110 |
| No | 205538764 | YORK | YHM36B22 | CU48CXA1+TXV | YP9C100C16MP13 | 21,800 | $1,090 |
| No | 203076744 | YORK | YHM36B22 | CM48CBCA1 | YP9C100C16MP13 | 21,800 | $1,090 |
| No | 205538823 | YORK | YHM36B22 | CM48CXA1+TXV | YP9C100C16MP13 | 21,800 | $1,090 |
| No | 203076730 | YORK | YHM36B22 | CF48CBCA1 | YP9C100C16MP13 | 21,800 | $1,090 |
| No | 205538780 | YORK | YHM36B22 | CU48CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 203076739 | YORK | YHM36B22 | CM48CBCA1 | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205538778 | YORK | YHM36B22 | CM48CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 203076726 | YORK | YHM36B22 | CF48CBCA1 | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205538763 | YORK | YHM36B22 | CU48CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 203076734 | YORK | YHM36B22 | CM48CBCA1 | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205538761 | YORK | YHM36B22 | CM48CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 203076722 | YORK | YHM36B22 | CF48CBCA1 | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205538759 | YORK | YHM36B22 | CF48CXA1+TXV | YP9C100C16MP13 | 21,800 | $1,090 |
| No | 205538757 | YORK | YHM36B22 | CF48CXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205538756 | YORK | YHM36B22 | CF48CXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 203076677 | YORK | YHM36B22 | CM48DBCA1 | YP9C100C16MP13 | 21,800 | $1,090 |
| No | 205538754 | YORK | YHM36B22 | CU48DXA1+TXV | YP9C100C16MP13 | 21,800 | $1,090 |
| No | 205538753 | YORK | YHM36B22 | CM48DXA1+TXV | YP9C100C16MP13 | 21,800 | $1,090 |
| No | 203076672 | YORK | YHM36B22 | CM48DBCA1 | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205538750 | YORK | YHM36B22 | CU48DXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205538748 | YORK | YHM36B22 | CM48DXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 203076668 | YORK | YHM36B22 | CM48DBCA1 | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205538746 | YORK | YHM36B22 | CU48DXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205538743 | YORK | YHM36B22 | CM48DXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 205538741 | YORK | YHM36B22 | CF48DXA1+TXV | YP9C100C16MP13 | 21,800 | $1,090 |
| No | 205538738 | YORK | YHM36B22 | CF48DXA1+TXV | TP9C100C16MP13 | 21,800 | $1,090 |
| No | 205538736 | YORK | YHM36B22 | CF48DXA1+TXV | TM9V100C16MP12 | 21,800 | $1,090 |
| No | 203076622 | YORK | YHM36B22 | CM36CBCA1 | YP9C100C20MP13 | 22,400 | $1,120 |
| No | 205538735 | YORK | YHM36B22 | CU36CXA1+TXV | YP9C100C20MP13 | 22,400 | $1,120 |
| No | 205538732 | YORK | YHM36B22 | CM36CXA1+TXV | YP9C100C20MP13 | 22,400 | $1,120 |
| No | 205538730 | YORK | YHM36B22 | CU36CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 203076618 | YORK | YHM36B22 | CM36CBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205538728 | YORK | YHM36B22 | CM36CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205538725 | YORK | YHM36B22 | CU36CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203076612 | YORK | YHM36B22 | CM36CBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205538723 | YORK | YHM36B22 | CM36CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205538722 | YORK | YHM36B22 | CF36CXA1+TXV | YP9C100C20MP13 | 22,400 | $1,120 |
| No | 205538720 | YORK | YHM36B22 | CF36CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205538717 | YORK | YHM36B22 | CF36CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205538716 | YORK | YHM36B22 | CU42CXA1+TXV | YP9C100C20MP13 | 22,400 | $1,120 |
| No | 203076557 | YORK | YHM36B22 | CM42CBCA1 | YP9C100C20MP13 | 22,400 | $1,120 |
| No | 205538715 | YORK | YHM36B22 | CM42CXA1+TXV | YP9C100C20MP13 | 22,400 | $1,120 |
| No | 203076541 | YORK | YHM36B22 | CF42CBCA1 | YP9C100C20MP13 | 22,400 | $1,120 |
| No | 205538714 | YORK | YHM36B22 | CU42CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 203076551 | YORK | YHM36B22 | CM42CBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205538712 | YORK | YHM36B22 | CM42CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 203076536 | YORK | YHM36B22 | CF42CBCA1 | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205538709 | YORK | YHM36B22 | CU42CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203076546 | YORK | YHM36B22 | CM42CBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205538706 | YORK | YHM36B22 | CM42CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 203076530 | YORK | YHM36B22 | CF42CBCA1 | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 205538700 | YORK | YHM36B22 | CF42CXA1+TXV | YP9C100C20MP13 | 22,400 | $1,120 |
| No | 205538699 | YORK | YHM36B22 | CF42CXA1+TXV | TP9C100C20MP13 | 22,400 | $1,120 |
| No | 205538698 | YORK | YHM36B22 | CF42CXA1+TXV | TM9V100C20MP12 | 22,400 | $1,120 |
| No | 206779053 | YORK | YHM36B22 | CM42DXA1+TXV | YP9C120D20MP13 | 22,000 | $1,100 |
| No | 206779052 | YORK | YHM36B22 | CM42DXA1+TXV | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 206779051 | YORK | YHM36B22 | CM42DXA1+TXV | TM9V120D20MP12 | 22,000 | $1,100 |
| No | 206779049 | YORK | YHM36B22 | CF42DXA1+TXV | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 206779048 | YORK | YHM36B22 | CF42DXA1+TXV | TM9V120D20MP12 | 22,000 | $1,100 |
| No | 206779050 | YORK | YHM36B22 | CF42DXA1+TXV | YP9C120D20MP13 | 22,000 | $1,100 |
| No | 203076295 | YORK | YHM36B22 | CM48DBCA1 | YP9C120D20MP13 | 22,000 | $1,100 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205538704 | YORK | YHM36B22 | CU48DXA1+TXV | YP9C120D20MP13 | 22,000 | $1,100 |
| No | 203076291 | YORK | YHM36B22 | CM48DBCA1 | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 205538702 | YORK | YHM36B22 | CM48DXA1+TXV | YP9C120D20MP13 | 22,000 | $1,100 |
| No | 205538697 | YORK | YHM36B22 | CU48DXA1+TXV | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 205538695 | YORK | YHM36B22 | CM48DXA1+TXV | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 203076286 | YORK | YHM36B22 | CM48DBCA1 | TM9V120D20MP12 | 22,000 | $1,100 |
| No | 205538692 | YORK | YHM36B22 | CU48DXA1+TXV | TM9V120D20MP12 | 22,000 | $1,100 |
| No | 205538690 | YORK | YHM36B22 | CM48DXA1+TXV | TM9V120D20MP12 | 22,000 | $1,100 |
| No | 205538686 | YORK | YHM36B22 | CF48DXA1+TXV | TP9C120D20MP13 | 22,000 | $1,100 |
| No | 205538685 | YORK | YHM36B22 | CF48DXA1+TXV | TM9V120D20MP12 | 22,000 | $1,100 |
| No | 205538687 | YORK | YHM36B22 | CF48DXA1+TXV | YP9C120D20MP13 | 22,000 | $1,100 |
| No | 203076272 | YORK | YHM36B22 | CM48DBCA1+MVC20DN21 | | 22,000 | $1,100 |
| No | 205538681 | YORK | YHM36B22 | CM48DXA1+MVC20DN21+TXV | | 22,000 | $1,100 |
| No | 205538679 | YORK | YHM36B22 | CF48DXA1+MVC20DN21+TXV | | 22,000 | $1,100 |
| No | 205538677 | YORK | YHM36B22 | CM42DXA1+MVC20DN21+TXV | | 22,000 | $1,100 |
| No | 205538675 | YORK | YHM36B22 | CF42DXA1+MVC20DN21+TXV | | 22,000 | $1,100 |
| No | 205538674 | YORK | YHM36B22 | CM42DXA1+MVC14DN21+TXV | | 22,200 | $1,110 |
| No | 205538672 | YORK | YHM36B22 | CF42DXA1+MVC14DN21+TXV | | 22,200 | $1,110 |
| No | 205074053 | YORK | YHM24B21 | CM30AXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 202613895 | YORK | YHM24B21 | CF30ABAA1 | TL8E060A12UH11 | 15,100 | $755 |
| No | 205073809 | YORK | YHM24B21 | CF30AXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205537972 | YORK | YHM24B21 | CM36AXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 205537971 | YORK | YHM24B21 | CF36AXA1+TXV | TL8E060A12UH11 | 15,100 | $755 |
| No | 202586531 | YORK | YHM48B21 | CM48DBCA1 | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 205537968 | YORK | YHM48B21 | CU48DXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 205537965 | YORK | YHM48B21 | CM48DXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 205537963 | YORK | YHM48B21 | CF48DXA1+TXV | TL8E080C16UH11 | 28,400 | $1,420 |
| No | 202586526 | YORK | YHM48B21 | CM48CBCA1 | TL8E100C20UH11 | 28,200 | $1,410 |
| No | 205537962 | YORK | YHM48B21 | CU48CXA1+TXV | TL8E100C20UH11 | 28,200 | $1,410 |
| No | 205537969 | YORK | YHM48B21 | CM48CXA1+TXV | TL8E100C20UH11 | 28,200 | $1,410 |
| No | 202586525 | YORK | YHM48B21 | CF48CBCA1 | TL8E100C20UH11 | 28,200 | $1,410 |
| No | 205537960 | YORK | YHM48B21 | CF48CXA1+TXV | TL8E100C20UH11 | 28,200 | $1,410 |
| No | 205537958 | YORK | YHM48B21 | CU48DXA1+TXV | TL8E100C20UH11 | 28,600 | $1,430 |
| No | 202586523 | YORK | YHM48B21 | CM48DBCA1 | TL8E100C20UH11 | 28,600 | $1,430 |
| No | 205537954 | YORK | YHM48B21 | CF48DXA1+TXV | TL8E100C20UH11 | 28,600 | $1,430 |
| No | 205537957 | YORK | YHM48B21 | CM48DXA1+TXV | TL8E100C20UH11 | 28,600 | $1,430 |
| No | 205537953 | YORK | YHM48B21 | CM64DXA1+TXV | TL8E100C20UH11 | 29,400 | $1,470 |
| No | 205537951 | YORK | YHM48B21 | CF64DXA1+TXV | TL8E100C20UH11 | 29,400 | $1,470 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205537949 | YORK | YHM48B21 | CU48CXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 202586518 | YORK | YHM48B21 | CM48CBCA1 | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205537959 | YORK | YHM48B21 | CM48CXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 202586517 | YORK | YHM48B21 | CF48CBCA1 | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205537947 | YORK | YHM48B21 | CF48CXA1+TXV | TL9E080C16UH11 | 28,600 | $1,430 |
| No | 205537943 | YORK | YHM48B21 | CU48CXA1+TXV | TL9E100C20UH11 | 28,400 | $1,420 |
| No | 202586510 | YORK | YHM48B21 | CM48CBCA1 | TL9E100C20UH11 | 28,400 | $1,420 |
| No | 205537945 | YORK | YHM48B21 | CM48CXA1+TXV | TL9E100C20UH11 | 28,400 | $1,420 |
| No | 202586509 | YORK | YHM48B21 | CF48CBCA1 | TL9E100C20UH11 | 28,400 | $1,420 |
| No | 205537941 | YORK | YHM48B21 | CF48CXA1+TXV | TL9E100C20UH11 | 28,400 | $1,420 |
| No | 202586507 | YORK | YHM48B21 | CM48DBCA1 | TL9E100C20UH11 | 28,600 | $1,430 |
| No | 205537937 | YORK | YHM48B21 | CU48DXA1+TXV | TL9E100C20UH11 | 28,600 | $1,430 |
| No | 205537935 | YORK | YHM48B21 | CM48DXA1+TXV | TL9E100C20UH11 | 28,600 | $1,430 |
| No | 205537934 | YORK | YHM48B21 | CF48DXA1+TXV | TL9E100C20UH11 | 28,600 | $1,430 |
| No | 205537932 | YORK | YHM48B21 | CM64DXA1+TXV | TL9E100C20UH11 | 30,400 | $1,520 |
| No | 205537930 | YORK | YHM48B21 | CF64DXA1+TXV | TL9E100C20UH11 | 30,400 | $1,520 |
| No | 205537928 | YORK | YHM48B21 | CU48CXA1+TXV | TMLE080B12MP11 | 28,000 | $1,400 |
| No | 205537939 | YORK | YHM48B21 | CM48CXA1+TXV | TMLE080B12MP11 | 28,000 | $1,400 |
| No | 203423057 | YORK | YHM48B21 | CM48CBCA1 | TMLE080B12MP11 | 28,000 | $1,400 |
| No | 203423054 | YORK | YHM48B21 | CF48CBCA1 | TMLE080B12MP11 | 28,000 | $1,400 |
| No | 202586502 | YORK | YHM48B21 | CM48CBCA1 | TM8E080B12MP11 | 28,000 | $1,400 |
| No | 205537926 | YORK | YHM48B21 | CU48CXA1+TXV | TM8E080B12MP11 | 28,000 | $1,400 |
| No | 205537924 | YORK | YHM48B21 | CM48CXA1+TXV | TM8E080B12MP11 | 28,000 | $1,400 |
| No | 205537923 | YORK | YHM48B21 | CF48CXA1+TXV | TMLE080B12MP11 | 28,000 | $1,400 |
| No | 202586501 | YORK | YHM48B21 | CF48CBCA1 | TM8E080B12MP11 | 28,000 | $1,400 |
| No | 205537921 | YORK | YHM48B21 | CF48CXA1+TXV | TM8E080B12MP11 | 28,000 | $1,400 |
| No | 205537919 | YORK | YHM48B21 | CU48CXA1+TXV | TMLE080C16MP11 | 28,600 | $1,430 |
| No | 203423049 | YORK | YHM48B21 | CM48CBCA1 | TMLE080C16MP11 | 28,600 | $1,430 |
| No | 205537917 | YORK | YHM48B21 | CM48CXA1+TXV | TMLE080C16MP11 | 28,600 | $1,430 |
| No | 203423048 | YORK | YHM48B21 | CF48CBCA1 | TMLE080C16MP11 | 28,600 | $1,430 |
| No | 205537914 | YORK | YHM48B21 | CU48CXA1+TXV | TM8E080C16MP11 | 28,600 | $1,430 |
| No | 202586498 | YORK | YHM48B21 | CM48CBCA1 | TM8E080C16MP11 | 28,600 | $1,430 |
| No | 205537911 | YORK | YHM48B21 | CM48CXA1+TXV | TM8E080C16MP11 | 28,600 | $1,430 |
| No | 202586497 | YORK | YHM48B21 | CF48CBCA1 | TM8E080C16MP11 | 28,600 | $1,430 |
| No | 205537909 | YORK | YHM48B21 | CF48CXA1+TXV | TMLE080C16MP11 | 28,600 | $1,430 |
| No | 205537907 | YORK | YHM48B21 | CF48CXA1+TXV | TM8E080C16MP11 | 28,600 | $1,430 |
| No | 203423044 | YORK | YHM48B21 | CM48DBCA1 | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 205537904 | YORK | YHM48B21 | CU48DXA1+TXV | TMLE080C16MP11 | 27,800 | $1,390 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205537903 | YORK | YHM48B21 | CM48DXA1+TXV | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 205537899 | YORK | YHM48B21 | CU48DXA1+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 202586495 | YORK | YHM48B21 | CM48DBCA1 | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205537897 | YORK | YHM48B21 | CM48DXA1+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205537894 | YORK | YHM48B21 | CF48DXA1+TXV | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 205537891 | YORK | YHM48B21 | CF48DXA1+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205073759 | YORK | YHM48B21 | CU60DXA2+TXV | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 205073758 | YORK | YHM48B21 | CM60DXA2+TXV | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 205073756 | YORK | YHM48B21 | CU60DXA2+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205073755 | YORK | YHM48B21 | CM60DXA2+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205073753 | YORK | YHM48B21 | CF60DXA2+TXV | TMLE080C16MP11 | 27,800 | $1,390 |
| No | 205073751 | YORK | YHM48B21 | CF60DXA2+TXV | TM8E080C16MP11 | 27,800 | $1,390 |
| No | 205537884 | YORK | YHM48B21 | CM64DXA1+TXV | TMLE080C16MP11 | 30,600 | $1,530 |
| No | 205537882 | YORK | YHM48B21 | CM64DXA1+TXV | TM8E080C16MP11 | 30,600 | $1,530 |
| No | 205537880 | YORK | YHM48B21 | CF64DXA1+TXV | TMLE080C16MP11 | 30,600 | $1,530 |
| No | 205537878 | YORK | YHM48B21 | CF64DXA1+TXV | TM8E080C16MP11 | 30,600 | $1,530 |
| No | 203423034 | YORK | YHM48B21 | CM48CBCA1 | TMLE100B12MP11 | 27,800 | $1,390 |
| No | 205537901 | YORK | YHM48B21 | CM48CXA1+TXV | TMLE100B12MP11 | 27,800 | $1,390 |
| No | 205537876 | YORK | YHM48B21 | CU48CXA1+TXV | TMLE100B12MP11 | 27,800 | $1,390 |
| No | 203423032 | YORK | YHM48B21 | CF48CBCA1 | TMLE100B12MP11 | 27,800 | $1,390 |
| No | 205537889 | YORK | YHM48B21 | CU48CXA1+TXV | TM8E100B12MP11 | 27,800 | $1,390 |
| No | 202586489 | YORK | YHM48B21 | CM48CBCA1 | TM8E100B12MP11 | 27,800 | $1,390 |
| No | 205537887 | YORK | YHM48B21 | CM48CXA1+TXV | TM8E100B12MP11 | 27,800 | $1,390 |
| No | 202586488 | YORK | YHM48B21 | CF48CBCA1 | TM8E100B12MP11 | 27,800 | $1,390 |
| No | 205537873 | YORK | YHM48B21 | CF48CXA1+TXV | TMLE100B12MP11 | 27,800 | $1,390 |
| No | 205537872 | YORK | YHM48B21 | CF48CXA1+TXV | TM8E100B12MP11 | 27,800 | $1,390 |
| No | 205537867 | YORK | YHM48B21 | CU48CXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 203423026 | YORK | YHM48B21 | CM48CBCA1 | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205537869 | YORK | YHM48B21 | CM48CXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 203423025 | YORK | YHM48B21 | CF48CBCA1 | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205537865 | YORK | YHM48B21 | CU48CXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 202586485 | YORK | YHM48B21 | CM48CBCA1 | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 202586484 | YORK | YHM48B21 | CF48CBCA1 | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 205537863 | YORK | YHM48B21 | CM48CXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 205537861 | YORK | YHM48B21 | CF48CXA1+TXV | TMLE100C16MP11 | 28,000 | $1,400 |
| No | 205537859 | YORK | YHM48B21 | CF48CXA1+TXV | TM8E100C16MP11 | 28,000 | $1,400 |
| No | 206779270 | YORK | YHM48B21 | CM64DXA1+TXV | TMLE100C16MP11 | 30,600 | $1,530 |
| No | 206779269 | YORK | YHM48B21 | CM64DXA1+TXV | TM8E100C16MP11 | 30,600 | $1,530 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206779268 | YORK | YHM48B21 | CF64DXA1+TXV | TMLE100C16MP11 | 30,600 | $1,530 |
| No | 206779267 | YORK | YHM48B21 | CF64DXA1+TXV | TM8E100C16MP11 | 30,600 | $1,530 |
| No | 205073700 | YORK | YHM48B21 | CM60CXA2+TXV | TMLE100C20MP11 | 27,200 | $1,360 |
| No | 205073702 | YORK | YHM48B21 | CU60CXA2+TXV | TMLE100C20MP11 | 27,200 | $1,360 |
| No | 205073697 | YORK | YHM48B21 | CM60CXA2+TXV | TM8E100C20MP11 | 27,200 | $1,360 |
| No | 205073695 | YORK | YHM48B21 | CF60CXA2+TXV | TMLE100C20MP11 | 27,200 | $1,360 |
| No | 205073699 | YORK | YHM48B21 | CU60CXA2+TXV | TM8E100C20MP11 | 27,200 | $1,360 |
| No | 205073693 | YORK | YHM48B21 | CF60CXA2+TXV | TM8E100C20MP11 | 27,200 | $1,360 |
| No | 205073692 | YORK | YHM48B21 | CU60DXA2+TXV | TMLE100C20MP11 | 27,400 | $1,370 |
| No | 205073690 | YORK | YHM48B21 | CM60DXA2+TXV | TMLE100C20MP11 | 27,400 | $1,370 |
| No | 205073689 | YORK | YHM48B21 | CU60DXA2+TXV | TM8E100C20MP11 | 27,400 | $1,370 |
| No | 205073687 | YORK | YHM48B21 | CM60DXA2+TXV | TM8E100C20MP11 | 27,400 | $1,370 |
| No | 205073685 | YORK | YHM48B21 | CF60DXA2+TXV | TMLE100C20MP11 | 27,400 | $1,370 |
| No | 205073684 | YORK | YHM48B21 | CF60DXA2+TXV | TM8E100C20MP11 | 27,400 | $1,370 |
| No | 203423005 | YORK | YHM48B21 | CM48DBCA1 | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 205537854 | YORK | YHM48B21 | CU48DXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 205537852 | YORK | YHM48B21 | CM48DXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 202586472 | YORK | YHM48B21 | CM48DBCA1 | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 205537851 | YORK | YHM48B21 | CU48DXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 205537849 | YORK | YHM48B21 | CM48DXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 205537847 | YORK | YHM48B21 | CF48DXA1+TXV | TMLE120C16MP11 | 28,000 | $1,400 |
| No | 205537844 | YORK | YHM48B21 | CF48DXA1+TXV | TM8E120C16MP11 | 28,000 | $1,400 |
| No | 205073671 | YORK | YHM48B21 | CU60CXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205073670 | YORK | YHM48B21 | CM60CXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205073669 | YORK | YHM48B21 | CU60CXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 205073667 | YORK | YHM48B21 | CM60CXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 205073666 | YORK | YHM48B21 | CF60CXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205073665 | YORK | YHM48B21 | CF60CXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 205073663 | YORK | YHM48B21 | CU60DXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205073661 | YORK | YHM48B21 | CM60DXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205073659 | YORK | YHM48B21 | CU60DXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 205073657 | YORK | YHM48B21 | CM60DXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 205073656 | YORK | YHM48B21 | CF60DXA2+TXV | TMLE120C20MP11 | 27,200 | $1,360 |
| No | 205073654 | YORK | YHM48B21 | CF60DXA2+TXV | TM8E120C20MP11 | 27,200 | $1,360 |
| No | 202586458 | YORK | YHM48B21 | CM48DBCA1 | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 205537832 | YORK | YHM48B21 | CU48DXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 205537831 | YORK | YHM48B21 | CM48DXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |
| No | 205537829 | YORK | YHM48B21 | CF48DXA1+TXV | TM9E080C16MP12 | 27,800 | $1,390 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 205073631 | YORK | YHM48B21 | CU60CXA2+TXV | TM9E080C20MP12 | 27,200 | $1,360 |
| No | 205073629 | YORK | YHM48B21 | CM60CXA2+TXV | TM9E080C20MP12 | 27,200 | $1,360 |
| No | 205073628 | YORK | YHM48B21 | CF60CXA2+TXV | TM9E080C20MP12 | 27,200 | $1,360 |
| No | 205073626 | YORK | YHM48B21 | CU60DXA2+TXV | TM9E080C20MP12 | 27,600 | $1,380 |
| No | 205073624 | YORK | YHM48B21 | CM60DXA2+TXV | TM9E080C20MP12 | 27,600 | $1,380 |
| No | 202586449 | YORK | YHM48B21 | CM48DBCA1 | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205537837 | YORK | YHM48B21 | CU48DXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205073622 | YORK | YHM48B21 | CF60DXA2+TXV | TM9E080C20MP12 | 27,600 | $1,380 |
| No | 205537835 | YORK | YHM48B21 | CM48DXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205537834 | YORK | YHM48B21 | CF48DXA1+TXV | TM9E100C16MP12 | 27,800 | $1,390 |
| No | 205073621 | YORK | YHM48B21 | CU60DXA2+TXV | TM9E100C16MP12 | 28,000 | $1,400 |
| No | 205073620 | YORK | YHM48B21 | CM60DXA2+TXV | TM9E100C16MP12 | 28,000 | $1,400 |
| No | 205073617 | YORK | YHM48B21 | CF60DXA2+TXV | TM9E100C16MP12 | 28,000 | $1,400 |
| No | 205537827 | YORK | YHM48B21 | CM64DXA1+TXV | TM9E100C16MP12 | 28,800 | $1,440 |
| No | 205537826 | YORK | YHM48B21 | CF64DXA1+TXV | TM9E100C16MP12 | 28,800 | $1,440 |
| No | 205073615 | YORK | YHM48B21 | CU60CXA2+TXV | TM9E100C20MP12 | 27,200 | $1,360 |
| No | 205073614 | YORK | YHM48B21 | CM60CXA2+TXV | TM9E100C20MP12 | 27,200 | $1,360 |
| No | 205537824 | YORK | YHM60B21 | CM64DXA1+TXV | TL8E100C20UH11 | 32,800 | $1,640 |
| No | 205073612 | YORK | YHM48B21 | CF60CXA2+TXV | TM9E100C20MP12 | 27,200 | $1,360 |
| No | 205537823 | YORK | YHM60B21 | CF64DXA1+TXV | TL8E100C20UH11 | 32,800 | $1,640 |
| No | 205537820 | YORK | YHM60B21 | CM64DXA1+TXV | TL9E100C20UH11 | 32,800 | $1,640 |
| No | 205537817 | YORK | YHM60B21 | CF64DXA1+TXV | TL9E100C20UH11 | 32,800 | $1,640 |
| No | 205537815 | YORK | YHM60B21 | CM64DXA1+TXV | TMLE080C20MP11 | 32,600 | $1,630 |
| No | 205537813 | YORK | YHM60B21 | CM64DXA1+TXV | TM8E080C20MP11 | 32,600 | $1,630 |
| No | 205537811 | YORK | YHM60B21 | CF64DXA1+TXV | TMLE080C20MP11 | 32,600 | $1,630 |
| No | 205537810 | YORK | YHM60B21 | CF64DXA1+TXV | TM8E080C20MP11 | 32,600 | $1,630 |
| No | 206779690 | YORK | YHM60B21 | CM64DXA1+TXV | TMLE120C16MP11 | 32,800 | $1,640 |
| No | 206779689 | YORK | YHM60B21 | CM64DXA1+TXV | TM8E120C16MP11 | 32,800 | $1,640 |
| No | 206779688 | YORK | YHM60B21 | CF64DXA1+TXV | TMLE120C16MP11 | 32,800 | $1,640 |
| No | 206779687 | YORK | YHM60B21 | CF64DXA1+TXV | TM8E120C16MP11 | 32,800 | $1,640 |
| No | 205537808 | YORK | YHM60B21 | CM64DXA1+TXV | TM9E080C20MP12 | 32,600 | $1,630 |
| No | 205537806 | YORK | YHM60B21 | CF64DXA1+TXV | TM9E080C20MP12 | 32,600 | $1,630 |
| No | 205537804 | YORK | YHM60B21 | CM64DXA1+TXV | TM9E100C20MP12 | 32,600 | $1,630 |
| No | 205537802 | YORK | YHM60B21 | CF64DXA1+TXV | TM9E100C20MP12 | 32,600 | $1,630 |
| No | 205537800 | YORK | YHM60B21 | CM64DXA1+TXV | TM9E120D20MP12 | 33,200 | $1,660 |
| No | 205537798 | YORK | YHM60B21 | CF64DXA1+TXV | TM9E120D20MP12 | 33,200 | $1,660 |
| No | 206838910 | YORK | YHM24B21 | CM36AXA1+TXV | YPLC060A12MP13 | 15,000 | $750 |
| No | 206838909 | YORK | YHM24B21 | CM36AXA1+TXV | TPLC060A12MP13 | 15,000 | $750 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206838908 | YORK | YHM24B21 | CM36AXA1+TXV | TMLV060A12MP12 | 15,000 | $750 |
| No | 206838907 | YORK | YHM24B21 | CM36AXA1+TXV | TM8V060A12MP12 | 15,000 | $750 |
| No | 206838906 | YORK | YHM24B21 | CF36AXA1+TXV | YPLC060A12MP13 | 15,000 | $750 |
| No | 206838905 | YORK | YHM24B21 | CF36AXA1+TXV | TPLC060A12MP13 | 15,000 | $750 |
| No | 206838903 | YORK | YHM24B21 | CF36AXA1+TXV | TM8V060A12MP12 | 15,000 | $750 |
| No | 206778777 | YORK | YHM24B21 | CU24BXA1+TXV | YPLC080B12MP13 | 15,100 | $755 |
| No | 206778776 | YORK | YHM24B21 | CM24BBAA1 | YPLC080B12MP13 | 15,100 | $755 |
| No | 206838904 | YORK | YHM24B21 | CF36AXA1+TXV | TMLV060A12MP12 | 15,000 | $750 |
| No | 206778775 | YORK | YHM24B21 | CM24BXA1+TXV | YPLC080B12MP13 | 15,100 | $755 |
| No | 202099118 | YORK | YHM24B21 | CF24BBAA1 | YPLC080B12MP13 | 15,100 | $755 |
| No | 206778774 | YORK | YHM24B21 | CU24BXA1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 206778773 | YORK | YHM24B21 | CM24BBAA1 | TPLC080B12MP13 | 15,100 | $755 |
| No | 206778772 | YORK | YHM24B21 | CM24BXA1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 202099116 | YORK | YHM24B21 | CF24BBAA1 | TPLC080B12MP13 | 15,100 | $755 |
| No | 206779047 | YORK | YHM24B21 | CU24BXA1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 206779046 | YORK | YHM24B21 | CM24BBAA1 | TM8V080B12MP12 | 15,100 | $755 |
| No | 206779045 | YORK | YHM24B21 | CM24BXA1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 202099112 | YORK | YHM24B21 | CF24BBAA1 | TM8V080B12MP12 | 15,100 | $755 |
| No | 206779043 | YORK | YHM24B21 | CF24BXA1+TXV | YPLC080B12MP13 | 15,100 | $755 |
| No | 206779042 | YORK | YHM24B21 | CF24BXA1+TXV | TPLC080B12MP13 | 15,100 | $755 |
| No | 206779041 | YORK | YHM24B21 | CF24BXA1+TXV | TM8V080B12MP12 | 15,100 | $755 |
| No | 206779025 | YORK | YHM24B21 | CU36BXA1+TXV | YPLC080B12MP13 | 15,000 | $750 |
| No | 206779024 | YORK | YHM24B21 | CM36BBAA1 | YPLC080B12MP13 | 15,000 | $750 |
| No | 206779023 | YORK | YHM24B21 | CM36BXA1+TXV | YPLC080B12MP13 | 15,000 | $750 |
| No | 206779022 | YORK | YHM24B21 | CF36BBAA1 | YPLC080B12MP13 | 15,000 | $750 |
| No | 206779021 | YORK | YHM24B21 | CU36BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206779020 | YORK | YHM24B21 | CM36BBAA1 | TPLC080B12MP13 | 15,000 | $750 |
| No | 206779019 | YORK | YHM24B21 | CM36BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206779018 | YORK | YHM24B21 | CF36BBAA1 | TPLC080B12MP13 | 15,000 | $750 |
| No | 206779017 | YORK | YHM24B21 | CU36BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206779015 | YORK | YHM24B21 | CM36BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206779016 | YORK | YHM24B21 | CM36BBAA1 | TM8V080B12MP12 | 15,000 | $750 |
| No | 206779014 | YORK | YHM24B21 | CF36BBAA1 | TM8V080B12MP12 | 15,000 | $750 |
| No | 206779013 | YORK | YHM24B21 | CF36BXA1+TXV | YPLC080B12MP13 | 15,000 | $750 |
| No | 206779012 | YORK | YHM24B21 | CF36BXA1+TXV | TPLC080B12MP13 | 15,000 | $750 |
| No | 206779011 | YORK | YHM24B21 | CF36BXA1+TXV | TM8V080B12MP12 | 15,000 | $750 |
| No | 206779010 | YORK | YHM24B21 | CU36CXA1+TXV | YPLC100C16MP13 | 15,100 | $755 |
| No | 206779008 | YORK | YHM24B21 | CU36CXA1+TXV | YPLC080C16MP13 | 15,100 | $755 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206779007 | YORK | YHM24B21 | CM36CXA1+TXV | YPLC080C16MP13 | 15,100 | $755 |
| No | 206779009 | YORK | YHM24B21 | CM36CXA1+TXV | YPLC100C16MP13 | 15,100 | $755 |
| No | 206779006 | YORK | YHM24B21 | CU36CXA1+TXV | TPLC100C16MP13 | 15,100 | $755 |
| No | 206779005 | YORK | YHM24B21 | CM36CXA1+TXV | TPLC100C16MP13 | 15,100 | $755 |
| No | 206779004 | YORK | YHM24B21 | CU36CXA1+TXV | TPLC080C16MP13 | 15,100 | $755 |
| No | 206779003 | YORK | YHM24B21 | CM36CXA1+TXV | TPLC080C16MP13 | 15,100 | $755 |
| No | 206779002 | YORK | YHM24B21 | CU36CXA1+TXV | TMLV100C16MP12 | 15,100 | $755 |
| No | 206779001 | YORK | YHM24B21 | CM36CXA1+TXV | TMLV100C16MP12 | 15,100 | $755 |
| No | 206778999 | YORK | YHM24B21 | CM36CXA1+TXV | TM8V080C16MP12 | 15,100 | $755 |
| No | 206778998 | YORK | YHM24B21 | CU36CXA1+TXV | TM8V100C16MP12 | 15,100 | $755 |
| No | 206779000 | YORK | YHM24B21 | CU36CXA1+TXV | TM8V080C16MP12 | 15,100 | $755 |
| No | 206778997 | YORK | YHM24B21 | CM36CXA1+TXV | TM8V100C16MP12 | 15,100 | $755 |
| No | 206778996 | YORK | YHM24B21 | CF36CXA1+TXV | YPLC100C16MP13 | 15,100 | $755 |
| No | 206778995 | YORK | YHM24B21 | CF36CXA1+TXV | YPLC080C16MP13 | 15,100 | $755 |
| No | 206778994 | YORK | YHM24B21 | CF36CXA1+TXV | TPLC100C16MP13 | 15,100 | $755 |
| No | 206778993 | YORK | YHM24B21 | CF36CXA1+TXV | TPLC080C16MP13 | 15,100 | $755 |
| No | 206778992 | YORK | YHM24B21 | CF36CXA1+TXV | TMLV100C16MP12 | 15,100 | $755 |
| No | 206778991 | YORK | YHM24B21 | CF36CXA1+TXV | TM8V080C16MP12 | 15,100 | $755 |
| No | 206778990 | YORK | YHM24B21 | CF36CXA1+TXV | TM8V100C16MP12 | 15,100 | $755 |
| No | 205537666 | YORK | YHM24B21 | CU30BXA1+TXV | TM9Y060B12MP11 | 15,300 | $765 |
| No | 205537664 | YORK | YHM24B21 | CM30BBAA1 | TM9Y060B12MP11 | 15,300 | $765 |
| No | 205537663 | YORK | YHM24B21 | CM30BXA1+TXV | TM9Y060B12MP11 | 15,300 | $765 |
| No | 205537661 | YORK | YHM24B21 | CF30BBAA1 | TM9Y060B12MP11 | 15,300 | $765 |
| No | 205537653 | YORK | YHM24B21 | CF30BXA1+TXV | TM9Y060B12MP11 | 15,300 | $765 |
| No | 205073591 | YORK | YHM24B21 | CM30AXA1+TXV | TM9V040A10MP12 | 15,100 | $755 |
| No | 202143649 | YORK | YHM24B21 | CF30ABAA1 | TM9V040A10MP12 | 15,100 | $755 |
| No | 205074029 | YORK | YHM24B21 | CF30AXA1+TXV | TM9V040A10MP12 | 15,100 | $755 |
| No | 205537707 | YORK | YHM24B21 | CM36AXA1+TXV | TM9V040A10MP12 | 15,000 | $750 |
| No | 205537705 | YORK | YHM24B21 | CF36AXA1+TXV | TM9V040A10MP12 | 15,000 | $750 |
| No | 206778886 | YORK | YHM24B21 | CU24BXA1+TXV | YP9C060B12MP13 | 15,200 | $760 |
| No | 206778885 | YORK | YHM24B21 | CM24BBAA1 | YP9C060B12MP13 | 15,200 | $760 |
| No | 206778884 | YORK | YHM24B21 | CM24BXA1+TXV | YP9C060B12MP13 | 15,200 | $760 |
| No | 202099041 | YORK | YHM24B21 | CF24BBAA1 | YP9C060B12MP13 | 15,200 | $760 |
| No | 206778883 | YORK | YHM24B21 | CU24BXA1+TXV | TP9C060B12MP13 | 15,200 | $760 |
| No | 206778882 | YORK | YHM24B21 | CM24BBAA1 | TP9C060B12MP13 | 15,200 | $760 |
| No | 206778881 | YORK | YHM24B21 | CM24BXA1+TXV | TP9C060B12MP13 | 15,200 | $760 |
| No | 202099040 | YORK | YHM24B21 | CF24BBAA1 | TP9C060B12MP13 | 15,200 | $760 |
| No | 206778880 | YORK | YHM24B21 | CU24BXA1+TXV | TM9V060B12MP12 | 15,200 | $760 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206778879 | YORK | YHM24B21 | CM24BBAA1 | TM9V060B12MP12 | 15,200 | $760 |
| No | 206778878 | YORK | YHM24B21 | CM24BXA1+TXV | TM9V060B12MP12 | 15,200 | $760 |
| No | 202099039 | YORK | YHM24B21 | CF24BBAA1 | TM9V060B12MP12 | 15,200 | $760 |
| No | 206778848 | YORK | YHM24B21 | CF24BXA1+TXV | YP9C060B12MP13 | 15,200 | $760 |
| No | 206778847 | YORK | YHM24B21 | CF24BXA1+TXV | TP9C060B12MP13 | 15,200 | $760 |
| No | 206778846 | YORK | YHM24B21 | CF24BXA1+TXV | TM9V060B12MP12 | 15,200 | $760 |
| No | 206778845 | YORK | YHM24B21 | CU30BXA1+TXV | YP9C060B12MP13 | 15,400 | $770 |
| No | 206778844 | YORK | YHM24B21 | CM30BBAA1 | YP9C060B12MP13 | 15,400 | $770 |
| No | 206778843 | YORK | YHM24B21 | CM30BXA1+TXV | YP9C060B12MP13 | 15,400 | $770 |
| No | 206778842 | YORK | YHM24B21 | CF30BBAA1 | YP9C060B12MP13 | 15,400 | $770 |
| No | 206778841 | YORK | YHM24B21 | CU30BXA1+TXV | TP9C060B12MP13 | 15,400 | $770 |
| No | 206778840 | YORK | YHM24B21 | CM30BBAA1 | TP9C060B12MP13 | 15,400 | $770 |
| No | 206778839 | YORK | YHM24B21 | CM30BXA1+TXV | TP9C060B12MP13 | 15,400 | $770 |
| No | 206778838 | YORK | YHM24B21 | CF30BBAA1 | TP9C060B12MP13 | 15,400 | $770 |
| No | 206778837 | YORK | YHM24B21 | CU30BXA1+TXV | TM9V060B12MP12 | 15,400 | $770 |
| No | 206778836 | YORK | YHM24B21 | CM30BBAA1 | TM9V060B12MP12 | 15,400 | $770 |
| No | 206778835 | YORK | YHM24B21 | CM30BXA1+TXV | TM9V060B12MP12 | 15,400 | $770 |
| No | 206778834 | YORK | YHM24B21 | CF30BBAA1 | TM9V060B12MP12 | 15,400 | $770 |
| No | 206778833 | YORK | YHM24B21 | CF30BXA1+TXV | YP9C060B12MP13 | 15,400 | $770 |
| No | 206778832 | YORK | YHM24B21 | CF30BXA1+TXV | TP9C060B12MP13 | 15,400 | $770 |
| No | 206778831 | YORK | YHM24B21 | CF30BXA1+TXV | TM9V060B12MP12 | 15,400 | $770 |
| No | 206778986 | YORK | YHM24B21 | CM24BBAA1 | YP9C080B12MP13 | 15,000 | $750 |
| No | 206778987 | YORK | YHM24B21 | CU24BXA1+TXV | YP9C080B12MP13 | 15,000 | $750 |
| No | 206778985 | YORK | YHM24B21 | CM24BXA1+TXV | YP9C080B12MP13 | 15,000 | $750 |
| No | 202099117 | YORK | YHM24B21 | CF24BBAA1 | YP9C080B12MP13 | 15,000 | $750 |
| No | 206778984 | YORK | YHM24B21 | CU24BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 206778983 | YORK | YHM24B21 | CM24BBAA1 | TP9C080B12MP13 | 15,000 | $750 |
| No | 206778982 | YORK | YHM24B21 | CM24BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 202099115 | YORK | YHM24B21 | CF24BBAA1 | TP9C080B12MP13 | 15,000 | $750 |
| No | 206778981 | YORK | YHM24B21 | CU24BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 206778980 | YORK | YHM24B21 | CM24BBAA1 | TM9V080B12MP12 | 15,000 | $750 |
| No | 206778979 | YORK | YHM24B21 | CM24BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 206778957 | YORK | YHM24B21 | CM30BBAA1 | TP9C080B12MP13 | 15,000 | $750 |
| No | 206778959 | YORK | YHM24B21 | CF30BBAA1 | YP9C080B12MP13 | 15,000 | $750 |
| No | 206778963 | YORK | YHM24B21 | CF24BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 206778962 | YORK | YHM24B21 | CU30BXA1+TXV | YP9C080B12MP13 | 15,000 | $750 |
| No | 206778956 | YORK | YHM24B21 | CM30BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 206778955 | YORK | YHM24B21 | CF30BBAA1 | TP9C080B12MP13 | 15,000 | $750 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206778958 | YORK | YHM24B21 | CU30BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 206778953 | YORK | YHM24B21 | CM30BBAA1 | TM9V080B12MP12 | 15,000 | $750 |
| No | 206778964 | YORK | YHM24B21 | CF24BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 206778965 | YORK | YHM24B21 | CF24BXA1+TXV | YP9C080B12MP13 | 15,000 | $750 |
| No | 206778960 | YORK | YHM24B21 | CM30BXA1+TXV | YP9C080B12MP13 | 15,000 | $750 |
| No | 206778961 | YORK | YHM24B21 | CM30BBAA1 | YP9C080B12MP13 | 15,000 | $750 |
| No | 202099113 | YORK | YHM24B21 | CF24BBAA1 | TM9V080B12MP12 | 15,000 | $750 |
| No | 206778954 | YORK | YHM24B21 | CU30BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 206778952 | YORK | YHM24B21 | CM30BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 206778950 | YORK | YHM24B21 | CF30BXA1+TXV | YP9C080B12MP13 | 15,000 | $750 |
| No | 206778951 | YORK | YHM24B21 | CF30BBAA1 | TM9V080B12MP12 | 15,000 | $750 |
| No | 206778949 | YORK | YHM24B21 | CF30BXA1+TXV | TP9C080B12MP13 | 15,000 | $750 |
| No | 206778947 | YORK | YHM24B21 | CU36BXA1+TXV | YP9C080B12MP13 | 15,100 | $755 |
| No | 206778948 | YORK | YHM24B21 | CF30BXA1+TXV | TM9V080B12MP12 | 15,000 | $750 |
| No | 206778946 | YORK | YHM24B21 | CM36BBAA1 | YP9C080B12MP13 | 15,100 | $755 |
| No | 206778945 | YORK | YHM24B21 | CM36BXA1+TXV | YP9C080B12MP13 | 15,100 | $755 |
| No | 206778943 | YORK | YHM24B21 | CU36BXA1+TXV | TP9C080B12MP13 | 15,100 | $755 |
| No | 206778942 | YORK | YHM24B21 | CM36BBAA1 | TP9C080B12MP13 | 15,100 | $755 |
| No | 206778944 | YORK | YHM24B21 | CF36BBAA1 | YP9C080B12MP13 | 15,100 | $755 |
| No | 206778941 | YORK | YHM24B21 | CM36BXA1+TXV | TP9C080B12MP13 | 15,100 | $755 |
| No | 206778940 | YORK | YHM24B21 | CF36BBAA1 | TP9C080B12MP13 | 15,100 | $755 |
| No | 206778939 | YORK | YHM24B21 | CU36BXA1+TXV | TM9V080B12MP12 | 15,100 | $755 |
| No | 206778938 | YORK | YHM24B21 | CM36BBAA1 | TM9V080B12MP12 | 15,100 | $755 |
| No | 206778937 | YORK | YHM24B21 | CM36BXA1+TXV | TM9V080B12MP12 | 15,100 | $755 |
| No | 206778936 | YORK | YHM24B21 | CF36BBAA1 | TM9V080B12MP12 | 15,100 | $755 |
| No | 206778935 | YORK | YHM24B21 | CF36BXA1+TXV | YP9C080B12MP13 | 15,100 | $755 |
| No | 206778934 | YORK | YHM24B21 | CF36BXA1+TXV | TP9C080B12MP13 | 15,100 | $755 |
| No | 206778933 | YORK | YHM24B21 | CF36BXA1+TXV | TM9V080B12MP12 | 15,100 | $755 |
| No | 206778815 | YORK | YHM24B21 | CU36CXA1+TXV | YP9C080C16MP13 | 15,100 | $755 |
| No | 206778814 | YORK | YHM24B21 | CM36CXA1+TXV | YP9C080C16MP13 | 15,100 | $755 |
| No | 206778813 | YORK | YHM24B21 | CU36CXA1+TXV | TP9C080C16MP13 | 15,100 | $755 |
| No | 206778812 | YORK | YHM24B21 | CM36CXA1+TXV | TP9C080C16MP13 | 15,100 | $755 |
| No | 206778811 | YORK | YHM24B21 | CU36CXA1+TXV | TM9V080C16MP12 | 15,100 | $755 |
| No | 206778810 | YORK | YHM24B21 | CM36CXA1+TXV | TM9V080C16MP12 | 15,100 | $755 |
| No | 206778809 | YORK | YHM24B21 | CF36CXA1+TXV | YP9C080C16MP13 | 15,100 | $755 |
| No | 206778808 | YORK | YHM24B21 | CF36CXA1+TXV | TP9C080C16MP13 | 15,100 | $755 |
| No | 206778807 | YORK | YHM24B21 | CF36CXA1+TXV | TM9V080C16MP12 | 15,100 | $755 |
| No | 206778977 | YORK | YHM24B21 | CU36CXA1+TXV | YP9C100C16MP13 | 15,100 | $755 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206778976 | YORK | YHM24B21 | CM36CXA1+TXV | YP9C100C16MP13 | 15,100 | $755 |
| No | 206778975 | YORK | YHM24B21 | CU36CXA1+TXV | TP9C100C16MP13 | 15,100 | $755 |
| No | 206778974 | YORK | YHM24B21 | CM36CXA1+TXV | TP9C100C16MP13 | 15,100 | $755 |
| No | 206778973 | YORK | YHM24B21 | CU36CXA1+TXV | TM9V100C16MP12 | 15,100 | $755 |
| No | 206778972 | YORK | YHM24B21 | CM36CXA1+TXV | TM9V100C16MP12 | 15,100 | $755 |
| No | 206778971 | YORK | YHM24B21 | CF36CXA1+TXV | YP9C100C16MP13 | 15,100 | $755 |
| No | 206778970 | YORK | YHM24B21 | CF36CXA1+TXV | TP9C100C16MP13 | 15,100 | $755 |
| No | 206778969 | YORK | YHM24B21 | CF36CXA1+TXV | TM9V100C16MP12 | 15,100 | $755 |
| No | 206779586 | YORK | YHM60B21 | CM64DXA1+TXV | YP9C100C16MP13 | 32,600 | $1,630 |
| No | 206779585 | YORK | YHM60B21 | CM64DXA1+TXV | TP9C100C16MP13 | 32,600 | $1,630 |
| No | 206779584 | YORK | YHM60B21 | CM64DXA1+TXV | TM9V100C16MP12 | 32,600 | $1,630 |
| No | 206779583 | YORK | YHM60B21 | CF64DXA1+TXV | YP9C100C16MP13 | 32,600 | $1,630 |
| No | 206779582 | YORK | YHM60B21 | CF64DXA1+TXV | TP9C100C16MP13 | 32,600 | $1,630 |
| No | 206779581 | YORK | YHM60B21 | CF64DXA1+TXV | TM9V100C16MP12 | 32,600 | $1,630 |
| No | 206779280 | YORK | YHM48B21 | CM48DBCA1+MVC14DN21 | | 28,000 | $1,400 |
| No | 206779278 | YORK | YHM48B21 | CF48DXA1+MVC14DN21+TXV | | 28,000 | $1,400 |
| No | 206779279 | YORK | YHM48B21 | CM48DXA1+MVC14DN21+TXV | | 28,000 | $1,400 |
| No | 206779286 | YORK | YHM48B21 | CM48DBCA1+MVC20DN21 | | 27,800 | $1,390 |
| No | 206779285 | YORK | YHM48B21 | CM48DXA1+MVC20DN21+TXV | | 27,800 | $1,390 |
| No | 206779201 | YORK | YHM48B21 | CM64DXA1+MVC20DN21+TXV | | 29,800 | $1,490 |
| No | 206779284 | YORK | YHM48B21 | CF48DXA1+MVC20DN21+TXV | | 27,800 | $1,390 |
| No | 206779200 | YORK | YHM48B21 | CF64DXA1+MVC20DN21+TXV | | 29,800 | $1,490 |
| No | 9035724 | YORK | YHM48B21 | AVC48DX21+TXV | | 28,200 | $1,410 |
| No | 206779263 | YORK | YHM48B21 | CM64DXA1+TXV | YPLC100C16MP13 | 29,000 | $1,450 |
| No | 206779262 | YORK | YHM48B21 | CM64DXA1+TXV | YPLC080C16MP13 | 29,000 | $1,450 |
| No | 206779261 | YORK | YHM48B21 | CM64DXA1+TXV | TPLC100C16MP13 | 29,000 | $1,450 |
| No | 206779260 | YORK | YHM48B21 | CM64DXA1+TXV | TPLC080C16MP13 | 29,000 | $1,450 |
| No | 206779259 | YORK | YHM48B21 | CM64DXA1+TXV | TMLV100C16MP12 | 29,000 | $1,450 |
| No | 206779258 | YORK | YHM48B21 | CM64DXA1+TXV | TM8V080C16MP12 | 29,000 | $1,450 |
| No | 206779257 | YORK | YHM48B21 | CM64DXA1+TXV | TM8V100C16MP12 | 29,000 | $1,450 |
| No | 206779256 | YORK | YHM48B21 | CF64DXA1+TXV | YPLC100C16MP13 | 29,000 | $1,450 |
| No | 206779255 | YORK | YHM48B21 | CF64DXA1+TXV | YPLC080C16MP13 | 29,000 | $1,450 |
| No | 206779254 | YORK | YHM48B21 | CF64DXA1+TXV | TPLC100C16MP13 | 29,000 | $1,450 |
| No | 206779253 | YORK | YHM48B21 | CF64DXA1+TXV | TPLC080C16MP13 | 29,000 | $1,450 |
| No | 206779252 | YORK | YHM48B21 | CF64DXA1+TXV | TMLV100C16MP12 | 29,000 | $1,450 |
| No | 206779251 | YORK | YHM48B21 | CF64DXA1+TXV | TM8V080C16MP12 | 29,000 | $1,450 |
| No | 206779250 | YORK | YHM48B21 | CF64DXA1+TXV | TM8V100C16MP12 | 29,000 | $1,450 |
| No | 206779249 | YORK | YHM48B21 | CU48CXA1+TXV | YPLC120C20MP13 | 28,000 | $1,400 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206779247 | YORK | YHM48B21 | CM48CXA1+TXV | YPLC120C20MP13 | 28,000 | $1,400 |
| No | 206779248 | YORK | YHM48B21 | CM48CBCA1 | YPLC120C20MP13 | 28,000 | $1,400 |
| No | 206779265 | YORK | YHM48B21 | CM48CBCA1 | YPLC100C20MP13 | 28,000 | $1,400 |
| No | 206779266 | YORK | YHM48B21 | CU48CXA1+TXV | YPLC100C20MP13 | 28,000 | $1,400 |
| No | 202098784 | YORK | YHM48B21 | CF48CBCA1 | YPLC120C20MP13 | 28,000 | $1,400 |
| No | 206779264 | YORK | YHM48B21 | CM48CXA1+TXV | YPLC100C20MP13 | 28,000 | $1,400 |
| No | 202098783 | YORK | YHM48B21 | CF48CBCA1 | YPLC100C20MP13 | 28,000 | $1,400 |
| No | 206779245 | YORK | YHM48B21 | CM48CBCA1 | TPLC120C20MP13 | 28,000 | $1,400 |
| No | 206779244 | YORK | YHM48B21 | CM48CXA1+TXV | TPLC120C20MP13 | 28,000 | $1,400 |
| No | 206779246 | YORK | YHM48B21 | CU48CXA1+TXV | TPLC120C20MP13 | 28,000 | $1,400 |
| No | 202098774 | YORK | YHM48B21 | CF48CBCA1 | TPLC120C20MP13 | 28,000 | $1,400 |
| No | 206779243 | YORK | YHM48B21 | CU48CXA1+TXV | TPLC100C20MP13 | 28,000 | $1,400 |
| No | 206779242 | YORK | YHM48B21 | CM48CBCA1 | TPLC100C20MP13 | 28,000 | $1,400 |
| No | 206779241 | YORK | YHM48B21 | CM48CXA1+TXV | TPLC100C20MP13 | 28,000 | $1,400 |
| No | 202098773 | YORK | YHM48B21 | CF48CBCA1 | TPLC100C20MP13 | 28,000 | $1,400 |
| No | 206779240 | YORK | YHM48B21 | CU48CXA1+TXV | TMLV120C20MP12 | 28,000 | $1,400 |
| No | 206779239 | YORK | YHM48B21 | CM48CBCA1 | TMLV120C20MP12 | 28,000 | $1,400 |
| No | 206779238 | YORK | YHM48B21 | CM48CXA1+TXV | TMLV120C20MP12 | 28,000 | $1,400 |
| No | 202098764 | YORK | YHM48B21 | CF48CBCA1 | TMLV120C20MP12 | 28,000 | $1,400 |
| No | 206779237 | YORK | YHM48B21 | CU48CXA1+TXV | TM8V100C20MP12 | 28,000 | $1,400 |
| No | 206779236 | YORK | YHM48B21 | CM48CBCA1 | TM8V100C20MP12 | 28,000 | $1,400 |
| No | 206779235 | YORK | YHM48B21 | CM48CXA1+TXV | TM8V100C20MP12 | 28,000 | $1,400 |
| No | 202098753 | YORK | YHM48B21 | CF48CBCA1 | TM8V100C20MP12 | 28,000 | $1,400 |
| No | 206779234 | YORK | YHM48B21 | CU48CXA1+TXV | TM8V120C20MP12 | 28,000 | $1,400 |
| No | 206779233 | YORK | YHM48B21 | CM48CBCA1 | TM8V120C20MP12 | 28,000 | $1,400 |
| No | 206779232 | YORK | YHM48B21 | CM48CXA1+TXV | TM8V120C20MP12 | 28,000 | $1,400 |
| No | 202098754 | YORK | YHM48B21 | CF48CBCA1 | TM8V120C20MP12 | 28,000 | $1,400 |
| No | 206779228 | YORK | YHM48B21 | CF48CXA1+TXV | YPLC120C20MP13 | 28,000 | $1,400 |
| No | 206779227 | YORK | YHM48B21 | CF48CXA1+TXV | YPLC100C20MP13 | 28,000 | $1,400 |
| No | 206779226 | YORK | YHM48B21 | CF48CXA1+TXV | TPLC120C20MP13 | 28,000 | $1,400 |
| No | 206779224 | YORK | YHM48B21 | CF48CXA1+TXV | TMLV120C20MP12 | 28,000 | $1,400 |
| No | 206779225 | YORK | YHM48B21 | CF48CXA1+TXV | TPLC100C20MP13 | 28,000 | $1,400 |
| No | 206779223 | YORK | YHM48B21 | CF48CXA1+TXV | TM8V100C20MP12 | 28,000 | $1,400 |
| No | 206779222 | YORK | YHM48B21 | CF48CXA1+TXV | TM8V120C20MP12 | 28,000 | $1,400 |
| No | 206779328 | YORK | YHM48B21 | CM64DXA1+TXV | YP9C100C16MP13 | 29,200 | $1,460 |
| No | 206779327 | YORK | YHM48B21 | CM64DXA1+TXV | TP9C100C16MP13 | 29,200 | $1,460 |
| No | 206779326 | YORK | YHM48B21 | CM64DXA1+TXV | TM9V100C16MP12 | 29,200 | $1,460 |
| No | 206779325 | YORK | YHM48B21 | CF64DXA1+TXV | YP9C100C16MP13 | 29,200 | $1,460 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206779324 | YORK | YHM48B21 | CF64DXA1+TXV | TP9C100C16MP13 | 29,200 | $1,460 |
| No | 206779323 | YORK | YHM48B21 | CF64DXA1+TXV | TM9V100C16MP12 | 29,200 | $1,460 |
| No | 206779565 | YORK | YHM48B21 | CU48CXA1+TXV | YP9C100C20MP13 | 28,400 | $1,420 |
| No | 206779564 | YORK | YHM48B21 | CM48CBCA1 | YP9C100C20MP13 | 28,400 | $1,420 |
| No | 206779563 | YORK | YHM48B21 | CM48CXA1+TXV | YP9C100C20MP13 | 28,400 | $1,420 |
| No | 202098779 | YORK | YHM48B21 | CF48CBCA1 | YP9C100C20MP13 | 28,400 | $1,420 |
| No | 206779562 | YORK | YHM48B21 | CU48CXA1+TXV | TP9C100C20MP13 | 28,400 | $1,420 |
| No | 206779561 | YORK | YHM48B21 | CM48CBCA1 | TP9C100C20MP13 | 28,400 | $1,420 |
| No | 206779560 | YORK | YHM48B21 | CM48CXA1+TXV | TP9C100C20MP13 | 28,400 | $1,420 |
| No | 202098769 | YORK | YHM48B21 | CF48CBCA1 | TP9C100C20MP13 | 28,400 | $1,420 |
| No | 206779559 | YORK | YHM48B21 | CU48CXA1+TXV | TM9V100C20MP12 | 28,400 | $1,420 |
| No | 206779558 | YORK | YHM48B21 | CM48CBCA1 | TM9V100C20MP12 | 28,400 | $1,420 |
| No | 206779557 | YORK | YHM48B21 | CM48CXA1+TXV | TM9V100C20MP12 | 28,400 | $1,420 |
| No | 202098759 | YORK | YHM48B21 | CF48CBCA1 | TM9V100C20MP12 | 28,400 | $1,420 |
| No | 206779554 | YORK | YHM48B21 | CF48CXA1+TXV | YP9C100C20MP13 | 28,400 | $1,420 |
| No | 206779553 | YORK | YHM48B21 | CF48CXA1+TXV | TP9C100C20MP13 | 28,400 | $1,420 |
| No | 206779552 | YORK | YHM48B21 | CF48CXA1+TXV | TM9V100C20MP12 | 28,400 | $1,420 |
| No | 206779277 | YORK | YHM48B21 | CM64DXA1+TXV | YP9C100C20MP13 | 29,000 | $1,450 |
| No | 206779275 | YORK | YHM48B21 | CM64DXA1+TXV | TM9V100C20MP12 | 29,000 | $1,450 |
| No | 206779274 | YORK | YHM48B21 | CF64DXA1+TXV | YP9C100C20MP13 | 29,000 | $1,450 |
| No | 206779273 | YORK | YHM48B21 | CF64DXA1+TXV | TP9C100C20MP13 | 29,000 | $1,450 |
| No | 206779272 | YORK | YHM48B21 | CF64DXA1+TXV | TM9V100C20MP12 | 29,000 | $1,450 |
| No | 206779276 | YORK | YHM48B21 | CM64DXA1+TXV | TP9C100C20MP13 | 29,000 | $1,450 |
| No | 205537427 | YORK | YHM48B21 | CM64DXA1+TXV | TM8Y080C16MP11 | 29,400 | $1,470 |
| No | 205537424 | YORK | YHM48B21 | CM64DXA1+TXV | TM8Y100C16MP11 | 29,400 | $1,470 |
| No | 205537415 | YORK | YHM48B21 | CF64DXA1+TXV | TM8Y080C16MP11 | 29,400 | $1,470 |
| No | 205537414 | YORK | YHM48B21 | CF64DXA1+TXV | TM8Y100C16MP11 | 29,400 | $1,470 |
| No | 206921029 | YORK | HMH72B241 | CF36BXA1+TXV | TM9E040A10MP12 | 14,500 | $725 |
| No | 206921032 | YORK | HMH72B241 | CM36BBAA1 | TM9E040A10MP12 | 14,500 | $725 |
| No | 206921030 | YORK | HMH72B241 | CF36BBAA1 | TM9E040A10MP12 | 14,500 | $725 |
| No | 206921031 | YORK | HMH72B241 | CM36BXA1+TXV | TM9E040A10MP12 | 14,500 | $725 |
| No | 206921033 | YORK | HMH72B241 | CU36BXA1+TXV | TM9E040A10MP12 | 14,500 | $725 |
| No | 207334432 | YORK | HMH72B241 | CF36AXA1+TXV | TM8Y060A12MP11 | 14,200 | $710 |
| No | 207334428 | YORK | HMH72B241 | CF36BBAA1 | TM8Y060A12MP11 | 14,300 | $715 |
| No | 207334433 | YORK | HMH72B241 | CM36AXA1+TXV | TM8Y060A12MP11 | 14,200 | $710 |
| No | 207334427 | YORK | HMH72B241 | CF36BXA1+TXV | TM8Y060A12MP11 | 14,300 | $715 |
| No | 207334429 | YORK | HMH72B241 | CM36BXA1+TXV | TM8Y060A12MP11 | 14,300 | $715 |
| No | 207334430 | YORK | HMH72B241 | CM36BBAA1 | TM8Y060A12MP11 | 14,300 | $715 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207334431 | YORK | HMH72B241 | CU36BXA1+TXV | TM8Y060A12MP11 | 14,300 | $715 |
| No | 207175977 | YORK | HMH72B241 | CF36CXA1+TXV | TM9Y060B12MP11 | 14,500 | $725 |
| No | 207175978 | YORK | HMH72B241 | CM36CXA1+TXV | TM9Y060B12MP11 | 14,500 | $725 |
| No | 206920998 | YORK | HMH72B241 | CF36CXA1+TXV | TM9V060B12MP12 | 14,500 | $725 |
| No | 206920999 | YORK | HMH72B241 | CF36CXA1+TXV | TP9C060B12MP13 | 14,500 | $725 |
| No | 206921000 | YORK | HMH72B241 | CF36CXA1+TXV | YP9C060B12MP13 | 14,500 | $725 |
| No | 206921001 | YORK | HMH72B241 | CM36CXA1+TXV | TM9V060B12MP12 | 14,500 | $725 |
| No | 207334422 | YORK | HMH72B241 | CF36BXA1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 206921003 | YORK | HMH72B241 | CM36CXA1+TXV | TP9C060B12MP13 | 14,500 | $725 |
| No | 206921005 | YORK | HMH72B241 | CM36CXA1+TXV | YP9C060B12MP13 | 14,500 | $725 |
| No | 207334420 | YORK | HMH72B241 | CF36CXA1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207334421 | YORK | HMH72B241 | CM36CXA1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207334423 | YORK | HMH72B241 | CF36BBAA1 | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207334424 | YORK | HMH72B241 | CM36BXA1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207334425 | YORK | HMH72B241 | CM36BBAA1 | TM8Y080B12MP11 | 14,300 | $715 |
| No | 207334426 | YORK | HMH72B241 | CU36BXA1+TXV | TM8Y080B12MP11 | 14,300 | $715 |
| No | 206920983 | YORK | HMH72B241 | CF36BXA1+TXV | TM9V080B12MP12 | 14,400 | $720 |
| No | 206920984 | YORK | HMH72B241 | CF36BXA1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 206920985 | YORK | HMH72B241 | CF36BXA1+TXV | YP9C080B12MP13 | 14,400 | $720 |
| No | 206920986 | YORK | HMH72B241 | CF36BBAA1 | TM9V080B12MP12 | 14,400 | $720 |
| No | 206920987 | YORK | HMH72B241 | CM36BXA1+TXV | TM9V080B12MP12 | 14,400 | $720 |
| No | 206920989 | YORK | HMH72B241 | CU36BXA1+TXV | TM9V080B12MP12 | 14,400 | $720 |
| No | 206920988 | YORK | HMH72B241 | CM36BBAA1 | TM9V080B12MP12 | 14,400 | $720 |
| No | 206920993 | YORK | HMH72B241 | CU36BXA1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 206920990 | YORK | HMH72B241 | CF36BBAA1 | TP9C080B12MP13 | 14,400 | $720 |
| No | 206920991 | YORK | HMH72B241 | CM36BXA1+TXV | TP9C080B12MP13 | 14,400 | $720 |
| No | 206920992 | YORK | HMH72B241 | CM36BBAA1 | TP9C080B12MP13 | 14,400 | $720 |
| No | 206920994 | YORK | HMH72B241 | CF36BBAA1 | YP9C080B12MP13 | 14,400 | $720 |
| No | 206920995 | YORK | HMH72B241 | CM36BXA1+TXV | YP9C080B12MP13 | 14,400 | $720 |
| No | 206920996 | YORK | HMH72B241 | CM36BBAA1 | YP9C080B12MP13 | 14,400 | $720 |
| No | 207251145 | YORK | HMH72B481 | CF64DXA1+TXV | TM9E100C16MP12 | 31,000 | $1,550 |
| No | 206920997 | YORK | HMH72B241 | CU36BXA1+TXV | YP9C080B12MP13 | 14,400 | $720 |
| No | 207251146 | YORK | HMH72B481 | CM64DXA1+TXV | TM9E100C16MP12 | 31,000 | $1,550 |
| No | 206971126 | YORK | HMH72B481 | CF64DXA1+TXV | TM9V080C16MP12 | 30,800 | $1,540 |
| No | 206971127 | YORK | HMH72B481 | CF64DXA1+TXV | TP9C080C16MP13 | 30,800 | $1,540 |
| No | 206971128 | YORK | HMH72B481 | CF64DXA1+TXV | YP9C080C16MP13 | 30,800 | $1,540 |
| No | 206971129 | YORK | HMH72B481 | CM64DXA1+TXV | TM9V080C16MP12 | 30,800 | $1,540 |
| No | 206971130 | YORK | HMH72B481 | CM64DXA1+TXV | TP9C080C16MP13 | 30,800 | $1,540 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207175973 | YORK | HMH72B481 | CF64DXA1+TXV | TM9Y100C16MP11 | 30,200 | $1,510 |
| No | 206971131 | YORK | HMH72B481 | CM64DXA1+TXV | YP9C080C16MP13 | 30,800 | $1,540 |
| No | 207175974 | YORK | HMH72B481 | CM64DXA1+TXV | TM9Y100C16MP11 | 30,200 | $1,510 |
| No | 206920974 | YORK | HMH72B241 | CF36CXA1+TXV | TM9V080B12MP12 | 14,300 | $715 |
| No | 206920975 | YORK | HMH72B241 | CF36CXA1+TXV | TP9C080B12MP13 | 14,300 | $715 |
| No | 206920976 | YORK | HMH72B241 | CF36CXA1+TXV | YP9C080B12MP13 | 14,300 | $715 |
| No | 206920977 | YORK | HMH72B241 | CM36CXA1+TXV | TM9V080B12MP12 | 14,300 | $715 |
| No | 206920979 | YORK | HMH72B241 | CM36CXA1+TXV | TP9C080B12MP13 | 14,300 | $715 |
| No | 206920981 | YORK | HMH72B241 | CM36CXA1+TXV | YP9C080B12MP13 | 14,300 | $715 |
| No | 207251147 | YORK | HMH72B481 | CF64DXA1+TXV | TM9E080C16MP12 | 31,200 | $1,560 |
| No | 207251148 | YORK | HMH72B481 | CM64DXA1+TXV | TM9E080C16MP12 | 31,200 | $1,560 |
| No | 206971164 | YORK | HMH72B481 | CF64DXA1+TXV | TL9E080C16UH11 | 29,600 | $1,480 |
| No | 206971165 | YORK | HMH72B481 | CM64DXA1+TXV | TL9E080C16UH11 | 29,600 | $1,480 |
| No | 206921043 | YORK | HMH72B241 | CF36CXA1+TXV | TM8V100C16MP12 | 14,300 | $715 |
| No | 206921044 | YORK | HMH72B241 | CF36CXA1+TXV | TM8V080C16MP12 | 14,300 | $715 |
| No | 206921045 | YORK | HMH72B241 | CF36CXA1+TXV | TMLV100C16MP12 | 14,300 | $715 |
| No | 206921046 | YORK | HMH72B241 | CF36CXA1+TXV | TPLC080C16MP13 | 14,300 | $715 |
| No | 206921047 | YORK | HMH72B241 | CF36CXA1+TXV | TPLC100C16MP13 | 14,300 | $715 |
| No | 206921048 | YORK | HMH72B241 | CF36CXA1+TXV | YPLC080C16MP13 | 14,300 | $715 |
| No | 206921049 | YORK | HMH72B241 | CF36CXA1+TXV | YPLC100C16MP13 | 14,300 | $715 |
| No | 206921050 | YORK | HMH72B241 | CM36CXA1+TXV | TM8V100C16MP12 | 14,300 | $715 |
| No | 206921052 | YORK | HMH72B241 | CM36CXA1+TXV | TM8V080C16MP12 | 14,300 | $715 |
| No | 206921054 | YORK | HMH72B241 | CM36CXA1+TXV | TMLV100C16MP12 | 14,300 | $715 |
| No | 206921060 | YORK | HMH72B241 | CM36CXA1+TXV | YPLC080C16MP13 | 14,300 | $715 |
| No | 206921056 | YORK | HMH72B241 | CM36CXA1+TXV | TPLC080C16MP13 | 14,300 | $715 |
| No | 206921058 | YORK | HMH72B241 | CM36CXA1+TXV | TPLC100C16MP13 | 14,300 | $715 |
| No | 206921062 | YORK | HMH72B241 | CM36CXA1+TXV | YPLC100C16MP13 | 14,300 | $715 |
| No | 207175975 | YORK | HMH72B481 | CF64DXA1+TXV | TM9Y080C16MP11 | 30,200 | $1,510 |
| No | 207175976 | YORK | HMH72B481 | CM64DXA1+TXV | TM9Y080C16MP11 | 30,200 | $1,510 |
| No | 207334438 | YORK | HMH72B481 | CF64DXA1+TXV | TM8Y080C16MP11 | 30,200 | $1,510 |
| No | 207334439 | YORK | HMH72B481 | CM64DXA1+TXV | TM8Y080C16MP11 | 30,200 | $1,510 |
| No | 206971172 | YORK | HMH72B481 | CF64DXA1+TXV | TM8E100C16MP11 | 30,200 | $1,510 |
| No | 206971173 | YORK | HMH72B481 | CF64DXA1+TXV | TMLE100C16MP11 | 30,200 | $1,510 |
| No | 206971174 | YORK | HMH72B481 | CM64DXA1+TXV | TM8E100C16MP11 | 30,200 | $1,510 |
| No | 206971177 | YORK | HMH72B481 | CM64DXA1+TXV | TL8E080C16UH11 | 30,200 | $1,510 |
| No | 206971175 | YORK | HMH72B481 | CM64DXA1+TXV | TMLE100C16MP11 | 30,200 | $1,510 |
| No | 206971176 | YORK | HMH72B481 | CF64DXA1+TXV | TL8E080C16UH11 | 30,200 | $1,510 |
| No | 206971108 | YORK | HMH72B481 | CF64DXA1+TXV | TM9V100C16MP12 | 30,800 | $1,540 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206971109 | YORK | HMH72B481 | CF64DXA1+TXV | TP9C100C16MP13 | 30,800 | $1,540 |
| No | 206971110 | YORK | HMH72B481 | CF64DXA1+TXV | YP9C100C16MP13 | 30,800 | $1,540 |
| No | 206971111 | YORK | HMH72B481 | CM64DXA1+TXV | TM9V100C16MP12 | 30,800 | $1,540 |
| No | 206971112 | YORK | HMH72B481 | CM64DXA1+TXV | TP9C100C16MP13 | 30,800 | $1,540 |
| No | 206971113 | YORK | HMH72B481 | CM64DXA1+TXV | YP9C100C16MP13 | 30,800 | $1,540 |
| No | 206971120 | YORK | HMH72B481 | CF64DXA1+TXV | TM9V100C20MP12 | 31,000 | $1,550 |
| No | 206971121 | YORK | HMH72B481 | CF64DXA1+TXV | TP9C100C20MP13 | 31,000 | $1,550 |
| No | 206971122 | YORK | HMH72B481 | CF64DXA1+TXV | YP9C100C20MP13 | 31,000 | $1,550 |
| No | 206971124 | YORK | HMH72B481 | CM64DXA1+TXV | TP9C100C20MP13 | 31,000 | $1,550 |
| No | 206971123 | YORK | HMH72B481 | CM64DXA1+TXV | TM9V100C20MP12 | 31,000 | $1,550 |
| No | 206971170 | YORK | HMH72B481 | CM64DXA1+TXV | TM8E120C16MP11 | 30,200 | $1,510 |
| No | 206971125 | YORK | HMH72B481 | CM64DXA1+TXV | YP9C100C20MP13 | 31,000 | $1,550 |
| No | 206971168 | YORK | HMH72B481 | CF64DXA1+TXV | TM8E120C16MP11 | 30,200 | $1,510 |
| No | 206971169 | YORK | HMH72B481 | CF64DXA1+TXV | TMLE120C16MP11 | 30,200 | $1,510 |
| No | 206971171 | YORK | HMH72B481 | CM64DXA1+TXV | TMLE120C16MP11 | 30,200 | $1,510 |
| No | 206971162 | YORK | HMH72B481 | CM64DXA1+TXV | TM8E080C16MP11 | 30,200 | $1,510 |
| No | 206971160 | YORK | HMH72B481 | CF64DXA1+TXV | TM8E080C16MP11 | 30,200 | $1,510 |
| No | 206971161 | YORK | HMH72B481 | CF64DXA1+TXV | TMLE080C16MP11 | 30,200 | $1,510 |
| No | 206971163 | YORK | HMH72B481 | CM64DXA1+TXV | TMLE080C16MP11 | 30,200 | $1,510 |
| No | 206971148 | YORK | HMH72B481 | CF64DXA1+TXV | TMLV100C16MP12 | 29,600 | $1,480 |
| No | 206971146 | YORK | HMH72B481 | CF64DXA1+TXV | TM8V100C16MP12 | 29,600 | $1,480 |
| No | 206971147 | YORK | HMH72B481 | CF64DXA1+TXV | TM8V080C16MP12 | 29,600 | $1,480 |
| No | 206971149 | YORK | HMH72B481 | CF64DXA1+TXV | TPLC080C16MP13 | 29,600 | $1,480 |
| No | 206971150 | YORK | HMH72B481 | CF64DXA1+TXV | TPLC100C16MP13 | 29,600 | $1,480 |
| No | 206971151 | YORK | HMH72B481 | CF64DXA1+TXV | YPLC080C16MP13 | 29,600 | $1,480 |
| No | 206971152 | YORK | HMH72B481 | CF64DXA1+TXV | YPLC100C16MP13 | 29,600 | $1,480 |
| No | 206971153 | YORK | HMH72B481 | CM64DXA1+TXV | TM8V100C16MP12 | 29,600 | $1,480 |
| No | 206971154 | YORK | HMH72B481 | CM64DXA1+TXV | TM8V080C16MP12 | 29,600 | $1,480 |
| No | 206971155 | YORK | HMH72B481 | CM64DXA1+TXV | TMLV100C16MP12 | 29,600 | $1,480 |
| No | 206971156 | YORK | HMH72B481 | CM64DXA1+TXV | TPLC080C16MP13 | 29,600 | $1,480 |
| No | 206971157 | YORK | HMH72B481 | CM64DXA1+TXV | TPLC100C16MP13 | 29,600 | $1,480 |
| No | 206971159 | YORK | HMH72B481 | CM64DXA1+TXV | YPLC100C16MP13 | 29,600 | $1,480 |
| No | 206971158 | YORK | HMH72B481 | CM64DXA1+TXV | YPLC080C16MP13 | 29,600 | $1,480 |
| No | 207175971 | YORK | HMH72B481 | CF64DXA1+TXV | TM9Y120D20MP11 | 30,600 | $1,530 |
| No | 207175972 | YORK | HMH72B481 | CM64DXA1+TXV | TM9Y120D20MP11 | 30,600 | $1,530 |
| No | 207334434 | YORK | HMH72B481 | CF64DXA1+TXV | TM8Y120C20MP11 | 29,800 | $1,490 |
| No | 207334435 | YORK | HMH72B481 | CF64DXA1+TXV | TM8Y100C20MP11 | 29,800 | $1,490 |
| No | 207334436 | YORK | HMH72B481 | CM64DXA1+TXV | TM8Y120C20MP11 | 29,800 | $1,490 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207334437 | YORK | HMH72B481 | CM64DXA1+TXV | TM8Y100C20MP11 | 29,800 | $1,490 |
| No | 206971132 | YORK | HMH72B481 | CF64DXA1+TXV | TM8V120C20MP12 | 29,800 | $1,490 |
| No | 206971133 | YORK | HMH72B481 | CF64DXA1+TXV | TM8V100C20MP12 | 29,800 | $1,490 |
| No | 206971134 | YORK | HMH72B481 | CF64DXA1+TXV | TMLV120C20MP12 | 29,800 | $1,490 |
| No | 206971135 | YORK | HMH72B481 | CF64DXA1+TXV | TPLC100C20MP13 | 29,800 | $1,490 |
| No | 206971136 | YORK | HMH72B481 | CF64DXA1+TXV | TPLC120C20MP13 | 29,800 | $1,490 |
| No | 206971137 | YORK | HMH72B481 | CF64DXA1+TXV | YPLC100C20MP13 | 29,800 | $1,490 |
| No | 206971138 | YORK | HMH72B481 | CF64DXA1+TXV | YPLC120C20MP13 | 29,800 | $1,490 |
| No | 206971139 | YORK | HMH72B481 | CM64DXA1+TXV | TM8V120C20MP12 | 29,800 | $1,490 |
| No | 206971141 | YORK | HMH72B481 | CM64DXA1+TXV | TMLV120C20MP12 | 29,800 | $1,490 |
| No | 206971140 | YORK | HMH72B481 | CM64DXA1+TXV | TM8V100C20MP12 | 29,800 | $1,490 |
| No | 206971143 | YORK | HMH72B481 | CM64DXA1+TXV | TPLC120C20MP13 | 29,800 | $1,490 |
| No | 206971142 | YORK | HMH72B481 | CM64DXA1+TXV | TPLC100C20MP13 | 29,800 | $1,490 |
| No | 206971144 | YORK | HMH72B481 | CM64DXA1+TXV | YPLC100C20MP13 | 29,800 | $1,490 |
| No | 206971145 | YORK | HMH72B481 | CM64DXA1+TXV | YPLC120C20MP13 | 29,800 | $1,490 |
| No | 206971114 | YORK | HMH72B481 | CF64DXA1+TXV | TM9V120D20MP12 | 30,800 | $1,540 |
| No | 206971115 | YORK | HMH72B481 | CF64DXA1+TXV | TP9C120D20MP13 | 30,800 | $1,540 |
| No | 206971116 | YORK | HMH72B481 | CF64DXA1+TXV | YP9C120D20MP13 | 30,800 | $1,540 |
| No | 206971117 | YORK | HMH72B481 | CM64DXA1+TXV | TM9V120D20MP12 | 30,800 | $1,540 |
| No | 206971118 | YORK | HMH72B481 | CM64DXA1+TXV | TP9C120D20MP13 | 30,800 | $1,540 |
| No | 206971119 | YORK | HMH72B481 | CM64DXA1+TXV | YP9C120D20MP13 | 30,800 | $1,540 |
| No | 206971166 | YORK | HMH72B481 | CF64DXA1+TXV | TL8E100C20UH11 | 30,000 | $1,500 |
| No | 206971167 | YORK | HMH72B481 | CM64DXA1+TXV | TL8E100C20UH11 | 30,000 | $1,500 |
| No | 206921214 | YORK | HMH72B361 | CF36CXA1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 206921215 | YORK | HMH72B361 | CF36CXA1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 206921216 | YORK | HMH72B361 | CF36CXA1+TXV | YP9C060B12MP13 | 25,000 | $1,250 |
| No | 206921217 | YORK | HMH72B361 | CM36CXA1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 206921218 | YORK | HMH72B361 | CM36CBCA1 | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 206921262 | YORK | HMH72B361 | CM36BXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206921263 | YORK | HMH72B361 | CM36BBCA1 | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206921350 | YORK | HMH72B361 | CF36BXA1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 206921264 | YORK | HMH72B361 | CU36BXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206921349 | YORK | HMH72B361 | CF36BXA1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 206921352 | YORK | HMH72B361 | CF36BBCA1 | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 206921351 | YORK | HMH72B361 | CF36BXA1+TXV | YPLC080B12MP13 | 24,600 | $1,230 |
| No | 206921353 | YORK | HMH72B361 | CM36BXA1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 206921354 | YORK | HMH72B361 | CM36BBCA1 | TM8V080B12MP12 | 24,600 | $1,230 |
| No | 206921355 | YORK | HMH72B361 | CU36BXA1+TXV | TM8V080B12MP12 | 24,600 | $1,230 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921356 | YORK | HMH72B361 | CF36BBCA1 | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 206921357 | YORK | HMH72B361 | CM36BXA1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 206921358 | YORK | HMH72B361 | CM36BBCA1 | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 206921359 | YORK | HMH72B361 | CU36BXA1+TXV | TPLC080B12MP13 | 24,600 | $1,230 |
| No | 206921361 | YORK | HMH72B361 | CM36BXA1+TXV | YPLC080B12MP13 | 24,600 | $1,230 |
| No | 206921360 | YORK | HMH72B361 | CF36BBCA1 | YPLC080B12MP13 | 24,600 | $1,230 |
| No | 206921362 | YORK | HMH72B361 | CM36BBCA1 | YPLC080B12MP13 | 24,600 | $1,230 |
| No | 206921363 | YORK | HMH72B361 | CU36BXA1+TXV | YPLC080B12MP13 | 24,600 | $1,230 |
| No | 206921364 | YORK | HMH72B361 | CF36BXA1+TXV | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 206921365 | YORK | HMH72B361 | CF36BXA1+TXV | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 206921366 | YORK | HMH72B361 | CF36BXA1+TXV | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 206921367 | YORK | HMH72B361 | CF36BXA1+TXV | YPLC060A12MP13 | 25,000 | $1,250 |
| No | 206921368 | YORK | HMH72B361 | CF36BBCA1 | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 206921369 | YORK | HMH72B361 | CM36BXA1+TXV | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 206921372 | YORK | HMH72B361 | CF36BBCA1 | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 206921370 | YORK | HMH72B361 | CM36BBCA1 | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 206921371 | YORK | HMH72B361 | CU36BXA1+TXV | TM8V060A12MP12 | 25,000 | $1,250 |
| No | 206921373 | YORK | HMH72B361 | CM36BXA1+TXV | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 206921374 | YORK | HMH72B361 | CM36BBCA1 | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 206921375 | YORK | HMH72B361 | CU36BXA1+TXV | TMLV060A12MP12 | 25,000 | $1,250 |
| No | 206921376 | YORK | HMH72B361 | CF36BBCA1 | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 206921377 | YORK | HMH72B361 | CM36BXA1+TXV | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 206921378 | YORK | HMH72B361 | CM36BBCA1 | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 206921379 | YORK | HMH72B361 | CU36BXA1+TXV | TPLC060A12MP13 | 25,000 | $1,250 |
| No | 206921381 | YORK | HMH72B361 | CM36BXA1+TXV | YPLC060A12MP13 | 25,000 | $1,250 |
| No | 206921380 | YORK | HMH72B361 | CF36BBCA1 | YPLC060A12MP13 | 25,000 | $1,250 |
| No | 206921383 | YORK | HMH72B361 | CU36BXA1+TXV | YPLC060A12MP13 | 25,000 | $1,250 |
| No | 206921382 | YORK | HMH72B361 | CM36BBCA1 | YPLC060A12MP13 | 25,000 | $1,250 |
| No | 206921503 | YORK | HMH72B361 | CM36AXA1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206921502 | YORK | HMH72B361 | CF36AXA1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206921442 | YORK | HMH72B361 | CF36BXA1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 206921443 | YORK | HMH72B361 | CF36BXA1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 206921444 | YORK | HMH72B361 | CF36BBCA1 | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 206921445 | YORK | HMH72B361 | CM36BXA1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 206921446 | YORK | HMH72B361 | CM36BBCA1 | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 206921447 | YORK | HMH72B361 | CU36BXA1+TXV | TM8E080B12MP11 | 24,800 | $1,240 |
| No | 206921449 | YORK | HMH72B361 | CM36BXA1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 206921448 | YORK | HMH72B361 | CF36BBCA1 | TMLE080B12MP11 | 24,800 | $1,240 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921450 | YORK | HMH72B361 | CM36BBCA1 | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 206921451 | YORK | HMH72B361 | CU36BXA1+TXV | TMLE080B12MP11 | 24,800 | $1,240 |
| No | 206921452 | YORK | HMH72B361 | CF36BXA1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206921453 | YORK | HMH72B361 | CF36BXA1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206921454 | YORK | HMH72B361 | CF36BBCA1 | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206921455 | YORK | HMH72B361 | CM36BXA1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206921456 | YORK | HMH72B361 | CM36BBCA1 | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206921457 | YORK | HMH72B361 | CU36BXA1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206921458 | YORK | HMH72B361 | CF36BBCA1 | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206921459 | YORK | HMH72B361 | CM36BXA1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206921460 | YORK | HMH72B361 | CM36BBCA1 | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206921461 | YORK | HMH72B361 | CU36BXA1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206921497 | YORK | HMH72B361 | CF36BXA1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206921498 | YORK | HMH72B361 | CF36BBCA1 | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206921499 | YORK | HMH72B361 | CM36BXA1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206921500 | YORK | HMH72B361 | CM36BBCA1 | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206921501 | YORK | HMH72B361 | CU36BXA1+TXV | TL8E060A12UH11 | 24,600 | $1,230 |
| No | 206921199 | YORK | HMH72B361 | CF36BXA1+TXV | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 206921200 | YORK | HMH72B361 | CF36BXA1+TXV | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 206921201 | YORK | HMH72B361 | CF36BXA1+TXV | YP9C080B12MP13 | 24,600 | $1,230 |
| No | 206921203 | YORK | HMH72B361 | CM36BXA1+TXV | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 206921202 | YORK | HMH72B361 | CF36BBCA1 | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 206921204 | YORK | HMH72B361 | CM36BBCA1 | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 206921205 | YORK | HMH72B361 | CU36BXA1+TXV | TM9V080B12MP12 | 24,600 | $1,230 |
| No | 206921206 | YORK | HMH72B361 | CF36BBCA1 | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 206921207 | YORK | HMH72B361 | CM36BXA1+TXV | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 206921208 | YORK | HMH72B361 | CM36BBCA1 | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 206921209 | YORK | HMH72B361 | CU36BXA1+TXV | TP9C080B12MP13 | 24,600 | $1,230 |
| No | 206921213 | YORK | HMH72B361 | CU36BXA1+TXV | YP9C080B12MP13 | 24,600 | $1,230 |
| No | 206921210 | YORK | HMH72B361 | CF36BBCA1 | YP9C080B12MP13 | 24,600 | $1,230 |
| No | 206921211 | YORK | HMH72B361 | CM36BXA1+TXV | YP9C080B12MP13 | 24,600 | $1,230 |
| No | 206921212 | YORK | HMH72B361 | CM36BBCA1 | YP9C080B12MP13 | 24,600 | $1,230 |
| No | 206921256 | YORK | HMH72B361 | CF36CXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206921257 | YORK | HMH72B361 | CM36CXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206921258 | YORK | HMH72B361 | CM36CBCA1 | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 207175953 | YORK | HMH72B361 | CF36BXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 207175954 | YORK | HMH72B361 | CF36BBCA1 | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 207175955 | YORK | HMH72B361 | CM36BXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921408 | YORK | HMH72B361 | CF36CXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 207175956 | YORK | HMH72B361 | CM36BBCA1 | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 207175957 | YORK | HMH72B361 | CU36BXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 206921409 | YORK | HMH72B361 | CF36CXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206921410 | YORK | HMH72B361 | CM36CXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206921411 | YORK | HMH72B361 | CM36CBCA1 | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206921413 | YORK | HMH72B361 | CM36CXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206921414 | YORK | HMH72B361 | CM36CBCA1 | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 207175945 | YORK | HMH72B361 | CF36CXA1+TXV | TM9Y080C16MP11 | 24,600 | $1,230 |
| No | 207175946 | YORK | HMH72B361 | CM36CXA1+TXV | TM9Y080C16MP11 | 24,600 | $1,230 |
| No | 207175947 | YORK | HMH72B361 | CM36CBCA1 | TM9Y080C16MP11 | 24,600 | $1,230 |
| No | 207175962 | YORK | HMH72B361 | CF36BXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207175963 | YORK | HMH72B361 | CF36BBCA1 | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207175964 | YORK | HMH72B361 | CM36BXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207175965 | YORK | HMH72B361 | CM36BBCA1 | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207175966 | YORK | HMH72B361 | CU36BXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207334451 | YORK | HMH72B361 | CF36BXA1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 207334452 | YORK | HMH72B361 | CF36BBCA1 | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 207334453 | YORK | HMH72B361 | CM36BXA1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 207334454 | YORK | HMH72B361 | CM36BBCA1 | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 207334455 | YORK | HMH72B361 | CU36BXA1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 206921269 | YORK | HMH72B361 | CF36BXA1+TXV | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 206921270 | YORK | HMH72B361 | CF36BBCA1 | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 206921271 | YORK | HMH72B361 | CM36BXA1+TXV | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 206921272 | YORK | HMH72B361 | CM36BBCA1 | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 206921273 | YORK | HMH72B361 | CU36BXA1+TXV | TM9E060B12MP12 | 24,400 | $1,220 |
| No | 206921337 | YORK | HMH72B361 | CF36CXA1+TXV | TM8V080B12MP12 | 24,400 | $1,220 |
| No | 206921338 | YORK | HMH72B361 | CF36CXA1+TXV | TPLC080B12MP13 | 24,400 | $1,220 |
| No | 206921339 | YORK | HMH72B361 | CF36CXA1+TXV | YPLC080B12MP13 | 24,400 | $1,220 |
| No | 206921340 | YORK | HMH72B361 | CM36CXA1+TXV | TM8V080B12MP12 | 24,400 | $1,220 |
| No | 206921341 | YORK | HMH72B361 | CM36CBCA1 | TM8V080B12MP12 | 24,400 | $1,220 |
| No | 206921343 | YORK | HMH72B361 | CM36CXA1+TXV | TPLC080B12MP13 | 24,400 | $1,220 |
| No | 206921344 | YORK | HMH72B361 | CM36CBCA1 | TPLC080B12MP13 | 24,400 | $1,220 |
| No | 206921347 | YORK | HMH72B361 | CM36CBCA1 | YPLC080B12MP13 | 24,400 | $1,220 |
| No | 206921346 | YORK | HMH72B361 | CM36CXA1+TXV | YPLC080B12MP13 | 24,400 | $1,220 |
| No | 206921419 | YORK | HMH72B361 | CM36BXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206921416 | YORK | HMH72B361 | CF36BXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206921417 | YORK | HMH72B361 | CF36BXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921418 | YORK | HMH72B361 | CF36BBCA1 | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206921420 | YORK | HMH72B361 | CM36BBCA1 | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206921421 | YORK | HMH72B361 | CU36BXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206921422 | YORK | HMH72B361 | CF36BBCA1 | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206921423 | YORK | HMH72B361 | CM36BXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206921424 | YORK | HMH72B361 | CM36BBCA1 | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206921425 | YORK | HMH72B361 | CU36BXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206921434 | YORK | HMH72B361 | CF36CXA1+TXV | TM8E080B12MP11 | 24,600 | $1,230 |
| No | 206921435 | YORK | HMH72B361 | CF36CXA1+TXV | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 206921437 | YORK | HMH72B361 | CM36CBCA1 | TM8E080B12MP11 | 24,600 | $1,230 |
| No | 206921436 | YORK | HMH72B361 | CM36CXA1+TXV | TM8E080B12MP11 | 24,600 | $1,230 |
| No | 206921439 | YORK | HMH72B361 | CM36CXA1+TXV | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 206921440 | YORK | HMH72B361 | CM36CBCA1 | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 206971063 | YORK | HMH72B601 | CF64DXA1+TXV | TM9V080C16MP12 | 38,000 | $1,900 |
| No | 206971064 | YORK | HMH72B601 | CF64DXA1+TXV | TP9C080C16MP13 | 38,000 | $1,900 |
| No | 206971065 | YORK | HMH72B601 | CF64DXA1+TXV | YP9C080C16MP13 | 38,000 | $1,900 |
| No | 206971066 | YORK | HMH72B601 | CM64DXA1+TXV | TM9V080C16MP12 | 38,000 | $1,900 |
| No | 206971067 | YORK | HMH72B601 | CM64DXA1+TXV | TP9C080C16MP13 | 38,000 | $1,900 |
| No | 206971068 | YORK | HMH72B601 | CM64DXA1+TXV | YP9C080C16MP13 | 38,000 | $1,900 |
| No | 207334456 | YORK | HMH72B361 | CF36AXA1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 207334457 | YORK | HMH72B361 | CM36AXA1+TXV | TM8Y060A12MP11 | 24,400 | $1,220 |
| No | 206921241 | YORK | HMH72B361 | CF36BXA1+TXV | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 206921242 | YORK | HMH72B361 | CF36BBCA1 | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 206921243 | YORK | HMH72B361 | CM36BXA1+TXV | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 206921244 | YORK | HMH72B361 | CM36BBCA1 | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 206921245 | YORK | HMH72B361 | CU36BXA1+TXV | TM9V040A10MP12 | 24,200 | $1,210 |
| No | 206921279 | YORK | HMH72B361 | CF36AXA1+TXV | TM9E060A10MP12 | 24,200 | $1,210 |
| No | 206921280 | YORK | HMH72B361 | CM36AXA1+TXV | TM9E060A10MP12 | 24,200 | $1,210 |
| No | 206921476 | YORK | HMH72B361 | CF36AXA1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206921477 | YORK | HMH72B361 | CF36AXA1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 206921478 | YORK | HMH72B361 | CM36AXA1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206921479 | YORK | HMH72B361 | CM36AXA1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 207175958 | YORK | HMH72B361 | CF36CXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207175960 | YORK | HMH72B361 | CM36CBCA1 | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207175959 | YORK | HMH72B361 | CM36CXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207334446 | YORK | HMH72B361 | CF36BXA1+TXV | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 207334447 | YORK | HMH72B361 | CF36BBCA1 | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 207334448 | YORK | HMH72B361 | CM36BXA1+TXV | TM8Y080B12MP11 | 24,600 | $1,230 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207334449 | YORK | HMH72B361 | CM36BBCA1 | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 207334450 | YORK | HMH72B361 | CU36BXA1+TXV | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 207175949 | YORK | HMH72B361 | CF36CXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 207175950 | YORK | HMH72B361 | CM36CXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 207175951 | YORK | HMH72B361 | CM36CBCA1 | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 206921175 | YORK | HMH72B361 | CF36CXA1+TXV | TM9V080C16MP12 | 24,400 | $1,220 |
| No | 206921176 | YORK | HMH72B361 | CF36CXA1+TXV | TP9C080C16MP13 | 24,400 | $1,220 |
| No | 206921178 | YORK | HMH72B361 | CM36CXA1+TXV | TM9V080C16MP12 | 24,400 | $1,220 |
| No | 206921177 | YORK | HMH72B361 | CF36CXA1+TXV | YP9C080C16MP13 | 24,400 | $1,220 |
| No | 206921179 | YORK | HMH72B361 | CM36CBCA1 | TM9V080C16MP12 | 24,400 | $1,220 |
| No | 206921181 | YORK | HMH72B361 | CM36CXA1+TXV | TP9C080C16MP13 | 24,400 | $1,220 |
| No | 206921182 | YORK | HMH72B361 | CM36CBCA1 | TP9C080C16MP13 | 24,400 | $1,220 |
| No | 206921184 | YORK | HMH72B361 | CM36CXA1+TXV | YP9C080C16MP13 | 24,400 | $1,220 |
| No | 206921185 | YORK | HMH72B361 | CM36CBCA1 | YP9C080C16MP13 | 24,400 | $1,220 |
| No | 206921252 | YORK | HMH72B361 | CF36CXA1+TXV | TM9E080C16MP12 | 24,600 | $1,230 |
| No | 206921254 | YORK | HMH72B361 | CM36CBCA1 | TM9E080C16MP12 | 24,600 | $1,230 |
| No | 206921253 | YORK | HMH72B361 | CM36CXA1+TXV | TM9E080C16MP12 | 24,600 | $1,230 |
| No | 206921482 | YORK | HMH72B361 | CM36CBCA1 | TL9E080C16UH11 | 24,600 | $1,230 |
| No | 206921480 | YORK | HMH72B361 | CF36CXA1+TXV | TL9E080C16UH11 | 24,600 | $1,230 |
| No | 206921481 | YORK | HMH72B361 | CM36CXA1+TXV | TL9E080C16UH11 | 24,600 | $1,230 |
| No | 206921226 | YORK | HMH72B361 | CF36BXA1+TXV | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 206921227 | YORK | HMH72B361 | CF36BXA1+TXV | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 206921228 | YORK | HMH72B361 | CF36BXA1+TXV | YP9C060B12MP13 | 24,400 | $1,220 |
| No | 206921229 | YORK | HMH72B361 | CF36BBCA1 | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 206921230 | YORK | HMH72B361 | CM36BXA1+TXV | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 206921231 | YORK | HMH72B361 | CM36BBCA1 | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 206921232 | YORK | HMH72B361 | CU36BXA1+TXV | TM9V060B12MP12 | 24,400 | $1,220 |
| No | 206921233 | YORK | HMH72B361 | CF36BBCA1 | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 206921234 | YORK | HMH72B361 | CM36BXA1+TXV | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 206921235 | YORK | HMH72B361 | CM36BBCA1 | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 206921239 | YORK | HMH72B361 | CM36BBCA1 | YP9C060B12MP13 | 24,400 | $1,220 |
| No | 206921238 | YORK | HMH72B361 | CM36BXA1+TXV | YP9C060B12MP13 | 24,400 | $1,220 |
| No | 206921236 | YORK | HMH72B361 | CU36BXA1+TXV | TP9C060B12MP13 | 24,400 | $1,220 |
| No | 206921237 | YORK | HMH72B361 | CF36BBCA1 | YP9C060B12MP13 | 24,400 | $1,220 |
| No | 206921240 | YORK | HMH72B361 | CU36BXA1+TXV | YP9C060B12MP13 | 24,400 | $1,220 |
| No | 206921309 | YORK | HMH72B361 | CF36CXA1+TXV | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 206921310 | YORK | HMH72B361 | CF36CXA1+TXV | TM8V080C16MP12 | 24,600 | $1,230 |
| No | 206921311 | YORK | HMH72B361 | CF36CXA1+TXV | TMLV100C16MP12 | 24,600 | $1,230 |

Updated: June 19, 2023

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921312 | YORK | HMH72B361 | CF36CXA1+TXV | TPLC080C16MP13 | 24,600 | $1,230 |
| No | 206921313 | YORK | HMH72B361 | CF36CXA1+TXV | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 206921315 | YORK | HMH72B361 | CF36CXA1+TXV | YPLC100C16MP13 | 24,600 | $1,230 |
| No | 206921314 | YORK | HMH72B361 | CF36CXA1+TXV | YPLC080C16MP13 | 24,600 | $1,230 |
| No | 206921316 | YORK | HMH72B361 | CM36CXA1+TXV | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 206921317 | YORK | HMH72B361 | CM36CBCA1 | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 206921319 | YORK | HMH72B361 | CM36CXA1+TXV | TM8V080C16MP12 | 24,600 | $1,230 |
| No | 206921320 | YORK | HMH72B361 | CM36CBCA1 | TM8V080C16MP12 | 24,600 | $1,230 |
| No | 206921322 | YORK | HMH72B361 | CM36CXA1+TXV | TMLV100C16MP12 | 24,600 | $1,230 |
| No | 206921323 | YORK | HMH72B361 | CM36CBCA1 | TMLV100C16MP12 | 24,600 | $1,230 |
| No | 206921325 | YORK | HMH72B361 | CM36CXA1+TXV | TPLC080C16MP13 | 24,600 | $1,230 |
| No | 206921326 | YORK | HMH72B361 | CM36CBCA1 | TPLC080C16MP13 | 24,600 | $1,230 |
| No | 206921328 | YORK | HMH72B361 | CM36CXA1+TXV | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 206921329 | YORK | HMH72B361 | CM36CBCA1 | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 206921331 | YORK | HMH72B361 | CM36CXA1+TXV | YPLC080C16MP13 | 24,600 | $1,230 |
| No | 206921334 | YORK | HMH72B361 | CM36CXA1+TXV | YPLC100C16MP13 | 24,600 | $1,230 |
| No | 206921332 | YORK | HMH72B361 | CM36CBCA1 | YPLC080C16MP13 | 24,600 | $1,230 |
| No | 206921335 | YORK | HMH72B361 | CM36CBCA1 | YPLC100C16MP13 | 24,600 | $1,230 |
| No | 206921466 | YORK | HMH72B361 | CF36BXA1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206921467 | YORK | HMH72B361 | CF36BXA1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 206921468 | YORK | HMH72B361 | CF36BBCA1 | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206921469 | YORK | HMH72B361 | CM36BXA1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206921470 | YORK | HMH72B361 | CM36BBCA1 | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206921471 | YORK | HMH72B361 | CU36BXA1+TXV | TM8E040A12MP11 | 24,600 | $1,230 |
| No | 206921472 | YORK | HMH72B361 | CF36BBCA1 | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 206921473 | YORK | HMH72B361 | CM36BXA1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 206921474 | YORK | HMH72B361 | CM36BBCA1 | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 206921475 | YORK | HMH72B361 | CU36BXA1+TXV | TMLE040A12MP11 | 24,600 | $1,230 |
| No | 206921488 | YORK | HMH72B361 | CF36BXA1+TXV | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 206921489 | YORK | HMH72B361 | CF36BBCA1 | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 206921291 | YORK | HMH72B361 | CM36CXA1+TXV | TM8V100C20MP12 | 24,600 | $1,230 |
| No | 206921490 | YORK | HMH72B361 | CM36BXA1+TXV | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 206921491 | YORK | HMH72B361 | CM36BBCA1 | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 206921492 | YORK | HMH72B361 | CU36BXA1+TXV | TL9E060B12UH11 | 24,200 | $1,210 |
| No | 206921281 | YORK | HMH72B361 | CF36CXA1+TXV | TM8V120C20MP12 | 24,600 | $1,230 |
| No | 206921282 | YORK | HMH72B361 | CF36CXA1+TXV | TM8V100C20MP12 | 24,600 | $1,230 |
| No | 206921283 | YORK | HMH72B361 | CF36CXA1+TXV | TMLV120C20MP12 | 24,600 | $1,230 |
| No | 206921287 | YORK | HMH72B361 | CF36CXA1+TXV | YPLC120C20MP13 | 24,600 | $1,230 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921284 | YORK | HMH72B361 | CF36CXA1+TXV | TPLC100C20MP13 | 24,600 | $1,230 |
| No | 206921285 | YORK | HMH72B361 | CF36CXA1+TXV | TPLC120C20MP13 | 24,600 | $1,230 |
| No | 206921286 | YORK | HMH72B361 | CF36CXA1+TXV | YPLC100C20MP13 | 24,600 | $1,230 |
| No | 206921288 | YORK | HMH72B361 | CM36CXA1+TXV | TM8V120C20MP12 | 24,600 | $1,230 |
| No | 206921289 | YORK | HMH72B361 | CM36CBCA1 | TM8V120C20MP12 | 24,600 | $1,230 |
| No | 206921292 | YORK | HMH72B361 | CM36CBCA1 | TM8V100C20MP12 | 24,600 | $1,230 |
| No | 206921294 | YORK | HMH72B361 | CM36CXA1+TXV | TMLV120C20MP12 | 24,600 | $1,230 |
| No | 206921295 | YORK | HMH72B361 | CM36CBCA1 | TMLV120C20MP12 | 24,600 | $1,230 |
| No | 206921297 | YORK | HMH72B361 | CM36CXA1+TXV | TPLC100C20MP13 | 24,600 | $1,230 |
| No | 206921298 | YORK | HMH72B361 | CM36CBCA1 | TPLC100C20MP13 | 24,600 | $1,230 |
| No | 206921300 | YORK | HMH72B361 | CM36CXA1+TXV | TPLC120C20MP13 | 24,600 | $1,230 |
| No | 206921301 | YORK | HMH72B361 | CM36CBCA1 | TPLC120C20MP13 | 24,600 | $1,230 |
| No | 206921303 | YORK | HMH72B361 | CM36CXA1+TXV | YPLC100C20MP13 | 24,600 | $1,230 |
| No | 206921304 | YORK | HMH72B361 | CM36CBCA1 | YPLC100C20MP13 | 24,600 | $1,230 |
| No | 206921306 | YORK | HMH72B361 | CM36CXA1+TXV | YPLC120C20MP13 | 24,600 | $1,230 |
| No | 206921307 | YORK | HMH72B361 | CM36CBCA1 | YPLC120C20MP13 | 24,600 | $1,230 |
| No | 206921248 | YORK | HMH72B361 | CF36CXA1+TXV | TM9E100C16MP12 | 24,600 | $1,230 |
| No | 206921249 | YORK | HMH72B361 | CM36CXA1+TXV | TM9E100C16MP12 | 24,600 | $1,230 |
| No | 206921250 | YORK | HMH72B361 | CM36CBCA1 | TM9E100C16MP12 | 24,600 | $1,230 |
| No | 207334418 | YORK | HMH72B601 | CF64DXA1+TXV | TM8Y080C16MP11 | 38,000 | $1,900 |
| No | 207334419 | YORK | HMH72B601 | CM64DXA1+TXV | TM8Y080C16MP11 | 38,000 | $1,900 |
| No | 206971087 | YORK | HMH72B601 | CF64DXA1+TXV | TL8E080C16UH11 | 38,000 | $1,900 |
| No | 206971088 | YORK | HMH72B601 | CM64DXA1+TXV | TL8E080C16UH11 | 38,000 | $1,900 |
| No | 207334443 | YORK | HMH72B361 | CF36CXA1+TXV | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 207334444 | YORK | HMH72B361 | CM36CXA1+TXV | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 207334445 | YORK | HMH72B361 | CM36CBCA1 | TM8Y080B12MP11 | 24,600 | $1,230 |
| No | 206921187 | YORK | HMH72B361 | CF36CXA1+TXV | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 206921188 | YORK | HMH72B361 | CF36CXA1+TXV | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 206921189 | YORK | HMH72B361 | CF36CXA1+TXV | YP9C080B12MP13 | 24,400 | $1,220 |
| No | 206921190 | YORK | HMH72B361 | CM36CXA1+TXV | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 206921191 | YORK | HMH72B361 | CM36CBCA1 | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 206921193 | YORK | HMH72B361 | CM36CXA1+TXV | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 206921194 | YORK | HMH72B361 | CM36CBCA1 | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 206921196 | YORK | HMH72B361 | CM36CXA1+TXV | YP9C080B12MP13 | 24,400 | $1,220 |
| No | 206921197 | YORK | HMH72B361 | CM36CBCA1 | YP9C080B12MP13 | 24,400 | $1,220 |
| No | 206921151 | YORK | HMH72B361 | CF36CXA1+TXV | TM9V100C20MP12 | 24,400 | $1,220 |
| No | 206921152 | YORK | HMH72B361 | CF36CXA1+TXV | TP9C100C20MP13 | 24,400 | $1,220 |
| No | 206921153 | YORK | HMH72B361 | CF36CXA1+TXV | YP9C100C20MP13 | 24,400 | $1,220 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921154 | YORK | HMH72B361 | CM36CXA1+TXV | TM9V100C20MP12 | 24,400 | $1,220 |
| No | 206921155 | YORK | HMH72B361 | CM36CBCA1 | TM9V100C20MP12 | 24,400 | $1,220 |
| No | 206921157 | YORK | HMH72B361 | CM36CXA1+TXV | TP9C100C20MP13 | 24,400 | $1,220 |
| No | 206921158 | YORK | HMH72B361 | CM36CBCA1 | TP9C100C20MP13 | 24,400 | $1,220 |
| No | 206921160 | YORK | HMH72B361 | CM36CXA1+TXV | YP9C100C20MP13 | 24,400 | $1,220 |
| No | 206921161 | YORK | HMH72B361 | CM36CBCA1 | YP9C100C20MP13 | 24,400 | $1,220 |
| No | 206921392 | YORK | HMH72B361 | CF36CXA1+TXV | TM8E120C16MP11 | 24,600 | $1,230 |
| No | 206921393 | YORK | HMH72B361 | CF36CXA1+TXV | TMLE120C16MP11 | 24,600 | $1,230 |
| No | 206921394 | YORK | HMH72B361 | CM36CXA1+TXV | TM8E120C16MP11 | 24,600 | $1,230 |
| No | 206921395 | YORK | HMH72B361 | CM36CBCA1 | TM8E120C16MP11 | 24,600 | $1,230 |
| No | 206921397 | YORK | HMH72B361 | CM36CXA1+TXV | TMLE120C16MP11 | 24,600 | $1,230 |
| No | 206921398 | YORK | HMH72B361 | CM36CBCA1 | TMLE120C16MP11 | 24,600 | $1,230 |
| No | 206921400 | YORK | HMH72B361 | CF36CXA1+TXV | TM8E100C16MP11 | 24,600 | $1,230 |
| No | 206921401 | YORK | HMH72B361 | CF36CXA1+TXV | TMLE100C16MP11 | 24,600 | $1,230 |
| No | 206921402 | YORK | HMH72B361 | CM36CXA1+TXV | TM8E100C16MP11 | 24,600 | $1,230 |
| No | 206921403 | YORK | HMH72B361 | CM36CBCA1 | TM8E100C16MP11 | 24,600 | $1,230 |
| No | 206921405 | YORK | HMH72B361 | CM36CXA1+TXV | TMLE100C16MP11 | 24,600 | $1,230 |
| No | 206921406 | YORK | HMH72B361 | CM36CBCA1 | TMLE100C16MP11 | 24,600 | $1,230 |
| No | 206971035 | YORK | HMH72B601 | CF64DXA1+TXV | TM9V100C20MP12 | 38,000 | $1,900 |
| No | 206971036 | YORK | HMH72B601 | CF64DXA1+TXV | TP9C100C20MP13 | 38,000 | $1,900 |
| No | 206971059 | YORK | HMH72B601 | CF64DXA1+TXV | TM8E100C16MP11 | 38,000 | $1,900 |
| No | 206971037 | YORK | HMH72B601 | CF64DXA1+TXV | YP9C100C20MP13 | 38,000 | $1,900 |
| No | 206971038 | YORK | HMH72B601 | CM64DXA1+TXV | TM9V100C20MP12 | 38,000 | $1,900 |
| No | 206971039 | YORK | HMH72B601 | CM64DXA1+TXV | TP9C100C20MP13 | 38,000 | $1,900 |
| No | 206971040 | YORK | HMH72B601 | CM64DXA1+TXV | YP9C100C20MP13 | 38,000 | $1,900 |
| No | 206971060 | YORK | HMH72B601 | CF64DXA1+TXV | TMLE100C16MP11 | 38,000 | $1,900 |
| No | 206971061 | YORK | HMH72B601 | CM64DXA1+TXV | TM8E100C16MP11 | 38,000 | $1,900 |
| No | 206971062 | YORK | HMH72B601 | CM64DXA1+TXV | TMLE100C16MP11 | 38,000 | $1,900 |
| No | 206971079 | YORK | HMH72B601 | CF64DXA1+TXV | TM8E080C16MP11 | 38,000 | $1,900 |
| No | 206971080 | YORK | HMH72B601 | CF64DXA1+TXV | TMLE080C16MP11 | 38,000 | $1,900 |
| No | 206971081 | YORK | HMH72B601 | CM64DXA1+TXV | TM8E080C16MP11 | 38,000 | $1,900 |
| No | 206971082 | YORK | HMH72B601 | CM64DXA1+TXV | TMLE080C16MP11 | 38,000 | $1,900 |
| No | 206921246 | YORK | HMH72B361 | CF36AXA1+TXV | TM9V040A10MP12 | 24,000 | $1,200 |
| No | 206921247 | YORK | HMH72B361 | CM36AXA1+TXV | TM9V040A10MP12 | 24,000 | $1,200 |
| No | 206921384 | YORK | HMH72B361 | CF36AXA1+TXV | TM8V060A12MP12 | 24,200 | $1,210 |
| No | 206921385 | YORK | HMH72B361 | CF36AXA1+TXV | TMLV060A12MP12 | 24,200 | $1,210 |
| No | 206921386 | YORK | HMH72B361 | CF36AXA1+TXV | TPLC060A12MP13 | 24,200 | $1,210 |
| No | 206921387 | YORK | HMH72B361 | CF36AXA1+TXV | YPLC060A12MP13 | 24,200 | $1,210 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921388 | YORK | HMH72B361 | CM36AXA1+TXV | TM8V060A12MP12 | 24,200 | $1,210 |
| No | 206921163 | YORK | HMH72B361 | CF36CXA1+TXV | TM9V100C16MP12 | 24,400 | $1,220 |
| No | 206921389 | YORK | HMH72B361 | CM36AXA1+TXV | TMLV060A12MP12 | 24,200 | $1,210 |
| No | 206921390 | YORK | HMH72B361 | CM36AXA1+TXV | TPLC060A12MP13 | 24,200 | $1,210 |
| No | 206921391 | YORK | HMH72B361 | CM36AXA1+TXV | YPLC060A12MP13 | 24,200 | $1,210 |
| No | 206921164 | YORK | HMH72B361 | CF36CXA1+TXV | TP9C100C16MP13 | 24,400 | $1,220 |
| No | 206921165 | YORK | HMH72B361 | CF36CXA1+TXV | YP9C100C16MP13 | 24,400 | $1,220 |
| No | 206921166 | YORK | HMH72B361 | CM36CXA1+TXV | TM9V100C16MP12 | 24,400 | $1,220 |
| No | 206921167 | YORK | HMH72B361 | CM36CBCA1 | TM9V100C16MP12 | 24,400 | $1,220 |
| No | 206921169 | YORK | HMH72B361 | CM36CXA1+TXV | TP9C100C16MP13 | 24,400 | $1,220 |
| No | 206921170 | YORK | HMH72B361 | CM36CBCA1 | TP9C100C16MP13 | 24,400 | $1,220 |
| No | 206921172 | YORK | HMH72B361 | CM36CXA1+TXV | YP9C100C16MP13 | 24,400 | $1,220 |
| No | 206921173 | YORK | HMH72B361 | CM36CBCA1 | YP9C100C16MP13 | 24,400 | $1,220 |
| No | 206971051 | YORK | HMH72B601 | CF64DXA1+TXV | TM8E120C16MP11 | 38,000 | $1,900 |
| No | 206971052 | YORK | HMH72B601 | CF64DXA1+TXV | TMLE120C16MP11 | 38,000 | $1,900 |
| No | 206971053 | YORK | HMH72B601 | CM64DXA1+TXV | TM8E120C16MP11 | 38,000 | $1,900 |
| No | 206921426 | YORK | HMH72B361 | CF36CXA1+TXV | TM8E080C16MP11 | 24,400 | $1,220 |
| No | 206971054 | YORK | HMH72B601 | CM64DXA1+TXV | TMLE120C16MP11 | 38,000 | $1,900 |
| No | 207175967 | YORK | HMH72B601 | CF64DXA1+TXV | TM9Y120D20MP11 | 38,000 | $1,900 |
| No | 207175968 | YORK | HMH72B601 | CM64DXA1+TXV | TM9Y120D20MP11 | 38,000 | $1,900 |
| No | 206921427 | YORK | HMH72B361 | CF36CXA1+TXV | TMLE080C16MP11 | 24,400 | $1,220 |
| No | 206921428 | YORK | HMH72B361 | CM36CXA1+TXV | TM8E080C16MP11 | 24,400 | $1,220 |
| No | 206921429 | YORK | HMH72B361 | CM36CBCA1 | TM8E080C16MP11 | 24,400 | $1,220 |
| No | 206921431 | YORK | HMH72B361 | CM36CXA1+TXV | TMLE080C16MP11 | 24,400 | $1,220 |
| No | 206921432 | YORK | HMH72B361 | CM36CBCA1 | TMLE080C16MP11 | 24,400 | $1,220 |
| No | 206971041 | YORK | HMH72B601 | CF64DXA1+TXV | TM9V100C16MP12 | 38,000 | $1,900 |
| No | 206971042 | YORK | HMH72B601 | CF64DXA1+TXV | TP9C100C16MP13 | 38,000 | $1,900 |
| No | 206971043 | YORK | HMH72B601 | CF64DXA1+TXV | YP9C100C16MP13 | 38,000 | $1,900 |
| No | 206971044 | YORK | HMH72B601 | CM64DXA1+TXV | TM9V100C16MP12 | 38,000 | $1,900 |
| No | 206971045 | YORK | HMH72B601 | CM64DXA1+TXV | TP9C100C16MP13 | 38,000 | $1,900 |
| No | 206971046 | YORK | HMH72B601 | CM64DXA1+TXV | YP9C100C16MP13 | 38,000 | $1,900 |
| No | 206971069 | YORK | HMH72B601 | CF64DXA1+TXV | TM9E120D20MP12 | 38,500 | $1,925 |
| No | 206971070 | YORK | HMH72B601 | CM64DXA1+TXV | TM9E120D20MP12 | 38,500 | $1,925 |
| No | 206971089 | YORK | HMH72B601 | CF64DXA1+TXV | TM8V120C20MP12 | 39,000 | $1,950 |
| No | 206971090 | YORK | HMH72B601 | CF64DXA1+TXV | TM8V100C20MP12 | 39,000 | $1,950 |
| No | 206971091 | YORK | HMH72B601 | CF64DXA1+TXV | TMLV120C20MP12 | 39,000 | $1,950 |
| No | 206971092 | YORK | HMH72B601 | CF64DXA1+TXV | TPLC100C20MP13 | 39,000 | $1,950 |
| No | 206971093 | YORK | HMH72B601 | CF64DXA1+TXV | TPLC120C20MP13 | 39,000 | $1,950 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206971094 | YORK | HMH72B601 | CF64DXA1+TXV | YPLC100C20MP13 | 39,000 | $1,950 |
| No | 206971096 | YORK | HMH72B601 | CM64DXA1+TXV | TM8V120C20MP12 | 39,000 | $1,950 |
| No | 206971095 | YORK | HMH72B601 | CF64DXA1+TXV | YPLC120C20MP13 | 39,000 | $1,950 |
| No | 206971097 | YORK | HMH72B601 | CM64DXA1+TXV | TM8V100C20MP12 | 39,000 | $1,950 |
| No | 206971098 | YORK | HMH72B601 | CM64DXA1+TXV | TMLV120C20MP12 | 39,000 | $1,950 |
| No | 206971099 | YORK | HMH72B601 | CM64DXA1+TXV | TPLC100C20MP13 | 39,000 | $1,950 |
| No | 206971100 | YORK | HMH72B601 | CM64DXA1+TXV | TPLC120C20MP13 | 39,000 | $1,950 |
| No | 207175969 | YORK | HMH72B601 | CF64DXA1+TXV | TM9Y100C20MP11 | 38,000 | $1,900 |
| No | 206971101 | YORK | HMH72B601 | CM64DXA1+TXV | YPLC100C20MP13 | 39,000 | $1,950 |
| No | 206971102 | YORK | HMH72B601 | CM64DXA1+TXV | YPLC120C20MP13 | 39,000 | $1,950 |
| No | 207175970 | YORK | HMH72B601 | CM64DXA1+TXV | TM9Y100C20MP11 | 38,000 | $1,900 |
| No | 206971055 | YORK | HMH72B601 | CF64DXA1+TXV | TM8E100C20MP11 | 38,500 | $1,925 |
| No | 206971056 | YORK | HMH72B601 | CF64DXA1+TXV | TMLE100C20MP11 | 38,500 | $1,925 |
| No | 206971057 | YORK | HMH72B601 | CM64DXA1+TXV | TM8E100C20MP11 | 38,500 | $1,925 |
| No | 206971058 | YORK | HMH72B601 | CM64DXA1+TXV | TMLE100C20MP11 | 38,500 | $1,925 |
| No | 207175941 | YORK | HMH72B361 | CF36CXA1+TXV | TM9Y100C16MP11 | 24,200 | $1,210 |
| No | 207175942 | YORK | HMH72B361 | CM36CXA1+TXV | TM9Y100C16MP11 | 24,200 | $1,210 |
| No | 207175943 | YORK | HMH72B361 | CM36CBCA1 | TM9Y100C16MP11 | 24,200 | $1,210 |
| No | 206971083 | YORK | HMH72B601 | CF64DXA1+TXV | TL9E100C20UH11 | 38,000 | $1,900 |
| No | 206971084 | YORK | HMH72B601 | CM64DXA1+TXV | TL9E100C20UH11 | 38,000 | $1,900 |
| No | 206971072 | YORK | HMH72B601 | CM64DXA1+TXV | TM9E100C20MP12 | 38,500 | $1,925 |
| No | 206971071 | YORK | HMH72B601 | CF64DXA1+TXV | TM9E100C20MP12 | 38,500 | $1,925 |
| No | 206971085 | YORK | HMH72B601 | CF64DXA1+TXV | TL8E100C20UH11 | 38,000 | $1,900 |
| No | 206971086 | YORK | HMH72B601 | CM64DXA1+TXV | TL8E100C20UH11 | 38,000 | $1,900 |
| No | 206971073 | YORK | HMH72B601 | CF64DXA1+TXV | TM9E080C20MP12 | 38,500 | $1,925 |
| No | 206971074 | YORK | HMH72B601 | CM64DXA1+TXV | TM9E080C20MP12 | 38,500 | $1,925 |
| No | 206971033 | YORK | HMH72B601 | CM64DXA1+TXV | TP9C120D20MP13 | 39,000 | $1,950 |
| No | 206971029 | YORK | HMH72B601 | CF64DXA1+TXV | TM9V120D20MP12 | 39,000 | $1,950 |
| No | 206971030 | YORK | HMH72B601 | CF64DXA1+TXV | TP9C120D20MP13 | 39,000 | $1,950 |
| No | 206971031 | YORK | HMH72B601 | CF64DXA1+TXV | YP9C120D20MP13 | 39,000 | $1,950 |
| No | 206971032 | YORK | HMH72B601 | CM64DXA1+TXV | TM9V120D20MP12 | 39,000 | $1,950 |
| No | 206971034 | YORK | HMH72B601 | CM64DXA1+TXV | YP9C120D20MP13 | 39,000 | $1,950 |
| No | 207334414 | YORK | HMH72B601 | CF64DXA1+TXV | TM8Y120C20MP11 | 37,800 | $1,890 |
| No | 207334415 | YORK | HMH72B601 | CF64DXA1+TXV | TM8Y100C20MP11 | 37,800 | $1,890 |
| No | 207334416 | YORK | HMH72B601 | CM64DXA1+TXV | TM8Y120C20MP11 | 37,800 | $1,890 |
| No | 207334417 | YORK | HMH72B601 | CM64DXA1+TXV | TM8Y100C20MP11 | 37,800 | $1,890 |
| No | 206971047 | YORK | HMH72B601 | CF64DXA1+TXV | TM8E120C20MP11 | 37,600 | $1,880 |
| No | 206971048 | YORK | HMH72B601 | CF64DXA1+TXV | TMLE120C20MP11 | 37,600 | $1,880 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206971049 | YORK | HMH72B601 | CM64DXA1+TXV | TM8E120C20MP11 | 37,600 | $1,880 |
| No | 206971050 | YORK | HMH72B601 | CM64DXA1+TXV | TMLE120C20MP11 | 37,600 | $1,880 |
| No | 207334440 | YORK | HMH72B361 | CF36CXA1+TXV | TM8Y080C16MP11 | 24,200 | $1,210 |
| No | 207334441 | YORK | HMH72B361 | CM36CXA1+TXV | TM8Y080C16MP11 | 24,200 | $1,210 |
| No | 206921493 | YORK | HMH72B361 | CF36CXA1+TXV | TL8E080C16UH11 | 24,000 | $1,200 |
| No | 207334442 | YORK | HMH72B361 | CM36CBCA1 | TM8Y080C16MP11 | 24,200 | $1,210 |
| No | 206921495 | YORK | HMH72B361 | CM36CBCA1 | TL8E080C16UH11 | 24,000 | $1,200 |
| No | 206921494 | YORK | HMH72B361 | CM36CXA1+TXV | TL8E080C16UH11 | 24,000 | $1,200 |
| No | 206971075 | YORK | HMH72B601 | CF64DXA1+TXV | TM8E080C20MP11 | 37,800 | $1,890 |
| No | 206971076 | YORK | HMH72B601 | CF64DXA1+TXV | TMLE080C20MP11 | 37,800 | $1,890 |
| No | 206971077 | YORK | HMH72B601 | CM64DXA1+TXV | TM8E080C20MP11 | 37,800 | $1,890 |
| No | 206971078 | YORK | HMH72B601 | CM64DXA1+TXV | TMLE080C20MP11 | 37,800 | $1,890 |
| No | 206921223 | YORK | HMH72B361 | CM36CXA1+TXV | YP9C060B12MP13 | 25,000 | $1,250 |
| No | 206921220 | YORK | HMH72B361 | CM36CXA1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 206921221 | YORK | HMH72B361 | CM36CBCA1 | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 206921224 | YORK | HMH72B361 | CM36CBCA1 | YP9C060B12MP13 | 25,000 | $1,250 |
| No | 206921265 | YORK | HMH72B361 | CF36CXA1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 206921266 | YORK | HMH72B361 | CM36CXA1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 206921267 | YORK | HMH72B361 | CM36CBCA1 | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 206921485 | YORK | HMH72B361 | CM36CXA1+TXV | TL9E060B12UH11 | 24,800 | $1,240 |
| No | 206921484 | YORK | HMH72B361 | CF36CXA1+TXV | TL9E060B12UH11 | 24,800 | $1,240 |
| No | 206921486 | YORK | HMH72B361 | CM36CBCA1 | TL9E060B12UH11 | 24,800 | $1,240 |
| No | 206921274 | YORK | HMH72B361 | CF36BXA1+TXV | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 206921275 | YORK | HMH72B361 | CF36BBCA1 | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 206921276 | YORK | HMH72B361 | CM36BXA1+TXV | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 206921277 | YORK | HMH72B361 | CM36BBCA1 | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 206921278 | YORK | HMH72B361 | CU36BXA1+TXV | TM9E060A10MP12 | 24,600 | $1,230 |
| No | 206921462 | YORK | HMH72B361 | CF36AXA1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206921463 | YORK | HMH72B361 | CF36AXA1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206921464 | YORK | HMH72B361 | CM36AXA1+TXV | TM8E060A12MP11 | 24,600 | $1,230 |
| No | 206921465 | YORK | HMH72B361 | CM36AXA1+TXV | TMLE060A12MP11 | 24,600 | $1,230 |
| No | 206921260 | YORK | HMH72B361 | CF36BXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206921261 | YORK | HMH72B361 | CF36BBCA1 | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206921528 | YORK | HMH72B361 | AE36BX21+TXV | | 24,400 | $1,220 |
| No | 206971182 | YORK | HMH72B481 | AVC60DX21+TXV | | 30,600 | $1,530 |
| No | 206971183 | YORK | HMH72B481 | CF64DXA1+ME14DN21+TXV | | 30,000 | $1,500 |
| No | 206971184 | YORK | HMH72B481 | CM64DXA1+ME14DN21+TXV | | 30,000 | $1,500 |
| No | 207175944 | YORK | HMH72B361 | CU36CXA1+TXV | TM9Y100C16MP11 | 24,200 | $1,210 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207175948 | YORK | HMH72B361 | CU36CXA1+TXV | TM9Y080C16MP11 | 24,600 | $1,230 |
| No | 207175961 | YORK | HMH72B361 | CU36CXA1+TXV | TM9Y060B12MP11 | 24,600 | $1,230 |
| No | 207175952 | YORK | HMH72B361 | CU36CXA1+TXV | TM9Y080B12MP11 | 24,600 | $1,230 |
| No | 207175979 | YORK | HMH72B241 | CU36CXA1+TXV | TM9Y060B12MP11 | 14,500 | $725 |
| No | 207175985 | YORK | HMH72B241 | AE36BX21+TXV | | 14,300 | $715 |
| No | 207175986 | YORK | HMH72B241 | AE36BBA21 | | 14,300 | $715 |
| No | 206921180 | YORK | HMH72B361 | CU36CXA1+TXV | TM9V080C16MP12 | 24,400 | $1,220 |
| No | 206921183 | YORK | HMH72B361 | CU36CXA1+TXV | TP9C080C16MP13 | 24,400 | $1,220 |
| No | 206921186 | YORK | HMH72B361 | CU36CXA1+TXV | YP9C080C16MP13 | 24,400 | $1,220 |
| No | 206921192 | YORK | HMH72B361 | CU36CXA1+TXV | TM9V080B12MP12 | 24,400 | $1,220 |
| No | 206921195 | YORK | HMH72B361 | CU36CXA1+TXV | TP9C080B12MP13 | 24,400 | $1,220 |
| No | 206921198 | YORK | HMH72B361 | CU36CXA1+TXV | YP9C080B12MP13 | 24,400 | $1,220 |
| No | 206921219 | YORK | HMH72B361 | CU36CXA1+TXV | TM9V060B12MP12 | 25,000 | $1,250 |
| No | 206921222 | YORK | HMH72B361 | CU36CXA1+TXV | TP9C060B12MP13 | 25,000 | $1,250 |
| No | 206921225 | YORK | HMH72B361 | CU36CXA1+TXV | YP9C060B12MP13 | 25,000 | $1,250 |
| No | 206921255 | YORK | HMH72B361 | CU36CXA1+TXV | TM9E080C16MP12 | 24,600 | $1,230 |
| No | 206921487 | YORK | HMH72B361 | CU36CXA1+TXV | TL9E060B12UH11 | 24,800 | $1,240 |
| No | 206921496 | YORK | HMH72B361 | CU36CXA1+TXV | TL8E080C16UH11 | 24,000 | $1,200 |
| No | 206921504 | YORK | HMH72B361 | CF36CXA1+MVC16CN21+TXV | | 24,200 | $1,210 |
| No | 206921505 | YORK | HMH72B361 | CM36CXA1+MVC16CN21+TXV | | 24,200 | $1,210 |
| No | 206921506 | YORK | HMH72B361 | CM36CBCA1+MVC16CN21 | | 24,200 | $1,210 |
| No | 206921507 | YORK | HMH72B361 | CF36CXA1+MVC12CN21+TXV | | 24,000 | $1,200 |
| No | 206921508 | YORK | HMH72B361 | CM36CXA1+MVC12CN21+TXV | | 24,000 | $1,200 |
| No | 206921509 | YORK | HMH72B361 | CM36CBCA1+MVC12CN21 | | 24,000 | $1,200 |
| No | 206921002 | YORK | HMH72B241 | CU36CXA1+TXV | TM9V060B12MP12 | 14,500 | $725 |
| No | 206921004 | YORK | HMH72B241 | CU36CXA1+TXV | TP9C060B12MP13 | 14,500 | $725 |
| No | 206921006 | YORK | HMH72B241 | CU36CXA1+TXV | YP9C060B12MP13 | 14,500 | $725 |
| No | 206921146 | YORK | HMH72B241 | AVC36BX21+TXV | | 14,300 | $715 |
| No | 206921290 | YORK | HMH72B361 | CU36CXA1+TXV | TM8V120C20MP12 | 24,600 | $1,230 |
| No | 206921293 | YORK | HMH72B361 | CU36CXA1+TXV | TM8V100C20MP12 | 24,600 | $1,230 |
| No | 206921296 | YORK | HMH72B361 | CU36CXA1+TXV | TMLV120C20MP12 | 24,600 | $1,230 |
| No | 206921299 | YORK | HMH72B361 | CU36CXA1+TXV | TPLC100C20MP13 | 24,600 | $1,230 |
| No | 206921302 | YORK | HMH72B361 | CU36CXA1+TXV | TPLC120C20MP13 | 24,600 | $1,230 |
| No | 206921305 | YORK | HMH72B361 | CU36CXA1+TXV | YPLC100C20MP13 | 24,600 | $1,230 |
| No | 206921308 | YORK | HMH72B361 | CU36CXA1+TXV | YPLC120C20MP13 | 24,600 | $1,230 |
| No | 206921318 | YORK | HMH72B361 | CU36CXA1+TXV | TM8V100C16MP12 | 24,600 | $1,230 |
| No | 206921321 | YORK | HMH72B361 | CU36CXA1+TXV | TM8V080C16MP12 | 24,600 | $1,230 |
| No | 206921324 | YORK | HMH72B361 | CU36CXA1+TXV | TMLV100C16MP12 | 24,600 | $1,230 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921327 | YORK | HMH72B361 | CU36CXA1+TXV | TPLC080C16MP13 | 24,600 | $1,230 |
| No | 206921330 | YORK | HMH72B361 | CU36CXA1+TXV | TPLC100C16MP13 | 24,600 | $1,230 |
| No | 206921333 | YORK | HMH72B361 | CU36CXA1+TXV | YPLC080C16MP13 | 24,600 | $1,230 |
| No | 206921336 | YORK | HMH72B361 | CU36CXA1+TXV | YPLC100C16MP13 | 24,600 | $1,230 |
| No | 206921396 | YORK | HMH72B361 | CU36CXA1+TXV | TM8E120C16MP11 | 24,600 | $1,230 |
| No | 206921399 | YORK | HMH72B361 | CU36CXA1+TXV | TMLE120C16MP11 | 24,600 | $1,230 |
| No | 206921404 | YORK | HMH72B361 | CU36CXA1+TXV | TM8E100C16MP11 | 24,600 | $1,230 |
| No | 206921407 | YORK | HMH72B361 | CU36CXA1+TXV | TMLE100C16MP11 | 24,600 | $1,230 |
| No | 206921412 | YORK | HMH72B361 | CU36CXA1+TXV | TM8E100B12MP11 | 24,600 | $1,230 |
| No | 206921415 | YORK | HMH72B361 | CU36CXA1+TXV | TMLE100B12MP11 | 24,600 | $1,230 |
| No | 206921433 | YORK | HMH72B361 | CU36CXA1+TXV | TMLE080C16MP11 | 24,400 | $1,220 |
| No | 206921430 | YORK | HMH72B361 | CU36CXA1+TXV | TM8E080C16MP11 | 24,400 | $1,220 |
| No | 206921438 | YORK | HMH72B361 | CU36CXA1+TXV | TM8E080B12MP11 | 24,600 | $1,230 |
| No | 206921441 | YORK | HMH72B361 | CU36CXA1+TXV | TMLE080B12MP11 | 24,600 | $1,230 |
| No | 206921520 | YORK | HMH72B361 | CF36BXA1+ME12BN21+TXV | | 24,400 | $1,220 |
| No | 206921521 | YORK | HMH72B361 | CF36BBCA1+ME12BN21 | | 24,400 | $1,220 |
| No | 206921522 | YORK | HMH72B361 | CM36BXA1+ME12BN21+TXV | | 24,400 | $1,220 |
| No | 206921523 | YORK | HMH72B361 | CM36BBCA1+ME12BN21 | | 24,400 | $1,220 |
| No | 206921524 | YORK | HMH72B361 | CF36BXA1+ME08BN21+TXV | | 23,600 | $1,180 |
| No | 206924125 | YORK | HMH72B361 | CF36BBCA1+ME08BN21 | | 23,600 | $1,180 |
| No | 206921525 | YORK | HMH72B361 | CM36BXA1+ME08BN21+TXV | | 23,600 | $1,180 |
| No | 206924126 | YORK | HMH72B361 | CM36BBCA1+ME08BN21 | | 23,600 | $1,180 |
| No | 206921526 | YORK | HMH72B361 | AVC36CX21+TXV | | 24,200 | $1,210 |
| No | 206921527 | YORK | HMH72B361 | AVC36BX21+TXV | | 24,600 | $1,230 |
| No | 206921051 | YORK | HMH72B241 | CU36CXA1+TXV | TM8V100C16MP12 | 14,300 | $715 |
| No | 206921053 | YORK | HMH72B241 | CU36CXA1+TXV | TM8V080C16MP12 | 14,300 | $715 |
| No | 206921055 | YORK | HMH72B241 | CU36CXA1+TXV | TMLV100C16MP12 | 14,300 | $715 |
| No | 206921057 | YORK | HMH72B241 | CU36CXA1+TXV | TPLC080C16MP13 | 14,300 | $715 |
| No | 206921059 | YORK | HMH72B241 | CU36CXA1+TXV | TPLC100C16MP13 | 14,300 | $715 |
| No | 206921061 | YORK | HMH72B241 | CU36CXA1+TXV | YPLC080C16MP13 | 14,300 | $715 |
| No | 206921063 | YORK | HMH72B241 | CU36CXA1+TXV | YPLC100C16MP13 | 14,300 | $715 |
| No | 206921141 | YORK | HMH72B241 | CF36CXA1+ME12CN21+TXV | | 14,200 | $710 |
| No | 206921142 | YORK | HMH72B241 | CM36CXA1+ME12CN21+TXV | | 14,200 | $710 |
| No | 206921156 | YORK | HMH72B361 | CU36CXA1+TXV | TM9V100C20MP12 | 24,400 | $1,220 |
| No | 206921159 | YORK | HMH72B361 | CU36CXA1+TXV | TP9C100C20MP13 | 24,400 | $1,220 |
| No | 206921162 | YORK | HMH72B361 | CU36CXA1+TXV | YP9C100C20MP13 | 24,400 | $1,220 |
| No | 206921168 | YORK | HMH72B361 | CU36CXA1+TXV | TM9V100C16MP12 | 24,400 | $1,220 |
| No | 206921171 | YORK | HMH72B361 | CU36CXA1+TXV | TP9C100C16MP13 | 24,400 | $1,220 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921174 | YORK | HMH72B361 | CU36CXA1+TXV | YP9C100C16MP13 | 24,400 | $1,220 |
| No | 206921251 | YORK | HMH72B361 | CU36CXA1+TXV | TM9E100C16MP12 | 24,600 | $1,230 |
| No | 206921259 | YORK | HMH72B361 | CU36CXA1+TXV | TM9E080B12MP12 | 24,800 | $1,240 |
| No | 206921268 | YORK | HMH72B361 | CU36CXA1+TXV | TM9E060B12MP12 | 24,800 | $1,240 |
| No | 206921483 | YORK | HMH72B361 | CU36CXA1+TXV | TL9E080C16UH11 | 24,600 | $1,230 |
| No | 206921510 | YORK | HMH72B361 | CF36BXA1+MVC12BN21+TXV | | 24,400 | $1,220 |
| No | 206921511 | YORK | HMH72B361 | CF36BBCA1+MVC12BN21 | | 24,400 | $1,220 |
| No | 206921512 | YORK | HMH72B361 | CM36BXA1+MVC12BN21+TXV | | 24,400 | $1,220 |
| No | 206921513 | YORK | HMH72B361 | CM36BBCA1+MVC12BN21 | | 24,400 | $1,220 |
| No | 206920978 | YORK | HMH72B241 | CU36CXA1+TXV | TM9V080B12MP12 | 14,300 | $715 |
| No | 206920980 | YORK | HMH72B241 | CU36CXA1+TXV | TP9C080B12MP13 | 14,300 | $715 |
| No | 206920982 | YORK | HMH72B241 | CU36CXA1+TXV | YP9C080B12MP13 | 14,300 | $715 |
| No | 206921145 | YORK | HMH72B241 | AVC36CX21+TXV | | 14,200 | $710 |
| No | 206921342 | YORK | HMH72B361 | CU36CXA1+TXV | TM8V080B12MP12 | 24,400 | $1,220 |
| No | 206921345 | YORK | HMH72B361 | CU36CXA1+TXV | TPLC080B12MP13 | 24,400 | $1,220 |
| No | 206921348 | YORK | HMH72B361 | CU36CXA1+TXV | YPLC080B12MP13 | 24,400 | $1,220 |
| No | 206921514 | YORK | HMH72B361 | CF36CXA1+ME16CN21+TXV | | 23,800 | $1,190 |
| No | 206921515 | YORK | HMH72B361 | CM36CXA1+ME16CN21+TXV | | 23,800 | $1,190 |
| No | 206921517 | YORK | HMH72B361 | CF36CXA1+ME12CN21+TXV | | 24,200 | $1,210 |
| No | 206921518 | YORK | HMH72B361 | CM36CXA1+ME12CN21+TXV | | 24,200 | $1,210 |
| No | 206921516 | YORK | HMH72B361 | CM36CBCA1+ME16CN21 | | 23,800 | $1,190 |
| No | 206921519 | YORK | HMH72B361 | CM36CBCA1+ME12CN21 | | 24,200 | $1,210 |
| No | 206921135 | YORK | HMH72B241 | CF36CXA1+MVC12CN21+TXV | | 14,200 | $710 |
| No | 206921136 | YORK | HMH72B241 | CM36CXA1+MVC12CN21+TXV | | 14,200 | $710 |
| No | 206921137 | YORK | HMH72B241 | CF36BXA1+MVC12BN21+TXV | | 14,300 | $715 |
| No | 206921138 | YORK | HMH72B241 | CF36BBAA1+MVC12BN21 | | 14,300 | $715 |
| No | 206921139 | YORK | HMH72B241 | CM36BXA1+MVC12BN21+TXV | | 14,300 | $715 |
| No | 206921140 | YORK | HMH72B241 | CM36BBAA1+MVC12BN21 | | 14,300 | $715 |
| No | 206921147 | YORK | HMH72B241 | CF36BXA1+ME08BN21+TXV | | 14,100 | $705 |
| No | 206921148 | YORK | HMH72B241 | CF36BBAA1+ME08BN21 | | 14,100 | $705 |
| No | 206921149 | YORK | HMH72B241 | CM36BXA1+ME08BN21+TXV | | 14,100 | $705 |
| No | 206921150 | YORK | HMH72B241 | CM36BBAA1+ME08BN21 | | 14,100 | $705 |
| No | 206971178 | YORK | HMH72B481 | CF64DXA1+MVC20DN21+TXV | | 30,200 | $1,510 |
| No | 206971179 | YORK | HMH72B481 | CM64DXA1+MVC20DN21+TXV | | 30,200 | $1,510 |
| No | 206971105 | YORK | HMH72B601 | CF64DXA1+ME20DN21+TXV | | 39,000 | $1,950 |
| No | 206971103 | YORK | HMH72B601 | CF64DXA1+MVC20DN21+TXV | | 39,000 | $1,950 |
| No | 206971104 | YORK | HMH72B601 | CM64DXA1+MVC20DN21+TXV | | 39,000 | $1,950 |
| No | 206971106 | YORK | HMH72B601 | CM64DXA1+ME20DN21+TXV | | 39,000 | $1,950 |

Hydro Québec

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206971107 | YORK | HMH72B601 | AVC60DX21+TXV | | 39,000 | $1,950 |
| No | 206921108 | YORK | HMH72B241 | CF36AXA1+TXV | TM8V060A12MP12 | 14,100 | $705 |
| No | 206921109 | YORK | HMH72B241 | CF36AXA1+TXV | TMLV060A12MP12 | 14,100 | $705 |
| No | 206921110 | YORK | HMH72B241 | CF36AXA1+TXV | TPLC060A12MP13 | 14,100 | $705 |
| No | 206921112 | YORK | HMH72B241 | CM36AXA1+TXV | TM8V060A12MP12 | 14,100 | $705 |
| No | 206921111 | YORK | HMH72B241 | CF36AXA1+TXV | YPLC060A12MP13 | 14,100 | $705 |
| No | 206921113 | YORK | HMH72B241 | CM36AXA1+TXV | TMLV060A12MP12 | 14,100 | $705 |
| No | 206921114 | YORK | HMH72B241 | CM36AXA1+TXV | TPLC060A12MP13 | 14,100 | $705 |
| No | 206921076 | YORK | HMH72B241 | CF36BBAA1 | TM8V080B12MP12 | 14,400 | $720 |
| No | 206921115 | YORK | HMH72B241 | CM36AXA1+TXV | YPLC060A12MP13 | 14,100 | $705 |
| No | 206921073 | YORK | HMH72B241 | CF36BXA1+TXV | TM8V080B12MP12 | 14,400 | $720 |
| No | 206921074 | YORK | HMH72B241 | CF36BXA1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 206921075 | YORK | HMH72B241 | CF36BXA1+TXV | YPLC080B12MP13 | 14,400 | $720 |
| No | 206921077 | YORK | HMH72B241 | CM36BXA1+TXV | TM8V080B12MP12 | 14,400 | $720 |
| No | 206921081 | YORK | HMH72B241 | CM36BXA1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 206921078 | YORK | HMH72B241 | CM36BBAA1 | TM8V080B12MP12 | 14,400 | $720 |
| No | 206921079 | YORK | HMH72B241 | CU36BXA1+TXV | TM8V080B12MP12 | 14,400 | $720 |
| No | 206921080 | YORK | HMH72B241 | CF36BBAA1 | TPLC080B12MP13 | 14,400 | $720 |
| No | 206921082 | YORK | HMH72B241 | CM36BBAA1 | TPLC080B12MP13 | 14,400 | $720 |
| No | 206921083 | YORK | HMH72B241 | CU36BXA1+TXV | TPLC080B12MP13 | 14,400 | $720 |
| No | 206921085 | YORK | HMH72B241 | CM36BXA1+TXV | YPLC080B12MP13 | 14,400 | $720 |
| No | 206921084 | YORK | HMH72B241 | CF36BBAA1 | YPLC080B12MP13 | 14,400 | $720 |
| No | 206921130 | YORK | HMH72B241 | CM36BXA1+TXV | TL8E060A12UH11 | 14,500 | $725 |
| No | 206921087 | YORK | HMH72B241 | CU36BXA1+TXV | YPLC080B12MP13 | 14,400 | $720 |
| No | 206921086 | YORK | HMH72B241 | CM36BBAA1 | YPLC080B12MP13 | 14,400 | $720 |
| No | 206921128 | YORK | HMH72B241 | CF36BXA1+TXV | TL8E060A12UH11 | 14,500 | $725 |
| No | 206921129 | YORK | HMH72B241 | CF36BBAA1 | TL8E060A12UH11 | 14,500 | $725 |
| No | 206921131 | YORK | HMH72B241 | CM36BBAA1 | TL8E060A12UH11 | 14,500 | $725 |
| No | 206921132 | YORK | HMH72B241 | CU36BXA1+TXV | TL8E060A12UH11 | 14,500 | $725 |
| No | 206921133 | YORK | HMH72B241 | CF36AXA1+TXV | TL8E060A12UH11 | 14,400 | $720 |
| No | 206921134 | YORK | HMH72B241 | CM36AXA1+TXV | TL8E060A12UH11 | 14,400 | $720 |
| No | 206921067 | YORK | HMH72B241 | CM36CXA1+TXV | TM8V080B12MP12 | 14,300 | $715 |
| No | 206921064 | YORK | HMH72B241 | CF36CXA1+TXV | TM8V080B12MP12 | 14,300 | $715 |
| No | 206921065 | YORK | HMH72B241 | CF36CXA1+TXV | TPLC080B12MP13 | 14,300 | $715 |
| No | 206921066 | YORK | HMH72B241 | CF36CXA1+TXV | YPLC080B12MP13 | 14,300 | $715 |
| No | 206921068 | YORK | HMH72B241 | CU36CXA1+TXV | TM8V080B12MP12 | 14,300 | $715 |
| No | 206921069 | YORK | HMH72B241 | CM36CXA1+TXV | TPLC080B12MP13 | 14,300 | $715 |
| No | 206921070 | YORK | HMH72B241 | CU36CXA1+TXV | TPLC080B12MP13 | 14,300 | $715 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 206921071 | YORK | HMH72B241 | CM36CXA1+TXV | YPLC080B12MP13 | 14,300 | $715 |
| No | 206921072 | YORK | HMH72B241 | CU36CXA1+TXV | YPLC080B12MP13 | 14,300 | $715 |
| No | 206921088 | YORK | HMH72B241 | CF36BXA1+TXV | TM8V060A12MP12 | 14,000 | $700 |
| No | 206921089 | YORK | HMH72B241 | CF36BXA1+TXV | TMLV060A12MP12 | 14,000 | $700 |
| No | 206921090 | YORK | HMH72B241 | CF36BXA1+TXV | TPLC060A12MP13 | 14,000 | $700 |
| No | 206921091 | YORK | HMH72B241 | CF36BXA1+TXV | YPLC060A12MP13 | 14,000 | $700 |
| No | 206921092 | YORK | HMH72B241 | CF36BBAA1 | TM8V060A12MP12 | 14,000 | $700 |
| No | 206921093 | YORK | HMH72B241 | CM36BXA1+TXV | TM8V060A12MP12 | 14,000 | $700 |
| No | 206921094 | YORK | HMH72B241 | CM36BBAA1 | TM8V060A12MP12 | 14,000 | $700 |
| No | 206921095 | YORK | HMH72B241 | CU36BXA1+TXV | TM8V060A12MP12 | 14,000 | $700 |
| No | 206921096 | YORK | HMH72B241 | CF36BBAA1 | TMLV060A12MP12 | 14,000 | $700 |
| No | 206921097 | YORK | HMH72B241 | CM36BXA1+TXV | TMLV060A12MP12 | 14,000 | $700 |
| No | 206921098 | YORK | HMH72B241 | CM36BBAA1 | TMLV060A12MP12 | 14,000 | $700 |
| No | 206921099 | YORK | HMH72B241 | CU36BXA1+TXV | TMLV060A12MP12 | 14,000 | $700 |
| No | 206921100 | YORK | HMH72B241 | CF36BBAA1 | TPLC060A12MP13 | 14,000 | $700 |
| No | 206921101 | YORK | HMH72B241 | CM36BXA1+TXV | TPLC060A12MP13 | 14,000 | $700 |
| No | 206921102 | YORK | HMH72B241 | CM36BBAA1 | TPLC060A12MP13 | 14,000 | $700 |
| No | 206921103 | YORK | HMH72B241 | CU36BXA1+TXV | TPLC060A12MP13 | 14,000 | $700 |
| No | 206921104 | YORK | HMH72B241 | CF36BBAA1 | YPLC060A12MP13 | 14,000 | $700 |
| No | 206921105 | YORK | HMH72B241 | CM36BXA1+TXV | YPLC060A12MP13 | 14,000 | $700 |
| No | 206921106 | YORK | HMH72B241 | CM36BBAA1 | YPLC060A12MP13 | 14,000 | $700 |
| No | 206921107 | YORK | HMH72B241 | CU36BXA1+TXV | YPLC060A12MP13 | 14,000 | $700 |
| No | 206921116 | YORK | HMH72B241 | CF36AXA1+TXV | TM8E040A12MP11 | 14,400 | $720 |
| No | 206921117 | YORK | HMH72B241 | CF36AXA1+TXV | TMLE040A12MP11 | 14,400 | $720 |
| No | 206921124 | YORK | HMH72B241 | CF36BBAA1 | TL9E060B12UH11 | 14,500 | $725 |
| No | 206921118 | YORK | HMH72B241 | CM36AXA1+TXV | TM8E040A12MP11 | 14,400 | $720 |
| No | 206921119 | YORK | HMH72B241 | CM36AXA1+TXV | TMLE040A12MP11 | 14,400 | $720 |
| No | 206921123 | YORK | HMH72B241 | CF36BXA1+TXV | TL9E060B12UH11 | 14,500 | $725 |
| No | 206921125 | YORK | HMH72B241 | CM36BXA1+TXV | TL9E060B12UH11 | 14,500 | $725 |
| No | 206921126 | YORK | HMH72B241 | CM36BBAA1 | TL9E060B12UH11 | 14,500 | $725 |
| No | 206921127 | YORK | HMH72B241 | CU36BXA1+TXV | TL9E060B12UH11 | 14,500 | $725 |
| No | 206971180 | YORK | HMH72B481 | CF64DXA1+MVC14DN21+TXV | | 29,200 | $1,460 |
| No | 206971181 | YORK | HMH72B481 | CM64DXA1+MVC14DN21+TXV | | 29,200 | $1,460 |
| No | 206787284 | YORK | HMH72B241 | AE36CX21+TXV | | 14,000 | $700 |
| No | 206787282 | YORK | HMH72B361 | AE36CX21+TXV | | 24,000 | $1,200 |
| No | 206787283 | YORK | HMH72B481 | AE60DX21+TXV | | 30,200 | $1,510 |
| No | 206787281 | YORK | HMH72B601 | AE60DX21+TXV | | 36,800 | $1,840 |

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 8578569 | YORK BY JOHNSON CONTROLS | DHX09CSB21S | DHX09NWB21S | | 7,300 | $365 |
| No | 8578433 | YORK BY JOHNSON CONTROLS | DHR24CSB21S | DHR24NDB21S | | 16,700 | $835 |
| No | 8578445 | YORK BY JOHNSON CONTROLS | DHR30CSB21S | DHR30NDB21S | | 16,700 | $835 |
| No | 8578505 | YORK BY JOHNSON CONTROLS | DHW42CMB21S | Heat pump without ducts | | 29,000 | $1,450 |
| No | 8578421 | YORK BY JOHNSON CONTROLS | DHR18CSB21S | DHR18NDB21S | | 10,900 | $545 |
| No | 8578577 | YORK BY JOHNSON CONTROLS | DHX18CSB21S | DHX18NWB21S | | 12,400 | $620 |
| No | 8578573 | YORK BY JOHNSON CONTROLS | DHX12CSB21S | DHX12NWB21S | | 7,700 | $385 |
| No | 8578457 | YORK BY JOHNSON CONTROLS | DHR36CSB21S | DHR36NDB21S | | 24,600 | $1,230 |
| No | 8578589 | YORK BY JOHNSON CONTROLS | DHZ12CSB21S | DHZ12NWB21S | | 8,500 | $425 |
| No | 8578581 | YORK BY JOHNSON CONTROLS | DHX24CSB21S | DHX24NWB21S | | 14,600 | $730 |
| No | 8578441 | YORK BY JOHNSON CONTROLS | DHR24CSB21S | DHR24NCB21S | | 15,700 | $785 |
| No | 8578585 | YORK BY JOHNSON CONTROLS | DHZ09CSB21S | DHZ09NWB21S | | 5,500 | $275 |
| No | 8578437 | YORK BY JOHNSON CONTROLS | DHR24CSB21S | DHR24NKB21S | | 15,700 | $785 |

Updated: June 19, 2023

| Special offer | AHRI No. | Brand | Model No. of outdoor unit | Model No. of indoor unit | Model No. of furnace (if applicable) | Heating output (-8°C) | Financial assistance |
|---|---|---|---|---|---|---|---|
| No | 207827124 | ZENAIR TECHNOLOGIES | ZEN-WM18HP23S/O | ZEN-WM18HP23S/I | | 11,100 | $555 |
| No | 207827123 | ZENAIR TECHNOLOGIES | ZEN-WM12HP23S/O | ZEN-WM12HP23S/I | | 10,300 | $515 |
| No | 207911499 | ZENAIR TECHNOLOGIES | ZEN-PC30HP20S/O | ZEN-PC30HP20S/I | | 21,000 | $1,050 |
| No | 207036648 | ZEPHYR | ZE-60HPB | AH-60B | | 40,000 | $2,000 |
| No | 207036646 | ZEPHYR | ZE-48HPB | AH-48B | | 31,000 | $1,550 |
| No | 207036642 | ZEPHYR | ZE-36HPB | AH-36B | | 24,000 | $1,200 |
| No | 207036640 | ZEPHYR | ZE-24HPB | AH-24B | | 15,000 | $750 |
| No | 204580063 | ZEPHYR | ZE-18CA22EXT | ZE-18CA22INT | | 11,600 | $580 |
| No | 204580064 | ZEPHYR | ZE-12CA22EXT | ZE-12CA22INT | | 7,500 | $375 |
| No | 206346135 | ZEPHYR | ZE-42M522SCO | Combination heat pumps with or without ducts | | 24,000 | $1,200 |
| No | 206346134 | ZEPHYR | ZE-42M522SCO | Heat pump without ducts | | 24,000 | $1,200 |
| No | 206347271 | ZEPHYR | ZE-36M422SCO | Combination heat pumps with or without ducts | | 22,600 | $1,130 |
| No | 206347270 | ZEPHYR | ZE-36M422SCO | Heat pump without ducts | | 23,200 | $1,160 |
| No | 206346131 | ZEPHYR | ZE-24M322SCO | Combination heat pumps with or without ducts | | 15,400 | $770 |
| No | 206346130 | ZEPHYR | ZE-24M322SCO | Heat pump without ducts | | 15,400 | $770 |
| No | 206346129 | ZEPHYR | ZE-18M222SCO | Combination heat pumps with or without ducts | | 12,200 | $610 |
| No | 206346128 | ZEPHYR | ZE-18M222SCO | Heat pump without ducts | | 12,200 | $610 |
| No | 205306851 | ZEPHYR | ZE-24HPA | AH-24 | | 15,300 | $765 |
| No | 206031034 | ZEPHYR | ZE-60HPA | AH-60 | | 32,400 | $1,620 |
| No | 205131573 | ZEPHYR | ZE-09DA17EXT | ZE-09DA17INT | | 5,000 | $250 |
| No | 10277947 | ZEPHYR | ZE-18CA17EXT | ZE-18CA17INT | | 11,600 | $580 |
| No | 209867862 | ZERO | ZMSB-24HVD-US | ZMSB-24HVD-US | | 16,500 | $825 |
| No | 209867861 | ZERO | ZMSB-18HVD-US | ZMSB-18HVD-US | | 11,400 | $570 |
| No | 209867860 | ZERO | ZMSB-12HVD-US | ZMSB-12HVD-US | | 7,000 | $350 |
| No | 209867859 | ZERO | ZMSB-09HVD-US | ZMSB-09HVD-US | | 6,000 | $300 |
| No | 209867858 | ZERO | ZMSB-12HVD110-US | ZMSB-12HVD110-US | | 7,800 | $390 |
| No | 209867857 | ZERO | ZMSB-09HVD110-US | ZMSB-09HVD110-US | | 6,300 | $315 |