


Ice cover condition in the flyover area		Other component	
	Continuous ice cover		Sampling site
	Area of water not covered by flyover		Hummocked ice
	Opening		Ice jam
	Open water with floating ice		Ice cracks
	Slush		Observed snowmobile trail

SHEET 05

Universal Transverse Mercator Projection, Zone 18
Reference area: NAD 1983
File: 6675_cm_1724_ice_Mars12_Waska_F01-07_120328

Flyover done by:
Consultant representatives: Le Groupe-Conseil Lasalle inc.
Cree observers: Gordon Weistche and Starr Hester



Eastmain-1-A/Sarcelle/Rupert Project

Ice cover monitoring
(March 2012)